



# STEAM TURBINE INSPECTION REPORT

## ADSP Installation

for

AMERICAN ELECTRIC POWER COMPANY INC  
MITCHELL, Unit 2

Equipment Serial #: 170X394

Job Start Date: 9/12/2005

Report Issued: 02/08/06

FSR#: 96CE0024

Report Printed: January 30, 2006

Prepared By:  
Tom Perkins  
Field Engineer

Approved By:  
David Talmage  
Service Manager



## TABLE OF CONTENTS

	PAGE
JOB SUMMARY	3
INSPECTION SUMMARY	5
RECOMMENDATIONS	9
PARTS USED AND RECOMMENDED	12
TIL/ECN ACTIVITY	13
NOZZLES	14
TURBINE SHELLS	20
TURBINE ROTOR	41
DIAPHRAGM	45
SHAFT & DIAPHRAGM PACKING	51
TURBINE ALIGNMENT & CLEARANCES	58
BEARINGS	76
LUBRICATION SYSTEM	83
TURNING GEAR	85
STANDARDS	86
CONTROL SYSTEM	87
ALIGNMENT & CLEARANCE OVERVIEW	88
STARTUP COMMENTS	90
APPENDIX	93



## JOB SUMMARY

Customer: AMERICAN ELECTRIC POWER COMPANY IN  
Station: MITCHELL  
Unit No.: 2

Equipment Serial #: 170X394      Rating: 738 MW  
Turbine Type: G5E      Service Year: 1971  
Eng. Responsibility: LST  
Generator Code:      Control System: Non-GE  
LSB Length: 33.5      Generator Cooling: H  
Service Type: Tech Direction

Steam Conditions:  
Inlet Pressure: 3334 PSI      Inlet Temperature: 1000 Deg F

Office Location: CENT FS-PITTSBURGH  
FSR#: 96CE0024  
Service Manager: David Talmage  
Service Director: Dot Harris  
Field Engineer: Tom Perkins

Job Start Date: 9/12/2005      Completion Date: 1/4/2006  
Job Type: Major  
Work Scope: [Y] Turbine [N] Generator [N] Valves [N] Auxiliary  
[N] Other



## **JOB SUMMARY**

Unit #2 was removed from service September 9, 2005, for a scheduled maintenance outage. GE responsibility for this outage was limited to the ADSP installation. GE provided (MPL-1LX0365) parts, project management and technical direction. Labor and supervision were provided by AEP. The turbine outage was scheduled for thirteen weeks, two ten hour shifts, six days per week during disassembly and reassembly and five days per week while inner shell and components were off site.

Additional turbine work performed this outage included internal inspection of the second reheat, and valves. This work was performed under customer direction without GE involvement.



## INSPECTION SUMMARY

Section Component	Location	Description	Action
<u>Nozzle Box</u>			
Assembly	HP	Preventive Maintenance	Replaced
Partition		Erosion Spe	Replaced
Ring	Inlet Seal		ASSOCIATED PARTS
<u>HP Outer Shell</u>			
Fit	Inner Shell - LH	Cracked	Weld Repaired
Fit	Mid-span Seal Ring	Damaged	Weld Repaired
Flange	Inlet	Distortion	Machined
Guide	Thermocouple	Preventive Maintenance	New Part Installed
Inlet Bore	Lower Left	Fretted	Machined
Inlet Bore	Upper Left	Fretted	Weld Repaired
Insulation		Improperly Installed	Temporary Repair
Pipe	Extraction	Cracked	Ground
Pipe	Mid-span Access	Damaged	Replaced
Pressure Tap	1st and 3rd Sta	Preventive Maintenance	Replaced
Shell	N1, N3	Improperly Installed	Modified
Snout	Reheat Inlet Pipe	Out Of Round	Machined
Stud	31	Broken	Replaced
<u>HP Inner Shell</u>			
Assembly		FMI	FMI Satisfied
Assembly		Preventive Maintenance	Repaired
Fit	RS 3rd Sta PT	Pounded	Weld Repaired
Flange	UH	Cracked	Weld Repaired
Gib	Circular Key	Corrosion	Stoned
Key	Joint	Modification	Modified
Orifice	Cooling Pipe	Plugged	Repaired
Ring	Reheat Extr	Preventive Maintenance	Replaced



## INSPECTION SUMMARY

<u>Section Component</u>	<u>Location</u>	<u>Description</u>	<u>Action</u>
Ring	Reheat Inlet Seal	Preventive Maintenance	Replaced
Snout	MSI Pipe	Preventive Maintenance	New Part Installed
<u>Shell</u>			
Bolt		Bolt Stretch	Bolting Stretched To Specification
Ring	Inlet Seal	Preventive Maintenance	Modified
Ring	Midspan Access Seal	Preventive Maintenance	Replaced
<u>HP/RHT Rotor</u>			
Assembly		FMI	FMI Satisfied
Coupling	A	Preventive Maintenance	Machined
<u>LP B Rotor</u>			
Guard	C Coupling	Rubbed	Ground
<u>HP Diaphragm</u>			
Assembly	HP/RH	FMI	FMI Satisfied
Partition	5, 6	Damaged Foreign Matl	Modified
Spill Strip	2	Improperly Installed	Modified
<u>Shaft Packing</u>			
Assembly	Diaphragm, Steam Seal	Preventive Maintenance	New Part Installed
<u>HP Diaphragm Packing</u>			
Teeth	2nd Stage	Damaged	Modified
<u>Packing Casing</u>			
Assembly	N1, N3	Dimensional Checks	Ok - Measurements Are Within Tolerance
<u>Packing Head</u>			



## INSPECTION SUMMARY

<u>Section Component</u>	<u>Location</u>	<u>Description</u>	<u>Action</u>
Assembly	N1	Preventive Maintenance	Realigned
Assembly	N1, N3	Distortion	Modified
Assembly	N2	FMI	FMI Satisfied
Assembly	N3	Preventive Maintenance	Realigned
<u>Alignment - Coupling</u>			
Rotor	A	Misalignment	Realigned
<u>Alignment - Steam Path</u>			
Assembly	HP/RH	Misalignment	Realigned
Shell	HP/RH Inner	Misalignment	Realigned
Shell	HP/RH Outer	Misalignment	Repositioned
<u>Clearances - Turbine</u>			
Rotor	HP/RH	Clearance Check	Clearance Check Was Satisfactory
<u>Thrust Bearing</u>			
Assembly		General Thrust Brg Inspection	Routine Inspection Completed
<u>Turbine Journal Bearing</u>			
Assembly	T1, T2	Assembled Improperly	Repaired
<u>Oil Deflector</u>			
Assembly	T1, T2	Preventive Maintenance	Retoothed
<u>Main Oil Pump</u>			
Assembly		Cleaned And Inspected	Good Condition - No Visual Defects
Valve - Check		Assembled Improperly	Modified
<u>Turning Gear</u>			



### INSPECTION SUMMARY

<u>Section Component</u>	<u>Location</u>	<u>Description</u>	<u>Action</u>
Rod	Engagement	Misadjustment	Used As Is - Warrants Repair
<u>Front Standard Assembly</u>		Rusted	Cleaned
<u>Mid Standard Guard</u>	A Coupling	Assembled Improperly	Used As Is - Warrants Repair
<u>TSI Detector Instrumentation Probe</u>	Thrust Position Key Phaser T2 Right	Misadjustment Improperly Installed Failed	Used As Is - Warrants Repair Repaired Modified



## RECOMMENDATIONS

### 1. Standard, Mid; Guard; A Coupling

Investigate excessive "A" coupling oil spray next inspection. Check spray line orifice.

### 2. Shell, HP Outer; Insulation;

Prior to reinsulation of the turbine shells, the insulating contractor should be determined qualified to properly insulate the shells. (Insulators did not seem to know what the requirements are.)

### 3. Rotor, LP B; Guard; C Coupling

Axial positioning of the LP rotors and "C" coupling guard should be checked next outage to verify adequate clearance for rotor expansion.

### 4. Packing Casing; Assembly; N1, N3

Consider removing the N3 bolt-on packing casing next outage to correct distortion and allow standard packing to be used. This would necessitate tracking the radial alignment of the shell so that the casing could be realigned to the same location as a reference for internal alignment. (Note as-left relative alignment position due to the distortion.)

### 5. Packing Head; Assembly; N1, N3

During future packing replacements in the N1 and N3 internal packing heads, re-roundable packing will need to be installed and adjusted, or the hook fits should be machined round and special packing should be installed with undersize hook diameters.

### 6. Packing Head; Assembly; N3

Note that upper packing keys were left out (with engineering approval) due to broken retainer bolts stuck in the horn. The broken bolts should be drilled out next inspection.



## RECOMMENDATIONS

### 7. Alignment - Coupling; Rotor; A

Lateral coupling face alignment was inconsistent over time. There appears to be foundation and/or pedestal shifting due to ambient or some other plant condition changes.

### 8. Alignment - Steam Path; Assembly; HP/RH

Note that disassembly radial rotor position checks at N1 and N3 will reflect the packing casing distortion, plus the shell will be an additional 10 mils high to prevent upper seal rubbing when shells are unbolted. N1 will show 18 mils high, and N3 will show 30 mils high.

### 9. Clearances - Turbine; Rotor; HP/RH

Radial clearances at the N2 packing head and reheat diaphragms show a 15 mil offset to the left due to tops-on movement. The HP diaphragms were offset 5 mils to the right.

### 10. Bearing, Turbine Journal; Assembly; T1, T2

Consider obtaining new design bearing pads for the next HP/RH turbine inspection. New design pads have replaceable anti-rotation pin inserts in the upper pads.

### 11. Turning Gear; Rod; Engagement

The turning gear engagement mechanism should be inspected and repaired next opportunity.

### 12. Standard, Front; Assembly;

Lube oil condition should be frequently monitored for water content to prevent rusting of oil side components.



## RECOMMENDATIONS

### 13. TSI [EHC]; Detector; Thrust Position

The thrust position detector should be readjusted to position the meter at zero when the rotor is centered in the thrust travel.

### 14. TSI [EHC]; Probe; T2 Right

The key-phaser and #2 bearing vibration probe problems should be investigated and corrected next opportunity.



**PARTS USED AND RECOMMENDED**

Item	Ins Rec	PU	RI	RO	QTY	UM	Parts Description	Cust Stk #	Catalog #	Drawing #
1	4	X			1	Each	Nozzle Box,Assembly,HP		1600	Spare
2	39	X			4	Set	Nozzle Box, Ring, Inlet Seal		1600	808L5247G0001
3	49	X			1	Set	HP Outer Shell, Guide, Thermocouple		5200	808L3359G0002
4	31	X			1	Each	HP Outer Shell, Pipe, Mid-span Access		5200	126C3425P0001
5	50	X			4	Each	HP Outer Shell, Pressure Tap, 1st and 3rd Sta		5200	145D4691G0006
6	36	X			1	Each	HP Outer Shell, Stud, 31		5200	Customer Stock
7	42	X			1	Accu	HP Inner Shell, Ring, Reheat Extr		5200	808L3369G0002
8	41	X			1	Accu	HP Inner Shell, Ring, Reheat Inlet Seal		5200	808L3346G0001
9	32	X			2	Each	HP Inner Shell, Snout, MSI Pipe		0600	Customer Supplied
10	30	X			1	Accu	Shell, Ring, Inlet Seal		5200	102L2597G0001
11	43	X			1	Accu	Shell, Ring, Midspan Access Seal		0600	808L3350G0002
12	2	X			1	Set	HP Diaphragm, Assembly, HP/RH		2400	ADSP
13	11	X			1	Accu	Shaft Packing, Assembly, Diaphragm		2400	815L1460G0001
14	11	X			1	Accu	Shaft Packing, Assembly, Steam Seal		2400	815L1456G0001
15	3	X			1	Assy	Packing Head, Assembly, N2		5000	ADSP N2

PU=Part Used During the Inspection

RI=Part Recommended for Immediate Restock

RO=Part Recommended for the Next Inspection



**TIL/ECN ACTIVITY**

(None this outage)



## NOZZLES

### Nozzle Box

#### Ring; Inlet Seal

### Nozzle Box

#### Assembly; HP

A customer supplied spare nozzle box was reconditioned and installed with the ADSP. The axial fits were machined for location and clearance in the inner shell. Initial fitting and contact checks were done in the Pittsburgh Service Center. Final keys were machined after tops-on, tops-off alignment. New inlet seal rings were installed.

### Nozzle Box

#### Partition;


The as-found nozzle box partitions had severe erosion. The upper right inlet had a broken seal ring. See attached photos.



# 180° Nozzle Boxes

## Axial Rabbet Fit Clearance Data – Form B

Date(m,d,y) 11/14/2005 Turbine Serial No. 170X394 Prepared by Charlie LeMaster



ST00068

UPPER HALF				Axial Float Check
Fit	Left	Right	Top	
D	1.956	1.956	1.956	
C	1.947	1.947	1.947	
Clearance D-C	0.009	0.009	0.009	0.007
SURFACE CONDITION				
Acceptable	X	X	X	
Needs Repair				
LOWER HALF				Axial Float Check
Fit	Left	Right	Top	
D	1.956	1.957	1.957	
C	1.948	1.947	1.947	
Clearance D-C	0.008	0.010	0.010	0.007
SURFACE CONDITION				
Acceptable	X	X	X	
Needs Repair				

\*Axial float to agree with measured clearance within .002 inch.

Comments
<b>FINALS</b>


Nozzle Axial Fit Clr(a)



# 180° Nozzle Boxes

## Vertical Positioning Shim Data – Form E

Date(m,d,y) 11/15/2005 Turbine Serial No 170X394 Prepared by Charlie LeMaster



**NOTES:** On upper half box, the B dimension is to be taken with the upper clearance shim plate (or crush pins) removed.  
 Data in inches.

DIMENSION	UPPER BOX (CLEARANCE SHIM)			
	TURBINE END		GENERATOR END	
	Left	Right	Left	Right
A	5.049	5.055	5.055	5.054
B	4.325	4.327	4.325	4.326
Temporary Shim (A-B)	0.724	0.728	0.730	0.728
Permanent Shim	0.701	0.703	0.703	0.700

DIMENSION	LOWER BOX (SUPPORT SHIM)			
	TURBINE END		GENERATOR END	
	Left	Right	Left	Right
A	5.636	5.645	5.625	5.630
B	4.751	4.749	4.750	4.751
Temporary Shim (A-B)	0.885	0.896	0.875	0.879
Permanent Shim	<b>0.884</b>	<b>0.901</b>	<b>0.887</b>	<b>0.888</b>

Comments


Nozzle Vert Pos Shim Data(a)



# 180° Nozzle Boxes

## Vertical Centerline Gib Key Data – Form F

Date 11/12/2005 Turbine Serial No 170X394 Prepared by Charlie LeMaster



**NOTE:** Permanent sizes are to give proper alignment and provide specified drawing clearance.

				UPPER HALF		
KEY		UPPER HALF	LOWER HALF	KEY	TURBINE END	GENERATOR END
L	Temporary			L	Temporary	
	Permanent	0.896	0.869		Permanent	
R	Temporary			R	Temporary	
	Permanent	1.041	1.067		Permanent	

FINAL SIDE FLOAT				LOWER HALF			
	ACTUAL FLOAT	KEY CLEARANCE	DIFF	L	Temporary		
Upper	0.018	0.020	-0.002	L	Permanent		
Lower	0.018	0.018	0.000		R	Temporary	
*Maximum .002"				Permanent			

<b>Comments</b>	


Nozzle Vert CL Gib Key(a)



# 180° Nozzle Boxes

## Horizontal Joint Checks – Form H

Date(m,d,y) 11/15/2005 Turbine Serial No. 170X394 Prepared by Charlie LeMaster



ST00074

**NOTES:**

- +Means Box Joint is Higher than Inner Shell Joint.
- -Means Box Joint is Lower than Inner Shell Joint.
- Box Joint Must be Transversely Parallel with Inner Shell Joint Within .004" (maximum of .004" difference between left and right joint check readings)
- The Algebraic Sum ( $\Delta$ ) of the Upper and Lower Left to Left and Right to Right Joint Check Readings Must Show the Specified Clearance Shim Clearance Within .002".


GEN. LEFT U <u>-0.029</u> L <u>0.011</u> $\Delta$ <div style="border: 1px solid black; padding: 2px; width: fit-content;">0.018</div>	GEN. RIGHT U <u>-0.031</u> L <u>0.011</u> $\Delta$ <div style="border: 1px solid black; padding: 2px; width: fit-content;">0.020</div>
TURB. LEFT U <u>-0.025</u> L <u>0.006</u> $\Delta$ <div style="border: 1px solid black; padding: 2px; width: fit-content;">0.019</div>	TURB. RIGHT U <u>-0.028</u> L <u>0.009</u> $\Delta$ <div style="border: 1px solid black; padding: 2px; width: fit-content;">0.019</div>

Comments	

Nozzle Hor Jt Cks(a)



Nozzle Partition Erosion



Broken Nozzle Seal Ring



## **TURBINE SHELLS**

### HP Outer Shell

#### Fit; Inner Shell - LH

The outer shell inner surfaces were NDT'd by AEP personnel. A crack was found in the inner shell locating male fit in the lower half. This crack was in the ligament from the original mid-span eccentricity hole that was previously plugged. The crack was ground out and repair welded by AEP personnel.

### HP Outer Shell

#### Fit; Mid-span Seal Ring

The upper surface of the seal ring bore for the mid-span balance access in the UH outer shell was found badly damaged from apparent arc-cutting. The surface was weld repaired and machined by I&RS. I&RS installed new seal rings.

### HP Outer Shell

#### Flange; Inlet

The main steam inlet flanges on the outer shell were machined by CMS to remove dishing and indents from the mating flange surface. The pipe side flanges were not machined this outage.

### HP Outer Shell

#### Guide; Thermocouple

All new shell thermocouple guide pipes were supplied with the ADSP and were installed.

### HP Outer Shell

#### Inlet Bore; Lower Left

The lower left inlet in the outer shell was found damaged from the first ring fretting down into the face. The face was remachined by I&RS about 1/2" deeper than drawing and a special thicker first inner ring was installed.



## **TURBINE SHELLS**

### HP Outer Shell

#### Inlet Bore; Upper Left

The upper left inlet bore in the outer shell was found badly fretted from the first upper ring. These rings had been installed incorrectly, with the outer fit ring first. This ring was apparently too loose, and fretted into the bore and up into the face. The bore was weld repaired using GE's "Torch Temper" process and machined by I&RS.

### HP Outer Shell

#### Insulation;

The HP/RH and 2nd Reheat shells were not reinsulated correctly after the outage. Several attempts by the insulating contractor were required to make the shell insulation appear adequate.

Prior to reinsulation of the turbine shells, the insulating contractor should be determined qualified to properly insulate the shells. (Insulators did not seem to know what the requirements are.)

### HP Outer Shell

#### Pipe; Extraction

The reheat extraction pipe in the lower outer shell was found cracked in the stellite at the taper on the end. The crack was ground out and blended.

### HP Outer Shell

#### Pipe; Mid-span Access

The removed midspan balance pipe had damaged stellite fits and was bent. A new pipe was obtained from GE and installed.

### HP Outer Shell

#### Pressure Tap; 1st and 3rd Sta

Both 1st stage and both 3rd stage pressure taps were supplied with the ADSP and were installed. AEP personnel performed the welding.



## **TURBINE SHELLS**

### HP Outer Shell

#### Shell; N1, N3

Flow steps in the shell casting were found at the interface to the N1 and N3 packing heads. These were ground and blended to allow uninterrupted steam flow for performance improvement.

### HP Outer Shell

#### Snout; Reheat Inlet Pipe

The reheat inlet snout pipes were found out-of-round and were trued up by CMS.

### HP Outer Shell

#### Stud; 31

One of the large thru-studs (31) was found broken at disassembly. The stud was replaced from customer stock.

### HP Inner Shell

#### Assembly;

The HP/RH inner shell upper and lower halves were sent to an I&RS machining vendor after CMS repairs for machining internal component axial fits. All seal ring bores were also trued up. When this work was complete, the shells were sent to the Pittsburgh Service Center for initial fitting of the diaphragms, N2 and nozzle.

### HP Inner Shell

#### Assembly;

The following repairs were performed to the HP inner shell while at the Pittsburgh Service Center: Weld and machine the B inlet bore; remove studs 88 and 90 (partially unscrewed and stuck) and tap holes; minor crack grinding and blending in lower fit radii; remove broken nozzle elevation key bolts.



## **TURBINE SHELLS**

### HP Inner Shell

#### Fit; RS 3rd Sta PT

The right side 3rd stage pressure tap hole in the lower inner shell was found badly pounded out. The pressure tap was missing. The hole was repair welded by I&RS and a new hole was machined.

### HP Inner Shell

#### Flange; UH

The upper and lower inner shells were removed and sent to CMS for seal ring removal, blast cleaning and NDT. A previously repaired large crack along the bolting flange in the upper shell was repair welded at CMS. I&RS completed laser mapping on the horizontal joints of both halves to determine flatness. The lower half was in plane and had minimal distortion from outer to inner. The upper half also had minimal outer to inner distortion, but one corner was out of plane by 28 mils. Since the joint closed when bolted, no horizontal joint machining was done. However, this joint distortion affects lateral tops-on, tops-off alignment changes.

### HP Inner Shell

#### Gib; Circular Key

The upper inner shell center gib posts were found badly pitted from apparent corrosion. These surfaces were remachined at CMS. The lower shell posts were pitted to a lesser degree, and were hand dressed by I&RS.

### HP Inner Shell

#### Key; Joint

Horizontal joint seal keys were added to the N2 area of the upper inner shell as part of the ADSP modification.

### HP Inner Shell

#### Orifice; Cooling Pipe

The cooling line under the HP inner shell was found plugged and the orifice was eroded. New orifice and pipe components were installed at the Pittsburgh Service Center.



## **TURBINE SHELLS**

### HP Inner Shell

#### Ring; Reheat Extr

New bi-metallic reheat extraction rings were machined and installed by I&RS. (The extraction pipe snout was not removed.)

### HP Inner Shell

#### Ring; Reheat Inlet Seal

All new bi-metallic reheat inlet seal rings were machined and installed by I&RS.

### HP Inner Shell

#### Snout; MSI Pipe

The customer supplied two new inlet snout pipes to replace two that were found cracked. These were installed in the lower half. The two pipes re-used were trued up and installed in the upper half.

### Shell

#### Ring; Inlet Seal

All new HP inlet seal rings were machined and installed by I&RS. The shell bores were honed true. The rings were the bi-metallic design, which allows more clearance to the pipe for ease of installation.

### Shell

#### Ring; Midspan Access Seal

I&RS replaced the midspan balance pipe seal rings in the inner and outer shell with bi-metallic design rings.

### Shell

#### Bolt;

The inner shell, outer shell and steam lead bolts were stretched using Mannings Induction Heaters and measured with extensimeters.



## TURBINE SHELLS



Mid-span Ecc Hole Crack



## TURBINE SHELLS



Mid-span Balance Seal Ring Bore



## TURBINE SHELLS



Lower Inlet Face Fretting



## TURBINE SHELLS



Upper Inlet Bore Damage



## TURBINE SHELLS



Stellite Crack Before Grinding



## TURBINE SHELLS



N1 Before Grinding



## TURBINE SHELLS



N3 Before Grinding



## TURBINE SHELLS



N1 After Grinding



## TURBINE SHELLS



N3 After Grinding





## TURBINE SHELLS



Damaged PT hole



## H P Inner Shell Mitchell Unit # 2 Laser Horizontal Joint Flatness Check

### LOWER HALF



Readings taken at AEP CMS Charleston W.Va.  
09-27-05 by Vince Kollin & Craig Schmotzer  
Inner Shell Horizontal Joint LHSheet1

AEP Mitchell Unit # 2  
HP Inner Shell Upper Half  
Horizontal Joint Flatness  
Check W/ Hamar Laser



Inner Shell Horizontal Joint UHSheet1



Shell Gib Surface Pitting











## **TURBINE ROTOR**

### HP/RHT Rotor

#### Assembly:

The AEP spare HP/RH rotor was modified for the ADSP installation prior to the outage at the Pittsburgh Service Center. New buckets were installed, and necessary machining was performed. The rotor was low speed balanced. The control rotor was removed from the existing rotor and assembled to the replacement rotor. The T1 journal final size was 15.993. The T2 journal final size was 16.966.

### HP/RHT Rotor

#### Coupling; A

The A coupling was line-bored by CMS and assembled using AEP procedure. Four bolt holes were lined bored 90 degrees apart and fitted studs were installed. The new coupling on the 2nd reheat had undersize bolt holes, resulting in high clearance on the HP half bolts that were not fitted. The differential runout was adjusted prior to line boring. Conventional bolting was used.

### LP B Rotor

#### Guard; C Coupling

During initial roll, a rubbing noise was heard at the "C" coupling. The covers were removed and a protruding guard joint bolt was found rubbing on the generator end windage covers. The bolt was cut shorter to remove the protrusion.

Axial positioning of the LP rotors and "C" coupling guard should be checked next outage to verify adequate clearance for rotor expansion.



# Coupling Bolt Assembly Data

Date(m,d,y) 12/1/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

COUPLING A Bolt Type Conventional - AEP Spec  
 (Conventional / Hydraulic)

STUD HOLE	COUPLING HOLE DIAMETER			STUD/SLEEVE DIAMETER		CLEARANCE		
	TB. SIDE	GEAR/SPACER	GEN. SIDE	TB. SIDE	GEN. SIDE	TB. SIDE	GEAR/SPACER	GEN. SIDE
1 (M)	2.896 "	2.896 "	2.896 "	2.730 "	2.730 "	0.166 "	0.166 "	0.166 "
2	2.813 "	2.753 "	2.752 "	2.730 "	2.730 "	0.083 "	0.023 "	0.022 "
3	2.874 "	2.874 "	2.874 "	2.873 "	2.873 "	0.001 "	0.001 "	0.001 "
4	2.813 "	2.753 "	2.753 "	2.730 "	2.730 "	0.083 "	0.023 "	0.023 "
5	2.813 "	2.753 "	2.751 "	2.730 "	2.730 "	0.083 "	0.023 "	0.021 "
6	2.880 "	2.880 "	2.880 "	2.879 "	2.879 "	0.001 "	0.001 "	0.001 "
7	2.813 "	2.753 "	2.750 "	2.730 "	2.730 "	0.083 "	0.023 "	0.020 "
8	2.813 "	2.753 "	2.750 "	2.730 "	2.730 "	0.083 "	0.023 "	0.020 "
9	2.813 "	2.753 "	2.750 "	2.730 "	2.730 "	0.083 "	0.023 "	0.020 "
10	2.813 "	2.753 "	2.751 "	2.730 "	2.730 "	0.083 "	0.023 "	0.021 "
11	2.896 "	2.896 "	2.896 "	2.895 "	2.895 "	0.001 "	0.001 "	0.001 "
12	2.813 "	2.753 "	2.751 "	2.730 "	2.730 "	0.083 "	0.023 "	0.021 "
13	2.813 "	2.753 "	2.750 "	2.730 "	2.730 "	0.083 "	0.023 "	0.020 "
14	2.874 "	2.874 "	2.874 "	2.873 "	2.873 "	0.001 "	0.001 "	0.001 "
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								

**Comments:**

Coupling Bolts(a)





# Coupling Assembly Checks Without Integral Rabbets

Date(m,d,y) 12/1/2005

Turbine Serial No. 170X394

Prepared by T. Perkins

**NOTES:**

- (1) For radial runout set indicator to read "0" at the number 1 position.
- (2) Mark positions 1-8 to agree with factory stamped degree marks on rotor as shown on Fig. 1.

Coupling

Data   
 (as found/final)





Fig. 1



ST00094

Fig. 2

**Coupling Runouts**

(Readings are in Mills)

Area Indicated		Position Number								
		1 0°	2 45°	3 90°	4 135°	5 180°	6 225°	7 270°	8 315°	1 0°
TE Journal	A									
TE Cplg. Periphery	B	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Spacer	C	0.0	0.0	0.0	-1.0	-1.0	-1.0	-1.0	0.0	0.0
GE Cplg. Periphery	D	0.0	-1.0	0.0	0.0	0.0	-1.0	-1.0	-1.0	0.0
GE Journal	E									

**Differential Runouts**

Journals	A-E								
Cplg. Periphery	B-D	0.0	1.0	0.0	0.0	0.0	1.0	1.0	1.0
Spacer to Cplg	C-B	0.0	0.0	0.0	-1.0	-1.0	-1.0	-1.0	0.0
Spacer to Cplg	C-D	0.0	1.0	0.0	-1.0	-1.0	0.0	0.0	1.0

**Maximum Runouts**

Area Indicated		Data Check	TIR Runout	TIR Check
TE Journal	A			
TE Cplg. Periphery	B	OK	0.0	OK
Spacer	C	OK	1.0	OK
GE Cplg. Periphery	D	OK	1.0	OK
GE Journal	E			

**Maximum Differential Runouts**

		Max. Diff.	Diff. Check
Journals	A-E		
Cplg. Periphery	B-D	1.0	OK
Spacer to Cplg	C-B	1.0	OK
Spacer to Cplg	C-D	2.0	OK

Coupling Runout(a)



## **DIAPHRAGM**

### HP Diaphragm

#### Assembly; HP/RH

New HP and reheat diaphragms were supplied with the ADSP modification. The diaphragms were initially fitted at the Pittsburgh Service Center. New centering pins were machined and installed in the shell. The diaphragm fits and crush pins were machined to locate the diaphragms axially. Final sideslips and drop checks were recorded after final alignment on site. Clearance spacers were adjusted after final alignment.

### HP Diaphragm

#### Partition; 5, 6

The 5th and 6th stage diaphragm partitions had severe impact damage. See attached photos.

### HP Diaphragm

#### Spill Strip; 2

A badly deteriorated spill strip segment was found in the second stage diaphragm, probably incorrect material. See attached photo.






## Diaphragm Axial Float Checks Lower Half

Date(m/d/y) 11/1/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

Stage	Left	Right
6	0.006	0.008
5	0.010	0.014
4	0.017	0.015
3	0.011	0.007
2	0.010	0.012
7/8	0.008	0.008
9	0.006	0.009
10	0.012	0.013

Comments
Note: New diaphragms do not have crushpins in upper halves






Impact Damage



Impact Damage



Deteriorated 2nd Stage Spill Strip



## SHAFT & DIAPHRAGM PACKING

### Shaft Packing

#### Assembly; Diaphragm, Steam Seal

All high pressure and reheat packing was replaced with the ADSP modification. Standard packing was installed in the diaphragms and N2 packing head. Re-roundable packing was installed in the N1 and N3 packing glands. Grooves 1 and 2 in N1 did not require adjustments due to minimal distortion and acceptable clearances. All packing butt clearances were checked and adjusted as necessary by I&RS.

### HP Diaphragm Packing

#### Teeth; 2nd Stage

HP packing as found was in poor condition, with chipped teeth in the 2nd and 3rd stages. See attached photo.

### Packing Casing

#### Assembly; N1, N3

Dimensional checks and titewire alignment checks at disassembly showed the bolt-on packing casings aligned well to the outer shell. Since re-roundable packing was supplied for the N1 and N3 packing, the lower packing casings were not removed this outage. This also simplified the alignment process. The N1 casing had minimal distortion and did not require adjustments to the packing. (Supplied with standard hook diameter pins.) The N3 packing casing was squeezed vertically about 40 mils smaller than the horizontal dimension and required adjustment to the packing pins. I&RS did this on site.

Consider removing the N3 bolt-on packing casing next outage to correct distortion and allow standard packing to be used. This would necessitate tracking the radial alignment of the shell so that the casing could be realigned to the same location as a reference for internal alignment. (Note as-left relative alignment position due to the distortion.)

### Packing Head

#### Assembly; N1

The N1 packing head was realigned. (See diaphragm data.) I&RS machined a new upper circular gib key.



## SHAFT & DIAPHRAGM PACKING

### Packing Head

#### Assembly; N1, N3

The N1 and N3 internal packing heads were sent to the Pittsburgh Service Center for fitting re-roundable packing. The N1 head had minimal distortion and required light skimming of the teeth to restore drawing clearances. The N3 casing had moderate distortion. Adjustments were made for excess clearance, and the teeth were machined where necessary to restore drawing clearance. Truth rings were machined in each end of the bores for alignment.

During future packing replacements in the N1 and N3 internal packing heads, re-roundable packing will need to be installed and adjusted, or the hook fits should be machined round and special packing should be installed with undersize hook diameters.

### Packing Head

#### Assembly; N2

A new N2 packing casing (head) was provided with the ADSP modification. The axial locating fits were machined at the Pittsburgh Service Center for location and clearance in the inner shell. New keys were machined for alignment.

### Packing Head

#### Assembly; N3

The N3 packing head was realigned. (See diaphragm data.) Broken upper key retainer bolts were found during assembly. (The bolts install from under the gib and were overlooked.) Since new packing heads do not have upper key provisions and access prevented drilling the broken bolts, the upper keys were left out. Factory engineering was consulted and concurred that upper packing head keys were unnecessary. The broken bolts were staked in place.

Note that upper packing keys were left out (with engineering approval) due to broken retainer bolts stuck in the horn. The broken bolts should be drilled out next inspection.



## SHAFT & DIAPHRAGM PACKING



As Found Packing Damage - 2nd Stage






# Packing Casing Roundness

Date(m,d,y) 11/11/8/05

Turbine Serial No. 170X394

Prepared by T. Perkins

Packing Casing	Upper Outer Shell Off			Upper Outer Shell Bolted			Comments
	A-Dia	B-Dia	C-Dia	A-Dia	B-Dia	C-Dia	
N1 G1 OB	21.522	21.502	21.497	21.511	21.506	21.490	
N1 G1 IB	21.521	21.501	21.495				
N1 G2 IB	21.520	21.500	21.492	21.513	21.508	21.489	
N1 G2 OB	21.523	21.502	21.493				
N3 G4 OB	22.542	22.541	22.486	22.540	22.537	22.487	
N3 G4 IB	22.537	33.537	22.488				
N3 G5 IB	22.525	22.526	22.484				
N3 G5 OB	22.518	22.523	22.482	22.523	22.520	22.479	



**Comments**


Note: For the N1 "Outer Shell Off readings", the left side dowel was not in. There was a step at the joint from the UH being warped outward. Use "B" readings for horizontal comparison. A new dowel was made for the "Shell Bolted" readings.




# UH N1 Circular Gib Key

Date(m/d/y) 11/30/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

HP/RH N1 Turb.End



HP/RH \_\_\_\_\_ Gen.End



Comments	



## N2 Packing Head Keys

Date(m/d/y) 11/20/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

<b>Final</b>	<u>Upper Half</u>	<u>Lower Half</u>
Left Key	0.856	0.878
Right Key	0.902	0.885
Post	2.501	2.495
Keyway	4.268	4.263
Clearance	0.009	0.005

### During Tops-On

Left	0.895	0.915
Right	0.871	

Comments

N2 Packing Head Keys(a)



## **TURBINE ALIGNMENT & CLEARANCES**

### Alignment - Coupling

#### Rotor; A

During assembly of the 2nd reheat turbine, a large left move was made on the #3 bearing to align the face at B coupling. (This face opening was not seen at disassembly.) Prior to final installation of the HP inner shell and components, the HP rotor was temporarily installed to check "A" coupling and make initial bearing shim changes. Large left and upward moves were required on #1, and a large left move was required at #2. At assembly with tops on, the #1 bearing had to be moved back to the right part of the initial move, and the #2 bearing was raised further. Coupling lateral face alignment appears to change with time and possibly ambient conditions. The final T1 position was 12 mils left from as-found. T2 was 19 mils left from as-found.

Lateral coupling face alignment was inconsistent over time. There appears to be foundation and/or pedestal shifting due to ambient or some other plant condition changes.

### Alignment - Steam Path

#### Assembly; HP/RH

A complete tops-on, tops-off laser alignment was performed on the HP/RH section. New inner shell keys and nozzle keys were machined to align the axial fits parallel for maximum axial float, and maintain concentricity to the rotor. Diaphragms and packing heads were realigned with new keys. All hold-down spacers and shell crushpins were adjusted. The upper nozzle was aligned in the upper half horizontally by laser, and vertically by joint checks. The upper half N2 alignment was set by measuring key gaps during tops-on, and was confirmed in the upper half with temporary supports. The LH bolt-on packing casings were not removed since disassembly alignment and distortion checks showed good alignment to the outer shell. The final line was set with the N1 casing 8 mils high to the rotor and N3 20 mils high to the rotor to compensate for diametrical distortion. The tops-off keys were machined to raise the shell an additional 10 mils since the large vertical tops-on movement would cause upper spill strips to land on the rotor when upper halves were installed (prior to the inner shell being bolted).

Note that disassembly radial rotor position checks at N1 and N3 will reflect the packing casing distortion, plus the shell will be an additional 10 mils high to prevent upper seal rubbing when shells are unbolted. N1 will show 18 mils high, and N3 will show 30 mils high.



## **TURBINE ALIGNMENT & CLEARANCES**

### Alignment - Steam Path

#### Shell; HP/RH Inner

The inner shell was positioned on temporary elevation keys initially with the joint approximately flush with the outer shell. It was necessary to raise the generator end about 25 mils to achieve the expected axial float in the locating fit. (Fits parallel.) This is the same condition the shell was found in. Radial alignment of shell bores was also good in this position. New elevation keys were machined and circular gib keys were machined to center the shell left to right.

### Alignment - Steam Path

#### Shell; HP/RH Outer

After final coupling alignment, the outer shell running (elevation) keys and centerline gib keys were machined to position the shell to the desired location at the N1 and N3 setpoints. Final shell positions and rotor positions are attached. The tops-off (building) keys were machined to raise the shell 10 mils due to the large upward movement in the tops-on bolted condition. (With the inner shell unbolted, the diaphragms drop far enough that the upper spill strips could land on the bucket covers.) New safety keys were also machined to provide 60 mils clearance.

### Clearances - Turbine

#### Rotor; HP/RH

All rotor/diaphragm/packing clearances were recorded at assembly and approved by GE Engineering. Axial clearances were very close to design at the buckets and HP packing. The reheat and N3 packing axial clearances were off in the rotor long direction from the thrust, indicating the rotor is shorter than drawing since the bucket machining was based on the first stage wheel. Axial dimensional checks on the outer shell were within a few mils of drawing. Also, the N3 G5 axial clearances were an additional 1/16" off due to a deviation in the location of the rotor lands at that row of packing. (The G5 lands are 1/16" closer to G4 than drawing.)

All radial clearances were within acceptable tolerance.

Radial clearances at the N2 packing head and reheat diaphragms show a 15 mil offset to the left due to tops-on movement. The HP diaphragms were offset 5 mils to the right.




# Alignment Couplings

Date 11/23/2005 Turbine Serial No. 170X394 Prepared by T. Perkins  
 Coupling "A" HP/2nd Reheat

**Alignment Readings (Insert readings in (mils))**

Position	Top	Left	Bottom	Right
Rim	0	0	2	2
Face 0°	609	610	610	610
Face 90°	608	609	611	611
Face 180°	608	608	610	611
Face 270°	608	607	607	608
Average	608.3	608.5	609.5	610.0
Relative	0	0.2	1.2	1.7
<b>Check</b>		<b>Face</b>	<b>Rim</b>	
Top + Bottom =		1.2	2.0	
Right + Left =		1.9	2.0	
Difference =		-0.7	0.0	




Comments

Final A Coupling Check(a)



# Mitchell Unit 2 Laser Alignment

Date(m/d/y) 11/11/2005 Turbine Serial No. 170X394 Prepared by C. LeMaster




COMPONENT NAME	AXIAL DISTANCE	11/11/2005		11/8/2005		DIFFERENCE	
		TOPS OFF		TOPS ON		HORZ	VERT
		HORZ	VERT	HORZ	VERT		
<b>T2 Oil Deflector</b>	309.875"	-3.6	-25.3	-0.8	-11.0	2.8	14.3
<b>N3 G5</b>	303.625"	<b>0.0</b>	<b>0.0</b>	<b>0.0</b>	<b>0.0</b>	0.0	0.0
<b>Outer Shell Bore GE</b>	297.750"	8.3	-27.5	4.7	-14.5	-3.6	13.0
<b>N3 G2</b>	288.500"	8.6	-26.3	8.4	-29.0	-0.2	-2.7
<b>10th Stage</b>	274.875"	8.9	-3.6	-7.7	15.8	-16.6	19.4
<b>GE Inn Shell Bore</b>	268.875"	5.6	-64.3	-8.7	-16.9	-14.3	47.4
<b>9th Stage</b>							
<b>8th Stage</b>	253.500"	24.0	-12.7	6.9	14.0	-17.1	26.7
<b>7th Stage</b>	240.500"	17.4	-16.3	4.6	3.7	-12.8	20.0
<b>N2 G7</b>	236.125"	-9.1	-26.8	-25.8	-1.3	-16.7	25.5
<b>N2 G1</b>	209.250"	-13.6	-9.1	-25.2	10.9	-11.6	20.0
<b>Nozzle Left</b>	155.625"	93.6	-62.4	97.7	-54.1	4.1	8.3
<b>Nozzle Right</b>	155.875"	70.4	-62.4	74.9	-54.2	4.5	8.2
<b>2rd Stage</b>	145.000"	-10.3	-1.0	-7.2	12.3	3.1	13.3
<b>3th Stage</b>	135.875"	-4.7	0.8	1.0	15.2	5.7	14.4
<b>4th Stage</b>	127.750"	8.4	41.3	13.2	49.9	4.8	8.6
<b>5th Stage</b>							
<b>TE Inn Shell Bore</b>	116.250"	-3.6	-46.1	10.5	-20.0	14.1	26.1
<b>6th Stage</b>	111.750"	3.4	17.6	11.0	24.1	7.6	6.5
<b>N1 G7</b>	101.250"	0.1	1.6	1.2	-1.4	1.1	-3.0
<b>N1 G5</b>	92.500"	-2.4	-3.9	1.7	-6.8	4.1	-2.9
<b>N1 G3</b>	79.125"	-2.0	-10.0	-2.0	-10.9	0.0	-0.9
<b>Outer Shell Bore TE</b>	77.625"	-1.8	8.6	-0.2	9.9	1.6	1.3
<b>N1 G1</b>	69.000"	<b>0.0</b>	<b>0.0</b>	<b>0.0</b>	<b>0.0</b>	0.0	0.0
<b>T1 Oil Deflector</b>	62"	4.1	30.6	-3.3	26.1	-7.4	-4.5

**Comments:**  
 Tops On / Tops Off With Building Keys Installed  
 Fixed points in N1 G1 & N3 G5



# Mitchell Unit 2 Laser Alignment

Date(m/d/y) 11/16/05 Turbine Serial No. 170X394 Prepared by C. LeMaster



COMPONENT NAME	AXIAL DISTANCE	FINAL LINE		IDEAL LINE		Joint Checks	
		HORZ	VERT	HORZ	VERT	Left	Right
<b>N3 G5</b>	303.625"	<b>0.0</b>	<b>18.0</b>	<b>0.0</b>	<b>18.0</b>		
<b>N3 G2</b>	288.500"	0.6	-2.8	<b>0.0</b>	<b>0.0</b>		
<b>GE Inner Shell Bore</b>	268.875"	-6.4	-62.7	-----	-----		
<b>10th Stage</b>	274.875"	17.0	-24.2	<b>15.0</b>	<b>-23.0</b>		
<b>9th Stage</b>		13.7	-27.7	<b>15.0</b>	<b>-27.0</b>		
<b>8th Stage</b>	253.500"	15.7	-30.5	<b>15.0</b>	<b>-30.0</b>		
<b>7th Stage</b>	240.500"	13.9	-33.3	<b>15.0</b>	<b>-34.0</b>		
<b>N2 G7</b>	236.125"	14.7	-35.6	<b>15.0</b>	<b>-34.0</b>		
<b>N2 G1</b>	209.250"	13.7	-35.7	<b>15.0</b>	<b>-34.0</b>		
<b>Nozzle Left</b>	155.625"	1.6	-20.2	<b>4.0</b>	<b>-16.0</b>		
<b>Nozzle Right</b>	155.875"	-14.7	-18.5	<b>-12.0</b>	<b>-16.0</b>		
<b>2rd Stage</b>	145.000"	-3.3	-23.1	<b>-5.0</b>	<b>-20.0</b>		
<b>3th Stage</b>	135.875"	-4.9	-21.7	<b>-5.0</b>	<b>-21.0</b>		
<b>4th Stage</b>	127.750"	-2.5	-16.9	<b>-5.0</b>	<b>-16.0</b>		
<b>5th Stage</b>		-3.8	-13.6	<b>-5.0</b>	<b>-14.0</b>		
<b>6th Stage</b>	111.750"	-5.1	-12.4	<b>-5.0</b>	<b>-12.0</b>		
<b>TE Inner Shell Bore</b>	116.250"	-6.2	-49.9	-----	-----		
<b>N1 G7</b>	101.250"	-2.6	-2.6	<b>-4.0</b>	<b>-1.0</b>		
<b>N1 G5</b>	92.500"	-0.5	-2.8	<b>-4.0</b>	<b>-1.0</b>		
<b>N1 G3</b>	79.125"	-2.0	-6.4	<b>-4.0</b>	<b>-1.0</b>		
<b>N1 G1</b>	69.000"	<b>0.0</b>	<b>6.0</b>	<b>0.0</b>	<b>6.0</b>		

**Comments:**  
 Final Line with Presets at N1 H= 0.0 V= 6.0 N3 H=0.0 V= 18.0  
  
 Fixed Points N1 and N3



# Mitchell Unit 2 Laser Alignment

Date(m/d/y) 11/18/05 Turbine Serial No. 170X394 Prepared by C. LeMaster

<b>Final Alignment</b>	<p>POSITION</p>
<b>HP / RH</b>	


COMPONENT NAME	AXIAL DISTANCE	FINAL LINE		IDEAL LINE		DIFFERENCE	
		HORZ	VERT	HORZ	VERT	HORZ	VERT
<b>N3 G5</b>	303.625"	0.0	18.0	0.0	18.0		
<b>GE Inn Shell Bore</b>		-6.4	-62.7				
<b>Nozzle Left</b>	155.625"	1.6	-20.2	4.0	-16.0		
<b>Nozzle Right</b>	155.875"	-14.7	-18.5	-12	-16		
<b>TE Inn Shell Bore</b>		-6.2	-49.9				
<b>N1 G1</b>	69.000"	0.0	6.0	0.0	6.0		
<b>Upper Nozzle Align</b>							
<b>GE Inner Shell Bore</b>		0.0	0.0				
<b>Nozzle Left</b>		-8.5		-7.9			
<b>Nozzle Right</b>		8.0		8.5			
<b>N2 G7</b>		-20.7		-20			
<b>N2 G1</b>		-21.1		-21			
<b>TE Inner Shell Bore</b>		0.0	0.0				

**Comments:**



## Mitchell Unit 2 Laser Alignment (Adjusted for setting shell high in tops off condition)

Date(m/d/y) 11/18/2005 Turbine Serial No. 170X394 Prepared by C. LeMaster



COMPONENT NAME	AXIAL DISTANCE	FINAL LINE		IDEAL LINE		DIFFERENCE	
		HORZ	VERT	HORZ	VERT	HORZ	VERT
<b>N3 G5</b>	303.625"	<b>0.0</b>	<b>28.0</b>	<b>0.0</b>	<b>28.0</b>	<b>0.0</b>	<b>0.0</b>
<b>N3 G2</b>	288.500"	0.6	7.2	0.0	10.0	-0.6	2.8
<b>GE Inn Shell Bore</b>	268.875"	-6.4	-52.7	---	---		
<b>10th Stage</b>	274.875"	17.0	-14.2	15.0	-13.0	-2.0	1.2
<b>9th Stage</b>	264.375"	13.7	-17.7	15.0	-17.0	1.3	0.7
<b>8th Stage</b>	253.500"	15.7	-20.5	15.0	-20.0	-0.7	0.5
<b>7th Stage</b>	240.500"	13.9	-23.3	15.0	-24.0	1.1	-0.7
<b>N2 G7</b>	236.125"	14.7	-25.6	15.0	-24.0	0.3	1.6
<b>N2 G1</b>	209.250"	13.7	-25.7	15.0	-24.0	1.3	1.7
<b>Nozzle Left</b>	155.625"	1.6	-10.2	4.0	-6.0	2.4	4.2
<b>Nozzle Right</b>	155.875"	-14.7	-8.5	-12.0	-6.0	2.7	2.5
<b>2rd Stage</b>	145.000"	-3.3	-13.1	-5.0	-10.0	-1.7	3.1
<b>3th Stage</b>	135.875"	-4.9	-11.7	-5.0	-11.0	-0.1	0.7
<b>4th Stage</b>	127.750"	-2.5	-6.9	-5.0	-6.0	-2.5	0.9
<b>5th Stage</b>	119.875"	-3.8	-3.6	-5.0	-4.0	-1.2	-0.4
<b>6th Stage</b>	111.750"	-5.1	-2.4	-5.0	-2.0	0.1	0.4
<b>TE Inn Shell Bore</b>	116.250"	-6.2	-39.9	---	---		
<b>N1 G7</b>	101.250"	-1.6	12.6	-4.0	9.0	-2.4	-3.6
<b>N1 G5</b>	92.500"	-0.5	7.2	-4.0	9.0	-3.5	1.8
<b>N1 G3</b>	79.125"	-2.0	1.6	-4.0	9.0	-2.0	7.4
<b>N1 G1</b>	69.000"	<b>0.0</b>	<b>16.0</b>	<b>0.0</b>	<b>16.0</b>	<b>0.0</b>	<b>0.0</b>

**Comments:**  
 Final Line with Presets at N1: H = 0.0, V = 16.0 N3: H = 0.0 , V = 28.0  
 Fixed points in N1 G1 & N3 G5




# HP Inner Shell Location Measurements

**Final**

Date(m/d/y) 11/17/2005 Turbine Serial No. 170X394 Prepared by T. Kudas

INSPECTIONS & CHECKS			CODE	
TE Left Elevation Shim	0.504		<b>X</b>	Work Carried Out
TE Right Elevation Shim	0.511		<b>N</b>	Not Done
GE Left Elevation Shim	0.520		<b>NA</b>	Not Applicable
GE Right Elevation Shim	0.535		<b>C</b>	See Comments
			<b>V</b>	Visual Inspection
			<b>MP</b>	Mag. Particle
			<b>UT</b>	Ultrasonic
			<b>PT</b>	Penetrant

Generator End




Comments
Float = Left Side .008 Right Side .011




# LH HP Circular Gib Keys

Date(m/d/y) 11/30/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

HP/RH LH Turb.End



HP/RH LH Gen.End




Comments




# UH HP Circular Gib Keys

Date(m/d/y) 11/30/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

HP/RH UH Turb.End



HP/RH UH Gen.End



Comments	



# Shell Arm Keys

Date(m/d/y) 12/1/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

		As Found	As Left
A1	TE Tops-On L	1.028	1.058
A2	TE Tops-On R	1.012	1.047
A3	TE Tops-Off L	1.051	1.077
A4	TE Tops-Off R	1.036	1.071
A5	TE Thrust T-L	0.749	0.749
A6	TE Thrust T-R	0.726	0.726
A7	TE Thrust G-L	1.003	1.003
A8	TE Thrust G-R	1.024	1.024
A9	TE Safety L	0.355	0.408
A10	TE Safety R	0.350	0.405
C1	GE Tops-On L	1.017	1.033
C2	GE Tops-On R	1.002	1.021
C3	GE Tops-Off L	1.049	1.061
C4	GE Tops-Off R	1.034	1.056
C5	GE Thrust T-L	1.041	1.041
C6	GE Thrust T-R	1.022	1.022
C7	GE Thrust G-L	0.720	0.720
C8	GE Thrust G-R	0.737	0.737
C9	GE Safety L	0.384	0.408
C10	GE Safety R	0.361	0.384


Comments



# Lower Centerline Key Data

Date (m/d/y) 12/1/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

INSPECTIONS & CHECKS		CODE
Measure Keys	_____	X Work Carried Out
	_____	N Not Done
	_____	NA Not Applicable



**Notes:** Enter key location as #1 Standard - HP, etc.  
 Data in inches.

ST00151

KEY LOCATION: TE HP							
Location	Key-Way Data		Key Data		Clearance		Comments
	L/S	R/S	L/S	R/S	L/S	R/S	
1 (T)	0.771	0.736	0.769	0.733	0.002	0.003	Right side key tapered to match slot
2 (T)			0.769	0.733			
3 (C)			0.769	0.732			
4 (C)			0.769	0.732			
5 (B)			0.769	0.730			
6 (B)			0.769	0.730			


KEY LOCATION: GE HP							
Location	Key-Way Data		Key Data		Clearance		Comments
	L/S	R/S	L/S	R/S	L/S	R/S	
1 (T)	0.787	0.726	0.783	0.726	0.004	0.000	
2 (T)			0.783	0.726			
3 (C)			0.783	0.726			
4 (C)			0.783	0.726			
5 (B)			0.783	0.726			
6 (B)			0.783	0.726			



# Upper Centerline Key Data

Date (m/d/y) 12/2/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

INSPECTIONS & CHECKS		CODE
Measure Keys	_____	X Work Carried Out
	_____	N Not Done
	_____	NA Not Applicable



**Notes:** Enter key location as #1 Standard - HP, etc.  
 Data in inches.

ST00151

KEY LOCATION: TE HP							
Location	Key-Way Data		Key Data		Clearance		Comments
	L/S	R/S	L/S	R/S	L/S	R/S	
1 (T)	0.758	0.742	0.756	0.740	0.002	0.002	
2 (T)	0.758	0.742	0.756	0.740	0.002	0.002	
3 (C)	0.758	0.742	0.756	0.740	0.002	0.002	
4 (C)	0.758	0.742	0.756	0.740	0.002	0.002	
5 (B)	0.758	0.742	0.756	0.740	0.002	0.002	
6 (B)	0.758	0.742	0.756	0.740	0.002	0.002	

KEY LOCATION:							
Location	Key-Way Data		Key Data		Clearance		Comments
	L/S	R/S	L/S	R/S	L/S	R/S	
1 (T)							
2 (T)							
3 (C)							
4 (C)							
5 (B)							
6 (B)							





# Diaphragm Clearance Record (New Method)

Date:(m,d,y) 11/28/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

STA NO.		Wheel Discharge Side Clearances					Wheel Admission Side Clearances									
		P	A	B	C	D	E	G	H	NL	NR	L <sub>TIP</sub>	L <sub>Root</sub>	L'L	L'R	V
6T	A	0.813				0.820			0.688	0.336	0.342	0.430	0.470	0.322	0.325	0.455
	E	0.774				0.800			0.694	0.343	0.343	0.437	0.470	0.330	0.330	0.460
	D	0.039				0.020			-0.006	-0.007	-0.001	-0.007	0.000	-0.008	-0.005	-0.005
5T	A	0.692				0.767			0.540	0.332	0.344	0.430	0.457	0.315	0.319	0.451
	E	0.699				0.768			0.577	0.335	0.335	0.429	0.460	0.320	0.320	0.455
	D	-0.007				-0.001			-0.037	-0.003	0.009	0.001	-0.003	-0.005	-0.001	-0.004
4T	A	0.731				0.796			0.856	0.327	0.330	0.427	0.455	0.314	0.313	0.465
	E	0.740				0.798			0.852	0.329	0.329	0.423	0.453	0.313	0.313	0.450
	D	-0.009				-0.002			0.004	-0.002	0.001	0.004	0.002	0.001	0.000	0.015
3T	A	0.690				0.699			0.735	0.327	0.321	0.415	0.487	0.340	0.347	0.480
	E	0.702				0.711			0.748	0.316	0.316	0.409	0.468	0.328	0.328	0.465
	D	-0.012				-0.012			-0.013	0.011	0.005	0.006	0.019	0.012	0.019	0.015
2T	A	0.676				0.699			0.703	0.312	0.315	0.415	0.476	0.326	0.331	0.470
	E	0.673				0.690			0.706	0.314	0.314	0.408	0.462	0.322	0.322	0.460
	D	0.003				0.009			-0.003	-0.002	0.001	0.007	0.014	0.004	0.009	0.010
1T	A	0.804				3.172					0.236	0.234	0.493			0.640
	E	0.794				3.233					0.226	0.226	0.486			0.640
	D	0.010				-0.061					0.010	0.008	0.007			0.000
	A															
	E															
	D															
7G	A	0.469				0.730			1.043	0.400	0.400	0.485	0.385	0.269	0.260	0.425
	E	0.401				0.680			1.046	0.410	0.410	0.547	0.406	0.265	0.265	0.405
	D	0.068				0.050			-0.003	-0.010	-0.010	-0.062	-0.021	0.004	-0.005	0.020
8G	A	0.520				0.987			0.985	0.194	0.184	0.298	0.356	0.235	0.227	0.380
	E	0.518				0.984			1.000	0.196	0.196	0.372	0.374	0.234	0.234	0.370
	D	0.002				0.003			-0.015	-0.002	-0.012	-0.074	-0.018	0.001	-0.007	0.010
9G	A	0.539				1.715			1.860	0.167	0.164	0.260	0.345	0.219	0.214	0.339
	E	0.508				1.710			1.890	0.153	0.153	0.323	0.350	0.210	0.210	0.345
	D	0.031				0.005			-0.030	0.014	0.011	-0.063	-0.005	0.009	0.004	-0.006
10G	A	0.516				0.792			1.592	0.169	0.155	0.260	0.320	0.189	0.177	0.320
	E	0.500				0.749			1.634	0.155	0.155	0.285	0.331	0.191	0.191	0.320
	D	0.016				0.043			-0.042	0.014	0.000	-0.025	-0.011	-0.002	-0.014	0.000
	A															
	E															
	D															
	A															
	E															
	D															

Comments
N3 axial position = .540





# Spill Strip & Packing Clearance

Date:(m/d/y) 11/28/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

STAGE NO.		Radial Clearances								Axial Clearances						
		M	Z-1L	Z-1R	Z-2L	Z-2R	WL	WR	RL	RR	X	Y	Z-3	Z-4	XA	Fig.
6T	A	0.280	0.032	0.036	0.039	0.045	0.045	0.050	0.027	0.028	0.285	0.562	0.681	0.129		1
	E	0.250	0.030	0.030	0.030	0.030	0.040	0.040	0.025	0.025	0.296	0.556	0.653	0.115		
	D	0.030	0.002	0.006	0.009	0.015	0.005	0.010	0.002	0.003	-0.011	0.006	0.028	0.014		
5T	A	0.275	0.039	0.044	0.040	0.047	0.050	0.050	0.024	0.029	0.275	0.563	0.288	0.117		1
	E	0.250	0.030	0.030	0.030	0.030	0.040	0.040	0.025	0.025	0.296	0.556	0.306	0.115		
	D	0.025	0.009	0.014	0.010	0.017	0.010	0.010	-0.001	0.004	-0.021	0.007	-0.018	0.002		
4T	A	0.275	0.040	0.041	0.039	0.045	0.042	0.046	0.028	0.030	0.290	0.563	0.296	0.119		5
	E	0.250	0.030	0.030	0.030	0.030	0.040	0.040	0.025	0.025	0.296	0.556	0.311	0.115		
	D	0.025	0.010	0.011	0.009	0.015	0.002	0.006	0.003	0.005	-0.006	0.007	-0.015	0.004		
3T	A	0.275	0.035	0.031	0.035	0.033	0.040	0.041	0.030	0.024	0.295	0.549	0.292	0.210		5
	E	0.250	0.030	0.030	0.030	0.030	0.040	0.040	0.025	0.025	0.296	0.556	0.316	0.175		
	D	0.025	0.005	0.001	0.005	0.003	0.000	0.001	0.005	-0.001	-0.001	-0.007	-0.024	0.035		
2T	A	0.277	0.037	0.035	0.037	0.038	0.042	0.040	0.030	0.024	0.278	0.564	0.281	0.133		5
	E	0.250	0.030	0.030	0.030	0.030	0.040	0.040	0.025	0.025	0.296	0.557	0.321	0.137		
	D	0.027	0.007	0.005	0.007	0.008	0.002	0.000	0.005	-0.001	-0.018	0.007	-0.040	-0.004		
1T	A	0.250	0.060	0.046			0.070	0.058					0.359			
	E	0.229	0.050	0.050			0.060	0.060					0.365			
	D	0.021	0.010	-0.004			0.010	-0.002					-0.006			
7T	A						0.067	0.048								
	E						0.050	0.050								
	D						0.017	-0.002								
7G	A	0.275	0.060	0.041	0.051	0.034	0.067	0.045	0.073	0.049	0.251	0.300	0.196	0.157		2
	E	0.250	0.040	0.040	0.040	0.040	0.050	0.050	0.055	0.055	0.238	0.299	0.213	0.146		
	D	0.025	0.020	0.001	0.011	-0.006	0.017	-0.005	0.018	-0.006	0.013	0.001	-0.017	0.011		
8G	A	0.310	0.063	0.042			0.069	0.045	0.082	0.053	0.180	0.238	0.172			2
	E	0.250	0.040	0.040			0.050	0.050	0.060	0.060	0.156	0.256	0.197			
	D	0.060	0.023	0.002			0.019	-0.005	0.022	-0.007	0.024	-0.018	-0.025			
9G	A	0.315	0.055	0.036	0.062	0.040	0.068	0.048	0.041	0.021	0.190	0.232	0.188	0.076	0.250	2
	E	0.250	0.040	0.040	0.040	0.040	0.050	0.050	0.025	0.025	0.154	0.258	0.173	0.080	0.250	
	D	0.065	0.015	-0.004	0.022	0.000	0.018	-0.002	0.016	-0.004	0.036	-0.026	0.015	-0.004	0.000	
10G	A	0.300	0.060	0.030	0.064	0.026	0.065	0.040	0.045	0.015	0.190	0.215	0.127	0.192		2
	E	0.250	0.040	0.040	0.040	0.040	0.050	0.050	0.025	0.025	0.155	0.257	0.140	0.189		
	D	0.050	0.020	-0.010	0.024	-0.014	0.015	-0.010	0.020	-0.010	0.035	-0.042	-0.013	0.003		
	A															
	E															
	D															
	A															
	E															
	D															

**Comments:**

Note: .015 tops on movement in the reheat to the right. HP diaphragm movement .005 left.



## Spill Strip & Packing Clearance (Special)

Date:(m/d/y) 11/19/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

STAGE NO.		Radial Clearances						Axial Clearances				Fig.	
		Z-5L	Z-5R				R'L	R'R	X'	Y'			
6T	A	0.021	0.029										1
	E	0.020	0.020										
	D												
5T	A	0.022	0.030										1
	E	0.020	0.020										
	D												
4T	A	0.024	0.028				0.056	0.051	NA				5
	E	0.020	0.020				0.045	0.045	0.331				
	D												
3T	A	0.021	0.020				0.055	0.051	NA				5
	E	0.020	0.020				0.045	0.045	0.331				
	D												
2T	A	0.026	0.022				0.055	0.047	NA				5
	E	0.020	0.020				0.045	0.045	0.331				
	D												
1T	A												
	E												
	D												
N2 G1	A						0.091	0.076	NA				6
	E						0.065	0.065	0.333				
	D												
N2 G3	A						0.084	0.060	NA				6
	E						0.065	0.065	0.334				
	D												
8G	A	0.079	0.051										2
	E	0.050	0.050										
	D												
9G	A	0.069	0.046										2
	E	0.050	0.050										
	D												
10G	A												2
	E												
	D												
	A												
	E												
	D												
	A												
	E												
	D												

**Comments:** Anti-whirl teeth are not like clearance dwg. No place to measure axial clearance.



## **BEARINGS**

### Thrust Bearing

#### Assembly:

The thrust bearing was disassembled and inspected. The plates and seal rings were in good condition and were re-used. Taper checks and flatness checks were performed on the plates. New shims were machined for rotor position and thrust clearance. The thrust ball was pinch checked and torque checked. The ball was scraped to achieve 85% contact. A 2 mil shim was added to the saddle to achieve 1 mils loose fit and torque of 1300 ft-lbs.

### Turbine Journal Bearing

#### Assembly; T1, T2

The T1 and T2 bearings were sent to the Pittsburgh Service Center for inspection and reconditioning. The pads were rebabbitted to restore correct radial position and bored for clearance to the rotor. New anti-rotation pins were installed. New upper rocker plates were installed due to wear in the pin holes. (The existing pads were re-used, these are an old modified rocker plate design which is obsolete.) The T1 bearing was bored to 16.016. T2 was bored to 16.991. NOTE: These bearings are the original joint feed design, and have not been modified to the individual pad feed type.

Consider obtaining new design bearing pads for the next HP/RH turbine inspection. New design pads have replaceable anti-rotation pin inserts in the upper pads.

### Oil Deflector

#### Assembly; T1, T2

The T1 and T2 oil deflectors were found rubbed and packed with coal dust. Both were retooled by AEP and aligned at assembly.




# Thrust Bearing Straddle

Date(m/d/y) 11/26/2005 Turbine Serial No. 170X394 Prepared by T. Kudas

INSPECTIONS & CHECKS				CODE	
Ball Contact Check	<u>X</u>	Runner Inspection	<u>X</u>	<b>X</b>	Work Carried Out
Ball Pinch Check	<u>X</u>	Wear Device Inspection		<b>N</b>	Not Done
Ball Torque Check	<u>X</u>	Screens and Orifices		<b>NA</b>	Not Applicable
Parallelism Check	<u>X</u>	Thermocouples Calib.		<b>C</b>	See Comments
Thrust Plate Inspection	<u>X</u>	Seal Rings Inspection	<u>X</u>	<b>V</b>	Visual Inspection
Babbitt Inspection	<u>X</u>			<b>MP</b>	Mag. Particle
				<b>UT</b>	Ultrasonic
				<b>PT</b>	Penetrant

### THRUST BEARING DATA

"A" Shim	.563"
"B" Plate	1.249"
"C" Shim	.415"
"D" Plate	1.262"
"E" Gasing	11.496"
"T" Total	14.985"
"F" Rotor	15.007"



### THRUST CLEARANCE

Clearance (F minus T)	.022"
Clearance (By float)	.022"
Difference	.000"
Stack Check	✓

### RUNOUT (mils TIL)

G	
H	

### BALL TORQUE

Ball Diam.		Inches
Reading	1300	Ft-Lb
Check		

### SEAL RING CLEARANCES

	Turbine End			Generator End		
	0°	90°	Out of Round	0°	90°	Out of Round
Seal Diameter (J)	15.009"	15.010"	.001"	15.011"	15.005"	.006"
Rotor Diameter (K)	15.000"	15.000"		15.000"	15.000"	
Clearance	.009"	.010"		.011"	.005"	

### Comments

2 mil shim was added at assembly for 1 mil loose pinch.



Thrust Bearing(a)



# Thrust Bearing

## Independently Mounted - Tapered Land

Date(m,d,y) 9/23/2005 Turbine Serial No. 170X394 Prepared by T. Perkins



Axial Location  
Gen  
 (Turb or Gen End)

Joint Orientation  
Vert  
 (Vert or Horiz)

Sketch in Joint Split (horizontal or vertical) and Land Number Sequence for Data Listed Below. Use Toolbar.

### LAND TAPER

Position/Land	1	2	3	4	5	6	7	8	9	10	11	12
<b>OD</b>	A	0	0	0	0	0	0	0	0	0		
	B	-2	-2	-1	-2	-2	-1	-1	-1	-1	-2	
	C	-5	-5	-4	-5	-6	-5	-5	-4	-4	-6	
	D	-8	-8	-8	-8	-9	-8	-9	-8	-8	-9	
	E	-12	-12	-12	-11	-13	-12	-12	-11	-12	-13	
<b>MEAN</b>	F	0	0	-1	-1	0	0	-1	-1	0	0	
	G	-2	-2	-2	-2	-2	-2	-2	-3	-2	-2	
	H	-5	-6	-6	-6	-5	-5	-6	-7	-6	-6	
	J	-9	-10	-10	-9	-9	-9	-9	-10	-10	-10	
	K	-14	-14	-14	-13	-14	-13	-14	-14	-14	-14	
<b>ID</b>	L	-1	-1	-2	-1	-1	-1	-1	-1	-1	-1	
	M	-2	-3	-4	-3	-2	-2	-2	-3	-3	-2	
	N	-7	-7	-7	-7	-7	-6	-6	-7	-8	-6	
	P	-10	-11	-11	-11	-10	-10	-10	-11	-11	-10	
	Q	-14	-15	-16	-15	-15	-14	-15	-16	-16	-15	
<b>LAND HAS TC (Yes or No)</b>												
<b>PERCENT *</b>												



\*Actual width of land (flat) in percent of total land width.

Comments



# Thrust Bearing Independently Mounted - Tapered Land

Date(m,d,y) 9/23/20005 Turbine Serial No. 170X394 Prepared by J. Groll



Axial Location  
TE  
(Turb or Gen End)

Joint Orientation  
Vert  
(Vert or Horiz)

Sketch in Joint Split (horizontal or vertical) and Land Number Sequence for Data Listed Below. Use Toolbar.

**LAND TAPER**

All readings are in mils

Position/Land	1	2	3	4	5	6	7	8	9	10	11	12
<b>OD</b>	A	0	0	0	0	0	0	0	0	0		
	B	-2	-2	-2	-2	-3	-3	-3	-3	-2	-1	
	C	-5	-6	-5	-5	-6	-7	-6	-7	-4	-3	
	D	-9	-9	-9	-8	-9	-10	-10	-10	-8	-7	
<b>MEAN</b>	E	-12	-13	-12	-13	-12	-13	-13	-13	-11	-9	
	F	0	0	0	0	0	-2	-1	-1	-1		
	G	-2	-2	-2	-2	-3	-4	-4	-4	-2	-2	
	H	-5	-6	-6	-6	-6	-8	-8	-8	-5	-5	
	J	-10	-10	-10	-10	-10	-12	-11	-12	-9	-9	
<b>ID</b>	K	-13	-14	-13	-13	-14	-15	-15	-15	-13	-12	
	L	0	-1	-1	-1	0	-3	-2	-2	-2	-1	
	M	-2	-2	-2	-3	-2	-5	-4	-4	-2	-3	
	N	-6	-6	-6	-7	-7	-9	-8	-8	-6	-6	
	P	-10	-11	-12	-11	-12	-14	-13	-13	-10	-11	
Q	-14	-14	-14	-15	-15	-17	-17	-16	-14	-14		
<b>LAND HAS TC (Yes or No)</b>												
<b>PERCENT*</b>												

\*Actual width of land (flat) in percent of total land width.

Comments



T1 Oil Deflector Coal Dust Contamination




# Oil Deflector

Date(m,d,y) 10/16/2005

Turbine Serial No. 170X394

Prepared by B. Haglock

INSPECTIONS & CHECKS				CODE	
Teeth Inspected	_____	_____	_____	<b>X</b>	Work Carried Out
Journals Inspected	_____	_____	_____	<b>N</b>	Not Done
Drain Holes Inspected	_____	_____	_____	<b>NA</b>	Not Applicable
Inspect for Rubs	_____	_____	_____	<b>C</b>	See Comments
	_____	_____	_____	<b>V</b>	Visual Inspection
<b>All retooled</b>	_____	_____	_____	<b>MP</b>	Mag. Particle
	_____	_____	_____	<b>UT</b>	Ultrasonic
	_____	_____	_____	<b>PT</b>	Penetrant



Location Number	Oil Deflector			Journal Dia	Clearance			Condition Comment
	A-Dia	B-Dia	C-Dia		Average	Min.	Max.	
T-1 OB	18.527"	18.527"	18.527"	18.497"	.030"	.030"	.030"	
T-1 IB	18.528"	18.530"	18.529"	18.497"	.032"	.031"	.033"	
T-2 OB	18.024"	18.020"	18.025"	17.991"	.032"	.029"	.034"	
T-2 IB	18.024"	18.020"	18.024"	17.991"	.032"	.029"	.033"	


**Comments:**

Oil Deflectors Final(a)



# Oil Deflector Alignment

Date (m,d,y) 12/2/2005 Turbine Serial No. 170X394 Prepared by T. Perkins



Deflector Location	POSITION (Mils)						CLEARANCE			IDEAL POSITION		
	1	2	3	4	5	6	Median	Min.	Max	Top	Bottom	Sides
T1	14	8	14	14	20	14	14	8	20	19	9	14
T2	13	6	13	13	20	13	13	6	20	17	9	13

**Comments**

Oil Deflector Alignment(a)



## LUBRICATION SYSTEM

### Main Oil Pump

#### Valve - Check;

The main oil pump check valve was disassembled and inspected. The stop nut was found too low, causing the disk to hit the pipe when open. The nut was built up with weld per customer procedure.

### Main Oil Pump

#### Assembly;

The main shaft driven oil pump was inspected. The seal rings were mic'd and were in good condition. The bearing had excess clearance and was rebabbitted by the customer. The casing was removed during the outage and a new gasket was installed to allow realignment. The casing was aligned transversely to the rotor after coupling alignment. Elevation was good after bearing shim changes. The steady bearing was movement checked and force checked and aligned at assembly.




# Main Oil Pump

## Centrifugal Pump, Double Suction

Date(m/d/y) 11/27/2005 Turbine Serial No. 170X394 Prepared by T. Perkins

INSPECTIONS & CHECKS		CODE
Mechanical Condition	<u>V</u>	<b>X</b> Work Carried Out
Internal Clearances	<u>X</u>	<b>N</b> Not Done
Bearing Condition & Clearance	<u>X</u>	<b>NA</b> Not Applicable
Steady Bearing Force and Movement Checks	<u>X</u>	<b>C</b> See Comments
		<b>V</b> Visual Inspection
		<b>MP</b> Mag. Particle
		<b>UT</b> Ultrasonic
		<b>PT</b> Penetrant



**STEADY BEARING FORCE CHECK**

FORCE(lbs)	MOVEMENT (inches)
500	_____
1000	_____
1500	_____
2500	_____
3000	_____
SLIPS	<u>2700#</u>

<b>Comments:</b>	

MOP Final(a)



## **TURNING GEAR**

### Turning Gear

#### Rod; Engagement

The turning gear toggle mechanism is not centered in its travel. This results in lower spring force holding it engaged, and the angle is just barely adequate to hold it disengaged.

The turning gear engagement mechanism should be inspected and repaired next opportunity.



## STANDARDS

### Front Standard

#### Assembly:

Rusted surfaces were found in the front standard and mid-standard. This could indicate water in the lube oil, or condensation from extended periods with the lube oil off during sectionalized maintenance.

Lube oil condition should be frequently monitored for water content to prevent rusting of oil side components.

### Mid Standard

#### Guard; A Coupling

While installing "A" coupling balance weights, an excessive amount of oil was spraying from the coupling guard. Possibly the orifice is missing from the spray line.

Investigate excessive "A" coupling oil spray next inspection. Check spray line orifice.



## CONTROL SYSTEM

### TSI

#### Detector; Thrust Position

The thrust position detector meter was set in the wrong direction at assembly, resulting in the position shifting from negative to more negative.

The thrust position detector should be readjusted to position the meter at zero when the rotor is centered in the thrust travel.

### TSI

#### Instrumentation; Key Phaser

Prior to start-up, the key phaser was not functioning when the unit was placed on turning gear. Investigation showed the notch in a different axial location than the removed rotor. The probe was moved about 1" toward the generator to line up with the notch. Also, during start-up, the key phaser became erratic at times. Customer personnel made changes to the electrical connections to correct the problem.

### TSI

#### Probe; T2 Right

During start-up, the 2X vibration probe failed. The connections were changed to the spare probe.

The key-phaser and #2 bearing vibration probe problems should be investigated and corrected next opportunity.



## ALIGNMENT & CLEARANCE OVERVIEW

A GE Laser Alignment Specialist performed a tops-on, tops-off laser alignment of the steam path. The line was fixed in each bolt-on packing casing for the tops-on, tops-off, so all movement is relative to the packing casing bores. During disassembly, titewire checks and distortion checks showed the packing casings in good alignment with the outer shell, so the lower halves were not removed this outage. The final tops-off line was set to compensate for existing distortion in the packing casings, and the shell was aligned to the rotor after coupling alignment to match these setpoints. (N1 was smaller vertically by .016. N3 was smaller vertically by .040. Reroundable packing was adjusted to correct for N3 distortion. The N1 distortion was minimal enough to use standard hook diameter packing.) The bolt-on packing casing bores were measured in both the tops-off, and tops-on shell bolted condition. No significant change in distortion was measured. A large change in internal component position was seen from tops-off to tops-on. The vertical movement of the components in the inner shell was in the range of .008 to .026 in the upward direction. The HP diaphragms moved about .005 to the left. The N2 and reheat diaphragms moved about .015 to the right. The out-of-plane upper inner shell joint probably contributed to this large lateral movement.

At disassembly, the generator end of the inner shell was found about .025 higher than the turbine end with respect to the outer shell joint. This condition had to be duplicated at assembly to achieve the expected float on the axial locating fit. Radial alignment of the shell bores was also good in this condition.

Comparing tops-off shell keys to gaps at disassembly showed the left side keys larger than the gaps by an additional .012 than the right side. Optical checks of the lower outer shell joint also showed the left side higher than the right by about .035. Optical and laser checks showed the lower shell four corners in plane, with only a 2 mil twist. (4 mils low at TE left with respect to other three corners.) This was corrected with final keys. The building keys were machined to make the key vs gap difference the same on all four corners, keeping the joint in plane and making it more level left to right, and matching the levelness with existing running keys. From this point, all shell key changes were made equal left to right. Final tops-off keys were sized to position the shell 10 mils higher than tops-on so the upper spill strips would not land on top of the bucket covers when the shells were in the unbolted condition.

During assembly, the #3 bearing was moved to the left to close up a large face opening at "B" coupling. (This large face opening was not seen at the disassembly coupling check.) This was done prior to the HP assembly, so the HP rotor was installed temporarily before the inner shell was installed to check the "A" coupling alignment. This confirmed the expected HP bearing side moves to correct the face and rim. The bearings were moved to the left based on this check and the shell was moved to match prior to installing the rotor in the steam path. The bearings were also raised to correct elevation at this time. However, coupling checks with upper components on showed the "A" face open now on the right. Shim changes were made to correct the alignment,



## **ALIGNMENT & CLEARANCE OVERVIEW**

but the full face correction was not realized. Based on inconsistent lateral face alignment at the couplings, it appears that the standards are moving laterally over time, back and forth, possibly with ambient condition changes.

Axial and radial clearances were approved by GE Engineering. All clearances were close to design except axial packing clearances in the reheat and at N3. The "X" clearances were progressively larger toward the generator from N2. No rotor packing land machining was done on the rotor. All bucket machining was based on the first stage wheel. Since wheel clearances and HP axial packing clearances were good, the existing rotor lands must be off drawing. (Rotor shorter.) Also, the N3 G5 "X" clearance is 1/16" larger than the other N3 grooves due to an original rotor machining deviation.



## **STARTUP COMMENTS**

The unit was first rolled 12/17/05, and tripped at about 200 rpm due to noise at the "C" coupling. The coupling cover was removed and a long bolt was found in the coupling guard rubbing the generator end windage covers. While the unit was down for this repair, tube leaks were found in the boiler. Boiler repairs were completed and the unit was rolled again 12/21/05. The unit had to be tripped several times below running speed due to high #4 bearing vibration. With the unit at speed, varying vibration data indicated rubs in the 2nd reheat. The unit was rolled and synchronized 12/22/05, still with high #4 bearing vibration, varying from 6 to 9 mils. Load was increased to 360 MW. T4 bearing was still in the 7 to 8 mil range, T2 was at 6 mils. The unit was shut down 12/23 for balance shots in the "A" and "B" couplings. The "B" coupling had the expected effects, but the "A" coupling showed a larger effect angle than expected. The unit was loaded to 660 MW and was removed from service 12/25/05 due to boiler tube leaks. The previous "A" coupling shot was rotated and a couple shot was installed in LP A. This reduced T2 and T4 to about 3.5 mils. Future trim shots were planned in the "A" and "B" couplings. (See attached data sheet.)



# Mitchell #2 Vibration Data Sheet

Date(m/d/y) 1/4/2006 Turbine Serial No. 170X394 Prepared by T. Perkins

DATE, TIME	FILTER	1X		2X		A COUPLING				3X		4X		B COUPLING				5X		6X	
		BRG	BRG	BRG	BRG	TURB END	GEN END	BRG	BRG	TURB END	GEN END	BRG	BRG	TURB END	GEN END	BRG	BRG	BRG	BRG		
LOAD/SPEED		AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG
12/23/05, 8:45	OUT	1.6		6.4						4.5		7.7						4.1		2.5	
356 MW	IN	1.5	284	6	39	8.9	270	7.5	260	4.5	33	7.6	136	9.5	0	9.5	5	4	108	2.2	302
12/23/05, 17:00	OUT	Added 12 oz @ 245 degrees in "A" cplg																			
Balance Shot	IN	Added 18 oz @ 300 degrees in "B" cplg																			
12/24/05, 8:20	OUT	1.8		5.3						3.2		4.7						2.9		3.2	
335 MW	IN	1.7	204	5.1	355	6.7	230	5.7	220	3.1	349	4.5	135	5	345	5	0	2.8	93	3	263
12/25/05, 3:33	OUT	1		5.5						2.8		5.2						2.6		3.6	
660 MW	IN	0.9	312	5.3	322	8.5	215	5.3	200	2.6	335	5	151	5.4	0	5.5	15	2.6	90	3.5	251
12/27/05, 12:00	OUT	Rotated previous "A" cplg shot from 245 to 205 degrees																			
Balance Shot	IN	Added 12.5 oz @ 225 degrees TE of LPA; added 12.5 oz @ 45 degrees GE of LPA																			
1/4/06, 13:02	OUT	0.7		3.4						1.8		3.6						1.7		1.7	
681 MW	IN	0.5	4	3.3	335	5.9	230	2.5	190	1.6	342	3.4	121	4.5	325	3.8	355	1.6	84	1.3	270
	OUT																				
	IN																				
	OUT																				
	IN																				
	OUT																				
	IN																				

Rotor Critical Speeds - \_\_\_\_\_  
 Frequency Scan - \_\_\_\_\_  
 Equipment Used - B/N - Brgs; IRD - Cplgs  
 Equipment Lag Angle - \_\_\_\_\_  
 Zero Ref Mark Color - \_\_\_\_\_  
 Inlet Oil Temp - \_\_\_\_\_

**Comments:**

Note: Phase angles are raw data. Key phaser is 45L. IRD data on couplings read at right horizontal joint.

Mitchell Vibration(a)



# Mitchell #2 Vibration Data Sheet

Date(m/d/y) 1/4/2006 Turbine Serial No. 170X394 Prepared by T. Perkins

DATE, TIME	LOAD/SPEED	FILTER	C COUPLING				7X		8X		D COUPLING				9X		10X		12X		13X	
			TURB	END	GEN	END	BRG	BRG	TURB	END	GEN	END	BRG									
			AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG	AMP	DEG
12/23/05, 8:45		OUT					0.8		1.5						1.8		3.2		0.7		2	
356 MW		IN	0.8	225	3	230	0.6	331	1.5	232	5	130	3	100	1.6	21	2.8	73	0.3	271	0.8	106
12/23/05,17:00		OUT	Added 12 oz @ 245 degrees in "A" cplg																			
Balance Shot		IN	Added 18 oz @ 300 degrees in "B" cplg																			
12/24/05, 8:20		OUT					0.8		2						1.9		3.2		0.7		2	
335 MW		IN	1.8	155	3.3	205	0.5	303	1.8	243	5.7	130	3.5	115	1.8	352	2.6	60	0.2	270	0.8	105
12/25/05, 3:33		OUT					1.4		1.3						2.9		3.7		0.7		1.7	
660 MW		IN	1.9	130	2.9	185	1.2	268	1.1	237	5.3	140	2.8	125	2.8	4	3.2	56	0.2	274	0.8	113
12/27/05,12:00		OUT	Rotated previous "A" cplg shot from 245 to 205 degrees																			
Balance Shot		IN	Added 12.5 oz @ 225 degrees TE of LPA; added 12.5 oz @ 45 degrees GE of LPA																			
1/4/06, 13:02		OUT					0.6		1.3						2.8		3.5		0.6		1.5	
681 MW		IN	0.1	350	2.2	220	0.4	325	1.1	239	4.6	125	2.5	100	2.7	16	3.1	55	0.2	249	0.7	114
		OUT																				
		IN																				
		OUT																				
		IN																				
		OUT																				
		IN																				

Rotor Critical Speeds - \_\_\_\_\_  
 Frequency Scan - \_\_\_\_\_  
 Equipment Used - B/N - Brgs; IRD - Cplgs  
 Equipment Lag Angle - \_\_\_\_\_  
 Zero Ref Mark Color - \_\_\_\_\_  
 Inlet Oil Temp - \_\_\_\_\_

**Comments:**

Mitchell Vibration(b)



**APPENDIX**