



**A Century of Firsts**

---

# Mitchell Station Unit #1

## American Electric Power Company

### Ohio Power Company



## Westinghouse T-G Set

800 MWs - Tandem Compound - 3600 rpm

VHP-HP Turbine	Serial Number	13A3160-1
IP Turbine	Serial Number	13A3161-1
LP Turbine #1	Serial Number	13A3162-1
LP Turbine #2	Serial Number	13A3163-1
Turbine Instruction Book		1250-C679
Generator	Serial Number	1-S-87P0755
Brush Collector	Serial Number	1-S-94P0063
Generator Instruction Book		90P0944
Brush Collector Instruction Book		1560-0093
Boiler Feed Pump Drive Turbine		15-A-2961-1
BFP/DT Instruction Manual		1150-C129
Spring Outage		4-1-2006 to 6-18-2006

## **Table of Contents**

<b>Executive Summary</b>	Page 5
<b>Resources</b>	
Outage AEP Key Personnel	Page 6
Outage Sub-contractors	Page 7
WO Numbers	Page 8
<b>Main Unit</b>	<b>Tab 1</b>
<b>IP Turbine Element</b>	
Rotor & Blading	Page 9
Stationary Blading	Page 9
Centerline Alignment	Page 9
Turbine Casings	Page 10
<b>Electric Generator</b>	
Rotor & Retaining Rings	Page 10
Stator & End Turns	Page 10
Hydrogen Glands	Page 10
Gland Seal Oil Skid	Page 11
<b>Brush Collector</b>	
Alignment	Page 11
<b>Pedestals &amp; Couplings</b>	
<b>Pedestal #1</b>	
Main Oil Pump	Page 12
Oil Deflector	Page 12
Bearing #1	Page 12
<b>IP Pedestal #2-#3</b>	
Oil Deflectors	Page 13
Bearing #2	Page 13
Bearing #3	Page 13

**IP Pedestal #4**

Oil Deflector Page13  
 Bearing #4 Page13

Rotor Coupling "A" Page 14  
 Rotor Coupling "B" Page 14  
 Rotor Coupling "C" Page 14

**Main Turbine Steam Flow Valves**

Main Stop Valves (4) Page 14  
 Control Valves (8) Page 15  
 Reheat Stop Valves (1<sup>st</sup> RHT RS) Page 15

**Drive Turbine**

Pedestals & Coupling Page 15

**Miscellaneous Inspections (Other)**

**Tab 2** Page 17  
 (2 Pages)  
 Columbus Generator Report (103 Pages)  
 CMS Work Performed Report (21 Pages)  
 Siemens Vibration Report (9 Pages)  
 MOP Pipe Weld Traveler (19 Pages)  
 Mitchell Boiler Outage

**Site Turbine Tools** **Tab 3** Page 18

**Recommendations** **Tab 4** Page 19

**Data Attachments**

**Tab 5** Page 20  
 Page 21  
 Page 22  
 Page 23  
 Page 24  
 Page 25  
 Page 26  
 Page 27  
 Page 28  
 Page 29  
 Page 30  
 Page 31  
 Page 32  
 Page 33

A1 – Field Drawing Rotor TE 39415 Shroud Dia.  
 A1 – Field Drawing Upper LO Cooler Lantern Fit  
 A1 – IP GNN Charting Review  
 A1 – IP GVN Charting Review  
 A1 – IP Packing Clearance page 1  
 A1 – IP Packing Clearance page 2  
 A1 – IP Packing Gap Review  
 A1 – IP Reaction Blade Clearance  
 A1 - IP S2 & S3 Blade GNN Clearance  
 A1 - IP S2 & S3 Blade GVN Clearance  
 A1 - IP S2 & S3 Blade Ring Alteration  
 A1 – Rotor L Reference Readings  
 A1 – IP Tite Wire Readings

A2 – Field Drawing #10 Oil Deflector	Page 34
A2 – Field Drawing H2 Cooler Cover Dimensions	Page 35
A2 – Field Drawing SOS Lantern Ring page 1	Page 36
A2 – Field Drawing SOS Lantern Ring page 2	Page 37
A2 – H2 Gland Casing	Page 38
A2 - H2 Seal Ring	Page 39
A3 – Vibration Data page 1	Page 40
A3 – Vibration Data page 2	Page 41
A4 – Field Drawing MOP Shim Plate - Split	Page 42
A4 – MOP Housing Bore Readings	Page 43
A4 – MOP Seal Ring Dimensions	Page 44
A4 – MOP Shaft Diameters	Page 45
A6 – Oil Bore Radial Readings	Page 46
A6 – Oil Deflector Clearances	Page 47
A6 – Tilting Pad Bearing Flood Ring Clearance	Page 48
A7 – Coupling A Alignment	Page 49
A7 – Coupling A Bolt Clearance	Page 50
A7 – Coupling A Runout	Page 51
A7 – Coupling B Bolt Clearance	Page 52
A7 – Coupling B Runout	Page 53
A7 – Coupling C Alignment	Page 54
A7 – Coupling C Bolt Clearance	Page 55
A7 – Coupling C Runout	Page 56
A7 – Coupling Spacer Spigot Inspection	Page 57
A8 – Governor Valve #1 Data	Page 58
A8 – Governor Valve #2 Data	Page 59
A8 – Governor Valve #3 Data	Page 60
A8 – Governor Valve #4 Data	Page 61
A8 – Governor Valve #5 Data	Page 62
A8 – Governor Valve #6 Data	Page 63
A8 – Governor Valve #7 Data	Page 64
A8 – Governor Valve #8 Data	Page 65
A8 – Throttle Valve #1 Data	Page 66
A8 – Throttle Valve #2 Data	Page 67
A8 – Throttle Valve #3 Data	Page 68
A8 – Throttle Valve #4 Data	Page 69
A8 – Throttle Valve #1 Settings	Page 70
A8 – Throttle Valve #2 Settings	Page 71
A8 – Throttle Valve #3 Settings	Page 72
A8 – Throttle Valve #4 Settings	Page 73
A9 – BFPT Coupling Alignment	Page 74

## **Executive Summary**

Mitchell Station Unit 1 was removed from service on Friday, 4/1/06 for a scheduled ten-week outage. The primary scope of the work included an inspection of the IP double flow turbine element (2<sup>nd</sup> Reheat) and the HP main steam flow valves.

RSO crews teamed with CMS personnel performed the inspection work during the outage. See below for the key personnel for the outage. All work was completed by 6/10/06, and the unit was released to the system on 6/18/06 after a successful start-up.

A brief summary of the work completed by the RSO and CMS crews during the outage is as follows:

- Disassembled/reassembled the double flow intermediate pressure turbine element
- Disassembled/reassembled the collector end electric generator casing end bell and hydrogen seal gland
- In-Situ inspection electric generator field rotor and stator
- Overhaul four main turbine stop valves
- Overhaul eight main turbine control valves
- Gasket replacement of the right side 1<sup>st</sup> reheat stop valve bonnet
- Cleaning of the main turbine lubrication oil coolers
- Cleaning of electric generator hydrogen seal oil skid coolers
- Cleaning of the electric generator stator water cooling skid coolers
- Cleaning of the EHC skid coolers and skid
- NDE inspection of the main unit low pressure turbine element(s) L-0 blading
- NDE inspection of the boiler feed pump drive turbine element L-0 blading.
- Replacement of BFPT drive coupling

Start-up of the main turbine occurred on 6/18/06. Less the vibration dampening at #11 bearing, all vibrations levels were acceptable to the plant personnel without field balancing for grid generation.

## Resources

### Internal

Steve Dolan  
Jack Huggins  
Ralph Pederson  
John Powell  
John Lackner  
Ron Kline  
Jeff Brothers  
Doug Foster  
Doug Graley  
Jim Cable

Mitchell Station  
Mitchell Station  
GET TSV TC  
GET TSV TC  
GET TSV Planning  
GET TSV RSO  
GET TSV RSO  
GET TSV RSO  
GET TSV CMS  
GET

Process Owner – Electric  
Rotating Equipment  
Lead Turbine Coordinator  
2<sup>nd</sup> Shift Turbine Coordinator  
Maintenance Planner  
Supervisor – Turbine Crew  
Supervisor – Turbine Crew  
Supervisor – Turbine Crew  
Non Destructive Examination  
Eng'g Turbine Engineer

**External**

Federal Industrial  
Mannings  
Cincinnati Babbitt  
Schmidt Industries  
Shutler Machining  
Steam Turbine Alternative Resources

Sandblasting Services  
Bolt Induction Heating Consultation  
Bearing Repairs  
Replacement Hi – Temp Fasteners  
Shop Machining Services  
Steam Path Packing

**WO Numbers**

See Attached Following Three Pages

## Main Unit

## Tab 1

### IP Turbine Element

#### Rotor & Blading

This equipment inspection involved the removal of the existing operating rotor, TD 44176, and its replacement with an OEM refurbished rotor, TD 39415. New style blading in rows 2 and 3 of refurbished CI rotor required the placement of new J hook seal strips in the #1 blade rings (GVN & GNN). The existing seal strips were machined level with the blade ring bore ID. New grooves were machined into blade path bores approximately  $\frac{3}{4}$ " from the existing labyrinth grooves. The grooves were located by instructions on OEM provided drawings, included later. The placement of new seal strip grooves was due to a change of the shroud width. The new style blades were an integral shroud design with no need for riveted cover shroud.

#### Stationary Blading

The blade rings (1 & 2; GVN & GNN) were shipped to CMS.

The #1 blade rings (GVN & GNN) were grit cleaned and NDE inspected. New row 1 blade diaphragms were installed. The installed diaphragms were machined to OEM provided drawings. The new diaphragm shroud width due to machining resulting in a new "K" dimension for charting and setting the rotor axial location. The rotor was moved 0.040" toward the GVN. The movement matched up within 0.007" of using the plant stored "A" and "C" coupling spacers installed originally with this rotor train. The new rotor blading of rows 2 and 3 resulted in new axial readings for proper charting.

The #2 blade rings (GVN & GNN) were grit cleaned and NDE inspected. Several rows of required repair welding of hard particle erosion (see CMS Shop Report).

#### Centerline Alignment

The centerline alignment of the internal IP components was performed with the tops off. The lower blade ring transverse alignment pockets required weld patches to be applied to one side or the other and field dressing to restore pin to pocket clearances of 0.005". The blade ring elevations were corrected at the horizontal joint as necessary. These vertical alignments were minor of about 0.010". The clearances of the internal split line key features in their respected cylinder pockets were opened up as necessary per Siemens Bulletin Operations and Maintenance Memo 148 (Support Key Vertical Clearances).

## Turbine Casings

The inner cylinder was grit blasted and NDE inspected in the field. The component halves were found in good condition and required no repairs. The inner to outer cylinder floating seal rings were manually cleaned and verified for freedom of movement before installation.

The outer cylinder was grit blasted and NDE inspected. The component halves were found in good condition. The lower cylinder exhaust bowl struts and their seal welds were found cracked. These were repair welded using 7018-A1 electrodes after removing the fractured inconel seal.

The inlet flow guide was found distorted. Past reports showed this to be a pre-existing condition. There appears to have no change to this component.

## Electric Generator

Rotor & Retaining Ring (see attached Columbus report)

Stator & End Turns (see attached Columbus report)

This was a rotor In-Situ inspection. See attachment for Columbus inspection report. All requested action items of this report were completed.

## Hydrogen Glands

The collector end generator end bell and hydrogen gland casing were disassembled to investigate the cause of hydrogen side seal oil entering the stator coil cavity during generation operation. This disassembly aided the Columbus Engineering interior inspections. The disassembly aided the mechanical inspection of the hydrogen gland casing and seal ring for condition and possible cause of oil leakage to the coil cavity. Inspections of the seal ring and gland casing found nothing of real note other than visual scuffmarks on the seal ring axial faces as it aligned to the upper half gland. The large diameter taper alignment pin to the right side of the gland casing had physical mechanical distress marks on it. Shutler Machine produced a new pin to replace the damaged item. Precision measurements of the gland casing and seal ring found clearances in expected acceptable conditions. The reassembly of the hydrogen gland casing and the end bell halves resulted in no greater than a 0.001" step at the horizontal joints.

The investigation of the oil egress into the coil cavity continued with the removal of inspection covers on the end bell defoaming tanks at each end of the generator. These tanks were found relatively clean with no foreign debris. The oil drain lines were inspected with a borescope camera back to the loop seal tank and nothing was found. The loop seal tank was drained and hand valves removed to visually inspect interior for debris; none found.

## Gland Seal Oil Skid

The air side and hydrogen side seal oil positive displacement pumps were shipped out for refurbishment at RPM. The air side pump after system testing required its bearing flanges shipped to Shutler Machine to establish "O" ring grooves to seal the heavy leakage from these mechanical joints.

The air side seal oil cooler(s) cooling water return loops were shipped to Shutler Machine to repair erosion damage at the lantern ring and "O" ring fit areas. These repairs (field drawings attached later) were necessary to return to the original seal techniques without use of RTV compound and other fixatives, which interfere with the movement of the cooler floating head.

## Brush Collector Rotor

### Alignment

The collector rotor was elevated at the #11 bearing to put a 0.003" gap at the bottom of the coupling. This gap is a deviation from the Siemens technical manual for this aftermarket equipment. The gap was established to put additional loading on the #11 bearing thus reduce the high vibrations being experienced during operation. The rotor was then put through a swing check to assure the outboard end of the rotor ran a crank of no more than 0.005" TIR with the coupling bolts at expected torque values. The TIR was 0.003" with torque values no more than 2400 foot-pounds and no less than 2000 foot-pounds.

This alignment activity above reduced the vibration energy when the rotor rolled through its critical speed, but the at speed vibration levels are above 6 mils. Operations continues to dampen this energy by controlling the hydrogen side seal oil and air side seal oil supply temperatures at a differential spread of approximately 30 degrees Fahrenheit. Operations has found this technique dampens the collector shaft vibration, at issue with this technique is the mechanical twisting of the brass/babbitt seal ring thus inhibiting the OEM intended floating in its gland casing groove. Operations have been using this technique since the brush collector installation. This twisted ring condition is a source of concern for seal oil entering the generator coil cavity. The amount of oil entering the collector end of the generator varied from shift to shift during the start up from barrels down to gallons per shift. The seal oil skid operation was reviewed and adjusted without much success. A thermograph review to the hydrogen side seal oil regulating tank showed it and the receiver tank full with hot return drain oil backed up the line toward the generator end bell defoaming tanks. The regulating tank appeared to not be operating properly. A boiler outage a short while later provided an opportunity to investigate the regulating tank float valves (see attached report). The adjustment of the float valve(s) dead band brought the seal oil entering the generator during operation down to four ounces per shift.

## **Pedestals & Couplings**

### **Pedestal #1**

#### **Main Oil Pump**

The front standard was disassembled to allow correction of experienced high main oil pump seal ring wear. The brass seal rings were fretting to destruction. The fretting activity had damaged the seal ring grooves of the pump housing. This work order removed the stub shaft and its mounted oil pump impellor from the HP rotor element-coupling flange. The stub shaft was shipped to CMS for inspection and repair. The stub shaft was disassembled to its smallest components and inspected (see CMS Shop Report). The stub shaft was reassembled and the impellor nut torqued to 1000 foot-pounds. The rotor was then checked for runout and the operational seal lands precision ground. The stub shaft was remounted to the HP turbine element pulling the coupling flange bolts to 600 foot-pounds. The swing test of the stub shaft revealed a TIR of 0.002”.

The pump housing seal grooves required weld repair and dimensional restoration. This required the parting of the suction and discharge pump lines below the concrete pier after cutting openings into the guard pipe. The removed pump housing base and cover were shipped to CMS for weld repair and machining (see CMS Shop Report). The sealing shim rings between the pump housing feet and the oil pedestal floor were replaced with split ring components to allow future elevation changes as needed without cutting supply and discharge piping. The thickness of the shim rings was cut to set the housing bore central to the pump impellor. This required lowering the pump housing 0.105” from as found. Field drawing of Shim Ring Detail attached later.

#### **Oil Deflector**

The oil deflector was removed to allow installation of the rotor jack during the rotor and shell movements needed to correct the “A” coupling alignment. The labyrinths were found in good condition but large diameter. The seal at reassembly was gapped 0.006” at the bottom and even at the sides.

#### **Bearing #1**

The tilting pad bearing sleeve was found in good condition. It was disassembled to support correction of HP element to the 2<sup>nd</sup> reheat IP element coupling alignment. Alignment is accomplished by changing dimension changes of the pucks between the bearing shell and babbitt pad. Upper pad clearances were restored after alignment completion.

### **IP Pedestal #2-#3**

#### Oil Deflectors

The oil deflectors were removed to allow installation of the rotor jack during the rotor and shell movements needed to correct the "A" coupling alignment. The #2 labyrinths were in good condition. The #3 labyrinths were found with excessive clearance and thus repaired at CBI. The deflectors at reassembly were gapped 0.005" to 0.006" at the bottom and even at the sides.

#### Bearing #2

The tilting pad bearing sleeve was found in good condition. It was disassembled to support correction of HP element to the 2<sup>nd</sup> reheat IP element coupling alignment. Coupling alignment is accomplished by changing dimensions of the pucks between the bearing shell and babbitt pad. Upper pad clearances were restored after alignment completion.

#### Bearing #3

The tilting pad bearing sleeve was shipped to Cincinnati Babbitt Inc to apply new babbitt to the pads for the replacement rotor journal. The rework of the pads also eliminated spalled babbitt edges. The pads were blued checked to a mandrel before setting the top pad(s) clearance to the rotor. The upper bearing pad(s) to journal clearances were corrected to design. Coupling alignment is accomplished by changing shims of the bearing shell outer spherical pads to the pedestal saddle.

### **IP Pedestal #4**

#### Oil Deflector

The #4 oil deflector was removed to allow removal of the rotor for the outage inspection. The labyrinths were found with excessive clearance as compared to the replacement rotor and thus repaired at CBI. The deflector at reassembly was gapped 0.005" to 0.006" at the bottom and even at the sides.

#### Bearing #4

The tilting pad bearing sleeve was shipped to Cincinnati Babbitt Inc to apply new babbitt to the pads for the replacement rotor journal. The rework of the pads also eliminated spalled babbitt edges. The pads were blued checked to a mandrel before setting the top pad(s) clearance to the rotor. The upper bearing pad(s) to journal clearances were corrected

to design. Coupling alignment is accomplished by changing shims of the bearing shell outer spherical pads to the pedestal saddle.

### **Rotor Coupling “A”**

The alignment of the HP element to the 2<sup>nd</sup> reheat IP element required the dropping the #1 bearing sleeve and the GVN of the HP shell to bring it into circular letter expectations. Difficulty was encountered developing repeatable sixteen point face readings. The most reliable repeatable readings were found taken at the rotor(s) spigot faces rather than the highly polished coupling head(s) friction surfaces.

### **Rotor Coupling “B”**

The coupling heads were inspected and found in good condition. This coupling assembles without axial spacer.

### **Rotor Coupling “C”**

The assembled 2<sup>nd</sup> reheat IP rotor element and jackshaft required very little movement of the #3 and #4 bearing sleeves to bring the “C” coupling to within circular letter expectations.

## **Main Turbine Steam Flow Valves**

### **Main Stop Valves (4)**

The valve bonnets were jacked out of their steam chests with difficulty due to oxide scale build up. This resulted in a number of jack bolt threads being damaged to complete the activity. The bonnets after valve plug removal were shipped to CMS to repair these threads. CMS installed double threaded sleeves as a repair. CMS at this time installed the fine mesh screens to the bonnet strainers. The fine mesh screens were stitch welded to the strainers. See CMS Shop Report.

Valve bonnets 2 and 4 required replacement of the backseat bushings due to damage in the backseat face. CMS completed the removal and installation of these items.

The valve plugs were disassembled down to their finest components. Two valve main plugs were replaced. A number of new parts were put into the four valve plug assemblies to complete the inspection and overhaul. The rebuild of the plug assemblies re-established the required component travels of the valves from the interior pilots to the stem themselves. The actuator dashpots were checked and found adequate at the time these components were ganged to the installed valve assemblies, not linkage adjustment

was necessary. The Belleville washer compression was reviewed and adjusted as needed after the unit start up.

### Control Valves (8)

The valve stands #4 and #6 were shipped to CMS to have the snout bushings reset, as these were pulled loose or cocked with respect to the stand itself at disassembly. Disassembly was hindered by oxide scale build up in the clearance between the steam chest bore and valve stand snout alignment interface. The stand #6 had a new snout bushing installed, as one was allowable. The #4 snout was pulled and reset. New bushings for the bushings should be in stock for the next valve inspection (quantity 8).

Many new parts were put in the valve plug and stem assemblies to restore sliding clearances or the correct plug damage. The dashpot of the actuators were checked and corrected when the linkages were assembled. The Belleville washer compression was reviewed and adjusted as needed. Several washer trays needed washer correction.

### Reheat Stop Valves (1<sup>st</sup> RHT RS)

The valve cover was removed to replace the failed flexitallic gasket. The component(s) sealing faces were found in good condition and did not require any repairs other than clean up. The gasket and cover were installed with the fasteners pulled to a 45KPSI preload using a torque wrench.

## **Drive Turbine**

### Pedestals & Couplings

The coupling between the drive turbine and the boiler feed pump was disassembled to the point of removing the coupling heads from both pump and turbine shaft. It was intended to install a new style coupling but was found not ready for this outage. The source of issue was an incorrect spool piece between the coupling heads.

The shaft fit areas and the old coupling head components were inspected for correct geometry and NDE'd for evidence of crack propagation, none found. The pump coupling head ID was blued to the shaft with good contact evident. The coupling heads were heated and put on with proper advance.

The GVN pedestal fasteners were removed one at a time and RTV sealant applied to the heads to eliminate an oil seepage path.

The EHC piping gas filled accumulators were recharged with nitrogen gas to resolve system behavior issues. No data was found as to when the Viton bladders were last changed out. Nothing more was heard about these during start up.

**Miscellaneous Inspections**

**Tab 2**

Columbus AEP Generator Report	(2 Pages)
CMS Work Performed Report	(103 Pages)
MOP Pipe Weld Traveler	(9 Pages)
Siemens Vibration Report	(21 Pages)
Mitchell Boiler Outage	(19 Pages)

## **Mitchell 1 Generator Inspection**

### **April 6, 2006**

Unit 1 generator was inspected with the rotor in place. The turbine end was entered via the riverside access cover, on the side of the generator. The collector end upper half endbell was removed. The single bushing well access cover was removed to allow for its inspection.

Generally the generator was in good condition. Heavy oil contamination was observed on the collector end. The turbine end had a light coating of oil.

### **Items Recommended For Completion During The 2006 Outage**

#### **Collector End Of The Stator**

1. Wipe the end turns with solvent dampened rags to remove the oil.
2. Wipe the collector end water hoses with dry rags to remove the oil drippings.
3. Investigate the water header supports at the 1:00 and 11:00 o'clock positions. Check the tightness of the locked tabbed bolts and tighten as required. Clean off the greasing on the surface of the water header supports.
4. Vacuum up the paint chips at the top of the stator. They are mostly concentrated between the bars next to the core.

#### **Equalizing Line**

The stator water equalizing line, which runs from the collector end to the turbine end is scheduled for replacement during this outage.

A new line will be run parallel to the existing line. The existing line will be retired in place.

Present plans are to fabricate a new line outside of the generator stator and complete the final two welds in the stator.

Support of the new line is planned to be by using epoxy saturated glass roving around the new line, existing retired line and the larger diameter gas distribution pipe in the top of the stator. Note: The larger diameter gas distribution pipe has holes drilled on the side. These are at approximately the 5:00 o'clock position when facing the collector end of the generator. Dacron epoxy saturated felt should be used to pad the new line, old line and gas distribution line.

To provide greater airflow during the welding and epoxy loaded material installation, remove the second cover on the turbine end, opposite the cover already removed.

A small person will be required to install the epoxy materials in the top of the generator stator.

Consideration should be given to installing the new line between the old equalizing line and the gas distribution pipe.

### Bushing Well

The angled bushings have deep puddles of oil at their bases. Generally the bushing well is very oily. The oil needs wiped up and the interior of the bushing well needs wiped with clean rags.

### Collector Rings and Brush Rigging

Clean the flyash and carbon deposits from the brush supports. Clean the base area of the collector rings and brush rigging.

### Generator Rotor

At the collector end, clean the accessible dust and oil out from under the retaining ring.

Megger the generator field with 50 vdc for ten minutes, when all repairs are completed.

### Generator CT's

The generator CT area is coated with flyash and dirt. Wipe the CT's and supports off with solvent dampened rags.

While in the area, change the Isophase bus air intake filter. It is very dirty.

### Collector Ring Dog House

1. Wipe down the interior of the doghouse to remove the oil, carbon dust and flyash.
2. Clean off the oil and flyash on the exterior of the doghouse, at the shaft entrance area.
3. Replace the filters on the top of the exciter doghouse.

Steve Ridenbaugh  
AEP-Columbus  
200-1465

Dan Shriver  
AEP-Columbus  
200-2138



**AMERICAN  
ELECTRIC  
POWER**

DATE: July 20, 2006

SUBJECT: MITCHELL PLANT UNIT 1  
PLANNED SPRING 2006 OUTAGE

FROM: B. K. Mabe – Central Machine Shop

TO: W. L. Irons / C. W. George – Mitchell Plant

Attached is a report concerning the work CMS performed during this planned spring Unit 1 outage. If you have questions concerning the report or require additional information, please contact me.

C: D. J. Sculley – GET Engineering  
File – CMS

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 1  
JULY 20, 2006

## **NDE INSPECTIONS PERFORMED AT MITCHELL PLANT**

### **LOW PRESSURE "A" AND "B" TURBINE ROTORS**

Magnetic particle (wet fluorescent) inspection of the last stage blades (L-0 Stage) on the "A" and "B" low pressure turbine rotors revealed no defect indications (cracks) are present on the rotors

### **BEARINGS**

Ultrasonic inspection of the T-3, T-4 and T-11 bearings housing to babbett bond revealed a satisfactory bond on all three bearings.

### **STUD BOLTS**

Ultrasonic inspection of the 2rh. turbine outer shell stud bolts revealed no defect indications (cracks) are present.

Ultrasonic inspection of the 2rh turbine inner shell studs revealed no defect indications (cracks) are present.

Ultrasonic inspection of the 2rh turbine packing gland studs revealed no defect indications (cracks) are present.

Ultrasonic inspection of the four throttle valve studs revealed no defect indications (cracks) are present.

Ultrasonic inspection of the eight governor valve studs revealed no defect indications (cracks) are present.

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 2  
JULY 20, 2006

## NDE INSPECTIONS PERFORMED AT MITCHELL PLANT(continued)

### FLOW GUIDE BOLTS


Ultrasonic inspection of the low pressure "A" turbine and low pressure "B" turbine steam flow guide bolts revealed no defect indications (cracks) are present.

### VALVES

#### THROTTLE VALVES

Visible dye inspection of the four throttle valve stellite seats revealed no defect indications (cracks) are present in valves # 1, 2 and 3. Valve #4 has one small crack and, in another location, has three pits (porosity) that are linked together.

MITCHELL PLANT UNIT 1  
SPRING 2006 OUTAGE



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 3  
JULY 20, 2006

## **NDE INSPECTIONS PERFORMED AT MITCHELL PLANT**(continued)

### **THROTTLE VALVES** (CONTINUED)

Magnetic particle inspection of the inside and outside of the four (4) throttle valve bodies revealed no defect indications (cracks) are present.

### **GOVERNOR VALVES**

Magnetic particle (wet fluorescent) inspection of the governor valve chests (2) revealed no defect indications (cracks) are present. The non-stellite governor valve seats have visual areas of erosion in the seat area. There is a 1/4" crack on the bypass pipe weld to the flange and a 3/4" long crack on the flange face outlet hole.

Magnetic particle (wet fluorescent) inspection of the governor valve stands revealed one with an 1/8" to 1/4" long crack beside the rabbit fit on the inside section of the stand.

### **HAND SHUT OFF VALVES**

Magnetic particle (wet fluorescent) inspection of the hand shut off valve welds revealed the following:

- 12<sup>th</sup> Floor – Penthouse 5R vent valve – 2 welds – No defect indications (cracks)
- 12<sup>th</sup> Floor – Penthouse 6L vent valve – 2 welds – No defect indications (cracks)
- 11<sup>th</sup> Floor – Drain Valve 11R – 3 welds – No defect indications (cracks)
- 11<sup>th</sup> Floor – Drain valve 12R – 3 welds – No defect indications (cracks)
- 11<sup>th</sup> Floor – Drain valve 13R – 2 welds – No defect indications (cracks)
- 11<sup>th</sup> Floor – Drain valve 14R – 2 welds – No defect indications (cracks)
- 11<sup>th</sup> Floor – Drain valve 13L – 2 welds – No defect indications (cracks)
- 11<sup>th</sup> Floor – Drain valve 14L – 2 welds – No defect indications (cracks)
- 11<sup>th</sup> Floor – Drain valve 7L – Inside Penthouse – 1 weld – No defect indications (cracks)
- 7<sup>th</sup> Floor – Drain valve 19R – 4 welds – No defect indications (cracks)
- 5<sup>th</sup> Floor – Drain valve 25R – 3 welds – No defect indications (cracks)

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 4  
JULY 20, 2006

## **NDE INSPECTIONS PERFORMED AT MITCHELL PLANT**(continued)

### **HAND SHUT OFF VALVES** (CONTINUED)

- 5<sup>th</sup> Floor – Drain valve 25R – 3 welds – No defect indications (cracks)
- 5<sup>th</sup> Floor – Drain valve 25L – 2 welds – No defect indications (cracks)
- 5<sup>th</sup> Floor – Drain valve 29L – Inside boiler – 1 weld – No defect indications (cracks)
- 5<sup>th</sup> Floor – Drain valve 29R – 2 welds – No defect indications (cracks)
- 5<sup>th</sup> Floor – Drain valve 30R – 2 welds – No defect indications (cracks)
- 5<sup>th</sup> Floor – Drain valve 30L – 2 welds – No defect indications (cracks)

Magnetic particle (wet fluorescent) inspection of hand shut off valve 32R welds (2) revealed no defect indications (cracks) are present.

### **DRAIN LINE WELD REPAIRS**

Magnetic particle inspection of the following drain line weld repairs revealed the following:

- Pass 5 to 6 bottle drain – Coupling weld repairs just outside of boiler – No defect indications (cracks) are present.
- #3 Main Stop Valve – Below seat drain line – Weld repair to the west side of 1<sup>st</sup> hand shut off valve – No defect indications (cracks) are present.
- #31L Boiler Drain – Inspection of welds on one (1) hand shut off valve and 1 butt weld on the outside of the boiler at the “T” above small expansion joint and two (2) 1” line welds on the inside of the boiler revealed no defect indications (cracks) are present.

### **2<sup>ND</sup> REHEAT STEAM LINE**

Magnetic particle inspection of the **cover pass weld on the gamma plug** revealed no defect indications (cracks) are present.

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 5  
JULY 20, 2006

## **NDE INSPECTIONS PERFORMED AT MITCHELL PLANT**(continued)

### **DEAERATOR**

Magnetic particle (wet fluorescent) inspection of the deaerator circumferential (all) welds on the outside of the deaerator, the inlet lines welds, the outlet lines welds, the small lines welds, the stiffener leg support welds, the pressure relief valve welds and manway welds revealed no defect indications (cracks) are present.

Magnetic particle (wet fluorescent) inspection of the deaerator pad weld at the outside northeast corner revealed no defect indications (cracks) are present.

Magnetic particle inspection of the deaerator next to last circumferential weld and the seam weld between the next to last and last hemi head circular weld in the back end of the deaerator revealed the weld has eroded away on a 18" long area of the circular weld on the south wall. This was a previously weld repaired area.

Magnetic particle (wet fluorescent) inspection of the welds inside of the deaerator in an area toward the backside of the deaerator revealed the following:

- #5 -- Donut weld at back pipe – No defect indications (cracks) are present.
- #3 -- Circumferential weld at back hemi head – No defect indications (cracks) are present.
- #6 -- Big line weld at center buck – No defect indications (cracks) are present.
- #2 & #8 -- Hemi Head pad welds – No defect indications (cracks) are present.
- #10 -- Arc strike – No defect indications (cracks) are present.
- #11 -- Arc strike – No defect indications (cracks) are present.
- #12 -- Arc strike – No defect indications (cracks) are present.
- #13 -- Arc strike – No defect indications (cracks) are present.
- #15 – Two (2) small 90° welds at the south wall – No defect indications (cracks) are present. Two (2) top 4" pipe welds – No defect indications (cracks) are present. Two(2) 14" pipe welds at south wall – No defect indications (cracks) are present.

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 6  
JULY 20, 2006

## **NDE INSPECTIONS PERFORMED AT MITCHELL PLANT**(continued)

### **DEAERATOR**(continued)

- #1 Pad weld at northeast lower wall has a area with cracks.
- Magnetic particle inspection of the circumferential weld repair on the inside and outside of the deaerator on the south wall revealed no defect indications (cracks) in the weld repairs.
- Magnetic particle inspection of the outside cover pass on two 14" heater drains where they go through the shell wall revealed both welds are free from defect indications (cracks).
- A section of plate was removed from the south east corner of the deaerator was reinstalled and a magnetic particle inspection of the welds cover pass on the inside and outside revealed no defect indications (cracks) are present. A entry door was installed into the section of plate and a magnetic particle inspection revealed no defect indications (cracks) are present in the inside and outside root, and cover pass welds.

### **HEATERS**

Magnetic particle (wet fluorescent) inspection of the #1 low pressure heater shell revealed no defect indications (cracks) in the inside circumferential welds, the inside seam welds, the inside inlet nozzle welds and the inside spray nozzle welds.

Ultrasonic inspection was performed to the inlet nozzles to determine wall thickness. The inspection was started at the back nozzle and moving to the front. Approximately

Ten (10) thickness readings at each location revealed the following:

- Back nozzle – Pipe thickness -- .493" to .565".
- Back nozzle - - Shell part of nozzle -- .625" to .795".
- 2<sup>nd</sup> nozzle – Pipe thickness -- .475" to .580"

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 7  
JULY 20, 2006

## **NDE INSPECTIONS PERFORMED AT MITCHELL PLANT**(continued)

### **HEATER INLET NOZZLE THICKNESS READINGS**(continued)

- 2<sup>nd</sup> nozzle – Shell part of nozzle -- .619” to .782”
- 3<sup>rd</sup> nozzle – Pipe thickness -- .419” to .567”
- 3<sup>rd</sup> nozzle – Shell part of nozzle -- .642” to .793”
- 4<sup>th</sup> nozzle – Pipe thickness -- .427” to .558”
- 4<sup>th</sup> nozzle – Shell part of nozzle -- .637” to .802”
- 5<sup>th</sup> nozzle – Pipe thickness -- .429” to .508”
- 5<sup>th</sup> nozzle – Shell part of nozzle -- .682” to .793”
- Front nozzle – Pipe thickness -- .489” to .528”
- Front nozzle – Shell part of nozzle -- .693” to .728”

Magnetic particle inspection of the #1 low pressure heater front heater shell circumferential weld where a small “C” shaped section was cut from the shell for alignment purposes revealed no defect indications (cracks) are present after weld repair was completed. The root pass, halfway out and the cover pass welds were inspected when the shell segment was weld back into place.

### **BOILER FEED PUMP TURBINE**

Ultrasonic inspection of the boiler feed pump turbine rotor shaft from the pump end to the governor end revealed no defect indications (cracks) are present

Magnetic particle (wet fluorescent) inspection of the boiler feed pump turbine rotor pump end and governor end L-0 blades revealed no defect indications (cracks) are present.

Magnetic particle(wet fluorescent) inspection of the boiler feed pump couplings and coupling covers revealed no defect indications (cracks) are present.

### **PRIMARY AIR FAN**

Magnetic particle inspection was performed to the outboard bearing journal on the fan shaft and no defect indications (cracks) are present.

### **MAIN OIL PUMP LINES**


Magnetic particle (wet fluorescent) inspection of the main oil pump suction and discharge leg welds revealed no defect indications (cracks) are present.

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 8  
JULY 20, 2006

## **NDE INSPECTIONS PERFORMED AT MITCHELL PLANT**(continued)

### **SECOND REHEAT TURBINE OUTER LOWER HALF SHELL**

Visible dye inspection of sixteen (16) stiffener brace welds revealed twelve (12) of the brace welds have cracks. The 1-1/4" to 1-1/2" long cracks were ground and weld repairs to the 12 cracked welds was completed. A follow up visible dye inspection revealed no defect indications (cracks) remain after weld repair.




MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 9  
JULY 20, 2006

**NDE INSPECTIONS PERFORMED AT MITCHELL PLANT**(continued)


**SECOND REHEAT TURBINE OUTER LOWER HALF SHELL**(continued)

The following is a sketch showing the location of the twelve (12) cracked welds on the eight (8) stiffener braces:

MITCHELL PLANT UNIT 1  
SPRING 2006 PLANNED OUTAGE



2ND REHEAT TURBINE SHELL LOWER HALF SUPPORT BRACES (STRUTS)




MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 10  
JULY 20, 2006

**NDE INSPECTIONS PERFORMED AT MITCHELL PLANT**(continued)


**SECOND REHEAT TURBINE OUTER UPPER HALF SHELL**(continued)

The following is a sketch showing the location of three (3) cracked welds of 16 welds on the eight (8) stiffener braces:

MITCHELL PLANT UNIT 1  
SPRING 2006 PLANNED OUTAGE



**2ND REHEAT TURBINE OUTER SHELL UPPER HALF SUPPORT BRACES (STRUTS)**



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 11  
JULY 12, 2006

## **OUTAGE WORK PERFORMED @ MITCHELL PLANT BY CMS**

### **SECOND REHEAT TURBINE OUTER SHELL SUPPORT STRUTS (BRACES) (CONTINUED)**

CMS personnel traveled to Mitchell Plant and ground to remove cracks from the second reheat turbine outer shell support struts. The ground areas were weld repaired. After welding was completed a visible dye inspection of the welded areas revealed no defect indications (cracks) are present.

MITCHELL PLANT UNIT 1  
 PLANNED 2006 SPRING OUTAGE  
 PAGE 12  
 JULY 20, 2006

## OUTAGE WORK PERFORMED @ CMS

### #1 BLADE RING

The #1 and #2 governor and generator end blade rings were transported to CMS where the following tasks were performed:


- The row 1 blades governor and generator end were removed and new row 1 blades were installed and machined to the correct configuration and dimensions.

MITCHELL PLANT UNIT 1  
 NEW 2RH TB 1ST ROW BLADES  
 GEN END #1 BR  
 APRIL 2006

WESTINGHOUSE REPORTS THERE IS .125"  
 OF EXTRA STOCK ON BOTH SIDES OF THE  
 BLADE ROOT  
 WESTINGHOUSE ALSO REPORTS THE DESIGN GROOVE  
 WIDTH IS 2.921" AND THE .125" OF EXTRA STOCK ON EACH  
 SIDE WAS BASED ON THIS WIDTH.

APRIL 29, 2006

14



FINISH MACHINING DRAWING FOR GOV. & GEN ENDS  
 OF MITCHELL PLANT UNIT 1 2ND REHEAT TURBINE  
 STATIONARY 1ST ROW BLADES APRIL 29, 2006

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 13  
JULY 20, 2006

## **OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

### **#1 BLADE RING (CONTINUED)**

- The governor and generator end 1<sup>st</sup> stage blades were removed, new blades were installed and machined.
- Impact damage and eroded areas in the 2<sup>nd</sup> and 3<sup>rd</sup> stage blade vane sections were repaired by straightening and welding. The welded areas were finish ground and all blades were NDE inspected after repairs. These inspections revealed no defect indications (cracks) remain.
- The #1 blade ring upper half was set on the lower half and dimensions were taken and recorded. The upper and lower halves were then bolted together and dimensions were taken and recorded to determine how the blade rings moved diametrically after being bolted as opposed to being free standing. See attachments below for dimensions.
- All seals were removed, new seals were installed and were machined to the correct diameters with the upper and lower half bolted together.
- The **row 2 and row 3 stationary seal grooves were moved** to make the blade ring(carrier) compatible with 2RH rotor TD 39415 which was installed during this outage. This rotor had modified blades installed at Siemens Westinghouse and requires a different seal configuration. The blade ring new seal grooves were machined per Siemens Westinghouse drawings 9D13676, 9D13686 and 9D13683 to change the location of the seals and establish the correct diameter for the seals.



MITCHELL PLANT UNIT 1  
 PLANNED 2006 SPRING OUTAGE  
 PAGE 14  
 JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#1 BLADE RING (CONTINUED)**

**MITCHELL #1 GOV. END BLADE CARRIER**

BOLTED	
UNBOLTED	X

	ROW 1		ROW 2		ROW 3	
A	34.449	34.444	36.324	36.337	38.225	38.241
B	34.441	34.445	36.351	36.368	38.258	38.291
C	34.441	34.432	36.328	36.356	38.257	38.286
	DIS	ADM	DIS	ADM	DIS	ADM



DATE: May 3, 2006  
 TAKEN BY: Josh Duncan



MITCHELL PLANT UNIT 1  
 PLANNED 2006 SPRING OUTAGE  
 PAGE 15  
 JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#1 BLADE RING (CONTINUED)**

**MITCHELL #1 GOV. END BLADE CARRIER**

BOLTED	X
UNBOLTED	

	ROW 1		ROW 2		ROW 3	
A	34.420	34.425	36.304	36.318	38.202	38.226
B	34.423	34.428	36.345	36.362	38.251	38.283
C	34.433	34.433	36.347	36.347	38.245	38.275
	DIS	ADM	DIS	ADM	DIS	ADM




DATE: May 3, 2006  
 TAKEN BY: Josh Duncan

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 16  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#1 BLADE RING (CONTINUED)**

**MITCHELL U-1 #1 GOV. END BLADE CARRIER JULY 2006**





MITCHELL PLANT UNIT 1  
 PLANNED 2006 SPRING OUTAGE  
 PAGE 17  
 JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#1 BLADE RING (CONTINUED)**

**MITCHELL #1 GEN. END BLADE CARRIER**

BOLTED	
UNBOLTED	X

	ROW 1		ROW 2		ROW 3	
A	34.405	34.406	36.299	36.280	38.211	38.196
B	34.405	34.406	36.327	36.305	38.254	38.219
C	34.405	34.406	36.342	36.318	38.251	38.224
	DIS	ADM	DIS	ADM	DIS	ADM



DATE: May 3, 2006  
 TAKEN BY: Sam Halstead



MITCHELL PLANT UNIT 1  
 PLANNED 2006 SPRING OUTAGE  
 PAGE 18  
 JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#1 BLADE RING (CONTINUED)**

**MITCHELL #1 GEN. END BLADE CARRIER**

<b>BOLTED</b>	<b>X</b>
<b>UNBOLTED</b>	

	ROW 1		ROW 2		ROW 3	
<b>A</b>	34.404	34.406	36.293	36.279	38.202	38.191
<b>B</b>	34.404	34.406	36.325	36.307	38.252	38.222
<b>C</b>	34.405	34.406	36.338	36.319	38.246	38.223
	DIS	ADM	DIS	ADM	DIS	ADM




**DATE: May 3, 2006**  
**TAKEN BY: Sam Halstead**

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 19  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#1 BLADE RING (CONTINUED)**

**MITCHELL U-1 #1 GEN. END BLADE CARRIER JULY 2006**



MITCHELL PLANT UNIT 1  
 PLANNED 2006 SPRING OUTAGE  
 PAGE 20  
 JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**



**#2 BLADE RING**

- Impact damage and eroded areas in the vane sections of all stages were repaired by straightening and welding. The welded areas were finish ground and all blades were NDE inspected after repairs. These inspections revealed no defect indications (cracks) remain.
- The #2 blade ring upper half was set on the lower half and dimensions were taken and recorded. The upper and lower halves were then bolted together and dimensions were taken and recorded to determine how the blade rings moved diametrically after being bolted as opposed to free standing dimensions. See attachments below for dimensions.
- All seals were removed, new seals were installed and the new seals were machined to the correct diameters with the upper and lower half bolted together.

**MITCHELL PLANT UNIT 1 #2 GOV. END BLADE CARRIER JULY 2006**  
**MITCHELL #2 GOV. END BLADE CARRIER**

<b>BOLTED</b>	
<b>UNBOLTED</b>	<b>X</b>

	ROW 4		ROW 5		ROW 6	
A	40.043	40.026	41.927	41.916	43.928	43.940
B	40.055	40.035	41.919	41.900	43.909	43.921
C	40.040	40.029	41.908	41.890	43.903	43.921
	DIS	ADM	DIS	ADM	DIS	ADM



DATE: April 30, 2006  
 TAKEN BY: Halstead and Pence



MITCHELL PLANT UNIT 1  
 PLANNED 2006 SPRING OUTAGE  
 PAGE 21  
 JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#2 BLADE RING (CONTINUED)**

**MITCHELL U-1 #2 GOV. END BLADE CARRIER JULY 2006**

<b>BOLTED</b>	<b>X</b>
<b>UNBOLTED</b>	

	ROW 4		ROW 5		ROW 6	
A	40.039	40.024	41.924	41.909	43.932	43.920
B	40.051	40.035	41.924	41.906	43.927	43.914
C	40.041	40.029	41.929	41.896	43.927	43.906
	DIS	ADM	DIS	ADM	DIS	ADM




DATE: MAY 1, 2006  
 TAKEN BY: SMOOT & PENCE

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 22  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#2 BLADE RING (CONTINUED)**

**MITCHELL U-1 #2 BLADE RING JULY 2006**





MITCHELL PLANT UNIT 1  
 PLANNED 2006 SPRING OUTAGE  
 PAGE 23  
 JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#2 BLADE RING (CONTINUED)**

**MITCHELL #2 GEN. END BLADE CARRIER**

BOLTED	
UNBOLTED	X

	ROW 4		ROW 5		ROW 6	
A	40.082	40.047	41.939	41.921	43.938	43.925
B	40.023	39.993	41.890	41.878	43.893	43.877
C	40.034	40.007	41.887	41.875	43.895	43.889
	DIS	ADM	DIS	ADM	DIS	ADM



DATE: May 1, 2006  
 TAKEN BY: Smoot and Pence



MITCHELL PLANT UNIT 1  
 PLANNED 2006 SPRING OUTAGE  
 PAGE 24  
 JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**#2 BLADE RING (CONTINUED)**

**MITCHELL U-1 #2 GEN. END BLADE CARRIER**

<b>BOLTED</b>	<b>X</b>
<b>UNBOLTED</b>	

	ROW 4		ROW 5		ROW 6	
A	40.059	40.030	41.925	41.909	43.931	43.921
B	40.038	40.022	41.900	41.882	43.912	43.897
C	40.029	40.014	41.897	41.879	43.900	43.983
	DIS	ADM	DIS	ADM	DIS	ADM




**DATE: May 1, 2006**  
**TAKEN BY: Smoot and Pence**

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 25  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**#2 BLADE RING (CONTINUED)**

**MITCHELL U-1 #2 BLADE RING JULY 2006**



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 26  
JULY 20, 2006

## **OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

### **CIRCULATING WATER PUMP IMPELLER "11 A & 11 B"**


The 11 A circulating water pump impeller assembly was transported to CMS for inspection and repair. The following is a description of the repairs performed:

- Magnetic particle(wet fluorescent) inspection of the exposed areas on the circulating water pump shafts revealed no defect indications (cracks) are present.
- The impeller assembly was disassembled for cleaning and inspection.
- The type 304 stainless steel impeller has areas of cavitation on the vane sections. These areas of cavitation were ground to produce a smooth surface. The ground areas were weld repaired using ER308L stainless steel filler metal. The area to be welded was preheated only enough to remove moisture prior to welding.
- Areas of erosion on the outside of the flow guide were filled using Defcon Ceramic Repair 11700 then the outside of the flow guide was coated with Chesterton 855 to prevent erosion damage.
- The impeller assembly was reassembled using new packing sleeves and new bearings. All other assembly components were reused.
- See sketches below for dimensional information:

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 27  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**


MITCHELL U-1 CWP JULY 2006  
IMPELLER AXIAL POSITION & ROTATION  
PUMP 11 A  
SKETCH #1



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 28  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**

**MITCHELL U-1 CWP IMPELLER ASSEMBLY JULY 2006**  
**PUMP 11 A**  
**SKETCH #2**



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 29  
JULY 20, 2006


**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**  
**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**

MITCHELL U-1 CWP 11A SHAFT JULY 2006

**PUMP 11 A**

SKETCH #3

EXISTING SHAFT WAS REUSED (AS RECEIVED)  
COUNTERCLOCKWISE ROTATION




DATE: 4-18-06  
RECORDED BY: Mike Smoot

MITCHELL U-1 CWP SLEEVES (NEW) JULY 2006


**NEW SLEEVES**

SKETCH #4

**PUMP 11 A**



DATE: May 15, 2006  
RECORDED BY: Pyles/Harpold



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 30  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**


**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**

**MITCHELL UNIT 1 CWP 11 A JULY 2006**


**SKETCH #5**

**PUMP 11 A  
BEARING  
HOUSINGS**

**INBOARD  
HOUSING**



**OUTBOARD  
HOUSING**



MIC DIRECTLY  
WHERE THE  
BEARING FITS.

DATE: 4-18-06  
RECORDED BY: Mike Smoot

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 31  
JULY 20, 2006


## OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### CIRCULATING WATER PUMP IMPELLERS (CONTINUED)

MITCHELL U-1 CWP 11 A JULY 2006

FINAL RUNOUT CHECKS WITHOUT PACKING SLEEVES

CWP PUMP 11 A



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 32  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**


**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**

MITCHELL U-1 CWP 11A JULY 2006

**RUNOUT CHECKS WITH PACKING SLEEVES**

**CWP 11 A**

SKETCH #7




**FINAL**  
RUNOUT CHECK

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 33  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**

**MITCHELL U-1 CWP 11 A  
PARTS DESCRIPTION  
SKETCH #8**




MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 34  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**

**MITCHELL U-1 CWP 11A  
BRONZE PACKING RINGS  
ID AND OD DIAMETERS**

SKETCH #9



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 35  
JULY 20, 2006

## **OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

### **CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**

The 11 B circulating water pump impeller assembly was transported to CMS for inspection and repair. The following is a description of the repairs performed:

- The impeller assembly was disassembled for cleaning and inspection.
- The type 304 stainless steel impeller has areas of cavitation on the vane sections. These areas of cavitation were ground to produce a smooth surface. The ground areas were weld repaired using ER308L stainless steel filler metal. The area to be welded was preheated only enough to remove moisture prior to welding.
- Areas of erosion on the outside of the flow guide were filled using Defcon Ceramic Repair 11700 then the outside of the flow guide was coated with Chesterton 855 to prevent erosion damage.
- The impeller assembly was reassembled using new packing sleeves and new bearings. All other assembly components were reused.

See sketches below for dimensional information:


MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 36  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**



MITCHELL U-1 CWP 11 B JULY 2006  
**IMPELLER AXIAL POSITION & ROTATION  
PUMP 11 B**

SKETCH #1



COUNTERCLOCKWISE

CLOCKWISE



DATE: 4-18-08  
RECORDED BY: Rick Stiekley

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 37  
JULY 20, 2006


### OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### CIRCULATING WATER PUMP IMPELLERS (CONTINUED)

MITCHELL U-1 CWP 11B JULY 2006

### PUMP 11 B

#### SKETCH #2



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 38  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**


**MITCHELL U-1 CWP SHAFT 11B JULY 2006**

EXISTING  
SHAFT  
DIAMETERS

CLOCKWISE ROTATION

**CWP SHAFT 11B**

**SKETCH #3**



DATE: 4-18-06  
RECORDED BY: Rick Stickley


MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 39  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**

MITCHELL U-1 CWP 11B FINAL RUNOUT CHECKS JULY 2006  
RUNOUT CHECKS WITHOUT PACKING SLEEVES  
PUMP 11 B

**SKETCH #4**



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 40  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**


MITCHELL U-1 CWP 11 B JULY 2006  
**RUNOUT CHECKS WITH PACKING SLEEVES**

**PUMP 11 B**

**FINAL**

**RUNOUT CHECK**

**SKETCH #5**



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 41  
JULY 20, 2006


**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**


**MITCHELL U-2 CWP 11 B JULY 2006**

**PUMP 11 B**

INBOARD  
BEARING  
HOUSING



OUTBOARD  
BEARING  
HOUSING



MIC DIRECTLY  
WHERE THE  
BEARING FITS.

DATE: 4-18-06  
RECORDED BY: Mike Smoot

SKETCH #6

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 42  
JULY 20, 2006


**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**CIRCULATING WATER PUMP IMPELLERS (CONTINUED)**

MITCHELL U-1 CWP 11B JULY 2006

**PARTS DESCRIPTION**

**SKETCH #7**



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 43  
JULY 20, 2006


## OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### MAIN OIL PUMP HOUSING

The main oil pump housing was transported to CMS where it was weld repaired and machined. See attached sketch for area that was welded and machined.

### MITCHELL UNIT 1 MAIN OIL PUMP HOUSING

THERE ARE TWO GROOVES TO MACHINE IN THE  
LOWER HALF AND ONE GROOVE IN THE UPPER HALF



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 44  
JULY 20, 2006

## OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### THROTTLE VALVE BONNETTS (4)

The throttle valve bonnets were transported to CMS and the following work was performed:

- The existing screens were removed from the strainer part of the bonnet and new screens were installed. The existing screens were bolted to the strainer. The new screens were stitch welded to the strainer body per the procedure below:

Band the new screen to insure it is tight against the body of the strainer.


Preheat the strainer to 250 degrees F.

Use ER410 stainless filler metal and tack weld the screen to the strainer body. After a tack is deposited hit it with a hammer to make sure it is against the strainer body. Start at the center of the strainer body and tack both sides starting from the center and working both sides toward the ends.

After the strainer has been tacked around the circumference and across both ends insure the strainer body weld area is preheated to a minimum of 250 degrees and maintain this during welding.

Secure the screen to the strainer body using 1-1/2" long stitch welds on 9" centers with ER410 stainless steel. Do not leave craters at the ends of the welds. That will give us a 7-1/2" space between the end of one tack weld and the beginning of another tack weld.

INSURE FINISHED WELD IS  
SLIGHTLY CONVEX WITH NO  
CRATERS @ END OF WELD



The intercept valve bonnet jack bolt holes were drilled to a larger diameter and tapped to repair the damaged holes.

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 45  
JULY 20, 2006

## OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### COUPLING SPACERS

The 2<sup>nd</sup> reheat (IP) turbine and generator end coupling spacers were transported to CMS where they were ground to the following thicknesses:

TB End = 1.424" final thickness.


GEN End = 1.3995" final thickness.

### #4 GOVERNOR VALVE

A new bushing was installed in the #4 governor valve and was machined to the following dimensions:

#### MITCHELL UNIT 1 #4 GOVERNOR VALVE

INSTALLED NEW BUSHING  
MACHINED RABBET FITS TO 5.572




DATE: May 8, 2006  
TAKEN BY: Rick Lovejoy

MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 46  
JULY 20, 2006

### OUTAGE WORK PERFORMED @ CMS (CONTINUED) LUBE OIL COOLER SPOOL PIECE

The lube oil cooler spool piece was transported to CMS where it was modified by machining to reduce the overall length and to reestablish the fits in one end.

### MITCHELL U-1 OIL COOLER SPOOL PIECE LANTERN RING FIT JULY




MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 47  
JULY 20, 2006

### OUTAGE WORK PERFORMED @ CMS (CONTINUED)

#### LUBE OIL COOLER SPOOL PIECE (CONTINUED)

The lube oil cooler spool piece was transported to CMS where it was modified by machining to reduce the overall length from 17-7/8" to 16-3/8" and to reestablish the lantern ring fits its in one end.


MITCHELL PLANT UNIT 1  
LUBE OIL COOLER SPOOL PIECE  
MAY 2006



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 48  
JULY 20, 2006

**OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

**LUBE OIL COOLER SPOOL PIECE (CONTINUED)**



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 49  
JULY 20, 2006

## OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### SECOND REHEAT TURBINE ROTOR CONTROL ROTOR

The control rotor for the second reheat turbine rotor was transported to CMS for repair of rough areas on the fits. The following tasks were performed on the control rotor:


- The rotor was set up in a lathe and incoming runout readings were taken.
- Several fits on the control rotor were ground and the final sizes were recorded.
- Final runout readings were taken and recorded.

See the following sketches for detailed information:

### MITCHELL UNIT 1 SECOND REHEAT TURBINE ROTOR CONTROL ROTOR

JULY 2006

#### INITIAL RUNOUTS




MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 50  
JULY 20, 2006

## OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### SECOND REHEAT TURBINE ROTOR CONTROL ROTOR (CONTINUED)

MITCHELL UNIT 1 SECOND REHEAT TURBINE ROTOR CONTROL ROTOR JULY 2006

FINAL DIAMETERS  
AFTER FITS WERE  
GROUND



DATE: May 4, 2006  
RECORDED BY: Ron Taylor


MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 51  
JULY 20, 2006

## OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### SECOND REHEAT TURBINE ROTOR CONTROL ROTOR (CONTINUED)

MITCHELL UNIT 1 2ND REHEAT TURBINE ROTOR CONTROL ROTOR JULY 2006

FINAL RUNOUTS  
WITHOUT STUB  
SHAFT BOLTED ON




MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 52  
JULY 20, 2006

## OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### SECOND REHEAT TURBINE ROTOR CONTROL ROTOR (CONTINUED)

MITCHELL UNIT 1 SECOND REHEAT TURBINE ROTOR CONTROL ROTOR JULY 2006

FINAL RUNOUTS AFTER STUB SHAFT  
WAS REATTACHED AND FITS WERE  
GROUND




MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE  
PAGE 53  
JULY 20, 2006

## **OUTAGE WORK PERFORMED @ CMS (CONTINUED)**

### **SECOND REHEAT TURBINE ROTOR CONTROL ROTOR(CONTINUED)**

MITCHELL PLANT UNIT 1  
2RH TB ROTOR  
CONTROL ROTOR  
APRIL 2006

ML U-1 2RH TB ROTOR CONTROL ROTOR



MITCHELL PLANT UNIT 1  
PLANNED 2006 SPRING OUTAGE

PAGE 54


JULY 20, 2006

## OUTAGE WORK PERFORMED @ CMS (CONTINUED)

### SECOND REHEAT TURBINE ROTOR CONTROL ROTOR (CONTINUED)

MITCHELL PLANT UNIT 1  
2RH TB ROTOR  
CONTROL ROTOR  
APRIL 2006

ML U-1 2RH TB ROTOR CONTROL ROTOR






MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 76 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 3-31-06

ACCOUNT NUMBER 40595243-06

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item A & B L.P. Turbine Spindles

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - A, 000

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant

9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the governor & generator ends of the L-O stage blades of both rotors. Results showed no cracks.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Graley & Strickland


DATE 3-31-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

**ULTRASONIC TEST REPORT**  
**AMERICAN ELECTRIC POWER**  
**CENTRAL MACHINE SHOP**  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303



WORK ORDER NO. ~~40594989-06~~ 40594989-06 DATE 4-18-06

**1. IDENTIFICATION:**

Facility Mitchell Item Turbine Bearings  
PC/SN Unit 1

**2. TECHNIQUE:**

Straight Beam     Angle Beam     Frequency -  1 MH     2.25 MH     5 MH  
 Search Angle -  90°     45°     60°     Single Transducer     Dual Transducer

Type of Couplant Ultra Gel II Test Unit Krautkramer USK 7D

**3. CALIBRATION - REFLECTOR TYPE:**  Drilled Hole     V. Notch     IIW Block     Other \_\_\_\_\_

**4. INSPECTION PROCEDURE:** MI-1-5-2-4

**5. INSPECTION SPECIFICATIONS:** \_\_\_\_\_

**6. TYPE OF INDICATION:**

1. Crack     2. Lamination     3. Corrosion/Erosion     4. Internal Voids     5. Linear

**7. SKETCH/DESCRIPTION:**

A ultrasonic inspection was performed to the following turbine bearings to detect if babbitt bond was at acceptable levels.

T3 Bearing - 4/H - 4/H - Bond OK  
T4 Bearing - 4/H - 4/H - Bond OK  
T11 Bearing - 4/H - 4/H - Bond OK


**8. INSPECTION PERFORMED BY:** (AEP Level II UT Inspector)

Signature Doug Dralcy DATE 4-18-06

**9. APPROVED BY:** (NDE Supervisor)

Signature \_\_\_\_\_ DATE \_\_\_\_\_

**ULTRASONIC TEST REPORT**  
**AMERICAN ELECTRIC POWER**  
**CENTRAL MACHINE SHOP**  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303



WORK ORDER NO. 40594989-06  
40595680-03 DATE 4-18-06

1. IDENTIFICATION:  
Facility Mitchell Item Stud Bolts  
PC/SN Unit 1

2. TECHNIQUE:  
 Straight Beam  Angle Beam  Frequency -  1 MH  2.25 MH  5 MH  
 Search Angle -  90°  45°  60°  Single Transducer  Dual Transducer  
Type of Couplant Ultra Gel II Test Unit Kraut Kramer USK7D

3. CALIBRATION - REFLECTOR TYPE:  Drilled Hole  V. Notch  IIW Block  Other \_\_\_\_\_

4. INSPECTION PROCEDURE: MI-1-5-2-4


5. INSPECTION SPECIFICATIONS: \_\_\_\_\_

6. TYPE OF INDICATION:  
 1. Crack  2. Lamination  3. Corrosion/Erosion  4. Internal Voids  5. Linear

7. SKETCH/DESCRIPTION:  
A ultrasonic inspection was performed to the following studs.  
Reheat Shell  
Outer shell Studs - OK  
Inner Shell Studs - OK  
Packing Gland Studs - OK  
  
Throttle Valves (4) - Studs OK  
Governor Valves (8) - Studs OK

8. INSPECTION PERFORMED BY: (AEP Level II UT Inspector)  
Signature Doug Draley DATE 4-18-06

9. APPROVED BY: (NDE Supervisor)  
Signature \_\_\_\_\_ DATE \_\_\_\_\_



**ULTRASONIC TEST REPORT**  
**AMERICAN ELECTRIC POWER**  
**CENTRAL MACHINE SHOP**  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303

WORK ORDER NO. 40595243-06 DATE 4-19-06

**1. IDENTIFICATION:**

Facility Mitchell Item Steam Flow Guide Bolts  
PC/SN Unit 1

**2. TECHNIQUE:**

Straight Beam     Angle Beam     Frequency -  1 MH     2.25 MH     5 MH  
 Search Angle -  90°     45°     60°     Single Transducer     Dual Transducer

Type of Couplant Ultra Gel II Test Unit Krautkramer USK7D

**3. CALIBRATION - REFLECTOR TYPE:**  Drilled Hole     V. Notch     IIW Block     Other \_\_\_\_\_

**4. INSPECTION PROCEDURE:** MI-1-5-2-4

**5. INSPECTION SPECIFICATIONS:** \_\_\_\_\_

**6. TYPE OF INDICATION:**

1. Crack     2. Lamination     3. Corrosion/Erosion     4. Internal Voids     5. Linear

**7. SKETCH/DESCRIPTION:**

A ultrasonic inspection was performed to the generator & governor end flow guide bolts of A and B L.P. rotors. Results showed no cracks.


**8. INSPECTION PERFORMED BY: (AEP Level II UT Inspector)**

Signature Doug Eraley 4-19-06  
DATE

**9. APPROVED BY: (NDE Supervisor)**

Signature \_\_\_\_\_ DATE \_\_\_\_\_

LIQUID PENETRANT INSPECTION REPORT  
AMERICAN ELECTRIC POWER  
CENTRAL MACHINE SHOP  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303



WORK ORDER NO. 40595680-03

DATE 4-18-06

1. IDENTIFICATION:

Facility Mitchell  
PC/SN Unit 1  
Item Throttle Valve Stellite Seats

2. MATERIAL:

Ferrous  Nonferrous

3. TECHNIQUE:

Visible Dye  Fluorescent  
 Water Washable

4. MFG/TYPE: Cleaner \_\_\_\_\_ Penetrant \_\_\_\_\_ Developer \_\_\_\_\_

5. INSPECTION PROCEDURE: MI-1-5-2-2

6. INSPECTION SPECIFICATIONS: \_\_\_\_\_

7. TEMPERATURE: Ambient \_\_\_\_\_ Surface \_\_\_\_\_


8. TYPE OF INDICATION:

Crack  Linear  Inline Porosity  Rounded  Other \_\_\_\_\_

9. SKETCH/DESCRIPTION:

A visible dye inspection was performed to the stellite seats of the 4 throttle valves.

Value #1 - Seat OK  
Value #3 - Seat OK  
Value #2 - Seat OK



Value #4

10. INSPECTION PERFORMED BY: Doug Graley  
AEP Level II PT Inspector Signature

4-18-06  
DATE


11. APPROVED BY: \_\_\_\_\_  
NDE Supervisor Signature

\_\_\_\_\_  
DATE

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 201-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 81 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 4-18-06

ACCOUNT NUMBER 40595680-03

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Combined Throttle-Governor  
Valve Bodies

2. TECHNIQUE:

Dry Powder       Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil    Prods    Yoke    Clamps  
Central Conductor

4. CURRENT TYPE:       AC    DC

5. AMP TURNS - 51000  
Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack    2. Linear Surface    3. Linear Subsurface    4. Undercut    5. Non Relevant

9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the inside and outside of the throttle (4) valves and the governor valve chest (2). No cracks were found, but most governor valve seat areas have erosion. These seats are not stellite.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Daley

DATE 4-18-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 82 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkie Avenue, Bldg. 309  
South Charleston, West Virginia 25303

CMS NUMBER 4059680-08

DATE 4-19-06



ACCOUNT NUMBER \_\_\_\_\_

1. IDENTIFICATION

Facility MITCHELL - U1  
PC/SN \_\_\_\_\_

Item GOV. VALUE

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - 3000

6. INSPECTION PROCEDURE: MI 1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant

9. SKETCH/DESCRIPTION: A MT INSPECTION WAS PERFORMED ON THE FOLLOWING.

VALUE STAND - THERE WAS  $\frac{1}{8}$ " TO  $\frac{1}{4}$ " CRACKS BESIDE THE RADIUS FIT ON I.D. SECTION OF THE STAND

VALUE BODY - THERE WAS A  $\frac{1}{4}$ " CRACK ON THE BYPASS PIPE WELD TO FLANGE. THERE WAS CRACKS NOTED IN THE RADIUS OF THE VALUE BODY BUSHING, ALSO MARKED WAS A  $\frac{3}{4}$ " CRACK ON THE FLANGE FACE OUTLET HOLE.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature STRICKLAND

DATE 4-19-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 83 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 5-11-06

ACCOUNT NUMBER 40594989

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Hand Shut off Valve Welds

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant

9. SKETCH/DESCRIPTION:

12th Floor - Penthouse  
SR Vent Valve - 2 welds - OK ✓  
6L Vent Valve - 2 welds - OK ✓  
11th Floor - Drain Valves  
11R - 3 welds - OK ✓  
13R - 2 welds - OK ✓  
14R - 2 welds - OK ✓  
12R - 3 welds - OK ✓  
13L - 2 welds - OK ✓  
14L - 2 welds - OK ✓  
7L - Inside Penthouse - 1 weld - OK ✓

7th Floor - Drain Valves  
19R - 4 welds - OK ✓  
8th Floor - Drain Valves  
25R - 3 welds - OK ✓  
25L - 2 welds - OK ✓  
29L - Inside Boiler - 1 weld - OK ✓  
29R - 2 welds - OK ✓  
30R - 2 welds - OK ✓  
30L - 2 welds - OK ✓

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Graley

DATE \_\_\_\_\_

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

CMS NUMBER \_\_\_\_\_

✓ DATE 5-19-06

ACCOUNT NUMBER \_\_\_\_\_

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item 32R Hand Shutoff Valve welds

2. TECHNIQUE:

Dry Powder     Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:     AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to the two welds of the valve. Results showed no defects.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Draley

DATE 5-19-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 85 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

✓  
DATE 5-19-06

CMS NUMBER \_\_\_\_\_

ACCOUNT NUMBER \_\_\_\_\_

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item 31 L Boiler Drain

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to 1 hand shut off valve weld and 1 butt weld on the outside of the boiler and 2 welds at the "t" above small expansion joint and 2-1" lines welds on the inside of the boiler. All welds were O.K.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Haley

DATE 5-19-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 86 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 4-17-06

ACCOUNT NUMBER 40594989-06

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 2

Item Drain Line Weld Repairs

2. TECHNIQUE:

Dry Powder     Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:     AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the following weld repairs:

Pass 5 to 6 Bottle Drain - Coupling weld repairs just outside of boiler - OK

#3 Main Stop Valve - Below Seat Drain Line - weld repair to the west side of 1st hand shutoff valve - OK

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Draley

DATE 4-17-06

11. APPROVED BY: (NDE Supervisor)


Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 87 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 5-19-06

ACCOUNT NUMBER 40594989

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item 2nd Reheat Steam Line

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:

AC  DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE:

MI-1-5-2-3

7. INSPECTION SPECIFICATIONS:

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to the cover pass weld of the gamma plug. Results showed no cracks.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Shaley

DATE 5-19-06

11. APPROVED BY: (NDE Supervisor)


Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 88 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 4-26-06

ACCOUNT NUMBER 40594634-10

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Deaerator

2. TECHNIQUE:

Dry Powder     Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:     AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to the welds on the outside of deaerator. The welds included all circumferential, seam, inlet lines, outlet lines, small lines, stiffner, leg support, pressure relief valves and manway. Results showed no cracks.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Douglas Bradley

DATE 4-26-06


11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

# MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 5-4-06

ACCOUNT NUMBER 40594634-10

## 1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Decelerator Pad Weld

## 2. TECHNIQUE:

Dry Powder       Wet Fluorescent  
 Non Fluorescent

## 3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:       AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

## 8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to the weld pad area at the outside northeast corner. Results showed no cracks.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Bradley

DATE 5-4-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_



# MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 90 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

CMS NUMBER \_\_\_\_\_

DATE 5-25-06

ACCOUNT NUMBER \_\_\_\_\_

## 1. IDENTIFICATION

Facility Mitchell

Item Deaerator

PC/SN Unit 1

## 2. TECHNIQUE:

- Dry Powder
- Wet Fluorescent
- Non Fluorescent

## 3. EQUIPMENT:

- Coil
- Prods
- Yoke
- Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

## 8. TYPE OF INDICATION FOUND:

- 1. Crack
- 2. Linear Surface
- 3. Linear Subsurface
- 4. Undercut
- 5. Non Relevant

9. SKETCH/DESCRIPTION: The new 14" drain lines were installed through the deaerator wall on the south side. A seal weld was made to both drain lines on the inside of deaerator. The welds were background from the outside to good metal. A magnetic particle inspection was performed to the inside & outside welds of both lines. All welds were O.K. The cover pass on the outside welds will be inspected after completion.

## 10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Tralcy

DATE 5-25-06


## 11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

# MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 5-11-06

ACCOUNT NUMBER 40594634-10

## 1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Deaerator

## 2. TECHNIQUE:

Dry Powder       Wet Fluorescent  
 Non Fluorescent

## 3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:       AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

## 8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to the next to last circumferential weld and the seam, weld between next to last and last (hem head) circ. weld in the back end of deaerator. Results showed heavy erosion (weld missing) on a 18" long area of the circ. weld on the south wall of a previously repaired area.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Draley

DATE 5-11-06

11. APPROVED BY: (NDE Supervisor)


Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 92 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 5-15-06

ACCOUNT NUMBER 40594634

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Deaerator-Inside

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant

9. SKETCH/DESCRIPTION: The following areas were inspected toward the backside-inside of deaerator, Location

- # 5 - Donut Weld at Back Pipe - OK
- # 3 - Circ. Weld - Hemi Head - Back - OK
- # 6 - Big Line Weld - Center Back - OK
- # 2 - Pad Weld - Hemi Head - OK
- # 8 - Pad Weld - Hemi Head - OK
- # 10 - Arc Strike - OK
- # 11 - Arc Strike - OK
- # 12 - Arc Strike - OK
- # 13 - Arc Strike - OK
- # 14 - Angle Bracket Weld - OK
- # 15 - 2 - Small 90° Welds - South Wall - OK
- 2 - Top 4" Pipe Welds - OK

2 - 14" Pipe Welds - South Wall - OK  
# 1 - Pad Weld - Northeast Lower Wall -  Cracked Area

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)


Signature Douglas G. Haley

DATE 5-15-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_



### MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

CMS NUMBER \_\_\_\_\_

DATE 6-7-06

ACCOUNT NUMBER 40594634

**1. IDENTIFICATION**

Facility Mitchell  
PC/SN Unit 1

Item Deaerator

**2. TECHNIQUE:**

Dry Powder     Wet Fluorescent  
 Non Fluorescent

**3. EQUIPMENT:**

Coil     Prods     Yoke     Clamps

**4. CURRENT TYPE:**     AC     DC

**5. AMP TURNS -** Parker Probe

**6. INSPECTION PROCEDURE:** MI-1-5-2-3

**7. INSPECTION SPECIFICATIONS:** \_\_\_\_\_

**8. TYPE OF INDICATION FOUND:**

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

**9. SKETCH/DESCRIPTION:** A magnetic particle inspection was performed to the outside cover pass on the two 14" heater drains where they go through the shell wall. Both welds were O.K.

**10. INSPECTION PERFORMED BY:** (AEP Level II MT Inspector)

Signature Doug Traley

DATE 6-7-06

**11. APPROVED BY:** (NDE Supervisor)


Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 34 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 5-19-06

ACCOUNT NUMBER 40594634-10

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Deaerator

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to the circumferential weld repair on the inside & outside of the deaerator on the south wall, Results showed the repairs were O.K.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Bailey

DATE 5-19-06

11. APPROVED BY: (NDE Supervisor)


Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 95 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 5-9-06

ACCOUNT NUMBER 40701930-21

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item # 1 L.P. Heater Shell

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to the circumferential, seam, inlet nozzles and spray nozzle weld on the inside of the heater shell. Results showed no cracks.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Huley

DATE 5-9-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

**ULTRASONIC TEST REPORT**  
**AMERICAN ELECTRIC POWER**  
**CENTRAL MACHINE SHOP**  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303

WORK ORDER NO. 40701930-21

DATE 5-9-06

**1. IDENTIFICATION:**

Facility Mitchell Item #1 L.P. Heater Inlet Nozzles  
PC/SN Unit 1

**2. TECHNIQUE:**

Straight Beam     Angle Beam     Frequency -  1 MH     2.25 MH     5 MH  
 Search Angle -  90°     45°     60°     Single Transducer     Dual Transducer

Type of Couplant Ultra Gel II Test Unit Krautkramer USK 7D

**3. CALIBRATION - REFLECTOR TYPE:**  Drilled Hole     V. Notch     IIV Block     Other \_\_\_\_\_

**4. INSPECTION PROCEDURE:** MI-1-5-2-4

**5. INSPECTION SPECIFICATIONS:** \_\_\_\_\_

**6. TYPE OF INDICATION:**

1. Crack     2. Lamination     3. Corrosion/Erosion     4. Internal Voids     5. Linear

**7. SKETCH/DESCRIPTION:** A ultrasonic inspection was performed to the inlet nozzles to determine wall thickness, starting at the back nozzle ~~to~~ and moving to the front. Approx. ten thickness readings each place.

Back Nozzle  
Pipe - .493 to .565  
Shell Part of Nozzle - .625 to .795

2nd Nozzle  
Pipe - .475 to .580  
Shell Part of Nozzle - .619 to .782

3rd Nozzle  
Pipe .419 to .567  
Shell Part of Nozzle .642 to .793

4th Nozzle  
Pipe .427 to .558  
Shell Part of Nozzle .637 to .802

5th Nozzle  
Pipe .429 to .508  
Shell Part of Nozzle .682 to .793

Front Nozzle  
Pipe .489 to .528  
Shell Part of Nozzle .693 to .728

**8. INSPECTION PERFORMED BY:** (AEP Level II UT Inspector)

Signature Doug Huley

**9. APPROVED BY:** (NDE Supervisor)


Signature \_\_\_\_\_

5-9-06  
DATE

DATE

### MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 6-8-06

ACCOUNT NUMBER 40594634

**1. IDENTIFICATION**

Facility Mitchell  
PC/SN Unit 1

Item Deaerator

**2. TECHNIQUE:**

- Dry Powder     Wet Fluorescent  
 Non Fluorescent

**3. EQUIPMENT:**

- Coil     Prods     Yoke     Clamps

**4. CURRENT TYPE:**     AC     DC

**5. AMP TURNS -** Parker Probe

**6. INSPECTION PROCEDURE:** MI-1-5-2-3

**7. INSPECTION SPECIFICATIONS:** \_\_\_\_\_

**8. TYPE OF INDICATION FOUND:**

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

**9. SKETCH/DESCRIPTION:** The section of plate that was cut out of the south east corner of the deaerator was re-installed. A magnetic particle inspection was performed to the ~~root~~ cover pass on the inside. The outside weld was ground back to clean weld and a inspection was performed. A final inspection was performed to the outside cover pass. A entry door was installed into the section of plate, a inspection was performed to the root and cover pass on the inside and to the 2 cover passes on the outside. All inspections showed no defects

**10. INSPECTION PERFORMED BY:** (AEP Level II MT Inspector)

Signature Doug Dralcy


DATE 6-8-06

**11. APPROVED BY:** (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

**ULTRASONIC TEST REPORT**  
**AMERICAN ELECTRIC POWER**  
**CENTRAL MACHINE SHOP**  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303



WORK ORDER NO. 45894989-06

DATE 4-19-06

**1. IDENTIFICATION:**

Facility Mitchell  
PC/SN Unit 1

Item BFP Turbine Rotor Shaft

**2. TECHNIQUE:**

Straight Beam     Angle Beam  
 Search Angle -  90°     45°     60°

Frequency -  1 MH     2.25 MH     5 MH  
 Single Transducer     Dual Transducer

Type of Couplant Ultra Gel II

Test Unit Krautkramer USK 7.0

**3. CALIBRATION - REFLECTOR TYPE:**     Drilled Hole     V. Notch     IIW Block     Other \_\_\_\_\_

**4. INSPECTION PROCEDURE:** MI-1-5-2-4

**5. INSPECTION SPECIFICATIONS:** \_\_\_\_\_

**6. TYPE OF INDICATION:**

1. Crack     2. Lamination     3. Corrosion/Erosion     4. Internal Voids     5. Linear

**7. SKETCH/DESCRIPTION:**

A ultrasonic inspection was performed to the shaft from the pump end. Results showed no cracks.

**8. INSPECTION PERFORMED BY:** (AEP Level II UT Inspector)

Signature Doug Daley

4-19-06  
DATE

**9. APPROVED BY:** (NDE Supervisor)

Signature \_\_\_\_\_

DATE

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 99 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 3-31-06

ACCOUNT NUMBER 40595243-06

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item BFP Turbine Rotor Blades

2. TECHNIQUE:

Dry Powder     Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:     AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS:

8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the pump & turbine end L-O stage blades. Results showed no cracks.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Graley & Strickland

DATE 3-31-06

11. APPROVED BY: (NDE Supervisor)


Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 100 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 4-28-06

ACCOUNT NUMBER 40594989-06

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item 1/4 Reheat Outer Shell

2. TECHNIQUE:

Dry Powder       Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:       AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to the 12 weld repairs on the shell stiffener braces (struts). Results showed all repairs were o.k.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Huley

DATE 4-28-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

KPSC Case No. 2012-00578  
Staff's First Set of Data Requests  
Item No. 33  
Attachment 15  
Page 101 of 253

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 4-18-06

ACCOUNT NUMBER 40594989-06

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item 1/4 Outer Shell - Reheat

2. TECHNIQUE:

Dry Powder     Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:     AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the areas that were blast cleaned. Results showed no cracks.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Dralcy


DATE 4-18-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

**LIQUID PENETRANT INSPECTION REPORT**  
AMERICAN ELECTRIC POWER  
CENTRAL MACHINE SHOP  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303



WORK ORDER NO. 40594989-06 DATE 4-18-06

1. IDENTIFICATION:  
Facility Mitchell  
PC/SN Unit 1  
Item L/H Outer Shell Support Brace Welds - Reheat

2. MATERIAL:  Ferrous  Nonferrous  
3. TECHNIQUE:  Visible Dye  Fluorescent  
 Water Washable

4. MFG/TYPE: Cleaner \_\_\_\_\_ Penetrant \_\_\_\_\_ Developer \_\_\_\_\_

5. INSPECTION PROCEDURE: MI-1-5-2-2

6. INSPECTION SPECIFICATIONS: \_\_\_\_\_

7. TEMPERATURE: Ambient \_\_\_\_\_ Surface \_\_\_\_\_

8. TYPE OF INDICATION:  
 Crack  Linear  Inline Porosity  Rounded  Other \_\_\_\_\_

9. SKETCH/DESCRIPTION:  
A visible dye inspection was performed to the 16 welds of the 8 braces, See attached sheet for results.

10. INSPECTION PERFORMED BY: Doug Stanley 4-18-06  
AEP Level II PT Inspector Signature DATE


11. APPROVED BY: \_\_\_\_\_ DATE \_\_\_\_\_  
NDE Supervisor Signature

Shell  
Support  
Braces

Turb. End


Left  
Side

X = Cracked  
welds



MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 4-18-06

ACCOUNT NUMBER 40594989-06

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item 1/4 Outer Shell - Reheat

2. TECHNIQUE:

Dry Powder     Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:     AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the areas that were blast cleaned. Results showed no cracks.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Dralcy

DATE 4-18-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_



Signature \_\_\_\_\_

11. APPROVED BY: (NDE Supervisor) \_\_\_\_\_

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector) \_\_\_\_\_

*Handwritten signature*

DATE \_\_\_\_\_

DATE \_\_\_\_\_

*6-12-06*

66156A0894

A magnetic particle inspection was performed to 4 welds of 2 90° elbows. Results showed no defects.

9. SKETCH/DESCRIPTION:

- 1. Crack
- 2. Linear Surface
- 3. Linear Subsurface
- 4. Undercut
- 5. Non Relevant

8. TYPE OF INDICATION FOUND:

7. INSPECTION SPECIFICATIONS:

6. INSPECTION PROCEDURE:

*MI-1-S-2-3*

5. AMP TURNS - Parker Probe

4. CURRENT TYPE:

- AC
- DC

2. TECHNIQUE:

- Wet Fluorescent
- Dry Powder
- Non Fluorescent

3. EQUIPMENT:

- Coil
- Prods
- Yoke
- Clamps

1. IDENTIFICATION

Facility: *Mitchell*  
PC/SN: *Unit 1*

ACCOUNT NUMBER *40595680*

CMS NUMBER \_\_\_\_\_

DATE \_\_\_\_\_

*6-12-06*

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

MAGNETIC PARTICLE INSPECTION REPORT



**LIQUID PENETRANT INSPECTION REPORT**  
**AMERICAN ELECTRIC POWER**  
**CENTRAL MACHINE SHOP**  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303



WORK ORDER NO. 40594989-06 DATE 4-21-06

**1. IDENTIFICATION:**

Facility Mitchell  
PC/SN Unit 1  
Item 1/4" Outer Shell Support Strut Welds - Reheat

**2. MATERIAL:**

Ferrous  Nonferrous

**3. TECHNIQUE:**

Visible Dye  Fluorescent  
 Water Washable

**4. MFG/TYPE:** Cleaner \_\_\_\_\_ Penetrant \_\_\_\_\_ Developer \_\_\_\_\_

**5. INSPECTION PROCEDURE:** MI-1-5-2-2

**6. INSPECTION SPECIFICATIONS:** \_\_\_\_\_

**7. TEMPERATURE:** Ambient \_\_\_\_\_ Surface \_\_\_\_\_

**8. TYPE OF INDICATION:**

Crack  Linear  Inline Porosity  Rounded  Other \_\_\_\_\_

**9. SKETCH/DESCRIPTION:**

A visible dye inspection was performed to the 16 welds of the 8 bars.

Gov. End - No Cracked Welds

Gen. End - The left side bar has a 1/4" to 1/2" long crack on each weld. The right side bar has a 1/4" long crack on the top weld.

**10. INSPECTION PERFORMED BY:** Doug Graley  
AEP Level II PT Inspector Signature

4-21-06  
DATE

**11. APPROVED BY:** \_\_\_\_\_  
NDE Supervisor Signature

\_\_\_\_\_  
DATE

# MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

CMS NUMBER \_\_\_\_\_

DATE 5-22-06

ACCOUNT NUMBER 40701930-20

## 1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item #1 L.P. Heater

## 2. TECHNIQUE:

Dry Powder       Wet Fluorescent  
 Non Fluorescent

## 3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:       AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

## 8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION: A magnetic particle inspection was performed to the root pass and cover pass of the front heater shell circumferential weld. A small "C" shaped section was cut from the shell for alignment purposes. The root pass, halfway out and the cover pass welds were inspected when the shell segment was welded back into place. All weld inspections showed no defect indications.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Traley

DATE 5-22-06


11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

# MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 4-21-06

ACCOUNT NUMBER \_\_\_\_\_

## 1. IDENTIFICATION

Facility Mitchell

Item BFP Coupling Assembly

PC/SN Unit 1

## 2. TECHNIQUE:

- Dry Powder
- Wet Fluorescent
- Non Fluorescent

## 3. EQUIPMENT:

- Coil
  - Prods
  - Yoke
  - Clamps
- Central Conductor

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - 4,500

6. INSPECTION PROCEDURE: MT-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

## 8. TYPE OF INDICATION FOUND:

- 1. Crack
- 2. Linear Surface
- 3. Linear Subsurface
- 4. Undercut
- 5. Non Relevant

## 9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the couplings and coupling covers. Results showed no cracks.

## 10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)


Signature Doug Hraley

DATE 4-21-06

## 11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_



**ULTRASONIC TEST REPORT**  
**AMERICAN ELECTRIC POWER**  
**CENTRAL MACHINE SHOP**  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303

WORK ORDER NO. 40594989-06 DATE 4-19-06

**1. IDENTIFICATION:**

Facility Mitchell Item BFP Turbine Rotor Shaft  
PC/SN Unit 1

**2. TECHNIQUE:**

Straight Beam     Angle Beam     Frequency -  1 MH     2.25 MH     5 MH  
 Search Angle -  90°     45°     60°     Single Transducer     Dual Transducer  
Type of Couplant Ultra Gel II Test Unit KrautKramer USK7D

**3. CALIBRATION - REFLECTOR TYPE:**  Drilled Hole     V. Notch     IIW Block     Other \_\_\_\_\_

**4. INSPECTION PROCEDURE:** MI-1-5-2-4

**5. INSPECTION SPECIFICATIONS:** \_\_\_\_\_

**6. TYPE OF INDICATION:**

1. Crack     2. Lamination     3. Corrosion/Erosion     4. Internal Voids     5. Linear

**7. SKETCH/DESCRIPTION:**

A ultrasonic inspection was performed to the shaft from the pump end. Results showed no cracks.

**8. INSPECTION PERFORMED BY:** (AEP Level II UT Inspector)

Signature Doug Snaley DATE 4-19-06

**9. APPROVED BY:** (NDE Supervisor)

Signature \_\_\_\_\_ DATE \_\_\_\_\_

# MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303



CMS NUMBER \_\_\_\_\_

DATE 5-9-06

ACCOUNT NUMBER \_\_\_\_\_

## 1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item South PA Fan

## 2. TECHNIQUE:

Dry Powder       Wet Fluorescent  
 Non Fluorescent

## 3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:       AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

## 8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

## 9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the outboard bearing journal of the fan shaft. Results showed no cracks.

## 10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Bradley

DATE 5-9-06

## 11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

CMS NUMBER \_\_\_\_\_

DATE 5-11-06

ACCOUNT NUMBER 40594989

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Main Oil Pump Section of Discharge Leg Welds

2. TECHNIQUE:

Dry Powder       Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:       AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the weld on each line. Results showed no defects.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Dralcy

DATE 5-11-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_













MAGNETIC PARTICLE INSPECTION REPORT

*A.E.P.*

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

CMS NUMBER \_\_\_\_\_

DATE A-20-06

ACCOUNT NUMBER 40594989-05

1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Blade Rings

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - 5,000

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant.

9. SKETCH/DESCRIPTION:

#1 Blade Ring 1/4 - Gov. End - Both stages have minor foreign object damage on discharge side.  
#2 Blade Ring 1/4 - Gov. End - All 3 stages have minor foreign object damage on discharge side.  
#2 Blade Ring 1/4 - Gen End - All 3 stages have minor foreign object damage on discharge side.  
#2 Blade Ring 1/4 - Gov End - All 3 stages - No defect  
#2 Blade Ring 1/4 - Gen End - All 3 stages - No defect  
#1 Blade Ring 1/4 - Gov. End - Both stages have minor foreign object damage on discharge side.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Smiley

DATE 4-27-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

@  
CMS

CMS NUMBER \_\_\_\_\_

DATE 4-27-06

ACCOUNT NUMBER 40594989-05



1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Blade Rings

2. TECHNIQUE:

Dry Powder  Wet Fluorescent  
 Non Fluorescent

3. EQUIPMENT:

Coil  Prods  Yoke  Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - 5,000

6. INSPECTION PROCEDURE: MI-1-S-2-3

7. INSPECTION SPECIFICATIONS:

8. TYPE OF INDICATION FOUND:

1. Crack  2. Linear Surface  3. Linear Subsurface  4. Undercut  5. Non Relevant

9. SKETCH/DESCRIPTION:

Blade Ring # 1 ~~Gen~~ 1/4 - Gen End - Both stages have minor foreign object damage on discharge side.  
Blade Ring # 1 - 1/4 - Gen. End - Both stages have minor foreign object damage on discharge side.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature Doug Drale

DATE 4-27-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

@ms

**ULTRASONIC TEST REPORT**  
AMERICAN ELECTRIC POWER  
CENTRAL MACHINE SHOP  
3100 MacCorkle Avenue, Building 309  
South Charleston, WV 25303



WORK ORDER NO. 40594989-05 DATE 4-20-06

1. IDENTIFICATION:  
Facility Mitchell Item Blade Ring Studs  
PC/SN Unit 1

2. TECHNIQUE:  
 Straight Beam  Angle Beam  Frequency -  1 MH  2.25 MH  5 MH  
 Search Angle -  90°  45°  60°  Single Transducer  Dual Transducer  
Type of Couplant Exoseno 20 Test Unit KrautKramer USK7D

3. CALIBRATION - REFLECTOR TYPE:  Drilled Hole  V. Notch  IIW Block  Other

4. INSPECTION PROCEDURE: MI-1-5-2-4

5. INSPECTION SPECIFICATIONS:

6. TYPE OF INDICATION:  
 1. Crack  2. Lamination  3. Corrosion/Erosion  4. Internal Voids  5. Linear

7. SKETCH/DESCRIPTION:  
#1 Blade Ring - Gov End - No cracked studs  
#1 Blade Ring - Gen End - No cracked studs. Small stud has bad thread  
#2 Blade Ring - Gov End - No cracked studs  
#2 Blade Ring - Gen End - 1 small stud has broken top threads

8. INSPECTION PERFORMED BY: (AEP Level II UT Inspector)  
Signature Doug Bailey DATE 4-27-06  
9. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_ DATE \_\_\_\_\_

① CMS ✓

MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

CMS NUMBER \_\_\_\_\_

DATE 4-18-06

ACCOUNT NUMBER 40634908-04

1. IDENTIFICATION

Facility MLI

PC/SN \_\_\_\_\_

Item CIRCULATING WATER  
PUMP SHAFTS 11A+B

2. TECHNIQUE:

- Dry Powder
- Wet Fluorescent
- Non Fluorescent

3. EQUIPMENT:

- Coil
- Prods
- Yoke
- Clamps

4. CURRENT TYPE:  AC  DC

5. AMP TURNS - 4000

6. INSPECTION PROCEDURE: MI-1-5-2-3

7. INSPECTION SPECIFICATIONS: MI-1-5-2-3

8. TYPE OF INDICATION FOUND:

- 1. Crack
- 2. Linear Surface
- 3. Linear Subsurface
- 4. Undercut
- 5. Non Relevant

9. SKETCH/DESCRIPTION:

THE EXPOSED AREAS OF THE  
SHAFT WERE MAG I-INSPECTED

NO CRACKS WERE FOUND

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)

Signature J COSB

DATE 4-18-06

11. APPROVED BY: (NDE Supervisor)

Signature \_\_\_\_\_

DATE \_\_\_\_\_

**Ohio Power Co  
Mitchell {WV}  
Unit Number: 1**

**Outage From: 2006/06/15 to 2006/06/21**

**Serial Number: 13A3160-1**

**Frame Type/Building Blocks: 4316VT4**

**Job Number: 0ZCT06027077**

## **Vibration Analysis**

**Report Written By: KC Jones**

**District Service Manager: Carol Andrews**

## ***CUSTOMER FINAL REPORT***

# TABLE OF CONTENTS

## 1. Summary

- 1.1 Scope / Introduction
- 1.2 Unit Information / Name Plate
- 1.3 Equipment Status / Unit Configuration

## 2. Outage Personnel

- 2.1 Outage Personnel / Customer
- 2.2 Outage Personnel / Siemens

## 3. Work Description

## 4. Conclusions and Recommendations

## 5. Miscellaneous Attachments

N/A

## 6. Datasheet Attachments

## 7. Photo Attachments

## 1. Summary

### 1.1 Scope / Introduction

The customer requested a Siemens Balance Engineer to provide vibration analysis and field balancing support during startup of Ohio Power / AEP Mitchell Unit 1 following a scheduled maintenance outage. Siemens Power Generation was not involved with the outage and Siemens personnel were not onsite during the outage. The customer reported the following work was performed during the outage:

- \* Replaced IP rotor with spare rotor
- \* Throttle and Governor valve inspection
- \* Minor Collector work

The Siemens Balance Engineer arrived at site on June 16, 2006.

### 1.2 Unit Information / Name Plate

Turbine S.O. No: 13A3160-1  
Turbine Frame: 4316VT4  
Generator S.O. No: 73P0475-1  
Exciter S.O. No: 418541

### 1.3 Equipment Status / Unit Configuration

-Stream Turbine (fossil) - Westinghouse - BB46A-58-73-73 - S.O. 13A3160-1

-Generator - Westinghouse Hydrogen Cooled - Frame-2-112X245

-In Service Date: April 1970

-Rated-816 MVA

-Speed/Grid-3600RPM/60Hz

Customer's Supervisory:

-Bently Nevada 3300 Series

-B/N 200mv Proximity Probes

The turbine generator is equipped with a Bently Nevada (B/N) 3300 vibration monitoring system reading orthogonal (A/B) relative probes on ST bearings #1 through #11. The vibration probes on bearings #1, #2, #3, #9, #10, and #11 are mounted directly on the bearing casing for true relative vibration. The vibration probes on bearings #4, #5, #6, #7, and #8 are mounted directly on the foundation sole plate for shaft vibration relative to foundation. An ST keyphasor ( ) is located between bearings #2 and #3 at a Top Dead Center (TDC) orientation and is designated as 0°.

Please refer to the Bearing Schematic and Probe Location Schematic in Attachment 6.1.

Control Room Equipment:

Ovation

Vibration monitoring - Absolute (unfiltered) Both X and Y Probes all bearing.

### 1.3 Equipment Status / Unit Configuration {Continued}

Alarm Levels Control Room:

Alarm.....7 mils all bearings  
Trip..... 10 mils all bearings

Siemens Equipment Used:

- TurboTest connected to Bently X Y Outputs
- Channel A = X Probe Left 135° Brg 1-10
- Channel B =Y Probe Right 135° Brg 1-10
- Channel A = X Probe Left 45° Brg 11
- Channel B =Y Probe Right 45° Brg 11
- Data collected is Not True High Spot

Note: The above listing is correct. The Siemens TurboTest data collector was setup according to customer supplied information for pickup location. The information supplied was incorrect, and resulted in the TurboTest data being swapped for the X and Y locations. Left Side data is actually taken at the right side pickup and vice-versa for all Siemens TurboTest data collected. This correction needs to be taken into account when analyzing the Siemens TurboTest data.

## 2. Outage Personnel

### 2.1 Outage Personnel / Customer

<u>Name</u>	<u>Job Description</u>
Jack Huggins	Electrical Process Coordinator

### 2.2 Outage Personnel / Siemens

<u>Name</u>	<u>Job Description</u>
KC Jones	Field Service Engineer

## 3. Work Description

Vibration analysis entailed the following activities:

Setup TurboBalancer for data collection during startup and load ascension. Reviewed data and made appropriate balance recommendations

## 4. Conclusions and Recommendations

The customer's acceptance criteria for rotor vibration is higher than the Siemens recommended levels; therefore, no balance moves were made while the Siemens Vibration Engineer was on site.

The following weight moves are suggested to reach the Siemens vibration acceptance criteria of 3.0 mils 1X filtered. The customer has indexed the shaft at the turning gear area in line with the Bently interruption notch. Angles increase with rotation as viewed from governor end.

HP - Currently the unit has approximately 2.2 mils of static unbalance and 3.0 mils of dynamic unbalance. The following

#### 4. Conclusions and Recommendations {Continued}

weight move is recommended to reduce the dynamic forces.

HP Move: Add 5.0 oz Plane 1 at 70°

IP - The rotor currently has a large amount of static unbalance (4.3) mils and a very small amount of dynamic unbalance. To reach Siemens recommended vibration levels, several weight moves may be required. The initial move would be a center plane balance move with a high likelihood of additional move required in the end planes. If AEP wishes to pursue balancing of the IP rotor, it is recommended that several days be set aside to complete this task. Due to the high probability that several moves will be required, no single move is recommended at this time.

LPA - The rotor has a considerable amount of static unbalance (2.5 to 3.5 mils) and a large amount of dynamic (6.5 mils). The following weight move is recommended to reduce the dynamic forces.

LP A Move: Add 1 Standard 16.0 oz weight Plane 5 at 80°

LPB - This rotor also has a significant amount of static unbalance (2.0 - 2.5 mils) and a small amount of dynamic unbalance. Vibration levels on this rotor are only slightly above the Siemens 3.0 mils 1X criteria. At this time, Siemens feels the benefit of reducing vibration amplitudes on LPB is minimal; therefore, no balance move is recommended. If levels increase, AEP should contact Siemens for assistance in calculating a balance move.

Generator - All vibration amplitudes at the generator bearings are currently below the Siemens recommended amplitudes of 3.0 Mil 1X filtered and require no balancing. Note: The Bently probes are wired incorrectly at both the #9 and #10 bearings - the X and Y are reversed.

Collector - Vibration amplitudes at this bearing have been elevated for some time. Currently vibration level is 5.5 mils. The customer has been controlling this vibration by maintaining a mismatched temperature setting on the hydrogen and air side seal oil. Currently these temperatures are running 116° F hydrogen side and 144° F air side. Siemens recommends operating with the hydrogen side and air side matched at 110° F. The Siemens Balance Engineer requested that these temperatures be matched and the customer elected to match them at 130° F. Vibration at the collector bearing increased to 7.8 mils, so the customer elected to return the temperatures to the mismatched condition in order to reduce the vibration. Note that operating in this condition may thermally distort the generator hydrogen seals. The Siemens Balance Engineer recommended that a balance move be attempted to reduce the vibration amplitude at the collector bearing, however, he did not feel comfortable calculating a move at this time based only on the limited data obtained while at the site. Therefore, Siemens recommends that additional vibration data be captured while the unit is operating with the proper seal oil temperatures. Once this data has been reviewed, Siemens can calculate a balance move for the collector bearing. The customer should be aware that during the balancing effort the seal oil temperatures will have to be maintained at the Siemens recommended setting.


#### 5. Miscellaneous Attachments

N/A


#### 6. Datasheet Attachments

- 6.1 Mitchell1-2006
- 6.2 Mitchell Spectral

### Bearing Schematic



### Probe Location Schematic



### ST Probe Orientation from Governor End

**TurboTest Setup data:**

Machine or Plant Name	Mitchell	Enter a name to describe the machine
Machine Number within Plant	1	Enter an ID to identify the machine
Normal Running Speed	3600	RPM (Numeric value)
Minimum Acquisition Speed	200	RPM (Numeric value)
Maximum Speed for Plots	4000	RPM (Numeric value)
Const Speed Storage Interval	60	Seconds (Numeric value)
Speed Increment for readings	10	RPM (Numeric value)
Store Vibration Spectra ?	N	N= NO any other = YES
Low Speed Acquisition Revs	2	(Numeric value normally 2)
Switch over Speed	600	RPM (Numeric value normally 600)
Normal Acquisition Revs	8	(Numeric value normally 8)
Unit System	Imperial	System of Units (Metric or Imperial)

Set up									
Ch	Tag	Signal	XD	mV/EU	Gap V	Alarm	Volts	HW	Detect / Display
1	H1FRL	D->D	X BRG1	200	-9.941	5	10	0.5	RMS / P-P
2	H1FRR	D->D	Y BRG1	200	-10.605	5	10	0.5	RMS / P-P
3	H1RRL	D->D	X BRG2	200	-10.225	5	10	0.5	RMS / P-P
4	H1RRR	D->D	Y BRG2	200	-10.254	5	10	0.5	RMS / P-P
5	I1FRL	D->D	X BRG3	200	-11.074	5	10	0.5	RMS / P-P
6	I1FRR	D->D	Y BRG3	200	-10.508	5	10	0.5	RMS / P-P
7	I1RRL	D->D	X BRG4	200	-10.059	5	10	0.5	RMS / P-P
8	I1RRR	D->D	Y BRG4	200	-10.117	5	10	0.5	RMS / P-P
9	L1FRL	D->D	X BRG5	200	-10.01	5	10	0.5	RMS / P-P
10	L1RRL	D->D	X BRG6	200	-6.191	5	10	0.5	RMS / P-P
11	L2FRL	D->D	X BRG7	200	-9.033	5	10	0.5	RMS / P-P
12	L2RRL	D->D	X BRG8	200	-6.719	5	10	0.5	RMS / P-P
13	G1TRL	D->D	X BRG9	200	-8.262	5	10	0.5	RMS / P-P
14	G1XRL	D->D	X BRG1	200	-10.498	5	10	0.5	RMS / P-P
15	X1RRL	D->D	X BRG1	200	-10.156	5	10	0.5	RMS / P-P
16	X1RRR	D->D	Y BRG1	200	-10.608	5	10	0.5	RMS / P-P

**“As Found” / “As Left” TurboTest data 800MW**

CH	TAG	DC	OK	TOTAL	FILTER 1X		FILTER 2X		FILTER 0.125X	
					AMP	ANG	AMP	ANG	AMP	UNITS
1	H1FRL	-10.598		1.71	1.63	197	0.14	195	0.15	Mils P-P
2	H1FRR	-11.904		1.24	1.20	281	0.12	163	0.03	Mils P-P
3	H1RRL	-10.532		2.77	2.71	268	0.10	128	0.16	Mils P-P
4	H1RRR	-10.518		3.17	3.15	346	0.12	81	0.11	Mils P-P
5	I1FRL	-12.165		2.87	2.78	211	0.13	308	0.05	Mils P-P
6	I1FRR	-12.133		3.16	3.08	312	0.36	108	0.11	Mils P-P
7	I1RRL	-11.269		4.13	4.09	200	0.25	319	0.07	Mils P-P
8	I1RRR	-10.670		4.28	4.26	286	0.23	75	0.05	Mils P-P
9	L1FRL	-10.989		4.28	4.24	149	0.31	251	0.01	Mils P-P
10	L1RRL	-7.001		4.39	4.34	66	0.46	344	0.05	Mils P-P
11	L2FRL	-9.290		3.27	3.24	60	0.22	62	0.01	Mils P-P
12	L2RRL	-7.899		2.97	2.91	137	0.56	150	0.01	Mils P-P
13	G1TRL	-11.260		0.88	0.28	141	0.32	293	0.02	Mils P-P
14	G1XRL	-12.601		1.07	0.17	348	0.98	356	0.01	Mils P-P
15	X1RRL	-8.030		5.06	5.05	318	0.33	216	0.03	Mils P-P
16	X1RRR	-8.240		4.75	4.74	265	0.08	273	0.04	Mils P-P

Location	Brq 1	Brq 2	Brq 3	Brq 4	Brq 5	Brq 6	Brq 7	Brq 8	Brq 9	Brq 10	Brq 11
<b>TurboTest</b>											
X	1.5/199	2.8/265	2.7/211	4.2/285	4.2/147	4.5/66	3.5/58	3.0/136	0.2/171	0.1/18	5.2/319
Y	1.1/280	3.2/344	4.0/197	4.2/148	4.9/256	3.4/155	2.1/147	1.4/177	0.5/347	0.1/17	4.7/265
<b>Runout Comp TurboTest</b>											
X	0.4/170	3.4/267	3.5/296	3.4/280	1.4/95	2.2/75	4.7/60	3.9/194	NA	NA	NA
Y	2.1/288	4.1/335	4.3/206	5.0/155	NA						
<b>PIE Unfiltered</b>											
LS	1.5/283	3.6/345	3.0/311	4.7/285	5.0/260	3.6/154	2.5/148	1.8/174	1.6/353	1.6/257	4.9/266
RS	1.8/202	3.2/268	3.6/213	4.5/200	4.7/149	4.6/67	3.6/61	3.3/137	1.4/134	1.4/358	5.4/318

Note: NA = No data available or runout minimal



**"As Left" Bearing Metal and Oil Temperatures 800MW:**



location	Metal F.
Brq 1	177.9°F
Brq 2	187.1°F
Brq 3	150.6°F
Brq 4	149.5°F
Brq 5	191.5°F
Brq 6	196.5°F
Brq 7	198.3°F
Brq 8	189.1°F
Brq 9	163.7°F
Brq 10	165.2°F
Brq 11	146.3°F
Cooler out	124.4°F
Cooler In	162°F
Air Side SO	144°F
Hydro Side SO	116°F



**TurboTest log:**



6:Jun:2006 - 09:01 Create new job.  
 16:Jun:2006 - 09:02 Create data volume 1 - BIG MITCHELL UNIT 1 AEP KC JONES 6/16/2006 IP SPARE ROTOR INSTALLED  
 16:Jun:2006 - 23:59 Vol1.vec rdg 34----> first steam roll  
 17:Jun:2006 - 09:04 Vol1.vec rdg 536----> unit trip generator problems  
 17:Jun:2006 - 15:45 Vol1.vec rdg 1210----> on line  
 17:Jun:2006 - 15:51 Vol1.vec rdg 1211----> 40MW  
 17:Jun:2006 - 16:15 Vol1.vec rdg 1217----> 19MW  
 17:Jun:2006 - 16:56 Vol1.vec rdg 1225----> 38MW  
 18:Jun:2006 - 06:57 Vol1.vec rdg 1393----> 330MW  
 18:Jun:2006 - 09:09 Vol1.vec rdg 1419----> 434MW

18:Jun:2006 - 09:50 Vol1.vec rdg 1429---> 417MW  
18:Jun:2006 - 11:49 Vol1.vec rdg 1452---> 458MW  
18:Jun:2006 - 12:17 Vol1.vec rdg 1458---> 476MW  
18:Jun:2006 - 13:18 Vol1.vec rdg 1470---> 480MW  
18:Jun:2006 - 13:43 Vol1.vec rdg 1475---> 360MW  
19:Jun:2006 - 07:05 Vol1.vec rdg 1684---> 688MW  
19:Jun:2006 - 07:10 Vol1.vec rdg 1685---> 711MW  
19:Jun:2006 - 07:15 Vol1.vec rdg 1686---> 740MW  
19:Jun:2006 - 09:40 Vol1.vec rdg 1799---> 790MW  
19:Jun:2006 - 10:56 Vol1.vec rdg 1873---> 800MW



































7. Photo Attachments

N/A

THE AMERICAN ELECTRIC POWER SERVICE CORPORATION  
 TRAVELER

PLANT & UNIT: (MLU106-017) Mitchell Plant Unit -1  
 INSPECTOR PHONE APPROVAL: \_\_\_\_\_  
 JOB NO.: 40634913-06  
 APPLICABLE CODE: B31.1  
 DATE: 5/9/2006  
 Operating TEMP & PRESSURE (B31.1): Oil Pipe: 140 °F. @ 380 psi,  
 Guard Pipe: ambient and 6" vacuum

REPAIR DESCRIPTION & LOCATION: **Turbine Main Oil Pump Suction and Discharge Piping – reweld joint approximately 14 feet below turbine front standard pedestal floor.**

AREA	*HOLD POINT	QCC AUDIT	*INSPECTOR RELEASE	MAINTENANCE RELEASE
1. DESIGN		Wayne Miller 5-24-06		R. Pederson RP 5/9/06
2. MATERIAL		SWP 5-24-06		R. Pederson RP 5/9/06
A. ORIGINAL				
B. REPLACEMENT		N/A		N/A
3. QUALIFICATIONS				R. Pederson RP 5/9/06
A. WELD PROCEDURE		SWP 5-24-06		
B. WELDER		SWP 5-24-06		RP 5/24/06
C. NDE PERSONNEL		SWP 5-24-06		RP 5/29/06
D. HEAT TREATMENT		N/A		N/A
4. REPAIR				
A. END PREPARATION				RP 5/24/06
B. FITUP/ALIGNMENT				RP 5/24/06
C. PREHEAT		SWP 5-24-06		RP 5/24/06
D. WELD (VISUAL)				RP 5/24/06
NDE		SWP N/A 5-24-06		N/A
F. PWHT		SWP N/A 5-24-06		N/A
5. PRESSURE TEST				
Pressure:				
Medium:				None

6. DOCUMENTS			
1. Drawings, Specs., etc.:	Metal analysis provided by CMS		
Weld Size (Fillet/Seal):			
2A. Size, Spec. and Grade:	Oil Pipe: 5" & 8" Sch 40 (3/8" wall) A106 Gr B, Guard Pipe: 14" Sch 40 A106 Gr B, – (4 cut access ports to 5" & 8" pipes inside)		
2B. Size, Spec, Grade, & P. O. No.:			
3A. WPS No.:	1.2a		
3B. Welder's Name and Stamp:	See Attached Sheet J. Reitter		
3C. NDE Personnel Name, Method & Exp. Date:	VT by: D. Galey (Exp. 2/1/07), MT by: D. Galey (Exp 2/1/07)		
3D. Temp Range:	N/A	Heat Rate (Max):	N/A
Cool Rate (Max):	N/A	Hold Time (Min):	N/A
4C. Min Preheat Temp:	50° F.		
4D. Electrode/Rods:	E 7018		

\* PLANT MAINTENANCE SUPERVISION: NOTIFY QCC AND STOP FABRICATION AT ALL HOLD POINTS.  
 \* INDICATE THE REQUIRED HOLD POINTS BY INITIALS. \* INDICATE RELEASE OF HOLD POINTS BY INITIALS.  
 \* ITE: INDIVIDUALS WILL INITIAL AND DATE TO SIGNIFY COMPLETION.

PLANT QC ACCEPTANCE: \_\_\_\_\_  
 INSPECTOR ACCEPTANCE: \_\_\_\_\_  
 (When reviewed)

6 welds  
 6 MT  
 0 Reg

**MATERIAL** Carbon Steel, P-1 & S-1

**PROCESS** SMAW

**FILLER METAL**  
E7018 E7018-A1  
E7015 E7015-A1  
E7016 E7016-A1

**GAS**  
**SHIELD** N/A  
**PURGE** N/A

**JOINT DESIGN** JD-2, JD-3, JD-4, JD-5 (girth only for Sec. I) & JD-10 (welding neck w/backing)

**POSITION** All

**PREHEAT**  
50° F min.  
175° F min. for mat'l with both C over 0.30% and T over 1" (VIII)  
200° F min. for mat'l with T over 1-1/4" (VIII)

**INTERPASS TEMP.** 500° F max. recommended

**POST HEAT** Not required

**WELD DATA**

Pass	Dia.	E70XX & A1
1 & over	3/32"	65-110 amps
1 & over	1/8"	100-165 amps
3 & over	5/32"	140-220 amps

**TECHNIQUE**  
Stringer bead\*  
Vertical upward progression

**QUALIFICATION (PQR)** (107) & (358) Base metal: 1/16 to 3/4" (I & B31.1), 1/16 to 1-1/2" (VIII)  
Weld max: 3/4" (I & B31.1), 1-1/2" (VIII)

**MISCELLANEOUS**  
B31.1, I & VIII also approved for Ohio Piping.  
\* Refer to General Welding Instruction No. 1 and also for general information.

03/02/2000

**FOSSIL**

**WELDING PROCEDURE  
SPECIFICATION**

NO. 1.2a

SMAW B31.1, I & VIII  
Carbon Steel, P-1  
E7018 Backed Groove

PREPARED BY JM Andres DATE 4/20/01

QC APPROVAL DD E. [Signature] DATE 4-20-01



**MATERIAL** Carbon Steel, P-1 & S-1

**PROCESS** SMAW

**FILLER METAL**  
E7018 E7018-A1  
E7015 E7015-A1  
E7016 E7016-A1

**GAS**  
**SHIELD** N/A  
**PURGE** N/A

**JOINT DESIGN** JD-2, JD-3, JD-4, JD-5 (girth only for Sec. I) & JD-10 (welding neck w/backing)

**POSITION** All

**PREHEAT**  
50° F min.  
175° F min. for mat'l with both C over 0.30% and T over 1" (VIII)  
200° F min. for mat'l with T over 1-1/4" (VIII)

**INTERPASS TEMP.** 500° F max. recommended

**POST HEAT** Not required

**WELD DATA**

Pass	Dia.	E70XX & A1
1 & over	3/32"	65-110 amps
1 & over	1/8"	100-165 amps
3 & over	5/32"	140-220 amps

**TECHNIQUE**  
Stringer bead\*  
Vertical upward progression

**QUALIFICATION (PQR)** (107) & (358) Base metal: 1/16 to 3/4" (I & B31.1), 1/16 to 1-1/2" (VIII)  
Weld max: 3/4" (I & B31.1), 1-1/2" (VIII)

**MISCELLANEOUS**  
B31.1, I & VIII also approved for Ohio Piping.  
\* Refer to General Welding Instruction No. 1 and also for general information.

03/02/2000

**FOSSIL**


**WELDING PROCEDURE  
SPECIFICATION**

NO. 1.2a

SMAW B31.1, I & VIII  
Carbon Steel, P-1  
E7018 Backed Groove

PREPARED BY JM Andres DATE 4/20/01

QC APPROVAL DD E. [Signature] DATE 4-20-01





### MAGNETIC PARTICLE INSPECTION REPORT

AMERICAN ELECTRIC POWER  
Central Machine Shop  
3100 MacCorkle Avenue, Bldg. 309  
South Charleston, West Virginia 25303

CMS NUMBER \_\_\_\_\_

DATE 5-11-06

ACCOUNT NUMBER \_\_\_\_\_

#### 1. IDENTIFICATION

Facility Mitchell  
PC/SN Unit 1

Item Main Oil Pump Section &  
Discharge Leg Welds

#### 2. TECHNIQUE:

Dry Powder       Wet Fluorescent  
 Non Fluorescent

#### 3. EQUIPMENT:

Coil     Prods     Yoke     Clamps

4. CURRENT TYPE:       AC     DC

5. AMP TURNS - Parker Probe

6. INSPECTION PROCEDURE: MI - 1 - 5 - 2 - 3

7. INSPECTION SPECIFICATIONS: \_\_\_\_\_

#### 8. TYPE OF INDICATION FOUND:

1. Crack     2. Linear Surface     3. Linear Subsurface     4. Undercut     5. Non Relevant

#### 9. SKETCH/DESCRIPTION:

A magnetic particle inspection was performed to the weld on each line. Results showed no defects.

10. INSPECTION PERFORMED BY: (AEP Level II MT Inspector)


Signature Doug Dralcy


DATE 5-11-06


APPROVED BY: (NDE Supervisor)


Signature \_\_\_\_\_

DATE \_\_\_\_\_











**A Century of Firsts**

---

# Mitchell Station Unit #1

## American Electric Power Company

## Ohio Power Company



# Steam Cycle Shutdown

## Westinghouse T-G Set

800 MWs - Tandem Compound - 3600 rpm

VHP-HP Turbine	Serial Number	13A3160-1
IP Turbine	Serial Number	13A3161-1
LP Turbine #1	Serial Number	13A3162-1
LP Turbine #2	Serial Number	13A3163-1
Turbine Instruction Book		1250-C679
HP Generator	Serial Number	1-S-87P0755
HP Exciter	Serial Number	1-S-73P0476
Generator Instruction Book		90P0944
Boiler Feed Pump Drive Turbine		15-A-2961-1
BFP/DT Instruction Manual		1150-C129
July Shutdown		7-20-2006 to 7-24-2006

## **Table of Contents**

### **Executive Summary**

**Page 3**

### **Resources**

**Page 4**

Outage AEP Key Personnel

Outage Sub-contractors

WO Numbers

### **Work Performed**

Hydrogen Seal Oil Skid

Page 5

Reheat Stop Valve

Page 6

Stop Valve Strainer Differential

Page 6

Stator Water Cooler Leak

Page 6

### **Attachments**

Attachment 1	SOS Floats As Found	Page 7
Attachment 2	SOS Floats As Left	Page 8
Attachment 3	SOS Regulating Tank Level Indicator	Page 9
Attachment 4	Seal Oil Diagram Original	Page 10
Attachment 5	Seal Oil Diagram Red Lined	Page 11
Attachment 6	Seal Oil Diagram As Built	Page 12
Attachment 7	Removed Exciter Valve 326	Page 13
Attachment 8	Installed Bland for Valve 326	Page 14
Attachment 9	Stator Water I/O Tube Plug	Page 15
Attachment 10	Stator Water Reverse Tube Plug	Page 16
Attachment 11	SW Reversing Cover Crack	Page 17
Attachment 12	SW Reversing Cover Crack	Page 18
Attachment 13	SW Reversing Cover Dimensions	Page 19

## **Executive Summary**

This scope is work performed during a four-day system cycle shutdown to repair boiler tube leakage. The work performed by this RSO Crew was; 1.) The open, inspect and repair of the electric generator hydrogen seal oil skid regulator tank level control, 2.) The repair of a steam leak at the first reheat stop valve bonnet, 3.) Review and possible correction of poor performance of a steam chest strainer differential gage point, and 4.) Correcting water leakage across a Stator Water Coolant Skid heat exchanger tube.

## **Recommendations**

1. Install new circulating water isolation valves for the stator water coolant skid.
2. Replace the upper cooler reversing head of the stator water coolant skid.
3. Replace root valves for main turbine steam chest sensing lines.
4. Had Auto – Cad correct OEM Tech Manual Seal Oil Diagram to reflect the abandonment of the hydrogen cooled exciter. All in-use Tech Manuals should be updated accordingly.

## Resources

### Internal

Steve Dolan	KAMMER STATION	Electric Process Owner
Jack Huggins	KAMMER STATION	Electrical Process Supervisor
Ralph Pederson	GET TSV TC	Lead Turbine Coordinator
Doug Fox	GET TSV RSO	Supervisor – Turbine Crew
Jeff Brothers	GET TSV RSO	Supervisor – Turbine Crew
Robin Margolis	GET TSV CMS	Non Destructive Examination
Robert Lake	GET TSV RSO	Gavin Tool Facility

### External

NONE

### WO Numbers

40794550 01	Hydrogen SOS Repairs
40794556 01	LS Reheat Stop Valve Gasket – 1 <sup>st</sup>
40794562 01	Strainer Tap Diff Loop & Valve
40794567 01	Stator Water Cooler Leak

## **Work Performed**

### **Hydrogen Seal Oil Skid**

The hydrogen seal oil skid regulating tank was opened to determine the cause for back flooding the electric generator collector end defoaming tank into the stator cavity. Operations had been manually draining lubricating seal oil from collector end liquid detector. Personnel have been removing this material on an hourly and sometimes more frequent schedule. The leakage is worse on power cycle start up and shut down.

The east end regulator tank cover was removed to inspect the tank interior and the inlet and drain float valve mechanisms. The interior of the tank was found gritty and with evidence of water in the past. The condition of the float valve mechanisms was good with no dropped linkage pins. The mechanisms were manually manipulated to determine smooth function of the mechanisms. The mechanisms were found to swing easily and with no sign of drag. The valves and their mechanisms were removed from the tank for closer inspection. The internals of the valves and mechanisms were in excellent condition. The valves and their mechanisms were restored to the regulating tank. The stem lengths of the valves were changed to correct their function interact. The drain valve stem length was shortened 0.180" while the inlet valve stem length was expanded by 0.100". The change of stem length gives a dead band of approximately one inch from the time the inlet valve stops porting oil until the time when the drain valve begins dropping tank level. The dead band was set up to be at approximately tank horizontal centerline. The As Found float stem lengths had the drain valve open before the inlet valve was closed.

The mechanical magnetic level indicator was inspected to determine cause to failure to properly show level. The action of level indicator during inspection was good. The cause of poor indication service appeared to be the swing arc of the inlet valve float arm could strike the indicator. This was reviewed and the concern for impeded operation of the two devices was corrected by establishing a 3/16" clearance between the devices. Westinghouse Tech Manual diagram intends this removed regulating tank cover to be at the west end.

The oil connection line between the regulating tank and the receiver tank was blown with air to determine no obstruction existed. The same process was applied to the gas connection line at the top of these tanks. No obstruction was found in either line. The line from the float drain valve to the airside pump was inspected for obstruction and none found. An attempt was made to push a probe camera up the drain line from the defoaming tanks to the receiver tank. The probe could be pushed approximately 28 feet before the drag of the numerous elbows stopped progress advancement. Nothing unusually was noted in the pipe scoped.

### **Reheat Stop Valve**

The Main Turbine left side first reheat stop valve bonnet cover was removed to install a new flexitallic gasket. The sealing faces were cleaned and stoned. No damage was found on these surfaces. A new gasket was seated and the bonnet fasteners torqued to a preload of 45,000 PSI.


### **Stop Valve Strainer Differential Sensing Line**

The plant was having difficulty obtaining main stop valve strainer differential pressures from the right side steam chest. RSO applied 80-PSI air pressure to this sensing line and impact shock to the steam chest root valve. The sensing line has an approximate line run of 50 feet. The line finally would past air from the wall-mounted indicator to the steam chest root valve after a number of applications.


### **Stator Water Cooler Leak**

The plant reported the Stator Water Coolant Skid to be using approximately 30 to 40 gallons of demineralized water a shift for makeup. It was felt that there was a tube leak to the circulating water side. The skid coolers were isolated from the stator and pressure tested using circulating water. The through wall tube leak was found to be in the top cooler. The circulating water isolation valves at the cooler were found to leak through and thus the isolation was moved to the cooling tower line. The inlet-outlet and reversing heads were removed and the tube sheets soaped to determine damaged tube while the cooler shell side was pressurized with 5-PSI air. A single tube was found to be the source of leakage and brass tube plugs seated. The cooler heads were reassembled using new gaskets. An existing linear indication was found on the reversing head. The indication is water tight and has been coated with an epoxy sometime in the past. The cooler head assembly interfaces were pressurized with circulating water to review for leakage to human environment. None were observed. The reversing head was installed as is as the indication had been epoxy coated in the past and was water tight. See Photos.

Attachment 1 - SOS Regulating Tank at Disassembly –Note fine debris and rust




Attachment 2 - SOS Regulating Tank Floats as Restored



Attachment 3 - SOS Regulating Tank Level Indication Float




Attachment 4 - Old Tech Manual Seal Oil Diagram



SEAL OIL DIAGRAM

Dwg. 687770-5 Seal Oil Diagram FIG. 1


Attachment 5 - Seal Oil Diagram Red Line



Dwg. 687770-5 Seal Oil Diagram FIG. 1

SEAL OIL DIAGRAM


Attachment 6 - Seal Oil Diagram Cleaned Up As Built




Attachment 7 - Removed Exciter H2 Drain Valve 326




Attachment 8 - Blank Installment for Valve 326



Attachment 9 - Stator Water Inlet-Outlet End Tube Plug



Attachment 10 - Stator Water Reversing End Tube Plug



Attachment 11 - Stator Water Reversing Cover Crack




Attachment 12 - Stator Water Reversing Cover Crack



### Attachment 13 - Stator Water Reversing Cover Dimensions

#### Mitchell Unit #1 Stator Cooling Water Upper Cooler Reversing Cover Dimensions



**Site Turbine Tools**  
(Pages 25)

**Tab 3**

**Manager of Specialty Tools Documentation of Tool Form**

Manager of Specialty Tools: Please note Tool ID and then sign and date the appropriate box(es). If other, please clearly specify the action using as many rows as necessary to explain. If an action is not applicable to a specific tool please mark the appropriate box "NA".

Tool ID #	Specialty Tool Identification Form Completed	Specialty Tool Critical Requirements Checklist Completed	Engineering Review Submittal	Engineering Review Complete	Received Proper Documentation from Reviewer	Certification (Approved for Use)	Permanent ID Label Application	Testing (Be Specific)	Re-certification	Other (Please Specify)
ML-U1 - TV-001	X	X								
ML-U1 - TV-002	X	X								
ML-U1 - <del>TV-003</del>	X	X								
ML-U1 - TV-004	X	X								
ML-U1 - TV-005										
ML-U1 - GV-001	X	X								
ML-U1 - GV-002	X	X								

This document contains information confidential and proprietary to AEPSC. It shall not be reproduced in whole or in part or released to any third party without the expressed written consent of AEPSC.

**Specialty Tool Identification Form**

General Information		
Tool Name: Throttle Plug Lock	Tool Originator:	Tool ID #: ML-U1-TV-001
Date of ID Issue:	Manager Name:	Tool Location: Mitchell Station Unit #
Tool Function and Description: Secure Unit # / throttle plug for disassembly of internal steam pilot valve		

Re-certification		
Is re-certification required?	Y	(N)
If yes, please give a specific amount of time or usage.		
Other stipulations?		

Verification of ID Usage		
Location on Tool:	Manager Initials:	Date:
Specific Label:		

**Specialty Tool Critical Requirements Checklist**

Tool ID #: ML-U1-TV-001	Completed By: Ralph Pederson	Date Completed: 4/6/06
Tool Name: Throttle plug Lock	Manager Name:	Date Reviewed:
Brief Description of Tool: Secure Unit #1 throttle plug for disassembly of internal steam pilot valve.		

<i>Unfit For Use Criteria</i>		Yes	No
1	For an existing tool, are there any visual material deformations such as: cracks, crazing, nicks, excessive rust, significant wear, mushrooming, etc.		X
Is this tool <i>unfit</i> for use?  (Any checkmarks under the Yes column establish this tool as <i>Unfit for Use</i> and this tool shall no longer be used. A tool determined unfit for use shall be properly labeled and a new tool shall be fabricated in accordance with this document.)		Unfit for Use	Fit for Use  X

<i>Testing Criteria</i>		Yes	No
1	Is this tool used for lifting, as a lifting accessory, or for specialized rigging?		X
Must this tool complete required testing?  (Any checkmarks under the Yes column require this tool complete required testing before further use. A tool required to complete testing must be properly labeled until approved for use by Specialty Tool Manager. A list of reference regulations for required testing may be found in the attachment titled Specialty Equipment Industry and Safety Requirements. Tools in this category are now regulated by the requirements of the applicable document.)		Testing Required	No Testing Required  X


\*\* Checklist Continued on Next Page\*\*

**Specialty Tool Critical Requirements Checklist**

<i>Critical Criteria</i>		Yes	No
1	Does this tool operate under machine power?		X
2	Does this tool contain significant stored energy (springs, trigger mechanism, etc)?		X
3	If the tool were to fail, would its failure result in operator injury?		X
4	Does this tool operate in extreme environments (temperature, pressure, potentially corrosive, etc.)?		X
5	Does this tool operate in a repetitive manner at high levels of force (conditions indicative of fatigue)?		X
6	Regardless of checklist results, does good judgment necessitate an engineering review of this tool?		X
Does this tool require Engineering Review?		Critical	Non-critical
(Any checkmarks under the Yes column require the tool to go through an engineering review. A tool required to complete an engineering review must be properly labeled until approved for use by Specialty Tool Manager.)			X

Signature of Tool Originator	<i>Ralph Pederson</i>	Date	<i>4/6/06</i>
Signature of Specialty Tool Manager		Date	

ML-U1-TV-001 - Throttle Plug Lock



**Specialty Tool Identification Form**

General Information		
Tool Name: Throttle Plug Spanner	Tool Originator:	Tool ID #: ML-UL-TV-002
Date of ID Issue:	Manager Name:	Tool Location: Mitchell Station Unit #1
Tool Function and Description: Spanner wrench to turn throttle plug internal pilot valve bashing nut		

Re-certification		
Is re-certification required?	Y	(N)
If yes, please give a specific amount of time or usage.		
Other stipulations?		

Verification of ID Usage		
Location on Tool:	Manager Initials:	Date:
Specific Label:		

**Specialty Tool Critical Requirements Checklist**

Tool ID #: ML-41-TV-002	Completed By: Ralph Pederson	Date Completed: 1/6/06
Tool Name: throttle plug Spanner	Manager Name:	Date Reviewed:
Brief Description of Tool: Spanner wrench to turn throttle plug internal pilot valve bushing nut		

Unfit For Use Criteria		Yes	No
1	For an existing tool, are there any visual material deformations such as: cracks, crazing, nicks, excessive rust, significant wear, mushrooming, etc.		X
Is this tool <i>unfit</i> for use?  (Any checkmarks under the <i>Yes</i> column establish this tool as <i>Unfit for Use</i> and this tool shall no longer be used. A tool determined unfit for use shall be properly labeled and a new tool shall fabricated in accordance with this document.)		Unfit for Use	Fit for Use  X

Testing Criteria		Yes	No
1	Is this tool used for lifting, as a lifting accessory, or for specialized rigging?		X
Must this tool complete required testing?  (Any checkmarks under the <i>Yes</i> column require this tool complete required testing before further use. A tool required to complete testing must be properly labeled until approved for use by Specialty Tool Manager. A list of reference regulations for required testing may be found in the attachment titled Specialty Equipment Industry and Safety Requirements. Tools in this category are now regulated by the requirements of the applicable document.)		Testing Required	No Testing Required  X


\*\* Checklist Continued on Next Page\*\*

**Specialty Tool Critical Requirements Checklist**

<i>Critical Criteria</i>		Yes	No
1	Does this tool operate under machine power?		
2	Does this tool contain significant stored energy (springs, trigger mechanism, etc)?		X
3	If the tool were to fail, would its failure result in operator injury?		X
4	Does this tool operate in extreme environments (temperature, pressure, potentially corrosive, etc.)?		X
5	Does this tool operate in a repetitive manner at high levels of force (conditions indicative of fatigue)?		X
6	Regardless of checklist results, does good judgment necessitate an engineering review of this tool?		X
Does this tool require Engineering Review?		Critical	Non-critical
(Any checkmarks under the Yes column require the tool to go through an engineering review. A tool required to complete an engineering review must be properly labeled until approved for use by Specialty Tool Manager.)			X

Signature of Tool Originator	Ralph Pederson	Date	4/6/06
Signature of Specialty Tool Manager		Date	

ML-U1-TV-002 – Throttle Plug Spanner



**Specialty Tool Identification Form**

General Information		
Tool Name: Throttle Pilot Spanner	Tool Originator:	Tool ID #: ML-K1-TV-003
Date of ID Issue:	Manager Name:	Tool Location: Mitchell Station Unit #1
Tool Function and Description: Throttle Valve pilot nut spanner wrench		

Re-certification		
Is re-certification required?	Y	(N)
If yes, please give a specific amount of time or usage.		
Other stipulations?		

Verification of ID Usage		
Location on Tool:	Manager Initials:	Date:
Specific Label:		

**Specialty Tool Critical Requirements Checklist**

Tool ID #: ML-KI-TV-003	Completed By: Ralph Pederson	Date Completed: 4/6/06
Tool Name: Throttle Pilot Spanner	Manager Name:	Date Reviewed:
Brief Description of Tool:		

<i>Unfit For Use Criteria</i>		Yes	No
1	For an existing tool, are there any visual material deformations such as: cracks, crazing, nicks, excessive rust, significant wear, mushrooming, etc.		X
Is this tool <i>unfit</i> for use?  (Any checkmarks under the Yes column establish this tool as <i>Unfit for Use</i> and this tool shall no longer be used. A tool determined unfit for use shall be properly labeled and a new tool shall be fabricated in accordance with this document.)		Unfit for Use	Fit for Use  X

<i>Testing Criteria</i>		Yes	No
1	Is this tool used for lifting, as a lifting accessory, or for specialized rigging?		X
Must this tool complete required testing?  (Any checkmarks under the Yes column require this tool complete required testing before further use. A tool required to complete testing must be properly labeled until approved for use by Specialty Tool Manager. A list of reference regulations for required testing may be found in the attachment titled Specialty Equipment Industry and Safety Requirements. Tools in this category are now regulated by the requirements of the applicable document.)		Testing Required	No Testing Required  X


\*\* Checklist Continued on Next Page\*\*

**Specialty Tool Critical Requirements Checklist**

<i>Critical Criteria</i>		Yes	No
1	Does this tool operate under machine power?		X
2	Does this tool contain significant stored energy (springs, trigger mechanism, etc)?		X
3	If the tool were to fail, would its failure result in operator injury?		X
4	Does this tool operate in extreme environments (temperature, pressure, potentially corrosive, etc.)?		X
5	Does this tool operate in a repetitive manner at high levels of force (conditions indicative of fatigue)?		X
6	Regardless of checklist results, does good judgment necessitate an engineering review of this tool?		X
Does this tool require Engineering Review?  (Any checkmarks under the Yes column require the tool to go through an engineering review. A tool required to complete an engineering review must be properly labeled until approved for use by Specialty Tool Manager.)		Critical	Non-critical  X

Signature of Tool Originator	<i>Ralph Pedera</i>	Date	<i>4/6/06</i>
Signature of Specialty Tool Manager		Date	

ML-U1-TV-003 – Throttle Pilot Spanner



**Specialty Tool Critical Requirements Checklist**

Tool ID #: ML-U1-TV-004	Completed By: Ralph Pederson	Date Completed: 4-12-2006
Tool Name: TV Secondary Plug lock	Manager Name:	Date Reviewed:
Brief Description of Tool: Clamp to hold throttling valve secondary plug stationary while loosening guide bushing nut		

<i>Unfit For Use Criteria</i>		Yes	No
1	For an existing tool, are there any visual material deformations such as: cracks, crazing, nicks, excessive rust, significant wear, mushrooming, etc.		X
Is this tool <i>unfit</i> for use?  (Any checkmarks under the Yes column establish this tool as <i>Unfit for Use</i> and this tool shall no longer be used. A tool determined unfit for use shall be properly labeled and a new tool shall fabricated in accordance with this document.)		Unfit for Use	Fit for Use  Y

<i>Testing Criteria</i>		Yes	No
1	Is this tool used for lifting, as a lifting accessory, or for specialized rigging?		X
Must this tool complete required testing?  (Any checkmarks under the Yes column require this tool complete required testing before further use. A tool required to complete testing must be properly labeled until approved for use by Specialty Tool Manager. A list of reference regulations for required testing may be found in the attachment titled Specialty Equipment Industry and Safety Requirements. Tools in this category are now regulated by the requirements of the applicable document.)		Testing Required	No Testing Required  Y

\*\* Checklist Continued on Next Page\*\*

**Specialty Tool Identification Form**

General Information		
Tool Name: TV Secondary Plug Lock	Tool Originator:	Tool ID #: ML-41-TV-004
Date of ID Issue: 4-12-2006	Manager Name:	Tool Location:
Tool Function and Description: Clamp to hold throttle Valve secondary plug stationary while loosening guide bushing nut		

Re-certification		
Is re-certification required?	Y	(N)
If yes, please give a specific amount of time or usage.		
Other stipulations?		


Verification of ID Usage		
Location on Tool:	Manager Initials:	Date:
Specific Label:		

**Specialty Tool Critical Requirements Checklist**

<i>Critical Criteria</i>		Yes	No
1	Does this tool operate under machine power?		✓
2	Does this tool contain significant stored energy (springs, trigger mechanism, etc)?		X
3	If the tool were to fail, would its failure result in operator injury?		X
4	Does this tool operate in extreme environments (temperature, pressure, potentially corrosive, etc.)?		X
5	Does this tool operate in a repetitive manner at high levels of force (conditions indicative of fatigue)?		X
6	Regardless of checklist results, does good judgment necessitate an engineering review of this tool?		X
Does this tool require Engineering Review? <small>(Any checkmarks under the Yes column require the tool to go through an engineering review. A tool required to complete an engineering review must be properly labeled until approved for use by Specialty Tool Manager.)</small>		Critical	Non-critical  X

Signature of Tool Originator	<i>Ralph Pedersen</i>	Date	<i>4-12-2006</i>
Signature of Specialty Tool Manager		Date	

ML-U1-TV-004 – TV Secondary Plug Lock



**Specialty Tool Identification Form**

<i>General Information</i>		
Tool Name: GV Plug Lock	Tool Originator:	Tool ID #: ML-KI-GV-001
Date of ID Issue: 4-17-2006	Manager Name:	Tool Location: Mitchell Station
Tool Function and Description: Clamp to hold governor valve plug while loosening valve bushing guide nut		

<i>Re-certification</i>		
Is re-certification required?	Y	(N)
If yes, please give a specific amount of time or usage.		
Other stipulations?		

<i>Verification of ID Usage</i>		
Location on Tool:	Manager Initials:	Date:
Specific Label:		

**Specialty Tool Critical Requirements Checklist**

Tool ID #: ML-41-GV-001	Completed By: Ralph Pederson	Date Completed: 4-17-2006
Tool Name:	Manager Name:	Date Reviewed:
Brief Description of Tool: Clamp to hold governor valve plug while loosening valve guide bushing nut		

<i>Unfit For Use Criteria</i>		Yes	No
1	For an existing tool, are there any visual material deformations such as: cracks, crazing, nicks, excessive rust, significant wear, mushrooming, etc.		X
Is this tool <i>unfit</i> for use? <small>(Any checkmarks under the Yes column establish this tool as <i>Unfit for Use</i> and this tool shall no longer be used. A tool determined unfit for use shall be properly labeled and a new tool shall fabricated in accordance with this document.)</small>		Unfit for Use	Fit for Use ✓

<i>Testing Criteria</i>		Yes	No
1	Is this tool used for lifting, as a lifting accessory, or for specialized rigging?		X
Must this tool complete required testing? <small>(Any checkmarks under the Yes column require this tool complete required testing before further use. A tool required to complete testing must be properly labeled until approved for use by Specialty Tool Manager. A list of reference regulations for required testing may be found in the attachment titled Specialty Equipment Industry and Safety Requirements. Tools in this category are now regulated by the requirements of the applicable document.)</small>		Testing Required	No Testing Required X

**\*\* Checklist Continued on Next Page\*\***

**Specialty Tool Critical Requirements Checklist**

<i>Critical Criteria</i>		Yes	No
1	Does this tool operate under machine power?		X
2	Does this tool contain significant stored energy (springs, trigger mechanism, etc.)?		X
3	If the tool were to fail, would its failure result in operator injury?		X
4	Does this tool operate in extreme environments (temperature, pressure, potentially corrosive, etc.)?		X
5	Does this tool operate in a repetitive manner at high levels of force (conditions indicative of fatigue)?		X
6	Regardless of checklist results, does good judgment necessitate an engineering review of this tool?		X
Does this tool require Engineering Review?		Critical	Non-critical
(Any checkmarks under the Yes column require the tool to go through an engineering review. A tool required to complete an engineering review must be properly labeled until approved for use by Specialty Tool Manager.)			X

Signature of Tool Originator	<i>Ralph Pederson</i>	Date	<i>4-17-2006</i>
Signature of Specialty Tool Manager		Date	

ML-U1-GV-001 – GV Plug Lock



**Specialty Tool Critical Requirements Checklist**

Tool ID #: ML-41-GV-002	Completed By: Ralph Pedersen	Date Completed: 4-17-2006
Tool Name: GV Plug Spanner	Manager Name:	Date Reviewed:
Brief Description of Tool: Spanner wrench to work on GV bushing guide nut while ML-41-GV-001 holds GV plug		

<i>Unfit For Use Criteria</i>		Yes	No
1	For an existing tool, are there any visual material deformations such as: cracks, crazing, nicks, excessive rust, significant wear, mushrooming, etc.		X
Is this tool <i>unfit</i> for use?		Unfit for Use	Fit for Use
(Any checkmarks under the Yes column establish this tool as <i>Unfit for Use</i> and this tool shall no longer be used. A tool determined unfit for use shall be properly labeled and a new tool shall be fabricated in accordance with this document.)			X

<i>Testing Criteria</i>		Yes	No
1	Is this tool used for lifting, as a lifting accessory, or for specialized rigging?		X
Must this tool complete required testing?		Testing Required	No Testing Required
(Any checkmarks under the Yes column require this tool complete required testing before further use. A tool required to complete testing must be properly labeled until approved for use by Specialty Tool Manager. A list of reference regulations for required testing may be found in the attachment titled Specialty Equipment Industry and Safety Requirements. Tools in this category are now regulated by the requirements of the applicable document.)			X

\*\* Checklist Continued on Next Page\*\*

**Specialty Tool Identification Form**

General Information		
Tool Name: GV Plug Spanner	Tool Originator:	Tool ID #: ML-41-GV-002
Date of ID Issue: 4-17-2006	Manager Name:	Tool Location: Mitchell Station
Tool Function and Description: Spanner wrench to work on GV bushing guide nut while ML-41-GV-001 holds GV plug		

Re-certification		
Is re-certification required?	Y	(N)
If yes, please give a specific amount of time or usage.		
Other stipulations?		

Verification of ID Usage		
Location on Tool:	Manager Initials:	Date:
Specific Label:		

**Specialty Tool Critical Requirements Checklist**

<i>Critical Criteria</i>		<i>Yes</i>	<i>No</i>
1	Does this tool operate under machine power?		X
2	Does this tool contain significant stored energy (springs, trigger mechanism, etc)?		X
3	If the tool were to fail, would its failure result in operator injury?		X
4	Does this tool operate in extreme environments (temperature, pressure, potentially corrosive, etc.)?		X
5	Does this tool operate in a repetitive manner at high levels of force (conditions indicative of fatigue)?		X
6	Regardless of checklist results, does good judgment necessitate an engineering review of this tool?		X
Does this tool require Engineering Review?  (Any checkmarks under the Yes column require the tool to go through an engineering review. A tool required to complete an engineering review must be properly labeled until approved for use by Specialty Tool Manager.)		Critical	Non-critical  X

Signature of Tool Originator	<i>Ralph Pederson</i>	Date	<i>4-17-2006</i>
Signature of Specialty Tool Manager		Date	

ML-U1-GV-002 – GV Plug Spanner



## Recommendations


## Tab 4

1. The collector shaft fan needs to be balanced to eliminate the plant's operating process of running a 30-degree Frahanhiet differential of the air side and hydrogen side seal oil temperatures. It appears that the temperature differential is twisting the seal ring itself into a bound condition. This condition is pushing oil along the shaft past the seal gland casing labyrinth seals and into the hydrogen gas cavity. The plant operations currently drain approximately four ounces from the collector end liquid detector.
2. The generator collector end liquid detector alarm is not working. This device should be repaired or replaced.
3. The Seal Oil Skid turbine end and exciter end equalizing valves appear sluggish and binding. These should be shipped to Ruggles-Klingmann for a full overhaul and bench test.
4. The governor valve stand snout bushings are distressing from past tack welds. The next inspection should replace all eight of these bushings.



**Data Attachments**

**Tab 5**

**American Electric Power  
Mitchell Plant Unit #1  
5/21/2006  
MLU106  
TD 39415**



**Diagram of LO Cooler Lantern  
Ring Fit for Mitchell Plant #1  
MLU106**



Rotor was set on "K" = 0.880 Design "K" = 0.880																																																																																																																																																																																																																																																																																																																																																																					
CYLIND																																																																																																																																																																																																																																																																																																																																																																					
GNN																																																																																																																																																																																																																																																																																																																																																																					
MRTT = 0.040 MRTT is Move Rotor To Thrust ***** Closer to Design or Better																																																																																																																																																																																																																																																																																																																																																																					
SPINDLE(Rotor)																																																																																																																																																																																																																																																																																																																																																																					
<table border="1"> <thead> <tr> <th colspan="3">Left Side</th> <th colspan="6">Right Side</th> </tr> <tr> <th>Row</th> <th>A</th> <th>B</th> <th>L</th> <th>M</th> <th>S</th> <th>T</th> <th>E</th> <th>F</th> <th>A</th> <th>B</th> <th>L</th> <th>M</th> <th>S</th> <th>T</th> <th>E</th> <th>F</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>0.942</td> <td>0.647</td> <td></td> <td></td> <td></td> <td></td> <td>0.776</td> <td>0.676</td> <td>0.947</td> <td>0.639</td> <td></td> <td></td> <td></td> <td></td> <td>0.811</td> <td>0.657</td> </tr> <tr> <td>Design</td> <td>0.810</td> <td>0.500</td> <td></td> <td></td> <td></td> <td></td> <td>0.810</td> <td>0.500</td> <td>Design</td> <td>0.810</td> <td>0.500</td> <td></td> <td></td> <td></td> <td>0.810</td> <td>0.500</td> </tr> <tr> <td>MRTT</td> <td>0.902</td> <td>0.607</td> <td>*****</td> <td></td> <td></td> <td></td> <td>0.816</td> <td>0.716</td> <td>MRTT</td> <td>0.907</td> <td>0.599</td> <td>*****</td> <td></td> <td></td> <td>0.851</td> <td>0.697</td> </tr> <tr> <td>2</td> <td>1.159</td> <td>0.365</td> <td></td> <td></td> <td></td> <td></td> <td>1.117</td> <td>0.397</td> <td>1.144</td> <td>0.383</td> <td></td> <td></td> <td></td> <td></td> <td>1.131</td> <td>0.421</td> </tr> <tr> <td>Design</td> <td>1.130</td> <td>0.380</td> <td></td> <td></td> <td></td> <td></td> <td>1.130</td> <td>0.380</td> <td>Design</td> <td>1.130</td> <td>0.380</td> <td></td> <td></td> <td></td> <td>1.130</td> <td>0.380</td> </tr> <tr> <td>MRTT</td> <td>1.119</td> <td>0.325</td> <td></td> <td></td> <td></td> <td></td> <td>1.157</td> <td>0.437</td> <td>MRTT</td> <td>1.104</td> <td>0.343</td> <td></td> <td></td> <td></td> <td>1.171</td> <td>0.461</td> </tr> <tr> <td>3</td> <td>1.154</td> <td>0.346</td> <td></td> <td></td> <td></td> <td></td> <td>XXXXXX</td> <td>XXXXXX</td> <td>Design</td> <td>1.133</td> <td>0.333</td> <td></td> <td></td> <td></td> <td>XXXXXX</td> <td>XXXXXX</td> </tr> <tr> <td>Design</td> <td>1.130</td> <td>0.380</td> <td></td> <td></td> <td></td> <td></td> <td>XXXXXX</td> <td>XXXXXX</td> <td>MRTT</td> <td>1.093</td> <td>0.293</td> <td></td> <td></td> <td></td> <td>XXXXXX</td> <td>XXXXXX</td> </tr> <tr> <td>MRTT</td> <td>1.114</td> <td>0.306</td> <td></td> </tr> <tr> <td>4</td> <td>0.785</td> <td>0.350</td> <td></td> <td></td> <td></td> <td></td> <td>0.740</td> <td>0.415</td> <td>0.760</td> <td>0.341</td> <td></td> <td></td> <td></td> <td></td> <td>0.735</td> <td>0.414</td> </tr> <tr> <td>Design</td> <td>0.720</td> <td>0.340</td> <td></td> <td></td> <td></td> <td></td> <td>0.780</td> <td>0.410</td> <td>Design</td> <td>0.720</td> <td>0.340</td> <td></td> <td></td> <td></td> <td>0.780</td> <td>0.410</td> </tr> <tr> <td>MRTT</td> <td>0.745</td> <td>0.310</td> <td>*****</td> <td></td> <td></td> <td></td> <td>0.780</td> <td>0.455</td> <td>MRTT</td> <td>0.720</td> <td>0.301</td> <td>*****</td> <td></td> <td></td> <td>0.775</td> <td>0.454</td> </tr> <tr> <td>5</td> <td>0.764</td> <td>0.321</td> <td></td> <td></td> <td></td> <td></td> <td>1.263</td> <td>0.930</td> <td>0.744</td> <td>0.316</td> <td></td> <td></td> <td></td> <td></td> <td>1.279</td> <td>0.925</td> </tr> <tr> <td>Design</td> <td>0.720</td> <td>0.340</td> <td></td> <td></td> <td></td> <td></td> <td>1.280</td> <td>0.910</td> <td>Design</td> <td>0.720</td> <td>0.340</td> <td></td> <td></td> <td></td> <td>1.280</td> <td>0.910</td> </tr> <tr> <td>MRTT</td> <td>0.724</td> <td>0.281</td> <td>*****</td> <td></td> <td></td> <td></td> <td>1.303</td> <td>0.970</td> <td>MRTT</td> <td>0.704</td> <td>0.276</td> <td></td> <td></td> <td></td> <td>1.319</td> <td>0.965</td> </tr> <tr> <td>6</td> <td>1.013</td> <td>0.340</td> <td></td> <td></td> <td></td> <td></td> <td>0.437</td> <td></td> <td>1.109</td> <td>0.343</td> <td></td> <td></td> <td></td> <td></td> <td>0.445</td> <td></td> </tr> <tr> <td>Design</td> <td>0.970</td> <td>0.340</td> <td></td> <td></td> <td></td> <td></td> <td>0.410</td> <td>XXXXXX</td> <td>Design</td> <td>0.970</td> <td>0.340</td> <td></td> <td></td> <td></td> <td>0.410</td> <td>XXXXXX</td> </tr> <tr> <td>MRTT</td> <td>0.973</td> <td>0.300</td> <td>*****</td> <td></td> <td></td> <td></td> <td>0.477</td> <td></td> <td>MRTT</td> <td>1.069</td> <td>0.303</td> <td>*****</td> <td></td> <td></td> <td>0.485</td> <td></td> </tr> <tr> <td colspan="13">GNN</td> </tr> </tbody> </table>													Left Side			Right Side						Row	A	B	L	M	S	T	E	F	A	B	L	M	S	T	E	F	1	0.942	0.647					0.776	0.676	0.947	0.639					0.811	0.657	Design	0.810	0.500					0.810	0.500	Design	0.810	0.500				0.810	0.500	MRTT	0.902	0.607	*****				0.816	0.716	MRTT	0.907	0.599	*****			0.851	0.697	2	1.159	0.365					1.117	0.397	1.144	0.383					1.131	0.421	Design	1.130	0.380					1.130	0.380	Design	1.130	0.380				1.130	0.380	MRTT	1.119	0.325					1.157	0.437	MRTT	1.104	0.343				1.171	0.461	3	1.154	0.346					XXXXXX	XXXXXX	Design	1.133	0.333				XXXXXX	XXXXXX	Design	1.130	0.380					XXXXXX	XXXXXX	MRTT	1.093	0.293				XXXXXX	XXXXXX	MRTT	1.114	0.306															4	0.785	0.350					0.740	0.415	0.760	0.341					0.735	0.414	Design	0.720	0.340					0.780	0.410	Design	0.720	0.340				0.780	0.410	MRTT	0.745	0.310	*****				0.780	0.455	MRTT	0.720	0.301	*****			0.775	0.454	5	0.764	0.321					1.263	0.930	0.744	0.316					1.279	0.925	Design	0.720	0.340					1.280	0.910	Design	0.720	0.340				1.280	0.910	MRTT	0.724	0.281	*****				1.303	0.970	MRTT	0.704	0.276				1.319	0.965	6	1.013	0.340					0.437		1.109	0.343					0.445		Design	0.970	0.340					0.410	XXXXXX	Design	0.970	0.340				0.410	XXXXXX	MRTT	0.973	0.300	*****				0.477		MRTT	1.069	0.303	*****			0.485		GNN												
Left Side			Right Side																																																																																																																																																																																																																																																																																																																																																																		
Row	A	B	L	M	S	T	E	F	A	B	L	M	S	T	E	F																																																																																																																																																																																																																																																																																																																																																					
1	0.942	0.647					0.776	0.676	0.947	0.639					0.811	0.657																																																																																																																																																																																																																																																																																																																																																					
Design	0.810	0.500					0.810	0.500	Design	0.810	0.500				0.810	0.500																																																																																																																																																																																																																																																																																																																																																					
MRTT	0.902	0.607	*****				0.816	0.716	MRTT	0.907	0.599	*****			0.851	0.697																																																																																																																																																																																																																																																																																																																																																					
2	1.159	0.365					1.117	0.397	1.144	0.383					1.131	0.421																																																																																																																																																																																																																																																																																																																																																					
Design	1.130	0.380					1.130	0.380	Design	1.130	0.380				1.130	0.380																																																																																																																																																																																																																																																																																																																																																					
MRTT	1.119	0.325					1.157	0.437	MRTT	1.104	0.343				1.171	0.461																																																																																																																																																																																																																																																																																																																																																					
3	1.154	0.346					XXXXXX	XXXXXX	Design	1.133	0.333				XXXXXX	XXXXXX																																																																																																																																																																																																																																																																																																																																																					
Design	1.130	0.380					XXXXXX	XXXXXX	MRTT	1.093	0.293				XXXXXX	XXXXXX																																																																																																																																																																																																																																																																																																																																																					
MRTT	1.114	0.306																																																																																																																																																																																																																																																																																																																																																																			
4	0.785	0.350					0.740	0.415	0.760	0.341					0.735	0.414																																																																																																																																																																																																																																																																																																																																																					
Design	0.720	0.340					0.780	0.410	Design	0.720	0.340				0.780	0.410																																																																																																																																																																																																																																																																																																																																																					
MRTT	0.745	0.310	*****				0.780	0.455	MRTT	0.720	0.301	*****			0.775	0.454																																																																																																																																																																																																																																																																																																																																																					
5	0.764	0.321					1.263	0.930	0.744	0.316					1.279	0.925																																																																																																																																																																																																																																																																																																																																																					
Design	0.720	0.340					1.280	0.910	Design	0.720	0.340				1.280	0.910																																																																																																																																																																																																																																																																																																																																																					
MRTT	0.724	0.281	*****				1.303	0.970	MRTT	0.704	0.276				1.319	0.965																																																																																																																																																																																																																																																																																																																																																					
6	1.013	0.340					0.437		1.109	0.343					0.445																																																																																																																																																																																																																																																																																																																																																						
Design	0.970	0.340					0.410	XXXXXX	Design	0.970	0.340				0.410	XXXXXX																																																																																																																																																																																																																																																																																																																																																					
MRTT	0.973	0.300	*****				0.477		MRTT	1.069	0.303	*****			0.485																																																																																																																																																																																																																																																																																																																																																						
GNN																																																																																																																																																																																																																																																																																																																																																																					

Rotor was set on "K" = <u>0.880</u> Design "K" = <u>0.880</u> CYLIND																
<b>GVN</b>																
MRTT = 0.040 MRTT is Move Rotor To Thrust ***** Closer to Design or Better																
Left Side				Right Side												
Row	A	B	L	M	S	T	E	F	A	B	L	M	S	T	E	F
1	0.761	0.608					0.937	0.620	0.880	0.571					0.787	0.610
Design	0.880	0.560					0.750	0.440	Design	0.880	0.560				0.750	0.440
MRTT	0.801	0.648	*****				0.897	0.580	MRTT	0.920	0.611	*****			0.747	0.570
2	1.167	0.394					1.070	0.391		1.167	0.384				1.070	0.404
Design	1.190	0.440					0.690	0.310	Design	1.190	0.440				0.690	0.310
MRTT	1.207	0.434	*****				1.030	0.351	MRTT	1.207	0.424	*****			1.030	0.364
3	1.166	0.379								1.168	0.370					
Design	1.190	0.440					XXXXXX	XXXXXX	Design	1.190	0.440				XXXXXX	XXXXXX
MRTT	1.206	0.419	*****						MRTT	1.208	0.410	*****				
4	0.785	0.404					0.771	0.371		0.771	0.348				0.751	0.389
Design	0.780	0.410					0.720	0.340	Design	0.780	0.410				0.720	0.340
MRTT	0.825	0.444	*****				0.731	0.331	MRTT	0.811	0.388	*****			0.711	0.349
5	0.752	0.357					1.266	0.893		0.746	0.337				1.302	0.914
Design	0.780	0.410					1.220	0.840	Design	0.780	0.410				1.220	0.840
MRTT	0.792	0.397	*****				1.226	0.853	MRTT	0.786	0.377	*****			1.262	0.874
6	0.992	0.381					0.469	0.484		0.989	0.346				0.469	0.480
Design	1.030	0.410					0.410	XXXXXX	Design	1.030	0.410				0.410	XXXXXX
MRTT	1.032	0.421	*****				0.429	0.429	MRTT	1.029	0.386	*****			0.429	0.429
<b>GVN</b>																

# Steam Seal Clearance Record

## IP Rotor Clearances

Sheet 1

Date: 5/22/2006 Turbine Serial No. MLU106 Prepared by Bordenkircher

ROW NO.	Left Side Clearances					Right Side Clearances					
		A	B	C	D	A	B				
1	A	0.052	0.050	0.280	0.375			0.060	0.060		
	E	0.030	0.030	0.320	0.320			0.030	0.030		
	D	0.022	0.020	-0.040	0.055			0.030	0.030		
2	A	0.040	0.044	0.305	0.351			0.042	0.042		
	E	0.020	0.020	0.320	0.320			0.020	0.020		
	D	0.020	0.024	-0.015	0.031			0.022	0.022		
3	A	0.012	0.012	0.275	0.370			0.030	0.029		
	E	0.020	0.020	0.320	0.320			0.020	0.020		
	D	-0.008	-0.008	-0.045	0.050			0.010	0.009		
4	A	0.016	0.012	0.300	0.356			0.032	0.031		
	E	0.020	0.020	0.320	0.320			0.020	0.020		
	D	-0.004	-0.008	-0.020	0.036			0.012	0.011		
5	A	0.014	0.015	0.297	0.357			0.033	0.031		
	E	0.020	0.020	0.320	0.320			0.020	0.020		
	D	-0.006	-0.005	-0.023	0.037			0.013	0.011		
GV6	A	0.025	0.027	0.330	0.390			0.045	0.046		
	E	0.035	0.035	0.380	0.320			0.035	0.035		
	D	-0.010	-0.008	-0.050	0.070			0.010	0.011		
GV5	A	0.030	0.027	0.322	0.403			0.045	0.045		
	E	0.035	0.035	0.380	0.320			0.035	0.035		
	D	-0.005	-0.008	-0.058	0.083			0.010	0.010		
GV4	A	0.027	0.024	0.370	0.355			0.046	0.046		
	E	0.035	0.035	0.380	0.320			0.035	0.035		
	D	-0.008	-0.011	-0.010	0.035			0.011	0.011		
GV3	A	0.045	0.044	0.360	0.367			0.067	0.067		
	E	0.035	0.035	0.410	0.290			0.035	0.035		
	D	0.010	0.009	-0.050	0.077			0.032	0.032		
GV2	A	0.044	0.042	0.370	0.355			0.061	0.057		
	E	0.035	0.035	0.410	0.290			0.035	0.035		
	D	0.009	0.007	-0.040	0.065			0.026	0.022		
FG	A	0.012						0.090			
	E										
	D										
FG	A	0.012						0.087			
	E										
	D										
GE2	A	0.035	0.036	0.376	0.348			0.044	0.046		
	E	0.035	0.035	0.350	0.350			0.035	0.035		
	D	0.000	0.001	0.026	-0.002			0.009	0.011		

Comments: "K" = .880"

A = Actual E = Expected D = Difference

## Steam Seal Clearance Record

### IP Rotor Clearances

Sheet 2

Date: 5/22/2006 Turbine Serial No. MLU106 Prepared by Bordenkircher

ROW NO.	Left Side Clearances				Right Side Clearances								
	A	B	C	D	A	B							
GE3	A	0.042	0.035	0.394	0.330			0.049	0.045				
	E	0.035	0.035	0.350	0.350			0.035	0.035				
	D	0.007	0.000	0.044	-0.020			0.014	0.010				
GE4	A	0.017	0.016	0.407	0.320			0.075	0.072				
	E	0.035	0.035	0.380	0.320			0.035	0.035				
	D	-0.018	-0.019	0.027	0.000			0.040	0.037				
GE5	A	0.014	0.015	0.402	0.317			0.046	0.040				
	E	0.035	0.035	0.380	0.320			0.035	0.035				
	D	-0.021	-0.020	0.022	-0.003			0.011	0.005				
GE6	A	0.016	0.014	0.390	0.332			0.061	0.055				
	E	0.035	0.035	0.380	0.320			0.035	0.035				
	D	-0.019	-0.021	0.010	0.012			0.026	0.020				
6	A	0.003	0.004	0.387	0.274			0.041	0.037				
	E	0.020	0.020	0.350	0.350			0.020	0.020				
	D	-0.017	-0.016	0.037	-0.076			0.021	0.017				
7	A	0.012	0.011	0.372	0.295			0.045	0.046				
	E	0.020	0.020	0.350	0.350			0.020	0.020				
	D	-0.008	-0.009	0.022	-0.055			0.025	0.026				
8	A	0.017	0.015	0.407	0.252			0.040	0.041				
	E	0.020	0.020	0.350	0.350			0.020	0.020				
	D	-0.003	-0.005	0.057	-0.098			0.020	0.021				
9	A	0.026	0.023	0.407	0.277			0.058	0.061				
	E	0.020	0.020	0.350	0.350			0.020	0.020				
	D	0.006	0.003	0.057	-0.073			0.038	0.041				
10	A	0.022	0.021	0.407	0.234			0.065	0.061				
	E	0.030	0.030	0.350	0.290			0.030	0.030				
	D	-0.008	-0.009	0.057	-0.056			0.035	0.031				
	A												
	E												
	D												
	A												
	E												
	D												
	A												
	E												
	D												
	A												
	E												
	D												
Comments:		"K"= .880"											
A = Actual E = Expected D = Difference													

## Packing Butt Gaps

### Westinghouse GS Casing and Stationary Blade Shroud

Date(m/d/y) 5/20/2006 Turbine S/N: MLU106 Prepared by Rahn

Data   
 (As Found/Final)

Section  IP  
 (HP/LP)

Notes: 1. Packing above diaphragm record as PLUS (+).  
 2. Packing below diaphragm record as MINUS (-).


Stage	Lower Half		Upper Half		Packing Butt Gap		Amount to Machine per segment	# of Segments
	Left Mils	Right Mils	Left Mils	Right Mils	Total	Design		
<b>GV OT G1</b>	7	-41	6	16	-12	12		<b>OK</b>
<b>GV OT G2</b>	-20	-4	-6	9	-21	12		<b>OK</b>
<b>GV IN G3</b>	22	-1	-18	-15	-12	12		<b>OK</b>
<b>GV IN G4</b>	19	18	-68	19	-12	12		<b>OK</b>
<b>GV IN G5</b>	1	8	0	-46	-37	12		<b>OK</b>
<b>GV R6</b>	-41	42	-231	214	-16	12		<b>OK</b>
<b>GV R5</b>	25	0	-154	111	-18	12		<b>OK</b>
<b>GV R4</b>	41	0	33	-96	-22	12		<b>OK</b>
<b>GV R3</b>	-9	55	-37	-21	-12	12		<b>OK</b>
<b>GV R2</b>	46	-25	-27	-36	-42	12		<b>OK</b>
<b>GV R1</b>	-123	113	-7	0	-17	12		<b>OK</b>
<b>GE R1</b>	14	35	-42	-55	-48	12		<b>OK</b>
<b>GE R2</b>	68	-39	-38	-6	-15	12		<b>OK</b>
<b>GE R3</b>	93	-38	-76	-3	-24	12		<b>OK</b>
<b>GE R4</b>	-30	1	-60	71	-18	12		<b>OK</b>
<b>GE R5</b>	-64	6	5	5	-48	12		<b>OK</b>
<b>GE R6</b>	73	-11	-37	-46	-21	12		<b>OK</b>
<b>GE IN G6</b>	10	8	6	-47	-23	12		<b>OK</b>
<b>GE IN G7</b>	-11	-6	-13	-3	-33	12		<b>OK</b>
<b>GE IN G8</b>	-14	5	-9	6	-12	12		<b>OK</b>
<b>GE OT G9</b>	-8	-19	-5	20	-12	12		<b>OK</b>
<b>GE OT G10</b>	-9	-43	26	-3	-29	12		<b>OK</b>

## Reaction Blading Clearance Record

### IP Rotor Clearances

Date: 5/22/2006 Turbine Serial No. MLU106 Prepared by Vickers

ROW NO.	Left Side Clearances							Right Side Clearances								
	A	B	E	F	L	M		A	B	E	F	L	M			
GV1	A	0.761	0.608	0.937	0.620	0.207	0.186		0.880	0.571	0.787	0.610	0.230	0.220		
	E	x	0.560	0.750	0.440	0.035	0.035		x	0.560	0.750	0.440	0.035	0.035		
	D		0.048	0.187	0.180	0.172	-0.151			0.011	0.037	0.170	0.195	0.185		
GV2	A	1.167	0.394	1.131	0.391	0.019	0.021		1.167	0.384	1.117	0.404	0.052	0.055		
	E	0.810	0.440	0.690	0.310	0.035	0.035		0.810	0.440	0.690	0.310	0.035	0.035		
	D	0.357	-0.046	0.441	0.081	-0.016	-0.014		0.357	-0.056	0.427	0.094	0.017	0.020		
GV3	A	1.666	0.379	1.031	1.511	0.050	0.040		1.168	0.370	1.031	1.529	0.075	0.055		
	E	0.810	0.440	x	x	0.035	0.035		0.810	0.440	x	x	0.035	0.035		
	D	0.856	-0.061			0.015	0.005		0.358	-0.070			0.040	0.020		
GV4	A	0.785	0.404	0.771	0.371	0.190	0.035		0.771	0.348	0.751	0.389	0.195	0.044		
	E	0.780	0.410	0.720	0.340	0.035	0.035		0.780	0.410	0.720	0.340	0.035	0.035		
	D	0.005	-0.006	0.051	0.031	0.155	0.000		-0.009	-0.062	0.031	0.049	0.160	0.009		
GV5	A	0.752	0.357	1.266	0.893	0.035	0.036		0.746	0.337	1.302	0.914	0.045	0.042		
	E	0.780	0.410	1.220	0.840	0.035	0.035		0.780	0.410	1.220	0.840	0.035	0.035		
	D	-0.028	-0.053	0.046	0.053	0.000	0.001		-0.034	-0.073	0.082	0.074	0.010	0.007		
GV6	A	0.992	0.381	0.469	0.484	0.035	0.036		0.989	0.346	0.469	0.480	0.050	0.044		
	E	1.030	0.410	0.410	x	0.035	0.035		1.030	0.410	0.410	x	0.035	0.035		
	D	-0.038	-0.029	0.059		0.000	0.001		-0.041	-0.064	0.059		0.015	0.009		
	A															
	E															
	D															
GE1	A	0.942	0.647	0.776	0.676	0.200	0.194		0.947	0.639	0.811	0.657	0.226	0.217		
	E	0.810	0.500	0.810	0.500	0.035	0.035		0.810	0.500	0.810	0.500	0.035	0.035		
	D	0.132	0.147	-0.034	0.176	0.165	0.159		0.137	0.139	0.001	0.157	0.191	0.182		
GE2	A	1.159	0.365	1.117	0.397	0.035	0.032		1.144	0.383	1.131	0.421	0.045	0.045		
	E	0.750	0.380	0.750	0.380	0.035	0.035		0.750	0.380	0.750	0.380	0.035	0.035		
	D	0.409	-0.015	0.367	0.017	0.000	-0.003		0.394	0.003	0.381	0.041	0.010	0.010		
GE3	A	1.154	0.346	1.284	1.574	0.045	0.045		1.133	0.333	1.187	1.587	0.049	0.049		
	E	0.750	0.380	x	x	0.035	0.035		0.750	0.380	x	x	0.035	0.035		
	D	0.404	-0.034			0.010	0.010		0.383	-0.047			0.014	0.014		
GE4	A	0.785	0.350	0.740	0.415	0.130	0.015		0.760	0.341	0.735	0.414	0.200	0.058		
	E	0.720	0.340	0.780	0.410	0.035	0.035		0.720	0.340	0.780	0.410	0.035	0.035		
	D	0.065	0.010	-0.040	0.005	0.095	-0.020		0.040	0.001	-0.045	0.004	0.165	0.023		
GE5	A	0.764	0.321	1.263	0.930	0.011	0.012		0.744	0.316	1.279	0.925	0.055	0.064		
	E	0.720	0.340	1.280	0.910	0.035	0.035		0.720	0.340	1.280	0.910	0.035	0.035		
	D	0.044	-0.019	-0.017	0.020	-0.024	-0.023		0.024	-0.024	-0.001	0.015	0.020	0.029		
GE6	A	1.013	0.340	0.437	0.580	0.014	0.015		1.109	0.343	0.445	0.568	0.060	0.066		
	E	0.970	0.340	0.470	x	0.035	0.035		0.970	0.340	0.470	x	0.035	0.035		
	D	0.043	0.000	-0.033		-0.021	-0.020		0.139	0.003	-0.025		0.025	0.031		
Comments:																
"K" = .880"																
A = Actual E = Expected D = Difference																



**NOTES:**

1. THESE CLEARANCES RESULT AFTER UPPER HALVES ARE IN PLACE. RECORD ACTUAL CLEARANCES UPPER HALVES OFF.
2. FOR ALL OTHER VIEWS AND DIMENSIONS SEE ORIGINAL ROTOR CLEARANCE 775J709.
3. CLEARANCES ON DRAWING WERE TAKEN FROM INITIAL SHOP ASSEMBLY, AND ADJUSTED FOR NEW BLADES WITH DIFFERENT AXIAL SHROUD WIDTHS.

**SYMBOLS:**

A. P.S. - 84800WJ PT. 1 ASSEMBLY VERIFICATION OF STEAM TURBINE.

**BLADE AXIAL CLEARANCES - GENERATOR END (BLADING)**

QZ	ROTOR BLADES			CYLINDER BLADES		
	INLET	OUTLET	OUTLET	INLET	OUTLET	OUTLET
1	.50	.50	.50			
2	.38	.38	.38			
3	.38					

TOLERANCE: ± .020

**BLADE RADIAL CLEARANCES - GNN**


QZ	ROTOR			CYLINDER		
	INLET	M	OUTLET	INLET	M	OUTLET
1	.035	.035	.035			
2	.035	.035	.035			
3	.035	.035	.035			

TOLERANCE: ± .005/- .002

**ENGINEERING INFO ONLY**  
 THIS DRAWING IS FOR REPLACEMENT OF IP PADDLE BLADES ONLY. DO NOT ATTEMPT CONSTRUCTIVE SERVICE ENGINEERING OF FIRST BLADE REPLACEMENT INFO.

<b>SEE COMPUTERIZED BILL OF MATERIAL</b>	PART NAME: PBS9D15663010	QTY: 1	REV: 30002JIS	SHIP ORDER: 13A361-1
<b>THIRD ANGLE PROJECTION</b>	THIS DRAWING CONTAINS INFORMATION PROPRIETARY TO SIEMENS WESTINGHOUSE POWER CORPORATION. IT IS SUBJECT TO THE TERMS AND CONDITIONS OF THE SIEMENS WESTINGHOUSE POWER CORPORATION SUPPLIER AGREEMENT. IT IS NOT TO BE REPRODUCED, TRANSMITTED, OR USED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION OF SIEMENS WESTINGHOUSE POWER CORPORATION.			
<b>SIEMENS Westinghouse</b>		A Siemens Company		
TITLE: ROTOR CLEARANCE		QTY: 9D13683	REV: 01	
APPLICATION: BB 58		REFERENCE DRAWING: 8039D66 775J709	SHEET: 1	FORMAT: SWPC.D

CAD DRAWING NO. MANUAL CHANGES




**ENGINEERING INFO ONLY**  
 THIS DRAWING IS FOR REPLACEMENT OF PARTS AND IS NOT TO BE USED FOR ADDING OR REMOVING PARTS WITHOUT CONTACTING SERVICE. SEE SPECIFICATIONS FOR PARTS. SEE REPLACEMENT INFO.

SEE COMPUTERIZED BILL OF MATERIAL	DATE	BY	DESCRIPTION	REV
	P880136830201	ADRA	30002215	13A381-1

THIS DRAWING CONTAINS INFORMATION PROPRIETARY TO SIEMENS WESTINGHOUSE POWER CORPORATION. IT IS TO BE USED ONLY FOR THE PURPOSES AND SCOPE OF THE PROJECT FOR WHICH IT IS PREPARED AND RETURNED TO SIEMENS WESTINGHOUSE POWER CORPORATION UPON COMPLETION OF THE PROJECT. ANY REUSE OR DISSEMINATION OF THIS INFORMATION WITHOUT THE WRITTEN AUTHORIZATION OF SIEMENS WESTINGHOUSE POWER CORPORATION IS STRICTLY PROHIBITED.

**SIEMENS Westinghouse**  
 Siemens Westinghouse Power Corporation  
 A Siemens Company


ROTOR CLEARANCE SUPPL	9D13683	01
APPLICATION	BB 58	8035066 775J709
DRAWING NOT TO SCALE		
FORMAT	LSHPC.D	







American Electric Power  
 Ohio Power Company  
 Mitchell Station  
 Unit #1

### Rotor Axial L Reference Readings




Date	L1 rs	L2 ls	L3 ls	L4 ls	L5 ls	L6 ls	L7 ls	FG
6/3/2006	5.767	15.183	15.471*	18.366*		4.955*		
<b>CPLG A spacer is 1.405" CPLG C spacer is 1.211"</b>								
<b>IP Rotor TD 39415</b>								
IP "K" Dimension is 0.920" due to new Row 1 Stationary Blading.								
VHP/HP "K" Dimension continues to be 0.369".								
LPA "K" Dimension continues to be 0.755"								
L1 is to Welded Key Stock Right Side of Machine Pedestal								
L6 is to Coupling Guard Mounting Flange								
L reference readings are to permanent structures of bearing pedestals.								
* denotes a calculated measurement, not a physical dimension. GVN side of Thrust bearing loaded.								

MITCHELL-1 IP		DATE	5/22/06		TIME	Days											
LOCATION	SAG	RAW			RELATIVE			TRUE	TARGET			TRUE	ELEV	MOVE	SHIM	SHIM	
		LEFT	BOT	RIGHT	LEFT	BOT	RIGHT	ELEV	LEFT	BOT	RIGHT	ELEV	CHNG	SIDE-	CHNG	CHNG	
														WAYS	LEFT	RIGHT	
T-3 Oil Bore	0.005				0		0	0.005				0	0.005	0	0.005	0.005	
R2 Outer Gland	9				0		0	9				0	9	0	9	9	
<b>Gland Bore Set Point</b>	0	483		484	0		1	-0.5	0		0	0	-0.5	-0.5	-1	0	
R3 Inner Gland	1	649		667	0		18	-13	0		10	-16	3	-4	-1	7	
R5 Inner Gland	2	649		663	0		14	2	0		8	-2	4	-3	1	7	
R6-SS-GVN	4	459		457	2		0	5	0		3	9.5	-4.5	2.5	-2	-7	
<b>#2 GVN</b>			459			6					11						
R4-SS-GVN	6	88		78	10		0	3	0		9	-6.5	9.5	9.5	19	0	
			80			8					-2						
R3-SS-GVN	6				0		0	6	7		0	12.5	-6.5	-3.5	-10	-3	
<b>#1 GVN</b>						6					16						
R1-SS-GVN	7	173		173	0		0	50	4		0	46	4	-2	2	6	
			216			50					48						
FG-GVN	7	474		550	0		76	-77	0		61	-88.5	11.5	-7.5	4	19	
			428			-39					-58						
FG-GNN	7	486		539	0		53	-97.5	0		81	-90.5	-7	14	7	-21	
			408			-71					-50						
R1-SS-GNN	7	267		273	0		6	16	0		3	16.5	-0.5	-1.5	-2	1	
<b>#1 GNN</b>			279			19					18						
R3-SS-GNN	6				0		0	6	0		14	0	6	7	13	-1	
						6					7						
R4-SS-GNN	6	92		110	0		18	10	0		6	-2	12	-6	6	18	
<b>#2 GNN</b>			105			19					1						
R6-SS-GNN	4	485		502	0		17	3.5	0		4	5	-1.5	-6.5	-8	5	
			493			12					7						
R6 Inner Gland	2	664		660	4		0	-9	1		0	-10.5	1.5	1.5	3	0	
			651			-7					-10						
R8 Inner Gland	1	669		658	11		0	-18.5	2		0	-16	-2.5	4.5	2	-7	
			644			-13					-15						
<b>Gland Bore Set Point</b>	0	492		491	1		0	0.5	0		0	0	0.5	0.5	1	0	
			492			1					0						
R9 Outer Gland	9				0		0	9	0		0	0	9	0	9	9	
						9					0						
T-4 Oil Bore	6				0		0	6	1		0	16.5	-10.5	-0.5	-11	-10	
						6					17						



### Mitchell #1 Hydrogen Cooler Cooler & Reversing Chamber Spacer




Use original parts to plot through bolt holes, eye bolt threaded holes and jack screw threaded holes.

Tolerances on these dimensions =/- 0.025".





The cover thickness may go to 1.250" but no thicker than 1.5".

The reversing chamber spacer thickness is best held at 2.0".


# Dimensions of the Seal Oil Skid Cooler Components page 1/2





Cooler Support Flange



## Dimensions of the Seal Oil Skid Cooler Components page 2/2



CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>GENERATOR CLEARANCES: LABYRINTH SEAL</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	GENERATOR DWG.:



DIM. / END	A	B	C	Shaft OD	Clearance
DIA. NO. 1 TE					
DIA. NO. 2 TE					
DIA. NO. 3 TE					
DIA. NO. 1 EE	20.937	20.931	20.931	20.865	0.068
DIA. NO. 2 EE	22.513	22.516	22.515	22.454	0.039
DIA. NO. 3 EE	22.512	22.514	22.516	22.454	0.040

Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_\_

As Found \_\_\_\_\_


Reading Taken By: \_\_\_\_\_ Date: \_\_\_\_\_

As Charted \_\_\_\_\_

Reviewed By Turb Coord.: \_\_\_\_\_ Date: \_\_\_\_\_

**AEP/RSO**

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>GENERATOR HYDROGEN SEAL CLEARANCES</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.: GENERATOR	DWG.:



LOCATION	DIM A = GROOVE WIDTH	DIM B = RING THICKNESS	CLEARANCE
TOP	1.911	1.903	0.008
BOTTOM	1.911	1.903	0.008
RIGHT SIDE	1.910	1.903	0.007
LEFT SIDE	1.910	1.902	0.008

Design clearance: .007 1/2 - .009

RADIAL CLEARANCES			
LOCATION	DIM C = JOURNAL	DIM D = RING I.D.	CLEARANCE
1	20.865	20.864	0.009
2	20.865	20.879	0.014
3	20.865	20.876	0.010

Design clearance: .009-.011 on diameter

FLATNESS CHECK	
READINGS > 0.00"	LOCATION (IB/OB SIDE, DEG. FROM A.R. PIN)
0.0015	AR = 90d to 170 d
0.002	AR = 120 d to 150 d

Tool # Used \_\_\_\_\_  
 As Found \_\_\_\_\_

Cal. Due Date \_\_\_\_\_

As Assembled \_\_\_\_\_

1st Reading Taking By: \_\_\_\_\_  
 2nd Reading Taking By: \_\_\_\_\_  
 Reviewed By Supervisor: \_\_\_\_\_  
 Verified By Plant REP: \_\_\_\_\_  
 Reviewed By Coordinator: \_\_\_\_\_

# Vibration Data Sheet



Date (m/d/y) 6/19/2006 Turbine Serial No. MLU106 Prepared by

DATE/TIME RPM of MW	Position	#1		#2		#3		#4		#5		#6		#7		#8		#9		#10		#11	
		BRG	DEG																				
6/17/2006 3:16	LS	0.9	299	0.8	122	1.1	65	1.1	40	2.1	285	2.3	161	1.2	8	3.0	128	0.6	188	1.2	10	0.4	215
495 RPM -RunOut	RS	0.9	213	0.8	35	1.3	342	0.9	308	2.5	176	2.3	55	1.5	262	1.9	37	0.6	55	1.2	108	0.4	308
6/18/2006 1:00	LS	1.2	269	1.2	348	3.5	325	4.2	302	5.7	253	4.1	147	2.8	133	1.5	153	1.9	293	1.6	97	2.7	239
43 MW	RS	1.6	180	1.1	287	3.4	238	4.4	215	5.3	143	5.1	62	4.0	51	2.4	137	2.9	241	2.3	51	5.3	288
6/18/2006 2:00	LS	1.3	267	1.1	352	3.2	326	4.1	298	5.6	251	4.0	147	2.8	133	1.4	156	1.9	298	1.6	103	2.8	237
84 MW	RS	1.6	175	1.1	297	3.2	237	4.2	210	5.3	142	5.2	61	4.1	51	2.5	137	2.8	242	2.2	53	5.2	297
6/18/2006 3:45	LS	1.6	253	0.9	19	3.2	322	3.8	298	5.5	254	4.1	156	2.5	147	1.4	150	2.2	305	1.8	116	2.8	241
100 MWV	RS	2.0	168	0.7	348	2.8	238	4.2	200	5.6	141	5.1	70	3.7	62	2.5	139	2.8	255	2.3	68	5.4	296
6/18/2006 5:30	LS	1.2	266	1.2	349	3.4	328	3.9	292	5.6	261	4.4	158	2.8	145	1.6	149	2.1	278	1.7	90	2.5	230
145 MWV	RS	1.4	170	0.8	293	2.8	244	4.4	200	5.8	141	4.5	67	3.2	56	2.3	138	3.2	247	2.7	51	5.3	292
6/18/2006 6:00	LS	1.6	268	0.6	14	2.8	332	4.4	290	5.6	259	4.1	152	2.7	140	1.5	152	1.9	295	1.6	105	2.8	235
220 MWV	RS	1.8	178	0.6	28	2.2	241	4.8	202	5.9	147	4.9	61	3.6	55	2.4	142	2.8	247	2.3	55	5.3	284
6/18/2006 6:25	LS	1.8	265	1.0	11	3.8	325	3.6	302	4.8	256	3.8	150	2.5	133	1.5	156	1.9	297	1.5	117	2.6	238
315 MW	RS	2.5	184	0.7	15	3.5	235	3.8	212	5.2	146	4.8	63	3.5	54	2.5	138	2.6	243	2.1	48	4.9	288
6/18/2006 9:20	LS	1.8	298	2.8	8	2.9	306	4.3	295	4.8	258	3.9	153	2.8	144	1.6	175	2.0	303	1.7	144	4.1	235
435 MWV	RS	1.2	223	2.0	269	3.1	209	4.4	204	4.7	146	5.1	67	4.2	58	3.1	138	2.4	243	1.9	70	6.5	297
6/19/2006 0:00	LS	1.9	281	2.5	7	3.5	321	4.9	288	5.0	260	3.6	153	2.5	141	1.6	162	1.8	307	1.5	125	3.7	242
440 MWV	RS	2.2	205	2.4	292	3.2	225	4.9	200	5.1	151	4.4	68	3.3	60	2.8	142	2.4	241	2.0	56	5.3	302
6/19/2006 3:05	LS	1.9	282	2.8	4	3.5	321	4.9	288	5.2	261	3.5	154	2.4	144	1.7	154	1.9	310	1.6	131	3.4	245
500 MWV	RS	2.2	202	2.5	290	3.2	225	4.9	200	5.4	149	4.3	66	3.4	58	2.7	144	2.6	251	2.0	70	5.3	301
6/19/2006 6:00	LS	1.6	290	2.4	8	3.4	329	4.8	288	5.2	260	3.6	154	2.8	149	1.6	168	1.9	324	1.6	152	3.6	258
600 MWV	RS	2.0	212	2.1	286	3.1	232	4.6	204	4.9	150	4.9	68	4.1	61	2.9	141	2.0	258	1.7	87	5.2	308

**Comments:**

Operations is operating the hydrogen seal oil skid with seal delivery temperatures of 115 F and 145 F to the hydrogen & air sides of the electric generator shaft seal rings, respectively. This condition is thermally twisting the rings in their gland operating groove. This condition is also generating a dampening effect on the vibration mode of the number eleven bearing. Any balance moves for the number eleven bearing would be unpredictable.

**Note:** The Bearing Eleven readings at 435 MW's of 6/18/2006 are with the air/hydrogen seal oil temperature balanced at 130 F, it is expected that hydrogen seal rings have not completely restored their shape yet.



# Vibration Data Sheet

Date(m/d/y)		6/19/2006		Turbine Serial No.		MLU106		Prepared by																
DATE TIME	RPM or MW	Position	#1		#2		#3		#4		#5		#6		#7		#8		#9		#10		#11	
			BRG	DEG	BRG	DEG	BRG	DEG	BRG	DEG	BRG	DEG	BRG	DEG	BRG	DEG	BRG	DEG	BRG	DEG	BRG	DEG	BRG	DEG
6/19/2006	7.59	LS	1.4	279	3.4	346	3.4	312	5.1	290	5.0	260	3.7	154	2.8	148	1.7	175	1.8	338	1.5	222	4.4	268
	733 MW	RS	1.9	200	3.0	270	3.2	215	4.7	208	4.4	150	4.9	67	4.1	60	3.1	136	1.5	238	1.5	36	5.2	319
6/19/2006	10:53	LS	1.5	283	3.6	345	3.0	311	4.7	285	5.0	260	3.6	154	2.5	148	1.8	174	1.6	353	1.6	257	4.9	266
	795 MW	RS	1.8	202	3.2	268	3.6	213	4.5	200	4.7	149	4.6	67	3.6	61	3.3	137	1.4	134	1.4	358	5.4	318
		LS																						
		RS																						
		LS																						
		RS																						
		LS																						
		RS																						
		LS																						
		RS																						
		LS																						
		RS																						

**Comments:**

Operations is operating the hydrogen seal oil skid with seal delivery temperatures of 115 F and 145 F to the hydrogen & air sides of the electric generator shaft seal rings, respectively. This condition is thermally twisting the rings in their gland operating groove. This condition is also generating a dampening effect on the vibration mode of the number eleven bearing. Any balance moves for the number eleven bearing would be unpredictable.

## Main Oil Pump Housing Shim Pattern




Plate ID to be 9 7/8"

Plate OD to be 14"

Bolt Circle centerline is 12 1/2", Twelve holes evenly spaced on this circle

Bolt Holes to be bored to 13/16"

Thirteenth hole to be midpoint of adjacent bolt holes' chord and bored to 13/16"

Split of the ring through the center of the thirteenth hole

Finish of flat faces to be 32 or better

Flat faces to be parallel

Produce these quantities



4 – 0.500" thick

6 – 0.250" thick



6 – 0.100" thick



American Electric	Attachment 15
Mitchell Station Unit #1	Page 222 of 253
Main Oil Pump Bore Readings	
Ohio Power Company	5-29-2006



I




Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_\_

As Found \_\_\_\_\_ Reading Taken By: \_\_\_\_\_ Date: \_\_\_\_\_

As Charted \_\_\_\_\_ Reviewed By (W) Eng.: \_\_\_\_\_ Date: \_\_\_\_\_

CUSTOMER: American Electric Power	
LOCATION/UNIT #: Mitchell #1 / MLU106	
<b>MAIN OIL PUMP OIL SEAL RING CLRS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:



5.498

SEAL NO.	Groove Width	Ring thickness	Axial Clrs	Diametrical Clearance			SHAFT DIA.	MAX. CLR
				A	B	C		
1	0.630	0.623	0.007	5.498	5.498	5.498	5.495	0.003
2	0.630	0.623	0.007	9.208	9.205	9.208	9.202	0.005
3	0.629	0.623	0.006	9.210	9.206	9.210	9.202	0.006
4	0.634	0.623	0.011	5.500	5.499	5.500	5.495	0.005

Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_\_

As Found \_\_\_\_\_

Reading Taken By: \_\_\_\_\_

Date: \_\_\_\_\_


As Assembled \_\_\_\_x\_\_\_\_

Reviewed By (W) Eng.: \_\_\_\_\_

Date: \_\_\_\_\_

# MITCHELL UNIT 1 CONTROL ROTOR


FINAL DIAMETERS



DATE: May 4, 2006  
RECORDED BY: Ron Taylor



American Electric Power	
Mitchell Station Unit #1	
Oil Deflector Bore Readings	
Ohio Power Company	5-29-2006



Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_\_


As Found \_\_\_\_\_

Reading Taken By: \_\_\_\_\_ Date: \_\_\_\_\_

As Charted \_\_\_\_\_

Reviewed By (W) Eng.: \_\_\_\_\_ Date: \_\_\_\_\_

CUSTOMER: <i>American Electric Power / Ohio Power Company</i>	
LOCATION/UNIT #: <i>Mitchell Unit #1 MLU106</i>	
<b>OIL SEAL RING AND SHAFT DIMENSIONS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:



SEAL NO.	LOCATION	A	B	C	AVG SEAL I.D.	ROTOR O.D.	AVE Clearance	Min / Max	Design Clearance
<i>T-1</i>		<i>15.518</i>	<i>15.496</i>	<i>15.501</i>	<i>15.505</i>	<i>15.455</i>	<i>0.050</i>	<i>54/59</i>	<i>0.031</i>
<i>T-3</i>		<i>15.468</i>	<i>15.463</i>	<i>15.468</i>	<i>15.466</i>	<i>15.448</i>	<i>0.018</i>	<i>15/20</i>	<i>0.031</i>
<i>T-4</i>		<i>17.463</i>	<i>17.461</i>	<i>17.466</i>	<i>17.463</i>	<i>17.445</i>	<i>0.018</i>	<i>16/21</i>	<i>0.035</i>
<i>T-11 GVN</i>		<i>9.976</i>	<i>9.976</i>	<i>9.976</i>	<i>9.976</i>	<i>9.958</i>	<i>0.018</i>	<i>18/18</i>	<i>0.020</i>
<i>T-11 GNN</i>		<i>9.976</i>	<i>9.976</i>	<i>9.975</i>	<i>9.976</i>	<i>9.958</i>	<i>0.018</i>	<i>17/18</i>	<i>0.020</i>

Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_\_


As Found \_\_\_\_\_

Reading Taken By: \_\_\_\_\_ Date: \_\_\_\_\_

As Charted \_\_\_\_\_

Reviewed By Turb Coord.: \_\_\_\_\_ Date: \_\_\_\_\_

CUSTOMER: <i>American Electric Power / Ohio Power Company</i>	
LOCATION/UNIT #: <i>Mitchell Unit #1 MLU106</i>	
Tilting Pad Bearing Flood Ring Dimensions	
BB/FRAME:	JOB NO.:
COMPONENT/S. O.:	DWG.:



SEAL NO.	LOCATION	A	B	C	AVG SEAL I.D.	ROTOR O.D.	AVE Clearance	Min / Max	Design Clearance
<i>T-3</i>									
<i>GVN</i>		<i>13.987</i>	<i>13.992</i>	<i>13.992</i>	<i>13.990</i>	<i>13.959</i>	<i>0.031</i>	<i>28/33</i>	<i>0.028</i>
<i>GNN</i>		<i>13.987</i>	<i>13.991</i>	<i>13.991</i>	<i>13.990</i>	<i>13.959</i>	<i>0.031</i>	<i>28/32</i>	<i>0.028</i>
<i>T-4</i>									
<i>GVN</i>		<i>15.991</i>	<i>15.991</i>	<i>15.991</i>	<i>15.991</i>	<i>15.958</i>	<i>0.033</i>	<i>33/33</i>	<i>0.032</i>
<i>GNN</i>		<i>15.992</i>	<i>15.991</i>	<i>15.991</i>	<i>15.991</i>	<i>15.958</i>	<i>0.033</i>	<i>32/33</i>	<i>0.032</i>
<i>T-11</i>									
<i>GVN</i>		<i>9.014</i>	<i>9.012</i>	<i>9.012</i>	<i>9.012</i>	<i>9.000</i>	<i>0.012</i>	<i>12/14</i>	<i>0.018</i>
<i>GNN</i>		<i>9.013</i>	<i>9.011</i>	<i>9.013</i>	<i>9.012</i>	<i>9.000</i>	<i>0.012</i>	<i>11/13</i>	<i>0.018</i>

Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_

As Found \_\_\_\_\_

Reading Taken By: \_\_\_\_\_ Date: \_\_\_\_\_

As Charted \_\_\_\_\_

Reviewed By Turb Coord.: \_\_\_\_\_ Date: \_\_\_\_\_

# Coupling Alignment


## "A" Coupling

Final

Date 06/01/06 Turbine Serial No. MLU106 Prepared by Moore/Hennnen  
 Coupling "A" Sweep Diameter 32" Indicator Mounted on IP

### Alignment Readings

Position	Top	Left	Bottom	Right	Top
Rim (Mils)	0 mils	-2 mils	-4 mils	-2 mils	0 mils
Face 0°	1.275"	1.273"	1.274"	1.273"	
Face 90°	1.271"	1.273"	1.273"	1.272"	
Face 180°	1.272"	1.272"	1.272"	1.273"	
Face 270°	1.269"	1.270"	1.269"	1.270"	
Average	1.272"	1.272"	1.272"	1.272"	
Relative	0 mils	0 mils	0 mils	0 mils	
Check		Face	Rim		
Top + Bottom=		0 mils	-4 mils		
Right + Left =		0 mils	-4 mils		
Difference=		0 mils	0 mils		



### Rim Recheck (If Necessary)

Position	Top	Right	Bottom	Left	Top
Rim (Mils)					

Comments:

Desired Alignment: Rims concentric, faces parallel.

Face readings taken on Male rabbit faces



## Coupling Assembly Checks With Integral Rabbits

Date(m,d,y) 6/3/2006 Turbine Serial No. MLU106 Prepared by Rahn

**NOTES:**

- (1) For radial runout set indicator to read "0" at the number 1 position.
- (2) Mark positions 1-8 to agree with factory stamped degree marks on rotor as shown on Fig. 1.

Coupling A

Data Final  
 (as found/final)





Fig. 1



ST00094

Fig. 2

**Coupling Runouts**

(Readings are in Mils)

Area Indicated		Position Number								
		1 0°	2 45°	3 90°	4 135°	5 180°	6 225°	7 270°	8 315°	1 0°
TE Journal	A	0.0	0.0	-0.5	-0.5	0.0	0.0	0.0	0.5	0.0
TE Cplg. Periphery	B	0.0	-0.5	-0.5	0.0	0.0	1.0	1.0	1.0	0.0
Spacer	C	0.0	-1.0	0.0	0.0	1.0	1.0	2.0	1.5	0.0
GE Cplg. Periphery	D	0.0	0.0	0.0	0.0	0.0	-1.0	0.0	0.0	0.0
GE Journal	E	0.0	0.0	0.0	0.0	0.0	-1.0	0.0	0.0	0.0

**Differential Runouts**

Journals	A-E	0.0	0.0	0.5	0.5	0.0	1.0	0.0	0.5	0.0
Cplg. Periphery	B-D	0.0	0.5	0.5	0.0	0.0	2.0	1.0	1.0	0.0
Spacer to Cplg	C-B	0.0	0.5	0.5	0.0	1.0	0.0	1.0	0.5	0.0
Spacer to Cplg	C-D	0.0	1.0	0.0	0.0	1.0	2.0	2.0	1.5	0.0

**Maximum Runouts**

Area Indicated	Data Check	TIR Runout	TIR Check	
TE Journal	A	OK	1.0	OK
TE Cplg. Periphery	B	OK	1.5	OK
Spacer	C	OK	3.0	OK
GE Cplg. Periphery	D	OK	1.0	OK
GE Journal	E	OK	1.0	OK

**Maximum Differential Runouts**

		Max. Diff.	Diff. Check
Journals	A-E	1.0	OK
Cplg. Periphery	B-D	2.0	Check
Spacer to Cplg	C-B	1.0	OK
Spacer to Cplg	C-D	2.0	OK



## Coupling Assembly Checks With Integral Rabbets

Date(m,d,y) 6/1/2006 Turbine Serial No. MLU106 Prepared by Courtright

**NOTES:**

- (1) For radial runout set indicator to read "0" at the number 1 position.
- (2) Mark positions 1-8 to agree with factory stamped degree marks on rotor as shown on Fig. 1.

Coupling

Data   
 (as found/final)





Fig. 1



ST00094

Fig. 2

**Coupling Runouts**

(Readings are in Mils)

Area Indicated		Position Number									
		1 0°	2 45°	3 90°	4 135°	5 180°	6 225°	7 270°	8 315°	1 0°	
TE Journal	A	0.0	0.0	1.0	0.0	1.0	1.0	0.0	0.0	0.0	
TE Cplg. Periphery	B	0.0	0.0	0.0	0.0	0.0	0.0	0.0	-0.5	0.0	
Spacer	C										
GE Cplg. Periphery	D	0.0	0.0	0.0	-1.0	-1.0	-1.0	-1.0	-0.5	-0.5	
GE Journal	E	0.0	0.0	2.0	1.0	0.0	0.0	-1.0	-0.5	0.0	

**Differential Runouts**

Journals	A-E	0.0	0.0	1.0	1.0	1.0	1.0	1.0	0.5	0.0
Cplg. Periphery	B-D	0.0	0.0	0.0	1.0	1.0	1.0	1.0	0.0	0.5
Spacer to Cplg	C-B									
Spacer to Cplg	C-D	0.0	0.0	0.0	1.0	1.0	1.0	1.0	0.5	0.5

**Maximum Runouts**

Area Indicated	Data Check	TIR Runout	TIR Check	
TE Journal	A	OK	1.0	OK
TE Cplg. Periphery	B	OK	0.5	OK
Spacer	C			
GE Cplg. Periphery	D	Check	1.0	OK
GE Journal	E	OK	3.0	Check

**Maximum Differential Runouts**

	Max. Diff.	Diff. Check	
Journals	A-E	1.0	OK
Cplg. Periphery	B-D	1.0	OK
Spacer to Cplg	C-B		
Spacer to Cplg	C-D	1.0	OK

# Coupling Alignment


## "C" Coupling

Date 05/28/06 Turbine Serial No. MLU106 Prepared by Vickers

Coupling "C" Sweep Diameter \_\_\_\_\_ Indicator Mounted on IP

### Alignment Readings

Position	Top	Left	Bottom	Right	Top
Rim (Mils)	0 mils	-6 mils	-13 mils	-5 mils	0 mils
Face 0°	1.042"	1.042"	1.043"	1.043"	
Face 90°	1.046"	1.045"	1.047"	1.047"	
Face 180°	1.046"	1.049"	1.051"	1.048"	
Face 270°	1.051"	1.052"	1.052"	1.051"	
Average	1.046"	1.047"	1.048"	1.047"	
Relative	0 mils	1 mils	2 mils	1 mils	
Check		Face	Rim		
Top + Bottom =		2 mils	-13 mils		
Right + Left =		2 mils	-11 mils		
Difference =		0 mils	-2 mils		



### Rim Recheck (If Necessary)

Position	Top	Right	Bottom	Left	Top
Rim (Mils)					

Comments:

Desired Alignment: IP .007" low to LP centerline, face open .004" on bottom.

Face readings taking inside coupling bolt diameter



## Coupling Assembly Checks With Integral Rabbits

Date(m,d,y) 6/1/2006 Turbine Serial No. MLU106 Prepared by Courtright

**NOTES:**

- (1) For radial runout set indicator to read "0" at the number 1 position.
- (2) Mark positions 1-8 to agree with factory stamped degree marks on rotor as shown on Fig. 1.

Coupling

Data   
 (as found/final)




Fig. 1




Fig. 2

ST00094

**Coupling Runouts**

(Readings are in Mils)

Area Indicated		Position Number								
		1 0°	2 45°	3 90°	4 135°	5 180°	6 225°	7 270°	8 315°	1 0°
TE Journal	A	0.0	0.0	0.0	0.0	1.0	1.0	0.5	0.0	0.0
TE Cplg. Periphery	B	0.0	0.0	0.0	-2.0	-4.0	-4.0	-3.5	-1.5	0.0
Spacer	C	0.0	1.0	2.0	-1.0	-2.0	-4.0	-4.0	-2.0	0.0
GE Cplg. Periphery	D	0.0	1.0	2.5	0.0	-1.0	-2.5	-2.5	-1.5	0.0
GE Journal	E	0.0	1.0	2.0	1.5	1.0	0.0	-0.5	-0.5	0.0

**Differential Runouts**

Journals	A-E	0.0	1.0	2.0	1.5	0.0	1.0	1.0	0.5	0.0
Cplg. Periphery	B-D	0.0	1.0	2.5	2.0	3.0	1.5	1.0	0.0	0.0
Spacer to Cplg	C-B	0.0	1.0	2.0	1.0	2.0	0.0	0.5	0.5	0.0
Spacer to Cplg	C-D	0.0	0.0	0.5	1.0	1.0	1.5	1.5	0.5	0.0

**Maximum Runouts**

Area Indicated	Data Check	TIR Runout	TIR Check	
TE Journal	A	OK	1.0	OK
TE Cplg. Periphery	B	OK	4.0	Check
Spacer	C	OK	6.0	Check
GE Cplg. Periphery	D	OK	5.0	Check
GE Journal	E	OK	2.5	Check

**Maximum Differential Runouts**

		Max. Diff.	Diff. Check
Journals	A-E	2.0	Check
Cplg. Periphery	B-D	3.0	Check
Spacer to Cplg	C-B	2.0	OK
Spacer to Cplg	C-D	1.5	OK

# Coupling Inspection

Date(m/d/y) \_\_\_\_\_ Turbine Serial No. 13A3161-1 Prepared by Unger  
 Rotor Identification \_\_\_\_\_ Coupling Spacers  
 (Turbine End or Generator End)

INSPECTIONS & CHECKS		CODE
Bolt Covers & Screws	Coupling Runouts	<b>X</b> Work Carried Out
Lockplates	Bolt Extension Measurements	<b>N</b> Not Done
Coupling Bolts/Studs		<b>NA</b> Not Applicable
Coupling Mating Surface		<b>C</b> See Comments
Rabbet		<b>V</b> Visual Inspection
Dimensional Checks		<b>MP</b> Mag. Particle
Coupling Flatness		<b>UT</b> Ultrasonic
		<b>PT</b> Penetrant




Fig. 1




Fig. 2

ST00100a

**NOTES:**

**COUPLING DIMENSIONAL CHECKS** Readings in Inches


		Position Number				Male Fit	Clrc
		1 0°	2 45°	3 90°	4 135°		
1.403" tk	GNN "A" Spacer (B)	20.001	20.001	20.001	20.001	20.000	0.001
1.403" tk	GNN "A" Spacer (B)	19.997	19.997	19.997	19.997	19.996	0.001
1.211" tk	GNN "C" Spacer (B)	22.001	22.001	22.001	22.001	22.000	0.001
1.211" tk	GNN "C" Spacer (B)	21.996	21.996	21.996	21.996	21.995	0.001

Measurements after from CMS to size Female Fits

<b>Comments:</b>	

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>GOVERNOR VALVE DIMENSIONS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

Valve #   1  



New Disc & Nut

NO. <u>  1  </u> VALVE DATA (AS FOUND)				Design Clear.	Service allowed	NO. <u>  1  </u> VALVE DATA (AS LEFT)			
DIM.	O.D.	I.D.	CLR			DIM.	O.D.	I.D.	CLR
A	1.736	1.752	0.016	.010/.012	.009/.018	A	1.736	1.752	0.016
B	1.736	1.751	0.015			B	1.736	1.751	0.015
C	4.174	4.183	0.009	.010/.012	.009/.018	C	4.174	4.183	0.009
D	4.168	4.186	0.018			D	4.175	4.185	0.010
E	5.580	5.583	0.003	.001/.003	.001/.015	E	5.577	5.583	0.006
F	5.579	5.593	0.014			F	5.572	5.593	0.021
STEM RUNOUT =			0.001	.001/.003	.004	STEM RUNOUT =			0.001
DIMENSION L =			0.176			DIMENSION L =			0.134

Tool # Used \_\_\_\_\_


Cal. Due Date \_\_\_\_\_

As Found  Reading Taken By: Bordenkircher/Messerschmidt Date: \_\_\_\_\_

As Assembled  Reviewed By: Powell Date: 5/16/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>GOVERNOR VALVE DIMENSIONS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

Valve #   2  



NO. <u>  2  </u> VALVE DATA (AS FOUND)				Design Clear.	Service allowed	NO. <u>  2  </u> VALVE DATA (AS LEFT)			
DIM.	O.D.	I.D.	CLR			DIM.	O.D.	I.D.	CLR
A	1.738	1.755	0.017	.010/.012	.009/.018	A	1.738	1.755	0.017
B	1.739	1.749	0.01	.010/.012	.009/.018	B	1.739	1.750	0.011
C	4.177	4.185	0.008	.010/.012	.009/.018	C	4.177	4.185	0.008
D	4.177	4.186	0.009	.010/.012	.009/.018	D	4.177	4.186	0.009
E	5.790			.001/.003	.001/.015	E	5.576	5.589	0.013
F	5.578			.001/.003	.001/.015	F	5.574	5.597	0.023
STEM RUNOUT =			0.002	.001/.003	.004	STEM RUNOUT =			0.002
DIMENSION L =			0.183	.115/.135	.115/.135	DIMENSION L =			0.183

Tool # Used \_\_\_\_\_


Cal. Due Date \_\_\_\_\_

As Found  Reading Taken By: Bordenkircher/Messerschmidt Date: \_\_\_\_\_

As Assembled  Reviewed By: Powell Date: 5/16/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>GOVERNOR VALVE DIMENSIONS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

Valve #   3  



New Stem, Plug & Nut

NO. <u>  3  </u> VALVE DATA (AS FOUND)				Design Clear.	Service allowed	NO. <u>  3  </u> VALVE DATA (AS LEFT)			
DIM.	O.D.	I.D.	CLR			DIM.	O.D.	I.D.	CLR
A	1.738	1.751	0.013	.010/.012	.009/.018	A	1.737	1.751	0.014
B	1.734	1.750	0.016	.010/.012	.009/.018	B	1.737	1.750	0.013
C	4.173	4.184	0.011	.010/.012	.009/.018	C	4.174	4.184	0.010
D	4.169	4.187	0.018	.010/.012	.009/.018	D	4.174	4.188	0.014
E	5.583	5.586	0.003	.001/.003	.001/.015	E	5.576	5.586	0.010
F	5.583	5.586	0.003	.001/.003	.001/.015	F	5.577	5.595	0.018
STEM RUNOUT =			0.002	.001/.003	.004	STEM RUNOUT =			0.001
DIMENSION L =			0.218	.115/.135	.115/.135	DIMENSION L =			0.172

Tool # Used \_\_\_\_\_


Cal. Due Date \_\_\_\_\_

As Found  Reading Taken By: Bordenkircher/Messerschmidt Date: \_\_\_\_\_

As Assembled  Reviewed By: Powell Date: 5/16/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>GOVERNOR VALVE DIMENSIONS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

Valve #   4  



NO. <u>  4  </u> VALVE DATA (AS FOUND)				Design Clear.	Service allowed	NO. <u>  4  </u> VALVE DATA (AS LEFT)			
DIM.	O.D.	I.D.	CLR			DIM.	O.D.	I.D.	CLR
A	1.735	1.768	0.033	.010/.012	.009/.018	A	1.735	1.768	0.033
B	1.736	1.710	-0.026	.010/.012	.009/.018	B	1.736	1.752	0.016
C	4.173	4.185	0.012	.010/.012	.009/.018	C	4.173	4.190	0.017
D	4.170	4.187	0.017	.010/.012	.009/.018	D	4.170	4.191	0.021
E	5.566			.001/.003	.001/.015	E	5.573	5.577	0.004
F	5.545			.001/.003	.001/.015	F	5.570	5.593	0.023
STEM RUNOUT =		0.000		.001/.003	.004	STEM RUNOUT =		0.000	
DIMENSION L =		0.180		.115/.135	.115/.135	DIMENSION L =		0.172	

Tool # Used \_\_\_\_\_


Cal. Due Date \_\_\_\_\_

As Found  Reading Taken By: Bordenkircher/Messerschmidt Date: \_\_\_\_\_

As Assembled  Reviewed By: Powell Date: 5/16/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>GOVERNOR VALVE DIMENSIONS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

Valve #   5  



NO. <u>  5  </u> VALVE DATA (AS FOUND)				Design Clear.	Service allowed	NO. <u>  5  </u> VALVE DATA (AS LEFT)			
DIM.	O.D.	I.D.	CLR			DIM.	O.D.	I.D.	CLR
A	1.737	1.752	0.015	.010/.012	.009/.018	A	1.737	1.752	0.015
B	1.737	1.751	0.014	.010/.012	.009/.018	B	1.737	1.751	0.014
C	4.175	4.183	0.008	.010/.012	.009/.018	C	4.175	4.183	0.008
D	4.171	4.185	0.014	.010/.012	.009/.018	D	4.171	4.185	0.014
E	5.582	5.589	0.007	.001/.003	.001/.015	E	5.580	5.589	0.009
F	5.582	5.603	0.021	.001/.003	.001/.015	F	5.577	5.603	0.026
STEM RUNOUT =			0.000	.001/.003	.004	STEM RUNOUT =			0.000
DIMENSION L =			0.162	.115/.135	.115/.135	DIMENSION L =			0.162

Tool # Used \_\_\_\_\_


Cal. Due Date \_\_\_\_\_

As Found  Reading Taken By: Bordenkircher/Messerschmidt Date: \_\_\_\_\_

As Assembled  Reviewed By: Powell Date: 5/16/06

CUSTOMER:	AEP
LOCATION/UNIT#:	
<b>GOVERNOR VALVE DIMENSIONS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

Valve # 6



NO. <u>6</u> VALVE DATA (AS FOUND)				Design Clear.	Service allowed	NO. <u>6</u> VALVE DATA (AS LEFT)			
DIM.	O.D.	I.D.	CLR			DIM.	O.D.	I.D.	CLR
A				.010/.012	.009/.018	A	1.737	1.752	0.015
B				.010/.012	.009/.018	B	1.737	1.753	0.016
C				.010/.012	.009/.018	C	4.175	4.184	0.009
D				.010/.012	.009/.018	D	4.175	4.187	0.012
E				.001/.003	.001/.015	E	5.578	5.585	0.007
F				.001/.003	.001/.015	F	5.579	5.596	0.017
STEM RUNOUT =				.001/.003	.004	STEM RUNOUT =			0.002
DIMENSION L =				.115/.135	.115/.135	DIMENSION L =			0.143

Tool # Used \_\_\_\_\_


Cal. Due Date \_\_\_\_\_

As Found  Reading Taken By: Bordenkircher/Messerschmidt Date: \_\_\_\_\_

As Assembled  Reviewed By: Powell Date: 5/16/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>GOVERNOR VALVE DIMENSIONS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

Valve #   7  



New Stem, Plug & Nut

NO. <u>  7  </u> VALVE DATA (AS FOUND)				Design Clear.	Service allowed	NO. <u>  7  </u> VALVE DATA (AS LEFT)			
DIM.	O.D.	I.D.	CLR			DIM.	O.D.	I.D.	CLR
A		1.755		.010/.012	.009/.018	A	1.738	1.755	0.017
B		1.752		.010/.012	.009/.018	B	1.738	1.752	0.014
C		4.186		.010/.012	.009/.018	C	4.172	4.186	0.014
D		4.187		.010/.012	.009/.018	D	4.172	4.187	0.015
E	5.585	5.588	0.003	.001/.003	.001/.015	E	5.580	5.588	0.008
F	5.583	5.607	0.024	.001/.003	.001/.015	F	5.580	5.607	0.027
STEM RUNOUT =				.001/.003	.004	STEM RUNOUT =			0.002
DIMENSION L =				.115/.135	.115/.135	DIMENSION L =			0.142

Tool # Used \_\_\_\_\_


Cal. Due Date \_\_\_\_\_

As Found  Reading Taken By: Bordenkircher/Messerschmidt Date: \_\_\_\_\_

As Assembled  Reviewed By: Powell Date: 5/16/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>GOVERNOR VALVE DIMENSIONS</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S. O.:	DWG.:

Valve #   8  



NO. <u>  8  </u> VALVE DATA (AS FOUND)			
DIM.	O.D.	I.D.	CLR
A	1.737	1.750	0.013
B	1.737	1.753	0.016
C	4.174	4.185	0.011
D	4.172	4.183	0.011
E	5.583		
F	5.584		
STEM RUNOUT =		0.001	
DIMENSION L =		0.171	

Design Clear.	Service allowed
.010/.012	.009/.018
.010/.012	.009/.018
.010/.012	.009/.018
.010/.012	.009/.018
.001/.003	.001/.015
.001/.003	.001/.015
.001/.003	.004
.115/.135	.115/.135

NO. <u>  8  </u> VALVE DATA (AS LEFT)			
DIM.	O.D.	I.D.	CLR
A	1.737	1.750	0.013
B	1.737	1.753	0.016
C	4.174	4.185	0.011
D	4.172	4.183	0.011
E	5.572	5.586	0.014
F	5.576	5.595	0.019
STEM RUNOUT =		0.001	
DIMENSION L =		0.171	

Tool # Used \_\_\_\_\_


Cal. Due Date \_\_\_\_\_

As Found  Reading Taken By: Bordenkircher/Messerschmidt Date: \_\_\_\_\_

As Assembled  Reviewed By: Powell Date: 5/16/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>THROTTLE VALVE</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

LOCATION : \_\_\_\_\_ #1 \_\_\_\_\_



As Found Throttle Valve Clearances				
DIA	O.D.	I.D.	ACTUAL	DESIGN
A	2.111	2.124	0.013	.010/.013
B	2.111	2.125	0.014	.010/.013
C	1.381	1.393	0.012	.005/.007
D	1.487	1.499	0.012	.010/.013
E	1.487	1.498	0.011	.010/.013
F	5.491	5.494	0.003	.011/.017
G	1.930	1.935	0.005	.010/.013
H	3.806	3.808	0.002	.002/.005
I = RUNOUT				0/.003

As Assembled Throttle Valve Clearances				
DIA	O.D.	I.D.	ACTUAL	DESIGN
A	2.110	2.125	0.015	.010/.013
B	2.110	2.125	0.015	.010/.013
C	1.381	1.392	0.011	.005/.007
D	1.487	1.501	0.014	.010/.013
E	1.487	1.497	0.010	.010/.013
F	5.487	5.497	0.010	.011/.017
G	1.924	1.935	0.011	.010/.013
H	3.805	3.808	0.003	.002/.005
I = RUNOUT				0/.003

Tool # Used \_\_\_\_\_ Cal. Due Date \_\_\_\_\_


As Found Reading Taken By: Burnheimer/VanDyke Date: 4/12/06

As Assembled Reading Taken By: Burnheimer/VanDyke Date: 4/24/06

Reviewed By Turbine Coordinator: Powell Date: 5/13/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>THROTTLE VALVE</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

LOCATION : \_\_\_\_\_ #2 \_\_\_\_\_



As Found Throttle Valve Clearances				
DIA	O.D.	I.D.	ACTUAL	DESIGN
A	2.109	2.124	0.015	.010/.013
B	2.110	2.124	0.014	.010/.013
C	1.382	1.391	0.009	.005/.007
D	1.481	1.501	0.020	.010/.013
E	1.482	1.497	0.015	.010/.013
F	5.471	5.486	0.015	.011/.017
G	1.926	1.935	0.009	.010/.013
H	3.803	3.808	0.005	.002/.005
I = RUNOUT				0/.003

As Assembled Throttle Valve Clearances				
DIA	O.D.	I.D.	ACTUAL	DESIGN
A	2.110	2.124	0.014	.010/.013
B	2.110	2.124	0.014	.010/.013
C	1.381	1.391	0.010	.005/.007
D	1.488	1.501	0.013	.010/.013
E	1.488	1.498	0.010	.010/.013
F	5.482	5.494	0.012	.011/.017
G	1.924	1.934	0.010	.010/.013
H	3.806	3.808	0.002	.002/.005
I = RUNOUT				0/.003

Tool # Used \_\_\_\_\_ Cal. Due Date \_\_\_\_\_


As Found Reading Taken By: \_Burnheimer/VanDyke\_\_\_\_\_ Date: \_4/12/06\_\_\_\_\_

As Assembled Reading Taken By: \_Burnheimer/VanDyke\_\_\_\_\_ Date: \_4/24/06\_\_\_\_\_

Reviewed By Turbine Coordinator: \_\_Powell\_\_\_\_\_ Date: \_5/13/06\_\_\_\_\_

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>THROTTLE VALVE</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

LOCATION : \_\_\_\_\_ #3 \_\_\_\_\_



As Found Throttle Valve Clearances				
DIA	O.D.	I.D.	ACTUAL	DESIGN
A	2.114	2.125	0.011	.010/.013
B	2.115	2.124	0.009	.010/.013
C	1.380	1.387	0.007	.005/.007
D	1.485	1.496	0.011	.010/.013
E	1.486	1.497	0.011	.010/.013
F	5.476	5.490	0.014	.011/.017
G	1.926	1.936	0.010	.010/.013
H	3.806	3.809	0.003	.002/.005
I = RUNOUT				0/.003

As Assembled Throttle Valve Clearances				
DIA	O.D.	I.D.	ACTUAL	DESIGN
A	2.113	2.125	0.012	.010/.013
B	2.114	2.124	0.010	.010/.013
C	1.380	1.388	0.008	.005/.007
D	1.487	1.496	0.009	.010/.013
E	1.487	1.497	0.010	.010/.013
F	5.470	5.490	0.020	.011/.017
G	1.926	1.936	0.010	.010/.013
H	3.805	3.809	0.004	.002/.005
I = RUNOUT				0/.003

Tool # Used \_\_\_\_\_ Cal. Due Date \_\_\_\_\_


As Found Reading Taken By: \_Burnheimer/VanDyke\_\_\_\_\_ Date: \_4/12/06\_\_\_\_\_

As Assembled Reading Taken By: \_Burnheimer/VanDyke\_\_\_\_\_ Date: \_4/24/06\_\_\_\_\_

Reviewed By Turbine Coordinator: \_Powell\_\_\_\_\_ Date: \_5/13/06\_\_\_\_\_

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>THROTTLE VALVE</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:

LOCATION : \_\_\_\_\_ #4 \_\_\_\_\_



As Found Throttle Valve Clearances				
DIA	O.D.	I.D.	ACTUAL	DESIGN
A	2.111	2.125	0.014	.010/.013
B	2.111	2.124	0.013	.010/.013
C	1.381	1.393	0.012	.005/.007
D	1.487	1.498	0.011	.010/.013
E	1.488	1.498	0.01	.010/.013
F	5.482	5.489	0.007	.011/.017
G	1.929	1.935	0.006	.010/.013
H	3.802	3.806	0.004	.002/.005
I = RUNOUT				0/.003

As Assembled Throttle Valve Clearances				
DIA	O.D.	I.D.	ACTUAL	DESIGN
A	2.110	2.125	0.015	.010/.013
B	2.110	2.124	0.014	.010/.013
C	1.382	1.387	0.005	.005/.007
D	1.487	1.498	0.011	.010/.013
E	1.488	1.498	0.010	.010/.013
F	5.486	5.497	0.011	.011/.017
G	1.924	1.935	0.011	.010/.013
H	3.808	3.809	0.001	.002/.005
I = RUNOUT				0/.003

Tool # Used \_\_\_\_\_


Cal. Due Date \_\_\_\_\_

As Found Reading Taken By: \_Burnheimer/VanDyke\_\_\_\_\_ Date: \_4/12/06\_\_\_\_\_

As Assembled Reading Taken By: \_Burnheimer/VanDyke\_\_\_\_\_ Date: \_4/24/06\_\_\_\_\_

Reviewed By Turbine Coordinator: \_Powell\_\_\_\_\_ Date: \_5/13/06\_\_\_\_\_

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>THROTTLE VALVE</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:



AXIAL TRAVEL			
NUMBER	DESCRIPTION		DISTANCE
1	A2 SPRING GUIDE SEATED		0.463
2	A1 SPRING GUIDE NOT SEATED		0.626
3	STEM BACKSEATED		1.167
4	MAIN VALVE BACKSEATED		5.482
CALCULATED VALUES			
	DESCRIPTION	DISTANCE CALCULATION	VALUE
	PILOT SPRING COMPRESSION	#2 MINUS #1	0.163
	PILOT TRAVEL	#3 MINUS #2	0.541
	MAIN VALVE TRAVEL	#4 MINUS #3	4.315
	TOTAL TRAVEL	#4 MINUS #2	4.856

Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_\_


As Found \_\_\_\_\_

Reading Taken By: Henning Date: 5/17/06

As Assembled  \_\_\_\_\_

Reviewed By Turb Coord: Powell Date: 5/17/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>THROTTLE VALVE</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:



AXIAL TRAVEL			
NUMBER	DESCRIPTION		DISTANCE
1	A2 SPRING GUIDE SEATED		0.553
2	A1 SPRING GUIDE NOT SEATED		0.705
3	STEM BACKSEATED		1.221
4	MAIN VALVE BACKSEATED		5.434
CALCULATED VALUES			
	DESCRIPTION	DISTANCE CALCULATION	VALUE
	PILOT SPRING COMPRESSION	#2 MINUS #1	0.152
	PILOT TRAVEL	#3 MINUS #2	0.516
	MAIN VALVE TRAVEL	#4 MINUS #3	4.213
	TOTAL TRAVEL	#4 MINUS #2	4.729

Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_\_


As Found \_\_\_\_\_

Reading Taken By: Burnheimer Date: 5/17/06

As Assembled  \_\_\_\_\_

Reviewed By Turb Coord: Powell Date: 5/17/06

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>THROTTLE VALVE</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:



AXIAL TRAVEL			
NUMBER	DESCRIPTION		DISTANCE
1	A2 SPRING GUIDE SEATED		0.686
2	A1 SPRING GUIDE NOT SEATED		0.849
3	STEM BACKSEATED		1.361
4	MAIN VALVE BACKSEATED		5.436
CALCULATED VALUES			
	DESCRIPTION	DISTANCE CALCULATION	VALUE
	PILOT SPRING COMPRESSION	#2 MINUS #1	0.163
	PILOT TRAVEL	#3 MINUS #2	0.512
	MAIN VALVE TRAVEL	#4 MINUS #3	4.075
	TOTAL TRAVEL	#4 MINUS #2	4.587


Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_\_

As Found \_\_\_\_\_ Reading Taken By: Burnheimer Date: 5/16/06

As Assembled X Reviewed By Turb Coord: \_\_\_\_\_ Date: \_\_\_\_\_

CUSTOMER:	AEP
LOCATION/UNIT #:	
<b>THROTTLE VALVE</b>	
BB/FRAME:	JOB NO.:
COMPONENT/S.O.:	DWG.:



AXIAL TRAVEL			
NUMBER	DESCRIPTION		DISTANCE
1	A2 SPRING GUIDE SEATED		0.505
2	A1 SPRING GUIDE NOT SEATED		0.640
3	STEM BACKSEATED		1.150
4	MAIN VALVE BACKSEATED		5.405
CALCULATED VALUES			
	DESCRIPTION	DISTANCE CALCULATION	VALUE
	PILOT SPRING COMPRESSION	#2 MINUS #1	0.135
	PILOT TRAVEL	#3 MINUS #2	0.510
	MAIN VALVE TRAVEL	#4 MINUS #3	4.255
	TOTAL TRAVEL	#4 MINUS #2	4.765

Tool # Used \_\_\_\_\_

Cal. Due Date \_\_\_\_\_

As Found \_\_\_\_\_

Reading Taken By: Bordenkircher Date: 5/13/06

As Assembled  \_\_\_\_\_

Reviewed By Turb Coord: Powell Date: 5/13/06


## Alignment Couplings

Date 5/8/2006 Turbine Serial No. MLU1 Prepared by Bordenkircher

Coupling BFP Sweep Diameter \_\_\_\_\_ Indicator Mounted on Turb

### Alignment Readings

Position	Top	Left	Bottom	Right	Top
Rim (Mils)	0 mils	8 mils	15 mils	7 mils	
Face 0°	0.945"	0.945"	0.947"	0.949"	
Face 90°	0.947"	0.945"	0.947"	0.948"	
Face 180°	0.931"	0.932"	0.932"	0.932"	
Face 270°	0.930"	0.931"	0.933"	0.931"	
Average	0.938"	0.938"	0.940"	0.940"	
Relative	0 mils	0 mils	2 mils	2 mils	



Check	Face	Rim
Top + Bottom =	2 mils	15 mils
Right + Left =	2 mils	15 mils
Difference =	0 mils	0 mils

### Rim Recheck (If Necessary)

Position	Top	Left	Bottom	Right	Top
Rim (Mils)					

Comments:	
Design - Turbine 7 mils high to pump, 14 mils TIR	