



ENGINEERED PUMP SERVICES, INC.

624 Perkins Drive ! Mukwonago, WI 53149-1454
(262)363-9002 ! (800)657-0845 ! fax (262)363-9013
www.epspumps.com ! email: eps@epspumps.com


INSPECTION REPORT

CUSTOMER	: East Kentucky Power Cooperative	REPORT DATE	: 12/17/21
PLANT NAME	: Spurlock Generating Station	REPORT NO.	: 56743-IR1
CITY/STATE	: Maysville, Kentucky	CUST. ORDER	: TBD
EQUIPMENT	: 29" APKD - 4	COPY	: Anthony Ring
SERVICE	: Condensate Water	FILE	: 56743
MANF.	: Ingersoll-Rand	PAGE	: 1 of 4 Pages
SERIAL NO.	: Unit #2		

The subject pump element was sent to EPS as part of a planned overhaul in fall 2021. The scope of this overhaul was to use an existing (repaired) pump element and match it to the upper components of a complete pump assembly needing overhaul. The lower element removed from that complete pump is the subject of this inspection report. The pump element was completely dismantled and glass bead blasted clean with the exception of the shafts which were only hand cleaned. The pump element was then visually and dimensionally inspected; furthermore, the impellers and shafting were submitted for non destructive testing. The results of the inspection are discussed in detail below and are listed by part name. Please see the attached inspection data sheets for the as-found dimensions, fits, and clearances.

Overall Condition – The pump has the typical light to moderate wear seen on condensate pumps that have been in service for a long period of time. Typically speaking, the impeller to case ring clearances and bearing to shaft journal sleeve clearances are all moderately excessive. As mentioned in the paragraphs below, the shaft to impeller clearances and most of the casing fits are marginally loose which might account for some of the higher running clearances measured. The impellers are in overall good condition, and there was no significant amount of cavitation damage.

Pump Shaft – All of the impeller and bearing journal sleeve fits measure consistently to a uniform diameter; however, the impeller to shaft fit clearances are all marginally excessive. The total indicated runout (TIR) of the shaft is .005" which is marginal for a condensate pump application. The coupling sleeve was very difficult to remove and had to be cut at disassembly. The underlying shaft turn was moderately galled as a result. Ultrasonic and magnetic particle testing did not reveal any linear indications of damage.

BY: 
Aaron Stull

INSPECTION REPORT

CUSTOMER : EKPC - Spurlock
REPORT NO. : 56743-IR1

REPORT DATE : 12/17/21
PAGE NO. : 2 of 4

Upper Shaft – The upper shaft body measures consistently to a uniform diameter across all coupling and journal sleeve fits. The total indicated runout (TIR) of the shaft is .005” which is marginal for this application. There is a small area of deep wear at the top of the shaft caused by contact with the floating seal ring of the mechanical seal assembly. Ultrasonic and magnetic particle testing did not reveal any linear indications of damage.

Impeller Split Retaining Rings – Overall, the retaining rings are in good condition with minor tool damage at the parting line and light working damage on the axial mounting faces. Dimensionally, all the rings measure to a uniform thickness with appropriate axial clearance to the shaft grooves.

Impellers – Generally speaking, the impellers are in fair dimensional and good visual condition. As mentioned above, the fit clearances to the shaft are all marginally excessive. All of the impeller sealing turns are integral to the impeller (no wear rings) and only have very light visible grooving and wear; the resulting running clearances to the case ring are all moderately excessive. As mentioned previously, the 1st stage impeller has only minor cavitation on the vanes and vane fillets. All impellers had multiple linear indications when magnetic particle NDE tested.

Journal Sleeves – The (8) shaft sleeves are in fair condition with light to moderate eccentric radial wear on the outer diameters; as mentioned previously, the resulting running clearances to the graphite bearings are all moderately excessive. The fit bores to the shaft all measure to expected design diameters with appropriate fit clearances to the shaft.

Impeller Keys – With a couple of exceptions, all of the impeller keys are in good visual condition. Typically speaking, the key widths are moderately undersized resulting in a loose fit to the shaft.

Suction Bell – Overall, the suction bell is in fair condition. The wear ring and tail bearing show light visible wear, and the resulting running clearances are moderately oversized. There is minor cavitation damage on the inlet suction faces and some unusual cavitation in the lower bearing. The male fit turn to the 1st casing section measures over the existing diameter with the resulting fit actually measuring as interference instead of light clearance. There does not to be any galling or lack of sealing resulting from this tight fit.

First Stage Casing – The first stage casing is in overall good visual condition. The fit clearances to the mating series casing and suction bell are marginally excessive. The bearing bore has moderate wear resulting in excessive fit clearance to the journal sleeve. The suction inlet guide for to the 1st stage impeller has minor cavitation damage. Both case wear rings are lightly worn with excessive running clearances to the impellers.

INSPECTION REPORT

CUSTOMER : EKPC-Spurlock
REPORT NO. : 56743-IR1

REPORT DATE : 12/17/21
PAGE NO. : 3 of 4

Series Casing – The (2) series stage casings are in fair visual condition. Both stages have little or no vane damage and negligible corrosion. The fit clearances between all stages are marginally out of tolerance. Both bearing bores have moderate wear resulting in excessive fit clearance to the journal sleeves. Both case rings are lightly worn with excessive running clearances to the impellers.

Upper Casing – The upper casing is in good visual condition with little or no vane damage and negligible corrosion. The fit turn to the lower column measures to the expected design diameter. The bearing bore has moderate wear resulting in excessive fit clearance to the journal sleeve.

Hardware – Generally speaking, the hardware is in fair condition although some studs have worn or rolled threads.



Photo 1: Pump As Received




Photo 2: Seal Ring Wear On Upper Shaft




Photo 3: Shaft Galls At 1st Stage Impeller Nut



Photo 4: Typical Case Ring Wear

INSPECTION REPORT

CUSTOMER : EKPC-Spurlock
REPORT NO. : 56743-IR1

REPORT DATE : 12/17/21
PAGE NO. : 4 of 4




Photo 5: Typical Cavitation On 1st Stage Impeller




Photo 6: Typical Cavitation On 1st Stage Impeller



Photo 7: Typical Wear On Series Bearing



Photo 8: Cavitation Damage On Suction Bearing




Photo 9: Typical Wear On Series Shaft Sleeves



Photo 10: Wear On Suction Shaft Sleeve

EPS JOB #	56743	CUSTOMER	EAST KENTUCKY POWER
PO #		PLANT	SPURLOCK
INSP. BY	ACS	SERIAL #	UNIT #2
DATE	12/17/21		




RUNNING CLR.		STAGE 1	STAGE 2	STAGE 3	STAGE 4				
A	BEARING BORE	2.507	2.511						
B	SLEEVE TURN	2.490	2.500						
	CLR.	0.007	0.021						
C	BEARING BORE	4.780	4.790						
D	SLEEVE TURN	4.742	4.750						
	CLR.	0.030	0.048						
E	BEARING BORE			4.770	4.773	4.773	4.780	4.768	4.775
F	SLEEVE TURN			4.742	4.750	4.742	4.750	4.742	4.750
	CLR.			0.020	0.031	0.023	0.038	0.018	0.033
G	RING BORE	10.504	10.506						
H	IMPELLER TURN	10.481	10.483						
	CLR.	0.021	0.025						
I	RING BORE	10.503	10.506						
J	IMPELLER TURN	10.482	10.483						
	CLR.	0.020	0.024						
K	RING BORE			10.503	10.507	10.505	10.507	10.504	10.505
L	IMPELLER TURN			10.482	10.485	10.483	10.485	10.482	10.483
	CLR.			0.018	0.025	0.020	0.024	0.021	0.023
FITS									
M	IMPELLER BORE	2.125	2.127						
N	SHAFT TURN	2.123	2.124						
	FIT	0.001	0.004						
O	IMPELLER BORE			4.253	4.254	4.253	4.254	4.253	4.255
P	SHAFT TURN			4.249	4.249	4.249	4.249	4.249	4.250
	FIT			0.004	0.005	0.004	0.005	0.003	0.006
Q	CASING BORE	15.002	15.003						
R	SUC. BELL TURN	15.003	15.004						
	FIT	-0.002	0.000						
S	CASING BORE			17.002	17.003	17.003	17.004	17.003	17.004
T	CASING TURN			16.998	16.999	16.999	16.999	16.998	16.999
	FIT			0.003	0.005	0.004	0.005	0.004	0.006

1 SMG 06/03/2011

UNLESS OTHERWISE SPECIFIED
ALL DIMENSIONS ARE IN INCHES
TOLERANCES:

<u>DECIMALS</u>	<u>ANGULAR</u>
.X ± .1	± 25°
.XX ± .01	
.XXX ± .005	
SURFACE ROUGHNESS	N/A



DRAWN BY
SMG
CHECKED BY



ENGINEERED PUMP SERVICES, INC.
MUKWONAGO, WISCONSIN

SIZE PART NAME
A **APKD INSPECTION**


PART NO. 103-500-149

MATERIAL ASSY


SCALE NTS WEIGHT LBS. SHEET 1 OF 2 REV 1

REMOVE ALL BURRS AND SHARP EDGES .03 MAX RADIUS OR CHAMFER.

EPS JOB #	56743	CUSTOMER	EAST KENTUCKY POWER
PO #		PLANT	SPURLOCK
INSP. BY	ACS	SERIAL #	UNIT #2
DATE	12/17/21		



	1	2	3	4	5	6	7	8	9	10	11
0	.0000	.0000	.0000	.0000	.0000	.0000	.0000	.0000	.0000	.0000	.0000
90	-.0020	-.0020	-.0010	-.0010	-.0010	-.0005	-.0005	.0000	+.0020	+.0010	+.0010
180	-.0020	-.0030	-.0010	-.0010	-.0010	-.0005	.0000	+.0010	+.0020	-.0020	-.0020
270	-.0005	-.0010	.0000	-.0010	.0000	-.0005	.0000	+.0010	+.0015	-.0020	-.0030




	1	2	3	4	5	6
0	.0000	.0000	.0000	.0000	.0000	.0000
90	.0000	-.0010	-.0010	-.0030	-.0010	+.0020
180	.0000	.0000	+.0005	-.0020	-.0010	+.0020
270	-.0010	+.0010	+.0010	.0000	.0000	.0000

1 SMG 06/03/2011

UNLESS OTHERWISE SPECIFIED
ALL DIMENSIONS ARE IN INCHES
TOLERANCES:

DECIMALS	ANGULAR
.X ± .1	± .25°
.XX ± .01	
.XXX ± .005	
SURFACE ROUGHNESS	N/A



DRAWN BY
SMG
CHECKED BY



ENGINEERED PUMP SERVICES, INC.
MUKWONAGO, WISCONSIN

SIZE **A** PART NAME
APKD INSPECTION

PART NO. 103-500-149

MATERIAL ASSY

SCALE NTS WEIGHT LBS. SHEET 2 OF 2 REV 1

REMOVE ALL BURRS AND SHARP EDGES .03 MAX RADIUS OR CHAMFER.



This test is accredited and meet(s) the requirements of ISO/IEC 17025 as verified by the ANSI-ASQ National Accreditation Board/ANAB. Refer to certificate and scope of accreditation (L-2243 Milwaukee).

Acuren Inspection, Inc.
3710 North Richards Street
Milwaukee, Wisconsin 53212

www.acuren.com
A Higher Level of Reliability

Report Number: MIL3272

MAGNETIC PARTICLE EXAMINATION REPORT

Page 1 of 4

CUSTOMER: ENGINEERED PUMP SERVICES			ACUREN SERVICE CALL #: 765601		DATE: 12/16/2021	
LOCATION/ADDRESS: 3710 North Richards Street Milwaukee, Wisconsin 53212			CUSTOMER CONTACT: RICHARD LAUX			
PART # / DRAWING #: Impeller			CUSTOMER PO #: 3034255	CUSTOMER WO #: See below.		
ITEM DESCRIPTION: N/A			STAGE OF MANUFACTURE: In Process	SURFACE CONDITION: Media Blasted		
SURFACE PREPARATION: N/A		COMMENT: N/A	PARTS INSPECTED: 4	ACCEPTABLE: 1	REJECTED: 3	
NDE PROCEDURE MT-5	REV. 2	SPECIFICATION/CODE ASTM E 709-15	REV./EDITION 2015	ACCEPTANCE STANDARD CLIENT SPEC / NO LINEARS		
MATERIAL: N/A			THICKNESS: varied in.	QUANTITY: 4	ITEM TEMP.: 70 °F	
<input type="checkbox"/> Wet	<input type="checkbox"/> Dry	<input checked="" type="checkbox"/> Continuous	<input type="checkbox"/> AC	<input type="checkbox"/> Halfwave	Weight S/N's	
<input checked="" type="checkbox"/> Fluorescent	<input type="checkbox"/> Perm. Magnet	<input type="checkbox"/> Residual	<input checked="" type="checkbox"/> DC	<input checked="" type="checkbox"/> Fullwave	1. N/A	
<input type="checkbox"/> Yoke	Spacing: _____	<input type="checkbox"/> Prod. Spacing: _____	Amps: 50%		2. N/A	
<input checked="" type="checkbox"/> Circular	<input checked="" type="checkbox"/> Direct Contact	<input type="checkbox"/> Central Conductor	Amps: _____		Yoke Daily Verification: 3. N/A	
<input checked="" type="checkbox"/> Longitudinal	<input type="checkbox"/> Wrap, Turns: _____	<input type="checkbox"/> Fixed Coil Turns	Amps: _____		<input type="checkbox"/> Acc. <input type="checkbox"/> Rej. <input type="checkbox"/> N/A 4. N/A	
EQUIPMENT MODEL: Magnaflux MD3-2060-LR	SERIAL NO.: 202289	CAL DUE DATE: 01/09/2022	MEDIUM MANUFACTURER: Magnaflux	TYPE: 14A	COLOR: BLK	BATCH NO.: 19G047
DEMAGNETIZATION EQUIPMENT: AC Coil					<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
BLACKLIGHT MFG, OR LIST APPROVED LIGHT SOURCE: Rel, Inc.	SERIAL NO.: 02231704	LIGHTMETER MFG./SN: 121020A	SERIAL NO.: 208914	CAL. DUE DATE: 08/03/2022	INTENSITY: 3500 <input type="checkbox"/> FC <input type="checkbox"/> LUX <input checked="" type="checkbox"/> μ W/CM ²	
Items	Quantity	Comments			Accept/Reject	
	1	Accepted. Serial # 4			Accept	
	3	Serial # 1, 2, 3 rejected. See weld maps.			Reject	
	INFO	Customer: EKPC-Spurlock Pump: Ingersoll-Rand 29" APKD-4			Info. Only	
	INFO	Job Number: 56743-01 Order Number: 3034255			Info. Only	

<input type="checkbox"/> High Temp	Wire Wheel:	Other:	Customer Contact:		
Per Diam:	Unit #:	No. on Job:	Travel if Applicable: Hours: Miles Total:	Hours Worked: to and to	Total Hours:
CLIENT REPRESENTATIVE		ACUREN INSPECTOR Kyle Schmidt		12/16/2021	NAS 410 II
Print Name / Signature		Date	Print Name / Signature		Date
					Inspection Level

Client acknowledges receipt and custody of the report or other work ("Deliverable"). Client agrees that it is responsible for assuring that acceptance standards, specifications and criteria in the Deliverable and Statement of Work ("SOW") are correct. Client acknowledges that Acuren is providing the Deliverable according to the SOW, and not any other standards.

PEER REVIEW (IF APPLICABLE):

Print Name / Signature Date

Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect it, identify deficiencies in writing, and provide written rejection, or else the Deliverable will be deemed accepted. The Deliverable and other services provided by Acuren are governed by a Master Services Agreement ("MSA"). If the parties have not entered into an MSA, then the Deliverable and services are governed by the SOW and the "Acuren Standard Service Terms" (www.acuren.com/service/terms) in effect when the services were ordered.



Acuren Inspection, Inc.
 3710 North Richards Street
 Milwaukee, Wisconsin 53212

www.acuren.com
A Higher Level of Reliability

Report Number: MIL3272

PHOTOGRAPHIC SUMMARY SHEET

Page 2 of 4

CUSTOMER: ENGINEERED PUMP SERVICES	ACUREN SERVICE CALL #: 765601	DATE: 12/16/2021
LOCATION/ADDRESS: 3710 North Richards Street Milwaukee, Wisconsin 53212	CUSTOMER CONTACT: RICHARD LAUX	
PART # / DRAWING #: Impeller	CUSTOMER PO #: 3034255	CUSTOMER WO #: See below.
ITEM DESCRIPTION: N/A	STAGE OF MANUFACTURE: In Process	SURFACE CONDITION: Media Blasted

Photo 1

Serial # 1 rejected for 1/4" crack. (Picture Zoomed)



Photo 2

Serial # 2 rejected for 1" through-wall crack.





PHOTOGRAPHIC SUMMARY SHEET

Acuren Inspection, Inc.
3710 North Richards Street
Milwaukee, Wisconsin 53212

www.acuren.com
A Higher Level of Reliability

Report Number: MIL3272

Page 3 of 4

CUSTOMER: ENGINEERED PUMP SERVICES	ACUREN SERVICE CALL #: 765601	DATE: 12/16/2021
LOCATION/ADDRESS: 3710 North Richards Street Milwaukee, Wisconsin 53212	CUSTOMER CONTACT: RICHARD LAUX	
PART # / DRAWING #: Impeller	CUSTOMER PO #: 3034255	CUSTOMER WO #: See below.
ITEM DESCRIPTION: N/A	STAGE OF MANUFACTURE: In Process	SURFACE CONDITION: Media Blasted


Photo 3

Serial # 3 rejected for multiple 1/16"-1/8" cracks.



Photo 4

Serial # 3 rejected for multiple 1/16"-1/8" cracks.





Acuren Inspection, Inc.
3710 North Richards Street
Milwaukee, Wisconsin 53212

www.acuren.com
A Higher Level of Reliability

Report Number: MIL3272

PHOTOGRAPHIC SUMMARY SHEET

Page 4 of 4

CUSTOMER: ENGINEERED PUMP SERVICES	ACUREN SERVICE CALL #: 765601	DATE: 12/16/2021
LOCATION/ADDRESS: 3710 North Richards Street Milwaukee, Wisconsin 53212	CUSTOMER CONTACT: RICHARD LAUX	
PART # / DRAWING #: Impeller	CUSTOMER PO #: 3034255	CUSTOMER WO #: See below.
ITEM DESCRIPTION: N/A	STAGE OF MANUFACTURE: In Process	SURFACE CONDITION: Media Blasted

Photo 5

Serial # 3 rejected for multiple 1/16"-1/8" cracks.



Photo 6

Serial # 3 rejected for multiple 1/16"-1/8" cracks.

