City of Liberty

P.O. Box 127 • Liberty, KY 42539

RECEIVED

JUL 0 2 2020

PUBLIC SERVICE COMMISSION

June 29, 2020

Kentucky Public Service Commission 211 Sower Boulevard P.O. Box 615 Frankfort, KY 40602

Re: Case No. 2017-00053

Dear Commission,

Attached is the repair report for the final of the four grade 3 leaks discovered during the leakage survey for the Liberty Gas System, which was completed by Heath Consultants in July 2019.

The repair reports for other three grade 3 leaks in Liberty's gas system were submitted in November 2019.

The Liberty Gas System will be contracting Heath Consultants to perform the yearly leakage survey in August 2020 and will submit that to the PSC as soon as it's received.

Please contact me at 606-787-9973 or <u>libertybb@windstream.net</u> with any questions or concerns.

Sincerely,

idett Blake

Bridgett Blake, City Clerk City of Liberty, Kentucky



City Hall (606) 787-9973

## Aboveground Leaks 2019 Liberty KY



DATE	HOUSE#	ADDRESS	GRADE	REMARKS	
07/30/2019	511	Middleburg St	3	Reulator Vent	
07/30/2019		N Hwy 127	3	3 Inlet Reulator T Meter#07J092523	
07/31/2019	634	Button Knob	3	Farm Tap Grease Plug	
07/31/2019	617	Button Knob	3	Inlet T on Second Phase Regulator	

Form 635 Revised 8/11			White/System/LOS Yellow/Central/NR Pink/Pending/Until Repaired				
		LEAK REPORT	Uprating Copy/Work Order File/LOS				
Date Discovered: Leak Class: Submitted By:	7/30/2019 1 = 2 = 3 Heath Consaltants	Resurvey Date(s): Facility Classification: Distribution: Service L Meter Inst	ine D Transmission Line				
Leak Location: <u>N. Hwy /27 - Pyles Concrete</u> Map Sheet Number: GPS Latitude:							
How Discovered:	VIP Pipeline Designation		ide:				
Date Repaired: 6-16-20 Repaired By: Darren Greg							
	Corrosion	Incorrect Operations	Other Outside Force				
	<ul> <li>Atmospheric</li> <li>External</li> <li>Internal         <ul> <li>(Send Pipe Sample to Director-Technical Services)</li> </ul> </li> </ul>	<ul> <li>Human Error</li> <li>Ineffective Procedures</li> </ul>	<ul> <li>External Loading</li> <li>Fire/Explosion</li> <li>Vandalism</li> <li>Vehicle</li> <li>Other – Explain:</li> </ul>				
1	Natural Forces	Equipment	Material and Welds				
	<ul> <li>Earthquake</li> <li>Earth/Rock Movement</li> <li>Flood</li> <li>Frost Heave</li> <li>Landslide</li> <li>Lightning</li> <li>Subsidence</li> <li>Tornado</li> <li>Washout</li> <li>Other</li> </ul>	<ul> <li>Excess Flow Valve</li> <li>Filter</li> <li>Flow/Pressure Controller</li> <li>Heater</li> <li>Meter Casing</li> <li>Ødorizer</li> <li>Regulator/Relief Valve</li> <li>Thread</li> <li>Valve</li> <li>Other – Explain:</li> </ul>	<ul> <li>Directional Fitting</li> <li>Flange</li> <li>Mechanical Fitting</li> <li>Pipe</li> <li>Plastic Fusion Coupling</li> <li>Plastic to Plastic Compression Coupling</li> <li>Plastic to Steel Transition</li> <li>Screw Fitting</li> <li>Tap Tee</li> <li>Workmanship Defect</li> <li>Other – Explain:</li> </ul>				
e -	<ul> <li>Brittleness – Crack/Sp (Send Pipe Sample to Manager-Construction)</li> <li>Other – Explain:</li> </ul>	Name of Excavator: Result of Previous Damage: 0	Yes No				
Pipe Size: Pipe Condition:  Good  Fair Poor							
Pipe Type: Plastic: Aldyl A Plexco PE 2406 Other Steel: Threaded Welded							
Cathodically Protected:       Yes       No       Cathodic Protection P/S Reading:         Type of Coating:       Bare       Millwrap       Plastic X-Tru Coat       Thin Film         (Steel Only)       Other - Explain:							
Coating Condition:  Satisfactory Unsatisfactory Year Pipe Installed:							
Steel Pipe Condition Report Number: Original Work Order Number:							
Repair Method: 🛛 Replaced 🗆 Leak Clamp 🗅 Other - Explain:							
Test Method:  Leak (Fittings)  Pressure Psig Duration (Reinstated Service Lines Only)							
		Approved By:	Atro				