COMMONWEALTH OF KENTUCKY BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY UTILITIES COMPANY	}
	CASE NO. 94-202
ALLEGED VIOLATIONS OF COMMISSION REGULATIONS	,

ORDER

Kentucky Utilities Company ("KU"), a Kentucky corporation which engages in the distribution of electricity to the public for compensation for light, heat, power, and other uses, is a utility subject to Commission jurisdiction. KRS 278.010.

KRS 278.280(2) directs the Commission to prescribe rules and regulations for the performance of services by utilities. Pursuant to this statutory directive, the Commission promulgated Commission Regulation 807 KAR 5:041, Section 3, which requires electric utilities to maintain their plant and facilities in accordance with the standards of the National Electrical Safety Code (1990 edition) ("NESC"). It also promulgated Commission Regulation 807 KAR 5:006, Section 24, which requires a utility to adopt and execute a safety program.

Commission Staff has submitted to the Commission an Electrical Utility Accident Investigation Report dated February 28, 1994, appended hereto, which alleges:

1. On September 13, 1993, James David Stratton suffered burn injuries to his right hand and left thigh while performing

maintenance on an energized 7200-volt three phase power line in Muhlenberg County, Kentucky.

- 2. At the time of the incident, Stratton was not wearing protective clothing or using protective equipment.
- 3. At the time of the incident, Mike Robards was in charge of the work crew performing the maintenance.
- 4. At the time of the incident, KU owned the facilities in question.
- 5. At the time of the incident, Stratton and Robards were employees of KU and acting within the scope of their employment.
- 6. NESC Section 420H requires employees to "use the personal protective equipment, the protective devices, and the special tools provided for their work."
- 7. KU Safety Rule 31-2 prohibits employees from touching or working on "any exposed energized lines or apparatus except when wearing protective equipment approved for the voltage to be contacted."
- 8. While performing maintenance on the 7200-volt line, Stratton failed to comply with NESC Section 420H and KU Safety Rule 31-2.
- 9. Robards failed to see that all safety and operating procedures were observed by those under his direction. His failure is a violation of NESC Rule 421A which requires a person in charge to adopt such precautions as are within his authority to prevent accidents and to see that all safety rules and operating procedures are observed by those under his direction.

10. As a result of these failures, KU is in probable violation of Commission Regulations 807 KAR 5:006, Section 24, and 807 KAR 5:041, Section 3.

Based on its review of the Electrical Utility Accident Investigation Report and being otherwise sufficiently advised, the Commission finds that prima facie evidence exists that KU has failed to comply with Commission Regulations 807 KAR 5:006, Section 24, and 807 KAR 5:041, Section 3.

The Commission, on its own motion, HEREBY ORDERS that:

- 1. KU shall appear before the Commission on August 18, 1994 at 10:00 a.m., Eastern Daylight Time, in Hearing Room 1 of the Commission's offices at 730 Schenkel Lane, Frankfort, Kentucky, for the purpose of presenting evidence concerning the alleged violations of Commission Regulations 807 KAR 5:006, Section 24, and 807 KAR 5:041, Section 3, and of showing cause why it should not be subject to the penalties prescribed in KRS 278.990(1) for these alleged violations.
- 2. KU shall submit to the Commission, within 20 days of the date of this Order, a written response to the allegations contained in the Electrical Utility Accident Investigation Report.
- 3. The Electrical Utility Accident Investigation Report of February 28, 1994, a copy of which is appended hereto, is made part of the record of this proceeding.
- 4. Any motion requesting any informal conference with Commission Staff to consider any matter which would aid in the

handling or disposition of this proceeding shall be filed with the Commission no later than 20 days from the date of this Order.

Done at Frankfort, Kentucky, this 24th day of May, 1994.

PUBLIC SERVICE COMMISSION

hairman

lce Chairman

Commissioner

ATTEST:

Executive Director

APPENDIX

APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE COMMISSION IN CASE NO. 94-202 DATED 5/24/94

ELECTRICAL UTILITY ACCIDENT INVESTIGATION

DATE OF THIS REPORT 2/28/94 SUBMITTED BY Robert Ueltschi
NAME OF UTILITY Kentucky Utilities Company (Western Division)
ACCIDENT REPORTED BY Mr. Brian Dickey
DATE & TIME ACCIDENT OCCURRED 9/13/93 - 4:30 P.M. CST
DATE & TIME UTILITY LEARNED OF ACCIDENT 9/13/93 - 5:30 P.M. EST
DATE & TIME ACCIDENT REPORTED 9/13/93 - 6:10 P.M. EST
DATE OF ACCIDENT INVESTIGATION 9/14/93
DATE SUMMARY WRITTEN REPORT WAS RECEIVED FROM UTILITY 9/20/93
PERSONS ASSISTING IN THE INVESTIGATION Mr. Gerald Locke, Mr. Brian
Dickey, Mr. Mike Robards - Kentucky Utilities Company and Robert
Ueltschi - PSC
NAME OF VICTIM(S) James David Stratton SEX M AGE 36
PATAL No NAME OF EMPLOYER Kentucky Utilities Company
INJURIES Burns - right index finger extending to thumb and
left thigh.
LOCATION OF ACCIDENT SITE South Carrollton on Ky. 81 in
Muhlenberg County.
DESCRIPTION OF ACCIDENT Mr. James David Stratton was working on a
7200 V three phase power line. In the process of squeezing up #4
copper to #2 ACSR with a "D" die machine (Compression tool), Mr.
Stratton made contact with the 7200 volt line. Mr. Stratton was
not wearing protective rubber gloves at the time of the accident.
Mr. Mike Robards was the superintendent on the project.

ELECTRICAL UTILITY ACCIDENT INVESTIGATION (Continued)
SOURCE OF INFORMATION Mr. Mike Robards, Mr. Gerald Locke and Mr.
Brian Dickey - Kentucky Utilities Company
PROBABLE VIOLATIONS OF COMMISSION REGULATIONS Mr. Stratton was in
probable violation of 807 KAR 5:041 (Electric), Section 3(2) and
NESC Section 42 subsection (420H) tools and protective equipment.
Mr. Stratton was also in probable violation of Kentucky Utilities'
safety rule(s) General 31-2.a.
Mr. Robards was in probable violation of NESC Section 42
subsection 421A. 1 and 2. Duties of a first level supervisor or
person in charge.
RECOMMENDATIONS It is recommended that the Commission consider
action in accordance with KRS 278.990 and the probable violation of
Commission Regulations 807 KAR 5:041, Section 3(2), and 807 KAR
5:006, Section 24.
CORPECATOR ACATON None

ELECTRICAL UTILITY ACCIDENT INVESTIGATION (Continued)

LINE CLEARANCES

	LINE CL	As A	dessured		NESC NESC
A.	AT POINT OF ACCIDENT				
	Phase conductors to ground elevation:	Center-	27'- 11 27'- 11 27'- 11	1/2"	20' - 0" 20' - 0" 20' - 0"
	Neutral conductor to ground elevation:		24' - 2	1/2"	18' - 0"
	Communication conductor to ground elevation:		N/A	·	N/A
	Phase conductor to structure:		N/A	·	N/A
	Neutral conductor to structure:		N/A		N/A
	Communication conductor to structure:		N/A		N/A
В.	AT LOWEST POINT OF SPAN				
	Phase conductor to ground is elevation:	enter phi		- 3"	20' - 0" 20' - 0" 20' - 0"
	Neutral conductor to ground elevation:		19' -	8_1/2"	18' - 0"
	Communication conductor to ground elevation:		N/A		N/A
c.	SPAN LENGTE 300'				
Date	the line or facilities were	constru	cted <u>196</u>	3	
Volt	age of line or facilities	200 Volt	- 3 phas	3 <i>e</i>	······································
Date	last inspected by utility _	1/21/93			
Utility Kentucky Utilities Company (Western Division)					
Date	9/14/93	Time 8:	30 A.M.	CST	

Approximate temperature 75° F Measurements made by Mike Robards, Stephen Hendrix, Brian Dickey - Kentucky Utilities Company - Robert Ueltschi, PSC Submitted by: Accident Continued)

KENTUCKY UTILITIES COMPANY
ONE QUALITY STREET
LEXINGTON, KY 40507
PHONE: (606) 255-2100

September 17, 1993

RECEIVED

SFP 20 1993

Mr. Bob Ueltschi
Public Service Commission
730 Schenkel Lane
P.O. Box 615
Frankfort, KY 40802

DIVISION OF UTILITY ENGINEERING & SERVICES

Dear Bob:

BUBJECT: REPORT OF ACCIDENT-EMPLOYEER JAMES DAVID STRATTON DATE OF ACCIDENT: 09/13/83

Enclosed is a copy of a Report of Accident-Employee for the captioned. Mr. Stratton was raising handle of "D" Die Machine and contacted 7.2 KV line resulting in burns.

If you need additional information please advise.

Sincerely,

James A. Brackney, F.E. Manager, Risk Management

JAB/ss Enclosure

cc: R. M. Hewett W. N. English

Kentucky Utilities Company REPORT OF ACCIDENCE 118 Court Street KU \$4-11 REV 1 Greenville. 42345 EP 1 5 1993 Location at Which Injured Employee Date of This Report Employed Greenville District Crew **Acadent Number** RISK MANAGEMENT TEPT {Hour James David Stratton ADD 36 WHOSE /Week (Month O. Box 542 Greenville 42345 ZID CITY PAY Area Code and Telephone Number _ Married WHO WAS INJURED? Employee Birthday __ __ No. of children under 15 years ____ 2 ___ No. of Dependents _ List hames, birthdates, relationship_ Years employed by company 10 Mg beent job 8 Mg. Occupation Line Tech A (RII) District Crew Department XX Date 9/13/93 Hour 4:30 \mathbf{x} Did acadent occur on employer's premises TIME AND PLACE OF South Carrollton. Place of accident Hwy 81 INJURY City Address Name WITNESSES William Mackey Bailey TO THE Livermore, KY INJURY Steve Hendrix Rt 2, Greenville, KY. Parts of Body invited and nature of injuries Right index finger extending to thumb and NATURE AND **EXTENT OF** left thich INJURY 9/13/93 Date of first treatment by Doctor___ Probable Length of Disability _ (Include All Emergency room or injuries) Amending Physician Edward Shuttleworth Address Greenville, Date Hospitalized 9/13/93 Name and Address of hospital Muhlenberg Community Hospital Greenville, Ky 42345 identity object, substance or machine which directly injured employee 7-2 KV conductor What was employee doing when injured? (Se specific) raising handle of "D" Die Machine. How did accident or exposure occur? (Tell what happened and now it Happened) <u>Employee contacted 7.2 KV</u> ACCIDENT Employee was squeezing up #4 Copper to Describe events which resulted in injury ___ #2 ACSR Employee's Signature Date Supervisor's Signature 9-14-93 (Dist. Mgr. or Dept. Head)


KU INSPECTION REPORT	
OFFICE Centrel City	RECEIVED
METER AND SERVICE DROP INSPECTION ROUTE No.	SER 25 1993
DISTRIBUTION AND SECONDARIES INSPECTION ZONE (LINE LOCATION) 27-11 6-2-1	DIVISION OF CHALLES ENGINEERING & SERVICES
Instructions to inspection personnel: Inspect all distribution fa complete report and present it to local manager, copy to	
Inspection Check List:	
Insulators Guys and anchors C Poles/structures Transformers S	
Maintenance required or other remarks (attach addition Show location by line, route or address	nal sheets as required).
ACCOUNT SILLEGE DID ARRESTER Blown	
Visual Inspection performed in whole or in part in conn	ection with regular duties.
Date Completed 1-21-99	inspection Personnel
Instructions to maintenance personnel: When work is finished manager, copy to district manager.	•
Repairs or other maintenance performed (attach addit	tional sheets as required)
Date Completed Z - 12 - 93 Colonia	PT
Date Completed 2-19-93 Endang	Maintenance Personnel

KENTUCKY UTILITIES COMPANY

FOR COMPANY BUSINESS ONLY

Subject	PSC Request	
From	Gerald Locke	
To	Brian Dickey	

Date September 15, 1993



Enclosed is a copy of a facility map showing the location of the accident at South Carrollton involving David Stratton on 9/13/93. The 1 Ø tap line was constructed in 1963 with no known upgrading necessary.

A distribution inspection was completed on 1/21/93 for this zone on 77-11. Maintenance was not indicated to be needed at the site.

The arrester identified on the inspection was at the location for account work completed 2/19/93.

GL:waj
attachment

cc: K. Curtis

K. Sheridan

15-32		Scheduled	13000
No uparndes	ROUTINI	E ORDER	
Oate	Tux District	Charge To	POLI I
District	Town Base Map	Detail/Sub _6-2-/	P.M
	CUMMINDS TOP in		444
	•		
Reason Needed 4,060			
		Other U	tility Contact Req.
Easement Sec. & Recorded) by date Eas	e. Not Req. []	
	255 KWill	•	
	25,44		
Dis 80	36 X 2	21 6	2 30 - 2
Job Comments/Delays	•		25.2.
Submitted by		(esclude travel)	ua! Hours
Approved by		_ Contractor/Crew Used	