95

COMMONWEALTH OF KENTUCKY BEFORE THE PUBLIC SERVICE COMMISSION

In the matter of:

Gene	- Ray Hardy		
	Full Name) (COMPLAINANT)	RECEIVED	
	· COMPLAMAN I)	JAN 2 6 2006	
VS.	ville Gas and Electoric Co.	PUBLIC SERVICE COMMISSION	
(Name of Utility)) CASE 2006-00043			
•	DEFENDANT)		
	COMPLAINT		
The complai	int of Gene Ray Hardy (Your Full Name)	respectfully shows:	
(a)	(Your Full Name)		
	4418 Jacob Glen Way he (Your Address)	WSW. 11e , Ky 40241	
(b)	Loursurle Cas & Electric (Name of Utility)		
	220 West Main St. Loursuil	e Ky	
		40202	
(c)	That: On Dec 15, 2005, or a (Describe here, attaching additional sheet)		
	Failed; which caused the hot wire to confact the specific act, fully and clearly, or facts that are the reason		
	the neutral wire, which sent a strong		
electrical current surge dun the service			
wife to my apartment building located at			

Continued on Next Page

Hench Thank (Your Signature)

(Name and address of attorney, if any)

A MM DD MY 12 15'	YYYY 2005 1 05-000088	Change Basic
FDID * State * Incident Dat	Station Incident Number	No Activity
B Location* Check this box to In Hodule In Section B	dicate that the address for this incident is provided on the "Alternative Location Specification". Use only for Wildlam	d fires. Census Tract 0128 - 01
XStreet address 3508	Fern Lea	RD Street Type Suffix
Intersection Number/Milepost Prefit		Street Type Suffix
Rear of # 5 Sh	ively	State Zip Code
Adjacent to		
Cross street or dire		ight is 0000 E2 Shift & Alarms
C Incident Type *	E1 Date & Times Check boxes if Month Day	Local Option
440 Electrical wiring/equipment Incident Type	Check boxes if Month Day dates are she same as Alarm ALARM always required	1 01 3
D Aid Given or Received*	Date. Alarm * 12 15 ARRIVAL required, unless cancel	2005 01:23:00 Shift or Alarms District Platoon
[Mutual aid received	X Arrival * 12 15	2005 01:29:00 E3
2 X Automatic aid recv. Their FDID Their State	CONTROLLED Optional, Except for	
3 Mutual aid given 4 Nautomatic aid given	Controlled	Local Option
5 Other aid given Their Incident Number	Last Unit CLEARED, required exce	Special Special
I None	X Cleared 12 15	2005 02:05:00 Study ID# Study Value
F Actions Taken *	G1 Resources * G2	2 Estimated Dollar Losses & Values
	Check this box and skip this section if an Apparatus or	LOSSES: Required for all fires if known. Optional for non fires. None
86 Investigate	Personnel form is used. Apparatus Personnel Pro	
Primary Action Taken (1)	Suppression 0002 0005	ntents \$ 000 , 000 [7]
45 Remove hazard		PRE-INCIDENT VALUE: Optional
Additional Action Taken (2)	Other	
Additional Action Taken (3)	Check box if resource counts	operty \$, 000, 000 []
marcional factor factor (5)		ntents \$, 000, 000 _
Completed Modules H1*Casualties	None H 3 Hazardous Materials	
	uries N None	NN Not Mixed 10 Assembly use
Structure-3 Givil Fire Cas4	1 Natural Gas: alow leak, no evamat 2 Propane gas: 21 lb. tank (as in	1
Fire Serv. Cas5 Civilian	2 Propane gas: <1 lb. tank (as in Gasoline: vahicle fuel tank or port	able container 40 Residential use
EMS-6	4 Kerosene: fuel burning equipment or	portable storage 51 Row of stores Rnclosed mall
HazMat-7 Required for Confined Wildland Fire-8		
X Apparatus-9	upants 6 Household solvents: home/office 7 Motor oil: from engine or portable	60 Industrial use
☑Personnel-10 2 Detector did not ale		1 02 IMILITARY use
Arson-11 U Unknown	O Cther: Special HazMat actions requires	d or spill > 55gal., 00 Other mixed use
J Property Use* Structures	341 Clinic, clinic type infirmary 342 Doctor/dentist office	539 Household goods, sales, repairs 579 Motor vehicle/boat sales/repair
.31 Church, place of worship	361 Prison or jail, not juvenile	571 Gas or service station
.61 Restaurant or cafeteria	419 1-or 2-family dwelling	599 Business office
62 Bar/Tavern or nightclub 13 Elementary school or kindergarten	429 X Multi-family dwelling 439 Rooming/boarding house	615 Electric generating plant 629 Laboratory/science lab
15 High school or junior high	449 Commercial hotel or motel	700 Manufacturing plant
41 College, adult education	459 Residential, board and care	819 Livestock/poultry storage (barn)
11 Care facility for the aged 31 Rospital	464 Dormitory/barracks 519 Food and beverage sales	882 Non-residential parking garage
Outside	936 Vacant lot	981 Construction site
24 Playground or park	938 Graded/care for plot of land	984 Industrial plant yard
55 Crops or orchard	946 Lake, river, stream	Lookup and enter a Property Use code only if
69 Forest (timberland) 07 Outdoor storage area	951 Railroad right of way 960 Other street	Lookup and enter a Property Use code only if you have NOT checked a Property Use box: Property Use 429
19 Dump or sanitary landfill	961 Highway/divided highway	
31 Open land or field	962 Residential street/driveway	Multifamily dwellings NFIRS-1 Revision 03/11/99

Secret This Now if State Secret Secret The Secret Secret Secret The Secret Secre	1 Person/Enti	Bu i name (if applicable) Area Code Phone Number	
The code of this man and all plants of the code of the	M same address as incident location. Then skip the three duplicate address lines.	Mr., Mrs. First Name MI Last Name Suffix 3508 Fern Lea RD Number Frefix Street or Highway # 5 Shively Post Office Box Apt./Suite/Room City KY 40216 State Zip Code	
Remarks	Then check this box and skip The rest of this section.		
Maile on the scene of Run # 882 @ 2258 Crums Lane, Dispatch called to advise that they had another run for us at 3508 Fern Lea Road on a fire alarm sounding and wanted to know if we could split the company to handle the new run. I told them that Truck 25 would remain at the Crums Lane run and that I would send Engine 25 to check on the Fern Lea run. These two locations are directly across the street from one another. When Engine 25 arrived on scene they found that the hard wired smoke detector in Apartment 5 had shorted out. They found that the cover to the detector had been "blown off" the base when the unit shorted out. Truck 25 cleared from the Crums Lane run and joined the Engine on Fern Lea. We disconnected the wiring to the detector and removed the base of the detector from the ceiling and checked around the junction box to make sure there were no hot spots in the ceiling because there was quite a bit of sooty residue on the detector and the ceiling where the detector had been. Using the Thermal Imaging Camera, we found no significant heat in the area. There was no power to this apartment upon our arrival. The resident said she was awakened when she heard a loud popping noise in the hall of the apartment. This appeared to be some sort of power surge that overloaded the smoke detector circuit, although I can not say that for sure as I am not an expert on electricity and wiring. Lamborous Gegon Camborous, Gregory Scott CP Continued the Month Day Year Stofficer Member making report ID Signature Camborous, Gregory Scott CP Camborous and Assignment Month Day Year Stofficer Member making report ID Signature Camborous Gregory Scott CP Camborous Camborou	-i same address as incident location. Then skip the three duplicate address	Number Prefix Street or Highway Street Type Suffix Post Office Box Apt./Suite/Room City	
This appeared to be some sort of power surge that overloaded the smoke detector circuit, although I can not say that for sure as I am not an expert on electricity and wiring. LAuthorization GSC Officer in charge ID Signature Cambron, Gregory Scott CP Position or rank Assignment Nonth Day Year CP Signature CP Position or rank Assignment Nonth Nonth Day Year CP Signature CP Position or rank Assignment Nonth Nonth Day Year	Nhile on the scanother run for could split the the Crums Lane of they found that that the cover of the wiring to the around the junctives quite a bit been. Using the	us at 3508 Fern Lea Road on a fire alarm sounding and wanted to know if we company to handle the new run. I told them that Truck 25 would remain at run and that I would send Engine 25 to check on the Fern Lea run. These two rectly across the street from one another. When Engine 25 arrived on scene the hard wired smoke detector in Apartment 5 had shorted out. They found to the detector had been "blown off" the base when the unit shorted out. I from the Crums Lane run and joined the Engine on Fern Lea. We disconnected the detector and removed the base of the detector from the ceiling and checked ion box to make sure there were no hot spots in the ceiling because there of sooty residue on the detector and the ceiling where the detector had thermal Imaging Camera, we found no significant heat in the area. There	
Authorization GSC Cambron, Gregory Scott CP Log Log Year Cambron, Gregory Scott CP Log Log Year Cambron, Gregory Scott CP Log Log Year Check Sox if GSC Cambron, Gregory Scott CP Log Log Year Check Sox if GSC Signature Cambron, Gregory Scott CP Log Log Zoot Some Sox if S			
GSC Cambron, Gregory Scott CP 12 20 2005 Officer in charge ID Signature Position or rank Assignment Month Day Year Check Sox if X GSC Cambron, Gregory Scott CP 12 20 2005 Same as Officer Member making report ID Signature Position or rank Assignment Month Day Year			
GSC Cambron, Gregory Scott CP 12 20 2005 Officer in charge ID Signature Position or rank Assignment Month Day Year Check Sox if X GSC Cambron, Gregory Scott CP 12 20 2005 Same as Officer Member making report ID Signature Position or rank Assignment Month Day Year			
Officer in charge ID Signature Position or rank Assignment Month Day Year Check Sox if X GSC Cambron, Gregory Scott CP 12 20 2005 same as Officer Member making report ID Signature Position or rank Assignment Month Day Year			
30x if X GSC Cambron, Gregory Scott CP 12 2005 Same as Officer Member making report ID Signature Position or rank Assignment Month Day Year	Officer in charg	Position or walk	
	same as Officer Member making re		