Electric Distribution Utility Annual Reliability Report

SECTION 1: CONTACT INFORMATION

UTILITY NAME	1.1	Inter-County Energy
OTILITI INVINE	1.1	inter-county Energy

REPORT PREPARED BY 1.2 Jessie Turpin

E-MAIL ADDRESS OF PREPARER 1.3 jessie@intercountyenergy.net

PHONE NUMBER OF PREPARER 1.4 859-236-4561 ext. 7857

SECTION 2: REPORT YEAR

CALENDAR YEAR OF REPORT 2.1 2022

SECTION 3: MAJOR EVENT DAYS

 T_{MED} 3.1 9.376

FIRST DATE USED TO DETERMINE T_{MED} 3.2 Jan. 1, 2017

LAST DATE USED TO DETERMINE T_{MED} 3.3 Dec. 31, 2021

NUMBER OF MED IN REPORT YEAR 3.4

NOTE: Per IEEE 1366 T_{MED} should be calculated using the daily SAIDI values for the five prior years. If five years of data are not available, then utilities should use what is available until five years are accumulated.

SECTION 4: SYSTEM RELIABILITY INFORMATION AND RESULTS

System-wide Information

TOTAL CUSTOMERS 27151 TOTAL CIRCUITS 46

Excluding MED

5 Y	EAR AVERAGE	REPORTING YEAR	
SAIDI	102.25	SAIDI 122.62	
SAIFI	1.03	SAIFI 1.35	

Including MED

5 Y	EAR AVERAGE	REPORTING YEAR	
SAIDI	345.67	SAIDI	186.76
SAIFI	2.00	SAIFI	1.98

Notes:

- 1) All duration indices (SAIDI, CAIDI) are to be reported in units of minutes.
- 2) Reports are due on the first business day of May of each year
- 3) Reports cover the calendar year ending in the December before the reports are due.
- 4) IEEE 1366 (latest version) is used to define SAIDI, SAIFI, CAIDI, and T_{MED}

Substation Name and Number	Lancaster (1)	
2. Substation Location	Garrard-Buckeye Rd-Lancaster	
3. Circuit Name and Number	Lex Road(2)	
4. Circuit Location	Lexington Rd, Kember Ln,	
Fork Churc	ch Rd, Danville Hwy, Goggin Ln, I	Betts Ln, Old Danville Rd
5. Total Circuit Length (Miles)		84.36
6. Customer Count		851
7. Date of Last Circuit Trim		2022
8. Outage Cause (% of Total Outage Numbers)		2022
8. Outage Cause (% of Total Outage Numbers)	Animals	22.60%
	Lightning	1.33%
	High Wind	0.00%
	Equip. Failure	20.42%
	Deteriorated	2.32%
	Cars or Trucks	47.66%
	Insulation broke	0.00%
	Vegetation/Trees	1.00%
	rees Cut Into Line	0.69%
	Equipment OL	0.00%
	Rain/ Ice	0.00%
	Cased by Others	3.97%
	Cased by Others	3.91 /6
9. Circuit 5 Year Average (SAIDI)		2.808
10. Reporting Year (SAIDI)		5.278
11. Circuit 5 Year Average (SAIFI)		1.647
12. Reporting Year (SAIFI)		4.893
13. List of Corrective Action, If Any, Taken or To	Be Taken	

Official #2			
1. Substation Name and Number	Ballard (2)	Ballard (2)	
2. Substation Location	Garrard-Fisher Ford Rd-Lancaster Wells Landing (2)		
3. Circuit Name and Number			
4. Circuit Location			
	Wells Landing Rd, Old Bridge, Ta	aylor Rd, Old Lexington Rd	
5. Total Circuit Length (Miles)		24.11	
6. Customer Count		469	
7. Date of Last Circuit Trim		2020	
8. Outage Cause (% of Total Outage No	ımbers)	2020	
	Animals	0.73%	
	Lightning	33.47%	
	High Wind	21.28%	
	Equip. Failure	32.97%	
	Deteriorated	0.00%	
	Cars or Trucks	0.16%	
	Insulation broke	0.00%	
	Vegetation/Trees	4.58%	
	Trees Cut Into Line	0.00%	
	Equipment OL	0.00%	
	Rain/ Ice	0.00%	
	Cased by Others	6.80%	
9. Circuit 5 Year Average (SAIDI)		0.682	
10. Reporting Year (SAIDI)		1.383	
11. Circuit 5 Year Average (SAIFI)		0.431	
12. Reporting Year (SAIFI)		1.128	
13. List of Corrective Action, If Any, Tak	en or To Be Taken		

Substation Name and Number	Ballard (2)	
2. Substation Location	Garrard-Fisher F	ord Rd-Lancaster
3. Circuit Name and Number	ParadiseCamp(3	3)
4. Circuit Location	Fisher Ford Rd, Carry Nation Rd,	
Lake View Point, Sunrise Shore Dr, F	Paradise Camp Rd, Kennedy Bri	idge Rd, Bardshaw Ln
5. Total Circuit Length (Miles)		22.4
6. Customer Count		507
7. Date of Last Circuit Trim		2019
8. Outage Cause (% of Total Outage Numbers)		
	Animals	1.53%
	Lightning	0.66%
	High Wind	21.38%
	Equip. Failure	0.79%
	Deteriorated	0.00%
	Cars or Trucks	0.00%
Ir	sulation broke	0.00%
Ve	getation/Trees	47.62%
Tree	s Cut Into Line	0.00%
	Equipment OL	0.00%
	Rain/ Ice	0.38%
Ca	sed by Others	27.64%
9. Circuit 5 Year Average (SAIDI)		0.922
10. Reporting Year (SAIDI)		3.237
11. Circuit 5 Year Average (SAIFI)		0.512
12. Reporting Year (SAIFI)		1.690
13. List of Corrective Action, If Any, Taken or To Be	Taken	

Ollodit II 4			
1. Substation Name and Number	Shelby C	Shelby City(4)	
2. Substation Location	Boyle-E Knob Lick Rd-Junction City Old127Loop(2)		
3. Circuit Name and Number			
4. Circuit Location			
	Old127 North Loop, Moores Ln	, HWY 1194, Peyton Well Rd	
5. Total Circuit Length (Miles)		26.83	
6. Customer Count		200	
7. Date of Last Circuit Trim		2022	
8. Outage Cause (% of Total Outage N	umbers)		
	Animals	3.81%	
	Lightning	4.56%	
	High Wind	49.11%	
	Equip. Failure	0.00%	
	Deteriorated	0.00%	
	Cars or Trucks	10.24%	
	Insulation broke	0.00%	
	Vegetation/Trees	0.00%	
	Trees Cut Into Line	27.93%	
	Equipment OL	0.00%	
	Rain/ Ice	0.00%	
	Cased by Others	4.35%	
9. Circuit 5 Year Average (SAIDI)		0.427	
10. Reporting Year (SAIDI)		1.275	
11. Circuit 5 Year Average (SAIFI)		0.388	
12. Reporting Year (SAIFI)		0.990	
13. List of Corrective Action, If Any, Ta	ken or To Be Taken		

Substation Name and Number	Shelby City(4)	
2. Substation Location	Boyle-E Knob Li	ck Rd-Junction City
3. Circuit Name and Number	Hustonville(3)	
4. Circuit Location	USHWY 127N, KYHWY1194	
Jeffries	Ln, KY HWY 2141, Harris Creek Rd, Black	ack Pike, Holtzclaw Ln
5. Total Circuit Length (Miles)		57.03
6. Customer Count		1159
7. Date of Last Circuit Trim		2021
8. Outage Cause (% of Total Outage Numb	ers)	
	Animals	0.63%
	Lightning	0.03%
	High Wind	0.04%
	Equip. Failure	96.68%
	Deteriorated	0.00%
	Cars or Trucks	0.00%
	Insulation broke	0.00%
	Vegetation/Trees	0.00%
	Trees Cut Into Line	0.61%
	Equipment OL	0.00%
	Rain/ Ice	0.20%
	Cased by Others	1.81%
0.00: (0.4101)		4 400
9. Circuit 5 Year Average (SAIDI)		1.432
10. Reporting Year (SAIDI)		9.531
11. Circuit 5 Year Average (SAIFI)		0.760
12. Reporting Year (SAIFI)	ar Ta Da Takan	2.080
13. List of Corrective Action, If Any, Taken of	or to be taken	
-		
_		

On dail #0		
1. Substation Name and Number	Shelby C	ity(4)
2. Substation Location	Boyle-E ł	Knob Lick Rd-Junction City
3. Circuit Name and Number	Alum Springs(4)	
4. Circuit Location	W Knob Lick Rd, White Oak Rd,	
Nosco Rd, Hogue Hollow Rd,	Alum Springs Rd, Alum Sp	orings Crosspike, Stewarts Ln
5. Total Circuit Length (Miles)		78.2
6. Customer Count		1199
7. Date of Last Circuit Trim		2021
8. Outage Cause (% of Total Outage Numbers)		
	Animals	0.32%
	Lightning	35.75%
	High Wind	10.47%
	Equip. Failure	5.38%
	Deteriorated	0.08%
	Cars or Trucks	0.00%
	Insulation broke	0.00%
V	egetation/Trees	39.10%
Tre	es Cut Into Line	0.00%
	Equipment OL	0.10%
	Rain/ Ice	0.00%
	Cased by Others	8.80%
9. Circuit 5 Year Average (SAIDI)		1.128
10. Reporting Year (SAIDI)		3.041
11. Circuit 5 Year Average (SAIFI)		0.777
12. Reporting Year (SAIFI)		2.174
13. List of Corrective Action, If Any, Taken or To B	e Taken	

Substation Name and Number	Perryville (6)	
2. Substation Location	Boyle-Harrodsh	ourg-Perryville
3. Circuit Name and Number	Harrodsburg(1)	
4. Circuit Location	US 68, Quirks	Run, Bluegrass Pike
5. Total Circuit Length (Miles)		59.9
6. Customer Count		430
7. Date of Last Circuit Trim		2020
8. Outage Cause (% of Total Outage Numbers)		
	Animals	0.90%
	Lightning	10.08%
	High Wind	23.44%
Eq	uip. Failure	0.44%
D	eteriorated	0.00%
Car	or Trucks	0.41%
Insul	ation broke	0.00%
Veget	ation/Trees	11.47%
Trees C	ut Into Line	0.00%
Equ	ipment OL	0.00%
	Rain/ Ice	0.00%
Cased	by Others	53.26%
O Circuit E Voor Average (CAIDI)		1.165
9. Circuit 5 Year Average (SAIDI)		1.709
10. Reporting Year (SAIDI)		
11. Circuit 5 Year Average (SAIFI)		0.402
12. Reporting Year (SAIFI)		1.340
13. List of Corrective Action, If Any, Taken or To Be Ta	<u>(en</u>	

Substation Name and Number	Perryvill	e (6)
2. Substation Location	Boyle-H	arrodsburg-Perryville
3. Circuit Name and Number	Mitchell	sburg(2)
4. Circuit Location		
Perryville Rd, Godbey Ln, Mitche	ll Ln, Webster Rd, Harbei	son Ln, Cash Rd, Lebanon Rd
Tank Pond Rd	Johnson Branch Rd, For	kland Rd, Carpenter Creek Rd
5. Total Circuit Length (Miles)		79.64
6. Customer Count		735
7. Date of Last Circuit Trim		
8. Outage Cause (% of Total Outage Numbers)		
	Animals	0.26%
	Lightning	1.23%
	High Wind	11.92%
	Equip. Failure	0.32%
	Deteriorated	0.00%
	Cars or Trucks	0.00%
	Insulation broke	0.00%
\	/egetation/Trees	3.52%
Tre	ees Cut Into Line	0.00%
	Equipment OL	0.00%
	Rain/ Ice	82.21%
	Cased by Others	0.54%
9. Circuit 5 Year Average (SAIDI)		0.700
10. Reporting Year (SAIDI)		4.043
11. Circuit 5 Year Average (SAIFI)		0.313
12. Reporting Year (SAIFI)		1.859
13. List of Corrective Action, If Any, Taken or To E	Be Taken	_

1. Substation Name and Number	Loretto(8)	
2. Substation Location	Marion-Loretto Rd-Lebanon	
3. Circuit Name and Number	Holy Cross (4)	
4. Circuit Location	St Francis Hwy, Holy Cross Rd, Nerinx Rd,	
George Edelen Rd, Springtowr	n Rd, Manton Rd, Raley Rd, Beantow	vn Rd, Sam Browning Rd
5. Total Circuit Length (Miles)		65.36
6. Customer Count		547
7. Date of Last Circuit Trim		2021
8. Outage Cause (% of Total Outage Number	ers)	
	Animals	14.66%
	Lightning	6.16%
	High Wind	0.00%
	Equip. Failure	0.84%
	Deteriorated	0.00%
	Cars or Trucks	0.72%
	Insulation broke	0.00%
	Vegetation/Trees	5.48%
	Trees Cut Into Line	0.00%
	Equipment OL	24.70%
	Rain/ Ice	0.39%
	Cased by Others	47.05%
9. Circuit 5 Year Average (SAIDI)		0.267
10. Reporting Year (SAIDI)		2.128
11. Circuit 5 Year Average (SAIFI)		0.316
12. Reporting Year (SAIFI)		1.138
13. List of Corrective Action, If Any, Taken o	r To Be Taken	

Substation Name and Number	Sulphe	er Ck.(9)
2. Substation Location	Nelsor	n-Gap Knob Rd-New Hope
3. Circuit Name and Number	Howar	dstown(2)
4. Circuit Location		
	Stiles Rd, Scott Rd, F	lowardstown Rd, Walter Hall Rd
5. Total Circuit Length (Miles)		54.48
6. Customer Count		295
7. Date of Last Circuit Trim		2018
8. Outage Cause (% of Total Outage Numb	ers)	
	Animals	0.08%
	Lightning	26.84%
	High Wind	0.00%
	Equip. Failure	0.00%
	Deteriorated	0.92%
	Cars or Trucks	0.00%
	Insulation broke	0.00%
	Vegetation/Trees	10.78%
	Trees Cut Into Line	57.30%
	Equipment OL	0.00%
	Rain/ Ice	2.92%
	Cased by Others	1.15%
0. 0: :: 5. // 4 (0.4.151)		0.005
9. Circuit 5 Year Average (SAIDI)		2.805
10. Reporting Year (SAIDI)		10.335
11. Circuit 5 Year Average (SAIFI)		1.685
12. Reporting Year (SAIFI)	vr To Do Tokon	4.363
13. List of Corrective Action, If Any, Taken of	or to be taken	

Onodit #11		
1. Substation Name and Number	H.T. Adams (10)
2. Substation Location	Mercer-DryBr	anchRd-Harrodsburg
3. Circuit Name and Number	Harrodsburg(1)
4. Circuit Location		
Dr	y Branch Rd, Kyle Ln, Sparrow Ln, Dan	ville Rd, Beaumount Ave,
Bud James Ln, Bellows Mill Rd, N	Mercer Ave, Boyle Ave, Adams Ln, Brigh	ntleaf Dr, Cold Springs Dr
5. Total Circuit Length (Miles)		40.75
6. Customer Count		611
7. Date of Last Circuit Trim		2021
8. Outage Cause (% of Total Outage Nur	mbers)	
	Animals	2.46%
	Lightning	2.22%
	High Wind	1.82%
	Equip. Failure	1.46%
	Deteriorated	0.00%
	Cars or Trucks	0.00%
	Insulation broke	0.00%
	Vegetation/Trees	52.80%
	Trees Cut Into Line	0.00%
	Equipment OL	12.67%
	Rain/ Ice	0.00%
	Cased by Others	26.57%
9. Circuit 5 Year Average (SAIDI)		0.539
10. Reporting Year (SAIDI)		2.297
11. Circuit 5 Year Average (SAIFI)		0.821
12. Reporting Year (SAIFI)		1.403
13. List of Corrective Action, If Any, Take	n or To Be Taken	1.400
13. List of Corrective Action, if Arry, Take	ITOT TO BE TAKE!!	

GHOGIC # 12		
1. Substation Name and Number	Marion Indus	trial(12)
2. Substation Location	Marion-Indus	strial Dr-Lebanon
3. Circuit Name and Number	Ky Hwy 208(1	l)
4. Circuit Location		
New Calvery Rd, Lovers Ln, Millers Pike,	Campbellsville Hwy, McElro	y Pike, Wards Branch Rd
5. Total Circuit Length (Miles)		66.81
6. Customer Count		1101
7. Date of Last Circuit Trim		2021
8. Outage Cause (% of Total Outage Numbers)		
, <u> </u>	Animals	3.11%
	Lightning	27.79%
	High Wind	0.62%
-	quip. Failure	26.89%
	Deteriorated	0.00%
C	ars or Trucks	0.00%
Ins	ulation broke	0.44%
Veg	etation/Trees	0.00%
Trees	Cut Into Line	5.48%
E	quipment OL	0.16%
	Rain/ Ice	0.16%
Cas	ed by Others	35.35%
9. Circuit 5 Year Average (SAIDI)		0.250
10. Reporting Year (SAIDI)		2.229
11. Circuit 5 Year Average (SAIFI)		0.381
12. Reporting Year (SAIFI)		1.269
13. List of Corrective Action, If Any, Taken or To Be	aken	

On oak # 10		
Substation Name and Number		Garrard(13)
2. Substation Location		Garrard-Enterprise Dr-Lancaster
3. Circuit Name and Number		Paintlick(1)
4. Circuit Location		Richmond Rd, Sunrise Dr,
Richmond Rd Loop 1, Kirksville Rd,	Perry Rogers Rd, Po	oor House Rd, Hurt Ln, Kelly Ridge Rd
Maupin Rd, Gooch Pike, Gaffney Rd, Walker F	Pike, Brock Rd, Old I	Railroad Grade Rd, Gillespie Pike, Bro
5. Total Circuit Length (Miles)		88.86
6. Customer Count		783
7. Date of Last Circuit Trim		2022
8. Outage Cause (% of Total Outage Numbers)	
	Animals	24.08%
	Lightning	1.25%
	High Wind	0.21%
	Equip. Failure	7.70%
	Deteriorated	0.00%
	Cars or Trucks	2.75%
	Insulation broke	0.54%
	Vegetation/Trees	4.72%
	Trees Cut Into Line	0.00%
	Equipment OL	0.00%
	Rain/ Ice	57.69%
	Cased by Others	1.04%
9. Circuit 5 Year Average (SAIDI)		0.750
10. Reporting Year (SAIDI)		6.303
11. Circuit 5 Year Average (SAIFI)		0.430
12. Reporting Year (SAIFI)		3.609
13. List of Corrective Action, If Any, Taken or T	o Bo Takon	3.003
13. List of Corrective Action, if Arry, Taken of T	O De Takeli	
-		

Electric Distribution Utility Annual Reliability Report Additional pages may be attached as necessary SECTION 6: VEGETATION MANAGEMENT PLAN REVIEW

Inter-County Energy has restarting a new 6 year cycle and will be closely monitoring the results of the cycle progress.
SECTION 7: UTILITY COMMENTS
<u>9291191111 99111119</u>
<u> </u>