# Electric Distribution Utility Annual Reliability Report

## **SECTION 1: CONTACT INFORMATION**

UTILITY NAME Meade County RECC REPORT PREPARED BY Michael French E-MAIL ADDRESS OF PREPARER mfrench@mcrecc.com (270) 422-2162 PHONE NUMBER OF PREPARER

### **SECTION 2: REPORTING YEAR**

CALENDAR YEAR OF REPORT 2024

### **SECTION 3: MAJOR EVENT DAYS (MED)**

**TMED** 5.9975 FIRST DATE USED TO DETERMINE TMED 1/1/2019 LAST DATE USED TO DETERMINE TMED 12/31/2023 NUMBER OF MED IN REPORT YEAR

NOTE: Per IEEE 1366 TMED should be calculated using the daily SAIDI values for the five prior years. If five years of data are not available, then utilities should use what is available until five years are accumulated.

## **SECTION 4: SYSTEM RELIABILITY INFORMATION AND RESULTS**

## **System-wide Information**

TOTAL CUSTOMERS 31606 TOTAL CIRCUITS 86

## **Excluding MED**

**5 YEAR AVERAGE** REPORTING YEAR SAIDI 80.51 SAIDI 108.558501550339 SAIFI 0.83 SAIFI 1.28

## **Including MED**

**5 YEAR AVERAGE** REPORTING YEAR SAIDI 229.9 SAIDI 371.367461874328 SAIFI 1.17 SAIFI 1.91

#### Notes:

- 1) All duration indices (SAIDI) are to be reported in units of minutes.
- 2) Reports are due on the first business day of May of each year
- 3) Reports cover the calendar year ending in the December before the reports are due.
- 4) IEEE 1366 (latest version) is used to define SAIDI, SAIFI, and TMED

## **SECTION 5: CIRCUIT REPORTING**

(CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

CIRCUIT #1

	CITCOIT #	1						
	1. SUBSTA	HARDINSBURG1						
<ol> <li>SUBSTATION LOCATION (COUNTY-ROAD-TOWN)         Behind MCRECC's Hardinsburg Office</li> <li>CIRCUIT NAME AND NUMBER         Feeder 7</li> <li>CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)         Center of town West from office</li> <li>TOTAL CIRCUIT LENGTH (MILES)         2.42</li> <li>CUSTOMER COUNT FOR THIS CIRCUIT         145</li> <li>DATE OF LAST CIRCUIT TRIM (VM)         2020</li> </ol>								
	8.	Cause Pre-Arranged	Count 3	Percentage 100	Customer-Hours 29	Customer-Count 72	SAIDI 12.08	
	a CIPCLII	T 5 YEAR AVERAC	2E (QAII	וח			26.35	
	9. OII.OOI	1 3 TEAR AVERAC	JE (OAII	(וט			20.00	
	10. REPOI	RTING YEAR (SAII	OI)				12	
	11. CIRCU	JIT 5 YEAR AVERA	GE (SA	JFI)			0.27	
	12. REPOI	0.5						
	13. CORR	ECTIVE ACTION F	PLAN					
		Two pre-arranged	outage	s on 8/16/24	and one on 10/3/2	24		

#### **SECTION 5: CIRCUIT REPORTING**

### (CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #2

1. SUBSTATION NAME AND NUMBER

**IRVINGTON** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

North side of Irvington, take Kentucky St west off Hwy 79 approximately 0.5 miles to sub

3. CIRCUIT NAME AND NUMBER

Feeder 5

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

South of Irvington along US 60

5. TOTAL CIRCUIT LENGTH (MILES)

48.08

6. CUSTOMER COUNT FOR THIS CIRCUIT

7. DATE OF LAST CIRCUIT TRIM (VM)

2021

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Public, other	1	4.17	236	73	35.05	0.18
	Pre-Arranged	5	20.83	84	100	12.44	0.25
	Cause unknown	5	20.83	59	42	8.74	0.1
	Small animal/bird	4	16.67	59	33	8.72	80.0
	Tree out of R/W	1	4.17	2	2	0.29	0

9. CIRCUIT 5 YEAR AVERAGE (SAIDI)				

10. REPORTING YEAR (SAIDI) 65.29

11. CIRCUIT 5 YEAR AVERAGE (SAIFI) 0.18

12. REPORTING YEAR (SAIFI) 0.63

## 13. CORRECTIVE ACTION PLAN

On 7/5/24, a car struck a pole after a downline recloser causing 73 members to be out for approximately 3 hours while crews changed the pole.

#### **SECTION 5: CIRCUIT REPORTING**

### (CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

### (CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #3

1. SUBSTATION NAME AND NUMBER

**MCDANIELS** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

From Harned take Hwy 259 South approximately 10.6 miles to sub

3. CIRCUIT NAME AND NUMBER

Feeder 4

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

SE from Sub along Hwy 259 and South on Hwy 737

5. TOTAL CIRCUIT LENGTH (MILES)

41.88

6. CUSTOMER COUNT FOR THIS CIRCUIT

7. DATE OF LAST CIRCUIT TRIM (VM)

2022

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Public, other	4	7.27	1760	589	139.13	0.78
	Cause unknown	3	5.45	1140	1103	90	1.45
	Tree out of R/W	3	5.45	298	87	23.53	0.11
	Pre-Arranged	22	40	132	103	10.41	0.14
	Maintenance	1	1.82	79	207	6.2	0.27
9. CIRCUIT 5 YEAR AVERAGE (SAIDI) 122.64							

o. ontoon o letatottoe (orabi)	122.04
10. REPORTING YEAR (SAIDI)	279.5
11. CIRCUIT 5 YEAR AVERAGE (SAIFI)	1.13
12. REPORTING YEAR (SAIFI)	2.92

## 13. CORRECTIVE ACTION PLAN

On 7/25/24, a car struck a pole after a downline recloser causing 344 members to be out for approximately 4.5 hours while crews changed the pole.

On 1/14/24, a high side fuse blew creating a 1 hour outage. No cause was found after a thorough investigation.

#### **SECTION 5: CIRCUIT REPORTING**

(CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #4

1. SUBSTATION NAME AND NUMBER

**CLOVERPORT** 

1.16

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

Hwy 60 to Cloverport, turn on U.S. 60 Business into Cloverport then turn on L.M. Basham Road.

3. CIRCUIT NAME AND NUMBER

Feeder 4

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

West side of town

5. TOTAL CIRCUIT LENGTH (MILES)

6.19

6. CUSTOMER COUNT FOR THIS CIRCUIT

268

7. DATE OF LAST CIRCUIT TRIM (VM)

2023

	8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
		Tree out of R/W	1	5.26	200	261	45.8	1
		Pre-Arranged	10	52.63	58	23	12.99	0.09
		Cause unknown	3	15.79	10	13	2.25	0.05
		Small animal/bird	1	5.26	7	6	1.57	0.02
		Maintenance	1	5.26	5	3	1.12	0.01
9. CIRCUIT 5 YEAR AVERAGE (SAIDI)								
10. REPORTING YEAR (SAIDI)							64.03	
11. CIRCUIT 5 YEAR AVERAGE (SAIFI)							0.53	

## 13. CORRECTIVE ACTION PLAN

12. REPORTING YEAR (SAIFI)

On 3/1/24, a tree out of ROW fell onto a line outaging the entire feeder. 261 members were out for approximately 45 minutes.

The substation ROW was trimmed in 2023 and was sprayed in 2024. Relatively high reliably feeder. No further action is deemed necessary.

#### **SECTION 5: CIRCUIT REPORTING**

### (CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #5

1. SUBSTATION NAME AND NUMBER

**MCDANIELS** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

From Harned take Hwy 259 South approximately 10.6 miles to sub

3. CIRCUIT NAME AND NUMBER

Feeder 3

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

SE from Sub along Hwy 259 and NW on McCoy-Roff Rd.

5. TOTAL CIRCUIT LENGTH (MILES)

28.9

6. CUSTOMER COUNT FOR THIS CIRCUIT

384

7. DATE OF LAST CIRCUIT TRIM (VM)

2022

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Pre-Arranged	36	64.29	646	634	100.94	1.65
	Cause unknown	3	5.36	496	471	77.5	1.23
	Tree in R/W	1	1.79	225	91	35.81	0.24
	Tree out of R/W	4	7.14	166	156	26.01	0.41
	Small animal/bird	2	3.57	75	61	11.72	0.16

9. CIRCUIT 5 YEAR AVERAGE (SAIDI)	238.36
-----------------------------------	--------

10. REPORTING YEAR (SAIDI) 259.22

11. CIRCUIT 5 YEAR AVERAGE (SAIFI) 1.86

12. REPORTING YEAR (SAIFI) 3.78

## 13. CORRECTIVE ACTION PLAN

36 small pre-arranged outages for construction and maintenance.

On 1/14/24, a high side fuse blew creating a 1 hour outage. No cause was found after a thorough investigation.

#### **SECTION 5: CIRCUIT REPORTING**

### (CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #6

1. SUBSTATION NAME AND NUMBER

**IRVINGTON** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

North side of Irvington, take Kentucky St west off Hwy 79 approximately 0.5 miles to sub

3. CIRCUIT NAME AND NUMBER

Feeder 3

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

West side of town, South on Hwy 2202, East and West on Hwy 333

5. TOTAL CIRCUIT LENGTH (MILES)

28.99

6. CUSTOMER COUNT FOR THIS CIRCUIT

630

7. DATE OF LAST CIRCUIT TRIM (VM)

2021

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Motor vehicle	2	16.67	2405	1250	230.88	2
	Small animal/bird	4	33.33	83	131	7.97	0.21
	Storm	1	8.33	45	56	4.35	0.09
	Pre-Arranged	1	8.33	1	1	0.1	0

9. CIRCUIT 5 YEAR AVERAGE (SAIDI)	21.09
10. REPORTING YEAR (SAIDI)	241.33
11. CIRCUIT 5 YEAR AVERAGE (SAIFI)	0.37
12. REPORTING YEAR (SAIFI)	2.28

## 13. CORRECTIVE ACTION PLAN

On 11/5/24, a car struck a guy wire on a pole wrapping it around the primary wire outaging the entire feeder causing 625 members to be out for approximately 2 hours while crews changed the pole.

#### **SECTION 5: CIRCUIT REPORTING**

(CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

1/1 58

## CIRCUIT #7

1. SUBSTATION NAME AND NUMBER

Behind MCRECC's Hardinsburg Office

HARDINSBURG1

- 2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)
- 3. CIRCUIT NAME AND NUMBER

Feeder 3

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

East Side of town

5. TOTAL CIRCUIT LENGTH (MILES)

2.44

6. CUSTOMER COUNT FOR THIS CIRCUIT

169

7. DATE OF LAST CIRCUIT TRIM (VM)

Q CIRCUIT 5 YEAR AVERAGE (SAIDI)

2020

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Small animal/bird	2	33.33	369	138	131.01	0.82
	Pre-Arranged	4	66.67	37	12	13.21	0.07

5. CINCOTT 3 TEAN AVENAGE (SAIDT)	14.50
10. REPORTING YEAR (SAIDI)	144.14
11. CIRCUIT 5 YEAR AVERAGE (SAIFI)	0.2
12. REPORTING YEAR (SAIFI)	0.89

#### 13. CORRECTIVE ACTION PLAN

On 6/28/24 a small animal or bird blew a downline fuse outaging 69 members approximately 5 hours while crews searched for the animal.

#### **SECTION 5: CIRCUIT REPORTING**

## (CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #8

1. SUBSTATION NAME AND NUMBER

**BATTLETOWN** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

Approximately 1.5 miles North of Battletown

3. CIRCUIT NAME AND NUMBER

Feeder 3

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

North of Sub along Battletown Rd, Big Bend Rd, and West along Cedar Flat Rd.

5. TOTAL CIRCUIT LENGTH (MILES)

36.97

6. CUSTOMER COUNT FOR THIS CIRCUIT

151

7. DATE OF LAST CIRCUIT TRIM (VM)

2020

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Storm	3	13.04	366	152	144.47	1
	Tree out of R/W	4	17.39	289	157	114.83	1.04
	Weather, other	2	8.7	125	39	49.67	0.26
	Major Storms	2	8.7	13	19	5.17	0.13
	Pre-Arranged	3	13.04	13	45	5.17	0.3
9. CIRCUIT 5 YEAR AVERAGE (SAIDI)							
10. REPORTING YEAR (SAIDI)						322.65	
11. CIRCUIT 5 YEAR AVERAGE (SAIFI)						1.13	
12. REPORTING YEAR (SAIFI) 2.7							

## 13. CORRECTIVE ACTION PLAN

Several storms have affected this feeder throughout the year. All have been downline devices except for one outage on 4/19/24 that outaged the entire feeder for 1 hour.

On 1/19/24, 11/5/24, and 12/29/24 trees fell out of the ROW affecting the same downline recloser causing 52 members to be outaged approximately 5.5 hours in total. In all three cases wind was blowing strong.

ROW will be cut in this area in 2025 and danger trees will be looked at.

#### **SECTION 5: CIRCUIT REPORTING**

## (CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #9

1. SUBSTATION NAME AND NUMBER

**MCDANIELS** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

From Harned take Hwy 259 South approximately 10.6 miles to sub

3. CIRCUIT NAME AND NUMBER

Feeder 2

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

North along Hwy 259 and East along Hwy 690

5. TOTAL CIRCUIT LENGTH (MILES)

56.44

6. CUSTOMER COUNT FOR THIS CIRCUIT

910

7. DATE OF LAST CIRCUIT TRIM (VM)

2022

DI SAIFI
5 1.06
3 0.35
6 0.23
0.21
0.19

9. CIRCUIT 5 YEAR AVERAGE (SAIDI)	9.21
-----------------------------------	------

10. REPORTING YEAR (SAIDI) 150.42

11. CIRCUIT 5 YEAR AVERAGE (SAIFI) 0.56

12. REPORTING YEAR (SAIFI) 2.11

#### 13. CORRECTIVE ACTION PLAN

On 1/14/24, a high side fuse blew creating a 1 hour outage. No cause was found after a thorough investigation.

#### **SECTION 5: CIRCUIT REPORTING**

### (CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

### (CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #10

1. SUBSTATION NAME AND NUMBER

HARDINSBURG1

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

Behind MCRECC's Hardinsburg Office

3. CIRCUIT NAME AND NUMBER

Feeder 2

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

NW along Hwy 259

5. TOTAL CIRCUIT LENGTH (MILES)

30.27

6. CUSTOMER COUNT FOR THIS CIRCUIT

307

7. DATE OF LAST CIRCUIT TRIM (VM)

2020

8. Cause Storm Motor vehicle Cause unknown Pre-Arranged Tree out of R/W	Count 6 2 3 2 1	Percentage 37.5 12.5 18.75 12.5 6.25	Customer-Hours 2208 644 40 7	Customer-Count 1130 534 43 10 2	SAIDI 430.13 125.45 7.79 1.36 1.37	3.67	
0. CIDCUIT 5 VEAD AVEDACE (SAIDI)							

9. C	CIRCUIT 5 YEAR AVERAGE (SAIDI)	37.15

10. REPORTING YEAR (SAIDI) 568.73

11. CIRCUIT 5 YEAR AVERAGE (SAIFI) 0.62

12. REPORTING YEAR (SAIFI) 5.61

## 13. CORRECTIVE ACTION PLAN

Several storms have affected this feeder throughout the year. All have been downline devices except for one outage on 8/1/24 that outaged the entire feeder for 1 hour.

On 9/30/24, a car struck a pole after a downline recloser causing 267 members to be out for approximately 2 hours while crews changed the pole.

#### **SECTION 5: CIRCUIT REPORTING**

(CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #11

1. SUBSTATION NAME AND NUMBER

**CLOVERPORT** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

Hwy 60 to Cloverport, turn on U.S. 60 Business into Cloverport then turn on L.M. Basham Road.

3. CIRCUIT NAME AND NUMBER

Feeder 2

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

East along Hwy 60 and North along Hwy 144

5. TOTAL CIRCUIT LENGTH (MILES)

26.47

6. CUSTOMER COUNT FOR THIS CIRCUIT

193

7. DATE OF LAST CIRCUIT TRIM (VM)

2023

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Weather, other	2	13.33	857	258	265.05	1.33
	Tree out of R/W	1	6.67	29	7	9.21	0.04
	Storm	2	13.33	18	10	5.6	0.05
	Pre-Arranged	3	20	13	6	4.04	0.03
	Cause unknown	1	6.67	6	4	1.87	0.02

9. CIRCUIT 5 YEAR AVERAG	SE (SAIDI)	58.23

10. REPORTING YEAR (SAIDI) 287.56

11. CIRCUIT 5 YEAR AVERAGE (SAIFI) 0.89

12. REPORTING YEAR (SAIFI) 1.49

#### 13. CORRECTIVE ACTION PLAN

On 12/5/24, a tree out of ROW fell onto a line due to wind outaging 129 members for approximately 3 hours.

#### **SECTION 5: CIRCUIT REPORTING**

(CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

#### CIRCUIT #12

1. SUBSTATION NAME AND NUMBER

**BATTLETOWN** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

Approximately 1.5 miles North of Battletown

3. CIRCUIT NAME AND NUMBER

Feeder 2

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

SE along Battletown Rd.

5. TOTAL CIRCUIT LENGTH (MILES)

42.78

6. CUSTOMER COUNT FOR THIS CIRCUIT

358

7. DATE OF LAST CIRCUIT TRIM (VM)

2020

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Public, other	4	18.18	841	743	140.95	2.08
	Storm	2	9.09	337	183	57.77	0.52
	Construction	2	9.09	49	7	8.21	0.02
	Tree out of R/W	1	4.55	21	4	3.54	0.01
	Cause unknown	2	9.09	19	17	3.18	0.05

9. CIRCUIT 5 YEAR AVERAGE (SAIDI)	49.76
-----------------------------------	-------

10. REPORTING YEAR (SAIDI) 216.54

11. CIRCUIT 5 YEAR AVERAGE (SAIFI) 0.56

12. REPORTING YEAR (SAIFI) 2.72

## 13. CORRECTIVE ACTION PLAN

On 9/10/24, an excavator working on the road got into the line outaging the entire feeder causing 358 members to be outaged for approximately 1.5 hours as crews worked to fix the wire. No one was injured and a full investigation was performed.

Several storms have affected this feeder throughout the year. All have been downline devices except for one outage on 4/19/24 that outaged the entire feeder for approximately 2 hours.

#### **SECTION 5: CIRCUIT REPORTING**

## (CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #13

1. SUBSTATION NAME AND NUMBER

**IRVINGTON** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

North side of Irvington, take Kentucky St west off Hwy 79 approximately 0.5 miles to sub

3. CIRCUIT NAME AND NUMBER

Feeder 1

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

North along Hwy 79 and East along Guston Rd.

5. TOTAL CIRCUIT LENGTH (MILES)

20.44

6. CUSTOMER COUNT FOR THIS CIRCUIT

249

7. DATE OF LAST CIRCUIT TRIM (VM)

2021

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Storm	1	7.14	58	57	14.15	0.23
	Small animal/bird	3	21.43	45	43	10.89	0.17
	Pre-Arranged	3	21.43	35	26	8.5	0.11
	Cause unknown	3	21.43	32	42	7.77	0.17

9. CIRCUIT 5 YEAR AVERAGE (SAIDI)	16.46
10. REPORTING YEAR (SAIDI)	40.96
11. CIRCUIT 5 YEAR AVERAGE (SAIFI)	0.43
12. REPORTING YEAR (SAIFI)	0.67

#### 13. CORRECTIVE ACTION PLAN

Relatively high reliably feeder and substation; therefore no action is deemed necessary.

#### **SECTION 5: CIRCUIT REPORTING**

(CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #14

1. SUBSTATION NAME AND NUMBER

**FORTAVENUE** 

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

Approximately 2 miles north of the intersection of Hwy 313 and Ky-1882 (Fort Ave)

3. CIRCUIT NAME AND NUMBER

Feeder 1

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

N Hwy 1882, W Hwy 1816, N Hwy 2726

5. TOTAL CIRCUIT LENGTH (MILES)

4.94

6. CUSTOMER COUNT FOR THIS CIRCUIT

57

7. DATE OF LAST CIRCUIT TRIM (VM)

2020

8.	Cause	Count	Percentage	Customer-Hours	Customer-Count	SAIDI	SAIFI
	Pre-Arranged	3	30	17	8	18.21	0.14
	Cause unknown	3	30	5	6	5.17	0.1
	Storm	1	10	1	2	1.07	0.04

9. CIRCUIT 5 YEAR AVERAGE (SAIDI)	12.05
10. REPORTING YEAR (SAIDI)	24.21
11. CIRCUIT 5 YEAR AVERAGE (SAIFI)	0.04
12. REPORTING YEAR (SAIFI)	0.28

#### 13. CORRECTIVE ACTION PLAN

Relatively high reliably feeder and substation; therefore no action is deemed necessary.

#### **SECTION 5: CIRCUIT REPORTING**

(CIRCUITS WITH SAIDI AND/OR SAIFI EXCEEDING 5 YEAR AVERAGE)

(CIRCUIT NUMBERS SHOULD BE REPORTED EXCLUDING MED)

## CIRCUIT #15

1. SUBSTATION NAME AND NUMBER

**ANDYVILLE** 

1.94

2. SUBSTATION LOCATION (COUNTY-ROAD-TOWN)

Approximately 500 ft. N of the intersection of Hwy 144 and Hwy 228

3. CIRCUIT NAME AND NUMBER

Feeder 1

4. CIRCUIT LOCATION (TOWN-ROAD-GENERAL AREA)

North along Wolf Creek Rd.

5. TOTAL CIRCUIT LENGTH (MILES)

43.96

6. CUSTOMER COUNT FOR THIS CIRCUIT

280

7. DATE OF LAST CIRCUIT TRIM (VM)

2024

8.	Cause Cause unknown Tree out of R/W Storm Conductor sag or Public, other	4 6 6	Percentage 16.67 25 25 4.17 16.67	Customer-Hours 545 216 207 90 32	Customer-Count 319 98 87 30 23	114.74 44.69 43.43	
9. CIRC	CUIT 5 YEAR AVERAG	SE (SAI	DI)			53.53	

10. REPORTING YEAR (SAIDI)	227.13
11. CIRCUIT 5 YEAR AVERAGE (SAIFI)	0.6

#### 13. CORRECTIVE ACTION PLAN

12. REPORTING YEAR (SAIFI)

On 1/8/24, an outage occurred affecting the entire feeder. 284 members were out for approximately 1 hour and 45 minutes while crews tried to determine the cause. Nothing was found.

Relatively high reliably feeder and substation; therefore no action is deemed necessary.

#### SECTION 6: VEGETATION MANAGEMENT PLAN REVIEW

INCLUDE CURRENT VEGETATION MANAGEMENT PLAN
Additional page may be attached as needed

Meade County RECC's vegetation management practices have continued to benefit our reliability figures and reduce outages." "For example, trees in ROW events only
contributed 0.0153 to SAIFI and 12.7331 to SAIDI. Currently, there is no anticipated
change to the existing ROW program. We continue to monitor risks associated with
dead ash trees from the emerald ash borer, which are starting to be a concern related to
power outages and other power disturbances. We are addressing this issue within our
ROW program, in addition to removing danger trees identified by our crews.

## **SECTION 7: UTILITY COMMENTS**

Weather events continue to be one of the greatest causes for power disturbances at Meade County RECC, thus impacting our reliability figures. Excluding weather disturbances, Meade County RECC reliability numbers have remained strong. However, our power outage data reveals vehicle incidents are problematic to our electric distribution system as we encounter several damage poles due to vehicle incidents. The other contributor to our reliability metrics is pre-arranged power outages as we continue to invest into our distribution system. These events require deliberate deenergized conditions to safely repair or build distribution services within our system.