

Panyrile Area Development District a regional planning and development agency

300 Hammond Drive, Hopkinsville, KY 42240

voice (270) 886-9484 fax (270) 886-3211

www.peadd.org

email peadd@peadd.org

January 25, 2021

Mayor Mike Jones City of Drakesboro P.O. Box 129 Drakesboro, KY 42337

RE:

Drakesboro Natural Gas System Rehabilitation Project

Dear Mayor Jones,

This letter is to certify that the City of Drakesboro has submitted an application for assistance under the 2020 Community Development Block Grant Program (CDBG) for assistance in the rehabilitation of the natural gas system that serves Drakesboro and the surrounding community. The application was submitted by the Pennyrile Area Development District on behalf of the City in July 2020. Additional information was request by the Department for Local Government (DLG) concerning the application; the response for the request for information was submitted on December 14, 2020.


As of the date of this letter, DLG has not made funding decisions or announcements concerning the project applications that were received under the 2020 CDBG Program. The Pennyrile Area Development District will continue to work with the City of Drakesboro to pursue funding options for the natural gas system rehab project.

If we can provide additional information or assistance to the City, please don't hesitate to contact us.

Sincerely,

Amy Frogue

Associate Director, CED



CIT OF DRAKESBORO

P.O. Box 129 • Mose Rager Blvd. • Drakesboro, KY 42337 270-476-8986 (888) 662 – 2406 (Voice/TTY); (866) 557 – 5762 (Español

Melissa,

The City of Drakesboro natural gas system had 4 areas with exposed gas lines. We fixed 2 of these areas on January $18^{th}/19^{th}$, 2021.

The exposed pipe was covered with tubing, concrete, and dirt until no longer exposed.

We plan to fix the remaining 2 areas as soon as possible using the same method.

We have attached pictures of the exposed areas before and after it was corrected.

We will continue to patrol the remaining areas until they are corrected at which time, we will send you work orders and pictures of the work done.

Thank you,


Mayor: Mike Jones

PATROLLING OF PIPELINE SYSTEM

	Form 4
COMPANY: City of Drckesboro	
Period Covered: Began Ended	
Areas Covered: Union Bidge Exposed #2	
Map References:	
Leakage Indications Discovered (describe locations and indications, such as a condition of vegeta	
No leaks found.	
Describe any unusual conditions at highway and railroad crossings:	
Follow-up (repairs, maintenance or test resulting from this inspection): Exposed pipe ha loven covered up. Specyed, the polly pipe with 4" flex pipe. Covered with diff. Padded with concrete bags, then dressed with ciff (aff.	5
Comments: This location will be removed from the patrolling li	<i>SF</i>
Number of Persons in Patrol Party: 2	
Signature of Person in Charge of Patrol Party:	
Date: $\frac{1-12}{-2}$	

	Gas Service Work Order Work Type: Repair		
Location/Address: Unfon Bidge exposed	#2 Facility Classification: Distribution		
Leak Information			
Date Discovered: 4/14 How Discovered	: Costomer Reported To: Drakes boro Utilities		
Leak Grade: CGI Used? Percentage	of Gas(%Gas in Air): Graded By:		
Description of Leak:			
Cause of Leak:			
Corrosion Incorrect-Operations Atmospheric Human Error	Other Outside Force Dig In		
Atmospheric Human Error External Internal Internal	External Loading Fire/Explosion Information of Excavator Vandalism Vehicle Other		
Natural Forces Equipment Failure	Material and Welds Was 811 Called:		
Earthquake Excess Flow Valve Earth/Rock Movement Filter Flood Flow/Pressure Controller Meter Casing Landslide Regulator/Relief Valve Lightning Threads Tornado Valve Washout Other Excess Flow Valve Filter Flow/Pressure Controller Meter Casing Regulator/Relief Valve Valve Other	Flange Mechanical Fitting Fipe Plastic Fusion Coupling Plastic Dresser Plastic to Steel Transition Screw Fitting Tap Tee Workmanship Defect Other		
Pipe Information			
Pipe Size: Pipe Material: Polly	Coating: Pipe-Condition: EFV		
Corrosion Information	V IN		
Cathodic Protection: Pipe to Soil Rea	ding: Coupons Taken:		
External Condition: Pit Depth:	Internal Condition: Pit Depth:		
Anodes Installed: Anode type: Repair	Coating 1: Repair Coating 2:		
Depth of Cover: Feet Inches Soil Conc	lition: Soil Packing:		
Repair Information			
Repair Method: Coursed Date Repaired:	Repaired By:		
Description of Repair: Exposed pipe Sleeved in flet, covered with dart, concrete, + fift raff.			
Test Information	, , ,		
Length of Pipe FT Test Type:	Test Medium: X-Ray(STEEL):		
Test Start Date/Time: Pressure at Start:	Pressure Loss: Operating Pressure lbs		
Test End Date/Time: Pressure at End:	Operating Pressure:		
Reason for Loss:	Corrections Made:		
Other			
Other Information: Section of Tipe no	longer needs patrolling.		
Cleared By: Well 800	Date: 1-14-2(

CIT OF DRAKESBORO



P.O. Box 129 · Mose Rager Blvd. · Drakesboro, KY 42337 270-476-8986

(888) 662 - 2406 (Voice/TTY); (866) 557 - 5762 (Español)


Drakesboro W	ork Order Work Order #:
Date: <u>/-/-/-a/</u> Time: Gas	s Water WW Acct #:
Name:	Mobile Number:
Address: Union Ridge Exposed # 2.	
Work to be Done:	
New Meter#	New Reading
Turn on & Read	Old Reading
Read and Lock	Set Meter and Lock
Reading Only	Locate Line (See Below)
Read and Lock (Nonpayment)Number	Get Meter
Check Pressure	Flush Line Check & Leak
Unlock Only and Read (Do Not Turn On)	
Special Instructions Exposed Pipe need Work Done:	
Flushed: Yes No GPM:	How Long: Water Logs:
Water Leak: Yes No GPM:	
Parts Used to Complete Job:	
4" Flex Pipe	
Dirt, Concrete, Riff Baff.	
Comments: Dug out around exposed	1 pipe. Split flex pipe, and
Steeved the expored pipe. Then pas	ded with dirt, Padded with
concrete bags, then dressed with	riff raff.
Work Completed By: Well 80	Date Completed: /-/4-21
Time Started:	Time Ended:

PATROLLING OF PIPELINE SYSTEM

Form 4
COMPANY: City of Drakeshoro
Period Covered: Began Ended
Areas Covered: Union Ridge Exposed #1
Map References: \mathcal{N}/\mathcal{A}
Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
No lecks found
Describe any unusual conditions at highway and railroad crossings:
Other Factors noted which could affect present or future safety or operations of the gas system:
Follow-up (repairs, maintenance or test resulting from this inspection): Exposed Section Of Dipe has been covered. Pipe was encased with 4" flet Pipe: Covered with dirt. Padded with concrete bags, ther dressed with riff raft.
Comments: This location will be removed from the patrolling
Number of Persons in Patrol Party:
Signature of Person in Charge of Patrol Party:
vale: (- (- / - 0)

Gas Service Work O. Work Type: Repair Union Ridge Expose Location/Address: Facility Classification: Leak Information Date Discovered: How Discovered: Customer Reported To: Drakerboro Utili Leak Grade: CGI Used? Percentage of Gas(%Gas in Air): Graded By: Description of Leak: Cause of Leak: Corrosion Incorrect-Operations **Other Outside Force** ☐ Dig In Atmospheric Human Error External Loading External Information of Excavator Ineffective Procedures Fire/Explosion Internal Vandalism Vehicle Other Was 811 Called: **Natural Forces** Equipment Failure . **Material and Welds** Earthquake Excess Flow Valve Flange Earth/Rock Movement Explain Other Filter Mechanical Fitting Flood Flow/Pressure Controller Pipe Frost Heave Plastic Fusion Coupling Meter Casing Landslide Regulator/Relief Valve Plastic Dresser Lightning Threads Plastic to Steel Transition Fornado Valve Screw Fitting Washout Other Tap Tee Other Workmanship Defect Other Pipe Information Pipe Material: Polly Pipe Size: Coating: Pipe Condition: **EFV** Corrosion Information Cathodic Protection: Pipe to Soil Reading: Wall Thickness: Coupons Taken: External Condition: Pit Depth: Internal Condition: Pit Depth: Anodes Installed: Anode type: Repair Coating 1: Repair Coating 2: Depth of Cover: Feet Soil Condition: Moisture: Soil Packing: Inches Repair Information Repair Method: Date Repaired: Repaired By: Description of Repair: concrete Riff Baff. **Test Information** Test Type: Length of Pipe Test Medium: X-Ray(STEEL): lbs Test Start Date/Time: Pressure at Start: Pressure Loss: lb Operating Pressure: lbs lbs Test End Date/Time: Pressure at End: Amount of Loss Reason for Loss: Corrections Made: Other Other Information: longer needs NO Cleared By: Date:

CIT OF DRAKESBORO



P.O. Box 129 • Mose Rager Blvd. • Drakesboro, KY 42337 270-476-8986 (888) 662 – 2406 (Voice/TTY): (866) 557 – 5762 (Español)

Drakesboro W	ork Order Work Order #:		
Date: <u>/-/4-2/</u> Time: Ga	S Water WW Acct #:		
Name:	Mobile Number:		
Name:Address: Onion Bidge Exposed Pil	Pe #1		
Work to be Done:			
New Meter#	New Reading		
Turn on & Read	Old Reading		
Read and Lock	Set Meter and Lock		
Reading Only	Locate Line (See Below)		
Read and Lock (Nonpayment)Number	Get Meter		
Check Pressure	Flush Line Check & Leak		
Unlock Only and Read (Do Not Turn On)			
Special Instructions Exposed pipe needed to be covered up.			
Work Done:			
Flushed: Yes No GPM:	How Long: Water Logs:		
Water Leak: Yes No GPM:	How Long: Water Logs:		
Parts Used to Complete Job:			
4" FILL Pipe.			
Dirt, concretes Riff Raff			
Comments: Dug out around expos	ed pipe. Split flex pipe, and		
encased exposed gas line. Then Padde			
concrete bags over over, then dre	essed with riff raff.		
Work Completed By: Del Str	Date Completed: 1-14-21		
Time Started:	Time Ended:		