

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 3/25/22 Ended 3/25/22

Areas Covered: DITCH LINE @ 431s IN BEECHMONT  
ACROSS FROM DOLLAR STORE

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" STEEL LINE ~~ON~~ FEEDING WESTER ST.

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: AREA IS MONITORED WITH CGI EVERY DAY  
TO CHECK FOR LEAKS;

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Ry Alled

Date: 3/25/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 3/25/22 Ended 3/25/22

Areas Covered: DITCH LINE @ 431'S NEXT TO W&R HEAT

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS FOUND

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" STEEL LINE @ DITCH

Follow-up (repairs, maintenance or test resulting from this inspection):  
LINE IS ONLY PARTLY COVERED AND WRAPPED

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 3/25/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESROCK

Period Covered: Began 3/25/22 Ended 3/25/22

Areas Covered: DITCH LINE NEXT TO OLD DOLLAR STORE @ BEECHMONT

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

4" GAS MAIN CROSSING DITCH

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: PIPE IS INSIDE PVC AND RIFF RAFF / CONCRETE FOR PROTECTION

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: R. Alford

Date: 3/25/22