

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: City of Drakesboro

Period Covered: Began 8-8-19 9:45am Ended 8-8-19 9:52am

Areas Covered: Wyatt's Chapel Cemetery Rd.

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
No Leak Found.

Describe any unusual conditions at highway and railroad crossings: None

Other Factors noted which could affect present or future safety or operations of the gas system:  
1/2" Polly Service Line, Exposed in 3 places on ditch line that washes out. Exposed places are very close to each other, approximately 8"-10" in each spot within a 12' section.

Follow-up (repairs, maintenance or test resulting from this inspection):  
Preperations to try to fix wash out and re-cover the exposed section of pipe are being made.

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: James D. [Signature]

Date: 8-8-19

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: City of Drakeboro

Period Covered: Began 8-8-19 9:55 am Ended 8-8-19 10:10 am

Areas Covered: Wyatt's Chapel Cemetery Rd.

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
No Leak Found.

Describe any unusual conditions at highway and railroad crossings: None.

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" Polly Pipe exposed in a ditch.  
18" section of pipe 32" deep. Ditch has  
washed out and exposed top half of the pipe.

Follow-up (repairs, maintenance or test resulting from this inspection):  
Preparations are made to cover this section  
of pipe.

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: David S. Co

Date: 8-8-19

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: City of Drakesboro

Period Covered: Began 8-8-19 10:50 am Ended 8-8-19 11:00 am

Areas Covered: Union Ridge Road. Exposed #1

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
No Leak Found

Describe any unusual conditions at highway and railroad crossings: None

Other Factors noted which could affect present or future safety or operations of the gas system:  
1 1/4" Polly Pipe Exposed next to tile in a ditch.  
27" are exposed at about 37 inches deep.

Follow-up (repairs, maintenance or test resulting from this inspection):  
Plans are being discussed to bury pipe below ditch line.

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: James S. O

Date: 8-8-19

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: City of Drakesboro

Period Covered: Began 8-8-19 11:05 am Ended 8-8-19 11:09 am

Areas Covered: Union Bridge Rd. Exposed #2

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
No Leak Found.

Describe any unusual conditions at highway and railroad crossings: None.

Other Factors noted which could affect present or future safety or operations of the gas system:  
1/4" Poly pipe laying exposed in a ditch next to tile entrance. 3 1/2 Ft of pipe exposed, and to the ditch bank its about 49 inches deep.

Follow-up (repairs, maintenance or test resulting from this inspection):  
Plans are being made to bury piped below ditch levels.

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Daniel J. [Signature]

Date: 8-8-19

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: City of Drakesboro

Period Covered: Began 8-8-19 8:30am Ended 8-8-19 8:45 am

Areas Covered: US 431 South, Next to W/R Heating & Cooling.

Map References: NA

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
No leaks Found

Describe any unusual conditions at highway and railroad crossings: None.

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" Steel Main Exposed in a ditch. Main crossed ditch from one bank to the next above water levels. But at only 23" Deep.

Follow-up (repairs, maintenance or test resulting from this inspection):  
Main has been cleaned, and wrapped w/ pipe tape from ditch bank to ditch bank. This pipe is checked pretty often.

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: David [Signature]

Date: 8-8-19