

Gas Pipeline Inspection


Address: 48 BEECHCREEK/BROWDER **Location:**

Material	Pipe Condition	Visual/Pitting	Coating
Steel /	Excellent	Localized	Millwrap /
PE	Good /	General	Enamel
Cast Iron	Slight Pitting	Other	Roskete
CSST	Extreme Pitting	Fitting Depth	Oridemp
Main	Hole/Voids		Xtracoat
Service	graphitization		Mastic
Other	Bent		Cold Roll
	Broke		Hot Wrap
	Other		Heat Shrink

Affected Pipe Condition	Soil Type	Soil Condition	Work Performed
Good /	Rock /	Dry /	Main Ext.
Poor	Cinder	Wet/Swampy	Service Tap
Damaged	Clay /	Normal	Leak Repair /
Other	Loam	Moister Range (3-5)	Re-routing
	Sand	Moister Range(5-8)	Third Party
	Alluvion		Abandonment
	Other		Deactivation
			Utility Theft
			Other

Discription	Comments
2" STEEL LINE	LEAK WAS FOUND DURING SURVEY. WAS DUG UP AND A CLAMP WAS PUT ON. TESTED GOOD AND BACKFILED WITH SAND / GRAVEL

Visual Discription



Name: B. Alled **Date:** 9/9/21

Gas Pipeline Inspection

Address: 1576 US RT 4315


Location:

Material	Pipe Condition	Visual/Pitting	Coating
Steel	Excellent	Localized	Millwrap
PE	Good	General	Enamel
Cast Iron	Slight Pitting	Other	Roskete
CSST	Extreme Pitting	Fitting Depth	Oridemp
Main	Hole/Voids		Xtracoat
Service	graphitization		Mastic
Other	Bent		Cold Roll
	Broke		Hot Wrap
	Other		Heat Shrink

Affected Pipe Condition	Soil Type	Soil Condition	Work Performed
Good	Rock	Dry	Main Ext.
Poor	Cinder	Wet/Swampy	Service Tap
Damaged	Clay	Normal	Leak Repair
Other	Loam	Moister Range (3-5)	Re-routing
	Sand	Moister Range(5-8)	Third Party
	Alluvion		Abandonment
	Other		Deactivation
			Utility Theft
			Other

Discription	Comments
4" STEEL MAIN	LEAK WAS DETECTED DURING SURVEY. REPLACED 6' OF STEEL LINE & TAP. WELD WAS TESTED AND BACKFILLED WITH GRAVEL SAND

Visual Discription



Name: B. Alled

Date: 9/7/21