

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began \_\_\_\_\_ Ended \_\_\_\_\_

Areas Covered: DITCH C 4315 NEXT TO W/IZ HEATING

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAK/DAMAGE

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" STEEL LINE CROSSING DITCH

Follow-up (repairs, maintenance or test resulting from this inspection):  
LINE IS WRAPPED WITH WAX WRAP

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 9/23/21

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 9/23/21 Ended 9/23/21

Areas Covered: DITCH ACROSS FROM DOLLAR STORE @  
431 WESTERS

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" STEEL LINE CROSSES DITCH

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alced

Date: 9/23/21

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 9/23/21 Ended 9/23/21

Areas Covered: DITCH LINE @ 431 NEXT TO OLD DOLLAR STORE.

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
4" GAS MAIN (STEEL) CROSSING DITCH LINE. LINE HAS PVC PROTECTING WITH ROCK / CONCRETE

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 9/23/21