Case No. 2023-00422 Attachment 2 to Response to PSC-1 Question No. 17 Page 1 of 2 Bellar

Acronyms for Geoforce PITP Work

Pole Units

M, MC, MO – Molding DP – Digital Photo CR - Computerized Reports F - Fumigant Holes I – Internal Treatment G – Guy Marker GRR – Ground Rod Re-drive EX – External Treatment W - Ground Wire repair NUM - Stencil

Decay Code

Internal Decay – ID Internal Decay Above Groundline – IDAG Internal Decay at Groundline – IDGL Internal Decay Below Groundline – IDBG External Decay Above Groundline – EXAG External Decay at Groundline – EXGL External Decay Below Groundline - EXBG Hollow Heart - HH External Pocket - EP Internal Pocket - IP Rotten Butt - RB Shell Rot Chip - SRC Shell Rot Shave – SRS

Inspection Code

Visual – V Visual Foreign – V/F Visual Reject – VX Sound & Bore – B Bore Decay – BD Bore Reject – BX Treat Decay – TD Treat Excavated (T) Treat Reject – TX PreviReinforced/Treated - PD

Case No. 2023-00422 Attachment 2 to Response to PSC-1 Question No. 17 Page 2 of 2 Bellar

Rejection Code

- PR Priority Reject replace with in thirty days
- RP1 Reject priority one replace in a six-month period
- RP2 Reject priority two- replace in a one-year period
- RP3 Reject priority three- replace in a two-year period
- RR Reinforceable Reject