

March 21, 2017

Ms. Talina Mathews Executive Director Public Service Commission of Kentucky 211 Sower Boulevard Frankfort, KY 40602

Subject: Administrative Case No. 2011-00450

Kennett & Stock

Dear Ms. Mathews:

This letter is provided to serve notice that Kenergy has completed and submitted the 2016 Electric Distribution Utility Annual Reliability Report pursuant to Administrative Case Number 2011-00450.

The report accompanies this letter for your review. Please contact me at 270-689-6160 with any questions regarding this report.

Sincerely,

Kenneth R Stock VP of Operations

### Electric Distribution Utility Annual Reliability Report

### **SECTION 1: CONTACT INFORMATION**

UTILITY NAME

Kenergy Corp.

REPORT PREPARED BY

Kenneth Stock, Robert Hayden, Kevin Holland

E-MAIL ADDRESS OF PREPARER

rhayden@kenergycorp.com

PHONE NUMBER OF PREPARER

800-844-4832

#### **SECTION 2: REPORTING YEAR**

CALENDAR YEAR OF REPORT

2016

### **SECTION 3: MAJOR EVENT DAYS (MED)**

 $T_{MED}$ 

7.53

FIRST DATE USED TO DETERMINE  $\mathsf{T}_{\mathsf{MED}}$ 

1/1/2011

LAST DATE USED TO DETERMINE  $T_{\text{MED}}$ 

12/31/2015

NUMBER OF MED IN REPORT YEAR

5

NOTE: Per IEEE 1366  $T_{MED}$  should be calculated using the daily SAIDI values for the five prior years. If five years of data are not available, then utilities should use what is available until five years are accumulated.

#### SECTION 4: SYSTEM RELIABILITY INFORMATION AND RESULTS

#### **System-wide Information**

TOTAL CUSTOMERS 56,813 TOTAL CIRCUITS 195

### Excluding MED

5 YEAR AVERAGE		REPORTING YEAR		
SAIDI	106.37	SAIDI	83.60	
SAIFI	1.61	SAIFI	1.15	

### **Including MED**

	5 YEAR AVERAGE	REPORTING YEAR		
SAIDI	148.37	SAIDI	214.17	
SAIFI	1.82	SAIFI	1.73	

#### Notes:

- 1) All duration indices (SAIDI) are to be reported in units of minutes.
- 2) Reports are due on the first business day of May of each year
- 3) Reports cover the calendar year ending in the December before the reports are due.
- 4) IEEE 1366 (latest version) is used to define SAIDI, SAIFI, and T<sub>MED</sub>

### SEE ADDITIONAL TABS.

### SECTION 6: VEGETATION MANAGEMENT PLAN REVIEW INCLUDE CURRENT VEGETATION MANAGEMENT PLAN

Additional page may be attached as needed.

Kenergy's vegetation management efforts are continually evaluated to ensure adequacy and effectiveness. During 2016, approximately 1,100 miles of line were cleared which is consistent with the cycle length outlined in Kenergy's Vegetation Management Plan (not to exceed six years). The 2017 scope of work has been developed and is also consistent with Kenergy's cycle length. At this point, Kenergy does not anticipate any significant modifications to the vegetation management program in 2017.

#### **SECTION 8: UTILITY COMMENTS**

In section 5, "Resolved at time of outage" means that the issue, whether a mechanical failure, public hit pole, tree on the line, animal with guard being installed, or any other means where the issue was corrected and is most likely not going to repeat.

Section 5:1 Substation name and Number--- Adams Lane 106

Section 5:2 Substation Location--- County---Henderson Road---US Hwy 41 Town---Henderson

Section 5:3 Circuit Name and Number--- Happy Acres Feeder 1

Section 5:4 Circuit Location--- Hwy 41 South

Section 5:5Total Circuit Length----16.43Section 5:6Member count for this circuit----223Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	22.2%	0.0%	11.1%	66.7%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.175676
Section 5:10	Reporting year (SAIDI)	0.295572
Section 5:11	Circuit 5 year average (SAIFI)	0.002843
Section 5:12	Reporting year (SAIFI)	0.005374

Section 5:13 List of corrective action, if any, taken or to be taken--- Installed critter guard, Circuit scheduled for inspection

Section 5:1 Substation name and Number--- Adams Lane 106

Section 5:2 Substation Location--- County---Henderson Road---US Hwy 41 Town---Henderson

Section 5:3 Circuit Name and Number--- Adams Lane Feeder 2
Section 5:4 Circuit Location--- Carriage Home Park

Section 5:5Total Circuit Length----36.06Section 5:6Member count for this circuit---448Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	25.0%	0.0%	25.0%	37.5%	12.5%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.357577
Section 5:10	Reporting year (SAIDI)	0.519743
Section 5:11	Circuit 5 year average (SAIFI)	0.005304
Section 5:12	Reporting year (SAIFI)	0.008627

Section 5:13 List of corrective action, if any, taken or to be taken--- Installed critter guard, Circuit scheduled for inspection

Section 5:1 Substation name and Number--- Adams Lane 106

Section 5:2 Substation Location--- County---Henderson Road---US Hwy 41 Town---Henderson

Section 5:3Circuit Name and Number---Cresline Feeder 3Section 5:4Circuit Location---Cresline Plastics

Section 5:5Total Circuit Length----3.01Section 5:6Member count for this circuit---29Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	25.0%	0.0%	0.0%	50.0%	0.0%	25.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.012328
Section 5:10	Reporting year (SAIDI)	0.040447
Section 5:11	Circuit 5 year average (SAIFI)	0.000228
Section 5:12	Reporting year (SAIFI)	0.000689

Section 5:13 List of corrective action, if any, taken or to be taken--- Installed critter guard, Circuit scheduled for inspection

Section 5:1 Substation name and Number--- Beda 41

Section 5:2 Substation Location--- County---Ohio Road---Hwy 136 Town---Hartford

Section 5:3 Circuit Name and Number--- 231 North Feeder 1

Section 5:4 Circuit Location--- 231 N, Beda, Shinkle Chapplel Rd

Section 5:5Total Circuit Length----67.61Section 5:6Member count for this circuit---512Section 5:7Date of last circuit trim (VM)2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	8.8%	11.8%	8.8%	41.2%	20.6%	2.9%	5.9%

Section 5:9	Circuit 5 year average (SAIDI)	1.780942
Section 5:10	Reporting year (SAIDI)	4.191004
Section 5:11	Circuit 5 year average (SAIFI)	0.012614
Section 5:12	Reporting year (SAIFI)	0.014726

**Section 5:13** List of corrective action, if any, taken or to be taken---

System improvement work order scheduled, VM to trim circuit, Circuit scheduled for inspection

.

Section 5:1 Substation name and Number--- Beda 41

Section 5:2 Substation Location--- County---Ohio Road---Hwy 136 Town---Hartford

Section 5:3 Circuit Name and Number--- Whoopee Hill Feeder 2

Section 5:4Circuit Location---Hwy 1414Section 5:5Total Circuit Length----50.27Section 5:6Member count for this circuit----329Section 5:7Date of last circuit trim (VM)2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	11.1%	16.7%	27.8%	16.7%	5.6%	22.2%

Section 5:9	Circuit 5 year average (SAIDI)	1.514944
Section 5:10	Reporting year (SAIDI)	0.318747
Section 5:11	Circuit 5 year average (SAIFI)	0.009923
Section 5:12	Reporting year (SAIFI)	0.004031
		_

Section 5:13 List of corrective action, if any, taken or to be taken---- Repaired at time of outage, VM to trim circuit, Circuit scheduled for inspection.

Section 5:1 Substation name and Number---Beda 41

Substation Location---

County---Ohio

Section 5:3 Circuit Name and Number--- Road---Hwy 136

Town---Hartford

Section 5:4 Circuit Location--- Heflin Feeder 3

Hwy 136

Section 5:5 Total Circuit Length----

58.09

Section 5:6

Section 5:2

275

Member count for this circuit---

Section 5:7 Date of last circuit trim (VM) Section 5:8

2012/2017

List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	13.3%	13.3%	46.7%	6.7%	6.7%	13.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.862160
Section 5:10	Reporting year (SAIDI)	0.981291
Section 5:11	Circuit 5 year average (SAIFI)	0.007006
Section 5:12	Reporting year (SAIFI)	0.005604

Section 5:13 List of corrective action, if any, taken or to be taken--- Look at adding additional lightning protection, VM to trim circuit, System improvement work order scheduled.

Section 5:1 Substation name and Number--- Beda 41

Section 5:2 Substation Location--- County---Ohio Road---Hwy 136 Town---Hartford

Section 5:3Circuit Name and Number---Iron Mountain Feeder 4Section 5:4Circuit Location---Wal-Mart, Iron Mountain

Section 5:5Total Circuit Length----36.85Section 5:6Member count for this circuit---346Section 5:7Date of last circuit trim (VM)2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY PLANNED	D	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	10.0%	0.0%	0.0%	50.0%	10.0%	0.0%	30.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.812162
Section 5:10	Reporting year (SAIDI)	0.621037
Section 5:11	Circuit 5 year average (SAIFI)	0.010274
Section 5:12	Reporting year (SAIFI)	0.005480

Section 5:13 List of corrective action, if any, taken or to be taken--- Resolved at time of outage, VM to trim circuit, Circuit scheduled for inspection

Section 5:1 Substation name and Number--- Beech Grove 33

Section 5:2 Substation Location--- County---McLean Road---Hwy 256 Town---Beech Grove

Section 5:3 Circuit Name and Number--- Webster Co Water Feeder 1

Section 5:4Circuit Location---Hwy 256Section 5:5Total Circuit Length----31.92Section 5:6Member count for this circuit---135Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%		14.3%	0.0%	35.7%	35.7%	0.0%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.154219
Section 5:10	Reporting year (SAIDI)	0.197213
Section 5:11	Circuit 5 year average (SAIFI)	0.002003
Section 5:12	Reporting year (SAIFI)	0.003094

Section 5:13 List of corrective action, if any, taken or to be taken--- Added critter guard,

Section 5:1 Substation name and Number--- Beech Grove 33

Section 5:2 Substation Location--- County---McLean Road---Hwy 256 Town---Beech Grove

Section 5:3 Circuit Name and Number--- Beech Grove Feeder 2

Section 5:4Circuit Location---Hwy 136Section 5:5Total Circuit Length----18.21Section 5:6Member count for this circuit---149Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	40.0%	20.0%	0.0%	40.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.148337
Section 5:10	Reporting year (SAIDI)	0.169918
Section 5:11	Circuit 5 year average (SAIFI)	0.002543
Section 5:12	Reporting year (SAIFI)	0.002740

Section 5:1 Substation name and Number--- Beech Grove 33

Section 5:2 Substation Location--- County---McLean Road---Hwy 256 Town---Beech Grove

Section 5:3Circuit Name and Number---Elba Feeder 3Section 5:4Circuit Location---Hwy 56Section 5:5Total Circuit Length----43.57Section 5:6Member count for this circuit---227

Date of last circuit trim (VM)

Section 5:7

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

2015

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	13.0%	13.0%	39.1%	17.4%	4.3%	13.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.293123
Section 5:10	Reporting year (SAIDI)	0.244854
Section 5:11	Circuit 5 year average (SAIFI)	0.003595
Section 5:12	Reporting year (SAIFI)	0.002616

Section 5:13 List of corrective action, if any, taken or to be taken--- Critter guard added

Section 5:1 Substation name and Number--- Beech Grove 33

Section 5:2 Substation Location--- County---McLean Road---Hwy 256 Town---Beech Grove

Section 5:3 Circuit Name and Number--- Hudson Food Feeder 4

Section 5:4 Circuit Location--- Rangers Landing

Section 5:5Total Circuit Length----38.84Section 5:6Member count for this circuit---156Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	7.1%	0.0%	50.0%	7.1%	21.4%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.391182
Section 5:10	Reporting year (SAIDI)	0.369394
Section 5:11	Circuit 5 year average (SAIFI)	0.004167
Section 5:12	Reporting year (SAIFI)	0.004084

Section 5:1 Substation name and Number--- Bon Harbor 27

Section 5:2 Substation Location--- County---Daviess Road---Worthington Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Post Office Feeder 1
Section 5:4 Circuit Location--- Bon Harbor, Tradewinds

Section 5:5Total Circuit Length----16.12Section 5:6Member count for this circuit---350Section 5:7Date of last circuit trim (VM)2016

**Section 5:8** List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
25.0%	0.0%	0.0%	25.0%	50.0%	0.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.163414
Section 5:10	Reporting year (SAIDI)	0.096574
Section 5:11	Circuit 5 year average (SAIFI)	0.003571
Section 5:12	Reporting year (SAIFI)	0.001503

Section 5:1 Substation name and Number--- Bon Harbor 27

Section 5:2 Substation Location--- County---Daviess Road---Worthington Rd Town---Owensboro

Section 5:3Circuit Name and Number---Ben Hawes Park Feeder 2Section 5:4Circuit Location---Audubon, Boothfield Rd.

Section 5:5Total Circuit Length----31.53Section 5:6Member count for this circuit---364Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
50%	0.0%	0.0%	0.0%	0.0%	0.0%	50.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.212001
Section 5:10	Reporting year (SAIDI)	0.000919
Section 5:11	Circuit 5 year average (SAIFI)	0.003644
Section 5:12	Reporting year (SAIFI)	0.000035

Section 5:1 Substation name and Number--- Bon Harbor 27

Section 5:2 Substation Location--- County---Daviess Road---Worthington Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Worthington Rd Feeder 3
Section 5:4 Circuit Location--- Worthington Rd , Pecan Ridge

Section 5:5Total Circuit Length----5.01Section 5:6Member count for this circuit---87Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
33% 0.0%	0.0%	0.0%	33.3%	33.3%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.044120
Section 5:10	Reporting year (SAIDI)	0.012905
Section 5:11	Circuit 5 year average (SAIFI)	0.000717
Section 5:12	Reporting year (SAIFI)	0.000035

Section 5:1 Substation name and Number--- Bon Harbor 27

Section 5:2 Substation Location--- County---Daviess Road---Worthington Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- 5Th Street Rd Feeder 4

Section 5:4 Circuit Location--- 5Th Street Road

Section 5:5Total Circuit Length----23.23Section 5:6Member count for this circuit---445Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
11%	0.0%	22.2%	0.0%	11.1%	44.4%	0.0%	11.1%

Section 5:9	Circuit 5 year average (SAIDI)	0.232396
Section 5:10	Reporting year (SAIDI)	0.161133
Section 5:11	Circuit 5 year average (SAIFI)	0.003314
Section 5:12	Reporting year (SAIFI)	0.002333
Section 5:13	List of corrective action if any taken or to be	taken

Section 5:1 Substation name and Number--- Bon Harbor 27

Section 5:2 Substation Location--- County---Daviess Road---Worthington Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Lee Rudy/ Hwy 60 Feeder 5

Section 5:4Circuit Location---Hwy 279Section 5:5Total Circuit Length----37.79Section 5:6Member count for this circuit---391Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
7%	0.0%	42.9%	0.0%	21.4%	14.3%	7.1%	7.1%

Section 5:9	Circuit 5 year average (SAIDI)	0.249175
Section 5:10	Reporting year (SAIDI)	0.494058
Section 5:11	Circuit 5 year average (SAIFI)	0.006219
Section 5:12	Reporting year (SAIFI)	0.015521

Section 5:1 Substation name and Number--- Caldwell Springs 60

Section 5:2 Substation Location--- County---Crittenden Road---Hwy 855 Town---Fredonia

Section 5:3 Circuit Name and Number--- March Oliver Road Feeder 1

Section 5:4 Circuit Location--- March Oliver Road

Section 5:5Total Circuit Length----28.38Section 5:6Member count for this circuit---112Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	37.5%	0.0%	25.0%	12.5%	12.5%	12.5%

Section 5:9	Circuit 5 year average (SAIDI)	0.095527
Section 5:10	Reporting year (SAIDI)	0.086002
Section 5:11	Circuit 5 year average (SAIFI)	0.001076
Section 5:12	Reporting year (SAIFI)	0.000937

Section 5:1 Substation name and Number--- Caldwell Springs 60

Section 5:2 Substation Location--- County---Crittenden Road---Hwy 855 Town---Fredonia

Section 5:3 Circuit Name and Number--- Dycusburg Feeder 2

Section 5:4Circuit Location---Hwy 1943Section 5:5Total Circuit Length----59.38Section 5:6Member count for this circuit---285Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	6.3%	12.5%	0.0%	18.8%	37.5%	6.3%	18.8%

Section 5:9	Circuit 5 year average (SAIDI)	1.038863
Section 5:10	Reporting year (SAIDI)	0.291188
Section 5:11	Circuit 5 year average (SAIFI)	0.006256
Section 5:12	Reporting year (SAIFI)	0.003270

Section 5:13 List of corrective action, if any, taken or to be taken--- Installed critter guard

Section 5:1 Substation name and Number--- Caldwell Springs 60

Section 5:2 Substation Location--- County---Crittenden Road---Hwy 855 Town---Fredonia

Section 5:3 Circuit Name and Number--- Caldwell Springs Church Feeder 3

Section 5:4 Circuit Location--- Seven Springs, Reiter Corner

Section 5:5Total Circuit Length----70.18Section 5:6Member count for this circuit---993Section 5:7Date of last circuit trim (VM)2014

**Section 5:8** List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	34.8%	26.1%	0.0%	13.0%	0.0%	8.7%	17.4%

Section 5:9	Circuit 5 year average (SAIDI)	1.322636
Section 5:10	Reporting year (SAIDI)	3.096168
Section 5:11	Circuit 5 year average (SAIFI)	0.009887
Section 5:12	Reporting year (SAIFI)	0.017165

Section 5:1 Substation name and Number--- Centertown 40

Section 5:2 Substation Location--- County---Ohio Road---Pitts Lane Town---Centertown

Section 5:3 Circuit Name and Number--- Matanzas Feeder 1
Section 5:4 Circuit Location--- Mantazas, Hwy 85

Section 5:5Total Circuit Length----29.57Section 5:6Member count for this circuit---141Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	16.7%	16.7%	0.0%	33.3%	16.7%	16.7%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.225871
Section 5:10	Reporting year (SAIDI)	0.054589
Section 5:11	Circuit 5 year average (SAIFI)	0.002819
Section 5:12	Reporting year (SAIFI)	0.000619

Section 5:13 List of corrective action, if any, taken or to be taken--- System improvement work order scheduled, Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Centertown 40

Section 5:2 Substation Location--- County---Ohio Road---Pitts Lane Town---Centertown

Section 5:3 Circuit Name and Number--- Goshen Rd. Feeder 2

Section 5:4Circuit Location---MantazasSection 5:5Total Circuit Length----29.57Section 5:6Member count for this circuit---100Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	60.0%	10.0%	20.0%	0.0%	10.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.329152
Section 5:10	Reporting year (SAIDI)	0.329018
Section 5:11	Circuit 5 year average (SAIFI)	0.003387
Section 5:12	Reporting year (SAIFI)	0.001998

Section 5:13 List of corrective action, if any, taken or to be taken--- System improvement work order scheduled, Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Centertown 40

Section 5:2 Substation Location--- County---Ohio Road---Pitts Lane Town----Centertown

Section 5:3Circuit Name and Number---Rockport Feeder 3Section 5:4Circuit Location---Hwy 85 South

Section 5:5Total Circuit Length----44.78Section 5:6Member count for this circuit---270Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%		38.9%	5.6%	33.3%	0.0%	0.0%	16.7%

Section 5:9	Circuit 5 year average (SAIDI)	2.095682
Section 5:10	Reporting year (SAIDI)	0.111334
Section 5:11	Circuit 5 year average (SAIFI)	0.010428
Section 5:12	Reporting year (SAIFI)	0.000937

Section 5:1 Substation name and Number--- Centertown 40

Section 5:2 Substation Location--- County---Ohio Road---Pitts Lane Town---Centertown

Section 5:3 Circuit Name and Number--- Bishner Lane Feeder 4

Section 5:4 Circuit Location--- Bishner Lane

Section 5:5 Total Circuit Length---- 2

Section 5:6 Member count for this circuit--- 10
Section 5:7 Date of last circuit trim (VM) 2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SU	JPPLY	PLANNED	<b>EQUIPMENT FAILURE</b>	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
	0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.010173
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.000162
Section 5:12	Reporting year (SAIFI)	0.000000
Section 5:13	List of corrective action, if any, taken or to be take	en

Section 5:1 Substation name and Number--- Crossroads 61

Section 5:2 Substation Location--- County---Caldwell Road---Hwy 70 Town---Princeton

Section 5:3 Circuit Name and Number--- Old Barnes Store Feeder 2

Section 5:4 Circuit Location--- Hwy 293 South

Section 5:5Total Circuit Length----96.45Section 5:6Member count for this circuit---328Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	14.3%	32.1%	17.9%	10.7%	0.0%	10.7%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	1.046762
Section 5:10	Reporting year (SAIDI)	0.876569
Section 5:11	Circuit 5 year average (SAIFI)	0.009279
Section 5:12	Reporting year (SAIFI)	0.005321
Castian F.13	The of compating paters of any appearance by adding	_

Section 5:13 List of corrective action, if any, taken or to be taken--- System Improvement work order scheduled, Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Crossroads 61

Section 5:2 Substation Location--- County---Caldwell Road---Hwy 70 Town---Princeton

Section 5:3 Circuit Name and Number--- Flatrock Feeder 2

Section 5:4 Circuit Location--- Hwy 70 west, Ferry Rd.

Section 5:5Total Circuit Length----46.88Section 5:6Member count for this circuit---167Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	9.1%	36.4%	0.0%	36.4%	0.0%	0.0%	18.2%

Section 5:9	Circuit 5 year average (SAIDI)	0.365421
Section 5:10	Reporting year (SAIDI)	0.067723
Section 5:11	Circuit 5 year average (SAIFI)	0.003629
Section 5:12	Reporting year (SAIFI)	0.000760

Section 5:13 List of corrective action, if any, taken or to be taken--- Look at adding lighting protection, Equipment replaced at time of outage.

Section 5:1 Substation name and Number--- Crossroads 61

Section 5:2 Substation Location--- County---Caldwell Road---Hwy 70 Town---Princeton

Section 5:3 Circuit Name and Number--- Morganhill/Farmersville Feeder 2

Section 5:4Circuit Location---Hwy 1119Section 5:5Total Circuit Length----142.31Section 5:6Member count for this circuit---720Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	7.9%	31.6%	5.3%	36.8%	2.6%	2.6%	13.2%

Section 5:1	List of corrective action, if any, taken of	or to be taken	Look at adding lighting protection, Equipment replaced at time of outage, Circuit scheduled for inspection.
Section 5:1	Reporting year (SAIFI)	0.012940	
Section 5:1	L1 Circuit 5 year average (SAIFI)	0.018684	
Section 5:1	Reporting year (SAIDI)	1.246723	
Section 5:9	Circuit 5 year average (SAIDI)	2.255185	

Section 5:1 Substation name and Number--- Crossroads 61

Section 5:2 Substation Location--- County---Caldwell Road---Hwy 70 Town---Princeton

Section 5:3 Circuit Name and Number--- Creswell Feeder 4
Section 5:4 Circuit Location--- Hwy 902, Hwy 139

Section 5:5Total Circuit Length----28.94Section 5:6Member count for this circuit---128Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0.0%	16.7%	16.7%	33.3%	16.7%	0.0%	0.0%	16.7%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.180785

 Section 5:10
 Reporting year (SAIDI)
 0.284064

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.002328

 Section 5:12
 Reporting year (SAIFI)
 0.002210

**Section 5:13** List of corrective action, if any, taken or to be taken--- **Circuit scheduled for inspection.** 

Section 5:1 Substation name and Number--- Dermont 17

Section 5:2 Substation Location--- County---Daviess Road---Pleasant Valley Rd Town---Owensboro

Section 5:3Circuit Name and Number---Reid Road Feeder 1Section 5:4Circuit Location---Reid Rd., Lane Rd.

Section 5:5Total Circuit Length----18.01Section 5:6Member count for this circuit----220Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	25.0%	0.0%	25.0%	25.0%	0.0%	25.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.679821
Section 5:10	Reporting year (SAIDI)	0.050187
Section 5:11	Circuit 5 year average (SAIFI)	0.009264
Section 5:12	Reporting year (SAIFI)	0.000424

Section 5:1 Substation name and Number--- Dermont 17

Section 5:2 Substation Location--- County---Daviess Road---Pleasant Valley Rd Town---Owensboro

Section 5:3Circuit Name and Number---Dee Acres Feeder 2Section 5:4Circuit Location---Pleasant Valley Rd

Section 5:5Total Circuit Length----11.38Section 5:6Member count for this circuit---116Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	14.3%	14.3%	14.3%	28.6%	14.3%	0.0%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.018993
Section 5:10	Reporting year (SAIDI)	0.020329
Section 5:11	Circuit 5 year average (SAIFI)	0.000271
Section 5:12	Reporting year (SAIFI)	0.000354

Section 5:1 Substation name and Number--- Dermont 17

Section 5:2 Substation Location--- County---Daviess Road---Pleasant Valley Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Timber Ridge Subdivision Feeder 3

Section 5:4 Circuit Location--- Hwy 142, Hwy 54, Fields Rd

Section 5:5Total Circuit Length----23.07Section 5:6Member count for this circuit----312Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	27.3%	18.2%	0.0%	9.1%	0.0%	45.5%

Section 5:9	Circuit 5 year average (SAIDI)	0.161827
Section 5:10	Reporting year (SAIDI)	0.046563
Section 5:11	Circuit 5 year average (SAIFI)	0.002789
Section 5:12	Reporting year (SAIFI)	0.000689

Section 5:1 Substation name and Number--- Dermont 17

Section 5:2 Substation Location--- County---Daviess Road---Pleasant Valley Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Locust Hills Feeder 4

Section 5:4 Circuit Location--- Fields Rd north

Section 5:5Total Circuit Length----33.37Section 5:6Member count for this circuit---590Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	27.3%	9.1%	9.1%	27.3%	18.2%	9.1%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.403414
Section 5:10	Reporting year (SAIDI)	0.037777
Section 5:11	Circuit 5 year average (SAIFI)	0.006602
Section 5:12	Reporting year (SAIFI)	0.000937

Section 5:1 Substation name and Number--- Dermont 17

Section 5:2 Substation Location--- County---Daviess Road---Pleasant Valley Rd Town---Owensboro

Section 5:3Circuit Name and Number---Ensor Feeder 5Section 5:4Circuit Location---Hwy 144Section 5:5Total Circuit Length----50.77Section 5:6Member count for this circuit---497Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	37.5%	0.0%	0.0%	12.5%	25.0%	0.0%	25.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.232887
Section 5:10	Reporting year (SAIDI)	0.042674
Section 5:11	Circuit 5 year average (SAIFI)	0.002896
Section 5:12	Reporting year (SAIFI)	0.001273

Section 5:1 Substation name and Number--- Dixon 62

Section 5:2 Substation Location--- County---Webster Road---SR 1063 Town---Dixon

Section 5:3 Circuit Name and Number--- Hwy 41A North Feeder 1

Section 5:4 Circuit Location--- Oak Heights

Section 5:5Total Circuit Length----41.42Section 5:6Member count for this circuit---250Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	20.0%	0.0%	40.0%	0.0%	0.0%	20.0%	20.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.662113
Section 5:10	Reporting year (SAIDI)	0.184945
Section 5:11	Circuit 5 year average (SAIFI)	0.007710
Section 5:12	Reporting year (SAIFI)	0.002068

Section 5:1 Substation name and Number--- Dixon 62

Section 5:2 Substation Location--- County---Webster Road---SR 1063 Town---Dixon

Section 5:3Circuit Name and Number---Dixon Feeder 2Section 5:4Circuit Location---Hwy 132 West

Section 5:5Total Circuit Length----45.4Section 5:6Member count for this circuit---270Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	33.3%	0.0%	33.3%	0.0%	0.0%	33.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.097277
Section 5:10	Reporting year (SAIDI)	0.031396
Section 5:11	Circuit 5 year average (SAIFI)	0.001530
Section 5:12	Reporting year (SAIFI)	0.000477

Section 5:1	Substation name and Number	Dixon 62
-------------	----------------------------	----------

Section 5:2 Substation Location--- County---Webster Road---SR 1063 Town---Dixon

Section 5:3 Circuit Name and Number--- Clay Feeder 3

Section 5:4 Circuit Location--- Free Union, Little Zion

Section 5:5Total Circuit Length----75.21Section 5:6Member count for this circuit---342Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0.00%	0.00%	55.56%	0.00%	33.33%	0.00%	11.11%	0.00%

Section 5:9	Circuit 5 year average (SAIDI)	0.876314
Section 5:10	Reporting year (SAIDI)	1.082567
Section 5:11	Circuit 5 year average (SAIFI)	0.009271
Section 5:12	Reporting year (SAIFI)	0.006930

Section 5:1 Substation name and Number--- East Owensboro 19

Section 5:2 Substation Location--- County---Daviess Road---Hayden Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Covent Gardens Feeder 2

Section 5:4 Circuit Location--- Hayden Road

Section 5:5Total Circuit Length----29.48Section 5:6Member count for this circuit---471Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	40.0%	0.0%	0.0%	20.0%	0.0%	40.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.675665
Section 5:10	Reporting year (SAIDI)	0.073186
Section 5:11	Circuit 5 year average (SAIFI)	0.008450
Section 5:12	Reporting year (SAIFI)	0.001008

Section 5:13 List of corrective action, if any, taken or to be taken--- Conductor conversion work order scheduled,

Section 5:1 Substation name and Number--- East Owensboro 19

Section 5:2 Substation Location--- County---Daviess Road---Hayden Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Thruston/Dermont Fire Station Feeder 3

Section 5:4 Circuit Location--- Pleasant View, Fire Station

Section 5:5Total Circuit Length----11.93Section 5:6Member count for this circuit---158Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	50.0%	16.7%	16.7%	0.0%	0.0%	16.7%

Section 5:9	Circuit 5 year average (SAIDI)	0.099504
Section 5:10	Reporting year (SAIDI)	0.105943
Section 5:11	Circuit 5 year average (SAIFI)	0.001139
Section 5:12	Reporting year (SAIFI)	0.000654

Section 5:1 Substation name and Number--- East Owensboro 19

Section 5:2 Substation Location--- County---Daviess Road---Hayden Rd Town---Owensboro

Section 5:3Circuit Name and Number---Memorial Gardens Feeder 4Section 5:4Circuit Location---Reid Orchard, Town & Country

Section 5:5Total Circuit Length----6.69Section 5:6Member count for this circuit---36Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	75.0%	25.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.029487
Section 5:10	Reporting year (SAIDI)	0.004543
Section 5:11	Circuit 5 year average (SAIFI)	0.000595
Section 5:12	Reporting year (SAIFI)	0.000071

Section 5:1 Substation name and Number--- East Owensboro 19

Section 5:2 Substation Location--- County---Daviess Road---Hayden Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Brownwood Manor Feeder 5

Section 5:4 Circuit Location--- Brown Wood Maner, Sterling Park

Section 5:5Total Circuit Length----19.69Section 5:6Member count for this circuit---381Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	25.0%	37.5%	0.0%	25.0%	0.0%	12.5%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.231710
Section 5:10	Reporting year (SAIDI)	0.188038
Section 5:11	Circuit 5 year average (SAIFI)	0.003873
Section 5:12	Reporting year (SAIFI)	0.001962

Section 5:1 Substation name and Number--- Geneva 63

Section 5:2 Substation Location--- County---Henderson Road---Hwy 136 Town---Corydon

Section 5:3 Circuit Name and Number--- Alzey Feeder 1

Section 5:4Circuit Location---Hwy 268Section 5:5Total Circuit Length----54.51Section 5:6Member count for this circuit---167Section 5:7Date of last circuit trim (VM)2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	5.9%	47.1%	11.8%	23.5%	0.0%	0.0%	11.8%

Section 5:9	Circuit 5 year average (SAIDI)	0.546039
Section 5:10	Reporting year (SAIDI)	0.404219
Section 5:11	Circuit 5 year average (SAIFI)	0.005665
Section 5:12	Reporting year (SAIFI)	0.003483

Section 5:13 List of corrective action, if any, taken or to be taken--- VM to trim circuit, Evaluate & inspection circuit.

Section 5:1 Substation name and Number--- Geneva 63

Section 5:2 Substation Location--- County---Henderson Road---Hwy 136 Town---Corydon

Section 5:3 Circuit Name and Number--- Airport/Office Feeder 2
Section 5:4 Circuit Location--- Kenergy HQ, Hwy 60 West

Section 5:5Total Circuit Length----54.96Section 5:6Member count for this circuit----560Section 5:7Date of last circuit trim (VM)2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	3.7%	22.2%	14.8%	18.5%	22.2%	3.7%	14.8%

Section 5:9	Circuit 5 year average (SAIDI)	0.982875
Section 5:10	Reporting year (SAIDI)	1.184037
Section 5:11	Circuit 5 year average (SAIFI)	0.018781
Section 5:12	Reporting year (SAIFI)	0.017200

Section 5:13 List of corrective action, if any, taken or to be taken--- VM to trim circuit, Evaluate & inspection circuit.

Section 5:1 Substation name and Number--- Geneva 63

Section 5:2 Substation Location--- County---Henderson Road---Hwy 136 Town---Corydon

Section 5:3 Circuit Name and Number--- Smith Mills Feeder 3

Section 5:4Circuit Location---Smith MillsSection 5:5Total Circuit Length----117.88Section 5:6Member count for this circuit---581

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	15.9%	4.5%	47.7%	6.8%	13.6%	11.4%

Section 5:9	Circuit 5 year average (SAIDI)	2.513963
Section 5:10	Reporting year (SAIDI)	1.686156
Section 5:11	Circuit 5 year average (SAIFI)	0.026366
Section 5:12	Reporting year (SAIFI)	0.021673

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit, VM to trim circuit, Look at adding additional lightning protection.

Section 3.1 Substation hame and Number Guine 31	Section 5:1	Substation name and Number	Guffie 31
---	-------------	----------------------------	-----------

Section 5:2 Substation Location--- County---Mclean Road---Hwy 140 Town---Calhoun

Section 5:3 Circuit Name and Number--- Glenville Feeder 1

Section 5:4 Circuit Location--- Hwy 81, Hwy 815 north, Hwy 554

Section 5:5Total Circuit Length----98.72Section 5:6Member count for this circuit---691Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	6.3%	18.8%	9.4%	31.3%	18.8%	3.1%	12.5%

Section 5:9	Circuit 5 year average (SAIDI)	2.522326	
Section 5:10	Reporting year (SAIDI)	1.258708	
Section 5:11	Circuit 5 year average (SAIFI)	0.030595	
Section 5:12	Reporting year (SAIFI)	0.017908	
Cootion F.12	tiet of annuation action if any talent auto he talent		1 1 4 -

Section 5:13 List of corrective action, if any, taken or to be taken--- Look at adding additional lightning protection.

Section 5:1 Substation name and Number--- Guffie 31

Section 5:2 Substation Location--- County---Mclean Road---Hwy 140 Town---Calhoun

Section 5:3 Circuit Name and Number--- Hwy 815 South Feeder 2

Section 5:4 Circuit Location--- Brookschool Rd, Hwy 815 south

Section 5:5Total Circuit Length----52.28Section 5:6Member count for this circuit---445Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	7.7%	23.1%	0.0%	15.4%	23.1%	7.7%	23.1%

Section 5:9	Circuit 5 year average (SAIDI)	1.506244
Section 5:10	Reporting year (SAIDI)	1.359507
Section 5:11	Circuit 5 year average (SAIFI)	0.007783
Section 5:12	Reporting year (SAIFI)	0.008591

Section 5:1 Substation name and Number--- Guffie 31

Section 5:2 Substation Location--- County---Mclean Road---Hwy 140 Town---Calhoun

Section 5:3 Circuit Name and Number--- Poverty Feeder 3

Section 5:4 Circuit Location--- Hwy 140, Hwy 136, Hwy 256

Section 5:5Total Circuit Length----30.39Section 5:6Member count for this circuit---83Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	25.0%	0.0%	50.0%	0.0%	0.0%	25.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.115292
Section 5:10	Reporting year (SAIDI)	0.009122
Section 5:11	Circuit 5 year average (SAIFI)	0.000665
Section 5:12	Reporting year (SAIFI)	0.000106

**Section 5:13** List of corrective action, if any, taken or to be taken--- **System improvement work order scheduled.** 

Section 5:1 Substation name and Number--- Guffie 31

Section 5:2 Substation Location--- County---Mclean Road---Hwy 140 Town---Calhoun

Section 5:3 Circuit Name and Number--- Cleopatra Feeder 4

Section 5:4 Circuit Location--- Beulah Rd., Cleopatra Rd.

Section 5:5Total Circuit Length----30.48Section 5:6Member count for this circuit---118Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	23.5%	5.9%	0.0%	23.5%	23.5%	0.0%	23.5%

Section 5:9	Circuit 5 year average (SAIDI)	0.066070
Section 5:10	Reporting year (SAIDI)	0.054978
Section 5:11	Circuit 5 year average (SAIFI)	0.000691
Section 5:12	Reporting year (SAIFI)	0.000742

Section 5:1 Substation name and Number--- Hanson 51

Section 5:2 Substation Location--- County---Hopkins Road---Brown Road Town---Madisonville

Section 5:3 Circuit Name and Number--- Stringtown Feeder F3

Section 5:4Circuit Location---Hwy 254Section 5:5Total Circuit Length----10.93Section 5:6Member count for this circuit---58Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	16.7%	0.0%	33.3%	16.7%	33.3%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.084628
Section 5:10	Reporting year (SAIDI)	0.043151
Section 5:11	Circuit 5 year average (SAIFI)	0.001285
Section 5:12	Reporting year (SAIFI)	0.001255

Section 5:1 Substation name and Number--- Hanson 51

Section 5:2 Substation Location--- County---Hopkins Road---Brown Road Town---Madisonville

Section 5:3 Circuit Name and Number--- Brown Road Feeder 4
Section 5:4 Circuit Location--- Hwy 254, Hwy 260

Section 5:5Total Circuit Length----76.42Section 5:6Member count for this circuit---479Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	5.3%	10.5%	31.6%	36.8%	5.3%	10.5%

Section 5:9	Circuit 5 year average (SAIDI)	0.935397
Section 5:10	Reporting year (SAIDI)	1.094659
Section 5:11	Circuit 5 year average (SAIFI)	0.014738
Section 5:12	Reporting year (SAIFI)	0.010571
Section 5:12	List of corrective action if any taken or to be ta	kon Inspect 9

Section 5:13 List of corrective action, if any, taken or to be taken---- Inspect & evaluate circuit

Section 5:1 Substation name and Number--- Hawesville 13

Section 5:2 Substation Location--- County---Hancock Road---Hwy 1389 Town---Hawesville

Section 5:3 Circuit Name and Number--- Downtown Hawesville Feeder 1
Section 5:4 Circuit Location--- Hwy 334, Downtown, Pear Tree Lane

Section 5:5Total Circuit Length----16.88Section 5:6Member count for this circuit---270Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	50.0%	0.0%	16.7%	33.3%	0.0%	0.0%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.097082

 Section 5:10
 Reporting year (SAIDI)
 0.052114

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.001504

 Section 5:12
 Reporting year (SAIFI)
 0.000654

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit.

Section 5:1 Substation name and Number--- Hawesville 13

Section 5:2 Substation Location--- County---Hancock Road---Hwy 1389 Town---Hawesville

Section 5:3 Circuit Name and Number--- Kelly Heights Feeder 2
Section 5:4 Circuit Location--- Kelly Heights, Skkillman Rd

Section 5:5Total Circuit Length----44.65Section 5:6Member count for this circuit---445Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	27.3%	9.1%	9.1%	45.5%	0.0%	9.1%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.808229

 Section 5:10
 Reporting year (SAIDI)
 0.127350

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.008303

 Section 5:12
 Reporting year (SAIFI)
 0.000707

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit, System improvement work order scheduled.

Section 5:1 Substation name and Number--- Hawesville 13

Section 5:2 Substation Location--- County---Hancock Road---Hwy 1389 Town---Hawesville

Section 5:3 Circuit Name and Number--- Hwy 69 Feeder 3

Section 5:4 Circuit Location--- Hwy 69, Tick Ridge Rd

Section 5:5Total Circuit Length----61.92Section 5:6Member count for this circuit---479Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	17.4%	21.7%	30.4%	4.3%	17.4%	8.7%

Section 5:9	Circuit 5 year average (SAIDI)	0.901861
Section 5:10	Reporting year (SAIDI)	3.434626
Section 5:11	Circuit 5 year average (SAIFI)	0.006109
Section 5:12	Reporting year (SAIFI)	0.019905

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit, System improvement work order scheduled.

Section 5:1 Substation name and Number--- Hawesville 13

Section 5:2 Substation Location--- County---Hancock Road---Hwy 1389 Town---Hawesville

Section 5:3Circuit Name and Number---Utility/Hwy 1389Section 5:4Circuit Location---Frank Gaynor Rd.

Section 5:5Total Circuit Length----68.25Section 5:6Member count for this circuit---372Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	21.4%	7.1%	57.1%	0.0%	0.0%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.233914
Section 5:10	Reporting year (SAIDI)	0.086798
Section 5:11	Circuit 5 year average (SAIFI)	0.003293
Section 5:12	Reporting year (SAIFI)	0.000442

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit.

Section 5:1 Substation name and Number--- Hawesville 13

Section 5:2 Substation Location--- County---Hancock Road---Hwy 1389 Town---Hawesville

Section 5:3 Circuit Name and Number--- Windward Heights Feeder 5

Section 5:4Circuit Location---Hwy 1847Section 5:5Total Circuit Length----25.37Section 5:6Member count for this circuit---238Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

РО	WER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
	0%	10.0%	30.0%	0.0%	10.0%	20.0%	0.0%	30.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.271080
Section 5:10	Reporting year (SAIDI)	0.197814
Section 5:11	Circuit 5 year average (SAIFI)	0.003807
Section 5:12	Reporting year (SAIFI)	0.001485

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit.

Section 5:1 Substation name and Number Horse	e Fork 20
--	-----------

Section 5:2 Substation Location--- County---Daviess Road---Veach Road Town---Owensboro

Section 5:3 Circuit Name and Number--- Foors Lane Feeder 1

Section 5:4 Circuit Location--- Deer Park, Stone Creek, Foors Lane

Section 5:5Total Circuit Length----15.27Section 5:6Member count for this circuit---236Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	10.0%	30.0%	0.0%	30.0%	10.0%	10.0%	10.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.196595	
Section 5:10	Reporting year (SAIDI)	0.232816	
Section 5:11	Circuit 5 year average (SAIFI)	0.003629	
Section 5:12	Reporting year (SAIFI)	0.008591	
Continu F.13	Charles and a compaction of the contract of th		_

Section 5:1 Substation name and Number Horse F	ork 20
--	--------

Section 5:2 Substation Location--- County---Daviess Road---Veach Road Town---Owensboro

Section 5:3Circuit Name and Number---Springbank Feeder 2Section 5:4Circuit Location---Forest Hills, Bridle Ridge

Section 5:5Total Circuit Length----22.97Section 5:6Member count for this circuit---355Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	33.3%	33.3%	0.0%	0.0%	11.1%	0.0%	22.2%

Section 5:9	Circuit 5 year average (SAIDI)	0.641379
Section 5:10	Reporting year (SAIDI)	0.980991
Section 5:11	Circuit 5 year average (SAIFI)	0.006864
Section 5:12	Reporting year (SAIFI)	0.010288

Section 5:1 Substation name and Number--- Horse Fork 20

Section 5:2 Substation Location--- County---Daviess Road---Veach Road Town---Owensboro

Section 5:3 Circuit Name and Number--- Sutherland Road Feeder 3

Section 5:4 Circuit Location--- Sutherland Road

Section 5:5Total Circuit Length----3.71Section 5:6Member count for this circuit----8Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POW	VER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
	0%	0.0%	50.0%	0.0%	0.0%	50.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.004168
Section 5:10	Reporting year (SAIDI)	0.004808
Section 5:11	Circuit 5 year average (SAIFI)	0.000068
Section 5:12	Reporting year (SAIFI)	0.000141

Section 5:1 Substation name and Number--- Horse Fork 20

Section 5:2 Substation Location--- County---Daviess Road---Veach Road Town---Owensboro

Section 5:3 Circuit Name and Number--- Marlboro Apartments Feeder 4

Section 5:4 Circuit Location--- Lowes, Staples

Section 5:5Total Circuit Length----9.28Section 5:6Member count for this circuit---173Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	100.0%	0.0%	0.0%	0.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.329990
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.001684
Section 5:12	Reporting year (SAIFI)	0.000000

Section 5:1	Substation name and Number	Horse Fork 20
-------------	----------------------------	---------------

Section 5:2 Substation Location--- County---Daviess Road---Veach Road Town---Owensboro

Section 5:3Circuit Name and Number---Hampton Inn Feeder 5Section 5:4Circuit Location---Salem Drive, Comfort Inn

Section 5:5Total Circuit Length----9.46Section 5:6Member count for this circuit---263Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	100.0%	0.0%	0.0%	0.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	1.133236
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.005983
Section 5:12	Reporting year (SAIFI)	0.000000
C	the form of the second	_

Section 5:1 Substation name and Number--- Hudson 65

Section 5:2 Substation Location--- County---Henderson Road--Quinns Landing Town---Robards

Section 5:3Circuit Name and Number---Protein Feeder 1Section 5:4Circuit Location---Tyson Plant

Section 5:5Total Circuit Length----0.95Section 5:6Member count for this circuit---1Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN

Section 5:9	Circuit 5 year average (SAIDI)	0.0000
Section 5:10	Reporting year (SAIDI)	0.0000
Section 5:11	Circuit 5 year average (SAIFI)	0.0000
Section 5:12	Reporting year (SAIFI)	0.0000

Section 5:13 List of corrective action, if any, taken or to be taken--- No Outages

Section 5:1 Substation name and Number--- Hudson 65

Section 5:2 Substation Location--- County---Henderson Road--Quinns Landing Town---Robards

Section 5:3 Circuit Name and Number--- Sebree #1 Feeder 4

Section 5:4 Circuit Location--- Feed Mill, Southern States

Section 5:5Total Circuit Length----7.82Section 5:6Member count for this circuit---30Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	33.3%	0.0%	0.0%	33.3%	0.0%	0.0%	33.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.023623
Section 5:10	Reporting year (SAIDI)	0.004190
Section 5:11	Circuit 5 year average (SAIFI)	0.000288
Section 5:12	Reporting year (SAIFI)	0.000053

Section 5:1 Substation name and Number--- Hudson 65

Section 5:2 Substation Location--- County---Henderson Road--Quinns Landing Town---Robards

Section 5:3 Circuit Name and Number--- Water #2 Feeder 6
Section 5:4 Circuit Location--- Hwy 41, Truck Stop

Section 5:5Total Circuit Length----21.36Section 5:6Member count for this circuit---146Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	7.7%	7.7%	23.1%	30.8%	15.4%	15.4%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.246380
Section 5:10	Reporting year (SAIDI)	0.814785
Section 5:11	Circuit 5 year average (SAIFI)	0.003441
Section 5:12	Reporting year (SAIFI)	0.008326

Section 5:1 Substation name and Number---Hudson 65

County---Henderson

Road--Quinns Landing Town---Robards

Section 5:3 Circuit Name and Number---

Substation Location---

Energy #2 Feeder 7

Section 5:4 Circuit Location--- **Tyson Plant** 

Section 5:5 Total Circuit Length---- 0.57

Section 5:6

Member count for this circuit---1

Section 5:7

Section 5:2

Date of last circuit trim (VM) 2013

Section 5:8

List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.115047
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.002759
Section 5:12	Reporting year (SAIFI)	0.000000

**Section 5:13** List of corrective action, if any, taken or to be taken---

Section 5:1 Substation name and Number--- Lewisport 12

Section 5:2 Substation Location--- County---Hancock Road---Hwy 657 Town---Lewisport

Section 5:3 Circuit Name and Number--- Morton Lane Feeder 1

Section 5:4 Circuit Location--- Old Hwy 60

Section 5:5Total Circuit Length----23.45Section 5:6Member count for this circuit---428Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	27.3%	45.5%	0.0%	9.1%	9.1%	9.1%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.241427
Section 5:10	Reporting year (SAIDI)	0.070340
Section 5:11	Circuit 5 year average (SAIFI)	0.004559
Section 5:12	Reporting year (SAIFI)	0.001273

**Section 5:13** List of corrective action, if any, taken or to be taken--- **System improvement work order scheduled.** 

Section 5:1 Substation name and Number--- Lewisport 12

Section 5:2 Substation Location--- County---Hancock Road---Hwy 657 Town---Lewisport

Section 5:3 Circuit Name and Number--- Lewisport Feeder 2

Section 5:4 Circuit Location--- Downtown

Section 5:5Total Circuit Length----20.16Section 5:6Member count for this circuit---442Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	25.0%	16.7%	0.0%	50.0%	0.0%	8.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.257587
Section 5:10	Reporting year (SAIDI)	0.311676
Section 5:11	Circuit 5 year average (SAIFI)	0.005035
Section 5:12	Reporting year (SAIFI)	0.008662

Section 5:1 Substation name and Number--- Lewisport 12

Section 5:2 Substation Location--- County---Hancock Road---Hwy 657 Town---Lewisport

Section 5:3 Circuit Name and Number--- Shopping Center Feeder 3
Section 5:4 Circuit Location--- Subway, Hancock Bank

Section 5:5Total Circuit Length----35.3Section 5:6Member count for this circuit---229Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

<b>POWER SUPPLY</b>	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	8.3%	16.7%	8.3%	33.3%	8.3%	16.7%	8.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.479687
Section 5:10	Reporting year (SAIDI)	1.051030
Section 5:11	Circuit 5 year average (SAIFI)	0.004684
Section 5:12	Reporting year (SAIFI)	0.005586

Section 5:1 Substation name and Number--- Lewisport 12

Section 5:2 Substation Location--- County---Hancock Road---Hwy 657 Town---Lewisport

Section 5:3Circuit Name and Number---Hwy 657 Feeder 4Section 5:4Circuit Location---Hwy 657, Hwy 661

Section 5:5Total Circuit Length----39.92Section 5:6Member count for this circuit---228Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	21.4%	28.6%	21.4%	14.3%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.537323
Section 5:10	Reporting year (SAIDI)	0.424177
Section 5:11	Circuit 5 year average (SAIFI)	0.004315
Section 5:12	Reporting year (SAIFI)	0.003111

**Section 5:13** List of corrective action, if any, taken or to be taken--- **Circuit scheduled for inspection.** 

Section 5:1 Substation name and Number--- Lewisport 12

Section 5:2 Substation Location--- County---Hancock Road---Hwy 657 Town---Lewisport

Section 5:3 Circuit Name and Number--- Dal Tile Feeder 5

Section 5:4Circuit Location---Dal TileSection 5:5Total Circuit Length----1.77Section 5:6Member count for this circuit---2Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.001139			
Section 5:10	Reporting year (SAIDI)	0.000000			
Section 5:11	Circuit 5 year average (SAIFI)	0.000007			
Section 5:12	Reporting year (SAIFI)	0.000000			
Costion F.13	List of competitive actions if any tallog out a locately of				

**Section 5:13** List of corrective action, if any, taken or to be taken---

Section 5:1 Substation name and Number--- Lewisport 12

Section 5:2 Substation Location--- County---Hancock Road---Hwy 657 Town---Lewisport

Section 5:3 Circuit Name and Number--- Mcgill Lane Feeder 6

Section 5:4 Circuit Location--- Mroton Lane

Section 5:5Total Circuit Length----6.62Section 5:6Member count for this circuit---75Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	33.3%	33.3%	33.3%	0.0%	0.0%	0.0%	0.0%

Section 5:9Circuit 5 year average (SAIDI)0.069507Section 5:10Reporting year (SAIDI)0.076598Section 5:11Circuit 5 year average (SAIFI)0.001279Section 5:12Reporting year (SAIFI)0.001361

**Section 5:13** List of corrective action, if any, taken or to be taken--- **Circuit scheduled for inspection.** 

Section 5:1 Substation name and Number--- Lewisport 12

Section 5:2 Substation Location--- County---Hancock Road---Hwy 657 Town---Lewisport

Section 5:3 Circuit Name and Number--- Maxwell Brothers Lumber Feeder 7

Section 5:4 Circuit Location--- Sand hill Rd., Hwy 334

Section 5:5Total Circuit Length----50.02Section 5:6Member count for this circuit---313Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUF	PLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
	)%	0.0%	16.7%	0.0%	41.7%	8.3%	0.0%	33.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.839649	
Section 5:10	Reporting year (SAIDI)	0.282632	
Section 5:11	Circuit 5 year average (SAIFI)	0.008485	
Section 5:12	Reporting year (SAIFI)	0.001856	

**Section 5:13** List of corrective action, if any, taken or to be taken--- **Circuit scheduled for inspection.** 

Section 5:1 Substation name and Number--- Little Dixie 66

Section 5:2 Substation Location--- County---Henderson Road---Lod Powell Rd Town---Corydon

Section 5:3 Circuit Name and Number--- Little Dixie Feeder 1

Section 5:4Circuit Location---Hwy 145Section 5:5Total Circuit Length----64.97Section 5:6Member count for this circuit---406Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	9.1%	31.8%	4.5%	4.5%	18.2%	9.1%	22.7%

Section 5:9Circuit 5 year average (SAIDI)0.624194Section 5:10Reporting year (SAIDI)0.368581Section 5:11Circuit 5 year average (SAIFI)0.011953Section 5:12Reporting year (SAIFI)0.009281

Section 5:13 List of corrective action, if any, taken or to be taken--- Repaired at time of outage

Section 5:1 Substation name and Number--- Little Dixie 66

Section 5:2 Substation Location--- County---Henderson Road---Lod Powell Rd Town---Corydon

Section 5:3 Circuit Name and Number--- Jonestand Feeder 2

Section 5:4 Circuit Location--- Jack Allen Rd.

Section 5:5Total Circuit Length----49.23Section 5:6Member count for this circuit---217Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	4.8%	28.6%	4.8%	23.8%	14.3%	9.5%	14.3%

Section 5:9Circuit 5 year average (SAIDI)0.442533Section 5:10Reporting year (SAIDI)0.737728Section 5:11Circuit 5 year average (SAIFI)0.006043Section 5:12Reporting year (SAIFI)0.008362

Section 5:13 List of corrective action, if any, taken or to be taken--- Repaired at time of outage

Section 5:1 Substation name and Number--- Little Dixie 66

Section 5:2 Substation Location--- County---Henderson Road---Lod Powell Rd Town---Corydon

Section 5:3 Circuit Name and Number--- Candyland Feeder 3

Section 5:4Circuit Location---Hwy 141Section 5:5Total Circuit Length----43.55Section 5:6Member count for this circuit---157Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	6.7%	33.3%	6.7%	20.0%	13.3%	20.0%	0.0%

Section 5:9Circuit 5 year average (SAIDI)0.468357Section 5:10Reporting year (SAIDI)0.976271Section 5:11Circuit 5 year average (SAIFI)0.005122Section 5:12Reporting year (SAIFI)0.007053

Section 5:13 List of corrective action, if any, taken or to be taken--- Repaired at time of outage

Section 5:1 Substation name and Number--- Lyon County 69

Section 5:2 Substation Location--- County---Lyon Road---Hwy 810 Town---Kuttawa

Section 5:3Circuit Name and Number---Sunnyside Feeder 1Section 5:4Circuit Location---Hwy 810 North

Section 5:5Total Circuit Length----56.36Section 5:6Member count for this circuit---322

Section 5:7 Date of last circuit trim (VM) 2013/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	7.7%	19.2%	7.7%	34.6%	7.7%	11.5%	11.5%

Section 5:9Circuit 5 year average (SAIDI)1.121624Section 5:10Reporting year (SAIDI)2.852905Section 5:11Circuit 5 year average (SAIFI)0.009375Section 5:12Reporting year (SAIFI)0.016953

Section 5:13 List of corrective action, if any, taken or to be taken--- VM to trim circuit, Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Lyon County 69

Section 5:2 Substation Location--- County---Lyon Road---Hwy 810 Town---Kuttawa

Section 5:3Circuit Name and Number---Iron Hill Feeder 2Section 5:4Circuit Location---Suwaee, Moon Bay

Section 5:5Total Circuit Length----53.24Section 5:6Member count for this circuit---842

Section 5:7 Date of last circuit trim (VM) 2013/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	4.2%	12.5%	16.7%	29.2%	25.0%	0.0%	12.5%

Section 5:9Circuit 5 year average (SAIDI)5.920468Section 5:10Reporting year (SAIDI)4.440649Section 5:11Circuit 5 year average (SAIFI)0.058076Section 5:12Reporting year (SAIFI)0.069226

**Section 5:13** List of corrective action, if any, taken or to be taken--- **VM to trim circuit, Circuit scheduled for inspection.** 

Section 5:1 Substation name and Number Lyon Co	ounty 69
--	----------

Section 5:2 Substation Location--- County---Lyon Road---Hwy 810 Town---Kuttawa

Section 5:3 Circuit Name and Number--- Barkley Dam F3

Section 5:4Circuit Location---Hwy 62Section 5:5Total Circuit Length----29.18Section 5:6Member count for this circuit---301Section 5:7Date of last circuit trim (VM)2013/2017

**Section 5:8** List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	25.0%	25.0%	37.5%	0.0%	12.5%	0.0%

Circuit 5 year average (SAIDI)	0.491939
Reporting year (SAIDI)	0.545659
Circuit 5 year average (SAIFI)	0.005842
Reporting year (SAIFI)	0.006558
	Reporting year (SAIDI)  Circuit 5 year average (SAIFI)

Section 5:13 List of corrective action, if any, taken or to be taken--- VM to trim circuit, Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Maceo 28

Section 5:2 Substation Location--- County---Daviess Road---Yelvington Grandview Town---Maceo

Section 5:3 Circuit Name and Number--- Chestnut Grove Rd Feeder 1

Section 5:4 Circuit Location--- Kelly Cemetery Road

Section 5:5Total Circuit Length----22.46Section 5:6Member count for this circuit---85Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	14.3%	14.3%	0.0%	28.6%	0.0%	0.0%	42.9%

Section 5:9	Circuit 5 year average (SAIDI)	0.219785
Section 5:10	Reporting year (SAIDI)	0.117486
Section 5:11	Circuit 5 year average (SAIFI)	0.002289
Section 5:12	Reporting year (SAIFI)	0.001025

Section 5:13 List of corrective action, if any, taken or to be taken--- Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Maceo 28

Section 5:2 Substation Location--- County---Daviess Road---Yelvington Grandview Rd Town---Maceo

Section 5:3 Circuit Name and Number--- Maceo Feeder 2

Section 5:4Circuit Location---Hwy 60Section 5:5Total Circuit Length----20.66Section 5:6Member count for this circuit---209Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	50.0%	33.3%	0.0%	16.7%	0.0%	0.0%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.469705

 Section 5:10
 Reporting year (SAIDI)
 0.077411

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.005103

 Section 5:12
 Reporting year (SAIFI)
 0.000407

Section 5:13 List of corrective action, if any, taken or to be taken Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Maceo 28

Section 5:2 Substation Location--- County---Daviess Road---Yelvington Grandview Rd Town---Maceo

Section 5:3 Circuit Name and Number--- Daviess co. Fish/Game Feeder 3

Section 5:4Circuit Location---Hwy 662Section 5:5Total Circuit Length----34.33Section 5:6Member count for this circuit----203Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	25.0%	8.3%	16.7%	16.7%	16.7%	16.7%

 Section 5:9
 Circuit 5 year average (SAIDI)
 1.248274

 Section 5:10
 Reporting year (SAIDI)
 0.749589

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.008407

 Section 5:12
 Reporting year (SAIFI)
 0.004808

Section 5:13 List of corrective action, if any, taken or to be taken Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Maceo 28

Section 5:2 Substation Location--- County---Daviess Road---Yelvington Grandview Rd Town---Maceo

Section 5:3 Circuit Name and Number--- Carpenters Lake Feeder 4

Section 5:4 Circuit Location--- Saur Rd., Hwy 405

Section 5:5Total Circuit Length----18.77Section 5:6Member count for this circuit---257Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	16.7%	16.7%	16.7%	50.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.617041
Section 5:10	Reporting year (SAIDI)	0.034277
Section 5:11	Circuit 5 year average (SAIFI)	0.004977
Section 5:12	Reporting year (SAIFI)	0.000566

Section 5:13 List of corrective action, if any, taken or to be taken--- Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Maceo 28

Section 5:2 Substation Location--- County---Daviess Road---Yelvington Grandview Rd Town---Maceo

Section 5:3 Circuit Name and Number--- Stinnet Road Feeder 5

Section 5:4Circuit Location---Stinnet Rd.Section 5:5Total Circuit Length----12.51

Section 5:6Member count for this circuit---95Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	50.0%	0.0%	33.3%	0.0%	0.0%	16.7%

Section 5:9	Circuit 5 year average (SAIDI)	0.079843
Section 5:10	Reporting year (SAIDI)	0.017855
Section 5:11	Circuit 5 year average (SAIFI)	0.001062
Section 5:12	Reporting year (SAIFI)	0.000177

Section 5:13 List of corrective action, if any, taken or to be taken Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Madisonville 49

Section 5:2 Substation Location--- County---Hopkins Road---Nebo Road Town----Madisonville

Section 5:3 Circuit Name and Number--- Industrial Park Feeder 1
Section 5:4 Circuit Location--- Tucker Schoolhouse Rd.

Section 5:5Total Circuit Length----12.67Section 5:6Member count for this circuit---167Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	12.5%	25.0%	0.0%	0.0%	62.5%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.367381
Section 5:10	Reporting year (SAIDI)	0.083068
Section 5:11	Circuit 5 year average (SAIFI)	0.006458
Section 5:12	Reporting year (SAIFI)	0.001361

Section 5:13 List of corrective action, if any, taken or to be taken--- Added Critter guard

Section 5:1 Substation name and Number--- Madisonville 49

Section 5:2 Substation Location--- County---Hopkins Road---Nebo Road Town----Madisonville

Section 5:3 Circuit Name and Number--- Manitou Feeder 2

Section 5:4Circuit Location---Hwy 41ASection 5:5Total Circuit Length----36.5Section 5:6Member count for this circuit----286Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	14.3%	28.6%	7.1%	7.1%	28.6%	0.0%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.043099
Section 5:10	Reporting year (SAIDI)	0.151145
Section 5:11	Circuit 5 year average (SAIFI)	0.000525
Section 5:12	Reporting year (SAIFI)	0.001556

Section 5:13 List of corrective action, if any, taken or to be taken--- Resolved at time of outage.

Section 5:1 Substation name and Number--- Madisonville 49

Section 5:2 Substation Location--- County---Hopkins Road---Nebo Road Town----Madisonville

Section 5:3 Circuit Name and Number--- Land of Frost Feeder 3

Section 5:4 Circuit Location--- Land of Frost

Section 5:5Total Circuit Length----0.8Section 5:6Member count for this circuit---1Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.000225
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.000011
Section 5:12	Reporting year (SAIFI)	0.000000
C		

**Section 5:13** List of corrective action, if any, taken or to be taken

Section 5:1 Substation name and Number--- Marion 70

Section 5:2 Substation Location--- County---Crittenden Road---Sparmill Rd Town---Marion

Section 5:3 Circuit Name and Number--- Mattoon Feeder 1

Section 5:4Circuit Location---Hwy 120Section 5:5Total Circuit Length----102.31Section 5:6Member count for this circuit----451

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	18.2%	9.1%	36.4%	18.2%	0.0%	18.2%

Section 5:9	Circuit 5 year average (SAIDI)	0.491694
Section 5:10	Reporting year (SAIDI)	0.041560
Section 5:11	Circuit 5 year average (SAIFI)	0.006441
Section 5:12	Reporting year (SAIFI)	0.000725
Continu F.13	the of compating patient if any application has been been	

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit, VM scheduled to trim circuit

Section 5:1 Substation name and Number--- Marion 70

Section 5:2 Substation Location--- County---Crittenden Road---Sparmill Rd Town---Marion

Section 5:3 Circuit Name and Number--- Princeton Feeder 2
Section 5:4 Circuit Location--- Piney Creek Rd.

Section 5:5Total Circuit Length----78.42Section 5:6Member count for this circuit---319

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	26.7%	0.0%	40.0%	20.0%	0.0%	13.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.676320
Section 5:10	Reporting year (SAIDI)	0.349542
Section 5:11	Circuit 5 year average (SAIFI)	0.004458
Section 5:12	Reporting year (SAIFI)	0.003483
Continu F.13	the of compating agency of any advangage by tall-	

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit, VM scheduled to trim circuit

Section 5:1 Substation name and Number--- Marion 70

Section 5:2 Substation Location--- County---Crittenden Road---Sparmill Rd Town---Marion

Section 5:3Circuit Name and Number---Sheridan Feeder 3Section 5:4Circuit Location---Crittenden Springs Rd.

Section 5:5Total Circuit Length----170.48Section 5:6Member count for this circuit---268

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	22.2%	22.2%	11.1%	33.3%	0.0%	0.0%	11.1%

Section 5:9	Circuit 5 year average (SAIDI)	0.371287
Section 5:10	Reporting year (SAIDI)	0.363384
Section 5:11	Circuit 5 year average (SAIFI)	0.002365
Section 5:12	Reporting year (SAIFI)	0.001591
Costion F.12	List of compating action if any taken as to be take	

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit, VM scheduled to trim circuit

Section 5:1 Substation name and Number--- Marion 70

Substation Location---

County---Crittenden Road---Sparmill Rd

Town----Marion

Section 5:3 Circuit Name and Number---

Dam 50 Feeder 4

10WII---IVIAIIOII

Section 5:4 Circuit Location---

Hwy 91 North

Section 5:5 Total Circuit Length----

78.34

Section 5:6

76.34

Section 5:2

Member count for this circuit--- 729

Section 5:7

Date of last circuit trim (VM) 2012/2017

Section 5:8

List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	2.19	27.7%	17.0%	29.8%	12.8%	2.1%	8.5%

Section 5:9	Circuit 5 year average (SAIDI)	2.912896
Section 5:10	Reporting year (SAIDI)	0.978109
Section 5:11	Circuit 5 year average (SAIFI)	0.029010
Section 5:12	Reporting year (SAIFI)	0.009528
Continu F.13	the of compating patient if any application has been been	

Section 5:13 List of corrective action, if any, taken or to be taken--- Eva

Evaluate & inspection circuit, VM scheduled to trim circuit

Section 5:1 Substation name and Number--- Masonville 23

Section 5:2 Substation Location--- County---Daviess Road---Hill Bridge Rd Town---Masonville

Section 5:3 Circuit Name and Number--- Velvet Farms Pump Feeder 1

Section 5:4 Circuit Location--- Hwy 231 North

Section 5:5Total Circuit Length----17.46Section 5:6Member count for this circuit---255Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0.0%	25.0%	41.7%	0.0%	16.7%	0.0%	8.3%	8.3%

Section 5:9Circuit 5 year average (SAIDI)0.281653Section 5:10Reporting year (SAIDI)0.852562Section 5:11Circuit 5 year average (SAIFI)0.002318Section 5:12Reporting year (SAIFI)0.007584

Section 5:13 List of corrective action, if any, taken or to be taken--- Resolved at time of outage

Section 5:1 Substation name and Number--- Masonville 23

Section 5:2 Substation Location--- County---Daviess Road---Hill Bridge Rd Town---Masonville

Section 5:3 Circuit Name and Number--- Stoney Brook Subdivision Feeder 2

Section 5:4 Circuit Location--- Old Hartford Road

Section 5:5Total Circuit Length----26.22Section 5:6Member count for this circuit---509Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0.0%	9.1%	27.3%	0.0%	9.1%	45.5%	9.1%	0.0%

Section 5:9Circuit 5 year average (SAIDI)0.752401Section 5:10Reporting year (SAIDI)0.066256Section 5:11Circuit 5 year average (SAIFI)0.005544Section 5:12Reporting year (SAIFI)0.001326

Section 5:13 List of corrective action, if any, taken or to be taken--- System improvement work order scheduled.

Section 5:1 Substation name and Number--- Masonville 23

Section 5:2 Substation Location--- County---Daviess Road---Hill Bridge Rd Town---Masonville

Section 5:3Circuit Name and Number---Msonville Feeder 3Section 5:4Circuit Location---Hwy 231 South

Section 5:5Total Circuit Length----54.25Section 5:6Member count for this circuit---688Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	25.0%	8.3%	0.0%	12.5%	29.2%	16.7%	8.3%

Section 5:9	Circuit 5 year average (SAIDI)	1.210221
Section 5:10	Reporting year (SAIDI)	0.273811
Section 5:11	Circuit 5 year average (SAIFI)	0.020150
Section 5:12	Reporting year (SAIFI)	0.004066

Section 5:13 List of corrective action, if any, taken or to be taken--- System improvement work order scheduled.

Section 5:1 Substation name and Number--- Morganfield 71

Section 5:2 Substation Location--- County---Union Road---Tina Waggener Rd Town---Morganfield

Section 5:3 Circuit Name and Number--- Waverly Feeder 1
Section 5:4 Circuit Location--- Hwy 141, Hwy 666

Section 5:5Total Circuit Length----102.73Section 5:6Member count for this circuit---505Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	2.1%	14.9%	4.3%	40.4%	14.9%	4.3%	19.1%

Section 5:9	Circuit 5 year average (SAIDI)	1.555222
Section 5:10	Reporting year (SAIDI)	1.432339
Section 5:11	Circuit 5 year average (SAIFI)	0.017794
Section 5:12	Reporting year (SAIFI)	0.012905

Section 5:13 List of corrective action, if any, taken or to be taken--- Look at adding additional lightning protection.

Section 5:1 Substation name and Number--- Morganfield 71

Section 5:2 Substation Location--- County---Union Road---Tina Waggener Rd Town---Morganfield

Section 5:3Circuit Name and Number---Boxville Feeder 2Section 5:4Circuit Location---Blueberry HillSection 5:5Total Circuit Length----120.61Section 5:6Member count for this circuit---711Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	18.8%	34.4%	9.4%	25.0%	6.3%	6.3%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	3.498910
Section 5:10	Reporting year (SAIDI)	0.588510
Section 5:11	Circuit 5 year average (SAIFI)	0.034814
Section 5:12	Reporting year (SAIFI)	0.005834

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit.

Section 5:1 Substation name and Number--- Morganfield 71

Section 5:2 Substation Location--- County---Union Road---Tina Waggener Rd Town---Morganfield

Section 5:3Circuit Name and Number---Caseyville Feeder 3Section 5:4Circuit Location---Hwy 109, Hwy 1508

Section 5:5Total Circuit Length----84.42Section 5:6Member count for this circuit---428Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	4.2%	12.5%	50.0%	8.3%	0.0%	25.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.611521
Section 5:10	Reporting year (SAIDI)	0.178086
Section 5:11	Circuit 5 year average (SAIFI)	0.006910
Section 5:12	Reporting year (SAIFI)	0.001998

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit.

Section 5:1 Substation name and Number--- Morganfield 71

Section 5:2 Substation Location--- County---Union Road---Tina Waggener Rd Town---Morganfield

Section 5:3 Circuit Name and Number--- Spring Grove Feeder 4

Section 5:4 Circuit Location--- Hwy 56, Hwy 360

Section 5:5Total Circuit Length----74.18Section 5:6Member count for this circuit---337Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	14.8%	11.1%		7.4%	11.1%	14.8%

Section 5:9	Circuit 5 year average (SAIDI)	1.664106
Section 5:10	Reporting year (SAIDI)	1.077229
Section 5:11	Circuit 5 year average (SAIFI)	0.016570
Section 5:12	Reporting year (SAIFI)	0.006700

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit.

Section 5:1 Substation name and Number--- Niagara 80

Section 5:2 Substation Location--- County---Henderson Road---Hwy 136 Town---Henderson

Section 5:3 Circuit Name and Number--- Niagara Feeder 1

Section 5:4Circuit Location---Hwy 136Section 5:5Total Circuit Length----102.6Section 5:6Member count for this circuit---703Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	2.8%	19.4%	16.7%	44.4%	2.8%	5.6%	8.3%

Section 5:9Circuit 5 year average (SAIDI)1.133099Section 5:10Reporting year (SAIDI)0.386824Section 5:11Circuit 5 year average (SAIFI)0.011994Section 5:12Reporting year (SAIFI)0.005480

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit,

Section 5:1 Substation name and Number--- Niagara 80

Section 5:2 Substation Location--- County---Henderson Road---Hwy 136 Town---Henderson

Section 5:3 Circuit Name and Number--- Hwy 283 South Feeder 2

Section 5:4 Circuit Location--- Pleasant Valley Rd

Section 5:5Total Circuit Length----58.22Section 5:6Member count for this circuit---443Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	4.3%	26.1%	4.3%	26.1%	26.1%	8.7%	4.3%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.578644

 Section 5:10
 Reporting year (SAIDI)
 0.536732

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.008284

 Section 5:12
 Reporting year (SAIFI)
 0.014284

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit,

Section 5:1 Substation name and Number--- Niagara 80

Section 5:2 Substation Location--- County---Henderson Road---Hwy 136 Town---Henderson

Section 5:3 Circuit Name and Number--- Anthoston Feeder 3
Section 5:4 Circuit Location--- Hwy 41 south

Section 5:5Total Circuit Length----37.9Section 5:6Member count for this circuit---370Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	7.7%	38.5%	15.4%	7.7%	23.1%	7.7%	0.0%

Section 5:9Circuit 5 year average (SAIDI)0.360321Section 5:10Reporting year (SAIDI)0.056392Section 5:11Circuit 5 year average (SAIFI)0.006171Section 5:12Reporting year (SAIFI)0.000601

**Section 5:13** List of corrective action, if any, taken or to be taken--- **Resolved at time of outage.** 

Section 5:1	Substation name and Number	Nuckols 42
Jechon J.T	Substation name and Number	IVUUNUIS 72

Section 5:2 Substation Location--- County---McLean Road---Hwy 431 Town---Livia

Section 5:3 Circuit Name and Number--- Barmet #1 Feeder 1

Section 5:4Circuit Location---Hwy 431Section 5:5Total Circuit Length----1.59Section 5:6Member count for this circuit---12Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPL	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0	0.0%	0.0%	25.0%	75.0%	0.0%	0.0%	0.0%

Circuit 5 year average (SAIDI)	0.012825
Reporting year (SAIDI)	0.041366
Circuit 5 year average (SAIFI)	0.000234
Reporting year (SAIFI)	0.000742
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

**Section 5:13** List of corrective action, if any, taken or to be taken--- **Resolved at time of outage.** 

Section 5:1 Substation name and Number--- Nuckols 42

Section 5:2 Substation Location--- County---McLean Road---Hwy 431 Town---Livia

Section 5:3 Circuit Name and Number--- Barmet #2 Feeder 2

Section 5:4Circuit Location---Hwy 431Section 5:5Total Circuit Length----0.74Section 5:6Member count for this circuit---1Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	100.0%	0.0%	0.0%	0.0%

Section 5:9Circuit 5 year average (SAIDI)0.000106Section 5:10Reporting year (SAIDI)0.000530Section 5:11Circuit 5 year average (SAIFI)0.000007Section 5:12Reporting year (SAIFI)0.000035

**Section 5:13** List of corrective action, if any, taken or to be taken **Resolved at time of outage.** 

Section 5:1 Substation name and Number--- Nuckols 42

Section 5:2 Substation Location--- County---McLean Road---Hwy 431 Town---Livia

Section 5:3Circuit Name and Number---Nuckols Feeder 3Section 5:4Circuit Location---Hwy 136, Hwy 1080

Section 5:5Total Circuit Length----60.95Section 5:6Member count for this circuit---408Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	5.6%	11.1%	0.0%	55.6%	5.6%	5.6%	16.7%

Section 5:9	Circuit 5 year average (SAIDI)	0.657089
Section 5:10	Reporting year (SAIDI)	0.182364
Section 5:11	Circuit 5 year average (SAIFI)	0.006045
Section 5:12	Reporting year (SAIFI)	0.001909

Section 5:13 List of corrective action, if any, taken or to be taken--- Look at adding additional lightning protection.

Section 5:1 Substation name and Number--- Nuckols 42

County---McLean Road---Hwy 431 Town---Livia

Section 5:3 Circuit Name and Number--- Hwy 250/Buel Feeder 4

Section 5:4 Circuit Location--- Hwy 250/Hwy 798

Section 5:5Total Circuit Length----60.42Section 5:6Member count for this circuit---367Section 5:7Date of last circuit trim (VM)2014

Substation Location---

Section 5:2

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	5.3%	5.3%	31.6%	31.6%	5.3%	21.1%

Section 5:9	Circuit 5 year average (SAIDI)	0.652311
Section 5:10	Reporting year (SAIDI)	0.378710
Section 5:11	Circuit 5 year average (SAIFI)	0.008017
Section 5:12	Reporting year (SAIFI)	0.002616

Section 5:13 List of corrective action, if any, taken or to be taken--- Added Critter guard

Section 5:1 Substation name and Number--- Onton 52

Section 5:2 Substation Location--- County---Webster Road---Hwy 41 Town---Slaughters

Section 5:3 Circuit Name and Number--- Hwy 120 Feeder 1

Section 5:4 Circuit Location--- Hwy 1069, Texas Gas Rd.

Section 5:5Total Circuit Length----83.57Section 5:6Member count for this circuit---400Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	21.4%	7.1%	42.9%	14.3%	0.0%	14.3%

Section 5:9Circuit 5 year average (SAIDI)0.747485Section 5:10Reporting year (SAIDI)1.308984Section 5:11Circuit 5 year average (SAIFI)0.006964Section 5:12Reporting year (SAIFI)0.006488

Section 5:13 List of corrective action, if any, taken or to be taken--- Resolved at time of outage

Section 5:1 Substation name and Number--- Onton 52

Section 5:2 Substation Location--- County---Webster Road---Hwy 41 Town---Slaughters

Section 5:3Circuit Name and Number---Sebree Feeder 2Section 5:4Circuit Location---Hwy 41, Hwy 147

Section 5:5Total Circuit Length----66.76Section 5:6Member count for this circuit---415Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	7.1%	35.7%	0.0%	14.3%	14.3%	14.3%	14.3%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.296492

 Section 5:10
 Reporting year (SAIDI)
 0.372912

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.004720

 Section 5:12
 Reporting year (SAIFI)
 0.007867

Section 5:13 List of corrective action, if any, taken or to be taken--- Resolved at time of outage

Section 5:1 Substation name and Number--- Onton 52

Section 5:2 Substation Location--- County---Webster Road---Hwy 41 Town---Slaughters

Section 5:3 Circuit Name and Number--- Vandetta Road Feeder 3
Section 5:4 Circuit Location--- Hwy 1033, Hwy 281

Section 5:5Total Circuit Length----47.1Section 5:6Member count for this circuit---239Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	5.0%	20.0%	15.0%	40.0%	10.0%	5.0%	5.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.343818
Section 5:10	Reporting year (SAIDI)	0.566183
Section 5:11	Circuit 5 year average (SAIFI)	0.002616
Section 5:12	Reporting year (SAIFI)	0.003536

Section 5:13 List of corrective action, if any, taken or to be taken--- Resolved at time of outage.

Section 5:1	Substation name and Number	Philpot 25
-------------	----------------------------	------------

Section 5:2 Substation Location--- County---Daviess Road---Winkler Town---Philpot

Section 5:3 Circuit Name and Number--- Pleasant Valley Rd. Feeder 1
Section 5:4 Circuit Location--- Knottsville, Pleasant Point

Section 5:5Total Circuit Length----56.38Section 5:6Member count for this circuit---461Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	7.7%	23.1%	23.1%	23.1%	7.7%	7.7%	7.7%

Section 5:9	Circuit 5 year average (SAIDI)	1.207841
Section 5:10	Reporting year (SAIDI)	1.455355
Section 5:11	Circuit 5 year average (SAIFI)	0.009930
Section 5:12	Reporting year (SAIFI)	0.017855

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit

Section 5:1 Substation name and Number--- Philpot 25

Section 5:2 Substation Location--- County---Daviess Road---Winkler Town---Philpot

Section 5:3 Circuit Name and Number--- Old State Road Feeder 3

Section 5:4 Circuit Location--- Old 54, Habit

Section 5:5Total Circuit Length----32.91Section 5:6Member count for this circuit---294Section 5:7Date of last circuit trim (VM)2015

**Section 5:8** List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	11.1%	33.3%	0.0%	22.2%	11.1%	0.0%	22.2%

Section 5:9	Circuit 5 year average (SAIDI)	0.289468
Section 5:10	Reporting year (SAIDI)	0.023511
Section 5:11	Circuit 5 year average (SAIFI)	0.004110
Section 5:12	Reporting year (SAIFI)	0.000336

Section 5:1	Substation name and Number	Philpot 25
-------------	----------------------------	------------

Section 5:2 Substation Location--- County---Daviess Road---Winkler Town---Philpot

Section 5:3 Circuit Name and Number--- Premium Alled Tool F4

Section 5:4 Circuit Location--- Cedar Hills, Hagans

Section 5:5Total Circuit Length----6.53Section 5:6Member count for this circuit---93Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	0.0%	100.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.052388
Section 5:10	Reporting year (SAIDI)	0.005834
Section 5:11	Circuit 5 year average (SAIFI)	0.001440
Section 5:12	Reporting year (SAIFI)	0.000106
		_

Section 5:1	Substation name and Number	Philpot 25
-------------	----------------------------	------------

Section 5:2 Substation Location--- County---Daviess Road---Winkler Town---Philpot

Section 5:3 Circuit Name and Number--- Karnes Grove Road Feeder 5

Section 5:4Circuit Location---Hwy 54Section 5:5Total Circuit Length----55.01Section 5:6Member count for this circuit---417Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER	RSUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
	0%	4.5%	31.8%	4.5%	27.3%	9.1%	13.6%	9.1%

Section 5:9	Circuit 5 year average (SAIDI)	0.200971
Section 5:10	Reporting year (SAIDI)	0.102248
Section 5:11	Circuit 5 year average (SAIFI)	0.002005
Section 5:12	Reporting year (SAIFI)	0.001697

Section 5:1	Substation name and Number	Philpot 25
-------------	----------------------------	------------

Section 5:2 Substation Location--- County---Daviess Road---Winkler Town---Philpot

Section 5:3 Circuit Name and Number--- Cedar Hills Feeder 7

Section 5:4 Circuit Location--- Jack Hinton Rd., Short Station Rd.

Section 5:5Total Circuit Length----51.83Section 5:6Member count for this circuit---454Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUP	LY PLAN	NNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
	)%	10.5%	26.3%	5.3%	15.8%	21.1%	0.0%	21.1%

Section 5:9	Circuit 5 year average (SAIDI)	0.808472
Section 5:10	Reporting year (SAIDI)	0.758782
Section 5:11	Circuit 5 year average (SAIFI)	0.008204
Section 5:12	Reporting year (SAIFI)	0.005568

Section 5:1 Substation name and Number--- Pleasant Ridge 26

Section 5:2 Substation Location--- County---Ohio Road---Hwy 764 Town---Pleasant Ridge

Section 5:3 Circuit Name and Number--- Bells Run Feeder 1

Section 5:4Circuit Location---Hwy 764Section 5:5Total Circuit Length----34.65Section 5:6Member count for this circuit---253Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	11.8%	0.0%	5.9%	29.4%	11.8%	29.4%	11.8%

Section 5:9	Circuit 5 year average (SAIDI)	0.862442
Section 5:10	Reporting year (SAIDI)	2.727941
Section 5:11	Circuit 5 year average (SAIFI)	0.008208
Section 5:12	Reporting year (SAIFI)	0.018986

Section 5:1 Substation name and Number--- Pleasant Ridge 26

Section 5:2 Substation Location--- County---Ohio Road---Hwy 764 Town---Pleasant Ridge

Section 5:3 Circuit Name and Number--- Maple Leaf Lake Feeder 2

Section 5:4Circuit Location---Hwy 231Section 5:5Total Circuit Length----56.05Section 5:6Member count for this circuit---536Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

F	POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
	0%	12.0%	8.0%	24.0%	16.0%	20.0%	0.0%	20.0%

Section 5:9Circuit 5 year average (SAIDI)0.545569Section 5:10Reporting year (SAIDI)0.797408Section 5:11Circuit 5 year average (SAIFI)0.006480Section 5:12Reporting year (SAIFI)0.005940

Section 5:1 Substation name and Number--- Pleasant Ridge 26

Section 5:2 Substation Location--- County---Ohio Road---Hwy 764 Town---Pleasant Ridge

Section 5:3 Circuit Name and Number--- Poplar Log Bridge Feeder 3

Section 5:4 Circuit Location--- Hwy 231, Crane Pond

Section 5:5Total Circuit Length----39.54Section 5:6Member count for this circuit---252Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER S	SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
	0%	0.0%	7.7%	15.4%	46.2%	7.7%	0.0%	23.1%

Section 5:9	Circuit 5 year average (SAIDI)	0.634490	
Section 5:10	Reporting year (SAIDI)	0.143225	
Section 5:11	Circuit 5 year average (SAIFI)	0.005284	
Section 5:12	Reporting year (SAIFI)	0.006983	
Castian F.13	Contract and Contr		

Section 5:1	Substation name and Number	Pleasant Ridge 26
-------------	----------------------------	-------------------

Section 5:2 Substation Location--- County---Ohio Road---Hwy 764 Town---Pleasant Ridge

Section 5:3 Circuit Name and Number--- Hwy 140 west Feeder 4
Section 5:4 Circuit Location--- Hwy 140, Girl Scout Rd.

Section 5:5Total Circuit Length----19.51Section 5:6Member count for this circuit---144Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	12.5%	37.5%	37.5%	12.5%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.087867
Section 5:10	Reporting year (SAIDI)	0.023016
Section 5:11	Circuit 5 year average (SAIFI)	0.002239
Section 5:12	Reporting year (SAIFI)	0.002758
Section E-12	List of corrective action if any taken or to	ho takan Poselyed a

#### **Section 5: Circuit Reporting 2016**

#### (Circuits with SAIDI and /or SAIFI exceeding 5 year average)

#### Circuit Numbers should be reported excluding MED

#### Removed from service 2015

Section 5:1 Substation name and Number--- Portable 59

Section 5:2 Substation Location--- County---Hancock Road---Skillman Town---Hawesville

Section 5:3 Circuit Name and Number--- Cannelton F1

Section 5:4 Circuit Location--- Mason Rd., Skillman Rd.

 Section 5:5
 Total Circuit Length--- 1.4

 Section 5:6
 Member count for this circuit--- 26

 Section 5:7
 Date of last circuit trim (VM)
 2011

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	WEATHER	ANIMAL	PUBLIC	UNKNOWN	ROW
0%	0%	0%	0%	0%	0%	0%	0%

Section 5:9	Circuit 5 year average (SAIDI)	0.057858
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.000517
Section 5:12	Reporting year (SAIFI)	0.000000
		_

Section 5:13 List of corrective action, if any, taken or to be taken--- Removed from service.

Section 5:1	Substation name and Number	Providence 81

Section 5:2 Substation Location--- County---Hopkins Road---Cutoff Rd Town---Providence

Section 5:3Circuit Name and Number---Providence Feeder 1Section 5:4Circuit Location---Hwy 120, Hwy 293

Section 5:5Total Circuit Length----64.03Section 5:6Member count for this circuit---314Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	13.3%	13.3%	0.0%	20.0%	20.0%	0.0%	33.3%

Section E-12	List of corrective action if any taken or to be taken		Posolyad at tin
Section 5:12	Reporting year (SAIFI)	0.003483	
Section 5:11	Circuit 5 year average (SAIFI)	0.010868	
Section 5:10	Reporting year (SAIDI)	0.154344	
Section 5:9	Circuit 5 year average (SAIDI)	1.357327	

Section 5:1	Substation name and Number	Providence 81

Section 5:2 Substation Location--- County---Hopkins Road---Cutoff Rd Town---Providence

Section 5:3 Circuit Name and Number--- Dalton Feeder 2

Section 5:4Circuit Location---Hwy 109Section 5:5Total Circuit Length----65.66Section 5:6Member count for this circuit---390Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	17.6%	0.0%	58.8%	0.0%	0.0%	23.5%

Section 5:13	List of corrective action, if any, taken or to be taker	1	Look at adding additional lightning protection.	Evaluate & inspection circuit
Section 5:12	Reporting year (SAIFI)	0.001167		
Section 5:11	Circuit 5 year average (SAIFI)	0.007514		
Section 5:10	Reporting year (SAIDI)	0.089432		
Section 5:9	Circuit 5 year average (SAIDI)	0.851655		

Section 5:1 Substation name and Number Provid
---

Section 5:2 Substation Location--- County---Hopkins Road---Cutoff Rd Town---Providence

Section 5:3 Circuit Name and Number--- Liberty Feeder 4

Section 5:4 Circuit Location--- Hwy 120 East, Hwy 41A

Section 5:5Total Circuit Length----80.07Section 5:6Member count for this circuit---428Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPP	Y PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
C	% 9.5%	14.3%	9.5%	23.8%	19.0%	9.5%	14.3%

Section 5:13	List of corrective action, if any, taken or to be taken	)	Look at adding additional lightning protection.	Evaluate & inspection circuit
Section 5:12	Reporting year (SAIFI)	0.003111		
Section 5:11	Circuit 5 year average (SAIFI)	0.009299		
Section 5:10	Reporting year (SAIDI)	0.462450		
Section 5:9	Circuit 5 year average (SAIDI)	0.872773		

Section 5:1 Substation name and Number--- Race Creek 82

Section 5:2 Substation Location--- County---Henderson Road---Hwy 1078 Town---Henderson

Section 5:3 Circuit Name and Number--- Spottsville Feeder 1

Section 5:4 Circuit Location--- Hwy 1078 South

Section 5:5Total Circuit Length----29.22Section 5:6Member count for this circuit---306Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	12.5%	12.5%	18.8%	25.0%	6.3%	0.0%	25.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.739294
Section 5:10	Reporting year (SAIDI)	0.145806
Section 5:11	Circuit 5 year average (SAIFI)	0.008427
Section 5:12	Reporting year (SAIFI)	0.001785

Section 5:1 Substation name and Number--- Race Creek 82

Section 5:2 Substation Location--- County---Henderson Road---Hwy 1078 Town---Henderson

Section 5:3Circuit Name and Number---Baskett Feeder 2Section 5:4Circuit Location---Country Club

Section 5:5Total Circuit Length----28.03Section 5:6Member count for this circuit---444Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	33.3%	11.1%	22.2%	0.0%	33.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.345242
Section 5:10	Reporting year (SAIDI)	0.972347
Section 5:11	Circuit 5 year average (SAIFI)	0.005602
Section 5:12	Reporting year (SAIFI)	0.017908

Section 5:1 Substation name and Number--- Race Creek 82

Section 5:2 Substation Location--- County---Henderson Road---Hwy 1078 Town---Henderson

Section 5:3 Circuit Name and Number--- Rucker Road #1 Feeder 3

Section 5:4 Circuit Location--- Hwy 60, Wathem Lane

Section 5:5Total Circuit Length----36.26Section 5:6Member count for this circuit---374Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	5.9%	29.4%	23.5%	11.8%	17.6%	11.8%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.316697

 Section 5:10
 Reporting year (SAIDI)
 0.260835

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.003885

 Section 5:12
 Reporting year (SAIFI)
 0.004207

Section 5:1 Substation name and Number--- Riverport 83

Section 5:2 Substation Location--- County---Henderson Road--- Town---Henderson

Section 5:3 Circuit Name and Number--- Valley Grain Feeder 1

Section 5:4 Circuit Location--- Valley Grain Plant

Section 5:5Total Circuit Length----0.02Section 5:6Member count for this circuit---1

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPE	LY PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
(	0.0%	0.0%	0.0%	0.0%	100.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.004046
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.000055
Section 5:12	Reporting year (SAIFI)	0.000000
Saction E-12	List of corrective action if any taken	ar to be taken

**Section 5:13** List of corrective action, if any, taken or to be taken---

Section 5:1 Substation name and Number--- Riverport 83

Section 5:2 Substation Location--- County---Henderson Road--- Town---Henderson

Section 5:3 Circuit Name and Number--- Unison Feeder 2
Section 5:4 Circuit Location--- Industrial Drive

Section 5:5Total Circuit Length----1.54Section 5:6Member count for this circuit---10

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPL	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
09	0.0%	0.0%	0.0%	0.0%	100.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.000328		
Section 5:10	Reporting year (SAIDI)	0.000000		
Section 5:11	Circuit 5 year average (SAIFI)	0.000007		
Section 5:12	Reporting year (SAIFI)	0.000000		
Section 5:13	List of corrective action, if any, taken or to be taken			

Section 5:1 Substation name and Number--- Riverport 83

Section 5:2 Substation Location--- County---Henderson Road--- Town---Henderson

Section 5:3Circuit Name and Number---Shamrock Feeder 3Section 5:4Circuit Location---Shamrock Tecnologies

Section 5:5 Total Circuit Length---- 0.49
Section 5:6 Member count for this circuit--- 3

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPL	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
09	0.0%	0.0%	0.0%	0.0%	100.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.000000			
Section 5:10	Reporting year (SAIDI)	0.000000			
Section 5:11	Circuit 5 year average (SAIFI)	0.000007			
Section 5:12	Reporting year (SAIFI)	0.000000			
Section 5:13	List of corrective action, if any, taken or to be taken				

Section 5:1 Substation name and Number--- Sacramento 50

Section 5:2 Substation Location--- County---McLean Road---Hwy 254 Town---Sacramento

Section 5:3 Circuit Name and Number--- Hwy 81 North Feeder 1

Section 5:4 Circuit Location--- Hwy 81, Hwy 85

Section 5:5Total Circuit Length----49.3Section 5:6Member count for this circuit---265Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	15.8%	0.0%	26.3%	31.6%	15.8%	10.5%

Section 5:9	Circuit 5 year average (SAIDI)	0.475909
Section 5:10	Reporting year (SAIDI)	1.152447
Section 5:11	Circuit 5 year average (SAIFI)	0.004370
Section 5:12	Reporting year (SAIFI)	0.004207

Section 5:13 List of corrective action, if any, taken or to be taken--- Circuit scheduled for inspection.

Section 5:1 Substation name and Number--- Sacramento 50

Section 5:2 Substation Location--- County---McLean Road---Hwy 254 Town---Sacramento

Section 5:3 Circuit Name and Number--- Hwy 81 South Feeder 3

Section 5:4 Circuit Location--- Hwy 81, Hwy 85

Section 5:5Total Circuit Length----24.81Section 5:6Member count for this circuit---130Section 5:7Date of last circuit trim (VM)2014

**Section 5:8** List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER	SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
	0%	0.0%	0.0%	0.0%	66.7%	8.3%	0.0%	25.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.245527
Section 5:10	Reporting year (SAIDI)	0.091783
Section 5:11	Circuit 5 year average (SAIFI)	0.002814
Section 5:12	Reporting year (SAIFI)	0.000725

**Section 5:13** List of corrective action, if any, taken or to be taken--- **Circuit scheduled for inspection.** 

Section 5:1 Substation name and Number--- Sacramento 50

Section 5:2 Substation Location--- County---McLean Road---Hwy 254 Town---Sacramento

Section 5:3 Circuit Name and Number--- Poplar Grove Feeder 4

Section 5:4 Circuit Location--- Hwy 1155, Bell Rd.

 Section 5:5
 Total Circuit Length--- 53.71

 Section 5:6
 Member count for this circuit-- 293

 Section 5:7
 Date of last circuit trim (VM)
 2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	30.4%	13.0%	0.0%	21.7%	26.1%	0.0%	8.7%

Section 5:9	Circuit 5 year average (SAIDI)	0.579619
Section 5:10	Reporting year (SAIDI)	0.128323
Section 5:11	Circuit 5 year average (SAIFI)	0.008575
Section 5:12	Reporting year (SAIFI)	0.005957
		_

Section 5:13 List of corrective action, if any, taken or to be taken--- Circuit scheduled for inspection. System improvement work order scheduled.

Section 5:1 Substation name and Number--- Sebree 84

Section 5:2 Substation Location--- County---Webster Road---Hwy 283 Town---Sebree

Section 5:3Circuit Name and Number---Robards Feeder 1Section 5:4Circuit Location---Hwy 283, Hwy 416

Section 5:5Total Circuit Length----29.34Section 5:6Member count for this circuit---137Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	11.1%	11.1%	0.0%	22.2%	22.2%	0.0%	33.3%

Circuit 5 year average (SAIDI)	0.110336
Reporting year (SAIDI)	0.050293
Circuit 5 year average (SAIFI)	0.001534
Reporting year (SAIFI)	0.001114
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- Sebree 84

Section 5:2 Substation Location--- County---Webster Road---Hwy 283 Town---Sebree

Section 5:3 Circuit Name and Number--- N/S Truck Stop Feeder 2

Section 5:4 Circuit Location--- Watkins School Rd.

Section 5:5Total Circuit Length----28.85Section 5:6Member count for this circuit---166Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	28.6%	0.0%	28.6%	28.6%	0.0%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.083856
Section 5:10	Reporting year (SAIDI)	0.086480
Section 5:11	Circuit 5 year average (SAIFI)	0.000994
Section 5:12	Reporting year (SAIFI)	0.001361

Section 5:1 Substation name and Number--- Sebree 84

Section 5:2 Substation Location--- County---Webster Road---Hwy 283 Town---Sebree

Section 5:3Circuit Name and Number---Ortiz Feeder 3Section 5:4Circuit Location---Hwy 132, Hwy 138

Section 5:5Total Circuit Length----68.47Section 5:6Member count for this circuit---533Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	9.5%	33.3%	0.0%	23.8%	9.5%	4.8%	19.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.882085
Section 5:10	Reporting year (SAIDI)	0.087098
Section 5:11	Circuit 5 year average (SAIFI)	0.014942
Section 5:12	Reporting year (SAIFI)	0.001397

Section 5:1 Substation name and Number--- Sebree 84

Section 5:2 Substation Location--- County---Webster Road---Hwy 283 Town---Sebree

Section 5:3 Circuit Name and Number--- Poole Feeder 4

Section 5:4Circuit Location---Hwy 56Section 5:5Total Circuit Length----22.98Section 5:6Member count for this circuit---122Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	40.0%	60.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.138521
Section 5:10	Reporting year (SAIDI)	0.008008
Section 5:11	Circuit 5 year average (SAIFI)	0.001567
Section 5:12	Reporting year (SAIFI)	0.000159

Section 5:1 Substation name and Number--- South Dermont 18

Section 5:2 Substation Location--- County---Daviess Road---Settles Rd Town---Owensboro

Section 5:3Circuit Name and Number---Lake Forest Feeder 1Section 5:4Circuit Location---Lake Forest, Woodlands

Section 5:5Total Circuit Length----27.72Section 5:6Member count for this circuit---878Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	5.3%	57.9%	5.3%	5.3%	10.5%	10.5%	5.3%

 Section 5:9
 Circuit 5 year average (SAIDI)
 1.186390

 Section 5:10
 Reporting year (SAIDI)
 5.382643

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.009762

 Section 5:12
 Reporting year (SAIFI)
 0.042745

Section 5:1 Substation name and Number--- South Dermont 18

Section 5:2 Substation Location--- County---Daviess Road---Settles Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Old Mill Feeder 2

Section 5:4 Circuit Location--- Country Heights School

Section 5:5Total Circuit Length----17.99Section 5:6Member count for this circuit---423Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPP	Y PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
(	% 0.0%	37.5%	12.5%	0.0%	12.5%	0.0%	37.5%

Circuit 5 year average (SAIDI)	0.069823
Reporting year (SAIDI)	0.275843
Circuit 5 year average (SAIFI)	0.000922
Reporting year (SAIFI)	0.003695
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- South Dermont 18

Section 5:2 Substation Location--- County---Daviess Road---Settles Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Windridge Country Club Feeder 3

Section 5:4 Circuit Location--- Millers Mill Road

Section 5:5Total Circuit Length----25.35Section 5:6Member count for this circuit---295Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPL	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
09	6 10.0%	30.0%	10.0%	10.0%	20.0%	0.0%	20.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.207210
Section 5:10	Reporting year (SAIDI)	0.023122
Section 5:11	Circuit 5 year average (SAIFI)	0.003145
Section 5:12	Reporting year (SAIFI)	0.001202

Section 5:1 Substation name and Number--- South Dermont 18

Section 5:2 Substation Location--- County---Daviess Road---Settles Rd Town---Owensboro

Section 5:3Circuit Name and Number---Scotty Lane Feeder 4Section 5:4Circuit Location---Brookhill, Hunters Ridge

Section 5:5Total Circuit Length----35.04Section 5:6Member count for this circuit---627Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	14.3%	28.6%	0.0%	0.0%	14.3%	42.9%

Circuit 5 year average (SAIDI)	0.290468
Reporting year (SAIDI)	0.237253
Circuit 5 year average (SAIFI)	0.005667
Reporting year (SAIFI)	0.005462
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- South Dermont 18

Section 5:2 Substation Location--- County---Daviess Road---Settles Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Southeastern Parkway Feeder 5

Section 5:4 Circuit Location--- Hillcrest, Daviess Co. High

Section 5:5Total Circuit Length----29.95Section 5:6Member count for this circuit---620Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	16.7%	0.0%	16.7%	33.3%	16.7%	16.7%

Section 5:9	Circuit 5 year average (SAIDI)	0.440771
Section 5:10	Reporting year (SAIDI)	0.072143
Section 5:11	Circuit 5 year average (SAIFI)	0.005547
Section 5:12	Reporting year (SAIFI)	0.001184

Section 5:1 Substation name and Number--- South Dermont 18

Section 5:2 Substation Location--- County---Daviess Road---Settles Rd Town---Owensboro

Section 5:3 Circuit Name and Number--- Kenergy Feeder 6
Section 5:4 Circuit Location--- Alvey Park Drive

Section 5:5Total Circuit Length----10.75Section 5:6Member count for this circuit---176Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	12.5%	12.5%	37.5%	0.0%	0.0%	37.5%

Section 5:9	Circuit 5 year average (SAIDI)	0.102297
Section 5:10	Reporting year (SAIDI)	0.055596
Section 5:11	Circuit 5 year average (SAIFI)	0.001760
Section 5:12	Reporting year (SAIFI)	0.000354

Section 5:13 List of corrective action, if any, taken or to be taken--- Resolved at time of outage, System Improvement work order scheduled

Section 5:1 Substation name and Number--- South Hanson 53

Section 5:2 Substation Location--- County---Hopkins Road---Brown Badgett Loop Town---Madisonville

Section 5:3 Circuit Name and Number--- Otter Lake Feeder 1
Section 5:4 Circuit Location--- Hwy 1069, Channel 19

Section 5:5Total Circuit Length----24.49Section 5:6Member count for this circuit---235Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	11.1%	55.6%	0.0%	11.1%	11.1%	11.1%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.255520
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.003399
Section 5:12	Reporting year (SAIFI)	0.000000

Section 5:1 Substation name and Number--- South Hanson 53

Section 5:2 Substation Location--- County---Hopkins Road---Brown Badgett Loop Town---Madisonville

Section 5:3 Circuit Name and Number--- Veterans Hospital Feeder 2

Section 5:4 Circuit Location--- Hwy 281, Hwy 260

Section 5:5Total Circuit Length----26.1Section 5:6Member count for this circuit---205Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	12.5%	18.8%	0.0%	25.0%	31.3%	6.3%	6.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.437983
Section 5:10	Reporting year (SAIDI)	0.189718
Section 5:11	Circuit 5 year average (SAIFI)	0.006662
Section 5:12	Reporting year (SAIFI)	0.001927

Section 5:1 Substation name and Number--- South Hanson 53

Section 5:2 Substation Location--- County---Hopkins Road---Brown Badgett Loop Town---Madisonville

Section 5:3 Circuit Name and Number--- Gus Fowler Feeder 3
Section 5:4 Circuit Location--- Hwy 85, Brown Road

Section 5:5Total Circuit Length----35.65Section 5:6Member count for this circuit---407Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	7.1%	42.9%	0.0%	7.1%	14.3%	14.3%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	1.171093
Section 5:10	Reporting year (SAIDI)	3.311960
Section 5:11	Circuit 5 year average (SAIFI)	0.009778
Section 5:12	Reporting year (SAIFI)	0.011473

Section 5:1 Substation name and Number--- South Hanson 53

Section 5:2 Substation Location--- County---Hopkins Road---Brown Badgett Loop Town---Madisonville

Section 5:3 Circuit Name and Number--- Tucker Schoolhouse Road Feeder 4

Section 5:4 Circuit Location--- Hwy 41, Rainwater Road

Section 5:5Total Circuit Length----19.57Section 5:6Member count for this circuit---177Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	12.5%	50.0%	0.0%	12.5%	18.8%	6.3%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.319772
Section 5:10	Reporting year (SAIDI)	0.028779
Section 5:11	Circuit 5 year average (SAIFI)	0.002632
Section 5:12	Reporting year (SAIFI)	0.000442

Section 5:1 Substation name and Number--- South Hanson 53

Section 5:2 Substation Location--- County---Hopkins Road---Brown Badgett Loop Town---Madisonville

Section 5:3 Circuit Name and Number--- Wolf Hollow Road Feeder 5
Section 5:4 Circuit Location--- Rose Creek, Hwy 630 North

Section 5:5Total Circuit Length----59.48Section 5:6Member count for this circuit---461Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	14.8%	29.6%	0.0%	18.5%	11.1%	11.1%	14.8%

Section 5:9	Circuit 5 year average (SAIDI)	0.688302
Section 5:10	Reporting year (SAIDI)	0.115188
Section 5:11	Circuit 5 year average (SAIFI)	0.007269
Section 5:12	Reporting year (SAIFI)	0.001821

Section 5:1 Substation name and Number--- South Hanson 53

Section 5:2 Substation Location--- County---Hopkins Road---Brown Badgett Loop Town---Madisonville

Section 5:3 Circuit Name and Number--- Stagecoach Rd. Feeder 6
Section 5:4 Circuit Location--- Olive Rd., Jones Rd.

Section 5:5Total Circuit Length----72.16Section 5:6Member count for this circuit---555Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	4.2%	37.5%	8.3%	12.5%	20.8%	4.2%	12.5%

Section 5:9	Circuit 5 year average (SAIDI)	1.291003
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.012096
Section 5:12	Reporting year (SAIFI)	0.000000

Section 5:1 Substation name and Number--- South Owensboro 58

Section 5:2 Substation Location--- County---Daviess Road---Back Sq Drive Town---Owensboro

Section 5:3 Circuit Name and Number--- Town quare North Feeder 1

Section 5:4 Circuit Location--- Ponderosa

Section 5:5 Total Circuit Length---- 4.96
Section 5:6 Member count for this circuit--- 312

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	100.0%	0.0%	0.0%	0.0%	0.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.180979
Section 5:10	Reporting year (SAIDI)	0.001114
Section 5:11	Circuit 5 year average (SAIFI)	0.002658
Section 5:12	Reporting year (SAIFI)	0.000778

Section 5:1 Substation name and Number--- South Owensboro 58

Section 5:2 Substation Location--- County---Daviess Road---Back Sq Drive Town---Owensboro

Section 5:3 Circuit Name and Number--- Penny's/Town Square Ct. Feeder 2

Section 5:4 Circuit Location--- Famous Barr

Section 5:5Total Circuit Length----1.23Section 5:6Member count for this circuit---31Section 5:7Date of last circuit trim (VM)2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0%	0%	0%	0%	0%	0%	0%

Section 5:9	Circuit 5 year average (SAIDI)	0.007574		
Section 5:10	Reporting year (SAIDI)	0.000000		
Section 5:11	Circuit 5 year average (SAIFI)	0.000114		
Section 5:12	Reporting year (SAIFI)	0.000000		
Section 5:13	List of corrective action, if any, taken or to be taken			

Section 5:1 Substation name and Number--- South Owensboro 58

Section 5:2 Substation Location--- County---Daviess Road---Back Sq Drive Town---Owensboro

Section 5:3 Circuit Name and Number--- Sear's/Town Square Ct. Feeder 3

Section 5:4 Circuit Location--- Sears, Ruby Tuesday's

Section 5:5Total Circuit Length----1.22Section 5:6Member count for this circuit---27

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0%	0%	0%	0%	0%	0%	0%

Section 5:9	Circuit 5 year average (SAIDI)	0.003547			
Section 5:10	Reporting year (SAIDI)	0.000000			
Section 5:11	Circuit 5 year average (SAIFI)	0.000096			
Section 5:12	Reporting year (SAIFI)	0.000000			
Section 5:13	List of corrective action, if any, taken or to be taken				

Section 5:1 Substation name and Number--- South Owensboro 58

Section 5:2 Substation Location--- County---Daviess Road---Back Sq Drive Town---Owensboro

Section 5:3 Circuit Name and Number--- Hollywood Video Feeder 4

Section 5:4 Circuit Location--- Strictland Drive, Southtown Blvd.

Section 5:5 Total Circuit Length---- 1.69
Section 5:6 Member count for this circuit--- 17

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	33.3%	33.3%	0.0%	33.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.008802
Section 5:10	Reporting year (SAIDI)	0.011809
Section 5:11	Circuit 5 year average (SAIFI)	0.000175
Section 5:12	Reporting year (SAIFI)	0.000194

Section 5:1 Substation name and Number--- South Owensboro 58

Section 5:2 Substation Location--- County---Daviess Road---Back Sq Drive Town---Owensboro

Section 5:3 Circuit Name and Number--- Twin Lakes Feeder 5

Section 5:4 Circuit Location--- South Town

Section 5:5Total Circuit Length----24.49Section 5:6Member count for this circuit---601

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	18.2%	27.3%	0.0%	18.2%	27.3%	9.1%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	1.257299
Section 5:10	Reporting year (SAIDI)	2.711925
Section 5:11	Circuit 5 year average (SAIFI)	0.014385
Section 5:12	Reporting year (SAIFI)	0.017501

Section 5:1 Substation name and Number--- South Owensboro 58

Section 5:2 Substation Location--- County---Daviess Road---Back Sq Drive Town---Owensboro

Section 5:3 Circuit Name and Number--- Cracker Barrel Feeder 6

Section 5:4 Circuit Location--- Wal-Mart

Section 5:5Total Circuit Length----3.24Section 5:6Member count for this circuit---34

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	0.0%	100.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.007351
Section 5:10	Reporting year (SAIDI)	0.002404
Section 5:11	Circuit 5 year average (SAIFI)	0.000142
Section 5:12	Reporting year (SAIFI)	0.000071

Section 5:1 Substation name and Number--- South Owensboro 58

Section 5:2 Substation Location--- County---Daviess Road---Back Sq Drive Town---Owensboro

Section 5:3 Circuit Name and Number--- Todd Bridge Rd. Feeder 7

Section 5:4 Circuit Location--- Todd Bridge Rd.

Section 5:5Total Circuit Length----10.41Section 5:6Member count for this circuit---45

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0%	0%	0%	0%	0%	0%	0%

Section 5:9	Circuit 5 year average (SAIDI)	0.023461
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.000368
Section 5:12	Reporting year (SAIFI)	0.000000
Section 5:13	List of corrective action, if any, taken or to be take	n

Section 5:1 Substation name and Number--- St Joe 32

Section 5:2 Substation Location--- County---Daviess Road---Hwy 500 Town---St. Joe

Section 5:3Circuit Name and Number---Curdsville Feeder1Section 5:4Circuit Location---Hwy 500, Hwy 456

Section 5:5Total Circuit Length----54.28Section 5:6Member count for this circuit---361Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	16.0%	0.0%	48.0%	20.0%	12.0%	4.0%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.933881

 Section 5:10
 Reporting year (SAIDI)
 2.665627

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.009501

 Section 5:12
 Reporting year (SAIFI)
 0.013824

Section 5:13 List of corrective action, if any, taken or to be taken--- Look at adding additional lightning protection.

Section 5:1 Substation name and Number--- St Joe 32

Section 5:2 Substation Location--- County---Daviess Road---Hwy 500 Town---St. Joe

Section 5:3Circuit Name and Number---West Louisville Feeder 2Section 5:4Circuit Location---Hwy 56, Mulligan Rd.

Section 5:5Total Circuit Length----52.26Section 5:6Member count for this circuit---286Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	12.0%	4.0%	4.0%	32.0%	20.0%	16.0%	12.0%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.619390

 Section 5:10
 Reporting year (SAIDI)
 0.371462

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.006488

 Section 5:12
 Reporting year (SAIFI)
 0.004084

Section 5:1 Substation name and Number--- St Joe 32

Section 5:2 Substation Location--- County---Daviess Road---Hwy 500 Town---St. Joe

Section 5:3Circuit Name and Number---Possum Trot Feeder 3Section 5:4Circuit Location---Hwy 56, Mulligan Rd.

Section 5:5Total Circuit Length----27.41Section 5:6Member count for this circuit---162Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	7.1%	7.1%	7.1%	50.0%	14.3%	0.0%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.115596
Section 5:10	Reporting year (SAIDI)	0.273439
Section 5:11	Circuit 5 year average (SAIFI)	0.002117
Section 5:12	Reporting year (SAIFI)	0.002899

Section 5:1 Substation name and Number--- Stanley 21

Section 5:2 Substation Location--- County---Daviess Road---Hwy 1551 Town---Stanley

Section 5:3 Circuit Name and Number--- Newman Feeder 1

Section 5:4 Circuit Location--- Hwy 60 West, Steamboat Road

Section 5:5Total Circuit Length----62.83Section 5:6Member count for this circuit---446Section 5:7Date of last circuit trim (VM)2013/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	9.7%	12.9%	19.4%	35.5%	12.9%	0.0%	9.7%

Section 5:9	Circuit 5 year average (SAIDI)	0.925942
Section 5:10	Reporting year (SAIDI)	0.186253
Section 5:11	Circuit 5 year average (SAIFI)	0.012836
Section 5:12	Reporting year (SAIFI)	0.002422
		-

Section 5:1 Substation name and Number---Stanley 21

Section 5:2 County----Daviess Road---Hwy 1551 Town---Stanley Substation Location---

Section 5:3 Circuit Name and Number---Hwy 60 East Feeder 2

Section 5:4 Circuit Location---Hwy 60 East Section 5:5 9.12 Total Circuit Length----Section 5:6 Member count for this circuit---75 Section 5:7 Date of last circuit trim (VM) 2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	20.0%	20.0%	60.0%	0.0%	0.0%	0.0%

Section 5:9 Circuit 5 year average (SAIDI) 0.013062 Section 5:10 Reporting year (SAIDI) 0.036292 Section 5:11 Circuit 5 year average (SAIFI) 0.000199 Section 5:12 Reporting year (SAIFI) 0.002422 Section 5:13

VM to trim circuit. List of corrective action, if any, taken or to be taken---

Section 5:1 Substation name and Number--- Stanley 21

Section 5:2 Substation Location--- County---Daviess Road---Hwy 1551 Town---Stanley

Section 5:3Circuit Name and Number---Birk City Feeder 3Section 5:4Circuit Location---5th Street, Birk City

Section 5:5Total Circuit Length----26.72Section 5:6Member count for this circuit---162Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	33.3%	33.3%	16.7%	16.7%	0.0%	0.0%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.139737

 Section 5:10
 Reporting year (SAIDI)
 0.185581

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.002399

 Section 5:12
 Reporting year (SAIFI)
 0.003164

**Section 5:13** List of corrective action, if any, taken or to be taken--- VM to trim circuit.

Section 5:1 Substation name and Number--- Sullivan 85

Section 5:2 Substation Location--- County---Crittended Road---Blackford Ch Rd Town---Sturgis

Section 5:3Circuit Name and Number---Sullivan Feeder 1Section 5:4Circuit Location---Hwy 141, Hwy 60 East

Section 5:5Total Circuit Length----44.14Section 5:6Member count for this circuit---170Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	12.5%	37.5%	0.0%	12.5%	12.5%	0.0%	25.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.626427
Section 5:10	Reporting year (SAIDI)	0.171810
Section 5:11	Circuit 5 year average (SAIFI)	0.006310
Section 5:12	Reporting year (SAIFI)	0.003765
Castian F.13	The of compating patient if any selection is a least the	Franks

Section 5:1 Substation name and Number--- Sullivan 85

Section 5:2 Substation Location--- County---Crittended Road---Blackford Ch Rd Town---Sturgis

Section 5:3Circuit Name and Number---Blackford Feeder 2Section 5:4Circuit Location---Blackford, Hwy 143

Section 5:5Total Circuit Length----83.3Section 5:6Member count for this circuit---274Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	0.0%	100.0%	0.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.632002
Section 5:10	Reporting year (SAIDI)	0.004455
Section 5:11	Circuit 5 year average (SAIFI)	0.007263
Section 5:12	Reporting year (SAIFI)	0.000035
Coation F.12	The of compating patient if any selection is a least the selection	Franks 0

Section 5:1 Substation name and Number--- Sullivan 85

Section 5:2 Substation Location--- County---Crittenden Road---Blackford Ch Rd Town---Sturgis

Section 5:3Circuit Name and Number---Ky Stone Feeder 3Section 5:4Circuit Location---Hwy 60 West

Section 5:5Total Circuit Length----59.75Section 5:6Member count for this circuit---234Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	3.8%	15.4%	11.5%	30.8%	11.5%	3.8%	23.1%

Section 5:9	Circuit 5 year average (SAIDI)	0.440363
Section 5:10	Reporting year (SAIDI)	0.921965
Section 5:11	Circuit 5 year average (SAIFI)	0.006317
Section 5:12	Reporting year (SAIFI)	0.008256

Section 5:1 Substation name and Number--- Thruston 11

Section 5:2 Substation Location--- County---Daviess Road---Highway 405 Town---Owensboro

Section 5:3Circuit Name and Number---Hwy 405 North Feeder 1Section 5:4Circuit Location---Hwy 405 North, Saur Lane

Section 5:5Total Circuit Length----19.06Section 5:6Member count for this circuit---156Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	12.5%	25.0%	12.5%	37.5%	0.0%	0.0%	12.5%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.198047

 Section 5:10
 Reporting year (SAIDI)
 0.013753

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.002708

 Section 5:12
 Reporting year (SAIFI)
 0.000230

Section 5:1 Substation name and Number--- Thruston 11

Section 5:2 Substation Location--- County---Daviess Road---Highway 405 Town---Owensboro

Section 5:3Circuit Name and Number---Wrights Acres Feeder 2Section 5:4Circuit Location---Hwy 1389, Summit

Section 5:5Total Circuit Length----67.33Section 5:6Member count for this circuit----585Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	22.7%	9.1%	13.6%	22.7%	18.2%	4.5%	9.1%

Section 5:9	Circuit 5 year average (SAIDI)	1.173516
Section 5:10	Reporting year (SAIDI)	0.975104
Section 5:11	Circuit 5 year average (SAIFI)	0.012897
Section 5:12	Reporting year (SAIFI)	0.008609

Section 5:1 Substation name and Number--- Thruston 11

Section 5:2 Substation Location--- County---Daviess Road---Highway 405 Town---Owensboro

Section 5:3 Circuit Name and Number--- Graham Lane Feeder 3

Section 5:4 Circuit Location--- Graham Lane, Yellow Creek Park

Section 5:5Total Circuit Length----19.21Section 5:6Member count for this circuit----408Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	37.5%	12.5%	0.0%	25.0%	12.5%	0.0%	12.5%

Section 5:9	Circuit 5 year average (SAIDI)	0.601114
Section 5:10	Reporting year (SAIDI)	0.059450
Section 5:11	Circuit 5 year average (SAIFI)	0.005175
Section 5:12	Reporting year (SAIFI)	0.001308

Section 5:1 Substation name and Number--- Thruston 11

Section 5:2 Substation Location--- County---Daviess Road---Highway 405 Town---Owensboro

Section 5:3 Circuit Name and Number--- Thruston Feeder 4
Section 5:4 Circuit Location--- Thruston Playground

Section 5:5Total Circuit Length----7.87Section 5:6Member count for this circuit---78Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	66.7%	33.3%	0.0%	0.0%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.023121

 Section 5:10
 Reporting year (SAIDI)
 0.008468

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.000437

 Section 5:12
 Reporting year (SAIFI)
 0.000177

Section 5:1 Substation name and Number--- Thruston 11

Section 5:2 Substation Location--- County---Daviess Road---Highway 405 Town---Owensboro

Section 5:3 Circuit Name and Number--- Lamplite Estate Feeder 5
Section 5:4 Circuit Location--- Irene Ave., Iceland Road

Section 5:5Total Circuit Length----37.51Section 5:6Member count for this circuit----479Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	5.6%	22.2%	5.6%	11.1%	33.3%	0.0%	22.2%

Castian 5:12	List of accounting and the state of the stat	
Section 5:12	Reporting year (SAIFI)	0.003182
Section 5:11	Circuit 5 year average (SAIFI)	0.014869
Section 5:10	Reporting year (SAIDI)	0.171315
Section 5:9	Circuit 5 year average (SAIDI)	0.988990

Section 5:1 Substation name and Number--- Utica 24

Section 5:2 Substation Location--- County---Daviess Road---Hwy 140 Town---Utica

Section 5:3 Circuit Name and Number--- BrownsValley Feeder 1

Section 5:4 Circuit Location--- Hwy 431,Hwy 554

Section 5:5Total Circuit Length----61.96Section 5:6Member count for this circuit---408Section 5:7Date of last circuit trim (VM)2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	4.0%	24.0%	12.0%	40.0%	12.0%	4.0%	4.0%

Circuit 5 year average (SAIDI)	0.536020
Reporting year (SAIDI)	0.231472
Circuit 5 year average (SAIFI)	0.007833
Reporting year (SAIFI)	0.002157
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- Utica 24

Section 5:2 Substation Location--- County---Daviess Road---Hwy 140 Town---Utica

Section 5:3 Circuit Name and Number--- Red Hill Feeder 2

Section 5:4 Circuit Location--- Hwy 140 E

Section 5:5 Total Circuit Length---- 67.33

Section 5:6 Member count for this circuit--- 430

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	11.4%	14.3%	17.1%	28.6%	17.1%	8.6%	2.9%

Section 5:9	Circuit 5 year average (SAIDI)	0.584211
Section 5:10	Reporting year (SAIDI)	1.269757
Section 5:11	Circuit 5 year average (SAIFI)	0.011099
Section 5:12	Reporting year (SAIFI)	0.025880

Section 5:1 Substation name and Number--- Utica 24

Section 5:2 Substation Location--- County---Daviess Road---Hwy 140 Town---Utica

Section 5:3 Circuit Name and Number--- Locust Grove Road Feeder 3
Section 5:4 Circuit Location--- Hwy 431 South, Mill Street

Section 5:5Total Circuit Length----41.36Section 5:6Member count for this circuit---328Section 5:7Date of last circuit trim (VM)2013/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	5.6%	0.0%	5.6%	50.0%	5.6%	11.1%	22.2%

Section 5:9	Circuit 5 year average (SAIDI)	0.352361
Section 5:10	Reporting year (SAIDI)	0.335152
Section 5:11	Circuit 5 year average (SAIFI)	0.006646
Section 5:12	Reporting year (SAIFI)	0.007354

Section 5:1 Substation name and Number--- Utica 24

Section 5:2 Substation Location--- County---Daviess Road---Hwy 140 Town---Utica

Section 5:3 Circuit Name and Number--- Utica Feeder 4

Section 5:4 Circuit Location--- Hwy 140 West, Hwy 1207

Section 5:5Total Circuit Length----33.12Section 5:6Member count for this circuit---240Section 5:7Date of last circuit trim (VM)2013/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	6.7%	20.0%	26.7%	33.3%	0.0%	13.3%

Section E-12	List of corrective action if any taken or to be taken	n	VM to trim circ
Section 5:12	Reporting year (SAIFI)	0.005339	)
Section 5:11	Circuit 5 year average (SAIFI)	0.005405	;
Section 5:10	Reporting year (SAIDI)	0.271848	3
Section 5:9	Circuit 5 year average (SAIDI)	0.413242	<u>.</u>

Section 5:13 List of corrective action, if any, taken or to be taken--- VM to trim circuit

Section 5:1 Substation name and Number--- Utica 24

Section 5:2 Substation Location--- County---Daviess Road---Hwy 140 Town---Utica

Section 5:3 Circuit Name and Number--- Old Barmet Feeder 5

Section 5:4Circuit Location---Hwy 431Section 5:5Total Circuit Length----3.66Section 5:6Member count for this circuit---12Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	50.0%	0.0%	0.0%	0.0%	0.0%	50.0%	0.0%

Circuit 5 year average (SAIDI)	0.026873
Reporting year (SAIDI)	0.008114
Circuit 5 year average (SAIFI)	0.000165
Reporting year (SAIFI)	0.000265
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number---Weaverton 64

County---Henderson Road---Madisonville Rd Town---Henderson

WEATHER

0.0%

ANIMAL

0.0%

PUBLIC

100.0%

UNKNOWN

0.0%

Section 5:3 Circuit Name and Number---

Substation Location---

Crestline Plastics Feeder 1

Section 5:4 Circuit Location--- Hwy 136,

Section 5:5 Total Circuit Length----

Section 5:2

Section 5:8

2.21

Section 5:6 Member count for this circuit--- 35

Section 5:7 Date of last circuit trim (VM)

2015 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED		EQUIPMENT FAILURE	ROW		
0%	0.	.0%	0.0%		0.0%	
•						

Section 5:9	Circuit 5 year average (SAIDI)	0.013334
Section 5:10	Reporting year (SAIDI)	0.000902
Section 5:11	Circuit 5 year average (SAIFI)	0.000140
Section 5:12	Reporting year (SAIFI)	0.000053
C4: F.13	The of compating patential action action on a first action	

Section 5:1 Substation name and Number--- Weaverton 64

Section 5:2 Substation Location--- County---Henderson Road---Madisonville Rc Town---Henderson

Section 5:3 Circuit Name and Number--- Hwy 41A South Feeder 2

Section 5:4 Circuit Location--- Hwy 1299, Cario

Section 5:5Total Circuit Length----77.74Section 5:6Member count for this circuit---668Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	9.5%	33.3%	19.0%	4.8%	14.3%	4.8%	14.3%

Circuit 5 year average (SAIDI)	0.648844
Reporting year (SAIDI)	0.190319
Circuit 5 year average (SAIFI)	0.012429
Reporting year (SAIFI)	0.002705
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- Weaverton 64

Section 5:2 Substation Location--- County---Henderson Road---Madisonville Rc Town---Henderson

Section 5:3 Circuit Name and Number--- Country View Feeder 3

Section 5:4 Circuit Location--- Country View

Section 5:5Total Circuit Length----8.92Section 5:6Member count for this circuit---268Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	25.0%	0.0%	75.0%	0.0%	0.0%

Circuit 5 year average (SAIDI)	0.184145
Reporting year (SAIDI)	0.047217
Circuit 5 year average (SAIFI)	0.002674
Reporting year (SAIFI)	0.000795
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- Weberstown 14

Section 5:2 Substation Location--- County---Hancock Road---SR 69 Town---Hawesville

Section 5:3 Circuit Name and Number--- South Hancock Elementry Feeder 1

Section 5:4 Circuit Location--- Hwy 144, Hwy 69

Section 5:5Total Circuit Length----109.04Section 5:6Member count for this circuit---639Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	3.6%	21.4%	7.1%	39.3%	7.1%	7.1%	14.3%

Section 5:9	Circuit 5 year average (SAIDI)	2.483662
Section 5:10	Reporting year (SAIDI)	0.238862
Section 5:11	Circuit 5 year average (SAIFI)	0.022193
Section 5:12	Reporting year (SAIFI)	0.003730

Section 5:1 Substation name and Number--- Weberstown 14

Section 5:2 Substation Location--- County---Hancock Road---SR 69 Town---Hawesville

Section 5:3 Circuit Name and Number--- Roseville Feeder 2

Section 5:4 Circuit Location--- Easton Road, Bates Hollow Road

Section 5:5Total Circuit Length----94.96Section 5:6Member count for this circuit---475Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	8.6%	14.3%	28.6%	25.7%	11.4%	5.7%	5.7%

Section 5:9	Circuit 5 year average (SAIDI)	1.354520
Section 5:10	Reporting year (SAIDI)	1.578251
Section 5:11	Circuit 5 year average (SAIFI)	0.010685
Section 5:12	Reporting year (SAIFI)	0.018650

Section 5:1 Substation name and Number--- Weberstown 14

Section 5:2 Substation Location--- County---Hancock Road---SR 69 Town---Hawesville

Section 5:3 Circuit Name and Number--- Pellville Feeder 3

Section 5:4 Circuit Location--- Hwy 144 West, Hwy 764

Section 5:5Total Circuit Length----85.39Section 5:6Member count for this circuit---534Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	10.5%	15.8%	15.8%	31.6%	10.5%	5.3%	10.5%

Section 5:9	Circuit 5 year average (SAIDI)	1.762703	
Section 5:10	Reporting year (SAIDI)	5.043371	
Section 5:11	Circuit 5 year average (SAIFI)	0.011502	
Section 5:12	Reporting year (SAIFI)	0.018385	
Section 5:13	List of corrective action if any taken or to be taken	′on	Evaluato & i

Section 5:13 List of corrective action, if any, taken or to be taken--- Evaluate & inspection circuit.

System improvement work order scheduled.

Section 5:1 Substation name and Number--- West Owensboro 22

Section 5:2 Substation Location--- County---Daviess Road---Old Lyddane Br Town---Owensboro

Section 5:3 Circuit Name and Number--- Meadowlark Drive Feeder 1

Section 5:4 Circuit Location--- Medowlark Drive

Section 5:5Total Circuit Length----3.34Section 5:6Member count for this circuit----6Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	20.0%	20.0%	0.0%	20.0%	20.0%	0.0%	20.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.002619
Section 5:10	Reporting year (SAIDI)	0.001927
Section 5:11	Circuit 5 year average (SAIFI)	0.000046
Section 5:12	Reporting year (SAIFI)	0.000053

Section 5:1 Substation name and Number--- West Owensboro 22

Section 5:2 Substation Location--- County---Daviess Road---Old Lyddane Br Town---Owensboro

Section 5:3Circuit Name and Number---Airport Feeder 2Section 5:4Circuit Location---Bittle Rd., Boatman

Section 5:5Total Circuit Length----10.94Section 5:6Member count for this circuit---116Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	16.7%	50.0%	0.0%	16.7%	0.0%	0.0%	16.7%

Circuit 5 year average (SAIDI)	0.063371
Reporting year (SAIDI)	0.025085
Circuit 5 year average (SAIFI)	0.001132
Reporting year (SAIFI)	0.002086
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- West Owensboro 22

Section 5:2 Substation Location--- County---Daviess Road---Old Lyddane Br Town---Owensboro

Section 5:3 Circuit Name and Number--- Hwy 81 South Feeder 3
Section 5:4 Circuit Location--- Wayne Bridge Road

Section 5:5Total Circuit Length----66.38Section 5:6Member count for this circuit---658Section 5:7Date of last circuit trim (VM)2015

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	10.0%	30.0%	0.0%	50.0%	5.0%	0.0%	5.0%

Circuit 5 year average (SAIDI)	0.803748
Reporting year (SAIDI)	0.158516
Circuit 5 year average (SAIFI)	0.022224
Reporting year (SAIFI)	0.003182
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:13 List of corrective action, if any, taken or to be taken--- Look at adding additional lightning protection.

Section 5:1 Substation name and Number--- West Owensboro 22

Section 5:2 Substation Location--- County---Daviess Road---Old Lyddane Br Town---Owensboro

Section 5:3 Circuit Name and Number--- Lyddane Br Rd Feeder 4
Section 5:4 Circuit Location--- Hwy 279, Pruden Lane

Section 5:5Total Circuit Length----24.76Section 5:6Member count for this circuit---148Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	8.3%	16.7%	8.3%	41.7%	25.0%	0.0%	0.0%

Circuit 5 year average (SAIDI)	0.265795
Reporting year (SAIDI)	0.064506
Circuit 5 year average (SAIFI)	0.003294
Reporting year (SAIFI)	0.000902
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- West Owensboro 22

Section 5:2 Substation Location--- County---Daviess Road---Old Lyddane Br Town---Owensboro

Section 5:3 Circuit Name and Number--- Hwy 56/Sorgho

Section 5:4 Circuit Location--- Woodlawn Subdivision

Section 5:5Total Circuit Length----49.54Section 5:6Member count for this circuit---756Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	8.3%	29.2%	0.0%	12.5%	29.2%	4.2%	16.7%

Section 5:9	Circuit 5 year average (SAIDI)	0.944332
Section 5:10	Reporting year (SAIDI)	2.419977
Section 5:11	Circuit 5 year average (SAIFI)	0.012918
Section 5:12	Reporting year (SAIFI)	0.028178

Section 5:1 Substation name and Number--- Whitesville 15

Section 5:2 Substation Location--- County---Daviess Road---Hwy 764 Town----Whiteswville

Section 5:3 Circuit Name and Number--- Hwy 54 West Feeder 1
Section 5:4 Circuit Location--- Haynes Station Road

Section 5:5Total Circuit Length----28.25Section 5:6Member count for this circuit---242Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	6.7%	20.0%	6.7%	26.7%	13.3%	26.7%	0.0%

Circuit 5 year average (SAIDI)	0.404071
Reporting year (SAIDI)	0.276250
Circuit 5 year average (SAIFI)	0.002733
Reporting year (SAIFI)	0.005657
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- Whitesville 15

Section 5:2 Substation Location--- County---Daviess Road---Hwy 764 Town----Whiteswville

Section 5:3 Circuit Name and Number--- Whitesville Feeder 2

Section 5:4 Circuit Location--- Hwy 764 North, Old Leitchfield Road

Section 5:5Total Circuit Length----69.38Section 5:6Member count for this circuit---728Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	2.8%	30.6%	0.0%		27.8%	11.1%	8.3%

Section 5:9	Circuit 5 year average (SAIDI)	0.822810
Section 5:10	Reporting year (SAIDI)	0.991633
Section 5:11	Circuit 5 year average (SAIFI)	0.010434
Section 5:12	Reporting year (SAIFI)	0.019799

Section 5:1 Substation name and Number--- Whitesville 15

Section 5:2 Substation Location--- County---Daviess Road---Hwy 764 Town----Whiteswville

Section 5:3Circuit Name and Number---Ralph Feeder 3Section 5:4Circuit Location---Magan,Narrows

Section 5:5Total Circuit Length----111.53Section 5:6Member count for this circuit---576Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	4.2%	29.2%	8.3%	45.8%	0.0%	8.3%	4.2%

Section 5:9	Circuit 5 year average (SAIDI)	1.499512
Section 5:10	Reporting year (SAIDI)	1.563632
Section 5:11	Circuit 5 year average (SAIFI)	0.016442
Section 5:12	Reporting year (SAIFI)	0.024024

Section 5:1 Substation name and Number--- Whitesville 15

Section 5:2 Substation Location--- County---Daviess Road---Hwy 764 Town----Whiteswville

Section 5:3 Circuit Name and Number--- Stevens School Road Feeder 4

Section 5:4 Circuit Location--- Deserter Creek Road

Section 5:5Total Circuit Length----56.46Section 5:6Member count for this circuit---327Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	38.5%	7.7%	30.8%	7.7%	7.7%	7.7%

Circuit 5 year average (SAIDI)	0.283972
Reporting year (SAIDI)	0.971869
Circuit 5 year average (SAIFI)	0.003427
Reporting year (SAIFI)	0.012304
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- Wolf Hills 91

Section 5:2 Substation Location--- County---Henderson Road---Wathen Road Town---Henderson

Section 5:3 Circuit Name and Number--- WFIE Feeder 1

Section 5:4Circuit Location---WFIESection 5:5Total Circuit Length----1.38Section 5:6Member count for this circuit---5Section 5:7Date of last circuit trim (VM)2014

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	0.0%	0.0%	0.0%	100.0%	0.0%

Section 5:9	Circuit 5 year average (SAIDI)	0.000345
Section 5:10	Reporting year (SAIDI)	0.001732
Section 5:11	Circuit 5 year average (SAIFI)	0.000007
Section 5:12	Reporting year (SAIFI)	0.000035

Section 5:1 Substation name and Number--- Wolf Hills 91

Section 5:2 Substation Location--- County---Henderson Road---Wathen Road Town---Henderson

Section 5:3 Circuit Name and Number--- Wathem Lane Feeder 3

Section 5:4 Circuit Location--- Melody Lane

Section 5:5Total Circuit Length----21.39Section 5:6Member count for this circuit---286Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	0.0%	16.7%	50.0%	16.7%	0.0%	16.7%

Section 5:9	Circuit 5 year average (SAIDI)	0.072993
Section 5:10	Reporting year (SAIDI)	0.052238
Section 5:11	Circuit 5 year average (SAIFI)	0.001149
Section 5:12	Reporting year (SAIFI)	0.001114

Section 5:1 Substation name and Number--- Wolf Hills 91

Section 5:2 Substation Location--- County---Henderson Road---Wathen Road Town---Henderson

Section 5:3 Circuit Name and Number--- Ellis Park Feeder 4
Section 5:4 Circuit Location--- Rivber Camps, Ellis Park

Section 5:5Total Circuit Length----21.87Section 5:6Member count for this circuit---154Section 5:7Date of last circuit trim (VM)2013

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	16.7%	16.7%	0.00%	16.7%	50.0%	0.0%

Circuit 5 year average (SAIDI)	0.617312
Reporting year (SAIDI)	0.469326
Circuit 5 year average (SAIFI)	0.007956
Reporting year (SAIFI)	0.006063
	Reporting year (SAIDI) Circuit 5 year average (SAIFI)

Section 5:1 Substation name and Number--- Yager Material 10

Section 5:2 Substation Location--- County---Hancock Road---River Road Town--- Hawesville

Section 5:3 Circuit Name and Number--- Yager Feeder 1

Section 5:4 Circuit Location--- Yager Material, Western Ky Energy

Section 5:5 Total Circuit Length---- 1.46
Section 5:6 Member count for this circuit--- 3

Section 5:7 Date of last circuit trim (VM) 2012/2017

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0%	0%	0%	0%	0%	0%	0%

Section 5:9	Circuit 5 year average (SAIDI)	0.000748
Section 5:10	Reporting year (SAIDI)	0.000000
Section 5:11	Circuit 5 year average (SAIFI)	0.000011
Section 5:12	Reporting year (SAIFI)	0.000000
Section 5:13	List of corrective action, if any, taken or to be take	n

Section 5:1 Substation name and Number--- Zion 90

Section 5:2 Substation Location--- County---Henderson Road--- Hwy 1078 Town---Zion

Section 5:3 Circuit Name and Number--- Hwy 1078 N Feeder 1

Section 5:4Circuit Location---Hwy 1078Section 5:5Total Circuit Length----15.91Section 5:6Member count for this circuit----215Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	16.7%	8.3%	58.3%	8.3%	0.0%	8.3%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.155846

 Section 5:10
 Reporting year (SAIDI)
 0.018668

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.001764

 Section 5:12
 Reporting year (SAIFI)
 0.000301

Section 5:1 Substation name and Number--- Zion 90

Section 5:2 Substation Location--- County---Henderson Road--- Hwy 1078 Town---Zion

Section 5:3 Circuit Name and Number--- Beals/Reed Feeder 2
Section 5:4 Circuit Location--- Old Hwy 60, Reed

Section 5:5Total Circuit Length----76.55Section 5:6Member count for this circuit---547Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	46.7%	13.3%	6.7%	20.0%	0.0%	13.3%

 Section 5:9
 Circuit 5 year average (SAIDI)
 0.559511

 Section 5:10
 Reporting year (SAIDI)
 1.080464

 Section 5:11
 Circuit 5 year average (SAIFI)
 0.008779

 Section 5:12
 Reporting year (SAIFI)
 0.010660

Section 5:1 Substation name and Number--- Zion 90

Section 5:2 Substation Location--- County---Henderson Road--- Hwy 1078 Town---Zion

Section 5:3 Circuit Name and Number--- Hebbardsville Feeder 3

Section 5:4 Circuit Location--- Hwy 351, Hwy 416

Section 5:5Total Circuit Length----90.57Section 5:6Member count for this circuit---630Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0%	0.0%	13.6%	13.6%	40.9%	13.6%	13.6%	4.5%

Section 5:9Circuit 5 year average (SAIDI)1.354998Section 5:10Reporting year (SAIDI)0.621320Section 5:11Circuit 5 year average (SAIFI)0.011002Section 5:12Reporting year (SAIFI)0.013064

Section 5:1 Substation name and Number--- Zion 90

Section 5:2 Substation Location--- County---Henderson Road---Hwy 1078 N Town---Zion

Section 5:3 Circuit Name and Number--- Galloway Corner Feeder 4

Section 5:4Circuit Location---Airline Rd.Section 5:5Total Circuit Length----25.39Section 5:6Member count for this circuit---227Section 5:7Date of last circuit trim (VM)2016

Section 5:8 List outage causes for circuit along with % of total outage numbers represented by each cause---

POWER SUPPLY	PLANNED	EQUIPMENT FAILURE	ROW	WEATHER	ANIMAL	PUBLIC	UNKNOWN
0.00%	0.00%	28.57%	14.29%	42.86%	14.29%	0.00%	0.00%

Section 5:9	Circuit 5 year average (SAIDI)	0.213078
Section 5:10	Reporting year (SAIDI)	0.026835
Section 5:11	Circuit 5 year average (SAIFI)	0.002383
Section 5:12	Reporting year (SAIFI)	0.000442