




**LICKING VALLEY**  
RURAL ELECTRIC COOPERATIVE CORPORATION  
P. O. Box 605 • 271 Main Street  
West Liberty, KY 41472-0605  
(606) 743-3179



RECEIVED

MAR 13 2020

PUBLIC SERVICE  
COMMISSION

March 11, 2020

Director of Engineering  
Public Service Commission  
211 Sower Boulevard  
P.O. Box 615  
Frankfort, KY 40602

Dear Sir:

Enclosed you will find Licking Valley Electric Cooperative Corporation's Electric Distribution Utility Annual Reliability and Accountability Report for the year ending 2019.

If additional information is needed, please let us know.

Sincerely,

Chris Murphy  
Superintendent of Operations

CM:oh

**Report prepared for:**

**LICKING VALLEY RURAL ELECTRIC COOPERATIVE CORPORATION**

**Prepared by:**

**Oneida Haney**  
[ohaney@lvrecc.com](mailto:ohaney@lvrecc.com)  
**606-743-7500**

# **2019 Annual Reliability Report**

**Major Event Days**

**SAIDI Value      89.4754**

**First Date Used to Determine T'Med----- February 07, 2019**

**Last Date Used to Determine T'Med----- August 20, 2019**

**Number of MED in Report Year----28**

## System Reliability Information and Results

### System-Wide Information

Total consumers 17,188

Total Circuits 36

### System-Wide Results

#### Excluding MED

Reporting Year	5 Year Average
SAIDI 199.2011	166.0869
SAIFI 1.3666	1.3621

#### Including MED

Reporting Year	5 Year Average
SAIDI 288.6765	383.0357
SAIFI 1.8651	2.0233

**Ten Worst Performing Circuits and Major Outage Category Without T'Med for SAIFI Index:**

<b>Substation</b>	<b>Circuit</b>	<b>SAIFI Value</b>	<b>Major Cause</b>
Sublett	Carver	3.3363	Pre-Arranged
Campton	Vortex	2.9414	Equipment Failure
Sublett	Gunlock	2.9177	Right-of-Way Outside
Maggard	Flat Fork	2.2500	Pre-Arranged
Sublett	Gun Creek	2.0000	Pre-Arranged
Index	Liberty Road	1.9100	Pre-Arranged
Maggard	Lick Creek	1.9020	Right-of-Way Outside
Helechawa	Vancleve	1.8284	Pre-Arranged
Maggard	Rockhouse	1.7800	Pre-Arranged
Index	Mize	1.7000	Right-of-Way Inside

**Ten Worst Performing Circuits and Major Outage Category Without T'Med for SAIDI Index:**

<b>Substation</b>	<b>Circuit</b>	<b>SAIDI Value</b>	<b>Major Cause</b>
Sublett	Carver	1287.4192	Pre-Arranged
Maggard	Lick Creek	417.8670	Right-of-Way Outside
Sublett	Gun Lock	372.2949	Right-of-Way Outside
Sublett	Lakeville	357.5572	Right-of-Way Outside
Oakdale	Highland	346.7570	Unknown
Oakdale	Elkatawa	287.0601	Equipment Failure
Campton	Vortex	280.1667	Equipment Failure
Maggard	Flat Fork	259.2112	Pre-Arranged
Oakdale	War Creek	208.2741	Right-of-Way Outside
Sublett	Gun Creek	204.4740	Pre-Arranged

**Ten Worst Performing Circuits and Major Cause Category Without T'Med for CAIDI Value:**

<b>Substation</b>	<b>Circuit</b>	<b>CAIDI Value</b>	<b>Major Cause</b>
Sublett	Carver	385.8823	Pre-Arranged
Sublett	Lakeville	231.0697	Right-of-Way Out
Oakdale	Highland	221.1742	Unknown
Maggard	Lick Creek	219.6987	Equipment Failure
Campton	Stillwater	183.5202	Unknown
Oakdale	Elkatawa	181.5802	Right-of-Way Out
Zachariah	Leeco	167.5383	Right-of-Way Out
Oakdale	War Creek	145.5546	Line Down
Sublett	Gunlock	127.5988	Consumer Caused
Maytown	Ezel	123.4955	Animals



**System-Wide SAIFI, SAIDI, and CAIDI for the past 5 years, Includes T'Med**

	<b>2015</b>	<b>2016</b>	<b>2017</b>	<b>2018</b>	<b>2019</b>
<b>SAIFI</b>	<b>2.2879</b>	<b>1.6367</b>	<b>2.4136</b>	<b>1.9134</b>	<b>1.8651</b>
<b>SAIDI</b>	<b>434.8157</b>	<b>207.9844</b>	<b>344.1047</b>	<b>639.5972</b>	<b>288.6765</b>
<b>CAIDI</b>	<b>190.05</b>	<b>127.07</b>	<b>142.57</b>	<b>334.27</b>	<b>154.78</b>

**System-Wide SAIFI, SAIDI, and CAIDI for the past 5 years, Excludes T'Med**

	<b>2015</b>	<b>2016</b>	<b>2017</b>	<b>2018</b>	<b>2019</b>
<b>SAIFI</b>	<b>1.6890</b>	<b>1.1743</b>	<b>1.3105</b>	<b>1.2702</b>	<b>1.3666</b>
<b>SAIDI</b>	<b>203.4541</b>	<b>129.5736</b>	<b>137.2827</b>	<b>160.9228</b>	<b>199.2011</b>
<b>CAIDI</b>	<b>120.46</b>	<b>110.34</b>	<b>104.76</b>	<b>126.69</b>	<b>145.76</b>







		SAIDI Values for every circuit---excluding MED's						
		2015	2016	2017	2018	2019	5 Year Average	
<b>Campton Substation</b>								
	Pine Ridge Circuit	56.8558	101.1563	41.7274	33.5112	111.4313	68.9364	
	Stillwater Circuit	208.8360	44.5341	96.1985	52.5457	92.0354	98.8299	
	Vortex Circuit	293.2477	557.3380	90.2226	252.4380	280.1667	294.6826	
	Elkins Road Circuit	51.7021	220.0352	120.7291	21.1634	101.6542	103.0568	
<b>Index Substation</b>								
	Caney Circuit	70.4868	72.6010	66.3265	38.4080	86.6418	66.8928	
	Index Circuit	11.7956	68.9507	75.5798	44.1217	52.6201	50.6136	
	Mize Circuit	352.2212	159.5184	29.8132	338.1005	97.9194	195.5145	
	Prison Circuit				188.0000	27.7500		
	School Circuit	30.0000			2.2500		6.4500	
<b>Maytown Substation</b>								
	Ezel Circuit	117.097	54.1790	17.6252	100.6312	94.4000	55.7090	
	Hazel Green Circuit	76.3127	35.371	79.6557	144.5493	43.0548	69.4219	
	Pomeroyton Circuit	53.5035	58.8554	20.0938	93.3734	35.6158	52.2884	
<b>Crockett Substation</b>								
	Lenox Circuit	94.0735	40.7669	45.9177	167.8000	49.8800	79.6876	
	Williams Creek Circuit	52.6992	42.6087	178.2226	249.0188	146.0522	133.7203	
	Crockett Circuit	99.1437	47.5911	276.2323	160.9704	61.9824	129.1840	

## **Circuit Reporting**

**Circuits With SAIFI or SAIDI Value Higher Than 5 Year Average**

## Circuit Reporting

Substation # 2; Oakdale Substation, located on Rt. 52 at Oakdale in Breathitt County.

Circuit # 3, Elkatawa Circuit; this circuit serves the areas of Five-Mile, Wolverine, Elkatawa, Belcher Fork, and Cane Creek.

This circuit has approximately 57.3 miles of line and serves approximately 766 consumers.

This circuit was cut out in 2016.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Equipment Failure	65%	83%
Pre-Arranged Maintenance	12%	5%
Consumer Caused	10%	4%
Unknown	5%	3%
Right-of-Way Inside	5%	3%
Animals	2%	1%
Right-of-Way Outside	1%	1%
Line Down	>1%	>1%

Circuit 5 Year Average SAIFI----1.8364

Reporting Year 2019 SAIFI—1.5809

Circuit 5 Year Average SAIDI---162.7750

Reporting Year 2019 SAIDI—287.0601

Equipment failure is something that is beyond our control.

## Circuit Reporting

Substation # 4; Hot Mix Substation, located on Sugar Camp Road in Morgan County.

Circuit # 2, Liberty Road Circuit; this circuit serves areas of Rt 7 and Liberty Road.

This circuit has approximately 14 miles and serves approximately 100 consumers.

This circuit was cut out in 2019.

Causes and percentages for this circuit:

Cause	%SAIFI	%SAIDI
Pre-Arranged Maintenance	71%	53%
Animals	23%	16%
Right-of-Way Outside	5%	29%
Unknown	1%	2%

Circuit 5 Year Average SAIFI—.8225

Reporting Year, 2019 SAIFI—1.9100

Circuit 5 Year Average SAIDI—49.0721

Reporting Year, 2019 SAIDI—101.6900

In order to complete necessary repairs safely, serviceman had to turn power off until repairs were completed.



## Circuit Reporting

Substation # 4; Hot Mix Substation, located on Sugar Camp Road in Morgan County.

Circuit # 4, 519 Circuit; this circuit serves areas of Hwy 519, Yocum, Blaze, Zag and Dehart.

This Circuit has approximately 99 miles of line and serves approximately 800 consumers.

This circuit was cut out in 2019.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Pre-Arranged Maintenance	35%	36%
Right-of-Way Crew	20%	23%
Unknown	19%	12%
Equipment Failure	16%	19%
Consumer Caused	5%	1%
Animals	2%	3%
Right-of-Way Outside	2%	4%
Right-of-Way Inside	1%	2%
Line Down	>1%	>1%

Circuit 5 Year Average SAIFI—1.0428

Reporting Year, 2019 SAIFI—1.5832

Circuit 5 Year Average SAIDI—104.1848

Reporting Year, 2019 SAIDI—108.8872

In order for needed repairs to be completed safely, serviceman had to turn power off until repairs were completed.

## Circuit Reporting

Substation #4; Hot Mix Substation, located on Sugar Camp Road in Morgan County.

Circuit # 5, Wrigley Circuit; this circuit serves areas of Wrigley, Redwine and Blairs Mill.

This Circuit has approximately 57 miles of line and serves approximately 369 consumers.

This circuit was cut out in 2019.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Pre-Arranged Maintenance	48%	27%
Right-of-Way Crew	40%	13%
Consumer Caused	4%	52%
Animals	4%	3%
Equipment Failure	3%	3%
Right-of-Way Outside	1%	2%

Circuit 5 Year Average SAIFI—1.1141

Reporting Year, 2019 SAIFI—1.2819

Circuit 5 Year Average SAIDI—128.6956

Reporting Year, 2019 SAIDI—134.4418

In order for needed repairs to be completed safely, servicemen had to turn power off until repairs were completed.

## Circuit Reporting

Substation # 5, Maggard Substation, located on Rt 1081 at Coon Creek in Magoffin County.

Circuit # 1; Rockhouse Circuit; this circuit serves areas of Improvement Fork, Rockhouse and Logville.

This circuit has approximately 32.5 miles of line and serves approximately 274 consumers.

This circuit was cut out in 2013.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Pre-Arranged Maintenance	87%	84%
Right-of-Way Outside	9%	10%
Equipment Failure	2%	2%
Unknown	1%	2%
Right-of-Way Inside	1%	2%
Animals	>1%	>1%

Circuit 5 Year Average SAIFI--.9068

Reporting Year 2019 SAIFI—1.9780

Circuit 5 Year Average SAIDI—127.6613

Reporting Year 2019 SAIDI—127.0147

In order for needed repairs to completed safely, serviceman had to turn power off until repairs were completed.

## Circuit Reporting

Substation # 5, Maggard Substation, located on Rt. 1081 at Coon Creek in Magoffin County.

Circuit # 2; Flat Fork Circuit; this circuit serves areas of Coon Creek, Mud Lick, Flat Fork, Mine Fork, and Litteral.

This circuit has approximately 43 miles of line and serves approximately 516 consumers.

This circuit was cut out in 2013.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Pre-Arranged Maintenance	77%	53%
Unknown	14%	26%
Line Down	4%	11%
Right-of-Way Outside	2%	3%
Animals	2%	2%
Equipment Failure	1%	3%
Consumer Caused	>1%	2%

Circuit 5 Year Average SAIFI—1.0656

Reporting Year 2019 SAIFI—2.2500

Circuit 5 Year Average SAIDI—134.6791

Reporting Year 2019 SAIDI—259.2112

In order for needed repairs to be completed safely, servicemen had to turn power off until repairs were completed.

## Circuit Reporting

Substation #5, Maggard Substation, located on Rt. 1081 at Coon Creek Road in Magoffin County.

Circuit # 3; Lick Creek Circuit; this circuit serves areas of Lick Creek Road, Buffalo, Brushy Fork and Cripple Creek.

This circuit has approximately 48.5 miles of line and serves approximately 601 consumers.

This circuit was cut out in 2013.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Right-of-Way Outside	55%	54%
Pre-Arranged Maintenance	34%	36%
Unknown	5%	3%
Equipment Failure	3%	6%
Animals	1%	1%
Line Down	1%	>1%
Right-of-Way Crew	1%	>1%
Right-of-Way Inside	>1%	>1%
Consumer Caused	>1%	>1%

Circuit 5 Year Average SAIFI--.8756

Reporting Year 2019 SAIFI—1.9020

Circuit 5 Year Average SAIDI—145.7523

Reporting Year 2019 SAIDI—417.8670

We have no control over right-of-way outside of our cutting area, however, any danger trees that we see outside of our right-of-way we will cut.

## Circuit Reporting

Substation # 6, Sublett Substation, located on Rt 7 near Royalton in Magoffin County.

Circuit # 1, Carver Circuit; this circuit serves areas of Sublett, Stinson, Foraker and Hendricks.

This circuit has approximately 71.4 miles of line and serves approximately 675 consumers.

This circuit was cut out in 2012.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Pre-Arranged Maintenance	72%	90%
Right-of-Way Outside	7%	2%
Line Down	6%	2%
Right-of-Way Inside	5%	2%
Unknown	4%	2%
Consumer Caused	3%	2%
Right-of-Way Crew	2%	>1%
Equipment Fail	1%	>1%
Animals	>1%	>1%
Fire	>1%	>1%

Circuit 5 Year Average SAIFI—1.3902

Reporting Year 2019 SAIFI—3.3363

Circuit 5 Year Average SAIDI—339.2860

Reporting Year 2019 SAIDI—1287.4192

In order to do necessary repairs safely, serviceman had to turn power off until repairs were completed.

## Circuit Reporting

Substation # 6, Sublett Substation, located on Rt 7 near Royalton in Magoffin County.

Circuit # 2, Lakeville Circuit,; this circuit serves areas of Lakeville, Mason Creek, Salyer Branch, Middle Fork, Fritz and Seitz.

This circuit has approximately 54-1 miles of line and serves approximately 621 consumers.

This circuit was cut out in 2012.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Right-of-Way Outside	42%	64%
Right-of-Way Inside	42%	31%
Pre-Arranged Maintenance	9%	2%
Animals	4%	2%
Unknown	3%	1%
Equipment Failure	>1%	>1%
Consumer Caused	>1%	>1%

Circuit 5 Year Average SAIFI—1.5997

Reporting Year 2019, SAIFI—1.5474

Circuit 5 Year Average SAIDI—235.3650

Reporting Year 2019, SAIDI—357.5572

We have no control over right-of-way outside of our cutting area, however, any danger trees that we see outside of our right-of-way we will cut.

## Circuit Reporting

Substation # 6, Sublett Substation, located on Rt 7 near Royalton in Magoffin County.

Circuit # 3, Gunlock Circuit; this circuit serves areas of Swampton, Puncheon, Big Half Mountain, Trace Fork, Salt Lick, Long Branch and Gypsy.

This circuit has approximately 101.8 miles of line and serves approximately 875 consumers.

This circuit was cut out in 2012.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Right-of-Way Outside	59%	48%
Pre-Arranged Maintenance	28%	37%
Animals	5%	5%
Right-of-Way Inside	3%	3%
Unknown	2%	3%
Consumer Caused	2%	3%
Right-of-Way Crew	1%	1%
Line Down	>1%	>1%
Equipment Failure	>1%	>1%

Circuit 5 Year Average SAIFI—2.1710

Reporting Year, 2019 SAIFI—2.8331

Circuit 5 Year Average SAIDI—335.6068

Reporting Year, 2019 SAIDI—372.2949

We have no control over right-of-way outside of our cutting area, however, any danger trees that we see outside of our right-of-way we will cut.



## Circuit Reporting

Substation # 7, Campton Substation, located on Rt 15 in Campton, Wolfe County.

Circuit # 1; Pine Ridge Circuit; this circuit serves areas of Campton, Old Rt 15, Pine Ridge, and part of Quillen Chapel.

This circuit has approximately 29.9 miles of line and serves approximately 691 consumers.

This circuit was cut out in 2015.

Causes and percentages for this circuit:

Cause	%SAIFI	%SAIDI
Right-of-Way Crew	61%	25%
Right-of-Way Outside	17%	54%
Animals	7%	8%
Pre-Arranged Maintenance	7%	3%
Equipment Failure	6%	8%
Unknown	1%	1%
Consumer Caused	1%	1%
Right-of-Way Inside	>1%	>1%

Circuit 5 Year Average SAIFI--.8556

Reporting Year 2019, SAIFI—1.6990

Circuit 5 Year Average SAIDI—68.9364

Reporting Year 2019, SAIDI—111.4313

Sometimes Right-of-Way Crews have a hard time with the direction a tree will fall, may be due to weather conditions or the condition of the tree. Will stress to them about being more cautious when cutting trees near the lines.

## Circuit Reporting

Substation # 7, Campton Substation, located on Rt 15 in Campton, Wolfe County.

Circuit # 3, Vortex Circuit; this circuit serves areas of Hwy 15, Flat Mary, Big Bloody and Bethany.

This circuit has approximately 83 miles of line and serves approximately 546 consumers.

This circuit was cut out in 2015.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Equipment Failure	37%	22%
Pre-Arranged Maintenance	32%	27%
Line Down	21%	36%
Right-of-Way Outside	8%	12%
Animals	1%	2%
Right-of-Way Inside	1%	1%
Unknown	>1%	>1%
Consumer Caused	>1%	>1%

Circuit 5 Year Average SAIFI—2.3965

Reporting Year 2019, SAIFI—2.9414

Circuit 5 Year Average SAIDI—294.6826

Reporting Year 2019, SAIDI—280.1667

We have no control over Equipment failing.

## Circuit Reporting

Substation # 7, Campton Substation, located on Rt 15 in Campton, Wolfe County.

Circuit # 4, Elkins Road; this circuit serves areas of Sandy Ridge, Mullins Point, Elkins Road and Bear Pen.

This circuit has approximately 34.6 miles of line and serves approximately 298 consumers.

This circuit was cut out in 2015.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Right-of-Way Outside	78%	76%
Right-of-Way Inside	7%	6%
Animals	6%	9%
Unknown	4%	5%
Pre-Arranged Maintenance	3%	2%
Equipment Failure	1%	1%
Consumer Caused	1%	1%

Circuit 5 Year Average SAIFI—1.2131

Reporting Year 2019, SAIFI—1.2886

Circuit 5 Year Average SAIDI—103.0568

Reporting Year 2019, SAIDI—101.6542

We have no control over right-of-way outside of our cutting area, however, any danger trees that we see outside of our right-of-way we will cut.

## Circuit Reporting

Substation # 8, Index Substation, located on Rt 191 at Index in Morgan County.

Circuit # 1, Caney Circuit; this circuit serves areas of Malone, Caney, Stacy Fork, and Vance Fork.

This circuit has approximately 36.5 miles of line and serves approximately 402 consumers.

This circuit was last trimmed in 2011.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Pre-Arranged Maintenance	61%	69%
Right-of-Way Outside	18%	18%
Equipment Failure	9%	7%
Animals	7%	4%
Consumer Caused	3%	1%
Right-of-Way Inside	2%	1%
Unknown	>1%	>1%

Circuit 5 Year Average SAIFI--.7143

Reporting Year 2019, SAIFI--.7388

Circuit 5 Year Average SAIDI—66.8928

Reporting Year 2019, SAIDI—86.6418

In order for necessary repairs to be made safely, the power had to be turned off until all repairs were completed.

## Circuit Reporting

Substation #8, Index Substation, located on Rt 191 at Index in Morgan County.

Circuit # 2, Index Circuit; this circuit serves areas of Index and Liberty Road.

This circuit has approximately 22.6 miles of line and serves approximately 279 consumers.

Last time circuit was trimmed was in 2011.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Consumer Caused	40%	24%
Pre-Arranged Maintenance	35%	48%
Right-of-Way Inside	10%	9%
Animals	9%	10%
Right-of-Way Crew	4%	3%
Equipment Failure	2%	6%

Circuit 5 Year Average SAIFI--.7098

Reporting Year 2019, SAIFI--.7563

Circuit 5 Year Average SAIDI--50.6136

Reporting Year 2019, SAIDI--52.6201

We have articles in Magazines and Newspapers and Radio to educate our consumers about watching for power lines when they are working outside. We also do Safety Demonstrations at the Annual Meeting and during Community Days in each County.

## Circuit Reporting

Substation # 9, Maytown Substation, located on Rt 1010 at Maytown, in Morgan County.

Circuit # 1; Ezel Circuit; this circuit serves areas of Ezel, Greasy, Little Blackwater, Hwy 772 and Upper Long Branch.

This circuit has approximately 98.2 miles of line and serves approximately 730 consumers.

This circuit was cut out in 2015.

Causes and percentages for this circuit:

<b>Cause</b>	<b>%SAIFI</b>	<b>%SAIDI</b>
Pre-Arranged Maintenance	55%	63%
Consumer Caused	12%	6%
Equipment Failure	10%	11%
Unknown	9%	8%
Right-of-Way Inside	7%	4%
Right-of-Way Outside	4%	4%
Animals	3%	4%

Circuit 5 Year Average SAIFI--.7086

Reporting Year 2019, SAIFI--.7644

Circuit 5 Year Average SAIDI—55.7090

Reporting Year 2019, SAIDI—94.4000

In order for necessary repairs to be made safely the power had to be turned off until all repairs were completed.

## Circuit Reporting

Substation # 10, Crockett Substation, located on Hwy 172 in Morgan County.

Circuit # 2; Williams Creek Circuit; this circuit serves areas of Williams Creek, Coffee Creek, Upper Sandlick, and Lick Branch.

This circuit has approximately 69.4 miles of line and serves approximately 516 consumers.

Last trim on this circuit was in 2010, but Right-of-Way crew is cutting this circuit out in 2020.

Causes and percentages for this circuit:

Cause	%SAIFI	%SAIDI
Right-of-Way Outside	38%	39%
Right-of-Way Inside	25%	25%
Pre-Arranged Maintenance	20%	9%
Equipment Failure	12%	20%
Unknown	4%	6%
Animals	1%	1%

Circuit 5 Year Average SAIFI—1.2893

Reporting Year 2019, SAIFI—1.2519

Circuit 5 Year Average SAIDI—133.7203

Reporting Year 2019, SAIDI—146.0522

We have no control over right-of-way outside of our cutting area, however, any danger trees that we see outside of our right-of-way we will cut.

## **Vegetation Management Plan**

Licking Valley Rural Electric Cooperative Corporation has an aggressive vegetation program and has contracted B M C Contracting to address our cooperatives right-of-way requirements. Our cooperative like to maintain a sixty foot ground to sky right-of-way clearance on new and existing accounts; however some variety in right-of-way clearance is based on geography/terrain, easement widths, line voltages and property owner issues.

LVRECC is currently working on an eight (8) year rotation cycle. B M C Contracting has a bid crew that is cutting each Substation by Circuit. They also have an hourly crew that cuts hot spots and consumer requests. In addition to B M C; the cooperative has a bush hog that is used for right-of-way clearing when time allows. The cooperative has a right-of-way foreman that oversees B M C contracting crews. B M C Contracting primarily does our Herbicide Treatment, mostly in the months of May through September. As time allows the cooperative does some Herbicide Treatment.