

A Touchstone Energy Cooperative

RECEIVED

APR 13 2022

PUBLIC SERVICE COMMISSION

April 13, 2022

Ms. Linca C. Bridwell, P.E. Executive Director Kentucky Public Service Commission P. O. Box 615 Frankfort, KY 40602-0615

Re: ADMINISTRATIVE CASE NO. 2006-00494 AN INVESTIGATION OF THE RELIABILITY MEASURES OF KENTUCKY'S JURISDICTIONAL ELECTRIC DISTRIBUTION UTILITIES AND CERTAIN RELIABILITY MAINTENANCE PRACTICES

Dear Ms. Bridwell:

Enclosed is Inter-County Energy Cooperative's Annual Report of Reliability pursuant to Public Service Commission Case No. 2006-00494 dated October 26, 2007.

If you have further questions or comments, please direct those to David Phelps, Vice President-Operations, 859-936-7818, <u>davidp@intercountyenergy.net</u> or to Jessie Turpin, System Engineer, 859-936-7857, jessie@intercountyenergy.net.

Sincerely,

Jerry W. Carter President/CEO

This institution is an equal opportunity provider and employer.

SECTION 1: CONTACT INFORMATION

UTILITY NAME REPORT PREPARED BY E-MAIL ADDRESS OF PREPARER PHONE NUMBER OF PREPARER	1.1 1.2 1.3 1.4	Inter-County Energy Jessie Turpin jessie@intercountyenergy.net 859-236-4561 ext. 7857
SECTION	<u>2: REP(</u> 2.1	<u>DRT YEAR</u> 2021

SECTION 3: MAJOR EVENT DAYS

T _{MED}	3.1	8.52437
FIRST DATE USED TO DETERMINE T_{MED}	3.2	Jan. 1, 2016
LAST DATE USED TO DETERMINE T_{MED}	3.3	Dec. 31, 2020
NUMBER OF MED IN REPORT YEAR	3.4	10

NOTE: Per IEEE 1366 T_{MED} should be calculated using the daily SAIDI values for the five prior years. If five years of data are not available, then utilities should use what is available until five years are accumulated.

SECTION 4: SYSTEM RELIABILITY INFORMATION AND RESULTS

TOTAL CUSTOMERS <u>26956</u>	TOTAL CIRCUITS <u>42</u>		
Excluding MED			
5 YEAR AVERAGE SAIDI 98.54 SAIFI 1.04	REPORTING YEAR SAIDI 107.05 SAIFI 1.03		
Including MED			
5 YEAR AVERAGE SAIDI <u>233.33</u> SAIFI <u>1.88</u>	REPORTING YEAR SAIDI 732.50 SAIFI 2.60		

Notes:

1) All duration indices (SAIDI, CAIDI) are to be reported in units of minutes.

2) Reports are due on the first business day of May of each year

3) Reports cover the calendar year ending in the December before the reports are due.

4) IEEE 1366 (latest version) is used to define SAIDI, SAIFI, CAIDI, and $\rm T_{\rm MED}$

2021	

Circuit #1

1. Substation Name and Number

2. Substation Location

3. Circuit Name and Number

4. Circuit Location

Sutton Lane, US Hwy. 27, Ballard Road, Swope Road

Garrard-Fisher Ford Rd-Lancaster

Ballard (2)

Toddville(1)

5. Total Circuit Length (Miles)	22.19
6. Customer Count	387
7. Date of Last Circuit Trim	2020
8. Outage Cause (% of Total Outage Numbers)	
Animals	0.00%
Lightning	4.95%
High Wind	0.00%
Equip. Failure	1.23%
Deteriorated	0.70%
Cars or Trucks	17.76%
Insulation broke	0.00%
Vegetation/Trees	0.00%
Trees Cut Into Line	0.00%
Equipment OL	7.97%
Rain/ Ice	0.00%
Cased by Others	67.40%

9. Circuit 5 Year Average (SAIDI)	0.462464641
10. Reporting Year (SAIDI)	0.667958656
11. Circuit 5 Year Average (SAIFI)	0.243080144
12. Reporting Year (SAIFI)	0.434108527
13. List of Corrective Action, If Any, Taken or To Be Taken	

Circuit #2

1. Substation Name and Number

2. Substation Location

3. Circuit Name and Number

4. Circuit Location

Ottenhiem, Hwy. 39, Broughtontown, Chapel Gap

Lincoln-GreasyRdgRd-Stanford

Highland(3)

Ottenhiem(1)

5. Total Circuit Length (Miles)	91.97
6. Customer Count	784
7. Date of Last Circuit Trim	2017
8. Outage Cause (% of Total Outage Numbers)	
Animals	0.02%
Lightning	0.76%
High Wind	0.01%
Equip. Failure	43.76%
Deteriorated	0.00%
Cars or Trucks	0.89%
Insulation broke	0.00%
Vegetation/Trees	4.83%
Trees Cut Into Line	0.04%
Equipment OL	0.00%
Rain/ Ice	45.05%
Cased by Others	4.64%

9. Circuit 5 Year Average (SAIDI)	2,904690815
10. Reporting Year (SAIDI)	8.054315476
11. Circuit 5 Year Average (SAIFI)	1.798478435
12. Reporting Year (SAIFI)	2.932397959
13. List of Corrective Action, If Any, Taken or To Be Taken	

Circuit #3	
1. Substation Name and Number	Highland(3)
2. Substation Location	Lincoln-GreasyRdgRd-Stanford
3. Circuit Name and Number	Waynesburg(2)
4. Circuit Location	
KY HWY 1247, Red Oak Ln, Rocky	Hollow Rd, US HWY 27S, KY HWY 501, Greenbriar Ro
5 Total Circuit Longth (Miloo)	35.6
5. Total Circuit Length (Miles)	
6. Customer Count	45:
7. Date of Last Circuit Trim	201
8. Outage Cause (% of Total Outage Numbers)	
	Animals 1.44%
	Lightning 18.89%
	High Wind 5.30%
	Equip. Failure 7.09%
	Deteriorated 0.00%
	Cars or Trucks 0.46%
	Insulation broke 0.00%
	egetation/Trees 6.66%
Tre	es Cut Into Line 0.00%
	Equipment OL 0.00%
	Rain/ Ice 56.86%
(Cased by Others 3.29%

9. Circuit 5 Year Average (SAIDI)	1.09736297
10. Reporting Year (SAIDI)	4.400805861
11. Circuit 5 Year Average (SAIFI)	0.815279584
12. Reporting Year (SAIFI)	2.498901099
13. List of Corrective Action, If Any, Taken or To Be Taken	

Circuit #4		
1. Substation Name and Number		Highland(3)
2. Substation Location		Lincoln-GreasyRdgRd-Stanford
3. Circuit Name and Number		GreenRiver(3)
4. Circuit Location	Greasy Ridge Rd, Good	Paster Rd, KyHwy 698, Martins Trail
Spice Ridge, Peck Hol	low, Hwy 198, Mt Salem Rd, S	Short Pike, Indian Creek, Angel Ridge Rd
5. Total Circuit Length (Miles)		135.27
6. Customer Count		1062
7. Date of Last Circuit Trim		2017
8. Outage Cause (% of Total Outag	ge Numbers)	
	Animal	s 0.49%
	Lightning	g 6.48%
	High Wind	d 1.82%
	Equip. Failur	e 2.43%
	Deteriorate	d 0.00%
	Cars or Truck	s 0.16%
	Insulation broke	e 0.00%
	Vegetation/Tree	s 2.29%
	Trees Cut Into Line	e 0.00%
	Equipment O	L 0.00%
	Rain/ Ice	e 19.51%
	Cased by Other	s 66.82%

<u>2021</u>

9. Circuit 5 Year Average (SAIDI)	2.953820485
10. Reporting Year (SAIDI)	5.728358443
11. Circuit 5 Year Average (SAIFI)	1.477811226
12. Reporting Year (SAIFI)	3.481167608
13. List of Corrective Action, If Any, Taken or To Be Taken	

Circuit #5 1. Substation Name and Number Loretto(8) 2. Substation Location Marion-Loretto Rd-Lebanon 3. Circuit Name and Number Spencer H.(3) 4. Circuit Location Loretto Rd, Spencer Hamilton Rd 5. Total Circuit Length (Miles) 10.83 6. Customer Count 109 7. Date of Last Circuit Trim 2021 8. Outage Cause (% of Total Outage Numbers) 162% 4. High Wind 0.00% Cars or Trucks 0.00% 1. Deteriorated 6.47% Cars or Trucks 0.00% 1. Insulation broke 2.67% Vegetation/Trees 0.00% Cars or Trucks 0.00% <	<u>2021</u>	
2. Substation Location Marion-Loretto Rd-Lebanon 3. Circuit Name and Number Spencer H.(3) 4. Circuit Location Loretto Rd, Spencer Hamilton Rd 5. Total Circuit Length (Miles) 10.83 6. Customer Count 109 7. Date of Last Circuit Trim 2021 8. Outage Cause (% of Total Outage Numbers) 1.62% Lightning 18.43% High Wind 0.00% Equip. Failure 0.00% Cars or Trucks 0.00% Insulation broke 2.67% Vegetation/Trees 0.00% Trees Cut Into Line 0.00% Equipment OL 1.15% Rain/ Ice 60.35%	Circuit #5	
3. Circuit Name and Number Spencer H.(3) 4. Circuit Location Loretto Rd, Spencer Hamilton Rd 5. Total Circuit Length (Miles) 10.83 6. Customer Count 109 7. Date of Last Circuit Trim 2021 8. Outage Cause (% of Total Outage Numbers) Animals 1.62% Lightning 18.43% High Wind 0.00% Equip. Failure 0.00% Cars or Trucks 0.00% Insulation broke 2.67% Vegetation/Trees 0.00% Trees Cut Into Line 0.00% Equipment OL 1.15% Rain/ Ice 60.35%	1. Substation Name and Number	Loretto(8)
4. Circuit Location Loretto Rd, Spencer Hamilton Rd 5. Total Circuit Length (Miles) 10.83 6. Customer Count 109 7. Date of Last Circuit Trim 2021 8. Outage Cause (% of Total Outage Numbers) Animals 1.62% Lightning 18. Outage Cause (% of Total Outage Numbers) 0.00% Equip. Failure 0.00% Cars or Trucks 0.00% Insulation broke 2.67% Vegetation/Trees 0.00% Trees Cut Into Line 0.00% Equipment OL 1.15% Rain/ Ice 60.35%	2. Substation Location	Marion-Loretto Rd-Lebanon
5. Total Circuit Length (Miles) 10.83 6. Customer Count 109 7. Date of Last Circuit Trim 2021 8. Outage Cause (% of Total Outage Numbers) 1.62% Lightning 18.43% High Wind 0.00% Equip. Failure 0.00% Deteriorated 6.47% Cars or Trucks 0.00% Insulation broke 2.67% Vegetation/Trees 0.00% Trees Cut Into Line 0.00% Equipment OL 1.15% Rain/ Ice 60.35%	3. Circuit Name and Number	Spencer H.(3)
6. Customer Count 109 7. Date of Last Circuit Trim 2021 8. Outage Cause (% of Total Outage Numbers) Animals 1.62% Lightning 18.43% High Wind 0.00% Equip. Failure 0.00% Deteriorated 6.47% Cars or Trucks 0.00% Insulation broke 2.67% Vegetation/Trees 0.00% Trees Cut Into Line 0.00% Equipment OL 1.15% Rain/ Ice	4. Circuit Location	Loretto Rd, Spencer Hamilton Rd
6. Customer Count 109 7. Date of Last Circuit Trim 2021 8. Outage Cause (% of Total Outage Numbers) Animals 1.62% Lightning 18.43% High Wind 0.00% Equip. Failure 0.00% Deteriorated 6.47% Cars or Trucks 0.00% Insulation broke 2.67% Vegetation/Trees 0.00% Trees Cut Into Line 0.00% Equipment OL 1.15% Rain/ Ice		
7. Date of Last Circuit Trim 2021 8. Outage Cause (% of Total Outage Numbers) Animals 1.62% Lightning 18.43% High Wind 0.00% Equip. Failure 0.00% Equip. Failure 0.00% Deteriorated 6.47% Cars or Trucks 0.00% Insulation broke 2.67% Vegetation/Trees 0.00% Trees Cut Into Line 0.00% Equipment OL 1.15% Rain/ Ice 60.35% 0.05% 0.05%	5. Total Circuit Length (Miles)	
8. Outage Cause (% of Total Outage Numbers) Animals 1.62% Lightning 18.43% High Wind 0.00% Equip. Failure 0.00% Deteriorated 6.47% Cars or Trucks 0.00% Insulation broke 2.67% Vegetation/Trees 0.00% Trees Cut Into Line 0.00% Equipment OL 1.15% Rain/ Ice 60.35%		
Animals 1.62% Lightning 18.43% High Wind 0.00% Equip. Failure 0.00% Deteriorated 6.47% Cars or Trucks 0.00% Insulation broke 2.67% Vegetation/Trees 0.00% Trees Cut Into Line 0.00% Equipment OL 1.15% Rain/ Ice 60.35%	7. Date of Last Circuit Trim	2021
Lightning18.43%High Wind0.00%Equip. Failure0.00%Deteriorated6.47%Cars or Trucks0.00%Insulation broke2.67%Vegetation/Trees0.00%Trees Cut Into Line0.00%Equipment OL1.15%Rain/ Ice60.35%	8. Outage Cause (% of Total Outage Numbers)	
High Wind0.00%Equip. Failure0.00%Deteriorated6.47%Cars or Trucks0.00%Insulation broke2.67%Vegetation/Trees0.00%Trees Cut Into Line0.00%Equipment OL1.15%Rain/ Ice60.35%	Animals	s 1.62%
Equip. Failure0.00%Deteriorated6.47%Cars or Trucks0.00%Insulation broke2.67%Vegetation/Trees0.00%Trees Cut Into Line0.00%Equipment OL1.15%Rain/ Ice60.35%	Lightning	g 18.43%
Deteriorated6.47%Cars or Trucks0.00%Insulation broke2.67%Vegetation/Trees0.00%Trees Cut Into Line0.00%Equipment OL1.15%Rain/ Ice60.35%	High Wind	d 0.00%
Cars or Trucks0.00%Insulation broke2.67%Vegetation/Trees0.00%Trees Cut Into Line0.00%Equipment OL1.15%Rain/ Ice60.35%	Equip. Failure	e 0.00%
Insulation broke2.67%Vegetation/Trees0.00%Trees Cut Into Line0.00%Equipment OL1.15%Rain/ Ice60.35%	Deteriorated	d 6.47%
Vegetation/Trees0.00%Trees Cut Into Line0.00%Equipment OL1.15%Rain/ Ice60.35%	Cars or Trucks	s 0.00%
Trees Cut Into Line0.00%Equipment OL1.15%Rain/ Ice60.35%	Insulation broke	e 2.67%
Equipment OL1.15%Rain/ Ice60.35%	Vegetation/Trees	s 0.00%
Rain/ Ice 60.35%	Trees Cut Into Line	e 0.00%
	Equipment OI	1.15%
Cased by Others 9.31%	Rain/ Ice	e 60.35%
	Cased by Others	s 9.31%

9. Circuit 5 Year Average (SAIDI)	0.267301035
10. Reporting Year (SAIDI)	2.128134557
11. Circuit 5 Year Average (SAIFI)	0.316025235
12. Reporting Year (SAIFI)	1.137614679
13. List of Corrective Action, If Any, Taken or To Be Taken	

	<u>2021</u>	
Circuit #6		
1. Substation Name and Number	H.T. Adams (10))
2. Substation Location	Mercer-DryBran	chRd-Harrodsburg
3. Circuit Name and Number	Harrodsburg(1)	
4. Circuit Location		
	Dry Branch Rd, Kyle Ln, Sparrow Ln, Danville	e Rd, Beaumount Ave,
Bud James Ln, Bellows Mill I	Rd, Mercer Ave, Boyle Ave, Adams Ln, Brightle	af Dr, Cold Springs Dr
5. Total Circuit Length (Miles)		40.88
6. Customer Count		621
7. Date of Last Circuit Trim		2021
8. Outage Cause (% of Total Outage	Numbers)	
	Animals	14.10%
	Lightning	2.62%
	High Wind	0.00%
	Equip. Failure	2.34%
	Deteriorated	41.22%
	Cars or Trucks	0.45%
	Insulation broke	0.00%
	Vegetation/Trees	2.19%
	Trees Cut Into Line	0.00%
	Equipment OL	0.00%
	Rain/ Ice	0.00%
	Cased by Others	37.08%

9. Circuit 5 Year Average (SAIDI)	0.454929228
10. Reporting Year (SAIDI)	0.50907139
11. Circuit 5 Year Average (SAIFI)	0.392541136
12. Reporting Year (SAIFI)	2.22705314
13. List of Corrective Action, If Any, Taken or To Be Taken	

 Circuit #7	
1. Substation Name and Number	Gooch(11)
2. Substation Location	Lincoln-Rice Ln-Stanford
3. Circuit Name and Number	Preachersville(1)
4. Circuit Location	Preachersville Rd, Rice Ln,
Swope Rd, Fall Lick Rd, Drakes Creek Rd, Swampe	er Rd, Harmons Lick Rd, Hwy 3249, Dripping
Springs Rd, Hamilton Valley Rd, Carte	ersville Rd, White Lick Rd, Wallacetown Rd, Calico F
5. Total Circuit Length (Miles)	126.4
6. Customer Count	113
7. Date of Last Circuit Trim	201
8. Outage Cause (% of Total Outage Numbers)	
	Animals 0.89
	Lightning 0.91
	High Wind 21.63
	Equip. Failure 0.39
	Deteriorated 1.79
	Cars or Trucks 0.06
 Ir	nsulation broke 0.00
Ve	getation/Trees 5.33
Tree	s Cut Into Line 0.03
	Equipment OL 0.00
	Rain/ Ice 0.22
Ca	ased by Others 68.74

9. Circuit 5 Year Average (SAIDI)	0.925965904
10. Reporting Year (SAIDI)	4.883996463
11. Circuit 5 Year Average (SAIFI)	0.458615386
12. Reporting Year (SAIFI)	4.274093722
13. List of Corrective Action, If Any, Taken or To Be Taken	

<u>2021</u>

Circuit #8

1. Substation Name and Number

2. Substation Location

3. Circuit Name and Number

4. Circuit Location

Gilberts Creek Road, Goshen Road, Hwy. 590, US 27 North

Lincoln-Rice Ln-Stanford

Gooch(11)

Lancaster(4)

5. Total Circuit Length (Miles)	46.53
6. Customer Count	820
7. Date of Last Circuit Trim	2016
8. Outage Cause (% of Total Outage Numbers)	
Animals	1.44%
Lightning	18.89%
High Wind	5.30%
Equip. Failure	7.09%
Deteriorated	0.00%
Cars or Trucks	0.46%
Insulation broke	0.00%
Vegetation/Trees	6.66%
Trees Cut Into Line	0.00%
Equipment OL	0.00%
Rain/ Ice	56.86%
Cased by Others	3.29%

9. Circuit 5 Year Average (SAIDI)	0.238294092
10. Reporting Year (SAIDI)	0.698821138
11. Circuit 5 Year Average (SAIFI)	0.226257555
12. Reporting Year (SAIFI)	1.179268293
13. List of Corrective Action, If Any, Taken or To Be Taken	

	2021	
Circuit #9		
1. Substation Name and Number	Gooch(11)	
2. Substation Location	Lincoln-Rice Ln-Stanford	
3. Circuit Name and Number	Fairgrounds(5)	
4. Circuit Location		
KY Hwy 1247, Old Ottenheim	Rd, US Hwy 27 S, Maywood Rd, KY	Hwy 3249, KY Hwy 643
E Tatal Observation and (Malas)		C4 00
5. Total Circuit Length (Miles)		61.29
6. Customer Count		894
7. Date of Last Circuit Trim		2016
8. Outage Cause (% of Total Outage Number	,	
	Animals	2.10%
	Lightning	1.74%
	High Wind	1.56%
	Equip. Failure	0.00%
	Deteriorated	8.13%
	Cars or Trucks	1.44%
	Insulation broke	0.00%
	Vegetation/Trees	4.83%
	Trees Cut Into Line	0.00%
	Equipment OL	0.00%
	Rain/ Ice	59.23%
	Cased by Others	20.96%

9. Circuit 5 Year Average (SAIDI)	1.04652653
10. Reporting Year (SAIDI)	5.303765846
11. Circuit 5 Year Average (SAIFI)	0.88849748
12. Reporting Year (SAIFI)	2.16442953
13. List of Corrective Action, If Any, Taken or To Be Taken	

Circuit #10	
1. Substation Name and Number	Garrard(13)
2. Substation Location	Garrard-Enterprise Dr-Lancaster
3. Circuit Name and Number	Gilberts Ck(2)
4. Circuit Location	
Richmond Rd, Eastland Acres, Fall	Lick Rd, Crab Orchard Rd, Stingy Creek Rd, Perkins L
E Total Circuit Langth (Milea)	
5. Total Circuit Length (Miles)	31.7
6. Customer Count	36
7. Date of Last Circuit Trim	201
8. Outage Cause (% of Total Outage Numbers)	
	Animals 2.70°
	Lightning 11.14 ^o
	High Wind 8.95
	Equip. Failure 37.12 ^o
	Deteriorated 0.009
	Cars or Trucks 0.00
	Insulation broke 0.00 ⁴
	/egetation/Trees 8.00 ⁴
Tre	ees Cut Into Line 0.00
	Equipment OL 0.00
	Rain/ Ice 9.62
	Cased by Others 22.46 ^c

9. Circuit 5 Year Average (SAIDI)	0.345720259
10. Reporting Year (SAIDI)	0.717167577
11. Circuit 5 Year Average (SAIFI)	0.327302454
12. Reporting Year (SAIFI)	0.412568306
13. List of Corrective Action, If Any, Taken or To Be Taken	

Electric Distribution Utility Annual Reliability Report

Additional pages may be attached as necessary SECTION 6: VEGETATION MANAGEMENT PLAN REVIEW

Inter-County Energy will complete the revised 6 year vegetation management plan and will be restarting the new 6 year cycle in 2023. Inter-County Energy is closely monitoring the results of the cycle progress.

SECTION 7: UTILITY COMMENTS