

COMMONWEALTH OF KENTUCKY  
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

TONY HENDERSON D/B/A TONY HENDERSON )  
PLUMBING )  
 )  
\_\_\_\_\_)  
 )  
ALLEGED VIOLATION OF UNDERGROUND )  
FACILITY DAMAGE PREVENTION ACT )

CASE NO.  
2021-00230

OPENING ORDER

Tony Henderson D/B/A Tony Henderson Plumbing (Mr. Henderson) has been named as a party to an investigation before the Kentucky Public Service Commission (Commission) for allegedly violating the Kentucky Underground Facility Damage Prevention Act (Act).<sup>1</sup>

Pursuant to KRS 278.495(2), the Commission has jurisdiction to regulate the safety of natural gas facilities in Kentucky and to enforce minimum federal pipeline safety standards. Under the Act, the Commission has authority to investigate and assess civil penalties for any violation of the Act that results in excavation damage to an underground facility used to transport natural gas or hazardous liquid subject to federal pipeline safety laws, 49 U.S.C. § 60101, *et seq.* Any person who violates any provision of the Act is subject to assessment of a civil penalty in the amount of \$250 for the first offense, no more than \$1,000 for the second offense within one year, and no more than \$3,000 for the third and any subsequent offense. Additionally, any person whose violation of the Act

---

<sup>1</sup> KRS 367.4901 through KRS 367.4917.

results in damage to an underground facility containing any flammable, toxic, corrosive, or hazardous material or results in the release of any flammable, toxic, corrosive, or hazardous material is subject to an additional penalty of up to \$1,000.

Following receipt of a report of excavation damage to its underground gas pipeline from an operator, Commission Staff (Staff) conducted an investigation and prepared an Incident Report, a copy of which is attached to this Order as an Appendix. In its Incident Report, Staff cites Mr. Henderson for violation of the following provision of the Act:

KRS 367.4911(3)(c) – Each excavator shall provide each applicable protection notification center with adequate information regarding the excavation or demolition site location or locations, each of which shall not exceed two thousand (2,000) feet in length unless the excavator and operator agree to a larger area, the city or community, county and street address, including the nearest cross street.

Based on its review of the Incident Report and being otherwise sufficiently advised, the Commission finds prima facie evidence that Mr. Henderson violated the Underground Facility Damage Prevention Act. The Commission further finds that a formal investigation into the excavation damage incident should be conducted.

IT IS THEREFORE ORDERED that:

1. Mr. Henderson shall submit to the Commission, via email sent to [PSCED@ky.gov](mailto:PSCED@ky.gov) with the case number of this proceeding in the subject line of the message, a written response to the allegations contained in the Staff Incident Report within 20 days of receipt of this Order.


2. **Any partnership, corporation, or business entity (including a limited liability company) must be represented by an attorney licensed to practice law in Kentucky, and such representation includes the filing of papers with and appearances at hearings before the Commission.**

3. The Staff Incident Report 43377 in the Appendix to this Order is made a part of the record in this case.

**4. Please note that notice of a hearing to be held in this matter will be mailed to Mr. Henderson once proof of service is received by the Commission. Parties who fail to appear after service will be subject to entry of a default judgment against them.**

[REMAINDER OF PAGE INTENTIONALLY LEFT BLANK]

By the Commission



ATTEST:

---

Executive Director

APPENDIX

APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE  
COMMISSION IN CASE NO. 2021-00230 DATED JUN 25 2021

NINETEEN PAGES TO FOLLOW

# PIPELINE DAMAGE INVESTIGATION REPORT

## Investigation Information

<b>KY PSC Investigator(s)</b> Eric V. Tout <b>Incident Date</b> 1/29/2021 12:40:00 PM	<b>Incident ID</b> 43377 <b>Report Submitted</b> 2/14/2021 7:31:32 PM	<b>Key</b> 7260
--	--	-----------------

## OPERATOR INFORMATION

<b>Operator</b> Atmos Energy Corporation <b>Phone</b> (270) 779-4849 <b>Incident Location</b> 740 Cedar, Calvert City/ Paducah 740 Cedar St Calvert City, KY 42029 Marshall	<b>Reported By</b> Anthony Stallins <b>Email</b> anthony.stallins@atmosenergy. <b>Locate Ticket Number</b> 2101261454
---	---

## EXCAVATOR INFORMATION

<b>Name of Excavator</b> Henderson, Tony <b>Phone</b> 270-703-0215/270-210-0131 <b>Excavator Address</b> Tony Henderson Plumbing 163 Mulberry Dr. Gilbertsville, KY 42044	<b>Organization ID</b> <b>Email</b> tonyh@mchsi.com <b>Locate Ticket Number</b>
--	---

## INCIDENT

The Operator reports that the Excavator damaged a 3/4 inch gas service with a backhoe repairing a water leak and the Loacte Ticket (LT) was for the address of 758 Cedar St., but the damage occurred in the back yard of 740/738 Cedar St.

The Damage Report (DR) is include as Attachment 1.

## DR Summary

Excavation Within 18" (Approximate Location)	Type Of Equipment Used	Cost of Damage	Amount Billed
Outside scope of LT	Mechanized / Backhoe	\$867.00	\$867.00

## LT Summary

Ticket #& Address	Valid	Initial Date	Expiration Date (21 calendar days from Initial date)	Incident Date	# of Days Expired	Within Scope of Excavation
2101261454 758 Cedar St.	Yes	01/26/21	02/16/21	01/29/21	0	No

The Locate Ticket(s) is/are include as Attachment 2.

## INVESTIGATION

A review of LT...1454 reveals the ticket was obtained on 01/26/21 by the Excavator for the address of 758 Cedar St. To locate the rear of the building within a 100 foot radius. *Note:* Said ticket mentions no location across Apricot Ave. at 740 Cedar St.

On 03/19/21 the Excavator, Tony Henderson Plumbing's Tony Henderson, stated that this was within the scope of the LT and the Operator did not mark the entire ticket. Mr. Henderson stated that the damage occurred across the street within the 100 foot radius of the rear of 758 Cedar St.

On 03/22/21 the Operator, Atmos's Anthony Stallins, provide an aerial photograph indicating both addresses, 740 & 758 Cedar, are on the corner of Cedar St. and Apricot Ave. The photograph depicts the damage occurred in the back/side yard across Apricot Ave, at 740 Cedar St.

Atmos's photograph is include as Attachment 3.

On 03/23/21 Mr. Henderson stated that the 03/19/21 conversation was not with him it was with an employee. Mr. Henderson was informed of the above noted information and he provided the following. Mr. Henderson stated that the Housing Authority owns the subdivision, therefore anything within 100 ft. radius of 758 Cedar St., including across Apricot Ave. at 740 Cedar St. should have been marked. Staff informed Mr. Henderson of the Damage Prevention Course and 30 days to make the reduced penalty payment of \$250.00 or within 30 days send a letter to the Commission indicating the intention to dispute Staff's findings.

On 03/23/21 Mr. Stallins provide the Show Compliance/Construction report and photographs. The report indicates the damage cause as Insufficient Call and the photographs depict the incident location and damage.  
**Report & Photographs are included as Attachment 4.**

**VIOLATION**

**KRS 367.4911**

**(3)** Each excavator shall provide each applicable protection notification center with adequate information regarding:  
**(c)** The excavation or demolition site location or locations, each of which shall not exceed two thousand (2,000) feet in length unless the excavator and operator agree to a larger area, the city or community, county and street address, including the nearest cross street.

**# of Offences**

(Including this incident)

<b>Excavator</b>	<b>Last Offence Incident #</b>	<b>Last Offence Incident Date</b>	<b>Last Offence Resolved Date</b>
1 <sup>st</sup>	N/A	N/A	N/A

# Attachment 1



# Gas Excavation Damage Report

## Atmos Energy Corporation

Submitted 2/14/2021 Incident ID 43377

[Set back to Edit](#)[Staff Edit](#)[Print \(PDFForm.aspx?Rpt=GasInvestigation&IG=43377\)](#)

### Reported By:

Name	Anthony Stallins
Phone	(270) 779-4849
Email	anthony.stallins@atmosenergy.com

### Gas Line Incident Occured:

Date	1/29/2021
Time	12:40 PM

### Details:

Reported Date	1/30/2021 7:58 AM
---------------	-------------------

### Incident Location Address:

Location	740 CEDAR, CALVERT CITY/ Paducah
Address	740 Cedar St
City	Calvert City
State	KY
County	Marshall
Zip	42029
Confirm Code	Y

Number of Customers out	2
-------------------------	---

Was gas or hazardous liquids contained in the underground facility?	<input checked="" type="checkbox"/>
---	-------------------------------------

Was gas or hazardous liquids released into the atmosphere?	<input checked="" type="checkbox"/>	*
		3/2020

Locate Request Ticket No.	2101261454
---------------------------	------------

Excavator	Contractor
-----------	------------

### Excavator Address:

First Name	Tony
Last Name	Henderson
Organization ID	
Company	Tony Henderson Plumbing
Phone	270-703-0215/270-210-0131
Email	tonyh@mchsi.com

**Address** 163 Mulberry Dr  
**City** Gilbertsville  
**State** KY  
**Zip** 42044  
**Confirm Code** Y  
**Excavation Damage** One Call notification practices not sufficient

**Description of Incident** Cut 3/4" PE service line. Locate ticket (wrong address). Two customers off. No injuries.

Summary Information

---

2/14/2021

**Full details such as the cause** Tony Henderson Plumbing, repairing a water leak, cut a 3/4" PE service line with a backhoe. Tony Henderson Plumbing had called KY 811 for a locate ticket (2101261454). The ticket was called in for 758 Cedar St, "Locate the rear of the building with 100 foot radius". The service was cut across the street (Apricot Ave) from 758 Cedar St, in the back yard of 740/738 Cedar St (duplex). The damage was due to the wrong, insufficient dig site information (correct address) being provided to KY 811.

**Extent of the damage** The damage PE was repaired and service restored to the two affected customers.

**Cost of the damage** \$867.00

**Steps taken to prevent re-occurrence** Tony Henderson Plumbing was made aware of the need to provide a correct addresses on their locate tickets.

**Amount billed to excavator** \$867.00

# Attachment 2

NORMAL NOTICE

Ticket : 2101261454 Date: 01/26/2021 Time: 16:07 Oper: JCOONEY Chan:000

State: KY Cnty: MARSHALL City: CALVERT CITY  
Subdivision:

Address : 758  
Street : CEDAR ST  
Cross 1 : APRICOT AVE  
Location: LOCATE THE THE REAR OF THE BUILDING WITH A 100 FOOT RADIUS  
:  
Boundary: n 37.022888 s 37.021074 w -88.349741 e -88.347446

Work type : REPAIRING WATER LEAK  
Done for : HOUSING AUTHORITY OF BENTON  
Start date: 01/28/2021 Time: 16:15 Hours notice: 48/48 Priority: NORM  
Ug/Oh/Both: U Blasting: NO Emergency: N  
Duration : N/A Depth: 6 FEET


Company : TONY HENDERSON PLUMBING Type: OTHR  
Co addr : 163 MULBERRY DRIVE  
City : GILBERTSVILLE State: KY Zip: 42044  
Caller : SCOTT MARTIN Phone: (270)210-0131  
Contact : SCOTT MARTIN - CELL Phone:  
Mobile : (270)703-0215  
Email : TONYH@MCHSI.COM

Submitted date: 01/26/2021 Time: 16:07  
Members: 0135 0725 WINKY

# Attachment 3

758 Cedar St

Legend

 758 Cedar St

 758 Cedar St

100 ft



Google Earth



# Attachment 4

**Atmos Energy Corporation - Show Compliance/Construction Order Details**

Business: 3404 40 Ky - eAM	Asset: LEAK710026	Order# - Done - Status - Type: 19920114 - 01/29/2021 - C - LKRP	Job Code: LKRP
<input type="button" value="Display Normal"/> <input type="button" value="Display Debug"/> <input type="button" value="ReSet"/>		Run Time: 03/23/2021 13:21	

**Job Details**

Status Complete	Office: PADUCAH	Done: 01/29/2021	Source: Qk
Type:	SubRegion: West Central	District:	In MA:
Region: NORTHERN			

**Schedule Data**

Start Date: 01/30/2021	Base Date:	Interval: 0	Printed:	Print Date:
------------------------	------------	-------------	----------	-------------

**Asset Description**

Asset Group: LEAKS	Asset#: LEAK710026	Parent Asset#: LKS (2637)
Asset: 740 CEDAR 1201600 CALVERT CITY		Activity: LEAK REPAIR 1 2637
Description: Owning WB2637	Child Assets:	Status: InActive
Department:		

**Location Physical Information**

GPS 37.02219	GPS Longitude: -88.34835	GPS Altitude: 0
Latitude:		State: KY
Address: 740 CEDAR	Time Zone:	DST:
Town/City: 1201600 CALVERT CITY	Cross Street: apricot	
In/Outside: INSIDE		
City Limits:		
Other Location Information:		Class Location: 3
Map Number:		Control Code:
County: 21157 MARSHALL		
Property: 92701 MARSHALL,CALVERT CITY,CALVERT CTY & COM SCH		
Tax Code:		
School District:		
Land Description:		Certificate of Occupancy Required:
City Inspection Required:		

**Location Additional Information**

WorkArea/SubArea: KYPADUCA	PipeLine #:	Read Sequence:
Station Number:	Printer Name: noprint	Corrosion Section:
System Number:		Project Number:
Pipeline Balance Code:		Task Number:
Operation Area: KYPAD	Rate Division: 009	Facilities Classification: DIST
Retirement Unit Name: Non Utilized Retirement Unit		Zip:
Related SAP SO Number: 100018778200		

**Leak Data**

Date: 2021/01/29 12:40	Time Classified: 12:50:17	Leak Grade: 1
Found:		CGI Reading: 100
Leak Grade: 11200 Schmidt, Richard	Grade 2 Interval:	Unit of Measure: % GAS
By:	Population Density: RES	
Apparent Location: SERVICE	Surface Type: DIRT	
Ft To: 50		
Building: DUG UP INLET RISER	Leak Repaired: N	Leak Located (LKFD - 2): 2 - Below Ground
Location:		
Comments: line not marked		

**(LKRP) Leak Repair Completion Data**

Leak	Facility Involved: 2 - Service	Origin of Leak: 2 - Body of Pipe
------	--------------------------------	----------------------------------



Atmos Energy Corporation - Show Compliance/Construction Order Details

Business: 3404  
40  
Ky - eAM

Asset:  
LEAK710026

Order# - Done - Status - Type:  
19920114 - 01/29/2021 - C - LKRP

Job Code:  
LKRP

Display Normal



Display Debug

ReSet

Run Time: 03/23/2021 13:21

Found (Yes/No):  
Reason Not  
Type of Pipe: 8 - High Density Polyethylene  
Repaired: Not  
Initial Cause: EXCAVATION GROUP Ferc Acct: 8740  
Condition of Coating: NA Wall Thickness: 0 External Corrosion: NA  
Corrosion 0 Internal Corrosion: NA PS Reading: 0  
Pit Depth (in): NA Test Pressure: 156 Test Duration: 7  
Coating Type: NA Soap Test (YNMA): Y Info Chg Req: N  
Repaired Date: 01/29/2021 Test Medium: NITROGEN Addit. Maint. Req: N  
Residual Gas Follow-Up: N

Installed 1	Length Units: 5	Task: SERVICE	Size: 1	Type: PE
Removed 1	Length Units: 5	Task: 02980	Size: 80	Type: PE
Installed 2	Length Units:	Task:	Size:	Type:
Removed 2	Length Units:	Task:	Size: 0	Type:

Leak Located: 2 - Below Ground Cause Code: 22 - Other Third Party Excavators Repair Method: 6 - Pipe Replaced  
Other Leak Cause: Fitting Type: Astm Code: OTP  
Pipe Size: 3rd Party Y Pipe Mfg Code: OTH - Other Manufacturer Joint Type: Other Mfg: Charter Plastic  
Damage:

(LK3P) Leak 3rd Party Data

Completion Data  
Activity: LEAK REPAIR 1 Asset Num: Task ID:  
2637  
Damage Date: 2021/01/29 Leak Area Sq. IN: 0 Locate ID #: Y  
3rd Party Name: tony henderson plumbing Locate Ticket #: 2101261454  
Address: 163mulberry  
Leak 3 Located By: CONTRACTLOC  
Duration Minutes: 3  
Injuries or Deaths OnSite: 0 Damage to Property: Y Date Located2:  
Locate Mark within State Law: U Repair Total: 3rd Party Phone #:  
Reason Damage Occurred: INSUFCALL Type of 3rd Party Work: WATER  
Date Locate Requested: Locate Priority: Ferc Acct:  
Equipment Causing Damage: Date Located: Date Locate Requested: 2021/01/27  
3rd Party Contact: tony henderson  
Ins Company: Ins Agent: Agent Phone:  
Type Excavator: CONTRACTOR Damage Where: City: gilbertsville  
Facility Involved: DISTRIBUTION Num Cust Effected: 2 State: KY  
Time Located: Billed: Zip: 42044  
Damage Location: Damage By: THIRDPY Title 16: U

Atmos Energy Corporation - Show Compliance/Construction Order Details

Business: 3404  
40  
Ky - eAM

Asset:  
LEAK710026

Order# - Done - Status - Type:  
19920114 - 01/29/2021 - C - LKRP

Job Code:  
LKRP

Display Normal Display Debug ReSet

Run Time: 03/23/2021 13:21

FAC Material: BODYOFPIPE	FAC Release Plan: Y	One Call Code: yes
Damage: FAC 911 U	FAC Locate Code: INTRA	FAC Pipe Diameter: 0
Damage Call:	Excavator Ticket: 2101261454	Excavator Notify Oper: U
Excavator Y	Pipeline Material: POLYPLAS	Pipeline Year:
Call:	Fire Comments:	Type of Injury:
Pipeline IS: ACTIVE	Mark 2nd Call Rsn:	Mark 2nd Call Oth:
Prod Trans Code:	Mark 2nd Call Date:	Mark 2nd Call Resp:
Mark ::	Mark Why and Rsn:	Mark Why Other:
Positive Response:	Locator Other Explain:	
Mark 2nd Call Ticket:		
Mark ::		
Positive Response:		
Mark 0		
Variance Inches:		
SubDivision:	Incident Address: 740 cedar	Incident Time: 12:40:PM
Lat Long DECIMAL	Latitude: 37.02219	Longitude: -88.34835
LkUp:	Travel 3: .1	OnSite 3: 3
Tech 3: 27111 Baker, Clayton		

(LK3P) RRC Leak 3rd Party

Data Completion Data	Asset Num:	Task ID:
Activity: LEAK REPAIR 1 2637	Excavator Name: tony henderson plumbing	Excavator Address: 163mulberry
Date of Damage: 2021/01/29	Excavator State: KY	Excavator Zip: 42044
Excavator City: gilbertsville	Excavator Phone:	Excavator Fax:
Excavator Contact Name: tony henderson	Excavator Type Code: CONTRACTOR	Excavation Type:
Excavator Email: U	Excavator Depth Ft: 0	Excavator Depth In: 0
Work Code: WATER	Incident NO:	Country: US
Performed Code: N	City: yes	Address: 740 cedar
Was Called: N	RightOfWay Type: CITYST	Fac Damaged Code:
State: KY	Fac Damaged Depth Ft: 3	Fac Damaged Depth In: 0
Intersection: apricot	OneCall Member: Y	Locate Request: Y
Fac Affected Code: DISTRIBUTION	OneCall Ticket#: 2101261454	OneCall Ctr Notified Date: 2021/01/27
Joint U	Locator Name: health	Fac Marks Visible: N
Trench:	Marked Variance Ft: 0	Marked on Time:
OneCall Center Code: yes	Marked Loc. Meth Oth:	Marked by Paint:
Locate Org Code: CONTRACTLOC	Marked by Other: N	Marked by Other Comnt:
Fac Marks Correct:	Marked Spec Instruction: N	Marked Using Maps: U
Marked Locate Method:	Marked Loc Met with Exc: U	Marked Reps OnSite: Y
Marked by Flags:	Marked Procedure Used: U	Marked Positive Response: U
Marked By White Lining:	Excavator Down Time: -1	Excavator Down Cost:
Marked 48 HR Notice:	Service Interruption: Y	Outage Hours: 0
Marked Second Call:		
Excavator Down:		
Was Fac Y		

Atmos Energy Corporation - Show Compliance/Construction Order Details

Business: 3404  
40  
Ky - eAM

Asset:  
LEAK710026

Order# - Done - Status - Type:  
19920114 - 01/29/2021 - C - LKRP

Job Code:  
LKRP

Display Normal Display Debug ReSet

Run Time: 03/23/2021 13:21

Damaged:		
Customers Affected:	Restoral Cost: 0	Number People Injured: 0
Number:	Impact Fire Occurr: N	Impact Evac: N
Fatalities:	Impact Evac Comnt:	Impact Media Covrg: N
Impact Evac No People:	Impact Street: N	Impact Street Comnt:
Impact Media Covrg Comnt:	Impact Explosion Comnt:	Impact Other: N
Impact N:	Impact No addl:	Damage Cause Code: INSUFCALL
Explosion:		
Impact Other:		
Explanation:		
Damage:		
Other Desc:		

Comments & Labor

Comments: Excavator cut 3/4 service line while repairing water leak.[Excavator cut 3/4 service line while repairing water leak.

Tech: 27738 Hill, Jared

Travel: .02

OnSite: 8.35

Tech 3: 27111 Baker, Clayton

Travel 3: .1

OnSite 3: 3

Data Entry Stats

Asset	01/29/2021	By: 8247	EAMADMIN
Order	01/29/2021	By: 8247	EAMADMIN
Q.	02/01/2021	By: 8247	EAMADMIN

ET .933 Minutes RECORD Count

0

Atmos All Clear Flag in yard of 758 Cedar St. where locate was called in.



Picture of duplex 740-738 Cedar St where damage occurred.



Picture showing equipment in the yard of 740-738 Cedar where damage occurred.



Picture of damage.



Picture showing damage from Apricot Ave.



## Tout, Eric V (PSC)

---

**From:** Stallins, Anthony A <Anthony.Stallins@atmosenergy.com>  
**Sent:** Tuesday, March 23, 2021 2:50 PM  
**To:** Tout, Eric V (PSC)  
**Subject:** RE: 43377, 1/29/2021, 740 Cedar, Calvert City, Tony Henderson Plumbing  
**Attachments:** Damage from Apricot St.jpg

Eric,

Picture showing damage from Apricot Ave.

Thanks, Anthony

---

**From:** Stallins, Anthony A <Anthony.Stallins@atmosenergy.com>  
**Sent:** Tuesday, March 23, 2021 1:48 PM  
**To:** Tout, Eric V (PSC) <ericv.tout@ky.gov>  
**Cc:** Stallins, Anthony A <Anthony.Stallins@atmosenergy.com>  
**Subject:** RE: 43377, 1/29/2021, 740 Cedar, Calvert City, Tony Henderson Plumbing

Eric,

Picture showing equipment in the yard of 740-738 Cedar where damage occurred.  
Picture of damage.

Thanks, Anthony

---

**From:** Stallins, Anthony A <[Anthony.Stallins@atmosenergy.com](mailto:Anthony.Stallins@atmosenergy.com)>  
**Sent:** Tuesday, March 23, 2021 1:45 PM  
**To:** Tout, Eric V (PSC) <[ericv.tout@ky.gov](mailto:ericv.tout@ky.gov)>  
**Cc:** Stallins, Anthony A <[Anthony.Stallins@atmosenergy.com](mailto:Anthony.Stallins@atmosenergy.com)>  
**Subject:** RE: 43377, 1/29/2021, 740 Cedar, Calvert City, Tony Henderson Plumbing

Eric,

Atmos All Clear Flag in yard of 758 Cedar St where locate was called in.

Picture of duplex 740-738 Cedar St where damage occurred.

Anthony

---

**From:** Stallins, Anthony A <[Anthony.Stallins@atmosenergy.com](mailto:Anthony.Stallins@atmosenergy.com)>  
**Sent:** Tuesday, March 23, 2021 1:29 PM  
**To:** Tout, Eric V (PSC) <[ericv.tout@ky.gov](mailto:ericv.tout@ky.gov)>  
**Cc:** Stallins, Anthony A <[Anthony.Stallins@atmosenergy.com](mailto:Anthony.Stallins@atmosenergy.com)>  
**Subject:** 43377, 1/29/2021, 740 Cedar, Calvert City, Tony Henderson Plumbing

Eric,

Atmos Report for the damage at 740 Cedar St in Calvert City. I will forward you the pictures.

Thanks, Anthony

---

**From:** Tout, Eric V (PSC) <[ericv.tout@ky.gov](mailto:ericv.tout@ky.gov)>  
**Sent:** Tuesday, March 23, 2021 11:32 AM  
**To:** Stallins, Anthony A <[Anthony.Stallins@atmosenergy.com](mailto:Anthony.Stallins@atmosenergy.com)>  
**Subject:** [EXT] 43377, 1/29/2021, 740 Cedar, Calvert City, Tony Henderson Plumbing

**CAUTION: Don't be quick to click. This e-mail originated from outside of Atmos Energy. Do not click links or open attachments unless you recognize the sender and know the content is safe.**

Anthony,

Getting push back on this one may go the hearing, will need damage report and all photos.

*Thanks,  
Eric V. Tout  
Kentucky Public Services Commission  
Division of Inspections / Damage Prevention  
211 Sower Blvd., Frankfort, KY 40601  
Office: 502-782-2622  
Fax: 502-564-1582*



Tony Henderson Plumbing  
163 Mulberry Dr.  
Gilbertsville, KENTUCKY 42044