

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY POWER COMPANY)	
)	
and)	
)	
SOUTH CENTRAL BELL TELEPHONE COMPANY)	CASE NO.
)	89-258
_____)	
)	
ALLEGED FAILURE TO COMPLY WITH)	
COMMISSION REGULATIONS)	

O R D E R

IT IS ORDERED that Kentucky Power Company ("Kentucky Power") shall file the original and 12 copies of the following information with the Commission within 15 days from the date of this Order with a copy to all parties of record. Each copy of the data requested should be placed in a bound volume with each item tabbed. When a number of sheets are required for an item, each sheet should be appropriately indexed, for example, Item 1(a), Sheet 2 of 6. Include with each response the name of the witness who will be responsible for responding to questions relating to the information provided. Careful attention should be given to copied material to ensure that it is legible.

1. List and describe all discussions between South Central Bell Telephone Company ("SCB") employees and Kentucky Power employees since January 1, 1989 concerning Kentucky Power or SCB facilities in the vicinity of the accident site. List the name

and position of each Kentucky Power employee involved. List the date of each discussion. Provide any correspondence or internal memorandum concerning these discussions. Provide any correspondence between SCB and Kentucky Power since January 1, 1989 involving SCB or Kentucky Power facilities in the vicinity of the accident site.

2. When did Kentucky Power learn of the accident involving Johnny Minks?

3. When, if ever, did Kentucky Power advise SCB of the accident involving Johnny Minks? How did it advise SCB? What information did Kentucky Power provide SCB about the accident and about SCB facilities in the vicinity of the accident?

Done at Frankfort, Kentucky, this 12th day of April, 1990.

PUBLIC SERVICE COMMISSION


For the Commission

ATTEST:

Executive Director

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY POWER COMPANY)	
)	
and)	
)	
SOUTH CENTRAL BELL TELEPHONE COMPANY)	CASE NO.
)	89-258
_____)	
)	
ALLEGED FAILURE TO COMPLY WITH)	
COMMISSION REGULATIONS)	

O R D E R

IT IS ORDERED that South Central Bell Telephone Company ("SCB") shall file the original and 12 copies of the following information with the Commission within 15 days from the date of this Order with a copy to all parties of record. Each copy of the data requested should be placed in a bound volume with each item tabbed. When a number of sheets are required for an item, each sheet should be appropriately indexed, for example, Item 1(a), Sheet 2 of 6. Include with each response the name of the witness who will be responsible for responding to questions relating to the information provided. Careful attention should be given to copied material to ensure that it is legible.

1. Prior to June 21, 1989, when did SCB last inspect its facilities at the accident site as required by Commission Regulation 807 KAR 5:006, Section 23(6)(a)? Identify the persons who conducted this inspection. How was the inspection conducted?

2. When an inspection of the accident site area was conducted on July 7, 1989, was the clearance defect cited in the Electrical Utility Accident Investigation Report detected by those conducting the inspection? If not, why not?

3. Did the work order issued on July 7, 1989 for corrections at the accident site originally include rerouting the span of SCB telephone cable which overhung Gregory Heavy Equipment Repair Garage? If no, when was the work order amended to include rerouting of this span? What repair work did the original work order cover?

4. When did SCB learn of the accident involving Johnny Minks? How did SCB learn of this accident?

5. When did SCB learn of the clearance defect cited in the Electrical Utility Accident Investigation Report? How did SCB learn of it?


6. List and describe all discussions between SCB employees and Kentucky Power Company ("Kentucky Power") employees since January 1, 1989 concerning Kentucky Power or SCB facilities in the vicinity of the accident site. Identify the name and position of each SCB employee involved. List the date of each discussion. Provide any correspondence or internal memorandum concerning such discussions. Provide any correspondence between SCB and Kentucky Power after January 1, 1989 involving SCB or Kentucky Power facilities in the vicinity of the accident site.

7. When did SCB first learn of the construction of a structure under its telephone cables at the accident site?

8. On August 17, 1989, Kentucky Power rerouted its 7200 volt overhead line to ensure that its path did not cross any structure on the premises of Gregory Heavy Equipment Repair Garage. When did SCB learn of Kentucky Power's action? Did Kentucky Power's actions require SCB to make changes to its own facilities? If yes, list and describe these changes.

Done at Frankfort, Kentucky, this 12th day of April, 1990.

PUBLIC SERVICE COMMISSION


For the Commission

ATTEST:

Executive Director