

RECEIVED

OCT 12 2010

PUBLIC SERVICE
COMMISSION

October 12, 2010

HAND DELIVERED

Mr. Jeff Derouen
Executive Director
Kentucky Public Service Commission
P.O. Box 615
211 Sower Boulevard
Frankfort, KY 40602

Re: PSC Case No. 2010-00265

Dear Mr. Derouen:

Please find enclosed for filing with the Commission in the above-referenced case an original and ten copies of East Kentucky Power Cooperative Inc.'s revised response to Item 7, Page 17 of 37, originally filed September 7, 2010. Information for the March 19 and March 26 outages has been modified.

Very truly yours,



Ann F. Wood
Manager, Regulatory Services

Enclosures

Production Management Reporting System



East Kentucky Power

Appendix B

From: Nov. 1, 2009 thru April 30, 2010

ITEM NO. 7

Page 17 of 37

REVISED

Green Valley Landfill

Unit Two

Date	Time Off/On	Available MW	Forced or Scheduled	Status	Actual		Cause or Reason
					Hours	Minutes	
11/16/2009	0207	0.0	Forced	Fuel Outage	1	45	Reserved shutdown state due to fuel supply.
01/03/2010	1431	0.0	Forced	Maintenance	6	21	Unit in standby due to substation breaker operation.
01/03/2010	2052	0.0	Forced	Fuel Outage	20	23	Reserved shutdown state due to fuel supply.
01/09/2010	1515	0.0	Forced	Maintenance	2	8	Unit in standby due to substation breaker operation.
01/20/2010	0950	0.0	Scheduled	Maintenance	0	25	Oil service.
01/31/2010	1735	0.0	Forced	Fuel Outage	2	16	Reserved shutdown state due to fuel supply.
03/12/2010	0802	0.0	Forced	Maintenance	0	6	Detonation caused by shift in gas quality.
03/15/2010	0507	0.0	Forced	Maintenance	29	51	Engine failure.
03/19/2010	1712	0.0	Forced	Fuel Outage	165	18	Reserved shutdown state due to fuel supply.
03/26/2010	1558	0.0	Forced	Maintenance	0	10	Repaired engine.
03/26/2010	1622	0.0	Forced	Maintenance	1	7	Repaired engine.
03/31/2010	0913	0.0	Scheduled	Maintenance	6	27	Performed plug, valve, and oil service.
04/08/2010	2346	0.0	Forced	Maintenance	11	43	Unit tripped due to methane detection system failure.
04/10/2010	1324	0.0	Forced	Maintenance	67	25	Unit tripped due to methane detection system failure.
04/13/2010	1043	0.0	Forced	Maintenance	0	51	High oxygen due to well field mechanical failure.
04/13/2010	1207	0.0	Forced	Maintenance	1	40	High oxygen due to well field mechanical failure.
04/13/2010	1419	0.0	Forced	Maintenance	19	49	High oxygen due to well field mechanical failure.
04/17/2010	1533	0.0	Forced	Maintenance	42	34	Unit tripped due to flare malfunction.