COMMONWEALTH OF KENTUCKY BEFORE THE PUBLIC SERVICE COMMISSION

in the Matter of:

LOUISVILLE GAS AND ELECTRIC COMPANY)))	CASE NO. 2013-00	0373
ALLEGED FAILURE TO COMPLY WITH KRS 278.042)		

ORDER

Louisville Gas and Electric Company ("LG&E"), a Kentucky corporation which engages in the distribution for compensation of gas and electricity to the public for heat, light, power, and other uses, is a utility subject to Commission jurisdiction.¹

KRS 278.042 requires the Commission to ensure that each electric utility constructs and maintains its plant and facilities in accordance with accepted engineering practices as set forth in the Commission's administrative regulations and orders and in the most recent edition of the National Electrical Safety Code ("NESC").

KRS 278.030 requires every utility to furnish adequate, efficient, and reasonable service. KRS 278.260 permits the Commission, upon its own motion, to investigate any act or practice of a utility that affects or is related to the service of a utility. KRS 278.280(1) further permits the Commission, after conducting such investigation and finding that a practice is unreasonable, unsafe, improper, or inadequate to determine the reasonable, safe, proper, or adequate practice or methods to be observed and to fix same by Order.

__

¹ KRS 278.010(3)(a).

Pursuant to 278.280(2), which directs the Commission to prescribe rules and regulations for the performance of services by utilities, the Commission has promulgated Administrative Regulation 807 KAR 5:006, Section 25, which requires all utilities to adopt and execute a safety program. 807 KAR 5:006, Section 25(1) requires each utility to establish a safety manual with written guidelines for safe working practices and procedures to be followed by utility employees. Here, LG&E has adopted the LG&E Health and Safety Manual.

Commission Staff submitted to the Commission an Accident Investigation Staff Report ("Report") regarding this incident, which is attached to this Order as the Appendix. The Report alleges that on May 23, 2013, Seneca Newton, a LG&E employee, sustained injuries while replacing a 480-volt line in the underground network system at 719 West Jefferson Street in Louisville, Kentucky. The work crew at the job site included crew leader Robert Yates, victim Seneca Newton, Matt Bewley, and Scott Underwood. Preceding the incident, Mr. Newton was attempting to connect new energized secondary conductors. Mr. Newton was working on multiple energized conductors at the same time, and when the conductors were connected, an arc occurred, causing burns to Mr. Newton's right forearm. Mr. Newton admitted that he was not wearing his sleeves down and buttoned at the time of the incident.²

The access grate to the underground vault at the incident site was also not secured to prevent unauthorized entry, and the access ladder was not made of non-conductive material.

-2-

² See Attachment A to the Report, Seneca Newton's written statement.

Based on Commission Staff's investigation of the incident as set forth in the Report, the information provided by LG&E in its seven-day summary report (Attachment A to the Report), Commission Staff alleges that LG&E has violated multiple provisions of the NESC and of its safety manual. These violations are identified as follows:

- 1. Failure to properly phase the conductors prior to connecting the two conductors.
 - a. NESC, Part 3, Section 31, Rule 313.A.3 General Requirements applying to Underground Lines Tests When considered necessary, lines and equipment shall be subjected to practical tests to determine required maintenance.
 - b. NESC, Part 4, Section 42, Rule 420.C.4 General Rules for Employees Safeguarding Oneself and Others Employees who work on or in the vicinity of energized lines shall consider all of the effects of their actions, taking into account their own safety as well as the safety of other employees on the job site, or on some other part of the affected electric system, the property of others, and the public in general.
 - c. LG&E Health & Safety Manual, A.2.1 (Individual Responsibility) General Rules Individual Responsibility It is the responsibility of each employee to perform assigned duties to assure:
 - a. Safety to himself or herself.
 - b. Safety to fellow employees.
 - c. Protection of the public.
 - d. Protection of company property
 - d. LG&E Health & Safety Manual, E.8.6 Underground Residential Distribution Entering Underground Structures Before any work is done on a cable, it shall be identified by an approved method. If there is any doubt as to the identification, work shall not be started until checked and identified by a qualified employee.
- 2. Failure to work on only one energized conductor at a time.
 - a. LG&E Health & Safety Manual, E.5.7 Underground Residential Distribution Work on Energized Equipment –

URD – Only one energized secondary or service conductor shall be worked on at any one time, and protective devices shall be used to insulate or isolate it from all others.

- b. LG&E Health & Safety Manual, E.9.7 Underground Residential Distribution Work on Energized Cables, Manholes or Vaults Immediately after each conductor of an energized cable less than 600 volts is cut in two, the ends shall be insulated before another conductor is cut. During the course of the work, only one insulated conductor shall be worked at any one time.
- 3. Failure to lock access grate to utility vault.

NESC, Part 3, Section 32, Rule 323.E.3 – Underground Conduit System – Vault and Utility Tunnel Access – Where accessible to the public, access doors to utility tunnels and vaults shall be locked unless qualified persons are in attendance to restrict entry by unqualified persons. When vaults and utility tunnels contain exposed live parts, prominent safety signs shall be visibly posted before entering the vault.

4. Failure to button sleeves while performing work on energized underground cables.

LG&E Health & Safety Manual, E.5.8 – Underground Residential Distribution – Work on Energized Equipment – URD – An approved shirt or coveralls, with full-length sleeves rolled down and cuffs buttoned, shall be worn when work is performed on any energized UG cable or apparatus.

5. Failure to use an approved nonconductive ladder to gain access to the vault.

LG&E Health & Safety Manual, E.8.4 – Underground Residential Distribution – Entering Underground Structures – An approved nonconductive straight ladder shall always be used in entering or leaving a manhole or vault. Climbing into or out of manholes by stepping on cables or hangers is forbidden.

Based on its review of the Report and being otherwise sufficiently advised, the Commission finds that prima facie evidence exists that LG&E has failed to comply with

KRS 278.042, the most recent edition of the National Electrical Safety Code, and LG&E's Safety Manual. We further find that a formal investigation into the incident that is the subject matter of the Report should be conducted and that this investigation should also examine the adequacy, safety, and reasonableness of LG&E's practices related to the construction, installation, and repair of electric facilities.

The Commission, on its own motion, HEREBY ORDERS that:

- LG&E shall submit to the Commission, within 20 days of the date of this
 Order, a written response to the allegations contained in the Report.
- 2. LG&E shall appear on Wednesday, January 29, 2014, at 10:00 a.m. Eastern Standard Time, in Hearing Room 1 of the Commission's offices at 211 Sower Boulevard, Frankfort, Kentucky, for the purpose of presenting evidence concerning the alleged violations of KRS 278.042, from the most recent edition of the National Electrical Safety Code, LG&E's Safety Manual, and showing cause why it should not be subject to the penalties prescribed in KRS 278.990(1) for these alleged violations.
- 3. At the scheduled hearing in this matter, LG&E shall also present evidence on the adequacy, safety, and reasonableness of its practices related to the construction, installation, and repair of electric facilities as they relate to the facts of this case and whether such practices require revision as related to this incident.
 - 4. The January 29, 2014 hearing shall be recorded by videotape only.
 - 5. The Report in Appendix A is made a part of the record in this case.
- 6. Any requests for an informal conference with Commission Staff shall be set forth in writing and filed with the Commission within 20 days of the date of this Order.

By the Commission

ENTERED

OCT 24 2013

KENTUCKY PUBLIC SERVICE COMMISSION

ATTEST:

Executive Director

APPENDIX

APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE COMMISSION IN CASE NO. 2013-00373 DATED OCT 2 4 2013

Steven L. Beshear Governor

Leonard K. Peters Secretary Energy and Environment Cabinet



Commonwealth of Kentucky
Public Service Commission

211 Sower Blvd. P.O. Box 615 Frankfort, Kentucky 40602-0615 Telephone: (502) 564-3940 Fax: (502) 564-3460 psc.ky.gov David L. Armstrong Chairman

James W. Gardner Vice Chairman

> Charles Borders Commissioner

ACCIDENT INVESTIGATION STAFF REPORT

Report Date: August 13, 2013


Accident Date: May 23, 2013

Serving Utility: Louisville Gas and Electric

Accident Location: 719 West Jefferson Street, Louisville, Kentucky

Accident Victims: Seneca Newton

PSC Investigator: Steve Kingsolver







Kentucky Public Service Commission

Electric Utility Personal Injury Incident Report

Utility:

Louisville Gas and Electric (LG&E)

Reported By:

Ken Sheridan

Director of Operations and Security

Incident Occurred:

Approximately 12:39PM, May 23, 2013

Utility Discovered:

Approximately 12:39PM, May 23, 2013

Utility Discovered Treatment to the victim: Approximately 4:25PM, May 23, 2013

PSC Notified:

Approximately 4:30PM,

May 23, 2013

PSC Investigated:

9:00 AM, May 24, 2013

Report Received:

May 30, 2013

Incident Location:

719 West Jefferson Street

Louisville, Jefferson County, Kentucky

Incident Description:

This accident took place on May 23, 2013 at approximately 12:39 PM at 719 West Jefferson Street, Louisville, Kentucky. The victim, Seneca Newton, was working as a crew member on a crew that was in the process of replacing secondary conductors, 480 Volts, between two vaults that are part of the LG&E underground network system. The conductor being replaced had to pass through two manholes between the two vaults. The conductors were in place and had been energized from one of the vaults through the two manholes and into the vault where this accident happened. In the LG&E underground network system there are multiple sources feeding into a set of underground secondary conductors. The victim was in the process of connecting the new energized secondary conductors to a second source that would also be feeding the new secondary conductors. There is a process called phasing that will determine which conductors can and cannot be connected together. This process was not completed by the victim before he attempted to connect two of the conductors together. This action created an arc that caused burns to the victim's right forearm. The victim admits he did not have his sleeves down and buttoned as required by the LG&E safety manual. During my accident site visit it was noticed that the access grate to the below ground vault where this accident took place was not secured to prevent untrained persons from entering the vault as required by the National Electrical safety Code. Also during this accident site visit it was noticed that the access ladder used to gain entry into this vault was not made of non-conductive material as required by the LG&E Safety Manual.

Employer: Name: Address: Victim: 6611 Fernbush Drive LG&E Seneca Newton Louisville, Kentucky 40228

Position Employer: Witnesses: Name: Matt Bewley Network Technician B LG&E LG&E Scott Underwood Network technician C

Employee at job site but did not witness accident:

Position Name: Employer: Lead Network Technician LG&E Robert Yates (Employee in Charge of this Job Site)

Note: Statements from the 4 employees listed above are made part of the Utility Summary Report.

Information From: Name: Position: Employer: Director of Operations and Security LG&E Ken Sheridan Keith McBride LG&E/KU Investigator LG&E LG&E Bill Harper Group Leader

Temp & Weather: 70-75 Clear and Dry

FINDINGS:

It is the investigator's opinion that LG&E did not meet or exceed the following requirements set forth in the Commission Regulations, the National Electrical Safety Code, and the LG&E Safety Manual.

RELEVANT CODES, STATUTES, REGULATIONS, OR SAFETY MANUAL ISSUES THAT ARE PERTINENT TO THE INVESTIGATION

278.042 Service adequacy and safety standards for electric utilities **National Electrical Safety Code**

- (1) For the purposes of this section, "NESC" means the National Electrical Safety Code as published by the Institute of Electrical and Electronics Engineers, Inc.
- (2) Except as otherwise provided by law, the commission shall, in enforcing service adequacy and safety standards for electric utilities, ensure that each electric utility constructs and maintains its plant and facilities in accordance with accepted engineering practices as set forth in the commission's administrative regulations and orders and in the most recent edition of the NESC.

Effective: June 24, 2003

History: Created 2003 Ky. Acts Ch. 84, sec. 1, Effective June 24, 2003.

2012 National Electric Safety Code:

See 2012 NESC Code to view each rule in its entirety.

National Electrical Safety Code

Part 3: Safety Rules for Underground Lines

Section 31: General Requirements applying to Underground Lines

313: Inspection and Tests of Lines and Equipment

A: Tests

3: When considered necessary, lines and equipment shall be subjected to practical tests to determine required maintenance.

(P-234)

National Electrical Safety Code

Part 3: Safety Rules for Underground Lines **Section 32:** Underground Conduit System **323:** Manholes, Hand holes, and Vaults

E: Vault and Utility Tunnel Access

3. Where accessible to the public, access doors to utility tunnels and vaults shall be locked unless qualified persons are in attendance to restrict entry by unqualified persons. When vaults and utility tunnels contain exposed live parts, prominent safety signs shall be visibly posted before entering the vault.

(P-241)

National Electrical Safety Code

Part 4: Work Rules for the Operation of Electric Supply and Communication Lines and Equipment

Section 42: General Rules for Employees

420: General

C: Safeguarding Oneself and Others

4: Employees who work on or in the vicinity of energized lines shall consider all of the effects of their actions, taking into account their own safety as well as the safety of other employees on the job site, or on some other past of the affected electric system, the property of others, and the public in general.

(P-269)

807 KAR 5:006. General rules.

RELATES TO: KRS 65.810, 74, 96.934, 220.510, 278, 49 C.F.R. Part 192, 49 U.S.C. 60105 STATUTORY AUTHORITY: KRS 278.230, 278.280(2), 49 C.F.R. 192

NECESSITY, FUNCTION, AND CONFORMITY: KRS 278.230(3) requires every utility to file with the commission reports, schedules, and other information that the commission requires. KRS 278.280(2) requires the commission to promulgate an administrative regulation for the performance of a service or the furnishing of a commodity by a utility. This administrative regulation establishes requirements that apply to electric, gas, water, sewage, and telephone utilities.

807 KAR 5:006 General Rules Section 24: Safety Program

Section 24: Safety Program: Each utility shall adopt and execute a safety program, appropriate to the size and type of its operations. At a minimum, the safety program shall:

- (1) Establish a safety manual with written guidelines for safe working practices and procedures to be followed by utility employees.
- (2) Instruct employees in safe methods of performing their work.
- (3) Instruct employees who, in the course of their work, are subject to the hazard of electrical shock, asphyxiation or drowning, in accepted methods of artificial respiration.

LG&E Safety Manual

(May 23, 2013 Accident) (Victim: Newton)

See LG&E Safety Manual to view each rule in its entirety.

LG&E Safety Manual

A. General Rules

A.2 Individual Responsibility

A.2.1 It is the responsibility of each employee to perform assigned duties to assure:

- a. Safety to himself or herself.
- b. Safety to fellow employees.
- c. Protection of the public.
- d. Protection of company property

(P-25)

LG&E Safety Manual

E. Underground Residential DistributionE.5 Work on Energized Equipment — URD

E.5.7 Only one energized secondary or service conductor shall be worked on at any one time, and protective devices shall be used to insulate or isolate it from all others. **(P-126)**

LG&E Safety Manual

E. Underground Residential Distribution

E.5 Work on Energized Equipment — URD

E.5.8 An approved shirt or coveralls, with full-length sleeves rolled down and cuffs buttoned, shall be worn when work is performed on any energized UG cable or apparatus. **(P-126)**

LG&E Safety Manual

E. Underground Residential Distribution

E.8 Entering Underground Structures

E.8.4 An approved nonconductive straight ladder shall always be used in entering or leaving a manhole or vault. Climbing into or out of manholes by stepping on cables or hangers is forbidden. **(P-130)**

LG&E Safety Manual

E. Underground Residential Distribution

E.8 Entering Underground Structures

E.8.6 Before any work is done on a cable, it shall be identified by an approved method. If there is any doubt as to the identification, work shall not be started until checked and identified by a qualified employee.

(P-130)

LG&E Safety Manual

E. Underground Residential Distribution
E.9 Work on Energized Cables, Manholes or Vaults

E.9.7 Immediately after each conductor of an energized cable less than 600 volts is cut in two, the ends shall be insulated before another conductor is cut. During the course of the work, only one insulated conductor shall be worked at any one time. **(P-130)**

Recommendation:

Information on Completed Job Briefing Forms: Insure that all signatures and employee numbers are legible. (Possibly print name and sign)

Investigated By:	Name:	Company:
mreougated by.	i tuille:	<u> </u>

Signed: The Kongaluer

Date: 8-/3-/3

Attachments: A. Utility Incident Report

B. KPSC Photographs of Incident Site C. KPSC Map of Accident Location

Attachment A	
Utility Incident Report	



May 29, 2013

Mr. Etic Bowman Kentucky Public Service Commission 211 Sower Blvd. P.O. Box 615 Frankfort, KY 40602

Re:

Secondary Flash Burn

Date of Incident: May 23, 2013

Dear Mr. Bowman:

I am forwarding the enclosed Investigation Report prepared by Keith McBride regarding the injury of LG&E employee Seneca Newton that occurred in Jefferson County, Kentucky on Thursday, May 23, 2013. Louisville Gas & Electric Company is providing this report to the KPSC in accordance with the applicable seven-day reporting requirement. Please return a file stamped copy of the report in the envelope provided.

Should you need additional information concerning this incident, please contact me at (502) 627-3203 so I can direct your request to the appropriate person.

Singerely,

Jay/Warren

JW/kcg

Enclosures:

- 1) Area print
- 2) Utility photographs
- 3) Job briefing form
- 4) Written statements
- 5) Training excerpts

RECEIVED

MAY 8 0 2013

PUBLIC SERVICE COMMISSION

LG&E and KU Energy, LLC Corporate Law 220 W. Main Street Louisville, Kentucky 40202 www.lge-ku.com

Jay Warren Senior Corporate Attorney T 502-627-3203 F 502-627-3367 Jay.Warren @lge-ku.com

REVIEWED 13

INVESTIGATION REPORT

Secondary Flash Burn / LG&E Employee 13-ED-E-012

Type of Report Number

Keith McBride May 23, 2013

Investigator Date of Incident

Location: 719 West Jefferson Street

Louisville, Jefferson County, Kentucky, 40203

Incident Summary

On May 23, 2013 at approximately 12:39 P.M. Seneca Newton, LG&E-KU Network Technician-A was making a connection on a 480 volt line in a vault in front of 719 West Jefferson between 7th Street and 8th Street on the north side.

An arc occurred and Mr. Newton received a flash burn to his right forearm.

Ken Sheridan, Director of Operations and Security notified the Kentucky Public Service Commission (KPSC) of the incident.

Incident Investigation

On May 23, 2013 at approximately 12:39 P.M. Seneca Newton, LG&E-KU Network Technician-A was making a connection on a 480 volt line in a vault in front of 719 West Jefferson between 7th Street and 8th Street on the north side.

While making the 480 volt connection, an arc occurred and Mr. Newton received a flash burn to his right forearm. Mr. Newton was taken to the hospital by an LG&E Team Leader where he received treatment.

On May 23, 2013 LG&E Network crews were replacing a 480 volt line because several days prior, voltage was detected on the outside of the insulation. The crews opened up the 480 volt line in the vault in front of 719 West Jefferson in preparation of replacing a section of the 480 volt line west of the vault near 8th Street.

Once the sections of conductors were replaced, Mr. Newton started making the 480 volt connection while energized. Mr. Newton installed a line limiter on one conductor and when Mr. Newton attempted to make the second connection on that phase, an arc occurred.

Investigation found that Mr. Newton was relying on markings placed on the cables and did not phase the conductors.

It appears that Mr. Newton bucked phases on this 480 volt line. Mr. Newton received burns to his right forearm and was taken to the hospital where he received treatment and was released that same day.

Injured Employee: Seneca Newton, Network Technician-A 6611 Fernbush Drive Louisville, Kentucky 40228 DOB: March 21, 1985


Robert Yates, Lead Network Technician / Not in vault Matt Bewley, Network Technician-B / Co-worker Scott Underwood, Network Technician-C / Co-worker


• Temperature: 70 − 75 degrees / clear


• Secondary glove testing expiration date: July 5, 2013


• Leather protectors used


DATE OF REPORT: May 29, 2013 END OF REPORT











































Pre-job briefing

Date 5-23-13		84	SE
Location 7th + Jefferson			PPL company
Circuit # 1334, 1336 Voltage 13.8	KV Circuit on "One-Shot" [
Conducted by Robert Yates	Foreman/person in ch	narge <u>Robert</u>	Yates
Nearest medical facility Lowersity			2)627-3366
Part I — Provide work overview discussed	I with the crew:		911
Isolate old section of	480 V ties and	pull out. I	nstall a
new sets of 500 mcm the vault. Phase in car			e ana in
THE VAUTY . FTASE TH CAR	THE MITTER CONTRACTION	9	
Part II — List recognized hazards and pre	ventions discussed with the ci	rew:	
wear and use all proper	PPE. Observe al	Il hazards wi	th the job
and around the jobsite		I THEAT OF THE	'''-'-'-'-'-
and acound the Jobsite			
			<u></u>
Discussion topic guide (check all that app	7		
☑Work procedures involved	☑ Cover-up i		
☑ Bucket or line truck placement	Assignme	ent of work tasks	
☑Material handling and rigging	☑ Traffic cor	ntrol requirements	
Special precautions needed	Public saf	ety precautions	• ,
Energy source controls (cut-outs, switches	. -	ates (marked/unmarked	Ď
grounds, generator backfeed, "open points		ental issues	₹ -
			÷.
Grounding (when necessary)		ther work groups in area	
Personal protective equipment (PPE)	· · · · · · · · · · · · · · · · · · ·	ś that may change durin	ig the day
Observer responsibilities	✓ Confined-	space entry procedures	,
Interruptions and distractions	☑ Minimum	approach distance	
Echo protocol	☐ Excavation	n and trench hazards	
Additional comments and suggestions:			

Each of the following crew members has been i	ncluded in this discussion involvin	g the potential risks of th	e works at this
ocation and understands the necessary precau			
	loyee # Signat <u>ur</u> e		Employee #
		X	
1 Comment 10	1928_ >=		26575
114/10/16/2	•		
IIII WINXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Loca Sil	1 2	27253
- West Control -		/	
			
		· · · · · · · · · · · · · · · · · · ·	

poluso tram

	.
digs yadow Cable to the west, histolled fusellnt	1
= Un courced the black place as both of der	100
Crimps due Millers and getergun ? torch 3	1 V 285V
Opened Sout went down sattered	
to make The Secondary cable hat again.	
thou of mater of slid not bound)
157/7)	
tege there (abbs and covered the banded	
maked both sides of the cable with place	
Me soft served and the Man	//
Reconsided Seardery Cobes to remove	
Leconsoft Holds Alelds Ard there of	
Sone con I would in manhole	-/
2017 yp (ones Thodard Sighs	-
Site back to the manner of the Fast	
Sets at Stordery able Anihal and moved job	
Somera worked the whole we pulled a	
while senses got in the bole	
Set up some Tripud 3.5.900 Snewed diver.	-
Lebot parturned jak briceing and discurring	•
Allthu dat 300 street	
a time to the second that the state of the desire is a single production of the second contract of the second cont	
Magnessian in the control of the property defection from a property of the control of the contro	

	 		ma makerand treatises, the Prince		<u></u>	والمعادية فيستوجع والأواجع والمعاددة الموادة	American Services (Services Services Services Services Services Services Services Services Services Services S Services Services	والموال محرش
	When	tripped tried	to make	ther cub - conne	le to	make.	Connection (SUC	S
	Fired	v2.	and the mental parties after the					
710	1		*		-111			
, ,		A. A	and the second second second second	(a) \$4 (-1) (a) (-1) (-1) (-1) (-1) (-1) (-1) (-1) (-1	+		and the second s	-137-4- 137
*	o piece de la completa del la completa de la completa del la completa de la compl	سنا مه ساوس شده در پیش شاه در سازه در آن	er best kan berefin op in sambrest til der en et sterne en er en er En er en er en en er en e	والمراوة والمراجعة والمراوة والمراجعة والمراجع	e announce in Europe des des des eus au par	u kipinika kipinini manaka manaka y	ه الله الله الله الله الله الله الله ال	
		پيرودونه، نج مولسيدنده سنده وليه مذه	स्थानं क्षांत्राच्या है हुन क्षेत्रस्थात्त्राची है । यह नहस्थान	بالمحسسة بنواع مرجو المراسية تدويها وعطيتها	غالاه والمناهدة والمناولين والمناولين والمناولين	ger fil befor med frieder i de Kriegerier en de enem	فالبرنية فللمبرغ الربية أدستك بالمديق فوقاه	و ه در و همه
	وق تستيامة القلسلي برج نهير تبهرة	and the first death to the control of word 1911 and 250	الما وهو المراكبة المواقعة والمواقعة المواقعة المواقعة المواقعة المواقعة المواقعة المواقعة المواقعة المواقعة ا	والمرابط والمهارية المساورة المرابط والمرابط والمرابط المرابط	المراجعة الم	epister of the graph principles	ng ngagin ngganggab di masari 14 ligun stari	
grand a la comi n frakting pala di ti	end in minimum propriet of the contract	gant i ng Palatiga ta patawa Palatinan ing	Alexanderioris de distribution programme	a nite away mini kangana in ina <u>mana kana kana ka</u> P	Karatania da PAPAN dinggari ng menadi afasi a	engan kalendaryang di mengangkan lan	ە « ئەنىز ئەم چەلىلىلىك سەينىيىنىدىدىدى بىلىرىدى ش	********
,	ajin an newij ve vin nimere eja.	; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	أه مناه المُنْ عَيْمَ مِنْهُ فَيْمَا لَا لِمَا الْمُعَالِّمَ الْمُعَالِّمَةِ الْمُعَالِّمُ الْمُعَالِمُ فَالْ			a. Afarana y paginda ama	منته غفر بعدم والمرابع أعموه والمراز والمدار والمراز المراز	
i sanita i i i i i i i i i i i i i i i i i i	<u> </u>		yd i sawe girkin, mi yg am galle est y a ameri n.	ومستومع مفتر فيره المتحدث والمتحدد والمتحدد		وهراهم موجعت المتحاجم مقارمها	منځه پهرنهمورو و پهنه داو تا تا تا توفخترين. او	-11-p-2
			personalismi e directifus applicatifus in destruit par B	*	يا. د در در در در در دور هاي و دور دور دور دور دور دور دور دور دور د	itaryyerini maa makima.	والمتحققة والمتحققة والمتحدد المتحدد والمتحدد والمتحددة	
		ورياد ماده دريده وجادية ومرادية و	Parkyja v Rijsopa zajana jak rajev omo	والمعارفة والمناكي ومدومه ويسويون وواما الم	مهار فدوه دستان بيسارفية مياسين	وودوماني بويولينسٽ، و	4 ************************************	, um e ()
		, danis urus filos presidente de la constitución de la cons :	RD N. B. William of Addison & Machine South Street			et dage and western the see		diringa arma i
	ar ain maanan astri waa maa		nije il alt mie Produzija krajija distributurija i i sama dis	merjen sambleme en		er Transfer occudenter	i landinida in in in managan	amelik tok a r
	بينجيك شند واجلي وينجم	Sanding Said nos should at 1976	t grupcy o sometiologic copie greature made och				المطاول معاومه حواست حراطا كالويداء سيجيدي	Att of the Section
		تتنصرنهم ويردوا والربي ويتاو فطر للماسين	OPPORTUGE OF STATE OF THE PROPERTY OF THE PROP	ngere kana madia sing sacramanan kangga k	a de la companya de l	mannénsyséppenéps vene	والمواقعة والمداوية والمتحددة والمتحدد والمتحدد والمتحدد والمتحدد والمتحدد والمتحدد والمتحدد والمتحدد والمتحدد	به نازه بندنه
The second section of the second section sec		e garan sansiyan yanay di asmany	rengaziwych w nazwięczneg i opie zwasto w	ng madi mana ayan ayan angan ang	ويسائل وجوج هيد حصوب والمساد	والراوة أسمح فإن بيانية وفاس مدس	aan gelaligaa dhiiga gaadh dhiistoo dhi	
			وربية بدريين مولها لا الريازية بها يا مطالة عالم المجاب	ه هنشه هفاه د شهمه کار به در هری هیگ به ماون نم	ديندر از ده د ه در بههها و جينيت آهيست د	ويورغوانه معدده يمودنى دجانه بالمعسدة ثا	ing anjula di manananan mang di dinang papagan sa sa	
**************************************	ender and desired the second s	tamiyan kili ingani minaki matamah K	स्तानी सम्बद्धाना है राज्यां दश्चान सम्बद्धाना निर्मा पूर्वकरण है पर हत्तुव	فسيميها فالهدمية فليفاع أغري يهافله أداده الانتخاص	د به مدن أب الأول به مدن أب الله الله الله الله الله الله الله الل	بأؤ ووسلا يونيوناها متحان المحاد	era ağınısının de de dirilik isine yazılmışı sanışı	
		يون و دونورسانويون المواهد المعدد المواهد المعدد المواهد المواهد المواهد المواهد المواهد المعدد المواهد المواهد المواهد المواهد	ng gran, siya firasa manalishi siya na dawa .	ranadikkiaina jaironja rokusaji ailija etki k	a per communicación de desperador y siculo.	eniarioriotalaja maranga.	er agus por a goderním ser Province de mesos en A	مه عبوية
11								

Park E-Z Vault Book Poster YATES - Arrived at the jobsite around 8:15 am - Wrote out a job briefing and had a 10 min discussion with the crew about the job. Crew included Yates, Newton, Bewley, and Underwood And The Man Man We want over the job which included de-energizing the 480v tie between Park E-z and the Juvenile Vault. Cutting out and replacing a section of cable, - Discussed the hazards involved, air testing manholes and vaults, using all required PPE and testing equipment. Set up jobsite with cones and signs. - Opened Juvenile vault and the manhole across the street from Juvenile vault. - Installed 2 new sets of 500 mcm secondary from the manhale to the vault. - De-energized the 480 v tie between vaults by culting cables in each vault. - Tested cables in 2 manholes to verify cables were de-energized.
- After testing was complete we removed burndy molds and crimped the dead cable back together. · Mike Byrum's crew re-energized the 2 sets of cable at the Juvenile Vault back to the Park E-z vault Seneral Scott, + Matt worked in the Vault and Yates was the top man. We talked about the proper steps to reconnecting the 2 sets back together. Senera verified with a wiggy that the cables had voltage both ways.

- I heard a bang and fire coming out of the vau	
- I yelled to see if everyone was fine but it was	2000
30 sec. before there was any response.	11.
- All 3 guys came out of the vault and seemed t	
- Fine and the second of the s	
- Seneca showed me his arm, which was burned, and	
called Neal Puris at 12: 42 pm to inform him ab	out the
Si tuation	a alan cinamina di malangan da sangan da
- Neal took Seneca to the University of Louisville +	
treatment	
- We completed the work shortly after the accident	
The same of the sa	a magnicular mental
	and the second second
The state of the s	I in it is in its owner and
The state of the s	. entransis quantitati de la compressa de la c
The property of the second sec	es augument and property and the second of the second or t
The state of the s	
The second secon	
The second secon	the state of the s
A PRINCE OF THE	And the state of t
The state of the s	annaham kada sina sananisya massilisian
The state of the s	Aller de le volument de la
The state of the s	a girin - Tim a girin - Timatan indikatan ing paganan d
	Tallina trace - the and relative desired strates of the first series and a
	ners with despite for the main resident of the transpose of the first terminal
	passite from the condition and the control of the condition of the conditi
The state of the s	The state of the s

	#**
(3)	
•	
**************************************	Scott UNDERWOOD
ين د را الله الله الله الله الله الله الله ا	- Arrived to job on Jefferson.
دو معادد مدون براه و دو معاود و معاود ما معاود و معاود	- Did jeb briefing and discussed jeb
مستسمه عاملهما ومشاره وفروسيوه	- Popped manhole ! I'd on Jefferson accross from
ب مين الدران المراز	Juvenille vault
والمراجعة	televices and a little and the same and the
ودموني ويومون وسنست المستناد	- Set up tripod and put up cones in
والمستحد والمستحد والمستحدد والمستحد والمستحدد والمستحد والمستحدد	isork & darea and the same state of the same sta
***************************************	- Soneca went into manhele and began to
international des sous des sous de la contraction	Shake ductingoing south to juvenille wants
1 h mariamente manages trabado de la francesa de la	- He pulled back out snake putting nule string
	in conduit and did the same for the
مه مسيد پيديد په در در کارن که کارن که کارن ميکوم مسيد په سيد پيديد په در	next duct
	- I helped pull of winch line to pull in
were your command representation of the state of the stat	new cable it is the state with the printer with
Dalaman and the state of the st	we pulled in 2 sets of soo copy
	Secondary All March Marc
	- we closed up manhale and went to
Dences Matt B	Pacistasy a vaultistic qui
- Me Me	went down into want to take the 1800
puminaminaminakanistanistanistanistanistanistanistanist	tie between Parkensy vault and Juvenille vault
ر يوم در دورين يې د دوري د د د د د د د د د د د د د د د د د د د	- we taped each side tof cable and cut it
a marayay in a marana a marayay a maray	and immediately put fingers ion' each end
grames sound the grame of the state of the s	- Once Sinisted we come out of vault
n na main naman manana pamana kalabat salah garan salah	- we set up and popped manhele infront
ي المعاددة ا	of Parkeasy vault.
	- Serieca and Matt went down to remove
matern grant mengensagensag pagagat tidi di Alfahinsag, positiana ay ba	old bees burney moles and make straight
	17560

- I worked the top of the hole for a	a and a state of the state of t
few minutes	. 4
- Then went and got an extra air monitor from	l .
Typene Dorsey to go back down into	A garden districted of the committee of the company
Packeasy woult to hang new racks for the	
1/80 v. Lie we was working in on	
- Then matt and senera came down while I	الوائد والمراجع والوائد والمراجع والمرا
was finishing up the racks	and procedure (and care of the continue of the care
- They began to check the cables with the	Na pakanangan mujagan bagam mpanan menangan
wigi	
- Robert to ld us that Mile Byrums are what	t a market in a subjective destroy security supplies of the subject of the subjec
made 2 My cables hot to us.	ite distribution of the section of t
- Senece and Matt started using the wight and I	1 1
was picking some stuff up off of the Sloor	راية المستقدية المستقد
- They asked me to bed help and hold a cable.	
- We made Sure both cables were not with.	1 1
the wigi is the same of the sa	والمستعددة
= we put fise limiter on my cable and slid tube	<u> </u>
- when we went to tap both cables together thats	
when the mexplosion occured with the	. ,
- millioning Covered back up both ends and came	الله والمعادلة في المناسعة
up out of raulting	ومسروا والمساورة المساورة والمساورة
Andrew	de suma una un commenta en en esperantista de mende en el composito de la composito de la composito de la comp
	الما غايا عاديات المساورة على المان المساورة على المان المساورة على المان المساورة على المان المان المان المان
The state of the s	!
	and the second of the second second second second second second second second
	1.

u	
	SENECA NEWTON
i i	-Arrived downtown around 8:30 MM
§.	- Went over job briefing
1	- Read tob briefing & signed it
1 ·	Pu Setup Tobsite, Cores, tripod, arrow board & sign
4	One crew is set up at juvenile roult and our crewis set up atminde
· · · · · · · · · · · · · · · · · · ·	Pulled workable 2 New sets of cable from manhole to vault
4.1	Put phase tape on New cable
1:3	Got out of manhole & closed it up
911	Got back in manhole be cause the crew wanted to phone & phase the cable
	Cut off phase tape and phone the cable out taget phases that the crow
*	Et + Com 1 10
11	Sot up at Park EZ vault Ctripod, somes, barricades,
11	West down in rout
	found two sets of cable, marked cable on each side with phase tape,
***************************************	once that was done we proceeded to cut the cable one atatime a
	put fingers on them.
	Got out of vault
	Walted on the othe crew to cut the cable Hinthe other vaut to
11	Kill the cable between Junevile vault & Park EZ vault
11	Went Set up at one manhole Infront of Park EZ vault
11	Found two sets of cable that we were working on, we cut the burney moles
E 1	at a time so nothing would be out of phase
	Firished the work in our manhole
l t	Got out of manhole
	Waited on other creu to finish up in the other manhole

en a conse per manager	once they were done, they moved to the Juvenile vault , we went don in the park EZ vault
	the other crew made I phase out of each set hot coming from the
1	Tuverila rault to the parkEZ vault.
*** * *** *** b** * *	So we hot 2 hot legs in the Park EZ rault, we had out PPE on I did not have my shirt buttoned on the sleeves, we found the hot legs with a voltage indicator so we know with which legs are hot.
	Both phases that we had were the black ones, one oneachset
1	On the phases we had, Just on the black ones we had to put
n gala serimanining (d.	fuse limiters on both phase, the reason why we had to is from
1	a previous fullure
and the second	Proceeded to put both black cables together and wedge that was
11	
	when we had the explosion and my forearm got flished
ammery and a second as	
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished
	when we had the explosion and my forearm got flished

USING ELECTRICAL TEST EQUIPMENT Glossary (continued)

Ohmmeter

A meter used to measure resistance (ohms).

Ohm's Law

The law that relates current, voltage, and resistance: voltage is equal to current times resistance (E = IR).

Parallel (in parallel)

Connections that provide alternate paths for current to follow.

Phase-to-phase line check * --

A check of power lines that is done by checking each individual line against every other line in the group.

PMMC (permanent magnet - moving coil) arrangment

A type of meter movement consisting of a coil of wire and a permanent magnet and activated by current flowing through the coil.

Resistance

The opposition offered by a body or substance to the passage of electric current.

Resistor

A component capable of providing resistance to the passage of current.

Series (in series)

An arrangement of the parts or elements in an electrical circuit in which the current passes through each element without branching off.

Shunt resistor

A resistor that joins two points in an electrical circuit so as to form a parallel or alternative path through which a portion of the current may pass.

USING LINE TEST EQUIPMENT

4. Application of Voltmeters (continued)

The recording voltmeters are left to record changes in voltage levels over a specific period of time. When the lineman returns to check the readings, he uses an indicating voltmeter as a final check to make sure that the recording voltmeters are accurate. Then, the readings on the recording voltmeters' paper charts are checked. (The action to be taken if the readings show a voltage problem is beyond the scope of this program.)

4.2 Using a Phasing Tool to "Phase Out a Corner"

A common use of a phasing tool is to measure the potential difference between sets of primary conductors to see if the phases match. This type of measurement is essential whenever two sets of primary conductors are to be connected without interrupting service to customers. The example described in this section shows how a phasing tool can be used to match two sets of three-phase primary conductors at a utility pole. This job is often referred to as "phasing out a corner." As shown in Figure 4-2, one set of three-phase primaries crosses over the top crossarms of the utility pole, and the other set terminates at the lower crossarms.




Figure 4-2. Two Sets of Three-Phase Primaries at a Utility Pole

USING LINE TEST EQUIPMENT 4. Application of Voltmeters (continued)

The conductors in this example are two three-phase primaries energized at 13.2 KV. The potential difference between any two phases in the same primary or between any two unmatched phases of different primaries is the full 13.2 KV. The potential difference between two matched phases is nearly zero. Matched phases with a potential difference near zero can be connected safely, but the connecting of two unmatched phases could result in a dangerous short circuit. Phases are often labeled on a pole. However, conditions may have changed since the labeling, so a phasing tool should be used to test the conductors before any connections are made.

Before a phasing tool is used in the field, it should be inspected to make sure that it is in good condition. Particular attention should be paid to the condition of the cable that connects the probes. If there are signs of cracking, chafing, or other indications of wear, the device may be unsafe to use.


The first step in using a phasing tool is to test it to make sure that it is working. Also, each phase of the two sets of primaries to be connected is tested to make sure that it is energized. First, the probes of the phasing tool are hooked between the first two conductors of the same set of primaries.

If the phasing tool is operating correctly, and if the two phases being tested are energized, the phasing tool should read the full potential difference of 13.2 KV. The procedure is then repeated by hooking the phasing tool between the first conductor and the third conductor of the same primary. If the phasing tool reads the full potential difference of 13.2 KV between these two conductors, then this first set of primaries is energized.


The procedure is then repeated for the conductors of the second set of primaries. If the phasing tool indicates a reading substantially less than 13.2 KV between any two conductors of the same primary, there may be a problem that will prevent the two sets of conductors from being matched and connected.


A	tta	Cr	1r	n	eı	T	B

KPSC Photographs of Incident Site





<u>#1</u>







<u>#3</u>







<u>#5</u>






<u>#7</u>






<u>#9</u>



,	A	I	ta	C	n	П	1	е	n	τ	C

KPSC Map of Accident Location



Ed Staton LG&E and KU Energy LLC 220 West Main Street Louisville, KENTUCKY 40202