



Mailing Address:
139 East Fourth Street
1303 Main
Cincinnati, Ohio 45202
o: 513-287-4320
f: 513-287-4385

VIA OVERNIGHT DELIVERY

RECEIVED

December 12, 2018

DEC 13 2018

Ms. Gwen R. Pinson
Executive Director
Kentucky Public Service Commission
211 Sower Blvd
Frankfort, KY 40601

PUBLIC SERVICE
COMMISSION

Re: **Case No. 2018- 00416**


In the Matter of an Application of Duke Energy Kentucky, Inc., For an Order Approving the Establishment of a Regulatory Asset

Dear Ms. Pinson:

Duke Energy Kentucky, Inc. hereby submits its *Application for an Order Approving the Establishment of a Regulatory Asset* pursuant to 807 KAR 5:001. The original application in paper medium and 10 copies will be mailed to the Commission via overnight delivery.

Please date-stamp the extra two copies of this letter and return to me in the enclosed envelope.

Respectfully submitted,



Rocco D'Ascenzo (92796)
Deputy General Counsel
Duke Energy Kentucky, Inc.
139 East Fourth Street, 1313 Main
Cincinnati, Ohio 45201-0960
Phone: (513) 287-4320
Fax: (513) 287-4385
Rocco.D'ascenzo@duke-energy.com
Counsel for Duke Energy Kentucky, Inc.

Enclosures: Rebecca Goodman

RECEIVED

DEC 13 2018

PUBLIC SERVICE
COMMISSION

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of an Application of Duke)
Energy Kentucky, Inc. For an Order) Case No. 2018- 00416
Approving The Establishment of a)
Regulatory Asset)

VERIFIED APPLICATION OF DUKE ENERGY KENTUCKY, INC.

To the Honorable Kentucky Public Service Commission:

Duke Energy Kentucky, Inc. (Duke Energy Kentucky or the Company) respectfully petitions the Kentucky Public Service Commission (Commission) for an accounting order permitting Duke Energy Kentucky to accumulate and defer for recovery in rate proceedings before the Commission expenses incurred to repair damage and restore service to its customers caused by severe ice and wind conditions from November 15, 2018, through November 18, 2018 (November Ice Storm). In support of this Application, Duke Energy Kentucky states as follows:

Introduction

1. Duke Energy Kentucky is an investor-owned utility engaged in the business of furnishing natural gas and electric services to various municipalities and unincorporated areas in Boone, Bracken, Campbell, Gallatin, Grant, Kenton, and Pendleton Counties in the Commonwealth of Kentucky.

2. Pursuant to 807 KAR 5:001, Section 14(2), Duke Energy Kentucky is a Kentucky corporation originally incorporated on March 20, 1901, in good standing, and a public utility as that term is defined in KRS 278.010(3), and, therefore, is subject to the Commission's jurisdiction.

3. Pursuant to 807 KAR 5:001, Section 14(1), Duke Energy Kentucky's business address is 139 East Fourth Street, Cincinnati, Ohio 45202. Duke Energy Kentucky's local office in Kentucky is Duke Energy Envision Center, 4580 Olympic Boulevard, Erlanger, Kentucky 41018.

4. Copies of all orders, pleadings and other communications related to this proceeding should be sent to:

Rocco O. D'Ascenzo
Deputy General Counsel
Duke Energy Kentucky, Inc.
139 E. 4th St., Cincinnati, OH 45202
Rocco.D'Ascenzo@duke-energy.com
KYfilings@duke-energy.com

5. Pursuant to KRS 278.220, the Commission is authorized to prescribe accounting to be kept by utilities subject to its jurisdiction. By Order dated January 31, 2002, in Case No. 2001-00092, the Commission required Duke Energy Kentucky to obtain Commission approval to establish any new regulatory assets.

6. The November Ice Storm struck Duke Energy Kentucky's service territory in mid-November 2018, causing damage to the Company's electric delivery system that necessitated significant restoration efforts and expenses. The November Ice Storm began on or about November 15, 2018, and brought a mix of freezing rain and snow that covered trees, utility lines, and the ground with layers of ice. The ice and winds brought widespread damage to Duke Energy Kentucky's electric delivery system including, but not limited to, down tree limbs, wires and poles, and other equipment damage. In terms of system impact, Duke Energy Kentucky documented approximately 26,482 sustained outages (greater than five minutes in length), and 1,127 total events, due to the damage

caused by the November Ice Storm. In total, approximately 29,474 Duke Energy Kentucky customers were without power due to the November Ice Storm.¹

7. Because of the timing of the storm in relation to the need for Duke Energy Kentucky to file and request deferral of these costs prior to the end of the calendar year, Duke Energy Kentucky does not have final numbers regarding the extent of the damage to its system. Contractor and vendor invoices remain outstanding as the storm occurred less than thirty days ago, and indeed the Company does not expect the final invoices to be submitted and processed for approximately ninety days. Despite the best and diligent efforts of Duke Energy Kentucky's employees, contractors, and colleagues from its parent utility in Ohio and its sister utilities in North and South Carolina, service could not be fully restored to 100% of Duke Energy Kentucky's territory until November 18, 2018.

8. Duke Energy Kentucky used its best available resources to monitor and respond to the November Ice Storm. Because this winter storm covered such a large footprint in the Midwest that impacted all regional utilities, Duke Energy Kentucky, along with its parent utility in Ohio and sister utility in Indiana, requested aid from its Carolina affiliates to assist in restoration efforts in the Midwest Service Area. Duke Energy customer call centers were alerted to anticipate increased call volume on anticipated outages as a result.

9. Duke Energy Kentucky and its parent utility, Duke Energy Ohio, Inc, (Duke Energy Ohio) coordinated their efforts and immediately began implementing their emergency plans to respond to the damage. With respect to the service territories of Duke Energy Kentucky and Duke Energy Ohio, the storm affected every part of the 3,000-

¹ Duke Energy Kentucky has 142,750 total electric customers.

square-mile service area in Northern Kentucky and Southwest Ohio. More than 1,200 Duke Energy employees and contractors responded to the storm by assessing damage, preparing material for the field, assigning jobs to crews, removing damaged vegetation, repairing down lines and equipment and providing support services. Duke Energy Kentucky and Duke Energy Ohio employed more than 300 call center employees to handle the call volume related to the initial outages on November 15th and 16th. Duke Energy Kentucky and Duke Energy Ohio worked together to retain approximately 350 employees and contractors from Duke Energy Carolinas to assist in the restoration effort for Kentucky and Ohio customers. Duke Energy Kentucky has tabulated a consolidated damage assessment for its Northern Kentucky service territory as depicted on Exhibit 1.

10. The estimated costs of restoration that Duke Energy Kentucky incurred due to the November Ice Storm are projected to significantly and materially exceed the Company's average annual storm-related costs. Duke Energy Kentucky presently has approximately \$1 million in base rates for major storm restoration. Prior to the occurrence of this November Ice Storm, Duke Energy Kentucky had already experienced major storm restoration expenses of \$719,000 for 2018. Duke Energy Kentucky estimates that its November Ice Storm-related expenses alone, most of which are operations and maintenance costs, will be approximately \$1.6 million. The current estimates for repair costs are attached hereto as Exhibit 2. These costs are based upon both actual and estimated costs incurred to date and reasonable estimates of contingencies.

11. Duke Energy Kentucky does not maintain property and casualty insurance that covers its distribution and transmission systems for damage caused by severe weather because of the cost of doing so. In fact, upon information and belief, such coverage has

not been available from general insurance carriers and has been specifically excluded from policies since the early 1990s. As a result, Duke Energy Kentucky has not and will not receive any insurance proceeds to offset the November Ice Storm damage expenses.

12. Duke Energy Kentucky asks the Commission for permission to record as a regulatory asset and defer for future recovery in appropriate accounts, the actual costs incurred due to the November Ice Storm in excess of major storm expense contained in base rates. The measures Duke Energy Kentucky took to restore service, and the costs related thereto, were reasonable and prudent and should therefore be recoverable as a necessary cost of providing service to Duke Energy Kentucky's customers. If approved, Duke Energy Kentucky will hold its deferred costs in Account No. 182.3, Other Regulatory Assets, until the Commission considers the method of recovery in a future rate proceeding.

13. The accounting treatment requested herein related to the November Ice Storm will only have a small impact on customers when the Commission subsequently approves amortization and rate recovery of the regulatory asset. For example, if in the next rate case, the Commission approves a five-year amortization of this regulatory asset to be included in revenue requirements, the overall impact on retail customers' monthly bills is expected to be significantly less than one percent (1%).

14. The Commission has exercised its discretion to approve a regulatory asset upon demonstration that the expenses to be deferred fall into one of four categories:

- (1) An extraordinary, nonrecurring expense which could not have reasonably been anticipated in the utility's planning;
- (2) An expense resulting from a statutory or administrative directive;
- (3) An expense in relation to an approved industry initiative; or

- (4) An extraordinary or nonrecurring expense that over time will result in a saving that fully offsets the cost.

The Commission has previously approved accounting treatment for such extraordinary storm-related events and permitted deferral and amortization of significant and extraordinary expenses to the extent such costs exceed the amount of storm-related costs contained in base rates.² Duke Energy Kentucky respectfully submits that the costs incurred because of the November Ice Storm undeniably qualify as such extraordinary non-recurring expenses and that such expenses could not have been reasonably anticipated in the utility's planning.

15. The Commission has also recognized the impact of a late-occurring major event storm as it relates to the utility's fiscal year operations and the timing constraint placed upon seeking accounting orders from the Commission. As a result, the Commission has stated that it would "allow jurisdictional utilities to record expenses for Major Event storms occurring in the fourth quarter of the fiscal year as a deferred asset for accounting purposes only, subject to the utility's filing of an application within 90 days of the occurrence of the Major Event storm seeking Commission approval for such authority."³ With this Application, Duke Energy Kentucky is both informing the Commission of the need to establish this deferred asset and is also providing the best

² See e.g. *In the Matter of: An Adjustment of the Electric Rates, Terms and Conditions of Kentucky Utilities Company*, Case No. 2003-00434, Order at 39-41 (June 30, 2004), finding Kentucky Utilities' proposal to defer and amortize significant ice storm related expenses as reasonable; *In the Matter of General Adjustment of Rates of East Kentucky Power Cooperative*, Case No. 2006-472 (Order)(December 7, 2007) Permitting amortization of forced outage expenses over three years due to the significance and extraordinary nature of the event; *In the Matter of an Application of Duke Energy Kentucky, Inc for An Order Approving the Establishment of a Regulatory Asset*, Case No. 2008-476, (Order at 4)(January 7, 2009) Permitting deferral of storm restoration costs associated with Hurricane Ike.

³ *In the Matter of: Application of Kentucky Power Company for an Order Approving Accounting Practices to Establish Regulatory Assets and Liabilities Related to the Extraordinary Expenses Incurred by Kentucky Power Company in Connection with the Two 2015 Major Storm Events*, (Ky. P.S.C. December 12, 2016).

available information at this time in order for the Commission to consider the Company's deferral request.

16. Consistent with Statements of Financial Standards No. 71 codified as Accounting Standards Codification (ASC) 980, granting such treatment in this case will allow Duke Energy Kentucky to make appropriate adjustments to its books of account for the regulatory asset and prevent Duke Energy Kentucky from having to record extraordinary storm costs as expenses on its books. To comply with ASC 980, Duke Energy Kentucky respectfully requests the Commission to state explicitly in its order that it is authorizing Duke Energy Kentucky to accumulate in a regulatory asset and defer the actual amounts up to \$1.6 million of extraordinary expenses Duke Energy Kentucky incurred to repair damage and restore service to customers following the November Ice Storm, in a regulatory asset in Account No. 182.3, Other Regulatory Assets.


17. If the Commission approves Duke Energy Kentucky's requested regulatory asset treatment of its November Ice Storm related expenses, Duke Energy Kentucky will make the following journal entries:

Debit	182.3	Other Regulatory Assets
Credit	58X	Distribution Operation Expense
	59X	Distribution Maintenance Expense
	9XX	Administrative & General Expense
	408	Payroll Taxes

WHEREFORE, Duke Energy Kentucky prays that the Commission issue an order granting authority to accumulate in a regulatory asset and defer for future recovery the actual amounts up to \$1.6 million of extraordinary expenses Duke Energy Kentucky incurred to repair damage and restore service to customers following the November Ice Storm and to apply the proposed accounting treatment to make appropriate adjustments on its books of account for the year ending December 31, 2018.

Respectfully submitted,

Duke Energy Kentucky, Inc.



Rocco O. D'Ascenzo (92796)

Deputy General Counsel

Duke Energy Kentucky, Inc.

139 East Fourth Street, 1303-Main

Cincinnati, Ohio 45201-0960

Phone: (513) 287-4320

Fax: (513) 287-4385

E-mail: Rocco.D'Ascenzo@duke-energy.com

CERTIFICATE OF SERVICE

This is to certify that a copy of the foregoing Application of Duke Energy Kentucky, Inc. has been served via electronic mail to the following party on this 12th day of December 2018.



Rocco O. D'Ascenzo

Rebecca W. Goodman
The Office of the Attorney General
Utility Intervention and Rate Division
700 Capital Ave., Ste 20
Frankfort, Kentucky 40601
Rebecca.Goodman@ky.gov

VERIFICATION

STATE OF OHIO)
) SS:
COUNTY OF HAMILTON)

The undersigned, Amy B. Spiller, being duly sworn, deposes and states as follows: that she is the President of Duke Energy Kentucky, Inc., that she has personal knowledge of the matters set forth in the foregoing, and that the information contained therein is true and correct to the best of her knowledge, information, and belief.



Amy B. Spiller, Affiant

Subscribed and sworn to before me by Amy B. Spiller on this 12th day of December 2018.



NOTARY PUBLIC

My Commission Expires: July 8, 2022



E. MINNA ROLFES-ADKINS
Notary Public, State of Ohio
My Commission Expires
July 8, 2022

Detail Report - Florence Office

Report Date:

Event Types: OUT, NON - 1068 Events

Date Range: 11/15/2018 6:00:11 AM to 11/19/2018 12:00:11 PM

12/5/2018 4:49:36 PM

Outage Management

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
1	8115091	Wilder-H9320590046	11/15/2018 11:45:06 AM	11/17/2018 10:28:00 AM	11/18/2018 12:00:00 PM	TXOH: CA14-237: 26899564	-	0	1	CMP	PP-H-On,Dmg-On	2	20 Equipment failure	Unselected	23 Found on Inspection	Florence	CMPL 2018-11-17 10:28:00 by CLWILLS RMK: CUSTOMER HAS POWER, SERVICE LINE TIED UP TO TREE MAKING SITUATION SAFE- ADVISED CUSTOMER REPAIRS NEEDED - L GROTHAUS 513-906-0133 - UPDATED AT 6:45PM
2	8107644	Villa-H9322430043	11/15/2018 6:08:22 AM	11/16/2018 11:12:00 AM	11/18/2018 12:00:00 PM	FOH: K95-721: 25998858	65T	61	54	CMP	PP-H-Out,Out-Dmg,Out,Pl O	1	03 Vegetation	LL Tree limb fails	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-16 11:12:00 by T95129 RMK: ROB MILLER 513 543 8745 BKT TRK ACCESS LG LIMBS ON NEUT/ 1/0 PRIM DOWN 1 SPAN K95-35 TO 36 SEC DOWN @ 75 BEECH -DISC SVC
3	8107809	White Tower-H9323040041	11/15/2018 6:18:53 AM	11/17/2018 5:21:33 PM	11/18/2018 12:00:00 PM	TXOH: 22K-646: 26878509	-	1	3	CMP	PP-H-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	25T FUSE BLOWN @ POLE# 22K-376E, (2) #8CU SPANS PRI & N DWN, POLE #S 22K-645E TO 22K-646E, MULTI SPICES REQ'D, 1 LIMB TO CLEAR, OH LINE CREW, TAPED AREA OFF FOR CAUTION -L GROTHAUS 513-906-0133 9:20AM 11/16/18 - GENERATOR IN USE BY CUST.
4	8107900	White Tower-H9323040043	11/15/2018 6:24:20 AM	11/16/2018 3:02:00 PM	11/18/2018 12:00:00 PM	FOH: 19K-485: 25988442	100T	25	68	CMP	Out-S-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	44 Replaced Fuse	Florence	100T FUSE BLOWN AT CORNER OF RICKEY LN & TAYLOR MILL RD. TAP FUSE THAT FEEDS RICKEY LANE POLE # (19K-458E) - ASSESSED TAP NO ISSUES FOUND - L GROTHAUS 513-906-0133 @ 8:48AM ON 11/16/18
5	8107940	White Tower-H9323040043	11/15/2018 6:27:48 AM	11/16/2018 9:49:00 AM	11/16/2018 10:00:00 AM	FOH: 19K-1002: 26046305	100T	73	96	CMP	PP-H-Out,Out-S-Out,Tree-PP,Out	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Limb	Florence	CMPL 2018-11-16 09:49:00 by T22400 RMK: TREE
6	8108124	Donaldson-H9320550042	11/15/2018 8:24:59 PM	11/17/2018 3:45:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-656: 26904909	-	0	0	CMP	Out-Dmg	1	28 Other Cause	Unselected	26 OK Arrival	Florence	CMPL 2018-11-17 15:45:00 by CMTURNE RMK: OK ARRVL. TWPP K105-565C AND K105-566C RMVD. FUSE IN K105-656C. ALL ON. NO OUTAGE.
7	8108161	Decoursey-H9322990041	11/17/2018 8:00:09 AM	11/17/2018 1:45:00 PM	11/17/2018 2:30:00 PM	TXOH: 11K-94: 26872294	-	3	1	CMP	Out-Dmg,Out	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-17 13:45:00 by WACASSO RMK: PING OFF-REQ 8125942-OFF as of 6:34AM 11/17/18 ZWYsins 513-458-3806. Tree down on lines in yard. R/ET 1/0AL SEC DOWN FROM K11-94 TO LIFT POLE. NEED TO STRAIGHT LIFT POLE/LENGHT SVC 1 CUST READY TO ENERGIZE. 1 CU
8	8108290	Augustine-H9320780041	11/15/2018 6:44:27 AM	11/16/2018 4:20:00 PM	11/16/2018 5:00:00 PM	FOH: K70-325: 25995551	65T	31	39	CMP	Equip-E-911-Out-Othr-O Equip-E-Out,PP-H-Tree-PP-Out,Tree-PP-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	44 Replaced Fuse	Covington	CMPL 2018-11-16 16:20:00 by T39767 RMK: 65T FUSE BLOWN @ POLE # K70-325. DWN PRI & TREE ON SEC B/W POLE # K70-333 & K70-335E. @ 271 LAKE ST & CORNER OF LAUREL - L GROTHAUS 513-906-0133
9	8108317	Augustine-H9320780046	11/15/2018 6:45:56 AM	11/16/2018 11:54:00 AM	11/18/2018 12:00:00 PM	FOH: K72-241: 25995625	65T	61	96	CMP	Out-Dmg,Out	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Covington	65T FUSE BLOWN AT 101 MORRIS AVE. LIMB ON LINE @ POLE # K72-240 (18 HOWARD DR), LIMB ON LINE @ POLE # K72-230C (102 BARRINGTON RD) ALSO OPEN 3 WIRE SEC 1 LEG DOWN #2CUWPS - L GROTHAUS 513-906-0133
10	8108326	White Tower-H9323040043	11/15/2018 6:46:40 AM	11/18/2018 2:09:10 PM		TXOH: 19K-412: 26877035	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	CUT IN THE CLEAR CUSTOMER NEEDS TO GET ELECTRICIAN
11	8108348	Empire-H9322890041	11/15/2018 6:47:52 AM	11/16/2018 1:32:00 PM	11/16/2018 2:30:00 PM	FOH: 36BN-583: 367132991	-	38	67	CMP	Equip-E-Tree-PH-Out,PH-H-Out,Out-Othr-O,Out	1	EA Weather	Unselected	17 Closed Switch	Florence	CMPL 2018-11-16 13:32:00 by T25446 RMK: NICK HAMILTON 513-240-8825. 1 SPAN 4CU PRIMARY/NEUTRAL BETWEEN POLE 36BN-570 & 36BN-576 LOCATE REAR LOT 9998 HAVEN HILL. LIMB ON SERVICE AT 9998. FUSE BLOWN 36BN-583 780 MT ZION RD
12	8108419	Crescent-H9320700045	11/15/2018 6:51:41 AM	11/17/2018 8:08:10 AM	11/18/2018 12:00:00 PM	TXOH: K92-129: 26915842	Retrofit 1/24/2014	4	4	CMP	PH-H-Tree-PH-Out,CC-H-Pt O-Othr-O-ED,Out,Pl O,Dmg-On	1	03 Vegetation	Unselected	18 Customer Trouble/No Outage	Florence	ROB MILLER 513 543 8745BKT TRK ACCESS 819 SUNGLOW-SEC/SVC DOWN- CUST ADVISED TO REPLACE DAMAGED SEC-DISCONNECT ROB MILLER 513 543 8745 819 SUNGLOW BKT TRK ACCESS SEC/SVC DOWN-CUST ADVISED TO REPLACE DAMAGED SEC-DISCONNECT
13	8108455	Augustine-H9320780046	11/15/2018 6:53:38 AM	11/15/2018 3:29:20 PM		TXOH: K72-219: 26912438	-	0	1	CMP	PH-H-On,Dmg-On	1	28 Other Cause	Unselected	26 OK Arrival	Covington	K GOETZ 859-404-1222 IN AND OK
14	8108485	Richwood-H9321990042	11/15/2018 6:55:15 AM	11/16/2018 4:50:00 PM	11/16/2018 5:30:00 PM	FOH: 35BN-333: 26078778	65T	38	92	CMP	Tree-PP-Out,Out-Dmg,Out	1	EA Weather	Unselected	17 Closed Switch	Florence	CMPL 2018-11-16 16:50:00 by T25446 RMK: 65T-JOE GROESCHEN 859 250 0319- LIMB ON 1 PH PRIM & NEU BETWEEN POLES 40BN-110C & 40BN-111C LOCATED AT 10604 KILARNEY - 2ND LIMB ON PRIM & NEU BETWEEN POLES 40BN-97 & 40BN-96 LOCATED BEHIND 10366 KILARNEY TAP FUS
15	8108859	Donaldson-H9320550042	11/15/2018 7:11:36 AM	11/16/2018 6:04:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-743: 26904474	-	11	5	CMP	PP-H-Out,PP-H-Out-O-On,PP-H-On,PH-H-Out,Out-Dmg	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-16 18:04:00 by T95129 RMK: #2 serv up perm r2e entrance cable

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
16	8108915	Donaldson-H9320550042	11/15/2018 7:13:14 AM	11/18/2018 9:49:00 AM	11/18/2018 12:00:00 PM	TXOH: K104-378: 26864422	-	0	1	CMP	Tree-PH-On,Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-18 09:49:00 by T23397 RMK: ROB MILLER 513 543 8745 R/ET SM LIMB ON SERVICE-KNOB & SEC PULLED AWAY FROM HOUSE-DISCONNECT @ P#K104-379 CUST NOTIFIED customer states that the limb is still on the limb - not a big limb but that she has no mean
17	8108950	Donaldson-H9320550041	11/15/2018 7:14:48 AM	11/18/2018 1:03:19 PM		TXOH: K105-529: 26904723	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	EA Weather	Unselected	18 Customer Trouble/No Outage	Florence	R/E Customer Notified ROB MILLER 513 543 8745 CUST SEC DAMAGED & KNOB PULLING OUT-SVC HANGING LOW W BROKE NEU CUST ADVISED REPAIRS NEEDED-DISCONNECT @ POLE K105-529 AREA TAPED OFF WILL NEED LADDER @ HOUSE TO DISC
18	8109096	Bellevue-H9321310044	11/15/2018 7:20:26 AM	11/16/2018 12:27:00 PM	11/18/2018 12:00:00 PM	TXUG: CAK-2051: 27173911	-	1	8	CMP	Out-Dmg,Out	1	28 Other Cause	Unselected	11 Checked Voltage/All OK	Florence	CMPL 2018-11-16 12:27:00 by T39767 RMK: R-ET J GROESCHEN 859 250 0319 TREE BRANCH LAYING ACROSS DEAD END POLE CA3-727 LOCATED BEHIND CHASE BANK 2 CUTOUTS OPEN AT CA3-726 ON CORNER- 2 CUTOUTS OPEN ON POLE CA3-630 ON RIVIERA
19	8109137	Buffington-H9320670045	11/15/2018 7:21:53 AM	11/17/2018 4:43:56 PM	11/18/2018 12:00:00 PM	TXOH: K117-311: 26907955	-	0	1	CMP	Obj-L-On,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	ROB MILLER 513 543 8745 ENGERIZED SERVICE ON GROUND-RE-SAG, 161 SERVICE KNOB PULLED FROM HOUSE CUST NEED TO REATTACH SEC TO HOUSE-DISCONNECT SERVICE REAR LOT ENG SERV ON GRND RESAG, 161 SERV KNOW PULLED CUST NEEDS TO REATTACH SEC-DISC POWER
20	8109196	Crescent-H9320700045	11/15/2018 6:56:16 AM	11/17/2018 9:59:00 AM	11/17/2018 10:45:00 PM	TXOH: K92-189: 26915688	Retrofit 2/3/2014	8	8	CMP	PH-H-Tree-PH-Out,PH-H-Out,Tree-PH-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-17 09:59:00 by T66296 RMK: ROB MILLER 513 543 8745BKT TRK ACCESS SVC DOWN @ POLE K92-187 AND HOUSE - RECONNECT NEED 75' 1/0 ALTX
21	8109441	Crescent-H9320700043	11/15/2018 7:33:26 AM	11/17/2018 4:05:00 PM	11/17/2020 5:30:00 PM	TXOH: K72-68: 26865015	-	0	0	CMP	Out-Dmg,Out	1	EA Weather	Unselected	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-17 16:05:00 by T74214 RMK: PING ON-REQ 8125994-ON as of 7:10AM 11/17/18 ZWysins 513-458-3806. LINE ACROSS ROAD - MANNING - 513-218-6533 - TROUBLE IS AT 306 BIRCHWOOD - 3" TREE ON 2ALTX SERVICE FROM POLE K72-328 TO HOUSE - CUST HAS POWER.
22	8109668	Buffington-H9320670045	11/15/2018 7:41:51 AM	11/17/2018 8:07:17 PM	11/18/2018 12:00:00 PM	TXOH: K105-426: 26904627	-	0	1	CMP	PP-H-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	M.ORTH 859-300-4794. REATTACH SECONDARY AT POLE KNK-5506. NEW RK-1. TRUCK ACCESSIBLE. M.ORTH 859-300-4794. REATTACH SECONDARY AT POLE KNK-5506. NEW RK-1. TRUCK ACCESSIBLE. RE-ATTACHED LIFT POLE AND MADE NEW CONNECTIONS
23	8109830	Florence-H9322410046	11/15/2018 7:47:26 AM	11/16/2018 4:19:37 PM	11/18/2018 12:00:00 PM	FOH: 31BN-259: 25990017	40T	7	5	CMP	PP-H-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	44 Replaced Fuse	Florence	JOE GROESCHEN 8592500319 - SECONDARY DOWN ON POLE 31BN-1176 AT LIONS CLUB-FUSE BLOWN ON POLE 32BN-730C- TAP FUSE BLOWN ON POLE 31BN-259
24	8109963	White Tower-H9323040041	11/15/2018 7:53:11 AM	11/17/2018 9:24:13 PM	11/18/2018 12:00:00 PM	TXOH: 22K-629: 26878461	-	0	1	CMP	Tree-PH-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	LARGE BROKEN LIMB OVER SERVICE, REAR PROP ALAN EAST 513-313-9220 TT COMPLETE
25	8109993	Villa-H9322430043	11/15/2018 7:53:57 AM	11/17/2018 10:31:00 AM	11/17/2018 11:00:00 AM	FOH: K96-235: 26097325	65T	3	7	CMP	Equip-E-Othr-O-On,PH-H-911-PF-Othr,Out-Dmg,Out	1	EA Weather	Unselected	44 Replaced Fuse	Florence	CMPL 2018-11-17 10:31:00 by T25446 RMK: ROB MILLER 513 543 8745 REAR LOT ACCESS FROM 3021 LEE LN 65T FUSE BLOWN @ POLE K96-235- NO OTHER DAMAGE
26	8110013	Constance-H9320420041	11/15/2018 7:54:48 AM	11/18/2018 11:18:14 AM	11/18/2018 12:00:00 PM	TXOH: 8BN-155: 26871724	-	1	3	CMP	Out-Dmg,Out	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	PING FAILED PING - REQ 8127930 - OFF as of 18:16 11/17/18 I25080 513-458-3792 ***Tri plex pulled off of secondary at pole# 5G-379C bucket access avail.
27	8110270	Buffington-H9320670045	11/15/2018 8:05:20 AM	11/17/2018 4:44:36 PM	11/18/2018 12:00:00 PM	TXOH: K117-317: 26907993	-	0	1	CMP	PH-H-On,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	ROB MILLER 513-543-8745REAR LOT SERV KNOB PULLED. SEC & SVC ON GRND ENERGIZED. CUST NEEDS TO REPLACE SEC-DISC POWER
28	8110366	Crescent-H9320700043	11/15/2018 8:09:07 AM	11/17/2018 8:11:10 PM	11/18/2018 12:00:00 PM	TXOH: K83-245: 26925739	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	MANNING - 513-218-6533 - REAR LOT - ENERGIZED 1/0ATLX LOW IN NEIGHBORS YARD FROM POLE K83-245 TO HOUSE - CUST NOTIFIED HE NEEDS ELECTRICIAN AND WILL LOSE POWER - NEEDS NEW SEC, WH AND RK1
29	8110485	Augustine-H9320780046	11/15/2018 7:53:01 AM	11/17/2018 1:34:35 PM	11/18/2018 12:00:00 PM	TXOH: K72-635: 26912119	-	2	4	CMP	PH-H-Out,Out-Dmg,Out,Othr-O-On	1	03 Vegetation	Unselected	20 Cut In/Reconnect at Pole	Covington	SEE EVENT 8109960. K GOETZ 849-404-1222. SERVICE PULLED FROM WH. CUSTOMER REPAIRS REQ'D. CUSTOMER NOTIFIED. REAR LOT POLE K72-635E. CHECK TRANSFORMER FUSE. 1/0ATLX SERVICE DOWN K GOETZ 849-404-1222. SERVICE PULLED FROM WH. CUSTOMER REPAIRS REQ'D. CUSTO
30	8110862	Florence-H9322410042	11/15/2018 8:26:57 AM	11/17/2018 8:37:29 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-669: 26918829	-	0	1	CMP	PP-H-Othr,Dmg-On	1	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	NICK HAMILTON 513-240-8825 SERVICE AT 217 ALLISON IS PULLED DUE TO TREE LIMB. SERVICE MAINT BENT AND SERVICE KNOB BROKE OFF. TALKED TO CUSTOMER AND INFORMED NEEDED ELECTRICIAN. NO OTHER ISSUES FOUND AT SITE. POLE 26BN-594C. AT COLONIAL AND ALLISON.

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
31	8110871	Buffington-H9320670041	11/15/2018 8:27:19 AM	11/17/2018 10:10:18 PM	11/18/2018 12:00:00 PM	TXOH: K116-491: 26906687	-	0	1	CMP	Tree-PH-On,Dmg-On	1	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	TWPH. M.ORTH 859-300-4794. BRANCH ON PRI BTWN K16-616 & K16-617. SEND BUCKET TRUCK TO CLEAR. M.ORTH 859-300-4794. BRANCH ON PRI BTWN K16-616 & K16-617. SEND BUCKET TRUCK TO CLEAR.
32	8110900	Buffington-H9320670041	11/15/2018 8:28:06 AM	11/18/2018 9:18:56 AM	11/18/2018 12:00:00 PM	TXOH: K116-538: 26906722	-	0	1	CMP	Tree-PP-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	TWPP. M.ORTH 859-300-4794. TREE TRIMMING ON SEC IN FRONT OF 15 DORCAS. CUST HAS POWER. M.ORTH 859-300-4794. TREE TRIMMING ON SEC IN FRONT OF 15 DORCAS. CUST HAS POWER. TT COMPLETE.
33	8111101	White Tower-H9323040042	11/15/2018 8:36:49 AM	11/16/2018 8:41:15 PM	11/18/2018 12:00:00 PM	TXOH: 22K-482: 26878402	-	0	1	CMP	Equip-E-Tree-PP-LF-Othr,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	LIMB ON LINE @ POLE # 22K-474E, (2988 LAKEVIEW DR), OH PRI MISSING DEADEND JUMPER, PRI HELD BY HLC STIRRUP - STILL ALL IS ENERGIZED NO CUSTOMERS OUT, OH LINE CREW REQ'D ALL IS ASSESSABLE, - L GROTHAUS 513-906-0133. ALL CUSTOMERS RESTORED
34	8111132	Empire-H9322890041	11/15/2018 8:37:47 AM	11/17/2018 10:33:43 PM	11/18/2018 12:00:00 PM	TXOH: 31BN-1288: 26883720	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	NICK HAMILTON 513-240-8825. CUSTOMER HAS POWER. DOWN TREE LIMB ON SERVICE WIRE. SERVICE WIRE IS PULLING ON HOUSE. RTT NICK HAMILTON 513-240-8825. CUSTOMER HAS POWER. DOWN TREE LIMB ON SERVICE WIRE. SERVICE WIRE IS PULLING ON HOUSE. TT COMPLETE
35	8111164	Buffington-H9320670045	11/15/2018 8:39:02 AM	11/18/2018 10:44:16 AM	11/18/2018 12:00:00 PM	TXOH: K117-535: 26908025	-	1	2	CMP	PH-H-Out-Othr-O,Dmg-On,Othr	1	EA Weather	Unselected	29 Permanent Repair	Florence	Rob Miller 513 543 8745 rear lot sm limb on service-sec & wh pulled from house around rk1, meter base pulled from house- disconnect service owner notified to make repairs. sm limb on service to 363. internal fuse blown @ oh xfrm pole K117-535
36	8111167	Donaldson-H9320550042	11/15/2018 8:39:11 AM	11/17/2018 8:02:09 PM	11/18/2018 12:00:00 PM	TXOH: K105-655: 26904915	-	0	1	CMP	Out-Dmg,Tree-PH-On	1	EA Weather	Unselected	19 Cut In/Reconnect at Weatherhe	Florence	K GOETZ 859-404-1222. LIMB ON SERVICE. PULLED FROM HOUSE. CUSTOMER TO MAKE REPAIRS. SERVICE KNOB PULLED. TREE TRIMMING REQ'D. CUSTOMER HAS POWER.
37	8111357	White Tower-H9323040041	11/15/2018 8:44:39 AM	11/17/2018 4:24:03 PM	11/18/2018 12:00:00 PM	TXOH: 22K-824: 26878411	-	0	1	CMP	PP-H-Tree-PP-On,Dmg-On	1	EA Weather	Unselected	13 Close Work Needed	Florence	R/ET ENERGIZED SERVICE ON GROUND. CUSTOMER NEED RK1 AND SEC REATTACHED. CUSTOMER NOTIFIED BY VM AND DOOR HANGER REAR PROPERTY. ALAN EAST 513-313-9220
38	8111385	White Tower-H9323040041	11/15/2018 8:42:22 AM	11/17/2018 5:14:28 PM	11/18/2018 12:00:00 PM	TXOH: 22K-968: 26878089	-	0	3	CMP	PH-H-Tree-PH-On,PH-H-On,Tree-PH-On,Dmg-On	1	EA Weather	Unselected	13 Close Work Needed	Florence	R/ET ENERGIZED SERVICE ON ROOF. CUSTOMER NEED TO REPAIR MAST. CUSTOMER NOTIFIED. ALAN EAST 513-313-9220
39	8111548	Crescent-H9320700044	11/15/2018 10:48:39 AM	11/17/2018 11:30:01 AM	11/18/2018 12:00:00 PM	TXOH: K93-289: 26927181	-	1	1	CMP	PP-H-Pf O	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	NICK HAMILTON 513-240-8825. R-E/T ROAD SIDE PRIMARY DOWN 1 SPAN POLE K93-226 TO K93-243. FUSE BLOWN POLE K93-291. PING ON - REQ 8124105 as of 11/16/2018 13:51. part power no ETR power line down going from pole to church. Cafeteria lost freezer fridge
40	8111688	Longbranch-H9320980042	11/15/2018 10:25:26 AM	11/18/2018 3:50:00 PM	11/18/2018 8:01:00 PM	TXOH: 45BN-163: 26870002	-	0	0	CMP	Out-Dmg	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-18 15:50:00 by WACASSO RMK: SERVICE WIRE FROM POLE 45BN-163E TO HOUSE IS LOW. NEEDS RE-SAGGED. NUETRAL WIRE BROKE UP BY POLE. #2 AL TX. CUSTOMER NOTIFIED ABOUT BROKEN MAST GUY
41	8111719	Buffington-H9320670045	11/15/2018 8:57:07 AM	11/17/2018 8:35:11 PM	11/18/2018 12:00:00 PM	TXOH: K117-30: 26907670	-	0	2	CMP	PP-H-911-On,PH-H-Tree-PH-On,Out,Dmg	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	JOE GROESCHEN 8592500319 - NEUTRAL BROKEN ON #2ALTX SERVICE TO HOUSE FROM POLE K117-87 CUSTOMER HAS PARTIAL POWER. MADE REPAIRS TO NEUTRAL
42	8111867	Villa-H9322430041	11/15/2018 9:02:53 AM	11/17/2018 4:21:15 PM	11/18/2018 12:00:00 PM	TXOH: K84-574: 26926654	-	0	1	CMP	PP-H-911-Tree-PP-Othr,Dmg-On	1	28 Other Cause	Unselected	26 OK Arrival	Florence	ROB MILLER 513 543 8745 BKT TRK ACCESS SM LOOSE LIMBS ON OPEN 3W SEC 1 SPAN POLE K84-513 TO K884-576-CUST @ 101 IN & OK
43	8111895	Donaldson-H9320550042	11/15/2018 9:04:02 AM	11/16/2018 2:49:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-244: 26905052	-	18	6	CMP	PP-H-Out,PP-H-Othr,PP-H-On,Othr-H-Othr,Out-Dmg,Out	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-16 14:49:00 by T95129 RMK: #4 tri up perm
44	8111896	Crescent-H9320700043	11/15/2018 9:02:50 AM	11/17/2018 11:52:10 AM	11/18/2018 12:00:00 PM	TXOH: K84-338: 26925917	-	0	2	CMP	PH-H-Tree-PH-Othr,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	MANNING - 513-218-6533 - REAR LOT - ENERGIZED 4ALTX SERVICE DOWN FROM POLE K84-339 TO HOUSE. CUST HAS POWER. WILL NEED ELECTRICIAN, NEW WH & RK-1 (NOT NOTIFIED) SMALL BRANCH ON SERVICE OF 33 THOMPSON. SERVICE IN AN OK.
45	8111939	Richwood-H9321990042	11/15/2018 9:05:26 AM	11/16/2018 11:59:24 PM	11/18/2018 12:00:00 PM	TXOH: 35BN-634: 26885240	-	0	1	CMP	PH-H-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	R/TT: Tree on Service at house by weatherhead, Pole # 25BN-634E up customer driveway near house - Reffer to TREE TRIMMING Manual crew (1 birch tree with many branches) - L Grothaus 513-906-0133

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
46	8112084	White Tower-H9323040041	11/15/2018 9:11:18 AM	11/17/2018 11:05:00 AM	11/18/2018 12:00:00 PM	FOH: 23K-27: 26063754	65T	5	9	CMP	Out-Dmg,Out	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	65T FUSE BLOWN POLE# 23K-27E, #6CU (PRI & NEUTRAL) DOWN REAR LOT B/W POLE # 23K-33E & KNK-1666E, MULTI GENERATORS IN USE, L GROTHAUS 10:34AM 11/16/18 513-906-0133
47	8112092	Longbranch-H9320980042	11/15/2018 9:11:37 AM	11/17/2018 8:45:54 PM	11/18/2018 12:00:00 PM	TXOH: 34BN-71: 26863108	-	0	1	CMP	Obj-L-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	NICK HAMILTON 513-240-8825. 3IN TREE LINE HUNG ON PRIMARY 1PH BETWEEN POLE 34BN-884 AND 34BN-71 (NPT). LIMB ON PRIMARY HANGING OFF GROUND.
48	8112132	Augustine-H9320780041	11/15/2018 9:12:53 AM	11/17/2018 5:50:00 PM	11/18/2018 12:00:00 PM	TXOH: K61-149: 26923722	-	0	1	CMP	PH-H-On,Dmg-On	1	20 Equipment failure	Unselected	29 Permanent Repair	Covington	CMPL 2018-11-17 17:50:00 by T17410 RMK: Kim Powell onsite waiting - Triplex Service down across drive - Customer repairs required / xfer 1/0 tr to newly installed house knob
49	8112175	Buffington-H9320670045	11/15/2018 9:14:32 AM	11/16/2018 8:36:00 PM	11/16/2018 9:30:00 PM	TXOH: K117-6: 26907663	-	7	7	CMP	PH-H-Tree-PH-Pt O,PH-H-Obj-L-LF-On,PH-H-Tree-PH-Othr-PQ-On,PH-H-Pt O,Othr-H-Tree-PP-Pt O,Out-Dmg,Out	1	EA Weather	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-16 20:36:00 by T25446 RMK: SERVICE HOLDING UP LG LIMB BROKE NEU @ MAST -ALSO 8 CIRCLE SMALL LIMB ON SERVICE
50	8112237	Florence-H9322410042	11/15/2018 9:17:15 AM	11/17/2018 8:38:57 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-373: 26881260	-	0	1	CMP	PP-H-Tree-PP-On,Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	not resolved customer states tree is laying on wires 11/17/18- NICK HAMILTON 513-240-8825. TREE ON SECONDARY P-P POLE 26BN-12 AND 26BN-360. SERVICE WIRE TO HOMES 81 AND 83 CORETA NEED TO BE RE-SAGGED- LESS THAN 10FT OVER GRASS.
51	8112280	Donaldson-H9320550041	11/15/2018 9:19:19 AM	11/17/2018 7:10:20 PM	11/18/2018 12:00:00 PM	TXOH: K105-83: 26904774	-	1	1	CMP	PH-H-Tree-PH-Out,Out-Dmg	1	EA Weather	Unselected	26 OK Arrival	Florence	ROB MILLER 513 543 8745 BKT TRK ACC RECONNECT SERV @ POLE K105-83
52	8112354	Villa-H9322430044	11/15/2018 9:22:21 AM	11/17/2018 7:11:34 PM	11/18/2018 12:00:00 PM	TXOH: K96-354: 26916703	-	0	1	CMP	PP-H-Tree-PP-On,Dmg-On	1	EA Weather	Unselected	39 Repaired Overhead Conductor	Florence	ROB MILLER 513 543 8745 REAR LOT SEC & KNOB PULLED FROM HOUSE-DISCONNECT SERVICE-DOOR HANGER LEFT FOR CUSTOMER
53	8112405	Crescent-H9320700041	11/16/2018 9:10:50 PM	11/17/2018 4:53:00 PM	11/17/2018 5:52:00 PM	TXOH: K84-437: 26926614	-	0	0	CMP	Out-Dmg	1	03 Vegetation	Unselected	12 Checked Voltage/Fixed Connect	Florence	CMPL 2018-11-17 16:53:00 by T39767 RMK: NICK HAMILTON 513-240-8825. SERVICE FROM POLE TO HOUSE DOWN. POLE K84-437C. WH. SEC. SERVICE KNOB PULLED FROM HOME. CUST STILL HAS POWER. ADVISED NEEDS ELECTRICIAN.
54	8112504	KY Univ-H9322870042	11/15/2018 9:29:14 AM	11/17/2018 8:51:15 PM	11/18/2018 12:00:00 PM	TXOH: CA17-125: 26900512	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	- limb on open 3 wire service. Need tree crew only. Side yard, not truck accessible. M.Clark 513 460 3358 TT COMPLETE
55	8112676	Augustine-H9320780046	11/15/2018 9:35:34 AM	11/16/2018 6:20:25 PM	11/18/2018 12:00:00 PM	TXOH: K72-219: 26912438	-	1	1	CMP	PH-H-Out,Out-Dmg	1	28 Other Cause	Unselected	27 Other/See Notes	Covington	K GOETZ 859-404-1222. SVC PULLED FROM HOUSE. LIMB ON SERVICE. CUSTOMER TO MAKE REPAIRS. POLE K72-219E. BROKEN NEUTRAL, 2ALTX 85'. MADE REPAIRS TO SERVICE. CUSTOMER RESTORED
56	8112690	Donaldson-H9320550042	11/15/2018 9:36:06 AM	11/17/2018 5:29:09 PM	11/18/2018 12:00:00 PM	TXOH: K104-401: 26903965	-	0	1	CMP	Tree-PH-On,Dmg-On	1	EA Weather	Unselected	25 No Problem Found	Florence	ROB MILLER 513 543 8745 NOT BUCKET ACC-SM LIMB ON SERV-CUST HAS POWER
57	8112699	Florence-H9322410046	11/15/2018 9:36:30 AM	11/17/2018 8:17:32 PM	11/18/2018 12:00:00 PM	TXOH: 31BN-1176: 26883492	-	0	1	CMP	PP-H-Othr-O-Othr,Dmg-On	1	03 Vegetation	Unselected	48 Replaced Service/Secondary	Florence	JOE GROESCHEN 8592500319 R-ET - SECONDARY FOR LIGHT IS ROLLED UP AT POLE 31BN-1202. RE-CONNECT SECONDARY BETWEEN 31BN-1202 & 31BN-1176 SERVICE TO BUILDING IN/OK
58	8112982	Florence-H9322410045	11/15/2018 9:50:37 AM	11/18/2018 11:22:28 AM	11/18/2018 12:00:00 PM	TXOH: 25BN-664: 26880508	-	0	2	CMP	PH-H-Pole-L-On,PH-H-On,Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	JOE GROESCHEN 859 250 0319 - 42 STONEGATE HAS SERVICE BANJO TIGHT & PULLING THE CORNER OFF SIDE OF HOUSE ADVISED CUSTOMER TO GET A CONTRACTOR & CALL FOR DROP SERV- 58 KELLEY HAS LOW SERVICE OVER ROAD BOTH SERVICES WILL NEED TO BE RESAGGED AT 25BN-664
59	8113012	Beaver-H9320860041	11/15/2018 9:52:24 AM	11/18/2018 11:57:59 AM	11/18/2018 2:00:00 PM	TXOH: 29K-125: 26881974	-	1	5	CMP	PH-H-Out,Out-Dmg,Out	1	EA Weather	Unselected	49 Replaced Transformer	Florence	TOM GEIMAN 513.446.4723 1 SPAN OF LIGHTING 2NDARY DOWN (#2ALTX) BTW P# 29K-125E & 29K-21E. CUSTOMER HAS POWER. PING OFF - REQ 8124133 as of 11/16/2018 13:57. ESphr 513-458-3803 NEEDS TRANSFORMER - replaced trf and out up duplex
60	8113076	Villa-H9322430043	11/15/2018 9:55:49 AM	11/17/2018 9:39:00 AM	11/17/2018 10:30:00 AM	FOH: K95-57: 25998899	65T	16	30	CMP	Out-Dmg,Out	1	EA Weather	-	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-17 09:39:00 by T25446 RMK: ROB MILLER 513 543 8745 REAR LOT ACCESS FROM 74 DUDLEY 2 SPANS 4CU PRIM DOWN FROM K95-289 TO 297-NO OTHER DAMAGE
61	8113120	Wilder-H9320590046	11/15/2018 9:57:50 AM	11/17/2018 11:54:00 AM	11/18/2018 12:00:00 PM	TXOH: CA14-157: 26899747	-	0	1	CMP	PH-H-On,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 11:54:00 by CLWILLS RMK: Small Tree Limb on Down Service - Taped off area, advised customer to make repairs 1/0ALTX (100ft) Customer still energized Neutral broken at weather head - L Grothaus
62	8113355	Florence-H9322410042	11/15/2018 10:10:03 AM	11/17/2018 9:12:08 PM	11/18/2018 12:00:00 PM	TXOH: K116-873: 26906887	-	0	1	CMP	Dmg-On,On	1	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	NICK HAMILTON 513-240-8825. CUST HAS POWER. LIMB IN NEUTRAL AT POLE K116-873C.
63	8113518	Hands-H9321280045	11/15/2018 10:21:01 AM	11/18/2018 5:08:44 PM		TXOH: 15K-858: 26874414	-	0	1	CMP	PH-H-Othr,Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	R/TT Manual Crew Needed 1/0 ALTX LIMB ON SERVICE. CUSTOMER IS REPLACING SERVICE KNOB. POLE #15K-858 D.WRIGHT 513-207-2228

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
64	8113572	Villa-H9322430041	11/15/2018 10:23:59 AM	11/17/2018 12:37:03 PM	11/18/2018 12:00:00 PM	TXOH: K84-51: 26926364	Retrofit 12/2/2013	0	1	CMP	Dmg-On,Othr-O-On	1	03 Vegetation	-	-	Florence	ROB MILLER 513 543 8745 CUST RK1 AND SERV DOWN-SERVICE HANGING LOW DISCONNECT-OWNER ADVISED REAR LOT POLE K84-51
65	8113636	Beaver-H9320860041	11/15/2018 10:27:21 AM	11/17/2018 10:42:49 PM	11/18/2018 12:00:00 PM	TXOH: 29K-172: 26882088	-	0	1	CMP	Dmg-On,Othr-O-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	TOM GEIMAN 513.447.4623 LARGE LIMB ON LIFT POLE 29K-181E, CUSTOMER HAS POWER. TT COMPLETE
66	8113908	Hebron-H9321520042	11/15/2018 10:39:57 AM	11/17/2018 1:50:00 PM	11/18/2018 12:00:00 PM	FOH: 7BN-13: 25987197	65T	8	4	CMP	Out-S-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 13:50:00 by T29408 RMK: NICK HAMILTON 513-240-8825. 2IN TREE LIMB IN 1PH PRIMARY/NEUTRAL. BETWEEN POLE 7BN-24E AND 7BN-25E NEXT TO 2764 SUTTON GENERATORS HEARD IN AREA ON MULTIPLE HOMES. FUSE BLOWN AT 7BN-13 TAP POLE...NEEDS TREE CRE
67	8113950	Florence-H9322410042	11/15/2018 9:12:31 AM	11/16/2018 6:44:00 PM	11/16/2018 7:30:00 PM	TXOH: 26BN-482: 26919089	-	12	32	CMP	Equip-E-Tree-PH-On, Equip-E-Out, PP-H-Tree-PH-Out, PP-H-Tree-PH-H-Obj-L-Out, PH-H-Tree-PH-Out, PH-H-Tree-PH-Out, PH-H-Tree-PH-Out, PH-H-Tree-PH-Out, PH-H-Tree-PH-Out	1	EA Weather	Unselected	51 Reset Transformer Breaker	Florence	CMPL 2018-11-16 18:44:00 by T25446 RMK: NICK HAMILTON 513-240-8825. SERVICE DROP FROM MIDSPAN TO HOUSE OK. POWER OUTAGE DUE TO TRANSFORMER FUSE BLOWN 26BN-482C. NICK HAMILTON 513-240-8825 TREE LIMB ON SERVICE. TRANSFORMER BLOWN 26BN-482C. MIDSPAN TAP.
68	8114017	Decoursey-H9322990041	11/15/2018 10:46:32 AM	11/17/2018 5:05:00 PM	11/18/2018 12:00:00 PM	TXOH: 15K-857: 26874755	-	0	1	CMP	Tree-PH-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 17:05:00 by WACASSO RMK: R/TT small limb on open 3 wire, no conductor or customer equipment damaged,back at the end of long private drive, D Wright 513-207-2228.
69	8114280	Longbranch-H9320980043	11/15/2018 10:58:44 AM	11/17/2018 8:28:24 AM	11/18/2018 12:00:00 PM	TXOH: 35BN-235: 26885152	-	1	2	CMP	Othr-H-Pt O-Othr-O,Out-Dmg,Out	1	28 Other Cause	Unselected	12 Checked Voltage/Fixed Connect	Florence	NEUT SNAPPED AT W/H, FIXED CONN, CUST BACK FULL POWER
70	8114298	White Tower-H9323040041	11/15/2018 10:59:37 AM	11/17/2018 10:35:10 PM	11/18/2018 12:00:00 PM	TXOH: 26K-104: 26881881	-	0	1	CMP	PH-H-Pole-L-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	Mrs. Conley said branch still on line, line 3-4 ft from ground and pole leaning. 11-17-18. LARGE BRANCH ON ENERGIZED SERVICE LINE. TREE TRIMMING REQ'D. ALAN EAST 513-313-9220 TT COMPLETE
71	8114305	Buffington-H9320670041	11/15/2018 11:00:08 AM	11/18/2018 10:23:23 AM	11/18/2018 12:00:00 PM	TXOH: K116-260: 26906648	-	0	1	CMP	PP-H-911-Othr,Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	M ORTH 859-300-4794. SPREADER STICK FOR MID SPAN TAP OFF TOP LEG BTWN POLES K116-260 & K116-259. M ORTH 859-300-4794. SPREADER STICK FOR MID SPAN TAP OFF TOP LEG BTWN POLES K116-260 & K116-259
72	8114372	Richwood-H9321990042	11/17/2018 10:02:47 AM	11/18/2018 12:42:00 PM	11/18/2018 1:30:00 PM	TXUG: 36BN-110: 26886990	-	0	0	CMP	Out-Dmg	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-18 12:42:00 by T81490 RMK: Tom Geiman 513.446.4723 P# 36BN-128E SERVICE HANGING VERY LOW (2ALTX) ACCESS FROM 191 GREENLAWN. SERVICE PULLED LOOSE @ POLE REAR LOT
73	8114492	Hands-H9321280041	11/15/2018 11:11:03 AM	11/18/2018 3:29:46 PM	11/18/2018 12:00:00 PM	TXOH: 15K-971: 26875250	-	0	2	CMP	PP-H-Tree-PP-On, PH-H-Othr-O-On,Dmg-On	1	EA Weather	Unselected	21 Cut Off/Disconnect at Weather	Florence	R/E Customer to get Electrician R/ET 1/0 ALTX. TREE LIMB ON SERVICE, DISCONNECT SERVICE AND ROLE UP TO POLE, CUSTOMER TO REPAIR SEC & KNOB, DOORHANGER LEFT, POLE #15K-172, D-WRIGHT 513-207-2228
74	8114642	Crescent-H9320700041	11/15/2018 11:18:38 AM	11/17/2018 11:25:25 PM	11/18/2018 12:00:00 PM	TXOH: K83-232: 26925506	-	0	1	CMP	PH-H-On,Dmg-On	1	03 Vegetation	Unselected	27 Other/See Notes	Florence	SERVICE LAYING ON GROUND, R TO E ON W/H. LEFT NOTE. C.I.C. AND ROLLED UP TO POLE. HOUSE LOOKS TO BE VACANT.
75	8114964	Longbranch-H9320980043	11/15/2018 11:36:52 AM	11/17/2018 7:13:45 PM	11/18/2018 12:00:00 PM	TXOH: 35BN-574: 26885200	-	1	2	CMP	PP-H-Tree-PP-On, PH-H-Tree-PH-Out,Dmg-On	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	TREE LIMB HAS TAKEN DOWN TRIPLEX NEXT DOOR STILL ENERGIZED, CAUTION TAPED AND LEFT DOOR HANGER AT 10053 INDIAN HILL DUE TO TRIPLEX ON GROUND AND SEC OFF HOUSE, R TO E, BUCKET ACCESSIBLE
76	8115383	Buffington-H9320670041	11/15/2018 12:03:47 PM	11/16/2018 6:08:00 PM	11/16/2018 8:00:00 PM	FOH: K116-255: 25994657	65T	71	111	CMP	PP-H-Out,Othr-O,Tree-PP-Out,Out,Dmg-On	1	03 Vegetation	11 Unknown Cause	44 Replaced Fuse	Florence	CMPL 2018-11-16 18:08:00 by T39767 RMK: ROB MILLER 513 543 8745 BUCKET TRK ACCESS 65T BLOWN @ K116 -255. LG TREE ON PRIM @ K116-258 PTP BROKE SEC DOWN @ 102 -SEC NEEDS REPLACED FAULTY-DISCONNECT SERVICE
77	8115403	Hebron-H9321520042	11/15/2018 12:04:48 PM	11/17/2018 12:09:24 PM	11/18/2018 12:00:00 PM	FOH: 12BN-53: 25986151	40T	3	3	CMP	PP-H-Out,Out-Dmg,Out	1	03 Vegetation	03 Tree (Vegetation)	17 Closed Switch	Florence	NICK HAMILTON 513-240-8825. CUTOFF BLOWN ON POLE 12BN-53C. PRIMARY AND NEUTRAL BROKE POLE 12BN-51E TO POLE 12BN-45. REAR LOT NO ACCESS
78	8115430	Hands-H9321280041	11/15/2018 12:05:42 PM	11/17/2018 6:19:13 PM	11/18/2018 12:00:00 PM	TXOH: 19K-40: 26876642	-	0	1	CMP	PH-H-On,Dmg-On	1	EA Weather	Unselected	26 OK Arrival	Florence	R/ET ALAN EAST 513-313-9220. WEATHERHEAD AND SEC DETACHED FROM HOME, ENERGIZED SVC ON ROOF, LIFT POLE 19K-42, CUST NOTIFIED BY DOOR HANGER
79	8115671	Hebron-H9321520042	11/15/2018 9:28:08 AM	11/16/2018 7:43:33 PM	11/18/2018 12:00:00 PM	FOH: 11BN-146: 25986074	65T	5	10	CMP	PP-H-Out,PH-H-Out,Out,Dmg,Out,Othr-O-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	NICK HAMILTON 513-240-8825. NEUTRAL SPAN BROKE LAYING ON GROUND BETWEEN POLE 11BN-270 AND POLE 11BN-271. TAP FUSE BLOWN AT POLE 11BN-146...CUSTOMERS ARE IN AND HOLDING
80	8115772	Donaldson-H9320550042	11/15/2018 12:26:20 PM	11/18/2018 10:13:00 AM	11/18/2018 12:00:00 PM	TXOH: K104-224: 26903850	-	0	1	CMP	Tree-PH-On,Dmg-On	1	03 Vegetation	Unselected	11 Checked Voltage/All OK	Florence	CMPL 2018-11-18 10:13:00 by MHMURRE RMK: ROB MILLER 513 543 8745 BKT TRK ACC SM LIMB ON OPEN 3W SERVICE-CUST HAS POWER

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
81	8115957	Empire-H9322890041	11/15/2018 12:38:56 PM	11/18/2018 12:40:51 PM		TXOH: 31BN-831-84914268	-	0	1	CMP	PH-H-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	JOE GROESCHEN R-E/T- 1/0 ALTX SERVICE ON GROUND BETWEEN POLE 31BN-831C & HOUSE. WHEAD, SEC. AND SERVICE ATTACHMENT PULLED LOOSE FROM HOUSE ADVISED CUSTOMER TO GET ELECTRI 1/0ALTX SERVICE DOWN POLE TO HOUSE SEC.WHEAD, SEVICE ATTACHMENT PULLED FROM HO
82	8116518	Buffington-H9320670045	11/15/2018 1:19:54 PM	11/15/2018 9:15:00 PM	11/15/2018 9:45:00 PM	FOH: K105-719-25994280	65T	66	67	CMP	Out-Dmg,Out	1	03 Vegetation	28 Other Failure Mode	29 Permanent Repair	Florence	CMPL 2018-11-15 21:15:00 by T81490 RMK: ROB MILLER 513 543 8745 RECONNECT SERVICE @ 3914 HOPE POLE K105-805. DISCONNECT SERVICE TO 446 FOREST SEC FAULTY AND PULLED FROM HOUSE. 65T BLOWN @ K105-719- NO OTHER DAMAGE FOUND ON LINE BUCKET TRUCK ACC
83	8116648	Florence-H9322410042	11/15/2018 11:09:55 AM	11/17/2018 9:54:00 AM	11/18/2018 12:00:00 PM	TXOH: 26BN-739-26881413	-	4	5	CMP	Equip-E-PF-Othr,PH-H-Out-PF,PH-H-Out,CC-H-Out,Out-Dmg,Out	1	EA Weather	Unselected	26 OK Arrival	Florence	CMPL 2018-11-17 09:54:00 by CMTURNE RMK: OK ARRVL. PWR RESTORED.
84	8116797	Buffington-H9320670041	11/15/2018 9:02:50 AM	11/16/2018 9:14:00 PM	11/16/2018 10:17:00 PM	TXOH: 26BN-228-26881168	-	9	12	CMP	Equip-E-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	44 Replaced Fuse	Florence	CMPL 2018-11-16 21:14:00 by T39767 RMK: T. GEIMAN 513-447-4623. LIMB ON SERVICE @ 19 RIDGEWAY BROKE SPREADER STICK ON O3W BTW P#26BN-226C & 227C. O3W TWISTED BTW 26BN-227 & 228. BLOWN TRF FUSES (CSP) @ P# 26BN-227C & 26BN-228C
85	8116834	Donaldson-H9320550041	11/15/2018 1:41:24 PM	11/18/2018 9:49:48 AM	11/18/2018 12:00:00 PM	TXOH: K105-76-26904935	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	ROB MILLER 513 543 8745 BKT TRK ACC SEC & KNOB PULLED FROM HOUSE-SVC HANGING LOW-DISCONNECT SVC @ POLE ADJ TO K105-76-DOOR HGRLEFT NO CONTACT W/ CUSTOMER AREA TAPED OFF
86	8117057	Marshall-H9323580041	11/15/2018 8:46:22 AM	11/17/2018 5:15:00 AM	11/18/2018 12:00:00 PM	TXOH: 35CA-123-26885973	-	0	2	CMP	PP-H-On,PH-H-On,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 05:15:00 by T17494 RMK: R/ET Damage located at 823 Johns Hill RD. Respicce neutral in two locations 2 ALTX. Truck accessible, flagging required, no customer repairs required 1 pole north of 35C-998 tree on wire wire on ground
87	8117200	Wilder-H9320590045	11/15/2018 2:12:44 PM	11/15/2018 7:50:00 PM	11/15/2018 8:45:00 PM	TXOH: CA11-138-26899132	-	0	1	CMP	PP-H-911-Tree-PP-On,Out-Dmg	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-15 19:50:00 by T17636 RMK: L Grothaus 513-906-0133 3:45pm. BETWEEN POLE # CA11-137C AND CA11-145C REMOVE TREE LIMB 1/0 PHASE AND # 2 3 WIRE SECONDARY. POLE # CA11-136C CLOSE CUTOUT 19:50. CUSTOMER CONTACT
88	8117338	Limaburg-H9321890041	11/15/2018 2:23:09 PM	11/18/2018 9:15:00 AM	11/18/2018 12:00:00 PM	TXOH: 19BN-506-26868131	-	0	0	CMP	Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-18 09:15:00 by T56235 RMK: Eric Moore 513-255-2120/ Triplex down needs cutoff for safety/cust been referred to electrician
89	8117400	Wilder-H9320590042	11/15/2018 2:28:06 PM	11/17/2018 3:03:00 AM	11/17/2018 4:22:00 PM	TXOH: CA11-9-26898758	-	0	0	CMP	Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 03:03:00 by T17494 RMK: rear lot service hanging low. Customer needs to make repairs service pulled away from house. Service Crew to cut off service, Feed From Pole # CA11-10E. PRIVATE DRIVE ACCESS TO POLE BEHIND HOME - ADVISED CUSTOMER
90	8117450	Decoursey-H9322990041	11/15/2018 7:37:52 AM	11/17/2018 3:15:00 PM	11/17/2018 4:00:00 PM	TXOH: 11K-390-26872070	-	1	2	CMP	PP-H-Out,PH-H-Tree-PH-Out,Out-Dmg	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-17 15:15:00 by WACASSO RMK: PING OFF - REQ 8123494 as of 11/16/2018 12:18. power out. front yard. ESphahr 513-458-3803, R/ET ENERGIZED SERVICE ON GROUND. DISCONNECTED FROM HOME, CUSTOMER NOTIFIED TO RECONNECT WEATHERHEAD AND RACK UP SEC CABL
91	8117521	Mt Zion-H9323050043	11/15/2018 2:37:15 PM	11/17/2018 10:06:55 PM	11/18/2018 12:00:00 PM	TXOH: 36BN-170-26887322	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	TOM GEIMAN 513.446.4723 SMALL LIMB ON SERVICE. SERVICE & CUSTOMER EQUIPMENT OK. CUSTOMER HAS POWER
92	8117572	Decoursey-H9322990041	11/15/2018 2:41:40 PM	11/17/2018 6:17:58 PM	11/18/2018 12:00:00 PM	TXOH: 11K-971-26872602	-	0	1	CMP	Tree-PH-On,Dmg-On	1	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	customer unsure if tree branches are on the line. R/ET NON EMERGENCY CUST HAS POWER TREE BRANCH ON SERVICE LINE. NO CUSTOMER WORK REQ'D. ALAN EAS R/ET NON EMERGENCY CUST HAS POWER TREE BRANCH ON SERVICE LINE. NO CUSTOMER WORK REQ'D. ALAN EAST 513-313-9
93	8117579	Decoursey-H9322990041	11/15/2018 2:42:05 PM	11/17/2018 3:30:00 PM	11/18/2018 12:00:00 PM	TXOH: 11K-1125-26872600	-	0	1	CMP	Dmg-On,Othr-O-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 15:30:00 by WACASSO RMK: branch is still on hot line. R/ET LIMB ON LINE POLE 11K-1124. ALAN EAST 513-313-9220 branch is still on hot line. R/ET LIMB ON LINE POLE 11K-1124. ALAN EAST 513-313-9220
94	8117699	Donaldson-H9320550042	11/17/2018 2:11:20 PM	11/18/2018 8:43:00 AM	11/18/2018 12:00:00 PM	TXOH: K104-174-26903841	-	0	0	CMP	Dmg-On	1	05 Planned (IEEE)	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-18 08:43:00 by T74214 RMK: ROB MILLER 513 543 8745 CUST INSTALLED NEW SEC MAKE PERM CONN-HOLD FOR RELEASE. PING OFF - REQ 8123482 as of 11/16/2018 12:18. tree took wire down caught fire/ fire dept on scene/ lines down. ESphahr 513-458-3803
95	8117727	Verona-H9321250041	11/15/2018 2:54:22 PM	11/17/2018 12:16:34 PM	11/18/2018 12:00:00 PM	TXOH: 57BN-26-26871171	-	1	2	CMP	PP-H-Tree-PP-On,Out,Dmg-On	1	EA Weather	Unselected	39 Repaired Overhead Conductor	Florence	TOM GEIMAN 513.446.4723 - 1 NEUTRAL SPAN DOWN (4CU, 250) BTW P# 57BN-26E & 27E REAR LOT, CUSTOMER HAVE POWER.

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
96	8117840	Verona-H9321250041	11/15/2018 3:04:16 PM	11/17/2018 9:58:00 AM	11/18/2018 12:00:00 PM	TXUG: 37K-2: 26889844	-	2	10	CMP	Out-Dmg,Out	1	03 Vegetation	Unselected	41 Replaced Arrestor	Florence	Tom Geiman 513.446.4723. 40T fuse blown @ 37K-51E. POSSIBLY BAD UG PRIM NOT STORM RELATED. CHECK PADMOUNT TRF37K-2. MAIN LINE HAS POWER.
97	8117923	White Tower-H9323040041	11/16/2018 3:08:18 PM	11/18/2018 10:40:00 AM	11/18/2018 11:30:00 AM	TXOH: 22K-520: 26878047	-	0	0	CMP	Dmg-On	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-18 10:40:00 by WACASSO RMK: PING OFF - REQ 8123365 as of 11/16/2018 11:53. line down in yard. ESphr 513-458-3803. R/ET SERVICE PULLED DOWN AT POLE 22K-520 NEEDS RECONNECTED LIGHT TREE TRIMMING REQ'D TRUCK ACCESSIBLE. RETENTION GUY FOR SVC
98	8118207	Hands-H9321280041	11/15/2018 3:34:06 PM	11/17/2018 6:16:57 PM	11/18/2018 12:00:00 PM	TXOH: 19K-33: 26876592	-	0	1	CMP	Tree-PH-On,Dmg-On	1	EA Weather	Unselected	26 OK Arrival	Florence	Still an issue, 11/16/18 R/ET ENERGIZED SERVICE ON GROUND FROM POLE 19K-33E TO HOUSE. CUSTOMER NOTIFIED REPAIRS TO WEATHERHEAD RK1 AND SEC NEED REATTACHED. ALAN EAST 513-313-9220
99	8118508	Hands-H9321280044	11/15/2018 7:02:29 AM	11/18/2018 11:27:30 AM	11/18/2018 12:00:00 PM	TXOH: K87-116: 26914807	-	0	2	CMP	PP-H-Tree-PP-On,Dmg-On,On	1	EA Weather	Unselected	26 OK Arrival	Florence	. KEVIN LANHAM 513-504-1488 TT COMPLETE
100	8118629	Donaldson-H9320550042	11/15/2018 11:45:52 AM	11/17/2018 8:50:08 PM	11/18/2018 12:00:00 PM	TXOH: K105-653: 26904922	-	0	2	CMP	Tree-PP-On,Dmg-On,On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	. K GOETZ 859-404-1222. LIMB ON SERVICE. CUSTOMER EQUIPMENT OK. TREE TRIMMING REQD. CUSTOMER HAS POWER. TT COMPLETE
101	8119072	Villa-H9322430041	11/16/2018 1:20:08 PM	11/17/2018 10:43:00 AM	11/17/2018 11:46:00 AM	TXOH: K84-18: 26926751	-	0	0	CMP	Dmg-On	1	03 Vegetation	Unselected	12 Checked Voltage/Fixed Connect	Florence	ROB MILLER 513 543 8745 REAR LOT SERVICE NEUT BROK @ HOUSE & POLE POLE K84-18- ACCESS ON LANE DR BEHIND HOUSE- REFERRED TO ERLPING ON - REQ 8123176 as of 11/16/2018 11:32. wires snap live wires about 2ft from house and laying on gutter, bracket pulled fr
102	8119152	Buffington-H9320670041	11/15/2018 5:00:11 PM	11/18/2018 3:22:00 AM	11/18/2018 12:00:00 PM	TXOH: K116-493: 26906712	-	0	1	CMP	Tree-PP-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-18 03:22:00 by T17410 RMK: branch on primary@Bustetter and Fieda Pl near pole K116-617. cust at 30 bustetter w full power. B. Brown 513-313-3454 / limbs removed from 1/0 primary
103	8119211	Villa-H9322430041	11/15/2018 4:40:58 PM	11/17/2018 7:37:00 PM	11/17/2018 8:37:00 PM	TXOH: K84-605: 26926354	-	1	2	CMP	Tree-PH-Pl O,Out,Dmg-On	1	03 Vegetation	Unselected	12 Checked Voltage/Fixed Connect	Florence	CMPL 2018-11-17 19:37:00 by T39767 RMK: ROB MILLER 513 543 8745 REAR LOT Tree down on serv P-H.Broken -N- at pole,broken leg at wh.bent mast at house,fenced yard,caution taped.Call Mike 10 min away 8596534194 CUST AWARE MAY NEED TO DE-ENERGIZE DUE TO
104	8119215	Decoursey-H9322990041	11/15/2018 3:27:12 PM	11/17/2018 2:00:00 PM	11/18/2018 12:00:00 PM	TXOH: 11K-577: 26862363	-	0	2	CMP	PH-H-Othr-O-On,PH-H-On,Dmg-On	1	03 Vegetation	Unselected	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-17 14:00:00 by WACASSO RMK: R/ET, ENERGIZED SERVICE IN YARD CUSTOMER NOTIFIED TO REPAIR BROKEN MAST. ELECTRICIAN TO MAKE REPAIRS MONDAY 19TH. ALAN EAST 513-313-9220
105	8119230	Villa-H9322430044	11/15/2018 5:09:21 PM	11/17/2018 10:36:35 PM	11/18/2018 12:00:00 PM	TXOH: K96-325: 26917244	-	0	1	CMP	PH-H-Obj-L-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	NICK HAMILTON 513-240-8825. SERVICE HAS 2IN LIMB ON SERVICE IN TREE. CUST HAS POWER. NO OTHER ISSUES FOUND. NICK HAMILTON 513-240-8825. SERVICE HAS 2IN LIMB ON SERVICE IN TREE. CUST HAS POWER. NO OTHER ISSUES FOUND. TT COMPLETE
106	8119425	Buffington-H9320670045	11/15/2018 6:54:07 AM	11/17/2018 8:08:40 PM	11/18/2018 12:00:00 PM	TXOH: K106-966: 26905851	-	0	2	CMP	PH-H-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	M ORTH 859-300-4794. SERVICES DOWN AT 1046 & 1052. AT POLE K106-966. DISCONNECT SERVICES CUST TO MAKE REPAIRS, DOOR HANGER LEFT M.ORTH 859-300-4794. SERVICES DOWN AT 1046 & 1052. AT POLE K106-966. , RE-ATTACHED. ELECTRICIAN NEEDED
107	8119488	Decoursey-H9322990041	11/15/2018 5:29:29 PM	11/17/2018 8:47:10 AM	11/18/2018 12:00:00 PM	TXOH: 11K-101: 26862335	-	0	1	CMP	PP-H-Othr-O-On,Dmg-On	1	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OK 513-313-9220
108	8119513	Buffington-H9320670045	11/15/2018 5:31:05 PM	11/18/2018 10:22:26 AM	11/18/2018 12:00:00 PM	TXOH: K117-165: 26907815	-	0	1	CMP	PP-H-Obj-L-Othr,Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	TOM GEIMAN 513 446 4723. LIMB ON 2NDARY BTW P# K117-167E & 667E. NEAR 7950 DIXIE. TRAFFIC FLAGGING REQ'D. CUSTOMER HAS POWER- lines still down per customer. intersection of spruce dr and us 25 by pine lake apartments.11-16 18 TT COMPLETE
109	8119723	Crescent-H9320700043	11/15/2018 6:35:25 AM	11/17/2018 2:11:00 AM	11/18/2018 12:00:00 PM	TXOH: K72-497: 26912612	-	4	5	CMP	PH-H-Tree-PH-Out,PH-H-Out,Tree-PH-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	14 Closed Breaker	Florence	CMPL 2018-11-17 02:11:00 by T66296 RMK: ROB MILLER 513 543 8745 REAR LOT-WORK @ 305 CHERRYWOOD-SERV DOWN-RECONNECT @ POLE K72-497
110	8119792	Verona-H9321250041	11/15/2018 5:53:26 PM	11/17/2018 12:15:32 PM	11/18/2018 12:00:00 PM	TXOH: 33K-141: 26884484	-	1	4	CMP	Out-Dmg,Out	1	03 Vegetation	Unselected	44 Replaced Fuse	Florence	TOM GEIMAN 513-446-4723 - CHECK CSP OH TRF @ P# 33K-141E. SERVICE APPREAR TO BE CLEAR. TRAFFIC FLAGGING REQ'D
111	8119846	Constance-H9320420041	11/15/2018 9:29:48 AM	11/17/2018 5:30:00 PM	11/17/2018 6:45:00 PM	TXOH: 4BN-6: 26870972	-	1	7	CMP	PP-H-Tree-PH-Pl O,PH-H-Tree-PH-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 17:30:00 by T66296 RMK: pole # 4BN-6E One hot leg and neutral broke in service drop. bucket access PING OFF - REQ 8122420 as of 11/16/2018 9:24. ESphr 513-458-3803

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
112	8119943	Wilder-H9320590042	11/16/2018 8:51:31 PM	11/17/2018 2:35:00 PM	11/17/2018 3:48:00 PM	TXOH: CA11-492: 26898839	-	0	0	CMP	Out-Dmg	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 14:35:00 by T17494 RMK: R/ET PING ON - REQ 8123023 as of 11/16/2018 10:54. LIMB WAS ON LINE AND FIRE DEPT PUT OUT FIRE AND LIMB BURNED BUT LINE IS STILL ARCHING. ESphr 513-458-3803 Limb still tangled in OWS secondary. Truck accessabl
113	8119983	Villa-H9322430044	11/15/2018 6:11:55 PM	11/18/2018 11:13:46 AM	11/18/2018 12:00:00 PM	TXOH: K96-416: 26918653	-	0	1	CMP	PH-H-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	JOE GROESCHEN 859 250 0319 R-ET- WHEAD, SEC, SERV KNOB PULLED LOOSE FROM 3405 & 3407 MISTY CREEK DR. (DUPLX) - 1/0 ALTX SERVICE ON GROUND FROM POLE K96-416 SPOKE TO LANDLORD & ADVISE DUKE WILL DROP SERVICE TO MAKE SAFE & TO HIRE ELECTRICIAN/ REPAIR
114	8120008	Villa-H9322430041	11/15/2018 6:14:27 PM	11/16/2018 3:43:49 PM	11/18/2018 12:00:00 PM	FOH: K84-97: 366961125	-	92	65	CMP	Equip-E-911-Out-PF,Othr-H-On,Tree-PP-On,Out-Dmg,Out	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	R/TT THEY'VE BEEN NOTIFIED. 65T-NICK HAMILTON 513-240-8825. 2 LIMBS ON PRIMARY AND NEUTRAL BOTH SIDES OF POLE. K84-105E BEHIND 37 ARCADIA REAR LOT NON ACCESS. CUTOUT OPEN ON TAP POLE K84-97 DIXIE HIGHWAY
115	8120244	White Tower-H9323040042	11/15/2018 6:43:10 PM	11/16/2018 8:42:20 PM	11/18/2018 12:00:00 PM	TXOH: 22K-708: 26878239	-	0	1	CMP	PH-H-Othr-O-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	CUST. ENERGIZED. LOW LAYING 1/0ALTX SERVICE TO HOUSE FROM POLE # 22K-708E. CUST REPAIRS REQ'D - ADVISED CUST. ADDITIONALLY LIMB ON PRI LINE @ POLE # 22K-706E- L GROTHAUS - 513-906-0133 / 11/16/18 11AM. ALL CUSTOMERS ON. ADVISED THAT HE NEEDS ELECTRICIA
116	8120294	Beaver-H9320860041	11/15/2018 10:13:04 AM	11/17/2018 7:41:03 PM	11/18/2018 12:00:00 PM	TXOH: 49BN-48: 26870946	-	0	2	CMP	PP-H-Othr-O-On,PH-H-Tree-PH-Othr,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	TOM GEIMAN 513 446 4723 P# 49BN-48E LOW SERVICE (ZALTX) BROKEN SERVICE NEUT NEAR POLE. CUSTOMER HAS POWER...SERV NEUTRAL REPAIRED
117	8120535	Buffington-H9320670045	11/15/2018 8:41:03 AM	11/18/2018 2:20:50 PM		TXOH: K105-854: 26864442	-	0	2	CMP	PH-H-Othr,PH-H-On,Dmg-On	1	EA Weather	Unselected	22 Cut Off/Disconnect at Pole	Florence	R/E custM ORTH 859-300-4794. ENERGIZED SERVICE DOWN ACROSS STREET AT POLE K105-854. DISCONNECT SERVICE CUST TO MAKE REPAIRS. CUST NOTIFIED. M ORTH 859-300-4794. ENERGIZED SERVICE DOWN ACROSS STREET AT POLE K105-854. DISCONNECT SERVICE CUST TO MAKE REP
118	8120798	Verona-H9321250041	11/15/2018 8:20:13 PM	11/16/2018 10:01:00 PM	11/16/2018 10:00:00 PM	FOH: 34K-94: 25990300	25T	2	5	CMP	PH-H-911-Tree-PH-Othr,Othr-H-Obj-L-On,Out-Dmg,Out	1	03 Vegetation	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-16 22:01:00 by T22400 RMK: Tom Geiman 513-446-4723 25T FUSE BLOWN @ P# 34K-94E. TREE ON PRIM BTW P# 34K-265E & 266E. REAR LOT, REMAINING TAP APPEARS TO BE CLEAR
119	8121107	Donaldson-H9320550042	11/15/2018 9:24:33 PM	11/16/2018 5:30:00 PM	11/16/2018 5:45:00 PM	FOH: K104-171: 25994141	40T	43	31	CMP	Equip-E-Tree-PP-Out,Out-Dmg,Out-Othr-O,Out	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-16 17:30:00 by WACASSO RMK: ROB MILLER 513 543 8745 BKT TRK ACCESS 1 SPAN 1/0 PRIM DOWN K104-175 TO 183. K104-175 SM LIMB ON SVC. SEC DOWN & KNOB @ 3165,3151,3153 HICKORY-DISCONNECT SVC. 452 BIRCH LG LIMB ON SVC 40T BLOWN @ K104-171
120	8121450	Hebron-H9321520045	11/15/2018 7:34:14 AM	11/17/2018 3:20:00 PM	11/18/2018 12:00:00 PM	TXOH: 14BN-459: 26867330	-	3	7	CMP	PH-H-Tree-PH-Out,PH-H-Othr-O-On,Out-Dmg,Out	1	03 Vegetation	Unselected	49 Replaced Transformer	Florence	NICK HAMILTON 513-240-8825. SERVICE CABLE #2 AL TPX DOWN AT ADDRESS 2920 LIMABURG RD. SERVICE KNOB, SEC, AND WH PULLED OFF OF HOUSE. METER BASE/EQUIPMENT DETERIORATED. INFORMED CUSTOMER TO CALL ELECTRICIAN. FUSE AT TRANSFORMER BLOWN. 14BN-459
121	8121455	Wilder-H9320590041	11/16/2018 9:03:23 PM	11/17/2018 6:10:00 PM	11/18/2018 12:00:00 PM	TXOH: CA11-441: 26898672	-	0	0	CMP	Out-Dmg	1	03 Vegetation	Unselected	12 Checked Voltage/Fixed Connect	Florence	CMPL 2018-11-17 18:10:00 by T84692 RMK: R/ET Customer has made corrections and is ready for reconnect. PING OFF - REQ 8122478 as of 11/16/2018 9:32. ESphr 513-458-3803
122	8121657	Crescent-H9320700043	11/17/2018 7:40:54 AM	11/17/2018 5:48:00 PM	11/17/2018 7:00:00 PM	TXOH: K83-142: 26925838	-	0	0	CMP	Out-Dmg	1	EA Weather	Unselected	48 Replaced Service/Secondary	Florence	CMPL 2018-11-17 17:48:00 by T74214 RMK: PING OFF - REQ 8122467 as of 11/16/2018 9:30. ESphr 513-458-3803 - 11/17 - MANNING - 513-218-6533 - SERVICE REMOVED FROM POLE K83-142 TO HOUSE. CUST SERVICE IN AND OK - ERECT 100' OF 2ALTX
123	8121833	Richwood-H9321990043	11/16/2018 7:20:03 AM	11/18/2018 4:51:47 PM	11/18/2018 5:33:00 PM	TXOH: 41BN-340: 26891706	-	1	4	CMP	Out-Dmg,Out	1	EA Weather	Unselected	29 Permanent Repair	Florence	REFER TO CBT SEE NOTE. TREE BOSS NOTIFIED @ 0808. 65T FUSE BLOWN 41BN-39, P# 41BN-238E(45/4) BROKE(1PH DDE) & TRF DOWN (1PH, 25KVA)2 SPANS OF PRIM/NEUT DOWN (8ACU, 50' & 200') REAR LOT P#41BN-39, GRD AN TAGED 21414
124	8121860	Crittenden-H9321240041	11/16/2018 7:28:09 AM	11/17/2018 7:48:00 PM	11/17/2018 8:15:00 PM	TXOH: 37K-117: 358821010	-	1	2	CMP	Out-Dmg,Out	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 19:48:00 by T22838 RMK: TOM GEIMAN 513.446.4723 TRF FUSE BLOWN @ P#37K-115E (250' NORTH OF BARN) 2NDARY APPEARS TO BE CLEAR, REAR LOT - PING - OFF - REQ 8122373 as of 11/16/2018 9:16. ESphr 513-458-3803

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
125	8121997	White Tower-H9323040042	11/16/2018 7:59:12 AM	11/16/2018 8:44:02 PM	11/18/2018 12:00:00 PM	TXOH: 22K-985: 26878448	-	1	5	CMP	PH-H-LF-On,PH-H-On,Out-Dmg,Out,CIE,On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	1/0ALTX SERVICE FROM POLE # 22K-832 TO LEFT SIDE OF HOUSE, NEUTRAL BROKEN, ADVISED CUST. MINOR REPAIRS REQUIRED - NOT TRUCK ASSESSABLE - CUSTOMER HAS PARTIAL POWER - L GROTHAUS 513-906-0133 11/16/18 10AM. ALL POWER HAS BEEN RESTORED
126	8122007	Crescent-H9320700045	11/15/2018 6:56:00 AM	11/17/2018 9:20:00 AM	11/17/2018 11:00:00 AM	TXOH: K93-297: 26927170	-	33	22	CMP	PP-H-Tree-PP-Out,PH-H-Tree-PH-Out,PH-H-Other-O,PH-H-Other-Tree-PH-Out,S-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	27 Other/See Notes	Florence	CMP 2018-11-17 09:20:00 by T66296 RMK: PING OFF - REQ 8122179 as of 11/16/2018 8:37. Line down with tree branch on it. ESphr 513-458-3803 ROB MILLER 513 543 8745 40T BLOWN @ K92-194. SM LIMB ON PRIM @K93-294 REAR LOT BEHIND 2595 LAKE CT, 734 & 662
127	8122160	Crescent-H9320700045	11/16/2018 2:52:53 PM	11/17/2018 10:41:00 AM	11/17/2018 12:00:00 PM	TXOH: K92-189: 26915688	Retrofit 2/3/2014	0	0	CMP	Out-Dmg	1	03 Vegetation	Unselected	48 Replaced Service/Secondary	Florence	CMP 2018-11-17 10:41:00 by T66296 RMK: ROB MILLER 513 543 8745 BKT TRK ACCESS-BUSY RD SERVICE DOWN @ POLE K92-189C-RECONNECT SVC
128	8122189	Longbranch-H9320980042	11/16/2018 8:40:57 AM	11/17/2018 8:15:20 PM	11/18/2018 12:00:00 PM	TXUG: BNK-2907: 27159607	-	1	2	CMP	CC-H-911-Pole-L-Other,Out,Dmg-On	1	03 Vegetation	Unselected	47 Replaced Pole	Florence	DUPLICATE RFER TO EVENT-8122189-POLE# 35BN-249 SNAPPED AT BASE, 811 CONTACTED CONF# 1811170050, POLE LEANING AWAY FROM ROAD PRI POLE SNAPPED AT BASE, THREE SPAN ON POLE
129	8122196	Crescent-H9320700043	11/15/2018 4:38:46 PM	11/18/2018 11:00:00 AM	11/18/2018 12:00:00 PM	TXOH: K74-235: 26925094	-	0	2	CMP	PH-H-Tree-PH-On,PH-H-On,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	MANNING - 513-218-6533 -REAR LOT - TREE TRIMMING REQ'D - LARGE TREE ON ENERGIZED 1/0ALTX SERVICE FROM POLE K74-235 TO HOUSE. CUST HAS POWER, NEW RK1 INSTALLED, WILL NEED TO STRAP SEC & WH WHEN PUT BACK UP.
130	8122203	Richwood-H9321990042	11/15/2018 4:24:22 PM	11/16/2018 11:14:00 PM	11/18/2018 12:00:00 PM	TXOH: 36BN-328: 26887368	-	2	4	CMP	PH-H-Tree-PH-Out,PH-H-Obj-L-Other,Out,Dmg,Out,Pt O	1	EA Weather	Unselected	29 Permanent Repair	Florence	CMP 2018-11-16 23:14:00 by JWDVAV2 RMK: R-TREE TRIMMING, OH CREW, FLAGGING REQ'D, 2 SPANS 1/0ALTX SEC DWN P# 36BN-328E TO 36BN-329, 1 SPAN DUPLEX DWN, (2) SERVICES DWN (10220 & 10226 DIXIE HWY), 3RD SPAN SEC DWN 36BN-329 TO 36BN-56, L GROTHAUS 513-906
131	8122247	Longbranch-H9320980042	11/16/2018 8:51:34 AM	11/17/2018 10:56:00 PM	11/18/2018 12:00:00 PM	TXOH: 34BN-60: 26884555	-	0	1	CMP	PH-H-Tree-PH-Other,Dmg-On	1	11 Unknown Cause	Unselected	26 OK Arrival	Florence	ERIC MOORE 513-255-2120, TREE LIMB LAYING ON TRIPLEX, TRIPLEX LOW DUE TO HOUSE PIN OFF, STILL ENERGIZED, CAUTION TAPED AND CUSTOMER ON PREM R TO E
132	8122284	Villa-H9322430041	11/15/2018 6:30:39 PM	11/17/2018 10:50:00 AM	11/17/2018 12:00:00 PM	TXOH: K84-11: 26926090	-	15	6	CMP	Tree-PH-Out,Out-Dmg,Out	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMP 2018-11-17 10:50:00 by WACASSO RMK: NICK HAMILTON 513-240-8825 TROUBLE ON SITE. WILL CLEAR LIMB OFF WIRE. CLEAR BROKE WIRES. SECONDARY P-P DOWN K84-485 & K84-467. 1PH PRIMARY DOWN 2 SPANS K84-467 TO K84-13. FUSE BLOWN AT K84-13. GEISEN ST COMPLE
133	8122330	Hands-H9321280043	11/16/2018 9:07:28 AM	11/17/2018 7:34:08 PM	11/18/2018 12:00:00 PM	TXOH: 18K-360: 26876167	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	SMALL LIMB ON SERVICE TREE TRIMMING REQ'D. ALAN EAST 51-313-9220 TT COMPLETE
134	8122570	Crescent-H9320700045	11/15/2018 9:25:50 AM	11/17/2018 10:49:42 AM	11/18/2018 12:00:00 PM	TXOH: K92-350: 26915947	-	0	2	CMP	PH-H-Tree-PH-Other,PH-H-On,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	NICK HAMILTON 513-240-8825. SERVICE P-H DOWN. TREE FELL ON MESSENGER/BULL RING BETWEEN POLES K92-350 TO K92-349. CUSTOMER STILL HAS POWER. CREW JUST ARRIVED ON SITE
135	8122663	Villa-H9322430044	11/16/2018 9:55:52 AM	11/18/2018 9:16:00 AM	11/18/2018 12:00:00 PM	TXOH: K96-342: 26917125	-	0	1	CMP	PH-H-On,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMP 2018-11-18 09:16:00 by T23860 RMK: REFER TO E/T. TRIPLEX ON GROUND ENERGIZED. HOUSE KNOB AND WH PULLED OFF HOUSE. CUST TO HAVE ELEC TO REATTACH WH AND HOUSE KNOB. NEED TRIPLEX RESAGGED. REAR PROP. NO TRUCK ACCESS. R/ET NO CHANGE, NOTIFIED CUSTOMER
136	8122779	Crittenden-H9321240041	11/16/2018 10:13:21 AM	11/16/2018 4:45:00 PM	11/18/2018 12:00:00 PM	SolidBar: 5G-285: 25999079	BAR	80	29	CMP	Out-Dmg,Out	1	03 Vegetation	LH Tree limb, overhang	37 Removed Limb or Tree From Lin	Florence	CMP 2018-11-16 16:45:00 by T66296 RMK: TOM GEIMAN 513-446-4723, FUSE BLOWN @ 5G-285E, FLAGGING REQ'D. SMALL LIMB ON PRIM BTW P# 5G-385C & 386C REAR LOT. CHECK FUSE @ P# 5G-384E. SERVICE DOWN @ P# 5G-605E (1235 SHADY), REMAINING TAP APPEARS TO BE CLE
137	8122836	Marshall-H9323580041	11/16/2018 10:21:55 AM	11/17/2018 5:41:00 PM	11/17/2018 6:30:00 PM	TXOH: 35CA-702: 26885688	-	0	1	CMP	PH-H-Obj-L-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMP 2018-11-17 17:41:00 by T17494 RMK: SMALL BRANCH ON 1/0 SECONDARY. REMOVE BRANCH. KEVIN LANHAM 513-504-1488. TT COMPLETE
138	8122862	Crescent-H9320700044	11/16/2018 10:27:13 AM	11/18/2018 1:40:00 PM		TXUG: K93-B1-11: 26927412	-	0	1	CMP	Out-Dmg,LV-Other	1	11 Unknown Cause	Unselected	11 Checked Voltage/All OK	Florence	CMP 2018-11-18 13:40:00 by T29408 RMK: J GROESCHEN 859 250 0319 R-E/T DUKE EQUIPT APPEARS TO BE OK- METER FOR UNIT 20 IS ON- OTHER METERS IN BUILDING ON UNDERGROUND AREA IN APT COMPLEX. POSSIBLE UNDERGROUND SERVICE BURNED OUT SEND PREMISE TO CHEC

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
139	8123003	Marshall-H9320580041	11/16/2018 10:50:35 AM	11/17/2018 12:03:00 AM	11/18/2018 12:00:00 PM	TXOH: 35CA-1011: 26886813	-	0	0	CMP	Dmg-On	1	03 Vegetation	Unselected	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-17 00:03:00 by T17636 RMK: POLE # 35CA-1010C DROP # 4 TRI. SERVICE. REFERRED TO ELECTRIC CONTRACTOR. WEATHER HEAD. SERVICE ENTRANCE CABLE AND METER BASE. CUSTOMER CONTACT CARD
140	8123042	Donaldson-H9320550042	11/16/2018 10:55:20 AM	11/18/2018 9:03:00 AM	11/18/2018 12:00:00 PM	TXOH: K104-273: 26903859	-	0	1	CMP	Dmg-On,Othr-O-On	1	05 Planned (IEEE)	Unselected	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-18 09:03:00 by T74214 RMK: R/ET ROB MILLER 513 543 8745 MAKE PERM CONN @ WH RELEASE C-720147 repairs made ready to be hooked up per notes on order
141	8123216	Villa-H9322430041	11/16/2018 11:25:00 AM	11/17/2018 10:56:08 AM	11/18/2018 12:00:00 PM	TXOH: K85-70: 26914439	-	1	2	CMP	PH-H-Tree-PH-On,PH-H-Out,Out-Dmg	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	NICK HAMILTON 513-240-8825. SERVICE AT 35 PAUL HESSER DR IS DOWN. CUST. STILL HAS POWER. SERVICE KNOB ATTACHED TO HOUSE. WH AND SEC PULLED OFF. METER IN BASEMENT. CUSTOMER NEEDS ELECTRICIAN. POLE TO HOUSE. POLE K85-70C REAR LOT NO ACCESS
142	8123247	Verona-H9321250042	11/16/2018 11:29:33 AM	11/17/2018 4:29:35 PM	11/18/2018 12:00:00 PM	TXOH: 50BN-70: 26894099	-	1	2	CMP	Out-Dmg,PI O-MO,PI O	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	TOM GEIMAN 513.446.4723 -SERVICE NEUTAL BREAK(2ALTX, 90) @ P# 50BN-367E. CHECK CONNECTION, CUSTOMER HAS PARTIAL POWER. CUSTOMER WAS NOTIFIED OF ADDITIONAL REPAIRS REQ'D TO SERVICE THAT ARE NOT STORM RELATED.
143	8123386	Donaldson-H9320550043	11/16/2018 11:53:16 AM	11/17/2018 1:15:00 PM	11/18/2018 12:00:00 PM	TXOH: 21BN-385: 26877613	-	8	4	CMP	PH-H-Out,Out,Dmg-On	1	03 Vegetation	Unselected	20 Cut In/Reconnect at Pole	Florence	CMPL 2018-11-17 13:15:00 by CMTURNE RMK: RECONNECT ALTX SERVICE AT 21BN-385. SAG WIRE, CONN AT POLE AND HOUSE
144	8123590	Buffington-H9320670045	11/16/2018 9:33:22 PM	11/17/2018 5:52:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-449: 26904113	-	0	0	CMP	Out-Dmg	1	03 Vegetation	Unselected	19 Cut In/Reconnect at Weatherhe	Florence	CMPL 2018-11-17 17:52:00 by CMTURNE RMK: REATTACHED SERV. DAMAGE TO CUST WIRE & EQ. TEMP WEATHER HEAD. SERVICE OK TEMPO. CUST NOTIFIED. WILL MAKE REPAIRS AND CALL FOR COORD. BACK ON @1736.
145	8123768	KY Univ-H9322870042	11/16/2018 1:00:25 PM	11/17/2018 7:40:31 PM	11/18/2018 12:00:00 PM	TXOH: CA17-153: 26900336	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	REMOVE LIMB FROM TRIPLEX SERVICE. NO DAMAGE TO CUSTOMER FACILITIES OR TRIPLEXV. TRUCK ACCESSIBLE. 1 SPAN SOUTH OF CA17-133. KEVIN LANHAM 513-504-1488 TT COMPLETE
146	8124144	Buffington-H9320670045	11/16/2018 1:55:23 PM	11/17/2018 4:48:00 PM	11/18/2018 12:00:00 PM	TXOH: K117-305: 26907944	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-17 16:48:00 by T24175 RMK: another accessing crew on prem **sec pulled off house. rear property. no bucket access. NCC. REMOVED TREE AND PICKED SERV BACK UP
147	8124180	Donaldson-H9320550041	11/16/2018 2:01:58 PM	11/18/2018 1:01:25 PM		TXOH: K105-624: 26904767	-	0	1	CMP	PP-H-On,Dmg-On	1	EA Weather	Unselected	18 Customer Trouble/No Outage	Florence	R/E temp repair customer notified ROB MILLER 513 543 8745 BKT TRK ACC CUST SEC /RK1 PULKLED FROM HOUSE-ENERGIZED SVC ON GRND-DISCONNECT @ P#K105-624. DOOR HANGER LEFT FOR CUSTOMER
148	8124313	KY Univ-H9322870042	11/16/2018 2:33:24 PM	11/17/2018 7:35:00 PM	11/18/2018 12:00:00 PM	TXOH: 35CA-411: 26885823	-	0	1	CMP	PH-H-On,Dmg-On	1	28 Other Cause	Unselected	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-17 19:35:00 by CLWILLS RMK: SERVICE DROP PULLED FROM FRONT OF HOUSE. NO INSUL. KNOB CUSTOMER NOTIFIED. CUS HAS MADE TEMPO REPAIRS TO MAINTAIN SER
149	8124455	Crescent-H9320700041	11/16/2018 3:07:05 PM	11/17/2018 2:25:00 PM	11/17/2018 2:35:00 PM	FOH: K84-662: 25998568	65T	14	4	CMP	Out-Dmg,Out	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 14:25:00 by T25446 RMK: 2608 Marlo k84-658 has phase and neut down. Limb still hanging in way. could get a small bucket (with morals) to trim tree and repair wire
150	8124457	Beaver-H9320860041	11/16/2018 3:07:24 PM	11/17/2018 5:03:50 PM	11/18/2018 12:00:00 PM	TXOH: 50BN-198: 26920951	-	0	1	CMP	PH-H-Tree-PH-On,Dmg-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	TOM GEIMAN 513.446.4723 P#50BN-512E. LOW SERVICE (1/0ALTX), CUSTOMER REPAIRS REQ'D, CUSTOMER NOTIFIED
151	8124587	Buffington-H9320670045	11/16/2018 3:27:26 PM	11/17/2018 8:09:52 PM	11/18/2018 12:00:00 PM	TXOH: K106-1032: 26905689	-	0	1	CMP	PH-H-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	M.ORTH 859-300-4794. SPREADER STICK AT MID SPAN TAP BROKE AT POLE K106-1032. CUST HAS POWER. M.ORTH 859-300-4794. SPREADER STICK AT MID SPAN TAP BROKE AT POLE K106-1032. CUST HAS POWER. RE-ATTACHED SRV
152	8124700	Crittenden-H9321240042	11/16/2018 3:50:58 PM	11/18/2018 10:16:00 AM	11/18/2018 12:01:00 PM	TXOH: 5G-380: 26895819	-	0	1	CMP	Out-Dmg,Out	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-18 10:16:00 by T22838 RMK: TOM GEIMAN 513.446.4723- SERVICE DOWN (2ALTX) P# 5G-379C TRAFFIC FLAGGING REQ'D. CUSTOMER REPAIRS REQ'D, DOOR HANGER LEFT.
153	8124709	Buffington-H9320670045	11/16/2018 3:54:55 PM	11/17/2018 6:37:00 PM	11/18/2018 12:00:00 PM	TXOH: K116-678: 26907382	-	0	0	CMP	Dmg-On	1	03 Vegetation	Unselected	22 Cut Off/Disconnect at Pole	Florence	CMPL 2018-11-17 18:37:00 by T81490 RMK: WDPH T. GEIMAN 513.446.4723 P#K116-677E ENERGIZED SERVICE DOWN (2ALTX, 90) BLOCKING ST. JUDE STREET, CUSTOMER REPAIRS REQ'D, CUSTOMER NOTIFIED.
154	8124749	Villa-H9322430044	11/16/2018 4:06:51 PM	11/17/2018 4:05:00 PM	11/18/2018 12:00:00 PM	TXOH: K95-442: 26927656	-	0	1	CMP	Out-Dmg,Othr-O-On	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	NEUTRAL BROKE ON SERVICE AT POLE K95-442C. REAR LOT NO ACCESS. CUST HAS PARTIAL POWER.
155	8124860	Buffington-H9320670045	11/16/2018 4:30:38 PM	11/17/2018 12:42:42 PM	11/18/2018 12:00:00 PM	TXOH: K117-309: 26907950	-	1	1	CMP	PH-H-Out,Out-Dmg	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	T GEIMAN 513.447.4723 P# K117-309C REAR LOT. SERVICE DOWN (2ALTX, 105) @ 149 RAINTREE & LIMB ON SERVICE (2ALTX, 105) @ 151 RAINTREE. CUSTOMER REPAIRS REQ'D @ 151 RAINTREE. CUSTOMER NOTIFIED

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
156	8124990	Donaldson-H9320550041	11/16/2018 4:59:35 PM	11/17/2018 6:15:15 PM	11/18/2018 12:00:00 PM	TXOH: K116-367-26906736	-	1	3	CMP	PH-H-911-PF-Othr,CC-H-911-Out-Othr-O,Out.Dmg-On	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	ROB MILLER 513 543 8745 BKT TRK ACC CUST SEC DMG & RK1 PULLED OUT-DISC SERVICE POLE K116-367. LEFT DOOR HANGER FOR CUSTOMER. PING - REQ 8127520 - ON as of 3:42PM 11/17/18. See log. Caller states LIVE WIRE down on street & sidewalk. ABraun 513-458-3797
157	8125078	Constance-H9320420041	11/16/2018 5:21:09 PM	11/18/2018 9:43:08 AM	11/18/2018 12:00:00 PM	TXOH: 8BN-153-26871699	-	0	1	CMP	PP-H-On,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	one span of triplex down under tree. will need tree crew. bucket access avail. pole # 8BN-153C WORK COMPLETED
158	8125107	Crescent-H9320700043	11/16/2018 5:27:44 PM	11/17/2018 11:34:57 AM	11/18/2018 12:00:00 PM	TXOH: K73-88-26913077	-	1	3	CMP	Out-Dmg,Out,Othr-O-On	1	03 Vegetation	Unselected	29 Permanent Repair	Florence	ROB MILLER 513 543 8745 BKT TRK ACCESS @ ROAD-CUST INSTALLED NEW RK1 AND STRAPS ON SEC-RECONNECT @ POLE K73-87
159	8125123	Villa-H9322430044	11/15/2018 8:16:48 AM	11/17/2018 10:51:00 AM	11/17/2018 11:15:00 AM	TXOH: K96-221-26916777	-	3	5	CMP	PH-H-Tree-PH-On,PH-H-Out,PH-H-Othr,PH-H-On,Tree-PH-Out,Out-Dmg	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-17 10:51:00 by T25446 RMK: ROB MILLER 513 543 8745 REAR LOT REPLACE SERVICE NEED 40' 1/0 ALTX-CUST SEC OK
160	8125158	Richwood-H9321990042	11/16/2018 5:40:52 PM	11/18/2018 11:37:00 AM	11/18/2018 12:00:00 PM	TXOH: 35BN-1092-26863127	-	0	1	CMP	Pole-h-Othr,Dmg-On	1	09 Public Accident/Damage	Unselected	47 Replaced Pole	Florence	CMPL 2018-11-18 11:37:00 by T25446 RMK: TOM GEIMAN 513.446.4723 - AUTO DAMAGE P#35BN-249E (45/4, 3PH T/L) BROKE. 250' WEST OF GALILEO BLVD. KUPS ON SITE AS OF 12PM 11.17.18. TRAFFIC FLAGGING REQ'D
161	8125376	Crescent-H9320700043	11/16/2018 6:55:46 PM	11/17/2018 3:29:00 PM	11/18/2018 12:00:00 PM	TXOH: K83-242-26925640	-	1	4	CMP	PH-H-Tree-PH-On,PH-H-On,Pt O-VF,Dmg-On	1	03 Vegetation	Unselected	21 Cut Off/Disconnect at Weather	Florence	ROB MILLER 513 543 8745 REAR LOT SEC/KNOB PULLED OUT @ 84 & 86 BURDSALL. SVC ON GRND-DISCONNECT OWNERS NOTIFIED REPAIRS NEEDED
162	8125622	Crescent-H9320700044	11/16/2018 8:41:43 PM	11/17/2018 7:22:15 AM	11/18/2018 12:00:00 PM	TXOH: K83-596-26925388	-	1	1	CMP	Othr-H-Out-Othr-O,Othr-PQ,Dmg-On	1	28 Other Cause	Unselected	26 OK Arrival	Florence	J GROESCHEN 8592500319 IN/OK METER ON
163	8125900	Florence-H9322410042	11/17/2018 5:24:28 AM	11/17/2018 10:07:21 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-519-26881452	-	0	1	CMP	Out-Dmg,LF-Othr	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	Hamilton 51-6446-6232 Service drop has broken neutral in several places. rear property no bucket access. SERVICE GOOD. ELECTRIC GOOD. VOLTAGE GOOD
164	8126298	Crescent-H9320700043	11/17/2018 11:04:07 AM	11/17/2018 4:56:00 PM	11/17/2018 5:30:00 PM	TXOH: K72-10-26865111	-	0	0	CMP	Out-Dmg	1	EA Weather	Unselected	48 Replaced Service/Secondary	Florence	CMPL 2018-11-17 16:56:00 by T74214 RMK: MANNING - 513-218-6533 - 2ALTX SERVICE DOWN POLE K72-012 TO HOUSE - BROKE AT POLE- NEW ATTACHMENT KNOB INSTALLED. READY TO RESTORE
165	8126301	White Tower-H9323040041	11/17/2018 9:14:42 AM	11/17/2018 6:42:07 PM	11/18/2018 12:00:00 PM	TXOH: 22K-797-26878172	-	1	1	CMP	Pt O-LV,Dmg-On	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	NEUT BROKE AT POLE,REAR PROPERTY R/ET NEUTRAL SVC BROKE AT POLE 22K-797 REAR PROP NOT TRUCK ACCESSIBLE. ALAN EAST 513-313-9220. ALL REPAIRS HAVE BEEN MADE AND VOLTAGE IS NOW CORRECTED
166	8126334	Crescent-H9320700044	11/16/2018 6:22:23 PM	11/17/2018 12:20:08 PM	11/18/2018 12:00:00 PM	TXOH: K93-448-26927287	-	0	1	CMP	Tree-PP-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	NICK HAMILTON 513-240-8825. TREE LIMB ON DUPLEX SECONDARY BETWEEN POLE K93-448C AND POLE K93-453. NICK HAMILTON 513-240-8825. TREE LIMB ON DUPLEX SECONDARY BETWEEN POLE K93-448C AND POLE K93-453.
167	8126346	White Tower-H9323040041	11/17/2018 9:24:49 AM	11/18/2018 11:05:00 AM	11/18/2018 12:00:00 PM	TXOH: 26K-32-26881832	-	3	5	CMP	Othr-H-Tree-PH-On,Tree-PH-Out-VF,Out-Dmg,Out-LV,Out	1	20 Equipment failure	Unselected	11 Checked Voltage/All OK	Florence	CMPL 2018-11-18 11:05:00 by WACASSO RMK: R/ET BROKEN NEUTRAL ON SVC NEAR HOUSE. TRUCK ACCESSIBLE. ALAN EAST 513-313-9220
168	8126360	Beaver-H9320860041	11/17/2018 9:28:09 AM	11/17/2018 7:15:22 PM	11/18/2018 12:00:00 PM	TXOH: 49BN-23-26870924	-	0	1	CMP	Othr-H-Othr-O,Othr-PQ-On,Dmg-On	1	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	TRIPLEX NEUT SNAPPED AT LIFT POLE. TRIPLEX WAS TIED TO MAST WITH ROPE ON ARRIVAL. BUCKET ACCESSIBLE
169	8126377	Donaldson-H9320550041	11/16/2018 12:48:25 PM	11/17/2018 6:39:14 PM	11/18/2018 12:00:00 PM	TXOH: K116-280-26906632	-	0	2	CMP	PH-H-On,Tree-PP-On,Dmg-On	1	EA Weather	Unselected	35 OK per Phone Call	Florence	ROB MILLER 513 543 8745 CUST SEC & KNOB PULLED OUT-DISC SVC @ MIDSPAN ADJ POLE K116-135. CUST NOTIFIED branch on line across the road. the branch is causing the line to sag very low. customer has power
170	8126386	Crescent-H9320700043	11/16/2018 7:04:37 PM	11/17/2018 3:23:00 PM	11/18/2018 12:00:00 PM	TXOH: K84-302-26926589	-	4	7	CMP	PP-H-Tree-PP-On,PH-H-S-Out,Pt O,PH-H-Pt O-Othr-O,Othr-PQ,Othr-H-Othr-O-VF-Othr,Out-Dmg,Out,Pt O-VF,Pt O	1	03 Vegetation	Unselected	20 Cut In/Reconnect at Pole	Florence	TT EN ROUT - MANNING 513-218-6533 - REAR LOT - NEUTRAL BROKE MID-SPAN ON 1/0ALTX SERVICE - CUST HAS PARTIAL POWER
171	8126389	Hands-H9321280041	11/17/2018 9:40:29 AM	11/17/2018 5:27:00 PM	11/17/2018 6:00:00 PM	TXOH: 14K-410-26873750	-	0	2	CMP	PH-H-Tree-PH-On,Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 17:27:00 by T25446 RMK: R/ET 1/0 ALTX service on ground needs to be cut and rolled up to pole to allow customer to make repairs. rear lot, left door hanger. pole 14k-410 D.Wright 513-207-2228
172	8126421	Decoursey-H9322990041	11/17/2018 9:49:48 AM	11/17/2018 2:30:00 PM	11/17/2018 3:30:00 PM	TXOH: 11K-102-26862329	-	0	0	CMP	Dmg-On	1	03 Vegetation	Unselected	20 Cut In/Reconnect at Pole	Florence	CMPL 2018-11-17 14:30:00 by WACASSO RMK: R/ET ALAN EAST 513-313-9220
173	8126626	Villa-H9322430041	11/17/2018 11:47:58 AM	11/17/2018 9:14:03 PM	11/17/2018 11:21:00 PM	TXOH: K84-601-26926129	-	0	0	CMP	Out-Dmg	1	03 Vegetation	-	12 Checked Voltage/Fixed Connect	Florence	CMPL 2018-11-17 21:11:00 by T39767 RMK: ROB MILLER 513 543 8745 CUST REWIRED READY FOR RECONNECT -K84 601 SERVICE ROLLED UP ON POLE RELEASE C-729882

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
174	8126836	Bellevue-H9321310043	11/17/2018 1:14:57 PM	11/17/2018 5:41:00 PM	11/17/2018 6:15:00 PM	TXOH: CA8-188-26922052	-	0	0	CMP	Out-Dmg	1	03 Vegetation	Unselected	20 Cut In/Reconnect at Pole	Florence	CMPL 2018-11-17 17:41:00 by CAMUSTA RMK: pole CA8-188 reattach #4 tpx to midspan cust eq ok meter in basement service coiled at cust home Tyler Burns 513-335-2291 pole CA - MANNING - 513-218-6533 - SERVICES FOR 121 & 117 HARTWG WERE CUT LOOSE. REPAIRS
175	8126900	Florence-H9322410046	11/17/2018 12:29:14 PM	11/18/2018 3:14:42 PM		TXOH: 31BN-468-26863024	-	0	1	CMP	Dmg-On,On	1	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	crossarm bracket broken on pole 31BN-168 rear prop. custs are still in service.bucket & tree crews needed. spand runs behind 109 - 117 dlrstr dr
176	8127065	Covington KY-H9322170041	11/17/2018 1:22:50 PM	11/17/2018 6:41:00 PM	11/17/2018 7:30:00 PM	TXOH: K51-756-26908086	-	0	0	CMP	Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Covington	CMPL 2018-11-17 18:41:00 by T25446 RMK: R/ET 2 ALTX. SPLICE NEUTRAL AND ONE LEG. POLE # K51-1522. TRUCK ACCESSIBLE. 1 WAY STREET NO FLAGGING REQUIRED. MULTIPLE SERVICES FROM POLE TO BUILDING ONLY CONDO #120 IS DAMAGED. D.WRIGHT 513-207-2228
177	8127110	Donaldson-H9320550041	11/17/2018 1:37:16 PM	11/18/2018 1:08:55 PM		TXOH: K116-280-26906632	-	0	1	CMP	PP-H-Tree-PP-On,Dmg-On	1	EA Weather	Unselected	18 Customer Trouble/No Outage	Florence	R/E 114 Lloyd perm. 117 Lloyd temp repair cust. notified ROB MILLER 513 543 8745 R T/T LG LIMB ON SVC-CUST SEC IN & OK CUST HAS PWR BKT TRK ACC FLAGGING-BUSY STREET
178	8127207	Crescent-H9320700044	11/17/2018 2:09:43 PM	11/17/2018 10:31:00 PM	11/18/2018 12:00:00 PM	TXOH: K92-41-26915966	-	0	1	CMP	Tree-PP-On,Dmg-On	1	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 22:31:00 by T18514 RMK: removed limb
179	8127216	Donaldson-H9320550042	11/17/2018 2:11:43 PM	11/18/2018 8:30:00 AM	11/18/2018 9:30:00 AM	TXOH: K104-174-26903841	-	0	0	CMP	Dmg-On	1	05 Planned (IEEE)	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-18 08:30:00 by T74214 RMK: ROB MILLER 513 543 8745 CUST INSTALLED NEW SEC MAKE PERM CONN-HOLD FOR RELEASE
180	8127451	Longbranch-H9320980041	11/17/2018 3:22:18 PM	11/18/2018 10:30:00 AM	11/18/2018 12:00:00 PM	TXUG: BNK-800-27080467	-	0	1	CMP	Dmg-On,Othr	1	28 Other Cause	Unselected	12 Checked Voltage/Fixed Connect	Florence	CMPL 2018-11-18 10:30:00 by T95129 RMK: 122/122/245 W/LOAD
181	8127464	Buffington-H9320670045	11/17/2018 3:24:19 PM	11/18/2018 4:07:03 PM	11/18/2018 5:38:00 PM	TXOH: K105-718-26904717	-	1	2	CMP	Out-Dmg,Out,Othr-O-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	PING OFF - Req 8127470 as of 15:26 on 11/17/18 jrcraig 1 513.458.3791 - power is out repairs made ready for re-connect according to order notes-JOE GROESCHEN 8592500319 REPAIRS MADE READY TO BE ENERGIZED #4ALTX COILED UP ON GROUND BY METER BASE
182	8127601	Villa-H9322430044	11/17/2018 4:12:08 PM	11/18/2018 1:35:00 PM	11/18/2018 2:30:00 PM	TXOH: K96-348-26917319	-	0	1	CMP	PH-H-Othr,Dmg-On	1	EA Weather	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-18 13:35:00 by T74214 RMK: M.ORTH 859-300-4794. NEU BROKEN ON #2ALTX AT POLE K96-349. NEED 70' OF #2ALTX. REAR PROPERTY ENTER AT GATE ON LEFT SIDE OF 3249. M.ORTH 859-300-4794. NEU BROKEN ON #2ALTX AT POLE K96-349. NEED 70' OF #2ALTX. REAR
183	8127719	Crescent-H9320700041	11/17/2018 4:52:55 PM	11/18/2018 9:50:55 AM	11/18/2018 12:00:00 PM	TXOH: K84-437-26926614	-	1	3	CMP	PH-H-Tree-PH-Othr,PH-H-Tree-PH-On,PH-H-MO-Othr,Dmg-On	1	04 Wildlife	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-18 09:45:00 by T29408 RMK: ROB MILLER 513 543 8745 WORK IS REAR LOT BEHIND 19 MIAMI-SVC FROM MIDSPAN HAS BROKE NEUT & SM LIMB ON-CUST SEC IN & OK
184	8127753	Buffington-H9320670045	11/17/2018 5:00:51 PM	11/17/2018 7:57:29 PM	11/18/2018 12:00:00 PM	TXOH: K117-527-26907490	-	2	2	CMP	Othr-H-Out-Othr-O,Out-Dmg,Out	1	28 Other Cause	Unselected	27 Other/See Notes	Florence	R/ET TRANSFORMER FUSE BLOWN POLE ON POLE K117-527 REAR LOT NOT TRUCK ACCESSIBLE. CUST STATES SQUIREL GOT INTO BUSHINGS. NEED NEW FUSE AND ANIMAL GUARDS. ALAN EAST 513-313-9220. OKAY ON ARRIVAL
185	8107803	Crescent-H9320700044	11/15/2018 6:18:34 AM	11/15/2018 6:18:34 AM		S-RCL: 11430: K93-59: 107815355	-	131	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	-
186	8107804	Crescent-H9320700044	11/15/2018 6:18:34 AM	11/15/2018 6:18:37 AM		S-RCL: 11430: K93-59: 107815355	-	218	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	-
187	8107816	Crittenden-H9321240041	11/15/2018 6:19:22 AM	11/17/2018 2:54:52 PM	11/18/2018 12:00:00 PM	TXOH: 5G-646-26895579	-	0	1	CMP	Equip-E-911-PF-Othr	0	03 Vegetation	Unselected	26 OK Arrival	Florence	-
188	8107842	Mt Zion-H9323050043	11/15/2018 6:20:49 AM	11/15/2018 3:50:00 PM	11/15/2018 4:45:00 PM	FOH: 36BN-252-25990782	65T	59	40	CMP	Othr-H-Out-Pole-L,Out-Pole-L,Out	0	03 Vegetation	EA Cause Not Coded in Weather	17 Closed Switch	Florence	CMPL 2018-11-15 15:50:00 by T56235 RMK: Removed tree limb off of 1/0 phase and neut at pole 36BN-738 Closed tap fuse phase B pole36BN-252
189	8107844	Buffington-H9320670045	11/15/2018 6:20:51 AM	11/17/2018 6:45:50 AM	11/18/2018 12:00:00 PM	TXOH: K117-378-26907769	-	1	2	CMP	PH-H-Out,Tree-PH-Othr	0	03 Vegetation	Unselected	26 OK Arrival	Florence	PING ON-REQ 8125937-ON as of 6:28AM 11/17/18 ZWysins 513-458-3806
190	8107915	Wilder-H9320590041	11/15/2018 6:25:16 AM	11/15/2018 2:35:00 PM	11/15/2018 2:45:00 PM	TXOH: CA10-833-26897587	-	0	1	CMP	PH-H-On	0	03 Vegetation	-	26 OK Arrival	Florence	CMPL 2018-11-15 14:35:00 by T25680 RMK: removed limb
191	8107919	Empire-H9322890041	11/15/2018 6:25:50 AM	11/17/2018 5:56:03 PM	11/18/2018 12:00:00 PM	TXOH: 31BN-774-26884037	-	0	1	CMP	PP-H-911-Tree-PP-Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ok arrival. this is actually919 weaver rd. and evergreen is own electric. no wire down here
192	8107928	Crescent-H9320700045	11/15/2018 6:26:50 AM	11/17/2018 9:04:53 AM	11/18/2018 12:00:00 PM	TXOH: K92-115-26915724	Retrofit 1/22/2014	1	5	CMP	PH-H-Tree-PH-Pi O,Othr,On	0	03 Vegetation	Unselected	26 OK Arrival	Florence	PING ON-REQ 8125939-ON as of 6:29AM 11/17/18 ZWysins 513-458-3806- NICK HAMILTON 513-240-8825 SERVICE IN/OK
193	8107932	Claryville-H9321470042	11/15/2018 6:27:19 AM	11/16/2018 2:33:52 PM	11/18/2018 12:00:00 PM	FOH: 47CA-360-26050896	65T	75	14	CMP	PP-H-911-Out,Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ALL CST'S HAVE POWER.
194	8107937	Wilder-H9320590046	11/15/2018 6:27:36 AM	11/15/2018 5:11:51 PM		TXOH: CA11-767-26898610	-	7	3	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	in & ok - CUSTOMER CONTACT MADE - L GROTHAUS 5:11PM
195	8107967	Beaver-H9320860041	11/15/2018 6:27:32 AM	11/15/2018 6:46:12 AM		S-RCL: 50BN-474-412692188	-	72	1	S-CMP	Out	0	03 Vegetation	03 Tree (Vegetation)	44 Replaced Fuse	Florence	CMPL 2018-11-15 08:00:00 by T66296 RMK: REMOVED TREE OFF PH &NUET
196	8108022	Villa-H9322430044	11/15/2018 6:32:04 AM	11/17/2018 7:35:00 PM	11/18/2018 12:00:00 PM	TXOH: K106-664-26905809	-	1	3	CMP	PP-H-911-Tree-PP-Othr,PH-H-Out,Out	0	03 Vegetation	Unselected	20 Cut In/Reconnect at Pole	Florence	CMPL 2018-11-17 19:35:00 by CAMUSTA RMK: PING OFF-REQ 8125941-OFF as of 6:32AM 11/17/18 ZWysins 513-458-3806. Tree on lines. was on fire

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
197	8108119	Marshall-H9323580041	11/15/2018 6:36:46 AM	11/15/2018 1:06:00 PM	11/15/2018 2:00:00 PM	FUG: 35CA-1751: 25990592	-	130	43	CMP	Out,Pt O	0	03 Vegetation	03 Tree (Vegetation)	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-15 13:06:00 by T66296 RMK: REMOVED TREE
198	8108136	White Tower-H9323040043	11/15/2018 6:38:00 AM	11/16/2018 4:28:14 PM	11/18/2018 12:00:00 PM	TXOH: 19K-764: 26877171	-	0	1	CMP	PH-H-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	-
199	8108148	Crescent-H9320700041	11/15/2018 6:38:41 AM	11/16/2018 7:54:30 PM	11/18/2018 12:00:00 PM	TXOH: K84-702: 26865962	-	10	7	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
200	8108184	Villa-H9322430041	11/15/2018 6:40:09 AM	11/16/2018 4:53:53 PM	11/18/2018 12:00:00 PM	FOH: K85-170: 26048537	65T	18	24	CMP	PP-H-Out,PP-H-Othr,PH-H-Out,Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	-
201	8108212	Bellevue-H9321310043	11/15/2018 6:41:19 AM	11/16/2018 12:43:00 PM	11/18/2018 12:00:00 PM	FUG: CA8-426: 370718397	-	27	18	CMP	PP-H-Out-Othr-O,Out-S-Out,Out	0	-	Unselected	26 OK Arrival	Florence	25T
202	8108223	Donaldson-H9320550042	11/15/2018 6:35:10 AM	11/16/2018 5:02:00 PM	11/18/2018 12:00:00 PM	TXOH: K104-182: 26903763	-	0	6	CMP	Equip-E-911-PF-Othr,PP-H-911-Othr,PH-H-Tree-PH-On,PH-H-On,Tree-PP-On,Tree-PH-On	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-16 17:02:00 by T22595 RMK: Line still down across street blew transformer, limb still on wire. DUKE CREWS ON SITE
203	8108231	Kenton-H9320090044	11/15/2018 6:42:04 AM	11/15/2018 9:51:00 PM	11/15/2018 10:31:00 PM	FOH: K73-224: 85184562	-	83	51	CMP	Out	0	03 Vegetation	EA Cause Not Coded in Weather	56 Sectionalized/Restored Serv	Florence	CMPL 2018-11-15 21:51:00 by T33303 RMK: WIRE DOWN REAR OF 1420 HENRY CLAY POLE # K63-25C BREAKS CUT AT POLE# K63-23C GROUND TAG # 20549
204	8108255	Marshall-H9323580041	11/15/2018 6:42:59 AM	11/16/2018 1:46:00 PM	11/15/2018 2:00:00 PM	FUG: 35CA-1403: 25990580	65T	18	10	CMP	Out	0	03 Vegetation	-	11 Checked Voltage/All OK	Florence	CMPL 2018-11-16 13:46:00 by T39767 RMK: -]
205	8108304	Buffington-H9320670045	11/15/2018 6:45:23 AM	11/17/2018 7:48:03 PM	11/18/2018 12:00:00 PM	TXOH: K116-228: 26907305	-	1	1	CMP	PP-H-Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	PING ON-REQ 8125943-ON as of 6:30AM 11/17/18 ZWysins 513-458-3806. Lines down at this address. power out next door. DOWN SERVICE HAS BEEN REPAIRED
206	8108324	Villa-H9322430044	11/15/2018 6:46:32 AM	11/16/2018 8:31:59 PM	11/18/2018 12:00:00 PM	TXOH: K95-455: 26927695	-	1	2	CMP	PH-H-Tree-PH-Out,PH-H-911-PF-Othr	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	THIS CALL WAS OKAY ON ARRIVAL
207	8108342	Augustine-H9320780043	11/15/2018 6:47:17 AM	11/16/2018 10:41:00 PM	11/18/2018 12:00:00 PM	TXOH: K52-832: 26908757	-	9	2	CMP	PP-H-911-Out-PF,PP-H-911-Out	0	03 Vegetation	-	22 Cut Off/Disconnect at Pole	Covington	CMPL 2018-11-16 22:41:00 by T17410 RMK: remove 100' #2tri, down by tree, refer to electrician for repairs @ 1113 Gerrard
208	8108349	Buffington-H9320670045	11/15/2018 6:47:57 AM	11/17/2018 4:50:49 PM	11/18/2018 12:00:00 PM	TXOH: K106-240: 26905474	-	1	6	CMP	PH-H-Tree-PH-Out,PH-H-Out,Othr-H-Out,Out	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	PING OFF-REQ 8125944-OFF as of 6:34AM 11/17/18 ZWysins 513-458-3806. Down lines on van
209	8108350	Buffington-H9320670045	11/15/2018 6:48:06 AM	11/15/2018 6:48:07 AM		S-RCL: 4991: K106-115: 84304128	-	722	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	-
210	8108352	Marshall-H9323580041	11/15/2018 6:48:08 AM	11/15/2018 1:06:00 PM	11/15/2018 2:00:00 PM	FUG: 35CA-1706: 25990568	65T	20	8	CMP	Out	0	03 Vegetation	-	44 Replaced Fuse	Florence	CMPL 2018-11-15 13:06:00 by T66296 RMK: REMOVED TREE
211	8108367	Buffington-H9320670045	11/15/2018 6:48:46 AM	11/17/2018 5:08:59 PM	11/18/2018 12:00:00 PM	TXOH: K116-357: 26907319	-	0	1	CMP	PH-H-911-PF-Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ok arrival. everything has been put back up and cust's are in service
212	8108368	Richwood-H9321990042	11/15/2018 6:48:54 AM	11/15/2018 6:48:58 AM		S-RCL: 511: BNK-5618: 112919424	Programmed as 800 A Recl	375	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	-
213	8108393	Decoursey-H9322990041	11/15/2018 6:50:22 AM	11/16/2018 8:45:00 AM	11/16/2018 9:30:00 AM	FOH: 11K-99: 25987494	65T	46	10	CMP	PP-H-Out-PF,PP-H-Out,Out	0	03 Vegetation	Unselected	26 OK Arrival	Florence	CMPL 2018-11-16 08:45:00 by T40067 RMK: 65T
214	8108418	Wilder-H9320590046	11/15/2018 6:51:41 AM	11/15/2018 5:36:07 PM		TXOH: CA14-237: 26899564	-	1	1	CMP	PH-H-911-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK - L GROTHAUS 5:30PM
215	8108429	Buffington-H9320670045	11/15/2018 6:52:08 AM	11/15/2018 7:05:57 PM		FOH: K106-309: 26048822	65T	181	73	CMP	Equip-E-Othr,PP-H-911-Tree-PP-Out,PP-H-911-Out-PF,PP-H-Out,PH-H-Out,Out	0	03 Vegetation	Unselected	Unselected	Florence	-
216	8108444	Hebron-H9321520045	11/15/2018 6:53:12 AM	11/15/2018 9:05:00 PM	11/15/2018 9:30:00 PM	FOH:25986195	65T	9	13	CMP	PH-H-Out,Out	0	03 Vegetation	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-15 21:05:00 by WACASSO RMK: REMOVED TREE OFF 2 PHASES
217	8108464	Marshall-H9323580041	11/15/2018 6:54:00 AM	11/17/2018 8:05:46 AM	11/18/2018 12:00:00 PM	TXUG: 35CA-HF-1: 26886411	-	0	1	CMP	Equip-E-911-PF-Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OK ARRIVAL
218	8108480	Villa-H9322430041	11/15/2018 6:55:09 AM	11/15/2018 6:55:11 AM		S-RCL: 4226: K74-84: 164009350	-	29	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	-
219	8108563	Crescent-H9320700043	11/15/2018 6:58:45 AM	11/16/2018 10:42:18 AM	11/18/2018 12:00:00 PM	FOH: K73-42: 25995711	65T	9	6	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NICK HAMILTON 513-240-8825 SERVICE IN/OK.
220	8108606	Villa-H9322430041	11/15/2018 7:01:43 AM	11/16/2018 9:04:30 PM	11/16/2018 10:00:00 PM	FOH: K74-45: 25998250	65T	32	32	CMP	PP-H-Out,Out	0	03 Vegetation	-	-	Florence	KENTON 41 PH BC DWN BTWK74-52-53 I/O ALUM OPEN PH A @K74-45 FOR SAFETY
221	8108656	Crescent-H9320700043	11/15/2018 7:04:19 AM	11/16/2018 11:25:00 AM	11/18/2018 12:00:00 PM	FOH: K73-480: 370546721	-	31	30	CMP	PP-H-Out,Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-16 11:25:00 by WACASSO RMK: 65T
222	8108710	Verona-H9321250042	11/15/2018 7:06:15 AM	11/15/2018 3:40:00 PM		TXOH: 50BN-105: 26894225	-	1	1	CMP	Tree-PH-Out	0	03 Vegetation	-	12 Checked Voltage/Fixed Connect	Florence	CMPL 2018-11-15 15:40:00 by PNLAUER RMK: rehung triplex at pole
223	8108738	Bellevue-H9321310041	11/15/2018 7:07:09 AM	11/15/2018 9:30:01 AM		TXOH: CA4-181: 26930892	-	0	1	CMP	PP-H-Othr-O-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN/OK J GROESCHEN 8592500319 CATV LINE ON CAR NOT DUKE
224	8108763	Villa-H9322430044	11/15/2018 7:08:02 AM	11/17/2018 3:30:00 PM	11/18/2018 12:00:00 PM	TXOH: K95-153: 26927892	-	1	1	CMP	PP-H-911-Out	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	PING ON-REQ 8125945-ON as of 6:29AM 11/17/18 ZWysins 513-458-3806. Line down across car
225	8108843	Villa-H9322430041	11/15/2018 7:10:53 AM	11/15/2018 3:22:00 PM	11/15/2018 4:00:00 PM	FOH: K84-6: 366961119	-	136	27	CMP	PP-H-911-Out,Out	0	EA Weather	28 Other Failure Mode	17 Closed Switch	Florence	CMPL 2018-11-15 15:22:00 by T25446 RMK: removed tree from primary, closed cutout 140T @1522
226	8108852	Limaburg-H9321890042	11/15/2018 7:11:18 AM	11/17/2018 7:30:27 PM	11/18/2018 12:00:00 PM	TXOH: 23BN-180: 26869045	-	0	1	CMP	PH-H-Tree-PH-On	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	BRANCH ON GARAGE AND HAD SERVICE WIRE PINNED DOWN. BRANCH REMOVED.

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
543	8115607	Richwood-H9321990042	11/15/2018 12:15:25 PM	11/17/2018 11:24:37 AM	11/18/2018 12:00:00 PM	TXUG: 36BN-1374: 26888221		1	1	CMP	Tree-PP-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK AS OF 11:21 AM TOM GEIMAN 513.446.4723. PING ON - REQ 8123677 as of 11/16/2018 12:50. line down pole to pole between houses in back. branch behind house fell and hit line. pole to pole in line branches have taken wires down. ESphr 513-458-380
544	8115718	Verona-H9321250042	11/15/2018 12:21:58 PM	11/17/2018 1:22:09 PM	11/18/2018 12:00:00 PM	TXUG: BNK-2114: 27111143		0	1	CMP	Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK AS OF 1:18 PM ON 11.17.18 TOM GEIMAN 513.446.4723
545	8115890	Florence-H9322410045	11/15/2018 12:34:40 PM	11/17/2018 4:25:00 PM	11/17/2018 4:30:00 PM	TXOH: 26882261		1	1	CMP	PH-H-Tree-PH-PI O	0	11 Unknown Cause	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-17 16:25:00 by T81490 RMK: PING OFF - REQ 8123675 as of 11/16/2018 12:53 in front yard. ESphr 513-458-3803
546	8115898	Donaldson-H9320550041	11/15/2018 12:34:55 PM	11/17/2018 2:26:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-98: 26904711		0	1	CMP	PP-H-On	0	03 Vegetation	Unselected	22 Cut Off/Disconnect at Pole	Florence	CMPL 2018-11-17 14:26:00 by CMTURNE RMK: TWP, TORE SERV ENTRANCE AND MAST OFF BLDG. NO TEMPO. DISC FOR SAFTEY. CUST TO MAKE REPAIRS. NOTIFIED.
547	8115916	Bellevue-H9321310043	11/15/2018 12:35:46 PM	11/15/2018 3:45:00 PM	11/15/2018 4:30:00 PM	TXUG: CA7-783: 27107747		30	3	CMP	Out-S-Out,Out	0	28 Other Cause	-	44 Replaced Fuse	Florence	CMPL 2018-11-15 15:45:00 by T17410 RMK: 65t overloaded, replace with 100t
548	8116092	Claryville-H9321470042	11/15/2018 12:50:20 PM	11/17/2018 12:33:24 PM	11/18/2018 12:00:00 PM	TXOH: 47CA-64: 26893226		0	1	CMP	Obj-L-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	approx 12' broke off branch hanging on serv wire pole-house needs to be removed
549	8116121	Augustine-H9320780043	11/15/2018 12:52:21 PM	11/17/2018 2:34:00 AM	11/17/2018 2:00:00 AM	TXUG: KNK-5402: 362821615		1	8	CMP	Out	0	09 Public Accident/Dam age	Unselected	44 Replaced Fuse	Covington	CMPL 2018-11-17 02:34:00 by T18514 RMK: PING OFF - REQ 8123668 as of 11/16/2018 12:53. power out at location. ESphr 513-458-3803 RESTORED @ 2:00 AM WITH 1318 MADISON 2 6ST @ KNK 5786 DUE TO BUDWEISER TRUCK STRIKING POLE
550	8116275	Crescent-H9320700043	11/15/2018 1:03:18 PM	11/17/2018 8:46:28 AM	11/18/2018 12:00:00 PM	TXOH: K83-648: 26925645		0	1	CMP	Tree-PH-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	MANNING - 513-218-6533 - OK ARRIVAL
551	8116310	Buffington-H9320670045	11/15/2018 12:11:45 PM	11/17/2018 3:50:51 PM	11/18/2018 12:00:00 PM	TXUG: KNK-1601: 27107468		0	2	CMP	PP-H-Othr-O-On On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	M ORTH 859-300-4794. IN & OK.
552	8116371	Crescent-H9320700043	11/15/2018 8:24:10 AM	11/16/2018 6:19:35 PM	11/18/2018 12:00:00 PM	TXOH: K73-45: 26912703		6	3	CMP	PH-H-Tree-PH-Tree-PH-PI O,PH-H-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	CUSTOMER NEEDS NEW WH- CUST ADVISED TO MAKE REPAIRS AND CALL BACK WHEN READY-SVC CURRENTLY TEMPED IN AND NEEDS TO BE TRANSFERED TO NEW RK1CUST HAS INSTALLED
553	8116408	Villa-H9322430041	11/15/2018 1:12:46 PM	11/17/2018 11:10:55 AM	11/18/2018 12:00:00 PM	TXOH: K94-367: 26926790		0	1	CMP	PH-H-Tree-PH-MO-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ROB MILLER 513 543 8745 IN & OK
554	8116443	Villa-H9322430043	11/15/2018 1:14:55 PM	11/15/2018 8:08:00 PM	11/15/2018 8:25:00 PM	TXOH: K96-299: 26916554		0	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	-	25 No Problem Found	Florence	CMPL 2018-11-15 20:08:00 by T25680 RMK: not a problem, limb touching secondaries not laying on. RECL 4991 Oil
555	8116457	Buffington-H9320670045	11/15/2018 1:16:00 PM	11/15/2018 1:17:43 PM		S-RCL: 4991: K106-115: 84304128		395	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	
556	8116481	Augustine-H9320780041	11/15/2018 1:17:18 PM	11/15/2018 2:31:32 PM		TXOH: K60-321: 26909949		0	1	CMP	Othr-O-On	0	28 Other Cause	Unselected	26 OK Arrival	Covington	In & Ok - spoke to customer onsite - L Grothaus
557	8116515	Hands-H9321280041	11/15/2018 12:01:14 PM	11/17/2018 7:52:41 PM	11/18/2018 12:00:00 PM	TXOH: 14K-524: 26873872		0	2	CMP	PH-H-On,Tree-PH-On	0	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	LIMB BROKE OFF TREE AND IS ON TRI-PLEX VERY HEAVY.NEEDS REMOVED
558	8116527	Crittenden-H9321240041	11/15/2018 1:20:38 PM	11/15/2018 1:20:42 PM		S-RCL: 7448: GRK-1435: 53005153		446	0	M-CMP	-	0	-	-	-	Florence	-
559	8116543	Marshall-H9323580041	11/15/2018 6:37:14 AM	11/15/2018 7:45:00 PM	11/15/2018 8:45:00 PM	FUG: 35CA-1751: 25990592		130	98	CMP	Out-S-Out,Out,Pt O	0	11 Unknown Cause	28 Other Failure Mode	17 Closed Switch	Florence	CMPL 2018-11-15 19:45:00 by T66296 RMK: SPOKE TO CUST, BACK OUT BLOWN FUSE ON TP OVER LOAD ON FUSE
560	8116588	Dixie-H9320890042	11/15/2018 8:59:42 AM	11/17/2018 8:07:00 PM	11/18/2018 12:00:00 PM	TXUG: 31BN-38: 26883875		1	3	CMP	PP-H-Tree-PP-Out Othr-PQ-Out	0	EA Weather	Unselected	26 OK Arrival	Florence	
561	8116638	Cold Spring-H9321320041	11/15/2018 1:27:54 PM	11/15/2018 9:48:00 PM	11/18/2018 12:00:00 PM	TXOH: 43CA-877: 26892000		0	1	CMP	Tree-PH-On	0	28 Other Cause	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-15 21:48:00 by T27867 RMK: CUST CALLED ABOUT LIMB OVER SECONDARY LINE POLE/HOUSE.LIMB NOT BROKE OR TOUCHING LINES. OK NO PROBLEM
562	8116644	Villa-H9322430041	11/15/2018 1:28:11 PM	11/15/2018 8:43:55 PM		TXUG: K85-A2-21: 26914280		0	1	CMP	Trap-E-911-On	0	EA Weather	Unselected	Unselected	Florence	-
563	8116659	Donaldson-H9320550041	11/15/2018 1:29:35 PM	11/17/2018 6:28:00 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-1134: 26880948		0	2	CMP	PH-H-Othr-O-On,PH-H-On	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	-
564	8116666	Villa-H9322430041	11/15/2018 10:52:35 AM	11/16/2018 10:18:21 AM	11/18/2018 12:00:00 PM	TXOH: K94-68: 26916406		0	2	CMP	Othr-H-Othr-O-On On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NICK HAMILTON 513-240-8825 SERVICE IN/OK.
565	8116746	Buffington-H9320670045	11/15/2018 1:35:29 PM	11/17/2018 4:49:31 PM	11/18/2018 12:00:00 PM	TXOH: K106-253: 26905511		1	2	CMP	PH-H-911-Out,PH-H-Othr	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	PING ON - REQ 8123665 as of 11/16/2018 12:48.lines pulled from house. ESphr 513-458-3803
566	8116755	Verona-H9321250042	11/15/2018 1:35:39 PM	11/17/2018 5:04:36 PM	11/18/2018 12:00:00 PM	TXOH: 50BN-105: 26894225		1	1	CMP	PH-H-Tree-PH-Out	0	28 Other Cause	Unselected	30 Phone or TV Cable Problem	Florence	PING OFF - REQ 8123662 as of 11/16/2018 12:51. line is on the ground, elderly cust on prem. ESphr 513-458-3803
567	8116764	Bellevue-H9321310043	11/15/2018 1:36:14 PM	11/17/2018 10:19:38 AM	11/18/2018 12:00:00 PM	TXOH: CA7-292: 26902290		0	1	CMP	PH-H-On	0	03 Vegetation	Unselected	30 Phone or TV Cable Problem	Florence	per customer line is low and is only being held up by tree
568	8116779	M Zion-H9323050043	11/15/2018 1:37:09 PM	11/16/2018 2:15:54 PM	11/18/2018 12:00:00 PM	TXOH: 36BN-260: 26887214		0	1	CMP	PH-H-Tree-PH-On	0	EA Weather	Unselected	35 OK per Phone Call	Florence	issue resolved per customer
569	8116792	Donaldson-H9320550042	11/15/2018 1:38:13 PM	11/16/2018 4:44:00 PM	11/18/2018 12:00:00 PM	TXOH: K104-258: 26903723		0	2	CMP	PH-H-LF-Othr,PH-H-Othr	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-16 16:44:00 by T22595 RMK: line is still down driveway to house per neighbor dense 859-630-6317PUT TRI-PLEX BACK UP ON HOUSE TEMPO AND REPAIRED NEUT. TO GET OUT OF STREET FOR SAFETY.NO ONE ON PREM.CUST NEEDS TO MAKE REPAIRS
570	8116856	Bellevue-H9321310042	11/15/2018 1:43:12 PM	11/17/2018 9:33:54 PM	11/18/2018 12:00:00 PM	TXOH: CA5-295: 26900978		0	1	CMP	Tree-PH-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	REM LIMB OK.
571	8116975	Dixie-H9320890042	11/15/2018 1:53:32 PM	11/16/2018 1:06:40 PM	11/18/2018 12:00:00 PM	TXOH: 31BN-739: 26883883		1	2	CMP	Out	0	03 Vegetation	Unselected	26 OK Arrival	Florence	PING ON - REQ 8123660 as of 11/16/2018 12:48. ESphr 513-458-3803. Ticket being completed.

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
572	8116977	Alexandria South-H9322050041	11/15/2018 1:53:37 PM	11/16/2018 10:59:00 AM	11/18/2018 12:00:00 PM	TXOH: 44CA-420:26892787	-	0	0	1	CMP	Tree-PH-On	03 Vegetation	-	27 Other/See Notes	Florence	CMP 2018-11-16 10:59:00 by T24175 RMK: removed limb off service
573	8116984	Buffington-H9320670045	11/15/2018 1:53:55 PM	11/17/2018 6:24:00 PM	11/18/2018 12:00:00 PM	TXOH: K117-50:26907847	-	1	5	5	CMP	Tree-PH-Pt O-LF,Pt O	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	PING ON - REQ 8123658 as of 11/16/2018 12:48. Only 114 Roger Ln pinged off for this transformer. ESphar 513-458-3803.
574	8117010	Constance-H9320420042	11/15/2018 1:56:20 PM	11/17/2018 10:53:24 AM	11/18/2018 12:00:00 PM	TXUG: K101-D2-18:26903325	-	0	0	1	CMP	Othr	28 Other Cause	Unselected	27 Other/See Notes	Florence	NO INFORMATION TO RUN A CREW ON.
575	8117012	Villa-H9322430043	11/15/2018 9:27:51 AM	11/16/2018 10:12:00 PM	11/18/2018 12:00:00 PM	TXOH: K97-274:26917542	-	3	3	3	CMP	PH-H-Tree-PH-Out,PH-H-Out,Othr-H-911-Othr-O-Othr	03 Vegetation	-	22 Cut Off/Disconnect at Pole	Florence	CMP 2018-11-16 22:12:00 by T95129 RMK: 3093 balsam will need entrance cable put back up by electr rear prop,r2e 3090 magnolia r2e entrance cable 1/0 in existing knob
576	8117022	Hebron-H9321520042	11/15/2018 1:56:59 PM	11/17/2018 6:30:00 PM	11/18/2018 12:00:00 PM	TXOH: 7BN-70:26871442	-	0	0	1	CMP	Othr-H-Tree-PP-On	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMP 2018-11-17 18:30:00 by T29408 RMK: tree limb still on line per customer 11/16/18
577	8117081	Bellevue-H9321310044	11/15/2018 2:03:06 PM	11/16/2018 9:53:00 AM	11/18/2018 12:00:00 PM	TXOH: CA6-1594:26901246	-	1	1	1	CMP	PP-H-Tree-PP-Out	28 Other Cause	-	11 Checked Voltage/All OK	Florence	CMP 2018-11-16 09:53:00 by T39767 RMK: oka
578	8117091	Verona-H9321250042	11/15/2018 10:40:06 AM	11/15/2018 8:09:00 PM		TXOH: 50BN-400:26894197	-	1	1	1	CMP	PH-H-Tree-PH-Out-S-Out	03 Vegetation	-	12 Checked Voltage/Fixed Connect	Florence	CMP 2018-11-15 20:09:00 by PNLAUER RMK: limb took service down
579	8117141	Buffington-H9320670045	11/15/2018 2:08:24 PM	11/17/2018 6:12:35 PM	11/18/2018 12:00:00 PM	TXOH: K116-701:26906555	-	0	0	1	CMP	Tree-PH-LF-Othr	28 Other Cause	Unselected	26 OK Arrival	Florence	OK
580	8117153	Crescent-H9320700041	11/15/2018 2:09:11 PM	11/16/2018 9:06:35 PM	11/18/2018 12:00:00 PM	TXOH: K84-435:27167852	-	1	1	1	CMP	PH-H-Tree-PH-Out	28 Other Cause	Unselected	26 OK Arrival	Florence	PING ON - REQ 8123657 as of 11/16/2018 12:48. tree branches fell on lines going to the house, there are other limbs laying on lines in this area as well. ESphar 513-458-3803. NICK HAMILTON 513-240-8825 SERVICE IN/OK
581	8117174	Villa-H9322430041	11/15/2018 2:10:52 PM	11/17/2018 12:01:26 PM	11/18/2018 12:00:00 PM	TXOH: K84-145:26925938	-	0	0	1	CMP	Tree-PH-On	28 Other Cause	Unselected	26 OK Arrival	Florence	no answer by phone. NICK HAMILTON 513-240-8825. SERVICE IN/OK TRIED TO CALL CUST. NO ANSWER. NO TREES DOWN ON SITE.
582	8117198	Villa-H9322430041	11/15/2018 2:12:40 PM	11/17/2018 12:27:25 PM	11/18/2018 12:00:00 PM	TXUG: K85-A2-9:26914425	-	0	0	1	CMP	PP-H-Othr-O-On	28 Other Cause	Unselected	26 OK Arrival	Florence	phone out of order- NICK HAMILTON 513-240-8825. SERVICE IN/OK. NO ISSUES FOUND.
583	8117245	Buffington-H9320670045	11/15/2018 2:16:42 PM	11/15/2018 3:31:03 PM		TXOH: K117-530:26908004	-	0	0	1	CMP	PH-H-On	28 Other Cause	Unselected	26 OK Arrival	Florence	ROB MILLER 513-543-8745 IN & OK
584	8117290	Villa-H9322430044	11/15/2018 2:19:59 PM	11/17/2018 7:51:40 PM	11/18/2018 12:00:00 PM	TXOH: K96-347:26917296	-	0	0	1	CMP	PH-H-On	EA Weather	Unselected	26 OK Arrival	Florence	no answer by phone
585	8117337	Longbranch-H9320980043	11/15/2018 2:23:07 PM	11/17/2018 9:29:38 PM	11/18/2018 12:00:00 PM	TXOH: 35BN-221:26885133	-	0	0	1	CMP	Tree-PH-On	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	no answer by phone
586	8117355	Buffington-H9320670045	11/15/2018 7:28:48 AM	11/17/2018 1:31:59 PM	11/18/2018 12:00:00 PM	TXOH: K105-440:26904643	-	0	2	2	CMP	PP-H-Tree-PP-On,PH-H-On	28 Other Cause	Unselected	26 OK Arrival	Florence	no answer by phone M.ORTH 859-300-4794. 11/17/18. COMMUNICATION LINES DOWN NOT DUKE.
587	8117367	Decoursey-H9322990041	11/15/2018 11:31:46 AM	11/17/2018 8:53:45 AM	11/18/2018 12:00:00 PM	TXOH: 11K-105:26872241	-	0	2	2	CMP	PP-H-On,PH-H-On	28 Other Cause	Unselected	26 OK Arrival	Florence	Mother says can get in/out of street but doesn't know if wire still down or moved over. IN AND OK ALAN EAST 513-313-9220
588	8117386	Limaburg-H9321890042	11/15/2018 2:27:14 PM	11/17/2018 7:29:27 PM	11/18/2018 12:00:00 PM	TXOH: 23BN-195:26862174	-	0	0	1	CMP	Tree-PP-Othr-PQ-On	28 Other Cause	Unselected	27 Other/See Notes	Florence	LIMB ON MAST AND BUSTED METER. ELECTRICIAN MADE REPAIRS AND SERVICE WAS RE-ATTACHED TO HOUSE
589	8117404	Buffington-H9320670045	11/15/2018 2:28:26 PM	11/16/2018 5:45:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-726:26904837	-	1	2	2	CMP	PP-H-Tree-PP-On,PH-H-Tree-PH-Out	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMP 2018-11-16 17:45:00 by T22595 RMK: PING ON - REQ 8123496 as of 11/16/2018 12:15. Tasset 859-466-2286 to the right of the house line hanging low. Telephone line NO ONE ON PREM.ALL DUKE LINES UP AND OK. HIS TELEPHONE IS LOW. R TO MA BELL
590	8117438	Florence-H9322410042	11/15/2018 7:42:26 AM	11/16/2018 5:27:49 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-121:26881429	-	0	2	2	CMP	PP-H-Othr,Othr-H-On	EA Weather	Unselected	35 OK per Phone Call	Florence	-
591	8117446	Donaldson-H9320550043	11/15/2018 2:31:35 PM	11/15/2018 7:32:40 PM		FOH: 21BN-324:25988674	65T	47	2	2	CMP	Out	28 Other Cause	Unselected	26 OK Arrival	Florence	K GOETZ 859-404-1222. IN AND OK
592	8117466	Donaldson-H9320550041	11/15/2018 2:32:58 PM	11/17/2018 7:00:00 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-302:26862830	-	1	1	1	CMP	PH-H-Out	EA Weather	Unselected	19 Cut In/Reconnect at Weatherhe	Florence	PING ON - REQ 8123492 as of 11/16/2018 12:15. Trimmed 2 trees and service line was affected. ESphar 513-458-3803
593	8117492	Verona-H9321250042	11/15/2018 2:34:53 PM	11/16/2018 12:30:25 PM	11/18/2018 12:00:00 PM	TXOH: 29K-367:26862894	-	1	2	2	CMP	Out	03 Vegetation	Unselected	26 OK Arrival	Florence	PING ON - REQ 8123489 as of 11/16/2018 12:15. ESphar 513-458-3803. Ticket being Completed
594	8117571	Crescent-H9320700044	11/15/2018 2:41:38 PM	11/16/2018 7:08:47 PM	11/18/2018 12:00:00 PM	TXOH: K93-129:26927249	-	0	0	1	CMP	PP-H-Tree-PP-Othr	EA Weather	Unselected	35 OK per Phone Call	Florence	-
595	8117586	Claryville-H9321470041	11/15/2018 9:29:47 AM	11/17/2018 3:51:58 PM	11/18/2018 12:00:00 PM	TXOH: 51CA-396:26894902	-	0	0	1	CMP	Othr-H-911-Othr-O-Othr	28 Other Cause	Unselected	26 OK Arrival	Florence	no answer. NOT DUKE ENERGY SERVICE TERRITORY
596	8117596	Buffington-H9320670041	11/15/2018 9:34:12 AM	11/17/2018 4:20:37 PM	11/18/2018 12:00:00 PM	TXOH: K106-553:26905970	-	0	0	1	CMP	Othr-H-911-Othr-O-Othr	28 Other Cause	Unselected	26 OK Arrival	Florence	M.ORTH 859-300-4794. IN & OK.
597	8117607	Wilder-H9320590042	11/15/2018 2:44:02 PM	11/17/2018 4:21:00 AM	11/17/2018 5:33:00 PM	TXOH: CA11-46:26898776	-	0	0	1	CMP	PP-H-On	04 Wildlife	Unselected	48 Replaced Service/Secondary	Florence	CMP 2018-11-17 04:21:00 by T17494 RMK: Customer in power neutral broke rplace 100' #41tpx at midspan pole CA11-46 service crew needed Tyler Burns 513-335-2291 Customer in power neutral broke rplace 100' #41tpx at midspan pole CA11-46 service crew needed
598	8117629	Kenton-H9320090044	11/15/2018 2:44:34 PM	11/17/2018 5:36:41 PM	11/18/2018 12:00:00 PM	TXOH: K73-317:26912916	-	1	1	1	CMP	PH-H-Pt O-Othr-O	28 Other Cause	Unselected	26 OK Arrival	Florence	PING OFF - REQ 8123484 as of 11/16/2018 12:18. line down p-h across the road in front house. ESphar 513-458-3803
599	8117690	Hands-H9321280044	11/15/2018 2:50:08 PM	11/15/2018 11:53:00 PM	11/18/2018 12:00:00 PM	TXOH: K87-222:26915079	-	1	1	1	CMP	Out	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
600	8117721	Florence-H9322410045	11/15/2018 2:53:44 PM	11/17/2018 8:07:47 AM	11/18/2018 12:00:00 PM	TXOH: 30BN-267:26882485	-	0	0	1	CMP	Tree-PH-On	11 Unknown Cause	Unselected		Florence	no answer

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
601	8117748	Longbranch-H9320980042	11/15/2018 2:55:40 PM	11/17/2018 11:07:00 PM	11/18/2018 12:00:00 PM	TXOH: 34BN-101: 26884587	-	0	1	CMP	On	0	03 Vegetation	Unselected	19 Cut In/Reconnect at Weatherhe	Florence	WDPH CROSSING THE ROAD.
602	8117755	White Tower-H9323040041	11/15/2018 2:56:37 PM	11/15/2018 9:40:00 PM	11/18/2018 12:00:00 PM	TXOH: 30K-260: 26883127	-	0	1	CMP	PH-H-Othr	0	03 Vegetation	-	11 Checked Voltage/All OK	Florence	CMPL 2018-11-15 21:40:00 by PNLauer RMK: ok arrival
603	8117793	Bellevue-H9321310044	11/15/2018 3:00:14 PM	11/15/2018 5:19:00 PM	11/15/2018 6:30:00 PM	TXOH: CA6-1217: 26901189	-	1	1	CMP	PH-H-Out	0	03 Vegetation	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-15 17:19:00 by T40067 RMK: all customers picked up perm.
604	8117802	Villa-H9322430041	11/15/2018 3:00:15 PM	11/16/2018 7:34:00 AM	11/18/2018 12:00:00 PM	TXOH: KNK-3761: 102832741	-	0	1	CMP	Othr-H-Othr	0	11 Unknown Cause	-	26 OK Arrival	Florence	CMPL 2018-11-16 07:34:00 by T17572 RMK: OK ARR
605	8117832	Crescent-H9320700043	11/15/2018 3:03:53 PM	11/17/2018 8:35:27 AM	11/18/2018 12:00:00 PM	TXOH: K73-98: 26865127	-	0	1	CMP	Othr-O-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	no answer left message - MANNING - 513-218-6533 OK ARRIVAL
606	8117834	Grant-H9321610041	11/15/2018 3:03:58 PM	11/16/2018 12:11:10 PM	11/18/2018 12:00:00 PM	TXOH: GRK-15: 27069854	-	1	1	CMP	Pt O	0	03 Vegetation	Unselected	26 OK Arrival	Florence	PING ON - REQ 8123371 as of 11/16/2018 11:50. ESphr 513-458-3803. Ticket being Completed
607	8117839	Villa-H9322430043	11/15/2018 3:04:15 PM	11/17/2018 5:42:00 PM	11/18/2018 12:00:00 PM	TXOH: K96-373: 26917205	-	1	11	CMP	Tree-PH-On,Out,On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	PING OFF - REQ 8123368 as of 11/16/2018 11:53. tree down on the house. ESphr 513-458-3803
608	8117949	Donaldson-H9320550041	11/15/2018 3:11:09 PM	11/17/2018 8:04:34 PM	11/18/2018 12:00:00 PM	TXUG: 26BN-66: 26918904	-	0	1	CMP	On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745 TWP
609	8117953	Augustine-H9320780041	11/15/2018 3:11:56 PM	11/17/2018 3:56:00 AM	11/18/2018 12:00:00 PM	TXOH: K70-336: 26911864	-	1	1	CMP	PP-H-Tree-PH-Out	0	11 Unknown Cause	Unselected	25 No Problem Found	Covington	CMPL 2018-11-17 03:56:00 by T18514 RMK: PING OFF - REQ 8123362 as of 11/16/2018 11:53. ree branches on lines, lines hanging lower than normal. ESphr 513-458-3803 NABP FURNACE WAS RUNNING APPEAR TO HAVE POWER
610	8118112	Hands-H9321280044	11/15/2018 3:24:12 PM	11/17/2018 1:50:40 PM	11/18/2018 12:00:00 PM	TXOH: K87-208: 26914975	-	1	2	CMP	Equip-E-Tree-PH-Out,PH-H-Tree-PH-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING ON - REQ 8123193 as of 11/16/2018 11:32. limbs on line, weighed down, sparking in neighbors at one point. located in backyard. ESphr 513-458-3803 . IN AND OKAY. KEVIN LANHAM 513-504-1488
611	8118231	Buffington-H9320670042	11/15/2018 7:56:49 AM	11/15/2018 5:11:00 PM	11/15/2018 6:00:00 PM	TXUG: 13K-6: 26918567	-	1	2	CMP	Out-S-Out,Pt O	0	11 Unknown Cause	-	44 Replaced Fuse	Florence	CMPL 2018-11-15 17:11:00 by T81490 RMK: refused 140t fuse. unknown reason for blowing
612	8118237	Donaldson-H9320550042	11/15/2018 1:06:50 PM	11/17/2018 5:31:33 PM	11/18/2018 12:00:00 PM	TXOH: 26903956	-	0	2	CMP	PH-H-Mtr-Othr-Othr-H-Othr-O-On	0	EA Weather	Unselected	13 Close Work Needed	Florence	Still an issue, 11/16/18.
613	8118268	Buffington-H9320670045	11/15/2018 3:39:28 PM	11/16/2018 1:47:00 PM	11/18/2018 12:00:00 PM	TXOH: K117-309: 26907950	-	1	3	CMP	PH-H-Tree-PH-Out,PH-H-Out,Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	-
614	8118285	Hebron-H9321520041	11/15/2018 3:40:45 PM	11/17/2018 3:18:00 PM	11/18/2018 12:00:00 PM	TXOH: 13BN-60: 26873102	-	0	1	CMP	PP-H-Obj-L-On	0	03 Vegetation	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 15:18:00 by T29408 RMK: cleared limb off line
615	8118294	Beaver-H9320860041	11/15/2018 6:24:13 AM	11/17/2018 3:59:08 PM	11/18/2018 12:00:00 PM	TXOH: 48BN-2: 26862224	-	0	1	CMP	PP-H-911-Tree-PP Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK AS OF 3:55PM ON 11.17.18 TOM GEIMAN 513 446 4723
616	8118296	Villa-H9322430041	11/15/2018 3:41:53 PM	11/17/2018 10:21:42 AM	11/18/2018 12:00:00 PM	TXUG: K85-A2-1: 26914294	-	0	1	CMP	PP-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ROB MILLER 513 543 8745 IN & OK
617	8118319	Buffington-H9320670045	11/15/2018 7:35:19 AM	11/16/2018 1:00:00 PM	11/16/2018 1:30:00 PM	TXOH: K105-611: 26904190	-	59	21	CMP	PH-H-911-Out,PH-H-Out-Othr-O,Out-Dmg,Out	0	03 Vegetation	LH Tree limb, overhang	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-16 13:00:00 by T95129 RMK: ROB MILLER 513 543 8745 BUCKET TRK ACCC GENERATOR @ 55, LG TREE ON PRIM @ POLE K105-460 & 597, 1/0 PRIM DOWN 1 SPAN K105-604 TO 611, 65T BLOWN K105-47, SEC DOWN & KNOB PULLED FROM HOUSE @ 47-DE-ENERGIZE, SEC FAU
618	8118366	Hebron-H9321520042	11/15/2018 3:47:10 PM	11/17/2018 9:45:25 PM	11/18/2018 12:00:00 PM	TXOH: 11BN-42: 26866819	-	0	1	CMP	PH-H-On	0	EA Weather	Unselected	26 OK Arrival	Florence	says was not at location but all he knows is a wire was down at the pole but was not affecting anyone. 11-1618
619	8118373	Crescent-H9320700042	11/15/2018 8:58:08 AM	11/16/2018 5:26:06 PM	11/18/2018 12:00:00 PM	TXUG: K81-38: 26913496	-	4	2	CMP	Othr-H-Out-Othr-O,Out-PQ,Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
620	8118389	Decoursey-H9322990041	11/15/2018 3:49:00 PM	11/17/2018 7:33:27 AM	11/18/2018 12:00:00 PM	TXOH: 11K-181: 26872780	-	0	0	CMP	PP-H-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING ON - REQ 8123187 as of 11/16/2018 11:32.power out lines down in the yard 8594917600 Mr Bramlage. ESphr 513-458-3803. IN AND OK ALAN EAST 513-313-9220
621	8118392	Wilder-H9320590042	11/15/2018 3:49:19 PM	11/17/2018 11:33:25 AM	11/18/2018 12:00:00 PM	TXOH: CA11-81: 26898807	-	0	1	CMP	PH-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ok on arrival no duke work required
622	8118405	Buffington-H9320670045	11/15/2018 3:50:24 PM	11/17/2018 2:46:18 PM	11/18/2018 12:00:00 PM	TXOH: K106-272: 26905236	-	0	1	CMP	Tree-PH-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	-
623	8118412	Kenton-H9320090044	11/15/2018 3:51:17 PM	11/16/2018 6:30:32 PM	11/18/2018 12:00:00 PM	TXOH: K63-12: 26910575	-	1	1	CMP	PH-H-Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	SERVICE DOWN. REPAIRS MADE AND CUSTOMER IS BACK IN SERVICE
624	8118454	Crescent-H9320700043	11/15/2018 1:14:09 PM	11/17/2018 5:20:54 PM	11/18/2018 12:00:00 PM	FOH: K83-650: 25998332	40T	153	21	CMP	Out	0	03 Vegetation	Unselected	47 Replaced Pole	Florence	41 BURSALL REAR PROP. BRKN 40CL4 P#K84-305 @P#K84-306 SEC REQ RESAG. REQ TT ALSO. TT COMPLETE.
625	8118532	Donaldson-H9320550042	11/15/2018 4:02:34 PM	11/17/2018 5:32:41 PM	11/18/2018 12:00:00 PM	TXOH: K105-213: 26904140	-	0	1	CMP	PP-H-Othr	0	EA Weather	Unselected	26 OK Arrival	Florence	-
626	8118538	Buffington-H9320670045	11/15/2018 4:03:15 PM	11/15/2018 6:56:00 PM	11/15/2018 7:30:00 PM	TXOH: K106-567: 26906063	-	0	1	CMP	CC-H-On	0	03 Vegetation	-	36 Referred to FUN	Florence	CMPL 2018-11-15 18:56:00 by T81490 RMK: 40 class 4 requires replacing. top of pole broke out. tempo with ptx. good for later date.
627	8118581	Crescent-H9320700041	11/15/2018 4:07:02 PM	11/16/2018 3:21:39 PM	11/18/2018 12:00:00 PM	TXOH: K94-149: 26916451	-	1	2	CMP	PP-H-On,PH-H-Obj-L-Out	0	28 Other Cause	Unselected	39 Repaired Overhead Conductor	Florence	PING OFF - REQ 8123185 as of 11/16/2018 11:31. line laying on back patio and snapped in middle of line. ESphr 513-458-3803
628	8118589	Crescent-H9320700041	11/15/2018 3:59:11 PM	11/16/2018 2:37:34 PM	11/18/2018 12:00:00 PM	TXOH: K84-789: 26928028	-	0	2	CMP	Equip-E-911-Othr,PP-H-Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	-

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
629	8118638	Richwood-H9321990043	11/15/2018 4:11:26 PM	11/16/2018 3:49:00 AM	11/18/2018 12:00:00 PM	TXOH: 41BN-340:26891706	-	1	1	CMP	911-Out-PF	0	20 Equipment failure	Unselected	22 Cut Off/Disconnect at Pole	Florence	CMPL 2018-11-16 03:49:00 by T22400 RMK: P#41BN-39, GRD AN TAGED 21414, NEED 40CL 4 AN 50KVA, P# 41BN-238 IS POLE THATS BROKE, NEED FLAGGERS, MIGHT BEABLE TO REACH FROM ROAD, OR MAY NEED REAR PROP CART TO SET POLE.
630	8118649	Villa-H9322430044	11/15/2018 11:36:13 AM	11/18/2018 2:37:00 PM		TXOH: K106-321:26906054	-	0	2	CMP	PP-H-On,PH-H-On	0	EA Weather	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-18 14:37:00 by T23397 RMK: Line is still down over the wire. Customer does has power. They cant get in and out their driveway 11-16-18
631	8118658	Buffington-H9320670045	11/15/2018 4:12:47 PM	11/17/2018 6:45:59 PM	11/18/2018 12:00:00 PM	TXUG: K117-CI-11:26907748	-	0	1	CMP	PP-H-Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OK
632	8118691	Hebron-H9321520045	11/15/2018 4:16:00 PM	11/17/2018 4:34:01 PM	11/18/2018 12:00:00 PM	TXOH: 14BN-826:26867373	-	0	1	CMP	Trap-E-911-On	0	28 Other Cause	Unselected	35 OK per Phone Call	Florence	William was not home 11-16-18. BAD PHONE NUMBER 11-17-18
633	8118714	Wilder-H9320590042	11/15/2018 3:39:59 PM	11/17/2018 10:46:13 AM	11/18/2018 12:00:00 PM	TXOH: CA10-370:26897601	-	0	2	CMP	PP-H-On,PH-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ok on arrival no duke work comm line on ground Tyler Burns 513-335-2291
634	8118719	Villa-H9322430041	11/15/2018 4:19:17 PM	11/17/2018 1:44:00 PM	11/18/2018 12:00:00 PM	TXOH: K84-96:26925943	-	1	1	CMP	PH-H-Tree-PH-Out	0	03 Vegetation	Unselected	22 Cut Off/Disconnect at Pole	Florence	CMPL 2018-11-17 13:44:00 by T39767 RMK: PING OFF - REQ 8123183 as of 11/16/2018 11:18. Frank Kroger 859-466-7617 Line down in front of the house. no power. ESphr 513-458-3803
635	8118730	Hands-H9321280041	11/15/2018 4:20:05 PM	11/17/2018 11:48:41 AM	11/18/2018 12:00:00 PM	TXOH: 14K-425:26873915	-	0	1	CMP	Tree-PH-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	-
636	8118794	Buffington-H9320670042	11/15/2018 4:25:54 PM	11/17/2018 1:31:23 PM	11/18/2018 12:00:00 PM	TXUG: 13K-5:26918578	-	1	3	CMP	Pt O	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OK
637	8118795	Crescent-H9320700041	11/15/2018 8:22:54 AM	11/16/2018 1:01:00 PM	11/18/2018 12:00:00 PM	RCL: 11362: KNK-3706: 26228649	-	419	46	CMP	Equip-E-Out,Equip-E-Pt O-Othr-O-Out-S-Out,Out,Pt O	0	03 Vegetation	Unselected	56 Sectionalized/Restored Serv	Florence	#2copper phase down rear property by tree, tree trimmers not req'd. between K94-138 & K94-141, fuse tail hanging on K94-137 refer to 5 man crew to make repairs BEST ACCESS OFF OF SHAKER
638	8118808	Crescent-H9320700041	11/15/2018 9:21:09 AM	11/16/2018 4:39:41 PM	11/18/2018 12:00:00 PM	TXOH: K84-791:26926068	-	3	7	CMP	Out-S-Out,Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	-
639	8118839	Buffington-H9320670045	11/15/2018 4:29:10 PM	11/16/2018 1:47:39 PM	11/18/2018 12:00:00 PM	FOH: BNK-6748:407075523	-	81	75	CMP	Tree-PP-Out,Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	100T
640	8118864	Buffington-H9320670042	11/15/2018 4:31:51 PM	11/17/2018 1:30:35 PM	11/18/2018 12:00:00 PM	TXOH: 13K-288:26865323	-	1	1	CMP	Pt O	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OK
641	8118876	Bellevue-H9321310043	11/15/2018 4:32:34 PM	11/16/2018 10:43:00 AM	11/18/2018 12:00:00 PM	TXOH: CA8-188:26922052	-	0	1	CMP	PP-H-911-PF-Othr	0	03 Vegetation	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-16 10:43:00 by T66296 RMK: R TO E WH ENT KNOB TRI ON SIGHT
642	8118896	Decoursey-H9322990041	11/15/2018 4:34:52 PM	11/16/2018 7:07:31 PM	11/18/2018 12:00:00 PM	TXOH: 11K-766:26872451	-	0	1	CMP	PP-H-Othr-O-On	0	EA Weather	Unselected	35 OK per Phone Call	Florence	-
643	8118905	Florence-H9322410045	11/15/2018 10:00:59 AM	11/17/2018 9:25:16 PM	11/18/2018 12:00:00 PM	TXOH: 30BN-484:26882487	-	0	3	CMP	Equip-E-PF-LF-Othr,Othr-H-Tree-PH-On,Tree-PP-LF-Othr	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	, REQ. MANUAL TREE CREW, TREE ON NEUT, GOOD ADDRESS, ***LINE IS ENERGIZED*** TT COMPLETE
644	8118924	Bellevue-H9321310043	11/15/2018 9:27:30 AM	11/16/2018 9:35:00 AM	11/18/2018 12:00:00 PM	TXOH: CA7-625:26902211	-	1	3	CMP	PH-H-Tree-PH-Othr,Othr-H-Tree-PH-Out,Othr	0	28 Other Cause	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-16 09:35:00 by T66296 RMK: R TO E ON M-BASES WH ENT
645	8118932	Villa-H9322430041	11/15/2018 4:37:52 PM	11/16/2018 4:35:33 PM	11/18/2018 12:00:00 PM	TXOH: K84-149:26926151	-	0	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	Unselected	38 Removed Object From Line	Florence	-
646	8118970	Mt Zion-H9323050043	11/15/2018 4:41:12 PM	11/17/2018 8:23:00 PM	11/18/2018 12:00:00 PM	TXUG: 36BN-FF-3:26887745	-	1	1	CMP	Pt O	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	PING ON - REQ 8123177 as of 11/16/2018 11:31. building states from its from exterior from the breaker box , burning smell. ESphr 513-458-3803
647	8119028	Villa-H9322430042	11/15/2018 4:45:36 PM	11/16/2018 11:17:05 AM	11/18/2018 12:00:00 PM	TXOH: K96-597:26917101	-	0	1	CMP	PP-H-Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OK
648	8119080	Augustine-H9320780046	11/15/2018 4:52:21 PM	11/16/2018 9:02:04 PM	11/18/2018 12:00:00 PM	TXOH: K72-456:26912130	-	0	1	CMP	Othr	0	28 Other Cause	Unselected	27 Other/See Notes	Covington	OKAY ON ARRIVAL
649	8119087	Richwood-H9321990042	11/15/2018 4:52:54 PM	11/16/2018 8:56:21 PM	11/18/2018 12:00:00 PM	TXOH: 36BN-619:26888248	-	0	1	CMP	Tree-PH-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK - L Grothaus
650	8119089	Hands-H9321280044	11/15/2018 4:53:16 PM	11/17/2018 1:29:01 PM	11/18/2018 12:00:00 PM	TXOH: K87-224:26914981	-	0	1	CMP	Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OKAY
651	8119113	Florence-H9322410045	11/15/2018 4:56:38 PM	11/15/2018 7:05:56 PM		TXUG: BNK-606:27085317	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NICK HAMILTON 513-240-8825 IN/OK. CUST HAS POWER
652	8119174	Covington KY-H9322170044	11/15/2018 4:21:11 PM	11/16/2018 9:00:00 PM	11/18/2018 12:00:00 PM	TXOH: K52-1091:27083232	-	0	1	CMP	PP-H-Tree-PP-On	0	28 Other Cause	-	23 Found on Inspection	Covington	CMPL 2018-11-16 21:00:00 by T33329 RMK: CATV. NON DUKE ISSUE
653	8119176	White Tower-H9323040043	11/15/2018 4:34:51 PM	11/18/2018 9:40:00 AM	11/18/2018 12:00:00 PM	TXOH: 19K-844:27146710	-	0	1	CMP	PH-H-911-Othr-O-On	0	03 Vegetation	-	27 Other/See Notes	Florence	CMPL 2018-11-18 09:40:00 by WACASSO RMK: LARGE TREE BRANCHES LAYING ON TRI-PLEX VERY HEAVY,AND ARE LOW NEEDS REMOVED
654	8119197	Buffington-H9320670045	11/15/2018 3:19:52 PM	11/17/2018 1:49:52 PM	11/18/2018 12:00:00 PM	TXOH: K106-1032:26905689	-	0	2	CMP	PP-H-Othr-O-On,PP-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	M.ORTH 859-300-4794. IN & OK.
655	8119219	Cold Spring-H9321320049	11/15/2018 5:08:03 PM	11/17/2018 3:32:00 PM	11/18/2018 12:00:00 PM	TXOH: 36CA-666:26889045	-	1	4	CMP	Out,Othr-O-On	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	PING OFF - REQ 8123104 as of 11/16/2018 11:09. REPAIRS MADE-READY FOR RECONNECT. ESphr 513-458-3803
656	8119227	Augustine-H9320780046	11/15/2018 8:54:28 AM	11/18/2018 12:01:00 AM	11/18/2018 12:00:00 PM	TXOH: K72-417:26912571	-	0	2	CMP	PH-H-LF-Othr,Tree-PP-LF-Othr	0	03 Vegetation	-	37 Removed Limb or Tree From Lin	Covington	CMPL 2018-11-18 00:01:00 by T17410 RMK: remove limb #2 tri repair neutral perm
657	8119231	Augustine-H9320780046	11/15/2018 2:36:17 PM	11/17/2018 11:39:15 AM	11/18/2018 12:00:00 PM	TXOH: K62-402:26865841	-	6	4	CMP	PH-H-Out,Out,CIE-Othr-O	0	EA Weather	Unselected	29 Permanent Repair	Covington	THIS NEEDS TO BE DONE IN THE DAYLIGHT AS OF 11/18/18 @ 19:38. BRING A ROLL OF 1/0 TRIPLEX

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
658	8119268	Villa-H9322430043	11/15/2018 10:09:25 AM	11/17/2018 5:09:23 PM	11/18/2018 12:00:00 PM	TXOH: K95-56: 26927849	-	0	1	CMP	Tree-PH-On	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	-
659	8119274	Buffington-H9320670045	11/15/2018 11:12:17 AM	11/17/2018 1:41:01 PM	11/18/2018 12:00:00 PM	TXOH: K105-422: 26904592	-	0	2	CMP	PP-H-Tree-PP-On Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	M ORTH 859-300-4794. COMMUNICATION LINES DOWN NOT DUKE.
660	8119277	Verona-H9321250042	11/15/2018 5:12:32 PM	11/16/2018 11:15:23 AM	11/18/2018 12:00:00 PM	TXOH: 50BN-70: 26894099	-	1	1	CMP	Pi O	0	03 Vegetation	Unselected	Unselected	Florence	PING ON - REQ 8123101 as of 11/16/2018 11:06. Espahr 513-458-3803. Ticket being completed.
661	8119281	Villa-H9322430044	11/15/2018 9:13:41 AM	11/17/2018 11:56:00 AM	11/18/2018 12:00:00 PM	TXOH: K96-195: 26917183	-	0	2	CMP	Tree-PP-On,LF-On	0	03 Vegetation	-	27 Other/See Notes	Florence	CMPL 2018-11-17 11:56:00 by T24175 RMK: removed tree branch off roof and serv
662	8119286	Crescent-H9320700043	11/15/2018 6:58:05 AM	11/16/2018 6:29:00 AM	11/18/2018 12:00:00 PM	TXOH: K83-152: 26925679	-	1	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	-	27 Other/See Notes	Florence	CMPL 2018-11-16 06:29:00 by T17572 RMK: REPAIRED 1/0 TRI SER
663	8119300	Dayton-H9320760041	11/15/2018 11:05:27 AM	11/17/2018 1:01:00 PM	11/18/2018 12:00:00 PM	TXOH: CA1-128: 26897120	-	0	1	CMP	Tree-PP-Othr	0	03 Vegetation	-	25 No Problem Found	Florence	CMPL 2018-11-17 13:01:00 by T24175 RMK: no problems found,el in the clear all around this address
664	8119318	Crescent-H9320700043	11/15/2018 7:29:09 AM	11/16/2018 8:25:00 AM	11/18/2018 12:00:00 PM	FOH: K83-650: 25998332	40T	132	3	CMP	Othr-H-911-Out,Out	0	03 Vegetation	28 Other Failure Mode	37 Removed Limb or Tree From Limb	Florence	CMPL 2018-11-16 08:25:00 by WACASSO RMK: 40T
665	8119374	Decoursey-H9322990041	11/15/2018 5:21:13 PM	11/17/2018 10:17:21 AM	11/18/2018 12:00:00 PM	TXOH: 11K-775: 26862340	-	0	1	CMP	PP-H-Othr-O-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OK
666	8119485	Hands-H9321280045	11/15/2018 5:29:22 PM	11/17/2018 2:08:40 PM	11/18/2018 12:00:00 PM	TXOH: 11K-859: 26872707	-	1	1	CMP	PH-H-Tree-PH-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING ON - REQ 8123097 as of 11/16/2018 11:06. limbs are on the lines p-h. pulling lines down. Espahr 513-458-3803 IN AND OKAY. KEVIN LANHAM 513-504-1488
667	8119502	Buffington-H9320670045	11/15/2018 5:30:13 PM	11/16/2018 1:31:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-688: 26904530	-	1	1	CMP	Equip-E-911-Pi-O PF-Othr-PQ	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-16 13:31:00 by T22595 RMK: PING ON - REQ 8123095 CANNOT SEE SIGNS OF FIRE.TEMPO REPAIRS HAVE BEEN MADE ON 1 POLE. BUT DOES NOT LOOK NEW,NO ONE ON PREM AT 102 STEVENSON
668	8119517	Villa-H9322430041	11/15/2018 5:31:41 PM	11/17/2018 1:33:57 PM	11/18/2018 12:00:00 PM	TXOH: K74-59: 26924920	-	1	6	CMP	PH-H-Othr,PH-H-On,Out	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	PING ON - REQ 8123094 as of 11/16/2018 11:05. line laying in the road and the other side of the line is hanging over fire hydrant. Espahr 513-458-3803, CUST TO CLAMPS FOR SEC. OK TEMPO. per cust everything has been corrected 11-16-18
669	8119518	Decoursey-H9322990041	11/15/2018 5:29:25 PM	11/16/2018 4:09:32 PM	11/18/2018 12:00:00 PM	TXOH: 11K-785: 26872314	-	0	1	CMP	PP-H-On	0	EA Weather	Unselected	35 OK per Phone Call	Florence	
670	8119627	Donaldson-H9320550041	11/15/2018 5:41:44 PM	11/17/2018 4:41:26 PM	11/18/2018 12:00:00 PM	TXOH: K116-132: 26906634	-	1	2	CMP	PH-H-Out,PH-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ROB MILLER 513 543 8745 IN & OK LINE IS COMMUNICATION. PING ON - REQ 8123092 as of 11/16/2018 11:05. not sure if it is p-p or p-h. line is laying in yard, can't walk out of front door or get to car due to down line. Espahr 513-458-3803
671	8119675	Villa-H9322430044	11/15/2018 5:45:38 PM	11/16/2018 10:01:38 AM	11/18/2018 12:00:00 PM	TXOH: K96-417: 26916656	-	8	5	CMP	Out-S-Out,Out	0	28 Other Cause	Unselected	Unselected	Florence	OK ARRIVAL
672	8119861	Villa-H9322430044	11/15/2018 6:01:52 PM	11/17/2018 6:03:00 PM	11/18/2018 12:00:00 PM	TXUG: K97-60: 26917594	-	1	1	CMP	Pi O-LF	0	11 Unknown Cause	Unselected	12 Checked Voltage/Fixed Connect	Florence	CMPL 2018-11-17 18:03:00 by WACASSO RMK: PING ON - REQ 8123026 as of 11/16/2018 10:54. cst rpt pt pwr - flickering and very dim lights heating unit will not come on ph 859-409-2286. Espahr 513-458-3803
673	8119895	Wilder-H9320590041	11/15/2018 6:00:21 PM	11/16/2018 1:02:00 AM	11/18/2018 12:00:00 PM	TXOH: CA11-441: 26898672	-	1	3	CMP	PP-H-911-Out,PP-H-Othr-O-Othr,PH-H-Out	0	03 Vegetation	-	22 Cut Off/Disconnect at Pole	Florence	CMPL 2018-11-16 01:02:00 by T17636 RMK: CA11-441C COOP # 4 TRI. SERVICE REFERRED TO ELECTRIC CONTRACTOR. RK1. SERVICE ENTRANCE CABLE, AND WEATHER HEAD. CUSTOMER CONTACT. CUT CABLE TV IN CLEAR.
674	8119939	Bellevue-H9321310042	11/15/2018 10:00:31 AM	11/16/2018 10:27:00 AM	11/16/2018 11:30:00 AM	TXOH: CA5-43: 26900784	-	9	23	CMP	PH-H-Tree-PH-Out,Out	0	03 Vegetation	Unselected	18 Customer Trouble/No Outage	Florence	138 STRTATHMORE WILL REQ A NEW TRIPLEX WHEN PORV ELEC IS COMPLE W/ WORK. WIL REQ INSP
675	8119964	White Tower-H9323040041	11/15/2018 6:10:14 PM	11/17/2018 12:49:31 PM	11/18/2018 12:00:00 PM	TXOH: 23K-331: 26928272	-	0	1	CMP	Obj-L-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OK
676	8119991	Kenton-H9320090044	11/15/2018 6:12:20 PM	11/16/2018 6:28:38 PM	11/18/2018 12:00:00 PM	TXOH: K63-7: 26910651	-	1	1	CMP	PH-H-Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	PING ON - REQ 8123022 as of 11/16/2018 10:54. Line down in backyard between home and neighbors. Espahr 513-458-3803. MADE REPAIRS BACK IN SERVICE
677	8119994	Villa-H9322430043	11/15/2018 8:29:50 AM	11/17/2018 1:44:06 PM	11/18/2018 12:00:00 PM	TXOH: K95-566: 26927587	-	1	2	CMP	PH-H-Tree-PH-Out,PH-H-Out	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	-
678	8120017	Donaldson-H9320550041	11/15/2018 12:57:44 PM	11/17/2018 6:17:00 PM	11/18/2018 12:00:00 PM	TXOH: K116-367: 26906736	-	0	3	CMP	PH-H-911-Othr,PH-H-Tree-PH-On,PH-H-On	0	EA Weather	Unselected	26 OK Arrival	Florence	
679	8120044	Hands-H9321280041	11/15/2018 6:18:31 PM	11/18/2018 2:12:35 PM	11/18/2018 4:40:00 PM	TXOH: 15K-170: 164866233	-	1	1	CMP	PH-H-Out	0	EA Weather	Unselected	30 Phone or TV Cable Problem	Florence	PING ON - REQ 8123018 as of 11/16/2018 10:54. line down on front yard and gravel driveway and going up to neighbors home. ROLL UP 200 FT. OF 2-WIRE FEEDING STREET LIGHTS,AT BASE OF POLE--already completed by DAN Elsb
680	8120059	Crittenden-H9321240041	11/15/2018 6:20:33 PM	11/17/2018 5:44:09 PM	11/18/2018 12:00:00 PM	TXUG: 10G-35: 26918144	-	1	13	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK AS OF 5:42 PM ON 11.17.18 TOM GEIMAN 513.446.4723 - PREMISE PING ON - REQ 8122761 as of 11/16/2018 10:13. reset breakers/when resetting breakers gets error message "error 4" after flashing the reading/. Espahr 513-458-3803
681	8120107	Crittenden-H9321240042	11/15/2018 6:25:25 PM	11/17/2018 2:53:41 PM	11/18/2018 12:00:00 PM	TXOH: 26874330	-	0	1	CMP	PH-H-On	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	-
682	8120178	Verona-H9321250042	11/15/2018 6:32:55 PM	11/16/2018 5:16:55 PM	11/18/2018 12:00:00 PM	TXOH: 50BN-701: 26894222	-	0	1	CMP	On	0	EA Weather	Unselected	35 OK per Phone Call	Florence	Spoke to Mr Aull, said believes spectrum has taken care of the issue.

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
683	8120189	Hands-H9321280045	11/15/2018 6:34:26 PM	11/17/2018 2:13:57 PM	11/18/2018 12:00:00 PM	TXOH: 15K-1260-26874609	-	1	1	CMP	PH-H-Out-Othr-O	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING ON - REQ 8122757 as of 11/16/2018 10:12. Customer said to check transformer. ESphr 513-458-3803. IN AND OKAY. KEVIN LANHAM 513-504-1488
684	8120233	Donaldson-H9320550041	11/15/2018 6:40:28 PM	11/17/2018 7:13:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-149-26904680	-	0	1	CMP	PP-H-Othr-O-On	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-17 19:13:00 by CMTURNE RMK: Spoke to ms Mcknight. Confirmed issue resolved. She called about wire down on Cowie Ave. Cleared earlier today. Assoc with Event #8109619. 3514 Cowie Ave, Erlanger.
685	8120271	Bellevue-H9321310043	11/15/2018 6:48:41 PM	11/17/2018 12:50:00 PM	11/18/2018 12:00:00 PM	TXOH: CA8-349-26921984	-	0	1	CMP	PH-H-On	0	20 Equipment failure	Unselected	23 Found on Inspection	Florence	CMPL 2018-11-17 12:50:00 by CLWILLS RMK: rk1 and weatherhead pulled loose from house from pole CA8-485 customer has power service crew needed tyler burns513-335-2291 rk1 and weatherhead pulled loose from house from pole CA8-485 customer has power servi
686	8120436	Bellevue-H9321310042	11/15/2018 7:10:12 PM	11/17/2018 10:08:14 AM	11/18/2018 12:00:00 PM	TXOH: CA5-116-26909090	-	0	1	CMP	Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ok on arrival no duke work required
687	8120438	Buffington-H9320670045	11/15/2018 5:42:57 PM	11/16/2018 10:28:27 AM	11/18/2018 12:00:00 PM	TXOH: K105-449-26904113	-	1	1	CMP	Out-S-Out	0	03 Vegetation	Unselected	Unselected	Florence	PING ON - REQ 8122750 as of 11/16/2018 10:12. ESphr 513-458-3803. Ticket being completed.
688	8120453	Wilder-H9320590045	11/15/2018 7:13:19 PM	11/15/2018 7:50:00 PM		FOH: CA11-136-25993246	100T	81	16	CMP	Out	0	EA Weather	Unselected	44 Replaced Fuse	Florence	-
689	8120480	Limaburg-H9321890041	11/15/2018 7:21:01 PM	11/18/2018 9:50:00 AM	11/18/2018 12:00:00 PM	TXOH: 19BN-512-26868281	-	0	2	CMP	PP-H-Othr-O-Othr,PH-H-On	0	03 Vegetation	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-18 09:50:00 by T81490 RMK: HOUSE KNOB RIPPED OFF. SERVICE LOW. COOP - 2ND ASSESSMENT JOE GROESCHEN 8592500319 - WHEAD. SEC. SERVICE ATTACMENT STILL PULLED OFF HOUSE SERVICE HANGING LOW ACROSS DRIVE TO POLE 19BN-512C LEFT DOOR HANGER CUST N
690	8120496	Decoursey-H9322990041	11/15/2018 7:25:51 PM	11/17/2018 10:20:37 AM	11/18/2018 12:00:00 PM	TXOH: 11K-764-26862338	-	1	2	CMP	PH-H-Out,PH-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING ON - REQ 8122749 as of 11/16/2018 10:12. line laying on road neighborhood area only one way out and people in need of getting out to apts, elderly people in this area. ESphr 513-458-3803. IN AND OK ALAN EAST 513-313-9220
691	8120545	Decoursey-H9322990041	11/15/2018 10:33:50 AM	11/17/2018 10:18:33 AM	11/18/2018 12:00:00 PM	TXOH: 11K-773-26872221	-	0	2	CMP	PH-H-Tree-PH-Othr,PH-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OK
692	8120624	Buffington-H9320670045	11/15/2018 7:49:56 PM	11/17/2018 8:17:25 PM	11/18/2018 12:00:00 PM	TXOH: K105-817-26864460	-	0	1	CMP	PH-H-Tree-PH-On	0	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	Mr. Collett said no change tree still on line from pole to bldg and hanging low
693	8120752	Empire-H9322890041	11/15/2018 8:11:06 PM	11/17/2018 6:07:00 PM	11/18/2018 12:00:00 PM	TXOH: 31BN-814-26883566	-	1	1	CMP	PH-H-Tree-PH-Out	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	PING OFF - REQ 8122748 as of 11/16/2018 10:13. Service from pole to house is down. ESphr 513-458-3803
694	8120768	Villa-H9322430043	11/15/2018 8:13:40 PM	11/16/2018 8:35:00 PM	11/18/2018 12:00:00 PM	TXOH: K96-586-26917314	-	1	2	CMP	PP-H-Tree-PP-On,PH-H-Tree-PH-Out	0	03 Vegetation	Unselected	26 OK Arrival	Florence	CMPL 2018-11-16 20:35:00 by T95129 RMK: folo bowlin onsite and done
695	8120772	Decoursey-H9322990041	11/15/2018 8:15:03 PM	11/17/2018 4:33:00 PM	11/18/2018 12:00:00 PM	TXOH: 8K-129-26896809	-	0	1	CMP	PP-H-Othr-O-On	0	03 Vegetation	-	30 Phone or TV Cable Problem	Florence	CMPL 2018-11-17 16:33:00 by WACASSO RMK: PHONE DROP
696	8120776	Verona-H9321250041	11/15/2018 8:16:00 PM	11/15/2018 8:16:03 PM		S-RCL: 31212-33K-359-26229334	-	182	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	RECL 31212 O/ PH A
697	8120806	Villa-H9322430043	11/15/2018 8:22:08 PM	11/16/2018 8:27:00 PM	11/18/2018 12:00:00 PM	TXOH: K97-254-26917497	-	1	1	CMP	Tree-PP-Out	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-16 20:27:00 by T95129 RMK: removed limb from 1/0 phase, 100ft oak in rear and dead ash around phases. referred to veg mang
698	8120916	Crescent-H9320700043	11/15/2018 8:46:48 PM	11/16/2018 10:16:03 AM	11/18/2018 12:00:00 PM	TXOH: K73-493-26912663	-	1	1	CMP	Out-S-Out	0	03 Vegetation	Unselected	Unselected	Florence	PING ON - REQ 8122741 as of 11/16/2018 10:10. ESphr 513-458-3803. Ticket being Completed
699	8120972	Buffington-H9320670045	11/15/2018 5:46:29 PM	11/17/2018 5:43:25 PM	11/18/2018 12:00:00 PM	TXOH: K105-990-26904444	-	0	1	CMP	PP-H-Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	M.ORTH 859-300-4794. IN & OK.
700	8120975	Buffington-H9320670045	11/15/2018 5:49:01 PM	11/17/2018 7:57:33 PM	11/18/2018 12:00:00 PM	TXOH: K106-567-26906063	-	0	1	CMP	PP-H-Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OK
701	8121095	Crescent-H9320700044	11/15/2018 6:21:27 AM	11/17/2018 10:50:00 AM	11/18/2018 12:00:00 PM	FOH: K93-291-366463041	-	10	19	CMP	PP-H-Tree-PP-Out,PP-H-Out-Othr-O,PP-H-Out,PH-H-Out,Out-Dmg,Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	PING - OFF - REQ 8122302 as of 11/16/2018 9:01. ESphr 513-458-3803
702	8121201	Kenton-H9320090044	11/15/2018 9:40:01 AM	11/15/2018 9:45:00 PM	11/18/2018 12:00:00 PM	FOH: K73-224-85184562	-	64	1	CMP	Out	0	EA Weather	Unselected	27 Other/See Notes	Florence	-
703	8121231	Alexandria South-H9322050041	11/15/2018 10:14:02 PM	11/16/2018 12:55:00 PM	11/18/2018 12:00:00 PM	TXOH: 47CA-325-26920311	-	0	1	CMP	Tree-PH-On	0	03 Vegetation	-	27 Other/See Notes	Florence	CMPL 2018-11-16 12:55:00 by T24175 RMK: removed branches off serv-ok
704	8121240	Kenton-H9320090044	11/15/2018 9:40:01 AM	11/16/2018 3:25:57 PM	11/18/2018 12:00:00 PM	P1OH: 12202646	-	19	13	CMP	Out-S-Out,Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	WIRE DOWN REAR OF 1420 HENRY CLAY POLE # K63-25C BREAKS CUT AT POLE# K63-23C GROUND TAG # 20549
705	8121242	White Tower-H9323040041	11/15/2018 10:07:31 PM	11/15/2018 10:56:00 PM	11/18/2018 12:00:00 PM	TXUG: KNK-609-27092254	-	0	1	CMP	Othr	0	28 Other Cause	-	27 Other/See Notes	Florence	CMPL 2018-11-15 22:56:00 by T27867 RMK: UNSEALED METER OK
706	8121322	Oakbrook-H9322100042	11/15/2018 11:16:48 PM	11/15/2018 11:16:50 PM		S-RCL: 7495- BNK-5451-53035198	MLD	357	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	recl 7495 o/ ph c
707	8121328	Longbranch-H9320980042	11/15/2018 11:22:38 PM	11/16/2018 6:04:00 AM	11/16/2018 4:00:00 PM	TXUG: BNK-2907-27159607	-	1	1	CMP	PD-E-911-Out-PF	0	09 Public Accident/Dam age	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-16 06:04:00 by T22400 RMK: P# 35BN-249 NEEDS CHANGED 3PH 45CL4 NEED FLAGGER . ON OUTAGE, NEEDS DONE TODAY
708	8121351	Buffington-H9320670045	11/15/2018 9:02:59 PM	11/16/2018 10:09:19 AM	11/18/2018 12:00:00 PM	TXOH: K105-451-26904129	-	1	1	CMP	Out	0	03 Vegetation	Unselected	Unselected	Florence	PING ON - REQ 8122603 as of 11/16/2018 9:46. ESphr 513-458-3803. Ticket being completed.
709	8121352	Buffington-H9320670045	11/15/2018 7:31:59 PM	11/16/2018 10:06:30 AM	11/18/2018 12:00:00 PM	TXOH: K105-721-26904871	-	1	1	CMP	Out-S-Out	0	03 Vegetation	Unselected	Unselected	Florence	PING ON - REQ 8122599 as of 11/16/2018 9:46. ESphr 513-458-3803. Ticket is being completed

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
710	8121367	Hebron-H9321520045	11/15/2018 6:00:52 PM	11/17/2018 5:30:00 PM	11/18/2018 12:00:00 PM	TXOH: 14BN-315: 26867562	-	1	2	CMP	PH-H-Tree-PH-On,Out	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 17:30:00 by T29408 RMK: PING OFF - REQ 8122597 as of 11/16/2018 9:46. Line is down. ESphr 513-458-3803
711	8121392	Donaldson-H9320550043	11/16/2018 12:20:14 AM	11/16/2018 12:49:00 PM	11/18/2018 12:00:00 PM	TXOH: 21BN-385: 26877613	-	1	1	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-16 12:49:00 by T2595 RMK: PING OFF - REQ 8122594 as of 11/16/2018 9:46. ESphr 513-458-3803, NEEDS REPAIRS TO HOUSE FOR REC AT POLE
712	8121418	Constance-H9320420042	11/15/2018 10:27:46 AM	11/16/2018 5:16:45 PM	11/18/2018 12:00:00 PM	TXUG: KNK-5916: 393399128	-	1	1	CMP	PH-H-Pi O	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING OFF - REQ 8122590 as of 11/16/2018 9:46 kitchen out and 150 seniors in facility. ESphr 513-458-3803 IN & OK ROB MILLER 513 543 8745
713	8121476	Villa-H9322430041	11/16/2018 1:48:14 AM	11/16/2018 1:48:29 AM		S-RCL: 4226: K74-84: 164009350	-	29	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	RECL 4226 O/ PH AB
714	8121503	Buffington-H9320670045	11/16/2018 1:38:01 AM	11/17/2018 2:08:37 PM	11/18/2018 12:00:00 PM	TXOH: K106-1035: 26905711	-	1	4	CMP	PH-H-Tree-PH-On,PH-H-On,PI O On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING ON - REQ 8122477 as of 11/16/2018 9:31. partial power. ESphr 513-458-3803 M.ORTH 859-300-4794 11/17/18. IN & OK.
715	8121641	Hebron-H9321520042	11/15/2018 8:43:26 PM	11/17/2018 7:42:17 PM	11/18/2018 12:00:00 PM	TXOH: 6BN-401: 26871378	-	0	1	CMP	PP-H-Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ok arrival. telephone trunk line is tied up.1 no sign of anything else on line must have already been removed if it was even on our power line
716	8121648	Cold Spring-H9321320041	11/16/2018 5:04:45 AM	11/16/2018 1:50:00 PM	11/18/2018 12:00:00 PM	TXOH: 39CA-1052: 26890874	-	1	1	CMP	Pi O	0	11 Unknown Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-16 13:50:00 by T24175 RMK: checked voltage at meter base 119.4-119.5-238 ok cc
717	8121730	Crescent-H9320700043	11/15/2018 6:58:05 AM	11/17/2018 7:14:00 AM	11/18/2018 12:00:00 PM	TXOH: K83-152: 26925679	-	1	3	CMP	PH-H-Tree-PH-Out,Othr-H-Tree-PH-Out,Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING ON - REQ 8122466 as of 11/16/2018 9:30. Live line tree sitting on it. across street from school. kids walking around it. ESphr 513-458-3803
718	8121750	Florence-H9322410042	11/16/2018 6:47:45 AM	11/17/2018 10:06:07 PM	11/18/2018 12:00:00 PM	TXOH: K116-88: 399320545	-	1	1	CMP	Pi O	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	PING ON - REQ 8122423 as of 11/16/2018 9:24. Power to elevator not getting 3 phase power. ESphr 513-458-3803. ALL FUSES IN GOOD 3P VOLTAGE
719	8121905	Crescent-H9320700041	11/17/2018 11:04:04 AM	11/17/2018 4:57:00 PM	11/18/2018 12:00:00 PM	TXOH: K84-437: 26926614	-	0	0	CMP	PH-H-Out,Tree-PH-Out	0	28 Other Cause	Unselected	11 Checked Voltage/All OK	Florence	CMPL 2018-11-17 16:57:00 by T39767 RMK: PING ON - REQ 8122337 as of 11/16/2018 9:08. Lines down in back yard. ESphr 513-458-3803
720	8121968	Buffington-H9320670045	11/16/2018 7:53:41 AM	11/17/2018 1:59:02 PM	11/18/2018 12:00:00 PM	TXOH: K106-1021: 26905678	-	0	1	CMP	PH-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	M.ORTH 859-300-4794. IN & OK.
721	8121988	Buffington-H9320670045	11/16/2018 7:57:35 AM	11/17/2018 7:23:00 PM	11/18/2018 12:00:00 PM	TXOH: K117-81: 26907797	-	0	1	CMP	PP-H-911-Tree-PP On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	-
722	8121992	Augustine-H9320780046	11/16/2018 7:58:11 AM	11/18/2018 12:50:00 AM	11/18/2018 12:00:00 PM	TXOH: K72-483: 26912474	-	0	1	CMP	Tree-PH-On	0	03 Vegetation	-	37 Removed Limb or Tree From Lin	Covington	CMPL 2018-11-18 00:50:00 by T17410 RMK: remove limb 1/0 tri
723	8122069	Villa-H9322430041	11/15/2018 1:32:05 PM	11/17/2018 4:21:51 PM	11/18/2018 12:00:00 PM	TXOH: K84-84: 26926193	-	0	3	CMP	PH-H-Obj-L-On,PH-H-Tree-PH-Othr,911-Othr	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	-
724	8122154	Alexandria South-H9322050041	11/16/2018 8:34:21 AM	11/16/2018 3:54:32 PM	11/18/2018 12:00:00 PM	TXUG: 44CA-913: 26892837	-	1	2	CMP	Out,VF-On	0	28 Other Cause	Unselected	18 Customer Trouble/No Outage	Florence	1 LEG DEAD UG PER DUKE. CUST NOT HOME. NOT SURE ABOUT WIRE CARE.
725	8122156	Kenton-H9320090044	11/16/2018 8:34:50 AM	11/16/2018 6:29:37 PM	11/18/2018 12:00:00 PM	TXOH: K73-228: 26913144	-	1	1	CMP	Tree-PH-Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	4 SERVICES DOWN COMING FROM THE POLE AND ALL 4 OF THE SERVICES WERE FIXED AND ALL CUSTOMERS RESTORED
726	8122175	Kenton-H9320090046	11/16/2018 8:36:54 AM	11/17/2018 3:45:00 PM	11/18/2018 12:00:00 PM	TXOH: 7K-260: 26896426	-	0	1	CMP	PH-H-On	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	-
727	8122180	Alexandria South-H9322050041	11/16/2018 8:38:01 AM	11/17/2018 12:28:57 PM	11/18/2018 12:00:00 PM	TXOH: CAK-4421: 391854768	-	0	1	CMP	PH-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ok on arrival no duke work required
728	8122185	Bellevue-H9321310042	11/16/2018 8:39:40 AM	11/17/2018 8:23:58 AM	11/18/2018 12:00:00 PM	TXOH: CA5-43: 26900784	-	1	2	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	in and ok no duke work required
729	8122193	Villa-H9322430041	11/15/2018 4:39:26 PM	11/17/2018 2:58:08 PM	11/18/2018 12:00:00 PM	TXOH: K84-206: 26926683	-	0	3	CMP	PH-H-Obj-L-On,PH-H-Tree-PH-On,Tree-PH-On	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	rob miller 513 543 8745 ENERGIZED SERVICE HANGING ACROSS ROAD OVER COMMUNICATION AND HANGING LOW AT HOUSE. SEC PULLED AWAY AND RK1 PULLED OUT-DISCONNECT SERVICE-CUSTOMER ADVISED TO MAKE REPAIRS
730	8122215	Augustine-H9320780046	11/15/2018 8:39:38 AM	11/16/2018 8:10:37 PM	11/18/2018 12:00:00 PM	TXOH: K72-462: 26912286	-	5	2	CMP	PH-H-Tree-PH-Out,Tree-PH-Out,Out-Dmg	0	28 Other Cause	Unselected	27 Other/See Notes	Covington	K GOETZ 859-404-1222. SERVICE PULLED FROM HOUSE. INFORMED CUSTOMER OF REPAIRS NEEDED. FUSE BLOWN ON POLE K72-100E PH B. 100T NEAR INTERSECTION OF AMSTERDAM AND FT HENRY. SPAN BTWN K72-466E & 465E IS LOW. NEEDS TO BE RE-SLACKED. REAR LOT NEAR 1723 FT HE
731	8122309	Villa-H9322430041	11/16/2018 9:03:05 AM	11/17/2018 12:41:20 PM	11/18/2018 12:00:00 PM	TXOH: K74-42: 26925054	-	0	1	CMP	PH-H-Tree-PH-LF-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NICK HAMILTON 513-240-8825 SERVICE IN/OK. CUST. CONCERNED ABOUT TREE LIMBS OVER SERVICE. NO ISSUES FOUND
732	8122334	Augustine-H9320780043	11/16/2018 9:08:02 AM	11/17/2018 2:45:00 AM	11/18/2018 12:00:00 PM	TXOH: K52-604: 26909108	-	0	1	CMP	Tree-PH-On	0	EA Weather	-	26 OK Arrival	Covington	CMPL 2018-11-17 02:45:00 by T18514 RMK: NO OUTAGE NPF
733	8122343	Kenton-H9320090044	11/16/2018 9:09:42 AM	11/17/2018 5:37:10 PM	11/18/2018 12:00:00 PM	TXOH: K73-317: 26912916	-	0	1	CMP	Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	-
734	8122369	Oakbrook-H9322100042	11/16/2018 9:15:09 AM	11/16/2018 9:15:13 AM		S-RCL: 7495: BNK-5451: 53035198	MLD	357	0	M-CMP	-	0	EA Weather	Unselected	10 Automatic Restoration	Florence	RECL 749578, PHASE C O/I
735	8122370	Bellevue-H9321310043	11/16/2018 9:15:12 AM	11/16/2018 11:18:00 AM	11/18/2018 12:00:00 PM	TXOH: CA8-162: 26921853	-	1	2	CMP	Out-Othr-O,Out	0	03 Vegetation	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-16 11:18:00 by T66296 RMK: RECONNECT SERVICE CUST MADE PERM REPAIRS
736	8122403	Hands-H9321280041	11/16/2018 9:21:22 AM	11/17/2018 5:25:37 PM	11/17/2018 6:10:00 PM	TXOH: 14K-319: 26873931	-	0	1	CMP	PH-H-On	0	EA Weather	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 17:24:00 by T25446 RMK: CUST SERVICE TORN OFF HOUSE AND TRI-PLEX ON GROUND,STILL HAS ELECTRIC

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
737	8122405	Buffington-H9320670045	11/16/2018 9:21:59 AM	11/17/2018 6:57:00 PM	11/17/2018 7:45:00 PM	TXOH: K116-678: 26907382	-	0	1	CMP	PH-H-Othr-O-LV-On	0	03 Vegetation	-	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-17 18:57:00 by T81490 RMK: triplex serv down p-h, low across st, police blocked st and taped off area wh, sec and mtr base tore off house still energized
738	8122408	Beaver-H9320860041	11/16/2018 9:22:38 AM	11/16/2018 1:38:50 PM	11/18/2018 12:00:00 PM	TXOH: 50BN-196: 26920960	-	1	1	CMP	Out-S-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	JOE GROESCHEN 8592500319 IN/OK
739	8122419	Oakbrook-H9322100042	11/16/2018 9:23:54 AM	11/16/2018 9:23:55 AM		S-RCL: 7495: BNK-5451: 53035198	MLD	357	0	M-CMP	-	0	-	-	-	Florence	-
740	8122436	York-H9320770043	11/16/2018 9:06:59 AM	11/17/2018 1:06:09 PM	11/18/2018 12:00:00 PM	TXOH: CA6-1784: 26901411	-	0	2	CMP	Othr-O-Othr-Othr-O-On	0	EA Weather	Unselected	20 Cut In/Reconnect at Pole	Florence	-
741	8122454	Oakbrook-H9322100042	11/16/2018 9:29:18 AM	11/16/2018 3:16:37 PM	11/18/2018 12:00:00 PM	TXUG: 25BN-89: 26879698	-	0	1	CMP	MO-Othr	0	28 Other Cause	Unselected	35 OK per Phone Call	Florence	-
742	8122461	Oakbrook-H9322100042	11/16/2018 9:30:20 AM	11/16/2018 3:15:39 PM	11/18/2018 12:00:00 PM	TXUG: BNK-1548: 27129227	-	0	2	CMP	Othr	0	28 Other Cause	Unselected	35 OK per Phone Call	Florence	-
743	8122499	Oakbrook-H9322100042	11/16/2018 9:38:15 AM	11/16/2018 12:56:21 PM	11/18/2018 12:00:00 PM	S-RCL: 7495: BNK-5451: 53035198	MLD	1270	370	S-CMP	Othr-H-Out-Othr-O	0	11 Unknown Cause	20 Equipment failure	32 Pole Tied Up Temporarily	Florence	CMPL 2018-11-16 12:55:00 by WACASSO RMK: SECT 749578 L/O. PHASE C TO GRD FAULT.
744	8122510	Augustine-H9320780046	11/16/2018 9:37:28 AM	11/17/2018 11:40:04 AM	11/18/2018 12:00:00 PM	TXOH: K62-402: 26865841	-	6	2	CMP	Out	0	EA Weather	Unselected	29 Permanent Repair	Covington	THIS NEEDS TO BE DONE IN THE DAYLIGHT AS OF 11/18/18 @ 19:38...BRING A ROLL OF 1/0 TRIPLEX
745	8122517	Kenton-H9320090044	11/16/2018 9:38:19 AM	11/17/2018 12:04:16 PM	11/18/2018 12:00:00 PM	TXOH: K63-58: 26910150	-	0	1	CMP	PH-H-On	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	-
746	8122546	Buffington-H9320670045	11/16/2018 9:41:58 AM	11/17/2018 3:55:02 PM	11/18/2018 12:00:00 PM	TXUG: KNK-1607: 27107480	-	0	1	CMP	PP-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	M.ORTH 859-300-4794. IN & OK.
747	8122551	Bellevue-H9321310043	11/15/2018 9:27:30 AM	11/17/2018 8:35:59 AM	11/18/2018 12:00:00 PM	TXOH: CA7-625: 26902211	-	1	1	CMP	Othr-H-Tree-PH-Out-S-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	in and ok on arrival no duke work required tyler burns 513-335-2291
748	8122600	Alexandria South-H9322050041	11/16/2018 9:46:31 AM	11/16/2018 8:45:37 PM	11/18/2018 12:00:00 PM	TXOH: 40CA-226: 26891276	-	1	1	CMP	PH-H-Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	ICE PULLED HOUSE KNOB OUT OF THE HOUSE. RE-ATTACHED BACK TO HOUSE. NO OUTAGE
749	8122604	Florence-H9322410046	11/16/2018 9:46:44 AM	11/17/2018 7:36:12 PM	11/18/2018 12:00:00 PM	TXOH: 31BN-241: 26883797	-	1	2	CMP	CC-H-Out,Othr-H-Tree-PP-On	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	no outage-broken 5' cross arm on field side appears to be 4kv neutral pin and broken insulator base of pole # 31BN-241E. Small branch hanging on primary line. secured area around pole with caution tape. TREE LIMB REMOVED
750	8122623	Oakbrook-H9322100041	11/16/2018 9:50:02 AM	11/17/2018 2:29:02 PM	11/18/2018 12:00:00 PM	TXOH: 20BN-694: 26868977	-	0	1	CMP	LF-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NICK HAMILTON 513-240-8825. SERVICE IN/OK CHECKED METER. TALKED TO CUSTOMER ON SITE. THEY HAVE POWER. NO ISSUES FOUND.
751	8122655	Villa-H9322430042	11/16/2018 9:54:12 AM	11/16/2018 11:20:34 AM	11/18/2018 12:00:00 PM	TXOH: K95-348: 26927540	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OK
752	8122710	Kenton-H9320090044	11/15/2018 9:48:57 PM	11/16/2018 7:46:15 PM	11/18/2018 12:00:00 PM	TXOH: K73-641: 26912839	-	15	4	CMP	PP-H-Pt O PH-H-Othr,PH-H-Pt O PH-H-Othr	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	PING ON - REQ 8122740 as of 11/16/2018 10:09. Service line down. ESphr 513-458-3803. DOWN SERVICE. CUSTOMER IS BACK ON
753	8122736	Hebron-H9321520041	11/16/2018 10:08:51 AM	11/17/2018 11:40:00 AM	11/18/2018 12:00:00 PM	TXOH: 13BN-205: 26873169	-	0	1	CMP	PP-H-Tree-PP-On	0	28 Other Cause	-	26 OK Arrival	Florence	CMPL 2018-11-17 11:40:00 by T24406 RMK: NO ISSUE
754	8122738	Donaldson-H9320550041	11/16/2018 10:09:05 AM	11/16/2018 8:24:44 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-586: 26918716	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
755	8122815	Villa-H9322430041	11/16/2018 10:18:18 AM	11/17/2018 1:35:45 PM	11/18/2018 12:00:00 PM	TXOH: K74-59: 26924920	-	0	2	CMP	PH-H-On	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	CUST REQ CLAMPS FOR SEC. OK TEMPO.
756	8122824	Crescent-H9320700041	11/16/2018 10:19:26 AM	11/16/2018 7:59:44 PM	11/18/2018 12:00:00 PM	TXOH: K83-73: 26925523	-	0	1	CMP	PP-H-On	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CHRIS TIBBS STATES THIS IS A PHONE WIRE
757	8122841	Wildier-H9320590041	11/16/2018 10:23:06 AM	11/17/2018 4:40:00 PM	11/18/2018 12:00:00 PM	TXOH: CA8-315: 26921837	-	0	1	CMP	PH-H-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 16:40:00 by T84692 RMK: medium limb on customer service line neutral is broke 1/0tpx. customer weather head pulled of house pole CA8-315 service crew needed medium limb on service line neutral broke 1/0tpx weatherhead pulled off house s
758	8122845	Kenton-H9320090044	11/16/2018 10:24:17 AM	11/17/2018 6:05:15 PM	11/18/2018 12:00:00 PM	TXOH: KNK-3315: 27175928	-	0	1	CMP	PH-H-Obj-L-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	COMMUNICATION LINE DOWN, CUSTOMER CONTACT MADE. IN & OKAY; CPC HEATHER LEET 513-630-8595
759	8122909	York-H9320770043	11/16/2018 10:35:18 AM	11/16/2018 8:55:00 PM	11/18/2018 12:00:00 PM	TXOH: CA3-121: 26929794	-	20	3	CMP	Out	0	03 Vegetation	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-16 20:55:00 by T66296 RMK: R TO E ON WH RK1 ENTRANCE TO BE RE ATTACHED
760	8122920	Buffington-H9320670045	11/16/2018 10:37:33 AM	11/16/2018 8:14:01 PM	11/18/2018 12:00:00 PM	TXOH: K117-383: 26907449	-	1	1	CMP	PH-H-Tree-PH-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	TOM GEIMAN 513.446.4723 IN&OK
761	8122925	Crescent-H9320700043	11/16/2018 10:38:00 AM	11/17/2018 8:06:15 AM	11/18/2018 12:00:00 PM	TXOH: K84-341: 26925927	-	0	1	CMP	Tree-PH-VF-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	MANNING - 513-218-6533 - OK ARRIVAL
762	8122932	Wildier-H9320590045	11/16/2018 10:38:35 AM	11/16/2018 7:37:15 PM	11/18/2018 12:00:00 PM	TXOH: CA13-167: 26899425	-	1	4	CMP	PH-H-On,Tree-PH-On,Out,Dmg-On	0	03 Vegetation	Unselected	48 Replaced Service/Secondary	Florence	CMPL 2018-11-15 17:35:00 by T17410 RMK: Tree on 1/0ALTX service from Pole # CA19-167E @ address 136 Sherman, Ft. Thomas Ky - Tree trimming required / Service crew - Customer Repairs Needed - L. Grothaus 513-906-0133 / disconnect # 4tri, refer to electric
763	8122953	Villa-H9322430043	11/16/2018 10:41:10 AM	11/17/2018 2:23:59 PM	11/18/2018 12:00:00 PM	TXOH: K86-125: 26927103	-	0	1	CMP	PH-H-On	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	-
764	8122969	Augustine-H9320780043	11/16/2018 10:43:14 AM	11/16/2018 3:40:09 PM	11/18/2018 12:00:00 PM	TXOH: K52-653: 26908669	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Covington	-
765	8122984	Donaldson-H9320550044	11/16/2018 10:45:50 AM	11/16/2018 8:10:00 PM	11/18/2018 12:00:00 PM	TXUG: K104-25: 26903897	-	1	1	CMP	Out	0	28 Other Cause	-	11 Checked Voltage/All OK	Florence	CMPL 2018-11-16 20:10:00 by T33329 RMK: NO ONE ON PREM. LINE AND LOAD VOLTAGE. SERV AVAIL

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
766	8123004	Oakbrook-H9322100042	11/16/2018 10:50:44 AM	11/16/2018 3:14:45 PM	11/18/2018 12:00:00 PM	TXUG: 25BN-19:26879972	-	1	1	CMP	Out-Othr-PQ	0	28 Other Cause	Unselected	35 OK per Phone Call	Florence	-
767	8123050	Hands-H9321280044	11/15/2018 7:37:01 AM	11/16/2018 10:35:13 PM	11/18/2018 12:00:00 PM	TXOH: K87-190:26914956	-	8	7	CMP	PH-H-Tree-PH-Out,PH-H-PI O.Out	0	EA Weather	Unselected	29 Permanent Repair	Florence	REMOVED TREE AND REPAIRED SERV
768	8123086	Buffington-H9320670045	11/16/2018 11:02:26 AM	11/16/2018 4:08:36 PM	11/18/2018 12:00:00 PM	TXOH: K105-511:26904896	-	1	1	CMP	Out	0	28 Other Cause	Unselected	39 Repaired Overhead Conductor	Florence	-
769	8123091	Florence-H9322410045	11/16/2018 11:03:34 AM	11/16/2018 8:23:23 PM	11/18/2018 12:00:00 PM	TXUG: 25BN-364:26879819	-	1	2	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
770	8123194	Villa-H9322430043	11/15/2018 11:14:24 AM	11/16/2018 1:05:35 PM	11/18/2018 12:00:00 PM	TXOH: K95-70:26927715	-	25	9	CMP	PH-H-Tree-PP-Out,PH-H-Tree-PH-Out,PH-H-Tree-PH-On,PH-H-On,Tree-PH-Out,Out-S-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	In & OK now. Issue was worked on ticket # 8107644 which C&M has since completed. Per Rob Miller.-RBURT 513-391-7714
771	8123204	Donaldson-H9320550042	11/16/2018 11:21:26 AM	11/17/2018 8:03:41 PM	11/18/2018 12:00:00 PM	TXOH: K104-481:26903938	-	0	1	CMP	PP-H-Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
772	8123239	Crescent-H9320700043	11/16/2018 11:28:04 AM	11/16/2018 1:14:48 PM	11/18/2018 12:00:00 PM	TXOH: K72-5:26912236	-	0	1	CMP	PH-H-On	0	EA Weather	Unselected	26 OK Arrival	Florence	-
773	8123322	Crescent-H9320700043	11/16/2018 11:40:58 AM	11/16/2018 7:58:00 PM	11/18/2018 12:00:00 PM	TXOH: K73-604:26912842	-	1	1	CMP	Out-S-Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
774	8123358	Villa-H9322430041	11/16/2018 11:47:41 AM	11/17/2018 12:40:37 PM	11/18/2018 12:00:00 PM	TXOH: K84-358:26926296	-	0	1	CMP	PP-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
775	8123423	Augustine-H9320780046	11/15/2018 7:12:19 AM	11/16/2018 1:44:44 PM	11/18/2018 12:00:00 PM	FOH: K72-241:25995625	65T	61	2	CMP	Out-S-Out	0	28 Other Cause	Unselected	26 OK Arrival	Covington	ROB MILLER 513 543 8745 IN & OK
776	8123500	Limaburg-H9321890041	11/16/2018 12:14:39 PM	11/18/2018 11:09:00 AM	11/18/2018 12:00:00 PM	TXOH: 19BN-625:26888017	-	0	1	CMP	Tree-PH-On	0	03 Vegetation	-	11 Checked Voltage/All OK	Florence	CMPL 2018-11-18 11:09:00 by MHMURRE RMK: ok arrival
777	8123515	Buffington-H9320670041	11/16/2018 12:17:06 PM	11/16/2018 1:49:13 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-227:26881163	-	6	2	CMP	Out	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	-
778	8123526	Florence-H9322410046	11/16/2018 12:19:24 PM	11/17/2018 8:17:00 PM	11/18/2018 12:00:00 PM	TXOH: 31BN-424:26883761	-	1	1	CMP	Tree-PP-On	0	03 Vegetation	Unselected	27 Other/See Notes	Florence	serv down pole-house,RK1 out of brick,sec peeled down wall,meters ok.serv still on large branch on transf. Secured area wit caution tape
779	8123529	Kenton-H9320090044	11/16/2018 12:20:16 PM	11/17/2018 5:38:46 PM	11/18/2018 12:00:00 PM	TXOH: K73-251:26913089	-	0	1	CMP	PH-H-911-Othr	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	-
780	8123544	Augustine-H9320780045	11/16/2018 12:23:24 PM	11/16/2018 9:11:00 PM	11/18/2018 12:00:00 PM	TXOH: K53-718:26923048	-	0	1	CMP	Tree-PH-LF-On	0	28 Other Cause	-	27 Other/See Notes	Covington	CMPL 2018-11-16 21:11:00 by T22595 RMK: VERY SHORT SERVICE FROM POLE TO HOUSE.NO TREES.NO ONE ON PREM
781	8123572	Kenton-H9320090044	11/16/2018 12:28:09 PM	11/17/2018 5:38:15 PM	11/18/2018 12:00:00 PM	TXOH: K73-252:26913156	-	0	1	CMP	Tree-PP-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	-
782	8123581	Florence-H9322410042	11/16/2018 12:31:03 PM	11/17/2018 9:35:00 AM	11/18/2018 12:00:00 PM	TXOH: 26BN-593:26918821	-	0	1	CMP	Tree-PH-On	0	11 Unknown Cause	-	11 Checked Voltage/All OK	Florence	CMPL 2018-11-17 09:35:00 by T24406 RMK: FULL POWER PER CUST
783	8123591	Florence-H9322410044	11/16/2018 12:35:09 PM	11/16/2018 9:34:08 PM	11/18/2018 12:00:00 PM	TXUG: WBNK-2893:27168250	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
784	8123601	Buffington-H9320670045	11/16/2018 12:37:59 PM	11/18/2018 9:18:27 AM	11/18/2018 12:00:00 PM	TXOH: K116-283:26907101	-	3	4	CMP	PP-H-Tree-PP-LF-On,PP-H-LF-On,Out	0	EA Weather	Unselected	22 Cut Off/Disconnect at Pole	Florence	PING - REQ 8123601 - OFF as of 3:48PM 11/17/18. ABraun 513-458-3797 Customer service disconnected for safety Customer advised to get electrician
785	8123625	Donaldson-H9320550042	11/16/2018 12:41:23 PM	11/17/2018 8:38:00 PM	11/17/2018 10:00:00 PM	TXOH: K105-550:26904449	-	0	1	CMP	PP-H-Tree-PP-On	0	EA Weather	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 20:38:00 by T74214 RMK: #2tri up permanent
786	8123645	Donaldson-H9320550042	11/15/2018 1:34:22 PM	11/17/2018 9:00:00 PM	11/17/2018 9:30:00 PM	TXOH: K104-131:26903765	-	0	2	CMP	PH-H-Tree-PH-On,Othr-O-On	0	-	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 21:00:00 by T74214 RMK: removed limb from #4 triplex
787	8123747	Augustine-H9320780046	11/16/2018 12:59:15 PM	11/16/2018 8:07:11 PM	11/18/2018 12:00:00 PM	TXOH: K62-38:26924493	-	1	1	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Covington	CUSTOMER IS OKAY ON ARRIVAL
788	8123766	Buffington-H9320670045	11/16/2018 1:00:17 PM	11/16/2018 4:12:19 PM	11/18/2018 12:00:00 PM	TXOH: K105-611:26904190	-	8	1	CMP	Out	0	03 Vegetation	Unselected	26 OK Arrival	Florence	-
789	8123783	Oakbrook-H9322100042	11/16/2018 9:40:09 AM	11/16/2018 3:10:00 PM	11/18/2018 12:00:00 PM	FUG: 25BN-441:25989272	-	231	48	CMP	Out-S-Out,Out	0	11 Unknown Cause	02 Insufficient Capability	17 Closed Switch	Florence	CMPL 2018-11-16 15:10:00 by WACASSO RMK: FUSE MELTED DUE TO LOAD
790	8123802	Oakbrook-H9322100042	11/16/2018 1:07:50 PM	11/16/2018 1:33:06 PM	11/18/2018 12:00:00 PM	FUG: 25BN-284:25989254	-	82	2	CMP	Out-S-Out	0	28 Other Cause	Unselected	35 OK per Phone Call	Florence	-
791	8123858	Buffington-H9320670041	11/16/2018 1:16:18 PM	11/16/2018 8:18:07 PM	11/18/2018 12:00:00 PM	TXOH: K106-498:26905261	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
792	8123878	Buffington-H9320670041	11/16/2018 1:19:50 PM	11/17/2018 9:07:54 AM	11/18/2018 12:00:00 PM	TXOH: K116-445:26907212	-	0	1	CMP	Tree-PH-On	0	11 Unknown Cause	Unselected	Unselected	Florence	-
793	8124014	Kenton-H9320090044	11/16/2018 1:38:17 PM	11/18/2018 9:00:36 PM	11/18/2018 12:00:00 PM	TXOH: K73-708:26912883	-	0	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	R/TT NEED MAN. TREE CREW. POLE SAW MIGHT WORK. REMOVE 3' LIMB FROM TRIPLEX SERVICE, K73-708, REAR LOT; 1732 MT VERNON DR; CUSTOMER HAS FULL POWER; CPC HEATHER LEET 513-630-8595
794	8124025	Oakbrook-H9322100042	11/16/2018 10:08:04 AM	11/16/2018 3:02:51 PM	11/18/2018 12:00:00 PM	TXUG: BNK-1311:27131327	-	1	2	CMP	Out-S-Out,Out	0	28 Other Cause	Unselected	35 OK per Phone Call	Florence	-
795	8124113	Villa-H9322430043	11/16/2018 11:19:37 AM	11/16/2018 8:28:05 PM	11/18/2018 12:00:00 PM	TXOH: K95-70:26927715	-	1	1	CMP	Out-S-Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
796	8124145	Florence-H9322410045	11/16/2018 1:55:35 PM	11/17/2018 3:23:00 PM	11/17/2018 4:30:00 PM	TXOH: 30BN-496:26882238	-	0	1	CMP	PP-H-On	0	03 Vegetation	-	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-17 15:23:00 by T81490 RMK: TRIPLEX ON GROUND LIVE .WH. SEC AND HOUSE KNOB RIPPED OFF HOUSE. INFORMED CUST TO HAVE REPAIRS MADE .CAUTION TAPED OFF AREA .NEED DROP SERVICE FOR REPAIRS. REAR PROP .NO TRUCK ACCESS

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
797	8124176	Buffington-H9320670045	11/16/2018 2:01:26 PM	11/16/2018 5:47:00 PM	11/18/2018 12:00:00 PM	TXOH: K117-300:26907862	-	1	1	CMP	Out-Othr-O	0	11 Unknown Cause	-	11 Checked Voltage/All OK	Florence	C MPL 2018-11-16 17:47:00 by T27867 RMK: FOUND ALREADY RECONNECTED, FULL POWER, OK
798	8124177	Crescent-H9320700043	11/16/2018 2:01:29 PM	11/16/2018 8:39:15 PM	11/18/2018 12:00:00 PM	TXOH: K83-246:26925746	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
799	8124186	Wilder-H9320590046	11/16/2018 2:03:23 PM	11/16/2018 9:16:02 PM	11/18/2018 12:00:00 PM	TXOH: CA14-338:27117411	-	0	1	CMP	CC-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OK ARRIVAL
800	8124222	Decoursey-H9322990041	11/16/2018 2:10:14 PM	11/17/2018 9:21:37 AM	11/18/2018 12:00:00 PM	TXOH: 11K-102:26862329	-	1	2	CMP	Out	0	EA Weather	Unselected	27 Other/See Notes	Florence	SERVICE CUT AND COILED. CUSTOMER TO CALL INTO ELECTRIC WHEN HE GETS RELEASE. ALAN EAST 513-313-9220
801	8124277	Beaver-H9320860042	11/16/2018 2:24:44 PM	11/17/2018 4:29:03 PM	11/18/2018 12:00:00 PM	TXOH: 50BN-411:26893963	-	0	1	CMP	PH-H-Tree-PH-Othr	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	-
802	8124311	Buffington-H9320670045	11/16/2018 2:33:21 PM	11/17/2018 4:46:24 PM	11/18/2018 12:00:00 PM	TXOH: K117-303:26907837	-	0	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	-
803	8124347	Villa-H9322430043	11/16/2018 2:39:51 PM	11/17/2018 2:45:00 PM	11/18/2018 12:00:00 PM	TXOH: K96-173:26865276	Retrofit 10/17/2013	0	1	CMP	Tree-PP-On	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	-
804	8124351	Buffington-H9320670045	11/16/2018 2:41:55 PM	11/18/2018 10:45:41 AM	11/18/2018 12:00:00 PM	TXOH: K105-292:26904085	-	0	1	CMP	Tree-PH-On	0	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	no outage, large split branch 12" where attached to tree about 8" where resting on triplex serv. taped off area in case limb breaks loose-SAME AS ABOVE STILL NOT FIXED -JOE GROESCHEN 8592500319
805	8124359	Claryville-H9321470042	11/15/2018 6:05:32 PM	11/17/2018 9:21:20 AM	11/18/2018 12:00:00 PM	FOH: 43CA-630:25991955	25T	3	4	CMP	Out-S-Out, Out	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	-
806	8124393	Donaldson-H9320550041	11/16/2018 2:51:40 PM	11/16/2018 5:12:00 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-1134:26880948	-	0	1	CMP	On	0	11 Unknown Cause	-	26 OK Arrival	Florence	C MPL 2018-11-16 17:12:00 by T27867 RMK: OK, NOT DUKE LINES, PHONE LINES
807	8124433	Buffington-H9320670045	11/16/2018 3:01:50 PM	11/18/2018 9:35:34 AM	11/18/2018 12:00:00 PM	TXOH: K117-388:26907446	-	0	1	CMP	PH-H-Othr-O-Othr	0	EA Weather	Unselected	29 Permanent Repair	Florence	JOE GROESCHEN 8592500319 REFER TO E/T, CUT OFF FOR SAFETY, LIMB FELL ON SECONDARY RIPPING HOUSE KNOB AND WH OFF HOUSE AND BENT NEIGHBORS MAST, SECONDARIES ON GROUND CAUTION TAPED, CUSTOMERS STILL HAVE POWER, REFER CUST. TO ELECTRICIAN.
808	8124442	KY Univ-H9322870043	11/16/2018 3:04:24 PM	11/16/2018 7:47:00 PM	11/18/2018 12:00:00 PM	TXUG: CAK-679:27125544	-	1	1	CMP	Out	0	11 Unknown Cause	-	27 Other/See Notes	Florence	C MPL 2018-11-16 19:47:00 by T24175 RMK: no problem found, serv on
809	8124445	Augustine-H9320780041	11/16/2018 3:05:17 PM	11/17/2018 5:03:00 AM	11/18/2018 12:00:00 PM	TXOH: K60-321:26909949	-	0	1	CMP	PP-H-On	0	11 Unknown Cause	-	29 Permanent Repair	Covington	C MPL 2018-11-17 05:03:00 by T18514 RMK: PUP #4 TRI SERVICE RTE ON SEC
810	8124460	Bellevue-H9321310044	11/16/2018 1:54:14 PM	11/17/2018 2:53:56 PM	11/18/2018 12:00:00 PM	TXOH: CA6-1217:26901189	-	1	4	CMP	PH-H-Tree-PH-Out, Out	0	EA Weather	Unselected	20 Cut In/Reconnect at Pole	Florence	-
811	8124530	Augustine-H9320780046	11/16/2018 4:30:08 PM	11/16/2018 7:06:50 PM	11/18/2018 12:00:00 PM	TXOH: k62-7:26924835	-	1	1	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Covington	THIS IS A DUPLICATE TICKET. LIMB TOOK WIRE DOWN AND REPAIRS HAVE BEEN MADE MY SHAWN HURT, CONTRACTOR OPEN FOR SAFETY ON P#K94-149
812	8124539	Crescent-H9320700041	11/16/2018 3:20:33 PM	11/16/2018 3:20:50 PM	11/18/2018 12:00:00 PM	TXOH: K94-149:26916451	-	4	0	CMP	-	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	-
813	8124584	Buffington-H9320670045	11/16/2018 3:26:45 PM	11/17/2018 5:27:14 PM	11/18/2018 12:00:00 PM	TXOH: K105-616:26904295	-	0	1	CMP	PP-H-Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	M. ORTH 859-300-4794. IN & OK.
814	8124595	Villa-H9322430041	11/16/2018 3:28:19 PM	11/17/2018 12:05:00 PM	11/18/2018 12:00:00 PM	TXUG: KNK-6165:398397456	-	0	1	CMP	PP-H-911-Othr	0	03 Vegetation	-	26 OK Arrival	Florence	C MPL 2018-11-17 12:05:00 by WACASSO RMK: WAS PART OF CALL WITH TREE HANGING ON WIRE PREVIOUSLY -OK NOW TREE REMOVED
815	8124600	Oakbrook-H9322100042	11/16/2018 3:29:13 PM	11/16/2018 6:15:00 PM	11/18/2018 12:00:00 PM	TXUG: 25BN-10:26879811	-	1	1	CMP	Out-S-Out	0	28 Other Cause	-	11 Checked Voltage/All OK	Florence	C MPL 2018-11-16 18:15:00 by T27867 RMK: OK ARRIVAL, FULL POWER
816	8124610	Villa-H9322430041	11/16/2018 3:31:10 PM	11/17/2018 9:04:22 PM	11/18/2018 12:00:00 PM	TXOH: K85-226:26914518	-	0	1	CMP	On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	M. ORTH 859-300-4794. IN & OK.
817	8124652	Cold Spring-H9321320042	11/16/2018 3:40:36 PM	11/17/2018 9:42:00 AM	11/18/2018 12:00:00 PM	TXOH: 36CA-720:26888744	-	1	2	CMP	PP-H-Tree-PP-On, Othr-H-911-PF-Othr	0	03 Vegetation	Unselected	11 Checked Voltage/All OK	Florence	C MPL 2018-11-17 09:42:00 by CAMUSTA RMK: already complete ... multi ticket
818	8124657	Oakbrook-H9322100042	11/16/2018 3:41:11 PM	11/16/2018 7:15:00 PM	11/18/2018 12:00:00 PM	TXUG: 25BN-1010:26879226	-	1	1	CMP	Out	0	11 Unknown Cause	-	26 OK Arrival	Florence	C MPL 2018-11-16 19:15:00 by T33329 RMK: OK ARRIVAL
819	8124669	Florence-H9322410045	11/16/2018 3:44:07 PM	11/16/2018 8:25:53 PM	11/18/2018 12:00:00 PM	TXOH: 26882261	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
820	8124692	Empire-H9322890041	11/16/2018 3:48:23 PM	11/17/2018 6:02:03 PM	11/18/2018 12:00:00 PM	TXOH: 31BN-1074:26883423	-	0	1	CMP	Equip-E-Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NICK HAMILTON 513-240-8825. SERVICE IN/OK. TALKED TO CUSTOMER.
821	8124696	Villa-H9322430044	11/16/2018 3:49:55 PM	11/17/2018 7:50:01 AM	11/18/2018 12:00:00 PM	TXUG: K106-949:26905721	-	1	1	CMP	PH-H-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	in & ok rob miller 513 543 8745
822	8124707	Hands-H9321280044	11/16/2018 3:53:51 PM	11/16/2018 11:16:22 PM	11/18/2018 12:00:00 PM	TXOH: K87-194:26914947	-	0	1	CMP	PH-H-On	0	EA Weather	Unselected	37 Removed Limb or Tree From Lin	Florence	REMOVED LIMB
823	8124721	Florence-H9322410042	11/16/2018 3:58:23 PM	11/17/2018 10:00:00 AM	11/18/2018 12:00:00 PM	TXOH: K116-290:26906578	-	0	1	CMP	Tree-PH-LF-Othr	0	28 Other Cause	-	11 Checked Voltage/All OK	Florence	C MPL 2018-11-17 10:00:00 by T24406 RMK: OK ARRIVAL
824	8124725	Buffington-H9320670041	11/16/2018 3:58:59 PM	11/17/2018 4:34:00 AM	11/18/2018 12:00:00 PM	TXOH: K106-496:26905273	-	0	2	CMP	PP-H-On	0	20 Equipment failure	-	30 Phone or TV Cable Problem	Florence	C MPL 2018-11-17 04:34:00 by T17410 RMK: catv service drop
825	8124736	Limaburg-H9321890042	11/16/2018 4:02:11 PM	11/17/2018 8:11:55 PM	11/18/2018 12:00:00 PM	TXOH: 18BN-41:26867762	-	0	1	CMP	Tree-PH-On	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	REMOVED LIMB. EVERYTHING CLEARED AND SEPARATED
826	8124760	Augustine-H9320780045	11/16/2018 4:08:43 PM	11/17/2018 1:18:00 AM	11/17/2018 1:30:00 AM	TXOH: K63-340:26910709	-	1	2	CMP	Out	0	EA Weather	-	44 Replaced Fuse	Florence	C MPL 2018-11-17 01:18:00 by T18514 RMK: REPLCED FUSED
827	8124768	Oakbrook-H9322100042	11/16/2018 4:10:22 PM	11/17/2018 2:15:44 PM	11/18/2018 12:00:00 PM	TXUG: 25BN-225:26879620	-	0	1	CMP	On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NICK HAMILTON 513-240-8825. SERVICE IN/OK. TRIED TO CALL CUSTOMER. WAS UNABLE TO REACH THEM. CHECKED METER. CUSTOMER HAS POWER. NO ISSUES FOUND.
828	8124776	Hands-H9321280041	11/16/2018 4:12:42 PM	11/16/2018 8:05:02 PM	11/18/2018 12:00:00 PM	TXOH: 14K-446:26873521	-	1	1	CMP	Pt O	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
829	8124815	Bellevue-H93221310043	11/16/2018 4:20:40 PM	11/17/2018 5:43:00 PM	11/18/2018 12:00:00 PM	TXOH: CA8-188:26922052	-	0	1	CMP	Othr-O-On	0	03 Vegetation	Unselected	20 Cut In/Reconnect at Pole	Florence	CMPL 2018-11-17 17:43:00 by CAMUSTA RMK: pole CA8-188 reattach #2 tpx to midspan cust eq ok service coiled at cust home Tyler Burns 513-335-2291 pole CA8-188 reattach #2 tpx to midspan cust eq ok service coiled at cust home Tyler Burns 513-335-2291
830	8124835	Covington KY-H9322170044	11/16/2018 9:33:19 AM	11/16/2018 8:33:00 PM	11/18/2018 12:00:00 PM	TXOH: K52-241:53963657	-	0	1	CMP	On	0	28 Other Cause	-	27 Other/See Notes	Covington	CMPL 2018-11-16 20:33:00 by T22595 RMK: NO ONE ON PREM.SERVICE NEEDS KNOB,WEATHERHEAD,NO METER OR COVER ON BASE
831	8124836	Florence-H9322410042	11/16/2018 4:24:13 PM	11/17/2018 3:19:46 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-482:26919089	-	0	1	CMP	Othr-O-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	JOE GROESCHEN 8592500319 - IN/OK CUSTOMER HAS POWER AND PERMANANT CONNECTIONS
832	8124850	Florence-H9322410042	11/16/2018 4:27:43 PM	11/17/2018 12:13:00 AM	11/18/2018 12:00:00 PM	TXOH: 26BN-482:26919089	-	12	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK TOM GEIMAN 513.446.4723
833	8124890	Crescent-H9320700045	11/16/2018 4:35:57 PM	11/17/2018 10:50:12 AM	11/18/2018 12:00:00 PM	TXOH: K92-322:26916031	-	0	1	CMP	CC-H-On	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	-
834	8124982	Buffington-H9320670045	11/16/2018 4:57:36 PM	11/17/2018 2:45:35 PM	11/18/2018 12:00:00 PM	TXOH: K107-35:26906114	-	1	2	CMP	Tree-PH-Out	0	03 Vegetation	Unselected	22 Cut Off/Disconnect at Pole	Florence	CUST REQ ELECTRICIAN TO MAKE REP @ MAST.
835	8124988	Alexandria South-H9322050041	11/16/2018 4:59:06 PM	11/17/2018 2:00:00 PM	11/18/2018 12:00:00 PM	TXUG: 44CA-913:26892837	-	1	2	CMP	Out	0	20 Equipment failure	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 14:00:00 by CLWILLS RMK: PING FAILED 1 leg dead underground,elderly with MS can't get in and out of electric chair,bed has battery back up but not chair
836	8125017	Crescent-H9320700041	11/16/2018 5:08:27 PM	11/16/2018 5:08:28 PM	-	S-RCL: 52630; K83-289: 49497102	-	70	0	M-CMP	-	0	11 Unknown Cause	Unselected	10 Automatic Restoration	Florence	RECL 52630 PH C O/I
837	8125024	Villa-H9322430044	11/15/2018 8:52:57 AM	11/16/2018 7:30:00 PM	11/16/2018 8:00:00 PM	RCL: K95-460:26228374	-	98	22	CMP	PP-H-Out,Out	0	03 Vegetation	-	44 Replaced Fuse	Florence	CMPL 2018-11-16 19:30:00 by T17410 RMK: assist B Casson close fuse on Villa 41 pole K95-447 65t, clear tree limb off line rear prop
838	8125039	Villa-H9322430044	11/16/2018 5:13:36 PM	11/18/2018 11:51:15 AM	-	TXOH: K96-494:26916717	-	0	1	CMP	On	0	EA Weather	Unselected	29 Permanent Repair	Florence	RECONNECT - splice neut and reconnect
839	8125043	Crescent-H9320700041	11/16/2018 5:15:20 PM	11/16/2018 6:39:31 PM	11/18/2018 12:00:00 PM	FOX: K83-423:84862649	65T	30	2	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	NEUTRAL WAS BROKE AND TREE ON PRIMARY. TREE TRIMMERS DID WORK AND REPAIRS WERE MADE
840	8125093	Buffington-H9320670045	11/16/2018 5:25:23 PM	11/16/2018 9:02:00 PM	11/18/2018 12:00:00 PM	TXOH: K117-130:26907870	-	0	1	CMP	Othr-O-On	0	28 Other Cause	-	27 Other/See Notes	Florence	CMPL 2018-11-16 21:02:00 by T27867 RMK: REMOVED LIMB FROM SECONDARY
841	8125103	Buffington-H9320670045	11/16/2018 5:26:30 PM	11/16/2018 8:38:00 PM	11/18/2018 12:00:00 PM	TXOH: K117-6:26907663	-	0	1	CMP	On	0	11 Unknown Cause	-	27 Other/See Notes	Florence	CMPL 2018-11-16 20:38:00 by T27867 RMK: DUKE CREW ONSITE REMOVING LIMBS
842	8125104	Kenton-H9320090044	11/16/2018 5:26:30 PM	11/17/2018 6:11:04 PM	11/18/2018 12:00:00 PM	TXOH: K73-228:26913144	-	1	1	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	PING FAILED PING-OFF REQ 8126653 as of 11/17/18 11:17am cstn!...PER MATT JOHNSON THIS WAS OKAY ON ARRIVAL
843	8125111	White Tower-H9323040042	11/16/2018 5:28:27 PM	11/17/2018 10:01:00 AM	11/18/2018 12:00:00 PM	TXUG: 22K-1138:26878045	-	1	1	CMP	Pt O	0	28 Other Cause	-	26 OK Arrival	Florence	CMPL 2018-11-17 10:01:00 by T22595 RMK: OK ARRIVAL
844	8125126	Donaldson-H9320550042	11/16/2018 5:31:29 PM	11/17/2018 6:07:21 PM	11/18/2018 12:00:00 PM	TXOH: K105-225:26904082	-	0	1	CMP	PH-H-Tree-PH-On	0	EA Weather	Unselected	20 Cut In/Reconnect at Pole	Florence	-
845	8125142	Crittenden-H9321240041	11/16/2018 12:56:12 PM	11/16/2018 8:07:30 PM	11/18/2018 12:00:00 PM	TXOH: 5G-586:26895661	-	1	1	CMP	Out	0	03 Vegetation	Unselected	44 Replaced Fuse	Florence	CMPL 2018-11-16 16:45:00 by T66296 RMK: TOM GEIMAN 513-446-4723, FUSE BLOWN @ 5G-285E, FLAGGING REQ'D. SMALL LIMB ON PRIM BTW P# 5G-385C & 386C REAR LOT, CHECK FUSE @ P# 5G-384E. SERVICE DOWN @ P# 5G-605E (1235 SHADY). REMAINING TAP APPEARS TO BE CLE
846	8125153	Richwood-H9321990042	11/16/2018 5:39:53 PM	11/17/2018 8:09:50 AM	11/18/2018 12:00:00 PM	TXOH: 35BN-342:26885225	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN&OK, METER& LIGHTS ON AS OF 8:05AM 11/17/18 TOM GEIMAN 513.446.4723. PING FAILED
847	8125162	Constance-H9320420042	11/16/2018 5:41:09 PM	11/17/2018 8:28:15 AM	11/18/2018 12:00:00 PM	TXOH: K92-220:26915822	-	1	1	CMP	Out	0	28 Other Cause	Unselected	18 Customer Trouble/No Outage	Florence	CUST NOTIFIED, REQ AN ELECTRICIAN FOR REPAIR.
848	8125165	York-H9320770041	11/16/2018 5:42:39 PM	11/16/2018 7:55:04 PM	11/18/2018 12:00:00 PM	TXUG: CA6-A4-5:26901645	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
849	8125174	Richwood-H9321990042	11/16/2018 5:47:03 PM	11/17/2018 7:53:24 AM	11/18/2018 12:00:00 PM	TXOH: 36BN-797:27072488	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN&OK, METER& LIGHTS ON AS OF 7:49 AM 11/17/18 TOM GEIMAN 513.446.4723
850	8125179	Kenton-H9320090044	11/16/2018 5:47:54 PM	11/16/2018 8:14:02 PM	11/18/2018 12:00:00 PM	TXOH: K73-841:26913150	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
851	8125203	Donaldson-H9320550041	11/16/2018 5:54:56 PM	11/16/2018 7:03:00 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-1134:26880948	-	0	1	CMP	PP-H-On	0	28 Other Cause	-	26 OK Arrival	Florence	CMPL 2018-11-16 19:03:00 by T27867 RMK: NOT DUKE LINES,PHONE LINES
852	8125215	Crittenden-H9321240041	11/16/2018 5:58:25 PM	11/16/2018 7:53:35 PM	11/18/2018 12:00:00 PM	TXOH: 5G-187:26863756	-	1	1	CMP	Out-S-Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-
853	8125238	Dry Ridge-H9321090041	11/16/2018 6:06:51 PM	11/17/2018 1:26:42 PM	11/18/2018 12:00:00 PM	TXOH: 20G-145:26877311	-	0	1	CMP	PP-H-On	0	28 Other Cause	C2 Other Utility Problem	Unselected	Florence	-
854	8125239	Villa-H9322430043	11/16/2018 6:07:09 PM	11/17/2018 3:02:00 PM	11/18/2018 12:00:00 PM	TXOH: K96-299:26916554	-	0	1	CMP	PH-H-On	0	03 Vegetation	Unselected	19 Cut In/Reconnect at Weatherhe	Florence	-
855	8125240	Villa-H9322430041	11/16/2018 6:07:34 PM	11/17/2018 11:01:13 AM	11/18/2018 12:00:00 PM	TXOH: K74-152:27126182	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	ROB MILLER 513 543 8745 IN & OK
856	8125245	Buffington-H9320670045	11/15/2018 3:03:22 PM	11/16/2018 8:27:00 PM	11/18/2018 12:00:00 PM	TXOH: K117-291:26907391	-	1	4	CMP	PH-H-Tree-PH-Out,Tree-PH-Out,Out	0	28 Other Cause	-	12 Checked Voltage/Fixed Connect	Florence	CMPL 2018-11-16 20:27:00 by T27867 RMK: NEUTRAL BROKE AT WH, FIXED CONNECTION OK, 122-122-244
857	8125249	Hebron-H9321520041	11/16/2018 6:09:03 PM	11/16/2018 6:16:49 PM	11/18/2018 12:00:00 PM	TXOH: 14BN-301:26867365	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	-

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
858	8125333	Constance-H9320420042	11/16/2018 6:37:02 PM	11/17/2018 8:25:57 AM	11/18/2018 12:00:00 PM	TXOH: K92-222: 26915696	-	1	1	CMP	Pt O	0	28 Other Cause	Unselected	26 OK Arrival	Florence	-
859	8125344	Augustine-H9320780046	11/15/2018 8:26:24 AM	11/17/2018 8:48:00 PM	11/17/2018 9:00:00 PM	TXOH: K62-658: 26924441	Retro fit	1	4	CMP	PP-H-911-Out-S-Out,PH-H-Out,Out	0	03 Vegetation	-	20 Cut In/Reconnect at Pole	Covington	CMPL 2018-11-17 20:48:00 by T17636 RMK: POLE # K62-658E INSTALL 1/0 TRI. SERVICE 85 FEET. RESET TWO METERS.
860	8125392	Crescent-H9320700043	11/16/2018 7:04:37 PM	11/16/2018 8:14:26 PM	11/18/2018 12:00:00 PM	TXOH: K84-302: 26926589	-	0	0	CMP	PH-H-Pt O	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB ILLER 513 543 8745 METER INSIDE UNABLE TO CHK-LIGHT ON SIDE WINDOW
861	8125407	Beaver-H9320860041	11/16/2018 7:14:11 PM	11/17/2018 2:49:32 PM	11/18/2018 12:00:00 PM	TXOH: 50BN-155: 26894004	-	0	2	CMP	PH-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK AS OF 2:45PM ON 11.17.18 TOM GEIMAN 513 446 4723 COMM WIRE
862	8125512	York-H9320770043	11/16/2018 7:59:29 PM	11/17/2018 1:25:01 PM	11/18/2018 12:00:00 PM	TXOH: CA3-121: 26929794	-	1	1	CMP	PH-H-Out	0	EA Weather	Unselected	26 OK Arrival	Florence	-
863	8125513	Crescent-H9320700043	11/15/2018 7:42:53 AM	11/17/2018 9:40:36 AM	11/18/2018 12:00:00 PM	TXOH: K73-78: 26865193	-	5	5	CMP	PH-H-Obj-L-Pt O-Othr-PQ,PH-H-Tree-PH-Pt O,PH-H-Out,PH-H-Pt O,Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	PING FAILED TREE branch tore rack out of house.broke 1 leg,triplex serv still up part out.
864	8125533	Crescent-H9320700041	11/16/2018 8:06:54 PM	11/17/2018 9:29:33 AM	11/18/2018 12:00:00 PM	TXOH: K83-403: 26925401	-	0	1	CMP	PP-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NICK HAMILTON 513-240-8825. SERVICE IN/OK. CATV WAS DOWN.
865	8125565	Buffington-H9320670041	11/15/2018 9:02:50 AM	11/17/2018 4:08:00 AM	11/18/2018 12:00:00 PM	TXOH: 26BN-227: 26881163	-	6	31	CMP	Equip-E-Out,Out-S-Out,Out	0	03 Vegetation	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-17 04:08:00 by T17410 RMK: limbs previously removed
866	8125566	Buffington-H9320670041	11/15/2018 10:51:54 AM	11/17/2018 3:53:00 AM	11/18/2018 12:00:00 PM	TXOH: 26BN-227: 26881163	-	1	1	CMP	PH-H-Out	0	11 Unknown Cause	-	25 No Problem Found	Florence	CMPL 2018-11-17 03:53:00 by T17410 RMK: limbs previously removed
867	8125567	Buffington-H9320670041	11/15/2018 6:13:19 PM	11/17/2018 4:07:00 AM	11/18/2018 12:00:00 PM	TXOH: 26BN-227: 26881163	-	1	1	CMP	PH-H-Out	0	03 Vegetation	-	25 No Problem Found	Florence	CMPL 2018-11-17 04:07:00 by T17410 RMK: limbs previously removed
868	8125606	Augustine-H9320780046	11/15/2018 9:54:03 AM	11/17/2018 6:15:00 PM	11/18/2018 12:00:00 PM	TXOH: K72-22: 26865106	-	0	1	CMP	PH-H-Obj-L-Othr	0	03 Vegetation	Unselected	25 No Problem Found	Covington	CMPL 2018-11-17 18:15:00 by T17410 RMK: TREE ON SECONDARY. NO OUTAGE...TRK ACC / limbs previously removed
869	8125624	Covington KY-H9322170044	11/16/2018 8:43:34 PM	11/16/2018 8:53:58 PM	11/18/2018 12:00:00 PM	TXOH: K51-705: 26908113	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Covington	-
870	8125730	Hands-H9321280044	11/15/2018 8:30:29 AM	11/16/2018 10:37:15 PM	11/18/2018 12:00:00 PM	TXOH: K87-178: 26914959	-	8	6	CMP	PP-H-Pt O,PH-H-Tree-PH-Pt O,Out	0	EA Weather	Unselected	29 Permanent Repair	Florence	REPAIRED SERV
871	8125816	Crescent-H9320700043	11/15/2018 8:04:56 AM	11/17/2018 7:55:08 AM	11/18/2018 12:00:00 PM	TXOH: K84-464: 26926437	-	0	2	CMP	Equip-E-Obj-L-On,PH-H-Othr-O-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	-
872	8125856	Covington KY-H9322170041	11/17/2018 1:43:28 AM	11/17/2018 1:10:57 PM	11/18/2018 12:00:00 PM	TXOH: K51-756: 26908086	-	1	1	CMP	Pt O-LV	0	11 Unknown Cause	Unselected	26 OK Arrival	Covington	-
873	8125896	Hebron-H9321520041	11/17/2018 5:09:37 AM	11/17/2018 2:00:00 PM	11/18/2018 12:00:00 PM	TXOH: 14BN-284: 26867359	-	1	2	CMP	PH-H-Tree-PH-On,Out	0	03 Vegetation	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 14:00:00 by T29408 RMK: job complete
874	8125909	Florence-H9322410046	11/17/2018 5:48:02 AM	11/17/2018 10:08:00 AM	11/17/2018 11:00:00 AM	FOH: 30BN-418: 26055414	65T	39	24	CMP	Out	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 10:08:00 by T81490 RMK: 65T
875	8126029	Villa-H9322430043	11/17/2018 7:23:16 AM	11/17/2018 2:30:00 PM	11/18/2018 12:00:00 PM	TXOH: K97-246: 26917426	-	0	1	CMP	PH-H-On	0	28 Other Cause	-	27 Other/See Notes	Florence	CMPL 2018-11-17 14:30:00 by T22595 RMK: SPLICE PC. OF NEUT .SERVICE UP PERM. ELECTRIC CO. ON SITE FOR REPAIRS
876	8126052	Donaldson-H9320550042	11/17/2018 7:31:55 AM	11/17/2018 7:31:57 AM		S-RCL: 630: KNK-5333: 164310000	-	168	0	M-CMP	-	0	11 Unknown Cause	Unselected	10 Automatic Restoration	Florence	RECL 630453 PH A O/I
877	8126066	Decoursey-H9322990041	11/15/2018 3:49:00 PM	11/17/2018 9:32:22 AM	11/18/2018 12:00:00 PM	TXOH: 11K-181: 26872780	-	1	1	CMP	PP-H-Out-S-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN AND OK
878	8126105	Augustine-H9320780046	11/17/2018 8:00:50 AM	11/17/2018 1:35:11 PM	11/18/2018 12:00:00 PM	TXOH: K72-635: 26912119	-	1	1	CMP	Out	0	03 Vegetation	Unselected	20 Cut In/Reconnect at Pole	Covington	-
879	8126106	Villa-H9322430044	11/17/2018 8:01:05 AM	11/17/2018 11:04:00 AM	11/17/2018 11:45:00 AM	TXOH: K96-227: 26916952	-	1	1	CMP	Out-S-Out	0	EA Weather	-	26 OK Arrival	Florence	CMPL 2018-11-17 11:04:00 by T25446 RMK: new house. new underground service has electric. meter for temporary service to build house has been removed but service is still there OK Arrival
880	8126146	Donaldson-H9320550042	11/17/2018 8:13:25 AM	11/17/2018 10:54:00 AM	11/18/2018 12:00:00 PM	TXOH: K95-226: 26866055	-	1	1	CMP	Out	0	04 Wildlife	Unselected	44 Replaced Fuse	Florence	CMPL 2018-11-17 10:54:00 by CMTURNE RMK: Refuse P# K95-187
881	8126171	Crescent-H9320700043	11/17/2018 8:32:04 AM	11/17/2018 8:41:30 AM	11/18/2018 12:00:00 PM	TXOH: K84-341: 26925927	-	0	1	CMP	Obj-L-On	0	03 Vegetation	Unselected	18 Customer Trouble/No Outage	Florence	CUST REQ ELECTRICIAN AND NEW SEC. SERV C/C .
882	8126174	Covington KY-H9322170044	11/17/2018 8:33:21 AM	11/17/2018 11:16:41 AM	11/18/2018 12:00:00 PM	TXOH: K51-694: 26864757	-	1	1	CMP	Out	0	03 Vegetation	Unselected	26 OK Arrival	Covington	PING-ON REQ 8126642 as of 11/17/18 11:15am No notes so marking ticket as COMPLETED. cstrun1
883	8126175	Florence-H9322410046	11/17/2018 8:33:50 AM	11/17/2018 11:26:04 AM	11/18/2018 12:00:00 PM	TXUG: 31BN-BE-6: 26883220	-	1	1	CMP	Out	0	03 Vegetation	Unselected	26 OK Arrival	Florence	PING-ON REQ 8126678 as of 11/17/18 11:24am cstrun1
884	8126176	Villa-H9322430044	11/17/2018 8:33:54 AM	11/17/2018 1:08:22 PM	11/18/2018 12:00:00 PM	TXOH: K96-343: 26916602	-	0	1	CMP	Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	JOE GROESCHEN 859 250 0319 IN/OK
885	8126185	Villa-H9322430043	11/17/2018 8:37:44 AM	11/17/2018 2:18:00 PM	11/18/2018 12:00:00 PM	TXOH: K96-458: 26865282	-	0	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	-	27 Other/See Notes	Florence	CMPL 2018-11-17 14:18:00 by T22595 RMK: REMOVE LIMBS FROM TRI-PLEX
886	8126191	Crescent-H9320700045	11/17/2018 8:39:39 AM	11/17/2018 8:39:44 AM		S-RCL: 8152: KNK-5088: 86421461	MLD	721	0	M-CMP	-	0	11 Unknown Cause	Unselected	10 Automatic Restoration	Florence	RECL 815269 PH C O/I
887	8126219	Longbranch-H9320980042	11/17/2018 8:51:00 AM	11/17/2018 11:14:33 AM	11/18/2018 12:00:00 PM	TXOH: 35BN-675: 26885220	-	0	1	CMP	PP-H-Pole-L-Othr	0	11 Unknown Cause	Unselected	28 Patrolled & No Problem Found	Florence	ERIC MOORE 513-255-2120. PATROLLED AREA DESCRIBED IN NOTES AND NO WIRES DOWN LOCATED. DO SEE POLE SNAPPED THAT HAS ALREADY BEEN REPORTED BUT WIRES NOT DOWN
888	8126259	Buffington-H9320670045	11/17/2018 9:01:34 AM	11/17/2018 8:16:27 PM	11/18/2018 12:00:00 PM	TXOH: K106-570: 26905502	-	1	1	CMP	PP-H-Out	0	EA Weather	Unselected	29 Permanent Repair	Florence	-
889	8126287	Crescent-H9320700044	11/15/2018 6:21:27 AM	11/17/2018 11:01:25 AM	11/18/2018 12:00:00 PM	TXOH: K93-244: 26927231	-	1	2	CMP	Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	-

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
890	8126287	Augustine-H9320780046	11/17/2018 9:10:43 AM	11/17/2018 7:48:00 PM	11/18/2018 12:00:00 PM	TXOH: K72-406-28912220	-	0	1	CMP	Tree-PH-On	0	03 Vegetation	-	37 Removed Limb or Tree From Lin	Covington	CMPL 2018-11-17 19:48:00 by T17410 RMK: remove broken limbs from # 2 tri
891	8126314	York-H9320770043	11/17/2018 9:18:40 AM	11/17/2018 1:36:00 PM	11/18/2018 12:00:00 PM	TXOH: CA6-1784-26901411	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	CMPL 2018-11-17 13:36:00 by T24175 RMK: ciop by Bolin earlier
892	8126335	Kenton-H9320090044	11/17/2018 9:23:23 AM	11/17/2018 11:12:31 AM	11/18/2018 12:00:00 PM	TXOH: K63-42-26910724	-	1	1	CMP	PP-H-Tree-PP-Out	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	TT ON SITE
893	8126345	Beaver-H9320860042	11/16/2018 3:41:36 PM	11/17/2018 7:40:10 PM	11/18/2018 12:00:00 PM	TXOH: 26880689	-	0	1	CMP	PH-H-Pole-L-On	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	2 POLES LEANING, DUE TO BRANCH COMING DOWN AND THE POLES WERE STRAIGHTENED OUT BY CHRIS STEWART
894	8126356	Limaburg-H9321890041	11/16/2018 5:09:28 PM	11/17/2018 12:26:00 PM	11/18/2018 12:00:00 PM	TXOH: 19BN-328-27075560	-	0	1	CMP	Tree-PP-Othr	0	28 Other Cause	-	30 Phone or TV Cable Problem	Florence	CMPL 2018-11-17 12:26:00 by T24406 RMK: NOT DUKE EQUIPMENT
895	8126409	Villa-H9322430043	11/17/2018 9:46:10 AM	11/17/2018 11:22:39 AM	11/18/2018 12:00:00 PM	TXOH: K95-298-26927926	-	1	1	CMP	Out-S-Out	0	03 Vegetation	Unselected	26 OK Arrival	Florence	PING-ON REQ 8126667 as of 11/17/18 11:21 am cstrun1
896	8126412	Villa-H9322430041	11/15/2018 9:34:46 AM	11/17/2018 11:45:46 AM	11/18/2018 12:00:00 PM	TXOH: K84-18-26926751	-	1	3	CMP	PH-H-Pt O Out	0	28 Other Cause	Unselected	30 Phone or TV Cable Problem	Florence	-
897	8126423	Crescent-H9320700045	11/17/2018 9:50:11 AM	11/17/2018 10:41:00 AM	11/17/2018 12:00:00 PM	TXOH: K92-189-26915688	Retrofit 2/3/2014	8	1	CMP	Out	0	03 Vegetation	-	48 Replaced Service/Secondary	Florence	CMPL 2018-11-17 10:41:00 by T66296 RMK: 1/0 DOWN BY TREE
898	8126448	Kenton-H9320090044	11/17/2018 9:57:08 AM	11/17/2018 7:49:57 PM	11/18/2018 12:00:00 PM	TXOH: K63-40-26910589	-	1	2	CMP	PH-H-On,Tree-PP-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING - REQ 8127554 - ON as of 3:53PM 11/17/18. See log: Tree about to snap line. ABraun 513-458-3797; IN & OKAY; CPC HEATHER LEET 513-630-8595
899	8126467	Bellevue-H9321310043	11/17/2018 10:06:45 AM	11/17/2018 1:15:00 PM	11/17/2018 1:14:00 PM	TXOH: CA7-315-26902340	-	1	1	CMP	Equip-E-Out	0	04 Wildlife	-	29 Permanent Repair	Florence	CMPL 2018-11-17 13:15:00 by CLWLLS RMK: REF 10D 0115
900	8126486	Villa-H9322430043	11/17/2018 10:14:13 AM	11/17/2018 5:28:00 PM	11/18/2018 12:00:00 PM	TXOH: K97-274-26917542	-	1	3	CMP	PH-H-Out,Out-S-Out	0	03 Vegetation	Unselected	19 Cut In/Reconnect at Weatherhe	Florence	TRI-PLEX OFF OF POLE AND ON GROUND, TREE CLEARED, NEEDS REC. TRI-PLEX STILL ATTACHED TO HOUSE Pinged Off 11/17 11:27am
901	8126488	Florence-H9322410048	11/17/2018 7:07:01 AM	11/17/2018 10:23:44 AM	11/18/2018 12:00:00 PM	FOH: 30BN-418-26055414	65T	39	2	CMP	Out-S-Out	0	28 Other Cause	Unselected	35 OK per Phone Call	Florence	-
902	8126493	Crescent-H9320700045	11/16/2018 8:35:31 AM	11/17/2018 11:15:32 AM	11/18/2018 12:00:00 PM	TXOH: K92-189-26915688	Retrofit 2/3/2014	1	1	CMP	Tree-PH-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	-
903	8126533	Crescent-H9320700043	11/17/2018 10:36:10 AM	11/17/2018 1:15:20 PM	11/18/2018 12:00:00 PM	TXOH: K83-245-26925739	-	5	0	CMP	-	0	28 Other Cause	Unselected	26 OK Arrival	Florence	MANNING - 513-218-6533 - OK ARRIVAL
904	8126534	Crescent-H9320700043	11/17/2018 10:36:22 AM	11/17/2018 1:16:02 PM	11/18/2018 12:00:00 PM	TXOH: K83-244-26925642	-	10	0	CMP	-	0	28 Other Cause	Unselected	26 OK Arrival	Florence	MANNING - 513-218-6533 - OK ARRIVAL
905	8126550	Villa-H9322430044	11/17/2018 10:43:20 AM	11/17/2018 12:22:00 PM	11/17/2018 1:00:00 PM	TXOH: K96-273-26916595	-	0	1	CMP	PH-H-Tree-PH-On	0	05 Planned (IEEE)	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-17 12:22:00 by T25446 RMK: opened to remove limb from primary line for safety.
906	8126564	Donaldson-H9320550044	11/17/2018 10:46:16 AM	11/17/2018 4:32:45 PM	11/18/2018 12:00:00 PM	TXUG: K104-24-26903895	-	0	1	CMP	PP-H-Tree-PP-On	0	EA Weather	Unselected	29 Permanent Repair	Florence	-
907	8126573	Covington KY-H9322170041	11/17/2018 10:50:05 AM	11/17/2018 3:13:23 PM	11/18/2018 12:00:00 PM	TXOH: K51-221-26865692	-	0	1	CMP	Equip-E-Othr-O-On	0	28 Other Cause	Unselected	26 OK Arrival	Covington	ok arrival
908	8126651	Crescent-H9320700043	11/17/2018 11:16:55 AM	11/17/2018 1:01:41 PM	11/18/2018 12:00:00 PM	TXOH: K83-700-26925647	-	0	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	-
909	8126658	Villa-H9322430043	11/17/2018 11:17:31 AM	11/17/2018 11:24:11 AM	11/18/2018 12:00:00 PM	TXOH: K97-274-26917542	-	0	0	CMP	Out	0	03 Vegetation	Unselected	26 OK Arrival	Florence	PING-ON REQ 8126676 as of 11/17/18 11:23am. No notes so marking ticket as COMPLETED. cstrun1
910	8126682	Kenton-H9320090046	11/17/2018 11:26:15 AM	11/17/2018 5:31:00 PM	11/18/2018 12:00:00 PM	TXOH: 7K-323-26896482	-	1	1	CMP	Out	0	03 Vegetation	Unselected	19 Cut In/Reconnect at Weatherhe	Florence	-
911	8126685	Villa-H9322430043	11/17/2018 11:26:49 AM	11/17/2018 3:38:53 PM	11/18/2018 12:00:00 PM	TXOH: K95-54-26927853	-	9	2	CMP	Out	0	EA Weather	Unselected	33 OK per Meter Interrogation	Florence	-
912	8126709	Crescent-H9320700045	11/17/2018 11:37:45 AM	11/17/2018 12:31:57 PM	11/18/2018 12:00:00 PM	TXOH: K92-335-26915563	-	8	3	CMP	Out	0	28 Other Cause	Unselected	35 OK per Phone Call	Florence	-
913	8126785	Villa-H9322430044	11/16/2018 11:36:15 PM	11/17/2018 12:30:29 PM	11/18/2018 12:00:00 PM	TXOH: K96-346-26916808	-	1	1	CMP	Pt O	0	03 Vegetation	Unselected	27 Other/See Notes	Florence	CREW DIS CUST SVC @ WH. CUST NEEDS REPAIRS, CUST CONTACT
914	8126832	Covington KY-H9322170044	11/17/2018 12:06:54 PM	11/17/2018 12:51:21 PM	11/18/2018 12:00:00 PM	TXOH: K51-694-26864757	-	0	0	CMP	Out	0	03 Vegetation	Unselected	33 OK per Meter Interrogation	Covington	-
915	8126835	Villa-H9322430044	11/17/2018 12:08:13 PM	11/17/2018 12:24:42 PM	11/18/2018 12:00:00 PM	FOH: K96-312-25996332	65T	111	8	CMP	Out,Dmg-On	0	03 Vegetation	Unselected	44 Replaced Fuse	Florence	ROB MILLER 513 543 8745 BROKE SERVICE NEUT @ HOUSE MAST NEED LADDER
916	8126837	Villa-H9322430044	11/17/2018 12:09:47 PM	11/17/2018 1:44:38 PM	11/18/2018 12:00:00 PM	TXOH: K96-195-26917183	-	0	1	CMP	Tree-PH-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
917	8126838	Kenton-H9320090044	11/15/2018 7:41:31 AM	11/17/2018 5:37:40 PM	11/18/2018 12:00:00 PM	TXOH: K73-314-26913044	-	0	6	CMP	PP-H-On,PH-H-On,Tree-PH-Othr,Tree-PH-On	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	-
918	8126843	Villa-H9322430043	11/17/2018 12:11:29 PM	11/17/2018 3:57:00 PM	11/18/2018 12:00:00 PM	TXOH: K95-566-26927587	-	0	1	CMP	PH-H-Tree-PH-On	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	-
919	8126902	Decoursey-H9322990041	11/15/2018 6:39:15 AM	11/17/2018 2:33:34 PM	11/18/2018 12:00:00 PM	TXOH: 11K-94-26872294	-	1	2	CMP	PP-H-Out,PH-H-Tree-PH-On	0	28 Other Cause	Unselected	16 Closed Recl or Sectionalizer	Florence	IN AND OKAY
920	8126903	Decoursey-H9322990041	11/17/2018 12:29:42 PM	11/17/2018 2:35:21 PM	11/18/2018 12:00:00 PM	TXOH: 11K-94-26872294	-	1	1	CMP	PP-H-Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	-
921	8126914	Villa-H9322430044	11/17/2018 12:31:45 PM	11/17/2018 2:01:23 PM	11/18/2018 12:00:00 PM	TXOH: K96-422-26917330	-	1	1	CMP	Out-S-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
922	8126919	Donaldson-H9320550041	11/17/2018 12:33:59 PM	11/17/2018 2:39:43 PM	11/18/2018 12:00:00 PM	TXOH: K105-98-26904711	-	0	1	CMP	PP-H-911-PF-Othr	0	EA Weather	Unselected	22 Cut Off/Disconnect at Pole	Florence	-
923	8126939	Crescent-H9320700045	11/17/2018 12:41:23 PM	11/17/2018 2:15:00 PM	11/18/2018 12:00:00 PM	FOH: K92-194-366463071	-	33	7	CMP	Out	0	03 Vegetation	-	51 Reset Transformer Breaker	Florence	CMPL 2018-11-17 14:15:00 by T66296 RMK: RESET CSP
924	8126951	Augustine-H9320780046	11/17/2018 12:45:07 PM	11/17/2018 3:51:20 PM	11/18/2018 12:00:00 PM	TXOH: K62-402-26865841	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Covington	OK ARRIVAL
925	8126989	Covington KY-H9322170044	11/17/2018 12:06:54 PM	11/17/2018 2:04:30 PM	11/18/2018 12:00:00 PM	TXOH: K51-694-26864757	-	1	1	CMP	Out-S-Out	0	03 Vegetation	Unselected	33 OK per Meter Interrogation	Covington	-

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
926	8127072	Covington KY- H9322170042	11/17/2018 1:24:21 PM	11/17/2018 5:07:00 PM	11/17/2018 6:00:00 PM	TXOH: K51-1883: 26865706	-	1	1	CMP	Out	0	20 Equipment failure	Unselected	29 Permanent Repair	Covington	CMPL 2018-11-17 17:07:00 by CLWILLS RMK: BUSINESS
927	8127083	Donaldson- H9320550041	11/17/2018 1:28:05 PM	11/17/2018 3:48:57 PM	11/18/2018 12:00:00 PM	TXOH: K116-132: 26906634	-	0	1	CMP	PH-H-On	0	EA Weather	Unselected	35 OK per Phone Call	Florence	
928	8127117	Villa- H9322430044	11/17/2018 1:38:46 PM	11/17/2018 1:53:18 PM	11/18/2018 12:00:00 PM	TXOH: K96-492: 26916728	-	1	1	CMP	Out	0	03 Vegetation	Unselected	33 OK per Meter Interrogation	Florence	
929	8127125	Bellevue- H9321310042	11/17/2018 1:42:29 PM	11/17/2018 8:47:06 PM	11/18/2018 12:00:00 PM	TXOH: CA5-51: 26900830	-	1	1	CMP	PH-H-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OK ARRIVAL
930	8127164	Florence- H9322410046	11/17/2018 1:54:16 PM	11/17/2018 3:19:13 PM	11/18/2018 12:00:00 PM	TXUS: 31BN-BE-6: 26883220	-	1	1	CMP	Out	0	03 Vegetation	Unselected	33 OK per Meter Interrogation	Florence	
931	8127203	Alexandria South- H9322050041	11/17/2018 2:09:01 PM	11/18/2018 8:27:00 AM	11/18/2018 12:00:00 PM	TXOH: 43CA-298: 26930014	-	1	1	CMP	PH-H-Out	0	03 Vegetation	Unselected	20 Cut In/Reconnect at Pole	Florence	CMPL 2018-11-18 08:27:00 by T95129 RMK: PING OFF REQ 8127762 as of 17:03 on 11/17/18 jrcraig1 513 458 3791 - electrician states cust is ready to have line reattached to meter they have temp releases
932	8127206	Donaldson- H9320550042	11/17/2018 2:09:29 PM	11/17/2018 5:25:03 PM	11/18/2018 12:00:00 PM	TXOH: K105-813: 26904938	-	0	1	CMP	PH-H-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
933	8127214	Decoursey- H9322990041	11/17/2018 9:49:48 AM	11/17/2018 2:52:26 PM	11/18/2018 12:00:00 PM	TXOH: 11K-102: 26862329	-	1	2	CMP	PH-H-Tree-PH-Out,On	0	28 Other Cause	Unselected	35 OK per Phone Call	Florence	
934	8127223	Crescent- H9320700041	11/17/2018 2:13:19 PM	11/17/2018 3:54:00 PM	11/18/2018 12:00:00 PM	TXOH: K83-261: 26925417	-	1	2	CMP	PH-H-Tree-PH-On,Tree-PH-Pt O-LF	0	03 Vegetation	Unselected	26 OK Arrival	Florence	CMPL 2018-11-17 15:54:00 by T66296 RMK: Wires across drive blocking driveway CATV AND CBT DOWN
935	8127238	Villa- H9322430043	11/17/2018 2:17:48 PM	11/17/2018 5:05:00 PM	11/18/2018 12:00:00 PM	TXOH: K95-54: 26927853	-	0	1	CMP	PH-H-LF-On	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	
936	8127241	Crescent- H9320700045	11/17/2018 2:18:20 PM	11/17/2018 4:19:00 PM	11/18/2018 12:00:00 PM	TXOH: K92-129: 26915842	Retrofit 1/24/2014	1	1	CMP	Pt O	0	03 Vegetation	-	15 Closed Elbow or Jumper	Florence	CMPL 2018-11-17 16:19:00 by T66296 RMK: R TO E WH RK1 ENTRANCE
937	8127244	Donaldson- H9320550043	11/17/2018 2:19:04 PM	11/17/2018 3:35:57 PM	11/18/2018 12:00:00 PM	TXOH: 21BN-321: 26877620	-	0	0	CMP	Out	0	03 Vegetation	Unselected	33 OK per Meter Interrogation	Florence	
938	8127260	Augustine- H9320780046	11/17/2018 2:24:12 PM	11/17/2018 7:46:00 PM	11/18/2018 12:00:00 PM	TXOH: K72-406: 26912220	-	0	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	-	37 Removed Limb or Tree From Lin	Covington	CMPL 2018-11-17 19:46:00 by T17410 RMK: remove broken tree limbs # 2 tri
939	8127263	Donaldson- H9320550041	11/17/2018 2:25:52 PM	11/17/2018 9:34:50 PM	11/18/2018 12:00:00 PM	TXOH: K105-98: 26904711	-	1	2	CMP	PP-H-On,Tree-PP-Out	0	EA Weather	Unselected	22 Cut Off/Disconnect at Pole	Florence	Wires down
940	8127264	Villa- H9322430041	11/17/2018 2:25:44 PM	11/18/2018 11:52:30 AM	11/17/2018 11:20:00 PM	TXOH: K84-51: 26926364	Retrofit 12/2/2013	1	1	CMP	Out	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	PING ON REQ 8127765 as of 17:05 on 11/17/18 jrcraig1 11/17/18 - ARC Electric request to have svrc line reattached, new weather head insulator connected - resagged wire and attached to house
941	8127328	Augustine- H9320780041	11/17/2018 2:41:24 PM	11/17/2018 4:11:00 PM	11/18/2018 12:00:00 PM	TXOH: K71-85: 26911982	-	0	1	CMP	PP-H-On	0	28 Other Cause	-	27 Other/See Notes	Florence	CMPL 2018-11-17 16:11:00 by T17410 RMK: pole base washed out by creek, previously turned over to engineering dept. for repairs
942	8127341	Constance- H9320420042	11/17/2018 2:45:14 PM	11/18/2018 9:44:00 AM	11/18/2018 10:30:00 AM	TXOH: K92-220: 26915822	-	1	2	CMP	Out	0	03 Vegetation	-	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-18 09:44:00 by T84225 RMK: #4 tri. back up perm.
943	8127371	Donaldson- H9320550042	11/17/2018 2:53:49 PM	11/17/2018 4:11:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-556: 26904878	-	1	1	CMP	Equip-E-On	0	03 Vegetation	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-17 16:11:00 by CMTURNE RMK: OK ARRIVAL. ASSOCIATED WITH EVENT #8109403. RMDV TWPP. NO OUTAGES.
944	8127372	Donaldson- H9320550042	11/17/2018 2:53:49 PM	11/17/2018 4:14:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-556: 26904878	-	1	1	CMP	PP-H-On	0	03 Vegetation	-	27 Other/See Notes	Florence	CMPL 2018-11-17 16:14:00 by CMTURNE RMK: OK ARRVL. ASSOCIATED WITH EVENT #8109403. RMDV TWPP K105-556. NO OUTAGES.
945	8127381	Crescent- H9320700043	11/17/2018 2:57:00 PM	11/17/2018 8:18:50 PM	11/18/2018 12:00:00 PM	TXOH: K84-304: 26925940	-	1	1	CMP	PH-H-Out-Othr-O	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NEW POLE SET NXT DR.NOW HIS MID-SPAN SERVICE IS MUCH LOWER APPROX. 9 FT. ABOVE DRIVEWAY.WOULD LIKE RAISED. NEIGHBORS HAD REPAIRS NEW POLE .ETC. CUST SERVICE IS A MID-SPAN ,SAYS IT IS MUCH LOWER NOW,APPOX. 9 FT. SEE ADNTL NOTES
946	8127396	Crescent- H9320700043	11/17/2018 3:00:41 PM	11/17/2018 7:40:00 PM	11/18/2018 12:00:00 PM	TXOH: K83-629: 26925292	-	0	1	CMP	PP-H-Othr-O-On	0	03 Vegetation	-	27 Other/See Notes	Florence	CMPL 2018-11-17 19:40:00 by T22595 RMK: FOUND SOME BRANCHES ON CABLE LINES NOTHING ON DUKE LINES
947	8127404	Florence- H9322410046	11/17/2018 3:04:54 PM	11/17/2018 9:22:34 PM	11/18/2018 12:00:00 PM	TXOH: 31BN-424: 26883761	-	1	3	CMP	Equip-E-Out,PH-H-Othr,PH-H-On	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	PING - REQ 8127422 - ON as of 3:13PM 11/17/18 See log: Line down in front yard. ABraun 513-458-3797...SERVICE CUT IN CLEAR CUSTOMER NEEDS TO MAKE REPAIRS/ NEED RISER AND W/H REPAIR. REMOVED SEV IN & OK ROB MILLER 513 543 8745
948	8127427	Donaldson- H9320550041	11/17/2018 3:14:33 PM	11/17/2018 4:49:42 PM	11/18/2018 12:00:00 PM	TXOH: 26BN-774: 26865365	-	0	1	CMP	Othr-H-911-Pole-h-Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	
949	8127438	Bellevue- H9321310042	11/17/2018 3:17:27 PM	11/17/2018 8:10:00 PM	11/17/2018 8:28:00 PM	TXOH: CA5-43: 26900784	-	1	1	CMP	Out	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-17 20:10:00 by T84692 RMK: PING OFF REQ 8127510 as of 15:38 on 11/17/18 jrcraig1 513 458 3791
950	8127489	Covington KY- H9322170044	11/17/2018 3:33:18 PM	11/17/2018 6:12:00 PM	11/18/2018 12:00:00 PM	TXOH: K51-694: 26864757	-	0	1	CMP	Equip-E-Othr-O-Othr-PQ-On	0	28 Other Cause	-	27 Other/See Notes	Covington	CMPL 2018-11-17 18:12:00 by T22595 RMK: R TO LANDLORD
951	8127490	Augustine- H9320780046	11/17/2018 3:33:23 PM	11/17/2018 9:54:00 PM	11/18/2018 12:00:00 PM	TXOH: K62-64: 26924778	-	0	1	CMP	Othr-O-On	0	03 Vegetation	-	18 Customer Trouble/No Outage	Covington	CMPL 2018-11-17 21:54:00 by CAMUSTA RMK: customer needs to get rk1 replaced and entrance cable re attached ... ok tempo
952	8127512	Florence- H9322410045	11/17/2018 3:39:50 PM	11/17/2018 3:39:53 PM		S-RCL: 605: BNK-5981: 359188859	-	298	0	M-CMP	-	0	11 Unknown Cause	Unselected	10 Automatic Restoration	Florence	RECL 605297 PH C O/I
953	8127530	Donaldson- H9320550042	11/15/2018 6:36:58 AM	11/17/2018 5:29:14 PM	11/18/2018 12:00:00 PM	TXOH: K105-656: 26904909	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
954	8127534	Donaldson- H9320550043	11/17/2018 2:19:00 PM	11/17/2018 5:55:00 PM	11/18/2018 12:00:00 PM	TXOH: 21BN-321: 26877620	-	1	2	CMP	Out-S-Out,Out-AMI	0	03 Vegetation	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-17 17:55:00 by T17636 RMK: INSTALLING 110' OF #2 TRI ELEC CLAIMS DUKE HAS IBI NUMBER

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
955	8127600	Kenton-H9320090044	11/17/2018 2:09:07 PM	11/18/2018 8:05:31 AM	11/18/2018 12:00:00 PM	TXOH: K73-306-26912671	-	1	1	1	CMP Out-S-Out	0	28 Other Cause	Unselected	24 N/A	Florence	CUST NEEDS ELECTRICIAN
956	8127614	Crescent-H9320700043	11/17/2018 9:13:04 AM	11/17/2018 6:03:00 PM	11/18/2018 12:00:00 PM	TXOH: K72-10:26865111	-	1	1	1	CMP Out	0	28 Other Cause	Unselected	25 No Problem Found	Florence	CMPL 2018-11-17 18:03:00 by T74214 RMK: Pinged off @ 16:34
957	8127684	Wilder-H9320590047	11/17/2018 2:34:05 PM	11/17/2018 8:46:00 PM	11/18/2018 12:00:00 PM	TXOH: CA9-401:26902925	-	0	1	1	CMP Tree-PP-On	0	03 Vegetation	-	25 No Problem Found	Florence	CMPL 2018-11-17 20:46:00 by T24175 RMK: all electric lines in the clear,branch on phone opposite side of st. this was on 19th st which runs off home st per cust.
958	8127700	Hands-H9321280041	11/15/2018 9:31:15 AM	11/17/2018 4:54:14 PM	11/18/2018 12:00:00 PM	TXOH: KNK-1713:27111705	-	1	5	NEW	PP-H-Out/Out	0	03 Vegetation	Unselected	17 Closed Switch	Florence	-
959	8127711	Hebron-H9321520045	11/17/2018 4:50:46 PM	11/17/2018 5:45:00 PM	11/18/2018 12:00:00 PM	TXOH: 14BN-322:26867305	-	1	2	CMP	PP-H-Tree-PP-Out-PP-H-Tree-PP-On	0	-	-	11 Checked Voltage/All OK	Florence	CMPL 2018-11-17 17:45:00 by T29408 RMK: ok
960	8127720	Crescent-H9320700041	11/17/2018 4:52:55 PM	11/17/2018 9:02:29 PM	11/18/2018 12:00:00 PM	TXOH: K84-437:26926614	-	1	1	CMP	Tree-PP-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
961	8127721	Crescent-H9320700041	11/15/2018 9:24:49 AM	11/17/2018 9:13:20 PM	11/18/2018 12:00:00 PM	TXOH: K84-437:26926614	-	1	1	CMP	PH-H-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	IN & OK ROB MILLER 513 543 8745
962	8127744	Wilder-H9320590041	11/16/2018 1:21:21 AM	11/17/2018 6:09:00 PM	11/18/2018 12:00:00 PM	TXOH: CA11-441:26898672	-	1	6	CMP	Out-Othr-O-On	0	03 Vegetation	-	54 Scheduled	Florence	CMPL 2018-11-17 18:09:00 by T84692 RMK: REPLACED CUST SERVICE ENTRANCE WIRE
963	8127761	Augustine-H9320780043	11/17/2018 5:03:28 PM	11/17/2018 7:20:49 PM	11/17/2018 7:30:00 PM	TXOH: K52-832:26908757	-	1	1	CMP	Out-Othr-O	0	EA Weather	Unselected	29 Permanent Repair	Covington	-
964	8127792	Crescent-H9320700043	11/16/2018 5:15:49 AM	11/17/2018 7:31:46 PM	11/18/2018 12:00:00 PM	TXOH: K83-142:26925838	-	1	2	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING - REQ 8127824 - OFF as of 5:30PM 11/17/18. ABraun 513-458-3797; IN & OKAY; CPC HEATHER LEET 513-630-8595
965	8127814	Wilder-H9320590045	11/17/2018 5:23:06 PM	11/18/2018 4:04:03 AM	11/18/2018 12:00:00 PM	TXOH: CA13-167:26899425	-	1	2	CMP	PH-H-Out-Othr-O	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	REM LIMB OK.
966	8127832	Crescent-H9320700041	11/17/2018 11:04:04 AM	11/17/2018 7:22:33 PM	11/18/2018 12:00:00 PM	TXOH: K84-437:26926614	-	1	1	CMP	PH-H-Out-S-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OK
967	8127859	Bellevue-H9321310043	11/17/2018 5:40:40 PM	11/17/2018 8:40:52 PM	11/18/2018 12:00:00 PM	TXOH: CA8-188:26922052	-	1	4	CMP	Othr-H-Out-Othr-O Othr-PQ-Out,Othr	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OK ARRIVAL
968	8127880	Buffington-H9320670045	11/16/2018 12:34:00 PM	11/17/2018 8:23:30 PM	11/18/2018 12:00:00 PM	TXOH: K105-449:26904113	-	1	2	CMP	Tree-PH-Out/Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	OKAY ON ARRIVAL
969	8127900	Florence-H9322410045	11/17/2018 6:04:14 PM	11/17/2018 9:03:00 PM	11/17/2018 9:30:00 PM	TXOH: 30BN-297:26882577	-	1	1	CMP	Pt O	0	11 Unknown Cause	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-17 21:03:00 by T81490 RMK: PING OFF REQ 8127905 as of 18:08 on 11/17/18 jrcraig1 513.458.3791 - customer states they lost 220 power, breakers have been reset
970	8127925	Covington KY-H9322170041	11/17/2018 1:22:50 PM	11/17/2018 7:21:36 PM	11/17/2018 7:15:00 PM	TXOH: K51-756:26908086	-	1	1	CMP	Out	0	EA Weather	Unselected	29 Permanent Repair	Covington	-
971	8127945	Crescent-H9320700043	11/17/2018 6:23:58 PM	11/17/2018 7:23:34 PM	11/18/2018 12:00:00 PM	TXOH: K72-10:26865111	-	1	1	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING ON REQ 8128014 as of 18:59 on 11/17/18 jrcraig1 513.458.3791 - no notes, OK
972	8127957	Donaldson-H9320550041	11/17/2018 6:31:38 PM	11/17/2018 8:31:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-98:26904711	-	1	1	CMP	Out	0	03 Vegetation	Unselected	27 Other/See Notes	Florence	PING ON REQ 8128017 as of 19:00 on 11/17/18 jrcraig1 513.458.3791 // no notes, can't call to confirm due to phone #
973	8128007	Donaldson-H9320550041	11/17/2018 6:56:19 PM	11/17/2018 9:14:00 PM	11/18/2018 12:00:00 PM	TXOH: K105-83:26904774	-	1	2	CMP	Out	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	PING OFF REQ 8128011 as of 18:58 on 11/17/18 jrcraig1 513.458.3791 // power out
974	8128032	Donaldson-H9320550043	11/17/2018 7:09:34 PM	11/18/2018 9:51:00 AM	11/18/2018 10:30:00 AM	TXOH: 21BN-385:26877613	-	1	2	CMP	Out	0	EA Weather	Unselected	48 Replaced Service/Secondary	Florence	CMPL 2018-11-18 09:51:00 by T74214 RMK: PING OFF REQ 8128033 as of 19:10 on 11/17/18 jrcraig1 513.458.3791 // no notes
975	8128038	Florence-H9322410046	11/17/2018 7:30:33 PM	11/17/2018 7:35:37 PM	11/18/2018 12:00:00 PM	FOH: 31BN-230:26077609	40T	27	2	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	OPENED FOR SAFETY FOR EVENT 8122604
976	8128135	Longbranch-H9320980042	11/17/2018 8:21:03 PM	11/17/2018 8:44:20 PM	11/18/2018 12:00:00 PM	FOH: 34BN-40:25990274	65T	53	11	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	OPENED FOR REPAIRS FOR EVEN 8112092
977	8128148	Villa-H9322430041	11/17/2018 11:10:11 AM	11/17/2018 9:20:34 PM	11/18/2018 12:00:00 PM	TXOH: K84-601:26926129	-	1	2	CMP	Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	PING OFF REQ 8128151 as of 20:33 on 11/17/18 jrcraig1 513.458.3791 // no notes. M.ORTH 859-300-4794, 9:20PM 11/17/18. CREW ON SITE MAKING FINAL CONNECTIONS.
978	8128194	Hands-H9321280041	11/15/2018 7:25:58 PM	11/18/2018 6:38:00 AM	11/18/2018 7:00:00 AM	TXOH: 15K-1214:26875235	-	2	2	CMP	Out-S-Out/Out	0	03 Vegetation	-	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-18 06:38:00 by T18514 RMK: REMOVE TREE LIMB ACROSS PH & NU REAR PROP
979	8128221	Buffington-H9320670045	11/17/2018 10:01:09 PM	11/18/2018 4:30:00 AM	11/18/2018 5:00:00 AM	TXOH: K117-527:26907490	-	1	1	CMP	Out-Othr-O	0	04 Wildlife	-	44 Replaced Fuse	Florence	CMPL 2018-11-18 04:30:00 by T17410 RMK: 10d squirrel
980	8128231	Donaldson-H9320550041	11/17/2018 10:25:08 PM	11/18/2018 2:14:00 AM	11/18/2018 12:00:00 PM	TXOH: K116-367:26906736	-	0	1	CMP	On	0	03 Vegetation	-	30 Phone or TV Cable Problem	Florence	CMPL 2018-11-18 02:14:00 by T17410 RMK: limbs on calv & tel, electric in clear, left card on door
981	8128232	Crescent-H9320700044	11/17/2018 10:24:25 PM	11/17/2018 10:27:30 PM	11/18/2018 12:00:00 PM	S-RCL: 11430:K93-59-107815355	-	344	4	S-CMP	Out	0	05 Planned (IEEE)	Unselected	16 Closed Recl or Sectionalizer	Florence	OPEN RECL 11430 FOR SAFETY
982	8128238	Marshall-H9323580041	11/16/2018 10:50:35 AM	11/18/2018 12:49:58 AM	11/18/2018 12:00:00 PM	TXOH: 35CA-1011:26886813	-	1	1	CMP	PH-H-Tree-PH-Out	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OKA
983	8128239	Marshall-H9323580041	11/17/2018 10:31:30 PM	11/18/2018 12:50:36 AM	11/18/2018 12:00:00 PM	TXOH: 35CA-1011:26886813	-	1	1	CMP	PH-H-911-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OKA
984	8128240	Marshall-H9323580041	11/17/2018 10:31:30 PM	11/18/2018 12:51:18 AM	11/18/2018 12:00:00 PM	TXOH: 35CA-1011:26886813	-	1	1	CMP	PH-H-Tree-PH-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	OKA.
985	8128301	Florence-H9322410046	11/18/2018 12:56:50 AM	11/18/2018 1:00:08 AM	11/18/2018 12:00:00 PM	TXOH: 31BN-424:26883761	-	1	1	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CUSTOMER WAS DISCONNECTED. REPAIRS NEED TO BE MADE, NEED RISER AND WH REPAIRS
986	8128411	Donaldson-H9320550042	11/17/2018 2:11:43 PM	11/18/2018 8:30:00 AM	11/18/2018 12:00:00 PM	TXOH: K104-174:26903841	-	1	1	CMP	PH-H-Out	0	28 Other Cause	-	29 Permanent Repair	Florence	CMPL 2018-11-18 08:30:00 by T74214 RMK: per connections at wh
987	8128423	Dayton-H9320760042	11/18/2018 8:30:59 AM	11/18/2018 9:01:00 AM	11/18/2018 12:00:00 PM	TXOH: CA1-685:26897486	-	1	1	CMP	Out	0	28 Other Cause	Unselected	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-18 09:01:00 by T95129 RMK: CUST LOOKS TO BE ON, PROBABLE INTERNAL ISSUE, NO ACCESS TO METERS
988	8128432	Donaldson-H9320550042	11/15/2018 7:18:20 AM	11/18/2018 9:06:00 AM	11/18/2018 12:00:00 PM	TXOH: K104-174:26903841	-	1	4	CMP	Equip-E-Out-PF,PH-H-Out	0	05 Planned (IEEE)	-	29 Permanent Repair	Florence	CMPL 2018-11-18 09:06:00 by T74214 RMK: perm connectis at wh

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
989	8128453	Florence-H9322410046	11/18/2018 9:09:49 AM	11/18/2018 9:16:35 AM	11/18/2018 12:00:00 PM	TXOH: 31BN-424: 26883761	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	GOOD VOLTAGE CHECK BREAKERS CALL MAINT
990	8128461	Crescent-H9320700041	11/18/2018 9:18:45 AM	11/18/2018 9:45:00 AM	11/18/2018 12:00:00 PM	TXOH: K84-437: 26926614	-	7	0	CMP	-	0	05 Planned (IEEE)	Unselected	17 Closed Switch	Florence	TRF OPEN
991	8128463	Dayton-H9320760042	11/18/2018 9:20:03 AM	11/18/2018 10:00:00 AM	11/18/2018 12:00:00 PM	TXOH: CA1-685: 26897486	-	1	1	CMP	Out	0	28 Other Cause	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-18 10:00:00 by T56235 RMK: Customer reset House breaker
992	8128464	Hands-H9321280044	11/18/2018 9:22:15 AM	11/18/2018 10:50:49 AM	11/18/2018 12:00:00 PM	TXOH: K87-190: 26914956	-	1	1	CMP	Out-Othr-O	0	EA Weather	Unselected	22 Cut Off/Disconnect at Pole	Florence	R to E meter base & SEC off house. Knob pulled off customer notified RECONNECT when repairs are made
993	8128476	Wilder-H9320590043	11/18/2018 9:31:06 AM	11/18/2018 7:12:00 PM	11/18/2018 7:45:00 PM	TXUG: 26923225	-	1	1	CMP	Out	0	Unselected	Unselected	63 Temporary Cable-Secondary	Florence	REFER TO DANA UG. LEAD SECONDARIES. CUSTOMERS ARE RESTORED...MCKENNEY WILL STAY ON SITE UNTIL AMS IS DONE AND WILL CALL WHEN THAT HAPPENS
994	8128492	Florence-H9322410046	11/18/2018 9:36:42 AM	11/18/2018 1:11:00 PM	11/18/2018 2:00:00 PM	TXOH: 31BN-424: 26883761	-	9	2	CMP	Out	0	03 Vegetation	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-18 13:11:00 by T81490 RMK: triplex from pole to house gone, customer needs new seu cable and rk-1, may require cpc.
995	8128512	Florence-H9322410044	11/18/2018 9:55:16 AM	11/18/2018 12:11:44 PM		TXUG: 30BN-764: 26882563	-	0	1	CMP	Equip-E-Tree-PP-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	TREE LIMB ON LINE -- REMOVED LIMBS FROM LINE
996	8128532	White Tower-H9323040041	11/15/2018 3:09:23 PM	11/18/2018 10:40:00 AM	11/18/2018 11:30:00 AM	TXOH: 22K-520: 26878047	-	1	2	CMP	PH-H-Tree-PH-Out,Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-18 10:40:00 by WACASSO RMK: LINE DOWN IN THE YARD
997	8128552	White Tower-H9323040043	11/18/2018 10:24:17 AM	11/18/2018 11:18:00 AM	11/18/2018 12:00:00 PM	TXOH: 19K-803: 26876482	-	0	1	CMP	911-Tree-PP-Othr	0	03 Vegetation	Unselected	30 Phone or TV Cable Problem	Florence	CMPL 2018-11-18 11:18:00 by T95129 RMK: PHONE
998	8128566	Dry Ridge-H9321090041	11/18/2018 10:39:26 AM	11/18/2018 12:23:13 PM		TXOH: 20G-145: 26877311	-	0	1	CMP	PH-H-On	0	EA Weather	Unselected	30 Phone or TV Cable Problem	Florence	LINES DOWN
999	8128578	Villa-H9322430044	11/18/2018 10:54:57 AM	11/18/2018 1:43:00 PM	11/18/2018 2:40:00 PM	TXOH: K96-346: 26916608	-	0	1	CMP	Othr	0	EA Weather	Unselected	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-18 13:43:00 by T74214 RMK: REMOVE METER FOR REPAIRS
1000	8128596	Crescent-H9320700043	11/18/2018 11:08:47 AM	11/18/2018 1:00:00 PM		TXOH: K84-306: 26926491	-	0	1	CMP	PP-H-On	0	11 Unknown Cause	Unselected	30 Phone or TV Cable Problem	Florence	CMPL 2018-11-18 13:00:00 by WACASSO RMK: LINES DOWN REAR OF BUILDING
1001	8128653	Bellevue-H9321310042	11/18/2018 11:51:42 AM	11/18/2018 12:40:00 PM		TXOH: CA5-133: 49419702	-	1	1	CMP	Out	0	-	-	27 Other/See Notes	Florence	CMPL 2018-11-18 12:40:00 by T56235 RMK: Talked with customer Referred to electrician (ENTRANCE CABLE BROKEN AT WEATHER HEAD) WILL CALL BACK WHEN REPAIRS ARE COMPLETED
1002	8128666	Empire-H9322890041	11/18/2018 11:59:12 AM	11/18/2018 12:40:19 PM		TXOH: 31BN-831: 84914268	-	2	0	CMP	-	0	EA Weather	Unselected	48 Replaced Service/Secondary	Florence	OPEN FOR SAFETY
1003	8128683	Villa-H9322430041	11/18/2018 12:10:03 PM	11/18/2018 2:40:00 PM	11/18/2018 3:15:00 PM	TXOH: K84-96: 26925943	-	1	1	CMP	Out	0	03 Vegetation	-	20 Cut In/Reconnect at Pole	Florence	CMPL 2018-11-18 14:40:00 by WACASSO RMK: RECONNECT
1004	8128684	Limaburg-H9321890041	11/18/2018 12:10:08 PM	11/18/2018 1:37:00 PM		TXOH: 19BN-512: 26868281	-	0	1	CMP	Othr-O-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	CMPL 2018-11-18 13:37:00 by T95129 RMK: new knob isnt secure enough.
1005	8128690	Beaver-H9320860041	11/18/2018 12:13:21 PM	11/18/2018 1:01:00 PM		TXOH: 50BN-596: 26920876	-	0	1	CMP	-	0	28 Other Cause	Unselected	26 OK Arrival	Florence	CMPL 2018-11-18 13:01:00 by T95129 RMK: 11977 SKYWAY DR. WALTON KY NEEDS A NEW METER INSTALLED
1006	8128752	Hebron-H9321520045	11/18/2018 1:06:38 PM	11/18/2018 2:49:00 PM	11/18/2018 7:00:00 PM	TXOH: 14BN-459: 26867330	-	1	1	CMP	PH-H-Out	0	03 Vegetation	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-18 14:49:00 by T81490 RMK: WD/PH Electrician not ready, getting supplies and hoping to complete today. Electrician will call when service is complete
1007	8128772	Crescent-H9320700045	11/18/2018 1:29:03 PM	11/18/2018 1:31:16 PM		TXOH: K92-129: 26915842	Retrofit 1/24/2014	0	1	CMP	On	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	GOOD VOLTAGE CHECK BREAKERS CALL ELECTRICIAN
1008	8128786	Mt Zion-H9323050043	11/18/2018 1:33:17 PM	11/18/2018 2:25:00 PM	11/18/2018 7:00:00 PM	TXUG: 36BN-1432: 26887169	-	1	1	CMP	Pt O	0	-	Unselected	27 Other/See Notes	Florence	PT-O
1009	8128810	Villa-H9322430041	11/18/2018 2:02:15 PM	11/18/2018 2:53:45 PM	11/18/2018 8:15:00 PM	TXOH: K74-54: 26925048	-	0	1	CMP	PH-H-On	0	28 Other Cause	Unselected	Unselected	Florence	phone
1010	8128815	Buffington-H9320670045	11/18/2018 2:06:21 PM	11/18/2018 3:30:00 PM	11/18/2018 8:15:00 PM	TXOH: K105-854: 26864442	-	1	1	CMP	Out	0	EA Weather	Unselected	48 Replaced Service/Secondary	Florence	CMPL 2018-11-18 15:30:00 by T74214 RMK: RECONN
1011	8128820	Alexandria South-H9322050041	11/18/2018 2:10:07 PM	11/18/2018 4:08:00 PM	11/18/2018 5:00:00 PM	TXOH: 47CA-434: 26920254	-	0	1	CMP	PH-H-Tree-PP-On	0	EA Weather	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-18 16:08:00 by T25446 RMK: TWPH
1012	8128845	Limaburg-H9321890042	11/18/2018 2:30:17 PM	11/18/2018 3:30:00 PM	11/18/2018 8:45:00 PM	TXOH: 19BN-86: 26867844	-	1	1	CMP	PH-H-Pt O-LV	0	-	Unselected	39 Repaired Overhead Conductor	Florence	LOW LINES
1013	8128850	Florence-H9322410043	11/18/2018 2:36:15 PM	11/18/2018 3:05:00 PM	11/18/2018 4:00:00 PM	TXUG: BNK-4087: 27195768	-	1	1	CMP	Out	0	11 Unknown Cause	Unselected	44 Replaced Fuse	Florence	CMPL 2018-11-18 15:05:00 by T56235 RMK: OLIVE GARDEN OUT
1014	8128856	Buffington-H9320670045	11/18/2018 2:48:22 PM	11/18/2018 4:10:00 PM	11/18/2018 9:00:00 PM	TXOH: K117-544: 26907743	-	0	1	CMP	PH-H-On	0	EA Weather	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-18 16:10:00 by T74214 RMK: LOW LINES
1015	8128877	Donaldson-H9320550043	11/18/2018 3:15:19 PM	11/18/2018 4:37:00 PM	11/18/2018 9:30:00 PM	TXOH: K104-389: 26903787	-	1	1	CMP	Out	0	03 Vegetation	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-18 16:37:00 by T17410 RMK: service down by tree, refer to electrician for repairs
1016	8128893	Longbranch-H9320980042	11/15/2018 8:56:19 AM	11/18/2018 6:17:00 PM		TXOH: 45BN-163: 26870002	-	1	1	CMP	PH-H-Out	0	11 Unknown Cause	Unselected	25 No Problem Found	Florence	CMPL 2018-11-18 18:17:00 by T17410 RMK: LW/PH / no low wires found
1017	8128897	Florence-H9322410046	11/18/2018 3:40:24 PM	11/18/2018 5:56:00 PM	11/18/2018 9:45:00 PM	TXUG: 31BN-BE-6: 26883220	-	1	2	CMP	Out	0	20 Equipment failure	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-18 17:56:00 by T17636 RMK: PAD B# 31BN-BE-6 RESET MAIN BREAKER. CUSTOMER CONTACT. REFERRED TO ELECTRIC CONTRACTOR TO REPLACE MAIN BREAKER.

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
1018	8128901	Marshall-H9323580041	11/18/2018 3:46:27 PM	11/18/2018 7:00:00 PM	11/18/2018 6:45:00 PM	TXUG: 35CA-2095: 26886358	-	1	2	CMP	Out	0	20 Equipment failure	-	50 Reset Customer Breaker/Fuse/S	Florence	CMPL 2018-11-18 19:00:00 by T17636 RMK: PAD # 35CA-2095 RESET 100 AMP MAIN BREAKER. CUSTOMER CONTACT. REFERRED TO ELECTRIC CONTRACTOR 100 AMP MAIN BREAKER. 123-123-246 VOLYAGE AT METER BASE.
1019	8128918	Richwood-H9321990042	11/18/2018 4:20:46 PM	11/18/2018 5:52:00 PM	11/18/2018 10:30:00 PM	TXUG: BNK-3370: 27189812	-	1	1	CMP	Equip-E-Pt O-Othr	0	11 Unknown Cause	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-18 17:52:00 by T17410 RMK: reset customer breakers
1020	8128922	Crescent-H9320700045	11/18/2018 4:23:57 PM	11/18/2018 5:46:00 PM	11/18/2018 10:30:00 PM	TXOH: K92-314: 26915939	-	0	1	CMP	PH-H-Othr	0	20 Equipment failure	Unselected	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-18 17:46:00 by T18514 RMK: WD/PH OK TEMPO FENCED IN YARD NO KIDS OR PETS CAUTION TAPED ELDERLY CUST RTE ON RK1 SEC WH NO WAY TO TUT
1021	8128925	Crittenden-H9321240042	11/18/2018 4:30:20 PM	11/18/2018 6:06:00 PM	11/18/2018 7:00:00 PM	TXOH: 15G-52: 26874145	-	0	1	CMP	Tree-PP-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-18 18:06:00 by T25446 RMK: TREE ON WIRE
1022	8128958	Claryville-H9321470042	11/18/2018 5:19:40 PM	11/18/2018 8:59:00 PM	11/18/2018 9:45:00 PM	TXOH: 48CA-278: 26893698	-	1	2	CMP	Pt O	0	20 Equipment failure	-	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-18 20:59:00 by T17636 RMK: POLE # 48CA-278E CHECK # 4 TRI. SERVICE OK. CHECK CONNECTIONS IN METER BASE OK. 123-123-246 VOLTAGE AT METER BASE. CUSTOMER CONTACT. REFERRED TO ELECTRIC CONTRACTOR MAIN BREAKER.
1023	8128976	Buffington-H9320670041	11/18/2018 5:50:33 PM	11/18/2018 6:02:58 PM	11/19/2018 12:00:00 AM	TXUG: 26BN-1325: 26881084	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	GOOD VOLTAGE @ METER AND ALL METER ON TRF ARE PINGING ON. CUST ISSUE
1024	8128979	Hebron-H9321520045	11/18/2018 5:52:47 PM	11/18/2018 7:24:00 PM		TXOH: 14BN-459: 26867330	-	0	1	CMP	Othr	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-18 19:24:00 by T18514 RMK: INSTALL 60' OF #2 TRI
1025	8128984	Longbranch-H9320980043	11/18/2018 6:12:22 PM	11/18/2018 9:17:00 PM	11/18/2018 9:30:00 PM	TXOH: 35BN-235: 26885152	-	1	1	CMP	Pt O	0	20 Equipment failure	Unselected	11 Checked Voltage/All OK	Florence	CMPL 2018-11-18 21:17:00 by T17410 RMK: PT O/NO 220 / good voltage in house panel. r to e
1026	8129062	Donaldson-H9320550041	11/18/2018 7:54:09 PM	11/19/2018 1:55:00 AM	11/19/2018 2:00:00 AM	TXOH: K105-73: 26905105	-	1	1	CMP	Pt O-Othr-PQ	0	03 Vegetation	Unselected	11 Checked Voltage/All OK	Florence	CMPL 2018-11-19 01:55:00 by T97390 RMK: T PT OUT
1027	8129068	White Tower-H9323040041	11/18/2018 8:20:44 PM	11/18/2018 10:50:00 PM		TXOH: 30K-1: 26862946	-	0	1	CMP	Othr-O-LF-Othr	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-18 22:50:00 by T17636 RMK: POLE # 3K-1 REPAIR AND RESAG # 4 TRI. SERVICE. 121-121-242 VOLTAGE AT METER BASE. CUSTOMER CONTACT.
1028	8129072	Donaldson-H9320550043	11/18/2018 8:42:48 PM	11/18/2018 8:48:53 PM	11/18/2018 11:30:00 PM	TXOH: K104-389: 26903787	-	1	2	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	THIS WAS RAN EARLIER TODAY. CUSTOMER'S SERVICE IS ROLLED UP. NEEDS ELECTRICIAN. DOOR HANGER WAS LEFT ON BACK DOOR
1029	8129082	White Tower-H9323040043	11/18/2018 10:49:55 PM	11/18/2018 10:52:53 PM		TXOH: 19K-412: 26877035	-	0	1	CMP	Othr	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	NEED INSPECTION OR A RELEASE
1030	8129126	Bellevue-H9321310043	11/19/2018 12:50:53 AM	11/19/2018 1:31:00 AM		TXOH: CA7-240: 26902362	-	0	2	CMP	Fire-E-911-PF-Othr	0	28 Other Cause	Unselected	22 Cut Off/Disconnect at Pole	Florence	CMPL 2018-11-19 01:31:00 by T97390 RMK: 911 STRUCT FIRE
1031	8129137	Wilder-H9320590043	11/19/2018 4:09:58 AM	11/19/2018 6:07:00 AM	11/19/2018 6:30:00 AM	TXUG: 26923225	-	0	1	CMP	Othr	0	20 Equipment failure	-	48 Replaced Service/Secondary	Florence	CMPL 2018-11-19 06:07:00 by MLMCKEN RMK: arms installed new duct and 350 cable connections were made.
1032	8129145	Alexandria South-H9322050041	11/19/2018 6:02:38 AM	11/19/2018 7:39:23 AM	11/19/2018 10:00:00 AM	S-RCL: 582: CAK-4426: 408737314	-	290	54	S-CMP	Out	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	RECL 582757 L/O ALL PHASES - TREE ON LINE @ P#40CA-33
1033	8129157	Hands-H9321280041	11/19/2018 7:08:52 AM	11/19/2018 5:06:00 PM		TXOH: 14K-319: 26873931	-	0	2	CMP	PH-H-On_On	0	05 Planned (IEEE)	Unselected	19 Cut In/Reconnect at Weatherhe	Florence	CMPL 2018-11-19 17:06:00 by T97055 RMK: RECON AT WH
1034	8129159	Silver Grove-H9320620043	11/19/2018 7:11:02 AM	11/19/2018 9:02:00 AM	11/19/2018 10:00:00 AM	TXOH: 40CA-159: 26891202	-	1	1	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-19 09:02:00 by T97635 RMK: CUST NOT ON PREM. DID NOT ANSWER PHONE. DOGS RUNNING LOOSE ON PROPERTY. COULD NOT GET TO MTR. CUST NEEDS TO BE ON PREM AND HAVE DOGS UP.
1035	8129165	Crescent-H9320700043	11/19/2018 7:21:25 AM	11/19/2018 9:49:00 AM		TXOH: K84-304: 26925940	-	0	1	CMP	PH-H-LF-On	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-19 09:49:00 by T97635 RMK: NO ONE ON PREM. NO ACCESS TO MTR. CUST APPEARS TO HAVE POWER. SAW LIGHT ON AND COULD SEE DISPLAY ON MTR THROUGH GARAGE WINDOW. CUST NEEDS TO BE ON PREM.
1036	8129177	Alexandria South-H9322050041	11/19/2018 7:39:23 AM	11/19/2018 7:39:27 AM		S-RCL: 514: 43CA-352: 409694906	EAM LOC ID 79557	470	0	M-CMP	-	0	03 Vegetation	Unselected	10 Automatic Restoration	Florence	PART OF E# 8129145
1037	8129187	Alexandria South-H9322050041	11/19/2018 6:02:00 AM	11/19/2018 9:19:00 AM	11/19/2018 10:30:00 AM	TXOH: CAK-4409: 391854243	-	3	2	CMP	Out-S-Out,Out-AMI	0	11 Unknown Cause	Unselected	11 Checked Voltage/All OK	Florence	CMPL 2018-11-19 09:19:00 by T97055 RMK: TRF PINGED OFF CUST SAID WENT OFF 0600 AND BACK ON AT 0800
1038	8129199	Florence-H9322410044	11/19/2018 8:01:39 AM	11/19/2018 1:32:00 PM	11/19/2018 2:00:00 PM	TXOH: 25BN-430: 26880331	-	1	2	CMP	Out	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-19 13:32:00 by T95129 RMK: repaired storm repairs
1039	8129204	Alexandria South-H9322050041	11/19/2018 6:10:29 AM	11/19/2018 9:49:00 AM	11/19/2018 11:00:00 AM	TXOH: CAK-311: 27187478	-	1	2	CMP	Out-S-Out,Out	0	03 Vegetation	Unselected	24 N/A	Florence	CMPL 2018-11-19 09:49:00 by T97055 RMK: SINGLE OUT OUT AT0600 TO 0800
1040	8129206	Donaldson-H9320550044	11/19/2018 8:14:00 AM	11/19/2018 8:54:00 AM		TXUG: K104-24: 26903895	-	0	1	CMP	Tree-PH-On	0	03 Vegetation	Unselected	26 OK Arrival	Florence	CMPL 2018-11-19 08:54:00 by T95129 RMK: no problem found
1041	8129220	Florence-H9322410046	11/19/2018 8:25:33 AM	11/19/2018 9:00:00 AM	11/19/2018 11:15:00 AM	TXUG: 31BN-BE-6: 26883220	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	GOOD VOLTAGE TO METER. REF TO ELECTRICIAN
1042	8129229	Donaldson-H9320550043	11/19/2018 8:32:12 AM	11/19/2018 9:42:00 AM		TXOH: 21BN-572: 26877927	-	0	1	CMP	PH-H-On	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-19 09:42:00 by T95129 RMK: 1/0 up perm. r2e entrance cable
1043	8129241	Verona-H9321250041	11/19/2018 8:43:34 AM	11/19/2018 6:47:46 PM		TXOH: 37K-5: 26919642	-	0	1	CMP	CC-H-Othr-O-On	0	03 Vegetation	Unselected	47 Replaced Pole	Florence	CREW REPL POLE OK.

#	Event #	Circuit	Start Time	End Time	Est Rest Time	Device Type	Device Location	# Cust Out	# Cust Calls	Status	Trouble Condition	Damage Assessment	Cause	Damage / Failure	Action Taken	Callout Zone	Remarks
1044	8129271	Villa-H9322430043	11/19/2018 9:05:24 AM	11/19/2018 12:21:00 PM		TXOH: K96-549: 26916571	-	0	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	Unselected	38 Removed Object From Line	Florence	CMPL 2018-11-19 12:21:00 by T95129 RMK: remove tree
1045	8129301	Villa-H9322430044	11/19/2018 9:21:43 AM	11/19/2018 10:01:00 AM		TXOH: K106-774: 26905211	-	0	1	CMP	PH-H-On	0	03 Vegetation	Unselected	30 Phone or TV Cable Problem	Florence	CMPL 2018-11-19 10:01:00 by T95129 RMK: LWPH ctv
1046	8129328	Claryville-H9321470042	11/19/2018 9:40:10 AM	11/19/2018 4:10:00 PM		TXOH: 47CA-80: 26920359	-	0	1	CMP	Othr-O-On	0	05 Planned (IEEE)	Unselected	19 Cut In/Reconnect at Weatherher	Florence	CMPL 2018-11-19 16:10:00 by T29408 RMK: RECON WIRE NEEDS TO BE PUT UP ACROSS RD WIRE IS ON POLE TRUCK ACC AND FLAG? WDPH
1047	8129330	Donaldson-H9320550041	11/19/2018 9:44:39 AM	11/19/2018 1:06:55 PM		TXOH: 26BN-654: 26918726	-	0	1	CMP	PH-H-On	0	EA Weather	Unselected	30 Phone or TV Cable Problem	Florence	
1048	8129336	Hands-H9321280041	11/19/2018 9:49:59 AM	11/19/2018 12:58:00 PM	11/19/2018 7:00:00 PM	TXOH: 15K-158: 26875368	-	1	1	CMP	PH-H-Tree-PH-Out	0	03 Vegetation	Unselected	22 Cut Off/Disconnect at Pole	Florence	CMPL 2018-11-19 12:58:00 by T97055 RMK: NEED CREW 30 TO35' LIFT POLE 15K-932, 275' #2 TRI TRUCK ACC NO FLAGGER MAY NEED REAR PROP CAR BC OF RAIN.
1049	8129347	White Tower-H9323040041	11/19/2018 10:00:52 AM	11/19/2018 10:37:00 AM		TXOH: 23K-631: 26928284	-	0	1	CMP	Tree-PP-Othr	0	03 Vegetation	Unselected	30 Phone or TV Cable Problem	Florence	CMPL 2018-11-19 10:37:00 by T95129 RMK: phone
1050	8129348	Limaburg-H9321890042	11/19/2018 10:02:18 AM	11/19/2018 10:53:00 AM	11/19/2018 1:00:00 PM	TXOH: 18BN-41: 26867762	-	1	2	CMP	Out	0	28 Other Cause	Unselected	11 Checked Voltage/All OK	Florence	CMPL 2018-11-19 10:53:00 by T95500 RMK: SINGLE OUT **** cust tried to call back and cancel call but was unable to. ok arrival
1051	8129354	Florence-H9322410042	11/19/2018 10:09:25 AM	11/19/2018 2:14:00 PM		TXOH: 26BN-507: 26865360	-	0	1	CMP	PH-H-Tree-PH-On	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-19 14:14:00 by T25446 RMK: TWPH
1052	8129366	Covington KY-H9322170042	11/19/2018 10:18:47 AM	11/19/2018 11:59:00 AM		TXUG: K51-D1-4: 30638673	-	0	1	CMP	Equip-E-Othr	0	20 Equipment failure	Unselected	18 Customer Trouble/No Outage	Covington	CMPL 2018-11-19 11:59:00 by T97055 RMK: WPH IS SMOKING COUG FOR CUST WORK, IN SIDE WALK.
1053	8129377	Crescent-H9320700043	11/19/2018 10:27:18 AM	11/19/2018 1:32:00 PM		TXOH: K83-629: 26925292	-	0	1	CMP	PP-H-Tree-PP-On	0	11 Unknown Cause	Unselected	25 No Problem Found	Florence	CMPL 2018-11-19 13:32:00 by T29408 RMK: TWPP REAR PROP
1054	8129379	Florence-H9322410042	11/19/2018 10:28:56 AM	11/19/2018 2:10:00 PM		TXOH: K116-939: 26906810	-	0	1	CMP	Tree-PH-On	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-19 14:10:00 by T25446 RMK: TWPH
1055	8129394	Crescent-H9320700043	11/19/2018 10:39:07 AM	11/19/2018 12:00:00 PM	11/19/2018 1:30:00 PM	TXOH: K73-495: 26912675	-	1	1	CMP	Pt O	0	20 Equipment failure	Unselected	12 Checked Voltage/Fixed Connect	Florence	CMPL 2018-11-19 12:00:00 by T29408 RMK: REF E/T. CUST HAS ONE DEAD LEG. CAN NOT GET TO WEATHERHEAD WITH LADDER SAFELY. REFER TO OH TROUBLE. CUST WILL BE ON PREM.
1056	8129402	Buffington-H9320670045	11/19/2018 10:43:00 AM	11/19/2018 3:25:00 PM		TXOH: K117-300: 26907862	-	0	1	CMP	On	0	03 Vegetation	Unselected	39 Repaired Overhead Conductor	Florence	CMPL 2018-11-19 15:25:00 by T56235 RMK: RECON
1057	8129419	Florence-H9322410046	11/19/2018 10:51:48 AM	11/19/2018 12:01:00 PM	11/19/2018 1:45:00 PM	TXUG: 31BN-AE-26: 26883244	-	1	1	CMP	Out	0	28 Other Cause	Unselected	27 Other/See Notes	Florence	CMPL 2018-11-19 12:01:00 by T95500 RMK: SINGLE OUT*** mtr was off remotely I turned mtr on and left avail.
1058	8129422	Covington KY-H9322170044	11/19/2018 10:48:23 AM	11/19/2018 6:17:00 PM		TXOH: K52-241: 53963657	-	0	1	CMP	Othr-O-On	0	05 Planned (IEEE)	Unselected	24 N/A	Covington	CMPL 2018-11-19 18:17:00 by T97055 RMK: RECON NOT READY YET
1059	8129423	Crescent-H9320700044	11/19/2018 10:55:08 AM	11/19/2018 11:29:00 AM	11/19/2018 1:45:00 PM	TXUG: K93-B1-11: 26927412	-	1	1	CMP	Pt O	0	28 Other Cause	-	11 Checked Voltage/All OK	Florence	CMPL 2018-11-19 11:29:00 by T97635 RMK: 123-123-246. VOLTAGE GOOD. NO CUST ON PREM
1060	8129424	Florence-H9322410046	11/19/2018 10:55:59 AM	11/19/2018 2:35:00 PM		TXOH: 31BN-966: 26883459	-	0	1	CMP	Tree-PH-Othr	0	03 Vegetation	Unselected	37 Removed Limb or Tree From Lin	Florence	CMPL 2018-11-19 14:35:00 by T25446 RMK: TWPH
1061	8129433	Villa-H9322430041	11/19/2018 11:03:52 AM	11/19/2018 2:33:00 PM		TXOH: K95-529: 26927859	-	0	1	CMP	PH-H-On	0	03 Vegetation	Unselected	30 Phone or TV Cable Problem	Florence	CMPL 2018-11-19 14:33:00 by T97055 RMK: LWPH/REAR PROP
1062	8129457	Florence-H9322410046	11/19/2018 11:20:07 AM	11/19/2018 11:25:11 AM	11/19/2018 2:15:00 PM	TXUG: 31BN-BE-6: 26883220	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	GOOD VOLTAGE TO METER. UNABLE TO MAKE CUS CONTACT
1063	8129472	Crittenden-H9321240041	11/19/2018 11:28:04 AM	11/19/2018 2:47:38 PM		TXOH: 6G-103: 26896279	-	0	1	CMP	Tree-PH-Othr	0	11 Unknown Cause	Unselected	26 OK Arrival	Florence	OK ARRIVAL
1064	8129485	Beaver-H9320860042	11/19/2018 11:33:47 AM	11/19/2018 12:00:13 PM	11/19/2018 2:30:00 PM	TXOH: 41BN-127: 26891600	-	1	1	CMP	Out	0	28 Other Cause	Unselected	33 OK per Meter Interrogation	Florence	GOOD VOLTAGE TO METER. REF TO ELECTRICIAN
1065	8129490	Buffington-H9320670045	11/19/2018 11:35:02 AM	11/19/2018 2:35:00 PM	11/19/2018 3:00:00 PM	TXOH: K105-460: 26904885	-	1	1	CMP	PH-H-Out	0	03 Vegetation	Unselected	29 Permanent Repair	Florence	CMPL 2018-11-19 14:35:00 by T56235 RMK: LWPH
1066	8129494	Hands-H9321280041	11/19/2018 11:37:19 AM	11/19/2018 12:33:00 PM		TXOH: 14K-446: 26873521	-	0	1	CMP	On	0	28 Other Cause	-	11 Checked Voltage/All OK	Florence	CMPL 2018-11-19 12:33:00 by T97635 RMK: 122-122-244. GOOD VOLTAGE. CUST NOT ON PREM
1067	8129507	Bellevue-H9321310044	11/19/2018 11:51:42 AM	11/19/2018 3:05:00 PM		TXOH: CA6-1326: 26901329	-	0	1	CMP	Tree-PP-Othr	0	03 Vegetation	Unselected	18 Customer Trouble/No Outage	Florence	CMPL 2018-11-19 15:05:00 by T97055 RMK: TWPP
1068	8129511	Donaldson-H9320550042	11/19/2018 11:53:07 AM	11/19/2018 1:22:28 PM		TXOH: 26903956	-	0	1	CMP	PH-H-Tree-PH-On	0	28 Other Cause	Unselected	26 OK Arrival	Florence	NO ISSUE FOUND PER MATT JOHNSON

2018 November Ice Storm Restoration Estimate
Duke Energy Kentucky

<u>November Ice Storm (O&M including Payroll taxes)</u>	<u>Kentucky Estimated O&M Expense</u>
Estimated Internal Duke Energy Kentucky Labor	\$ 333,554
Linemen Contractors	\$1,012,146
Tree Trimming Contractors	<u>\$ 243,804</u>
Subtotal Contractor Estimate	\$1,255,950
Materials & Supplies Expensed	\$ 39,738
Other Non-Labor Expenses (Food, Lodging, etc.)	\$ 69,162
<i>Total Kentucky O&M Cost Projection Estimate for November Ice Storm Restoration</i>	<u>\$1,698,404</u>
Estimated Amount Considered Normal Operations (Internal Duke Energy Kentucky Labor)	\$.58,872
<i>Total Estimated Incremental O&M Impacts to Kentucky</i>	<u>\$1,639,532</u>