COMMONWEALTH OF KENTUCKY

BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY FRONTIER GAS, LLC

ALLEGED VIOLATION OF UNDERGROUND FACILITY DAMAGE PREVENTION ACT

CASE NO. 2019-00321

NOTICE OF FILING

Notice is given to all parties that the Gas Excavation Damage Report for Incident

31465 has been filed into the record for this proceeding.

ven R. Purso

Gwen R. Pinson Executive Director Public Service Commission P.O. Box 615 Frankfort, KY 40602

DATED OCT 3 1 2019

cc: Parties of Record

Gas Excavation Damage Report

Kentucky Frontier Gas, LLC

Print

Submitted 4/12/2019 Incident ID: 31465

Set back to Edit Staff Edit

Reported By: Name: Heather Music

Phone: 606-886-2431 ext 100

Email: hmusic@kyfrontiergas.com

Gas Line Incident Occured: Date: 3/14/2019

Time: 2:00 PM

Details: Reported Date: 4/12/2019 10:29 AM

Incident Location Address: Location: 37.70233 -82.77659

Address: Stephens Branch Rd

City: Prestonsburg

State: KY

County: Floyd

Zip: 41653

Confirm Code:

Address	City	State	
ZipCode	County	State	

Number of Customers out: 43

Locate Request Ticket No.: 1903040814

Excavator: Contractor

Organization ID	Company	Status	Company Type
Excavator Address: First Name: Casey			
Last Name: Duncan			
Organization ID: 1007031			
Company: Duncan Construction L.L.C.			
Phone: 606-226-1048			
Email:			
Address: 1875 Abbott Creek Rd			
City: Prestonsburg			
State: KY			
Zip: 41653			
Confirm Code: Y			
Address	City		State
ZipCode	County		State

Excavation Damage: Facility could not be found or located

Description of Incident Construction crew nicked a 4" main line causing a cut on the side which resulted in the release of gas.

Summary Information 4/12/2019

 Full details such as the Duncan Construction was clearing out ditches with an excavator and nicked our 4" main with the side cutter on the bucket. KFG construction

crew was within 10 minutes of the jobsite and were able to respond quickly. The crew shut off a critical valve and had the situation safe within 20 minutes of the call in. This resulted in the loss of service to 43 customers in the area. Our construction crew repaired the section with pretested PE and were able to pressure the line back up within an hour. Field technicians went to each affected customer and restored service if they were home or left a door tag. KFG did receive an 811 on this job, but we were unable to give an exact location within the tolerance zone of the main line. The locator technician spoke with the company representative and showed them the general location of the line and requested for them to call into the office when the job was being done so that a technician could come and stay with the crew during excavation.

Extent of the damage

Cost of the damage

Damage to the pipe was fairly minimal and repaired with a small amount of pipe and 2 EF couplings. \$450.00

KFG inherited many miles of lines that were never mapped correctly, we

and put them in to the system. We do have equipment to locate lines but

the majority of older lines were put in without tracer wire.

Steps taken to prevent have upgraded to a GIS system and are consistently working to locate lines

re-occurance

Amount billed to excavator

\$0.00

CT Corporation System Register Agent 306 W Main Street, Suite 512 Frankfort, KENTUCKY 40601

*Honorable John N Hughes Attorney at Law 124 West Todd Street Frankfort, KENTUCKY 40601

*Kentucky Frontier Gas, LLC 4891 Independence Street, Suite 200 Wheat Ridge, CO 80033

*Kentucky Frontier Gas, LLC Kentucky Frontier Gas, LLC 4891 Independence Street, Suite 200 Wheat Ridge, CO 80033