

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

CHAD PEERCY

ALLEGED VIOLATION OF UNDERGROUND
FACILITY DAMAGE PREVENTION ACT

)
)
)
)
)
)

CASE NO.
2019-00339

NOTICE OF FILING

Notice is given to all parties that a Gas Excavation Damage Report for Incident 31302 has been filed into the record of this proceeding.



Gwen R. Pinson
Executive Director
Public Service Commission
P.O. Box 615
Frankfort, KY 40602

DATED NOV 08 2019

cc: Parties of Record

Gas Excavation Damage Report

Delta Natural Gas Company, Inc.

Submitted 1/30/2019 Incident ID: 31302

[Set back to Edit](#)

[Staff Edit](#)

[Print \(PDFForm.aspx?Rpt=GasInvestigation&IG=31302\)](#)

Reported By:

Name: Mary Virginia Rupard
Phone: 859-744-6171 ext. 1160
Email: mvrupard@deltagas.com

Gas Line Incident Occured:

Date: 1/16/2019
Time: 4:30 PM

Details:

Reported Date: 1/25/2019 1:10 PM

Incident Location Address:

Location: 113 Mountain View Drive
Address: 113 Mountain View Dr
City: Berea
State: KY
County: Madison
Zip: 40403
Confirm Code: Y
Number of Customers out: 1
Locate Request Ticket No.: 1901081786
Excavator: Contractor

Excavator Address:

First Name: Chad
Last Name: Peercy
Organization ID:
Company: Peercy Lawn Care
Phone: 859-358-1934
Email: chad.peercy@gmail.com
Address: 2341 Lancaster Rd
City: Richmond
State: KY
Zip: 40475

Confirm Code: Y

Excavation Damage: Failure to support exposed facilities

Description of Incident Chad Peercy was using a backhoe to dig a ditch to install a drainage pipe when he hit and broke a 3/4-inch plastic service line.

Summary Information

1/30/2019

Full details such as the cause	Chad Peercy called 811 to request a line location prior to excavating. The line was located and marked correctly by a Delta employee. Mr. Peercy exposed the service line prior to excavating. The service line broke when he used the backhoe to remove some tree roots.
Extent of the damage	There were no injuries or property damage attributable to this incident. Delta employees replaced two feet of 3/4-inch plastic pipe and installed two permasert couplings.
Cost of the damage	\$182.00
Steps taken to prevent re-occurrence	Mr. Peercy was advised to be more cautious when working around an exposed gas line.
Amount billed to excavator	\$0.00

*Chad Percy
2341 Lancaster Rd.
Richmond, KENTUCKY 40475

*Chad Percy
5106 Walnut Meadow Road
, KENTUCKY 40461