

COMMONWEALTH OF KENTUCKY  
BEFORE THE PUBLIC SERVICE COMMISSION

RECEIVED

OCT 06 2010

PUBLIC SERVICE  
COMMISSION


In the Matter of:

KENTUCKY POWER COMPANY )  
D/B/A AMERICAN ELECTRIC POWER )  
\_\_\_\_\_) )  
ALLEGED FAILURE TO COMPLY WITH )  
KRS 278.042 )

CASE NO. 2010-000317

Notice of Filing Of Exhibit 1 To Response

Kentucky Power Company hereby files Exhibit 1 to its Response to the Public Service Commission of Kentucky's August 20, 2010 Order in this matter. The exhibit was inadvertently omitted when the Response was filed.



Mark R. Overstreet  
STITES & HARBISON PLLC  
421 West Main Street  
P.O. Box 634  
Frankfort, KY 40602-0634  
Telephone: (502) 223-3477  
COUNSEL FOR KENTUCKY POWER  
COMPANY

## Exhibit 1

### Description of Subject Matter of Photographs Appended As Attachment C to Commission Report

1. View of Service Pole and point of attachment facing the front of the mobile home. Photo was taken to show the amount of lean on the Service Pole towards the direction of the service pull.
2. Close up view of contact point of the service conductor.
3. A close up view of the point of contact from the opposite side of #1.
4. Same as #1.
5. Broad view of Service Drop Path.
6. View of Customer Service Pole taken to show the amount of wash out and erosion around base of the pole area.
7. View of Service Conductor at the contact point.
8. View of Customer Service Pole. Photo taken to show the amount of Pole lean in the service direction.
9. View of washed out area around Customer Service Pole.
10. View of the Service point attachment on the Customer Service Pole. The photo was taken to show the pole and attachment height above the roof of the mobile home.
11. View at the edge of the fill area where the drop off occurs.
12. A wider view of the Service Drop at the point where the drop off occurs.
13. View depicting the amount of rise to the earth facing KYPCO Pole.
14. An opposite view of picture #9.
15. View of the Meter.
16. View of the Customer Service Pole from the elevated drive of next door neighbor.
17. A different angle depicting wash out area of the Customer Service Pole.
18. Different angle view of service conductor.