

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY FRONTIER GAS, LLC)
)
_____)
)

ALLEGED VIOLATION OF UNDERGROUND)
FACILITY DAMAGE PREVENTION ACT)

CASE NO.
2019-00280

NOTICE OF FILING

Notice is given to all parties that the Gas Excavation Damage Report for Incident 21110 has been filed into the record for this proceeding.



Gwen R. Pinson
Executive Director
Public Service Commission
P.O. Box 615
Frankfort, KY 40602

DATED OCT 31 2019

cc: Parties of Record

Gas Excavation Damage Report

Kentucky Frontier Gas, LLC

Submitted 11/7/2018 Incident ID: 21110

[Set back to Edit](#)

[Staff Edit](#)

[Print](#)

Reported By:

Name:

Heather Music

Phone:

606-886-2431 ext 100

Email:

hmusic@kyfrontiergas.com

Gas Line Incident Occured:

Date:

10/6/2018

Time:

1:30 PM

Details:

Reported Date: 11/2/2018 11:04 AM

Incident Location Address:

Location:

37.74397 -83.09326

Address:

290 Connelly Farm Rd

City:

Salyersville

State:

KY

County:

Magoffin

Zip:

41465

Confirm Code:

Y

| | | |
|---------|--------|-------|
| Address | City | State |
| ZipCode | County | State |

Number of Customers out: 0

Locate Request Ticket No.: 1809061449

Excavator: Home Owner

| Organization ID | Company | Status | Company Type |
|-----------------|---------|--------|--------------|
|-----------------|---------|--------|--------------|

Excavator Address:

First Name:

Tim

Last Name:

May

Organization ID:

Company:

Phone:

606-349-1092

Email:

Address:

290 Conelley Road

City:

Salyersville

State:

Ky

Zip:

41465

Confirm Code:

| Address | City | State |
|---------|--------|-------|
| ZipCode | County | State |

Excavation Damage: Facility could not be found or located

Description of Incident Mr. May was using a ditch witch and hit our 1" service line.

Summary Information *11/7/2018*

Full details such as the cause This line was unlocateable, KFG field technician went out and met with the customer and indicated that he was not sure where the line was but that

there was one in the area. During digging, a 1" service line was broken. The line was capped off at the break by KFG construction crew.

| | |
|---|---|
| Extent of the damage | Minimal, 1" service line capped off |
| Cost of the damage | \$115.00 |
| Steps taken to prevent re-occurrence | KFG is in the process of investigating options to improve our ability to locate PE lines that do not have tracer wire and are not in an section that we are able to use our line locator. |
| Amount billed to excavator | \$0.00 |

CT Corporation System Register Agent
306 W Main Street, Suite 512
Frankfort, KENTUCKY 40601

*Honorable John N Hughes
Attorney at Law
124 West Todd Street
Frankfort, KENTUCKY 40601

*Kentucky Frontier Gas, LLC
4891 Independence Street, Suite 200
Wheat Ridge, CO 80033

*Kentucky Frontier Gas, LLC
Kentucky Frontier Gas, LLC
4891 Independence Street, Suite 200
Wheat Ridge, CO 80033