

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY FRONTIER GAS, LLC)
)
_____)
)

ALLEGED VIOLATION OF UNDERGROUND)
FACILITY DAMAGE PREVENTION ACT)

CASE NO.
2019-00316

NOTICE OF FILING

Notice is given to all parties that the Gas Excavation Damage Report for Incident 21255 has been filed into the record for this proceeding.



Gwen R. Pinson
Executive Director
Public Service Commission
P.O. Box 615
Frankfort, KY 40602

DATED OCT 31 2019

cc: Parties of Record

Gas Excavation Damage Report

Kentucky Frontier Gas, LLC

Submitted 12/27/2018 Incident ID: 21255

[Set back to Edit](#)

[Staff Edit](#)

[Print](#)

Reported By:

Name:

Heather Music

Phone:

606-886-2431 ext 100

Email:

hmusic@kyfrontiergas.com

Gas Line Incident Occured:

Date:

11/29/2018

Time:

11:00 AM

Details:

Reported Date: 12/27/2018 3:34 PM

Incident Location Address:

Location:

37.68608 -82.81422

Address:

Abbott Creek Road

City:

Prestonsburg

State:

KY

County:

Floyd

Zip:

41653

Confirm Code:

Address	City	State	
ZipCode	County	State	

Number of Customers out: 1

Locate Request Ticket No.: 1811040087

Excavator: Contractor

Organization ID	Company	Status	Company Type
-----------------	---------	--------	--------------

Excavator Address:

First Name:

Kirby

Last Name:

Bowling

Organization ID:

0456636

Company:

BOCA ENTERPRISES INC.

Phone:

606-454-1694

Email:

kirbybowling@yahoo.com

Address:

7435 State Hwy 321

City:

Prestonburg

State:

Ky

Zip:

41653

Confirm Code:

Address	City	State
ZipCode	County	State

Excavation Damage: Facility could not be found or located

Description of Incident Contractor was installing a sewer main for a utility company and hit a 1" PE service line

Summary Information 12/27/2018

Full details such as the cause

During excavation, the construction crew for BOCA punctured a 1" PE service line with the tooth of the excavator. An 811 was done for the area by the contractor on 11-4-18 and KFG went out to the dig site to do the locate. Due to insufficient mapping from the previous company who installed the lines, we were unable to mark within the 18inch requirement but did speak with the contractor supervisor and indicated that we were unsure where the service line was in that area.

Extent of the damage Minimal, had to replace 3' of 1" PE

Cost of the damage \$125.00

Steps taken to prevent re-occurrence

After visibly seeing the line and acquiring GPS coordinates, KFG updated our GIS system to prevent reoccurrence in this area for future locate tickets.

Amount billed to excavator

\$0.00

CT Corporation System Register Agent
306 W Main Street, Suite 512
Frankfort, KENTUCKY 40601

*Honorable John N Hughes
Attorney at Law
124 West Todd Street
Frankfort, KENTUCKY 40601

*Kentucky Frontier Gas, LLC
4891 Independence Street, Suite 200
Wheat Ridge, CO 80033

*Kentucky Frontier Gas, LLC
Kentucky Frontier Gas, LLC
4891 Independence Street, Suite 200
Wheat Ridge, CO 80033