COMMONWEALTH OF KENTUCKY BEFORE THE PUBLIC SERVICE COMMISSION

,			
)		
)	CASE 2019-00	

NOTICE OF FILING

Notice is given to all parties that the Gas Excavation Damage Report for Incident 31516 has been filed into the record for this proceeding.

Gwen R. Pinson Executive Director

Public Service Commission

P.O. Box 615

Frankfort, KY 40602

DATED OCT 3 1 2019

cc: Parties of Record

Gas Excavation Damage Report

Kentucky Frontier Gas, LLC

Submitted 4/25/2019 Incident ID: 31516

Set back to Edit	Staff Edit	Prin
2 4 1 D	-	

Reported By:

Name:

Heather Music

Phone:

606-886-2431 ext 100

Email:

hmusic@kyfrontiergas.com

Gas Line Incident Occured:

Date: 3/28/2019

Time: 5:33 PM

Details:

Reported Date: 4/25/2019 1:17 PM

Incident Location Address:

Location:

37.76284 -83.08919

Address:

Elk Creek Road

City:

Salyersville

State:

KY

County: Magoffin

Zip:

41465

Confirm Code:

Address	City	State
ZipCode	County	State

Number of Customers out: 15

Locate Request Ticket No.: 1903180293

Excavator: Contractor

Organization ID	Company	Status	Company Type
Excavator Address: First Name: Bret			
Last Name: Conley			
Organization ID:			
Company: L&L Excavating			
Phone: 606-349-1933			
Email: bconley1963@gmail.com			
Address: 111 Brad Dr			
City: Salyersville			
State: KY			
Zip: 41465			
Confirm Code: Y			

Address	City	State
ZipCode	County	State

Excavation Damage: Facility could not be found or located

Description of Incident While shooting a mole underneath the road for a sewer drain, the excavator hit our 3" PE main line causing a 1" hole in the pipe wall.

Summary Information 4/25/2019

During an ongoing sewer line job, the construction company was boring under the main road to do a crossing. Their equipment hit a 3" PE main line of KFG's that was alongside the roadway, causing damage resulting in the release of gas. Upon responding to the scene, KFG field technicians shut down 3 valves to stop the gas from blowing until the construction crew

cause

Full details such as the could get to the scene and do the repairs. Repairs were made by EF and when the gas line was pressured back up, field technicians restored gas service to the affected customers or left door hangers if they were not home. KFG techs responded to an 811 for this area and informed the contractor that there were lines alongside the roadway but did not put down actual marks due to not being able to locate within the tolerance zone of 18 inches on each side.

Extent of the damage

Minor damage to the line, techs responded within 20 minutes so gas loss was minimal.

Cost of the damage

\$300.00

Steps taken to prevent re-occurance

KFG and L&L Excavating have had an ongoing communication about the sewer project and have for the most part been able to avoid line breakage during this large job. KFG purchased this company after all of the lines were in the ground and they were not buried with tracer wire. It is an ongoing process finding lines and updating maps in our ARC GIS system.

Amount billed to excavator

\$0.00

CT Corporation System Register Agent 306 W Main Street, Suite 512 Frankfort, KENTUCKY 40601

*Honorable John N Hughes Attorney at Law 124 West Todd Street Frankfort, KENTUCKY 40601

*Kentucky Frontier Gas, LLC 4891 Independence Street, Suite 200 Wheat Ridge, CO 80033

*Kentucky Frontier Gas, LLC Kentucky Frontier Gas, LLC 4891 Independence Street, Suite 200 Wheat Ridge, CO 80033