

Subject: Case 2012-00362: City of Tompkinsville
From: Joseph Orazen (jorazen@yahoo.com)
To: jason.brangers@ky.gov;
Cc: shmartin1@bellsouth.net; reed@reedmoorelaw.com; jarmscityclerk@yahoo.com; mcphersonc93@yahoo.com;
Date: Tuesday, March 5, 2013 11:15 AM

RECEIVED
MAR 7 2013
PUBLIC SERVICE
COMMISSION

To:
Jason Brangers
Manager, Pipeline Safety Branch
Kentucky Public Service Commission

Jason, The Leakage Control Reports requested by Joel Grugen are being mailed to your office today. If they need to be sent anywhere else, please let me know. There will be more to follow.

Sincerely,

Joe Orazen
Operations Manager
Martin Contracting, Inc.
2371 Irvine Road
Richmond, KY 40475
606-305-6436



Page No. 1

Date 9-12

①

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 ③

TIME REPORTED _____

1 LEAK ONLY

**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

M. 15th Street, P. 12, #1119

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks Here we broke down the meter set, redoped the fittings & tested for leaks.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

Date 9-12

(2)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 (2) 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

Site in old site, old Henson Building

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	



LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks We found a tap on the risor here leaking. We replaced the risor at the Henson Building, feed off of the ^{new} plastic service line & ran it back to the secondary service.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

Date 9-11

(3)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 (3)

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

Meter # 3099763

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE	
High	
Intermediate	
Low	


LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks Found a leak at the bottom of the lock valve. We broke down the meter set and backed off the lock valve enough to redope the inlet side of the and retightened it. We put everything back together and retested for leaks



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

Date 9-17

(4)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 (3)

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

Metter # 1263937

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE	
High	
Intermediate	
Low	


LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We dug up the riser and replaced it to remove the dresser fitting. We then rebuilt the meter set.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1
Date 9-12

3

Status (Circle Status) Pos. Neg.
Leak Indication Classification (Circle Leak Indication)
1 2 3

TIME REPORTED _____
1 LEAK ONLY

Company _____ District _____
City Tompkinsville State Ky
Nearest Street Address _____

11031 Weisit, 4th St, Irmore

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere		
Bar Hole Test		
Man Hole		
Pit (Reg. or Meter)		
Valve Box		
Main Valve		
Curb Valve		
Meter Box		
Underground Fuel Tank		
Selected Test		

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION


Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	



LEAK INDICATION (Vegetation Only)

Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks A leak was found at the bottom of the regulator.
We broke down the meter set, redoped the regulator and
rebuilt the meter set. We then tested for leaks.

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

Date 9-12

⑥

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 ② 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

1102 West 4th Street

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Plt (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE	
High	
Intermediate	
Low	


LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks A leak was detected in the ground here. The leak expanded for a long way down the street. More information on the next report.



Page No. 1 ⑦
 Date 9-12
 Status (Circle Status) Pos. Neg.
 Leak Indication Classification (Circle Leak Indication)
 ① 2 3
 TIME REPORTED _____
 1 LEAK ONLY

**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Company _____ District _____
 City Tompkinsville State Ky
 Nearest Street Address _____

21012, West 14th St

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION


Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	



LEAK INDICATION (Vegetation Only)

Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks
 The leak here on 4th Street extended so far that we couldn't pinpoint the leak. The pipe was also in bad shape. We tied in at Main St. and put in new 3" PE all the way to Lake St & ran new services to each customer on the line.

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

Date 9-17

8

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 **3**

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State KY

Nearest Street Address _____

1, 0, 8, 2, and 5 ft.

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	



LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks On this service, the valve was locked off
it was leaking on the nut. When we checked
it, the nut was very loose. The fix was as
simple as tightening the valve nut.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Page No. 1
 Date 9-12 (9)
 Status (Circle Status) Pos. Neg.
 Leak Indication Classification (Circle Leak Indication)
 1 2 3
 TIME REPORTED _____
 1 LEAK ONLY


**LEAKAGE CONTROL REPORT
 FIELD SURVEY**

Company _____ District _____
 City Tompkinsville State Ky
 Nearest Street Address _____

11077 Daniel St.

TYPE OF GAS	LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	METHOD OF SURVEY	LEAK INDICATION APPEARS TO BE AT:
Natural	Atmosphere	Vegetation	Main
Manuf.	Bar Hole Test	Portable F I	Service
L.P.	Man Hole	Mobile F I	Service Tap
Other	Pit (Reg. or Meter)	Bar Hole	Main At Tie In
	Valve Box	Other	Drip
	Main Valve		Meter
	Curb Valve		Curb Valve
	Meter Box		Main Valve
	Underground Fuel Tank		Other
	Selected Test		

PIPE DESIGNATION	PRESSURE
Distribution	High
Transmission	Intermediate
Gathering	Low
Other	



CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)

Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	

Remarks The service here had repair fitting on the base of the riser covering a spot that had pitted out. We replaced the riser & rebuilt the entire meter set.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

Date 9-12

(10)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 (3)

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

1109 Supervisor Site

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	



LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks The leak was on the ~~st~~ inlet side of the lock valve. It didn't look to be in very good shape. We decided it would be best to replace the lock valve + rebuild the meter loop back.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

Date 9-17

(11)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

11015 Carmin Sit

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	



LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks The leak here was on the outlet side spud nut of the meter bar. We simply tightened the nut to fix it. We also discovered a leak on the inlet side of the regulator that is on the next report.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

Date 9-12

(12)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

11051 Clairmont St

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	


LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We had a leak on the inlet side of the regulator. We broke down the service & replaced the regulator. We then rebuilt the meter set, tested for leaks & turned the gas back on.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

(13)

Date 9-14

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 3

TIME REPORTED _____

1 LEAK ONLY

Company _____

District _____

City Tompkinsville

State KY

Nearest Street Address _____

21021 Joicekision St.

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)


Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks The lock valve on the service was leaking.
We broke down the service and backed off the lock valve,
We redoped it & threaded it back. We then rebuilt
the service & tested for leaks.



Page No. 1
 Date 9-12

14

Status (Circle Status) Pos. Neg.
 Leak Indication Classification (Circle Leak Indication)
 1 2 **3**

**LEAKAGE CONTROL REPORT
 FIELD SURVEY**

TIME REPORTED
 1 LEAK ONLY

Company _____ District _____
 City Tompkinsville State Ky
 Nearest Street Address _____

Birchington's Hardware Jacksonville St.

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere		
Bar Hole Test		
Man Hole		
Pit (Reg. or Meter)		
Valve Box		
Main Valve		
Curb Valve		
Meter Box		
Underground Fuel Tank		
Selected Test		

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION


Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	



LEAK INDICATION (Vegetation Only)

Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks We found a leak on the customers side of the service meter on the 1/4 x 2" reducer. We immediately notified the customer & showed him the problem. We went back to check it & found that the leak had been repaired.

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1

Date 9-12

(15)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tempkinsville State Ky

Nearest Street Address _____

Jaimie James, Bird and Service

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	



LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks We broke down the meter set, redoped the valve & rebuilt the meter set. We then tested for leaks & turned on the gas.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1
Date 9-12

(16)

Status (Circle Status) Pos. Neg.
Leak Indication Classification (Circle Leak Indication)
1 2 (3)

TIME REPORTED _____
1 LEAK ONLY

Company _____ District _____
City Tompkinsville State Ky
Nearest Street Address _____

Corner of Jackson & 3rd

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)		
Atmosphere		
Bar Hole Test		
Man Hole		
Pit (Reg. or Meter)		
Valve Box		
Main Valve		
Curb Valve		
Meter Box		
Underground Fuel Tank		
Selected Test		

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE	
High	
Intermediate	
Low	


LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST	
Positive	
Negative	


LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We detected a leak here. We tied in the new line on 4th St., and it appears it Migrated from that section. We are continuing to monitor the area.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 1
 Date 9-11 (17)
 Status (Circle Status) Pos. Neg.
 Leak Indication Classification (Circle Leak Indication)
 1 2 **3**
 TIME REPORTED _____
 1 LEAK ONLY

Company _____ District _____
 City Tompkinsville State Ky
 Nearest Street Address _____

Holmes join at the corner with Jackson + Bird

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)		
Atmosphere		
Bar Hole Test		
Man Hole		
Pit (Reg. or Meter)		
Valve Box		
Main Valve		
Curb Valve		
Meter Box		
Underground Fuel Tank		
Selected Test		

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	


LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We dug out the steel riser and replaced it with a new one. We then rebuilt the meter set. We then tested for leaks & returned gas to the service



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. _____
Date 9-18

18

Status (Circle Status) Pos. Neg.
Leak Indication Classification (Circle Leak Indication)
1 2 **3**

TIME REPORTED _____
1 LEAK ONLY

Company _____ District _____
City Tompkinsville State Ky
Nearest Street Address _____

307 Jackson St, Main Jackson St, Main Road

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	


LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We picked up a portion of Jackson St. with the new line we laid on 4th St. We dug down where the leak was detected & found that the line was laying on rock & had a hole rubbed in it. We temporarily put a repair clamp on it. When we tied Jackson St. in off of 4th St., we went past the leak & found where the original line ~~was~~ was up off the rock & made the tie in.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 2

Date 9-17

(19)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 (3)

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

31071 Jiaokhisoini Sit

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)		
Atmosphere		
Bar Hole Test		
Man Hole		
Pit (Reg. or Meter)		
Valve Box		
Main Valve		
Curb Valve		
Meter Box		
Underground Fuel Tank		
Selected Test		

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks Here, we replaced the lock valve because it was leaking through. We broke down the meter set, replaced the lock valve, & rebuilt the meter set. We then tested for leaks & returned services.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 2

(22)

Date 9-17

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 (2) 3

TIME REPORTED

1 LEAK ONLY

Company _____ District _____

City Tombkinsville State Ky

Nearest Street Address _____

Specialized Site Remediation Office

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE	
High	
Intermediate	
Low	


LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST	
Positive	
Negative	


LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We detected a leak here on the 2" main line. We began digging at the hottest point & followed the line ft. We found a total of 4 places in the line leaking. We put on repair clamps & fixed them.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 2

Date 9-17

(24)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 (3)

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

11016 Firrisite St

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY

Vegetation	
Portable FI	
Mobile FI	
Bar Hole	
Other	

PRESSURE

High	
Intermediate	
Low	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)


Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE


Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We had a leak in the ground on the service. We replaced the riser & rebuilt the meter set. We tested the service for leaks & relit the customer.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 2

25

Date 9-12

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)
1 2 3

TIME REPORTED
1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address

Intersection of 1st Street, Magnolia

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Plt (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE	
High	
Intermediate	
Low	


LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks Valve hadn't been greased & worked for a good while. We greased & worked it, & it seems to have solved the problem



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 2

Date 4-13

(24)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 **3**

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

Initiate resection of 4th & Main St.

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE	
High	
Intermediate	
Low	


LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST	
Positive	
Negative	


LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We greased & worked the valve, as well as replacing the line on 4th St to Lake St.



Page No. 2
 Date 9-13 (27)
 Status (Circle Status) Pos. Neg.
 Leak Indication Classification (Circle Leak Indication)
 1 2 3
 TIME REPORTED _____
 1 LEAK ONLY

**LEAKAGE CONTROL REPORT
 FIELD SURVEY**

Company _____ District _____
 City Tompkinsville State Ky
 Nearest Street Address _____

Initiate investigation of Main St. & Hwy 121/66

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)


Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE


Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks The valve on Main St. was greased & worked.
We also replaced the valve on KY Avenue due to
a leak on it. After working the valve on
Main St, we have detected no gas present.
Monitoring will continue.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 2 (29) (30)
 Date 9-13
 Status (Circle Status) Pos. Neg.
 Leak Indication Classification (Circle Leak Indication)
 1 2 3
 TIME REPORTED _____
 1 LEAK ONLY

Company _____ District _____
 City Tompkinsville State Ky
 Nearest Street Address _____

51031 Main St

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	



METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	



LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks We had 2 leaks at this service. One in the ground by the water meter & One on a repair clamp on the riser. We dug out the riser & found a bad spot on the service as well. We replaced the bad section as well as the riser. We rebuilt the meter set & tested for leaks.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 2

Date 9-13

(31)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

① 2 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville § State Ky

Nearest Street Address

McDonald's, Main St.

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	



LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	


Main Street Man hole



LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks We picked up a trace of gas here in the manhole for the sewer system. We immediately vented the man hole. The gas disapated fairly quickly. The man hole isn't far from the leak that was found on the 2" valve at the intersection of Hwy 166 + Main St. After making repairs there, the problem has been resolved. We are continuing monitoring.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. _____

Date 9-13

32

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 **3**

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

5115 Main St

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)		
Atmosphere		
Bar Hole Test		
Man Hole		
Pit (Reg. or Meter)		
Valve Box		
Main Valve		
Curb Valve		
Meter Box		
Underground Fuel Tank		
Selected Test		

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE	
High	
Intermediate	
Low	


LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks The lock valve on the service was leaking on the Inlet side. We redoped the lock valve & rebuilt the meter set. We tested for leaks & resolved the problem.



Page No. 3

Date 9-13

34

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 **3**

TIME REPORTED _____

1 LEAK ONLY

**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

Dir. Blair's Office, Main St.

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere		
Bar Hole Test		
Man Hole		
Pit (Reg. or Meter)		
Valve Box		
Main Valve		
Curb Valve		
Meter Box		
Underground Fuel Tank		
Selected Test		

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)

Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	


COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	

.....


↑
N
↓

.....



Remarks We had a leak on a 1x3/4 reducer on this service.

We put in new parts including the regulator starting at the lock valve. This removed the 1x3/4 reducer preventing any future problems.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 4

Date 10-16

(32)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 (3)

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

Initiative circuit, join 10 ft, 4th & Magnolia

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere		
Bar Hole Test		
Man Hole		
Pit (Reg. or Meter)		
Valve Box		
Main Valve		
Curb Valve		
Meter Box		
Underground Fuel Tank		
Selected Test		

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)


Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	


COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks

Gas traces were detected in the valve box, possibly on the valve. We greased & worked the valve, & so far it seems to have resolved the problem. It appears that several main line valves here in town have not been greased or worked for a long time. We went through the system & worked every valve that we knew of.



Page No. 4

Date 10-16

39

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 3

TIME REPORTED _____

1 LEAK ONLY

**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Company _____ District _____

City Tombkinsville State Ky

Nearest Street Address

104 North Magnolia

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable FI	
Mobile FI	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	


PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	




LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	



LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks 104 N. Magnolia was scheduled to be tore down to build an addition on to the service station at the corner of 4th and Magnolia. We dug out the leak location & found a place on the main leaking. We repaired it using a repair clamp. We then tied into the old service & rerouted it to allow for demolition.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Page No. 4

Date 10-16

(40)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 (3)

TIME REPORTED _____

1 LEAK ONLY

**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

41151 Cirrawford Rd Sit

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE

High	
Intermediate	
Low	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)


Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks

The lock valve was leaking on the inlet side of the service. It was in bad condition, so we replaced it. We then rebuilt the service using new parts, tested for leaks, & relit the customer



Page No. 2

Date 10-16

(41)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)
1 2 ③

TIME REPORTED _____

1 LEAK ONLY

**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

Circuit field, 15th, Mainline Gas Trail

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)		
Atmosphere		
Bar Hole Test		
Man Hole		
Pit (Reg. or Meter)		
Valve Box		
Main Valve		
Curb Valve		
Meter Box		
Underground Fuel Tank		
Selected Test		

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We had a leak on the lock valve & on the regulator at the service. We replaced the riser due to corrosion & rebuilt the meter set using new parts. We then tested for leaks & relit. the customer



Page No. 4
 Date 10-16

42

Status (Circle Status) Pos. Neg.
 Leak Indication Classification (Circle Leak Indication)
 ① 2 3

**LEAKAGE CONTROL REPORT
 FIELD SURVEY**

TIME REPORTED _____
 1 LEAK ONLY

Company _____ District _____
 City Tompkinsville State Ky
 Nearest Street Address _____

21021 Cirrawfield T Tompkinsville, Dirvigi Stone

TYPE OF GAS	
Natural	<input type="checkbox"/>
Manuf.	<input type="checkbox"/>
L.P.	<input type="checkbox"/>
Other	<input type="checkbox"/>

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	<input type="checkbox"/>
Bar Hole Test	<input type="checkbox"/>
Man Hole	<input type="checkbox"/>
Pit (Reg. or Meter)	<input type="checkbox"/>
Valve Box	<input type="checkbox"/>
Main Valve	<input type="checkbox"/>
Curb Valve	<input type="checkbox"/>
Meter Box	<input type="checkbox"/>
Underground Fuel Tank	<input type="checkbox"/>
Selected Test	<input type="checkbox"/>

METHOD OF SURVEY	
Vegetation	<input type="checkbox"/>
Portable F I	<input type="checkbox"/>
Mobile F I	<input type="checkbox"/>
Bar Hole	<input type="checkbox"/>
Other	<input type="checkbox"/>

LEAK INDICATION APPEARS TO BE AT:	
Main	<input type="checkbox"/>
Service	<input type="checkbox"/>
Service Tap	<input type="checkbox"/>
Main At Tie In	<input type="checkbox"/>
Drip	<input type="checkbox"/>
Meter	<input type="checkbox"/>
Curb Valve	<input type="checkbox"/>
Main Valve	<input type="checkbox"/>
Other	<input type="checkbox"/>

PIPE DESIGNATION	
Distribution	<input type="checkbox"/>
Transmission	<input type="checkbox"/>
Gathering	<input type="checkbox"/>
Other	<input type="checkbox"/>


PRESSURE	
High	<input type="checkbox"/>
Intermediate	<input type="checkbox"/>
Low	<input type="checkbox"/>

CGI TEST	
Positive	<input type="checkbox"/>
Negative	<input type="checkbox"/>


LEAK INDICATION (Vegetation Only)	
Trees	<input type="checkbox"/>
Shrubs	<input type="checkbox"/>
Grass	<input type="checkbox"/>
Lawn	<input type="checkbox"/>
Weeds	<input type="checkbox"/>
Odor	<input type="checkbox"/>
Other	<input type="checkbox"/>

LOCATION OF PIPE	
Street	<input type="checkbox"/>
Between St. & Sidewalk	<input type="checkbox"/>
Under Sidewalk	<input type="checkbox"/>
Lawn	<input type="checkbox"/>
Easement	<input type="checkbox"/>
R.O.W.	<input type="checkbox"/>
Other	<input type="checkbox"/>

COVER	
Concrete	<input type="checkbox"/>
Asphalt	<input type="checkbox"/>
Brick	<input type="checkbox"/>
Gravel	<input type="checkbox"/>
Soil	<input type="checkbox"/>
Other	<input type="checkbox"/>



Remarks The leak here extended a good distance. We dug down in several places & the pipe was in bad shape. We found one place that had been hacked with a backhoe or trucker bucket & damaged. It wasn't leaking, but was mashed & pulled up. We replaced the entire section with 2" PE & tied in all services.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 4

Date 10-16

43

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)
1 2 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address

1125 Crawford St.

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	


LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks There was a leak on the lock valve at this service. We replaced the lock valve + installed a new regulator + meter. We replumbed + tested for leaks.



Page No. 4
 Date 10-16-

44

Status (Circle Status) Pos. Neg.
 Leak Indication Classification (Circle Leak Indication)
 1 2 ③

**LEAKAGE CONTROL REPORT
 FIELD SURVEY**

TIME REPORTED _____
 1 LEAK ONLY

Company _____ District _____
 City Tompkinsville State Ky
 Nearest Street Address _____

Jamie Haynes Crawford St

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)


Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks We had a leak on the lock valve at this address.
We replaced the faulty lock valve & replumbed the meter
back. We then tested the set for leaks & relit the
customer.



Page No. 4

Date 10-17

(47)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)
 1 2 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tombkinsville State Ky

Nearest Street Address _____

Proffitt, Reality, and St.

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	




LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks We had gas present in a wide area here. Proffitt Reality building had gas present inside the building. The were asked to leave for the day until we could repair the problem. We started digging up the main & found 5 separate leaks in a 200' section of the main. We put repair clamps on the bad places to temporarily fix it. We plan to put in new line as soon as possible to discontinue use of the bad line.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 4

Date 10-17

42

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 **3**

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address _____

21016 Sciotech Magnolia

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks
Installed New Riser, Lock Valve, 4" by 3/4" nipple
Sweeping 90° - New meter Box - meter - 4" nipple
3" nipple and 90° basically rebuilt whole meter set.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 4

Date 10-17

49

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky
Nearest Street Address _____

51011th Magnolia Ln, E.M.C. 6110111

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	



LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks We had a leak on the lock valve at the service We broke down the meter redoped the lock valve & replumbed the meter set. We tested for leaks & relit the customer.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Page No. 4

Date 10-17

(50)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)
1 2 3

TIME REPORTED _____

1 LEAK ONLY

**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Company _____ District _____

City Tombkinsville State Ky

Nearest Street Address _____

3011 South Magnolia

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere	
Bar Hole Test	
Man Hole	
Plt (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

PRESSURE

High	
Intermediate	
Low	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)


Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks

Broke Down and Replaced New Lock Valve - Redaped and assembled.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 5

Date 10 17

(52)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 (2) 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address

303 1/2 South Magnolia

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)


Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks put in new valve, broke down and redoped
Fittings - Locked off gas not inuse - NO
meter.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 5

Date 10-17

53

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)

1 2 3

TIME REPORTED _____

1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky

Nearest Street Address

Sittlerdies, Trailoria Park, South Magnolia

TYPE OF GAS

Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)

Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY

Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:

Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION

Distribution	
Transmission	
Gathering	
Other	

PRESSURE

High	
Intermediate	
Low	

CGI TEST

Positive	
Negative	

LEAK INDICATION (Vegetation Only)


Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE

Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER

Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks The regulator on this service was broke. It
looked like it had been hit by a lawn mower or something,
We replaced it & tested for leaks.



**LEAKAGE CONTROL REPORT
FIELD SURVEY**

Page No. 5

Date 10-17

(53)

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)
1 2 (3)

TIME REPORTED
1 LEAK ONLY

Company _____ District _____

City Tompkinsville State Ky
Nearest Street Address _____

Stavie A. Lat, Sivuti, Mann

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	


METHOD OF SURVEY	
Vegetation	
Portable F I	
Mobile F I	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	

PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	




LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

Remarks We had a leak on the lock valve at the meter set. We broke the set down & replaced lock valve and added a new 3" x 3/4 nipple.

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Page No. 5
 Date 10-17

56

Status (Circle Status) Pos. Neg.
 Leak Indication Classification (Circle Leak Indication)
 ① 2 3

**LEAKAGE CONTROL REPORT
 FIELD SURVEY**

TIME REPORTED _____
 1 LEAK ONLY

Company _____ District _____
 City Tombkinsville State Ky
 Nearest Street Address _____

Examined and failed on West Side

TYPE OF GAS	
Natural	
Manuf.	
L.P.	
Other	

LEAK INDICATION FIRST DETECTED (AT) (IN) (BY)	
Atmosphere	
Bar Hole Test	
Man Hole	
Pit (Reg. or Meter)	
Valve Box	
Main Valve	
Curb Valve	
Meter Box	
Underground Fuel Tank	
Selected Test	

METHOD OF SURVEY	
Vegetation	
Portable FI	
Mobile FI	
Bar Hole	
Other	

LEAK INDICATION APPEARS TO BE AT:	
Main	
Service	
Service Tap	
Main At Tie In	
Drip	
Meter	
Curb Valve	
Main Valve	
Other	

PIPE DESIGNATION	
Distribution	
Transmission	
Gathering	
Other	


PRESSURE	
High	
Intermediate	
Low	

CGI TEST	
Positive	
Negative	

LEAK INDICATION (Vegetation Only)	
Trees	
Shrubs	
Grass	
Lawn	
Weeds	
Odor	
Other	

LOCATION OF PIPE	
Street	
Between St. & Sidewalk	
Under Sidewalk	
Lawn	
Easement	
R.O.W.	
Other	

COVER	
Concrete	
Asphalt	
Brick	
Gravel	
Soil	
Other	



Remarks This service wasn't leaking, but on the downstream side of the meter we found a 1/2" P.E. line above ground tied into the meter going to the store. We turned off the gas & informed the customer that they had to pipe the gas into the building using steel.