

EAST KENTUCKY NETWORK
101 TECHNOLOGY TRAIL
IVEL, KY 41642
PHONE: (606) 874-7550
FAX: (606) 874-7551
EMAIL: INFO@EKN.COM
WEBSITE: WWW.EKN.COM

EAST KENTUCKY
NETWORK



RECEIVED

FEB - 3 2014

**PUBLIC SERVICE
COMMISSION**

January 29, 2014

Linda Faulkner, Division Director Filings
Public Service Commission
211 Sower Blvd.
P.O. Box 615
Frankfort, KY 40602-0615

RE: Public Service Commission of Kentucky (Case No. 2013-00369)

Dear Ms. Faulkner:

Please find enclosed the approval letter from the FAA for the Harlan HS Tower (Case No. 2013-00369).

If you have any questions, feel free to contact me at 606-477-2355, ext. 1007 or via email lhane@ekn.com.

Sincerely,

A handwritten signature in cursive script that reads "Lynn Haney". The signature is written in black ink and is positioned above the typed name and title.

Lynn Haney
Compliance Coordinator

Enclosure



Mail Processing Center
 Federal Aviation Administration
 Southwest Regional Office
 Obstruction Evaluation Group
 2601 Meacham Boulevard
 Fort Worth, TX 76193

Aeronautical Study No.
 2013-ASO-10475-OE

Issued Date: 12/18/2013

Ali Kuzehkanani
 East Kentucky Network, LLC
 8300 Greensboro Drive, Suite 1200
 McLean, VA 22102

**** DETERMINATION OF NO HAZARD TO AIR NAVIGATION ****

The Federal Aviation Administration has conducted an aeronautical study under the provisions of 49 U.S.C., Section 44718 and if applicable Title 14 of the Code of Federal Regulations, part 77, concerning:

Structure: Antenna Tower Harlan HS
 Location: Harlan, KY
 Latitude: 36-53-43.14N NAD 83
 Longitude: 83-16-33.26W
 Heights: 1568 feet site elevation (SE)
 190 feet above ground level (AGL)
 1758 feet above mean sea level (AMSL)

This aeronautical study revealed that the structure does not exceed obstruction standards and would not be a hazard to air navigation provided the following condition(s), if any, is(are) met:

It is required that FAA Form 7460-2, Notice of Actual Construction or Alteration, be e-filed any time the project is abandoned or:

- At least 10 days prior to start of construction (7460-2, Part I)
- Within 5 days after the construction reaches its greatest height (7460-2, Part II)

Based on this evaluation, marking and lighting are not necessary for aviation safety. However, if marking/lighting are accomplished on a voluntary basis, we recommend it be installed and maintained in accordance with FAA Advisory circular 70/7460-1 K Change 2.

This determination expires on 06/18/2015 unless:

- (a) the construction is started (not necessarily completed) and FAA Form 7460-2, Notice of Actual Construction or Alteration, is received by this office.
- (b) extended, revised, or terminated by the issuing office.
- (c) the construction is subject to the licensing authority of the Federal Communications Commission (FCC) and an application for a construction permit has been filed, as required by the FCC, within 6 months of the date of this determination. In such case, the determination expires on the date prescribed by the FCC for completion of construction, or the date the FCC denies the application.

NOTE: REQUEST FOR EXTENSION OF THE EFFECTIVE PERIOD OF THIS DETERMINATION MUST BE E-FILED AT LEAST 15 DAYS PRIOR TO THE EXPIRATION DATE. AFTER RE-EVALUATION OF CURRENT OPERATIONS IN THE AREA OF THE STRUCTURE TO DETERMINE THAT NO SIGNIFICANT AERONAUTICAL CHANGES HAVE OCCURRED, YOUR DETERMINATION MAY BE ELIGIBLE FOR ONE EXTENSION OF THE EFFECTIVE PERIOD.

This determination is based, in part, on the foregoing description which includes specific coordinates , heights, frequency(ies) and power . Any changes in coordinates , heights, and frequencies or use of greater power will void this determination. Any future construction or alteration , including increase to heights, power, or the addition of other transmitters, requires separate notice to the FAA.

This determination does include temporary construction equipment such as cranes, derricks, etc., which may be used during actual construction of the structure. However, this equipment shall not exceed the overall heights as indicated above. Equipment which has a height greater than the studied structure requires separate notice to the FAA.

This determination concerns the effect of this structure on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

A copy of this determination will be forwarded to the Federal Communications Commission (FCC) because the structure is subject to their licensing authority.

If we can be of further assistance, please contact our office at (817) 321-7755. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2013-ASO-10475-OE.

Signature Control No: 201247705-203958694

(DNE)

Debbie Cardenas
Technician

Attachment(s)
Frequency Data

cc: FCC

Frequency Data for ASN 2013-ASO-10475-OE

| LOW FREQUENCY | HIGH FREQUENCY | FREQUENCY UNIT | ERP | ERP UNIT |
|--------------------------|---------------------------|---------------------------|------------|---------------------|
| 698 | 806 | MHz | 1000 | W |
| 806 | 824 | MHz | 500 | W |
| 824 | 849 | MHz | 500 | W |
| 851 | 866 | MHz | 500 | W |
| 869 | 894 | MHz | 500 | W |
| 896 | 901 | MHz | 500 | W |
| 901 | 902 | MHz | 7 | W |
| 930 | 931 | MHz | 3500 | W |
| 931 | 932 | MHz | 3500 | W |
| 932 | 932.5 | MHz | 17 | dBW |
| 935 | 940 | MHz | 1000 | W |
| 940 | 941 | MHz | 3500 | W |
| 1850 | 1910 | MHz | 1640 | W |
| 1930 | 1990 | MHz | 1640 | W |
| 2305 | 2310 | MHz | 2000 | W |
| 2345 | 2360 | MHz | 2000 | W |