Kentucky 811 < tickets@kentucky811.org>

6/1/2021 7:45 PM

## KUPI 0032 2021/06/01 #00004 2106012131-00A EMER NEW

Emergency: Y

To drakesboro@comcast.net

0032 00004 KUPIa 06/01/2021 20:45:15 2106012131-00A EMER NEW GRID

**EMERGENCY SEE REMARKS** 

Ticket: 2106012131 Date: 06/01/2021 Time: 20:45 Oper: KENTUCKY811 Chan:000

State: KY Cnty: MUHLENBERG City: BEECHMONT

Subdivision:

Address: 3959 Street: US RT 431 S Cross 1: ARNOLD DR

Location: LOCATE FRONT OF PROPERTY AND BOTH SIDES OF THE STREET

Boundary: n 37.166361 s 37.163831 w -87.034128 e -87.032589

Work type: REPAIR GAS MAIN Done for: CITY OF DRAKESBORO

Start date: 06/01/2021 Time: 20:28 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: NO

Duration: N/A Depth: 6 FT

Company: MARTIN CONTRACTING Type: OTHR

Co addr:

City: RICHMOND State: KY

Caller: CURTIS SPURLIN Phone: (270)476-8986 Contact: MARTIN CONTRACTING - OFFICE Phone:

Mobile: (859)623-0112

Email: <u>DRAKESBORO@COMCAST.NET</u>

Remarks: CREW EN ROUTE

Submitted date: 06/01/2021 Time: 20:45

Members: 0032 0139

AREA MARKED WITH PAINT
BALLED
6/2/21



### **Ticket Status Notification**

To:

MARTIN CONTRACTING

Email: DRAKESBORO@COMCAST.NET

Below lists utilities that were statused by USIC. Please note there may be other Utilities which include private facilities that may be present in the work area and are NOT the responsibility of USIC to locate or mark.

You are receiving this notification because your contact information is listed on the above ticket from the One Call System. If you have any guestions regarding this notification, please contact USIC at 1-800-762-0592.

**Ticket** 

**Address** 

2106012131

3959 US RT 431 S, BEECHMONT, KY

**Utility** AT&T

Locate Date /

Status

**Detail** 

06/2/21 07:06 AM

Not Marked

**Excavation Onsite Clear** 

Stay Up-to-Date with Real-Time Access to USIC's assigned Tickets through our DigCheck Pro App. You will have the flexibility to see Open and Closed Tickets, Post Locate Photos, and Street Views! There is no cost to access our DigCheck Pro App.

Sign up by emaling

DigCheck@usicllc.com

and provide your

First Name: Last Name: Company Name: Email Address: State or States: Phone Number:

You can download DigCheck Pro from Apple App Store or Google Play Store Now!



Questions or Comments:

DigCheck@usicllc.com

It's Free!



#### Kentucky 811 <tickets@kentucky811.org>

6/1/2021 7:46 PM

## KUPI CONFRM 2021/06/01 #00000 2106012131-00A EMER NEW

To drakesboro@comcast.net

00000 KUPIa 06/01/2021 20:46:50 2106012131-00A EMER NEW GRID

EMERGENCY SEE REMARKS

Ticket: 2106012131 Date: 06/01/2021 Time: 20:45 Oper: KENTUCKY811 Chan:000

State: KY Cnty: MUHLENBERG City: BEECHMONT

Subdivision:

Address: 3959

Street : US RT 431 S Cross 1 : ARNOLD DR

Location: LOCATE FRONT OF PROPERTY AND BOTH SIDES OF THE STREET

:

Boundary: n 37.166361 s 37.163831 w -87.034128 e -87.032589

Work type : REPAIR GAS MAIN
Done for : CITY OF DRAKESBORO

Start date: 06/01/2021 Time: 20:28 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: NO Emergency: Y

Duration : N/A Depth: 6 FT

Company: MARTIN CONTRACTING Type: OTHR

Co addr :

City : RICHMOND State: KY

Caller : CURTIS SPURLIN Phone: (270)476-8986 Contact : MARTIN CONTRACTING - OFFICE Phone:

Mobile : (859)623-0112

Email : DRAKESBORO@COMCAST.NET

Remarks : CREW EN ROUTE

Submitted date: 06/01/2021 Time: 20:45

Utilities notified:

AT&T DISTRIBUTION
CITY OF DRAKESBORO

COMMUNICATIONS
GAS, SEWER, WATER

!!!!==== For information regarding this request, please visit <a href="https://kentucky811.org/public/">https://kentucky811.org/public/</a> ====!!!!

		Gas	Pip	eline Inspection	
Address 3	3954 Hora	431 Beechmo	_	Location:	
	aterial	Pipe Condition	<u> </u>	Visual/Pitting	Costing
Steel	1 1 1 1	Excellent		Localized Localized	Coating Millwrap
PE		Good		General	Enamel
Cast Iron	104	Slight Pitting		Other	Roskete
CSST		Extreme Pitting		Fitting Depth	Oridemp
Vlain	<del></del>	Hole/Voids		realing Depen	Xtracoat
Service	V	graphitization			Mastic
Other		Bent	V		Cold Roll
			i v		Hot Wrap
		Other			Heat Shrink
Affected P	ipe Condition	Soil Type		Soil Condition	Work Performed
Good		Rock		Dry	Main Ext.
Poor		Cinder		Wet/Swampy	Service Tap
Damaged	V	Clay	/	Normal	Leak Repair
Other		Loam		Moister Range (3-5)	Re-routing
		Sand		Moister Range(5-8)	Third Party
		Alluvion			Abandonment
		Other			Deactivation
					Utility Theft
l	Discriptio				Other Comments
		V	'isua	l Discription	
			Lack	' Value	
1 Serv	rice Line	153' TREPIA	C+5	Riseripe of Aire	
	lasvin &				

			1		1	T										-			, ·	-	7	7	-		作品		1		T		1
N6. 0034	State A/	Date (6-2-1	Grade 3	Thetide	2 spirano.	William Control of the	100 a.			H.S.	C ni	000	Flantaching Annual Top 4 M		#3 Regulator	* #6 Inlet Cap/Swivel	#9 Fuel Line Pitting	#12 Fuel Line	WKATHER	Clear	Wet	Hot (85-100)	Cold (0-40)		Resear Dank	Bare	Coated	ired: 62-21	ecked:		12-2-
Date Installed			Grade 2						Zn 00		K	1			#2 HP Cock	#5 Inlet Loop	#8 Outlet Loop	ифек	Size	.5-2.0	2.0-3.0	3.0-4.0	6.0-8.0	10.2-12.0		/ I-S	5-Greator	Date Repaired:	Date Rechecked		e: (
10	8						-	) 				V	V		12 H	5 Inle	Outl	#11 Index		7			$\dashv$			7				-	Date:
	ras burg		Grade 1				,	Ti-	9	h-	î	n n	ũ.						Fig. 19 PPP	Steel	PE	Cast Iron	CSST	PVCB							
33	hil				2 - M									(	#1 Riser	Coc	wS/di	s Me	1	7					X Dr.			_			
	MU			51806 314		10 M						•			(F)	#4 LP Cock	#7 Out Cap/Swivel	#10 Gas Meter	i de la companya de l	Grass	Dirt	Asphalt	Concrete	Sidewalk	The state of the s	Residential	Rural	Commercial	Industrial		
										•																J					
Dakikas	Clty/County	Jano	-row																		(1-30)	(31-60	(61-99.9)	(100-399)			uo	e Iron	J		
	Ö			9															g							Steel	Cast Iron	Ductile Iron	Copper	Plastic	
Photos #	(	2	25	)			1.4 )												College	%Gas		Ţ	×						>		
34.5	Prop	ليا	4/													8				%	LEL	UBL	PPM	_	4						
52:1:12	Beechmons	4 Trailer YRAN																		Rock	Cinder	Clay 6	Loam	Sand		Transmission	Main	Service	Meter Set	Customer Pipe	h
7	431	X	017	5																	7			9	74 / A	7	7			7	Jan 1
1 1	Huy	7,000 K	100	1444															10 12 12	Main	Service	Tap	Valve	Meter					Jr.	nection	3 /4
Cakesher	43.68	00.7	- 3	ġ (	11.Sel	•														Inside Bldg	Outside Bldg	Manhole	Undergrnd	Atmosphere		Pype	Valve	Fitting	Regulator	Tap Connection	XV pro
	117	100		) L	N.															됩	Ō	7	Ď	¥	57 20 20 20 20 20 20 20 20 20 20 20 20 20						
		7	4	Meter St. Bearing	The K								37	٠.						Mobile Fi	Flame Pack	Visual	CCGI/EGD	Smell		Corrosion	Outside Force	Const/Defect	Material Defect	Other	Signature:

Gas Service Work Order Work Type:	
ocation/Address: 3954 Hwy 431 Beech mon T. Facility Classification: Distribution	
eak Information	
Pate Discovered: 6-1-21 How Discovered: Reported To:	
eak Grade: CGI Used? Percentage of Gas(%Gas in Air): Graded By:	
Pescription of Leak: Pickup Truck And Trailor RAN over GAS Meter	
ause of Leak: <u>Corrosion</u> Incorrect-Operations Other Outside Force	
Atmospheric Human Error External Loading External Ineffective Procedures Fire/Explosion Information of Excavator	
Internal   Vandalism   Vehicle   Other	
Natural Forces Equipment Failure Material and Welds Was 811 Called: UES	
Earthquake Excess Flow Valve Flange Earth/Rock Movement Filter Mechanical Fitting Explain Other	
Flood   Flow/Pressure Controller   Pipe   Pips   Plastic Fusion Coupling   Plastic Fusion Coupling   Plastic Fusion Coupling   Plastic Fusion Floor Flor Fl	
Landslide Regulator/Relief Valve Plastic Dresser Lightning Threads Plastic to Steel Transition	
Tornado Valve Screw Fitting Washout Other Tap Tee	
Other Workmanship Defect Other .	
ipe Information	
ipe Size: 1 11 Pipe Material: 5+-4   Coating: Mill WAP Pipe Condition: Bro How EFV	
orrosion Information	
athodic Protection: Pipe to Soil Reading: Wall Thickness: Coupons Taken:	
xternal Condition: Pit Depth: Internal Condition: Pit Depth: IN	
nodes Installed: Anode type: Repair Coating 1: Repair Coating 2:	
epth of Cover: Feet 2 Inches Soil Condition: Moisture: Soil Packing:	
epair Information	
epair Method: Date Repaired: 6-7-21 Repaired By: MAR fin Contacting	
escription of Repair: Weld A NEW Riser into Places And HAND BUITThe New Motes Lo	ef
est Information	
ength of Pipe Test Type: Test Medium: X-Ray(STEEL):	
est Start Date/Time: Pressure at Start: Pressure Loss: Operating Pressure:	
est End Date/Time: Pressure at End: Ibs Amount of Loss Ibs	
eason for Loss: Corrections Made:	
ther	
ther Information:	
Cleared By:	

Page 1

Run Date: 6/01/2021 22:24:26

Incident Number: 2019189842

**Incident Type:** 

**NORMAL** 

**Priority:** 

IC Number:

21-0000017975

**Details** 

**Received Date** 

Dispatched

Complaint:

Received By **SMATHENY** 

6/1/2021 18:13:58

6/1/2021 20:27:11

**GAS LEAK** 

**GAS LEAK** 

Comment

ACROSS FROM THIS LOCATION A VEH HIT A METER, SEVERE GAS LEAK

Disposition

CALL COMPLETED

Location

ALI ESN:

Call ESN: 235

**ALI Address:** 

Location Address: 3959 U S HIGHWAY 431 S, BEECHMONT

**ALI Phone:** 

Location Phone: 270-792-4475

**GIS Address:** 

Landmark::

**ALI Caller:** 

Latitude:

Longitude:

Caller

**Location Caller:** 

1503

CLINIC PHARMACY (BEECHMONT)/STEVE FARRIS

**Raw ALI Feed** 

**Dispatched Units** 

MCSO

**Case Number:** 

**Status EN ROUTE** ON SCENE

CLEARED

Set Date/Time 6/1/2021 20:27:11 6/1/2021 20:34:05

6/1/2021 20:34:08

0.00 0.00 0.00

Odometer Comments

Set By **CSMITH** 

**SMATHENY SMATHENY** 

**Incident Narrative** 

**SMATHENY** 

6/1/2021 18:20:56

**NEG CONTACT MIKE JONES** 

**CSMITH** 

6/1/2021 19:02:41

CURTIS WITH CITY OF DRAKESBORO ADVISED GAS IS CAPPED OFF AND 10-4

ATTHIS TIME

**SMATHENY** 

6/1/2021 20:23:45

675MPF NOTIFY OWNER TO MOVE VEH

Complainants

**Vehicles** 

Make: CHEV

Model: EQU

Style:

Color: SIL

Year: 2012

Tag Number:

675MPF

Tag State: KY

Model: 2GNFLGEK7C6128307

Comments:

JENKINS, ALLIE D / JENKINS, LEE MICHAEL // EXP 12-31-2021

109 CARDINAL DR, CENTRAL CITY KY 42330

Wreckers

**Wrecker Company** 

Service Area

Caller Requested Responded

Call Date/Time

NO

NO

### Run Date: 6/01/2021 22:24:26

### Did Not Respond Reason:

#### Comments:

Radio Communi	cations					
MCSO-1503	6/1/2021 20	:27:11	<b>EN ROUTE</b>			CSMITH
MCSO-1503	6/1/2021 20	:34:05	ON SCENE			SMATHENY
MCSO-1503	6/1/2021 20	:34:08	CLEARED			SMATHENY
Incident Status I	Log		T. S. S. P. Addies			
ACTIVE	SMATHENY	6/1/20	21 18:13:58	56		
CLOSED	SMATHENY	6/1/20	21 19:10:16	0	CALL COMPLETED -	
REACTIVATED	SMATHENY	6/1/20	21 20:20:30	70		
CLOSED	SMATHENY	6/1/20	21 21:30:44	0	CALL COMPLETED -	
<b>Complaint Code</b>	Change Log					
GAS LEAK			06/01/20	21 18:14:45	SMATHENY	

#### Page 1 of 4

## **UTILITY STRIKE INVESTIGATION**

## **GENERAL INFORMATION**

Date of strike (MM/DD/YY): 06-01-2021 Time of strike (24-hour clock): 18:01
Date of report (MM/DD/YY):
Foreman's Name: Mike Jones Project Manager:
Employee who struck Utility: Spotter:
Address of Utility Strike: 3959 US Hwy 4315. Beechmont, KY
Access from Chric Pharmacy South
Utility Owner: Nockes or 6A5 Prime Contractor:
Witness name/s: <u>276 792 4475</u> Contact Phone #'s: <u>270 793 4475</u>
Type of work being performed: ☐ Water ☐ Sewer ☐ Natural Gas
Utility Damaged: ☐ Natural Gas ☐ Telephone ☐ Water ☐ Electrical ☐ Fiber ☐ Internet ☐ Sewer
Describe in detail: 125 psi StEEL   " (Material Type/Pressure/Size) Example: Poly-Service / 60 PSI / 1 Inch
Location of Utility:   Underground   Aerial   Above ground
Valid 811 locates called in? ☐ Yes ☑ No 811 Ticket Number:
Distance to nearest mark on ground: 45' to White Pole on South Bound CV.
Was the utility active?   ✓ Yes □ No Name of person stating it is inactive:
What damaged the utility? Vehicle Pulling A Utility Trailer, Trailer, Trailer, Trailer, Trailer, Trailer, Bore)  Depth of Utility? FT
Customers/Houses that are out of service?  1) One Customer - Utility Trailer HH his meter that are out of service?
Length of interrupted service: 500 feet from Weter to Rasidance
Type of Mark: ☐ Marked ☐ Un-Marked ☐ Mis-Marked
How was it Marked? //A (Paint, Flag, Stake, Other)

## UTILITY STRIKE INVESTIGATION

## **Personnel Information**

Note: Fill out when any persons arrive on site and when they leave. Including first responders.

Personnel Name	Company Name	Job Title	Arrival Time	Departure Time
Mike Jones	Drakesboro gas	Worker	18:15	19:01
	former Drallesboro gos	Worker	18:15	19:01
Crutis Spurlin	Drakesburg gas	worker	18:20	19:01
Timmothy Keith	Drakisboro gas	Worker	18:20	23:30
Brian Alland	Dralysboro gas	worker	6:25	19:01
•				
		ı.		

## **Equipment Used:**

Equipment Type	Company Name	Was it used?	Arrival Time	Departure Time
,		Yes / No		
		Yes / No		
		Yes / No		
		Yes / No		

### **Materials Used**

Type of Repair	Company making repair	Material used (Conduit / Steel)	Length	Diameter
Compression filling Sthat off Valvo, Plug	Cuty of Drahusbaro	Stee	N/A	1 **

# **Incident Statement Form**

Date of Incident	06/01/2021	Time of Incident	Gas Metar S	strike
Date of Report	06 02 12021	Time of Report	19:10	
Name	Mike Jones	Phone Number	(270) 476-898	6
Occupation/Title	Mayor   Gas operator	>		
Location of Inciden	t: 3959 US Highwa	ay 4315	s. Beechmon	t
Brief description of  Arrived  Motorist st  A drive	fyour activity during incident:  on scene to find Mades his trailer hit go	leter broke as meter	e off riser. As he pull	ed into
	J			
Statement describin	g incident in detail: (If more room is nee	ded, use back of sh	eet)	
Motor	hit gas meter a	with his	letility Tre	Ailer
While	pulling into a dri	Veway.	The state of the s	
***************************************	•			
				***************************************
Andreas & Allegan Control of the Con				
	· · · · · · · · · · · · · · · · · · ·			
**************************************		31		
I HAVE READ ABOVE	AND IT IS TRUE TO THE BEST OF MY KN	OWLEDGE.		
Signature:	Attaka Jame	Date:	<i>06/02/2021</i> Time:	09:30
Investigator Signatu	ure: Milla Jourse	Date:	Time:	