

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: RT 474 - GRASSY creek  
DATE: 1-7-20 TIME OF INTERRUPTION: FROM 1:00 TO 2:00  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 25  
CAUSE OF INTERRUPTION: 3" Bell  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.46  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST.....	\$ _____
EQUIPMENT COST.....	\$ _____
LABOR COST.....	\$ _____
_____ REG. HOURS @ \$ _____ P/H	
_____ O.T. HOURS @ \$ _____ P/H	
MATERIAL COST.....	\$ _____
MISC. COST.....	\$ _____
TOTAL COST.....	\$ _____

\*\*\*\*\*

MATERIALS USED IN REPAIRS: Hy max coupling

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR [Signature] DATE 1-7-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

# Boil Water Advisory

This consumer advisory is being issued by:  
Rattlesnake Ridge Water District

## What should you do?

Although **NO CONTAMINATION HAS BEEN CONFIRMED** we recommend: Bring all water to a rolling boil, let it boil for three (3) minutes, and let it cool before using, or use bottled water. Boiled or bottled water should be used for drinking, making ice, brushing teeth, washing dishes, and food preparation until further notice. Boiling kills bacteria and other organisms in the water.

## What are the areas being affected?

rt 474 Grassy lick branch

People with severely compromised immune systems, infants, and some elderly may be at increased risk. These people should seek advice from their health care providers about drinking water.

## What happened?

3' bell

## are we correcting the problem?

band clamp

We apologize for any inconvenience this may have caused you. This advisory was issued as a precautionary action and can only be lifted with the approval of the Kentucky Division of Water. When all appropriate laboratory testing is completed and the Kentucky Division of Water allows us to lift the advisory, we will inform you when you no longer need to boil your water.

For more information, please contact:

606-474-7570

David Gifford  
Po box 475  
Grayson  
Ky 41143

Issued @ 8:00 AM  
BERINS

Lifted @ 11:15  
1-14-20

Per ASB/ky

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

so 20  
21  
22

This notice is being sent to you by:  
Public Water System ID #:

Rattlesnake Ridge Water District  
Ky0220555

Date 1/7/2020

Spanish - Este informe contiene información muy importante sobre la calidad de su agua beber. Tradúzcalo o hable con alguien que lo entienda bien.

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Rose Ridge Service

DATE: 3-30-20 TIME OF INTERRUPTION: FROM 12 TO 1

DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 0

CAUSE OF INTERRUPTION: 3/4 service split

DATE AND TIME CHLORINE RESIDUAL TAKEN: 1-26

DATE AND TIME BAC-TEE'S TAKEN: 3-30-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 78000 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3/4 Band Clamp made pressur

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDOWN) \_\_\_\_\_ OPERATOR D. L. Lyle DATE 3-30-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Rt 182 Rick Steves  
DATE: 3-30-20 TIME OF INTERRUPTION: FROM 9 TO 10  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 0  
CAUSE OF INTERRUPTION: 3/4 split  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.49  
DATE AND TIME BAC-TEE'S TAKEN: 3-30-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 107800 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: service leak for  
long time.

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR [Signature] DATE 3-30-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Rattlesnake Fork  
DATE: 3-30-70 TIME OF INTERRUPTION: FROM 2 TO 3  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 0  
CAUSE OF INTERRUPTION: Worked on Blow off valve  
DATE AND TIME CHLORINE RESIDUAL TAKEN: NA  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 164000 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: put new END on  
Blow off that been leaking

REMEDY OR STEPS TAKEN TO PREVENT REOCCURENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR D. J. Spill DATE 3-30-70

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: RT 1  
DATE: 3-27-20 TIME OF INTERRUPTION: FROM 3 TO 4  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 0  
CAUSE OF INTERRUPTION: 3" CRACK  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.36  
DATE AND TIME BAC-TEE'S TAKEN: 3-27-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 170,000 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3" BAND UNDER PRESSURE

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) \_\_\_\_\_ OPERATOR: [Signature] DATE: 3-27-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 4-mile  
DATE: 3-27-20 TIME OF INTERRUPTION: FROM 1 TO 2  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 0  
CAUSE OF INTERRUPTION: 3/4 service Band clamp  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.36  
DATE AND TIME BAC-TEE'S TAKEN: 3-27-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 325000 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: Band clamp up

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDOWN) \_\_\_\_\_ OPERATOR D. S. [Signature] DATE 3-27-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Rt 1

DATE: 3-25-20 TIME OF INTERRUPTION: FROM 9 TO 10

DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 0

CAUSE OF INTERRUPTION: 3/4 service

DATE AND TIME CHLORINE RESIDUAL TAKEN: 3-25-20 1.39

DATE AND TIME BAC-TEE'S TAKEN:  
\*\*\*\*\*

WATER LOSS (IF ANY): 93000 GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_

\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3/4 Band Clamp

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDOWN)

D. S. [Signature]  
OPERATOR 3-25-20  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Horner Flats  
DATE: 3-23-20 TIME OF INTERRUPTION: FROM 9 TO 11  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 3" split  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.51  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 1056000 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3" Band Been leaking  
For while.

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) Dwight 3-23-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: FLUTZ  
DATE: 3-20-20 TIME OF INTERRUPTION: FROM 9 TO 11  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: 0  
CAUSE OF INTERRUPTION: 8" crack  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.46  
DATE AND TIME BAC-TEE'S TAKEN: 3-20-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 140,328 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 8" BAND CLAMP  
UNDER PRESSURE

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDOWN) \_\_\_\_\_  
OPERATOR [Signature] DATE 3-20-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: SEAGRAVES Hollow  
DATE: 3-17-20 TIME OF INTERRUPTION: FROM 9.00 TO 10.00  
DURATION OF INTERRUPTION: 1 hr POPULATION AFFECTED: 0  
CAUSE OF INTERRUPTION: 3/4 UP -  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.29  
DATE AND TIME BAC-TEE'S TAKEN: 3-17-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 225000 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3/4 BAND CLAMP

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDOWN) \_\_\_\_\_ OPERATOR D. M. [Signature] DATE 3-17-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Mills Branch  
DATE: 3-16-20 TIME OF INTERRUPTION: FROM 12 TO 2  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 6" split  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.49  
DATE AND TIME BAC-TEE'S TAKEN: 3-16-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 45000 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 6" BAND

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) \_\_\_\_\_ OPERATOR D. L. [Signature] DATE 3-16-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Gilliam Branch  
DATE: 3-10-20 TIME OF INTERRUPTION: FROM 3 TO 4  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 0  
CAUSE OF INTERRUPTION: 3/4 split  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 3-10-20  
DATE AND TIME BAC-TEE'S TAKEN: 1.91  
\*\*\*\*\*

WATER LOSS (IF ANY): 45000 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3/4 Band (UP)

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) D. J. [Signature] 3-10-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Bear Ridge  
DATE: 3-9-20 TIME OF INTERRUPTION: FROM 2 TO 3  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 3/4 581.4  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.39  
DATE AND TIME BAC-TEE'S TAKEN: 3-9-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 735000 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3/4 BAND

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) \_\_\_\_\_ OPERATOR D. H. W. DATE 3-9-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: B Rt 706  
DATE: 3-9-20 TIME OF INTERRUPTION: FROM 3 TO 4  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 1  
CAUSE OF INTERRUPTION: 3/4 split under pressure  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.39  
DATE AND TIME BAC-TEE'S TAKEN: 3-9-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 360000 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3/4 BAND

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) D. J. Pharis 3-9-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 474 serv. co

DATE: 3-9-20 TIME OF INTERRUPTION: FROM 1 TO 2

DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 1

CAUSE OF INTERRUPTION: 3/4 split

DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.46

DATE AND TIME BAC-TEE'S TAKEN:  
\*\*\*\*\*

WATER LOSS (IF ANY): 164 131 GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_

\*\*\*\*\*

MATERIALS USED IN REPAIRS: BAND under pressure

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDOWN) *[Signature]* 3-9-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Pump station At 986  
DATE: 3-5-20 TIME OF INTERRUPTION: FROM 4 PM TO 6: PM  
DURATION OF INTERRUPTION: 2HK POPULATION AFFECTED: 0  
CAUSE OF INTERRUPTION: SPBZ on line At Pump station  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: 1.46  
\*\*\*\*\*

WATER LOSS (IF ANY): 214415 GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 4" Band clamp.

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

OPERATOR: D. W. B. J.

DATE: 3-5-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Rt 7 & Rt 986  
DATE: 4-28-20 TIME OF INTERRUPTION: FROM 3pm TO 6pm  
DURATION OF INTERRUPTION: 3HR POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 10" PVC CRACK  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 4-28-20 - 1.44  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 50,000 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
           REG. HOURS @ \$ \_\_\_\_\_ P/H  
           O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 10" Band Clamp

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) [Signature] 4-28-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Thompson Branch

DATE: 5-4-20 TIME OF INTERRUPTION: FROM 11:45 TO 1:20

DURATION OF INTERRUPTION: 2 HR POPULATION AFFECTED: 30

CAUSE OF INTERRUPTION: 4" PVC PIPE BELL LEAK

DATE AND TIME CHLORINE RESIDUAL TAKEN: 5-4-20 1 PM 121

DATE AND TIME BAC-TEE'S TAKEN: 5-6-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 30,000 GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_

\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3" Hymax Coupling

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) [Signature] 5-4-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Cains Creek  
DATE: 6-17-20 TIME OF INTERRUPTION: FROM 9 AM TO 11 AM  
DURATION OF INTERRUPTION: 2 HRS POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 4" Piped in slip in Road  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 6-17-20 - 1.10  
DATE AND TIME BAC-TEE'S TAKEN: 6-17-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 30,000 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
           REG. HOURS @ \$ \_\_\_\_\_ P/H  
           O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 4" Pipe & Hymat Coupling

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

[Signature] 6-17-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Church Ridge  
DATE: 7-2-20 TIME OF INTERRUPTION: FROM 7 AM TO 8 AM  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 35  
CAUSE OF INTERRUPTION: 3" PVC PIPE BREAK  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 7-2-20 1.31  
DATE AND TIME BAC-TEE'S TAKEN: 7-2-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 40,000 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
           REG. HOURS @ \$ \_\_\_\_\_ P/H  
           O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: new pipe & Hydrant Coupling

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) [Signature] 7-2-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: \_\_\_\_\_

DATE: \_\_\_\_\_ TIME OF INTERRUPTION: FROM \_\_\_\_\_ TO \_\_\_\_\_

DURATION OF INTERRUPTION: \_\_\_\_\_ POPULATION AFFECTED: \_\_\_\_\_

CAUSE OF INTERRUPTION: \_\_\_\_\_

DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_

DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

OPERATOR \_\_\_\_\_

DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570


BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 4-mile Road  
DATE: 7-13-20 TIME OF INTERRUPTION: FROM 2pm TO 4pm  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: 25  
CAUSE OF INTERRUPTION: 3" PVC Bell Leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 7-13-20 1.21  
DATE AND TIME BAC-TEE'S TAKEN: 7-14-20  
\*\*\*\*\*

WATER LOSS (IF ANY): 30,000 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
           REG. HOURS @ \$ \_\_\_\_\_ P/H  
           O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3" Pipe & Hyman Coupling

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN)  7-13-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Thompson Branch & Mushroom Hill  
DATE: 8-24-20 TIME OF INTERRUPTION: FROM 1:30<sup>pm</sup> TO 3:30<sup>pm</sup>  
DURATION OF INTERRUPTION: 2 HR POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 2" PVC Blowed out  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 8-24-20  
DATE AND TIME BAC-TEE'S TAKEN: 8-24-20 109  
\*\*\*\*\*

WATER LOSS (IF ANY): 20,000 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
           REG. HOURS @ \$ \_\_\_\_\_ P/H  
           O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 2" pipe & Hydrant

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN)

[Signature]  
OPERATOR

8-24-20  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Opposum Hollow, Oakland Ridge  
DATE: 9-12-20 TIME OF INTERRUPTION: FROM 4:AM TO 7:AM  
DURATION OF INTERRUPTION: 3HR POPULATION AFFECTED: 100  
CAUSE OF INTERRUPTION: 6" PVC Break  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 7:00 AM 1.26  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 69,000 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
         REG. HOURS @ \$ \_\_\_\_\_ P/H  
         O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 6" Pipe & Hydrant

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

[Signature]  
OPERATOR

9-12-20  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Mayhew Flats - 8+773  
DATE: 9-16-20 TIME OF INTERRUPTION: FROM 8:00 am TO 4:00 pm  
DURATION OF INTERRUPTION: 8 HR POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: maintenance to Pump Station  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 9-16-20 1.36  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 0 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: Redove Pump Station  
completely

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) [Signature] 9-16-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD





RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Wicker Hollow - Possum Hollow

DATE: 11-1-20 TIME OF INTERRUPTION: FROM 5 TO 6 PM

DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 30

CAUSE OF INTERRUPTION: 6" POC CRACK

DATE AND TIME CHLORINE RESIDUAL TAKEN: 11-1-20 1.42

DATE AND TIME BAC-TEE'S TAKEN:  
\*\*\*\*\*

WATER LOSS (IF ANY): 30,000 GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_

\*\*\*\*\*

MATERIALS USED IN REPAIRS: 6" BAND CLAMP

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

\_\_\_\_\_

(BREAKDWN)

[Signature]  
OPERATOR

11-1-20  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: HUFFS Run  
DATE: 11-15-20 TIME OF INTERRUPTION: FROM 11:30 TO 1:30  
DURATION OF INTERRUPTION: 2 HRS POPULATION AFFECTED: 25  
CAUSE OF INTERRUPTION: 8" POC split  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 11-15-20 1.36  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 40,000 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 8" Pipe & Hyman

REMEDY OR STEPS TAKEN TO PREVENT REOCCURENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) [Signature] 11-15-20  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: \_\_\_\_\_

DATE: \_\_\_\_\_ TIME OF INTERRUPTION: FROM \_\_\_\_\_ TO \_\_\_\_\_

DURATION OF INTERRUPTION: \_\_\_\_\_ POPULATION AFFECTED: \_\_\_\_\_

CAUSE OF INTERRUPTION: \_\_\_\_\_

DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_

DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

OPERATOR \_\_\_\_\_

DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESHAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Little Fork 1496  
DATE: 12/26/19 TIME OF INTERRUPTION: FROM 7:30 TO 8:30  
DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 9  
CAUSE OF INTERRUPTION: 4" Bell Leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 12/26/19 1.34  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN)

[Signature]  
OPERATOR

12/26/19  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Rt 474 - GRASSY creek

DATE: 1-7-20 TIME OF INTERRUPTION: FROM 1:00 TO 2:00

DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: 25

CAUSE OF INTERRUPTION: 3" Bell

DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.46

DATE AND TIME BAC-TEE'S TAKEN:  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_

\*\*\*\*\*

MATERIALS USED IN REPAIRS: Hy max coupling

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN)

[Signature]  
OPERATOR \_\_\_\_\_ DATE 1-7-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Pt 7 From Plant to 986  
DATE: 4/28/20 TIME OF INTERRUPTION: FROM 6:00 TO 9:00  
DURATION OF INTERRUPTION: 3 POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 10" Bell leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 4-28-20 1.41  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 10" Bell Repair with ~~flex~~ max

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) \_\_\_\_\_  
OPERATOR [Signature] DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

Basl water issued But  
Camp ground was closed  
Due TO COVID-19.  
[Signature]

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Thompson Branch - Conn Hill  
DATE: 5-4-20 TIME OF INTERRUPTION: FROM 1:00 TO 2:00  
DURATION OF INTERRUPTION: 1:00 POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 4" Bell Leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 5-4-20  
DATE AND TIME BAC-TEE'S TAKEN: 1.46  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 4" Hy Mat

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) \_\_\_\_\_  
OPERATOR [Signature] DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

Boil water issued.  
[Signature]

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Sammons Hollow  
DATE: 5-4-20 TIME OF INTERRUPTION: FROM 3:00<sup>pm</sup> TO 5:00<sup>pm</sup>  
DURATION OF INTERRUPTION: 2 HRS POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 3" BLOW OFF  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
\_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
\_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN)

OPERATOR \_\_\_\_\_

DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 504 EAST  
DATE: 5-5-20 TIME OF INTERRUPTION: FROM      TO       
DURATION OF INTERRUPTION: 0 POPULATION AFFECTED:       
CAUSE OF INTERRUPTION: 3/4" SERVICE LEAK  
DATE AND TIME CHLORINE RESIDUAL TAKEN:     

DATE AND TIME BAC-TEE'S TAKEN:  
\*\*\*\*\*

WATER LOSS (IF ANY):      GALLONS  
WATER COST..... \$       
EQUIPMENT COST..... \$       
LABOR COST..... \$       
     REG. HOURS @ \$      P/H  
     O.T. HOURS @ \$      P/H  
MATERIAL COST..... \$       
MISC. COST..... \$       
TOTAL COST..... \$       
\*\*\*\*\*

MATERIALS USED IN REPAIRS:     

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
      
    

(BREAKDWN)      OPERATOR      DATE     

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Bill Carroll  
DATE: 5-7-20 TIME OF INTERRUPTION: FROM 9am TO 10am  
DURATION OF INTERRUPTION: 0 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: Service Leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/M  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR \_\_\_\_\_ DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: RT 486  
DATE: 5-7-20 TIME OF INTERRUPTION: FROM 3<sup>00</sup> TO 4<sup>00</sup>  
DURATION OF INTERRUPTION: 0 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 3/4" service leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_

DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR \_\_\_\_\_ DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Possom Hollow  
DATE: 5-8-20 TIME OF INTERRUPTION: FROM 9am TO 11am  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 16" Bell  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/M  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/M  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR \_\_\_\_\_ DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 105 60  
DATE: 5-8-20 TIME OF INTERRUPTION: FROM 12A TO 2<sup>PM</sup>  
DURATION OF INTERRUPTION: 0 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 3/4" service LEAK  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

OPERATOR \_\_\_\_\_

DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Kitchen Halls  
DATE: 5-11-20 TIME OF INTERRUPTION: FROM 10 AM TO 12 PM  
DURATION OF INTERRUPTION: 0 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 3/4" SERVICE LEAK  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR \_\_\_\_\_ DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 4-mile  
DATE: 5-12-20 TIME OF INTERRUPTION: FROM 4pm TO 6pm  
DURATION OF INTERRUPTION: 2 hrs POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 2" cap  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR \_\_\_\_\_ DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 4-mile

DATE: 4-12-20 TIME OF INTERRUPTION: FROM 3<sup>pm</sup> TO 4<sup>pm</sup>

DURATION OF INTERRUPTION: 1 POPULATION AFFECTED: \_\_\_\_\_

CAUSE OF INTERRUPTION: 3/4" service leak

DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_

DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

\_\_\_\_\_

(BREAKDWN)

OPERATOR \_\_\_\_\_

DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 504 EAST  
DATE: 5-13-20 TIME OF INTERRUPTION: FROM 10:00 TO 11:00  
DURATION OF INTERRUPTION: 0 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 3/4" SERVICE LEAK  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR \_\_\_\_\_ DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: JORDAN FORK  
DATE: 5-14-20 TIME OF INTERRUPTION: FROM 9am TO 10am  
DURATION OF INTERRUPTION: 0 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 3/4" service leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

OPERATOR \_\_\_\_\_

DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 504 EAST  
DATE: 5-18-20 TIME OF INTERRUPTION: FROM 9am TO 10am  
DURATION OF INTERRUPTION: 0 POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: 3/4 service LEAK  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

OPERATOR \_\_\_\_\_

DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Cains Creek  
DATE: 6-17-20 TIME OF INTERRUPTION: FROM 11:00<sup>PM</sup> TO 1:00 AM  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 4" Bell Pulled  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 6-17-20 - 1.37cl  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 4" Hymax

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) [Signature] 6-17-20  
OPERATOR \_\_\_\_\_ DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

Boil water issued on  
6-18-20 To James  
Bevins

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Church Ridge & Big Sinkling  
DATE: 7-2-20 TIME OF INTERRUPTION: FROM 7:00am TO 9:00  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: 35  
CAUSE OF INTERRUPTION: 3' Pipe split  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 7-2-20 - 1:41  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: new Pipe & Hymax

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

[Signature]  
OPERATOR

7-2-20  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 4-mile Road  
DATE: 7-13-2020 TIME OF INTERRUPTION: FROM 2:00 TO 4:00  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: 25  
CAUSE OF INTERRUPTION: 3" PVC CRACK  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 7-13-20 - 1.62  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: new pipe & Hymax

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDOWN) \_\_\_\_\_ OPERATOR [Signature] DATE 7-13-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

Boil water issued @ 4:30  
@ lifted 7-15-20 @ 8:16  
Per  
James Bovins

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Thompson Branch - 8' mushroom hill  
DATE: 8-24-20 TIME OF INTERRUPTION: FROM 12:00<sup>PM</sup> TO 3:00<sup>PM</sup>  
DURATION OF INTERRUPTION: 3 POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 2" PVC Broke  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_

\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_

\*\*\*\*\*

MATERIALS USED IN REPAIRS: 2" Pipe & Coupling

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDOWN) \_\_\_\_\_  
OPERATOR D. Miller DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

BW issued @ 4:05 on 24th

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Possman Hollow - Oakland Ridge  
DATE: 9-12-20 TIME OF INTERRUPTION: FROM 4:00<sup>AM</sup> TO 7:00<sup>AM</sup>  
DURATION OF INTERRUPTION: 3 POPULATION AFFECTED: 100  
CAUSE OF INTERRUPTION: 6" line break  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.53  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 6" Pipe & Hymat Coupler

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDOWN) \_\_\_\_\_ OPERATOR \_\_\_\_\_ DATE 9-12-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

Issued BWA @ 11:00  
ON 9-14-20  
Filed 9-15-20  
@ 12:42  
Bevins



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 773 - Mayhew Flats - wells RD.

DATE: 9-16-20 TIME OF INTERRUPTION: FROM 10:00 TO 6:00

DURATION OF INTERRUPTION: 8 POPULATION AFFECTED: 30

CAUSE OF INTERRUPTION: maintenance in Pump st. New PRU

DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.57

DATE AND TIME BAC-TEE'S TAKEN:  
\*\*\*\*\*

WATER LOSS (IF ANY): NO GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_  
\_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

[Signature]  
OPERATOR

9-16-20  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

Issued BWA @ 8:30 AM  
ON 9-17-

Lifted @ 1:20 PM

ON 9-22-20

Bevins

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Hitchiss & Menette RD  
DATE: 9-22-20 TIME OF INTERRUPTION: FROM 1:00 TO 3:00  
DURATION OF INTERRUPTION: 2<sup>00</sup> POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 3" Bell Brake  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) [Signature] 9-22-20  
OPERATOR \_\_\_\_\_ DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

BWA FSSM @ 2:30  
TO BEVINS.

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Little Fork - Rt 1122  
DATE: 10-26-20 TIME OF INTERRUPTION: FROM 11:30 TO 1:30  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: 20  
CAUSE OF INTERRUPTION: 4" Line Break  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 4" Hymax

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) [Signature] 10-20-20  
OPERATOR \_\_\_\_\_ DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD  
BWA @ 11:40 AM  
Lifted @ 10:30 (Bevins)

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: wicker Hollow, Possum Hollow  
DATE: 11-1-20 TIME OF INTERRUPTION: FROM 3:00 TO 5:00  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 6" line Break  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.26  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 6" Hymax & Pipe

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDOWN) \_\_\_\_\_ 11-1-20  
OPERATOR \_\_\_\_\_ DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD  
Issued @ 11-2-20 8:18 AM Per WC  
Lithd 11-6-20 @ 10:15 - Berry

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: HUFFS RUN  
DATE: 11-15-20 TIME OF INTERRUPTION: FROM 12: TO 3:00  
DURATION OF INTERRUPTION: 3 POPULATION AFFECTED: 25  
CAUSE OF INTERRUPTION: 8" Bell Leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 8" Hyman

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR [Signature] DATE 11-15-20

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

BWA @ 9:45 - on 11/16  
Lifted @ 12:22 on 11/18  
Bevins

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Mayhew Flats, Iscerville webbsville  
DATE: 1-1-21 TIME OF INTERRUPTION: FROM \_\_\_\_\_ TO \_\_\_\_\_  
DURATION OF INTERRUPTION: 24HR POPULATION AFFECTED: 300  
CAUSE OF INTERRUPTION: Low TAN K leak @ cl. fly  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1-1-21 1.59  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_

\*\*\*\*\*  
WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 6" Agmat

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) OPERATOR \_\_\_\_\_ DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

*Boil water was issued because  
TANKS got low and people were  
running out of water.*  
*[Signature]*

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Harter Flats  
DATE: 1-5-21 TIME OF INTERRUPTION: FROM 7:30 TO 9:30  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: 6  
CAUSE OF INTERRUPTION: Bell Leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: Hy max

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) \_\_\_\_\_  
OPERATOR [Signature] DATE 1-5-21

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Horton Flats  
DATE: 1-5-21 TIME OF INTERRUPTION: FROM 10:00 TO 1:00  
DURATION OF INTERRUPTION: 3 hrs POPULATION AFFECTED: 6  
CAUSE OF INTERRUPTION: 3" Bell  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1-5-21- 1.61  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3" Hymax coupling

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDWN) \_\_\_\_\_ OPERATOR \_\_\_\_\_ DATE 1-5-21

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

Boil water was issued  
FROM ERWIN MARKWELL  
TO END OF LINE.

AS



RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Fields BRANCH  
DATE: 3-16-21 TIME OF INTERRUPTION: FROM 9:30 TO 12:30  
DURATION OF INTERRUPTION: 3 HR POPULATION AFFECTED: 50  
CAUSE OF INTERRUPTION: County Road Hit Line  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 3-16-21 - 1.64  
DATE AND TIME BAC-TEE'S TAKEN: 3-20-16 - 9:10 AM  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: Pipe & Hyman

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

*D. P. Smith*  
OPERATOR

3-16-21  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Rt 1025  
DATE: 3-12-21 TIME OF INTERRUPTION: FROM 2:00 TO 4:00 PM  
DURATION OF INTERRUPTION: 2 HRS POPULATION AFFECTED: 25  
CAUSE OF INTERRUPTION: 4" Bell Leak  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 3-12-21 1:56  
DATE AND TIME BAC-TEE'S TAKEN: 3-15-21 1:38 PM  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN: \_\_\_\_\_

(BREAKDOWN) \_\_\_\_\_  
OPERATOR [Signature] DATE 3-12-21

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 504 - From Pearl Sparks to Gerleisr

DATE: 4-8-21 TIME OF INTERRUPTION: FROM 11:00 TO 2:00 pm

DURATION OF INTERRUPTION: 3 POPULATION AFFECTED: 15

CAUSE OF INTERRUPTION: Hit Line Building BARN

DATE AND TIME CHLORINE RESIDUAL TAKEN: 4-8-21 1:24

DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 30,000 GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H


MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 20' 4" SDR17  
1-4" Hy max

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)  4-8-21  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: 504 - From Pearl Sparks to GARRIS

DATE: 4-8-21 TIME OF INTERRUPTION: FROM 11:00 TO 2:00 PM

DURATION OF INTERRUPTION: 3 POPULATION AFFECTED: 15

CAUSE OF INTERRUPTION: Hit Live Building BARN

DATE AND TIME CHLORINE RESIDUAL TAKEN: 4-8-21 1:24

DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 30,000 GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 20' 4" SDR17

1-4" Hy max

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

[Signature]  
OPERATOR

4-8-21  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: \_\_\_\_\_  
DATE: 5/24/21 TIME OF INTERRUPTION: FROM 12:00 TO 2:00  
DURATION OF INTERRUPTION: 2 POPULATION AFFECTED: 40  
CAUSE OF INTERRUPTION: 16" PVC CRACK  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 5/24/21 1:34  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 16" Hydrant

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN) \_\_\_\_\_  
OPERATOR [Signature] DATE 5/24/21

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Walnut Grove & Rose Ridge

DATE: 6/11/21 TIME OF INTERRUPTION: FROM 10:00<sup>AM</sup> TO 4:00

DURATION OF INTERRUPTION: 6 POPULATION AFFECTED: 150

CAUSE OF INTERRUPTION: Low Pressure - Power outage & leak

DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_

DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: - - 0 -

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)  6/11/21  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Oakland Ridge & Carter City

DATE: 6/13/21 TIME OF INTERRUPTION: FROM 1:00 TO 1:30

DURATION OF INTERRUPTION: 2 1/2 POPULATION AFFECTED: 100

CAUSE OF INTERRUPTION: 3" Leak

DATE AND TIME CHLORINE RESIDUAL TAKEN: 6/13/21 1:40

DATE AND TIME BAC-TEE'S TAKEN: 6-14-21

\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_

\*\*\*\*\*

MATERIALS USED IN REPAIRS: 3" Hyman

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

\_\_\_\_\_

(BREAKDWN) [Signature] 6-13-21  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: US 60

DATE: 6-24-21 TIME OF INTERRUPTION: FROM \_\_\_\_\_ TO \_\_\_\_\_

DURATION OF INTERRUPTION: NO POPULATION AFFECTED: 0

CAUSE OF INTERRUPTION: 1" service split

DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_

DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 287,668 GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ 1" Band

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 1" Band 135.00

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

[Signature]  
OPERATOR

6-24-21  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD





RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Grayson Lake

DATE: 8-30-21 TIME OF INTERRUPTION: FROM 5:00 TO 7:00

DURATION OF INTERRUPTION: 2hr POPULATION AFFECTED: 100

CAUSE OF INTERRUPTION: 8" Ductile Iron Hole

DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.36

DATE AND TIME BAC-TEE'S TAKEN:  
\*\*\*\*\*

WATER LOSS (IF ANY): 1,206,087 GALLONS

WATER COST..... \$ \_\_\_\_\_

EQUIPMENT COST..... \$ \_\_\_\_\_

LABOR COST..... \$ \_\_\_\_\_

\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H

\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H

MATERIAL COST..... \$ \_\_\_\_\_

MISC. COST..... \$ \_\_\_\_\_

TOTAL COST..... \$ \_\_\_\_\_

\*\*\*\*\*

MATERIALS USED IN REPAIRS: 8" BAND clamp

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

(BREAKDWN)

  
OPERATOR

8-30-21  
DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: RT 1496  
DATE: 9-4-21 TIME OF INTERRUPTION: FROM 2 TO 3:20  
DURATION OF INTERRUPTION: 1 HR POPULATION AFFECTED: 0  
CAUSE OF INTERRUPTION: Small crack in 4" PVC  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 719,187 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 4" Band clamp

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:

\_\_\_\_\_

(BREAKDWN)

[Signature] OPERATOR 9-4-21 DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: Rt 60 Wicker Hollow  
DATE: 9-27-21 TIME OF INTERRUPTION: FROM 4:00 TO 6:00 AM  
DURATION OF INTERRUPTION: 2 HR POPULATION AFFECTED: 30  
CAUSE OF INTERRUPTION: 6" split  
DATE AND TIME CHLORINE RESIDUAL TAKEN: 1.46  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): 499, 025 GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: 6" BAND clamp

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN) [Signature] 9-27-21  
OPERATOR DATE

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

RATTLESNAKE RIDGE WATER DISTRICT  
P.O. BOX 475  
GRAYSON, KENTUCKY 41143  
(606) 474-7570

BREAKDOWN RECORD

LOCATION OF INTERRUPTION: RT 286  
DATE: 10-9-21 TIME OF INTERRUPTION: FROM 6:00 TO 8:00 pm  
DURATION OF INTERRUPTION: 2 hr POPULATION AFFECTED: \_\_\_\_\_  
CAUSE OF INTERRUPTION: \_\_\_\_\_  
DATE AND TIME CHLORINE RESIDUAL TAKEN: \_\_\_\_\_  
DATE AND TIME BAC-TEE'S TAKEN: \_\_\_\_\_  
\*\*\*\*\*

WATER LOSS (IF ANY): \_\_\_\_\_ GALLONS  
WATER COST..... \$ \_\_\_\_\_  
EQUIPMENT COST..... \$ \_\_\_\_\_  
LABOR COST..... \$ \_\_\_\_\_  
    \_\_\_\_\_ REG. HOURS @ \$ \_\_\_\_\_ P/H  
    \_\_\_\_\_ O.T. HOURS @ \$ \_\_\_\_\_ P/H  
MATERIAL COST..... \$ \_\_\_\_\_  
MISC. COST..... \$ \_\_\_\_\_  
TOTAL COST..... \$ \_\_\_\_\_  
\*\*\*\*\*

MATERIALS USED IN REPAIRS: \_\_\_\_\_  
\_\_\_\_\_

REMEDY OR STEPS TAKEN TO PREVENT REOCCURRENCE OF BREAKDOWN:  
\_\_\_\_\_  
\_\_\_\_\_

(BREAKDWN)

OPERATOR \_\_\_\_\_

DATE \_\_\_\_\_

COPY TO: DOW-FRANKFORT  
DOW-MOREHEAD

*Lifted:  
9/10/45  
Per  
JAMES*