CHRISTIAN CO. WATER DISTRICT - OPERATIONS

018648

Vendor 23586	5 Vermeer of Indiana, Inc.		Check Date 08/21/	2020 Check Nu	mber 18648	
Voucher Number	Invoice Number	Invoice Date	Invoice Amount	Amount Paid	Discount Taken	Net Amount
054401	CHRIS020 Item Description trencher repairs	08/21/2020	\$20,980.69	\$20,980.69	\$0.00	\$20,980.69
Materials & S	upplies Equipment		\$20,980.69	\$20,980.69	\$0.00 Check Total	\$20,980.69 \$20,980.69



Vermeer of Indiana, Inc. 13402 Britton Park Rd.. Fishers, IN 46038 Ph 317 842 1040 FX 317 577 1179

STATEMENT

REMIT TO:

Vermeer of Indiana, Inc. 13402 Britton Park Rd.. Fishers, IN 46038

Amount Enclosed \$20,980. 69

PAGE:

DATE: 08/04/20

CUSTOMER#: CHRIS020

BRANCH: Newburgh, IN

Christian County Water PO Box 7 Hopkinsville KY 42241-0007

				INVOICE	PREVIOUS	CURRENT	BALANCE
INVOICE#	DATE	$\underline{\mathtt{BR}}$	Description	AMOUNT	PAYMENTS	PAYMENTS	DUE
S07291	08/03/20	03	INVOICE	20980.69			20980.69



CURRENT 20980.69 31-60 .00 61-90 .00 91-120 .00 OVER 120 .00 LATE CHARGES .00 TOTAL 20980.69

TOTALS



Vermeer of Indiana, Inc. 3566 Citadel Circle Newburgh, IN 47630 Ph 812 490 4400 FX 812 490 4404

Ship to:	B-CCW RT950 #453 RICKY 270-881-8403
Invoice to:	Christian County Water PO Box 7 Hopkinsville KY 42241-0007

Branch			
Newburgh, I	N		
Date	Time		Page
07/31/20	07:38:	48 (0)	01
Account No.	Phone No.		Invoice No.
CHRIS020	270886	3696	S07291
Ship Via		hase Orde	r
	RIC	CKY	
		Sale	sperson
			JBR

SERVICE PRELIMINARY

FLEET#

LAINT:

RT950 BASIC TRACTO

HRS SN/EIN 1VR4112F0A1000453

652

WARRANTY DATE

07/14/11

HRS

RT950

73089746

NT# 1 5 JOSHB 0000V - Diagnostic

06/10/20 06/10/20

1.00

chment drive motor making noise and customer has found l in hydraulic filters TIONAL DESCRIPTION:

ight machine into shop and drained hydraulic tank. Found t of metal in the bottom of the tank and around the ion screens for the trencher drive and drive motor s. Cleaned metal out of tank, cleaned screens and aled tank. Removed hyd return and charge filters and them open to inspect. Did not find much metal in the ers but customer had just changed them after hyd ure. Customer stated trencher drive motor was making a of noise. Removed cover and hose from trencher drive r and found pieces of metal stuck in the hose. Looked nd ordered needed parts for hyd system clean out and ir.

02001

0001

KEY-IGNITION SW

1

4.23

4.23

KEY-IGNITION SWITCH (SET OF 2)

PARTS

4.23

LABOR SEGMENT TOTAL ==>

118.00 122.23

NT# 2 5 JOSHB 4033V

06/24/20 06/29/20

13.50

13.50

- Hydrostatic Pump R&R CMP (including flushing) ved hood, engine muffler and exhaust piping and frame s brace from over the top of the hystat pump. Removed

ed hoses and electrical connections. Unbolted pump and

CONTINUED ON PAGE 02

Authorized By



Vermeer of Indiana, Inc. 3566 Citadel Circle Newburgh, IN 47630 Ph 812 490 4400 FX 812 490 4404

	B-CCW RT950 #453	Newbur
to	RICKY 270-881-8403	Date
Ship		07/31/ Account No.
		CHRISO
		Ship Via
to.	Christian County Water	
Invoice	PO Box 7	
Ž	Hopkinsville KY 42241-0007	
-		

Newburgh, I Date	Time	Page
07/31/20	. 07:38:48 (0) 02
Account No.	Phone No.	Invoice No.
CHRIS020	2708863696	S07291
Ship Via	Purchase Or	der
	RICKY	
	S	alesperson
		JBR

SERVICE PRELIMINARY

TK#/FLEET	r#	HRS SN/EIN	WARR	ANTY DATE	HRS	
001285	RT950 BASIC TRACTO	652 1VR4112F0A	1000453	07/14/11		. T.
	RT950	73089746			A	3
removed :	from machine. Took pump	to be rebuilt. Re	installed			1 Page 1
pump in	reverse order. Filled wi	th hydraulic oil	before			
starting	. Checked for leaks afte	r starting. Had t	o replace		· · · · · · · · · · · · · · · · · · ·	
1 hose th	hat was leaking from the	trencher drive s	ection.		CO IN	7
26594100	l C	-RING - 154V75	2 N	2.76	1869	5.52
72895001	C	RING-SQ. #16	6 S	1.95	The state of the s	11.70
	O RING-SQ. #16 F	LANGE				
				PARTS		17.22
				LABOR		1593.00
11110001			SEGMENT	TOTAL==>		1610.22
ECMENT# :	3 5 JOSHB 4110V 0	6/24/20 06/25/20				
	round Drive Motor (each)			2 00	2 00	
			1 1 1 1 1 1	3.00	3.00	
	floor plate from machine					
	om the ground drive moto					
	and removed from machine					
72895001	led in reverse order and					
72895001		RING-SQ. #16	4 S	1.95		7.80
	O RING-SQ. #16 F	LANGE				
				PARTS		7.80
				LABOR		354.00
11110001			SEGMENT	TOTAL==>		361.80
EGMENT# 4	1 5 JOSHB 8510V 0	6/24/20 06/25/20				
	OTOR TRENCHER CMP*****			4.50	4.50	
	inspection cover from tr					
	hoses. Went to remove t					
master li	ink pin was seized. Had	to cut link in or	der to			

CONTINUED ON PAGE 03

Authorized By

remove chain. Removed chain and unbolted sprocket from the motor. Unbolted motor from the mount and removed. Swapped



Vermeer of Indiana, Inc. 3566 Citadel Circle Newburgh, IN 47630 Ph 812 490 4400 FX 812 490 4404

	D CON PERSON		Bran	nch				
	B-CCW RT950 #453		l N	lewburgh, IN				
Ship to:	RICKY 270-881-8403		Date)	Time			Page
20			Lo	7/31/20	07.	38:48 ((0)	
				ount No.	Phone No).	In	103 Noice No.
			c	HRISO20	270	8863696		
	Christian Count		Ship	Via	2/0	Purchase (Order	07291
nvoice to:	Christian County Wat	er				RICKY		
You	Hopkinsville KY 4224					ALE CALL		
=	TOPALINSVILLE RY 4224	1-0007						
							Salespe	rson
							JBI	R
		SERVICE PR	ELIMINAR	Y				
				•				****
TK#/FLEE	T#	HRS SN/EIN						
001285	RT950 BASIC TRACTO	/	WAR	RANTY DATE		S		
	RT950			07/14/11		· · · · · · · · · · · · · · · · · · ·	The state of the s	
fittings	over from old drive m	notor to	112	65	The state of the s	3 7	9	
					77.	. 1	\$	
			inge and		\$ 4		7	\$
			iose and		5	MAK	6	ge se
270572003	1	MOTOR-RADIAL PI	1 N	4239.87		100		
72894001		O RING-SO, #12	4 N	05.07	and the same			4239.87
	O RING-SQ. #12	FLANGE		1.54				6.16
				PARTS				4246.03
.1110001				LABOR				531.00
			SEGMENT	TOTAL==>				4777.03
GMENT# 5	5 JOSHB 4990V	06/24/20 06/29/20						
:990 - MO	TOR-STEERING R&R-CMP*	+ + + + + + + + + + + + + + + + + + +	****					
	over brace irom dach	IInhola-1		2.25		2.25		
			in in					
0.	rder. Ran to verify no	leaks or issues						
69777001		MOTOR - STEERIN	1 N	660.20				
			_ 17	669.39				669.39
1110001				PARTS LABOR				669.39
1110001			SEGMENT	TOTAL==>				265.50
GMENT# 6	5 JOSHB A001V			101711-23				934.89
001 - Equ	ipment Wash	06/24/20 07/14/20	N					
ashed ins	side of machine before	atortina				2.00		
	TIL GICEI WOLK WAS COM	nleted to	and					
nd check	for leaks.	preced to remove oil	l residue					
				LABOR			2	233.64

CONTINUED ON PAGE 04

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular prices. I agree to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire,



Vermeer of Indiana, Inc. 3566 Citadel Circle Newburgh, IN 47630 Ph 812 490 4400 FX 812 490 4404

Ship to:	B-CCW RT950 #453 RICKY 270-881-8403
Invoice to:	Christian County Water PO Box 7 Hopkinsville KY 42241-0007

Newburgh, I Date	Time	Page
07/31/20	07:38:48 (0)	04
Account No.	Phone No.	Invoice No.
CHRIS020	2708863696	S07291
Ship Via	Purchase Ord	der
	RICKY	
	S	alesperson
		JBR

TK#/FLEET# HRS SN/EIN WARRANTY DATE HRS 001285 RT950 BASIC TRACTO 652 1VR4112F0A1000453 07/14/11 RT950 73089746 233.64 11110001 SEGMENT TOTAL ==> EGMENT# 7 5 JOSHB M021V 06/24/20 06/24/20 Y 5.00 5.00 M021 - Hydraulic System Service CMP Completed 4 hydraulic services on machine. Including removing inspection cover on the bottom of the tank twice to clean out any residual metal from tank. Removed suction hoses to change suction screens twice as well. 50.48 HOSE1 HYD. HOSE 1"/FT 4 12.62 PHD17170 874.80 2.16 68 HYD OIL/QT. 405 5935.23 SUBLETL HYDRAULC REPAIR 1 5935.23 29.60 10643-16-16 #16 JIC SWIV X 2 14.80 #16 JIC SWIV X #16 CRIMP 199.28 296387478 FILTER ELEMENT 4 S 49.82 29.22 116.88 64101001 STRAINER-SUCTIO 4 N 12.45 6500-10-10 7 12.45 ADAPTER 7.85 6502-10-10 ADAPTER 1 7.85 343.76 81902001 8 S 42.97 FILTER-OIL **15 MICRON** 1635.10 PARTS LABOR 590.00 5935.23 SUBLET 8160.33 11110001 SEGMENT TOTAL ==> SEGMENT# 8 5 JOSHB 4325V 06/24/20 06/29/20

SERVICE PRELIMINARY

from bottom of hyd cooler. Unbolted radiator and lifted up to unbolt cooler from radiator assembly. Removed cooler

from machine. Swapped fittings from old cooler to new.

Removed front grill and inspection cover. Removed hoses

4325 - Hydraulic Oil Cooler R&R CMP (w/o Backhoe)

CONTINUED ON PAGE 05

4.50

Authorized By

4.50

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular prices. I agree to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.



B-CCW RT950 #453

Vermeer of Indiana, Inc. 3566 Citadel Circle Newburgh, IN 47630 Ph 812 490 4400 FX 812 490 4404

Branch

Newburgh, IN

			11/6	WULLUL IN			
Ship to:	RICKY 270-881-8403		Date		Time		Page
S			Accour	/31/20	07:38:4 Phone No.	8 (0)	0.5 Invoice No.
					Filone No.		invoice ivo.
			CHI Ship Vi	RISO20	2708863		S07291
nvoice to:				la	Purch	ase Order	
e D	Christian County Water	er			RIC	KY	
wolc	PO Box 7						
_ ≧	Hopkinsville KY 4224:	1-0007					
						Sale	sperson
							JBR
			<u> </u>				ODK
		SERVICE	PRELIMINARY				
TK#/FLEF				ANTY DATE	HRS		
001285	RT950 BASIC TRACTO	652 1VR411	2F0A1000453	07/14/11			
Dada a s	RT950	730897	46				
Reinstal	led in reverse order.	Ran to verify n	o leaks.				
26763600)1	OIL COOLER-RT9	5 1 N	999.52			999.52
				PARTS			999.52
				LABOR			531.00
11110001			SEGMENT	TOTAL==>			1530.52
							1330.32
	9 5 JOSHB 4L00V	06/24/20 06/30	/20				
	YDRAULIC LABOR				13.	50	
Removed	control valve, disasse	mbled and cleane	ed thoroughly		13.	30	urah.
Reassemo	led control valve and	reinstalled back	k in machine		المراجعة المتعادي والمراجعة		5
Removed	hoses, cleaned or repl	aced and reinsta	alled Removed		" " J. "	فيع بدنو الأرا	y . *
crossove	r relief valve and dis	assembled to cla	-an			3.7%	
Reassemb	led and reinstalled af	ter cleaning. Re	emoved and				
creaned	return manifold. Remov	ed and cleaned s	solenoid valve		14	1148	
manifold	. Removed and cleaned	creep control va	alve			00010	
m 1					3 634		

EGMENT#10 5 JOSHB 4994V

HOSE

270475001

11110001

06/24/20 06/24/20

1.50

284.41

138.31

PARTS

LABOR

1.50

4994 - VALVE-PRIORITY / FLOW R&R-CMP************* Removed priority flow valve from machine. Removed fittings and reinstalled on new priority valve and installed new

Removed and cleaned implement bypass valve. Removed and

cleaned filter bases and filter bypass valves.

valve. Ran to verify no other issues. 114018001

VALVE-PRIORITY

CUSTOM HOSE

HOSE-HYD-1.25X3

1 N 226.89

SEGMENT TOTAL ==>

2 N

1 N

226.89

PARTS

226.89

568.82

138.31

707.13

1593.00

2300.13

CONTINUED ON PAGE 06

Authorized By

hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular prices. I agree to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.



11110001

Vermeer of Indiana, Inc. 3566 Citadel Circle Newburgh, IN 47630 Ph 812 490 4400 FX 812 490 4404

	B-CCW RT950 #453 RICKY 270-881-8403 Christian County Water PO Box 7 Hopkinsville KY 42241-0007			Branch Newburgh, I				
Invoice to: Ship to:				Date 07/31/20 Account No. CHRIS020	Time 07:38:48 (O) Phone No. 2708863696		Page 0 06 Invoice No. S07291	
				Ship Via	Purchase Ord		er	
						Sa	esperson JBR	
	-		SERVICE PRELII	MINARY				
TK#/FLEI 001285	ET# RT950 BASIC TRACTO RT950	HRS 652	SN/EIN 1VR4112F0A100 73089746	WARRANTY DA 00453 07/14/		RS		

LABOR

SEGMENT TOTAL ==>

177.00

403.89

EGMENT#11 5 JOSHB 3L00V 06/10/20 07/21/20 3L00 - Frame Labor 3.00 Replaced links in trencher chain that had to be cut off to remove chain. Had to cut pins out to remove the needed links. Reinstalled new links in the chain with new master pins. Reinstalled chain on machine. 260397001 PIN ASSEMBLY-76 1 S 13.43 305919001 LINK-CONN ATT 7 7 N 67.53 LINK-CONN ATT 7600H - NR 305920001 LINK-BLOCK 7600 1 N 53.52 53.52 LINK-BLOCK 7600H - NR 384016 5/8-18X1 3/4"GR 2.96 11.84 5/8-18X1 3/4"GRADE#8HEX BOLT 396001 NUT-5/8-18 GR 8 6.56 1.64 NUT-5/8-18 GR 8 SLTL 70055044 BOLT-7/8 9 X 4 6.73 6.73 1 N BOLT-7/8 9 X 4 1/2 NC GR.8 72009001 BOLT-7/8NCX4 GR 20.28 5.07 BOLT-7/8NCX4 GRADE 8 83268001 7/8-9 LOCK NUT 12.12 6 N 2.02 7/8-9 LOCK NUT GRADE C PARTS 192.01 LABOR 354.00 11110001 SEGMENT TOTAL ==> 546.01

***** WORK ORDER TOTALS ******
CONTINUED ON PAGE 07

Authorized By

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular prices. I agree to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.



B-CCW RT950 #453

Vermeer of Indiana, Inc. 3566 Citadel Circle Newburgh, IN 47630 Ph 812 490 4400 FX 812 490 4404

Ship to	RICKY 270-881-8403
c)	
Invoice to:	Christian County Water PO Box 7 Hopkinsville KY 42241-0007

Newburgh, I Date	Time	Page
07/31/20	07:38:48 (0)	07
Account No.	Phone No.	Invoice No.
CHRIS020	2708863696	S07291
Ship Via	Purchase Ord	
	RICKY	
	Sa	lesperson
		JBR

SERVICE PRELIMINARY

CK#/FLEET#

)01285

RT950 BASIC TRACTO

RT950

HRS SN/EIN

652

WARRANTY DATE

HRS

1VR4112F0A1000453 73089746

> PARTS LABOR

8705.32 6340.14

SUBLET

07/14/11

5935.23

CHARGE ON ACCOUNT

20980.69