Case No. 2022-00402 Attachment to Response to JI-2 Question No. 89(b) Page 1 of 6 Isaacson

				Isaacso
Count of Enrollment ID	Year Installed 2020	2021	2022	Grand Total
Installed Measure				
5.5 INCH (DENSE PACK)			2	2
AERATOR - INSTALL LOW FLOW AERATOR - BAT	1133	630	599	2362
AERATOR - INSTALL LOW FLOW AERATOR - KIT	1956	1872	1041	4869
AIR SEALING - BLOWER DOOR GUIDED	1746	2392	2490	6628
ATTIC - BOXING AND DAMMING ATTIC ACCESS	8	3	7	18
ATTIC - BOXING AND DAMMING HEAT PRODUCIN	1	5	5	11
ATTIC - CREATE HATCH COVER - INSULATED &	298	367	417	1082
ATTIC - CREATE HATCH INTERIOR GREATER TH	45	19	23	87
ATTIC - CREATE HATCH INTERIOR LESS THAN	38	22	28	88
ATTIC - INTERIOR ATTIC STAIR COVER	1	5		6
ATTIC - PULL DOWN STAIR COVER - BUILT ON	41	47	72	160
ATTIC - PULL DOWN STAIR COVER - PRE-FAB		1		1
BLDG REPAIR - DRYWALL REPLACEMENT (FINIS	23	94	60	177
BLDG REPAIR - FLOORING REPLACEMENT (FINI	6	2	6	14
BLDG REPAIR - FLOORING REPLACEMENT (PLYW	1	10	13	24
CO DETECTOR - INSTALLATION	1266	1450	745	3461
CONTRACTOR - GAS LEAK REPAIR FEE (HRLY L		1	1	2
CONTRACTOR - GENERAL LABOR (HRLY LABOR)	224	632	286	1142
CONTRACTOR - SERVICE VISIT (QUOTE)	979	1008	1068	3055
CONTRACTOR - SPECIALTY OR MAJOR ISSUES (			1	1
CRAWL SPACE - AIR SEAL AND INSULATE WALL	1	1	3	5
CRAWL SPACE - FLOOR COVERING		1	1	2
CRAWL SPACE - INSTALL 6 MILL VAPOR BARRI		1		1
CRAWL SPACE - INSTALL CEILING/FLOOR INSU	43	28	50	121
CRAWL SPACE - INSTALL VENT CLOSER	3	5	1	9
CRAWL SPACE - PERIMETER INSULATION (RIM	25	16	19	60
DOOR - INSTALL DOOR SWEEP	1088	1850	1933	4871
DOOR - REPLACE EXT DOOR W CUSTOM MADE	2	3	3	8
DOOR - REPLACE LOCKSET	471	416	406	1293
DOOR - REPLACE PRIMARY EXT DOOR W SOLID	791	996	1168	2955
DOOR - WEATHER STRIPPING KIT - GENERAL	1424	2278	2242	5944
DUCT - SEAL/INSTALL INSULATION TO R6 EQU	4	3	6	13
DUCT - SEALING (DUCT BLASTER GUIDED OR E	282	343	386	1011
DUCT - WRAP	1	5	1	7
FAUCET - REPLACE FAUCET - BATHROOM SINK	3	15	16	34
FAUCET - REPLACE FAUCET - KITCHEN SINK	8	24	12	44
FILTER - CLEAN/REPLACE HVAC FILTER	377	323	213	913
FILTER - CLEAN/REPLACE WINDOW AC FILTER	3	1	2	6
FLUE - REPAIR	9	63	30	102
FRIDGE - REPLACE WITH ENERGY STAR 15 CU	21	8		29

Case No. 2022-00402

Attachment to Response to JI-2 Question No. 89(b)

Page 2 of 6

				Page 2 of 6
				Isaacson
FRIDGE - REPLACE WITH ENERGY STAR 17 CU	95	73	32	200
FRIDGE - REPLACE WITH ENERGY STAR 18 CU	159	204	166	529
FRIDGE - REPLACE WITH ENERGY STAR 21 CU	108	65	21	194
GABLE VENT INSTALLED	2			2
HVAC - COOLING - TUNE-UP (PER SYSTEM)	138	118	546	802
HVAC - HEATING - REPAIR SYSTEM (PARTS)	4	1		5
HVAC - HEATING - REPLACE SYSTEM (HRLY LA	2			2
HVAC - HEATING - TUNE-UP (PER SYSTEM)	481	470	1043	1994
INSULATE - INSTALL 1 INCH INSULATION BOA	1		2	3
INSULATE - INSTALL 1/2 INCH INSULATION B	1		2	3
INSULATE - INSTALL 2 INCH INSULATION BOA	1	3	8	12
INSULATE - RIM JOIST	14	13	9	36
INSULATE - UNINSULATED FLOORED ATTIC TO		2	1	3
INSULATE - UNINSULATED KNEEWALLS TO R11	4	6	4	14
INSULATE - UNINSULATED KNEEWALLS TO R13	22	16	22	60
INSULATE - UNINSULATED KNEEWALLS TO R19	16	10	15	41
INSULATE - UNINSULATED SLOPE CEILING TO	5	2	11	18
INSULATE - UNINSULATED WALLS 3.5 INCH (F	116	64	74	254
INSULATE - UNRESTRICTED ATTIC R11 TO R26	9	56	32	97
INSULATE - UNRESTRICTED ATTIC R11 TO R30	963	759	767	2489
INSULATE - UNRESTRICTED ATTIC R11 TO R36	6	1	3	10
INSULATE - UNRESTRICTED ATTIC R11 TO R38	279	312	298	889
INSULATE - UNRESTRICTED ATTIC R8 TO R19		1	2	3
INSULATION TRUCK SET-UP FEE (LESS THAN	4	1	27	32
INSULATION TRUCK SET-UP FEE (601 - 900 S	526	497	510	1533
INSULATION TRUCK SET-UP FEE (901 - 1200	452	418	433	1303
INSULATION TRUCK SET-UP FEE (GRTR THAN 1	268	126	105	499
LED - REPLACE INCANDESCENT WITH 11W BR30	1406	1930	2988	6324
LED - REPLACE INCANDESCENT WITH 8.5W A19	2032	1508	134	3674
LED NIGHT LIGHTS	1629	2050	2239	5918
MOBILE HOME - FIBERGLASS BLOW BELLY R-19	20	7	14	41
MOBILE HOME - INSTALL PLEXIGLASS	7	9	8	24
MOBILE HOME - RECONN ROUND DUCT 3 SCREWS	3	5	3	11
MOBILE HOME - REPAIR BELLY RUPTURES HOLE	35	12	17	64
MOBILE HOME - REPAIR SUBFLOOR	16	36	14	66
MOBILE HOME - REPL MISSING WALL FLOOR CE			2	2
MOBILE HOME - SEAL AROUND A/C UNIT	14	5	23	42
SHOWERHEAD - INSTALL LOW FLOW	89	38	30	157
SHOWERHEAD - INSTALL LOW FLOW HAND HELD	2442	2447	2102	6991
SMART STRIP SURGE PROTECTOR - INSTALLATI	1891	2258	1980	6129
THERMOSTAT - PROGRAMMABLE (HONEYWELL FP6	1		2	3
THERMOSTAT - PROGRAMMABLE (LIGHTSTAT)		2	1	3
THERMOSTAT (EASY TO READ)	723	595	581	1899
VENTING - INSTALL BATHROOM VENTILATION F	3	2	1	6
VENTING - INSTALL DRYER VENTILATION FAN	2	3	2	7
WATER HEATER - DWH TEMP REDUCTION TO 120	32	1	1	34
WATER HEATER - INSULATE PIPES 8 FT FROM	10	47	58	115

Case No. 2022-00402 Attachment to Response to JI-2 Question No. 89(b) Page 3 of 6 Isaacson

WATER HEATER - LEAK REPAIR BATHROOM FAUC	2	1	4	7
WATER HEATER - LEAK REPAIR KITCHEN FAUCE		2	5	7
WATER HEATER - PIPE INSULATION (PER LINE	4	1	14	19
WATER HEATER - WRAP DWH W INSULATION BLA	11	9	32	52
WINDOW - DOUBLE PANE WOOD WINDOW REPLACE	41	30	73	144
WINDOW - GENERAL REPLACEMENT	173	97	111	381
WINDOW - INSTALL INTERIOR WINDOW KIT	546	589	214	1349
WINDOW - INSTALL STORM WINDOW	1	1	4	6
WINDOW - REPLACE WINDOW W DOUBLE PANE GL	17	22	46	85
WINDOW - REPLACE WINDOW W DOUBLE PANE WO	1	5	6	12
WINDOW - REPLACE WINDOW W SINGLE PANE GL	29	42	40	111
WINDOW - REPLACE WINDOW W SINGLE PANE WO	179	104	76	359
WINDOW AC - REMOVAL OF SECONDARY UNIT		2	5	7
WINDOW AC 10000 BTUH; 10.8 EER - INSTALL	3	72	18	93
WINDOW AC 12000 BTUH; 10.8 EER - INSTALL	6	4	23	33
WINDOW AC 15000 BTUH; 10.7 EER - INSTALL	2	1	7	10
WINDOW AC 6000 BTUH; 11.2 EER - INSTALLA	30	16	10	56
WINDOW AC 8000 BTUH; 10.8 EER - INSTALLA	14	19	11	44
Grand Total	27412	30130	28388	85930

Case No. 2022-00402 Attachment to Response to JI-2 Question No. 89(b) Page 4 of 6 Isaacson Year Installed 2020 2021 2022 Grand Total

Installed Measure				
5.5 INCH (DENSE PACK)	0.00%	0.00%	0.01%	0.00%
AERATOR - INSTALL LOW FLOW AERATOR - BAT	4.13%	2.09%	2.11%	2.75%
AERATOR - INSTALL LOW FLOW AERATOR - KIT	7.14%	6.21%	3.67%	5.67%
AIR SEALING - BLOWER DOOR GUIDED	6.37%	7.94%	8.77%	7.71%
ATTIC - BOXING AND DAMMING ATTIC ACCESS	0.03%	0.01%	0.02%	0.02%
ATTIC - BOXING AND DAMMING HEAT PRODUCIN	0.00%	0.02%	0.02%	0.01%
ATTIC - CREATE HATCH COVER - INSULATED &	1.09%	1.22%	1.47%	1.26%
ATTIC - CREATE HATCH INTERIOR GREATER TH	0.16%	0.06%	0.08%	0.10%
ATTIC - CREATE HATCH INTERIOR LESS THAN	0.14%	0.07%	0.10%	0.10%
ATTIC - INTERIOR ATTIC STAIR COVER	0.00%	0.02%	0.00%	0.01%
ATTIC - PULL DOWN STAIR COVER - BUILT ON	0.15%	0.16%	0.25%	0.19%
ATTIC - PULL DOWN STAIR COVER - PRE-FAB	0.00%	0.00%	0.00%	0.00%
BLDG REPAIR - DRYWALL REPLACEMENT (FINIS	0.08%	0.31%	0.21%	0.21%
BLDG REPAIR - FLOORING REPLACEMENT (FINI	0.02%	0.01%	0.02%	0.02%
BLDG REPAIR - FLOORING REPLACEMENT (PLYW	0.00%	0.03%	0.05%	0.03%
CO DETECTOR - INSTALLATION	4.62%	4.81%	2.62%	4.03%
CONTRACTOR - GAS LEAK REPAIR FEE (HRLY L	0.00%	0.00%	0.00%	0.00%
CONTRACTOR - GENERAL LABOR (HRLY LABOR)	0.82%	2.10%	1.01%	1.33%
CONTRACTOR - SERVICE VISIT (QUOTE)	3.57%	3.35%	3.76%	3.56%
CONTRACTOR - SPECIALTY OR MAJOR ISSUES (	0.00%	0.00%	0.00%	0.00%
CRAWL SPACE - AIR SEAL AND INSULATE WALL	0.00%	0.00%	0.01%	0.01%
CRAWL SPACE - FLOOR COVERING	0.00%	0.00%	0.00%	0.00%
CRAWL SPACE - INSTALL 6 MILL VAPOR BARRI	0.00%	0.00%	0.00%	0.00%
CRAWL SPACE - INSTALL CEILING/FLOOR INSU	0.16%	0.09%	0.18%	0.14%
CRAWL SPACE - INSTALL VENT CLOSER	0.01%	0.02%	0.00%	0.01%
CRAWL SPACE - PERIMETER INSULATION (RIM	0.09%	0.05%	0.07%	0.07%
DOOR - INSTALL DOOR SWEEP	3.97%	6.14%	6.81%	5.67%
DOOR - REPLACE EXT DOOR W CUSTOM MADE	0.01%	0.01%	0.01%	0.01%
DOOR - REPLACE LOCKSET	1.72%	1.38%	1.43%	1.50%
DOOR - REPLACE PRIMARY EXT DOOR W SOLID	2.89%	3.31%	4.11%	3.44%
DOOR - WEATHER STRIPPING KIT - GENERAL	5.19%	7.56%	7.90%	6.92%
DUCT - SEAL/INSTALL INSULATION TO R6 EQU	0.01%	0.01%	0.02%	0.02%
DUCT - SEALING (DUCT BLASTER GUIDED OR E	1.03%	1.14%	1.36%	1.18%
DUCT - WRAP	0.00%	0.02%	0.00%	0.01%
FAUCET - REPLACE FAUCET - BATHROOM SINK	0.01%	0.05%	0.06%	0.04%
FAUCET - REPLACE FAUCET - KITCHEN SINK	0.03%	0.08%	0.04%	0.05%
FILTER - CLEAN/REPLACE HVAC FILTER	1.38%	1.07%	0.75%	1.06%
FILTER - CLEAN/REPLACE WINDOW AC FILTER	0.01%	0.00%	0.01%	0.01%
FLUE - REPAIR	0.03%	0.21%	0.11%	0.12%
FRIDGE - REPLACE WITH ENERGY STAR 15 CU	0.08%	0.03%	0.00%	0.03%

**Count of Enrollment ID** 

Case No. 2022-00402

Attachment to Response to JI-2 Question No. 89(b)

Page 5 of 6

				Page 5 01 6
				Isaacson
FRIDGE - REPLACE WITH ENERGY STAR 17 CU	0.35%	0.24%	0.11%	0.23%
FRIDGE - REPLACE WITH ENERGY STAR 18 CU	0.58%	0.68%	0.58%	0.62%
FRIDGE - REPLACE WITH ENERGY STAR 21 CU	0.39%	0.22%	0.07%	0.23%
GABLE VENT INSTALLED	0.01%	0.00%	0.00%	0.00%
HVAC - COOLING - TUNE-UP (PER SYSTEM)	0.50%	0.39%	1.92%	0.93%
HVAC - HEATING - REPAIR SYSTEM (PARTS)	0.01%	0.00%	0.00%	0.01%
HVAC - HEATING - REPLACE SYSTEM (HRLY LA	0.01%	0.00%	0.00%	0.00%
HVAC - HEATING - TUNE-UP (PER SYSTEM)	1.75%	1.56%	3.67%	2.32%
INSULATE - INSTALL 1 INCH INSULATION BOA	0.00%	0.00%	0.01%	0.00%
INSULATE - INSTALL 1/2 INCH INSULATION B	0.00%	0.00%	0.01%	0.00%
INSULATE - INSTALL 2 INCH INSULATION BOA	0.00%	0.01%	0.03%	0.01%
INSULATE - RIM JOIST	0.05%	0.04%	0.03%	0.04%
INSULATE - UNINSULATED FLOORED ATTIC TO	0.00%	0.01%	0.00%	0.00%
INSULATE - UNINSULATED KNEEWALLS TO R11	0.01%	0.02%	0.01%	0.02%
INSULATE - UNINSULATED KNEEWALLS TO R13	0.08%	0.05%	0.08%	0.07%
INSULATE - UNINSULATED KNEEWALLS TO R19	0.06%	0.03%	0.05%	0.05%
INSULATE - UNINSULATED SLOPE CEILING TO	0.02%	0.01%	0.04%	0.02%
INSULATE - UNINSULATED WALLS 3.5 INCH (F	0.42%	0.21%	0.26%	0.30%
INSULATE - UNRESTRICTED ATTIC R11 TO R26	0.03%	0.19%	0.11%	0.11%
INSULATE - UNRESTRICTED ATTIC R11 TO R30	3.51%	2.52%	2.70%	2.90%
INSULATE - UNRESTRICTED ATTIC R11 TO R36	0.02%	0.00%	0.01%	0.01%
INSULATE - UNRESTRICTED ATTIC R11 TO R38	1.02%	1.04%	1.05%	1.03%
INSULATE - UNRESTRICTED ATTIC R8 TO R19	0.00%	0.00%	0.01%	0.00%
INSULATION TRUCK SET-UP FEE (LESS THAN	0.01%	0.00%	0.10%	0.04%
INSULATION TRUCK SET-UP FEE (601 - 900 S	1.92%	1.65%	1.80%	1.78%
INSULATION TRUCK SET-UP FEE (901 - 1200	1.65%	1.39%	1.53%	1.52%
INSULATION TRUCK SET-UP FEE (GRTR THAN 1	0.98%	0.42%	0.37%	0.58%
LED - REPLACE INCANDESCENT WITH 11W BR30	5.13%	6.41%	10.53%	7.36%
LED - REPLACE INCANDESCENT WITH 8.5W A19	7.41%	5.00%	0.47%	4.28%
LED NIGHT LIGHTS	5.94%	6.80%	7.89%	6.89%
MOBILE HOME - FIBERGLASS BLOW BELLY R-19	0.07%	0.02%	0.05%	0.05%
MOBILE HOME - INSTALL PLEXIGLASS	0.03%	0.03%	0.03%	0.03%
MOBILE HOME - RECONN ROUND DUCT 3 SCREWS	0.01%	0.02%	0.01%	0.01%
MOBILE HOME - REPAIR BELLY RUPTURES HOLE	0.13%	0.04%	0.06%	0.07%
MOBILE HOME - REPAIR SUBFLOOR	0.06%	0.12%	0.05%	0.08%
MOBILE HOME - REPL MISSING WALL FLOOR CE	0.00%	0.00%	0.01%	0.00%
MOBILE HOME - SEAL AROUND A/C UNIT	0.05%	0.02%	0.08%	0.05%
SHOWERHEAD - INSTALL LOW FLOW	0.32%	0.13%	0.11%	0.18%
SHOWERHEAD - INSTALL LOW FLOW HAND HELD	8.91%	8.12%	7.40%	8.14%
SMART STRIP SURGE PROTECTOR - INSTALLATI	6.90%	7.49%	6.97%	7.13%
THERMOSTAT - PROGRAMMABLE (HONEYWELL FP6	0.00%	0.00%	0.01%	0.00%
THERMOSTAT - PROGRAMMABLE (LIGHTSTAT)	0.00%	0.01%	0.00%	0.00%
THERMOSTAT (EASY TO READ)	2.64%	1.97%	2.05%	2.21%
VENTING - INSTALL BATHROOM VENTILATION F	0.01%	0.01%	0.00%	0.01%
VENTING - INSTALL DRYER VENTILATION FAN	0.01%	0.01%	0.01%	0.01%
WATER HEATER - DWH TEMP REDUCTION TO 120	0.12%	0.00%	0.00%	0.04%
WATER HEATER - INSULATE PIPES 8 FT FROM	0.04%	0.16%	0.20%	0.13%

WATER HEATER - LEAK REPAIR BATHROOM FAUC 0.01% 0.00% 0.01% 0.01% WATER HEATER - LEAK REPAIR KITCHEN FAUCE 0.01% 0.02% 0.01% 0.00% WATER HEATER - PIPE INSULATION (PER LINE 0.01% 0.00% 0.05% 0.02% WATER HEATER - WRAP DWH W INSULATION BLA 0.04% 0.03% 0.06% 0.11% WINDOW - DOUBLE PANE WOOD WINDOW REPLACE 0.15% 0.10% 0.26% 0.17% WINDOW - GENERAL REPLACEMENT 0.39% 0.63% 0.32% 0.44% WINDOW - INSTALL INTERIOR WINDOW KIT 1.99% 1.95% 0.75% 1.57% WINDOW - INSTALL STORM WINDOW 0.00% 0.00% 0.01% 0.01% WINDOW - REPLACE WINDOW W DOUBLE PANE GL 0.06% 0.07% 0.16% 0.10% WINDOW - REPLACE WINDOW W DOUBLE PANE WO 0.00% 0.02% 0.02% 0.01% WINDOW - REPLACE WINDOW W SINGLE PANE GL 0.11% 0.14% 0.14% 0.13% WINDOW - REPLACE WINDOW W SINGLE PANE WO 0.27% 0.42% 0.65% 0.35% WINDOW AC - REMOVAL OF SECONDARY UNIT 0.00% 0.01% 0.02% 0.01% WINDOW AC 10000 BTUH; 10.8 EER - INSTALL 0.01% 0.24% 0.06% 0.11% WINDOW AC 12000 BTUH; 10.8 EER - INSTALL 0.02% 0.01% 0.08% 0.04% WINDOW AC 15000 BTUH; 10.7 EER - INSTALL 0.00% 0.01% 0.02% 0.01% WINDOW AC 6000 BTUH; 11.2 EER - INSTALLA 0.11% 0.05% 0.04% 0.07% WINDOW AC 8000 BTUH; 10.8 EER - INSTALLA 0.05% 0.06% 0.04% 0.05% **Grand Total** 100.00% 100.00% 100.00% 100.00%

Case No. 2022-00402 Attachment to Response to JI-2 Question No. 89(b) Page 6 of 6 Isaacson