

Year	Pole Number	Owner	Class	Height	Manufacturer	Species	OriginalTreatment	DecayCode	Inspection Code	Rejection Code	Date Inspected
2021	PO2709405765	KU		5	35 BRN	SP	CRE	ED,ID	BX	RP1	1/4/2021
2021	PO2682205182	KU		4	40 BRN	SP	CRE	ED,ID	BX	RP1	1/5/2021
2021	PO2655503915	KU		4	40 BRN	SP	CRE	ED,ID,RB	BX	PX	1/6/2021
2021	PO5707800725	F		3	40 BRO	SP	P		V		1/7/2021
2021	PO5701900672	KU		5	35 BRO	SP	CCA		V		1/8/2021
2021	PO5690100754	KU		3	40 BRO	SP	CCA	ED	TD		1/9/2021
2021	PO5708100488	F		7	40 BRO	SP	CRE		V		1/10/2021
2021	PO5714400514	F		4	40 BRO	SP	CRE		V		1/11/2021
2021	PO4129385848	LGE		6	25 BRN	SP	CRE	ID,IP,SRS	TD		1/12/2021
2021	PO4129385855	LGE		4	40 BRN	SP	CCA	ID,IP	TD		1/13/2021
2021	PO0811759451	F		4	40 BRO	SP	CRE		V		1/14/2021
2021	PO0802260179	KU		5	35 BRO	SP	CRE	ED,ID	BD		1/15/2021
2021	PO0805160321	KU		5	35 BRO	SP	CCA		V		1/16/2021
2021	PO0781160267	KU		3	45 BRO	SP	CCA		V		1/17/2021
2021	PO0770060544	KU		4	40 BRO	SP	CCA		V		1/18/2021
2021	PO5005004613	F		5	35 OTH	SP	CRE		V		1/19/2021
2021	PO5007004827	F		4	45 OTH	SP	CCA		V		1/20/2021
2021	PO5014204544	F		4	40 XXX	SP	CRE		V		1/21/2021
2021	PO2332003418	KU		3	45 UNK	SP	CCA		V		1/22/2021
2021	PO2290402119	KU		5	40 UNK	SP	CRE	ID,IP	BD		1/23/2021
2021	PO9489469430	KU		5	30 BRO	SP	CRE	ED,ID	TD		1/24/2021
2021	PO9489269313	F		6	30 BRO	SP	S		V		1/25/2021
2021	PO9490469211	F		4	40 BRO	SP	CRE		V		1/26/2021
2021	PO2852503791	KU		4	40 BRN	SP	CRE	ED,ID	TD		1/27/2021
2021	PO4127885855	LGE		4	40 BRN	SP	CRE	ID,SRS	TD		1/28/2021
2021	PO4127985849	LGE		3	25 BRN	SP	CRE	ID,SRS	TD		1/29/2021
2021	PO5022504483	F		4	40 XXX	SP	CRE		V		1/30/2021
2021	PO5028804434	F		4	40 XXX	SP	CRE		V		1/31/2021
2021	PO9664669807	KU		4	40 BRO	SP	CRE	ED,ID	TD		2/1/2021
2021	PO2821103635	KU		3	40 BRN	SP	S		V		2/2/2021
2021	PO2301002000	KU		4	45 UNK	SP	CRE	ID,IP	TD		2/3/2021
2021	PO4178086470	LGE		4	35 BRO	SP	A	ED,ID,IP	TD		2/4/2021
2021	PO5008705432	F		4	40 XXX	SP	CRE		V		2/5/2021
2021	PO4997204898	C		6	30 XXX	SP	CRE		V		2/6/2021
2021	PO5000604933	F		4	45 KOP	SP	P		V		2/7/2021
2021	PO5002904866	F		5	35 OTH	SP	CCA		V		2/8/2021
2021	PO5015605100	KU		6	30 XXX	SP	CRE	ED,ID	TD		2/9/2021
2021	PO5021505212	KU		6	30 BRN	SP	CCA		V		2/10/2021
2021	PO4176686464	LGE		4	35 BRO	SP	CRE	ED,ID	TD		2/11/2021
2021	PO4133485871	LGE		4	35 BRN	SP	P	ID	TD		2/12/2021
2021	PV8488070387	F		3	50 BRN	SP	P		V		2/13/2021
2021	PO4134885859	F		3	50 BRN	SP	CCA		V		2/14/2021
2021	PO4134885860	F		3	50 BRN	SP	P		V		2/15/2021
2021	PO1455612725	KU		3	45 BRN	SP	CCA		V		2/16/2021
2021	PO1456012643	KU		5	35 BRN	WC	CRE		B		2/17/2021
2021	PO1396412665	KU		4	40 BRN	SP	CRE		V		2/18/2021
2021	PO1413012395	KU		4	40 BRN	SP	CRE		V		2/19/2021
2021	PO1437111481	KU		3	45 BRN	SP	CCA		B		2/20/2021
2021	PO1496611405	KU		4	40 BRN	SP	CCA		B		2/21/2021
2021	PO1466811443	KU		3	40 BRN	SP	CCA		B		2/22/2021
2021	PO4176986459	LGE		4	35 BRO	SP	A	ED,ID,IP	TD		2/23/2021
2021	PO4134985871	LGE		4	35 BRN	SP	P	ID,IP,RB	TX	RR	2/24/2021
2021	PO4177086453	LGE		4	40 BRO	SP	CRE	ID,IP	BD		2/25/2021

2021 PO4134885876	F	3	50 BRN	SP	CRE		V	2/26/2021
2021 PO4135085879	LGE	3	45 BRN	SP	P	ID	BD	2/27/2021
2021 PO5745500413	KU	3	45 BRO	SP	CRE	ED	BD	2/28/2021
2021 PO5763000597	KU	7	35 BRO	SP	CRE		B	3/1/2021
2021 PO5766000954	KU	3	40 BRO	SP	CCA	ED	TD	3/2/2021
2021 PO5777800763	KU	3	40 BRO	SP	CRE	ED,HH,ID,RB	X PX	3/3/2021
2021 PO9678069667	KU	6	30 STP	SP	CCA		V	3/4/2021
2021 9686069526A	KU	5	35 STP	SP	CRE	ED,ID	TD	3/5/2021
2021 PO9686069526	KU	5	30 STP	SP	CRE	ED,ID	BD	3/6/2021
2021 PO4177886446	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	3/7/2021
2021 PO4135185948	F	3	50 BRN	SP	CRE		V	3/8/2021
2021 PO4134085953	LGE	4	40 BRN	SP	P		V	3/9/2021
2021 PO4135285963	F	3	55 BRN	SP	CRE		V	3/10/2021
2021 PO4132985963	F	4	40 BRN	SP	P		V	3/11/2021
2021 PO4132485955	F	4	40 BRN	SP	CRE		V	3/12/2021
2021 PO9732868862	KU	6	30 STP	SP	CRE	ED,ID	TD	3/13/2021
2021 PO4179686448	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	3/14/2021
2021 PO4133785943	LGE	3	40 BRN	SP	CRE	ED,IP,SRC	TX RR	3/15/2021
2021 PO4133785942	LGE	3	45 BRN	SP	CCA		V	3/16/2021
2021 PO4133385936	LGE	4	35 BRN	SP	CCA		V	3/17/2021
2021 PO4132985935	LGE	4	35 BRN	SP	CCA		V	3/18/2021
2021 PO4131985946	F	4	40 BRN	SP	CRE	ED,EP	V	3/19/2021
2021 PO4131485938	F	3	45 BRN	SP	CCA		V	3/20/2021
2021 PO4128885888	LGE	4	40 BRN	SP	CRE	ID,IP	TD	3/21/2021
2021 PO9732169042	KU	4	45 STP	SP	CRE	ED,ID	TD	3/22/2021
2021 PO9770068829	KU	6	30 STP	SP	CRE	ED,EP,ID,IP	TX RR	3/23/2021
2021 PO0717061853	KU	3	45 BRO	SP	CCA		V	3/24/2021
2021 PO1476412318	F	4	40 BRN	SP	CRE		V	3/25/2021
2021 PO1526011466	KU	4	40 BRN	SP	CCA		B	3/26/2021
2021 PO1459312232	F	5	35 BRN	SP	CRE		V	3/27/2021
2021 A1	F	4	40 BRN	SP	CRE		V	3/28/2021
2021 PO1433112146	F	4	40 BRN	SP	CRE		V	3/29/2021
2021 PO1408812073	F	4	45 BRN	SP	CRE		V	3/30/2021
2021 PO1330012283	KU	5	35 BRN	WC	CRE	ID	BD	3/31/2021
2021 PO1383911998	F	3	40 BRN	SP	CRE		V	4/1/2021
2021 PO1362911992	F	4	40 BRN	SP	CRE		V	4/2/2021
2021 PO1335612117	F	4	40 BRN	WC	CRE		V	4/3/2021
2021 PO1283812176	F	5	35 BRN	WC	CRE		V	4/4/2021
2021 PO1305712268	F	4	40 BRN	WC	CRE		V	4/5/2021
2021 PO4179386450	LGE	2	45 BRO	SP	CRE	ID,IP	BD	4/6/2021
2021 PO2292401222	F	4	40 UNK	SP	P		V	4/7/2021
2021 PO2309001064	F	4	40 UNK	SP	P		V	4/8/2021
2021 PO2324000931	F	3	40 UNK	SP	P		V	4/9/2021
2021 PO2311700894	F	5	30 UNK	SP	CRE		V	4/10/2021
2021 PO2662904247	KU	4	45 BRN	SP	S		V	4/11/2021
2021 PO2351000733	KU	3	40 UNK	SP	P	ED,ID,IP	TD	4/12/2021
2021 PO4179686445	LGE	3	45 BRO	SP	A	ID,IP	BD	4/13/2021
2021 PO2605203893	KU	4	40 BRN	SP	S		V	4/14/2021
2021 PO5726900266	F	6	40 BRO	SP	CRE		V	4/15/2021
2021 PO5722000216	F	4	40 BRO	SP	CRE		V	4/16/2021
2021 PO5731700065	F	7	30E BRO	SP	CRE		V	4/17/2021
2021 PO5737900102	F	3	40 BRO	SP	CRE		V	4/18/2021
2021 PO5749999947	F	6	35E BRO	SP	CRE		V	4/19/2021
2021 PO5778699775	F	3	40 BRO	SP	CRE		V	4/20/2021

2021 PO2414100361	KU	4	40 UNK	SP	CRE	ID	TD	4/21/2021	
2021 PO9773868934	KU	4	40 STP	SP	S		V	4/22/2021	
2021 PO9861268599	KU	4	40 STP	SP	CRE	ED,ID	TD	4/23/2021	
2021 PO9832968661	KU	5	35 STP	SP	CRE	ED,ID	TD	4/24/2021	
2021 PO9818868790	KU	4	40 STP	SP	CRE	ED,ID	TD	4/25/2021	
2021 PO9797768874	KU	4	40 STP	SP	CRE	ED,ID	TD	4/26/2021	
2021 PO2548103510	KU	4	40 BRN	SP	CRE		V	4/27/2021	
2021 PO2571803666	KU	4	40 BRN	SP	CRE		V	4/28/2021	
2021 PO2593003813	KU	4	40 BRN	SP	CRE		V	4/29/2021	
2021 PO5795099110	KU	7	30E BRO	SP	CRE	ED	TD	4/30/2021	
2021 PO5761299690	F	6	35E BRO	SP	CRE		V	5/1/2021	
2021 PO5766599733	F	3	40 BRO	SP	CRE		V	5/2/2021	
2021 PO5780299556	F	5	40 BRO	SP	CCA		V	5/3/2021	
2021 PO5780899451	KU	7	35 BRO	SP	CRE	ED,ID	TD	5/4/2021	
2021 PO5787399147	KU	7	30 BRO	SP	CRE	ED,ID	TD	5/5/2021	
2021 PO5810999021	F	7	30E BRO	SP	CRE		V	5/6/2021	
2021 PO5796399245	F	6	30 BRO	SP	CRE		V	5/7/2021	
2021 PO0671862252	F	4	40 BRO	SP	CRE		V	5/8/2021	
2021 PO0673162340	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/9/2021	
2021 PO2473000056	KU	4	45 UNK	SP	CRE	ED,ID	TD	5/10/2021	
2021 PO2435000250	KU	4	40 UNK	SP	CRE	ID	TD	5/11/2021	
2021 2473000056-A	KU	6	30 UNK	SP	CRE	HH,ID	X	PX	5/12/2021
2021 PO9822068913	KU	6	30 STP	SP	CRE	ED,ID	TD	5/13/2021	
2021 PO4181086416	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	5/14/2021	
2021 PO5042904782	F	4	40 OTH	SP	CRE		V	5/15/2021	
2021 PO5029104882	F	4	40 OTH	SP	CRE		V	5/16/2021	
2021 PO5017904968	F	4	45 OTH	SP	CCA		V	5/17/2021	
2021 PO5026405083	F	4	40 KOP	SP	CRE		V	5/18/2021	
2021 PO5029305325	F	6	30 BRN	SP	CRE		V	5/19/2021	
2021 PO5044305128	KU	5	35 XXX	SP	CRE	ED,ID	TD	5/20/2021	
2021 PO5031705154	F	4	40 KOP	SP	A		V	5/21/2021	
2021 PO5038705246	F	3	50 BRN	SP	CCA		V	5/22/2021	
2021 PO5046405338	F	4	40 KOP	SP	A		V	5/23/2021	
2021 PO2704602396A	KU	2	50 BRN	SP	CCA		V	5/24/2021	
2021 PO0651762372	KU	4	40 BRO	SP	CRE		B	5/25/2021	
2021 PO0640662054	KU	6	30 BRO	SP	CRE	ID	BD	5/26/2021	
2021 PO9841868681	KU	4	40 STP	SP	CRE	ED,ID	TD	5/27/2021	
2021 PO2697902244	F	4	40 BRN	SP	CCA		V	5/28/2021	
2021 PO2743703325	F	3	45 BRN	SP	CCA		V	5/29/2021	
2021 PO2755603606	F	4	40 BRN	SP	CCA		V	5/30/2021	
2021 PO2723202843	F	4	40 BRN	SP	CCA		V	5/31/2021	
2021 PO2734003091	F	3	45 BRN	SP	CCA		V	6/1/2021	
2021 PO2704602396	F	3	45 BRN	SP	CCA		V	6/2/2021	
2021 PO2711302375	KU	4	40 BRN	SP	CCA		V	6/3/2021	
2021 PO2690102062	F	4	40 BRN	SP	CCA		V	6/4/2021	
2021 PO2680901847	F	4	40 BRN	SP	CCA		V	6/5/2021	
2021 PO0635662123	KU	4	40 BRO	SP	CRE	ED,ID	BD	6/6/2021	
2021 PO4181186434	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	6/7/2021	
2021 PO4132485919	F	4	40 BRN	SP	CRE		V	6/8/2021	
2021 PO4129285901	LGE	4	40 BRN	SP	CRE	ID,IP	TD	6/9/2021	
2021 PO4129785910	LGE	4	40 BRN	SP	CRE	ID,IP	TD	6/10/2021	
2021 2205701090-A	KU	6	30 UNK	SP	CRE	ID	BD	6/11/2021	
2021 PO2205701090	KU	3	55 UNK	SP	CRE	ID	BD	6/12/2021	
2021 PO2203101108	KU	3	55 UNK	SP	CRE	ID,SRS	TD	6/13/2021	

2021 PO4126785855	LGE	4	40 BRN	SP	CRE	ID,IP,SRC	TX	RR	6/14/2021
2021 PO4134985883	F	3	50 BRN	SP	P	ED,ID,RB	BX	RP1	6/15/2021
2021 PO2176601293	KU	4	40 UNK	SP	CRE	ED,ID	BD		6/16/2021
2021 PO9859568606	KU	4	40 STP	SP	CCA		V		6/17/2021
2021 PO9854468454	KU	2	60 STP	SP	P		V		6/18/2021
2021 9904268375A	KU	4	40 STP	SP	S		V		6/19/2021
2021 PO9904268375	KU	2	65 STP	ST	P		V		6/20/2021
2021 PO4130385920	F	4	40 BRN	SP	CRE		V		6/21/2021
2021 PO4130885929	F	4	40 BRN	SP	CRE		V		6/22/2021
2021 PO4132085925	F	4	40 BRN	SP	CRE		V		6/23/2021
2021 PO4132485909	F	4	40 BRN	SP	CCA		V		6/24/2021
2021 PO4132085900	F	4	40 BRN	SP	CRE		V		6/25/2021
2021 PO4132085891	F	4	40 BRN	SP	CRE		V		6/26/2021
2021 PO4131985880	F	4	40 BRN	SP	CRE		V		6/27/2021
2021 PO4132485872	F	4	30 BRN	SP	CRE		V		6/28/2021
2021 PO4144085121	LGE	4	40 BRN	SP	CRE	ID	BD		6/29/2021
2021 PO4144385101	LGE	4	30 BRN	SP	CRE		V		6/30/2021
2021 PO4144585101	LGE	4	40 BRN	SP	CRE		V		7/1/2021
2021 PO4181386420	LGE	4	40 BRO	SP	CCA		V		7/2/2021
2021 PO4180786420	LGE	3	55 BRO	SP	CRE	ID,IP	BD		7/3/2021
2021 PO9924268160	KU	4	40 STP	SP	CRE	ED,ID	BD		7/4/2021
2021 PO9938068317	KU	2	70 STP	SP	CRE		V		7/5/2021
2021 PO5794699361	F	3	40 BRO	SP	CCA		V		7/6/2021
2021 PO5810899347	F	6	35 BRO	SP	CRE		V		7/7/2021
2021 PO5808499181	F	3	40E BRO	SP	CRE		V		7/8/2021
2021 PO9981268262	KU	6	30 STP	SP	CRE	ED,ID	TD		7/9/2021
2021 PO9979368214	KU	2	70 STP	SP	CRE		V		7/10/2021
2021 PO9971768197	KU	4	40 STP	SP	CRE	ED,ID	TD		7/11/2021
2021 PO4180386430	LGE	3	55 BRO	SP	CRE	ED,ID,IP	TD		7/12/2021
2021 PO2171800607	KU	4	40 UNK	SP	CRE	ID	TD		7/13/2021
2021 PO9985568138	KU	4	40 STP	SP	CRE	ED,ID	TD		7/14/2021
2021 PO0000768148	KU	4	40 STP	SP	CCA		V		7/15/2021
2021 PO0008568121	KU	3	50 STP	ST	CRE		V		7/16/2021
2021 PO4925805109	F	6	35 XXX	SP	CRE		V		7/17/2021
2021 PO4949105137	KU	6	30 XXX	SP	CRE	ED,ID	TD		7/18/2021
2021 PO2788803488	KU	4	45 BRN	SP	CRE	ED,ID,RB	TX	RR	7/19/2021
2021 PO9705469902	KU	4	40 BRO	SP	CRE	ED,ID	BD		7/20/2021
2021 PO9676769867	KU	4	40 BRO	SP	CRE	ED,ID	BD		7/21/2021
2021 PO5672499922	F	4	40 BRO	SP	S		V		7/22/2021
2021 PO9665699955	KU	4	40 BRO	SP	S		V		7/23/2021
2021 PO5646500095	F	4	40 BRO	SP	CCA		V		7/24/2021
2021 PO5625000240	F	4	40 BRO	SP	CRE		V		7/25/2021
2021 PO5597900422	F	4	40 BRO	SP	S		V		7/26/2021
2021 PO5586600410	F	5	35 BRO	SP	CRE		V		7/27/2021
2021 PO5678000658	KU	4	40 BRO	SP	CCA	ED	TD		7/28/2021
2021 PO0752360982	KU	4	40 BRO	SP	CCA		V		7/29/2021
2021 PO0744861121	KU	4	40 BRO	SP	CCA		V		7/30/2021
2021 PO4126885864	LGE	4	40 BRN	SP	CRE	ID,IP,SRC	TX	RR	7/31/2021
2021 PO2867906363	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/1/2021
2021 PO4210286374	LGE	4	35 ACE	SP	CCA		V		8/2/2021
2021 PO4212186372	LGE	4	35 ACE	SP	CCA		V		8/3/2021
2021 PO4212786370	LGE	4	40 ACE	SP	CCA		V		8/4/2021
2021 PO4205286320	LGE	4	40 ACE	SP	CCA		V		8/5/2021
2021 PO4206586297	LGE	4	35 ACE	SP	CCA		V		8/6/2021



2021 PO4206886292	LGE	4	35 ACE	SP	CCA		V	8/7/2021
2021 PO4206586280	LGE	4	30 ACE	SP	CCA		V	8/8/2021
2021 PO4206486261	LGE	4	40 ACE	SP	CCA		V	8/9/2021
2021 PO4206686242	LGE	3	25 ACE	SP	A		V	8/10/2021
2021 PO4206586237	LGE	4	40 ACE	SP	CCA		V	8/11/2021
2021 PO4206586230	LGE	4	40 ACE	SP	CCA		V	8/12/2021
2021 PO4206586212	LGE	4	35 ACE	SP	CCA		V	8/13/2021
2021 PO4206586203	LGE	4	35 ACE	SP	CCA		V	8/14/2021
2021 PO4206586196	LGE	4	35 ACE	SP	CCA		V	8/15/2021
2021 PO4208186356	LGE	5	25 ACE	SP	A		V	8/16/2021
2021 PO4211386270	LGE	4	30 ACE	SP	CCA		V	8/17/2021
2021 PO4212086277	LGE	4	30 ACE	SP	CCA		V	8/18/2021
2021 PO4212486280	LGE	4	30 ACE	SP	CCA		V	8/19/2021
2021 PO4212986286	LGE	4	30 ACE	SP	CCA		V	8/20/2021
2021 PO4213186293	LGE	4	30 ACE	SP	CCA		V	8/21/2021
2021 PO4209986294	LGE	4	35 ACE	SP	CCA		V	8/22/2021
2021 PO4208586296	LGE	4	35 ACE	SP	CCA		V	8/23/2021
2021 PO4206786280	LGE	4	40 ACE	SP	CCA		V	8/24/2021
2021 PO4213186310	LGE	4	35 ACE	SP	CCA		V	8/25/2021
2021 PO4213686305	LGE	4	30 ACE	SP	CCA		V	8/26/2021
2021 PO4205186309	LGE	4	35 ACE	SP	CCA		V	8/27/2021
2021 PO4205586194	LGE	4	35 ACE	SP	CCA		V	8/28/2021
2021 PO4204486195	LGE	4	35 ACE	SP	CCA		V	8/29/2021
2021 PO4204386205	LGE	4	35 ACE	SP	CCA		V	8/30/2021
2021 PO4204686220	F	4	35 ACE	SP	CCA		V	8/31/2021
2021 PO4204986299	LGE	4	35 ACE	SP	CCA		V	9/1/2021
2021 PO4209086380	LGE	4	40 ACE	SP	CCA		V	9/2/2021
2021 PO4208486374	LGE	4	40 ACE	SP	CCA		V	9/3/2021
2021 PO4208186370	LGE	4	35 ACE	SP	CCA		V	9/4/2021
2021 PO9451669326	KU	5	35 BRO	SP	CRE	ED,ID	TD	9/5/2021
2021 PO4997404671	F	4	40 XXX	SP	CRE		V	9/6/2021
2021 PO4986504575	F	4	40 XXX	SP	CCA		V	9/7/2021
2021 PO4975404693	F	6	30 XXX	SP	CRE		V	9/8/2021
2021 PO4980004758	F	4	40 XXX	SP	CRE		V	9/9/2021
2021 PO4987004705	F	4	40 XXX	SP	CRE		V	9/10/2021
2021 PO4997804715	F	4	45 KOP	SP	P		V	9/11/2021
2021 PO4134685831	F	3	50 BRN	SP	CCA		V	9/12/2021
2021 PO4133285857	LGE	4	35 BRN	SP	CCA		V	9/13/2021
2021 PO5062385263	LGE	4	40 ACE	SP	P	ED	BD	9/14/2021
2021 PO8331484073	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	9/15/2021
2021 PO8306883935	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	9/16/2021
2021 PO8282283799	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	9/17/2021
2021 PO8261583759	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	9/18/2021
2021 PO8268983437	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	9/19/2021
2021 PO8279983057	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	9/20/2021
2021 PO4543187951	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	9/21/2021
2021 PO1933171198	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	9/22/2021
2021 PO1917570964	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	9/23/2021
2021 PO5064785276	LGE	3	45 ACE	SP	CCA		V	9/24/2021
2021 PO5064285283	LGE	4	30 ACE	SP	P	ED	BD	9/25/2021
2021 PO8013786673	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX PX	9/26/2021
2021 PO1596672026	LGE	3	45 BRO	SP	CCA		V	9/27/2021
2021 PO4447285955	LGE	4	35 BRO	SP	P	ED,EP,ID,IP	BD	9/28/2021
2021 PO0049496409	ODP	4	40 BRO	SP	CRE	ED,ID	TD	9/29/2021

2021 P00031596505	ODP	4	40 BRO	SP	CRE	ED,ID	BD	9/30/2021
2021 P00054196564	ODP	4	40 BRO	SP	CRE	ED,ID	TD	10/1/2021
2021 P00036796790	ODP	4	40 BRO	SP	CRE	ED,ID	BD	10/2/2021
2021 P00059796721	ODP	6	35 BRO	SP	CRE	ED,ID	TD	10/3/2021
2021 P00063096826	ODP	5	35 BRO	SP	CRE		V	10/4/2021
2021 P00078997122	ODP	6	35 BRO	SP	CRE		V	10/5/2021
2021 P04921789937	LGE	3	45 BRN	SP	P	ED,ID	TD	10/6/2021
2021 P07602043395	ODP	4	40 KOP	SP	CRE	ED	TD	10/7/2021
2021 P07573843528	ODP	5	30 KOP	SP	CRE	ED	BD	10/8/2021
2021 P07594643467	ODP	4	40 KOP	SP	CRE	ED	TD	10/9/2021
2021 P05539020033	F	4	35 OTH	SP	P		V	10/10/2021
2021 P05265922270	F	5	35 BRN	SP	CCA		V	10/11/2021
2021 P07784243520	F	4	40 KOP	SP	CRE		V	10/12/2021
2021 P07794143554	F	4	40 KOP	SP	CRE		V	10/13/2021
2021 P07797143469	F	4	40 KOP	SP	CRE		V	10/14/2021
2021 P08138742491	ODP	5	35 XXX	SP	P	ED,ID,IP	TD	10/15/2021
2021 P08142442556	ODP	5	30 XXX	SP	S		V	10/16/2021
2021 P08074641833	ODP	6	30 XXX	SP	CRE		V	10/17/2021
2021 P08078741752	ODP	4	40 XXX	SP	S		V	10/18/2021
2021 P08072941709	ODP	5	35 XXX	SP	S		V	10/19/2021
2021 P05543220071	KU	4	35 BRN	SP	CRE	ED,ID,IP	TD	10/20/2021
2021 P04708389715	F	3	45 ACE	SP	CRE		V	10/21/2021
2021 P04707189708	F	4	40 ACE	SP	CRE		V	10/22/2021
2021 P04704489692	F	4	40 ACE	SP	CRE		V	10/23/2021
2021 P07095941853	ODP	4	45 BRN	SP	CCA	ED,ID	TD	10/24/2021
2021 P07073741514	F	4	40 BRN	SP	CRE		V	10/25/2021
2021 P07078041726	ODP	6	30 BRN	SP	CRE	ID,IP	BD	10/26/2021
2021 P07072941601	ODP	4	45 BRN	SP	CCA	ED,ID	TD	10/27/2021
2021 P07093841634	ODP	4	45 BRN	SP	CCA	ED,ID	TD	10/28/2021
2021 P07094841946	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	10/29/2021
2021 P07295742644	ODP	6	30 KOP	SP	CCA		V	10/30/2021
2021 P07290242366	ODP	6	30 KOP	SP	S		V	10/31/2021
2021 P07283042219	ODP	6	30 KOP	SP	S		V	11/1/2021
2021 P09605991528	ODP	4	40 KOP	SP	CRE	ED,ID	TD	11/2/2021
2021 P09646091266	ODP	5	35 KOP	SP	CRE		V	11/3/2021
2021 P09654391452	ODP	4	45 KOP	SP	CCA		V	11/4/2021
2021 P09661291643	ODP	4	45 KOP	SP	CCA		V	11/5/2021
2021 P09642291610	ODP	4	45 KOP	SP	CCA		T	11/6/2021
2021 P09631691769	ODP	6	30 KOP	SP	CCA		V	11/7/2021
2021 P09636491884	ODP	4	40 KOP	SP	CRE	ED,ID	TD	11/8/2021
2021 P09665291790	ODP	4	45 KOP	SP	CCA		V	11/9/2021
2021 P09670891884	ODP	2	55 KOP	SP	CCA		V	11/10/2021
2021 P09683592238	ODP	4	40 KOP	SP	CRE	ED,ID	TD	11/11/2021
2021 P04875589928	LGE	3	45 BRN	SP	P		V	11/12/2021
2021 P04878089945	LGE	4	40 BRN	SP	P		V	11/13/2021
2021 P04878089943	LGE	4	40 BRN	SP	P		V	11/14/2021
2021 P04878089940	LGE	3	50 BRN	SP	P		V	11/15/2021
2021 P04878989924	LGE	4	40 BRN	SP	CRE		V	11/16/2021
2021 P05867112196	LGE	3	45 BRN	SP	P	ED,ID	BD	11/17/2021
2021 P04879989906	LGE	4	40 BRN	SP	CCA		V	11/18/2021
2021 P07280742041	ODP	5	35 KOP	SP	CCA		V	11/19/2021
2021 P07296042063	ODP	4	45 KOP	SP	CCA		V	11/20/2021
2021 P07320442092	ODP	2	50 KOP	SP	CCA		V	11/21/2021
2021 P07306141967	F	4	40 KOP	SP	CRE		V	11/22/2021

2021 PO7370541990	F	4	40 KOP	SP	CRE		V	11/23/2021
2021 PO4928988657	LGE	3	45 BRO	SP	CCA		V	11/24/2021
2021 PO5537021548	KU	3	45 KOP	SP	CCA		V	11/25/2021
2021 PO7762643514	ODP	4	45 BRN	SP	CCA		V	11/26/2021
2021 PO7726043289	ODP	4	40 BRN	SP	CRE	ED,ID	TD	11/27/2021
2021 PO7328150315	ODP	4	35 KOP	SP	CRE	ED,SRS	TD	11/28/2021
2021 PO7310350212	ODP	4	45 KOP	SP	CCA		V	11/29/2021
2021 PO7328150314	ODP	4	40 KOP	SP	CCA		V	11/30/2021
2021 PO8005546302	ODP	4	45 KOP	SP	CCA		V	12/1/2021
2021 PO7744043454	ODP	4	45 BRN	SP	CRE	ED,ID,IP	TD	12/2/2021
2021 PO7736643419	F	4	40 BRN	SP	CRE		V	12/3/2021
2021 PO7749743465	ODP	4	45 BRN	SP	CRE	ED,ID	TD	12/4/2021
2021 PO4889589086	LGE	4	30 BRO	SP	CCA		V	12/5/2021
2021 PO7358650082	ODP	4	45 KOP	SP	CCA		V	12/6/2021
2021 PO4956889681	LGE	3	50 BRN	SP	CRE	ED,ID	BD	12/7/2021
2021 PO4954589690	LGE	3	45 BRN	SP	A	ED,ID	BD	12/8/2021
2021 PO7319255475	ODP	4	40 KOP	SP	CRE	ED,ID	TD	12/9/2021
2021 PO7319755596	ODP	6	30 KOP	SP	CCA		T	12/10/2021
2021 PO7851243945	ODP	6	30 BRN	SP	CRE	ID	BD	12/11/2021
2021 PO5512011800	KU	6	30 BRN	SP	CRE		V	12/12/2021
2021 PO5503511693	KU	4	40 BRN	SP	CRE		V	12/13/2021
2021 PO5500211560	KU	4	40 BRN	SP	CRE	ID	BD	12/14/2021
2021 PO5510711721	KU	6	30 BRN	SP	CRE		V	12/15/2021
2021 PO5496111402	KU	4	40 BRN	SP	CRE	HH,ID,RB	BX	12/16/2021
2021 PO5492211245	KU	4	45 BRN	SP	CRE		V	12/17/2021
2021 PO7785943594	ODP	4	40 BRN	SP	CRE	ED,ID	TD	12/18/2021
2021 PO7827143742	ODP	4	45 BRN	SP	CRE	ED,ID,IP	TD	12/19/2021
2021 PO7791643615	ODP	4	40 BRN	SP	CRE	ED,ID	TD	12/20/2021
2021 PO7805243663	ODP	4	40 BRN	SP	CRE	ED,ID	TD	12/21/2021
2021 PO7842543799	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	12/22/2021
2021 PO7854443842	ODP	3	45 BRN	SP	CCA		V	12/23/2021
2021 PO7969743877	ODP	5	35 BRN	SP	CRE	ED,ID	TD	12/24/2021
2021 PO7982246362	ODP	6	30 BRO	SP	CRE	ID	BD	12/25/2021
2021 PO7966446445	ODP	6	30 BRO	SP	CRE	ED,ID,IP	TD	12/26/2021
2021 PO7966146381	ODP	6	30 BRO	SP	CRE	ID	BD	12/27/2021
2021 PO4950989703	LGE	3	50 BRN	SP	CRE	ED,ID	BD	12/28/2021
2021 PO4893889118	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	12/29/2021
2021 PO4952089698	LGE	3	50 BRN	SP	A	ED,ID	TD	12/30/2021
2021 PO4964689812	LGE	3	45 BRN	SP	P	ED,ID	BD	12/31/2021
2021 PO4965789823	LGE	1	50 BRN	SP	CCA		V	1/1/2022
2021 PO4968089845	LGE	3	45 BRN	SP	P	ED,ID	BD	1/2/2022
2021 PO4700089801	F	4	40 ACE	SP	P		V	1/3/2022
2021 PO7117341388a	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	1/4/2022
2021 PO7117341388	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	1/5/2022
2021 PO7321449773	ODP	4	40 KOP	SP	CRE	ED	TD	1/6/2022
2021 PO4699389797	F	4	30 ACE	SP	P		V	1/7/2022
2021 PO4053110963	F	4	30 ACE	SP	P		V	1/8/2022
2021 PO4696889864	F	4	40 ACE	SP	P		V	1/9/2022
2021 PO7940446686	ODP	5	30 BRO	SP	CCA		V	1/10/2022
2021 PO7306249592	ODP	3	45 KOP	SP	CCA		V	1/11/2022
2021 PO7291949774	ODP	4	40 KOP	SP	CRE	ED,SRC	TD	1/12/2022
2021 PO7947846803	ODP	4	40 BRO	SP	CCA		V	1/13/2022
2021 PO7966946826	ODP	5	30 BRO	SP	CRE	ID	BD	1/14/2022
2021 PO7945346618	ODP	4	45 BRO	SP	CCA		V	1/15/2022

2021	PO5427711869	KU	4	40 BRN	SP	CCA			V		1/16/2022
2021	PO5466511789	KU	4	40 BRN	SP	CRE	ID		BD		1/17/2022
2021	PO5481012320	KU	4	40 BRN	SP	CRE			V		1/18/2022
2021	PO5458211443	KU	4	40 BRN	SP	CRE			V		1/19/2022
2021	PO5477410667	KU	3	50 BRN	SP	S			V		1/20/2022
2021	PO5551322797	KU	3	45 BRN	SP	CRE	ED,ID,IP		TD		1/21/2022
2021	PO7964046770	ODP	4	40 BRO	SP	CCA			V		1/22/2022
2021	PO7968546697	ODP	5	30 BRO	SP	CRE	ED,ID		TD		1/23/2022
2021	PO5559222701	KU	3	45 BRN	SP	CRE	ED,ID,IP		TD		1/24/2022
2021	PO7284249274	ODP	6	30 KOP	SP	CCA	ED,SRS		TD		1/25/2022
2021	PO7293749457	ODP	4	40 KOP	SP	CRE	ED,ID		BD		1/26/2022
2021	PO5565922620	KU	2	50 BRN	SP	CCA			V		1/27/2022
2021	PO7982946755	ODP	6	35 BRO	SP	CRE	ED,ID,IP		BD		1/28/2022
2021	PO4697189849	F	4	40 ACE	SP	P			V		1/29/2022
2021	PO7999446728	ODP	4	45 BRO	SP	CCA			V		1/30/2022
2021	PO8000246827	ODP	4	40 BRO	SP	CCA			V		1/31/2022
2021	PO7985646852	ODP	5	30 BRO	SP	CCA			V		2/1/2022
2021	PO8024046262	ODP	4	40 BRO	SP	CCA			V		2/2/2022
2021	PO8038246472	ODP	4	40 BRO	SP	CCA			V		2/3/2022
2021	PO8031746653	ODP	4	40 BRO	SP	CCA			V		2/4/2022
2021	PO8029646752	ODP	4	40 BRO	SP	CCA			V		2/5/2022
2021	PO5573722527	KU	3	45 BRN	SP	CRE	ED,ID,IP,RB		BX	RP2	2/6/2022
2021	PO7822843984	ODP	6	30 BRO	SP	CCA			V		2/7/2022
2021	PO7832844056	ODP	2	45 BRN	SP	CRE	ID		TD		2/8/2022
2021	PO4701689773	F	4	45 ACE	SP	P			V		2/9/2022
2021	PO4701189769	F	4	30 ACE	SP	P			V		2/10/2022
2021	PO4703189748	F	4	40 ACE	SP	CCA			V		2/11/2022
2021	PO4702589745	F	4	30 ACE	SP	CRE			V		2/12/2022
2021	PO4702889702	LGE	4	40 ACE	SP	CCA			V		2/13/2022
2021	PO4728290049	LGE	4	35 ACE	SP	CCA			V		2/14/2022
2021	PO4729290055	LGE	3	45 ACE	SP	CCA			V		2/15/2022
2021	PO7305955567	ODP	3	45 KOP	SP	CCA			V		2/16/2022
2021	PO8004346938	ODP	3	45 BRO	SP	CCA			V		2/17/2022
2021	PO8000247130	ODP	3	45 BRO	SP	CCA			V		2/18/2022
2021	PO7977047187	ODP	6	30 BRO	SP	CRE			V		2/19/2022
2021	PO7986647313	ODP	3	45 BRO	SP	CCA			V		2/20/2022
2021	PO7963547456	ODP	3	45 BRO	SP	CCA			V		2/21/2022
2021	PO7290355369	ODP	4	45 KOP	SP	CCA			V		2/22/2022
2021	PO7255555109	ODP	3	45 KOP	SP	CCA			V		2/23/2022
2021	PO4892989107	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TD		2/24/2022
2021	PO5582522423	KU	3	45 BRN	SP	CRE	ED,ID,IP		TD		2/25/2022
2021	PO5313210995	KU	2	50 BRN	SP	S			V		2/26/2022
2021	PO5313310994	F	4	40 BRN	SP	CRE			V		2/27/2022
2021	PO5312010857	F	4	45 BRN	SP	CRE			V		2/28/2022
2021	PO5313811094	F	3	50 BRN	SP	CRE			V		3/1/2022
2021	PO5315711339	F	4	40 BRN	SP	CRE			V		3/2/2022
2021	PO5311110661	F	4	40 BRN	SP	CRE			V		3/3/2022
2021	PO5310110552	F	3	45 BRN	SP	CRE			V		3/4/2022
2021	PO5314711181	F	4	40 BRN	SP	CRE			V		3/5/2022
2021	PO5589422405	KU	3	50 BRN	SP	CRE	ED,ID		BD		3/6/2022
2021	PO8015945101	ODP	4	40 XXX	SP	CRE	ED,ID,IP		TD		3/7/2022
2021	PO7999545019	ODP	6	30 XXX	SP	CRE	ED,ID		TD		3/8/2022
2021	PO7991445063	ODP	4	45 XXX	SP	S			V		3/9/2022
2021	PO7997945068	ODP	4	45 XXX	SP	CRE	ED,ID		TD		3/10/2022

2021 PO7935047545	ODP	6	30 BRO	SP	CCA	ID	BD	3/11/2022
2021 PO7949647680	ODP	4	40 BRO	SP	CRE	ID	BD	3/12/2022
2021 PO7947247541	ODP	3	45 BRO	SP	CCA		V	3/13/2022
2021 PO7938447592	ODP	3	45 BRO	SP	CCA		V	3/14/2022
2021 PO7940347500	ODP	6	30 BRO	SP	CCA		V	3/15/2022
2021 PO7918547955	ODP	4	40 BRO	SP	CCA		V	3/16/2022
2021 PO7053042387	ODP	5	30 BRN	SP	CCA	ED,ID	TD	3/17/2022
2021 PO7052942284	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	3/18/2022
2021 PO7216055041	F	4	40 KOP	SP	CRE		V	3/19/2022
2021 PO7269655222	ODP	5	35 KOP	SP	S		V	3/20/2022
2021 PO7252254790	ODP	5	30 KOP	SP	CRE		V	3/21/2022
2021 PO7242655006	ODP	3	45 KOP	SP	CCA		V	3/22/2022
2021 PO7246354955	ODP	5	35 KOP	SP	CRE	ED,ID	TD	3/23/2022
2021 PO7246354931	ODP	5	35 KOP	SP	CCA		T	3/24/2022
2021 PO7221254891	ODP	4	40 KOP	SP	CCA		T	3/25/2022
2021 PO7818144438	ODP	4	40 BRN	SP	CRE	ID	TD	3/26/2022
2021 PO7812344380	ODP	5	30 BRN	SP	CRE	ED	T	3/27/2022
2021 PO7898548464	ODP	4	40 BRO	SP	CCA		V	3/28/2022
2021 PO7893948325	ODP	3	45 BRO	SP	CCA		V	3/29/2022
2021 PO7921048381	ODP	4	40 BRO	SP	CCA		V	3/30/2022
2021 PO7903148423	ODP	4	40 BRO	SP	CCA		V	3/31/2022
2021 PO7893348471	ODP	4	40 BRO	SP	CCA		V	4/1/2022
2021 PO5584222365	KU	1	55 BRN	SP	CCA		V	4/2/2022
2021 PO5582822438	KU	6	30 OTH	SP	CRE	ED,ID,IP	TD	4/3/2022
2021 PO4893189096	LGE	4	40 BRO	SP	CCA		V	4/4/2022
2021 PO7909349096A	ODP	4	40 BRO	SP	CCA		V	4/5/2022
2021 PO7882243941	ODP	4	45 BRN	SP	CRE	ED,ID	TD	4/6/2022
2021 PO7909349096	ODP	5	35 BRO	SP	CCA		V	4/7/2022
2021 PO7891643976	ODP	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD	4/8/2022
2021 PO7932144125	ODP	4	40 BRN	SP	CRE	ED,ID	TD	4/9/2022
2021 PO7918144074	ODP	4	40 BRN	SP	CRE	ED,ID	TD	4/10/2022
2021 PO7920044011	F	4	40 BRN	SP	CRE		V	4/11/2022
2021 PO7658342563	ODP	5	35 KOP	SP	CRE		V	4/12/2022
2021 PO7081142344	ODP	5	30 BRN	SP	CRE	ED,ID,IP	TD	4/13/2022
2021 PO7085742178	ODP	5	35 BRN	SP	CCA		V	4/14/2022
2021 PO4890189085	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/15/2022
2021 PO7223754832	ODP	6	30 KOP	SP	CRE	ED,ID	TD	4/16/2022
2021 PO7163254932	ODP	4	40 KOP	SP	CCA		T	4/17/2022
2021 PO7197154794	ODP	4	40 KOP	SP	CRE	ED,ID	TD	4/18/2022
2021 PO5516521997	KU	4	40 BRN	SP	CRE	ID,IP	BD	4/19/2022
2021 PO5509122074	KU	5	35 BRN	SP	CRE	ID	BD	4/20/2022
2021 PO5528821879	KU	3	45 BRN	SP	CRE	ID,IP	BD	4/21/2022
2021 PO7841444502	ODP	5	35 BRN	SP	CRE	ID	TD	4/22/2022
2021 PO7829544631	ODP	4	40 BRN	SP	CRE	ID	TD	4/23/2022
2021 PO7824144735	ODP	4	40 BRN	SP	CCA		V	4/24/2022
2021 PO5575122528	KU	6	30 OTH	SP	CRE	ED,ID	BD	4/25/2022
2021 PO7691742779	ODP	6	30 KOP	SP	CCA		V	4/26/2022
2021 PO7695042510A	ODP	5	35 KOP	SP	CRE	ED,ID	TD	4/27/2022
2021 PO7303050509	ODP	4	40 KOP	SP	CCA		V	4/28/2022
2021 PO7317250503	ODP	6	30 KOP	SP	CRE	ED,SRS	TD	4/29/2022
2021 PO7305550607	ODP	6	30 KOP	SP	CCA		V	4/30/2022
2021 PO7298350695	ODP	4	40 KOP	SP	CCA		V	5/1/2022
2021 PO7698542536	ODP	5	30 KOP	SP	CRE		V	5/2/2022
2021 PO7695042510	ODP	4	45 KOP	SP	CRE	ED,ID	TD	5/3/2022

2021 PO7689342525	ODP	4	45 KOP	SP	CRE	ED,ID	TD	5/4/2022
2021 PO7694842567	ODP	6	30 KOP	SP	CCA		V	5/5/2022
2021 PO7691242519	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD	5/6/2022
2021 PO5567622618	KU	6	30 OTH	SP	CRE	ED,ID	BD	5/7/2022
2021 PO4888889115	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/8/2022
2021 PO4888889119	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	5/9/2022
2021 PO4889789128	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/10/2022
2021 PO4890889144	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/11/2022
2021 PO4889289146	LGE	4	40 BRO	SP	A	ID,IP	BD	5/12/2022
2021 PO7200454669	ODP	4	40 KOP	SP	CRE		V	5/13/2022
2021 PO7178654480	ODP	4	40 KOP	SP	CRE	ED,ID	TD	5/14/2022
2021 PO4969989863	LGE	3	45 BRN	SP	P	ED,ID	TD	5/15/2022
2021 PO4971889881	LGE	3	45 BRN	SP	P	ED,ID	TD	5/16/2022
2021 PO7311350953	ODP	5	30 KOP	SP	CRE	ED	T	5/17/2022
2021 PO4729690097	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	5/18/2022
2021 PO7172254688	ODP	4	40 KOP	SP	CRE		T	5/19/2022
2021 PO7145154566	ODP	5	35 KOP	SP	CRE	ED,ID	TD	5/20/2022
2021 PO7122354471	ODP	6	35 KOP	SP	CRE	ED,ID	TD	5/21/2022
2021 PO7094354361	ODP	4	40 KOP	SP	CRE	ED,ID	TD	5/22/2022
2021 PO7054254583	ODP	3	45 KOP	SP	CCA		V	5/23/2022
2021 PO5558622729	KU	6	30 OTH	SP	CRE	ED,ID,IP	TD	5/24/2022
2021 PO4731290096	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	5/25/2022
2021 PO4732190089	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	5/26/2022
2021 PO7872343906	ODP	4	40 BRN	SP	CRE	ED,ID	TD	5/27/2022
2021 PO7871143942	ODP	5	35 BRN	SP	CRE	ID	BD	5/28/2022
2021 PO7871143941	ODP	5	35 BRN	SP	CRE	ID	TD	5/29/2022
2021 PO7866744078	ODP	5	35 BRN	SP	CRE	ID,IP	BD	5/30/2022
2021 PO7859144019	ODP	6	30 BRN	SP	CCA	ED	T	5/31/2022
2021 PO7858744147	ODP	5	35 BRN	SP	CRE	ID	TD	6/1/2022
2021 PO7850344247	ODP	6	30 BRN	SP	CCA		V	6/2/2022
2021 PO7746344348	ODP	6	30 BRN	SP	CRE		V	6/3/2022
2021 PO7818344005	ODP	5	35 BRN	SP	CRE	ID	TD	6/4/2022
2021 PO7829043954	ODP	6	30 BRN	SP	CCA		V	6/5/2022
2021 PO7290750960	ODP	5	35 KOP	SP	CRE	ED,SRS	TD	6/6/2022
2021 PO7106042517	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	6/7/2022
2021 PO7097042470	ODP	4	40 BRN	SP	P	ED,ID,IP	TD	6/8/2022
2021 PO5324484711	KU	4	40 BRN	SP	CCA		V	6/9/2022
2021 PO5323084598	KU	3	45 BRN	SP	CCA		V	6/10/2022
2021 PO5321284477	KU	3	45 BRN	SP	CRE		V	6/11/2022
2021 PO4042784401	LGE	3	45 ACE	SP	CRE	ED,IP	BD	6/12/2022
2021 PO4042784402	LGE	3	45 ACE	SP	CRE	ED,IP	BD	6/13/2022
2021 PO3981484503	F	4	40 ACE	SP	CRE		V	6/14/2022
2021 PO2054092002	KU	4	40 UNK	SP	CRE	ID	TD	6/15/2022
2021 PO3581084649	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/16/2022
2021 PO4045883319	F	3	65 BRO	SP	CRE		V	6/17/2022
2021 PO5358328951	KU	2	50 BRN	SP	CCA		V	6/18/2022
2021 PO5366128949	KU	2	50 BRN	SP	CCA		V	6/19/2022
2021 PO5337228971	KU	2	50 BRN	SP	CCA		V	6/20/2022
2021 PO5331628974	KU	2	50 BRN	SP	CCA		V	6/21/2022
2021 PO5338229044	KU	4	40 BRN	UN	CCA		V	6/22/2022
2021 PO3990684466	F	UNK	45 ACE	SP	A		V	6/23/2022
2021 PO2004592209	KU	3	45 UNK	SP	P	ID	TD	6/24/2022
2021 PO4085984283	LGE	3	45 BRO	SP	CCA		V	6/25/2022
2021 PO4084884303	LGE	4	30 BRO	SP	P	ED,ID	TD	6/26/2022

2021 PO4085584297	LGE	4	35 BRO	SP	P		ED,ID	TD	6/27/2022
2021 PO3582684557	KU	3	45 BRO	SP	S			V	6/28/2022
2021 PO3591084217	KU	3	45 BRO	SP	S			V	6/29/2022
2021 PO3532884545	KU	4	50 BRO	SP	CRE		ED,ID,IP	TD	6/30/2022
2021 PO7975369697	KU	4	40 ACE	SP	CRE		ED,ID	TD	7/1/2022
2021 PO7961469813	KU	4	40 ACE	SP	CRE		ED,ID	TD	7/2/2022
2021 PO7957369843	KU	4	45 ACE	SP	CCA		ED	TD	7/3/2022
2021 PO7953669875	KU	4	40 ACE	SP	CCA			V	7/4/2022
2021 PO7949769907	KU	4	40 ACE	SP	CRE		ED,ID	BD	7/5/2022
2021 PO4043184400	LGE	4	40 ACE	SP	CRE		ED	TD	7/6/2022
2021 PO5348827799	KU	3	45 BRN	SP	CCA			V	7/7/2022
2021 PO5344427822	KU	3	45 BRN	SP	CCA			V	7/8/2022
2021 PO5381128079	KU	3	45 BRN	UN	CCA			V	7/9/2022
2021 PO4046783298	F	4	30 BRO	SP	CRE			V	7/10/2022
2021 PO3494284449	KU	5	35 BRO	SP	CRE		ED,ID,IP	TD	7/11/2022
2021 PO3488084299	KU	6	30 BRO	SP	CRE		ED,ID,IP	TD	7/12/2022
2021 PO3479084352	KU	3	45 BRO	SP	S			V	7/13/2022
2021 PO4048183303	F	4	40 BRO	SP	CRE			V	7/14/2022
2021 PO4087084290	LGE	4	40 BRO	SP	A		ED,ID,IP	TD	7/15/2022
2021 PO8041354591	LGE	4	35 BRO	SP	CCA			V	7/16/2022
2021 PO4088184297	LGE	4	40 BRO	SP	CCA			V	7/17/2022
2021 PO3985684467	F	4	40 ACE	SP	CRE			V	7/18/2022
2021 PO3984284467	F	4	40 ACE	SP	CRE			V	7/19/2022
2021 PO5399828814	KU	3	45 BRN	SP	CRE			B	7/20/2022
2021 PO5403228709	KU	3	45 BRN	SP	CRE			B	7/21/2022
2021 PO5395728731	KU	3	45 BRN	SP	CRE		ID,RB	BX	PX 7/22/2022
2021 PO7943769960	KU	4	40 ACE	SP	CRE		ED,ID	BD	7/23/2022
2021 PO7937169877	KU	6	30 ACE	SP	CCA			V	7/24/2022
2021 PO4047583347	LGE	4	40 BRO	SP	CRE		ED,ID,IP	TD	7/25/2022
2021 PO4047383353	LGE	4	35 BRO	SP	CRE		ED,ID	TD	7/26/2022
2021 PO3474084400	KU	4	40 BRO	SP	CRE		ED,ID	TD	7/27/2022
2021 PO4089984309	LGE	3	45 BRO	SP	CCA			V	7/28/2022
2021 PO4090184292	LGE	4	30 BRO	SP	P		ED,ID	TD	7/29/2022
2021 PO4089284304	LGE	3	45 BRO	SP	A		ED,ID,IP	TD	7/30/2022
2021 PO4088684309	LGE	4	30 BRO	SP	CCA			V	7/31/2022
2021 PO8053654971	LGE	4	35 BRO	SP	CCA			V	8/1/2022
2021 PO4090184316	LGE	4	40 BRO	SP	CCA			V	8/2/2022
2021 PO4091484314	LGE	3	45 BRO	SP	CCA			V	8/3/2022
2021 PO4091584321	LGE	3	45 BRO	SP	CCA			V	8/4/2022
2021 PO4092784318	LGE	4	40 BRO	SP	CCA			V	8/5/2022
2021 PO4096784344	LGE	4	30 BRO	SP	P		ED,ID	BD	8/6/2022
2021 PO4097384340	LGE	4	40 BRO	SP	P		ED,ID	BD	8/7/2022
2021 PO4098584346	LGE	4	40 BRO	SP	CRE			B	8/8/2022
2021 PO5410028858	KU	2	45 BRN	SP	CCA			V	8/9/2022
2021 PO5412028850	KU	4	40 BRN	SP	CCA			V	8/10/2022
2021 PO5414128888	KU	2	45 BRN	SP	CCA			V	8/11/2022
2021 PO5417628882	KU	3	45 BRN	SP	CCA			V	8/12/2022
2021 PO5420028872	KU	3	45 BRN	SP	CCA			V	8/13/2022
2021 PO5424428836	KU	2	45 BRN	SP	CCA			V	8/14/2022
2021 PO5419828814	KU	4	40 BRN	SP	CRE			B	8/15/2022
2021 PO5424328796	KU	2	45 BRN	SP	CRE			B	8/16/2022
2021 PO5442328718	KU	3	45 BRN	SP	CRE			B	8/17/2022
2021 PO5299685847	KU	3	45 XXX	SP	CRE			V	8/18/2022
2021 PO4040084330	LGE	4	30 ACE	SP	CCA			V	8/19/2022

2021 PO3982584632	F	4	30 ACE	SP	CCA		V	8/20/2022
2021 PO3982284636	F	4	40 ACE	SP	P		V	8/21/2022
2021 PO5483729188	KU	5	35 BRN	SP	CRE		B	8/22/2022
2021 PO3982784648	F	4	40 ACE	SP	P		V	8/23/2022
2021 PO3983484665	F	4	35 ACE	SP	CRE		V	8/24/2022
2021 PO3973384485	LGE	4	30 ACE	SP	A	ED,ID	TD	8/25/2022
2021 PO4051983361	LGE	3	45 BRO	SP	A	ID	BD	8/26/2022
2021 PO4050283304	F	4	40 BRO	SP	CRE	HH,ID,RB	VX	8/27/2022
2021 PO5488529091	KU	6	30 BRN	SP	CRE		B	8/28/2022
2021 PO4050283309	F	5	25 BRO	SP	CRE		V	8/29/2022
2021 PO7910969263	KU	4	45 ACE	SP	CRE	ED,ID	TD	8/30/2022
2021 PO4044084419	LGE	4	40 ACE	SP	CRE	ED,IP	TD	8/31/2022
2021 PO4043984420	LGE	3	50 ACE	SP	CRE	ED,ID	TD	9/1/2022
2021 PO3990484484	F	4	40 ACE	SP	CRE		V	9/2/2022
2021 PO3991584467	F	7	25 ACE	SP	CRE		V	9/3/2022
2021 PO3990884497	F	4	30 ACE	SP	CCA		V	9/4/2022
2021 PO3990284498	F	1	50 ACE	SP	CCA		V	9/5/2022
2021 PO3988284498	F	3	45 ACE	SP	CCA		V	9/6/2022
2021 PO8026170016	KU	4	40 ACE	SP	CCA		V	9/7/2022
2021 PO4043884426	LGE	1	40 ACE	SP	CRE		V	9/8/2022
2021 PO4043684421	LGE	6	30E ACE	SP	CRE	ED	BD	9/9/2022
2021 PO4043684423	LGE	3	35E ACE	SP	CRE	ED	BD	9/10/2022
2021 PO5552528023	KU	4	40 BRN	SP	CCA		V	9/11/2022
2021 PO5563027957	KU	5	35 BRN	SP	CCA		V	9/12/2022
2021 PO5563628057	KU	5	35 BRN	SP	CCA		V	9/13/2022
2021 PO5574327940	KU	3	50 BRN	SP	CCA		V	9/14/2022
2021 PO5549728063	KU	3	50 BRN	SP	CCA		V	9/15/2022
2021 PO8016369875	KU	1	65 ACE	SP	CRE		V	9/16/2022
2021 PO8006669744	KU	5	35 ACE	SP	CCA		V	9/17/2022
2021 PO7997469611	KU	2	70 ACE	SP	CRE		V	9/18/2022
2021 PO4096084299	LGE	4	40 BRO	UN	CRE		V	9/19/2022
2021 PO4093884282	LGE	4	35 BRO	UN	CRE		V	9/20/2022
2021 PO3986984498	F	4	40 ACE	SP	CRE		V	9/21/2022
2021 PO5557728124	KU	4	40 BRN	SP	CCA		V	9/22/2022
2021 PO5562728173	KU	3	40 BRN	SP	CCA		V	9/23/2022
2021 PO5567528149	KU	2	50 BRN	SP	CCA		V	9/24/2022
2021 PO5568828237	KU	4	40 BRN	SP	CCA		V	9/25/2022
2021 PO5560828275	F	4	40 BRN	SP	CRE		V	9/26/2022
2021 PO5552328315	F	4	40 BRN	SP	CRE		V	9/27/2022
2021 PO4088484315	LGE	UNK	45 BRO	UN	CRE		V	9/28/2022
2021 PO4087084258	LGE	4	30 BRO	SP	CRE	ED,ID,IP,Src	TD	9/29/2022
2021 PV3985584499	F	4	40 ACE	SP	CRE		V	9/30/2022
2021 PO3984184499	F	4	40 ACE	SP	CRE		V	10/1/2022
2021 PO3982784501	F	4	40 ACE	SP	CRE		V	10/2/2022
2021 PO5543528269	KU	4	45 BRN	SP	CCA		V	10/3/2022
2021 PO3388985253A	KU	6	30 BRO	SP	CRE	ED,ID	TD	10/4/2022
2021 PO3394084911	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/5/2022
2021 PO3388985253	KU	4	45 BRO	SP	S		V	10/6/2022
2021 PO3402384349	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD	10/7/2022
2021 PO3406784146	KU	4	50 BRO	SP	CRE	ED,ID	TD	10/8/2022
2021 PO3386985402	KU	6	30 BRO	SP	S		V	10/9/2022
2021 PO3378485342	KU	5	35 BRO	SP	CRE	ED,ID	BD	10/10/2022
2021 PO3399284567	KU	4	40 BRO	SP	S		V	10/11/2022
2021 PO3400085236	KU	4	45 BRO	SP	S		V	10/12/2022



2021 PO3398084173	KU	5	35 BRO	SP	CRE	ED,ID	TD	10/13/2022
2021 PO4052783303	LGE	4	30 BRO	SP	A	ED,ID	TD	10/14/2022
2021 PO4052183300	F	4	40 BRO	SP	CRE		V	10/15/2022
2021 PO4053583295	F	4	40 BRO	SP	A		V	10/16/2022
2021 PO5476829013	KU	3	45 BRN	SP	CRE		T	10/17/2022
2021 PO5480029084	KU	6	30 BRN	SP	CRE	ED,RB	BX PX	10/18/2022
2021 PO5476229000	KU	3	45 BRN	SP	CCA		V	10/19/2022
2021 PO5444829117	KU	6	30 BRN	SP	CCA		V	10/20/2022
2021 PO5474229012	KU	5	35 BRN	SP	CCA		V	10/21/2022
2021 PO5452829123	KU	5	35 BRN	SP	CCA		V	10/22/2022
2021 PO1818794479	KU	3	45 BRO	SP	CCA		V	10/23/2022
2021 PO1865093893	F	4	40 UNK	SP	P		V	10/24/2022
2021 PO1887494618	KU	4	40 KOP	SP	CRE	ID	TD	10/25/2022
2021 PO7896869205	KU	4	45 ACE	SP	CRE	ED,ID	BD	10/26/2022
2021 PO7901969253	KU	5	35 ACE	SP	CCA	ED	TD	10/27/2022
2021 PO3983984677	F	3	45 ACE	SP	A		V	10/28/2022
2021 PO4043084400	LGE	4	50 ACE	SP	CRE	ED,EP,ID,MD	TX RR	10/29/2022
2021 PO9157997924A	KU	6	30 BRN	SP	CCA		V	10/30/2022
2021 PO9776298391A	F	2	35 UNK	SP	CRE		V	10/31/2022
2021 PO9489897573	C	3	60 XXX	SP	CRE		V	11/1/2022
2021 PO9347098897	KU	5	35 BRN	SP	CCA		V	11/2/2022
2021 PO3366798860	KU	5	35 BRN	SP	CCA		V	11/3/2022
2021 PO9390398693	KU	3	45 BRN	SP	CCA		V	11/4/2022
2021 PO8997496670	KU	5	35 BRN	AL	CCA		V	11/5/2022
2021 PO9464897839	KU	5	35 BRN	SP	CCA		V	11/6/2022
2021 PO9337898028	KU	3	45 BRN	SP	CCA		V	11/7/2022
2021 PO9471497576	KU	3	45 BRN	SP	CCA		V	11/8/2022
2021 PO9374698693	KU	3	45 BRN	SP	CCA		V	11/9/2022
2021 PO9749098332	F	5	35 BRN	SP	CRE		V	11/10/2022
2021 PO9331598544	KU	4	40 BRN	SP	CCA		V	11/11/2022
2021 PO9448897762	KU	4	40 BRN	SP	CCA		V	11/12/2022
2021 PO9360598695	KU	3	45 BRN	SP	CCA		V	11/13/2022
2021 PO9757798392	KU	4	40 BRN	SP	CRE		V	11/14/2022
2021 PO9424997503	KU	3	45 BRN	SP	CCA		V	11/15/2022
2021 PO9080395969	KU	6	30 INP	SP	CRE	ED,SRS	T	11/16/2022
2021 PO9363898840	KU	5	35 KOP	SP	CCA		V	11/17/2022
2021 PO9350098439	KU	3	45 OTH	SP	CCA		V	11/18/2022
2021 PO9373199076	KU	3	45 BRN	SP	CCA		V	11/19/2022
2021 PO9460297573	KU	3	45 BRN	SP	CCA		V	11/20/2022
2021 PO1927341534	F	4	45 OTH	SP	CCA		V	11/21/2022
2021 PO1934241634	F	4	40 OTH	SP	CCA		V	11/22/2022
2021 PO2351042442	F	6	30 OTH	SP	CCA		V	11/23/2022
2021 PO1842540896	F	4	40 BRN	SP	CRE		V	11/24/2022
2021 PO1897241283	F	4	40 BRN	SP	CRE		V	11/25/2022
2021 PO1907941391	F	4	40 BRN	SP	CRE		V	11/26/2022
2021 PO1885041194	F	4	40 BRN	SP	CRE		V	11/27/2022
2021 PO1935494712	KU	5	35 UNK	SP	CCA		V	11/28/2022
2021 PO2119392229	KU	3	40 UNK	SP	CRE	ID	BD	11/29/2022
2021 PO3984483401	LGE	3	45 BRO	SP	CRE	ED,ID,JP	TD	11/30/2022
2021 PO5605228061	F	3	45 BRN	SP	CRE		V	12/1/2022
2021 PO5596228103	F	4	40 BRN	SP	CRE		V	12/2/2022
2021 PO5571427675	KU	5	35 BRN	SP	CCA		V	12/3/2022
2021 PO5579227752	KU	2	50 BRN	SP	CCA		V	12/4/2022
2021 PO5540727884	KU	6	30 BRN	SP	CRE		B	12/5/2022

2021	PO5557927860	KU	6	35 BRN	SP	CRE		V	12/6/2022
2021	PO5557427883	KU	6	30 BRN	SP	CRE		B	12/7/2022
2021	PO5555527932	KU	6	30 BRN	SP	CRE		B	12/8/2022
2021	PO5539427983	KU	3	50 BRN	SP	CCA		V	12/9/2022
2021	PO5293585623	KU	4	40 XXX	SP	CRE	ID	TD	12/10/2022
2021	PO5302985685	KU	4	40 XXX	SP	CRE		V	12/11/2022
2021	PO5309685545	KU	3	45 XXX	SP	CCA		V	12/12/2022
2021	PO5271185436	KU	4	40 XXX	SP	CRE	ID	BD	12/13/2022
2021	PO5464028777	KU	2	45 BRN	SP	CRE		B	12/14/2022
2021	PO5466228796	KU	2	50 BRN	SP	CRE		B	12/15/2022
2021	PO4049583360	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	12/16/2022
2021	PO3979384512	F	4	40 ACE	SP	CRE		V	12/17/2022
2021	PO4042084378	LGE	3	50 ACE	SP	A	ED	BD	12/18/2022
2021	PO4050283361	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/19/2022
2021	PO5471828911	KU	4	40 BRN	SP	CRE		T	12/20/2022
2021	PO5477628880	KU	3	45 BRN	SP	CRE		T	12/21/2022
2021	PO5491828884	KU	4	40 BRN	SP	CCA		V	12/22/2022
2021	PO5505928888	KU	3	45 BRN	SP	CCA		V	12/23/2022
2021	PO5512528890	KU	4	45 BRN	SP	CCA		V	12/24/2022
2021	PO3979484531	F	4	40 ACE	SP	CRE		V	12/25/2022
2021	PO2030391936	KU	6	30 BRO	SP	CCA		V	12/26/2022
2021	PO2029291551	KU	3	45 BRO	SP	CCA		V	12/27/2022
2021	PO3979684545	F	4	40 ACE	SP	A		V	12/28/2022
2021	PO3979784559	F	4	40 ACE	SP	P		V	12/29/2022
2021	PO7926469604	KU	6	30 ACE	SP	CCA	ED	TD	12/30/2022
2021	PO4050083375	LGE	3	45 BRO	SP	A	ED,ID	TD	12/31/2022
2021	PO3979884573	F	4	40 ACE	SP	A		V	1/1/2023
2021	PO3980284586	F	4	40 ACE	SP	CCA		V	1/2/2023
2021	PO4049983389	LGE	3	45 BRO	SP	A	ID	BD	1/3/2023
2021	PO4050283410	LGE	3H	45 BRO	SP	A	ID	BD	1/4/2023
2021	PO5430628770	KU	5	35 BRN	UN	CCA		V	1/5/2023
2021	PO5436428786	KU	2	45 BRN	SP	CCA		V	1/6/2023
2021	PO5441928762	KU	2	45 BRN	SP	CCA		V	1/7/2023
2021	PO5463228627	KU	3	50 BRN	SP	CRE		B	1/8/2023
2021	PO5447628753	KU	3	50 BRN	SP	CCA		V	1/9/2023
2021	PO5455128663	KU	3	45 BRN	SP	CCA		V	1/10/2023
2021	PO5473228584	KU	3	50 BRN	SP	CCA		V	1/11/2023
2021	PO3360383160	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/12/2023
2021	PO3361182718	KU	3	45 BRO	SP	S		V	1/13/2023
2021	PO3384183043	KU	6	30 BRO	SP	S		V	1/14/2023
2021	PO3380783190	KU	6	30 BRO	SP	S		V	1/15/2023
2021	PO3377283336	KU	4	45 BRO	SP	CRE	ED,ID	TD	1/16/2023
2021	PO3365383383	KU	6	30 BRO	SP	S		V	1/17/2023
2021	PO7745044885	LGE	4	30 BRO	SP	CCA		V	1/18/2023
2021	PO4056483287	F	4	40 BRO	SP	CRE		V	1/19/2023
2021	PO4056483295	F	4	40 BRO	SP	CCA		V	1/20/2023
2021	PO4057383299	F	3	45 BRO	SP	A		V	1/21/2023
2021	PO4058383325	LGE	3	45 BRO	SP	A	ID	BD	1/22/2023
2021	PO1934894567	KU	4	40 UNK	SP	CRE	ID	BD	1/23/2023
2021	PO4040084335	LGE	UNK	55 ACE	SP	A	ED	TD	1/24/2023
2021	PO4035884352	LGE	4	35 ACE	SP	CRE		V	1/25/2023
2021	PO4037884343	LGE	4	35 ACE	SP	CRE		V	1/26/2023
2021	PO1462597307	KU	4	45 INP	SP	CRE	ID	TD	1/27/2023
2021	PO4037784347	LGE	3	50 ACE	SP	CRE	ED,ID,MD	BD	1/28/2023

2021 PO8043074146	KU	5	35 ACE	SP	CCA		V			1/29/2023
2021 PO8043773967	KU	2	70 ACE	SP	CCA		V			1/30/2023
2021 PO8070973862	KU	4	45 ACE	SP	CCA		V			1/31/2023
2021 PO8057373886	KU	4	45 ACE	SP	CCA		V			2/1/2023
2021 PO3977883768	F	3	45 BRO	SP	A		V			2/2/2023
2021 PO3976783769	F	4	40 BRO	SP	CRE		V			2/3/2023
2021 PO8043873887	KU	4	40 ACE	SP	CCA		V			2/4/2023
2021 PO1389594967	KU	4	40 INP	SP	CRE	ID	TD			2/5/2023
2021 PO8043873815	KU	4	40 ACE	SP	CCA		V			2/6/2023
2021 PO8043973656	KU	1	80 ACE	SP	CRE		V			2/7/2023
2021 PO8044473535	KU	4	40 ACE	SP	CCA		V			2/8/2023
2021 PO8034074204	KU	3	50 ACE	SP	CCA		V			2/9/2023
2021 PO1484997196	KU	4	40 INP	SP	CRE	ID	TD			2/10/2023
2021 PO3851584778	KU	5	35 BRO	SP	CRE	ED,ID	BD			2/11/2023
2021 PO3762984682	KU	6	30 BRO	SP	CRE	ED,ID	TD			2/12/2023
2021 PO8037674244	KU	3	50 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		2/13/2023
2021 PO3981383766	F	3	45 BRO	SP	CRE	EP,HH,ID,IP,RB	VX	RP1		2/14/2023
2021 PO4601250340	KU	4	40 BRN	SP	CRE	ED,HH	BX	RP1		2/15/2023
2021 PO8758264584	LGE	4	40 BRO	SP	CCA	ED,HH,ID	BX	PX		2/16/2023
2021 PO4159885262	LGE	4	40 BRO	SP	A	ID	BD			2/17/2023
2021 PO4589250736a	KU	5	35 BRN	SP	CRE	ID	BD			2/18/2023
2021 PO4092085503	LGE	3	45 ACE	SP	P	ED,ID	BD			2/19/2023
2021 PO4573450248	KU	5	35 BRN	SP	CRE	ID	BD			2/20/2023
2021 PO4077885334	LGE	4	35 ACE	SP	P	ED,ID	BD			2/21/2023
2021 PO4077185325	LGE	4	35 ACE	SP	P	ED,ID	BD			2/22/2023
2021 PO4074985318	LGE	4	35 ACE	SP	P	ED,ID	BD			2/23/2023
2021 PO4091685497	LGE	2	80 ACE	SP	CRE	ED,ID	BD			2/24/2023
2021 PO4091285489	LGE	2	70 ACE	SP	CRE	ED,ID	BD			2/25/2023
2021 PO4165585239	LGE	4	40 BRO	SP	CRE	ED,ID	BD			2/26/2023
2021 PO4163085225	LGE	4	40 BRO	SP	CRE	ID	BD			2/27/2023
2021 PO4570349688	KU	5	35 BRN	SP	CRE	ID	BD			2/28/2023
2021 PO4586849687	KU	4	40 BRN	SP	CRE	ID	BD			3/1/2023
2021 PO4574449336	KU	3	50 BRN	SP	CRE	ID	BD			3/2/2023
2021 PO4605450470	KU	4	40 BRN	SP	CRE	ID	BD			3/3/2023
2021 PO4625150937	KU	4	40 BRN	SP	CRE	ID	BD			3/4/2023
2021 PO4629050924	KU	4	40 BRN	SP	A	ID	BD			3/5/2023
2021 PO4159985226	LGE	4	40 BRO	SP	CRE	ID	BD			3/6/2023
2021 PO3980919745	KU	4	45 KOP	SP	CRE	ID	BD			3/7/2023
2021 PO4088885441	LGE	3	45 ACE	SP	P	ED,ID	BD			3/8/2023
2021 PO4088285434	LGE	3	45 ACE	SP	P	ED,ID	BD			3/9/2023
2021 PO4089485449	LGE	3	45 ACE	SP	P	ED	BD			3/10/2023
2021 PO4087485424	LGE	3	45 ACE	SP	P	ED,ID	BD			3/11/2023
2021 PO4090385460	LGE	3	55 ACE	SP	P	ED,HH,ID,IP	BD			3/12/2023
2021 PO4092885495	LGE	2	65 ACE	SP	P	ED,ID	BD			3/13/2023
2021 PO4176486207	LGE	3	45 BRO	SP	CRE	ID,IP	BD			3/14/2023
2021 PO0347005203	KU	3	50 UNK	SP	CRE	ID	BD			3/15/2023
2021 PO4600150488	KU	5	45 BRN	SP	CRE	ID	BD			3/16/2023
2021 PO4159785245	LGE	4	40 BRO	SP	CRE	ID	BD			3/17/2023
2021 PO4097685569	LGE	2	60 ACE	SP	P	ED,ID	BD			3/18/2023
2021 PO4096585547	LGE	2	60 ACE	SP	P	ED,ID	BD			3/19/2023
2021 PO0534705424	KU	3	40 UNK	SP	CRE	ID,IP	BD			3/20/2023
2021 PO4177586217	LGE	5	25 BRO	SP	CRE	ID	BD			3/21/2023
2021 PO5810210553	KU	2	70 ACW	SP	CRE	ED,ID	BD			3/22/2023
2021 PO4093985514	LGE	2	55 ACE	SP	P	ED,ID	BD			3/23/2023

2021 PO4094185516	LGE	2	65 ACE	SP	P	ED,ID	BD		3/24/2023
2021 PO3681525886	KU	4	40 CPT	SP	CRE	ID	BD		3/25/2023
2021 PO3801124733	KU	5	30 UNK	SP	CRE	ID	BD		3/26/2023
2021 PO4095285532	LGE	2	65 ACE	SP	P	ED,ID	BD		3/27/2023
2021 PO4175486193	LGE	4	30 BRO	SP	CRE	ID	BD		3/28/2023
2021 PO5825910691	KU	2	45 ACW	SP	CRE	ED,ID,IP	BD		3/29/2023
2021 PO5824110715	KU	2	45 ACW	SP	CRE	ED,ID	BD		3/30/2023
2021 PO4081685354	LGE	3	45 ACE	SP	CRE	ED,ID	BD		3/31/2023
2021 PO4158485178	LGE	4	40 BRO	SP	P	ID	BD		4/1/2023
2021 PO4082885368	LGE	3	45 ACE	SP	CRE	ED,ID	BD		4/2/2023
2021 PO4086285409	LGE	3	45 ACE	SP	CRE	ED,ID	BD		4/3/2023
2021 PO4158085214	LGE	4	40 BRO	SP	CRE	ID	BD		4/4/2023
2021 PO5793510557	KU	4	40 ACW	SP	CRE	ED,ID	BD		4/5/2023
2021 PO3991741352	KU	4	40 BRO	SP	CCA		B		4/6/2023
2021 PO3975341294	KU	4	40 BRO	SP	CCA		B		4/7/2023
2021 PO3952741289	KU	4	45 BRO	SP	CCA		B		4/8/2023
2021 PO3966341280	KU	4	40 BRO	SP	CCA		B		4/9/2023
2021 PO4687950669	KU	5	35 BRN	SP	CRE	ID	X	RP3	4/10/2023
2021 PO5846110865	KU	4	40 ACW	SP	CRE	ED,ID,IP,MD,RB	X	PX	4/11/2023
2021 PO3455151415	KU	3	45 ACW	SP	CRE		VX	RP1	4/12/2023
2021 PO4156685983	F	4	40 BRO	SP	CRE	HH,ID,RB	VX	RP1	4/13/2023
2021 PO4152085946	LGE	5	35 BRO	SP	CCA		V		4/14/2023
2021 Po44591484485a	KU	5	35 BRN	SP	CCA		V		4/15/2023
2021 Po4485048231a	KU	4	40 BRN	SP	CCA		V		4/16/2023
2021 PO4155485971	LGE	4	35 BRO	SP	CRE		V		4/17/2023
2021 PO5850110970	KU	5	45 ACW	SP	S		V		4/18/2023
2021 PO8917665497	LGE	4	40 ACE	SP	CCA		V		4/19/2023
2021 PO4175485331	LGE	4	30 ACE	SP	CRE		V		4/20/2023
2021 PO4152985984	F	3	45 BRO	SP	CCA		V		4/21/2023
2021 PO4154285983	F	4	40 BRO	SP	CRE		V		4/22/2023
2021 PO4155485983	F	4	40 BRO	SP	A		V		4/23/2023
2021 PO4154185956	F	4	40 BRO	SP	CRE		V		4/24/2023
2021 PO4155385956-B	KU	4	35 BRO	SP	CCA		V		4/25/2023
2021 PO4155385956-A	KU	4	35 BRO	SP	CCA		V		4/26/2023
2021 PO4156585959	F	3	45 BRO	SP	CCA		V		4/27/2023
2021 PO4155385956	F	3	45 BRO	SP	A		V		4/28/2023
2021 PO4156485947	F	4	40 BRO	SP	A		V		4/29/2023
2021 Po4690951505a	KU	3	45 BRN	SP	CCA		V		4/30/2023
2021 PO4640051219	KU	4	40 BRN	SP	CCA		V		5/1/2023
2021 PO4635351091	F	4	40 BRN	SP	CRE		V		5/2/2023
2021 PO4152885953	F	4	40 BRO	SP	CCA		V		5/3/2023
2021 PO5883411207	KU	5	45 ACW	SP	S		V		5/4/2023
2021 PO5879411260	KU	5	45 ACW	SP	S		V		5/5/2023
2021 PO5813911084	KU	3	45 ACW	SP	S		V		5/6/2023
2021 PO4156685971	F	4	40 BRO	SP	CRE		V		5/7/2023
2021 PO4153685944	LGE	4	35 BRO	SP	CCA		V		5/8/2023
2021 PO4428048214	KU	4	40 BRN	SP	CRE		V		5/9/2023
2021 PO0144883981	KU	4	40 UNK	SP	CCA		V		5/10/2023
2021 PO4147786026	F	3	45 BRO	SP	CCA		V		5/11/2023
2021 PO0210285247	KU	1	65 UNK	SP	CCA		V		5/12/2023
2021 PO5921311451	F	4	40 ACW	SP	P		V		5/13/2023
2021 PO5903311364	KU	5	45 ACW	SP	S		V		5/14/2023
2021 PO5943211524	F	5	35 ACW	SP	P		V		5/15/2023
2021 PO9988881613	KU	4	40 UNK	SP	CCA		V		5/16/2023

2021	PO4156085992	LGE	4	40 BRO	SP	CCA		V		5/17/2023	
2021	PO4172985357	LGE	4	35 ACE	SP	CCA		V		5/18/2023	
2021	PO4156786018	F	3	50 BRO	SP	CRE		V		5/19/2023	
2021	PO4156886023	F	3	45 BRO	SP	CRE		V		5/20/2023	
2021	PO4156886037	F	4	35 BRO	SP	A		V		5/21/2023	
2021	PO4156986045	F	3	45 BRO	SP	CRE		V		5/22/2023	
2021	PO5867710979	F	5	35 ACW	SP	P		V		5/23/2023	
2021	PO5832910928	KU	4	40 ACW	SP	S		V		5/24/2023	
2021	PO5857910895	F	6	30 ACW	SP	P	EP,IP	V		5/25/2023	
2021	PO5840410873	KU	4	40 ACW	SP	S		V		5/26/2023	
2021	PO4152886029	F	4	35 BRO	SP	A		V		5/27/2023	
2021	PO5876011052	F	4	35 ACW	SP	P		V		5/28/2023	
2021	PO4451549149	KU	4	40 BRN	SP	CCA		V		5/29/2023	
2021	PO4443549151	KU	4	40 BRN	SP	CCA		V		5/30/2023	
2021	PO4444149102	KU	6	35 BRN	SP	CCA		V		5/31/2023	
2021	PO0027582152	KU	4	40 UNK	SP	CCA		V		6/1/2023	
2021	PO0012181938	KU	3	45 UNK	SP	CCA		V		6/2/2023	
2021	PO9950881065	KU	1	60 UNK	SP	CCA		V		6/3/2023	
2021	PO9912380713	KU	2	55 UNK	SP	CRE		V		6/4/2023	
2021	PO9911280705	KU	2	55 UNK	SP	CRE		V		6/5/2023	
2021	PO4171685344	LGE	4	30 ACE	SP	CRE		V		6/6/2023	
2021	PO4155286025	F	3	45 BRO	SP	CRE		V		6/7/2023	
2021	PO4153986026	F	3	50 BRO	SP	CRE		V		6/8/2023	
2021	PO4153186014	F	3	45 BRO	SP	A		V		6/9/2023	
2021	PO4154386013	F	4	40 BRO	SP	CRE		V		6/10/2023	
2021	PO4155586013	F	3	45 BRO	SP	A		V		6/11/2023	
2021	PO4173185396	LGE	4	40 ACE	SP	CCA		V		6/12/2023	
2021	PO4173185383	LGE	4	35 ACE	SP	CCA		V		6/13/2023	
2021	PO4156685995	F	4	40 BRO	SP	CRE		V		6/14/2023	
2021	PO4156786006	F	4	40 BRO	SP	CRE		V		6/15/2023	
2021	PO4173185375	LGE	4	35 ACE	SP	CCA		V		6/16/2023	
2021	PO4173485336	LGE	4	35 ACE	SP	P	ED,ID,IP,RB	TX	RR	6/17/2023	
2021	PO4176685363	LGE	4	40 ACE	SP	CRE		ED,ID		TD	6/18/2023
2021	PO4170585337	LGE	4	40 ACE	SP	P		ED,ID		TD	6/19/2023
2021	PO4171585337	LGE	4	40 ACE	SP	P		ED,ID		TD	6/20/2023
2021	PO4172685336	LGE	4	40 ACE	SP	P		ED,ID		TD	6/21/2023
2021	PO4174685331	LGE	4	35 ACE	SP	P		ED,ID		TD	6/22/2023
2021	PO4175485334	LGE	4	40 ACE	SP	P		ED,ID		TD	6/23/2023
2021	PO4176685335	LGE	4	40 ACE	SP	P		ED,ID		TD	6/24/2023
2021	PO4176685324	LGE	4	35 ACE	SP	CRE		ED,ID		TD	6/25/2023
2021	PO4181285330	LGE	4	40 ACE	SP	P		ED,ID		TD	6/26/2023
2021	PO4180085331	LGE	4	40 ACE	SP	P		ED,ID		TD	6/27/2023
2021	PV4180785331	LGE	4	40 ACE	SP	CRE		ED,ID		TD	6/28/2023
2021	PO4177785333	LGE	4	40 ACE	SP	P		ED,ID		TD	6/29/2023
2021	PO3713445824	KU	4	40 UNK	SP	CRE		ID		TD	6/30/2023
2021	PO3737045831	KU	4	40 UNK	SP	CRE		ID		TD	7/1/2023
2021	PO4182285330	LGE	4	40 ACE	SP	CRE		ED,ID		TD	7/2/2023
2021	PO338353225	KU	4	40 BRO	SP	CRE		ID		TD	7/3/2023
2021	PO3701745802	KU	4	40 UNK	SP	CRE		ED,ID		TD	7/4/2023
2021	PO4176685352	LGE	4	40 ACE	SP	P		ED,ID		TD	7/5/2023
2021	PO4176685344	LGE	4	40 ACE	SP	CRE		ED,ID,IP		TD	7/6/2023
2021	PO4156085942	LGE	4	40 BRO	SP	A		ED,ID,IP		TD	7/7/2023
2021	PO4485048231	KU	4	40 BRN	SP	CRE		ID		TD	7/8/2023
2021	PO4459148485	KU	4	40 BRN	SP	CRE		ID		TD	7/9/2023

2021 PO4176585376	LGE	4	40 ACE	SP	P	ED,ID	TD	7/10/2023
2021 PO4176685388	LGE	4	40 ACE	SP	P	ED,ID	TD	7/11/2023
2021 PO0207984965	KU	2	60 UNK	SP	CRE	ID	TD	7/12/2023
2021 PO0286586586	KU	3	50 UNK	SP	CRE	ID,IP,SRS	TD	7/13/2023
2021 PO4147885953	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	7/14/2023
2021 PO3404851668	KU	5	35 UNK	SP	CRE	ED,ID	TD	7/15/2023
2021 PO4177885395	LGE	4	40 ACE	SP	CRE	ED,ID	TD	7/16/2023
2021 PO4638251339	KU	6	30 BRN	SP	CRE	ID	TD	7/17/2023
2021 PO5818610939	KU	5	35 ACW	SP	CRE	ED,ID	TD	7/18/2023
2021 PO4690951505	KU	4	40 BRN	SP	CRE	ID	TD	7/19/2023
2021 PO4652651616	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	7/20/2023
2021 PO5872811095	KU	2	55 ACW	SP	CRE	ED,ID	TD	7/21/2023
2021 PO5888911223	KU	2	50 ACW	SP	CRE	ED,ID,IP	TD	7/22/2023
2021 PO4132885853	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	7/23/2023
2021 PO4400548761	KU	4	40 BRN	SP	CRE	ID	TD	7/24/2023
2021 PO0160684228	KU	4	40 UNK	SP	CRE	ID,IP	TD	7/25/2023
2021 PO0176884481	KU	5	35 UNK	SP	CRE	ID	TD	7/26/2023
2021 PO4114048628	KU	4	40 BRN	SP	CRE	ID	TD	7/27/2023
2021 PO3434951510	KU	4	40 UNK	SP	CRE	ID	TD	7/28/2023
2021 PO4104148700	KU	6	30 BRN	SP	CRE	ID	TD	7/29/2023
2021 PO4438848512	KU	4	40 BRN	SP	CRE	ID	TD	7/30/2023
2021 PO0128683728	KU	5	35 UNK	SP	CRE	ID	TD	7/31/2023
2021 PO4152085952	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	8/1/2023
2021 PO4151685948	LGE	4	40 BRO	SP	A	ED,ID	TD	8/2/2023
2021 PO3423052795	KU	4	40 UNK	SP	CRE	ID	TD	8/3/2023
2021 PO4181785361	LGE	4	30 ACE	SP	P	ED,ID	TD	8/4/2023
2021 PO4181285361	LGE	4	40 ACE	SP	P	ED,ID	TD	8/5/2023
2021 PO4180485362	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/6/2023
2021 PO4179685362	LGE	4	40 ACE	SP	P	ED,ID	TD	8/7/2023
2021 PO4179185363	LGE	4	35 ACE	SP	CRE	ED,ID	TD	8/8/2023
2021 PO3426752479	KU	4	40 UNK	SP	CRE	ID	TD	8/9/2023
2021 PO4178385363	LGE	4	40 ACE	SP	P	ED,ID	TD	8/10/2023
2021 PO4177685364	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	8/11/2023
2021 PO4176785364	LGE	4	35 ACE	SP	CRE	ED,ID	TD	8/12/2023
2021 PO4181685393	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	8/13/2023
2021 PO4181585380	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	8/14/2023
2021 PO0255986049	KU	4	40 UNK	SP	CCA	ID,SRS	TD	8/15/2023
2021 PO4471148677	KU	4	40 BRN	SP	CRE	ID	TD	8/16/2023
2021 PO5907011349	KU	2	50 ACW	SP	CRE	ED,ID	TD	8/17/2023
2021 PO5932711546	KU	2	60 ACW	SP	CRE	ED,ID	TD	8/18/2023
2021 PO0223585481	KU	3	50 UNK	SP	CRE	ID	TD	8/19/2023
2021 PO0240885783	KU	3	40 UNK	SP	CRE	ID	TD	8/20/2023
2021 PO4181685402	LGE	4	35 ACE	SP	CRE	ED,ID	TD	8/21/2023
2021 PO4182885390	LGE	4	35 ACE	SP	P	ED,ID	TD	8/22/2023
2021 PO4180185393	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	8/23/2023
2021 PO4147385955	LGE	5	25 BRO	SP	A	ED,ID,IP	TD	8/24/2023
2021 PO5926510247	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/25/2023
2021 PO5924510227	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/26/2023
2021 PO5908110254	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/27/2023
2021 PO4149885950	LGE	4	40 BRO	SP	A	ED,ID	TD	8/28/2023
2021 PO4477348667	KU	6	30 BRN	SP	CRE	ID	TD	8/29/2023
2021 PO4178585394	LGE	4	40 ACE	SP	P	ED,ID	TD	8/30/2023
2021 PO4179085394	LGE	4	45 ACE	SP	CRE	ED,ID	TD	8/31/2023
2021 PO4147886032	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	9/1/2023

2021 PO4662450816	KU	4	40 BRN	SP	CRE	ID	TD		9/2/2023
2021 PO4642550879	KU	4	40 BRN	SP	CRE	ID	TD		9/3/2023
2021 PO4644150910	KU	5	30 BRN	SP	CRE	ID	TD		9/4/2023
2021 PO4626051146	KU	4	45 BRN	SP	CRE	ID	TD		9/5/2023
2021 PO4643151321	KU	4	40 BRN	SP	CRE	ID	TD		9/6/2023
2021 PO3364353237	KU	4	40 INP	SP	CRE	ID	TD		9/7/2023
2021 PO3348253240	KU	4	40 BRO	SP	CRE	ID	TD		9/8/2023
2021 PO4174385366	LGE	4	40 ACE	SP	P	ED,ID	TD		9/9/2023
2021 PO4175485365	LGE	4	40 ACE	SP	P	ED,ID	TD		9/10/2023
2021 PO4174585369	LGE	4	35 ACE	SP	P	ED,ID	TD		9/11/2023
2021 PO4173285366	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		9/12/2023
2021 PO4173185411	LGE	4	35 ACE	SP	P	ED,ID	TD		9/13/2023
2021 PO4172885411	LGE	4	35 ACE	SP	P	ED,ID,IP	TD		9/14/2023
2021 PO4154285998	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		9/15/2023
2021 PO4469649080	KU	4	40 BRN	SP	CRE	ID	TD		9/16/2023
2021 PO4477248898	KU	4	40 BRN	SP	CRE	ID	TD		9/17/2023
2021 PO4480649126	KU	4	40 BRN	SP	CRE	ID	TD		9/18/2023
2021 PO4181485369	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		9/19/2023
2021 PO0272986346	KU	3	40 UNK	SP	CRE	ID	TD		9/20/2023
2021 PO0295386804	KU	3	50 UNK	SP	CRE	ID,IP,SRS	TD		9/21/2023
2021 PO0305387050	KU	3	45 UNK	SP	CRE	ID	TD		9/22/2023
2021 PO4154486028	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		9/23/2023
2021 PO9979181479	KU	4	40 UNK	SP	CRE	ID,IP	TD		9/24/2023
2021 PO9968781333	KU	3	40 UNK	SP	CRE	ID	TD		9/25/2023
2021 PO9958781183	KU	3	45 UNK	SP	CRE	ID,SRS	TD		9/26/2023
2021 PO4176685396	LGE	4	35 ACE	SP	CRE	ED,HH,ID,IP	TD		9/27/2023
2021 PO5848611034	KU	4	40 ACW	SP	S	ED,MD,SRC	T		9/28/2023
2021 PO4174585335	LGE	4	40 ACE	SP	P	ED,HH,ID,RB	BX	RP1	9/29/2023
2021 PO5907310309	F	4	40 ACW	DF	CRE	ED,HH,ID,RB	BX	RP1	9/30/2023
2021 PO3348453531	KU	4	40 BRO	SP	CRE	ID	BD		10/1/2023
2021 PO0001681792	KU	3	40 UNK	SP	CRE	ID	BD		10/2/2023
2021 PO4660750636	KU	6	30 BRN	SP	CRE	ID	BD		10/3/2023
2021 PO4648550860	KU	4	40 BRN	SP	CRE	ID	BD		10/4/2023
2021 PO5924410095	KU	4	45 ACW	SP	CRE	ED,ID,IP	BD		10/5/2023
2021 PO3379351608	KU	4	45 UNK	SP	CRE	ID	BD		10/6/2023
2021 PO3410452944	KU	4	40 UNK	SP	CRE	ID	BD		10/7/2023
2021 PO4412047796	KU	4	40 BRN	SP	CRE	ID	BD		10/8/2023
2021 PO4496748884	KU	4	40 BRN	SP	CRE	ID	BD		10/9/2023
2021 PO4153085944	LGE	4	30 BRO	SP	A	ID	BD		10/10/2023
2021 PO0193084733	KU	3	45 UNK	SP	CRE	ID	BD		10/11/2023
2021 PO4420248738	KU	4	40 BRN	SP	CRE	ID	BD		10/12/2023
2021 PO4444248710	KU	4	40 BRN	SP	CRE	ID	BD		10/13/2023
2021 PO4176185365	LGE	4	40 ACE	SP	CRE	ED,ID	BD		10/14/2023
2021 PO3386253443	KU	5	35 BRO	SP	CCA		B		10/15/2023
2021 PO4041047818	KU	4	40 BRN	SP	CRE	HH,ID	X	RP1	10/16/2023
2021 PO4020947879	KU	4	40 BRN	SP	CRE	EP,ID	X	RP2	10/17/2023
2021 PO9762758678	KU	4	40 UNK	SP	CRE	HH,ID	X	RP3	10/18/2023
2021 PO4174785355	LGE	4	35 BRO	SP	CCA	ED,ID,RB	X	RP2	10/19/2023
2021 PO3983047664	KU	2	40 BRN	SP	CRE	HH,ID,IP	X	RP2	10/20/2023
2021 PO4152186027	F	3	55 BRO	SP	CRE	ED,ID,IP,MD,RB	VX	RP1	10/21/2023
2021 PO4170085366	LGE	4	35 BRO	SP	CRE		V		10/22/2023
2021 PO4170285369	LGE	4	35 BRO	SP	CCA		V		10/23/2023
2021 PO4170085378	LGE	4	35 BRO	SP	CCA		V		10/24/2023
2021 PO5659810203	F	4	40 ACW	SP	CRE		V		10/25/2023

2021 PO4116684387	F	4	40 BRO	SP	CRE		V	10/26/2023
2021 PO4115584385	F	4	30 BRO	SP	CRE		V	10/27/2023
2021 PO3727318226	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/28/2023
2021 PO3723518202	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/29/2023
2021 PO3865613979	KU	4	45 XXX	SP	CRE	ID	TD	10/30/2023
2021 PO4454185703	LGE	4	30 ACE	SP	P	ED,ID	TD	10/31/2023
2021 PO3903613944	KU	4	45 XXX	SP	CRE	ID	TD	11/1/2023
2021 PO8057009256	KU	3	45 BRN	SP	CRE	ED	TD	11/2/2023
2021 PO4432985224	LGE	4	30 ACE	SP	CRE	ED,ID	TD	11/3/2023
2021 PO3946516041	KU	4	45 XXX	SP	CRE	ID	TD	11/4/2023
2021 PO9913791530	KU	3	45 UNK	SP	CRE	ED,ID	TD	11/5/2023
2021 PO9595691063	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/6/2023
2021 PO4393785254	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	11/7/2023
2021 PO9465996474	KU	5	35 XXX	SP	P	ED,ID,IP	TD	11/8/2023
2021 PO4434586139	LGE	4	35 BRO	SP	A	ED,ID	TD	11/9/2023
2021 PO9572691059	KU	5	35 UNK	SP	CRE	ED,ID	TD	11/10/2023
2021 PO8004610043	KU	3	45 KOP	SP	CRE	ED	TD	11/11/2023
2021 PO8006310077	KU	3	45 KOP	SP	CRE	ED	TD	11/12/2023
2021 PO2185623490	KU	2	60 BRN	SP	CRE	ED,ID	TD	11/13/2023
2021 PO2164723529	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/14/2023
2021 PO2134823572	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/15/2023
2021 PO4435086162	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/16/2023
2021 PO7990810231	KU	4	40 KOP	SP	CRE	ED	TD	11/17/2023
2021 PO4432786151	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	11/18/2023
2021 PO9365891104	KU	4	40 UNK	SP	CRE	ED,ID	TD	11/19/2023
2021 PO4393885250	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	11/20/2023
2021 PO7980410550	KU	3	45 BRN	SP	CRE	ED	TD	11/21/2023
2021 PO9301390971	KU	4	40 UNK	SP	CRE	ED,ID	TD	11/22/2023
2021 PO9328891112	KU	4	35 UNK	SP	CRE	ED,ID,IP	TD	11/23/2023
2021 PO9304090081	KU	5	35 UNK	SP	CRE	ED,ID	TD	11/24/2023
2021 PO4458686054	LGE	3	45 ACE	SP	CRE	ED	TD	11/25/2023
2021 PO4455886046	LGE	4	35 ACE	SP	P	ED	TD	11/26/2023
2021 PO9340691233	KU	4	40 UNK	SP	CRE	ED,ID	TD	11/27/2023
2021 PO9341390983	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	11/28/2023
2021 PO9543495213	KU	3	45 XXX	SP	CRE	ED,ID	TD	11/29/2023
2021 PO9535095312	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/30/2023
2021 PO9700994479	KU	3	45 XXX	SP	CRE	ED,ID	TD	12/1/2023
2021 PO3600516157	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/2/2023
2021 PO8086212081	KU	5	35 BRN	SP	CRE	ED	TD	12/3/2023
2021 PO8022912121	KU	5	35 BRN	SP	CRE	ED	TD	12/4/2023
2021 PO4477885884	LGE	4	40 ACE	SP	P	ED	TD	12/5/2023
2021 PO3625717339	KU	4	40 BRN	SP	CRE	ID	TD	12/6/2023
2021 PO4470685898	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/7/2023
2021 PO4473585975	LGE	3	45 ACE	SP	P	ED,IP	TD	12/8/2023
2021 PO3580317953	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	12/9/2023
2021 PO4239413515	KU	5	35 XXX	SP	CRE	ID	TD	12/10/2023
2021 PO4231313545	KU	2	45 XXX	SP	CRE	ID	TD	12/11/2023
2021 PO9696494070	KU	3	45 XXX	SP	CRE	ED,ID	TD	12/12/2023
2021 PO3546916391	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/13/2023
2021 PO8025312037	KU	4	35 BRN	SP	CRE	ED	TD	12/14/2023
2021 PO7964811609	KU	4	45 BRN	SP	CRE	ED	TD	12/15/2023
2021 PO4457686046	LGE	4	35 ACE	SP	P	ED,IP	TD	12/16/2023
2021 PO4462486042	LGE	3	45 ACE	SP	CRE	ED,IP	TD	12/17/2023
2021 PO4464386070	LGE	3	45 ACE	SP	P	ED	TD	12/18/2023



2021	PO4465086131	LGE	3	55 ACE	SP	P	ED	TD	12/19/2023
2021	PO4463786100	LGE	4	35 ACE	SP	P	ED	TD	12/20/2023
2021	PO4462585929	LGE	4	30 ACE	SP	P	ED	TD	12/21/2023
2021	PO7949810622	KU	3	45 BRN	SP	CRE	ED	TD	12/22/2023
2021	PO3945114997	KU	5	35 XXX	SP	CRE	ID,IP	TD	12/23/2023
2021	PO3939614794	KU	5	35 XXX	SP	CRE	ID	TD	12/24/2023
2021	PO3933814578	KU	4	40 XXX	SP	CRE	ID	TD	12/25/2023
2021	PO3927414346	KU	5	35 XXX	SP	CRE	ID	TD	12/26/2023
2021	PO3925214158	KU	5	35 XXX	SP	CCA	ID	TD	12/27/2023
2021	PO4423785784	LGE	4	30 BRO	SP	CRE	ED,ID	TD	12/28/2023
2021	PO3658916638	KU	5	35 BRN	SP	CRE	ED,ID	TD	12/29/2023
2021	PO9599096271	KU	4	45 XXX	SP	CRE	ED,ID	TD	12/30/2023
2021	PO9596396313	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD	TD	12/31/2023
2021	PO9587396308	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	1/1/2024
2021	PO7969410954	KU	4	40 BRN	SP	CRE	ED,SRS	TD	1/2/2024
2021	PO4457685842	LGE	3	45 ACE	SP	P	ED,EP	TD	1/3/2024
2021	PO4458385847	LGE	3	45 ACE	SP	P	ED	TD	1/4/2024
2021	PO4458385851	LGE	4	30 ACE	SP	P	ED	TD	1/5/2024
2021	PO4463185885	LGE	3	45 ACE	SP	P	ED	TD	1/6/2024
2021	PO9600789236	KU	4	40 UNK	SP	CRE	ED,ID	TD	1/7/2024
2021	PO4427385837	LGE	4	30 BRO	SP	CCA	ED,ID,IP	TD	1/8/2024
2021	PO9611789237	KU	5	35 UNK	SP	CRE	ED,ID	TD	1/9/2024
2021	PO9592888943	KU	4	40 UNK	SP	CRE	ED,ID	TD	1/10/2024
2021	PO9811288369	KU	4	40 UNK	SP	CRE	ED,ID	TD	1/11/2024
2021	PO3637115940	KU	5	35 BRN	SP	CRE	ED,ID	TD	1/12/2024
2021	PO9199589900	KU	5	35 UNK	SP	CRE	ED,ID	TD	1/13/2024
2021	PO7964510872	KU	3	45 BRN	SP	CRE	ED	TD	1/14/2024
2021	PO9210890199	KU	4	40 UNK	SP	CRE	ED,ID	TD	1/15/2024
2021	PO9586588893	KU	4	40 UNK	SP	CRE	ED,ID	TD	1/16/2024
2021	PO4207514047	KU	6	30 XXX	SP	CRE	ID	TD	1/17/2024
2021	PO4201314014	KU	5	35 XXX	SP	CRE	ID	TD	1/18/2024
2021	PO3616516071	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	1/19/2024
2021	44644786104	LGE	3	45 ACE	SP	CRE	ED	TD	1/20/2024
2021	PO9106590902	KU	4	40 UNK	SP	CRE	ED,ID	TD	1/21/2024
2021	PO7985311218	KU	3	45 BRN	SP	CRE	ED	TD	1/22/2024
2021	PO9138690911	KU	5	35 UNK	SP	CRE	ED,ID	TD	1/23/2024
2021	PO9211490932	KU	4	40 UNK	SP	CRE	ED,ID	TD	1/24/2024
2021	4467186002	LGE	3	45 ACE	SP	CRE	ED,IP	TD	1/25/2024
2021	4467386006	LGE	3	45 ACE	SP	CRE	ED	TD	1/26/2024
2021	4468286001	LGE	3	45 ACE	SP	P	ED	TD	1/27/2024
2021	4468286004	LGE	3	45 ACE	SP	P	ED	TD	1/28/2024
2021	4468486004	LGE	3	45 ACE	SP	P	ED,IP	TD	1/29/2024
2021	PO3639716073	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/30/2024
2021	PO4146414250	KU	4	40 XXX	SP	CCA	ED	TD	1/31/2024
2021	PO4179514098	KU	6	30 XXX	SP	CRE	ED,ID,MD	TD	2/1/2024
2021	PO9610296105	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/2/2024
2021	PO4200213777	KU	4	40 XXX	SP	CRE	ID	TD	2/3/2024
2021	PO9085690895	KU	4	40 UNK	SP	CRE	ID	TD	2/4/2024
2021	PO8050711055	KU	4	40 BRN	SP	CRE	ED	TD	2/5/2024
2021	PO4213413858	KU	4	40 XXX	SP	CRE	ID	TD	2/6/2024
2021	PO8982791560	KU	4	40 UNK	SP	CRE	ED,ID	TD	2/7/2024
2021	PO9001491554	KU	4	40 KOP	SP	CRE	ED,ID	TD	2/8/2024
2021	PO9044991309	KU	4	40 UNK	SP	CRE	ED,ID	TD	2/9/2024
2021	PO7923010965	KU	4	40 BRN	SP	CRE	ED	TD	2/10/2024

2021 PO4227813944	KU	6	30 XXX	SP	CRE	ID,IP	TD	2/11/2024
2021 PO4430586041	LGE	4	35 BRO	SP	A	ED,ID	TD	2/12/2024
2021 PO4485585532	LGE	3	45 ACE	SP	CCA	ED,ID	TD	2/13/2024
2021 PO4484985528	LGE	3	45 ACE	SP	A	ED	TD	2/14/2024
2021 PO4483285517	LGE	3	45 ACE	SP	CCA	ED,ID	TD	2/15/2024
2021 PO9622294508	KU	6	30 XXX	SP	CRE	ED,ID	TD	2/16/2024
2021 PO3660319646	KU	3	45 BRN	SP	CRE	ED,ID	TD	2/17/2024
2021 PO9431291001	KU	2	55 UNK	SP	CRE	ED,ID	TD	2/18/2024
2021 PO9447091020	KU	4	40 UNK	SP	CRE	ED,ID	TD	2/19/2024
2021 PO9448390722	KU	4	40 KOP	SP	CRE	ED,ID	TD	2/20/2024
2021 PO3679719535	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD	2/21/2024
2021 PO8008210119	KU	3	45 BRN	SP	CRE	ED	TD	2/22/2024
2021 PO4213213646	KU	4	40 XXX	SP	CRE	ID,IP	TD	2/23/2024
2021 PO9518691050	KU	6	35 UNK	SP	CRE	ED,ID	TD	2/24/2024
2021 PO3532519536	KU	3	45 BRN	SP	CRE	ED,ID	TD	2/25/2024
2021 PO3521819406	KU	3	45 BRN	SP	CRE	ED,ID	TD	2/26/2024
2021 PO4024116161	KU	4	40 XXX	SP	CRE	ID	TD	2/27/2024
2021 PO3986216314	KU	4	45 XXX	SP	CRE	ID	TD	2/28/2024
2021 PO3963316427	KU	4	45 XXX	SP	CRE	ID	TD	2/29/2024
2021 PO3968416156	KU	6	30 XXX	SP	CRE	ID,IP	TD	3/1/2024
2021 PO3960016199	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/2/2024
2021 PO8031610614	KU	3	45 BRN	SP	CRE	ED	TD	3/3/2024
2021 PO4457385459	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/4/2024
2021 PO4458485467	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/5/2024
2021 PO3961115259	KU	4	40 XXX	SP	CRE	ID	TD	3/6/2024
2021 PO3642019751	KU	3	45 BRN	SP	CRE	ED,ID	TD	3/7/2024
2021 PO9453590145	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/8/2024
2021 PO9407291376	KU	5	35 UNK	SP	CRE	ED,ID	TD	3/9/2024
2021 PO3968715168	KU	5	35 XXX	SP	CRE	ID	TD	3/10/2024
2021 PO9512291850	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/11/2024
2021 PO9549292852	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/12/2024
2021 4473985579-a	LGE	3	40 ACE	SP	CRE	ED,ID	TD	3/13/2024
2021 PO3547819727	KU	3	45 BRN	SP	CRE	ED,ID	TD	3/14/2024
2021 PO9517892648	KU	5	35 UNK	SP	CRE	ED,ID	TD	3/15/2024
2021 PO9568695888	KU	3	45 XXX	SP	CRE	ED,ID,IP,MD	TD	3/16/2024
2021 PO9567195228	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	3/17/2024
2021 PO9424591275	KU	2	50 UNK	SP	CRE	ED,ID	TD	3/18/2024
2021 PO7872007548	KU	3	45 BRN	SP	CRE	ED	TD	3/19/2024
2021 PO1885424096	KU	5	35 BRN	SP	CRE	ED,ID	TD	3/20/2024
2021 PO1865424150	KU	5	35 BRN	SP	CRE	ED,ID	TD	3/21/2024
2021 PO7889907714	KU	3	45 BRN	SP	CRE	ED	TD	3/22/2024
2021 PO1824724365	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	3/23/2024
2021 PO3741715805	KU	2	60 XXX	SP	CRE	ID	TD	3/24/2024
2021 PO3732915824	KU	5	35 XXX	SP	CRE	ID	TD	3/25/2024
2021 PO9621594656	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/26/2024
2021 PO4454585691	LGE	3	45 ACE	SP	A	ED	TD	3/27/2024
2021 PO4633812419	KU	6	30 XXX	SP	CCA	ED	TD	3/28/2024
2021 PO4455085682	LGE	4	40 ACE	SP	P	ED	TD	3/29/2024
2021 PO4455785671	LGE	3	45 ACE	SP	A	ED	TD	3/30/2024
2021 PO4456185665	LGE	4	30 ACE	SP	P	ED	TD	3/31/2024
2021 PO4454985810	LGE	3	45 ACE	SP	CCA	ED	TD	4/1/2024
2021 PO4604512383	KU	6	30 XXX	SP	CRE	ID	TD	4/2/2024
2021 PO7896007769	KU	4	45 BRN	SP	CRE	ED	TD	4/3/2024
2021 PO3690219247	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD	4/4/2024

2021 PO1788924851	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/5/2024
2021 PO1798325397	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/6/2024
2021 PO7935011130	KU	3	45 BRN	SP	CRE	ED	TD	4/7/2024
2021 PO9109092601	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/8/2024
2021 PO9079290551	KU	5	35 XXX	SP	CRE	ED,ID	TD	4/9/2024
2021 PO9080390251	KU	5	35 XXX	DF	CRE	ED,ID,IP	TD	4/10/2024
2021 PO9124589504	KU	2	40 XXX	SP	CRE	ED,ID	TD	4/11/2024
2021 PO9076890034	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	4/12/2024
2021 PO9617694251	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	4/13/2024
2021 PO1821024272	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/14/2024
2021 PO9610193588	KU	3	45 BRO	SP	CRE	ED,ID	TD	4/15/2024
2021 PO4417586151	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	4/16/2024
2021 PO9629593472	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/17/2024
2021 PO9607094120	KU	5	35 XXX	SP	CRE	ED,ID	TD	4/18/2024
2021 PO9602194006	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	4/19/2024
2021 PO9634394634	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/20/2024
2021 PO9628694538	KU	3	45 XXX	SP	CRE	ED,ID	TD	4/21/2024
2021 PO9691993076	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/22/2024
2021 PO1899124059	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/23/2024
2021 PO9683393134	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/24/2024
2021 PO3709716434	KU	2	65 XXX	SP	CRE	ID	TD	4/25/2024
2021 PO3752615782	KU	5	35 XXX	SP	CRE	ID	TD	4/26/2024
2021 PO7954008306	KU	3	45 BRN	SP	CCA	MD,SRS	TD	4/27/2024
2021 PO7939308171	KU	3	45 BRN	SP	CRE	ED	TD	4/28/2024
2021 PO4396085216	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/29/2024
2021 PO1939823964	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/30/2024
2021 PO1915324017	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/1/2024
2021 PO1970723895	KU	5	35 BRN	SP	CRE	ED,ID	TD	5/2/2024
2021 PO9780892465	KU	2	45 UNK	SP	CRE	ED,ID	TD	5/3/2024
2021 PO4470185573	LGE	3	45 ACE	SP	P	ED,ID	TD	5/4/2024
2021 PO8017108891	KU	3	45 BRN	SP	CRE	ED	TD	5/5/2024
2021 PO2068223691	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/6/2024
2021 PO2039323747	KU	5	35 BRN	SP	CRE	ED,ID	TD	5/7/2024
2021 PO7995408692	KU	3	45 BRN	SP	CRE	ED	TD	5/8/2024
2021 PO3917515388	KU	4	45 XXX	SP	CRE	ID	TD	5/9/2024
2021 PO9801292321	KU	3	45 UNK	SP	CRE	ED,ID	TD	5/10/2024
2021 PO2020423785	KU	5	35 BRN	SP	CRE	ED,ID	TD	5/11/2024
2021 PO3795015743	KU	6	30 XXX	SP	CRE	ID,IP	TD	5/12/2024
2021 PO	KU	5	35 XXX	SP	CRE	ED,ID	TD	5/13/2024
2021 PO9466495292	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	5/14/2024
2021 PO9476195418	KU	5	35 XXX	SP	P	ED,ID	TD	5/15/2024
2021 PO9442995235	KU	5	35 XXX	SP	CRE	ED,ID	TD	5/16/2024
2021 PO4392785242	LGE	4	35 BRO	SP	A	ED,ID	TD	5/17/2024
2021 PO9090891150	KU	4	35 UNK	SP	CRE	ED,ID	TD	5/18/2024
2021 PO7971511369	KU	3	45 BRN	SP	CRE	ED	TD	5/19/2024
2021 PO9106992221	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/20/2024
2021 PO9103891602	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/21/2024
2021 PO9102291302	KU	4	35 UNK	SP	CRE	ED,ID	TD	5/22/2024
2021 PO9587993651A	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	5/23/2024
2021 PO9587993651	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/24/2024
2021 PO9560293891	KU	2	50 UNK	SP	CRE	ED,ID	TD	5/25/2024
2021 PO8003210015	KU	2	50 KOP	SP	CRE	ED	TD	5/26/2024
2021 PO8022209868	KU	3	45 KOP	SP	CRE	ED	TD	5/27/2024
2021 PO4430686151	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	5/28/2024

2021 PO4435386158	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	5/29/2024
2021 PO9487390736	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/30/2024
2021 PO3698819008	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD	5/31/2024
2021 PO3707818759	KU	3	45 BRN	SP	CRE	ED,ID	TD	6/1/2024
2021 PO9616691067	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	6/2/2024
2021 PO4468085547	LGE	UNK	45 ACE	SP	A	ED,ID	TD	6/3/2024
2021 PO8067110970	KU	3	45 BRN	SP	CRE	ED	TD	6/4/2024
2021 PO4434986156	LGE	4	40 BRO	SP	A	ED,ID	TD	6/5/2024
2021 PO9537089631	KU	6	30 UNK	SP	CRE	ED,ID	TD	6/6/2024
2021 PO9518095514	KU	2	50 XXX	SP	CRE	ED,ID,IP	TD	6/7/2024
2021 PO8080309475	KU	3	45 BRN	SP	CRE	ED,ID	TD	6/8/2024
2021 PO1802624518	KU	5	35 BRN	SP	CRE	ED,ID	TD	6/9/2024
2021 PO9590993714	KU	4	40 UNK	SP	CRE	ED,ID	TD	6/10/2024
2021 PO9912890916	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	6/11/2024
2021 PO1784624648	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	6/12/2024
2021 PO9911991036	KU	2	40 UNK	SP	CRE	ED,ID	TD	6/13/2024
2021 PO9887791312	KU	4	40 UNK	SP	CRE	ED,ID	TD	6/14/2024
2021 PO9907791312	KU	3	45 UNK	SP	CRE	ED,ID	TD	6/15/2024
2021 PO4456185790	LGE	3	45 ACE	SP	P	ED	TD	6/16/2024
2021 PO2097823634	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	6/17/2024
2021 PO9934091389	KU	6	30 UNK	SP	CRE	ED,ID	TD	6/18/2024
2021 PO8068009360	KU	3	45 BRN	SP	CRE	ED	TD	6/19/2024
2021 PO9925891438	KU	3	45 UNK	SP	CRE	ED,ID	TD	6/20/2024
2021 PO9912691492	KU	4	40 UNK	SP	CRE	ED,ID	TD	6/21/2024
2021 PO9898991633	KU	3	45 UNK	SP	CRE	ED,ID	TD	6/22/2024
2021 PO9917791243	KU	6	30 UNK	SP	CRE	ED	T	6/23/2024
2021 PO8081410977	KU	6	30 BRN	SP	CCA		T	6/24/2024
2021 PO3686515920	KU	4	40 XXX	SP	CCA	ED	T	6/25/2024
2021 PO3710816708	KU	2	65 XXX	SP	P	ED	T	6/26/2024
2021 PO9631294186	KU	5	35 XXX	SP	S	ED,MD,SRC	T	6/27/2024
2021 PO9614394048	KU	5	35 XXX	SP	S	ED,MD,SRC	T	6/28/2024
2021 PO1840124219	KU	4	40 BRN	SP	CCA	ED	T	6/29/2024
2021 PO1796225257	KU	4	40 BRN	SP	CCA	ED	T	6/30/2024
2021 PO4407586082	LGE	4	30 BRO	SP	CCA	ED	T	7/1/2024
2021 PO7855107392	KU	3	45 BRN	SP	CRE	ID	T	7/2/2024
2021 PO7976611074	KU	3	45 BRN	SP	CRE		T	7/3/2024
2021 PO4226413566	KU	4	45 XXX	SP	CCA	ED	T	7/4/2024
2021 PO3605917861	KU	6	35 BRN	SP	CRE	ED	T	7/5/2024
2021 PO3630117550	KU	4	40 BRN	SP	CRE	ID,IP	BD	7/6/2024
2021 PO4021285397	F	4	40 BRN	SP	CRE		V	7/7/2024
2021 PO4022685396	F	4	40 BRN	SP	CRE		V	7/8/2024
2021 PO4028585391	F	4	40 BRN	SP	CRE		V	7/9/2024
2021 PO4026785393	F	4	40 BRN	SP	CCA		V	7/10/2024
2021 PO4025485394	F	4	40 BRN	SP	CRE		V	7/11/2024
2021 PO4024085395	F	4	40 BRN	SP	P		V	7/12/2024
2021 PO4029285366	F	4	40 BRN	SP	CCA		V	7/13/2024
2021 PO4080584784	LGE	4	40 BRO	SP	CRE	ED,ID	TD	7/14/2024
2021 PO4080684795	LGE	4	40 BRO	SP	CCA	ED,ID	TD	7/15/2024
2021 PO4081484810	LGE	4	30 BRO	SP	CRE	ED,ID	TD	7/16/2024
2021 PO4081084810	LGE	4	40 BRO	SP	CCA	ED,ID	TD	7/17/2024
2021 PO4080084822	LGE	4	35 BRO	SP	CRE		V	7/18/2024
2021 PO4081284819	LGE	4	35 BRO	SP	CCA		V	7/19/2024
2021 PO4081584829	LGE	4	40 BRO	SP	CRE	ED,ID	TD	7/20/2024
2021 PO4081284833	LGE	4	30 BRO	SP	CRE	ED,ID	TD	7/21/2024

2021 PO4082184846	LGE	3	45 BRO	SP	P		ED,ID	BD	7/22/2024
2021 PO4131684907	LGE	3	45 ACE	SP	CCA			V	7/23/2024
2021 PO4130284908	LGE	4	40 ACE	SP	P		ED,ID	TD	7/24/2024
2021 PO5700533783	KU	4	40 BRO	SP	CRE		ED,ID	TD	7/25/2024
2021 PO6558348361	F	4	40 UNK	SP	CCA			V	7/26/2024
2021 PO6569948634	F	4	40 UNK	SP	CCA			V	7/27/2024
2021 PO6580448883	F	4	40 UNK	SP	CCA			V	7/28/2024
2021 PO5760335154	KU	4	40 BRO	SP	CRE		ED,ID	TD	7/29/2024
2021 PO5772035087	KU	6	30 BRO	SP	CRE		ED,ID	TD	7/30/2024
2021 PO4049685351	LGE	4	30 BRN	SP	P		ED,ID	TD	7/31/2024
2021 PO4049785354	F	4	40 BRN	SP	CRE			V	8/1/2024
2021 PO5732035448	KU	3	45 BRO	SP	CCA			V	8/2/2024
2021 PO6597149032	F	5	35 UNK	SP	CCA			V	8/3/2024
2021 PO6588349057	F	3	45 UNK	SP	CCA			V	8/4/2024
2021 PO6564049765	KU	6	30 UNK	SP	CRE			V	8/5/2024
2021 PO6557649670	F	5	35 UNK	SP	A			V	8/6/2024
2021 PO4010485586	F	4	40 BRN	SP	A			V	8/7/2024
2021 PO4158185575	LGE	4	30 BRO	SP	CCA			V	8/8/2024
2021 PO4158585565	LGE	4	30 BRO	SP	CCA			V	8/9/2024
2021 PO4163185608	F	4	40 BRO	SP	CRE			V	8/10/2024
2021 PO4163085598	F	4	40 BRO	SP	CRE			V	8/11/2024
2021 PO4824902066	KU	3	45 BRN	SP	CCA			V	8/12/2024
2021 PO3503621651	F	4	40 XXX	SP	P			V	8/13/2024
2021 PO3509821450	F	4	40 XXX	SP	P			V	8/14/2024
2021 PO3499021361	F	4	40 XXX	SP	P			V	8/15/2024
2021 PO4819702098	KU	4	45 BRN	SP	CCA		ED	TD	8/16/2024
2021 PO4010285557	F	4	40 BRN	SP	A			V	8/17/2024
2021 PO4010385568	F	4	40 BRN	SP	A			V	8/18/2024
2021 PO4009785554	F	4	40 BRN	SP	A			V	8/19/2024
2021 PO4809802169	KU	3	45 BRN	SP	CRE		ED,ID	BD	8/20/2024
2021 PO4803002041	KU	4	40 BRN	SP	CRE		ED,ID	TD	8/21/2024
2021 PO3494521276	F	4	40 XXX	SP	P			V	8/22/2024
2021 PO3499721197	F	4	40 XXX	SP	P			V	8/23/2024
2021 PO3507521295	F	4	40 XXX	SP	P			V	8/24/2024
2021 PO4804401736	KU	7	30 BRN	SP	CRE		ED,ID	TD	8/25/2024
2021 PO3531521328	F	4	40 XXX	SP	P			V	8/26/2024
2021 PO3537321360	F	4	40 XXX	SP	P			V	8/27/2024
2021 PO4163085594	F	4	40 BRO	SP	CRE			V	8/28/2024
2021 PO4165985564	LGE	4	35 BRO	SP	CCA			V	8/29/2024
2021 PO4077284831	LGE	4	40 BRO	SP	CRE		ED,ID	TD	8/30/2024
2021 PO5593131970	KU	5	35 BRO	SP	CRE		ED,ID	TD	8/31/2024
2021 PO6588046167	KU	4	45 UNK	SP	CRE		ID	TD	9/1/2024
2021 PO6566846363	KU	4	45 UNK	SP	CRE		ID	TD	9/2/2024
2021 PO4014585567	F	4	40 BRN	SP	A			V	9/3/2024
2021 PO4014685578	F	4	40 BRN	SP	CCA			V	9/4/2024
2021 PO4014085579	F	3	45 BRN	SP	CCA			V	9/5/2024
2021 PO4020985524	F	4	40 BRN	SP	A			V	9/6/2024
2021 PO4342402705	KU	4	40 BRN	SP	CRE		ED,ID	TD	9/7/2024
2021 PO4123485590	F	4	40 ACE	SP	CRE			V	9/8/2024
2021 PO4123485577	F	4	40 ACE	SP	P			V	9/9/2024
2021 PO4123385560	F	4	40 ACE	SP	P			V	9/10/2024
2021 PO4398901915	KU	3	40 BRN	SP	CRE		ED,ID	TD	9/11/2024
2021 PO4354102772	KU	4	40 BRN	SP	CCA			V	9/12/2024
2021 PO5580831322	KU	4	40 BRO	SP	CCA			V	9/13/2024

2021 PO4021985519	F	4	40 BRN	SP	A		V	9/14/2024
2021 PO4022985515	F	4	40 BRN	SP	CCA		V	9/15/2024
2021 PO4019185475	F	4	30 BRN	SP	P		V	9/16/2024
2021 PO4019085469	F	4	40 BRN	SP	P		V	9/17/2024
2021 PO4017685476	F	4	35 BRN	SP	P		V	9/18/2024
2021 PO4017585471	F	4	40 BRN	SP	CCA		V	9/19/2024
2021 PO6423545623	KU	4	40 UNK	SP	CCA	ID,SRS	TD	9/20/2024
2021 PO4128285614	F	4	40 ACE	SP	CRE		V	9/21/2024
2021 PO4129385609	F	4	40 ACE	SP	CRE		V	9/22/2024
2021 PO4130285600	F	4	40 ACE	SP	CRE		V	9/23/2024
2021 PO4131485600	F	4	40 ACE	SP	CRE		V	9/24/2024
2021 PO4361802643	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/25/2024
2021 PO4372202654	KU	5	40 BRN	SP	CCA	ED,ID	BD	9/26/2024
2021 PO4017385467	LGE	4	35 BRN	SP	CCA		V	9/27/2024
2021 PO4017285456	LGE	4	35 BRN	SP	CCA		V	9/28/2024
2021 PO4016385477	F	4	35 BRN	SP	P		V	9/29/2024
2021 PO4081784861	LGE	4	40 BRO	SP	CRE	ED,ID	TD	9/30/2024
2021 PO4083784861	LGE	4	40 BRO	SP	CRE	ED,ID	TD	10/1/2024
2021 PO4082584861	F	4	40 BRO	SP	CCA		V	10/2/2024
2021 PO6331445313	KU	3	45 UNK	SP	CCA		V	10/3/2024
2021 PO6355045395	KU	3	45 UNK	SP	CCA		V	10/4/2024
2021 PO6355045395-A	KU	3	45 UNK	SP	CCA		V	10/5/2024
2021 PO3513226262	F	4	40 XXX	SP	P		V	10/6/2024
2021 PO3529126307	F	4	40 XXX	SP	P		V	10/7/2024
2021 PO3533326053	F	4	40 XXX	SP	P		V	10/8/2024
2021 PO3537925848	F	4	40 XXX	SP	P		V	10/9/2024
2021 PO4129484905	LGE	4	40 ACE	SP	CRE	ED,ID	BD	10/10/2024
2021 PO4133084907	LGE	3	45 ACE	SP	CCA		V	10/11/2024
2021 PO4028385362	F	4	40 BRN	SP	CCA		V	10/12/2024
2021 PO4027185358	F	4	40 BRN	SP	CCA		V	10/13/2024
2021 PO4026085353	F	4	40 BRN	SP	CCA		V	10/14/2024
2021 PO4024985349	F	4	40 BRN	SP	CRE		V	10/15/2024
2021 PO4023985348	F	4	40 BRN	SP	CCA		V	10/16/2024
2021 PO4022685348	F	4	40 BRN	SP	CCA		V	10/17/2024
2021 PO4021485349	F	4	40 BRN	SP	CRE		V	10/18/2024
2021 PO4042085328	F	4	45 BRN	SP	CRE		V	10/19/2024
2021 PO4094685275	LGE	4	40 BRO	SP	CRE	ID	TD	10/20/2024
2021 PO6378145316	KU	3	45 UNK	SP	CCA		V	10/21/2024
2021 PO6370845297	KU	6	30 UNK	SP	CCA		V	10/22/2024
2021 PO6391845245	KU	4	40 UNK	SP	CCA		V	10/23/2024
2021 PO3554325695	F	4	40 XXX	SP	P		V	10/24/2024
2021 PO3558325593	F	4	40 XXX	SP	P		V	10/25/2024
2021 PO3552425442	F	4	40 XXX	SP	P		V	10/26/2024
2021 PO3476325725	F	4	40 XXX	SP	P		V	10/27/2024
2021 PO6381844932	KU	4	40 UNK	SP	CCA		V	10/28/2024
2021 PO6376944747	KU	4	45 UNK	SP	CCA		V	10/29/2024
2021 PO5664132556	KU	3	45 BRO	SP	CCA		V	10/30/2024
2021 PO5629133060	KU	5	35 BRO	SP	CRE	ED,ID	TD	10/31/2024
2021 PO5638033035	KU	6	30 BRO	SP	CRE	ED,ID	TD	11/1/2024
2021 PO5658833737	KU	4	40 BRO	SP	CCA		V	11/2/2024
2021 PO5650533538	KU	4	40 BRO	SP	CRE	ED,ID	BD	11/3/2024
2021 PO5675533452	F	4	40 BRO	SP	CCA		V	11/4/2024
2021 PO4091885272	LGE	4	30 BRO	SP	CCA		V	11/5/2024
2021 PO4092385279	LGE	4	40 BRO	SP	CRE	ED,ID	TD	11/6/2024

2021 PO4093285267	LGE	4	30 BRO	SP	CCA		V	11/7/2024	
2021 PO4093385277	LGE	3	45 BRO	SP	CCA	ID	BD	11/8/2024	
2021 PO6364144326	KU	4	45 UNK	SP	CCA		V	11/9/2024	
2021 PO6372744224	KU	5	35 UNK	SP	CRE	ID	BD	11/10/2024	
2021 PO3477325570	F	4	40 XXX	SP	P		V	11/11/2024	
2021 PO3484125584	F	4	40 XXX	SP	P		V	11/12/2024	
2021 PO4006285587	F	4	35 BRN	SP	A		V	11/13/2024	
2021 PO4007885599	F	4	30 BRN	SP	A		V	11/14/2024	
2021 PO4009085615	F	4	40 BRN	SP	CCA		V	11/15/2024	
2021 PO3999985252	F	4	40 BRN	SP	A		V	11/16/2024	
2021 PO3997885265	F	4	25 BRN	SP	A		V	11/17/2024	
2021 PO3998085261	F	4	40 BRN	SP	A		V	11/18/2024	
2021 PO3996285247	F	4	40 BRN	SP	A		V	11/19/2024	
2021 PO4116885622	F	4	40 ACE	SP	CRE		V	11/20/2024	
2021 PO4118085622	F	4	45 ACE	SP	P		V	11/21/2024	
2021 PO4119385622	F	4	40 ACE	SP	CRE		V	11/22/2024	
2021 PO4419703628	KU	3	45 BRN	SP	CRE	ED,ID	TD	11/23/2024	
2021 PO4393003460	KU	3	45 BRN	SP	CRE	ED,ID,MD	TD	11/24/2024	
2021 PO4065184784	LGE	3	45 BRO	SP	CCA		V	11/25/2024	
2021 PO4066084775	LGE	3	45 BRO	SP	CCA		V	11/26/2024	
2021 PO4067784766	LGE	3	45 BRO	SP	CCA		V	11/27/2024	
2021 PO4066884771	LGE	3	45 BRO	SP	CCA		V	11/28/2024	
2021 PO7847659339	LGE	4	40 BRO	SP	CRE	ED,ID	BD	11/29/2024	
2021 PO4120985639	F	4	40 ACE	SP	CRE		V	11/30/2024	
2021 PO4120585631	F	4	40 ACE	SP	P		V	12/1/2024	
2021 PO4120485621	F	4	45 ACE	SP	P		V	12/2/2024	
2021 PO4122085620	F	4	40 ACE	SP	CRE		V	12/3/2024	
2021 PO4124685618	F	4	40 ACE	SP	CRE		V	12/4/2024	
2021 PO4123485642	F	3	45 ACE	SP	CCA		V	12/5/2024	
2021 PO4123585630	F	4	40 ACE	SP	P		V	12/6/2024	
2021 PO4123585619	F	4	45 ACE	SP	P		V	12/7/2024	
2021 PO3406420249	F	4	40 OTH	SP	P		V	12/8/2024	
2021 PO4102985402	LGE	4	40 BRO	SP	CCA		V	12/9/2024	
2021 PO4102285361	LGE	4	40 BRO	SP	CCA		V	12/10/2024	
2021 PO4166785473	F	4	40 BRO	SP	CRE		V	12/11/2024	
2021 PO4066584780	LGE	4	30 BRO	SP	CRE	ED,ID	TD	12/12/2024	
2021 PO4069184772	LGE	4	40 BRO	SP	CRE	ED,ID	TD	12/13/2024	
2021 PO4069184759	LGE	4	40 BRO	SP	CRE		V	12/14/2024	
2021 PO4070484756	LGE	4	30 BRO	SP	CRE	ED,ID	TD	12/15/2024	
2021 PO4070284752	LGE	4	40 BRO	SP	CRE	ED,ID	BD	12/16/2024	
2021 PO4442903812	KU	3	45 BRN	SP	CRE	ED,ID,MD,RB	X	PX	12/17/2024
2021 PO6561648088	KU	4	40 UNK	SP	CRE	ID	TD	12/18/2024	
2021 PO4123585601	F	4	45 ACE	SP	P		V	12/19/2024	
2021 PO6549848083	KU	4	45 UNK	SP	CRE	ID	TD	12/20/2024	
2021 PO4165085471	F	4	30 BRO	SP	CCA		V	12/21/2024	
2021 PO4165085474	F	4	40 BRO	SP	CCA		V	12/22/2024	
2021 PO4165185482	F	4	40 BRO	SP	CRE		V	12/23/2024	
2021 PO3995585244	F	4	40 BRN	SP	A		V	12/24/2024	
2021 PO3995885238	F	4	30 BRN	SP	A		V	12/25/2024	
2021 PO3998685247	F	4	40 BRN	SP	A		V	12/26/2024	
2021 PO3998285240	F	4	30 BRN	SP	A		V	12/27/2024	
2021 PO3999385231	F	4	40 BRN	SP	A		V	12/28/2024	
2021 PO3996985210	F	4	30 BRN	SP	A		V	12/29/2024	
2021 PO4069784779	LGE	4	40 BRO	SP	CRE	ED,ID	TD	12/30/2024	

2021 PO4072684831	LGE	4	35 BRO	SP	CCA	ED,ID	BD	12/31/2024
2021 PO4070784793	LGE	4	30 BRO	SP	CCA	ED,ID	TD	1/1/2025
2021 PO4070484794	LGE	4	40 BRO	SP	CRE	ED,ID	TD	1/2/2025
2021 PO4135984820	LGE	5	30 ACE	SP	P	ED,ID	TD	1/3/2025
2021 PO4135584820	LGE	4	30 ACE	SP	P	ED,ID	TD	1/4/2025
2021 PO4134784820	LGE	4	40 ACE	SP	P	ED,ID	TD	1/5/2025
2021 PO3996685215	F	4	40 BRN	SP	CCA		V	1/6/2025
2021 PO3997985222	F	4	40 BRN	SP	A		V	1/7/2025
2021 PO3999085226	F	4	40 BRN	SP	A		V	1/8/2025
2021 PO4000085218	F	4	40 BRN	SP	A		V	1/9/2025
2021 PO4000585204	F	4	40 BRN	SP	A		V	1/10/2025
2021 PO7124863460	LGE	4	40 BRN	SP	A	ED,ID,IP	BD	1/11/2025
2021 PO3997685187	F	4	40 BRN	SP	A		V	1/12/2025
2021 PO3999885191	F	4	40 BRN	SP	A		V	1/13/2025
2021 PO4001385189	F	4	40 BRN	SP	A		V	1/14/2025
2021 PO4001685176	F	4	40 BRN	SP	A		V	1/15/2025
2021 PO4001785163	F	4	40 BRN	SP	A		V	1/16/2025
2021 PO4003085137	LGE	4	40 BRN	SP	CCA		V	1/17/2025
2021 PO4004285134	LGE	4	40 BRN	SP	CCA	ED,ID	BD	1/18/2025
2021 PO3628498724	KU	4	40 BRN	SP	CCA		V	1/19/2025
2021 PO3525122597	F	4	40 XXX	SP	P		V	1/20/2025
2021 PO3518722942	F	4	40 XXX	SP	P		V	1/21/2025
2021 PO3524322759	F	4	40 XXX	SP	P		V	1/22/2025
2021 PO6146140901	KU	5	35 UNK	SP	CRE	ID,IP	TD	1/23/2025
2021 PO3628498544	KU	4	40 BRN	SP	CCA		V	1/24/2025
2021 PO6119740873	KU	6	35 UNK	SP	CRE	ID,IP,SRS	TD	1/25/2025
2021 PO3499598919	KU	4	40 BRN	SP	CCA		V	1/26/2025
2021 PO4135384838	LGE	4	40 ACE	SP	CCA		V	1/27/2025
2021 PO4135784855	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	1/28/2025
2021 PO3508023066	F	4	40 XXX	SP	P		V	1/29/2025
2021 PO3474023210	F	4	40 XXX	SP	P		V	1/30/2025
2021 PO3480023257	F	4	40 XXX	SP	P		V	1/31/2025
2021 PO3488523132	F	4	40 XXX	SP	P		V	2/1/2025
2021 PO3486723020	F	4	40 XXX	SP	P		V	2/2/2025
2021 PV4072784815	LGE	4	35 BRO	SP	P		V	2/3/2025
2021 PO4071484809	LGE	3	45 BRO	SP	CCA		V	2/4/2025
2021 PO4072084806	LGE	4	30 BRO	SP	CCA		V	2/5/2025
2021 PO4071084814	LGE	4	30 BRO	SP	CCA		V	2/6/2025
2021 PO4074084827	LGE	3	45 BRO	SP	CCA		V	2/7/2025
2021 PO4074384819	LGE	4	30 BRO	SP	CRE	ED,ID	BD	2/8/2025
2021 PO4072884821	LGE	3	45 BRO	SP	CCA		V	2/9/2025
2021 PO3484799122	KU	4	40 BRN	SP	CCA		V	2/10/2025
2021 PO3511699499	KU	3	45 BRN	SP	CRE	ED,ID,MD	TD	2/11/2025
2021 PO6114440541	KU	4	40 UNK	SP	CRE	ID	TD	2/12/2025
2021 PO4005185132	LGE	4	40 BRN	SP	A	ED,ID	BD	2/13/2025
2021 PO4004985127	LGE	4	35 BRN	SP	A	ED,ID	BD	2/14/2025
2021 PO4162485532	F	3	45 BRO	SP	CRE		V	2/15/2025
2021 PO4162585541	F	4	45 BRO	SP	CRE		V	2/16/2025
2021 PO4162685551	F	4	40 BRO	SP	CRE		V	2/17/2025
2021 PO4162885565	F	4	40 BRO	SP	CRE		V	2/18/2025
2021 PO4003385432	F	4	40 BRN	SP	CCA		V	2/19/2025
2021 PO3428420485	F	4	40 OTH	SP	P		V	2/20/2025
2021 PO4371703332	KU	3	45 BRN	SP	CCA		V	2/21/2025
2021 PO4115985621	F	4	40 ACE	SP	P		V	2/22/2025



2021 PO3984385401	F	4	40 BRN	SP	A		V	2/23/2025
2021 PO4004485515	F	4	40 BRN	SP	A		V	2/24/2025
2021 PO4005185515	F	4	30 BRN	SP	A		V	2/25/2025
2021 PO4004685530	F	4	40 BRN	SP	CCA		V	2/26/2025
2021 PO4005285530	F	4	30 BRN	SP	A		V	2/27/2025
2021 PO4005085559	F	3	45 BRN	SP	CCA		V	2/28/2025
2021 PO4004785544	F	3	45 BRN	SP	CCA		V	3/1/2025
2021 PO4005485544	F	4	30 BRN	SP	A		V	3/2/2025
2021 PO4005885560	F	4	35 BRN	SP	CCA		V	3/3/2025
2021 PO4005585572	F	4	40 BRN	SP	A		V	3/4/2025
2021 PO4171285442	F	4	40 BRO	SP	CRE	ED,EP	V	3/5/2025
2021 PO4171185432	F	3	45 BRO	SP	CCA		V	3/6/2025
2021 PO4171085429	F	4	40 BRO	SP	CRE		V	3/7/2025
2021 PO4098085180	LGE	4	35 BRO	SP	CCA		V	3/8/2025
2021 PO4097085198	LGE	3	50 BRO	SP	CCA		V	3/9/2025
2021 PO4096085203	LGE	3	45 BRO	SP	CCA		V	3/10/2025
2021 PO3615198750	KU	3	40 BRN	SP	CRE	ED,ID	TD	3/11/2025
2021 PO3453919693	F	4	40 XXX	SP	P		V	3/12/2025
2021 PO3480019743	F	4	40 XXX	SP	P		V	3/13/2025
2021 PO3507619809	F	4	40 XXX	SP	P		V	3/14/2025
2021 PO6555647222	KU	5	30 UNK	SP	CRE	ID,IP	BD	3/15/2025
2021 PO6557846836	KU	4	40 UNK	SP	CRE	ID,IP	BD	3/16/2025
2021 PO4698404461	KU	3	40 BRN	SP	CRE	ED,ID	TD	3/17/2025
2021 PO4675604535	KU	5	40 BRN	SP	CRE	ED,ID	TD	3/18/2025
2021 PO8652673320	LGE	4	35 BRO	SP	CCA		V	3/19/2025
2021 PO4150386153	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	3/20/2025
2021 PO4151186162	LGE	4	35 BRO	SP	CCA		V	3/21/2025
2021 PO4669204401	KU	3	50 BRN	SP	CRE	ED	BD	3/22/2025
2021 PO8657873902	LGE	4	35 BRO	SP	CRE	ED,ID	TD	3/23/2025
2021 PO4625005007a	KU	3	50 BRN	SP	CCA	ED	TD	3/24/2025
2021 PO4559305108	KU	3	45 BRN	SP	CCA		V	3/25/2025
2021 PO4590905436	KU	3	40 BRN	SP	CCA	ED	TD	3/26/2025
2021 PO4608005221	KU	3	50 BRN	SP	CCA	ED	TD	3/27/2025
2021 PO4568705162	KU	2	50 BRN	SP	CCA		V	3/28/2025
2021 PO4625005007	KU	3	45 BRN	SP	CCA	ED	TD	3/29/2025
2021 PO4574505647	KU	3	50 BRN	SP	CCA	ED	TD	3/30/2025
2021 PO8804482928	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/31/2025
2021 PO8778482794	KU	5	40 BRO	SP	CRE	ED,ID	TD	4/1/2025
2021 PO8703382657	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/2/2025
2021 PO8743282749	KU	4	35 BRO	SP	P	ED,ID	TD	4/3/2025
2021 PO8703382657-A	KU	6	30 BRO	SP	CRE	ID,IP	B	4/4/2025
2021 PO8680084142	LGE	3	45 BRO	SP	CCA		V	4/5/2025
2021 PO4157086180	LGE	4	35 BRO	SP	A	ED,ID	TD	4/6/2025
2021 PO4155986170	LGE	4	35 BRO	SP	A	ED,ID	TD	4/7/2025
2021 PO4154586175	LGE	4	35 BRO	SP	A	ED,ID	TD	4/8/2025
2021 PO4153486185	LGE	4	35 BRO	SP	A	ED,ID	TD	4/9/2025
2021 PO8686174073	LGE	5	35 BRO	SP	CCA		V	4/10/2025
2021 PO4157286213	LGE	3	45 BRO	SP	CCA		V	4/11/2025
2021 PO4823102442	F	3	40 BRN	SP	CRE	HH,ID	BX PX	4/12/2025
2021 PO1777344537	KU	6	35 BRN	SP	CRE	ED,ID	TD	4/13/2025
2021 PO4684204182	KU	2	50 BRN	SP	CRE	ED,ID,IP	TX RR	4/14/2025
2021 PO4667904074	KU	5	35 BRN	SP	CCA	ED	TD	4/15/2025
2021 PO4754302898	KU	2	55 BRN	SP	CCA		V	4/16/2025
2021 PO4153084735	LGE	4	40 ACE	SP	CRE	ED,ID	BD	4/17/2025

2021	PO3748719657	F	4	40 XXX	SP	P		V	4/18/2025
2021	PO3739419652	F	4	40 XXX	SP	P		V	4/19/2025
2021	PO3756019529	F	4	40 XXX	SP	P		V	4/20/2025
2021	PO3747819553	KU	4	40 BRN	SP	CCA		V	4/21/2025
2021	PO3758219333	F	4	40 XXX	SP	P		V	4/22/2025
2021	PO3758719266	F	4	40 XXX	SP	P		V	4/23/2025
2021	PO3749819329	F	4	40 XXX	SP	P		V	4/24/2025
2021	PO3743019229	KU	3	45 BRN	SP	CCA		V	4/25/2025
2021	PO3773919299	F	4	40 XXX	SP	P		V	4/26/2025
2021	PO3770619239	F	4	40 XXX	SP	P		V	4/27/2025
2021	PO7530662839	KU	6	30 BRO	ST	P		V	4/28/2025
2021	PO7545262943	KU	6	30 BRO	ST	P		V	4/29/2025
2021	PO7543363156	KU	4	40 BRO	SP	S		V	4/30/2025
2021	PO7586662957	KU	4	45 BRO	SP	CCA		V	5/1/2025
2021	PO7600562779	F	4	40 BRO	SP	CRE		V	5/2/2025
2021	PO4707204285	KU	7	30 BRN	SP	CRE	ED,ID	TD	5/3/2025
2021	PO4727504083	KU	3	40 BRN	SP	CRE		B	5/4/2025
2021	PO4757503981	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/5/2025
2021	PO4694104287	KU	7	35 BRN	SP	CCA		V	5/6/2025
2021	PO7663459614	KU	5	35 UNK	SP	CCA		V	5/7/2025
2021	PO7652459652	F	4	40 UNK	SP	CRE		V	5/8/2025
2021	PO7639460456	F	4	40 BRO	SP	CRE		V	5/9/2025
2021	PO4139786068	LGE	1	55 BRO	SP	CCA		V	5/10/2025
2021	PO4140386086	LGE	3	45 BRO	SP	A	ED,ID	TD	5/11/2025
2021	PO4140286079	LGE	1	50 BRO	SP	CCA		V	5/12/2025
2021	PO7627360355	KU	6	30 BRO	SP	CCA		V	5/13/2025
2021	PO7635660370	KU	6	30 BRO	SP	CCA		V	5/14/2025
2021	PO4149684830	LGE	4	45 ACE	SP	P	ED,ID	TD	5/15/2025
2021	PO7647659582	KU	3	45 UNK	SP	CCA		V	5/16/2025
2021	PO7640659481	KU	3	50 UNK	SP	CCA		V	5/17/2025
2021	PO7632759411	KU	5	35 UNK	SP	CCA		V	5/18/2025
2021	PO7620859368	F	5	35 UNK	SP	CCA		V	5/19/2025
2021	PO7625959353	KU	6	30 UNK	SP	CRE	ED,ID,JP	TD	5/20/2025
2021	PO4139786083	F	3	45 BRO	SP	CCA		V	5/21/2025
2021	PO4139186089	LGE	3	45 BRO	SP	CCA		V	5/22/2025
2021	PO4149784817	LGE	4	40 ACE	SP	P	ED,ID	TD	5/23/2025
2021	PO4148984805	LGE	7	25 ACE	SP	CRE	ED,ID,JP	TD	5/24/2025
2021	PO4149984805	LGE	4	45 ACE	SP	P	ED,ID	TD	5/25/2025
2021	PO7612764911	F	4	40 BRO	SP	CRE		V	5/26/2025
2021	PO7610564758	F	4	40 BRO	SP	CRE		V	5/27/2025
2021	PO4188485963	LGE	4	40 BRO	SP	CCA		V	5/28/2025
2021	PO4150386079	LGE	4	35 BRO	SP	A	ED,ID	TD	5/29/2025
2021	PO4150484806	LGE	4	30 ACE	SP	P	ED,ID	TD	5/30/2025
2021	PO7515764114	KU	6	30 BRO	SP	CRE		V	5/31/2025
2021	PO7613859214	F	6	30 UNK	SP	CRE	ED,ID	VX	RP1 6/1/2025
2021	PO7604864738	F	5	30 BRO	SP	CRE		V	6/2/2025
2021	PO7594864786	F	4	40 BRO	SP	CRE		V	6/3/2025
2021	PO7623264736	F	5	30 BRO	SP	CRE		V	6/4/2025
2021	PO7584658701	F	6	30 UNK	SP	CRE		V	6/5/2025
2021	PO7580258767	KU	6	30 UNK	SP	CRE	ID	TD	6/6/2025
2021	PO4142586080	LGE	4	35 BRO	SP	CCA		V	6/7/2025
2021	PO7609364541	F	4	40 BRO	SP	CRE		V	6/8/2025
2021	PO7617464529	F	5	30 BRO	SP	CRE		V	6/9/2025
2021	PO7617164442	KU	6	30 BRO	SP	CRE	ED,ID	TD	6/10/2025

2021 PO7603964469	F	4	40 BRO	SP	CRE		V	6/11/2025
2021 PO7609664433	F	4	40 BRO	SP	CRE		V	6/12/2025
2021 PO7610264290	F	4	40 BRO	SP	CRE		V	6/13/2025
2021 PO7595164273	F	5	30 BRO	SP	CRE		V	6/14/2025
2021 PO7611564103	F	4	40 BRO	SP	CRE		V	6/15/2025
2021 PO7605864097	F	4	40 BRO	SP	CRE		V	6/16/2025
2021 PO7596263886	F	4	40 BRO	SP	CRE		V	6/17/2025
2021 PO7597964057	KU	6	30 BRO	SP	CCA		V	6/18/2025
2021 PO7586263938	F	4	40 BRO	SP	CRE		V	6/19/2025
2021 PO7593563957	KU	5	35 BRO	SP	CRE	ED,ID	TD	6/20/2025
2021 PO3946817755	KU	2	50 BRN	SP	CCA		V	6/21/2025
2021 PO8244385077	KU	3	50 BRO	SP	CRE		VX	6/22/2025
2021 PO8245984757	KU	4	45 BRO	SP	CRE	ED,ID	TD	6/23/2025
2021 PO3911717976	KU	5	35 XXX	SP	CRE	ED,ID	TD	6/24/2025
2021 PO3918017741	KU	3	50 BRN	SP	CCA		V	6/25/2025
2021 PO3903917616	KU	3	50 BRN	SP	CCA		V	6/26/2025
2021 PO3898617561	KU	3	50 BRN	SP	CCA		V	6/27/2025
2021 PO7578263908	F	4	40 BRO	SP	A		V	6/28/2025
2021 PO7548664009	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/29/2025
2021 PO4142486088	LGE	3	45 BRO	SP	A	ED,ID	TD	6/30/2025
2021 PO8555172712	LGE	4	35 BRO	SP	CCA		V	7/1/2025
2021 PO8563172707	LGE	4	35 BRO	SP	CCA		V	7/2/2025
2021 PO8249484088	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	7/3/2025
2021 PO8250284541	KU	4	45 BRO	SP	CRE	ED,ID	TD	7/4/2025
2021 PO8247183764	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/5/2025
2021 PO4152084790	LGE	7	25 ACE	SP	CRE	ED,ID,IP	BD	7/6/2025
2021 PO3777720236	F	4	40 XXX	SP	P		V	7/7/2025
2021 PO3785220300	F	4	40 XXX	SP	P		V	7/8/2025
2021 PO3788420195	F	4	40 XXX	SP	P		V	7/9/2025
2021 PO3789020079	F	4	40 XXX	SP	P		V	7/10/2025
2021 PO3779920033	F	4	40 XXX	SP	P		V	7/11/2025
2021 PO3783319968	F	4	40 XXX	SP	P		V	7/12/2025
2021 PO3772419896	F	4	40 XXX	SP	P		V	7/13/2025
2021 PO3759319828	F	4	40 XXX	SP	P		V	7/14/2025
2021 PO3745319782	F	4	40 XXX	SP	P		V	7/15/2025
2021 PO3685819622	KU	4	45 BRN	SP	CCA		V	7/16/2025
2021 PO3713919632	KU	4	45 BRN	SP	CCA		V	7/17/2025
2021 PO3721719674	F	4	40 XXX	SP	P	ED	BX	7/18/2025
2021 PO3726719761	F	4	40 XXX	SP	P		V	7/19/2025
2021 PO7525064092	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/20/2025
2021 PO7713058200	KU	4	40 UNK	SP	CRE	ID,IP	TD	7/21/2025
2021 PO7704358391	KU	4	40 UNK	SP	CRE	ID,IP	TD	7/22/2025
2021 PO4150684783	LGE	4	30 ACE	SP	CRE	ED,ID	TD	7/23/2025
2021 PO4151084787	LGE	4	45 ACE	SP	P	ED,ID	TD	7/24/2025
2021 PO4145286087	LGE	4	40 BRO	SP	CCA		V	7/25/2025
2021 PO4148086086	LGE	3	45 BRO	SP	A	ID	BD	7/26/2025
2021 PO7489264317	KU	4	40 BRO	SP	CCA		V	7/27/2025
2021 PO7481664253	KU	5	35 BRO	SP	CCA		V	7/28/2025
2021 PO4151086095	LGE	3	45 BRO	SP	A	ID	BD	7/29/2025
2021 PO7454464295	KU	3	45 BRO	SP	CCA		V	7/30/2025
2021 PO7701758488	KU	4	40 UNK	SP	CRE	ID	BD	7/31/2025
2021 PO7685058632	KU	4	40 UNK	SP	CRE	ID,IP	BD	8/1/2025
2021 PO4151086097	LGE	3	45 BRO	SP	A	ID	BD	8/2/2025
2021 PO4144186110	LGE	4	35 BRO	SP	CCA		V	8/3/2025

2021 PO4145986140	F	3	45 BRO	SP	A		V		8/4/2025
2021 PO8649374013	LGE	4	35 BRO	SP	CCA		V		8/5/2025
2021 PO4151684772	LGE	4	40 ACE	SP	CRE	ED,ID	TD		8/6/2025
2021 PO7629463831	KU	6	30 BRO	SP	CRE	ED,ID	TD		8/7/2025
2021 PO7613663963	F	4	40 BRO	SP	CRE		V		8/8/2025
2021 PO7615463833	F	4	40 BRO	SP	CRE		V		8/9/2025
2021 PO7618663641	KU	5	35 BRO	SP	CCA		V		8/10/2025
2021 PO7611063567	F	4	40 BRO	SP	CRE		V		8/11/2025
2021 PO7604963288	F	4	40 BRO	SP	A		V		8/12/2025
2021 PO7604263262	F	4	40 BRO	SP	CRE		V		8/13/2025
2021 PO7615663255	KU	6	30 BRO	SP	CCA		V		8/14/2025
2021 PO8199983534	KU	4	45 BRO	SP	CRE	ED,ID	BD		8/15/2025
2021 PO8162783678	KU	4	40 BRO	SP	CRE	ED,ID	TD		8/16/2025
2021 PO8169283373	KU	4	40 BRO	SP	CRE	ED,EP,ID,IP	TD		8/17/2025
2021 PO8142483258	KU	4	45 BRO	SP	CRE	ED,ID	TD		8/18/2025
2021 PO8109883092	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD		8/19/2025
2021 PO4152184759	LGE	4	40 ACE	SP	CRE	ED,ID	TD		8/20/2025
2021 PO7668558761	KU	4	40 UNK	SP	CRE	ID	BD		8/21/2025
2021 PO7655258849	KU	4	40 UNK	SP	CRE	ID	BD		8/22/2025
2021 PO7640458947	KU	4	40 UNK	SP	CRE	HH,ID	BD		8/23/2025
2021 PO7627259071	KU	4	45 UNK	SP	CRE	ID	BD		8/24/2025
2021 PO4138186062	LGE	3	45 BRO	SP	A	ED,ID,IP	TX	RR	8/25/2025
2021 PO4772603520	KU	7	35 BRN	SP	CRE	ED,ID	TD		8/26/2025
2021 PO7677861395	F	4	40 BRO	SP	CRE		V		8/27/2025
2021 PO7688861432	F	5	30 BRO	SP	CRE		V		8/28/2025
2021 PO7683961276	F	4	40 BRO	SP	CRE		V		8/29/2025
2021 PO7680461228	F	4	40 BRO	SP	A		V		8/30/2025
2021 PO7688959524	F	6	30 UNK	SP	CRE		V		8/31/2025
2021 PO7685859689	F	4	40 UNK	SP	CRE		V		9/1/2025
2021 PO3987816971	KU	4	45 XXX	SP	CRE	ED,ID	TD		9/2/2025
2021 PO4002617074	KU	4	40 XXX	SP	CRE	ID	BD		9/3/2025
2021 PO7689061195	F	4	40 BRO	SP	CRE		V		9/4/2025
2021 PO7694561101	F	4	40 BRO	SP	CRE		V		9/5/2025
2021 PO7693161242	F	6	30 BRO	SP	CRE		V		9/6/2025
2021 PO7697861302	F	6	30 BRO	SP	CRE		V		9/7/2025
2021 PO7697861086	F	4	40 BRO	SP	CRE		V		9/8/2025
2021 PO7699261020	F	4	40 BRO	SP	CRE		V		9/9/2025
2021 PO7711861183	F	4	40 BRO	SP	CRE		V		9/10/2025
2021 PO7722461238	KU	5	35 BRO	SP	CCA		V		9/11/2025
2021 PO4761703646	KU	3	40 BRN	SP	CRE	ED,ID	TD		9/12/2025
2021 PO4137286058	LGE	5	35 BRO	SP	CRE		V		9/13/2025
2021 PO8877083480	KU	4	40 BRO	SP	CRE	ED,EP,ID,IP,RB	BX	RP2	9/14/2025
2021 PO8887284403	KU	4	45 BRO	SP	CRE		B		9/15/2025
2021 PO8884483960	KU	4	45 BRO	SP	CRE		B		9/16/2025
2021 PO8880283666	KU	4	40 BRO	SP	CRE	ED,ID	TD		9/17/2025
2021 PO8841283207	KU	4	40 BRO	SP	CRE	ED,ID	TD		9/18/2025
2021 PO8841283207-A	KU	4	40 BRO	SP	CRE	ED,ID	TD		9/19/2025
2021 PO8641389082	KU	4	40 BRO	SP	CCA		V		9/20/2025
2021 PO8580588761	KU	3	50 BRO	SP	CRE	ED,ID	TD		9/21/2025
2021 PO8612988988	KU	4	40 BRO	SP	CRE	ED,ID	BD		9/22/2025
2021 PO7681960620	KU	6	30 BRO	SP	CCA		V		9/23/2025
2021 PO7740860646	F	4	40 BRO	SP	CRE		V		9/24/2025
2021 PO7731860704	F	4	40 BRO	SP	CRE		V		9/25/2025
2021 PO7724860752	F	4	40 BRO	SP	CRE		V		9/26/2025

2021 PO7728060651	KU	6	30 BRO	SP	CRE	ED,ID	TD	9/27/2025
2021 PO7702560391	KU	4	40 UNK	SP	CRE	ID	BD	9/28/2025
2021 PO7695160276	KU	5	35 UNK	SP	CRE	ID	TD	9/29/2025
2021 PO7688960233	KU	6	30 UNK	SP	CRE	ID	TD	9/30/2025
2021 PO3929416009	KU	4	40 XXX	SP	CRE	ID	BD	10/1/2025
2021 PO3545820419	F	4	40 SWP	SP	P		V	10/2/2025
2021 PO3545420746	F	4	40 SWP	SP	P		V	10/3/2025
2021 PO3553520169	F	4	40 SWP	SP	P		V	10/4/2025
2021 PO3541220836	KU	6	30 BRN	SP	CCA		V	10/5/2025
2021 PO3523020005	F	4	40 SWP	SP	P		V	10/6/2025
2021 PO3532920368	F	4	40 SWP	SP	P		V	10/7/2025
2021 PO3538420244	F	4	40 SWP	SP	P		V	10/8/2025
2021 PO3521320445	F	4	40 SWP	SP	P		V	10/9/2025
2021 PO3518020353	F	4	40 SWP	SP	P		V	10/10/2025
2021 PO3516420747	F	4	40 BRN	SP	P		V	10/11/2025
2021 PO3932315892	KU	6	30 BRN	SP	CCA		V	10/12/2025
2021 PO3945315913	KU	4	40 BRN	SP	CCA		V	10/13/2025
2021 PO3955815888	KU	3	45 BRN	SP	CCA		V	10/14/2025
2021 PO3954415862	F	5	35 XXX	SP	P		V	10/15/2025
2021 PO3945715897	KU	2	45 BRN	SP	CCA		V	10/16/2025
2021 PO7717660803	F	4	40 BRO	SP	CRE		V	10/17/2025
2021 PO7707860701	KU	4	45 BRO	SP	CCA		V	10/18/2025
2021 PO7698260611	F	4	40 BRO	SP	CRE		V	10/19/2025
2021 PO7689760538	F	4	40 BRO	SP	CRE		V	10/20/2025
2021 PO7695460475	F	4	40 BRO	SP	CRE		V	10/21/2025
2021 PO7697660443	F	4	40 BRO	SP	CRE		V	10/22/2025
2021 PO7713260837	F	4	40 BRO	ST	P		V	10/23/2025
2021 PO7706360914	F	4	40 BRO	ST	P		V	10/24/2025
2021 PO7665260316	F	4	40 BRO	SP	CRE		V	10/25/2025
2021 PO7660960286	KU	3	50 BRO	SP	CRE	ED,ID	BD	10/26/2025
2021 PO3963516352	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD	10/27/2025
2021 PO3954016111	KU	4	40 XXX	SP	CRE	ID	BD	10/28/2025
2021 PO4760603384	KU	7	30 BRN	SP	CRE	ED,ID	TD	10/29/2025
2021 PO7683860024	F	5	35 UNK	SP	CCA		V	10/30/2025
2021 PO7689960047	KU	5	35 UNK	SP	CRE	ID	BD	10/31/2025
2021 PO4140586087	F	3	45 BRO	SP	CCA		V	11/1/2025
2021 PO7671260389	F	4	40 BRO	SP	CRE		V	11/2/2025
2021 PO7667961268	KU	6	30 BRO	SP	CRE	ED,ID	TD	11/3/2025
2021 PO7685360113-A	KU	5	35 UNK	SP	CCA		V	11/4/2025
2021 PO7684159926	F	5	35 UNK	SP	CCA		V	11/5/2025
2021 PO7685360113	KU	4	40 UNK	SP	CCA		V	11/6/2025
2021 PO4779103586	KU	3	40 BRN	SP	CRE	ED,ID	TD	11/7/2025
2021 PO3972816586	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	11/8/2025
2021 PO4004517208	KU	4	45 XXX	SP	CRE	ED,HH,ID,RB	BX	11/9/2025
2021 PO3981016802	KU	4	40 XXX	SP	CRE	ED,HH,ID,RB	X	11/10/2025
2021 PO7606562692	F	4	40 BRO	SP	CRE		V	11/11/2025
2021 PO7609362749	KU	5	35 BRO	SP	S		V	11/12/2025
2021 PO7614562577	F	4	40 BRO	SP	CRE		V	11/13/2025
2021 PO7598062894	F	4	40 BRO	SP	CRE		V	11/14/2025
2021 PO4153084722	LGE	6	30 ACE	SP	CRE	ED,ID,IP	TD	11/15/2025
2021 PO4141786098	F	3	45 BRO	SP	A		V	11/16/2025
2021 PO4153384727	LGE	4	40 ACE	SP	CRE	ED,ID	TD	11/17/2025
2021 PO4154184708	LGE	4	40 ACE	SP	CRE	ED,ID	TD	11/18/2025
2021 PO4142386104	F	3	45 BRO	SP	A		V	11/19/2025

2021 PO4153784699	LGE	4	40 ACE	SP	CRE	ED,ID	BD		11/20/2025
2021 PO4144386124	F	3	45 BRO	SP	A		V		11/21/2025
2021 PO7624662131	KU	6	30 BRO	SP	CRE	ED,ID	TD		11/22/2025
2021 PO7581458198-A	KU	6	30 UNK	SP	CRE	HH,ID	X	RP2	11/23/2025
2021 PO7622062566	KU	5	35 BRO	SP	CCA		V		11/24/2025
2021 PO4319914982	KU	2	80 XXX	SP	CRE	ID,IP	BD		11/25/2025
2021 PO4453585643	LGE	3	45 ACE	SP	CCA	ED,ID	BD		11/26/2025
2021 PO4398685266	LGE	4	40 BRO	SP	A	ID,IP	BD		11/27/2025
2021 PO93944494735	KU	3	45 XXX	SP	CRE	ED,ID	BD		11/28/2025
2021 PO9378594384	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD		11/29/2025
2021 PO9362195416	KU	4	45 XXX	SP	CRE	ED,ID	BD		11/30/2025
2021 PO9355494943	KU	2	40 XXX	SP	CRE	ED,ID	BD		12/1/2025
2021 PO9361795037	KU	4	40 XXX	SP	CRE	ED,ID	BD		12/2/2025
2021 PO9365295761	KU	6	30 XXX	SP	CRE	ED,ID	BD		12/3/2025
2021 PO4455485512	LGE	UNK	65 ACE	SP	CRE	ED	BD		12/4/2025
2021 PO4455285514	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD		12/5/2025
2021 PO4439985458	LGE	UNK	55 ACE	SP	CRE	ED	BD		12/6/2025
2021 PO1686867709	LGE	4	40 ACE	SP	P	ED	BD		12/7/2025
2021 PO4454685508	LGE	4	40 ACE	SP	CRE	ED,IP	BD		12/8/2025
2021 PO4454185533	LGE	UNK	65 ACE	SP	A	ED	BD		12/9/2025
2021 PO5840009536	KU	1	80 XXX	SP	CRE	ID	BD		12/10/2025
2021 PO5862109526	KU	1	75 XXX	SP	CRE	ID	BD		12/11/2025
2021 PO8418696954	KU	4	40 XXX	DF	CRE	ED,ID	BD		12/12/2025
2021 PO4465585607	LGE	3	50 ACE	SP	A	ED	BD		12/13/2025
2021 PO4467085618	LGE	4	35 ACE	SP	A	ED	BD		12/14/2025
2021 4568185630-a	LGE	3	40 ACE	SP	CRE	ED	BD		12/15/2025
2021 PO4470785643	LGE	3	50 ACE	SP	CRE	ED	BD		12/16/2025
2021 PO5859197951	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		12/17/2025
2021 PO4454085492	LGE	4	35 ACE	SP	A	ED,ID	BD		12/18/2025
2021 PO9347494993	KU	2	50 XXX	SP	CRE	ED,ID	BD		12/19/2025
2021 PO0028888560	KU	6	30 UNK	SP	CRE	ID	BD		12/20/2025
2021 PO0163590667	KU	5	35 UNK	SP	CRE	ID	BD		12/21/2025
2021 PO0150090358	KU	5	35 UNK	SP	CRE	ID	BD		12/22/2025
2021 PO4448585401	LGE	UNK	70 ACE	SP	CRE	ED	BD		12/23/2025
2021 PO9522293982	KU	4	40 XXX	SP	CRE	ED,ID	BD		12/24/2025
2021 PO9522694006	KU	3	45 XXX	SP	CRE	ED,ID	BD		12/25/2025
2021 PO0156190040	KU	4	40 UNK	SP	CRE	ED,HH,ID	BX	RP1	12/26/2025
2021 PO4589111487	F	4	40 XXX	SP	CRE	HH	BX	PX	12/27/2025
2021 PO6336403660	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	12/28/2025
2021 PO6250702809	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	12/29/2025
2021 PO5827000505	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	12/30/2025
2021 PO5854308835	KU	4	45 XXX	SP	CRE	HH,ID	BX	RP2	12/31/2025
2021 PO6157497774	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/1/2026
2021 PO6144498442	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	1/2/2026
2021 PO6141898599	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/3/2026
2021 PO6070495899	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/4/2026
2021 PO6339101055	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/5/2026
2021 PO6337300824	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/6/2026
2021 PO4779110243	KU	6	30 XXX	SP	CRE	ID,IP	BX	RP3	1/7/2026
2021 PO0275894186	KU	4	40 UNK	SP	P	ED,HH,ID	BX	PX	1/8/2026
2021 PO6110096961	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/9/2026
2021 PO9516194082	KU	4	40 XXX	SP	CRE	ED,ID,IP,RB	BX	RP1	1/10/2026
2021 PO6363101171	KU	4	45 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/11/2026
2021 PO6317003445	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/12/2026

2021 PO5888000041	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/13/2026
2021 PO8447701100	KU	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	RP2	1/14/2026
2021 O185391314A	KU	4	40 UNK	SP	CCA		T		1/15/2026
2021 PO0185391314	KU	4	40 BRO	SP	CCA		T		1/16/2026
2021 PO9446494762	KU	3	45 XXX	SP	S	ED,SR	T		1/17/2026
2021 PO0102391141	KU	4	40 UNK	SP	CRE		T		1/18/2026
2021 PO5768204388	KU	6	30 XXX	SP	CCA	ED	T		1/19/2026
2021 PO0187691544	KU	4	40 BRO	SP	CCA		T		1/20/2026
2021 PO5213411531	KU	6	30 XXX	SP	CCA	ED	T		1/21/2026
2021 PO5260111430	KU	4	40 XXX	SP	CRE	ID	TD		1/22/2026
2021 PO4934409544	KU	5	35 XXX	SP	CRE	ID	TD		1/23/2026
2021 PO4554711210	KU	6	30 XXX	SP	CRE	ID	TD		1/24/2026
2021 PO4537312713	KU	4	40 XXX	SP	CRE	ID	TD		1/25/2026
2021 PO5814800572	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		1/26/2026
2021 PO0078891266	KU	2	40 UNK	SP	CRE	ED,ID	TD		1/27/2026
2021 PO0093990982	KU	4	40 UNK	SP	CRE	ED,ID	TD		1/28/2026
2021 PO0012892002	KU	4	40 UNK	SP	CRE	ED,ID	TD		1/29/2026
2021 PO4427285251	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		1/30/2026
2021 PO4425785261	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		1/31/2026
2021 PO4426985262	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		2/1/2026
2021 PO0066191348	KU	5	35 UNK	SP	CRE	ED,ID	TD		2/2/2026
2021 PO9922890912	KU	4	45 KOP	SP	P	ED,ID	TD		2/3/2026
2021 PO4512215569	KU	3	45 XXX	SP	CRE	ID	TD		2/4/2026
2021 PO4310914450	KU	6	30 XXX	SP	CRE	ID	TD		2/5/2026
2021 PO9986691219	KU	4	40 UNK	SP	CRE	ED,ID	TD		2/6/2026
2021 PO0015191193	KU	2	40 UNK	SP	CRE	ED,ID	TD		2/7/2026
2021 PO0019091248	KU	4	40 UNK	SP	CRE	ED,ID	TD		2/8/2026
2021 PO0021491151	KU	4	40 UNK	SP	CRE	ED,ID	TD		2/9/2026
2021 PO8763892743	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SR	TD		2/10/2026
2021 PO4582411953	KU	4	40 XXX	SP	CRE	ID	TD		2/11/2026
2021 PO4401385269	LGE	4	40 BRO	SP	A	ED,ID	TD		2/12/2026
2021 PO9978391081	KU	3	45 UNK	SP	CRE	ED,ID	TD		2/13/2026
2021 PO0073990566	KU	4	40 UNK	SP	CRE	ED,ID	TD		2/14/2026
2021 PO0104090571	KU	6	30 UNK	SP	CRE	ED,ID	TD		2/15/2026
2021 PO0081590399	KU	5	40 UNK	SP	CRE	ED,ID	TD		2/16/2026
2021 PO4541611627	KU	4	40 XXX	SP	CRE	ID	TD		2/17/2026
2021 PO0085390375	KU	3	40 UNK	SP	CRE	ED,ID	TD		2/18/2026
2021 PO0221789689	KU	2	40 UNK	SP	CRE	ED,ID,IP	TD		2/19/2026
2021 PO9354695454	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD		2/20/2026
2021 PO6057599070	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD		2/21/2026
2021 PO9367295389	KU	3	45 XXX	SP	CRE	ED,ID	TD		2/22/2026
2021 PO9369494221	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD	TD		2/23/2026
2021 PO4450885662	LGE	4	35 ACE	SP	CRE	ED,ID	TD		2/24/2026
2021 PO4308214803	KU	3	35 XXX	SP	CRE	ID	TD		2/25/2026
2021 PO9389494652	KU	3	45 XXX	SP	CRE	ED,ID	TD		2/26/2026
2021 PO9942391321	KU	3	45 UNK	SP	CRE	ED,ID	TD		2/27/2026
2021 PO9949791359	KU	6	30 UNK	SP	CRE	ED,ID	TD		2/28/2026
2021 PO9959391413	KU	5	35 UNK	SP	CRE	ED,ID	TD		3/1/2026
2021 PO9956391541	KU	4	40 UNK	SP	CRE	ED,ID	TD		3/2/2026
2021 PO9381694710	KU	2	40 XXX	SP	CRE	ED,ID,IP	TD		3/3/2026
2021 PO9934390908	KU	4	40 UNK	SP	CRE	ED,ID	TD		3/4/2026
2021 PO0142890198	KU	5	35 UNK	SP	CRE	HH,ID	TD		3/5/2026
2021 PO0204990406	KU	4	40 UNK	SP	CRE	ED,ID	TD		3/6/2026
2021 PO0178790572	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD		3/7/2026

2021 PO0243190493	KU	2	40 UNK	SP	CRE	ED,ID,IP	TD	3/8/2026
2021 PO0236290348	KU	5	35 UNK	SP	CRE	ED,ID	TD	3/9/2026
2021 PO0234290302	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	3/10/2026
2021 PO9330895131	KU	3	45 XXX	SP	CRE	ED,ID	TD	3/11/2026
2021 PO9331495152	KU	2	50 XXX	SP	CRE	ED,ID	TD	3/12/2026
2021 PO9333195197	KU	3	45 XXX	SP	CRE	ED,ID	TD	3/13/2026
2021 PO9342895244	KU	2	50 XXX	SP	CRE	ED,ID,IP	TD	3/14/2026
2021 PO9406394374	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	3/15/2026
2021 PO5865597855	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	3/16/2026
2021 PO4398885239	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	3/17/2026
2021 PO4455685466	LGE	4	35 ACE	SP	A	ED,ID	TD	3/18/2026
2021 PO4454885479	LGE	4	35 ACE	SP	A	ED,ID	TD	3/19/2026
2021 PO4469585635	LGE	3	50 ACE	SP	P	ED	TD	3/20/2026
2021 PO8356496105	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/21/2026
2021 PO5872109447	KU	4	40 XXX	SP	CRE	ID	TD	3/22/2026
2021 PO5868609299	KU	4	40 XXX	SP	CRE	ID	TD	3/23/2026
2021 PO4436085483	LGE	4	30 ACE	SP	CRE	ED	TD	3/24/2026
2021 PO5861208974	KU	4	40 XXX	SP	CRE	ID	TD	3/25/2026
2021 PO4449985629	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/26/2026
2021 PO4449685634	LGE	4	40 ACE	SP	P	ED,ID	TD	3/27/2026
2021 PO5852008664	KU	4	45 XXX	SP	CRE	ID	TD	3/28/2026
2021 PO5846008473	KU	4	40 XXX	SP	CRE	ID	TD	3/29/2026
2021 PO0037292491	KU	5	40 UNK	SP	CRE	ED,ID	TD	3/30/2026
2021 PO4454185521	LGE	4	30 ACE	SP	P	ED,ID	TD	3/31/2026
2021 PO0073692454	KU	6	35 UNK	SP	CRE	ED,ID	TD	4/1/2026
2021 PO9126496491	KU	3	45 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	4/2/2026
2021 PO0112790191	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/3/2026
2021 PO0099990276	KU	5	35 UNK	SP	CRE	ED,ID	TD	4/4/2026
2021 PO0091490333	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/5/2026
2021 PO4409685300	LGE	4	30 BRO	SP	A	ED,ID	TD	4/6/2026
2021 PO4441585672	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	4/7/2026
2021 PO8925493742	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	4/8/2026
2021 PO8939894039	KU	6	35 XXX	SP	CRE	ED,ID,MD	TD	4/9/2026
2021 PO8952694300	KU	6	35 XXX	SP	CRE	ED,ID,IP,MD	TD	4/10/2026
2021 PO8965694559	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/11/2026
2021 PO4472585618	LGE	4	40 ACE	SP	CRE	ID	TD	4/12/2026
2021 PO4441585661	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	4/13/2026
2021 PO8942193632	KU	4	45 XXX	SP	CRE	ED,ID	TD	4/14/2026
2021 PO8830293282	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	4/15/2026
2021 PO8855993416	KU	4	35 XXX	DF	CRE	ED,ID,MD,SRC	TD	4/16/2026
2021 PO8884393564	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/17/2026
2021 PO8836593968	KU	4	35 XXX	SP	CRE	ED,ID,IP	TD	4/18/2026
2021 PO8855694285	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/19/2026
2021 PO4426685409	LGE	4	30 BRO	SP	CRE	ED,ID	TD	4/20/2026
2021 PO4469985672	LGE	4	40 ACE	SP	A	ID	TD	4/21/2026
2021 PO4443385638	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	4/22/2026
2021 PO6043299157	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	4/23/2026
2021 PO4443485626	LGE	4	35 BRO	SP	A	ED,ID	TD	4/24/2026
2021 PO4471485645	LGE	4	40 ACE	SP	CRE	ED	TD	4/25/2026
2021 PO4472185634	LGE	4	40 ACE	SP	CRE	ID	TD	4/26/2026
2021 PO0099791171	KU	4	40 ACW	SP	CRE	ED,ID	TD	4/27/2026
2021 PO0113391129	KU	6	30 UNK	SP	CRE	ED,ID	TD	4/28/2026
2021 PO4418885280	LGE	4	35 BRO	SP	A	ED,ID	TD	4/29/2026
2021 PO0110191155	KU	6	30 UNK	SP	CRE	ED,ID	TD	4/30/2026



2021	PO0041891506	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/1/2026
2021	PO0050291452	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/2/2026
2021	PO4438785467	LGE	4	40 ACE	SP	CRE	ED,ID	TD	5/3/2026
2021	PO0071098452	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/4/2026
2021	PO4441285449	LGE	4	40 ACE	SP	CRE	ED,ID	TD	5/5/2026
2021	PO0063897689	KU	5	30 UNK	SP	CRE	ED,ID	TD	5/6/2026
2021	PO0065197661	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/7/2026
2021	PO0060797365	KU	5	40 UNK	SP	CRE	ED,ID	TD	5/8/2026
2021	PO0055997043	KU	3	45 UNK	SP	CRE	ED,ID	TD	5/9/2026
2021	PO0046296785	KU	5	40 UNK	SP	CRE	ED,ID	TD	5/10/2026
2021	PO0035796508	KU	5	35 UNK	SP	CRE	ED,ID	TD	5/11/2026
2021	PO0243391960	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/12/2026
2021	PO0251191441	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/13/2026
2021	PO4405386240	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	5/14/2026
2021	PO0032091939	KU	5	40 UNK	SP	CRE	ED,ID	TD	5/15/2026
2021	PO0032991790	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/16/2026
2021	PO0032891814	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/17/2026
2021	PO4489785701	LGE	1	40 ACE	SP	P	ED,ID	TD	5/18/2026
2021	PO4435085403	LGE	3	30 ACE	SP	P	ED,ID	TD	5/19/2026
2021	PO4422385605	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	5/20/2026
2021	PO4434685376	LGE	4	30 ACE	SP	P	ED	TD	5/21/2026
2021	PO4435185415	LGE	3	30 ACE	SP	A	ED,ID	TD	5/22/2026
2021	PO4435485433	LGE	4	30 ACE	SP	A	ID	TD	5/23/2026
2021	PO4400886287	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	5/24/2026
2021	PV4489485732	LGE	4	40 ACE	SP	P	ED,ID	TD	5/25/2026
2021	PO9465895066	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	5/26/2026
2021	PO9461694997	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/27/2026
2021	PO9430194656	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	5/28/2026
2021	PO9445594744	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	5/29/2026
2021	PO9456294914	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	5/30/2026
2021	PO9424694623	KU	6	30 XXX	DF	CRE	ED,ID	TD	5/31/2026
2021	PO0028595464	KU	4	40 UNK	SP	CRE	ED,ID	TD	6/1/2026
2021	PO0200191265	KU	4	40 UNK	SP	CRE	ED,ID	TD	6/2/2026
2021	PO9501094072	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	6/3/2026
2021	PO9471794380	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	6/4/2026
2021	PO9506794151	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/5/2026
2021	PO0047590919	KU	6	30 UNK	SP	CRE	ED,ID	TD	6/6/2026
2021	PO0030191095	KU	4	40 UNK	SP	CRE	ED,ID	TD	6/7/2026
2021	PO0017190878	KU	4	40 UNK	SP	CRE	ED,ID	TD	6/8/2026
2021	PO0035390815	KU	6	30 UNK	SP	CRE	ED,ID	TD	6/9/2026
2021	PO9240797163	KU	2	50 XXX	SP	CRE	ED,ID,IP	TD	6/10/2026
2021	PO9202797037	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	6/11/2026
2021	PO4468785691	LGE	3	50 ACE	SP	CRE	ID	TD	6/12/2026
2021	PO4445785674	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	6/13/2026
2021	PO4444685664	LGE	4	35 BRO	SP	A	ED,ID	TD	6/14/2026
2021	PO4446685662	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	6/15/2026
2021	PO4395485212	LGE	4	35 BRO	SP	A	ED,ID	TD	6/16/2026
2021	PO0122990128	KU	4	40 UNK	SP	CRE	ED,ID	TD	6/17/2026
2021	PO0016794794	KU	5	40 UNK	SP	CRE	ED,ID	TD	6/18/2026
2021	PO9158597120	KU	2	45 XXX	SP	CRE	ED,ID,IP	TD	6/19/2026
2021	PO0044090617	KU	5	35 UNK	SP	P	ED,ID	TD	6/20/2026
2021	PO4639412082	KU	4	40 XXX	SP	CRE	ID	TD	6/21/2026
2021	PO0017592368	KU	4	40 UNK	SP	CRE	ED,ID	TD	6/22/2026
2021	PO4465585746	LGE	4	40 ACE	SP	CRE	ED,ID	TD	6/23/2026

2021	PO4775409455	KU	5	35 XXX	SP	CRE	ID	TD	6/24/2026
2021	PO0027395674	KU	4	40 KOP	SP	CRE	ED,ID	TD	6/25/2026
2021	PO0009893578	KU	5	35 UNK	SP	CRE	HH,ID	TD	6/26/2026
2021	PO9985193619	KU	5	35 UNK	SP	CRE	ED,ID	TD	6/27/2026
2021	PO8813393571	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	6/28/2026
2021	PO8799293316	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/29/2026
2021	PO8724492962	KU	5	35 XXX	SP	CRE	ED,ID	TD	6/30/2026
2021	PO8750292952	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	7/1/2026
2021	PO9945993282	KU	5	35 UNK	SP	CRE	ED,ID	TD	7/2/2026
2021	PO4484785664	LGE	UNK	45 ACE	SP	CRE	ED	TD	7/3/2026
2021	PO0011890195	KU	4	40 UNK	SP	CRE	ED,ID	TD	7/4/2026
2021	PO9957288245	KU	4	45 UNK	SP	CRE	ED,ID	TD	7/5/2026
2021	PO4397485228	LGE	4	35 BRO	SP	A	ED,ID	TD	7/6/2026
2021	PO8567193765	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/7/2026
2021	PO8573593640	KU	6	30 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	7/8/2026
2021	PO4444885603	LGE	4	35 BRO	SP	A	ED,ID	TD	7/9/2026
2021	PO4444185614	LGE	5	35 BRO	SP	A	ED,ID	TD	7/10/2026
2021	PO0045496389	KU	4	40 UNK	SP	CRE	ED,ID	TD	7/11/2026
2021	PO0071598662	KU	4	40 UNK	SP	CRE	ED,ID	TD	7/12/2026
2021	PO0013191784	KU	5	35 UNK	SP	CRE	ED,ID	TD	7/13/2026
2021	PO0023991588	KU	6	30 UNK	SP	CRE	ED,ID	TD	7/14/2026
2021	PO4428185251	LGE	3	45 BRO	SP	A	ED,ID	TD	7/15/2026
2021	PO4433485273	LGE	4	30 ACE	SP	CRE	ED	TD	7/16/2026
2021	PO4433885310	LGE	4	30 ACE	SP	CRE	ED	TD	7/17/2026
2021	PO4434085323	LGE	4	30 ACE	SP	CRE	ED,ID	TD	7/18/2026
2021	PO4434285333	LGE	4	30 ACE	SP	A	ED,ID	TD	7/19/2026
2021	PO4434085341	LGE	4	30 ACE	SP	P	ED,ID	TD	7/20/2026
2021	PO0060090785	KU	4	40 KOP	SP	CRE	ED,ID	TD	7/21/2026
2021	PO4428285273	LGE	4	40 BRO	SP	A	ED,ID	TD	7/22/2026
2021	PO6346000994	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	7/23/2026
2021	PO8327201897	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/24/2026
2021	PO5797800539a	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	7/25/2026
2021	PO4415785289	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	7/26/2026
2021	PO4443085687	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	7/27/2026
2021	PO4468285720	LGE	4	40 ACE	SP	P	ED,ID	TD	7/28/2026
2021	PO4466985722	LGE	4	40 ACE	SP	A	ED,ID	TD	7/29/2026
2021	PO4395685314	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	7/30/2026
2021	PO0025895929	KU	6	30 UNK	SP	CRE	ED,ID	TD	7/31/2026
2021	PO0016794445	KU	5	35 UNK	SP	CRE	ED,ID	TD	8/1/2026
2021	PO9971890976	KU	4	40 UNK	SP	CRE	ED,ID	TD	8/2/2026
2021	PO9983590907	KU	6	30 UNK	SP	CRE	ED,ID	TD	8/3/2026
2021	PO9960287891	KU	4	45 UNK	SP	CRE	ED,ID	TD	8/4/2026
2021	PO3942486373	F	4	40 ACE	SP	CCA	V	8/5/2026	
2021	PO3943386382	F	4	40 ACE	SP	CRE	V	8/6/2026	
2021	PO3944986360	F	4	40 ACE	SP	P	V	8/7/2026	
2021	PO3944786367	F	4	40 ACE	SP	CRE	V	8/8/2026	
2021	PO3941486362	F	3	45 ACE	SP	CCA	V	8/9/2026	
2021	PO3941886322	F	4	40 ACE	SP	CRE	V	8/10/2026	
2021	PO3941686317	LGE	4	35 ACE	SP	CCA	V	8/11/2026	
2021	PO6549174701	LGE	4	35 ACE	SP	CCA	V	8/12/2026	
2021	PO3943386313	F	4	40 ACE	SP	CCA	V	8/13/2026	
2021	PO3945286305	F	4	40 ACE	SP	CRE	V	8/14/2026	
2021	PO3947286295	F	4	40 ACE	SP	CCA	V	8/15/2026	
2021	PO3948086280	F	4	30 ACE	SP	CCA	V	8/16/2026	

2021 PO3948286284	F	4	40 ACE	SP	CCA		V	8/17/2026	
2021 PO3962986465	F	4	40 ACE	SP	P		V	8/18/2026	
2021 PO3956786358	F	4	40 ACE	SP	A		V	8/19/2026	
2021 PO3956386354	F	6	30 ACE	SP	CRE		V	8/20/2026	
2021 PO3958086370	F	4	40 ACE	SP	CCA		V	8/21/2026	
2021 PO5345035390	KU	2	55 BRN	SP	CCA		V	8/22/2026	
2021 PO4085286317	F	4	40 BRO	SP	CRE		V	8/23/2026	
2021 PO4083386322	F	4	40 BRO	SP	A		V	8/24/2026	
2021 PO4081986331	F	5	25 BRO	SP	CRE		V	8/25/2026	
2021 PO4081886326	F	4	40 BRO	SP	CRE		V	8/26/2026	
2021 PO4080686327	F	4	40 BRO	SP	CRE		V	8/27/2026	
2021 PO4079486327	F	4	40 BRO	SP	CRE		V	8/28/2026	
2021 PO4078286328	F	4	40 BRO	SP	CRE		V	8/29/2026	
2021 PO4077086320	F	5	25 BRO	SP	CRE		V	8/30/2026	
2021 PO4077086329	F	4	40 BRO	SP	CRE		V	8/31/2026	
2021 PO4061386355	LGE	4	40 BRO	SP	CRE		V	9/1/2026	
2021 PO4062086351	LGE	4	40 BRO	SP	CRE		V	9/2/2026	
2021 PO4063086345	LGE	4	40 BRO	SP	CRE		V	9/3/2026	
2021 PO5207037791	KU	4	40 UNK	SP	CRE	ID	TD	9/4/2026	
2021 PO4063186335	F	4	40 BRO	SP	CCA		V	9/5/2026	
2021 PO4071686331	F	4	40 BRO	SP	CRE		V	9/6/2026	
2021 PO4073486332	F	4	40 BRO	SP	CRE		V	9/7/2026	
2021 PO4065786419	LGE	3	45 BRO	SP	CCA		V	9/8/2026	
2021 PO5326937945	KU	3	45 BRO	SP	CRE		V	9/9/2026	
2021 4069686434A	LGE	4	35 BRO	SP	CCA		V	9/10/2026	
2021 PO4069686434	F	4	40 BRO	SP	CRE		V	9/11/2026	
2021 PO4073686419	F	4	40 BRO	SP	CRE		V	9/12/2026	
2021 PO4072286444	F	4	40 BRO	SP	CRE		V	9/13/2026	
2021 PO4071086429	F	4	40 BRO	SP	CRE		V	9/14/2026	
2021 PO3963386444	F	4	40 ACE	SP	CRE		V	9/15/2026	
2021 PV3963986218	LGE	3	45 ACE	SP	CCA		V	9/16/2026	
2021 PO3950086273	F	4	40 ACE	SP	P		V	9/17/2026	
2021 PO3951286266	F	4	40 ACE	SP	P		V	9/18/2026	
2021 PO3951886262	F	4	40 ACE	SP	CRE		V	9/19/2026	
2021 PO3953086255	F	4	40 ACE	SP	CCA		V	9/20/2026	
2021 PO3954186249	F	3	45 ACE	SP	CCA		V	9/21/2026	
2021 PO3955286243	F	4	40 ACE	SP	CCA		V	9/22/2026	
2021 PO3956986233	F	4	40 ACE	SP	A		V	9/23/2026	
2021 PO3958786223	LGE	2	45 ACE	SP	CCA		V	9/24/2026	
2021 PO3959286220	F	4	40 ACE	SP	CCA		V	9/25/2026	
2021 PO3961086209	F	4	40 ACE	SP	CCA		V	9/26/2026	
2021 PO3962086203	F	4	40 ACE	SP	CCA		V	9/27/2026	
2021 PO3963886194	F	4	40 ACE	SP	A		V	9/28/2026	
2021 PO3964886187	F	3	45 ACE	SP	CCA		V	9/29/2026	
2021 PO3965886182	F	4	40 ACE	SP	CRE		V	9/30/2026	
2021 PO3965586170	F	4	40 ACE	SP	CRE		V	10/1/2026	
2021 PO4087686218	LGE	4	40 BRO	SP	A		V	10/2/2026	
2021 PO4086486219	LGE	4	40 BRO	SP	CRE		V	10/3/2026	
2021 PO5291634538	KU	2	50 BRN	SP	CCA		V	10/4/2026	
2021 PO4074186333	F	4	40 BRO	SP	CRE	RB	BX	RP3	10/5/2026
2021 PO4074186341	F	4	40 BRO	SP	CCA		V	10/6/2026	
2021 PO4074086353	F	4	40 BRO	SP	CCA		V	10/7/2026	
2021 PO4073886365	F	4	40 BRO	SP	CRE		V	10/8/2026	
2021 PO4074386363	F	4	30 BRO	SP	CRE		V	10/9/2026	

2021 PO5247337993	KU	3	50 UNK	SP	CRE	ID	TD		10/10/2026
2021 PO4073286385	F	4	40 BRO	SP	CRE		V		10/11/2026
2021 PO4072286385	F	3	45 BRO	SP	CRE		V		10/12/2026
2021 PO4070986392	F	4	40 BRO	SP	CRE		V		10/13/2026
2021 PO4069386399	F	4	40 BRO	SP	CRE		V		10/14/2026
2021 PO4068186406	F	4	40 BRO	SP	CRE		V		10/15/2026
2021 PO4066986413	F	4	40 BRO	SP	CRE	ED,ID	BX	RP3	10/16/2026
2021 PO5286238191	KU	2	45 BRO	SP	CRE	ID,SRS	TD		10/17/2026
2021 PO5263038073	KU	2	45 ESC	SP	CRE	ID	TD		10/18/2026
2021 PO5361435376	KU	4	40 BRN	SP	CCA		V		10/19/2026
2021 PO5475835229	KU	3	50 BRN	SP	CCA	ED,RB	X	RP2	10/20/2026
2021 PO5497335212	KU	4	45 BRN	SP	CCA	ID	BD		10/21/2026
2021 PO5505335115	KU	3	45 BRN	SP	CCA		V		10/22/2026
2021 PO5531035098	KU	3	45 BRN	SP	CCA		V		10/23/2026
2021 PO5556035082	KU	4	45 BRN	SP	CRE	ID	BD		10/24/2026
2021 PO5413235692	KU	3	45 BRN	SP	CRE	ID	BD		10/25/2026
2021 PO4075886302	F	4	40 BRO	SP	CRE		V		10/26/2026
2021 PO4074986301	F	5	25 BRO	SP	CRE		V		10/27/2026
2021 PO4075786316	F	4	40 BRO	SP	CRE		V		10/28/2026
2021 PO4074786324	F	4	30 BRO	SP	CRE		V		10/29/2026
2021 PO4075686326	F	4	40 BRO	SP	CRE		V		10/30/2026
2021 PO4064886426	LGE	4	40 BRO	SP	CRE		V		10/31/2026
2021 PO4085286220	LGE	4	40 BRO	SP	CRE		V		11/1/2026
2021 PO5351737502	KU	2	45 KOP	SP	CRE		B		11/2/2026
2021 PO5352937539	KU	4	40 KOP	SP	CRE	ID	TD		11/3/2026
2021 PO5352237107	KU	3	50 UNK	SP	CRE	ED,ID	X	PX	11/4/2026
2021 PO5331437172	KU	3	50 UNK	SP	CRE	ID	TD		11/5/2026
2021 PO5338637149	KU	2	55 KOP	SP	CCA		B		11/6/2026
2021 PO5345237326	KU	2	45 UNK	SP	CRE	ID	TD		11/7/2026
2021 PO5335537048	KU	4	45 UNK	SP	CRE	ID	TD		11/8/2026
2021 PO5337937092	F	4	35 CPT	SP	CRE		V		11/9/2026
2021 PO5369137052	KU	2	50 UNK	SP	CCA		V		11/10/2026
2021 PO5382537010	KU	2	50 UNK	SP	CRE	ID	TD		11/11/2026
2021 PO4069986224	F	4	40 BRO	SP	CRE		V		11/12/2026
2021 PO4068586225	F	4	40 BRO	SP	CRE		V		11/13/2026
2021 PO4067386226	F	4	40 BRO	SP	CRE		V		11/14/2026
2021 PO4083886193	F	4	40 BRO	SP	CRE		V		11/15/2026
2021 PO4083986200	LGE	4	30 BRO	SP	CCA		V		11/16/2026
2021 PO4084986192	F	4	40 BRO	SP	CRE		V		11/17/2026
2021 PO4086286191	F	4	40 BRO	SP	CRE		V		11/18/2026
2021 PO4087486198	F	5	25 BRO	SP	A		V		11/19/2026
2021 PO4087486190	F	4	40 BRO	SP	CRE		V		11/20/2026
2021 PO5416636998	KU	2	45 UNK	SP	CRE	ID	TD		11/21/2026
2021 PO3965186157	F	4	40 ACE	SP	A		V		11/22/2026
2021 PO3940086383	LGE	4	40 ACE	SP	CCA		V		11/23/2026
2021 PO5902511436	KU	5	45 ACW	SP	S		V		11/24/2026
2021 PO5900911487	KU	5	45 ACW	SP	S		V		11/25/2026
2021 PO5904911625	KU	5	45 ACW	SP	S		V		11/26/2026
2021 PO5920312131	KU	5	35 ACW	SP	S		V		11/27/2026
2021 PO5921212037	KU	4	40 ACW	SP	S		V		11/28/2026
2021 PO5903611707	KU	5	45 ACW	SP	S		V		11/29/2026
2021 PO5901211859	KU	5	45 ACW	SP	S		V		11/30/2026
2021 PO5909711912	KU	5	45 ACW	SP	S		V		12/1/2026
2021 PO5917911966	KU	5	45 ACW	SP	S		V		12/2/2026

2021 PO5916012065	KU	5	45 ACW	SP	S		V	12/3/2026
2021 PO5913712194	KU	5	45 ACW	SP	S		V	12/4/2026
2021 PO5898012177	KU	5	45 ACW	SP	S		V	12/5/2026
2021 PO5890112046	KU	5	45 ACW	SP	S		V	12/6/2026
2021 PO5914212319	KU	4	40 ACW	SP	S		V	12/7/2026
2021 PO3953686421	LGE	4	30 ACE	SP	CRE	ED,HH,ID	BD	12/8/2026
2021 PO3954586431	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	12/9/2026
2021 PO3956686456	LGE	4	30 ACE	SP	CRE		V	12/10/2026
2021 PO3962086503	LGE	6	30 ACE	SP	A	ID	TD	12/11/2026
2021 PO3957186362	LGE	4	40 ACE	SP	CCA		V	12/12/2026
2021 PO3960886403	LGE	4	40 ACE	SP	CCA	ED,ID	TD	12/13/2026
2021 PO3921485940	LGE	4	40 ACE	SP	A		V	12/14/2026
2021 PO3921085937	F	4	35 ACE	SP	A		V	12/15/2026
2021 PO3919985949	F	3	45 ACE	SP	CCA		V	12/16/2026
2021 PO3919685945	F	4	35 ACE	SP	CRE		V	12/17/2026
2021 PO3916885968	LGE	4	40 ACE	SP	P		V	12/18/2026
2021 PO3932185908	F	4	40 ACE	SP	CCA		V	12/19/2026
2021 PO3930485919	F	4	40 ACE	SP	A		V	12/20/2026
2021 PO3985885905	LGE	4	35 ACE	SP	CRE	ED,ID	TD	12/21/2026
2021 PO4056786323	F	4	40 BRO	SP	CRE		V	12/22/2026
2021 PO4057586327	LGE	5	30 BRO	SP	CRE	ED,ID	BX	12/23/2026
2021 PO4057686309	LGE	UNK	65 BRO	SP	CRE		V	12/24/2026
2021 PO4057786322	LGE	H2	70 BRO	SP	P		V	12/25/2026
2021 PO3934785893	F	3	45 ACE	SP	CCA		V	12/26/2026
2021 PO3934185897	F	4	40 ACE	SP	CRE		V	12/27/2026
2021 PO3933285902	F	4	40 ACE	SP	CRE		V	12/28/2026
2021 PO5116936600	KU	3	45 UNK	SP	CRE	ID	BD	12/29/2026
2021 PO3929785923	F	4	40 ACE	SP	CRE		V	12/30/2026
2021 PO3990885929	F	4	40 ACE	SP	CRE		V	12/31/2026
2021 PO3927485936	F	4	45 ACE	SP	A		V	1/1/2027
2021 PO3927685931	F	4	30 ACE	SP	CRE		V	1/2/2027
2021 PO3991985924	F	4	40 ACE	SP	CRE		V	1/3/2027
2021 PO3996985913	F	4	40 ACE	SP	CRE		V	1/4/2027
2021 PO4058086275	LGE	4	30 BRO	SP	CCA		V	1/5/2027
2021 PO4055786292	LGE	2	65 BRO	SP	CRE		V	1/6/2027
2021 PO4055886297	F	4	35 BRO	SP	CRE		V	1/7/2027
2021 PO3916586028	F	4	45 ACE	SP	CRE		V	1/8/2027
2021 PO3917686021	F	4	40 ACE	SP	CRE		V	1/9/2027
2021 PO3918286018	F	3	45 ACE	SP	CCA		V	1/10/2027
2021 PO3919186013	F	3	45 ACE	SP	CCA		V	1/11/2027
2021 PO3921885997	F	4	40 ACE	SP	A		V	1/12/2027
2021 PO3922485993	F	3	45 ACE	SP	CCA		V	1/13/2027
2021 PO3923585987	F	4	40 ACE	SP	CRE		V	1/14/2027
2021 PO3989885951	F	4	40 ACE	SP	CRE		V	1/15/2027
2021 PO3990485962	F	3	40 ACE	SP	CRE		V	1/16/2027
2021 PO3990185979	F	3	45 ACE	SP	CRE		V	1/17/2027
2021 PO3991585971	F	3	40 ACE	SP	CRE		V	1/18/2027
2021 PO3932185937	F	4	40 ACE	SP	P		V	1/19/2027
2021 PO3932985933	LGE	4	40 ACE	SP	A		V	1/20/2027
2021 PO3933885927	F	4	40 ACE	SP	A		V	1/21/2027
2021 PO4051986282	LGE	4	35 BRO	SP	CRE		V	1/22/2027
2021 PO4051886294	LGE	2	65 BRO	SP	CCA		V	1/23/2027
2021 PO4051986300	F	5	35 BRO	SP	CRE		V	1/24/2027
2021 PO4050686301	F	4	35 BRO	SP	CCA		V	1/25/2027

2021 PO3934585923	F	4	40 ACE	SP	CRE			V	1/26/2027
2021 PO3935485918	F	4	40 ACE	SP	A			V	1/27/2027
2021 PO3936885918	LGE	4	35 ACE	SP	CRE	ID		TD	1/28/2027
2021 PO3936785911	LGE	4	35 ACE	SP	P			V	1/29/2027
2021 PO3939285897	F	4	40 ACE	SP	P			V	1/30/2027
2021 PO3938285902	F	4	40 ACE	SP	CCA			V	1/31/2027
2021 PO3940085892	LGE	4	30 ACE	SP	CRE			V	2/1/2027
2021 PO3940485890	F	3	45 ACE	SP	CCA			V	2/2/2027
2021 PO3961886188	F	4	35 ACE	SP	A			V	2/3/2027
2021 PO3947686331	LGE	4	35 ACE	SP	P	ID		BD	2/4/2027
2021 PO4048786307	LGE	3	70 BRO	SP	CRE			V	2/5/2027
2021 PO5138736629	KU	3	45 INP	SP	CRE	ID		TD	2/6/2027
2021 PO5320229720a	KU	5	35 BRN	SP	CRE	ED,ID		TD	2/7/2027
2021 PO5339729739	KU	3	40 BRN	SP	A	ED		T	2/8/2027
2021 PO5344029598	KU	4	35 BRN	SP	A			B	2/9/2027
2021 PO5324929778	KU	6	30 BRN	SP	CRE			V	2/10/2027
2021 PO5297029972	KU	4	45 BRN	SP	CCA			V	2/11/2027
2021 PO5318829906	KU	4	40 BRN	SP	CCA			V	2/12/2027
2021 PO5323029888	KU	4	40 BRN	SP	CRE	ID		TD	2/13/2027
2021 PO5325729880	KU	3	45 BRN	SP	CCA			V	2/14/2027
2021 PO5338529838	KU	4	40 BRN	SP	CCA			V	2/15/2027
2021 PO4090186259	F	4	35 BRO	SP	CRE			V	2/16/2027
2021 PO6093312456	KU	4	45 ACW	SP	S			V	2/17/2027
2021 PO6070012469	KU	4	40 ACW	SP	S			V	2/18/2027
2021 PO6065512439	KU	5	35 ACW	SP	S			V	2/19/2027
2021 PO4107386258	LGE	3	45 BRO	SP	CCA			T	2/20/2027
2021 PO4107186256	LGE	5	25 BRO	SP	CRE			V	2/21/2027
2021 PO4106686236	LGE	5	25 BRO	SP	CRE			V	2/22/2027
2021 PO4107486237	F	5	35 BRO	SP	CRE			V	2/23/2027
2021 PO4105586243	LGE	5	25 BRO	SP	CRE			V	2/24/2027
2021 PO4107486244	F	5	45 BRO	SP	CRE			V	2/25/2027
2021 PO3999585960	F	4	40 ACE	SP	CRE			V	2/26/2027
2021 PO3998385951	F	3	45 ACE	SP	CCA			V	2/27/2027
2021 PO3998185936	F	4	40 ACE	SP	CRE			V	2/28/2027
2021 PO3998985931	F	4	40 ACE	SP	CRE			V	3/1/2027
2021 PO4000285924	F	4	40 ACE	SP	CRE			V	3/2/2027
2021 PO4001285918	F	4	40 ACE	SP	CRE			V	3/3/2027
2021 PO4002485912	F	4	40 ACE	SP	CRE			V	3/4/2027
2021 PO4003085922	LGE	4	30 ACE	SP	CRE			V	3/5/2027
2021 PO4109086242	F	4	40 BRO	SP	CCA			V	3/6/2027
2021 PO4110486230	F	5	30 BRO	SP	CRE			V	3/7/2027
2021 PO4108986232	F	5	30 BRO	SP	A			V	3/8/2027
2021 PO4110086242	F	5	45 BRO	SP	CRE			V	3/9/2027
2021 PO4112186240	F	4	40 BRO	SP	CRE			V	3/10/2027
2021 PO4113486239	F	4	40 BRO	SP	CRE			V	3/11/2027
2021 PO4114686238	F	4	40 BRO	SP	CRE			V	3/12/2027
2021 PO4111986229	F	5	30 BRO	SP	CRE			V	3/13/2027
2021 PO4113486232	F	5	35 BRO	SP	CRE			V	3/14/2027
2021 PO4114886231	F	4	30 BRO	SP	CRE			V	3/15/2027
2021 PO3999286077	LGE	1	70 ACE	SP	CRE			V	3/16/2027
2021 PO4119486233	F	4	45 BRO	SP	CRE			V	3/17/2027
2021 PO4000486101	LGE	4	35 ACE	SP	CCA			V	3/18/2027
2021 PO4011286037	LGE	4	40 ACE	SP	P	ED,ID		BD	3/19/2027
2021 PO4010686034	LGE	4	30 ACE	SP	CCA			V	3/20/2027

2021 PO4068486317	F	4	40 BRO	SP	CRE	ED,HH,ID	V	3/21/2027
2021 PO4069786316	F	4	40 BRO	SP	CRE		V	3/22/2027
2021 PO4067086318	LGE	3	45 BRO	SP	CCA		V	3/23/2027
2021 PO4065886319	F	3	45 BRO	SP	CRE		V	3/24/2027
2021 PO4064586319	F	3	50 BRO	SP	CRE		V	3/25/2027
2021 PO4014086021	LGE	3	45 ACE	SP	CCA		V	3/26/2027
2021 PO4013786016	LGE	4	30 ACE	SP	P	ED,ID	TD	3/27/2027
2021 PO4063286320	F	UNK	55 BRO	SP	CRE		V	3/28/2027
2021 PO4070486333	F	4	40 BRO	SP	CRE		V	3/29/2027
2021 PO4061986321	LGE	3	60 BRO	SP	CRE	ED,ID	TD	3/30/2027
2021 PO4060886321	LGE	3	65 BRO	SP	CRE	ED,ID	TD	3/31/2027
2021 PO4069386338	F	4	40 BRO	SP	CRE		V	4/1/2027
2021 PO4068086345	F	4	40 BRO	SP	CCA		V	4/2/2027
2021 PO5279435185	KU	4	40 BRN	SP	CRE	ID,IP	BX PX	4/3/2027
2021 PO5263234759	KU	4	40 BRN	SP	CRE	ID	TD	4/4/2027
2021 PO6306011675	KU	4	45 ACW	SP	S		V	4/5/2027
2021 PO6328911665	KU	4	45 ACW	SP	S		V	4/6/2027
2021 PO6356011688	KU	4	45 ACW	SP	S		V	4/7/2027
2021 PO6355311540	KU	4	45 ACW	SP	S		V	4/8/2027
2021 PO5155536560	KU	3	45 INP	SP	CRE	ID	TD	4/9/2027
2021 PO5151736464	KU	3	45 INP	SP	CRE	ID	BD	4/10/2027
2021 PO4098586245	LGE	UNK	60 BRO	SP	CRE		V	4/11/2027
2021 PO4097286246	F	4	40 BRO	SP	CRE		V	4/12/2027
2021 PO4096986246	LGE	2	60 BRO	SP	CRE		V	4/13/2027
2021 PO4095286248	LGE	2	60 BRO	SP	CRE	ED,ID	BX RP3	4/14/2027
2021 PO4032985006	F	4	40 BRO	SP	CRE		V	4/15/2027
2021 PO4052384589	LGE	1	85 ACE	SP	CRE		V	4/16/2027
2021 PO4051584571	LGE	1	85 ACE	SP	CRE		V	4/17/2027
2021 PO4050784553	LGE	1	85 ACE	SP	CRE		V	4/18/2027
2021 PO4049984535	LGE	1	85 ACE	SP	CRE		V	4/19/2027
2021 PO5044739856	KU	3	45 BRO	SP	CCA		V	4/20/2027
2021 PO5062639779	KU	3	45 BRO	SP	CCA		V	4/21/2027
2021 PO5076939863	KU	2	50 UNK	SP	P		V	4/22/2027
2021 PO5089939993	KU	2	50 UNK	SP	P		V	4/23/2027
2021 PO4041485271	F	4	30 BRO	SP	CRE		V	4/24/2027
2021 PO4041585276	F	3	45 BRO	SP	CCA		V	4/25/2027
2021 PO4042485275	F	4	40 BRO	SP	CRE		V	4/26/2027
2021 PO5179859333	KU	3	45 BRN	SP	CCA		V	4/27/2027
2021 PO5119759126	KU	4	45 BRN	SP	CCA		V	4/28/2027
2021 PO5138159326	KU	3	45 BRN	SP	CCA		V	4/29/2027
2021 PO4114885211	LGE	4	40 ACE	SP	CRE	ED,ID	BD	4/30/2027
2021 PO4034285014	F	3	45 BRO	SP	CCA		V	5/1/2027
2021 PO7503761906	F	3	45 BRO	SP	CCA		V	5/2/2027
2021 PO4035885023	F	4	45 BRO	SP	CCA		V	5/3/2027
2021 PO7508862012	LGE	3	50 BRO	SP	CCA		V	5/4/2027
2021 PO4035285035	F	3	50 BRO	SP	CCA		V	5/5/2027
2021 PO4035785036	F	5	25 BRO	SP	CRE		V	5/6/2027
2021 PO4035485050	F	3	45 BRO	SP	CCA		V	5/7/2027
2021 PO4035985048	F	5	30 BRO	SP	CRE		V	5/8/2027
2021 PO4035985058	F	5	30 BRO	SP	A		V	5/9/2027
2021 PO4118785211	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	5/10/2027
2021 PO4118085214	LGE	4	35 ACE	SP	CRE		B	5/11/2027
2021 PO4976639425	KU	3	45 BRO	SP	CCA		V	5/12/2027
2021 PO4123185156	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	5/13/2027

2021 PO4122585155	LGE	4	30 ACE	SP	A	ID	BD	5/14/2027
2021 PO8878708614	KU	4	40 OTH	SP	CRE	ID	TD	5/15/2027
2021 PO8889008631	KU	4	40 OTH	SP	CRE	ID	TD	5/16/2027
2021 PO8871808552	F	4	40 OTH	SP	CRE		V	5/17/2027
2021 PO8854108581	KU	5	35 OTH	SP	CCA		V	5/18/2027
2021 PO4049084517	LGE	1	85 ACE	SP	CRE		V	5/19/2027
2021 PO4048284498	LGE	1	85 ACE	SP	CRE		V	5/20/2027
2021 PO4047484481	LGE	1	85 ACE	SP	CRE		V	5/21/2027
2021 PO4045784445	LGE	1	85 ACE	SP	CRE		V	5/22/2027
2021 PO4044984427	LGE	1	85 ACE	SP	CRE		V	5/23/2027
2021 PO4035585065	F	4	40 BRO	SP	CRE		V	5/24/2027
2021 PO4035685074	F	4	40 BRO	SP	CRE		V	5/25/2027
2021 PO3964585050	LGE	2	55 ACE	SP	CRE	ED,HH,ID	TD	5/26/2027
2021 PO4036385085	F	4	35 BRO	SP	CCA		V	5/27/2027
2021 PO4035685088	F	4	40 BRO	SP	A		V	5/28/2027
2021 PO4035785102	F	3	45 BRO	SP	CCA		V	5/29/2027
2021 PO4035885114	F	4	40 BRO	SP	CRE		V	5/30/2027
2021 PO4035985127	F	4	40 BRO	SP	CCA		V	5/31/2027
2021 PO4036085137	F	4	40 BRO	SP	CRE		V	6/1/2027
2021 PO4036585151	F	5	30 BRO	SP	A		V	6/2/2027
2021 PO4036085146	F	4	40 BRO	SP	CRE		V	6/3/2027
2021 PO4036685161	F	5	30 BRO	SP	A		V	6/4/2027
2021 PO4036185162	F	4	40 BRO	SP	CCA		V	6/5/2027
2021 PO4036285175	F	4	35 BRO	SP	CCA		V	6/6/2027
2021 PO4044084408	LGE	1	85 ACE	SP	CRE		V	6/7/2027
2021 PO4042384366	LGE	1	85 ACE	SP	CRE		V	6/8/2027
2021 PO4043184384	LGE	1	85 ACE	SP	CRE		V	6/9/2027
2021 PO8871808510	KU	5	30 OTH	SP	CCA		V	6/10/2027
2021 PO8874108459	KU	4	45 OTH	SP	CCA	ID,SRS	TD	6/11/2027
2021 PO8864008442	F	4	40 OTH	SP	CRE		V	6/12/2027
2021 PO8853708494	F	4	40 OTH	SP	CRE		V	6/13/2027
2021 PO8864908337	F	4	40 OTH	SP	CRE		V	6/14/2027
2021 PO8871408349	KU	5	35 OTH	SP	CRE	ID	TD	6/15/2027
2021 PO3966285058	LGE	2	55 ACE	SP	CCA		V	6/16/2027
2021 PO3968085066	LGE	2	55 ACE	SP	P		V	6/17/2027
2021 PO4060785294	F	4	40 ACE	SP	CRE		V	6/18/2027
2021 PO3969585073	LGE	3	55 ACE	SP	P	ED,ID	TD	6/19/2027
2021 PO4039485277	F	4	40 BRO	SP	CRE		V	6/20/2027
2021 PO4038885272	F	5	30 BRO	SP	CCA		V	6/21/2027
2021 PO4038385277	F	4	40 BRO	SP	CRE		V	6/22/2027
2021 PO5066541053	KU	3	45 BRO	SP	CCA		V	6/23/2027
2021 PO4037285274	F	4	35 BRO	SP	CCA		V	6/24/2027
2021 PO4036885264	F	4	40 BRO	SP	CRE		V	6/25/2027
2021 PO4036785250	F	3	45 BRO	SP	CCA		V	6/26/2027
2021 PO4036885278	F	4	45 BRO	SP	CRE		V	6/27/2027
2021 PO4036985292	F	4	40 BRO	SP	CRE		V	6/28/2027
2021 PO4039785244	LGE	4	30 BRO	SP	CRE	ED,ID	TD	6/29/2027
2021 PO4041385247	F	4	40 BRO	SP	CRE		V	6/30/2027
2021 PO4040285247	F	4	40 BRO	SP	CRE		V	7/1/2027
2021 PO4039285248	F	4	40 BRO	SP	CRE		V	7/2/2027
2021 PO5155859521	KU	3	45 BRN	SP	CCA		V	7/3/2027
2021 PO3971485081	LGE	1	50 ACE	SP	CCA		V	7/4/2027
2021 PO3973285090	LGE	2	55 ACE	SP	CRE	ED,ID	TD	7/5/2027
2021 PO4038385248	F	4	40 BRO	SP	CCA		V	7/6/2027



2021 PO4041085218	F	5	45 BRO	SP	CRE		V	7/7/2027
2021 PO4040185218	F	4	40 BRO	SP	CRE		V	7/8/2027
2021 PO8866008220	F	4	40 OTH	SP	CRE		V	7/9/2027
2021 PO8867008119	F	2	50 OTH	SP	CCA		V	7/10/2027
2021 PO8868207990	F	3	45 OTH	SP	CCA		V	7/11/2027
2021 PO8859008003	KU	6	30 OTH	SP	CCA		V	7/12/2027
2021 PO8903307946	F	3	45 OTH	SP	CCA		V	7/13/2027
2021 PO8904007885	KU	6	30 OTH	SP	A	ID,SRS	TD	7/14/2027
2021 PO5101058929	KU	2	50 BRN	SP	CRE	ID	BD	7/15/2027
2021 PO5083558742	KU	2	50 BRN	SP	CRE	ID	BD	7/16/2027
2021 PO4039085219	F	4	40 BRO	SP	CCA		V	7/17/2027
2021 PO4038085220	F	4	40 BRO	SP	CRE		V	7/18/2027
2021 PO4036685235	F	4	40 BRO	SP	A		V	7/19/2027
2021 PO4036585221	F	4	40 BRO	SP	CCA		V	7/20/2027
2021 PO4036685205	F	4	40 BRO	SP	CRE		V	7/21/2027
2021 PO4122685178	LGE	3	50 ACE	SP	CRE	ED,ID	TD	7/22/2027
2021 PO4036385193	F	4	40 BRO	SP	CRE		V	7/23/2027
2021 PO4039385191	F	4	40 BRO	SP	A		V	7/24/2027
2021 PO4040585190	F	3	45 BRO	SP	CCA		V	7/25/2027
2021 PO4038485192	F	4	40 BRO	SP	CRE		V	7/26/2027
2021 PO4037685063	F	4	40 BRO	SP	CRE		V	7/27/2027
2021 PO5096140977	KU	3	45 BRO	SP	CCA		V	7/28/2027
2021 PO5116740863	KU	3	45 BRO	SP	CCA		V	7/29/2027
2021 PO5118740849	KU	3	45 BRO	SP	CCA		V	7/30/2027
2021 PO4125185176	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD	7/31/2027
2021 PO4124385176	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD	8/1/2027
2021 PO4124085186	LGE	4	40 ACE	SP	A	ED,HH,ID	TD	8/2/2027
2021 PO4060185280	F	4	35 ACE	SP	CRE		V	8/3/2027
2021 PO4062185285	F	4	35 ACE	SP	CRE		V	8/4/2027
2021 PO4053185260	LGE	4	25 ACE	SP	CRE	ED,ID	TD	8/5/2027
2021 PO4061485316	F	4	35 ACE	SP	CRE		V	8/6/2027
2021 PO3974985099	LGE	3	55 ACE	SP	CRE	ED,ID,IP	TD	8/7/2027
2021 PO4038785062	F	4	40 BRO	SP	CRE		V	8/8/2027
2021 PO4040385061	F	4	40 BRO	SP	CRE		V	8/9/2027
2021 PO4042085060	F	4	40 BRO	SP	CCA		V	8/10/2027
2021 PO4043685060	F	4	45 BRO	SP	CRE		V	8/11/2027
2021 PO5578457129	KU	3	40 BRN	SP	CRE		B	8/12/2027
2021 PO7878864250	F	3	45 BRO	SP	CCA		V	8/13/2027
2021 PO4072685256	F	4	45 BRO	SP	CRE		V	8/14/2027
2021 PO4071585245	LGE	4	55 BRO	SP	CRE	HH,ID	BD	8/15/2027
2021 PO4049584893	F	4	40 ACE	SP	CRE		V	8/16/2027
2021 PO4049784896	LGE	4	30 ACE	SP	CCA		V	8/17/2027
2021 PO4048384898	F	4	40 ACE	SP	CCA		V	8/18/2027
2021 PO4047184903	F	4	40 ACE	SP	CCA		V	8/19/2027
2021 PO4047384906	F	4	25 ACE	SP	P		V	8/20/2027
2021 PO7616060878	LGE	3	45 ACE	SP	CCA		V	8/21/2027
2021 PO3968186479	LGE	4	35 ACE	SP	A	ED,ID	TD	8/22/2027
2021 PO3967686484	LGE	4	40 ACE	SP	CRE	ED,HH,ID	TD	8/23/2027
2021 PO3891385537	LGE	3	50 ACE	SP	P	ED,ID	TD	8/24/2027
2021 PO3891385535	LGE	3	50 ACE	SP	P	ED,ID	TD	8/25/2027
2021 PO4070885237	LGE	4	45 BRO	SP	CRE		V	8/26/2027
2021 PO4070785237	LGE	4	30 BRO	SP	A	ED,ID	BD	8/27/2027
2021 PO4071985227	LGE	5	25 BRO	SP	CCA		V	8/28/2027
2021 PO7890263995	LGE	5	35 BRO	SP	CCA		V	8/29/2027

2021 PO7867463776	LGE	4	30 BRO	SP	CCA		V	8/30/2027
2021 PO4072185205	LGE	3	45 BRO	SP	CRE	ED,ID	TD	8/31/2027
2021 PO7888063722	LGE	5	35 BRO	SP	CCA		V	9/1/2027
2021 PO5332957055	KU	4	40 BRN	SP	CRE	ID	TD	9/2/2027
2021 PO5325957163	KU	4	40 BRN	SP	CRE	ID	TD	9/3/2027
2021 PO5308556893	KU	4	40 BRN	SP	CRE	ID,IP	BD	9/4/2027
2021 PO4869139686	KU	2	45 UNK	SP	CRE	ED,ID	TX RR	9/5/2027
2021 PO4882339620	KU	2	45 ACW	SP	CRE	ID	TD	9/6/2027
2021 PO4045984907	F	1	50 ACE	SP	CCA		V	9/7/2027
2021 PO4045984910	LGE	4	40 ACE	SP	P	ED,ID	BD	9/8/2027
2021 PO4046084885	F	4	40 ACE	SP	P	ED,ID	BD	9/9/2027
2021 PO3971886514	LGE	4	40 ACE	SP	CRE	ED,ID,RB	BX RP2	9/10/2027
2021 PO3971486505	LGE	4	45 ACE	SP	CRE	ED,ID	BD	9/11/2027
2021 PO4044384890	LGE	4	45 ACE	SP	P	ED,ID	BD	9/12/2027
2021 PO4046084924	LGE	4	35 ACE	SP	P	ED,ID	BD	9/13/2027
2021 PO3889585546	LGE	3	50 ACE	SP	P	ED,ID	BD	9/14/2027
2021 PO3889485547	LGE	3	50 ACE	SP	CCA		V	9/15/2027
2021 PO3889285548	LGE	3	50 ACE	SP	CCA		V	9/16/2027
2021 PO3889585549c	KU	4	40 ACE	SP	P	ED,ID	BD	9/17/2027
2021 PO3889585549b	KU	1	50 ACE	SP	CCA		V	9/18/2027
2021 PO3889585549a	KU	1	50 ACE	SP	CCA		V	9/19/2027
2021 PO3889585549	LGE	1	50 ACE	SP	CCA		V	9/20/2027
2021 PO4043184866	LGE	4	40 ACE	SP	P	ED,ID	BD	9/21/2027
2021 PO3970886495	LGE	4	40 ACE	SP	P	ED,ID	TD	9/22/2027
2021 PO3970286482	LGE	3	45 ACE	SP	CCA		V	9/23/2027
2021 PO4041184883	LGE	4	35 ACE	SP	P	ED,ID	BD	9/24/2027
2021 PO4042584882	LGE	4	40 ACE	SP	P	ED,ID	BD	9/25/2027
2021 PO4043084875	LGE	4	40 ACE	SP	P	ED,ID	BD	9/26/2027
2021 PO4042984892	LGE	4	40 ACE	SP	CCA	ED,ID	BD	9/27/2027
2021 PO4042784907	LGE	4	40 ACE	SP	A	ED,ID	BD	9/28/2027
2021 PO4042884936	F	4	35 ACE	SP	A		V	9/29/2027
2021 PO3888585546	KU	4	35 ACE	SP	CCA		V	9/30/2027
2021 PO7832063824	LGE	3	45 BRO	SP	CCA		V	10/1/2027
2021 PO4067685199	LGE	4	45 BRO	SP	CCA		V	10/2/2027
2021 PO4067285193	LGE	3	45 BRO	SP	CRE	ED,ID	BD	10/3/2027
2021 PO4067085190	LGE	3	45 BRO	SP	CCA		V	10/4/2027
2021 PO3977586434	LGE	1	55 ACE	SP	CCA		V	10/5/2027
2021 PO9933880427	KU	2	55 OTH	SP	CRE		V	10/6/2027
2021 PO9914779729	KU	3	40 OTH	SP	CRE		V	10/7/2027
2021 PO9904879370	KU	3	40 OTH	SP	CRE		V	10/8/2027
2021 PO9890678874	KU	3	50 OTH	SP	CCA		V	10/9/2027
2021 PO9885478661	KU	3	45 OTH	SP	CCA		V	10/10/2027
2021 PO9876778343	KU	4	45 OTH	SP	CRE		V	10/11/2027
2021 PO3886285501	LGE	1	85 ACE	SP	P	ED,ID	TD	10/12/2027
2021 PO3977986426	LGE	4	40 ACE	SP	CRE	ID	BD	10/13/2027
2021 PO3978986425	LGE	4	40 ACE	SP	CRE	ED,ID	TD	10/14/2027
2021 PO3981086420	LGE	4	30 ACE	SP	CCA		V	10/15/2027
2021 PO3980386417	LGE	4	40 ACE	SP	A	ED,ID	TD	10/16/2027
2021 PO3981386406	LGE	4	30 ACE	SP	CCA	ED,HH,ID	TD	10/17/2027
2021 PO3981786409	LGE	4	40 ACE	SP	A	ED,ID,RB	TD	10/18/2027
2021 PO3982786399	LGE	4	30 ACE	SP	CRE	ID	TD	10/19/2027
2021 PO3982886403	LGE	4	40 ACE	SP	CCA		V	10/20/2027
2021 PO4066585185	LGE	3	45 BRO	SP	CCA		V	10/21/2027
2021 PO4066285179	LGE	4	45 BRO	SP	CCA		V	10/22/2027

2021 PO4065385166	LGE	3	45 BRO	SP	CCA			V	10/23/2027	
2021 PO4064785157	LGE	4	45 BRO	SP	CCA			V	10/24/2027	
2021 PO4064085147	LGE	4	40 BRO	SP	CRE		ED,ID	BD	10/25/2027	
2021 PO4866239615	KU	2	45 UNK	SP	CRE		ID	BD	10/26/2027	
2021 PO4886339601	KU	3	45 UNK	SP	CCA			B	10/27/2027	
2021 PO4896239553	KU	3	45 UNK	SP	CRE		ID	BD	10/28/2027	
2021 PO4907339700	KU	3	45 ACW	SP	CRE		ID	TD	10/29/2027	
2021 PO6076167131	LGE	1	50 ACE	SP	CCA			V	10/30/2027	
2021 PO6097467192	LGE	1	50 ACE	SP	CCA			V	10/31/2027	
2021 PO3898085543	LGE	1	50 ACE	SP	CCA			V	11/1/2027	
2021 PO3898185543	LGE	3	45 ACE	SP	CCA			V	11/2/2027	
2021 PO6077467179	LGE	2	55 ACE	SP	CCA			V	11/3/2027	
2021 PO3893185571	LGE	1	70 ACE	SP	P		ED,ID	BD	11/4/2027	
2021 PO4063385137	LGE	3	45 BRO	SP	CCA			V	11/5/2027	
2021 PO4062685127	LGE	3	45 BRO	SP	CCA			V	11/6/2027	
2021 PO4061985116	LGE	5	45 BRO	SP	CRE		ED,ID	BD	11/7/2027	
2021 PO3890185588a	KU	1	50 ACE	SP	CCA			V	11/8/2027	
2021 PO4062885105	LGE	4	40 BRO	SP	CRE		ED,ID	BD	11/9/2027	
2021 PO3883885618	LGE	4	35 ACE	SP	P		ED,ID	BD	11/10/2027	
2021 PO4060985101	LGE	4	45 BRO	SP	CRE		ED,ID	TD	11/11/2027	
2021 PO4059785084	F	4	45 BRO	SP	CRE			V	11/12/2027	
2021 PO3884385622	LGE	4	45 ACE	SP	P			V	11/13/2027	
2021 PO3885185610b	KU	4	45 ACE	SP	P		ED,ID	TD	11/14/2027	
2021 PO5300757007	KU	4	40 BRN	SP	CRE		ID	TD	11/15/2027	
2021 PO5290557042	KU	6	30 BRN	SP	CRE		ID	TD	11/16/2027	
2021 PO5249056909	KU	6	30 BRN	SP	CRE		ID,IP	TD	11/17/2027	
2021 PO5231856824	KU	6	30 BRN	SP	CCA			V	11/18/2027	
2021 PO5262856585	KU	4	40 BRN	SP	CRE		ID	TD	11/19/2027	
2021 PO4056885034	LGE	4	45 BRO	SP	CRE		ED,ID	BD	11/20/2027	
2021 PO4056485024	LGE	3	50 BRO	SP	CCA			V	11/21/2027	
2021 PO4056085015	LGE	4	45 BRO	SP	CRE		ED,ID	TD	11/22/2027	
2021 PO3885485534	LGE	4	40 ACE	SP	CRE		ED,ID,IP	BD	11/23/2027	
2021 PO5987366831a	KU	5	35 ACE	SP	P		ED,ID	BD	11/24/2027	
2021 PO5987366831	LGE	3	45 ACE	SP	P		ED,ID	BD	11/25/2027	
2021 PO9856077586	KU	4	50 OTH	SP	CRE		ID,IP	TD	11/26/2027	
2021 PO4912239717	KU	3	45 UNK	SP	CRE		ID	TD	11/27/2027	
2021 PO4898439480	KU	3	45 UNK	SP	CRE		ID	BD	11/28/2027	
2021 PO7705261810	LGE	3	45 BRO	SP	CCA			V	11/29/2027	
2021 PO4050384902	F	4	40 ACE	SP	CRE			V	11/30/2027	
2021 PO6007466822	LGE	4	30 ACE	SP	P		ED,ID	BD	12/1/2027	
2021 PO5999666615	LGE	4	40 ACE	SP	CRE		ED,ID	BD	12/2/2027	
2021 PO3886185513	LGE	4	40 ACE	SP	P		ED,ID	BD	12/3/2027	
2021 PO6008966557	LGE	3	45 ACE	SP	CCA			V	12/4/2027	
2021 PO9846077224	KU	4	40 OTH	SP	CRE		ID,IP	TD	12/5/2027	
2021 PO9834876814	KU	4	40 OTH	SP	CRE		ID,IP	TD	12/6/2027	
2021 PO4900539531	KU	3	45 UNK	SP	CRE		ID	BD	12/7/2027	
2021 PO3986386383	LGE	4	40 ACE	SP	P		ID	TD	12/8/2027	
2021 PO3987186379	LGE	4	40 ACE	SP	P		ID	TD	12/9/2027	
2021 PO3884785496	LGE	3	60 ACE	SP	CRE		ED,ID	TD	12/10/2027	
2021 PO4052584950	F	4	35 BRO	SP	CRE			V	12/11/2027	
2021 PO4052484959	F	4	40 BRO	SP	CCA			V	12/12/2027	
2021 PO4931839638	KU	3	45 UNK	SP	CRE		ID	BX	RR	12/13/2027
2021 PO4979538848	KU	3	45 UNK	SP	CRE		HH,ID	BX	PX	12/14/2027
2021 PO4982338915	KU	4	40 UNK	SP	CRE		ED,EP,ID	BX	RP2	12/15/2027

2021 PO4946839328	KU	3	45 BRO	SP	CCA		V	12/16/2027
2021 PO4927538881	KU	3	45 BRO	SP	CCA		V	12/17/2027
2021 PO4052884970	F	3	45 BRO	SP	CCA		V	12/18/2027
2021 PO4053484982	F	3	45 BRO	SP	CCA		V	12/19/2027
2021 PO4053784991	F	4	40 BRO	SP	CRE		V	12/20/2027
2021 PO1976951138	F	3	45 BRO	SP	CCA		V	12/21/2027
2021 PO4054885016	F	3	50 BRO	SP	CRE		V	12/22/2027
2021 PO4051585030	F	3	45 BRO	SP	CCA		V	12/23/2027
2021 PO7825168047	KU	3	45 ACE	SP	CRE	ED,ID	TD	12/24/2027
2021 PO7811668005	KU	2	45 ACE	SP	CCA		V	12/25/2027
2021 PO7800967975	KU	4	40 ACE	SP	CCA	ED	TD	12/26/2027
2021 PO5640126961	KU	4	40 UNK	SP	CRE		B	12/27/2027
2021 PO5634026958	KU	5	30 UNK	SP	CRE		B	12/28/2027
2021 PO5632427043	KU	6	30 UNK	SP	CRE		B	12/29/2027
2021 PO5630027091	KU	6	30 UNK	SP	CRE		B	12/30/2027
2021 PO5628227175	KU	5	35 UNK	SP	CRE		B	12/31/2027
2021 PO5627427228	KU	6	30 UNK	SP	CRE		B	1/1/2028
2021 PO5730627439	F	3	45 UNK	SP	CCA		V	1/2/2028
2021 PO1758594310	KU	3	45 KOP	SP	CCA		T	1/3/2028
2021 PO1740394233	KU	3	45 BRO	SP	CCA		V	1/4/2028
2021 PO1941594654	KU	5	35 BRN	SP	CCA		V	1/5/2028
2021 PO5503925926	KU	5	35 BRN	SP	CRE		B	1/6/2028
2021 PO5493926013	KU	4	45 BRN	SP	CCA		V	1/7/2028
2021 PO5502625709	KU	4	40 BRN	SP	CRE		B	1/8/2028
2021 PO5499825665	KU	4	40 BRN	SP	CRE		B	1/9/2028
2021 PO3973683727	F	4	40 BRO	SP	CRE		V	1/10/2028
2021 PO3972383727	F	4	40 BRO	SP	A		V	1/11/2028
2021 PO3181681503B	KU	6	30 BRO	DF	CRE	ED,ID	TD	1/12/2028
2021 PO3181681503A	KU	3	40 BRO	SP	S		V	1/13/2028
2021 PO3208181582	KU	6	30 BRO	SP	S	ED	T	1/14/2028
2021 PO5673027639	KU	3	45 BRN	SP	CRE		B	1/15/2028
2021 PO4063384350	LGE	3	45 BRO	SP	CCA		V	1/16/2028
2021 PO4063984365	LGE	4	35 BRO	SP	P	ED,ID	BD	1/17/2028
2021 PO5684527329	KU	2	40 UNK	SP	CRE		B	1/18/2028
2021 PO1883593071	KU	4	45 UNK	SP	CRE	ID	TD	1/19/2028
2021 PO7617268638	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	1/20/2028
2021 PO5669627036	KU	4	40 UNK	SP	CRE	ID,RB	BX PX	1/21/2028
2021 PO7610368874	KU	3	55 ACE	SP	CRE	ED,ID	BD	1/22/2028
2021 PO7601368847	KU	3	45 ACE	SP	CRE	ED,ID	BD	1/23/2028
2021 PO5677827197	KU	2	40 UNK	SP	CRE	ID,RB	BX RP3	1/24/2028
2021 PO5673127104	KU	4	40 UNK	SP	CRE	ID,RB	BX RP3	1/25/2028
2021 PO5657327009	KU	4	40 UNK	SP	CRE		T	1/26/2028
2021 PO5666126959	KU	4	40 UNK	SP	CCA		V	1/27/2028
2021 PO5654126857	KU	4	40 UNK	SP	CRE		B	1/28/2028
2021 PO5662626899	KU	3	45 UNK	SP	CCA		V	1/29/2028
2021 PO1960492677	KU	3	45 BRO	SP	CCA		V	1/30/2028
2021 PO1929592339	KU	3	45 BRO	SP	CCA		V	1/31/2028
2021 PO1934292019	KU	4	40 UNK	SP	CRE	ID	TD	2/1/2028
2021 PO3241882390	KU	3	45 BRO	SP	S		V	2/2/2028
2021 PO3247082244	F	4	40 BRO	SP	P		V	2/3/2028
2021 PO3265582244	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/4/2028
2021 PO3980583723	F	4	40 BRO	SP	A		V	2/5/2028
2021 PO3979383724	F	4	40 BRO	SP	CRE	HH,ID,IP,RB	VX RP1	2/6/2028
2021 PO1990394720	KU	5	35 BRN	SP	CCA		V	2/7/2028

2021 PO1849095177	F	4	40 UNK	SP	P		V			2/8/2028
2021 PO1826295314	KU	6	30 UNK	SP	CRE	ID	TD			2/9/2028
2021 PO1826695170	KU	4	45 UNK	SP	CRE	ID	TD			2/10/2028
2021 PO5518426294	KU	4	40 BRN	SP	CCA		V			2/11/2028
2021 PO5522426295	KU	3	50 BRN	SP	CCA		V			2/12/2028
2021 PO5521626400	KU	4	40 BRN	ST	CCA		V			2/13/2028
2021 PO5531226185	KU	3	50 BRN	SP	CCA		V			2/14/2028
2021 PO3977783750	F	3	45 BRO	SP	CCA		V			2/15/2028
2021 PO3977683737	F	4	40 BRO	SP	CRE		V			2/16/2028
2021 PO4050784359	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP,RB,SRC	TX		RR	2/17/2028
2021 PO4049484365	LGE	4	40 BRO	SP	P	ED,EP,ID,IP	TD			2/18/2028
2021 PO4047984368	LGE	2	45 BRO	SP	CCA		V			2/19/2028
2021 PO4065584337	LGE	3	45 BRO	SP	CCA		V			2/20/2028
2021 PO4064584345	LGE	3	45 BRO	SP	CCA		V			2/21/2028
2021 PO5508926392	KU	2	70 BRN	SP	CRE		B			2/22/2028
2021 PO5504126388	KU	2	50 BRN	SP	CRE		B			2/23/2028
2021 PO3977983725	F	3	45 BRO	SP	A		V			2/24/2028
2021 PO3976683725	F	4	40 BRO	SP	CRE		V			2/25/2028
2021 PO7835069014	KU	6	30 ACE	SP	CRE	ED,ID	TD			2/26/2028
2021 PO3975583721	LGE	4	35 BRO	SP	CCA		T			2/27/2028
2021 PO5483126287	KU	4	40 BRN	SP	CRE		B			2/28/2028
2021 PO5511226393	KU	2	50 BRN	ST	CCA		V			2/29/2028
2021 PO5473926367	KU	1	70 BRN	ST	CCA		V			3/1/2028
2021 PO5492026380	KU	2	70 BRN	ST	CCA		V			3/2/2028
2021 PO3236681943	KU	2	55 BRO	SP	CRE	ED,ID	TD			3/3/2028
2021 PO3250682090	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD			3/4/2028
2021 PO7778768860	KU	4	40 ACE	SP	CCA		V			3/5/2028
2021 PO5489726178	KU	4	45 BRN	SP	CCA		V			3/6/2028
2021 PO5489026191	KU	3	45 BRN	SP	CCA		V			3/7/2028
2021 PO7855369171	KU	5	35 ACE	SP	CRE	ED,ID	TD			3/8/2028
2021 PO3975383730	F	4	30 BRO	SP	CRE		V			3/9/2028
2021 PO3975283726	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX		RP1	3/10/2028
2021 PO5496825910	KU	2	45 BRN	SP	CRE		B			3/11/2028
2021 PO4004383480	LGE	4	35 BRO	SP	A	ED,ID,IP	TD			3/12/2028
2021 PO4003483492	LGE	4	40 BRO	SP	CCA		V			3/13/2028
2021 PO1728494066	KU	3	45 BRO	SP	CCA		V			3/14/2028
2021 PO1907892636	KU	3	45 BRO	SP	CCA		V			3/15/2028
2021 PO7791167947	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX		RP1	3/16/2028
2021 PO4004783467	LGE	4	35 BRO	SP	A	ED,ID	TD			3/17/2028
2021 PO7776167956	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD			3/18/2028
2021 PO7777867910	KU	3	45 ACE	SP	CRE	ED,ID	TD			3/19/2028
2021 PO7646067708	KU	3	50 ACE	SP	CRE	ED,ID	BD			3/20/2028
2021 PO4003883460	LGE	4	30 BRO	SP	A	ED,ID,IP	TD			3/21/2028
2021 PO4004083454	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD			3/22/2028
2021 PO5692927493	KU	4	40 UNK	SP	CRE	ID,RB	BX		PX	3/23/2028
2021 PO5686927575	KU	2	45 UNK	SP	CRE		B			3/24/2028
2021 PO5694727537	KU	H1	85 UNK	SP	CRE		B			3/25/2028
2021 PO5682127597	F	3	45 UNK	SP	CCA		V			3/26/2028
2021 PO569927591	F	4	40 UNK	SP	CRE		V			3/27/2028
2021 PO4063684406	LGE	4	40 BRO	SP	P	ED,ID	TD			3/28/2028
2021 PO4064384408	LGE	4	30 BRO	SP	P	ED,ID	TD			3/29/2028
2021 PO4065084405	LGE	4	40 BRO	SP	P	ED,ID	BD			3/30/2028
2021 PO4060884384	LGE	4	35 BRO	SP	P	ED,ID	TD			3/31/2028
2021 PO4060884397	LGE	4	35 BRO	SP	CCA	ED,ID,SR	TD			4/1/2028

2021 PO4059784405	LGE	4	30 BRO	SP	P	ED,ID	TD	4/2/2028
2021 PO4060184407	LGE	3	45 BRO	SP	CCA		V	4/3/2028
2021 PO3139481748	KU	6	35 BRO	SP	CRE	ED,ID	TD	4/4/2028
2021 PO3128781752	KU	6	30 BRO	SP	S		V	4/5/2028
2021 PO3137981923	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/6/2028
2021 PO3124981696	KU	6	30 BRO	SP	S		V	4/7/2028
2021 PO3138381888	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/8/2028
2021 PO3114381749	KU	6	30 BRO	SP	S		V	4/9/2028
2021 PO5708027550	F	4	40 UNK	SP	CRE	ID,RB	VX PX	4/10/2028
2021 PO5707727468	KU	2	45 UNK	SP	CRE		B	4/11/2028
2021 PO5722427396	KU	H1	85 UNK	SP	CRE		B	4/12/2028
2021 PO5728227366	KU	3	45 UNK	SP	CCA		V	4/13/2028
2021 PO7638667945	KU	3	45 ACE	SP	CRE	ED,ID	BD	4/14/2028
2021 PO7631668176	KU	4	45 ACE	SP	CRE	ED,ID	BD	4/15/2028
2021 PO7624368411	KU	4	45 ACE	SP	CCA		V	4/16/2028
2021 PO1917892971	KU	4	40 UNK	SP	P		V	4/17/2028
2021 PO1858493188	KU	3	45 BRN	SP	CCA		V	4/18/2028
2021 PO1971094772	KU	4	40 BRN	SP	CRE	ID	TD	4/19/2028
2021 PO5273283256	KU	4	45 BRN	SP	CRE	ID,IP	TD	4/20/2028
2021 PO5301283076	KU	4	40 BRN	SP	CRE	ID	TD	4/21/2028
2021 PO5247783444	KU	4	40 BRN	SP	CCA		V	4/22/2028
2021 PO5235783444	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/23/2028
2021 PO5245783317	F	5	35 BRN	SP	CCA		V	4/24/2028
2021 PO5275188139	KU	4	40 BRN	SP	CRE	ID	TD	4/25/2028
2021 PO5260688529	KU	4	40 BRN	SP	CRE	ID	TD	4/26/2028
2021 PO5247888968	KU	4	40 BRN	SP	CRE	ID	TD	4/27/2028
2021 PO5237789290	KU	4	40 BRN	SP	CCA		V	4/28/2028
2021 PO5287288937	KU	4	40 BRN	SP	CRE	ID	TD	4/29/2028
2021 PO3988484466	F	4	40 ACE	SP	CRE		V	4/30/2028
2021 PO3987084467	F	4	40 ACE	SP	CRE		V	5/1/2028
2021 PO5420728354	KU	3	45 BRN	SP	CRE		B	5/2/2028
2021 PO5425728568	KU	3	45 BRN	SP	CRE		B	5/3/2028
2021 PO5385328933	KU	2	50 BRN	SP	CCA		V	5/4/2028
2021 PO5386928846	KU	6	30 BRN	UN	CCA		V	5/5/2028
2021 PO4047683326	F	4	30 BRO	SP	CRE		V	5/6/2028
2021 PO4047583335	F	3	45 BRO	SP	CCA		V	5/7/2028
2021 PO4043883352	F	4	40 BRO	SP	CRE		V	5/8/2028
2021 PO2030492154	KU	4	40 UNK	SP	P	ID	TD	5/9/2028
2021 PO4046583307	F	4	40 BRO	SP	A		V	5/10/2028
2021 PO5385828736	KU	3	45 BRN	SP	CRE		B	5/11/2028
2021 PO5386728754	KU	3	45 BRN	SP	CRE		B	5/12/2028
2021 PO5387428798	KU	5	35 BRN	SP	CRE		T	5/13/2028
2021 PO5380428766	KU	6	30 BRN	SP	CRE		B	5/14/2028
2021 PO5387828807	KU	4	40 BRN	UN	CCA		V	5/15/2028
2021 PO4041984384	LGE	4	45 ACE	SP	CRE	ED	BD	5/16/2028
2021 PO4041884383	LGE	4	45 ACE	SP	CRE	ED	BD	5/17/2028
2021 PO2029492093	KU	4	40 BRO	SP	CRE	ID	TD	5/18/2028
2021 PO7993169553	KU	4	40 ACE	SP	CRE	ED,ID	BD	5/19/2028
2021 PO7974469268	KU	1	75 ACE	SP	CCA		V	5/20/2028
2021 PO4048483343	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	5/21/2028
2021 PO4042384382	LGE	3	50 ACE	SP	A	ED,HH,ID,RB	X PX	5/22/2028
2021 PO2024991849	KU	4	40 BRO	SP	CRE	ID	TD	5/23/2028
2021 PO2034391948	KU	3	45 BRO	SP	CCA		V	5/24/2028
2021 PO3982984469	F	4	40 ACE	SP	CRE		V	5/25/2028

2021	PO5390429086	KU	3	50 BRN	SP	CCA			V	5/26/2028	
2021	PO5403229010	KU	3	50 BRN	SP	CRE			B	5/27/2028	
2021	PO5403128887	KU	4	45 BRN	SP	CRE			V	5/28/2028	
2021	PO3981684470	F	4	40 ACE	SP	CRE			V	5/29/2028	
2021	PO3980384472	F	4	40 ACE	SP	CRE			V	5/30/2028	
2021	PO3978984469	F	4	40 ACE	SP	CRE			V	5/31/2028	
2021	PO4041284357	LGE	4	40 ACE	SP	CRE		ED,JP	TD	6/1/2028	
2021	PO1839693407	KU	4	40 UNK	SP	CRE		ID	BD	6/2/2028	
2021	PO1820493637	KU	3	45 KOP	SP	CRE		ID	TX	RR	6/3/2028
2021	PO7914569384	KU	6	30 ACE	SP	CCA			ED	TD	6/4/2028
2021	PO7908369386	KU	5	35 ACE	SP	CRE		ED,ID	TD	6/5/2028	
2021	PO3980484592	F	4	40 ACE	SP	P			V	6/6/2028	
2021	PO3980884599	F	4	40 ACE	SP	A			V	6/7/2028	
2021	PO3981284614	F	3	45 ACE	SP	CCA			V	6/8/2028	
2021	PO1896393921	KU	4	45 BRO	SP	P		ED,ID	BX	RP1	6/9/2028
2021	PO1853693878	KU	6	30 BRO	SP	CRE		ID	TD	6/10/2028	
2021	PO1848393828	KU	4	40 BRO	SP	CRE		ID	TD	6/11/2028	
2021	PO4041184358	LGE	3	50 ACE	SP	CCA		ED	BD	6/12/2028	
2021	PO4093784321	LGE	3	45 BRO	SP	P		ED,ID	TD	6/13/2028	
2021	PO4094584324	LGE	4	40 BRO	SP	CCA		ED,ID	TD	6/14/2028	
2021	PO4093384326	LGE	4	30 BRO	SP	P		ED,ID	BD	6/15/2028	
2021	PO4094384330	LGE	4	35 BRO	SP	P		ED,ID	TD	6/16/2028	
2021	PO5402229122	KU	3	45 BRN	SP	CCA			V	6/17/2028	
2021	PO5417929042	KU	3	45 BRN	SP	CCA			V	6/18/2028	
2021	PO5442428888	KU	3	45 BRN	SP	CRE			B	6/19/2028	
2021	PO5431128941	KU	3	45 BRN	SP	CCA			V	6/20/2028	
2021	PO5438328963	KU	6	30 BRN	SP	CCA			V	6/21/2028	
2021	PO5453728917	KU	4	40 BRN	SP	CCA			V	6/22/2028	
2021	PO3436985980	KU	4	45 BRO	SP	S			V	6/23/2028	
2021	PO3452184346	KU	4	40 BRO	SP	S			V	6/24/2028	
2021	PO3416585611	KU	4	45 BRO	SP	S			V	6/25/2028	
2021	PO3426284280	KU	4	40 BRO	SP	CRE		ED,ID	TD	6/26/2028	
2021	PO5381183881	KU	4	40 BRN	SP	CRE		ID	BD	6/27/2028	
2021	PO5352283932	KU	5	35 BRN	SP	CRE		ID	TD	6/28/2028	
2021	PO5357684008	KU	4	40 BRN	SP	CRE		ID	TD	6/29/2028	
2021	PO5339284210	KU	5	35 BRN	SP	CRE		ID	TD	6/30/2028	
2021	PO5320784294	KU	3	45 BRN	SP	CRE			V	7/1/2028	
2021	PO5328184137	KU	5	35 BRN	SP	CRE		ID	TD	7/2/2028	
2021	PO5320783990	KU	6	30 BRN	SP	CCA			V	7/3/2028	
2021	PO5307784131	KU	3	40 BRN	SP	CRE			V	7/4/2028	
2021	PO5291284112	KU	6	30 BRN	SP	CRE		ID	BD	7/5/2028	
2021	PO5296984001	KU	4	40 BRN	SP	CRE		ID	TD	7/6/2028	
2021	PO5302983945	KU	6	30 BRN	SP	CRE		ID	TD	7/7/2028	
2021	PO5265183714	KU	4	40 BRN	SP	CRE		ID	TD	7/8/2028	
2021	PO5296983864	KU	6	30 BRN	SP	CRE		ID,IP	TD	7/9/2028	
2021	PO5302283751	KU	4	45 BRN	SP	CCA			V	7/10/2028	
2021	PO5289783907	KU	4	40 BRN	SP	CCA			V	7/11/2028	
2021	PO3979284498	F	4	40 ACE	SP	CRE			V	7/12/2028	
2021	PO4042484381	LGE	4	40 ACE	SP	A		ED,ID	TD	7/13/2028	
2021	PO3984584691	F	3	40 ACE	SP	CRE			V	7/14/2028	
2021	PO3984384706	F	4	30 ACE	SP	CRE			V	7/15/2028	
2021	PO3985084704	F	3	40 ACE	SP	CRE			V	7/16/2028	
2021	PO3984984719	F	4	30 ACE	SP	CCA			V	7/17/2028	
2021	PO3985584715	F	3	35 ACE	SP	CCA			V	7/18/2028	

2021 PO4054883300	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	7/19/2028
2021 PO4055083295	F	4	40 BRO	SP	CRE		V	7/20/2028
2021 PO7876869128	KU	3	50 ACE	SP	CRE	ED,ID	TD	7/21/2028
2021 PO7880569138	KU	4	45 ACE	SP	CRE	ED,ID	BD	7/22/2028
2021 PO7885669003	KU	1	75 ACE	SP	CRE		V	7/23/2028
2021 PO7883368957	KU	3	45 ACE	SP	CRE	ED,ID	TD	7/24/2028
2021 PO7889268804	KU	3	45 ACE	SP	CRE	ED,ID	TD	7/25/2028
2021 PO7892568819	KU	4	40 ACE	SP	CRE	ED,ID	BD	7/26/2028
2021 PO7963669122	KU	5	35 ACE	SP	CCA		V	7/27/2028
2021 PO7955469007	KU	1	65 ACE	SP	CRE		V	7/28/2028
2021 PO7941168813	KU	1	75 ACE	SP	CCA		V	7/29/2028
2021 PO7928168638	KU	1	70 ACE	SP	CRE		V	7/30/2028
2021 PO7922668562	KU	4	45 ACE	SP	CCA		V	7/31/2028
2021 PO3395683812	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/1/2028
2021 PO7920868539	KU	4	45 ACE	SP	CCA		V	8/2/2028
2021 PO7810568995	KU	4	40 ACE	SP	CCA		V	8/3/2028
2021 PV3986184724	LGE	4	35 ACE	SP	CCA		V	8/4/2028
2021 PO4095884331	LGE	4	40 BRO	SP	P	ED,ID	BD	8/5/2028
2021 PO4095984339	LGE	4	30 BRO	SP	CCA	ED,ID	TD	8/6/2028
2021 PO5526028186	KU	6	30 BRN	SP	CRE	ED,ID	BX	RP3 8/7/2028
2021 PO5528028342	KU	4	40 BRN	SP	CCA		V	8/8/2028
2021 PO5546228344	F	4	40 BRN	SP	CRE		V	8/9/2028
2021 PO5531928409	F	4	40 BRN	SP	CRE		V	8/10/2028
2021 PO5518728466	F	4	40 BRN	SP	CRE		V	8/11/2028
2021 PO5508628433	KU	4	40 BRN	SP	CCA		V	8/12/2028
2021 PO5515828401	KU	4	40 BRN	SP	CCA		V	8/13/2028
2021 PO5501928462	KU	5	35 BRN	SP	CCA		V	8/14/2028
2021 PO3987683412	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	8/15/2028
2021 PO4050283360	F	5	35 BRO	SP	CCA		V	8/16/2028
2021 PO4053783295	F	3	45 BRO	SP	CCA		V	8/17/2028
2021 PO4082884264	LGE	4	40 BRO	SP	CCA		V	8/18/2028
2021 PO4083784269	LGE	4	40 BRO	SP	CCA		V	8/19/2028
2021 PO4084884276	LGE	4	40 BRO	SP	CCA		V	8/20/2028
2021 PO2169992374	KU	5	35 UNK	SP	CRE	ID	BD	8/21/2028
2021 PO3602584665	KU	5	35 BRO	SP	CRE	ED,ID	TD	8/22/2028
2021 PO5489428515	KU	4	40 BRN	SP	CRE		B	8/23/2028
2021 PO5485028534	KU	2	50 BRN	SP	CCA		V	8/24/2028
2021 PO5499828471	KU	4	40 BRN	UN	CRE		V	8/25/2028
2021 PO5511928419	KU	3	45 BRN	SP	CCA		V	8/26/2028
2021 PO4086784272	LGE	4	35 BRO	SP	P	ED,ID	TD	8/27/2028
2021 PO2371902263	F	4	40 UNK	SP	CRE		V	8/28/2028
2021 PO4174686473	LGE	4	40 BRO	SP	A	ED,ID	TD	8/29/2028
2021 PO4853302341	C	6	25 XXX	SP	CRE	ED,ID,RB	BX	RP1 8/30/2028
2021 PO3428901980	KU	4	45 UNK	SP	CRE	ID	BD	8/31/2028
2021 PO3398601816	KU	6	30 UNK	SP	CRE		V	9/1/2028
2021 PO3402301805	KU	4	40 UNK	SP	CRE		V	9/2/2028
2021 PO3383202572	KU	4	40 UNK	SP	CRE		V	9/3/2028
2021 PO3370302658	KU	4	40 UNK	SP	CRE	ID	TD	9/4/2028
2021 PO3359902760	F	4	40 UNK	SP	CRE		V	9/5/2028
2021 PO1545948781	KU	6	30 BRO	SP	CCA		V	9/6/2028
2021 PO9318773925	KU	4	40 BRO	SP	CCA		V	9/7/2028
2021 PO9118973338	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/8/2028
2021 PO9126173095	KU	3	50 BRO	SP	S		V	9/9/2028
2021 PO9113173040	F	3	45 BRO	SP	CRE		V	9/10/2028



2021 PO9102673063	KU	5	30 BRO	SP	CCA		V	9/11/2028	
2021 PO9099472985	KU	3	45 BRO	SP	CCA		V	9/12/2028	
2021 PO4102085984	LGE	4	35 ACE	SP	P	ED,ID	TD	9/13/2028	
2021 PO1559748748	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	9/14/2028	
2021 PO4842504976	KU	6	30 XXX	SP	CRE	ED,ID	TD	9/15/2028	
2021 PO4853905063	KU	6	30 BRN	SP	CCA		V	9/16/2028	
2021 PO1650446161	KU	4	40 BRO	SP	CRE	ED,EP,ID,MD	TD	9/17/2028	
2021 PO1668545891	KU	4	40 BRO	SP	CCA		V	9/18/2028	
2021 PO1698145475	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	9/19/2028	
2021 PO4101886208	LGE	4	40 ACE	SP	CCA		V	9/20/2028	
2021 PO4099086210	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	9/21/2028	
2021 PO4919004188	F	4	40 XXX	SP	CRE		V	9/22/2028	
2021 PO4910804251	F	3	50 XXX	SP	P		V	9/23/2028	
2021 PO4906304434	KU	6	30 XXX	SP	CRE	ED,ID	TD	9/24/2028	
2021 PO4920704594	KU	6	30 XXX	SP	CRE	ED,ID	TD	9/25/2028	
2021 PO2008316261	KU	4	45 BRN	SP	CRE	ID,IP	TX	RR	9/26/2028
2021 PO9072372499	KU	6	30 BRO	SP	CCA		V	9/27/2028	
2021 PO9077872458	KU	3	45 BRO	SP	CRE		V	9/28/2028	
2021 PO4176986509	LGE	5	35 BRO	SP	A	ED,ID	TD	9/29/2028	
2021 PO9114672739	KU	4	40 BRO	SP	CCA		V	9/30/2028	
2021 PO9098372660	KU	4	45 BRO	SP	CRE	ED,ID	TD	10/1/2028	
2021 PO4176486510	LGE	4	35 BRO	SP	A	ED,ID	TD	10/2/2028	
2021 PO9097672468	KU	4	45 BRO	SP	CRE	ED,ID	TD	10/3/2028	
2021 PO5488504710	F	3	30E BRN	SP	P	ED,ID,RB	BX	RP2	10/4/2028
2021 PO9318274429	KU	5	35 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2	10/5/2028
2021 PO9319074109	KU	5	35 BRO	SP	CRE	ED,ID,RB	BX	RP2	10/6/2028
2021 PO3419201274	KU	4	45 UNK	SP	CRE	EP,HH,ID	BX	RP2	10/7/2028
2021 PO2489403825	KU	4	40 UNK	SP	CRE	HH,ID	BX	RP2	10/8/2028
2021 PO2487903965	KU	3	50 UNK	SP	CRE	HH,ID	BX	RP2	10/9/2028
2021 PO4817805708	F	4	40 KOP	SP	CCA		V	10/10/2028	
2021 PO4818005851	F	4	40 KOP	SP	CCA		V	10/11/2028	
2021 PO2176815727	KU	4	40 BRN	SP	CRE	ED,ID	TX	RR	10/12/2028
2021 PO2185915633	KU	4	40 BRN	SP	CCA		V	10/13/2028	
2021 PO2187615467	F	4	40 BRN	SP	CRE		V	10/14/2028	
2021 PO2215315329	KU	4	40 BRN	SP	CRE	ID	BD	10/15/2028	
2021 PO2033816316	KU	4	45 BRN	SP	CRE	ED,ID	TD	10/16/2028	
2021 PO5383204753	F	3	45 BRN	SP	CCA		V	10/17/2028	
2021 PO5362304843	F	4	40 BRN	SP	CRE		V	10/18/2028	
2021 PO3452001272	KU	4	40 UNK	SP	CCA		V	10/19/2028	
2021 PO2769209251	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/20/2028	
2021 PO2795909644	KU	4	40 BRN	SP	CCA		V	10/21/2028	
2021 PO2730309205	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/22/2028	
2021 PO5410304635	F	6	35E BRN	SP	CRE		V	10/23/2028	
2021 PO5397504691	F	4	40 BRN	SP	CRE		V	10/24/2028	
2021 PO4780605687	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	10/25/2028	
2021 PO3431901071	F	4	40 UNK	SP	CCA		V	10/26/2028	
2021 PO4799104718	KU	4	40 BRN	SP	CCA		V	10/27/2028	
2021 PO4785204563	F	4	40 XXX	SP	CRE		V	10/28/2028	
2021 PO4785904727	F	4	40 XXX	SP	CRE		V	10/29/2028	
2021 PO4781004719	F	4	40 XXX	SP	CRE		V	10/30/2028	
2021 PO2132316315	KU	4	40 BRN	SP	CRE	ED,ID	BD	10/31/2028	
2021 PO4184586565	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	11/1/2028	
2021 PO4184386556	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/2/2028	
2021 PO2752009838	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/3/2028	

2021 PO2971408406	F	4	40 BRN	SP	CRE		V	11/4/2028
2021 PO2737409613	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/5/2028
2021 PO4108386148	LGE	4	35 ACE	SP	P	ED,ID,IP	TD	11/6/2028
2021 PO4107986161	LGE	4	35 ACE	SP	P	ED,ID,IP	TD	11/7/2028
2021 PO1464048757	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/8/2028
2021 PO5464504269	KU	3	45 BRN	SP	CRE	ED,ID	TD	11/9/2028
2021 PO4137585611	LGE	4	35 BRN	SP	P	ED,ID,IP	TD	11/10/2028
2021 PV4138485615	LGE	4	30 BRN	SP	CRE	ID,IP	TD	11/11/2028
2021 PO3423901540	KU	6	30 UNK	SP	CRE	ID,IP	TD	11/12/2028
2021 PO4774805018	F	4	40 XXX	SP	CRE		V	11/13/2028
2021 PO4772005110	F	4	40 XXX	SP	CRE		V	11/14/2028
2021 PO4780605185	F	4	40 XXX	SP	CRE		V	11/15/2028
2021 PO4759604700	F	4	40 XXX	SP	CRE		V	11/16/2028
2021 PO1488948417	KU	4	40 BRO	SP	CCA	ED,EP,ID,IP,MD	TD	11/17/2028
2021 PO2140416185	KU	4	45 BRN	SP	CRE	ED,ID	TD	11/18/2028
2021 PO5446604218	F	3	40 BRN	SP	CRE		V	11/19/2028
2021 PO5457804387	F	3	40 BRN	SP	CRE		V	11/20/2028
2021 PO5453804440	F	3	40 BRN	SP	CRE		V	11/21/2028
2021 PO2963408260	F	4	40 BRN	SP	CRE		V	11/22/2028
2021 PO2895008547	F	4	40 BRN	SP	CCA		V	11/23/2028
2021 PO2944108417	F	4	40 BRN	SP	CRE		V	11/24/2028
2021 PO2941608368	F	4	40 BRN	SP	CRE		V	11/25/2028
2021 PO2917708472	F	4	40 BRN	SP	CRE		V	11/26/2028
2021 PO1501148246	KU	4	40 BRO	SP	CRE	ED,HH,ID	TD	11/27/2028
2021 PO4760705017	F	4	40 XXX	SP	CRE		V	11/28/2028
2021 PO4106486168	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	11/29/2028
2021 PO4106386160	LGE	4	40 ACE	SP	CRE	ED,ID	BD	11/30/2028
2021 PO4138485615	LGE	4	35 BRN	SP	P	RB	X PX	12/1/2028
2021 PO2076613916	KU	4	45 BRN	SP	CRE		V	12/2/2028
2021 PO2074514102	KU	4	45 BRN	SP	CCA	ED,ID	BD	12/3/2028
2021 PO2037114202	KU	2	45 BRN	SP	CRE	ID	TD	12/4/2028
2021 PO2014314089	KU	3	45 BRN	SP	CCA		V	12/5/2028
2021 PO2035614531	KU	2	45 BRN	SP	P	ID	BD	12/6/2028
2021 PO2032514832	KU	2	45 BRN	SP	P	ID	BD	12/7/2028
2021 PO2030715118	KU	2	45 BRN	SP	P	ID	BD	12/8/2028
2021 PO2018615987	KU	2	45 BRN	SP	P	ID	TD	12/9/2028
2021 PO2023515683	KU	2	45 BRN	SP	CRE	ID	TD	12/10/2028
2021 PO2026315396	KU	2	45 BRN	SP	P	ID	TD	12/11/2028
2021 PO1938316218	KU	4	45 BRN	SP	CRE	ID	TD	12/12/2028
2021 PO1931516301	F	7	20 BRN	SP	CRE		V	12/13/2028
2021 PO1944116073	KU	6	30 BRN	SP	CCA		V	12/14/2028
2021 PO1948115543	KU	6	35 BRN	SP	CRE	ID	BD	12/15/2028
2021 PO1945715667	F	4	40 BRN	SP	CRE		V	12/16/2028
2021 PO1959515548	KU	4	45 BRN	SP	CRE	ID	BD	12/17/2028
2021 PO1974415560	KU	4	45 BRN	SP	CRE		V	12/18/2028
2021 PO1977715807	KU	4	45 BRN	SP	CRE	ID	TD	12/19/2028
2021 PO1959716098	KU	4	40 BRN	SP	CRE	ID	TD	12/20/2028
2021 PO1980715998	KU	4	40 BRN	SP	CRE	ID	TD	12/21/2028
2021 PO1994516149	KU	4	40 BRN	SP	CRE	ID,IP	BD	12/22/2028
2021 PO9135672993	KU	6	30 BRO	SP	CRE		V	12/23/2028
2021 PO4176786528	LGE	4	35 BRO	SP	A	ID	TD	12/24/2028
2021 PO1513048072	KU	4	35 BRO	SP	CCA	ED,EP,HH,ID	TD	12/25/2028
2021 PO1537147713	KU	4	45 BRO	SP	CRE	ED,EP,ID	TD	12/26/2028
2021 PO5460304920	KU	3	45 BRN	SP	CCA		V	12/27/2028

2021	PO2861808648	F	4	40 BRN	SP	CRE		V		12/28/2028
2021	PO2882508629	F	4	40 BRN	SP	CCA		V		12/29/2028
2021	PO5486304670	F	3	40 BRN	SP	P		V		12/30/2028
2021	PO5474104712	F	2	50E BRN	SP	CRE		V		12/31/2028
2021	PO5465704792	F	3	40 BRN	SP	P		V		1/1/2029
2021	PO4770304899	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		1/2/2029
2021	PO2840708664	F	4	40 BRN	SP	CRE		V		1/3/2029
2021	PO3447202026	KU	5	35 UNK	SP	CRE	HH,ID	TD		1/4/2029
2021	PO2805508126	F	4	40 BRN	SP	CRE	ED,ID,RB	BX	PX	1/5/2029
2021	PO4139085597	F	3	55 BRN	SP	P		V		1/6/2029
2021	PO4139285566	F	3	45 BRN	SP	CRE		V		1/7/2029
2021	PO4139185568	F	3	45 BRN	SP	CRE		V		1/8/2029
2021	PO2815908634	F	4	40 BRN	SP	CRE		V		1/9/2029
2021	PO2814208525	F	4	40 BRN	SP	CRE		V		1/10/2029
2021	PO2810708349	F	4	40 BRN	SP	CRE		V		1/11/2029
2021	PO5491204694	F	6	35E BRN	SP	P		V		1/12/2029
2021	PO5500904523	F	7	40 BRN	SP	CRE		V		1/13/2029
2021	PO5489804646	F	4	40 BRN	SP	A		V		1/14/2029
2021	PO9311074591	KU	6	30 BRO	SP	CRE	ED,ID	BD		1/15/2029
2021	PO4177786537	LGE	4	30 BRO	SP	CRE	ID,IP	BD		1/16/2029
2021	PO8539067386	LGE	1	50 BRN	SP	CCA		V		1/17/2029
2021	PO4139385544	F	3	45 BRN	SP	CRE		V		1/18/2029
2021	PO4139785544	F	4	30 BRN	SP	CCA		V		1/19/2029
2021	PO2803608679	F	4	40 BRN	SP	CRE		V		1/20/2029
2021	PO4105186189	LGE	2	60 ACE	SP	CRE		V		1/21/2029
2021	PO4106686177	LGE	2	60 ACE	SP	CRE		V		1/22/2029
2021	PO1489549763	KU	4	40 BRO	SP	CRE	ED,ID	TD		1/23/2029
2021	PO1479349891	F	5	35 BRO	SP	CRE		V		1/24/2029
2021	PO1449250165	KU	6	30 BRO	SP	CCA		V		1/25/2029
2021	PO4781504909	KU	6	30 XXX	SP	CRE	ED,EP,ID,IP	TX	RR	1/26/2029
2021	PO2788908979	F	4	40 BRN	SP	CRE		V		1/27/2029
2021	PO2765109082	F	4	40 BRN	SP	CRE		V		1/28/2029
2021	PO1448550050	KU	3	45 BRO	SP	CCA		V		1/29/2029
2021	PO2772709377	F	4	40 BRN	SP	CRE		V		1/30/2029
2021	PO4185686534	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/31/2029
2021	PO4133385689	LGE	4	40 BRN	SP	P	ID	BD		2/1/2029
2021	PO5281905108	F	4	40 BRN	SP	CRE		V		2/2/2029
2021	PO5299705069	F	5	35 BRN	SP	P		V		2/3/2029
2021	PO5301405111	F	4	40 BRN	SP	P		V		2/4/2029
2021	PO5291805156	F	4	40 BRN	SP	CRE		V		2/5/2029
2021	PO5313905055	F	4	40 BRN	SP	CRE		V		2/6/2029
2021	PO5326305001	F	4	40 BRN	SP	CRE		V		2/7/2029
2021	PO5332804922	F	7	40 BRN	SP	CRE		V		2/8/2029
2021	PO4758104991	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	PX	2/9/2029
2021	PO9272374697	KU	5	35 BRO	SP	CRE	ED,ID	TD		2/10/2029
2021	PO9289174082	KU	4	45 BRO	SP	CRE	ED,ID	TD		2/11/2029
2021	PO9287174235	KU	4	40 BRO	SP	CRE	ED,ID	TD		2/12/2029
2021	PO5334904962	F	3	40 BRN	SP	CRE		V		2/13/2029
2021	PO5349804897	F	4	40 BRN	SP	P		V		2/14/2029
2021	PO5355104873	F	4	40 BRN	SP	CRE		V		2/15/2029
2021	PO4817205161	F	4	40 XXX	SP	CRE		V		2/16/2029
2021	PO4817405335	F	4	40 XXX	SP	CRE		V		2/17/2029
2021	PO4817605505	F	4	40 XXX	SP	CRE		V		2/18/2029
2021	PO4782805352	KU	6	30 XXX	SP	CRE	ED,ID	TX	RR	2/19/2029

2021 PO2711303039	KU	4	40 UNK	SP	CRE	ID	BD	2/20/2029
2021 PO5568303441	F	5	40 BRO	SP	P		V	2/21/2029
2021 PO4178886522	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/22/2029
2021 PO4138785427	F	3	45 BRN	SP	CCA		V	2/23/2029
2021 PO4138885427	LGE	4	40 BRN	SP	CCA		V	2/24/2029
2021 PO4140285417	F	3	45 BRN	SP	P		V	2/25/2029
2021 PO4140285428	F	3	45 BRN	SP	P		V	2/26/2029
2021 PO2911606539	KU	4	40 BRN	SP	CRE	ED,ID	BD	2/27/2029
2021 PO9082873039	KU	6	35 BRO	SP	CRE	ED,ID	TD	2/28/2029
2021 PO9074273056	KU	5	30 BRO	SP	A	ED,ID	BD	3/1/2029
2021 PO1582847092	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	3/2/2029
2021 PO4886004218	F	4	40 KOP	SP	CCA		V	3/3/2029
2021 PO4903204154	F	4	40 KOP	SP	P		V	3/4/2029
2021 PO4886604401	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/5/2029
2021 PO4142485455	LGE	4	30 BRN	SP	CCA		V	3/6/2029
2021 PO4140285442	F	3	45 BRN	SP	P		V	3/7/2029
2021 PO5570003557	F	3	40 BRO	SP	CRE	ED	V	3/8/2029
2021 PO4182886488	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/9/2029
2021 PO2888306663	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/10/2029
2021 PO4140885466	LGE	3	45 BRN	SP	CCA		V	3/11/2029
2021 PO4140085461	F	2	60 BRN	SP	CCA		V	3/12/2029
2021 PO4139585481	F	3	50 BRN	SP	P		V	3/13/2029
2021 PO4139085496	F	4	40 BRN	SP	P		V	3/14/2029
2021 PO4139385495	F	3	55 BRN	SP	CRE		V	3/15/2029
2021 PO4139285500	F	3	50 BRN	SP	CRE		V	3/16/2029
2021 PO5601504016	KU	7	35 BRO	SP	CRE	ED,ID	TD	3/17/2029
2021 PO4100186210	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/18/2029
2021 PO9156872891	KU	5	35 BRO	SP	CRE	ED,ID	BD	3/19/2029
2021 PO9133872814	KU	4	40 BRO	SP	CCA		V	3/20/2029
2021 PO1627546482	KU	4	40 BRO	SP	CRE	ID	TD	3/21/2029
2021 PO9102272835	KU	6	30 BRO	SP	A		V	3/22/2029
2021 PO1609446745	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	3/23/2029
2021 PO4139185507	F	3	50 BRN	SP	P		V	3/24/2029
2021 9079372643A	KU	3	40 BRO	SP	CRE	ED,ID	BD	3/25/2029
2021 PO4139185507-A	KU	3	45 BRN	SP	P		V	3/26/2029
2021 PO4138685520	F	3	55 BRN	SP	CRE		V	3/27/2029
2021 PO4137485555	F	4	40 BRN	SP	CCA		V	3/28/2029
2021 PO4138385533	F	4	40 BRN	SP	P		V	3/29/2029
2021 PO4137885544	F	4	40 BRN	SP	P		V	3/30/2029
2021 PO4137085567	F	4	40 BRN	SP	P		V	3/31/2029
2021 PO4138685718	LGE	3	50 BRN	SP	P	HH,SR	BX	4/1/2029
2021 PO4135485709	LGE	4	40 BRN	SP	CRE		V	4/2/2029
2021 PO4138185703	LGE	4	35 BRN	SP	CCA		V	4/3/2029
2021 PO4138785697	LGE	2	60 BRN	SP	CRE		V	4/4/2029
2021 PO8530168898	LGE	3	45 BRN	SP	CCA		V	4/5/2029
2021 PO4138685705	LGE	4	45 BRN	SP	CRE		V	4/6/2029
2021 PO9089072793	F	3	40 BRO	SP	A		V	4/7/2029
2021 PO9079372643	KU	3	45 BRO	SP	CCA		V	4/8/2029
2021 PO1653945911	KU	6	30 BRO	SP	CRE	ED,ID	TD	4/9/2029
2021 PO4186386523	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/10/2029
2021 PO4185086544	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/11/2029
2021 PO3447001916	KU	6	30 UNK	SP	CRE	ID,IP	BD	4/12/2029
2021 PO3427401289	KU	6	30 UNK	SP	CRE	ID,IP	TD	4/13/2029
2021 PO5424604566	F	5	40 BRN	SP	CRE		V	4/14/2029

2021 PO5438704505	F	6	35E	BRN	SP	CRE		V		4/15/2029
2021 PO5470304507	KU	3	45	BRN	SP	CRE	ED,ID	TD		4/16/2029
2021 PO4804005335	KU	6	30	BRN	SP	CRE	ED,ID,RB	X	PX	4/17/2029
2021 PO4801605066	KU	6	30	BRN	SP	CRE	ED,ID	TX	RR	4/18/2029
2021 PO4816605071	KU	6	30	BRN	SP	CRE		V		4/19/2029
2021 PV8510868092	LGE	4	35	BRN	SP	P	ED,ID,IP,SR	TX	RR	4/20/2029
2021 PO4136885611	LGE	4	35	BRN	SP	P	ED,ID,IP	TD		4/21/2029
2021 PO9294074185	KU	4	40	BRO	SP	CRE	ED,ID	TD		4/22/2029
2021 PO4800004881	KU	6	30	BRN	SP	CRE	ED,ID	TD		4/23/2029
2021 PO2073816227	KU	4	40	BRN	SP	CRE	ED,ID	TD		4/24/2029
2021 PO4133485782	LGE	4	40	BRN	SP	P	EP,ID,RB	TX	RR	4/25/2029
2021 PO4133285713	LGE	4	40	BRN	SP	P	ID	BD		4/26/2029
2021 PO1474849731	KU	3	45	BRO	SP	CCA		V		4/27/2029
2021 PO9191473678	KU	5	35	BRO	SP	CRE	ED,ID	TD		4/28/2029
2021 PO9201573546	F	3	45	BRO	SP	CRE		V		4/29/2029
2021 PO5555003902	KU	7	30	BRN	SP	CRE	ED,ID	TD		4/30/2029
2021 PO9213773745	F	3	45	BRO	SP	A		V		5/1/2029
2021 9267573738A	KU	5	35	BRN	SP	S		V		5/2/2029
2021 PO9238473688	KU	2	50	BRO	SP	CCA		V		5/3/2029
2021 PO9267573738	KU	4	40	BRN	SP	CRE	ED,ID	TD		5/4/2029
2021 PO5527804050	KU	7	35	BRN	SP	CCA		V		5/5/2029
2021 PO5532704258	F	6	30E	BRN	SP	CRE	ED,HH,ID,RB	BX	PX	5/6/2029
2021 PO1506149634	F	4	40	BRO	SP	CRE		V		5/7/2029
2021 PO8476105946	KU	5	35	UNK	SP	CRE	ID	BD		5/8/2029
2021 PO4168385320	LGE	7	25	ACE	SP	CRE	ED,ID	BD		5/9/2029
2021 PO4160785326	LGE	4	35	ACE	SP	CRE	ID	BD		5/10/2029
2021 PO4161085349	LGE	4	35	ACE	SP	P	ED,HH,ID	BD		5/11/2029
2021 PO4148885134	LGE	3	50	ACE	SP	CRE	ID	BD		5/12/2029
2021 PO4168485264	LGE	4	40	ACE	SP	CRE	ED,ID	BD		5/13/2029
2021 PO4165185261	LGE	7	25	ACE	SP	CRE	ED,ID	BD		5/14/2029
2021 PO5985309835	KU	5	35	ACW	SP	CRE	ED,ID	BD		5/15/2029
2021 PO8494306021	KU	4	40	UNK	SP	CRE	ID,IP	BD		5/16/2029
2021 PO8498106027	KU	4	45	UNK	SP	CRE	ID	BD		5/17/2029
2021 PO8500306025	KU	4	45	UNK	SP	CRE	ID	BD		5/18/2029
2021 PO5986610086	KU	5	35	ACW	SP	CRE	ED,ID	BD		5/19/2029
2021 PO4169685269	LGE	7	25	ACE	SP	CRE	ED,ID	BD		5/20/2029
2021 PO4169185258	LGE	4	30	ACE	SP	P	ED,ID	BD		5/21/2029
2021 PO6028310225	KU	4	40	ACW	SP	CRE	ED,ID	BD		5/22/2029
2021 PO3584459088	KU	4	40	UNK	SP	CRE		B		5/23/2029
2021 PO3586058679	KU	4	40	UNK	SP	CRE		B		5/24/2029
2021 PO4139248736	KU	4	40	BRN	SP	CRE	EP,ID,RB	X	RP1	5/25/2029
2021 PO8522607462	KU	6	30	UNK	SP	CRE	ID	TD		5/26/2029
2021 PO8502807349	KU	6	30	UNK	SP	CRE	ID,IP	TD		5/27/2029
2021 PO8489207206	KU	6	30	UNK	SP	CRE	ID,IP	TD		5/28/2029
2021 PO8616307651	KU	6	30	UNK	SP	CCA		V		5/29/2029
2021 PO8573907798	F	3	40	UNK	SP	CCA		V		5/30/2029
2021 PO8573107607	KU	5	35	UNK	SP	CCA		V		5/31/2029
2021 PO8594307637	KU	6	30	UNK	SP	CRE	ID	TD		6/1/2029
2021 PO4163785372	LGE	6	30	ACE	SP	P	ED,ID,RB	X	RP3	6/2/2029
2021 PO4163885379	LGE	4	40	ACE	SP	CRE	ED,ID,IP	TD		6/3/2029
2021 PO4163985390	LGE	4	40	ACE	SP	CRE	ED,ID,IP	TD		6/4/2029
2021 PO4161285370	LGE	4	40	ACE	SP	CRE	ID	TD		6/5/2029
2021 PO4161185363	LGE	4	40	ACE	SP	A	ED,HH,ID	BX	PX	6/6/2029
2021 PO4161185358	LGE	4	40	ACE	SP	P	ED,EP,RB	VX	PX	6/7/2029

2021 PO4160885338	LGE	4	35 ACE	SP	CRE	ID	TD		6/8/2029
2021 PO4121985215	LGE	4	40 ACE	SP	CRE	ED,ID	TD		6/9/2029
2021 PO8593507820	F	3	45 UNK	SP	CCA		V		6/10/2029
2021 PO4122348904	KU	4	40 BRN	SP	CRE	ID	TD		6/11/2029
2021 PO4128949094	KU	3	50 BRN	SP	CRE	ID	TD		6/12/2029
2021 PO4065247988	KU	4	45 BRN	SP	CRE	ID	BD		6/13/2029
2021 PO4085348253	KU	5	35 BRN	SP	CRE	ID	TD		6/14/2029
2021 PO4096848407	KU	5	35 BRN	SP	CRE	ID,IP	TD		6/15/2029
2021 PO8642607661	KU	5	30 UNK	SP	CCA		V		6/16/2029
2021 PO8608907921	F	5	35 UNK	SP	CRE		V		6/17/2029
2021 PO8609807838	F	4	40 UNK	SP	CRE		V		6/18/2029
2021 PO8611707665	F	4	40 UNK	SP	CRE		V		6/19/2029
2021 PO4122285227	LGE	4	40 ACE	SP	CRE	ED,ID,RB	BX	RR	6/20/2029
2021 PO4096185221	LGE	4	45 ACE	SP	A	ED,HH,ID,MD	BD		6/21/2029
2021 PO8613207512	F	3	45 UNK	SP	A		V		6/22/2029
2021 PO8603207506	KU	5	35 UNK	SP	CCA		V		6/23/2029
2021 PO8628007387	KU	6	30 UNK	SP	CCA		V		6/24/2029
2021 PO8626307254	KU	6	30 UNK	SP	CCA		V		6/25/2029
2021 PO8638407176	KU	6	30 UNK	SP	CCA	SRS	TD		6/26/2029
2021 PO8647507196	KU	6	30 UNK	SP	CCA		V		6/27/2029
2021 PO4100185195	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD		6/28/2029
2021 PO4103085207	LGE	4	45 ACE	SP	A	ID	BD		6/29/2029
2021 PO4102785198	LGE	4	35 ACE	SP	CCA		V		6/30/2029
2021 PO8663007212	KU	6	30 UNK	SP	CRE	ID,IP	TD		7/1/2029
2021 PO8614607378	F	4	40 UNK	SP	CRE		V		7/2/2029
2021 PO8616207241	F	3	45 UNK	SP	CCA		V		7/3/2029
2021 PO8596907098	KU	6	30 UNK	SP	CCA	SRS	TD		7/4/2029
2021 PO4102185193	LGE	3	55 ACE	SP	CRE	ED,ID	BD		7/5/2029
2021 PO4100985181	LGE	3	45 ACE	WC	CRE	ID	TD		7/6/2029
2021 PO8595607219	F	4	40 UNK	SP	CRE		V		7/7/2029
2021 PO8579206998	KU	6	30 UNK	SP	CRE	ID	BD		7/8/2029
2021 PO8570707072	KU	5	35 UNK	SP	CRE	ID,IP,SRS	TD		7/9/2029
2021 PO8612207149	KU	6	30 UNK	SP	CCA	SRS	TD		7/10/2029
2021 PO8581107204	F	3	45 UNK	SP	CCA		V		7/11/2029
2021 PO8567407189	F	3	45 UNK	SP	A		V		7/12/2029
2021 PO8535807098	KU	4	40 UNK	SP	CRE	ID	TD		7/13/2029
2021 PO4102885181	LGE	4	35 ACE	SP	A	ID	TD		7/14/2029
2021 PO4100785163	LGE	4	35 ACE	SP	CRE	HH,ID	BD		7/15/2029
2021 PO4098185197	LGE	3	50 ACE	SP	CCA	ED,EP,ID,RB,SRS	TX	RR	7/16/2029
2021 PO4098585201	LGE	4	35 ACE	SP	A	ED,HH,ID	TD		7/17/2029
2021 PO4157685296	LGE	4	35 ACE	SP	P	ID	BD		7/18/2029
2021 PO4158085307	LGE	3	50 ACE	SP	CRE	ED,ID	TD		7/19/2029
2021 PO4160585313	LGE	4	40 ACE	SP	CRE	ED,ID	TD		7/20/2029
2021 PO4159885313	LGE	4	30 ACE	SP	A	ED,HH,ID	TD		7/21/2029
2021 PO4163385346	LGE	4	35 ACE	SP	A	ID	TD		7/22/2029
2021 PO4163285334	LGE	3	45 ACE	SP	CCA		V		7/23/2029
2021 PO4163685359	LGE	4	40 ACE	SP	A	ID	TD		7/24/2029
2021 PO4163785369	LGE	5	40 ACE	SP	P	ED,ID	BD		7/25/2029
2021 PO6051009723	KU	4	40 ACW	SP	CRE	ED,HH,ID,RB,SR	X	PX	7/26/2029
2021 PO8576509051	F	4	40 UNK	SP	CRE		V		7/27/2029
2021 PO8570109024	KU	6	30 UNK	SP	CCA		V		7/28/2029
2021 PO8575808892	F	4	40 UNK	SP	CRE		V		7/29/2029
2021 PO4104885198	LGE	4	40 ACE	SP	A	ED,ID,RB	TX	RR	7/30/2029
2021 PO4104685192	LGE	2	70 ACE	SP	CCA		V		7/31/2029

2021 PO3865747360	KU	3	50 BRN	SP	CRE	ID	BD	8/1/2029
2021 PO3838947340	KU	4	45 BRN	SP	CRE	ID	BD	8/2/2029
2021 PO3931147760	KU	2	50 BRN	SP	CCA		V	8/3/2029
2021 PO4059385328	LGE	4	40E ACE	SP	CRE	ED,ID	BD	8/4/2029
2021 PO4059485336	LGE	4	40 ACE	SP	CCA	ED	V	8/5/2029
2021 PO4059485342	LGE	4	40E ACE	SP	CRE	ED,ID	BD	8/6/2029
2021 PO4011785145	F	4	35 BRO	SP	CRE		V	8/7/2029
2021 PO4010785144	F	5	30 BRO	SP	CRE	ED,ID	VX	RP3 8/8/2029
2021 PO3752267514	F	4	40 UNK	SP	P		V	8/9/2029
2021 PO4011685160	F	4	35 BRO	SP	CRE		V	8/10/2029
2021 PO4012785175	F	5	30 BRO	SP	CRE		V	8/11/2029
2021 PO4013085169	F	4	35 BRO	SP	CRE		V	8/12/2029
2021 4014085172A	F	5	30 BRO	SP	CRE		V	8/13/2029
2021 PO4014085172	F	4	35 BRO	SP	CRE		V	8/14/2029
2021 PO4015285179	F	5	30 BRO	SP	CCA		V	8/15/2029
2021 PO4015285172	F	3	45 BRO	SP	CCA		V	8/16/2029
2021 PO8572208758	F	4	40 UNK	SP	CRE		V	8/17/2029
2021 PO8560008711	KU	6	30 UNK	SP	CRE	ID,IP	TD	8/18/2029
2021 PO4153685197	LGE	2	55 ACE	SP	CRE	ED,HH,ID,RB	BX	PX 8/19/2029
2021 PO4152685184	LGE	3	45 ACE	SP	CRE	ED,ID	BD	8/20/2029
2021 PO4151885174	LGE	3	45 ACE	SP	CRE	ED,ID	BD	8/21/2029
2021 PO3914047969	KU	2	50 BRN	SP	CCA		V	8/22/2029
2021 PO3909447851	KU	4	40 BRN	SP	CCA		V	8/23/2029
2021 PO4376249305	KU	4	40 BRN	SP	CRE	ID	BD	8/24/2029
2021 PO4391449404	KU	4	40 BRN	SP	A	ID	BD	8/25/2029
2021 PO4385549495	KU	5	35 BRN	SP	CCA		V	8/26/2029
2021 PO4057285299	LGE	4	45 ACE	SP	P	ED,ID	TD	8/27/2029
2021 PO4150985162	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD	8/28/2029
2021 PO4013385212	F	4	40 BRO	SP	CCA		V	8/29/2029
2021 PO4012285207	F	4	40 BRO	SP	CRE		V	8/30/2029
2021 PO4011485198	F	4	35 BRO	SP	CRE		V	8/31/2029
2021 PO4011285204	F	4	40 BRO	SP	CRE	RB	VX	RP3 9/1/2029
2021 PO4014485217	F	3	45 BRO	SP	CCA		V	9/2/2029
2021 PO4014485224	F	3	45 BRO	SP	CCA		V	9/3/2029
2021 PO4014985227	F	4	40 BRO	SP	CRE		V	9/4/2029
2021 PO4015385217	F	4	40 BRO	SP	CRE		V	9/5/2029
2021 PO8576208675	KU	6	30 UNK	SP	CRE	ID,IP	TD	9/6/2029
2021 PO8570008622	F	4	40 UNK	SP	CRE		V	9/7/2029
2021 PO8568108492	KU	4	40 UNK	SP	CRE	HH,ID	BX	RP3 9/8/2029
2021 PO4057285304	LGE	3	45 ACE	SP	CCA		V	9/9/2029
2021 PO3748468662	KU	6	30 UNK	SP	CRE	ID	TD	9/10/2029
2021 PO4106885152	LGE	4	30 ACE	SP	CCA		V	9/11/2029
2021 PO4106785152	LGE	4	40 ACE	SP	A	ID	TD	9/12/2029
2021 PO4108685150	LGE	4	40 ACE	SP	CRE	ID	BD	9/13/2029
2021 PO4095885198	LGE	3	50 ACE	SP	CRE	ED,ID,IP	BD	9/14/2029
2021 PO4106785145	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	9/15/2029
2021 PO4015885207	F	4	40 BRO	SP	CCA		V	9/16/2029
2021 PO6059810278	KU	3	50 ACW	SP	S		V	9/17/2029
2021 PO6065110180	KU	5	35 ACW	SP	S		V	9/18/2029
2021 PO6058510183	KU	4	40 ACW	SP	CCA		V	9/19/2029
2021 PO6043710219	KU	4	45 ACW	SP	S		V	9/20/2029
2021 PO6058809861	KU	4	40 ACW	SP	CRE	ED,ID	BD	9/21/2029
2021 PO6054309797	KU	3	45 ACW	SP	S		V	9/22/2029
2021 PO4016385196	F	4	35 BRO	SP	CRE		V	9/23/2029

2021 PO4016585168	F	4	35 BRO	SP	CRE		V	9/24/2029
2021 PO4016585180	F	4	35 BRO	SP	CRE		V	9/25/2029
2021 PO7313863339	F	4	35 BRO	SP	CRE		V	9/26/2029
2021 PO4017285168	F	4	35 BRO	SP	CCA		V	9/27/2029
2021 PO4015585153	F	5	35 BRO	SP	CRE		V	9/28/2029
2021 PO4016685158	F	4	40 BRO	SP	CRE		V	9/29/2029
2021 PO4017085151	F	4	35 BRO	SP	CRE		V	9/30/2029
2021 PO4017485144	F	3	45 BRO	SP	CCA		V	10/1/2029
2021 PO4018185130	F	4	40 BRO	SP	CRE		V	10/2/2029
2021 PO4150285154	LGE	1	55 ACE	SP	CRE	ED,ID,JP	TD	10/3/2029
2021 PO4151585163	LGE	4	30 ACE	SP	CCA		V	10/4/2029
2021 PO4057385318	LGE	3	45 ACE	SP	CCA		V	10/5/2029
2021 PO4057285327	LGE	4	40 ACE	SP	CCA		V	10/6/2029
2021 PO4057485326	LGE	4	40 ACE	SP	CCA		V	10/7/2029
2021 PO4058185329	LGE	4	35E ACE	SP	CRE	ID	BD	10/8/2029
2021 PO8572808350	KU	6	30 UNK	SP	CRE	ID	TD	10/9/2029
2021 PO3766268394	KU	3	35 UNK	SP	CRE	ED,ID	BX RR	10/10/2029
2021 PO4019685119	F	5	35 BRO	SP	CRE		V	10/11/2029
2021 PO4018985117	F	4	40 BRO	SP	CRE		V	10/12/2029
2021 PO4020185103	F	5	35 BRO	SP	CRE		V	10/13/2029
2021 PO4020385087	F	4	30 BRO	SP	CRE		V	10/14/2029
2021 PO4019585099	F	4	35 BRO	SP	CRE		V	10/15/2029
2021 PO4019785086	F	4	35 BRO	SP	CRE		V	10/16/2029
2021 PO4020485073	F	5	35 BRO	SP	A		V	10/17/2029
2021 PO4019785073	F	4	35 BRO	SP	CRE		V	10/18/2029
2021 PO4020485062	LGE	4	30 BRO	SP	CCA		V	10/19/2029
2021 PO4019685062	F	5	35 BRO	SP	CRE		V	10/20/2029
2021 PO4019985030	F	4	30 BRO	SP	CCA		V	10/21/2029
2021 PO4019485050	F	5	35 BRO	SP	CRE		V	10/22/2029
2021 PO4019285031	F	5	35 BRO	SP	CRE		V	10/23/2029
2021 PO4019885018	F	4	30 BRO	SP	CCA		V	10/24/2029
2021 PO4019185017	F	5	35 BRO	SP	CRE		V	10/25/2029
2021 PO4407044803	KU	4	40 BRN	SP	CRE	ID	BD	10/26/2029
2021 PO4147585118	LGE	3	45 ACE	SP	P	ED,ID	BD	10/27/2029
2021 PO3770468313	KU	4	40 INP	SP	CRE	ED	TD	10/28/2029
2021 PO3796568560	KU	4	40 KOP	SP	CRE	ID	BD	10/29/2029
2021 PO3764167153	KU	6	30 UNK	SP	CRE	ED	BD	10/30/2029
2021 PO4422744583	KU	5	35 BRN	SP	CRE	ID	TD	10/31/2029
2021 PO4448444571	KU	5	35 BRN	SP	CRE	ID	TD	11/1/2029
2021 PO4303844326	KU	3	40 BRN	SP	CRE	ID	BD	11/2/2029
2021 PO4018785006	F	4	35 BRO	SP	CRE		V	11/3/2029
2021 PO4018585002	F	4	40 BRO	SP	CRE		V	11/4/2029
2021 PO4019385002	F	4	30 BRO	SP	CCA		V	11/5/2029
2021 PO4147985115	LGE	4	30 ACE	SP	P	ED,ID	BD	11/6/2029
2021 PO4147685110	LGE	4	35 ACE	SP	P	ED,ID	BD	11/7/2029
2021 PO4147185112	LGE	3	50 ACE	SP	P	ED,JP	BD	11/8/2029
2021 PO4146585106	LGE	3	50 ACE	SP	P	ED,ID	TD	11/9/2029
2021 PO4145685092	LGE	3	50 ACE	SP	P	ED,ID	TD	11/10/2029
2021 PO8222563435	LGE	3	45 ACE	SP	CCA		V	11/11/2029
2021 PO8229563435	LGE	4	35 ACE	SP	CCA		V	11/12/2029
2021 PO4058185322	LGE	4	40E ACE	SP	CRE	ED	BD	11/13/2029
2021 PO4058085314	LGE	3	40E ACE	SP	CRE	ED	BD	11/14/2029
2021 PO4058185299	LGE	2	70 ACE	SP	CRE		V	11/15/2029
2021 PO4059785298	LGE	2	70 ACE	SP	CRE		V	11/16/2029



2021 PO4063685284	LGE	2	80 ACE	SP	CRE			V	11/17/2029
2021 PO4062585289	LGE	2	75 ACE	SP	CRE			V	11/18/2029
2021 PO4005685357	LGE	3	45 ACE	SP	CCA			V	11/19/2029
2021 PO5824010324	KU	4	40 ACW	SP	CRE	ED,EP,HH,ID,IP,RB		X	11/20/2029
2021 PO5846610279	KU	3	45 ACW	SP	S			V	11/21/2029
2021 PO4141785096	LGE	2	55 ACE	SP	CCA			V	11/22/2029
2021 PO4052385307	LGE	5	30 ACE	SP	P	ED		TD	11/23/2029
2021 PO4052485303	LGE	4	45 ACE	SP	A	ED,ID		TD	11/24/2029
2021 PO4051985302	LGE	2	35E ACE	SP	CRE			V	11/25/2029
2021 PO8668607406	KU	5	35 UNK	SP	CRE			V	11/26/2029
2021 PO8671207228	F	4	40 UNK	SP	CRE			V	11/27/2029
2021 PO7319561294	LGE	3	45 BRO	SP	CCA			V	11/28/2029
2021 PO4015884959	LGE	4	35 BRO	SP	CRE	ED,ID		BD	11/29/2029
2021 PO8652307210	F	4	40 UNK	SP	CRE			V	11/30/2029
2021 PO8651407279	F	6	30 UNK	SP	A			V	12/1/2029
2021 PO8641807200	F	4	40 UNK	SP	CRE			V	12/2/2029
2021 PO8635707194	F	4	40 UNK	SP	CRE			V	12/3/2029
2021 PO8627507186	F	4	40 UNK	SP	CRE			V	12/4/2029
2021 PO4018884985	F	4	45 BRO	SP	CRE			V	12/5/2029
2021 PO4017984995	F	4	40 BRO	SP	CRE			V	12/6/2029
2021 PO4016884990	F	3	45 BRO	SP	CCA			V	12/7/2029
2021 PO4054485296	LGE	4	40E ACE	SP	A	ED		TD	12/8/2029
2021 PO8620006883	F	4	40 UNK	SP	CRE			V	12/9/2029
2021 PO8621606724	F	3	45 UNK	SP	CCA			V	12/10/2029
2021 PO8623206591	F	4	40 UNK	SP	CRE			V	12/11/2029
2021 PO8516306082	KU	5	35 UNK	SP	CCA			V	12/12/2029
2021 PO4055085300	LGE	2	75 ACE	SP	CRE			V	12/13/2029
2021 PO4015285028	F	4	35 BRO	SP	CRE			V	12/14/2029
2021 PO4014485039	F	4	35 BRO	SP	CRE			V	12/15/2029
2021 PO4013385053	F	4	35 BRO	SP	CRE			V	12/16/2029
2021 PO4012485063	F	4	30 BRO	SP	CRE			V	12/17/2029
2021 PO3727268872	KU	4	40 UNK	SP	CRE	ID		TD	12/18/2029
2021 PO8462006943	KU	6	30 UNK	SP	CCA			V	12/19/2029
2021 PO8464307006	KU	6	30 UNK	SP	CRE	ID		TD	12/20/2029
2021 PO4011585074	F	3	45 BRO	SP	CCA			V	12/21/2029
2021 PO4010785083	F	4	30 BRO	SP	CRE			V	12/22/2029
2021 PO4054285268	LGE	4	40 ACE	SP	CRE	ED,ID		BD	12/23/2029
2021 PO4054285266	LGE	4	30E ACE	SP	CRE	ID		BD	12/24/2029
2021 PO4112585239	LGE	4	35 ACE	SP	CRE	ED,ID		TD	12/25/2029
2021 PO4166185369	LGE	3	50 ACE	SP	CRE	ED,HH,ID		BX	12/26/2029
2021 PO5941710244	KU	5	35 ACW	SP	CRE	ED,ID,IP		TD	12/27/2029
2021 PO4061984532	LGE	4	35 BRO	SP	CCA			V	12/28/2029
2021 PO4061484528	F	4	40 BRO	SP	CRE			V	12/29/2029
2021 PO4064384525	LGE	4	45 BRO	SP	CCA			V	12/30/2029
2021 PO5956610246	KU	4	40 ACW	SP	CRE	ED,ID		BD	12/31/2029
2021 PO5969010242	KU	4	40 ACW	SP	CRE	ED,ID		TD	1/1/2030
2021 PO5963810298	F	4	40 ACW	SP	S			V	1/2/2030
2021 PO4065384511	LGE	4	45 BRO	SP	CRE	ED,ID		TD	1/3/2030
2021 PO4066384497	LGE	4	45 BRO	SP	CRE	ED,ID		TD	1/4/2030
2021 PO4067384483	LGE	4	45 BRO	SP	CRE	ED,ID		TD	1/5/2030
2021 PO4094285205	LGE	4	30 ACE	SP	P	ED,ID		TD	1/6/2030
2021 PO4093585205	LGE	4	30 ACE	SP	A	ID		TD	1/7/2030
2021 PO4094585199	LGE	3	50 ACE	SP	CRE	ED,ID		BD	1/8/2030
2021 PO4093485200	LGE	3	50 ACE	SP	CRE	ID		TD	1/9/2030

2021 PO4091985206	LGE	4	35 ACE	SP	A	ID	TD	1/10/2030
2021 PO4091985201	LGE	3	50 ACE	SP	A	ED,ID	TD	1/11/2030
2021 PO4092685206	LGE	4	35 ACE	SP	A	ED,ID,IP,MD	TD	1/12/2030
2021 PO4002385376	LGE	4	30E ACE	SP	CRE	ED	TD	1/13/2030
2021 PO4001685382	LGE	3	45 BRN	SP	CCA		V	1/14/2030
2021 PO4004485361	LGE	3	45E ACE	SP	P	ED	TD	1/15/2030
2021 PO4079685782	LGE	4	40 ACE	SP	CCA		V	1/16/2030
2021 PO4079585763	F	4	40 ACE	SP	CRE		V	1/17/2030
2021 PO4078585750	F	6	30 ACE	SP	CRE		V	1/18/2030
2021 PO4078585745	LGE	3	45 ACE	SP	CCA		V	1/19/2030
2021 PO4018586045	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD	1/20/2030
2021 PO4019686056	LGE	3	50 ACE	SP	CRE	ED,ID	TD	1/21/2030
2021 PO4076686624	LGE	4	40 ACE	SP	CCA		V	1/22/2030
2021 PO5357434206	KU	4	40 BRO	SP	CCA		B	1/23/2030
2021 PO5361834317	KU	4	40 BRO	SP	CRE	ID	TD	1/24/2030
2021 PO5372834603	KU	4	40 BRO	SP	CRE	ID	BD	1/25/2030
2021 PO5375334668	KU	4	40 BRO	SP	CRE	ID	BD	1/26/2030
2021 PO5379234769	KU	4	40 BRO	SP	CRE	ID	TD	1/27/2030
2021 PO5389135023	KU	4	40 BRO	SP	CRE	ID	BD	1/28/2030
2021 PO5390734919	KU	6	30 BRO	SP	CRE	ID	TD	1/29/2030
2021 PO5383734886	KU	4	40 BRO	SP	CRE	ID	TD	1/30/2030
2021 PO4163086058	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	1/31/2030
2021 PO4164586053	LGE	4	35 BRO	SP	A	ID	BD	2/1/2030
2021 PO4165886051	F	4	40 BRO	SP	CRE		V	2/2/2030
2021 PO4163986051	F	4	40 BRO	SP	CCA		V	2/3/2030
2021 PO4079485749	F	4	45 ACE	SP	A		V	2/4/2030
2021 PO4079385740	F	4	40 ACE	SP	CRE		V	2/5/2030
2021 PO4080885758	F	7	25 ACE	SP	CRE		V	2/6/2030
2021 PO4080885752	F	4	40 ACE	SP	CRE		V	2/7/2030
2021 PO4082785724	F	4	30 ACE	SP	CCA		V	2/8/2030
2021 PO4082585736	F	4	40 ACE	SP	CRE		V	2/9/2030
2021 PO4083585751	F	7	25 ACE	SP	CRE		V	2/10/2030
2021 PO4082685751	F	4	40 ACE	SP	CCA		V	2/11/2030
2021 PO4082685766	F	4	40 ACE	SP	CRE		V	2/12/2030
2021 PO4020686066	LGE	1	55 ACE	SP	CCA		V	2/13/2030
2021 PO4044186497	LGE	UNK	75 ACE	SP	CRE		V	2/14/2030
2021 PO4041786510	LGE	UNK	75 ACE	SP	CRE		V	2/15/2030
2021 PO4039486522	LGE	UNK	80 ACE	SP	CRE		V	2/16/2030
2021 PO4040486541	LGE	UNK	70 ACE	SP	CRE		V	2/17/2030
2021 PO4039286548	LGE	UNK	70 ACE	SP	CRE		V	2/18/2030
2021 PO4037886556	LGE	UNK	60 ACE	SP	CRE		V	2/19/2030
2021 PO4036586564	LGE	UNK	60 ACE	SP	CRE		V	2/20/2030
2021 PO5133808377	KU	3	40 ACE	SP	CRE	SRC	TD	2/21/2030
2021 PO4039486173	LGE	4	40 KOP	SP	P		V	2/22/2030
2021 PO5227822828	KU	4	40 UNK	SP	CRE		B	2/23/2030
2021 PO4040386190	F	4	40 KOP	SP	CCA		V	2/24/2030
2021 PO4059185969	F	4	40 ACE	SP	A		V	2/25/2030
2021 PO4040686194	F	4	25 KOP	SP	P		V	2/26/2030
2021 PO4057785970	F	4	40 ACE	SP	CRE		V	2/27/2030
2021 PO4056185971	F	3	45 ACE	SP	CCA		V	2/28/2030
2021 PO4004485847	LGE	4	40 ACE	SP	CRE	ED,ID	BD	3/1/2030
2021 PO4055885971	F	3	45 ACE	SP	CCA		V	3/2/2030
2021 PO4054685972	F	4	35 ACE	SP	CRE		V	3/3/2030
2021 PO4057085970	F	4	40 ACE	SP	CRE		V	3/4/2030

2021 PO4056985963	F	4	40 ACE	SP	CCA		V	3/5/2030
2021 PO4056785947	F	4	40 ACE	SP	A		V	3/6/2030
2021 PO5156408433	KU	7	30 ACE	SP	CCA		V	3/7/2030
2021 PO4056685930	F	4	40 ACE	SP	A		V	3/8/2030
2021 PO4056485915	F	4	40 ACE	SP	A		V	3/9/2030
2021 PO4056385900	F	4	40 ACE	SP	P		V	3/10/2030
2021 PO4055585888	F	4	30 ACE	SP	CRE		V	3/11/2030
2021 PO4056285887	F	4	40 ACE	SP	P		V	3/12/2030
2021 PO4056085891	F	4	30 ACE	SP	CCA		V	3/13/2030
2021 PO4035186572	LGE	UNK	60 ACE	SP	CRE		V	3/14/2030
2021 PO4033886580	LGE	UNK	60 ACE	SP	CRE		V	3/15/2030
2021 PO4034186600	LGE	4	30 ACE	SP	CRE	ED,ID	TD	3/16/2030
2021 PO4034386594	LGE	4	35 ACE	SP	CRE	ED,ID	BD	3/17/2030
2021 PO5245022787	KU	2	40 UNK	SP	CRE		B	3/18/2030
2021 PO5244122728	KU	3	45 UNK	SP	CRE		B	3/19/2030
2021 PO4032586588	LGE	UNK	60 ACE	SP	CRE		V	3/20/2030
2021 PO5016113436	KU	3	50 KOP	SP	CRE	ED,ID	BD	3/21/2030
2021 PO5010213337	KU	6	30 KOP	SP	CRE	ED,ID	TD	3/22/2030
2021 PO7531673651	LGE	4	35 KOP	SP	CCA		V	3/23/2030
2021 PO5163208398	KU	6	35 ACE	SP	CCA		V	3/24/2030
2021 PO4038486205	LGE	4	35 KOP	SP	P	ED,ID,MD	TD	3/25/2030
2021 PO5163908322	KU	7	35 ACE	SP	CCA		V	3/26/2030
2021 PO5143008241	KU	6	35 ACE	SP	P	ED	TD	3/27/2030
2021 PO5157208299	F	3	40 ACE	SP	P		V	3/28/2030
2021 PO5148108332	F	4	40 ACE	SP	P		V	3/29/2030
2021 PO5129408302	KU	6	40 ACE	SP	P	RB	X PX	3/30/2030
2021 PO4058985847	F	4	40 ACE	SP	CRE		V	3/31/2030
2021 PO4059085860	F	4	40 ACE	SP	CRE		V	4/1/2030
2021 PO4059185873	F	3	45 ACE	SP	CCA		V	4/2/2030
2021 PO4059385887	F	4	40 ACE	SP	CRE		V	4/3/2030
2021 PO4059385899	F	4	40 ACE	SP	CRE		V	4/4/2030
2021 PO4059485913	F	4	40 ACE	SP	CRE		V	4/5/2030
2021 PO4059585926	F	4	40 ACE	SP	CRE		V	4/6/2030
2021 PO3998585835	LGE	3	45 ACE	SP	CCA		V	4/7/2030
2021 PO3996685818	F	4	35 ACE	SP	P		V	4/8/2030
2021 PO5256722652	KU	4	40 UNK	SP	CRE		B	4/9/2030
2021 PO3999485827	F	4	40 ACE	SP	P		V	4/10/2030
2021 PO4000485820	F	4	40 ACE	SP	CCA		V	4/11/2030
2021 PO4032086617	LGE	4	35 ACE	SP	CCA		V	4/12/2030
2021 PO4031986600	LGE	4	40 ACE	SP	CRE	ED,HH,ID	BX PX	4/13/2030
2021 PO4031586593	LGE	UNK	60 ACE	SP	CCA		V	4/14/2030
2021 PO4001385811	LGE	4	30 ACE	SP	P	ED,ID,IP	TD	4/15/2030
2021 PO4001585813	F	4	40 ACE	SP	CCA		V	4/16/2030
2021 PO4002485806	F	4	40 ACE	SP	CRE		V	4/17/2030
2021 PO4003585799	F	4	40 ACE	SP	CRE		V	4/18/2030
2021 PO4005585785	F	4	40 ACE	SP	CRE		V	4/19/2030
2021 PO4004585792	F	4	40 ACE	SP	CRE		V	4/20/2030
2021 PO4045886585	LGE	4	35 ACE	SP	CRE	ED,ID	TD	4/21/2030
2021 PO7578377585	F	4	35 ACE	SP	CRE		V	4/22/2030
2021 PO4044986577	F	4	35 ACE	SP	CRE		V	4/23/2030
2021 PO4045886570	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD	4/24/2030
2021 PO4136485985	LGE	4	40 BRO	SP	CCA	ED	T	4/25/2030
2021 PO4027986135	LGE	3	50 ACE	SP	CRE	ED,ID	TD	4/26/2030
2021 PO5186908192	F	5	30 ACE	SP	CRE		V	4/27/2030

2021	PO5202108260	KU	7	35 ACE	SP	CRE	ID	BD		4/28/2030
2021	PO5395335209	KU	6	30 BRO	SP	CCA		V		4/29/2030
2021	PO5393735165	KU	4	40 BRO	SP	CRE	ID	BX	RP2	4/30/2030
2021	PO4029086146	LGE	3	50 ACE	SP	CRE	ED,ID	BD		5/1/2030
2021	PO4030086156	LGE	3	55 ACE	SP	CRE	ED,ID	BD		5/2/2030
2021	PO4031086165	LGE	3	50 ACE	SP	CRE	ED,ID	BD		5/3/2030
2021	PO4045286556	LGE	4	40 ACE	SP	CRE	ED	BD		5/4/2030
2021	PO4046086558	LGE	4	35 ACE	SP	CRE	ED,ID	TD		5/5/2030
2021	PO4045786542	LGE	4	40 ACE	SP	CRE	ED,ID	BD		5/6/2030
2021	PO4044786543	LGE	4	40 ACE	SP	CRE	ED,ID	TD		5/7/2030
2021	PO4030986175	LGE	4	35 ACE	SP	P	ED,ID	TD		5/8/2030
2021	PO4030286185	LGE	4	35 ACE	SP	P	ED,ID	TD		5/9/2030
2021	PO4031586185	LGE	4	35 ACE	SP	P	ED,ID	BD		5/10/2030
2021	PO4032386177	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD		5/11/2030
2021	PO4033286189	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD		5/12/2030
2021	PO4044586515	LGE	4	35 ACE	SP	CRE	ED,ID	TD		5/13/2030
2021	PO4045386527	LGE	4	40 ACE	SP	CRE	ED,ID	TD		5/14/2030
2021	PO5188008234	KU	7	35 ACE	SP	CCA		V		5/15/2030
2021	PO5227108691	KU	7	30 ACE	SP	CRE	ED,ID,SRC	TD		5/16/2030
2021	PO4176886039	LGE	1	100 BRO	SP	CRE	ED,ID,IP	TD		5/17/2030
2021	PO4048586023	F	4	40 KOP	SP	A		V		5/18/2030
2021	PO4175886039	LGE	2	55 BRO	SP	A	ED,ID	TD		5/19/2030
2021	PO4098385877	F	4	40 ACE	SP	CRE		V		5/20/2030
2021	PO4098385890	F	4	40 ACE	SP	CRE		V		5/21/2030
2021	PO4101985951	F	4	40 ACE	SP	CRE		V		5/22/2030
2021	PO4098485906	F	4	40 ACE	SP	CRE		V		5/23/2030
2021	PO4098685923	F	4	40 ACE	SP	CRE		V		5/24/2030
2021	PO4098785941	F	4	40 ACE	SP	A		V		5/25/2030
2021	PO4099185952	F	3	45 ACE	SP	CCA		V		5/26/2030
2021	PO4102685937	F	6	30 ACE	SP	A		V		5/27/2030
2021	PO4101985938	F	4	40 ACE	SP	CRE		V		5/28/2030
2021	PO4101985925	F	4	40 ACE	SP	CRE		V		5/29/2030
2021	PO4101885913	F	4	40 ACE	SP	CRE		V		5/30/2030
2021	PO4101785900	F	4	40 ACE	SP	CRE		V		5/31/2030
2021	PO4101685888	F	4	40 ACE	SP	A		V		6/1/2030
2021	PO4101585876	F	4	40 ACE	SP	A		V		6/2/2030
2021	PO4101485864	F	4	40 ACE	SP	CRE		V		6/3/2030
2021	PO4101385851	F	3	45 ACE	SP	CCA		V		6/4/2030
2021	PO4101285839	F	4	45 ACE	SP	A		V		6/5/2030
2021	PO5270324500	KU	6	30 UNK	SP	CCA		B		6/6/2030
2021	PO5280724500	KU	6	30 UNK	SP	CCA		V		6/7/2030
2021	PO5285424515	KU	3	45 UNK	SP	CRE		B		6/8/2030
2021	PO5291524496	KU	6	30 UNK	SP	CCA		B		6/9/2030
2021	PO7563576876	LGE	4	35 ACE	SP	CCA		V		6/10/2030
2021	PO4043186522	LGE	4	40 ACE	SP	CRE	ED,ID	TD		6/11/2030
2021	PO4043186543	LGE	4	45 ACE	SP	CRE	ED,ID	BD		6/12/2030
2021	PO4043086556	LGE	4	40 ACE	SP	CRE	ED,ID	TD		6/13/2030
2021	PO4043986569	LGE	4	45 ACE	SP	CRE	ED,ID	TD		6/14/2030
2021	PO5304024513	KU	4	40 UNK	SP	CCA		V		6/15/2030
2021	PO5313724513	KU	3	45 UNK	SP	CRE		B		6/16/2030
2021	PO5321724494	KU	6	30 UNK	UN	CCA		V		6/17/2030
2021	PO5223508599	KU	7	30 ACE	SP	CRE	ED	TD		6/18/2030
2021	PO4033486188	LGE	1	55 ACE	SP	CCA		V		6/19/2030
2021	PO4174986040	LGE	2	55 BRO	SP	A	ED,ID,IP	TX	RR	6/20/2030

2021 PO4174086040	LGE	2	55 BRO	SP	A	ED,ID	TD	6/21/2030
2021 PO4173486040	LGE	2	55 BRO	SP	A	ED,ID,JP	TD	6/22/2030
2021 PO4034486198	LGE	3	50 ACE	SP	CRE	ED,ID	TD	6/23/2030
2021 PO4036786223	LGE	4	30 ACE	SP	CRE	ED,ID	TD	6/24/2030
2021 PO5327424511	KU	3	45 UNK	SP	CRE		T	6/25/2030
2021 PO4140285963	LGE	2	80 BRO	ST	P		V	6/26/2030
2021 PO4158986047	LGE	1	95 BRO	ST	P		V	6/27/2030
2021 PO5313922418	KU	6	30 UNK	SP	CRE	ED,ID	BX	6/28/2030
2021 PO3999983610	LGE	4	35 BRO	SP	CCA		V	6/29/2030
2021 PO4024585559	LGE	UNK	45 KOP	SP	P		V	6/30/2030
2021 PO4025885537	LGE	5	30 KOP	SP	P		V	7/1/2030
2021 PO4026285540	LGE	3	45 KOP	SP	CCA		V	7/2/2030
2021 PO5442532078	KU	4	40 KOP	SP	CRE	ID	TD	7/3/2030
2021 PO4108885947	LGE	4	40 ACE	SP	CRE	ED,ID	BD	7/4/2030
2021 PO4108885943	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	7/5/2030
2021 PO4107685946	F	4	40 ACE	SP	CCA		V	7/6/2030
2021 PO4108485939	F	4	40 ACE	SP	CRE		V	7/7/2030
2021 PO4110285927	F	3	45 ACE	SP	CRE		V	7/8/2030
2021 PO4113385898	F	UNK	45 ACE	SP	CRE		V	7/9/2030
2021 PO4112185907	F	UNK	45 ACE	SP	CRE		V	7/10/2030
2021 PO4111585913	F	4	40 ACE	SP	CRE		V	7/11/2030
2021 PO4110785902	F	4	40 ACE	SP	CRE		V	7/12/2030
2021 PO5455332099	KU	4	40 KOP	SP	CRE	ID	TD	7/13/2030
2021 PO5415033764	KU	5	35 KOP	SP	CCA		V	7/14/2030
2021 PO4110285894	F	4	40 ACE	SP	CRE		V	7/15/2030
2021 PO4109685886	F	4	40 ACE	SP	CRE		V	7/16/2030
2021 PO4109085878	LGE	4	40 ACE	SP	CCA		V	7/17/2030
2021 PO4108485870	F	4	40 ACE	SP	CRE		V	7/18/2030
2021 PO4107885862	F	4	40 ACE	SP	CRE		V	7/19/2030
2021 PO4107385853	F	4	40 ACE	SP	CRE		V	7/20/2030
2021 PO5080112789	KU	5	35 KOP	SP	CRE	ED,ID	TD	7/21/2030
2021 PO5341625122	KU	4	40 UNK	SP	CRE		B	7/22/2030
2021 PO4107085844	F	4	40 ACE	SP	CRE		V	7/23/2030
2021 PO4107085834	F	4	40 ACE	SP	CCA		V	7/24/2030
2021 PO4106985829	F	4	30 ACE	SP	CRE		V	7/25/2030
2021 PO5340925037	KU	4	40 UNK	SP	CRE		B	7/26/2030
2021 PO4103785810	F	4	40 ACE	SP	CCA		V	7/27/2030
2021 PO4103785819	LGE	4	40 ACE	SP	CRE		V	7/28/2030
2021 PO4103885830	LGE	4	40 ACE	SP	CRE		V	7/29/2030
2021 PO4103985849	F	4	40 ACE	SP	CCA		V	7/30/2030
2021 PO4103985840	LGE	4	40 ACE	SP	CCA		V	7/31/2030
2021 PO4104485860	LGE	5	35 ACE	SP	CRE	ED,ID	V	8/1/2030
2021 PO4104085860	F	4	40 ACE	SP	CRE		V	8/2/2030
2021 PO4104185870	F	4	40 ACE	SP	CRE		V	8/3/2030
2021 PO4028785526	LGE	5	25 KOP	SP	A		V	8/4/2030
2021 PO5340224946	KU	4	40 UNK	SP	CRE		T	8/5/2030
2021 PO5339424804	KU	4	40 UNK	SP	CRE		T	8/6/2030
2021 PO5089512494	F	4	40 KOP	SP	CRE		V	8/7/2030
2021 PO5085712394	F	4	40 KOP	SP	CRE		V	8/8/2030
2021 PO5084512522	KU	6	30 KOP	SP	CRE	ED,ID	TD	8/9/2030
2021 PO4027985507	LGE	3	45 KOP	SP	CCA		V	8/10/2030
2021 PO4043185727	F	4	30 KOP	SP	P		V	8/11/2030
2021 PO4043685713	F	4	35 KOP	SP	A		V	8/12/2030
2021 PO4042585713	F	4	40 KOP	SP	A		V	8/13/2030

2021 PO4037886444	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/14/2030
2021 PO5394622248	KU	3	45 UNK	SP	CCA		V	8/15/2030
2021 PO5385022351	KU	3	45 UNK	SP	CCA		V	8/16/2030
2021 PO5383622365	KU	3	45 UNK	SP	CRE		B	8/17/2030
2021 PO4055686197	LGE	6	30 ACE	SP	CRE		V	8/18/2030
2021 PO4036486460	LGE	4	40 ACE	SP	CRE	ED,ID	BD	8/19/2030
2021 PO4042485701	F	4	40 KOP	SP	A		V	8/20/2030
2021 PO4058486074	F	4	40 ACE	SP	CRE		V	8/21/2030
2021 PO4058286054	F	4	45 ACE	SP	CRE		V	8/22/2030
2021 PO4058186048	F	4	35 ACE	SP	A		V	8/23/2030
2021 PO4058986032	F	4	40 ACE	SP	A		V	8/24/2030
2021 PO4059786007	F	4	40 ACE	SP	CCA		V	8/25/2030
2021 PO4059686012	F	4	40 ACE	SP	A		V	8/26/2030
2021 PO4059386020	F	4	40 ACE	SP	A		V	8/27/2030
2021 PO4057386020	F	4	40 ACE	SP	CRE		V	8/28/2030
2021 PO4042985687	F	4	40 KOP	SP	CCA		V	8/29/2030
2021 PO4006285927	LGE	3	50 ACE	SP	CRE	ED,ID	TD	8/30/2030
2021 PO4005485938	LGE	4	35 ACE	SP	CRE	ED,ID	TD	8/31/2030
2021 PO4013883243	LGE	4	40 BRO	SP	A	ID	BD	9/1/2030
2021 PO4043085667	F	4	30 KOP	SP	P		V	9/2/2030
2021 PO4050986092	F	4	40 ACE	SP	CRE		V	9/3/2030
2021 PO4052086086	F	3	45 ACE	SP	CCA		V	9/4/2030
2021 PO4053486079	F	3	45 ACE	SP	CCA		V	9/5/2030
2021 PO4052686045	F	4	40 ACE	SP	CCA		V	9/6/2030
2021 PO4053286058	F	3	45 ACE	SP	P		V	9/7/2030
2021 PO4054186076	LGE	3	45 ACE	SP	CCA		V	9/8/2030
2021 PO4049786097	F	4	35 ACE	SP	CRE		V	9/9/2030
2021 PO4050286108	F	4	35 ACE	SP	A		V	9/10/2030
2021 PO4043085653	F	4	30 KOP	SP	A		V	9/11/2030
2021 PO4042985641	F	6	30 KOP	SP	A		V	9/12/2030
2021 PO5380032142	KU	3	45 BRO	SP	CCA		V	9/13/2030
2021 PO5397832167	KU	4	40 BRO	SP	CCA		V	9/14/2030
2021 PO5416032194	KU	3	45 BRO	SP	CCA		V	9/15/2030
2021 PO5417731961	KU	3	45 BRO	SP	CCA		V	9/16/2030
2021 5417731961A	KU	3	45 BRO	SP	CCA		V	9/17/2030
2021 PO5420431819	KU	5	35 UNK	SP	CRE	ID	BD	9/18/2030
2021 PO5408931800	KU	4	45 BRO	SP	CCA		V	9/19/2030
2021 PO5409331825	KU	2	45 BRO	SP	CCA		V	9/20/2030
2021 PO5406531676	KU	3	45 BRO	SP	CRE	ID	BD	9/21/2030
2021 PO4004685950	LGE	4	35 ACE	SP	P	ED,ID	TD	9/22/2030
2021 PO5372622486	KU	5	45 UNK	SP	CRE		B	9/23/2030
2021 PO4042085617	F	3	45 KOP	SP	CCA		V	9/24/2030
2021 PO4042085629	F	3	45 KOP	SP	CCA		V	9/25/2030
2021 PO4078385748	LGE	4	40 ACE	SP	P	ID	TD	9/26/2030
2021 PO4077385749	LGE	4	30 ACE	SP	P	ED,ID	TD	9/27/2030
2021 PO8418267402	KU	5	35 ACE	SP	CCA		V	9/28/2030
2021 PO4004983647	LGE	3	45 BRO	SP	CCA	ED	T	9/29/2030
2021 PO8404867385	KU	5	35 ACE	SP	CRE	ED,ID	TD	9/30/2030
2021 PO4005683657	LGE	3	45 BRO	SP	CRE	ED,ID	TD	10/1/2030
2021 PO3103294961	KU	6	30 ACE	SP	CRE		V	10/2/2030
2021 PO3089995045	KU	3	45 ACE	SP	CRE	ED	TD	10/3/2030
2021 PO8398367408	KU	3	45 ACE	SP	CCA		V	10/4/2030
2021 PO8387967401	KU	3	45 ACE	SP	CCA		V	10/5/2030
2021 PO3112994701	KU	5	40 ACE	SP	CRE	ED	TD	10/6/2030

2021 PO4004283637	LGE	3	45 BRO	SP	CCA	ED	T		10/7/2030
2021 PO4003583635	LGE	4	30 BRO	SP	CCA	ED	T		10/8/2030
2021 PO8381667395	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD		10/9/2030
2021 PO8367267400	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD		10/10/2030
2021 PO8366967436	KU	4	40 ACE	SP	CCA		V		10/11/2030
2021 PO4003583627	LGE	3	45 BRO	SP	CCA		V		10/12/2030
2021 PO4002883625	LGE	4	35 BRO	SP	CCA	ED	T		10/13/2030
2021 PO3172294418	KU	3	45 ACE	SP	CCA		V		10/14/2030
2021 PO4014183306	LGE	4	35 BRO	SP	A	ED,ID	TD		10/15/2030
2021 PO4013583297	LGE	4	35 BRO	SP	CRE	ED	TD		10/16/2030
2021 PO4012983302	LGE	4	35 BRO	SP	A	ED,ID	TD		10/17/2030
2021 PO4007883724-A	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		10/18/2030
2021 PO1844086452	KU	4	40 KOP	SP	CRE	ID	TD		10/19/2030
2021 PO1562782520	KU	4	40 BRO	SP	CCA		V		10/20/2030
2021 PO3030295654	KU	4	40 ACE	SP	CRE	ED,ID,SRC	TD		10/21/2030
2021 PO8357166961	KU	3	45 ACE	ST	CRE		V		10/22/2030
2021 PO8388366979a	F	5	35 ACE	SP	CCA	ED	V		10/23/2030
2021 PO1868385595	KU	4	40 BRO	SP	CRE	ID	TD		10/24/2030
2021 PO4107485994	LGE	4	45 ACE	SP	CCA		V		10/25/2030
2021 PO4108285990	LGE	4	30 ACE	SP	CCA		V		10/26/2030
2021 PO4107385984	LGE	4	45 ACE	SP	CRE	ED,ID	BD		10/27/2030
2021 PO4108085988	LGE	4	35 ACE	SP	A	ID	BD		10/28/2030
2021 PO4107485982	LGE	4	45 ACE	SP	CRE	ID	BD		10/29/2030
2021 PO4107985964	LGE	4	45 ACE	SP	CRE	ED,HH,ID	BD		10/30/2030
2021 PO4107985963	LGE	6	25 ACE	SP	P	ED,ID,RB	X	PX	10/31/2030
2021 PO4007883688	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		11/1/2030
2021 PO4007083677	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		11/2/2030
2021 PO8813596345	KU	4	45 KOP	SP	CCA		V		11/3/2030
2021 PO3063895075	KU	3	40 ACE	SP	CRE	ED	TD		11/4/2030
2021 PO8446867644	KU	3	45 ACE	SP	CRE	ED,ID	BD		11/5/2030
2021 PO6067185473	KU	4	45 ACE	SP	CRE	ID	TD		11/6/2030
2021 PO6066185215	KU	4	45 ACE	SP	CCA		V		11/7/2030
2021 PO6061284957A	KU	4	45 XXX	SP	CCA		V		11/8/2030
2021 PO6061284957	KU	4	45 ACE	SP	CCA		V		11/9/2030
2021 PO6113384942	KU	4	45 ACE	SP	CCA		V		11/10/2030
2021 PO6126985543	KU	6	30 ACE	SP	CRE		V		11/11/2030
2021 PO6237685172	KU	4	40 ACE	SP	CRE		B		11/12/2030
2021 PO6176485451	KU	4	50 ACE	SP	CRE		B		11/13/2030
2021 PO6131085638	KU	4	30 ACE	SP	CRE		V		11/14/2030
2021 PO6210085311	KU	4	40 ACE	SP	CRE		V		11/15/2030
2021 PO6268085135	KU	4	40 ACE	SP	CRE		V		11/16/2030
2021 PO8820496246	KU	3	45 KOP	SP	CCA		V		11/17/2030
2021 PO8815796161	KU	4	40 KOP	SP	CRE	ED,EP,ID	X	RP2	11/18/2030
2021 PO8791496227	KU	4	40 KOP	SP	CRE	ED,ID	TD		11/19/2030
2021 PO8817695951	KU	4	40 KOP	SP	CRE		V		11/20/2030
2021 PO8809495981	KU	6	30 KOP	SP	CRE	ED,ID	TD		11/21/2030
2021 PO8822496131	KU	6	30 CAH	SP	CRE	ED,EP,ID	TX	RR	11/22/2030
2021 PO8828695853	KU	6	30 BRO	SP	P		V		11/23/2030
2021 PO8840695827	KU	6	30 CAH	SP	CRE	ED,ID	TD		11/24/2030
2021 PO8842995783	F	4	40 BRO	SP	P		V		11/25/2030
2021 PO6044986249	KU	6	30 ACE	SP	CCA		V		11/26/2030
2021 PO6053886393	KU	4	40 ACE	SP	CRE	ID	TD		11/27/2030
2021 PO6038486254	KU	5	30 ACE	SP	CRE	ID	BD		11/28/2030
2021 PO6035286142	KU	4	45 ACE	SP	CCA		V		11/29/2030

2021 PO6043385942	F	5	35 ACE	SP	P		V	11/30/2030
2021 PO6074085940	KU	4	40 ACE	SP	CRE	ID	TD	12/1/2030
2021 PO8527967177	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	12/2/2030
2021 PO8851596404	KU	6	30 BRO	SP	CRE	ED,ID	TD	12/3/2030
2021 PO8865996591	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/4/2030
2021 PO8852796554	KU	4	40 BRO	SP	CRE	ED,ID	BD	12/5/2030
2021 PO8857596509	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/6/2030
2021 PO8525967171	KU	3	45 ACE	SP	CCA		V	12/7/2030
2021 PO4051685999	F	4	40 ACE	SP	CRE		V	12/8/2030
2021 PO8852196301	KU	6	30 BRO	SP	CRE	ED,ID	TD	12/9/2030
2021 PO8842896316	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/10/2030
2021 PO8350167380	KU	3	50 ACE	SP	CRE	ED,HH,ID,RB	BX	12/11/2030
2021 PO3635833704	KU	3	45 BRO	SP	CCA		V	12/12/2030
2021 PO8332567372	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD	12/13/2030
2021 PO3161194464	KU	5	40 ACE	SP	CRE		T	12/14/2030
2021 PO8314767367	KU	3	50 ACE	SP	CCA		V	12/15/2030
2021 PO8310167385	KU	3	50 ACE	SP	CCA		V	12/16/2030
2021 PO8285867349	KU	3	50 ACE	SP	CCA		V	12/17/2030
2021 PO8281967349	KU	2	50 ACE	SP	CCA		V	12/18/2030
2021 PO8277967342	KU	3	50 ACE	SP	CCA		V	12/19/2030
2021 PO8272967338	KU	3	50 ACE	SP	CCA		V	12/20/2030
2021 PO8261067330	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD	12/21/2030
2021 PO8266067369	KU	3	45 ACE	SP	CCA		V	12/22/2030
2021 PO4015183314	LGE	4	35 BRO	SP	CRE	ED,ID	TD	12/23/2030
2021 PO4015883320	LGE	4	40 BRO	SP	A	ED,ID	TD	12/24/2030
2021 PO3143894540	KU	3	45 ACE	SP	CCA		V	12/25/2030
2021 PO1569482837	KU	4	40 BRO	SP	CRE		V	12/26/2030
2021 PO1590683219	KU	3	45 BRO	SP	CCA		T	12/27/2030
2021 PO1621883305	KU	3	45 BRO	SP	CCA		T	12/28/2030
2021 PO1594483609	KU	4	45 BRO	SP	CCA		V	12/29/2030
2021 PO1629184659	KU	3	45 BRO	SP	CCA		V	12/30/2030
2021 PO1620184636	KU	4	40 BRO	SP	CCA		V	12/31/2030
2021 PO1627984971	KU	5	35 BRO	SP	CCA		V	1/1/2031
2021 PO1630985156	KU	4	40 BRO	SP	CCA		V	1/2/2031
2021 PO1654585293	KU	5	35 BRO	SP	CRE		V	1/3/2031
2021 PO1661485339	KU	4	40 BRO	SP	CRE		B	1/4/2031
2021 PO1702185568	KU	4	40 BRO	SP	CRE	ID	TD	1/5/2031
2021 PO1713285632	KU	3	45 BRO	SP	CCA		V	1/6/2031
2021 PO1719086128	KU	3	45 BRO	SP	CCA		V	1/7/2031
2021 PO1738885887	KU	3	45 BRO	SP	CCA		V	1/8/2031
2021 PO1747685906	KU	3	45 BRO	SP	CCA		V	1/9/2031
2021 PO8902196226	KU	4	35 KOP	SP	CRE	ED,ID	BD	1/10/2031
2021 PO3009095492	KU	3	45 ACE	SP	CCA		V	1/11/2031
2021 PO3004695794	KU	5	45 ACE	SP	CRE		T	1/12/2031
2021 PO1841685727	KU	4	40 BRO	SP	CRE	ID	TD	1/13/2031
2021 PO1726785486	KU	4	40 BRO	SP	CRE	ID	BD	1/14/2031
2021 PO8377366994	KU	3	45 ACE	ST	CRE		V	1/15/2031
2021 PO8483867096	F	2	60 ACE	ST	CCA		V	1/16/2031
2021 PO3004695794a	KU	4	40 ACE	SP	CCA		V	1/17/2031
2021 PO3076495788	KU	3	40 ACE	SP	CRE	SRC	TD	1/18/2031
2021 PO3047295465	KU	3	40 ACE	SP	CRE	ED,ID,IP	TD	1/19/2031
2021 PO3058695590	KU	3	40 ACE	SP	CRE	SRS	TD	1/20/2031
2021 PO6015586243	KU	4	40 ACE	SP	CRE	ID	TD	1/21/2031
2021 PO5992086374	KU	4	40 ACE	SP	CRE	ID	TD	1/22/2031



2021	PO5965886492	KU	4	40 ACE	SP	CRE	ID	BD	1/23/2031
2021	PO5931286654	KU	4	40 ACE	SP	CRE	ID	TD	1/24/2031
2021	PO5902186789	KU	4	40 ACE	SP	CRE	ID,IP	TD	1/25/2031
2021	PO4056285974	F	4	40 ACE	SP	CRE		V	1/26/2031
2021	PO4056285977	F	4	40 ACE	SP	CRE		V	1/27/2031
2021	PO4056585995	F	3	45 ACE	SP	CCA		V	1/28/2031
2021	PO4056585996	F	3	45 ACE	SP	CCA		V	1/29/2031
2021	PO4058485995	LGE	4	40 ACE	SP	A	ED,ID	BD	1/30/2031
2021	PO4057985987	LGE	4	40 ACE	SP	CRE	ED,ID	BD	1/31/2031
2021	PO4058885986	F	4	30 ACE	SP	CRE		V	2/1/2031
2021	PO4059985983	F	4	40 ACE	SP	CRE		V	2/2/2031
2021	PO4061886019	F	4	30 ACE	SP	A		V	2/3/2031
2021	PO4010383763	LGE	2	55 BRO	SP	CRE	ED,ID	TD	2/4/2031
2021	PO8360268252	KU	4	40 ACE	SP	CRE	ED,ID	BD	2/5/2031
2021	PO8348668176	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	2/6/2031
2021	PO8351868295	KU	4	40 ACE	SP	CRE	ED,ID	BD	2/7/2031
2021	PO8377668092	KU	4	40 ACE	SP	CRE	ED,ID	BD	2/8/2031
2021	PO8369568000	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	2/9/2031
2021	PO3194094299	KU	3	45 ACE	SP	CCA		V	2/10/2031
2021	PO8383867871	KU	6	30 ACE	SP	CCA		V	2/11/2031
2021	PO8391967964	KU	4	40 ACE	SP	CRE	ED,ID	BD	2/12/2031
2021	PO3220894178	KU	4	40 ACE	SP	CRE	ED,SRS	TD	2/13/2031
2021	PO8386467615	KU	6	30 ACE	SP	CCA		V	2/14/2031
2021	PO8381467615	KU	6	35 ACE	SP	CRE	ED,ID	TD	2/15/2031
2021	PO8489066877	F	2	70 ACE	SP	CRE		V	2/16/2031
2021	PO8489866665	F	2	65 ACE	SP	P		V	2/17/2031
2021	PO8490366550	F	3	55 ACE	SP	CRE		V	2/18/2031
2021	PO8489266832	KU	2	55 ACE	SP	CRE	ED,ID	BD	2/19/2031
2021	PO3098096039	KU	4	40 ACE	SP	CRE	SRC	TD	2/20/2031
2021	PO5866886964	KU	4	50 ACE	SP	CRE	ID	TD	2/21/2031
2021	PO5834587098	KU	4	40 ACE	SP	CRE	ID,IP	TD	2/22/2031
2021	PO8490766398	F	4	40 ACE	SP	CCA		V	2/23/2031
2021	PO8491866250	F	4	40 ACE	SP	CCA		V	2/24/2031
2021	PO8494565895	F	3	55 ACE	SP	CCA		V	2/25/2031
2021	PO8494465850	F	3	55 ACE	SP	CCA		V	2/26/2031
2021	PO8493965748	KU	4	45 ACE	SP	CCA		V	2/27/2031
2021	PO4061186118	LGE	4	35 ACE	SP	A	ID	TD	2/28/2031
2021	PO4048786283	LGE	4	40 ACE	SP	CRE		V	3/1/2031
2021	PO4055786206	LGE	6	25 ACE	SP	CRE		V	3/2/2031
2021	PO4055686114	LGE	4	35 ACE	SP	CCA		V	3/3/2031
2021	PO4052186023	LGE	4	40 ACE	SP	CRE		V	3/4/2031
2021	PO4052786022	LGE	7	25 ACE	SP	CRE		V	3/5/2031
2021	PO7660271818	LGE	4	35 ACE	SP	CCA		V	3/6/2031
2021	PO4051986011	LGE	3	45 ACE	SP	CCA		V	3/7/2031
2021	PO8893096285	KU	4	40 KOP	SP	CRE	ED,ID	TD	3/8/2031
2021	PO8881096366	KU	5	35 KOP	SP	CRE	ED,ID	TD	3/9/2031
2021	PO8862096337	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/10/2031
2021	PO8868696438	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	3/11/2031
2021	PO3128896355	KU	3	45E ACE	SP	CRE	ED,SRC	TD	3/12/2031
2021	PO8494165720	F	2	45 ACE	SP	CCA		V	3/13/2031
2021	PO8524666876	KU	1	65 ACE	SP	P		V	3/14/2031
2021	PO4009983756	LGE	2	95 BRO	SP	CRE	ED,ID	TD	3/15/2031
2021	PO8496267912	KU	5	35 ACE	SP	CCA		V	3/16/2031
2021	PO8488067163	F	3	45 ACE	SP	P		V	3/17/2031

2021 PO4009383747	LGE	3	50 BRO	SP	A	ED,ID,IP	TD		3/18/2031
2021 PO8497767156	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		3/19/2031
2021 PO8506867148	KU	4	45 ACE	SP	CCA		V		3/20/2031
2021 PO4008783737	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		3/21/2031
2021 PO8834496499	KU	4	45 KOP	SP	CRE	ED,ID,IP	TD		3/22/2031
2021 PO8845396531	KU	4	40 KOP	SP	CRE	ED,ID	TD		3/23/2031
2021 PO3076295159	KU	6	30 ACE	SP	CRE		V		3/24/2031
2021 PO3600631478	KU	1	50 BRN	SP	CCA		V		3/25/2031
2021 PO3645333823	KU	3	45 BRO	SP	CCA		V		3/26/2031
2021 PO3621333346	KU	3	45 BRO	SP	CCA		V		3/27/2031
2021 PO3661334025	KU	3	45 BRO	SP	CCA		V		3/28/2031
2021 PO3619333105	KU	3	45 BRO	SP	CCA		V		3/29/2031
2021 PO3687334234	KU	3	45 BRO	SP	CCA		V		3/30/2031
2021 PO3623333549	KU	3	45 BRO	SP	CCA		V		3/31/2031
2021 PO3655733953	KU	3	45 BRO	SP	CCA		V		4/1/2031
2021 PO4006583705	LGE	3	50 BRO	SP	A	ED,ID	TD		4/2/2031
2021 PO4007283716	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		4/3/2031
2021 PO4106885962	LGE	4	40 ACE	SP	A		V		4/4/2031
2021 PO8216771976	LGE	3	45 ACE	SP	CCA		V		4/5/2031
2021 PO4108986012	LGE	4	40 ACE	SP	P	ED,ID	TD		4/6/2031
2021 PO8388566966	KU	3	50 ACE	SP	CCA		V		4/7/2031
2021 PO8388366979	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		4/8/2031
2021 PO8388166992	KU	4	45 ACE	SP	CRE	ED,ID	BD		4/9/2031
2021 PO4008683699	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		4/10/2031
2021 PO8391867126	KU	3	45 ACE	SP	CCA		V		4/11/2031
2021 PO8384767193	KU	3	50 ACE	SP	CRE	ED,ID	TD		4/12/2031
2021 PO8825896404	KU	3	45 KOP	SP	CRE	ED,ID	TD		4/13/2031
2021 PO5992985251	KU	4	45 ACE	SP	CCA		V		4/14/2031
2021 PO6006385455	KU	4	45 ACE	SP	CRE	ID,IP	TX	RR	4/15/2031
2021 PO6036185448	KU	4	45 ACE	SP	CRE	ID	BD		4/16/2031
2021 PO8217071999	LGE	3	45 ACE	SP	CRE		V		4/17/2031
2021 PO4107485994A1	KU	4	35 ACE	SP	A	ID	BD		4/18/2031
2021 PO1842986109	KU	4	40 BRO	SP	CRE	ID	TX	RR	4/19/2031
2021 PO8914995933	KU	4	45 BRO	SP	CRE	ED,ID	BD		4/20/2031
2021 PO2976995235	KU	7	30 ACE	SP	CCA		V		4/21/2031
2021 PO8908895818	KU	5	35 BRO	SP	CRE	ED,ID,IP	BD		4/22/2031
2021 PO8908695577	KU	2	55 BRO	SP	CRE	ED	TD		4/23/2031
2021 PO8902495710	KU	4	40 KOP	SP	CRE	ED,ID,IP	TD		4/24/2031
2021 PO8891795633	KU	5	35 BRN	SP	P	ED,ID	TD		4/25/2031
2021 PO8855495696	KU	6	30 BRN	SP	CRE	ED,EP,ID	TX	RR	4/26/2031
2021 PO8898095880	KU	3	45 BRN	SP	CCA		V		4/27/2031
2021 PO8891495769	KU	3	45 BRN	SP	CCA		V		4/28/2031
2021 PO8882395860	KU	3	45 BRN	SP	CCA		V		4/29/2031
2021 PO8876996047	KU	3	45 KOP	SP	CCA		V		4/30/2031
2021 PO8876796014	KU	4	45 KOP	SP	CRE	ED,ID,IP	TD		5/1/2031
2021 PO8847895989	KU	4	40 KOP	SP	CRE	ED,ID	TD		5/2/2031
2021 PO8868395921	KU	4	40 KOP	SP	CRE	ED,ID	TD		5/3/2031
2021 PO8970095495	KU	6	30 BRO	SP	CCA		V		5/4/2031
2021 PO5295426931	KU	2	50 UNK	SP	CRE		B		5/5/2031
2021 PO5278626933	KU	2	45 UNK	SP	CRE		B		5/6/2031
2021 PO8956395415	KU	3	45 BRO	SP	CCA		V		5/7/2031
2021 PO8958795312	KU	4	45 KOP	SP	CRE	ED,ID	BD		5/8/2031
2021 PO8962395335	KU	4	40 KOP	SP	CRE	ED,ID	BD		5/9/2031
2021 PO8942195055	KU	4	40 BRO	SP	CRE		V		5/10/2031

2021 PO8916495322	KU	4	45 KOP	SP	CRE		ED,ID	BD	5/11/2031	
2021 PO5314026935	KU	3	45 UNK	SP	CRE			B	5/12/2031	
2021 PO5315726936	KU	3	45 UNK	SP	CRE			B	5/13/2031	
2021 PO2630194432	KU	3	50 BRN	SP	CRE		ED	TD	5/14/2031	
2021 PO2622894673	KU	4	45 BRN	SP	CCA			V	5/15/2031	
2021 PO5440227007	KU	3	50 UNK	SP	CRE			T	5/16/2031	
2021 PO5440326970	KU	2	45 UNK	SP	CRE			B	5/17/2031	
2021 PO5437827133	KU	3	45 UNK	SP	CCA			V	5/18/2031	
2021 PO5412927003	KU	3	45 UNK	SP	CCA			V	5/19/2031	
2021 PO5403727165	KU	3	45 UNK	SP	CRE			T	5/20/2031	
2021 PO2662894651	KU	5	40 ACE	SP	CCA			V	5/21/2031	
2021 PO2647594527	KU	3	40 ACE	SP	CCA			V	5/22/2031	
2021 PO8413367558	KU	6	30 ACE	SP	CCA			V	5/23/2031	
2021 PO2735694768	KU	4	40 ACE	SP	CRE		ED,SRS	TD	5/24/2031	
2021 PO5404626959	KU	3	45 UNK	SP	CCA			V	5/25/2031	
2021 PO5404826902	KU	6	30 UNK	SP	CRE			B	5/26/2031	
2021 PO1663689262	KU	4	40 BRO	SP	CRE		ID	TD	5/27/2031	
2021 PO1697789611	KU	4	40 BRO	SP	CRE		ID	BD	5/28/2031	
2021 PO4104986004	LGE	3	45 ACE	SP	CCA			V	5/29/2031	
2021 PO2450888211	KU	4	40 KOP	SP	CRE		ED,ID	TD	5/30/2031	
2021 PO5379926936	KU	4	60 UNK	SP	CRE			B	5/31/2031	
2021 PO5385126858	KU	2	45 UNK	SP	CRE			B	6/1/2031	
2021 PO5360326727	KU	3	45 UNK	SP	CRE			T	6/2/2031	
2021 PO4106085992	LGE	4	40 ACE	SP	P		ED,ID	BD	6/3/2031	
2021 PO4105785984	LGE	4	35 ACE	SP	CRE		ID	BD	6/4/2031	
2021 PO2731494844b	KU	4	40 BRN	SP	CCA			V	6/5/2031	
2021 PO5326985484	KU	6	35 XXX	SP	CRE		HH,ID	TX	RR	6/6/2031
2021 PO5314185379	KU	3	45 XXX	SP	CCA			V	6/7/2031	
2021 PO5317485231	KU	4	45 XXX	SP	CRE		ID,IP	TD	6/8/2031	
2021 PO5321384930	KU	3	45 BRN	SP	CRE			V	6/9/2031	
2021 PO5334584702	F	6	30 BRN	SP	CCA			V	6/10/2031	
2021 PO8032682453	KU	5	35 BRO	SP	CRE		ED,ID	TD	6/11/2031	
2021 PO8010882392	KU	5	35 BRO	SP	CRE		ED,ID	BD	6/12/2031	
2021 PO8049282229	KU	5	45 BRO	SP	CRE		ED,ID	BD	6/13/2031	
2021 PO4190086464	LGE	3	40 BRO	SP	CRE		ID,IP	BD	6/14/2031	
2021 PO4190586457	LGE	4	40 BRO	SP	CRE		ID	BD	6/15/2031	
2021 PO4190786453	LGE	4	40 BRO	SP	CRE		ED,ID	TD	6/16/2031	
2021 PO8033281847	KU	4	40 BRO	SP	CRE		ED,ID	BD	6/17/2031	
2021 PO4184286429	LGE	4	40 BRO	SP	CCA			V	6/18/2031	
2021 PO4184286443	LGE	4	45 BRO	SP	CCA			V	6/19/2031	
2021 PO7558982597	KU	4	40 BRO	SP	CRE		ED,ID	TD	6/20/2031	
2021 PO7602582005	KU	4	40 BRO	SP	CRE		ED,ID	TD	6/21/2031	
2021 PO7563482235	KU	4	45 BRO	SP	CRE		ED,ID	TD	6/22/2031	
2021 PO4127186302	LGE	4	40 BRN	SP	CCA			V	6/23/2031	
2021 PO4123986304	LGE	4	40 BRN	SP	P		ED,ID	BD	6/24/2031	
2021 PO4125786303	LGE	4	40 BRN	SP	P		ED,ID	BD	6/25/2031	
2021 PO4130586299	LGE	4	40 BRN	SP	CRE		ID	BD	6/26/2031	
2021 PO417786646	LGE	4	35 BRO	SP	A		ED,ID	TD	6/27/2031	
2021 PO0978352339	KU	4	40 BRN	SP	CRE		ID	BD	6/28/2031	
2021 PO4177186635	LGE	4	40 BRO	SP	A		ED,ID	TD	6/29/2031	
2021 PO4176386641	LGE	4	30 BRO	SP	A		ED,ID	TD	6/30/2031	
2021 PO0938551633	KU	5	35 BRN	SP	CRE		HH,ID,IP	BD	7/1/2031	
2021 PO4130786283	LGE	4	40 BRN	SP	P		ID	TD	7/2/2031	
2021 PO4131086294	LGE	4	30 BRN	SP	CRE		ID	TD	7/3/2031	

2021 PO4131186298	LGE	4	40 BRN	SP	P	ID,SRS	TD		7/4/2031
2021 PO5166504588	KU	4	40 BRN	SP	CRE	ED,ID	TD		7/5/2031
2021 PO4421509018	F	4	40 XXX	SP	CRE		V		7/6/2031
2021 PO4414709134	F	4	40 XXX	SP	CRE		V		7/7/2031
2021 PO0806251653	KU	4	40 BRN	SP	CRE	ID	TD		7/8/2031
2021 PO0898551127	KU	6	35 BRN	SP	CRE	ID	BD		7/9/2031
2021 PO8370274773	LGE	4	35 BRN	SP	CCA		V		7/10/2031
2021 PO4124786290	LGE	4	35 BRN	SP	S		V		7/11/2031
2021 PO8381074845	LGE	4	35 BRN	SP	CCA		V		7/12/2031
2021 PO4127886292	LGE	4	30 BRN	SP	CCA		V		7/13/2031
2021 PO4129186290	LGE	4	40 BRN	SP	CRE	ID,SRS	TD		7/14/2031
2021 PO4129886289	LGE	4	30 BRN	SP	CRE	ID,IP,RB	X	RP2	7/15/2031
2021 PO4122686306	LGE	4	40 BRN	SP	P	ID	TD		7/16/2031
2021 PO0863950540A1	KU	7	20 BRN	SP	P	ID	BD		7/17/2031
2021 PO0872059835A1	KU	6	30 BRN	SP	CRE	ID	BD		7/18/2031
2021 PO0872050835	KU	4	40 BRN	SP	CRE	ID	BD		7/19/2031
2021 PO0863950540	KU	4	40 BRN	SP	CRE	ID	BD		7/20/2031
2021 PO4483008028	F	4	40 XXX	SP	P		V		7/21/2031
2021 PO4491308232	F	4	40 XXX	SP	P		V		7/22/2031
2021 PO4471608077	F	4	40 XXX	SP	CRE		V		7/23/2031
2021 PO4458008132	F	4	45 KOP	SP	P		V		7/24/2031
2021 PO5190004572	KU	5	35 BRN	SP	CRE	ED,ID,RB	X	PX	7/25/2031
2021 PO7576681695	KU	6	30 BRO	SP	CRE	ED,ID	TD		7/26/2031
2021 PO7584081629	KU	4	40 BRO	SP	CRE	ED,ID	BD		7/27/2031
2021 PO7573581788	KU	4	45 BRO	SP	CRE	ED,ID	BD		7/28/2031
2021 PO0808251217	KU	3	45 BRN	SP	CRE		V		7/29/2031
2021 PO0809651368	KU	3	45 BRN	SP	CRE		V		7/30/2031
2021 PO7513582032	KU	4	40 BRO	SP	CRE	ED,ID	BX	RP2	7/31/2031
2021 PO0830551381	KU	4	40 BRN	SP	CCA		V		8/1/2031
2021 PO0805650317	KU	6	30 BRN	SP	CRE	ID	TD		8/2/2031
2021 PO0799450434	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/3/2031
2021 PO00807850496	KU	6	35 BRN	SP	CCA	ED,ID	BD		8/4/2031
2021 PO4107185748	LGE	3	50 BRN	SP	CCA		V		8/5/2031
2021 PO4106785741	LGE	4	35 BRN	SP	P		B		8/6/2031
2021 PO5207205615	KU	2	35 BRN	SP	CRE	ED,ID	TD		8/7/2031
2021 PO5219905702	F	6	30E BRN	SP	CRE		V		8/8/2031
2021 PO5214405617	F	7	30E BRN	SP	P		V		8/9/2031
2021 PO5221905735	F	7	30E BRN	SP	CRE		V		8/10/2031
2021 PO1245849946	KU	4	40 BRN	SP	CRE	ID	BD		8/11/2031
2021 PO1245950350	KU	4	40 BRN	SP	CRE	ID	BD		8/12/2031
2021 PO6714019333	KU	4	40 ACW	SP	CRE	ED,ID	TD		8/13/2031
2021 PO6734419372	KU	4	40 ACW	SP	CRE	ED,ID	TD		8/14/2031
2021 PO5207405509	F	7	30E BRN	SP	P	ED,ID,RB	BX	RP1	8/15/2031
2021 PO4343798898	KU	4	40 UNK	SP	CCA		V		8/16/2031
2021 PO1247149647	KU	4	45 BRN	SP	CRE	ID	BD		8/17/2031
2021 PO1222749418	KU	4	40 BRN	SP	CRE	ID	BD		8/18/2031
2021 PO4107585726	LGE	4	35 BRN	SP	P	ID,MD	TD		8/19/2031
2021 PO4112985781	LGE	3	45 BRN	SP	CRE	ED,HH,ID	BX	RP2	8/20/2031
2021 PO7856081216	KU	4	40 BRO	SP	CRE	ED,ID	BD		8/21/2031
2021 PO7876681181	KU	4	40 BRO	SP	CRE	ED,ID	TD		8/22/2031
2021 PO1201449201	KU	4	40 BRN	SP	CRE	ID	BD		8/23/2031
2021 PO4106285732	LGE	3	45 BRN	SP	CRE	ID,IP	BD		8/24/2031
2021 PO4112085804	LGE	4	35 BRN	SP	CRE	ID	BD		8/25/2031
2021 PO8236669725	LGE	1	50 BRN	SP	CCA		V		8/26/2031

2021 PO4114085774	F	7	30 BRN	SP	CRE		V	8/27/2031
2021 PO4109985798	LGE	3	50 BRN	SP	CRE	ED,ID,IP	BD	8/28/2031
2021 PO4111285791	LGE	2	55 BRN	SP	CRE	ED,ID	BD	8/29/2031
2021 PO4111685788	LGE	2	55 BRN	SP	CRE	ED,ID	BD	8/30/2031
2021 PO4113785794	LGE	4	40 BRN	SP	CRE	ID	BD	8/31/2031
2021 PO4113585778	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	9/1/2031
2021 PO5175805182	F	6 35E	BRN	SP	CCA		V	9/2/2031
2021 PO5198205353	KU	2	35 BRN	SP	CRE	ED,ID,IP	TD	9/3/2031
2021 PO1158849342	KU	4	40 BRN	SP	CRE	ID	BD	9/4/2031
2021 PO1177749279	KU	4	40 BRN	SP	CRE	ID	BD	9/5/2031
2021 PO7857781381	F	4	40 BRO	SP	CCA		V	9/6/2031
2021 PO1131047513	KU	4	40 BRN	SP	CRE	ID	BD	9/7/2031
2021 PO8359985079	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/8/2031
2021 PO1047147004	KU	4	40 BRN	SP	CRE		V	9/9/2031
2021 PO1086447283	KU	4	40 BRN	SP	CCA		V	9/10/2031
2021 PO1046947252	KU	4	40 BRN	SP	CRE	ID	BD	9/11/2031
2021 PO0872548586	KU	4	45 BRN	SP	CRE	ID	BD	9/12/2031
2021 PO4197886329	LGE	3	45 BRO	SP	A	ED,ID	TD	9/13/2031
2021 PO8359085445A	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/14/2031
2021 8382885215A	KU	5	40 BRO	SP	CRE	ED,ID	TD	9/15/2031
2021 PO8359085445	KU	4	45 BRO	SP	CCA		V	9/16/2031
2021 PO8382885215	KU	4	40 BRO	ST	P		V	9/17/2031
2021 PO4198386332	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	9/18/2031
2021 PO4198786333	LGE	4	35 BRO	SP	CCA		V	9/19/2031
2021 PO4197786326	LGE	4	40 BRO	SP	CCA		V	9/20/2031
2021 PO8924378093	LGE	4	30 BRO	SP	CRE		V	9/21/2031
2021 PO8920678117	LGE	4	30 BRO	SP	CRE		V	9/22/2031
2021 PO8920378145	LGE	4	30 BRO	SP	CRE		V	9/23/2031
2021 PO4178786626	LGE	4	35 BRO	SP	CRE		V	9/24/2031
2021 PO5181105225	KU	3	50 BRN	SP	CRE	ED,ID	TD	9/25/2031
2021 PO5228205539	F	5	35 BRN	SP	CCA		V	9/26/2031
2021 PO6841918605	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	9/27/2031
2021 PO4128686081	LGE	4	40 BRN	SP	CRE	ID,IP	BD	9/28/2031
2021 PO4128286062	LGE	4	40 BRN	SP	CRE	ID,SRS	TD	9/29/2031
2021 PO4127686051	LGE	4	40 BRN	SP	CCA		V	9/30/2031
2021 PO4127486047	LGE	4	40 BRN	SP	CRE	ID	TD	10/1/2031
2021 PO4126486052	LGE	3	45 BRN	SP	CCA		V	10/2/2031
2021 PO4128286042	LGE	4	40 BRN	SP	P	ID,SRS	TD	10/3/2031
2021 PO4131586022	LGE	4	45 BRN	SP	P	ED,ID	TD	10/4/2031
2021 PO4129186037	LGE	4	40 BRN	SP	CCA		V	10/5/2031
2021 PO4129986032	LGE	3	45 BRN	SP	CCA		V	10/6/2031
2021 PO8434472029	LGE	3	45 BRN	SP	CCA		V	10/7/2031
2021 PO4130686027	LGE	1	50 BRN	SP	CCA		V	10/8/2031
2021 PO4132185980	LGE	2	55 BRN	SP	CRE	ID,IP	BD	10/9/2031
2021 PO6741519029	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/10/2031
2021 PO6736418878	KU	6	30 ACW	SP	CRE	ED,ID	TD	10/11/2031
2021 PO6734419372A	KU	7	30 ACW	SP	CRE	ED,ID	BD	10/12/2031
2021 PO6743819533	KU	5	35 ACW	SP	CRE	ED,ID	TD	10/13/2031
2021 PO4132685988	LGE	2	75 BRN	ST	P		V	10/14/2031
2021 PO4130085985	LGE	4	40 BRN	SP	P	ID	BD	10/15/2031
2021 PO4128985989	LGE	3	75 BRN	SP	CRE		V	10/16/2031
2021 PO4131585995	LGE	1	75 BRN	ST	P		V	10/17/2031
2021 PO4130386002	LGE	1	70 BRN	ST	P		V	10/18/2031
2021 PO4127685978	LGE	1	75 BRN	SP	CRE		V	10/19/2031

2021 PO4127085972	LGE	5	25 BRN	SP	CRE	ID	TD	10/20/2031
2021 PO5231405590	F	6	35 BRN	SP	CCA		V	10/21/2031
2021 PO5237505678	F	6	35 BRN	SP	CCA		V	10/22/2031
2021 PO5244105707	KU	6	35 BRN	SP	CRE	ED,ID	TD	10/23/2031
2021 PO5244305780	F	3	40 BRN	SP	CRE	ED	V	10/24/2031
2021 PO5246305822	KU	7	35 BRN	SP	CRE	ED,ID	TD	10/25/2031
2021 PO4127185971	LGE	3	45 BRN	SP	S		V	10/26/2031
2021 PO4122885941	LGE	4	40 BRN	SP	P	ID	TD	10/27/2031
2021 PO4122885943	F	4	30 BRN	SP	CCA		V	10/28/2031
2021 PO4116785898	LGE	6	30E BRN	SP	CRE	ID,IP	BD	10/29/2031
2021 PO1162849950	KU	4	40 BRN	SP	CRE	ID	BD	10/30/2031
2021 PO5240606065	KU	6	35 BRN	SP	CCA		V	10/31/2031
2021 PO1147050693	KU	4	45 BRN	SP	CRE	ID	BD	11/1/2031
2021 PO4119485927	F	3	45 BRN	SP	CRE	ED,HH	BX	RP2 11/2/2031
2021 PO4120185932	F	3	45 BRN	SP	CRE		V	11/3/2031
2021 PO4120785937	F	3	45 BRN	SP	CRE		V	11/4/2031
2021 PO4121785944	F	3	45 BRN	SP	CRE		V	11/5/2031
2021 PO4122285948	F	3	45 BRN	SP	CRE		V	11/6/2031
2021 PO4123585958	LGE	3	45 BRN	SP	CRE	ID	BD	11/7/2031
2021 PO4124285963	F	4	45 BRN	SP	CRE	ED,ID	V	11/8/2031
2021 PO4125385971	F	3	45 BRN	SP	P		V	11/9/2031
2021 PO4126585981	F	3	45 BRN	SP	CCA		V	11/10/2031
2021 PO4126185989	LGE	1	70 BRN	ST	P		V	11/11/2031
2021 PO4127085985	F	4	40 BRN	SP	CRE	IP	V	11/12/2031
2021 PO4127485987	F	4	40 BRN	SP	CRE		V	11/13/2031
2021 PO4128285993	F	4	35 BRN	SP	CCA		V	11/14/2031
2021 PO2110432651	KU	4	40 BRN	SP	CRE	ED,EP,ID,RB	X	PX 11/15/2031
2021 PO2587416756	KU	2	50 BRN	SP	CRE		V	11/16/2031
2021 PO5263006544	KU	7	35 BRN	SP	CCA		V	11/17/2031
2021 PO4114985882	LGE	4	40 BRN	SP	P	ID	TD	11/18/2031
2021 PO4113985870	LGE	4	35 BRN	SP	CRE		V	11/19/2031
2021 PO3716999479	KU	6	30 UNK	SP	CRE	ID,IP	TD	11/20/2031
2021 PO8276471401	F	3	45 BRN	SP	CCA		V	11/21/2031
2021 PO5257606393	KU	2	35 BRN	SP	CRE	ED,ID	TD	11/22/2031
2021 PO5240506202	KU	6	30 BRN	SP	CRE	ED,ID	TD	11/23/2031
2021 PO4110785811	LGE	3	45 BRN	SP	P	ID	BD	11/24/2031
2021 PO1154748530	KU	4	40 BRN	SP	CRE	ID	BD	11/25/2031
2021 PO1149048360	KU	4	40 BRN	SP	CRE	ID	BD	11/26/2031
2021 PO1136548350	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	11/27/2031
2021 PO4113485835	LGE	3	45 BRN	SP	P	ID	BD	11/28/2031
2021 PO5249306166	KU	2	35 BRN	SP	CRE	ED,EP,ID,IP	BX	PX 11/29/2031
2021 PO3719899586-A	KU	5	35 UNK	SP	CRE	ID	TD	11/30/2031
2021 PO1139650419	KU	4	45 BRN	SP	CRE	ED,HH,ID,MD	BD	12/1/2031
2021 PO4107785758	LGE	3	45 BRN	SP	CRE	ED,HH,ID	X	PX 12/2/2031
2021 PO1139650419a1	KU	4	40 BRN	SP	CRE	ID	BD	12/3/2031
2021 PO1127049937	KU	4	40 BRN	SP	CRE	ID	BD	12/4/2031
2021 PO1129749407	KU	4	40 BRN	SP	CRE	ID	BD	12/5/2031
2021 PO3982600053	KU	3	40 UNK	SP	CCA		V	12/6/2031
2021 PO3954499996	KU	3	40 UNK	SP	CCA		V	12/7/2031
2021 PO3928599943	KU	3	50 UNK	SP	CCA		V	12/8/2031
2021 PO3900899876	KU	3	40 UNK	SP	CCA		V	12/9/2031
2021 PO3875599826	KU	3	40 UNK	SP	CCA		V	12/10/2031
2021 PO3850099775	KU	3	40 UNK	SP	CCA		V	12/11/2031
2021 PO3716599724	KU	3	45 UNK	SP	CCA		V	12/12/2031

2021 PO3740999680	KU	3	45 UNK	SP	CCA		V	12/13/2031
2021 PO3775899622	KU	3	50 UNK	SP	CCA		V	12/14/2031
2021 PO3797799666	KU	3	40 UNK	SP	CCA		V	12/15/2031
2021 PO3824999727	KU	5	35 UNK	SP	CRE		V	12/16/2031
2021 PO5237305833	F	3	40 BRN	SP	CRE		V	12/17/2031
2021 PO5214306001	F	4	40 BRN	SP	CRE		V	12/18/2031
2021 PO5227905901	F	3	40 BRN	SP	P		V	12/19/2031
2021 PO5219005967	F	6	35 BRN	SP	CRE		V	12/20/2031
2021 PO4109285786	LGE	3	50 BRN	SP	P	ID	BD	12/21/2031
2021 PO4108685774	LGE	3	45 BRN	SP	CRE	ED,ID	BD	12/22/2031
2021 PO7843481458	KU	5	35 BRO	SP	CRE	ED,ID	TD	12/23/2031
2021 PO6725919209	KU	6	30 ACW	SP	CRE	ED,ID	BD	12/24/2031
2021 PO6721619124	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/25/2031
2021 PO6751719277	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/26/2031
2021 PO6764619433	KU	6	30 ACW	SP	CRE	ED,ID	TD	12/27/2031
2021 PO6784619092	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/28/2031
2021 PO6769819176	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	12/29/2031
2021 PO1087448088	KU	4	40 BRN	SP	CRE	ID	BD	12/30/2031
2021 PO1104948868	KU	4	40 BRN	SP	CRE	ID	BD	12/31/2031
2021 PO4196786314	LGE	4	40 BRO	SP	CCA		V	1/1/2032
2021 PO4193586286	F	4	40 BRO	SP	CCA		V	1/2/2032
2021 PO4195686305	LGE	3	45 BRO	SP	CCA		V	1/3/2032
2021 PO1099548037	KU	4	45 BRN	SP	CRE	ED,EP,HH,ID	BD	1/4/2032
2021 PO4194286291	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	1/5/2032
2021 PO5168605231	KU	4	40 BRN	SP	CRE	ID	TD	1/6/2032
2021 PO8270185056	KU	4	40 BRO	SP	CRE	ED,ID	TX	RR 1/7/2032
2021 8270186056A	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/8/2032
2021 PO1288445382	KU	3	45 BRN	SP	CRE	ID,IP	BD	1/9/2032
2021 PO1300945822	KU	4	45 BRN	SP	A	ID	BD	1/10/2032
2021 PO4112785785	LGE	3	50 BRN	SP	CRE	ED,HH,ID,RB	BX	RP1 1/11/2032
2021 PO4113185785	LGE	4	40 BRN	SP	P	ED,ID	BD	1/12/2032
2021 PO4114485809	LGE	3	45 BRN	SP	P	ED,ID	BD	1/13/2032
2021 PO4115785717	LGE	4	35 BRN	SP	P	ID	BD	1/14/2032
2021 PO4116385729	LGE	4	35 BRN	SP	P	ID	BD	1/15/2032
2021 PO4194786294	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/16/2032
2021 PO4194986298	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	1/17/2032
2021 PO1191947091a1	KU	6	30 BRN	SP	CRE	ID	BD	1/18/2032
2021 PO1169047423	KU	4	40 BRN	SP	CRE	ID	BD	1/19/2032
2021 PO8331584913	KU	3	50 BRO	SP	CRE	ED,ID	TD	1/20/2032
2021 8359985079A	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/21/2032
2021 PO1154647435	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	1/22/2032
2021 PO1048046735	KU	4	40 BRN	SP	CRE		V	1/23/2032
2021 PO3674999799	KU	4	40 UNK	SP	CCA		V	1/24/2032
2021 PO3719899586	KU	4	40 UNK	SP	A		V	1/25/2032
2021 PO4116385903	F	6	30 BRN	SP	CRE		V	1/26/2032
2021 PO4118585920	F	4	35 BRN	SP	CRE	HH,ID	BX	RP2 1/27/2032
2021 PO4117985915	F	4	35 BRN	SP	P		V	1/28/2032
2021 PO4129085999	F	4	40 BRN	SP	CCA		V	1/29/2032
2021 PO4130086007	F	5	40 BRN	SP	CCA		V	1/30/2032
2021 PO4131086090	LGE	4	35 BRN	SP	P	ID,SRS	TD	1/31/2032
2021 PO4129686085	LGE	3	45 BRN	SP	CRE	ID,SRS	TD	2/1/2032
2021 PO4129586085	LGE	3	45 BRN	SP	CRE	ID,SRS	TD	2/2/2032
2021 PO6815918650	KU	4	40 ACW	SP	CRE	ED,ID	TD	2/3/2032
2021 PO6833218600	KU	4	40 ACW	SP	S		V	2/4/2032

2021 PO1139447418	F	6	35 BRN	SP	CRE	ED,EP,ID,MD	VX	PX	2/5/2032
2021 PO0981855257	KU	5	30 BRO	SP	CRE		VX	RP3	2/6/2032
2021 PO1364245111	KU	5	35 BRN	SP	CRE		VX	RP3	2/7/2032
2021 PO0553850473	KU	4	40 BRO	SP	CRE		VX	RP2	2/8/2032
2021 PO8152791217	KU	5	35 BRO	SP	CCA		V		2/9/2032
2021 PO3446900510	KU	3	50 UNK	SP	CCA		V		2/10/2032
2021 PO8642288928	KU	4	40 BRO	SP	CRE		V		2/11/2032
2021 PO4163586297	LGE	5	25 BRO	SP	CRE		V		2/12/2032
2021 PO0529151156	F	4	40 BRO	SP	CRE		V		2/13/2032
2021 PO0521751076	KU	5	30 BRO	SP	CRE		V		2/14/2032
2021 PO1299845899	F	4	40 BRN	SP	CRE		V		2/15/2032
2021 PO8656887032	F	4	40 BRO	SP	CCA		V		2/16/2032
2021 PO3487100424	KU	3	45 UNK	SP	CCA		V		2/17/2032
2021 PO3507700378	KU	3	45 UNK	SP	CCA		V		2/18/2032
2021 PO4194086238	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		2/19/2032
2021 PO4195486238	LGE	3	45 BRO	SP	A	ED,ID	TD		2/20/2032
2021 PO4195986237	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		2/21/2032
2021 PO4196986237	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		2/22/2032
2021 PO4198286237	LGE	4	35 BRO	SP	A	ED,ID	TD		2/23/2032
2021 PO4198286242	LGE	6	30 BRO	SP	CRE	ED,ID,IP	TD		2/24/2032
2021 PO4198586237	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		2/25/2032
2021 PO2192535563	F	4	40 BRN	SP	CCA		V		2/26/2032
2021 PO2226435750	F	4	40 BRN	SP	CCA		V		2/27/2032
2021 PO2238035911	KU	3	45 BRN	SP	CCA		V		2/28/2032
2021 PO2250035706	KU	3	45 BRN	SP	CCA		V		2/29/2032
2021 PO2260535543	KU	3	45 BRN	SP	CCA		V		3/1/2032
2021 PO2280335234	KU	3	45 BRN	SP	CCA		V		3/2/2032
2021 PO2290135078	KU	3	45 BRN	SP	CCA		V		3/3/2032
2021 PO2298634945	KU	3	45 BRN	SP	CCA		V		3/4/2032
2021 PO2308034813	KU	3	45 BRN	SP	CCA		V		3/5/2032
2021 PO2321434525	F	4	40 BRN	SP	CRE		V		3/6/2032
2021 PO2328534509	KU	3	45 BRN	SP	CCA		V		3/7/2032
2021 PO2344134273	KU	3	45 BRN	SP	CCA		V		3/8/2032
2021 PO2354434063	F	5	40 BRN	SP	CRE		V		3/9/2032
2021 PO2359434041	KU	3	45 BRN	SP	CCA		V		3/10/2032
2021 PO2361934527	KU	3	45 BRN	SP	CRE		V		3/11/2032
2021 PO2372133842	KU	3	45 BRN	SP	CCA		V		3/12/2032
2021 PO2383233685	KU	3	45 BRN	SP	CCA		V		3/13/2032
2021 PO2384633559	KU	3	45 BRN	SP	CCA		V		3/14/2032
2021 PO2395833692	KU	6	30 BRN	SP	CRE		V		3/15/2032
2021 PO2400633325	KU	6	30 BRN	SP	CRE		V		3/16/2032
2021 PO2428632624	KU	3	45 BRN	SP	CCA		V		3/17/2032
2021 PO2433732672	KU	3	45 BRN	SP	CCA		V		3/18/2032
2021 PO2440532305	KU	3	45 BRN	SP	CCA		V		3/19/2032
2021 PO2454532706	KU	3	45 BRN	SP	CCA		V		3/20/2032
2021 PO2459131939	KU	3	45 BRN	SP	CCA		V		3/21/2032
2021 PO2461327231	KU	5	30 BRN	SP	CRE		V		3/22/2032
2021 PO2466427072	KU	4	40 BRN	SP	CRE		V		3/23/2032
2021 PO2472231626	KU	3	45 BRN	SP	CCA		V		3/24/2032
2021 PO2472526773	KU	3	45 BRN	SP	CCA		V		3/25/2032
2021 PO2474727408	KU	3	45 BRN	SP	CCA		V		3/26/2032
2021 PO2475626378	KU	4	45 BRN	SP	CRE		V		3/27/2032
2021 PO2477927678	KU	3	45 BRN	SP	CCA		V		3/28/2032
2021 PO2479531680	KU	5	35 BRN	SP	CCA		V		3/29/2032



2021 PO2480925972	KU	3	45 BRN	SP	CCA		V	3/30/2032
2021 PO2482325567	KU	4	45 BRN	SP	CCA		V	3/31/2032
2021 PO2484727866	KU	3	45 BRN	SP	CCA		V	4/1/2032
2021 PO2486131344	KU	3	45 BRN	SP	CCA		V	4/2/2032
2021 PO2494933528	KU	3	40 BRN	SP	CCA		V	4/3/2032
2021 PO2498230945	KU	4	45 BRN	SP	CCA		V	4/4/2032
2021 PO2500831043	KU	3	45 BRN	SP	CCA		V	4/5/2032
2021 PO2507828293	KU	3	45 BRN	SP	CCA		V	4/6/2032
2021 PO2513233271	KU	3	45 BRN	SP	CCA		V	4/7/2032
2021 PO2529729413	KU	3	45 BRN	SP	CCA		V	4/8/2032
2021 PO3322600789	KU	2	50 UNK	SP	CCA		V	4/9/2032
2021 PO3359300708	KU	4	45 UNK	SP	CCA		V	4/10/2032
2021 PO3331801220	KU	6	30 UNK	SP	CRE	ID,IP	TD	4/11/2032
2021 PO3333001521	KU	6	30 UNK	SP	CRE	ID,IP	TD	4/12/2032
2021 PO3337401300	KU	6	30 UNK	SP	CRE	ID,IP	TD	4/13/2032
2021 PO3342401164	KU	4	40 UNK	SP	CRE	ID	TD	4/14/2032
2021 PO3370200913	KU	4	40 UNK	SP	CRE	ID,IP	TD	4/15/2032
2021 PO2484233680	KU	5	35 BRN	SP	CRE	ID	BD	4/16/2032
2021 PO4110108923	KU	3	45 BRN	SP	S		V	4/17/2032
2021 PO4118108731	KU	4	45 BRN	SP	S		V	4/18/2032
2021 PO4127908491	KU	3	45 BRN	SP	S		V	4/19/2032
2021 PO4133607743	KU	4	45 BRN	SP	S		V	4/20/2032
2021 PO4135507933	KU	5	35 BRN	SP	S		V	4/21/2032
2021 PO4137308036	KU	4	45 BRN	SP	S		V	4/22/2032
2021 PO4140908447	KU	3	45 BRN	SP	S		V	4/23/2032
2021 PO4144708020	KU	4	45 BRN	SP	S		V	4/24/2032
2021 PO4145307715	KU	4	45 BRN	SP	S		V	4/25/2032
2021 PO4146808325	KU	4	45 BRN	SP	CRE		V	4/26/2032
2021 PO4152707696	KU	4	40 BRN	SP	S		V	4/27/2032
2021 PO4155807902	KU	5	35 BRN	SP	S		V	4/28/2032
2021 PO4158607982	KU	4	45 BRN	SP	S		V	4/29/2032
2021 PO4162207665	KU	4	45 BRN	SP	CRE		V	4/30/2032
2021 PO4169907865	KU	5	35 BRN	SP	S		V	5/1/2032
2021 PO4170108291	KU	3	45 BRN	SP	S		V	5/2/2032
2021 PO4176607970	KU	4	45 BRN	SP	CRE		V	5/3/2032
2021 PO4183008251	KU	3	50 BRN	SP	S		V	5/4/2032
2021 PO4185707585	KU	4	45 BRN	SP	S		V	5/5/2032
2021 PO4185808062	KU	4	45 BRN	SP	CRE		V	5/6/2032
2021 PO4187507894	KU	5	35 BRN	SP	S		V	5/7/2032
2021 PO4189508163	KU	3	50 BRN	SP	S		V	5/8/2032
2021 PO4192808128	KU	3	50 BRN	SP	S		V	5/9/2032
2021 PO4197307518	KU	4	45 BRN	SP	S		V	5/10/2032
2021 PO4198707756	KU	5	35 BRN	SP	S		V	5/11/2032
2021 PO4205007967	KU	3	50 BRN	SP	S		V	5/12/2032
2021 PO4208507456	KU	4	45 BRN	SP	S		V	5/13/2032
2021 PO4214307664	KU	5	35 BRN	SP	S		V	5/14/2032
2021 PO4221707379	KU	4	45 BRN	SP	S		V	5/15/2032
2021 PO4227407581	KU	5	35 BRN	SP	S		V	5/16/2032
2021 PO4230706447	KU	3	50 BRN	SP	CRE		V	5/17/2032
2021 PO4233407669	KU	3	50 BRN	SP	S		V	5/18/2032
2021 PO4234607313	KU	4	45 BRN	SP	S		V	5/19/2032
2021 PO4235606580	KU	3	50 BRN	SP	CRE		V	5/20/2032
2021 PO4237706524	KU	3	45 BRN	SP	CRE		V	5/21/2032
2021 PO4239507512	KU	5	35 BRN	SP	S		V	5/22/2032

2021 PO4244807610	KU	3	50 BRN	SP	S		V	5/23/2032
2021 PO4245206685	KU	3	50 BRN	SP	CRE		V	5/24/2032
2021 PO4246807248	KU	4	45 BRN	SP	S		V	5/25/2032
2021 PO4252006717	KU	3	50 BRN	SP	CRE		V	5/26/2032
2021 PO4254207438	KU	5	35 BRN	SP	S		V	5/27/2032
2021 PO4257307108	KU	5	35 BRN	SP	CCA		V	5/28/2032
2021 PO4257907545	KU	3	50 BRN	SP	S		V	5/29/2032
2021 PO4260707174	KU	4	45 BRN	SP	S		V	5/30/2032
2021 PO4266806786	KU	3	50 BRN	SP	CRE		V	5/31/2032
2021 PO4269907361	KU	5	35 BRN	SP	S		V	6/1/2032
2021 PO4272207469	KU	3	50 BRN	SP	S		V	6/2/2032
2021 PO4276807095	KU	4	45 BRN	SP	S		V	6/3/2032
2021 PO4279907430	KU	3	50 BRN	SP	S		V	6/4/2032
2021 PO4283006861	KU	3	50 BRN	SP	CRE		V	6/5/2032
2021 PO4290407254	KU	5	35 BRN	SP	S		V	6/6/2032
2021 PO4291807016	KU	3	50 BRN	SP	S		V	6/7/2032
2021 PO4293807357	KU	3	50 BRN	SP	S		V	6/8/2032
2021 PO4298506990	KU	3	45 BRN	SP	S		V	6/9/2032
2021 PO4301607190	KU	3	50 BRN	SP	S		V	6/10/2032
2021 PO4307207285	KU	2	55 BRN	SP	S		V	6/11/2032
2021 PO4321907136	KU	4	45 BRN	SP	S		V	6/12/2032
2021 PO4327507074	KU	3	45 BRN	SP	S		V	6/13/2032
2021 PO4333606947	KU	4	45 BRN	SP	S		V	6/14/2032
2021 PO4337806744	KU	3	45 BRN	SP	CCA		V	6/15/2032
2021 PO4338506708	F	4	45 BRN	SP	S		V	6/16/2032
2021 PO4338806677	KU	3	45 BRN	SP	CCA		V	6/17/2032
2021 PO4802206441	F	4	40 XXX	SP	CRE		V	6/18/2032
2021 PO4821006444	F	4	40 XXX	SP	P		V	6/19/2032
2021 PO4836806450	F	4	40 XXX	SP	CRE		V	6/20/2032
2021 PO4857906455	F	4	40 XXX	SP	CRE		V	6/21/2032
2021 PO4983902737	KU	3	45 BRN	SP	CCA		V	6/22/2032
2021 PO4987002822	KU	3	45 BRN	SP	CCA		V	6/23/2032
2021 PO5002502408	KU	4	45 BRN	SP	CCA		V	6/24/2032
2021 PO4819106505	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	6/25/2032
2021 PO5000102446	KU	4	45 XXX	SP	CRE	ED,ID	TD	6/26/2032
2021 PO3542707514	KU	3	40 BRN	SP	S		V	6/27/2032
2021 PO3559307484	KU	3	45 BRN	SP	CCA		V	6/28/2032
2021 PO3606907403	KU	3	45 BRN	SP	CCA		V	6/29/2032
2021 PO3619007382	KU	3	45 BRN	SP	CCA		V	6/30/2032
2021 PO3655507313	KU	4	40 BRN	SP	CCA		V	7/1/2032
2021 PO3793407081	KU	3	45 BRN	SP	CCA		V	7/2/2032
2021 PO3809407052	KU	2	50 BRN	SP	CCA		V	7/3/2032
2021 PO3827807016	KU	3	45 BRN	SP	CCA		V	7/4/2032
2021 PO3849706977	KU	4	40 BRN	SP	S		V	7/5/2032
2021 PO3876506935	KU	3	45 BRN	SP	CCA		V	7/6/2032
2021 PO3897006898	KU	3	45 BRN	SP	CCA		V	7/7/2032
2021 PO3915406873	KU	4	40 BRN	SP	CCA		V	7/8/2032
2021 PO3931006850	KU	3	45 BRN	SP	CCA		V	7/9/2032
2021 PO4000706824	KU	4	45 BRN	SP	CCA		V	7/10/2032
2021 PO4000707049	KU	3	45 BRN	SP	CCA		V	7/11/2032
2021 PO4000707244	KU	3	45 BRN	SP	CCA		V	7/12/2032
2021 PO4021006785	KU	3	45 BRN	SP	CCA		V	7/13/2032
2021 PO4037206779	KU	4	40 BRN	SP	CCA		V	7/14/2032
2021 PO4049606774	KU	4	40 BRN	SP	S		V	7/15/2032

2021 PO4061406769	KU	2	50 BRN	SP	S					V	7/16/2032	
2021 PO4091506706	KU	3	50 BRN	SP	S					V	7/17/2032	
2021 PO4116206617	KU	3	50 BRN	SP	S					V	7/18/2032	
2021 PO4128606573	KU	3	50 BRN	SP	S					V	7/19/2032	
2021 PO4144206517	KU	3	50 BRN	SP	S					V	7/20/2032	
2021 PO4162606451	KU	3	50 BRN	SP	S					V	7/21/2032	
2021 PO4192706344	KU	3	50 BRN	SP	S					V	7/22/2032	
2021 PO4211206273	KU	4	45 BRN	SP	S					V	7/23/2032	
2021 PO4222906230	KU	3	50 BRN	SP	S					V	7/24/2032	
2021 PO4003106788	KU	3	45 BRN	SP	CRE		ED,ID,RB			TX	RR	7/25/2032
2021 PO3575407456	KU	4	40 BRN	SP	CRE		ED,ID			TD		7/26/2032
2021 PO3590507429	KU	5	35 BRN	SP	CRE		ED,ID			TD		7/27/2032
2021 PO3638007348	KU	5	35 BRN	SP	CRE		ED,ID			TD		7/28/2032
2021 PO3674507281	KU	5	35 BRN	SP	CRE		ED,ID			TD		7/29/2032
2021 PO3692407252	KU	4	40 BRN	SP	CRE		ED,ID			TD		7/30/2032
2021 PO3707407228	KU	4	40 BRN	SP	CRE		ED,ID			TD		7/31/2032
2021 PO3721007206	KU	5	35 BRN	SP	CRE		ED,ID			TD		8/1/2032
2021 PO3739707175	KU	3	45 BRN	SP	CRE		ED,ID			TD		8/2/2032
2021 PO3755507147	KU	4	40 BRN	SP	CRE		ED,ID			TD		8/3/2032
2021 PO3771707119	KU	5	35 BRN	SP	CRE		ED,ID			TD		8/4/2032
2021 PO3951106822	KU	4	40 BRN	SP	CRE		ID			TD		8/5/2032
2021 PO3967506800	KU	4	40 BRN	SP	CRE		ED,ID			TD		8/6/2032
2021 PO4417405528	KU	2	50 BRN	SP	CCA					V		8/7/2032
2021 PO4403305578	KU	2	50 BRN	SP	CRE					V		8/8/2032
2021 PO4345505782	KU	2	55 BRN	SP	S					V		8/9/2032
2021 PO4507105513	KU	4	40 BRN	SP	S					V		8/10/2032
2021 PO4490105444	KU	3	45 BRN	SP	CCA					V		8/11/2032
2021 PO4514205542	KU	3	45 BRN	SP	S					V		8/12/2032
2021 PO4477405392	KU	4	40 BRN	SP	S					V		8/13/2032
2021 PO4521905601	KU	3	45 BRN	SP	CCA					V		8/14/2032
2021 PO4557905856	F	2	55 BRN	SP	CRE					V		8/15/2032
2021 PO4464505377	KU	4	40 BRN	SP	S					V		8/16/2032
2021 PO4461905430	KU	5	35 BRN	SP	CCA					V		8/17/2032
2021 PO4530605661	KU	4	40 BRN	SP	S					V		8/18/2032
2021 PO4464605478	KU	4	45 BRN	SP	S					V		8/19/2032
2021 PO4181386284	F	4	40 BRO	SP	A					V		8/20/2032
2021 PO4180586297	F	3	45 BRO	SP	CCA					V		8/21/2032
2021 PO0729357378	KU	4	45 BRO	SP	CRE		ED,ID			TD		8/22/2032
2021 PO0737457195	KU	3	45 BRO	SP	CCA					V		8/23/2032
2021 PO0706657379	KU	4	40 BRO	SP	CRE		ED,EP,ID			TD		8/24/2032
2021 PO4184286334	LGE	4	35 BRO	SP	A		ED,ID			TD		8/25/2032
2021 PO0674157410	KU	4	40 BRO	SP	CRE		ED,ID,MD			TD		8/26/2032
2021 PO4182886331	F	4	30 BRO	SP	A					V		8/27/2032
2021 PO0652157429	KU	4	50 BRO	SP	CRE		ED,ID,MD			TD		8/28/2032
2021 PO4182486322	F	4	40 BRO	SP	A					V		8/29/2032
2021 PO4181586314	F	4	40 BRO	SP	CRE					V		8/30/2032
2021 PO4179986307	F	3	45 BRO	SP	A					V		8/31/2032
2021 PO4179186333	LGE	4	30 BRO	SP	A		ED,ID			TD		9/1/2032
2021 PO4179386317	F	4	40 BRO	SP	CRE					V		9/2/2032
2021 PO4178686329	F	4	40 BRO	SP	CRE					V		9/3/2032
2021 PO4178186338	F	4	35 BRO	SP	A					V		9/4/2032
2021 PO4177886353	F	4	40 BRO	SP	A					V		9/5/2032
2021 PO4177486359	F	4	40 BRO	SP	A					V		9/6/2032
2021 PO4177186355	F	4	40 BRO	SP	CCA					V		9/7/2032

2021 PO4567106319	KU	4	45 XXX	SP	CRE	ED,ID	TD	9/8/2032
2021 PO4402905903	KU	4	45 BRN	SP	CCA		V	9/9/2032
2021 PO4569805941	KU	4	45 BRN	SP	CRE	ED,ID,RB	BX PX	9/10/2032
2021 PO4561506455	KU	4	45 XXX	SP	CRE	ED,ID	TD	9/11/2032
2021 PO4548406600	KU	4	45 XXX	SP	CRE	ED,ID	TD	9/12/2032
2021 PO4447105757	KU	2	50 BRN	SP	CCA		V	9/13/2032
2021 PO4419005627	KU	4	45 BRN	SP	CCA		V	9/14/2032
2021 PO4428905645	KU	3	45 BRN	SP	S		V	9/15/2032
2021 PO4420605727	KU	4	45 BRN	SP	S		V	9/16/2032
2021 PO4540606678	KU	4	40 BRN	SP	CCA		V	9/17/2032
2021 PO4535006731	KU	2	50 BRN	SP	CCA		V	9/18/2032
2021 PO4521206877	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/19/2032
2021 PO4515306740	KU	3	45 BRN	SP	CCA		V	9/20/2032
2021 PO4509706612	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/21/2032
2021 PO4579406153	F	4	40 XXX	SP	CRE	ID	BX RP1	9/22/2032
2021 PO4567406055	KU	5	35 BRN	SP	CCA		V	9/23/2032
2021 PO4555806023	KU	3	45 BRN	SP	CCA		V	9/24/2032
2021 PO4499005796	KU	3	45 BRN	SP	CCA		V	9/25/2032
2021 PO4505205634	KU	3	45 BRN	SP	CCA		V	9/26/2032
2021 PO4477905773	KU	4	40 BRN	SP	CCA		V	9/27/2032
2021 PO4487605900	KU	3	45 BRN	SP	CCA		V	9/28/2032
2021 PO4483705937	KU	4	40 BRN	SP	CCA		V	9/29/2032
2021 PO2635428967	KU	3	40 BRN	SP	CRE		V	9/30/2032
2021 PO2617529046	KU	4	45 BRN	SP	CCA		V	10/1/2032
2021 PO0885256388	KU	4	40 BRO	SP	CCA		V	10/2/2032
2021 PO0851456314	KU	4	40 BRO	SP	CRE		V	10/3/2032
2021 PO0758256127	KU	3	45 BRO	SP	CCA		V	10/4/2032
2021 PO0823056566	KU	3	45 BRO	SP	CRE		V	10/5/2032
2021 PO0794556547	KU	4	40 BRO	SP	CRE	ED,ID	BD	10/6/2032
2021 PO0772656368	KU	5	35 BRO	SP	P	ID	BD	10/7/2032
2021 PO0794556547c	KU	4	40 BRO	SP	S		V	10/8/2032
2021 PO3596707362	KU	3	45 BRN	SP	CCA		V	10/9/2032
2021 PO4236706174	KU	2	50 BRN	SP	CRE		V	10/10/2032
2021 PO4253706106	KU	2	50 BRN	SP	CRE		V	10/11/2032
2021 PO4328705841	KU	2	50 BRN	SP	S		V	10/12/2032
2021 PO4379205663	KU	3	50 BRN	SP	CCA		V	10/13/2032
2021 PO4315505887	KU	2	50 BRN	SP	S		V	10/14/2032
2021 PO4284205998	KU	2	50 BRN	SP	S		V	10/15/2032
2021 PO4449905504	KU	2	50 BRN	SP	CCA		V	10/16/2032
2021 PO4362905720	KU	2	55 BRN	SP	S		V	10/17/2032
2021 PO4299305945	KU	2	50 BRN	SP	CRE		V	10/18/2032
2021 PO4433005497	KU	2	50 BRN	SP	CCA		V	10/19/2032
2021 PO4189686304	LGE	4	35 BRO	SP	A	ED,ID,JP,RB	X RP1	10/20/2032
2021 PO2595429611	KU	3	45 BRN	SP	CCA		V	10/21/2032
2021 PO2621028018	KU	3	45 BRN	SP	CCA		V	10/22/2032
2021 PO2617428316	KU	3	45 BRN	SP	CCA		V	10/23/2032
2021 PO2612528713	KU	3	45 BRN	SP	CCA		V	10/24/2032
2021 PO2599529092	KU	3	45 BRN	SP	CCA		V	10/25/2032
2021 PO2589429403	KU	3	45 BRN	SP	CCA		V	10/26/2032
2021 PO2580029702	KU	3	40 BRN	SP	CCA		V	10/27/2032
2021 PO2563329910	KU	3	45 BRN	SP	CCA		V	10/28/2032
2021 PO3538623437	F	4	40 KOP	SP	P		V	10/29/2032
2021 PO3548223524	F	4	40 KOP	SP	P		V	10/30/2032
2021 PO3556023740	F	4	40 XXX	SP	P		V	10/31/2032

2021	PO3569023790	F	4	40 XXX	SP	P	HH,ID,RB	BX	RP1	11/1/2032
2021	PO3588823854	F	4	45 KOP	SP	P		V		11/2/2032
2021	PO3613223743	F	4	45 XXX	SP	P		V		11/3/2032
2021	PO4123984884	LGE	4	45 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	11/4/2032
2021	PO4409402976	KU	3	40 BRN	SP	CRE	ED,ID	TD		11/5/2032
2021	PO4123684882	LGE	4	30 ACE	SP	P	ED,EP,ID	TD		11/6/2032
2021	PO4123384886	LGE	3	50 ACE	SP	P	ED,ID	TD		11/7/2032
2021	PO6441550490	KU	4	40 UNK	SP	CRE	ID	BD		11/8/2032
2021	PO6468350487	KU	5	35 UNK	SP	CRE	ID,SRS	TD		11/9/2032
2021	PO4417002864	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/10/2032
2021	PO4085884695	LGE	4	30 BRO	SP	P	ED,ID	BD		11/11/2032
2021	PO3628023796	F	4	40 XXX	SP	P		V		11/12/2032
2021	PO3634323670	F	4	45 KOP	SP	P		V		11/13/2032
2021	PO3643123553	F	4	40 XXX	SP	P		V		11/14/2032
2021	PO4119484871	LGE	4	45 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	11/15/2032
2021	PO6495350697	KU	5	35 UNK	SP	CRE	ID	BD		11/16/2032
2021	PO6482250812	F	5	35 UNK	SP	A		V		11/17/2032
2021	PO6482650934	KU	6	30 UNK	SP	CCA		V		11/18/2032
2021	PO6463150978	KU	5	35 UNK	SP	CCA		V		11/19/2032
2021	PO6495650861	KU	4	40 UNK	SP	CCA		V		11/20/2032
2021	PO6491951088	KU	4	40 UNK	SP	CRE	ID	TD		11/21/2032
2021	PO4048685485	F	4	30 BRN	SP	CRE		V		11/22/2032
2021	PO4049685498	F	4	40 BRN	SP	CRE		V		11/23/2032
2021	PO4049585485	F	4	40 BRN	SP	CCA		V		11/24/2032
2021	PO4049485473	F	4	40 BRN	SP	CRE		V		11/25/2032
2021	PO4048585462	F	4	25 BRN	SP	CCA		V		11/26/2032
2021	PO4049485462	F	4	40 BRN	SP	P		V		11/27/2032
2021	PO4049485451	F	3	45 BRN	SP	CCA		V		11/28/2032
2021	PO4090585115	LGE	4	40 BRO	SP	CCA		V		11/29/2032
2021	PO4091285125	LGE	4	35 BRO	SP	P	ED,ID	TD		11/30/2032
2021	PO4091885135	LGE	4	35 BRO	SP	CCA		V		12/1/2032
2021	PO4092385146	LGE	4	35 BRO	SP	P	ED,ID	TD		12/2/2032
2021	PO6186341881	F	4	40 BRO	SP	CRE		V		12/3/2032
2021	PO6186741595	F	4	40 BRO	SP	A		V		12/4/2032
2021	PO6102640303	F	4	40 BRO	SP	CRE		V		12/5/2032
2021	PO6069940347	KU	4	40 BRO	SP	CCA		V		12/6/2032
2021	PO4139385010	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		12/7/2032
2021	PO4138085006	LGE	4	40 ACE	SP	CRE	ED,ID	BD		12/8/2032
2021	PO4137184987	LGE	5	30 ACE	SP	CRE	ED,ID	BD		12/9/2032
2021	PO9645017467A	KU	4	40 ACW	SP	S		V		12/10/2032
2021	PO9605018114	KU	4	40 ACW	SP	S		V		12/11/2032
2021	PO9619718114	KU	4	40 ACW	SP	S		V		12/12/2032
2021	PO4052085489	LGE	4	35 BRN	SP	P	ED,ID	TD		12/13/2032
2021	PO4051185482	F	4	40 BRN	SP	CCA		V		12/14/2032
2021	PO4053285493	F	4	40 BRN	SP	CRE		V		12/15/2032
2021	PO4052185485	F	4	40 BRN	SP	CRE		V		12/16/2032
2021	PO4054185500	F	4	40 BRN	SP	CRE		V		12/17/2032
2021	PO4137284999	LGE	3	45 ACE	SP	P	ED,ID	TD		12/18/2032
2021	PO4135884996	LGE	4	40 ACE	SP	CRE	ED,EP,ID	TD		12/19/2032
2021	PO4135784999	LGE	5	35 ACE	SP	CRE	ED,ID	BD		12/20/2032
2021	PO6105539271	F	4	40 BRO	SP	A		V		12/21/2032
2021	PO6092039482	F	4	40 BRO	SP	CCA		V		12/22/2032
2021	PO6082839598	F	4	40 BRO	SP	A		V		12/23/2032
2021	PO6068939796	F	4	40 BRO	SP	A		V		12/24/2032

2021 PO6078640094	KU	4	30 BRO	SP	CCA		V			12/25/2032
2021 PO4135284995	LGE	4	40 ACE	SP	CCA		V			12/26/2032
2021 PO4129885038	LGE	4	40 ACE	SP	CCA		V			12/27/2032
2021 PO4126985020	LGE	3	45 ACE	SP	CCA		V			12/28/2032
2021 PO6066840015	F	4	40 BRO	SP	CRE		V			12/29/2032
2021 PO4091384803	LGE	5	25 BRO	SP	CRE	ED,ID	BD			12/30/2032
2021 PO8055659873	LGE	4	35 BRO	SP	CCA		V			12/31/2032
2021 PO4090484808	LGE	3	45 BRO	SP	CCA		V			1/1/2033
2021 PO8609315319	KU	1	70 ACW	SP	S		V			1/2/2033
2021 PO8579815312	KU	3	50 ACW	SP	CRE		V			1/3/2033
2021 PO8546515311	KU	1	70 ACW	SP	S		V			1/4/2033
2021 PO8546515331	KU	1	65 ACW	SP	S		V			1/5/2033
2021 PO8476715287	KU	2	70 ACW	SP	S		V			1/6/2033
2021 PO8476615307	KU	2	55 ACW	SP	CRE		V			1/7/2033
2021 PO8441715264	KU	2	70 ACW	SP	CRE		V			1/8/2033
2021 PO8317215229	KU	1	70 ACW	ST	CRE		V			1/9/2033
2021 PO8059115050	F	4	40 ACW	SP	CRE	ID,RB	BX	PX		1/10/2033
2021 PO4088785083	LGE	4	35 BRO	SP	P	ED,ID,SRC	X	RP2		1/11/2033
2021 PO4089485095	LGE	4	40 BRO	SP	CCA		V			1/12/2033
2021 PO4142785020	LGE	4	30 ACE	SP	P	ED,ID	BD			1/13/2033
2021 PO4143085016	LGE	4	35 ACE	SP	CRE	ED,ID	TD			1/14/2033
2021 PO4438502915	KU	5	40 BRN	SP	CRE	ED,ID	TD			1/15/2033
2021 PO4077884560	LGE	4	40 BRO	SP	P	ED,ID	TD			1/16/2033
2021 PO4081984630	LGE	4	40 BRO	SP	CRE	ED,ID	TD			1/17/2033
2021 PO4080984612	LGE	4	40 BRO	SP	CCA		V			1/18/2033
2021 PO4080384602	LGE	3	45 BRO	SP	CCA		V			1/19/2033
2021 PO4078684572	LGE	4	40 BRO	SP	CCA		V			1/20/2033
2021 PO4079484587	LGE	4	40 BRO	SP	CRE	ED,ID	TD			1/21/2033
2021 PO4077184548	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX		1/22/2033
2021 PO3598623293	F	4	40 XXX	SP	P		V			1/23/2033
2021 PO4076484536	LGE	4	40 BRO	SP	CRE	ED,ID	BD			1/24/2033
2021 PO3600923230	F	4	40 XXX	SP	P		V			1/25/2033
2021 PO4075784524	LGE	3	45 BRO	DF	CCA		V			1/26/2033
2021 PO8233915210	KU	2	65 ACW	SP	S		V			1/27/2033
2021 PO8270015219	KU	ST	75 ACW	SP	CCA		V			1/28/2033
2021 PO8193015197	KU	1	70 ACW	SP	CRE		V			1/29/2033
2021 PO8186715206	KU	4	40 ACW	SP	S		V			1/30/2033
2021 PO8150815189	KU	2	65 ACW	SP	CRE		V			1/31/2033
2021 PO8117315177	KU	1	70 ACW	SP	CRE		V			2/1/2033
2021 PO8112715175	KU	3	45 ACW	SP	S		V			2/2/2033
2021 PO3503924006	F	4	40 XXX	SP	P		V			2/3/2033
2021 PO3503523892	F	4	40 XXX	SP	P		V			2/4/2033
2021 PO3512423976	F	4	40 XXX	SP	P		V			2/5/2033
2021 PO3521424117	F	4	40 KOP	SP	P		V			2/6/2033
2021 PO4453003266	KU	4	40 BRN	SP	CRE	ED,ID	TD			2/7/2033
2021 PO4473703401	KU	4	45 BRN	SP	CRE	ED,ID,RB	X	PX		2/8/2033
2021 PO5937939497	KU	4	40 BRO	SP	CRE	ED,ID	TD			2/9/2033
2021 PO5926039330	KU	5	35 BRO	SP	CCA		V			2/10/2033
2021 PO5951039716	KU	4	40 BRO	SP	CRE	ED,ID	TD			2/11/2033
2021 PO6269450682	KU	3	40 UNK	SP	A		V			2/12/2033
2021 PO6313150603	KU	5	35 UNK	SP	CRE	ID,IP,SRS	TD			2/13/2033
2021 PO6285350833	KU	4	40 UNK	SP	CRE	ID	BD			2/14/2033
2021 PO4052285404	LGE	4	30 BRN	SP	CCA		V			2/15/2033
2021 PO4053085406	LGE	3	45 BRN	SP	CCA		V			2/16/2033

2021	PO4053485393	F	4	40 BRN	SP	CCA		V		2/17/2033
2021	PO4053285380	F	4	40 BRN	SP	P		V		2/18/2033
2021	PO4053285367	F	4	40 BRN	SP	CRE		V		2/19/2033
2021	PO4053185359	F	4	40 BRN	SP	CCA		V		2/20/2033
2021	PO4391802863	KU	6	40 BRN	SP	CRE	ED,ID	TD		2/21/2033
2021	PO4439803484	KU	5	40 BRN	SP	CRE	ED,ID,RB	TX	RR	2/22/2033
2021	PO4022185411	F	4	40 BRN	SP	CCA		V		2/23/2033
2021	PO4022285424	F	3	45 BRN	SP	CCA		V		2/24/2033
2021	PO4022385433	F	4	40 BRN	SP	CCA		V		2/25/2033
2021	PO3538424230	F	4	40 XXX	SP	P		V		2/26/2033
2021	PO3542024173	F	4	40 XXX	SP	P		V		2/27/2033
2021	PO5969239851	F	4	40 BRO	SP	CCA		V		2/28/2033
2021	PO3559224370	F	4	40 KOP	SP	P		V		3/1/2033
2021	PO3577024342	F	4	40 KOP	SP	P		V		3/2/2033
2021	PO3583524091	F	4	40 KOP	SP	A		V		3/3/2033
2021	PO4126984862	LGE	4	35 ACE	SP	P	ED,ID	BD		3/4/2033
2021	PO4158385582	F	3	45 BRO	SP	CCA		V		3/5/2033
2021	PO4158785582	F	3	45 BRO	SP	CCA		V		3/6/2033
2021	PO4160185580	F	4	40 BRO	SP	CCA		V		3/7/2033
2021	PV4160185581	F	4	45 BRO	SP	P		V		3/8/2033
2021	PO4161485580	F	4	40 BRO	WC	CRE		V		3/9/2033
2021	PO4162885579	F	4	45 BRO	WC	CRE		V		3/10/2033
2021	PO4164285578	F	4	35 BRO	WC	CRE		V		3/11/2033
2021	PO4166085577	LGE	3	45 BRO	SP	CCA		V		3/12/2033
2021	PO4048485448	F	4	25 BRN	SP	CRE		V		3/13/2033
2021	PO4048385437	F	4	25 BRN	SP	CRE		V		3/14/2033
2021	PO4049685446	F	4	45 BRN	SP	P		V		3/15/2033
2021	PO4050585434	F	4	40 BRN	SP	CRE		V		3/16/2033
2021	PO4051385425	F	4	40 BRN	SP	CCA		V		3/17/2033
2021	PO4053385461	F	4	25 BRN	SP	CRE		V		3/18/2033
2021	PO4054485471	F	4	25 BRN	SP	CRE		V		3/19/2033
2021	PO4055685477	F	4	25 BRN	SP	P		V		3/20/2033
2021	PO4059885496	F	4	25 BRN	SP	CRE		V		3/21/2033
2021	PO4062585462	LGE	4	30 BRN	SP	CCA		V		3/22/2033
2021	PO4061885479	F	4	40 BRN	SP	CCA		V		3/23/2033
2021	PO4051085472	F	4	30 BRN	SP	CCA		V		3/24/2033
2021	PO4117984858	LGE	4	40 ACE	SP	CCA		V		3/25/2033
2021	PO4118084850	LGE	4	30 ACE	SP	P	ED,ID	BD		3/26/2033
2021	PO4117184861	LGE	4	40 ACE	SP	CRE	ED,ID	TD		3/27/2033
2021	PO6265242754	KU	4	45 BRO	SP	CRE	ED,ID	BD		3/28/2033
2021	PO6272442872	KU	6	30 BRO	SP	CRE	ED,ID	TD		3/29/2033
2021	PO6284343110	F	4	40 BRO	SP	CCA		V		3/30/2033
2021	PO4441202873	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR	3/31/2033
2021	PO4435802814	KU	4	40 BRN	SP	CRE	ED,ID,RB	X	PX	4/1/2033
2021	PO4432202637	KU	4	40 BRN	SP	CRE	ED,HH,ID,RB	TX	RR	4/2/2033
2021	PO4425202742	KU	4	40 BRN	SP	CRE	ED,ID,RB	X	PX	4/3/2033
2021	PO4439902521	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR	4/4/2033
2021	PO6292743336	F	4	40 BRO	SP	CCA		V		4/5/2033
2021	PO6302143561	F	4	40 BRO	SP	CCA		V		4/6/2033
2021	PO3567923065	F	4	40 XXX	SP	CRE		V		4/7/2033
2021	PO3575923169	F	4	40 XXX	SP	P		V		4/8/2033
2021	PO3578023094	F	4	40 XXX	SP	P		V		4/9/2033
2021	PO4090884823	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX	4/10/2033
2021	PO8000358619	LGE	4	30 BRO	SP	CRE		V		4/11/2033

2021 PO4086084681	LGE	4	30 BRO	SP	CCA	ED,ID	TD	4/12/2033
2021 PO4084884687	LGE	3	45 BRO	SP	CCA		V	4/13/2033
2021 PO7998758561	LGE	4	30 BRO	SP	CCA		V	4/14/2033
2021 PO4084384674	LGE	4	40 BRO	SP	CRE		B	4/15/2033
2021 PO7993758444	LGE	4	30 BRO	SP	CRE		V	4/16/2033
2021 PO4083884664	LGE	4	40 BRO	SP	CRE		B	4/17/2033
2021 PO4083284652	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX	4/18/2033
2021 PO4082584640	LGE	3	45 BRO	SP	CCA		V	4/19/2033
2021 PO6220942365	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/20/2033
2021 PO6223242544	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/21/2033
2021 PO6235542506	F	4	40 BRO	SP	CRE		V	4/22/2033
2021 PO6249342622	F	4	40 BRO	SP	CRE		V	4/23/2033
2021 PO4121384875	LGE	3	50 ACE	SP	P	ED,ID	TD	4/24/2033
2021 PO4404802589	KU	4	40 BRN	SP	CRE	HH,ID	TD	4/25/2033
2021 PO4416102666	KU	5	40 BRN	SP	CRE	ED,ID,IP	TD	4/26/2033
2021 PO4121684871	LGE	4	30 ACE	SP	CCA		V	4/27/2033
2021 PO4088085073	LGE	4	35 BRO	SP	CRE	ED,EP,ID,RB	X	4/28/2033
2021 PO4049385370	F	4	30 BRN	SP	CCA		V	4/29/2033
2021 PO5929839110	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/30/2033
2021 PO4099985237	LGE	4	40 BRO	SP	CCA	ED,ID	TD	5/1/2033
2021 PO6504250226	KU	4	40 UNK	SP	CRE	ID,IP	TD	5/2/2033
2021 PO5924539168	KU	6	30 BRO	SP	CRE	ED,HH,ID,RB	BX	5/3/2033
2021 PO8674715686	KU	4	45 ACW	SP	S		V	5/4/2033
2021 PO8744915356	KU	2	70 ACW	SP	CRE		V	5/5/2033
2021 PO8770015360	KU	2	65 ACW	SP	CRE		V	5/6/2033
2021 PO8815715390	KU	H1	85 ACW	SP	CRE		V	5/7/2033
2021 PO8799415384	KU	2	70 ACW	SP	CRE		V	5/8/2033
2021 PO8672915511	KU	4	40 ACW	SP	S		V	5/9/2033
2021 PO8716315347	KU	3	55 ACW	SP	CRE		V	5/10/2033
2021 PO8687315339	KU	2	65 ACW	SP	CRE		V	5/11/2033
2021 PO8384715262	KU	H1	85 ACW	ST	CRE		V	5/12/2033
2021 PO8402915260A	KU	4	40 ACW	SP	S		V	5/13/2033
2021 PO8402915260	KU	1	75 ACW	ST	S		V	5/14/2033
2021 PO8656615330	KU	H1	85 ACW	SP	CRE		V	5/15/2033
2021 PO8672215336	KU	1	70 ACW	SP	CRE		V	5/16/2033
2021 PO6516650083	KU	4	40 UNK	SP	CRE	ID,IP,SRS	TD	5/17/2033
2021 PO3492424758	F	4	40 XXX	SP	P		V	5/18/2033
2021 PO4098785238	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/19/2033
2021 PO4085284817	LGE	4	40 BRO	SP	CRE	ED,ID	BD	5/20/2033
2021 PO4087484827	LGE	5	25 BRO	SP	CRE	ED,ID	TD	5/21/2033
2021 PO4086484825	LGE	4	40 BRO	SP	CRE	ED,ID	TD	5/22/2033
2021 PO3501124779	F	4	40 XXX	SP	P		V	5/23/2033
2021 PO4392702903	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/24/2033
2021 PO3501524687	F	4	40 XXX	SP	P		V	5/25/2033
2021 PO4378303006	KU	6	40 BRN	SP	CRE	ED,ID	TD	5/26/2033
2021 PO6520149887	KU	6	30 UNK	SP	CRE	ID	TD	5/27/2033
2021 PO6527549957	KU	5	35 UNK	SP	CRE	ID,IP	TD	5/28/2033
2021 PO6537549845	KU	4	40 UNK	SP	CRE	ID	TD	5/29/2033
2021 PO6481650443	KU	4	45 UNK	SP	CCA		V	5/30/2033
2021 PO4165885576	F	4	40 BRO	SP	CCA		V	5/31/2033
2021 PO4166785576	F	4	40 BRO	SP	P		V	6/1/2033
2021 PO4167585576	F	4	35 BRO	SP	CRE		V	6/2/2033
2021 PO4168185576	F	4	35 BRO	SP	CRE		V	6/3/2033
2021 PO4170385575	F	4	40 BRO	SP	CRE		V	6/4/2033



2021 PO4169185575	F	4	40 BRO	SP	CRE		V	6/5/2033
2021 PO4171585574	F	4	40 BRO	WC	CRE		V	6/6/2033
2021 PO4171785470	F	6	35 BRO	SP	CRE		V	6/7/2033
2021 PO4171385471	F	4	40 BRO	SP	CRE		V	6/8/2033
2021 PO4171085470	F	4	40 BRO	SP	CRE		V	6/9/2033
2021 PO4171585489	F	4	40 BRO	SP	CRE		V	6/10/2033
2021 PO4171485478	F	2	45 BRO	SP	CCA		V	6/11/2033
2021 PO4171685501	F	4	40 BRO	SP	CRE		V	6/12/2033
2021 PO4171885514	F	4	40 BRO	SP	CRE		V	6/13/2033
2021 PO4171985527	F	4	40 BRO	SP	CRE		V	6/14/2033
2021 PO4172085538	F	4	40 BRO	SP	CRE		V	6/15/2033
2021 PO4172185550	F	4	40 BRO	SP	CRE		V	6/16/2033
2021 PO4172385572	F	4	40 BRO	SP	CCA		V	6/17/2033
2021 PO4172285562	F	4	40 BRO	SP	CCA		V	6/18/2033
2021 PO3617223395	F	4	40 XXX	SP	P		V	6/19/2033
2021 PO4074284502	LGE	4	40 BRO	SP	CRE	ED,ID	BD	6/20/2033
2021 PO4074984513	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP,RB	BX RP2	6/21/2033
2021 PO4073784498	LGE	3	45 BRO	SP	CCA		V	6/22/2033
2021 PO6503751211	KU	4	45 UNK	SP	CRE	ID,IP	TD	6/23/2033
2021 PO6518551133	KU	4	40 UNK	SP	CCA		V	6/24/2033
2021 PO6522651300	KU	4	45 UNK	SP	CRE	ID,IP	BD	6/25/2033
2021 PO4141685013	LGE	4	30 ACE	SP	P	ED,ID	TD	6/26/2033
2021 PO4140585014	LGE	4	40 ACE	SP	CRE	ED,ID	BD	6/27/2033
2021 PO3633623424	F	4	40 XXX	SP	P		V	6/28/2033
2021 PO3635423232	F	4	40 XXX	SP	P		V	6/29/2033
2021 PO3645623010	F	4	40 XXX	SP	P		V	6/30/2033
2021 PO4089985104	LGE	4	35 BRO	SP	A	ID	TD	7/1/2033
2021 PO6210242225	F	4	40 BRO	SP	CRE		V	7/2/2033
2021 PO6201042223	KU	3	45 BRO	SP	CCA		V	7/3/2033
2021 PO6199642103	F	4	40 BRO	SP	CRE		V	7/4/2033
2021 PO6195042133	F	4	40 BRO	SP	CRE		V	7/5/2033
2021 PO6184642120	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/6/2033
2021 PO4160385594	F	4	35 BRO	SP	CCA		V	7/7/2033
2021 PO4161185589	LGE	4	35 BRO	SP	CRE	ID	TD	7/8/2033
2021 PO5718426783	KU	2	45 BRN	SP	CCA		V	7/9/2033
2021 PO3993184252	LGE	4	40 ACE	SP	CRE	ED,ID	TD	7/10/2033
2021 PO1286798450	F	4	40 KOP	SP	P		V	7/11/2033
2021 PO4001483884	LGE	4	30 BRO	SP	CRE		V	7/12/2033
2021 PO4000583886	F	3	45 BRO	SP	CRE		V	7/13/2033
2021 PO3999683886	F	4	30 BRO	SP	A		V	7/14/2033
2021 PO3999883908	LGE	4	30 BRO	SP	CRE		V	7/15/2033
2021 PO4000483895	F	4	40 BRO	SP	A		V	7/16/2033
2021 PO4084484435	F	4	40 BRO	SP	P		V	7/17/2033
2021 PO4085184443	F	3	45 BRO	SP	CCA		V	7/18/2033
2021 PO4087484454	F	3	50 BRO	SP	CCA		V	7/19/2033
2021 PO4088684462	F	3	50 BRO	SP	CCA		V	7/20/2033
2021 PO4089184465	F	3	50 BRO	SP	CCA		V	7/21/2033
2021 PO8066656541	F	3	50 BRO	SP	CCA		V	7/22/2033
2021 PO4092484485	F	3	50 BRO	SP	CCA		V	7/23/2033
2021 PO4095784506	F	3	45 BRO	SP	P		V	7/24/2033
2021 PO4094084496	F	2	55 BRO	SP	CCA		V	7/25/2033
2021 PO4097284523	F	4	30 BRO	SP	CCA		V	7/26/2033
2021 PO3993584115	F	4	40 ACE	SP	CRE	ED	V	7/27/2033
2021 PO3990384099	LGE	4	30 ACE	SP	CCA		V	7/28/2033

2021 PO3990384089	F	4	30 ACE	SP	CRE	ED	V	7/29/2033
2021 PO4009983770	LGE	5	35 BRO	SP	CCA		V	7/30/2033
2021 PO3993583974	F	4	40 ACE	SP	CRE	ED	V	7/31/2033
2021 PO3993683986	F	3	45 ACE	SP	CCA		V	8/1/2033
2021 PO4500788314	LGE	4	40 BRN	SP	CCA		V	8/2/2033
2021 PO4499488302	LGE	1	50 BRN	SP	CCA		V	8/3/2033
2021 PO3993784001	F	4	40 ACE	SP	P	ED	V	8/4/2033
2021 PO4542613707	LGE	1	50 BRN	SP	CCA		V	8/5/2033
2021 PO4497688276	LGE	3	45 BRN	SP	CCA		V	8/6/2033
2021 PO7392469171	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/7/2033
2021 PO3993884015	F	4	40 ACE	SP	P	ED	V	8/8/2033
2021 PO3993884029	F	4	40 ACE	SP	CRE	ED	V	8/9/2033
2021 PO3993984044	F	3	45 ACE	SP	CCA		V	8/10/2033
2021 PO4010883869	F	4	35 BRO	SP	A		V	8/11/2033
2021 PO4497588255	LGE	3	45 BRN	SP	CCA		V	8/12/2033
2021 PO4497488240	LGE	1	50 BRN	SP	CCA		V	8/13/2033
2021 PO3994084058	F	4	40 ACE	SP	CRE	ED	V	8/14/2033
2021 PO3993384068	F	3	45 ACE	SP	CCA		V	8/15/2033
2021 PO4009983843	F	4	35 BRO	SP	A		V	8/16/2033
2021 PO7413569333	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/17/2033
2021 PO3995284084	F	4	40 ACE	SP	A	ED	V	8/18/2033
2021 PO3994184095	F	4	30 ACE	SP	CRE	ED	V	8/19/2033
2021 PO3994084085	F	3	45 ACE	SP	CCA		V	8/20/2033
2021 PO3992984086	F	2	45 ACE	SP	CCA		V	8/21/2033
2021 PO4497488223	LGE	4	40 BRN	SP	CCA		V	8/22/2033
2021 PO2216391294	KU	4	40 KOP	SP	CRE	ID	TD	8/23/2033
2021 PO4501488199	LGE	1	50 BRN	SP	CCA		V	8/24/2033
2021 PO4501388214	LGE	3	45 BRN	SP	CCA		V	8/25/2033
2021 PO4499988214	LGE	3	45 BRN	SP	CCA		V	8/26/2033
2021 PO2083094546	LGE	4	40 BRN	SP	CCA		V	8/27/2033
2021 PO4498688215	LGE	4	40 BRN	SP	CCA		V	8/28/2033
2021 PO4497488215	LGE	3	45 BRN	SP	CCA		V	8/29/2033
2021 PO4491888244	LGE	3	45 BRN	SP	CCA		V	8/30/2033
2021 PO4490688235	LGE	3	45 BRN	SP	CCA		V	8/31/2033
2021 PO4490588225	LGE	3	45 BRN	SP	CCA		V	9/1/2033
2021 PO4490588210	LGE	3	45 BRN	SP	CCA		V	9/2/2033
2021 PO4490488197	LGE	3	45 BRN	SP	CCA		V	9/3/2033
2021 PO4490488184	LGE	3	45 BRN	SP	CCA		V	9/4/2033
2021 PO4490388171	LGE	3	45 BRN	SP	CCA		V	9/5/2033
2021 PO4492788172	LGE	3	45 BRN	SP	CCA		V	9/6/2033
2021 PO4492788163	LGE	3	45 BRN	SP	CCA		V	9/7/2033
2021 PO4492988198	LGE	3	45 BRN	SP	CCA		V	9/8/2033
2021 PO4493188264	LGE	4	40 BRN	SP	CCA		V	9/9/2033
2021 PO4493088244	LGE	4	40 BRN	SP	CCA		V	9/10/2033
2021 PO4495288217	F	4	40 BRN	SP	A		V	9/11/2033
2021 PO4494888221	F	4	30 BRN	SP	A		V	9/12/2033
2021 PO4494988217	F	3	45 BRN	SP	CCA		V	9/13/2033
2021 PO4494388217	F	4	30 BRN	SP	CRE		V	9/14/2033
2021 PO4009283852	LGE	3	45 BRO	SP	A	ED,ID	BD	9/15/2033
2021 PO7487469903a	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/16/2033
2021 PO4009583852	LGE	3	45 BRO	SP	A	ID	BD	9/17/2033
2021 PO5828625554	F	4	40 ACE	SP	CRE		V	9/18/2033
2021 PO7480167516	KU	4	40 ACE	SP	CRE	ED,ID	BD	9/19/2033
2021 PO5831625498	KU	3	45 ACE	SP	CRE		B	9/20/2033

2021	PO5830125486	KU	4	40 ACE	SP	CRE		B		9/21/2033
2021	PO4501888099	LGE	4	45 BRN	SP	CRE	ED,HH,ID	BX	RR	9/22/2033
2021	PO4003383613	LGE	3	50 BRO	SP	CCA		V		9/23/2033
2021	PO7350951363	LGE	4	35 ACE	SP	CCA	ED	V		9/24/2033
2021	PO7357151470	LGE	4	35 ACE	SP	CCA	ED	V		9/25/2033
2021	PO7458967321	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	9/26/2033
2021	PO4126984505	F	1	55 BRO	SP	CCA		V		9/27/2033
2021	PO4128584517	LGE	3	50 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	9/28/2033
2021	PO5821125400	KU	4	40 ACE	SP	CRE		B		9/29/2033
2021	PO7437467124a	KU	4	40 ACE	SP	CRE	ED,ID	BD		9/30/2033
2021	PO4018583981	LGE	1	60 ACE	SP	CCA		V		10/1/2033
2021	PO7377768495	KU	4	40 ACE	SP	CRE	ED,ID	BD		10/2/2033
2021	PO4010783858	F	4	35 ACE	SP	P	ED	V		10/3/2033
2021	PO4010783864	LGE	4	30 ACE	SP	CCA		V		10/4/2033
2021	PO4022384087	F	4	35 ACE	SP	CCA		V		10/5/2033
2021	PO5851725332	KU	4	40 ACE	SP	CRE		B		10/6/2033
2021	PO5849125463	KU	3	45 ACE	SP	CRE		B		10/7/2033
2021	PO4020984107	LGE	UNK	45 ACE	SP	A	ED	BD		10/8/2033
2021	PO4004783589	LGE	3	45 BRO	SP	CCA		V		10/9/2033
2021	PO5841525444	F	3	40 ACE	SP	CRE		V		10/10/2033
2021	PO5835925502	F	3	40 ACE	SP	CRE		V		10/11/2033
2021	PO5833325516	F	3	40 ACE	SP	CRE		V		10/12/2033
2021	PO5856225385	KU	4	45 ACE	SP	CCA		V		10/13/2033
2021	PO4020784108	LGE	UNK	50 ACE	SP	A	ED,ID	BD		10/14/2033
2021	PO4005183604	LGE	4	40 BRO	SP	A	ID,IP	BD		10/15/2033
2021	PO4004983605	LGE	3	45 BRO	SP	CCA		V		10/16/2033
2021	PO5860725337	KU	3	45 ACE	SP	CRE		B		10/17/2033
2021	PO5866225278	KU	3	45 ACE	SP	CCA		V		10/18/2033
2021	PO5855125295	F	4	40 BRO	SP	CRE		V		10/19/2033
2021	PO5847525377	F	4	40 BRO	SP	CRE		V		10/20/2033
2021	PO4019384109	LGE	UNK	50 ACE	SP	CRE	ED,ID	BD		10/21/2033
2021	PO7365468097	KU	5	35 ACE	SP	CRE	ED,ID	BD		10/22/2033
2021	PO7349968012	KU	4	40 ACE	SP	CRE	ED,ID	BD		10/23/2033
2021	PO4003183603	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		10/24/2033
2021	PO5839925222	KU	5	35 BRO	SP	CRE		T		10/25/2033
2021	PO4016184111	LGE	UNK	50 ACE	SP	A	ED,ID	BD		10/26/2033
2021	PO4138484633	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		10/27/2033
2021	PO4138984640	LGE	4	35 BRO	SP	CRE	ED,ID	TD		10/28/2033
2021	PO4134384587	LGE	4	30 BRO	SP	P	ED,ID	TD		10/29/2033
2021	PO4133984580	LGE	4	30 BRO	SP	P	ED,ID	TD		10/30/2033
2021	PO4135684598	LGE	4	35 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	10/31/2033
2021	PO4131784548	LGE	4	30 BRO	ST	CCA		V		11/1/2033
2021	PO4019684167	LGE	4	35 ACE	SP	P	ED	V		11/2/2033
2021	PO7336567940	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		11/3/2033
2021	PO7328567503	KU	5	35 ACE	SP	CRE	ED,ID	VX	RP1	11/4/2033
2021	PO7309967651	KU	5	35 ACE	SP	CRE	ED,ID	BD		11/5/2033
2021	PO7340867407	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		11/6/2033
2021	PO4021184166	LGE	4	35 ACE	SP	P		V		11/7/2033
2021	PO4018784153	LGE	4	35 ACE	SP	P	ED,ID	BD		11/8/2033
2021	PO4002483598	LGE	3	45 BRO	SP	A	ED,ID	TD		11/9/2033
2021	PO4018684139	LGE	4	35 ACE	SP	P	ED,ID	BD		11/10/2033
2021	PO4021284128	LGE	4	30 ACE	SP	CCA	ED,ID	BD		11/11/2033
2021	PO4021184122	LGE	4	35 ACE	SP	P	ED,ID	BD		11/12/2033
2021	PO2077092058A	KU	3	45 BRO	SP	CCA		V		11/13/2033

2021 PO2077092058	KU	3	45 UNK	SP	CRE	ID	TD	11/14/2033
2021 PO2098191948	KU	4	40 KOP	SP	CRE	ID	TD	11/15/2033
2021 PO2176991538	KU	4	45 KOP	SP	CRE	ED,ID	BX PX	11/16/2033
2021 PO7045272735	KU	2	45 ACE	SP	CCA		V	11/17/2033
2021 PO7041572591	KU	3	45 ACE	SP	CCA		V	11/18/2033
2021 PO4071084361	F	4	40 BRO	SP	CRE		V	11/19/2033
2021 PO4071084378	F	4	40 BRO	SP	CRE		V	11/20/2033
2021 PO4072284368	F	4	40 BRO	SP	CCA		V	11/21/2033
2021 PO4073784368	F	3	50 BRO	SP	P		V	11/22/2033
2021 PO4075384378	F	3	45 BRO	SP	P		V	11/23/2033
2021 PO4077384391	F	3	50 BRO	SP	CCA		V	11/24/2033
2021 PO4078084395	F	4	40 BRO	SP	P		V	11/25/2033
2021 PO4079284399	F	4	35 BRO	SP	P		V	11/26/2033
2021 PO7043072604	KU	3	45 ACE	SP	CCA		V	11/27/2033
2021 PO7036772544	KU	4	45 ACE	SP	CCA		V	11/28/2033
2021 PO7034572305	KU	2	45 ACE	SP	CCA		V	11/29/2033
2021 PO7044872170	KU	3	45 ACE	SP	CCA		V	11/30/2033
2021 PO7051972064	KU	3	45 ACE	SP	CCA		V	12/1/2033
2021 PO7060971945	KU	2	45 ACE	SP	CCA		V	12/2/2033
2021 PO4516388159	LGE	4	40 BRN	SP	CCA		V	12/3/2033
2021 PO4515588171	LGE	3	45 BRN	SP	CCA		V	12/4/2033
2021 PO4514888182	LGE	4	35 BRN	SP	CCA		V	12/5/2033
2021 PO4514288192	LGE	3	45 BRN	SP	CCA		V	12/6/2033
2021 PO4513388205	LGE	3	45 BRN	SP	CCA		V	12/7/2033
2021 PO4512588218	LGE	3	45 BRN	SP	CCA		V	12/8/2033
2021 PO4515088216	LGE	3	50 BRN	SP	CCA		V	12/9/2033
2021 PO4514388227	LGE	3	45 BRN	SP	P	ID	BD	12/10/2033
2021 PO4513488241	LGE	3	45 BRN	SP	A	ID	BD	12/11/2033
2021 PO4511988232	LGE	3	45 BRN	SP	CCA		V	12/12/2033
2021 PO7654174336	KU	4	40 ACE	SP	CRE	ED,ID	BD	12/13/2033
2021 PO7636975048	KU	3	45 ACE	SP	CRE	ED,ID	BD	12/14/2033
2021 PO7636875138	KU	3	55 ACE	SP	CRE	ED,ID	BD	12/15/2033
2021 PO4079284402	F	4	40 BRO	SP	P		V	12/16/2033
2021 PO4079684393	F	4	35 BRO	SP	P		V	12/17/2033
2021 PO4080484410	F	4	40 BRO	SP	P		V	12/18/2033
2021 PO7365568964	KU	4	40 ACE	SP	CRE	ED,ID	TD	12/19/2033
2021 PO4010083848	LGE	4	40 BRO	SP	CCA		V	12/20/2033
2021 PO4510088239	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	BD	12/21/2033
2021 PO4511288246	LGE	4	40 BRN	SP	CCA		V	12/22/2033
2021 PO4089684492	F	4	40 BRO	SP	CRE		V	12/23/2033
2021 PO4082184421	F	2	60 BRO	SP	CCA		V	12/24/2033
2021 PO4083484429	F	4	40 BRO	SP	P		V	12/25/2033
2021 PO4083984432	F	4	40 BRO	SP	P		V	12/26/2033
2021 PO7340168659	F	4	40 ACE	SP	P		V	12/27/2033
2021 PO7330468576	F	4	40 ACE	SP	P		V	12/28/2033
2021 PO7319068485	F	4	40 ACE	SP	P		V	12/29/2033
2021 PO7365168345	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	12/30/2033
2021 PO7310168409	F	4	40 ACE	SP	P		V	12/31/2033
2021 PO5796525006	KU	5	35 ACE	SP	CRE		T	1/1/2034
2021 PO5794825022	KU	3	45 ACE	SP	CCA		V	1/2/2034
2021 PO5785825064	KU	5	35 ACE	SP	CRE		B	1/3/2034
2021 PO0154900024	KU	4	40 KOP	SP	CRE	ID	TD	1/4/2034
2021 PO0143200238	KU	4	45 KOP	SP	CRE	ID	TD	1/5/2034
2021 PO5788825089	KU	4	40 ACE	SP	CCA		V	1/6/2034

2021	PO5795925158	KU	4	40 ACE	SP	CRE			B	1/7/2034
2021	PO5803725233	KU	4	40 ACE	SP	CCA			V	1/8/2034
2021	PO4001383593	LGE	4	30 BRO	SP	CCA			V	1/9/2034
2021	PO0119900430	KU	4	40 KOP	SP	CRE	ID		TD	1/10/2034
2021	PO7300668345	F	4	40 ACE	SP	P			V	1/11/2034
2021	PO4001783639	LGE	2	50 BRO	SP	CRE	ED,ID,IP		TD	1/12/2034
2021	PO7291668293	F	4	40 ACE	SP	P			V	1/13/2034
2021	PO7278168220	F	4	40 ACE	SP	P			V	1/14/2034
2021	PO5795325245	F	4	40 ACE	SP	CRE			V	1/15/2034
2021	PO5792625219	KU	5	35 ACE	SP	CRE			B	1/16/2034
2021	PO0204900184	KU	4	40 KOP	SP	CRE	ID		TD	1/17/2034
2021	PO7264468144	KU	4	40 ACE	SP	CRE	ED,ID		BD	1/18/2034
2021	PO4022783956	LGE	UNK	45 ACE	SP	CRE	ED		V	1/19/2034
2021	PO5774925049	KU	1	45 ACE	SP	CCA			V	1/20/2034
2021	PO5779325090	KU	5	35 ACE	SP	CRE			B	1/21/2034
2021	PO5786425157	F	3	40 ACE	SP	CRE			V	1/22/2034
2021	PO7251268072	F	6	30 ACE	SP	P			V	1/23/2034
2021	PO7258268241	KU	6	30 ACE	SP	CCA			V	1/24/2034
2021	PO7333768734	F	5	35 ACE	SP	P			V	1/25/2034
2021	PO4020883970	LGE	UNK	55 ACE	SP	CRE	ED,ID		TD	1/26/2034
2021	PO4020983970	LGE	3	45 ACE	SP	CRE	ED,ID		BD	1/27/2034
2021	PO4021383968	LGE	UNK	55 ACE	SP	CRE	ED,ID		BD	1/28/2034
2021	PO0261100367	KU	4	40 KOP	SP	CCA			T	1/29/2034
2021	PO0289400465	KU	4	45 KOP	SP	CRE	ID		TD	1/30/2034
2021	PO1688366045	KU	4	40 BRN	SP	CRE	ED,IP,SRS		TD	1/31/2034
2021	PO1728566443	KU	4	40 BRN	SP	CRE	ED,IP,SRS		TD	2/1/2034
2021	PO4021483971	LGE	4	30 ACE	SP	CRE	ED,ID		BD	2/2/2034
2021	PO7385951462	LGE	4	35 ACE	SP	CCA			V	2/3/2034
2021	PO5816225569	KU	6	30 ACE	SP	CRE			T	2/4/2034
2021	PO5815025431	F	4	40 ACE	SP	CRE			V	2/5/2034
2021	PO5816825448	F	4	40 ACE	SP	CRE			V	2/6/2034
2021	PO0282600734	KU	4	40 KOP	SP	CRE	ID		TD	2/7/2034
2021	PO0430600304	KU	4	35 KOP	SP	CRE	ID		BD	2/8/2034
2021	PO0396700344	KU	4	40 BRO	SP	CRE	ID		BD	2/9/2034
2021	PO5822425505	KU	6	30 ACE	SP	CRE			B	2/10/2034
2021	PO7066872453	KU	3	45 ACE	SP	CCA			V	2/11/2034
2021	PO2033792330	KU	4	40 BRO	SP	CRE	ID		TD	2/12/2034
2021	PO4501188110	LGE	4	45 BRN	SP	CRE	ED,HH,ID,RB		BX	RR 2/13/2034
2021	PO7487469903	KU	4	40 ACE	SP	CCA			V	2/14/2034
2021	PO7504370028	KU	4	40 ACE	SP	CCA			V	2/15/2034
2021	PO4097684519	F	4	40 BRO	SP	P			V	2/16/2034
2021	PO4098984528	F	3	45 BRO	SP	CCA			V	2/17/2034
2021	PO4104384532	F	3	45 BRO	SP	CCA			V	2/18/2034
2021	PO4104184512	F	2	45 BRO	SP	CCA			V	2/19/2034
2021	PO4105884501	F	3	45 BRO	SP	P			V	2/20/2034
2021	PO4107484491	F	3	45 BRO	SP	CCA			V	2/21/2034
2021	PO4110684465	F	4	40 BRO	SP	P			V	2/22/2034
2021	PO4109084478	F	3	45 BRO	SP	P			V	2/23/2034
2021	PO4119484481	F	3	45 BRO	SP	CCA			V	2/24/2034
2021	PO4120784483	F	1	50 BRO	SP	CCA			V	2/25/2034
2021	PO4122684485	F	3	50 BRO	SP	P			V	2/26/2034
2021	PO4119184459	F	4	40 BRO	SP	P			V	2/27/2034
2021	PO4118584473	F	4	40 BRO	SP	CRE			V	2/28/2034
2021	PO4118284480	F	3	50 BRO	SP	CRE			V	3/1/2034

2021 PO7518970088	KU	4	40 ACE	SP	CCA		V		3/2/2034
2021 PO7533570153	KU	4	40 ACE	SP	CCA		V		3/3/2034
2021 PO7554870246	KU	4	40 ACE	SP	CCA		V		3/4/2034
2021 PO7578970348	KU	4	40 ACE	SP	CCA		V		3/5/2034
2021 PO7595370423	KU	4	40 ACE	SP	CCA		V		3/6/2034
2021 PO7615670509	KU	4	40 ACE	SP	CCA		V		3/7/2034
2021 PO7631970576	KU	4	40 ACE	SP	CRE	ED,ID	BD		3/8/2034
2021 PO3993983955	F	UNK	25 ACE	SP	CRE	ED	V		3/9/2034
2021 PO4005883793	F	3	45 BRO	SP	A		V		3/10/2034
2021 PO3995183960	F	4	40 ACE	SP	CRE	ED	V		3/11/2034
2021 PO3994083961	F	3	45 ACE	SP	CCA		V		3/12/2034
2021 PO3992783965	F	4	40 ACE	SP	CRE	ED	V		3/13/2034
2021 PO3991183958	F	UNK	25 ACE	SP	CRE	ED	V		3/14/2034
2021 PO7639670601	KU	2	45 ACE	SP	CRE	ED,ID	BD		3/15/2034
2021 PO4006783783	F	4	35 BRO	SP	CRE		V		3/16/2034
2021 PO3991483970	F	4	40 ACE	SP	CCA	ED	V		3/17/2034
2021 PO3989383979	F	UNK	25 ACE	SP	CRE	ED	V		3/18/2034
2021 PO6690595789	F	4	40 ACE	SP	P		V		3/19/2034
2021 PO6676995763	F	4	40 ACE	SP	CRE		V		3/20/2034
2021 PO6665095734	F	4	40 ACE	SP	CRE		V		3/21/2034
2021 PO6652495710	KU	4	40 ACE	SP	P		V		3/22/2034
2021 PO6639795706	F	4	40 ACE	SP	CRE		V		3/23/2034
2021 PO6624295732	F	4	40 ACE	SP	CCA		V		3/24/2034
2021 PO6615995944	F	4	40 ACE	SP	P		V		3/25/2034
2021 PO4384685741	LGE	4	35 ACE	SP	P	ED	BD		3/26/2034
2021 PO4876284732	LGE	4	40 BRO	SP	A	ID,IP	BD		3/27/2034
2021 PO4512587773	LGE	3	45 BRO	SP	CCA		V		3/28/2034
2021 PO4511087763	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		3/29/2034
2021 PO4514087784	F	4	40 BRO	SP	CCA		V		3/30/2034
2021 PO4515187792	LGE	3	45 BRO	SP	CCA		V		3/31/2034
2021 PO4514487802	F	4	40 BRO	SP	CRE		V		4/1/2034
2021 PO4384385745	LGE	3	50 ACE	SP	CRE	ED,IP	TD		4/2/2034
2021 PO4385085744	LGE	4	40 ACE	SP	CRE	ED,ID	BX	RR	4/3/2034
2021 PO4918085148	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	4/4/2034
2021 PO5159584752	LGE	4	40 ACE	SP	P	ED,ID	BD		4/5/2034
2021 PO4919485166	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		4/6/2034
2021 PO4920285163	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		4/7/2034
2021 PO5156384781	LGE	4	40 ACE	SP	P	ED,ID	TD		4/8/2034
2021 PO4495497774-A	LGE	4	35 BRO	SP	P	ED,ID	BD		4/9/2034
2021 PO4495487774	LGE	4	35 BRO	SP	P	ED,ID	BD		4/10/2034
2021 PO4494987782	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		4/11/2034
2021 PO4494487790	LGE	4	40 BRO	SP	CRE	ED,ID	BD		4/12/2034
2021 PO4493987797	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		4/13/2034
2021 PO4493387807	LGE	3	45 BRO	SP	CCA		V		4/14/2034
2021 PO4493087811	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		4/15/2034
2021 PO4493087819	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP	BD		4/16/2034
2021 PO4493187828	LGE	4	35 BRO	SP	CCA		V		4/17/2034
2021 PO4377285609	LGE	4	35 ACE	SP	CRE	ED	BD		4/18/2034
2021 PO4379585693	LGE	1	30E ACE	SP	CCA		V		4/19/2034
2021 PO4378885703	LGE	1	50 ACE	SP	CCA		V		4/20/2034
2021 PO4520687929	F	4	35 BRO	SP	P		V		4/21/2034
2021 PO4499687839	LGE	4	40 BRO	SP	CCA	ED,ID	BD		4/22/2034
2021 PO4366285506	LGE	3	55E ACE	SP	CRE	ED,ID	BD		4/23/2034
2021 PO4367185496	LGE	3	55E ACE	SP	P	ED	BD		4/24/2034

2021 PO5142984734	LGE	4	40 ACE	SP	P	ED,HH,ID	BD	4/25/2034	
2021 PO5124084588	LGE	4	40 ACE	SP	CRE	ED,ID	BD	4/26/2034	
2021 PO4499487840	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	4/27/2034	
2021 PO4367985486	LGE	3	55 ACE	SP	A	ED	BD	4/28/2034	
2021 PO4369985461	LGE	3	55 ACE	SP	CRE	ED	BD	4/29/2034	
2021 PO4372885427	LGE	1	55 ACE	SP	CRE	ED	BD	4/30/2034	
2021 PO6660897368a	KU	5	35 ACE	SP	CCA		V	5/1/2034	
2021 PO5638708065	F	4	40 XXX	SP	CRE		V	5/2/2034	
2021 PO5634307952	F	4	40 XXX	SP	CRE		V	5/3/2034	
2021 PO5623208048	KU	6	30 XXX	SP	CRE	ID	TD	5/4/2034	
2021 PO5523108954	F	4	40 XXX	SP	CRE		V	5/5/2034	
2021 PO5201384420	F	4	40 ACE	SP	P		V	5/6/2034	
2021 PO5203084405	F	4	40 ACE	SP	P		V	5/7/2034	
2021 PO5202484475	LGE	4	40 ACE	SP	CCA		V	5/8/2034	
2021 PO5201584462	LGE	4	40 ACE	SP	CCA		V	5/9/2034	
2021 PO5200684448	LGE	4	40 ACE	SP	CCA		V	5/10/2034	
2021 PO4378285824	LGE	4	40 ACE	SP	CRE	ED,IP	BD	5/11/2034	
2021 PO4378685817	LGE	4	40 ACE	SP	CRE	ED	VX	PX	5/12/2034
2021 PO4379385808	LGE	4	40 ACE	SP	CRE	ED	TD	5/13/2034	
2021 PO4380385797	LGE	4	45 ACE	SP	CRE	ED	TD	5/14/2034	
2021 PO6617296382	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	5/15/2034
2021 PO6604396432	F	4	40 ACE	SP	CRE		V	5/16/2034	
2021 PO6607796529	F	4	40 ACE	SP	CRE		V	5/17/2034	
2021 PO6592196477	F	4	40 ACE	SP	CRE		V	5/18/2034	
2021 PO6586096369	F	4	40 ACE	SP	P		V	5/19/2034	
2021 PO6586296498	F	3	40 ACE	SP	P		V	5/20/2034	
2021 PO6580496520	F	4	40 ACE	SP	CRE		V	5/21/2034	
2021 PO5211684321	F	3	45 ACE	SP	CCA		V	5/22/2034	
2021 PO5212684304	F	3	50 ACE	SP	P		V	5/23/2034	
2021 PO5213784283	F	3	45 ACE	SP	P		V	5/24/2034	
2021 PO5214384274	F	4	40 ACE	SP	P		V	5/25/2034	
2021 PO5216284248	F	4	40 ACE	SP	P		V	5/26/2034	
2021 5216284248-a	F	3	45 ACE	SP	P		V	5/27/2034	
2021 PO6564396567	F	4	40 ACE	SP	P		V	5/28/2034	
2021 PO6551896614	F	4	40 ACE	SP	CRE		V	5/29/2034	
2021 PO6540496652	F	4	40 ACE	SP	CRE		V	5/30/2034	
2021 PO4371485899	LGE	4	30 ACE	SP	CCA		V	5/31/2034	
2021 PO4371685884	LGE	3	45 ACE	SP	CCA		V	6/1/2034	
2021 4378885703a	LGE	3	45 ACE	SP	P	ED,ID	BD	6/2/2034	
2021 PO4372085884	LGE	4	30 ACE	SP	CCA		V	6/3/2034	
2021 PO4379285706	LGE	3	45E ACE	SP	CRE	ED	BD	6/4/2034	
2021 PO4379585705	LGE	4	30 ACE	SP	P	ED	BD	6/5/2034	
2021 PO4379885711	LGE	4	40 ACE	SP	CRE	ED	BD	6/6/2034	
2021 PO5596407939	F	3	45 XXX	SP	P		V	6/7/2034	
2021 PO5604208044	F	4	40 XXX	SP	CRE		V	6/8/2034	
2021 PO4372085872	LGE	4	40 ACE	SP	CRE	ED	BD	6/9/2034	
2021 PO4373085875	LGE	4	30 ACE	SP	CRE	ED,ID	BD	6/10/2034	
2021 PO8780398950	KU	4	40 XXX	SP	S	ED,SRC	T	6/11/2034	
2021 PO8657299976	KU	2	50 XXX	SP	S		V	6/12/2034	
2021 PO8680299797	KU	2	50 XXX	SP	CCA		V	6/13/2034	
2021 PO8703499624	KU	2	50 XXX	SP	CCA		V	6/14/2034	
2021 PO8715299545	KU	2	50 XXX	SP	S		V	6/15/2034	
2021 PO4381285721	LGE	3	50 ACE	SP	CRE	ED,EP	TD	6/16/2034	
2021 PO5127784557	LGE	4	40 ACE	SP	CRE	ED	BD	6/17/2034	

2021 PO4499087842	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	6/18/2034
2021 PO4368785476	LGE	3	55 ACE	SP	CRE	ED	BD	6/19/2034
2021 PO4371685444	LGE	UNK	60 ACE	SP	CCA		V	6/20/2034
2021 PO4371585442	LGE	1	55 ACE	SP	CCA	ED	V	6/21/2034
2021 PO6660897368	F	4	40 ACE	SP	CRE		V	6/22/2034
2021 PO6655097214	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	6/23/2034
2021 PO4512687777	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/24/2034
2021 PO5125884557	LGE	3	45 ACE	SP	CCA		V	6/25/2034
2021 PO8333802192	KU	1	60 XXX	SP	S		V	6/26/2034
2021 PO4380185791	LGE	4	30 ACE	SP	P	ED	TD	6/27/2034
2021 PO5203284451	LGE	3	45 ACE	SP	P	ED,ID	TD	6/28/2034
2021 PO5204684441	LGE	3	45 ACE	SP	P	ED,ID	BD	6/29/2034
2021 PO4504587884	LGE	3	45 BRO	SP	CCA		V	6/30/2034
2021 PO4503687878	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	7/1/2034
2021 PO4502287868	LGE	4	40 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	BX RP1	7/2/2034
2021 PO4502887873	LGE	4	40 BRO	SP	CCA		V	7/3/2034
2021 PO4502587854	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	7/4/2034
2021 PO4530287664	F	4	40 BRO	SP	CRE		V	7/5/2034
2021 PO4528287681	F	4	40 BRO	SP	P		V	7/6/2034
2021 PO4529087668	F	4	40 BRO	SP	P		V	7/7/2034
2021 PO6646396535	F	4	40 ACE	SP	CRE		V	7/8/2034
2021 PO6647396565	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	7/9/2034
2021 PO5204784393	F	3	45 ACE	SP	A		V	7/10/2034
2021 PO5203984388	F	3	45 ACE	SP	P		V	7/11/2034
2021 PO5203584385	LGE	3	50 ACE	SP	P		V	7/12/2034
2021 PO6648596596	F	4	40 ACE	SP	CRE		V	7/13/2034
2021 PO5206384376	F	4	40 ACE	SP	P		V	7/14/2034
2021 PO6576096959	F	4	40 ACE	SP	CRE		V	7/15/2034
2021 PO5208084397	F	4	40 ACE	SP	P	ED	VX RP2	7/16/2034
2021 PO6564696885	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	7/17/2034
2021 PO6572096853	F	3	45 ACE	SP	P		V	7/18/2034
2021 PO6567296731	F	4	40 ACE	SP	P		V	7/19/2034
2021 PO6556196694	KU	5	35 ACE	SP	CCA		V	7/20/2034
2021 PO6562596607	F	3	45 ACE	SP	CRE		V	7/21/2034
2021 PO5209184350	F	4	40 ACE	SP	P		V	7/22/2034
2021 PO5211384369	LGE	4	40 ACE	SP	P	ED,ID	TD	7/23/2034
2021 PO6534496903	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	7/24/2034
2021 PO4381585775	LGE	4	30 ACE	SP	P	ED,ID	TD	7/25/2034
2021 PO4382085774	LGE	4	40 ACE	SP	P	ED	BD	7/26/2034
2021 PO4382885764	LGE	4	35 ACE	SP	CRE	ED	TD	7/27/2034
2021 PO4383485757	LGE	4	40 ACE	SP	CRE	ED	BD	7/28/2034
2021 PO4383885759	LGE	5	30 ACE	SP	CRE	ED,IP	TD	7/29/2034
2021 PO4381285785	LGE	4	40 ACE	SP	CCA		V	7/30/2034
2021 5212284326	LGE	3	40 ACE	SP	P	ED	VX RP1	7/31/2034
2021 PO6638796305	F	4	40 ACE	SP	CRE		V	8/1/2034
2021 PO6626696350	F	4	40 ACE	SP	CRE		V	8/2/2034
2021 PO5218184221	LGE	3	45 ACE	SP	P	ED,ID	TD	8/3/2034
2021 PO8495001073	KU	2	50 XXX	SP	S		V	8/4/2034
2021 PO8523400886	KU	2	55 XXX	SP	S		V	8/5/2034
2021 PO8538300785	KU	2	55 XXX	SP	S		V	8/6/2034
2021 PO8554800672	KU	2	50 XXX	SP	S		V	8/7/2034
2021 PO8564000612	KU	5	35 XXX	SP	CRE	ED,ID	TD	8/8/2034
2021 PO8571600563	KU	2	50 XXX	SP	S		V	8/9/2034
2021 PO8584100481	KU	2	50 XXX	SP	S		V	8/10/2034



2021 PO8588800534	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	8/11/2034
2021 PO8594200415	KU	2	55 XXX	SP	S		V	8/12/2034
2021 PO8604800343	KU	1	60 XXX	SP	S		V	8/13/2034
2021 PO8611900301	KU	1	60 XXX	SP	S		V	8/14/2034
2021 PO8618500259	KU	2	55 XXX	SP	S		V	8/15/2034
2021 PO8315402343	KU	5	35 XXX	SP	S		V	8/16/2034
2021 PO5199784435	F	4	40 ACE	SP	P	ED	V	8/17/2034
2021 PO6635196609	F	3	40 ACE	SP	P		V	8/18/2034
2021 PO6624096650	F	4	40 ACE	SP	CRE		V	8/19/2034
2021 PO6612696692	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	8/20/2034
2021 PO6607296712	F	3	40 ACE	SP	P		V	8/21/2034
2021 PO5197484454	F	1	50 ACE	SP	CCA	ID	V	8/22/2034
2021 PO4502187738	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	8/23/2034
2021 PO4501587748	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	8/24/2034
2021 PO4498987763	LGE	3	45 BRO	SP	CCA		V	8/25/2034
2021 PO6595696755	F	4	40 ACE	SP	CRE		V	8/26/2034
2021 PO6584796795	F	4	40 ACE	SP	CRE		V	8/27/2034
2021 PO5664207787	KU	5	35 XXX	SP	CRE	ID	TD	8/28/2034
2021 PO5658607863	KU	6	30 XXX	SP	CRE	ID	TD	8/29/2034
2021 PO5661608071	KU	6	30 XXX	SP	CRE	ID	TD	8/30/2034
2021 PO5673507986	KU	6	30 XXX	SP	CCA		V	8/31/2034
2021 PO5670408184	F	4	40 XXX	SP	CRE		V	9/1/2034
2021 PO5662808211	KU	3	45 XXX	SP	CCA		V	9/2/2034
2021 PO5647908313	KU	5	35 XXX	SP	CCA		V	9/3/2034
2021 PO5646508270	F	4	40 XXX	SP	CCA		V	9/4/2034
2021 PO5642708172	F	4	40 XXX	SP	CRE		V	9/5/2034
2021 PO5212284326	LGE	4	30 ACE	DF	P	ED,ID	BD	9/6/2034
2021 PO4382185727	LGE	3	50 ACE	SP	CRE	ED,IP	BD	9/7/2034
2021 PO5148784775	LGE	4	40 ACE	SP	P	ED,ID	TD	9/8/2034
2021 PO5146584769	LGE	4	40 ACE	SP	CRE	ED,ID	TD	9/9/2034
2021 PO8726199478	KU	1	60 XXX	SP	S		V	9/10/2034
2021 PO8743699369	KU	1	60 XXX	SP	S		V	9/11/2034
2021 PO8757599283	KU	2	55 XXX	SP	S		V	9/12/2034
2021 PO5144684763	LGE	4	40 ACE	SP	P	ED	TD	9/13/2034
2021 PO5143184759	LGE	3	45 ACE	SP	CCA		V	9/14/2034
2021 PO8779899148	KU	2	50 XXX	SP	S		V	9/15/2034
2021 PO8795199053	KU	2	55 XXX	SP	S		V	9/16/2034
2021 PO8793199163	KU	2	50 XXX	SP	S		V	9/17/2034
2021 PO8813198939	KU	1	60 XXX	SP	S		V	9/18/2034
2021 PO8840198774	KU	2	50 XXX	SP	S		V	9/19/2034
2021 PO8859198653	KU	2	50 XXX	SP	S		V	9/20/2034
2021 PO8873998561	KU	2	50 XXX	SP	S		V	9/21/2034
2021 PO8889198468	KU	2	50 XXX	SP	S		V	9/22/2034
2021 PO8908198352	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	9/23/2034
2021 PO4383385736	LGE	4	40 ACE	SP	P	ED	BD	9/24/2034
2021 PO4383585734	LGE	4	30 ACE	SP	CRE	ED	TD	9/25/2034
2021 PO8932798198	KU	3	45 XXX	SP	S		V	9/26/2034
2021 PO8950798084	KU	3	45 XXX	SP	S		V	9/27/2034
2021 PO8972797950	KU	3	45 XXX	SP	S		V	9/28/2034
2021 PO8988097855	KU	3	45 XXX	SP	S		V	9/29/2034
2021 PO9000597773	KU	3	45 XXX	SP	S		V	9/30/2034
2021 PO9022597634	KU	3	45 XXX	SP	S		V	10/1/2034
2021 PO8348202396	KU	4	40 XXX	SP	S		V	10/2/2034
2021 PO8316902314	KU	1	55 XXX	SP	S		V	10/3/2034

2021	PO8325402252	KU	1	55 XXX	SP	S			V			10/4/2034
2021	PO5142284756	LGE	4	40 ACE	SP	CCA	ED,ID		TD			10/5/2034
2021	PO5603608007	KU	4	35 XXX	SP	CRE	ID		TD			10/6/2034
2021	PO5191184531	LGE	3	45 ACE	SP	P	ED		V			10/7/2034
2021	PO5189084514	F	3	45 ACE	SP	CCA			V			10/8/2034
2021	PO5190484506	LGE	3	45 ACE	SP	CCA			V			10/9/2034
2021	PO4389285686	LGE	3	45 ACE	SP	P	ED		V			10/10/2034
2021	PO9081958546	LGE	3	45 ACE	SP	CCA			V			10/11/2034
2021	PO9097958425	LGE	3	45 ACE	SP	CCA			V			10/12/2034
2021	PO5194784472	LGE	3	45 ACE	SP	CCA			V			10/13/2034
2021	PO4496387826	LGE	4	40 BRO	SP	CRE	ED,ID,IP		BD			10/14/2034
2021	PO4496687831	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TD			10/15/2034
2021	PO4499387766	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB		TX	RR		10/16/2034
2021	PO4500087770	LGE	4	40 BRO	SP	CCA			V			10/17/2034
2021	PO4501087758	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TD			10/18/2034
2021	PO5196084463	LGE	3	45 ACE	SP	CCA			V			10/19/2034
2021	PO5612207862	KU	5	35 XXX	SP	CRE	ID		BD			10/20/2034
2021	PO5618007893	KU	5	35 XXX	SP	CRE	ID,IP		BD			10/21/2034
2021	PO5629507823	F	4	40 XXX	SP	CRE	ED,ID,MD		BX	RP3		10/22/2034
2021	PO8462901409	KU	5	35 XXX	SP	CRE	ED,ID		TD			10/23/2034
2021	PO8439501478	KU	2	55 XXX	SP	S	ED,SR		T			10/24/2034
2021	PO8459801340	KU	2	50 XXX	SP	S			V			10/25/2034
2021	PO8479201196	KU	2	50 XXX	SP	S			V			10/26/2034
2021	PO8511600962	KU	2	55 XXX	SP	S			V			10/27/2034
2021	PO8532601004	KU	6	30 XXX	SP	CRE	ED,ID		TD			10/28/2034
2021	PO8535001019	KU	4	45 XXX	SP	S			V			10/29/2034
2021	PO8537101004	KU	4	45 XXX	SP	S			V			10/30/2034
2021	PO8522201111	KU	4	45 XXX	SP	S			V			10/31/2034
2021	PO8506301221	KU	4	40 XXX	SP	S			V			11/1/2034
2021	PO4366185328	LGE	4	40 ACE	SP	CCA			V			11/2/2034
2021	PO4383085814	LGE	4	45 ACE	SP	CCA			V			11/3/2034
2021	PO4384385796	LGE	4	40 ACE	SP	CCA			V			11/4/2034
2021	PO4385585780	LGE	3	45 ACE	SP	CCA			V			11/5/2034
2021	PO4385985775	LGE	3	45 ACE	SP	P	ED		BD			11/6/2034
2021	PO4386885762	LGE	1	55 ACE	SP	CCA			V			11/7/2034
2021		4369185920	LGE	3	45 ACE	SP	A	ED	TD			11/8/2034
2021	PO4369185920	LGE	4	35 ACE	SP	P	ED,ID		TD			11/9/2034
2021	PO4367885935	LGE	4	40 ACE	SP	P	ED,ID		TD			11/10/2034
2021	PO4374385670	LGE	4	40 ACE	SP	P	ED,ID		BD			11/11/2034
2021	PO4370985900	LGE	4	40 ACE	SP	CRE	ID		BD			11/12/2034
2021	PO4370185910	LGE	4	40 ACE	SP	P	ED,ID		TD			11/13/2034
2021	PO4375585679	LGE	3	45 ACE	SP	CRE	ED,IP		BD			11/14/2034
2021	PO4370485911	LGE	4	30 ACE	SP	A	ID		TD			11/15/2034
2021	PO4376585687	LGE	3	45E ACE	SP	P	ED		TD			11/16/2034
2021	PO4371285896	LGE	4	40 ACE	SP	P	ED,ID		BD			11/17/2034
2021	PO5408111395	KU	3	45 BRO	SP	CCA			V			11/18/2034
2021	PO5813511402	KU	4	40 KOP	SP	S			V			11/19/2034
2021	PO5810611540	KU	4	40 KOP	SP	S			V			11/20/2034
2021	PO5818511154	KU	4	40 KOP	SP	S			V			11/21/2034
2021	PO5821310953	KU	5	35 KOP	SP	S			V			11/22/2034
2021	PO5816211269	KU	4	40 KOP	SP	S			V			11/23/2034
2021	PO5821311016	KU	4	40 KOP	SP	S			V			11/24/2034
2021	PO5419211354	KU	5	40 BRO	SP	CCA			V			11/25/2034
2021	PO4033785886	F	4	40 KOP	SP	CCA			V			11/26/2034

2021 PO4033285872	F	3	45 KOP	SP	CCA	V	11/27/2034
2021 PO4958532605	KU	3	45 BRN	SP	CCA	V	11/28/2034
2021 PO4948032342	KU	3	45 BRN	SP	CCA	V	11/29/2034
2021 PO4944332363	KU	2	45 BRN	SP	CCA	V	11/30/2034
2021 PO5220026841	KU	4	40 BRN	SP	CRE	B	12/1/2034
2021 PO5210426893	KU	5	35 BRN	SP	CCA	V	12/2/2034
2021 PO5218126957	KU	4	35 BRN	SP	CCA	B	12/3/2034
2021 PO4874032458	KU	4	45 BRN	SP	CCA	V	12/4/2034
2021 PO5199726052	KU	3	50 BRN	SP	CRE	B	12/5/2034
2021 PO5465814981	KU	2	45 BRO	SP	CCA	V	12/6/2034
2021 PO5456114806	KU	3	45 BRO	SP	CCA	V	12/7/2034
2021 PO5455114605	KU	2	45 BRO	SP	CCA	V	12/8/2034
2021 PO4032685858	F	4	40 KOP	SP	CCA	V	12/9/2034
2021 PO4032285850	F	4	40 KOP	SP	CCA	V	12/10/2034
2021 PO3940285879	LGE	3	50 ACE	SP	CCA	V	12/11/2034
2021 PO3941685897	LGE	1	55 ACE	SP	CCA	V	12/12/2034
2021 PO3943485902	F	4	30 ACE	SP	CRE	V	12/13/2034
2021 PO5199426077	KU	2	40 BRN	SP	CCA	V	12/14/2034
2021 PO5196026296	KU	3	45 BRN	SP	CRE	B	12/15/2034
2021 PO5197726186	KU	3	45 BRN	SP	CCA	V	12/16/2034
2021 PO5197426204	KU	3	45 BRN	SP	CCA	V	12/17/2034
2021 PO5193326463	KU	2	40 BRN	SP	CRE	B	12/18/2034
2021 PO5374310115	KU	1	70 KOP	SP	CRE	V	12/19/2034
2021 PO5383810049	KU	1	75 KOP	SP	CRE	V	12/20/2034
2021 PO4062085710	F	3	45 BRO	SP	CCA	V	12/21/2034
2021 PO4063085709	F	4	40 BRO	SP	CRE	V	12/22/2034
2021 PO4064185708	F	4	40 BRO	SP	CRE	V	12/23/2034
2021 PO4064985707	F	4	40 BRO	SP	CCA	V	12/24/2034
2021 PO4066585706	F	3	45 BRO	SP	CRE	V	12/25/2034
2021 PO5190626634	KU	4	40 BRN	SP	CCA	V	12/26/2034
2021 PO4030285799	LGE	4	40 KOP	SP	CCA	V	12/27/2034
2021 PO4068185705	F	4	40 BRO	SP	P	V	12/28/2034
2021 PO4069785707	F	4	30 BRO	SP	P	V	12/29/2034
2021 PO5191926554	KU	4	40 BRN	SP	CRE	B	12/30/2034
2021 PO5191226598	KU	4	40 BRN	SP	CRE	B	12/31/2034
2021 PO5404409822	KU	5	35 KOP	SP	S	V	1/1/2035
2021 PO5392609652	KU	3	45 KOP	SP	S	V	1/2/2035
2021 PO4052885879	F	4	40 BRO	SP	CRE	V	1/3/2035
2021 PO4052885891	F	3	45 BRO	SP	CCA	V	1/4/2035
2021 PO4052385911	F	4	40 BRO	SP	CRE	V	1/5/2035
2021 PV4052785910	F	4	35 BRO	SP	CRE	V	1/6/2035
2021 PO4052985924	F	4	40 BRO	SP	CRE	V	1/7/2035
2021 PO4053185931	F	3	45 BRO	SP	CCA	V	1/8/2035
2021 PO4027185725	LGE	4	40 KOP	SP	CCA	V	1/9/2035
2021 PO4026685709	LGE	4	40 KOP	SP	CCA	V	1/10/2035
2021 PO5114726658	KU	4	40 BRN	SP	CRE	B	1/11/2035
2021 PO4146886060	F	4	40 BRO	SP	CRE	V	1/12/2035
2021 PO4148086059	F	4	40 BRO	SP	CRE	V	1/13/2035
2021 PO4142886062	LGE	4	40 BRO	SP	CCA	V	1/14/2035
2021 PO4141886062	F	4	35 BRO	SP	A	V	1/15/2035
2021 PO4143686062	F	3	45 BRO	SP	CRE	V	1/16/2035
2021 PO4145186061	F	4	40 BRO	SP	CRE	V	1/17/2035
2021 PO4025885693	LGE	4	40 KOP	SP	CCA	V	1/18/2035
2021 PO4023385689	LGE	4	40 KOP	SP	CCA	V	1/19/2035

2021 PO4021185690	LGE	3	45 KOP	SP	CCA	V	1/20/2035
2021 PO4020386538	LGE	4	35 ACE	SP	CRE	V	1/21/2035
2021 PO4022386511	LGE	4	35 ACE	SP	CRE	V	1/22/2035
2021 PO4023486504	LGE	4	35 ACE	SP	CRE	V	1/23/2035
2021 PO4025086492	LGE	4	35 ACE	SP	CRE	V	1/24/2035
2021 PO7384976469	LGE	4	35 ACE	SP	CCA	V	1/25/2035
2021 PO4023786463	LGE	4	35 ACE	SP	CRE	V	1/26/2035
2021 PO4021986473	LGE	4	35 ACE	SP	CRE	V	1/27/2035
2021 PO4020486481	LGE	4	35 ACE	SP	CRE	V	1/28/2035
2021 PO4019586492	LGE	4	40 ACE	SP	CRE	V	1/29/2035
2021 PO4020286505	LGE	4	40 ACE	SP	CRE	V	1/30/2035
2021 PO4020686518	LGE	2	45 ACE	SP	CCA	V	1/31/2035
2021 PO4020486519	LGE	4	45 ACE	SP	P	V	2/1/2035
2021 PO4182986205	F	4	40 BRO	SP	CRE	V	2/2/2035
2021 PO4181586205	F	4	40 BRO	SP	CRE	V	2/3/2035
2021 PO4069785703	F	4	40 BRO	SP	CRE	V	2/4/2035
2021 PO4071285709	F	4	30 BRO	SP	CCA	V	2/5/2035
2021 PO4071185602	F	3	45 BRO	SP	CCA	V	2/6/2035
2021 PO4072885700	F	4	35 BRO	SP	P	V	2/7/2035
2021 PO4073385704	F	4	30 BRO	SP	P	V	2/8/2035
2021 PO4074485698	F	3	45 BRO	SP	CCA	V	2/9/2035
2021 PO4074485703	F	4	30 BRO	SP	CCA	V	2/10/2035
2021 PO4075585702	F	4	30 BRO	SP	CCA	V	2/11/2035
2021 PO4075985697	F	4	40 BRO	SP	CCA	V	2/12/2035
2021 PO4077585695	F	4	35 BRO	SP	CRE	V	2/13/2035
2021 PO4077885700	F	4	30 BRO	SP	CRE	V	2/14/2035
2021 PO4079285694	F	4	40 BRO	SP	CRE	V	2/15/2035
2021 PO4079485699	F	4	35 BRO	SP	CCA	V	2/16/2035
2021 PO4080685692	F	3	45 BRO	SP	CCA	V	2/17/2035
2021 PO4081385698	F	4	40 BRO	SP	CRE	V	2/18/2035
2021 PO4081385691	F	4	40 BRO	SP	CCA	V	2/19/2035
2021 PO4082385691	F	3	45 BRO	SP	CCA	V	2/20/2035
2021 PO4082585697	F	4	30 BRO	SP	CRE	V	2/21/2035
2021 PO4083585690	F	4	40 BRO	SP	P	V	2/22/2035
2021 PO4084885693	F	4	35 BRO	SP	CRE	V	2/23/2035
2021 PO4084785688	F	4	40 BRO	SP	CRE	V	2/24/2035
2021 PO4085985697	F	4	30 BRO	SP	P	V	2/25/2035
2021 PO4085885688	F	3	45 BRO	SP	CCA	V	2/26/2035
2021 PO4028485793	LGE	4	40 KOP	SP	CCA	V	2/27/2035
2021 PO4053986659	LGE	4	40 ACE	SP	CCA	V	2/28/2035
2021 PO5420110018	KU	3	45 KOP	SP	S	V	3/1/2035
2021 PO5409210117	F	4	40 KOP	SP	S	V	3/2/2035
2021 PO5406510038	KU	2	50 KOP	SP	S	V	3/3/2035
2021 PO5400510055	KU	4	40 KOP	SP	S	V	3/4/2035
2021 PO5399309840	KU	3	45 KOP	SP	S	V	3/5/2035
2021 PO5412810216	F	4	40 KOP	SP	S	V	3/6/2035
2021 PO5416410319	F	4	40 KOP	SP	P	V	3/7/2035
2021 PO5328130225	KU	4	40 BRN	SP	CCA	V	3/8/2035
2021 PO4005386464	F	3	50 ACE	SP	CRE	V	3/9/2035
2021 PO4006686468	F	3	50 ACE	SP	CCA	V	3/10/2035
2021 PO4006686474	LGE	4	30 ACE	SP	CRE	V	3/11/2035
2021 PO4007986474	F	2	55 ACE	SP	CCA	V	3/12/2035
2021 PO4009086480	F	4	35 ACE	SP	CCA	V	3/13/2035
2021 PO4010286486	F	3	50 ACE	SP	CCA	V	3/14/2035

2021	PO4014286527	LGE	3	50 ACE	SP	CCA		V	3/15/2035
2021	PO4013486499	LGE	4	45 ACE	SP	CRE		V	3/16/2035
2021	PO4012986501	F	4	40 ACE	SP	CRE		V	3/17/2035
2021	PO4016686554	LGE	3	50 ACE	SP	CCA		V	3/18/2035
2021	PO4017486555	F	4	40 ACE	SP	CCA		V	3/19/2035
2021	PO4016686542	LGE	3	50 ACE	SP	CCA		V	3/20/2035
2021	PO4016086558	LGE	7	25 ACE	SP	CCA		V	3/21/2035
2021	PO4016286557	LGE	6	25 ACE	SP	CCA		V	3/22/2035
2021	PO4016586554	LGE	2	55 ACE	SP	CCA		V	3/23/2035
2021	PO4013986513	F	4	35 ACE	SP	CRE		V	3/24/2035
2021	PO4058885834	F	4	40 BRO	SP	CRE		V	3/25/2035
2021	PO4981237850	KU	3	45 BRO	SP	CCA		V	3/26/2035
2021	PO4972537639	KU	2	50 BRO	SP	CCA		V	3/27/2035
2021	PO4935637340	KU	3	45 BRO	SP	CCA		B	3/28/2035
2021	PO5447109946A	F	5	35 KOP	SP	P	ED,ID	B	3/29/2035
2021	PO5448309807	KU	3	45 KOP	SP	S		V	3/30/2035
2021	PO5436510087	KU	6	30 KOP	SP	S		V	3/31/2035
2021	PO5447109946	KU	3	45 KOP	SP	S		V	4/1/2035
2021	PO5435010000	KU	H1	85 KOP	SP	CRE		V	4/2/2035
2021	PO5453509998	KU	H1	70 KOP	ST	CRE		V	4/3/2035
2021	PO4052785868	F	4	40 BRO	SP	CCA		V	4/4/2035
2021	PO5129637532	KU	5	35 KOP	SP	CCA		B	4/5/2035
2021	PO5051334046	KU	5	35 BRN	ST	CCA		V	4/6/2035
2021	PO5359211422	KU	3	40 BRO	SP	P		B	4/7/2035
2021	PO4043285559	F	4	40 BRO	SP	CRE		V	4/8/2035
2021	PO4028585855	F	4	40 KOP	SP	P		V	4/9/2035
2021	PO4032186336	LGE	5	35 ACE	SP	CCA		V	4/10/2035
2021	PO4035586382	LGE	3	50 ACE	SP	CRE		V	4/11/2035
2021	PO5411211229	F	3	40 BRO	SP	CRE		V	4/12/2035
2021	PO5280125930	KU	3	45 BRN	SP	CCA		V	4/13/2035
2021	PO5280125995	KU	2	45 BRN	SP	CRE		B	4/14/2035
2021	PO4023185799	LGE	3	45 KOP	SP	CCA		V	4/15/2035
2021	PO4032986389	LGE	3	45 ACE	SP	CCA		V	4/16/2035
2021	7458175458	LGE	4	30 ACE	SP	CCA		V	4/17/2035
2021	PO5043634084	KU	3	45 BRN	SP	CCA		V	4/18/2035
2021	PO5423611212	KU	6	30 BRO	SP	CRE		V	4/19/2035
2021	PO5025233793	KU	3	45 BRN	SP	CCA		V	4/20/2035
2021	PO5019733698	KU	3	40 BRN	SP	CCA		V	4/21/2035
2021	PO4030585847	LGE	3	45 KOP	SP	CCA		V	4/22/2035
2021	PO4140385982	LGE	1	80 BRO	SP	CRE		V	4/23/2035
2021	PO4021585761	LGE	4	40 KOP	UN	CCA		V	4/24/2035
2021	PO4026185865	F	3	45 KOP	SP	CCA		V	4/25/2035
2021	PO7510675004	LGE	4	35 ACE	SP	CCA		V	4/26/2035
2021	PO7516574968	LGE	5	35 ACE	SP	CCA		V	4/27/2035
2021	PO7522374933	LGE	5	35 ACE	SP	CCA		V	4/28/2035
2021	PO7500574957	LGE	4	35 ACE	SP	CCA		V	4/29/2035
2021	PO7501974987	LGE	4	40 ACE	SP	CCA		V	4/30/2035
2021	PO7504475041	LGE	4	40 ACE	SP	CCA		V	5/1/2035
2021	PO4013186330	F	4	40 ACE	SP	CCA		V	5/2/2035
2021	PO4039486082	LGE	3	45 KOP	SP	CCA		V	5/3/2035
2021	PO5392611291	F	3	40 BRO	SP	P		V	5/4/2035
2021	PO4028085859	LGE	3	45 KOP	SP	CCA		V	5/5/2035
2021	PO4051085555	F	4	40 BRO	SP	CCA		V	5/6/2035
2021	PO4049785551	F	4	30 BRO	SP	P		V	5/7/2035

2021 PO4048585552	F	4	30 BRO	SP	CCA	V	5/8/2035
2021 PO4047485557	LGE	3	45 BRO	SP	CCA	V	5/9/2035
2021 PO7495575046	LGE	4	30 ACE	SP	CCA	V	5/10/2035
2021 PO7497475114	LGE	4	40 ACE	SP	CCA	V	5/11/2035
2021 PO7494575142	LGE	4	35 ACE	SP	CCA	V	5/12/2035
2021 PO4049885555	LGE	3	45 BRO	SP	CCA	V	5/13/2035
2021 PO4061985655	F	4	35 BRO	SP	CRE	V	5/14/2035
2021 PO4063185654	F	4	40 BRO	SP	CRE	V	5/15/2035
2021 PO4064285654	F	4	40 BRO	SP	P	V	5/16/2035
2021 PO4064885652	F	4	40 BRO	SP	P	V	5/17/2035
2021 PO4047485552	F	4	30 BRO	SP	CCA	V	5/18/2035
2021 PO4046185553	F	5	35 BRO	SP	CCA	V	5/19/2035
2021 PO4046185557	F	4	40 BRO	SP	CRE	V	5/20/2035
2021 PO4044985553	F	4	30 BRO	SP	CRE	V	5/21/2035
2021 PO4044985558	F	4	40 BRO	SP	CRE	V	5/22/2035
2021 PO5119438407	KU	4	40 BRO	SP	CCA	B	5/23/2035
2021 PO5278525642	KU	3	45 BRN	SP	CCA	V	5/24/2035
2021 PO5280125839	KU	3	45 BRN	SP	CCA	V	5/25/2035
2021 PO5429311171	F	3	40 BRO	SP	P	V	5/26/2035
2021 PO4030286340	LGE	4	40 ACE	SP	CCA	V	5/27/2035
2021 PO4037185968	F	3	45 KOP	SP	CCA	V	5/28/2035
2021 PO4036585954	F	4	40 KOP	SP	P	V	5/29/2035
2021 PO4035985941	F	4	40 KOP	SP	CCA	V	5/30/2035
2021 PO4060085750	LGE	4	40 BRO	SP	P	V	5/31/2035
2021 PO7733169230	LGE	4	30 BRO	SP	CCA	V	6/1/2035
2021 PO4058685751	F	4	40 BRO	SP	CCA	V	6/2/2035
2021 PO4035485927	F	3	45 KOP	SP	CCA	V	6/3/2035
2021 PO4034885914	F	4	40 KOP	SP	P	V	6/4/2035
2021 PO4034285899	F	4	40 KOP	SP	CCA	V	6/5/2035
2021 PO5231926093	KU	2	50 BRN	SP	CRE	B	6/6/2035
2021 PO5225126521	F	4	40 BRN	SP	CRE	V	6/7/2035
2021 PO5543410064	F	4	40 KOP	SP	P	V	6/8/2035
2021 PO5498010384	KU	5	35 KOP	SP	S	V	6/9/2035
2021 PO5502009955	KU	6	30 KOP	SP	S	V	6/10/2035
2021 PO5290931513	KU	5	35 BRN	SP	CCA	V	6/11/2035
2021 PO5213226652	KU	5	30 BRN	SP	CRE	B	6/12/2035
2021 PO5550810075	F	4	40 KOP	SP	S	V	6/13/2035
2021 PO5565110096	F	5	35 KOP	SP	S	V	6/14/2035
2021 PO5575210109	KU	4	40 KOP	SP	S	V	6/15/2035
2021 PO5484710520	KU	5	35 KOP	SP	S	V	6/16/2035
2021 PO3943685922	F	3	50 ACE	SP	CRE	V	6/17/2035
2021 PO4003786458	F	3	50 ACE	SP	CRE	V	6/18/2035
2021 PO4056085863	F	4	40 BRO	SP	CRE	V	6/19/2035
2021 PO4055985850	F	4	40 BRO	SP	CRE	V	6/20/2035
2021 PO4055985837	F	3	45 BRO	SP	CCA	V	6/21/2035
2021 PO4055185824	F	4	40 BRO	SP	CRE	V	6/22/2035
2021 PO4053885825	F	4	40 BRO	SP	P	V	6/23/2035
2021 PO4052585825	F	4	40 BRO	SP	CRE	V	6/24/2035
2021 PO4052485833	F	4	40 BRO	SP	CCA	V	6/25/2035
2021 PO4052585844	F	4	40 BRO	SP	CCA	V	6/26/2035
2021 PO4052685856	F	4	40 BRO	SP	CRE	V	6/27/2035
2021 PO4060385822	F	3	45 BRO	SP	CCA	V	6/28/2035
2021 PO4059085823	F	4	40 BRO	SP	CRE	V	6/29/2035
2021 PO4057785823	F	4	40 BRO	SP	CRE	V	6/30/2035

2021 PO4056485824	F	4	40 BRO	SP	CRE		V			7/1/2035
2021 PO4056185876	F	3	45 BRO	SP	CCA		V			7/2/2035
2021 PO5129226681	KU	4	40 BRN	SP	CRE		T			7/3/2035
2021 PO4027685736	LGE	4	35 KOP	SP	P	ED,ID	TD			7/4/2035
2021 PO4028085747	LGE	4	35 KOP	SP	P	ED,ID,IP	TD			7/5/2035
2021 PO6021812297	KU	4	45 KOP	SP	CRE	ED,HH,ID,RB	BX	PX		7/6/2035
2021 PO5484110392	KU	4	40 KOP	SP	CRE	ED,ID	BD			7/7/2035
2021 PO4154086050	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TX	RR		7/8/2035
2021 PO4152886050	LGE	2	95 BRO	SP	A	ED,ID	TD			7/9/2035
2021 PO4136086061	LGE	4	40 BRO	SP	A	ED,ID	TD			7/10/2035
2021 PO4053186638	LGE	4	35 ACE	SP	CRE	ED,ID	TD			7/11/2035
2021 PO4052586626	LGE	4	40 ACE	SP	CRE	ED,ID	TD			7/12/2035
2021 PO4052186615	LGE	4	40 ACE	SP	CRE	ED,ID	TD			7/13/2035
2021 PO5186626901	KU	5	35 BRN	SP	CRE		T			7/14/2035
2021 PO4028585759	LGE	4	40 KOP	SP	P	ED	TD			7/15/2035
2021 PO6168609987	KU	5	35 KOP	SP	CRE	ED,ID	TD			7/16/2035
2021 PO5305230316	KU	4	40 BRN	SP	CRE	ID,RB	X	RP1		7/17/2035
2021 PO5261231282	KU	2	40 BRN	SP	CRE	ED,ID	BX	RP2		7/18/2035
2021 PO5296131345	KU	3	45 BRN	SP	CRE	HH,ID,IP	BX	RP1		7/19/2035
2021 PO5257531177	KU	3	45 BRN	SP	CRE	ID	BD			7/20/2035
2021 PO5284331405	KU	4	45 BRN	SP	CRE	ID	TD			7/21/2035
2021 PO5431211312	KU	3	40 BRO	SP	CRE	ID	TD			7/22/2035
2021 PO5442311274	KU	6	40 BRO	SP	P	ED,ID	T			7/23/2035
2021 PO4063986522	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP3		7/24/2035
2021 PO4871532754	KU	4	40 BRN	SP	CRE	ID	TD			7/25/2035
2021 PO4965732725	KU	4	40 BRN	SP	CRE	ID	BD			7/26/2035
2021 PO5231226137	KU	4	40 BRN	SP	CRE	ID,IP,RB	BX	RP2		7/27/2035
2021 PO4029686329	LGE	5	25 ACE	SP	CRE	ED,ID	TD			7/28/2035
2021 PO8498601118	KU	4	40 XXX	SP	CRE	ED,HH,ID,IP,RB	X	PX		7/29/2035
2021 PO8345402128	KU	1	55 XXX	SP	S		V			7/30/2035
2021 PO8356002072	KU	1	50 XXX	SP	S		V			7/31/2035
2021 PO8369001982	KU	1	55 XXX	SP	S		V			8/1/2035
2021 PO8382201875	KU	1	55 XXX	SP	S		V			8/2/2035
2021 PO8392801808	KU	1	55 XXX	SP	S		V			8/3/2035
2021 PO8402601736	KU	1	60 XXX	SP	S		V			8/4/2035
2021 PO8410601681	KU	1	60 XXX	SP	S		V			8/5/2035
2021 PO8414101656	KU	1	60 XXX	SP	S		V			8/6/2035
2021 PO4376819458	KU	5	35 XXX	SP	CRE	ID	TD			8/7/2035
2021 PO4376919253	KU	5	40 XXX	SP	CRE	ID	TD			8/8/2035
2021 PO4377019072	KU	5	35 XXX	SP	CRE	ID	TD			8/9/2035
2021 PO4377018910	KU	4	35 XXX	SP	CRE	ID	BD			8/10/2035
2021 PO4376818736	KU	4	40 XXX	SP	CCA		V			8/11/2035
2021 PO4375918573	KU	4	35 XXX	SP	CRE	ID	BD			8/12/2035
2021 PO4374618387	KU	4	40 XXX	SP	CRE	ID	TD			8/13/2035
2021 PO4375918244	KU	4	35 XXX	SP	CRE	ID	TD			8/14/2035
2021 PO4362117843	KU	4	40 XXX	SP	CRE	ID	TD			8/15/2035
2021 PO4378817938	KU	4	40 XXX	SP	CRE	ID	TD			8/16/2035
2021 PO5079084947	LGE	3	45 ACE	SP	CCA		V			8/17/2035
2021 PO5077984941	LGE	3	45 ACE	SP	A	ED,ID	BD			8/18/2035
2021 PO4939985005	LGE	3	45 BRO	SP	CCA		V			8/19/2035
2021 PO4941084998	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD			8/20/2035
2021 PO5074384917	LGE	3	50 ACE	SP	A	ED	BD			8/21/2035
2021 PO5074884901	LGE	4	35 ACE	SP	CCA		V			8/22/2035
2021 PO4940085011	F	3	50 BRO	SP	CCA		V			8/23/2035

2021 PO4942085008	F	3	50 BRO	SP	CCA		V	8/24/2035
2021 PO5069184911	LGE	4	30 ACE	SP	CRE		V	8/25/2035
2021 PO5071084902	LGE	3	45 ACE	SP	CCA	ED	BD	8/26/2035
2021 PO2076273710	KU	5	35 BRO	SP	CRE	ED,IP,MD,SRS	TD	8/27/2035
2021 PO2093173876	KU	4	40 BRO	SP	CCA	ED,SRS	T	8/28/2035
2021 PO2056573551	F	4	40 BRO	SP	CRE		V	8/29/2035
2021 PO2080374009	KU	4	40 BRO	SP	CRE	ED,IP	BD	8/30/2035
2021 PO2061373518	KU	4	45 BRO	SP	CCA		V	8/31/2035
2021 PO5069284911	LGE	3	40 ACE	SP	P	ED	BD	9/1/2035
2021 PO2225274909	F	5	35 BRO	SP	CCA		V	9/2/2035
2021 PO4953784963	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/3/2035
2021 PO4952284977	LGE	5	30 BRO	SP	CRE	ID	V	9/4/2035
2021 PO4709611147	KU	4	40 KOP	SP	CRE	ED,ID	TD	9/5/2035
2021 PO4718411021	KU	6	30 KOP	SP	CRE	ED,ID,IP	BD	9/6/2035
2021 PO4687911284	F	4	40 KOP	SP	S		V	9/7/2035
2021 PO4779410687	KU	5	35 KOP	SP	CRE	ED,ID	BD	9/8/2035
2021 PO4738411031	KU	1	65 KOP	ST	CCA		V	9/9/2035
2021 PO4778710726	KU	4	40 KOP	SP	CRE	ED,ID	BD	9/10/2035
2021 PO4684511422	KU	4	45 KOP	SP	S		V	9/11/2035
2021 PO5064184909	LGE	2	50 ACE	SP	P	ED	BD	9/12/2035
2021 PO4863586203	LGE	1	50 ACE	SP	CCA		V	9/13/2035
2021 PO4528687592	F	4	45 BRO	SP	P		V	9/14/2035
2021 PO4529487570	F	4	30 BRO	SP	P		V	9/15/2035
2021 PO4528787571	F	3	45 BRO	SP	CCA		V	9/16/2035
2021 PV2382288234	F	2	55 BRO	SP	P		V	9/17/2035
2021 PO4605911831	F	4	40 KOP	SP	CRE	ED,HH,ID	BX	PX 9/18/2035
2021 PO4708411243	KU	3	45 KOP	SP	S		V	9/19/2035
2021 PO4773810618	KU	5	35 KOP	SP	CRE	ED,ID	BD	9/20/2035
2021 PO4682511390	KU	1	65 KOP	ST	CCA		V	9/21/2035
2021 PO4748910965	KU	3	45 KOP	SP	S		V	9/22/2035
2021 PO4688511511	KU	3	45 KOP	SP	S		V	9/23/2035
2021 PO4756310843	KU	4	40 KOP	SP	P	ED,ID	BD	9/24/2035
2021 PO4788010741	KU	4	40 KOP	SP	S		V	9/25/2035
2021 PO4770110831	KU	3	65 KOP	ST	CRE		V	9/26/2035
2021 PO4698111287	KU	4	40 KOP	SP	S		V	9/27/2035
2021 PO4736010879	KU	4	40 KOP	SP	CRE	ED,ID,IP	TD	9/28/2035
2021 PO4717011101	F	4	40 KOP	SP	S		V	9/29/2035
2021 PO4724711053	F	4	30 KOP	SP	S		V	9/30/2035
2021 PO4764110469	KU	5	35 KOP	SP	S		V	10/1/2035
2021 PO4775910742	F	4	40 KOP	SP	S		V	10/2/2035
2021 PO4723211128	KU	4	45 KOP	SP	CRE	ED,ID	TD	10/3/2035
2021 PO4709011216	KU	1	65 KOP	ST	CCA		V	10/4/2035
2021 PO4679211347	F	4	45 KOP	SP	S		V	10/5/2035
2021 PO4744810924	F	4	40 KOP	SP	P		V	10/6/2035
2021 PO4709611147	F	4	45 KOP	SP	S		V	10/7/2035
2021 PO4696311235	F	4	40 KOP	SP	S		V	10/8/2035
2021 PO4703111190	F	4	40 KOP	SP	S		V	10/9/2035
2021 PO4687911477	KU	4	45 KOP	SP	S		V	10/10/2035
2021 PO5059784867	LGE	4	40 ACE	SP	P	ED	BD	10/11/2035
2021 PO5057584858	LGE	4	40 ACE	SP	CCA	ED	BD	10/12/2035
2021 PO5055484850	LGE	4	40 ACE	SP	CRE	ED,ID	BD	10/13/2035
2021 PO5053284845	LGE	3	45 ACE	SP	A	ED	BD	10/14/2035
2021 PO5051084840	LGE	4	40 ACE	SP	CCA	ED,ID	BD	10/15/2035
2021 PO2221474950	KU	6	35 BRO	SP	CRE	ED,IP,SRS	TD	10/16/2035



2021 PO4952784945	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/17/2035
2021 PO5073285388	LGE	3	55 ACE	SP	CCA		V	10/18/2035
2021 PO5070785397	LGE	2	55 ACE	SP	CCA		V	10/19/2035
2021 PO5070085401	LGE	1	60 ACE	SP	CCA		V	10/20/2035
2021 PO4951184948	LGE	3	45 BRO	SP	A	ED,ID	TD	10/21/2035
2021 PO5068185419	LGE	2	55 ACE	SP	CCA		V	10/22/2035
2021 PO4854885503	LGE	6	25 ACE	SP	CRE	ED,ID	BD	10/23/2035
2021 PO4854485501	LGE	4	40 ACE	SP	A	ED,IP	BD	10/24/2035
2021 PO5066985442	LGE	4	30 ACE	SP	CCA	ED,ID	BD	10/25/2035
2021 PO5066485438	LGE	3	50 ACE	SP	CCA		V	10/26/2035
2021 PO4949584954	LGE	4	40 BRO	SP	A	ED,ID	TD	10/27/2035
2021 PO4856585468	LGE	3	45 ACE	SP	P	ED	TD	10/28/2035
2021 PO5065285457	LGE	3	50 ACE	SP	CCA		V	10/29/2035
2021 PO5063685477	LGE	3	50 ACE	SP	CCA		V	10/30/2035
2021 PO5062185495	LGE	1	50 ACE	SP	CCA	ED,ID	V	10/31/2035
2021 PO5052685798	LGE	4	35 ACE	SP	CCA		V	11/1/2035
2021 PO4857685466	LGE	4	40 ACE	SP	CRE	ED	BD	11/2/2035
2021 PO5061285505	LGE	3	50 ACE	SP	CCA	ED,ID	V	11/3/2035
2021 PO5060685518	LGE	4	30 ACE	SP	CRE		V	11/4/2035
2021 PO5060485515	LGE	3	50 ACE	SP	CCA		V	11/5/2035
2021 PO4984885320	F	4	40 BRO	SP	A		V	11/6/2035
2021 PO4984985302	F	4	40 BRO	SP	A		V	11/7/2035
2021 PO5056285531	LGE	4	40 ACE	SP	CRE	ED,ID	BD	11/8/2035
2021 PO4552887977	LGE	4	40 BRO	SP	CRE		V	11/9/2035
2021 PO5057185547	LGE	3	50 ACE	SP	CCA		V	11/10/2035
2021 PO5055885569	LGE	3	50 ACE	SP	CCA		V	11/11/2035
2021 PO5056085594	LGE	4	30 ACE	SP	CCA		V	11/12/2035
2021 PO5054685603	LGE	3	50 ACE	SP	CCA		V	11/13/2035
2021 PO5055285589	LGE	3	50 ACE	SP	CCA		V	11/14/2035
2021 PO5054485585	LGE	4	30 ACE	SP	CCA		V	11/15/2035
2021 PO5053685618	LGE	3	50 ACE	SP	CCA		V	11/16/2035
2021 PO5052985637	LGE	2	55 ACE	SP	CCA		V	11/17/2035
2021 PO5050985684	LGE	3	50 ACE	SP	CCA		V	11/18/2035
2021 PO5051685668	LGE	3	50 ACE	SP	CCA		V	11/19/2035
2021 PO5052285652	LGE	3	50 ACE	SP	CCA		V	11/20/2035
2021 PO5050385700	LGE	3	50 ACE	SP	CCA		V	11/21/2035
2021 PO5049685716	LGE	3	50 ACE	SP	CCA		V	11/22/2035
2021 PO5049285727	LGE	3	50 ACE	SP	CCA		V	11/23/2035
2021 PO4985185365	LGE	5	30 BRO	SP	A	ID	BD	11/24/2035
2021 PO4985085361	F	4	40 BRO	SP	A		V	11/25/2035
2021 PO4983685360	F	4	40 BRO	SP	A		V	11/26/2035
2021 PO4983685367	F	4	30 BRO	SP	P		V	11/27/2035
2021 PO5051685648	LGE	4	30 ACE	SP	CCA		V	11/28/2035
2021 PO4987785375	KU	4	35 BRO	SP	A		V	11/29/2035
2021 PO5048285752	F	1	55 ACE	SP	CCA		V	11/30/2035
2021 PO4987885369	KU	4	40 BRO	SP	CRE		V	12/1/2035
2021 PO4986285356	F	4	40 BRO	SP	CCA		V	12/2/2035
2021 PO4986885337	F	4	40 BRO	SP	A		V	12/3/2035
2021 PO4988685348	LGE	4	30 BRO	SP	A	ED,ID	TD	12/4/2035
2021 PO4988085346	F	4	40 BRO	SP	CRE		V	12/5/2035
2021 PO4988085796	LGE	H1	65 ACE	SP	CCA		V	12/6/2035
2021 PO4989885373	LGE	4	35 BRO	SP	A		V	12/7/2035
2021 PO4849485782	F	4	40 ACE	SP	P		V	12/8/2035
2021 PO4899185661	LGE	H1	65 ACE	SP	CCA		V	12/9/2035

2021 PO4583212086	KU	5	35 KOP	SP	S		V		12/10/2035
2021 PO4596212167	KU	6	30 KOP	SP	S		V		12/11/2035
2021 PO4587312154	KU	5	35 KOP	SP	S		V		12/12/2035
2021 PO4855186158	LGE	4	40 ACE	SP	P	ED,IP	BD		12/13/2035
2021 PO5089984829	LGE	4	40 ACE	SP	A	ED,ID	BD		12/14/2035
2021 PO5091584820	LGE	4	40 ACE	SP	A	ED,ID	BD		12/15/2035
2021 PO4855386152	LGE	3	35 ACE	SP	P	ED,ID,RB	BD		12/16/2035
2021 PO4857786175	LGE	4	40 ACE	SP	P	ED,IP	BD		12/17/2035
2021 PO4855386152	LGE	3	45 ACE	SP	P	ED,ID,RB	BX	RR	12/18/2035
2021 PO7706180327	KU	1	60 ACE	ST	CCA		V		12/19/2035
2021 PO7744280423	KU	5	35 ACE	SP	CRE	ED,ID	TD		12/20/2035
2021 PO7680980091	KU	1	75 ACE	SP	CCA		V		12/21/2035
2021 PO7751979990	KU	4	40 ACE	SP	CRE		V		12/22/2035
2021 PO7756179939	KU	3	45 ACE	SP	CCA		V		12/23/2035
2021 PO4860585468	LGE	4	40 ACE	SP	CRE	ED,IP	TD		12/24/2035
2021 PO4947984964	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		12/25/2035
2021 PO4862585470	LGE	4	40 ACE	SP	CRE	ED,IP	TD		12/26/2035
2021 PO4861085471	LGE	4	40 ACE	SP	CCA		V		12/27/2035
2021 PO4861485489	LGE	4	40 ACE	SP	CCA		V		12/28/2035
2021 PO5057485483	LGE	4	40 ACE	SP	CRE	ED,ID	BD		12/29/2035
2021 PO4851085767	LGE	4	40E ACE	SP	P	ED,IP	TD		12/30/2035
2021 PO4850285774	F	4	25 ACE	SP	P		V		12/31/2035
2021 PO4985285337	LGE	4	30 BRO	SP	A	ID	BD		1/1/2036
2021 PO4984785339	F	4	40 BRO	SP	A		V		1/2/2036
2021 PO4983385344	F	4	40 BRO	SP	A		V		1/3/2036
2021 PO5059085502	LGE	3	45 ACE	SP	CCA		V		1/4/2036
2021 PO4981685318	LGE	4	30 BRO	SP	A	ED,ID	TD		1/5/2036
2021 PO4981985312	F	4	40 BRO	SP	A		V		1/6/2036
2021 PO5059685523	LGE	3	50 ACE	SP	CCA		V		1/7/2036
2021 PO5058485531	LGE	3	50 ACE	SP	CCA		V		1/8/2036
2021 PO5103484758	LGE	3	45 ACE	SP	P	ED	TD		1/9/2036
2021 PO2065873966	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD		1/10/2036
2021 PO4533587951	LGE	4	40 BRO	SP	CCA	ED,ID	BD		1/11/2036
2021 PO4532687945	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		1/12/2036
2021 PO4531187936	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		1/13/2036
2021 PO4532487931	LGE	3	45 BRO	SP	CCA		V		1/14/2036
2021 PO4531887940	LGE	3	45 BRO	SP	CCA		V		1/15/2036
2021 PO4530287930	LGE	4	40 BRO	SP	P	ED,ID	TD		1/16/2036
2021 PV5116084814	LGE	H3	45 ACE	SP	P	ED	BD		1/17/2036
2021 PO5116384832	LGE	3	45 ACE	SP	P	ED	BD		1/18/2036
2021 PO5117784846	LGE	3	45 ACE	SP	P	ED	BD		1/19/2036
2021 PO4503113013	KU	6	30 KOP	SP	CRE	ED,ID	TD		1/20/2036
2021 PO4524212735	KU	4	45 KOP	SP	S		V		1/21/2036
2021 PO4517112851	KU	4	45 KOP	SP	S		V		1/22/2036
2021 PO4462312679	KU	6	30 KOP	SP	CRE		V		1/23/2036
2021 PO4521213093	KU	3	45 KOP	SP	S		V		1/24/2036
2021 PO4526112823	KU	4	45 KOP	SP	CRE	ED,ID	TD		1/25/2036
2021 PO4853185601	LGE	4	35 ACE	SP	A	ED,ID	X	RP2	1/26/2036
2021 PO4853985613	LGE	4	35 ACE	SP	CCA		V		1/27/2036
2021 PO4527987916	LGE	4	40 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP2	1/28/2036
2021 PO4528687920	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		1/29/2036
2021 PO4527187911	LGE	3	45 BRO	SP	CCA		V		1/30/2036
2021 PO4529487926	LGE	3	45 BRO	SP	CCA		V		1/31/2036
2021 PO4528987609	LGE	4	40 BRO	SP	P	ED,ID	BD		2/1/2036

2021	PO4537512281	F	4	40 KOP	SP	CRE		V	2/2/2036
2021	PO4521612386	F	4	40 KOP	SP	CRE		V	2/3/2036
2021	PO4513312441	F	4	40 KOP	SP	P		V	2/4/2036
2021	PO4513912723	KU	4	45 KOP	SP	S		V	2/5/2036
2021	PO4497312547	F	2	50 KOP	SP	S		V	2/6/2036
2021	PO4552912181	F	4	40 KOP	SP	CRE		V	2/7/2036
2021	PO4562512188	KU	4	40 KOP	SP	S		V	2/8/2036
2021	PO4578012081	KU	2	70 KOP	SP	P		V	2/9/2036
2021	PO4465712740	F	4	40 KOP	SP	CRE		V	2/10/2036
2021	PO4517711377	F	4	40 KOP	SP	CRE		V	2/11/2036
2021	PO4480410478	F	4	40 KOP	SP	CRE		V	2/12/2036
2021	PO4447712850	F	2	50 KOP	SP	S		V	2/13/2036
2021	PO4439712976	KU	2	65 KOP	SP	CRE		V	2/14/2036
2021	PO4526411592	F	4	40 KOP	SP	CRE		V	2/15/2036
2021	PO4449812630	F	4	40 KOP	SP	CRE		V	2/16/2036
2021	PO4440912695	F	4	40 KOP	SP	CRE		V	2/17/2036
2021	PO4450112903	KU	2	65 KOP	SP	CRE		V	2/18/2036
2021	PO4491010729	F	4	40 KOP	SP	CRE		V	2/19/2036
2021	PO4452612609	KU	3	45 KOP	SP	S		V	2/20/2036
2021	PO4474410344	F	4	40 KOP	SP	CRE		V	2/21/2036
2021	PO4444012940	KU	5	35 KOP	SP	S		V	2/22/2036
2021	PO4496610863	F	4	40 KOP	SP	CRE		V	2/23/2036
2021	PO4485810600	F	4	40 KOP	SP	CRE		V	2/24/2036
2021	PO4501510983	F	4	40 KOP	SP	CRE		V	2/25/2036
2021	PO4443812762	F	4	40 KOP	SP	CRE		V	2/26/2036
2021	PO4457212577	F	4	40 KOP	SP	CRE		V	2/27/2036
2021	PO4507511128	F	4	40 KOP	SP	P		V	2/28/2036
2021	PO4513011263	F	4	40 KOP	SP	CRE		V	2/29/2036
2021	PO4544687950	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	3/1/2036
2021	PO4543587944	LGE	3	45 BRO	SP	P	ED,ID,IP	TD	3/2/2036
2021	PO4540487994	LGE	3	45 BRO	SP	P	ED,ID,IP	BD	3/3/2036
2021	PO4539387987	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	3/4/2036
2021	PO4538487982	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	3/5/2036
2021	PO4535387962	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	3/6/2036
2021	PO4537887965	LGE	3	45 BRO	SP	CCA		V	3/7/2036
2021	PO4537287974	LGE	3	45 BRO	SP	CCA		V	3/8/2036
2021	PO4536287968	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	3/9/2036
2021	PO4503113013	KU	4	40 KOP	SP	S		V	3/10/2036
2021	PO4850385750	LGE	3	45 ACE	SP	CRE	ED,ID	BD	3/11/2036
2021	PO5115484795	LGE	H3	45 ACE	SP	P	ED	TD	3/12/2036
2021	PO4849785682	LGE	3	45 ACE	SP	CCA		V	3/13/2036
2021	PO4850685681	LGE	4	30 ACE	SP	P	ED,IP	TD	3/14/2036
2021	PO4372217547	KU	4	35 XXX	SP	CRE	ID	TD	3/15/2036
2021	PO4369117440	KU	4	40 XXX	SP	CRE	ID	TD	3/16/2036
2021	PO4853085658	LGE	4	40 ACE	SP	P	ED,IP	TD	3/17/2036
2021	PO5115084769	LGE	H3	45 ACE	SP	P	ED	TD	3/18/2036
2021	PO4363717284	KU	4	35 XXX	SP	CRE	ID	TD	3/19/2036
2021	PO4359717132	KU	4	35 XXX	SP	CRE	ID	TD	3/20/2036
2021	PO4355516973	KU	4	40 XXX	SP	CRE	ID	BD	3/21/2036
2021	PO4175618258	KU	4	40 XXX	SP	CRE	ID	BD	3/22/2036
2021	PO4850185666	LGE	3	45 ACE	SP	P	ED,IP	BD	3/23/2036
2021	PO8125385077	F	3	45 ACE	SP	CRE		V	3/24/2036
2021	PO8129084990	F	4	40 ACE	SP	P		V	3/25/2036
2021	PO5113484753	LGE	3	45 ACE	SP	P	ED	BD	3/26/2036

2021 PO4335917084	KU	4	40 XXX	SP	CCA		V	3/27/2036
2021 PO4321417158	KU	4	40 XXX	SP	CRE	ID	TD	3/28/2036
2021 PO4286517352	KU	4	40 XXX	SP	CRE	ID	TD	3/29/2036
2021 PO4260517495	KU	4	40 XXX	SP	CRE	ID	TD	3/30/2036
2021 PO4238517726	KU	4	45 XXX	SP	CRE	ID	BD	3/31/2036
2021 PO4217017949	KU	4	45 XXX	SP	CCA		V	4/1/2036
2021 PO5102384702	LGE	3	45 ACE	SP	P	ED	BD	4/2/2036
2021 PO5102184676	LGE	3	45 ACE	SP	P	ED	BD	4/3/2036
2021 PO5101584651	LGE	3	45 ACE	SP	P	ED	BD	4/4/2036
2021 PO5100484623	LGE	3	45 ACE	SP	P	ED	BD	4/5/2036
2021 PO4851385619	LGE	3	45 ACE	SP	P	ED,IP	BD	4/6/2036
2021 PO4850785642	LGE	3	45 ACE	SP	CCA		V	4/7/2036
2021 PO8132384917	F	4	40 ACE	SP	CRE		V	4/8/2036
2021 PO3966385785	F	4	40 ACE	SP	CCA		V	4/9/2036
2021 PO3965485773	F	4	40 ACE	SP	CCA		V	4/10/2036
2021 PO3964885780	LGE	3	45 ACE	SP	CCA		V	4/11/2036
2021 PO3969385834	LGE	3	45 ACE	SP	CCA		V	4/12/2036
2021 PO3969085819	F	4	40 ACE	SP	CCA		V	4/13/2036
2021 PO3968685826	LGE	3	45 ACE	SP	CCA		V	4/14/2036
2021 PO3967285808	LGE	4	40 ACE	SP	CRE		V	4/15/2036
2021 PO3968285809	F	4	40 ACE	SP	CCA		V	4/16/2036
2021 PO3963885767	F	3	45 ACE	SP	CCA		V	4/17/2036
2021 PO3964585750	LGE	4	40 ACE	SP	CCA		V	4/18/2036
2021 PO4091386023	F	4	40 ACE	SP	CRE		V	4/19/2036
2021 PO4093986021	F	4	40 ACE	SP	CRE		V	4/20/2036
2021 PO4095286021	F	4	40 ACE	SP	CRE		V	4/21/2036
2021 PO4092686022	F	4	40 ACE	SP	CRE		V	4/22/2036
2021 PO4095986016	F	4	40 ACE	SP	CRE		V	4/23/2036
2021 PO3967686147	LGE	1	55 ACE	SP	CCA		V	4/24/2036
2021 PO4091586049	F	4	40 ACE	SP	CRE		V	4/25/2036
2021 PO4092886048	F	4	40 ACE	SP	CRE		V	4/26/2036
2021 PO4092886063	F	4	40 ACE	SP	CRE		V	4/27/2036
2021 PO4092986077	F	4	40 ACE	SP	CRE		V	4/28/2036
2021 PO4093286092	F	4	40 ACE	SP	CRE		V	4/29/2036
2021 PO3990485497	F	4	40 ACE	SP	CCA		V	4/30/2036
2021 PO3993085483	F	4	40 ACE	SP	CCA		V	5/1/2036
2021 PO3991885489	F	4	40 ACE	SP	CRE		V	5/2/2036
2021 PO3993485462	F	4	35 ACE	SP	CCA		V	5/3/2036
2021 PO3994885479	F	4	30 ACE	SP	CCA		V	5/4/2036
2021 PO3994685474	F	4	40 ACE	SP	CRE		V	5/5/2036
2021 PO3996285464	F	4	40 ACE	SP	CRE		V	5/6/2036
2021 PO4094186047	F	3	45 ACE	SP	CCA		V	5/7/2036
2021 PO4095386046	F	4	40 ACE	SP	CRE		V	5/8/2036
2021 PO4095986051	F	4	40 ACE	SP	CRE		V	5/9/2036
2021 PO4096186064	F	4	40 ACE	SP	CRE		V	5/10/2036
2021 PO4096186077	F	4	40 ACE	SP	CRE		V	5/11/2036
2021 PO4096286090	F	4	40 ACE	SP	CRE		V	5/12/2036
2021 PO4096386103	F	4	40 ACE	SP	CRE		V	5/13/2036
2021 PO4096586128	F	4	40 ACE	SP	CRE		V	5/14/2036
2021 PO3965686140	LGE	4	30 ACE	SP	P		V	5/15/2036
2021 PO4093686117	F	4	40 ACE	SP	CRE		V	5/16/2036
2021 PO4094986116	F	4	40 ACE	SP	CRE		V	5/17/2036
2021 PO4096486117	F	3	45 ACE	SP	CCA		V	5/18/2036
2021 PO4094486146	F	4	40 ACE	SP	CRE		V	5/19/2036

2021 PO4095186149	F	2	45 ACE	SP	CCA		V	5/20/2036
2021 PO3988085512	F	4	40 ACE	SP	CRE		V	5/21/2036
2021 PO3996185445	F	4	40 ACE	SP	CRE		V	5/22/2036
2021 PO6783873004	LGE	4	35 ACE	SP	CCA		V	5/23/2036
2021 PO4140686030	LGE	1	90 BRO	SP	CRE		V	5/24/2036
2021 PO4093286232	F	4	40 ACE	SP	CCA		V	5/25/2036
2021 PO4093786257	F	4	40 ACE	SP	CRE		V	5/26/2036
2021 PO4093786262	F	4	40 ACE	SP	A		V	5/27/2036
2021 PO4093986277	F	4	40 ACE	SP	CCA		V	5/28/2036
2021 PO4094086293	F	4	40 ACE	SP	CRE		V	5/29/2036
2021 PO4094186306	F	2	45 ACE	SP	CCA		V	5/30/2036
2021 PO4094886338	F	UNK	25 ACE	SP	CRE		V	5/31/2036
2021 PO4094486338	F	UNK	45 ACE	SP	CRE		V	6/1/2036
2021 PO4142086037	LGE	4	35 BRO	SP	CRE		V	6/2/2036
2021 PO4141186031	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	6/3/2036
2021 PO4096986213	F	4	30 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	RP3 6/4/2036
2021 PO4093386339	LGE	4	40 ACE	SP	CRE	ED,ID	TD	6/5/2036
2021 PO3963486126	LGE	3	55 ACE	SP	A	ID	TD	6/6/2036
2021 PO3963486126B	KU	3	45 ACE	SP	A	ID	TD	6/7/2036
2021 PO3963486126A	KU	3	45 ACE	SP	A	ID	TD	6/8/2036
2021 PO4094286322	F	4	40 ACE	SP	CRE	ED,ID	BX	RP3 6/9/2036
2021 PO4092286118	F	4	40 ACE	SP	CRE	ED,ID	BX	RP3 6/10/2036
2021 PO4140486022	LGE	4	40 BRO	SP	A	ED,ID	TD	6/11/2036
2021 PO4141986022	LGE	4	35 BRO	SP	CRE	ED,ID	TD	6/12/2036
2021 PO4141886012	LGE	4	35 BRO	SP	A	ED,ID	TD	6/13/2036
2021 PO3989285504	LGE	4	40 ACE	SP	CCA	ED,ID	TD	6/14/2036
2021 PO3964986142A1	KU	4	30 ACE	SP	P	ED,ID	TD	6/15/2036
2021 PO3964986142	LGE	3	50 ACE	SP	A	ED,ID	TD	6/16/2036
2021 PO3996785462	LGE	UNK	25 ACE	SP	CRE	ED,ID	BD	6/17/2036
2021 PO4093786103	LGE	4	30 ACE	SP	CRE	ED,EP,ID	TD	6/18/2036
2021 PO4140486011	LGE	2	85 BRO	SP	CRE	ED,ID	TD	6/19/2036
2021 PO3963385762	LGE	4	40 ACE	SP	CRE	ID	TD	6/20/2036
2021 PO3966285803	LGE	4	40 ACE	SP	CRE	ED,EP,ID	X	PX 6/21/2036
2021 PO3964485763	LGE	4	30 ACE	SP	CRE	ID	BD	6/22/2036
2021 PO6821569949	LGE	4	30 ACE	SP	CRE	ED,ID	TD	6/23/2036
2021 PO3938785783	LGE	4	30 ACE	SP	A	ID	TD	6/24/2036
2021 PO4066486724	LGE	4	35 ACE	SP	A	ED,ID	BD	6/25/2036
2021 PO3996185482	LGE	4	30 ACE	SP	A	ED,ID	BD	6/26/2036
2021 PO3546805485	KU	4	40 XXX	SP	CRE	ID	BD	6/27/2036
2021 PO3516705882	KU	4	40 XXX	SP	CRE	ID	BD	6/28/2036
2021 PO4050986668	LGE	4	40 ACE	SP	CRE	ED,ID	TD	6/29/2036
2021 PO3948358756	LGE	4	45 ACE	SP	A	ID	BD	6/30/2036
2021 PO3985185565	LGE	4	35 ACE	SP	CRE	ED,ID	TD	7/1/2036
2021 PO4065686760	LGE	4	35 ACE	SP	CRE	ED,ID	BD	7/2/2036
2021 PO4066286789	LGE	4	35 ACE	SP	CRE	ED	TD	7/3/2036
2021 PO4068886799	LGE	4	40 ACE	SP	CRE	ED,ID	BD	7/4/2036
2021 PO4068786807	LGE	4	35 ACE	SP	CRE	ED,ID	BD	7/5/2036
2021 PO4068586788	LGE	4	35 ACE	SP	CRE	ED,ID	BD	7/6/2036
2021 4068886799A	LGE	4	40 ACE	SP	CRE	ED,ID	BD	7/7/2036
2021 PO4066986724	LGE	4	35 ACE	SP	CRE	ED,ID	TD	7/8/2036
2021 PO3987785633	LGE	UNK	25 ACE	SP	CRE	ED,ID	TD	7/9/2036
2021 PO4068486726	LGE	4	35 ACE	SP	CRE	ED,ID	BD	7/10/2036
2021 PO3954385874	LGE	4	30 ACE	SP	CRE	ED,HH,ID	TD	7/11/2036
2021 PO3953985872	LGE	4	30 ACE	SP	CRE	ID,IP	BD	7/12/2036

2021 PO3957786072	KU	2	55 ACE	SP	CRE	ED,ID,MD	TD	7/13/2036
2021 PO3959186084	LGE	3	50 ACE	SP	CRE	ED,ID	BD	7/14/2036
2021 PO3956386060	LGE	1	60 ACE	SP	CRE	ED,ID,IP	BD	7/15/2036
2021 PO4140486007	LGE	3	45 BRO	SP	CRE	ED,ID	TD	7/16/2036
2021 PO4088886006	LGE	4	35 ACE	SP	CRE	ED,ID	TD	7/17/2036
2021 PO3962685759	LGE	4	40 ACE	SP	A	ED,ID	TD	7/18/2036
2021 PO3962785755	LGE	4	40 ACE	SP	CRE	ID	TD	7/19/2036
2021 PO4142086031	LGE	3	45 BRO	SP	A	ID,IP	TD	7/20/2036
2021 PO4143586030	LGE	3	45 BRO	SP	A	ED,ID	TD	7/21/2036
2021 PO4144486030	LGE	3	45 BRO	SP	A	ED,ID,IP	TX	7/22/2036
2021 PO4145986029	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	7/23/2036
2021 PO4147586032	LGE	4	45 BRO	SP	A	ED,ID	TD	7/24/2036
2021 PO4148586041	LGE	4	35 BRO	SP	A	ED,ID	TD	7/25/2036
2021 PO3956386060A1	KU	1	55 ACE	SP	A	ID	TD	7/26/2036
2021 PO4087886006	LGE	4	35 ACE	SP	CRE	ED,ID	TD	7/27/2036
2021 PO4049386651	LGE	4	40 ACE	SP	CRE	ED,ID	TD	7/28/2036
2021 PO3951186014	LGE	3	50 ACE	SP	CRE	ED,ID	TD	7/29/2036
2021 PO3952386025	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD	7/30/2036
2021 PV8525572056	LGE	4	40 BRO	SP	A	ED	TD	7/31/2036
2021 PO3953786037	LGE	3	50 ACE	SP	A	ED,HH,ID	TD	8/1/2036
2021 PO4047686634	LGE	3	45 ACE	SP	CCA		T	8/2/2036
2021 PO4048586643	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/3/2036
2021 PO3949685997	LGE	3	50 ACE	SP	A	ED,ID	TD	8/4/2036
2021 PO3938885839	LGE	3	50 ACE	SP	CRE	ED,EP,HH,ID	X	8/5/2036
2021 PO4046286620	LGE	4	40 ACE	SP	A	ED,ID	TD	8/6/2036
2021 PO4047186621	LGE	4	30 ACE	SP	CRE	ED,ID	TD	8/7/2036
2021 PO4046986627	LGE	4	40 ACE	SP	CRE	ED	TD	8/8/2036
2021 PO3962686105	LGE	4	30 ACE	SP	A	ID	BD	8/9/2036
2021 PO4983532840	KU	3	45 BRN	SP	CCA		V	8/10/2036
2021 PO5263131483	KU	4	45 BRN	SP	CCA		V	8/11/2036
2021 PO4189686246	F	4	40 BRO	SP	CRE		V	8/12/2036
2021 PO4188086229	F	4	40 BRO	SP	CRE		V	8/13/2036
2021 PO5361612372	KU	3	35 BRO	SP	CCA		V	8/14/2036
2021 PO4065986623	LGE	4	40 ACE	SP	CCA		V	8/15/2036
2021 PO4062586638	LGE	5	30 ACE	SP	CCA		V	8/16/2036
2021 PO4062786640	LGE	3	45 ACE	SP	CCA		V	8/17/2036
2021 PO4878137754	KU	3	45 UNK	SP	CCA		B	8/18/2036
2021 PO4069485765	F	3	45 BRO	SP	CCA		V	8/19/2036
2021 PO4067185767	F	3	45 BRO	SP	CCA		V	8/20/2036
2021 PO4068385766	F	3	45 BRO	SP	CCA		V	8/21/2036
2021 PO4068285760	F	4	30 BRO	SP	CRE		V	8/22/2036
2021 PO4065785763	F	4	35 BRO	SP	A		V	8/23/2036
2021 PO4065985768	F	4	40 BRO	SP	CRE		V	8/24/2036
2021 PO4064385764	F	4	35 BRO	SP	CCA		V	8/25/2036
2021 PO4064485770	F	3	45 BRO	SP	CCA		V	8/26/2036
2021 PO4062085822	F	4	40 BRO	SP	CRE		V	8/27/2036
2021 PO4062485835	F	4	40 BRO	SP	CCA		V	8/28/2036
2021 PO4062085845	F	3	45 BRO	SP	CCA		V	8/29/2036
2021 PO4062285858	F	3	45 BRO	SP	CCA		V	8/30/2036
2021 PO4062385871	F	4	40 BRO	SP	CRE		V	8/31/2036
2021 PO4062385885	F	3	45 BRO	SP	CCA		V	9/1/2036
2021 PO4062485897	F	4	40 BRO	SP	CRE		V	9/2/2036
2021 PO4062585910	F	4	40 BRO	SP	CRE		V	9/3/2036
2021 PO4062685923	F	3	45 BRO	SP	CCA		V	9/4/2036

2021 PO4062785936	F	4	40 BRO	SP	CRE		V	9/5/2036
2021 PO4061386647	LGE	4	40 ACE	SP	CCA	ED,ID	V	9/6/2036
2021 PO5335212473	KU	3	40 BRO	SP	CCA		V	9/7/2036
2021 PO4018085589	LGE	4	35 KOP	SP	CCA		V	9/8/2036
2021 PO5422212128	KU	5	35 BRO	SP	CRE		V	9/9/2036
2021 PO5410012188	KU	3	35 BRO	SP	CCA		V	9/10/2036
2021 PO4017585525	F	4	40 KOP	SP	P		V	9/11/2036
2021 PO4015785519	F	3	45 KOP	SP	CCA		V	9/12/2036
2021 PO4015485529	F	4	40 KOP	SP	CCA		V	9/13/2036
2021 PO4017885534	F	4	40 KOP	SP	CCA		V	9/14/2036
2021 PO4017185547	F	3	45 KOP	SP	CCA		V	9/15/2036
2021 PO5089526378	F	4	40 BRN	SP	CRE		V	9/16/2036
2021 PO5080626463	KU	4	40 BRN	SP	CRE		B	9/17/2036
2021 PO5083826680	F	4	40 BRN	SP	CRE		V	9/18/2036
2021 PO5424212202	KU	6	30 BRO	SP	CRE		V	9/19/2036
2021 PO5399612310	KU	6	35 BRO	SP	CCA		V	9/20/2036
2021 PO5086526544	F	4	40 BRN	SP	CRE		V	9/21/2036
2021 4021486572A	F	5	30 ACE	SP	CRE		V	9/22/2036
2021 PO4021486572	F	4	35 ACE	SP	CRE		V	9/23/2036
2021 PO4021386564	LGE	4	30 ACE	SP	CCA		V	9/24/2036
2021 PO4011985611	LGE	3	45 KOP	SP	CCA		V	9/25/2036
2021 PO5486110020	KU	H1	85 KOP	SP	CRE		V	9/26/2036
2021 PO4022586566	F	4	35 ACE	SP	CRE		V	9/27/2036
2021 PO4013485610	LGE	4	40 KOP	SP	CCA		V	9/28/2036
2021 PO4014885608	LGE	4	40 KOP	SP	CCA		V	9/29/2036
2021 PO3976386232	F	4	35 ACE	SP	CRE		V	9/30/2036
2021 PO5047426871	KU	5	35 BRN	SP	CRE		B	10/1/2036
2021 PO5361911854	F	3	40 BRO	SP	P		V	10/2/2036
2021 PO5358711767	KU	2	50 BRO	SP	CCA		V	10/3/2036
2021 PO5353111613	F	2	45 BRO	SP	P		V	10/4/2036
2021 PO7208176133	LGE	4	40 ACE	SP	A		V	10/5/2036
2021 PO4002286458	LGE	4	30 ACE	SP	CCA		V	10/6/2036
2021 PO4016485701	LGE	4	40 KOP	SP	CCA		V	10/7/2036
2021 PO4015085705	LGE	4	40 KOP	SP	A		V	10/8/2036
2021 PO4002486454	F	3	50 ACE	SP	CRE		V	10/9/2036
2021 PO4001086452	LGE	4	35 ACE	SP	CCA		V	10/10/2036
2021 PO4001286448	F	1	55 ACE	SP	CCA		V	10/11/2036
2021 PO7124976019	LGE	4	35 ACE	SP	CCA		V	10/12/2036
2021 PO3999986438	F	3	50 ACE	SP	CRE		V	10/13/2036
2021 PO3997586422	LGE	4	30 ACE	SP	CCA		V	10/14/2036
2021 PO7111175902	LGE	4	35 ACE	SP	CCA		V	10/15/2036
2021 PO3998786428	F	2	55 ACE	SP	CCA		V	10/16/2036
2021 PO3997286419	F	7	25 ACE	SP	A		V	10/17/2036
2021 PO5547135203	KU	3	45 BRN	SP	CRE		B	10/18/2036
2021 PO5571535186	KU	4	45 BRN	SP	CRE		B	10/19/2036
2021 PO4069085802	F	4	40 BRO	SP	CRE		V	10/20/2036
2021 PO4070285802	F	3	45 BRO	SP	CCA		V	10/21/2036
2021 PO4071485801	F	4	40 BRO	SP	CCA		V	10/22/2036
2021 PO4072985799	F	3	45 BRO	SP	P		V	10/23/2036
2021 PO4074985817	F	3	50 BRO	SP	CCA		V	10/24/2036
2021 PO4072885817	F	4	40 BRO	SP	P		V	10/25/2036
2021 PO4074685797	F	4	40 BRO	SP	A		V	10/26/2036
2021 PO4074585785	F	4	40 BRO	SP	P		V	10/27/2036
2021 PO4074485773	F	3	45 BRO	SP	CCA		V	10/28/2036

2021 PO4869433624	KU	3	45 BRN	SP	CCA		V	10/29/2036
2021 PO4018885687	LGE	4	40 KOP	SP	CCA		V	10/30/2036
2021 PO4016785681	LGE	4	40 KOP	SP	CCA		V	10/31/2036
2021 PO4180086206	F	4	40 BRO	SP	CRE		V	11/1/2036
2021 PO4179086206	F	4	40 BRO	SP	CRE		V	11/2/2036
2021 PO4178086208	F	4	40 BRO	SP	CCA		V	11/3/2036
2021 PO4017785605	LGE	4	40 KOP	SP	P		V	11/4/2036
2021 PO4018185620	LGE	4	40 KOP	SP	A		V	11/5/2036
2021 PO4019185642	LGE	4	40 KOP	SP	A		V	11/6/2036
2021 PO4018685631	LGE	4	40 KOP	SP	A		V	11/7/2036
2021 PO4019585653	LGE	4	40 KOP	SP	P		V	11/8/2036
2021 PO4020085665	LGE	3	45 KOP	SP	CCA		V	11/9/2036
2021 PO4020485676	LGE	4	40 KOP	SP	CCA		V	11/10/2036
2021 PO4020885683	LGE	5	30 KOP	SP	P		V	11/11/2036
2021 PO5328512545	KU	6	35 BRO	SP	CCA		V	11/12/2036
2021 PO5349512527	KU	7	30 BRO	SP	CRE		B	11/13/2036
2021 PO3980586718	LGE	4	35 ACE	SP	CRE		V	11/14/2036
2021 PO5038426604	KU	4	40 BRN	SP	CRE		B	11/15/2036
2021 PO5520235194	KU	3	45 BRO	SP	CCA		V	11/16/2036
2021 PO4046586485	LGE	UNK	70 ACE	ST	P		V	11/17/2036
2021 PO3993285575	F	4	40 ACE	SP	CRE		V	11/18/2036
2021 PO3984285468	LGE	4	40 ACE	SP	CCA		V	11/19/2036
2021 PO3992785599	F	4	40 ACE	SP	CCA		V	11/20/2036
2021 PO4073786566	F	3	45 ACE	SP	CCA		V	11/21/2036
2021 PO4074786564	F	4	40 ACE	SP	CRE		V	11/22/2036
2021 PO4076086563	F	4	40 ACE	SP	CRE		V	11/23/2036
2021 PO4077386562	F	4	40 ACE	SP	CRE		V	11/24/2036
2021 PO4078586561	F	4	40 ACE	SP	CRE		V	11/25/2036
2021 PO4079786564	F	4	40 ACE	SP	CRE		V	11/26/2036
2021 PO4076886578	F	4	40 ACE	SP	CRE		V	11/27/2036
2021 PO4077686588	F	4	40 ACE	SP	CRE		V	11/28/2036
2021 PO4066285890	F	3	45 BRO	SP	CRE		V	11/29/2036
2021 PO4066785889	F	4	40 BRO	SP	CRE		V	11/30/2036
2021 PO4068385888	F	4	40 BRO	SP	CCA		V	12/1/2036
2021 PO4069385896	F	3	45 BRO	SP	CCA		V	12/2/2036
2021 PO4070685886	F	4	40 BRO	SP	CRE		V	12/3/2036
2021 PO4071485892	F	3	45 BRO	SP	CCA		V	12/4/2036
2021 PO4071785903	F	4	40 BRO	SP	CRE		V	12/5/2036
2021 PO4072585934	F	4	40 BRO	SP	CRE		V	12/6/2036
2021 PO4072185927	F	4	40 BRO	SP	CRE		V	12/7/2036
2021 PO4071685915	F	4	40 BRO	SP	CRE		V	12/8/2036
2021 PO4073285944	F	4	40 BRO	SP	CRE		V	12/9/2036
2021 PO4074285950	F	3	45 BRO	SP	CCA		V	12/10/2036
2021 PO4759538470	KU	4	40 BRO	SP	CCA		B	12/11/2036
2021 PO3992185623	F	4	40 ACE	SP	CCA		V	12/12/2036
2021 PO3991185631	F	4	40 ACE	SP	CRE		V	12/13/2036
2021 PO4078586598	F	4	40 ACE	SP	CRE		V	12/14/2036
2021 PO4079286608	F	4	40 ACE	SP	CRE		V	12/15/2036
2021 PO4080086619	F	4	40 ACE	SP	CRE		V	12/16/2036
2021 PO4080886629	F	4	40 ACE	SP	CRE		V	12/17/2036
2021 PO4031385022	LGE	4	40 BRO	SP	CRE	ED,ID	TD	12/18/2036
2021 PO4040485300	LGE	4	30 ACE	SP	CCA		V	12/19/2036
2021 PO4159485292	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	12/20/2036
2021 PO4159085287	LGE	3	45 ACE	SP	P	ED,ID	BD	12/21/2036



2021 PO4158385290	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD		12/22/2036
2021 PO4041585291	LGE	5	25 ACE	SP	CRE	ED,ID	TD		12/23/2036
2021 PO4121185160	LGE	4	45 ACE	SP	CRE	ED,ID	TD		12/24/2036
2021 PO4120585179	LGE	3	50 ACE	SP	CCA	ED,HH,ID	X	PX	12/25/2036
2021 PO4121485179	LGE	3	50 ACE	SP	A	ED,ID	BD		12/26/2036
2021 PO8670207720-A	KU	6	30 INP	SP	CRE	ID,IP	TD		12/27/2036
2021 PO4041485304	LGE	2	75 ACE	SP	CRE		V		12/28/2036
2021 PO4042685303	LGE	2	75 ACE	SP	CRE	ED	V		12/29/2036
2021 PO4028885013	F	3	45 BRO	SP	CCA		V		12/30/2036
2021 PO4029085017	LGE	4	35 BRO	SP	CCA		V		12/31/2036
2021 PO4030885012	F	4	40 BRO	SP	CCA		V		1/1/2037
2021 PO4031385012	F	4	35 BRO	SP	CRE		V		1/2/2037
2021 PO4027385014	F	4	40 BRO	SP	CRE		V		1/3/2037
2021 PO4122685185	LGE	7	25 ACE	SP	CRE	ED,ID,IP	TD		1/4/2037
2021 PO4154785210	LGE	3	50 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	1/5/2037
2021 PO4154385196	LGE	4	30 ACE	SP	P	ED,ID	BD		1/6/2037
2021 PO4155185206	LGE	4	30 ACE	SP	CCA		V		1/7/2037
2021 PO4155185225	LGE	3	45 ACE	SP	CCA		V		1/8/2037
2021 PO4155885223	LGE	1	55 ACE	SP	CCA		V		1/9/2037
2021 PO4152185167	LGE	4	30 ACE	SP	CRE	ED,ID	BD		1/10/2037
2021 PO4045385275	LGE	4	40 ACE	SP	P	ED	BD		1/11/2037
2021 PO4122185203	LGE	4	40 ACE	SP	CRE	ID	TD		1/12/2037
2021 PO8662807895	F	3	45 UNK	SP	A		V		1/13/2037
2021 PO8650007882	F	4	40 UNK	SP	CRE		V		1/14/2037
2021 PO8636707869	F	4	40 UNK	SP	CRE		V		1/15/2037
2021 PO8623007853	F	3	45 UNK	SP	A		V		1/16/2037
2021 PO8548807495	F	5	35 UNK	SP	CRE		V		1/17/2037
2021 PO4033384997	F	4	40 BRO	SP	CRE		V		1/18/2037
2021 PO4034384986	LGE	4	35 BRO	SP	A	ED,ID	TX	RR	1/19/2037
2021 PO4035484985	LGE	4	35 BRO	SP	A	ED,ID	TD		1/20/2037
2021 PO4046185301	LGE	4	30 ACE	SP	P	ED	TD		1/21/2037
2021 PO4157585266	LGE	3	50 ACE	SP	P	ED,ID	TD		1/22/2037
2021 PO4156485256	LGE	4	35 ACE	SP	P	ED,ID	TD		1/23/2037
2021 PO4156885243	LGE	3	50 ACE	SP	CRE	ED,ID	TD		1/24/2037
2021 PO3891738232	KU	4	40 BRN	SP	CRE	ID	TD		1/25/2037
2021 PO3881638172	KU	4	40 BRN	SP	CRE	ID,RB	BX	RP1	1/26/2037
2021 PO4043785297	LGE	4	35E ACE	SP	P	ED	TD		1/27/2037
2021 PO4045485291	LGE	4	35E ACE	DF	P	ED	BD		1/28/2037
2021 PO3881241208	KU	4	45 BRN	SP	CCA		V		1/29/2037
2021 PO4037485001	F	4	40 BRO	SP	CRE		V		1/30/2037
2021 PO4037185007	F	4	35 BRO	SP	CRE		V		1/31/2037
2021 PO4035985017	LGE	4	30 BRO	SP	CCA		V		2/1/2037
2021 PO4037784989	F	4	40 BRO	SP	CRE		V		2/2/2037
2021 PO4037784966	F	4	40 BRO	SP	CRE		V		2/3/2037
2021 PO4037884960	F	4	30 BRO	SP	CRE		V		2/4/2037
2021 PO4037184957	F	4	40 BRO	SP	CRE		V		2/5/2037
2021 PO4037084964	F	4	35 BRO	SP	CCA		V		2/6/2037
2021 PO4037184976	F	4	30 BRO	SP	CRE		V		2/7/2037
2021 PO4037784977	F	3	45 BRO	SP	CCA		V		2/8/2037
2021 PO4043785303	LGE	2	75 ACE	SP	CRE		V		2/9/2037
2021 PO4158185347	LGE	3	50 ACE	SP	CRE	ED,ID,IP	BD		2/10/2037
2021 PO5934011923	KU	4	40 ACW	SP	S		V		2/11/2037
2021 PO5946811974	KU	4	40 ACW	SP	S		V		2/12/2037
2021 PO5944012123	KU	4	40 ACW	SP	S		V		2/13/2037

2021 PO5941712234	KU	4	40 ACW	SP	S		V	2/14/2037
2021 PO5920212599	KU	4	40 ACW	SP	S		V	2/15/2037
2021 PO5932712624	KU	4	40 ACW	SP	S		V	2/16/2037
2021 PO5908612576	KU	4	40 ACW	SP	S		V	2/17/2037
2021 PO5944612644	KU	4	40 ACW	SP	S		V	2/18/2037
2021 PO5959512677	KU	4	40 ACW	SP	S		V	2/19/2037
2021 PO5938812378	KU	4	40 ACW	SP	S		V	2/20/2037
2021 PO8799807562	KU	5	35 OTH	SP	CCA	ID	BD	2/21/2037
2021 PO8797507562	KU	3	45 OTH	SP	CCA		V	2/22/2037
2021 PO4158185350	LGE	3	50 ACE	SP	P	ED,ID	BD	2/23/2037
2021 PO4139885119	LGE	4	35 ACE	SP	A	ED,ID	TD	2/24/2037
2021 PO4138585124	LGE	4	40 ACE	SP	A	ID	TD	2/25/2037
2021 PO4025785128	LGE	4	40 BRO	SP	CCA		V	2/26/2037
2021 PO4025785115	F	4	35 BRO	SP	CRE		V	2/27/2037
2021 PO4025685104	F	4	40 BRO	SP	CRE		V	2/28/2037
2021 PO4138785124	LGE	4	40 ACE	SP	A	ID	BD	3/1/2037
2021 PO4163185329	LGE	1	30 ACE	SP	A		V	3/2/2037
2021 PO4025585091	F	4	35 BRO	SP	CRE		V	3/3/2037
2021 PO4025485076	F	4	35 BRO	SP	CRE		V	3/4/2037
2021 PO4139485135	LGE	3	45 ACE	SP	CCA	ED,HH,ID	BD	3/5/2037
2021 PO8546463222	LGE	3	45 ACE	SP	CCA		V	3/6/2037
2021 PO8809707390	KU	6	30 OTH	SP	CRE	ID	BD	3/7/2037
2021 PO8784507562-A	KU	5	35 OTH	SP	CRE	ID	BD	3/8/2037
2021 PO8779507577	KU	6	30 OTH	SP	CRE	ED,HH,ID	BX	PX 3/9/2037
2021 PO8786907346	KU	3	50 OTH	SP	CCA		V	3/10/2037
2021 PO8775607336	KU	4	40 OTH	SP	CCA		V	3/11/2037
2021 PO8761807485	F	5	35 OTH	SP	CRE		V	3/12/2037
2021 PO8762607403	F	4	40 OTH	SP	CRE		V	3/13/2037
2021 PO8763307323	F	4	40 OTH	SP	CRE		V	3/14/2037
2021 PO3516027542	KU	4	40 BRN	SP	CCA		V	3/15/2037
2021 PO3530327586	KU	4	40 BRN	SP	CCA		V	3/16/2037
2021 PO4116885190	LGE	4	40 ACE	SP	A	ID	TD	3/17/2037
2021 PO4115085192	LGE	4	40 ACE	SP	CCA		V	3/18/2037
2021 PO4116685163	LGE	4	35 ACE	SP	CRE	ID	TD	3/19/2037
2021 PO4035885320	LGE	4	35 ACE	SP	P	ED	TD	3/20/2037
2021 PO4025385064	F	4	35 BRO	SP	CRE		V	3/21/2037
2021 PO4025285052	F	4	40 BRO	SP	CCA		V	3/22/2037
2021 PO4025185040	F	4	40 BRO	SP	CRE		V	3/23/2037
2021 PO4024585034	LGE	4	30 BRO	SP	CCA		V	3/24/2037
2021 PO4025085028	F	4	40 BRO	SP	CCA		V	3/25/2037
2021 PO4025085016	F	4	35 BRO	SP	CRE		V	3/26/2037
2021 PO4024485010	LGE	4	30 BRO	SP	CCA		V	3/27/2037
2021 PO3633859741	KU	4	40 UNK	SP	CRE	ID	BD	3/28/2037
2021 PO3658459801	KU	4	40 UNK	SP	CRE	ID	BD	3/29/2037
2021 PO3681959832	KU	5	35 BRO	SP	CCA		B	3/30/2037
2021 PO4159885435	LGE	4	30 ACE	SP	P	ED,ID	TD	3/31/2037
2021 PO4161585436	F	4	40 ACE	SP	CRE		V	4/1/2037
2021 PO5972511911	KU	4	40 ACW	SP	S		V	4/2/2037
2021 PO4028985313	LGE	2	75 ACE	SP	CRE		V	4/3/2037
2021 PO4030585312	LGE	2	35 ACE	SP	CRE		V	4/4/2037
2021 PO4031985310	LGE	2	75 ACE	SP	CRE	ED	V	4/5/2037
2021 PO4032585310	LGE	5	35E ACE	SP	CRE	ED	TD	4/6/2037
2021 PO8751407310	F	4	40 OTH	SP	CRE	ED	V	4/7/2037
2021 PO8741807231	KU	6	30 OTH	SP	CCA	ID	BD	4/8/2037

2021 PO8740907300	F	4	40 OTH	SP	CRE	HH,ID,RB	VX	RP2	4/9/2037
2021 PO8768507173	KU	6	30 OTH	SP	CCA	ID,SRS	TD		4/10/2037
2021 PO8734407351	KU	6	35 OTH	SP	CRE	ID,IP	BD		4/11/2037
2021 PO8723807259	F	5	35 OTH	SP	CRE		V		4/12/2037
2021 PO8718007279	F	4	40 OTH	SP	CRE		V		4/13/2037
2021 PO8702606983	F	4	40 OTH	SP	CRE		V		4/14/2037
2021 PO3603456824	KU	4	40 INP	SP	CRE	ED,ID	TX	RR	4/15/2037
2021 PO4160885300	LGE	1	25 ACE	SP	A		V		4/16/2037
2021 PO4160285284	LGE	4	40 ACE	SP	CRE	ED,ID	TD		4/17/2037
2021 PO8751964793	LGE	4	35 ACE	SP	CCA		V		4/18/2037
2021 PO4033785309	LGE	2	75 ACE	SP	CRE		V		4/19/2037
2021 PO4035485308	LGE	2	75 ACE	SP	CRE		V		4/20/2037
2021 PO4115585163	LGE	4	35 ACE	SP	A	ED,ID,IP	TD		4/21/2037
2021 PO4033085036	F	4	40 BRO	SP	CRE		V		4/22/2037
2021 PO4033285070	F	4	35 BRO	SP	CCA		V		4/23/2037
2021 PO4033485066	F	4	40 BRO	SP	CCA		V		4/24/2037
2021 PO4034485065	F	4	40 BRO	SP	CRE		V		4/25/2037
2021 PO4034185103	F	4	40 BRO	SP	CRE		V		4/26/2037
2021 PO4033885095	F	4	25 BRO	SP	A		V		4/27/2037
2021 PO4033085099	LGE	4	30 BRO	SP	A		V		4/28/2037
2021 PO4033085104	F	4	40 BRO	SP	A		V		4/29/2037
2021 PO4162385283	LGE	4	40 ACE	SP	P	ED,ID	TD		4/30/2037
2021 PO8777664809	LGE	4	35 ACE	SP	CCA		V		5/1/2037
2021 PO4118585189	LGE	4	40 ACE	SP	CCA		V		5/2/2037
2021 PO4033385129	F	4	40 BRO	SP	A		V		5/3/2037
2021 PO4034385128	F	4	40 BRO	SP	CRE		V		5/4/2037
2021 PO4034885128	LGE	4	35 BRO	SP	CRE	ED	TD		5/5/2037
2021 PO4035385162	F	4	40 BRO	SP	CRE		V		5/6/2037
2021 PO4034385159	F	4	35 BRO	SP	CCA		V		5/7/2037
2021 PO4034985376	F	4	45 ACE	SP	A		V		5/8/2037
2021 PO4035185363	F	3	45 ACE	SP	P		V		5/9/2037
2021 PO4156685198	LGE	4	35 ACE	SP	P	ED,ID	TD		5/10/2037
2021 PO4157085196	LGE	4	40 ACE	SP	P	ED,ID	BD		5/11/2037
2021 PO4035685331	F	4	40 ACE	SP	CRE		V		5/12/2037
2021 PO3561756987	KU	4	40 BRN	SP	CRE	ID	BD		5/13/2037
2021 PO3500058830	KU	4	40 BRN	SP	CRE	ID	TD		5/14/2037
2021 PO4035985314	F	4	45 ACE	SP	P		V		5/15/2037
2021 PO4035985320	F	4	40 ACE	SP	P		V		5/16/2037
2021 PO4034185163	F	1	40 BRO	SP	CCA		V		5/17/2037
2021 PV4033185164	F	4	40 BRO	SP	CRE		V		5/18/2037
2021 PO4029785166	F	4	35 BRO	SP	CRE		V		5/19/2037
2021 PO7433463306	LGE	4	35 BRO	SP	CCA		V		5/20/2037
2021 PO4029485162	LGE	4	40 BRO	SP	CRE		V		5/21/2037
2021 PO4030785165	F	1	40 BRO	SP	CCA		V		5/22/2037
2021 PO4032185150	F	4	40 BRO	SP	CCA		V		5/23/2037
2021 PO4032085139	F	4	40 BRO	SP	CRE		V		5/24/2037
2021 PO4032285164	F	4	40 BRO	SP	CRE		V		5/25/2037
2021 PO4031585180	LGE	4	35 BRO	SP	CRE	ED,ID	TD		5/26/2037
2021 PO4157285170	LGE	4	40 ACE	SP	P	ED,ID	TD		5/27/2037
2021 PO4157385152	LGE	4	40 ACE	SP	P	ED,ID	TD		5/28/2037
2021 PO4157285179	LGE	4	40 ACE	SP	P		V		5/29/2037
2021 PO4163885341	LGE	4	40 ACE	SP	CRE	ED,ID	TD		5/30/2037
2021 PO4120385188	LGE	4	40 ACE	SP	A	ED,ID	BD		5/31/2037
2021 PO4118885181	LGE	3	50 ACE	SP	A	ED,ID	BD		6/1/2037

2021	PO5733210448	KU	5	35 ACW	SP	CRE	ED,ID	TD	6/2/2037
2021	PO5689410230	KU	4	40 ACW	SP	CRE	ED,ID	TD	6/3/2037
2021	PO5658709866	KU	6	30 ACW	SP	CRE	ED,ID	TD	6/4/2037
2021	PO5643509852	KU	5	35 ACW	SP	S		V	6/5/2037
2021	PO6112510318	KU	3	50 ACW	SP	S		V	6/6/2037
2021	PO4028185132	F	4	40 BRO	SP	CRE		V	6/7/2037
2021	PO4029285131	F	4	40 BRO	SP	CCA		V	6/8/2037
2021	PO4030385131	F	3	45 BRO	SP	CCA		V	6/9/2037
2021	PO4030885137	LGE	4	30 BRO	SP	CRE	ED,ID	TD	6/10/2037
2021	PO8692907165	KU	5	35 OTH	SP	CCA		V	6/11/2037
2021	PO8700907138	F	4	40 OTH	SP	CRE		V	6/12/2037
2021	PO4032085130	F	4	40 BRO	SP	CRE		V	6/13/2037
2021	PO4031985117	F	3	45 BRO	SP	CCA		V	6/14/2037
2021	PO4027485107	F	4	40 BRO	SP	CRE		V	6/15/2037
2021	PO4028585107	F	4	40 BRO	SP	CRE		V	6/16/2037
2021	PO4029585106	F	4	40 BRO	SP	CCA		V	6/17/2037
2021	PO4031285102	LGE	4	30 BRO	SP	CRE	ED	TD	6/18/2037
2021	PO4031885105	F	3	45 BRO	SP	CCA		V	6/19/2037
2021	PO4032085100	F	4	30 BRO	SP	CRE		V	6/20/2037
2021	PO4031785090	F	4	40 BRO	SP	CRE		V	6/21/2037
2021	PO4031785077	F	3	45 BRO	SP	CCA		V	6/22/2037
2021	PO4164585349	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/23/2037
2021	PO4165285357	LGE	3	45 ACE	SP	CRE	ED,ID	BD	6/24/2037
2021	PO8697007452	F	4	40 OTH	SP	CRE		V	6/25/2037
2021	PO8687107243	F	4	40 OTH	SP	CRE		V	6/26/2037
2021	PO8698607321	F	4	40 OTH	SP	CRE		V	6/27/2037
2021	PO8748407197	KU	6	30 OTH	SP	CCA		V	6/28/2037
2021	PO8694807635	F	4	40 INP	SP	CRE		V	6/29/2037
2021	PO4118485177	LGE	4	35 ACE	SP	A	ED,HH,ID	TD	6/30/2037
2021	PO4036485308	LGE	4	40 ACE	SP	CRE	ED	TD	7/1/2037
2021	PO4117585168	LGE	4	40 ACE	SP	A	ED,ID,IP	TD	7/2/2037
2021	PO4118885166	LGE	4	35 ACE	SP	A	ID	BD	7/3/2037
2021	PO3482358710	KU	5	35 UNK	SP	CRE	ID	BD	7/4/2037
2021	PO4161685317	LGE	4	40 ACE	SP	CRE	ED,ID	TD	7/5/2037
2021	PO4162285324	LGE	3	45 ACE	SP	CCA		V	7/6/2037
2021	PO4161285306	LGE	4	30 ACE	SP	P	ED,ID	BD	7/7/2037
2021	PO4160985308	LGE	4	40 ACE	SP	P	ED,HH,ID,RB	BX PX	7/8/2037
2021	PO4160185300	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	7/9/2037
2021	PO3482727251	KU	4	45 BRN	SP	CRE	ID	TD	7/10/2037
2021	PO3476826886	KU	4	45 BRN	SP	CRE	ID	TD	7/11/2037
2021	PO3473326668	KU	4	45 BRN	SP	CRE	ID	X RP1	7/12/2037
2021	PO3844636298	KU	4	40 BRN	SP	CCA		V	7/13/2037
2021	PO3821636322	KU	3	45 BRN	SP	CCA		V	7/14/2037
2021	PO3816236523	KU	4	40 BRN	SP	CRE	ID	BD	7/15/2037
2021	PO4037185309	LGE	4	40 ACE	SP	CRE	ED	TD	7/16/2037
2021	PO4027685074	F	4	30 BRO	SP	CRE		V	7/17/2037
2021	PO8704306827	KU	4	40 OTH	SP	CRE		V	7/18/2037
2021	PO4030284904	LGE	4	35 BRO	SP	CRE	ED,ID	TD	7/19/2037
2021	PO4029884919	LGE	4	40 BRO	SP	CRE	ED,ID	TD	7/20/2037
2021	PO4030184929	LGE	4	40 BRO	SP	CRE	ED,ID	TD	7/21/2037
2021	PO4029584955	LGE	3	45 BRO	SP	CRE	ED,ID	TD	7/22/2037
2021	PO4028584966	LGE	4	40 BRO	SP	CRE	ED,ID	TD	7/23/2037
2021	PO8805207366	KU	4	40 OTH	SP	CRE	ID,IP	BD	7/24/2037
2021	PO8795507356	KU	3	45 OTH	SP	CCA		V	7/25/2037

2021 PO3487228854	KU	4	40 UNK	SP	CRE		B	7/26/2037
2021 PO8758907846	F	4	40 OTH	SP	CRE		V	7/27/2037
2021 PO8789707573	KU	6	30 OTH	SP	CCA		V	7/28/2037
2021 PO8759607762	F	4	40 OTH	SP	CRE		V	7/29/2037
2021 PO8760707628	F	4	40 OTH	SP	CRE		V	7/30/2037
2021 PO7442365169	LGE	4	35 ACE	SP	CCA		V	7/31/2037
2021 PO4042384825	F	3	45 ACE	SP	P		V	8/1/2037
2021 PO4028285300	LGE	4	35 ACE	SP	CCA		V	8/2/2037
2021 PO4042384829	F	3	45 ACE	SP	CRE		V	8/3/2037
2021 PO7584260041	F	3	45 ACE	SP	CCA		V	8/4/2037
2021 PO4043884830	F	3	45 ACE	SP	CRE		V	8/5/2037
2021 PO4045284832	F	3	45 ACE	SP	CRE		V	8/6/2037
2021 PO7613360111	LGE	3	45 ACE	SP	CCA		V	8/7/2037
2021 PO4046584833	F	3	45 ACE	SP	CCA		V	8/8/2037
2021 PO4076885045	LGE	3	50 ACE	SP	P	ED,ID	BD	8/9/2037
2021 PO7892762359	LGE	3	50 ACE	SP	P		V	8/10/2037
2021 PV4139085148	LGE	4	40 ACE	SP	CRE		V	8/11/2037
2021 PO4127585181	LGE	4	40 ACE	SP	CCA		V	8/12/2037
2021 PO4029984944	LGE	4	40 BRO	SP	CRE	ED	TD	8/13/2037
2021 PO4030884952	LGE	4	40 BRO	SP	CRE	ED,ID	TD	8/14/2037
2021 PO4032384941	LGE	3	45 BRO	SP	CRE	ED	BD	8/15/2037
2021 PO4032384951	LGE	4	45 BRO	SP	CCA		V	8/16/2037
2021 PO8802307919	KU	6	30 OTH	SP	CRE	ID	BD	8/17/2037
2021 PO8797707873	F	5	40 OTH	ST	P		V	8/18/2037
2021 PO4027085303	LGE	4	30 ACE	SP	P		BD	8/19/2037
2021 PO3515629034	KU	4	40 UNK	SP	CRE	ID	BD	8/20/2037
2021 PO4026685310	LGE	4	30 ACE	SP	CCA		V	8/21/2037
2021 PO4033784937	LGE	4	40 BRO	SP	A	ED,ID	TD	8/22/2037
2021 PO4034384924	LGE	4	35 BRO	SP	CRE	ID	TD	8/23/2037
2021 PO8780807907	KU	6	30 OTH	SP	CCA		V	8/24/2037
2021 PO8785207907	F	3	50 OTH	SP	A		V	8/25/2037
2021 PO8786307811	F	3	45 OTH	SP	P		V	8/26/2037
2021 PO8794107733	F	6	30 OTH	SP	A		V	8/27/2037
2021 PO2499224056	KU	6	30 BRN	SP	CCA		V	8/28/2037
2021 PO2478923882	KU	4	40 BRN	SP	CCA		V	8/29/2037
2021 PO2497025108	KU	5	35 BRN	SP	CCA		V	8/30/2037
2021 PO2489025108	KU	3	45 BRN	SP	CCA		V	8/31/2037
2021 PO8088260499	F	4	40 BRO	SP	CRE		V	9/1/2037
2021 PO8084160283	F	4	40 BRO	SP	CRE		V	9/2/2037
2021 PO6873117343	KU	4	40 ACW	SP	S		V	9/3/2037
2021 PO6836117476	KU	6	30 ACW	SP	S		V	9/4/2037
2021 PO6865817631	KU	4	40 ACW	SP	S		V	9/5/2037
2021 PO2313733813	KU	5	35 BRN	SP	CRE		V	9/6/2037
2021 PO2569119074	KU	5	35 BRN	SP	CCA		V	9/7/2037
2021 PO2578918936	KU	4	45 BRN	SP	CCA		V	9/8/2037
2021 PO2580419081	KU	3	45 BRN	SP	CCA		V	9/9/2037
2021 PO1838843158	KU	3	45 BRN	SP	CCA		V	9/10/2037
2021 PO2148437170	KU	6	30 BRN	SP	CRE		V	9/11/2037
2021 PO4195905547	KU	3	40 BRN	SP	CCA		V	9/12/2037
2021 PO4179405547	KU	3	40 BRN	SP	CCA		V	9/13/2037
2021 PO4035506907	KU	4	40 BRN	SP	CCA		V	9/14/2037
2021 PO8117963206	KU	3	45 BRO	SP	CCA		V	9/15/2037
2021 PO4042607196	KU	4	40 BRN	SP	CCA		V	9/16/2037
2021 PO4162986317	F	4	35 BRO	SP	CCA		V	9/17/2037

2021 PO4163286324	LGE	4	35 BRO	SP	A		V			9/18/2037
2021 PO4169386403	LGE	2	65 BRO	SP	CCA		V			9/19/2037
2021 PO4644008686	KU	6	30 BRN	SP	CCA		V			9/20/2037
2021 PO4176386553	F	4	40 BRO	SP	A		V			9/21/2037
2021 PO8858077422	LGE	4	35 BRO	SP	CCA		V			9/22/2037
2021 PO4175786547	F	4	40 BRO	SP	A		V			9/23/2037
2021 PO1715645204	KU	5	35 BRN	SP	CCA		V			9/24/2037
2021 PO4175386536	F	4	40 BRO	SP	A		V			9/25/2037
2021 PO2507629662	F	4	40 BRN	SP	P		V			9/26/2037
2021 PO2485329598	F	4	40 BRN	SP	P		V			9/27/2037
2021 PO2461129528	F	4	40 BRN	SP	CRE		V			9/28/2037
2021 PO2431729444	F	4	40 BRN	SP	CRE		V			9/29/2037
2021 PO2401529357	F	4	40 BRN	SP	P		V			9/30/2037
2021 PO8198861552	KU	6	30 BRO	SP	CCA		V			10/1/2037
2021 PO5256801454	KU	3	40 BRN	SP	CCA		V			10/2/2037
2021 PO4132186245	KU	4	40 BRN	SP	P	IP,RB	TX	RR		10/3/2037
2021 PO4134386235	LGE	4	30 BRN	SP	P	ID,RB	TX	RR		10/4/2037
2021 PO4133586242	LGE	3	55 BRN	SP	CRE	ED,ID,SRC	TX	RR		10/5/2037
2021 PO5215001244	KU	4	35 BRN	SP	CRE	ED,ID,IP,RB	TX	RR		10/6/2037
2021 PO4134586262	LGE	3	55 BRN	SP	CRE	EP,ID,IP,SRC	TX	RR		10/7/2037
2021 PO1075152990	KU	4	40 BRO	SP	CRE	ED,ID	TD			10/8/2037
2021 PO4667208983	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD			10/9/2037
2021 PO1012952499	KU	4	40 BRO	SP	CRE	ED,ID	TD			10/10/2037
2021 80644559885A	KU	6	30 BRO	SP	CRE	ED,ID	TD			10/11/2037
2021 PO4176886652	LGE	3	45 BRO	SP	A	ED,ID	TD			10/12/2037
2021 PO2341032512	KU	4	40 BRO	SP	CRE	ED,ID	TD			10/13/2037
2021 PO4139086314	LGE	3	45 BRN	SP	P	ID	TD			10/14/2037
2021 PO8197758612	KU	4	40 UNK	SP	CRE	ID	TD			10/15/2037
2021 PO7038621150	KU	2	60 ACW	SP	CRE	ED,ID,IP	TD			10/16/2037
2021 PO7513416112	KU	4	40 ACW	SP	CRE	ED,ID	TD			10/17/2037
2021 PO7505115717	KU	4	40 ACW	SP	CRE	ED,ID	TD			10/18/2037
2021 PO7520515870	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			10/19/2037
2021 PO1717743443	KU	4	40 BRO	SP	CRE	ED,ID	TD			10/20/2037
2021 PO1704343396	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD			10/21/2037
2021 PO4619907370	KU	4	45 XXX	SP	CRE	ED,ID	TD			10/22/2037
2021 PO1704343047	KU	5	35 BRO	SP	CRE	ED,ID	TD			10/23/2037
2021 PO7584858563	KU	4	40 UNK	SP	CRE	ID,SRS	TD			10/24/2037
2021 PO7590858704	KU	4	40 UNK	SP	CRE	ID,IP	TD			10/25/2037
2021 PO4169985428	LGE	4	40 BRN	SP	P	ID,SRS	TD			10/26/2037
2021 PO8156858734	KU	4	45 UNK	SP	CRE	ID	TD			10/27/2037
2021 PO0529150641	KU	4	40 BRN	SP	CRE	ID	TD			10/28/2037
2021 PO2446824708	KU	4	40 BRN	SP	CRE	ID	TD			10/29/2037
2021 PO7002220713	KU	2	70 ACW	SP	S	ED,ID	TD			10/30/2037
2021 PO4662708691	KU	6	30 XXX	SP	CRE	ED,ID	TD			10/31/2037
2021 PO7033320769	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			11/1/2037
2021 PO8176658618	KU	6	30 UNK	SP	CRE	ID,IP	TD			11/2/2037
2021 PO8192658402	KU	6	30 UNK	SP	CRE	ID,IP	TD			11/3/2037
2021 PO2325832516	KU	4	40 BRO	SP	CRE	ED,ID	TD			11/4/2037
2021 PO4135086270	LGE	4	40 BRN	SP	CRE	ID,IP,SRS	TD			11/5/2037
2021 PO4323505454	KU	4	40 BRN	SP	CRE	ED,ID	TD			11/6/2037
2021 PO4169986530	LGE	4	40 BRO	SP	CRE	ED,ID	TD			11/7/2037
2021 PO7025221217	KU	3	45 ACW	SP	CRE	ED,ID,IP	TD			11/8/2037
2021 PO7863261822	KU	4	40 BRO	SP	CRE	ED,ID	TD			11/9/2037
2021 PO7888761670	KU	4	45 BRO	SP	CRE	ED,ID	TD			11/10/2037

2021 PO7605459050	KU	5	35 UNK	SP	CRE	ID	TD	11/11/2037
2021 PO4181585428	LGE	1	55 BRN	SP	CRE	ID,SRS	TD	11/12/2037
2021 PO5172401306	KU	6	35 BRN	SP	CRE	ED	TD	11/13/2037
2021 PO2501024678	KU	5	35 BRN	SP	CRE	ED,ID	TD	11/14/2037
2021 PO2510124629	KU	6	30 BRN	SP	CRE	ID	TD	11/15/2037
2021 PO2467724727	KU	4	40 BRN	SP	CRE	ID	TD	11/16/2037
2021 PO2490124699	KU	5	35 BRN	SP	CRE	ID	TD	11/17/2037
2021 PO4178685427	LGE	4	40 BRN	SP	CRE	ID,IP,SRS	TD	11/18/2037
2021 PO7121121414	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/19/2037
2021 PO7129721680	KU	4	45 ACW	SP	CRE	ED,ID	TD	11/20/2037
2021 PO7139921983	KU	4	45 ACW	SP	CRE	ED,ID	TD	11/21/2037
2021 PO7000020271	KU	5	35 ACW	SP	CRE	ED,ID	TD	11/22/2037
2021 PO7522516724	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/23/2037
2021 PO7544316787	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/24/2037
2021 PO7530216919	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/25/2037
2021 PO4185385416	LGE	4	40 BRN	SP	P	ID,SRS	TD	11/26/2037
2021 PO7690558197	KU	6	30 UNK	SP	CRE	ID,IP	TD	11/27/2037
2021 PO2318532770	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/28/2037
2021 PO2340132867	KU	6	30 BRO	SP	CRE	ED,ID	TD	11/29/2037
2021 PO4610909141	KU	6	30 BRN	SP	CCA	ED	TD	11/30/2037
2021 PO2353432908	KU	4	40 BRO	SP	CRE	ED,EP,ID,IP	TD	12/1/2037
2021 PO7533116040	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/2/2037
2021 PO7542116252	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/3/2037
2021 PO7546116490	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/4/2037
2021 PO4590008900	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/5/2037
2021 PO4133086233	LGE	4	40 BRN	SP	CRE	ID,SRS	TD	12/6/2037
2021 PO4132686225	LGE	3	55 BRN	SP	CRE	ID,SRS	TD	12/7/2037
2021 PO4656208983	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/8/2037
2021 PO4174986560	LGE	4	35 BRO	SP	A	ED,ID	TD	12/9/2037
2021 PO2478425018	KU	4	40 BRN	SP	CRE	ID	TD	12/10/2037
2021 PO4183685570	LGE	3	55 BRN	SP	CRE	ID,SRS	TD	12/11/2037
2021 PO4131786208	LGE	3	55 BRN	SP	CCA	ID,SRS	TD	12/12/2037
2021 PO4173586521	LGE	3	50 BRO	SP	A	ED,ID	TD	12/13/2037
2021 PO4173486518	LGE	2	60 BRO	SP	A	ED,ID	TD	12/14/2037
2021 PO4172986523	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/15/2037
2021 PO8162858179	KU	4	40 UNK	SP	CRE	ID,IP	TD	12/16/2037
2021 PO8165358365	KU	4	40 UNK	SP	CRE	ID	TD	12/17/2037
2021 PO8148858474	KU	4	40 UNK	SP	CRE	ID	TD	12/18/2037
2021 PO8157161297	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/19/2037
2021 PO8160961591	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/20/2037
2021 PO4668408858	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/21/2037
2021 PO1707145357	KU	4	40 BRN	SP	CRE	ID	TD	12/22/2037
2021 PO4698308690	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/23/2037
2021 PO4679208743	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/24/2037
2021 PO4263405442	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	12/25/2037
2021 PO4040207087	KU	7	30 BRN	SP	CRE	ED,ID	TD	12/26/2037
2021 PO8269258560	KU	4	40 UNK	SP	CRE	ID,IP	TD	12/27/2037
2021 PO4173786536	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	12/28/2037
2021 PO4139386376	LGE	2	60 BRN	SP	CRE	ID	TD	12/29/2037
2021 PO5176600893	KU	3	40 BRN	SP	CRE	ED,ID	TD	12/30/2037
2021 PO5156600735	KU	3	40 BRN	SP	CRE	ED,ID	TD	12/31/2037
2021 PO4652808857	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/1/2038
2021 PO4645208858	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/2/2038
2021 PO4644808983	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	1/3/2038

2021 PO8111158879	KU	4	45 UNK	SP	CRE	ID	TD			1/4/2038
2021 PO7626558757	KU	6	30 UNK	SP	CRE	ID,IP	TD			1/5/2038
2021 PO4622908690	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD			1/6/2038
2021 PO7668358489	KU	6	30 UNK	SP	CRE	ID	TD			1/7/2038
2021 PO5175601034	KU	3	40 BRN	SP	CRE	ED,ID	TD			1/8/2038
2021 PO5159901235	KU	4	40 BRN	SP	CRE	ED,ID	TD			1/9/2038
2021 PO7670458440	KU	6	30 UNK	SP	CRE	ID,IP	TD			1/10/2038
2021 PO4617609651	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX		1/11/2038
2021 PO4595709125	KU	4	40 XXX	SP	CRE	HH,ID,RB	BX	RP1		1/12/2038
2021 PO4589309662	F	4	40 XXX	SP	CRE	HH,ID	BX	RP2		1/13/2038
2021 PO1043552963	KU	5	35 BRO	SP	CRE	ED,EP,ID	BX	RP3		1/14/2038
2021 PO1046552780	KU	4	40 BRO	SP	CRE	ED,ID	BD			1/15/2038
2021 PO1050652642	KU	4	40 BRO	SP	CRE	ED,ID	BD			1/16/2038
2021 PO4141886344	LGE	4	40 BRN	SP	CRE		BD			1/17/2038
2021 PO0815956967	KU	4	40 BRN	SP	CRE	ID	BD			1/18/2038
2021 PO7596858853	KU	4	45 UNK	SP	CRE	ID	BD			1/19/2038
2021 PO1704143222	KU	6	30 BRO	SP	CRE	ED,ID	BD			1/20/2038
2021 PO4631207378	KU	4	45 XXX	SP	CRE	ID	BD			1/21/2038
2021 PO4171985426	LGE	2	55 BRN	SP	CRE	ID	BD			1/22/2038
2021 PO4174685426	LGE	2	55 BRN	SP	P	ID	BD			1/23/2038
2021 PO4142085344	LGE	3	45 BRN	SP	CRE	ID	BD			1/24/2038
2021 PO4173686531	LGE	4	40 BRO	SP	CRE	ID	BD			1/25/2038
2021 PO7115221217	KU	4	45 ACW	SP	CRE	ED,ID	BD			1/26/2038
2021 PO4660108857	KU	4	40 XXX	SP	CRE	ID	BD			1/27/2038
2021 PO2322332283	KU	4	40 BRO	SP	CRE	ED,ID	BD			1/28/2038
2021 PO7704057943	KU	4	40 UNK	SP	CRE	ID	BD			1/29/2038
2021 PO7677458063	KU	4	40 UNK	SP	CRE	ID	BD			1/30/2038
2021 PO2378733156	KU	4	45 BRO	SP	CRE	ED,ID	BD			1/31/2038
2021 PO2369733334	KU	4	40 BRO	SP	CRE	ED,ID	BD			2/1/2038
2021 PO2384332718	KU	4	40 BRO	SP	CRE	ED,ID	BD			2/2/2038
2021 PO7660958216	KU	4	40 UNK	SP	CRE	ID	BD			2/3/2038
2021 PO6959516259	KU	4	40 ACW	SP	CRE	ED,ID	BD			2/4/2038
2021 PO4184985454	LGE	4	40 BRN	SP	P	ID	BD			2/5/2038
2021 PO2339433163	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD			2/6/2038
2021 PO2311733006	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD			2/7/2038
2021 PO4171586526	LGE	4	40 BRO	SP	CRE	ID	BD			2/8/2038
2021 PO8148958588	KU	6	30 UNK	SP	CRE	ID	BD			2/9/2038
2021 PO7647458339	KU	4	40 UNK	SP	CRE	ID,IP	BD			2/10/2038
2021 PO8863276917	LGE	4	35 BRO	SP	A	ID	BD			2/11/2038
2021 PO7638458515	KU	4	45 UNK	SP	CRE	ID	BD			2/12/2038
2021 PO7638458515-A	KU	4	40 UNK	SP	CRE	ID	BD			2/13/2038
2021 PO7619958635	KU	4	40 UNK	SP	CRE	ID,IP	BD			2/14/2038
2021 PO4174086546	LGE	4	35 BRO	SP	A	ID	BD			2/15/2038
2021 PO4175086544	LGE	4	30 BRO	SP	A	ID,IP	BD			2/16/2038
2021 PO4656708859	KU	4	40 XXX	SP	CRE	ID	BD			2/17/2038
2021 PO4174186518	LGE	3	50 BRO	SP	A	ED,ID	BD			2/18/2038
2021 PO4141986361	LGE	4	40 BRN	SP	P	ID	BD			2/19/2038
2021 PO4140486362	LGE	4	40 BRN	SP	CRE	ID	BD			2/20/2038
2021 PO4318805764	KU	3	45 BRN	SP	CRE		B			2/21/2038
2021 PO4196185159	LGE	3	50 BRN	SP	CRE		B			2/22/2038
2021 PV4194485178	LGE	4	35 BRN	SP	P		B			2/23/2038
2021 PO3431899057	KU	3	40 BRN	SP	CRE	ED,ID	X	RP1		2/24/2038
2021 PO4577807545	KU	4	40 XXX	SP	CRE	ED,HH,ID	X	RP2		2/25/2038
2021 PO0938947645	KU	4	40 BRN	SP	CRE	ED,EP,ID,MD	VX	PX		2/26/2038



2021 PO4203086031	F	4	35 BRN	SP	P		V	2/27/2038	
2021 PO4220285946	LGE	1	70E BRN	SP	CRE		V	2/28/2038	
2021 PO4209685942	F	7	35E BRN	SP	P		V	3/1/2038	
2021 PO4203085946	LGE	1	65 BRN	SP	CRE		V	3/2/2038	
2021 PO4203185948	LGE	4	30 BRN	SP	P		V	3/3/2038	
2021 PO4203285980	LGE	1	75 BRN	SP	CCA		V	3/4/2038	
2021 PO4203385999	LGE	2	55E BRN	SP	A		V	3/5/2038	
2021 PO4203386018	LGE	2	70 BRN	SP	CRE		V	3/6/2038	
2021 PO4201686034	LGE	2	60 BRN	SP	CRE		V	3/7/2038	
2021 PO4191086034	LGE	1	75 BRN	SP	CRE		V	3/8/2038	
2021 PO4187386030	LGE	4	40 BRN	SP	CRE		V	3/9/2038	
2021 PO4186986031	LGE	4	40 BRN	SP	CCA		V	3/10/2038	
2021 PO4166786014	LGE	4	35 BRN	SP	CRE		V	3/11/2038	
2021 PO4183985625	LGE	4	30 BRN	ST	CCA		V	3/12/2038	
2021 PO4184485683	LGE	3	45 BRN	SP	P		V	3/13/2038	
2021 PO4189186034	LGE	1	85 BRN	SP	CRE		V	3/14/2038	
2021 PO4564607928	F	3	45 BRN	SP	CCA		V	3/15/2038	
2021 PO4560107943	F	4	40 BRN	SP	CCA		V	3/16/2038	
2021 PO7527059835	KU	4	45 UNK	SP	CCA		V	3/17/2038	
2021 PO4584507739	F	4	40 XXX	SP	CCA		V	3/18/2038	
2021 PO4564307635	KU	6	30 BRN	SP	CRE		V	3/19/2038	
2021 PO4532407705	KU	4	45 BRN	SP	CCA		V	3/20/2038	
2021 PO4184785690	LGE	4	30 BRN	ST	CCA		V	3/21/2038	
2021 PO4601008012	KU	3	45 BRN	SP	CCA		V	3/22/2038	
2021 PO7516958988	KU	6	30 UNK	SP	CCA		V	3/23/2038	
2021 PO4139086051	LGE	1	80 BRN	ST	P		V	3/24/2038	
2021 PO4142786056	LGE	2	75E BRN	SP	CRE		V	3/25/2038	
2021 PO4134485965	F	1	55 BRN	SP	CCA		V	3/26/2038	
2021 PO4174986520	LGE	1	80 BRN	ST	S		V	3/27/2038	
2021 PO4200686342	F	3	50 BRN	SP	CRE		V	3/28/2038	
2021 PO4183786043	F	4	40 BRN	SP	A		V	3/29/2038	
2021 PO4184186042	F	4	35 BRN	SP	CRE		V	3/30/2038	
2021 PO4184486042	F	3	50 BRN	SP	S		V	3/31/2038	
2021 PO4514007877	F	4	40 XXX	SP	P		V	4/1/2038	
2021 PO4509307755	F	4	40 XXX	SP	CRE		V	4/2/2038	
2021 PO4186685917	LGE	4	30 BRN	SP	P		V	4/3/2038	
2021 PO7575459464	KU	4	45 UNK	SP	CCA		V	4/4/2038	
2021 PO7591859394	KU	3	45 UNK	SP	CCA		V	4/5/2038	
2021 PO4588807860	F	4	40 BRN	SP	CCA		V	4/6/2038	
2021 PO4579307591	F	3	45 BRN	SP	CCA		V	4/7/2038	
2021 PO3442597869	KU	3	40 BRN	SP	CCA		V	4/8/2038	
2021 PO4632407823	F	4	40 XXX	SP	CRE		V	4/9/2038	
2021 PO4601207938	KU	3	45 BRN	SP	CCA		V	4/10/2038	
2021 PO4601407917	KU	3	45 BRN	SP	CCA		V	4/11/2038	
2021 PO4186886005	LGE	3	50 BRN	SP	P	HH,ID,SRS	TX	RR	4/12/2038
2021 PO4223785947	LGE	4	40 BRN	SP	P	HH,RB	TX	RR	4/13/2038
2021 PO0921047753	KU	3	45 BRN	SP	CRE	ED,HH,ID,MD	TX	RR	4/14/2038
2021 PO1353744106	KU	4	40 BRN	SP	CRE	ED,EP,HH,ID	TX	RR	4/15/2038
2021 PO4222585946	LGE	4	40 BRN	SP	P	ID,SRS	TD		4/16/2038
2021 PO3416798241	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/17/2038
2021 PO3439497471	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/18/2038
2021 PO7583558994	KU	6	30 UNK	SP	CRE	ID,IP	TD		4/19/2038
2021 PO7583459102	KU	5	35 UNK	SP	CRE	ID,IP	TD		4/20/2038
2021 PO7588659073	KU	5	35 UNK	SP	A	ID	TD		4/21/2038

2021 PO4183885656	LGE	4	40 BRN	SP	P	ID,SRS	TD		4/22/2038
2021 PO4183685643	LGE	4	40 BRN	SP	P	ID_SRC	TD		4/23/2038
2021 PO3435797007	KU	7	35 BRN	SP	CRE	ED,ID	TD		4/24/2038
2021 PO7399915348	KU	4	40 ACW	SP	CRE	ED,ID	TD		4/25/2038
2021 PO7413615258	KU	5	35 ACW	SP	CRE	ED,ID	TD		4/26/2038
2021 PO3431898760	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/27/2038
2021 PO3394298152	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/28/2038
2021 PO4578208100	KU	5	35 BRN	SP	CCA	ED,MD	TD		4/29/2038
2021 PO4186485934	LGE	3	45 BRN	SP	P	ID,IP,SRS	TD		4/30/2038
2021 PO4186885927	LGE	6	25 BRN	SP	P	ID	TD		5/1/2038
2021 PO7591159641	KU	6	30 UNK	SP	CRE	ID,IP	TD		5/2/2038
2021 PO4186585888	LGE	4	30 BRN	SP	P	ID,SRS	TD		5/3/2038
2021 PO4186585876	LGE	4	30 BRN	SP	P	ID_SRC	TD		5/4/2038
2021 PO3448598840	KU	4	35 BRN	SP	CRE	ED,ID	TD		5/5/2038
2021 PO3450999057	KU	6	35 BRN	SP	CRE	ED,ID	TD		5/6/2038
2021 PO7354015667	KU	5	35 ACW	SP	CRE	ED,ID	TD		5/7/2038
2021 PO8137484939	F	5	35 ACE	LAM	CRE		V		5/8/2038
2021 PO8146284736	F	6	30 ACE	SP	CCA		V		5/9/2038
2021 PO8141284715	F	4	40 ACE	SP	CRE		V		5/10/2038
2021 PO8154584522	F	6	30 ACE	SP	CRE		V		5/11/2038
2021 PO8149284507	F	4	40 ACE	SP	CRE		V		5/12/2038
2021 PO8156984350	F	5	35 ACE	SP	CCA		V		5/13/2038
2021 PO8151384343	F	4	40 ACE	SP	CRE		V		5/14/2038
2021 PO8265772633	LGE	4	40 ACE	SP	CCA		V		5/15/2038
2021 PO4113486109	LGE	4	40 ACE	SP	CCA		V		5/16/2038
2021 PO4183386557	LGE	4	40 BRO	SP	A	ED,ID	TD		5/17/2038
2021 PO4182086558	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	5/18/2038
2021 PO9378974748	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/19/2038
2021 PO4203886079	LGE	4	30 BRN	SP	CCA		V		5/20/2038
2021 PO4145285575	KU	4	40 BRN	SP	CRE	ID	TD		5/21/2038
2021 PO4145785577	LGE	4	35 BRN	SP	CRE	ID	TD		5/22/2038
2021 PO4145785573	F	4	40 BRN	SP	CRE		V		5/23/2038
2021 PO1210452807	KU	5	35 BRO	SP	CCA		V		5/24/2038
2021 PO4119886074	LGE	2	60 ACE	SP	CRE		V		5/25/2038
2021 PO4172586436	F	5	35 BRO	SP	CCA		V		5/26/2038
2021 PO1939543738	KU	4	45 BRO	SP	CRE	ED,EP	TD		5/27/2038
2021 PO5246103282	KU	4	40 BRN	SP	CRE	ED,ID	TD		5/28/2038
2021 PO1951943667	KU	4	40 BRO	SP	CRE	ED,ID,IP,MD	TD		5/29/2038
2021 PO1963343812	KU	6	30 BRO	SP	CRE	ED,ID	TD		5/30/2038
2021 PO1017854918	F	4	40 BRO	SP	CRE		V		5/31/2038
2021 PO5231903274	KU	3	45 BRN	SP	CCA		V		6/1/2038
2021 PO5241803196	KU	7	30 BRN	SP	CRE	ED,ID	TD		6/2/2038
2021 PO5215103440	KU	4	40 BRN	SP	CCA		V		6/3/2038
2021 PO5233603431	KU	3	40 BRN	SP	CCA		V		6/4/2038
2021 KU	KU	4	40 BRO	SP	CCA		V		6/5/2038
2021 PO1964544203	KU	4	40 BRN	SP	CRE	ED,EP,ID	BX	RR	6/6/2038
2021 PO5233703461	KU	4	40 BRN	SP	CCA		V		6/7/2038
2021 PO5197203452	KU	3	40 BRN	SP	CCA		V		6/8/2038
2021 PO5253903432	KU	7	30 BRN	SP	CRE	ED,ID	TD		6/9/2038
2021 PO1943144003	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD	TD		6/10/2038
2021 PO1269551465	KU	4	40 BRN	SP	CRE	ED,EP,ID	TD		6/11/2038
2021 PO1290551206	KU	4	40 BRN	SP	CRE	ED,EP,ID	TD		6/12/2038
2021 PO0939656644	KU	5	35 BRO	SP	CRE	ED,EP,ID	TD		6/13/2038
2021 PO0985052322	F	4	40 BRO	SP	CRE		V		6/14/2038

2021 PO1926344204	KU	4	40 BRN	SP	CCA	ED,SRS	TD	6/15/2038
2021 PO1942944362	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD	6/16/2038
2021 PO5256603267	KU	3	40 BRN	SP	CRE	ED,ID	TD	6/17/2038
2021 PO4112186129	LGE	2	60 ACE	SP	CRE	ED,ID	V	6/18/2038
2021 PO4111186139	LGE	2	60 ACE	SP	CRE	ED,ID	V	6/19/2038
2021 PO4118686082	LGE	2	60 ACE	SP	CRE		V	6/20/2038
2021 PO5277203285	KU	7	30 BRN	SP	CRE	ED,ID	TD	6/21/2038
2021 PO5272903240	KU	3	40 BRN	SP	CRE	ED,ID	TD	6/22/2038
2021 PO1906944459	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD	6/23/2038
2021 PO1918344550	KU	6	30 BRN	SP	CRE	ED,ID	BD	6/24/2038
2021 PO4124186155	F	4	40 ACE	SP	CRE		V	6/25/2038
2021 PO4123486159	F	4	40 ACE	SP	CRE		V	6/26/2038
2021 PO4122286160	F	4	40 ACE	SP	CRE		V	6/27/2038
2021 PO4120686162	F	4	40 ACE	SP	P		V	6/28/2038
2021 PO4119086163	F	4	40 ACE	SP	P		V	6/29/2038
2021 PO4117586165	F	4	40 ACE	SP	P		V	6/30/2038
2021 PO4116586166	F	4	40 ACE	SP	P	ED,ID,IP	V	7/1/2038
2021 PO4115186167	F	4	40 ACE	SP	P		V	7/2/2038
2021 PO4113786168	F	4	40 ACE	SP	P		V	7/3/2038
2021 PO4110986157	F	4	35 ACE	SP	CCA		V	7/4/2038
2021 PO4110086148	LGE	2	60 ACE	SP	CRE		V	7/5/2038
2021 PO4121185933	LGE	4	35 ACE	SP	CCA		V	7/6/2038
2021 PO4112386176	F	6	30 ACE	SP	CRE		V	7/7/2038
2021 PO1781043645	F	4	40 BRO	SP	CRE		V	7/8/2038
2021 PO1892744462	KU	6	30 BRO	SP	CRE	ED,ID	BD	7/9/2038
2021 PO1884244558	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/10/2038
2021 PO1897844585	KU	6	30 BRO	SP	CRE	ED,EP,HH	BX	7/11/2038
2021 PO1893044628	KU	4	40 BRO	SP	CRE	ED,ID,MD	TD	7/12/2038
2021 PO1748744530	F	4	40 BRO	SP	CRE		V	7/13/2038
2021 PO4221907746	KU	3	50 BRN	SP	CCA		V	7/14/2038
2021 PO4203307853	KU	4	45 BRN	SP	CCA		V	7/15/2038
2021 PO4212107885	KU	2	55 BRN	SP	CCA		V	7/16/2038
2021 PO4213307859	KU	3	50 BRN	SP	CCA		V	7/17/2038
2021 PO5287303167	KU	7	30 BRN	SP	CRE	ED,ID	TD	7/18/2038
2021 PO1891644761	KU	6	30 BRO	SP	CRE	EP,HH,MD	BX	7/19/2038
2021 PO1882744861	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/20/2038
2021 PO5287503214	KU	3	40 BRN	SP	CRE	ED,ID	TD	7/21/2038
2021 PO1868744754	KU	4	40 BRO	SP	CRE	ED,EP,ID	BD	7/22/2038
2021 PO1842844563	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	7/23/2038
2021 PO4172786440	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/24/2038
2021 PO4172786440-A	KU	4	35 BRO	SP	A	ED,ID	TD	7/25/2038
2021 PO1836144583	KU	5	35 BRO	SP	CRE	ED,ID,SR	TD	7/26/2038
2021 PO1826044445	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	7/27/2038
2021 PO4111486172	F	5	30 ACE	SP	CRE		V	7/28/2038
2021 PO4112386170	F	4	40 ACE	SP	P		V	7/29/2038
2021 PO4111886167	F	4	35 ACE	SP	P		V	7/30/2038
2021 PO1816444434	KU	5	35 BRO	SP	CRE	ED,EP,ID,IP	TD	7/31/2038
2021 PO4111586163	F	4	35 ACE	SP	CRE		V	8/1/2038
2021 PO4111386154	F	4	40 ACE	SP	P		V	8/2/2038
2021 PO4112286146	F	4	40 ACE	SP	CRE		V	8/3/2038
2021 PO4113186138	F	4	40 ACE	SP	P		V	8/4/2038
2021 PO5296103199	KU	3	40 BRN	SP	CRE	ED,ID	TD	8/5/2038
2021 PO4114086130	F	4	40 ACE	SP	P		V	8/6/2038
2021 PO4115386121	F	4	40 ACE	SP	P		V	8/7/2038

2021 PO4117186117	F	4	35 ACE	SP	P		V	8/8/2038	
2021 PO4118586110	F	4	35 ACE	SP	CCA		V	8/9/2038	
2021 PO4120186093	F	4	40 ACE	SP	CRE		V	8/10/2038	
2021 PO4121686091	F	4	35 ACE	SP	CCA		V	8/11/2038	
2021 PO4121286087	F	4	40 ACE	SP	CRE		V	8/12/2038	
2021 PO4122686086	F	5	35 ACE	SP	CRE		V	8/13/2038	
2021 PO4122386081	F	4	40 ACE	SP	CRE		V	8/14/2038	
2021 PO1805144717	KU	4	40 BRO	SP	CRE	ED,ID,IP,MD	TD	8/15/2038	
2021 PO1851344295	KU	4	45 BRO	SP	CRE	ED,ID,MD	TD	8/16/2038	
2021 PO4173986421	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	8/17/2038	
2021 PO4173886423	LGE	3	45 BRO	SP	CCA		V	8/18/2038	
2021 PO4175186430	LGE	4	35 BRO	SP	CCA		V	8/19/2038	
2021 PO5293803090	KU	6	35 BRN	SP	CCA	ED	TD	8/20/2038	
2021 PO4109186156	LGE	2	60 ACE	SP	CRE		V	8/21/2038	
2021 PO4174986429	LGE	4	40 BRO	SP	CRE	ID,IP	BD	8/22/2038	
2021 PO4175286434	LGE	4	35 BRO	SP	CCA		V	8/23/2038	
2021 PO1168852692	KU	5	45 BRN	SP	CRE	ED,ID,IP	TD	8/24/2038	
2021 PO4121885808	LGE	2	75 BRN	SP	CRE		V	8/25/2038	
2021 PO4122585821	LGE	2	75 BRN	SP	CRE		V	8/26/2038	
2021 PO4123085786	LGE	1	40 BRN	SP	CRE		V	8/27/2038	
2021 PO4123485810	LGE	4	35 BRN	SP	CCA		V	8/28/2038	
2021 PO4124185796	LGE	4	35 BRN	SP	CCA		V	8/29/2038	
2021 PO4124185847	LGE	1	75 BRN	ST	P		V	8/30/2038	
2021 PO4124785791	LGE	1	50 BRN	SP	CCA		V	8/31/2038	
2021 PO4124885859	LGE	1	75 BRN	ST	P		V	9/1/2038	
2021 PO4126485886	LGE	2	75 BRN	SP	CRE		V	9/2/2038	
2021 PO4127285898	LGE	2	75 BRN	SP	CRE		V	9/3/2038	
2021 PO4127485790	LGE	4	40 BRN	SP	CCA		V	9/4/2038	
2021 PO4128085912	LGE	2	75 BRN	SP	CRE		V	9/5/2038	
2021 PO4128785924	LGE	2	75 BRN	SP	CRE		V	9/6/2038	
2021 PO4130385950	LGE	2	75 BRN	ST	P		V	9/7/2038	
2021 PO4130485782	LGE	4	30 BRN	SP	CCA		V	9/8/2038	
2021 PO4131185964	LGE	2	75 BRN	ST	P		V	9/9/2038	
2021 PO4132085977	LGE	1	80 BRN	ST	P		V	9/10/2038	
2021 PO4132685781	LGE	4	35 BRN	SP	CCA		V	9/11/2038	
2021 PO4134185971	LGE	2	80 BRN	SP	P		V	9/12/2038	
2021 PO4141685169	LGE	3	45 BRN	SP	CRE		V	9/13/2038	
2021 PO4142985179	LGE	3	50 BRN	SP	CCA		V	9/14/2038	
2021 PO4202586210	KU	6	30 BRO	SP	CRE		V	9/15/2038	
2021 PO4202586215	F	4	30 BRO	SP	A		V	9/16/2038	
2021 PO4202586220	F	4	35 BRO	SP	CCA		V	9/17/2038	
2021 PO4202986213	LGE	3	45 BRO	SP	CCA		V	9/18/2038	
2021 PO8401369420	LGE	3	45 BRN	SP	CCA		V	9/19/2038	
2021 PO8427669266	LGE	4	35 BRN	SP	CCA		V	9/20/2038	
2021 PO8430169594	LGE	4	35 BRN	SP	CCA		V	9/21/2038	
2021 PO8431369433	LGE	4	35 BRN	SP	CCA		V	9/22/2038	
2021 PO8446469677	KU	4	35 BRN	SP	CCA		V	9/23/2038	
2021 PO4143085127	LGE	4	35 BRN	SP	P	ED,ID,RB	TX	RR	9/24/2038
2021 PO4143185149	LGE	3	55 BRN	SP	P	ED,ID,RB	TX	RR	9/25/2038
2021 PO4140585162	KU	4	35 BRN	SP	P	ID	TD		9/26/2038
2021 PO4141185170	LGE	4	35 BRN	SP	P	ID	TD		9/27/2038
2021 PO4143085136	LGE	4	35 BRN	SP	CCA	ID,IP	TD		9/28/2038
2021 PO4143085161	LGE	3	45 BRN	SP	P	ID	TD		9/29/2038
2021 PO4143385121	LGE	3	50 BRN	SP	P	ID	TD		9/30/2038

2021 PO4144085149	LGE	4	30 BRN	SP	P	ID, SRC	TD	10/1/2038	
2021 PO4193286244	LGE	4	35 BRO	SP	A	ED, ID, IP	TD	10/2/2038	
2021 PO4194386255	LGE	4	35 BRO	SP	A	ED, ID	TD	10/3/2038	
2021 PO4195486266	LGE	4	35 BRO	SP	A	ED, ID	TD	10/4/2038	
2021 PO4195486266-A	KU	5	35 BRO	SP	A	ED, ID, IP	TD	10/5/2038	
2021 PO4195886269	LGE	4	35 BRO	SP	CRE	ED, ID, IP	TD	10/6/2038	
2021 PO4196586277	LGE	4	35 BRO	SP	CRE	ED, ID, IP	TD	10/7/2038	
2021 PO4197386286	LGE	4	35 BRO	SP	A	ED, ID, IP	TD	10/8/2038	
2021 PO4198286295	LGE	4	35 BRO	SP	CRE	ED, ID, IP	TD	10/9/2038	
2021 PO4198986301	LGE	4	35 BRO	SP	CRE	ED, ID, IP	TD	10/10/2038	
2021 PO4199886311	LGE	4	35 BRO	SP	CRE	ED, ID	TD	10/11/2038	
2021 PO4200686319	LGE	4	35 BRO	SP	CRE	ED, ID, IP	TD	10/12/2038	
2021 PO4202986201	LGE	4	35 BRO	SP	CRE	ED, ID, IP	TD	10/13/2038	
2021 PO4202986201-A	KU	4	35 BRO	SP	A	ED, ID, IP	TD	10/14/2038	
2021 PO4202986213-A	KU	5	35 BRO	SP	CRE	ED, ID, IP	TD	10/15/2038	
2021 PO4203086225	LGE	4	35 BRO	SP	A	ED, ID, IP	TD	10/16/2038	
2021 PO4203086225-A	KU	5	35 BRO	SP	CRE	ED, ID	TD	10/17/2038	
2021 PO4203086237	LGE	4	35 BRO	SP	A	ED, ID, IP	TD	10/18/2038	
2021 PO4203086242	LGE	4	30 BRO	SP	CRE	ED, ID	TD	10/19/2038	
2021 PO4203086327	LGE	6	25 BRO	SP	CRE	ED, ID, IP	TD	10/20/2038	
2021 PO4204286242	LGE	4	30 BRO	SP	CRE	ED, ID, IP	TD	10/21/2038	
2021 PO4204386237	LGE	4	40 BRO	SP	CRE	ED, ID, IP	TD	10/22/2038	
2021 PO4204786337	LGE	4	40 BRO	SP	A	ED, ID, IP	TD	10/23/2038	
2021 PO4205086242	LGE	4	30 BRO	SP	CRE	ED, ID, IP	TD	10/24/2038	
2021 PO4205286237	LGE	4	40 BRO	SP	A	ED, ID	TD	10/25/2038	
2021 PO4141185172	LGE	3	45 BRN	SP	P	ID	BD	10/26/2038	
2021 PO4141585168	LGE	3	50 BRN	SP	P	ID	BD	10/27/2038	
2021 PO4145985156	LGE	4	40 BRN	SP	P	ID	BD	10/28/2038	
2021 PO4204386333	LGE	4	40 BRO	SP	CRE	ID, IP	BD	10/29/2038	
2021 PO1806643945	KU	4	40 BRN	SP	CRE	ED, HH, ID	X	PX	10/30/2038
2021 PO4230839821	KU	4	40 BRO	SP	CRE	ED, EP	VX	PX	10/31/2038
2021 PO0730161478	KU	3	45 BRO	SP	CCA		V		11/1/2038
2021 PO0758960823	KU	4	40 BRO	SP	CCA		V		11/2/2038
2021 PO0825759132	F	4	40 BRO	SP	CRE		V		11/3/2038
2021 PO1769545980	KU	4	40 BRN	SP	CRE		V		11/4/2038
2021 PO1791945309	KU	4	40 BRN	SP	CCA		V		11/5/2038
2021 PO1793143726	KU	3	50 BRN	SP	CCA		V		11/6/2038
2021 PO1806743781	KU	4	40 BRN	SP	CCA		V		11/7/2038
2021 PO1850745278	KU	5	35 BRN	SP	CRE		V		11/8/2038
2021 PO3360741748	KU	6	30 ACE	SP	CRE		V		11/9/2038
2021 PO3375441731	KU	4	40 ACE	SP	CRE		V		11/10/2038
2021 PO3382942046	KU	6	30 ACE	SP	CRE		V		11/11/2038
2021 PO3385041965	KU	4	40 ACE	SP	CRE		V		11/12/2038
2021 PO4260539550	KU	4	40 BRO	SP	CRE		V		11/13/2038
2021 PO4260740830	KU	6	30 BRO	SP	CRE		V		11/14/2038
2021 PO5325645748	KU	3	45 BRO	SP	CCA		V		11/15/2038
2021 PO5358945929	KU	4	45 BRO	SP	CCA		V		11/16/2038
2021 PO5359645928	KU	4	45 BRO	SP	CCA		V		11/17/2038
2021 PO5373945989	KU	3	50 BRO	SP	CCA		V		11/18/2038
2021 PO8908372072	KU	6	30 BRO	SP	CCA		V		11/19/2038
2021 PO8916872753	KU	6	30 BRO	SP	CCA		V		11/20/2038
2021 PO8917172103	KU	3	45 BRO	SP	CCA		V		11/21/2038
2021 PO8934472220	KU	3	45 BRO	SP	CCA		V		11/22/2038
2021 PO8937072510	KU	4	40 BRO	SP	CRE		V		11/23/2038

2021 PO8979872640	F	4	40 BRO	SP	A		V			11/24/2038
2021 PO9005872623	F	4	40 BRO	SP	CRE		V			11/25/2038
2021 PO9009672445	KU	4	40 BRO	SP	CCA		V			11/26/2038
2021 PO9169978699	F	5	30 BRO	SP	CRE		V			11/27/2038
2021 PO9170976582	KU	4	40 BRO	SP	CCA		V			11/28/2038
2021 PO9185478664	KU	3	45 BRO	SP	CCA		V			11/29/2038
2021 PO9192876658	F	2	50 BRO	SP	A		V			11/30/2038
2021 PO9192977558	KU	3	50 BRO	SP	CCA		V			12/1/2038
2021 PO9209576320	F	4	40 BRO	SP	A		V			12/2/2038
2021 PO9218775624	F	4	40 BRO	SP	A		V			12/3/2038
2021 PO9220076199	F	3	45 BRO	SP	A		V			12/4/2038
2021 PO9221175625	KU	3	45 BRO	SP	CCA		V			12/5/2038
2021 PO9228976381	KU	4	40 BRO	SP	S		V			12/6/2038
2021 PO9242276035	KU	4	40 BRO	SP	S		V			12/7/2038
2021 PO1831444138	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX	RR		12/8/2038
2021 PO2067541698	KU	4	40 BRN	SP	CRE	ED,EP,ID	TX	RR		12/9/2038
2021 PO9457579119	KU	3	40 BRO	SP	CRE	ED,ID	TX	RR		12/10/2038
2021 PO0803459631	KU	4	45 BRO	SP	CRE	ED,EP,ID	TD			12/11/2038
2021 PO1098553701	KU	4	40 BRN	SP	CRE	ED,EP,ID	TD			12/12/2038
2021 PO1145353029	KU	5	35 BRN	SP	CRE	ED,EP,ID,IP	TD			12/13/2038
2021 PO1155752891	KU	4	35 BRN	SP	CRE	ED,EP,ID	TD			12/14/2038
2021 PO1188952279	KU	6	35 BRN	SP	CRE	ED,ID	TD			12/15/2038
2021 PO1195452315	KU	4	45 BRO	SP	CRE	ED,EP,ID,MD	TD			12/16/2038
2021 PO1220651998	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD			12/17/2038
2021 PO1246051685	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD			12/18/2038
2021 PO1308750946	KU	4	40 BRO	SP	CRE	ED,ID,MD	TD			12/19/2038
2021 PO1325350707	KU	4	40 BRO	SP	CCA	ED,ID,MD	TD			12/20/2038
2021 PO1344550431	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD			12/21/2038
2021 PO1385449871	KU	4	40 BRO	SP	CRE	ED,ID,MD	TD			12/22/2038
2021 PO1442449051	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD			12/23/2038
2021 PO1788145640	KU	4	40 BRN	SP	CRE	ED,ID	TD			12/24/2038
2021 PO1789045584	KU	4	40 BRN	SP	CRE	ED,EP,ID	TD			12/25/2038
2021 PO1802145782	KU	6	30 BRN	SP	CRE	ID	TD			12/26/2038
2021 PO1802944070	KU	6	30 BRN	SP	CRE	ID	TD			12/27/2038
2021 PO1810345187	KU	5	35 BRN	SP	CRE	ID	TD			12/28/2038
2021 PO1814744005	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			12/29/2038
2021 PO1822545548	KU	4	40 BRN	SP	CRE	ID	TD			12/30/2038
2021 PO1824244080	KU	6	40 BRN	SP	CRE	ID,SRS	TD			12/31/2038
2021 PO1827345292	KU	4	40 BRN	SP	CRE	HH,ID	TD			1/1/2039
2021 PO1842545190	KU	4	40 BRN	SP	CRE	ED,ID	TD			1/2/2039
2021 PO2056541569	KU	4	40 BRN	SP	CRE	ID	TD			1/3/2039
2021 PO2087741514	KU	4	40 BRN	SP	CRE	ID	TD			1/4/2039
2021 PO2088041911	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			1/5/2039
2021 PO4267440419	KU	5	35 BRO	SP	CRE	ED,EP,ID	TD			1/6/2039
2021 PO4269840737	KU	6	30 BRO	SP	CRE	ED,ID	TD			1/7/2039
2021 PO4270640865	KU	5	30 BRO	SP	CRE	ED,EP,ID	TD			1/8/2039
2021 PO8891972586	KU	5	35 BRO	SP	CRE	ID	TD			1/9/2039
2021 PO8927172742	KU	5	35 BRO	SP	CRE	ED,ID	TD			1/10/2039
2021 PO8950572617	KU	5	35 BRO	SP	CRE	ED,ID	TD			1/11/2039
2021 PO8954872391	KU	4	40 BRO	SP	CRE	ED,ID	TD			1/12/2039
2021 PO8962372567	KU	4	40 BRO	SP	CRE	ED,ID	TD			1/13/2039
2021 PO8974872519	KU	4	40 BRO	SP	CRE	ED,ID	TD			1/14/2039
2021 PO9220276718	KU	4	40 BRO	SP	CRE	ED,ID	TD			1/15/2039
2021 PO9438877822	KU	4	40 BRO	SP	CRE	ED,ID	TD			1/16/2039

2021 PO9477679047	KU	4	40 BRO	SP	CRE	ED,ID	TD		1/17/2039
2021 PO9453478234	KU	4	40 BRO	SP	CRE	ED,HH,ID	BX	RP2	1/18/2039
2021 PO1118453409	KU	4	35 BRN	SP	CRE	ED,ID	BD		1/19/2039
2021 PO1132453205	KU	4	40 BRN	SP	CRE	ED,ID	BD		1/20/2039
2021 PO1797245812	KU	4	40 BRN	SP	CRE	ID	BD		1/21/2039
2021 PO1797245812A1	KU	6	30 BRN	SP	CRE	ED,ID,IP	BD		1/22/2039
2021 PO5711914427	KU	6	30 BRN	SP	CCA		V		1/23/2039
2021 PO5694114315	KU	4	45 BRN	SP	CCA		V		1/24/2039
2021 PO5751915725	KU	3	45 UNK	SP	S		V		1/25/2039
2021 PO4350307879	KU	4	45 KOP	SP	CCA		V		1/26/2039
2021 PO4345008155	KU	3	50 KOP	SP	CCA		V		1/27/2039
2021 PO4344208425	KU	3	50 KOP	SP	CCA		V		1/28/2039
2021 PO4343108681	KU	3	50 KOP	SP	CCA		V		1/29/2039
2021 PO4342908808	KU	3	50 KOP	SP	CCA		V		1/30/2039
2021 PO4341909028	KU	3	50 KOP	SP	CCA		V		1/31/2039
2021 PO5440212125	KU	4	40 UNK	SP	CCA		V		2/1/2039
2021 PO5439012093	KU	4	40 UNK	SP	CCA		V		2/2/2039
2021 PO5049519107	KU	5	35 KOP	SP	CCA		V		2/3/2039
2021 PO5059819027	KU	2	55 BRO	SP	CCA		V		2/4/2039
2021 PO5078019237	KU	2	55 BRO	SP	CCA		V		2/5/2039
2021 PO5080919371	KU	3	45 BRO	SP	CCA		V		2/6/2039
2021 PO5086219325	KU	3	55 BRO	SP	CCA		V		2/7/2039
2021 PO5096319426	KU	2	50 BRO	SP	CCA		V		2/8/2039
2021 PO5111219564	KU	2	50 BRO	SP	CCA		V		2/9/2039
2021 PO5133119308	KU	5	35 BRO	SP	CCA		V		2/10/2039
2021 PO5149219083	KU	2	50 BRO	SP	CCA		V		2/11/2039
2021 PO5155119164	KU	2	50 BRO	SP	CCA		V		2/12/2039
2021 PO5176019029	KU	5	35 BRO	SP	CCA		V		2/13/2039
2021 PO5196218897	KU	5	35 BRO	SP	CCA		V		2/14/2039
2021 PO5216318766	KU	5	35 BRO	SP	CCA		V		2/15/2039
2021 PO5236518635	KU	5	35 BRO	SP	CCA		V		2/16/2039
2021 PO5257018477	KU	5	35 BRO	SP	CCA		V		2/17/2039
2021 PO5277518319	KU	5	35 BRO	SP	CCA		V		2/18/2039
2021 PO5314315629	F	4	40 BRN	SP	CRE		V		2/19/2039
2021 PO5306915633	F	4	40 BRN	SP	CRE		V		2/20/2039
2021 PO5304715711	F	4	40 BRN	SP	CCA		V		2/21/2039
2021 PO4426507094	KU	2	50 KOP	SP	CCA		V		2/22/2039
2021 PO4422307189	KU	3	45 KOP	SP	CCA		V		2/23/2039
2021 PO4404307313	KU	4	45 KOP	SP	CCA		V		2/24/2039
2021 PO2960318413	KU	3	45 BRN	SP	CCA		V		2/25/2039
2021 PO6453327012	KU	4	40 UNK	SP	CCA		V		2/26/2039
2021 PO6464827234	KU	4	40 UNK	SP	CCA		V		2/27/2039
2021 PO6447726758	KU	4	40 UNK	SP	CRE		V		2/28/2039
2021 PO6439126811	KU	3	45 UNK	SP	CCA		V		3/1/2039
2021 PO6434025632	KU	4	40 UNK	SP	CCA		V		3/2/2039
2021 PO6427325687	F	4	40 UNK	SP	CRE		V		3/3/2039
2021 PO6435826626	KU	4	40 UNK	SP	CCA		V		3/4/2039
2021 PO5003817916	KU	3	45 BRO	SP	CCA		V		3/5/2039
2021 PO5294716142	F	4	40 BRN	SP	CRE		V		3/6/2039
2021 PO6444427183	KU	3	45 UNK	SP	CCA		V		3/7/2039
2021 PO6426319334	KU	4	40 BRN	SP	CCA		V		3/8/2039
2021 PO5295216828	KU	2	50 BRN	SP	CCA		V		3/9/2039
2021 PO5290916718	KU	5	35 BRN	SP	CCA		V		3/10/2039
2021 PO5298216700	F	4	40 BRN	SP	CRE		V		3/11/2039

2021	PO5297016491	F	4	40 BRN	SP	CRE		V	3/12/2039
2021	PO5296316373	F	4	40 BRN	SP	CRE		V	3/13/2039
2021	PO5280516035	KU	6	30 BRN	SP	CCA		V	3/14/2039
2021	PO5286616036	KU	6	30 BRN	SP	CCA		V	3/15/2039
2021	PO5280716190	KU	6	30 BRN	SP	CCA		V	3/16/2039
2021	PO5298015901	F	4	40 BRN	SP	CCA		V	3/17/2039
2021	PO5040818577	KU	2	50 BRO	SP	CCA		V	3/18/2039
2021	PO5029318632	KU	4	45 BRO	SP	CCA		V	3/19/2039
2021	PO5033818789	KU	5	35 BRO	SP	CRE		V	3/20/2039
2021	PO5043718732	KU	2	50 BRO	SP	CCA		V	3/21/2039
2021	PO5049818876	KU	2	50 BRO	SP	CCA		V	3/22/2039
2021	PO5068218896	KU	3	50 BRO	SP	CCA		V	3/23/2039
2021	PO6432425061	KU	4	40 UNK	SP	CCA		V	3/24/2039
2021	PO6426025087	F	4	40 UNK	SP	CCA		V	3/25/2039
2021	PO6426825383	F	4	40 UNK	SP	P		V	3/26/2039
2021	PO6424724638	KU	4	40 UNK	SP	CCA		V	3/27/2039
2021	PO6474219419	KU	4	40 BRN	SP	CCA		V	3/28/2039
2021	PO5299316853	F	4	40 BRN	SP	CRE		V	3/29/2039
2021	PO3006718109	F	3	45 BRN	SP	CCA		V	3/30/2039
2021	PO5059618337	KU	1	70 UNK	ST	CCA		V	3/31/2039
2021	PO5325918365	F	3	50 UNK	SP	P		V	4/1/2039
2021	PO2886916334	KU	4	40 BRN	SP	CCA		V	4/2/2039
2021	PO5308417388	F	3	50 BRN	SP	CRE		V	4/3/2039
2021	PO5301717221	F	4	40 BRN	SP	CRE		V	4/4/2039
2021	PO5310317553	F	3	50 BRN	SP	CRE		V	4/5/2039
2021	PO5366916801	KU	2	50 BRO	SP	CCA		V	4/6/2039
2021	PO5322918216	F	4	40 BRN	SP	CRE		V	4/7/2039
2021	PO5311418131	KU	5	35 BRN	SP	CCA		V	4/8/2039
2021	PO5313518068	F	4	30 BRN	SP	CCA		V	4/9/2039
2021	PO5321018073	F	4	40 BRN	SP	CRE		V	4/10/2039
2021	PO5317217894	F	3	50 BRN	SP	CRE		V	4/11/2039
2021	PO5313917727	F	3	50 BRN	SP	CRE		V	4/12/2039
2021	PO4938717564	KU	2	50 BRO	SP	CCA		V	4/13/2039
2021	PO5466911802	F	4	40 XXX	SP	CRE	ED	V	4/14/2039
2021	PO5263819035	KU	3	45 BRO	SP	CCA		V	4/15/2039
2021	PO5271818979	KU	3	45 BRO	SP	CCA		V	4/16/2039
2021	PO5261218814	KU	3	45 BRO	SP	CCA		V	4/17/2039
2021	PO5250518648	KU	3	45 UNK	SP	CCA		V	4/18/2039
2021	PO5278318812	KU	4	40 BRO	SP	CCA		V	4/19/2039
2021	PO5333218679	F	3	45 BRO	SP	P		V	4/20/2039
2021	PO5322918683	KU	4	45 BRO	SP	CCA		V	4/21/2039
2021	PO5313018682	KU	3	45 BRO	SP	CCA		V	4/22/2039
2021	PO6414618790	KU	4	40 BRN	SP	CCA		V	4/23/2039
2021	PO6392818640	KU	5	35 BRN	SP	CCA		V	4/24/2039
2021	PO5309018711	KU	3	45 BRO	SP	CCA		V	4/25/2039
2021	PO5292118833	KU	3	45 BRO	SP	CCA		V	4/26/2039
2021	PO5247819144	KU	5	45 BRO	SP	CCA		V	4/27/2039
2021	PO5084418210	KU	3	45 BRO	SP	CCA		V	4/28/2039
2021	PO5083018251	KU	3	45 BRO	SP	CCA		V	4/29/2039
2021	PO5085118297	KU	3	45 BRO	SP	CCA		V	4/30/2039
2021	PO5092118375	KU	2	55 BRO	SP	CCA		V	5/1/2039
2021	PO5086618400	KU	2	45 BRO	SP	CCA		V	5/2/2039
2021	PO5083018417	KU	2	50 BRO	SP	CCA		V	5/3/2039
2021	PO5070918374	KU	2	50 BRO	SP	CCA		V	5/4/2039



2021	PO5576212564	KU	4	45 BRN	SP	CCA		V	5/5/2039
2021	PO5567712600	KU	3	45 BRN	SP	CCA		V	5/6/2039
2021	PO5562012606	KU	4	45 BRN	SP	CCA		V	5/7/2039
2021	PO6814323788	F	4	40 XXX	SP	P		V	5/8/2039
2021	PO6812923846	KU	3	45 XXX	SP	CCA		V	5/9/2039
2021	PO6830923773	F	4	40 XXX	SP	P		V	5/10/2039
2021	PO7008923426	F	4	40 XXX	SP	CCA		V	5/11/2039
2021	PO7035723268	F	4	40 XXX	SP	P		V	5/12/2039
2021	PO7027823045	F	4	40 XXX	SP	P		V	5/13/2039
2021	PO7014222695	F	4	40 XXX	SP	P		V	5/14/2039
2021	PO6794623860	KU	4	40 XXX	SP	CCA		V	5/15/2039
2021	PO2235220116	KU	4	40 BRN	SP	CCA		V	5/16/2039
2021	PO2253520521	KU	3	45 BRN	SP	CCA		V	5/17/2039
2021	PO6281323489	F	4	40 UNK	SP	CCA		V	5/18/2039
2021	PO6319923768	F	3	45 UNK	SP	CCA		V	5/19/2039
2021	PO2447120108	F	4	40 BRN	SP	A		V	5/20/2039
2021	PO6354923765	F	4	40 UNK	SP	CCA		V	5/21/2039
2021	PO2350721153	KU	4	45 BRN	SP	CCA		V	5/22/2039
2021	PO2351320862	KU	3	45 BRN	SP	CCA		V	5/23/2039
2021	PO2350920809	KU	3	45 BRN	SP	CCA		V	5/24/2039
2021	PO2351420669	KU	4	45 BRN	SP	CCA		V	5/25/2039
2021	PO6799522547	F	4	40 XXX	SP	CRE		V	5/26/2039
2021	PO6636524131	KU	5	35 XXX	SP	CCA		V	5/27/2039
2021	PO6651224196	KU	4	40 XXX	SP	CCA		V	5/28/2039
2021	PO5492712342	F	4	45 KOP	SP	CCA		V	5/29/2039
2021	PO5497212485	F	4	40 KOP	SP	CRE		V	5/30/2039
2021	PO5522012708	F	4	40 KOP	SP	P		V	5/31/2039
2021	PO5504212714	F	4	45 KOP	SP	P		V	6/1/2039
2021	PO5504312830	F	4	45 KOP	SP	P		V	6/2/2039
2021	PO6409824644	KU	4	40 UNK	SP	CCA		V	6/3/2039
2021	PO6431424370	KU	4	40 UNK	SP	CCA		V	6/4/2039
2021	PO6424124376	F	4	40 UNK	SP	CCA		V	6/5/2039
2021	PO5981318642	F	4	40 UNK	SP	CRE		V	6/6/2039
2021	PO5989018649	F	6	30 UNK	SP	CRE		V	6/7/2039
2021	PO5994618561	F	4	40 UNK	SP	CRE		V	6/8/2039
2021	PO7058723296	KU	4	40 KOP	SP	CCA		V	6/9/2039
2021	PO5574407088	KU	5	30 BRN	SP	CRE	ED	TD	6/10/2039
2021	PO5551307152	KU	3	45 BRN	SP	CRE	ED	TD	6/11/2039
2021	PO5546307175	KU	6	30 BRN	SP	CRE	ED	TD	6/12/2039
2021	PO5488808329	KU	5	35 BRN	SP	CRE	ED,ID	TD	6/13/2039
2021	PO5169408077	KU	5	35 XXX	SP	CRE	ED,ID,MD,SRC	TD	6/14/2039
2021	PO5224808124	KU	4	45 XXX	SP	CRE	ED,ID	TD	6/15/2039
2021	PO5229308107	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD	6/16/2039
2021	PO5261408336	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	6/17/2039
2021	PO5580512415	KU	1	70 UNK	SP	CRE	ED,ID	TD	6/18/2039
2021	PO5485708419	KU	3	45 BRN	SP	CRE	ED,ID	TD	6/19/2039
2021	PO5575712264	KU	1	75 UNK	SP	CRE	ED,ID	TD	6/20/2039
2021	PO5573507303	KU	5	30 BRN	SP	CRE	ED	TD	6/21/2039
2021	PO5522006919	KU	3	45 BRN	SP	CRE	ED	TD	6/22/2039
2021	PO5655312505	KU	6	30 UNK	SP	CRE	ED,ID	TD	6/23/2039
2021	PO5467607817	KU	H1	85 BRN	SP	CRE	ED,ID,MD	TD	6/24/2039
2021	PO5238808571	KU	5	35 XXX	SP	CRE	ED,ID	TD	6/25/2039
2021	PO5194108664	KU	3	45 XXX	SP	CRE	ED,ID	TD	6/26/2039
2021	PO5583707475	KU	6	30 BRN	SP	CRE	ED,ID	TD	6/27/2039

2021	PO5570807514	KU	6	30 BRN	SP	CRE	ED	TD	6/28/2039
2021	PO5583707690	KU	6	30 BRN	SP	CRE	ED	TD	6/29/2039
2021	PO5595807658	KU	6	30 BRN	SP	CRE	ED	TD	6/30/2039
2021	PO5433314311	KU	4	40 UNK	SP	CRE	ED,ID	TD	7/1/2039
2021	PO5525712970	KU	4	40 UNK	SP	CRE	ED,ID	TD	7/2/2039
2021	PO5504913087	KU	4	40 UNK	SP	CRE	ED,ID	TD	7/3/2039
2021	PO5519112863	KU	3	45 UNK	SP	CRE	ED,ID	TD	7/4/2039
2021	PO5596008201	KU	5	35 BRN	SP	CRE	ED	TD	7/5/2039
2021	PO5560607678	KU	2	40 BRN	SP	CRE	ED	TD	7/6/2039
2021	PO5548107027	KU	3	45 BRN	SP	CRE	ED	TD	7/7/2039
2021	PO5537307084	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/8/2039
2021	PO7342105568	KU	5	35 BRN	SP	CRE	ED	TD	7/9/2039
2021	PO7340005688	KU	6	30 BRN	SP	CRE	ED	TD	7/10/2039
2021	PO5425613821	KU	6	30 UNK	SP	CRE	ED,ID	TD	7/11/2039
2021	PO5414013898	KU	5	35 UNK	SP	CRE	ED,ID	TD	7/12/2039
2021	PO5594013628	KU	6	30 UNK	SP	CRE	ED,ID	TD	7/13/2039
2021	PO7687805247	KU	2	45 BRN	SP	CRE	ED	TD	7/14/2039
2021	PO7693105950	KU	2	55 BRN	SP	CRE	ED	TD	7/15/2039
2021	PO5438913296	KU	6	30 BRO	SP	P	ED,ID	TD	7/16/2039
2021	PO5231405544	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	7/17/2039
2021	PO5594306962	KU	2	45 BRN	SP	CRE	ED	TD	7/18/2039
2021	PO5591906768	KU	2	45 BRN	SP	CRE	ED	TD	7/19/2039
2021	PO5589106547	KU	2	45 BRN	SP	CRE	ED	TD	7/20/2039
2021	PO5605106425	KU	4	40 BRN	SP	CRE	ED	TD	7/21/2039
2021	PO5606806549	KU	4	40 BRN	SP	CRE	ED	TD	7/22/2039
2021	PO5608806690	KU	4	40 BRN	SP	CRE	ED	TD	7/23/2039
2021	PO5610506807	KU	4	40 BRN	SP	CRE	ED	TD	7/24/2039
2021	PO4428985529	LGE	4	35 BRO	SP	A	ED	TD	7/25/2039
2021	PO4426885515	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	7/26/2039
2021	PO4393885874	LGE	3	45 BRO	SP	A	ED,ID	TD	7/27/2039
2021	PO4423985496	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/28/2039
2021	PO4406385861	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	7/29/2039
2021	PO4426685549	LGE	5	25 BRO	SP	A	ED,ID,IP	TD	7/30/2039
2021	PO4427485537	LGE	5	25 BRO	SP	A	ED,ID,IP	TD	7/31/2039
2021	PO4402685924	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	8/1/2039
2021	PO6137021656	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	8/2/2039
2021	PO4332708072	KU	3	45 KOP	SP	CRE	ID	TD	8/3/2039
2021	PO2736916566	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/4/2039
2021	PO4385807501	KU	4	45 KOP	SP	CRE	ID	TD	8/5/2039
2021	PO6658323904	KU	4	40 XXX	SP	CRE	ID	TD	8/6/2039
2021	PO6664923526	KU	6	30 XXX	SP	CRE	ID	TD	8/7/2039
2021	PO5290316288	KU	4	45 BRN	SP	CRE	ED	TD	8/8/2039
2021	PO5014617855	KU	3	45 UNK	SP	CRE	ED,ID	TD	8/9/2039
2021	PO2275921681	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/10/2039
2021	PO6721623883	KU	4	40 XXX	SP	CRE	ID	TD	8/11/2039
2021	PO2272721056	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/12/2039
2021	PO5019717972	KU	1	85 UNK	SP	CRE	ED,ID	TD	8/13/2039
2021	PO4982817837	KU	3	45 CPT	SP	CRE	ED,ID	TD	8/14/2039
2021	PO6722423605	KU	4	40 XXX	SP	CRE	ID	TD	8/15/2039
2021	PO6722823284	KU	4	45 XXX	SP	CRE	ID	TD	8/16/2039
2021	PO6729223215	KU	4	45 XXX	SP	CRE	ID	TD	8/17/2039
2021	PO6216019150	KU	4	40 UNK	SP	CRE	ED,ID	TD	8/18/2039
2021	PO6058419173	KU	4	40 UNK	SP	CRE	ED,ID	TD	8/19/2039
2021	PO5480411658	KU	4	40 UNK	SP	CRE	ED,ID	TD	8/20/2039

2021 PO6803824247	KU	4	40 XXX	SP	CRE	ID	TD	8/21/2039
2021 PO6814924359	KU	4	40 XXX	SP	CRE	ID	TD	8/22/2039
2021 PO6830224680	KU	4	40 XXX	SP	CRE	ID	TD	8/23/2039
2021 PO6831023829	KU	5	35 XXX	SP	CRE	ID	TD	8/24/2039
2021 PO6853523801	KU	4	40 XXX	SP	CRE	ID	TD	8/25/2039
2021 PO6891123748	KU	5	35 XXX	SP	CRE	ID	TD	8/26/2039
2021 PO6918523705	KU	5	35 XXX	SP	CRE	ID	TD	8/27/2039
2021 PO6416423951	KU	3	50 UNK	SP	CRE	ED,ID	TD	8/28/2039
2021 PO6750123876	KU	5	35 XXX	SP	CRE	ID	TD	8/29/2039
2021 PO6783623865	KU	5	35 XXX	SP	CRE	ID	TD	8/30/2039
2021 PO6353723869	KU	5	35 UNK	SP	CRE	ED,ID	TD	8/31/2039
2021 PO5438012254	KU	5	35 UNK	SP	CRE	ED,ID	TD	9/1/2039
2021 PO6772722793	KU	5	35 XXX	SP	CRE	ID	TD	9/2/2039
2021 PO6784922475	KU	4	40 XXX	SP	CRE	ID	TD	9/3/2039
2021 PO2433720425	KU	5	35 BRN	SP	CRE	ED,ID	TD	9/4/2039
2021 PO6450019063	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/5/2039
2021 PO5484712664	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/6/2039
2021 PO6693823891	KU	4	40 XXX	SP	CRE	ID	TD	9/7/2039
2021 PO6037918617	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/8/2039
2021 PO4642712074	KU	4	40 KOP	SP	CRE	ID	TD	9/9/2039
2021 PO5998818402	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/10/2039
2021 PO2216122667	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/11/2039
2021 PO6035318687	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	9/12/2039
2021 PO6070718601	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/13/2039
2021 PO6951123643	KU	5	35 KOP	SP	CRE	ID	TD	9/14/2039
2021 PO5817415716	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/15/2039
2021 PO5837516313	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/16/2039
2021 PO5928817821	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/17/2039
2021 PO5723911224	KU	5	35 KOP	SP	CRE	ID	TD	9/18/2039
2021 PO5519611624	KU	4	40 KOP	SP	CRE	ID	TD	9/19/2039
2021 PO5517811677	KU	5	35 KOP	SP	CRE	ID	TD	9/20/2039
2021 PO5486911534	KU	6	30 KOP	SP	CRE	ID	TD	9/21/2039
2021 PO5579111779	KU	6	30 KOP	SP	CRE	ID	TD	9/22/2039
2021 PO5585011976	KU	4	45 KOP	SP	CRE	ID	TD	9/23/2039
2021 PO4320808206	KU	4	40 KOP	SP	CRE	ID	TD	9/24/2039
2021 PO5808215447	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/25/2039
2021 PO5938817981	KU	5	35 UNK	SP	CRE	ED,ID	TD	9/26/2039
2021 PO5557211819	KU	4	40 KOP	SP	CRE	ID	TD	9/27/2039
2021 PO4656912007	KU	5	45 KOP	SP	CRE	ID	TD	9/28/2039
2021 PO4664911969	KU	4	40 KOP	SP	CRE	ID	TD	9/29/2039
2021 PO7080523163	KU	5	35 KOP	SP	CRE	ID	TD	9/30/2039
2021 PO7689305903	KU	3	45 BRN	SP	CCA		T	10/1/2039
2021 PO5253906997	KU	4	45 XXX	SP	S	ED,SR	T	10/2/2039
2021 PO5185333734	KU	5	35 BRN	SP	CRE	ID	BD	10/3/2039
2021 PO5165033294	KU	2	70 BRN	SP	CRE	ID	TD	10/4/2039
2021 PO4041786333	LGE	4	40 ACE	SP	CRE	ED,ID	TD	10/5/2039
2021 PO5067437384	KU	4	40 BRO	SP	CRE	ID	BD	10/6/2039
2021 PO5069536624	KU	3	45 UNK	SP	CRE	ID	TD	10/7/2039
2021 PO4045686345	LGE	4	40 ACE	SP	CRE	ED,ID	TD	10/8/2039
2021 PO4045386340	LGE	4	40 ACE	SP	CRE	ED,ID	TD	10/9/2039
2021 PO4045086078	LGE	3	45 KOP	SP	A	ED,ID,IP,MD	TD	10/10/2039
2021 PO4047086068	LGE	3	50 KOP	SP	CCA	ED	T	10/11/2039
2021 PO5269011042	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/12/2039
2021 PO5263011015	KU	3	40 BRO	SP	CRE	ED,ID	TD	10/13/2039

2021 PO5243011140	KU	3	40 BRO	SP	CRE	ED,ID	TD		10/14/2039
2021 PO5222111217	KU	2	45E BRO	SP	CRE	ID,IP	TD		10/15/2039
2021 PO4052585748	LGE	4	40 BRO	SP	CRE	ED,ID,RB	TX	RR	10/16/2039
2021 PO4052185754	LGE	2	55 BRO	SP	CRE	ED,ID	TD		10/17/2039
2021 PO4053985727	LGE	4	40 BRO	SP	CCA	ED,EP,ID,RB	TX	RR	10/18/2039
2021 PO4603412146	KU	3	45 KOP	SP	CRE	ED,ID	BD		10/19/2039
2021 PO4673511881	KU	4	40 KOP	SP	CRE	ED,ID	BD		10/20/2039
2021 PO4048285826	LGE	4	35 BRO	SP	P	ED,ID	TD		10/21/2039
2021 PO4047485827	LGE	4	35 BRO	SP	P	ED,ID	TD		10/22/2039
2021 PO5300510937	KU	4	40 BRO	SP	CRE	ID	TD		10/23/2039
2021 PO5251625338	KU	4	40 BRN	SP	CRE		T		10/24/2039
2021 PO4046586340	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD		10/25/2039
2021 PO5341511308	KU	3	50 BRO	SP	CRE	ID	TD		10/26/2039
2021 PO5273133036	KU	5	35 BRN	SP	CRE	ID	TD		10/27/2039
2021 PO5338811231	KU	1	65 BRO	SP	CRE	ED,ID,IP	BD		10/28/2039
2021 PO5330611215	KU	1	65 BRO	SP	CRE	ED,ID,SR	TD		10/29/2039
2021 PO5289232567	KU	4	40 BRN	SP	CRE	ID,IP	X	RP1	10/30/2039
2021 PO5298432676	KU	3	45 BRN	SP	CRE	ID	TD		10/31/2039
2021 PO5188533361	KU	4	40 BRN	SP	CRE	ID	TD		11/1/2039
2021 PO4657612138	KU	5	35 KOP	SP	CRE	ED,ID	TD		11/2/2039
2021 PO4668812471	KU	5	35 KOP	SP	CRE	ED,ID	BD		11/3/2039
2021 PO5147625511	KU	6	30 UNK	SP	CRE		T		11/4/2039
2021 PO4041786090	LGE	5	25 KOP	SP	A	ED,ID	TD		11/5/2039
2021 PO4041886093	LGE	3	45 KOP	SP	A	ED,ID,IP,MD	TD		11/6/2039
2021 PO5156225579	KU	6	30 UNK	SP	CRE		T		11/7/2039
2021 PO4043286087	LGE	3	45 KOP	SP	CCA		T		11/8/2039
2021 PO4896035484	KU	3	45 UNK	SP	CRE	ID	BX	PX	11/9/2039
2021 PO4909535811	KU	4	40 BRO	SP	CRE	ID	X	PX	11/10/2039
2021 PO4905035702	KU	2	40 BRO	SP	CRE	ID	TD		11/11/2039
2021 PO4914035920	KU	5	35 KOP	SP	CRE	ID	TD		11/12/2039
2021 PO4918436030	KU	4	40 UNK	SP	CRE	ID	BD		11/13/2039
2021 PO5083936541	KU	3	40 UNK	SP	CRE	ID	BX	RP2	11/14/2039
2021 PO4663912328	KU	5	35 KOP	SP	CRE	ED,ID	BD		11/15/2039
2021 PO4672812973	KU	4	40 KOP	SP	CRE	ED,ID	BD		11/16/2039
2021 PO4683113128	KU	4	40 KOP	SP	CRE	ED,ID	TD		11/17/2039
2021 PO5143225389	KU	6	30 UNK	SP	CRE		T		11/18/2039
2021 PO5250132886	KU	4	40 BRN	SP	CRE	ID	TD		11/19/2039
2021 PO5263432784	KU	5	35 BRN	SP	CRE	ID	BD		11/20/2039
2021 PO5276832669	KU	4	40 BRN	SP	CRE	ID	TD		11/21/2039
2021 PO5145325198	KU	6	30 UNK	SP	CRE		T		11/22/2039
2021 PO5170525137	KU	6	30 UNK	SP	CRE		T		11/23/2039
2021 PO4631213327	KU	5	35 KOP	SP	CRE	ED,ID	BD		11/24/2039
2021 PO4040486101	LGE	3	45 KOP	SP	A	ED,ID,MD	TD		11/25/2039
2021 PO4625313118	KU	5	35 KOP	SP	CRE	ED,ID	BD		11/26/2039
2021 PO5087125574	KU	6	30 UNK	SP	CRE		T		11/27/2039
2021 PO4635513472	KU	5	35 KOP	SP	CRE	ED,ID	TD		11/28/2039
2021 PO4639813611	KU	5	35 KOP	SP	CRE	ED,ID	BD		11/29/2039
2021 PO5179511328	KU	7	30 BRO	SP	CRE	ID,SR	TD		11/30/2039
2021 PO4978534889	KU	4	35 ACW	SP	CRE	ID	TD		12/1/2039
2021 PO5006834566	KU	2	50 BRO	SP	CRE	ID	TD		12/2/2039
2021 PO4014086288	LGE	4	35 ACE	SP	P	ED,ID	BD		12/3/2039
2021 PO4015286289	LGE	4	35 ACE	SP	A	ED,ID	BD		12/4/2039
2021 PO4710412920	KU	4	40 KOP	SP	CRE	ED,ID	TD		12/5/2039
2021 PO4731312627	KU	4	40 KOP	SP	CRE	ED,ID	BD		12/6/2039

2021 PO4720312840	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/7/2039
2021 PO4703312814	KU	5	35 KOP	SP	CRE	ED,ID	TD	12/8/2039
2021 PO4012986298	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/9/2039
2021 PO5341711555	KU	7	30 BRO	SP	CRE	ID	BD	12/10/2039
2021 PO4059985593	F	4	40 BRO	SP	CRE		VX	12/11/2039
2021 PO4032985961	F	3	45 KOP	SP	CCA		V	12/12/2039
2021 PO4039485762	F	4	40 KOP	SP	A		V	12/13/2039
2021 PO4039485740	F	4	40 KOP	SP	A		V	12/14/2039
2021 PO4039485727	F	4	40 KOP	SP	A		V	12/15/2039
2021 PO4039385715	F	4	40 KOP	SP	A		V	12/16/2039
2021 PO4039385703	F	3	45 KOP	SP	CCA		V	12/17/2039
2021 PV4039285691	F	4	40 KOP	SP	CCA		V	12/18/2039
2021 PO4039285680	F	4	40 KOP	SP	A		V	12/19/2039
2021 PO4039185667	F	3	45 KOP	SP	CCA		V	12/20/2039
2021 PO4033485527	LGE	4	30 KOP	SP	A		V	12/21/2039
2021 PO4033485532	LGE	4	55 KOP	SP	A		V	12/22/2039
2021 PO4033685541	LGE	4	30 KOP	SP	P		V	12/23/2039
2021 PO4033185552	LGE	4	30 KOP	SP	CCA		V	12/24/2039
2021 PO4032885564	LGE	5	30 KOP	SP	A		V	12/25/2039
2021 PO4033785564	F	3	45 KOP	SP	CCA		V	12/26/2039
2021 PO4033785574	LGE	4	40 KOP	SP	A		V	12/27/2039
2021 PO4033885587	LGE	4	40 KOP	SP	CCA		V	12/28/2039
2021 PO4033185595	LGE	4	35 KOP	SP	P		V	12/29/2039
2021 PO4033885595	LGE	4	40 KOP	SP	CCA		V	12/30/2039
2021 PO4032985605	LGE	4	30 KOP	SP	P		V	12/31/2039
2021 PO4033985609	LGE	3	45 KOP	SP	CCA		V	1/1/2040
2021 PO7494068011	LGE	4	35 KOP	SP	CCA		V	1/2/2040
2021 PO4042185528	LGE	4	35 BRO	SP	CCA		V	1/3/2040
2021 PO4031085651	F	4	40 KOP	SP	A		V	1/4/2040
2021 PO4032885669	F	6	25 KOP	SP	A		V	1/5/2040
2021 PO4033785668	F	3	45 KOP	SP	CCA		V	1/6/2040
2021 PO4033285681	F	5	25 KOP	SP	P		V	1/7/2040
2021 PO4033985679	F	4	40 KOP	SP	A		V	1/8/2040
2021 PO4033785695	F	5	25 KOP	SP	P		V	1/9/2040
2021 PO4034585690	F	4	40 KOP	SP	CCA		V	1/10/2040
2021 PO4035285692	F	4	30 KOP	SP	P		V	1/11/2040
2021 PO4035985703	F	4	30 KOP	SP	P		V	1/12/2040
2021 PO4035385703	F	3	45 KOP	SP	CCA		V	1/13/2040
2021 PO4036485715	F	4	30 KOP	SP	A		V	1/14/2040
2021 PO5271526344	KU	2	50 UNK	SP	CCA		V	1/15/2040
2021 PO5258126327	KU	4	40 UNK	SP	CCA		V	1/16/2040
2021 PO5264026141	KU	2	55 UNK	ST	CCA		V	1/17/2040
2021 PO4033385970	F	3	45 KOP	SP	CCA		V	1/18/2040
2021 PO4033885978	F	3	45 KOP	SP	CCA		V	1/19/2040
2021 PO5430535290	KU	2	50 BRO	SP	CCA		V	1/20/2040
2021 PO4032485650	F	4	40 KOP	SP	A		V	1/21/2040
2021 PO5361131924	KU	6	30 KOP	SP	CCA		V	1/22/2040
2021 PO5358232088a	KU	3	45 KOP	SP	CCA		V	1/23/2040
2021 PO5352131998	KU	6	30 KOP	SP	CCA		V	1/24/2040
2021 PO4035885715	F	4	40 KOP	SP	A		V	1/25/2040
2021 PO4035885730	F	6	25 KOP	SP	A		V	1/26/2040
2021 PO4036585727	F	4	40 KOP	SP	P		V	1/27/2040
2021 PO4040985513	F	4	40 BRO	SP	P		V	1/28/2040
2021 PO4040885493	F	4	40 BRO	SP	P		V	1/29/2040

2021 PO4040885506	F	4	40 BRO	SP	CRE	V	1/30/2040
2021 PO4036985745	F	4	25 KOP	SP	P	V	1/31/2040
2021 PO4037185738	F	3	45 KOP	SP	CCA	V	2/1/2040
2021 PO4038085750	F	4	25 KOP	SP	P	V	2/2/2040
2021 PO4038085741	F	3	45 KOP	SP	CCA	V	2/3/2040
2021 PO4040785482	F	4	40 BRO	SP	CRE	V	2/4/2040
2021 PO5039835154	KU	3	45 BRO	SP	CCA	B	2/5/2040
2021 PO5054135406	KU	3	45 BRO	SP	CCA	B	2/6/2040
2021 PO5082635912	KU	3	45 BRO	SP	CCA	B	2/7/2040
2021 PO5089836041	KU	3	45 BRO	SP	CCA	B	2/8/2040
2021 PO5097136170	KU	3	45 BRO	SP	CCA	B	2/9/2040
2021 PO4035985875	F	3	45 KOP	SP	CCA	V	2/10/2040
2021 PO4035485866	F	4	40 KOP	SP	P	V	2/11/2040
2021 PO4034985855	F	4	40 KOP	SP	A	V	2/12/2040
2021 PO4034385840	F	4	40 KOP	SP	A	V	2/13/2040
2021 PO4036585985	F	3	50 KOP	SP	CCA	V	2/14/2040
2021 PO5200610324	KU	6	35 BRO	SP	CCA	V	2/15/2040
2021 PO4040685470	F	3	45 BRO	SP	CCA	V	2/16/2040
2021 PO4040685454	F	3	45 BRO	SP	CCA	V	2/17/2040
2021 PO4040485449	F	4	40 BRO	SP	CCA	V	2/18/2040
2021 PO4040485438	F	3	45 BRO	SP	CCA	V	2/19/2040
2021 PO4039285454	F	4	40 BRO	SP	CRE	V	2/20/2040
2021 PO4037885450	F	4	35 BRO	SP	A	V	2/21/2040
2021 PO4037185445	F	4	35 BRO	SP	CRE	V	2/22/2040
2021 PO4037685456	F	4	35 BRO	SP	CRE	V	2/23/2040
2021 PO4035785452	F	4	30 BRO	SP	CCA	V	2/24/2040
2021 PO4035785458	F	4	40 BRO	SP	CRE	V	2/25/2040
2021 PO4034485454	F	4	30 BRO	SP	CRE	V	2/26/2040
2021 PO4034485459	F	3	45 BRO	SP	CCA	V	2/27/2040
2021 PO4033185460	F	4	40 BRO	SP	CCA	V	2/28/2040
2021 PO4033185455	F	4	30 BRO	SP	CRE	V	2/29/2040
2021 PO4031685457	F	4	35 BRO	SP	P	V	3/1/2040
2021 PO5069035655	KU	3	45 BRO	SP	CCA	B	3/2/2040
2021 PO4034985808	F	3	40 KOP	SP	CCA	V	3/3/2040
2021 PO4034385818	F	4	40 KOP	SP	CCA	V	3/4/2040
2021 PO4034285829	F	4	40 KOP	SP	A	V	3/5/2040
2021 PO5109825899	KU	5	35 UNK	SP	CRE	V	3/6/2040
2021 PO4034485758	F	3	45 KOP	SP	CCA	V	3/7/2040
2021 PO4034085747	F	3	45 KOP	SP	CCA	V	3/8/2040
2021 PO4033485736	F	3	45 KOP	SP	CCA	V	3/9/2040
2021 PO4032985726	F	4	40 KOP	SP	A	V	3/10/2040
2021 PO4031085733	F	3	45 KOP	SP	CCA	V	3/11/2040
2021 PO5226811337	F	4	40 KOP	SP	CRE	V	3/12/2040
2021 PO5221311459	KU	7	35 KOP	SP	CCA	V	3/13/2040
2021 PO5251525910	KU	6	30 UNK	SP	CRE	B	3/14/2040
2021 PO4032485716	F	3	45 KOP	SP	CCA	V	3/15/2040
2021 PO4031885705	F	3	45 KOP	SP	CCA	V	3/16/2040
2021 PO4031385694	F	4	40 KOP	SP	A	V	3/17/2040
2021 PO4029485703	F	3	45 KOP	SP	CCA	V	3/18/2040
2021 PO5223411513	KU	6	35 KOP	SP	CCA	V	3/19/2040
2021 PO4043585524	F	3	45 BRO	SP	CCA	V	3/20/2040
2021 PO4043585517	F	4	40 BRO	SP	CRE	V	3/21/2040
2021 PO4043485505	F	4	40 BRO	SP	P	V	3/22/2040
2021 PO4043385492	F	3	45 BRO	SP	CCA	V	3/23/2040

2021 PO4043285479	F	4	40 BRO	SP	P	V	3/24/2040
2021 PO4043285466	F	4	40 BRO	SP	P	V	3/25/2040
2021 PO4043185453	F	4	40 BRO	SP	CRE	V	3/26/2040
2021 PO4043085440	F	4	40 BRO	SP	P	V	3/27/2040
2021 PO4042985427	F	3	45 BRO	SP	CCA	V	3/28/2040
2021 PO4042885414	F	3	45 BRO	SP	CCA	V	3/29/2040
2021 PO4042885407	F	3	45 BRO	SP	CCA	V	3/30/2040
2021 PO5250125819	KU	5	35 UNK	SP	CCA	V	3/31/2040
2021 PO5219311403	KU	7	35 KOP	SP	CCA	V	4/1/2040
2021 PO5154710083	F	4	40 BRO	SP	CCA	V	4/2/2040
2021 PO4030085682	F	7	30 KOP	SP	P	V	4/3/2040
2021 PO4029685670	F	3	45 KOP	SP	CCA	V	4/4/2040
2021 PO4030085667	F	6	30 KOP	SP	A	V	4/5/2040
2021 PO5273726590	KU	1	75 UNK	SP	CRE	B	4/6/2040
2021 PO5270926793	KU	1	75 UNK	SP	CRE	B	4/7/2040
2021 PO5270526859	KU	5	35 UNK	SP	CRE	B	4/8/2040
2021 PO5269326939	KU	1	80 UNK	SP	CRE	B	4/9/2040
2021 PO4029085652	F	4	40 KOP	SP	A	V	4/10/2040
2021 PO4027685653	F	3	45 KOP	SP	CCA	V	4/11/2040
2021 PO4027085653	F	4	40 KOP	SP	A	V	4/12/2040
2021 PO5268626996	KU	2	60 UNK	SP	CRE	B	4/13/2040
2021 PO5133410156	KU	4	40 BRO	SP	CCA	V	4/14/2040
2021 PO5141410091	KU	3	40 BRO	SP	CCA	V	4/15/2040
2021 PO5145310116	F	3	40 BRO	SP	P	V	4/16/2040
2021 PO5123310446	F	7	35E BRO	SP	CRE	V	4/17/2040
2021 PO5116110221	F	3	40 BRO	SP	CRE	V	4/18/2040
2021 PO5129010615	F	4	40 BRO	SP	CRE	V	4/19/2040
2021 PO5126510534	F	7	30E BRO	SP	CRE	V	4/20/2040
2021 PO5119610337	F	7	35E BRO	SP	CRE	V	4/21/2040
2021 PO5144210565	F	4	40 BRO	SP	CRE	V	4/22/2040
2021 PO5179510670	KU	2	70 BRO	ST	CRE	V	4/23/2040
2021 PO4042985617	F	4	35 BRO	SP	CRE	V	4/24/2040
2021 PO4044785616	F	4	40 BRO	SP	CRE	V	4/25/2040
2021 PO4046785620	F	4	35 BRO	SP	P	V	4/26/2040
2021 PO4046785615	F	3	45 BRO	SP	CCA	V	4/27/2040
2021 PO7622167904	LGE	4	30 BRO	SP	CCA	V	4/28/2040
2021 PO4048485619	F	4	35 BRO	SP	P	V	4/29/2040
2021 PO4048285614	F	3	45 BRO	SP	CCA	V	4/30/2040
2021 PO4049785619	F	4	35 BRO	SP	CCA	V	5/1/2040
2021 PO4049885614	F	4	40 BRO	SP	CRE	V	5/2/2040
2021 PO4050785613	F	4	40 BRO	SP	CCA	V	5/3/2040
2021 PO4051985618	F	4	35 BRO	SP	CCA	V	5/4/2040
2021 PO4051785613	F	4	40 BRO	SP	P	V	5/5/2040
2021 PO4039385984	F	4	40 KOP	SP	A	V	5/6/2040
2021 PO5255227024	KU	2	55 UNK	SP	CRE	B	5/7/2040
2021 PO5251726964	KU	2	45 UNK	SP	CRE	B	5/8/2040
2021 PO5249426995	KU	3	45 UNK	SP	CCA	V	5/9/2040
2021 PO5247927039	KU	2	50 UNK	SP	CRE	B	5/10/2040
2021 PO4040685986	F	4	25 KOP	SP	CCA	V	5/11/2040
2021 PO4040585983	F	3	45 KOP	SP	CCA	V	5/12/2040
2021 PO4030785683	F	4	40 KOP	SP	A	V	5/13/2040
2021 PO5240926161	KU	6	30 UNK	SP	CRE	B	5/14/2040
2021 PO5248226117	KU	2	55 UNK	ST	CCA	V	5/15/2040
2021 PO5173110470	KU	3	45 BRO	SP	CCA	V	5/16/2040

2021	PO5275226480	KU	5	35 UNK	SP	CCA			B	5/17/2040
2021	PO5275626455	KU	4	45 UNK	SP	CCA			V	5/18/2040
2021	PO5275926431	KU	6	30 UNK	SP	CRE			B	5/19/2040
2021	PO5266026520	KU	4	40 UNK	SP	CCA			V	5/20/2040
2021	PO4028185866	F	4	40 KOP	SP	A			V	5/21/2040
2021	PO4028885887	F	4	40 KOP	SP	A			V	5/22/2040
2021	PO4029385892	F	4	40 KOP	SP	CCA			V	5/23/2040
2021	PO4029285905	F	5	35 KOP	SP	A			V	5/24/2040
2021	PO4031585933	F	3	45 KOP	SP	CCA			V	5/25/2040
2021	PO4029985905	F	4	40 KOP	SP	CCA			V	5/26/2040
2021	PO5276626381	KU	1	75 UNK	SP	CRE			B	5/27/2040
2021	PO5271426255	KU	5	35 UNK	SP	CRE			B	5/28/2040
2021	PO4031185917	F	6	25 KOP	SP	A			V	5/29/2040
2021	PO5278626232	KU	2	45 UNK	SP	CRE			B	5/30/2040
2021	PO5279526165	KU	1	80 UNK	SP	CRE			B	5/31/2040
2021	PO4030685921	F	4	40 KOP	SP	A			V	6/1/2040
2021	PO5277026351	KU	2	50 UNK	SP	CCA			V	6/2/2040
2021	PO4034885611	LGE	4	40 KOP	SP	P			V	6/3/2040
2021	PO4035685611	F	3	45 KOP	SP	CCA			V	6/4/2040
2021	PO4036885610	LGE	4	40 KOP	SP	A			V	6/5/2040
2021	PO4038085609	LGE	4	40 KOP	SP	A			V	6/6/2040
2021	PO4039285609	LGE	4	40 KOP	SP	CCA			V	6/7/2040
2021	PO4040385608	F	4	40 KOP	SP	A			V	6/8/2040
2021	PO4041385608	F	4	40 KOP	SP	A			V	6/9/2040
2021	PO4041985607	F	4	40 KOP	SP	A			V	6/10/2040
2021	PO5509914665	KU	2	50 BRO	SP	CCA			V	6/11/2040
2021	PO1843590964	KU	3	45 BRN	SP	CCA			V	6/12/2040
2021	PO7853669039	KU	4	45 ACE	SP	CRE	ED,ID,IP		BD	6/13/2040
2021	PO7827168942	KU	4	45 ACE	SP	CRE	ED,ID		BD	6/14/2040
2021	PO4004183397	F	4	40 BRO	SP	CRE			V	6/15/2040
2021	PO4003383386	F	4	40 BRO	SP	CRE			V	6/16/2040
2021	PO1827889741	KU	3	45 BRO	SP	CCA			V	6/17/2040
2021	PO1813890041	KU	5	35 BRO	SP	CCA			V	6/18/2040
2021	PO5539326274	KU	2	70 UNK	SP	CRE			B	6/19/2040
2021	PO5541026201	KU	4	40 UNK	SP	CCA			V	6/20/2040
2021	PO5541526176	KU	5	35 UNK	SP	CRE			B	6/21/2040
2021	PO5537126293	F	4	40 UNK	SP	CRE			V	6/22/2040
2021	PO4002183379	F	4	40 BRO	SP	CRE			V	6/23/2040
2021	PO3997183371	LGE	4	35 BRO	SP	CRE	ED,ID,IP		TD	6/24/2040
2021	PO3996483374	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TX	RR 6/25/2040
2021	PO3996983379	LGE	4	35 BRO	SP	CRE	ED,ID,IP		TD	6/26/2040
2021	PO5543826064	KU	1	50 UNK	SP	CRE			B	6/27/2040
2021	PO5543226098	KU	5	35 UNK	SP	CRE			V	6/28/2040
2021	PO5547826214	KU	2	50 UNK	SP	CCA			V	6/29/2040
2021	PO1859491264	KU	3	45 BRN	SP	CCA			V	6/30/2040
2021	PO1874391275	KU	3	45 BRN	SP	CCA			V	7/1/2040
2021	PO5545126004	KU	3	50 UNK	SP	CRE			B	7/2/2040
2021	PO1836291406	KU	4	40 BRN	SP	CCA			V	7/3/2040
2021	PO1835391898	KU	4	40 KOP	SP	CRE	ID		TD	7/4/2040
2021	PO5549525797	KU	3	50 UNK	SP	CRE			B	7/5/2040
2021	PO5547725878	KU	1	50 UNK	SP	CRE			B	7/6/2040
2021	PO5556825803	KU	2	50 UNK	SP	CCA			V	7/7/2040
2021	PO5552825985	KU	3	45 UNK	SP	CCA			V	7/8/2040
2021	PO5550626084	KU	3	45 UNK	SP	CCA			V	7/9/2040



2021 PO4058684399	LGE	3	45 BRO	SP	CCA		V	7/10/2040	
2021 PO457784376-A	KU	3	45 BRO	SP	CCA		V	7/11/2040	
2021 PO4057784376	LGE	3	45 BRO	SP	CCA		V	7/12/2040	
2021 PO4056584378	LGE	3	45 BRO	SP	CCA		V	7/13/2040	
2021 PO5560725639	F	4	45 UNK	SP	CRE		V	7/14/2040	
2021 PO5511226393A	KU	2	70 UNK	SP	CRE		B	7/15/2040	
2021 PO3998683372	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	7/16/2040	
2021 PO3999683375	F	4	40 BRO	SP	CRE		V	7/17/2040	
2021 PO5558725719	F	3	45 UNK	SP	CRE		V	7/18/2040	
2021 PO5553325625	KU	5	35 UNK	SP	CRE		B	7/19/2040	
2021 PO4000583394	F	4	40 BRO	SP	A		V	7/20/2040	
2021 PO4000983376	F	4	40 BRO	SP	CRE		V	7/21/2040	
2021 PO4001183360	F	4	40 BRO	SP	CRE		V	7/22/2040	
2021 PO5561925582	KU	2	50 UNK	SP	CCA		V	7/23/2040	
2021 PO5563825496	KU	2	50 UNK	SP	CCA		V	7/24/2040	
2021 PO5556025479	KU	2	95 UNK	SP	CRE		B	7/25/2040	
2021 PO4000283412	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	7/26/2040	
2021 PO3999883427	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	7/27/2040	
2021 PO5565825404	F	4	45 UNK	SP	CRE		V	7/28/2040	
2021 PO5565825404A	KU	3	50 UNK	SP	CCA		V	7/29/2040	
2021 PO5568825265	KU	2	50 UNK	SP	CCA		V	7/30/2040	
2021 PO1846589840	KU	3	45 BRO	SP	CCA		V	7/31/2040	
2021 PO1827890041	KU	3	45 BRO	SP	CCA		V	8/1/2040	
2021 PO1764090584	KU	4	40 BRO	SP	CRE	ID	TD	8/2/2040	
2021 PO5563225205	KU	2	95 UNK	SP	CRE		B	8/3/2040	
2021 PO5562325190	KU	3	45 UNK	SP	CCA		V	8/4/2040	
2021 PO5570425189	KU	2	50 UNK	SP	CCA		V	8/5/2040	
2021 PO1827690323	KU	3	45 BRO	SP	CCA		V	8/6/2040	
2021 PO5571225148	KU	2	50 UNK	SP	CCA		V	8/7/2040	
2021 PO5573925154	KU	4	45 UNK	SP	CCA		V	8/8/2040	
2021 PO5604025195	KU	3	45 UNK	SP	CCA		V	8/9/2040	
2021 PO5603425221	KU	3	45 UNK	SP	CCA		V	8/10/2040	
2021 PO5592725168	KU	3	45 UNK	SP	CCA		V	8/11/2040	
2021 PO5591925197	KU	3	45 UNK	SP	CCA		V	8/12/2040	
2021 PO3998983439	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	8/13/2040	
2021 PO5612125242	KU	3	45 UNK	SP	CCA		V	8/14/2040	
2021 PO5615925284	KU	3	45 UNK	SP	CCA		V	8/15/2040	
2021 PO5652425434	KU	3	45 UNK	SP	CRE		B	8/16/2040	
2021 PO3997983450	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/17/2040	
2021 PO1878587508	KU	6	30 BRO	SP	CRE		V	8/18/2040	
2021 PO1819888763	KU	4	45 BRO	SP	CCA		V	8/19/2040	
2021 PO1862088677	KU	6	30 BRO	SP	CRE	ID	TD	8/20/2040	
2021 PO3996983429	LGE	3	45 BRO	SP	CCA		V	8/21/2040	
2021 PO3995883418	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	8/22/2040	
2021 PO3994983406	LGE	4	40 BRO	SP	CCA		V	8/23/2040	
2021 PO3993883392	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR	8/24/2040
2021 PO3993283380	LGE	4	35 BRO	SP	CRE	ED,ID	TD	8/25/2040	
2021 PO1835986875	KU	4	50 KOP	SP	CRE	ID	TD	8/26/2040	
2021 PO1861288551	KU	4	40 BRO	SP	CCA		V	8/27/2040	
2021 PO1853388086	KU	4	45 INP	SP	CRE	ID	TD	8/28/2040	
2021 PO3992683368	LGE	4	35 BRO	SP	CRE	ED,ID	TD	8/29/2040	
2021 PO3991983351	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	8/30/2040	
2021 PO3992483350	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	8/31/2040
2021 PO3991883337	LGE	4	30 BRO	SP	CRE	ID,RB	X	RP1	9/1/2040

2021 PO1885887503	KU	3	45 BRO	SP	CCA			V		9/2/2040
2021 PO3991283337	LGE	4	40 BRO	SP	CCA			V		9/3/2040
2021 PO3990783322	LGE	4	40 BRO	SP	A		ED,ID	TD		9/4/2040
2021 PO3989683327	LGE	4	30 BRO	SP	A		ED,ID	TD		9/5/2040
2021 PO3990183307	LGE	4	40 BRO	SP	A		ID	BD		9/6/2040
2021 PO5634326877	KU	1	65 UNK	SP	CRE			B		9/7/2040
2021 PO4059484446	LGE	3	45 BRO	SP	CCA			V		9/8/2040
2021 PO4059084417	LGE	3	45 BRO	SP	CCA			V		9/9/2040
2021 PO4057984427	LGE	3	45 BRO	SP	CCA			V		9/10/2040
2021 PO4057684424	LGE	4	30 BRO	SP	CCA			V		9/11/2040
2021 PO5642726702	KU	3	55 UNK	SP	CCA			V		9/12/2040
2021 PO5639626699	KU	5	35 UNK	SP	CCA			V		9/13/2040
2021 PO5628926707	KU	5	35 UNK	SP	CCA			V		9/14/2040
2021 PO5645826518	KU	6	30 UNK	SP	CRE			B		9/15/2040
2021 PO5644926627	KU	6	30 UNK	SP	CRE			B		9/16/2040
2021 PO4059484439	LGE	4	30 BRO	SP	CRE		ED,EP,ID,RB	TX	RR	9/17/2040
2021 PO4058784446	LGE	4	30 BRO	SP	A		ED,ID	BD		9/18/2040
2021 PO4056884435	LGE	3	45 BRO	SP	CCA			V		9/19/2040
2021 PO5658726681	KU	5	35 UNK	SP	CRE		ID,RB	BX	PX	9/20/2040
2021 PO1813891250	KU	5	35 BRN	SP	CRE			V		9/21/2040
2021 PO1904091994	KU	4	45 BRO	SP	CCA			V		9/22/2040
2021 PO5698826686	KU	6	30 UNK	SP	CRE			T		9/23/2040
2021 PO5706326785	KU	4	35 UNK	SP	CCA			V		9/24/2040
2021 PO4005083409	F	4	40 BRO	SP	CRE			V		9/25/2040
2021 PO7763268700	KU	3	50 ACE	SP	CRE		ED,ID	TD		9/26/2040
2021 PO1881891599	KU	3	45 BRO	SP	CCA			V		9/27/2040
2021 PO7811668876	KU	3	45 ACE	SP	CRE		ED,ID	BD		9/28/2040
2021 PO7789368786	KU	3	50 ACE	SP	CRE		ED,ID	BD		9/29/2040
2021 PO7801868839	KU	4	45 ACE	SP	CCA			V		9/30/2040
2021 PO4052484405	LGE	4	35 BRO	SP	P		ED,ID	TD		10/1/2040
2021 PO4052384399	LGE	4	35 BRO	SP	P		ED,ID	TD		10/2/2040
2021 PO4052884390	LGE	4	35 BRO	SP	P		ED,ID	TD		10/3/2040
2021 PO4054084382	LGE	4	40 BRO	SP	CRE		ED,ID	TD		10/4/2040
2021 PO4055284380	LGE	4	40 BRO	SP	CCA			V		10/5/2040
2021 PO4056184391	LGE	3	45 BRO	SP	CCA			V		10/6/2040
2021 PO1857491064	KU	6	30 BRN	SP	CCA			V		10/7/2040
2021 PO9361097879	F	5	35 KOP	SP	P			V		10/8/2040
2021 PO9485897481	F	5	35 OTH	SP	P			V		10/9/2040
2021 PO9470298059	F	3	60 BRO	SP	CCA			V		10/10/2040
2021 PO9346497923	F	5	35 KOP	SP	P			V		10/11/2040
2021 PO3988783404	LGE	4	40 BRO	SP	CRE		ED,ID,IP	TD		10/12/2040
2021 PO1900692477	KU	4	40 BRN	SP	CRE		ID	TD		10/13/2040
2021 PO1831493109	KU	4	40 BRN	SP	CRE		ID	TD		10/14/2040
2021 PO5613527408	KU	4	40 UNK	SP	CRE			B		10/15/2040
2021 PO5611127482	KU	4	40 UNK	SP	CRE			B		10/16/2040
2021 PO5603827463	KU	6	30 UNK	SP	CRE			B		10/17/2040
2021 PO4061384415	LGE	4	35 BRO	SP	P		ED,ID	TD		10/18/2040
2021 PO4061884420	LGE	4	30 BRO	SP	P		ED,ID	TD		10/19/2040
2021 PO4061484426	LGE	4	40 BRO	SP	P		ED,ID	TD		10/20/2040
2021 PO5611327222	KU	4	40 UNK	SP	CRE			T		10/21/2040
2021 PO5616627054	KU	4	40 UNK	SP	CRE			B		10/22/2040
2021 PO5619926967	KU	4	40 UNK	SP	CRE			B		10/23/2040
2021 PO5627026886	KU	5	35 UNK	SP	CCA			T		10/24/2040
2021 PO5650426683	KU	5	35 UNK	SP	CRE		ID,RB	BX	RP2	10/25/2040

2021 PO7776468746	KU	3	50 ACE	SP	CCA		V	10/26/2040
2021 PO5660726760	KU	5	35 UNK	SP	CCA		V	10/27/2040
2021 PO4055984436	LGE	4	35 BRO	SP	P	ED,ID	TD	10/28/2040
2021 PO4055184429	LGE	3	45 BRO	SP	CCA		V	10/29/2040
2021 PO4054184420	LGE	3	45 BRO	SP	CCA		V	10/30/2040
2021 PO4053184412	LGE	3	45 BRO	SP	CCA		V	10/31/2040
2021 PO1825992879	KU	4	40 BRN	SP	CRE	ID	TD	11/1/2040
2021 PO4001883450	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	11/2/2040
2021 PO4005983422	F	4	40 BRO	SP	A		V	11/3/2040
2021 PO5670926678	KU	2	100 UNK	ST	CCA		V	11/4/2040
2021 PO5675726675	KU	2	55 UNK	SP	CCA		V	11/5/2040
2021 PO5680626691	KU	4	40 UNK	SP	CCA		V	11/6/2040
2021 PO5687926690	KU	6	35 UNK	SP	CRE		T	11/7/2040
2021 PO5693726687	KU	5	30 UNK	SP	CRE		B	11/8/2040
2021 PO1809193244	KU	4	45 BRN	SP	CRE	ID	BD	11/9/2040
2021 PO1820591009	KU	5	35 BRN	SP	CRE		V	11/10/2040
2021 PO3285482466	KU	4	40 BRO	SP	S		V	11/11/2040
2021 PO3268982547	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/12/2040
2021 PO3294682398	KU	3	45 BRO	SP	S		V	11/13/2040
2021 PO3317982796	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/14/2040
2021 PO7762968274	KU	5	35 ACE	SP	CCA		V	11/15/2040
2021 PO7764368326	KU	4	40 ACE	SP	CCA		V	11/16/2040
2021 PO7759868224	KU	4	40 ACE	SP	CRE	ED,ID	BD	11/17/2040
2021 PO3983083781	F	3	45 BRO	SP	CRE		V	11/18/2040
2021 PO3982483782	F	4	30 BRO	SP	CRE		V	11/19/2040
2021 PO4053384353	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	11/20/2040
2021 PO4053084343	LGE	3	45 BRO	SP	CCA		V	11/21/2040
2021 PO4053384335	LGE	4	40 BRO	UN	CRE		V	11/22/2040
2021 PO4051884354	LGE	3	45 BRO	SP	CCA		V	11/23/2040
2021 PO3982983771	LGE	4	40 BRO	SP	CRE		V	11/24/2040
2021 PO3981783723	F	4	40 BRO	SP	CCA		V	11/25/2040
2021 PO4008783775	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	11/26/2040
2021 PO4062784321	LGE	3	45 BRO	SP	P	ED,ID	BD	11/27/2040
2021 PO4061784329	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	11/28/2040
2021 PO4060784338	LGE	4	40 BRO	SP	P	ED,ID	TD	11/29/2040
2021 PO4059884344	LGE	4	40 BRO	SP	P	ED,ID	TD	11/30/2040
2021 PO4058684347	LGE	4	40 BRO	SP	P	ED,ID	TD	12/1/2040
2021 PO4057184349	LGE	4	40 BRO	SP	P	ED,ID	TD	12/2/2040
2021 PO7735969119	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	12/3/2040
2021 PO7740468975	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX PX	12/4/2040
2021 PO3345682981	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/5/2040
2021 PO3331383099	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/6/2040
2021 PO7747368864	KU	4	40 ACE	SP	CRE	ED,ID	TD	12/7/2040
2021 PO1889194839	KU	4	45 BRN	SP	CRE	ID	TD	12/8/2040
2021 PO7745168838	KU	5	35 ACE	SP	CCA		V	12/9/2040
2021 PO4064484374	LGE	4	40 BRO	SP	CCA		V	12/10/2040
2021 PO4065184379	LGE	3	45 BRO	SP	CCA		V	12/11/2040
2021 PO4062484360	LGE	4	40 BRO	SP	P	ED,ID	BD	12/12/2040
2021 PO1936092799	KU	3	45 UNK	SP	CRE	ID	TD	12/13/2040
2021 PO1810894702	KU	4	45 UNK	SP	CRE	ID	TD	12/14/2040
2021 PO4008583451	F	3	45 BRO	SP	A		V	12/15/2040
2021 PO4008983452	F	4	30 BRO	SP	A		V	12/16/2040
2021 PO4009883458	F	4	40 BRO	SP	CRE		V	12/17/2040
2021 PO4010583457	LGE	4	35 BRO	SP	A	ED,ID	TD	12/18/2040

2021 PO7837768176c	KU	3	45 ACE	SP	CRE	ED,ID	BD		12/19/2040
2021 PO7837768176b	KU	3	45 ACE	SP	CRE	ED,ID	BD		12/20/2040
2021 PO7837768176a	KU	3	55 ACE	SP	CRE	ED,ID	BD		12/21/2040
2021 PO7837768176	KU	3	45 ACE	SP	CRE	ED,ID	BD		12/22/2040
2021 PO5667427521	KU	4	40 BRN	SP	CRE		B		12/23/2040
2021 PO5663827448	KU	4	40 BRN	SP	CRE		B		12/24/2040
2021 PO5660427377	KU	4	40 BRN	SP	CRE		B		12/25/2040
2021 PO4007483443	LGE	4	30 BRO	SP	A	ED,ID	TD		12/26/2040
2021 PO4006983434	F	4	40 BRO	SP	CRE		V		12/27/2040
2021 PO4006683438	F	4	40 BRO	SP	CRE		V		12/28/2040
2021 PO7894168331	KU	3	55 ACE	SP	CRE	ED,ID	BD		12/29/2040
2021 PO7892168231	KU	3	55 ACE	SP	CRE	ED,ID	BD		12/30/2040
2021 PO7890868257	KU	3	55 ACE	SP	CRE	ED,ID	BD		12/31/2040
2021 PO5643627311	KU	6	30 UNK	SP	CRE		B		1/1/2041
2021 PO5654527256	KU	4	40 UNK	SP	CRE		B		1/2/2041
2021 PO5652027205	KU	4	40 UNK	SP	CRE		B		1/3/2041
2021 PO4002583504	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		1/4/2041
2021 PO5650127168	KU	4	35 UNK	SP	CCA		B		1/5/2041
2021 PO5645227073	KU	5	35 UNK	SP	CRE		B		1/6/2041
2021 PO4001583509	LGE	4	40 BRO	SP	A	ED,ID	TD		1/7/2041
2021 PO1776994461A	KU	3	45 BRO	SP	CCA		V		1/8/2041
2021 PO1776994461	KU	3	45 BRO	SP	CCA		V		1/9/2041
2021 PO1759794328	KU	4	45 KOP	SP	CCA		T		1/10/2041
2021 PO4000783519	LGE	3	45 BRO	SP	A	ID	BD		1/11/2041
2021 PO4061684372	LGE	4	40 BRO	SP	CCA		V		1/12/2041
2021 PO4060384375	LGE	4	35 BRO	SP	P	ED,EP,ID,IP,RB	TX	RR	1/13/2041
2021 PO4059584361	LGE	4	35 BRO	SP	P	ED,ID	TD		1/14/2041
2021 PO4062284386	LGE	3	45 BRO	SP	CCA		V		1/15/2041
2021 PO4063184395	LGE	3	45 BRO	SP	CCA		V		1/16/2041
2021 PO7871968172	KU	2	55 ACE	SP	CRE	ED,ID	TD		1/17/2041
2021 PO7852968118	KU	1	50 ACE	SP	CRE		V		1/18/2041
2021 PO3181681503	F	4	40 BRO	SP	CRE		V		1/19/2041
2021 PO3173081385	KU	4	45 BRO	SP	CRE	ED,ID	TD		1/20/2041
2021 PO7591268818a	KU	3	45 ACE	SP	CCA		V		1/21/2041
2021 PO7591268818	KU	3	45 ACE	SP	CRE	ED,ID	BD		1/22/2041
2021 PO7586268803	KU	3	50 ACE	SP	P	ED,ID	TD		1/23/2041
2021 PO4000583471	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		1/24/2041
2021 PO4001583460	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		1/25/2041
2021 PO4002883438	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		1/26/2041
2021 PO4004083427	F	4	40 BRO	SP	CRE		V		1/27/2041
2021 PO7772268084	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/28/2041
2021 PO5690427443	KU	4	40 UNK	SP	CRE	RB	BX	RP3	1/29/2041
2021 PO7753768662	KU	3	55 ACE	SP	CRE	ED,ID	TD		1/30/2041
2021 PO1929394871	KU	4	45 BRN	SP	CRE	ID	TD		1/31/2041
2021 PO4056784335	LGE	4	40 BRO	SP	CCA	ED,ID	TD		2/1/2041
2021 PO4057484324	LGE	4	40 BRO	SP	P	ED,ID	TD		2/2/2041
2021 PO4056784325	LGE	4	30 BRO	SP	CCA	ED,ID	BD		2/3/2041
2021 PO4055984351	LGE	3	45 BRO	SP	CCA		V		2/4/2041
2021 PO4054584354	LGE	3	45 BRO	SP	CCA		V		2/5/2041
2021 PO7749668678	KU	5	35 ACE	SP	CCA		V		2/6/2041
2021 PO5303425852	KU	5	45 BRN	SP	CRE		B		2/7/2041
2021 PO7758268524	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	2/8/2041
2021 PO7754068555	KU	5	35 ACE	SP	CRE	ED,ID	TD		2/9/2041
2021 PO7757968423	KU	5	35 ACE	SP	CCA		V		2/10/2041

2021	PO5311225980	KU	6	30 BRN	SP	CCA		V	2/11/2041
2021	PO5308625857	KU	4	40 BRN	SP	CRE		B	2/12/2041
2021	PO5319225807	KU	3	45 BRN	SP	CRE		B	2/13/2041
2021	PO3988786369	LGE	4	40 ACE	SP	P	ED,ID,RB	BX RP1	2/14/2041
2021	PO3989486366	LGE	3	50 ACE	SP	CRE	ID	BD	2/15/2041
2021	PO3989686384	LGE	4	30 ACE	SP	P	ED,HH,ID,RB	BX PX	2/16/2041
2021	PO3883485490	LGE	3	60 ACE	SP	P	ED,ID	TD	2/17/2041
2021	PO3882085492	LGE	3	50 ACE	SP	P	ED,ID	BD	2/18/2041
2021	PO9826476507	KU	2	55 OTH	SP	CRE	ID,IP	TD	2/19/2041
2021	PO4050384904	LGE	5	35 ACE	SP	A	ED,ID	TD	2/20/2041
2021	PO4054084914	F	4	40 ACE	SP	CCA		V	2/21/2041
2021	PO4051284926	F	4	45 ACE	SP	CRE		V	2/22/2041
2021	PO4050984952	LGE	4	45 ACE	SP	A	ED,ID	BD	2/23/2041
2021	PO5256656818	KU	4	40 BRN	SP	CCA		V	2/24/2041
2021	PO5239956718	KU	4	40 BRN	SP	CRE	ID	BD	2/25/2041
2021	PO5236056695	KU	2	40 BRN	SP	CRE	ID	BD	2/26/2041
2021	PO5241856604	KU	6	30 BRN	SP	CRE	ID,IP	TD	2/27/2041
2021	PO3989986386	LGE	4	30 ACE	SP	A	ID	TD	2/28/2041
2021	PO3990286380	F	2	55 ACE	SP	CRE		V	3/1/2041
2021	PO7684062054	LGE	3	50 BRO	SP	CCA		V	3/2/2041
2021	PO4051285020	LGE	5	25 BRO	SP	CRE	ED,ID	TD	3/3/2041
2021	PO4732838581	KU	3	50 BRO	SP	CRE		B	3/4/2041
2021	PO5604757035	KU	5	35 BRN	SP	CCA		V	3/5/2041
2021	PO9750764949	KU	3	45 OTH	SP	CRE		V	3/6/2041
2021	PO4066285198	F	4	40 BRO	SP	CRE		V	3/7/2041
2021	PO5063739730A	KU	2	50 BRN	SP	CCA		V	3/8/2041
2021	PO6405300521	F	3	45 OTH	SP	P		V	3/9/2041
2021	PO6441200455	F	4	40 UNK	SP	CRE		V	3/10/2041
2021	PO6392200594	F	3	45 UNK	SP	CCA		V	3/11/2041
2021	PO4097086265	F	4	40 BRO	SP	CCA		V	3/12/2041
2021	PO4097586261	F	4	30 BRO	SP	CRE		V	3/13/2041
2021	PO4069286133	F	4	40 BRO	SP	CRE		V	3/14/2041
2021	PO4067986134	F	4	40 BRO	SP	CRE		V	3/15/2041
2021	PO4066686134	F	4	40 BRO	SP	CRE		V	3/16/2041
2021	PO4070586125	LGE	4	30 BRO	SP	CRE		V	3/17/2041
2021	PO4070586133	F	4	40 BRO	SP	CRE		V	3/18/2041
2021	PO4072486135	F	4	45 BRO	SP	CRE		V	3/19/2041
2021	PO4072586152	F	2	45 BRO	SP	CCA		V	3/20/2041
2021	PO4074086134	F	4	40 BRO	SP	CRE		V	3/21/2041
2021	PO4075386132	F	4	40 BRO	SP	CRE		V	3/22/2041
2021	PO4076586131	F	4	40 BRO	SP	CRE		V	3/23/2041
2021	PO4077886130	F	4	40 BRO	SP	CRE		V	3/24/2041
2021	PO4079286129	F	4	40 BRO	SP	CRE		V	3/25/2041
2021	PO4080586128	F	4	40 BRO	SP	CRE		V	3/26/2041
2021	PO4081886127	F	4	40 BRO	SP	CRE		V	3/27/2041
2021	PO4083286125	F	4	40 BRO	SP	CRE		V	3/28/2041
2021	PO4084586124	F	4	40 BRO	SP	CRE		V	3/29/2041
2021	PO4085886123	F	4	40 BRO	SP	CRE		V	3/30/2041
2021	PO4085886126	F	UNK	25 BRO	SP	CRE		V	3/31/2041
2021	PO4088486158	F	4	40 BRO	SP	CRE		V	4/1/2041
2021	PO4086086156	F	4	40 BRO	SP	CRE		V	4/2/2041
2021	PO4086086147	F	UNK	25 BRO	SP	CRE		V	4/3/2041
2021	PO4084586157	F	4	40 BRO	SP	CRE		V	4/4/2041
2021	PO4083186159	F	4	40 BRO	SP	CRE		V	4/5/2041

2021	PO5347335790	KU	2	50 BRN	SP	CCA			V	4/6/2041
2021	PO4081686160	F	4	40 BRO	SP	CRE			V	4/7/2041
2021	PO4080286161	F	4	40 BRO	SP	CRE			V	4/8/2041
2021	PO4078786162	F	4	40 BRO	SP	CRE			V	4/9/2041
2021	PO4078086163	F	4	40 BRO	SP	CRE			V	4/10/2041
2021	PO4076886164	F	4	40 BRO	SP	CRE			V	4/11/2041
2021	PO4074286166	F	4	40 BRO	SP	CRE			V	4/12/2041
2021	PO4075486165	F	4	40 BRO	SP	CRE			V	4/13/2041
2021	PO4014786225	LGE	4	35 ACE	SP	CCA			V	4/14/2041
2021	PO4062486207	LGE	4	40 BRO	SP	CRE			V	4/15/2041
2021	PO4062086207	LGE	4	40 BRO	SP	CRE			V	4/16/2041
2021	PO4062386193	F	4	40 BRO	SP	CRE			V	4/17/2041
2021	PO4062286180	F	4	40 BRO	SP	CRE			V	4/18/2041
2021	PO4061286207	F	4	40 BRO	SP	CRE	ED,ID	BX	RP3	4/19/2041
2021	PO4063686194	F	4	40 BRO	SP	CRE			V	4/20/2041
2021	PO4064986193	F	4	40 BRO	SP	CCA			V	4/21/2041
2021	PO4066286192	F	4	40 BRO	SP	CRE			V	4/22/2041
2021	PO4066986192	F	4	40 BRO	SP	CRE			V	4/23/2041
2021	PO4068386191	F	4	40 BRO	SP	CRE			V	4/24/2041
2021	PO4069586191	F	4	40 BRO	SP	CRE			V	4/25/2041
2021	PO4070986190	F	4	40 BRO	SP	CRE			V	4/26/2041
2021	PO4071086199	F	UNK	25 BRO	SP	CRE			V	4/27/2041
2021	PO4072786183	F	4	40 BRO	SP	CRE			V	4/28/2041
2021	PO4072686166	F	4	40 BRO	SP	CRE			V	4/29/2041
2021	PO4070786153	F	5	25 BRO	SP	CCA			V	4/30/2041
2021	PO4070886163	F	4	40 BRO	SP	CRE			V	5/1/2041
2021	PO4069386163	F	4	40 BRO	SP	CRE			V	5/2/2041
2021	PO4068086164	F	4	40 BRO	SP	CRE			V	5/3/2041
2021	PO4066886165	F	4	40 BRO	SP	CRE			V	5/4/2041
2021	PO4066086165	F	4	40 BRO	SP	CRE			V	5/5/2041
2021	PO4063486165	F	4	40 BRO	SP	CRE			V	5/6/2041
2021	PO4064786164	F	4	40 BRO	SP	CRE			V	5/7/2041
2021	PO5462135919	KU	5	35 BRO	SP	CRE	ID	BD		5/8/2041
2021	PO7251773618	LGE	4	30 ACE	SP	CCA			V	5/9/2041
2021	PO4011586201	LGE	4	45 ACE	SP	CCA			V	5/10/2041
2021	PO7257973713	LGE	3	45 ACE	SP	CCA			V	5/11/2041
2021	PO7268473732	LGE	4	30 ACE	SP	CCA			V	5/12/2041
2021	PO4013186213	LGE	4	35 ACE	SP	CCA			V	5/13/2041
2021	PO5454035664	KU	5	35 BRO	SP	CRE	ID	BD		5/14/2041
2021	PO4062286167	F	4	40 BRO	SP	CRE			V	5/15/2041
2021	PO4062086153	F	4	40 BRO	SP	CRE			V	5/16/2041
2021	PO4061986141	F	4	40 BRO	SP	CRE			V	5/17/2041
2021	PO4063286140	F	4	40 BRO	SP	CRE			V	5/18/2041
2021	PO4064086140	F	4	40 BRO	SP	CRE			V	5/19/2041
2021	PO4049584790	LGE	4	40 ACE	SP	CCA			V	5/20/2041
2021	PO4050484785	LGE	4	30 ACE	SP	CRE			V	5/21/2041
2021	PO4050984783	LGE	4	30 ACE	SP	CRE			V	5/22/2041
2021	PO4050584780	LGE	3	45 ACE	SP	CCA			V	5/23/2041
2021	PO4051884775	LGE	4	40 ACE	SP	CRE			V	5/24/2041
2021	PO4048184845	F	3	45 ACE	SP	CCA			V	5/25/2041
2021	PO4047684832	F	4	40 ACE	SP	P			V	5/26/2041
2021	PO7856562409	LGE	4	40 ACE	SP	CCA			V	5/27/2041
2021	PO5354836443	KU	2	50 BRN	SP	CCA			V	5/28/2041
2021	PO5356336559	KU	2	50 BRN	SP	CCA			V	5/29/2041

2021	PO5370536633	KU	4	40 BRN	SP	CRE		V	5/30/2041
2021	PO5358136712	KU	2	50 BRN	SP	CCA		V	5/31/2041
2021	PO5359836818	KU	2	50 BRN	SP	CCA		V	6/1/2041
2021	PO5362336955	KU	2	60 BRN	SP	CCA		V	6/2/2041
2021	PO5651756637	KU	3	45 BRN	SP	CRE	ID	BD	6/3/2041
2021	PO4049284732	LGE	4	35 ACE	SP	A		V	6/4/2041
2021	PO4052484698	LGE	4	40 ACE	SP	CRE		V	6/5/2041
2021	PO4051084703	LGE	4	40 ACE	SP	CRE		V	6/6/2041
2021	PO4062385173	LGE	4	35 BRO	SP	CRE	ED,ID	TD	6/7/2041
2021	PO4063485176	LGE	4	35 BRO	SP	CRE	ED,ID	BD	6/8/2041
2021	PO4064185172	LGE	4	35 BRO	SP	CRE	ED,ID	TD	6/9/2041
2021	PO7790063460	LGE	3	45 BRO	SP	CRE	ED,EP,HH,ID,IP,MD	X	RP3 6/10/2041
2021	PO4049684709	LGE	4	40 ACE	SP	CRE		V	6/11/2041
2021	PO4048184717	LGE	4	40 ACE	SP	CRE		V	6/12/2041
2021	PO5003838331	KU	4	40 UNK	SP	CRE	ID	BD	6/13/2041
2021	PO4047884725	LGE	4	40 ACE	SP	CCA		V	6/14/2041
2021	PO4047484741	LGE	4	35 ACE	SP	CRE		V	6/15/2041
2021	PO4047984752	LGE	4	35 ACE	SP	CRE		V	6/16/2041
2021	PO4047584756	LGE	3	45 ACE	SP	P		V	6/17/2041
2021	PO4046384762	LGE	4	35 ACE	SP	CRE	ED,ID	V	6/18/2041
2021	PO4046284760	LGE	3	45 ACE	SP	CCA		V	6/19/2041
2021	PO4045784759	LGE	2	50 ACE	SP	P		V	6/20/2041
2021	PO5008338345	KU	3	45 BRO	SP	CCA		V	6/21/2041
2021	PO5009638471	KU	3	45 ACW	SP	CRE	ED,ID	TD	6/22/2041
2021	PO5021538759	KU	3	45 UNK	SP	CRE	ID	TD	6/23/2041
2021	PO5032339023	KU	2	50 BRO	SP	CCA		V	6/24/2041
2021	PO4045484750	LGE	3	45 ACE	SP	CRE	ED,ID	BD	6/25/2041
2021	PO4044884734	LGE	1	55 ACE	SP	CCA		V	6/26/2041
2021	PO5628356761	KU	3	45 BRN	SP	CRE	ID	BD	6/27/2041
2021	PO5610656854	KU	3	45 BRN	SP	CRE	ID	BD	6/28/2041
2021	PO5475457249	KU	4	40 BRN	SP	CRE	ID	TD	6/29/2041
2021	PO4045684710	LGE	4	35 ACE	SP	CRE		V	6/30/2041
2021	PO4044684713	LGE	4	35 ACE	SP	CRE		V	7/1/2041
2021	PO4047984711	LGE	3	45 ACE	SP	CRE	ED,ID	BD	7/2/2041
2021	PO4046284724	LGE	3	50 ACE	SP	CRE	ED,ID,IP	BD	7/3/2041
2021	PO4064485172	F	3	45 BRO	SP	CCA		V	7/4/2041
2021	PO5491557520	KU	4	40 BRN	SP	CRE	ID	BD	7/5/2041
2021	PO5240055811	KU	4	40 BRN	SP	CRE	ID	BD	7/6/2041
2021	PO5255755493	KU	4	40 BRN	SP	CRE	ID	BD	7/7/2041
2021	PO7319374471	LGE	4	35 ACE	SP	CCA		V	7/8/2041
2021	PO4019086278	LGE	4	35 ACE	SP	CCA		V	7/9/2041
2021	PO4019286285	LGE	4	45 ACE	SP	CCA		V	7/10/2041
2021	PO3984286343	F	3	45 ACE	SP	CCA		V	7/11/2041
2021	PO3985386337	F	4	40 ACE	SP	CRE		V	7/12/2041
2021	PO3984085255	F	5	35 ACE	SP	P		V	7/13/2041
2021	PO4064786137	F	4	40 BRO	SP	CRE		V	7/14/2041
2021	PO7239073435	LGE	4	30 ACE	SP	CCA		V	7/15/2041
2021	PO4009886190	LGE	4	35 ACE	SP	CCA		V	7/16/2041
2021	PO5498635612	KU	5	35 BRO	SP	CRE	ID	BD	7/17/2041
2021	PO5463035654	KU	5	35 BRO	SP	CRE	ID	BD	7/18/2041
2021	PO5477435637	KU	4	40 BRO	SP	CCA		V	7/19/2041
2021	PO4046584661	LGE	4	35 OTH	SP	CCA		V	7/20/2041
2021	PO4011886226	LGE	3	45 ACE	SP	CCA		V	7/21/2041
2021	PO5507635551	KU	5	35 BRO	SP	CRE	ID	TD	7/22/2041

2021 PO4010986231	LGE	2	50 ACE	SP	CCA		V	7/23/2041
2021 PO4054484600	LGE	4	40 ACE	SP	P	ED,ID	TD	7/24/2041
2021 PO4053784619	LGE	3	50 ACE	SP	CCA		V	7/25/2041
2021 PO4048684709	LGE	4	35 ACE	SP	CRE	ED,ID	TD	7/26/2041
2021 PO4049084703	LGE	3	50 ACE	SP	CRE	ED,ID	TD	7/27/2041
2021 PO4050684691	LGE	3	50 ACE	SP	CRE	ED,ID	TD	7/28/2041
2021 PO7228673949	LGE	4	30 ACE	SP	CCA		V	7/29/2041
2021 PO4009886228	LGE	3	45 ACE	SP	CCA		V	7/30/2041
2021 PO4000185970	F	4	40 ACE	SP	P		V	7/31/2041
2021 PO4008086206	LGE	4	35 ACE	SP	CCA		V	8/1/2041
2021 PO7230873854	LGE	3	45 ACE	SP	CCA		V	8/2/2041
2021 PO7230073776	LGE	4	30 ACE	SP	CCA		V	8/3/2041
2021 PO4009386213	LGE	3	45 ACE	SP	CCA		V	8/4/2041
2021 PO7226673673	LGE	4	30 ACE	SP	CCA		V	8/5/2041
2021 PO7227973663	LGE	4	30 ACE	SP	CCA		V	8/6/2041
2021 PO7225273680	LGE	3	45 ACE	SP	CCA		V	8/7/2041
2021 PO7228773598	LGE	3	45 ACE	SP	CCA		V	8/8/2041
2021 PO7221073593	LGE	4	30 ACE	SP	CCA		V	8/9/2041
2021 PO4007786175	LGE	4	30 ACE	SP	CCA		V	8/10/2041
2021 PO7220773461	LGE	4	30 ACE	SP	CCA		V	8/11/2041
2021 PO4008386182	LGE	4	45 ACE	SP	CCA		V	8/12/2041
2021 PO7218573373	LGE	4	30 ACE	SP	CCA		V	8/13/2041
2021 PO4060585050	LGE	4	45 BRO	SP	CRE		V	8/14/2041
2021 PO4060585059	LGE	4	45 BRO	SP	CRE	ED,ID	BD	8/15/2041
2021 PO4060685064	LGE	4	30 BRO	SP	CRE	ED,ID	TD	8/16/2041
2021 PO4059085065	LGE	4	45 BRO	SP	CRE	ED,ID	TD	8/17/2041
2021 PO4058685066	LGE	3	45 BRO	SP	CRE	ED,ID	TD	8/18/2041
2021 PO5547235413	KU	3	50 UNK	SP	CRE	ED,ID	BX	8/19/2041
2021 PO4007286167	LGE	6	30 ACE	SP	A	ID,IP	TD	8/20/2041
2021 PO3952985883	LGE	4	40 ACE	SP	CCA		V	8/21/2041
2021 PO3951785895	LGE	4	40 ACE	SP	CCA		V	8/22/2041
2021 PO4000685982	F	4	40 ACE	SP	CRE		V	8/23/2041
2021 PO4000885995	F	4	40 ACE	SP	CRE		V	8/24/2041
2021 PO4001486008	F	4	40 ACE	SP	CRE		V	8/25/2041
2021 PO4002186020	F	3	45 ACE	SP	CCA		V	8/26/2041
2021 PO4003086028	F	4	40 ACE	SP	CRE		V	8/27/2041
2021 PO4003686040	F	4	40 ACE	SP	CRE		V	8/28/2041
2021 PO4004186049	F	4	40 ACE	SP	CRE		V	8/29/2041
2021 PO4053584670	LGE	3	50 ACE	SP	CRE	ED,ID	TD	8/30/2041
2021 PO4048984840	LGE	4	45 ACE	SP	CRE	ED,ID	BD	8/31/2041
2021 PO5548135572	KU	2	55 BRO	SP	CRE	ID	BD	9/1/2041
2021 PO5527035579	KU	5	35 BRO	SP	CRE	ID	TD	9/2/2041
2021 PO4056685056	F	3	45 BRO	SP	CCA		V	9/3/2041
2021 PO4507085063	LGE	3	45 BRO	SP	CCA		V	9/4/2041
2021 PO4055685062	LGE	4	35 BRO	SP	CRE	ED,ID	BD	9/5/2041
2021 PO4054485064	LGE	4	35 BRO	SP	CCA		V	9/6/2041
2021 PO4056385048	F	4	45 BRO	SP	CRE		V	9/7/2041
2021 PO4055685035	F	3	50 BRO	SP	CCA		V	9/8/2041
2021 PO4047084675	LGE	4	35 OTH	SP	CRE	ID,IP	TD	9/9/2041
2021 PO4047484688	LGE	4	35 OTH	SP	CRE	ID,IP,SRS	TD	9/10/2041
2021 PO4046884685	LGE	4	35 OTH	SP	CRE		V	9/11/2041
2021 PO4015286053	LGE	3	45 ACE	SP	CCA		V	9/12/2041
2021 PO4057585069	F	3	45 BRO	SP	CCA		V	9/13/2041
2021 PO4058185066	LGE	3	45 BRO	SP	CCA		V	9/14/2041



2021 PO4058385081	F	4	45 BRO	SP	CRE			V	9/15/2041
2021 PO4058885089	F	4	40 BRO	SP	CRE			V	9/16/2041
2021 PO4059985105	F	4	45 BRO	SP	CRE			V	9/17/2041
2021 PO7755862926	LGE	3	45 BRO	SP	CCA			V	9/18/2041
2021 PO4060885118	LGE	4	30 BRO	SP	CCA			V	9/19/2041
2021 PO4061085121	F	3	45 BRO	SP	CCA			V	9/20/2041
2021 PO5530635640	KU	4	40 UNK	SP	CRE	ID		TD	9/21/2041
2021 PO4048685173	LGE	4	30 BRO	SP	A			V	9/22/2041
2021 PO5457336072	KU	2	50 UNK	SP	CRE	ED,ID		BX	9/23/2041
2021 PO3967686474	F	4	40 ACE	SP	A			V	9/24/2041
2021 PO3966986468	F	4	40 ACE	SP	P			V	9/25/2041
2021 PO3966386463	F	4	40 ACE	SP	A			V	9/26/2041
2021 PO3965786448	F	4	40 ACE	SP	A			V	9/27/2041
2021 PO4049385186	LGE	5	30 BRO	SP	CRE	ED,ID		BD	9/28/2041
2021 PO4050285193	LGE	4	30 BRO	SP	CRE	ED,ID		TD	9/29/2041
2021 PO4014486046	LGE	3	45 ACE	SP	CCA			V	9/30/2041
2021 PO4014386044	LGE	3	45 ACE	SP	CCA			V	10/1/2041
2021 PO4013786038	LGE	4	35 ACE	SP	CRE	ED,ID		TD	10/2/2041
2021 PO3965086453	F	3	45 ACE	SP	CCA			V	10/3/2041
2021 PO3964286459	F	4	40 ACE	SP	CRE			V	10/4/2041
2021 PO4827638011	KU	3	45 BRN	SP	CCA			V	10/5/2041
2021 PO4859438572	KU	3	45 BRN	SP	CCA			V	10/6/2041
2021 PO4049685142	LGE	6	25 BRO	SP	CRE	ED,EP,HH,ID,IP		BD	10/7/2041
2021 PO4886937961	KU	3	45 BRN	SP	CCA			V	10/8/2041
2021 PO4895638168	KU	3	45 BRN	SP	CCA			V	10/9/2041
2021 PO4904238371	KU	3	45 BRN	SP	CCA			V	10/10/2041
2021 PO5531135769	KU	3	45 BRO	SP	CCA			V	10/11/2041
2021 PO4046984694	LGE	4	35 OTH	SP	A	ID,SRS		TD	10/12/2041
2021 PO4046584706	LGE	4	35 OTH	SP	CCA	ID		BD	10/13/2041
2021 PO4049584844	LGE	4	35 ACE	SP	P	ED,ID		BD	10/14/2041
2021 PO4049284847	LGE	3	45 ACE	SP	CCA			V	10/15/2041
2021 PO4049784861	LGE	3	45 ACE	SP	CRE	ED,HH,ID,RB		VX	10/16/2041
2021 PO4050684885	LGE	3	45 ACE	SP	CRE	ED,ID		BD	10/17/2041
2021 PO4050184871	LGE	3	45 ACE	SP	CCA			V	10/18/2041
2021 PO4049584809	LGE	4	40 ACE	SP	CCA	ED,ID		BD	10/19/2041
2021 PO3965286476	F	4	40 ACE	SP	CRE			V	10/20/2041
2021 PO3967686512	F	4	40 ACE	SP	CRE			V	10/21/2041
2021 PO3967386507	F	4	40 ACE	SP	CRE			V	10/22/2041
2021 PO3967086502	F	4	40 ACE	SP	CRE			V	10/23/2041
2021 PO3966386491	F	4	40 ACE	SP	CRE			V	10/24/2041
2021 PO4060285490	F	4	40 BRN	SP	CRE			V	10/25/2041
2021 PO4061385495	F	4	40 BRN	SP	CRE			V	10/26/2041
2021 PO4062385500	F	4	40 BRN	SP	CRE			V	10/27/2041
2021 PO6823444151	KU	4	45 BRO	SP	S			V	10/28/2041
2021 PO6859644243	KU	4	40 BRO	SP	CRE			V	10/29/2041
2021 PO6866644076	KU	6	30 BRO	SP	CRE	ED,ID		TD	10/30/2041
2021 PO4065685513	F	4	40 BRN	SP	CRE			V	10/31/2041
2021 PO4064585508	F	4	40 BRN	SP	CRE			V	11/1/2041
2021 PO4063585504	F	4	40 BRN	SP	CRE			V	11/2/2041
2021 PO4066885518	F	4	40 BRN	SP	CRE			V	11/3/2041
2021 PO4071285535	F	4	40 BRN	SP	CRE			V	11/4/2041
2021 PO4460802194	KU	4	40 BRN	SP	CRE	ED,HH,ID		BX	11/5/2041
2021 PO4461002648	KU	4	40 BRN	SP	CRE	ED,ID,IP		TX	11/6/2041
2021 PO4075084724	LGE	4	35 BRO	SP	CRE			V	11/7/2041

2021 PO5903838627	KU	4	45 BRO	SP	CRE	ED,ID	TD		11/8/2041
2021 PO5900738654	KU	5	35 BRO	SP	CRE	ED,ID	TD		11/9/2041
2021 PO4075984773	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		11/10/2041
2021 PO4076484773	LGE	4	35 BRO	SP	CRE	ED,ID	TD		11/11/2041
2021 PO4490403240	KU	4	40 BRN	SP	CRE	ED,ID	BD		11/12/2041
2021 PO4495603369	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/13/2041
2021 PO4470503031	KU	4	40 BRN	SP	CRE	ED,ID	BD		11/14/2041
2021 PO4075884759	LGE	4	30 BRO	SP	CRE	ED,ID	BD		11/15/2041
2021 PO4075484756	LGE	4	40 BRO	DF	CRE	ED,ID,IP	BD		11/16/2041
2021 PO4075484740	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD		11/17/2041
2021 PO4074884740	LGE	4	40 BRO	SP	CRE	ED,ID	TD		11/18/2041
2021 PO4074384724	LGE	4	40 BRO	SP	CRE	ED,ID	TD		11/19/2041
2021 PO4074884716	LGE	4	35 BRO	SP	CCA		V		11/20/2041
2021 PO4074284709	LGE	4	40 BRO	SP	CRE	ED,ID	TD		11/21/2041
2021 PO3935512941	KU	4	40 XXX	SP	CRE	ED,ID	TD		11/22/2041
2021 PO6534651835	KU	4	40 UNK	SP	CRE	ID	TD		11/23/2041
2021 PO9645017135	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/24/2041
2021 PO9648016840	KU	5	35 ACW	SP	CRE	ED,ID	TD		11/25/2041
2021 PO9648516624	KU	5	35 ACW	SP	CRE	ED,ID	TD		11/26/2041
2021 PO4133085015	LGE	4	40 ACE	SP	CRE	ED,EP,ID,IP,RB	TX	RR	11/27/2041
2021 PO4131985017	LGE	4	40 ACE	SP	CRE	ED,ID	BD		11/28/2041
2021 PO4130885019	LGE	4	40 ACE	SP	P	ED,ID	TD		11/29/2041
2021 PO3949212871	KU	3	45 XXX	SP	CRE	ED,ID	TD		11/30/2041
2021 PO3957112831	KU	5	35 XXX	SP	CRE	ID,MD	BD		12/1/2041
2021 PO3960813036	KU	4	40 XXX	SP	CRE	ED,ID	TD		12/2/2041
2021 PO4087685167	LGE	4	35 BRO	SP	CRE	ID	TD		12/3/2041
2021 PO6578651528	KU	4	45 UNK	SP	CRE	ID,IP	TD		12/4/2041
2021 PO5785037167	KU	4	40 BRO	SP	CRE		V		12/5/2041
2021 PO5744236760	F	4	45 BRO	SP	CCA		V		12/6/2041
2021 PO5745336833	F	4	45 BRO	SP	A		V		12/7/2041
2021 PO5740736535	F	4	40 BRO	SP	CRE		V		12/8/2041
2021 PO4056284633	LGE	3	50 BRO	SP	CCA		V		12/9/2041
2021 PO4054384624	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP,MD,RB	BX	PX	12/10/2041
2021 PO4057284260	LGE	3	45 BRO	SP	CRE	ED,ID,IP	BX	RP2	12/11/2041
2021 PO4055984622	LGE	4	40 BRO	SP	CRE	ED,ID	TD		12/12/2041
2021 PO4056084624	LGE	7	25 BRO	SP	CRE	ED,ID,RB	BX	RP3	12/13/2041
2021 PO4054084625	LGE	1	65E BRO	ST	CCA		V		12/14/2041
2021 PO4055584635	LGE	4	35 BRO	ST	CCA		V		12/15/2041
2021 PO4055684634	LGE	2	50 BRO	ST	CCA		V		12/16/2041
2021 PO4055784633	LGE	2	50 BRO	ST	CCA		V		12/17/2041
2021 PO4054984628	LGE	2	50 BRO	ST	CCA		V		12/18/2041
2021 PO4092885168	LGE	4	35 BRO	SP	A	ED,ID,RB	X	RP3	12/19/2041
2021 PO4091785168	LGE	4	35 BRO	SP	P	ED,ID,SRC	TD		12/20/2041
2021 PO4090685169	LGE	4	40 BRO	SP	CRE	ID	TD		12/21/2041
2021 PO5586335895	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/22/2041
2021 PO5649136037	KU	4	40 BRO	SP	CRE	ED,ID	BD		12/23/2041
2021 PO5604336143	KU	5	35 BRO	SP	CCA		V		12/24/2041
2021 PO5584436212	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/25/2041
2021 PO4447102412	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/26/2041
2021 PO4452902559	KU	4	40 BRN	SP	CRE		T		12/27/2041
2021 PO4074184692	LGE	4	40 BRO	SP	CRE	ED,ID	TD		12/28/2041
2021 PO4055384646	LGE	2	50 BRO	SP	CCA		V		12/29/2041
2021 PO4074684692	LGE	4	30 BRO	SP	CCA		V		12/30/2041
2021 PO4074484676	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP,RB	BX	RP2	12/31/2041

2021 PO4074884661	LGE	6	25 BRO	SP	CRE	ED,ID	TD	1/1/2042
2021 PO4074184664	LGE	4	40 BRO	SP	CRE	ED,ID	BD	1/2/2042
2021 PO4054884642	LGE	2	55 BRO	SP	P		V	1/3/2042
2021 PO4054384632	LGE	2	50 BRO	SP	CCA		V	1/4/2042
2021 PO4133085032	LGE	4	40 ACE	SP	P	ED,ID	TD	1/5/2042
2021 PO4080985088	LGE	4	35 BRO	SP	CRE	ID	TD	1/6/2042
2021 PO4080285076	LGE	4	40 BRO	SP	P	ID	TD	1/7/2042
2021 PO4079885069	LGE	4	30 BRO	SP	A	ID	TD	1/8/2042
2021 PO6641451469	KU	4	40 UNK	SP	CRE	ID	BD	1/9/2042
2021 PO4127385040	LGE	4	35 ACE	SP	P	ED,EP,ID	TD	1/10/2042
2021 PO4126685040	LGE	4	40 ACE	SP	P	ED,ID	TD	1/11/2042
2021 PO5773738461	KU	4	40 BRO	SP	CRE	ED,ID	BX	1/12/2042
2021 PO6659851121	KU	4	40 UNK	SP	CRE	ID,IP	TD	1/13/2042
2021 PO6641451469-A	KU	6	30 UNK	SP	CRE	ID	TD	1/14/2042
2021 PO6641451469-B	KU	6	30 UNK	SP	CRE	ID	TD	1/15/2042
2021 PO5798338372	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/16/2042
2021 PO8496113545	KU	6	30 ACW	SP	CRE	ED,ID	TD	1/17/2042
2021 PO8472213512	KU	4	40 ACW	SP	CRE	ED,ID	TD	1/18/2042
2021 PO8487313203	KU	4	40 ACW	SP	CRE	ED,ID	TD	1/19/2042
2021 PO5820438293	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/20/2042
2021 PO4010910851	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/21/2042
2021 PO7669615200	KU	2	70 ACW	SP	S		V	1/22/2042
2021 PO7697015173	KU	2	70 ACW	SP	CRE		V	1/23/2042
2021 PO4053684567	LGE	4	40 BRO	SP	CCA	ED,EP,ID,IP	TD	1/24/2042
2021 PO4054084563	LGE	5	25 BRO	SP	CRE	ED,ID	TD	1/25/2042
2021 PO4053184556	LGE	4	40 BRO	SP	CCA	ED,ID	TD	1/26/2042
2021 PO4121084991	LGE	4	45 ACE	SP	CRE	ED,ID	TD	1/27/2042
2021 PO4121584981	LGE	3	45 ACE	SP	CRE	ED,ID	BD	1/28/2042
2021 PO5524940162	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/29/2042
2021 PO5599240338	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/30/2042
2021 PO4086285106	LGE	4	35 BRO	SP	CRE	ID	TD	1/31/2042
2021 PO4085685096	LGE	4	35 BRO	SP	CRE	ID	TD	2/1/2042
2021 PO4084885083	LGE	4	35 BRO	SP	CRE	ED,ID,SRS	TD	2/2/2042
2021 PO4084335075A1	KU	4	40 BRO	SP	CRE	ID	TD	2/3/2042
2021 PO4084385075	LGE	4	35 BRO	SP	P	ED,ID	TD	2/4/2042
2021 PO4483202390a	KU	4	25E BRN	SP	CRE	ED,ID	TD	2/5/2042
2021 PO4483202390	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/6/2042
2021 PO4491802631	KU	3	40 BRN	SP	CRE	ED,ID	TD	2/7/2042
2021 PO4054684541	LGE	4	30 BRO	SP	P	ED,ID	BD	2/8/2042
2021 PO4054984538	LGE	4	30 BRO	SP	CRE	ED,ID	TD	2/9/2042
2021 PO4055484528	LGE	4	40 BRO	SP	CCA	ED,EP,ID,IP,RB	TX	2/10/2042
2021 PO4056484521	LGE	4	40 BRO	SP	CRE	ED,ID	TD	2/11/2042
2021 PO4057384514	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/12/2042
2021 PO4119484979	LGE	4	30 ACE	SP	P	ED,ID	TD	2/13/2042
2021 PO7763315141	KU	2	70 ACW	SP	CRE		V	2/14/2042
2021 PO7792915131	KU	2	70 ACW	SP	CRE		V	2/15/2042
2021 PO7819315124	KU	2	70 ACW	SP	CRE		V	2/16/2042
2021 PO7844715115	KU	2	65 ACW	SP	CRE		V	2/17/2042
2021 PO3978110539	KU	4	40 XXX	SP	CRE	ID	BD	2/18/2042
2021 PO3977610456	KU	6	30 BRN	SP	CCA		V	2/19/2042
2021 PO4130285038	LGE	4	40 ACE	SP	P	ED,ID	BD	2/20/2042
2021 PO4130685029	LGE	4	40 ACE	SP	P	ED,ID	TD	2/21/2042
2021 PO4446801951	KU	2	55 BRN	SP	CRE	ED,ID	TD	2/22/2042
2021 PO4082885118	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	2/23/2042

2021 PO4055585417	F	4	40 BRN	SP	CCA		V			2/24/2042
2021 PO4056685422	LGE	4	40 BRN	SP	CCA		V			2/25/2042
2021 PO4057785427	F	4	40 BRN	SP	CRE		V			2/26/2042
2021 PO4058485440	F	4	30 BRN	SP	CRE		V			2/27/2042
2021 PO4058885432	F	4	40 BRN	SP	CCA		V			2/28/2042
2021 PO4059585443	F	5	30 BRN	SP	CRE		V			3/1/2042
2021 PO4059485448	LGE	4	30 BRN	SP	P	ED,ID	TD			3/2/2042
2021 PO4059885435	F	4	40 BRN	SP	P		V			3/3/2042
2021 PO4060885447	LGE	4	30 BRN	SP	CRE	ED,ID	BD			3/4/2042
2021 PO4060985434	F	4	30 BRN	SP	CRE		V			3/5/2042
2021 PO4060985439	F	4	40 BRN	SP	CRE		V			3/6/2042
2021 PO4062185449	F	4	30 BRN	SP	CRE		V			3/7/2042
2021 PO4466702735	KU	4	40 BRN	SP	CRE	ED,HH,ID,RB	X	RP1		3/8/2042
2021 PO4482203109	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/9/2042
2021 PO4054285510	LGE	4	40 BRN	SP	CCA	ED,ID	TD			3/10/2042
2021 PO4052985518	LGE	4	40 BRN	SP	CRE	ED,ID	TD			3/11/2042
2021 PO6547251546	KU	4	40 UNK	SP	CRE	ID	TD			3/12/2042
2021 PO6595251612	KU	4	40 UNK	SP	CRE	ID	BD			3/13/2042
2021 PO4064785388	F	4	40 BRN	SP	CCA		V			3/14/2042
2021 PO4062385390	F	4	40 BRN	SP	CCA		V			3/15/2042
2021 PO4063785389	F	4	40 BRN	SP	CCA		V			3/16/2042
2021 PO4054285420	F	4	25 BRN	SP	CRE		V			3/17/2042
2021 PO4054585411	F	4	40 BRN	SP	CCA		V			3/18/2042
2021 PO4055185425	F	4	25 BRN	SP	CRE		V			3/19/2042
2021 PO5745337046	KU	3	45 BRO	SP	CCA		V			3/20/2042
2021 PO5735937041	KU	6	30 BRO	SP	CRE	ED,ID	TD			3/21/2042
2021 PO3970813127	KU	4	40 XXX	SP	CRE	ED,ID	TD			3/22/2042
2021 PO9647915772	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			3/23/2042
2021 PO9648216166	KU	4	45 ACW	SP	CRE	ED,ID	TD			3/24/2042
2021 PO9648516014	KU	4	40 ACW	SP	S		V			3/25/2042
2021 PO8474813811	KU	4	40 ACW	SP	CRE		V			3/26/2042
2021 PO8495613639	KU	4	45 ACW	SP	CRE	ED,ID	TD			3/27/2042
2021 PO8462613625	KU	4	40 ACW	SP	S		V			3/28/2042
2021 PO4141785018	LGE	4	40 ACE	SP	CRE	ED,ID	BD			3/29/2042
2021 PO6644651642	F	4	40 UNK	SP	CRE		V			3/30/2042
2021 PO6647151703	KU	4	40 UNK	SP	CRE	ID	TD			3/31/2042
2021 PO4085285159	LGE	4	35 BRO	SP	CRE	ID	BD			4/1/2042
2021 PO4084685149	LGE	4	35 BRO	SP	CRE	ID	BD			4/2/2042
2021 PO4084085139	LGE	4	35 BRO	SP	CRE	ID	BD			4/3/2042
2021 PO5774637100	KU	6	30 BRO	SP	CCA		V			4/4/2042
2021 PO5802237204	KU	4	40 BRO	SP	CRE	ED,ID	TD			4/5/2042
2021 PO5827337107	KU	4	40 BRO	SP	CCA		V			4/6/2042
2021 PO4455202101	KU	4	40 BRN	SP	CRE	ED,ID	TD			4/7/2042
2021 PO4439801829	KU	4	40 BRN	SP	CRE	ED,ID	TD			4/8/2042
2021 PO4083485128	LGE	4	35 BRO	SP	CCA	ID	TD			4/9/2042
2021 PO4025410842	KU	4	40 XXX	SP	CRE	ID	BD			4/10/2042
2021 PO4125285024	LGE	3	45 ACE	SP	P	ED,ID	TD			4/11/2042
2021 PO4124185019	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD			4/12/2042
2021 PO4088485204	LGE	1	50 BRO	SP	CCA		V			4/13/2042
2021 PO4088985203	LGE	3	55 BRO	WC	CRE	ID	BD			4/14/2042
2021 PO4089485197	LGE	4	35 BRO	WC	CRE	ED,ID,IP	TD			4/15/2042
2021 PO4089085208	LGE	4	35 BRO	SP	CCA		V			4/16/2042
2021 PO4088785188	LGE	4	30 BRO	SP	CRE	ED,ID	BD			4/17/2042
2021 PO4089385185	LGE	4	35 BRO	SP	CRE	ID	TD			4/18/2042

2021 PO4089285170	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		4/19/2042
2021 PO4089985152	LGE	5	35 BRO	SP	CRE	ID	BD		4/20/2042
2021 PO4089085157	LGE	3	40 BRO	SP	CCA		V		4/21/2042
2021 PO4088585147	LGE	3	40 BRO	SP	CCA		V		4/22/2042
2021 PO4087985137	LGE	4	35 BRO	SP	CRE	ID	TD		4/23/2042
2021 PO4507302986	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/24/2042
2021 PO4054484574	LGE	4	35 BRO	SP	CCA		V		4/25/2042
2021 PO4055684572	F	4	40 BRO	SP	CCA		V		4/26/2042
2021 PO4055484568	LGE	4	35 BRO	SP	CCA		V		4/27/2042
2021 PO6684351872	KU	5	35 UNK	SP	CRE	ID	TD		4/28/2042
2021 PO6684751799	KU	4	40 UNK	SP	CRE	ID,IP	TD		4/29/2042
2021 PO4025210952	KU	4	40 KOP	SP	CRE	ID	BD		4/30/2042
2021 PO4121685016	LGE	4	40 ACE	SP	P	ED,ID	TD		5/1/2042
2021 PO5708440231	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/2/2042
2021 PO5717740249	KU	6	30 BRO	SP	CRE	ED,ID	TD		5/3/2042
2021 PO4010111307	KU	6	30 XXX	SP	CRE	ED,ID,RB	BX	RP1	5/4/2042
2021 PO4015911096	KU	6	30 XXX	SP	CRE	ED,ID	TD		5/5/2042
2021 PO4022511072	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		5/6/2042
2021 PO4015711321	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/7/2042
2021 PO4122885007	LGE	4	40 ACE	SP	P	ED,ID	TD		5/8/2042
2021 PO4067885479	LGE	4	30 BRN	SP	CRE	ED	TD		5/9/2042
2021 PO4067185489	F	4	30 BRN	SP	CRE		V		5/10/2042
2021 PO6588449323	F	3	40 UNK	SP	CCA		V		5/11/2042
2021 PO4115884984	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD		5/12/2042
2021 PO9633518114	KU	4	40 ACW	SP	S		V		5/13/2042
2021 PO9645018114	KU	4	40 ACW	SP	CCA		V		5/14/2042
2021 PO9645017800	KU	4	40 ACW	SP	S		V		5/15/2042
2021 PO9645017467	KU	4	40 ACW	SP	S		V		5/16/2042
2021 PO4092685162	LGE	4	40 BRO	SP	CCA		V		5/17/2042
2021 PO5733236204	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/18/2042
2021 PO5690636114	KU	4	45 BRO	SP	CRE	ED,ID	BD		5/19/2042
2021 PO4136185023	LGE	3	45 ACE	SP	P	ED,ID	TD		5/20/2042
2021 PO4135085024	LGE	3	45 ACE	SP	CRE	ED,ID	TD		5/21/2042
2021 PO4134085016	LGE	4	40 ACE	SP	P	ED,ID	TD		5/22/2042
2021 PO3947712643	KU	4	40 XXX	SP	CRE	ID	BD		5/23/2042
2021 PO3964912595	KU	4	40 XXX	SP	CRE	ID	BD		5/24/2042
2021 PO3914412752	KU	4	40 BRN	SP	CCA		V		5/25/2042
2021 PO3942812686	KU	4	40 BRN	SP	CCA		V		5/26/2042
2021 PO6557351462	KU	4	45 UNK	SP	CRE	ID,IP	TD		5/27/2042
2021 PO4457902595	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		5/28/2042
2021 PO4062185440	F	4	45 BRN	SP	P		V		5/29/2042
2021 PO3957212426	KU	4	40 XXX	SP	CRE	HH,ID,RB	BX	RP1	5/30/2042
2021 PO4130185639	F	4	40 ACE	SP	CRE		V		5/31/2042
2021 PO4129085641	F	4	40 ACE	SP	CCA		V		6/1/2042
2021 PO4465302613	KU	7	30 BRN	SP	CCA		T		6/2/2042
2021 PO4094585166	LGE	4	30 BRO	SP	A	ED,ID	TD		6/3/2042
2021 PO4093985167	LGE	4	35 BRO	SP	CCA	ID	TD		6/4/2042
2021 PO3944512445	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD		6/5/2042
2021 PO4136785014	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		6/6/2042
2021 PO4056485519	LGE	4	40 BRN	SP	CCA	ED,ID	TD		6/7/2042
2021 PO4054285518	LGE	4	40 BRN	SP	CCA	ED,ID	TD		6/8/2042
2021 PO4058085519	LGE	4	40 BRN	SP	CCA	ED,ID	TD		6/9/2042
2021 PO4054185362	F	2	40 BRN	SP	CCA		V		6/10/2042
2021 PO6548751472	KU	6	30 UNK	SP	CRE	ID,IP	BD		6/11/2042

2021 PO4516203205	KU	3	40 BRN	SP	CRE	ED,ID	TD			6/12/2042
2021 PO4129185020	LGE	4	40 ACE	SP	P	ED,ID	TD			6/13/2042
2021 PO3995610667	KU	6	30 XXX	SP	P	ED,ID	TD			6/14/2042
2021 PO3993610581	KU	4	40 BRN	SP	CCA		V			6/15/2042
2021 PO4003710618	KU	4	40 XXX	SP	CRE	ID	BD			6/16/2042
2021 PO4128285020	LGE	4	40 ACE	SP	P	ED,ID	TD			6/17/2042
2021 PO5856637772	KU	4	40 BRO	SP	CCA		V			6/18/2042
2021 PO5845137534	KU	4	40 BRO	SP	CCA		V			6/19/2042
2021 PO5825837687	KU	4	40 BRO	SP	CRE		V			6/20/2042
2021 PO5844237914	F	4	40 BRO	SP	CRE		V			6/21/2042
2021 PO5847337965	KU	3	45 BRO	SP	CCA		V			6/22/2042
2021 PO5856238253	KU	4	40 BRO	SP	CCA		V			6/23/2042
2021 PO5837838035	KU	3	45 BRO	SP	CCA		V			6/24/2042
2021 PO5851538186	KU	4	40 BRO	SP	CRE	ED,ID	TD			6/25/2042
2021 PO4015210685	KU	4	40 XXX	SP	CRE	ED,ID	TD			6/26/2042
2021 PO4082285108	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD			6/27/2042
2021 PO4081585097	LGE	4	35 BRO	SP	CRE	ID	TD			6/28/2042
2021 PO4502102869	KU	2	45 BRN	SP	CRE	ED,ID	TD			6/29/2042
2021 PO4469602072	KU	4	40 BRN	SP	P	ED,ID,RB	X	PX		6/30/2042
2021 PO4511903101	KU	4	40 BRN	SP	CRE	ED,ID	TD			7/1/2042
2021 PO4497102753	KU	4	40 BRN	SP	CCA		V			7/2/2042
2021 PO4474402198	KU	4	40 BRN	SP	P	ED,ID,RB	TX	RR		7/3/2042
2021 PO4059584536	F	4	35 BRO	SP	CRE		V			7/4/2042
2021 PO7750368152	KU	4	40 ACE	SP	CRE	ED,ID	TD			7/5/2042
2021 PO3169981183	KU	4	45 BRO	SP	CRE	ED,ID	TD			7/6/2042
2021 PO3157181546	KU	4	40 BRO	SP	CRE	ED,ID	TD			7/7/2042
2021 PO7839268119	KU	3	55 ACE	SP	CRE	ED,ID	BD			7/8/2042
2021 PO7838368084	KU	2	50 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1		7/9/2042
2021 PO7836668119	KU	4	45 ACE	SP	CRE	ED,ID	BD			7/10/2042
2021 PO5055023727	KU	4	40 BRO	SP	CRE	ED,ID	BD			7/11/2042
2021 PO5047223654	KU	6	35 BRO	SP	CRE	ED,ID	BD			7/12/2042
2021 PO4434189054	LGE	3	45 ACE	SP	A	ED,ID	TD			7/13/2042
2021 PO4433089067	LGE	3	45 ACE	SP	A	ED,ID	TD			7/14/2042
2021 PO5036323725	KU	5	35 BRO	SP	CRE	ED	BD			7/15/2042
2021 PO5029823800	KU	6	35 BRO	SP	CRE	ED,ID	BD			7/16/2042
2021 PO5027023971	KU	4	40 BRO	SP	CRE	ED,ID	BD			7/17/2042
2021 PO4453887975	LGE	3	45 BRO	SP	A		V			7/18/2042
2021 PO5017723872	KU	6	35 BRO	SP	CRE	ED	BD			7/19/2042
2021 PO5042223939	KU	6	35 BRO	SP	CRE	ED	BD			7/20/2042
2021 PO4452687966	F	4	30 BRO	SP	CCA		V			7/21/2042
2021 PO4038316707	KU	4	45 KOP	SP	CCA		V			7/22/2042
2021 PO4049816918	KU	3	45 KOP	SP	CCA		V			7/23/2042
2021 PO4456988009	F	4	40 BRO	SP	A		V			7/24/2042
2021 PO4457688000	F	4	30 BRO	SP	A		V			7/25/2042
2021 PO4457287998	LGE	3	45 BRO	SP	A		V			7/26/2042
2021 PO4436089041	LGE	3	45 ACE	SP	A	ED,ID	BD			7/27/2042
2021 PO4435289041	F	3	45 ACE	SP	A		V			7/28/2042
2021 PO4435589036	LGE	4	40 ACE	SP	A	ED,ID	X	RR		7/29/2042
2021 PO4535687794	LGE	3	45 ACE	SP	CCA		V			7/30/2042
2021 PO4533887782	F	3	45 ACE	SP	CCA		V			7/31/2042
2021 PO4538487671	LGE	3	45 ACE	SP	CCA		V			8/1/2042
2021 PO4530787621	LGE	3	45 ACE	SP	CCA		V			8/2/2042
2021 PO4530687492	F	4	40 BRO	SP	CRE		V			8/3/2042
2021 PO4530287501	F	4	40 BRO	SP	CRE		V			8/4/2042

2021 PO4528887603	F	3	45 ACE	SP	CCA		V	8/5/2042
2021 PO4528787524	F	4	45 ACE	SP	A		V	8/6/2042
2021 PO4536587613	F	6	25 ACE	SP	CRE		V	8/7/2042
2021 PO4530987470	F	4	30 BRO	SP	CCA		V	8/8/2042
2021 PO4532287455	F	4	40 BRO	SP	CCA		V	8/9/2042
2021 PO4531487458	F	4	30 BRO	SP	CRE		V	8/10/2042
2021 PV2419887239	F	4	40 BRO	SP	CCA		V	8/11/2042
2021 PO4533987419	F	4	40 BRO	SP	P		V	8/12/2042
2021 PO1203260941	F	3	45 BRO	SP	CCA		V	8/13/2042
2021 PO4332923923	KU	4	40 XXX	SP	CCA		V	8/14/2042
2021 PO4351423995	KU	6	35 XXX	SP	CRE	ID	TD	8/15/2042
2021 PO4536287604	F	4	40 ACE	SP	P		V	8/16/2042
2021 PO3973918101	KU	6	35 KOP	SP	CCA		T	8/17/2042
2021 PO4540187516	F	5	40 ACE	SP	CRE		V	8/18/2042
2021 PO4371124073	KU	6	35 XXX	SP	CRE	ID,IP	TD	8/19/2042
2021 PO4384224119	KU	5	35 XXX	SP	CRE	ID	TD	8/20/2042
2021 PO4534387645	LGE	4	40 ACE	SP	CCA		V	8/21/2042
2021 PO4537187595	F	4	40 ACE	SP	P		V	8/22/2042
2021 PO4538087581	F	4	40 ACE	SP	P		V	8/23/2042
2021 PO4537687557	F	4	45 ACE	SP	CCA		V	8/24/2042
2021 4012917806a	KU	3	45E BRN	SP	CRE	ED,ID,IP,SRS	TD	8/25/2042
2021 PO4536687548	F	4	40 ACE	SP	CCA		V	8/26/2042
2021 PO4534187400	LGE	4	35 BRO	SP	P	ED,ID	BD	8/27/2042
2021 PO4534687405	F	4	40 BRO	SP	A		V	8/28/2042
2021 PO4535687550	F	4	40 ACE	SP	CCA		V	8/29/2042
2021 PO4533287571	F	4	40 ACE	SP	A		V	8/30/2042
2021 PO4532487394	F	4	40 BRO	SP	CRE		V	8/31/2042
2021 PO4531187386	F	4	40 BRO	SP	CCA		V	9/1/2042
2021 PO4530487381	F	4	40 BRO	SP	CRE		V	9/2/2042
2021 PO4532287381	F	4	40 BRO	SP	CRE		V	9/3/2042
2021 PO4407225403	KU	4	40 XXX	SP	CCA		V	9/4/2042
2021 PO4409425801	KU	4	35 XXX	SP	CCA	ID	BD	9/5/2042
2021 PO4402725794	KU	5	35 XXX	SP	CRE	ID,IP	BD	9/6/2042
2021 PO4408225604	KU	4	35 XXX	SP	CRE	ID	TD	9/7/2042
2021 PO4012917806	KU	3	45 KOP	SP	CRE	ED,ID,IP,SRS	TD	9/8/2042
2021 PO3962018157	KU	3	45 KOP	SP	CCA		T	9/9/2042
2021 PO4090016994	KU	2	55 BRN	SP	CCA		V	9/10/2042
2021 PO4405625146	KU	4	40 XXX	SP	CRE	ID	TD	9/11/2042
2021 PO4404624961	KU	4	35 XXX	SP	CRE	ID	TD	9/12/2042
2021 PO4403224738	KU	4	35 XXX	SP	CRE	ID	TD	9/13/2042
2021 PO4402124583	KU	4	35 XXX	SP	CRE	ID	TD	9/14/2042
2021 PO4401324465	KU	4	35 XXX	SP	CRE	ID	TD	9/15/2042
2021 PO4400624340	KU	4	35 XXX	SP	CRE	ID	TD	9/16/2042
2021 PO4492387936	F	4	30 BRO	SP	P		V	9/17/2042
2021 PO4492787942	LGE	2	55 BRO	SP	CRE	ED,ID,IP	BD	9/18/2042
2021 PO4492287942	LGE	2	55 BRO	SP	A	ED,ID,IP,MD	BD	9/19/2042
2021 PO4435489131	LGE	4	40 ACE	SP	CCA		V	9/20/2042
2021 PO4434989109	LGE	4	40 ACE	SP	CCA		V	9/21/2042
2021 PO4488187984	LGE	4	40 ACE	SP	CCA		V	9/22/2042
2021 PO4487887983	LGE	4	40 ACE	SP	CCA	ED,IP	BD	9/23/2042
2021 PO4435689114	LGE	4	35 ACE	SP	CCA	ED,ID	BD	9/24/2042
2021 PO4922609644	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	9/25/2042
2021 PO4911609641	F	4	40 OTH	SP	CCA		V	9/26/2042
2021 PO4905409540	F	4	40 INP	SP	CRE		V	9/27/2042

2021 PO4846309673	F	4	40 OTH	SP	CRE		V	9/28/2042
2021 PO4839709572	F	4	40 OTH	SP	CRE		V	9/29/2042
2021 PO4927509727	KU	6	30 BRN	SP	CCA		V	9/30/2042
2021 PO4832009455	F	3	45 OTH	SP	CCA		V	10/1/2042
2021 PO4815309208	F	4	40 OTH	SP	CCA		V	10/2/2042
2021 PO4919609768	F	3	45 INP	SP	CCA		V	10/3/2042
2021 PO4467187860-A	KU	4	40 BRO	SP	A	ID,IP	BD	10/4/2042
2021 PO4436689180	LGE	4	40 ACE	SP	CRE	ED,ID	BD	10/5/2042
2021 PO4481587944	LGE	2	55E ACE	SP	CRE	ED,ID	TD	10/6/2042
2021 PO4481587955	LGE	4	45 ACE	SP	CCA		V	10/7/2042
2021 PO4435689173	LGE	4	40 ACE	SP	CRE		V	10/8/2042
2021 PO4480887956	LGE	2	55 ACE	SP	CCA	ED	TD	10/9/2042
2021 PO4433889152	LGE	4	40 ACE	SP	CRE		V	10/10/2042
2021 PO4434589142	LGE	4	40 ACE	SP	CRE		V	10/11/2042
2021 PO4466287855	LGE	4	40 BRO	SP	CRE	ID,IP	BD	10/12/2042
2021 PO4432989153	LGE	3	45 ACE	SP	CRE		V	10/13/2042
2021 PO2352280783	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	10/14/2042
2021 PO4465087848	LGE	2	45 BRO	SP	A	ID,IP	BD	10/15/2042
2021 PO4464487845	LGE	3	50 BRO	SP	CRE	ID,IP	BD	10/16/2042
2021 PO4430889151	LGE	3	45 ACE	SP	P		V	10/17/2042
2021 PO4482787944	LGE	2	65 ACE	SP	CCA		V	10/18/2042
2021 PO4483187943	LGE	2	65 ACE	SP	CRE		V	10/19/2042
2021 PO4572526691	KU	4	40 BRO	SP	CRE		T	10/20/2042
2021 PO4579926705	KU	4	40 BRO	SP	CRE	ED	BD	10/21/2042
2021 PO4485087943	LGE	2	60 ACE	SP	A	ED,ID	BX	RR 10/22/2042
2021 PO4448889257	LGE	4	40 ACE	SP	A	ED,ID	BD	10/23/2042
2021 PO4447189245	LGE	4	40 ACE	SP	A	ED,ID	BD	10/24/2042
2021 PO4586826718	KU	4	40 BRO	SP	CRE	ED,ID	BD	10/25/2042
2021 PO4611426602	KU	2	50 BRO	SP	CCA		V	10/26/2042
2021 PO2392081367	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	10/27/2042
2021 PO4445989236	LGE	4	35 ACE	SP	CRE	ED,ID	BD	10/28/2042
2021 PO4579626381	KU	4	45 BRO	SP	CRE		T	10/29/2042
2021 PO4445089229	LGE	4	40 ACE	SP	CRE	ED,ID	BD	10/30/2042
2021 PO4444489240	LGE	4	40 ACE	DF	CRE		V	10/31/2042
2021 PV4469688122	F	5	35 BRO	SP	A		V	11/1/2042
2021 PO4617826312	KU	2	50 BRO	SP	CCA		V	11/2/2042
2021 PO4599426424	KU	4	45 BRO	SP	CRE		T	11/3/2042
2021 PO4614626458	KU	2	50 BRO	SP	CCA		V	11/4/2042
2021 PO4608026106	KU	4	40 BRO	SP	CRE		T	11/5/2042
2021 PO4443489233	LGE	4	40 ACE	SP	CRE	ED	V	11/6/2042
2021 PO4444089226	LGE	4	35 ACE	SP	CRE	ED	V	11/7/2042
2021 PO4485987943	LGE	2	65 ACE	SP	A	ED	BD	11/8/2042
2021 PO4444089213	LGE	4	40 ACE	SP	A	ED	BD	11/9/2042
2021 PO4444289198	LGE	4	40 ACE	SP	CCA		V	11/10/2042
2021 PO4486487943	LGE	2	55 ACE	SP	A	ED	BD	11/11/2042
2021 PO4487087943	LGE	2	60 ACE	SP	A	ED	TD	11/12/2042
2021 PO4488287943	LGE	2	65 ACE	SP	CRE	ED	BD	11/13/2042
2021 PO2380680904	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	11/14/2042
2021 PO2262280982	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	11/15/2042
2021 PO4594226083	KU	4	40 BRO	SP	CRE	ED,ID	BD	11/16/2042
2021 PO4586826071	KU	4	40 BRO	SP	CRE	ED	BD	11/17/2042
2021 PO4628025845	KU	2	50 BRO	SP	CCA		V	11/18/2042
2021 PO4489987942	LGE	2	60 ACE	SP	CRE	ED,IP	BD	11/19/2042
2021 PO4469888132	LGE	2	45 BRO	SP	A	ID	BD	11/20/2042



2021 PO4442889198	LGE	4	40 ACE	SP	CRE	ED,ID	BD	11/21/2042
2021 PO4490987942	LGE	1	60 ACE	SP	CCA		V	11/22/2042
2021 PO4491487942	LGE	4	40 ACE	SP	CCA		V	11/23/2042
2021 PO4441989202	LGE	4	40 ACE	SP	CRE	ED	BD	11/24/2042
2021 PO4468588144	LGE	3	55 BRO	SP	CRE	ID,IP	BD	11/25/2042
2021 PO4441689215	LGE	4	35 ACE	SP	CCA		V	11/26/2042
2021 PO4441289212	LGE	4	40 ACE	SP	A	ED	BD	11/27/2042
2021 PO4470288125	LGE	2	60 BRO	SP	CRE	ID,IP	BD	11/28/2042
2021 PO1394403726	LGE	3	45 ACE	SP	CCA		V	11/29/2042
2021 PO4431289138	F	4	40 ACE	SP	CCA		V	11/30/2042
2021 PO4433289132	F	4	40 ACE	SP	CCA		V	12/1/2042
2021 PO4463587840	LGE	4	40 BRO	SP	CCA		V	12/2/2042
2021 PO4434089121	F	4	35 ACE	SP	CCA		V	12/3/2042
2021 PO4463187838	LGE	1	50 BRO	SP	CCA		V	12/4/2042
2021 PO2369180945	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	12/5/2042
2021 PO2370481107	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	12/6/2042
2021 PO2362680957	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	12/7/2042
2021 PO2337981030	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	12/8/2042
2021 PO4462987837	LGE	1	55 BRO	SP	CRE	ID,IP	BD	12/9/2042
2021 PO4535087609	F	4	30 ACE	SP	CCA		V	12/10/2042
2021 PO4462287832	LGE	4	40 BRO	SP	CCA		V	12/11/2042
2021 PO4808426345	F	4	40 OTH	SP	P		V	12/12/2042
2021 PO4789926693	F	4	40 OTH	SP	CRE	ED,HH,ID	BX PX	12/13/2042
2021 PO4437789188	LGE	4	40 ACE	SP	A	ED,ID	BD	12/14/2042
2021 PO4645225159	KU	2	40 BRO	SP	CCA		V	12/15/2042
2021 PO4642725175	KU	2	45 BRO	SP	CCA		V	12/16/2042
2021 PO4471188111	LGE	1	70 BRO	SP	CCA		V	12/17/2042
2021 PO4440989057	LGE	4	40 ACE	SP	A	ED,ID	TD	12/18/2042
2021 PO4643625124	KU	2	45 BRO	SP	CCA		V	12/19/2042
2021 PO4440189069	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/20/2042
2021 PO4591325440	KU	6	30 BRO	SP	CCA		V	12/21/2042
2021 PO4441389096	F	3	45 ACE	SP	P		V	12/22/2042
2021 PO4443189113	F	3	45 ACE	SP	P		V	12/23/2042
2021 PO4445089130	F	3	45 ACE	SP	P		V	12/24/2042
2021 PO4461587829	LGE	2	55 BRO	SP	A	ID	BD	12/25/2042
2021 PO2225681294	KU	6	35 BRO	SP	CRE	ED,IP,SRS	TD	12/26/2042
2021 PO4431687797	LGE	3	45 BRO	SP	CCA		V	12/27/2042
2021 PO4431587797	LGE	2	65 BRO	SP	CRE	ID,IP	BD	12/28/2042
2021 PO4430187797	LGE	2	65 BRO	SP	CRE	ID,IP	BD	12/29/2042
2021 PO4428187801	LGE	3	55 BRO	SP	CRE	ID,IP	BD	12/30/2042
2021 PO2303481112	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	12/31/2042
2021 PO2268081189	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	1/1/2043
2021 PO4426787806	LGE	3	50 BRO	SP	CRE	ID	BD	1/2/2043
2021 PO4425287811	LGE	3	50 BRO	SP	CRE	ID,IP	BD	1/3/2043
2021 PO4423987815	LGE	3	50 BRO	SP	CCA		V	1/4/2043
2021 PO4619426829	F	4	40 BRO	SP	CCA		V	1/5/2043
2021 PO4611326904	F	3	45 BRO	SP	CRE		V	1/6/2043
2021 PO4605326858	KU	2	50 BRO	SP	CCA		V	1/7/2043
2021 PO4603427014	KU	6	30 BRO	SP	CCA		V	1/8/2043
2021 PO4599927087	KU	2	50 BRO	SP	CCA		V	1/9/2043
2021 PO4597326739	KU	4	40 BRO	SP	CRE		V	1/10/2043
2021 PO4454589201	LGE	4	35 ACE	SP	A	ED,ID	BD	1/11/2043
2021 PO4507387979	LGE	4	35 ACE	SP	P	ED	TD	1/12/2043
2021 PO4508587960	LGE	4	35 ACE	SP	P	ED	TD	1/13/2043

2021 PO4451689222	LGE	4	35 ACE	SP	A	ED	BD	1/14/2043
2021 PO4584826796	KU	4	40 BRO	SP	CRE	ED	BD	1/15/2043
2021 PO4585826757	KU	4	40 BRO	SP	CRE		V	1/16/2043
2021 PO4581426936	KU	4	40 BRO	SP	CCA		V	1/17/2043
2021 PO4440289205	LGE	4	40 ACE	SP	A	ED,ID	BD	1/18/2043
2021 PO4470688119	LGE	2	55 BRO	SP	CRE	ID,IP	BD	1/19/2043
2021 PO4439089197	LGE	4	40 ACE	SP	CRE	ED,ID	BD	1/20/2043
2021 PO4438389194	LGE	4	35 ACE	SP	A	ED,ID	BD	1/21/2043
2021 PO4481287933	LGE	4	30 ACE	SP	CCA		V	1/22/2043
2021 PO4481687941	LGE	2	60 ACE	SP	CRE	ED,MD	BD	1/23/2043
2021 PO4481087937	LGE	3	45 ACE	SP	CCA		V	1/24/2043
2021 PO4480387933	LGE	3	45 ACE	SP	CCA		V	1/25/2043
2021 PO4479787930	LGE	1	60 ACE	SP	CCA		V	1/26/2043
2021 PO4434089171	LGE	4	35 ACE	SP	CRE		V	1/27/2043
2021 PO4434489164	LGE	4	40 ACE	SP	CRE		V	1/28/2043
2021 PO4467187860	LGE	2	55 BRO	SP	CRE	ID,IP	BD	1/29/2043
2021 PO4451189231	LGE	4	35 ACE	SP	CCA		V	1/30/2043
2021 PO4555126974	KU	2	40 BRO	SP	CRE	ED	BD	1/31/2043
2021 PO4449389241	LGE	4	35 ACE	SP	A	ED,ID	BD	2/1/2043
2021 PO4559127026	KU	3	45 BRO	SP	CRE	ED	BD	2/2/2043
2021 PO4566827082	KU	4	40 BRO	SP	CRE	EP	BX	RP3 2/3/2043
2021 PO4452689266	LGE	4	35 ACE	SP	A	ED,ID	BD	2/4/2043
2021 PO4451189253	LGE	4	35 ACE	SP	A	ED,ID	BD	2/5/2043
2021 PO4567126982	KU	4	40 BRO	SP	CRE		T	2/6/2043
2021 PO4570027033	KU	2	40 BRO	SP	CRE		T	2/7/2043
2021 PO4578927035	KU	4	40 BRO	SP	CRE	ED,ID,RB	BX	PX 2/8/2043
2021 PO4607926762	KU	2	50 BRO	SP	CCA		V	2/9/2043
2021 PO4564026677	KU	4	40 BRO	SP	CRE	ED,ID	BD	2/10/2043
2021 PO2433982031	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	2/11/2043
2021 PO2423281854	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	2/12/2043
2021 PO2407381607	KU	4	45 BRO	SP	CCA		V	2/13/2043
2021 PO4621826129	KU	2	50 BRO	SP	CCA		V	2/14/2043
2021 PO1470504221	LGE	4	35 ACE	SP	CCA		V	2/15/2043
2021 PO4624725991	KU	2	50 BRO	SP	CCA		V	2/16/2043
2021 PO4614025970	KU	4	40 BRO	SP	CRE	ED	BD	2/17/2043
2021 PO4613525715	KU	6	30 BRO	SP	CRE		T	2/18/2043
2021 PO4614625641	KU	2	45 BRO	SP	CRE	ED,ID	BD	2/19/2043
2021 PO4637525413	KU	2	50 BRO	SP	CCA		V	2/20/2043
2021 PO4632025662	KU	2	50 BRO	SP	CCA		V	2/21/2043
2021 PO4636025477	KU	2	50 BRO	SP	CCA		V	2/22/2043
2021 PO4620225456	KU	3	45 BRO	SP	CRE	ED	BD	2/23/2043
2021 PO4609325441	KU	2	45 BRO	SP	CRE	ED	BD	2/24/2043
2021 PO4447089147	F	4	30 ACE	SP	CRE	ED	V	2/25/2043
2021 PO4462589180	LGE	3	45 ACE	SP	P	ED	V	2/26/2043
2021 PO4590425497	KU	6	30 BRO	SP	CCA		V	2/27/2043
2021 PO4505088014	LGE	4	35 ACE	SP	P	ED,IP	BD	2/28/2043
2021 PO4505688000	LGE	6 35E	ACE	SP	CRE	ED,IP	TD	3/1/2043
2021 PO4506487988	LGE	3	45 ACE	SP	CCA		V	3/2/2043
2021 PO4467089277	LGE	3	45 ACE	SP	A	ED	V	3/3/2043
2021 PO4472289325	LGE	4	40 ACE	SP	CCA		V	3/4/2043
2021 PO4472089336	LGE	3	45 ACE	SP	P	ED	V	3/5/2043
2021 PO4471489351	LGE	3	45 ACE	SP	CCA	ED	V	3/6/2043
2021 PO4616427384	KU	6	30 BRO	SP	CRE	ED	BD	3/7/2043
2021 PO4471389354	F	3	45 ACE	SP	CRE		V	3/8/2043

2021 PO4777726222	F	4	40 OTH	SP	CRE		V		3/9/2043
2021 PO4817826362	F	4	40 OTH	SP	P		V		3/10/2043
2021 PO4833026389	F	4	40 OTH	SP	CRE	ED	V		3/11/2043
2021 PO4843226411	F	4	40 OTH	SP	CRE	ED, SRC	V		3/12/2043
2021 PO4843726381	F	4	40 OTH	SP	CRE	ED, ID, IP	V		3/13/2043
2021 PO4853726341	F	4	40 OTH	SP	CRE		V		3/14/2043
2021 PO4841826489	F	4	40 OTH	SP	CRE		V		3/15/2043
2021 PO4838626616	F	4	40 OTH	SP	CRE		V		3/16/2043
2021 PO4821326748	F	3 45E	OTH	SP	CRE	ED, ID, IP	BX	RP1	3/17/2043
2021 PO4804126718	F	4	40 OTH	SP	P		V		3/18/2043
2021 PO4776626671	F	4	40 OTH	SP	P		V		3/19/2043
2021 PO4791126394	F	4 35E	OTH	SP	CRE	ED, HH, ID, RB	BX	PX	3/20/2043
2021 PO3977885683	F	4	40 ACE	SP	CRE		V		3/21/2043
2021 PO3926385873	F	4	40 BRO	SP	CRE		V		3/22/2043
2021 PO3926985884	F	3	55 BRO	SP	CRE		V		3/23/2043
2021 PO3927385881	F	5	25 BRO	SP	CRE		V		3/24/2043
2021 PO3970985730	F	4	40 ACE	SP	CRE		V		3/25/2043
2021 PO3972185728	F	4	40 ACE	SP	CRE		V		3/26/2043
2021 PO3973285722	F	4	40 ACE	SP	CRE		V		3/27/2043
2021 PO3974485716	F	4	40 ACE	SP	CRE		V		3/28/2043
2021 PO3925785863	F	UNK	55 BRO	SP	CRE		V		3/29/2043
2021 PO3926485830	LGE	5	30 BRO	SP	CRE	ED, ID	TD		3/30/2043
2021 PO3975585710	F	4	40 ACE	SP	CRE		V		3/31/2043
2021 PO3976685704	F	4	40 ACE	SP	P		V		4/1/2043
2021 PO6391869935	LGE	4	35 BRO	SP	CRE	ED, ID	TD		4/2/2043
2021 PO5278437339	KU	3	45 INP	SP	CRE	ID	BD		4/3/2043
2021 PO5287637212	KU	4	45 BRN	SP	CRE	ED, ID, SRC	TD		4/4/2043
2021 PO3979185673	LGE	4	30 ACE	SP	P	ED, ID, MD	TD		4/5/2043
2021 PO5269230506	KU	4	45 BRN	SP	CRE	ID, IP	BD		4/6/2043
2021 PO5262130532	KU	4	40 BRN	SP	CRE	ID	BD		4/7/2043
2021 PO3978785733	F	4	40 ACE	SP	A		V		4/8/2043
2021 PO3979585714	F	4	40 ACE	SP	CRE		V		4/9/2043
2021 PO3978485695	F	4	40 ACE	SP	CRE		V		4/10/2043
2021 PO3979185691	F	4	40 ACE	SP	CRE		V		4/11/2043
2021 PO3979885681	F	4	40 ACE	SP	CRE		V		4/12/2043
2021 PO3925585835	LGE	4	35 BRO	SP	CCA		V		4/13/2043
2021 PO3924485842	F	3	55 BRO	SP	CRE		V		4/14/2043
2021 PO3923385825	F	UNK	55 BRO	SP	CRE		V		4/15/2043
2021 PO3922885818	F	4	35 BRO	SP	CRE		V		4/16/2043
2021 PO3922385808	F	UNK	55 BRO	SP	CRE		V		4/17/2043
2021 PO5295936880	KU	4	40 BRN	SP	CRE	ID	TD		4/18/2043
2021 PO5297436880	KU	4	40 BRN	SP	CRE	ED, ID, IP	TX	RR	4/19/2043
2021 PO5298136951	KU	4	45 BRN	SP	CRE	ID, SRC	TD		4/20/2043
2021 PO5298937023	KU	3	45 BRN	SP	CRE	ID, SRS	TD		4/21/2043
2021 PO5322337093	KU	2	45 KOP	SP	S	SRS	BD		4/22/2043
2021 PO5319437104	KU	4	45 BRN	SP	CRE	ID, SRS	TD		4/23/2043
2021 PO5310837134	KU	4	40 BRN	SP	CRE	SRS	TD		4/24/2043
2021 PO5299637101	KU	2	50 BRN	SP	CCA		V		4/25/2043
2021 PO5300337170	KU	4	45 BRN	SP	CRE	ID, SRS	TD		4/26/2043
2021 PO5294237191	KU	4	45 BRN	SP	CCA	ID, SRS	TD		4/27/2043
2021 PO3978085766	F	4	40 ACE	SP	CRE	ED, HH, ID, RB	BX	PX	4/28/2043
2021 PO3921785799	F	4	40 BRO	SP	CRE		V		4/29/2043
2021 PO3978285751	F	4	40 ACE	SP	CRE		V		4/30/2043
2021 PO3977485733	F	4	40 ACE	SP	CRE		V		5/1/2043

2021	PO3976285739	F	4	40 ACE	SP	CRE		V	5/2/2043
2021	PO3975185746	F	4	40 ACE	SP	CRE		V	5/3/2043
2021	PO3974085751	F	4	40 ACE	SP	P		V	5/4/2043
2021	PO3973385757	F	4	40 ACE	SP	CRE		V	5/5/2043
2021	PO3974085763	F	4	40 ACE	SP	P		V	5/6/2043
2021	PO5826011803	KU	4	40 ACW	SP	S		V	5/7/2043
2021	PO5842111940	KU	4	40 ACW	SP	S		V	5/8/2043
2021	PO5825911937	KU	3	45 ACW	SP	S		V	5/9/2043
2021	PO5875711654	KU	5	45 ACW	SP	S		V	5/10/2043
2021	PO5852811702	KU	4	40 ACW	SP	S		V	5/11/2043
2021	PO5841111719	KU	4	40 ACW	SP	S		V	5/12/2043
2021	PO5826311498	KU	4	40 ACW	SP	S		V	5/13/2043
2021	PO5826111732	KU	4	40 ACW	SP	S		V	5/14/2043
2021	PO5841011349	KU	3	45 ACW	SP	S		V	5/15/2043
2021	PO5845711165	KU	5	45 ACW	SP	S		V	5/16/2043
2021	PO6345510079	KU	5	35 ACW	SP	CCA		V	5/17/2043
2021	PO6394709797	F	3	45 ACW	SP	S		V	5/18/2043
2021	PO6233110876	F	4	40 ACW	SP	P		V	5/19/2043
2021	PO6231310626	F	4	40 ACW	SP	P		V	5/20/2043
2021	PO6232510770	F	4	40 ACW	SP	P		V	5/21/2043
2021	391578748A	LGE	4	35 BRO	SP	CRE	ED,ID	TD	5/22/2043
2021	PO3917085723	F	UNK	55 BRO	SP	CRE		V	5/23/2043
2021	PO3915785748	F	4	40 BRO	SP	CRE		V	5/24/2043
2021	PO3933185658	F	4	30 ACE	SP	CCA		V	5/25/2043
2021	PO3933885662	F	4	40 ACE	SP	CCA		V	5/26/2043
2021	PO3934885672	F	4	40 ACE	SP	P		V	5/27/2043
2021	PO3935785684	F	3	45 ACE	SP	CCA		V	5/28/2043
2021	PO3918085743	F	3	55 BRO	SP	CRE		V	5/29/2043
2021	PO5430437194	KU	3	45 UNK	SP	CRE		V	5/30/2043
2021	PO5432337173	KU	2	45 UNK	SP	CRE		V	5/31/2043
2021	PO5442336936	KU	5	35 UNK	SP	CRE		V	6/1/2043
2021	PO5449436926	KU	2	40 UNK	SP	CRE	SRS	TD	6/2/2043
2021	PO3988885722	LGE	3	50 ACE	SP	CRE	ED,ID	BD	6/3/2043
2021	PO3939385825	LGE	4	45 ACE	SP	CRE	ID	BD	6/4/2043
2021	PO4067686269	LGE	5	35 BRO	SP	A	ED,ID	TD	6/5/2043
2021	PO4071486262	F	UNK	25 BRO	SP	CRE		V	6/6/2043
2021	PO4073086265	F	5	30 BRO	SP	A		V	6/7/2043
2021	PO4073386265	F	5	40 BRO	SP	CRE		V	6/8/2043
2021	PO3987285732	LGE	4	35 ACE	SP	CRE	ED,ID	TD	6/9/2043
2021	PO3986285739	LGE	4	35 ACE	SP	CCA		V	6/10/2043
2021	PO3938985827	F	3	45 ACE	SP	CCA		V	6/11/2043
2021	PO6204310691	F	4	40 ACW	SP	P		V	6/12/2043
2021	PO6233610544	F	4	40 ACW	SP	P		V	6/13/2043
2021	PO6234310429	F	4	40 ACW	SP	P		V	6/14/2043
2021	PO3934685863	F	4	45 ACE	SP	CRE		V	6/15/2043
2021	PO3920185774	F	3	55 BRO	SP	CRE	ED,ID	BX	6/16/2043
2021	PO3936585685	LGE	5	35 ACE	SP	CCA		V	6/17/2043
2021	PO3935585720	F	4	40 ACE	SP	CRE		V	6/18/2043
2021	PO3935185704	F	4	40 ACE	SP	CRE		V	6/19/2043
2021	PO3936385698	F	4	40 ACE	SP	A		V	6/20/2043
2021	PO3936885686	F	4	40 ACE	SP	P		V	6/21/2043
2021	PO3935985733	F	3	45 ACE	SP	CCA		V	6/22/2043
2021	PO3936285748	F	4	40 ACE	SP	CRE		V	6/23/2043
2021	PO3936485755	LGE	4	40 ACE	SP	CCA		V	6/24/2043

2021 PO3926685662	F	4	40 ACE	SP	CRE		V		6/25/2043
2021 PO3936885769	F	4	40 ACE	SP	CCA		V		6/26/2043
2021 PO3937485791	F	4	40 ACE	SP	CCA		V		6/27/2043
2021 PO3937985806	F	4	40 ACE	SP	CRE		V		6/28/2043
2021 PO3937185777	LGE	4	40 ACE	SP	CRE		V		6/29/2043
2021 PO3938685812	F	4	40 ACE	SP	CRE		V		6/30/2043
2021 PO3988485731	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD		7/1/2043
2021 PO3965886097	LGE	3	50 ACE	SP	CRE	ED,EP,ID,MD	X	PX	7/2/2043
2021 PO5839611230	KU	6	30 ACW	SP	S		V		7/3/2043
2021 PO6345510079	F	4	35 ACW	SP	S		V		7/4/2043
2021 PO6378109925	F	4	40 ACW	SP	P		V		7/5/2043
2021 PO6247910797	F	4	40 ACW	SP	P		V		7/6/2043
2021 PO6239310781	F	4	40 ACW	SP	P		V		7/7/2043
2021 PO3974985774	F	4	40 ACE	SP	CRE		V		7/8/2043
2021 PO3975785784	F	4	40 ACE	SP	CRE		V		7/9/2043
2021 PO3976485793	F	4	40 ACE	SP	P		V		7/10/2043
2021 PO3932185822	F	3	45 ACE	SP	CCA		V		7/11/2043
2021 PO3931485812	F	3	45 ACE	SP	CCA		V		7/12/2043
2021 PO3931185807	F	4	35 ACE	SP	A		V		7/13/2043
2021 PV3930285794	F	4	40 ACE	SP	A		V		7/14/2043
2021 PO3929785784	F	4	40 ACE	SP	A		V		7/15/2043
2021 PO3929785772	F	4	40 ACE	SP	CCA		V		7/16/2043
2021 PO3928285762	F	4	40 ACE	SP	CCA		V		7/17/2043
2021 PO3977085820	LGE	4	40 ACE	SP	CRE	ED,ID	TD		7/18/2043
2021 PO3977785801	F	4	40 ACE	SP	P		V		7/19/2043
2021 PO5252730566	KU	4	35 BRN	SP	CRE	ID	TD		7/20/2043
2021 PO3924885896	F	3	45 BRO	SP	CCA		V		7/21/2043
2021 PO3924385889	LGE	4	30 BRO	SP	CRE	ED,ID	TD		7/22/2043
2021 PO3923185830	F	4	40 BRO	SP	CRE		V		7/23/2043
2021 PO3933085838	F	3	45 ACE	SP	CCA		V		7/24/2043
2021 PO3933885850	F	3	45 ACE	SP	CCA		V		7/25/2043
2021 PO3923185869	F	4	40 BRO	SP	CRE	ED,ID,RB	BX	RP3	7/26/2043
2021 PO3922285854	F	4	40 BRO	SP	CRE		V		7/27/2043
2021 PO3921385841	F	4	40 BRO	SP	CRE		V		7/28/2043
2021 PO3920685829	F	4	40 BRO	SP	CRE		V		7/29/2043
2021 PO3919985817	F	4	40 BRO	SP	CRE		V		7/30/2043
2021 PO3953885755	F	4	40 ACE	SP	CCA		V		7/31/2043
2021 PO3954485762	F	4	40 ACE	SP	A		V		8/1/2043
2021 PO3955485773	F	4	40 ACE	SP	A		V		8/2/2043
2021 PO3956385785	F	4	40 ACE	SP	CCA		V		8/3/2043
2021 PO3957285797	F	4	40 ACE	SP	A		V		8/4/2043
2021 PO3958285809	F	4	40 ACE	SP	A		V		8/5/2043
2021 PO3959085819	F	4	40 ACE	SP	A		V		8/6/2043
2021 PO3930585755	F	4	40 ACE	SP	A		V		8/7/2043
2021 PO3931185765	F	3	45 ACE	SP	CCA		V		8/8/2043
2021 PO5241930605	KU	4	40 BRN	SP	CRE		V		8/9/2043
2021 PO5225930663	KU	4	40 BRN	SP	CRE	ID	BD		8/10/2043
2021 PO5224530779	KU	3	45 BRN	SP	CRE	ID	TD		8/11/2043
2021 PO3917785829	F	4	40 BRO	SP	CRE		V		8/12/2043
2021 PO3918485841	F	4	40 BRO	SP	CRE		V		8/13/2043
2021 PO3918985848	F	4	40 BRO	SP	CRE		V		8/14/2043
2021 PO7016168682	LGE	4	35 ACE	SP	CCA		V		8/15/2043
2021 PO3986985710	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		8/16/2043
2021 PO3919585858	F	4	40 BRO	SP	CRE		V		8/17/2043

2021 PO3920185867	F	4	40 BRO	SP	CRE		V	8/18/2043	
2021 PO3920785877	F	4	40 BRO	SP	CRE		V	8/19/2043	
2021 PO3921485888	F	4	40 BRO	SP	CRE		V	8/20/2043	
2021 PO3922285900	F	4	40 BRO	SP	CRE		V	8/21/2043	
2021 PO3985685714	LGE	4	35 ACE	SP	CCA		V	8/22/2043	
2021 PO3980985748	LGE	4	35 ACE	SP	CRE	ED,ID	TD	8/23/2043	
2021 PO3921485930	F	5	30 BRO	SP	CRE		V	8/24/2043	
2021 PO6233710310	F	4	40 ACW	SP	P		V	8/25/2043	
2021 PO6228310227	KU	3	50 ACW	SP	S		V	8/26/2043	
2021 PO6237010282	F	3	50 ACW	SP	S		V	8/27/2043	
2021 PO6204710809	F	4	40 ACW	SP	P		V	8/28/2043	
2021 PO6199010295	F	4	40 ACW	SP	S		V	8/29/2043	
2021 PO6203410572	F	4	40 ACW	SP	P		V	8/30/2043	
2021 PO6201610457	F	4	40 ACW	SP	P		V	8/31/2043	
2021 PO6199810360	F	4	40 ACW	SP	S		V	9/1/2043	
2021 PO6206210264	F	4	40 ACW	SP	P		V	9/2/2043	
2021 PO6205110917	F	4	40 ACW	SP	P		V	9/3/2043	
2021 PO6203911027	F	4	40 ACW	SP	P		V	9/4/2043	
2021 PO6204011095	F	4	40 ACW	SP	P		V	9/5/2043	
2021 PO6192711051	F	4	40 ACW	SP	P		V	9/6/2043	
2021 PO6184511061	F	4	40 ACW	SP	P		V	9/7/2043	
2021 PO6177711069	F	4	40 ACW	SP	S		V	9/8/2043	
2021 PO6170811076	F	4	40 ACW	SP	P		V	9/9/2043	
2021 PO6164211082	KU	4	45 ACW	SP	S		V	9/10/2043	
2021 PO6221211712	F	4	40 ACW	SP	P		V	9/11/2043	
2021 PO6219911406	F	4	40 ACW	SP	P		V	9/12/2043	
2021 PO6219611295	F	4	40 ACW	SP	S		V	9/13/2043	
2021 PO6312611362	KU	4	45 ACW	SP	S		V	9/14/2043	
2021 PO5443836415	KU	2	50 UNK	SP	CRE	IP	TX	RR	9/15/2043
2021 PO5445736702	KU	4	40 UNK	SP	CRE	ED,ID,IP	BX	RP1	9/16/2043
2021 PO5399636103	KU	5	35 UNK	SP	CRE	ID	BD	9/17/2043	
2021 PO3985685751	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	9/18/2043	
2021 PO3984085757	LGE	4	35 ACE	SP	P	ED,ID	TD	9/19/2043	
2021 PO3985285747	LGE	4	35 ACE	SP	CRE	ED,ID	BD	9/20/2043	
2021 PO4076186250	LGE	5	30 BRO	SP	CRE		V	9/21/2043	
2021 PO4076286263	LGE	UNK	65 BRO	SP	CRE		V	9/22/2043	
2021 PO4074686264	F	UNK	45 BRO	SP	CRE		V	9/23/2043	
2021 PO4076986270	F	5	35 BRO	SP	CRE		V	9/24/2043	
2021 PO3982785764	LGE	4	35 ACE	SP	CCA		V	9/25/2043	
2021 PO4078186262	LGE	UNK	60 BRO	SP	CRE		V	9/26/2043	
2021 PO4079486261	LGE	UNK	60 BRO	SP	CRE		V	9/27/2043	
2021 PO4078186269	F	5	35 BRO	SP	CRE		V	9/28/2043	
2021 PO4079386268	F	5	35 BRO	SP	CRE		V	9/29/2043	
2021 PO4080686267	F	4	35 BRO	SP	CRE		V	9/30/2043	
2021 PO4080786260	LGE	UNK	60 BRO	SP	CRE		V	10/1/2043	
2021 PO4081786266	F	5	35 BRO	SP	CRE		V	10/2/2043	
2021 PO4082986265	F	4	35 BRO	SP	CRE		V	10/3/2043	
2021 PO4084186264	F	5	35 BRO	SP	CRE		V	10/4/2043	
2021 PO4081986259	LGE	UNK	60 BRO	ST	P		V	10/5/2043	
2021 PO4083186258	LGE	UNK	60 BRO	SP	CRE		V	10/6/2043	
2021 PO4083886257	LGE	UNK	60 BRO	SP	CRE		V	10/7/2043	
2021 PO6737272554	LGE	1	50 ACE	SP	CCA		V	10/8/2043	
2021 PO5416536227	KU	5	35 KOP	SP	CRE	ID	BD	10/9/2043	
2021 PO5401036247	KU	5	35 KOP	SP	CRE	ID	BD	10/10/2043	

2021 PO5417136084	KU	3	45 BRO	SP	CCA			V		10/11/2043
2021 PO5441636153	KU	1	50 UNK	SP	CRE		ED,ID	BX	RP1	10/12/2043
2021 PO5441035815	KU	1	75 UNK	SP	CRE		ID	BD		10/13/2043
2021 PO5440735613	KU	4	40 BRO	SP	CCA			V		10/14/2043
2021 PO5440535497	KU	2	50 BRO	SP	CCA			B		10/15/2043
2021 PO5465535477	KU	2	60 UNK	SP	CRE		ED	BX	RP1	10/16/2043
2021 PO5527335429	KU	3	50 UNK	SP	CRE		ID	BD		10/17/2043
2021 PO3983585854	LGE	4	35 ACE	SP	CRE		ED,ID,IP	TD		10/18/2043
2021 PO3966086153	LGE	3	50 ACE	SP	CRE		ED,ID	BD		10/19/2043
2021 PO3944686332	LGE	4	40 ACE	SP	CCA			V		10/20/2043
2021 PO3944386363	LGE	4	30 ACE	SP	CCA			V		10/21/2043
2021 PO3984785851	LGE	4	30 ACE	SP	CRE		ED,ID,IP	TD		10/22/2043
2021 PO5062231001	KU	3	45 BRN	SP	CCA			V		10/23/2043
2021 PO3984085846	LGE	4	35 ACE	SP	P		ED,ID,IP	TD		10/24/2043
2021 PO3923885919	LGE	5	30 BRO	SP	A		ED,ID	TD		10/25/2043
2021 PO5288637308	F	4	35 ACW	SP	CRE		HH	BX	PX	10/26/2043
2021 PO5273830659	KU	4	45 BRN	SP	CRE		ID	TD		10/27/2043
2021 PO5869011944	KU	5	45 ACW	SP	S			V		10/28/2043
2021 PO5859011942	KU	4	40 ACW	SP	S			V		10/29/2043
2021 PO5877311740	KU	5	45 ACW	SP	S			V		10/30/2043
2021 PO4038886263	LGE	4	40 ACE	SP	P		ED,ID,IP	TD		10/31/2043
2021 PO4036986268	LGE	4	35 ACE	SP	P		ED,ID,IP	TD		11/1/2043
2021 PO4036086271	LGE	4	40 ACE	SP	P		ED,ID	TD		11/2/2043
2021 PO4035086274	LGE	4	40 ACE	SP	CRE		ED,ID,IP	TD		11/3/2043
2021 PO4034086277	LGE	4	40 ACE	SP	P		ED,ID	BD		11/4/2043
2021 PO4032686277	LGE	4	40 ACE	SP	CRE		ED,ID,IP	TD		11/5/2043
2021 PO4029586284	LGE	4	40 ACE	SP	CRE		ED,ID	TD		11/6/2043
2021 PO3977685782	F	3	45 ACE	SP	CCA			V		11/7/2043
2021 PO3968885704	F	4	40 ACE	SP	CRE			V		11/8/2043
2021 PO3969585698	F	4	40 ACE	SP	CRE			V		11/9/2043
2021 PO3921085924	F	4	40 BRO	SP	CRE			V		11/10/2043
2021 PO3920585914	F	4	40 BRO	SP	CRE			V		11/11/2043
2021 PO3919885895	F	4	40 BRO	SP	CRE			V		11/12/2043
2021 PO3915685835	F	4	40 BRO	SP	CRE			V		11/13/2043
2021 PO3916785852	F	3	45 BRO	SP	CCA			V		11/14/2043
2021 PO3917885870	F	4	40 BRO	SP	CRE			V		11/15/2043
2021 PO3918485880	F	4	40 BRO	SP	CCA			V		11/16/2043
2021 PO3982485749	LGE	4	40 ACE	SP	CCA			V		11/17/2043
2021 PO3917285839	LGE	4	35 BRO	SP	CRE		ED,ID	TD		11/18/2043
2021 PO3914485816	F	3	45 BRO	SP	CCA			V		11/19/2043
2021 PO3915185827	F	4	40 BRO	SP	CCA			V		11/20/2043
2021 PO3914185811	F	6	25 BRO	SP	CRE			V		11/21/2043
2021 PO5433736993	KU	5	35 UNK	SP	CRE		ID	BD		11/22/2043
2021 PO5433637150	KU	2	45 UNK	SP	CCA			V		11/23/2043
2021 PO3985485727	LGE	4	35 ACE	SP	CCA			V		11/24/2043
2021 PO3931585762	LGE	4	30 ACE	SP	CCA			V		11/25/2043
2021 PO3932085779	F	3	45 ACE	SP	CCA			V		11/26/2043
2021 PO3932485795	F	3	45 ACE	SP	CCA			V		11/27/2043
2021 PO3933485799	F	4	40 ACE	SP	P			V		11/28/2043
2021 PO5042924829	KU	6	30 BRO	SP	CRE			T		11/29/2043
2021 PO4469788388	LGE	4	30 ACE	DF	CRE		ED,ID	BD		11/30/2043
2021 PO4470788392	LGE	4	30 ACE	SP	CRE		ED,ID	TD		12/1/2043
2021 PO5050324822	KU	4	40 BRO	SP	CCA			V		12/2/2043
2021 PO5051624691	KU	4	40 BRO	SP	CRE		ED	BD		12/3/2043

2021 PO5052324625	KU	4	40 BRO	SP	CCA		V	12/4/2043
2021 PO5051224735	KU	6	30 BRO	SP	CRE	ED	BD	12/5/2043
2021 PO4316516360	KU	3	45 BRN	SP	CRE		T	12/6/2043
2021 PO4045884622	F	4	30 BRO	SP	CCA		V	12/7/2043
2021 PO4048684627	F	4	40 BRO	SP	CRE		V	12/8/2043
2021 PO4043584626	F	3	45 BRO	SP	CCA		V	12/9/2043
2021 PO4047384621	F	4	30 BRO	SP	P		V	12/10/2043
2021 PO4047184627	F	3	45 BRO	SP	CCA		V	12/11/2043
2021 PO4048684622	F	4	35 BRO	SP	CCA		V	12/12/2043
2021 PO4049984622	F	4	30 BRO	SP	CRE		V	12/13/2043
2021 PO4049884627	F	4	40 BRO	SP	CCA		V	12/14/2043
2021 PO4472088398	LGE	4	40 ACE	DF	CRE	ED,ID	TD	12/15/2043
2021 PO4471188394	LGE	4	40 ACE	DF	CRE	ED,ID	BD	12/16/2043
2021 PO2562988402	KU	3	40 BRO	SP	CCA		V	12/17/2043
2021 PO2818988038	KU	6	30 BRO	SP	CCA		V	12/18/2043
2021 PO2559588500	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	12/19/2043
2021 PO2582188312	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	12/20/2043
2021 PO5046324685	KU	6	30 BRO	SP	CRE		T	12/21/2043
2021 PO3983085645	LGE	4	45E ACE	SP	CRE	ED,IP	BD	12/22/2043
2021 PO3982885641	LGE	4	45E ACE	SP	CRE	ED,ID	BD	12/23/2043
2021 PO3984685673	LGE	4	30 ACE	SP	P	ED	BD	12/24/2043
2021 PO3984885667	LGE	4	45E ACE	SP	CRE	ED,IP,MD	BD	12/25/2043
2021 PO8613184382	KU	4	40 ACE	SP	CRE	ED,ID	BD	12/26/2043
2021 PO4993108151	F	3	40 BRN	SP	S		V	12/27/2043
2021 PO8613584193	KU	5	35 ACE	SP	CRE	ID,RB	BX PX	12/28/2043
2021 PO5163909676	KU	4	45 BRN	SP	CCA		V	12/29/2043
2021 PO5156309845	KU	5	35 BRN	SP	CCA		V	12/30/2043
2021 PO5151709974	KU	4	40 BRN	SP	CCA		V	12/31/2043
2021 PO5152509996	KU	2	70 BRN	SP	CRE	ID	BD	1/1/2044
2021 PO4106284029	LGE	4	45 ACE	SP	A		V	1/2/2044
2021 PO4106084032	LGE	4	45 ACE	SP	A		V	1/3/2044
2021 PO4100184076	LGE	4	40 ACE	SP	CCA		V	1/4/2044
2021 PO4095584091	LGE	4	40 ACE	SP	CCA		V	1/5/2044
2021 PO5047008729	F	4	40 BRN	SP	P		V	1/6/2044
2021 PO5052308691	F	4	40 BRN	SP	P		V	1/7/2044
2021 PO5063308635	F	4	40 BRN	SP	P		V	1/8/2044
2021 PO5071208595	F	4	40 BRN	DF	CRE		V	1/9/2044
2021 PO5011508156	F	4	40 BRN	SP	P		V	1/10/2044
2021 PO4074116323	KU	3	45 BRN	SP	CCA		V	1/11/2044
2021 PO4099484082	LGE	4	30 ACE	SP	CCA		V	1/12/2044
2021 PO4097984084	LGE	4	40 ACE	SP	CCA		V	1/13/2044
2021 PO4079116439	KU	3	45 BRN	SP	CCA		T	1/14/2044
2021 PO5165410230	KU	2	70 BRN	SP	CRE	ID	BD	1/15/2044
2021 PO5171210413	KU	1	75 BRN	SP	CRE	ID	TD	1/16/2044
2021 PO5147811382	KU	5	35 BRN	SP	CRE	ID	BD	1/17/2044
2021 PO5152911489	KU	4	40 BRN	SP	CRE	ID	TD	1/18/2044
2021 PO5086711052	KU	5	35 BRN	SP	CRE	ID	TD	1/19/2044
2021 PO5098211272	KU	6	30 BRN	SP	CRE	ED,EP,ID	TX RR	1/20/2044
2021 PO5060111488	KU	4	40 BRN	SP	CRE	ID	TD	1/21/2044
2021 PO5036111555	KU	4	45 BRN	SP	CRE	ID	TD	1/22/2044
2021 PO5043011695	KU	4	45 BRN	SP	CRE	ID	TD	1/23/2044
2021 PO5054812605	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/24/2044
2021 PO5034012685	KU	6	30 BRN	SP	CRE	ID	TD	1/25/2044
2021 PO2757187586	KU	4	40 BRO	SP	CCA		T	1/26/2044



2021 PO2763287678	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	1/27/2044
2021 PO7946885413	KU	4	40 ACE	SP	CRE	ED,ID	BD	1/28/2044
2021 PO7966885366	KU	4	40 ACE	SP	CCA		V	1/29/2044
2021 PO7968385431	KU	4	40 ACE	SP	CCA		V	1/30/2044
2021 PO7993685504	KU	4	40 ACE	SP	CCA		V	1/31/2044
2021 PO8018785563	KU	4	40 ACE	SP	CCA		V	2/1/2044
2021 PO8042485617	KU	4	45 ACE	SP	CCA		V	2/2/2044
2021 PO2907588994	KU	4	45 BRO	SP	CRE	ED,IP,SRS	TD	2/3/2044
2021 PO8072885369	KU	5	35 ACE	SP	CCA		V	2/4/2044
2021 PO8068985451	KU	4	40 ACE	SP	CCA		V	2/5/2044
2021 PO8095185257	KU	4	45 ACE	SP	CCA		V	2/6/2044
2021 PO8093385077	KU	4	45 ACE	SP	CCA		V	2/7/2044
2021 PO8110585089	KU	3	50 ACE	SP	CCA		V	2/8/2044
2021 PO2899089011	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	2/9/2044
2021 PO2889988881	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	2/10/2044
2021 PO4436587812	LGE	4	40 BRO	SP	CCA		V	2/11/2044
2021 PO160090272	LGE	4	40 BRO	SP	CCA		V	2/12/2044
2021 PO4449387799	LGE	4	40 BRO	SP	CRE		V	2/13/2044
2021 PO2899988646	KU	4	40 BRO	SP	CRE	ED	T	2/14/2044
2021 PO2887488722	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	2/15/2044
2021 PO4449387803	LGE	4	40 BRO	SP	CRE	ID,IP	BD	2/16/2044
2021 PO4450087811	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/17/2044
2021 PO4449787812	LGE	3	45 BRO	SP	A	ED,ID	TD	2/18/2044
2021 PO4449087812	LGE	3	45 BRO	SP	CCA		V	2/19/2044
2021 PO4448087812	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/20/2044
2021 PO4447187813	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	2/21/2044
2021 PO4445287812	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	2/22/2044
2021 PO4445887812	LGE	4	40 BRO	SP	CCA		V	2/23/2044
2021 PO4444387812	LGE	4	40 BRO	SP	CCA		V	2/24/2044
2021 PO4467987752	LGE	4	40 BRO	SP	CRE	ID,IP	BD	2/25/2044
2021 PO4467187764	LGE	4	40 BRO	SP	CRE		V	2/26/2044
2021 PO4482887496	LGE	4	40 BRO	SP	CCA		V	2/27/2044
2021 PO4481587488	LGE	4	40 BRO	SP	CRE	ID,IP	BD	2/28/2044
2021 PO4480887453	LGE	3	45 BRO	SP	CCA		V	2/29/2044
2021 PO4481087459	LGE	4	35 BRO	SP	A	ID,IP	BD	3/1/2044
2021 PO4481687462	LGE	3	45 BRO	SP	CRE	ID,IP	BD	3/2/2044
2021 PO8611883802	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	3/3/2044
2021 PO4490388543	LGE	4	35 ACE	SP	CCA		V	3/4/2044
2021 PO4489888552	LGE	4	35 ACE	SP	CCA		V	3/5/2044
2021 PO4489288563	LGE	4	40 ACE	SP	CCA		V	3/6/2044
2021 PO5025408845	KU	6	30 BRN	SP	S		V	3/7/2044
2021 PO5029508824	F	5	30 BRN	SP	S		V	3/8/2044
2021 PO5039608767	F	5	30 BRN	SP	CRE		V	3/9/2044
2021 PO4265711750	KU	3	45 BRN	SP	CCA		V	3/10/2044
2021 PO4249211046	KU	2	55 BRN	SP	CCA		T	3/11/2044
2021 PO4488588573	LGE	4	40 ACE	SP	CRE	ED,ID	BD	3/12/2044
2021 PO4488888575	LGE	4	25 ACE	SP	A	ED,ID	TD	3/13/2044
2021 PO8547783793	F	4	40 ACE	SP	CRE		V	3/14/2044
2021 PO4258311419	KU	2	50 BRN	SP	CCA		V	3/15/2044
2021 PO4457487800	LGE	4	30 BRO	SP	CCA		V	3/16/2044
2021 PO5085008442A	KU	4	30 BRN	SP	P	ED,ID	TD	3/17/2044
2021 PO5092208405	KU	6	30 BRN	SP	CRE	ED,ID	BD	3/18/2044
2021 PO5098708361	KU	6	30 BRN	SP	CRE		V	3/19/2044
2021 PO4249610704	KU	3	45 BRN	SP	CCA		V	3/20/2044

2021	PO5297112691	KU	4	40 BRN	SP	CRE	ID	TD		3/21/2044
2021	PO5274414491	KU	2	50 BRN	SP	CRE	HH,ID,RB	X	PX	3/22/2044
2021	PO5308614635	F	3	55 BRN	SP	CRE		V		3/23/2044
2021	PO5324514648	F	4	40 BRN	SP	CRE		V		3/24/2044
2021	PO5344414666	F	4	40 BRN	SP	CRE		V		3/25/2044
2021	PO5365514681	F	4	40 BRN	SP	P		V		3/26/2044
2021	PO5387714710	F	4	40 BRN	SP	P		V		3/27/2044
2021	PO5398814564	F	4	40 BRN	SP	P		V		3/28/2044
2021	PO5409514426	F	4	40 BRN	SP	P		V		3/29/2044
2021	PO5421014277	F	4	40 BRN	SP	P		V		3/30/2044
2021	PO4191510204	KU	2	50 BRN	SP	CCA		T		3/31/2044
2021	PO4251811138	KU	2	50 BRN	SP	CRE	ID	TD		4/1/2044
2021	PO4480287973	F	4	40 BRO	SP	P		V		4/2/2044
2021	PO4485187955	F	4	35 BRO	SP	A		V		4/3/2044
2021	PO4485887958	F	4	35 BRO	SP	CRE		V		4/4/2044
2021	PO4487587965	F	4	35 BRO	SP	A		V		4/5/2044
2021	PO4488787971	F	4	30 BRO	SP	P		V		4/6/2044
2021	PO4488287980	F	4	30 BRO	SP	P		V		4/7/2044
2021	PO4487487991	F	4	30 BRO	SP	CCA		V		4/8/2044
2021	PO4486287997	F	4	30 BRO	SP	CCA		V		4/9/2044
2021	PO4485187992	F	4	30 BRO	SP	P		V		4/10/2044
2021	PO4484087987	F	4	35 BRO	SP	P		V		4/11/2044
2021	PO4481687977-A	F	4	30 BRO	SP	P		V		4/12/2044
2021	PO4482987983	F	4	30 BRO	SP	P		V		4/13/2044
2021	PO4481687977	F	4	35 BRO	SP	CRE		V		4/14/2044
2021	PO4479788006	F	3	45 BRO	SP	CCA		V		4/15/2044
2021	PO4480588009	F	3	45 BRO	SP	CCA		V		4/16/2044
2021	PO4997908868	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		4/17/2044
2021	PO4491588512	LGE	4	45 ACE	SP	CRE	ED,ID	BD		4/18/2044
2021	PO4491288521	LGE	4	40 ACE	SP	CCA		V		4/19/2044
2021	PO4490888532	LGE	4	35 ACE	SP	CCA		V		4/20/2044
2021	PO5103908330	KU	6	30 BRN	SP	S		V		4/21/2044
2021	PO5110908283	F	5	35 BRN	SP	S		V		4/22/2044
2021	PO5117008242	F	5	35 BRN	SP	S		V		4/23/2044
2021	PO5121208202	KU	5	35 BRN	SP	S		V		4/24/2044
2021	PO4487788583	LGE	4	40 ACE	SP	CRE	ED,ID	BD		4/25/2044
2021	PO8610683678	KU	4	40 ACE	SP	CRE	ED,ID	BD		4/26/2044
2021	PO4942824181	KU	4	45 BRO	SP	CRE	ED	BD		4/27/2044
2021	PO8518683467	F	4	40 ACE	SP	CRE		V		4/28/2044
2021	PO8498383955	F	4	40 ACE	SP	CRE		V		4/29/2044
2021	PO4959324090	KU	4	40 BRO	SP	CRE	ED,ID,RB	BX	RP2	4/30/2044
2021	PO4461287827	LGE	4	40 BRO	SP	CCA		V		5/1/2044
2021	PO4459487816	LGE	3	50 BRO	SP	A	ID,IP	BD		5/2/2044
2021	PO4458287811	LGE	3	50 BRO	SP	CRE	ED,ID	TD		5/3/2044
2021	PO4954423304	KU	4	40 BRO	SP	CRE		T		5/4/2044
2021	PO4486888589	LGE	4	40 ACE	SP	CRE	ED,ID	BD		5/5/2044
2021	PO4485588597	LGE	4	40 ACE	SP	CRE	ED,ID	BD		5/6/2044
2021	PO4971123329	KU	4	40 BRO	SP	CRE	ED	BD		5/7/2044
2021	PO4977423193	KU	4	40 BRO	SP	CRE	ED	BD		5/8/2044
2021	PO4970923108	KU	4	40 BRO	SP	CRE	ED	BD		5/9/2044
2021	PO4457587812	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		5/10/2044
2021	PO7664594121	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		5/11/2044
2021	PO5093208501	KU	5	35 BRN	DF	CRE	ED,ID	TD		5/12/2044
2021	PO5107108425	KU	5	35 BRN	SP	CRE	ED,ID	TD		5/13/2044

2021 PO5118908360	KU	5	35 BRN	SP	CRE	ED,ID,SRC	TX	RR	5/14/2044
2021 PO7676193901	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		5/15/2044
2021 PO4277911705	KU	3	45 BRN	SP	CRE	ID	TD		5/16/2044
2021 PO4480587994	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX	5/17/2044
2021 PO4479687990	LGE	4	40 BRO	SP	P	ED,ID	BD		5/18/2044
2021 PO4480687990	LGE	4	35 BRO	SP	P	ED,ID	TD		5/19/2044
2021 PO4481487998	LGE	4	40 BRO	SP	CRE	ED,ID	TD		5/20/2044
2021 PO4482488002	LGE	4	40 BRO	SP	CRE	ED,ID	BD		5/21/2044
2021 PO4482587998	LGE	4	35 BRO	SP	A	ED,ID	TD		5/22/2044
2021 PO4483388006	LGE	4	40 BRO	SP	CRE	ED,ID	TD		5/23/2044
2021 PO4484488554	LGE	4	40 ACE	SP	CCA		V		5/24/2044
2021 PO4484988546	LGE	4	40 ACE	SP	A	ED,ID	BD		5/25/2044
2021 PO4485488539	LGE	4	40 ACE	SP	A	ED,ID	BD		5/26/2044
2021 PO5457113733	KU	3	45 BRN	SP	CRE	ED,HH,ID,IP	X	RP2	5/27/2044
2021 PO5457013822	KU	1	65 BRN	SP	CCA		V		5/28/2044
2021 PO5461413767	KU	1	65 BRN	SP	CCA		V		5/29/2044
2021 PO5466113647	KU	4	40 BRN	SP	P	ID	TD		5/30/2044
2021 PO5457113733A	KU	5	35 BRN	SP	CCA	ED	T		5/31/2044
2021 PO5478813890	KU	3	55 BRN	SP	CCA		V		6/1/2044
2021 PO5479613865	KU	3	55 BRN	SP	CCA		V		6/2/2044
2021 PO5484013703	F	4	40 BRN	SP	CRE		V		6/3/2044
2021 PO5489613561	F	4	40 BRN	SP	CRE		V		6/4/2044
2021 PO5492713419	F	4	40 BRN	SP	CRE		V		6/5/2044
2021 PO5503813285	F	4	45 BRN	SP	CCA		V		6/6/2044
2021 PO5503713182	F	3	45 BRN	SP	P		V		6/7/2044
2021 PO5457512262	F	5	35 BRN	SP	P		V		6/8/2044
2021 PO5422612435	KU	3	45 BRN	SP	CRE	ID	BD		6/9/2044
2021 PO5394912005	KU	4	35 BRN	SP	CRE	ID,IP	TD		6/10/2044
2021 PO5411111698	KU	5	35 BRN	SP	CRE	ED,ID	X	RP3	6/11/2044
2021 PO5406911658	F	5	35 BRN	SP	CRE		V		6/12/2044
2021 PO5379911745	F	5	35 BRN	SP	CCA		V		6/13/2044
2021 PO5056513128	KU	4	40 BRN	SP	CRE		V		6/14/2044
2021 PO4459687813	LGE	4	35 BRO	SP	CCA		V		6/15/2044
2021 PO4485888531	LGE	4	40 ACE	SP	A	ED,ID	BD		6/16/2044
2021 PO4457587807	LGE	4	30 BRO	SP	CRE	ID,IP	BD		6/17/2044
2021 PO4486488523	LGE	4	40 ACE	SP	CCA	ED,ID	BD		6/18/2044
2021 PO7808791519	KU	5	35 ACE	SP	CRE		V		6/19/2044
2021 PO4486988515	LGE	3	45 ACE	SP	CCA		V		6/20/2044
2021 PO4452787811	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		6/21/2044
2021 PO4453887811	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		6/22/2044
2021 PO4287311680	KU	3	45 BRN	SP	CCA		T		6/23/2044
2021 PO4486788502	LGE	4	40 ACE	SP	CRE	ED,ID	BD		6/24/2044
2021 PO4486088497	LGE	4	40 ACE	SP	CCA		V		6/25/2044
2021 PO4485188491	LGE	4	40 ACE	SP	CRE	ED,ID	BD		6/26/2044
2021 PO2790088939	KU	5	30 BRO	SP	CRE	ED,IP	BD		6/27/2044
2021 PO4484388486	LGE	3	45 ACE	SP	CRE	ED,ID	BD		6/28/2044
2021 PO4484288480	LGE	4	30 ACE	SP	A	ED,ID	TD		6/29/2044
2021 PO4482688476	F	3	45 ACE	SP	CCA		V		6/30/2044
2021 PO4483488460	F	3	45 ACE	SP	CCA		V		7/1/2044
2021 PO4484288450	F	3	45 ACE	SP	CCA		V		7/2/2044
2021 PV4475888534	LGE	4	40 ACE	SP	A	ED,ID	BD		7/3/2044
2021 PO4477088542	LGE	4	35 ACE	SP	CRE	ED,ID	BD		7/4/2044
2021 PO4450887806	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		7/5/2044
2021 PO5103207957A	KU	4	40 BRN	SP	CRE	ED,ID	BD		7/6/2044

2021	PO5103207957	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/7/2044
2021	PO5090808056	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/8/2044
2021	PO5079408140	KU	3	45 BRN	SP	S		V	7/9/2044
2021	PO5069008215	KU	4	40 BRN	SP	S		V	7/10/2044
2021	PO5054208265	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/11/2044
2021	PO5057908296	KU	4	40 BRN	SP	S		V	7/12/2044
2021	PO5047908204	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/13/2044
2021	PO4477788532	LGE	4	40 ACE	SP	CRE	ED,ID	BD	7/14/2044
2021	PO5036408092	KU	4	40 BRN	SP	CRE	ED,ID	BD	7/15/2044
2021	PO4451487807	LGE	4	30 BRO	SP	CCA		V	7/16/2044
2021	PO4478588519	LGE	4	40 ACE	SP	CRE	ED,ID	TD	7/17/2044
2021	PO4477488540	LGE	4	30 ACE	SP	CCA		V	7/18/2044
2021	PO2802688844	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	7/19/2044
2021	PO2812688816	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	7/20/2044
2021	PO2815788930	KU	4	40 BRO	SP	CRE	ED,IP,SRS	BD	7/21/2044
2021	PO4476588544	LGE	4	25 ACE	SP	CRE		V	7/22/2044
2021	PO4450787796	LGE	4	40 BRO	SP	A	ID,IP	BD	7/23/2044
2021	PO4451287796	LGE	4	30 BRO	SP	A	ID	BD	7/24/2044
2021	PO4479288508	LGE	4	40 ACE	SP	CRE	ED,ID	BD	7/25/2044
2021	PO4479888498	LGE	4	35 ACE	SP	A	ED,ID	TD	7/26/2044
2021	PO4480288491	LGE	4	40 ACE	SP	CRE	ED,ID	BD	7/27/2044
2021	PO4971023860	KU	2	40 BRO	SP	CRE	ED	BD	7/28/2044
2021	PO4971124024	KU	2	40 BRO	SP	CRE	ED	BD	7/29/2044
2021	PO7725593012	KU	5	35 ACE	SP	CRE	ED,ID	TD	7/30/2044
2021	PO7736792808	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX PX	7/31/2044
2021	PO4298311542	KU	7	30 BRN	SP	CCA		V	8/1/2044
2021	PO4311911560	KU	7	35 BRN	SP	CCA		T	8/2/2044
2021	PO4982624030	KU	2	40 BRO	SP	CRE	ED	BD	8/3/2044
2021	PO4992024168	KU	4	40 BRO	UN	CRE		V	8/4/2044
2021	PO4995624222	KU	4	40 BRO	SP	CRE	ED	BD	8/5/2044
2021	PO8032787165	F	6	30 ACE	SP	CCA		V	8/6/2044
2021	PO4481988015	F	4	35 BRO	SP	CCA		V	8/7/2044
2021	3735865786	KU	3	45 BRN	SP	CCA		V	8/8/2044
2021	PO3591256275	KU	4	45 BRN	SP	CRE	ID	BD	8/9/2044
2021	PO3588856420	KU	2	45 BRN	SP	CCA		V	8/10/2044
2021	PO3567156717	KU	2	50 BRN	SP	CCA		V	8/11/2044
2021	PO3558157172	KU	4	40 BRN	SP	CCA		V	8/12/2044
2021	PO3554557350	KU	4	40 BRN	SP	CCA		V	8/13/2044
2021	PO3552057493	KU	4	40 BRN	SP	CCA		V	8/14/2044
2021	PO3548257661	KU	4	40 BRN	SP	CCA		V	8/15/2044
2021	PO3545157816	KU	4	40 BRN	SP	CCA		V	8/16/2044
2021	PO3542157969	KU	4	40 BRN	SP	CCA		V	8/17/2044
2021	PO3539358084	KU	4	40 BRN	SP	CCA		V	8/18/2044
2021	PO3530258375	KU	4	40 BRN	SP	CCA		V	8/19/2044
2021	PO49333527057	KU	5	35 BRN	SP	CRE	ED,ID	BX PX	8/20/2044
2021	PO4947326616	F	4	40 BRN	SP	P	ED,ID	BX RP3	8/21/2044
2021	PO4951226311	F	4	40 BRN	SP	P	ED,ID	BX RP3	8/22/2044
2021	PO4946126172	KU	5	35 BRN	SP	P	ED,ID	X RP2	8/23/2044
2021	PO3802638318	KU	4	40 KOP	SP	CRE	ID	BD	8/24/2044
2021	PO3801337744	KU	3	50 BRO	SP	CRE	ID	TD	8/25/2044
2021	PO3795737749	KU	3	50 UNK	SP	CRE	ID	TD	8/26/2044
2021	PO4167685974	F	4	40 BRO	SP	CRE		V	8/27/2044
2021	PO4167585965	F	4	40 BRO	SP	A		V	8/28/2044
2021	PO4116685352	LGE	4	35 BRO	SP	CCA		B	8/29/2044

2021 PO3813209886	KU	4	45 XXX	SP	CRE	ID	BD	8/30/2044
2021 PO3841609699	KU	4	40 BRN	SP	CCA		V	8/31/2044
2021 PO3807309768	KU	2	50 XXX	SP	P		V	9/1/2044
2021 PO3810809762	KU	3	50 BRN	SP	CCA		V	9/2/2044
2021 PO5601514657	KU	6	35 BRN	SP	CCA		V	9/3/2044
2021 PO4939726624	KU	4	40 BRN	SP	CCA		V	9/4/2044
2021 PO4166985944	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	9/5/2044
2021 PO4162985888	F	4	40 BRO	SP	A		V	9/6/2044
2021 PO3899340145	KU	4	40 INP	SP	CRE	ID	TD	9/7/2044
2021 PO4162985877	F	4	40 BRO	SP	CCA		V	9/8/2044
2021 PO4087385224	LGE	3	45 ACE	SP	P	ED,ID	TD	9/9/2044
2021 PO4085685194	LGE	1	90 ACE	SP	CRE	ED,HH,ID,RB	BX PX	9/10/2044
2021 PO4837026096	F	4	40 BRN	SP	P		V	9/11/2044
2021 PO4826526155	F	4	40 BRN	SP	P		V	9/12/2044
2021 PO4827526095	F	4	40 BRN	SP	P		V	9/13/2044
2021 PO4070385328	LGE	4	45 BRN	SP	CRE	ED,ID,IP	TD	9/14/2044
2021 PO3907313458	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	9/15/2044
2021 PO3896213459	KU	6	30 XXX	SP	CRE	ED,ID	TD	9/16/2044
2021 PO5679215271	KU	3	45 BRN	SP	CCA		V	9/17/2044
2021 PO5562814833	KU	3	45 BRN	SP	CRE	ED,ID	TD	9/18/2044
2021 PO5593714923	KU	3	45 BRN	SP	CRE	ED,ID,MD	TD	9/19/2044
2021 PO4816526074	F	4	40 BRN	SP	CRE		V	9/20/2044
2021 PO3888339959	KU	3	45 BRO	SP	CCA		V	9/21/2044
2021 PO3873439839	KU	3	45 BRO	SP	CCA		V	9/22/2044
2021 PO3856539505	KU	3	45 BRO	SP	CCA		V	9/23/2044
2021 PO4063391161	KU	4	40 BRN	SP	CCA		V	9/24/2044
2021 PO4062591102	KU	4	40 BRN	SP	CCA		V	9/25/2044
2021 PO4164785827	F	4	35 BRO	SP	CRE		V	9/26/2044
2021 PO4164885841	F	4	35 BRO	SP	CCA		V	9/27/2044
2021 PO4164885845	F	4	35 BRO	SP	CRE		V	9/28/2044
2021 PO4164985876	F	4	35 BRO	SP	CRE		V	9/29/2044
2021 PO4164985883	F	4	35 BRO	SP	CRE		V	9/30/2044
2021 PO4165085901	F	4	35 BRO	SP	CRE		V	10/1/2044
2021 PO4090085472	F	3	50 ACE	SP	CRE		V	10/2/2044
2021 PO4089385462	F	4	40 ACE	SP	CRE		V	10/3/2044
2021 PO6628513851	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/4/2044
2021 PO6581213628	KU	4	40 ACW	SP	P	ED,ID	TD	10/5/2044
2021 PO6578314031	KU	4	45 ACW	SP	CRE	ED,ID	TD	10/6/2044
2021 PO6567513687	KU	6	30 ACW	SP	CRE	ED,ID	TD	10/7/2044
2021 PO4088585453	F	4	40 ACE	SP	P		V	10/8/2044
2021 PO3908813603	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/9/2044
2021 PO3897913600	KU	6	30 XXX	SP	CRE	ID	BD	10/10/2044
2021 PO4165185913	F	4	30 BRO	SP	CRE		V	10/11/2044
2021 PO4165285915	F	4	35 BRO	SP	A		V	10/12/2044
2021 PO4164085921	F	4	40 BRO	SP	A		V	10/13/2044
2021 PO4164985920	F	4	40 BRO	SP	A		V	10/14/2044
2021 PO4166285920	F	4	40 BRO	SP	CRE		V	10/15/2044
2021 PO4115085705	LGE	3	45 ACE	SP	CRE		V	10/16/2044
2021 PO4113985673	LGE	1	95 ACE	SP	CRE		V	10/17/2044
2021 PO5609214966	KU	3	45 BRN	SP	CRE	ED,ID	TD	10/18/2044
2021 PO4165385957	F	4	35 BRO	SP	CRE		V	10/19/2044
2021 PO4165385946	F	4	35 BRO	SP	CRE		V	10/20/2044
2021 PO4165285931	F	4	35 BRO	SP	CRE		V	10/21/2044
2021 PO4165485967	F	4	30 BRO	SP	A		V	10/22/2044

2021 PO4061090795	KU	4	40 BRN	SP	CRE	ID	BD	10/23/2044
2021 PO4072190982	KU	5	35 BRN	SP	CCA		V	10/24/2044
2021 PO4090491005	KU	4	40 BRN	SP	CRE	ID	BD	10/25/2044
2021 PO4077890912	KU	4	45 BRN	SP	CCA		V	10/26/2044
2021 PO4023290634	KU	4	45 BRN	SP	CCA		V	10/27/2044
2021 PO4005590429	KU	4	45 BRN	SP	CRE	ID	TD	10/28/2044
2021 PO3986190252	KU	4	45 BRN	SP	CCA		V	10/29/2044
2021 PO3952689948	KU	4	40 BRN	SP	CRE		V	10/30/2044
2021 PO3925789985	KU	4	40 BRN	SP	CCA		V	10/31/2044
2021 PO3932489857	KU	4	45 BRN	SP	CCA		V	11/1/2044
2021 PO3921989799	KU	4	40 BRN	SP	CRE	ID	TD	11/2/2044
2021 3894789587a	KU	4	40 BRN	SP	CRE	ID	TD	11/3/2044
2021 PO3894789587	KU	4	40 BRN	SP	CRE	ID	BD	11/4/2044
2021 PO4012487153	KU	4	40 BRN	SP	CCA		V	11/5/2044
2021 PO4052487155	KU	4	40 BRN	SP	CCA		V	11/6/2044
2021 PO4938226725	KU	4	40 BRN	SP	P	ED,ID	TD	11/7/2044
2021 PO5633415045	KU	3	45 BRN	SP	CRE	ED,ID,MD	TD	11/8/2044
2021 PO4164585976	F	4	40 BRO	SP	CRE		V	11/9/2044
2021 PO4166785974	F	4	40 BRO	SP	A		V	11/10/2044
2021 PO4165485975	F	4	40 BRO	SP	CCA		V	11/11/2044
2021 PO4165785990	F	4	35 BRO	SP	CRE		V	11/12/2044
2021 PO4935726902	KU	4	40 BRN	SP	S		V	11/13/2044
2021 PO3865039651	KU	4	40 BRO	SP	CCA		V	11/14/2044
2021 PO3846539326	KU	4	40 BRO	SP	CCA		V	11/15/2044
2021 PO3846139090	KU	4	40 BRO	SP	CCA		V	11/16/2044
2021 PO4144984947	LGE	4	30 ACE	SP	P	ED,ID	BD	11/17/2044
2021 PO4144884941	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	11/18/2044
2021 PO4144784915	LGE	4	30 ACE	SP	CRE	ED,ID	BD	11/19/2044
2021 PO4144584901	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	11/20/2044
2021 PO4165685979	F	4	35 BRO	SP	CRE		V	11/21/2044
2021 PO4165785998	F	4	35 BRO	SP	CRE		V	11/22/2044
2021 PO4165886010	F	4	35 BRO	SP	CRE		V	11/23/2044
2021 PO4934626982	KU	4	40 BRN	SP	P	ED,ID	TD	11/24/2044
2021 PO6133412215	KU	4	40 ACW	SP	CRE	ED,ID,IP,MD,RB	X	11/25/2044
2021 PO6083710295	KU	1	65 ACW	SP	S		V	11/26/2044
2021 PO6095610308	KU	4	40 ACW	SP	S		V	11/27/2044
2021 PO5534214835	KU	2	45 BRN	SP	CRE	ED,ID	TD	11/28/2044
2021 PO4116284802	LGE	4	35 ACE	SP	P	ED,ID	BD	11/29/2044
2021 PO4115784790	LGE	4	40 ACE	SP	P	ED,ID	TD	11/30/2044
2021 PO4115384780	LGE	4	35 ACE	SP	P	ED,ID	BD	12/1/2044
2021 PO4114984770	LGE	4	40 ACE	SP	P	ED,ID	BD	12/2/2044
2021 PO4114484758	LGE	4	35 ACE	SP	P	ED,ID	BD	12/3/2044
2021 PO4113984746	LGE	4	40 ACE	SP	CCA		V	12/4/2044
2021 PO4113584736	LGE	4	40 ACE	SP	CCA		V	12/5/2044
2021 PO4110284691	LGE	4	40 ACE	SP	P	ED,ID	BD	12/6/2044
2021 PO4109684693	LGE	4	30 ACE	SP	P	ED,ID	BD	12/7/2044
2021 PO4110784703	LGE	4	40 ACE	SP	CCA		V	12/8/2044
2021 PO4112784721	LGE	3	45 ACE	SP	CCA		V	12/9/2044
2021 PO411184722	LGE	4	40 ACE	SP	P	ED,ID	TD	12/10/2044
2021 PO4111184732	LGE	4	40 ACE	SP	CCA		V	12/11/2044
2021 PO4110784749	LGE	3	50 ACE	SP	P	ED,ID	BD	12/12/2044
2021 PO4052777616	KU	4	40 BRN	SP	CRE	ID	TD	12/13/2044
2021 PO5513414925	KU	7	30 BRN	SP	CCA		V	12/14/2044
2021 PO5500514870	KU	7	30 BRN	SP	CCA		V	12/15/2044

2021	PO5533314526	KU	3	40 BRN	SP	CRE	ED,ID	TD		12/16/2044
2021	PO5547614316	KU	2	50 BRN	SP	CRE	ED,ID,JP,RB	TX	RR	12/17/2044
2021	PO5552714308	KU	2	55 BRN	SP	CCA		V		12/18/2044
2021	PO5544214593	KU	2	45 BRN	SP	CRE	ED,ID,JP	X	RP2	12/19/2044
2021	PO4163085898	F	4	40 BRO	SP	CCA		V		12/20/2044
2021	PO4163585875	LGE	4	35 BRO	SP	CCA		V		12/21/2044
2021	PO5737015678	KU	3	45 BRN	SP	CCA		V		12/22/2044
2021	PO4131984722	LGE	4	30 ACE	SP	CRE	ED,ID	TD		12/23/2044
2021	PO5711415805	KU	3	45 BRN	SP	CCA	ED	TD		12/24/2044
2021	PO4068477703	KU	6	30 BRN	SP	CRE	ID	TD		12/25/2044
2021	PO4054177771	KU	4	40 BRN	SP	CRE	ID	TD		12/26/2044
2021	PO4033977940	KU	4	40 BRN	SP	CRE	ID	TD		12/27/2044
2021	PO3889611407	KU	4	40 XXX	SP	CRE	ID	BD		12/28/2044
2021	PO4132284728	LGE	3	45 ACE	SP	CCA		V		12/29/2044
2021	PO3952741497	KU	3	45 BRO	SP	CCA		V		12/30/2044
2021	PO3937141310	KU	3	45 BRO	SP	CCA		V		12/31/2044
2021	PO5716015717	KU	3	45 BRN	SP	CCA		V		1/1/2045
2021	PO5703715881	KU	3	40 BRN	SP	CCA		V		1/2/2045
2021	PO4806726118	F	4	40 BRN	SP	P		V		1/3/2045
2021	PO6528813301	KU	4	45 ACW	SP	CRE	ED,ID	TD		1/4/2045
2021	PO3595356050	KU	4	40 BRN	SP	CCA		V		1/5/2045
2021	PO3599755812	KU	4	40 BRN	SP	CCA		V		1/6/2045
2021	PO3614155408	KU	4	40 BRN	SP	CCA		V		1/7/2045
2021	PO3603455612	KU	4	40 BRN	SP	CCA		V		1/8/2045
2021	PO3930840922	KU	2	50 BRO	SP	CCA		V		1/9/2045
2021	PO3925440697	KU	3	45 BRO	SP	CCA		V		1/10/2045
2021	PO3918440485	KU	4	40 BRO	SP	CCA		V		1/11/2045
2021	PO4132584739	LGE	4	40 ACE	SP	CRE	ED,ID	TD		1/12/2045
2021	PO3942210395	KU	4	40 XXX	SP	CRE	ID	BD		1/13/2045
2021	PO3964710344	KU	4	40 XXX	SP	CRE	ED,ID	TD		1/14/2045
2021	PO5713515705	KU	6	35 BRN	SP	CCA	ED	TD		1/15/2045
2021	PO5723115582	C	3	45 BRN	DF	CCA		V		1/16/2045
2021	PO4163485965	F	4	35 BRO	SP	CCA		V		1/17/2045
2021	PO4163385954	F	4	40 BRO	SP	A		V		1/18/2045
2021	PO4163385943	F	4	40 BRO	SP	A		V		1/19/2045
2021	PO1309260399	LGE	4	35 BRO	SP	CCA		V		1/20/2045
2021	PO4163285934	F	4	40 BRO	SP	CRE		V		1/21/2045
2021	PO4132884738	LGE	5	30 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	1/22/2045
2021	PO4132184752	LGE	5	30 ACE	SP	CRE	ED,ID	BD		1/23/2045
2021	PO4132984755	LGE	3	45 ACE	SP	P	ED,ID	TD		1/24/2045
2021	PO6642013822	KU	5	35 ACW	SP	CRE	ED,ID	TD		1/25/2045
2021	PO4849325848	KU	3	45 BRN	SP	CRE	ED,ID	TD		1/26/2045
2021	PO39111340524	F	4	35 UNK	SP	P		V		1/27/2045
2021	PO3909940300	KU	4	40 BRO	SP	CCA		V		1/28/2045
2021	PO3926840318	KU	4	40 INP	SP	CRE	ID	BD		1/29/2045
2021	PO5709015484	KU	3	45 BRN	SP	CRE	ED,JP,IP	TD		1/30/2045
2021	PO4133184751	LGE	4	30 ACE	SP	P	ED,ID	TD		1/31/2045
2021	PO4133284756	LGE	4	30 ACE	SP	P	ED,ID	TD		2/1/2045
2021	PO4861125865	F	4	40 BRN	SP	CRE		V		2/2/2045
2021	PO4856425979	F	4	40 BRN	SP	CRE		V		2/3/2045
2021	PO4850826049	F	4	40 BRN	SP	P		V		2/4/2045
2021	PO4845526073	F	4	40 BRN	SP	P		V		2/5/2045
2021	PO4162085922	F	4	40 BRO	SP	A		V		2/6/2045
2021	PO4163185921	F	3	45 BRO	SP	CCA		V		2/7/2045

2021 PO4163985905	LGE	4	30 BRO	SP	A		V			2/8/2045
2021 PO6920114377	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			2/9/2045
2021 PO3895613178	KU	5	35 XXX	SP	CRE	ED,ID	TD			2/10/2045
2021 PO4163185909	F	4	40 BRO	SP	A		V			2/11/2045
2021 PO4847225984	KU	3	45 BRN	SP	S		V			2/12/2045
2021 PO3523658708	KU	4	40 BRN	SP	CCA		V			2/13/2045
2021 PO3515459554	KU	4	40 BRN	SP	CCA		V			2/14/2045
2021 PO3541159648	KU	2	50 BRN	SP	CCA		V			2/15/2045
2021 PO3559159722	KU	4	45 BRN	SP	CCA		V			2/16/2045
2021 PO3569859947	KU	4	45 BRN	SP	CCA		V			2/17/2045
2021 PO3586260277	KU	4	40 BRN	SP	CCA		V			2/18/2045
2021 PO3590760387	KU	3	45 BRN	SP	CCA		V			2/19/2045
2021 PO3593760552	KU	3	45 BRN	SP	CCA		V			2/20/2045
2021 PO3603561227	KU	4	40 BRN	SP	CCA		V			2/21/2045
2021 PO4959125754	F	4	40 BRN	SP	P	ED,ID	BX	RP3		2/22/2045
2021 PO4957825872	F	4	40 BRN	SP	P	ED,ID,RB	BX	RP3		2/23/2045
2021 PO4167585952	LGE	4	40 BRO	SP	A	ED,ID	TD			2/24/2045
2021 PO4167085958	LGE	4	35 BRO	SP	A	ED,ID,IP	TD			2/25/2045
2021 PO4141484637	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD			2/26/2045
2021 PO4941826480	KU	4	40 BRN	SP	P	ED,ID	BD			2/27/2045
2021 PO4949626461	F	4	40 BRN	SP	P		V			2/28/2045
2021 PO4072485321	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD			3/1/2045
2021 PO4073085328	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD			3/2/2045
2021 PO4943026371	KU	4	35 BRN	SP	CCA	ED,ID	TD			3/3/2045
2021 PO4143884807	LGE	4	30 ACE	SP	CRE	ED,ID	TD			3/4/2045
2021 PO5568814647	KU	6	35 BRN	SP	CRE	ED,ID	TD			3/5/2045
2021 PO5586614605	KU	7	35 BRN	SP	CCA		V			3/6/2045
2021 PO3803737871	KU	4	40 UNK	SP	CRE	ID	TD			3/7/2045
2021 PO5583315037	KU	4	40 BRN	SP	CCA	ED	TD			3/8/2045
2021 PO4129284798	LGE	4	40 ACE	SP	P	ED,ID	BD			3/9/2045
2021 PO4954025623	KU	4	40 BRN	SP	CRE	ED,ID	BD			3/10/2045
2021 PO4952225764	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/11/2045
2021 PO4950925862	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/12/2045
2021 PO4948526015	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/13/2045
2021 PO4944226300	KU	4	40 BRN	SP	P	ED,ID	TD			3/14/2045
2021 PO4167485941	LGE	4	40 BRO	SP	A	ED,ID	TD			3/15/2045
2021 PO4167285908	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			3/16/2045
2021 PO4129184796	LGE	4	40 ACE	SP	CCA		V			3/17/2045
2021 PO4129884821	LGE	4	40 ACE	SP	CCA		V			3/18/2045
2021 PO4130684844	LGE	4	40 ACE	SP	CCA		V			3/19/2045
2021 PO4167385919	F	4	40 BRO	SP	CRE		V			3/20/2045
2021 PO4166985923	LGE	4	35 BRO	SP	CRE	ED,ID	TD			3/21/2045
2021 PO4167385930	LGE	4	40 BRO	SP	A	ED,ID,IP	TD			3/22/2045
2021 PO6255312912	KU	5	35 ACW	SP	CRE	ED,ID	TD			3/23/2045
2021 PO6252113157	KU	5	35 ACW	SP	CRE	ED,ID	TD			3/24/2045
2021 PO6249913337	KU	4	40 ACW	SP	CRE	ED,ID	TD			3/25/2045
2021 PO6263113412	KU	6	30 ACW	SP	CRE	ED,ID	TD			3/26/2045
2021 PO3844738203	KU	4	40 UNK	SP	CRE	ID	TD			3/27/2045
2021 PO4077487158	KU	4	40 BRN	SP	CCA		V			3/28/2045
2021 PO4102287194	KU	4	40 BRN	SP	CCA		V			3/29/2045
2021 PO4126987230	KU	4	45 BRN	SP	CCA		V			3/30/2045
2021 PO3909786380	KU	4	40 BRN	SP	CRE	ID	TD			3/31/2045
2021 PO3936186393	KU	6	35 BRN	SP	CRE	ID	TD			4/1/2045
2021 PO3970786411	KU	6	35 BRN	SP	CRE	ID	TD			4/2/2045



2021 PO4024586439	KU	6	35 BRN	SP	CRE	ID	TD	4/3/2045
2021 PO3995686424	KU	6	35 BRN	SP	CRE	ID	TD	4/4/2045
2021 PO4026086570	KU	4	45 BRN	SP	CCA		V	4/5/2045
2021 PO4038286563	KU	4	40 BRN	SP	CCA		V	4/6/2045
2021 PO4128684792	LGE	4	35 ACE	SP	P	ED,ID	BD	4/7/2045
2021 PO4127384793	LGE	4	35 ACE	SP	P	ED,ID	TD	4/8/2045
2021 PO5577114939	KU	5	40 BRN	SP	CCA		V	4/9/2045
2021 PO5555114869	KU	4	40 BRN	SP	CCA	ED	TD	4/10/2045
2021 PO4115685247	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	4/11/2045
2021 PO4114785239	LGE	3	45 BRO	SP	CCA		V	4/12/2045
2021 PO5527614991a	KU	5	35 BRN	SP	CRE	ED,ID,MD	TD	4/13/2045
2021 PO5545514864	KU	3	40 BRN	SP	CCA	ED	TD	4/14/2045
2021 PO3828710494	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/15/2045
2021 PO4073085337	LGE	4	30 BRN	SP	CRE	ED,ID,IP	TD	4/16/2045
2021 PO8399059804	LGE	4	35 ACE	SP	CCA		V	4/17/2045
2021 PO4167085863	LGE	3	45 BRO	SP	CRE	ID,IP	BD	4/18/2045
2021 PO3851411609	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/19/2045
2021 PO4214411088	KU	5	35 BRN	SP	CRE	ED,ID,MD	TD	4/20/2045
2021 PO4075485055	LGE	3	50 BRN	SP	P	ED,ID,IP	TD	4/21/2045
2021 PO4075885060	LGE	7	25 BRN	SP	CRE	ED,EP,ID	TD	4/22/2045
2021 PO4073985061	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	4/23/2045
2021 PO3607361474	KU	4	40 BRN	SP	CCA		V	4/24/2045
2021 PO3615461715	KU	4	40 BRN	SP	CCA		V	4/25/2045
2021 PO3622761932	KU	3	45 BRN	SP	CCA		V	4/26/2045
2021 PO3629462139	KU	3	45 BRN	SP	CCA		V	4/27/2045
2021 PO3636962376	KU	4	40 BRN	SP	CCA		V	4/28/2045
2021 PO3644562602	KU	4	40 BRN	SP	CCA		V	4/29/2045
2021 PO3651962827	KU	4	40 BRN	SP	CCA		V	4/30/2045
2021 PO3671363401	KU	4	40 BRN	SP	CCA		V	5/1/2045
2021 PO3666663262	KU	4	40 BRN	SP	CCA		V	5/2/2045
2021 PO3659363049	KU	4	40 BRN	SP	CCA		V	5/3/2045
2021 PO3683163934	KU	4	40 BRN	SP	CRE		V	5/4/2045
2021 PO3688464152	KU	4	40 BRN	SP	CRE		V	5/5/2045
2021 PO3679363749	KU	4	40 BRN	SP	CCA		V	5/6/2045
2021	3691963835	KU	4	40 BRN	SP	CCA	V	5/7/2045
2021 PO3693564382	KU	3	45 BRN	SP	CCA		V	5/8/2045
2021 PO3709164623	KU	4	40 BRN	SP	CCA		V	5/9/2045
2021 PO3721064813	KU	4	40 BRN	SP	CCA		V	5/10/2045
2021	3692264104	KU	4	40 BRN	SP	CCA	V	5/11/2045
2021 PO3856311823	KU	4	40 XXX	SP	CRE	ED,ID,MD	TX	RR 5/12/2045
2021 PO4216011146	KU	3	40 BRN	SP	CCA	ED,MD	TD	5/13/2045
2021 PO4216711168	KU	3	45 BRN	SP	CRE	ED	TD	5/14/2045
2021 PO4210211171	KU	3	45 BRN	SP	CRE	ED,ID	TD	5/15/2045
2021 PO4180011151	KU	4	45 BRN	SP	CRE	ED	TD	5/16/2045
2021 PO3832311858	KU	4	45 XXX	SP	CRE	ED,ID	TD	5/17/2045
2021 PO3797811904A	KU	5	35 BRN	SP	CCA		V	5/18/2045
2021 PO6117110052	KU	3	40 ACW	SP	CRE	ED,ID	TD	5/19/2045
2021 PO6117109868	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	5/20/2045
2021 PO6102709947	KU	6	30 ACW	SP	CRE	ED,ID	TD	5/21/2045
2021 PO4196711206	KU	3	45 BRN	SP	CCA	ED	TD	5/22/2045
2021 PO4185311236	KU	3	45 BRN	SP	CCA		V	5/23/2045
2021 PO3797811904	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/24/2045
2021 PO3878186978	KU	4	40 BRN	SP	CRE	ID	BD	5/25/2045
2021 PO3769811646	KU	4	40 XXX	SP	CRE	ED,ID,RB	X	RP1 5/26/2045

2021	PO4183211241	KU	4	45 BRN	SP	CRE	ED,ID	BD	5/27/2045	
2021	PO4191011440	KU	3	45 BRN	SP	CCA	ED	TD	5/28/2045	
2021	PO4108885673	LGE	3	45 ACE	SP	P	ED,ID	TD	5/29/2045	
2021	PO4086285491a	KU	4	30 ACE	SP	CCA	ED,ID	TD	5/30/2045	
2021	PO4085585426	LGE	4	40 ACE	SP	CCA		V	5/31/2045	
2021	PO4196611643	KU	3	45 BRN	SP	CRE		V	6/1/2045	
2021	PO4111385205	LGE	3	45 BRO	SP	CCA		V	6/2/2045	
2021	PO4110885222	LGE	4	40 BRO	SP	CCA		V	6/3/2045	
2021	PO4110885242	LGE	4	40 BRO	SP	A	ID	TD	6/4/2045	
2021	PO4110585251	LGE	4	30 BRO	SP	CRE	ED,ID	TD	6/5/2045	
2021	PO4111085250	LGE	4	40 BRO	SP	CRE	ID	BD	6/6/2045	
2021	PO4110585260	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/7/2045	
2021	PO4110585267	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	6/8/2045	
2021	PO4110985263	LGE	3	45 BRO	SP	CCA		V	6/9/2045	
2021	PO4110885280	LGE	3	45 BRO	SP	CCA		V	6/10/2045	
2021	PO4110285279	LGE	4	30 BRO	SP	A	ED,ID	TD	6/11/2045	
2021	PO3540286739	KU	4	40 BRN	SP	CRE	ID	TD	6/12/2045	
2021	PO3515486539	KU	4	40 BRN	SP	CRE	ID	TD	6/13/2045	
2021	PO3536986571	KU	4	40 BRN	SP	CRE	ID	TD	6/14/2045	
2021	PO3549286638	KU	5	35 BRN	SP	CRE	ID	TD	6/15/2045	
2021	PO4166285753	F	4	40 BRO	SP	A		V	6/16/2045	
2021	PO4166485752	F	4	35 BRO	SP	A		V	6/17/2045	
2021	PO4165885743	F	4	40 BRO	SP	A		V	6/18/2045	
2021	PO4166285733	F	4	30 BRO	SP	CRE		V	6/19/2045	
2021	PO4165785730	F	4	40 BRO	SP	A		V	6/20/2045	
2021	PO4166085712	F	4	40 BRO	SP	CRE		V	6/21/2045	
2021	PO4165785722	F	4	40 BRO	SP	CRE		V	6/22/2045	
2021	PO4165785729	LGE	4	40 BRO	SP	A	ED,ID	TD	6/23/2045	
2021	PO4165885476	LGE	4	40 BRO	SP	CRE	ED,ID	TD	6/24/2045	
2021	PO4167685558	LGE	4	35 BRO	SP	CRE	ED,ID	TD	6/25/2045	
2021	PO4167685544	LGE	4	35 BRO	SP	CCA		V	6/26/2045	
2021	PO4167585534	LGE	4	35 BRO	SP	CRE	ED,ID	TD	6/27/2045	
2021	PO4044520286	KU	4	45 UNK	SP	CRE	ID	TD	6/28/2045	
2021	PO4085385423	LGE	6	25 ACE	SP	P	ED,ID	TD	6/29/2045	
2021	PO8020466171a	KU	4	45 ACE	SP	CCA		V	6/30/2045	
2021	PO4087385439	LGE	3	45 ACE	SP	CCA		V	7/1/2045	
2021	PO8020466171	LGE	3	45 ACE	SP	CCA		V	7/2/2045	
2021	PO5064427576	KU	4	40 BRN	SP	P	ID	BD	7/3/2045	
2021	PO4935128393	KU	6	30 BRN	SP	CRE		V	7/4/2045	
2021	PO7091564978	LGE	4	40 BRN	SP	A	ED,ID	BD	7/5/2045	
2021	PO3995185344	LGE	4	40 BRN	SP	A	ED,ID	BD	7/6/2045	
2021	PO3996585347	LGE	4	40 BRN	SP	A	ED,ID,IP	TD	7/7/2045	
2021	PO3732965004	KU	4	45 BRN	SP	CCA		V	7/8/2045	
2021	PO3734665228	KU	3	45 BRN	SP	CCA		V	7/9/2045	
2021		3739065343	KU	2	50 BRN	SP	CCA		V	7/10/2045
2021		3731765568	KU	3	45 BRN	SP	CCA		V	7/11/2045
2021	PO4084485437	LGE	4	40 ACE	SP	P	ED,ID	TD	7/12/2045	
2021	PO3566486181	KU	4	40 BRN	SP	CRE	ID	TD	7/13/2045	
2021	PO3550286053	KU	4	40 BRN	SP	CRE	ID	TD	7/14/2045	
2021	PO3553485940	KU	4	40 BRN	SP	CRE	ID	TD	7/15/2045	
2021	PO3501386411	KU	3	45 BRN	SP	CCA		V	7/16/2045	
2021	PO3489886296	KU	3	45 BRN	SP	CCA		V	7/17/2045	
2021	PO3997185349	LGE	4	40 BRN	SP	A	ED,ID	TD	7/18/2045	
2021	PO3997185347	LGE	4	40 BRN	SP	CCA		V	7/19/2045	

2021 PO3997985345	LGE	4	40 BRN	SP	P	ED,ID	BD		7/20/2045
2021 PO3941910751	KU	6	30 XXX	SP	CRE	ED,ID	TX	RR	7/21/2045
2021 PO3950310733	KU	4	40 XXX	SP	P	ED,ID,IP	TD		7/22/2045
2021 PO4084385428	LGE	4	40 ACE	SP	P	ED,ID	TD		7/23/2045
2021 PO6392310070	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD		7/24/2045
2021 PO6382110215	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		7/25/2045
2021 PO6389210273	KU	4	45 ACW	SP	S		V		7/26/2045
2021 PO6398610679	KU	6	30 ACW	SP	S		V		7/27/2045
2021 PO6428310583	KU	5	35 ACW	SP	S		V		7/28/2045
2021 PO4084085424	LGE	4	35 ACE	SP	A	ED,ID,IP	TD		7/29/2045
2021 PO4082185429	LGE	4	45 ACE	SP	P	ED,ID	TD		7/30/2045
2021 PO4085485416	F	3	45 ACE	SP	CCA		V		7/31/2045
2021 PO3998285345	LGE	7	25 BRN	SP	CRE	ED,ID,RB	X	RP2	8/1/2045
2021 PO3999085347	LGE	4	40 BRN	SP	CCA		V		8/2/2045
2021 PO4711807402	KU	5	35 BRN	SP	CCA	ED	TD		8/3/2045
2021 PO4680107383	KU	3	40 BRN	SP	CRE	ED,ID	TD		8/4/2045
2021 PO4704607398	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/5/2045
2021 PO5039027708	KU	3	50 BRN	SP	CRE	ED,ID	TD		8/6/2045
2021 PO4164485769	F	4	35 BRO	SP	CRE		V		8/7/2045
2021 PO4164485776	F	4	35 BRO	SP	CRE		V		8/8/2045
2021 PO4164585783	F	4	35 BRO	SP	CRE		V		8/9/2045
2021 PO4164685797	F	4	35 BRO	SP	CRE		V		8/10/2045
2021 PV4164685804	F	4	35 BRO	SP	CRE		V		8/11/2045
2021 PO4165485808	F	4	40 BRO	SP	CRE		V		8/12/2045
2021 PO3999585346	LGE	4	40 BRN	SP	CRE		V		8/13/2045
2021 PO4000285356	LGE	3	45 BRN	SP	CCA		V		8/14/2045
2021 PO4164685811	F	4	35 BRO	SP	CRE		V		8/15/2045
2021 PO3843835692	KU	4	40 BRO	SP	CCA		V		8/16/2045
2021 PO5022126356	F	4	40 BRN	SP	P		V		8/17/2045
2021 PO5008026983	F	4	40 BRN	SP	P		V		8/18/2045
2021 PO4190609883	KU	3	45 BRN	SP	CCA	ED	TD		8/19/2045
2021 PO4161385484	LGE	4	30 BRO	SP	CRE		V		8/20/2045
2021 PO4160685567	LGE	4	35 BRO	SP	A	ID	TD		8/21/2045
2021 PO4161785566	LGE	4	40 BRO	SP	A	ED,ID	TD		8/22/2045
2021 PO4161385565	LGE	4	35 BRO	SP	P		V		8/23/2045
2021 PO4161385551	LGE	4	35 BRO	SP	A	ED,ID	TD		8/24/2045
2021 PO4161085537	LGE	4	35 BRO	SP	A	ED,EP,ID,IP	TX	RR	8/25/2045
2021 PO4161085515	LGE	4	35 BRO	SP	A	ID	TD		8/26/2045
2021 PO4160985509	LGE	4	35 BRO	SP	A	ED,EP,ID,IP,RB	TX	RR	8/27/2045
2021 PO4160785494	LGE	4	35 BRO	SP	A	ED,ID,RB	BX	PX	8/28/2045
2021 PO4087785479	LGE	4	40 ACE	SP	P	ED,ID	BD		8/29/2045
2021 PO3892722910	KU	4	45 KOP	SP	CRE	ID	TD		8/30/2045
2021 PO5026026181	F	4	40 BRN	SP	CRE		V		8/31/2045
2021 PO5029825998	F	4	40 BRN	SP	CRE		V		9/1/2045
2021 PO4084685491	LGE	4	30 ACE	SP	CRE	ED,ID	TD		9/2/2045
2021 PO4085085494	LGE	3	45 ACE	SP	CCA		V		9/3/2045
2021 PO4086285491	LGE	4	40 ACE	SP	CCA		V		9/4/2045
2021 PO4087485490	LGE	3	50 ACE	SP	A		V		9/5/2045
2021 PO3879923120	KU	4	45 UNK	SP	CRE	ID	TD		9/6/2045
2021 PO4160585479	LGE	4	35 BRO	SP	CRE	ED,ID	TD		9/7/2045
2021 PO4160585465	LGE	4	35 BRO	SP	A	ED,ID	TD		9/8/2045
2021 PO4160285451	LGE	4	35 BRO	SP	P	ED,ID	TD		9/9/2045
2021 PO4163085533	LGE	5	25 BRO	SP	CRE	ED,ID	TD		9/10/2045
2021 PO4164385532	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		9/11/2045

2021 PO4164485542	LGE	4	35 BRO	SP	CRE	ED,ID	TD	9/12/2045
2021 PO4164585553	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	9/13/2045
2021 PO4164685564	LGE	4	35 BRO	SP	A	ED,ID	TD	9/14/2045
2021 PO4000685383	LGE	4	40 BRN	SP	A	ED,ID,IP	BD	9/15/2045
2021 PO3999785390	LGE	4	40 BRN	SP	A	ED,ID,IP	BD	9/16/2045
2021 PO4001685382	LGE	3	45 BRN	SP	CCA		V	9/17/2045
2021 PO4000785387	LGE	3	45 BRN	SP	CCA		V	9/18/2045
2021 PO4000385391	LGE	4	40 BRN	SP	CCA		V	9/19/2045
2021 PO4001685417	F	3	45 BRN	SP	CCA		V	9/20/2045
2021 PO4002185412	F	4	25 BRN	SP	P		V	9/21/2045
2021 PO4000585408	F	4	40 BRN	SP	CCA		V	9/22/2045
2021 PO4087585503	LGE	3	45 ACE	SP	CRE	ED,ID	BD	9/23/2045
2021 PO6237010474	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	9/24/2045
2021 PO6244410474	KU	5	35 ACW	SP	CRE	ED,ID	TD	9/25/2045
2021 PO4087785521	LGE	3	50 ACE	SP	CRE	ED,ID,IP	BD	9/26/2045
2021 PO4087885529	LGE	4	45 ACE	SP	P	ED,ID	TD	9/27/2045
2021 PV4166585796	LGE	4	40 BRO	SP	CRE	ED,ID	TD	9/28/2045
2021 PO4166485783	LGE	4	40 BRO	SP	CRE	ED,ID	TD	9/29/2045
2021 PO4163910373	KU	2	50 BRN	SP	CCA		V	9/30/2045
2021 PO4159510402	KU	2	50 BRN	SP	CCA		V	10/1/2045
2021 PO4146210449	KU	2	50 BRN	SP	CCA		V	10/2/2045
2021 PO4094685562	LGE	4	40 ACE	SP	CCA		V	10/3/2045
2021 PO4094485652	LGE	4	40 ACE	SP	CCA		V	10/4/2045
2021 PO4095185582	LGE	4	40 ACE	SP	CRE	ED,ID	BD	10/5/2045
2021 PO4120610548	KU	2	50 BRN	SP	CCA		V	10/6/2045
2021 PO4067110749	KU	2	50 BRN	SP	CCA		V	10/7/2045
2021 PO4166085784	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	10/8/2045
2021 PO4166385772	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/9/2045
2021 PO4094385586	LGE	4	35 ACE	SP	P	ED,ID,IP	TD	10/10/2045
2021 PO3999485413	LGE	4	30 BRN	SP	CCA		V	10/11/2045
2021 PO4001185405	F	4	30 BRN	SP	CRE		V	10/12/2045
2021 PO3998685397	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/13/2045
2021 PO4090810662	KU	2	50 BRN	SP	CCA		V	10/14/2045
2021 PO5130127112	KU	5	30 BRN	SP	CRE	ED,ID	BD	10/15/2045
2021 PO5127327007	F	4	40 BRN	SP	CRE	ED,ID	BX	10/16/2045
2021 PO4095485587	LGE	4	30 ACE	SP	P	ED,ID	BD	10/17/2045
2021 PO4166385763	LGE	4	40 BRO	SP	CRE	ED,ID	TD	10/18/2045
2021 PO4099010841	KU	3	45 BRN	SP	CCA	ED	TD	10/19/2045
2021 PO4093510721	KU	3	45 BRN	SP	CCA	ED	TD	10/20/2045
2021 PO4073110799	KU	4	40 BRN	SP	CRE	ED	TD	10/21/2045
2021 PO4020510916	KU	2	50 BRN	SP	CCA		V	10/22/2045
2021 PO4166385769	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	10/23/2045
2021 PO4166485772	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	10/24/2045
2021 PO3998485374	LGE	4	40 BRN	SP	CCA		V	10/25/2045
2021 PO3998185396	LGE	4	40 BRN	SP	A	ED,ID	BD	10/26/2045
2021 PO3997185387	F	4	30 BRN	SP	A		V	10/27/2045
2021 PO3997285381	LGE	3	45 BRN	SP	CCA		V	10/28/2045
2021 PO3995285366	LGE	4	35 BRN	SP	CCA		V	10/29/2045
2021 PO4088085569	LGE	4	40 ACE	SP	P	ED,ID	BD	10/30/2045
2021 PO3996985372	LGE	4	40 BRN	SP	CCA		V	10/31/2045
2021 PO3994485351	LGE	4	40 BRN	SP	CCA		V	11/1/2045
2021 PO3862423558	KU	3	50 BRO	SP	CCA		T	11/2/2045
2021 PO4088385583	LGE	4	40 ACE	SP	P	ED,ID	BD	11/3/2045
2021 PO8029767661	LGE	3	45 ACE	SP	CCA		V	11/4/2045

2021 PO4086785439	LGE	4	35 ACE	SP	P	ED,ID	BD	11/5/2045	
2021 PO3874411705	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/6/2045	
2021 PO3889223674	KU	4	45 BRO	SP	CCA		B	11/7/2045	
2021 PO3868223831	KU	4	40 BRO	SP	CCA		B	11/8/2045	
2021 PO4010610959	KU	3	45 BRN	SP	CRE	ED,ID	TD	11/9/2045	
2021 PO3882811832	KU	6	30 XXX	SP	CRE	ED,ID	TD	11/10/2045	
2021 PO3880611742	KU	4	40 XXX	SP	CRE	ID	BD	11/11/2045	
2021 PO4009210964a	KU	3	45 BRN	SP	CCA		V	11/12/2045	
2021 PO4006610781	KU	3	45 BRN	SP	CCA		V	11/13/2045	
2021 PO4009210964	KU	3	45 BRN	SP	CCA		V	11/14/2045	
2021 PO4086285426	LGE	3	45 ACE	SP	CCA		V	11/15/2045	
2021 PO4084385424	LGE	4	35 ACE	AL	CCA		V	11/16/2045	
2021 PO3993210445	KU	3	45 BRN	SP	CCA		V	11/17/2045	
2021 PO4002010668	KU	3	45 BRN	SP	CCA		V	11/18/2045	
2021 PO3858624098	KU	4	40 BRO	SP	CCA		B	11/19/2045	
2021 PO3856024184	KU	4	40 BRO	SP	CCA		B	11/20/2045	
2021 PO3897523983	KU	4	45 BRO	SP	CCA		B	11/21/2045	
2021 PO6246510216	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/22/2045	
2021 PO6264610274	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/23/2045	
2021 PO6265110333	KU	6	30 ACW	SP	CRE	ED,ID	TD	11/24/2045	
2021 PO6282610212	KU	4	40 ACW	SP	CRE	ED,ID	BD	11/25/2045	
2021 PO6283210266	F	6	30 ACW	SP	S		V	11/26/2045	
2021 PO6200410154	KU	4	40 ACW	SP	S		V	11/27/2045	
2021 PO5119327146	F	4	40 BRN	SP	CRE		V	11/28/2045	
2021 PO5102427016	F	4	40 BRN	SP	P	ED,ID	BX	PX	11/29/2045
2021 PO5087427022	F	3	45 BRN	SP	P		V	11/30/2045	
2021 PO5088427109	F	4	40 BRN	SP	P	ED,ID	BX	RP3	12/1/2045
2021 PO3997610556	KU	3	45 BRN	SP	CCA		V	12/2/2045	
2021 PO3976410022	KU	3	45 BRN	SP	CCA		V	12/3/2045	
2021 PO3988710334	KU	3	45 BRN	SP	CCA		V	12/4/2045	
2021 PO3984210221	KU	3	45 BRN	SP	CCA		V	12/5/2045	
2021 PO3552886850	KU	5	35 BRN	SP	CRE	ID	BD	12/6/2045	
2021 PO3558486827	KU	6	35 BRN	SP	CRE	ID	TD	12/7/2045	
2021 PO4164385809	F	4	40 BRO	SP	A		V	12/8/2045	
2021 PO4075685394	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/9/2045	
2021 PO4075485385	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/10/2045	
2021 PO3999685355	LGE	4	30 BRN	SP	A	ED,ID,IP	TD	12/11/2045	
2021 PO3999385397	LGE	1	50 BRN	SP	CCA		V	12/12/2045	
2021 PO4162585821	LGE	3	45 BRO	SP	CCA		V	12/13/2045	
2021 PO6315109176	KU	3	45 ACW	SP	S		V	12/14/2045	
2021 PO6329709387	KU	4	40 ACW	SP	S		V	12/15/2045	
2021 PO6314809418	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/16/2045	
2021 PO6314009861	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/17/2045	
2021 PO6313810121	KU	4	40 ACW	SP	CRE	ED,ID	BD	12/18/2045	
2021 PO4718307406	KU	4	40 BRN	SP	CRE	ED	TD	12/19/2045	
2021 PO8777370142	LGE	4	30 BRO	SP	CRE		V	12/20/2045	
2021 PO4098385493	LGE	4	30 ACE	SP	P	ED,ID	TD	12/21/2045	
2021 PO4874228634	KU	4	40 BRN	SP	P	ED,ID	TD	12/22/2045	
2021 PO3998885402	LGE	3	45 BRN	SP	CRE	ED,ID,IP	TD	12/23/2045	
2021 PO3997885407	LGE	4	45 BRN	SP	CCA		V	12/24/2045	
2021 PO3996285417	LGE	4	40 BRN	SP	CCA		V	12/25/2045	
2021 PO3987785439	LGE	4	35 BRN	SP	CRE		V	12/26/2045	
2021 PO4046785226	LGE	4	40 BRO	SP	CRE	ED,ID	TD	12/27/2045	
2021 PO7614464002	LGE	4	40 BRO	SP	CCA		V	12/28/2045	

2021	PO7599364117	F	4	40 BRO	SP	CCA		V		12/29/2045
2021	PO4047085257	LGE	4	40 BRO	SP	CRE	ED,ID	BD		12/30/2045
2021	PO4049085203	F	4	40 BRO	SP	CRE		V		12/31/2045
2021	PO4059785305	LGE	4	40 ACE	SP	CRE		V		1/1/2046
2021	PO3334953242	KU	4	40 KOP	SP	CRE	ID	TD		1/2/2046
2021	PO3351051887	KU	3	55 BRN	SP	S		B		1/3/2046
2021	PO3310052042	KU	3	55 UNK	SP	S		B		1/4/2046
2021	PO3270652233	KU	4	40 UNK	SP	CRE	ID	BD		1/5/2046
2021	PO5307057938	KU	4	40 BRN	SP	CRE	ID	BD		1/6/2046
2021	PO5324158040	KU	4	40 BRN	SP	CRE	ID	BX	RP3	1/7/2046
2021	PO5335958111	KU	4	40 BRN	SP	CRE	ID	TD		1/8/2046
2021	PO5353957969	KU	4	40 BRN	SP	CRE	ID	TD		1/9/2046
2021	PO5392857541	KU	3	45 BRN	SP	CRE	ID	TD		1/10/2046
2021	PO4052285257	LGE	4	30 BRO	SP	CRE	ID	TD		1/11/2046
2021	PO4052585251	F	3	45 BRO	SP	CRE		V		1/12/2046
2021	PO4052085241	F	3	45 BRO	SP	CRE		V		1/13/2046
2021	PO4059885312	LGE	3	45 ACE	SP	P	ED	BD		1/14/2046
2021	PO4051085232	KU	4	35 BRO	SP	A		V		1/15/2046
2021	PO4051485229	F	4	40 BRO	SP	CRE		V		1/16/2046
2021	PO4040985213	F	4	40 BRO	SP	CRE		V		1/17/2046
2021	PO4050685213	F	3	45 BRO	SP	CRE		V		1/18/2046
2021	PO4050985213	F	4	40 BRO	SP	CCA		V		1/19/2046
2021	PO4051485230	LGE	3	45 BRO	SP	CCA		V		1/20/2046
2021	PO4051985241	LGE	3	45 BRO	SP	CCA		V		1/21/2046
2021	PO4050885253	F	4	35 BRO	SP	CRE		V		1/22/2046
2021	PO4059885319	LGE	4	40 ACE	SP	CRE	ED,ID	BD		1/23/2046
2021	PO4060085335	LGE	4	40 ACE	SP	CRE	ED,ID	BD		1/24/2046
2021	PO4170485423	LGE	4	30 ACE	SP	CCA		V		1/25/2046
2021	PO4055285254	LGE	4	35 BRO	SP	CCA		V		1/26/2046
2021	PO8758307930	F	4	40 OTH	SP	CRE		V		1/27/2046
2021	PO8757808005	F	4	40 OTH	SP	CRE		V		1/28/2046
2021	PO4050185200	F	3	45 BRO	SP	CRE		V		1/29/2046
2021	PO4051485191	F	4	40 BRO	SP	CRE		V		1/30/2046
2021	PO4052685179	F	4	35 BRO	SP	CRE		V		1/31/2046
2021	PO4052985184	F	4	40 BRO	SP	CRE		V		2/1/2046
2021	PO4053885202	F	4	40 BRO	SP	CRE		V		2/2/2046
2021	PO4054485213	F	4	40 BRO	SP	CRE		V		2/3/2046
2021	PO4060985317	LGE	4	40 ACE	SP	CCA	ED	TD		2/4/2046
2021	PO4054985223	F	4	40 BRO	SP	CRE		V		2/5/2046
2021	PO4055585235	F	4	40 BRO	SP	CRE		V		2/6/2046
2021	PO4056085245	F	4	40 BRO	SP	CRE		V		2/7/2046
2021	PO3988985180	LGE	4	40 ACE	SP	CCA		V		2/8/2046
2021	PO4060985306	LGE	4	40 ACE	SP	CRE	ED	BD		2/9/2046
2021	PO4044185077	F	4	40 BRO	SP	CRE		VX	RP3	2/10/2046
2021	PO4055485172	F	4	45 BRO	SP	CRE		V		2/11/2046
2021	PO4056385167	F	4	45 BRO	SP	CCA		V		2/12/2046
2021	PO4058485155	F	4	40 BRO	SP	CRE		V		2/13/2046
2021	PO4108185195	LGE	4	40 ACE	SP	A	ED,HH,ID	TD		2/14/2046
2021	PO5401157738	KU	4	45 BRN	SP	CRE	ID	TD		2/15/2046
2021	PO5410357971	KU	4	45 BRN	SP	CRE	ID	BD		2/16/2046
2021	PO5398457877	KU	5	35 BRN	SP	CRE	ID	TD		2/17/2046
2021	PO5391457902	KU	4	40 BRN	SP	CRE	ID	TD		2/18/2046
2021	PO4058885160	F	4	40 BRO	SP	CCA		V		2/19/2046
2021	PO4059385168	F	4	40 BRO	SP	CRE		V		2/20/2046

2021 PO4059985177	F	4	40 BRO	SP	CRE		V	2/21/2046
2021 PO4060585189	F	4	35 BRO	SP	CRE		V	2/22/2046
2021 PO4061385190	LGE	4	30 BRO	SP	CRE	ED,ID	TD	2/23/2046
2021 PO4061185194	F	4	40 BRO	SP	CRE		V	2/24/2046
2021 PO4061785201	F	4	45 BRO	SP	CRE		V	2/25/2046
2021 PO4062285209	F	4	40 BRO	SP	CRE		V	2/26/2046
2021 PO4083085212	LGE	4	30 BRO	SP	CRE	ED,ID	TD	2/27/2046
2021 PO3981785068	LGE	3	55 ACE	SP	CRE		V	2/28/2046
2021 PO3987885239	LGE	3	50 ACE	SP	CCA		V	3/1/2046
2021 PO3988385203	F	3	50 ACE	SP	CRE		V	3/2/2046
2021 PO3249752349	KU	7	30 UNK	SP	P	ID	TD	3/3/2046
2021 PO4062885267	LGE	4	35 ACE	SP	CCA		V	3/4/2046
2021 PO4064785271	LGE	4	30 ACE	SP	CRE	ED	TD	3/5/2046
2021 PO4063385280	LGE	4	30 ACE	SP	CCA	ED	V	3/6/2046
2021 PO4063085218	F	4	40 BRO	SP	CRE		V	3/7/2046
2021 PO4061885225	F	4	40 BRO	SP	CRE		V	3/8/2046
2021 PO4059985226	F	4	30 BRO	SP	CRE		V	3/9/2046
2021 PO4060285228	F	4	40 BRO	SP	CRE		V	3/10/2046
2021 PO4059185233	F	4	40 BRO	SP	CRE		V	3/11/2046
2021 PO4058285238	F	4	40 BRO	SP	CRE		V	3/12/2046
2021 PO4108385197	LGE	4	40 ACE	SP	CRE	ED,HH,ID	TD	3/13/2046
2021 PO3465828048	KU	4	40 UNK	SP	CRE	ID	TD	3/14/2046
2021 PO4050485295	LGE	5	30 ACE	SP	P	ED	TD	3/15/2046
2021 PO4036985301	LGE	4	30 ACE	SP	P	ED,ID	TD	3/16/2046
2021 PO4013484984	LGE	3	50 ACE	SP	CRE	ED,ID,IP	BD	3/17/2046
2021 PO4165585434	LGE	4	30 ACE	SP	CCA		V	3/18/2046
2021 PO4164585443	LGE	7	25 ACE	SP	CRE		V	3/19/2046
2021 PO3468428474	KU	4	40 BRN	SP	S		B	3/20/2046
2021 PO3448728435	KU	4	40 UNK	SP	CRE	ID	TD	3/21/2046
2021 PO4077485259	LGE	4	40 BRO	SP	CRE	ED,ID	BD	3/22/2046
2021 PO4077285274	LGE	4	35 BRO	SP	CRE	ED,ID	TD	3/23/2046
2021 PO4076585267	LGE	4	40 BRO	SP	CRE	ED,ID	BD	3/24/2046
2021 PO4075485277	LGE	4	40 BRO	SP	CCA		V	3/25/2046
2021 PO4167685433	LGE	4	30 ACE	SP	CRE	ED,EP,ID	TX	RR 3/26/2046
2021 PO4074285238	LGE	3	45 BRO	SP	CRE		V	3/27/2046
2021 PO4075485227	LGE	4	40 BRO	SP	CRE		V	3/28/2046
2021 PO4078185202	LGE	3	45 BRO	SP	CRE		V	3/29/2046
2021 PO4075885224	LGE	4	40 BRO	SP	CRE		V	3/30/2046
2021 PO4076385218	LGE	4	40 BRO	SP	CRE		V	3/31/2046
2021 PO4077185211	LGE	4	40 BRO	SP	CRE		V	4/1/2046
2021 PO4077985213	LGE	4	30 BRO	SP	CRE		V	4/2/2046
2021 PO4015084969	LGE	3	50 ACE	SP	CRE	ED,EP,ID,IP	TD	4/3/2046
2021 PO4016784954	LGE	3	55 ACE	SP	CRE	ED,ID,IP	TD	4/4/2046
2021 PO4176785427	LGE	1	55 ACE	SP	A	ED,ID	TD	4/5/2046
2021 PO4177685427	LGE	2	55 ACE	SP	A	ID	BD	4/6/2046
2021 PO4079085193	LGE	3	45 BRO	SP	CCA		V	4/7/2046
2021 PO4019185313	LGE	4	30 ACE	SP	CRE	ED	TD	4/8/2046
2021 PO4019785313	LGE	4	30 ACE	SP	P	ED	TD	4/9/2046
2021 PO4017185313	LGE	4	30 ACE	SP	CRE	ED	TD	4/10/2046
2021 PO5402058155	KU	4	40 BRN	SP	CRE	ID	TD	4/11/2046
2021 PO5437558542	KU	3	45 BRN	SP	CCA		V	4/12/2046
2021 PO3442628729	KU	4	40 BRO	SP	CCA		B	4/13/2046
2021 PO3446528642	KU	4	40 BRO	SP	CCA		V	4/14/2046
2021 PO3416428474	KU	4	45 CPT	SP	CRE	ID,IP	BX	RR 4/15/2046

2021 PO4055585221	F	4	40 BRO	SP	CRE		V	4/16/2046
2021 PO4023585230	F	4	40 BRO	SP	CCA		V	4/17/2046
2021 PO5152956838	KU	4	40 BRN	SP	CRE	ID	TD	4/18/2046
2021 PO5261958694	KU	3	45 BRN	SP	CRE	ID	TD	4/19/2046
2021 PO4013885281	F	4	40 ACE	SP	P		V	4/20/2046
2021 PO4063785062	LGE	3	50 BRO	SP	CCA		V	4/21/2046
2021 PO3980885064	LGE	3	55 ACE	SP	P	ED,ID	TD	4/22/2046
2021 PO4061785061	LGE	4	30 BRO	SP	CRE	ED,ID	TD	4/23/2046
2021 PO4061785062	LGE	3	50 BRO	SP	CRE	ED,ID	BD	4/24/2046
2021 PO4062185058	LGE	4	35 BRO	SP	CRE	ED,ID	TD	4/25/2046
2021 PO4009185278	LGE	4	30 ACE	SP	P	ED	TD	4/26/2046
2021 PO3989085169	LGE	2	55 ACE	SP	CRE	ED,ID,RR	TX	4/27/2046
2021 PO3988185165	LGE	1	65 ACE	SP	CRE		V	4/28/2046
2021 PO4052185077	F	4	40 BRO	SP	CRE		V	4/29/2046
2021 PO5254958608	KU	6	35 BRN	SP	CRE	ID	TD	4/30/2046
2021 PO4052985086	F	4	40 BRO	SP	CRE		V	5/1/2046
2021 PO4052585088	F	5	30 BRO	SP	CRE		V	5/2/2046
2021 PO5264258718	KU	4	45 BRN	SP	CCA		V	5/3/2046
2021 PO5282558373	KU	6	35 BRN	SP	CRE	ID	TD	5/4/2046
2021 PO4053685095	F	4	40 BRO	SP	CRE		V	5/5/2046
2021 PO7689362734	LGE	4	40 BRO	SP	CCA		V	5/6/2046
2021 PO4054285106	F	4	40 BRO	SP	CRE		V	5/7/2046
2021 PO4053785127	F	4	40 BRO	SP	CRE		V	5/8/2046
2021 PO4054485117	LGE	4	40 BRO	SP	CCA		V	5/9/2046
2021 PO4054985116	F	4	40 BRO	SP	CCA		V	5/10/2046
2021 PO4010885268	F	4	40 ACE	SP	CCA		V	5/11/2046
2021 PO4009885269	F	4	40 ACE	SP	CCA		V	5/12/2046
2021 PO4054985134	F	4	40 BRO	SP	CRE		V	5/13/2046
2021 PO4055885127	F	4	40 BRO	SP	CRE		V	5/14/2046
2021 PO4056485136	F	4	30 BRO	SP	CRE		V	5/15/2046
2021 PO4057085134	F	4	40 BRO	SP	CRE		V	5/16/2046
2021 PO4057885145	F	4	40 BRO	SP	CRE		V	5/17/2046
2021 PO4008985269	F	4	40 ACE	SP	CRE		V	5/18/2046
2021 PO4001185094	LGE	3	50 ACE	SP	CCA		V	5/19/2046
2021 PO4002585081	LGE	3	50 ACE	SP	CRE	ED,ID	TD	5/20/2046
2021 PO4053285175	F	4	40 BRO	SP	CRE		V	5/21/2046
2021 PO4049785099	F	4	35 BRO	SP	CRE		V	5/22/2046
2021 PO4049285096	F	4	40 BRO	SP	CRE		V	5/23/2046
2021 PO4048485085	F	4	40 BRO	SP	CRE		V	5/24/2046
2021 PO4048085079	F	4	30 BRO	SP	CRE		V	5/25/2046
2021 PO4052985166	F	4	40 BRO	SP	CRE		V	5/26/2046
2021 PO4052385154	F	4	40 BRO	SP	CCA		V	5/27/2046
2021 PO4051085146	F	4	30 BRO	SP	CRE		V	5/28/2046
2021 PO4051585145	F	4	40 BRO	SP	CRE		V	5/29/2046
2021 PO4050585133	F	4	40 BRO	SP	CRE		V	5/30/2046
2021 PO5291858458	KU	3	45 BRN	SP	CRE	ID	TD	5/31/2046
2021 PO5304958159	KU	4	40 BRN	SP	CRE	ID	TD	6/1/2046
2021 PO5319558240	KU	4	40 BRN	SP	CCA		V	6/2/2046
2021 PO4052985107	F	4	40 BRO	SP	CRE		V	6/3/2046
2021 PO4052385113	F	4	35 BRO	SP	CRE		V	6/4/2046
2021 PO4052085107	F	4	40 BRO	SP	CRE		V	6/5/2046
2021 PO4051085118	F	4	35 BRO	SP	CRE		V	6/6/2046
2021 PO4050785112	F	4	45 BRO	SP	CRE		V	6/7/2046
2021 PO4012985255	F	3	45 ACE	SP	CCA		V	6/8/2046



2021 PO4011585242	F	4	45 ACE	SP	CCA	ED	V	6/9/2046	
2021 PO4010885237	F	4	40 ACE	SP	CRE		V	6/10/2046	
2021 PO4009685235	F	4	40 ACE	SP	CRE	ED	V	6/11/2046	
2021 PO4049785116	F	4	40 BRO	SP	CRE		V	6/12/2046	
2021 PO4050185121	F	4	30 BRO	SP	CRE		V	6/13/2046	
2021 PO4040485145	F	4	45 BRO	SP	CRE	ED,ID,IP	BX	RP3	6/14/2046
2021 PO4048585120	F	3	45 BRO	SP	CRE	ED,HH,ID,RB	BX	RP3	6/15/2046
2021 PO4008985236	F	4	35 ACE	SP	CCA	ED	V	6/16/2046	
2021 PO4004185067	LGE	3	45 ACE	SP	CRE	ED,ID	TD	6/17/2046	
2021 PO4005685053	LGE	3	40 ACE	SP	CRE	ED,ID	TD	6/18/2046	
2021 PO4007185040	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD	6/19/2046	
2021 PO4008785025	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD	6/20/2046	
2021 PO4007585328	LGE	8	40E ACE	SP	S		V	6/21/2046	
2021 PO4037285101	F	4	40 BRO	SP	CRE		V	6/22/2046	
2021 PV4038585101	F	4	40 BRO	SP	CCA		V	6/23/2046	
2021 PV4039485100	F	4	40 BRO	SP	CCA		V	6/24/2046	
2021 PO4040485099	F	4	40 BRO	SP	CRE		V	6/25/2046	
2021 PO4042085098	F	4	40 BRO	SP	CCA		V	6/26/2046	
2021 PO4043885097	F	4	30 BRO	SP	CRE		V	6/27/2046	
2021 PO4005285278	F	5	25 ACE	SP	P		V	6/28/2046	
2021 PO4004785272	F	4	40 ACE	SP	CRE	ED	V	6/29/2046	
2021 PO4006085266	F	5	25 ACE	SP	P	ED	V	6/30/2046	
2021 PO4005285263	F	4	40 ACE	SP	CRE	ED	V	7/1/2046	
2021 PO4045085080	F	5	30 BRO	SP	CRE		V	7/2/2046	
2021 PO4045585088	F	4	40 BRO	SP	CRE		V	7/3/2046	
2021 PO4005785250	F	4	40 ACE	SP	CCA	ED,ID	VX	RP2	7/4/2046
2021 PO4047085113	F	4	40 BRO	SP	CCA		V	7/5/2046	
2021 PO4046285101	F	4	40 BRO	SP	CRE		V	7/6/2046	
2021 PO4047385128	F	4	40 BRO	SP	CRE		V	7/7/2046	
2021 PO4045785137	F	4	40 BRO	SP	CRE		V	7/8/2046	
2021 PO4006285238	F	4	40 ACE	SP	CRE		V	7/9/2046	
2021 PO4006285229	F	4	30 ACE	SP	CRE		V	7/10/2046	
2021 PO4006985225	F	4	40 ACE	SP	CRE		V	7/11/2046	
2021 PO4044685130	F	4	40 BRO	SP	CRE		V	7/12/2046	
2021 PO4041985135	F	4	40 BRO	SP	CRE		V	7/13/2046	
2021 PO4043085127	F	4	40 BRO	SP	CRE		V	7/14/2046	
2021 PO4042985119	LGE	4	30 BRO	SP	CCA		V	7/15/2046	
2021 PO4039385146	F	3	45 BRO	SP	CCA		V	7/16/2046	
2021 PO4038285146	F	4	40 BRO	SP	CRE		V	7/17/2046	
2021 PO4045485153	F	4	40 BRO	SP	CRE		V	7/18/2046	
2021 PO4049485300	F	4	30 ACE	SP	CCA		V	7/19/2046	
2021 PO4021385340	LGE	5	35E ACE	SP	CRE	ED,ID	BD	7/20/2046	
2021 PO4313648864	KU	4	40 UNK	SP	CRE	ID	BD	7/21/2046	
2021 PO4266348920	KU	4	40 UNK	SP	CRE	ED,ID	TD	7/22/2046	
2021 PO4243548948	KU	4	40 KOP	SP	CRE	ED,HH,ID	X	RP1	7/23/2046
2021 PO4196449004	KU	4	40 KOP	SP	CRE	ID	BD	7/24/2046	
2021 PO4218948978	KU	3	40 KOP	SP	CRE	ID	BD	7/25/2046	
2021 PO4180949001	KU	4	40 KOP	SP	CRE	ID	TD	7/26/2046	
2021 PO4153149039	KU	4	40 KOP	SP	CRE	ID	TD	7/27/2046	
2021 PO3957535947	KU	4	40 UNK	SP	CRE	ID	BD	7/28/2046	
2021 PO3897536161	KU	4	40 ACW	SP	CRE	ID	BD	7/29/2046	
2021 PO3929936045	KU	4	40 ACW	SP	CRE	ID	BD	7/30/2046	
2021 PO4038685404	F	4	40 ACE	SP	CRE	ED	V	7/31/2046	
2021 PO4038485403	F	3	45 ACE	SP	P	ED	V	8/1/2046	

2021 PO4037285395	F	4	40 ACE	SP	CRE	ED	V	8/2/2046
2021 PO4034985398	F	4	40 ACE	SP	CRE	ED	V	8/3/2046
2021 PO4034185402	F	4	40 ACE	SP	CRE	ED	V	8/4/2046
2021 PO4036485400	LGE	4	40 ACE	SP	P	ED,ID	V	8/5/2046
2021 PO3998085282	F	4	40 ACE	SP	CRE	ED	V	8/6/2046
2021 PO3998685298	F	5	35E ACE	SP	A	ED	V	8/7/2046
2021 PO7145062734	LGE	3	50 ACE	SP	CRE	ED,ID,IP,RB	TX RR	8/8/2046
2021 PO3997385298	F	3	50 ACE	SP	CRE	ED	V	8/9/2046
2021 PO5139356658	KU	4	40 BRN	SP	CRE	ID	TD	8/10/2046
2021 PO5189856989	KU	4	40 BRN	SP	CRE	ID	TD	8/11/2046
2021 PO3993585272	LGE	4	30 ACE	SP	A	ED	BD	8/12/2046
2021 PO3996585306	LGE	4	35 ACE	SP	A	ED	BD	8/13/2046
2021 PO4065885061	LGE	3	45 BRO	SP	CRE	ED,ID	TD	8/14/2046
2021 PO4066385063	LGE	4	35 BRO	SP	CRE	ID	TD	8/15/2046
2021 PO4069985058	LGE	3	50 BRO	SP	CRE	ED,ID	BD	8/16/2046
2021 PO4067885060	LGE	3	50 BRO	SP	CRE	ED,ID	TX RR	8/17/2046
2021 PO3986085047	LGE	3	55 ACE	SP	CRE	ED,ID,RB	TX RR	8/18/2046
2021 PO3995085150	LGE	1	55 ACE	SP	CRE	ED,HH,ID	V	8/19/2046
2021 PO5181856990	KU	4	40 BRN	SP	CRE	ID	TD	8/20/2046
2021 PO4339848836	KU	4	40 UNK	SP	CRE	ED	TD	8/21/2046
2021 PO4363148805	KU	4	45 UNK	SP	CRE	ID	TD	8/22/2046
2021 PO4287548894	KU	4	40 UNK	SP	CRE	ED,ID	TD	8/23/2046
2021 PO4011885430	LGE	4	40 ACE	SP	P	ED	BD	8/24/2046
2021 PO5144656585	KU	4	40 BRN	SP	CRE	ID	TD	8/25/2046
2021 PO4010885418	LGE	4	45 ACE	SP	P	ED	BD	8/26/2046
2021 PO4010185392	LGE	4	40 ACE	SP	P	ED	BD	8/27/2046
2021 PO4009285391	LGE	4	40 ACE	SP	P	ED	BD	8/28/2046
2021 PO4008585384	LGE	4	35 ACE	SP	P	ED	TD	8/29/2046
2021 PO4007985357	LGE	3	45 ACE	SP	A	ED	TD	8/30/2046
2021 PO4008285369	LGE	3	45 ACE	SP	CCA	ED	V	8/31/2046
2021 PO4006885369	LGE	4	40E ACE	SP	CCA		V	9/1/2046
2021 PO4083285151	LGE	1	90 ACE	SP	CRE		V	9/2/2046
2021 PO8012963826	LGE	2	65 ACE	SP	P		V	9/3/2046
2021 PO4087185220	LGE	2	85 ACE	SP	CRE		V	9/4/2046
2021 PO4007685347	LGE	3	50 ACE	SP	CRE	ED,ID	TD	9/5/2046
2021 PO2632915168	KU	3	45 BRN	SP	CRE	ID	BD	9/6/2046
2021 PO2524915533	KU	4	40 BRN	SP	CRE	ID	BD	9/7/2046
2021 PO7409680398	KU	5	30 BRO	SP	CRE	ED,ID	TD	9/8/2046
2021 PO7416480503	KU	4	40 BRO	SP	CRE	ED,ID	BD	9/9/2046
2021 PO7425280703	KU	5	35 BRO	SP	CRE	ED,ID	TD	9/10/2046
2021 PO7433780731	KU	5	45 BRO	SP	CRE	ED,ID	TD	9/11/2046
2021 PO4167585425	F	3	55 BRN	SP	P		V	9/12/2046
2021 PO2553115411	KU	4	40 BRN	SP	CRE	ID	BD	9/13/2046
2021 PO5234004412	KU	5	40 BRN	SP	CRE	ED	TD	9/14/2046
2021 PO4167185425	LGE	4	30 BRN	SP	P	ID,IP,SRS	TD	9/15/2046
2021 PO4166485426	F	2	55 BRN	SP	CRE		V	9/16/2046
2021 PO4384608297	KU	6	30 BRN	SP	CCA		V	9/17/2046
2021 PO4387208444	KU	6	30 BRN	SP	CCA		V	9/18/2046
2021 PO4375008360	F	4	40 XXX	SP	CRE		V	9/19/2046
2021 PO4160885430	F	4	40 BRN	SP	CRE		V	9/20/2046
2021 PO2632915168	KU	4	45 BRN	SP	CRE	ID	BD	9/21/2046
2021 PO2609515075	KU	4	40 BRN	SP	CCA		V	9/22/2046
2021 PO4584898348	KU	3	45 UNK	SP	CCA		V	9/23/2046
2021 PO4593998203	KU	3	45 UNK	SP	CRE		V	9/24/2046

2021 PO2575814792	KU	3	45 BRN	SP	CRE	ED,ID	TD		9/25/2046
2021 PO2576014671	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD		9/26/2046
2021 PO4150385443	LGE	3	45 BRN	SP	P	ID	BD		9/27/2046
2021 PO6827918856	KU	4	40 ACW	SP	CRE	ED,ID	TD		9/28/2046
2021 PO6837818801	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		9/29/2046
2021 PO5228004412	KU	3	45 BRN	SP	CRE	ED	TD		9/30/2046
2021 PO5215404417	KU	3	50 BRN	SP	CRE	ED,HH,ID,RB	X	PX	10/1/2046
2021 PO4680898373	KU	3	45 UNK	SP	CCA		V		10/2/2046
2021 PO7400583963	KU	6	30 BRO	SP	CCA		V		10/3/2046
2021 PO7391384043	KU	4	40 BRO	SP	CRE	ED,ID	TD		10/4/2046
2021 PO4509804706	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		10/5/2046
2021 PO5213004393	KU	3	40 BRN	SP	CCA		V		10/6/2046
2021 PO5165204431	KU	4	45 BRN	SP	CRE	ED,ID	TD		10/7/2046
2021 PO5181504423	KU	4	40 BRN	ST	CCA		V		10/8/2046
2021 PO2590214048	KU	4	45 BRN	SP	CCA	ID	BD		10/9/2046
2021 PO2591014004	KU	5	35 BRN	SP	CCA	ED,ID	BD		10/10/2046
2021 PO2606029339	KU	4	45 BRN	SP	CCA		V		10/11/2046
2021 PO4550807418	F	4	40 KOP	SP	CRE		V		10/12/2046
2021 PO4159085387	LGE	2	55 BRN	SP	CRE	ED,ID,IP	BD		10/13/2046
2021 PO4158785363	LGE	3	45 BRN	SP	P	ID	BD		10/14/2046
2021 PO8742665915	LGE	4	40 BRN	SP	CCA		V		10/15/2046
2021 PO4158585426	LGE	2	55 BRN	SP	CRE	ID,IP,SRS	TD		10/16/2046
2021 PO4533307430	KU	4	40 XXX	SP	CRE	ED,ID	TD		10/17/2046
2021 PO4534707475	F	4	40 XXX	SP	CRE		V		10/18/2046
2021 PO4192086432	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		10/19/2046
2021 PO3280200995	KU	5	35 UNK	SP	CRE	ID	TD		10/20/2046
2021 PO3269200761	KU	2	60 UNK	SP	CRE	ID	BD		10/21/2046
2021 PO3256600585	KU	4	40 UNK	SP	CRE	ID	TD		10/22/2046
2021 PO3241500378	KU	4	40 UNK	SP	CRE	ID	TD		10/23/2046
2021 PO3228300193	KU	4	45 UNK	SP	CRE	ID	TD		10/24/2046
2021 PO4156285423	LGE	2	60 BRN	SP	S		V		10/25/2046
2021 PO4523207516	F	4	40 XXX	SP	CRE		V		10/26/2046
2021 PO4503007599	F	4	40 KOP	SP	P		V		10/27/2046
2021 PO4620207184	F	4	40 XXX	SP	CRE		V		10/28/2046
2021 PO4153785419	LGE	2	60 BRN	SP	CRE	ID	BD		10/29/2046
2021 PO7344184650	KU	4	40 BRO	SP	CRE	ED,ID	BD		10/30/2046
2021 PO7339085179	KU	3	45 BRO	SP	CRE	ED,ID	TD		10/31/2046
2021 PO4764906481	F	4	40 KOP	SP	P		V		11/1/2046
2021 PO4753706400	F	4	40 XXX	SP	CRE		V		11/2/2046
2021 PO2260234238	KU	5	35 BRN	SP	CRE	ID	TD		11/3/2046
2021 PO4121485820	LGE	4	30 BRN	SP	CRE	ID	BD		11/4/2046
2021 PO4120685830	LGE	4	40 BRN	SP	CCA		V		11/5/2046
2021 PO4118085817-A	KU	3	45E BRN	SP	CRE	ID	BD		11/6/2046
2021 PO4118085817	LGE	3	45 BRN	SP	P	ID,IP	BD		11/7/2046
2021 PO4544103866	KU	4	45 BRN	SP	CRE	ED,ID,SRC	TD		11/8/2046
2021 PO4570203716	KU	3	45 BRN	SP	S		V		11/9/2046
2021 PO4590303599	KU	4	40 BRN	SP	CRE	ED,ID	X	RP2	11/10/2046
2021 PO4554703806	KU	4	40 BRN	SP	CRE	ED,ID	X	PX	11/11/2046
2021 PO4578603667	KU	4	45 BRN	SP	CCA	ID	BD		11/12/2046
2021 PO4495704718	KU	4	40 BRN	SP	CRE	ED,ID,RB,SRC	TX	RR	11/13/2046
2021 PO5199704419	KU	4	40E BRN	SP	CRE	ED,ID,RB	TX	RR	11/14/2046
2021 PO2576614298	KU	4	40 BRN	SP	CRE	ID	TD		11/15/2046
2021 PO2576414540	KU	3	45 BRN	SP	CRE	ED,ID,IP	BD		11/16/2046
2021 PO4191586423	F	4	35 BRO	SP	CCA		V		11/17/2046

2021 PO4192586422	LGE	4	40 BRO	SP	CCA		V			11/18/2046
2021 PO6856919359	KU	6	30 ACW	SP	CRE	ED,ID	TD			11/19/2046
2021 PO6865919308	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			11/20/2046
2021 PO4194386389	LGE	4	40 BRO	SP	CCA		V			11/21/2046
2021 PO7262184672	KU	3	45 BRO	SP	CCA		V			11/22/2046
2021 PO4600307245	F	4	40 XXX	SP	CRE		V			11/23/2046
2021 PO4156785432	LGE	4	30 BRN	SP	CCA		V			11/24/2046
2021 PO7184784765	KU	6	30 BRO	SP	CRE	ED,ID	TD			11/25/2046
2021 PO7176584740	F	6	30 BRO	SP	CRE		V			11/26/2046
2021 PO4581007312	KU	3	45 BRN	SP	CCA		V			11/27/2046
2021 PO2188133399	KU	4	40 BRN	SP	CRE	ED,EP,ID	X		PX	11/28/2046
2021 PO4565003746	KU	4	40 BRN	SP	CRE	ED,ID	TX		RR	11/29/2046
2021 PO4192386366	LGE	4	40 BRO	SP	A	ED,ID	TD			11/30/2046
2021 PO5097204762	KU	3	40 BRN	SP	CRE	ED,ID,RB	X		PX	12/1/2046
2021 PO4191886376	LGE	4	40 BRO	SP	CRE	ID,IP,RB	X		RP1	12/2/2046
2021 PO4108585826	LGE	4	40 BRN	SP	CRE		V			12/3/2046
2021 PO4119685838	LGE	3	50 BRN	SP	CRE	HH,ID,RB	BX		PX	12/4/2046
2021 PO2276934223	KU	4	45 BRN	SP	CRE	ID	TD			12/5/2046
2021 PO2282034169	KU	6	30 BRN	SP	CRE	ID	TD			12/6/2046
2021 PO5235104395	KU	3	40 BRN	SP	CCA		V			12/7/2046
2021 PO4192886356	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX		RR	12/8/2046
2021 PO4751007556	F	4	40 XXX	SP	CRE		V			12/9/2046
2021 PO5116504674	KU	3	40 BRN	SP	CRE	ED,ID	BD			12/10/2046
2021 PO2209734131	KU	4	45 BRN	SP	CRE	ED,ID	TD			12/11/2046
2021 PO7257480746	KU	4	40 BRO	SP	CRE	ED,ID	BX		RP3	12/12/2046
2021 PO7243380392	KU	4	40 BRO	SP	CRE	ED,ID	TD			12/13/2046
2021 PO3082102035	KU	4	40 UNK	SP	CCA		V			12/14/2046
2021 PO3084202125	KU	4	40 UNK	SP	CRE	ID	BD			12/15/2046
2021 PO3081401972	KU	6	30 UNK	SP	CCA		V			12/16/2046
2021 PO3145902814	KU	4	40 UNK	SP	CRE		V			12/17/2046
2021 PO3123002746	KU	4	40 UNK	SP	CRE		V			12/18/2046
2021 PO2994301108	KU	4	40 UNK	SP	CRE	HH,ID	BX		RP3	12/19/2046
2021 PO2981900811	KU	4	40 UNK	SP	CRE	ID	BD			12/20/2046
2021 PO2969100310	KU	5	35 UNK	SP	CRE	ID	BD			12/21/2046
2021 PO4130485884	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD			12/22/2046
2021 PO4130985873	LGE	4	35 BRN	SP	P	ID	TD			12/23/2046
2021 PO4129885875	LGE	4	35 BRN	SP	CCA		V			12/24/2046
2021 PO4128685876	LGE	4	35 BRN	SP	CRE	ED,ID	TD			12/25/2046
2021 PO4127685873	LGE	4	35 BRN	SP	CRE		V			12/26/2046
2021 PO2244634107	F	6	35 BRN	SP	CRE		V			12/27/2046
2021 PO2240234188	KU	4	40 BRN	SP	CRE		V			12/28/2046
2021 PO2235234251	KU	5	35 BRN	SP	CRE		V			12/29/2046
2021 PO5101204653	KU	7	30 BRN	SP	CRE	ED,ID	TD			12/30/2046
2021 PO4783107109	F	4	40 XXX	SP	CRE		V			12/31/2046
2021 PO4782107217	F	4	45 XXX	SP	CRE		V			1/1/2047
2021 PO4784806970	F	4	40 XXX	SP	CRE		V			1/2/2047
2021 PO4786006821	F	4	40 XXX	SP	CCA		V			1/3/2047
2021 PO4787306664	F	4	40 XXX	SP	CCA		V			1/4/2047
2021 PO4801606666	F	4	40 XXX	SP	CRE		V			1/5/2047
2021 PO4828506673	F	4	40 XXX	SP	CRE	ED,ID,RB	BX		PX	1/6/2047
2021 PO4842206887	KU	5	35 XXX	SP	CRE	ID	BD			1/7/2047
2021 PO4838506634	KU	6	30 XXX	SP	CRE	ED,ID	TD			1/8/2047
2021 PO4830206646	F	4	40 XXX	SP	CRE		V			1/9/2047
2021 PO4816606670	F	4	45 KOP	SP	P		V			1/10/2047

2021 PO4791106436	F	4	40 XXX	SP	CRE		V		1/11/2047
2021 PO4774806431	F	4	40 XXX	SP	CRE		V		1/12/2047
2021 PO6859919121	KU	4	40 ACW	SP	CRE	ED,ID	TD		1/13/2047
2021 PO6846018766	KU	4	40 ACW	SP	CRE	ED,ID	TD		1/14/2047
2021 PO7184884715	KU	6	30 BRO	SP	CRE	ED,ID	BX	RP2	1/15/2047
2021 PO7300081227	KU	4	40 BRO	SP	CRE	ED,ID	TD		1/16/2047
2021 PO4197186342	LGE	3	45 BRO	SP	A	ED,ID	TD		1/17/2047
2021 PO4196586338	LGE	4	30 BRO	SP	A	ED,ID	TD		1/18/2047
2021 PO2161133500	KU	4	40 BRN	SP	CRE		V		1/19/2047
2021 PO2150333737	KU	3	45 BRN	SP	CCA		V		1/20/2047
2021 PO2163133845	KU	3	45 BRN	SP	CCA		V		1/21/2047
2021 PO6887019713	KU	6	30 ACW	SP	CRE	ED,ID	TD		1/22/2047
2021 PO6893419645	KU	4	40 ACW	SP	CRE	ED,ID	TD		1/23/2047
2021 PO4197286339	LGE	4	40 BRO	SP	CRE	ED,ID	TD		1/24/2047
2021 PO2182133976	KU	4	45 BRN	SP	CRE	ID	TD		1/25/2047
2021 PO7275681014	KU	5	35 BRO	SP	CCA		V		1/26/2047
2021 PO7277180964	KU	4	40 BRO	SP	CRE	ED,ID	TD		1/27/2047
2021 PO4118085742	LGE	1	80 BRN	SP	CRE		V		1/28/2047
2021 PO4118885756	LGE	1	75 BRN	SP	P		V		1/29/2047
2021 PO4119685769	LGE	1	75 BRN	SP	CRE		V		1/30/2047
2021 PO4120485782	LGE	1	75 BRN	SP	CRE		V		1/31/2047
2021 PO4121185795	LGE	1	75 BRN	SP	CRE		V		2/1/2047
2021 PO4116785877	LGE	2	55 BRN	SP	CRE	ED,HH,ID	BX	PX	2/2/2047
2021 PO6914919683	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/3/2047
2021 PO6903919664	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/4/2047
2021 PO6938519359	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		2/5/2047
2021 PO6958119095	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		2/6/2047
2021 PO6941219874	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/7/2047
2021 PO4193486345	LGE	4	40 BRO	SP	CRE	ED,ID	TD		2/8/2047
2021 PO4117985865	LGE	3	50 BRN	SP	CRE	ED,ID	TD		2/9/2047
2021 PO4117885864	LGE	3	45 BRN	SP	P	ID	TD		2/10/2047
2021 PO4118285862	LGE	3	50 BRN	SP	CRE	ID	BD		2/11/2047
2021 PO7222579862	KU	4	40 BRO	SP	CRE	ED,ID	BD		2/12/2047
2021 PO7215579882	F	6	30 BRO	SP	CRE		V		2/13/2047
2021 PO7206979747	KU	5	45 BRO	SP	CRE	ED,ID	TD		2/14/2047
2021 PO4119285851	LGE	4	35 BRN	SP	P	ID	BD		2/15/2047
2021 PO4119585847	LGE	4	40 BRN	SP	CCA	SRS	TD		2/16/2047
2021 PO4120185843	LGE	3	50 BRN	SP	CRE	ED,ID	BD		2/17/2047
2021 PO4120985837	LGE	4	30 BRN	SP	P	ID	TD		2/18/2047
2021 PO4120785850	LGE	4	35 BRN	SP	P	ID	BD		2/19/2047
2021 PO2301934459	KU	4	30 BRN	SP	CRE	ID	BD		2/20/2047
2021 PO2304434408	KU	4	45 BRN	SP	CRE	ID	BD		2/21/2047
2021 PO2292434518	KU	4	40 BRN	SP	CCA		V		2/22/2047
2021 PO4194586326	LGE	4	40 BRO	SP	CRE	ED,ID	TD		2/23/2047
2021 PO4195086318	LGE	4	30 BRO	SP	A	ID	BD		2/24/2047
2021 PO4195186315	LGE	3	45 BRO	SP	A	ID,IP	BD		2/25/2047
2021 PO4194086336	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	X	RP1	2/26/2047
2021 PO7195679545	KU	4	40 BRO	SP	CRE	ED,ID	TD		2/27/2047
2021 PO3029801843	KU	3	45 UNK	SP	CCA		V		2/28/2047
2021 PO3022701525	KU	3	45 UNK	SP	CCA		V		3/1/2047
2021 PO3015501205	KU	3	45 UNK	SP	CCA		V		3/2/2047
2021 PO2342734681	KU	4	40 BRN	SP	CRE	ID	TD		3/3/2047
2021 PO5233704215	KU	6	35 BRN	SP	CCA		V		3/4/2047
2021 PO5235104115	KU	6	40 BRN	SP	CCA		V		3/5/2047

2021	PO5231103190	F	6	35 BRN	SP	P		V	3/6/2047
2021	PO5234703742	KU	4	40 BRN	SP	CCA		V	3/7/2047
2021	PO4097285490	LGE	3	45 BRN	SP	CRE	ID	TD	3/8/2047
2021	PO4194686318	LGE	4	35 BRO	SP	CCA		V	3/9/2047
2021	PO7185679388	KU	5	45 BRO	SP	CRE	ED,ID	TD	3/10/2047
2021	7185679388A	KU	5	30 BRO	SP	CRE	ED,ID	BD	3/11/2047
2021	PO4188386437	LGE	4	35 BRO	SP	CCA		V	3/12/2047
2021	PO2298935324	KU	4	40 BRN	SP	CRE	ID	BD	3/13/2047
2021	PO4188786429	LGE	4	35 BRO	SP	CRE	ED,ID	TD	3/14/2047
2021	PO2956299736	KU	4	40 UNK	SP	CRE	ID,IP	TD	3/15/2047
2021	PO4189386418	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	3/16/2047
2021	PO7163379182	KU	3	45 BRO	SP	CCA		V	3/17/2047
2021	PO4189886409	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	3/18/2047
2021	PO4190586396	LGE	4	35 BRO	SP	CRE	ED,ID	TD	3/19/2047
2021	PO7158078890	KU	3	45 BRO	SP	CCA		V	3/20/2047
2021	PO7125178769	KU	3	45 BRO	SP	CCA		V	3/21/2047
2021	7125178769A	KU	6	30 BRO	SP	CCA		V	3/22/2047
2021	PO4191186387	LGE	4	40 BRO	SP	CRE	ID,IP	BD	3/23/2047
2021	PO7361385396	KU	3	45 BRO	SP	CCA		V	3/24/2047
2021	PO6890119173	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	3/25/2047
2021	PO6871119580	KU	6	30 ACW	SP	CRE	ED,ID	TD	3/26/2047
2021	PO6876919485	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	3/27/2047
2021	PO6893819531	KU	4	40 ACW	SP	CRE	ED,ID	TD	3/28/2047
2021	PO4193186411	LGE	4	40 BRO	SP	CCA	ED	T	3/29/2047
2021	PO4151385416	LGE	1	65 BRN	SP	A		V	3/30/2047
2021	PO4193786401	LGE	4	40 BRO	SP	CRE	ED,ID	TD	3/31/2047
2021	PO4575804654	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/1/2047
2021	PO4564504374	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TX	RR 4/2/2047
2021	PO4148885412	LGE	2	65 BRN	SP	CRE	EP,ID,IP	TD	4/3/2047
2021	PO5145804436	KU	2	35 BRN	SP	CCA	ED,ID,SRC	TX	RR 4/4/2047
2021	PO5147004561	KU	4	40 BRN	SP	CCA	ED	TD	4/5/2047
2021	PO4146085410	LGE	1	65 BRN	SP	CRE	ID,IP	BD	4/6/2047
2021	PO7383084542	KU	6	30 BRO	SP	CRE	ED,ID	TD	4/7/2047
2021	PO7382684317	KU	4	45 BRO	SP	CRE	ED,ID	TD	4/8/2047
2021	PO4720406994	F	4	40 KOP	SP	P		V	4/9/2047
2021	PO4705806990	F	4	40 XXX	SP	CRE		V	4/10/2047
2021	PO4676606981	F	4	40 XXX	SP	CRE		V	4/11/2047
2021	PO4661006978	F	4	40 XXX	SP	CRE		V	4/12/2047
2021	PO4640306975	F	4	40 XXX	SP	CRE		V	4/13/2047
2021	PO4622606971	F	4	40 KOP	SP	P		V	4/14/2047
2021	PO4620506991	F	4	40 XXX	SP	CRE		V	4/15/2047
2021	PO4194886381	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/16/2047
2021	PO4195486372	LGE	4	40 BRO	SP	CRE	ID,IP	BD	4/17/2047
2021	PO4143885409	F	2	55 BRN	SP	CRE		V	4/18/2047
2021	PO4143085406	F	2	55 BRN	SP	CRE		V	4/19/2047
2021	PO4141585399	LGE	3	45E BRN	SP	P	ID	BD	4/20/2047
2021	PO4196486354	LGE	4	40 BRO	SP	CRE	ED,ID	TD	4/21/2047
2021	PO4195986362	LGE	4	40 BRO	SP	CCA		V	4/22/2047
2021	PO7412284066	KU	4	45 BRO	SP	CRE	ED,ID	TD	4/23/2047
2021	PO4144486215	LGE	6	30 BRO	SP	CRE		V	4/24/2047
2021	PO7461583855	KU	6	30 BRO	SP	CRE	ED,ID	BD	4/25/2047
2021	PO7452983741	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/26/2047
2021	PO2257632522	KU	6	30 BRN	SP	CCA		V	4/27/2047
2021	PO4558904234	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	4/28/2047

2021 PO4568504475	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	4/29/2047
2021 PO2246132607	KU	4	40 BRN	SP	CRE	ID	TD	4/30/2047
2021 PO2204633111	KU	4	45 BRN	SP	CRE	ID	X PX	5/1/2047
2021 PO4548003984	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	5/2/2047
2021 PO4530203539	KU	4	45 BRN	SP	CRE	ED,ID	TD	5/3/2047
2021 PO4553404100	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/4/2047
2021 PO4132885972	LGE	2	55 BRN	SP	CRE	ID,IP	BD	5/5/2047
2021 PO7327081180	KU	4	40 BRO	SP	CRE		V	5/6/2047
2021 PO4121286630	LGE	3	50 BRN	SP	CCA		V	5/7/2047
2021 PO4149786387	LGE	3	50 BRN	SP	P	ID	TD	5/8/2047
2021 PO4149886388	LGE	3	50 BRN	SP	CRE	ID	BD	5/9/2047
2021 PO4149586384	LGE	3	45E BRN	SP	CCA	ID	TD	5/10/2047
2021 PO4197886343	LGE	4	30 BRO	SP	A	ED,ID	TD	5/11/2047
2021 PO4150486398	LGE	3	45 BRN	SP	P		V	5/12/2047
2021 PO4150386396	LGE	1	45 BRN	SP	P		V	5/13/2047
2021 PO4149486382	LGE	3	50 BRN	SP	CCA		V	5/14/2047
2021 PO4147286388	LGE	3	45 BRN	SP	CRE	ID	BD	5/15/2047
2021 PO4143286389	LGE	2	50 BRN	SP	P	ID,SRS	TD	5/16/2047
2021 PO4233936297	KU	3	45 BRO	SP	CCA		V	5/17/2047
2021 PO4322635379	KU	4	40 BRO	SP	CCA		B	5/18/2047
2021 PO4002571077	KU	4	40 BRN	SP	CRE	ID	TD	5/19/2047
2021 PO3927584118	KU	4	40 BRN	SP	CCA		V	5/20/2047
2021 PO4211135753	KU	3	45 BRO	SP	CCA		V	5/21/2047
2021 PO4209535481	KU	3	45 BRO	SP	CCA		V	5/22/2047
2021 PO4209034792	KU	3	45 BRO	SP	CCA		V	5/23/2047
2021 PO4203835000	KU	4	45 BRO	SP	CCA		B	5/24/2047
2021 PO4208035237	KU	3	45 BRO	SP	CCA		B	5/25/2047
2021 PO4336735518	F	4	45 BRO	SP	CCA		V	5/26/2047
2021 PO4347335681	F	4	45 BRO	SP	CCA		V	5/27/2047
2021 PO4427435078	KU	3	45 BRO	SP	CCA		V	5/28/2047
2021 PO4047871265	KU	4	45 BRN	SP	CRE	ID	TD	5/29/2047
2021 PO4070971360	KU	4	40 BRN	SP	CRE	ID	TD	5/30/2047
2021 PO4294135396	KU	4	45 BRO	SP	CCA		B	5/31/2047
2021 PO4274235491	KU	3	45 BRO	SP	CCA		B	6/1/2047
2021 PO4277935378	KU	3	40 BRO	SP	CCA		B	6/2/2047
2021 PO4282235610	KU	6	30 BRO	SP	CCA		B	6/3/2047
2021 PO4266335692	KU	4	45 BRO	SP	CCA		V	6/4/2047
2021 PO3894883483	F	5	35 BRN	SP	CRE		B	6/5/2047
2021 PO3917783615	KU	4	40 BRN	SP	CRE	ID	BD	6/6/2047
2021 PO4224835966	KU	3	45 BRO	SP	CCA		V	6/7/2047
2021 PO4245336124	KU	4	45 BRO	SP	CCA		B	6/8/2047
2021 PO4241735877	KU	4	40 BRO	SP	CCA		B	6/9/2047
2021 PO3898183882	KU	4	40 BRN	SP	CCA		V	6/10/2047
2021 PO3916983896	KU	4	40 BRN	SP	CCA		V	6/11/2047
2021 PO4087385263	F	4	40 ACE	SP	CRE		V	6/12/2047
2021 PO4087585271	F	4	40 ACE	SP	CRE		V	6/13/2047
2021 PO4086485271	F	4	40 ACE	SP	CRE		V	6/14/2047
2021 PO4085285272	F	4	40 ACE	SP	CRE		V	6/15/2047
2021 PO4084685272	F	4	40 ACE	SP	CRE		V	6/16/2047
2021 PO4140784562	LGE	4	40 ACE	SP	P	ED,ID	TD	6/17/2047
2021 PO9402415671	KU	6	30 ACW	SP	CRE	ED,ID	TD	6/18/2047
2021 PO9268615676	KU	6	30 ACW	SP	CRE	ED,ID	TD	6/19/2047
2021 PO4219877880	KU	4	40 BRN	SP	CRE	ID	TD	6/20/2047
2021 PO4140984576	LGE	4	40 ACE	SP	P	ED,ID	TD	6/21/2047

2021 PO4171385971	LGE	3	45 BRO	SP	A	ID	BD		6/22/2047
2021 PO4141284591	LGE	4	40 ACE	SP	CRE	ED,ID	TD		6/23/2047
2021 PO4141484605	LGE	4	35 ACE	SP	P	ED,ID	BD		6/24/2047
2021 PO4172685970	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		6/25/2047
2021 PO4213477722	KU	5	35 BRN	SP	CRE	ID	TD		6/26/2047
2021 PO4201177975	KU	5	35 BRN	SP	CRE	ED,HH,IP,RB	X	PX	6/27/2047
2021 PO4207778614	KU	3	45 BRN	SP	CCA		V		6/28/2047
2021 PO4193578547	KU	4	45 BRN	SP	CRE	MD	BX	RP3	6/29/2047
2021 PO4165478768	KU	4	40 BRN	SP	CRE	ID	BD		6/30/2047
2021 PO4111284743	LGE	4	35 ACE	SP	CCA		V		7/1/2047
2021 PO4134384616	LGE	4	40 ACE	SP	P	ED,ID	BD		7/2/2047
2021 PO8951315315	KU	4	40 ACW	SP	CRE	ED,ID	TD		7/3/2047
2021 PO8942115658	KU	4	40 ACW	SP	S		V		7/4/2047
2021 PO8833915185	KU	4	40 ACW	SP	CRE	ED,ID	TD		7/5/2047
2021 PO8872515250	KU	4	40 ACW	SP	S		V		7/6/2047
2021 PO4172885952	F	4	35 BRO	SP	A		V		7/7/2047
2021 PO4172785937	F	4	35 BRO	SP	CRE		V		7/8/2047
2021 PO4172685924	F	4	35 BRO	SP	CRE		V		7/9/2047
2021 PO4135784634	LGE	4	40 ACE	SP	P	ED,ID	BD		7/10/2047
2021 PO4196378891	KU	4	40 BRN	SP	CCA		V		7/11/2047
2021 PO4067979426	KU	4	40 BRN	SP	CRE	ID	BD		7/12/2047
2021 PO4060379640	KU	4	40 BRN	SP	CRE	ID	BD		7/13/2047
2021 PO3921881214	KU	3	45 BRN	SP	CCA		V		7/14/2047
2021 PO3926281511	KU	3	45 BRN	SP	CCA		V		7/15/2047
2021 PO3990981547	KU	3	45 BRN	SP	CCA		V		7/16/2047
2021 PO4011281832	KU	3	45 BRN	SP	CCA		V		7/17/2047
2021 PO4031582117	KU	4	40 BRN	SP	CCA		V		7/18/2047
2021 PO4135184627	LGE	4	40 ACE	SP	P	ED,ID	BD		7/19/2047
2021 PO4134884639	LGE	4	40 ACE	SP	P	ED,ID	TD		7/20/2047
2021 PO4133584642	LGE	4	40 ACE	SP	P	ED,ID	TD		7/21/2047
2021 PV8848171619	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		7/22/2047
2021 PO9061314413	KU	5	45 ACW	SP	S		V		7/23/2047
2021 PO9064314919	KU	5	45 ACW	SP	S		V		7/24/2047
2021 PO8646215549	KU	5	35 ACW	SP	CRE	ED,ID	BD		7/25/2047
2021 PO8632915819	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD		7/26/2047
2021 PO8581215733	KU	4	45 ACW	SP	CRE	ED,ID	TD		7/27/2047
2021 PO8598915534	KU	4	40 ACW	SP	CRE	ED,ID	TD		7/28/2047
2021 PO9135614017	KU	2	50 ACW	SP	S		V		7/29/2047
2021 PO9117813665	KU	3	45 ACW	SP	S		V		7/30/2047
2021 PO8392015510	KU	4	45 ACW	SP	CRE	ED,ID	TD		7/31/2047
2021 PO4171285949	LGE	4	40 BRO	SP	CRE	ED,ID	TD		8/1/2047
2021 PO4171285961	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/2/2047
2021 PO3799881927	KU	5	35 BRN	SP	CRE		V		8/3/2047
2021 PO4171185938	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/4/2047
2021 PO4171085928	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	8/5/2047
2021 PO4132884642	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		8/6/2047
2021 PO4171085916	LGE	3	55 BRO	SP	CRE	ED,ID,IP	TD		8/7/2047
2021 PO4172485916	F	4	40 BRO	SP	CRE		V		8/8/2047
2021 PO4171885916	F	4	40 BRO	SP	A		V		8/9/2047
2021 PO4172585916	LGE	4	35 BRO	SP	CCA		V		8/10/2047
2021 PO4172585909	F	4	35 BRO	SP	CRE		V		8/11/2047
2021 PO4172485897	F	4	35 BRO	SP	CRE		V		8/12/2047
2021 PO4172385883	F	4	35 BRO	SP	CRE		V		8/13/2047
2021 PO4172385868	F	4	35 BRO	SP	CRE		V		8/14/2047



2021	PO4129384587	LGE	4	40 ACE	SP	CRE	ED,ID,IP,RB	BD		8/15/2047
2021	PO4128584581	LGE	4	40 ACE	SP	P	ED,ID	TD		8/16/2047
2021	PO4170985903	F	4	40 BRO	SP	A		V		8/17/2047
2021	PO4170885893	F	3	45 BRO	SP	CCA		V		8/18/2047
2021	PO4170885883	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		8/19/2047
2021	PO4170485890	LGE	5	35 BRO	SP	A		V		8/20/2047
2021	PO4137384664	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	8/21/2047
2021	PO4135784673	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		8/22/2047
2021	PO4134384676	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	8/23/2047
2021	PO4134384672	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD		8/24/2047
2021	PO4133084670	LGE	3	45 ACE	SP	CCA		V		8/25/2047
2021	PO4133084683	LGE	4	40 ACE	SP	CCA		V		8/26/2047
2021	PO4132984656	LGE	4	40 ACE	SP	CCA		V		8/27/2047
2021	PO4174085884	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		8/28/2047
2021	PO4173885859	LGE	4	40 BRO	SP	CCA		V		8/29/2047
2021	PO4174085867	LGE	4	30 BRO	SP	CCA		V		8/30/2047
2021	PO4174085874	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	8/31/2047
2021	PO4174185905	LGE	4	40 BRO	SP	A	ED,ID	TD		9/1/2047
2021	PO4174085895	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	9/2/2047
2021	PO4129284592	LGE	4	45 ACE	SP	CRE	ED,ID,IP,RB	BD		9/3/2047
2021	PO4129284597	LGE	4	40 ACE	SP	P	ED,ID	TD		9/4/2047
2021	PO4129384604	LGE	4	40 ACE	SP	CRE	ED,ID	TD		9/5/2047
2021	PO4173085916	F	4	40 BRO	SP	A		V		9/6/2047
2021	PO4270177638	KU	4	40 BRN	SP	CRE	ID	TD		9/7/2047
2021	PO7762915046	KU	5	35 ACW	SP	CRE	ED,ID	TD		9/8/2047
2021	PO9759215932	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		9/9/2047
2021	PO9743115927	KU	4	40 ACW	SP	CRE	ED,ID	TD		9/10/2047
2021	PO9724215989	KU	4	40 ACW	SP	S		V		9/11/2047
2021	PO9698116067	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD		9/12/2047
2021	PO4173185970	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		9/13/2047
2021	PO4086185242	F	4	40 ACE	SP	CRE		V		9/14/2047
2021	PO4086785252	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	V		9/15/2047
2021	PO4088585257	LGE	4	30 ACE	SP	P	ED,ID	BD		9/16/2047
2021	PO9926515023	KU	4	40 ACW	SP	S		V		9/17/2047
2021	PO4432876167	KU	4	40 BRN	SP	CRE	ED,ID	X	RP2	9/18/2047
2021	PO4178885853	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		9/19/2047
2021	PO4472575637	KU	4	40 BRN	SP	CRE	ID	TD		9/20/2047
2021	PO4492175619	KU	4	40 BRN	SP	CRE	ID	TD		9/21/2047
2021	PO4482175694	KU	6	30 BRN	SP	CRE		V		9/22/2047
2021	PO4507875625	KU	4	40 BRN	SP	CRE	ID	TD		9/23/2047
2021	PO4089485269	LGE	5	35 ACE	SP	CRE		V		9/24/2047
2021	PO4240078770	KU	4	40 BRN	SP	CRE	ID	TD		9/25/2047
2021	PO4218878662	KU	2	50 BRN	SP	CRE	ID	TD		9/26/2047
2021	PO4121878714	KU	4	40 BRN	SP	CRE	ID	TD		9/27/2047
2021	PO4014576894	F	4	40 BRN	SP	CCA		V		9/28/2047
2021	PO8579960441	LGE	4	30 ACE	SP	P	ED,ID	TD		9/29/2047
2021	PO7168614957	KU	6	30 ACW	SP	CRE	ED,ID	TD		9/30/2047
2021	PO4174785992	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		10/1/2047
2021	PO4174886001	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		10/2/2047
2021	PO4174886012	LGE	4	35 BRO	SP	A	ED,ID	TD		10/3/2047
2021	PO4174986015	LGE	4	35 BRO	SP	A	ED,ID	TD		10/4/2047
2021	PO4143584850	LGE	3	45 ACE	SP	P	ED,ID	BD		10/5/2047
2021	PO4143584857	LGE	3	45 ACE	SP	CRE	ED,ID	TD		10/6/2047
2021	PO4143684870	LGE	3	45 ACE	SP	CRE	ED,ID	TD		10/7/2047

2021 PO7164015074	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/8/2047
2021 PO7163815146	KU	4	40 ACW	SP	CRE	ED,ID	BD	10/9/2047
2021 PO7163115225	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/10/2047
2021 PO7172715101	KU	6	30 ACW	SP	S		V	10/11/2047
2021 PO7590615128	KU	5	35 ACW	SP	S		V	10/12/2047
2021 PO7623015057	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/13/2047
2021 PO7628214841	KU	5	35 ACW	SP	S		V	10/14/2047
2021 PO7635014544	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/15/2047
2021 PO9956014718	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/16/2047
2021 PO4172985974	F	4	35 BRO	SP	CRE		V	10/17/2047
2021 PO4172985978	F	4	30 BRO	SP	CRE		V	10/18/2047
2021 PO4056778451	KU	4	35 BRN	SP	CRE	ID	BD	10/19/2047
2021 PO4094378122	KU	4	35 BRN	SP	CRE		V	10/20/2047
2021 PO4143284904	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	10/21/2047
2021 PO4142584900	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	10/22/2047
2021 PO4142584904	LGE	1	50 ACE	SP	CCA		V	10/23/2047
2021 PO4141684904	LGE	4	40 ACE	SP	CCA		V	10/24/2047
2021 PO4140384904	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	10/25/2047
2021 PO4139484905	LGE	4	40 ACE	SP	CCA		V	10/26/2047
2021 PO4138384905	LGE	4	40 ACE	SP	CRE	ED,ID	TD	10/27/2047
2021 PO4129784703	LGE	4	30 ACE	SP	P	ED,ID	BD	10/28/2047
2021 PO3510031816	KU	4	40 UNK	SP	CRE	ED	TD	10/29/2047
2021 PO4143784882	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD	10/30/2047
2021 PO4143984893	LGE	3	45 ACE	SP	P	ED,ID	TD	10/31/2047
2021 PO3453232829	KU	4	40 UNK	SP	CRE	ID	TD	11/1/2047
2021 PO3822123243	KU	5	35 UNK	SP	CRE	ED,ID	X	RP1 11/2/2047
2021 PO3494232100	KU	4	40 UNK	SP	CRE	ID	TD	11/3/2047
2021 PO4006476890	KU	4	40 BRN	SP	CRE	ID	TD	11/4/2047
2021 PO4010677396	KU	4	40 BRN	SP	CRE	ID	BD	11/5/2047
2021 PO4020077621	KU	4	40 BRN	SP	CRE	ID	TD	11/6/2047
2021 PO4048378267	KU	4	40 BRN	SP	CRE	ID	TD	11/7/2047
2021 PO3477632404	KU	4	40 UNK	SP	CRE	ID	TD	11/8/2047
2021 PO4174485947	LGE	4	40 BRO	SP	CCA		V	11/9/2047
2021 PO4174585958	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	11/10/2047
2021 PO4174385926	LGE	4	40 BRO	SP	CCA		V	11/11/2047
2021 PO9926115065	KU	4	35 ACW	SP	CRE	ED,ID	TD	11/12/2047
2021 PO4174685969	LGE	4	40 BRO	SP	A	ID,IP	BD	11/13/2047
2021 PO3437332967	KU	4	40 UNK	SP	CRE	ID	BD	11/14/2047
2021 PO3724422487	KU	4	40 UNK	SP	CRE		V	11/15/2047
2021 PO4143984903	LGE	3	45 ACE	SP	CRE	ED,ID	TD	11/16/2047
2021 PO4143984916	LGE	3	45 ACE	SP	CCA		V	11/17/2047
2021 PO4172985965	LGE	4	35 BRO	SP	CRE	ED,ID	TD	11/18/2047
2021 PO4171586003	LGE	4	40 BRO	SP	A	ED,ID	TD	11/19/2047
2021 PO4171485994	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/20/2047
2021 PO4171485983	LGE	4	40 BRO	SP	A	ED,ID	TD	11/21/2047
2021 PO4174385937	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR 11/22/2047
2021 PO4173785970	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR 11/23/2047
2021 PO3568229333	KU	3	45 UNK	SP	CRE	ED,ID	TD	11/24/2047
2021 PO3545229220	KU	4	45 UNK	SP	CRE		V	11/25/2047
2021 PO3568229136	KU	3	45 BRO	SP	CCA		V	11/26/2047
2021 PO3660732215	KU	4	40 UNK	SP	CRE	ID	TD	11/27/2047
2021 PO4509975466	KU	6	30 BRN	SP	CCA		V	11/28/2047
2021 PO4526475608	KU	4	40 BRN	SP	CRE	ID	TD	11/29/2047
2021 PO4143284810	LGE	3	45 ACE	SP	CRE	ED,ID	TD	11/30/2047

2021 PO7302814629	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/1/2047
2021 PO7300714404	KU	4	40 ACW	SP	CRE	ED,ID,JP	TD	12/2/2047
2021 PO7309314533	KU	4	40 ACW	SP	S		V	12/3/2047
2021 PO7047714444	KU	6	30 ACW	SP	CRE	ED,ID	TD	12/4/2047
2021 PO4143184794	LGE	2	45 ACE	SP	CCA		V	12/5/2047
2021 PO4179785852	LGE	4	35 BRO	SP	CRE	ED,ID,JP	TD	12/6/2047
2021 PO3637032441	KU	5	35 INP	SP	CRE	ID	TD	12/7/2047
2021 PO4548575699	KU	4	40 BRN	SP	CRE	ID	TD	12/8/2047
2021 PO4553975822	KU	4	40 BRN	SP	CRE	ID	TD	12/9/2047
2021 PO4438876529	KU	4	40 BRN	SP	CRE	ID	TD	12/10/2047
2021 PO4451775923	KU	2	40 BRN	SP	CRE	ID	TD	12/11/2047
2021 PO4143384821	LGE	3	45 ACE	SP	CRE	ED,ID,JP	TD	12/12/2047
2021 PO3614932651	KU	5	40 UNK	SP	CRE	ED,ID	TD	12/13/2047
2021 PO4179485839	F	4	35 BRO	SP	CRE		V	12/14/2047
2021 PO4179385827	F	4	35 BRO	SP	CRE		V	12/15/2047
2021 PO3689230875	KU	4	35 UNK	SP	CRE	ID	BD	12/16/2047
2021 PO4175685814	LGE	4	35 BRO	SP	A	ED,ID	TD	12/17/2047
2021 PO4143184837	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/18/2047
2021 PO4143484833	LGE	3	45 ACE	SP	CCA		V	12/19/2047
2021 PO7039115168	KU	4	40 ACW	SP	CRE	ED,ID,JP	TD	12/20/2047
2021 PO7047214979	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/21/2047
2021 PO7053514819	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/22/2047
2021 PO7170115024A	KU	6	30 ACW	SP	CRE	ED,ID	TD	12/23/2047
2021 PO4175785824	F	4	35 BRO	SP	A		V	12/24/2047
2021 PO4175985852	F	4	35 BRO	SP	CRE		V	12/25/2047
2021 PO4175885854	F	4	35 BRO	SP	CRE		V	12/26/2047
2021 PO4176185880	F	4	35 BRO	SP	CRE		V	12/27/2047
2021 PO4176385908	F	4	30 BRO	SP	A		V	12/28/2047
2021 PO4176685913	F	4	40 BRO	SP	A		V	12/29/2047
2021 PO4141384841	LGE	4	40 ACE	SP	CRE	ED,ID,JP	BD	12/30/2047
2021 PO4268778765	KU	4	40 BRN	SP	CRE	ID	BD	12/31/2047
2021 PO4138984844a	KU	4	35 ACE	SP	CCA		V	1/1/2048
2021 PO4138984844	LGE	3	45 ACE	SP	P	ED,ID	TD	1/2/2048
2021 PO4140684860	LGE	4	40 ACE	SP	P	ED,ID	TD	1/3/2048
2021 PO3546431311	KU	4	40 BRO	SP	CRE	ID	TD	1/4/2048
2021 PO4174285914	F	3	45 BRO	SP	A		V	1/5/2048
2021 PO3594033191	KU	4	45 BRO	SP	CRE		B	1/6/2048
2021 PO3539431674	KU	4	40 ESC	SP	CRE	ID	TD	1/7/2048
2021 PO4175485914	F	4	40 BRO	SP	CRE		V	1/8/2048
2021 PO4174685981	LGE	4	40 BRO	SP	A	ED,ID,JP	TD	1/9/2048
2021 PO4173085985	F	4	35 BRO	SP	CRE		V	1/10/2048
2021 PO4173085995	F	4	35 BRO	SP	CRE		V	1/11/2048
2021 PO4173186005	F	4	35 BRO	SP	CRE		V	1/12/2048
2021 PO4173286013	F	4	40 BRO	SP	A		V	1/13/2048
2021 PV8873672134	LGE	4	40 BRO	SP	CCA	ED	T	1/14/2048
2021 PO3749522958	KU	4	40 UNK	SP	CRE		V	1/15/2048
2021 PO3768822976	KU	4	40 UNK	SP	CRE		V	1/16/2048
2021 PO3770222598	KU	4	40 UNK	SP	CRE		V	1/17/2048
2021 PO3797023006	KU	6	35 UNK	SP	CRE	ED,ID	X	1/18/2048
2021 PO4171786030	LGE	3	45 BRO	SP	CCA		V	1/19/2048
2021 PO4062278641	KU	4	45 BRN	SP	CRE	ID	TD	1/20/2048
2021 PO4081178656	KU	4	40 BRN	SP	CRE	ID	TD	1/21/2048
2021 PO4079678528	KU	6	30 BRN	SP	CRE		V	1/22/2048
2021 PO4171486031	LGE	4	30 BRO	SP	CCA	ED	T	1/23/2048

2021 PO4171786034	LGE	4	35 BRO	SP	CCA		V	1/24/2048
2021 PO4071185209	LGE	1	75 BRN	SP	CRE	ED,ID,IP	BD	1/25/2048
2021 PO4080285430	LGE	4	40 ACE	SP	P	ED,ID	BD	1/26/2048
2021 PO4070085229	LGE	1	95 BRN	SP	CRE	ED,ID	BD	1/27/2048
2021 PO4082685156	LGE	3	45 BRN	SP	CRE	ED,ID,IP	BD	1/28/2048
2021 PO4082385425	LGE	4	30 ACE	SP	P	ED,ID	BD	1/29/2048
2021 PO4083785172	LGE	4	40 BRN	SP	CCA	ED,ID,IP	BD	1/30/2048
2021 PO4079585383	LGE	4	35 ACE	SP	P	ED,ID	BD	1/31/2048
2021 PO4075985197	LGE	4	40 BRN	SP	CCA	ED,ID,IP	BD	2/1/2048
2021 PO4079485394	LGE	4	35 ACE	SP	P	ED,ID	BD	2/2/2048
2021 PO4079385375	LGE	4	40 ACE	SP	P	ED,ID	BD	2/3/2048
2021 PO4069285106	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	2/4/2048
2021 PO4075485191	LGE	4	40 BRN	SP	A	ED,ID,IP	BD	2/5/2048
2021 PO4069285064	LGE	4	40 BRN	SP	A	ED,EP,ID	BD	2/6/2048
2021 PO4067985064	LGE	4	40 BRN	SP	A	ED,ID	BD	2/7/2048
2021 PO3729488068	KU	3	45 BRN	SP	CRE	ID	BD	2/8/2048
2021 PO3766387891	KU	5	35 BRN	SP	CRE	ID	BD	2/9/2048
2021 3789987872a	KU	4	40 BRN	SP	CRE	ID	BD	2/10/2048
2021 PO3924322229	KU	2	60 BRO	SP	CRE		B	2/11/2048
2021 PO3958522192	KU	4	40 BRO	SP	CCA		B	2/12/2048
2021 PO3578729384	KU	2	55 BRO	SP	CCA		B	2/13/2048
2021 PO3584729161	KU	4	45 BRO	SP	CCA		B	2/14/2048
2021 PO3593130126	KU	2	55 BRO	SP	CCA		B	2/15/2048
2021 PO3588829921	KU	3	50 BRO	SP	CCA		B	2/16/2048
2021 PO3274730198	KU	3	45 BRO	SP	CCA		V	2/17/2048
2021 PO3243830008	KU	3	45 BRO	SP	CCA		V	2/18/2048
2021 PO3212029956	KU	3	45 BRO	SP	CCA		V	2/19/2048
2021 PO3176229899	KU	3	45 BRO	SP	CCA		V	2/20/2048
2021 PO3153630028	KU	3	45 BRO	SP	CCA		V	2/21/2048
2021 PO3165430533	KU	3	45 BRO	SP	CCA		V	2/22/2048
2021 PO3153130406	KU	3	45 BRO	SP	CCA		V	2/23/2048
2021 PO3137730115	KU	3	45 BRO	SP	CCA		V	2/24/2048
2021 PO3109329875	KU	3	45 BRO	SP	CCA		V	2/25/2048
2021 PO3080030008	KU	3	45 BRO	SP	CCA		V	2/26/2048
2021 PO3074330234	KU	3	45 BRO	SP	CCA		V	2/27/2048
2021 PO3073130430	KU	3	45 BRO	SP	CCA		V	2/28/2048
2021 PO3051930538	KU	3	45 BRO	SP	CCA		V	2/29/2048
2021 PO3037530603	KU	3	45 BRO	SP	CCA		V	3/1/2048
2021 PO3035930496	KU	3	45 BRO	SP	CCA		V	3/2/2048
2021 PO3013030702	KU	3	45 BRO	SP	CCA		V	3/3/2048
2021 PO3000931028	KU	3	45 BRO	SP	CCA		V	3/4/2048
2021 PO3803187395	F	4	40 BRN	SP	A		V	3/5/2048
2021 PO3005831332	KU	3	45 BRO	SP	CCA		V	3/6/2048
2021 PO2996331299	KU	3	45 BRO	SP	CCA		V	3/7/2048
2021 PO3056432267	KU	3	45 BRO	SP	CCA		V	3/8/2048
2021 PO3054532028	KU	3	45 BRO	SP	CCA		V	3/9/2048
2021 PO3044231784	KU	3	45 BRO	SP	CCA		V	3/10/2048
2021 PO3032531813	KU	3	45 BRO	SP	CCA		V	3/11/2048
2021 PO3011631652	KU	3	45 BRO	SP	CCA		V	3/12/2048
2021 PO2988931516	KU	3	45 BRO	SP	CCA		V	3/13/2048
2021 PO2975631770	KU	3	45 BRO	SP	CCA		V	3/14/2048
2021 PO2960032066	KU	3	45 BRO	SP	CCA		V	3/15/2048
2021 PO3300330487	KU	3	45 BRO	SP	CCA		V	3/16/2048
2021 PO3602732313	KU	3	45 BRN	SP	CCA		V	3/17/2048

2021 PO3602132111	KU	3	45 BRN	SP	CCA		V					3/18/2048
2021 PO3601131887	KU	4	40 BRN	SP	CCA		V					3/19/2048
2021 PO3600631478	KU	1	50 BRN	SP	CCA		V					3/20/2048
2021 PO3600531321	KU	3	50 BRN	SP	CCA		V					3/21/2048
2021 PO3600331090	KU	3	50 BRN	SP	CCA		V					3/22/2048
2021 PO3613627901	F	4	45 UNK	SP	CRE		V					3/23/2048
2021 PO3621428090	KU	3	50 BRO	SP	S		V					3/24/2048
2021 PO3646927654	KU	3	50 BRO	SP	CCA		V					3/25/2048
2021 PO3638327811	KU	3	50 BRO	SP	CCA		V					3/26/2048
2021 PO3794187515	F	4	40 BRN	SP	P		V					3/27/2048
2021 PO3800587089	KU	6	30 BRN	SP	CCA		V					3/28/2048
2021 PO3835487074	KU	3	50 BRN	SP	CCA		V					3/29/2048
2021 PO3602832482	KU	3	50 BRN	SP	S		V					3/30/2048
2021 PO3846386930	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX		RR			3/31/2048
2021 PO3826286929	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX		RR			4/1/2048
2021 PO3760987075	KU	4	40 BRN	SP	CRE	ID	TD					4/2/2048
2021 PO3749686911	KU	4	40 BRN	SP	CRE	ID	TD					4/3/2048
2021 PO3858486736	KU	4	40 BRN	SP	CRE	ID	TD					4/4/2048
2021 PO3830087675	KU	4	40 BRN	SP	CRE	ID	TD					4/5/2048
2021 PO3801287532	KU	4	40 BRN	SP	CRE	ID	TD					4/6/2048
2021 PO3898322377	KU	6	30 UNK	SP	CRE	ED,ID	TD					4/7/2048
2021 PO3808987269	KU	4	40 BRN	SP	CRE	ID	TD					4/8/2048
2021 PO3790487357	KU	6	30 BRN	SP	CRE	ID	TD					4/9/2048
2021 PO3801487304	KU	4	40 BRN	SP	CRE	ID	TD					4/10/2048
2021 PO3831287383	KU	4	40 BRN	SP	CCA	ED	T					4/11/2048
2021 PO3615228177	KU	4	45 BRO	SP	S	MD	BD					4/12/2048
2021 PO3602528312	KU	4	45 BRO	SP	S	MD	BD					4/13/2048
2021 PO3590528784	KU	4	45 BRO	SP	S	MD	BD					4/14/2048
2021 PO3596328540	KU	4	45 BRO	SP	S	MD	BD					4/15/2048
2021 PO3892222411	KU	4	45 KOP	SP	CRE	ID	BD					4/16/2048
2021 PO3621827702	KU	4	40 UNK	SP	CRE	ID	BD					4/17/2048
2021 PO3823487234	KU	5	45 BRN	SP	CRE	ID	BD					4/18/2048
2021 PO3805087047	KU	4	40 BRN	SP	CRE	ID	BD					4/19/2048
2021 PO3816386954	KU	4	40 BRN	SP	CRE	ID	BD					4/20/2048
2021 PO3826686821	KU	4	40 BRN	SP	CRE	ID	BD					4/21/2048
2021 PO3811587395	KU	3	45 BRN	SP	CRE	ID	BD					4/22/2048
2021 PO3781287184	KU	4	40 BRN	SP	CRE	ID	BD					4/23/2048
2021 PO3858786891	KU	4	40 BRN	SP	CRE	ID	BD					4/24/2048
2021 PO3793887294	KU	4	40 BRN	SP	CRE	ID	BD					4/25/2048
2021 PO3772287104	KU	4	40 BRN	SP	CRE	ID	BD					4/26/2048
2021 PO3627628003	KU	2	55 BRO	SP	CCA		B					4/27/2048
2021 PO3802224954	KU	3	50 BRO	SP	CCA		V					4/28/2048
2021 PO3787425208	KU	3	50 BRO	SP	CCA		V					4/29/2048
2021 PO3772225447	KU	3	50 BRO	SP	CCA		V					4/30/2048
2021 PO3756925689	KU	3	50 BRO	SP	CCA		V					5/1/2048
2021 PO3742925920	KU	3	50 BRO	SP	CCA		V					5/2/2048
2021 PO3729926156	KU	3	50 BRO	SP	CCA		V					5/3/2048
2021 PO3718826356	KU	3	50 BRO	SP	CCA		V					5/4/2048
2021 PO3707426561	KU	3	50 BRO	SP	CCA		V					5/5/2048
2021 PO3694726792	KU	3	50 BRO	SP	CCA		V					5/6/2048
2021 PO3681827023	KU	3	50 BRO	SP	CCA		V					5/7/2048
2021 PO3670327231	KU	3	50 BRO	SP	CCA		V					5/8/2048
2021 PO3657627462	KU	3	50 UNK	SP	CCA		V					5/9/2048
2021 PO3861223259	F	4	35 UNK	SP	P		V					5/10/2048

2021 PO3866923292	KU	2	50 BRN	SP	CCA		V	5/11/2048
2021 PO3834223841	KU	2	50 BRO	SP	CCA		V	5/12/2048
2021 PO3832023790	KU	2	50 BRO	SP	CCA		V	5/13/2048
2021 PO3750825473	KU	3	45 BRO	SP	CCA		V	5/14/2048
2021 PO3762825253	KU	3	45 BRO	SP	CCA		V	5/15/2048
2021 PO3816424730	KU	3	50 BRO	SP	CCA		V	5/16/2048
2021 PO3831024487	KU	3	50 BRO	SP	CCA		V	5/17/2048
2021 PO3847424218	KU	2	55 BRO	SP	CCA		V	5/18/2048
2021 PO3842724080	KU	3	50 BRO	SP	CCA		V	5/19/2048
2021 PO3838423952	KU	3	50 BRO	SP	CCA		V	5/20/2048
2021 PO3608532720	KU	3	45 BRO	SP	CCA		V	5/21/2048
2021 PO3735525753	KU	3	45 BRO	SP	CCA		V	5/22/2048
2021 PO3838523691	KU	2	50 UNK	SP	CRE	ID	TD	5/23/2048
2021 PO3815124053	KU	4	45 BRO	SP	CRE	ED,ID	TD	5/24/2048
2021 PO3850723498	KU	4	40 UNK	SP	CRE	ED,ID	TD	5/25/2048
2021 PO3592631659	KU	4	40 UNK	SP	CRE	ID	TD	5/26/2048
2021 PO3601331654	KU	4	40 BRO	SP	CRE	ID	TD	5/27/2048
2021 PO3840723659	KU	2	50 KOP	SP	CRE	ID	BD	5/28/2048
2021 PO3845123586	KU	4	45 KOP	SP	CRE	ID	BD	5/29/2048
2021 PO3596732841	KU	3	50 BRO	SP	CCA		B	5/30/2048
2021 PO3599432492	KU	3	50 BRO	SP	CCA		B	5/31/2048
2021 PO3799324205	KU	3	55 BRO	SP	CRE		B	6/1/2048
2021 PO3675687147	KU	4	40 BRN	SP	CRE	ID	TD	6/2/2048
2021 PO4162385810	F	3	45 BRO	SP	CCA		V	6/3/2048
2021 PO4186809650	KU	3	45 BRN	SP	CCA	ED	TD	6/4/2048
2021 PO4172309426	KU	3	40 BRN	SP	CCA		V	6/5/2048
2021 PO4183409437	KU	2	50 BRN	SP	CCA	ED	TD	6/6/2048
2021 PO4011885267	F	3	45 BRN	SP	CCA		V	6/7/2048
2021 PO4012885267	F	4	40 BRN	SP	CCA		V	6/8/2048
2021 PO4252709288	KU	3	45 BRN	SP	CRE	ED	TD	6/9/2048
2021 PO4012585259	LGE	4	30 BRN	SP	CCA		V	6/10/2048
2021 PO3928710853	KU	4	40 XXX	SP	P	ED,ID	TD	6/11/2048
2021 PO4013685266	F	3	45 BRN	SP	CCA		V	6/12/2048
2021 PO4014985274	F	4	30 BRN	SP	CCA		V	6/13/2048
2021 PO3895388467	KU	5	35 BRN	SP	CRE	ID	TD	6/14/2048
2021 PO3683487410	KU	5	35 BRN	SP	CRE	ID	TD	6/15/2048
2021 PO3676687457	KU	4	40 BRN	SP	CCA		V	6/16/2048
2021 PO3689487518	KU	6	35 BRN	SP	CCA		V	6/17/2048
2021 PO4096085207	LGE	4	40 BRO	SP	CRE	ED,ID	BD	6/18/2048
2021 PO4096585204	LGE	4	40 BRO	SP	A	ID	TD	6/19/2048
2021 PO4097285213	LGE	4	35 BRO	SP	CRE	ED,ID	TD	6/20/2048
2021 PO4013985273	F	4	40 BRN	SP	A		V	6/21/2048
2021 PO4010085300	LGE	4	40 BRN	SP	CCA		V	6/22/2048
2021 PO4009785296	F	4	40 BRN	SP	CCA		V	6/23/2048
2021 PO6344510023	KU	4	40 ACW	SP	CRE	ED,ID	BD	6/24/2048
2021 PO6376409869	KU	4	40 ACW	SP	CRE	ED,ID,JP	TD	6/25/2048
2021 PO6376409869A	KU	4	40 ACW	SP	P	ED,ID	TD	6/26/2048
2021 PO4229809293	KU	3	50E BRN	SP	CCA	ED	V	6/27/2048
2021 PO4011485290	F	4	30 BRN	SP	CCA		V	6/28/2048
2021 PO4095285220	LGE	4	35 BRO	SP	CCA		V	6/29/2048
2021 PO4099285217	LGE	4	30 BRO	SP	A	ED,ID	TD	6/30/2048
2021 PO4099085210	LGE	4	30 BRO	SP	A	ID	BD	7/1/2048
2021 PO4597308184	KU	7	35 BRN	SP	CCA		V	7/2/2048
2021 PO6412210272	KU	4	45 ACW	SP	CRE	ED,ID	X PX	7/3/2048

2021 PO4103285313	LGE	6	35 BRO	SP	CRE	ED,ID,IP,SRC	TX	RR	7/4/2048
2021 PO4136885598	LGE	4	40 ACE	SP	CCA		V		7/5/2048
2021 PO4137185582	LGE	4	35 ACE	SP	P	ED,ID,IP	TD		7/6/2048
2021 PO4592308187	KU	7	35 BRN	SP	CCA	ED	TD		7/7/2048
2021 PO4102785337	LGE	4	30 BRO	SP	CCA		V		7/8/2048
2021 PO4102685330	LGE	4	40 BRO	SP	A	ED,ID	TD		7/9/2048
2021 PO4103985326	LGE	6	25 BRO	SP	CRE		V		7/10/2048
2021 PO4598908280	KU	3	40 BRN	SP	CRE	ED,ID	TD		7/11/2048
2021 PO4598008401	KU	3	40 BRN	SP	CRE	ED,ID	TD		7/12/2048
2021 PO4137685516	LGE	4	40 ACE	SP	P	ED,ID	TD		7/13/2048
2021 PO4137085529	LGE	4	40 ACE	SP	P	ED,ID	TD		7/14/2048
2021 PO4136585542	LGE	4	40 ACE	SP	P	ED,ID,IP	TD		7/15/2048
2021 PO4136085554	LGE	4	40 ACE	SP	P	ED,ID,IP	TD		7/16/2048
2021 PO4159085789	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		7/17/2048
2021 PO4595908528	KU	5	40 BRN	SP	CRE	ED,ID	TD		7/18/2048
2021 PO4592508620	KU	4	40 BRN	SP	CCA	ED	TD		7/19/2048
2021 PO4159085779	LGE	4	40 BRO	SP	CRE	ED,ID	TD		7/20/2048
2021 PO4158985768	LGE	4	35 BRO	SP	CCA		V		7/21/2048
2021 PO4134185572a	KU	4	40 ACE	SP	P	ED,EP,ID,IP	TX	RR	7/22/2048
2021 PO4134185572	KU	4	40 ACE	SP	CRE	ED,ID	TD		7/23/2048
2021 PO4136385575	F	4	40 ACE	SP	P		V		7/24/2048
2021 PO4589308750	KU	3	40 BRN	SP	CCA		V		7/25/2048
2021 PO4583208742	KU	3	40 BRN	SP	CCA	ED	TD		7/26/2048
2021 PO4158885752	LGE	4	30 BRO	SP	A	ED,ID	TD		7/27/2048
2021 PO4158985757	LGE	3	45 BRO	SP	CCA		V		7/28/2048
2021 PO4569609200	F	3	45 BRN	SP	CRE	ED,HH,ID,IP	BX	PX	7/29/2048
2021 PO6378910018	KU	6	30 ACW	SP	CRE	ED,ID	BX	PX	7/30/2048
2021 PO4160685778	F	4	35 BRO	SP	A		V		7/31/2048
2021 PO4160785788	F	4	35 BRO	SP	A		V		8/1/2048
2021 PO4100585377	LGE	4	40 BRO	SP	P	ED,ID	BD		8/2/2048
2021 PO4161485811	F	4	40 BRO	SP	A		V		8/3/2048
2021 PO3791670484	KU	2	50 BRN	SP	CCA		V		8/4/2048
2021 PO3790970701	KU	3	45 BRN	SP	CCA		V		8/5/2048
2021 PO3789870895	KU	2	50 BRN	SP	CCA		V		8/6/2048
2021 PO3720569519	KU	3	45 BRN	SP	CCA		V		8/7/2048
2021 PO3720669430	KU	3	45 BRN	SP	CCA		V		8/8/2048
2021 PO3720569693	KU	3	45 BRN	SP	CCA		V		8/9/2048
2021 PO3737969929	KU	4	40 BRN	SP	CCA		V		8/10/2048
2021 PO3753370087	KU	4	45 BRN	SP	CCA		V		8/11/2048
2021 PO3767270227	KU	4	40 BRN	SP	CCA		V		8/12/2048
2021 PO3779670361	KU	3	45 BRN	SP	CCA		V		8/13/2048
2021 PO6440809112	KU	2	50 ACW	SP	S		V		8/14/2048
2021 PO6463310887	KU	4	40 ACW	SP	CRE	ED,ID	TD		8/15/2048
2021 PO4103485359	LGE	4	40 BRO	SP	A	ID	BD		8/16/2048
2021 PO4160385811	F	4	40 BRO	SP	A		V		8/17/2048
2021 PO4082785402	LGE	4	35 ACE	SP	P	ED,ID	TD		8/18/2048
2021 PO4081685402	LGE	4	35 ACE	SP	P	ED,ID,IP	TD		8/19/2048
2021 PO4160885819	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		8/20/2048
2021 PO4161085827	F	4	35 BRO	SP	A	HH,RB	VX	RP1	8/21/2048
2021 PO4160985837	F	5	35 BRO	SP	CCA		V		8/22/2048
2021 PO4161185844	F	4	35 BRO	SP	CRE		V		8/23/2048
2021 PO4100485363	LGE	4	40 BRO	SP	P	ED,RB	X	RP3	8/24/2048
2021 PO3868012459	KU	3	45 XXX	SP	CRE	ED,ID	TD		8/25/2048
2021 PO4568508513	KU	3	45 BRN	SP	CCA	ED	TD		8/26/2048

2021	PO3988285458	LGE	4	30 BRN	SP	CCA		V		8/27/2048
2021	PO3987185459	LGE	4	40 BRN	SP	CCA	ED,ID,IP	BD		8/28/2048
2021	PO3986585462	LGE	4	30 BRN	SP	CCA	ED,ID,IP	TD		8/29/2048
2021	PO3987585467	LGE	3	45 BRN	SP	CCA		V		8/30/2048
2021	PO3986185475	LGE	4	35 BRN	SP	CCA		V		8/31/2048
2021	PO4543708628	F	3	40 BRN	SP	CRE	ED,ID	V		9/1/2048
2021	PO4563808518	KU	3	45 BRN	SP	CRE	ED	TD		9/2/2048
2021	PO4547408571	KU	3	45 BRN	SP	CCA	ED	TD		9/3/2048
2021	PO4100285344	LGE	4	40 BRO	SP	A	ED,ID	TD		9/4/2048
2021	PO4092885286	LGE	4	40 BRO	SP	CRE	ED,HH,ID	BD		9/5/2048
2021	PO4080785401	LGE	4	35 ACE	SP	P	ED,ID	TD		9/6/2048
2021	PO4080185401	LGE	4	35 ACE	SP	P	ED,ID	TD		9/7/2048
2021	PO4161085855	F	4	35 BRO	SP	CRE		V		9/8/2048
2021	PO4161185869	F	4	30 BRO	SP	A		V		9/9/2048
2021	PO4161085862	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	9/10/2048
2021	PO3874912486	F	4	40 SWP	SP	P		V		9/11/2048
2021	PO3874712446	KU	3	45 BRN	SP	CCA		V		9/12/2048
2021	PO4087685301	LGE	4	40 ACE	SP	P	ED,ID	TD		9/13/2048
2021	PO3986585476	LGE	3	45 BRN	SP	CCA		V		9/14/2048
2021	PO3986785487	LGE	4	35 BRN	SP	P	ED,ID	BD		9/15/2048
2021	PO3985785499	LGE	3	45 BRN	SP	CCA		V		9/16/2048
2021	PO4161285881	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		9/17/2048
2021	PO4161285889	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		9/18/2048
2021	PO4161385900	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		9/19/2048
2021	PO4559009001a	KU	3	40E BRN	SP	P	ED	V		9/20/2048
2021	PO4559009001	F	5	40 BRN	SP	CRE	ED	V		9/21/2048
2021	PO4562908964	KU	4	40 BRN	SP	CCA		V		9/22/2048
2021	3985585491	KU	4	40 BRN	SP	CCA		V		9/23/2048
2021	PO3985985492	LGE	3	45 BRN	SP	CCA		V		9/24/2048
2021	PO3985285513	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD		9/25/2048
2021	PO3985585527	LGE	4	30 BRN	SP	CCA		V		9/26/2048
2021	PO3985885531	LGE	4	35 BRN	SP	CCA		V		9/27/2048
2021	PO3984885527	LGE	4	40 BRN	SP	CCA		V		9/28/2048
2021	PO3984185544	LGE	4	40 BRN	SP	CRE	ED,ID	BD		9/29/2048
2021	PO3787371106	KU	3	45 BRN	SP	CCA		V		9/30/2048
2021	3819171270	KU	3	45 BRN	SP	CCA		V		10/1/2048
2021	PO3797371514	KU	3	45 BRN	SP	CCA		V		10/2/2048
2021	PO3825472072	KU	4	40 BRN	SP	CCA		V		10/3/2048
2021	PO5392731743	KU	4	40 UNK	SP	CRE	ID	BD		10/4/2048
2021	PO5363032366	KU	4	35 UNK	SP	CRE	ID	X	RP1	10/5/2048
2021	PO5381032208	KU	6	30 UNK	SP	CRE	ID	TD		10/6/2048
2021	4063486692A	LGE	5	30 ACE	SP	CCA		T		10/7/2048
2021	PO4013283349	LGE	4	35 BRO	SP	CRE	ED,ID	TD		10/8/2048
2021	PO4012883343	LGE	4	35 BRO	SP	CRE	ED,ID	TD		10/9/2048
2021	PO4089485848	F	4	40 ACE	SP	A		V		10/10/2048
2021	PO4012283335	LGE	4	35 BRO	SP	CRE	ED,ID	TD		10/11/2048
2021	PO4085885851	F	4	40 ACE	SP	CRE		V		10/12/2048
2021	PO4084785852	F	4	40 ACE	SP	CRE		V		10/13/2048
2021	PO4083585853	F	4	40 ACE	SP	CCA		V		10/14/2048
2021	PO4082285855	F	4	40 ACE	SP	CRE		V		10/15/2048
2021	PO4081185856	F	4	35 ACE	SP	CRE		V		10/16/2048
2021	PO4079885857	F	4	35 ACE	SP	CRE		V		10/17/2048
2021	PO4090785846	F	4	40 ACE	SP	CRE		V		10/18/2048
2021	PO4087885849	F	3	45 ACE	SP	CCA		V		10/19/2048



2021 PO4117284279	LGE	4	35 KOP	SP	P	ED,ID,IP	BD	10/20/2048
2021 PO4021083314	LGE	4	40 BRO	SP	A	ID	BD	10/21/2048
2021 PO4019183296	LGE	4	40 BRO	SP	A	ID,IP	BD	10/22/2048
2021 PO5407032512	KU	5	35 UNK	SP	CRE	ID	TD	10/23/2048
2021 PO4017383279	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	10/24/2048
2021 PO4011683224	LGE	4	40 BRO	SP	A		V	10/25/2048
2021 PO4041885814	LGE	4	35 KOP	SP	A	ED,ID,IP	TD	10/26/2048
2021 PO4043085806	F	4	40 KOP	SP	A		V	10/27/2048
2021 PO4043585810	F	4	30 KOP	SP	A		V	10/28/2048
2021 PO4044485796	F	5	30 KOP	SP	A		V	10/29/2048
2021 PO4043485796	F	4	30 KOP	SP	A		V	10/30/2048
2021 PO5404032432	KU	4	35 KOP	SP	CRE	ID	TD	10/31/2048
2021 PO3976085647	F	4	40 ACE	SP	CRE		V	11/1/2048
2021 PO4043585790	F	4	30 KOP	SP	P		V	11/2/2048
2021 PO4042985791	F	4	40 KOP	SP	A		V	11/3/2048
2021 PO4010983220	LGE	4	40 BRO	SP	A		V	11/4/2048
2021 PO4075986536	LGE	3	45 ACE	SP	CRE	ED,ID	BD	11/5/2048
2021 4074186541A	LGE	5	30 ACE	SP	CRE	ED,ID	TD	11/6/2048
2021 PO4074186541	LGE	3	45 ACE	SP	CCA		V	11/7/2048
2021 PO7095769875	LGE	1	50 ACE	SP	CCA		V	11/8/2048
2021 PO5362125384	KU	4	40 UNK	SP	CRE		T	11/9/2048
2021 PO5362625660	KU	4	40 UNK	SP	CRE		T	11/10/2048
2021 PO5376125663	KU	3	50 UNK	SP	CCA		V	11/11/2048
2021 PO4044785882	LGE	4	30 KOP	SP	CCA	ED,ID,IP,MD	TD	11/12/2048
2021 PO4014683369	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	11/13/2048
2021 PO4044685878	F	3	45 KOP	SP	CCA		V	11/14/2048
2021 PO4045085874	F	4	35 KOP	SP	CCA		V	11/15/2048
2021 PO4044685859	F	5	30 KOP	SP	A		V	11/16/2048
2021 PO4044285861	F	3	45 KOP	SP	CCA		V	11/17/2048
2021 PO5371525215	KU	4	40 UNK	SP	CRE		B	11/18/2048
2021 PO4044085828	LGE	4	40 KOP	SP	CCA		V	11/19/2048
2021 PO5394932429	KU	5	35 UNK	SP	CRE	ID	TD	11/20/2048
2021 PO4043385828	LGE	UNK	45 KOP	UN	CCA		V	11/21/2048
2021 PO4017083397	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	11/22/2048
2021 PO4043485826	F	4	40 KOP	SP	A		V	11/23/2048
2021 PO4042985819	F	4	30 KOP	SP	P		V	11/24/2048
2021 PO4043285818	F	3	45 KOP	SP	A		V	11/25/2048
2021 PO5371025116	KU	4	40 UNK	SP	CRE		B	11/26/2048
2021 PO5369624876	KU	4	40 UNK	SP	CRE		B	11/27/2048
2021 PO5369024771	KU	5	30 UNK	SP	CRE		B	11/28/2048
2021 PO5370325006	KU	4	40 UNK	SP	CCA		V	11/29/2048
2021 PO4043385776	F	4	40 KOP	SP	A		V	11/30/2048
2021 PO4042885777	F	4	40 KOP	SP	A		V	12/1/2048
2021 PO4072386114	F	4	40 ACE	SP	CRE		V	12/2/2048
2021 PO5347925144	KU	6	30 UNK	SP	CRE		T	12/3/2048
2021 PO5342725233	KU	4	40 UNK	SP	CRE		B	12/4/2048
2021 PO4010185924	LGE	4	35 ACE	SP	P	ED,HH,ID,RB	BX	12/5/2048
2021 PO4121684350	F	4	40 KOP	SP	A		V	12/6/2048
2021 PO7823578893	F	4	35 ACE	SP	CCA		V	12/7/2048
2021 PO7816379329	LGE	4	35 ACE	SP	CCA		V	12/8/2048
2021 PO7816779329	LGE	4	35 ACE	SP	CCA		V	12/9/2048
2021 PO7816279179	LGE	4	35 ACE	SP	CCA		V	12/10/2048
2021 PO7817379029	LGE	4	35 ACE	SP	CCA		V	12/11/2048
2021 PO4120684338	F	4	40 KOP	SP	A		V	12/12/2048

2021 PO4120084323	F	4	40 KOP	SP	CCA		V	12/13/2048	
2021 PO4120084309	F	4	40 KOP	SP	CCA		V	12/14/2048	
2021 PO4120084299	F	4	40 KOP	SP	A		V	12/15/2048	
2021 PO4071986747	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	12/16/2048	
2021 PO4009185935	LGE	4	40 ACE	SP	P	ED,ID	TD	12/17/2048	
2021 PO4119984291	F	4	40 KOP	SP	CCA		V	12/18/2048	
2021 PO4008685938	F	4	45 ACE	SP	A		V	12/19/2048	
2021 PO4008085932	F	4	45 ACE	SP	A		V	12/20/2048	
2021 PO4120984290	F	4	40 KOP	SP	A		V	12/21/2048	
2021 PO5065613055	KU	4	40 KOP	SP	CRE	ED,ID,RB,Src	TX	RR	12/22/2048
2021 PO4115584324	F	3	45 KOP	SP	CCA		V	12/23/2048	
2021 PO7297871712	LGE	4	35 ACE	SP	CCA		V	12/24/2048	
2021 PO4016085992	LGE	4	40 ACE	SP	CRE	ED,ID	BD	12/25/2048	
2021 PO4014085981	F	3	45 ACE	SP	CCA		V	12/26/2048	
2021 PO4014385993	F	3	45 ACE	SP	CCA		V	12/27/2048	
2021 PO4014585995	LGE	4	30 ACE	SP	CCA		V	12/28/2048	
2021 PV4012385974	F	3	45 ACE	SP	P		V	12/29/2048	
2021 PV4011185957	LGE	3	45 ACE	SP	CCA		V	12/30/2048	
2021 PV4011585966	F	4	45 ACE	SP	P		V	12/31/2048	
2021 PO4019783332	F	4	30 BRO	SP	A		V	1/1/2049	
2021 PO4020183337	F	4	30 BRO	SP	CRE		V	1/2/2049	
2021 PO5474431984	KU	4	35 UNK	SP	CRE	ID	TD	1/3/2049	
2021 PO5475831890	KU	4	40 UNK	SP	CRE	ID	BD	1/4/2049	
2021 PO5450231845	KU	4	35 UNK	SP	CRE	ID	TX	RR	1/5/2049
2021 PO4077785859	F	4	40 ACE	SP	CRE		V	1/6/2049	
2021 PO4108985845	LGE	4	35 ACE	SP	CCA		V	1/7/2049	
2021 PO5304125208	KU	3	45 UNK	SP	CRE		B	1/8/2049	
2021 4059686681A	LGE	5	30 ACE	SP	CCA	ED,ID	TD	1/9/2049	
2021 PO4059986676	LGE	4	30 ACE	SP	CRE	ED,ID	TD	1/10/2049	
2021 PO4057886676	LGE	UNK	60 ACE	SP	CRE	ED,ID	TD	1/11/2049	
2021 PO4059686681	LGE	UNK	60 ACE	SP	CRE	ED,ID	TD	1/12/2049	
2021 PO4059086683	F	4	35 ACE	SP	CCA		V	1/13/2049	
2021 PO4056086671	LGE	4	40 ACE	SP	CRE	ED,ID	TD	1/14/2049	
2021 PO4000785874	LGE	3	50 ACE	SP	CRE	ED,ID	BD	1/15/2049	
2021 PO4024785955	F	3	45 ACE	SP	CCA		V	1/16/2049	
2021 PO4024285958	F	3	45 ACE	SP	P		V	1/17/2049	
2021 PO4023085964	F	3	45 ACE	SP	CCA		V	1/18/2049	
2021 PO3989985737	LGE	3	50 ACE	SP	CRE	ED,ID	TD	1/19/2049	
2021 PO3990685748	LGE	3	50 ACE	SP	CRE	ED,ID	TD	1/20/2049	
2021 PO7075269566	LGE	3	50 ACE	SP	CCA		V	1/21/2049	
2021 PO3991485759	LGE	3	50 ACE	SP	CRE	ED,ID	TD	1/22/2049	
2021 PO4050885975	F	4	40 KOP	SP	CCA		V	1/23/2049	
2021 PO4049385976	F	4	40 KOP	SP	A		V	1/24/2049	
2021 PO4046885981	F	4	30 KOP	SP	A		V	1/25/2049	
2021 PO4046985978	F	UNK	45 KOP	SP	A		V	1/26/2049	
2021 PO4046885970	LGE	4	30 KOP	UN	CCA		V	1/27/2049	
2021 PO4046785969	F	4	40 KOP	SP	P		V	1/28/2049	
2021 PO5305425336	KU	3	45 UNK	SP	CRE		B	1/29/2049	
2021 PO5311425331	KU	3	45 UNK	SP	CRE		B	1/30/2049	
2021 PO5087812892	KU	4	40 KOP	SP	CRE	ED,ID	BD	1/31/2049	
2021 PO5075112982	KU	4	40 KOP	SP	CRE	ED,ID	BD	2/1/2049	
2021 PO3988983464	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	2/2/2049	
2021 PO4011383322	LGE	4	35 BRO	SP	CRE	ED,ID	TD	2/3/2049	
2021 PO4046485956	F	4	40 KOP	SP	A		V	2/4/2049	

2021 PO4046185943	F	3	45 KOP	SP	CCA		V	2/5/2049
2021 PO4045885931	F	4	40 KOP	SP	CCA		V	2/6/2049
2021 PO4046385931	F	5	35 KOP	SP	A		V	2/7/2049
2021 PO5324025322	KU	3	45 UNK	SP	CRE		B	2/8/2049
2021 PO7678078500	LGE	3	45 ACE	SP	CCA		V	2/9/2049
2021 PO4054786668	LGE	4	40 ACE	SP	CRE	ED,ID	BD	2/10/2049
2021 PO4054286666	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	2/11/2049
2021 PO4052686666	LGE	3	50 ACE	SP	CRE	ED,ID	BD	2/12/2049
2021 PO4010683318	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	2/13/2049
2021 PO5346225560	KU	2	45 UNK	SP	CRE		T	2/14/2049
2021 PO5346925689	KU	2	45 UNK	SP	CRE		B	2/15/2049
2021 PO5345425400	KU	4	40 UNK	SP	CRE		T	2/16/2049
2021 PO4045585917	F	4	40 KOP	SP	P		V	2/17/2049
2021 PO4046085916	F	4	30 KOP	SP	A		V	2/18/2049
2021 PO5092612584	F	4	40 KOP	SP	CRE		V	2/19/2049
2021 PO4094885812	LGE	4	40 ACE	SP	CRE		V	2/20/2049
2021 PO4093785802	F	4	40 ACE	SP	CCA		V	2/21/2049
2021 PO4092185803	F	4	40 ACE	SP	CRE		V	2/22/2049
2021 PO4090485805	F	4	45 ACE	SP	CRE		V	2/23/2049
2021 PO4089485811	F	4	30 ACE	SP	P		V	2/24/2049
2021 PO4087585808	F	4	45 ACE	SP	CRE		V	2/25/2049
2021 PO4119384348	F	4	40 KOP	SP	A		V	2/26/2049
2021 PO4079185857	F	4	40 ACE	SP	CRE		V	2/27/2049
2021 PO4089384267	LGE	4	30 KOP	SP	A	ED,ID,IP,RB	TD	2/28/2049
2021 PO4027986292	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1 3/1/2049
2021 PO4089684262	LGE	4	35 KOP	SP	A	ED,EP,ID,IP,MD	BD	3/2/2049
2021 PO4090184278	LGE	4	35 KOP	SP	P	ED,HH,ID,IP	TD	3/3/2049
2021 PO4090284269	LGE	3	45 KOP	SP	CCA		V	3/4/2049
2021 PO4016586009	LGE	4	35 ACE	ST	CCA		V	3/5/2049
2021 PO5131411339	F	4	40 KOP	SP	S		V	3/6/2049
2021 PO5143111283	F	4	40 KOP	SP	CRE		V	3/7/2049
2021 PO5123911373A	F	4	35 KOP	SP	S		V	3/8/2049
2021 PO5084512243	F	4	40 KOP	SP	CRE		V	3/9/2049
2021 PO5091612305	F	4	40 KOP	SP	CRE		V	3/10/2049
2021 PO5061711673	F	4	40 KOP	SP	CRE		V	3/11/2049
2021 PO5074511983	F	4	40 KOP	SP	CRE		V	3/12/2049
2021 PO4085984246	LGE	4	35 KOP	SP	P	ED,ID,IP,MD	TD	3/13/2049
2021 PO4086184242	LGE	4	30 KOP	SP	P	ED,EP,ID,MD	TD	3/14/2049
2021 PO4088284260	LGE	4	40 KOP	SP	P	ED,ID	TD	3/15/2049
2021 PO4046186284	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	3/16/2049
2021 PO4047786283	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	3/17/2049
2021 PO4047486283	LGE	1	70 ACE	SP	P		V	3/18/2049
2021 PO4044086276	LGE	3	45 ACE	SP	CRE	ED,ID	TD	3/19/2049
2021 PO4044786272	LGE	4	35 ACE	SP	CRE	ED,ID	TD	3/20/2049
2021 PO4045286260	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	3/21/2049
2021 PO4045286267	LGE	4	35 ACE	SP	CRE	ED,ID	TD	3/22/2049
2021 PO4091584268	LGE	4	35 KOP	SP	A	ED,ID,IP	TD	3/23/2049
2021 PO5103611468	F	4	45 KOP	SP	S		V	3/24/2049
2021 PO5079612118	F	4	40 KOP	SP	CRE		V	3/25/2049
2021 PO5067811810	F	4	40 KOP	SP	CRE		V	3/26/2049
2021 PO5123911373	F	4	40 KOP	SP	S		V	3/27/2049
2021 PO5089411536	F	4	40 KOP	SP	S		V	3/28/2049
2021 PO5072011617	F	4	40 KOP	SP	S		V	3/29/2049
2021 PO5055511664	F	4	40 KOP	SP	P		V	3/30/2049

2021 PO5080211579	F	4	40 KOP	SP	P		V	3/31/2049
2021 PO4101184303	LGE	3	45 KOP	SP	CCA		V	4/1/2049
2021 PO4045286240	LGE	1	40 ACE	SP	CRE		V	4/2/2049
2021 PO3994385817	LGE	1	30 ACE	SP	CRE		V	4/3/2049
2021 PV4009985968	LGE	1	30 ACE	SP	CCA		V	4/4/2049
2021 PO4100384321	LGE	3	45 KOP	SP	CCA		V	4/5/2049
2021 PO4091484273	LGE	4	40 KOP	SP	A	ED,ID	BD	4/6/2049
2021 PO5022911822B	KU	4	35 KOP	SP	P	ED,ID	TD	4/7/2049
2021 PO5022911822A	KU	4	40 KOP	SP	P	ED,ID	TD	4/8/2049
2021 PO5024611772	KU	4	45 KOP	SP	CRE	ED,ID	TD	4/9/2049
2021 PO5020811788	KU	4	45 KOP	SP	CRE	ED,ID	BD	4/10/2049
2021 PO5022911822	KU	3	45 KOP	SP	CCA		V	4/11/2049
2021 PO4098284350	LGE	4	30 KOP	SP	P	ED,ID	BD	4/12/2049
2021 PO4099184349	LGE	3	45 KOP	SP	P	ED,EP,ID,IP	BD	4/13/2049
2021 PO4985311169	KU	4	40 KOP	SP	CRE	ED,ID	BD	4/14/2049
2021 PO4990611187	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/15/2049
2021 PO4983310967	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/16/2049
2021 PO5009911385	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/17/2049
2021 PO5026211357	KU	6	30 KOP	SP	CCA		V	4/18/2049
2021 PO5004611425	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/19/2049
2021 PO5017711374	KU	5	35 KOP	SP	S		V	4/20/2049
2021 PO4084484231	LGE	2	50 KOP	SP	A	ED,ID,IP,MD	BD	4/21/2049
2021 PO4084884239	LGE	4	35 KOP	SP	A	ED,ID,IP,RB	TD	4/22/2049
2021 PO4045286248	LGE	4	35 ACE	SP	CRE	ED,ID	TD	4/23/2049
2021 PO4044886248	LGE	4	35 ACE	SP	CRE	ED,ID	TD	4/24/2049
2021 PO4956110990	KU	5	35 KOP	SP	CRE	ED,ID	TD	4/25/2049
2021 PO4087184253	LGE	4	35 KOP	SP	P	ED,ID,MD,RB	TD	4/26/2049
2021 PO4087384249	LGE	4	30 KOP	SP	P	ED,ID,MD	TD	4/27/2049
2021 PO4088584256	LGE	4	40 KOP	SP	P	ED,ID	BD	4/28/2049
2021 PO5020210606	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/29/2049
2021 PO5022410693	KU	6	30 KOP	SP	CRE	ED,ID	TD	4/30/2049
2021 PO4997810683	KU	5	45 KOP	SP	CRE	ED,ID	TD	5/1/2049
2021 PO4964510802	KU	4	40 KOP	SP	CRE	ED,ID	BD	5/2/2049
2021 PO4954110839	KU	4	40 KOP	SP	CRE	ED,ID	BD	5/3/2049
2021 PO4975810763	KU	4	40 KOP	SP	CRE	ED,ID	TD	5/4/2049
2021 PO4973910720	KU	6	30 KOP	SP	CRE	ED,ID	TD	5/5/2049
2021 PO4113984338	F	4	40 KOP	SP	A		V	5/6/2049
2021 PO6039186610	KU	4	40 ACE	SP	CRE	HH,ID	BX	5/7/2049
2021 PO1750185819	KU	3	45 BRO	SP	CCA		V	5/8/2049
2021 PO8823495647	F	4	40 KOP	SP	P		V	5/9/2049
2021 PO8816595573	F	4	40 CPT	SP	P	ED	V	5/10/2049
2021 PO8803295524	F	4	40 CPT	SP	CRE		V	5/11/2049
2021 PO8773695575	KU	4	40 BRN	SP	CCA		V	5/12/2049
2021 PO8773695575A	KU	2	35 OTH	SP	P	ID	BD	5/13/2049
2021 PO8753195662	KU	4	40 BRN	SP	CCA		V	5/14/2049
2021 PO8765595846	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/15/2049
2021 PO8763595945	KU	4	45 KOP	SP	CRE	ED,ID	TD	5/16/2049
2021 PO8752695915	KU	4	40 OTH	SP	CRE	ED,ID	TD	5/17/2049
2021 PO8753396026	KU	4	45 OTH	SP	CRE	ED,ID	TD	5/18/2049
2021 PO8733795720	KU	4	40 OTH	SP	CRE	ED,ID	TD	5/19/2049
2021 PO8744895833	KU	4	40 OTH	SP	CRE	ED,ID	TD	5/20/2049
2021 PO8720995838	F	4	40 OTH	SP	A		V	5/21/2049
2021 PO8439868257	KU	3	45 ACE	SP	CRE	ED,ID	BD	5/22/2049
2021 PO8439968069	KU	4	45 ACE	SP	CRE	ED,ID	BD	5/23/2049

2021 PO3082295090	KU	7	30 ACE	SP	CRE	ED,ID,SRC	TD	5/24/2049	
2021 PO3069495325	F	3	45 CPT	SP	A		V	5/25/2049	
2021 PO8439768419	KU	3	45 ACE	SP	CRE	ED,ID	BD	5/26/2049	
2021 PO8448368430	KU	6	30 ACE	SP	CCA		V	5/27/2049	
2021 PO8439168520	KU	3	45 ACE	SP	CRE	ED,ID	BD	5/28/2049	
2021 PO4111785885	LGE	4	35 ACE	SP	A	ED,ID	BD	5/29/2049	
2021 PO4111885893	LGE	4	35 ACE	SP	CRE	ED,ID	BD	5/30/2049	
2021 PO4090585820	LGE	4	35 ACE	SP	CRE		V	5/31/2049	
2021 PO4110885877	LGE	4	35 ACE	SP	CRE	ID	BD	6/1/2049	
2021 PO4109385856	LGE	4	35 ACE	SP	CRE	ED,ID	BD	6/2/2049	
2021 PO8452267428	KU	3	45 ACE	SP	CRE	ED,ID	BD	6/3/2049	
2021 PO8450367326	KU	5	35 ACE	SP	CCA		V	6/4/2049	
2021 PO4006483668	LGE	3	45 BRO	SP	CCA		V	6/5/2049	
2021 PO4004983647-A	KU	5	35 BRO	SP	CRE	ED,ID	TD	6/6/2049	
2021 PO8455267309	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/7/2049	
2021 PO8446867266	KU	3	45 ACE	SP	CCA		V	6/8/2049	
2021 PO4078885812	LGE	4	30 ACE	SP	A	ED,ID	TD	6/9/2049	
2021 PO4078185814	LGE	4	40 ACE	SP	P	ID	BD	6/10/2049	
2021 PO4077985797	LGE	4	40 ACE	SP	P	ID	BD	6/11/2049	
2021 PO4077885785	LGE	4	40 ACE	SP	P	ID	BD	6/12/2049	
2021 PO4077685765	LGE	4	40 ACE	SP	P	ED,ID	BD	6/13/2049	
2021 PO7856260206	F	3	45 BRO	SP	CRE		V	6/14/2049	
2021 PO7840960360	KU	6	30 BRO	SP	CRE		V	6/15/2049	
2021 PO7180654597	KU	4	45 UNK	SP	CRE	HH,ID	X	RP2	6/16/2049
2021 PO5371628707	KU	3	45 BRO	SP	CCA		V	6/17/2049	
2021 PO5326023817	KU	4	40 BRO	SP	CCA		V	6/18/2049	
2021 PO5316123669	KU	4	40 BRO	SP	CRE	ID	TD	6/19/2049	
2021 PO5285223408	KU	5	35 BRO	SP	CRE	ED,ID,MD,SRC	X	RP3	6/20/2049
2021 PO5301923420	KU	4	40 BRO	SP	CRE	ID	TD	6/21/2049	
2021 PO5293123265	KU	4	40 BRO	SP	CRE	ID	TD	6/22/2049	
2021 PO5282623083	KU	4	45 BRO	SP	CRE	ID	TD	6/23/2049	
2021 PO5267223189	KU	5	35 BRO	SP	CRE	ID	BD	6/24/2049	
2021 PO5274123288	KU	6	30 BRO	SP	CRE		V	6/25/2049	
2021 PO5227523324	KU	4	40 BRO	SP	CCA		V	6/26/2049	
2021 PO5249123141	KU	4	35 BRO	SP	CCA		V	6/27/2049	
2021 PO5256423078	KU	4	40 BRO	SP	CRE	ID	TD	6/28/2049	
2021 PO5263123021	KU	4	40 BRO	SP	CRE	ID	BD	6/29/2049	
2021 PO5295823023	KU	5	30 BRO	SP	CRE		V	6/30/2049	
2021 PO5307723656	KU	4	40 BRO	SP	CCA		V	7/1/2049	
2021 PO5224122144	F	4	40 BRO	SP	CRE		V	7/2/2049	
2021 PO5290622811	KU	5	35 BRO	SP	CRE	ID	BD	7/3/2049	
2021 PO5283922755	KU	4	40 BRO	SP	CRE	ID	BD	7/4/2049	
2021 PO5268322830	KU	4	40 BRO	SP	CRE	ID	BD	7/5/2049	
2021 PO5260722693	KU	4	40 BRO	SP	CRE	ED,HH,ID,IP,RB	TX	RR	7/6/2049
2021 PO5243222686	KU	6	30 BRO	SP	CRE	ID	TD	7/7/2049	
2021 PO5255122591	KU	4	40 BRO	SP	CRE		V	7/8/2049	
2021 PO5251122521	KU	4	40 BRO	SP	CRE		V	7/9/2049	
2021 PO5258922466	KU	3	40 BRO	SP	CRE		V	7/10/2049	
2021 PO5248622475	KU	5	35 BRO	SP	CRE		V	7/11/2049	
2021 PO5231222059	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/12/2049	
2021 PO5193622059	KU	4	40 BRO	SP	CRE		V	7/13/2049	
2021 PO9338261850	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/14/2049	
2021 PO9475262356	KU	3	45 BRO	SP	CCA		V	7/15/2049	
2021 PO9435462393	KU	3	45 BRO	SP	CCA		V	7/16/2049	

2021 PO9405562421	KU	3	45 BRO	SP	CCA		V	7/17/2049
2021 PO9375662448	KU	3	45 BRO	SP	CCA		V	7/18/2049
2021 PO9355762466	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/19/2049
2021 PO9348262546	KU	6	35 BRO	SP	CRE	ED,ID	TD	7/20/2049
2021 PO9363362791	KU	4	40 BRO	SP	CCA		V	7/21/2049
2021 PO9394565441	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/22/2049
2021 PO9430464693	KU	3	45 BRO	SP	CCA		V	7/23/2049
2021 PO9392664730	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/24/2049
2021 PO9390764173	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/25/2049
2021 PO6553451614	KU	5	35 UNK	SP	CRE	ID	TD	7/26/2049
2021 PO6721252718	KU	4	40 UNK	SP	CCA		V	7/27/2049
2021 PO6721252368	KU	4	40 UNK	SP	CCA		V	7/28/2049
2021 PO688853822	F	4	45 UNK	SP	A		V	7/29/2049
2021 PO6920153724	KU	3	45 UNK	SP	CCA		V	7/30/2049
2021 PO4010213042	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/31/2049
2021 PO4003013038A	KU	6	30 BRN	SP	CCA		V	8/1/2049
2021 PO4003013038	KU	5	35 BRN	SP	CCA		V	8/2/2049
2021 PO6900753773	KU	3	45 UNK	SP	CCA		V	8/3/2049
2021 PO6921254046	KU	4	45 UNK	SP	CRE	ID	TD	8/4/2049
2021 PO4010813358	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/5/2049
2021 PO4122385291	F	4	40 ACE	SP	CCA		V	8/6/2049
2021 PO4122385279	F	4	40 ACE	SP	P		V	8/7/2049
2021 PO4122385273	F	4	40 ACE	SP	CCA		V	8/8/2049
2021 PO4003413436	KU	5	35 XXX	SP	CRE	ID	BD	8/9/2049
2021 PO4010913481	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/10/2049
2021 PO6936854394	KU	4	40 UNK	SP	P	ID	BD	8/11/2049
2021 PO694454371	KU	4	45 UNK	SP	CCA		V	8/12/2049
2021 PO7005954397	KU	4	40 UNK	SP	CCA		V	8/13/2049
2021 PO6992354613	KU	4	45 UNK	SP	CCA		V	8/14/2049
2021 PO4161885977	LGE	4	40 BRO	SP	CRE	ID	BD	8/15/2049
2021 PO4758001301	KU	3	45 BRN	SP	CRE	ED,ID	TD	8/16/2049
2021 PO4748401380	KU	6	35 BRN	SP	CRE	ED,ID	TD	8/17/2049
2021 PO4122285258	F	4	40 ACE	SP	CRE		V	8/18/2049
2021 PO4162485977	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/19/2049
2021 PO7909959799	F	3	45 BRO	SP	CRE		V	8/20/2049
2021 PO7893159743	KU	6	30 BRO	SP	CCA		V	8/21/2049
2021 PO7905159624	KU	4	40 BRO	SP	CRE	ED,ID	BD	8/22/2049
2021 PO7928059560	KU	4	40 BRO	SP	S		V	8/23/2049
2021 PO4011113588	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/24/2049
2021 PO4003713572	KU	5	35 XXX	SP	CRE	ED,ID	TD	8/25/2049
2021 PO3992713684	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/26/2049
2021 PO7837260295	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/27/2049
2021 PO4163886045	LGE	2	55 BRO	SP	A	ED,ID	TD	8/28/2049
2021 PO7079454764	F	5	40 UNK	SP	A		V	8/29/2049
2021 PO7071654807	F	5	40 UNK	SP	A		V	8/30/2049
2021 PO7064154848	F	5	40 UNK	SP	A		V	8/31/2049
2021 PO7045354947	F	5	40 UNK	SP	A		V	9/1/2049
2021 PO7020054989	F	5	40 UNK	SP	CRE		V	9/2/2049
2021 PO7034354979	F	4	40 UNK	SP	CCA		V	9/3/2049
2021 PO7093954624	F	4	40 UNK	SP	CRE		V	9/4/2049
2021 PO7092954505	KU	3	45 UNK	SP	CCA		V	9/5/2049
2021 PO4644003407	KU	3	40 BRN	SP	CRE	ED,ID	TD	9/6/2049
2021 PO8002159631	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/7/2049
2021 PO4649803114	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/8/2049

2021 PO7091154503	KU	3	45 UNK	SP	CCA		V	9/9/2049
2021 PO8011359544	KU	6	30 BRO	SP	CRE	ED,ID	TD	9/10/2049
2021 PO7072554630	KU	6	30 UNK	SP	CRE	ID,IP	TD	9/11/2049
2021 PO7996559546	F	4	40 BRO	SP	CRE		V	9/12/2049
2021 PO8157457914	F	4	40 BRO	SP	CRE		V	9/13/2049
2021 PO4656002847	KU	4	40 BRN	SP	CCA		V	9/14/2049
2021 PO4690802571	KU	4	35 BRN	SP	CRE	ED,ID,IP	TD	9/15/2049
2021 PO8968068695	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD	9/16/2049
2021 PO9046269112	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/17/2049
2021 PO8971570413	KU	4	45 BRO	SP	CRE	ED,ID	TD	9/18/2049
2021 PO4151584885	LGE	4	30 ACE	SP	P	ED,ID	BD	9/19/2049
2021 PO4150484886	LGE	4	40 ACE	SP	P	ED,ID	TD	9/20/2049
2021 PO4135486035	LGE	1	80 BRO	ST	P		V	9/21/2049
2021 PV8501972183	LGE	4	35 BRO	SP	CRE		V	9/22/2049
2021 PO4137186037	LGE	5	35 BRO	SP	CRE		V	9/23/2049
2021 PO4139886056	LGE	4	40 BRO	ST	CCA		V	9/24/2049
2021 PO8530172823	LGE	4	35 BRO	SP	CCA		V	9/25/2049
2021 PO8537172681	LGE	4	40 BRO	SP	CCA		V	9/26/2049
2021 PO8099758151	F	4	45 BRO	SP	A		V	9/27/2049
2021 PO8100358247	F	4	40 BRO	SP	CRE		V	9/28/2049
2021 PO8116958313	F	4	40 BRO	SP	CRE		V	9/29/2049
2021 PO4140586057	LGE	1	95 BRO	ST	P		V	9/30/2049
2021 PO4150384877	LGE	4	40 ACE	SP	CRE	ED,ID	BD	10/1/2049
2021 PO4142186081	LGE	4	35 BRO	SP	CCA		V	10/2/2049
2021 PO4028913714	KU	4	45 XXX	SP	CRE	ID,IP	BD	10/3/2049
2021 8116958313A	KU	6	30 BRO	SP	S		V	10/4/2049
2021 PO8121958097	F	4	40 BRO	SP	CRE		V	10/5/2049
2021 PO8131757754	F	4	40 BRO	SP	CRE		V	10/6/2049
2021 PO4189686239	LGE	4	40 BRO	SP	CCA		V	10/7/2049
2021 PO4189486233	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	10/8/2049
2021 PO4731702249	KU	4	40 BRN	SP	CRE	ED,ID	BD	10/9/2049
2021 PO4146084758	LGE	4	40 ACE	SP	CRE	ED,ID	BD	10/10/2049
2021 PO4147684757	LGE	4	35 ACE	SP	P	ED,ID	TD	10/11/2049
2021 PO8281558158	KU	5	35 BRO	SP	CRE		V	10/12/2049
2021 PO8301357982	KU	5	35 BRO	SP	CRE		V	10/13/2049
2021 PO4004813871	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/14/2049
2021 PO4000713945	KU	4	45 XXX	SP	CRE	ED,ID	TD	10/15/2049
2021 PO3992214028	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/16/2049
2021 PO4010513708	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/17/2049
2021 PO4015213943	KU	4	40 BRN	SP	CCA		V	10/18/2049
2021 PO4020313823	KU	4	40 XXX	SP	CRE	ID	BD	10/19/2049
2021 PO4008813784	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/20/2049
2021 PO4011914142	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/21/2049
2021 PO7115154520	KU	3	45 UNK	SP	CCA		V	10/22/2049
2021 PO7115154620	KU	3	45 UNK	SP	CCA		V	10/23/2049
2021 PO4189186230	LGE	4	40 BRO	SP	CRE	ED,IP	TD	10/24/2049
2021 PO4774501910	KU	3	40 BRN	SP	CRE	ED,ID	TD	10/25/2049
2021 PO8092959100	F	4	40 BRO	SP	CRE		V	10/26/2049
2021 PO8078858943	F	4	40 BRO	SP	S		V	10/27/2049
2021 PO8068958835	F	4	40 BRO	SP	CRE		V	10/28/2049
2021 PO8046959008	F	4	40 BRO	SP	CRE		V	10/29/2049
2021 PO8069959026	F	4	40 BRO	SP	CCA		V	10/30/2049
2021 PO8061059113	F	4	40 BRO	SP	CRE		V	10/31/2049
2021 PO7124954888	KU	3	45 UNK	SP	CCA		V	11/1/2049

2021 PO8986869988	KU	4	45 BRO	SP	CCA		V	11/2/2049	
2021 PO9001169572	KU	4	45 BRO	SP	CCA		V	11/3/2049	
2021 PO9582969455	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/4/2049	
2021 PO9013068660	KU	4	45 BRO	SP	CCA		V	11/5/2049	
2021 PO4189586221	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	11/6/2049	
2021 PO7131354572	KU	4	40 UNK	SP	CRE	ID,IP	TD	11/7/2049	
2021 PO8055359427	F	4	40 BRO	SP	CCA		V	11/8/2049	
2021 PO8040859473	F	4	40 BRO	SP	CRE		V	11/9/2049	
2021 PO8069659574	F	4	40 BRO	SP	CRE		V	11/10/2049	
2021 PO41888286211	LGE	3	45 BRO	SP	A	ED,ID	TX	RR	11/11/2049
2021 PO7045042398	KU	3	45 BRN	SP	S		V	11/12/2049	
2021 PO6985341899	KU	4	40 BRN	SP	S		V	11/13/2049	
2021 PO7076942056	KU	3	45 BRN	SP	S		V	11/14/2049	
2021 PO7161941025	KU	4	40 BRN	SP	CRE	ED	TD	11/15/2049	
2021 PO7185640815	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/16/2049	
2021 PO5274222934	KU	3	45 BRO	SP	CCA		V	11/17/2049	
2021 PO7168354551	KU	4	40 UNK	SP	CRE	ID	TD	11/18/2049	
2021 PO7175354422	KU	4	45 UNK	SP	CRE	ID	BD	11/19/2049	
2021 PO7988459345	F	4	40 BRO	SP	CRE		V	11/20/2049	
2021 PO7977759392	F	4	40 BRO	SP	CRE		V	11/21/2049	
2021 PO4147784852	LGE	4	30 ACE	SP	P	ED,ID,IP	BD	11/22/2049	
2021 PO4148584837	LGE	4	30 ACE	SP	CCA		V	11/23/2049	
2021 PO4167186077	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	X	RP1	11/24/2049
2021 PO4188186187	LGE	3	45 BRO	SP	CRE	ED,ID	TD	11/25/2049	
2021 PO4741301737	KU	3	40 BRN	SP	CRE	ED,ID	TD	11/26/2049	
2021 PO4719501851	KU	6	40 BRN	SP	CRE	ED,ID	TD	11/27/2049	
2021 PO7950958806	F	4	40 BRO	SP	CRE		V	11/28/2049	
2021 PO7940158995	F	4	40 BRO	SP	CRE		V	11/29/2049	
2021 PO7936959239	F	4	40 BRO	SP	CRE		V	11/30/2049	
2021 PO7956559144	KU	6	30 BRO	SP	CRE	ED,ID	TD	12/1/2049	
2021 PO7966659194	F	4	40 BRO	SP	CRE		V	12/2/2049	
2021 PO7967459430	F	4	40 BRO	SP	CRE		V	12/3/2049	
2021 PO7946559507	F	4	40 BRO	SP	CRE		V	12/4/2049	
2021 PO8039759619	F	4	40 BRO	SP	CRE		V	12/5/2049	
2021 8042659332A	KU	5	30 BRO	SP	CRE	ED,ID	TD	12/6/2049	
2021 PO4752202086	KU	3	40 BRN	SP	CRE	ED,ID	TD	12/7/2049	
2021 PO4781702004	F	4	40 BRN	SP	CCA		V	12/8/2049	
2021 PO4759701637	KU	3	50 BRN	SP	CRE		V	12/9/2049	
2021 PO4188386197	LGE	3	45 BRO	SP	CRE	ED,ID	TD	12/10/2049	
2021 PO4146884862	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	12/11/2049	
2021 PO8037359155	KU	4	40 BRO	SP	CRE		V	12/12/2049	
2021 PO8023659201	F	4	40 BRO	SP	CRE		V	12/13/2049	
2021 PO8051459233	F	4	40 BRO	SP	S		V	12/14/2049	
2021 PO8042659332	F	4	40 BRO	SP	S		V	12/15/2049	
2021 PO7151654536	KU	4	40 UNK	SP	CRE	ID	TD	12/16/2049	
2021 PO4188286198	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	12/17/2049	
2021 PO4188986201	LGE	4	30 BRO	SP	A	ID,IP	BD	12/18/2049	
2021 PO8008459266	F	4	40 BRO	SP	CRE		V	12/19/2049	
2021 PO8016059380	KU	6	30 BRO	SP	CRE	ED,ID	TD	12/20/2049	
2021 PO9007366932	KU	6	30 BRO	SP	CCA		V	12/21/2049	
2021 PO9081668277	F	4	40 BRO	SP	CRE		V	12/22/2049	
2021 PO9081668424	KU	4	40 BRO	SP	CCA		V	12/23/2049	
2021 PO9050768628	KU	4	40 BRO	SP	CCA		V	12/24/2049	
2021 PO8892666448	KU	2	55 BRO	SP	CCA		V	12/25/2049	



2021 PO8893466411	KU	2	50 BRO	SP	CCA					V			12/26/2049
2021 PO8924366581	KU	2	55 BRO	SP	CCA					V			12/27/2049
2021 PO8925766546	KU	2	60 BRO	SP	CCA					V			12/28/2049
2021 PO9013667249	KU	5	35 BRO	SP	CRE					V			12/29/2049
2021 PO9000567774	KU	4	45 BRO	SP	CCA					V			12/30/2049
2021 PO9006968117	KU	4	45 BRO	SP	CCA					V			12/31/2049
2021 PO9009568414	KU	4	45 BRO	SP	CCA					V			1/1/2050
2021 PO9015168882	KU	4	45 BRO	SP	CCA					V			1/2/2050
2021 PO8947768687	KU	4	40 BRO	SP	CCA					V			1/3/2050
2021 PO9024869162	F	5	40 BRO	SP	CCA					V			1/4/2050
2021 PO9019069155	KU	3	45 BRO	SP	CCA					V			1/5/2050
2021 PO4145784847	LGE	4	35 ACE	SP	P		ED,ID			TD			1/6/2050
2021 PO4146784847	LGE	4	40 ACE	SP	CRE		ED,ID			TD			1/7/2050
2021 PO7953759601	KU	6	30 BRO	SP	CCA					V			1/8/2050
2021 PO7972359658	F	4	40 BRO	SP	CRE					V			1/9/2050
2021 PO4495900901	KU	6	30 KOP	SP	CCA					V			1/10/2050
2021 PO4147184822	LGE	6	25 ACE	SP	CRE		ED,ID			TD			1/11/2050
2021 PO4148484830	LGE	4	40 ACE	SP	CRE		ED,HH,ID,RB		X		RP1		1/12/2050
2021 PO8631660195	LGE	4	45 ACE	SP	CRE		ED,EP,ID,IP				RR		1/13/2050
2021 PO4145984832	LGE	4	45 ACE	SP	CRE		ED,HH,ID,RB		X		PX		1/14/2050
2021 PO4144484833	LGE	4	40 ACE	SP	CRE		ED,EP,ID				RR		1/15/2050
2021 PO4144084833	LGE	4	40 ACE	SP	CRE		ED,ID			TD			1/16/2050
2021 PO4689301759	KU	6	35 BRN	SP	CCA					V			1/17/2050
2021 PO4710401831	KU	4	40 BRN	SP	CRE		ED,ID			TD			1/18/2050
2021 PO7233154663	KU	5	45 UNK	SP	CRE		ID,IP			TD			1/19/2050
2021 PO7744060521	F	4	40 BRO	SP	CRE					V			1/20/2050
2021 PO7740960495	F	4	40 BRO	SP	CRE					V			1/21/2050
2021 PO3977614126	KU	4	40 XXX	SP	CRE		ED,ID,IP			TD			1/22/2050
2021 PO7735560450	F	4	40 BRO	SP	CRE					V			1/23/2050
2021 PO4009312774	KU	4	40 XXX	SP	CRE		ED,ID,MD				RR		1/24/2050
2021 PO3999612808	KU	6	30 XXX	SP	CRE		ED,ID			TD			1/25/2050
2021 PO6730152176	KU	4	40 UNK	SP	CRE		ID,IP,SRS			TD			1/26/2050
2021 PO6719752090	KU	5	35 UNK	SP	CRE		ID,IP			TD			1/27/2050
2021 PO3988012906	KU	4	40 XXX	SP	CRE		ID			BD			1/28/2050
2021 PO4002612902	KU	4	40 XXX	SP	CRE		ED,ID			TD			1/29/2050
2021 PO4009612870	KU	4	40 XXX	SP	CRE		ED,ID			TD			1/30/2050
2021 PO6877353345	KU	4	40 UNK	SP	CCA					V			1/31/2050
2021 PO6881453588	F	6	30 UNK	SP	CRE					V			2/1/2050
2021 PO6893053439	KU	4	45 UNK	SP	CCA					V			2/2/2050
2021 PO4176085862	F	4	35 BRO	SP	CRE					V			2/3/2050
2021 PO6884553975	KU	3	45 UNK	SP	CRE					V			2/4/2050
2021 PO3958114152	KU	4	40 XXX	SP	CRE		ED,ID			TD			2/5/2050
2021 PO7750560580	F	4	40 BRO	SP	CRE					V			2/6/2050
2021 PO7751660501	KU	3	45 BRO	SP	CCA					V			2/7/2050
2021 PO7738060386	KU	4	45 BRO	SP	CRE		ED,ID			BD			2/8/2050
2021 PO7726360370	F	4	40 BRO	SP	CRE					V			2/9/2050
2021 PO7730860323	KU	4	40 BRO	SP	CRE		ED,ID			TD			2/10/2050
2021 PO7723760150	KU	4	40 BRO	SP	CRE		ED,ID			TD			2/11/2050
2021 PO7711860161	F	6	30 BRO	SP	CCA					V			2/12/2050
2021 PO7714360257	F	4	40 BRO	SP	CRE					V			2/13/2050
2021 PO7707860200	F	4	40 BRO	SP	A					V			2/14/2050
2021 PO4188186175	LGE	3	45 BRO	SP	CRE		ED,ID,IP			TD			2/15/2050
2021 PO4187986163	LGE	4	40 BRO	SP	CRE		ED,ID,IP,RB		X		RP1		2/16/2050
2021 PO7252554570	KU	5	35 UNK	SP	CRE		ID,IP			BD			2/17/2050

2021 PO7260854697	KU	4	40 UNK	SP	CRE	ID	BD	2/18/2050
2021 PO5169621924	KU	3	45 BRO	SP	CCA		V	2/19/2050
2021 PO4188086161	LGE	3	45 BRO	SP	A	ED,ID,JP	TD	2/20/2050
2021 PO7813360257	F	4	40 BRO	SP	CRE		V	2/21/2050
2021 PO2531306486	KU	3	45 UNK	SP	CCA		V	2/22/2050
2021 PO2550207894	KU	5	35 UNK	SP	CCA		V	2/23/2050
2021 PO2555206247	KU	3	45 UNK	SP	CCA		V	2/24/2050
2021 PO2561307927	KU	4	40 UNK	ST	CRE		V	2/25/2050
2021 PO2579106008	KU	2	45 UNK	SP	CCA		V	2/26/2050
2021 PO2583405990	KU	2	45 UNK	SP	CCA		V	2/27/2050
2021 PO2607907485	KU	3	45 UNK	SP	CCA		V	2/28/2050
2021 PO2613605929	KU	5	35 UNK	SP	CCA		V	3/1/2050
2021 PO2643705868	KU	5	35 UNK	SP	CRE		V	3/2/2050
2021 PO2705907309	KU	3	45 UNK	SP	CCA		V	3/3/2050
2021 PO2706907328	KU	3	45 UNK	SP	CCA		V	3/4/2050
2021 PO2821006782	KU	4	40 UNK	SP	CRE		V	3/5/2050
2021 PO2827706751	KU	3	45 UNK	SP	CCA		V	3/6/2050
2021 PO2841106685	KU	4	45 UNK	SP	CCA		V	3/7/2050
2021 PO2846206906	KU	3	45 UNK	SP	CCA		V	3/8/2050
2021 PO2847106969	KU	3	45 UNK	SP	CCA		V	3/9/2050
2021 PO2849105690	KU	4	40 UNK	SP	CCA		V	3/10/2050
2021 PO2859806079	KU	4	40 UNK	SP	CCA		V	3/11/2050
2021 PO2860706674	KU	6	30 UNK	SP	CCA		V	3/12/2050
2021 PO2883306772	KU	3	45 UNK	SP	CCA		V	3/13/2050
2021 PO8037478686	KU	4	45 BRO	SP	CCA		V	3/14/2050
2021 PO8071578502	KU	4	45 BRO	SP	CRE		V	3/15/2050
2021 PO8096978364	KU	4	40 BRO	SP	CRE		V	3/16/2050
2021 PO8131678233	KU	3	50 BRO	SP	CCA		V	3/17/2050
2021 PO8153177660	F	6	30 BRO	SP	S		V	3/18/2050
2021 PO8166578079	KU	4	40 BRO	SP	CRE		V	3/19/2050
2021 PO8183478006	KU	5	35 BRO	SP	CCA		V	3/20/2050
2021 PO8194777957	KU	4	45 BRO	SP	CCA		V	3/21/2050
2021 PO8194777957A	KU	4	40 BRO	SP	S		V	3/22/2050
2021 PO8213477878	KU	4	45 BRO	SP	CCA		V	3/23/2050
2021 PO8230177805	KU	4	45 BRO	SP	CCA		V	3/24/2050
2021 PO8265577663	KU	3	50 BRO	SP	CCA		V	3/25/2050
2021 PO8295177523	KU	4	45 BRO	SP	CCA		V	3/26/2050
2021 PO8320677399	KU	4	45 BRO	SP	CCA		V	3/27/2050
2021 PO8325376995	KU	3	45 BRO	SP	CRE		V	3/28/2050
2021 PO8350377326	KU	4	45 BRO	SP	CCA		V	3/29/2050
2021 PO8361878189	KU	4	30 BRO	SP	CRE		V	3/30/2050
2021 PO8365479534	KU	6	30 BRO	SP	CCA		V	3/31/2050
2021 PO8406876163	KU	4	40 BRO	SP	S		V	4/1/2050
2021 PO8406876163A	KU	4	40 BRO	SP	CCA		V	4/2/2050
2021 PO8408877154	KU	4	45 BRO	SP	CCA		V	4/3/2050
2021 PO8437575007	KU	3	45 BRO	SP	CCA		V	4/4/2050
2021 PO8445576589A	KU	4	40 BRO	SP	S		V	4/5/2050
2021 PO8448077043	KU	4	45 BRO	SP	CCA		V	4/6/2050
2021 PO8453275096	KU	3	45 BRO	SP	CCA		V	4/7/2050
2021 PO8472476977	KU	5	45 BRO	SP	S		V	4/8/2050
2021 PO8474075215	KU	4	40 BRO	SP	CCA		V	4/9/2050
2021 PO8495376845	KU	3	45 BRO	SP	CCA		V	4/10/2050
2021 PO8533978293	KU	3	45 BRO	SP	CCA		V	4/11/2050
2021 PO8536577594	KU	4	40 BRO	SP	S		V	4/12/2050

2021 PO8568878329	KU	3	45 BRO	SP	CCA					V			4/13/2050
2021 PO8608578370	KU	3	45 BRO	SP	CCA					V			4/14/2050
2021 PO8647578460	KU	3	45 BRO	SP	CCA					V			4/15/2050
2021 PO8677278506	KU	3	45 BRO	SP	CCA					V			4/16/2050
2021 PO8706878554	KU	3	45 BRO	SP	CCA					V			4/17/2050
2021 PO8731178378	KU	3	45 BRO	SP	CCA					V			4/18/2050
2021 PO8753978569	F	4	40 BRO	SP	A					V			4/19/2050
2021 PO8759578652	KU	3	45 BRO	SP	CCA					V			4/20/2050
2021 PO8762578357	KU	3	45 BRO	SP	CCA					V			4/21/2050
2021 PO8785673911	KU	4	45 BRO	SP	CCA					V			4/22/2050
2021 PO8849772887	KU	4	45 BRO	SP	CCA					V			4/23/2050
2021 PO8866972553	KU	4	45 BRO	SP	CCA					V			4/24/2050
2021 PO8881873076	KU	3	45 BRO	SP	CCA					V			4/25/2050
2021 PO8904673179	KU	3	45 BRO	SP	CCA					V			4/26/2050
2021 PO2360137200	KU	4	45 BRN	SP	CRE		ED,EP,ID				TX	RR	4/27/2050
2021 PO2387037394	KU	4	45 BRN	SP	CRE		ED,EP,ID					RR	4/28/2050
2021 PO2615113291	KU	3	45 UNK	SP	CRE		ED,HH,ID					RR	4/29/2050
2021 PO1955341058	KU	5	35 BRN	SP	CRE		ED,ID						4/30/2050
2021 PO1986440439	KU	6	40 BRN	SP	CRE		ID						5/1/2050
2021 PO2015440729	KU	4	40 BRN	SP	CCA		ID						5/2/2050
2021 PO2241036411	KU	4	40 BRN	SP	CRE		ID						5/3/2050
2021 PO2261036547	KU	4	40 BRN	SP	CRE		ID,IP						5/4/2050
2021 PO2310036853	KU	4	40 BRN	SP	CRE		ID						5/5/2050
2021 PO23110375542A1	KU	4	40 BRN	SP	CRE		ID						5/6/2050
2021 PO2333237015	KU	4	40 BRN	SP	CRE		ID						5/7/2050
2021 PO2410237558	KU	4	40 BRN	SP	CRE		ID						5/8/2050
2021 PO2581514085	KU	4	40 UNK	SP	CRE		ID,IP						5/9/2050
2021 PO2606312948	KU	3	40 UNK	SP	CRE		ID,IP						5/10/2050
2021 PO2606507785	KU	3	50 UNK	SP	CRE		ID,IP,SRS						5/11/2050
2021 PO2646707605	KU	4	40 UNK	SP	CRE		ID						5/12/2050
2021 PO2670107493	KU	4	40 UNK	SP	CRE		ID						5/13/2050
2021 PO2673707474	KU	4	40 UNK	SP	CRE		ID,IP						5/14/2050
2021 PO2677807455	KU	4	40 UNK	SP	CRE		ID,IP						5/15/2050
2021 PO2732207197	KU	4	40 UNK	SP	CRE		ID,IP						5/16/2050
2021 PO2753907097	KU	4	40 UNK	SP	CRE		ID						5/17/2050
2021 PO2777406984	KU	4	40 UNK	SP	CRE		ID,IP						5/18/2050
2021 PO2798406883	KU	4	40 UNK	SP	CRE		ID						5/19/2050
2021 PO2835506715	KU	4	45 UNK	SP	CRE		ID						5/20/2050
2021 PO2860306590	KU	4	50 UNK	SP	CRE		ID						5/21/2050
2021 PO8166177646	KU	4	35 BRO	SP	A		ED,ID						5/22/2050
2021 PO8171777706	KU	4	40 BRO	SP	CRE		ED,ID						5/23/2050
2021 PO8329876656	KU	5	35 BRO	SP	CRE		ED,ID						5/24/2050
2021 PO8330076901	KU	4	35 BRO	SP	CRE		ED,ID						5/25/2050
2021 PO8342677794	KU	4	40 BRO	SP	CRE		ED,ID						5/26/2050
2021 PO8361878189A	KU	6	30 BRO	SP	A		ED,ID						5/27/2050
2021 PO8412176109	KU	6	30 BRO	SP	CRE		ED,ID						5/28/2050
2021 PO8445576589	KU	5	35 BRO	SP	CRE		ED,ID						5/29/2050
2021 PO8480375589	KU	4	40 BRO	SP	CRE		ED,ID						5/30/2050
2021 PO8504875319	KU	4	40 BRO	SP	A		ED,ID						5/31/2050
2021 PO8514475252	KU	6	30 BRO	SP	CRE		ED,ID						6/1/2050
2021 PO8521077463	KU	4	40 BRO	SP	CRE		ED,ID						6/2/2050
2021 PO8534375355	KU	4	45 BRO	SP	CRE		ED,ID						6/3/2050
2021 PO8547675372	KU	4	45 BRO	SP	CRE		ED,ID						6/4/2050
2021 PO8573375840	KU	4	40 BRO	SP	CRE		ED,ID						6/5/2050

2021 PO8852673095	KU	4	40 BRO	SP	CRE	ED,ID	TD		6/6/2050
2021 PO2590113867	KU	4	45 UNK	SP	CRE	ED,ID	BX	RP2	6/7/2050
2021 PO1871242792	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD		6/8/2050
2021 PO1876742612	KU	6	30 BRN	SP	CRE	ID	BD		6/9/2050
2021 PO1955341058A1	KU	6	35 BRN	SP	CRE	ID	BD		6/10/2050
2021 PO1974340239	KU	4	40 BRN	SP	CRE	ID	BD		6/11/2050
2021 PO2186036405	KU	6	30 BRN	SP	CRE	ID	BD		6/12/2050
2021 PO2219336288	KU	4	40 BRN	SP	CRE	ID	BD		6/13/2050
2021 PO2284836696	KU	4	45 BRN	SP	CRE	ID	BD		6/14/2050
2021 PO2311037542	KU	4	20 BRN	SP	CRE	ED,ID	BD		6/15/2050
2021 PO2333237015A1	KU	6	35 BRN	SP	CRE	ID	BD		6/16/2050
2021 PO2339037349	KU	6	30 BRN	SP	CRE	ID	BD		6/17/2050
2021 PO2410237558A1	KU	5	35 BRN	SP	CRE	ED,ID,IP,MD	BD		6/18/2050
2021 PO2427937697A1	KU	5	35 BRN	SP	CRE	ID	BD		6/19/2050
2021 PO2586407854	KU	4	45 UNK	SP	CRE	ID	BD		6/20/2050
2021 PO2611513562	KU	2	50 UNK	SP	CRE	ID,IP	BD		6/21/2050
2021 PO8324277220	KU	5	35 BRO	SP	CRE	ED,ID	BD		6/22/2050
2021 PO8361878560	KU	3	40 BRO	SP	CRE	ED,ID	BD		6/23/2050
2021 PO8362779283	KU	4	50 BRO	SP	CRE	ED,ID	BD		6/24/2050
2021 PO8367879755	KU	4	45 BRO	SP	CRE	ED,ID	BD		6/25/2050
2021 PO8553075774	KU	4	40 BRO	SP	CRE	ED,ID	BD		6/26/2050
2021 PO4651109336	KU	6	30 XXX	SP	CRE	ED,ID,RB	X	RP3	6/27/2050
2021 PO3009908300	KU	6	30 BRN	SP	CRE		V		6/28/2050
2021 PO3120407273	KU	4	40 BRN	SP	S		V		6/29/2050
2021 PO3124207692	KU	5	35 BRN	SP	S		V		6/30/2050
2021 PO3152307103A	KU	3	40 BRN	SP	S		V		7/1/2050
2021 PO3152307103B	KU	4	40 BRN	SP	S		V		7/2/2050
2021 PO3198907030	KU	4	45 BRN	SP	S		V		7/3/2050
2021 PO3203207219	KU	4	45 BRN	SP	S		V		7/4/2050
2021 PO3210006476	F	4	40 BRN	SP	CRE		V		7/5/2050
2021 PO3213106811	F	4	40 BRN	SP	CRE		V		7/6/2050
2021 PO3215907162	KU	4	40 BRN	SP	CRE		V		7/7/2050
2021 PO3219206822	KU	3	45 BRN	SP	CRE		V		7/8/2050
2021 PO3229306920	KU	3	45 BRN	SP	CRE		V		7/9/2050
2021 PO3229406679	KU	3	45 BRN	SP	CCA		V		7/10/2050
2021 PO3232006639	KU	3	45 BRN	SP	CRE		V		7/11/2050
2021 PO3244806853	KU	6	30 BRN	SP	CRE		V		7/12/2050
2021 PO3271406298	KU	3	45 BRN	SP	CRE		V		7/13/2050
2021 PO4585809409	KU	6	30 BRN	SP	CCA		V		7/14/2050
2021 PO4604209413	F	4	40 XXX	SP	CRE		V		7/15/2050
2021 PO4604309279	F	4	40 XXX	SP	CCA		V		7/16/2050
2021 PO4617109235	F	4	40 XXX	SP	CCA		V		7/17/2050
2021 PO4617809427	F	4	40 XXX	SP	CRE		V		7/18/2050
2021 PO4628309402	F	4	40 XXX	SP	CRE		V		7/19/2050
2021 PO4629709190	F	4	40 XXX	SP	CCA		V		7/20/2050
2021 PO4633109618	F	4	40 XXX	SP	CRE		V		7/21/2050
2021 PO4638809369	F	4	45 XXX	SP	P		V		7/22/2050
2021 PO4646809585	F	4	40 XXX	SP	CRE		V		7/23/2050
2021 PO4683209357	KU	6	30 BRN	SP	CCA		V		7/24/2050
2021 PO4743208569	KU	6	30 BRN	SP	S		V		7/25/2050
2021 PO9510115568	KU	4	40 ACW	SP	S		V		7/26/2050
2021 PO9540215457	KU	1	50 ACW	SP	CRE		V		7/27/2050
2021 PO9563415539	KU	3	45 ACW	SP	S		V		7/28/2050
2021 PO9590215524	KU	4	40 ACW	SP	S		V		7/29/2050

2021 PO9602814933	KU	4	40 ACW	SP	CRE		V			7/30/2050
2021 PO9611515511	KU	4	40 ACW	SP	S		V			7/31/2050
2021 PO9632815499	KU	4	40 ACW	SP	S		V			8/1/2050
2021 PO2990208736	KU	4	40 BRN	SP	CRE	ED,ID,RB,SRC	TX	RR		8/2/2050
2021 PO3232206998	KU	2	45 BRN	SP	CRE	ED,ID,RB	TX	RR		8/3/2050
2021 PO3250707401	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR		8/4/2050
2021 PO2845808723	KU	4	40 BRN	SP	CRE	ED,HH,ID	TD			8/5/2050
2021 PO2897108659	KU	4	40 BRN	SP	CRE	ED,ID	TD			8/6/2050
2021 PO3152307103	KU	4	40 BRN	SP	CRE	ED,ID	TD			8/7/2050
2021 PO3159307323	KU	4	40 BRN	SP	CRE	ED,ID	TD			8/8/2050
2021 PO3166707574	KU	4	40 BRN	SP	CRE	ED,ID	TD			8/9/2050
2021 PO3206506022	KU	4	45 BRN	SP	CRE	ED,ID,SRC	TD			8/10/2050
2021 PO3247807149	KU	4	40 BRN	SP	CRE	ED,ID	TD			8/11/2050
2021 PO4585409177	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/12/2050
2021 PO4590009575	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD			8/13/2050
2021 PO4592409319	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/14/2050
2021 PO4603309551	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/15/2050
2021 PO4621309315	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD			8/16/2050
2021 PO4631109529	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/17/2050
2021 PO4658809467	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/18/2050
2021 PO4663307825	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/19/2050
2021 PO4694407871	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/20/2050
2021 PO4703909223	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/21/2050
2021 PO4706909039	KU	4	40 XXX	SP	CRE	ED,ID	TD			8/22/2050
2021 PO4714507801	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/23/2050
2021 PO4715109091	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/24/2050
2021 PO4724308079	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD			8/25/2050
2021 PO4727208287	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/26/2050
2021 PO4727608986	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD			8/27/2050
2021 PO4729408828	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/28/2050
2021 PO4739308438	KU	6	30 XXX	SP	CRE	ED,ID	TD			8/29/2050
2021 PO9517515135	KU	4	40 ACW	SP	CRE	ED,ID	TD			8/30/2050
2021 PO9542115298	KU	5	35 ACW	SP	CRE	ED,ID	TD			8/31/2050
2021 PO9542715111	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			9/1/2050
2021 PO9617515454	KU	4	40 ACW	SP	CRE	ED,ID	TD			9/2/2050
2021 PO9621815178	KU	4	40 ACW	SP	CRE	ED,ID	TD			9/3/2050
2021 PO9624214989	KU	4	40 ACW	SP	CRE	ED,ID	TD			9/4/2050
2021 PO9639715352	KU	4	45 ACW	SP	CRE	ED,ID	TD			9/5/2050
2021 PO9646715419	KU	6	30 ACW	DF	CRE	ED,ID	TD			9/6/2050
2021 PO9646915494	KU	4	40 ACW	SP	CRE	ED,ID	TD			9/7/2050
2021 PO9659615734	KU	4	40 ACW	SP	CRE	ED,ID	TD			9/8/2050
2021 PO9668115726	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD			9/9/2050
2021 PO9715513153	KU	3	40 ACW	SP	CRE	ED,ID	TD			9/10/2050
2021 PO9756112927	KU	4	40 ACW	DF	CRE	ED,ID,IP	TD			9/11/2050
2021 PO9762312896	KU	4	40 ACW	SP	CRE	ED,ID	TD			9/12/2050
2021 PO9763513224	KU	4	40 ACW	SP	CRE	ED,ID	TD			9/13/2050
2021 PO9772513367	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			9/14/2050
2021 PO9776412997	KU	5	35 ACW	SP	CRE	ED,ID	TD			9/15/2050
2021 PO9797713255	KU	4	40 ACW	SP	CRE	ED,ID	TD			9/16/2050
2021 PO3254206427	KU	3	45 BRN	SP	S	ED,ID,SRC	T			9/17/2050
2021 PO2964608491	KU	6	30 BRN	SP	CRE	ID	BD			9/18/2050
2021 PO2987308506	KU	4	40 BRN	SP	CRE	ID	BD			9/19/2050
2021 PO3100206708	KU	4	40 BRN	SP	CRE	ID	BD			9/20/2050
2021 PO3044205187	KU	4	45 BRN	SP	S		B			9/21/2050

2021 PO3053805495	KU	4	45 BRN	SP	S					B	9/22/2050	
2021 PO3064805763	KU	4	45 BRN	SP	S					B	9/23/2050	
2021 PO3075706027	KU	4	45 BRN	SP	S					B	9/24/2050	
2021 PO3088206394	KU	4	40 BRN	SP	CRE					B	9/25/2050	
2021 PO3110906937	KU	4	40 BRN	SP	S					B	9/26/2050	
2021 PO4582109430	F	4	40 XXX	SP	CRE					B	9/27/2050	
2021 PO4131986249	LGE	4	45 ACE	SP	CRE		ED,HH,ID,RB			X	RP1	9/28/2050
2021 PO4132586162	LGE	4	35 ACE	SP	P		ED,HH,ID,RB			X	RP1	9/29/2050
2021 PO4144386373	LGE	4	30 BRN	SP	CRE		EP,HH,IP,RB			X	RP1	9/30/2050
2021 PO4144686358	LGE	3	50 BRN	SP	P		ED,HH,ID			X	RP2	10/1/2050
2021 PO4145386372	LGE	3	45 BRN	SP	P		HH,ID,RB			X	RP2	10/2/2050
2021 PO4146886310	LGE	3	45 BRN	SP	P		ED,HH,ID,SRC			X	RP2	10/3/2050
2021 PO4193686142	LGE	4	35 BRO	SP	A		ED,ID,IP,RB			X	RP1	10/4/2050
2021 PO4199086237	LGE	4	40 BRO	SP	CRE		HH,RB			X	RP1	10/5/2050
2021 PO4109286088	LGE	3	45 ACE	SP	CCA					V		10/6/2050
2021 PO4126286182	LGE	4	35 ACE	SP	CCA					V		10/7/2050
2021 PO4127786179	LGE	4	35 ACE	SP	CCA					V		10/8/2050
2021 PO4130286451	LGE	3	45 BRN	SP	CCA					V		10/9/2050
2021 PO4130586251	LGE	4	35 ACE	SP	CCA					V		10/10/2050
2021 PO4130986427	LGE	3	45 BRN	SP	CCA					V		10/11/2050
2021 PO4131586415	LGE	4	35 BRN	SP	CCA					V		10/12/2050
2021 PO4131586446	LGE	3	45 BRN	SP	CCA					V		10/13/2050
2021 PO4132086461	LGE	4	35 BRN	SP	CCA					V		10/14/2050
2021 PO4132485984	LGE	2	75 BRN	SP	CCA					V		10/15/2050
2021 PO4132785989	LGE	1	75 BRN	ST	P					V		10/16/2050
2021 PO4133285987	LGE	4	30 BRN	SP	CCA					V		10/17/2050
2021 PO4133586004	LGE	2	70 BRN	ST	P					V		10/18/2050
2021 PO4144086332	LGE	2	55 BRN	SP	CCA					V		10/19/2050
2021 PO4146786274	LGE	3	55 BRN	SP	P					V		10/20/2050
2021 PO4147186290	LGE	3	45 BRN	SP	P					V		10/21/2050
2021 PO4189386194	LGE	4	40 BRO	SP	CCA					V		10/22/2050
2021 PO4192586210	F	4	30 BRO	SP	CCA					V		10/23/2050
2021 PO4193786219	F	4	35 BRO	SP	CRE					V		10/24/2050
2021 PO8603374866	LGE	4	35 BRN	SP	CCA					V		10/25/2050
2021 PV4195486225	LGE	4	40 BRO	SP	CRE		ED,ID,IP			TX	RR	10/26/2050
2021 PO4120486187	LGE	6	30 ACE	SP	CRE		ED,ID,IP			TD		10/27/2050
2021 PO4120586193	LGE	4	40 ACE	SP	A		ED,ID,IP			TD		10/28/2050
2021 PO4122386185	LGE	6	35 ACE	SP	CRE		ED,ID,IP			TD		10/29/2050
2021 PO4122486191	LGE	4	40 ACE	SP	CRE		ED,ID,IP			TD		10/30/2050
2021 PO4124386189	LGE	3	45 ACE	SP	P		ED,ID			TD		10/31/2050
2021 PO4126086188	LGE	4	40 ACE	SP	CRE		ED,ID,IP			TD		11/1/2050
2021 PO2362002276	KU	4	45 UNK	SP	CRE		ID			TD		11/2/2050
2021 PO2330802317	KU	4	40 UNK	SP	CCA					V		11/3/2050
2021 PO0804859237	KU	4	45 BRO	SP	CRE		ED,ID			TD		11/4/2050
2021 PO2764303827	F	4	40 BRN	SP	CCA					V		11/5/2050
2021 PO2815005063	KU	3	45 BRN	SP	CCA					V		11/6/2050
2021 PO0795960519	KU	2	50 BRO	SP	CRE					B		11/7/2050
2021 PO0685362311	KU	4	40 BRO	SP	CRE		ED,EP,ID			TD		11/8/2050
2021 PO0596262634	KU	4	40 BRO	SP	CRE		ED,ID			TD		11/9/2050
2021 PO0851658518	F	4	40 BRO	SP	CRE					V		11/10/2050
2021 PO0845858664	F	4	35 BRO	SP	CRE					V		11/11/2050
2021 PO0837958821	F	4	40 BRO	SP	CRE					V		11/12/2050
2021 PO0626962398	KU	4	40 BRO	SP	CRE		ED,ID			TD		11/13/2050
2021 PO5759001276	F	3	40 BRO	SP	P					V		11/14/2050

2021 PO5787201042	KU	2	50 BRO	SP	CCA		V		11/15/2050
2021 PO4131885849	LGE	4	35 BRN	SP	P	ID	TD		11/16/2050
2021 PO9553069436	F	4	40 BRO	SP	CRE		V		11/17/2050
2021 PO9611069474	KU	4	40 BRO	SP	CRE	ED,ID	TD		11/18/2050
2021 KU	KU	3	45 BRO	SP	CCA		V		11/19/2050
2021 PO0701462240	KU	3	45 BRO	SP	CCA	ED	T		11/20/2050
2021 PO0831259008	F	4	40 BRO	SP	CRE		V		11/21/2050
2021 PO5776201235	KU	3	45 BRO	SP	CCA		V		11/22/2050
2021 PO5771501344	F	3	40 BRO	SP	P		V		11/23/2050
2021 PO5783301439	C	4	40 BRO	SP	CRE		V		11/24/2050
2021 PO5783001374	F	3	40 BRO	SP	CRE		V		11/25/2050
2021 PO5747501216	F	3	40 BRO	SP	P		V		11/26/2050
2021 PO5734501144	F	3	40 BRO	SP	CRE		V		11/27/2050
2021 PO0818859287	F	4	40 BRO	SP	CRE		V		11/28/2050
2021 PO0816659274	KU	5	35 BRO	SP	CRE	ED	TD		11/29/2050
2021 PO4131785853	LGE	3	45 BRN	SP	CRE	ID,IP,SRC	TD		11/30/2050
2021 PO2815904927	KU	4	40 BRN	SP	CCA		V		12/1/2050
2021 PO2810404952	KU	3	45 BRN	SP	CCA		V		12/2/2050
2021 PO2780004211	F	4	40 BRN	SP	CCA		V		12/3/2050
2021 PO2803204776	F	3	45 BRN	SP	CCA		V		12/4/2050
2021 PO4131085854	LGE	4	40 BRN	SP	CRE	IP,SRS	TD		12/5/2050
2021 PO2364602693	F	5	30 UNK	SP	CCA		V		12/6/2050
2021 PO2355302656	KU	4	45 UNK	SP	CCA		V		12/7/2050
2021 PO2352203055	KU	3	45 UNK	SP	CCA		V		12/8/2050
2021 PO5738701068	KU	6	35 BRO	SP	CCA		V		12/9/2050
2021 PO9513569320	KU	4	40 BRO	SP	CRE		VX	RP3	12/10/2050
2021 PO5707500865	F	3	40 BRO	SP	CRE		V		12/11/2050
2021 PO5704000863	F	3	40 BRO	SP	CRE		V		12/12/2050
2021 PO5693500820	F	7	30 BRO	SP	CRE		V		12/13/2050
2021 PO2321901867	F	5	40 UNK	SP	CRE		V		12/14/2050
2021 PO2300401849	KU	4	45 UNK	SP	CRE	ID	TD		12/15/2050
2021 PO2296101859	KU	3	45 UNK	SP	CRE	ID,IP,SRS	TD		12/16/2050
2021 PO2293201878	KU	3	45 UNK	SP	CRE	HH,ID	X	RP1	12/17/2050
2021 PO2257601669	KU	4	40 UNK	SP	CRE	ID	BD		12/18/2050
2021 PO2266201590	KU	4	45 UNK	SP	CRE	ID	TD		12/19/2050
2021 PO2268401574	KU	3	50 UNK	SP	CCA		V		12/20/2050
2021 PO2270801442	F	4	40 UNK	SP	P		V		12/21/2050
2021 PO9625269484	F	4	40 BRO	SP	CRE		V		12/22/2050
2021 PO9628069581	KU	6	30 BRO	SP	CRE	ED,ID	TD		12/23/2050
2021 9646069487A	KU	3	40 BRO	SP	A		V		12/24/2050
2021 PO5685600702	KU	4	40 BRO	SP	CCA	ED	TD		12/25/2050
2021 PO5699800452	KU	7	35 BRO	SP	CRE	ED	TD		12/26/2050
2021 PO5720900379	F	3	40 BRO	SP	P		V		12/27/2050
2021 PO5715800350	KU	7	35 BRO	SP	CRE	ED	TD		12/28/2050
2021 PO4128085863	LGE	4	35 BRN	SP	CRE	ID,IP,RB	TX	RR	12/29/2050
2021 PO4129385862	LGE	4	35 BRN	SP	CRE	HH,RB	X	PX	12/30/2050
2021 PO4177986458	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		12/31/2050
2021 PO4932505331	F	4	40 ACW	SP	CRE		V		1/1/2051
2021 PO9646069487	KU	4	40 STP	SP	CRE	ED,ID	BD		1/2/2051
2021 PO9647769315	KU	6	30 STP	SP	CRE	ED,ID	TD		1/3/2051
2021 PO9667369425	KU	4	40 STP	SP	CRE	ED,ID	TD		1/4/2051
2021 PO4131985866	LGE	4	45E BRN	SP	CRE	ID,IP	TD		1/5/2051
2021 PO4948705246	F	4	40 KOP	SP	CRE		V		1/6/2051
2021 PO4960705177	F	4	40 XXX	SP	CRE		V		1/7/2051

2021 PO4973705199	F	4	40 XXX	SP	CRE		V	1/8/2051
2021 PO4968305127	F	4	40 XXX	SP	CRE		V	1/9/2051
2021 PO5030005058	KU	5	40 XXX	ST	CRE		V	1/10/2051
2021 PO5041305101	KU	5	40 XXX	ST	CCA		V	1/11/2051
2021 PO4970504990	F	6	30 XXX	SP	CRE		V	1/12/2051
2021 PO4979705059	F	4	45 XXX	SP	CRE		V	1/13/2051
2021 PO4994105245	F	4	40 XXX	SP	CRE		V	1/14/2051
2021 PO5000805331	F	4	40 XXX	SP	CRE		V	1/15/2051
2021 PO2669304559	KU	4	45 BRN	SP	S		V	1/16/2051
2021 PO4134985906	F	3	50 BRN	SP	CRE	ED,ID	V	1/17/2051
2021 PO4134985917	F	3	50 BRN	SP	CRE		V	1/18/2051
2021 PO4133885929	LGE	4	35 BRN	SP	CCA		V	1/19/2051
2021 PO4133785917	LGE	4	40 BRN	SP	CCA		V	1/20/2051
2021 PO4135085932	F	3	50 BRN	SP	CCA		V	1/21/2051
2021 PO9201775355	LGE	4	40 ACE	SP	CCA		V	1/22/2051
2021 PO4207386364	LGE	4	40 ACE	SP	CCA		V	1/23/2051
2021 PO4206486339	LGE	4	35 ACE	SP	CCA		V	1/24/2051
2021 PO2713303727	KU	4	40 BRN	SP	CCA		V	1/25/2051
2021 PO2694805459	KU	4	40 BRN	SP	CCA		V	1/26/2051
2021 PO2728406161	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/27/2051
2021 PO9699269248	F	4	40 STP	SP	CRE		V	1/28/2051
2021 PO4175486460	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	1/29/2051
2021 PO4206586220	LGE	4	35 ACE	SP	CCA		V	1/30/2051
2021 PO5647637352	F	4	40 ACE	SP	CRE		V	1/31/2051
2021 PO5548745854	KU	3	45 ACE	SP	CCA		V	2/1/2051
2021 PO5043237236	KU	6	30 ACE	SP	CRE	ED,ID	TD	2/2/2051
2021 PO4321439515	KU	5	35 ACE	SP	CRE		V	2/3/2051
2021 PO4266539483	KU	4	35 ACE	SP	CCA		V	2/4/2051
2021 PO4465539468	KU	4	45 ACE	SP	CRE	ED,ID	TD	2/5/2051
2021 PO4440739483	KU	5	35 ACE	SP	CRE	ED,ID	TD	2/6/2051
2021 PO4418239497	KU	5	35 ACE	SP	CRE	ED,ID	TD	2/7/2051
2021 PO4393239517	KU	5	35 ACE	SP	CRE	ED,ID	TD	2/8/2051
2021 PO4370139531	KU	3	45 ACE	SP	CCA		V	2/9/2051
2021 PO4344639541	KU	3	45 ACE	SP	CCA		V	2/10/2051
2021 PO4306039493	KU	3	45 ACE	SP	CCA		V	2/11/2051
2021 PO4291039471	KU	3	45 ACE	SP	CCA		V	2/12/2051
2021 PO4258139486	KU	3	45 ACE	SP	CCA		V	2/13/2051
2021 PO4242739495	KU	4	35 ACE	SP	CRE	ED,ID,IP	TD	2/14/2051
2021 PO4218939502	KU	4	35 ACE	SP	CRE	ED,ID	TD	2/15/2051
2021 PO4196339519	KU	4	35 ACE	SP	CRE	ED,ID,IP	TD	2/16/2051
2021 PO4171739533	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	2/17/2051
2021 PO1425012064	KU	3	45 BRN	SP	CCA		T	2/18/2051
2021 PO1679112004	KU	6	30 BRN	SP	CRE		V	2/19/2051
2021 PO1604212774	KU	3	45 BRN	SP	CCA		V	2/20/2051
2021 PO1511012684	KU	4	40 BRN	SP	CRE	ID	TD	2/21/2051
2021 PO1484512770	KU	4	40 BRN	SP	CRE	ID	TD	2/22/2051
2021 PO1643412211	KU	3	45 BRN	SP	CCA		V	2/23/2051
2021 PO1577812473	KU	4	40 BRN	SP	CCA	ID	TD	2/24/2051
2021 PO1614712318	KU	4	40 BRN	SP	CRE		V	2/25/2051
2021 PO1455812867	KU	4	40 BRN	SP	CCA		V	2/26/2051
2021 PO2413500264	KU	6	30 UNK	SP	CRE		V	2/27/2051
2021 PO4206186319	LGE	4	40 ACE	SP	CCA		V	2/28/2051
2021 PO5858201457	KU	3	40 BRO	SP	CCA		V	3/1/2051
2021 PO5841001405	KU	3	40 BRO	SP	CCA		V	3/2/2051



2021 PO5861801401	KU	3	35 BRO	SP	CCA			V				3/3/2051
2021 PO5730001202	C	2	35 BRO	SP	CRE			V				3/4/2051
2021 PO2855006196	KU	4	40 BRN	SP	CCA			V				3/5/2051
2021 PO2855806070	KU	4	40 BRN	SP	CRE		ED,ID			TD		3/6/2051
2021 PO2861006196	KU	4	40 BRN	SP	CRE		ED,ID			TD		3/7/2051
2021 PO4207086298	LGE	4	35 ACE	SP	CCA			V				3/8/2051
2021 PO4208086360	LGE	4	35 ACE	SP	CCA			V				3/9/2051
2021 PO4207886335	LGE	4	35 ACE	SP	CCA			V				3/10/2051
2021 PO4211186373	LGE	4	35 ACE	SP	CCA			V				3/11/2051
2021 PO2847906238	C	4	40 BRN	SP	CRE			V				3/12/2051
2021 PO2792404512	KU	4	40 BRN	SP	CCA			V				3/13/2051
2021 PO2377402100	KU	3	55 UNK	SP	CRE		ID,IP			BD		3/14/2051
2021 PO4129785900	LGE	4	35 BRN	SP	CRE		ID,IP			TD		3/15/2051
2021 PO5812801322	KU	4	40 BRO	SP	CCA			V				3/16/2051
2021 PO4988005007	F	5	40 XXX	SP	CRE		ED,ID,RB		BX		RP2	3/17/2051
2021 PO5039104837	KU	7	35 OTH	SP	CRE		ED,ID		BX		PX	3/18/2051
2021 PO5606203162	F	4	40 BRO	SP	CRE		ED,HH,ID,RB		BX		PX	3/19/2051
2021 PO5646903319	KU	7	30 BRO	SP	CRE		ED,HH,ID,RB		BX		PX	3/20/2051
2021 PO4862502999	F	4	55 XXX	SP	P			V				3/21/2051
2021 PO4877203182	F	4	55 XXX	SP	P			V				3/22/2051
2021 PO4936802656	F	4	40 XXX	ST	CRE			V				3/23/2051
2021 PO4913102706	F	4	40 XXX	ST	CRE			V				3/24/2051
2021 PO4940302866	F	4	40 XXX	ST	CRE			V				3/25/2051
2021 PO4921002950	F	4	40 XXX	ST	CRE			V				3/26/2051
2021 PO4920403007	KU	4	40 XXX	ST	CRE			V				3/27/2051
2021 PO4964003527	F	4	40 XXX	SP	CRE			V				3/28/2051
2021 PO4951603185	KU	3	45 BRN	SP	CCA			V				3/29/2051
2021 PO4945403595	F	4	40 XXX	SP	CRE			V				3/30/2051
2021 PO4931203645	F	4	40 XXX	SP	CRE			V				3/31/2051
2021 PO4921503679	F	4	40 XXX	SP	CRE			V				4/1/2051
2021 PO4894503401	F	4	40 XXX	SP	P			V				4/2/2051
2021 PO4905003533	F	3	50 XXX	SP	S			V				4/3/2051
2021 PO4884603275	F	4	50 KOP	SP	P			V				4/4/2051
2021 PO4915403664	F	4	50 XXX	SP	P			V				4/5/2051
2021 PO4924003777	F	4	50 XXX	SP	P			V				4/6/2051
2021 PO4905303906	F	4	40 XXX	SP	CRE			V				4/7/2051
2021 PO4896803972	KU	6	30 KOP	SP	S			V				4/8/2051
2021 PO4942104009	F	4	50 KOP	SP	P			V				4/9/2051
2021 PO4934003903	F	4	40 XXX	SP	A			V				4/10/2051
2021 PO4937604043	F	4	40 XXX	SP	CRE			V				4/11/2051
2021 PO4956504287	C	4	40 XXX	ST	CRE			V				4/12/2051
2021 PO4961104253	F	4	50 KOP	SP	P			V				4/13/2051
2021 PO4952104137	F	4	40 XXX	SP	P			V				4/14/2051
2021 PO4947404026	F	4	45 XXX	SP	S			V				4/15/2051
2021 PO4949903947	KU	5	35 BRN	SP	CCA			V				4/16/2051
2021 PO4959403931	F	4	40 XXX	SP	P			V				4/17/2051
2021 PO4973103821	F	4	40 XXX	SP	CCA			V				4/18/2051
2021 PO4985603720	F	4	45 XXX	SP	CCA			V				4/19/2051
2021 PO4994103653	F	4	40 XXX	SP	P			V				4/20/2051
2021 PO4970004367	F	4	40 XXX	SP	CRE			V				4/21/2051
2021 PO4978804479	F	5	40 XXX	SP	S			V				4/22/2051
2021 PO4984004343	F	4	40 XXX	SP	CRE			V				4/23/2051
2021 PO4992904302	F	4	40 XXX	SP	CRE			V				4/24/2051
2021 PO5002204258	F	4	40 XXX	SP	CRE			V				4/25/2051

2021	PO4131185809	KU	4	30E	BRN	SP	CRE	ID,IP,SRS	TD		4/26/2051
2021	PO4131085818	LGE	4		30 BRN	SP	CRE		V		4/27/2051
2021	PO5624303469	F	2		40 BRO	SP	CRE		V		4/28/2051
2021	PO5605303508	F	6	35E	BRO	SP	CRE		V		4/29/2051
2021	PO4132085804	LGE	4		35 BRN	SP	P	ID,SRS	TD		4/30/2051
2021	PO2660203066	KU	4		40 UNK	SP	CRE	ID,IP	TD		5/1/2051
2021	PO5618503588	F	4		40 BRO	SP	CRE		V		5/2/2051
2021	PO5607703757	F	4		40 BRO	SP	CRE		V		5/3/2051
2021	PO5619903614	KU	3		40 BRO	SP	CCA	ED	TD		5/4/2051
2021	PO9082672091	F	4		40 BRO	SP	CCA		V		5/5/2051
2021	PO9075072091	KU	6		30 BRO	SP	CRE	ED,ID	TD		5/6/2051
2021	PO9074572233	KU	5		35 BRO	SP	CRE	ED,ID	TD		5/7/2051
2021	PO9082372236	KU	4		45 BRO	SP	CCA		V		5/8/2051
2021	PO2146916401	KU	5		35 BRN	SP	CCA		V		5/9/2051
2021	PO1833914292	KU	4		40 BRN	SP	CRE	ID	TD		5/10/2051
2021	PO1851214091	KU	4		40 BRN	SP	CRE	ED,EP,HH,ID	X	PX	5/11/2051
2021	PO1865114509	KU	6		35 BRN	SP	CRE	ID	TD		5/12/2051
2021	PO1850414622	KU	4		40 BRN	WC	CRE	ED,EP,ID,RB	BX	PX	5/13/2051
2021	PO5592004412	F	3		40 BRO	SP	CRE		V		5/14/2051
2021	PO5595503943	F	6		40 BRO	SP	CRE		V		5/15/2051
2021	PO5577504055	C	4		40 BRO	SP	CRE		V		5/16/2051
2021	PO5581804154	F	3		40 BRO	SP	CRE		V		5/17/2051
2021	PO5568304301	KU	7		30 BRO	SP	CRE	ED,ID	TD		5/18/2051
2021	PO5587404186	KU	6		30 BRO	SP	CRE		V		5/19/2051
2021	PO4133185825	LGE	4		30 BRN	SP	P	ID	TD		5/20/2051
2021	PO4133085811	LGE	4		30 BRN	SP	P	ID	BD		5/21/2051
2021	PO4132285828	LGE	4		40 BRN	SP	CCA		V		5/22/2051
2021	PO2882200922	KU	4		40 BRN	SP	S		V		5/23/2051
2021	PO2949198208	KU	5		35 BRN	SP	CRE	ED,ID	TD		5/24/2051
2021	PO2932098685	KU	5		35 BRN	SP	CRE	ED,ID	TD		5/25/2051
2021	PO9086671830	KU	4		45 BRO	SP	CRE	ED,ID	TD		5/26/2051
2021	PO9098871873	KU	4		40 BRO	SP	CRE	ED,ID	TD		5/27/2051
2021	PO9088571743	KU	6		30 BRO	SP	CCA		V		5/28/2051
2021	PO4132385838	LGE	3		45 BRN	SP	CRE	ID,IP,SRS	TD		5/29/2051
2021	PO2772299635	F	4		40 BRN	SP	CRE	ED,ID	V		5/30/2051
2021	PO2947298927	KU	3		40 BRN	SP	S		V		5/31/2051
2021	PO2801799560	F	4		40 BRN	SP	CRE	ED,ID	V		6/1/2051
2021	PO2635803251	KU	3		45 UNK	SP	CCA		V		6/2/2051
2021	PO2574302859	KU	4		40 UNK	SP	CRE	ID	TD		6/3/2051
2021	PO2600403037	KU	4		40 UNK	SP	CRE	ID	BD		6/4/2051
2021	PO2608902900	KU	4		40 UNK	SP	CRE	ID,IP	TD		6/5/2051
2021	9088071550	KU	6		30 BRO	SP	CRE	ED,ID	TD		6/6/2051
2021	9088071550A	KU	6		30 BRO	SP	CCA		V		6/7/2051
2021	PO9088071550	KU	4		40 BRO	SP	CRE	ED,ID	TD		6/8/2051
2021	PO9087071358	KU	4		40 BRO	SP	CCA		V		6/9/2051
2021	PO5641501435	KU	7		30 BRO	SP	CRE	ED	TD		6/10/2051
2021	PO5666902357	F	3		40 BRO	SP	P		V		6/11/2051
2021	PO5565103089	KU	7		30 BRO	SP	CRE	ED,ID	TD		6/12/2051
2021	PO5583403200	F	5		40 BRO	SP	CRE		V		6/13/2051
2021	PO5689903253	KU	4		40 BRO	SP	CCA		V		6/14/2051
2021	PO5635003214	F	3		40 BRO	SP	CRE	ED	V		6/15/2051
2021	PO5601202997	KU	6		30 BRO	SP	CRE		V		6/16/2051
2021	PO4180086551	LGE	4		40 BRO	SP	CRE	ED,ID,IP	TD		6/17/2051
2021	PO4130985828	LGE	4		45 BRN	SP	P	ID	BD		6/18/2051

2021 PO4130785831	LGE	4	40 BRN	SP	P	ID	TD	6/19/2051
2021 PO2827399433	F	4	40 BRN	SP	CRE	ED,ID	V	6/20/2051
2021 PO9084071088	KU	4	40 BRO	SP	CCA		V	6/21/2051
2021 PO4129285832	LGE	4	35 BRN	SP	CCA	ID,SRS	TD	6/22/2051
2021 PO1171853247	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/23/2051
2021 PO2827399433A	KU	4	40 BRN	SP	CRE	ED,ID	V	6/24/2051
2021 PO2887099233	F	4	40 BRN	SP	CRE	ED,ID	V	6/25/2051
2021 PO2910999591	F	4	40 BRN	SP	CRE	ED,ID	V	6/26/2051
2021 PO4126385832	LGE	5	35 BRN	SP	P	ID,MD	BD	6/27/2051
2021 PO4126985824	LGE	3	45E BRN	SP	CCA		V	6/28/2051
2021 PO5634802375	KU	3	40 BRO	SP	CRE	ED,ID	TD	6/29/2051
2021 PO5645702963	F	4	40 BRO	SP	A		V	6/30/2051
2021 PO5659503066	KU	7	35 BRO	SP	CCA		V	7/1/2051
2021 PO5652802767	F	5	40 BRO	SP	CRE		V	7/2/2051
2021 PO5669303163	KU	4	40 BRO	SP	CCA		V	7/3/2051
2021 PO5660302555	F	3	40 BRO	SP	A		V	7/4/2051
2021 PO5640203101	F	3	40 BRO	SP	CRE		V	7/5/2051
2021 PO5646003058	KU	3	40 BRO	SP	CCA		V	7/6/2051
2021 PO2849500665	KU	4	40 BRN	SP	S		V	7/7/2051
2021 PO2896900489	KU	3	40 BRN	SP	CRE	ED,ID	TD	7/8/2051
2021 PO2873700577	KU	4	40 BRN	SP	CRE		V	7/9/2051
2021 PO2927900367	KU	5	35 BRN	SP	CRE	ED,ID,RR,SRC	TX	7/10/2051
2021 PO2892000501	KU	4	40 BRN	SP	S		V	7/11/2051
2021 PO2907800150	KU	4	40 BRN	SP	CCA		V	7/12/2051
2021 PO4171586390	F	4	40 BRO	SP	A		V	7/13/2051
2021 PO4172086397	F	4	40 BRO	SP	CRE		V	7/14/2051
2021 PO4173386419	LGE	4	40 BRO	SP	CCA		V	7/15/2051
2021 PO4172686408	LGE	3	45 BRO	SP	CCA		V	7/16/2051
2021 PO0632548193	KU	4	40 BRN	SP	CCA		V	7/17/2051
2021 PO4115985907	LGE	1	65 BRN	SP	CCA		V	7/18/2051
2021 PO0749347905	F	4	40 BRN	SP	P		V	7/19/2051
2021 PO0751648507	F	6	30 BRN	SP	P		V	7/20/2051
2021 PO8757766066	KU	2	60 BRO	SP	CCA		V	7/21/2051
2021 PO8758766034	KU	2	55 BRO	SP	CCA		V	7/22/2051
2021 PO8726666365	KU	5	35 BRO	SP	CRE		V	7/23/2051
2021 PO8719765956	KU	3	50 BRO	SP	CRE		V	7/24/2051
2021 PO4529009905	F	4	40 XXX	SP	CRE		V	7/25/2051
2021 PO4544909886	F	4	40 XXX	SP	CRE		V	7/26/2051
2021 PO4556809870	F	4	40 XXX	SP	CRE		V	7/27/2051
2021 PO4570809855	F	4	40 XXX	SP	CRE		V	7/28/2051
2021 PO8505365456	KU	6	30 BRO	SP	CRE		V	7/29/2051
2021 PO8119063329	F	4	40 BRO	SP	A		V	7/30/2051
2021 PO0737848170	F	4	40 BRN	SP	P		V	7/31/2051
2021 PO0756747733	F	4	40 BRN	SP	P		V	8/1/2051
2021 PO0766746487	F	4	40 BRN	SP	A		V	8/2/2051
2021 PO0743946701	F	4	40 BRN	SP	P		V	8/3/2051
2021 PO0746847010	F	4	40 BRN	SP	P		V	8/4/2051
2021 PO0898151377	F	4	40 BRN	SP	A		V	8/5/2051
2021 PO0894251245	F	4	40 BRN	SP	A		V	8/6/2051
2021 PO0887251192	F	4	40 BRN	SP	A		V	8/7/2051
2021 PO0874451111	F	4	40 BRN	SP	A		V	8/8/2051
2021 PO0854151019	F	4	40 BRN	SP	A		V	8/9/2051
2021 PO0813953761	KU	4	40 BRO	SP	CRE		V	8/10/2051
2021 PO6958315816	KU	3	45 ACW	SP	S		V	8/11/2051

2021	PO8397364539	KU	3	45 BRO	SP	CCA	V	8/12/2051
2021	PO8395664566	KU	2	50 BRO	SP	CCA	V	8/13/2051
2021	PO0781952182	KU	4	40 BRO	SP	CCA	V	8/14/2051
2021	PO0667047688	KU	4	40 BRN	SP	CCA	V	8/15/2051
2021	PO1112153914	KU	3	45 BRO	SP	CCA	V	8/16/2051
2021	PO1060053950	KU	6	30 BRO	SP	CRE	V	8/17/2051
2021	PO1063253754	KU	4	40 BRO	SP	CCA	V	8/18/2051
2021	PO1056053636	KU	4	40 BRO	SP	CCA	V	8/19/2051
2021	PO1034453543	KU	6	30 BRO	SP	CCA	V	8/20/2051
2021	PO1035853454	KU	4	40 BRO	SP	CCA	V	8/21/2051
2021	PO0839753686	KU	4	40 BRO	SP	CRE	V	8/22/2051
2021	PO0869453626	KU	4	40 BRO	SP	CCA	V	8/23/2051
2021	PO8139163550	F	4	40 BRO	SP	CRE	V	8/24/2051
2021	PO8114256730	KU	4	40 UNK	SP	CCA	V	8/25/2051
2021	PO8140358726	F	4	40 UNK	SP	CCA	V	8/26/2051
2021	PO4583806093	F	5	35 BRO	SP	CRE	V	8/27/2051
2021	PO4515508774	F	4	40 XXX	SP	CRE	V	8/28/2051
2021	PO4524108731	F	4	40 XXX	SP	CRE	V	8/29/2051
2021	PO4516308330	F	4	40 XXX	SP	CRE	V	8/30/2051
2021	PO4489408452	F	4	40 XXX	SP	CRE	V	8/31/2051
2021	PO4498108413	KU	3	45 KOP	SP	P	V	9/1/2051
2021	PO8094056924	F	3	45 UNK	SP	A	V	9/2/2051
2021	PO8088856953	KU	3	45 UNK	SP	CCA	V	9/3/2051
2021	PO8069356659	KU	3	45 UNK	SP	CCA	V	9/4/2051
2021	PO4122886009	LGE	1	75E BRN	ST	P	V	9/5/2051
2021	PO8050856503	KU	3	45 UNK	SP	CCA	V	9/6/2051
2021	PO8038956414	KU	3	40 UNK	SP	CCA	V	9/7/2051
2021	PO4119585979	LGE	3	45 BRN	SP	S	V	9/8/2051
2021	PO4486109858	KU	5	35 BRN	SP	CCA	V	9/9/2051
2021	PO4501609835	KU	5	35 BRN	SP	CCA	V	9/10/2051
2021	PO4119185948	F	4	30 BRN	SP	CRE	V	9/11/2051
2021	PO8693565156	KU	4	45 BRO	SP	CCA	V	9/12/2051
2021	PO8024556313	KU	3	40 UNK	SP	CCA	V	9/13/2051
2021	PO8006156183	KU	3	40 UNK	SP	CCA	V	9/14/2051
2021	PO7989856067	KU	3	40 UNK	SP	CCA	V	9/15/2051
2021	PO1051754284	KU	4	40 BRO	SP	CCA	V	9/16/2051
2021	PO8206564705	KU	3	45 BRO	SP	CCA	V	9/17/2051
2021	PO4553909607	F	4	40 XXX	SP	CRE	V	9/18/2051
2021	PO8287263993	KU	4	40 BRO	SP	CRE	V	9/19/2051
2021	PO8285564027	KU	3	45 BRO	SP	CRE	V	9/20/2051
2021	PO6931315443	KU	4	40 ACW	SP	S	V	9/21/2051
2021	PO6919115235	KU	4	40 ACW	SP	S	V	9/22/2051
2021	PO8209964746	KU	4	45 BRO	SP	CCA	V	9/23/2051
2021	PO8198765439	KU	5	35 BRO	SP	CCA	V	9/24/2051
2021	PO8188365389	KU	4	40 BRO	SP	CRE	V	9/25/2051
2021	PO4165886349	LGE	3	45 BRO	SP	CCA	V	9/26/2051
2021	PO6819018134	KU	6	30 ACW	SP	S	V	9/27/2051
2021	PO3707209016	KU	3	45 BRN	SP	CCA	V	9/28/2051
2021	PO4117785945	LGE	3	45 BRN	SP	CCA	V	9/29/2051
2021	PO0720847624	KU	4	40 BRN	SP	CCA	V	9/30/2051
2021	PO0746547444	KU	4	40 BRN	SP	CCA	V	10/1/2051
2021	PO0774047253	KU	4	40 BRN	SP	CCA	V	10/2/2051
2021	PO0693047811	KU	4	40 BRN	SP	CCA	V	10/3/2051
2021	PO0680947843	KU	4	40 BRN	SP	CCA	V	10/4/2051

2021 PO7907455233	KU	3	45 UNK	SP	CCA	V	10/5/2051
2021 PO7907455233-A	KU	4	45 UNK	SP	CCA	V	10/6/2051
2021 PO7951455897	KU	3	45 UNK	SP	CCA	V	10/7/2051
2021 PO7954956016	KU	6	30 UNK	SP	CCA	V	10/8/2051
2021 PO7956955928	KU	3	45 UNK	SP	CCA	V	10/9/2051
2021 PO6895716044	KU	3	45 ACW	SP	S	V	10/10/2051
2021 PO6926816822	KU	4	45 ACW	SP	S	V	10/11/2051
2021 PO6912116683	KU	4	45 ACW	SP	S	V	10/12/2051
2021 PO0746347243	KU	3	45 BRN	SP	CCA	V	10/13/2051
2021 PO4167186392	LGE	4	35 BRO	SP	CCA	V	10/14/2051
2021 PO7998855702	KU	6	30 UNK	SP	CCA	V	10/15/2051
2021 PO7962255704	KU	3	45 UNK	SP	CCA	V	10/16/2051
2021 PO7975655505	KU	3	45 UNK	SP	CCA	V	10/17/2051
2021 PO7984955349	KU	3	45 UNK	SP	CCA	V	10/18/2051
2021 PO7977155333	KU	5	35 UNK	SP	CCA	V	10/19/2051
2021 PO0838748224	KU	3	45 BRN	SP	CCA	V	10/20/2051
2021 PO4575009717	F	4	40 XXX	SP	CRE	V	10/21/2051
2021 PO4581009752	F	4	40 XXX	SP	CRE	V	10/22/2051
2021 PO4600910184	F	4	40 XXX	SP	CRE	V	10/23/2051
2021 PO4597210103	F	4	40 XXX	SP	CRE	V	10/24/2051
2021 PO4590909967	F	4	40 XXX	SP	CRE	V	10/25/2051
2021 PO4586209867	F	4	40 XXX	SP	CRE	V	10/26/2051
2021 PO0747148555	KU	3	45 BRN	SP	CRE	V	10/27/2051
2021 PO2108933334	F	4	40 BRN	SP	CRE	V	10/28/2051
2021 PO2155933271	KU	4	40 BRN	SP	CRE	V	10/29/2051
2021 PO2144033602	F	4	45 BRN	SP	CRE	V	10/30/2051
2021 PO2127733484	F	4	45 BRN	SP	A	V	10/31/2051
2021 PO1698643512	F	6	30 BRN	SP	CRE	V	11/1/2051
2021 PO4129886137	F	4	40 BRN	SP	P	V	11/2/2051
2021 PO7790160061-A	KU	5	35 UNK	SP	CCA	V	11/3/2051
2021 PO7790160061	F	4	40 UNK	SP	CRE	V	11/4/2051
2021 PO7786560138	F	5	35 UNK	SP	CRE	V	11/5/2051
2021 PO7792360102	F	5	35 UNK	SP	CRE	V	11/6/2051
2021 PO8521566693	KU	3	45 BRO	SP	CCA	V	11/7/2051
2021 PO8484166326	KU	6	30 BRO	SP	CCA	V	11/8/2051
2021 PO8508366369	KU	3	45 BRO	SP	CCA	V	11/9/2051
2021 PO4131386137	F	4	30 BRN	SP	P	V	11/10/2051
2021 PO4131186133	F	4	40 BRN	SP	P	V	11/11/2051
2021 PO4132286130	F	4	40 BRN	SP	P	V	11/12/2051
2021 PO4187186161	F	4	40 BRO	SP	A	V	11/13/2051
2021 PO1647544055	F	4	40 BRN	SP	CRE	V	11/14/2051
2021 PO1637744247	F	6	30 BRN	SP	CRE	V	11/15/2051
2021 PO1632544209	F	4	40 BRN	SP	CRE	V	11/16/2051
2021 PO853665229	KU	3	45 BRO	SP	CCA	V	11/17/2051
2021 PO8535065262	KU	3	50 BRO	SP	CCA	V	11/18/2051
2021 PO4183286163	F	4	40 BRO	SP	CRE	V	11/19/2051
2021 PO4184186162	F	4	40 BRO	SP	A	V	11/20/2051
2021 PO4185286162	F	4	40 BRO	SP	CRE	V	11/21/2051
2021 PO4185486159	F	4	30 BRO	SP	A	V	11/22/2051
2021 PO4185286143	F	4	35 BRO	SP	CRE	V	11/23/2051
2021 PO4185786162	F	4	40 BRO	SP	A	V	11/24/2051
2021 PO4186286161	F	4	40 BRO	SP	CRE	V	11/25/2051
2021 PO4560209701	F	4	40 XXX	SP	CRE	V	11/26/2051
2021 PO4127286123	LGE	3	45 BRN	SP	CCA	V	11/27/2051

2021 PO4126786113	LGE	2	55 BRN	SP	CCA	V	11/28/2051
2021 PO1619144405	F	4	45 BRN	SP	CRE	V	11/29/2051
2021 PO1609744537	F	4	40 BRN	SP	CRE	V	11/30/2051
2021 PO1601344654	F	3	45 BRN	SP	CRE	V	12/1/2051
2021 PO1606244685	F	6	35 BRN	SP	CRE	V	12/2/2051
2021 PO1586344762	F	4	40 BRN	SP	CRE	V	12/3/2051
2021 PO7798360066	F	4	40 UNK	SP	CRE	V	12/4/2051
2021 PO4182286167	LGE	4	30 BRO	SP	CCA	V	12/5/2051
2021 PO8383864847	KU	3	45 BRO	SP	CCA	V	12/6/2051
2021 PO4124386082	F	4	40 BRN	SP	CRE	V	12/7/2051
2021 PO4125286084	LGE	3	50 BRN	SP	CCA	V	12/8/2051
2021 PO4522109689	F	4	40 XXX	SP	CRE	V	12/9/2051
2021 PO4520309581	F	4	40 KOP	SP	A	V	12/10/2051
2021 PO4537309632	F	4	40 XXX	SP	CRE	V	12/11/2051
2021 PO8147457415	KU	4	40 UNK	SP	CCA	V	12/12/2051
2021 PO8414365012	KU	6	30 BRO	SP	CCA	V	12/13/2051
2021 PO4122686034	LGE	1	80 BRN	SP	CRE	V	12/14/2051
2021 PO4185486180	LGE	4	40 BRO	SP	CCA	V	12/15/2051
2021 PO1332444170	F	4	40 BRN	SP	CRE	V	12/16/2051
2021 PO1325444146	F	5	40 BRN	SP	CRE	V	12/17/2051
2021 PO1319344300	F	6	35 BRN	SP	CRE	V	12/18/2051
2021 PO1327244304	F	4	40 BRN	SP	CRE	V	12/19/2051
2021 PO1322344457	F	4	40 BRN	SP	CRE	V	12/20/2051
2021 PO1314544672	F	4	40 BRN	SP	P	V	12/21/2051
2021 PO0953952082	F	4	40 BRN	SP	A	V	12/22/2051
2021 PO0931851773	F	4	40 BRN	SP	A	V	12/23/2051
2021 PO0915151552	F	4	40 BRN	SP	A	V	12/24/2051
2021 PO8120456393	KU	3	45 UNK	SP	CCA	V	12/25/2051
2021 PO8130256576	KU	3	40 UNK	SP	CCA	V	12/26/2051
2021 PO4125185990	F	4	30 BRN	SP	CCA	V	12/27/2051
2021 PO4124386008	LGE	4	30 BRN	SP	CCA	V	12/28/2051
2021 PO4124985996	LGE	1	70 BRN	ST	P	V	12/29/2051
2021 PO8379371825	LGE	1	50 BRN	SP	CCA	V	12/30/2051
2021 PO4123886003	LGE	2	80 BRN	SP	A	V	12/31/2051
2021 PO4121686016	LGE	1	75 BRN	SP	P	V	1/1/2052
2021 PO4126385999	LGE	4	35 BRN	SP	CCA	V	1/2/2052
2021 PO4126285997	LGE	4	35 BRN	SP	CCA	V	1/3/2052
2021 PO4506909707	KU	3	45 BRN	SP	CCA	V	1/4/2052
2021 PO4478309643	KU	5	35 BRN	SP	CCA	V	1/5/2052
2021 PO4497709482	KU	3	45 BRN	SP	CCA	V	1/6/2052
2021 PO8114256730-A	KU	3	40 UNK	SP	CCA	V	1/7/2052
2021 PO8271664510	KU	3	45 BRO	SP	CCA	V	1/8/2052
2021 PO8237964384	KU	4	40 BRO	SP	S	V	1/9/2052
2021 PO8283764146	KU	4	45 BRO	SP	CCA	V	1/10/2052
2021 PO4175286347	LGE	4	30 BRO	SP	CCA	V	1/11/2052
2021 PO4175886325	LGE	3	45 BRO	SP	CCA	V	1/12/2052
2021 PO4179386165	F	4	40 BRO	SP	CRE	V	1/13/2052
2021 PO4177486166	F	3	45 BRO	SP	CCA	V	1/14/2052
2021 PO8626765656	KU	4	45 BRO	SP	CCA	V	1/15/2052
2021 PO8625765689	KU	3	50 BRO	SP	CCA	V	1/16/2052
2021 PO7773960217	F	5	35 UNK	SP	CRE	V	1/17/2052
2021 PO7779860180	F	4	40 UNK	SP	CRE	V	1/18/2052
2021 PO8590865476	KU	2	50 BRO	SP	CCA	V	1/19/2052
2021 PO8589265513	KU	3	45 BRO	SP	CCA	V	1/20/2052

2021 PO4181186164	F	4	40 BRO	SP	CRE		V					1/21/2052
2021 PO8556566693	KU	3	45 BRO	SP	CCA		V					1/22/2052
2021 PO7764160278	F	5	35 UNK	SP	CRE		V					1/23/2052
2021 PO4154786308	LGE	4	35 BRO	SP	CCA		V					1/24/2052
2021 PO8013855067	KU	5	35 UNK	SP	CCA		V					1/25/2052
2021 PO7978455138	KU	3	45 UNK	SP	CCA		V					1/26/2052
2021 PO7987254710	KU	3	45 UNK	SP	CCA		V					1/27/2052
2021 PO7984854904	KU	3	45 UNK	SP	CCA		V					1/28/2052
2021 PO8766465275	KU	4	40 BRO	SP	CCA		V					1/29/2052
2021 PO8767265134	KU	4	40 BRO	SP	CRE		V					1/30/2052
2021 PO8730664961	KU	3	45 BRO	SP	CRE		V					1/31/2052
2021 PO4199686332	LGE	4	35 BRO	SP	CCA		V					2/1/2052
2021 PO4198386317	F	4	40 BRO	SP	CCA		V					2/2/2052
2021 PO4162486280	LGE	4	25 BRO	SP	CRE		V					2/3/2052
2021 PO4160486272	LGE	2	45 BRO	SP	P		V					2/4/2052
2021 PO7005115738	KU	4	40 ACW	SP	S		V					2/5/2052
2021 PO4160886254	LGE	4	40 BRO	SP	CRE		V					2/6/2052
2021 PO3804308445	KU	3	50 BRN	SP	CRE	ED,ID,IP	TX			RR		2/7/2052
2021 PO4124886076	LGE	3	45E BRN	SP	CRE	ID,IP,RB	TX			RR		2/8/2052
2021 PO0781553151	KU	4	35 BRO	SP	CRE	ED,EP,ID,IP	TX			RR		2/9/2052
2021 PO4535210088	KU	4	40 XXX	SP	CRE	ED,ID	TX			RR		2/10/2052
2021 PO3880806812	KU	6	30 BRN	SP	CRE	ED,ID,RB,SRC	TX			RR		2/11/2052
2021 PO0785752963	KU	5	35 BRO	SP	CRE	ED,EP,ID,IP	TX			RR		2/12/2052
2021 PO4116185914	LGE	4	30 BRN	SP	P	ID,RB	TX			RR		2/13/2052
2021 PO4156686266	LGE	3	50 BRO	SP	A	ED,ID	TD					2/14/2052
2021 PO0684248438	KU	4	40 BRN	SP	CRE	ID	TD					2/15/2052
2021 PO3890506537	KU	6	35 BRN	SP	CRE	ED,ID	TD					2/16/2052
2021 PO8206764159	KU	4	40 BRO	SP	CRE	ED,ID	TD					2/17/2052
2021 PO0776048402	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD					2/18/2052
2021 PO6960914862	KU	4	45 ACW	SP	CRE	ED,ID	TD					2/19/2052
2021 PO8152563831	KU	4	40 BRO	SP	CRE	ED,ID	TD					2/20/2052
2021 PO7000514409	KU	6	30 ACW	SP	CRE	ED,ID	TD					2/21/2052
2021 PO3894306726	KU	6	35 BRN	SP	CRE	ED,ID	TD					2/22/2052
2021 PO3674008974	KU	3	40 BRN	SP	CCA	ED	TD					2/23/2052
2021 PO8129558651	KU	4	40 UNK	SP	CRE	ID,IP	TD					2/24/2052
2021 PO8123758649	KU	6	30 UNK	SP	CRE	ID,IP	TD					2/25/2052
2021 PO7908855073	KU	5	30 UNK	SP	CRE	ID,IP	TD					2/26/2052
2021 PO8345464818	KU	4	35 BRO	SP	CRE	ED,ID	TD					2/27/2052
2021 PO6968515966	KU	4	40 ACW	SP	CRE	ED,ID	TD					2/28/2052
2021 PO6950015701	KU	4	40 ACW	SP	CRE	ED,ID	TD					2/29/2052
2021 PO4586310005	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD					3/1/2052
2021 PO4560610049	KU	4	40 XXX	SP	CRE	ED,ID	TD					3/2/2052
2021 PO8694865622	KU	4	40 BRO	SP	CRE	ED,ID	TD					3/3/2052
2021 PO8709465801	KU	4	40 BRO	SP	CRE	ED,ID	TD					3/4/2052
2021 PO0772652716	KU	4	40 BRO	SP	CRE	ED,ID	TD					3/5/2052
2021 PO0748754238	KU	4	40 BRO	SP	CRE	ED,ID	TD					3/6/2052
2021 PO0776753859	KU	4	40 BRO	SP	CRE	ED,ID	TD					3/7/2052
2021 PO0789153774	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD					3/8/2052
2021 PO1279045043	KU	4	40 BRN	SP	CRE	ID	TD					3/9/2052
2021 PO4172586283	LGE	4	40 BRO	SP	A	ED,ID	TD					3/10/2052
2021 PO4057706557	KU	6	35 BRN	SP	CRE	ED,ID	TD					3/11/2052
2021 PO0886753571	KU	4	40 BRO	SP	CRE	ED,ID	TD					3/12/2052
2021 PO4173586288	LGE	4	30 BRO	SP	CRE	ED,ID	TD					3/13/2052
2021 PO8679265432	KU	4	45 BRO	SP	CRE	ED,ID	TD					3/14/2052

2021 PO3768908769	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/15/2052
2021 PO4517609821	KU	6	30 XXX	SP	CRE	ED,ID	TD			3/16/2052
2021 PO8138958787	KU	4	45 UNK	SP	CRE	ID	TD			3/17/2052
2021 PO3872706506	KU	7	35 BRN	SP	CRE	ED,ID	TD			3/18/2052
2021 PO1388147573	KU	6	30 BRN	SP	CRE	ED,ID	TD			3/19/2052
2021 PO6886715697	KU	4	40 ACW	SP	CRE	ED,ID	TD			3/20/2052
2021 PO6874615636	KU	4	40 ACW	SP	CRE	ED,ID	TD			3/21/2052
2021 PO5040289624	LGE	4	40 ACE	SP	CRE	ED,ID	TD			3/22/2052
2021 PO5040189613	LGE	4	40 ACE	SP	CRE	ED,ID	TD			3/23/2052
2021 PO5042489623	LGE	4	40 ACE	SP	A	ED,ID	TD			3/24/2052
2021 PO5563498699	F	4	40 XXX	SP	CRE	ED,ID,MD	BX		RP3	3/25/2052
2021 PO5550398784	F	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	BX		PX	3/26/2052
2021 PO5549398688	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX		PX	3/27/2052
2021 PO5543598715	F	4	40 XXX	SP	CRE	ED,ID,IP,MD	BX		PX	3/28/2052
2021 PO5535898750	F	4	40 XXX	SP	CRE		V			3/29/2052
2021 PO2219358992	KU	5	35 BRO	SP	CRE	ED,ID,IP	TX		RR	3/30/2052
2021 PO1189278901	KU	5	35 BRO	SP	CRE	ED,ID	TD			3/31/2052
2021 PO1157979287	KU	5	35 BRO	SP	CCA		V			4/1/2052
2021 PO6564891021	F	4	45 BRN	SP	P		V			4/2/2052
2021 PO6546690958	F	4	40 BRN	SP	CRE		V			4/3/2052
2021 PO5045189588	LGE	4	40 ACE	SP	CRE	ED,ID	TD			4/4/2052
2021 PO5046789591	LGE	4	40 ACE	SP	A	ED,ID	TD			4/5/2052
2021 PO1304177323	KU	5	35 BRO	SP	CRE	ED,ID	TD			4/6/2052
2021 PO1304176844	KU	5	35 BRO	SP	CRE	ED,ID	TD			4/7/2052
2021 PO1148976494	KU	3	45 BRO	SP	CCA		V			4/8/2052
2021 PO2172358550	KU	4	40 BRO	SP	CRE	ED,ID,IP	TX		RR	4/9/2052
2021 PO0264461238	KU	4	40 BRO	SP	CRE	ED,ID	TD			4/10/2052
2021 PO0239761287	KU	3	40 BRO	SP	CRE	ED,ID	TD			4/11/2052
2021 PO0216161331	KU	4	40 BRO	SP	CRE	ED,ID	TD			4/12/2052
2021 PO1188976567	KU	3	45 BRO	SP	CCA		V			4/13/2052
2021 PO4066407281	F	4	40 BRN	SP	CRE	IP,RB	BX		RP2	4/14/2052
2021 PO5007888354	LGE	3	50 BRN	SP	P	ED,ID	T			4/15/2052
2021 PO5008888334	LGE	3	50 BRN	SP	CCA	MD	V			4/16/2052
2021 PO5009188327	F	4	40 BRN	SP	CCA		V			4/17/2052
2021 PO4974988591	LGE	4	30 BRO	SP	A	ED,ID,IP	TD			4/18/2052
2021 PO1224976642	KU	4	40 BRO	SP	CRE	ED,ID	TD			4/19/2052
2021 PO5001788286	LGE	4	30 BRN	SP	CRE	ED,ID	TD			4/20/2052
2021 PO5006688282	LGE	4	35 BRN	SP	CCA		T			4/21/2052
2021 PO5007788288	LGE	1	50 BRN	SP	CCA		V			4/22/2052
2021 PO7124895840	LGE	3	45 BRN	SP	P	ED,ID	BD			4/23/2052
2021 PO7128295818	LGE	4	30 BRN	SP	P	ED,ID	BD			4/24/2052
2021 PO5000988237	LGE	3	45 BRN	SP	P	ED,ID	BD			4/25/2052
2021 PO5044889581	LGE	4	40 ACE	SP	CRE	ED,ID	BD			4/26/2052
2021 PO1326177017	KU	4	40 BRO	SP	CRE	ED,ID	TD			4/27/2052
2021 PO6646289564	F	4	40 BRN	SP	CRE		V			4/28/2052
2021 PO0148660607	KU	6	30 UNK	SP	CRE	ED,ID	TD			4/29/2052
2021 PO0139760414	KU	3	45 BRO	SP	CCA		V			4/30/2052
2021 PO0126660109	KU	4	40 UNK	SP	CRE	ED,ID	TD			5/1/2052
2021 PO0122560147	KU	6	30 UNK	SP	CRE	ED,ID	TD			5/2/2052
2021 PO0122459869	KU	4	40 UNK	SP	CRE	ED,ID	TD			5/3/2052
2021 PO4970088561	LGE	3	45 BRO	SP	A	ED,ID,IP	TD			5/4/2052
2021 2009757014a	KU	6	30 BRO	SP	CRE	RB	BX		PX	5/5/2052
2021 PO2044856884	KU	4	45 BRO	SP	CRE	ED,ID	TD			5/6/2052
2021 PO2009757014	KU	5	40 BRO	SP	CRE	ED,ID	TD			5/7/2052



2021	PO6698789742	F	4	40 BRN	SP	CRE			V			5/8/2052
2021	PO5578098462	F	4	40 XXX	SP	P			V			5/9/2052
2021	PO5514398522	F	4	40 XXX	SP	CRE		ED,ID,MD,RB	BX		RP2	5/10/2052
2021	PO5527698562	F	4	40 XXX	SP	S			V			5/11/2052
2021	PO5523898459	F	3	40 XXX	SP	P			V			5/12/2052
2021	PO5533198413	F	4	40 XXX	SP	CRE		ED,ID,MD,RB	BX		PX	5/13/2052
2021	PO5553198435	F	4	40 XXX	SP	CRE		ED,ID,IP,MD	BX		RP2	5/14/2052
2021	PO5566098447	F	3	40 XXX	SP	P			V			5/15/2052
2021	PO5601398485	F	4	40 XXX	SP	CCA			V			5/16/2052
2021	PO5613298499	F	4	40 XXX	SP	P			V			5/17/2052
2021	PO5625698514	F	4	40 XXX	SP	P			V			5/18/2052
2021	PO5635998521	F	4	40 XXX	SP	P			V			5/19/2052
2021	PO5645198572	KU	3	40 XXX	SP	P			V			5/20/2052
2021	PO4118407416	F	4	40 BRN	SP	CRE		HH,ID,IP	BX		RP1	5/21/2052
2021	PO4179904238	F	3	45 BRN	SP	CCA			V			5/22/2052
2021	PO4171004269	F	3	40 BRN	SP	CCA			V			5/23/2052
2021	PO4100507376	F	4	40 BRN	SP	CRE		HH,ID,IP,RB	BX		PX	5/24/2052
2021	PO4185404489	F	4	40 BRN	SP	CRE		ED,EP,HH,ID,IP,RB	BX		PX	5/25/2052
2021	PO4132207325	F	4	40 BRN	SP	CRE			V			5/26/2052
2021	PO5040589594	LGE	3	45 ACE	SP	A		ED,ID	BD			5/27/2052
2021	PO5039989597	LGE	3	50 ACE	SP	A		ED,ID	BD			5/28/2052
2021	PO5037989605	LGE	3	45 ACE	SP	CCA			V			5/29/2052
2021	PO7458509407	LGE	3	45 ACE	SP	CCA			V			5/30/2052
2021	PO0111259907	KU	6	35 UNK	SP	CRE		ED,HH,ID	BX		PX	5/31/2052
2021	PO0113859476	KU	4	35 UNK	SP	CCA		ED,ID	TD			6/1/2052
2021	PO0096359049	KU	4	40 UNK	SP	CRE		ED,ID	TD			6/2/2052
2021	PO0104658991	KU	4	40 UNK	SP	CRE		ED,ID	TD			6/3/2052
2021	PO1448375636	KU	4	40 BRO	SP	CRE		ED,ID	TD			6/4/2052
2021	PO5002688262	LGE	3	50 BRN	SP	P			V			6/5/2052
2021	PO5450899697	F	4	40 XXX	DF	CRE		ED,ID,IP,MD	BX		RP1	6/6/2052
2021	PO1564080923A	KU	6	30 BRO	SP	CRE		ED,ID	TD			6/7/2052
2021	PO4851991519	LGE	4	25 BRN	SP	CRE		ED,ID	BD			6/8/2052
2021	PO4852091528	LGE	4	35 BRN	SP	CCA		ED,ID	BD			6/9/2052
2021	PO5598798737	F	4	40 XXX	SP	CRE			V			6/10/2052
2021	PO5574498711	F	4	40 XXX	SP	CRE			V			6/11/2052
2021	PO2103354551	KU	4	40 XXX	SP	CRE		ED,ID	TD			6/12/2052
2021	PO2114154516	KU	4	40 XXX	SP	CRE		ID	TD			6/13/2052
2021	PO2126254479	KU	4	40 XXX	SP	CRE		ID,IP	TD			6/14/2052
2021	PO2180660479	KU	4	40 BRO	SP	CRE		ED,ID	TD			6/15/2052
2021	PO1547780702	KU	4	40 BRO	SP	CRE		ED,ID	TD			6/16/2052
2021	PO1558380878	KU	5	30 BRO	SP	CRE		ED,ID	TD			6/17/2052
2021	PO1564080923	KU	6	30 BRO	SP	CRE		ED,ID	TD			6/18/2052
2021	PO1548180413	KU	4	40 BRO	SP	CRE		ED,ID	TD			6/19/2052
2021	PO4851789895	LGE	3	45 BRO	SP	CCA			V			6/20/2052
2021	PO4847489902	LGE	4	40 BRO	SP	CCA			V			6/21/2052
2021	PO6595395581	F	4	40 BRN	SP	CRE		MD	VX		PX	6/22/2052
2021	PO4856191532	LGE	4	35 BRN	SP	A		ED,ID	BD			6/23/2052
2021	4858491527-a	LGE	4	35 BRN	SP	A		ED,ID	BD			6/24/2052
2021	4858491527	KU	4	35 BRN	SP	A		ED,ID	BD			6/25/2052
2021	4858491527	LGE	4	35 BRN	SP	A		ED,ID,IP	BD			6/26/2052
2021	PO0275065484	KU	5	35 UNK	SP	CRE		ED,HH,ID,RB	X		RP1	6/27/2052
2021	PO5649098857	F	4	40 XXX	SP	CRE		ED,HH,ID,MD	BX		PX	6/28/2052
2021	PO5632498849	F	4	40 XXX	SP	CRE		ED,EP,ID,MD	BX		RP1	6/29/2052
2021	PO4231102727	KU	3	45 BRN	SP	S			V			6/30/2052

2021 PO4239602813	F	4	40 BRN	SP	CRE		V	7/1/2052
2021 PO4853491529	LGE	4	35 BRN	SP	A	ED,ID	BD	7/2/2052
2021 PO4854991531	LGE	4	35 BRN	SP	CCA		V	7/3/2052
2021 PO0308465726	KU	6	30 UNK	SP	CRE	ED,ID	TD	7/4/2052
2021 PO0237566020	KU	2	50 BRO	SP	CCA		V	7/5/2052
2021 PO4853689881	LGE	3	50 BRO	SP	CCA		V	7/6/2052
2021 PO4846889935	LGE	3	45 BRO	SP	CCA		V	7/7/2052
2021 PO6668895523	F	4	40 BRN	SP	CRE		V	7/8/2052
2021 PO6687695584	F	4	40 BRN	SP	CRE		V	7/9/2052
2021 PO2210260467	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/10/2052
2021 PO4843789960	LGE	3	45 BRO	SP	A	ID,IP	BD	7/11/2052
2021 PO4845389948	LGE	3	45 BRO	SP	A	ID,IP	BD	7/12/2052
2021 PO6633495497	F	4	40 BRN	SP	CRE		V	7/13/2052
2021 PO6611395524	F	4	40 BRN	SP	CRE		V	7/14/2052
2021 PO0250265571	KU	3	45 UNK	SP	CRE	ID	BD	7/15/2052
2021 PO0255865356	KU	3	45 BRO	SP	CCA		V	7/16/2052
2021 PO1566580360	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/17/2052
2021 PO1620880212	KU	3	45 BRO	SP	CCA		V	7/18/2052
2021 PO1548279990	KU	4	40 BRO	SP	CCA		V	7/19/2052
2021 PO1548879536	KU	5	35 BRO	SP	CCA		V	7/20/2052
2021 PO2384961342	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	7/21/2052
2021 PO2377461236	KU	4	40 BRO	SP	CCA		V	7/22/2052
2021 PO2128254361	KU	6	35 XXX	SP	CRE	ID	TD	7/23/2052
2021 PO2143554394	KU	4	40 XXX	SP	CRE	ID	TD	7/24/2052
2021 PO2142054127	KU	4	40 XXX	SP	CCA		V	7/25/2052
2021 PO2156054107	KU	5	35 XXX	SP	CCA		V	7/26/2052
2021 PO2141453947	KU	4	40 XXX	SP	CRE	ID	TD	7/27/2052
2021 PO5654998572	F	4	40 XXX	SP	P		V	7/28/2052
2021 PO5646798536	F	5	30 XXX	SP	P		V	7/29/2052
2021 PO5662998619	F	5	30 XXX	SP	P		V	7/30/2052
2021 PO6494496181	F	4	40 BRN	SP	CRE		V	7/31/2052
2021 PO6531895948	F	3	45 BRN	SP	CCA		V	8/1/2052
2021 PO6546795858	F	4	40 BRN	SP	CRE		V	8/2/2052
2021 PO6517796037	F	2	50 BRN	SP	CCA		V	8/3/2052
2021 PO6565495745	F	4	40 BRN	SP	CRE		V	8/4/2052
2021 PO6578595666	F	4	40 BRN	SP	CRE		V	8/5/2052
2021 PO6470996317	F	4	40 BRN	SP	CRE		V	8/6/2052
2021 PO6446396463	F	4	40 BRN	SP	CRE		V	8/7/2052
2021 PO6426296575	KU	2	45 BRN	SP	CCA		V	8/8/2052
2021 PO6707795612	F	4	40 BRN	SP	CRE		V	8/9/2052
2021 PO6702995422	F	4	40 BRN	SP	CRE		V	8/10/2052
2021 PO6697295222	KU	5	35 BRN	SP	CCA		V	8/11/2052
2021 PO6697295222	F	4	40 BRN	SP	CRE		V	8/12/2052
2021 PO6691395023	F	4	40 BRN	SP	CRE		V	8/13/2052
2021 PO6686194840	F	4	40 BRN	SP	CRE		V	8/14/2052
2021 PO0271965009	KU	4	40 UNK	SP	CRE	ED,ID	TD	8/15/2052
2021 PO0244764958	KU	4	45 UNK	SP	CRE	ED,ID	TD	8/16/2052
2021 PO0284664681	KU	3	50 UNK	SP	CRE	ID	BD	8/17/2052
2021 PO0232464570	KU	5	35 UNK	SP	CRE	ED,ID	TD	8/18/2052
2021 PO2359161043	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/19/2052
2021 PO4848189925	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	8/20/2052
2021 PO4851189888	LGE	3	50 BRO	SP	CCA		V	8/21/2052
2021 PO4214402556	F	4	40 BRN	SP	CRE		V	8/22/2052
2021 PO4222702641	F	4	40 BRN	SP	CRE		V	8/23/2052

2021 PO5000488493	LGE	4	35 BRN	SP	P		V			8/24/2052
2021 PO5013788950	LGE	4	40 BRN	SP	CCA		V			8/25/2052
2021 PO5015488935	LGE	4	40 BRN	SP	CCA		V			8/26/2052
2021 PO5016088930	LGE	4	40 BRN	SP	CCA		V			8/27/2052
2021 PO2372860946	KU	6	30 BRO	SP	CCA		V			8/28/2052
2021 PO5625998968	F	4	40 XXX	SP	CRE		V			8/29/2052
2021 PO5638498915	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX		8/30/2052
2021 PO5617099069	F	4	40 XXX	SP	P		V			8/31/2052
2021 PO5608999154	F	4	40 XXX	SP	CRE		V			9/1/2052
2021 PO5600799243	F	4	40 XXX	SP	P		V			9/2/2052
2021 PO5592899328	F	4	40 XXX	SP	P		V			9/3/2052
2021 PO5584399416	F	4	40 XXX	SP	CRE	HH,ID,MD	BX	PX		9/4/2052
2021 PO5579399453	F	4	40 XXX	SP	CRE	ED,ID,MD	BX	RP2		9/5/2052
2021 PO5570699510	F	4	40 XXX	SP	CRE		V			9/6/2052
2021 PO5547598931	F	4	40 XXX	SP	CRE		V			9/7/2052
2021 PO5553298936	F	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	BX	PX		9/8/2052
2021 2327660696a	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			9/9/2052
2021 PO2327660696	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD			9/10/2052
2021 PO0225364279	KU	5	35 UNK	SP	CRE	ED,ID	TD			9/11/2052
2021 PO0295064392	KU	3	40 UNK	SP	CRE	ID	BD			9/12/2052
2021 PO0245464310	KU	4	40 KOP	SP	CRE	ED,ID	TD			9/13/2052
2021 PO0305464076	KU	4	40 UNK	SP	CRE	ID	BD			9/14/2052
2021 PO2140753741	KU	5	35 XXX	SP	CRE	ID,IP	TD			9/15/2052
2021 PO2149253733	KU	6	30 XXX	SP	CRE	ID	TD			9/16/2052
2021 PO2138853552	KU	6	35 XXX	SP	CRE	ED,ID	TD			9/17/2052
2021 PO5584999022	F	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	BX	PX		9/18/2052
2021 PO2143153327	KU	6	30 XXX	SP	CRE	ID	TD			9/19/2052
2021 PO2134953348	KU	4	40 XXX	SP	CRE	ID	TD			9/20/2052
2021 PO2132153190	KU	4	35 XXX	SP	CRE	ID	TD			9/21/2052
2021 PO4823991032	LGE	2	55 BRN	SP	CCA		V			9/22/2052
2021 PO5652705810	F	4	40 BRN	SP	CRE		V			9/23/2052
2021 PO5646105884	F	4	40 BRN	SP	CRE		V			9/24/2052
2021 PO4310387203	LGE	3	45 BRO	SP	A	ID,IP	BD			9/25/2052
2021 PO2185652548	KU	4	40 XXX	SP	CRE	ID	TD			9/26/2052
2021 PO2219552620	KU	4	40 XXX	SP	CRE	ID	TD			9/27/2052
2021 PO2247952679	KU	4	40 XXX	SP	CCA		V			9/28/2052
2021 PO2297352748	KU	4	40 XXX	SP	CRE	ID	BD			9/29/2052
2021 PO2275152719	KU	4	40 XXX	SP	CRE	ID	TD			9/30/2052
2021 PO2317052778	KU	4	40 XXX	SP	CRE	ID	TD			10/1/2052
2021 PO2337152815	KU	4	40 XXX	SP	CRE	ID	TD			10/2/2052
2021 PO2337452945	KU	5	35 XXX	SP	CRE	ID	TD			10/3/2052
2021 PO2352852774	KU	4	40 XXX	SP	CRE	ID	TD			10/4/2052
2021 PO2374852757	KU	4	40 XXX	SP	CRE	ID	TD			10/5/2052
2021 PO6211489040	KU	4	45 BRN	SP	CRE		V			10/6/2052
2021 PO6206088955	KU	2	50 BRN	SP	CCA		V			10/7/2052
2021 PO6201588968	KU	2	50 BRN	SP	CCA		V			10/8/2052
2021 PO6185588751	KU	2	50 BRN	SP	CCA		V			10/9/2052
2021 PO1411771348	KU	4	40 BRO	SP	CRE	ED,ID	TD			10/10/2052
2021 PO5039688797	LGE	3	45 BRN	SP	P		V			10/11/2052
2021 PO5041288788	LGE	3	50 BRN	SP	P	ED,ID	TD			10/12/2052
2021 PO5039888797	LGE	3	50 BRN	SP	P	ED,ID	BD			10/13/2052
2021 PO5042888780	LGE	3	45 BRN	SP	P	ED,ID	BD			10/14/2052
2021 PO4310787180	LGE	3	45 BRO	SP	A	ID,IP	BD			10/15/2052
2021 PO6166588248	KU	2	45 BRN	SP	CRE	ED	TD			10/16/2052

2021 PO4309887161	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	10/17/2052
2021 PO4326286977	LGE	4	40 ACE	SP	CCA		V	10/18/2052
2021 PO4326886967	LGE	4	35 ACE	SP	CCA		V	10/19/2052
2021 PO6166388343	KU	6	30 BRN	SP	CCA		V	10/20/2052
2021 PO6163588356	KU	2	70 BRN	SP	CRE		V	10/21/2052
2021 PO6160888377	KU	3	40 BRN	SP	CRE		V	10/22/2052
2021 PO6158788343	KU	2	45 BRN	SP	CCA		V	10/23/2052
2021 PO6157188416	KU	3	45 BRN	SP	CCA		V	10/24/2052
2021 PO6159188416	KU	2	45 BRN	SP	CCA		V	10/25/2052
2021 PO4257903201	F	3	45 BRN	SP	CCA		V	10/26/2052
2021 PO4267003294	F	3	45 BRN	SP	CCA		V	10/27/2052
2021 PO4247303097	F	2	50 BRN	SP	CRE		V	10/28/2052
2021 PO4334087058	LGE	UNK	50 ACE	SP	CRE	ED	BD	10/29/2052
2021 PO9706256275	KU	4	40 UNK	SP	CRE	ID	BD	10/30/2052
2021 PO9706456387	KU	4	40 UNK	SP	CRE	ID	BD	10/31/2052
2021 PO1688971796	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/1/2052
2021 PO4312687184	LGE	4	30 BRO	SP	CRE	ID,IP	BD	11/2/2052
2021 PO4312387186	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	11/3/2052
2021 PO4240803603	KU	2	55 BRN	SP	S		V	11/4/2052
2021 PO4257503499	KU	3	50 BRN	SP	S		V	11/5/2052
2021 PO4271703421	F	1	55 BRN	SP	S		V	11/6/2052
2021 PO4251503423	KU	6	30 BRN	SP	CRE		V	11/7/2052
2021 PO1704071689	KU	3	45 BRO	SP	CCA		V	11/8/2052
2021 PO1715371507	KU	6	30 BRO	SP	CCA		V	11/9/2052
2021 PO4312787192	LGE	3	50 BRO	SP	CCA	ED	T	11/10/2052
2021 PO1720271583	KU	3	45 BRO	SP	CCA		V	11/11/2052
2021 PO1750971405	F	4	40 BRO	SP	CRE		V	11/12/2052
2021 PO1744271393	KU	3	45 BRO	SP	CCA		V	11/13/2052
2021 PO4313587185	LGE	3	55 BRO	SP	A	ED,ID	TD	11/14/2052
2021 PO4224403702	KU	3	50 BRN	SP	S		V	11/15/2052
2021 PO1774670980	KU	4	30 BRO	SP	CRE	ED,ID	TD	11/16/2052
2021 PO1781871101	KU	3	45 BRO	SP	CCA		V	11/17/2052
2021 PO1767071192	KU	4	45 BRO	SP	CCA		V	11/18/2052
2021 PO7546614134	KU	4	40 ACW	SP	CRE	ED,ID	BD	11/19/2052
2021 PO7581314415	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/20/2052
2021 PO4138884435	LGE	4	35 ACE	SP	CRE	ED,ID	TD	11/21/2052
2021 PO3625434605	KU	4	40 UNK	SP	CRE	ID	TD	11/22/2052
2021 PO4052684938	LGE	2	45 UNK	SP	CRE	ID,IP,SRS	TD	11/23/2052
2021 PO4706975101	KU	4	40 BRN	SP	CCA		V	11/24/2052
2021 PO4688375349	KU	5	35 BRN	SP	CRE	ID	TD	11/25/2052
2021 PO4711375239	KU	5	35 BRN	SP	CRE	ED,ID	X	11/26/2052
2021 PO4737575072	KU	5	35 BRN	SP	CRE	ED,ID	X	11/27/2052
2021 PO4753774967	KU	4	40 BRN	SP	CRE	ID	TD	11/28/2052
2021 PO4723374339	KU	4	45 BRN	SP	CRE	ID	TD	11/29/2052
2021 PO4137184426	F	4	40 ACE	SP	CRE	ED,ID	V	11/30/2052
2021 PO4133884361a	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	12/1/2052
2021 PO4052384928	LGE	2	45 UNK	SP	CRE	ID,IP	BD	12/2/2052
2021 PO4052184922	LGE	2	45 UNK	SP	CRE	ID,IP	BD	12/3/2052
2021 PO4051784913	LGE	2	50 UNK	SP	CCA		V	12/4/2052
2021 PO4051584908	LGE	2	45 UNK	SP	CRE	ID	BD	12/5/2052
2021 PO4051284900	LGE	3	45 UNK	SP	CCA		V	12/6/2052
2021 PO4061984827	LGE	3	45 UNK	SP	CCA		V	12/7/2052
2021 PO4062184831	LGE	4	30 UNK	SP	CCA		V	12/8/2052
2021 PO4061184833	LGE	4	40 UNK	SP	A		V	12/9/2052

2021 PO4060084839	LGE	4	40 UNK	SP	CRE		V			12/10/2052
2021 PO3602635128	KU	4	40 BRO	SP	CRE	ID	TD			12/11/2052
2021 PO4181885887	LGE	4	40 BRO	SP	CRE	ED,ID,JP,RB	TX		RR	12/12/2052
2021 PO7672218450	KU	3	45 ACW	SP	S		V			12/13/2052
2021 PO7695818470	KU	5	35 ACW	SP	CRE	ED,ID	TD			12/14/2052
2021 PO7720818336	KU	4	40 ACW	SP	S		V			12/15/2052
2021 PO7714218055	KU	4	40 ACW	SP	S		V			12/16/2052
2021 PO4180485998	F	4	35 BRO	SP	CRE		V			12/17/2052
2021 PO4180586007	F	4	35 BRO	SP	CRE		V			12/18/2052
2021 PO4180686013	LGE	4	35 BRO	SP	A	ED,ID	TD			12/19/2052
2021 PO4058884851	LGE	4	30 UNK	SP	CCA		V			12/20/2052
2021 PO4058884847	LGE	4	40 UNK	SP	CRE		V			12/21/2052
2021 PO4057584855	LGE	4	40 UNK	SP	CRE		V			12/22/2052
2021 PO4056384862	LGE	3	40 UNK	SP	CCA		V			12/23/2052
2021 PO4136784537	LGE	3	45 ACE	SP	P	ED,ID	TD			12/24/2052
2021 PO4137184546	LGE	4	30 ACE	SP	P	ED,ID	BD			12/25/2052
2021 PO3583635539	KU	3	40 UNK	SP	CRE	ID	TD			12/26/2052
2021 PO4732274518	KU	4	40 BRN	SP	CRE	ID	TD			12/27/2052
2021 PO7720318348	KU	4	40 ACW	SP	S		V			12/28/2052
2021 PO7721018499	KU	5	35 ACW	SP	CRE	ED,ID	TD			12/29/2052
2021 PO7748818524	KU	5	35 ACW	DF	CRE	ED,ID	TD			12/30/2052
2021 PO7773918544	KU	4	40 ACW	SP	CRE	ED,ID	BD			12/31/2052
2021 PO4746574574	KU	4	40 BRN	SP	CRE	ID	TD			1/1/2053
2021 PO4775374656	KU	5	35 BRN	SP	CRE	ID	TD			1/2/2053
2021 PO4768674861	KU	5	35 BRN	SP	CRE	ID	BX		RP2	1/3/2053
2021 PO4793874604	KU	6	30 BRN	SP	CRE	ID	TD			1/4/2053
2021 PO4135684542	LGE	3	45 ACE	SP	P	ED,ID	TD			1/5/2053
2021 PO4136584539	LGE	3	45 ACE	SP	P	ED,ID	TD			1/6/2053
2021 PO7712060432	LGE	4	30 UNK	SP	CCA	SRS	TD			1/7/2053
2021 PO4055184870	LGE	3	45 UNK	SP	CCA		V			1/8/2053
2021 PO4055684876	LGE	4	40 UNK	SP	A	ID	TD			1/9/2053
2021 PO4133184550	LGE	3	45 ACE	SP	P	ED,ID	BD			1/10/2053
2021 PO4132384553	LGE	3	45 ACE	SP	P	ED,HH,ID,RB	BX		PX	1/11/2053
2021 PO3573335715	KU	6	30 BRO	SP	CCA		B			1/12/2053
2021 PO3645635084	KU	4	40 KOP	SP	CRE	ID	TD			1/13/2053
2021 PO4177685861	LGE	4	35 BRO	SP	CCA		V			1/14/2053
2021 PO7789318405	KU	4	40 ACW	SP	S		V			1/15/2053
2021 PO7784118228	KU	4	40 ACW	SP	S		V			1/16/2053
2021 PO7865818549	KU	4	40 ACW	SP	S		V			1/17/2053
2021 PO7807118228	KU	4	40 ACW	SP	S		V			1/18/2053
2021 PO7819218712	KU	4	45 ACW	SP	CRE	ED,ID	TD			1/19/2053
2021 PO7827619051	KU	4	40 ACW	SP	CRE	ED,ID	TD			1/20/2053
2021 PO4135284604a	KU	5	35 ACE	SP	CRE	ED,ID	BX		RP1	1/21/2053
2021 PO4177885898	LGE	4	40 BRO	SP	A	ED,ID,JP	TX		RR	1/22/2053
2021 PO4134384588b	KU	4	35 ACE	SP	P	ED,ID	TD			1/23/2053
2021 PO4134384588a	KU	4	35 ACE	SP	P	ED,ID	TD			1/24/2053
2021 PO3679734845	KU	4	40 ACW	SP	CRE	ED,ID	TD			1/25/2053
2021 PO3706834734	KU	4	40 KOP	SP	CRE	ID	TD			1/26/2053
2021 PO3722734671	KU	4	40 UNK	SP	CRE	ID	BD			1/27/2053
2021 PO4132784563	LGE	4	30 ACE	SP	P	ED,ID,JP	TD			1/28/2053
2021 PO4146886054	LGE	2	55 BRO	SP	A	ED,ID,JP	TD			1/29/2053
2021 PO4135284604	LGE	3	50 ACE	SP	P	ED,ID	TD			1/30/2053
2021 PO4133884588	LGE	3	50 ACE	SP	P	ED,ID	TD			1/31/2053
2021 PO4906674262	KU	3	45 BRN	SP	CCA		V			2/1/2053

2021 PO4145886054	LGE	1	95 BRO	SP	A	ID,IP	BD		2/2/2053
2021 PO4144886055	LGE	2	55 BRO	SP	A	ED,ID	TD		2/3/2053
2021 PO4143586056	LGE	2	55 BRO	SP	A	ED,ID	TD		2/4/2053
2021 PO4143586046	LGE	4	35 BRO	ST	P		V		2/5/2053
2021 PO4143586053	LGE	4	30 BRO	SP	CCA		V		2/6/2053
2021 PO7909856537	LGE	4	30 UNK	SP	A		V		2/7/2053
2021 PO4132784552	LGE	3	45 ACE	SP	P	ED,ID	BD		2/8/2053
2021 PO4136584539a	KU	4	35 ACE	SP	P	ED,ID	TD		2/9/2053
2021 PO4179585864	F	4	35 BRO	SP	CRE		V		2/10/2053
2021 PO4179685870	F	4	35 BRO	SP	CRE	ID,IP,RB	VX	RP1	2/11/2053
2021 PO4179685877	F	4	35 BRO	SP	CRE	HH,ID,RB	VX	RP1	2/12/2053
2021 PO4179785892	F	4	35 BRO	SP	CRE	ED,ID,IP,RB	VX	RP1	2/13/2053
2021 PO4180885910	F	4	40 BRO	SP	CRE		V		2/14/2053
2021 PO4178985911	F	4	40 BRO	SP	A		V		2/15/2053
2021 PO4179885911	F	4	40 BRO	SP	CRE		V		2/16/2053
2021 PO4180085939	F	4	35 BRO	SP	CRE	ID,IP,RB	VX	RP1	2/17/2053
2021 PO4180185947	F	4	35 BRO	SP	CRE		V		2/18/2053
2021 PO4180185954	F	4	35 BRO	SP	CRE		V		2/19/2053
2021 PO4180185962	F	4	35 BRO	SP	CRE		V		2/20/2053
2021 PO4180285966	F	4	40 BRO	SP	CRE		V		2/21/2053
2021 PO4181385965	F	4	40 BRO	SP	CRE		V		2/22/2053
2021 PO4180385968	F	4	35 BRO	SP	CRE		V		2/23/2053
2021 PO4180485980	F	4	35 BRO	SP	CRE		V		2/24/2053
2021 PO7845218526	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/25/2053
2021 PO4053784878	LGE	4	40 UNK	SP	A		V		2/26/2053
2021 PO4052384890	LGE	4	40 UNK	SP	CRE		V		2/27/2053
2021 PO4052484886	LGE	3	45 UNK	SP	A		V		2/28/2053
2021 PO4177885889	LGE	4	40 BRO	SP	A	ED,ID	TD		3/1/2053
2021 PO4177785881	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		3/2/2053
2021 PO4177585852	LGE	4	40 BRO	SP	A	ED,ID	TD		3/3/2053
2021 PO4177785871	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	3/4/2053
2021 PO3645635084-A	KU	5	30 BRN	SP	P		B		3/5/2053
2021 PO3661535175	KU	5	35 UNK	SP	CRE	ID	TD		3/6/2053
2021 PO4062984821	LGE	4	40 UNK	SP	CRE		V		3/7/2053
2021 PO4063184826	LGE	3	30 UNK	SP	CCA		V		3/8/2053
2021 PO4063784815	F	5	35 UNK	SP	CRE		V		3/9/2053
2021 PO4058984618	LGE	3	45 UNK	SP	CCA		V		3/10/2053
2021 PO4059084624	LGE	5	35 UNK	SP	A		V		3/11/2053
2021 PO7789757918	LGE	3	45 UNK	SP	CCA		V		3/12/2053
2021 PO4061384610	LGE	5	30 UNK	SP	A		V		3/13/2053
2021 PO4061884616	LGE	3	45 UNK	SP	CCA		V		3/14/2053
2021 PO4061884618	LGE	6	25 UNK	SP	CRE		V		3/15/2053
2021 PO4062284622	LGE	5	35 UNK	SP	A		V		3/16/2053
2021 PO4064084613	LGE	3	45 UNK	SP	CCA		V		3/17/2053
2021 PO4064284620	LGE	5	30 UNK	SP	A		V		3/18/2053
2021 PO4066084616	LGE	4	35 UNK	SP	CCA		V		3/19/2053
2021 PO4066184611	LGE	3	45 UNK	SP	CCA		V		3/20/2053
2021 PO4069584636	LGE	4	40 UNK	SP	A		V		3/21/2053
2021 PO4068884608	LGE	4	40 UNK	SP	CRE		V		3/22/2053
2021 PO4068984611	LGE	4	30 UNK	SP	CCA		V		3/23/2053
2021 PO4070684609	LGE	4	40 UNK	SP	A		V		3/24/2053
2021 PO4067984588	LGE	5	35 UNK	SP	CRE		V		3/25/2053
2021 PO4789074694	KU	5	35 BRN	SP	CRE	ID	TD		3/26/2053
2021 PO4823874790	KU	4	40 BRN	SP	CRE	ID	TD		3/27/2053

2021 PO4843674794	KU	4	40 BRN	SP	CRE	ID	TD	3/28/2053
2021 PO4868774807	KU	4	40 BRN	SP	CRE	ID	TD	3/29/2053
2021 PO4873174624	KU	3	45 BRN	SP	CCA		V	3/30/2053
2021 PO4904074460	KU	3	45 BRN	SP	CCA		V	3/31/2053
2021 PO3818337812	KU	5	30 BRO	SP	CRE		V	4/1/2053
2021 PO3877237112	KU	4	40 BRO	SP	CRE		B	4/2/2053
2021 PO3831737493	KU	3	40 BRO	SP	CCA		B	4/3/2053
2021 PO3843237709	KU	6	35 UNK	SP	CRE	ID	TD	4/4/2053
2021 PO3877237112A	KU	3	45 BRO	SP	CCA		V	4/5/2053
2021 PO3918037263	KU	3	45 BRO	SP	CCA		V	4/6/2053
2021 PO3861237402	KU	4	40 INP	SP	CRE	ID	TD	4/7/2053
2021 PO3879437364	KU	4	40 UNK	SP	CRE	ID	TD	4/8/2053
2021 PO3843838076	KU	3	40 BRO	SP	CCA		B	4/9/2053
2021 PO3843037913	KU	3	40 BRO	SP	CCA		B	4/10/2053
2021 PO3735134843	KU	4	40 UNK	SP	CRE	ID	TD	4/11/2053
2021 PO3734935030	KU	5	35 UNK	SP	CCA		B	4/12/2053
2021 PO3724235113	KU	4	45 UNK	SP	CCA		B	4/13/2053
2021 PO3718135071	KU	5	35 UNK	SP	CCA		V	4/14/2053
2021 PO3714135293	KU	6	30 UNK	SP	CCA		V	4/15/2053
2021 PO3719335306	KU	4	45 UNK	SP	S		B	4/16/2053
2021 PO3725635988	KU	4	45 UNK	SP	CCA		B	4/17/2053
2021 PO3707036017	KU	4	45 UNK	SP	CRE		B	4/18/2053
2021 PO3779037766	KU	4	45 UNK	SP	CRE	ID	TD	4/19/2053
2021 PO5111075589	KU	4	40 BRN	SP	CRE	ID	BD	4/20/2053
2021 PO5096275524	KU	4	40 BRN	SP	CRE	ED,ID	X	4/21/2053
2021 PO5072975425	KU	3	40 BRN	SP	CRE	ID	TD	4/22/2053
2021 PO5100075433	KU	6	30 BRN	SP	CRE	ID	TD	4/23/2053
2021 PO5039974912	KU	4	40 BRN	SP	CRE	ID	TD	4/24/2053
2021 PO5045375315	KU	3	40 BRN	SP	CRE	ID	TD	4/25/2053
2021 PO3715137798	KU	4	40 BRO	SP	CCA		B	4/26/2053
2021 PO3752937226	KU	4	45 BRO	SP	CCA		B	4/27/2053
2021 PO3750336990	KU	4	45 BRO	SP	CCA		B	4/28/2053
2021 PO3744336967	KU	4	40 BRO	SP	CCA		B	4/29/2053
2021 PO3756037518	KU	4	45 BRO	SP	CCA		B	4/30/2053
2021 PO3735737609	KU	4	45 BRO	SP	CCA		B	5/1/2053
2021 PO3715537699A	KU	3	40 BRO	SP	CCA		V	5/2/2053
2021 PO3715537699	KU	4	40 BRO	SP	CCA		B	5/3/2053
2021 PO3715837601	KU	4	45 BRO	SP	CCA		B	5/4/2053
2021 PO3690037673	KU	4	45 BRO	SP	CCA		B	5/5/2053
2021 PO3666737601	KU	4	45 BRO	SP	CCA		B	5/6/2053
2021 PO3645437513	KU	3	45 BRO	SP	CCA		V	5/7/2053
2021 PO5026975091	KU	5	35 BRN	SP	CRE	ED	BX	5/8/2053
2021 PO5019975194	KU	4	45 BRN	SP	CRE	ID	TD	5/9/2053
2021 PO4998975100	KU	3	50 BRN	SP	CRE	ID	TD	5/10/2053
2021 PO4163786095	F	4	40 BRO	SP	A		V	5/11/2053
2021 PO4164886094	F	4	40 BRO	SP	CRE		V	5/12/2053
2021 PO4166086095	F	3	45 BRO	SP	CRE		V	5/13/2053
2021 PO4165886094	F	4	40 BRO	SP	CRE		V	5/14/2053
2021 PO4176986010	F	4	30 BRO	SP	CRE		V	5/15/2053
2021 PO4176986000	F	4	35 BRO	SP	CRE		V	5/16/2053
2021 PO3608532720A	KU	3	45 BRO	SP	CCA		V	5/17/2053
2021 PO5117075442	KU	4	40 BRN	SP	CCA		V	5/18/2053
2021 PO3702134341	KU	4	45 ESC	SP	CRE	ID	BD	5/19/2053
2021 PO8805272620	LGE	4	35 BRO	SP	CCA		V	5/20/2053

2021 PO4166386080	LGE	4	40 BRO	SP	A	ED,ID	TD		5/21/2053
2021 PO4159185517	LGE	4	35 BRO	SP	A	ED,ID,JP,MD	TD		5/22/2053
2021 PO4159685532	F	4	40 BRO	SP	A		V		5/23/2053
2021 PO4165986084	F	4	40 BRO	SP	CRE		V		5/24/2053
2021 PO4165986075	F	4	40 BRO	SP	CRE		V		5/25/2053
2021 PO4165886064	F	4	35 BRO	SP	CCA		V		5/26/2053
2021 PO4165986071	F	4	40 BRO	SP	CRE		V		5/27/2053
2021 PO4162085642	LGE	4	35 BRO	SP	A		V		5/28/2053
2021 PO4161985634	LGE	4	35 BRO	SP	A	ID	TD		5/29/2053
2021 PO4161885620	LGE	4	35 BRO	SP	A	ID	TD		5/30/2053
2021 PO4164486072	LGE	4	35 BRO	SP	CCA	ED	T		5/31/2053
2021 PO4719074008	KU	4	45 BRN	SP	CRE	ID	TD		6/1/2053
2021 PO4724673837	KU	4	45 BRN	SP	CRE	ID	TD		6/2/2053
2021 PO4731673862	KU	6	30 BRN	SP	CCA		V		6/3/2053
2021 PO4727673488	KU	4	40 BRN	SP	CRE	ID	TD		6/4/2053
2021 PO4161685606	LGE	4	35 BRO	SP	P	ID	TD		6/5/2053
2021 PO4161685596	LGE	4	35 BRO	SP	CRE	ID,MD	TD		6/6/2053
2021 PO4161085666	LGE	4	35 BRO	SP	CRE	ED,ID,MD	TD		6/7/2053
2021 PO4161585662	LGE	4	35 BRO	SP	CRE	ED,ID,MD	TD		6/8/2053
2021 PO4163685625	LGE	4	35 BRO	SP	A	ED,ID	TD		6/9/2053
2021 PO4163385593	LGE	4	40 BRO	SP	A	ID	TD		6/10/2053
2021 PO4166585591	LGE	7	25 BRO	SP	CRE		V		6/11/2053
2021 PO8905167595	LGE	4	35 BRO	SP	CCA		V		6/12/2053
2021 PO4163686072	LGE	4	35 BRO	SP	CRE	ED,ID	TD		6/13/2053
2021 PO4733373234	KU	4	45 BRN	SP	CRE	ID	TD		6/14/2053
2021 PO4752973245	KU	6	30 BRN	SP	CRE	ID	TD		6/15/2053
2021 PO4744872134	KU	5	35 BRN	SP	CRE	ED,RB	X	RP2	6/16/2053
2021 PO4743472263	KU	4	40 BRN	SP	CRE	ID	TD		6/17/2053
2021 PO4756472213	KU	6	30 BRN	SP	CCA		V		6/18/2053
2021 PO4757773023	KU	4	40 BRN	SP	CRE	ED,ID,JP	X	RP3	6/19/2053
2021 PO4773272994	KU	6	30 BRN	SP	CRE		V		6/20/2053
2021 PO4776772930	KU	6	30 BRN	SP	CRE		V		6/21/2053
2021 PO4162286073	LGE	4	35 BRO	SP	CRE	ED,ID	TD		6/22/2053
2021 PO4161086073	LGE	4	35 BRO	SP	CRE	ED,ID,JP	TD		6/23/2053
2021 PO4159786074	LGE	4	35 BRO	SP	CRE	ED,ID,JP	TD		6/24/2053
2021 PO4157586077	LGE	4	35 BRO	SP	CRE	ED,ID,JP	TD		6/25/2053
2021 PO4158786076	LGE	4	35 BRO	SP	CRE	ED,ID,JP,RB	X	RP1	6/26/2053
2021 PO4154586079	LGE	4	35 BRO	SP	A	ED,ID	TD		6/27/2053
2021 PO4155186078	LGE	4	35 BRO	SP	CCA	ED	T		6/28/2053
2021 PO4156086078	LGE	4	35 BRO	SP	A	ED,ID	TD		6/29/2053
2021 PO4706474205	KU	4	45 BRN	SP	CRE	ID,JP	TX	RR	6/30/2053
2021 PO4158885629	LGE	4	35 BRO	SP	CRE	ED,ID,JP	TD		7/1/2053
2021 PO4158785615	LGE	4	35 BRO	SP	A	ED,ID,MD	BD		7/2/2053
2021 PO4158585604	LGE	4	35 BRO	SP	CRE	ID	BD		7/3/2053
2021 PO4164085503	LGE	4	40 BRO	SP	A	ID	TD		7/4/2053
2021 PO4163685486	LGE	4	35 BRO	SP	A	ID	BD		7/5/2053
2021 PO4163785476	LGE	4	35 BRO	SP	CRE	ED,ID,RB	TX	RR	7/6/2053
2021 PO4163785472	LGE	4	35 BRO	SP	CRE	ID	TD		7/7/2053
2021 PO4163485465	LGE	4	30 BRO	SP	P		V		7/8/2053
2021 PO4084485216	F	4	35 ACE	SP	CCA		V		7/9/2053
2021 PO4083485211	LGE	4	40 ACE	SP	CRE	ED,ID	BD		7/10/2053
2021 PO4167586079	LGE	4	35 BRO	SP	A	ED,ID	TD		7/11/2053
2021 PO4084485223	F	4	40 ACE	SP	A		V		7/12/2053
2021 PO4083685233	LGE	4	30 ACE	SP	P	ED,ID	BD		7/13/2053



2021 PO7659618086	KU	4	40 ACW	SP	S		V	7/14/2053
2021 PO7658918160	KU	4	40 ACW	SP	S		V	7/15/2053
2021 PO7661018309	KU	4	40 ACW	SP	S		V	7/16/2053
2021 PO7649818261	KU	3	45 ACW	SP	S		V	7/17/2053
2021 PO7634718226	KU	4	45 ACW	SP	S		V	7/18/2053
2021 PO7638718341	KU	4	40 ACW	SP	S		V	7/19/2053
2021 PO7638718371	KU	4	40 ACW	SP	S		V	7/20/2053
2021 PO7638718521	KU	4	40 ACW	SP	S		V	7/21/2053
2021 PO7513715351	KU	4	40 ACW	SP	S		V	7/22/2053
2021 PO4140484548	LGE	4	40 ACE	SP	CRE	ED,ID,JP	TD	7/23/2053
2021 PO4139984525	LGE	4	40 ACE	SP	P	ED,ID,JP	TD	7/24/2053
2021 PO4140184528	LGE	4	40 ACE	SP	P	ED,ID	TD	7/25/2053
2021 PO4214839889	KU	4	45 BRO	SP	CCA		B	7/26/2053
2021 PO4227540110	KU	4	45 BRO	SP	CCA		B	7/27/2053
2021 PO4227540110A	KU	4	45 BRO	SP	CCA		B	7/28/2053
2021 PO4176986146	LGE	4	35 BRO	SP	A	ED,ID	TD	7/29/2053
2021 PO4078185931	F	4	40 ACE	SP	P		V	7/30/2053
2021 PO4077085927	F	4	40 ACE	SP	CRE		V	7/31/2053
2021 PO4076085920	F	4	40 ACE	SP	A		V	8/1/2053
2021 PO4081285909	LGE	4	40 ACE	SP	CCA		V	8/2/2053
2021 PO4075485910	F	4	40 ACE	SP	CRE		V	8/3/2053
2021 PO4075085898	F	4	40 ACE	SP	CRE		V	8/4/2053
2021 PO4076985899	F	4	45 ACE	SP	A		V	8/5/2053
2021 PO4079685896	F	4	40 ACE	SP	CRE		V	8/6/2053
2021 PO4078485897	F	4	40 ACE	SP	CRE		V	8/7/2053
2021 PO4048186117	F	5	35 KOP	SP	A		V	8/8/2053
2021 PO4047986110	F	4	40 KOP	SP	A		V	8/9/2053
2021 PO4047686104	LGE	4	30 KOP	SP	CCA		V	8/10/2053
2021 PO5198708603	KU	5	40 ACE	SP	CCA		V	8/11/2053
2021 PO4021586078	LGE	4	40 ACE	SP	CCA		V	8/12/2053
2021 PO4021986082	LGE	4	30 ACE	SP	CCA		V	8/13/2053
2021 PO4021286088	LGE	5	35 ACE	SP	CCA		V	8/14/2053
2021 PO5166208606	KU	4	40 ACE	SP	CCA		V	8/15/2053
2021 PO5192308616	KU	2	45 ACE	SP	CRE	ED	TD	8/16/2053
2021 PO4075586658	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD	8/17/2053
2021 PO4048986092	LGE	4	40 KOP	SP	CCA		V	8/18/2053
2021 PO4049286102	F	4	40 KOP	SP	A		V	8/19/2053
2021 PO4049786105	LGE	4	30 KOP	SP	A		V	8/20/2053
2021 PO4023486092	LGE	2	60 ACE	SP	CRE	ED,ID	TD	8/21/2053
2021 PO4023686108	LGE	4	35 ACE	SP	CRE		V	8/22/2053
2021 PO5292424334	KU	6	30 UNK	SP	CCA		T	8/23/2053
2021 PO5171108736	F	5	40 ACE	SP	CRE		V	8/24/2053
2021 PO5205908363	KU	4	40 ACE	SP	CRE	ID	TD	8/25/2053
2021 PO5169708705	KU	3	45 ACE	SP	CCA		V	8/26/2053
2021 PO5179908747	KU	7	30 ACE	SP	CCA		V	8/27/2053
2021 PO5175308832	F	4	40 ACE	SP	CRE		V	8/28/2053
2021 PO5167908653	F	4	40 ACE	SP	P		V	8/29/2053
2021 PO4049386087	F	3	45 KOP	SP	P		V	8/30/2053
2021 PO4051786139	F	4	40 KOP	SP	A		V	8/31/2053
2021 PO5325024274	KU	6	30 UNK	SP	CRE		B	9/1/2053
2021 PO5326024392	KU	6	30 UNK	SP	CRE		B	9/2/2053
2021 PO5324624175	KU	6	30 UNK	UN	S		V	9/3/2053
2021 A	KU	3	45 UNK	SP	CRE		B	9/4/2053
2021 PO4052286149	F	4	40 KOP	SP	A		V	9/5/2053

2021 PO4050986163	F	4	40 KOP	SP	A		V	9/6/2053
2021 PO4050186168	F	3	45 KOP	SP	CCA		V	9/7/2053
2021 PO4050286178	F	4	35 KOP	SP	A		V	9/8/2053
2021 PO4024786105	LGE	2	60 ACE	SP	P	ED,ID	BD	9/9/2053
2021 PO4080385895	F	4	40 ACE	SP	CRE		V	9/10/2053
2021 PO4081585894	F	4	40 ACE	SP	CRE		V	9/11/2053
2021 PO4082885893	F	4	40 ACE	SP	CRE		V	9/12/2053
2021 PO4084185892	F	4	30 ACE	SP	CRE		V	9/13/2053
2021 PO4084185902	LGE	4	35 ACE	SP	CRE		V	9/14/2053
2021 PO4083585903	F	7	25 ACE	SP	CRE		V	9/15/2053
2021 PO4084285915	F	4	40 ACE	SP	CRE		V	9/16/2053
2021 PO4083685929	F	6	35 ACE	SP	CRE		V	9/17/2053
2021 PO4052786165	F	5	40 KOP	SP	P		V	9/18/2053
2021 PO4025286110	LGE	2	55 ACE	SP	P	ED,ID,IP	BD	9/19/2053
2021 PO5323023982	KU	6	30 UNK	SP	CRE		B	9/20/2053
2021 PO5321923845	KU	6	30 UNK	SP	CRE		B	9/21/2053
2021 PO4052786183	F	4	40 KOP	SP	A		V	9/22/2053
2021 PO4052886198	F	3	45 KOP	SP	CCA		V	9/23/2053
2021 PO4048085977	F	4	40 KOP	SP	A		V	9/24/2053
2021 PO4078786627	LGE	4	45 ACE	SP	CRE	ED,ID	TD	9/25/2053
2021 PO4079186654	LGE	3	50 ACE	SP	CCA		V	9/26/2053
2021 PO4079586653	F	UNK	45 ACE	SP	CRE		V	9/27/2053
2021 PO4080286661	F	4	40 ACE	SP	CCA		V	9/28/2053
2021 PO4080186667	LGE	3	45 ACE	SP	CCA		V	9/29/2053
2021 PO4081086670	F	4	35 ACE	SP	CCA		V	9/30/2053
2021 PO4080786675	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD	10/1/2053
2021 PO4081986688	LGE	4	40 ACE	SP	CRE	ED,ID	BD	10/2/2053
2021 PO4025386123	LGE	4	35 ACE	SP	P	ED,ID	TD	10/3/2053
2021 PO5321223727	KU	6	30 UNK	SP	CRE		B	10/4/2053
2021 PO5321023661	KU	4	40 UNK	SP	CRE		B	10/5/2053
2021 PO5284923901	KU	6	30 UNK	SP	CRE		B	10/6/2053
2021 PO5287223798	KU	6	30 UNK	SP	CRE		B	10/7/2053
2021 PO5289223690	KU	6	30 UNK	SP	CRE		T	10/8/2053
2021 PO5305823587	KU	6	30 UNK	SP	CRE		BD	10/9/2053
2021 PO5292723590	KU	6	30 UNK	SP	CRE		B	10/10/2053
2021 PO5276923598	KU	6	30 UNK	SP	CRE		B	10/11/2053
2021 PO5263123604	KU	6	30 UNK	SP	CRE		B	10/12/2053
2021 PO5258123689	KU	6	30 UNK	SP	CRE		B	10/13/2053
2021 PO5258623795	KU	2	30 UNK	SP	CRE		B	10/14/2053
2021 PO5259023905	KU	6	30 UNK	SP	CRE		B	10/15/2053
2021 PO5259024015	KU	6	30 UNK	SP	CRE		B	10/16/2053
2021 PO5260724370	KU	6	30 UNK	SP	CRE		B	10/17/2053
2021 PO5259624198	KU	6	30 UNK	SP	CRE		B	10/18/2053
2021 PO4048285981	F	4	40 KOP	SP	A		V	10/19/2053
2021 PO5316823583	KU	6	30 UNK	SP	CCA		B	10/20/2053
2021 PO4025786115a	KU	2	55 ACE	SP	P	ED,ID	BD	10/21/2053
2021 PO4025786115	LGE	2	55 ACE	SP	P	ED,ID	TD	10/22/2053
2021 PO4048585991	F	3	45 KOP	SP	CCA		V	10/23/2053
2021 PO4048786003	F	4	40 KOP	SP	P		V	10/24/2053
2021 PO5212108540	KU	3	45 ACE	SP	CCA		V	10/25/2053
2021 PO5213008384	F	7	30 ACE	SP	CCA		V	10/26/2053
2021 PO5210308311	F	7	30 ACE	SP	CCA		V	10/27/2053
2021 PO5208408241	F	7	30 ACE	SP	CRE		V	10/28/2053
2021 PO5012511598	KU	4	45 KOP	SP	CRE	ED,ID	TD	10/29/2053

2021 PO4993211773	KU	4	40 KOP	SP	CRE	ED,ID	TD	10/30/2053
2021 PO5009111608	KU	4	45 KOP	SP	CRE	ED,ID	TD	10/31/2053
2021 PO5004411619	KU	4	45 KOP	SP	CRE	ED,ID	TD	11/1/2053
2021 PO4990311651	KU	4	40 KOP	SP	CRE	ED,ID,IP	TD	11/2/2053
2021 PO4088385928	F	4	40 ACE	SP	CRE		V	11/3/2053
2021 PO4087085929	F	4	40 ACE	SP	CRE		V	11/4/2053
2021 PO4085885930	F	4	40 ACE	SP	CRE		V	11/5/2053
2021 PO4084385931	F	4	40 ACE	SP	A		V	11/6/2053
2021 PO4084485941	F	4	40 ACE	SP	P		V	11/7/2053
2021 PO4084585956	F	4	30 ACE	SP	A		V	11/8/2053
2021 PO4083885955	F	4	30 ACE	SP	P		V	11/9/2053
2021 PO4101085827	LGE	4	30 ACE	SP	CRE		V	11/10/2053
2021 PO4099885828	F	4	40 ACE	SP	CRE		V	11/11/2053
2021 PO4099385835	F	4	30 ACE	SP	A		V	11/12/2053
2021 PO4098785832	F	4	40 ACE	SP	P		V	11/13/2053
2021 PO4098085840	F	4	40 ACE	SP	CRE		V	11/14/2053
2021 PO4098185853	F	4	40 ACE	SP	CRE		V	11/15/2053
2021 PO4098285865	F	4	40 ACE	SP	CRE		V	11/16/2053
2021 PO4049186024	F	4	40 KOP	SP	A		V	11/17/2053
2021 PO4135185971	LGE	4	30 BRO	SP	CRE	ED,EP,RB	X	RP1 11/18/2053
2021 PO5213908461	F	7	30 ACE	SP	CCA		V	11/19/2053
2021 PO5286823944	KU	6	30 UNK	SP	CRE		B	11/20/2053
2021 PO4048986016	F	4	40 KOP	SP	A		V	11/21/2053
2021 PO4026986125	LGE	2	50 ACE	SP	CRE	ED,ID,IP,MD	TD	11/22/2053
2021 PO5202908410	KU	6	40 ACE	SP	CRE	ID	BD	11/23/2053
2021 PO4135985999	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/24/2053
2021 PO4134785990	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/25/2053
2021 PO4046686567	LGE	4	40 ACE	SP	CRE	ED,ID	TD	11/26/2053
2021 PO4046886572	LGE	4	35 ACE	SP	CRE	ED,ID	TD	11/27/2053
2021 PO4046186577	LGE	4	35 ACE	SP	CRE	ED,ID	TD	11/28/2053
2021 PO4007685898	LGE	4	35 ACE	SP	P	ED,HH,ID,RB	BX	RP1 11/29/2053
2021 PO4078186642	LGE	4	40 ACE	SP	CRE	ED,ID	TD	11/30/2053
2021 PO4078486646	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD	12/1/2053
2021 PO4078086648	LGE	4	45 ACE	SP	CRE	ED,ID	TD	12/2/2053
2021 PO4077386643	LGE	4	35 ACE	SP	CRE	ED,ID	TD	12/3/2053
2021 PO4162386051	F	4	35 BRO	SP	CRE		V	12/4/2053
2021 PO4162186052	F	4	40 BRO	SP	A		V	12/5/2053
2021 PO4162086055	LGE	4	30 BRO	SP	CCA		V	12/6/2053
2021 PO4160986052	F	4	35 BRO	SP	CRE		V	12/7/2053
2021 PO4021686077	LGE	3	50 ACE	SP	CRE	ED,ID	TD	12/8/2053
2021 PO4020886084	LGE	4	40 ACE	SP	P	ED,ID	BD	12/9/2053
2021 PO4159886053	F	4	40 BRO	SP	CRE		V	12/10/2053
2021 PO4157286054	F	4	40 BRO	SP	A		V	12/11/2053
2021 PO4156186055	F	4	40 BRO	SP	CRE		V	12/12/2053
2021 PO4155086055	F	4	40 BRO	SP	CCA		V	12/13/2053
2021 PO4153586056	F	4	40 BRO	SP	A		V	12/14/2053
2021 PO4152186057	F	4	40 BRO	SP	CRE		V	12/15/2053
2021 PO4150786068	LGE	3	50 BRO	SP	A	ED,ID,IP	TD	12/16/2053
2021 PO4047186142	LGE	4	35 KOP	SP	P	ED,ID,IP	TD	12/17/2053
2021 PO5019412804	KU	6	30 KOP	SP	CRE	ED,ID	TD	12/18/2053
2021 PO4985811753	KU	6	30 KOP	SP	CRE	ED,ID	TD	12/19/2053
2021 PO5024412791	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/20/2053
2021 PO5028112886	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/21/2053
2021 PO5031912982	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/22/2053

2021 PO4992211933	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/23/2053
2021 PO5018312600	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/24/2053
2021 PO5026612994	KU	4	45 KOP	SP	CRE	ED,ID	TD	12/25/2053
2021 PO4046886121	F	3	45 KOP	SP	A		V	12/26/2053
2021 PO4078786643	F	4	40 ACE	SP	CRE	ED,ID,RB	BX	12/27/2053
2021 PO4078686642	LGE	5	25 ACE	SP	CRE	ED,ID	TD	12/28/2053
2021 PO4077886632	F	4	40 ACE	SP	CRE		V	12/29/2053
2021 PO4077586634	LGE	3	45 ACE	SP	CCA		V	12/30/2053
2021 PO5145508963	KU	7	30 ACE	SP	CRE	ED	TD	12/31/2053
2021 PO5271422565	KU	4	40 UNK	SP	CRE		B	1/1/2054
2021 PO5282422498	KU	5	35 UNK	SP	CRE		B	1/2/2054
2021 PO5295422418	KU	4	40 UNK	SP	CRE		B	1/3/2054
2021 PO5308022343	KU	4	40 UNK	SP	CRE		T	1/4/2054
2021 PO5037013118	KU	4	40 KOP	SP	CRE	ED,ID	TD	1/5/2054
2021 PO5041613239	KU	4	40 KOP	SP	CRE	ED,ID	TD	1/6/2054
2021 PO5021213362	KU	4	45 KOP	SP	CRE	ED,ID	TD	1/7/2054
2021 PO5037513225	KU	6	30 KOP	SP	CRE	ED,ID	TD	1/8/2054
2021 PO5024013387	KU	3	50 KOP	SP	CRE	ED,ID	TD	1/9/2054
2021 PO4041386185	LGE	3	50 KOP	SP	P	ED,ID,MD,RB	TD	1/10/2054
2021 PO3996285783	LGE	4	40 ACE	SP	P	ED,ID	BD	1/11/2054
2021 PO3995885787	LGE	4	30 ACE	SP	CCA		V	1/12/2054
2021 PO3995885806	F	3	45 ACE	SP	CCA		V	1/13/2054
2021 PO4091085720	F	4	30 ACE	SP	CCA		V	1/14/2054
2021 PO4059685939	F	4	40 ACE	SP	CRE		V	1/15/2054
2021 PO4059785952	F	4	40 ACE	SP	CRE		V	1/16/2054
2021 PO4059885967	F	4	45 ACE	SP	CRE		V	1/17/2054
2021 PO4065886513	LGE	4	40 ACE	SP	CRE	ED,ID	TX	1/18/2054
2021 PO4041086158	F	4	40 KOP	SP	P		V	1/19/2054
2021 PO4066186498	LGE	3	50 ACE	SP	CRE	ED,ID	TD	1/20/2054
2021 PO4065286504	LGE	4	35 ACE	SP	CRE	ED,ID	TD	1/21/2054
2021 PO4066986507	LGE	4	40 ACE	SP	CRE	ED,ID	TD	1/22/2054
2021 PO4067286510	LGE	4	40 ACE	SP	CRE	ED,ID	TD	1/23/2054
2021 PO3997285797	F	4	40 ACE	SP	P		V	1/24/2054
2021 PO3998285790	F	4	40 ACE	SP	CRE		V	1/25/2054
2021 PO4042186152	F	4	45 KOP	SP	CCA		V	1/26/2054
2021 PO4043186145	F	4	40 KOP	SP	CCA		V	1/27/2054
2021 PO4044286138	F	4	40 KOP	SP	P		V	1/28/2054
2021 PO4000285776	F	4	40 ACE	SP	CRE		V	1/29/2054
2021 PO3999285783	F	4	40 ACE	SP	CRE		V	1/30/2054
2021 PO4046986127	LGE	5	25 KOP	SP	A	ED,ID,IP	TD	1/31/2054
2021 PO4090785729	F	4	40 ACE	SP	CRE		V	2/1/2054
2021 PO4091585737	F	4	40 ACE	SP	CRE		V	2/2/2054
2021 PO4092285744	F	4	40 ACE	SP	CRE		V	2/3/2054
2021 PO4092985751	F	4	40 ACE	SP	CRE		V	2/4/2054
2021 PO4094485764	F	4	40 ACE	SP	CRE		V	2/5/2054
2021 PO4015786034	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	2/6/2054
2021 PO4181286037	LGE	2	55 BRO	SP	A	ED,ID	TD	2/7/2054
2021 PO4001285769	F	4	40 ACE	SP	CRE		V	2/8/2054
2021 PO4002285763	F	4	40 ACE	SP	CRE		V	2/9/2054
2021 PO4003185756	F	4	40 ACE	SP	CCA		V	2/10/2054
2021 PO5135808273	KU	5	40 ACE	SP	CCA		V	2/11/2054
2021 PO5158708178	KU	3	40 ACE	SP	CCA		V	2/12/2054
2021 PO5188808503	KU	6	30 ACE	SP	CCA		V	2/13/2054
2021 PO4045686130	F	5	40 KOP	SP	P		V	2/14/2054

2021	PO4134685976	LGE	4	40 BRO	SP	CRE		V	2/15/2054
2021	PO4135885978	LGE	5	25 BRO	SP	CRE		V	2/16/2054
2021	PO4016486025a	KU	4	35 ACE	SP	P	ED,ID	TD	2/17/2054
2021	PO4067386504	LGE	4	30 ACE	SP	CRE	ED,ID	BD	2/18/2054
2021	PO4094485769	F	4	40 ACE	SP	CRE		V	2/19/2054
2021	PO4095885783	F	4	30 ACE	SP	P		V	2/20/2054
2021	PO4094585781	F	4	40 ACE	SP	CRE		V	2/21/2054
2021	PO4094685802	LGE	4	40 ACE	SP	CCA		V	2/22/2054
2021	PO4088685793	F	4	40 ACE	SP	CRE		V	2/23/2054
2021	PO4136986051	LGE	3	50 BRO	SP	CRE	ED,ID,JP	TD	2/24/2054
2021	PO5303422752	KU	4	40 UNK	SP	CCA		V	2/25/2054
2021	PO4088585695	F	4	40 ACE	SP	CRE		V	2/26/2054
2021	PO4089185708	F	4	35 ACE	SP	CRE		V	2/27/2054
2021	PO4088685707	F	3	45 ACE	SP	CCA		V	2/28/2054
2021	PO4088785725	F	4	40 ACE	SP	CRE		V	3/1/2054
2021	PO4089185738	F	4	40 ACE	SP	CRE		V	3/2/2054
2021	PO4088685752	F	4	30 ACE	SP	CRE		V	3/3/2054
2021	PO4089285752	F	4	40 ACE	SP	A		V	3/4/2054
2021	PO4089285768	F	4	40 ACE	SP	CRE		V	3/5/2054
2021	PO4088685786	F	4	40 ACE	SP	CRE		V	3/6/2054
2021	PO4088685771	F	4	40 ACE	SP	P		V	3/7/2054
2021	PO4086685795	LGE	4	40 ACE	SP	CCA		V	3/8/2054
2021	PO4172686047	F	4	35 BRO	SP	A		V	3/9/2054
2021	PO4174186046	F	4	35 BRO	SP	A		V	3/10/2054
2021	PO5291622553	KU	4	40 UNK	SP	CRE		B	3/11/2054
2021	PO5302422510	KU	5	35 UNK	SP	CRE		T	3/12/2054
2021	PO5312722444	KU	5	45 UNK	SP	CRE		B	3/13/2054
2021	PO4165586048	LGE	4	35 BRO	SP	A	ED,ID,JP	TD	3/14/2054
2021	PO4178686046	F	4	35 BRO	SP	CRE		V	3/15/2054
2021	PO4178286046	F	4	35 BRO	SP	CRE		V	3/16/2054
2021	PO4177286045	F	4	35 BRO	SP	CRE		V	3/17/2054
2021	PO4176186046	F	4	35 BRO	SP	A		V	3/18/2054
2021	PO4171986058	LGE	5	25 BRO	SP	A	ED,ID,JP	TD	3/19/2054
2021	PO5364534388	KU	4	40 BRO	SP	CRE	ID	BD	3/20/2054
2021	PO5349933997	KU	4	40 BRO	SP	CRE	ID	TD	3/21/2054
2021	PO4016486025	LGE	1	50 ACE	SP	CCA		V	3/22/2054
2021	PO4017486035	LGE	3	50 ACE	SP	CRE	ED,ID	TD	3/23/2054
2021	PO4167086049	F	4	35 BRO	SP	CCA		V	3/24/2054
2021	PO4167986049	F	4	35 BRO	SP	CCA		V	3/25/2054
2021	PO4168486049	F	4	40 BRO	SP	A		V	3/26/2054
2021	PO4169486048	F	4	35 BRO	SP	CCA		V	3/27/2054
2021	PO4170086048	F	4	35 BRO	SP	CCA		V	3/28/2054
2021	PO4171686047	F	4	35 BRO	SP	CCA		V	3/29/2054
2021	PO4161386047	LGE	4	35 BRO	SP	CCA		V	3/30/2054
2021	PO4074386595	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/31/2054
2021	PO4074386589	F	4	40 ACE	SP	CRE		V	4/1/2054
2021	PO4075286599	F	4	40 ACE	SP	CRE	ED,ID	V	4/2/2054
2021	PO4076186611	F	4	40 ACE	SP	CRE		V	4/3/2054
2021	PO4077086622	F	UNK	35 ACE	SP	CRE	ED,ID	V	4/4/2054
2021	PO4075686611	LGE	4	40 ACE	SP	CRE	ED,ID	TD	4/5/2054
2021	PO4090885761	F	4	40 ACE	SP	CRE		V	4/6/2054
2021	PO4090885773	F	4	40 ACE	SP	CRE		V	4/7/2054
2021	PO4090885782	F	4	40 ACE	SP	CRE		V	4/8/2054
2021	PO4088685292	F	4	30 ACE	SP	CCA		V	4/9/2054

2021 PO4088785300	LGE	4	40 ACE	SP	CCA	V	4/10/2054
2021 PO4086685302	LGE	3	45 ACE	SP	CCA	V	4/11/2054
2021 PO4001985277	LGE	3	25 BRN	SP	CCA	V	4/12/2054
2021 PO4157285794	LGE	4	35 BRO	SP	CCA	V	4/13/2054
2021 PO4008185212	F	4	30 BRN	SP	CRE	V	4/14/2054
2021 PO4007585211	F	4	40 BRN	SP	A	V	4/15/2054
2021 PO4156085757	LGE	4	35 BRO	SP	CCA	V	4/16/2054
2021 PO4156985758	F	4	35 BRO	SP	CRE	V	4/17/2054
2021 PO4918128415	F	4	40 BRN	SP	P	V	4/18/2054
2021 PO4836128771	F	4	40 BRN	SP	P	V	4/19/2054
2021 PO4819528767	F	4	40 BRN	SP	P	V	4/20/2054
2021 PO4810028763	F	4	40 BRN	SP	P	V	4/21/2054
2021 PO3632487820	F	5	35 BRN	SP	CRE	V	4/22/2054
2021 PO3688688780	KU	3	45 BRN	SP	CCA	V	4/23/2054
2021 PO4941028299	F	4	40 BRN	SP	P	V	4/24/2054
2021 PO4932128112	F	4	40 BRN	SP	S	V	4/25/2054
2021 PO4885228579	F	4	40 BRN	SP	P	V	4/26/2054
2021 PO4896028525	F	4	40 BRN	SP	CRE	V	4/27/2054
2021 PO4862728691	F	4	40 BRN	SP	CCA	V	4/28/2054
2021 PO3643688093	KU	3	45 BRN	SP	CCA	V	4/29/2054
2021 PO3640687756	KU	3	45 BRN	SP	CCA	V	4/30/2054
2021 PO3641687975	KU	3	45 BRN	SP	CCA	V	5/1/2054
2021 PO4802828743	F	4	40 BRN	SP	P	V	5/2/2054
2021 PO4789828687	F	4	40 BRN	SP	S	V	5/3/2054
2021 PO4777128643	F	4	40 BRN	SP	P	V	5/4/2054
2021 PO4771028660	F	4	40 BRN	SP	P	V	5/5/2054
2021 PO4765228680	F	4	40 BRN	SP	P	V	5/6/2054
2021 PO4686728719	F	3	40 OTH	SP	P	V	5/7/2054
2021 PO4697728717	F	3	40 OTH	SP	P	V	5/8/2054
2021 PO4705228686	F	4	40 OTH	SP	P	V	5/9/2054
2021 PO4742828783	F	4	40 BRN	SP	P	V	5/10/2054
2021 PO4753528720	F	4	40 BRN	SP	P	V	5/11/2054
2021 PO4734828874	F	4	40 BRN	SP	P	V	5/12/2054
2021 PO4676928772	F	4	40 OTH	SP	CRE	V	5/13/2054
2021 PO4669428671	F	4	40 OTH	SP	CRE	V	5/14/2054
2021 PO4677628705	F	4	40 OTH	SP	CRE	V	5/15/2054
2021 PO3659588232	KU	3	45 BRN	SP	CCA	V	5/16/2054
2021 PO3669088318	KU	3	45 BRN	SP	CCA	V	5/17/2054
2021 PO4718128413	F	3	40 OTH	SP	P	V	5/18/2054
2021 PO4713828342	F	4	40 OTH	SP	P	V	5/19/2054
2021 PO4705328309	F	3	40 OTH	SP	P	V	5/20/2054
2021 PO4714028594	F	4	40 OTH	SP	CRE	V	5/21/2054
2021 PO4684628296	F	4	40 OTH	SP	CRE	V	5/22/2054
2021 PO4674528314	F	4	40 OTH	SP	CRE	V	5/23/2054
2021 PO4664028356	F	4	40 OTH	SP	CRE	V	5/24/2054
2021 PO4722328972	F	4	40 BRN	SP	P	V	5/25/2054
2021 PO4715429011	F	4	40 BRN	SP	P	V	5/26/2054
2021 PO4699529057	F	4	40 BRN	SP	P	V	5/27/2054
2021 PO4202003361	F	4	40 BRN	SP	P	V	5/28/2054
2021 PO4197103386	F	4	40 BRN	SP	P	V	5/29/2054
2021 PO4207903521	F	4	40 BRN	SP	CCA	V	5/30/2054
2021 PO4206703639	F	4	40 BRN	SP	P	V	5/31/2054
2021 PO4664127993	F	4	40 OTH	SP	P	V	6/1/2054
2021 PO4668128121	F	4	40 OTH	SP	CRE	V	6/2/2054

2021 PO4644928092	F	4	40 OTH	SP	CRE		V			6/3/2054
2021 PO4685129072	F	4	40 BRN	SP	P		V			6/4/2054
2021 PO4671929104	F	4	40 BRN	SP	P		V			6/5/2054
2021 PO4661729141	F	4	40 BRN	SP	P		V			6/6/2054
2021 3693188794a	KU	5	30 MAR	SP	CCA		V			6/7/2054
2021 PO3910105540	F	4	40 BRN	SP	P		V			6/8/2054
2021 PO4225804081	F	4	40 BRN	SP	P		V			6/9/2054
2021 PO4220403942	F	4	40 BRN	SP	S		V			6/10/2054
2021 PO3686888563	KU	3	35 BRN	SP	CRE		V			6/11/2054
2021 PO3692288477	KU	3	45 BRN	SP	CCA		V			6/12/2054
2021 PO3686388446	KU	3	45 BRN	SP	CCA		V			6/13/2054
2021 PO3675488368	KU	3	45 BRN	SP	CCA		V			6/14/2054
2021 PO4508004092	KU	5	40 BRN	SP	CRE	ED,ID,RB	TX		RR	6/15/2054
2021 PO5016502622	KU	5	40 BRN	SP	CRE	ED,ID,RB,SRC	TX		RR	6/16/2054
2021 PO4459905374	KU	3	40 BRN	SP	CRE	ED,ID	TD			6/17/2054
2021 PO5016102671	KU	3	40 BRN	SP	CRE	ED	TD			6/18/2054
2021 PO5005802450	KU	3	45 BRN	SP	CCA	ED	TD			6/19/2054
2021 PO4894502426	KU	7	35 BRN	SP	CRE	ED,ID	TD			6/20/2054
2021 PO4838802652	KU	4	40 BRN	SP	CRE	ED,ID	TD			6/21/2054
2021 PO5014902579	KU	5	40 BRN	SP	CRE	ED,ID,MD	TD			6/22/2054
2021 PO5009102456	KU	4	45 BRN	SP	CRE	ED,ID	TD			6/23/2054
2021 PO4884202716	KU	3	45 BRN	SP	CRE	ED,ID	TD			6/24/2054
2021 PO3981700514	KU	3	45 BRN	SP	CRE	ED	TD			6/25/2054
2021 PO3986601720	KU	3	40 BRN	SP	CRE	ED,ID,IP	TD			6/26/2054
2021 PO4452905072	KU	6	35 BRN	SP	CRE	ED	TD			6/27/2054
2021 PO4078585320	LGE	3	45 ACE	SP	P	ED,ID	TD			6/28/2054
2021 PO4003985193	LGE	4	40 BRN	SP	P	ED,ID	TD			6/29/2054
2021 PO4004585179	LGE	4	40 BRN	SP	P	ED,ID,IP	TD			6/30/2054
2021 PO4005185168	LGE	4	40 BRN	SP	P	ED,ID	TD			7/1/2054
2021 PO4008385173	LGE	4	40 BRN	SP	CRE	ED,ID	TD			7/2/2054
2021 PO4084785344	LGE	4	40 ACE	SP	CRE	ED,ID	TD			7/3/2054
2021 PO4148085758	LGE	4	35 BRO	SP	A	ED,ID	TD			7/4/2054
2021 PO3997485262	LGE	4	25 BRN	SP	CRE	ED,ID,IP	TD			7/5/2054
2021 PO4150885759	LGE	4	35 BRO	SP	A	ED,ID	TD			7/6/2054
2021 PO4149385760	LGE	4	35 BRO	SP	A	ED,ID,IP	TD			7/7/2054
2021 PO4148785772	LGE	4	35 BRO	SP	A	ED,ID	TD			7/8/2054
2021 PO4007085161	LGE	4	40 BRN	SP	P	ED,ID	TD			7/9/2054
2021 PO4147285772	LGE	4	35 BRO	SP	A	ED,ID	TD			7/10/2054
2021 PO4081285292	LGE	3	45 ACE	SP	P	ED,ID	TD			7/11/2054
2021 PO3988585085	LGE	4	40 BRN	SP	P	ED,ID	TD			7/12/2054
2021 PO4150285772	LGE	4	35 BRO	SP	A	ED,ID	TD			7/13/2054
2021 PO3998085151	LGE	4	40 BRN	SP	P	ED,ID	TD			7/14/2054
2021 PO4152185759	LGE	4	35 BRO	SP	A	ED,ID	TD			7/15/2054
2021 PO4151785772	LGE	4	35 BRO	SP	A	ED,ID,IP	TD			7/16/2054
2021 PO3999585146	LGE	4	40 BRN	SP	P	ED,ID	TD			7/17/2054
2021 PO4000785143	LGE	4	40 BRN	SP	A	ED,ID	TD			7/18/2054
2021 PO4000285125	LGE	4	40 BRN	SP	A	ED,ID	TD			7/19/2054
2021 PO4001985140	LGE	4	40 BRN	SP	A	ED,ID	TD			7/20/2054
2021 PO4157985758	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD			7/21/2054
2021 PO4156985772	LGE	4	35 BRO	SP	A	ED,ID	TD			7/22/2054
2021 PO4003285286	LGE	3	55 BRN	SP	P	ED,ID	TD			7/23/2054
2021 PO4002385274	LGE	1	80 BRN	SP	CRE	ED,ID	TD			7/24/2054
2021 PO4085485303	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD			7/25/2054
2021 PO4158585811	LGE	5	25 BRO	SP	A	ED,ID	TD			7/26/2054

2021 PO4157385833	LGE	4	35 BRO	SP	A	ED,ID,IP	TD			7/27/2054
2021 PO4006385327	LGE	2	80 BRN	SP	CRE	ED,ID	TD			7/28/2054
2021 PO4083685306	LGE	4	40 ACE	SP	P	ED,ID	TD			7/29/2054
2021 PO4084185321	LGE	6	25 ACE	SP	CRE	ED,ID	TD			7/30/2054
2021 PO4084285360	LGE	4	30 ACE	SP	P	ED,ID	TD			7/31/2054
2021 PO4157885813	LGE	4	30 BRO	SP	A	ED,ID,IP	TD			8/1/2054
2021 PO4157285814	LGE	4	35 BRO	SP	A	ED,ID,IP	TD			8/2/2054
2021 PO4084485304	LGE	4	40 ACE	SP	P	ED,ID	TD			8/3/2054
2021 PO4084285305	LGE	4	30 ACE	SP	P	ED,ID	TD			8/4/2054
2021 PO3627488390	KU	4	40 BRN	SP	CRE	ID	TD			8/5/2054
2021 PO3650888297	KU	4	40 BRN	SP	CRE	ID	TD			8/6/2054
2021 PO3648888248	KU	6	30 BRN	SP	CRE	ID	TD			8/7/2054
2021 PO3555488525	KU	5	35 BRN	SP	CRE	ID	TD			8/8/2054
2021 PO3581488441	KU	6	30 BRN	SP	CRE	ID	TD			8/9/2054
2021 PO3589288433	KU	5	35 BRN	SP	CRE	ID	TD			8/10/2054
2021 PO3603688443	KU	4	40 BRN	SP	CRE	ID	TD			8/11/2054
2021 PO3671289046	KU	5	35 BRN	SP	CRE	ID	TD			8/12/2054
2021 PO3676288843	KU	4	40 BRN	SP	CRE	ID	TD			8/13/2054
2021 PO3693188794	KU	6	30 BRN	SP	CRE	ID	TD			8/14/2054
2021 PO3691488906	KU	6	30 BRN	SP	CRE	ID	TD			8/15/2054
2021 PO3688888832	KU	6	30 BRN	SP	CRE	ID	TD			8/16/2054
2021 PO5018102719	KU	7	30 BRN	SP	CCA		T			8/17/2054
2021 PO4489203840	KU	3	40 BRN	SP	CRE		T			8/18/2054
2021 PO8618369608-C	KU	4	35 BRO	SP	CCA	ED	T			8/19/2054
2021 PO8618369608	LGE	4	35 BRO	SP	CCA	ED	T			8/20/2054
2021 PO8618369608-D	KU	4	35 BRO	SP	CCA	ED	T			8/21/2054
2021 PO8618369608-A	KU	4	35 BRO	SP	CCA	ED	T			8/22/2054
2021 PO8618369608-B	KU	4	35 BRO	SP	A	ED	T			8/23/2054
2021 PO3660088961	KU	4	40 BRN	SP	CCA	ED	T			8/24/2054
2021 PO3618488408	KU	4	40 BRN	SP	CCA	ED	T			8/25/2054
2021 PO3985501441	F	3	40 BRN	SP	CRE	ED,ID,IP	BX	RP2		8/26/2054
2021 PO4229604181	F	4	40 BRN	SP	P	ID	BX	PX		8/27/2054
2021 PO3913905829	F	4	40 BRN	SP	P	ID	BX	PX		8/28/2054
2021 PO3912605693	F	4	40 BRN	SP	P	ID	BX	PX		8/29/2054
2021 PO4929228360	F	4	40 BRN	SP	P	ID	BX	PX		8/30/2054
2021 PO4951828245	F	4	40 BRN	SP	P	ID	BX	PX		8/31/2054
2021 PO4850028754	F	4	40 BRN	SP	P	ID	BX	PX		9/1/2054
2021 PO4906928471	F	4	40 BRN	SP	P	ID	BX	PX		9/2/2054
2021 PO4694328284	F	4	40 OTH	SP	P	RB	BX	RP1		9/3/2054
2021 PO4652628050	F	4	40 OTH	SP	P	ED,ID,RB	BX	PX		9/4/2054
2021 PO4655928340	F	4	40 OTH	SP	CRE	ID,IP	BX	RP2		9/5/2054
2021 PO4659528436	F	4	40 OTH	SP	P	ED,HH,ID	BX	PX		9/6/2054
2021 PO4271805944	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD	BD			9/7/2054
2021 PO4008985198	LGE	3	25 BRN	SP	CRE	ED,ID	BD			9/8/2054
2021 PO4083985360	LGE	4	40 ACE	SP	P	ED,ID,IP	BD			9/9/2054
2021 PO4006785337	LGE	4	40 BRN	SP	A	ED,ID	BD			9/10/2054
2021 PO4007485339	LGE	1	90 BRN	SP	P	ED,ID	BD			9/11/2054
2021 PO4002785289	LGE	3	25 BRN	SP	CRE	ED,ID	BD			9/12/2054
2021 PO4147285790	LGE	4	35 BRO	SP	CCA	ID,IP	BD			9/13/2054
2021 PO4001585155	LGE	4	35 BRN	SP	CCA	ED	BD			9/14/2054
2021 PO4009585155	LGE	4	40 BRN	SP	P	ED,ID	BD			9/15/2054
2021 PO4008385158	LGE	4	40 BRN	SP	CCA	ED,ID	BD			9/16/2054
2021 PO4083885344	LGE	4	40 ACE	SP	CRE	ED,ID	BD			9/17/2054
2021 PO4082985324	LGE	4	35 ACE	SP	CRE	ED,ID	BD			9/18/2054



2021 PO4082285340	LGE	4	35 ACE	SP	CRE	ED,ID	BD		9/19/2054
2021 PO4083785331	LGE	3	45 ACE	SP	CRE	ED,ID	BD		9/20/2054
2021 PO4078785319	LGE	4	40 ACE	SP	P	ED,ID	BD		9/21/2054
2021 PO4703608392	KU	7	30 BRN	SP	CRE	ED,ID,RB	X	RP1	9/22/2054
2021 PO3991785385	LGE	4	30 BRN	SP	P	ED,ID	X	RP2	9/23/2054
2021 PO3990785379	LGE	4	30 BRN	SP	P	ED,ID,RB	X	RP2	9/24/2054
2021 PO3860789485	KU	6	30 BRN	SP	CRE	HH,ID	X	RP3	9/25/2054
2021 PO8774671727-A	KU	4	35 BRO	SP	A	ED,ID,RB	VX	RP1	9/26/2054
2021 PO4719508390	F	5	40 BRN	SP	CRE	ED	V		9/27/2054
2021 PO4658608393	KU	7	35 BRN	SP	CCA		V		9/28/2054
2021 PO4010785621	LGE	4	30 BRN	SP	CCA		V		9/29/2054
2021 PO8774671727	LGE	4	35 BRO	SP	CCA		V		9/30/2054
2021 PO4163685988	F	4	35 BRO	SP	CRE		V		10/1/2054
2021 PO4163685991	F	4	40 BRO	SP	CRE		V		10/2/2054
2021 PO4163685999	F	4	40 BRO	SP	CRE		V		10/3/2054
2021 PO4163786009	LGE	3	45 BRO	SP	CCA		V		10/4/2054
2021 PO4098985443	LGE	4	40 ACE	SP	CRE		V		10/5/2054
2021 PO4034385375	LGE	4	45 BRN	SP	S		V		10/6/2054
2021 PO4033185375	LGE	4	45 BRN	SP	CCA		V		10/7/2054
2021 PO4031485375	LGE	4	40 BRN	SP	CCA		V		10/8/2054
2021 PO3994685390	F	4	40 BRN	SP	P		V		10/9/2054
2021 PO3995285401	LGE	4	40 BRN	SP	CCA		V		10/10/2054
2021 PO3995385415	LGE	4	45 BRN	SP	S		V		10/11/2054
2021 PO4092085483	LGE	1	60 ACE	SP	CCA		V		10/12/2054
2021 PO3992885372	F	4	40 BRN	SP	P		V		10/13/2054
2021 PO3993585377	F	4	40 BRN	SP	P		V		10/14/2054
2021 PO3993385383	LGE	4	35 BRN	SP	CCA		V		10/15/2054
2021 PO3994385386	F	4	40 BRN	SP	CRE		V		10/16/2054
2021 PO4160285989	LGE	4	40 BRO	SP	CCA		V		10/17/2054
2021 PO4150285744	F	4	40 BRO	SP	CRE		V		10/18/2054
2021 PO8656569195	LGE	4	35 BRO	SP	CCA		V		10/19/2054
2021 PO4151185739	F	4	40 BRO	SP	CRE		V		10/20/2054
2021 PO4154985729	F	4	40 BRO	SP	CRE		V		10/21/2054
2021 PO4155185721	F	4	40 BRO	SP	CRE		V		10/22/2054
2021 PO4154485742	F	4	40 BRO	SP	CRE		V		10/23/2054
2021 PO4153285742	F	4	40 BRO	SP	CCA		V		10/24/2054
2021 PO4152285738	F	4	40 BRO	SP	CCA		V		10/25/2054
2021 PO4007185624	LGE	4	30 BRN	SP	CCA		V		10/26/2054
2021 PO4156885738	F	4	40 BRO	SP	CCA		V		10/27/2054
2021 PO4155685741	F	4	40 BRO	SP	CCA		V		10/28/2054
2021 PO4163385976	F	4	40 BRO	SP	A		V		10/29/2054
2021 PO4160185968	F	4	35 BRO	SP	CCA		V		10/30/2054
2021 PV3992385370	LGE	4	30 BRN	SP	CCA		V		10/31/2054
2021 PO4159385992	LGE	5	25 BRO	SP	CCA		V		11/1/2054
2021 PO4096485534	LGE	4	40 ACE	SP	CCA		V		11/2/2054
2021 PO4099485541	LGE	3	45 ACE	SP	CCA		V		11/3/2054
2021 PO4160386001	F	4	40 BRO	SP	A		V		11/4/2054
2021 PO4160486013	F	4	40 BRO	SP	CRE		V		11/5/2054
2021 PO4160586020	F	4	30 BRO	SP	A		V		11/6/2054
2021 PO4160586022	F	4	30 BRO	SP	CRE		V		11/7/2054
2021 PO4013185483	LGE	4	30 BRN	SP	CCA		V		11/8/2054
2021 PO4090985451	LGE	4	30 ACE	SP	CCA		V		11/9/2054
2021 PO4092185453	LGE	3	45 ACE	SP	CCA		V		11/10/2054
2021 PO4093585451	LGE	3	45 ACE	SP	CCA		V		11/11/2054

2021 PO4094785450	LGE	4	40 ACE	SP	CCA				V	11/12/2054	
2021 PO4095785448	LGE	4	40 ACE	SP	CCA				V	11/13/2054	
2021 PO4007085486	LGE	5	25 BRN	SP	CCA				V	11/14/2054	
2021 PO4090885455	LGE	3	45 ACE	SP	CCA				V	11/15/2054	
2021 PO4006585482	LGE	4	30 BRN	SP	CCA				V	11/16/2054	
2021 PO3991318727	KU	3	45 BRO	SP	S				V	11/17/2054	
2021 PO3994118479	KU	3	45 BRO	SP	S				V	11/18/2054	
2021 PO3677734202	KU	3	45 BRO	SP	CCA				V	11/19/2054	
2021 PO5213827131	F	4	40 BRN	SP	P				V	11/20/2054	
2021 PO5194027186	F	4	40 BRN	SP	P				V	11/21/2054	
2021 PO5097227464	F	4	40 BRN	SP	P				V	11/22/2054	
2021 PO3687334234	KU	3	45 BRO	SP	CCA				V	11/23/2054	
2021 PO3703989045	F	5	35 BRN	SP	CRE				V	11/24/2054	
2021 PO3778188886	KU	4	45 BRN	SP	CCA				V	11/25/2054	
2021 PO5075027533	F	4	40 BRN	SP	CRE				V	11/26/2054	
2021 PO5054227624	F	4	40 BRN	SP	P				V	11/27/2054	
2021 PO4972628118	F	4	40 BRN	SP	CCA				V	11/28/2054	
2021 PO4962228181	F	4	40 BRN	SP	P				V	11/29/2054	
2021 PO3999120612	KU	4	40 UNK	SP	CCA				V	11/30/2054	
2021 PO3983521094	KU	3	45 BRO	SP	CCA				V	12/1/2054	
2021 PO3800589001	KU	4	40 BRN	SP	CCA				V	12/2/2054	
2021 PO4982528057	F	4	40 BRN	SP	P				V	12/3/2054	
2021 PO5004227923	F	4	40 BRN	SP	CRE				V	12/4/2054	
2021 PO3998318032	KU	3	45 BRO	SP	S				V	12/5/2054	
2021 PO3995818252	KU	3	45 BRO	SP	S				V	12/6/2054	
2021 PO4108985310	LGE	4	40 ACE	SP	P	ED,EP,ID,IP			TX	RR	12/7/2054
2021 PO4163886020	LGE	4	40 BRO	SP	CRE	ED,ID,IP			TX	RR	12/8/2054
2021 PO3989318955	KU	4	40 UNK	SP	CRE	ED,ID			TX	RR	12/9/2054
2021 PO4720808131	KU	7	35 BRN	SP	CRE	ED,ID			TD		12/10/2054
2021 PO4789601621	KU	3	40 BRN	SP	CRE	ED,ID			TD		12/11/2054
2021 PO4669508295	KU	5	40 BRN	SP	CRE	ED,ID,IP			TD		12/12/2054
2021 PO4644508113	KU	6	35 BRN	SP	CRE	ED			TD		12/13/2054
2021 PO4679108863	KU	5	40 BRN	SP	CRE	ED,ID			TD		12/14/2054
2021 PO4697108862	KU	7	30 BRN	SP	CRE	ED			TD		12/15/2054
2021 PO4682908867	KU	3	40 BRN	SP	CRE	ED,ID			TD		12/16/2054
2021 PO4609308284	KU	7	30 BRN	SP	CRE	ED,ID			TD		12/17/2054
2021 PO4314587178	LGE	2	55 BRO	SP	CRE	ED,ID,IP			TD		12/18/2054
2021 PO1783871025	KU	4	40 BRO	SP	CRE	ED,ID			TD		12/19/2054
2021 PO1793671028	KU	5	35 BRO	SP	CRE	ED,ID			TD		12/20/2054
2021 PO4315587170	LGE	3	50 BRO	SP	CRE	ED,ID,IP			TX	RR	12/21/2054
2021 PO5583306109	F	4	40 BRN	SP	CRE	ED,MD,RB			VX	RP1	12/22/2054
2021 PO2053165740	KU	4	45 BRN	SP	CRE	ED,ID			TD		12/23/2054
2021 PO2056565597	KU	6	30 BRO	SP	CRE				V		12/24/2054
2021 PO4831890891	LGE	3	45 BRN	SP	P	ED,ID			TD		12/25/2054
2021 PO4839790912	LGE	3	50 BRN	SP	CCA				V		12/26/2054
2021 PO4839890932	LGE	3	45 BRN	SP	P				V		12/27/2054
2021 PO2072065858	F	4	40 BRO	SP	CRE				V		12/28/2054
2021 PO9128297856	KU	6	30 BRN	SP	CCA				V		12/29/2054
2021 PO9157997924	F	3	45 BRO	SP	CCA				V		12/30/2054
2021 PO9145698047	KU	6	30 KOP	SP	CCA				V		12/31/2054
2021 PO9109397492	F	3	45 BRN	SP	CRE				V		1/1/2055
2021 PO9197198273	F	2	45 BRO	SP	P				V		1/2/2055
2021 PO9147597822	F	4	40 KOP	SP	CRE				V		1/3/2055
2021 PO9072297395	KU	6	30 BRN	SP	CCA				V		1/4/2055

2021 PO9177398123	F	3	45 BRO	SP	CCA			V		1/5/2055
2021 PO9103797492	KU	5	35 BRN	SP	CCA			V		1/6/2055
2021 PO9168998037	F	4	40 BRO	SP	CRE			V		1/7/2055
2021 PO9212198261	F	4	40 KOP	SP	P			V		1/8/2055
2021 PO9193098347	F	2	35 KOP	SP	P			V		1/9/2055
2021 PO9186098202	F	3	45 BRO	SP	CCA			V		1/10/2055
2021 PO9130697677	F	4	40 KOP	SP	CRE		ED,EP,HH,ID,RB	BX	PX	1/11/2055
2021 PO9119997583	F	4	40 KOP	SP	P		ED,EP,ID	BX	RP2	1/12/2055
2021 PO9139097748	F	4	40 KOP	SP	CRE			V		1/13/2055
2021 PO9087497296	F	4	40 BRN	SP	CRE			V		1/14/2055
2021 PO9100797419	F	2	45 SWP	SP	P			V		1/15/2055
2021 PO5376528998	KU	6	35 UNK	SP	CCA			V		1/16/2055
2021 PO5369129003	KU	6	35 UNK	SP	CCA			V		1/17/2055
2021 PO3996083341	LGE	4	35 BRO	SP	CRE		ED,ID,IP,RB	X	RP1	1/18/2055
2021 PO4097085895	LGE	4	40 ACE	SP	A		ED,HH,ID	TD		1/19/2055
2021 PO7679766858	KU	3	45 ACE	SP	CCA			V		1/20/2055
2021 PO8069270919	LGE	4	35 ACE	SP	CCA			V		1/21/2055
2021 PO4093985916	LGE	4	35 ACE	SP	CRE		ED,HH,ID	BD		1/22/2055
2021 PO4095285910	LGE	4	35 ACE	SP	CRE		ED,ID	BD		1/23/2055
2021 PO2221692348	KU	3	45 BRN	SP	CRE		ED,SRS	TD		1/24/2055
2021 PO2191393269	KU	5	40 KOP	SP	CCA			T		1/25/2055
2021 PO3999183339	F	4	40 BRO	SP	CRE			V		1/26/2055
2021 PO4000583324	F	4	40 BRO	SP	CRE			V		1/27/2055
2021 PO4096885908	LGE	4	40 ACE	SP	P		ED,ID,IP	BD		1/28/2055
2021 PO4096985919	LGE	4	35 ACE	SP	P		ED,HH,ID,RB	X	PX	1/29/2055
2021 PO4094785946	LGE	4	35 ACE	SP	CRE		ED,ID,IP	BD		1/30/2055
2021 PO4096085939	LGE	4	35 ACE	SP	CRE		ED,ID,IP	BD		1/31/2055
2021 PO4000683338	F	4	40 BRO	SP	CRE			V		2/1/2055
2021 PO4001183343	F	4	30 BRO	SP	CRE			V		2/2/2055
2021 PO4002083337	F	4	40 BRO	SP	A			V		2/3/2055
2021 PO4003683343	F	4	30 BRO	SP	A			V		2/4/2055
2021 PO4003383337	F	4	40 BRO	SP	CRE			V		2/5/2055
2021 PO4004483342	F	4	40 BRO	SP	CRE			V		2/6/2055
2021 PO2236192172	KU	3	45 BRN	SP	CCA			V		2/7/2055
2021 PO4005483342	KU	4	40 BRO	SP	CRE			V		2/8/2055
2021 PO2203992741	KU	3	45 BRN	SP	CRE		ED,ID,IP	TD		2/9/2055
2021 PO2213792503	KU	5	40 BRN	SP	CCA			V		2/10/2055
2021 PO4006083371	F	4	40 BRO	SP	CRE			V		2/11/2055
2021 PO4007083385	F	4	40 BRO	SP	CRE		HH,RB	VX	RP1	2/12/2055
2021 PO4007883390	F	4	40 BRO	SP	CRE			V		2/13/2055
2021 PO4008883404	F	4	40 BRO	SP	CRE			V		2/14/2055
2021 PO4009683418	F	4	40 BRO	SP	A			V		2/15/2055
2021 PO4008783435	F	4	40 BRO	SP	CRE			V		2/16/2055
2021 PO4010183412	F	4	35 BRO	SP	CRE			V		2/17/2055
2021 PO4010883417	F	4	40 BRO	SP	CRE			V		2/18/2055
2021 PO2200692842	KU	5	40 BRN	SP	CRE		ED,SRS	TD		2/19/2055
2021 PO4089385947	LGE	3	50 ACE	SP	CCA			V		2/20/2055
2021 PO5514129164	KU	6	30 UNK	SP	CRE			B		2/21/2055
2021 PO5516629334	KU	6	35 UNK	SP	CRE			T		2/22/2055
2021 PO4015383423	F	4	30 BRO	SP	CRE			V		2/23/2055
2021 PO4015883457	LGE	3	45 BRO	SP	CRE		ED,ID	TD		2/24/2055
2021 PO2197093017	KU	5	40 BRN	SP	CRE			T		2/25/2055
2021 PO4015783471	LGE	4	35 BRO	SP	CRE		ED,ID,IP	TD		2/26/2055
2021 PO4016883435	LGE	4	30 BRO	SP	A		ED,ID	TD		2/27/2055

2021 PO4090785946	LGE	4	35 ACE	SP	CRE		V	2/28/2055
2021 PO4089785952	LGE	4	35 ACE	SP	CCA		V	3/1/2055
2021 PO4015683426	F	4	40 BRO	SP	CRE		V	3/2/2055
2021 PO4016583415	F	4	40 BRO	SP	A		V	3/3/2055
2021 PO7340746117	LGE	4	30 BRO	SP	CCA		V	3/4/2055
2021 PO4089385964	LGE	3	45 ACE	SP	A	ED,ID,IP	BD	3/5/2055
2021 PO4066486059	LGE	4	35 ACE	SP	CCA		V	3/6/2055
2021 PO4067286072	LGE	4	35 ACE	SP	CCA		V	3/7/2055
2021 PO2623082296	KU	4	45 KOP	SP	CRE	ED,ID	TD	3/8/2055
2021 PO2606882179	KU	6	30 KOP	SP	S		V	3/9/2055
2021 PO2613282343	KU	6	30 KOP	SP	S		V	3/10/2055
2021 PO4068586070	LGE	4	35 ACE	SP	P	ED,ID,IP	TD	3/11/2055
2021 PO5467826122	KU	3	45 UNK	SP	CCA		V	3/12/2055
2021 PO4095185978	F	4	40 ACE	SP	A		V	3/13/2055
2021 PO4097585976	F	4	40 ACE	SP	CRE		V	3/14/2055
2021 PO9094995767	KU	5	35 ACW	SP	CCA		V	3/15/2055
2021 PO9086695787	F	4	40 ACW	SP	P	ED	V	3/16/2055
2021 PO5349389015	KU	4	40 BRN	SP	CRE	ID	TD	3/17/2055
2021 PO5202489402	KU	6	30 BRN	SP	CCA		V	3/18/2055
2021 PO5231289532	KU	3	50 BRN	SP	CCA		V	3/19/2055
2021 PO5227789676	KU	4	45 BRN	SP	CCA		V	3/20/2055
2021 PO3079281876	KU	4	40 KOP	SP	CRE	ED,ID	TD	3/21/2055
2021 PO3049682024	KU	4	40 KOP	SP	CRE	ED,ID	TD	3/22/2055
2021 PO3071382012	KU	4	40 KOP	SP	CRE	ED,ID,IP	TX	RR 3/23/2055
2021 PO1794090442	KU	6	35 BRN	SP	CCA		V	3/24/2055
2021 PO1827890652	KU	3	45 BRN	SP	CCA		V	3/25/2055
2021 PO1787090518	KU	5	45 BRN	SP	CCA		V	3/26/2055
2021 PO2753994428	KU	3	45 KOP	SP	CCA		V	3/27/2055
2021 PO1589096957	KU	3	45 KOP	SP	CRE	ED,ID	TD	3/28/2055
2021 PO5506227293	KU	3	40 UNK	SP	CCA		V	3/29/2055
2021 PO4011783474	LGE	4	30 BRO	SP	A	ED,ID	TD	3/30/2055
2021 PO4011583485	F	3	45 BRO	SP	A		V	3/31/2055
2021 PO5541127310	KU	4	40 UNK	SP	CRE		B	4/1/2055
2021 PO5525927300	KU	4	40 UNK	SP	CRE		B	4/2/2055
2021 PO5526727210	KU	4	40 UNK	SP	CRE		B	4/3/2055
2021 PO5527327145	KU	4	40 UNK	SP	CRE		B	4/4/2055
2021 PO4011683431	F	4	30 BRO	SP	CCA		V	4/5/2055
2021 PO4012983439	F	4	30 BRO	SP	CRE		V	4/6/2055
2021 PO4013083430	F	4	40 BRO	SP	CRE		V	4/7/2055
2021 PO7752967837	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	4/8/2055
2021 PO4012283425	F	4	40 BRO	SP	CRE		V	4/9/2055
2021 PO4012783416	F	4	40 BRO	SP	CRE		V	4/10/2055
2021 PO4012983405	F	4	40 BRO	SP	CRE		V	4/11/2055
2021 PO5601526703	KU	4	40 UNK	SP	CRE		T	4/12/2055
2021 PO5613826746	KU	5	35 UNK	SP	CCA		V	4/13/2055
2021 PO4012383394	F	4	40 BRO	SP	CRE		V	4/14/2055
2021 PO4011083383	F	4	30 BRO	SP	CRE		V	4/15/2055
2021 PO4011483383	F	4	40 BRO	SP	CRE		V	4/16/2055
2021 PO4010483369	F	4	40 BRO	SP	CRE		V	4/17/2055
2021 PO4009783358	F	4	40 BRO	SP	CRE		V	4/18/2055
2021 PO4008883345	F	4	40 BRO	SP	CRE		V	4/19/2055
2021 PO3993183315	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	4/20/2055
2021 PO3993883310	LGE	4	40 BRO	SP	A		V	4/21/2055
2021 PO7727367769	KU	4	40 ACE	SP	CRE	ED,ID	TD	4/22/2055

2021 PO7701767702	KU	4	40 ACE	SP	CRE		ED,ID	BD		4/23/2055
2021 PO5616326635	KU	4	40 UNK	SP	CRE			B		4/24/2055
2021 PO7690467666	KU	4	40 ACE	SP	CRE		ED,ID	TD		4/25/2055
2021 PO7668967611	KU	4	45 ACE	SP	CRE		ED,ID	TD		4/26/2055
2021 PO7692266777	KU	4	40 ACE	SP	CCA			V		4/27/2055
2021 PO5617226618	KU	4	40 UNK	SP	CRE			T		4/28/2055
2021 PO3994783309	LGE	4	40 BRO	SP	A			V		4/29/2055
2021 PO3991883311	F	3	45 BRO	SP	CCA			V		4/30/2055
2021 PO5603526622	KU	4	40 UNK	SP	CRE			T		5/1/2055
2021 PO5603726590	KU	4	40 UNK	ST	CCA			V		5/2/2055
2021 PO3996283308	F	4	40 BRO	SP	A			V		5/3/2055
2021 PO3998083307	F	4	40 BRO	SP	A			V		5/4/2055
2021 PO3999483306	F	4	40 BRO	SP	CRE			V		5/5/2055
2021 PO4000983305	F	4	40 BRO	SP	CRE			V		5/6/2055
2021 PO4002583304	F	4	40 BRO	SP	CRE			V		5/7/2055
2021 PO4004083303	F	4	40 BRO	SP	CRE			V		5/8/2055
2021 PO4005283302	F	4	40 BRO	SP	CRE			V		5/9/2055
2021 PO7665667088	KU	2	55 ACE	SP	CRE		ED,ID	TD		5/10/2055
2021 PO4006083313	LGE	4	30 BRO	SP	A		ED,ID,IP	TD		5/11/2055
2021 PO4007183320	F	4	40 BRO	SP	CRE			V		5/12/2055
2021 PO4006383309	F	4	40 BRO	SP	CRE			V		5/13/2055
2021 PO4008083333	F	4	40 BRO	SP	CRE			V		5/14/2055
2021 PO7658267321	KU	2	55 ACE	SP	CRE		ED,ID	TD		5/15/2055
2021 PO7650567554	KU	2	55 ACE	SP	CRE		ED,ID	BD		5/16/2055
2021 PO7627467353	KU	4	40 ACE	SP	CCA			V		5/17/2055
2021 PO8272566842	KU	1	30 ACE	ST	CRE			V		5/18/2055
2021 PO4013483458	F	4	40 BRO	SP	A			V		5/19/2055
2021 PO4014183448	F	4	40 BRO	SP	A			V		5/20/2055
2021 PO4014883439	F	4	40 BRO	SP	CRE			V		5/21/2055
2021 PO4012783459	LGE	4	30 BRO	SP	A		ED,ID	TD		5/22/2055
2021 PO9051295845	F	4	40 UNK	SP	CRE		ED	V		5/23/2055
2021 PO9068095817	F	6	40 ACW	SP	CRE		ED	V		5/24/2055
2021 PO9077495803	F	4	40 ACW	SP	CRE		ED	V		5/25/2055
2021 PO8931996375	KU	5	40 ACW	SP	CRE		ED,ID,IP	TD		5/26/2055
2021 PO8983496106	KU	6	30 ACW	SP	CRE		ED,ID,IP	TD		5/27/2055
2021 PO5534929906	KU	6	30 UNK	SP	CRE			B		5/28/2055
2021 PO4068986058	LGE	4	35 ACE	SP	P		ID	TD		5/29/2055
2021 PO4068386048	LGE	3	45 ACE	SP	CCA			V		5/30/2055
2021 PO4076785987	F	4	40 ACE	SP	CRE		ED,HH,ID,RB	VX	PX	5/31/2055
2021 PO4078085986	F	3	45 ACE	SP	CCA			V		6/1/2055
2021 PO4078885985	F	4	40 ACE	SP	CRE			V		6/2/2055
2021 PO2626583009	KU	4	40 KOP	SP	CRE		ED,ID	TD		6/3/2055
2021 PO2603182633	KU	6	30 KOP	SP	CRE		ED,ID	TD		6/4/2055
2021 PO2599882450	KU	4	40 KOP	SP	CRE		ED,ID	TD		6/5/2055
2021 PO2596982578	KU	5	35 KOP	SP	S			V		6/6/2055
2021 PO2581782193	KU	4	40 KOP	SP	CRE		ED,ID	TD		6/7/2055
2021 PO2593582306	KU	4	40 KOP	SP	CRE		ED,ID	TD		6/8/2055
2021 PO2615582576	KU	4	40 KOP	SP	CRE		ED,ID	BD		6/9/2055
2021 PO2596982879	KU	5	35 KOP	SP	CRE		ED,ID	TD		6/10/2055
2021 PO2613782951	KU	6	30 KOP	SP	S			V		6/11/2055
2021 PO4069886014	LGE	4	35 ACE	SP	CRE		ED,HH,ID,RB	BX	PX	6/12/2055
2021 PO4069786003	LGE	4	40 ACE	WC	CRE		ED,ID,RB	VX	PX	6/13/2055
2021 PO4069786043	LGE	4	40 ACE	SP	CRE		ED,HH,ID	TD		6/14/2055
2021 PO4070186043	LGE	4	40 ACE	SP	CRE		ID	TD		6/15/2055

2021 PO9045296204	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	6/16/2055
2021 PO9052296196	KU	4	40 BRO	SP	CRE	ED,ID	BD	6/17/2055
2021 PO9049596158	KU	4	40 BRO	SP	CRE	ED,ID	BD	6/18/2055
2021 PO9046396112	F	2	40 BRO	SP	CRE		V	6/19/2055
2021 PO9054796059	F	4	40 BRO	SP	P		V	6/20/2055
2021 PO9057595881	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	6/21/2055
2021 PO9036795980	KU	4	40 BRO	SP	CRE	ID	BD	6/22/2055
2021 PO9042595858	F	4	40 BRO	SP	CRE		V	6/23/2055
2021 PO9028795864	F	3	40 BRO	SP	CRE	ED	V	6/24/2055
2021 PO8991996097	KU	6	30 BRO	SP	CRE	ED,ID	TD	6/25/2055
2021 PO9001496046	F	4	40 BRO	SP	CRE	ED	V	6/26/2055
2021 PO9005096090	KU	5	30 BRO	SP	CCA		V	6/27/2055
2021 PO8997896094	KU	3	45 BRO	SP	CCA		V	6/28/2055
2021 PO8996296073	KU	5	35 BRO	SP	CRE		V	6/29/2055
2021 PO9006396265	KU	6	30 BRO	SP	CRE		V	6/30/2055
2021 PO9015295777	F	4	40 BRO	SP	CRE		V	7/1/2055
2021 PO9011795904	KU	7	30 BRO	SP	CRE	ED,ID	TD	7/2/2055
2021 PO5523427570	KU	4	40 UNK	SP	CCA		V	7/3/2055
2021 PO5524827424	KU	4	40 UNK	SP	CRE		B	7/4/2055
2021 PO4012683469	F	3	45 BRO	SP	CCA		V	7/5/2055
2021 PO5515427297	KU	4	40 UNK	SP	CRE		B	7/6/2055
2021 PO3187980435	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/7/2055
2021 PO3181780771	KU	4	45 BRO	SP	CRE	ED,ID	TD	7/8/2055
2021 PO3148980987	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/9/2055
2021 PO3165581044	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/10/2055
2021 PO3149181153	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/11/2055
2021 PO3175980859	KU	5	35 BRO	DF	CRE	ED,ID	TD	7/12/2055
2021 PO3169680959	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/13/2055
2021 PO3155781170	KU	4	45 BRO	SP	CRE	ED,ID	TD	7/14/2055
2021 PO9069396208	KU	4	40 BRN	SP	CRE	ID	TD	7/15/2055
2021 PO9088696270	KU	3	50 BRN	SP	CRE	ID	TD	7/16/2055
2021 PO9080596145	KU	4	45 BRN	SP	CRE	ID	TD	7/17/2055
2021 PO9062096122	KU	6	30 BRN	SP	CRE	ID	TD	7/18/2055
2021 PO9067696058	KU	4	40 BRN	SP	CRE	ID,IP	TD	7/19/2055
2021 PO3060982402	F	4	40 KOP	SP	P	ED	V	7/20/2055
2021 PO3080482399	KU	6	30 BRO	SP	S		V	7/21/2055
2021 PO5443925389	KU	5	35 UNK	SP	CRE		B	7/22/2055
2021 PO5430825380	KU	4	40 UNK	SP	CRE		B	7/23/2055
2021 PO5421525373	KU	5	35 UNK	SP	CRE		B	7/24/2055
2021 PO5409525392	KU	6	30 UNK	SP	CCA		V	7/25/2055
2021 PO5420425650	KU	5	35 UNK	SP	CRE		T	7/26/2055
2021 PO5410825570	KU	6	30 UNK	SP	CCA		V	7/27/2055
2021 PO5466625617	KU	4	40 UNK	SP	CRE		B	7/28/2055
2021 PO5450125588	KU	6	30 UNK	SP	CCA		B	7/29/2055
2021 PO5435825659	KU	4	40 UNK	SP	CRE		B	7/30/2055
2021 PO5333788891	KU	4	40 BRN	SP	CRE	ID	TD	7/31/2055
2021 PO5451125669	KU	4	40 UNK	SP	CRE		B	8/1/2055
2021 PO5458125611	F	4	40 UNK	SP	CRE		B	8/2/2055
2021 PO5471925621	F	4	40 UNK	SP	CCA		V	8/3/2055
2021 PO5512626963	KU	6	30 UNK	SP	CRE		B	8/4/2055
2021 PO5518826966	KU	4	40 UNK	SP	CRE		B	8/5/2055
2021 PO5528826969	KU	4	40 UNK	SP	CRE		B	8/6/2055
2021 PO5535126980	KU	4	40 UNK	SP	CRE		T	8/7/2055
2021 PO5543726987	KU	4	40 UNK	SP	CRE		T	8/8/2055

2021 PO5474326281	KU	4	40 UNK	SP	CRE		B	8/9/2055
2021 PO5474526255	KU	4	40 UNK	SP	CRE		B	8/10/2055
2021 PO5476426088	KU	4	35 UNK	SP	CRE		B	8/11/2055
2021 PO5478025974	KU	4	40 UNK	SP	CRE		T	8/12/2055
2021 PO5479625847	KU	5	35 UNK	SP	CRE		B	8/13/2055
2021 PO5475026215	KU	3	45 UNK	SP	CCA		V	8/14/2055
2021 PO9025796528	KU	6	30 BRN	SP	CRE	ID	TD	8/15/2055
2021 PO9023696475	KU	4	50 BRN	SP	CRE	ID	TD	8/16/2055
2021 PO9037996391	KU	4	45 BRN	SP	CRE	ID	TD	8/17/2055
2021 PO9048796329	KU	5	35 BRN	SP	CRE	ID	TD	8/18/2055
2021 PO9057496278	KU	4	45 BRN	SP	CRE	ID	TD	8/19/2055
2021 PO3159880733	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/20/2055
2021 PO3196080341	KU	6	30 BRO	DF	CRE		V	8/21/2055
2021 PO3197580810	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/22/2055
2021 PO3088182833	KU	4	40 KOP	SP	CRE	ED,ID,RB,SRC	X	8/23/2055
2021 PO303035682787	KU	4	40 KOP	SP	CRE	ED,ID	TD	8/24/2055
2021 PO3038883250	KU	4	40 KOP	SP	CRE	ED,ID	BD	8/25/2055
2021 PO3066582768	KU	4	40 KOP	SP	CRE	ED,ID	TD	8/26/2055
2021 PO2995883823	KU	4	40 KOP	SP	CRE	ED,ID	TD	8/27/2055
2021 PO2969984023	KU	4	40 KOP	SP	CRE	ED,ID,RB,SRC	TD	8/28/2055
2021 PO2916484414	KU	4	40 KOP	SP	CRE	ED,ID	BD	8/29/2055
2021 PO2945284199	KU	4	40 KOP	SP	CRE	ED,ID	TD	8/30/2055
2021 PO3012983742	KU	4	40 KOP	SP	CRE	ED,ID	TD	8/31/2055
2021 PO5473425411	KU	4	40 UNK	SP	CCA		V	9/1/2055
2021 PO5461625335	F	4	40 UNK	SP	CRE		V	9/2/2055
2021 PO5456125399	KU	4	40 UNK	SP	CRE		B	9/3/2055
2021 PO5451425329	KU	6	30 UNK	SP	CCA		B	9/4/2055
2021 PO5450425243	KU	6	30 UNK	SP	CCA		V	9/5/2055
2021 PO5440525318	F	4	40 UNK	SP	CRE		V	9/6/2055
2021 PO1781990616	KU	4	45 BRO	SP	CRE	ID	TD	9/7/2055
2021 PO9734897172A	KU	5	35 XXX	SP	S	ED	T	9/8/2055
2021 PO2668421488	KU	4	40 BRN	SP	CCA	ED	T	9/9/2055
2021 PO2668421130	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/10/2055
2021 PO9752296905	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	9/11/2055
2021 PO9765097220	KU	2	45 XXX	SP	CRE	ED,ID	TD	9/12/2055
2021 PO9753697208	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/13/2055
2021 PO2615421902	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	9/14/2055
2021 PO2613022065	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/15/2055
2021 PO8616803520	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/16/2055
2021 PO2561020302	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	9/17/2055
2021 PO8560803503	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/18/2055
2021 PO2543820084	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/19/2055
2021 PO5400802763	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	9/20/2055
2021 PO2587922099	KU	4	45 BRN	SP	CRE	ED,ID	TD	9/21/2055
2021 PO9387601712	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/22/2055
2021 PO5576101968	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	9/23/2055
2021 PO4436785672	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	9/24/2055
2021 PO5596201826	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	9/25/2055
2021 PO9466500286	KU	2	55 BRO	SP	CRE	ED,ID	TD	9/26/2055
2021 PO8225511524	KU	1	45 BRN	SP	CRE	ED	TD	9/27/2055
2021 PO5532402202	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	9/28/2055
2021 PO5553002108	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	9/29/2055
2021 PO2549522151	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/30/2055
2021 PO9774295123	KU	4	45 UNK	SP	CRE	ED,ID	TD	10/1/2055

2021 PO4386884864	LGE	3	50 ACE	SP	A	ED,ID	TD	10/2/2055
2021 PO9723995640	KU	3	45 UNK	SP	CRE	ED,ID	TD	10/3/2055
2021 PO2579022540	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/4/2055
2021 PO2578022434	KU	6	30 BRN	SP	CRE	ED,ID	TD	10/5/2055
2021 PO8156810666	KU	3	45 BRN	SP	CRE	ED	TD	10/6/2055
2021 9672995890A	KU	6	30 UNK	SP	CRE	ED,ID	TD	10/7/2055
2021 PO8970696884	KU	5	35 XXX	SP	CRE	ED,ID,IP,MD	TD	10/8/2055
2021 PO8968096615	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/9/2055
2021 PO2578821318	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/10/2055
2021 PO2560522569	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/11/2055
2021 PO5786699660	KU	4	30 ACE	SP	CRE	ED,ID,IP	TD	10/12/2055
2021 PO5616101688	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/13/2055
2021 PO8286610867	KU	1	45 BRN	SP	CRE	ED	TD	10/14/2055
2021 PO2563121980	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	10/15/2055
2021 PO4414085972	LGE	4	30 BRO	SP	A	ED,ID	TD	10/16/2055
2021 PO9366701706	KU	4	40 UNK	SP	CRE	ED,ID	TD	10/17/2055
2021 PO9348001700	KU	4	40 UNK	SP	CRE	ED,ID	TD	10/18/2055
2021 PO4438685717	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	10/19/2055
2021 PO5659301446	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/20/2055
2021 PO4388885177	LGE	4	30 ACE	SP	CRE	ED,ID	TD	10/21/2055
2021 PO8277710966	KU	1	45 BRN	SP	CRE	ED	TD	10/22/2055
2021 PO2549721354	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/23/2055
2021 PO5636001573	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/24/2055
2021 PO5433802529	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/25/2055
2021 PO5407702642	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/26/2055
2021 PO8644906229	KU	4	40 UNK	SP	CRE	ED,ID	TD	10/27/2055
2021 PO5384602746	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/28/2055
2021 PO5363102844	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/29/2055
2021 PO8227811836	KU	3	45 BRN	SP	CRE	ED	TD	10/30/2055
2021 PO8209511797	KU	3	45 BRN	SP	CRE	ED	TD	10/31/2055
2021 PO8201611782	KU	3	45 BRN	SP	CRE	ED	TD	11/1/2055
2021 PO8188611759	KU	3	45 BRN	SP	CRE	ED	TD	11/2/2055
2021 PO3225315841	KU	6	30 BRN	SP	CRE	ED,ID	TD	11/3/2055
2021 PO9654196552	KU	3	45 UNK	SP	CRE	ED,ID	TD	11/4/2055
2021 PO9662296347	KU	3	45 UNK	SP	CRE	ED,ID	TD	11/5/2055
2021 PO3310716509	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/6/2055
2021 PO3306416530	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	11/7/2055
2021 PO9344495747	KU	4	40 UNK	SP	CRE	ED,ID	TD	11/8/2055
2021 PO2514921078	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/9/2055
2021 PO5467502489	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	11/10/2055
2021 PO3255415592	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	11/11/2055
2021 PO9656696487	KU	3	45 UNK	SP	CRE	ED,ID	TD	11/12/2055
2021 PO8172711731	KU	3	45 BRN	SP	CRE	ED	TD	11/13/2055
2021 PO8158411706	KU	3	45 BRN	SP	CRE	ED	TD	11/14/2055
2021 PO9378597436	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/15/2055
2021 PO9326397831	KU	4	40 UNK	SP	CRE	ED,ID	TD	11/16/2055
2021 PO8139212190	KU	4	40 BRN	SP	CRE	ED	TD	11/17/2055
2021 PO3387417410	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/18/2055
2021 PO8136412492	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	11/19/2055
2021 PO3390816587	KU	3	40 BRN	SP	CRE	ED,ID	TD	11/20/2055
2021 PO3375517695	KU	4	45 BRN	SP	CRE	ED,ID	TD	11/21/2055
2021 PO9334697460	KU	3	40 UNK	SP	CRE	ED,ID	TD	11/22/2055
2021 PO9330697636	KU	4	40 UNK	SP	CRE	ED,ID	TD	11/23/2055
2021 PO3387516372	KU	5	35 BRN	SP	CRE	ED,ID	TD	11/24/2055



2021 PO8117011771	KU	3	45 BRN	SP	CRE	ED	TD	11/25/2055
2021 PO8109112061	KU	3	45 BRN	SP	CRE	ED	TD	11/26/2055
2021 PO3277115418	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/27/2055
2021 PO9341996610	KU	4	40 UNK	SP	CRE	ED,ID	TD	11/28/2055
2021 PO8141711676	KU	3	45 BRN	SP	CRE	ED	TD	11/29/2055
2021 PO9342696380	KU	4	35 UNK	SP	CRE	ED,ID	TD	11/30/2055
2021 PO9663896237	KU	3	45 UNK	SP	CRE	ED,ID	TD	12/1/2055
2021 PO3293916275	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	12/2/2055
2021 PO4380585151	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/3/2055
2021 PO2508620824	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/4/2055
2021 PO2525320927	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/5/2055
2021 PO5512802290	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	12/6/2055
2021 PO5524002238	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	12/7/2055
2021 PO4379485077	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/8/2055
2021 PO4379485087	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/9/2055
2021 PO4379485097	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/10/2055
2021 PO4419685802	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	12/11/2055
2021 PO4424685443	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	12/12/2055
2021 PO4425686088	LGE	4	35 BRO	SP	A	ED,ID	TD	12/13/2055
2021 PO4379585113	LGE	4	40 ACE	SP	CRE	ED,ID	TD	12/14/2055
2021 PO4426685439	LGE	4	30 BRO	SP	P	ED,ID	TD	12/15/2055
2021 PO8106412522	KU	5	35 BRN	SP	CRE	ED	TD	12/16/2055
2021 PO3518816710	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/17/2055
2021 PO8120312379	KU	3	40 BRN	SP	CRE	ED	TD	12/18/2055
2021 PO3402417013	KU	4	45 BRN	SP	CRE	ED,ID	TD	12/19/2055
2021 PO3390616651	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/20/2055
2021 PO4422786130	LGE	3	50 BRO	SP	A	ED,ID,IP	TD	12/21/2055
2021 PO9787895951	KU	3	45 UNK	SP	CRE	ED,ID	TD	12/22/2055
2021 PO8177710389	KU	2	50 BRN	SP	CRE	ED	TD	12/23/2055
2021 PO9827295221	KU	3	45 UNK	SP	CRE	ED,ID,IP	TD	12/24/2055
2021 PO9717897181	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/25/2055
2021 PO9717497098	KU	5	35 XXX	SP	CRE	ED,ID	TD	12/26/2055
2021 PO9741997195	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/27/2055
2021 PO9714094661	KU	3	45 UNK	SP	CRE	ED,ID,IP	TD	12/28/2055
2021 PO2600522510	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/29/2055
2021 PO4424586129	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	12/30/2055
2021 PO8193911635	KU	4	40 BRN	SP	CRE	ED	TD	12/31/2055
2021 PO8208711661	KU	4	40 BRN	SP	CRE	ED	TD	1/1/2056
2021 PO8214411644	KU	1	45 BRN	SP	CRE	ED	TD	1/2/2056
2021 PO4378984926	LGE	4	40 ACE	SP	CRE	ED,ID	TD	1/3/2056
2021 PO9766495041	KU	3	45 UNK	SP	CRE	ED,ID	TD	1/4/2056
2021 PO4386684839	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD	1/5/2056
2021 PO8162910597	KU	3	45 BRN	SP	CRE	ED	TD	1/6/2056
2021 PO4424186090	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	1/7/2056
2021 PO4386884852	LGE	3	50 ACE	SP	CRE	ED,ID	TD	1/8/2056
2021 PO2621822484	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/9/2056
2021 PO9727595833	KU	3	45 UNK	SP	CRE	ED,ID	TD	1/10/2056
2021 PO9723295755	KU	3	45 UNK	SP	CRE	ED,ID	TD	1/11/2056
2021 PO9691997192	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	1/12/2056
2021 PO9691097092	KU	4	30 XXX	SP	CRE	ED,ID,IP	TD	1/13/2056
2021 PO2668821831	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	1/14/2056
2021 PO2669921991	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/15/2056
2021 PO4412186040	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	1/16/2056
2021 PO9640996976	KU	3	45 UNK	SP	CRE	ED,ID	TD	1/17/2056

2021 PO2714522170	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/18/2056
2021 PO9738996045	KU	3	45 UNK	SP	CRE	ED,ID	TD	1/19/2056
2021 PO9683794910	KU	5	35 UNK	SP	CRE	ED,ID	TD	1/20/2056
2021 PO4382884886	LGE	4	40 ACE	SP	CRE	ED,ID	TD	1/21/2056
2021 PO4382784872	LGE	4	40 ACE	SP	CRE	ED,ID	TD	1/22/2056
2021 PO4382984925	LGE	4	40 ACE	SP	A	ED,ID	TD	1/23/2056
2021 PO4378784887	LGE	4	40 ACE	SP	CRE	ED	TD	1/24/2056
2021 PO4415885946	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	1/25/2056
2021 PO8247909306	KU	1	45 BRN	SP	CRE	ED	TD	1/26/2056
2021 PO9828995326	KU	4	40 UNK	SP	CRE	ED,ID	TD	1/27/2056
2021 PO5757100768	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	1/28/2056
2021 PO5737500877	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	1/29/2056
2021 PO7929006295	KU	2	45 BRN	SP	CRE	ED	TD	1/30/2056
2021 PO9327601696	KU	4	40 UNK	SP	CRE	ED,ID	TD	1/31/2056
2021 PO3133717715	KU	4	35 BRN	SP	CRE	ED,ID	TD	2/1/2056
2021 PO4416786047	LGE	2	60 BRO	SP	CRE	ED,ID,IP	TD	2/2/2056
2021 PO3144717979	KU	4	35 BRN	SP	CRE	ED,ID	TD	2/3/2056
2021 PO3219317357	KU	6	30 BRN	SP	CRE	ED,ID	TD	2/4/2056
2021 PO3198017332	KU	5	35 BRN	SP	CRE	ED,ID	TD	2/5/2056
2021 PO3239217295	KU	5	35 BRN	SP	CRE	ED,ID	TD	2/6/2056
2021 PO7941806415	KU	2	45 BRN	SP	CRE	ED	TD	2/7/2056
2021 PO8090811175	KU	3	45 BRN	SP	CRE	ED	TD	2/8/2056
2021 PO8125311050	KU	3	45 BRN	SP	CRE	ED	TD	2/9/2056
2021 PO4378684860	LGE	4	40 ACE	SP	CRE	ED,ID	TD	2/10/2056
2021 PV4378684865	LGE	4	40 ACE	SP	CRE	ED,ID	TD	2/11/2056
2021 PO9311800332	KU	4	40 UNK	SP	CRE	ED,ID	TD	2/12/2056
2021 PO5421102677	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	2/13/2056
2021 PO2553720641	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	2/14/2056
2021 PO8624406007	KU	4	40 UNK	SP	CRE	ED,ID	TD	2/15/2056
2021 PO9652197990	KU	3	45 XXX	SP	CRE	ED,ID	TD	2/16/2056
2021 PO5349203000	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	2/17/2056
2021 PO8962196078	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	2/18/2056
2021 PO8965296346	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	2/19/2056
2021 PO8943296204	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/20/2056
2021 PO2603721287	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/21/2056
2021 PO8995997176	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD	TD	2/22/2056
2021 PO8975497301	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD	TD	2/23/2056
2021 PO9748796682	KU	3	45 UNK	SP	CRE	ED,ID	TD	2/24/2056
2021 PO4386884875	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD	2/25/2056
2021 PO4414186032	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	2/26/2056
2021 PO4422986128	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	2/27/2056
2021 PO4426086127	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	2/28/2056
2021 PO8293310525	KU	1	45 BRN	SP	CRE	ED	TD	2/29/2056
2021 PO4420385649	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	3/1/2056
2021 PO4441485699	LGE	3	40 BRO	SP	A	HH,ID,IP	TD	3/2/2056
2021 PO4442485685	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/3/2056
2021 PO4378684821	LGE	4	40 ACE	SP	P	ED,ID	TD	3/4/2056
2021 PO4378684833	LGE	4	40 ACE	SP	P	ED,ID	TD	3/5/2056
2021 PO4378584808	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/6/2056
2021 PO9317798953	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/7/2056
2021 PO4385485123	LGE	4	40 ACE	SP	A	ED,ID	TD	3/8/2056
2021 PO4383185151	LGE	4	40 ACE	SP	A	ED,ID	TD	3/9/2056
2021 PO9735196679	KU	3	45 UNK	SP	CRE	ED,ID	TD	3/10/2056
2021 PO9318498203	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/11/2056

2021 PO9322797987	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/12/2056
2021 PO2940720558	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	3/13/2056
2021 PO9316699383	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/14/2056
2021 PO9317299153	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	3/15/2056
2021 PO4422786095	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	3/16/2056
2021 PO8141610860	KU	3	45 BRN	SP	CRE	ED	TD	3/17/2056
2021 PO9315199843	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/18/2056
2021 PO9315899623	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/19/2056
2021 PO2928319440	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/20/2056
2021 PO4387385036	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/21/2056
2021 PO2495618658	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	3/22/2056
2021 PO2486418683	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	3/23/2056
2021 PO4387485056	LGE	4	35 ACE	SP	A	ED,ID	TD	3/24/2056
2021 PO4387485066	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/25/2056
2021 PO9530300010	KU	3	40 UNK	SP	CRE	ED,ID	TD	3/26/2056
2021 PO2535718505	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/27/2056
2021 PO4386684829	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/28/2056
2021 PO5787299393a	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	3/29/2056
2021 PO8161210426	KU	4	40 BRN	SP	CRE	ED	TD	3/30/2056
2021 PO4387084911	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/31/2056
2021 PO8534302866	KU	4	45 CPT	SP	CRE	ED,ID	TD	4/1/2056
2021 PO9784395332	KU	3	45 UNK	SP	CRE	ED,ID	TD	4/2/2056
2021 PO5453802440	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	4/3/2056
2021 PO8626305931	KU	5	35 UNK	SP	CRE	ED,ID	TD	4/4/2056
2021 PO2744022035	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/5/2056
2021 PO9683396701	KU	3	45 UNK	SP	CRE	ED,ID,IP	TD	4/6/2056
2021 PO8055512178	KU	4	40 BRN	SP	CRE	ED	TD	4/7/2056
2021 PO4440685718-A	LGE	5	35 BRO	SP	A	ED,ID	TD	4/8/2056
2021 PO2535322348	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/9/2056
2021 PO2539222606	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/10/2056
2021 PO4378684847	LGE	4	40 ACE	SP	P	ED,ID	TD	4/11/2056
2021 PO4378584784	LGE	4	40 ACE	SP	CRE	ED,ID	TD	4/12/2056
2021 PO8262909709	KU	1	45 BRN	SP	CRE	ED	TD	4/13/2056
2021 PO8271609944	KU	1	45 BRN	SP	CRE	ED	TD	4/14/2056
2021 PO2718722366	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/15/2056
2021 PO9672995890	KU	6	30 UNK	SP	CRE	ED,ID	TD	4/16/2056
2021 PO9674395978	KU	3	45 UNK	SP	CRE	ED,ID	TD	4/17/2056
2021 PO9700695335	KU	2	55 UNK	SP	CRE	ED,ID	TD	4/18/2056
2021 PO2919318584	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/19/2056
2021 PO4387184780	LGE	UNK	25 ACE	SP	CRE	ED,ID	TD	4/20/2056
2021 PO4425886102	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	4/21/2056
2021 PO4379384909	LGE	4	30 ACE	SP	CRE	ED,ID	TD	4/22/2056
2021 PO4378884908	LGE	4	40 ACE	SP	CRE	ED,ID	TD	4/23/2056
2021 PO9752794904	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/24/2056
2021 PO9757394948	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/25/2056
2021 PO5788199210	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	4/26/2056
2021 PO5793399166	KU	4	35 ACE	SP	CRE	ED,ID,IP	TD	4/27/2056
2021 PO8156410482	KU	4	40 BRN	SP	CRE	ED	TD	4/28/2056
2021 PO9529400249	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/29/2056
2021 PO8173510351	KU	3	45 BRN	SP	CRE	ED	TD	4/30/2056
2021 PO8168710308	KU	3	45 BRN	SP	CRE	ED	TD	5/1/2056
2021 PO4387384851	LGE	4	30 ACE	SP	CRE	ED,ID	TD	5/2/2056
2021 PO4386584798	LGE	4	40 ACE	SP	CRE	ED,ID	TD	5/3/2056
2021 PO4386584809	LGE	4	40 ACE	SP	CRE	ED,ID	TD	5/4/2056

2021 PO8160410230	KU	3	45 BRN	SP	CRE	ED	TD	5/5/2056
2021 PO9777795188	KU	3	45 UNK	SP	CRE	ED,ID,JP	TD	5/6/2056
2021 PO8133009980	KU	3	45 BRN	SP	CRE	ED	TD	5/7/2056
2021 PO4422986118	LGE	4	35 BRO	SP	A	ED,ID,JP	TD	5/8/2056
2021 PO7993106855	KU	2	45 BRN	SP	CRE	ED	TD	5/9/2056
2021 PO8024407135	KU	2	45 BRN	SP	CRE	ED	TD	5/10/2056
2021 PO8040107275	KU	2	45 BRN	SP	CRE	ED	TD	5/11/2056
2021 PO8071407555	KU	2	45 BRN	SP	CRE	ED	TD	5/12/2056
2021 PO8122808015	KU	2	50 BRN	SP	CRE	ED	TD	5/13/2056
2021 PO8162008365	KU	2	45 BRN	SP	CRE	ED	TD	5/14/2056
2021 PO8182808551	KU	2	45 BRN	SP	CRE	ED	TD	5/15/2056
2021 PO8217708820	KU	1	50 BRN	SP	CRE	ED	TD	5/16/2056
2021 PO9770896690	KU	3	45 UNK	SP	CRE	ED,ID	TD	5/17/2056
2021 PO7296813841	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/18/2056
2021 PO4128985106	LGE	4	45 BRO	SP	A	ED,ID	BD	5/19/2056
2021 PO3791244056-A	KU	6	30 BRN	SP	S		B	5/20/2056
2021 PO3810043687	KU	6	30 BRN	SP	S		V	5/21/2056
2021 PO3778044202	F	3	45 BRN	SP	S		V	5/22/2056
2021 PO3791244056	KU	3	45 BRN	SP	CCA		V	5/23/2056
2021 PO3774244441	KU	3	45 BRN	SP	CCA		V	5/24/2056
2021 PO3733944361	KU	4	40 UNK	SP	CRE	ID	BD	5/25/2056
2021 PO3767744637	KU	3	45 UNK	SP	CCA		V	5/26/2056
2021 PO3765644822	KU	3	45 UNK	SP	CCA		V	5/27/2056
2021 PO3768445025	KU	4	40 UNK	SP	CCA		V	5/28/2056
2021 PO3770945218	KU	4	40 UNK	SP	CCA		V	5/29/2056
2021 PO3773945414	KU	4	40 UNK	SP	CCA		V	5/30/2056
2021 PO3774045621	KU	4	40 UNK	SP	CCA		V	5/31/2056
2021 PO3774645851	KU	3	45 UNK	SP	CCA		V	6/1/2056
2021 PO3774246062	KU	3	45 UNK	SP	CCA		V	6/2/2056
2021 PO3780946818	KU	3	45 UNK	SP	CCA		V	6/3/2056
2021 PO1579706602	KU	3	45 UNK	SP	CRE	ID,IP,SRS	TD	6/4/2056
2021 PO4144885040	LGE	3	45 ACE	SP	P	ED,ID	TD	6/5/2056
2021 PO4144785040	LGE	3	45 ACE	SP	P	ED,ID	TD	6/6/2056
2021 PO4144585028	LGE	4	35 ACE	SP	P	ED,ID	TD	6/7/2056
2021 PO4145285018	LGE	4	35 ACE	SP	CCA		V	6/8/2056
2021 PO4144885018	LGE	3	45 ACE	SP	P	ED,ID,JP	BD	6/9/2056
2021 PO4127185110	LGE	1	50 BRO	SP	CCA		V	6/10/2056
2021 PO4168586092	F	4	40 BRO	SP	CRE		V	6/11/2056
2021 PO4274071470	KU	4	45 BRN	SP	CRE	ID	TD	6/12/2056
2021 PO4296371479	KU	4	45 BRN	SP	CCA		V	6/13/2056
2021 PO4272971834	KU	4	45 BRN	SP	CRE	ID	TD	6/14/2056
2021 PO4272572061	KU	4	40 BRN	SP	CRE	ID	TD	6/15/2056
2021 PO4403171264	KU	6	30 BRN	SP	CRE	ID	TD	6/16/2056
2021 PO4386171356	KU	6	30 BRN	SP	CRE	ID	TD	6/17/2056
2021 PO1540806703	KU	4	40 UNK	SP	CCA	ID,SRS	TD	6/18/2056
2021 PO4126685093	LGE	4	45 BRO	SP	P	ID	BD	6/19/2056
2021 PO4125685079	LGE	4	45 BRO	SP	P	ID	BD	6/20/2056
2021 PO1498306812	KU	3	45 UNK	SP	CCA		V	6/21/2056
2021 PO1458206915	KU	3	45 UNK	SP	CCA		V	6/22/2056
2021 PO1419307016	KU	3	45 UNK	SP	CCA		V	6/23/2056
2021 PO1382707110	KU	3	45 UNK	SP	CCA		V	6/24/2056
2021 PO4124785079	LGE	4	40 BRO	SP	P	ED,ID,RB	TX	RR 6/25/2056
2021 PO8407962497	LGE	4	35 BRO	SP	CCA		V	6/26/2056
2021 PO8400762414	LGE	4	35 BRO	SP	CCA		V	6/27/2056

2021 PO7218512375	KU	4	45 ACW	SP	S		V		6/28/2056
2021 PO1348407198	KU	4	40 UNK	SP	CRE	ID,IP	TD		6/29/2056
2021 PO1316507281	KU	4	45 UNK	SP	CCA	SRS	TD		6/30/2056
2021 PO1283907365	KU	3	45 UNK	SP	CRE	ID,IP	TD		7/1/2056
2021 PO1260707425	KU	3	50 UNK	SP	CRE	ID,IP	TD		7/2/2056
2021 PO4122085081	LGE	4	40 BRO	SP	A	ID	BD		7/3/2056
2021 PO4122185084	LGE	4	45 BRO	SP	A	ED,ID	BD		7/4/2056
2021 PO4123385081	LGE	4	40 BRO	SP	P	ID	TD		7/5/2056
2021 PO4117685098	LGE	4	50 BRO	SP	CCA		V		7/6/2056
2021 PO4167786120	LGE	4	35 BRO	SP	A	ED,ID	TD		7/7/2056
2021 PO4169186111	LGE	4	35 BRO	SP	CRE	ED,ID	TD		7/8/2056
2021 PO4167786111	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		7/9/2056
2021 PO4117585096	LGE	4	40 BRO	SP	CRE	ED,ID	BD		7/10/2056
2021 PO8332362638	LGE	4	40 BRO	SP	CCA		V		7/11/2056
2021 PO4170086110	LGE	4	35 BRO	SP	CRE	ED,ID,IP,RB	X	RP1	7/12/2056
2021 PO4116385078	LGE	4	40 BRO	SP	P	ID	BD		7/13/2056
2021 PO8307562602	LGE	4	35 BRO	SP	CCA		V		7/14/2056
2021 PO411285061A1	LGE	4	35 BRO	SP	P	ID	BD		7/15/2056
2021 PO4114285061	LGE	4	35 BRO	SP	P	ID	TD		7/16/2056
2021 PO4144784995	LGE	3	45 ACE	SP	P	ED,ID	TD		7/17/2056
2021 PO4171086110	LGE	4	35 BRO	SP	CRE	ED,ID	TD		7/18/2056
2021 PO4144684985	LGE	3	45 ACE	SP	P	ED,ID	BD		7/19/2056
2021 PO4144584971	LGE	3	45 ACE	SP	CCA		V		7/20/2056
2021 PO4114685049	LGE	4	35 BRO	SP	CCA		V		7/21/2056
2021 PO7184311948	KU	4	40 ACW	SP	CRE	ED,ID	BX	RP1	7/22/2056
2021 PO7298114010	KU	4	40 ACW	SP	CRE	ED,ID	BX	RP1	7/23/2056
2021 PO7294913655	KU	5	35 ACW	SP	CRE	ED,HH,ID	X	RP2	7/24/2056
2021 PO7202012173	KU	4	40 ACW	SP	S		V		7/25/2056
2021 PO7299614214	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD		7/26/2056
2021 PO1662206390	KU	3	40 UNK	SP	CRE	ID,IP,SRS	TD		7/27/2056
2021 PO4232870848	KU	4	45 BRN	SP	CCA		V		7/28/2056
2021 PO4210670632	KU	4	45 BRN	SP	CCA		V		7/29/2056
2021 PO4223071427	KU	4	45 BRN	SP	CCA		V		7/30/2056
2021 PO4182285999	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		7/31/2056
2021 PO4181786022	LGE	4	35 BRO	SP	A		V		8/1/2056
2021 PO4145985088	LGE	4	30 ACE	SP	P	ED,ID	BD		8/2/2056
2021 PO4146085090	LGE	4	35 ACE	SP	P	ED,ID	BD		8/3/2056
2021 PO4145185081	LGE	4	35 ACE	SP	CRE	ED,ID	BD		8/4/2056
2021 PO4135085093	LGE	3	45 BRO	SP	CCA		V		8/5/2056
2021 PO4132885098	LGE	3	45 BRO	SP	A	ED,ID	TD		8/6/2056
2021 PO4234371758	KU	4	45 BRN	SP	CCA		V		8/7/2056
2021 PO3627465539	KU	4	45 BRN	SP	CCA		V		8/8/2056
2021 PO0738105253	KU	2	65 UNK	SP	CRE	ED,EP,ID	X	RP2	8/9/2056
2021 PO0760004660	KU	2	65 UNK	SP	CRE	ID,IP	TD		8/10/2056
2021 PO0747705493	KU	2	70 UNK	SP	CCA		V		8/11/2056
2021 PO3942242629	KU	4	40 UNK	SP	CRE	ID	TD		8/12/2056
2021 PO3974742562	KU	4	40 UNK	SP	CRE	ID	TD		8/13/2056
2021 PO4139185044	LGE	4	30 BRO	SP	CRE	ID	TD		8/14/2056
2021 PO7247415266	KU	5	35 ACW	SP	CRE	ED,ID	BD		8/15/2056
2021 PO7388513443	KU	4	40 ACW	SP	S		V		8/16/2056
2021 PO4172286091	F	4	40 BRO	SP	A		V		8/17/2056
2021 PO4139185036	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/18/2056
2021 PO4138385042	LGE	4	40 BRO	SP	CRE	ID	BD		8/19/2056
2021 PO4173286090	F	4	40 BRO	SP	A		V		8/20/2056

2021 PO4174386090	F	4	40 BRO	SP	A		V	8/21/2056
2021 PO4175586089	F	4	40 BRO	SP	CRE		V	8/22/2056
2021 PO0927806866	KU	2	50 UNK	SP	CRE	ID	TD	8/23/2056
2021 PO0926706900	KU	2	65 UNK	SP	CRE	ID,IP	TD	8/24/2056
2021 PO3960642243	KU	4	40 BRO	SP	CCA		B	8/25/2056
2021 PO3982942270	KU	4	40 BRO	SP	CCA		B	8/26/2056
2021 PO3958642463	KU	3	45 BRO	SP	CCA		V	8/27/2056
2021 PO6994709233	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	8/28/2056
2021 PO7005410307	KU	4	45 ACW	SP	CRE	ED,ID	TD	8/29/2056
2021 PO7121011417	KU	5	35 ACW	SP	CRE	ED,ID	TD	8/30/2056
2021 PO4139285061	LGE	4	40 BRO	SP	CRE	ED,ID	TD	8/31/2056
2021 PO4182385953	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/1/2056
2021 PO8562462764	LGE	3	45 BRO	SP	CCA		V	9/2/2056
2021 PO4182285941	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/3/2056
2021 PO4182185931	LGE	4	40 BRO	SP	A	ED,ID	TD	9/4/2056
2021 PO4142485093	LGE	2	55 BRO	SP	CRE	ED,HH,ID	BD	9/5/2056
2021 PO4143885084	LGE	2	60 BRO	SP	CRE	ED,ID,IP	BD	9/6/2056
2021 PO8562462764	LGE	3	45 BRO	SP	CCA		V	9/7/2056
2021 PO4182185928	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	9/8/2056
2021 PO4182085914	LGE	4	40 BRO	SP	CCA		V	9/9/2056
2021 PO0932507348	KU	3	55 UNK	SP	CRE	ID,IP	TD	9/10/2056
2021 PO3608765327	KU	4	45 BRN	SP	CCA		V	9/11/2056
2021 PO3650365781	KU	4	40 BRN	SP	CRE	ID	TD	9/12/2056
2021 PO3781565857	KU	4	40 BRN	SP	A	ID	TD	9/13/2056
2021 PO4132784541	LGE	4	30 ACE	SP	A		V	9/14/2056
2021 PO4181985949	LGE	4	35 BRO	SP	CCA		V	9/15/2056
2021 PO0945508035	KU	2	65 UNK	SP	CRE	ID,SRS	TD	9/16/2056
2021 PO1001106959	KU	4	35 UNK	SP	CRE	ID,IP,SRS	TD	9/17/2056
2021 PO4119285242	LGE	4	40 BRO	SP	CRE	ID	TD	9/18/2056
2021 PO4153086080	LGE	4	35 BRO	SP	A	ED,ID	TD	9/19/2056
2021 PO4153686070	LGE	4	35 BRO	SP	A	ED,ID	TD	9/20/2056
2021 PO4118185237	LGE	4	40 BRO	SP	CRE	ED,ID	BD	9/21/2056
2021 PO3872743234	KU	3	45 BRO	SP	CCA		V	9/22/2056
2021 PO4138385042a1	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/23/2056
2021 PO3822065858	KU	4	40 BRN	SP	CRE	ID	BD	9/24/2056
2021 PO3849964934	KU	4	40 BRN	SP	CCA		V	9/25/2056
2021 PO4139084501	LGE	4	40 ACE	SP	P		V	9/26/2056
2021 PO4147084890	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/27/2056
2021 PO4146984877	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/28/2056
2021 PO3896543039	KU	3	45 BRO	SP	CCA		V	9/29/2056
2021 PO3862443113	KU	4	40 INP	SP	CRE	ID	TD	9/30/2056
2021 PO3914842908	KU	3	45 BRO	SP	CCA		V	10/1/2056
2021 PO3913142571	KU	4	40 INP	SP	CRE	ID	BD	10/2/2056
2021 PO7034310527	KU	3	45 ACW	SP	S		V	10/3/2056
2021 PO7050810663	KU	4	40 ACW	SP	S		V	10/4/2056
2021 PO7099410621	KU	6	30 ACW	SP	CRE	ED,ID	TD	10/5/2056
2021 PO7085110629	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/6/2056
2021 PO7087911031	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/7/2056
2021 PO7068210809	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/8/2056
2021 PO7109011202	KU	4	40 ACW	SP	S		V	10/9/2056
2021 PO7169511738	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/10/2056
2021 PO4139985067	LGE	4	40 BRO	SP	CRE	ED,ID	TD	10/11/2056
2021 PO4145984878	LGE	4	30 ACE	SP	P		V	10/12/2056
2021 PO3850765266	KU	4	45 BRN	SP	CCA		V	10/13/2056

2021 PO3850865522	KU	4	40 BRN	SP	CCA		V			10/14/2056
2021 PO3815443295	KU	6	30 UNK	SP	CRE		V			10/15/2056
2021 PO4157085471	LGE	4	35 BRO	SP	P	ED,ID,RB	BX	PX		10/16/2056
2021 PO4157185485	LGE	6	25 BRO	SP	CRE	ED,EP,ID,MD	BX	PX		10/17/2056
2021 PO4157185482	LGE	6	35 BRO	SP	CRE	ED,ID,IP	TD			10/18/2056
2021 PO4158185481	LGE	4	35 BRO	SP	CRE	ED,ID	TD			10/19/2056
2021 PO4181485276	LGE	4	40 ACE	SP	CRE	ED,ID	BD			10/20/2056
2021 PO8969464673	LGE	3	45 ACE	SP	CCA		V			10/21/2056
2021 PO4179885277	LGE	4	40 ACE	SP	CCA		V			10/22/2056
2021 PO4164786123	LGE	4	35 BRO	SP	A	ED,ID	TD			10/23/2056
2021 PO4164686114-A	LGE	5	35 BRO	SP	A	ED,ID,IP	TD			10/24/2056
2021 PO4164686114	LGE	4	35 BRO	SP	A	ED,ID,RB	X	RP1		10/25/2056
2021 PO4178285278	LGE	4	40 ACE	SP	P	ED,ID	TD			10/26/2056
2021 PO4177285279	LGE	4	40 ACE	SP	CCA		V			10/27/2056
2021 PO4176685279	LGE	4	40 ACE	SP	P	ED,ID	BD			10/28/2056
2021 PO4179785242	LGE	4	40 ACE	SP	CCA		V			10/29/2056
2021 PO4176685264	LGE	4	45 ACE	SP	CCA		V			10/30/2056
2021 PO4183285411	LGE	4	35 BRO	SP	CRE	ED,ID,MD	BX	RR		10/31/2056
2021 PO9172713390	KU	4	40 ACW	SP	S		V			11/1/2056
2021 PO9177913419	KU	4	40 ACW	SP	CCA		V			11/2/2056
2021 PO9164414031	KU	3	40 ACW	SP	S		V			11/3/2056
2021 PO8452716655	KU	4	40 ACW	SP	S		V			11/4/2056
2021 PO8470916587	KU	4	40 ACW	SP	S		V			11/5/2056
2021 PO8492916495	KU	4	40 ACW	SP	S		V			11/6/2056
2021 PO8514716408	KU	4	40 ACW	SP	S		V			11/7/2056
2021 PO7520518228	KU	4	40 ACW	SP	S		V			11/8/2056
2021 PO7457617896	KU	4	40 ACW	SP	S		V			11/9/2056
2021 PO7436618011	KU	4	45 ACW	SP	S		V			11/10/2056
2021 PO7444717887	KU	4	45 ACW	SP	S		V			11/11/2056
2021 PO7426318175	KU	4	45 ACW	SP	S		V			11/12/2056
2021 PO7414818356	KU	4	45 ACW	SP	S		V			11/13/2056
2021 PO7076709676	KU	6	30 ACW	SP	S		V			11/14/2056
2021 PO4491149195	KU	4	40 BRN	SP	CRE	ID	BD			11/15/2056
2021 PO0015701069	KU	3	45 UNK	SP	CRE	ID,SRS	TD			11/16/2056
2021 PO9352600769	KU	3	45 UNK	SP	CRE	ID	TD			11/17/2056
2021 PO9324900406	KU	4	40 UNK	SP	CRE	ID,IP,SRS	TD			11/18/2056
2021 PO9325700400	KU	4	40 UNK	SP	CRE	ID,SRS	TD			11/19/2056
2021 PO0044201409	KU	3	45 UNK	SP	CRE	ID,IP	TD			11/20/2056
2021 PO3629451823	KU	5	35 BRO	SP	CCA		T			11/21/2056
2021 PO0016501062	KU	3	45 UNK	SP	CRE	ID,IP	TD			11/22/2056
2021 PO9994100781	KU	3	40 UNK	SP	CRE	ID,IP,SRS	TD			11/23/2056
2021 PO3678950000	KU	4	40 BRO	SP	CCA		V			11/24/2056
2021 PO3685849798	KU	4	40 BRO	SP	CCA		V			11/25/2056
2021 PO3694049537	KU	4	40 BRO	SP	CCA		V			11/26/2056
2021 PO3699749369	KU	4	40 BRO	SP	CCA		V			11/27/2056
2021 PO3709149204	KU	4	40 BRO	SP	CCA		V			11/28/2056
2021 PO9983900654	KU	3	50 UNK	SP	CRE	EP,ID,SRS	TD			11/29/2056
2021 PO9962200661	KU	3	50 UNK	SP	CCA		V			11/30/2056
2021 PO9923600710	KU	3	50 UNK	SP	CCA		V			12/1/2056
2021 PO3718549045	KU	4	40 BRO	SP	CCA		V			12/2/2056
2021 PO3726448908	KU	3	45 BRO	SP	CCA		V			12/3/2056
2021 PO3736048745	KU	4	40 BRO	SP	CCA		V			12/4/2056
2021 PO3744648537	KU	4	40 BRO	SP	CCA		V			12/5/2056
2021 PO3752048335	KU	4	40 BRO	SP	CCA		V			12/6/2056

2021 PO3758548159	KU	4	40 BRO	SP	CCA		V			12/7/2056
2021 PO3764047997	KU	2	55 BRO	SP	CCA		V			12/8/2056
2021 PO3773647793	KU	4	40 BRO	SP	CCA		V			12/9/2056
2021 PO4504649269	KU	4	40 BRN	SP	CRE	ID	TD			12/10/2056
2021 PO4518249336	KU	4	40 BRN	SP	CRE	ID	TD			12/11/2056
2021 PO4531949379	KU	4	40 BRN	SP	CRE	ID	TD			12/12/2056
2021 PO4532449224	KU	6	30 BRN	SP	CRE	ID	TD			12/13/2056
2021 PO4518849240	KU	4	45 BRN	SP	CRE	ID	BD			12/14/2056
2021 PO4537848989	KU	6	30 BRN	SP	CRE	ID	BD			12/15/2056
2021 PO3782647210	KU	2	50 BRO	SP	CCA		V			12/16/2056
2021 PO3782046993	KU	3	45 BRO	SP	CCA		V			12/17/2056
2021 PO3897141492	KU	6	35 UNK	SP	CRE	ED,ID	TD			12/18/2056
2021 PO4114885074	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD			12/19/2056
2021 PO9887900870	KU	3	45 UNK	SP	CCA		V			12/20/2056
2021 PO4175785300	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1		12/21/2056
2021 PO4186486204	F	5	25 BRO	SP	CCA		V			12/22/2056
2021 PO4171385302	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD			12/23/2056
2021 PO4172685302	LGE	4	40 ACE	SP	CRE	ED,ID	TD			12/24/2056
2021 PO3886541475	KU	3	45 KOP	SP	CRE	ID	TD			12/25/2056
2021 PO9850800953	KU	3	35 UNK	SP	CRE	ID,IP	TD			12/26/2056
2021 PO9598601519	KU	2	60 UNK	SP	CRE	ID,IP	TD			12/27/2056
2021 PO9814300895	KU	3	45 UNK	SP	CCA		V			12/28/2056
2021 PO4184286204	LGE	4	40 BRO	SP	CCA		V			12/29/2056
2021 PO4157285354	LGE	7	25 BRO	SP	A	ED,ID,MD,RB	BX	RP2		12/30/2056
2021 PO9734101215	KU	4	45 UNK	SP	CCA		V			12/31/2056
2021 PO9762501151	KU	4	45 UNK	SP	CCA		V			1/1/2057
2021 PO9785400943	KU	3	45 UNK	SP	CCA		V			1/2/2057
2021 PO4543449027	KU	4	45 BRN	SP	CRE	ID	BD			1/3/2057
2021 PO4547349246	KU	4	45 BRN	SP	CRE	ID	BD			1/4/2057
2021 PO4549649373	KU	2	60 BRN	SP	CRE	ID	TD			1/5/2057
2021 PO4160585370	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR		1/6/2057
2021 PO4155085868	LGE	4	35 BRO	SP	CCA		V			1/7/2057
2021 PO9674401360	KU	2	60 UNK	SP	CRE	ID,SRS	TD			1/8/2057
2021 PO9674101350	KU	2	60 UNK	SP	CRE	ID,IP	TD			1/9/2057
2021 PO4173785301	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD			1/10/2057
2021 PO4155985869	LGE	4	35 BRO	SP	CCA		V			1/11/2057
2021 PO3884241526	KU	4	40 KOP	SP	CCA		B			1/12/2057
2021 PO3860441534	KU	4	40 UNK	SP	CRE	ID	BD			1/13/2057
2021 PO4158885372	LGE	2	55 BRO	SP	CCA		V			1/14/2057
2021 PO4175085296	LGE	4	30 ACE	SP	P	ED,ID	TD			1/15/2057
2021 PO4557749598	KU	4	40 BRN	SP	CRE	ID,IP	TX	RR		1/16/2057
2021 PO4174785300	LGE	4	40 ACE	SP	P	ED,ID	TD			1/17/2057
2021 PO9598801530	KU	2	60 UNK	SP	CRE	HH,ID,RB	X	PX		1/18/2057
2021 PO4158985379	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD			1/19/2057
2021 PO4163986172	F	4	40 BRO	SP	CCA		V			1/20/2057
2021 PO4166786175	LGE	4	40 BRO	SP	CCA	ED,ID,IP,RB	TX	RR		1/21/2057
2021 PO4553849487	KU	4	40 BRN	SP	CRE	ID	TD			1/22/2057
2021 PO4561249698	KU	5	45 BRN	SP	CRE	ID	TD			1/23/2057
2021 PO4522449521	KU	3	50 BRN	SP	CCA		V			1/24/2057
2021 PO4508749422	KU	5	35 BRN	SP	CRE	ID	TD			1/25/2057
2021 PO1010452951	KU	4	40 BRN	SP	CRE	ID	TD			1/26/2057
2021 PO6110429147	KU	2	55 UNK	ST	CCA		V			1/27/2057
2021 PO8224678297	KU	4	40 ACE	SP	CRE	ED,ID	BD			1/28/2057
2021 PO8226078171	KU	4	40 ACE	SP	CRE	ED,ID	BD			1/29/2057



2021 PO8225478240	KU	2	40 ACE	SP	CCA			V	1/30/2057
2021 PO8223278444	KU	4	40 ACE	SP	CRE	ED,ID		BD	1/31/2057
2021 PO4474687960	LGE	4	40 BRO	SP	CRE	ED,ID		TD	2/1/2057
2021 PO6079829013	KU	3	50 UNK	SP	CCA			V	2/2/2057
2021 PO6075729057	KU	3	50 UNK	SP	CCA			V	2/3/2057
2021 PO6071429100	KU	3	50 UNK	SP	CCA			V	2/4/2057
2021 PO6069729079	KU	2	60 UNK	UN	CRE			V	2/5/2057
2021 PO6092228978	F	3	45 UNK	SP	CRE			V	2/6/2057
2021 PO6089428913	KU	3	50 UNK	SP	CCA			V	2/7/2057
2021 PO6094928855	KU	5	35 UNK	SP	CCA			V	2/8/2057
2021 PO6078928873	KU	4	40 UNK	SP	CRE			BD	2/9/2057
2021 PO6084529080	KU	3	50 UNK	UN	CCA			V	2/10/2057
2021 PO6084829058	KU	3	60 UNK	UN	CRE			V	2/11/2057
2021 PO6074029180	F	4	40 UNK	UN	CRE			V	2/12/2057
2021 PO0989152958	KU	5	45 BRN	SP	CRE	ID		BD	2/13/2057
2021 PO0946452877	KU	4	40 BRN	SP	CRE	ID		TD	2/14/2057
2021 PO0950453076	KU	3	45 BRN	SP	CCA			V	2/15/2057
2021 PO8200780507	KU	4	40 ACE	SP	CCA			V	2/16/2057
2021 PO4497188276	LGE	4	30 ACE	SP	A	ED,ID		TD	2/17/2057
2021 PO2061595279	LGE	4	30 ACE	SP	CRE	ED,ID		BD	2/18/2057
2021 PO4476887969	LGE	4	40 BRO	SP	CCA	ED		T	2/19/2057
2021 PO4832211561	F	3	50 XXX	SP	S			V	2/20/2057
2021 PO5672919995	F	4	40 UNK	SP	CRE			B	2/21/2057
2021 PO5668220038	KU	6	30 UNK	SP	CRE	ID		TD	2/22/2057
2021 PO5674420050	KU	4	40 UNK	SP	CRE	ED,ID		TD	2/23/2057
2021 PO4838411783	F	4	40 XXX	SP	CRE			V	2/24/2057
2021 PO4841911900	F	4	45 XXX	SP	CRE			V	2/25/2057
2021 PO4497688265	LGE	4	40 ACE	SP	A	ED,ID		TD	2/26/2057
2021 PO4476187957	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TD	2/27/2057
2021 PO4439288238	LGE	4	40 BRO	SP	A	ED,ID,IP,RB		TX	RR 2/28/2057
2021 PO4439288242	LGE	5	30 BRO	SP	CRE	ED,HH,ID,RB		BX	RP1 3/1/2057
2021 PO4438188257	LGE	4	30 BRO	SP	A	ED,ID		TD	3/2/2057
2021 PO4438088244	LGE	4	40 BRO	SP	CRE	ED,ID		TD	3/3/2057
2021 PO4436288259	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TD	3/4/2057
2021 PO4436488268	LGE	6	30 BRO	SP	CRE	ED,ID		TD	3/5/2057
2021 PO4435788266	LGE	4	40 BRO	SP	A	ED,ID		TD	3/6/2057
2021 PO4435088275	LGE	4	40 BRO	SP	CRE	ED,ID,IP		BD	3/7/2057
2021 PO4845612052	F	4	45 XXX	SP	P			V	3/8/2057
2021 PO4818812154	F	4	45 XXX	SP	CRE			V	3/9/2057
2021 PO5669720093	KU	3	50 BRO	SP	CCA			V	3/10/2057
2021 PO5675920114	KU	3	50 BRO	SP	CCA			V	3/11/2057
2021 PO6152529509	KU	3	55 UNK	SP	CRE			T	3/12/2057
2021 PO4833212099	F	4	45 XXX	SP	CRE			V	3/13/2057
2021 PO4941310761	F	4	45 KOP	SP	CCA			V	3/14/2057
2021 PO4513888252	LGE	4	40 ACE	SP	A	ED,ID		TD	3/15/2057
2021 PO4476587951	LGE	4	40 BRO	SP	CCA	ED		T	3/16/2057
2021 PO4476987944	LGE	4	40 BRO	SP	A	ED,ID,IP,RB		TX	RR 3/17/2057
2021 PO6144329487	KU	4	40 UNK	SP	CRE			BD	3/18/2057
2021 PO6138329375	KU	4	40 UNK	ST	CCA			V	3/19/2057
2021 PO6168829664	KU	3	55 UNK	ST	CCA			V	3/20/2057
2021 PO6158929434	F	3	45 UNK	SP	CRE			V	3/21/2057
2021 PO8219878743	KU	4	40 ACE	SP	CRE	ED,ID		BD	3/22/2057
2021 PO8218378879	KU	4	40 ACE	SP	CRE	ED,ID		BD	3/23/2057
2021 PO8208279822	KU	4	40 ACE	SP	CCA			V	3/24/2057

2021 PO8209279726	KU	4	40 ACE	SP	CCA			V	3/25/2057
2021 PO8210479615	KU	4	40 ACE	SP	CCA			V	3/26/2057
2021 PO8211979473	KU	4	40 ACE	SP	CRE		ED,ID	BD	3/27/2057
2021 PO8235179372	KU	5	35 ACE	SP	CRE		ED,ID	BD	3/28/2057
2021 PO8222679360	KU	5	35 ACE	SP	CCA			V	3/29/2057
2021 PO8213279350	KU	4	40 ACE	SP	CCA			V	3/30/2057
2021 PO8215079182	KU	4	40 ACE	SP	CCA			V	3/31/2057
2021 PO8202680334	KU	4	40 ACE	SP	CCA			V	4/1/2057
2021 PO4512588253	LGE	4	40 ACE	SP	A		ED,ID	TD	4/2/2057
2021 PO6125729488	KU	6	30 UNK	SP	CRE			T	4/3/2057
2021 PO6119429421	KU	4	40 UNK	SP	CRE			BD	4/4/2057
2021 PO6139929640	KU	6	30 UNK	SP	CRE			T	4/5/2057
2021 PO6134729585	KU	5	35 UNK	SP	CRE			T	4/6/2057
2021 PO6127329664	KU	6	30 UNK	SP	CCA			V	4/7/2057
2021 PO6105727364	KU	6	30 UNK	UN	CRE			V	4/8/2057
2021 PO5663420146	KU	4	40 UNK	SP	CRE		ID	TD	4/9/2057
2021 PO5670220265	KU	6	30 UNK	SP	CRE		ID	TD	4/10/2057
2021 PO5680920346	KU	3	50 BRO	SP	CCA			V	4/11/2057
2021 PO5675820357	KU	4	40 UNK	SP	CRE		ED,ID	TD	4/12/2057
2021 PO5687020353	KU	5	35 BRO	SP	CRE			T	4/13/2057
2021 PO4508688231	LGE	4	40 ACE	SP	CRE		ED,ID	BD	4/14/2057
2021 PO4477287933	LGE	4	30 BRO	SP	CRE		ED,ID	TD	4/15/2057
2021 PO4477687935	LGE	3	45 BRO	SP	A		ED,ID,IP	TD	4/16/2057
2021 PO8204380180	KU	4	40 ACE	SP	CRE		ED,ID	BD	4/17/2057
2021 PO7904774111	KU	6	30 ACE	SP	CRE		ED,ID,IP	BD	4/18/2057
2021 PO8216380032	KU	6	30 ACE	SP	CRE		ED,ID,IP	TD	4/19/2057
2021 PO4513788175	LGE	4	40 ACE	SP	A		ED,ID	TD	4/20/2057
2021 PO6145328509	KU	6	30 UNK	SP	CRE			T	4/21/2057
2021 PO6150928565	KU	5	35 UNK	SP	CRE			BD	4/22/2057
2021 PO6156728622	KU	6	30 UNK	SP	CRE			BD	4/23/2057
2021 PO6164528699	KU	4	40 UNK	SP	CRE			BD	4/24/2057
2021 PO4932310626	F	4	40 XXX	SP	CRE			V	4/25/2057
2021 PO4932310524	F	6	30 XXX	SP	CRE			V	4/26/2057
2021 PO4924510508	F	4	40 XXX	SP	CRE		ED,ID,RB	BX	4/27/2057
2021 PO4919110427	F	4	45 XXX	SP	CCA			V	4/28/2057
2021 PO4936410129	F	4	40 XXX	SP	CRE			V	4/29/2057
2021 PO4941110211	F	5	35 XXX	SP	CRE			V	4/30/2057
2021 PO4922510207	F	4	40 XXX	SP	CRE			V	5/1/2057
2021 PO0925252846	KU	4	45 BRN	SP	CRE		ID	TD	5/2/2057
2021 PO6160828760	KU	6	30 UNK	SP	CCA			V	5/3/2057
2021 PO6134928662	KU	5	35 UNK	SP	CRE			BD	5/4/2057
2021 PO6141628615	KU	4	40 UNK	UN	CRE			V	5/5/2057
2021 PO6150228661	KU	6	30 UNK	SP	CCA			V	5/6/2057
2021 PO6131428561	F	4	40 UNK	SP	CRE			V	5/7/2057
2021 PO7921173775	KU	6	30 ACE	SP	CRE		ED,ID	BD	5/8/2057
2021 PO5677720441	KU	6	30 BRO	SP	CCA			V	5/9/2057
2021 PO5682920433	KU	3	50 BRO	SP	CCA			V	5/10/2057
2021 PO5675620590	KU	4	40 UNK	SP	CRE		ED,ID	TD	5/11/2057
2021 PO5686220533	KU	4	40 UNK	SP	CRE		ID	BD	5/12/2057
2021 PO5684220471	KU	2	50 BRO	SP	CCA			V	5/13/2057
2021 PO5687620471	KU	4	45 BRO	SP	CCA			V	5/14/2057
2021 PO5694920451	KU	4	45 UNK	SP	CRE		ID	TD	5/15/2057
2021 PO5695520448	KU	5	35 BRO	SP	CCA			V	5/16/2057
2021 PO5689620523	KU	4	40 UNK	SP	CRE		ID	TD	5/17/2057

2021 PO5694420511	KU	4	40 UNK	SP	CRE	ID	TD	5/18/2057
2021 PO5701220493	KU	4	40 UNK	SP	CRE	ID	TD	5/19/2057
2021 PO5708520408	KU	5	35 UNK	SP	CRE	ID	TD	5/20/2057
2021 PO5705720480	KU	4	40 BRO	SP	CRE	ID	TD	5/21/2057
2021 PO5709720470	KU	4	40 BRO	SP	CCA		V	5/22/2057
2021 PO5711820463	KU	4	40 BRO	SP	CCA		V	5/23/2057
2021 PO5705720421	KU	4	45 BRO	SP	CCA		V	5/24/2057
2021 PO5711120405	F	6	30 UNK	SP	P	ED,HH,ID,RB	BX PX	5/25/2057
2021 PO5701720340	KU	6	30 UNK	SP	CRE		B	5/26/2057
2021 PO5699820273	KU	6	30 UNK	SP	CRE	ID	BD	5/27/2057
2021 PO5698820245	KU	6	30 BRO	SP	CCA		V	5/28/2057
2021 PO5697920211	KU	2	40 BRO	SP	CRE	ID	BD	5/29/2057
2021 PO0912652901	KU	4	30 BRN	SP	CRE	ID	TD	5/30/2057
2021 PO0904453066	KU	3	45 BRN	SP	CCA		T	5/31/2057
2021 PO4500688271	LGE	4	35 ACE	SP	A	ED,ID	BD	6/1/2057
2021 PO4433788296	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/2/2057
2021 PO4434088286	LGE	4	40 BRO	SP	CCA	ED,ID	BD	6/3/2057
2021 PO4433388293	LGE	4	40 BRO	SP	P	ED,ID	TD	6/4/2057
2021 PO4432688300	LGE	4	40 BRO	SP	CCA		V	6/5/2057
2021 PO4436088299	LGE	4	40 BRO	SP	P	ED,ID	BD	6/6/2057
2021 PO4437088301	LGE	4	35 BRO	SP	CRE	ED,EP,ID,IP,RB	BD	6/7/2057
2021 PO4436488293	LGE	4	30 BRO	SP	P	ED,ID	BD	6/8/2057
2021 PO4434788148	F	4	35 BRO	SP	CRE		V	6/9/2057
2021 PO4437288188	LGE	3	50 BRO	UN	CRE		V	6/10/2057
2021 PO0889353188	KU	4	40 KOP	SP	CRE	ID	TX RR	6/11/2057
2021 PO6161229028	KU	4	40 UNK	SP	CRE		T	6/12/2057
2021 PO6157628994	KU	4	40 UNK	SP	CRE		T	6/13/2057
2021 PO4501488257	LGE	4	35 ACE	SP	CCA	ED,ID	BD	6/14/2057
2021 PO4501788260	LGE	4	35 ACE	SP	CCA		V	6/15/2057
2021 PO0890553058	KU	3	45 BRN	SP	CCA		V	6/16/2057
2021 PO0896952790	KU	4	45 INP	SP	CRE	ID	TD	6/17/2057
2021 PO0861052700	KU	4	45 INP	SP	CRE	ID	TD	6/18/2057
2021 PO4451587878	LGE	4	40 BRO	SP	CCA		V	6/19/2057
2021 PO7930073847	KU	4	40 ACE	SP	CCA		V	6/20/2057
2021 PO7933873729	KU	5	35 ACE	SP	CCA		V	6/21/2057
2021 PO6128528713	KU	3	45 UNK	SP	CRE		BD	6/22/2057
2021 PO6134628771	KU	3	45 UNK	SP	CCA		V	6/23/2057
2021 PO6140428827	KU	4	40 UNK	SP	CRE		BD	6/24/2057
2021 PO6151628934	KU	4	40 UNK	SP	CRE		BD	6/25/2057
2021 PO6166929081	KU	4	40 UNK	SP	CRE		BD	6/26/2057
2021 PO4502188251	LGE	4	40 ACE	SP	CRE	ED,ID	BD	6/27/2057
2021 PO4450887887	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	6/28/2057
2021 PO4451187890	LGE	4	30 BRO	SP	A	ID,IP	BD	6/29/2057
2021 PO4501888239	LGE	4	40 ACE	SP	A	ED,ID	BD	6/30/2057
2021 PO4501988249	LGE	4	40 ACE	SP	CCA	ED,ID	BD	7/1/2057
2021 PO4900810149	F	4	40 XXX	SP	S		V	7/2/2057
2021 PO4909510280	F	4	40 XXX	SP	CRE		V	7/3/2057
2021 PO5058412695	F	4	40 XXX	SP	CRE		V	7/4/2057
2021 PO7921174098	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	7/5/2057
2021 PO7933674073	KU	4	40 ACE	SP	CRE	ED,ID	TD	7/6/2057
2021 PO7942174211	F	4	35 ACE	SP	CRE		V	7/7/2057
2021 PO7935674213	F	4	40 ACE	SP	P		V	7/8/2057
2021 PO7938874341	F	4	40 ACE	SP	P		V	7/9/2057
2021 PO6114028749	F	4	40 UNK	SP	CRE		V	7/10/2057

2021 PO6108728717	KU	3	45 UNK	SP	CCA		V	7/11/2057
2021 PO4501888229	LGE	4	40 ACE	SP	CRE	ED,ID	TD	7/12/2057
2021 PO4450287893	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	7/13/2057
2021 PO4450587896	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	7/14/2057
2021 PO0863452949	KU	4	40 KOP	SP	CRE	ID	TD	7/15/2057
2021 PO0864253128	KU	4	40 KOP	SP	CRE	ID	TD	7/16/2057
2021 PO0557955219	KU	3	45 KOP	SP	CRE	ID	TD	7/17/2057
2021 PO4501888218	LGE	4	40 ACE	SP	CRE	ED,ID	TD	7/18/2057
2021 PO5998627749	F	3	30 UNK	SP	CRE		V	7/19/2057
2021 PO6000327812	KU	2	45 UNK	SP	CRE	ED,ID	BX	7/20/2057
2021 PO5992227848	KU	5	35 UNK	SP	CRE		BD	7/21/2057
2021 PO5989227858	F	3	35 UNK	SP	CRE		V	7/22/2057
2021 PO6013727941	KU	3	55 UNK	SP	CRE		BD	7/23/2057
2021 PO6024928046	KU	3	55 UNK	SP	CCA		V	7/24/2057
2021 PO6008827998	KU	5	35 UNK	SP	CRE		BD	7/25/2057
2021 PO6007127880	KU	4	45 UNK	SP	CRE		V	7/26/2057
2021 PO6001427935	F	4	40 UNK	SP	CRE		V	7/27/2057
2021 PO7948674660	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	7/28/2057
2021 PO7950974633	KU	4	40 ACE	SP	CRE	ED,ID	TD	7/29/2057
2021 PO7956874627	KU	5	35 ACE	SP	P	ED,ID	BD	7/30/2057
2021 PO7945874506	KU	4	40 ACE	SP	CRE	ED,ID	TD	7/31/2057
2021 PO4449287902	LGE	6	25 BRO	SP	A	ED,ID,IP	TD	8/1/2057
2021 PO7948174425	F	4	40 ACE	SP	P		V	8/2/2057
2021 PO7952674532	F	4	40 ACE	SP	P		V	8/3/2057
2021 PO4505388207	LGE	4	25 ACE	SP	CRE	ED,ID	TD	8/4/2057
2021 PO5046112635	F	4	40 XXX	SP	CRE		V	8/5/2057
2021 PO5048412727	F	4	40 XXX	SP	CRE		V	8/6/2057
2021 PO5034712577	F	4	40 XXX	SP	CRE		V	8/7/2057
2021 PO5079512630	F	4	40 XXX	SP	CRE		V	8/8/2057
2021 PO5045612537	F	4	40 XXX	SP	CRE		V	8/9/2057
2021 PO5055212503	F	4	40 XXX	SP	CRE		V	8/10/2057
2021 PO5070612449	F	4	40 XXX	SP	CRE		V	8/11/2057
2021 PO4449287898	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	8/12/2057
2021 PO4504688208	LGE	4	40 ACE	SP	CRE	ED,ID	BD	8/13/2057
2021 PO4505388196	LGE	4	40 ACE	SP	CCA		V	8/14/2057
2021 PO4506488162	LGE	4	30 ACE	SP	CRE	ED,ID	BD	8/15/2057
2021 PO2156993925	LGE	4	35 ACE	SP	CCA	ED,ID	BD	8/16/2057
2021 PO4506888155	LGE	3	45 ACE	SP	CCA		V	8/17/2057
2021 PO6022029738	KU	5	35 UNK	SP	CCA		V	8/18/2057
2021 PO6030429651	KU	4	30 UNK	SP	CCA		V	8/19/2057
2021 PO4508288154	LGE	3	45 ACE	SP	CCA		V	8/20/2057
2021 PO4504188157	LGE	3	45 ACE	SP	CCA		V	8/21/2057
2021 PO4447487896	LGE	4	40 BRO	SP	A	ED,ID	TD	8/22/2057
2021 PO4501288168	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/23/2057
2021 PO4446787892	LGE	4	35 BRO	SP	A	ED,ID	TD	8/24/2057
2021 PO0826352639	KU	4	40 KOP	SP	CRE	ID	TD	8/25/2057
2021 PO8312361782	ODP	4	40 BRN	SP	CCA		V	8/26/2057
2021 PO8303361739	F	4	45 OTH	SP	P		V	8/27/2057
2021 PO5213910149	F	4	40 XXX	SP	CRE		V	8/28/2057
2021 PO1118553048	KU	4	35 BRN	SP	CCA	ID	TD	8/29/2057
2021 PO4471387987	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	8/30/2057
2021 PO5773221999	KU	3	45 BRO	SP	CCA		V	8/31/2057
2021 PO4502488240	LGE	4	40 ACE	SP	CRE	ED,ID	BD	9/1/2057
2021 PO4506388192	LGE	4	30 ACE	SP	CCA		V	9/2/2057

2021 PO4505188210	LGE	4	30 ACE	SP	CRE	ED,ID	BD	9/3/2057
2021 PO4504088229	LGE	4	35 ACE	SP	CCA		V	9/4/2057
2021 PO4502988233	LGE	4	40 ACE	SP	CRE	ED,ID	BD	9/5/2057
2021 PO4504088238	LGE	4	35 ACE	SP	CCA		V	9/6/2057
2021 PO5258210874	F	4	40 XXX	SP	P		V	9/7/2057
2021 PO8346869699	ODP	3	45 XXX	SP	CCA		V	9/8/2057
2021 PO8335969513	ODP	3	45 XXX	SP	CCA		V	9/9/2057
2021 PO8364069568	ODP	4	45 XXX	SP	CCA		V	9/10/2057
2021 PO8379769442	ODP	4	45 XXX	SP	CCA		V	9/11/2057
2021 PO8398069299	ODP	2	55 XXX	SP	CCA		V	9/12/2057
2021 PO4440388238	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/13/2057
2021 PO4440788228	LGE	4	40 BRO	SP	P	ED,ID	TD	9/14/2057
2021 PO4440988219	LGE	4	40 BRO	SP	P	ED,ID	TD	9/15/2057
2021 PO4502988243	LGE	4	30 ACE	SP	CRE	ED,ID	BD	9/16/2057
2021 PO5253810743	F	4	40 XXX	SP	CRE		V	9/17/2057
2021 PO5248126658	KU	4	40 UNK	SP	CRE		BD	9/18/2057
2021 PO5246226782	KU	4	40 UNK	SP	CCA		V	9/19/2057
2021 PO4441288210	LGE	4	40 BRO	SP	P	ED,ID	TD	9/20/2057
2021 PO4441588202	LGE	4	40 BRO	SP	CRE	ED,ID	BD	9/21/2057
2021 PO4442188184	LGE	4	40 BRO	SP	CCA		V	9/22/2057
2021 PO4441888193	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	9/23/2057
2021 PO4442388178	LGE	3	45 BRO	SP	P	ED,ID,IP	TD	9/24/2057
2021 PO4442588171	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/25/2057
2021 PO4442588163	LGE	4	35 BRO	SP	CRE	ED,ID	TD	9/26/2057
2021 PO4442888161	LGE	3	45 BRO	SP	CCA		V	9/27/2057
2021 PO4441488245	F	4	30 BRO	SP	CCA		V	9/28/2057
2021 PO5244426896	KU	4	40 UNK	SP	CRE		BD	9/29/2057
2021 PO5246326972	KU	2	40 UNK	SP	CRE		BD	9/30/2057
2021 PO5234126891	KU	5	35 UNK	SP	CRE		V	10/1/2057
2021 PO5236427067	KU	2	45 UNK	SP	CRE		V	10/2/2057
2021 PO5233727075	KU	2	45 UNK	SP	CRE		V	10/3/2057
2021 PO5230227084	KU	2	50 UNK	UN	CCA		V	10/4/2057
2021 PO5387425122	KU	4	35 UNK	SP	CCA		V	10/5/2057
2021 PO4119785494	F	4	40 ACE	SP	P		V	10/6/2057
2021 PO4120985483	F	5	25 ACE	SP	CRE		V	10/7/2057
2021 PO4119685483	F	4	40 ACE	SP	P		V	10/8/2057
2021 PO4119685473	F	4	40 ACE	SP	P		V	10/9/2057
2021 PO4118685463	F	5	25 ACE	SP	CRE		V	10/10/2057
2021 PO4119385461	F	4	40 ACE	SP	P		V	10/11/2057
2021 PO4057684959	F	4	40 BRO	SP	P		V	10/12/2057
2021 PO4057784953	F	4	40 BRO	SP	P		V	10/13/2057
2021 PO4118585451	F	6	25 ACE	SP	CRE		V	10/14/2057
2021 PO4112485596	F	4	40 ACE	SP	CRE		V	10/15/2057
2021 PO4112985595	F	4	40 ACE	SP	CRE		V	10/16/2057
2021 PO4114185597	F	4	35 ACE	SP	CRE		V	10/17/2057
2021 PO4114385592	F	4	40 ACE	SP	CRE		V	10/18/2057
2021 PO4115185584	F	6	25 ACE	SP	CRE		V	10/19/2057
2021 PO4115285592	F	4	40 ACE	SP	P		V	10/20/2057
2021 PO4116285582	F	6	25 ACE	SP	CRE		V	10/21/2057
2021 PO4116285589	F	4	40 ACE	SP	CCA		V	10/22/2057
2021 PO4117485588	F	4	40 ACE	SP	CRE		V	10/23/2057
2021 PO4118185599	F	6	25 ACE	SP	CRE		V	10/24/2057
2021 PO4117485581	F	6	30 ACE	SP	CCA		V	10/25/2057
2021 PO6250150462	KU	4	40 UNK	SP	CCA		V	10/26/2057

2021 PO6247050243	KU	3	45 UNK	SP	CCA		V	10/27/2057	
2021 PO3425523650	F	4	40 BRN	SP	P		V	10/28/2057	
2021 PO3415323655	F	4	40 BRN	SP	P		V	10/29/2057	
2021 PO3416123728	F	4	40 BRN	SP	P		V	10/30/2057	
2021 PO3415823792	F	4	40 BRN	SP	P		V	10/31/2057	
2021 PO3423923774	F	4	40 BRN	SP	CRE		V	11/1/2057	
2021 PO3423623882	F	4	40 BRN	SP	P		V	11/2/2057	
2021 PO3415123878	F	4	40 BRN	SP	P		V	11/3/2057	
2021 PO3398723787	F	4	40 BRN	SP	P		V	11/4/2057	
2021 PO3393923863	F	4	40 BRN	SP	P		V	11/5/2057	
2021 PO4055684961	F	4	40 BRO	SP	P		V	11/6/2057	
2021 PO9732763220	KU	4	40 BRO	SP	CRE		V	11/7/2057	
2021 PO9573463308	KU	4	40 BRO	SP	CCA		V	11/8/2057	
2021 PO9805062866	KU	5	35 BRO	SP	CCA		V	11/9/2057	
2021 PO9806663017	KU	4	40 BRO	SP	CCA		V	11/10/2057	
2021 PO4157985969	F	4	35 BRO	SP	A		V	11/11/2057	
2021 PO4181085424	F	5	35 BRO	SP	CRE		V	11/12/2057	
2021 PO4179885424	F	5	35 BRO	SP	CCA		V	11/13/2057	
2021 PO4178485424	F	4	40 BRO	SP	CRE		V	11/14/2057	
2021 PO4157285850	LGE	3	40 BRO	SP	CRE	ED,ID,IP	TX	RR	11/15/2057
2021 PO4113385533	LGE	4	40 ACE	SP	CRE	ED,ID	TD		11/16/2057
2021 PO4113885505	LGE	4	40 ACE	SP	P	ED,ID	TD		11/17/2057
2021 PO4113685517	LGE	4	40 ACE	SP	P	ED,ID	TD		11/18/2057
2021 PO4157485850	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		11/19/2057
2021 PO4114085494	LGE	4	40 ACE	SP	P	ED,ID	TD		11/20/2057
2021 PO5598932349	KU	4	40 BRO	SP	CRE	ED,ID	TD		11/21/2057
2021 PO5587336403	KU	4	40 BRO	SP	CRE	ED,ID	TD		11/22/2057
2021 PO4068284838	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/23/2057
2021 PO4157285871-A	KU	5	35 BRO	SP	A	ED,ID	TD		11/24/2057
2021 PO4113385557	LGE	3	45 ACE	SP	P	ED,ID	TD		11/25/2057
2021 PO4157285871-B	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/26/2057
2021 PO4065484819	LGE	4	30 BRO	SP	CRE	ED,ID	TD		11/27/2057
2021 PO4154785772	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		11/28/2057
2021 PO4047184823	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		11/29/2057
2021 PO4057184901	LGE	4	35 BRO	SP	A	ED,ID	TD		11/30/2057
2021 PO4154785757	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		12/1/2057
2021 PO9410863427	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/2/2057
2021 PO4153285772	LGE	4	35 BRO	SP	A	ED,ID	TD		12/3/2057
2021 PO4153285758	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		12/4/2057
2021 PO4124585548	LGE	4	35 ACE	SP	P	ED,ID	TD		12/5/2057
2021 9833964816A	KU	5	30 BRO	SP	CRE	ED,ID	TD		12/6/2057
2021 PO9852465226	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/7/2057
2021 PO9965868031	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/8/2057
2021 PO4157585891	LGE	3	45 BRO	SP	CRE	ED,ID	TD		12/9/2057
2021 PO4111785597a	KU	5	35 ACE	SP	P	ED,ID	TD		12/10/2057
2021 PO9699270561	KU	5	35 BRO	SP	CRE	ED,ID	TD		12/11/2057
2021 PO9678570150	KU	4	40 BRO	SP	A	ED,ID	TD		12/12/2057
2021 PO4157785915	LGE	3	45 BRO	SP	CRE	ED,ID	TD		12/13/2057
2021 PO9927966822	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/14/2057
2021 PO4056284965	LGE	4	35 BRO	SP	P	ED,ID,IP	TD		12/15/2057
2021 PO9848763096	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/16/2057
2021 PO9822463127	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/17/2057
2021 PO9856364176	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/18/2057
2021 PO4157985984	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		12/19/2057

2021 PO4158185998	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		12/20/2057
2021 PO9780763173	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/21/2057
2021 PO4157485873	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		12/22/2057
2021 PO4157285871	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		12/23/2057
2021 PO4157885937	LGE	3	45 BRO	SP	CRE	ED,ID	TD		12/24/2057
2021 PO4157885953	LGE	4	35 BRO	SP	A	ED,ID	TD		12/25/2057
2021 PO4113585524	LGE	4	40 ACE	SP	P	ED,EP,ID,IP,RB	BX	RP1	12/26/2057
2021 PO3862111809	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	12/27/2057
2021 PO3877013220	KU	4	40 XXX	SP	CRE	ID,IP	BD		12/28/2057
2021 PO4058884986	LGE	4	40 BRO	SP	P	ED,ID	BD		12/29/2057
2021 PO4058684980	LGE	4	35 BRO	SP	P	ED,ID	BD		12/30/2057
2021 PO6495650482	KU	4	45 UNK	SP	CRE	ID	BD		12/31/2057
2021 PO6489150464	KU	4	40 UNK	SP	CRE	ID	BD		1/1/2058
2021 PO4113185545	LGE	3	45 ACE	SP	P	ED,ID	BD		1/2/2058
2021 PO3864012191	KU	4	45 XXX	SP	CRE	ID	BD		1/3/2058
2021 PO4651029041	KU	3	45 BRN	SP	CRE	ID	BD		1/4/2058
2021 PO9871165620	KU	4	40 BRO	SP	CRE	ED,ID	BD		1/5/2058
2021 PO4157485871	LGE	3	45 BRO	SP	A	ID	BD		1/6/2058
2021 PO9833964816	KU	4	40 BRO	SP	CRE	ED,ID	BD		1/7/2058
2021 PO4058184971	LGE	4	40 BRO	SP	P	ED,ID	BD		1/8/2058
2021 PO6553949629	KU	4	45 UNK	SP	CRE	ID	BD		1/9/2058
2021 PO9691070417	KU	4	40 BRO	SP	CRE	ED,ID	BD		1/10/2058
2021 PO9724770943	KU	4	40 BRO	SP	CRE	ED,ID	BD		1/11/2058
2021 PO6232849389	KU	4	40 UNK	SP	CRE	ID	BD		1/12/2058
2021 PO6239249822	KU	5	45 UNK	SP	CRE	ID	BD		1/13/2058
2021 PO5749535633	KU	6	30 BRO	SP	CCA		V		1/14/2058
2021 5698534419A	KU	5	30 BRO	SP	CCA		V		1/15/2058
2021 PO6314345482	KU	3	45 BRO	SP	CCA		V		1/16/2058
2021 PO6233445466	KU	3	45 BRO	SP	CCA		V		1/17/2058
2021 PO4058584801	LGE	4	40 BRO	SP	CCA		V		1/18/2058
2021 PO4112985478	LGE	3	45 ACE	SP	CCA		V		1/19/2058
2021 PO4050784741	LGE	4	40 BRO	SP	CCA		V		1/20/2058
2021 PO4052084744	LGE	4	30 BRO	SP	CCA		V		1/21/2058
2021 PO4115085472	LGE	4	30 ACE	SP	CCA		V		1/22/2058
2021 PO4056884760	LGE	4	40 BRO	SP	CCA		V		1/23/2058
2021 PO4053884755	LGE	4	40 BRO	SP	CCA		V		1/24/2058
2021 PO4054384767	LGE	4	40 BRO	SP	CCA		V		1/25/2058
2021 PO4055184789	LGE	4	40 BRO	SP	CCA		V		1/26/2058
2021 PO4103485394	LGE	3	45 ACE	SP	CCA		V		1/27/2058
2021 PO4103185412	LGE	4	40 ACE	SP	CCA		V		1/28/2058
2021 PO4102985423	LGE	4	35 ACE	SP	CCA		V		1/29/2058
2021 5408525286A	KU	5	30 BRO	SP	CCA		V		1/30/2058
2021 PO5390624466	KU	4	30 BRO	SP	CRE		V		1/31/2058
2021 5364924214A	KU	5	30 BRO	SP	S		V		2/1/2058
2021 PO5407524690	KU	3	45 BRO	SP	CCA		V		2/2/2058
2021 PO4102485472	LGE	3	45 ACE	SP	CCA		V		2/3/2058
2021 PO5338224041	F	4	40 BRO	SP	CRE		V		2/4/2058
2021 PO4068984878	LGE	3	45 BRO	SP	CCA		V		2/5/2058
2021 PO4053684913	LGE	4	35 BRO	SP	CRE	ED,ID,RB	TX	RR	2/6/2058
2021 PO4109885482	LGE	4	35 ACE	SP	P	ED,ID	TD		2/7/2058
2021 PO4109385472	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		2/8/2058
2021 PO4110785475	LGE	4	40 ACE	SP	CRE	ED,ID	TD		2/9/2058
2021 PO4110785477	LGE	4	35 ACE	SP	CRE	ED,ID	TD		2/10/2058
2021 PO4112185477	LGE	4	40 ACE	SP	P	ED,ID	TD		2/11/2058

2021 PO4106085468	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/12/2058
2021 PO4107085469	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/13/2058
2021 PO4051984737	LGE	4	40 BRO	SP	CRE	ED,ID	TD	2/14/2058
2021 PO4052984733	LGE	4	40 BRO	SP	CRE	ED,ID	TD	2/15/2058
2021 PO4054284728	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/16/2058
2021 PO4055384723	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/17/2058
2021 PO4056584719	LGE	4	40 BRO	SP	CRE	ED,ID	TD	2/18/2058
2021 PO4114385480	LGE	3	45 ACE	SP	P	ED,ID	TD	2/19/2058
2021 PO4114485480	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/20/2058
2021 PO5417927286	KU	4	40 BRO	SP	CRE	ED,ID	TD	2/21/2058
2021 PO5409927089	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/22/2058
2021 PO5408426863	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/23/2058
2021 PO5407626639	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/24/2058
2021 PO5406526418	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/25/2058
2021 PO4106285463	LGE	4	40 ACE	SP	CRE	ED,ID	TD	2/26/2058
2021 PO4056184742	LGE	4	40 BRO	SP	CRE	ED,ID	TD	2/27/2058
2021 PO5761035466	KU	4	45 BRO	SP	CRE	ED,ID	TD	2/28/2058
2021 PO4049784745	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/1/2058
2021 PO5714434692	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/2/2058
2021 PO5737035063	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/3/2058
2021 PO5698534419	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/4/2058
2021 PO4107185412	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/5/2058
2021 PO4107385401	LGE	4	40 ACE	SP	P	ED,ID	TD	3/6/2058
2021 PO4107385394	LGE	4	35 ACE	SP	CRE	ED,ID	TD	3/7/2058
2021 PO4107085390	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/8/2058
2021 PO4107485391	LGE	4	40 ACE	SP	P	ED,ID	TD	3/9/2058
2021 PO4105285386	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/10/2058
2021 PO5411526259	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/11/2058
2021 PO5407025999	KU	5	35 BRO	SP	CRE	ED,ID	TD	3/12/2058
2021 PO4054784778	LGE	4	40 BRO	SP	A	ED,ID	TD	3/13/2058
2021 PO4106785437	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/14/2058
2021 PO4106985424	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/15/2058
2021 PO4053384740	LGE	4	40 BRO	SP	CRE	ED,ID	TD	3/16/2058
2021 PO5378124367	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/17/2058
2021 PO5412725623	KU	5	35 BRO	SP	CRE	ED,ID	TD	3/18/2058
2021 PO5413525425	KU	4	30 BRO	SP	CRE	ED,ID	TD	3/19/2058
2021 PO5411325832	KU	5	35 BRO	SP	CRE	ED,ID	TD	3/20/2058
2021 PO4103085419	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/21/2058
2021 PO4103685400	LGE	4	35 ACE	SP	CRE	ED,ID	TD	3/22/2058
2021 PO4103285408	LGE	4	40 ACE	SP	CRE	ED,ID	TD	3/23/2058
2021 PO4055784800	LGE	4	40 BRO	SP	CRE	ED,ID	TD	3/24/2058
2021 PO4056184812	LGE	4	40 BRO	SP	CRE	ED,ID	TD	3/25/2058
2021 PO4057384774	LGE	4	40 BRO	SP	CRE	ED,ID	TD	3/26/2058
2021 PO4057984788	LGE	4	40 BRO	SP	CRE	ED,EP,ID,RB	TD	3/27/2058
2021 PO4070084862	LGE	4	40 BRO	SP	CRE	ED,ID	TD	3/28/2058
2021 PO4068384857	LGE	4	40 BRO	SP	CRE	ED,ID	TD	3/29/2058
2021 PO4068184870	LGE	4	40 BRO	SP	CCA	ED,ID	TD	3/30/2058
2021 PO4103385463	LGE	4	40 ACE	SP	P	ED,ID	TD	3/31/2058
2021 PO4104585465	LGE	4	40 ACE	SP	CRE	ED,ID	TD	4/1/2058
2021 PO4102385461	LGE	3	45 ACE	SP	CRE	ED,ID	TD	4/2/2058
2021 PO5408525286	KU	4	35 BRO	SP	CRE	ED,ID	TD	4/3/2058
2021 PO4102685445	LGE	4	40 ACE	SP	P	ED,ID	TD	4/4/2058
2021 PO4102985447	LGE	6	25 ACE	SP	CRE	ED,ID,IP	TD	4/5/2058
2021 PO5364924214	KU	5	35 BRO	SP	CRE	ED,ID	TD	4/6/2058



2021	PO5342623992	KU	4	40 BRO	SP	CRE	ED,ID	TD		4/7/2058
2021	PO5355124119	KU	5	35 BRO	SP	CRE	ED,ID	TD		4/8/2058
2021	PO5750935664	KU	6	30 BRO	SP	CRE	ED,HH,ID,MD	BX	RP2	4/9/2058
2021	PO4110985471	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	4/10/2058
2021	PO4107985470	LGE	4	40 ACE	SP	P	ED,ID,IP	BD		4/11/2058
2021	PV8243467108	LGE	4	35 ACE	SP	P	ED,ID	BD		4/12/2058
2021	PO4110285502	LGE	4	35 ACE	SP	P	ED,ID	BD		4/13/2058
2021	PO4109985514	LGE	4	35 ACE	SP	P	ED,ID	BD		4/14/2058
2021	PO4109685495	LGE	4	40 ACE	SP	P	ED,ID	BD		4/15/2058
2021	PO4057684715	LGE	4	40 BRO	SP	CRE	ED,ID	BD		4/16/2058
2021	PO4054084884	LGE	4	35 BRO	SP	P	ED,ID	BD		4/17/2058
2021	PO4054484893	LGE	4	35 BRO	SP	P	ED,ID	BD		4/18/2058
2021	5342623992A	KU	5	40 BRO	SP	CRE	ED,ID	BD		4/19/2058
2021	PO5322423934	KU	4	45 BRO	SP	CRE	ED,ID	BD		4/20/2058
2021	PO4069884873	LGE	4	40 BRO	SP	CRE	ED,ID	BD		4/21/2058
2021	PO4069284852	LGE	4	40 BRO	SP	CRE	ED,ID	BD		4/22/2058
2021	PO4056384816	LGE	5	25 BRO	SP	P	ED,ID	BD		4/23/2058
2021	PO5403624443	KU	4	40 BRO	SP	CRE	ED,ID	BD		4/24/2058
2021	PO4104085436	LGE	4	35 ACE	SP	P	ED,ID	BD		4/25/2058
2021	PO4102885432	LGE	4	40 ACE	SP	CRE	ED,ID	BD		4/26/2058
2021	PO4106585448	LGE	4	40 ACE	SP	CRE	ED,ID	BD		4/27/2058
2021	PO4103585384	LGE	4	40 ACE	SP	CRE	ED,ID	BD		4/28/2058
2021	PO4054884903	LGE	4	35 BRO	SP	A		B		4/29/2058
2021	PO4112585384	LGE	4	35 ACE	SP	CCA		V		4/30/2058
2021	PO4111485363	LGE	4	40 ACE	SP	CCA		V		5/1/2058
2021	PO4105385356a	KU	4	30 ACE	SP	CCA		V		5/2/2058
2021	PO4109885403	LGE	4	30 ACE	SP	P		V		5/3/2058
2021	PO4110485415	LGE	1	25 ACE	SP	CRE		V		5/4/2058
2021	PO8389286933	F	4	40 BRO	SP	CCA		V		5/5/2058
2021	PO8398686813	KU	4	40 BRO	SP	CCA		V		5/6/2058
2021	PO4113085521	LGE	6	85E ACE	OT	CCA	ID	V		5/7/2058
2021	PO4048984754	LGE	4	30 BRO	SP	CRE	ED,ID,RB	TX	RR	5/8/2058
2021	PO4050184751	LGE	4	30 BRO	SP	CRE	ED,HH,ID,IP	TX	RR	5/9/2058
2021	PO8259685763	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/10/2058
2021	PO8249985407	KU	5	45 BRO	SP	CRE	ED,ID	TD		5/11/2058
2021	PO4106285331	LGE	4	35 ACE	SP	P	ED,ID	TD		5/12/2058
2021	PO4107485333	LGE	4	35 ACE	SP	P	ED,ID	TD		5/13/2058
2021	PO4110285341	LGE	4	30 ACE	SP	P	ED,ID,IP	TD		5/14/2058
2021	PO4110385336	LGE	4	40 ACE	SP	P	ED,ID	TD		5/15/2058
2021	PO4111385342	LGE	4	35 ACE	SP	P	ED,ID	TD		5/16/2058
2021	PO4111585338	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		5/17/2058
2021	PO4104085358	LGE	4	35 ACE	SP	P	ED,ID	TD		5/18/2058
2021	PO4105385356	LGE	4	35 ACE	SP	P	ED,ID	TD		5/19/2058
2021	PO4109685335	LGE	4	40 ACE	SP	CRE	ED,ID	TD		5/20/2058
2021	PO4108685339	LGE	4	35 ACE	SP	P	ED,ID	TD		5/21/2058
2021	PO4108485349	LGE	4	35 ACE	SP	P	ED,ID	TD		5/22/2058
2021	PO4113285341	LGE	4	40 ACE	SP	CRE	ED,ID	TD		5/23/2058
2021	PO4110985368	LGE	4	35 ACE	SP	P	ED,ID	TD		5/24/2058
2021	PO4109785366	LGE	4	35 ACE	SP	P	ED,ID	TD		5/25/2058
2021	PO4048784750	LGE	4	40 BRO	SP	CRE	ED,ID	TD		5/26/2058
2021	PO4112685398	LGE	4	40 ACE	SP	P	ED,ID	TD		5/27/2058
2021	PO4112185394	LGE	4	30 ACE	SP	CRE	ED,ID	TD		5/28/2058
2021	PO4112085399	LGE	4	40 ACE	SP	CRE	ED,ID	TD		5/29/2058
2021	PO4112185400	LGE	7	25 ACE	SP	CRE	ED,ID	TD		5/30/2058

2021 PO4112085406	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	5/31/2058	
2021 PO4111885417	LGE	3	45 ACE	SP	P	ED,ID	TD	6/1/2058	
2021 PO4111685430	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/2/2058	
2021 PO4111485442	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/3/2058	
2021 PO4111185458	LGE	4	40 ACE	SP	CRE	ED,ID	TD	6/4/2058	
2021 PO4049584751	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	6/5/2058	
2021 PO4109385387	LGE	4	35 ACE	SP	P	ED,ID	TD	6/6/2058	
2021 PO4109785395	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/7/2058	
2021 PO4111085398	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/8/2058	
2021 PO8361986406	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/9/2058	
2021 PO8366186576	KU	5	35 BRO	SP	CRE	ED,ID	TD	6/10/2058	
2021 PO4053884692	LGE	3	45 BRO	SP	CRE	ED,ID	TD	6/11/2058	
2021 PO4055284687	LGE	3	45 BRO	SP	P	ED,ID	TD	6/12/2058	
2021 PO4117385389	LGE	4	40 ACE	SP	P	ED,ID	TD	6/13/2058	
2021 PO4117185405	LGE	4	40 ACE	SP	P	ED,ID	TD	6/14/2058	
2021 PO4115085401	LGE	4	40 ACE	SP	P	ED,ID	TD	6/15/2058	
2021 PO4380985669	F	4	40 ACE	SP	CRE		V	6/16/2058	
2021 PO4381785675	F	4	40 ACE	SP	CRE		V	6/17/2058	
2021 PO4382785681	F	4	40 ACE	SP	CRE		V	6/18/2058	
2021 PO6371700084	F	4	40 ACE	SP	CRE		V	6/19/2058	
2021 PO4383585689	F	4	40 ACE	SP	CRE		V	6/20/2058	
2021 PO6364099883	F	4	40 ACE	SP	P		V	6/21/2058	
2021 PO6554599753	F	4	40 ACE	SP	CRE		V	6/22/2058	
2021 PO6553099827	F	4	40 ACE	SP	CRE		V	6/23/2058	
2021 PO6525899897	F	4	40 ACE	SP	CRE		V	6/24/2058	
2021 PO6542899887	F	4	40 ACE	SP	CRE		V	6/25/2058	
2021 PO4392485422	F	4	30 ACE	SP	CRE		V	6/26/2058	
2021 PO4393085426	F	4	40 ACE	SP	CCA		V	6/27/2058	
2021 PO4392385435	F	4	40 ACE	SP	CRE		V	6/28/2058	
2021 PO4391685444	F	4	40 ACE	SP	A		V	6/29/2058	
2021 PO4391085452	F	4	40 ACE	SP	A		V	6/30/2058	
2021 PO4389785456	F	4	30 ACE	SP	A		V	7/1/2058	
2021 PO4390385461	F	4	40 ACE	SP	CCA		V	7/2/2058	
2021 PO8120889956	KU	4	40 XXX	SP	S		V	7/3/2058	
2021 PO4384785701	F	4	40 ACE	SP	CRE		V	7/4/2058	
2021 PO4385185693	F	4	40 ACE	SP	CRE		V	7/5/2058	
2021 PO4385985684	F	4	40 ACE	SP	CRE		V	7/6/2058	
2021 PO4386185676	F	4	40 ACE	SP	CRE		V	7/7/2058	
2021 PO4386885670	F	4	40 ACE	SP	CRE		V	7/8/2058	
2021 PO4386685665	F	4	40 ACE	SP	CRE		V	7/9/2058	
2021 PO4385285666	F	4	40 ACE	SP	CRE		V	7/10/2058	
2021 PO4384385659	F	4	40 ACE	SP	CCA		V	7/11/2058	
2021 PO5803905701	KU	4	40 XXX	SP	CCA		V	7/12/2058	
2021 PO5821105307	KU	4	40 XXX	SP	CCA		V	7/13/2058	
2021 PO4382585646	F	4	40 ACE	SP	CRE		V	7/14/2058	
2021 PO4381785639	F	4	40 ACE	SP	CRE		V	7/15/2058	
2021 PO4380785633	F	4	40 ACE	SP	CRE		V	7/16/2058	
2021 PO4379885626	F	4	40 ACE	SP	CRE		V	7/17/2058	
2021 PO4378985619	F	4	40 ACE	SP	CRE		V	7/18/2058	
2021 PO4378085613	F	4	40 ACE	SP	CRE		V	7/19/2058	
2021 PO4383485652	F	4	40 ACE	SP	CRE		VX	PX	7/20/2058
2021 PO4382285708	F	4	40 ACE	SP	CRE		VX	PX	7/21/2058
2021 PO7744590754	KU	2	45 XXX	SP	CRE	ED,ID	BD	7/22/2058	
2021 PO4382385275	LGE	3	45 ACE	SP	CCA	ED,IP	BD	7/23/2058	

2021 PO6118998620	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD		7/24/2058
2021 PO6121298663	KU	1	55 ACE	SP	CRE	ED,ID,IP	BD		7/25/2058
2021 PO7797790765	KU	4	40 XXX	SP	CRE	ED,ID	BD		7/26/2058
2021 PO6305401413	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		7/27/2058
2021 PO6323301115	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD		7/28/2058
2021 PO6267800847	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		7/29/2058
2021 PO4370385420	LGE	3	45 ACE	SP	P	ED	BD		7/30/2058
2021 PO4369685412	LGE	1	65 ACE	SP	P	ED,IP	BD		7/31/2058
2021 PO6164698891	KU	1	55 ACE	SP	CRE	ED,ID,IP	BD		8/1/2058
2021 PO6109198766	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD		8/2/2058
2021 PO5803407138	KU	6	30 XXX	SP	CRE	ID	BD		8/3/2058
2021 PO8419588180	KU	4	40 XXX	SP	CRE	ED,ID	BD		8/4/2058
2021 PO4384685248	LGE	3	45 ACE	SP	P	ED	BD		8/5/2058
2021 PO4384285251	LGE	3	45 ACE	SP	P	ED	BD		8/6/2058
2021 PO4383985255	LGE	3	45 ACE	SP	P	ED	BD		8/7/2058
2021 PO4382385229	LGE	4	40 ACE	SP	P	ED,IP	BD		8/8/2058
2021 PO4383185235	LGE	4	40 ACE	SP	CRE	ED	BD		8/9/2058
2021 PO4375685357	LGE	4	40 ACE	SP	P	ED	BD		8/10/2058
2021 PO6376200689	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	8/11/2058
2021 PO6354700369	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	8/12/2058
2021 PO7724090845	KU	4	40 XXX	SP	S	ED	T		8/13/2058
2021 PO5815204762	KU	5	35 XXX	SP	CCA	ED	T		8/14/2058
2021 PO5826004960	KU	5	35 XXX	SP	CCA	ED	T		8/15/2058
2021 PO5802305100	KU	5	35 XXX	SP	CCA	ED	T		8/16/2058
2021 PO5827605116	KU	5	35 XXX	SP	CCA	ED	T		8/17/2058
2021 PO5769604932	KU	5	35 XXX	SP	CCA	ED	T		8/18/2058
2021 PO4411785422	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/19/2058
2021 PO4432485494	LGE	3	25 ACE	SP	CRE	ED,ID	TD		8/20/2058
2021 PO4416085557	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		8/21/2058
2021 PO4407885357	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		8/22/2058
2021 PO4407185372	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		8/23/2058
2021 PO4409185351	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		8/24/2058
2021 PO4410285360	LGE	4	35 BRO	SP	A	ED,ID	TD		8/25/2058
2021 4435185466-A	LGE	3	30 ACE	SP	A	ED	TD		8/26/2058
2021 PO4435185466	LGE	4	40 ACE	SP	CRE	ED	TD		8/27/2058
2021 PO4434585495	LGE	4	40 ACE	SP	CRE	ED,ID	TD		8/28/2058
2021 PO4409885567	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/29/2058
2021 PO4405085382	LGE	4	30 ACE	SP	A	ED,ID	TD		8/30/2058
2021 PO4435085457	LGE	4	40 ACE	DF	CRE	ED	TD		8/31/2058
2021 PO7860490865	KU	5	35 XXX	SP	CRE	ED,ID	TD		9/1/2058
2021 PO8307888110	KU	5	35 XXX	DF	CRE	ED,ID,IP,MD,SRC	TD		9/2/2058
2021 PO7807490419	KU	5	35 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD		9/3/2058
2021 PO8354687575	KU	5	40 XXX	DF	CRE	ED,ID	TD		9/4/2058
2021 PO8334987802	KU	5	35 XXX	DF	CRE	ED,ID,IP,MD,SRC	TD		9/5/2058
2021 PO8320987959	KU	4	40 XXX	DF	CRE	ED,ID,IP,MD,SRC	TD		9/6/2058
2021 PO4406685490	LGE	4	30 BRO	SP	A	ED,ID	TD		9/7/2058
2021 PO5864007559	KU	5	35 XXX	SP	CRE	ID	TD		9/8/2058
2021 PO5850307667	KU	5	35 XXX	SP	CRE	ED,ID,MD	TD		9/9/2058
2021 PO4433385445	LGE	4	40 ACE	SP	P	ED,ID	TD		9/10/2058
2021 PO7880790897	KU	6	35 XXX	SP	CRE	ED,ID,MD,SRC	TD		9/11/2058
2021 PO4407685503	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		9/12/2058
2021 PO4410985552	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		9/13/2058
2021 4434985445-a	LGE	3	40 ACE	SP	P	ED,ID	TD		9/14/2058
2021 PO4434985445	LGE	4	40 ACE	SP	P	ED,ID	TD		9/15/2058

2021 PO7826490355	KU	5	35 XXX	SP	CRE	ED,ID	TD	9/16/2058
2021 PO4434685417	LGE	4	40 ACE	SP	A	ED,ID	TD	9/17/2058
2021 PO7856690056	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	9/18/2058
2021 PO7885089960	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/19/2058
2021 PO7876589651	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	9/20/2058
2021 PO4434485402	LGE	4	40 ACE	SP	A	ED,ID	TD	9/21/2058
2021 PO7789190485	KU	5	35 XXX	SP	CRE	ED,ID	TD	9/22/2058
2021 PO7767290557	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	9/23/2058
2021 PO5789004832	KU	5	35 XXX	SP	CCA	ED	TD	9/24/2058
2021 PO7706190923	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	9/25/2058
2021 PO4409185457	LGE	3	45 BRO	SP	A	ED,ID	TD	9/26/2058
2021 PO4380885292	LGE	5	40 ACE	SP	P	ED,IP	TD	9/27/2058
2021 PO4392385401	LGE	4	40 ACE	SP	P	ED,ID	TD	9/28/2058
2021 PO4413885546	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR 9/29/2058
2021 PO6359700782	F	4	40 ACE	SP	P		V	9/30/2058
2021 PO6352700820	F	4	40 ACE	SP	CRE		V	10/1/2058
2021 PO6361400977	F	4	40 ACE	SP	CRE		V	10/2/2058
2021 PO6367000741	F	4	40 ACE	SP	P		V	10/3/2058
2021 4377685333a	F	4	40 ACE	SP	P		V	10/4/2058
2021 PO4385185277	F	1	60 ACE	SP	CCA		V	10/5/2058
2021 PO4386185298	F	UNK	55 ACE	SP	CRE		V	10/6/2058
2021 PO4386985301	F	3	50 ACE	SP	A		V	10/7/2058
2021 PO4377685333	F	3	45 ACE	SP	CCA		V	10/8/2058
2021 PO4376985342	F	3	45 ACE	SP	CCA		V	10/9/2058
2021 PO4376385349	F	3	45 ACE	SP	P		V	10/10/2058
2021 PO4374885368	LGE	3	45 ACE	SP	CCA	ED	V	10/11/2058
2021 PO4374685370	LGE	4	30 ACE	SP	CCA		V	10/12/2058
2021 PO4383085266	LGE	3	45 ACE	SP	CCA	ED	V	10/13/2058
2021 PO4383585264	F	4	35 ACE	SP	CCA		V	10/14/2058
2021 PO4384185277	F	4	40 ACE	SP	CRE		V	10/15/2058
2021 PO4383585285	F	4	45 ACE	SP	CRE		V	10/16/2058
2021 PO6383400646	F	4	40 ACE	SP	P		V	10/17/2058
2021 PO6366801074	F	4	40 ACE	SP	CRE		V	10/18/2058
2021 PO6380901000	F	4	40 ACE	SP	CRE		V	10/19/2058
2021 PO6393700926	F	4	40 ACE	SP	CRE		V	10/20/2058
2021 PO4388485348	F	4	40 ACE	SP	A		V	10/21/2058
2021 PO4388185339	F	4	40 ACE	SP	P		V	10/22/2058
2021 PO4387885324	F	4	40 ACE	SP	P		V	10/23/2058
2021 4387885324-a	F	1	50 ACE	SP	CCA		V	10/24/2058
2021 PO4374585321	F	4	30 ACE	SP	CCA		V	10/25/2058
2021 PO4375185313	F	4	40 ACE	SP	CCA		V	10/26/2058
2021 PO4375685308	F	4	30 ACE	SP	CCA		V	10/27/2058
2021 PO4376485323	F	4	40 ACE	SP	CCA		V	10/28/2058
2021 PO4376085320	F	4	40 ACE	SP	P		V	10/29/2058
2021 PO4376685312	F	4	35E ACE	SP	P		V	10/30/2058
2021 PO4377185315	LGE	4	20 ACE	SP	P		V	10/31/2058
2021 PO4379285250	LGE	4	40 ACE	SP	CCA		V	11/1/2058
2021 PO4368585401	LGE	4	30 ACE	SP	CCA		V	11/2/2058
2021 PO4382685240	LGE	4	30 ACE	SP	P		V	11/3/2058
2021 PO5758904970	KU	4	45 XXX	SP	CCA		V	11/4/2058
2021 PO5761905149	KU	4	45 XXX	SP	CCA		V	11/5/2058
2021 PO5781805140	KU	4	40 XXX	SP	CCA		V	11/6/2058
2021 PO4413885540	LGE	4	30 BRO	SP	CCA		V	11/7/2058
2021 PO4414485545	F	4	30 BRO	SP	CRE		V	11/8/2058

2021 PO4432885507	LGE	2	55 ACE	SP	CCA		V	11/9/2058
2021 PO4415485558	F	4	40 BRO	SP	CCA		V	11/10/2058
2021 PO4416185548	F	4	30 BRO	SP	A		V	11/11/2058
2021 PO4383885242	LGE	4	40 ACE	SP	CRE		V	11/12/2058
2021 PO4399185469	F	4	30 ACE	SP	P		V	11/13/2058
2021 PO4397385456	F	4	30 ACE	SP	P		V	11/14/2058
2021 PO4405485479	F	4	30 ACE	SP	CCA		V	11/15/2058
2021 PO6262099790	F	4	40 ACE	SP	CRE		V	11/16/2058
2021 PO6245799884	F	4	40 ACE	SP	CRE		V	11/17/2058
2021 PO6523300347	F	4	40 ACE	SP	CRE		V	11/18/2058
2021 PO6483800459	KU	4	30 ACE	SP	CRE		V	11/19/2058
2021 PO4390285385	F	3	45 ACE	SP	CCA		V	11/20/2058
2021 PO4389085376	F	4	40 ACE	SP	P		V	11/21/2058
2021 PO4393385409	F	4	40 ACE	SP	CCA		V	11/22/2058
2021 PO4410185443	F	4	40 BRO	SP	CRE		V	11/23/2058
2021 PO4381385286	LGE	3	45 ACE	SP	CCA	ED	V	11/24/2058
2021 PO4394685408	F	4	30 ACE	SP	A		V	11/25/2058
2021 PO4383085282	F	4	30 ACE	SP	P		V	11/26/2058
2021 PO4400185457	F	4	40 ACE	SP	CCA		V	11/27/2058
2021 PO4400185463	F	4	35 ACE	SP	P		V	11/28/2058
2021 PO4393685368	F	4	30 ACE	SP	CCA		V	11/29/2058
2021 PO4395785428	F	4	40 ACE	SP	A		V	11/30/2058
2021 PO4394985422	F	4	40 ACE	SP	P		V	12/1/2058
2021 PO6405200144	F	4	40 ACE	SP	CRE		V	12/2/2058
2021 PO4408385467	F	4	40 BRO	SP	A		V	12/3/2058
2021 PO6398700179	F	4	40 ACE	SP	P		V	12/4/2058
2021 PO6391900218	F	4	40 ACE	SP	P		V	12/5/2058
2021 PO6380100285	F	4	40 ACE	SP	CRE		V	12/6/2058
2021 PO6367700297	F	4	40 ACE	SP	CRE		V	12/7/2058
2021 PO6339100446	F	4	40 ACE	SP	CRE		V	12/8/2058
2021 PO5798504925	KU	4	40 XXX	SP	CCA		V	12/9/2058
2021 PO5808104821	KU	4	40 XXX	SP	CCA		V	12/10/2058
2021 PO5812204912	KU	4	40 XXX	SP	CCA		V	12/11/2058
2021 PO5817604996	KU	4	40 XXX	SP	CCA		V	12/12/2058
2021 PO5789405025	KU	4	40 XXX	SP	CCA		V	12/13/2058
2021 PO4382785297	F	4	40 ACE	SP	CRE		V	12/14/2058
2021 PO4384185290	F	UNK	55 ACE	SP	CRE		V	12/15/2058
2021 PO4383285301	F	UNK	55 ACE	SP	CRE		V	12/16/2058
2021 PO4382785316	F	4	30 ACE	SP	CRE		V	12/17/2058
2021 PO4382085315	F	UNK	55 ACE	SP	CRE		V	12/18/2058
2021 PO4379785344	F	UNK	55 ACE	SP	CRE		V	12/19/2058
2021 PO4381685329	F	4	30 ACE	SP	CRE		V	12/20/2058
2021 PO4380985329	F	2	55 ACE	SP	CRE		V	12/21/2058
2021 PO4380485343	F	4	35 ACE	SP	CRE		V	12/22/2058
2021 PO4379385356	F	4	30 ACE	SP	P		V	12/23/2058
2021 PO4378985360	F	4	30 ACE	SP	P		V	12/24/2058
2021 PO4378585357	F	2	60 ACE	SP	CCA		V	12/25/2058
2021 PO4377885366	F	1	55 ACE	SP	CCA		V	12/26/2058
2021 PO6111669588	LGE	1	55 BRO	SP	CCA		V	12/27/2058
2021 PO4897685638	LGE	1	50 BRO	SP	CCA		V	12/28/2058
2021 PO0935066018	LGE	4	35 ACE	SP	CCA		V	12/29/2058
2021 PO6407100850	KU	4	40 ACE	SP	P		V	12/30/2058
2021 PO6104898755	KU	3	45 ACE	SP	CCA		V	12/31/2058
2021 PO6113298749	KU	2	50 ACE	SP	CCA		V	1/1/2059

2021 PO6096098804	KU	3	50 ACE	SP	CCA	V	1/2/2059
2021 PO4368885416	LGE	4	35 ACE	SP	CCA	V	1/3/2059
2021 PO4434885433	LGE	3	45 ACE	SP	CCA	V	1/4/2059
2021 PV0515598219	LGE	4	40 ACE	SP	CCA	V	1/5/2059
2021 PO4372185421	LGE	4	30 ACE	SP	P	V	1/6/2059
2021 PO4372385421	LGE	4	35 ACE	SP	CCA	V	1/7/2059
2021 PO6358501761	F	4	40 ACE	SP	CRE	V	1/8/2059
2021 P07920290958A	KU	3	40 XXX	SP	S	V	1/9/2059
2021 PO6355802126	F	4	40 ACE	SP	CRE	V	1/10/2059
2021 PO6398902544	F	4	40 ACE	SP	CRE	V	1/11/2059
2021 PO6151999109	F	2	50 ACE	SP	CCA	V	1/12/2059
2021 PO6154598956	F	1	60 ACE	SP	CCA	V	1/13/2059
2021 PO6148699318	F	4	40 ACE	SP	CRE	V	1/14/2059
2021 PO5767908014	F	5	35 XXX	SP	CCA	V	1/15/2059
2021 PO5767907967	F	4	40 XXX	SP	CRE	V	1/16/2059
2021 PO5763507833	F	4	40 XXX	SP	CCA	V	1/17/2059
2021 PO5807507889	F	4	45 XXX	SP	P	V	1/18/2059
2021 PO5830907807	F	4	45 XXX	SP	P	V	1/19/2059
2021 PO5756507763	F	4	40 XXX	SP	CCA	V	1/20/2059
2021 PO5748607711	F	4	40 XXX	SP	CCA	V	1/21/2059
2021 PO5744407616	F	4	40 XXX	SP	CCA	V	1/22/2059
2021 PO5738607481	F	4	40 XXX	SP	CCA	V	1/23/2059
2021 PO5733707367	F	4	40 XXX	SP	CCA	V	1/24/2059
2021 PO5830904592	KU	5	35 XXX	SP	CCA	V	1/25/2059
2021 PO4407585478	F	4	40 BRO	SP	CRE	V	1/26/2059
2021 PO4378485243	LGE	4	40 ACE	SP	CCA	V	1/27/2059
2021 PO4381585269	LGE	4	35 ACE	SP	CCA	V	1/28/2059
2021 PO4379985256	LGE	4	35 ACE	SP	CCA	V	1/29/2059
2021 PO4380885263	LGE	4	35 ACE	SP	CCA	V	1/30/2059
2021 PO4406085493	F	4	30 BRO	SP	CCA	V	1/31/2059
2021 PO6326699411	F	4	40 ACE	SP	CRE	V	2/1/2059
2021 PO6313399488	KU	4	40 ACE	SP	P	V	2/2/2059
2021 PO6306999527	F	4	40 ACE	SP	P	V	2/3/2059
2021 PO6300399567	F	4	40 ACE	SP	CRE	V	2/4/2059
2021 PO4406385494	F	4	40 BRO	SP	CRE	V	2/5/2059
2021 PO6287499641	F	4	40 ACE	SP	CRE	V	2/6/2059
2021 PO6275199715	F	4	40 ACE	SP	P	V	2/7/2059
2021 PO4397585549	F	4	30 ACE	SP	A	V	2/8/2059
2021 4399885545-a	F	3	30 ACE	SP	A	V	2/9/2059
2021 4400485538-A	F	4	30 ACE	SP	CRE	V	2/10/2059
2021 PO4398585554	F	4	30 ACE	SP	A	V	2/11/2059
2021 PO6349499416	F	4	40 ACE	SP	CRE	V	2/12/2059
2021 PO6345999488	F	3	45 ACE	SP	CRE	V	2/13/2059
2021 PO8397487970	KU	4	40 XXX	SP	S	V	2/14/2059
2021 PO4394385523	F	4	30 ACE	SP	CRE	V	2/15/2059
2021 PO4395585517	F	4	30 ACE	SP	A	V	2/16/2059
2021 PO4395285529	F	4	30 ACE	SP	A	V	2/17/2059
2021 PO1188167576	LGE	3	45 BRO	SP	CCA	V	2/18/2059
2021 PO4404985513	LGE	4	40 BRO	SP	CCA	V	2/19/2059
2021 PO4402985402	F	3	45 ACE	SP	CCA	V	2/20/2059
2021 PO4402285411	F	4	40 ACE	SP	CCA	V	2/21/2059
2021 PO4401985553	F	4	40 BRO	SP	A	V	2/22/2059
2021 PO4402485432	F	4	30 ACE	SP	CCA	V	2/23/2059
2021 PO4510288093	LGE	3	45 ACE	SP	CCA	V	2/24/2059

2021	PO5181011994	F	4	40 XXX	SP	CRE			V	2/25/2059
2021	PO8506663019	ODP	5	35 XXX	SP	CRE	ID		TD	2/26/2059
2021	PO8540262891	ODP	4	45 XXX	SP	CCA			V	2/27/2059
2021	PO8529562942	ODP	4	45 XXX	SP	CCA			V	2/28/2059
2021	PO8570162906	ODP	6	30 XXX	SP	CRE			V	3/1/2059
2021	PO8551262869	ODP	4	40 XXX	SP	CRE	ID		TD	3/2/2059
2021	PO8358462967	F	4	40 XXX	SP	P			V	3/3/2059
2021	PO8361963116	ODP	4	40 XXX	SP	CCA			V	3/4/2059
2021	PO8348062661	ODP	4	40 XXX	SP	CRE	ID		TD	3/5/2059
2021	PO8341662849	ODP	5	35 XXX	SP	CRE	ID		TD	3/6/2059
2021	PO8329262735	F	4	40 XXX	SP	CRE			V	3/7/2059
2021	PO8488279481	F	4	40 ACE	SP	CRE			V	3/8/2059
2021	PO8468379486	F	4	40 ACE	SP	P			V	3/9/2059
2021	PO4510988081	LGE	3	45 ACE	SP	CCA			V	3/10/2059
2021	PO4511688071	LGE	3	45 ACE	SP	CCA			V	3/11/2059
2021	PO8463679488	F	4	40 ACE	SP	CRE			V	3/12/2059
2021	PO4513288066	LGE	3	45 ACE	SP	CCA			V	3/13/2059
2021	PO8453379491	F	4	40 ACE	SP	P			V	3/14/2059
2021	PO8441179451	KU	6	30 ACE	SP	CCA			V	3/15/2059
2021	PO8441679496	F	4	40 ACE	SP	P			V	3/16/2059
2021	PO7886161345	ODP	4	40 BRN	SP	CRE	ED,ID,IP		TD	3/17/2059
2021	PO7835961348	ODP	5	35 BRN	SP	CRE	ED,ID,IP		TD	3/18/2059
2021	PO7888260881	ODP	4	40 BRN	SP	CRE	ED,ID,IP		TD	3/19/2059
2021	PO7865461714	F	4	40 BRN	SP	S			V	3/20/2059
2021	PO7855661646A	ODP	5	30 BRN	SP	P	ED,ID		BD	3/21/2059
2021	PO7855661646	ODP	4	40 BRN	SP	CRE	ED,ID		TD	3/22/2059
2021	PO8429879499	F	4	40 ACE	SP	P			V	3/23/2059
2021	PO8415779504	F	4	40 ACE	SP	P			V	3/24/2059
2021	PO8406679508	F	4	40 ACE	SP	P			V	3/25/2059
2021	PO4511788108	LGE	4	35 ACE	SP	P			V	3/26/2059
2021	PO4513488080	LGE	4	35 ACE	SP	A	ED,ID		BD	3/27/2059
2021	PO4512688093	LGE	4	35 ACE	SP	A	ED,ID		BD	3/28/2059
2021	PO8379979562	F	5	35 ACE	SP	CRE			V	3/29/2059
2021	PO8396079680	F	4	40 ACE	SP	CRE			V	3/30/2059
2021	PO8378879516	KU	4	40 ACE	SP	CRE			V	3/31/2059
2021	PO5865822894	KU	3	45 UNK	SP	CRE			BD	4/1/2059
2021	PO5858722825	KU	2	50 UNK	SP	CRE			BD	4/2/2059
2021	PO5851322753	KU	3	45 UNK	SP	CRE			BD	4/3/2059
2021	PO5203811983	F	4	40 XXX	SP	CRE			V	4/4/2059
2021	PO5199111986	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	PX	4/5/2059
2021	PO5201311915	F	4	40 XXX	SP	CRE			V	4/6/2059
2021	PO5198211830	F	4	40 KOP	SP	P			V	4/7/2059
2021	PO8308879777	KU	3	50 ACE	SP	CRE	ED,ID		BD	4/8/2059
2021	PO5833222503	KU	2	50 UNK	SP	CRE			T	4/9/2059
2021	PO5841622542	KU	4	40 UNK	SP	CRE			T	4/10/2059
2021	PO5836622559	KU	2	50 UNK	SP	CRE			T	4/11/2059
2021	PO5844722675	KU	3	45 UNK	SP	CRE			BD	4/12/2059
2021	PO4514288068	LGE	4	35 ACE	SP	P	ED,ID		BD	4/13/2059
2021	PO8395379511	F	3	45 ACE	SP	P			V	4/14/2059
2021	PO9702422618	KU	4	40 BRN	SP	CRE	ID		T	4/15/2059
2021	PO8394679382	F	4	40 ACE	SP	CRE			V	4/16/2059
2021	PO8394179277	F	4	40 ACE	SP	CRE			V	4/17/2059
2021	PO8393479152	F	4	40 ACE	SP	CRE			V	4/18/2059
2021	PO8392879025	F	5	35 ACE	SP	CRE			V	4/19/2059

2021	PO8392078904	F	5	35 ACE	SP	CRE		V	4/20/2059
2021	PO4515188077	LGE	4	40 ACE	SP	CRE	ED,ID,MD	TD	4/21/2059
2021	PO4515288079	LGE	4	45 ACE	SP	CRE	ED,ID	BD	4/22/2059
2021	PO9620721784	KU	4	40 BRN	SP	CRE	ID	TD	4/23/2059
2021	PO5192511678	F	4	40 XXX	SP	CRE		V	4/24/2059
2021	PO5184511462	F	4	40 XXX	SP	CRE		V	4/25/2059
2021	PO5187611546	F	4	40 XXX	SP	CRE		V	4/26/2059
2021	PO8391378770	F	5	35 ACE	SP	CRE	ED,ID,IP	V	4/27/2059
2021	PO8395578636	KU	6	30 ACE	SP	CRE	ED,ID	BD	4/28/2059
2021	PO8390678658	F	5	35 ACE	SP	CRE		V	4/29/2059
2021	PO8390178568	F	4	40 ACE	SP	P		V	4/30/2059
2021	PO8385478517	F	4	40 ACE	SP	CRE		V	5/1/2059
2021	PO8389478446	F	5	35 ACE	SP	CRE		V	5/2/2059
2021	PO8388778323	F	5	35 ACE	SP	CRE		V	5/3/2059
2021	PO8384178291	KU	4	40 ACE	SP	CCA		V	5/4/2059
2021	PO9644322047	KU	4	40 BRN	SP	CRE	ID	TD	5/5/2059
2021	PO9594521546	KU	4	40 BRN	SP	CRE	ID	TD	5/6/2059
2021	PO0461643905	KU	4	40 BRN	SP	CRE	ID	TD	5/7/2059
2021	PO0480944716	KU	4	40 BRN	SP	CRE	ID	TD	5/8/2059
2021	PO8370278189	KU	6	30 ACE	SP	CRE	ED,ID	BD	5/9/2059
2021	PO4514288072	LGE	4	40 ACE	SP	CRE	ED,ID	TD	5/10/2059
2021	PO5808722044	KU	3	50 UNK	SP	CCA		V	5/11/2059
2021	PO5809922105	KU	5	35 UNK	SP	CCA		V	5/12/2059
2021	PO7834561571	ODP	4	40 BRN	SP	CRE		V	5/13/2059
2021	PO7834161669A	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	5/14/2059
2021	PO7834161669	ODP	6	30 BRN	SP	CRE	ED,ID	TD	5/15/2059
2021	PO7812361343	ODP	5	35 BRN	SP	S		V	5/16/2059
2021	PO7798761837	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	5/17/2059
2021	PO7796762107	ODP	4	45 BRN	SP	S		V	5/18/2059
2021	PO7800561446	ODP	4	40 BRN	SP	CRE	ED,ID	BD	5/19/2059
2021	PO7798161339	ODP	5	35 BRN	SP	S		V	5/20/2059
2021	PO7836861049	ODP	5	35 BRN	SP	CRE	ED,ID	BD	5/21/2059
2021	PO7832360748	ODP	4	45 BRN	SP	S		V	5/22/2059
2021	PO5808122161	F	4	40 UNK	SP	CRE		V	5/23/2059
2021	PO5815022323	KU	3	45 UNK	SP	CCA		V	5/24/2059
2021	PO5812222207	F	3	45 UNK	SP	CRE		V	5/25/2059
2021	PO5805522225	KU	3	45 UNK	SP	CRE	RB	BX PX	5/26/2059
2021	PO5760922589	KU	5	35 UNK	SP	CRE		BD	5/27/2059
2021	PO5768222571	KU	5	35 UNK	SP	CCA		V	5/28/2059
2021	PO5771522505	F	3	45 UNK	SP	A		V	5/29/2059
2021	PO5778922543	KU	5	35 UNK	SP	CRE		BD	5/30/2059
2021	PO5783022533	KU	4	40 UNK	SP	CCA		V	5/31/2059
2021	PO5786122524	KU	4	40 UNK	SP	CRE		BD	6/1/2059
2021	PO1340853477	KU	4	40 BRN	SP	CRE	ID	TD	6/2/2059
2021	PO5794122505	KU	5	35 UNK	SP	CRE		BD	6/3/2059
2021	PO5799422551	KU	5	35 UNK	SP	CRE		BD	6/4/2059
2021	PO1361253025	KU	4	40 BRN	SP	CRE	ID	TD	6/5/2059
2021	PO5798022496	KU	5	35 UNK	SP	CRE		T	6/6/2059
2021	PO5816622484	KU	5	35 UNK	SP	CRE		BD	6/7/2059
2021	PO5819522522	KU	4	35 UNK	SP	CCA		V	6/8/2059
2021	PO5817622445	KU	4	40 UNK	SP	CCA		V	6/9/2059
2021	PO5806022480	KU	4	40 UNK	SP	CRE		BD	6/10/2059
2021	PO5808522468	KU	4	40 UNK	SP	CRE		BD	6/11/2059
2021	PO5807122410	F	4	40 UNK	SP	CRE		V	6/12/2059



2021 PO8297680607	KU	3	50 ACE	SP	CRE	ED,ID	BD	6/13/2059
2021 PO8296680559	KU	2	65 ACE	SP	CCA		V	6/14/2059
2021 PO8295880389	KU	2	60 ACE	SP	CRE	ED,ID	BD	6/15/2059
2021 PO8298580240	KU	6	30 ACE	SP	CRE	ED,ID	BD	6/16/2059
2021 PO8294580226	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/17/2059
2021 PO8298780051	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/18/2059
2021 PO8319963854	ODP	4	40 XXX	SP	CRE	ID	TD	6/19/2059
2021 PO8343663846	ODP	4	40 XXX	SP	CRE	ID	TD	6/20/2059
2021 PO8358963512	ODP	6	30 XXX	SP	CCA	ED	T	6/21/2059
2021 PO8371063520	ODP	2	40 XXX	SP	CRE	ID,IP	TD	6/22/2059
2021 PO8374963357	ODP	4	40 XXX	SP	CCA		V	6/23/2059
2021 PO8382263574	ODP	4	40 XXX	SP	CCA		V	6/24/2059
2021 PO8371963238	ODP	5	35 XXX	SP	CCA		V	6/25/2059
2021 PO8372563215	ODP	2	60 XXX	SP	CCA		V	6/26/2059
2021 PO8375663109	F	4	40 XXX	SP	P		V	6/27/2059
2021 PO8378063037	ODP	5	35 XXX	SP	CRE	ID	TD	6/28/2059
2021 PO8377362802	ODP	5	30 XXX	SP	CRE	ID	TD	6/29/2059
2021 PO8383262862	ODP	4	40 XXX	SP	CRE	ID	TD	6/30/2059
2021 PO8389962671	ODP	4	40 XXX	SP	CRE	ID	TD	7/1/2059
2021 PO1342053217	KU	3	45 BRN	SP	CCA		V	7/2/2059
2021 PO1360153649	F	3	45 SWP	SP	P		V	7/3/2059
2021 PO4444788184	LGE	4	35 BRO	SP	CRE		V	7/4/2059
2021 PO4450488130	LGE	4	35 BRO	SP	CRE		V	7/5/2059
2021 PO8312980115	KU	6	30 ACE	SP	CRE	ED,ID	TD	7/6/2059
2021 PO4516988050	LGE	3	50 ACE	SP	P	ED,ID,RB	BD	7/7/2059
2021 PO4516688051	LGE	4	40 ACE	SP	CCA		V	7/8/2059
2021 PO4516188048	LGE	4	40 ACE	SP	CRE	ED,ID	TD	7/9/2059
2021 PO4454987854	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/10/2059
2021 PO5724122600	KU	4	40 UNK	SP	CRE		BD	7/11/2059
2021 PO5726222620	KU	3	40 UNK	SP	CRE		BD	7/12/2059
2021 PO4517288055	LGE	4	30 ACE	SP	A	ED,ID	BD	7/13/2059
2021 PO8296379726	KU	4	40 ACE	SP	CRE	ED,ID	TD	7/14/2059
2021 PO8296679780	KU	5	35 ACE	SP	CRE	ED,ID	BD	7/15/2059
2021 PO8308879777a	KU	6	30 ACE	SP	CRE	ED,ID	TD	7/16/2059
2021 PO1336153703	F	3	45 SWP	SP	P		V	7/17/2059
2021 PO8284562831	ODP	4	40 BRN	SP	CRE	ED,ID	BD	7/18/2059
2021 PO8268562701	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	7/19/2059
2021 PO8276762633	ODP	5	35 BRN	SP	CRE	HH,ID,RB	X	7/20/2059
2021 PO8268163009	ODP	4	40 BRN	SP	CRE	ED,ID	BD	7/21/2059
2021 PO8253863302	ODP	4	45 BRN	SP	CRE	ED,ID	TD	7/22/2059
2021 PO8252963524	ODP	4	45 BRN	SP	S		V	7/23/2059
2021 PO8265764134	ODP	6	30 BRN	SP	S		V	7/24/2059
2021 PO8325564322	ODP	6	30 BRN	SP	S		V	7/25/2059
2021 PO8317064159	ODP	4	40 BRN	SP	CRE	ED,ID	TD	7/26/2059
2021 PO8271964123	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	7/27/2059
2021 PO8273964361	ODP	4	40 BRN	SP	CRE	ED,ID	TD	7/28/2059
2021 PO8272764552	ODP	4	40 BRN	SP	CRE		V	7/29/2059
2021 PO1312153722	F	3	45 SWP	SP	P		V	7/30/2059
2021 PO1284453285	KU	5	45 SWP	ST	CRE		V	7/31/2059
2021 PO4452188119	LGE	4	40 BRO	SP	P	ED,ID	TD	8/1/2059
2021 PO5215611734	F	4	40 XXX	SP	CRE		V	8/2/2059
2021 PO5219211834	F	6	30 XXX	SP	CRE		V	8/3/2059
2021 PO5223211944	KU	6	30 XXX	SP	CCA		V	8/4/2059
2021 PO5212711653	F	4	40 XXX	SP	CRE		V	8/5/2059

2021 PO4515488043	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/6/2059
2021 PO5744422631	KU	4	40 UNK	SP	CRE		BD	8/7/2059
2021 PO5741022498	KU	6	30 UNK	SP	CCA		V	8/8/2059
2021 PO5766722516	F	4	40 UNK	SP	CRE		V	8/9/2059
2021 PO5790922204	F	5	40 MAR	SP	P		V	8/10/2059
2021 PO4452288114	LGE	4	40 BRO	SP	P	ED,ID	BD	8/11/2059
2021 PO4452588107	LGE	4	40 BRO	SP	CCA		V	8/12/2059
2021 PO4452888099	LGE	3	45 BRO	SP	CCA		V	8/13/2059
2021 PO4453088095	LGE	4	40 BRO	SP	P	ED,ID	BD	8/14/2059
2021 PO5793622255	KU	4	40 UNK	SP	CRE	ED,ID	BD	8/15/2059
2021 PO5784022222	KU	4	40 BRO	SP	S		V	8/16/2059
2021 PO5780522288	KU	4	40 UNK	SP	CRE	ED,ID	BD	8/17/2059
2021 PO5765822325	KU	4	40 UNK	SP	CRE	ED,ID	BD	8/18/2059
2021 PO5769522316	KU	4	40 KOP	SP	S		V	8/19/2059
2021 PO5765922268	KU	5	35 UNK	SP	CRE	ID	TD	8/20/2059
2021 PO5753322608	KU	5	35 UNK	SP	CRE		T	8/21/2059
2021 PO5751522559	F	4	40 UNK	SP	CRE		V	8/22/2059
2021 PO5739222591	F	4	40 UNK	SP	CRE	ED,ID	VX	8/23/2059
2021 PO4514488038	LGE	3	45 ACE	SP	CCA		V	8/24/2059
2021 PO4513788033	LGE	3	45 ACE	SP	CCA		V	8/25/2059
2021 PO4512888027	LGE	4	40 ACE	SP	CCA	ED,ID	TD	8/26/2059
2021 PO4452188101	LGE	4	30 BRO	SP	P	ED,ID,IP	TD	8/27/2059
2021 PO4452688095	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	8/28/2059
2021 PO4451888093	LGE	7	25 BRO	SP	CRE	ED,ID	BD	8/29/2059
2021 PO5756022601	KU	5	35 UNK	SP	CRE		T	8/30/2059
2021 PO4451488090	LGE	4	40 BRO	SP	A	ED,ID	BD	8/31/2059
2021 PO4450988099	LGE	4	35 BRO	SP	P	ED,ID	BD	9/1/2059
2021 PO4450288108	LGE	4	35 BRO	SP	P	ED,ID	BD	9/2/2059
2021 PO8367079741	F	4	40 ACE	SP	P		V	9/3/2059
2021 PO4462188042	LGE	4	35 BRO	SP	A	ID	BD	9/4/2059
2021 PO4461988047	LGE	4	35 BRO	SP	A	ID	BD	9/5/2059
2021 PO4511888021	LGE	4	40 ACE	SP	P	ED,ID	BD	9/6/2059
2021 PO4510988015	LGE	4	40 ACE	SP	CCA		V	9/7/2059
2021 PO1291153539	KU	4	40 UNK	SP	CRE	ID	TD	9/8/2059
2021 PO1277252840	KU	5	35 SWP	SP	CRE	ID	TD	9/9/2059
2021 PO4509488011	LGE	4	30 ACE	SP	A	ED,ID	BD	9/10/2059
2021 PO4509888008	LGE	4	35 ACE	SP	A	ED,ID	BD	9/11/2059
2021 PO5774622876	KU	5	35 UNK	SP	CCA		T	9/12/2059
2021 PO5210011569	F	4	40 XXX	SP	CRE		V	9/13/2059
2021 PO5204711416	F	5	35 XXX	SP	CRE		V	9/14/2059
2021 PO5202311367	F	5	30 KOP	SP	P		V	9/15/2059
2021 PO5755222353	KU	4	40 UNK	SP	CRE	ID	BD	9/16/2059
2021 PO5750822305	KU	6	30 UNK	SP	CRE	ID	BD	9/17/2059
2021 PO5742922384	KU	4	40 UNK	SP	CRE	ID	BD	9/18/2059
2021 PO5795722765	KU	4	40 UNK	SP	CRE		T	9/19/2059
2021 PO4472388013	LGE	4	40 BRO	SP	A	ED,ID,JP	TD	9/20/2059
2021 PO4504588056	LGE	4	45 ACE	SP	CRE	ED,ID,MD	TD	9/21/2059
2021 PO1275352670	KU	5	35 SWP	SP	CRE		V	9/22/2059
2021 PO1256553231	KU	4	45 INP	SP	CRE	ID	TD	9/23/2059
2021 PO4450188111	LGE	4	35 BRO	SP	CRE	ED,ID,JP	BD	9/24/2059
2021 PO4449688118	LGE	4	40 BRO	SP	P	ED,ID	BD	9/25/2059
2021 PO4449388128	F	4	30 BRO	SP	CRE		V	9/26/2059
2021 PO5803122810	KU	4	40 UNK	SP	CRE		BD	9/27/2059
2021 PO5811622763	KU	4	40 UNK	SP	CRE		BD	9/28/2059

2021 PO5816122638	KU	3	50 UNK	SP	CRE		BD	9/29/2059
2021 PO8313379781a	KU	5	35 ACE	SP	CRE	ED,ID	TD	9/30/2059
2021 PO8325779769	KU	5	35 ACE	SP	CRE	ED,ID	TD	10/1/2059
2021 PO8313379781	KU	5	35 ACE	SP	CRE	ED,ID	BD	10/2/2059
2021 PO5732322412	KU	6	30 UNK	SP	CCA		V	10/3/2059
2021 PO5731222353	KU	5	35 UNK	SP	CRE	ID	TD	10/4/2059
2021 PO5728722356	KU	3	45 BRN	SP	S		V	10/5/2059
2021 PO5727922423	KU	4	40 BRN	SP	S		V	10/6/2059
2021 PO5722122438	KU	6	30 BRN	SP	S		V	10/7/2059
2021 PO5717422388	KU	2	40 UNK	SP	CRE	ID	TD	10/8/2059
2021 PO5705022163	KU	4	40 UNK	SP	CRE	ID	TD	10/9/2059
2021 PO5237811629	F	5	35 BRN	SP	P		V	10/10/2059
2021 PO4504188064	LGE	4	45 ACE	SP	CRE	ED,ID	TD	10/11/2059
2021 PO4471588004	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	10/12/2059
2021 PO5826822845	KU	4	40 UNK	SP	CRE		BD	10/13/2059
2021 PO5829422947	KU	4	40 UNK	SP	CRE		BD	10/14/2059
2021 PO5829922680	KU	4	40 UNK	SP	CCA		V	10/15/2059
2021 PO5824022733	KU	4	40 UNK	SP	CRE		BD	10/16/2059
2021 PO5834522864	KU	5	35 UNK	SP	CRE		T	10/17/2059
2021 PO5832322783	F	4	40 UNK	SP	CRE		V	10/18/2059
2021 PO5839822758	F	4	40 UNK	SP	CRE		V	10/19/2059
2021 PO5825122777	KU	5	35 UNK	SP	CRE		V	10/20/2059
2021 PO5831123014	KU	5	35 UNK	SP	CRE		BD	10/21/2059
2021 PO4503588072	LGE	4	45 ACE	SP	A	ED,ID	BD	10/22/2059
2021 PO5235311558	F	5	35 XXX	SP	CRE		V	10/23/2059
2021 PO5231011449	F	5	35 XXX	SP	CRE		V	10/24/2059
2021 PO5255011340	F	4	40 XXX	SP	CRE		V	10/25/2059
2021 PO8308179544	KU	3	50 ACE	SP	CRE	ED,ID	TD	10/26/2059
2021 PO8314979660	KU	5	35 ACE	SP	CRE	ED,ID	BD	10/27/2059
2021 PO8314779542	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/28/2059
2021 PO4470488007	F	4	35 BRO	SP	A		V	10/29/2059
2021 PO4004886174	F	4	30 ACE	SP	CCA		V	10/30/2059
2021 PO4004786182	F	4	30 ACE	SP	CRE		V	10/31/2059
2021 PO4005086179	F	3	45 ACE	SP	CCA		V	11/1/2059
2021 PO4005686196	F	3	45 ACE	SP	CCA		V	11/2/2059
2021 PO4006286209	F	3	45 ACE	SP	CCA		V	11/3/2059
2021 PO4006786224	F	3	45 ACE	SP	CCA		V	11/4/2059
2021 PO4006786241	F	6	30 ACE	SP	CRE		V	11/5/2059
2021 PO4007386238	F	3	45 ACE	SP	CCA		V	11/6/2059
2021 PO4007386254	F	4	30 ACE	SP	CRE		V	11/7/2059
2021 PO4007886252	F	3	45 ACE	SP	CCA		V	11/8/2059
2021 PO8487314617	KU	4	45 ACW	SP	CRE	ED,ID	BD	11/9/2059
2021 PO8499814629	KU	4	40 ACW	SP	CRE	ED,ID	BD	11/10/2059
2021 PO8499814629	KU	4	45 ACW	SP	CRE	ED,ID	TD	11/11/2059
2021 PO8497114116	KU	4	40 ACW	SP	CRE		V	11/12/2059
2021 PO8465214414	KU	4	45 ACW	SP	S		V	11/13/2059
2021 PO8541315870	KU	4	45 ACW	SP	CRE	ED,ID	BX	11/14/2059
2021 PO8530115873	KU	4	40 ACW	SP	S		V	11/15/2059
2021 PO9147215263	KU	5	35 ACW	SP	S		V	11/16/2059
2021 PO4008386266	F	3	45 ACE	SP	CCA		V	11/17/2059
2021 PO4008986280	F	3	45 ACE	SP	CCA		V	11/18/2059
2021 PO4009586294	F	3	45 ACE	SP	CCA		V	11/19/2059
2021 PO4011186323	F	3	45 ACE	SP	CCA		V	11/20/2059
2021 PO4010086310	F	3	45 ACE	SP	CCA		V	11/21/2059

2021 PO4012186336	F	3	45 ACE	SP	CCA		V	11/22/2059
2021 PO4011786331	F	5	35 ACE	SP	CRE		V	11/23/2059
2021 PO5597456864	KU	4	40 BRN	SP	CRE	ID	BD	11/24/2059
2021 PO5602056896	KU	5	35 BRN	SP	CRE	ID	BD	11/25/2059
2021 PO7317574425	LGE	4	30 ACE	SP	CCA		V	11/26/2059
2021 PO7319674350	LGE	3	45 ACE	SP	CCA		V	11/27/2059
2021 PO4018386264	LGE	4	35 ACE	SP	CCA		V	11/28/2059
2021 PO7310574216	LGE	4	35 ACE	SP	CCA		V	11/29/2059
2021 PO7315174109	LGE	4	30 ACE	SP	CCA		V	11/30/2059
2021 PO4017786247	LGE	4	45 ACE	SP	CCA		V	12/1/2059
2021 PO7306774138	LGE	4	30 ACE	SP	CCA		V	12/2/2059
2021 PO7304474064	LGE	3	45 ACE	SP	CCA		V	12/3/2059
2021 PO7300673952	LGE	4	30 ACE	SP	CCA		V	12/4/2059
2021 PO4016286236	LGE	4	45 ACE	SP	CCA		V	12/5/2059
2021 PO7292473978	LGE	3	45 ACE	SP	CCA		V	12/6/2059
2021 PO9176413245	KU	4	40 ACW	SP	S		V	12/7/2059
2021 PO9248614030	KU	4	45 ACW	SP	S		V	12/8/2059
2021 PO9257013712	KU	3	50 ACW	SP	S		V	12/9/2059
2021 PO3490886389	LGE	4	35 ACE	SP	CCA		V	12/10/2059
2021 PO7490018067	KU	4	40 ACW	SP	CRE		V	12/11/2059
2021 PO3950086383	LGE	4	40 ACE	SP	CCA		V	12/12/2059
2021 PO3950586380	LGE	6	30 ACE	SP	CRE		V	12/13/2059
2021 PO3958786470	F	4	40 ACE	SP	CCA		V	12/14/2059
2021 PO3957886461	F	4	40 ACE	SP	CCA		V	12/15/2059
2021 PO3957186453	F	4	40 ACE	SP	CRE		V	12/16/2059
2021 PO3955886439	F	4	40 ACE	SP	CCA		V	12/17/2059
2021 PO3955186431	F	4	40 ACE	SP	CCA		V	12/18/2059
2021 PO3949686392	LGE	4	35 ACE	SP	CCA		V	12/19/2059
2021 PO3951186388	LGE	4	30 ACE	SP	CRE		V	12/20/2059
2021 PV3949586429	F	4	40 ACE	SP	CCA		V	12/21/2059
2021 PO3950086435	F	4	40 ACE	SP	CCA		V	12/22/2059
2021 PO5384036287	KU	4	45 BRN	SP	CRE	ID	BD	12/23/2059
2021 PO5383836204	KU	5	35 BRN	SP	CRE	ID	BD	12/24/2059
2021 PO5379036295	KU	3	45 BRN	SP	CRE	ID	BD	12/25/2059
2021 PO5370436892	KU	4	40 BRN	SP	CRE		V	12/26/2059
2021 PO5380836828	KU	2	45 BRN	SP	CCA		V	12/27/2059
2021 PO5381536928	KU	2	50 BRN	SP	CCA		V	12/28/2059
2021 PO5405036846	KU	3	50 BRN	SP	CCA		V	12/29/2059
2021 PO5414836907	KU	2	45 BRN	SP	CCA		V	12/30/2059
2021 PO3950586439	F	4	40 ACE	SP	CCA		V	12/31/2059
2021 PO3950986438	F	4	30 ACE	SP	P		V	1/1/2060
2021 PO3951286446	F	4	35 ACE	SP	P		V	1/2/2060
2021 PO3952286450	F	6	30 ACE	SP	CRE		V	1/3/2060
2021 PO3952086454	F	4	40 ACE	SP	A		V	1/4/2060
2021 PO3952786460	F	4	40 ACE	SP	CCA		V	1/5/2060
2021 PO7512718654	KU	4	40 ACW	SP	CRE	ED,ID	TD	1/6/2060
2021 PO7535218155	KU	4	40 ACW	SP	S		V	1/7/2060
2021 PO7526218151	KU	4	40 ACW	SP	S	ED,ID	T	1/8/2060
2021 PO7527418206	KU	6	30 ACW	SP	CRE	ED,ID	TD	1/9/2060
2021 PO8499814629A	KU	4	40 ACW	SP	S		V	1/10/2060
2021 PO3954086473	F	4	35 ACE	SP	CCA		V	1/11/2060
2021 PO3955986480	F	6	30 ACE	SP	CRE		V	1/12/2060
2021 PO3955686489	F	4	40 ACE	SP	A		V	1/13/2060
2021 PO3954786473	F	3	45 ACE	SP	CCA		V	1/14/2060

2021 PO3954186489	F	4	35 ACE	SP	P		V	1/15/2060
2021 PO3954786475	F	4	35 ACE	SP	P		V	1/16/2060
2021 PO3956886500	F	4	40 ACE	SP	CCA		V	1/17/2060
2021 PO4017486164	LGE	4	35 ACE	SP	CCA		V	1/18/2060
2021 PO4015986172	LGE	4	40 ACE	SP	CCA		V	1/19/2060
2021 PO4012386145	LGE	4	35 ACE	SP	P	ED,ID	TD	1/20/2060
2021 PO4013686144	LGE	4	35 ACE	SP	P	ED,ID	TD	1/21/2060
2021 PO4014786048	LGE	4	35 ACE	SP	P	ED,ID	TD	1/22/2060
2021 PO4015886132	LGE	3	45 ACE	SP	CCA		V	1/23/2060
2021 PO4016886125	LGE	4	40 ACE	SP	CCA		V	1/24/2060
2021 PO4017986118	LGE	4	35 ACE	SP	P	ED,ID,IP	TD	1/25/2060
2021 PO4018986112	LGE	4	35 ACE	SP	P	ED,ID	TD	1/26/2060
2021 PO4075386377	F	4	40 BRO	SP	CRE		V	1/27/2060
2021 PO4076786371	F	4	40 BRO	SP	CRE		V	1/28/2060
2021 PO4077186366	F	4	40 BRO	SP	CRE		V	1/29/2060
2021 PO4079686360	F	4	40 BRO	SP	CRE		V	1/30/2060
2021 PO4081086355	F	3	45 BRO	SP	CCA		V	1/31/2060
2021 PO3955486328	LGE	4	30 ACE	SP	P	ID	BD	2/1/2060
2021 PO4082386344	F	4	35 BRO	SP	CRE		V	2/2/2060
2021 PO5152737727	KU	4	40 UNK	SP	CRE	ID	TD	2/3/2060
2021 PO5166237745	KU	3	45 UNK	SP	CRE	ID	TD	2/4/2060
2021 PO4091486275	LGE	4	30 BRO	SP	CRE	ED,ID	BD	2/5/2060
2021 PO4091586286	F	4	40 BRO	SP	CRE		V	2/6/2060
2021 PO4090486287	F	4	40 BRO	SP	CCA		V	2/7/2060
2021 PO4089286288	F	4	40 BRO	SP	CRE		V	2/8/2060
2021 PV4007486083	LGE	4	35 ACE	SP	P	ED,ID	BD	2/9/2060
2021 PO4088086288	F	4	40 BRO	SP	CRE		V	2/10/2060
2021 PO4086786289	F	4	40 BRO	SP	CRE		V	2/11/2060
2021 PO4085586290	F	4	40 BRO	SP	CRE		V	2/12/2060
2021 PO4084486291	F	4	40 BRO	SP	CRE		V	2/13/2060
2021 PO3958986379	F	4	40 ACE	SP	CCA		V	2/14/2060
2021 PO3959286390	F	4	35 ACE	SP	A		V	2/15/2060
2021 PO4077186298	F	4	40 BRO	SP	CCA		V	2/16/2060
2021 PO5179637762	KU	4	40 UNK	SP	CRE	ID	BD	2/17/2060
2021 PO5193237777	KU	4	40 UNK	SP	CRE	ID	TD	2/18/2060
2021 PO5202137787	KU	2	40 UNK	SP	CRE	ID	TD	2/19/2060
2021 PO5293734594	KU	2	50 BRN	SP	CCA		V	2/20/2060
2021 PO5301934816	KU	2	50 BRN	SP	CCA		V	2/21/2060
2021 PO5304034874	KU	2	50 BRN	SP	CCA		V	2/22/2060
2021 PO5297734705	KU	2	50 BRN	SP	CCA		V	2/23/2060
2021 PO5310535048	KU	2	50 BRN	SP	CCA		V	2/24/2060
2021 PO5315335178	KU	2	50 BRN	SP	CCA		V	2/25/2060
2021 PO5320335311	KU	2	50 BRN	SP	CCA		V	2/26/2060
2021 PO5323435392	KU	2	50 BRN	SP	CCA		V	2/27/2060
2021 PO5345535300	KU	2	40 BRN	SP	CCA		V	2/28/2060
2021 PO4065386434	F	4	40 BRO	SP	CRE		V	2/29/2060
2021 PO4066286442	F	4	40 BRO	SP	CRE		V	3/1/2060
2021 PO4067186443	F	4	40 BRO	SP	CRE		V	3/2/2060
2021 PO4068486438	F	4	40 BRO	SP	CRE		V	3/3/2060
2021 PO3958786397	LGE	4	30 ACE	SP	CCA		V	3/4/2060
2021 PO3959986382	F	4	40 ACE	SP	A		V	3/5/2060
2021 PO3959686388	F	3	45 ACE	SP	CCA		V	3/6/2060
2021 PO3960386396	F	4	40 ACE	SP	A		V	3/7/2060
2021 PO3961086397	F	4	30 ACE	SP	CCA		V	3/8/2060

2021 PO3962286432	F	3	45 ACE	SP	CCA		V					3/9/2060
2021 PO5351937796	KU	2	50 UNK	SP	CRE	ID	TD					3/10/2060
2021 PO5305038076	KU	2	45 BRO	SP	CRE	ID,SRS	TD					3/11/2060
2021 PO5415535976	KU	3	45 BRN	SP	CRE	ID	TD					3/12/2060
2021 PO4069886253	F	4	40 BRO	SP	CRE		V					3/13/2060
2021 PO4068686254	F	4	40 BRO	SP	CRE		V					3/14/2060
2021 PO4066786254	F	4	40 BRO	SP	CRE		V					3/15/2060
2021 PO4067486255	F	4	40 BRO	SP	CRE		V					3/16/2060
2021 PO4064186256	F	4	40 BRO	SP	CRE		V					3/17/2060
2021 PO4065486255	F	4	40 BRO	SP	CRE		V					3/18/2060
2021 PO5346837636	KU	3	45 BRO	SP	CCA		V					3/19/2060
2021 PO4061386273	LGE	4	40 BRO	SP	CRE		V					3/20/2060
2021 PO4062986272	LGE	4	40 BRO	SP	CRE		V					3/21/2060
2021 PO4062886258	LGE	4	40 BRO	SP	CRE		V					3/22/2060
2021 PO4062786245	LGE	4	40 BRO	SP	CRE		V					3/23/2060
2021 PO4062686232	LGE	4	40 BRO	SP	CRE		V					3/24/2060
2021 PO4062586219	F	4	40 BRO	SP	CCA		V					3/25/2060
2021 PO5339937430	KU	3	45 BRO	SP	CCA		V					3/26/2060
2021 PO4065386227	F	4	40 BRO	SP	CCA		V					3/27/2060
2021 PO4063986228	F	4	40 BRO	SP	CRE		V					3/28/2060
2021 PO4071186215	LGE	5	25 BRO	SP	CRE	ED,ID	TD					3/29/2060
2021 PO4071286225	F	4	40 BRO	SP	CRE		V					3/30/2060
2021 PO4073086215	LGE	4	40 BRO	SP	CRE		V					3/31/2060
2021 PO4072486207	F	5	30 BRO	SP	CCA		V					4/1/2060
2021 PO4072986206	F	4	40 BRO	SP	CRE		V					4/2/2060
2021 PO5325635509	KU	4	40 BRN	SP	CRE	ED,ID	BX		RP1			4/3/2060
2021 PO5329835638	KU	4	40 BRN	SP	CRE	ED,ID	BX		RP2			4/4/2060
2021 PO5368735553	KU	5	35 BRN	SP	CRE	ED	BX		RP3			4/5/2060
2021 PO5347235564	KU	3	50 BRN	SP	CCA		V					4/6/2060
2021 PO5345535654	KU	2	50 BRN	SP	CCA		V					4/7/2060
2021 PO5361335647	KU	3	45 BRN	SP	CRE	ID	TD					4/8/2060
2021 PO5373935618	KU	5	35 BRN	SP	CRE	ID	TD					4/9/2060
2021 PO5369935748	KU	4	45 BRN	SP	CCA		V					4/10/2060
2021 PO5369535644	KU	2	45 BRN	SP	CRE	ID	TD					4/11/2060
2021 PO5381535652	KU	3	45 BRN	SP	CRE	ID	TD					4/12/2060
2021 PO4072986198	LGE	4	40 BRO	SP	CRE		V					4/13/2060
2021 PO4074386191	F	5	30 BRO	SP	A		V					4/14/2060
2021 PO4074486199	F	4	40 BRO	SP	CRE		V					4/15/2060
2021 PO4075686199	F	4	40 BRO	SP	CRE		V					4/16/2060
2021 PO4076986198	F	4	40 BRO	SP	CRE		V					4/17/2060
2021 PO4078386197	F	4	40 BRO	SP	CRE		V					4/18/2060
2021 PO4078986197	F	4	40 BRO	SP	CRE		V					4/19/2060
2021 PO4080186196	F	4	40 BRO	SP	CRE		V					4/20/2060
2021 PO4081386195	F	4	40 BRO	SP	CRE		V					4/21/2060
2021 PO4082686194	F	4	40 BRO	SP	CRE		V					4/22/2060
2021 PO4071486252	F	4	40 BRO	SP	CRE	ED,ID	BX		RP3			4/23/2060
2021 PO559134647a	KU	5	35 BRN	SP	CRE	ID	TD					4/24/2060
2021 PO4021786138a	KU	4	35 ACE	SP	P	ED,ID	TD					4/25/2060
2021 PO4019586151	LGE	4	35 ACE	SP	P	ED,ID	TD					4/26/2060
2021 PO4020686144	LGE	4	35 ACE	SP	P	ED,ID,IP	TD					4/27/2060
2021 PO4021786138	LGE	4	40 ACE	SP	CCA		V					4/28/2060
2021 PO4018486157	LGE	4	40 ACE	SP	CCA		V					4/29/2060
2021 PO4091986303	LGE	4	40 BRO	SP	CRE	ED,ID	TD					4/30/2060
2021 PO4092486302	LGE	5	25 BRO	SP	CRE	ED,ID	BX		RP3			5/1/2060

2021 PO4092686307	F	4	40 BRO	SP	CRE		V	5/2/2060
2021 PO3953086298	LGE	4	40 ACE	SP	CCA		V	5/3/2060
2021 PO3952286285	LGE	4	40 ACE	SP	CCA		V	5/4/2060
2021 PO3951386269	LGE	4	40 ACE	SP	CCA		V	5/5/2060
2021 PO3939186337	F	4	40 ACE	SP	CCA		V	5/6/2060
2021 PO5286434405	KU	2	50 BRN	SP	CCA		V	5/7/2060
2021 PO5278834536	KU	2	45 BRN	SP	CCA		V	5/8/2060
2021 PO5289334476	KU	2	45 BRN	SP	A		V	5/9/2060
2021 PO5294834444	KU	3	40 BRN	SP	CCA		V	5/10/2060
2021 PO4010786073	LGE	4	35 ACE	SP	P	ED,ID,IP	BD	5/11/2060
2021 PO4011686078	LGE	4	30 ACE	SP	P	ED,ID	TD	5/12/2060
2021 PO4010586084	LGE	4	30 ACE	SP	CRE		V	5/13/2060
2021 PO4010986078	LGE	4	40 ACE	SP	P	ED,ID	TD	5/14/2060
2021 PO4076086334	F	4	40 BRO	SP	CRE		V	5/15/2060
2021 PO4075086337	F	4	40 BRO	SP	CRE		V	5/16/2060
2021 PO4076186342	F	5	25 BRO	SP	CRE		V	5/17/2060
2021 PO4011686066	LGE	3	45 ACE	SP	CCA		V	5/18/2060
2021 PO4011986072	LGE	3	45 ACE	SP	CCA		V	5/19/2060
2021 PO4012886061	LGE	5	35 ACE	SP	CRE	ED,ID	TD	5/20/2060
2021 PO4013186065	LGE	4	40 ACE	SP	P	ED,HH,ID,RB	BX	RP1 5/21/2060
2021 PO4012986065	LGE	4	40 ACE	SP	CRE	ED,ID	TD	5/22/2060
2021 PO4013386070	LGE	4	35 ACE	SP	P	ED,ID	BD	5/23/2060
2021 PO4012986053	LGE	4	35 ACE	SP	CCA		V	5/24/2060
2021 PO4013686056	LGE	4	30 ACE	SP	P	ED,ID	BD	5/25/2060
2021 PO4013986059	LGE	4	40 ACE	SP	P	ED,ID	TD	5/26/2060
2021 PO4084086221	F	4	40 BRO	SP	CRE		V	5/27/2060
2021 PO4082886222	F	4	40 BRO	SP	CCA		V	5/28/2060
2021 PO4081686223	F	4	40 BRO	SP	CRE		V	5/29/2060
2021 PO4080386224	F	4	40 BRO	SP	CRE		V	5/30/2060
2021 PO4079186225	F	4	40 BRO	SP	CRE		V	5/31/2060
2021 PO4078586226	F	4	40 BRO	SP	CRE		V	6/1/2060
2021 PO4074686229	F	4	40 BRO	DF	CRE		V	6/2/2060
2021 PO4075986228	F	4	40 BRO	SP	CRE		V	6/3/2060
2021 PO4077286226	F	4	40 BRO	SP	CRE		V	6/4/2060
2021 PO4073186229	F	4	40 BRO	SP	CRE		V	6/5/2060
2021 PO4073286248	F	4	40 BRO	SP	CRE		V	6/6/2060
2021 PO5414235825	KU	3	45 BRN	SP	CRE	ID	TD	6/7/2060
2021 PO5413235692a	KU	4	45 BRN	SP	CRE	ID	BD	6/8/2060
2021 PO5413835792	KU	3	45 BRN	SP	CCA		V	6/9/2060
2021 PO4066586226	F	4	40 BRO	SP	CRE		V	6/10/2060
2021 PO4082486349	F	4	40 BRO	SP	CCA		V	6/11/2060
2021 PO4083986344	F	4	40 BRO	SP	CCA		V	6/12/2060
2021 PO4085386338	F	4	40 BRO	SP	CRE		V	6/13/2060
2021 PO5266534699	KU	6	30 BRN	SP	CRE	ID	TD	6/14/2060
2021 PO5259134647	KU	2	45 BRN	SP	CCA		V	6/15/2060
2021 PO5254534528	KU	4	40 BRN	SP	CRE	ID	BD	6/16/2060
2021 PO5283834341	KU	4	40 BRN	SP	CRE	ID	BD	6/17/2060
2021 PO4086986333	F	4	40 BRO	SP	CRE		V	6/18/2060
2021 PO4088186327	F	3	45 BRO	SP	CCA		V	6/19/2060
2021 PO4008986068	LGE	4	30 ACE	SP	P	ED,ID	BD	6/20/2060
2021 PO3954486319	LGE	4	30 ACE	SP	CRE	ED,ID	BD	6/21/2060
2021 PO4007386098	LGE	4	40 ACE	SP	CCA		V	6/22/2060
2021 PO3953986315	LGE	4	35 ACE	SP	CRE	ED,ID	TD	6/23/2060
2021 PO4089586322	F	4	40 BRO	SP	CRE		V	6/24/2060

2021 PO4090986316	F	3	45 BRO	SP	CCA		V	6/25/2060
2021 PO4083186292	F	4	40 BRO	SP	CRE		V	6/26/2060
2021 PO4007286092	LGE	4	30 ACE	SP	P	ED,ID,IP	TD	6/27/2060
2021 PO4078486297	F	4	40 BRO	SP	CRE		V	6/28/2060
2021 PO4079586296	F	4	40 BRO	SP	CRE		V	6/29/2060
2021 PO4080786294	F	4	40 BRO	SP	CRE		V	6/30/2060
2021 PO4082086293	F	4	40 BRO	SP	CRE		V	7/1/2060
2021 PO4008386085	LGE	4	30 ACE	SP	P	ED,ID	BD	7/2/2060
2021 PO4008786091	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	7/3/2060
2021 PV4008686078	LGE	4	30 ACE	SP	P	ED,ID	TD	7/4/2060
2021 PO4009586078	LGE	4	30 ACE	SP	P	ED,ID	TD	7/5/2060
2021 PO4009886084	LGE	4	40 ACE	SP	P	ED,ID	BD	7/6/2060
2021 PO3940286349	F	4	40 ACE	SP	CRE		V	7/7/2060
2021 PO3938386342	F	4	45 ACE	SP	CRE		V	7/8/2060
2021 PO4474688286	LGE	4	40 ACE	SP	CCA		V	7/9/2060
2021 PO4474988288	F	4	35 ACE	SP	CRE		V	7/10/2060
2021 PO4474688295	F	4	35 ACE	SP	A		V	7/11/2060
2021 PO4434087831	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	7/12/2060
2021 PO8221578589	KU	4	40 ACE	SP	CCA		V	7/13/2060
2021 PO8222878609	KU	4	40 ACE	SP	CCA		V	7/14/2060
2021 PO8556060935	ODP	5	35 BRO	SP	CRE	ED,ID	TD	7/15/2060
2021 PO855166802	ODP	5	40 BRO	SP	CRE	ED,ID,IP	TD	7/16/2060
2021 PO8581960718	ODP	6	30 BRO	SP	S		V	7/17/2060
2021 PO6091328154	KU	6	35 UNK	SP	CRE		T	7/18/2060
2021 PO8216978493	F	4	40 ACE	SP	CRE		V	7/19/2060
2021 PO8216178570	F	4	40 ACE	SP	P		V	7/20/2060
2021 PO4447988070	F	4	40 BRO	SP	P		V	7/21/2060
2021 PO4447088067	F	4	35 BRO	SP	P		V	7/22/2060
2021 PV3438914609	F	4	40 BRO	SP	P		V	7/23/2060
2021 PO8233478675	KU	5	35 ACE	SP	CCA		V	7/24/2060
2021 PO4474988253	LGE	3	45 ACE	SP	CCA		V	7/25/2060
2021 PO8551864980	ODP	4	40 XXX	SP	CRE	ID	TD	7/26/2060
2021 PO4474988265	F	3	45 ACE	SP	CCA		V	7/27/2060
2021 PO4475288267	F	4	40 ACE	SP	P		V	7/28/2060
2021 PO8246478594	F	3	45 ACE	SP	CCA		V	7/29/2060
2021 PO8619060789	ODP	6	30 BRO	SP	CRE	ED,ID	TD	7/30/2060
2021 PO8621360601	F	6	30 BRO	SP	P		V	7/31/2060
2021 PO8606860628	F	4	40 BRO	SP	P		V	8/1/2060
2021 PO8650860616	ODP	5	35 BRO	SP	S	ED	T	8/2/2060
2021 PO8649760397	ODP	4	45 BRO	SP	CRE	ED,ID	BD	8/3/2060
2021 PO1847595158	F	4	40 ACE	SP	P		V	8/4/2060
2021 PO4474888277	F	4	40 ACE	SP	CRE		V	8/5/2060
2021 PO4475288282	F	4	40 ACE	SP	P		V	8/6/2060
2021 PO8541364610	ODP	4	40 XXX	SP	CCA		V	8/7/2060
2021 PO8422363475	ODP	4	40 XXX	SP	CRE	ID	TD	8/8/2060
2021 PO8227477526	F	4	40 ACE	SP	CRE		V	8/9/2060
2021 PO8448963747	ODP	5	30 XXX	SP	CRE	ID	TD	8/10/2060
2021 PO4496988230	LGE	4	30 ACE	SP	CRE	ED,ID	TD	8/11/2060
2021 PO8370576944	F	3	50 ACE	SP	CCA		V	8/12/2060
2021 PO4492988218	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/13/2060
2021 PO4474888209	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/14/2060
2021 PO4492988207	LGE	4	40 ACE	SP	CCA	ED,ID	TD	8/15/2060
2021 PO1847794050	LGE	4	35 ACE	SP	CRE	ED,ID,RB	TD	8/16/2060
2021 PO6171528533	F	4	40 UNK	SP	CRE	ED,ID	VX PX	8/17/2060



2021	PO6225029109	KU	5	35 UNK	SP	CRE	ED,ID	BX	RP2	8/18/2060
2021	PO6207528916	F	4	40 UNK	SP	CRE	ED,ID	VX	PX	8/19/2060
2021	PO8613561250	ODP	5	35 BRN	SP	CRE	ED,ID,IP	BD		8/20/2060
2021	PO4496488242	LGE	4	40 ACE	SP	CRE	ED,ID	BD		8/21/2060
2021	PO4474888166	LGE	3	55 ACE	SP	CRE	ED,ID	BD		8/22/2060
2021	PO4498688297	LGE	1	50 ACE	SP	CRE	ED,ID,MD	BD		8/23/2060
2021	PO1847694324	LGE	4	45 ACE	SP	P	ED,ID	BD		8/24/2060
2021	PO6187329421	KU	5	35 UNK	SP	CRE		B		8/25/2060
2021	PO2965289814	KU	4	45 BRO	SP	CRE	ED,IP,SRS	TD		8/26/2060
2021	PO4448187969	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		8/27/2060
2021	PO4447587977	LGE	4	40 BRO	SP	P	ED,ID	BD		8/28/2060
2021	PO4446887985	LGE	3	40 BRO	SP	CRE	ED,ID	BD		8/29/2060
2021	PO4446587993	LGE	4	40 BRO	SP	P	ED,ID	BD		8/30/2060
2021	PO4447088030	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		8/31/2060
2021	PO4449487992	LGE	4	35 BRO	SP	CRE	ED,ID	BD		9/1/2060
2021	PO4448288007	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD		9/2/2060
2021	PO4448088023	LGE	4	35 BRO	SP	P	ED,ID,IP	BD		9/3/2060
2021	PO8205077420	KU	4	40 ACE	SP	CRE	ED,ID	BD		9/4/2060
2021	PO8173477386	KU	3	45 ACE	SP	CRE	ED,ID	BD		9/5/2060
2021	PO2970789427	KU	6	30 BRO	SP	CRE	ED,IP	BD		9/6/2060
2021	PO2962089525	KU	4	40 BRO	SP	CCA		V		9/7/2060
2021	PO8350077097	KU	6	30 ACE	SP	CCA		V		9/8/2060
2021	PO8196477397	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		9/9/2060
2021	PO8400777080	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		9/10/2060
2021	PO8421977161	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD		9/11/2060
2021	PO8435976805	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		9/12/2060
2021	PO8379477172	KU	4	45 ACE	SP	CRE	ED,ID	BD		9/13/2060
2021	PO8363577260	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		9/14/2060
2021	PO8348877248	KU	5	35 ACE	SP	CRE	ED,ID	BD		9/15/2060
2021	PO6136128372	KU	4	40 UNK	SP	CRE		B		9/16/2060
2021	PO8389877046	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		9/17/2060
2021	PO8614961053	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		9/18/2060
2021	PO1847794223	LGE	4	35 ACE	SP	CRE	ED,ID	BD		9/19/2060
2021	PO4449088002	LGE	4	35 BRO	SP	P	ED,ID	BD		9/20/2060
2021	PO8410176787	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		9/21/2060
2021	PO4497488233	LGE	4	40 ACE	SP	CRE	ED,ID	BD		9/22/2060
2021	PO6127328274	KU	4	40 UNK	UN	CRE		V		9/23/2060
2021	PO8508261157	F	4	40 BRO	SP	CRE		V		9/24/2060
2021	PO4446288101	F	4	35 BRO	SP	CRE		V		9/25/2060
2021	PO8182177246	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD		9/26/2060
2021	PO4449388228-A	F	4	35 BRO	SP	P		V		9/27/2060
2021	PO6187628541	F	4	40 UNK	SP	CRE		V		9/28/2060
2021	PO8615060981	ODP	6	30 BRO	SP	CRE	ED,ID	TD		9/29/2060
2021	PO4446388002	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		9/30/2060
2021	PO4494288237	LGE	4	30 ACE	SP	CRE	ED,ID	BD		10/1/2060
2021	PO4448288033	LGE	4	35 BRO	SP	P	ED,ID	BD		10/2/2060
2021	PO8423776732	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD		10/3/2060
2021	PO8416377210	F	6	30 ACE	SP	CCA		V		10/4/2060
2021	PO4492888188	LGE	4	40 ACE	SP	P	ED,ID	BD		10/5/2060
2021	PO4474888190	LGE	3	45 ACE	SP	CRE	ED,ID	BD		10/6/2060
2021	PO4493088233	LGE	4	40 ACE	SP	CRE	ED,ID	BD		10/7/2060
2021	PO4492288178	LGE	4	30 ACE	SP	P	ED,ID	BD		10/8/2060
2021	PO8570961032	ODP	5	35 BRO	SP	CRE	ED,ID	TD		10/9/2060
2021	PO6191028818	KU	3	45 UNK	SP	CRE	ED,ID	BX	PX	10/10/2060

2021 PO6158029340	KU	3	45 UNK	SP	CRE	ED,ID	BX	PX	10/11/2060
2021 PO6162629293	KU	4	40 UNK	SP	CRE		B		10/12/2060
2021 PO6165929352	KU	4	40 UNK	SP	CCA		B		10/13/2060
2021 PO6143028343	KU	2	50 UNK	SP	CRE		B		10/14/2060
2021 PO6134928431	KU	5	35 UNK	SP	CRE		B		10/15/2060
2021 PO6143028436	KU	6	30 UNK	SP	CRE		B		10/16/2060
2021 PO6177528685	KU	3	45 UNK	SP	CRE		B		10/17/2060
2021 PO6170628619	KU	3	45 UNK	SP	CRE		B		10/18/2060
2021 PO6178229535	KU	3	45 UNK	SP	CRE		B		10/19/2060
2021 PO6186128769	KU	3	45 UNK	SP	CRE		B		10/20/2060
2021 PO6152028439	KU	4	45 UNK	SP	CRE		B		10/21/2060
2021 PO6160028517	KU	4	45 UNK	SP	CRE		B		10/22/2060
2021 PO6212829232	KU	4	40 UNK	SP	CRE		B		10/23/2060
2021 PO6173329181	KU	5	35 UNK	SP	CRE		B		10/24/2060
2021 PO6203229333	KU	4	40 UNK	SP	CRE		B		10/25/2060
2021 PO6188429762	KU	5	35 UNK	SP	CRE		B		10/26/2060
2021 PO6195729705	KU	3	45 UNK	SP	CRE		B		10/27/2060
2021 PO6186929620	KU	5	45 UNK	SP	CRE		B		10/28/2060
2021 PO6167429517	KU	5	35 UNK	SP	CRE		B		10/29/2060
2021 PO6224429189	KU	6	30 UNK	SP	CRE		B		10/30/2060
2021 PO6220729151	KU	4	40 UNK	SP	CRE		B		10/31/2060
2021 PO6212429077	KU	5	35 UNK	SP	CRE		B		11/1/2060
2021 PO6206129016	KU	5	35 UNK	SP	CRE		B		11/2/2060
2021 PO6199228907	KU	5	35 UNK	SP	CRE		B		11/3/2060
2021 PO4496788254	LGE	4	30 ACE	SP	P	ED,ID	BD		11/4/2060
2021 PO4503788260	LGE	4	35 ACE	SP	CRE	ED,ID	TD		11/5/2060
2021 PO8707961721	ODP	4	45 BRN	SP	S		V		11/6/2060
2021 PO8566464211	ODP	4	40 XXX	SP	CRE	ID	BD		11/7/2060
2021 PO8479464145	ODP	5	35 XXX	SP	CRE	ID	BD		11/8/2060
2021 PO8451476950	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		11/9/2060
2021 PO8432363610	ODP	4	40 XXX	SP	CRE	ID	TD		11/10/2060
2021 PO4474888179	LGE	3	50 ACE	SP	CCA	ED,ID	TD		11/11/2060
2021 PV1582292550	LGE	4	35 BRO	SP	P	ED,ID	TD		11/12/2060
2021 PO4445888022	LGE	4	40 BRO	SP	P	ED,ID	TD		11/13/2060
2021 PO4445688032	LGE	4	40 BRO	SP	CCA	ED,ID	TD		11/14/2060
2021 PO4445988001	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD		11/15/2060
2021 PO8515463823	ODP	4	40 XXX	SP	CRE	ID	TX	RR	11/16/2060
2021 PO4443187852	LGE	5	35 BRO	SP	A	IP,RB	X	RP1	11/17/2060
2021 PO8185577420	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		11/18/2060
2021 PO0626549851A	KU	6	30 BRN	SP	CRE	ID	TD		11/19/2060
2021 PO8500564605	F	4	40 XXX	SP	P		V		11/20/2060
2021 PO8403276972	KU	4	45 ACE	SP	CCA		V		11/21/2060
2021 PO8388876979	KU	4	40 ACE	SP	CRE	ED,ID	TD		11/22/2060
2021 PO8503363963	ODP	4	40 XXX	SP	P	ID	TD		11/23/2060
2021 PO4494688158	F	4	40 ACE	SP	CRE		V		11/24/2060
2021 PO8444463588	ODP	4	40 XXX	SP	CRE	ID	TD		11/25/2060
2021 PO6203829785	KU	3	50 UNK	SP	CCA		V		11/26/2060
2021 PO8462863683	ODP	4	40 XXX	SP	CRE	ID	TD		11/27/2060
2021 PO8484263829	ODP	4	40 XXX	SP	CRE	ID	TD		11/28/2060
2021 PO2888689195	F	4	40 BRO	SP	CRE		V		11/29/2060
2021 PO2883589042	F	4	40 BRO	SP	CRE		V		11/30/2060
2021 PO8417777101	F	4	40 ACE	SP	CRE		V		12/1/2060
2021 PO8415077103	F	4	40 ACE	SP	CRE		V		12/2/2060
2021 PO8369164126	F	3	45 XXX	SP	P		V		12/3/2060

2021 PO2879088915	F	4	40 BRO	SP	CRE		V	12/4/2060
2021 PO2873088749	F	4	40 BRO	SP	CRE		V	12/5/2060
2021 PO2870488674	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	12/6/2060
2021 PO2917689060	F	4	40 BRO	SP	CRE		V	12/7/2060
2021 PO8415777163	F	4	45 ACE	SP	CRE		V	12/8/2060
2021 PO8223877841	F	4	40 ACE	SP	P		V	12/9/2060
2021 PO8222977929	F	4	40 ACE	SP	P		V	12/10/2060
2021 PO4433587840	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/11/2060
2021 PO4432087856	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	12/12/2060
2021 PO6112928148	KU	5	35 UNK	SP	CCA		V	12/13/2060
2021 PO4432987849	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/14/2060
2021 PO2959989458	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	12/15/2060
2021 PO6120228210	KU	4	40 UNK	SP	CCA		V	12/16/2060
2021 PO6138128396	KU	2	50 UNK	SP	CCA		V	12/17/2060
2021 PO8203977414	KU	5	35 ACE	SP	CCA		V	12/18/2060
2021 PO0611949775	KU	5	35 BRN	SP	CCA		V	12/19/2060
2021 PO0618549849	KU	5	35 BRN	SP	CCA		T	12/20/2060
2021 PO0626549851	KU	4	45 UNK	SP	CRE	ID	TD	12/21/2060
2021 PO4490288161	LGE	1	55 ACE	SP	CCA		V	12/22/2060
2021 PO6214228842	F	4	40 UNK	SP	CRE		V	12/23/2060
2021 PO6216929029	F	4	40 UNK	SP	CRE		V	12/24/2060
2021 PO8162877326	KU	6	30 ACE	SP	CCA		V	12/25/2060
2021 PO4493188255	LGE	3	40 ACE	SP	CCA		V	12/26/2060
2021 PO8593061044	ODP	5	35 BRO	SP	CRE	ED,ID	TD	12/27/2060
2021 PO0549649145	KU	6	30 UNK	SP	CRE	ID	BD	12/28/2060
2021 PO0605749632	KU	4	45 UNK	SP	CRE	ID	TD	12/29/2060
2021 PO0593149785	KU	6	30 BRN	SP	CCA		T	12/30/2060
2021 PO8574360927	ODP	6	30 BRO	SP	S		V	12/31/2060
2021 PO8535361335	ODP	5	35 BRO	SP	CRE	ED,ID	TD	1/1/2061
2021 PO8535961241	ODP	6	30 BRO	SP	S		V	1/2/2061
2021 PO8531461079	ODP	5	35 BRO	SP	CRE	ED,ID	TD	1/3/2061
2021 PO4495088243	LGE	3	45 ACE	SP	CCA		V	1/4/2061
2021 PO4494688243	LGE	3	45 ACE	SP	CCA		V	1/5/2061
2021 PO4495688243	LGE	3	45 ACE	SP	CCA		V	1/6/2061
2021 PO4447888032	LGE	4	40 BRO	SP	CCA		V	1/7/2061
2021 PO4446388029	LGE	4	40 BRO	SP	CCA		V	1/8/2061
2021 PO4447188091	F	4	30 BRO	SP	P		V	1/9/2061
2021 PO4446788100	F	4	30 BRO	SP	P		V	1/10/2061
2021 PO4449088035	LGE	3	45 BRO	SP	CCA		V	1/11/2061
2021 PO8162977424	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	1/12/2061
2021 PO8162777468	KU	4	40 ACE	SP	CCA		V	1/13/2061
2021 PO8157777515	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	1/14/2061
2021 PO8157277604	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	1/15/2061
2021 PO8162977545	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	1/16/2061
2021 PO2896689437	F	4	40 BRO	SP	CRE		V	1/17/2061
2021 PO6145228322	KU	2	50 UNK	SP	CCA		V	1/18/2061
2021 PO8362477087	KU	6	30 ACE	SP	CCA		V	1/19/2061
2021 PO6203929412	F	4	40 UNK	SP	CRE		V	1/20/2061
2021 PO6207229444	F	4	40 UNK	SP	CRE		V	1/21/2061
2021 PO6200629312	KU	4	45 UNK	SP	CCA		V	1/22/2061
2021 PO6208329280	KU	4	40 UNK	SP	CCA		V	1/23/2061
2021 PO6159028270	F	4	40 UNK	SP	CRE		V	1/24/2061
2021 PO6153528238	KU	2	50 UNK	SP	CCA		V	1/25/2061
2021 PO6157528197	KU	3	45 UNK	SP	CCA		V	1/26/2061

2021 PO8641961928	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	1/27/2061
2021 PO8608961843	ODP	4	40 BRN	SP	S		V	1/28/2061
2021 PO8404176927	F	3	55 ACE	SP	P		V	1/29/2061
2021 PO6168729322	F	4	40 UNK	SP	CRE		V	1/30/2061
2021 PO0589949589	KU	5	30 BRO	SP	CRE	ID	TD	1/31/2061
2021 PO0588249454	KU	4	40 BRO	SP	CRE	ID	TD	2/1/2061
2021 PO8379477184	KU	4	45 ACE	SP	CCA		V	2/2/2061
2021 PO0576949429	KU	5	30 BRO	SP	CCA		T	2/3/2061
2021 PO8374977197	F	5	35 ACE	SP	P		V	2/4/2061
2021 PO8378877103	KU	4	45 ACE	SP	CCA		V	2/5/2061
2021 PO4442987873	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	2/6/2061
2021 PO2923490082	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	2/7/2061
2021 PO4442287867	LGE	4	35 BRO	SP	A	ED,ID	TD	2/8/2061
2021 PO3001989917	KU	3	45 BRO	SP	CCA		V	2/9/2061
2021 PO2976189791	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	2/10/2061
2021 PO4432287862	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	2/11/2061
2021 PO0561849355	KU	6	30 BRO	SP	CRE	ID	TD	2/12/2061
2021 PO0553649223	KU	5	35 UNK	SP	CRE	ID	TD	2/13/2061
2021 PO8378676940	F	3	45 ACE	SP	P		V	2/14/2061
2021 PO8373776942	F	4	40 ACE	SP	CCA		V	2/15/2061
2021 PO0540355768	KU	3	50 BRN	SP	CCA		V	2/16/2061
2021 PO4441787827	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	2/17/2061
2021 PO8163077600	KU	4	40 ACE	SP	CCA		V	2/18/2061
2021 PO4434287832	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	2/19/2061
2021 PO8676560864	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	2/20/2061
2021 PO8713560895	ODP	5	35 BRN	SP	CRE	ED,ID	TD	2/21/2061
2021 PO8688161717	ODP	4	45 BRN	SP	S		V	2/22/2061
2021 PO4443587877-A	KU	5	35 BRO	SP	A	ED,ID,IP	TD	2/23/2061
2021 PO8543364311	ODP	4	40 XXX	SP	CRE	ID	TD	2/24/2061
2021 PO0573349293	KU	4	45 BRO	SP	CRE	ID	TD	2/25/2061
2021 PO8670561950	ODP	5	35 BRN	SP	CRE	ED,ID	TD	2/26/2061
2021 PO8687762039	ODP	5	30 BRN	SP	CRE	ED,ID	TD	2/27/2061
2021 PO8446576909	F	4	45 ACE	SP	CRE		V	2/28/2061
2021 PO8513064341	F	4	40 XXX	SP	P		V	3/1/2061
2021 PO8543964154	ODP	5	35 XXX	SP	CCA		V	3/2/2061
2021 PO8524264158	ODP	6	35 XXX	SP	CRE	ID	TD	3/3/2061
2021 PO8571964294	ODP	5	35 XXX	SP	CCA		V	3/4/2061
2021 PO8582764120	ODP	3	45 XXX	SP	CCA		V	3/5/2061
2021 PO8610461552	ODP	4	45 BRN	SP	S		T	3/6/2061
2021 PO8704160986	ODP	3	45 BRN	SP	S		V	3/7/2061
2021 PO8370063867	ODP	4	40 XXX	SP	CRE	ID	TD	3/8/2061
2021 PO8388564041	ODP	5	30 XXX	SP	CRE	ID	TD	3/9/2061
2021 PO8221878054	F	4	40 ACE	SP	P		V	3/10/2061
2021 PO2958789604	KU	4	45 BRO	SP	CRE	ED,HH,IP,SRS	TD	3/11/2061
2021 PO8665061781	ODP	5	35 BRN	SP	CRE	ED,ID	BD	3/12/2061
2021 PO8660461535	ODP	5	35 BRN	SP	CRE	ED,ID	TD	3/13/2061
2021 PO8634461280	ODP	4	40 BRN	SP	S		V	3/14/2061
2021 PO6198228888	F	4	40 UNK	SP	CRE		V	3/15/2061
2021 PO4440387824	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	3/16/2061
2021 PO4492588222	LGE	4	30 ACE	SP	CCA		V	3/17/2061
2021 PO8146277453	KU	4	45 ACE	SP	CCA		V	3/18/2061
2021 PO1523849457	F	4	40 BRO	SP	CRE		V	3/19/2061
2021 PO1511949485	KU	5	35 BRO	SP	CRE	ED,EP,ID	BD	3/20/2061
2021 PO3435001901	KU	6	30 UNK	SP	CRE	ID,IP	TD	3/21/2061

2021 PO3438201948	KU	5	35 UNK	SP	CRE	ID,IP,SRS	TD		3/22/2061
2021 PO4133385737	LGE	4	40 BRN	SP	P	ID,SR	TD		3/23/2061
2021 PO1530049210	KU	4	40 BRO	SP	CRE	ED,EP,ID,MD	TD		3/24/2061
2021 PO4103585989	LGE	4	35 ACE	SP	P	ED,ID	TD		3/25/2061
2021 PO1515949125	KU	3	45 BRO	SP	CCA		V		3/26/2061
2021 PO1530149385	F	4	30 BRO	SP	CRE		V		3/27/2061
2021 PO1533849182	F	4	40 BRO	SP	CRE		V		3/28/2061
2021 PO1542149200	F	4	40 BRO	SP	CRE		V		3/29/2061
2021 PO1534948894	F	4	25 BRO	SP	CRE		V		3/30/2061
2021 PO1544148981	KU	4	40 BRO	SP	CRE	ED,ID	BD		3/31/2061
2021 PO9142373174	F	3	45 BRO	SP	CRE		V		4/1/2061
2021 PO9160873256	F	3	45 BRO	SP	CRE		V		4/2/2061
2021 PO4815104705	F	4	40 XXX	SP	CRE		V		4/3/2061
2021 PO4835804760	KU	6	30 XXX	SP	CRE	ED,ID	TD		4/4/2061
2021 PO4822204785	F	6	30 XXX	SP	CRE		V		4/5/2061
2021 PO4819604814	F	3	45 XXX	SP	CCA		V		4/6/2061
2021 PO4822804899	F	5	35 XXX	SP	CRE		V		4/7/2061
2021 PO4823604918	F	3	45 XXX	SP	S		V		4/8/2061
2021 PO4830505102	F	3	45 XXX	SP	CCA		V		4/9/2061
2021 PO4827705030	F	5	40 XXX	SP	CCA		V		4/10/2061
2021 PO4186986512	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		4/11/2061
2021 PO4133685762	LGE	4	40 BRN	SP	CCA	ED,SR	TX	RR	4/12/2061
2021 PO4132785781	LGE	4	30 BRN	SP	P	ID	BD		4/13/2061
2021 PO4855205156	KU	3	45 KOP	SP	S		V		4/14/2061
2021 PO4860105002	F	4	40 XXX	SP	A		V		4/15/2061
2021 PO4190786545	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		4/16/2061
2021 PO4101985989	F	4	40 ACE	SP	CRE		V		4/17/2061
2021 PO4101685990	LGE	4	30 ACE	SP	CCA		V		4/18/2061
2021 PO4102186008	F	4	40 ACE	SP	CRE		V		4/19/2061
2021 PO4102186021	F	4	40 ACE	SP	P		V		4/20/2061
2021 PO4102286033	F	4	40 ACE	SP	P		V		4/21/2061
2021 PO2945307913	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR	4/22/2061
2021 PO8438169169	LGE	4	35 BRN	SP	CCA		V		4/23/2061
2021 PO8454969187	LGE	4	35 BRN	SP	CCA		V		4/24/2061
2021 PO1550447425	KU	5	35 BRO	SP	S		V		4/25/2061
2021 PO4874904953	F	4	40 XXX	SP	P		V		4/26/2061
2021 PO4871604849	F	4	40 XXX	SP	CRE		V		4/27/2061
2021 PO4858904889	KU	6	30 XXX	SP	CRE	ED,ID	TD		4/28/2061
2021 PO1565247516	KU	3	50 BRO	SP	CCA		V		4/29/2061
2021 PO1555247453	KU	3	50 BRO	SP	CRE	ED,ID	BD		4/30/2061
2021 PO8450169182	LGE	4	35 BRN	SP	CCA		V		5/1/2061
2021 PO8435069201	LGE	4	35 BRN	SP	CCA		V		5/2/2061
2021 PO8433369129	LGE	4	35 BRN	SP	CCA		V		5/3/2061
2021 PO8448169103	LGE	4	35 BRN	SP	CCA		V		5/4/2061
2021 PO8464269136	LGE	4	35 BRN	SP	CCA		V		5/5/2061
2021 PO8463269086	LGE	4	35 BRN	SP	CCA		V		5/6/2061
2021 PO4131785712	LGE	4	35 BRN	SP	CCA		V		5/7/2061
2021 PO8445569011	LGE	4	35 BRN	SP	CCA		V		5/8/2061
2021 PO8431469031	LGE	4	35 BRN	SP	CCA		V		5/9/2061
2021 PO4102386047	F	3	45 ACE	SP	CCA		V		5/10/2061
2021 PO4102386060	F	3	45 ACE	SP	CCA		V		5/11/2061
2021 PO4192786509	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		5/12/2061
2021 PO5524004535	F	6	35E BRN	SP	CRE		V		5/13/2061
2021 PO5555003934	F	3	40 KOP	SP	CRE	IP	V		5/14/2061

2021 PO5557103993	F	7	35E	KOP	SP	CRE		V		5/15/2061
2021 PO5546304029	F	6	45E	KOP	SP	CRE		V		5/16/2061
2021 PO5536304124	F	3		40 KOP	SP	CRE		V		5/17/2061
2021 PO5533004174	F	3		40 BEL	SP	P		V		5/18/2061
2021 PO5507904447	F	3		40 BRN	SP	P		V		5/19/2061
2021 PO5521004386	F	7	35E	BEL	SP	CRE		V		5/20/2061
2021 PO5516404354	F	3		40 BEL	SP	CRE		V		5/21/2061
2021 PO5510004375	C	4		40 BRN	SP	CRE		V		5/22/2061
2021 PO4102486071	F	4		40 ACE	SP	CCA		V		5/23/2061
2021 PO4102586084	F	4		40 ACE	SP	CCA		V		5/24/2061
2021 PO4102686097	F	3		45 ACE	SP	CCA		V		5/25/2061
2021 PO4102886110	LGE	4		40 ACE	SP	P	ED,ID	TD		5/26/2061
2021 PO1591947661	KU	4		40 BRO	SP	CRE	ED,EP	VX	RP1	5/27/2061
2021 PO1620747840	KU	4		40 BRO	SP	CCA		V		5/28/2061
2021 PO1610548437	F	4		40 BRO	SP	CRE		V		5/29/2061
2021 PO4137285804	LGE	3		50 BRN	SP	CCA	ID	BD		5/30/2061
2021 PO4854304693	KU	6		30 XXX	SP	CRE	ED,ID	TD		5/31/2061
2021 PO9099972792	F	5		30 BRO	SP	A		V		6/1/2061
2021 PO4139285803	LGE	3		50 BRN	SP	P	ID	BD		6/2/2061
2021 PO4139885805	LGE	4		40 BRN	SP	P	ID	BD		6/3/2061
2021 PO4140185805	LGE	4		40 BRN	SP	P		V		6/4/2061
2021 PO4140185803	LGE	4		40 BRN	SP	P	ID	BD		6/5/2061
2021 PO4187686516	LGE	4		30 BRO	SP	CCA		V		6/6/2061
2021 PO1625848305	F	4		40 BRO	SP	CRE		V		6/7/2061
2021 PO1592948452	KU	4		40 BRO	SP	CRE	ED,EP,ID	TD		6/8/2061
2021 PO4187386509	LGE	4		35 BRO	SP	CRE	ED,ID,IP	TD		6/9/2061
2021 PO4187186508	LGE	4		30 BRO	SP	CCA	ED	T		6/10/2061
2021 PO4102986123	LGE	4		40 ACE	SP	CCA		V		6/11/2061
2021 PO4103086137	LGE	4		40 ACE	SP	CRE	ED,ID,IP	TD		6/12/2061
2021 PO4103186150	LGE	3		45 ACE	SP	CCA	ED	T		6/13/2061
2021 PO4103286163	LGE	4		40 ACE	SP	CCA		V		6/14/2061
2021 PO4135285805	LGE	2		55 BRN	SP	CCA		V		6/15/2061
2021 PO4138785749	LGE	3		50 BRN	SP	A	ED,ID,IP,MD,SRS	X	RP3	6/16/2061
2021 PO4138885742	LGE	3		50 BRN	SP	CCA		V		6/17/2061
2021 PO1617948200	KU	4		40 BRO	SP	CRE	ED,ID	TD		6/18/2061
2021 PO9164273466	KU	5		30 BRO	SP	CRE	ED,ID	TD		6/19/2061
2021 PO9180573487	KU	5		35 BRO	SP	CRE		V		6/20/2061
2021 PO9180673393	F	4		40 BRO	SP	A		V		6/21/2061
2021 PO9170173317	F	3		45 BRO	SP	CRE		V		6/22/2061
2021 PO4185786505	LGE	4		40 BRO	SP	CCA		V		6/23/2061
2021 PO4185386487	LGE	4		40 BRO	SP	A	ED,ID	TD		6/24/2061
2021 PO4184486490	LGE	3		45 BRO	SP	CCA		V		6/25/2061
2021 PO4138785733	LGE	3		50 BRN	SP	P	ID,IP,RB	TX	RR	6/26/2061
2021 PO1635148224	F	4		40 BRO	SP	CRE		V		6/27/2061
2021 PO1647748067	F	4		40 BRO	SP	CRE		V		6/28/2061
2021 PO2484603973	KU	3		50 UNK	SP	CRE	ID,IP,SRS	TD		6/29/2061
2021 PO2492503955	KU	3		50 UNK	SP	CRE	ID	BD		6/30/2061
2021 PO2492903817	KU	4		40 UNK	SP	CRE	ID	BD		7/1/2061
2021 PO1641547954	KU	4		40 BRO	SP	CRE	ED,ID	BD		7/2/2061
2021 PO4830404398	KU	4		40 XXX	SP	CRE	ID	BD		7/3/2061
2021 PO4829504574	KU	6		30 XXX	SP	CRE	ED,ID	TD		7/4/2061
2021 PO4812304634	KU	6		30 XXX	SP	CRE	ED,ID	TD		7/5/2061
2021 PO4819104473	F	4		40 XXX	SP	CRE		V		7/6/2061
2021 PO4802704473	KU	6		30 XXX	SP	CRE	ED,ID	TD		7/7/2061

2021 PO4834904411	F	4	40 XXX	SP	CRE		V	7/8/2061
2021 PO4844304374	F	4	40 XXX	SP	CRE		V	7/9/2061
2021 PO4842304532	KU	6	30 BRN	SP	CCA		V	7/10/2061
2021 PO4866204657	F	4	40 XXX	SP	CRE		V	7/11/2061
2021 PO4860304478	F	4	40 XXX	SP	CRE		V	7/12/2061
2021 PO4855404332	F	4	40 XXX	SP	CRE		V	7/13/2061
2021 PO9269174234	KU	3	40 BRO	SP	CRE	ED,ID	TD	7/14/2061
2021 PO9226173975	KU	3	45 BRO	SP	S		V	7/15/2061
2021 PO9201274069	KU	4	45 BRO	SP	S		V	7/16/2061
2021 PO9210074293	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/17/2061
2021 PO5575803794	KU	7	30 BRN	SP	CCA	ED,ID	TD	7/18/2061
2021 PO5570603765	F	3	40 KOP	SP	CRE		V	7/19/2061
2021 PO5520603983	F	3	40 BRO	SP	CRE		V	7/20/2061
2021 PO9285373960	KU	4	40 BRO	SP	CCA		V	7/21/2061
2021 PO9351873871	KU	4	40 BRO	SP	CCA		V	7/22/2061
2021 PO9385473807	KU	4	40 BRO	SP	CCA		V	7/23/2061
2021 PO9414673738	KU	4	40 BRO	SP	CCA		V	7/24/2061
2021 PO4113786114	LGE	1	60 ACE	SP	CCA		V	7/25/2061
2021 PO4134085737	LGE	4	40 BRN	SP	CCA	ID	BD	7/26/2061
2021 PO4134085713	LGE	4	40 BRN	SP	P	ID	BD	7/27/2061
2021 PO4134185702	LGE	4	40 BRN	SP	P	ID	BD	7/28/2061
2021 PO4139085531	F	4	55 BRN	SP	P		V	7/29/2061
2021 PO8538267109	F	1	55 BRN	SP	CCA		V	7/30/2061
2021 PO4140085497	F	3	45 BRN	SP	CCA		V	7/31/2061
2021 PO4180786488	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	8/1/2061
2021 PO4103386176	LGE	4	40 ACE	SP	P	ED,ID	TD	8/2/2061
2021 PO4103486189	LGE	4	40 ACE	SP	P	ED,ID	TD	8/3/2061
2021 PO2468603720	KU	4	40 UNK	SP	CRE	ID,IP	BD	8/4/2061
2021 PO2472703383	KU	3	60 UNK	SP	CRE	ED,EP	BX	8/5/2061
2021 PO2475803376	KU	3	60 UNK	SP	CRE	ID,IP	TD	8/6/2061
2021 PO2765103138	F	6	30 UNK	SP	CCA		V	8/7/2061
2021 PO2759703267	KU	4	40 UNK	SP	CRE		V	8/8/2061
2021 PO2914207223	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/9/2061
2021 PO2917907408	KU	2	45 BRN	SP	CRE	ED,ID,RB	X	8/10/2061
2021 PO2933507702	KU	2	45 BRN	SP	S		V	8/11/2061
2021 PO2909107245	KU	4	40 BRN	SP	CRE	ID	BD	8/12/2061
2021 PO2942807699	F	4	40 BRN	SP	CRE	ED,ID	V	8/13/2061
2021 PO5520603983a	KU	7	30 BRO	SP	CRE	ED,ID	TD	8/14/2061
2021 PO4135685694	LGE	4	40 BRN	SP	P		V	8/15/2061
2021 PO9275673876	KU	4	40 BRO	SP	CRE	ED,ID	BD	8/16/2061
2021 PO1665147735	KU	5	35 BRO	SP	CRE	ED,ID	TD	8/17/2061
2021 PO1652447895	F	4	40 BRO	SP	CRE		V	8/18/2061
2021 PO1673147738	F	4	40 BRO	SP	CRE		V	8/19/2061
2021 PO1685947633	F	4	40 BRO	SP	CRE		V	8/20/2061
2021 PO4178186517	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	8/21/2061
2021 PV8524566386	LGE	4	35 BRN	SP	P	ID	TD	8/22/2061
2021 PO4136385446	LGE	4	35 BRN	SP	P		V	8/23/2061
2021 PV8507866311	LGE	4	35 BRN	SP	P	ID	TD	8/24/2061
2021 PV8507866222	LGE	4	35 BRN	SP	P	EP,IP,RB	TX	8/25/2061
2021 PO4137285426	LGE	4	35 BRN	SP	P	HH,SRC	X	8/26/2061
2021 PO4180086500	LGE	4	40 BRO	SP	A	ED,ID	TD	8/27/2061
2021 PO9041473374	KU	4	40 BRO	SP	CCA		V	8/28/2061
2021 PO9078573546	KU	4	40 BRO	SP	CRE	ED,ID	BD	8/29/2061
2021 PO1686947523	KU	5	35 BRO	SP	CRE	ED,EP,ID	TD	8/30/2061

2021 PO1695647535	F	4	40 BRO	SP	CRE		V	8/31/2061
2021 PO1704247453	F	4	40 BRO	SP	CRE		V	9/1/2061
2021 PO1682247486	KU	4	40 BRO	SP	CCA		V	9/2/2061
2021 PO9107773711	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/3/2061
2021 PO4178386505	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	9/4/2061
2021 PO4179486511	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/5/2061
2021 PO4178986530	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/6/2061
2021 PO5510003949	KU	7	30 BRO	SP	CCA	ED	TD	9/7/2061
2021 PO5561603621	KU	7	30 BRO	SP	CCA	ED	TD	9/8/2061
2021 PO9095074037	KU	3	45 BRO	SP	CCA		V	9/9/2061
2021 PO4103486198	LGE	4	40 ACE	SP	P	ED,ID	TD	9/10/2061
2021 PO4103686206	LGE	4	40 ACE	SP	P	ED,ID	TD	9/11/2061
2021 PO1711847380	F	4	40 BRO	SP	CRE		V	9/12/2061
2021 PO1703147348	KU	6	35 BRO	SP	CRE	ED,ID	BD	9/13/2061
2021 PO1706047234	KU	4	40 BRO	SP	CCA		V	9/14/2061
2021 PO1725847015	KU	4	40 BRO	SP	CCA		V	9/15/2061
2021 PO1745646784	KU	4	40 BRO	SP	CCA		V	9/16/2061
2021 PO4865504295	F	4	40 KOP	SP	P		V	9/17/2061
2021 PO4872804266	F	4	40 KOP	SP	P		V	9/18/2061
2021 PO2739302989	KU	4	40 UNK	SP	CRE	ID	TD	9/19/2061
2021 PO2747402780	KU	5	30 UNK	SP	CRE	ID	TD	9/20/2061
2021 PO4632598337	KU	4	40 UNK	SP	CCA		V	9/21/2061
2021 PO4633098165	KU	3	45 UNK	SP	CCA		V	9/22/2061
2021 PO3386701893-A	KU	6	30 UNK	SP	CRE	ID	TD	9/23/2061
2021 PO3386701893	KU	5	35 UNK	SP	CRE	ED,ID	X	RP3 9/24/2061
2021 PO4142685278	LGE	4	40 BRN	SP	P	ED,ID	TD	9/25/2061
2021 PO4143485279	LGE	2	60 BRN	SP	CCA		V	9/26/2061
2021 PO4143285279	LGE	3	45 BRN	SP	P	ID,RB	TX	RR 9/27/2061
2021 PO1365250152	KU	4	40 BRO	SP	CRE	ED,ID,M,D	TD	9/28/2061
2021 PO4123086056	F	5	35 ACE	SP	CRE	ED,ID,IP	V	9/29/2061
2021 PO4122886054	LGE	2	75 ACE	SP	CRE	ED,ID	V	9/30/2061
2021 PO4121886061	LGE	2	70 ACE	SP	CRE	ED,ID	V	10/1/2061
2021 PO4120986070	LGE	6	25 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1 10/2/2061
2021 PO4120886067	LGE	2	65 ACE	SP	CRE	ED,ID	V	10/3/2061
2021 PO4115086105	LGE	2	65 ACE	SP	CRE	ED,ID	V	10/4/2061
2021 PO4107986166	LGE	2	60 ACE	SP	CRE	ED,ID	V	10/5/2061
2021 PO5277005430	F	4	40 BRN	SP	CRE		V	10/6/2061
2021 PO4175386399	LGE	4	40 BRO	SP	CRE	ID,IP	BD	10/7/2061
2021 PO4866305133	KU	6	30 XXX	SP	CRE	ID	BD	10/8/2061
2021 PO4809998057	KU	4	50 UNK	SP	CRE	ID	BD	10/9/2061
2021 PO4874205127	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	10/10/2061
2021 PO2996307669	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/11/2061
2021 PO3175808025	F	4	40 BRN	SP	CRE		V	10/12/2061
2021 PO3041607888	F	4	40 BRN	SP	CCA		V	10/13/2061
2021 PO3133607806	F	4	40 BRN	SP	CRE		V	10/14/2061
2021 PO3149107796	F	4	40 BRN	SP	CRE		V	10/15/2061
2021 PO3132008099	F	3	40 BRN	SP	S		V	10/16/2061
2021 PO2957408143	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/17/2061
2021 PO3051608233	F	3	40 BRN	SP	CCA		V	10/18/2061
2021 PO3066008207	F	3	40 BRN	SP	S		V	10/19/2061
2021 PO3105408140	F	3	40 BRN	SP	S		V	10/20/2061
2021 PO3054707864	F	4	40 BRN	SP	CRE		V	10/21/2061
2021 PO2979608154	F	4	40 BRN	SP	CRE		V	10/22/2061
2021 PO3109007820	F	3	45 BRN	SP	CCA		V	10/23/2061



2021 PO3030808271	F	3	45 BRN	SP	S		V	10/24/2061
2021 PO3080207835	F	4	40 BRN	SP	CRE		V	10/25/2061
2021 PO2992208069	F	4	40 BRN	SP	CRE		V	10/26/2061
2021 PO3094407828	F	4	40 BRN	SP	CCA		V	10/27/2061
2021 PO3169807785	F	4	40 BRN	SP	CRE		V	10/28/2061
2021 PO3009407982	F	4	40 BRN	SP	CRE		V	10/29/2061
2021 PO3045307831	KU	4	45 BRN	SP	CCA		V	10/30/2061
2021 PO3028907919	F	4	40 BRN	SP	CRE	ED,ID	V	10/31/2061
2021 PO2984008313	F	4	40 BRN	SP	CRE		V	11/1/2061
2021 PO3090408164	F	3	40 BRN	SP	S		V	11/2/2061
2021 PO4796397201	KU	4	40 UNK	SP	CRE	ID	TD	11/3/2061
2021 PO4783497114	KU	4	40 UNK	SP	CRE	ID,IP,SRS	TD	11/4/2061
2021 PO4892205059	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	11/5/2061
2021 PO4894405168	F	4	40 XXX	SP	CRE		V	11/6/2061
2021 PO4138885669	LGE	1	60 BRN	SP	CRE	ID,IP	BD	11/7/2061
2021 PO4905805149	F	4	40 KOP	SP	CRE		V	11/8/2061
2021 PO4914205136	F	4	40 XXX	SP	S		V	11/9/2061
2021 PO4912305002	KU	6	30 XXX	SP	CRE	ED,ID	TD	11/10/2061
2021 PO2558021873	KU	3	45 BRN	SP	CCA		V	11/11/2061
2021 PO2560121696	KU	3	45 BRN	SP	CCA		V	11/12/2061
2021 PO2561321375	KU	3	45 BRN	SP	CCA		V	11/13/2061
2021 PO2564321126	KU	3	45 BRN	SP	CCA		V	11/14/2061
2021 PO2568020747	KU	3	45 BRN	SP	CCA		V	11/15/2061
2021 PO2570620573	KU	3	45 BRN	SP	CCA		V	11/16/2061
2021 PO2574620342	KU	3	45 BRN	SP	CCA		V	11/17/2061
2021 PO2577520110	KU	3	45 BRN	SP	CCA		V	11/18/2061
2021 PO2581719813	KU	3	45 BRN	SP	CCA		V	11/19/2061
2021 PO2584819411	KU	3	45 BRN	SP	CCA		V	11/20/2061
2021 A1	KU	3	45 BRN	SP	CCA		V	11/21/2061
2021 PO2585318634	KU	3	45 BRN	SP	CCA		V	11/22/2061
2021 PO2591818313	KU	3	45 BRN	SP	CCA		V	11/23/2061
2021 PO2599717991	KU	3	45 BRN	SP	CCA		V	11/24/2061
2021 PO2605017683	KU	3	45 BRN	SP	CCA		V	11/25/2061
2021 PO2607917352	KU	3	45 BRN	SP	CCA		V	11/26/2061
2021 PO4148385165	LGE	4	30 BRO	SP	CCA		V	11/27/2061
2021 PO4624450615	F	4	40 BRN	SP	A		V	11/28/2061
2021 PO4632050784	F	4	40 BRN	SP	CCA		V	11/29/2061
2021 PO4145485212	LGE	7	25 BRO	SP	CRE		V	11/30/2061
2021 PO4145985179	LGE	7	25 BRO	SP	CRE		V	12/1/2061
2021 PO4148785151	LGE	4	35 BRO	SP	CCA		V	12/2/2061
2021 PO4156086142	LGE	4	40 BRO	SP	CCA		V	12/3/2061
2021 PO4727949969	KU	3	45 BRN	SP	CCA		V	12/4/2061
2021 PO4150885191	LGE	7	25 BRO	SP	CRE		V	12/5/2061
2021 PO4163186176	F	4	35 BRO	SP	A		V	12/6/2061
2021 PO4163286172	F	4	40 BRO	SP	A		V	12/7/2061
2021 PO4156586151	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX RR	12/8/2061
2021 PO4150085198	LGE	4	45 BRO	SP	CRE	ED,ID	TX RR	12/9/2061
2021 PO4149985234	LGE	4	40 BRO	SP	CRE	ED,ID,RB	TX RR	12/10/2061
2021 PO4681550128	KU	4	40 BRN	SP	CRE	ID	TX RR	12/11/2061
2021 PO4158286168	LGE	4	40 BRO	SP	A	ED,ID,IP	TX RR	12/12/2061
2021 PO4151085218	LGE	4	40 BRO	SP	CRE	ED,ID	TD	12/13/2061
2021 PO4750650696	KU	4	45 BRN	SP	CRE	ID	TD	12/14/2061
2021 PO4722950609	KU	4	45 BRN	SP	CRE	ID	TD	12/15/2061
2021 PO4739950664	KU	4	45 BRN	SP	CRE	ID	TD	12/16/2061

2021	PO4168386195	LGE	4	40 BRO	SP	A	ED,ID	TD		12/17/2061
2021	PO4152185208	LGE	4	40 BRO	SP	A	ID	TD		12/18/2061
2021	PO4153385199	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		12/19/2061
2021	PO4150285227	LGE	4	40 BRO	SP	CRE	ED,ID	TD		12/20/2061
2021	PO4149985223	LGE	4	30 BRO	SP	P	ID	TD		12/21/2061
2021	PO4168886185	LGE	4	35 BRO	SP	A	ED,ID	TD		12/22/2061
2021	PO4149585246	LGE	4	40 BRO	SP	CRE	ED,ID	TD		12/23/2061
2021	PO4796950642	KU	5	35 BRN	SP	CRE	ID	TD		12/24/2061
2021	PO4159986185	LGE	4	40 BRO	SP	CRE	ED,ID	TD		12/25/2061
2021	PO4147885257	LGE	4	40 BRO	SP	P	ID	TD		12/26/2061
2021	PO4159186176	LGE	4	40 BRO	SP	A	ED,ID	TD		12/27/2061
2021	PO4758950714	KU	4	40 BRN	SP	CRE	ID	TD		12/28/2061
2021	PO4166686164	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		12/29/2061
2021	PO4167886184	LGE	4	35 BRO	SP	CRE	ED,ID	TD		12/30/2061
2021	PO4148885233	LGE	7	25 BRO	SP	CRE	ED,ID	TD		12/31/2061
2021	PO4783550688	KU	5	35 BRN	SP	CRE	ID	TD		1/1/2062
2021	PO4754950691	KU	6	30 BRN	SP	CRE	ID	TD		1/2/2062
2021	PO4157086129	LGE	4	40 BRO	SP	A	ED,ID	TD		1/3/2062
2021	PO4146285211	LGE	4	40 BRO	SP	CRE	ID	TD		1/4/2062
2021	PO4145685248	LGE	4	45 BRO	SP	CRE	ED,ID,IP	TD		1/5/2062
2021	PO4146785222	LGE	4	40 BRO	SP	CRE	ID	TD		1/6/2062
2021	PO4146885161	LGE	4	40 BRO	SP	A	ID,SRC	TD		1/7/2062
2021	PO4147685170A1	KU	4	40 BRO	SP	A	ED,ID,IP	TD		1/8/2062
2021	PO4146585184	LGE	4	40 BRO	SP	CRE	ED,ID	TD		1/9/2062
2021	PO4621350621	KU	6	30 BRN	SP	CRE	ID	TD		1/10/2062
2021	PO4148885156	LGE	4	35 BRO	SP	P	ID	TD		1/11/2062
2021	PO4158286128	LGE	4	40 BRO	SP	CRE	ED,ID	TD		1/12/2062
2021	PO4696850113	KU	4	45 BRN	SP	CRE	ID	TD		1/13/2062
2021	PO4707250041	KU	6	30 BRN	SP	CRE	ID	TD		1/14/2062
2021	PO4709150337	KU	3	60 BRN	SP	CRE	ID	TD		1/15/2062
2021	PO4156286133	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/16/2062
2021	PO4157486159	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		1/17/2062
2021	PO4714850181	KU	4	45 BRN	SP	CRE	ID	TD		1/18/2062
2021	PO4145285247	LGE	7	25 BRO	SP	CRE	ED,ID	TD		1/19/2062
2021	PO4168086174	LGE	4	30 BRO	SP	CCA	ED	T		1/20/2062
2021	PO4148985271	LGE	4	40 BRO	SP	CRE	ED,ID,RB	BX	RP3	1/21/2062
2021	PO4149185257	LGE	4	40 BRO	SP	A	ID	BD		1/22/2062
2021	PO4146885253	LGE	4	40 BRO	SP	CRE	ED,ID	BD		1/23/2062
2021	PO4754550488	KU	5	45 BRN	SP	CRE	ID	BD		1/24/2062
2021	PO4149285189	LGE	4	40 BRO	SP	CRE	ED,ID	BD		1/25/2062
2021	PO4145885160	LGE	7	25 BRO	SP	CRE	ID	BD		1/26/2062
2021	PO4148585180	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		1/27/2062
2021	PO4622049670	KU	4	40 BRN	SP	CRE	ED,RB	X	RP1	1/28/2062
2021	PO4162186128	LGE	4	35 BRO	SP	CRE	ED,ID,IP,RB	X	RP1	1/29/2062
2021	PO4577650233	KU	4	40 BRN	SP	CRE	HH,ID	X	RP2	1/30/2062
2021	PO4174786231	LGE	4	35 BRO	SP	A	ED,ID,IP	X	RP1	1/31/2062
2021	PO4171986168	F	4	40 BRO	SP	CRE	ED,ID,RB	VX	RP1	2/1/2062
2021	PO4166186113	F	4	40 BRO	SP	CRE	ID,RB	VX	RP1	2/2/2062
2021	PO4170786224	F	4	35 BRO	SP	CRE	HH,ID,RB	VX	RP1	2/3/2062
2021	PO0447305902	KU	4	40 UNK	SP	CCA		V		2/4/2062
2021	PO0418106121	KU	3	45 UNK	SP	CCA		V		2/5/2062
2021	PO4635450169	KU	6	30 BRN	SP	CCA		V		2/6/2062
2021	PO4624750248	F	4	40 BRN	SP	A	ID	V		2/7/2062
2021	PO4606450135	KU	2	50 BRN	SP	CCA		V		2/8/2062

2021 PO4597250065	KU	2	50 BRN	SP	CCA		V	2/9/2062
2021 PO4173686258	F	4	40 BRO	SP	CRE		V	2/10/2062
2021 PO4174386245	F	4	40 BRO	SP	CRE		V	2/11/2062
2021 PO4174886238	F	4	40 BRO	SP	CRE		V	2/12/2062
2021 PO4175886219	F	4	40 BRO	SP	CRE		V	2/13/2062
2021 PO4177086226	F	4	35 BRO	SP	A		V	2/14/2062
2021 PO4178186233	F	4	40 BRO	SP	CRE		V	2/15/2062
2021 PO4179386240	F	4	35 BRO	SP	A		V	2/16/2062
2021 PO5823110586	KU	3	45 ACW	SP	S		V	2/17/2062
2021 PO5829810640	KU	5	35 ACW	SP	S		V	2/18/2062
2021 PO4170786211	F	4	40 BRO	SP	A		V	2/19/2062
2021 PO3705025900	F	4	40 KOP	SP	P		V	2/20/2062
2021 PO4159285276	LGE	4	40 BRO	SP	CCA		V	2/21/2062
2021 PO4172186210	F	4	40 BRO	SP	A		V	2/22/2062
2021 PO4173486209	F	4	40 BRO	SP	CRE		V	2/23/2062
2021 PO4161185223	LGE	4	35 BRO	SP	CCA	ED,JD	V	2/24/2062
2021 PO4175386228	F	4	40 BRO	SP	CRE		V	2/25/2062
2021 PO4175086221	F	5	25 BRO	SP	CRE		V	2/26/2062
2021 PO4170786218	F	4	35 BRO	SP	CRE		V	2/27/2062
2021 PO4170786235	F	4	40 BRO	SP	CCA		V	2/28/2062
2021 PO4617849727	KU	3	45 BRN	SP	CCA		V	3/1/2062
2021 PO4639849778	KU	3	45 BRN	SP	CCA		V	3/2/2062
2021 PO4666449628	KU	3	45 BRN	SP	CCA		V	3/3/2062
2021 PO4661949830	KU	3	45 BRN	SP	CCA		V	3/4/2062
2021 PO4670649433	KU	3	45 BRN	SP	CCA		V	3/5/2062
2021 PO4599850530	KU	6	30 BRN	SP	CCA		V	3/6/2062
2021 PO4174386208	F	4	40 BRO	SP	A		V	3/7/2062
2021 PO4175586207	F	4	35 BRO	SP	CRE		V	3/8/2062
2021 PO4159385267	LGE	4	40 BRO	SP	CCA		V	3/9/2062
2021 PO0467405750	KU	1	65 UNK	SP	CCA		V	3/10/2062
2021 PO4608950577	KU	4	40 BRN	SP	CCA		V	3/11/2062
2021 PO4616150964	F	4	40 BRN	SP	CRE		V	3/12/2062
2021 PO4166186123	F	4	40 BRO	SP	CRE		V	3/13/2062
2021 PO4164686133	F	4	40 BRO	SP	A		V	3/14/2062
2021 PO4160786127	LGE	4	40 BRO	SP	CCA		V	3/15/2062
2021 PO4163786134	F	4	40 BRO	SP	CRE		V	3/16/2062
2021 PO4163086134	F	4	40 BRO	SP	CRE		V	3/17/2062
2021 PO4157685167	LGE	4	30 BRO	SP	CCA		V	3/18/2062
2021 PO4169785242	LGE	4	35 BRO	SP	CCA		V	3/19/2062
2021 PO4147485151	LGE	4	35 BRO	SP	CCA		V	3/20/2062
2021 PO4161786127	F	4	40 BRO	SP	CRE		V	3/21/2062
2021 PO4174486167	F	4	40 BRO	SP	CRE		V	3/22/2062
2021 PO4173286168	F	4	40 BRO	SP	CRE		V	3/23/2062
2021 PO4169986169	F	4	40 BRO	SP	CRE		V	3/24/2062
2021 PO4170986169	F	4	40 BRO	SP	CRE		V	3/25/2062
2021 PO5769310550	KU	1	75 ACW	SP	CRE		V	3/26/2062
2021 PO4175386167	F	3	45 BRO	SP	A		V	3/27/2062
2021 PO4176486166	F	3	45 BRO	SP	CCA		V	3/28/2062
2021 PO4160586127	F	4	40 BRO	SP	CRE		V	3/29/2062
2021 PO4082385363	LGE	4	35 ACE	SP	CCA		V	3/30/2062
2021 PO4166086105	F	3	45 BRO	SP	CCA		V	3/31/2062
2021 PO4520250355b	KU	3	45 BRN	SP	CCA		V	4/1/2062
2021 PO4426149781	F	4	40 BRN	SP	A		V	4/2/2062
2021 PO4447149802	F	4	40 BRN	SP	A		V	4/3/2062

2021 PO4469349824	F	4	40 BRN	SP	A		V	4/4/2062
2021 PO4496049851	F	4	40 BRN	SP	A		V	4/5/2062
2021 PO4498349857	KU	4	40 BRN	SP	A		V	4/6/2062
2021 PO4520250355	F	4	40 BRN	SP	A		V	4/7/2062
2021 PO4519450146	F	4	40 BRN	SP	A		V	4/8/2062
2021 PO4518549931	F	4	40 BRN	SP	A		V	4/9/2062
2021 PO4072985274	F	4	40 ACE	SP	P		V	4/10/2062
2021 PO4073985284	F	3	45 ACE	SP	CCA		V	4/11/2062
2021 PO4148085136	LGE	4	40 BRO	SP	CCA		V	4/12/2062
2021 PO4159785209	LGE	7	25 BRO	SP	CCA		V	4/13/2062
2021 PO4074385289	F	3	45 ACE	SP	CCA		V	4/14/2062
2021 PO4075085297	F	1	55 ACE	SP	CCA		V	4/15/2062
2021 PO4073685298	F	7	25 ACE	SP	P	ED,ID	V	4/16/2062
2021 PO4076085308	F	3	45 ACE	SP	CCA		V	4/17/2062
2021 PO4076885316	F	3	45 ACE	SP	CRE	ED,ID,JP	V	4/18/2062
2021 PO4077485323	F	3	45 ACE	SP	P		V	4/19/2062
2021 PO4078285331	F	3	45 ACE	SP	P		V	4/20/2062
2021 PO4078685336	F	3	45 ACE	SP	P		V	4/21/2062
2021 PO4079585346	F	3	45 ACE	SP	CCA		V	4/22/2062
2021 PO4080385355	F	3	45 ACE	SP	CCA		V	4/23/2062
2021 Po4520250355a	KU	3	35 BRN	SP	CCA		V	4/24/2062
2021 PO4582950415	F	4	40 BRN	SP	A		V	4/25/2062
2021 PO4589250736	F	2	60 BRN	SP	CCA		V	4/26/2062
2021 PO3609553226	KU	5	30 UNK	SP	CRE		V	4/27/2062
2021 PO3625953357	F	4	35 KOP	SP	P		V	4/28/2062
2021 PO4162385264	LGE	4	40 BRO	SP	CCA		V	4/29/2062
2021 PO4161385262	LGE	4	40 BRO	SP	CCA		V	4/30/2062
2021 PO6035011923	KU	4	45 ACW	SP	S		V	5/1/2062
2021 PO6040012081	KU	1	65 ACW	SP	S		V	5/2/2062
2021 PO6030212024	KU	2	60 ACW	SP	S		V	5/3/2062
2021 PO5965011765	KU	4	40 ACW	SP	S		V	5/4/2062
2021 PO5976711727	F	4	45 ACW	SP	P		V	5/5/2062
2021 PO5986911786	KU	4	45 ACW	SP	S		V	5/6/2062
2021 PO4184386204	F	4	40 BRO	SP	CRE		V	5/7/2062
2021 PO4160885262	LGE	4	40 BRO	SP	CCA		V	5/8/2062
2021 PO4597450989	F	3	45 BRN	SP	CCA		V	5/9/2062
2021 PO4602351141	KU	4	40 BRN	SP	CCA		V	5/10/2062
2021 PO4580949950	F	4	40 BRN	SP	A		V	5/11/2062
2021 PO4163885237	LGE	4	40 BRO	SP	CCA		V	5/12/2062
2021 PO5699110514	KU	3	45 ACW	SP	S		V	5/13/2062
2021 PO5690110523	KU	5	40 ACW	SP	S		V	5/14/2062
2021 PO5674310657	KU	5	35 ACW	SP	S		V	5/15/2062
2021 PO5662810597	KU	6	30 ACW	SP	S		V	5/16/2062
2021 PO5663910517	KU	6	30 ACW	SP	S		V	5/17/2062
2021 PO4176786259	F	4	40 BRO	SP	CRE		V	5/18/2062
2021 PO4175986242	LGE	5	25 BRO	SP	CRE		V	5/19/2062
2021 PO4175486251	F	4	35 BRO	SP	CRE		V	5/20/2062
2021 PO0331706770	KU	4	40 UNK	SP	CCA		V	5/21/2062
2021 PO4185286204	F	4	40 BRO	SP	CRE		V	5/22/2062
2021 PO4185686207	F	4	40 BRO	SP	CRE		V	5/23/2062
2021 PO3921241254	F	4	40 UNK	SP	CRE		V	5/24/2062
2021 PO4088985482	LGE	4	35 ACE	SP	P	ED,ID	V	5/25/2062
2021 PO4584349910	KU	4	40 BRN	SP	CCA		V	5/26/2062
2021 PO4089285490	LGE	3	50 ACE	SP	CRE		V	5/27/2062

2021 PO4177886265	F	4	35 BRO	SP	A		V			5/28/2062
2021 PO4162285220	LGE	3	45 BRO	SP	CCA		V			5/29/2062
2021 PO5843410770	F	4	40 ACW	SP	CCA		V			5/30/2062
2021 PO6019311977	KU	3	50 ACW	SP	S		V			5/31/2062
2021 PO4161785202	LGE	4	45 BRO	SP	A	ED,EP,ID,RB	TX	RR		6/1/2062
2021 PO5774110575	KU	6	30 ACW	SP	CRE	ED,EP,ID,MD,SRC	TX	RR		6/2/2062
2021 PO4157685222	LGE	4	40 BRO	SP	CRE	ED,ID	TX	RR		6/3/2062
2021 PO4156785222	LGE	3	45 BRO	SP	A	ID	TD			6/4/2062
2021 PO4176586177	LGE	4	30 BRO	SP	A	ED,ID	TD			6/5/2062
2021 PO4176986184	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			6/6/2062
2021 PO5777510377	KU	4	40 ACW	SP	CRE	ED,EP,ID	TD			6/7/2062
2021 PO5765410412	KU	2	45 ACW	SP	CRE	ED,ID	TD			6/8/2062
2021 PO5769110340	KU	6	30 ACW	DF	CRE	ED,ID,MD,SRC	TD			6/9/2062
2021 PO5758810511	KU	4	35 ACW	SP	CCA	ED,ID	TD			6/10/2062
2021 PO5796510434	KU	2	45 ACW	SP	CRE	ED,ID	TD			6/11/2062
2021 PO4611450659	KU	4	40 BRN	SP	CRE	ID	TD			6/12/2062
2021 PO4158285204	LGE	4	40 BRO	SP	CRE	ID	TD			6/13/2062
2021 PO4158385190	LGE	4	40 BRO	SP	CRE	ED,ID	TD			6/14/2062
2021 PO4159386128	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			6/15/2062
2021 PO4620850951	KU	4	40 BRN	SP	CRE	ID	TD			6/16/2062
2021 PO4614450753	KU	4	40 BRN	SP	CRE	ID	TD			6/17/2062
2021 PO4617150840	KU	5	35 BRN	SP	CRE	ID	TD			6/18/2062
2021 PO4089785421	LGE	4	40 ACE	SP	P	ED,ID	TD			6/19/2062
2021 PO4090685430	LGE	4	35 ACE	SP	P	ED,ID	TD			6/20/2062
2021 PO4158685221	LGE	4	40 BRO	SP	CRE	ED,ID	TD			6/21/2062
2021 PO0365405432	KU	3	45 UNK	SP	CCA	SRS	TD			6/22/2062
2021 PO4159885234	LGE	4	40 BRO	SP	A	ID	TD			6/23/2062
2021 PO5774910428	KU	1	45 ACW	SP	CRE	ED,ID	TD			6/24/2062
2021 PO5781510362	KU	2	45 ACW	SP	CRE	ED,ID	TD			6/25/2062
2021 PO3978520015	KU	4	45 KOP	SP	CRE	ID	TD			6/26/2062
2021 PO0416405749	KU	3	40 UNK	SP	CRE	ID,IP	TD			6/27/2062
2021 PO4160385246	LGE	4	40 BRO	SP	CRE	ED,ID	TD			6/28/2062
2021 PO4160485219	LGE	4	30 BRO	SP	CRE	ID	TD			6/29/2062
2021 PO0500705754	KU	4	40 UNK	SP	CCA	ID,SRS	TD			6/30/2062
2021 PO0525305756	KU	3	55 UNK	SP	CRE	ID	TD			7/1/2062
2021 PO4159585255	LGE	4	40 BRO	SP	CRE	ED,ID	TD			7/2/2062
2021 PO4176986196	LGE	4	40 BRO	SP	A	ED,ID,IP	TD			7/3/2062
2021 PO5814410518	KU	6	30 ACW	SP	CRE	ED,ID	TD			7/4/2062
2021 PO4161185218	LGE	4	40 BRO	SP	CCA	ED,ID	TD			7/5/2062
2021 PO4170686207	LGE	5	25 BRO	SP	CRE	ED,ID	TD			7/6/2062
2021 PO4097585535	LGE	4	35 ACE	SP	P	ED,ID	TD			7/7/2062
2021 PO4097985538	LGE	4	40 ACE	SP	P	ED,ID,IP	TD			7/8/2062
2021 PO4097785548	LGE	4	35 ACE	SP	P	ED,ID	TD			7/9/2062
2021 PO3762625955	KU	4	40 UNK	SP	CRE	ED,ID	TD			7/10/2062
2021 PO4588550002	KU	4	45 BRN	SP	CRE	ID	TD			7/11/2062
2021 PO4592250088	KU	4	45 BRN	SP	CRE	ID	TD			7/12/2062
2021 PO4616550204	KU	5	45 BRN	SP	CRE	ID	TD			7/13/2062
2021 PO0394306299	KU	4	45 UNK	SP	CRE	ID,IP,SRS	TD			7/14/2062
2021 PO4173386238	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD			7/15/2062
2021 PO0361706545	KU	4	40 UNK	SP	CRE	ID	TD			7/16/2062
2021 PO4617451424	KU	4	45 BRN	SP	CRE	ID	TD			7/17/2062
2021 PO4599051034	KU	6	30 BRN	SP	CRE	ID	TD			7/18/2062
2021 PO4164685239	LGE	4	40 BRO	SP	CRE	ED,HH,ID	TD			7/19/2062
2021 PO3633953422	KU	5	35 UNK	SP	CRE	ED,ID	TD			7/20/2062

2021 PO4080185356	LGE	4	35 ACE	SP	P	ED,ID	TD			7/21/2062
2021 PO4163685271	LGE	4	40 BRO	SP	A	ED,ID,IP	TD			7/22/2062
2021 PO3934741126	KU	5	35 UNK	SP	CRE	ID	TD			7/23/2062
2021 PO3946340917	KU	4	40 UNK	SP	CRE	ID	TD			7/24/2062
2021 PO4161285205	LGE	4	30 BRO	SP	CRE	ED,ID	TD			7/25/2062
2021 PO4161385211	LGE	4	35 BRO	SP	CRE	ID	TD			7/26/2062
2021 PO5839910812	KU	2	55 ACW	SP	CRE	ED,ID	TD			7/27/2062
2021 PO4176086270	LGE	4	30 BRO	SP	A	ED,ID,IP	TD			7/28/2062
2021 PO4613250361	KU	5	35 BRN	SP	CRE	ID	TD			7/29/2062
2021 PO4163285232	LGE	4	40 BRO	SP	CRE	ID,IP	TD			7/30/2062
2021 PO5856710957	KU	2	55 ACW	SP	CRE	ED,ID	TD			7/31/2062
2021 PO4185386197	LGE	4	30 BRO	SP	CCA	ED	T			8/1/2062
2021 PO4085785402	LGE	4	35 ACE	SP	CRE	ED,HH,ID,RB	BX		RP1	8/2/2062
2021 PO4096585532	LGE	6	25 ACE	SP	CRE	ED,HH,ID,RB	BX		RP1	8/3/2062
2021 PO4091385472	LGE	2	55 ACE	SP	P	ED,HH,ID,RB	BX		RP1	8/4/2062
2021 PO4159485221	LGE	4	40 BRO	SP	CRE	ED,ID,RB,SRC	BX		RR	8/5/2062
2021 PO4599250275	KU	4	40 BRN	SP	CRE	ED,ID,RB	BX		RP1	8/6/2062
2021 PO7619862481	F	4	40 BRO	SP	CRE		V			8/7/2062
2021 PO7636262540	F	4	40 BRO	SP	CRE		V			8/8/2062
2021 PO7628462472	F	4	40 BRO	SP	CRE		V			8/9/2062
2021 PO7635562201	F	6	30 BRO	SP	CRE		V			8/10/2062
2021 PO7633862394	F	4	40 BRO	SP	CRE		V			8/11/2062
2021 PO7598958500	KU	4	40 UNK	SP	CRE	HH,ID	TX		RR	8/12/2062
2021 PO7599558576	KU	6	30 UNK	SP	CRE	ID,IP	TD			8/13/2062
2021 PO7571958380	KU	4	45 UNK	SP	CCA		V			8/14/2062
2021 PO7581458198	KU	5	35 UNK	SP	CCA		V			8/15/2062
2021 PO7587558399	KU	5	35 UNK	SP	CRE	HH,ID	BX		RP2	8/16/2062
2021 PO3831419499	F	4	40 XXX	SP	P		V			8/17/2062
2021 PO3829819596	F	4	40 XXX	SP	P		V			8/18/2062
2021 PO3821319520	F	4	40 XXX	SP	P		V			8/19/2062
2021 PO3814719606	F	4	40 XXX	SP	P		V			8/20/2062
2021 PO3805419536	F	4	40 XXX	SP	CRE		V			8/21/2062
2021 PO3799719439	F	4	40 XXX	SP	P		V			8/22/2062
2021 PO3805519405	F	4	40 XXX	SP	P		V			8/23/2062
2021 PO3787819252	F	4	40 XXX	SP	P		V			8/24/2062
2021 PO3783919175	F	4	40 XXX	SP	P		V			8/25/2062
2021 PO3778519060	F	4	40 XXX	SP	P		V			8/26/2062
2021 PO4143486115	F	3	45 BRO	SP	A		V			8/27/2062
2021 PO4144286142	LGE	7	25 BRO	SP	CCA		V			8/28/2062
2021 PO7643762146	KU	6	30 BRO	SP	CCA		V			8/29/2062
2021 PO4145286132	F	3	45 BRO	SP	A		V			8/30/2062
2021 7649362159A	KU	6	30 BRO	SP	CCA		V			8/31/2062
2021 PO7649362159	F	4	40 BRO	SP	CRE		V			9/1/2062
2021 PO4143786160	LGE	4	35 BRO	SP	CCA	ED	T			9/2/2062
2021 PO4143786160-A	KU	5	35 BRO	SP	CCA	ED	T			9/3/2062
2021 PO4145786159	LGE	4	35 BRO	SP	CCA		V			9/4/2062
2021 PO7645362225	F	4	40 BRO	SP	CRE		V			9/5/2062
2021 PO8660274237	LGE	4	35 BRO	SP	CCA		V			9/6/2062
2021 PO8673774309	LGE	4	35 BRO	SP	CCA		V			9/7/2062
2021 PO8677874165	LGE	4	35 BRO	SP	CCA		V			9/8/2062
2021 PO4741803510	KU	7	30 BRN	SP	CRE	ED,ID	TD			9/9/2062
2021 PO4772503380	KU	7	35 BRN	SP	CRE	ED,ID	TD			9/10/2062
2021 PO4755803368	KU	7	30 BRN	SP	CCA		V			9/11/2062
2021 PO4752503774	KU	7	30 BRN	SP	CCA		V			9/12/2062

2021 PO4743903707	KU	3	40 BRN	SP	CRE	ED,ID	TD			9/13/2062
2021 PO4793503722	KU	6	30 BRN	SP	CRE	ED,ID	TD			9/14/2062
2021 PO4808004261	F	2	40 BRN	SP	CRE		V			9/15/2062
2021 PO1930515184	KU	5	35 BRO	SP	CRE	ED,ID	BD			9/16/2062
2021 PO1906214915	KU	5	40 BRO	SP	CRE	ED,ID	BD			9/17/2062
2021 PO1948215361	KU	4	40 BRO	SP	CRE	ID	BD			9/18/2062
2021 PO1441944628	KU	4	40 BRO	SP	CRE	ID	BD			9/19/2062
2021 PO1415944657	KU	4	40 BRO	SP	CRE	ID	TD			9/20/2062
2021 PO1568144818	KU	4	40 BRO	SP	CRE		V			9/21/2062
2021 PO1588644817	KU	6	30 BRO	SP	CRE	ID,MD	TD			9/22/2062
2021 PO1828443443	KU	4	45 BRO	SP	CRE	ID	TD			9/23/2062
2021 PO1798844070	KU	3	45 BRO	SP	CRE		V			9/24/2062
2021 PO1738844500	KU	5	35 BRO	SP	CRE	ED,EP,ID	BX	PX		9/25/2062
2021 PO1757544894	KU	3	45 BRN	SP	CCA	ED,ID,RB	X	PX		9/26/2062
2021 PO1726844999	KU	4	40 BRN	SP	CRE	ID	TD			9/27/2062
2021 PO1331544889	KU	4	40 BRN	SP	CRE	ID	TD			9/28/2062
2021 PO2573616419	KU	6	30 BRN	SP	CRE		V			9/29/2062
2021 PO4767604241	KU	3	40 BRN	SP	CRE	ED,HH,ID,IP,RB	X	PX		9/30/2062
2021 PO4777304235	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR		10/1/2062
2021 PO4718204293	KU	7	30 BRN	SP	CRE	ED,ID,SR	TD			10/2/2062
2021 PO4751304291	KU	5	40 BRN	SP	CRE	ED,ID	TD			10/3/2062
2021 PO4748304193	KU	7	30 BRN	SP	CRE	ED,ID	TD			10/4/2062
2021 PO4777904092	KU	7	30 BRN	SP	CRE	ED,ID	TD			10/5/2062
2021 PO4801104154	KU	3	45 BRN	SP	CCA		V			10/6/2062
2021 PO4799004242	KU	7	30E BRN	SP	CRE		V			10/7/2062
2021 PO4780404200	KU	4	40 BRN	SP	CRE	ED,ID	TD			10/8/2062
2021 PO4737204337	KU	4	40 BRN	SP	CRE	ED,ID	TD			10/9/2062
2021 PO7502964164	KU	4	40 BRO	SP	CCA		V			10/10/2062
2021 PO4152784743	LGE	4	40 ACE	SP	P	ED,EP,ID,IP	TX	RR		10/11/2062
2021 PO4150284861	LGE	4	40 ACE	SP	CRE	ED,EP,ID,IP	TD			10/12/2062
2021 PO7684159791	F	5	35 UNK	SP	CCA		V			10/13/2062
2021 PO7676959868	F	5	35 UNK	SP	CRE		V			10/14/2062
2021 PO7673659914	KU	6	30 UNK	SP	CRE	ID,IP	TD			10/15/2062
2021 PO7664359752	F	5	35 UNK	SP	CRE		V			10/16/2062
2021 PO4138786059	LGE	3	45 BRO	SP	CCA		V			10/17/2062
2021 PO4139186071	LGE	4	40 BRO	SP	A	ID,IP	BD			10/18/2062
2021 PO4151184846	LGE	5	30 ACE	SP	CRE	ED,ID,IP	TD			10/19/2062
2021 PO7589460543	KU	3	45 BRO	SP	CCA		V			10/20/2062
2021 PO4150184846	LGE	4	45 ACE	SP	P	ED,ID	TD			10/21/2062
2021 PO4149784849	LGE	5	30 ACE	SP	CRE	ED,ID	BD			10/22/2062
2021 PO4005317376	KU	4	45 XXX	SP	CRE	ED,ID,IP,MD	TD			10/23/2062
2021 PO4003917556	KU	3	45 BRN	SP	CCA		V			10/24/2062
2021 PO7614860499	KU	4	40 BRO	SP	CCA		V			10/25/2062
2021 PO7679861029	F	4	40 BRO	SP	CRE	ED,ID	V			10/26/2062
2021 PO7670661085	KU	5	35 BRO	SP	CRE	ED,ID	TD			10/27/2062
2021 PO4147286213	LGE	3	45 BRO	SP	CRE		V			10/28/2062
2021 PO8576091955	KU	4	40 BRO	SP	CRE		V			10/29/2062
2021 PO8532391910	KU	4	40 BRO	SP	CRE		V			10/30/2062
2021 PO8489491851	KU	4	40 BRO	SP	CRE		V			10/31/2062
2021 PO8491091674	KU	4	50 BRO	SP	CRE		V			11/1/2062
2021 PO8494491435	KU	5	35 BRO	SP	CRE		V			11/2/2062
2021 PO8499691204	KU	4	35 BRO	SP	CCA		V			11/3/2062
2021 PO8511190722	KU	5	35 BRO	SP	CRE		V			11/4/2062
2021 PO8555589976	KU	4	40 BRO	SP	CRE		V			11/5/2062

2021 PO8567989760	KU	4	40 BRO	SP	CRE		V		11/6/2062
2021 PO8580389543	KU	4	40 BRO	SP	CRE		V		11/7/2062
2021 PO7641759774	F	4	40 UNK	SP	CRE		V		11/8/2062
2021 PO7680459344	F	4	40 UNK	SP	CRE		V		11/9/2062
2021 PO4148986161	LGE	2	80 BRO	SP	P		V		11/10/2062
2021 PO4149086204	LGE	4	40 BRO	SP	CCA		V		11/11/2062
2021 PO7670860932	F	4	40 BRO	SP	CRE		V		11/12/2062
2021 PO7657460852	F	4	40 BRO	SP	CRE		V		11/13/2062
2021 PO4797503848	KU	3	40 BRN	SP	CRE	ED,ID	TD		11/14/2062
2021 PO4789403876	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/15/2062
2021 PO7681259416	KU	6	30 UNK	SP	CRE	ID,IP	TD		11/16/2062
2021 PO7673959414	F	4	40 UNK	SP	CRE		V		11/17/2062
2021 PO4150486169	LGE	3	45 BRO	ST	P		V		11/18/2062
2021 PO7664760522	KU	5	35 BRO	SP	CCA		V		11/19/2062
2021 PO4150684829	LGE	4	40 ACE	SP	P	ED,ID	BD		11/20/2062
2021 PO4151484832	LGE	4	40 ACE	SP	P	ED,ID,IP	BD		11/21/2062
2021 PO4001317766	KU	2	50 BRN	SP	CRE	ED,HH,ID,MD,RB	BX	PX	11/22/2062
2021 PO4001917706	KU	2	50 BRN	SP	CCA		V		11/23/2062
2021 PO4007117907	KU	5	35 XXX	SP	CRE	ED,ID	TD		11/24/2062
2021 PO3978318091	F	5	35 XXX	SP	P		V		11/25/2062
2021 PO3973917762	KU	2	55 XXX	SP	CRE	ED,ID	TD		11/26/2062
2021 PO3979617763	KU	2	55 BRN	SP	CCA		V		11/27/2062
2021 PO7650360662	F	4	40 BRO	SP	CRE		V		11/28/2062
2021 PO7643860559	F	4	40 BRO	SP	CCA		V		11/29/2062
2021 PO7640860616	KU	6	30 BRO	SP	CRE	ED,ID	TD		11/30/2062
2021 PO4715304102	KU	3	40 BRN	SP	CRE	ED,ID	TD		12/1/2062
2021 PO4698704277	KU	3	45 BRN	SP	CCA	ED	TD		12/2/2062
2021 PO4772503930	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/3/2062
2021 PO7666959492	F	4	40 UNK	SP	CRE		V		12/4/2062
2021 PO4742604032	KU	4	40 BRN	SP	CRE	ED	BD		12/5/2062
2021 PO3888313793	KU	6	30 XXX	SP	CRE	ID	BD		12/6/2062
2021 PO3888213870	F	4	40 XXX	SP	P		V		12/7/2062
2021 PO3877913632	KU	3	45 BRN	SP	CCA		V		12/8/2062
2021 PO3884514337	KU	4	40 XXX	SP	CRE	ED,ID	TD		12/9/2062
2021 PO3885314078	F	4	40 BRN	SP	CCA		V		12/10/2062
2021 PO3889013956	F	4	40 XXX	SP	P		V		12/11/2062
2021 PO3844414538	KU	4	40 BRN	SP	CCA		V		12/12/2062
2021 PO3876014120	KU	2	50 BRN	SP	CCA		V		12/13/2062
2021 PO7520956852	KU	4	40 UNK	SP	CRE	ID,IP	TD		12/14/2062
2021 PO7527456842	KU	4	40 UNK	SP	CRE	ID	TD		12/15/2062
2021 PO4145584705	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD		12/16/2062
2021 PO4144984710	LGE	6	25 ACE	SP	CRE	ED,ID,IP	TD		12/17/2062
2021 PO4145684709	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		12/18/2062
2021 PO4145884724	LGE	3	45 ACE	SP	P	ED,ID	TD		12/19/2062
2021 PO7823259593	F	4	40 BRO	SP	CRE		V		12/20/2062
2021 PO7816959663	F	4	40 BRO	SP	CRE		V		12/21/2062
2021 PO7811459720	F	4	40 BRO	SP	CRE		V		12/22/2062
2021 PO2317714757	KU	4	40 BRO	SP	CRE	ID	X	RP3	12/23/2062
2021 PO4172386263	F	4	40 BRO	SP	A		V		12/24/2062
2021 PO1361944682	KU	3	50 BRO	SP	CRE	ID	BD		12/25/2062
2021 PO4173186267	F	3	50 BRO	SP	A		V		12/26/2062
2021 PO1485744603	KU	4	45 BRO	SP	CRE		V		12/27/2062
2021 PO1510244569	KU	5	35 BRO	SP	CRE	ID	TD		12/28/2062
2021 PO1538344596	KU	4	40 BRO	SP	CRE	ID	BD		12/29/2062



2021 PO1545644611	KU	4	45 BRO	SP	CRE	ID	BD		12/30/2062
2021 PO7779258794	F	4	40 BRO	SP	CRE		V		12/31/2062
2021 PO7494556258	KU	2	45 UNK	SP	CRE	ID	TD		1/1/2063
2021 PO7501956303	KU	3	55 UNK	SP	CCA		V		1/2/2063
2021 PO7766658678	KU	4	45 BRO	SP	CRE	ED,ID	TD		1/3/2063
2021 PO7751858832	KU	4	45 BRO	SP	CRE	ED,ID	TD		1/4/2063
2021 PO4150984706	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD		1/5/2063
2021 PO3912713731	KU	4	40 XXX	SP	CRE	ED,ID	TD		1/6/2063
2021 PO5141222899	KU	4	40 BRO	SP	CCA		V		1/7/2063
2021 PO4172786296	F	4	40 BRO	SP	CRE		V		1/8/2063
2021 PO9071815455	KU	3	55 KOP	SP	CRE	ED,EP,HH,ID	BX	RP1	1/9/2063
2021 PO4173586305	F	4	40 BRO	SP	CRE		V		1/10/2063
2021 PO4174386310	F	4	40 BRO	SP	CRE		V		1/11/2063
2021 PO4150884701	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		1/12/2063
2021 PO4175186315	F	4	40 BRO	SP	CRE		V		1/13/2063
2021 PO4149384702	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		1/14/2063
2021 PO3943714026	KU	5	35 XXX	SP	CRE	ED,ID	TD		1/15/2063
2021 PO3927013878	KU	5	35 XXX	SP	CRE	ID	BD		1/16/2063
2021 PO3922313914	KU	3	45 BRN	SP	CCA		V		1/17/2063
2021 PO3900514038	KU	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	1/18/2063
2021 PO4176086319	F	4	40 BRO	SP	A		V		1/19/2063
2021 PO7521356415	KU	4	45 UNK	SP	CRE	ID	TD		1/20/2063
2021 PO7520456330	KU	5	35 UNK	SP	CCA		V		1/21/2063
2021 PO7822760382	F	5	30 BRO	SP	CRE		V		1/22/2063
2021 PO7822160339	F	4	40 BRO	SP	CRE		V		1/23/2063
2021 PO7828960346	F	4	40 BRO	SP	CRE		V		1/24/2063
2021 PO7837060484	F	4	40 BRO	SP	CRE		V		1/25/2063
2021 PO4815803001	KU	7	30 BRN	SP	CRE	ED,ID,SRC	TD		1/26/2063
2021 PO3881415190	KU	4	40 BRN	SP	CCA		V		1/27/2063
2021 PO3868715321	KU	4	40 XXX	SP	CRE	ED,ID	TD		1/28/2063
2021 PO7841460522	F	5	30 BRO	SP	CRE		V		1/29/2063
2021 PO7844260574	F	5	30 BRO	SP	CRE		V		1/30/2063
2021 PO7847960686	F	4	40 BRO	SP	CRE		V		1/31/2063
2021 PO7875460637	F	6	30 BRO	SP	CCA		V		2/1/2063
2021 PO7805860307	KU	3	45 BRO	SP	CCA		V		2/2/2063
2021 PO4145984740	LGE	3	45 ACE	SP	CCA		V		2/3/2063
2021 PO4130686011	LGE	4	40 BRO	SP	CCA		V		2/4/2063
2021 PO4147584738	LGE	3	45 ACE	SP	P	ED,ID	TD		2/5/2063
2021 PO4131986021	F	4	35 BRO	SP	CCA		V		2/6/2063
2021 PO8461672108	F	4	35 BRO	SP	CCA		V		2/7/2063
2021 PO8999267258	KU	4	40 BRO	SP	CRE		V		2/8/2063
2021 PO9614668256	KU	2	55 BRO	SP	CCA	ED,EP,HH,ID,IP,RB	VX	PX	2/9/2063
2021 PO9526368171	KU	3	60 BRO	SP	CRE	ED,ID	VX	RP2	2/10/2063
2021 PO9148767257	KU	2	50 BRO	SP	CCA	ED,EP	VX	RP2	2/11/2063
2021 PO8715288277	KU	7	25E BRO	SP	CRE	ED,ID,IP	BX	PX	2/12/2063
2021 PO8704188101	KU	5	35 BRO	SP	CRE	ED,ID,IP	BX	RP2	2/13/2063
2021 PO8995366928	KU	4	40 BRO	SP	CCA		V		2/14/2063
2021 PO9015166908	KU	3	45 BRO	SP	CCA		V		2/15/2063
2021 PO4490203622	KU	3	40 BRN	SP	CRE	ED,ID	TD		2/16/2063
2021 PO4498403636	KU	3	45 BRN	SP	CRE	ED,ID	TD		2/17/2063
2021 PO7625359648	KU	3	40 BRO	SP	S		V		2/18/2063
2021 PO7621859513	F	4	40 BRO	SP	CRE		V		2/19/2063
2021 PO7630859583	F	4	40 BRO	SP	CRE		V		2/20/2063
2021 PO7271954684	KU	6	30 UNK	SP	CRE	ID,IP,SRS	TD		2/21/2063

2021	PO4503703605	KU	3	45 BRN	SP	CCA	ED	TD			2/22/2063
2021	PO3747923289	F	4	40 KOP	SP	P		V			2/23/2063
2021	PO3782623867	F	4	40 KOP	SP	P		V			2/24/2063
2021	PO3677322803	F	4	40 KOP	SP	CRE		V			2/25/2063
2021	PO4146284772	LGE	4	45 ACE	SP	CRE	ED,ID	TD			2/26/2063
2021	PO4187486180	LGE	4	40 BRO	SP	CCA		V			2/27/2063
2021	PO5231522156	KU	3	45 BRO	SP	CCA		V			2/28/2063
2021	PO5234722362	KU	4	40 BRO	SP	CCA		V			3/1/2063
2021	PO5214522503	KU	4	40 BRO	SP	CCA		V			3/2/2063
2021	PO4145484788	LGE	7	25 ACE	SP	CRE	ED,ID,IP	TD			3/3/2063
2021	PO3956713632	KU	4	40 KOP	SP	CRE	ED,ID	TD			3/4/2063
2021	PO3943313495	KU	4	40 XXX	SP	CRE	ED,ID	TD			3/5/2063
2021	PO3927213620A	KU	4	40 BRN	SP	CCA		V			3/6/2063
2021	PO3942413599	KU	5	35 XXX	SP	CRE	ED,ID,RB	X	PX		3/7/2063
2021	PO3941314086	KU	4	40 XXX	SP	CRE	ID	BD			3/8/2063
2021	PO4518003905	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			3/9/2063
2021	PO7432155972	KU	4	40 UNK	SP	CRE	ID,IP	TD			3/10/2063
2021	PO4146384788	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD			3/11/2063
2021	PO4146884794	LGE	4	30 ACE	SP	CRE	ED,ID	TD			3/12/2063
2021	PO4187586211	LGE	4	40 BRO	SP	CCA		V			3/13/2063
2021	PO4522004029	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/14/2063
2021	PO4188986236	F	3	45 BRO	SP	CCA		V			3/15/2063
2021	PO7452456038	KU	3	40 UNK	SP	CCA		V			3/16/2063
2021	PO7445956149	KU	4	40 UNK	SP	P		V			3/17/2063
2021	PO5197622520	KU	5	35 BRO	SP	CRE	ED,ID	TD			3/18/2063
2021	PO5189322391	KU	3	45 BRO	SP	CCA	ID	BD			3/19/2063
2021	PO5186322396	KU	3	45 BRO	SP	CCA		V			3/20/2063
2021	PO5176822241	KU	3	45 BRO	SP	CCA		V			3/21/2063
2021	PO4148084788	LGE	4	40 ACE	SP	CCA		V			3/22/2063
2021	PO4149384778	LGE	7	25 ACE	SP	CRE	ED,ID,IP	BD			3/23/2063
2021	PO4149284787	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD			3/24/2063
2021	PO7481256201	KU	3	45 UNK	SP	CRE	ID,IP	BD			3/25/2063
2021	PO7808460367	KU	6	30 BRO	SP	CRE		V			3/26/2063
2021	PO7806160252	F	4	40 BRO	SP	CRE		V			3/27/2063
2021	PO7476556198	KU	4	45 UNK	SP	CRE		V			3/28/2063
2021	PO4525304133	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/29/2063
2021	PO4529604267	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/30/2063
2021	PO7814358011	KU	4	40 BRO	SP	CRE	ED,ID	BX	RP3		3/31/2063
2021	PO3933513670	KU	6	30 XXX	SP	CRE	ED,ID	TD			4/1/2063
2021	PO7796958951	KU	5	35 BRO	SP	CRE		V			4/2/2063
2021	PO7810258385	KU	4	40 BRO	SP	CRE	ED,ID	BX	RP3		4/3/2063
2021	PO4539204383	KU	6	35 BRN	SP	CRE	ED,ID	TD			4/4/2063
2021	PO5155222446	KU	3	45 BRO	SP	CCA		V			4/5/2063
2021	PO5174022711	KU	5	35 BRO	SP	CRE	ED,ID	BD			4/6/2063
2021	PO5152822861	KU	4	40 BRO	SP	CRE	ED,ID	BD			4/7/2063
2021	PO5124122492	KU	3	45 BRO	SP	CCA		V			4/8/2063
2021	PO5016102199	KU	3	45 BRN	SP	CCA		V			4/9/2063
2021	PO7800458815	KU	4	40 BRO	SP	CRE	ED,ID	TD			4/10/2063
2021	PO3927213620	KU	4	40 XXX	SP	CRE	ED,ID	TD			4/11/2063
2021	PO3929513717	KU	6	30 XXX	SP	CRE	ED,ID	TD			4/12/2063
2021	PO7530256098	KU	3	45 UNK	SP	CCA		V			4/13/2063
2021	PO7507956219	KU	6	30 UNK	SP	CRE	ID	BD			4/14/2063
2021	PO4176786289	F	4	40 BRO	SP	CRE		V			4/15/2063
2021	PO4175486281	F	4	40 BRO	SP	A		V			4/16/2063

2021 PO3983483668	F	3	45 BRO	SP	A		V	4/17/2063
2021 PO3983483681	F	4	40 BRO	SP	CRE		V	4/18/2063
2021 PO3983483692	F	4	40 BRO	SP	A		V	4/19/2063
2021 PO3983583704	F	3	45 BRO	SP	A		V	4/20/2063
2021 PO3983683716	F	4	40 BRO	SP	CRE		V	4/21/2063
2021 PO7441569863a	KU	2	60E ACE	SP	CCA		V	4/22/2063
2021 PO7441569863	KU	3	40 ACE	SP	CCA		V	4/23/2063
2021 PO7428370015	KU	1	60E ACE	SP	CCA		V	4/24/2063
2021 PO7415370164	KU	3	40 ACE	SP	CCA		V	4/25/2063
2021 PO4025684766	LGE	4	30 BRN	SP	CCA		V	4/26/2063
2021 PO4024984751	F	4	30 BRN	SP	P		V	4/27/2063
2021 PO4024484746	F	4	40 BRN	SP	CRE		V	4/28/2063
2021 PO4025084759	F	7	25 BRN	SP	CRE		V	4/29/2063
2021 PO4024484762	F	4	40 BRN	SP	CCA		V	4/30/2063
2021 PO4024884730	F	7	25 BRN	SP	CRE		V	5/1/2063
2021 PO4025384739	F	4	40 BRN	SP	A		V	5/2/2063
2021 PO4036284101	LGE	4	35 BRO	UN	CCA		V	5/3/2063
2021 PO3999684190	F	4	30 ACE	SP	A	ED	V	5/4/2063
2021 PO3999884186	F	4	40 ACE	SP	CCA	ED	V	5/5/2063
2021 PO0470801334	KU	4	40 BRN	SP	CCA		T	5/6/2063
2021 PO0468401555	KU	4	40 BRN	SP	CCA		T	5/7/2063
2021 PO0418200928	KU	3	40 BRO	SP	S		V	5/8/2063
2021 PO0409900937	F	4	40 BRO	SP	P		V	5/9/2063
2021 PO0415000827	KU	4	40 BRO	SP	S		V	5/10/2063
2021 PO0416001035	KU	6	30 BRO	SP	S		V	5/11/2063
2021 PO4000884186	F	4	40 ACE	SP	CCA	ED	V	5/12/2063
2021 PO7187953593	LGE	4	40 ACE	SP	CCA		V	5/13/2063
2021 PO7192753591	LGE	4	40 ACE	SP	CCA	ED	V	5/14/2063
2021 PO4130484534	LGE	4	35 BRO	SP	P	ED,ID	TD	5/15/2063
2021 PO4133484491	LGE	3	45 BRO	SP	CCA		V	5/16/2063
2021 PO4131884523	LGE	4	35 BRO	SP	CRE	ED,ID	BD	5/17/2063
2021 PO4130484526	LGE	4	35 BRO	SP	CRE	ED,ID	BD	5/18/2063
2021 PO4129684524	LGE	4	35 BRO	SP	CRE	ED,ID	BD	5/19/2063
2021 PO4129584515	LGE	UNK	25 BRO	SP	CRE	ED,ID,IP	BD	5/20/2063
2021 PO4130084507	LGE	4	40 BRO	SP	CCA		V	5/21/2063
2021 PO4129484514	LGE	3	45 BRO	SP	P	ED,ID	BD	5/22/2063
2021 PO4130484496-A	KU	4	30 BRO	SP	P	ED,EP,ID,IP	BD	5/23/2063
2021 PO4130484496	KU	4	30 BRO	SP	CCA		V	5/24/2063
2021 PO4131584501	LGE	4	40 BRO	SP	P	ED,ID	BD	5/25/2063
2021 PO4003384128	F	3	45 ACE	SP	CCA	ED	V	5/26/2063
2021 PO0465901808	KU	4	40 BRN	SP	CCA		T	5/27/2063
2021 PO4003484143	F	3	45 ACE	SP	CCA		V	5/28/2063
2021 PO4002884139	LGE	4	30 ACE	SP	CCA		V	5/29/2063
2021 PO9967678983	KU	4	40 BRN	SP	CRE	IP,MD	BD	5/30/2063
2021 PO0405100862	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/31/2063
2021 PO0395000964	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/1/2063
2021 PO0399001109	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/2/2063
2021 PO4003584163	F	3	45 ACE	SP	CCA		V	6/3/2063
2021 PO7195653413	LGE	4	35 ACE	SP	CCA	ED	V	6/4/2063
2021 PO4003784184	F	4	40 ACE	SP	A	ED	V	6/5/2063
2021 PO4003884195	F	4	40 ACE	SP	CRE	ED	V	6/6/2063
2021 PO4003884208	F	3	45 ACE	SP	CCA		V	6/7/2063
2021 PO4004184242	F	4	40 ACE	SP	CCA	ED	V	6/8/2063
2021 PO4004084231	F	3	45 ACE	SP	CCA		V	6/9/2063

2021 PO0382600867	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/10/2063
2021 PO0357301099	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/11/2063
2021 PO0384301004	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/12/2063
2021 PO0449202076	KU	4	40 KOP	SP	CCA		T	6/13/2063
2021 PO0038279347	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	6/14/2063
2021 PO4024984361	LGE	4	30 ACE	SP	P	ED	TD	6/15/2063
2021 PO4024384365	F	4	40 ACE	SP	P		V	6/16/2063
2021 PO4023284367	F	4	40 ACE	SP	CCA		V	6/17/2063
2021 PO4022584369	F	4	40 ACE	SP	CRE		V	6/18/2063
2021 PO4022284366	F	6	30 ACE	SP	P		V	6/19/2063
2021 PO4020884401	LGE	4	35 ACE	SP	CCA		V	6/20/2063
2021 PO7373655708	LGE	3	45 ACE	SP	CCA		V	6/21/2063
2021 PO4021284375	F	4	40 ACE	SP	P		V	6/22/2063
2021 PO4021284371	F	3	45 ACE	SP	CRE		V	6/23/2063
2021 PO0543100724	KU	4	40 KOP	SP	CRE	ID	TD	6/24/2063
2021 PO7276469282	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	6/25/2063
2021 PO7290969394	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/26/2063
2021 PO7281969426	KU	5	35 ACE	SP	CRE	ED,ID	TD	6/27/2063
2021 PO7372855487	LGE	3	45 ACE	SP	CCA		V	6/28/2063
2021 PO4019784374	LGE	4	40 ACE	SP	A	ED	TD	6/29/2063
2021 PO4020084384	LGE	4	35 ACE	SP	P	ED	TD	6/30/2063
2021 PO7259869025	KU	3	40 ACE	SP	CCA		V	7/1/2063
2021 PO7245969179	KU	3	40 ACE	SP	CCA		V	7/2/2063
2021 PO4018784369	LGE	4	35 ACE	SP	P	ED	TD	7/3/2063
2021 PO7233069321	KU	3	45 ACE	SP	CCA		V	7/4/2063
2021 PO7220669453	KU	3	45 ACE	SP	CCA		V	7/5/2063
2021 PO7251569466	KU	3	40 ACE	SP	CCA		V	7/6/2063
2021 PO7268369611	KU	3	40 ACE	SP	CCA		V	7/7/2063
2021 PO7283269738	KU	3	40 ACE	SP	CCA		V	7/8/2063
2021 PO4019084375	F	4	40 ACE	SP	P		V	7/9/2063
2021 PO7308769601	KU	4	40 ACE	SP	CCA		V	7/10/2063
2021 PO4017684378	F	4	40 ACE	SP	CRE		V	7/11/2063
2021 PO4016484380	F	4	40 ACE	SP	CRE		V	7/12/2063
2021 PO7321869577	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	7/13/2063
2021 PO4015384387	F	4	30 ACE	SP	P		V	7/14/2063
2021 PO4015084383	F	4	40 ACE	SP	P		V	7/15/2063
2021 PO4013884385	F	4	40 ACE	SP	CCA		V	7/16/2063
2021 PO7299069873	KU	3	40 ACE	SP	CCA		V	7/17/2063
2021 PO4013184391	LGE	4	30 ACE	SP	P	ED	TD	7/18/2063
2021 PO7439869529	KU	3	40 ACE	SP	CRE	ED,ID	BD	7/19/2063
2021 PO7463369712	KU	4	40 ACE	SP	CRE	ED,ID	BD	7/20/2063
2021 PO4012784387	F	4	40 ACE	SP	CRE		V	7/21/2063
2021 PO7351669886	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX PX	7/22/2063
2021 PO7330370009	KU	3	40 ACE	SP	CCA		V	7/23/2063
2021 PO4009784393	LGE	4	40 ACE	SP	A	ED	TD	7/24/2063
2021 PO0537800666	F	4	40 KOP	SP	CRE		V	7/25/2063
2021 PO7352570103	KU	3	40 ACE	SP	CCA		V	7/26/2063
2021 PO7379670227	KU	3	40 ACE	SP	CCA		V	7/27/2063
2021 PO4011484386	LGE	4	30 ACE	SP	CCA		V	7/28/2063
2021 PO4003084256	LGE	4	40 ACE	SP	CRE	ED,ID	BD	7/29/2063
2021 PO4004284260	F	4	35 ACE	SP	A	ED	V	7/30/2063
2021 PO0431002336	KU	4	40 KOP	SP	CRE		T	7/31/2063
2021 PO0435502432	KU	6	30 KOP	SP	CCA		T	8/1/2063
2021 PO0040079093	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	8/2/2063

2021 PO0004179244	KU	4	45 BRN	SP	CRE	ED,SRS	TD	8/3/2063
2021 PO0080879607	KU	4	40 BRN	SP	CRE	ID,IP,SRS	TD	8/4/2063
2021 PO4005784271	LGE	4	35 ACE	SP	A	ED,ID	BD	8/5/2063
2021 PO4003684276	F	4	30 ACE	SP	A	ED	V	8/6/2063
2021 PO4004484276	F	3	35 ACE	SP	CCA		V	8/7/2063
2021 40040LGE84297	KU	4	30 ACE	SP	CCA	ED,ID	TD	8/8/2063
2021 PO4004584297	F	3	35 ACE	SP	CCA	ED	V	8/9/2063
2021 PO4004884332	F	3	45 ACE	SP	CCA		V	8/10/2063
2021 PO4005084352	F	4	35 ACE	SP	A	ED	V	8/11/2063
2021 PO4004684364	F	4	30 ACE	SP	CRE	ED	V	8/12/2063
2021 PO4005184361	F	3	45 ACE	SP	CCA		V	8/13/2063
2021 PO4011684389	F	4	40 ACE	SP	P		V	8/14/2063
2021 PO4010784391	F	4	40 ACE	SP	CCA		V	8/15/2063
2021 PO0535600584	KU	4	40 KOP	SP	CRE	ID	TD	8/16/2063
2021 PO0561300631	KU	6	30 KOP	SP	CRE	ID	TD	8/17/2063
2021 PO0586000549	KU	6	30 KOP	SP	CRE	ID	TD	8/18/2063
2021 PO7606471694	KU	6	30 ACE	SP	CCA		V	8/19/2063
2021 PO7607471641	KU	3	45 ACE	SP	CRE	ED,ID	BD	8/20/2063
2021 PO4008484396	LGE	4	40 ACE	SP	CRE	ED	TD	8/21/2063
2021 PO0586000549	KU	5	30 KOP	SP	CRE	ID	TD	8/22/2063
2021 PO0424100833	KU	4	40 KOP	SP	CRE	ID	TD	8/23/2063
2021 PO0452000878	KU	6	30 KOP	SP	CCA		V	8/24/2063
2021 PO7625271769	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	8/25/2063
2021 PO7629871801	KU	3	45 ACE	SP	CRE	ED,ID	BD	8/26/2063
2021 PO7657871735	KU	3	45 ACE	SP	CCA		V	8/27/2063
2021 PO7651171677	KU	6	30 ACE	SP	CCA		V	8/28/2063
2021 PO4008184367	LGE	4	30 ACE	SP	CRE		V	8/29/2063
2021 PO4007984395	LGE	4	40 ACE	SP	P	ED,ID	TD	8/30/2063
2021 PO4128684527	LGE	3	45 BRO	SP	CCA		V	8/31/2063
2021 PO4126584533	LGE	4	40 BRO	SP	P	ED,ID	TD	9/1/2063
2021 PO4126984542	LGE	4	40 BRO	SP	CCA	ED,ID,IP	BD	9/2/2063
2021 PO4127884535	LGE	4	40 BRO	SP	A	ED,ID,IP	BD	9/3/2063
2021 PO0428800904	F	4	40 KOP	SP	CRE		V	9/4/2063
2021 PO0454701004	KU	6	30 KOP	SP	CRE		V	9/5/2063
2021 PO0578500562	KU	5	35 BRO	SP	CRE	ED,ID	TD	9/6/2063
2021 PO7647171926	KU	3	45 ACE	SP	CRE	ED,ID	TD	9/7/2063
2021 PO7637171984	KU	4	45 ACE	SP	CRE	ED,ID	TD	9/8/2063
2021 PO7646472080	KU	4	45 ACE	SP	CRE	ED,ID	TD	9/9/2063
2021 PO7641372006	KU	6	30 ACE	SP	CCA		V	9/10/2063
2021 PO7645671895	KU	3	45 ACE	SP	CCA		V	9/11/2063
2021 PO0518000717	F	5	40 KOP	SP	CRE		V	9/12/2063
2021 PO7634971899	KU	6	30 ACE	SP	CCA		V	9/13/2063
2021 PO7642371798	KU	6	30 ACE	SP	CCA		V	9/14/2063
2021 PO7647272066	KU	4	45 ACE	SP	CCA		V	9/15/2063
2021 PO7644072107	KU	3	50 ACE	SP	CCA		V	9/16/2063
2021 PO4125884525	LGE	3	45 BRO	SP	P	ED,ID	TD	9/17/2063
2021 PO0498800768	F	4	40 UNK	SP	P		V	9/18/2063
2021 PO0483700802	F	4	40 UNK	SP	P		V	9/19/2063
2021 PO0470900825	F	5	35 BRN	SP	CRE		V	9/20/2063
2021 PO0460200847	KU	4	40 BRN	SP	CCA		T	9/21/2063
2021 PO0472701150	KU	4	40 BRN	SP	CCA		V	9/22/2063
2021 PO0559300524	KU	4	40 BRO	SP	CRE	ED,ID,IP,MD	TD	9/23/2063
2021 PO4127484499	LGE	4	30 BRO	SP	P	ED,ID	TD	9/24/2063
2021 PO5667084852	KU	4	45 KOP	SP	CRE	ED,ID	TD	9/25/2063

2021 PO4033884470	LGE	4	30 BRN	SP	A	ID	TD	9/26/2063
2021 PO4033684475	LGE	3	45 BRN	SP	CCA		V	9/27/2063
2021 PO4034384475	F	4	40 BRN	SP	CRE		V	9/28/2063
2021 PO4032884477	F	4	40 BRN	SP	CCA		V	9/29/2063
2021 PO4031984476	LGE	4	40 BRN	SP	A	ED,ID	BD	9/30/2063
2021 PO4031184482	F	4	45 BRN	SP	P		V	10/1/2063
2021 PO7451456701	F	3	45 BRN	SP	CCA		V	10/2/2063
2021 PO4030184484	F	3	45 BRN	SP	CCA		V	10/3/2063
2021 PO4028884489	F	4	40 BRN	SP	CRE		V	10/4/2063
2021 PO4028484489	F	4	40 BRN	SP	CRE		V	10/5/2063
2021 PO4026584475	F	4	30 BRN	SP	P		V	10/6/2063
2021 PO4026884483	F	4	45 BRN	DF	CRE		V	10/7/2063
2021 PO4026884487	LGE	4	30 BRN	SP	A		V	10/8/2063
2021 PO4027084493	F	4	40 BRN	SP	CRE		V	10/9/2063
2021 PO4025984492	LGE	7	25 BRN	SP	CRE		V	10/10/2063
2021 PO4026084496	F	4	40 BRN	SP	A		V	10/11/2063
2021 PO4024784500	F	4	40 BRN	SP	CRE		V	10/12/2063
2021 PO7372556223	F	4	30 BRN	SP	CRE		V	10/13/2063
2021 PO4021684447	F	4	40 BRN	SP	CRE		V	10/14/2063
2021 PO4022284464	F	4	40 BRN	SP	CRE		V	10/15/2063
2021 PO4022584475	F	4	40 BRN	SP	A		V	10/16/2063
2021 PO4023284495	F	4	35 BRN	SP	CRE		V	10/17/2063
2021 PO4023784503	F	4	40 BRN	SP	CRE		V	10/18/2063
2021 PO4022284512	F	4	30 BRN	SP	CRE		V	10/19/2063
2021 PO4021784509	F	4	40 BRN	SP	CRE		V	10/20/2063
2021 PO4020684477	F	4	40 BRN	SP	A		V	10/21/2063
2021 PO4020384494	F	4	40 BRN	SP	P		V	10/22/2063
2021 PO4020184481	LGE	4	40 BRN	SP	P	ED,EP,ID,RB	X	10/23/2063
2021 PO4020584529	F	4	35 BRN	SP	CCA		V	10/24/2063
2021 PO4019984510	F	7	25 BRN	SP	CRE		V	10/25/2063
2021 PO4019584515	F	5	30 BRN	SP	CCA		V	10/26/2063
2021 PO4020084513	F	4	40 BRN	SP	CCA		V	10/27/2063
2021 PO4011584119	LGE	UNK	25 ACE	SP	CRE		V	10/28/2063
2021 PO4012384140	F	4	40 ACE	SP	CRE	ED	V	10/29/2063
2021 PO4012484157	F	4	40 ACE	SP	A	ED	V	10/30/2063
2021 PO4012584175	F	4	40 ACE	SP	P	ED	V	10/31/2063
2021 PO0004979784	KU	4	45 BRN	SP	CRE	ED,IP,MD,SRS	TD	11/1/2063
2021 PO0034279741	KU	4	45 BRN	SP	CCA	ED,IP,SRS	TD	11/2/2063
2021 PO4012684184	LGE	4	40 ACE	SP	CRE	ED,ID	BD	11/3/2063
2021 PO7288953672	LGE	3	45 ACE	SP	CCA	ED	V	11/4/2063
2021 PO4012784215	F	4	40 ACE	SP	CRE	ED	V	11/5/2063
2021 PO4013384215	LGE	4	30 ACE	SP	CRE	ED,ID	TD	11/6/2063
2021 PO0051799673	KU	4	40 XXX	SP	CRE	ID	TD	11/7/2063
2021 PO0194700729	KU	6	30 XXX	SP	CCA		V	11/8/2063
2021 PO4026884289	F	4	40 BRN	SP	CCA		V	11/9/2063
2021 PO4026584277	F	4	35 BRN	SP	A		V	11/10/2063
2021 PO4026384264	F	4	45 BRN	SP	CCA		V	11/11/2063
2021 PO4026484248	F	6	30 BRN	SP	CCA		V	11/12/2063
2021 PO4026084249	F	4	40 BRN	SP	CCA		V	11/13/2063
2021 PO4024484205	F	4	40 BRN	SP	CCA		V	11/14/2063
2021 PO4025484169	F	1	55 BRN	SP	CCA		V	11/15/2063
2021 PO4026684199	F	1	50 BRN	SP	CCA		V	11/16/2063
2021 PO4026984210	F	1	50 BRN	SP	CCA		V	11/17/2063
2021 PO4027484225	F	1	50 BRN	SP	CCA		V	11/18/2063

2021 PO4027784235	F	1	50 BRN	SP	CCA		V	11/19/2063
2021 PO4028184252	F	1	50 BRN	SP	CCA		V	11/20/2063
2021 PO4028484268	F	3	45 BRN	SP	CCA		V	11/21/2063
2021 PO4028684275	F	1	50 BRN	SP	CCA		V	11/22/2063
2021 PO4028284288	LGE	4	35 BRN	SP	CCA		V	11/23/2063
2021 PO4028884287	F	1	50 BRN	SP	CCA		V	11/24/2063
2021 PO0122180292	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	11/25/2063
2021 PO0060479901	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	11/26/2063
2021 PO4008284133	LGE	4	30 ACE	SP	CCA		V	11/27/2063
2021 PO4007783600	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	11/28/2063
2021 PO4008984123	F	4	35 ACE	SP	CCA	ED	V	11/29/2063
2021 PO4007584138	F	4	40 ACE	SP	A	ED	V	11/30/2063
2021 PO4007684151	F	3	45 ACE	SP	CCA	ED	V	12/1/2063
2021 PO4007784165	F	3	45 ACE	SP	CCA	ED	V	12/2/2063
2021 PO4032383050	F	4	35 BRO	SP	CRE		V	12/3/2063
2021 PO4007184179	LGE	4	30 ACE	SP	A	ED,ID	BD	12/4/2063
2021 PO4007884179	F	4	40 ACE	SP	CRE	ED	V	12/5/2063
2021 PO4035883153	F	4	30 BRO	SP	CCA		V	12/6/2063
2021 PO4035383151	F	4	40 BRO	SP	A		V	12/7/2063
2021 PO4035583144	F	3	45 BRO	SP	A		V	12/8/2063
2021 PO4035983135	F	4	30 BRO	SP	CRE		V	12/9/2063
2021 PO7534143060	F	3	45 BRO	SP	CRE		V	12/10/2063
2021 PO4007984192	F	3	45 ACE	SP	CCA	ED	V	12/11/2063
2021 PO4035383151-A	KU	3	45 BRO	SP	CCA		V	12/12/2063
2021 PO4008084205	F	3	45 ACE	SP	CCA		V	12/13/2063
2021 PO4008284232	F	4	40 ACE	SP	CCA	ED	V	12/14/2063
2021 PO4008184217	F	4	40 ACE	SP	CCA	ED	V	12/15/2063
2021 PO4035683174	LGE	3	45 BRO	SP	CCA		V	12/16/2063
2021 PO4035083181	F	4	40 BRO	SP	A		V	12/17/2063
2021 PO4034783192	F	4	40 BRO	SP	CRE		V	12/18/2063
2021 PO4034183203	F	4	40 BRO	SP	A		V	12/19/2063
2021 PO4033683214	LGE	3	45 BRO	SP	A		V	12/20/2063
2021 PO4033183222	F	4	40 BRO	SP	A		V	12/21/2063
2021 PO4008384241	F	4	40 ACE	SP	A	ED	V	12/22/2063
2021 PO4075885028	LGE	3	45 ACE	SP	P		V	12/23/2063
2021 PO4074885011	LGE	3	45 ACE	SP	CRE		V	12/24/2063
2021 PO4073784992	LGE	2	45 ACE	SP	CRE		V	12/25/2063
2021 PO3875785305	LGE	2	55 ACE	SP	CRE	ED,ID	BD	12/26/2063
2021 PO3876085309	LGE	2	60 ACE	SP	CCA		V	12/27/2063
2021 PO3873285313	LGE	3	50 ACE	SP	CRE	ED,ID	BD	12/28/2063
2021 PO4072784974	LGE	3	45 ACE	SP	CRE		V	12/29/2063
2021 PO4071784957	LGE	3	45 ACE	SP	CRE		V	12/30/2063
2021 PO4070784940	LGE	3	45 ACE	SP	CRE		V	12/31/2063
2021 PO4069784923	LGE	3	50 ACE	SP	CRE		V	1/1/2064
2021 PO7845660914	LGE	3	45 ACE	SP	CCA		V	1/2/2064
2021 PO4068784908	LGE	3	45 ACE	SP	CCA		V	1/3/2064
2021 PO4067784891	LGE	3	50 ACE	SP	CCA		V	1/4/2064
2021 PO4066584870	LGE	3	50 ACE	SP	CCA		V	1/5/2064
2021 PO4065684856	LGE	3	50 ACE	SP	CCA		V	1/6/2064
2021 PO4064784839	LGE	3	50 ACE	SP	A		V	1/7/2064
2021 PO4064084827	LGE	3	50 ACE	SP	CCA		V	1/8/2064
2021 PO4058384472	LGE	4	40 ACE	SP	CRE	ED,ID	TD	1/9/2064
2021 PO4063384816	LGE	3	50 ACE	SP	CRE		V	1/10/2064
2021 PO4022784996	F	4	40 BRO	SP	A		V	1/11/2064

2021 PO4022484980	F	3	50 BRO	SP	CCA		V	1/12/2064
2021 PO4020684982	F	4	45 BRO	SP	CRE		V	1/13/2064
2021 PO4020284970	F	4	40 BRO	SP	CRE		V	1/14/2064
2021 PO4021084987	LGE	4	30 BRO	SP	CCA		V	1/15/2064
2021 PO4009584864	F	4	30 BRO	SP	CRE		V	1/16/2064
2021 PO4010384849	F	4	40 BRO	SP	CRE		V	1/17/2064
2021 PO4010884850	F	4	30 BRO	SP	CRE		V	1/18/2064
2021 PO4010684861	F	3	45 BRO	SP	CCA		V	1/19/2064
2021 PO3873285296	LGE	3	50 ACE	SP	CCA		V	1/20/2064
2021 PO5255557522	KU	4	40 BRN	SP	CRE	ID	BD	1/21/2064
2021 PO4010384878	F	5	30 BRO	SP	CRE		V	1/22/2064
2021 PO4011084873	F	4	40 BRO	SP	CRE		V	1/23/2064
2021 PO5036539215	KU	2	50 UNK	SP	CRE	ED,ID	X RP1	1/24/2064
2021 PO3900885309	LGE	1	70 ACE	SP	CRE		V	1/25/2064
2021 PO3900685312	LGE	1	75 ACE	SP	P		V	1/26/2064
2021 PO7305161019	LGE	3	45 BRO	SP	CCA		V	1/27/2064
2021 PO4014984906	F	4	40 BRO	SP	CCA		V	1/28/2064
2021 PO4014984850	LGE	3	45 BRO	SP	CCA		V	1/29/2064
2021 PO4015384872	LGE	3	45 BRO	SP	CCA		V	1/30/2064
2021 PO3997285301	LGE	7	25 ACE	SP	CCA		V	1/31/2064
2021 PO5038739177	KU	3	45 KOP	SP	CRE	ID	BD	2/1/2064
2021 PO4016484893	F	4	40 BRO	SP	CCA		V	2/2/2064
2021 PO4015684893	LGE	3	45 BRO	SP	CCA		V	2/3/2064
2021 PO3903685355	LGE	3	50 ACE	SP	P	ED,ID	TD	2/4/2064
2021 PO3903585360	LGE	3	45 ACE	SP	P	ED,ID	BD	2/5/2064
2021 PO4018184902	F	4	40 BRO	SP	CCA		V	2/6/2064
2021 PO4019484900	F	4	40 BRO	SP	CRE		V	2/7/2064
2021 PO4020884889	F	5	30 BRO	SP	A		V	2/8/2064
2021 PO4020884897	LGE	3	45 BRO	SP	CCA		V	2/9/2064
2021 PO4016584903	F	4	40 BRO	SP	CRE		V	2/10/2064
2021 PO4015784915	F	4	40 BRO	SP	CRE		V	2/11/2064
2021 PO4016684913	LGE	5	30 BRO	SP	CCA		V	2/12/2064
2021 PO4016784922	F	3	45 BRO	SP	CCA		V	2/13/2064
2021 PO4017684935	F	4	35 BRO	SP	CRE		V	2/14/2064
2021 PO4018084942	F	3	50 BRO	SP	CRE		V	2/15/2064
2021 PO4018884935	LGE	4	30 BRO	SP	CCA		V	2/16/2064
2021 PO4019784928	F	3	50 BRO	SP	CRE		V	2/17/2064
2021 PO3902885340	LGE	1	75 ACE	SP	P		V	2/18/2064
2021 PO4999239312	KU	3	45 ACW	SP	CRE	ID	TD	2/19/2064
2021 PO5001339358	KU	2	45 ESC	SP	CRE	ED,ID,IP	TD	2/20/2064
2021 PO3900585352	LGE	2	65 ACE	SP	CCA		V	2/21/2064
2021 PO3898285365	LGE	3	50 ACE	SP	CCA		V	2/22/2064
2021 PO3895985377	LGE	3	50 ACE	SP	CCA		V	2/23/2064
2021 PO4117985109	LGE	3	45 ACE	SP	CCA		V	2/24/2064
2021 PO4119685105	LGE	4	45 ACE	SP	A	ID	BD	2/25/2064
2021 PO4054985050	LGE	4	35 BRO	SP	CCA		V	2/26/2064
2021 PO5233457643	KU	4	40 BRN	SP	CRE	HH,ID,IP	BX PX	2/27/2064
2021 PO5226958785	KU	6	30 BRN	SP	CRE	ID	TD	2/28/2064
2021 PO5149158040	KU	4	40 BRN	SP	CRE	ID	TD	2/29/2064
2021 PO3912485349	LGE	3	50 ACE	SP	CRE		V	3/1/2064
2021 PO3912385349	LGE	3	50 ACE	SP	CRE		V	3/2/2064
2021 PO3912785330	LGE	3	50 ACE	SP	CCA		V	3/3/2064
2021 PO5040339215	KU	2	50 UNK	SP	P		V	3/4/2064
2021 PO8715308037	KU	6	30 OTH	SP	CRE	ID	TD	3/5/2064



2021 PO3807285400	KU	4	45 ACE	SP	P		ED,ID	BD		3/6/2064
2021 p06223065501	KU	1	50 ACE	SP	CCA			V		3/7/2064
2021 PO6208365563	LGE	4	40 ACE	SP	CCA			V		3/8/2064
2021 PO4009884837	F	4	40 BRO	SP	CRE			V		3/9/2064
2021 PO4009884815	F	4	35 BRO	SP	CRE			V		3/10/2064
2021 PO4009484821	F	1	50 BRO	SP	CCA			V		3/11/2064
2021 PO4008884803	F	4	40 BRO	SP	CRE			V		3/12/2064
2021 PO4008284829	F	4	40 BRO	SP	A			V		3/13/2064
2021 PO4006984836	F	4	40 BRO	SP	A			V		3/14/2064
2021 PO4006384844	F	4	40 BRO	SP	CRE			V		3/15/2064
2021 PO4125685183	LGE	4	30 ACE	SP	CRE		ED,EP,ID,RB	X	PX	3/16/2064
2021 PO4124585183	LGE	4	30 ACE	SP	CRE		ED,HH,ID	TD		3/17/2064
2021 PO4125485184	LGE	4	40 ACE	SP	A		ED,ID,MD	TD		3/18/2064
2021 PO3980385126	LGE	3	55 ACE	SP	CRE		ED,ID,IP	BD		3/19/2064
2021 PO3982185135	LGE	2	55 ACE	SP	CCA			V		3/20/2064
2021 PO3985685152	LGE	3	55 ACE	SP	CCA			V		3/21/2064
2021 PO3983885143	LGE	3	55 ACE	SP	CRE		ED,ID,RB	TX	RR	3/22/2064
2021 PO4002385365	LGE	4	30 ACE	SP	CCA			V		3/23/2064
2021 PO4023085300	F	4	45 ACE	SP	A			V		3/24/2064
2021 PO4022985288	F	3	45 ACE	SP	CCA			V		3/25/2064
2021 PO4023985287	F	4	40 ACE	SP	CRE			V		3/26/2064
2021 PO4021485289	F	3	45 ACE	SP	CCA			V		3/27/2064
2021 PO4127885173	LGE	3	50 ACE	SP	A		ED,ID,IP	TD		3/28/2064
2021 PO4128085182	LGE	4	30 ACE	SP	CRE		ID	BD		3/29/2064
2021 PO4020085289	F	4	40 ACE	SP	CRE			V		3/30/2064
2021 PO4015985299	LGE	4	35 ACE	SP	CRE		ED,ID	TD		3/31/2064
2021 PO4019085354	LGE	4	25 ACE	SP	A		ED,ID	TD		4/1/2064
2021 PO4121085100	LGE	3	50 ACE	SP	A			V		4/2/2064
2021 PO3893685390	LGE	3	50 ACE	SP	CCA			V		4/3/2064
2021 PO4018784953	F	4	40 BRO	SP	CRE			V		4/4/2064
2021 PO4018284956	F	4	30 BRO	SP	A			V		4/5/2064
2021 PO3891285403	LGE	3	50 ACE	SP	CCA			V		4/6/2064
2021 PO3888985415	LGE	3	50 ACE	SP	CCA			V		4/7/2064
2021 PO8456306969	KU	5	40 OTH	SP	CRE		ID	TD		4/8/2064
2021 PO3886585428	LGE	3	50 ACE	SP	CCA			V		4/9/2064
2021 PO3863785442	LGE	4	40 ACE	SP	CCA			V		4/10/2064
2021 PO8707307943	F	3	45 OTH	SP	CCA			V		4/11/2064
2021 PO8716607797	KU	5	30 OTH	SP	CRE			V		4/12/2064
2021 PO8717507858	KU	6	30 OTH	SP	CRE		ID,IP	TD		4/13/2064
2021 PO8721707960	F	4	40 OTH	SP	CRE			V		4/14/2064
2021 PO3884285440	LGE	3	45 ACE	SP	P		ED,ID	BD		4/15/2064
2021 PO3884285452	LGE	4	40 ACE	SP	P			V		4/16/2064
2021 PO4124185088	LGE	4	45 ACE	SP	A		ID	BD		4/17/2064
2021 PO4122485096	LGE	3	50 ACE	SP	CRE		ID	BD		4/18/2064
2021 PO5247057684	KU	4	40 BRN	SP	CRE		ID	BD		4/19/2064
2021 PO4005684849	F	4	40 BRO	SP	CRE			V		4/20/2064
2021 PO4006784855	F	3	45 BRO	SP	CCA			V		4/21/2064
2021 PO3904585415	LGE	1	60 ACE	SP	CCA			V		4/22/2064
2021 PO3936785028	LGE	1	50 ACE	SP	CCA			V		4/23/2064
2021 PO3945885005	LGE	2	60 ACE	SP	P		ED,ID	BD		4/24/2064
2021 PO5011039484	KU	2	55 KOP	SP	CCA			B		4/25/2064
2021 PO8737207977	F	4	40 OTH	SP	CRE			V		4/26/2064
2021 PO8795308039	F	5	35 OTH	SP	CCA			V		4/27/2064
2021 PO8827208174	KU	5	35 OTH	SP	CRE		HH,ID	BX	RP2	4/28/2064

2021 PO8826608165	KU	5	35 OTH	SP	CCA		V	4/29/2064
2021 PO8829308205	KU	3	50 OTH	SP	CCA		V	4/30/2064
2021 PO8840208331	KU	4	45 OTH	SP	CCA		V	5/1/2064
2021 PO8849908341	KU	6	30 OTH	SP	CRE	ID	BD	5/2/2064
2021 PO8836808486	F	4	45 OTH	SP	A		V	5/3/2064
2021 PO4007184868	F	4	40 BRO	SP	CRE		V	5/4/2064
2021 PO4006784884	F	5	30 BRO	SP	CRE		V	5/5/2064
2021 PO4007684882	F	4	40 BRO	SP	CRE		V	5/6/2064
2021 PO4008384896	F	4	40 BRO	SP	CRE		V	5/7/2064
2021 PO4007384899	F	4	30 BRO	SP	CRE		V	5/8/2064
2021 PO4008584909	F	4	30 BRO	SP	CRE		V	5/9/2064
2021 PO4009084902	F	4	40 BRO	SP	CRE		V	5/10/2064
2021 PO4011684913	F	4	30 BRO	SP	CRE		V	5/11/2064
2021 PO4010384916	F	4	30 BRO	SP	CRE		V	5/12/2064
2021 PO4010484909	F	4	40 BRO	SP	CRE		V	5/13/2064
2021 PO4011384906	F	4	40 BRO	SP	CRE		V	5/14/2064
2021 PO4011984898	F	3	45 BRO	SP	CCA		V	5/15/2064
2021 PO4012584889	F	5	30 BRO	SP	CCA		V	5/16/2064
2021 PO4012384883	F	4	40 BRO	SP	CCA		V	5/17/2064
2021 PO4013784894	F	4	40 BRO	SP	CRE		V	5/18/2064
2021 PO5235958897	KU	3	45 BRN	SP	CRE	ID	TD	5/19/2064
2021 PO5220459017	KU	3	45 BRN	SP	CCA		V	5/20/2064
2021 PO5207559119	KU	3	45 BRN	SP	CCA		V	5/21/2064
2021 PO5171857851	KU	5	35 BRN	SP	CRE	ID	TD	5/22/2064
2021 PO5024239649	KU	3	45 KOP	SP	CCA		B	5/23/2064
2021 PO5063739730	KU	2	50 UNK	SP	P		V	5/24/2064
2021 PO5061539709	F	2	50 UNK	SP	P		V	5/25/2064
2021 PO5059939672	F	2	50 UNK	SP	P		V	5/26/2064
2021 PO5053839533	KU	2	50 UNK	SP	P		V	5/27/2064
2021 PO8823708303	F	4	40 OTH	SP	CRE		V	5/28/2064
2021 PO8828208297	KU	5	35 OTH	SP	CRE	ID	BD	5/29/2064
2021 PO8823908399	KU	4	50 OTH	SP	CRE	ID	BD	5/30/2064
2021 PO8823908479	F	4	45 OTH	SP	A		V	5/31/2064
2021 PO8821908479	F	5	35 OTH	SP	A		V	6/1/2064
2021 PO4024284980	F	3	45 BRO	SP	CCA		V	6/2/2064
2021 PO4022984947	F	4	40 BRO	SP	CCA		V	6/3/2064
2021 PO4022784933	F	4	40 BRO	SP	CRE		V	6/4/2064
2021 PO4022684921	F	4	40 BRO	SP	CCA		V	6/5/2064
2021 PO4022684915	F	4	40 BRO	SP	CRE		V	6/6/2064
2021 PO4023684917	F	4	40 BRO	SP	CRE		V	6/7/2064
2021 PO4024984915	F	4	40 BRO	SP	CRE		V	6/8/2064
2021 PO3946785004	LGE	2	55 ACE	SP	CRE	ED,ID	BD	6/9/2064
2021 PO5047739393	F	2	50 UNK	SP	P		V	6/10/2064
2021 PO5043339288	F	2	50 UNK	SP	P		V	6/11/2064
2021 PO4910140239	KU	3	45 BRO	SP	CCA		V	6/12/2064
2021 PO4027184928	F	4	40 BRO	SP	CRE		V	6/13/2064
2021 PO4027084914	F	4	40 BRO	SP	CRE		V	6/14/2064
2021 PO4026984902	F	4	40 BRO	SP	CRE		V	6/15/2064
2021 PO4026884890	F	4	40 BRO	SP	CRE		V	6/16/2064
2021 PO4026884879	F	4	40 BRO	SP	CRE		V	6/17/2064
2021 PO4026884863	LGE	5	25 BRO	SP	CRE	ED,ID	TD	6/18/2064
2021 PO8822208573	KU	3	50 OTH	SP	CCA		V	6/19/2064
2021 PO5157157788	KU	4	40 BRN	SP	CRE	ID	TD	6/20/2064
2021 PO5177857742	KU	5	35 BRN	SP	CRE	ID	BD	6/21/2064

2021	PO5161657665	KU	4	40 BRN	SP	CRE	ID	BD	6/22/2064	
2021	PO3952485001	LGE	2	55 ACE	SP	CRE	ED,ID	BD	6/23/2064	
2021	PO3948285004	LGE	2	55 ACE	SP	CRE	ED,ID	BD	6/24/2064	
2021	PO7787359904	LGE	3	50 ACE	SP	CCA		V	6/25/2064	
2021	PO4062784804	LGE	3	50 ACE	SP	CRE		V	6/26/2064	
2021	PO4061784787	LGE	3	45 ACE	SP	CRE		V	6/27/2064	
2021	PO4060784769	LGE	3	50 ACE	SP	CRE		V	6/28/2064	
2021	PO4059884750	LGE	3	50 ACE	SP	CRE		V	6/29/2064	
2021	PO4058984732	LGE	3	50 ACE	SP	CRE		V	6/30/2064	
2021	PO4058284715	LGE	3	50 ACE	SP	CCA		V	7/1/2064	
2021	PO4057384696	LGE	3	50 ACE	SP	CCA		V	7/2/2064	
2021	PO4056484678	LGE	3	50 ACE	SP	P		V	7/3/2064	
2021	PO4055684659	LGE	3	50 ACE	SP	CRE		V	7/4/2064	
2021	PO4055484655	LGE	1	60 ACE	SP	CRE		V	7/5/2064	
2021	PO4053384609	LGE	1	85 ACE	SP	CRE		V	7/6/2064	
2021	PO8821509044	KU	5	35 OTH	SP	CRE	ID,IP	TD	7/7/2064	
2021	PO8822808921	KU	5	35 OTH	SP	CRE	ID	BD	7/8/2064	
2021	PO8823808795	KU	4	40 OTH	SP	CCA		V	7/9/2064	
2021	PO8902008926	F	4	40 OTH	SP	A		V	7/10/2064	
2021	PO4107185198	LGE	7	25 ACE	SP	CRE	ED,HH,ID	BD	7/11/2064	
2021	PO5175555853	KU	1	75 OTH	SP	CRE		V	7/12/2064	
2021	PO5151955693	KU	1	80 BRN	SP	CCA		V	7/13/2064	
2021	PO5222356170	KU	1	75 OTH	ST	CRE		V	7/14/2064	
2021	PO5243856316	KU	1	75 OTH	ST	CRE		V	7/15/2064	
2021	PO5127055504	KU	1	80 OTH	ST	CCA		V	7/16/2064	
2021	PO5201656030	KU	1	80 OTH	ST	CRE		V	7/17/2064	
2021	PO4925640092	KU	2	50 BRO	SP	CCA		V	7/18/2064	
2021	PO4928940170	KU	2	50 BRO	SP	CCA		V	7/19/2064	
2021	PO4933040290	KU	2	50 BRO	SP	CCA		V	7/20/2064	
2021	PO4934740330	KU	3	45 BRO	SP	CCA		V	7/21/2064	
2021	PO4946340267	KU	2	55 BRO	SP	CCA		V	7/22/2064	
2021	PO4957440218	KU	2	50 BRO	SP	CCA		V	7/23/2064	
2021	PO5068239801	KU	2	50 BRO	SP	CCA		V	7/24/2064	
2021	PO4969240172	KU	2	50 BRO	SP	CCA		V	7/25/2064	
2021	PO4027284939	F	4	40 BRO	SP	CCA		V	7/26/2064	
2021	PO4026684947	F	4	40 BRO	SP	CRE		V	7/27/2064	
2021	PO4026484963	F	4	40 BRO	SP	CRE		V	7/28/2064	
2021	PO4026584977	F	4	40 BRO	SP	CRE		V	7/29/2064	
2021	PO4026084982	F	4	45 BRO	SP	CRE		V	7/30/2064	
2021	PO4026884983	F	4	40 BRO	SP	CCA		V	7/31/2064	
2021	PO3950285002	LGE	1	55 ACE	SP	CCA		V	8/1/2064	
2021	PO3954385007	LGE	2	55 ACE	SP	CCA		V	8/2/2064	
2021	PO8902508792	F	4	40 OTH	SP	CRE		V	8/3/2064	
2021	PO3955985013	LGE	3	50 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	8/4/2064
2021	PO3957785020	LGE	2	55 ACE	SP	CRE	ED,ID,IP	TD		8/5/2064
2021	PO5165858150	KU	4	40 BRN	SP	CRE	ID	TD		8/6/2064
2021	PO4027484985	F	4	40 BRO	SP	CCA		V		8/7/2064
2021	PO4028184986	F	3	45 BRO	SP	CCA		V		8/8/2064
2021	PO7442561549	LGE	5	35 BRO	SP	CCA		V		8/9/2064
2021	PO4029584984	LGE	4	40 BRO	SP	CRE	ED,ID	BD		8/10/2064
2021	PO4029284989	F	4	40 BRO	SP	CRE		V		8/11/2064
2021	PO8900108657	F	4	40 OTH	SP	CRE		V		8/12/2064
2021	PO8871808629	KU	4	40 OTH	SP	CRE	ID	BD		8/13/2064
2021	PO8858108630	KU	3	45 OTH	SP	CCA		V		8/14/2064

2021 PO8840808814	KU	4	40 OTH	SP	CCA		V	8/15/2064
2021 PO4030384989	F	4	30 BRO	SP	CCA		V	8/16/2064
2021 PO4030584994	F	4	40 BRO	SP	CRE		V	8/17/2064
2021 PO4031584980	LGE	4	40 BRO	SP	CRE	ED,ID	TD	8/18/2064
2021 PO4996340043	KU	3	45 BRO	SP	CCA		V	8/19/2064
2021 PO5004240018	KU	2	50 BRO	SP	CCA		V	8/20/2064
2021 PO5020839964	KU	2	50 BRO	SP	CCA		V	8/21/2064
2021 PO5029839922	KU	3	45 BRO	SP	CCA		V	8/22/2064
2021 PO4106685198	LGE	4	30 ACE	SP	CCA		V	8/23/2064
2021 PO4107985188	LGE	2	50 ACE	SP	A	ID	BD	8/24/2064
2021 PO4109385195	LGE	4	40 ACE	SP	CRE	ID	BD	8/25/2064
2021 PO4111585193	LGE	4	40 ACE	SP	CCA		V	8/26/2064
2021 PO4109185187	LGE	1	60 ACE	SP	CCA		V	8/27/2064
2021 PO3962885042	LGE	2	55 ACE	SP	CRE	ED,HH,ID	TD	8/28/2064
2021 PO3959385026	LGE	2	55 ACE	SP	CRE	ED,ID	TD	8/29/2064
2021 PO3961185034	LGE	2	55 ACE	SP	CRE	ED,HH,ID	TD	8/30/2064
2021 PO4031584998	F	3	45 BRO	SP	CCA		V	8/31/2064
2021 PO4008484251	F	4	40 ACE	SP	A	ED	V	9/1/2064
2021 PO4008584266	F	4	40 ACE	SP	P	ED	V	9/2/2064
2021 PO0098599846	KU	4	40 XXX	SP	CRE	HH,ID	X	9/3/2064
2021 PO4134984800	LGE	4	30 ACE	SP	P	ED,ID	TD	9/4/2064
2021 PO4134384804	LGE	4	40 ACE	SP	P	ED,ID	TD	9/5/2064
2021 PO4097485301	LGE	4	40 BRO	SP	CRE	ED,ID	TD	9/6/2064
2021 PO4103485303	LGE	4	40 BRO	SP	CRE	ID	TD	9/7/2064
2021 PO4099085206	LGE	4	35 BRO	SP	CRE		V	9/8/2064
2021 PO4118185592	F	4	40 ACE	SP	CRE	ED,ID,JP	V	9/9/2064
2021 PO4120585591	F	4	40 ACE	SP	CRE		V	9/10/2064
2021 PO4121785590	F	4	40 ACE	SP	CRE		V	9/11/2064
2021 PO4350403204	KU	3	45 BRN	SP	CCA		V	9/12/2064
2021 PO4003685426	F	4	30 BRN	SP	CCA		V	9/13/2064
2021 PO4004085431	F	4	25 BRN	SP	A		V	9/14/2064
2021 PO4003785447	F	4	40 BRN	SP	CCA		V	9/15/2064
2021 PO4004485444	F	4	35 BRN	SP	A		V	9/16/2064
2021 PO4004485458	F	4	30 BRN	SP	A		V	9/17/2064
2021 PO4003985459	F	4	40 BRN	SP	A		V	9/18/2064
2021 PO4165285489	F	4	40 BRO	SP	A		V	9/19/2064
2021 PO4165385503	F	4	40 BRO	SP	CRE		V	9/20/2064
2021 PO4165485517	F	4	40 BRO	SP	CRE		V	9/21/2064
2021 PO4165685531	F	2	45 BRO	SP	CCA		V	9/22/2064
2021 PO4166085534	F	4	30 BRO	SP	CRE		V	9/23/2064
2021 PO3545799638	KU	3	45 BRN	SP	CCA		V	9/24/2064
2021 PO6552647926	KU	2	45 UNK	SP	CRE	ID	TD	9/25/2064
2021 PO6549247829	KU	3	45 UNK	SP	CCA		V	9/26/2064
2021 PO3571599308	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	9/27/2064
2021 PO3454320084	F	4	40 OTH	SP	P		V	9/28/2064
2021 PO3464520060	F	4	40 OTH	SP	P		V	9/29/2064
2021 PO3454420165	F	4	40 OTH	SP	P		V	9/30/2064
2021 PO3444020103	F	4	40 OTH	SP	P		V	10/1/2064
2021 PO3437319982	F	4	40 OTH	SP	P		V	10/2/2064
2021 PO3423119982	F	4	40 OTH	SP	P		V	10/3/2064
2021 PO4133384769	LGE	3	50 ACE	SP	CCA	ED,ID	TD	10/4/2064
2021 PO6601747727	F	4	45 UNK	SP	A		V	10/5/2064
2021 PO3592399043	KU	3	40 BRN	SP	CRE	ED,ID	TD	10/6/2064
2021 PO6580947756	F	4	40 UNK	SP	A		V	10/7/2064

2021 PO6552947748	KU	4	40 UNK	SP	CRE	ID,IP	TD	10/8/2064
2021 PO4133884786	LGE	4	40 ACE	SP	CRE	ED,ID	TD	10/9/2064
2021 PO4134384784	LGE	4	30 ACE	SP	CCA		V	10/10/2064
2021 PO3444219719	F	4	40 OTH	SP	P		V	10/11/2064
2021 PO3436219781	F	4	40 SWP	SP	P		V	10/12/2064
2021 PO3480922823	F	4	40 XXX	SP	P		V	10/13/2064
2021 PO3498522787	F	4	40 XXX	SP	P		V	10/14/2064
2021 PO4103085324	LGE	3	45 BRO	SP	CCA		V	10/15/2064
2021 PO4101485331	LGE	3	45 BRO	SP	CCA		V	10/16/2064
2021 PO4094385312	LGE	4	40 BRO	SP	CCA		V	10/17/2064
2021 PO4136284872	LGE	4	40 ACE	SP	CCA		V	10/18/2064
2021 PO6115440394	KU	5	35 UNK	SP	CRE	ID,IP	TD	10/19/2064
2021 PO4135384891	LGE	4	35 ACE	SP	P	ED,ID	BD	10/20/2064
2021 PO4136784889	LGE	4	40 ACE	SP	CRE	ED,ID	BD	10/21/2064
2021 PO3486199392	KU	3	40 BRN	SP	CCA		V	10/22/2064
2021 PO6544447908	F	4	45 UNK	SP	CCA		V	10/23/2064
2021 PO8518960021	LGE	4	30 ACE	SP	CCA		V	10/24/2064
2021 PO4119285591	F	4	40 ACE	SP	CRE		V	10/25/2064
2021 PO4064684817	LGE	4	40 BRO	SP	P	ED,ID	TD	10/26/2064
2021 PV4065884813	LGE	4	40 BRO	SP	P	ED,ID	TD	10/27/2064
2021 PO4065584801	LGE	4	30 BRO	SP	CRE	ED,ID	TD	10/28/2064
2021 PO4069284802	F	3	45 BRO	SP	CCA		V	10/29/2064
2021 PO4871602066	KU	5	35 BRN	SP	CCA		V	10/30/2064
2021 PO3438321071	F	4	40 OTH	SP	P		V	10/31/2064
2021 PO3435020921	F	4	40 OTH	SP	P		V	11/1/2064
2021 PO3442220993	F	4	40 OTH	SP	P		V	11/2/2064
2021 PO3412820956	F	4	40 OTH	SP	P		V	11/3/2064
2021 PO3422921038	F	4	40 OTH	SP	P		V	11/4/2064
2021 PO4094985303	LGE	4	40 BRO	SP	CRE	ED,ID	TD	11/5/2064
2021 PO4843702233	KU	2	55 BRN	SP	CCA		V	11/6/2064
2021 PO4861102036	KU	4	30 BRN	SP	CCA	ED	TD	11/7/2064
2021 PO4096285302	LGE	4	40 BRO	WC	CRE	ED,EP,ID	TD	11/8/2064
2021 PO4004085473	F	4	40 BRN	SP	A		V	11/9/2064
2021 PO4004985502	F	4	30 BRN	SP	A		V	11/10/2064
2021 PO3390821004	F	4	40 OTH	SP	P		V	11/11/2064
2021 PO4115585607	F	4	45 ACE	SP	P		V	11/12/2064
2021 PO3393020469	F	4	40 OTH	SP	P		V	11/13/2064
2021 PO3388020592	F	4	40 OTH	SP	P		V	11/14/2064
2021 PO3387920723	F	4	40 OTH	SP	P		V	11/15/2064
2021 PO3440320451	F	4	40 OTH	SP	P		V	11/16/2064
2021 PO3438320548	F	4	40 OTH	SP	P		V	11/17/2064
2021 PO3424420376	F	4	40 OTH	SP	P		V	11/18/2064
2021 PO4166485546	F	6	30 BRO	WC	CRE		V	11/19/2064
2021 PO4165785545	F	4	40 BRO	SP	CRE		V	11/20/2064
2021 PO4166285559	F	4	30 BRO	SP	CRE		V	11/21/2064
2021 PO4169085557	F	4	40 BRO	SP	CRE		V	11/22/2064
2021 PO4168985550	F	4	40 BRO	SP	CRE		V	11/23/2064
2021 PO4168985543	F	4	35 BRO	SP	CRE		V	11/24/2064
2021 PO4168785528	F	4	35 BRO	SP	CRE		V	11/25/2064
2021 PO4168685515	F	4	40 BRO	WC	CRE		V	11/26/2064
2021 PO4168585501	F	4	40 BRO	SP	CCA		V	11/27/2064
2021 PO4168485494	F	4	35 BRO	WC	CRE		V	11/28/2064
2021 PO4168385487	F	4	40 BRO	SP	CRE		V	11/29/2064
2021 PO4168885484	F	4	30 BRO	SP	A		V	11/30/2064

2021 PO4168285477	F	4	40 BRO	SP	CRE		V	12/1/2064
2021 PO4168285472	LGE	4	40 BRO	SP	CCA		V	12/2/2064
2021 PO4168285468	LGE	4	30 BRO	SP	CCA		V	12/3/2064
2021 PO4170085466	LGE	4	30 BRO	SP	CCA		V	12/4/2064
2021 PO4169985471	F	4	35 BRO	SP	CRE		V	12/5/2064
2021 PO4171485466	F	4	40 BRO	SP	CRE		V	12/6/2064
2021 PO4171385456	F	4	40 BRO	SP	CCA		V	12/7/2064
2021 PO4171285451	F	4	40 BRO	SP	CRE		V	12/8/2064
2021 PO3479222723	F	4	40 XXX	SP	P		V	12/9/2064
2021 PO3481422525	F	4	40 XXX	SP	P		V	12/10/2064
2021 PO3451699213	KU	4	40 BRN	SP	CCA	ED	TD	12/11/2064
2021 PO5957839627	F	5	35 UNK	SP	CCA		V	12/12/2064
2021 PO5972839750	KU	4	40 UNK	SP	CRE	ID	TD	12/13/2064
2021 PO3495922363	F	4	40 XXX	SP	P		V	12/14/2064
2021 PO3495822252	F	4	40 XXX	SP	P		V	12/15/2064
2021 PO3489622326	F	4	40 XXX	SP	P		V	12/16/2064
2021 PO3480722053	F	4	40 XXX	SP	P		V	12/17/2064
2021 PO3496721842	F	4	40 XXX	SP	P		V	12/18/2064
2021 PO3490021844	F	4	40 XXX	SP	P		V	12/19/2064
2021 PO3470099324	KU	4	40 BRN	SP	CCA	ED	TD	12/20/2064
2021 PO3640790618	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD	12/21/2064
2021 PO3334422435	F	4	40 BRN	SP	P		V	12/22/2064
2021 PO3338422190	F	4	40 BRN	SP	P		V	12/23/2064
2021 PO3336622013	F	4	40 BRN	SP	P		V	12/24/2064
2021 PO3355221819	F	4	40 BRN	SP	CCA		V	12/25/2064
2021 PO3376621719	F	4	40 BRN	SP	CCA		V	12/26/2064
2021 PO4062284889	F	4	40 BRO	SP	CRE		V	12/27/2064
2021 PO4063484883	F	4	40 BRO	SP	CRE		V	12/28/2064
2021 PO4064284880	F	4	40 BRO	SP	CRE		V	12/29/2064
2021 PO4064884885	F	4	40 BRO	SP	CRE		V	12/30/2064
2021 PO4065684897	F	4	40 BRO	SP	CRE		V	12/31/2064
2021 PO4066384909	F	3	45 BRO	SP	CCA		V	1/1/2065
2021 PO4157886023	F	4	45 BRO	SP	CRE		V	1/2/2065
2021 PO3330022706	F	4	40 BRN	SP	P		V	1/3/2065
2021 PO3331422608	F	4	40 BRN	SP	P		V	1/4/2065
2021 PO3308123960	F	4	40 BRN	SP	P		V	1/5/2065
2021 PO3325624981	F	4	40 BRN	SP	P		V	1/6/2065
2021 PO3290124805	F	4	40 BRN	SP	CRE		V	1/7/2065
2021 PO3298524904	F	4	40 BRN	SP	CRE		V	1/8/2065
2021 PO3325624981A	KU	4	40 BRN	SP	P		V	1/9/2065
2021 PO3325624981B	KU	4	40 BRN	SP	P		V	1/10/2065
2021 PO3314124992	F	4	40 BRN	SP	P		V	1/11/2065
2021 PO3461221895	F	4	40 BRN	SP	P		V	1/12/2065
2021 PO3302024849	F	4	40 BRN	SP	P		V	1/13/2065
2021 PO3287924659	F	4	40 BRN	SP	P		V	1/14/2065
2021 PO3297424555	F	4	40 BRN	SP	P		V	1/15/2065
2021 PO3291824440	F	4	40 BRN	SP	P		V	1/16/2065
2021 PO3301124349	F	4	40 BRN	SP	P		V	1/17/2065
2021 PO3297124142	F	4	40 BRN	SP	P		V	1/18/2065
2021 PO3304624140	F	4	40 BRN	SP	P		V	1/19/2065
2021 PO3300623942	F	4	40 BRN	SP	P		V	1/20/2065
2021 PO3303623771	F	4	40 BRN	SP	P		V	1/21/2065
2021 PO3313223666	F	4	40 BRN	SP	P		V	1/22/2065
2021 PO5996810546	KU	4	40 ACW	SP	S		V	1/23/2065

2021 PO5996510394	KU	4	40 ACW	SP	S	V	1/24/2065
2021 PO5996410324	KU	4	40 ACW	SP	S	V	1/25/2065
2021 PO5991810668	KU	5	35 ACW	SP	S	V	1/26/2065
2021 PO5996910693	KU	4	40 ACW	SP	S	V	1/27/2065
2021 PO5990010906	KU	4	40 ACW	SP	S	V	1/28/2065
2021 PO3680889475	F	4	40 OTH	SP	P	V	1/29/2065
2021 PO3673889688	F	4	40 OTH	SP	P	V	1/30/2065
2021 PO3706789532	KU	4	40 BRN	SP	CCA	V	1/31/2065
2021 PO3413022953	F	4	40 BRN	SP	P	V	2/1/2065
2021 PO3415322852	F	4	40 BRN	SP	P	V	2/2/2065
2021 PO3412922774	F	4	40 BRN	SP	P	V	2/3/2065
2021 PO3406022994	F	4	40 BRN	SP	P	V	2/4/2065
2021 PO3396222970	F	4	40 BRN	SP	P	V	2/5/2065
2021 PO4183985964	F	3	45 BRO	SP	CCA	V	2/6/2065
2021 PO4185085963	F	4	40 BRO	SP	CRE	V	2/7/2065
2021 PO3324822997	F	4	40 BRN	SP	P	V	2/8/2065
2021 PO3329723460	F	4	40 BRN	SP	P	V	2/9/2065
2021 PO3343423450	F	4	40 BRN	SP	P	V	2/10/2065
2021 PO3339823379	F	4	40 BRN	SP	P	V	2/11/2065
2021 PO3318923349	F	4	40 BRN	SP	P	V	2/12/2065
2021 PO4159485509	F	4	40 BRO	SP	CCA	V	2/13/2065
2021 PO4158885447	F	4	40 BRO	SP	CRE	V	2/14/2065
2021 PO3381221861	KU	3	50 BRN	SP	CCA	V	2/15/2065
2021 PO3406021604	F	4	40 BRN	SP	P	V	2/16/2065
2021 PO3397821686	F	4	40 BRN	SP	P	V	2/17/2065
2021 PO3415021785	F	4	40 BRN	SP	CRE	V	2/18/2065
2021 PO3437821845	F	4	40 BRN	SP	P	V	2/19/2065
2021 PO4166585412	LGE	3	45 BRO	SP	CCA	V	2/20/2065
2021 PO4066984919	F	4	40 BRO	SP	CRE	V	2/21/2065
2021 PO4166485401	LGE	3	45 BRO	SP	CCA	V	2/22/2065
2021 PO4067584930	F	4	40 BRO	SP	CRE	V	2/23/2065
2021 PO4068384943	F	4	40 BRO	SP	CRE	V	2/24/2065
2021 PO4068684948	F	4	40 BRO	SP	CRE	V	2/25/2065
2021 PO4069384960	F	4	40 BRO	SP	CRE	V	2/26/2065
2021 PO4069884969	F	4	40 BRO	SP	CRE	V	2/27/2065
2021 PO4070584980	F	4	40 BRO	SP	CRE	V	2/28/2065
2021 PO4184386014	F	4	35 BRO	SP	A	V	3/1/2065
2021 PO4184286001	F	4	35 BRO	SP	CRE	V	3/2/2065
2021 PO4184185993	F	4	35 BRO	SP	CRE	V	3/3/2065
2021 PO4184785996	LGE	4	35 BRO	SP	A	V	3/4/2065
2021 PO4184185980	F	4	40 BRO	SP	CRE	V	3/5/2065
2021 PO4184085977	F	4	40 BRO	SP	CCA	V	3/6/2065
2021 PO4184185973	F	4	40 BRO	SP	A	V	3/7/2065
2021 PO4184085966	F	4	40 BRO	SP	A	V	3/8/2065
2021 PO4071284992	F	4	40 BRO	SP	CRE	V	3/9/2065
2021 PO4071985004	F	4	40 BRO	SP	CRE	V	3/10/2065
2021 PO4072585015	F	4	40 BRO	SP	CRE	V	3/11/2065
2021 PO4073285026	F	4	40 BRO	SP	CRE	V	3/12/2065
2021 PO4074085051	F	3	45 BRO	SP	CCA	V	3/13/2065
2021 PO4073885037	F	4	40 BRO	SP	CRE	V	3/14/2065
2021 PO3400722908	F	4	40 BRN	SP	P	V	3/15/2065
2021 PO3379822929	F	4	40 BRN	SP	P	V	3/16/2065
2021 PO3382522864	F	4	40 BRN	SP	P	V	3/17/2065
2021 PO3362722884	F	4	40 BRN	SP	CRE	V	3/18/2065

2021 PO3363622815	F	4	40 BRN	SP	P		V					3/19/2065
2021 PO3348922778	F	4	40 BRN	SP	P		V					3/20/2065
2021 PO3347922629	F	4	40 BRN	SP	P		V					3/21/2065
2021 PO4060584968	F	3	45 BRO	SP	CCA		V					3/22/2065
2021 PO4059984959	F	4	40 BRO	SP	CRE		V					3/23/2065
2021 PO4059384946	F	3	45 BRO	SP	A		V					3/24/2065
2021 PO4058884938	F	3	45 BRO	SP	CCA		V					3/25/2065
2021 PO4058284927	F	3	45 BRO	SP	CCA		V					3/26/2065
2021 PO4056984918	F	4	40 BRO	SP	CRE		V					3/27/2065
2021 PO4058084912	F	4	40 BRO	SP	CRE		V					3/28/2065
2021 PO4058984907	F	4	40 BRO	SP	CCA		V					3/29/2065
2021 PO4060084901	F	4	40 BRO	SP	CCA		V					3/30/2065
2021 PO4061184895	F	4	40 BRO	SP	CRE		V					3/31/2065
2021 PO3682090364	KU	6	30 OTH	SP	CCA		V					4/1/2065
2021 PO3676190299	KU	4	40 OTH	SP	CCA		V					4/2/2065
2021 PO4163385619	F	4	40 BRO	SP	CRE		V					4/3/2065
2021 PO4095285219	LGE	2H	35 BRO	SP	CCA		V					4/4/2065
2021 PO4099385164	LGE	4	35 BRO	SP	CCA		V					4/5/2065
2021 PO4161685442	F	4	35 BRO	SP	CRE		V					4/6/2065
2021 PO4161685448	F	4	35 BRO	SP	CRE		V					4/7/2065
2021 PO4161885465	F	4	40 BRO	SP	A		V					4/8/2065
2021 PO4161985477	F	4	40 BRO	SP	CRE		V					4/9/2065
2021 PO4163185476	F	4	40 BRO	SP	CRE		V					4/10/2065
2021 PO4164085475	F	4	40 BRO	SP	CRE		V					4/11/2065
2021 PO8822667860	LGE	4	35 BRO	SP	CCA		V					4/12/2065
2021 PO8827967870	LGE	4	35 BRO	SP	CCA		V					4/13/2065
2021 PO4166485618	F	4	40 BRO	SP	CCA		V					4/14/2065
2021 PO4167285616	LGE	4	30 BRO	SP	CCA		V					4/15/2065
2021 PO4163585638	F	3	45 BRO	SP	CCA		V					4/16/2065
2021 PO4160585628	F	4	35 BRO	SP	CRE		V					4/17/2065
2021 PO4160485607	F	4	35 BRO	WC	CRE		V					4/18/2065
2021 PO3651690528	KU	5	30 OTH	SP	CRE	ED,ID,IP,SRC	TX			RR		4/19/2065
2021 PO3729089059	KU	5	45 OTH	SP	CRE	ED,ID,SRC	TX			RR		4/20/2065
2021 PO3728789181	KU	5	35 OTH	SP	CRE	ED,ID	TD					4/21/2065
2021 PO3721589303	KU	4	40 OTH	SP	CRE	ED,ID	TD					4/22/2065
2021 PO6412410483	KU	4	40 ACW	SP	CRE	ED,ID	TD					4/23/2065
2021 PO6412710642	KU	4	40 ACW	SP	CRE	ED,ID	TD					4/24/2065
2021 PO3501197760	KU	3	40 BRN	SP	CRE	ED,ID,IP	TD					4/25/2065
2021 PO3702589501	KU	6	30 BRN	SP	CRE	ED,ID,SRS	TD					4/26/2065
2021 PO3658897482	KU	4	40 BRN	SP	CRE	ED,ID	TD					4/27/2065
2021 PO6415211084	KU	4	40 ACW	SP	CRE	ED,ID	TD					4/28/2065
2021 PO4161885970	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD					4/29/2065
2021 PO4161885958	LGE	4	35 BRO	SP	CRE	ED,ID	TD					4/30/2065
2021 PO4161785948	LGE	4	35 BRO	SP	CRE	ED,ID	TD					5/1/2065
2021 PO4161685937	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD					5/2/2065
2021 PO4161285977	LGE	4	40 BRO	SP	CRE	ED,ID	TD					5/3/2065
2021 PO4162086000	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD					5/4/2065
2021 PO4161985990	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD					5/5/2065
2021 PO6412810755	KU	4	40 ACW	SP	CRE	ED,ID	TD					5/6/2065
2021 PO6416311201	KU	4	40 ACW	SP	CRE	ED,ID	TD					5/7/2065
2021 PO6417211306	KU	4	40 ACW	SP	CRE	ED,ID	TD					5/8/2065
2021 PO6413410870	KU	4	40 ACW	SP	CRE	ED,ID	TD					5/9/2065
2021 PO6433011540	KU	4	30 ACW	SP	CRE	ED,ID	TD					5/10/2065
2021 PO6414011687	KU	4	40 ACW	SP	CRE	ED,ID	TD					5/11/2065



2021	PO6418311434	KU	4	40 ACW	SP	CRE	ED,ID	TD		5/12/2065
2021	PO4158386013	LGE	4	35 BRO	SP	A	ED,ID	TD		5/13/2065
2021	PO3702990049	KU	4	40 OTH	SP	CRE	ED,ID	TD		5/14/2065
2021	PO4451688136	LGE	4	35 BRO	SP	P	ED,ID	BD		5/15/2065
2021	PO4450588132	LGE	4	40 BRO	SP	P	ED,ID	BD		5/16/2065
2021	PO4449888130	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP	BD		5/17/2065
2021	PO4449188126	LGE	4	40 BRO	SP	P	ED,ID	BD		5/18/2065
2021	PO4448788133	LGE	4	40 BRO	SP	P	ED,ID	BD		5/19/2065
2021	PO5620210248	KU	4	40 KOP	SP	CRE	ED,ID	TD		5/20/2065
2021	PO3974486201	LGE	3	50 ACE	SP	A	ED,ID	BD		5/21/2065
2021	PO3974186188	LGE	3	50 ACE	SP	A	ID	TD		5/22/2065
2021	PO3974186197	LGE	4	35 ACE	SP	A	ID	BD		5/23/2065
2021	PO3973686195	LGE	4	40 ACE	SP	CRE	ID	BD		5/24/2065
2021	PO5546510116	KU	4	40 KOP	SP	CRE	ED,ID,IP,MD,SR	TD		5/25/2065
2021	PO5565610142	KU	4	40 KOP	SP	CRE	ED,ID	TD		5/26/2065
2021	PO5546410268	KU	4	40 KOP	SP	CRE	ED,ID	BD		5/27/2065
2021	PO5590210178	KU	4	40 KOP	SP	CRE	ED,ID	BD		5/28/2065
2021	PO5599610527	KU	4	40 KOP	SP	P	ED,ID	TD		5/29/2065
2021	PO5540610232	KU	6	30 KOP	SP	CRE	ED,ID	BD		5/30/2065
2021	PO5336231230	KU	6	30 BRN	SP	CRE	ID	TD		5/31/2065
2021	PO5337731146	KU	4	45 BRN	SP	CRE	ID,IP	TD		6/1/2065
2021	PO5548810142	KU	4	40 KOP	SP	CRE	ED,HH,ID,RB	X	RP2	6/2/2065
2021	PO5512110063	KU	4	40 KOP	SP	CRE	ED,ID	BD		6/3/2065
2021	PO5502110048	KU	3	45 KOP	SP	CRE	ED,ID,IP	BD		6/4/2065
2021	PO5322331219	KU	4	40 BRN	SP	CRE	ID	TD		6/5/2065
2021	PO5061626645	KU	4	40 BRN	SP	CRE		T		6/6/2065
2021	PO4048786540	LGE	4	40 ACE	SP	CRE	ED,ID	TD		6/7/2065
2021	PO5277037242	KU	3	45 UNK	SP	CRE	ED,HH,ID	X	RP1	6/8/2065
2021	PO5275437112	KU	4	45 UNK	SP	CRE	ID	BD		6/9/2065
2021	PO5274437038	KU	4	45 UNK	SP	CRE	ID	BD		6/10/2065
2021	PO5273937012	KU	4	45 UNK	SP	CRE	ID	BD		6/11/2065
2021	PO3992485582	F	4	40 ACE	SP	CCA	ED,HH,ID,RB	VX	RP2	6/12/2065
2021	PO3980986265	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD		6/13/2065
2021	PO3981386260	LGE	3	50 ACE	SP	A	ED,ID,IP	BD		6/14/2065
2021	PO4806338156	KU	3	45 UNK	SP	CRE	ID	TD		6/15/2065
2021	PO5295831566	KU	5	35 BRN	SP	CRE	ID	TD		6/16/2065
2021	PO5292831479	KU	5	35 BRN	SP	CRE	ID	TD		6/17/2065
2021	PO5300831488	KU	3	45 BRN	SP	CRE	ID	TD		6/18/2065
2021	PO5307931288	KU	3	45 BRN	SP	CRE	ID	BD		6/19/2065
2021	PO4017885553	LGE	4	30 KOP	SP	P	ED	TD		6/20/2065
2021	PO4017985572	LGE	4	40E KOP	SP	P	ED,HH,ID,IP	VX	RP2	6/21/2065
2021	PO4022986585	LGE	4	35 ACE	SP	CCA		T		6/22/2065
2021	PO5309131749	KU	3	45 BRN	SP	CRE	ID	BD		6/23/2065
2021	PO4860837837	KU	3	45 UNK	SP	CRE	ID	BD		6/24/2065
2021	PO5563009744	KU	4	45 KOP	SP	CRE	ED,ID	BD		6/25/2065
2021	PO5078526572	KU	4	40 BRN	SP	CRE		T		6/26/2065
2021	PO5470110010	KU	2	40 KOP	SP	CRE	ED,ID	BD		6/27/2065
2021	PO5506610325	KU	5	35 KOP	SP	CRE	ED,ID	TD		6/28/2065
2021	PO4064186652	LGE	4	40 ACE	SP	CRE	ED,ID	TX	RR	6/29/2065
2021	PO3986885641	LGE	UNK	25 ACE	SP	CRE	ED,ID	TD		6/30/2065
2021	PO4143785994	LGE	4	40 BRO	SP	CRE	ED,ID	TD		7/1/2065
2021	PO4141985994	LGE	4	35 BRO	SP	CRE	ED,ID	TD		7/2/2065
2021	PO4090486508	LGE	3	45 ACE	SP	CCA		T		7/3/2065
2021	PO4092486566	LGE	4	40 ACE	SP	CRE	ED,ID	TD		7/4/2065

2021 PO4092786561	LGE	4	30 ACE	SP	CRE	ED,ID	TD	7/5/2065
2021 PO3982285598	LGE	UNK	45 ACE	SP	CCA		BD	7/6/2065
2021 PO5014426348	KU	5	35 BRN	SP	CRE		T	7/7/2065
2021 PO4142785967	LGE	4	30 BRO	SP	A	ED,ID	TD	7/8/2065
2021 PO4141585971	LGE	4	40 BRO	SP	A	ED,ID	TD	7/9/2065
2021 PO5465512896	KU	4	40 BRN	SP	CRE		T	7/10/2065
2021 PO4754238269	KU	3	45 UNK	SP	CRE	ID	BD	7/11/2065
2021 PO4745638106	KU	3	45 KOP	SP	CRE	ID	BD	7/12/2065
2021 PO4734337889	KU	3	45 KOP	SP	CRE	ID	BD	7/13/2065
2021 PO4725737724	KU	3	50 KOP	SP	CCA	ID	BD	7/14/2065
2021 PO4719437598	KU	2	50 KOP	SP	CRE	ID	TD	7/15/2065
2021 PO4964432883	KU	4	40 BRN	SP	CRE	ID	BD	7/16/2065
2021 PO4970832813	KU	4	40 BRN	SP	CRE	ID	BD	7/17/2065
2021 PO5088426071	KU	4	40 BRN	SP	CRE		T	7/18/2065
2021 PO3982786285	LGE	6	25 ACE	SP	A	ED,ID	TD	7/19/2065
2021 PO3983186288	LGE	4	45 ACE	SP	P	ID	BD	7/20/2065
2021 PO3982386270	LGE	3	50 ACE	SP	A	ED,ID,IP	BD	7/21/2065
2021 PO4178086195	LGE	4	30 BRO	SP	CRE	ED,ID	TD	7/22/2065
2021 PO4059786633	LGE	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP3 7/23/2065
2021 PO4016285669	LGE	4	35 KOP	SP	P	ED	TD	7/24/2065
2021 PO3985986305	LGE	3	50 ACE	SP	A	ID	BD	7/25/2065
2021 PO3986486279	LGE	4	40 ACE	SP	CRE	ID	BD	7/26/2065
2021 PO3984786290	LGE	4	40 ACE	SP	CRE	ID	BD	7/27/2065
2021 PO3984586292	LGE	3	50 ACE	SP	P	ED,ID	BD	7/28/2065
2021 PO3995786406	LGE	3	50 ACE	SP	CRE	ED,HH,ID	TX	RR 7/29/2065
2021 PO3995386396	LGE	4	30 ACE	SP	CRE	ID	BD	7/30/2065
2021 PO3994386401	LGE	2	55 ACE	SP	CRE	ED,HH,ID	BD	7/31/2065
2021 PO3994786399	LGE	2	55 ACE	SP	CRE	ED,HH,ID	BD	8/1/2065
2021 PO5339111663	KU	4	40 BRO	SP	CRE	ID	TD	8/2/2065
2021 PO5330711695	KU	3	40 BRO	SP	CCA		T	8/3/2065
2021 PO4014285644	LGE	4	30 KOP	SP	P	ED,ID	TD	8/4/2065
2021 PO5050926629	KU	4	40 BRN	SP	CRE		T	8/5/2065
2021 PO4140586052	LGE	2	50 BRO	SP	A	ED,ID,IP	TD	8/6/2065
2021 PO4140586049	LGE	2	50 BRO	SP	A	ED,ID	TD	8/7/2065
2021 PO3980485669	LGE	4	30 ACE	SP	CCA	ED,ID	TD	8/8/2065
2021 PO4138185996	LGE	3	45 BRO	SP	CCA	ED	T	8/9/2065
2021 PO4137886011	LGE	4	40 BRO	SP	A	ED,ID	TD	8/10/2065
2021 PO3975786204	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD	8/11/2065
2021 PO3975086197	LGE	2	50 ACE	SP	P	ED,HH,ID	TD	8/12/2065
2021 PO5360531011	KU	3	45 BRN	SP	CRE	ID	BD	8/13/2065
2021 PO5405713213	KU	3	40 BRN	SP	CRE	ID	TD	8/14/2065
2021 PO5393312892	KU	3	40 BRN	SP	CRE	ID	TD	8/15/2065
2021 PO4047886531	LGE	5	30 ACE	SP	CRE	ED,ID	BD	8/16/2065
2021 PO4048286529	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/17/2065
2021 PO4049886521	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/18/2065
2021 PO4047286518	LGE	5	30 ACE	SP	CCA		T	8/19/2065
2021 PO4047586516	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/20/2065
2021 PO4046486506	LGE	4	30 ACE	SP	CCA		T	8/21/2065
2021 PO4046686493	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/22/2065
2021 PO4141886056	LGE	2	55 BRO	SP	A	ED,ID	TD	8/23/2065
2021 PO4063785893	LGE	4	30 BRO	SP	P	ED,ID	TD	8/24/2065
2021 PO3981185676	LGE	4	30 ACE	SP	CCA	ED,ID	TD	8/25/2065
2021 PO4144385961	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	8/26/2065
2021 PO3988985984	LGE	4	40 ACE	SP	CCA	ED,ID	TD	8/27/2065

2021 PO4027186539	LGE	4	35 ACE	SP	CCA			T		8/28/2065
2021 PO5421212943	KU	5	40 BRO	SP	CRE		ED,ID,IP	TD		8/29/2065
2021 PO4027986531	LGE	4	35 ACE	SP	CRE		ED,ID	BD		8/30/2065
2021 PO4029586526	LGE	4	40 ACE	SP	CRE		ED,ID	TD		8/31/2065
2021 PO4145686024-A	KU	5	35 BRO	SP	CRE			VX	RP1	9/1/2065
2021 PO5398413035	KU	4	40 BRN	SP	CCA			T		9/2/2065
2021 PO5410212986	KU	3	40 BRO	SP	CRE			BX	RP1	9/3/2065
2021 PO3986485975	LGE	3	45 ACE	SP	CCA		ED,ID	TD		9/4/2065
2021 PO3987485974	LGE	4	40 ACE	SP	CCA		ED,ID	TD		9/5/2065
2021 PO4148286052	LGE	1	60 BRO	SP	A		ID,IP	BD		9/6/2065
2021 PO4148286052-A	KU	4	40 BRO	SP	A		ED,ID	TD		9/7/2065
2021 PO4147886053	LGE	2	55 BRO	SP	A		ED,ID,IP	TD		9/8/2065
2021 PO3983485611	LGE	4	35 ACE	SP	CRE		ED,ID	TD		9/9/2065
2021 PO4013185606	LGE	4	30 KOP	SP	P		ED	BD		9/10/2065
2021 PO5492710132	KU	5	35 KOP	SP	CRE		ED,ID	TD		9/11/2065
2021 PO4024086557	LGE	4	35 ACE	SP	CRE		ED,ID	TD		9/12/2065
2021 PO4025386549	LGE	4	35 ACE	SP	CCA			T		9/13/2065
2021 PO4142685962	LGE	4	40 BRO	SP	A		ED,ID	TD		9/14/2065
2021 PO4085186590	LGE	4	40 ACE	SP	CRE		ED,ID	BD		9/15/2065
2021 PO5018326158	KU	4	40 BRN	SP	CRE			T		9/16/2065
2021 PO3965185684	LGE	1	70 ACE	SP	A		ED,ID	TD		9/17/2065
2021 PO5457712803	KU	2	45 BRN	SP	CCA			T		9/18/2065
2021 PO3955685735	LGE	7	20 ACE	SP	CRE		ID	BD		9/19/2065
2021 PO3970286150	LGE	3	50 ACE	SP	CRE		ED,EP,HH,ID	BX	PX	9/20/2065
2021 PO3969286140	LGE	2	55 ACE	SP	CRE		ED,ID,IP	BD		9/21/2065
2021 PO4144385974	LGE	4	35 BRO	SP	CRE		ED,ID	TD		9/22/2065
2021 PO5097526005	KU	3	45 BRN	SP	CRE			T		9/23/2065
2021 PO5319830843	KU	3	45 BRN	SP	CRE		ID	TD		9/24/2065
2021 PO5315230700	KU	3	45 BRN	SP	CRE		ID	TD		9/25/2065
2021 PO5308530491	KU	4	40 BRN	SP	CRE		ID,IP	TD		9/26/2065
2021 PO5303930348	KU	4	40 BRN	SP	CRE		ID	TD		9/27/2065
2021 PO5431413112	KU	7	35 BRN	SP	CRE		ED,ID,MD,SRS	TD		9/28/2065
2021 PO4145686024	LGE	4	30 BRO	SP	CRE		ED,ID,IP	TD		9/29/2065
2021 PO5336930665	KU	6	30 BRN	SP	CRE		ID	TD		9/30/2065
2021 PO5354330750	KU	5	35 BRN	SP	CRE		ED	X	RP2	10/1/2065
2021 PO5340330804	KU	4	40 BRN	SP	CRE		ID	TD		10/2/2065
2021 PO5343530944	KU	4	40 BRN	SP	CRE		ID	BD		10/3/2065
2021 PO4795738226	KU	3	45 KOP	SP	CRE		ID	BD		10/4/2065
2021 PO4783738308	KU	3	45 KOP	SP	CRE		ID	BD		10/5/2065
2021 PO4772338385	KU	3	45 KOP	SP	CRE		ID	TD		10/6/2065
2021 PO4763238447	KU	3	45 KOP	SP	CRE		ID	TD		10/7/2065
2021 PO5025125868	KU	4	40 BRN	SP	CRE			T		10/8/2065
2021 PO3987785666	LGE	4	40 ACE	SP	CRE		ED,ID	TD		10/9/2065
2021 PO5024025920	KU	5	35 BRN	SP	CRE			T		10/10/2065
2021 PO5418213164	KU	3	40 BRN	SP	CRE		ID	TD		10/11/2065
2021 PO5026926585	KU	4	40 BRN	SP	CRE			T		10/12/2065
2021 PO5017926570	KU	4	40 BRN	SP	CRE			T		10/13/2065
2021 PO3973286180	LGE	3	50 ACE	SP	CRE		ED,ID,IP,MD	TD		10/14/2065
2021 PO3972386171	LGE	3	50 ACE	SP	A		ID	TD		10/15/2065
2021 PO3970486162	LGE	4	30 ACE	SP	CRE		ED,ID,IP	TD		10/16/2065
2021 PO3971386161	LGE	3	50 ACE	SP	CRE		ED,ID,IP,MD	TD		10/17/2065
2021 PO3954585750	LGE	4	40 ACE	SP	A		ID	TD		10/18/2065
2021 PO5348512421	KU	6	35 BRO	SP	CCA		ID	TD		10/19/2065
2021 PO5572609939	KU	4	40 KOP	SP	CRE		ED,ID,IP	TD		10/20/2065

2021 PO5508235203	KU	3	45 BRN	SP	CCA			T			10/21/2065
2021 PO3994586417	LGE	7	25 ACE	SP	CRE		ID	BD			10/22/2065
2021 PO4057586612	LGE	4	40 ACE	SP	CRE		ED,ID	TD			10/23/2065
2021 PO4058686623	LGE	4	40 ACE	SP	CCA			T			10/24/2065
2021 PO4015085645	LGE	4	35 KOP	SP	P		ED	TD			10/25/2065
2021 PO4019685695	LGE	4	35 KOP	SP	P		ED,ID	TD			10/26/2065
2021 PO4056486602	LGE	4	40 ACE	SP	CRE		ED,ID	BD			10/27/2065
2021 PO3996886416	F	4	30 ACE	SP	P			VX	PX		10/28/2065
2021 PO5348011629	KU	3	40 BRO	SP	CRE		ED,ID	TD			10/29/2065
2021 PO5356211854	KU	7	30 BRO	SP	CRE		ID,SRS	TD			10/30/2065
2021 PO4017785696	LGE	4	30 KOP	SP	P		ED	TD			10/31/2065
2021 PO4017285692	LGE	4	35 KOP	SP	CCA		ED,ID	TD			11/1/2065
2021 PO4848337896	KU	3	45 UNK	SP	CRE		ED,ID	VX	PX		11/2/2065
2021 PO5074526769	KU	4	40 BRN	SP	CRE			T			11/3/2065
2021 PO3977086228	LGE	4	35 ACE	SP	CRE		ID	TD			11/4/2065
2021 PO3976986215	LGE	3	50 ACE	SP	CRE		ED,ID,IP	TD			11/5/2065
2021 PO3977886224	LGE	3	50 ACE	SP	A		ID	TD			11/6/2065
2021 PO4149086052	LGE	1	95 BRO	SP	A		ED,ID	TD			11/7/2065
2021 PO5439612872	KU	3	40 BRO	SP	CRE		ID	T			11/8/2065
2021 PO4815538196	KU	4	40 UNK	SP	CRE		ID	TD			11/9/2065
2021 PO4830538103	KU	4	40 UNK	SP	CRE		ID	TD			11/10/2065
2021 PO3980286249	LGE	3	50 ACE	SP	A		ED,ID,IP	BD			11/11/2065
2021 PO3978486241	LGE	7	25 ACE	SP	A		ED,ID	TD			11/12/2065
2021 PO3979086236	LGE	3	50 ACE	SP	P		ID	TD			11/13/2065
2021 PO5488210060	KU	4	40 KOP	SP	CRE		ED,ID	TD			11/14/2065
2021 PO4835637958	KU	3	45 UNK	SP	CRE		ID	TD			11/15/2065
2021 PO5399012229	KU	4	40 BRO	SP	P		ID	T			11/16/2065
2021 PO5450312878	KU	4	40 BRO	SP	CRE			T			11/17/2065
2021 PO5268031466	KU	4	40 BRN	SP	CRE		EP,ID	TD			11/18/2065
2021 PO5295731788	KU	5	45 BRN	SP	CRE		ID	BD			11/19/2065
2021 PO5005226741	KU	4	40 BRN	SP	CRE		RB	BX	RP1		11/20/2065
2021 PO5008226600	KU	4	40 BRN	SP	CRE		RB	BX	PX		11/21/2065
2021 PO4017585588	LGE	3	45 KOP	SP	CCA		ED	TD			11/22/2065
2021 PO4017385567	LGE	4	40 KOP	SP	P		ED,ID,IP	TD			11/23/2065
2021 PO5378512306	KU	3	40 BRO	SP	CRE		ID	TD			11/24/2065
2021 PO4066086640	LGE	5	40 ACE	SP	CRE		ED,ID	TD			11/25/2065
2021 PO4064886631	LGE	5	40 ACE	SP	CRE		ED,ID	TD			11/26/2065
2021 PO4064286633	LGE	4	40 ACE	SP	CRE		ED,ID	TD			11/27/2065
2021 PO4875437767	KU	3	45 UNK	SP	CRE		ID	BD			11/28/2065
2021 PO4152286051	LGE	2	55 BRO	SP	CRE		ED,ID,IP	TD			11/29/2065
2021 PO4151086051	LGE	2	55 BRO	SP	CRE		ED,ID,IP	TX	RR		11/30/2065
2021 PO4150086052	LGE	2	55 BRO	SP	A		ED,ID,IP	TD			12/1/2065
2021 PO5464409932	KU	4	40 KOP	SP	CRE		ED,ID,IP	BD			12/2/2065
2021 PO5082626343	KU	4	40 BRN	SP	CRE			T			12/3/2065
2021 PO4890737693	KU	3	45 UNK	SP	CRE		ID	TD			12/4/2065
2021 PO4061086638	LGE	5	30 ACE	SP	CRE		ED,ID	TD			12/5/2065
2021 PO4060986644	LGE	4	40 ACE	SP	CRE		ED,ID	TD			12/6/2065
2021 PO4188786237	LGE	4	40 BRO	SP	CRE		HH	VX	RP1		12/7/2065
2021 PO4907737612	KU	3	45 UNK	SP	CRE		ID	TD			12/8/2065
2021 PO4027485895	F	4	35 KOP	SP	CCA			V			12/9/2065
2021 PO5275725209	F	5	35 BRN	SP	CCA			V			12/10/2065
2021 PO4027885938	F	4	40 KOP	SP	CCA			V			12/11/2065
2021 PO4026385946	F	4	40 KOP	SP	P			V			12/12/2065
2021 PO4037685985	F	4	40 KOP	SP	CCA			V			12/13/2065

2021 PO4061085703	F	4	30 BRO	SP	CRE		V	12/14/2065	
2021 PO4060585701	F	2	60 BRO	SP	CCA		V	12/15/2065	
2021 PO4060685712	F	3	55 BRO	SP	CRE		V	12/16/2065	
2021 PO4060685724	F	3	50 BRO	SP	CRE		V	12/17/2065	
2021 PO4060785738	F	3	45 BRO	SP	P		V	12/18/2065	
2021 PO4058485761	F	4	40 BRO	SP	CRE		V	12/19/2065	
2021 PO4058585773	F	4	40 BRO	SP	P		V	12/20/2065	
2021 PO4058585784	F	4	40 BRO	SP	CRE		V	12/21/2065	
2021 PO4058685794	F	4	40 BRO	SP	CRE		V	12/22/2065	
2021 PO4058685804	F	4	40 BRO	SP	CRE		V	12/23/2065	
2021 PO4057385728	F	6	25 BRO	SP	CRE		V	12/24/2065	
2021 PO4057085735	F	4	40 BRO	SP	P		V	12/25/2065	
2021 PO4057485744	F	6	30 BRO	SP	CRE		V	12/26/2065	
2021 PO4057085743	F	4	40 BRO	SP	CRE		V	12/27/2065	
2021 PO4056585752	F	4	40 BRO	SP	A		V	12/28/2065	
2021 PO4029485928	F	4	40 KOP	SP	CCA		V	12/29/2065	
2021 PO4029185933	F	4	30 KOP	SP	P		V	12/30/2065	
2021 PO4029085930	F	4	40 KOP	SP	CCA		V	12/31/2065	
2021 PO4028685922	F	4	40 KOP	SP	CCA		V	1/1/2066	
2021 PO4028185912	F	4	40 KOP	SP	CCA		V	1/2/2066	
2021 PO4055085755	F	3	45 BRO	SP	CCA		V	1/3/2066	
2021 PO4055085752	F	3	55 BRO	SP	CRE		V	1/4/2066	
2021 PO4055185767	F	4	40 BRO	SP	CRE		V	1/5/2066	
2021 PO4055285792	F	4	40 BRO	SP	P		V	1/6/2066	
2021 PO4055285804	F	4	40 BRO	SP	P		V	1/7/2066	
2021 PO4055385809	F	6	25 BRO	SP	CRE		V	1/8/2066	
2021 PO4061485760	F	4	35 BRO	SP	CCA		V	1/9/2066	
2021 PO4061485750	F	4	35 BRO	SP	CCA		V	1/10/2066	
2021 PO4060885750	F	3	45 BRO	SP	P		V	1/11/2066	
2021 PO4060985772	F	3	45 BRO	SP	CCA		V	1/12/2066	
2021 PO4061585772	F	4	30 BRO	SP	CRE		V	1/13/2066	
2021 PO4061685784	F	4	30 BRO	SP	CRE		V	1/14/2066	
2021 PO4061085784	F	4	40 BRO	SP	CRE		V	1/15/2066	
2021 PO4061685796	F	4	30 BRO	SP	CCA		V	1/16/2066	
2021 PO4061785808	F	3	45 BRO	SP	CCA		V	1/17/2066	
2021 PO4061185807	F	3	45 BRO	SP	CCA		V	1/18/2066	
2021 PO4061185796	F	4	40 BRO	SP	CCA		V	1/19/2066	
2021 PO4071785740	LGE	4	30 BRO	SP	CRE		V	1/20/2066	
2021 PO4060985977	LGE	3	45 BRO	SP	CCA		V	1/21/2066	
2021 PO4060885759	F	4	40 BRO	SP	CRE		V	1/22/2066	
2021 PO4032085891	F	4	30 KOP	SP	CCA		V	1/23/2066	
2021 PO4032285898	F	3	45 KOP	SP	CCA		V	1/24/2066	
2021 PO5229426247	F	2	35 BRN	SP	CRE		V	1/25/2066	
2021 PO5229026271	KU	2	45 BRN	SP	CRE		B	1/26/2066	
2021 PO5390811464	KU	3	40 BRO	SP	CCA		V	1/27/2066	
2021 PO4190186297	LGE	4	35 BRO	SP	A	ED,ID,JP,RB	X	RP1	1/28/2066
2021 PO4189086281	F	1	55 BRO	SP	CCA		V	1/29/2066	
2021 PO4189286278	F	3	55 BRO	SP	CRE		V	1/30/2066	
2021 PO4189686271	F	2	55 BRO	SP	CCA		V	1/31/2066	
2021 PO4189686269	F	3	55 BRO	SP	CRE		V	2/1/2066	
2021 PO0795157074	KU	4	40 BRO	SP	CCA		V	2/2/2066	
2021 PO0772557179	KU	4	40 BRO	SP	CCA		V	2/3/2066	
2021 PO4190586251	LGE	4	40 BRO	ST	P		V	2/4/2066	
2021 PO0834857435	KU	3	45 BRO	SP	CCA		V	2/5/2066	

2021 PO4189686266	LGE	3	50 BRO	SP	CRE	ID,IP	BD		2/6/2066
2021 PO4190586254	LGE	2	55 BRO	SP	CRE	ID,IP	BD		2/7/2066
2021 PO0812357714	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD		2/8/2066
2021 PO4936004872	F	4	45 XXX	SP	CCA		V		2/9/2066
2021 PO4888904908	F	4	40 XXX	SP	CRE		V		2/10/2066
2021 PO4901104872	F	4	45 XXX	SP	CCA		V		2/11/2066
2021 PO4924704890	F	4	45 XXX	SP	CCA		V		2/12/2066
2021 PO4915004834	F	4	45 XXX	SP	CCA		V		2/13/2066
2021 PO4894204599	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	RP1	2/14/2066
2021 PO4876804633	F	4	40 XXX	SP	CRE		V		2/15/2066
2021 PO4926304254	F	4	40 XXX	SP	CRE		V		2/16/2066
2021 PO4940604437	F	4	40 XXX	SP	CRE		V		2/17/2066
2021 PO4944604487	KU	4	40 XXX	SP	CRE	ED,ID	TD		2/18/2066
2021 PO4930804515	KU	6	30 XXX	SP	CRE	ED,ID	TD		2/19/2066
2021 PO4189786261	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		2/20/2066
2021 PO4189086268	LGE	4	35 BRO	SP	CRE	ID	BD		2/21/2066
2021 PO4187886254	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		2/22/2066
2021 PO9015574525	LGE	4	35 BRO	SP	CCA		V		2/23/2066
2021 PO4186986246	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		2/24/2066
2021 PO0781757647	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD		2/25/2066
2021 PO4186186238	LGE	4	35 BRO	SP	A	ED,ID	TD		2/26/2066
2021 PO4959202525	KU	4	45 XXX	SP	CRE	ID,RB	X	RP1	2/27/2066
2021 PO4972102492	KU	4	40 XXX	SP	CRE	ID	BD		2/28/2066
2021 PO4982802465	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		3/1/2066
2021 PO4962302196	KU	6	30 BRN	SP	CCA		V		3/2/2066
2021 PO4959102194	KU	4	40 BRN	SP	CCA		V		3/3/2066
2021 PO4951402192	KU	4	40 XXX	SP	CRE	ID	BD		3/4/2066
2021 PO4950202154	KU	4	40 XXX	SP	CRE	ID	BD		3/5/2066
2021 PO0744057502	KU	4	40 BRO	SP	CRE	ED,ID,MD	TD		3/6/2066
2021 PO4184086238	F	4	35 BRO	SP	CRE		V		3/7/2066
2021 PO4185086217	F	4	40 BRO	SP	CRE		V		3/8/2066
2021 PO3468507847	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		3/9/2066
2021 PO3389507992	KU	4	40 BRN	SP	CCA	ID	TD		3/10/2066
2021 PO2546529661	KU	3	45 BRN	SP	CCA		V		3/11/2066
2021 PO4183386249	F	4	35 BRO	SP	A		V		3/12/2066
2021 PO4182686261	F	4	40 BRO	SP	CRE		V		3/13/2066
2021 PO3511707626	KU	5	35 BRN	SP	CRE	ED,ID	TD		3/14/2066
2021 PO4181986272	F	4	40 BRO	SP	A		V		3/15/2066
2021 PO4269106051	KU	2	50 BRN	SP	CRE		V		3/16/2066
2021 PO0780257708	KU	4	40 BRO	SP	CCA		V		3/17/2066
2021 PO0761957601	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD		3/18/2066
2021 PO0760857669	KU	6	30 BRO	SP	CRE	ED,ID,SRC	BD		3/19/2066
2021 PO4185386230	F	4	35 BRO	SP	CCA		V		3/20/2066
2021 PO0810057880	KU	4	40 BRO	SP	CRE		V		3/21/2066
2021 PO4184686227	F	4	40 BRO	SP	CRE		V		3/22/2066
2021 PO4947202561	KU	4	45 XXX	SP	CRE	ID	BD		3/23/2066
2021 PO4190786238	LGE	4	35 BRO	SP	CCA		V		3/24/2066
2021 PO7933980599	KU	3	45 BRO	SP	CCA		V		3/25/2066
2021 PO7962480587	KU	3	45 BRO	SP	CCA		V		3/26/2066
2021 PO2044632901	F	2	45 BRN	SP	A		V		3/27/2066
2021 PO1986232937	F	2	45 BRN	SP	A		V		3/28/2066
2021 PO1982132942	F	2	45 BRN	SP	A		V		3/29/2066
2021 PO2004532921	F	2	45 BRN	SP	A		V		3/30/2066
2021 PO4121785827	F	3	50 BRN	SP	CCA		V		3/31/2066

2021 PO4191486238	F	4	35 BRO	SP	A		V	4/1/2066
2021 PO4107286328	LGE	4	30 ACE	SP	CRE	ED,ID	TD	4/2/2066
2021 PO4107286319	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	4/3/2066
2021 PO4107086317	LGE	4	30 ACE	SP	P	ED,ID	TD	4/4/2066
2021 PO7957580501	KU	6	30 BRO	SP	CRE	ED,ID	BD	4/5/2066
2021 PO7963780428	KU	3	45 BRO	SP	A	ED,ID	TD	4/6/2066
2021 PO4123385834	LGE	1	75 BRN	SP	CRE		V	4/7/2066
2021 PO2570809543	KU	2	45 UNK	SP	CRE	ID	BD	4/8/2066
2021 PO2575409541	KU	2	45 UNK	SP	CRE	ID	TD	4/9/2066
2021 PO2572809790	KU	4	45 UNK	SP	CRE	ID	BD	4/10/2066
2021 PO4192186301	LGE	4	40 BRO	SP	CRE	ID,IP	BD	4/11/2066
2021 PO4123485852	LGE	3	45 BRN	SP	CRE	ID,IP	BD	4/12/2066
2021 PO4124085862	LGE	3	45 BRN	SP	CRE	ID	BD	4/13/2066
2021 PO4192686290	LGE	4	40 BRO	SP	CRE	ID	BD	4/14/2066
2021 PO4191786307	LGE	4	40 BRO	SP	CRE	ID	BD	4/15/2066
2021 PO7973780157	KU	4	45 BRO	SP	CRE	ED,ID	TD	4/16/2066
2021 PO8016380048	KU	5	35 BRO	SP	CCA		V	4/17/2066
2021 PO4125385884	LGE	3	45 BRN	SP	CRE	ED,ID,IP	BD	4/18/2066
2021 PO4129585937	LGE	1	75 BRN	ST	P		V	4/19/2066
2021 PO4125685872	LGE	2	75 BRN	SP	CRE		V	4/20/2066
2021 PO4124885874	LGE	3	45 BRN	SP	CCA		V	4/21/2066
2021 PO2356434781	KU	5	35 BRN	SP	CRE	ED,HH,ID,IP	TD	4/22/2066
2021 PO0484650997	KU	4	40 BRO	SP	CRE	ED,EP,HH,MD	BX PX	4/23/2066
2021 PO2431233432	KU	4	40 BRN	SP	CRE	ID	TD	4/24/2066
2021 PO2426733401	KU	4	40 BRN	SP	CRE	ID	TD	4/25/2066
2021 PO2415232941	KU	3	45 BRN	SP	CCA		V	4/26/2066
2021 PO2424332882	KU	6	30 BRN	SP	CCA		V	4/27/2066
2021 PO2438832523	KU	6	30 BRN	SP	CRE	ID	BD	4/28/2066
2021 PO2466032452	KU	6	30 BRN	SP	CRE	ID	BD	4/29/2066
2021 PO2461932013	KU	6	30 BRN	SP	CRE	ID	BD	4/30/2066
2021 PO2498731182	KU	5	35 BRN	SP	CRE		V	5/1/2066
2021 PO2505331096	KU	5	35 BRN	SP	CCA		V	5/2/2066
2021 PO4121786267	LGE	4	40 ACE	SP	CRE	ED,ID	BD	5/3/2066
2021 PO3253602247	KU	4	40 UNK	SP	CRE	HH,ID	TX RR	5/4/2066
2021 PO4186286402	LGE	4	40 BRO	SP	A	ED,ID	TD	5/5/2066
2021 PO4122986266	LGE	4	40 ACE	SP	P	ED,ID	TD	5/6/2066
2021 PO4124186265	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	5/7/2066
2021 PO4125386264	F	4	40 ACE	SP	CCA		V	5/8/2066
2021 PO9682912016	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/9/2066
2021 PO9742711588	KU	4	40 ACW	SP	CRE	ED,ID,IP,MD,SRC	TD	5/10/2066
2021 PO9809011882	KU	4	40 ACW	SP	S		V	5/11/2066
2021 PO9719210413	KU	5	35 ACW	SP	CRE	ED,ID	TD	5/12/2066
2021 PO9702711037	KU	5	40 ACW	SP	S		V	5/13/2066
2021 PO9699011221	KU	5	35 ACW	SP	S		V	5/14/2066
2021 PO9688211771	KU	4	40 ACW	SP	S		V	5/15/2066
2021 PO8009081235	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/16/2066
2021 PO8014781370	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/17/2066
2021 PO4560003472	KU	4	40 BRN	SP	S		V	5/18/2066
2021 PO4193686308	LGE	4	35 BRO	SP	CCA		V	5/19/2066
2021 PO4678006439	F	5	45 XXX	SP	A		V	5/20/2066
2021 PO4691406443	F	4	40 XXX	SP	CRE		V	5/21/2066
2021 PO4728306657	F	4	40 XXX	SP	A		V	5/22/2066
2021 PO4732106885	F	4	40 XXX	SP	P		V	5/23/2066
2021 PO4707606536	KU	5	35 BRN	SP	CCA		V	5/24/2066

2021 PO4697606547	KU	6	30 BRN	SP	CCA		V	5/25/2066
2021 PO4721906842	F	4	40 KOP	SP	P		V	5/26/2066
2021 PO4708606841	F	4	40 XXX	SP	CRE		V	5/27/2066
2021 PO4611206356	F	3	45 BRN	SP	CCA		V	5/28/2066
2021 PO4582606445	F	4	45 XXX	SP	CRE		V	5/29/2066
2021 PO4600406384	F	4	40 XXX	SP	CRE		V	5/30/2066
2021 PO4603606301	F	3	45 XXX	SP	CCA		V	5/31/2066
2021 PO4588806207	F	4	40 XXX	SP	CRE		V	6/1/2066
2021 PO2452234618	KU	4	40 BRN	SP	CRE	ED,HH,ID	TD	6/2/2066
2021 PO2473433479	KU	6	30 BRN	SP	CRE	ID	BD	6/3/2066
2021 PO5237702640	F	3	45 BRN	SP	CCA		V	6/4/2066
2021 PO9710810629	KU	5	35 ACW	SP	CRE	ED,ID,JP,SRC	TD	6/5/2066
2021 PO9763311521	KU	5	40 ACW	SP	CRE	ED,ID,MD	TD	6/6/2066
2021 PO9787011778	KU	4	40 ACW	SP	S		V	6/7/2066
2021 PO9765511684	KU	4	40 ACW	SP	S		V	6/8/2066
2021 PO9791410474	KU	3	45 ACW	SP	S		V	6/9/2066
2021 PO9809710516	KU	3	45 ACW	SP	CRE		V	6/10/2066
2021 PO9739110599	KU	4	40 ACW	SP	CRE	ED,ID	TD	6/11/2066
2021 PO9763710401	KU	4	40 ACW	SP	CRE	ED,ID	TD	6/12/2066
2021 PO9787210204	KU	4	40 ACW	SP	CRE	ED,ID	TD	6/13/2066
2021 PO5238903290	F	3	45 BRN	SP	CCA		V	6/14/2066
2021 PO5238203033	F	3	45 BRN	SP	CCA		V	6/15/2066
2021 PO5239103435	F	3	40 BRN	SP	CCA		V	6/16/2066
2021 PO5238603165	F	3	45 BRN	SP	CCA		V	6/17/2066
2021 PO4571102751	KU	6	30 BRN	SP	S	ED	TD	6/18/2066
2021 PO4571102751	KU	4	40 BRN	SP	S	ED	TD	6/19/2066
2021 PO4563202635	KU	6	30 BRN	SP	CCA		V	6/20/2066
2021 PO4578602850	KU	4	45 BRN	SP	CRE	ED,ID,RB,SRC	TX	RR 6/21/2066
2021 PO8019579183	KU	3	45 BRO	SP	CCA		V	6/22/2066
2021 PO4130385969	LGE	4	40 BRN	SP	P	ID,IP	BD	6/23/2066
2021 PO4130085985	KU	4	35 BRN	SP	P	ID	BD	6/24/2066
2021 PO4131185977	LGE	4	40 BRN	SP	CCA	IP	BD	6/25/2066
2021 PO4131385980	LGE	4	40 BRN	ST	CCA		V	6/26/2066
2021 PO0494950825	KU	4	40 BRO	SP	CRE	ED,ID,MD	TD	6/27/2066
2021 PO4128586256	LGE	4	30 ACE	SP	P	ED,ID	TD	6/28/2066
2021 PO4129586255	LGE	5	35 ACE	SP	CRE	ED,ID	TD	6/29/2066
2021 PO7669476049	KU	6	30 BRO	SP	CRE	ED,ID	TD	6/30/2066
2021 PO7680876038	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/1/2066
2021 PO7711776416	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/2/2066
2021 PO0455750545	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/3/2066
2021 PO0460750218	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/4/2066
2021 PO0455550099	F	4	40 BRO	SP	CRE		V	7/5/2066
2021 PO0440249995	F	4	40 BRO	SP	CRE		V	7/6/2066
2021 PO4188586325	LGE	4	35 BRO	SP	A	ED,ID	TD	7/7/2066
2021 PO4189186316	LGE	4	35 BRO	SP	A	ED,ID	TD	7/8/2066
2021 PO7706176500	KU	4	45 BRO	SP	CRE	ED,ID	TD	7/9/2066
2021 PO4755006208	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	PX 7/10/2066
2021 PO4108786318	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	7/11/2066
2021 PO4122885840	LGE	3	45 BRN	SP	CRE	ID,IP	BX	RR 7/12/2066
2021 PO2024632902	F	2	45 BRN	SP	A		V	7/13/2066
2021 PO2037633513	KU	4	40 BRN	SP	CRE		V	7/14/2066
2021 PO4552203312	KU	4	45 BRN	SP	CRE	ED,ID,SRC	TD	7/15/2066
2021 PO4541903161	KU	4	45 BRN	SP	CRE	ED,ID	TD	7/16/2066
2021 PO4544802940	KU	6	30 BRN	SP	S		V	7/17/2066



2021	PO4523602905	KU	6	30 BRN	SP	CCA			V	7/18/2066
2021	PO4530803013	KU	3	45 BRN	SP	S			V	7/19/2066
2021	PO4531803208	KU	4	40 BRN	SP	CRE	ED,ID,RB	BX	RR	7/20/2066
2021	PO4519503047	KU	6	30 BRN	SP	S			V	7/21/2066
2021	PO4522203252	KU	4	40 BRN	SP	CRE	ED,ID		TD	7/22/2066
2021	PO5317901032	F	7	35E BRN	SP	CRE			V	7/23/2066
2021	PO5239503588	F	3	45 BRN	SP	CCA			V	7/24/2066
2021	PO5240403901	F	3	45 BRN	SP	CCA			V	7/25/2066
2021	PO5240103742	F	4	40 BRN	SP	CCA			V	7/26/2066
2021	PO5240704022	F	3	45 BRN	SP	CCA			V	7/27/2066
2021	PO2476033796	KU	4	40 BRN	SP	CRE	ID		TD	7/28/2066
2021	PO4186086368	LGE	4	35 BRO	SP	CRE			V	7/29/2066
2021	PO4186786395	F	4	35 BRO	SP	CRE			V	7/30/2066
2021	PO4187486382	F	4	40 BRO	SP	A			V	7/31/2066
2021	PO4189086372	F	4	40 BRO	SP	CRE			V	8/1/2066
2021	PO5243104759	F	4	40 BRN	SP	CRE			V	8/2/2066
2021	PO5241104145	F	3	45 BRN	SP	CCA			V	8/3/2066
2021	PO4130386050	LGE	4	30 BRN	SP	P	ID		BD	8/4/2066
2021	PO5241104213	F	3	45 BRN	SP	CCA			V	8/5/2066
2021	PO5241704335	F	3	40 BRN	SP	P			V	8/6/2066
2021	PO5241804411	F	3	45 BRN	SP	CCA			V	8/7/2066
2021	PO2480927481	KU	6	30 BRN	SP	CRE	ED,ID,MD		TD	8/8/2066
2021	PO2520629370	KU	2	60 BRN	SP	CRE	ID		TD	8/9/2066
2021	PO2519828407	KU	6	30 BRN	SP	CRE	ED,ID,IP		BD	8/10/2066
2021	PO2534528800	KU	5	35 BRN	SP	CCA	ID		V	8/11/2066
2021	PO2523928714	KU	3	45 BRN	SP	CCA			V	8/12/2066
2021	PO2525629063	KU	3	45 BRN	SP	CCA			V	8/13/2066
2021	PO2514628430	KU	3	45 BRN	SP	CCA			V	8/14/2066
2021	PO4187886300	F	3	55 BRO	SP	CRE			V	8/15/2066
2021	PO4187286312	F	2	55 BRO	SP	CCA			V	8/16/2066
2021	PO4186786321	F	2	55 BRO	SP	CRE			V	8/17/2066
2021	PO4186086333	F	2	55 BRO	SP	CCA			V	8/18/2066
2021	PO4185586341	F	3	55 BRO	SP	CRE			V	8/19/2066
2021	PO4188086360	LGE	3	40 BRO	SP	CCA			V	8/20/2066
2021	PO4187286350	LGE	4	35 BRO	SP	A	ED,ID		TD	8/21/2066
2021	PO4186786345	LGE	4	40 BRO	SP	CRE			V	8/22/2066
2021	PO4188086336	LGE	4	35 BRO	SP	A	ED,ID,IP		TD	8/23/2066
2021	PO9036271641	KU	4	40 BRO	SP	CRE	ED,ID		TD	8/24/2066
2021	PO8978171357	KU	4	40 BRO	SP	CRE	ED,ID		TD	8/25/2066
2021	PO9006471507	KU	4	40 BRO	SP	CRE	ED,ID		TD	8/26/2066
2021	PO8955371210	KU	4	40 BRO	SP	CRE	ED,ID		TD	8/27/2066
2021	PO8943371134	KU	4	45 BRO	SP	CCA			V	8/28/2066
2021	PO8927171434	KU	4	45 BRO	SP	CCA			V	8/29/2066
2021	PO8906971790	KU	4	45 BRO	SP	CCA			V	8/30/2066
2021	PO5245103742	F	6	40 BRN	SP	CRE			V	8/31/2066
2021	PO5261403736	F	3	40 BRN	SP	CRE			V	9/1/2066
2021	PO8880372289	KU	4	45 BRO	SP	CCA			V	9/2/2066
2021	PO5269403581	F	4	40 BRN	SP	CRE			V	9/3/2066
2021	PO5269403634	F	7	40 BRN	SP	CRE			V	9/4/2066
2021	PO5267003858	F	3	40 BRN	SP	CRE	ED,HH,ID	BX	RP1	9/5/2066
2021	PO4747106469	F	4	40 XXX	SP	P			V	9/6/2066
2021	PO4709806452	F	4	45 KOP	SP	P			V	9/7/2066
2021	PO4725306458	F	4	45 KOP	SP	P			V	9/8/2066
2021	PO4725406402	F	5	35 XXX	SP	P			V	9/9/2066

2021 PO9689914727	KU	4	40 ACW	SP	CRE	ED,ID	TD	9/10/2066
2021 PO2238735407	KU	6	35 BRN	SP	CRE	ID	TD	9/11/2066
2021 PO4114685681	LGE	1	95 BRN	ST	CCA		V	9/12/2066
2021 PO4112985656	LGE	1	95 BRN	SP	P		V	9/13/2066
2021 PO4112085640	LGE	1	95 BRN	ST	P		V	9/14/2066
2021 PO4111185624	LGE	1	95 BRN	ST	P		V	9/15/2066
2021 PO4110285609	LGE	1	95 BRN	ST	P		V	9/16/2066
2021 PO4109385597	LGE	1	95 BRN	ST	CCA		V	9/17/2066
2021 PO2277635066	F	6	30 BRN	SP	CRE		V	9/18/2066
2021 PO2070732926	KU	4	45 BRN	SP	CRE	ID	TD	9/19/2066
2021 PO4696606839	F	4	40 XXX	SP	CRE		V	9/20/2066
2021 PO4680006769	KU	5	35 BRN	SP	CCA		V	9/21/2066
2021 PO4678806835	F	4	40 XXX	SP	CRE		V	9/22/2066
2021 PO4661306833	F	4	40 XXX	SP	CRE		V	9/23/2066
2021 PO4639506831	F	4	40 XXX	SP	CRE		V	9/24/2066
2021 PO4192286333	LGE	4	35 BRO	SP	CRE	ED,ID	TD	9/25/2066
2021 PO4193086318	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	9/26/2066
2021 PO5290802188	KU	7	30 BRN	SP	CRE	ED,ID	TD	9/27/2066
2021 PO5272702021	F	5	40 BRN	SP	CRE		V	9/28/2066
2021 PO5261202023	F	3	40 BRN	SP	CRE		V	9/29/2066
2021 PO4088685246	LGE	1	80 BRN	SP	CRE		V	9/30/2066
2021 PO4087885232	LGE	1	85 BRN	ST	P		V	10/1/2066
2021 PO4115886312	LGE	3	45 ACE	SP	CCA		V	10/2/2066
2021 PO4111586325	LGE	4	30 ACE	SP	CCA		V	10/3/2066
2021 PO4110186324	LGE	4	35 ACE	SP	CRE	ED,ID	TD	10/4/2066
2021 PO4110286317	LGE	4	40 ACE	SP	CRE	ED,ID	TD	10/5/2066
2021 PO2935205842	KU	4	40 UNK	SP	CCA		V	10/6/2066
2021 PO4126085895	LGE	3	45 BRN	SP	P	ED,ID,IP	BD	10/7/2066
2021 PO4007883724	LGE	1	95 BRO	SP	A		V	10/8/2066
2021 PO4097085803	LGE	4	30 ACE	SP	CRE	EP,RB	VX	PX 10/9/2066
2021 PO5458227021	KU	5	35 UNK	SP	CRE		B	10/10/2066
2021 PO5471927034	KU	4	45 UNK	SP	CCA		V	10/11/2066
2021 PO4096685800	F	4	40 ACE	SP	CCA		V	10/12/2066
2021 PO4095685801	F	4	40 ACE	SP	CRE		V	10/13/2066
2021 PO4098685798	F	4	40 ACE	SP	CRE		V	10/14/2066
2021 PO4098185799	F	4	40 ACE	SP	CRE		V	10/15/2066
2021 PO4099785806	LGE	4	40 ACE	SP	CRE		V	10/16/2066
2021 PO4100885797	LGE	4	40 ACE	SP	CCA		V	10/17/2066
2021 PO3989683580	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	10/18/2066
2021 PO3988883580	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	10/19/2066
2021 PO5484326980	KU	3	45 UNK	SP	CRE		T	10/20/2066
2021 PO5493226984	KU	5	35 UNK	SP	CRE		B	10/21/2066
2021 PO5502726988	KU	5	35 UNK	SP	CRE		B	10/22/2066
2021 PO7911068409	KU	2	55 ACE	SP	CRE	ED,ID	BD	10/23/2066
2021 PO7908068392	KU	2	60 ACE	SP	CCA		V	10/24/2066
2021 PO2259292207	KU	4	40 KOP	SP	CCA		V	10/25/2066
2021 PO2336991642	KU	7	30 KOP	SP	CCA		V	10/26/2066
2021 PO4099585798	F	4	40 ACE	SP	CRE		V	10/27/2066
2021 PO7901468486	KU	4	45 ACE	SP	CRE	ED,ID	BD	10/28/2066
2021 PO7902368461	KU	2	55 ACE	SP	CRE	ED,ID	BD	10/29/2066
2021 PO7900968511	KU	4	45 ACE	SP	CCA		V	10/30/2066
2021 PO7903568539	KU	4	45 ACE	SP	CRE	ED,ID	TD	10/31/2066
2021 PO3987783579	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	11/1/2066
2021 PO4101385789	LGE	4	35 ACE	SP	CCA		V	11/2/2066

2021 PO4101985796	LGE	4	40 ACE	SP	CRE		V	11/3/2066
2021 PO5496727115	KU	5	35 UNK	SP	CRE		B	11/4/2066
2021 PO5485527109	KU	5	35 UNK	SP	CRE		B	11/5/2066
2021 PO5794687293	KU	4	40 ACE	SP	CRE	ID	TD	11/6/2066
2021 PO8977796848	KU	5	35 BRO	SP	CCA		V	11/7/2066
2021 PO8968796975	KU	5	35 BRO	SP	CCA		V	11/8/2066
2021 PO8956996852	KU	5	35 BRO	SP	CCA		V	11/9/2066
2021 PO8946096690	KU	6	30 BRO	SP	CCA		V	11/10/2066
2021 PO8950996658	KU	3	45 BRO	SP	CCA		V	11/11/2066
2021 PO8961996594	KU	3	45 BRO	SP	CCA		V	11/12/2066
2021 PO8969296501	F	5	40 UNK	SP	CRE	ED	V	11/13/2066
2021 PO8974296526	KU	5	35 UNK	SP	CRE	ED,ID	BD	11/14/2066
2021 PO8972396302	KU	5	35 UNK	SP	CRE	ED,ID	TD	11/15/2066
2021 PO8980796436	F	4	40 UNK	SP	CRE	ED	V	11/16/2066
2021 PO8982596340	KU	5	35 UNK	SP	CRE	ED,ID	TD	11/17/2066
2021 PO8987196451	KU	4	45 UNK	SP	CRE	ED,ID	BD	11/18/2066
2021 PO9000596377	KU	4	40 UNK	SP	CRE	ED,ID	BD	11/19/2066
2021 PO9022996261	KU	5	30 UNK	SP	CRE	ED,ID	TD	11/20/2066
2021 PO9013096306	KU	4	45 UNK	SP	CRE	ED,ID	BD	11/21/2066
2021 PO8931996604	KU	5	35 UNK	SP	CRE	ED,ID	BD	11/22/2066
2021 PO8922196721	KU	5	30 UNK	SP	CRE	ED,ID,IP	TD	11/23/2066
2021 PO8919796670	KU	4	40 UNK	SP	CRE	ED,ID	BD	11/24/2066
2021 PO8914496574	KU	5	35 BRO	SP	CCA		V	11/25/2066
2021 PO8900496905	KU	6	30 BRO	SP	CCA		V	11/26/2066
2021 PO8903696847	KU	5	35 UNK	SP	CRE	ED,ID	BD	11/27/2066
2021 PO8904596752	KU	5	35 UNK	SP	CRE	ED,ID	BD	11/28/2066
2021 PO8944896535	KU	4	40 BRO	SP	P		V	11/29/2066
2021 PO8938896415	KU	3	45 UNK	SP	CCA		V	11/30/2066
2021 PO9060895583	F	5	35 BRO	SP	P		V	12/1/2066
2021 PO9056595592	F	6	35 UNK	SP	CRE	ED	V	12/2/2066
2021 PO9051595597	F	5	35 BRO	SP	CRE	ED	V	12/3/2066
2021 PO9050995511	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/4/2066
2021 PO9050095755	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/5/2066
2021 PO9048395643	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/6/2066
2021 PO9031995600	F	5	35 BRO	SP	P	ED	V	12/7/2066
2021 PO2259192367	KU	4	40 KOP	SP	CCA		V	12/8/2066
2021 PO7908668534	KU	4	45 ACE	SP	CCA		V	12/9/2066
2021 PO7908568364	KU	1	90 ACE	ST	CRE		V	12/10/2066
2021 PO4103685795	LGE	3	50 ACE	SP	CRE		V	12/11/2066
2021 PO2471285842	KU	5	35 KOP	SP	S		V	12/12/2066
2021 PO2502185799	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/13/2066
2021 PO2460185812	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/14/2066
2021 PO2319792484	KU	7	30 KOP	SP	CCA		V	12/15/2066
2021 PO5795487537	KU	5	35 ACE	SP	CRE	ID	TD	12/16/2066
2021 PO5857287282	KU	4	45 ACE	SP	CRE	ID	TD	12/17/2066
2021 PO3987783579	KU	4	35 BRO	SP	A	ED,ID,IP	TD	12/18/2066
2021 PO4103685786	LGE	3	45 ACE	SP	CCA		V	12/19/2066
2021 PO4104285790	LGE	4	30 ACE	SP	A		V	12/20/2066
2021 PO4104085791	LGE	4	45 ACE	SP	A		V	12/21/2066
2021 PO4102985774	LGE	4	40 ACE	SP	CRE		V	12/22/2066
2021 PO4102785770	LGE	4	40 ACE	SP	CRE		V	12/23/2066
2021 PO4102585767	LGE	4	40 ACE	SP	CCA		V	12/24/2066
2021 PO4098385715	LGE	4	45 ACE	SP	A	ID	BD	12/25/2066
2021 PO4097885721	LGE	4	35 ACE	SP	CRE	ID	TD	12/26/2066

2021 PO3987783579-A	KU	4	35 BRO	SP	A	ED,ID,IP	TD		12/27/2066
2021 PO5424127463	KU	4	40 UNK	SP	CRE		B		12/28/2066
2021 PO5430727351	KU	3	45 UNK	SP	CCA		V		12/29/2066
2021 PO2316192566	KU	4	40 BRN	SP	CRE	ED	TD		12/30/2066
2021 PO5437027244	KU	2	45 UNK	SP	CRE		B		12/31/2066
2021 PO3991083592-A	KU	4	35 BRO	SP	A	ED,ID	TD		1/1/2067
2021 PO3991083592	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		1/2/2067
2021 PO2271291597	KU	6	45 KOP	SP	CRE	ED	TD		1/3/2067
2021 PO9017095851	F	2	40 SWP	SP	CRE	ED	V		1/4/2067
2021 PO8999095630	KU	4	40 SWP	SP	CRE	ED,ID,IP	TX	RR	1/5/2067
2021 PO3978283508	LGE	5	25 BRO	SP	CRE	ED,ID	TD		1/6/2067
2021 PO4100385970	F	4	40 ACE	SP	CRE		V		1/7/2067
2021 PO4100285961	F	4	40 ACE	SP	CRE		V		1/8/2067
2021 PO9012296171	F	5	35 BRO	SP	CRE	ED,ID,RB	BX	PX	1/9/2067
2021 PO2546393740	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/10/2067
2021 PO2580394118	KU	7	30 BRN	SP	CRE	ED	TD		1/11/2067
2021 PO3987783537	F	4	40 BRO	SP	CCA		V		1/12/2067
2021 PO3988783528	F	3	45 BRO	SP	CRE		V		1/13/2067
2021 PO3987983528	F	4	40 BRO	SP	CRE		V		1/14/2067
2021 PO8273166259	KU	3	45 ACE	SP	CRE	ED,ID	BD		1/15/2067
2021 PO3985883533	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		1/16/2067
2021 PO3987283528	F	4	40 BRO	SP	CCA		V		1/17/2067
2021 PO3986083528	F	4	40 BRO	SP	CRE		V		1/18/2067
2021 PO3984883533	F	4	30 BRO	SP	CRE		V		1/19/2067
2021 PO3984883528	F	3	45 BRO	SP	CCA		V		1/20/2067
2021 PO8274866014	KU	4	40 ACE	SP	CRE	ED,ID	BD		1/21/2067
2021 PO2456487946	KU	4	45 KOP	SP	S		V		1/22/2067
2021 PO2462887393	KU	4	40 KOP	SP	CRE	ED,ID	TD		1/23/2067
2021 PO2429487638	KU	4	40 KOP	DF	CRE	ED,ID	TD		1/24/2067
2021 PO2431887741	KU	4	40 KOP	SP	CRE	ED,ID	TD		1/25/2067
2021 PO2467287405	KU	4	40 KOP	SP	CRE	ED,ID	TD		1/26/2067
2021 PO2414888113	KU	5	35 KOP	SP	CRE	ED,ID	TD		1/27/2067
2021 PO1589188812	KU	4	40 BRN	SP	CCA		V		1/28/2067
2021 PO1561188076	KU	4	40 BRN	SP	CCA		V		1/29/2067
2021 PO1547987584	KU	4	40 BRN	SP	CCA		V		1/30/2067
2021 PO1552589016	KU	4	45 BRN	SP	CCA		V		1/31/2067
2021 PO1566589078	KU	3	45 BRN	SP	CRE		V		2/1/2067
2021 PO1600389168	KU	4	45 UNK	SP	CRE	ID	TD		2/2/2067
2021 PO8273665776	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		2/3/2067
2021 PO4097285753	F	4	40 ACE	SP	A		V		2/4/2067
2021 PO5560827321	F	4	40 UNK	SP	CRE		V		2/5/2067
2021 PO5561327290	KU	4	45 UNK	SP	CRE		B		2/6/2067
2021 PO2582994522	KU	5	40 BRN	SP	CRE	ED,ID	TD		2/7/2067
2021 PO8200566408	KU	4	40 ACE	SP	CRE	ED,ID	TD		2/8/2067
2021 PO4102485740	F	4	35 ACE	SP	P		V		2/9/2067
2021 PO8159469079	LGE	3	45 ACE	SP	A		V		2/10/2067
2021 PO4103485735	LGE	4	40 ACE	SP	A	ED,ID	BD		2/11/2067
2021 PO4102185761	F	4	40 ACE	SP	CRE		V		2/12/2067
2021 PO4101485748	F	4	40 ACE	SP	CRE		V		2/13/2067
2021 PO4103485721	F	4	45 ACE	SP	A		V		2/14/2067
2021 PO3982083593	F	5	25 BRO	SP	A		V		2/15/2067
2021 PO5562227201	F	4	40 UNK	SP	CRE	ED,ID,RB	VX	PX	2/16/2067
2021 PO5563127084	F	4	40 UNK	SP	CRE		V		2/17/2067
2021 PO2586494049	KU	5	40 BRN	SP	CRE	ED,ID,IP	TD		2/18/2067

2021 PO3983183599	F	4	40 BRO	SP	A		V			2/19/2067
2021 PO3982883593	F	4	40 BRO	SP	A		V			2/20/2067
2021 PO3982983582	F	4	40 BRO	SP	A		V			2/21/2067
2021 PO3982583556	F	4	40 BRO	SP	A		V			2/22/2067
2021 PO3983183564	F	4	30 BRO	SP	CRE		V			2/23/2067
2021 PO3982783570	F	4	40 BRO	SP	CCA		V			2/24/2067
2021 PO3983483572	F	5	25 BRO	SP	A		V			2/25/2067
2021 PO4104285730	F	4	40 ACE	SP	CRE		V			2/26/2067
2021 PO8177566377	KU	4	40 ACE	SP	CCA		V			2/27/2067
2021 PO4101585745	F	4	40 ACE	DF	CRE	ED,EP,HH,ID,RB	VX	PX		2/28/2067
2021 PO4100785750	LGE	4	45 ACE	SP	A	ED,ID	BD			3/1/2067
2021 PO8166366365	KU	4	45 ACE	SP	CCA		V			3/2/2067
2021 PO8151666346	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD			3/3/2067
2021 PO8127566356	KU	4	40 ACE	SP	CRE	ED,ID	BD			3/4/2067
2021 PO8103566367	KU	3	50 ACE	SP	CCA		V			3/5/2067
2021 PO8081866374	KU	2	50 ACE	SP	CCA		V			3/6/2067
2021 PO8061866451	KU	2	55 ACE	SP	CCA		V			3/7/2067
2021 PO5556827173	KU	3	50 UNK	SP	CCA		V			3/8/2067
2021 PO5557827074	KU	3	50 UNK	SP	CCA		V			3/9/2067
2021 PO8985696737	KU	6	30 BRO	SP	CRE	ED,ID	BD			3/10/2067
2021 PO2744194599	KU	5	40 KOP	SP	CCA		V			3/11/2067
2021 PO1582296926	KU	3	45 BRN	SP	CCA		V			3/12/2067
2021 PO1616997064	KU	3	40 KOP	SP	CRE	ED,IP	TD			3/13/2067
2021 PO1611597048	KU	3	45 KOP	SP	CCA		V			3/14/2067
2021 PO1592297295	KU	3	45 KOP	SP	CCA		V			3/15/2067
2021 PO1671097367	KU	7	35E KOP	SP	CRE	ED,ID,SR	TD			3/16/2067
2021 PO1642797166	KU	3	40 BRN	SP	CRE	ED,ID,IP	TD			3/17/2067
2021 PO4095385981	LGE	4	40 ACE	SP	CRE	ED,HH,ID,MD,RB	BX	RR		3/18/2067
2021 PO5481125736	KU	4	40 UNK	SP	CRE		B			3/19/2067
2021 PO2879481494	KU	4	40 KOP	SP	CRE	ED,ID	TD			3/20/2067
2021 PO2879981670	KU	4	40 KOP	SP	CRE	ED,ID	TD			3/21/2067
2021 PO2902881801	KU	4	40 KOP	DF	CRE	ED,HH,ID,IP,RB	BX	PX		3/22/2067
2021 PO2796180845	KU	4	40 KOP	SP	S		V			3/23/2067
2021 PO2896781754	KU	4	40 KOP	SP	CRE	ED,ID	TD			3/24/2067
2021 PO4096385980	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD			3/25/2067
2021 PO9034096349	F	5	35 KOP	SP	CRE	ED,HH,ID,RB	BX	RP1		3/26/2067
2021 PO4095485995	LGE	4	40 ACE	SP	A	ED,ID	TD			3/27/2067
2021 PO4094285885	LGE	4	35 ACE	SP	CRE	ED,HH,ID	BD			3/28/2067
2021 PO1689397336	KU	3	40 KOP	SP	CRE	ED,ID,MD	TD			3/29/2067
2021 PO2660082529	KU	3	45 KOP	SP	S		V			3/30/2067
2021 PO2822181475	KU	3	45 KOP	SP	S		V			3/31/2067
2021 PO2721582579	KU	4	40 KOP	SP	CRE	ED,ID	BD			4/1/2067
2021 PO2719982367	KU	4	45 KOP	SP	CRE	ED,ID	TD			4/2/2067
2021 PO2734682809	KU	3	45 KOP	SP	S		V			4/3/2067
2021 PO2681582458	KU	4	40 KOP	SP	S		V			4/4/2067
2021 PO2839781981	KU	4	45 KOP	SP	CRE	ED,ID	TD			4/5/2067
2021 PO2785082150	KU	4	40 KOP	DF	CRE	ED,ID	TD			4/6/2067
2021 PO9075395990	KU	5	35 KOP	SP	CCA		V			4/7/2067
2021 PO9074795948	F	5	35 KOP	SP	CRE		V			4/8/2067
2021 PO9064796161	F	5	35 KOP	SP	CRE		V			4/9/2067
2021 PO9079795918	F	2	35 KOP	SP	CRE		V			4/10/2067
2021 PO9078795870	F	5	35 BRN	SP	CRE		V			4/11/2067
2021 PO5506829255	KU	4	40 UNK	SP	CRE		B			4/12/2067
2021 PO5494929239	KU	2	50 UNK	SP	CRE		B			4/13/2067

2021	PO5503229301	KU	4	40 UNK	SP	CCA			V			4/14/2067
2021	PO5509029344	KU	4	40 UNK	SP	CCA			V			4/15/2067
2021	PO5514729411	KU	5	35 UNK	SP	CRE			B			4/16/2067
2021	PO5521329416	KU	4	40 UNK	SP	CCA			V			4/17/2067
2021	PO5517529470	KU	5	35 UNK	SP	CRE			B			4/18/2067
2021	PO5520729545	KU	5	35 UNK	SP	CRE			B			4/19/2067
2021	PO5526529531	KU	4	40 UNK	SP	CCA			V			4/20/2067
2021	PO5523229597	KU	5	35 UNK	SP	CCA			V			4/21/2067
2021	PO5529229591	KU	4	40 UNK	SP	CCA			V			4/22/2067
2021	PO5525229638	KU	5	35 UNK	SP	CRE			B			4/23/2067
2021	PO5531529641	KU	4	40 UNK	SP	CCA			V			4/24/2067
2021	PO5536129741	KU	4	40 UNK	SP	CCA			V			4/25/2067
2021	PO4016283412	F	4	30 BRO	SP	CRE			V			4/26/2067
2021	PO1793590582	KU	3	45 BRN	SP	CCA			V			4/27/2067
2021	PO3033281895	KU	4	40 KOP	SP	CRE		ED, SRC	T			4/28/2067
2021	PO2983982050	KU	4	40 KOP	SP	CRE		ED, ID	TD			4/29/2067
2021	PO2971181866	KU	4	40 KOP	SP	S			V			4/30/2067
2021	PO3019381892	KU	4	40 KOP	SP	CRE		ED, ID, IP	TD			5/1/2067
2021	PO5181989635	KU	4	40 BRN	SP	CRE		ID	BD			5/2/2067
2021	PO5201089639	KU	4	40 BRN	SP	CRE		ID	BD			5/3/2067
2021	PO5213489626	KU	4	40 BRN	SP	CRE		ID	TD			5/4/2067
2021	PO5221889938	KU	4	40 BRN	SP	CRE		ID	BD			5/5/2067
2021	PO5201390178	KU	4	40 BRN	SP	CRE		ID	TD			5/6/2067
2021	PO5146090788	KU	4	40 BRN	SP	CRE		ID	TD			5/7/2067
2021	PO5178690785	KU	4	40 BRN	SP	CRE		ID, IP	TX	RR		5/8/2067
2021	PO5217590439	KU	3	45 BRN	SP	CRE			V			5/9/2067
2021	PO5219190209	KU	4	45 BRN	SP	CRE			V			5/10/2067
2021	PO5214690823	KU	4	40 ACE	SP	CCA			V			5/11/2067
2021	PO5211991226	KU	4	40 ACE	SP	CCA			V			5/12/2067
2021	PO5249391452	KU	4	40 ACE	SP	CRE		ID	TD			5/13/2067
2021	PO5207191958	KU	4	40 ACE	SP	CCA			V			5/14/2067
2021	PO5208092285	KU	4	40 ACE	SP	CRE		ID	TD			5/15/2067
2021	PO5609387488	KU	5	45 ACE	SP	CCA			V			5/16/2067
2021	PO5660687753	F	3	45 ACE	SP	P			V			5/17/2067
2021	PO5665187571	KU	4	40 ACE	SP	CRE		ID, IP	TD			5/18/2067
2021	PO5726387885	KU	3	40 ACE	SP	CCA			V			5/19/2067
2021	PO5741988952	KU	3	45 ACE	SP	CCA		ED	T			5/20/2067
2021	PO5767490242	KU	4	40 ACE	SP	CCA			V			5/21/2067
2021	PO5768589521	KU	3	45 ACE	SP	CCA			V			5/22/2067
2021	PO5748288597	KU	3	45 ACE	SP	CCA			V			5/23/2067
2021	PO5708287933	KU	4	40 ACE	SP	CRE		ID	TD			5/24/2067
2021	PO2757094514	KU	7	30 KOP	SP	CRE			V			5/25/2067
2021	PO4094685973	LGE	4	35 ACE	SP	CCA			V			5/26/2067
2021	PO9036896765	KU	4	45 BRN	SP	CRE		ED, ID, RB	X	RP3		5/27/2067
2021	PO5483925627	KU	4	40 UNK	SP	CRE			B			5/28/2067
2021	PO4096485980	LGE	4	40 ACE	SP	CRE		ED, HH, ID	TD			5/29/2067
2021	PO5486625527	KU	3	45 UNK	SP	CCA			V			5/30/2067
2021	PO5490125395	KU	4	40 UNK	UN	CRE			V			5/31/2067
2021	PO5491525347	KU	4	40 UNK	SP	CRE		ED, ID	BX	RP3		6/1/2067
2021	PO5495725190	KU	4	40 UNK	SP	CRE			B			6/2/2067
2021	PO5493025290	KU	4	40 UNK	SP	CRE			B			6/3/2067
2021	PO5498325095	KU	4	40 UNK	SP	CRE			B			6/4/2067
2021	PO9024296618	KU	3	45 BRN	SP	CCA			V			6/5/2067
2021	PO1666897254	KU	3	40 BRN	SP	CRE		ED, ID, IP, MD	TD			6/6/2067

2021 PO9041696476	KU	5	35 BRN	SP	CCA		V	6/7/2067
2021 PO9033396310	KU	4	45 BRN	SP	CRE	ED,ID	BD	6/8/2067
2021 PO5500625010	KU	6	30 UNK	SP	CRE		T	6/9/2067
2021 PO5502624935	KU	6	30 UNK	SP	CRE		B	6/10/2067
2021 PO9045496282	F	5	30 KOP	SP	CRE		V	6/11/2067
2021 PO9054296224	F	5	30 KOP	SP	CRE		V	6/12/2067
2021 PO3994583342	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	6/13/2067
2021 PO3997483340	LGE	4	35 BRO	SP	CRE	ED,ID	TD	6/14/2067
2021 PO2237692115	KU	3	45 KOP	SP	CRE	ED,ID,IP	TD	6/15/2067
2021 PO4095785884	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	6/16/2067
2021 PO4096985883	LGE	4	35 ACE	SP	A	ED,HH,ID	BD	6/17/2067
2021 PO3527400336	KU	4	45 UNK	SP	CCA		V	6/18/2067
2021 PO3551300281	KU	3	45 UNK	SP	CCA		V	6/19/2067
2021 PO4164486314	LGE	4	40 BRO	SP	P		V	6/20/2067
2021 PO8657787322	F	4	40 BRO	SP	CCA		V	6/21/2067
2021 PO8685587709	F	4	40 BRO	SP	CCA		V	6/22/2067
2021 PO8665587485	F	4	40 BRO	SP	CRE		V	6/23/2067
2021 PO8700587936	F	4	40 BRO	SP	CRE		V	6/24/2067
2021 PO3568900241	KU	3	40 UNK	SP	CCA		V	6/25/2067
2021 PO8745888443	F	5	30 BRO	SP	A		V	6/26/2067
2021 PO8727488559	F	6	30 BRO	SP	CCA		V	6/27/2067
2021 PO8739488487	F	6	30 BRO	SP	CRE		V	6/28/2067
2021 PO8242784328	F	4	40 BRO	SP	CRE		V	6/29/2067
2021 PO8231784288	KU	5	35 BRO	SP	CCA		V	6/30/2067
2021 PO8218084576	F	4	40 BRO	SP	A		V	7/1/2067
2021 PO8165485709	KU	3	45 BRO	SP	CCA		V	7/2/2067
2021 PO8198484649	F	4	40 BRO	SP	A		V	7/3/2067
2021 PO8172784519	KU	3	45 BRO	SP	CCA		V	7/4/2067
2021 PO8178184727	F	4	40 BRO	SP	A		V	7/5/2067
2021 PO8230884409	F	4	40 BRO	SP	A		V	7/6/2067
2021 8230884409A	KU	6	30 BRO	SP	CCA		V	7/7/2067
2021 PO8753288802	KU	4	45 BRO	SP	CCA		V	7/8/2067
2021 PO4161486292	F	4	35 BRO	SP	CRE		V	7/9/2067
2021 PO8761689197	KU	4	45 BRO	SP	CCA		V	7/10/2067
2021 PO3665099923	KU	4	40 UNK	SP	CCA		V	7/11/2067
2021 PO3630400039	KU	3	50 UNK	SP	CCA		V	7/12/2067
2021 PO1207347256	KU	3	45 BRN	SP	CCA		V	7/13/2067
2021 PO8155984925	F	4	40 BRO	SP	A		V	7/14/2067
2021 PO8156084800	F	4	40 BRO	SP	A		V	7/15/2067
2021 PO8078485125	KU	3	45 BRO	SP	CCA		V	7/16/2067
2021 PO8111684959	KU	3	45 BRO	SP	CCA		V	7/17/2067
2021 PO8048586378	F	5	35 BRO	SP	CRE		V	7/18/2067
2021 PO8075086218	KU	4	40 BRO	SP	CCA		V	7/19/2067
2021 PO4190786273	LGE	4	35 BRO	SP	CRE		V	7/20/2067
2021 PO2607721023	KU	6	30 BRN	SP	CRE		V	7/21/2067
2021 PO2607321191	KU	5	35 BRN	SP	CRE		V	7/22/2067
2021 PO2589621208	KU	4	45 BRN	SP	CCA		V	7/23/2067
2021 PO0974947479	F	4	45 BRN	SP	P		V	7/24/2067
2021 PO0986447623	F	4	45 BRN	SP	P		V	7/25/2067
2021 PO0854848349	F	4	40 BRN	SP	CRE		V	7/26/2067
2021 PO2565415271	F	4	45 BRN	SP	CRE		V	7/27/2067
2021 PO0976647684	F	5	40 BRN	SP	P		V	7/28/2067
2021 PO0958147711	F	4	40 BRN	SP	CRE		V	7/29/2067
2021 PO4192986278	LGE	3	45 BRO	SP	CCA		V	7/30/2067

2021 PO0577850511	F	4	40 BRO	SP	CRE		V	7/31/2067	
2021 PO0565150677	F	4	40 BRO	SP	A		V	8/1/2067	
2021 PO0589750583	KU	4	40 BRO	SP	CCA		V	8/2/2067	
2021 PO8642989098	KU	4	45 BRO	SP	S		V	8/3/2067	
2021 PO0541150994	F	6	35 BRO	SP	CRE		V	8/4/2067	
2021 PO1377645130	KU	6	30 BRN	SP	CRE		V	8/5/2067	
2021 PO2678715376	KU	4	40 BRN	SP	CRE		V	8/6/2067	
2021 PO2650115260	KU	4	40 BRN	SP	CRE		V	8/7/2067	
2021 PO2637915149	KU	3	45 BRN	SP	CCA		V	8/8/2067	
2021 PO2603323286	KU	6	30 BRN	SP	CRE		V	8/9/2067	
2021 PO2606523414	KU	5	35 BRN	SP	CRE		V	8/10/2067	
2021 PO2604723549	KU	6	30 BRN	SP	CRE		V	8/11/2067	
2021 PO2557923329	KU	4	40 BRN	SP	CRE		V	8/12/2067	
2021 PO8084186101	F	4	40 BRO	SP	CRE		V	8/13/2067	
2021 PO8074186103	F	4	40 BRO	SP	CRE		V	8/14/2067	
2021 PO8103185518	F	4	40 BRO	SP	CRE		V	8/15/2067	
2021 PO8117585782	F	4	40 BRO	SP	CRE		V	8/16/2067	
2021 PO8141385198	F	4	40 BRO	SP	CRE		V	8/17/2067	
2021 PO4160586315	LGE	4	40 BRO	SP	CCA		V	8/18/2067	
2021 PO1044247510	F	4	40 BRN	SP	P		V	8/19/2067	
2021 PO4162086305	F	4	40 BRO	SP	A		V	8/20/2067	
2021 PO1061547540	F	4	45 BRN	SP	P		V	8/21/2067	
2021 PO1085347580	F	7	20 BRN	SP	CRE		V	8/22/2067	
2021 PO1005554815	KU	6	30 BRO	SP	CCA		V	8/23/2067	
2021 PO8146685413	F	4	40 BRO	SP	CRE		V	8/24/2067	
2021 PO8117285464	F	4	40 BRO	SP	CRE		V	8/25/2067	
2021 PO1150147371	F	4	40 BRN	SP	CCA		V	8/26/2067	
2021 PO1172147366	KU	5	35 BRN	SP	CCA		V	8/27/2067	
2021 PO4165986299	LGE	4	40 BRO	SP	A	ED,HH,IP,RR	TX	RR	8/28/2067
2021 PO3595500390	KU	5	35 UNK	SP	CRE	ID	ID	TD	8/29/2067
2021 PO3593000711	KU	4	40 UNK	SP	CRE	ID,IP	ID,IP	TD	8/30/2067
2021 PO3626100558	KU	5	35 UNK	SP	CRE	ID,IP	ID,IP	TD	8/31/2067
2021 PO4157986334	LGE	3	45 BRO	SP	A	ED,ID	ED,ID	TD	9/1/2067
2021 PO0486251674	KU	6	30 BRO	SP	CRE	ED,ID	ED,ID	TD	9/2/2067
2021 PO0497751531	KU	5	30 BRO	SP	CRE	ED,ID	ED,ID	TD	9/3/2067
2021 PO3463400476	KU	4	40 UNK	SP	CRE	ID,IP	ID,IP	TD	9/4/2067
2021 PO3465200067	KU	4	40 UNK	SP	CRE	ID	ID	TD	9/5/2067
2021 PO4159186324	LGE	3	45 BRO	SP	CRE	ED,ID	ED,ID	TD	9/6/2067
2021 PO0869848422	KU	4	40 BRN	SP	CRE	ED,ID,IP	ED,ID,IP	TD	9/7/2067
2021 PO4192786277	LGE	3	45 BRO	SP	CRE	ED,ID,IP	ED,ID,IP	TD	9/8/2067
2021 PO0967355511	KU	5	35 BRO	SP	CRE	ED,ID	ED,ID	TD	9/9/2067
2021 PO4166986342	LGE	4	35 BRO	SP	A	ED,ID	ED,ID	TD	9/10/2067
2021 PO4167786331	LGE	4	40 BRO	SP	CRE	ED,ID	ED,ID	TD	9/11/2067
2021 PO0964855893	KU	5	35 BRO	SP	CRE	ED,ID	ED,ID	TD	9/12/2067
2021 PO4166986315	LGE	4	40 BRO	SP	A	ED,ID	ED,ID	TD	9/13/2067
2021 PO7971581397	KU	4	45 BRO	SP	CRE	ED,ID	ED,ID	TD	9/14/2067
2021 PO0573650473	KU	4	40 BRO	SP	CRE	ED,ID	ED,ID	TD	9/15/2067
2021 PO0564550621	KU	4	45 BRO	SP	CRE	ED,ID	ED,ID	TD	9/16/2067
2021 PO8136690187	KU	4	40 BRO	SP	CRE	ED,ID	ED,ID	TD	9/17/2067
2021 PO8158590759	KU	4	40 BRO	SP	CRE	ED,ID	ED,ID	TD	9/18/2067
2021 PO8155091006	KU	4	45 BRO	SP	CRE	ED,ID	ED,ID	TD	9/19/2067
2021 PO0545650784	KU	4	40 BRO	SP	CRE	ED,ID	ED,ID	TD	9/20/2067
2021 PO0553050855	KU	4	35 BRO	SP	CCA	ED,ID	ED,ID	TD	9/21/2067
2021 PO0547451089	KU	6	30 BRO	SP	CRE	ED,ID	ED,ID	TD	9/22/2067



2021 PO4164986323	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		9/23/2067
2021 PO0991155100	KU	5	35 BRO	SP	CRE	ED,ID	TD		9/24/2067
2021 PO1038154680A									
PO1038154680A	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO8083885626	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO8077085953	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0973955403	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO8141185149	KU	3	45 BRO	SP	CCA	ED,ID	BX	RP3	00:00.0
2021 PO8133990709	KU	4	40 BRO	SP	CRE	ED,EP,HH,ID,IP	BX	RP3	00:00.0
2021 PO8635489137	KU	3	50 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO8664689397	KU	5	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4193186260	LGE	4	35 BRO	SP	CRE	ID	BD		00:00.0
2021 PO0497951600	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0514551426	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0533451156	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO8080386381	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PV9045074948	LGE	4	35 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4193786281	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4191586264	LGE	4	35 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4191886267	LGE	3	45 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO8118190687	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4733998150	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO1289145957	KU	4	45 BRN	SP	CRE	ED,EP,RB	X	PX	00:00.0
2021 PO4821303737	KU	4	40 BRN	SP	CRE	ED,HH,ID	X	PX	00:00.0
2021 PO6882816425	KU	4	40 ACV	SP	CRE	ED,HH,ID,MD,RB	X	RP1	00:00.0
2021 PO2588308212	KU	3	45 UNK	SP	CRE	ED,HH,ID	X	RP3	00:00.0
2021 PO1019347525	KU	5	35 BRN	SP	CRE	ED,ID,RB,SRS	X	RP3	00:00.0
2021 PO4864903941	KU	5	40 BRN	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021 PO4114585708	LGE	2	45 BRN	SP	CRE	ED,HH,ID	X	RP1	00:00.0
2021 PO4199086326	F	3	55 BRO	SP	CRE	HH,ID,RB	VX	RP1	00:00.0
2021 PO0577849507	KU	5	35 BRO	SP	CRE	ED	VX	RP3	00:00.0
2021 PO4118985983	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4119685992	F	4	35 BRN	SP	CCA		V		00:00.0
2021 8802590373A	KU	6	30 BRO	SP	S		V		00:00.0
2021 PO1205146920	KU	3	45 BRN	SP	CRE		V		00:00.0
2021 PO4557905856A	KU	2	55 BRN	SP	CCA		V		00:00.0
2021 PO4520805654	KU	5	35 BRN	SP	CRE		V		00:00.0
2021 PO4200086336	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO5222405161	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5224504845	F	7	30E BRN	SP	CRE		V		00:00.0
2021 PO4159286323	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4159386323	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO5205405168	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO5210005212	KU	3	40 BRN	SP	CRE		V		00:00.0
2021 PO5231105204	KU	3	40 BRN	SP	CRE		V		00:00.0
2021 PO0754952231	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO0778052375	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO0738752112	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO0681551968	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO0676251832	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO0616951307	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO0621151092	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO0661651460	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO0647151087	KU	4	40 BRO	SP	CCA		V		00:00.0

2021 PO0637551096	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO2976905650	KU	3	40 UNK	SP	CCA	V	00:00.0
2021 PO2981805438	KU	3	40 UNK	SP	CCA	V	00:00.0
2021 PO3003405240	KU	3	40 UNK	SP	CCA	V	00:00.0
2021 PO3823306969	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4114085908	LGE	6	25 BRN	SP	CRE	V	00:00.0
2021 PO4115285906	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO1261346394	F	5	35 BRN	SP	P	V	00:00.0
2021 PO4007506349	KU	3	45 BRN	SP	CRE	V	00:00.0
2021 PO6808216654	KU	4	40 ACW	SP	S	V	00:00.0
2021 PO4564610755	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4117785959-B	KU	5	35E BRN	SP	P	V	00:00.0
2021 PO4117785959	F	4	30 BRN	SP	P	V	00:00.0
2021 PO8801689859	KU	6	30 BRO	SP	CCA	V	00:00.0
2021 PO4115585916	F	2	55 BRN	SP	CCA	V	00:00.0
2021 PO4085706751	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4056106803	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO6728916713	KU	4	40 ACW	SP	S	V	00:00.0
2021 PO8669386603	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO8679086533	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4575610422	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4116185930	F	4	35 BRN	SP	CRE	V	00:00.0
2021 PO4116785943	F	4	30 BRN	SP	CRE	V	00:00.0
2021 PO4838903661	KU	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4236706174A	KU	5	35 BRN	SP	CCA	V	00:00.0
2021 PO1235746577	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO6858916821	KU	4	40 ACW	SP	S	V	00:00.0
2021 PO6839017200	KU	5	40 ACW	SP	S	V	00:00.0
2021 PO7096618859	KU	4	40 ACW	SP	S	V	00:00.0
2021 PO4417405528A	KU	5	35 BRN	SP	CCA	V	00:00.0
2021 PO4433005497A	KU	5	35 BRN	SP	CCA	V	00:00.0
2021 PO4121086018	F	4	35 BRN	SP	P	V	00:00.0
2021 PO4121486029	F	4	35 BRN	SP	P	V	00:00.0
2021 PO4122286044	F	4	35 BRN	SP	P	V	00:00.0
2021 PO4125386103	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO8395372933	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4126286120	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4128286156	F	4	35 BRN	SP	CRE	V	00:00.0
2021 PO4109685836	LGE	4	35 BRN	SP	CRE	V	00:00.0
2021 PO4111185832	F	3	50 BRN	SP	CCA	V	00:00.0
2021 PO4111785841	F	1	55 BRN	SP	CCA	V	00:00.0
2021 PO4112385853	F	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4112985864	F	3	45 BRN	SP	P	V	00:00.0
2021 PO4840304013	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4823604064	KU	3	40 BRN	SP	CCA	V	00:00.0
2021 PO4113385872	F	1	55 BRN	SP	CCA	V	00:00.0
2021 PO3738407120	KU	5	35 BRN	SP	CCA	V	00:00.0
2021 PO4158686246	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO1293845988	F	5	35 BRN	SP	A	V	00:00.0
2021 PO0753147342	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4625510716	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO4650211191	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO4640611111	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4635110968	F	4	40 XXX	SP	CRE	V	00:00.0

2021 PO4198586321	F	4	30 BRO	SP	A	V	00:00.0
2021 PO4198186317	LGE	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4113785881	F	3	50 BRN	SP	CRE	V	00:00.0
2021 PO4114285889	F	1	60 BRN	SP	CCA	V	00:00.0
2021 PO6738416451	KU	4	40 ACW	SP	S	V	00:00.0
2021 PO4136886327	F	4	35 BRN	SP	CRE	V	00:00.0
2021 PO4138186369	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PV4138786387	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4137486370	LGE	4	30 BRN	SP	CCA	V	00:00.0
2021 PO0541350048	KU	4	40 BRO	SP	CRE	V	00:00.0
2021 PO0515750144	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO3966606689	KU	4	40 KOP	SP	CRE	V	00:00.0
2021 PO4162886316	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8797790432	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4135986307	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021 PO2500904961	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO0628449734	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO0613650063	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO0617349191	KU	6	30 BRO	SP	CRE	V	00:00.0
2021 PO0885746028	F	4	45 BRN	SP	A	V	00:00.0
2021 PO4110485824	F	3	45E BRN	SP	P	V	00:00.0
2021 PO8416387210	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8151489569	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8165789801	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4195286288	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4195886294	F	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4134586275	F	4	30 BRN	SP	CRE	V	00:00.0
2021 PO4134986283	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4196286298	F	4	30 BRO	SP	A	V	00:00.0
2021 PO4196986304	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4197586311	F	3	55 BRO	SP	CRE	V	00:00.0
2021 PO4568911079	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO8522588360	KU	2	55 BRO	SP	CCA	V	00:00.0
2021 PO8508488258	KU	3	55 BRO	SP	CRE	V	00:00.0
2021 PO8502288269	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO8505288137	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4508810487	KU	5	35 BRN	SP	CCA	V	00:00.0
2021 PO4547710302	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4541610332	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4530510361	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO0856445335	F	3	40 BRN	SP	CRE	V	00:00.0
2021 PO0876445800	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO0866645577	F	3	40 BRN	SP	P	V	00:00.0
2021 PO4124006435	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO0893146216	KU	2	55 BRN	SP	CCA	V	00:00.0
2021 PO4565710221	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4121505951	KU	3	45 BRO	SP	CRE	V	00:00.0
2021 PO4123806231	KU	3	45 BRO	SP	CRE	V	00:00.0
2021 PO4120705681	KU	3	45 KOP	SP	CCA	V	00:00.0
2021 PO4047985731	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4050685724	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4049385731	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4049485748	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4049485755	F	4	35 BRO	SP	CRE	V	00:00.0

2021 PO4050785755	F	4	45 BRO	SP	P	V	00:00.0
2021 PO4051685755	F	4	30 BRO	SP	CCA	V	00:00.0
2021 PO4631712945	F	4	40 KOP	SP	P	V	00:00.0
2021 PO4639113165	KU	5	35 KOP	SP	S	V	00:00.0
2021 PO4662613130	KU	5	35 KOP	SP	S	V	00:00.0
2021 PO5257211085	KU	ST	80 BRO	ST	CCA	V	00:00.0
2021 PO4665911739A	KU	4	40 KOP	SP	S	V	00:00.0
2021 PO4045885827	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4058585734	LGE	UNK	25 BRO	UN	CRE	V	00:00.0
2021 PO5312710887	KU	1	65 BRO	ST	CCA	V	00:00.0
2021 PO5316810781	KU	7	35 BRO	SP	CCA	V	00:00.0
2021 PO4609112129	F	4	40 KOP	SP	P	V	00:00.0
2021 PO4614712321	F	4	40 KOP	SP	P	V	00:00.0
2021 PO4611412211	F	4	40 KOP	SP	P	V	00:00.0
2021 PO4684811966	KU	4	40 KOP	SP	S	V	00:00.0
2021 PO4665911739	KU	3	45 KOP	SP	S	V	00:00.0
2021 PO5286310987	KU	1	70 BRO	SP	CRE	V	00:00.0
2021 PO7590717796	KU	3	45 KOP	SP	S	V	00:00.0
2021 PO5289310981	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO5307610743	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4045486322	LGE	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4044786333	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO5160525868	KU	3	45 UNK	SP	CRE	B	00:00.0
2021 PO5159725886	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO4013586404	LGE	4	45 ACE	SP	CRE	V	00:00.0
2021 PO4012786390	LGE	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4011386364	LGE	4	40 ACE	SP	A	V	00:00.0
2021 PO4010586350	LGE	4	45 ACE	SP	A	V	00:00.0
2021 PO4010786344	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4014486323	F	4	40 ACE	SP	P	V	00:00.0
2021 PO5184825571	KU	4	40 UNK	SP	CRE	B	00:00.0
2021 PO5196025935	KU	5	35 UNK	ST	CCA	V	00:00.0
2021 PO4044186330	LGE	UNK	60 ACE	SP	CRE	V	00:00.0
2021 PO4042886338	LGE	UNK	60 ACE	SP	CRE	V	00:00.0
2021 PO5087836520	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO5054937407	KU	3	40 BRO	SP	CCA	V	00:00.0
2021 PO5213637279	KU	1	55 BRO	SP	CCA	V	00:00.0
2021 5213637279A	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO5179325886	KU	4	40 BRN	SP	CRE	B	00:00.0
2021 PO5182125728	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4046786074	F	4	40 KOP	SP	P	V	00:00.0
2021 PO4046786080	F	4	40 KOP	SP	P	V	00:00.0
2021 PO4041186338	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4041586345	LGE	UNK	60 ACE	SP	CRE	V	00:00.0
2021 PO4040286353	LGE	UNK	60 ACE	SP	CRE	V	00:00.0
2021 PO4040286340	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO4039086362	LGE	UNK	65 ACE	SP	CRE	V	00:00.0
2021 PO4046786096	F	3	45 KOP	SP	CCA	V	00:00.0
2021 PO4046786106	F	4	40 KOP	SP	P	V	00:00.0
2021 PO5192025735	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO5203625751	KU	5	30 BRN	SP	CCA	V	00:00.0
2021 PO5203125834	KU	3	45 BRN	SP	CRE	B	00:00.0
2021 PO4042986080	F	4	40 KOP	SP	A	V	00:00.0
2021 PO4060385672	F	4	40 BRO	SP	CRE	V	00:00.0

2021 PO4060385656	F	3	50 BRO	SP	CCA	V	00:00:00
2021 PO4060885636	F	5	35 BRO	SP	P	V	00:00:00
2021 PO5016834490	KU	1	65 BRO	SP	CCA	B	00:00:00
2021 PO7510875142	LGE	4	40 ACE	SP	CCA	V	00:00:00
2021 PO4037086374	LGE	UNK	85 ACE	SP	CRE	V	00:00:00
2021 PO7533274941	LGE	4	30 ACE	SP	CCA	V	00:00:00
2021 PO7539274907	LGE	4	30 ACE	SP	CCA	V	00:00:00
2021 PO4041086047	F	4	40 KOP	SP	P	V	00:00:00
2021 PO4040586038	F	4	35 KOP	SP	A	V	00:00:00
2021 PO4040086029	F	4	40 KOP	SP	A	V	00:00:00
2021 PO5265625921	F	4	40 BRN	SP	CRE	V	00:00:00
2021 PO4022486277	F	3	45 ACE	SP	CRE	V	00:00:00
2021 PO4022986269	LGE	1	65 ACE	SP	CRE	V	00:00:00
2021 PO4023486272	F	4	40 ACE	SP	P	V	00:00:00
2021 PO4023886269	F	4	40 ACE	SP	P	V	00:00:00
2021 PO4025086261	F	4	30 ACE	SP	CCA	V	00:00:00
2021 PO4024886264	F	3	50 ACE	SP	CCA	V	00:00:00
2021 PO4026486260	F	3	45 ACE	SP	CCA	V	00:00:00
2021 PO4018286301	F	4	40 ACE	SP	A	V	00:00:00
2021 PO7323574617	F	4	35 ACE	SP	A	V	00:00:00
2021 PO4019586294	F	4	40 ACE	SP	A	V	00:00:00
2021 PO4021086286	F	4	40 ACE	SP	CRE	V	00:00:00
2021 PO4046486417	F	4	40 ACE	SP	CRE	V	00:00:00
2021 PO4045586408	F	4	40 ACE	SP	CRE	V	00:00:00
2021 PO4022586226	LGE	4	35 ACE	SP	CCA	V	00:00:00
2021 PO7345573988	LGE	5	35 ACE	SP	CCA	V	00:00:00
2021 PO7342374122	LGE	5	35 ACE	SP	CCA	V	00:00:00
2021 PO5268725659	KU	5	35 BRN	SP	CRE	B	00:00:00
2021 PO4026086254	LGE	4	35 ACE	SP	CCA	V	00:00:00
2021 PO4043786393	F	4	40 ACE	SP	CRE	V	00:00:00
2021 PO4043886384	LGE	4	30 ACE	SP	CRE	V	00:00:00
2021 PO4042286386	F	4	40 ACE	SP	CRE	V	00:00:00
2021 PO4039486012	LGE	3	45 KOP	SP	CCA	V	00:00:00
2021 PO4050386486	LGE	3	50 ACE	SP	CRE	V	00:00:00
2021 PO4049486470	LGE	UNK	45 ACE	SP	CRE	V	00:00:00
2021 PO4048986473	LGE	UNK	80 ACE	SP	CRE	V	00:00:00
2021 PO4047386458	LGE	UNK	75 ACE	SP	CRE	V	00:00:00
2021 PO4045886443	LGE	UNK	70 ACE	SP	CRE	V	00:00:00
2021 PO4044786424	LGE	UNK	45 ACE	SP	CRE	V	00:00:00
2021 PO4044286428	LGE	UNK	70 ACE	SP	CRE	V	00:00:00
2021 PO4042286411	LGE	UNK	70 ACE	SP	CRE	V	00:00:00
2021 PO4040586398	LGE	UNK	80 ACE	SP	CRE	V	00:00:00
2021 PO4038786386	LGE	UNK	80 ACE	SP	CRE	V	00:00:00
2021 PO4038785994	LGE	4	30 KOP	SP	CCA	V	00:00:00
2021 PO4060985550	F	6	25 BRO	SP	CRE	V	00:00:00
2021 PO4059885567	F	3	45 BRO	SP	CCA	V	00:00:00
2021 PO4059585537	F	4	40 BRO	SP	CCA	V	00:00:00
2021 PO4059685551	F	3	45 BRO	SP	CCA	V	00:00:00
2021 PO4059385524	F	4	40 BRO	SP	CRE	V	00:00:00
2021 PO4059185511	LGE	4	35 BRO	SP	A	V	00:00:00
2021 PO4058585547	F	4	30 BRO	SP	CRE	V	00:00:00
2021 PO4058485551	F	4	40 BRO	SP	CRE	V	00:00:00
2021 PO4057085548	F	4	30 BRO	SP	P	V	00:00:00
2021 PO4057085552	F	3	45 BRO	SP	CCA	V	00:00:00

2021 PO4055885548	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4055885553	F	4	40 BRO	SP	P	V	00:00.0
2021 PO4054585549	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4054685553	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4053385549	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4053485554	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4052185550	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4052285554	F	4	40 BRO	SP	P	V	00:00.0
2021 PO4050985551	F	5	35 BRO	SP	CRE	V	00:00.0
2021 PO4038885996	F	UNK	25 KOP	SP	P	V	00:00.0
2021 PO5239024989	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4043186409	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4044486398	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5241825158	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO4046186389	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4047186383	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5251025569	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5252225634	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO5236625612	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO5220525590	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO4052186440	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4053186435	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4052486426	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4051986415	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4051286406	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4050286397	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4049486396	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5499015245	KU	7	35 BRO	SP	CCA	V	00:00.0
2021 PO5223225329	KU	3	50 BRN	SP	CCA	V	00:00.0
2021 PO4025286210	LGE	4	40 ACE	SP	A	V	00:00.0
2021 PO4028786207	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4027486214	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4038485997	F	6	30 KOP	SP	P	V	00:00.0
2021 PO4025886209	LGE	6	25 ACE	SP	CRE	V	00:00.0
2021 PO4027886256	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4054085719	F	4	40 BRO	SP	P	V	00:00.0
2021 PO4001686394	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4003086387	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4006586367	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4007986359	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4009286352	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4005686372	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4004286380	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4002286391	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4010386347	F	4	40 ACE	SP	A	V	00:00.0
2021 PO5232211179	KU	ST	80 BRO	ST	CCA	V	00:00.0
2021 PO5217332827	KU	2	60 KOP	SP	CCA	V	00:00.0
2021 PO5220832516	KU	2	50 KOP	SP	CCA	V	00:00.0
2021 PO5222832541	KU	2	50 KOP	SP	CCA	V	00:00.0
2021 PO5216032732	KU	3	45 KOP	SP	CCA	V	00:00.0
2021 PO7559215610	KU	4	40 KOP	SP	S	V	00:00.0
2021 PO7583516577	KU	3	45 KOP	SP	S	V	00:00.0
2021 PO7566215902	KU	3	45 KOP	SP	S	V	00:00.0
2021 PO7574816236	KU	3	45 KOP	SP	S	V	00:00.0

2021	PO5223111242	F	3	40 BRO	SP	CCA		V	00:00.0	
2021	PO5226525987	KU	3	45 UNK	SP	CRE		B	00:00.0	
2021	PO5178733131	KU	3	55 BRN	SP	CCA		V	00:00.0	
2021	PO5193733012	KU	4	45 KOP	SP	CCA		V	00:00.0	
2021	PO5024934905	KU	3	45 BRO	SP	CCA		B	00:00.0	
2021	PO5219625854	F	4	40 UNK	SP	CRE		V	00:00.0	
2021	PO5010734589	KU	3	45 BRO	SP	CCA		B	00:00.0	
2021	5010734589A	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4054085706	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO4053985697	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO4053785651	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO4053285639	F	4	30 BRO	SP	P		V	00:00.0	
2021	PO4053685634	F	4	40 BRO	SP	P		V	00:00.0	
2021	PO4974734825	KU	2	50 KOP	SP	CCA		B	00:00.0	
2021	PO7610917660	KU	4	40 KOP	SP	CRE		V	00:00.0	
2021	PO4039186107	LGE	3	45 KOP	SP	CCA		V	00:00.0	
2021	PO4627912808	F	4	40 KOP	SP	P		V	00:00.0	
2021	PO4965234897	KU	2	55 KOP	SP	CRE		B	00:00.0	
2021	PO5209833280	KU	6	30 BRN	SP	CRE		V	00:00.0	
2021	PO4955834971	KU	2	55 KOP	SP	CCA		B	00:00.0	
2021	PO5183724929	KU	4	40 UNK	SP	CRE		B	00:00.0	
2021	PO4019486012	LGE	4	40 KOP	SP	A		V	00:00.0	
2021	PO4998234250	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021	PO4048486437	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO4049486445	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO4050486455	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO5271025837	KU	6	30 BRN	SP	CRE		B	00:00.0	
2021	PO4047486426	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO5168433342	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO5007334358	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO5348011468	KU	3	45 BRO	SP	CRE	ED	TD	00:00.0	
2021	PO4989834146	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO4980133948	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO5193836665	KU	3	45 UNK	SP	CRE	ED,ID	BX	RP1	00:00.0
2021	PO5109537471	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0	
2021	PO5340411500	KU	6	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4038786024	LGE	6	25 KOP	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO5186225148	KU	4	40 UNK	SP	CRE		T	00:00.0	
2021	PO4037986114	LGE	3	45 KOP	SP	A	ED,ID	TD	00:00.0	
2021	PO4617112836	KU	5	35 KOP	SP	CRE	ED,ID	BD	00:00.0	
2021	PO5213433170	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021	PO5225533076	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO5243333277	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO4036886019	LGE	4	30 KOP	SP	P	ED,ID	BD	00:00.0	
2021	PO4038886103	LGE	5	25 KOP	SP	A	ED,ID,MD	TD	00:00.0	
2021	PO5200833267	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021	PO5188825364	KU	5	35 UNK	SP	CRE		T	00:00.0	
2021	PO5180025420	KU	4	40 UNK	SP	CRE		T	00:00.0	
2021	PO7590816885	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO5019334511	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0	
2021	PO5204911282	KU	1	70 BRO	SP	CRE	ID	TD	00:00.0	
2021	PO5193511326	KU	4	40 BRO	SP	CRE	ID,SRS	TD	00:00.0	
2021	PO5230925895	F	4	40 UNK	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021	PO5209832885	KU	2	60 KOP	SP	CRE	ID	TD	00:00.0	

2021	PO5208411221	F	5	40 BRO	SP	P	ID, RB	BX	PX	00:00.0
2021	PO5237532984	KU	4	40 KOP	SP	CRE	ID, IP	X	RP1	00:00.0
2021	PO5223133491	KU	6	30 BRN	SP	CRE	ID	TD		00:00.0
2021	PO5215133519	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO4053285736	LGE	4	40 BRO	SP	P	ED, ID, RB	TX	RR	00:00.0
2021	PO4058985664	F	4	40 BRO	SP	CRE	HH, RB	VX	RP2	00:00.0
2021	PO4057485664	F	4	40 BRO	SP	CRE	ED, EP, RB	VX	RP3	00:00.0
2021	PO4028086250	LGE	4	45 ACE	SP	A	ID	TD		00:00.0
2021	PO5351011553	KU	4	40 BRO	SP	CRE	ED	TD		00:00.0
2021	PO4026286215	LGE	4	35 ACE	SP	P	ID	BD		00:00.0
2021	PO4026486219	LGE	4	45 ACE	SP	A	ED, ID	TD		00:00.0
2021	PO4022886212a1	KU	5	40 ACE	SP	A	ED, ID	BD		00:00.0
2021	PO4024086232	LGE	4	40 ACE	SP	A	ED, ID	BD		00:00.0
2021	PO4024986227	LGE	4	40 ACE	SP	P	ID	BD		00:00.0
2021	PO5251125029	KU	4	40 BRN	SP	CRE		T		00:00.0
2021	PO4041386004	LGE	4	35 KOP	SP	CCA		T		00:00.0
2021	PO4039086006	LGE	4	40 KOP	SP	A	ED, ID	TD		00:00.0
2021	PO4022886212	LGE	4	40 ACE	SP	A	ED, ID	BD		00:00.0
2021	PO4709012527	KU	4	40 KOP	SP	CRE	ED, ID	TD		00:00.0
2021	PO4716812673	KU	4	40 KOP	SP	CRE	ED, ID	TD		00:00.0
2021	PO4026486253	LGE	4	30 ACE	SP	A	ED, ID, IP	BD		00:00.0
2021	PO4024086284	LGE	4	40 ACE	SP	P	ID	TD		00:00.0
2021	PO4025586257	LGE	4	35 ACE	SP	P	ED, ID	BD		00:00.0
2021	PO4024686244	LGE	4	35 ACE	SP	P	ID	BD		00:00.0
2021	PO5230537907	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021	PO4060485679	LGE	2	65 BRO	SP	CRE	ED, ID	TD		00:00.0
2021	PO4687112943	KU	5	35 KOP	SP	CRE	ED, ID	TD		00:00.0
2021	PO4679312756	KU	5	35 KOP	SP	CRE	ED, ID	TD		00:00.0
2021	PO4037786370	LGE	UNK	45 ACE	SP	CRE	ED, ID	TD		00:00.0
2021	PO4043586070	LGE	4	35 KOP	SP	A	ED, ID	TD		00:00.0
2021	PO5175333468	KU	5	35 BRN	SP	CRE	ID	BD		00:00.0
2021	PO5180933617	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO4930188641	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4929288639	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4768989315	LGE	4	40 ACE	SP	P	ED, ID	BD		00:00.0
2021	PO4928088636	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4762206128	KU	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4753406073	KU	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4774089313	LGE	4	35 ACE	SP	P	ED, ID	TD		00:00.0
2021	PO4775489307	F	1	65 ACE	SP	CCA		V		00:00.0
2021	PO4774189299	F	2	55 ACE	SP	CCA		V		00:00.0
2021	PO4772789291	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021	PO4812306016	LGE	4	35 ACE	SP	P	ED, ID, IP	TX	RR	00:00.0
2021	PO6765020189	ODP	6	30 UNK	SP	CRE	ED, ID	TD		00:00.0
2021	PO4931088644	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4931988647	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO9621860154	F	5	35 OTH	SP	CRE		V		00:00.0
2021	PO9677360604	KU	5	35 OTH	SP	CRE	ED, ID, SRS	TD		00:00.0
2021	PO9659060250	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO6269198102	KU	4	35 XXX	SP	CCA		V		00:00.0
2021	PO6337898009	F	4	45 XXX	SP	P		V		00:00.0
2021	PO6454399067	KU	4	40 XXX	SP	CRE	ED, ID	BD		00:00.0
2021	PO6514198958	F	3	40 XXX	SP	P		V		00:00.0
2021	PO6501798969	F	3	40 XXX	SP	P		V		00:00.0



2021	PO6478498992	KU	3	40 XXX	SP	P			V			00:00.0	
2021	PO6491199027	F	4	40 XXX	SP	P			V			00:00.0	
2021	PO6489398981	F	4	40 XXX	SP	CRE		ED,HH,ID	BX		PX	00:00.0	
2021	PO4361399808	F	4	40 BRN	SP	CRE			V			00:00.0	
2021	PO4350599853	F	4	40 BRN	SP	CRE			V			00:00.0	
2021	PO4340899894	F	4	40 BRN	SP	CRE			V			00:00.0	
2021	PO4334399921	F	4	40 BRN	SP	CRE			V			00:00.0	
2021	PO4635604117	KU	6	30 BRN	SP	CRE			V			00:00.0	
2021	PO4931088577	LGE	4	40 BRO	SP	CCA			V			00:00.0	
2021	PO4532304798	F	4	40 BRN	SP	CRE		HH,ID,IP,RB	BX		RP2	00:00.0	
2021	PO4326104545	F	4	40 BRN	SP	CRE			V			00:00.0	
2021	PO4672803634	F	4	40 BRN	SP	CRE			V			00:00.0	
2021	PO4678103753	F	2	40 BRN	SP	CRE			V			00:00.0	
2021	PO4936388489	LGE	4	30 BRO	ST	CCA			V			00:00.0	
2021	PO6691219237	ODP	4	40 BRO	SP	CRE		ED,ID,IP			TD	00:00.0	
2021	PO6741919183	ODP	4	45 BRO	SP	CCA			V			00:00.0	
2021	PO6715119285	ODP	4	40 BRO	SP	CRE		ED,ID			TD	00:00.0	
2021	PO6597120834	ODP	4	40 BRO	SP	CCA			V			00:00.0	
2021	PO5683716816	ODP	3	55 BRN	SP	CCA			V			00:00.0	
2021	PO5711416991	ODP	3	45 BRN	SP	CCA			V			00:00.0	
2021	PO5868217468	ODP	3	45 BRN	SP	CCA			V			00:00.0	
2021	PO5899718003	ODP	6	30 BRN	SP	CRE		ED,ID,IP			TD	00:00.0	
2021	PO6624920922	ODP	4	40 UNK	SP	CRE		ED,ID			TD	00:00.0	
2021	PO6639720945	ODP	5	35 BRO	SP	CRE		ED,ID,IP			TD	00:00.0	
2021	PO5899718003a	ODP	4	35 BRN	SP	CCA			V			00:00.0	
2021	PO4881705412	LGE	1	50 ACE	SP	CCA			V			00:00.0	
2021	PO4772289181	LGE	4	30 ACE	SP	CCA		ED			T	00:00.0	
2021	PO4779089116	LGE	4	30 ACE	SP	CCA			V			00:00.0	
2021	PO5895817902	ODP	4	40 BRN	SP	CRE		ED,ID,IP			TD	00:00.0	
2021	PO6658220959	ODP	3	45 BRO	SP	CCA			V			00:00.0	
2021	PO6672220312	ODP	4	40 UNK	SP	CRE		ED,ID			TD	00:00.0	
2021	PO0533835917	ODP	5	35 BRN	SP	CRE		ID			TD	00:00.0	
2021	PO0513435782	ODP	4	45 BRN	SP	CRE		ID			TD	00:00.0	
2021	PO0541835826	ODP	5	35 BRN	SP	CRE		ID			TD	00:00.0	
2021	PO5900817899	ODP	4	35 BRN	SP	CRE		ED,ID,IP			TD	00:00.0	
2021	PO6672720119	ODP	4	40 UNK	SP	CRE		ED,ID,IP			TD	00:00.0	
2021	PO6661920118	ODP	5	30 BRO	SP	CRE			V			00:00.0	
2021	PO6672419964	ODP	4	45 BRO	SP	CCA		ED,ID			TD	00:00.0	
2021	PO4930988583	LGE	5	25 BRO	SP	CCA			V			00:00.0	
2021	PO4779589122	LGE	4	40 ACE	SP	CCA			V			00:00.0	
2021	PO4779989126	LGE	4	30 ACE	SP	CRE		ED,HH,ID,RB			BX	RP1	00:00.0
2021	PO5884018011	ODP	5	35 BRN	SP	CRE		ED,ID,RB			X	RP1	00:00.0
2021	PO4934488559	LGE	4	40 BRO	SP	A		ID,IP			BD		00:00.0
2021	PO6756719983	ODP	5	35 ACW	SP	CRE		ED,ID			TD		00:00.0
2021	PO0508035848	ODP	3	45 BRN	SP	CRE		ID			TD		00:00.0
2021	PO0542836002	ODP	4	40 BRN	SP	CRE		ID			TD		00:00.0
2021	PO5858417960	F	4	40 BRN	SP	CRE		ED,ID			V		00:00.0
2021	PO5862117836	ODP	5	35 BRN	SP	CRE		ED,ID,RB			X	RP1	00:00.0
2021	PO4933588586	LGE	4	40 BRO	SP	CRE		ED,ID,IP			TD		00:00.0
2021	PO4932888583	LGE	3	45 BRO	SP	A		ED,ID,IP			TD		00:00.0
2021	PO4778089129	LGE	4	30 ACE	SP	CCA			V				00:00.0
2021	PO5867717804	ODP	6	30 BRN	SP	CRE		ED,ID,IP			TD		00:00.0
2021	PO4930088574	LGE	3	45 BRO	SP	A		ID,IP			BD		00:00.0
2021	PO9171359344	F	6	30 OTH	SP	CRE			V				00:00.0

2021	PO9175459404	F	5	35 OTH	SP	CRE		V	00:00.0	
2021	PO9240959349	KU	5	35 OTH	SP	CCA		TD	00:00.0	
2021	PO9233859272	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4383001784	F	5	35 BRN	SP	CRE		V	00:00.0	
2021	PO4395901191	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO4390901249	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO4386101300	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO4928088573	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021	PO6742020003	ODP	6	30 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO6757319757	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4931488579	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021	PO4778889127	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO0550136160	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO0556736094	ODP	6	30 BRN	SP	CCA		V	00:00.0	
2021	PO0567436134	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO0557136220	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO0614536783	ODP	5	35 BRN	SP	CCA		V	00:00.0	
2021	PO0565136576	ODP	1	60 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO0560936505	ODP	3	45 BRN	SP	CCA		V	00:00.0	
2021	PO0560036355	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO0565536298	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO0583236526	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO0585336260	ODP	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO0591336361	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO0588536468	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO0603236583	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO0597636652	F	5	35 KOP	SP	CRE		V	00:00.0	
2021	PO0624136746	ODP	6	30 KOP	SP	CRE	ID	TD	00:00.0	
2021	PO0682737270	ODP	4	45 KOP	SP	CCA		V	00:00.0	
2021	PO0634336898A	ODP	5	35 KOP	SP	CRE	ID	TD	00:00.0	
2021	PO5870517690	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO5864517681	ODP	4	35 BRN	SP	CRE	ED,ID,IP,SRC	TX	RR	00:00.0
2021	PO4777189131	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4936488500	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO4935188522	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO4935188540	LGE	3	45 BRO	SP	A	ID	BD	00:00.0	
2021	PO4775789133	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4389101707	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4357502173	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO9259759022A	F	2	55 OTH	SP	CCA		V	00:00.0	
2021	PO9506059956	F	3	50 OTH	SP	CRE		V	00:00.0	
2021	PO9499360015	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021	PO4146306679	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO9571160400	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0	
2021	PO9564160084	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021	PO9571660017	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021	PO9553360623	F	4	40 OTH	SP	CRE		V	00:00.0	
2021	PO9537360145	F	3	35 OTH	SP	CRE		V	00:00.0	
2021	PO4364901531	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO5572392643	KU	3	40 XXX	SP	P		V	00:00.0	
2021	PO5558592568	KU	4	40 XXX	SP	P		V	00:00.0	
2021	PO5578992672	KU	2	40 XXX	SP	P		V	00:00.0	
2021	PO5554792351	KU	3	45 XXX	SP	P		V	00:00.0	
2021	PO5568492233	F	2	45 XXX	SP	P		V	00:00.0	

2021	PO5581392335	KU	3	40 XXX	SP	P		V	00:00.0
2021	PO4383001420	F	6	30 XXX	SP	CRE		V	00:00.0
2021	PO9266556667	KU	4	40 OTH	SP	P	ED,ID,SRS	TD	00:00.0
2021	PO9289756762	KU	4	40 OTH	SP	P	ED,ID,SRS	TD	00:00.0
2021	PO9382455820	F	6	30 OTH	SP	CRE		V	00:00.0
2021	PO9447455677	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021	PO9424855791	F	6	30 OTH	SP	CRE		V	00:00.0
2021	PO9359056125	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9303555846	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9399255955	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9469355823	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9295456203	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9396956512	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9401656412	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9425055855	F	2	55 OTH	SP	CCA		V	00:00.0
2021	PO9290556413	F	4	35 OTH	SP	CRE		V	00:00.0
2021	PO9315855564	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9350656351	F	6	30 OTH	SP	CRE		V	00:00.0
2021	PO9412655932	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9470255638	F	6	35 OTH	SP	CRE		V	00:00.0
2021	PO9451855723	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9444755839	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9393256294	KU	6	30 OTH	SP	CRE		BD	00:00.0
2021	PO9312556858	KU	4	40 OTH	SP	P	ED,ID,SRS	TD	00:00.0
2021	PO9315555916	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9424255918	F	5	30 OTH	SP	CRE		V	00:00.0
2021	PO9342256321	F	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9371155715	F	5	35 OTH	SP	CRE		V	00:00.0
2021	PO9299456018	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9355556021	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9388655600	KU	4	40 OTH	SP	P	ED,ID,SRS	TD	00:00.0
2021	PO9444055789	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9389556425	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO9396656341	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9411755865	F	4	40 OTH	SP	CCA		V	00:00.0
2021	PO9335755953	KU	4	40 OTH	SP	CRE	ID	TD	00:00.0
2021	PO9384055870	F	4	45 OTH	SP	CRE		V	00:00.0
2021	PO9462355667	F	4	40 OTH	SP	CCA		V	00:00.0
2021	PO9318955493	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO6580525555	ODP	6	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO4801589424	F	4	45 ACE	SP	CRE		V	00:00.0
2021	PO4761289076	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4762489071	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4760989094	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO6572525193	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021	PO6581325118	ODP	6	35 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021	PO6622324378	ODP	4	40 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021	PO6611624000	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO6622323614	ODP	4	40 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021	PO6054816954	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6610623847	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021	PO6667724261	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO6673324374	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021	PO0700836279	ODP	4	40 BRN	SP	CRE		V	00:00.0

2021 PO0679436349	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0741836520	ODP	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO6156617868	ODP	6	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6147317822	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6581824629	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO6603924558A	ODP	5	35 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO6603924588	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO4766089063	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6147717496	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4761489090	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6154217330	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6149217232	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6153417169	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4944888775	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4944488785	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4760489104	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4760189111	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4763689119	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO6729924798	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6711124700	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6702424375	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6780924425	ODP	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6765124384	ODP	5	45 BRO	SP	CCA		V	00:00.0
2021 PO6724624259	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO6730024100	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6736123925	ODP	6	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO6742923725	ODP	6	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO6729923704	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO4943088798	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4774489101	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4942188795	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO0605536301	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0616136347A	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0616136347	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0632436594	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0634136486	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0647336633	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0657536643	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0669436838	ODP	6	30 BRN	SP	CCA	ED	T	00:00.0
2021 PO0673936757	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0690636882	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0702536985	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4773389131	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4943988801	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6524801331	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4772489139	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6160417185	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6168317354	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6751323545	ODP	6	35 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO6751523401	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6760323601	ODP	6	30 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO6842723433	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6845923203	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO6820423410	ODP	4	40 BRO	SP	CCA		V	00:00.0

2021 PO6809023200	F	4	40 SWP	SP	P		V	00:00.0
2021 PO6780823206	F	4	40 UNK	SP	P		V	00:00.0
2021 PO6751423205	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO4773089125	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4771989119	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4775189089	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4945388643	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4944988658	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4775789093	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4777089101	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4773789113	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4945288669	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6556299671	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5617510339	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO5614810526	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO3653854531	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3660354236	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4176385442	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4176385457	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4176685473	LGE	4	35 ACE	SP	A		V	00:00.0
2021 PO4180885488	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5675410223	F	4	40 ACW	SP	S		V	00:00.0
2021 PO5677710075	F	4	40 ACW	DF	CRE		V	00:00.0
2021 PO5635610134	KU	6	30 ACW	SP	S		V	00:00.0
2021 PO5621010213	KU	H1	85 ACW	SP	CRE		V	00:00.0
2021 PO5640810236	KU	H1	85 ACW	SP	CRE		V	00:00.0
2021 PO5629910223A	KU	3	35 ACW	SP	S		V	00:00.0
2021 PO5629910223	KU	3	40 ACW	SP	S	ED,MD	V	00:00.0
2021 PO5655410511	KU	4	45 ACW	SP	S		V	00:00.0
2021 PO5657410305	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO5656810254	KU	2	55 ACW	SP	S		V	00:00.0
2021 PO5683910324	KU	3	45 ACW	SP	S		V	00:00.0
2021 PO5684710290	KU	2	65 ACW	SP	CRE		V	00:00.0
2021 PO5687210239	F	4	40 ACW	SP	CRE		V	00:00.0
2021 PO3631555067	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4161985416	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO4161685396	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4161585391	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8765865796	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4160485383	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3662650318	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3670550156	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4171485429	F	7	25 ACE	SP	P		V	00:00.0
2021 PO4175685422	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4170185389	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4149985976	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9755759385	KU	1	60 UNK	SP	CCA		V	00:00.0
2021 PO9758959101	KU	3	50 UNK	SP	CCA		V	00:00.0
2021 PO4179885368	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4152085968	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4167885381	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4181685346	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO3566351068	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO3671550806A	KU	3	45 BRO	SP	CCA		V	00:00.0

2021 PO3928847528	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO5807509839	KU	1	65 ACW	SP	S		V	00:00.0	
2021 PO5817109649	KU	1	80 ACW	SP	CRE		V	00:00.0	
2021 PO5772810607	KU	6	30 ACW	SP	S		V	00:00.0	
2021 PO5771310637	KU	1	70 ACW	SP	CRE		V	00:00.0	
2021 PO5759610886	KU	1	70 ACW	SP	CRE		V	00:00.0	
2021 PO5766710734	KU	1	70 ACW	SP	CRE		V	00:00.0	
2021 PO9733161369	KU	4	45 UNK	SP	CCA		V	00:00.0	
2021 PO9721461702	KU	5	35 UNK	SP	CCA		V	00:00.0	
2021 PO9729561702	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO9770656808	KU	2	50 UNK	SP	CCA		V	00:00.0	
2021 PO9765756614	KU	3	50 UNK	SP	CCA		V	00:00.0	
2021 PO9760056393	KU	1	55 UNK	SP	CCA		V	00:00.0	
2021 PO9746556328	KU	4	45 UNK	SP	CCA		V	00:00.0	
2021 PO9745856345	KU	4	45 UNK	SP	CCA		V	00:00.0	
2021 PO8634572214	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO6174810321	KU	3	50 ACW	SP	S		V	00:00.0	
2021 PO6135210338	KU	3	50 ACW	SP	S		V	00:00.0	
2021 PO6159910409	KU	6	30 ACW	SP	S		V	00:00.0	
2021 PO6160010351	KU	3	50 ACW	SP	S		V	00:00.0	
2021 PO6164710159	KU	3	55 ACW	SP	S		V	00:00.0	
2021 PO3503651702	KU	2	50 UNK	SP	CCA		V	00:00.0	
2021 PO4149086028	F	3	45 BRO	SP	CRE		V	00:00.0	
2021 PO4149286015	F	4	35 BRO	SP	A		V	00:00.0	
2021 PO4150586027	F	3	50 BRO	SP	CRE		V	00:00.0	
2021 PO9745860219	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO9743560634	KU	2	55 UNK	SP	CCA		V	00:00.0	
2021 PO9740461027	KU	2	55 UNK	SP	CCA		V	00:00.0	
2021 PO4174785389	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO4174685392	LGE	4	35 BRO	SP	P	ED,ID	TX	RR	00:00.0
2021 PO4149785976	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021 PO4176585405	LGE	4	40 ACE	SP	CCA	ED,ID	TD		00:00.0
2021 PO3607650679	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO9758066066	KU	3	50 UNK	SP	CRE	ID	TD		00:00.0
2021 PO9755665695	KU	4	45 UNK	SP	CRE	ID,IP,SRS	TD		00:00.0
2021 PO4151885975	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4152185975	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4152386021	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4151986024	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4152186030	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3714265210	KU	6	30 UNK	SP	CRE	ED	TD		00:00.0
2021 PO4165385403	LGE	4	35 ACE	SP	A	ED,HH,ID	TD		00:00.0
2021 PO4165085381	LGE	4	35 ACE	SP	P	ID	TD		00:00.0
2021 PO4152286003	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4151886003	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4149886004	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO9762466739	KU	3	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO3644850505	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO9760566440	KU	4	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO4161185383	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4161485383	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO9764067141	KU	2	60 UNK	SP	CRE	ID	TD		00:00.0
2021 PO5673010029	KU	6	30 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO5674509910	KU	6	30 ACW	SP	CRE	ED,ID,SRC	TD		00:00.0

2021 Po6169485337a1	KU	4	35 BRO	SP	P	ED,HH,ID,SRC	TD	00:00.0
2021 PO4170385351	LGE	4	35 BRO	SP	CCA	ID	TD	00:00.0
2021 PO4054847854	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3955247595	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4006247729	KU	2	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4025647774	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3643154849	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4152686022	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3502052136	KU	5	35 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4147985999	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4183585344	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4166485366	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4168085351	LGE	4	40 BRO	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO4178385383	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4179985378	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO9767158280	KU	4	45 UNK	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO3782547595	KU	4	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4152185982	LGE	3	50 BRO	SP	A	ID,IP	TD	00:00.0
2021 PO4168585366	LGE	4	35 BRO	SP	CRE	ID,IP	TD	00:00.0
2021 PO4168985381	LGE	4	35 BRO	SP	CCA	ID	TD	00:00.0
2021 PO3782347391	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4181385354	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4180485346	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4178585350	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3539451008	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5794510101	KU	3	60 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO9779557157	KU	3	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO9731562019	KU	4	45 UNK	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO4176285395	LGE	7	25 BRO	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO6154410467	KU	4	30 ACW	SP	P	ED,ID	TD	00:00.0
2021 PO4180385403	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4173785317	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO9749159920	KU	3	50 UNK	SP	CRE	ID	TD	00:00.0
2021 PO9771557883	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO9775957485	KU	4	45 UNK	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO3582650791	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO3479151305	KU	3	50 BRO	SP	CCA		T	00:00.0
2021 PO3506651168	KU	4	40 BRO	SP	CCA		T	00:00.0
2021 PO4167285358	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4164785289	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4179585412	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4180685412	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4181785410	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4178485412	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4182585345	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4171785318	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4174785318	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4147785977	LGE	4	40 BRO	SP	CCA	ID,IP	BD	00:00.0
2021 PO4171085397	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4170985385	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4171285420	LGE	4	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4170385410	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4169185396	LGE	4	35 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4168185351	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0

2021 PO4168685344	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4169485337	LGE	4	35 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4017448067	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO9753265323	KU	3	50 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4173385426	LGE	2	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4175685426	LGE	2	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4172185422	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO9765067141	KU	2	60 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4165585403	LGE	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4172785427	LGE	2	55 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4147986005	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO0813905377	KU	2	65 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5670610270	KU	2	45 ACW	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO3650054719	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO3548150532	KU	4	40 BRO	SP	CCA		B	00:00.0
2021 PO8460705951	KU	5	35 UNK	SP	CRE	ED,HH,ID	X	RP2 00:00.0
2021 PO6189411418	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6189511498	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6189911563	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6190311682	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6173511313	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6173911430	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6174111498	F	4	40 ACW	SP	CRE		V	00:00.0
2021 PO6174411560	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6174811681	F	4	40 ACW	SP	P		V	00:00.0
2021 PO8546807254	KU	4	45 UNK	SP	CRE		V	00:00.0
2021 PO8566607363	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO8547807383	F	5	35 UNK	SP	A		V	00:00.0
2021 PO8545507165	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO4149785140	LGE	7	25 ACE	SP	CCA		V	00:00.0
2021 PO4164885270	LGE	1	20 ACE	AL	CCA		V	00:00.0
2021 PO6015810283	F	4	40 ACW	SP	P		V	00:00.0
2021 PO8550106971	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO8543206965	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO8540906740	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO8541806530	F	3	45 UNK	SP	A		V	00:00.0
2021 PO6028210164	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO4166485253	LGE	7	25 ACE	SP	CRE		V	00:00.0
2021 PO3636459556	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO8949066455	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4167385381	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4180585438	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO8966266626	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO8965566476	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4182285440	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4179085454	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO3518358957	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO8528105700	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO8514205718	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO8541605683	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO4160285321	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4148985136	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4146785121	LGE	6	25 ACE	SP	CCA		V	00:00.0
2021 PO4164685297	LGE	6	25 ACE	SP	P		V	00:00.0



2021 PO4159285309	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO6060609978	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6052910186	F	4	40 ACW	SP	CCA		V		00:00.0
2021 PO4164785275	LGE	7	25 ACE	SP	P		V		00:00.0
2021 PO4166885408	LGE	4	35 ACE	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021 PO4176685414	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	TX	RR	00:00.0
2021 PO8537707163-A	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3620960297	KU	4	40 ACW	SP	CRE	ID	TD		00:00.0
2021 PO6004210233	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO6016910228	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO3604160142	KU	6	30 BRO	SP	CRE	ID	TD		00:00.0
2021 PO8564807341	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO8537707163	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3592059612	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO5975509839	KU	5	35 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO5986109985	KU	5	35 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO8493705929	KU	5	35 UNK	SP	CCA	SRS	TD		00:00.0
2021 PO3561759550	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO5999909830	KU	5	35 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO6010709825	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO8476706082	KU	4	40 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021 PO8476506128	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO8475406037	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4176685422	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO6027809927	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO6028210049	KU	5	35 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO6026709816	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO6033209813	KU	5	35 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO3600560996	KU	5	35 INP	SP	CRE	ID	TD		00:00.0
2021 PO8512507050	KU	6	30 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3596660758	KU	5	35 INP	SP	CRE	ID	TD		00:00.0
2021 PO8519607048	KU	6	30 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3532459304	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3512659262	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4166585389	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4166785402	LGE	4	35 ACE	SP	CRE	ID	TD		00:00.0
2021 PO8485505930	KU	5	35 UNK	SP	CCA	SRS	TD		00:00.0
2021 PO4166585324	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4169285318	LGE	7	25 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO3518358957	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3549059339	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4164585288	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO3615759582	KU	4	40 BRO	SP	CCA		T		00:00.0
2021 PO3687164491	KU	4	45 BRO	SP	CCA		T		00:00.0
2021 PO4162485369	LGE	4	40 ACE	SP	CRE	ED,EP,ID,RB	BX	PX	00:00.0
2021 PO4166185376	LGE	4	40 ACE	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO4166285382	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4166285389	LGE	4	40 ACE	SP	A	ED,HH,ID	BD		00:00.0
2021 PO4164785307	LGE	7	25 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4164985322	LGE	7	25 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4939588667	F	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4775989103	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PV4012585770	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO4013585780	LGE	4	30 ACE	SP	CRE		V		00:00.0

2021	PV4011985758	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO4011485747	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4011085735	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4010585723	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO4012085719	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO4013685711	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4014385702	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4013785688	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4012585676	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4013085674	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO7281668384	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4012385661	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4011685660	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO3931185855	F	4	40 BRO	SP	A		V	00:00.0
2021	PO3930485848	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3930585845	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3950885807	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4010185713	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4009685700	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4001985689	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4008285679	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4009485674	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4007385685	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5058236346A	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5068936327	KU	3	45 BRO	SP	CCA		B	00:00.0
2021	PO5091236249	KU	3	45 BRO	SP	CCA		T	00:00.0
2021	PO4005585685	LGE	7	25 ACE	SP	CRE		V	00:00.0
2021	PO4005985692	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4005685705	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4006285717	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4006785728	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4007285739	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4007785750	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4008285760	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4008685771	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4009285782	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4009785794	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4010185806	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4010585816	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5736110309	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO5739910167	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO5734810364	KU	2	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO3949385835	LGE	4	40 ACE	SP	CRE	ED,ID	BX	PX 00:00.0
2021	PO3948185816	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5091236249A	KU	3	45 BRO	SP	CCA		T	00:00.0
2021	PO5098036216	KU	4	45 BRO	SP	CCA		B	00:00.0
2021	PO5166336760	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3947085797	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO3946685795	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4011185828	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4011585839	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4012285850	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5763310332	KU	5	35 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO5750710391	KU	H1	85 BRN	SP	CRE		V	00:00.0

2021	PO5843110461	KU	4	40 BRN	SP	S		V	00:00.0
2021	PO5830510505	KU	3	45 BRN	SP	S		V	00:00.0
2021	PO5793910382	F	4	40 BRN	SP	S		V	00:00.0
2021	PO5750310329	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5826710374	F	4	40 BRN	SP	S		V	00:00.0
2021	PO4022185969	F	3	45 ACE	SP	CRE		V	00:00.0
2021	PO4022085965	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4021685956	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4021185944	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4020685933	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4020185921	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4019585919	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4019685910	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4018885903	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4018085894	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3913185849	F	5	35 BRO	SP	CCA		V	00:00.0
2021	PO3913585848	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3913085837	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO3912785838	F	UNK	25 BRO	SP	CRE		V	00:00.0
2021	PO3915085881	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO3915885893	LGE	UNK	25 BRO	SP	CCA		V	00:00.0
2021	PO4034186140	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PV4035286133a	KU	4	35 ACE	SP	CRE	ED,HH,ID	BD	00:00.0
2021	PV4034986135	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021	PV4035286133	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PV4035486132	LGE	3	45 ACE	SP	CRE	ED,HH,ID,RB	BD	00:00.0
2021	PO4036886121	LGE	3	50 ACE	SP	CRE	ED,ID,IP,RB	BD	00:00.0
2021	PV4035686128	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO5697110307	KU	2	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO5706210341	KU	6	30 BRN	SP	S		V	00:00.0
2021	PO5716310338	KU	H1	85 BRN	SP	CRE		V	00:00.0
2021	PO5697910327	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO3950485791	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO3951185801	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4020285984	F	7	25 ACE	SP	P		V	00:00.0
2021	PO4021385974	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5170236884	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5183736888	KU	3	45 UNK	SP	CRE	ID	TD	00:00.0
2021	PO5199236897	KU	3	45 UNK	SP	CRE	ID	TD	00:00.0
2021	PO3914485888	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4023085989	LGE	4	40 ACE	SP	P	ED,ID,MD	BX	RP1 00:00.0
2021	PO4024286012	LGE	7	25 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4023786014	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021	3915185873A	KU	4	35 BRO	SP	CCA		V	00:00.0
2021	PO3915185873	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3914485862	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3914085856	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3911785856	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO3912385872	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4024086023	LGE	4	40 ACE	SP	P		BD	00:00.0
2021	PV4024386032	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO5283731197	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3929785832	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3928985820	F	4	35 BRO	SP	CCA		V	00:00.0

2021 PO3927385795	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3928985809	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO3928385810	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4011385650	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4010785640	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4010285644	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3927939251	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3923785818	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO3929085868	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3927585843	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4033386300	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4033486285	LGE	5	35 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4031786283	LGE	1	25 ACE	SP	CRE		V	00:00.0
2021 PO5097137326	KU	3	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5102637458	KU	3	45 BRO	SP	CCA		T	00:00.0
2021 PO5104337499	KU	3	45 KOP	SP	CRE	ID	TD	00:00.0
2021 PO5105837537	KU	4	40 UNK	SP	CRE	EP,ID	X RP2	00:00.0
2021 PO5107537667	KU	6	30 KOP	SP	CRE	ID	TD	00:00.0
2021 PO5111537671	KU	3	45 UNK	SP	CRE	ED,ID,IP	X RP2	00:00.0
2021 PO5139337709	KU	2	45 UNK	SP	CRE	ID,IP	BX RP2	00:00.0
2021 PO5137937844	KU	2	45 UNK	SP	CRE		B	00:00.0
2021 PO5130037863	KU	2	50 ACW	SP	CRE	ID	BD	00:00.0
2021 PO5113837902	KU	3	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5092537969	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5082637994	KU	3	45 BRO	SP	CCA		B	00:00.0
2021 PO5071938018	KU	3	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5034937980	KU	3	45 ACW	SP	CRE	ID	TD	00:00.0
2021 PO4999537945	KU	2	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4987037938	KU	4	40 CAH	SP	CRE	ID	X RP1	00:00.0
2021 PO5090037144	KU	2	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3996685475	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3997285500	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3998285494	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3997985512	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3998885509	F	UNK	25 ACE	SP	CRE		V	00:00.0
2021 PO3998285524	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4139785998	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3999285525	F	UNK	25 ACE	SP	CRE		V	00:00.0
2021 PO3998585542	F	4	30 ACE	SP	A		V	00:00.0
2021 PV853772016	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4146985959	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO3997085543	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3997985535	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3996085551	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3995285559	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3987685521	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3962385749	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3961885724	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO3961185735	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3960585726	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3960985776	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4089686001	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4088486024	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4087086025	F	4	40 ACE	SP	CRE		V	00:00.0

2021 PO4086486026	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4086586020	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4089986036	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3968886222	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3968486199	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3967386175	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4089886018	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3950085775	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3946485767	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3946085788	F	4	35 ACE	SP	A		V	00:00.0
2021 PO3948285785	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3944485807	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3945285804	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3944485801	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO3942985810	F	4	30 ACE	SP	A		V	00:00.0
2021 PO3943185815	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3941885822	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3941685817	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO6542469718	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3941285826	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3940185833	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO3939585836	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4096686142	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4096786155	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4096786167	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4095086174	F	4	40 ACE	SP	CRE	IP	V	00:00.0
2021 PO4096886180	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4096986193	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4090186186	F	UNK	25 ACE	SP	CRE		V	00:00.0
2021 PO4089286201	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4088286145	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4088886176	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4089086188	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4088686165	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4089186157	F	UNK	25 ACE	SP	CRE		V	00:00.0
2021 PO4087986133	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4087786120	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4087086108	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4087486108	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4087386095	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4087286083	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4087186071	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4086686060	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4087086053	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4087986051	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4089186050	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4089986049	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4090186063	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4090286075	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4090286087	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4090486099	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4091186108	F	5	30 ACE	SP	CRE		V	00:00.0
2021 PO4090886109	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4090986116	F	4	40 ACE	SP	CRE		V	00:00.0

2021 PO4091186126	F		4	45 ACE	SP	CRE		V	00:00.0
2021 PO4091486138	F	UNK		45 ACE	SP	CRE		V	00:00.0
2021 PO4091686150	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4091886162	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4092186174	F		3	45 ACE	SP	CCA		V	00:00.0
2021 PO4092386186	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4092586198	F		4	40 ACE	SP	CCA		V	00:00.0
2021 PO4089786221	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4089686217	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4091386215	F		4	40 ACE	SP	CCA		V	00:00.0
2021 PO4092886214	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4094286213	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4095686211	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4097186208	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4069086711	F		3	50 ACE	SP	CCA		V	00:00.0
2021 PO4068386740	LGE		4	35 ACE	SP	CRE	ED,ID	B	00:00.0
2021 PO4068886817	LGE		4	35 ACE	SP	CCA		V	00:00.0
2021 PO4068586776	LGE		4	40 ACE	SP	CRE		B	00:00.0
2021 PO4067386788	LGE		4	35 ACE	SP	CRE	ED,ID	B	00:00.0
2021 PO4068386755	LGE		3	45 ACE	SP	CCA		V	00:00.0
2021 PO3946885742	LGE		4	35 ACE	SP	CCA		V	00:00.0
2021 PO7782978993	LGE		4	35 ACE	SP	CCA		V	00:00.0
2021 PO4065486736	LGE		4	35 ACE	SP	CCA		B	00:00.0
2021 PO3988685544	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO3988485539	F		4	40 ACE	SP	A		V	00:00.0
2021 PO7807379355	LGE		4	35 ACE	SP	CCA		V	00:00.0
2021 PO3954385874A1	KU		4	40 ACE	SP	CCA		V	00:00.0
2021 PO3939285787	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO3970085842	LGE		3	45 ACE	SP	CCA		V	00:00.0
2021 PO6832670052	LGE		4	30 ACE	SP	CCA		V	00:00.0
2021 PO3964785815	LGE		4	40 ACE	SP	CCA		V	00:00.0
2021 PO3966585800	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO3967285797	F		4	40 ACE	SP	CCA		V	00:00.0
2021 PO3965885792	LGE		3	45 ACE	SP	CCA		V	00:00.0
2021 PO3964885800	LGE		4	35 ACE	SP	A		V	00:00.0
2021 PO0854162744	LGE		4	35 ACE	SP	CRE		V	00:00.0
2021 PO4367385008	LGE		3	50 ACE	SP	CRE		V	00:00.0
2021 PO4382984950	LGE		4	35 ACE	SP	CCA		V	00:00.0
2021 PO4384984951	LGE		4	30 ACE	SP	CCA		V	00:00.0
2021 PO4375885053	LGE		4	30 ACE	SP	CCA		V	00:00.0
2021 PO7861107195	KU		6	30 BRN	SP	CRE		V	00:00.0
2021 PO4412785703	LGE		4	35 BRO	SP	CRE		V	00:00.0
2021 PO4408785835	LGE		3	45 BRO	SP	P		BD	00:00.0
2021 PO4266586680	LGE		1	80 BRO	SP	CRE		V	00:00.0
2021 PO4414185945	LGE		4	30 BRO	SP	CCA		V	00:00.0
2021 PO4412385884	LGE		4	40 BRO	SP	CCA		V	00:00.0
2021 PO4410385928	LGE		4	35 BRO	SP	CCA		V	00:00.0
2021 PO4265786768	LGE		4	40 ACE	SP	CCA		V	00:00.0
2021 PO4264886691	LGE		1	70 ACE	SP	CRE		V	00:00.0
2021 PO4413685934	LGE		3	45 BRO	SP	CCA		V	00:00.0
2021 PO4258486596	LGE		4	35 ACE	SP	CCA		V	00:00.0
2021 PO4257186598	LGE		4	35 ACE	SP	CCA		V	00:00.0
2021 PO4259686614	LGE		4	35 ACE	SP	CCA		V	00:00.0
2021 PO4261286662	LGE		4	35 ACE	SP	CCA		V	00:00.0

2021 PO4261186655	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PV4265986632	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4427485625	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4414485852	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PV4267286628	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5632811041	KU	6	30 UNK	SP	CRE		V	00:00.0
2021 PO4380684950	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4381684951	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4366185099	LGE	4	30 ACE	DF	CRE		V	00:00.0
2021 PO4382284951	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO9137098132	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4370985012	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4370985002	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4367385018	LGE	3	20 ACE	SP	CCA		V	00:00.0
2021 PO9788278061	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4271686601	LGE	4	25 BRO	SP	CRE		V	00:00.0
2021 PO4367585092	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO4371185088	LGE	4	35 ACE	SP	A		V	00:00.0
2021 PO4386085215	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4367385028	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4366185027	LGE	3	60 ACE	SP	A		V	00:00.0
2021 PO4270386623	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4267086614	LGE	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4365785028	LGE	UNK	55 ACE	SP	CCA		V	00:00.0
2021 PO4262986646	LGE	3	50 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4265686604	LGE	1	50 BRO	SP	CRE		V	00:00.0
2021 PO7679706428	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4415085892	LGE	4	30 BRO	SP	A		V	00:00.0
2021 PO4374384971	LGE	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4264386551	LGE	1	70 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4264986603	LGE	3	50 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO1281168891	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO8415986876	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5526010977	KU	4	40 BRN	SP	CRE		BD	00:00.0
2021 PO7476305517	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7745406980	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7816804648	KU	6	30 BRN	SP	CRE	MD,SRC	TD	00:00.0
2021 PO9843177084	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO9835077152	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO9817977220	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO9805377287	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO7418701252	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7390602672	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7376402079	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7404101523	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9816378124	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO9802078114	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4265586596	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO9786777919	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO9785077777	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO9783077635	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4264486572	LGE	H3	50 BRO	SP	CCA		V	00:00.0
2021 PO7407002861	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7372402555	F	5	35 UNK	SP	P		V	00:00.0

2021 PO7367502302	KU	5	35 UNK	SP	CCA	ED,ID	TD		00:00.0
2021 PO7441503479	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO7516904361	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO7491800802	KU	5	35 KOP	SP	CCA		V		00:00.0
2021 PO7502600888	KU	5	35 KOP	SP	CCA		V		00:00.0
2021 PO7475200848	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO7482600875	KU	5	35 KOP	SP	CCA		V		00:00.0
2021 PO7517200683	KU	5	35 KOP	SP	CCA		V		00:00.0
2021 PO4259486593	LGE	4	30 ACE	AL	CCA		V		00:00.0
2021 PO4259486600	LGE	1	55 ACE	AL	CCA		V		00:00.0
2021 PO5519711877	KU	6	30 UNK	SP	CRE		BD		00:00.0
2021 PO5420110257	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021 PO5584910848	KU	6	30 UNK	SP	CRE		BD		00:00.0
2021 PO5574910846	KU	6	30 UNK	SP	CCA	ED,ID	TD		00:00.0
2021 PO9429501187	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7499608217	F	4	40 XXX	SP	CRE	ED,ID,IP	BX	RP2	00:00.0
2021 PO7532908077	F	4	40 XXX	SP	CRE	ED,ID,IP	BX	RP3	00:00.0
2021 PO7594507878	KU	2	40 XXX	SP	CRE	ED,ID,IP,MD,RB	BX	PX	00:00.0
2021 PO7491508249	F	4	40 XXX	SP	CRE	ID	V		00:00.0
2021 PO9428401459	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9431000509	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8733301020	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8664900655	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8668500925	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8386587210	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8710399726	KU	6	35 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5606109668	KU	5	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5735409343	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4270386611	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO2276122806	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5805909260	KU	4	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO2485617194	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5721609242	KU	6	30 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5710809217	KU	6	30 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5704809353	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5751409336	KU	4	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO2459917211	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5733409343	KU	2	40 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO5446010725	KU	4	40 UNK	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO5761009290	KU	6	30 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO2390720199	KU	5	35 BRN	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO2458020378	KU	6	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2453620283	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2431817234	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2410120490	KU	4	40 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO2393219918	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2400220193	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2219621805	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO2277622156	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2309922934	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2309822829	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2279422579	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO2277622670	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO2309522664	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0



2021	PO2293622656	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2250622807	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2265523007	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2295522963	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2199820772	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2277822991	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO2279022458	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2278322311	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2277122007	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO2260322191	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2239021906	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2249521728	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2276321834	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO224421951	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2196221121	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2197520948	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2194921289	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO5615209951	KU	6	30 BRN	SP	CRE	ID	BD		00:00.0
2021	PO2512317434	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2562618382	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2371020119	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO7496504103	KU	5	35 UNK	SP	CRE	ID	BX	PX	00:00.0
2021	PO5732909247	KU	6	30 BRN	SP	CRE	ID,IP	BD		00:00.0
2021	PO4372285102	LGE	3	45 ACE	SP	A	ED,ID,RB	VX	RP2	00:00.0
2021	PO4264186538	LGE	1	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4265986632	LGE	4	35 BRO	SP	A	ED,ID	BD		00:00.0
2021	PO4265786604	LGE	1	50 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO8591287026	KU	5	35 UNK	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021	PO8750100609	KU	4	40 UNK	SP	P	HH,ID	BX	RP2	00:00.0
2021	PO8921097846	KU	4	35 UNK	SP	CRE	ED,HH,ID	BX	RP2	00:00.0
2021	PO9762897435	KU	4	45 UNK	SP	CRE	HH,ID	BX	PX	00:00.0
2021	PO7518904386	KU	4	40 UNK	SP	CRE	ED,ID	BX	PX	00:00.0
2021	PO7446905536	F	4	40 UNK	SP	CRE	HH,ID	BX	PX	00:00.0
2021	PO4369985098	LGE	4	30 ACE	SP	A	ED,HH,ID	VX	RP2	00:00.0
2021	PO4264786536	F	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4264986554	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4379185182	LGE	UNK	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4374985146	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4376585160	LGE	UNK	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4377485167	LGE	UNK	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4366585104	LGE	4	40 ACE	SP	A	ED,ID,RB	X	RP2	00:00.0
2021	PO4369985103	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4371185103	LGE	3	45 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4368685103	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4368985098	LGE	4	30 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4367085103	LGE	3	45 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4375185099	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4372585137	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4371485142	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4371585138	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4375385141	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4371185071	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4371185081	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4367585082	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0

2021	PO4367485050	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4385884945	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4384484946	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4383484946	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4383785195	LGE	3	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4380085189	LGE	UNK	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4264086529	LGE	1	50 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4374685083	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4263086458	LGE	3	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO5429610287	KU	6	30 UNK	SP	CRE		BD		00:00.0
2021	PO7761607009	KU	3	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO7440601017	KU	2	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5516111017	KU	4	40 BRN	SP	CRE		BD		00:00.0
2021	PO5510511335	KU	4	40 UNK	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7635106664	KU	3	50 BRN	SP	CRE	ED	BD		00:00.0
2021	PO7658906347	KU	4	40 BRN	SP	CRE	ED	BD		00:00.0
2021	PO7612705200	KU	3	45 BRN	SP	CRE	ED	BD		00:00.0
2021	PO5686810988	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021	PO4523787625	F	4	40 BRO	SP	P		V		00:00.0
2021	PO5560611629	KU	4	40 BRN	SP	CRE		BD		00:00.0
2021	PO7756506989	KU	4	40 BRN	SP	CCA		V		00:00.0
2021	PO2253521865	KU	3	45 BRN	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO5600509452	KU	5	35 BRN	SP	CRE	ID,IP	BD		00:00.0
2021	PO2193821589	KU	4	45 BRN	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO2206022007	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2190322051	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2194721444	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2249621647	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4267286608	LGE	1	20 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO7653506422	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO4398185841	LGE	4	40 BRO	SP	A	ED,EP,ID,RB	BX	RR	00:00.0
2021	PO5422610326	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021	PO5596711303	KU	4	40 UNK	SP	CRE	ED,ID	BD		00:00.0
2021	PO4374785102	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4419585822	LGE	4	40 BRO	SP	CRE	ED,EP,ID,RB	X	RP1	00:00.0
2021	PO9706195768	KU	2	50 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5557411503	KU	4	40 BRN	SP	CRE		BD		00:00.0
2021	PO5451911098	KU	4	45 UNK	SP	CRE		BD		00:00.0
2021	PO5428610335	KU	6	30 UNK	SP	CRE		BD		00:00.0
2021	PO4384685203	LGE	3	45 ACE	SP	A	HH,ID	BD		00:00.0
2021	PO4382985188	LGE	3	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4535188006	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4534888011	LGE	4	40 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	00:00.0
2021	PO4860685025	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8257700343	KU	5	35 XXX	SP	S		V		00:00.0
2021	PO8254500449	KU	3	40 XXX	SP	S		V		00:00.0
2021	PO8251100569	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8241700896	KU	4	35 XXX	SP	S		V		00:00.0
2021	PO8246800713	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8238001023	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8266700379	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO8274400338	KU	6	30 XXX	SP	S		V		00:00.0
2021	PO6751797752	F	5	35 ACE	SP	CRE		V		00:00.0
2021	PO6740597843	F	4	40 ACE	SP	CRE		V		00:00.0

2021 PO4866784898	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4864984887	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4357185875	LGE	4	40 ACE	SP	CRE	ED	VX	RP2	00:00.0
2021 PO8204602259	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO8197702580	F	3	40 XXX	SP	P		V		00:00.0
2021 PO8214701916	KU	3	50 XXX	SP	S		V		00:00.0
2021 PO8218902089	KU	3	50 XXX	SP	S		V		00:00.0
2021 PO8203802671	KU	3	50 XXX	SP	S		V		00:00.0
2021 PO8197102608	F	3	40 XXX	SP	P		V		00:00.0
2021 PO8195702671	F	4	40 XXX	SP	P		V		00:00.0
2021 PO8208002499	KU	3	50 XXX	SP	S		V		00:00.0
2021 PO8213802283	KU	3	50 XXX	SP	S		V		00:00.0
2021 PO4541487978	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4358885885	LGE	4	40 ACE	SP	A	ED,ID,RB	TD		00:00.0
2021 PO4359985885	LGE	UNK	25 ACE	SP	CCA		V		00:00.0
2021 PO4359785890	LGE	4	40 ACE	SP	P	ID	TD		00:00.0
2021 PO4541087985	LGE	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4541587988	LGE	4	30 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4539487998	LGE	4	30 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4867784903	LGE	3	45 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4868484892	LGE	4	30 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4861284864	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4865584847	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4862084840	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6737397707	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4360785895	LGE	4	40 ACE	SP	A	ID	TD		00:00.0
2021 PO4360385888	LGE	4	30 ACE	SP	P	ID	TD		00:00.0
2021 PO4539588008	LGE	3	55 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4364385942	LGE	UNK	25 ACE	SP	P	ED	BD		00:00.0
2021 PO4363585944	LGE	3	50 ACE	SP	CCA	ED	BD		00:00.0
2021 PO4363485937	F	4	35 ACE	SP	CCA		V		00:00.0
2021 4364285932-a	LGE	4	30 ACE	SP	P	ED	BD		00:00.0
2021 PO4363985931	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4364185934	LGE	3	50 ACE	SP	CRE	ED	V		00:00.0
2021 PO4364285932	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4365885906	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8340799561	KU	4	40 XXX	SP	CRE		V		00:00.0
2021 PO8340399756	KU	6	30 XXX	SP	CRE	ED,ID,MD	BD		00:00.0
2021 PO8340399661	KU	5	35 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO8380299632	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SR	TD		00:00.0
2021 PO5510008557	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6563197337	F	6	30 ACE	SP	CRE		V		00:00.0
2021 PO6556097188	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6600697580	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6580597074	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8229401942	KU	3	45 XXX	SP	CRE	ED,EP,ID,IP,MD,SR	TX	RR	00:00.0
2021 PO6605997581	F	5	35 ACE	SP	CRE		V		00:00.0
2021 PO6596497471	F	4	40 ACE	SP	P		V		00:00.0
2021 PO6591897356	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6587697247	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO6583397144	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO6593897090	F	3	40 ACE	SP	P		V		00:00.0
2021 PO6605497046	KU	3	40 ACE	SP	P		V		00:00.0
2021 PO8233702054	KU	5	35 XXX	SP	CRE	ED,ID,IP,MD,SR	TD		00:00.0

2021 PO8237602152	KU	5	35 XXX	SP	CRE	ED,ID,IP,SRC	TD		00:00.0
2021 PO4863484878	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4542587961	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4542087969	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4863484878-A	KU	5	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4358085880	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO6616497006	F	3	40 ACE	SP	P		V		00:00.0
2021 PO6627596964	F	3	40 ACE	SP	P		V		00:00.0
2021 PO6639096921	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO6650596878	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6659096845	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6664196948	F	4	40 ACE	SP	P		V		00:00.0
2021 PO6669797067	F	4	40 ACE	SP	P		V		00:00.0
2021 PO6673097131	F	4	40 ACE	SP	P		V		00:00.0
2021 PO6670897152	F	4	40 ACE	SP	P		V		00:00.0
2021 PO6726697801	F	5	35 ACE	SP	P		V		00:00.0
2021 PO8414999614	KU	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	BX	PX	00:00.0
2021 PO8433799708	KU	4	40 XXX	SP	CRE	ED,ID,IP,RB,SRC	TX	RR	00:00.0
2021 PO8452499702	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4365985894	LGE	4	30 ACE	SP	P	ED,ID,RB	TD		00:00.0
2021 PO4366585892A	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO5481809011	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5485308878	KU	3	60 XXX	SP	CRE	ID	BD		00:00.0
2021 PO6640698844	KU	4	30 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6644098940	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5486508770	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5492108852	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5510608787	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5519508852	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5519108756	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5516008745	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5513008652	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6704797067	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4360985851	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO4361985852	LGE	4	40 ACE	SP	CRE	ED,ID,MD	BD		00:00.0
2021 PO4857684964	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6709897174	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6715197285	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4362985852	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4363985853	LGE	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO6720497395	F	4	40 ACE	SP	P		V		00:00.0
2021 PO6725497501	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6729497585	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6709597860	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4484013106	KU	5	35 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4488213093	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4499912905	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4484012959	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4379285953	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO4380685934	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4379985944	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4380385938	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4380785914	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4381385903	LGE	4	35 ACE	SP	CCA		V		00:00.0

2021	PO8167395774	KU	4	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8174095750	F	5	30 XXX	SP	P		V	00:00.0
2021	PO81733595921	KU	4	40 XXX	SP	CRE	ED,ID,MD	TD	00:00.0
2021	PO8173296069	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO8178796046	KU	4	40 XXX	SP	S		V	00:00.0
2021	PV0981871724	LGE	4	35 ACE	SP	CRE	ED	BD	00:00.0
2021	PV0980371596	LGE	4	35 ACE	SP	CRE	ED	TD	00:00.0
2021	PO5449105177	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5446805302	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5457705444	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4390585970	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021	PO4390985969	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4391585977	LGE	4	40 ACE	SP	CRE	ED	TD	00:00.0
2021	PO5452005430	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5457905559	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5462005538	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5462105656	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6347200712	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO5468005783	F	2	50 XXX	SP	P		V	00:00.0
2021	PO5475605949	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO8315097423	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO8326697533	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO8333797597	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO6724098896	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6719798828	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4855785107	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021	PO4524587896	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4536587921	LGE	4	40 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021	PO4537087913	LGE	4	35 BRO	SP	CRE	ED,ID,IP,RB	BX	RP1 00:00.0
2021	PO4531587998	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5482307003	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5488907045	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO5486407107	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5488707162	F	5	35 BRN	SP	CCA		V	00:00.0
2021	PO5481007457	F	6	30 XXX	SP	CRE		V	00:00.0
2021	PO5483107530	F	5	35 XXX	SP	CRE		BD	00:00.0
2021	PO5477507552	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5437407635	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5375207024	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5370307144	KU	5	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO5330507080	F	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5341307047	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO5292107737	KU	2	70 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4850685157	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO5309207671	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5316107644	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5496108934	F	5	35 XXX	SP	CRE		V	00:00.0
2021	PO4857385108	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4857885126	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4856985125	LGE	3	45 BRO	SP	CRE	ED,HH,ID,RB	TX	RR 00:00.0
2021	PO6729599183	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6741099119	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6753199050	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6765298982	F	4	40 ACE	SP	CRE		V	00:00.0

2021	PO6777398914	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PV4532187988	LGE	4	40 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	00:00.0
2021	PO4389785928	LGE	3	45 ACE	SP	CRE	ED	BD		00:00.0
2021	PO1047471629	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO6788798849	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO5725363983	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4857385068	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4857685076	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO1067071785	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4533887963	LGE	4	35 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021	PO4533287971	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4532787980	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021	PO4533187981	LGE	4	35 BRO	SP	CCA	ED,ID	TD		00:00.0
2021	PO1099172027	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO1087711954	LGE	3	45 ACE	SP	CCA	ED	V		00:00.0
2021	PO1088371973	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO8318798255	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8314498399	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8311498505	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8308698601	KU	4	35 XXX	SP	S		V		00:00.0
2021	PO8304098741	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8299298907	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8293999087	KU	3	40 XXX	SP	S		V		00:00.0
2021	PO8322298136	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO4397186003	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021	PO8332197790	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8329397891	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8325598019	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8288599271	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO4858385025	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4858185057	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6800998780	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6817698686	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6809998524	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6807198464	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6797398506	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6797498261a	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO8591999835	KU	5	35 XXX	DF	CRE	ED,ID,MD,RB	X	PX	00:00.0
2021	PO8862299116	KU	4	45 XXX	SP	S		V		00:00.0
2021	PO8844198818	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8260400388	KU	4	30 XXX	SP	CRE		V		00:00.0
2021	PO6337101329	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6340901298	KU	4	50 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6355701321	KU	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4526487975	LGE	4	40 BRO	SP	A	ED,ID,IP	BD		00:00.0
2021	PO4526987968	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4527487959	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4392885983	LGE	4	25 ACE	SP	CRE	ED	VX	RP3	00:00.0
2021	PO6274300847	KU	6	30 ACE	SP	CCA		V		00:00.0
2021	PO6242301312	KU	6	30 ACE	SP	CCA		V		00:00.0
2021	PO6236001493	KU	6	30 ACE	SP	CCA		V		00:00.0
2021	PO4392185985	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO6269400993	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6797498261	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0

2021	PO6779398180	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6791198130	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6782997960	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4359385911	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4531287948	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4530187967	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4530687959	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4529587976	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4528987985	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4536687678	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4533587691	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4534687699	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO6768297879	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6754197860	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6744797884	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6731797915	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4531087899	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4531687890	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO6556846984	KU	5	35 UNK	SP	CRE	ID,IP	TD	00:00.0
2021	PO6216312662	KU	4	40 ACW	SP	S		V	00:00.0
2021	PO6215612728	KU	2	65 ACW	SP	CRE		V	00:00.0
2021	PO6239912736	KU	2	60 ACW	SP	CRE		V	00:00.0
2021	PO6255912754	KU	2	50 ACW	SP	CRE		V	00:00.0
2021	PO6305112870	KU	2	60 ACW	SP	CRE		V	00:00.0
2021	PO6333112920	KU	2	60 ACW	SP	S		V	00:00.0
2021	PO6359212968	KU	3	50 ACW	SP	CRE		V	00:00.0
2021	PO6387613021	KU	3	50 ACW	SP	CRE		V	00:00.0
2021	PO6413912992	KU	5	30 ACW	SP	S		V	00:00.0
2021	PO6412113066	KU	1	60 ACW	SP	S		V	00:00.0
2021	PO6437213171	KU	2	55 ACW	SP	CRE		V	00:00.0
2021	PO6457013245	KU	2	70 ACW	SP	CRE		V	00:00.0
2021	PO6479613307	KU	2	70 ACW	SP	CRE		V	00:00.0
2021	PO6476713299	KU	6	30 ACW	SP	CCA		V	00:00.0
2021	PO6474413293	KU	4	40 ACW	SP	CCA		V	00:00.0
2021	PO4434302025	KU	2	55 BRN	SP	CRE	ED,HH,ID,RB	X PX	00:00.0
2021	PO3539721136	F	4	40 XXX	SP	P		V	00:00.0
2021	PO3545320980	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6540346186	KU	4	50 UNK	SP	CRE	ID	TD	00:00.0
2021	PO4009685533	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4009585522	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4009585509	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4011585530	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4329202956	KU	5	40 BRN	SP	CRE	ED,ID,RB	TX RR	00:00.0
2021	PO4075784798	LGE	4	40 BRO	SP	CCA	ED,ID	TD	00:00.0
2021	PO3513120838	F	4	40 XXX	SP	P		V	00:00.0
2021	PO3504420787	F	4	40 XXX	SP	P		V	00:00.0
2021	PO3506520701	F	4	40 XXX	SP	P		V	00:00.0
2021	PO3331625091	F	4	40 XXX	SP	P		V	00:00.0
2021	PO3342724880	F	4	40 XXX	SP	P		V	00:00.0
2021	PO3346224813	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO3361424862	F	4	40 XXX	SP	P		V	00:00.0
2021	PO3356624786	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4336502846	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4012585528	F	4	40 BRN	SP	A		V	00:00.0

2021	PO4013785528	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4014485527	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4015085543	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4014185559	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4075884780	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4076984799	LGE	4	30 BRO	SP	P		V	00:00.0
2021	PO4076884808	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4122985455	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4390202026	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4122985442	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4129485454	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4128685463	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4029185465	F	4	30 BRN	SP	CCA		V	00:00.0
2021	PO4027785460	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4026185467	F	4	30 BRN	SP	A		V	00:00.0
2021	PO4026185462	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4024585469	F	4	30 BRN	SP	A		V	00:00.0
2021	PO5565830453	F	4	40 BRO	SP	A		V	00:00.0
2021	PO5578630222	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4098685300	LGE	4	40 BRO	SP	A	ID	TD	00:00.0
2021	PO4099985299	LGE	4	40 BRO	SP	CRE	ED,HH,ID	TD	00:00.0
2021	PO4101185298	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4381402141	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO6533646639	KU	4	45 UNK	SP	CCA		V	00:00.0
2021	PO6502746592	KU	4	45 UNK	SP	CCA		V	00:00.0
2021	PO4127885474	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6538845929	KU	6	30 UNK	SP	CCA		V	00:00.0
2021	PO6532846034	KU	4	45 UNK	SP	CCA		V	00:00.0
2021	PO6494945906	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4127185483	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4126185491	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5579830705	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO5605432546	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	00:00.0
2021	PO5551531123	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5554631247	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4024485464	F	4	35 BRN	SP	CCA		V	00:00.0
2021	PO4023085465	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4023285470	F	4	30 BRN	SP	A		V	00:00.0
2021	PO4022385466	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4041185453	F	4	25 BRN	SP	CCA		V	00:00.0
2021	PO4016285472	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4015085479	F	4	30 BRN	SP	CCA		V	00:00.0
2021	PO4014785474	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4013485475	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4013885481	F	4	30 BRN	SP	CCA		V	00:00.0
2021	PO4012085477	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4103985259	LGE	6	25 BRO	SP	CRE		V	00:00.0
2021	PO4102685268	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD	00:00.0
2021	PO4104085266	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4405801801	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4415302255	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO6402345494	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO6392845594	KU	6	30 UNK	SP	CRE	ID,IP	TD	00:00.0
2021	PO4012485482	F	4	30 BRN	SP	P		V	00:00.0



2021 PO4010485483	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4009985480	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7242866525	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4008985480	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4008785485	F	4	35 BRN	SP	P		V	00:00.0
2021 PO4007685481	F	4	35 BRN	SP	P		V	00:00.0
2021 PO4005985482	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4004685484	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4004185484	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4002885485	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4002185491	F	4	30 BRN	SP	CCA		V	00:00.0
2021 PO7230866407	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4020085335	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4137184906	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4137284914	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4095885274	LGE	4	40 BRO	SP	CCA	ID	TD	00:00.0
2021 PO4096685273	LGE	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4096985277	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4100285270	LGE	4	40 BRO	SP	CRE	ED,ID,IP,MD	TD	00:00.0
2021 PO4097685272	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4099085271	LGE	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4081984793	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4081584778	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO8521760903	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4135884901	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4134584906	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO5612532690	KU	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4020085342	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4020085354	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4020085366	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4020185378	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4020185389	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4020185398	F	4	40 BRN	SP	P		V	00:00.0
2021 PO3486926498	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3492126545	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3489426628	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3480326611	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3480425427	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3493425359	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3489625302	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3499425445	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3506925256	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3525125326	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3546025282	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3542025135	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4418402053	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4424502125	KU	4	40 BRN	SP	CRE	ED,ID,IP	X	RP1 00:00.0
2021 PO4423102188	KU	4	45 BRN	OT	CRE	ED,ID	TD	00:00.0
2021 PO4130984867	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO6349144201	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4131484880	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO6320344081	KU	6	30 UNK	SP	CRE		V	00:00.0
2021 PO6326744165	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO6331944085	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0

2021	PO6322143923	KU	4	40 UNK	SP	CCA		V			00:00.0
2021	PO6273243685	KU	3	45 UNK	SP	CCA		V			00:00.0
2021	PO6271143793	KU	6	30 UNK	SP	CCA		V			00:00.0
2021	PO6290643901	KU	6	30 UNK	SP	CRE	ID			TD	00:00.0
2021	PO5669733985	KU	5	35 BRO	SP	CRE	ED,ID			TD	00:00.0
2021	PO5684333872	KU	5	35 BRO	SP	CRE	ED,ID			TD	00:00.0
2021	PO4096485260	LGE	4	40 BRO	SP	CRE	ED,ID,IP			TD	00:00.0
2021	PO4096385249	LGE	4	40 BRO	SP	CRE	ID			TD	00:00.0
2021	PO4106185238	LGE	6	25 BRO	SP	CRE	ED,ID			TD	00:00.0
2021	PO4105485236	LGE	4	40 BRO	SP	CRE	ID			BD	00:00.0
2021	PO4104785227	LGE	6	25 BRO	SP	CRE	ID			TD	00:00.0
2021	PO4104785234	LGE	4	40 BRO	SP	A	ED,ID			TD	00:00.0
2021	PO4103285240	LGE	4	30 BRO	SP	CCA				V	00:00.0
2021	PO4103585235	LGE	4	35 BRO	SP	P	ED,ID,RB	X		PX	00:00.0
2021	PO4102385235	LGE	4	40 BRO	SP	CRE	ED,EP,ID,MD,RB	BX		PX	00:00.0
2021	PO4101185236	LGE	4	40 BRO	SP	A	ED,EP,ID,RB	X		PX	00:00.0
2021	PO4131784894	LGE	4	40 ACE	SP	CRE	ED,ID			TD	00:00.0
2021	PO4409802354	KU	3	40 BRN	SP	CRE	ED,ID			BD	00:00.0
2021	PO4042485341	F	4	40 BRN	SP	CCA				V	00:00.0
2021	PO4042585354	F	4	40 BRN	SP	CRE				V	00:00.0
2021	PO4042585368	F	4	40 BRN	SP	CCA				V	00:00.0
2021	PO4042685380	F	2	45 BRN	SP	CCA				V	00:00.0
2021	PO4042785393	F	4	40 BRN	SP	CCA				V	00:00.0
2021	PO4043885331	F	4	25 BRN	SP	CRE				V	00:00.0
2021	PO4043885327	F	1	65 BRN	SP	CCA				V	00:00.0
2021	PO7584464866	F	4	40 BRN	SP	CRE				V	00:00.0
2021	PO4050885360	LGE	4	30 BRN	SP	CRE	ED			BD	00:00.0
2021	PO6303643814	F	4	40 UNK	SP	A				V	00:00.0
2021	PO6308243782	KU	4	40 UNK	SP	CCA				V	00:00.0
2021	PO4131984902	LGE	5	35E ACE	SP	CRE	ED,ID			TD	00:00.0
2021	PO4131984904	LGE	4	40 ACE	SP	CRE	ED,ID			TD	00:00.0
2021	PO4132084907	LGE	4	40 ACE	SP	P	ED,ID			TD	00:00.0
2021	PO6494250365	KU	4	40 UNK	SP	CRE	ED,HH,ID	X		RP3	00:00.0
2021	PO4024085504	F	4	40 BRN	SP	CCA				V	00:00.0
2021	PO4022385501	F	4	40 BRN	SP	CCA				V	00:00.0
2021	PO4123385544	F	4	40 ACE	SP	P				V	00:00.0
2021	PO5491429957	KU	4	40 BRO	SP	CRE	ED,ID			TD	00:00.0
2021	PO5490129830	KU	6	30 BRO	SP	CRE	ED,ID			BX	00:00.0
2021	PO4123285533	F	4	40 ACE	SP	P				V	00:00.0
2021	PO4123285520	F	4	40 ACE	SP	CCA				V	00:00.0
2021	PO4123185506	F	4	40 ACE	SP	CCA				V	00:00.0
2021	PO4123185493	F	3	45 ACE	SP	CCA				V	00:00.0
2021	PO4123085481	F	4	40 ACE	SP	CCA				V	00:00.0
2021	PO4022085475	F	4	40 BRN	SP	A				V	00:00.0
2021	PO4022185484	F	4	40 BRN	SP	A				V	00:00.0
2021	PO4028985459	F	4	40 BRN	SP	CCA				V	00:00.0
2021	PO4123085468	F	4	40 ACE	SP	CCA				V	00:00.0
2021	PO4104585285	LGE	4	30 BRO	SP	CCA				V	00:00.0
2021	PO4101485269	LGE	4	40 BRO	SP	CRE	ED,ID,MD,RB			TX	00:00.0
2021	PO4103885282	LGE	4	40 BRO	SP	CRE	ED,EP,ID,RB			BX	00:00.0
2021	PO3402825203	F	4	40 XXX	SP	P				V	00:00.0
2021	PO3415225181	F	4	40 XXX	SP	P				V	00:00.0
2021	PO3406925260	F	4	40 XXX	SP	P				V	00:00.0
2021	PO3403825091	F	4	40 XXX	SP	P				V	00:00.0

2021	PO3408225100	F	4	40 XXX	SP	P		V		00:00.0
2021	PO3505926378	F	4	40 XXX	SP	P		V		00:00.0
2021	PO3499726314	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4129485571	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4130785571	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4132085571	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4020485473	F	4	35 BRN	SP	A		V		00:00.0
2021	PO5603932461	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4376402587	KU	4	40 BRN	SP	CCA	ED	TD		00:00.0
2021	PO4020485468	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO6482550327	F	4	40 UNK	SP	CCA		V		00:00.0
2021	PO4047685349	LGE	4	25 BRN	SP	CRE		BD		00:00.0
2021	PO4048585353	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4047885369	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021	PO4048785369	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4050485318	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4050585336	F	3	45 BRN	SP	CCA		V		00:00.0
2021	PO4051185352	F	4	45 BRN	SP	P		V		00:00.0
2021	PO4052385356	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5732135689	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO5775035824	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4077684821	LGE	4	40 BRO	SP	CCA	ED,ID,IP	BD		00:00.0
2021	PO4125785501	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4377902309	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4125785513	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO3351825132	F	4	40 XXX	SP	P		V		00:00.0
2021	PO3349225193	F	4	40 XXX	SP	P		V		00:00.0
2021	PO3366925297	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4125885526	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4125885543	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4125885557	F	4	40 ACE	SP	P	ED,EP,ID	V		00:00.0
2021	PO4125985570	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4375502436	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4076184832	LGE	3	45 BRO	SP	CRE	EP	VX	RP3	00:00.0
2021	PO4126085583	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4102485297	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4103685293	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4127485567	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO6479545836	KU	4	40 UNK	SP	CCA		V		00:00.0
2021	PO6446745712	KU	6	30 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO6435745666	KU	4	40 UNK	SP	CCA		V		00:00.0
2021	PO4075584840	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4076284843	LGE	4	30 BRO	SP	A	HH,IP,MD,RB	BX	PX	00:00.0
2021	PO4077284848	LGE	4	35 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4077784846	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4078284872	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4078884859	LGE	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4080284862	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4369002518	KU	5	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO3382025379	F	4	40 XXX	SP	P		V		00:00.0
2021	PO3379725292	F	4	40 XXX	SP	P		V		00:00.0
2021	PO3394925370	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4128085571	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4104985266	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0

2021	PO4019685404	F	4	25 BRN	SP	CRE		V		00:00.0
2021	PO5454733297	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5338223021	KU	2	50 UNK	SP	CCA		V		00:00.0
2021	PO5374422688	KU	4	35 UNK	SP	CCA		V		00:00.0
2021	PO5344322939	KU	2	50 UNK	SP	CCA		V		00:00.0
2021	PO5346122919	KU	2	50 UNK	SP	CCA		V		00:00.0
2021	PO5349022886	KU	2	50 UNK	SP	CCA		V		00:00.0
2021	PO5005712807	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO5011912969	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO3985785662	F	4	45 ACE	SP	P		V		00:00.0
2021	PO3986385662	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4050386338	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO3991883503	LGE	1	90 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4048686308	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4048486309	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4049386329	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4048786318	F	4	35 ACE	SP	CRE		V		00:00.0
2021	PO4049086314	F	4	35 ACE	SP	CRE		V		00:00.0
2021	PO4049486309	F	4	35 ACE	SP	CRE		V		00:00.0
2021	PO4038186179	LGE	4	40 KOP	SP	CCA		V		00:00.0
2021	PO5452033475	KU	5	35 UNK	SP	CRE	ID	BX	PX	00:00.0
2021	PO4038786173	LGE	3	45 KOP	SP	CCA		V		00:00.0
2021	PO4039486167	LGE	4	40 KOP	SP	A	ED,ID,IP	BD		00:00.0
2021	PO4039386169	LGE	4	40 KOP	SP	A	ED,ID,MD	TD		00:00.0
2021	PO4073386013	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4073486026	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4073586039	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4073686052	F	4	40 ACE	SP	A		V		00:00.0
2021	PO4073786065	F	4	40 ACE	SP	CRE	ED,EP,HH,ID	VX	PX	00:00.0
2021	PO4073886079	F	4	40 ACE	SP	A		V		00:00.0
2021	PO4003485903	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO5395022120	KU	2	50 UNK	SP	CCA		V		00:00.0
2021	PO5408522280	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO4048786309	LGE	UNK	65 ACE	SP	CCA		V		00:00.0
2021	PO4050586295	LGE	UNK	65 ACE	SP	CRE		V		00:00.0
2021	PO4050486286	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021	PO4023686599	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021	PO4023486599	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4037286182	LGE	4	40 KOP	SP	A	ED,ID,IP,MD	BD		00:00.0
2021	PO4035986190	LGE	3	45 KOP	SP	CCA		V		00:00.0
2021	PO5019113159	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO4940212734	F	4	40 KOP	SP	S		V		00:00.0
2021	PO4954712803	KU	6	30 KOP	SP	S		V		00:00.0
2021	PO5015113048	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO4035286177	LGE	4	40 KOP	SP	P	ED,ID,IP,MD	TD		00:00.0
2021	PO5423022113	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO5436622075	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5430022150	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5414722208	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO5457433119	KU	5	35 UNK	SP	CRE	ID	TD		00:00.0
2021	PO5424121907	KU	6	30 UNK	SP	CCA		V		00:00.0
2021	PO5433022002	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO4074586093	F	4	30 ACE	SP	CRE		V		00:00.0
2021	PO4073986094	F	4	40 ACE	SP	CRE		V		00:00.0

2021 PO4071986096	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4070586097	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4069286097	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4034686169	LGE	4	40 KOP	SP	P	ED,ID,IP,MD	TD			00:00.0
2021 PO3994783542	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TX		RR	00:00.0
2021 PO4045886002	LGE	4	40 KOP	SP	P	ED,HH,ID,IP	BX		RP2	00:00.0
2021 PO4046185984	F	4	40 KOP	SP	A		V			00:00.0
2021 PO4045985979	F	4	45 KOP	SP	A		V			00:00.0
2021 PO5460232941	KU	5	35 UNK	SP	CRE	ID	BD			00:00.0
2021 PO5470532272	KU	4	40 UNK	SP	CRE	ID	BD			00:00.0
2021 PO4042885981	F	4	40 KOP	SP	A		V			00:00.0
2021 PO4000985884	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4001785884	LGE	3	50 ACE	SP	CRE	ED,ID	TD			00:00.0
2021 PO4063086114	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4062486104	F	4	30 ACE	SP	CRE		V			00:00.0
2021 PO4062486097	F	4	30 ACE	SP	CRE		V			00:00.0
2021 PO4062986101	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4062886085	F	4	40 ACE	SP	CCA		V			00:00.0
2021 PO4062786073	F	4	40 ACE	SP	CCA		V			00:00.0
2021 PO4062686060	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4062586045	F	4	35 ACE	SP	CRE		V			00:00.0
2021 PO4062486032	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4062386019	F	4	40 ACE	SP	CRE	ED,EP,HH,ID	VX		PX	00:00.0
2021 PO4062386014	F	4	30 ACE	SP	CRE		V			00:00.0
2021 PO4062386004	F	2	45 ACE	SP	CCA		V			00:00.0
2021 PO4059786055	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4058686093	F	4	40 ACE	SP	A		V			00:00.0
2021 PO4042185982	F	4	40 KOP	SP	CCA		V			00:00.0
2021 PO3996583567	LGE	2	95 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4004185907	LGE	4	35 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4002385889	LGE	3	50 ACE	SP	CRE	ED,ID	TD			00:00.0
2021 PO3996083559	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO3994183535	LGE	1	90 BRO	SP	PEN	ED,ID,IP	TD			00:00.0
2021 PO3994083534	LGE	3	45 BRO	SP	CCA		V			00:00.0
2021 PO5468032268	KU	5	35 UNK	SP	CRE	ID	TD			00:00.0
2021 PO5453632247	KU	4	35 UNK	SP	CRE	ID	BD			00:00.0
2021 PO4003685903	LGE	3	50 ACE	SP	CRE	ED,ID	TD			00:00.0
2021 PO4005085915	LGE	3	50 ACE	SP	CRE	ED,ID	TD			00:00.0
2021 PO4005285952	LGE	1	35 ACE	SP	CRE		V			00:00.0
2021 PO4006085946	LGE	2	35 ACE	SP	A		V			00:00.0
2021 PO4936412609	F	4	40 KOP	SP	CRE	HH	B			00:00.0
2021 PO4945512588	KU	6	30 KOP	SP	CRE	ED,ID	TD			00:00.0
2021 PO4931512498	F	4	40 KOP	SP	CRE		V			00:00.0
2021 PO5436432574	KU	4	40 UNK	SP	CRE	ID	BD			00:00.0
2021 PO5425822453	KU	4	40 UNK	SP	CRE	ED,ID	BX		PX	00:00.0
2021 PO4042185640	F	3	45 KOP	SP	CCA		V			00:00.0
2021 PO4925512052	KU	6	30 KOP	SP	CRE	ED,ID	BD			00:00.0
2021 PO4935312352	KU	6	30 KOP	SP	CRE	ED,ID	TD			00:00.0
2021 PO4896712047	F	4	40 KOP	SP	P		V			00:00.0
2021 PO4910711996	F	4	40 KOP	SP	P		V			00:00.0
2021 PO4918412183	F	4	40 KOP	SP	S		V			00:00.0
2021 PO4883012098	F	4	40 KOP	SP	P		V			00:00.0
2021 PO4926812382	F	4	40 KOP	SP	CRE		V			00:00.0
2021 PO4897112424	F	4	40 KOP	SP	P		V			00:00.0

2021 PO4908712380	KU	6	30 KOP	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021 PO4889912266	F	4	40 KOP	SP	P		V		00:00.0
2021 PO4914412083	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO4922712284	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO4042585726	F	3	45 KOP	SP	CCA		V		00:00.0
2021 PO5291032256	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO5472132128	KU	4	35 UNK	SP	CRE	ID		TD	00:00.0
2021 PO7380072569a	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7380072569	LGE	3	50 ACE	SP	CRE		V		00:00.0
2021 PO4023186077	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PV4022486071	F	3	45 ACE	SP	P		V		00:00.0
2021 PO4119184362	F	3	45 KOP	SP	CCA		V		00:00.0
2021 PO4000185856	F	4	35 ACE	SP	P		V		00:00.0
2021 PO4021186057	F	4	35 ACE	SP	P		V		00:00.0
2021 PO4021186058	F	3	45 ACE	SP	CRE		V		00:00.0
2021 PO4019086038	LGE	4	35 ACE	SP	P	ED,ID		BD	00:00.0
2021 PO4117484351	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4017986026	F	3	45 ACE	SP	P		V		00:00.0
2021 PO4116284350	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4115184344	F	4	40 KOP	SP	A		V		00:00.0
2021 PO7308771652	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO3995985824	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO3998685854	LGE	3	55 ACE	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO3999485861	LGE	3	55 ACE	SP	CRE	ED,ID		TD	00:00.0
2021 PO3991485743	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4014683379	LGE	4	35 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO4043785842	F	4	45 KOP	SP	A		V		00:00.0
2021 PO4044285842	F	4	30 KOP	SP	P		V		00:00.0
2021 PO4064186472	LGE	3	50 ACE	SP	CRE	ED,ID		BD	00:00.0
2021 PO4063086462	LGE	3	50 ACE	SP	CRE	ED,ID		BD	00:00.0
2021 PO4061886451	LGE	UNK	60 ACE	SP	CCA		V		00:00.0
2021 PO5374725763	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO5374125663	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO4015383389	LGE	4	35 BRO	SP	CRE	ID		BD	00:00.0
2021 PO4016583401	LGE	4	35 BRO	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO5373425533	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO5372425374	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO5360525221	KU	4	40 UNK	SP	CRE	ID,RB	BX	PX	00:00.0
2021 PO5098212809	KU	4	40 KOP	SP	CRE	ED,ID		BD	00:00.0
2021 PO5059512898	KU	5	35 KOP	SP	CRE	ED,ID		TD	00:00.0
2021 PO5096312696	F	4	40 KOP	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4009683322	LGE	4	35 BRO	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO4045685892	F	5	30 KOP	SP	A		V		00:00.0
2021 PO4044985895	F	4	40 KOP	SP	P		V		00:00.0
2021 PO3993785795	LGE	3	50 ACE	SP	CRE	ED,ID		TD	00:00.0
2021 PO3992185771	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO3992985783	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO7087169783	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO3994985811	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO4050986673	LGE	2	55 ACE	SP	S		V		00:00.0
2021 PO4049386680	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO5378432389	KU	5	40 UNK	SP	CRE	ID		TD	00:00.0
2021 PO4013583360	LGE	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO4072486546	LGE	4	40 ACE	SP	CRE	ED,ID		TD	00:00.0

2021 PO3997185838	LGE	3	55 ACE	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO4116584309	LGE	4	40 KOP	SP	A	ED,ID,IP,MD,SRC	TD		00:00.0
2021 PO4116884293	LGE	4	40 KOP	SP	P	ED,ID,IP,MD	TD		00:00.0
2021 PO4117184282	LGE	4	40 KOP	SP	P	ED,EP,ID,MD	BD		00:00.0
2021 PO4082485729	LGE	4	35 ACE	SP	A	ID	TD		00:00.0
2021 PO4021583343	LGE	4	35 BRO	SP	CCA	ED	T		00:00.0
2021 PO4020483326	LGE	4	35 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4080485731	LGE	4	35 ACE	SP	P	ID	TD		00:00.0
2021 PO4021083327	LGE	4	40 BRO	SP	A	ID	BD		00:00.0
2021 PO4120384437	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4119884432	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4120384419	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4120784408	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4121284395	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4075085831	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO5449131847	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO5458031861	KU	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021 PO5440431690	KU	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4076585814	F	4	30 ACE	SP	A		V		00:00.0
2021 PO4076685819	F	4	40 ACE	SP	A		V		00:00.0
2021 PO4076685823	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4078185819	F	4	40 ACE	SP	A		V		00:00.0
2021 PO4078585817	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4079585816	F	4	40 ACE	SP	A		V		00:00.0
2021 PO4080785815	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4082185813	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4082785813	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4083985812	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO7989769798	LGE	5	35 ACE	SP	CCA		V		00:00.0
2021 PO4084985811	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4085685810	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4024783453	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4121684385	F	4	40 KOP	SP	CCA		V		00:00.0
2021 PO4122184372	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4026683465	LGE	4	40 BRO	SP	CCA	ID	BD		00:00.0
2021 PO4010885946	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4124784367	LGE	4	30 KOP	SP	A	ID	BD		00:00.0
2021 PO4124384358	F	4	45 KOP	SP	P		V		00:00.0
2021 PO4122984352	F	4	30 KOP	SP	A		V		00:00.0
2021 PO4122684358	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4028283484	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4016983314	LGE	4	30 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4088785808	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4086285807	F	4	30 ACE	SP	A		V		00:00.0
2021 PO4086685804	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4086685809	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4087685822	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4087785836	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4071786733	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5344632205	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO5270632326	KU	5	35 UNK	SP	CRE	ID	TD		00:00.0
2021 PO5276132224	KU	3	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4071686719	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4071786717	F	4	30 ACE	SP	CCA		V		00:00.0

2021 PO4071686712	LGE	UNK	80	ACE	SP	CRE	ED,ID	TD	00:00.0		
2021 PO4069186707	LGE	UNK	60	ACE	SP	CRE	ID,MD	BD	00:00.0		
2021 PO4016483320	LGE		4	35	BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4016083328	LGE		4	35	BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4121684331	F		4	40	KOP	SP	CCA		V	00:00.0	
2021 PO4122984321	F		4	40	KOP	SP	A		V	00:00.0	
2021 PO4124184321	F		4	40	KOP	SP	A		V	00:00.0	
2021 PO4005885911	F		4	40	ACE	SP	P		V	00:00.0	
2021 PO4004985903	F		3	45	ACE	SP	P		V	00:00.0	
2021 PO4003785890	F		4	40	ACE	SP	P		V	00:00.0	
2021 PO4002385878	F		4	30	ACE	SP	P		V	00:00.0	
2021 PO3992885766	F		4	35	ACE	SP	P		V	00:00.0	
2021 PO3997985815	LGE		4	30	ACE	SP	CCA		V	00:00.0	
2021 PO3995785774	LGE		3	45	ACE	SP	A		V	00:00.0	
2021 PO4126284306	LGE		4	30	KOP	SP	A	ED,ID	BD	00:00.0	
2021 PO4125984313	F		4	40	KOP	SP	CCA		V	00:00.0	
2021 PO4065386697	LGE	UNK		60	ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4067286702	LGE		3	60	ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4066586706	F		4	35	ACE	SP	CRE		V	00:00.0	
2021 PO4064886700	F		4	35	ACE	SP	CRE		V	00:00.0	
2021 PO4124884311	F		4	40	KOP	SP	A		V	00:00.0	
2021 PO4085385890	F		4	40	ACE	SP	CRE		V	00:00.0	
2021 PO4084085873	LGE		7	25	ACE	SP	CRE		V	00:00.0	
2021 PO4123984293	F		4	40	KOP	SP	CCA		V	00:00.0	
2021 PO4086385890	F		4	40	ACE	SP	CRE		V	00:00.0	
2021 PO4088185889	F		1	60	ACE	SP	CCA		V	00:00.0	
2021 PO4088085875	F		3	45	ACE	SP	CCA		V	00:00.0	
2021 PO4088085866	F		4	40	ACE	SP	CCA		V	00:00.0	
2021 PO4091585847	F		4	30	ACE	SP	CRE		V	00:00.0	
2021 PO4063486692	LGE	UNK		60	ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4061286690	F		4	30	ACE	SP	S		V	00:00.0	
2021 PO4062986695	F		4	30	ACE	SP	CRE		V	00:00.0	
2021 PO4061586687	LGE	UNK		60	ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5312525141	KU		2	50	UNK	SP	CRE		B	00:00.0	
2021 PO4015683340	LGE		4	35	BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4015283350	LGE		4	40	BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO5274032217	KU		3	45	UNK	SP	CCA		B	00:00.0	
2021 PO5388331691	KU		6	30	UNK	SP	CRE	ID	BX	PX	00:00.0
2021 PO1807645442	KU		4	40	BRN	SP	CRE	ID	BD	00:00.0	
2021 PO1831444138A1	KU		6	35	BRN	SP	CCA	ED,ID	BD	00:00.0	
2021 PO1838145655	KU		5	35	BRN	SP	CRE	ID	BD	00:00.0	
2021 PO1862745075	KU		4	35	BRN	SP	CCA	ID	BD	00:00.0	
2021 PO1869045122	KU		4	35	BRN	SP	A	ED,ID	BD	00:00.0	
2021 PO2123341484	KU		6	30	BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4263339867	KU		4	45	BRO	SP	CRE	ID	BD	00:00.0	
2021 PO4265740196	KU		5	30	BRO	SP	CRE		BD	00:00.0	
2021 PO8954772180	KU		4	40	BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO8994472397	KU		5	35	BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9151177808	KU		6	30	BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9185677999	KU		4	40	BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9248775618	KU		3	45	BRO	SP	A	ID	BD	00:00.0	
2021 PO9262575079	KU		5	35	BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9464478596	KU		4	40	BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9480279303	KU		4	40	BRO	SP	CRE	ED,ID	BD	00:00.0	



2021 PO0018114444	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO0018315413	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO0019615976	KU	6	30 ACW	SP	S	ED	V	00:00.0
2021 PO0023416159	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO0033415221	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO0039716238	KU	3	40 ACW	SP	CRE		V	00:00.0
2021 PO0053816327	KU	4	40 ACW	SP	CRE		V	00:00.0
2021 PO0063916396	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO0072416453	KU	3	40 ACW	SP	S		V	00:00.0
2021 PO0077016168	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO0082316523	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO0095616319	KU	3	40 ACW	SP	S	MD	V	00:00.0
2021 PO4841806295	KU	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4844006272	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4851006040	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4855805422	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4856405635	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4857105845	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4857606055	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4858206268	KU	3	40 KOP	SP	CCA		V	00:00.0
2021 PO4873705737	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4874705894	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4875606021	F	4	40 KOP	SP	A		V	00:00.0
2021 PO4878606278	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4892506263	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4900805508	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4917205509	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4917405714	F	4	40 KOP	SP	CCA		V	00:00.0
2021 PO4918605912	F	4	45 KOP	SP	P		V	00:00.0
2021 PO4920006169	F	5	35 KOP	SP	CRE		V	00:00.0
2021 PO4920305834	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4922105966	F	4	40 KOP	SP	P		V	00:00.0
2021 PO4924806163	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4927306339	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4931105508	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4944706316	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4945505823	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4948205921	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4952806113	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9807815227	KU	3	40 ACW	SP	S		V	00:00.0
2021 PO9807914927	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9808315341	KU	4	40 ACW	SP	CRE		V	00:00.0
2021 PO9811114622	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9900915350	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9917615495	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9928514754	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9935415666	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9952415557	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9972015707	KU	4	45 ACW	SP	S		V	00:00.0
2021 PO9974515955	KU	3	40 ACW	SP	S		V	00:00.0
2021 PO9986715814	KU	4	40 ACW	DF	S		V	00:00.0
2021 PO9999015666	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9999314182	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9999616050	KU	2	50 ACW	SP	S		V	00:00.0

2021 PO0030613882	KU	4	40 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO0037913831	KU	6	30 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO0062213855	KU	4	40 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO0065913665	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4935105605	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4937305942	KU	6	30 XXX	SP	CRE	ED,ID	TD			00:00.0
2021 PO4941106133	KU	6	30 XXX	SP	CRE	ED,ID	TD			00:00.0
2021 PO4947505551	KU	6	30 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO4957506298	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX		PX	00:00.0
2021 PO9952615853	KU	4	40 ACW	SP	CRE	ID	BD			00:00.0
2021 PO4105085697	LGE	4	30 BRN	SP	CCA	EP,HH,ID,IP,RB	X		PX	00:00.0
2021 PO4118886158	LGE	4	30 ACE	SP	CRE	ED,EP,HH,ID,RB	X		PX	00:00.0
2021 PO4196786255	LGE	4	40 BRO	SP	CRE	ED	X		RP1	00:00.0
2021 PO4111386195	LGE	4	35 ACE	SP	CCA		V			00:00.0
2021 PO4115686126	F	4	35 ACE	SP	CRE		V			00:00.0
2021 PO4116586114	F	5	45 ACE	SP	CRE		V			00:00.0
2021 PO4117586142	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4117986106	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4119086100	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4119186133	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4120586098	F	6	35 ACE	SP	CRE		V			00:00.0
2021 PO4120586126	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4121786121	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4122886115	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4123386126	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4123986110	F	3	45 ACE	SP	CCA		V			00:00.0
2021 PO4123986138	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4124286146	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4140185394	LGE	3	55 BRN	SP	CCA		V			00:00.0
2021 PO4140185394-A	F	4	40 BRN	SP	P		V			00:00.0
2021 PO4140485355	LGE	4	30 BRN	SP	P		V			00:00.0
2021 PO4141085428	LGE	4	30 BRN	SP	CCA		V			00:00.0
2021 PO4142485324	LGE	3	50 BRN	SP	CRE		V			00:00.0
2021 PO4142985302	LGE	1	60 BRN	SP	CCA		V			00:00.0
2021 PO4143785416	LGE	4	30 BRN	SP	CCA		V			00:00.0
2021 PO4144085247	LGE	3	45 BRN	SP	CCA		V			00:00.0
2021 PO4144185262	LGE	3	45 BRN	SP	CCA		V			00:00.0
2021 PO4144185279	LGE	4	35 BRN	SP	CCA		V			00:00.0
2021 PO4176086377	F	4	30 BRO	SP	CRE		V			00:00.0
2021 PO4176286381	F	4	40 BRO	SP	A		V			00:00.0
2021 PO4176486368	F	3	45 BRO	SP	A		V			00:00.0
2021 PO4176486369	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4176886370	F	4	40 BRO	SP	A		V			00:00.0
2021 PO4176986372	F	3	45 BRO	SP	CCA		V			00:00.0
2021 PO4178686382	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4196186260	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4197986260	F	4	40 BRO	SP	CCA		V			00:00.0
2021 PO4199086260	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4199986288-A	KU	4	40 BRO	SP	CCA		V			00:00.0
2021 PO4201386260	F	4	35 BRO	SP	CCA		V			00:00.0
2021 PO4201486271	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4202086260	F	4	35 BRO	SP	A		V			00:00.0
2021 PO4203186285	LGE	4	35 BRO	SP	CCA		V			00:00.0
2021 PO4203386260	F	4	35 BRO	SP	CRE		V			00:00.0

2021 PO4203786260	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4205486344	LGE	4	40 BRO	SP	CCA		V			00:00.0
2021 PO4206386353	LGE	4	40 BRO	SP	CCA		V			00:00.0
2021 PO8578764955	LGE	1	60 BRN	SP	CCA		V			00:00.0
2021 PO4118686125	LGE	4	30 ACE	SP	P	ED,EP,ID,IP	TX	RR		00:00.0
2021 PO4201586305	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR		00:00.0
2021 PO4205286282	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR		00:00.0
2021 PO4111386201	LGE	4	45 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4112786194	LGE	4	35 ACE	SP	P	ED,ID,IP	TD			00:00.0
2021 PO4112986200	LGE	4	40 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4114686162	LGE	4	35 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4114686193	LGE	5	30 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4116686191	LGE	6	30 ACE	SP	P	ED,ID,IP	TD			00:00.0
2021 PO4116686197	LGE	4	45 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4118486189	LGE	4	35 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4118586195	LGE	4	45 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4122586109	LGE	5	35 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4123586131	LGE	4	40 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4123885800	LGE	4	40 BRN	SP	P	ID,IP,SRC	TD			00:00.0
2021 PO4124186122	LGE	4	30 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4126785761	LGE	4	40 BRN	SP	P	ID,IP	TD			00:00.0
2021 PO4134285776	LGE	4	40 BRN	SP	P	ID,SRC	TD			00:00.0
2021 PO4135085792	LGE	4	40 BRN	SP	CRE	ID,IP,SRC	TD			00:00.0
2021 PO4139585386	LGE	4	30 BRN	SP	CRE	ID	TD			00:00.0
2021 PO4140185368	LGE	4	30 BRN	SP	A	ID	TD			00:00.0
2021 PO4140285405	LGE	4	30 BRN	SP	P	ID	TD			00:00.0
2021 PO4141285417	LGE	4	35 BRN	SP	P	ID,IP,SRS	TD			00:00.0
2021 PO4142485345	LGE	4	30 BRN	SP	P	ID,SRS	TD			00:00.0
2021 PO4142885204	LGE	3	50 BRN	SP	P	HH,ID	TD			00:00.0
2021 PO4143485234	LGE	3	50 BRN	SP	CRE	ID,IP,SRS	TD			00:00.0
2021 PO4175686376	LGE	4	30 BRO	SP	A	ED,ID	TD			00:00.0
2021 PO4196286289	LGE	4	40 BRO	SP	A	ED,ID,IP	TD			00:00.0
2021 PO4197486258	LGE	4	35 BRO	SP	A	ED,ID,IP	TD			00:00.0
2021 PO4197486263	LGE	4	40 BRO	SP	A	ED,ID,IP	TD			00:00.0
2021 PO4198186270	LGE	3	40 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4199186281	LGE	6	25 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO4199986288	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4199986290	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4200686289	LGE	4	35 BRO	SP	A	ED,ID	TD			00:00.0
2021 PO4200986299	LGE	4	40 BRO	SP	A	ED,ID,IP	TD			00:00.0
2021 PO4202486314	LGE	4	35 BRO	SP	A	ED,ID,IP	TD			00:00.0
2021 PO4203386322	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4203786327	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4205286282-A	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4139585392	LGE	4	30 BRN	SP	CRE	HH	BX	RP2		00:00.0
2021 PO4114786198	LGE	4	40 ACE	SP	CRE	ED,ID,IP,RB	BD			00:00.0
2021 PO4115286178	LGE	4	30 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4124185804	LGE	3	45 BRN	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO4125785790	LGE	4	40 BRN	SP	P	ID,IP	BD			00:00.0
2021 PO4126085742	LGE	3	45 BRN	SP	P	ID,IP	BD			00:00.0
2021 PO4128785761	LGE	4	40 BRN	SP	P	ID	BD			00:00.0
2021 PO4134585783	LGE	4	40 BRN	SP	P	ID	BD			00:00.0
2021 PO4137985186	LGE	4	35 BRN	SP	P	ID	BD			00:00.0
2021 PO4140185388	LGE	4	40 BRN	SP	CRE	ID	BD			00:00.0

2021 PO4141185371	LGE	3	50 BRN	SP	P	ID,IP	BD	00:00.0
2021 PO4141585358	LGE	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4143385321	LGE	3	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4143485251	LGE	3	50 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4198986278	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4202186287	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO8574965101	LGE	2	60 BRN	SP	CCA	ID,IP	BD	00:00.0
2021 PO0628457049	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO1001555163	F	5	35 BRO	SP	CCA		V	00:00.0
2021 PO2150837498	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2164037332	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO2166937208	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2174037403	KU	3	40 BRN	SP	CCA		V	00:00.0
2021 PO2217437751	KU	6	35 BRN	SP	CRE		V	00:00.0
2021 PO2227738170	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO2233537869	KU	5	45 BRN	SP	CRE		V	00:00.0
2021 PO2248337963	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO2268638100	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO2285438974	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO2290038292	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO2291538882	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO2296838802	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO2301438733	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO2312038574	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO2316438507	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO2406009020	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO2425708679	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO2444909171	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO2488809402	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO2512922463	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2516323890	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2518222003	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2524323732	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2527823255	KU	5	35 BRO	SP	CRE		V	00:00.0
2021 PO2529723580	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2539323280	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2541923114	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2544722946	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2546122789	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2548511791	F	5	40 UNK	SP	CRE		V	00:00.0
2021 PO2549422543	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2553322194	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2555222064	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8568576149	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8594975616	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8595275911	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8609575750	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8630575561	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8650875378	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8668875209	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8690274999	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8705974837	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8726874626	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8753474315	KU	4	45 BRO	SP	CCA		V	00:00.0

2021 PO8760673650	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8775973086	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8776572554	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8779473485	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8810473639	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8834373518	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8844573369	KU	5	45 BRO	SP	S		V	00:00.0
2021 PO9111481120	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9140780597	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9140780597A	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO9158680291	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO9160980252	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9171278896	F	6	30 BRO	SP	S		V	00:00.0
2021 PO9173080057	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO9174979680	F	4	40 BRO	SP	A		V	00:00.0
2021 PO9175579880	F	4	40 BRO	SP	A		V	00:00.0
2021 PO9192480173	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9208076895	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO9221580099	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0624157219	KU	4	40 BRO	SP	CRE	ED,EP,ID,MD	TD	00:00.0
2021 PO0979555830	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4532187882	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4396586011	LGE	4	40 ACE	SP	CRE	ID	TD	00:00.0
2021 PO6220201247	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO4887985571	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4535487938	LGE	4	35 BRO	SP	CRE	ED,ID,JP	BD	00:00.0
2021 PO4397686021	LGE	4	40 ACE	SP	P	ID	TD	00:00.0
2021 PO8152579550g	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8152579550f	KU	6	30 ACE	ST	CCA		V	00:00.0
2021 PO8152579550e	KU	6	30E ACE	ST	CCA		V	00:00.0
2021 PO8162278856	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8152579550d	KU	6	30 ACE	ST	CCA		V	00:00.0
2021 PO8152579550c	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8152579550b	KU	6	30 ACE	ST	CCA		V	00:00.0
2021 PO8152579550a	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8152579550	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8152579615	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8152579710	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8201979903	F	5	35 ACE	SP	P		V	00:00.0
2021 PO8199479904	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8188479908	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8175979914	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8151479925	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8141479930	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8125079938	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8108879949	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8092279952	F	4	45 ACE	SP	P		V	00:00.0
2021 PO7970975101	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8165479919	F	4	40 ACE	SP	P	ED,HH,ID,RB	VX	RP1 00:00.0
2021 PO4451188248	LGE	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4458088338	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4459288331	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4452088195	LGE	4	45 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4452388172	LGE	3	55 ACE	SP	CRE	ED,ID	TD	00:00.0

2021 PO4464188188	LGE	4	35 ACE	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021 PO4829325408	KU	2	45 UNK	SP	CRE	RB	BX	PX	00:00.0
2021 PO5336131910	KU	4	40 UNK	SP	CRE	RB	BX	PX	00:00.0
2021 PO4875526567	F	4	40 UNK	SP	CRE	RB	VX	PX	00:00.0
2021 PO4865825704	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO4870325481	KU	2	55 UNK	SP	CRE		B		00:00.0
2021 PO4452188186	LGE	3	50 ACE	SP	CCA	ED	BD		00:00.0
2021 PO4452288179	LGE	3	50 ACE	SP	CRE	ED,ID,MD	BD		00:00.0
2021 PO4458388318	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4451888255	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4850125523	KU	2	50 UNK	SP	CRE		B		00:00.0
2021 PO5275832407	KU	2	40 UNK	SP	CRE		B		00:00.0
2021 PO5319332049	KU	2	50 UNK	SP	CRE		B		00:00.0
2021 PO2803790372	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO2852490186	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4891525517	KU	2	60 UNK	SP	CRE		B		00:00.0
2021 PO2619990499	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4462888355	LGE	3	60 ACE	SP	CRE	ED	V		00:00.0
2021 PO4460188350	LGE	3	50 ACE	SP	CRE	ED,ID,MD	BD		00:00.0
2021 PO4460988344	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4460488321	LGE	4	40 ACE	SP	CRE	ED,ID,RB	BD		00:00.0
2021 PO4011283488	F	5	35 BRO	SP	CCA		V		00:00.0
2021 PO4458688175	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4458688187	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4458588198	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4460788333	LGE	4	25 ACE	SP	CRE		V		00:00.0
2021 PO4009983482	LGE	4	40 BRO	SP	A		V		00:00.0
2021 PO4455988236	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4455888237	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4460388332	LGE	4	40 ACE	SP	CRE	ED,ID,MD	BD		00:00.0
2021 PO4462988347	LGE	4	35 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO5323732282	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO5331632217	KU	3	45 UNK	SP	CRE		B		00:00.0
2021 PO2639990486	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO2671690451	KU	4	40 BRO	SP	CRE	ED,IP	BD		00:00.0
2021 PO2744690402	KU	5	30 BRO	SP	CRE	ID,IP,MD,SRS	BD		00:00.0
2021 PO2789590051	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4450888241	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4450788247	LGE	4	25 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4463788188	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4463888176	LGE	3	45 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4451488239	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4451088227	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4463788083	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4460088352	LGE	3	60 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4461988340	LGE	4	35 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4462788332	LGE	4	35 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4457988216	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4457988209	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021 PO2796790002	KU	6	30 BRO	SP	CRE		V		00:00.0
2021 PO4464388167	LGE	2	55 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4001483657	LGE	2	50 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021 PO4006883544	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO5274232381	KU	4	40 UNK	SP	CRE	ID	BX	RP3	00:00.0

2021	PO5307632136	KU	2	65 UNK	SP	CRE		T	00:00.0
2021	PO0794249551	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021	PO4461688354	F	2	60 ACE	SP	CCA		V	00:00.0
2021	PO4007483558	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4006983570	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	4006983570-A	KU	5	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4007983535	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4007483542	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4009983495	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4009783504	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4008583522	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4007983512	LGE	5	25 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4009283518	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4007983544	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO2826789324	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2830189458	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2834089597	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO4463688194	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO2837789718	KU	4	40 BRO	SP	CRE	ED,IP	BD	00:00.0
2021	PO2859089673	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2878289630	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO4008483474	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO0774350029	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021	PO0766950335	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO0765150498	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021	PO2896389786	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO4826425403	KU	4	40 UNK	ST	CCA		V	00:00.0
2021	PO4853325451	KU	4	60 UNK	ST	CCA		V	00:00.0
2021	PO2820889764	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2732190426	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4869925542	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4860225545	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO4015583799	LGE	3	45 BRO	SP	CCA	ED	T	00:00.0
2021	PO4008983478	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO2753890437	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO2767890408	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4878226418	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4880826275	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4887525816	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4885325950	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO4882926128	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4889725670	F	3	40 UNK	SP	CRE		V	00:00.0
2021	PO0757851020	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021	PO0748551069	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0770851142	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0882448384	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO2861590241	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO0769551009	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO4451588227	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4451688217	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4451888208	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO0768150884	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO0781051125	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5325032135	KU	6	30 UNK	SP	CRE		T	00:00.0

2021 PO5344132119	KU	6	30 UNK	SP	CRE		T	00:00.0
2021 PO2819289826	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0755650672	KU	6	30 INP	SP	CRE	ID	TD	00:00.0
2021 PO0766250678	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO2784489863	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2801689816	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO0894548224	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0902847928	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0911448001	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0929047786	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0517656545	KU	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4000183616	LGE	3	60 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3999583606	LGE	3	55 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2847990360	F	4	40 BRO	SP	A		V	00:00.0
2021 PO1625494952	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4452888257	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO5327134403	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO0786449695	F	3	40 UNK	SP	P		V	00:00.0
2021 PO5322834287	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5284132508	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO4001983666	LGE	3	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4003683699	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO3999883647	F	3	45 BRO	SP	A		V	00:00.0
2021 PO3999983649	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4001083670	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4000783665	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4000483657	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3995383632	F	3	45 BRO	SP	A		V	00:00.0
2021 PO3996883631	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3997683638	KU	4	35 BRO	SP	CCA		V	00:00.0
2021 PO3997583631	F	1	50 BRO	SP	A		V	00:00.0
2021 PO3998783627	F	2	55 BRO	SP	A		V	00:00.0
2021 PO3998383620	F	2	55 BRO	SP	A		V	00:00.0
2021 PO4000883645	LGE	2	50 BRO	SP	CCA		V	00:00.0
2021 PO4458288328	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4002483677	LGE	2	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO3999983629	LGE	2	55 BRO	SP	A	ID	BD	00:00.0
2021 PO4460988319	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4449988256	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4450988258	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4450288253	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4451088254	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO2894990149	KU	5	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4448488174	LGE	4	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4447888177	LGE	3	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4447888211	LGE	4	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4453888223	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4449088264	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4448988241	LGE	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4448588291	LGE	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5768928442	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO4447388248	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4453988214	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4447488201	LGE	3	55 ACE	DF	CRE	ED,ID	BD	00:00.0



2021 PO4446788246	LGE	3	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4447088227	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4449288251	LGE	3	55 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4441687988	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4442887994	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5821728240	KU	2	60 UNK	SP	CRE		B	00:00.0
2021 PO4443587968	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO2845989983	KU	3	50 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO5802428370	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5717328505	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO4447988172	LGE	3	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4448488326	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4448088324	LGE	3	45 ACE	SP	CRE	ED,ID,MD	BD	00:00.0
2021 PO5738828680	KU	3	40 UNK	SP	CRE		B	00:00.0
2021 PO2809289676	KU	6	30 BRO	SP	CRE	ED,IP,SRS	BD	00:00.0
2021 PO8948059428	ODP	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO8804559574	ODP	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4003283245	LGE	3	45 BRO	SP	CRE		V	00:00.0
2021 PO8781060323	F	6	30 BRO	SP	S		V	00:00.0
2021 PO0819349138	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4441788126	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO8158878175	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5200734145	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO5195634015	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO5189833867	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5794628361	KU	2	55 UNK	SP	CRE		B	00:00.0
2021 PO4440988126	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4448288311	LGE	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4448588317	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4448488302	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4449388272	LGE	4	25 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4446888237	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5914127933	KU	4	40 UNK	SP	CRE	ED,ID	BX	PX 00:00.0
2021 PO4448588295	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4442688092	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4442488105	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4439888122	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5903627896	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5952527511	KU	4	45 UNK	SP	CRE		B	00:00.0
2021 PO5947127568	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5930927757	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5861028063	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5898827770	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5889027616	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO5897427532	KU	6	30 UNK	SP	CRE		B	00:00.0
2021 PO5896627602	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO5763328585	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO5867127992	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5876127899	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5885727488	KU	2	50 UNK	SP	CRE		B	00:00.0
2021 PO5885227576	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO5877827578	KU	3	50 UNK	SP	CRE		B	00:00.0
2021 PO5867327684	KU	2	50 UNK	SP	CRE		B	00:00.0
2021 PO5986428465	KU	4	40 UNK	SP	CCA		B	00:00.0

2021 PO5978128558	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5970028646	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5962228730	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO5949228874	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO4448788282	LGE	4	45 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4447288217	LGE	3	50 ACE	SP	CRE	ED,ID,RB	TX RR	00:00.0
2021 PO8772059528	ODP	4	40 BRO	SP	S		T	00:00.0
2021 PO4448088326	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8869552346	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4442887970	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7343915384	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO1308144637	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO1281644613	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4571607909	KU	5	35 KOP	SP	CCA	ED,MD	TD	00:00.0
2021 PO7421015399	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7421315622	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7405315608	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7409115869	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7221015201	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7197315528	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7183415715	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7525658941	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO7482015854	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7463615719	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7579258957	KU	3	50 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO7427715176	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7427615003	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO2484420848	KU	4	40 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO2506820855	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2525121048	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2529120852	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4613308019	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0959647612	KU	4	40 BRN	SP	CRE	ID,IP,MD	TD	00:00.0
2021 PO4185885851	LGE	4	35 BRN	SP	P	ID,SR	TD	00:00.0
2021 PO0902547853	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4540207719	KU	6	30 BRN	SP	CCA	ED,MD	TD	00:00.0
2021 PO7593359308	KU	6	30 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO4543207821	KU	6	30 KOP	SP	CCA	ED,MD	TD	00:00.0
2021 PO7586858913	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4608407940	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4619807823	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4186585883	LGE	4	30 BRN	SP	P	ED,HH,ID	BX RP2	00:00.0
2021 PO4184385685	LGE	3	55 BRN	SP	P	ED,ID,IP	BX RR	00:00.0
2021 PO3445298352	KU	6	30 BRN	SP	CRE	ED,ID	BX PX	00:00.0
2021 PO3447198613	KU	7	35 BRN	SP	CRE	ED,ID	BX PX	00:00.0
2021 PO4169086037	LGE	4	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0887647936	KU	4	40 BRN	SP	CRE		BD	00:00.0
2021 PO4183785618	LGE	3 55E	BRN	SP	P	ID,SRS	BD	00:00.0
2021 PO4188186034	LGE	4	30 BRN	SP	P	ID	BD	00:00.0
2021 PO7586759767	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021 PO1388344121	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4132985973	LGE	3	55 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4516607762	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4185985835	LGE	1	65 BRN	SP	CRE	ID	BD	00:00.0

2021 PO4185985819	LGE	1	70 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4185685779	LGE	1	85 BRN	SP	CRE	ID	BD		00:00.0
2021 PO7588259272	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO1298344959	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4551607637	KU	4	40 XXX	SP	CRE	ID,IP	BD		00:00.0
2021 PO4604207448	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO9372763103	KU	4	40 BRO	SP	CRE	EP	VX	RP3	00:00.0
2021 PO9384763511	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9331563508	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9247063487	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9156963514	KU	4	40 BRO	SP	CRE	ED,EP	VX	RP2	00:00.0
2021 PO9253663674	KU	5	35 BRO	SP	CRE	ED,HH,ID,IP	X	RP2	00:00.0
2021 PO9247063487-A	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO9274963494	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4147386185	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7786461490	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7737561700	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7740761761	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7722961815	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7718061929	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7717562032	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7727662171	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7741262298	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7746762370	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7751062303	KU	5	35 BRO	SP	CRE	ED,HH,ID	BX	RP2	00:00.0
2021 PO4147286177	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7808261737	KU	3	40 BRO	SP	CCA		V		00:00.0
2021 PO7811061707	KU	3	40 BRO	SP	CCA		V		00:00.0
2021 PO7809661722	KU	3	50 BRO	SP	CCA		V		00:00.0
2021 PO7837361885	KU	3	50 BRO	SP	CRE		V		00:00.0
2021 PO7775262448	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO7818562489	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO7798962211	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO7839161871	KU	3	40 BRO	SP	CRE		V		00:00.0
2021 PO7804361672	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7761161483	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4148086165	LGE	3	50 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4147786159	F	3	45 BRO	SP	A		V		00:00.0
2021 PO7746261401	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7773761334	F	6	30 BRO	SP	CRE		V		00:00.0
2021 PO7763061348	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7734861498	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7720361476	F	6	30 BRO	SP	CRE		V		00:00.0
2021 PO2575016163	KU	4	45 BRN	SP	CRE		V		00:00.0
2021 PO2576015931	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO2576615632	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4154986232	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4154986228	F	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4155786222	LGE	3	55 BRO	SP	P		V		00:00.0
2021 PO9846863639	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9873163633	KU	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7657162027	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7660961927	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7664161826	F	4	40 BRO	SP	CRE		V		00:00.0

2021 PO7666661745	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3797319108	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3832218906	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3816418951	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3825519265	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3820519006	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3818719172	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3845318947	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3828018855	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3839518759	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3855619046	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3809019014	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3799319178	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3857318945	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3847918775	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3833818807	F	4	40 KOP	SP	P		V	00:00.0
2021 PO7671761594	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7658461758	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4789601940	F	4	40 BRN	SP	CRE	ED,ID,IP,RB	V	00:00.0
2021 PO9796662481	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9814162441	KU	4	40 BRO	SP	CRE	ED,EP,ID,IP	BD	00:00.0
2021 PO9824862629	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO7668861677	F	4	40 BRO	SP	CRE		V	00:00.0
2021 7657162027A	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO4765701469	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO7643161655	KU	4	45 BRO	SP	S		V	00:00.0
2021 PO4698003998	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4789302755	KU	2	65 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4750503288	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4818402372	F	2	55 BRN	SP	P		V	00:00.0
2021 PO4848302822	F	2	50E BRN	SP	CRE		V	00:00.0
2021 PO4738103453	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4776001685	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4803202558	KU	3	50 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4721404386	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4837702673	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4725803615	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4797802052	F	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4722203664	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4830802559	F	4	40E BRN	SP	CRE		V	00:00.0
2021 PO4807102195	F	3	40 BRN	SP	P		V	00:00.0
2021 PO4783501839	F	4	40 BRN	SP	CRE	ED,MD	V	00:00.0
2021 PO4770901578	F	4	50 BRN	SP	CRE		V	00:00.0
2021 PO4769103032	KU	2	65 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4752103260	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO7645561731	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9824862629-A	KU	4	40 BRO	SP	CRE	ED,EP,ID	BD	00:00.0
2021 PO9904261944	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9879862161	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3853518278	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3839618040	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3882318377	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3836618112	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3854318540	F	4	40 KOP	SP	P		V	00:00.0

2021 PO3882218244	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3891918339	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3858418442	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3846418269	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3901618032	F	4	45 KOP	SP	P		V	00:00.0
2021 PO3861618546	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3882718565	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3897218117	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3855518055	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3978917974	F	4	40 BRO	SP	P		V	00:00.0
2021 PO3873118667	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3940717984	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3850618418	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3870218051	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3858918695	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3925618036	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO3936717915	F	5	35 KOP	SP	P		V	00:00.0
2021 PO3911318084	F	4	40 KOP	SP	P		V	00:00.0
2021 PO4709903833	KU	3	45 BRN	SP	CRE	ED,ID,IP	TX RR	00:00.0
2021 PO3868818129	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3890218640	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3885518044	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3962017973	F	4	45 KOP	SP	CRE		V	00:00.0
2021 PO2576015433	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2576415171	KU	3	50 BRN	SP	CRE		V	00:00.0
2021 PO1794243131	KU	5	20 BRN	SP	CRE		V	00:00.0
2021 PO1656243739	KU	3	40 BRN	SP	CRE		V	00:00.0
2021 PO1549645220	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO1529844583	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO1512345084	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO1457644627	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO1722644890	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO1496347630	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2238934996	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO1445147571	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2230334882	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO7580261356	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7586261435	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7598561429	KU	4	45 BRO	SP	A		V	00:00.0
2021 PO7597561438	F	4	40 BRO	SP	A		V	00:00.0
2021 PO7613761437	F	4	40 BRO	SP	A		V	00:00.0
2021 PO7628761445	F	4	40 BRO	SP	A		V	00:00.0
2021 PO7662861344	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7658661461	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7643761453	F	5	40 BRO	SP	A		V	00:00.0
2021 PO4146986149	LGGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO9936861434	KU	4	40 BRO	SP	CRE		B	00:00.0
2021 PO9923161249	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9909961039	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4145984969	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4147384969	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4148884967	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4147184953	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4147784952	F	4	30 ACE	SP	P		V	00:00.0

2021 PO4147084936	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4147584936	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4146984922	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4147484922	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4147184906	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4147684906	F	4	30 ACE	SP	P		V	00:00.0
2021 PO7674561507	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7683361539	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4147986136	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PV8626773326	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO7682261595	F	4	40 BRO	SP	S		V	00:00.0
2021 PO7679661668	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7677261701	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7695361584	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7707761634	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7706661749	KU	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7716061724	F	6	30 BRO	SP	CRE		V	00:00.0
2021 PO7718061673	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7726961702	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4150584896	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4149884913	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4150384928	F	5	35 ACE	SP	P		V	00:00.0
2021 PO4149784927	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4149684942	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4150784956	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4151284963	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4151584977	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4152084975	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4152284979	F	7	30 ACE	SP	CRE		V	00:00.0
2021 PO7720461531	F	4	40 BRO	SP	A		V	00:00.0
2021 PO7709761477	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7768861680	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7759861707	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO7792861937	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4149786172	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4155186307	LGE	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9051362750	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9067363501	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9034163535	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9035163097	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9019563177	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8724482714	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4151586169	LGE	4	35 BRO	SP	CCA	ED,ID	BD	00:00.0
2021 PO4150986117	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4657604593	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4627404721	KU	4	40 BRN	SP	CCA	ED	TD	00:00.0
2021 PO4641004805	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 PO4381984946	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4380484946	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4380785190	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4269686461	LGE	1	50 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4266786464	LGE	2	55 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4263286474	LGE	1	55 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4374785114	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	00:00.0

2021 PO4374984952	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4383885215	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4374284951	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4264786583	LGE	3	50 BRO	SP	A	ED,ID	BD		00:00.0
2021 PV4265686648	LGE	1	65 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4264486557	LGE	3	50 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9995279012	LGE	4	35 BRO	SP	CCA	ED,ID	BD		00:00.0
2021 PV4265886668	LGE	1	65 BRO	SP	A	ED,ID	BD		00:00.0
2021 PO8879597628	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,RB	BX	RP1	00:00.0
2021 PO7387701973	KU	4	40 UNK	SP	CRE	ED,HH,ID	X	RP2	00:00.0
2021 PO4268886610	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4271286612	LGE	4	40 BRO	SP	A	ED,ID	BD		00:00.0
2021 PO4526087639	F	4	40 BRO	SP	CRE	ED,HH,ID,IP,RB	VX	RP1	00:00.0
2021 PO8853797367	KU	4	40 XXX	SP	CRE	ED,EP,ID,IP,RB	BX	RP1	00:00.0
2021 PO7568107509	KU	2	45 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4379584946	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7446500737	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7488504001	KU	3	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5482711136	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021 PO5519211055	KU	6	30 KOP	SP	CRE		BD		00:00.0
2021 PO5644913233	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021 PO5538811935	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021 PO7453807959	F	3	45 XXX	SP	CRE	ED,ID,IP,MD,RB	BX	PX	00:00.0
2021 9674698384A	KU	3	45 BRO	SP	CRE	ID	BD		00:00.0
2021 PO0493451779	KU	5	35 BRN	SP	CCA		T		00:00.0
2021 PO4470988103	LGE	1	70 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4470388097	LGE	1	65 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO0518251781	KU	6	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4469788091	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4469788091	KU	1	50 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO5637122566	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021 PO5643022495	KU	5	35 UNK	SP	CRE		BD		00:00.0
2021 PO5658522304	KU	5	35 UNK	SP	CRE		T		00:00.0
2021 PO5643522560	F	4	40 UNK	SP	A		V		00:00.0
2021 PO5638522623	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO5657222395	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO5650922398	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO5664722248	KU	4	40 UNK	SP	CRE		T		00:00.0
2021 PO0512051668	KU	6	30 BRN	SP	CRE		T		00:00.0
2021 PO0516851727	KU	3	45 BRN	SP	S		T		00:00.0
2021 PO0527851697	KU	6	30 UNK	SP	CRE	ID	TD		00:00.0
2021 PO0533051594	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO5670921770	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021 PO5668821807	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO5663521793	KU	6	30 UNK	SP	CRE		BD		00:00.0
2021 PO5673221730	KU	4	40 UNK	SP	CRE		T		00:00.0
2021 PO5670521649	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021 PO5659321758	KU	6	30 UNK	SP	CCA		V		00:00.0
2021 PO5639822038	KU	6	30 UNK	SP	CCA		V		00:00.0
2021 PO5615622338	KU	5	35 UNK	SP	CCA		V		00:00.0
2021 PO5748820302	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO5741320324	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO5735620342	F	4	40 UNK	UN	CRE		V		00:00.0
2021 PO5724321267	KU	5	35 UNK	SP	CRE		V		00:00.0

2021 PO5725921646	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021 PO8317480914	KU	3	45 ACE	SP	CRE	ED,HH,ID,RB	VX	PX	00:00.0
2021 PO8296379726i	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO8296379726a	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4083885182	LGE	1	55 BRO	SP	CRE	ED,EP,ID,IP	BX	RP2	00:00.0
2021 PO8296379726d	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO5738023991	KU	2	40 UNK	SP	CRE	ED,ID	BX	RP2	00:00.0
2021 PO5662523626	KU	6	30 UNK	SP	A	ED,ID	X	PX	00:00.0
2021 PO8296379726f	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4465488106	LGE	4	40 BRO	SP	P	ED,EP,ID,RB	TX	RR	00:00.0
2021 PO4464788132	LGE	4	40 BRO	SP	P	ED,ID,IP,RB	BX	RP2	00:00.0
2021 PO4455787684	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8169682766	KU	3	40 ACE	SP	P		V		00:00.0
2021 PO8171882613	KU	2	45 ACE	SP	CCA		V		00:00.0
2021 PO4474588153	LGE	1	75 ACE	SP	CRE		V		00:00.0
2021 PO4473988153	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO4473188153	LGE	1	75 ACE	SP	CRE		V		00:00.0
2021 PO4476588152	LGE	1	75 ACE	SP	CRE		V		00:00.0
2021 PO4477388152	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4478888151	LGE	3	75 ACE	SP	CRE		V		00:00.0
2021 PO4480588151	LGE	1	75 ACE	SP	CRE		V		00:00.0
2021 PO4467288144	F	4	40 BRO	SP	P		V		00:00.0
2021 PO4465588143	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4465688135	LGE	4	30 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4464788143	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4465688095	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4465188117	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4465988086	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4466288073	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4481888151	LGE	1	75 ACE	SP	CRE		V		00:00.0
2021 PO8397263354	ODP	3	45 XXX	SP	CCA		V		00:00.0
2021 PO8405763243	ODP	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO8644357847	ODP	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4483388150	LGE	1	75 ACE	SP	CRE		V		00:00.0
2021 PO8172882431	KU	2	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8159482361	KU	3	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4486988150	LGE	1	75 ACE	SP	CRE		V		00:00.0
2021 PO4485388150	LGE	1	75 ACE	SP	CRE		V		00:00.0
2021 PO4491488077	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4490788089	LGE	4	30 ACE	SP	A		V		00:00.0
2021 PO4457287683	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD		00:00.0
2021 PO4460087688	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4489988101	LGE	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4489588108	LGE	4	35 ACE	SP	A		V		00:00.0
2021 PO4457488029	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO7998260096	ODP	4	45 BRN	SP	S		V		00:00.0
2021 PO4456888043	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4456688049	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4455888072	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4454788102	LGE	4	35 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4454288115	LGE	4	35 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4453888126	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4453188144	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4452788155	LGE	4	35 BRO	SP	P	ED,ID,IP	TD		00:00.0



2021 PO3926685942	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3988286414	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4489088112	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4488588122	LGE	4	35 ACE	SP	A		V	00:00.0
2021 PO7963660558	ODP	4	40 BRN	SP	S		V	00:00.0
2021 PO8187761040	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7991960798	ODP	4	40 BRN	SP	CRE	ED,ID,IP,SR	TD	00:00.0
2021 PO8620757804	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8614357904	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8529860954	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8530160847	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8546160748	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8541760675	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8553060614	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8536360530	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8547560480	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8526460497	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8517360465	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8507060424	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4467388155	LGE	3	45 BRO	SP	A	ED,ID,IP	BD	00:00.0
2021 PO4466788156	LGE	1	75 BRO	SP	P		V	00:00.0
2021 PO4466188156	LGE	3	45 BRO	SP	CRE	ED,EP,ID,MD	BD	00:00.0
2021 PO4465688156	LGE	3	50 BRO	SP	CCA	ED,ID	BD	00:00.0
2021 PO4464688156	LGE	1	80 BRO	SP	P		V	00:00.0
2021 PO4463888157	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4463088157	LGE	1	80 BRO	SP	P		V	00:00.0
2021 PO4462588157	LGE	3	50 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0498647508	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0500547242	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0504346619	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4512788120	LGE	4	45 ACE	SP	A	ED,ID,MD	BD	00:00.0
2021 PO4512288128	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO0494848020	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5690423443	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5674823637	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO4462088158	LGE	3	45 BRO	SP	CCA	ED,ID	BD	00:00.0
2021 PO4461188158	LGE	1	80 BRO	SP	P		V	00:00.0
2021 PO4460688158	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4459588159	LGE	3	50 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4458988159	LGE	1	80 BRO	SP	P		V	00:00.0
2021 PO4458088159	LGE	3	50 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4457788159	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4460887678	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5663923631	KU	3	45 UNK	SP	CRE		T	00:00.0
2021 PO5664723691	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PV4516188136	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4516788132	LGE	1	95 ACE	SP	CRE		V	00:00.0
2021 PO4458287734	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO8346278595c	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8346278595b	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8346278595a	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8346278595	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5661523814	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO5659623799	KU	2	60 UNK	SP	CRE		BD	00:00.0

2021 PO4457288159	LGE	1	80 BRO	SP	P		V	00:00.0
2021 PO4456588159	LGE	4	40 BRO	SP	A	ED,EP,ID,MD	BD	00:00.0
2021 PO4456288160	LGE	3	45 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4456688119	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4456488129	F	4	40 BRO	SP	P		V	00:00.0
2021 PO5670424444	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5678224206	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5678124041	KU	3	45 UNK	SP	CRE		BD	00:00.0
2021 PO4456587752	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4518188114	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4517088112	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5666823955	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5688824080	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO4516588117	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5656923875	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO4456387753	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4456287744	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4455487739	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8376079106	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5654023764	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5653323872	KU	2	40 UNK	SP	CRE		BD	00:00.0
2021 PO5647023950	KU	1	75 UNK	SP	CRE	ED	BD	00:00.0
2021 PO5646623855	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4516088110	LGE	4	25 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8195282267	F	6	30 ACE	SP	CRE		V	00:00.0
2021 PO5753423986	KU	6	30 UNK	SP	CRE		V	00:00.0
2021 PO4010185091	F	5	30 BRO	SP	A		V	00:00.0
2021 PO4006085351	LGE	4	35 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4021185490	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4063385304	LGE	6	25 BRO	SP	CRE		V	00:00.0
2021 PO4054285256	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4070685385	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4084785177	LGE	1	90 BRO	SP	A		V	00:00.0
2021 PO4084685176	LGE	2	55 BRO	SP	CRE		V	00:00.0
2021 PO4080985129	LGE	1	85 BRO	ST	CRE		V	00:00.0
2021 PO4080385133	LGE	1	80 BRO	ST	CRE		V	00:00.0
2021 PO4065284533	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4115385889	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4196586315	LGE	3	45 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4000984048	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4004684108	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5773724043	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5778024008	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO5772623964	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO5764323906	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO5753323826	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO4497288078	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4496288072	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO4021083694	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4019783678	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO0146637946	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0230239216	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0278839465	KU	5	35 BRN	SP	CCA		T	00:00.0
2021 PO0266539532	KU	3	45 BRN	SP	CCA		V	00:00.0

2021	PO0146637806	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO0251140283	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO0243339497	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO0292239570	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO0175838288	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5770223998	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO5751924211	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5750324233	F	4	45 UNK	SP	CRE		V	00:00.0
2021	PO5743724302	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO8279682374	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5760624200	KU	3	50 UNK	SP	CCA		V	00:00.0
2021	PO5764624151	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021	PO5759924122	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO8334882400	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4495388067	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4495488069	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4491788069	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4492888052	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4014683670	LGE	5	25 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5734624208	KU	6	30 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5740824136	KU	6	30 UNK	SP	CRE	ED	BD	00:00.0
2021	PO4014983676	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4016183669	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4017483661	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO5723724297	KU	6	35 UNK	SP	CRE		T	00:00.0
2021	PO5712724198	KU	5	30 UNK	SP	CRE		BD	00:00.0
2021	PO8175682295	F	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8178682022	F	4	40 ACE	SP	P		V	00:00.0
2021	PO8179581947	F	2	60 ACE	SP	CCA		V	00:00.0
2021	PO8181381776	F	5	35 ACE	SP	P		V	00:00.0
2021	PO8177482129	F	5	35 ACE	SP	P		V	00:00.0
2021	PO5718524130	KU	5	30 UNK	SP	CRE		BD	00:00.0
2021	PO5723824155	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021	PO5724324060	KU	5	30 UNK	SP	CRE		T	00:00.0
2021	PO8159282128	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8160581955	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8156181951	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4023383724	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO8182381713	F	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8184381507	F	3	40 ACE	SP	CCA		V	00:00.0
2021	PO8185581396	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO8188181175	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4489888060	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5740723856	KU	3	45 UNK	SP	CRE		T	00:00.0
2021	PO0508146025	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO4518388130	LGE	1	55 ACE	SP	CRE	ED,ID,MD	BD	00:00.0
2021	PO8505660638	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8508160230	F	4	40 XXX	SP	P		V	00:00.0
2021	PO8509260070	F	4	40 XXX	SP	P		V	00:00.0
2021	PO8509159944	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO8508859792	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO8509659684	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO8510259564	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO8491059089	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0

2021 PO8511459310	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8512259124	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8513358871	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4159786047	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TX RR	00:00.0
2021 PO4083886654	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3982885620a	KU	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3982885620	F	4	35 ACE	SP	P		V	00:00.0
2021 PO3983485611	KU	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4084786664	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4158086047	LGE	2	55 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4157086048	LGE	2	60 BRO	SP	CCA		V	00:00.0
2021 PO3982085600	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO3982685596	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4032186202	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4032886211	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4156486048	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4155786049	LGE	2	95 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4154686049	LGE	2	55 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4033786218	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4034086224	LGE	4	35 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4039486244	LGE	4	35 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4039886248	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4040886258	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7547274348	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4042186271	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4042686282	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4043386282	LGE	3	55 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4177686038	LGE	2	55 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4923425573	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO4933225590	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO4974225661	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO4981125672	KU	2	55 UNK	ST	CRE		V	00:00.0
2021 PO4964225642	KU	3	55 UNK	SP	CRE		T	00:00.0
2021 PO3975586167	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO3974386174	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4011586497	KU	3	45 ACE	SP	P	ID	TD	00:00.0
2021 PO3968785677	LGE	4	30 ACE	SP	P		V	00:00.0
2021 PO4043986287	LGE	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4045286301	LGE	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4048586282	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4047586283	LGE	2	55 ACE	SP	A		V	00:00.0
2021 PO4045086284	LGE	2	80 ACE	SP	CRE		V	00:00.0
2021 PO4045286287	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PV7517573938	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4037786228	LGE	2	55 ACE	SP	CRE	ED,EP,ID,RB	VX PX	00:00.0
2021 PO4039086241	LGE	3	50 ACE	SP	A	ID	TD	00:00.0
2021 PO4038286234	LGE	3	50 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4036986230	LGE	2	55 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4035086235	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4037086238	LGE	4	35 ACE	SP	A	ID	TD	00:00.0
2021 PO4029186252	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4998725706	KU	2	55 UNK	SP	CRE		B	00:00.0
2021 PO4989725690	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO4943525609	KU	3	50 UNK	ST	CRE		V	00:00.0

2021 PO3989285700	LGE	1	20 ACE	SP	CCA		V	00:00.0	
2021 PO7355677946	LGE	1	50 ACE	SP	CCA		V	00:00.0	
2021 4021486610A	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO4021086596	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4021886606	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO5050725797	KU	6	30 UNK	SP	CRE		T	00:00.0	
2021 PO4021486610	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4019486587	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4020486598	LGE	UNK	55 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5042325782	KU	3	55 UNK	SP	CRE		T	00:00.0	
2021 PO5058225811	KU	3	55 UNK	ST	CRE		V	00:00.0	
2021 PO4021685922	LGE	7	30 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4024685917a	KU	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4019986583	F	4	40 ACE	SP	A		V	00:00.0	
2021 PO5008125724	KU	5	35 UNK	SP	CRE		B	00:00.0	
2021 PO5016825742	KU	2	50 UNK	ST	CRE		V	00:00.0	
2021 PO4017986570	LGE	1	55 ACE	SP	CCA		V	00:00.0	
2021 PO5027525763	KU	4	40 UNK	SP	CRE		B	00:00.0	
2021 PO4023885943	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4023285931	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4022585918	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4024685917	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4024685911	LGE	1	20 ACE	SP	A		V	00:00.0	
2021 PO7383570741	LGE	1	20 ACE	SP	CCA		V	00:00.0	
2021 PO5400234296	KU	4	40 BRO	SP	CCA		B	00:00.0	
2021 PO4020386621	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4019986629	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4146085960	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO5075325957	KU	6	30 UNK	SP	CRE		T	00:00.0	
2021 PO5397034348	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO5387434422	KU	3	45 BRO	SP	CRE	ID	TX	RR	00:00.0
2021 PO4037786239	LGE	4	30 ACE	SP	P	ED,ID,IP	BD	00:00.0	
2021 PO4044286567	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4044186575	LGE	3	45 ACE	SP	S		V	00:00.0	
2021 PO5065325823	KU	4	40 UNK	SP	CRE		T	00:00.0	
2021 PO4005585842	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO5397934595	KU	4	40 BRO	SP	CRE	ID	BX	RP2	00:00.0
2021 PO5401134584	KU	2	40 BRO	SP	CRE	ID	TD	00:00.0	
2021 PO5406934563	KU	3	45 BRO	SP	CRE	ID	TD	00:00.0	
2021 PO4006685836	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5077625846	KU	2	55 UNK	SP	CRE		B	00:00.0	
2021 PO5238408380	F	5	35 KOP	SP	CRE		V	00:00.0	
2021 PO5257208364	KU	3	40 ACE	SP	CRE	ED	TD	00:00.0	
2021 PO5091825868	KU	4	35 UNK	SP	CCA		T	00:00.0	
2021 PO5100625884	KU	3	55 UNK	ST	CRE		V	00:00.0	
2021 PO5229408474	KU	3	40 ACE	SP	CRE	ED,ID,MD	TD	00:00.0	
2021 PO4007785829	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4008385826	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4008785823	LGE	5	35 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO4145685967	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4180586037	LGE	2	100 BRO	ST	P		V	00:00.0	
2021 PO4179286038	LGE	2	55 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4178686030	LGE	4	35 BRO	SP	CCA	ED	T	00:00.0	
2021 PO4067886517	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	

2021	4068286512	LGE	5	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3994785763	F	6	25 ACE	SP	CRE		V	00:00.0	
2021	PO3995385769	F	3	45 ACE	SP	CCA		V	00:00.0	
2021	4067086522A	LGE	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO4067086522	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3996285762	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO5191426033	KU	2	40 UNK	SP	CRE		T	00:00.0	
2021	PO5177126010	KU	3	55 UNK	ST	CRE		V	00:00.0	
2021	PO3997285755	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO3998285747	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO3999185741	F	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO4000185734	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO4001185727	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO4002185720	F	4	35 ACE	SP	CRE		V	00:00.0	
2021	PO4003185713	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO5167825994	KU	4	40 UNK	SP	CRE		B	00:00.0	
2021	PO4167286043	LGE	2	55 BRO	SP	CCA		V	00:00.0	
2021	PO4065386528	LGE	4	35 ACE	SP	CRE		V	00:00.0	
2021	PO4066286534	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4168186043	LGE	2	55 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4166686043	LGE	2	55 BRO	SP	A	ED,ID	TD	00:00.0	
2021	PO5405034487	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0	
2021	PO5155725972	KU	1	50 UNK	SP	CRE		T	00:00.0	
2021	PO4166686036	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	4068886529A	LGE	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4068886529	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4069786539	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4165786044	LGE	2	95 BRO	SP	CRE	ID	BD	00:00.0	
2021	PO4165686035	LGE	4	30 BRO	SP	CRE		V	00:00.0	
2021	PO5243108420	KU	3	40 ACE	SP	CRE		B	00:00.0	
2021	PO4032186238	LGE	4	30 ACE	SP	CRE	ED,HH,ID,MD	X	PX	00:00.0
2021	PO4032386243	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO4033686239	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO4030786247	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO4030686242	LGE	4	35 ACE	SP	A	ED,ID	BX	RP2	00:00.0
2021	PO7429773937	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021	PO4030186243	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0	
2021	PO5142925950	KU	3	55 UNK	ST	CRE		V	00:00.0	
2021	PO4002985706	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021	PO7187768908	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO4004285713	F	4	35 ACE	SP	CCA		V	00:00.0	
2021	PO4004285705	F	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO4004585692	F	6	25 ACE	SP	CRE		V	00:00.0	
2021	PO4004985699	F	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO4070086544	LGE	UNK	45 ACE	SP	CRE	ED,ID	BX	RP3	00:00.0
2021	PO4069386548	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021	PO4069486560	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4070286554	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4070686550	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO4071386558	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7822577476	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021	PO4070786566	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4071986566	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO4072286570	LGE	4	40 ACE	SP	CCA		V	00:00.0	

2021 PO4072086560	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5128925930	KU	3	55 UNK	SP	CRE		T	00:00.0
2021 PO5120525916	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO4002086385	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4000786399	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4005986167	LGE	4	40 ACE	SP	P		V	00:00.0
2021 PO4004786171	LGE	4	40 ACE	SP	P	ID	BD	00:00.0
2021 PO4003686176	LGE	4	40 ACE	SP	A	ID	BD	00:00.0
2021 PO4006286226	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4009086297a1	KU	4	30 ACE	SP	P	ID	BD	00:00.0
2021 PO4009086297	LGE	4	30 ACE	SP	A	ID	TD	00:00.0
2021 PO4007686318	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4008386325	LGE	4	30 ACE	SP	A	ID	BD	00:00.0
2021 PO4009786318	LGE	4	35 ACE	SP	CRE	ID	TD	00:00.0
2021 PO4010486339	LGE	4	35 ACE	SP	CRE	ID	TD	00:00.0
2021 PO4009286346	LGE	4	30 ACE	SP	CRE	HH,ID	TD	00:00.0
2021 PO3975385809	LGE	2	65 ACE	SP	A		V	00:00.0
2021 PO3973885790	LGE	2	65 ACE	SP	A		V	00:00.0
2021 PO4073386576	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4073186581	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5279508365	F	5	40 KOP	SP	CRE		V	00:00.0
2021 PO3990385711	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4072386588	LGE	UNK	45 ACE	SP	CCA		V	00:00.0
2021 PO4072586590	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO7851077949	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO7839177933	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO7833877837	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4071286593	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5281508200	KU	7	35 ACE	SP	CCA		V	00:00.0
2021 PO5221108507	KU	4	45 ACE	SP	CRE	ED	TD	00:00.0
2021 PO5272608304	KU	3	40 KOP	SP	CCA		V	00:00.0
2021 PO5286408251	KU	3	45 KOP	SP	CRE	ED	TD	00:00.0
2021 PO5377234464	KU	6	30 BRO	SP	CCA		T	00:00.0
2021 PO4008385902	LGE	4	35 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4979013313	KU	3	50 KOP	SP	S	ED,ID	V	00:00.0
2021 PO5143608594	KU	5	40 ACE	SP	CRE	SRC	TD	00:00.0
2021 PO5162208733	KU	5	45 ACE	SP	CRE	ID	BD	00:00.0
2021 PO4038186587	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4993613361	KU	2	60 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO5005113220	KU	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4009185910	LGE	4	35 ACE	SP	P	ED,HH,ID,MD,RB	BX	RP1 00:00.0
2021 PO4001885854	LGE	7	25 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1 00:00.0
2021 PO5154608704	F	6	40 ACE	SP	CCA		V	00:00.0
2021 PO4003385855	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4002285862	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4033285778	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO5155808543	KU	7	35 ACE	SP	CRE		B	00:00.0
2021 PO5261432484	KU	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5313422447	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4182386036	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO5141108814	KU	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO5142408850	KU	7	30 ACE	SP	P	ED	TD	00:00.0
2021 PO4967413108	KU	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4006785905	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0

2021 PO4043486576	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7551777436	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4041486581	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5151408773	KU	5	40 ACE	SP	CRE	ID	BD	00:00.0
2021 PO4037286589	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4039086586	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4041186185	LGE	4	30 KOP	SP	P	ED,ID,MD	TD	00:00.0
2021 PO4081585730	LGE	4	30 ACE	SP	A	ID	TD	00:00.0
2021 PO5243432624	KU	3	50 BRO	SP	CRE	ID	TD	00:00.0
2021 PO5240332647	KU	2	50 BRO	SP	CCA		B	00:00.0
2021 PO5393233884	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5383033973	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO5388034109	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5394434161	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5391934095	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5390034042	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5393134266	KU	4	40 BRO	SP	CRE	ID	BX	RP2 00:00.0
2021 PO5368834498	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4035686591	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4037986544	F	UNK	45 ACE	SP	CRE		V	00:00.0
2021 PO4039886520	LGE	UNK	45 ACE	SP	CRE		V	00:00.0
2021 PO4035086203	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4150686059	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4082785779	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4082785789	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4082885808	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4083685805	F	7	25 ACE	SP	CRE		V	00:00.0
2021 PO4074685839	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4075185841	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4075285853	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4075285866	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4074885872	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4079385932	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4074985885	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4082485924	LGE	4	40 ACE	SP	P		V	00:00.0
2021 PO4082085925	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4082085930	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4080685926	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4080085926	F	6	30 ACE	SP	P		V	00:00.0
2021 PO4080785931	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4109385581	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4111985569	LGE	6	25 ACE	SP	CRE	ED,ID	V	00:00.0
2021 PO4112785575	LGE	3	45 ACE	SP	CRE	ED,HH,ID,IP,RB	BD	00:00.0
2021 PO4112985574	LGE	6	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8449707268	KU	5	35 UNK	SP	CCA	ID,IP,SRS	TD	00:00.0
2021 PO8451107083	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO8446707002	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8435406970	KU	6	30 UNK	SP	CRE	ID,SRS	TD	00:00.0
2021 PO8549507386	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO4171949355	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4194349740	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO6188711288	F	4	40 ACW	SP	P		V	00:00.0
2021 PO4088085225	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4121585187	LGE	4	40 ACE	SP	CCA		V	00:00.0



2021 PO6114010193	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO3919542050	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO8583108312	KU	6	30 UNK	SP	CRE		V	00:00.0	
2021 PO3721069295	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO4004785368	LGE	4	30E ACE	SP	P	ID	BD	00:00.0	
2021 PO4003585367	LGE	5	35E ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4003285372	LGE	4	30E ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO8670207720	KU	5	35 UNK	SP	CCA		V	00:00.0	
2021 PO8684607630	KU	6	30 UNK	SP	CCA		V	00:00.0	
2021 PO4045485304	LGE	2	75 ACE	SP	CRE		V	00:00.0	
2021 PO4046985305	LGE	2	75 ACE	SP	CRE		V	00:00.0	
2021 PO4048085305	LGE	2	75 ACE	SP	CRE		V	00:00.0	
2021 PO4141785106	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO8672607573	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO8662707496	KU	6	30 UNK	SP	CRE	ID,IP	TD	00:00.0	
2021 PO8673607477	F	5	30 UNK	SP	A		V	00:00.0	
2021 PO4049085304	LGE	2	35E ACE	SP	CRE		V	00:00.0	
2021 PO5806910358	KU	3	45 ACW	SP	CRE	ED,EP,HH,ID,IP,MD,RB	X	RP1	00:00.0
2021 PO4050385303	LGE	2	45E ACE	SP	CRE	ID	BD	00:00.0	
2021 PO5820710177	KU	5	35 ACW	SP	S		V	00:00.0	
2021 PO4015284989	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO5860410271	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4013884995	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4012785008	F	3	45 BRO	SP	CRE		V	00:00.0	
2021 PO4011785019	F	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO4010985029	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4009885035	LGE	4	30 BRO	SP	CRE	ED	TD	00:00.0	
2021 PO4010185039	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4010185051	F	5	35 BRO	SP	CRE		V	00:00.0	
2021 PO8625007250	KU	3	45 UNK	SP	CRE		V	00:00.0	
2021 PO8616907176	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO8618407028	F	4	45 UNK	SP	A		V	00:00.0	
2021 PO4014285095	F	5	30 BRO	SP	CRE		V	00:00.0	
2021 PO4014685090	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4017685006	F	5	35 BRO	SP	A		V	00:00.0	
2021 PO4016985008	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4016185018	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4053585301	LGE	2	75E ACE	SP	CRE		V	00:00.0	
2021 PO5876810320	F	4	35 ACW	SP	S		V	00:00.0	
2021 PO5878510441	KU	4	40 ACW	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5878210336	KU	4	40 ACW	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5882709994	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO5869810022	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO5870310241	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO5870510268	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO5877610265	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5893010260	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO6009710414	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5929910136	KU	5	35 ACW	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO3961642044	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO3963441826	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO3975941835	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO3809647368	KU	2	50 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4015385103	F	5	30 BRO	SP	CCA		V	00:00.0	

2021 PO4111185223	LGE	4	40 ACE	SP	A	ID	TD	00:00.0
2021 PO4015685097	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4106685197	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4016785108	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4016885100	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4017585102	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3722669071	KU	4	40 KOP	SP	CRE		B	00:00.0
2021 PO3714468469	KU	6	30 ACW	SP	CRE	ID	TD	00:00.0
2021 PO4056285300	LGE	2 75E	ACE	SP	CRE		V	00:00.0
2021 PO4017085028	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4017585036	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4016685044	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4016085037	F	5	35 BRO	SP	CRE	ED,ID	VX RP3	00:00.0
2021 PO4060585366	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3814147364	KU	3	55 BRN	SP	CCA		V	00:00.0
2021 PO3896047438	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO8559007468	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 4015885053A	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4015185062	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4013585081	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4014385071	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4012785075	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4012185083	F	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4011585093	F	5 25E	BRO	SP	CRE		V	00:00.0
2021 PO4012985089	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4060285350	LGE	4	40 ACE	SP	CRE	ED	TD	00:00.0
2021 PO8522707710	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO4012485097	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4011285107	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4012185108	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4011885132	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4010885132	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4012085120	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4013285140	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4013285133	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4014085127	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4014585123	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4011585168	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO8551707781	F	4	40 UNK	SP	CCA		V	00:00.0
2021 PO8560807892	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO4060885296	LGE	2	80 ACE	SP	CRE		V	00:00.0
2021 PO7755464717	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4064885278	LGE	2 30E	ACE	SP	CRE		V	00:00.0
2021 PO4005285346	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO7202565185	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8566208339	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO8552608334	KU	6	30 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO4107085190	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4060784465	LGE	4	45 BRO	SP	A	ED	TD	00:00.0
2021 PO4060284483	LGE	4	40 BRO	SP	A	ED	BD	00:00.0
2021 PO4060084487	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4061884493	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4061484499	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4062284506	LGE	4	40 BRO	SP	CRE		V	00:00.0

2021 PO4063184514	F	4	45 BRO	SP	CRE		V	00:00.0	
2021 PO8549908272	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO8549308198	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO8557208202	KU	6	30 UNK	SP	CCA		V	00:00.0	
2021 PO8564308177	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO8570508126	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO8577508105	KU	6	30 UNK	SP	A	ID,SRS	TD	00:00.0	
2021 PO8562508021	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO8513808211	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO8494307628	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO8488607668	KU	6	30 UNK	SP	CCA		V	00:00.0	
2021 PO4316044835	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4344144821	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4328645324	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4321145960	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4345946010	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4381446927	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4361346403	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4132249451	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4164885369	LGE	4	35 ACE	SP	P	ID	BD	00:00.0	
2021 PO4090485207	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO4090285202	LGE	1	55 ACE	SP	CCA		V	00:00.0	
2021 PO4137584614	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4140584727	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO4138484727	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4143084784	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4143084778	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4142984763	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4142884753	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4142784737	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4142584725	LGE	1	55 ACE	SP	CCA		V	00:00.0	
2021 PO5979910241	KU	4	40 ACW	SP	CRE	ED,HH,ID,IP	TD	00:00.0	
2021 PO5996810236	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO3653661657	KU	4	45 BRN	SP	CCA		B	00:00.0	
2021 PO3646261842	KU	4	40 BRN	SP	CCA	SRS	TD	00:00.0	
2021 PO3652561883	F	4	45 BRN	SP	CCA		V	00:00.0	
2021 PO3661661881	KU	4	45 BRN	SP	CCA		B	00:00.0	
2021 PO3614164802	KU	4	45 BRN	SP	CCA		B	00:00.0	
2021 PO3713965690	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO4061984557	LGE	4	45 BRO	SP	CRE	HH,IP,RB	TX	RR	00:00.0
2021 PO4060784572	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4059584588	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4058384604	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO5997210852	KU	4	40 ACW	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5982510871	KU	5	35 ACW	SP	S		V	00:00.0	
2021 PO5983910374	KU	5	35 ACW	SP	S		V	00:00.0	
2021 PO5972310684	KU	5	35 ACW	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5972010423	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8485707489	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO8538907487	KU	6	30 UNK	SP	CCA		V	00:00.0	
2021 PO8469007607	KU	5	35 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO4063184541	LGE	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO8473807285	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO8466007157	F	3	45 UNK	SP	CCA		V	00:00.0	

2021 PO8459207032	F	3	45 UNK	SP	CCA		V		00:00.0
2021 PO5972410849	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4110585579	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4034585309	LGE	4	45 ACE	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021 PO4022985167	F	4	40 BRO	SP	CRE		V		00:00.0
2021 4020285168A	KU	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4021485167	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4019385168	F	4	30 BRO	SP	CRE		VX	RP3	00:00.0
2021 PO4020285168	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO7339263329	LGE	5	35 BRO	SP	CCA		V		00:00.0
2021 PO8784507562	KU	3	45 OTH	SP	CCA	ID,IP	BD		00:00.0
2021 PO8785407477	KU	3	60 OTH	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO3481227719	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3512527396	KU	4	40 BRN	SP	CRE	ID,IP	TD		00:00.0
2021 PO4024185166	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4025285166	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4026085175	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO7410463483	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4026085163	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4025985152	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4025885139	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4028185321	LGE	4	35 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4024885005	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4027185321	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4116885182	LGE	3	50 ACE	SP	CCA	ED,ID	TD		00:00.0
2021 PO4113485193	LGE	4	40 ACE	SP	CRE	ID	BD		00:00.0
2021 PO4113485184	LGE	3	50 ACE	SP	CCA	ED,ID,IP	BD		00:00.0
2021 PO4114985183	LGE	2	60 ACE	SP	CRE	ED,EP,HH,ID,RB	BX	RP1	00:00.0
2021 PO4114885176	LGE	4	30 ACE	SP	CRE	ID	TD		00:00.0
2021 PO4024085316	LGE	2	75 ACE	SP	CRE		V		00:00.0
2021 PO4025685315	LGE	2	35E ACE	SP	CRE	ED	BD		00:00.0
2021 PO4027385314	LGE	2	35E ACE	SP	CRE		V		00:00.0
2021 PO4028285313	LGE	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4034085035	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO5990212335	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5992812217	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5985012572	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5981912699	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5987412454	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5962712423	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5965312289	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5967612169	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5995612098	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5998012002	KU	4	40 ACW	SP	CRE		V		00:00.0
2021 PO5970012050	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO5998711962	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO4122585194	LGE	4	40 ACE	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021 PO4027785070	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4028785073	F	4	30 BRO	SP	A		V		00:00.0
2021 PO4028885069	F	4	40 BRO	DF	CRE		V		00:00.0
2021 PO4029885068	F	3	45 BRO	SP	CRE		V		00:00.0
2021 PO4031585067	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4031485047	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4037085307	LGE	2	75 ACE	SP	CRE	ED	V		00:00.0

2021 PO8693207774	F	4	40 INP	SP	CRE		V	00:00.0
2021 PO8707607784	KU	6	30 INP	SP	CRE	ID,SRS	TD	00:00.0
2021 PO8691507927	F	3	45 INP	SP	CCA		V	00:00.0
2021 PO8677407911	F	4	40 INP	SP	CRE		V	00:00.0
2021 PO8712207766	KU	6	30 INP	SP	CCA		V	00:00.0
2021 PO4118885153	LGE	4	40 ACE	SP	A	ID	TD	00:00.0
2021 PO4029785038	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4028785039	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4028685047	F	5	25 BRO	SP	CRE		V	00:00.0
2021 PO4027685045	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4027685039	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3870686353	KU	4	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO3897086371	KU	5	35 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4621676002	KU	4	45 UNK	SP	CRE	ED	BX	RP1 00:00.0
2021 PO3488958458	KU	4	40 INP	SP	CRE	ID	B	00:00.0
2021 PO4119785152	LGE	4	35 ACE	SP	A	ID	TD	00:00.0
2021 PO4121085151	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4038485306	LGE	2	75 ACE	SP	CRE	ED	V	00:00.0
2021 PO4039685305	LGE	2	75 ACE	SP	CRE	ED	V	00:00.0
2021 PO4120385158	LGE	4	35 ACE	SP	A	ID	TD	00:00.0
2021 PO4031485037	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4031385032	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4030985022	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4049385031	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4050685031	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9825376340	KU	4	45 OTH	SP	CRE	ID,IP	TD	00:00.0
2021 PO4045284969	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4045584977	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7658661250	LGE	4	35 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4048684966	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4051484933	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4051984946	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4052184952	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4052884995	LGE	4	35 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO9821075684	KU	4	40 OTH	SP	CRE	ID,IP	TD	00:00.0
2021 PO9818175397	KU	2	55 OTH	SP	CRE	ID	TD	00:00.0
2021 PO9819175397	KU	2	55 OTH	SP	CRE	ID,IP	TD	00:00.0
2021 PO9822975966	KU	4	40 OTH	SP	CRE	ID,IP	TD	00:00.0
2021 PO5221056606	KU	2	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5207256526	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5942066478	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO3880985484	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO3978386478	KU	3	50 ACE	SP	CRE	ID	TD	00:00.0
2021 PO6907576421	KU	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3980586463	LGE	3	45 ACE	SP	CRE	ED,EP,ID,RB	X	PX 00:00.0
2021 PO3980586463a1	KU	4	40 ACE	SP	P	ID	TD	00:00.0
2021 PO3982086454	LGE	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3983186447	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4045884989	F	4	40 BRO	SP	CRE		V	00:00.0
2021 4045884989A	F	5	30 BRO	SP	A		V	00:00.0
2021 PO4046385001	F	4	40 BRO	SP	CRE		V	00:00.0
2021 4046385001A	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4046785011	F	3	45 BRO	SP	CCA		V	00:00.0
2021 4047285027A	F	4	40 BRO	SP	CRE		V	00:00.0

2021 PO4047285027	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4046485032	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4045385032	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4043385033	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4042885037	F	5	30 BRO	SP	CRE		V		00:00.0
2021 PO3892985469	LGE	4	40 ACE	SP	A		V		00:00.0
2021 PO3904185356	LGE	3	45 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4041285019	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4041285005	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4041184994	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO3914685325	LGE	1	65 ACE	SP	P		V		00:00.0
2021 PO3915985357	LGE	1	70 ACE	SP	P		V		00:00.0
2021 PO4072384405	LGE	3	50 ACE	SP	CCA	ED,ID	TD		00:00.0
2021 PO3914085334	LGE	3	45 ACE	SP	P		V		00:00.0
2021 PO3912285350	LGE	4	35 ACE	SP	P		V		00:00.0
2021 PO3913185345	LGE	3	50 ACE	SP	P		V		00:00.0
2021 PO3915685364	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO3912185355	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3912585357	LGE	2	50 ACE	SP	CCA		V		00:00.0
2021 PO3911185370	LGE	2	55 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO3910185384	KU	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO3885485438	LGE	1	20E ACE	SP	CRE		V		00:00.0
2021 PO3886685443	LGE	2	20 ACE	SP	P		V		00:00.0
2021 PO3873485323	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4934839050	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4938639140	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4940439132	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4955039516	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4955339543	KU	3	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4958139532	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4981339279	KU	6	30 BRN	SP	CRE		V		00:00.0
2021 PO3985986429	LGE	3	45 ACE	SP	CRE	ED,HH,ID	BD		00:00.0
2021 PO3984686437	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5198456643	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5218256362	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO3987486419	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO3990786399a1	LGE	3	45 ACE	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021 PO3990786399	LGE	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO3991386396	LGE	1	55 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4041285028	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4041285035	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4039485032	F	5	30 BRO	SP	CRE		V		00:00.0
2021 PO4071384421	LGE	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4070384439	LGE	4	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4069584455	LGE	4	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4068484464	LGE	4	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4039485038	F	5	35 BRO	SP	CRE		V		00:00.0
2021 PO4037685031	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4037185029	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4041084982	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4041084971	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4048584856	F	3	45 ACE	SP	P		V		00:00.0
2021 PO4047584862	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4972239475	KU	3	45 UNK	SP	CRE	HH,ID	BX	PX	00:00.0

2021 PO5567257204	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO5571857076	KU	2	70 BRN	SP	CRE		V			00:00.0
2021 PO5512657482	KU	1	75 OTH	SP	CRE		V			00:00.0
2021 PO5537857319	KU	1	70 BRN	SP	CCA		V			00:00.0
2021 PO5558857183	KU	2	70 XXX	SP	CRE		V			00:00.0
2021 PO5570357088	KU	4	40 BRN	SP	CCA		V			00:00.0
2021 PO5525757398	KU	2	70 BRN	SP	CCA		V			00:00.0
2021 PO5086955201	KU	1	70 BRN	SP	CCA		V			00:00.0
2021 PO5051758323	KU	2	45 BRN	SP	CRE	ID		BD		00:00.0
2021 PO5495857591	KU	1	80 OTH	ST	CRE		V			00:00.0
2021 PO5556757197	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO5462457798	KU	1	70 BRN	SP	CCA		V			00:00.0
2021 PO5088855340	KU	1	80 BRN	SP	CCA		V			00:00.0
2021 PO5560257172	KU	4	45 BRN	SP	CCA		V			00:00.0
2021 PO5477957697	KU	1	75 BRN	SP	CCA		V			00:00.0
2021 PO5601956962	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO5494757896	KU	2	40 BRN	SP	CRE	ID,IP		TX	RR	00:00.0
2021 PO0038882329	KU	3	35 OTH	SP	CRE	ID		BD		00:00.0
2021 PO0051182521	KU	3	35 OTH	SP	CRE	ID		BD		00:00.0
2021 PO0068382789	KU	3	35 OTH	SP	CRE	ID		BD		00:00.0
2021 PO5454956906	KU	4	40 BRN	SP	CRE	ID		TD		00:00.0
2021 PO0082283006	KU	3	35 OTH	SP	CRE	ID		BD		00:00.0
2021 PO0098183253	KU	3	35 OTH	SP	CRE	ID		BD		00:00.0
2021 PO0113383491	KU	4	35 OTH	SP	CRE	ID		BD		00:00.0
2021 PO5447456750	KU	6	30 BRN	SP	CRE	ID		BD		00:00.0
2021 PO5452656697	KU	5	35 BRN	SP	CRE	ID		BD		00:00.0
2021 PO5443756468	KU	6	30 BRN	SP	CRE	ID		BD		00:00.0
2021 PO5450256483	KU	5	35 BRN	SP	CRE	ID		BD		00:00.0
2021 PO5447156210	KU	5	35 BRN	SP	CRE	ID		BD		00:00.0
2021 PO3979586322	LGE	4	40 ACE	SP	A	ED,ID		BD		00:00.0
2021 PO3985686313	LGE	4	30 ACE	SP	CRE	ED,ID		BD		00:00.0
2021 PO3985486314	LGE	4	40 ACE	SP	CRE	ED,ID		BD		00:00.0
2021 PO4065085179	F	4	40 BRO	SP	CCA		V			00:00.0
2021 PO4065885191	LGE	3	45 BRO	SP	CCA		V			00:00.0
2021 PO3988186342	LGE	3	45 ACE	SP	CRE	ED,HH,ID,RB		BX	PX	00:00.0
2021 PO3987486339	LGE	4	35 ACE	SP	A	ID		TD		00:00.0
2021 PO9799572560	KU	2	65 OTH	SP	CRE	ID,IP		TD		00:00.0
2021 PO9800572559	KU	2	65 OTH	SP	CRE	ID		BD		00:00.0
2021 PO4835539322	KU	3	45 UNK	SP	CRE	ID		BD		00:00.0
2021 PO5367657281	KU	4	40 BRN	SP	CRE	ID		TD		00:00.0
2021 PO5356657375	KU	5	35 BRN	SP	CRE	ID		BD		00:00.0
2021 PO7016475123	KU	1	50 ACE	SP	CCA		V			00:00.0
2021 PO3988186342	LGE	3	50 ACE	SP	A	ID		BD		00:00.0
2021 PO3988986356	LGE	1	55 ACE	SP	A	ED,ID		BD		00:00.0
2021 PO3987686352	LGE	4	40 ACE	SP	A	ID		TD		00:00.0
2021 PO9805073235	KU	2	65 OTH	SP	CRE	ID		BD		00:00.0
2021 PO9803973236	KU	2	65 OTH	SP	CRE	ID		BD		00:00.0
2021 PO3900085581	LGE	1	40 ACE	DF	CCA		V			00:00.0
2021 PO3900085580	LGE	2	45 ACE	SP	CRE		V			00:00.0
2021 PO6151067373	LGE	2	45 ACE	SP	CRE		V			00:00.0
2021 PO4847639184	KU	2	45 UNK	SP	CRE	HH,ID		BX	RP1	00:00.0
2021 PO4079185242	LGE	4	30 BRO	SP	CRE	ED,ID		BD		00:00.0
2021 PO4078985244	LGE	4	40 BRO	SP	CRE	ED,ID		BD		00:00.0
2021 PO4078485249	LGE	4	35 BRO	SP	CRE	ED,ID		BD		00:00.0

2021 PO4073585266	LGE	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4074185272	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9808773810	KU	2	65 OTH	SP	CRE	ID	BD	00:00.0
2021 PO9807773811	KU	2	65 OTH	SP	CRE	ID	BD	00:00.0
2021 PO3893785524	LGE	1	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3893885521	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6059966845	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4849239220	KU	2	45 KOP	SP	CCA		B	00:00.0
2021 PO4851139774	KU	2	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5362457252	KU	4	40 BRN	SP	CRE	ED,HH,ID,IP,RB	X	PX 00:00.0
2021 PO5362457252a	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3968486507	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4073285248	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3970486493	LGE	4	30 ACE	SP	CRE	ED,ID,RB	X	RP3 00:00.0
2021 PO4066985205	F	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4048684859	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4048984868	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4049384880	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4049884890	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3982285231	LGE	4	35 ACE	SP	S	ED,ID	BD	00:00.0
2021 PO4064485203	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4064885206	F	4	45 BRO	SP	A		V	00:00.0
2021 PO4065285214	LGE	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4064685229	LGE	4	35 BRO	SP	CRE	HH,ID	TD	00:00.0
2021 PO3981386305	LGE	4	40 ACE	SP	A	ID	TD	00:00.0
2021 PO4721238428	KU	3	45 BRO	SP	CCA		B	00:00.0
2021 PO6974064075	LGE	4	45 ACE	SP	CCA		V	00:00.0
2021 PO3983085244	KU	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3983285247	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4063785217	LGE	4	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4063985212	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5443755912	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5464156024	KU	5	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5455355975	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5386457394	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4723538396	KU	5	35 BRO	SP	CCA		B	00:00.0
2021 PO3977886339	LGE	4	40 ACE	SP	P	ID	BD	00:00.0
2021 PO9778869398	KU	2	55 OTH	SP	CCA		V	00:00.0
2021 PO9779869398	KU	2	55 OTH	SP	CCA		V	00:00.0
2021 PO9774668764	KU	2	55 OTH	SP	CCA		V	00:00.0
2021 PO9775768763	KU	2	55 OTH	SP	CCA		V	00:00.0
2021 PO9771568285	KU	2	55 OTH	SP	CRE		V	00:00.0
2021 PO9772568284	KU	2	55 OTH	SP	CRE		V	00:00.0
2021 PO4703738527	KU	5	35 BRO	SP	CCA		B	00:00.0
2021 PO3983486314	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3983986321	LGE	4	45 ACE	SP	A	ED,HH,ID	BD	00:00.0
2021 PO4712038471	KU	5	35 KOP	SP	CCA		B	00:00.0
2021 PO4850839258	KU	3	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO9766867572	KU	2	65 OTH	SP	CRE		V	00:00.0
2021 PO9767967572	KU	2	65 OTH	SP	CRE		V	00:00.0
2021 PO9793071415	KU	2	65 OTH	SP	CRE		V	00:00.0
2021 PO9789770906	KU	3	50 OTH	SP	CRE		V	00:00.0
2021 PO9787370541	KU	2	55 OTH	SP	CRE		V	00:00.0
2021 PO6443862547	LGE	3	45 ACE	SP	CCA		V	00:00.0



2021 PO3929285119	LGE	9	20 ACE	SP	CCA		V	00:00.0
2021 PO3977886379	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3978186386	LGE	4	30 ACE	SP	A	ED,HH,ID	BD	00:00.0
2021 PO3977486381	LGE	4	40 ACE	SP	A	ID,IP	BD	00:00.0
2021 PO4076585294	F	3	50 BRO	SP	CRE		V	00:00.0
2021 PO4077185305	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4076585298	LGE	3	50 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP3 00:00.0
2021 PO9795771985-A	KU	3	65 OTH	SP	CRE	ED,EP,ID,IP	TD	00:00.0
2021 PO9795771985	KU	3	55 OTH	SP	CRE	EP,ID,IP	TD	00:00.0
2021 PO4078185279	F	3	40 BRO	SP	CCA		V	00:00.0
2021 PO7937365616	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4853939329	KU	2	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3890685482	LGE	1	85 ACE	SP	P		V	00:00.0
2021 PO3887685495	LGE	1	85 ACE	SP	P		V	00:00.0
2021 PO6078066530	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4079685265	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7954964349	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3986386344	LGE	4	35 ACE	SP	A	ED,ID,RB	BD	00:00.0
2021 PO4081085251	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4076185291	LGE	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4075985291	LGE	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4075085282	LGE	3	50 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4074585277	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3986786328	LGE	4	40 ACE	SP	CRE	ID	BD	00:00.0
2021 PO3987286326	LGE	3	50 ACE	SP	CCA	ID,IP	BD	00:00.0
2021 PO3969486476	LGE	7	25 ACE	SP	CRE	ID,MD	BD	00:00.0
2021 PO3973186449	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3973686459	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4071485210	LGE	2	90 BRO	SP	CRE		V	00:00.0
2021 PO7865763913	LGE	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7870763960	LGE	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4069285219	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6024166863	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6010166801	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6018566752	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6005866724	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6008966557a	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4070385229	LGE	4	30 BRO	ST	P		V	00:00.0
2021 PO4069485223	LGE	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4068685213	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4860139471	KU	2	45 ACW	SP	CRE	ID	BD	00:00.0
2021 PO4067785188	LGE	4	30 BRO	SP	CRE	ID	BD	00:00.0
2021 PO3983786398	LGE	4	40 ACE	SP	P	ED,ID,RB,SRS	X	PX 00:00.0
2021 PO3885185610a	KU	1	45 ACE	SP	CCA		V	00:00.0
2021 PO3885185610	LGE	1	45 ACE	SP	CCA		V	00:00.0
2021 PO4043784948	F	4	35 ACE	SP	P		V	00:00.0
2021 PO7600561116	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4044584943	LGE	4	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4045884939	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4047384943	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3887385604	LGE	1	45 ACE	SP	CCA		V	00:00.0
2021 PO3890185588	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO606066940	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO9865977947	KU	4	40 OTH	SP	CRE	ID	TD	00:00.0

2021 PO3984586388	LGE	4	30 ACE	SP	A	ID	TD	00:00.0
2021 PO3985086386	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3984986391	LGE	4	40 ACE	SP	A	ID	TD	00:00.0
2021 PO4057985053	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4057285041	LGE	3	50 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO7733362317	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO8488858827	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8584460510	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8586560408	ODP	6	30 XXX	SP	CCA		T	00:00.0
2021 PO8568959977	ODP	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5612811835	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5653411676	F	4	40 CPT	SP	CRE		V	00:00.0
2021 PO5664011582	F	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5561908348	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5552308385	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5543508419	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO5724911873	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5574108080	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5288407665	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO5285807608	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO5291008223	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO5290008069	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO5289307865	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO4928508605	KU	2	45 XXX	SP	S		V	00:00.0
2021 PO5274007598	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO5639412393	F	5	40 BRO	SP	CRE		V	00:00.0
2021 PO5630612426	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5620712460	F	5	40 UNK	SP	CRE		V	00:00.0
2021 PO5127907782	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO5126207738	KU	4	45 XXX	SP	S		V	00:00.0
2021 PO5117607533	KU	4	45 XXX	SP	S		V	00:00.0
2021 PO5669912356	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5650612352	F	4	40 UNK	SP	P		V	00:00.0
2021 PO5115307146	KU	4	45 XXX	SP	S		V	00:00.0
2021 PO5111107380	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5108307317	KU	4	45 XXX	SP	S		V	00:00.0
2021 PO5598212619	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5771412121	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5760312193	F	4	40 BRO	SP	P		V	00:00.0
2021 PO5762212260	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5768412412	F	3	45 CPT	SP	P		V	00:00.0
2021 PO5779312382	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5793512335	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5168007362	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5176307567	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5699312882A	KU	5	40 UNK	SP	CRE		V	00:00.0
2021 PO5687312924	F	5	40 UNK	SP	CRE		V	00:00.0
2021 PO5676012966	F	4	40 UNK	SP	P		V	00:00.0
2021 PO5681913395	F	4	40 MAR	SP	P		V	00:00.0
2021 PO5706313267	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5725113237	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5723813172	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5720813068	F	4	40 CPT	SP	P		V	00:00.0
2021 PO5710113010	F	5	35 BRO	SP	CCA		V	00:00.0

2021	PO5718712985	F	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5264506349A	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5271406590	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5264506349	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5257706109	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5251505923	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5251505923A	KU	4	40 XXX	SP	S	V	00:00.0
2021	PO5850913018	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5838413037	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5826313057	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5805513089	F	5	40 UNK	SP	CRE	V	00:00.0
2021	PO5270307216	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5269407119	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5278707176	KU	2	50 XXX	SP	S	V	00:00.0
2021	PO5277506910	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5274406750	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5578511968	F	4	40 UNK	SP	CCA	V	00:00.0
2021	PO5581112122	F	5	40 UNK	SP	CRE	V	00:00.0
2021	PO5578512049	F	3	40 UNK	SP	CRE	V	00:00.0
2021	PO5552307184	KU	4	40 BRN	SP	CCA	V	00:00.0
2021	PO5789913122	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5774412809	F	4	40 UNK	SP	P	V	00:00.0
2021	PO5761712858	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5766012983	F	4	40 UNK	SP	P	V	00:00.0
2021	PO5772713154	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5746212917	F	4	40 UNK	SP	P	V	00:00.0
2021	PO5242007818	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5480108359	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO7591605125	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO5514810482	KU	3	50 XXX	SP	S	V	00:00.0
2021	PO5502210538	KU	2	50 XXX	SP	S	V	00:00.0
2021	PO5490610589	KU	3	50 XXX	SP	S	V	00:00.0
2021	PO5488510599	KU	3	50 XXX	SP	S	V	00:00.0
2021	PO5478510644	KU	1	50 XXX	SP	S	V	00:00.0
2021	PO5478510644A	KU	2	45 XXX	SP	S	V	00:00.0
2021	PO5500108288	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO5239208072	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5610412287	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5626912227	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5643412167	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5556608058	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO5708212614	F	4	35 MAR	SP	P	V	00:00.0
2021	PO5725412552	F	3	45 MAR	SP	CCA	V	00:00.0
2021	PO5738212514	F	3	45 MAR	SP	P	V	00:00.0
2021	PO5752212467	F	3	45 MAR	SP	P	V	00:00.0
2021	PO5782512053	F	4	40 UNK	SP	P	V	00:00.0
2021	PO5038706917	KU	4	45 XXX	SP	S	V	00:00.0
2021	PO5445513256	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5724112084	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5687112219	F	4	40 UNK	SP	P	V	00:00.0
2021	PO5670612280	F	3	40 MAR	SP	P	V	00:00.0
2021	PO5510507354	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO5522407295	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO5520407277	KU	3	45 BRN	SP	CCA	V	00:00.0

2021 PO5731612240	F	4	40 BRO	SP	P	V	00:00.0
2021 PO5737812105	KU	6	30 BRO	SP	CCA	V	00:00.0
2021 PO5703612159	F	3	40 MAR	SP	P	V	00:00.0
2021 PO5051206874	KU	4	45 XXX	SP	S	V	00:00.0
2021 PO5068406797	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO5071306832	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO5047407144	KU	4	45 XXX	SP	S	V	00:00.0
2021 PO5052707281	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO5054707332	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO4287586586	F	4	30 BRO	SP	A	V	00:00.0
2021 PO4278486649	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO4405285923	LGE	2	70 BRO	SP	A	V	00:00.0
2021 PO4277986635	LGE	3	50 ACE	SP	CCA	V	00:00.0
2021 PO9911978471	LGE	3	50 ACE	SP	CCA	V	00:00.0
2021 PO4406185910	LGE	1	65 BRO	SP	A	V	00:00.0
2021 PO4278286652	LGE	3	55 ACE	SP	CCA	V	00:00.0
2021 PO4519587950	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4517887947	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4511687911	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4512387900	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4517387859	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4516787945	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4510387933	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4521487946	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4521087952	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4516087850	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4515287843	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4514487837	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4504487831	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4511387837	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4283886340	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4428685563	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4277586550	LGE	2	55 ACE	SP	CCA	V	00:00.0
2021 PO4407385889	LGE	1	65 BRO	SP	P	V	00:00.0
2021 PO4404885928	LGE	2	55 BRO	SP	A	V	00:00.0
2021 PO4404485936	LGE	2	75 BRO	SP	CRE	V	00:00.0
2021 PO4518587870	F	4	40 ACE	DF	CRE	V	00:00.0
2021 PO4515687903	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4516687907	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4517887912	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4519187918	F	2	45 ACE	SP	CCA	V	00:00.0
2021 PO4520187881	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4520587884	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4521487890	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4522387897	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4524687914	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4525887875	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4525387883	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4508087839	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4525287666	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4426785570	F	4	30 BRO	SP	P	V	00:00.0
2021 PO4530587705	F	4	30 ACE	SP	A	V	00:00.0
2021 PO4533287745	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4530587799	F	4	35 ACE	SP	CRE	V	00:00.0

2021 PO4539387652	F		4	40 ACE	SP	CCA	V	00:00.0
2021 PO4540487618	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO4540087634	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO4278486406	LGE	H3		70 ACE	SP	CRE	V	00:00.0
2021 PO4420885478	LGE		3	45 BRO	SP	CCA	V	00:00.0
2021 PO4422485490	LGE		4	40 BRO	SP	CCA	V	00:00.0
2021 PO4277986429	LGE	5H		70 ACE	SP	CRE	V	00:00.0
2021 PO4423285656	F		3	45 BRO	SP	A	V	00:00.0
2021 PO9931275393	F		4	40 ACE	SP	CCA	V	00:00.0
2021 PO4279286367	F		4	35 ACE	SP	A	V	00:00.0
2021 PO4279386348	F		4	30 ACE	SP	CCA	V	00:00.0
2021 PO4279386347	F	H3		45 ACE	SP	CRE	V	00:00.0
2021 PO4427385584	F		2	50 BRO	SP	A	V	00:00.0
2021 PO4277886580	LGE		3	50 ACE	SP	CCA	V	00:00.0
2021 PO4516287585	F		4	40 ACE	SP	A	V	00:00.0
2021 PO4515587581	F		4	40 ACE	SP	A	V	00:00.0
2021 PO4278986329	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO4278986336	LGE		2	55 ACE	SP	CCA	V	00:00.0
2021 PO4278786367	LGE		2	110 ACE	SP	CRE	V	00:00.0
2021 PO4395485898	LGE		4	35 BRO	SP	CCA	V	00:00.0
2021 PO4392585883	LGE		4	35 BRO	SP	CCA	V	00:00.0
2021 PO4392385882	LGE		5	35 BRO	SP	CCA	V	00:00.0
2021 PO4391885897	LGE		4	35 BRO	SP	CCA	V	00:00.0
2021 PO4418485732	F		3	45 BRO	SP	A	V	00:00.0
2021 PO4418985724	F		3	45 BRO	SP	CCA	V	00:00.0
2021 PO4419485716	F		3	50 BRO	SP	A	V	00:00.0
2021 PO4419985709	F		3	45 BRO	SP	A	V	00:00.0
2021 PO4420385702	F		3	45 BRO	SP	A	V	00:00.0
2021 PO4421085694	F		3	45 BRO	SP	A	V	00:00.0
2021 PO4422785663	F		3	45 BRO	SP	A	V	00:00.0
2021 PO4421485685	F		3	50 BRO	SP	A	V	00:00.0
2021 PO4421985676	F		3	45 BRO	SP	A	V	00:00.0
2021 PO4542787914	LGE		3	45 ACE	SP	CCA	V	00:00.0
2021 PO4392985864	LGE		3	45 BRO	SP	CCA	V	00:00.0
2021 PO1048570851	LGE		3	45 BRO	SP	CCA	V	00:00.0
2021 PO4291186597	LGE		1	50 ACE	SP	CCA	V	00:00.0
2021 PO4293086608	LGE		4	40 ACE	SP	A	V	00:00.0
2021 PO4408385898	F		4	40 BRO	SP	A	V	00:00.0
2021 PO4409085904	LGE		3	50 BRO	SP	CCA	V	00:00.0
2021 PO4406285924	F		4	35 BRO	SP	A	V	00:00.0
2021 PO4406885916	F		4	35 BRO	SP	A	V	00:00.0
2021 PO4407685904	F		4	40 BRO	SP	CCA	V	00:00.0
2021 PO4424485634	F		3	45 BRO	SP	A	V	00:00.0
2021 PO4425185622	F		4	40 BRO	SP	A	V	00:00.0
2021 PO4423785646	F		3	45 BRO	SP	A	V	00:00.0
2021 PO5673413939	KU		4	40 BRN	SP	CCA	V	00:00.0
2021 PO5450611641	KU		4	40 BRN	SP	CCA	V	00:00.0
2021 PO5821715409	KU		4	40 BRN	SP	CCA	V	00:00.0
2021 PO5465711588	F		2	50 BRN	SP	CCA	V	00:00.0
2021 PO2213422054	KU		4	40 BRN	SP	CCA	V	00:00.0
2021 PO5539814048	KU		3	50 UNK	SP	CCA	V	00:00.0
2021 PO5488714106	KU		4	45 BRN	SP	S	V	00:00.0
2021 PO5500713952	KU		3	50 BRN	SP	CCA	V	00:00.0
2021 PO4245413926	F		6	30 KOP	SP	CCA	V	00:00.0

2021 PO4235013981	F	3	40 XXX	SP	CCA	V	00:00.0
2021 PO5520814010	KU	3	50 UNK	SP	CCA	V	00:00.0
2021 PO6012018567	F	4	40 UNK	SP	P	V	00:00.0
2021 PO5964118756	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5951518810	F	4	40 UNK	SP	P	V	00:00.0
2021 PO5412712054	F	5	30 UNK	SP	CCA	V	00:00.0
2021 PO5408312021	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5413911773	KU	4	40 BRN	SP	S	V	00:00.0
2021 PO5422611786	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5420611745	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5431711707	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5440511677	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5592412474	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO5869216833	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO5860717171	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5459312006	KU	4	40 UNK	SP	CCA	V	00:00.0
2021 PO5433711922	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5428211945	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO4512706197	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO4503806469	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO4498806354	KU	2	50 KOP	SP	CCA	V	00:00.0
2021 PO4479506553	KU	3	55 KOP	SP	CCA	V	00:00.0
2021 PO4458706752	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO4340108629	KU	5	35 KOP	SP	CCA	V	00:00.0
2021 PO4326908027	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO4326708238	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO2187922932	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO2188123107	KU	2	60 BRN	SP	CCA	V	00:00.0
2021 PO5767415781	KU	3	45 BRN	SP	S	V	00:00.0
2021 PO5783315604	KU	3	45 BRN	SP	S	V	00:00.0
2021 PO5940617681	KU	3	50 UNK	SP	CCA	V	00:00.0
2021 PO5899817558	KU	4	40 UNK	SP	CCA	V	00:00.0
2021 PO5566910846	KU	6	30 KOP	SP	CCA	V	00:00.0
2021 PO5499512157	KU	5	35 KOP	SP	CCA	V	00:00.0
2021 PO5584211883	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO5507111717	F	4	45 KOP	SP	CCA	V	00:00.0
2021 PO5495211666	F	3	40 KOP	SP	CCA	V	00:00.0
2021 PO5528111416	KU	5	30 KOP	SP	CCA	V	00:00.0
2021 PO5849316640	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO6429026199	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO6389325931	KU	4	40 UNK	SP	CCA	V	00:00.0
2021 PO6415325918	KU	4	40 UNK	SP	CCA	V	00:00.0
2021 PO6428125937	F	2	45 UNK	SP	CCA	V	00:00.0
2021 PO6438826074	KU	4	40 UNK	SP	CCA	V	00:00.0
2021 PO4664312743	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO5678314099	KU	3	55 UNK	SP	CCA	V	00:00.0
2021 PO5660814142	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4096186254	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4094886256	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4093686249	LGE	2	60 BRO	SP	CRE	V	00:00.0
2021 PO4091786251	LGE	2	60 BRO	SP	CRE	V	00:00.0
2021 PO4091386258	F	5	35 BRO	SP	CRE	V	00:00.0
2021 PO6254011010	KU	4	45 ACW	SP	S	V	00:00.0
2021 PO6324111360	KU	4	45 ACW	SP	S	V	00:00.0

2021 PO6321911290	KU	6	35 ACW	SP	S		V		00:00.0
2021 PO3980985848	LGE	4	35 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO3981885859	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3982985871	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO3983885883	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4059886291	LGE	2	85 BRO	SP	CRE		V		00:00.0
2021 PO3918585990	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4058586292	LGE	UNK	80 BRO	ST	P		V		00:00.0
2021 PO4057586291	LGE	UNK	75 BRO	ST	P		V		00:00.0
2021 PO3919785983	F	4	35 ACE	SP	A		V		00:00.0
2021 PO3924585953	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO3925385949	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3923085962	F	4	40 ACE	SP	P		V		00:00.0
2021 PO3921985969	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO3921385972	F	4	40 ACE	SP	P		V		00:00.0
2021 PO3921185970	F	4	30 ACE	SP	A		V		00:00.0
2021 PO3923286006	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4057286297	F	5	35 BRO	SP	CCA		V		00:00.0
2021 PO4054186311	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO3984885894	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4056286349	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4055186338	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4055486323	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4054186330	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4054486325	F	5	35 BRO	SP	CRE		V		00:00.0
2021 PO3930385914	F	4	30 ACE	SP	A		V		00:00.0
2021 PO3931485912	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3996185901	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3924485982	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO5121636698	KU	3	45 INP	SP	CRE	ID	TD		00:00.0
2021 PO4044486293	LGE	2	60 BRO	SP	CRE		V		00:00.0
2021 PO4054586298	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4053286299	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4053186294	LGE	2	60 BRO	SP	CRE		V		00:00.0
2021 PO3925585976	LGE	4	40 ACE	SP	A		V		00:00.0
2021 PO3926585970	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO3927685964	LGE	3	45 ACE	SP	CRE		V		00:00.0
2021 PO3929485969	LGE	4	30 ACE	SP	P		V		00:00.0
2021 PO3929985976	LGE	4	45 ACE	SP	P		V		00:00.0
2021 PO3928885957	F	4	45 ACE	SP	CRE		V		00:00.0
2021 PO3929485958	LGE	4	30 ACE	SP	A		V		00:00.0
2021 PO3934485932	LGE	4	30 ACE	SP	CRE		V		00:00.0
2021 PO3930485948	F	4	40 ACE	SP	A		V		00:00.0
2021 PO3947086321	F	4	40 ACE	SP	A		V		00:00.0
2021 PO3998486040	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3999186047	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3999986055	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4000786050	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4001786045	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6354611359	KU	4	45 ACW	SP	S		V		00:00.0
2021 PO6353911228	KU	3	45 ACW	SP	S		V		00:00.0
2021 PO6353111077	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6338711084	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6331711075	KU	4	40 ACW	SP	S		V		00:00.0

2021 PO6317711081	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO6065212261	KU	2	55 ACW	SP	S		V	00:00.0
2021 PO6072612091	KU	2	50 ACW	SP	S		V	00:00.0
2021 PO6080511907	KU	2	50 ACW	SP	S		V	00:00.0
2021 PO3918285959	F	4	45 ACE	SP	CCA		V	00:00.0
2021 PO3917285946	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3918185955	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3917185998	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3916486002	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3918885998	LGE	4	30 ACE	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO6248211053	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6249011203	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6246511268	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6247711392	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6249411679	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6248511523	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6220111482	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6240611690	F	4	40 ACW	SP	S		V	00:00.0
2021 PO3963886189	LGE	4	30 ACE	SP	CRE	ID	TD	00:00.0
2021 PO4088886260	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4089986252	LGE	2	65 BRO	SP	CRE		V	00:00.0
2021 PO4090286248	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4089986235	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5165836390	KU	3	45 BRO	SP	CRE		B	00:00.0
2021 PO5170736496	KU	3	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO3998185964	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PV3998585970	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5187836426	KU	3	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO5186036348	KU	3	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5181036153	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5176835988	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5174535896	F	4	35 UNK	SP	P		V	00:00.0
2021 PO4105986238	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4105686238	LGE	3	70 BRO	SP	CRE		V	00:00.0
2021 PO4104786239	LGE	4	45 BRO	SP	CRE		V	00:00.0
2021 PO4003086114	LGE	1	85 ACE	SP	PEN		V	00:00.0
2021 PO4001086094	LGE	1	75 ACE	SP	CRE		V	00:00.0
2021 PO4120886225	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4120986232	F	4	45 BRO	SP	CRE		V	00:00.0
2021 PO4122386220	F	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4122486231	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4123886229	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4123786219	F	6	30 BRO	SP	CRE		V	00:00.0
2021 PO4124586219	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4001786085	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4002086089	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4125386228	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4126686227	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4125986217	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4127586226	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4127486214	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4128086218	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4066986351	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4065886358	F	4	40 BRO	SP	CCA		V	00:00.0



2021 PO4064686364	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4063586371	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4062386377	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4067486386	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4066486391	F	3	45 BRO	SP	CCA		V			00:00.0
2021 PO4065386397	F	4	40 BRO	SP	CRE	ED,ID,MD,RB	BX	PX		00:00.0
2021 PO4064686402	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4009986124	LGE	4	40 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4010686119	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021 PO4071786343	F	4	40 BRO	SP	CRE	ED,ID	BX	RP1		00:00.0
2021 PO4006386084	LGE	4	35 ACE	SP	P	ED,ID	BD			00:00.0
2021 PO4005686090	LGE	4	40 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4005886102	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021 PO4006386112	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021 PO4007286121	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021 PO4068586380	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4069786374	F	3	45 BRO	SP	CCA		V			00:00.0
2021 PO4070986368	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4071686357	F	3	45 BRO	SP	CCA		V			00:00.0
2021 PO5267634875	KU	5	35 BRN	SP	CRE	ED,ID	BX	RP1		00:00.0
2021 PO4006186067	LGE	3	45 ACE	SP	P	ED,HH,ID,RB	BX	RP1		00:00.0
2021 PO4006686064	LGE	4	40 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4130386235	LGE	4	30 BRO	SP	CCA		T			00:00.0
2021 PO4129786221	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4131186213	LGE	4	40 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO4007186054	LGE	4	30 ACE	SP	P	ED,EP,ID,RB	TX	RR		00:00.0
2021 PO4130886212	LGE	UNK	55 BRO	SP	CRE		V			00:00.0
2021 PO4007786057	LGE	3	45 ACE	SP	P	ED,ID	BD			00:00.0
2021 PO4008186049	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4007586042	KU	4	35 ACE	SP	P	ED,ID,IP	TD			00:00.0
2021 PO4008886051	LGE	4	40 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4093686306	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO3945986309	F	4	40 ACE	SP	A		V			00:00.0
2021 PO3940586329	F	4	40 ACE	SP	A		V			00:00.0
2021 PO4010186043	LGE	4	40 ACE	SP	P	ED,ID	BD			00:00.0
2021 PO4071986314	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4071086316	F	4	40 BRO	SP	CCA		V			00:00.0
2021 PO5191636573	KU	3	45 UNK	SP	CRE	ID	TD			00:00.0
2021 PO6233711037	F	4	40 ACW	SP	P		V			00:00.0
2021 PO5289729996	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO3953386461	LGE	4	30 ACE	SP	CCA		V			00:00.0
2021 PO3950386418	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO3950986408	LGE	4	40 ACE	SP	CCA		V			00:00.0
2021 PO3951886398	LGE	4	40 ACE	SP	CCA		V			00:00.0
2021 PO3952786405	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021 PO3955586447	LGE	4	35 ACE	SP	P		V			00:00.0
2021 PO3954086419	F	4	40 ACE	SP	A		V			00:00.0
2021 PO3992985918	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO6276210759	KU	6	35 ACW	SP	S		V			00:00.0
2021 PO6276210759A	KU	4	40 ACW	SP	S		V			00:00.0
2021 PO6276210759	KU	4	45 ACW	SP	S		V			00:00.0
2021 PO6284811009	KU	4	45 ACW	SP	S		V			00:00.0
2021 PO6285411139	KU	4	45 ACW	SP	S		V			00:00.0
2021 PO6284711408	KU	4	45 ACW	SP	S		V			00:00.0

2021 PO6275111414	KU	5	35 ACW	SP	S		V	00:00.0	
2021 PO6301411365	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO6286311316	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO6320911668	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO6276211687	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO6291111681	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO3994085913	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3995185907	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3992585966	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3997285896	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3998285890	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3999385889	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO5245730067	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO5249130121	KU	3	50 BRN	SP	CCA		V	00:00.0	
2021 PO5644130078a	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO5264130078	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO5274430045	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO5320229720	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO3993685960	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3994685954	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3995885948	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3996985943	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3920686004	LGE	3	45 ACE	SP	A		V	00:00.0	
2021 PO3997585975	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4103086241	LGE	3	60 BRO	SP	CRE		V	00:00.0	
2021 PO3996585981	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3995285987	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4101586242	LGE	3	60 BRO	SP	CRE		V	00:00.0	
2021 PO4100986242	LGE	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4100186243	LGE	3	60 BRO	SP	CRE		V	00:00.0	
2021 PO4107486273	LGE	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO3994685990	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PV3995185997	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3995786007	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3996086013	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4100186230	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3996686023	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PV3997586031	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4128686224	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4004186067	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4129686214	LGE	4	30 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4012386031	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO5271834986	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5274935066	KU	4	40 BRN	SP	CRE	ED	BX	RP3	00:00.0
2021 PO5281935252	KU	4	35 BRN	SP	CCA		V	00:00.0	
2021 PO5236235052	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO5239535140	KU	3	50 BRN	SP	CRE	ID,IP	X	RP1	00:00.0
2021 PO5231334927	KU	5	35 BRN	SP	CRE	ED,ID	BX	RP2	00:00.0
2021 PO5247634714	KU	2	45 BRN	SP	CCA		V	00:00.0	
2021 PO5227434828	KU	2	45 BRN	SP	CCA		V	00:00.0	
2021 PO5212734911a	KU	2	50 BRN	SP	CCA		V	00:00.0	
2021 PO5212734911	KU	2	45 BRN	SP	CCA		V	00:00.0	
2021 PO4116386224	F	5	35 BRO	SP	CRE		V	00:00.0	
2021 PO4117886224	F	5	35 BRO	SP	CRE		V	00:00.0	

2021 PO4119386222	F	5	30 BRO	SP	CRE		V	00:00:00	
2021 PO4116486236	F	4	40 BRO	SP	CRE		V	00:00:00	
2021 PO4118086235	F	4	40 BRO	SP	CRE		V	00:00:00	
2021 PO3951786419	LGE	4	30 ACE	SP	P	ID	TD	00:00:00	
2021 PO3960086103	LGE	4	30 ACE	SP	CCA		V	00:00:00	
2021 PO6736772670	LGE	4	35 ACE	SP	CCA		V	00:00:00	
2021 PO3962186112	LGE	3	50 ACE	SP	A	ED,ID	TD	00:00:00	
2021 PO4085586256	LGE	UNK	60 BRO	SP	CRE		V	00:00:00	
2021 PO4086886254	LGE	UNK	60 BRO	SP	CRE		V	00:00:00	
2021 PO4088086254	LGE	UNK	60 BRO	SP	CRE		V	00:00:00	
2021 PO4085386263	F	5	35 BRO	SP	CRE		V	00:00:00	
2021 PO4086586262	F	4	35 BRO	SP	CRE		V	00:00:00	
2021 PO4087786261	F	5	35 BRO	SP	CRE		V	00:00:00	
2021 PO3979285802	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00:00	
2021 PO4077186290	LGE	UNK	60 BRO	SP	CRE		V	00:00:00	
2021 PO4075986289	LGE	3	45 BRO	SP	CCA		V	00:00:00	
2021 PO5488935459	KU	3	50 UNK	SP	CRE	ID	TD	00:00:00	
2021 PO3970885692	F	4	40 ACE	SP	CCA		V	00:00:00	
2021 PO3972185685	F	3	45 ACE	SP	CCA		V	00:00:00	
2021 PO3923485949	LGE	4	35 BRO	SP	CCA		V	00:00:00	
2021 PO3922485934	F	4	40 BRO	SP	CRE		V	00:00:00	
2021 392238593A	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00:00	
2021 PO3973385678	F	4	40 ACE	SP	CRE		V	00:00:00	
2021 PO3974485672	F	4	40 ACE	SP	CRE		V	00:00:00	
2021 PO3975385668	F	4	40 ACE	SP	CRE		V	00:00:00	
2021 PO3976785660	F	4	40 ACE	SP	CRE		V	00:00:00	
2021 PO3977985654	F	4	40 ACE	SP	CRE		V	00:00:00	
2021 PO3979085648	F	4	40 ACE	SP	CRE		V	00:00:00	
2021 PO3980085650	F	4	35 ACE	SP	CRE		V	00:00:00	
2021 PO3977285671	F	4	40 ACE	SP	CRE		V	00:00:00	
2021 PO4834085908	LGE	3	45 ACE	SP	CCA		V	00:00:00	
2021 PO5226912628	KU	4	40 KOP	SP	CCA		V	00:00:00	
2021 PO5206912501	KU	4	40 KOP	SP	S		V	00:00:00	
2021 PO4947910745	KU	4	35 XXX	SP	S		V	00:00:00	
2021 PO5297708647	KU	4	40 XXX	SP	S		V	00:00:00	
2021 PO5186710915	KU	2	70 KOP	SP	CRE		V	00:00:00	
2021 PO5215212352	KU	4	45 KOP	SP	S		V	00:00:00	
2021 PO5186012471	KU	3	45 KOP	SP	S		V	00:00:00	
2021 PO5027512603	F	4	40 XXX	SP	P		V	00:00:00	
2021 PO5190012445	KU	4	45 KOP	SP	CRE	ED,ID	BD	00:00:00	
2021 PO4944210077	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00:00	
2021 PO4900410327	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00:00	
2021 PO5213612258	KU	4	45 KOP	SP	CRE	ED,ID	BD	00:00:00	
2021 PO4914110559	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00:00	
2021 PO4950710135	KU	4	40 XXX	SP	S		V	00:00:00	
2021 PO5210112160	KU	2	55 KOP	SP	CRE	ED,ID	BD	00:00:00	
2021 PO4946010296	KU	6	30 XXX	SP	CRE		V	00:00:00	
2021 PO5169411421	F	4	40 KOP	SP	CRE		V	00:00:00	
2021 PO5193112417	KU	4	45 KOP	SP	S		V	00:00:00	
2021 PO4944310575	KU	4	40 XXX	SP	S		V	00:00:00	
2021 PO5116411352	KU	5	35 XXX	SP	S		V	00:00:00	
2021 PO5142211827	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00:00	
2021 PO4455088660	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX	PX	00:00:00
2021 PO4454588652	F	4	40 ACE	SP	CRE		V	00:00:00	

2021 PO4008083895	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4007183899	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4005983904	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4858185409	LGE	3	45 ACE	SP	P	ED,EP	V	00:00.0
2021 PO4857785410	LGE	3	45 ACE	SP	P	ED	V	00:00.0
2021 PO4453088649	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4452988687	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO1890670201	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1888470104	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO1885969996	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1871669996	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4450188658	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4862885407	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4450688663	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4449188673	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4002983860	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4003283868	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4002983877	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4860685390	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4004083886	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4449188731	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4448488715	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4559488044	LGE	4	40 BRO	SP	CRE	ED,ID,IP,MD	BD	00:00.0
2021 PO4559188043	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4558188032	F	4	25 BRO	SP	A	ED,HH,ID,RB	VX	RP2 00:00.0
2021 PO4558988028	LGE	H2	100 BRO	SP	A		V	00:00.0
2021 PO4558388038	LGE	2	60 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4557988035	LGE	3	45 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4558388076	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4467688894	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4467188886	LGE	4	35 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4466488877	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4465988869	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4468388901	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO4469688900	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4470988912	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4559288061	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4559588056	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4560288050	LGE	4	35 BRO	SP	P	ED,ID,IP,MD	BD	00:00.0
2021 PO4004783910	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4004683903	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4004183909	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4862785387	LGE	4	40 ACE	SP	P	ED,IP	BD	00:00.0
2021 PO4002483919	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4450588725	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4450288732	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4857185397	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO400083929	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4451488732	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4453288734	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3998883934	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4455188676	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4451788694	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4452788693	F	4	40 ACE	SP	CRE		V	00:00.0

2021 PO4454388691	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4454288701	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4456188709	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4457288714	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4856185240	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4858185237	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO1901770247	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4017883969	LGE	1	55 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO1911570281	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO1910770225	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO1929270183	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4457588715	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4457288727	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4457088736	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4017083955	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4456988749	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4017083955-A	KU	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO1942770259	KU	6	30 BRO	SP	CRE		V	00:00.0
2021 PO1948970143	F	3	50 BRO	SP	CRE		V	00:00.0
2021 PO4457088795	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4457088766	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4457088775	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4856085259	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO1689700394	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4016783949	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4458888816	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4015683929	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4015183921	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4460488842	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4461188859	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4853885240	LGE	1	60 ACE	SP	S		V	00:00.0
2021 PO4927210497	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO4830985958	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4830285931	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4446588867	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4831385950	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4447588862	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4446288869	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4829385848	LGE	4	40 ACE	SP	CRE	ED,ID	BX RR	00:00.0
2021 PO4829085936	F	4	35E ACE	SP	P		V	00:00.0
2021 PO4445088863	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4828385946	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4829385948	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4827185950	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4441988785	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4442488799	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4555288018	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4554388012	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4439388833	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4826985958	F	3	40 ACE	SP	P		V	00:00.0
2021 PO4827585961	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4825885958	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4441388833	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4439388826	F	4	40 ACE	SP	CCA		V	00:00.0

2021 PO1888470429	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4439588819	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4899784770	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4899784780	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4553088034	LGE	4	40 BRO	SP	CRE	ED,HH,ID,IP,RB	TX	RR	00:00.0
2021 PO2631992721	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4553688024	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4552488044	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4551788054	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4443688857	F	3	45 ACE	SP	P		V		00:00.0
2021 PO4442888852	F	3	45 ACE	SP	CRE		V		00:00.0
2021 PO4442088844	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4441988847	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4841485906	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4857785444	LGE	3	45 ACE	SP	CCA	ED,EP	VX	PX	00:00.0
2021 PO4442588834	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4443288830	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4446588830	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4446588821	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4448288807	F	4	30 ACE	SP	A		V		00:00.0
2021 PO4448288817	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4447488818	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4551288063	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4550888069	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4550288079	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4447288810	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4446588807	F	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4446488799	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4555688048	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4555088057	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4554388068	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4553888075	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4556088023	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4555988031	LGE	4	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PV4556288028	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021 PO4556888039	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4558288042	F	4	30 BRO	SP	A		V		00:00.0
2021 PO4901084754	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4446788778	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4452388769	F	4	35 ACE	SP	A		V		00:00.0
2021 PO4453088771	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4857185455	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4902084741	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4903884715	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4451888789	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4451088798	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4860785443	LGE	6 35E	ACE	SP	CRE	ED	BD		00:00.0
2021 PO4857985421	LGE	4	40 ACE	SP	A	ED,ID	BX	RR	00:00.0
2021 PO4452488775	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4451388783	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4858485421	LGE	4	40 ACE	SP	P	ED,IP	BD		00:00.0
2021 PO4450988780	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4905384696	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4860285421	LGE	4	40 ACE	SP	A	ED,IP	BD		00:00.0

2021 PO4861985421	LGE	4	40 ACE	SP	P	ED	VX	PX	00:00.0
2021 PO4863685421	LGE	4	40 ACE	SP	P	ED,IP	BD		00:00.0
2021 PO5170009434	KU	6	30 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO5236408803	KU	5	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5128209470	KU	6	30 XXX	SP	S		V		00:00.0
2021 PO5171609503	KU	6	30 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO5166208267	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5187109495	KU	6	30 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO5205508810	KU	5	35 XXX	SP	CCA		V		00:00.0
2021 PO5016808728	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5172408349	KU	5	35 XXX	SP	S		V		00:00.0
2021 PO5021108411	KU	5	35 XXX	SP	S		V		00:00.0
2021 PO5074009198	KU	5	35 XXX	SP	S		V		00:00.0
2021 PO5050308976	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5158909504	KU	6	30 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO5180408948	F	4	40 XXX	SP	S		V		00:00.0
2021 PO5177009618	KU	6	30 XXX	SP	S		V		00:00.0
2021 PO4458288697	F	3	45 ACE	SP	A		V		00:00.0
2021 PO4458688688	LGE	4	35 ACE	OT	CRE		V		00:00.0
2021 PO4008783877	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4455088668	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4453388629	F	4	30 ACE	SP	CRE	ED	V		00:00.0
2021 PO4009583890	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4010983883	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4011683879	F	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4560287978	LGE	4	40 BRO	SP	CRE	ED,ID,IP,MD	BD		00:00.0
2021 PO4559687987	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4559087995	LGE	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PV4558880003	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4558088010	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4557488019	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4451688634	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4558888068	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4846585827	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4833985905	LGE	4	35 ACE	SP	CCA	ED	V		00:00.0
2021 PO4969284827	LGE	3	45 BRO	SP	A	ID	BD		00:00.0
2021 PO2143674365	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4479188644	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO4969384845	LGE	3	45 BRO	SP	A	ID	BD		00:00.0
2021 PO4968884860	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4891910083	F	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4895110128	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO4907410057	KU	2	65 XXX	ST	CCA		V		00:00.0
2021 PO4918309993	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4931309918	KU	2	60 XXX	ST	CCA		V		00:00.0
2021 PO4943109848	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO4482988619	LGE	1	45 ACE	COMP	CCA		V		00:00.0
2021 PO4480788615	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO4480988611	LGE	1	45 ACE	COMP	CCA		V		00:00.0
2021 PO6629263370	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO6638963489	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO6654563680	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4954085028	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4463188605	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0

2021 PO4462988611	LGE	4	30 ACE	SP	CRE	ED	BD		00:00.0
2021 PO1727798360	LGE	4	40 ACE	SP	CRE	ED,ID,RB	X	RP2	00:00.0
2021 PO4334419599	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO4368720130	KU	6	30 XXX	SP	CRE	HH,ID	X	PX	00:00.0
2021 PO4369520273	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4370320437	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4481988612	LGE	1	45 ACE	COMP	CCA		V		00:00.0
2021 PO4371926883	KU	5	35 XXX	SP	CRE	ID,IP	BD		00:00.0
2021 PO4445530216	KU	4	40 BRN	SP	S		V		00:00.0
2021 PO4448130564	KU	5	45 XXX	SP	CCA		V		00:00.0
2021 PO2248575167	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO2238575080	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD		00:00.0
2021 PO4058584544	F	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4058784548	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4059984539	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4057784550	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4058084554	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4057384559	F	4	40 BRO	SP	P		V		00:00.0
2021 PO4056584560	F	4	30 BRO	SP	P		V		00:00.0
2021 PO4067685483	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4068585497	F	4	25 BRN	SP	S		V		00:00.0
2021 PO4068885492	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4045585330	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO7541015327	KU	2	70 ACW	SP	S		V		00:00.0
2021 PO7552615317	KU	5	35 ACW	SP	S		V		00:00.0
2021 PO7562015310	KU	2	60 ACW	SP	S		V		00:00.0
2021 PO7597315280	KU	3	70 ACW	SP	CRE		V		00:00.0
2021 PO7626115247	KU	2	70 ACW	SP	CRE		V		00:00.0
2021 PO7650015223	KU	2	70 ACW	SP	CRE		V		00:00.0
2021 PO6606449361	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO4045685342	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4045885368	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4045785355	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4045885381	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4045985394	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4046085406	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4045485421	F	4	30 BRN	SP	P		V		00:00.0
2021 PO4046185423	F	4	45 BRN	SP	P		V		00:00.0
2021 PO4046285434	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4046285446	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4046385460	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4046485473	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4046585486	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4046685499	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4046385502	F	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4046685511	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4046785523	F	4	35 BRN	SP	P		V		00:00.0
2021 PO4046485515	F	4	35 BRN	SP	P		V		00:00.0
2021 PO5620040616	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO3962311420	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO3976311544	KU	7	30 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4008411723	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4000111883	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4115084987	LGE	3	45 ACE	SP	CCA		V		00:00.0



2021	PO5630840908	F	4	40 BRO	SP	S		V		00:00.0
2021	PO7934315112	KU	2	70 ACW	SP	CRE		V		00:00.0
2021	PO4469602868	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4465402997	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO6546751401	KU	4	45 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO4126085592	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4126185601	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4126185618	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4126285633	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO5880538263	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO5869838069	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO5889537967	KU	4	40 BRO	SP	S		V		00:00.0
2021	PO6554851377	F	6	30 UNK	SP	CRE		V		00:00.0
2021	PO4126785639	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4127785641	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO5726736187	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4454002305	KU	4	40 BRN	SP	CRE		B		00:00.0
2021	PO4086585170	LGE	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021	PO4085085182	LGE	1	35 BRO	WC	CRE	ED,EP,ID,RB	BX	PX	00:00.0
2021	PO4085585179	LGE	4	45 BRO	SP	CCA		V		00:00.0
2021	PO4086385179	LGE	4	35 BRO	SP	CRE	ID	TD		00:00.0
2021	PO4086385167	LGE	3	25 BRO	SP	CCA		V		00:00.0
2021	PO4085885170	LGE	4	45 BRO	SP	CRE	ID	BD		00:00.0
2021	PO3952713080	KU	6	30 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO3965212983	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO5492529071	F	4	40 BRO	SP	S		V		00:00.0
2021	PO4055285367	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4056385381	F	4	30 BRN	SP	CCA		V		00:00.0
2021	PO4056685374	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO5483228952	F	4	40 BRO	SP	A		V		00:00.0
2021	PO5435527991	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4055084627	LGE	2	50 BRO	ST	CCA		V		00:00.0
2021	PO6613451629	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021	PO6619551586	F	6	30 UNK	SP	CCA		V		00:00.0
2021	PO4057785361	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4057785380	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4058585392	F	4	35 BRN	SP	CRE		V		00:00.0
2021	PO4058885384	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4059785395	F	4	30 BRN	SP	CCA		V		00:00.0
2021	PO4059985387	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4060985398	F	4	25 BRN	SP	CRE		V		00:00.0
2021	PO4061185390	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4054284582	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO3975810595	KU	6	30 XXX	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021	PO4083085052	LGE	4	40 BRO	SP	P	ID	TD		00:00.0
2021	PO4011411548	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO6583249609	F	5	35 UNK	SP	CCA		V		00:00.0
2021	PO6575949495	F	3	40 UNK	SP	CCA		V		00:00.0
2021	PO4087485128	LGE	4	35 BRO	SP	CRE	ED,EP,ID,IP	TX	RR	00:00.0
2021	PO4086885117	LGE	4	35 BRO	SP	CRE	ID	TD		00:00.0
2021	PO4062285420	F	4	45 BRN	SP	CRE		V		00:00.0
2021	PO4063485449	F	4	25 BRN	SP	CRE		V		00:00.0
2021	PO4063485440	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4065685439	F	4	40 BRN	SP	CRE		V		00:00.0

2021 PO4064385429	F	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4065685435	F	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4064485441	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4065085457	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4066185460	F	4	35 BRN	SP	P		V	00:00.0
2021 PO4065985466	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4067085469	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4064385463	F	4	25 BRN	SP	CRE		V	00:00.0
2021 PO4066785474	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4122685046	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4123285048	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4123285035	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO7733715152	KU	2	65 ACW	SP	CRE		V	00:00.0
2021 PO7870415105	KU	1	70 ACW	SP	CRE		V	00:00.0
2021 PO7905915107	KU	2	70 ACW	SP	CRE		V	00:00.0
2021 PO4119984974	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4118684977	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO6854252795	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO6869653162	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4117284980	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4116384986	LGE	4	30 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO5639140864	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5645340959	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4115484992	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO8000415116	KU	2	70 ACW	SP	S		V	00:00.0
2021 PO7998315394	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO7989815123	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO7984215433	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO8069415161	KU	1	70 ACW	SP	S		V	00:00.0
2021 PO8034115117	KU	1	70 ACW	SP	CRE		V	00:00.0
2021 PO7972015117	KU	2	65 ACW	SP	CRE		V	00:00.0
2021 PO7952315115	KU	2	60 ACW	SP	CRE		V	00:00.0
2021 PO9645017467C	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO9645017467B	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO8875567643	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4159785538	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4159885552	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4159985559	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4159985565	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4156685583	F	3	50 BRO	SP	P		V	00:00.0
2021 PO4157785587	F	4	30 BRO	SP	CCA		V	00:00.0
2021 PO3496423939	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4085184705	LGE	4	30 BRO	SP	CRE	ED,ID,RB	TX RR	00:00.0
2021 PO5912738950	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5917638874	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3493124679	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4372803049	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4388903121	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX RR	00:00.0
2021 PO4097585239	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4086184841	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP	TD	00:00.0
2021 PO4096285240	LGE	4	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4094885241	LGE	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4410403213	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4424003337	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0

2021 PO4085584846	LGE	4	30 BRO	SP	CRE	ED,ID,IP,RB			TX	RR	00:00.0
2021 PO3518624818	F	4	40 XXX	SP	P				V		00:00.0
2021 PO3514024868	F	4	40 XXX	SP	P				V		00:00.0
2021 PO3527324883	F	4	40 XXX	SP	P				V		00:00.0
2021 PO3544925000	F	4	40 XXX	SP	P				V		00:00.0
2021 PO4048885381	F	4	40 BRN	SP	CRE				V		00:00.0
2021 PO4047985395	F	4	25 BRN	SP	CRE				V		00:00.0
2021 PO4048985394	F	4	40 BRN	SP	CCA				V		00:00.0
2021 PO4048985410	F	4	25 BRN	SP	S				V		00:00.0
2021 PO4050885421	F	4	40 BRN	SP	P				V		00:00.0
2021 PO4050585416	F	4	40 BRN	SP	CCA				V		00:00.0
2021 PO4049485405	F	4	40 BRN	SP	CCA				V		00:00.0
2021 PO4052385414	F	4	40 BRN	SP	CCA				V		00:00.0
2021 PO4093685242	LGE	4	40 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4085684868	LGE	5	25 BRO	SP	CRE	ED,ID			BD		00:00.0
2021 PO4087784868	LGE	5	25 BRO	SP	CRE				V		00:00.0
2021 PO4092485243	LGE	4	40 BRO	SP	CRE	ID			TD		00:00.0
2021 PO4085784860	LGE	4	40 BRO	SP	CRE	ED,ID			BD		00:00.0
2021 PO4091285244	LGE	4	40 BRO	SP	CRE	ID,IP			TD		00:00.0
2021 PO4090085245	LGE	4	40 BRO	SP	CRE	ID			TD		00:00.0
2021 PO4089385245	LGE	4	40 BRO	SP	CRE	ID			TD		00:00.0
2021 PO4450103615	KU	4	40 BRN	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO5535729684	KU	5	35 BRO	SP	A				V		00:00.0
2021 PO5505629266	KU	5	35 BRO	SP	CRE				V		00:00.0
2021 PO5481829994	F	4	40 BRO	SP	CRE				V		00:00.0
2021 PO8012963826	LGE	3	95 BRO	SP	CRE	ID			BD		00:00.0
2021 PO4127084877	LGE	3	45 ACE	SP	CCA				V		00:00.0
2021 PO4127284886	LGE	5	30 ACE	SP	P	ED,ID			TD		00:00.0
2021 PO4127784887	LGE	4	30 ACE	SP	P	ED,ID			TD		00:00.0
2021 5970140015A	KU	5	30 BRO	SP	CCA				V		00:00.0
2021 PO5970140015	KU	5	45 BRO	SP	CRE				V		00:00.0
2021 PO5984940213	KU	5	45 BRO	SP	CCA				V		00:00.0
2021 PO5954940445	KU	5	45 BRO	SP	CRE				V		00:00.0
2021 PO6344550615	KU	5	35 UNK	SP	CRE	ID,IP			TD		00:00.0
2021 PO6006740165	KU	3	45 BRO	SP	CCA				V		00:00.0
2021 PO4023385431	F	4	40 BRN	SP	CCA				V		00:00.0
2021 PO4024585430	F	4	40 BRN	SP	CRE				V		00:00.0
2021 PO4025885428	F	4	40 BRN	SP	P				V		00:00.0
2021 PO4026985427	F	4	40 BRN	SP	P				V		00:00.0
2021 PO4028285426	F	4	40 BRN	SP	CCA				V		00:00.0
2021 PO4029485425	F	4	40 BRN	SP	P				V		00:00.0
2021 PO4030585424	F	4	40 BRN	SP	P				V		00:00.0
2021 PO4031885422	F	4	40 BRN	SP	P				V		00:00.0
2021 PO4033085421	F	4	40 BRN	SP	CRE				V		00:00.0
2021 PO4034285420	F	3	45 BRN	SP	CRE				V		00:00.0
2021 PO4035385419	F	4	40 BRN	SP	CCA				V		00:00.0
2021 PO4036585418	F	4	40 BRN	SP	CRE				V		00:00.0
2021 PO4037585417	F	4	40 BRN	SP	CRE				V		00:00.0
2021 PO4038885415	F	4	40 BRN	SP	CRE				V		00:00.0
2021 PO4039285416	F	4	25 BRN	SP	S				V		00:00.0
2021 PO4049885524	LGE	4	25 BRN	SP	CRE	ED,ID			X	RP3	00:00.0
2021 PO4051485519	LGE	4	40 BRN	SP	CRE	ED,ID			TD		00:00.0
2021 PO4049785520	LGE	4	40 BRN	SP	CRE	ED			BD		00:00.0
2021 PO4049785509	F	4	40 BRN	SP	CCA				V		00:00.0

2021	PO4127684889	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4127384896	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4126884905	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4125484899	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4089484791	LGE	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4448903239	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4454303237	KU	3	40 BRN	SP	CCA		V		00:00.0
2021	PO4443303202	KU	3	40 BRN	SP	CRE		V		00:00.0
2021	PO4088584774	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD		00:00.0
2021	PO4087984774	LGE	4	30 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4087684759	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP,RB	BX	RR	00:00.0
2021	PO6181341243	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4433103136	KU	3	45 BRN	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021	PO6380250570	KU	5	35 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO6404950533	KU	4	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO6188841326	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4086984751	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO8020759344	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4086284744	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4085284750	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4085884707	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4085484726	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021	PO4086084726	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO3569324806	F	4	40 XXX	SP	P		V		00:00.0
2021	PO3577724685	F	4	40 XXX	SP	P		V		00:00.0
2021	PO3576624510	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4089684853	LGE	3	45 BRO	SP	CRE		V		00:00.0
2021	PO4087684859	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4089684854	LGE	3	45 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO6190751416	KU	4	40 UNK	SP	CRE	ED,ID	BD		00:00.0
2021	PO5556029908	KU	5	30 BRO	SP	CCA		V		00:00.0
2021	PO6226951210	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021	PO6229150843	F	5	35 UNK	SP	CRE		V		00:00.0
2021	PO4460003523	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO5549530385	KU	3	45 BRO	SP	A		V		00:00.0
2021	PO4129984904	LGE	7	25 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4129084893	LGE	4	30 ACE	SP	P	ED,ID,IP	TD		00:00.0
2021	PO6241750748	F	5	35 UNK	SP	CRE		V		00:00.0
2021	PO6254650717	F	5	35 UNK	SP	CRE		V		00:00.0
2021	PO6244050763	KU	6	30 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO8890367617	LGE	4	35 BRO	SP	CCA	ID	V		00:00.0
2021	PO5932239286	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4128884898	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4126984885	LGE	1	25 ACE	SP	CRE		V		00:00.0
2021	PO4090784838	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4090684841	LGE	3	45 BRO	SP	CRE		V		00:00.0
2021	PO4090184838	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4422503062	KU	3	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO3541923553	F	4	40 KOP	SP	P		V		00:00.0
2021	PO4465488619	LGE	4	40 ACE	SP	CRE	ED,ID,MD	BD		00:00.0
2021	PO5365087699	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO8368067718	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO8314167715	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO8340067720	KU	4	40 ACE	SP	CCA		V		00:00.0

2021	PO8327167719	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8300767712	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8281667705	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8336666928	KU	4	45 ACE	ST	CCA		V	00:00.0
2021	PO2413788202A	KU	6	30 KOP	SP	S		V	00:00.0
2021	PO4098385763	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4099285751	LGE	4	40 ACE	SP	A		V	00:00.0
2021	PO4099885734	LGE	4	40 ACE	SP	P	ID	BD	00:00.0
2021	PO4100085739	LGE	6	30 ACE	SP	P		V	00:00.0
2021	PO4100985735	F	4	45 ACE	SP	A		V	00:00.0
2021	PO8274265527a	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5560226840	KU	3	50 UNK	SP	CCA		V	00:00.0
2021	PO5561526740	KU	3	50 UNK	SP	CCA		V	00:00.0
2021	PO5562826642	KU	3	50 UNK	SP	CCA		V	00:00.0
2021	PO8274265527	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5568326617	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO5566926734	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5566126807	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5564126973	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO8266865173	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8274665277	KU	4	40 ACE	SP	CRE	ED,ID	V	00:00.0
2021	PO1645089372	KU	4	40 BRN	SP	CRE	ID	BX	RP1 00:00.0
2021	PO1577588479	KU	4	40 BRN	SP	CRE		V	00:00.0
2021	PO9022796366	F	5	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO9022096342	F	5	35 BRO	SP	CRE	ED	V	00:00.0
2021	PO9011796479	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO9003396527	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO8997496624	KU	6	30 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO8993796581	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO8990496507	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8981396655	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO8969096727	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO8291066855	KU	4	45 ACE	ST	CCA		V	00:00.0
2021	PO2594083549	KU	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO2601083671	KU	5	35 KOP	SP	S		V	00:00.0
2021	PO4101685973	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4100085973	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4103385972	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4103385977	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO2600483938	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO2624484436	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO2295091145	KU	7	35 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021	PO4104385971	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4105385969	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4105585970	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7890668139	KU	5	35 ACE	SP	CRE		V	00:00.0
2021	PO7893968183	KU	1	90 ACE	ST	CRE		V	00:00.0
2021	PO3978983521	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3984883516	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021	PO4106885977	LGE	4	40 ACE	SP	A	ID	TD	00:00.0
2021	PO4104085805	F	4	30 ACE	SP	CCA		V	00:00.0
2021	PO2298291189	KU	3	40 KOP	SP	CRE	ED,ID,IP,SRC	TX	RR 00:00.0
2021	PO2357390910	KU	5	40 KOP	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021	PO2574384274	KU	3	45 KOP	SP	S		V	00:00.0

2021 PO2545584446	KU	4	45 KOP	SP	S		V	00:00.0	
2021 PO2552784193	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2517184649	KU	6	30 KOP	SP	S		V	00:00.0	
2021 PO2539984617	KU	4	40 KOP	SP	S		V	00:00.0	
2021 PO7898268571	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4108485792	LGE	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5524027516	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO7900868583	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO2356090594	KU	5	35 KOP	SP	CRE	ED,ID,SR	TD	00:00.0	
2021 PO3986783433	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO3987283441	LGE	2	90 BRO	SP	A		V	00:00.0	
2021 PO5558926954	KU	3	50 UNK	SP	CCA		V	00:00.0	
2021 PO5555627274	KU	3	50 UNK	SP	CCA		V	00:00.0	
2021 PO3982383544	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO3982783527	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO3982883515	LGE	5	25 BRO	SP	CRE		V	00:00.0	
2021 PO3981583526	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3979183524	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3980483525	F	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO5555127367	KU	3	50 UNK	SP	CCA		V	00:00.0	
2021 PO5554227429	KU	3	40 UNK	SP	CCA		V	00:00.0	
2021 PO5560427425	KU	3	50 UNK	SP	CCA		V	00:00.0	
2021 PO5559427542	KU	4	40 UNK	SP	CRE		B	00:00.0	
2021 PO5553527585	KU	5	35 UNK	SP	CRE		B	00:00.0	
2021 PO5506027669	KU	4	40 UNK	SP	CRE		B	00:00.0	
2021 PO5547227598	KU	4	40 UNK	SP	CRE		B	00:00.0	
2021 PO5540227610	KU	4	40 UNK	SP	CRE		B	00:00.0	
2021 PO5533627621	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO5526227634	KU	4	40 UNK	SP	CRE		B	00:00.0	
2021 PO5516127651	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO5270886435	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO4100185951	F	4	40 ACE	WC	CRE		V	00:00.0	
2021 PO7818267728	KU	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4080585984	F	4	30 ACE	SP	CRE		V	00:00.0	
2021 PO4082085983	LGE	4	30 ACE	SP	CRE	ED,EP,ID	TD	00:00.0	
2021 PO5258586225	KU	5	35 ACE	SP	CRE	ID,IP,RB	TX	RR	00:00.0
2021 PO5238786466	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO5202186547	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO8994595487	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8913595414	KU	4	50 OTH	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8933895456	KU	4	45 OTH	SP	CRE	ED,ID	BD	00:00.0	
2021 PO8954395487	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8950695494	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8943795505	KU	6	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9003396169	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5989588205	KU	6	30 ACE	SP	CRE	ID,RB	X	RP3	00:00.0
2021 PO2411092893	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0	
2021 PO5984088123	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO5983688327	KU	4	40 ACE	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO5991588560	KU	6	30 ACE	SP	CRE		V	00:00.0	
2021 PO5983688551	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO5973486716	KU	5	35 ACE	SP	CRE	ID,IP	TD	00:00.0	
2021 PO6013586760	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO3989983568	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	

2021 PO3989283569	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO2411092893a	KU	2	35 BRN	SP	CCA		V		00:00.0
2021 PO2419692924	KU	5	40 BRN	SP	CCA		V		00:00.0
2021 PO8340266626	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO2467492902	KU	3	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO2448692660	KU	3	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO2409586560	KU	6	30 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4099185759	F	4	40 ACE	SP	A		VX	RP1	00:00.0
2021 PO2331992361	KU	6	40 BRN	SP	CRE	ED	TD		00:00.0
2021 PO3991283577	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO5457427236	KU	5	35 UNK	SP	CRE		B		00:00.0
2021 PO5449927195	KU	3	50 UNK	SP	CCA		V		00:00.0
2021 PO2485486519	KU	4	40 KOP	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2457786065	KU	4	45 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO2507686176	KU	6	30 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO2492586140	KU	4	50 KOP	SP	CRE	ED,ID	BX	RP1	00:00.0
2021 PO3991183567	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO3991183567-A	KU	5	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO3991283577-A	KU	5	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO2396292027	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO5445827071	KU	2	45 UNK	SP	CRE		B		00:00.0
2021 PO5446127031	KU	3	50 UNK	SP	CCA		V		00:00.0
2021 PO5446227011	KU	3	45 UNK	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO2391892223	KU	6	40 BRN	SP	CCA		V		00:00.0
2021 PO2395092339	KU	7	35 BRN	SP	CCA		V		00:00.0
2021 PO8443566778	KU	2	65 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8463466803	KU	2	60 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8417566748	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8472966563	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO8392666719	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8365566670	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO8367766674	KU	3	50 ACE	SP	CCA		V		00:00.0
2021 PO2381392400	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021 PO2441292476	KU	3	40 BRN	SP	CRE	ED,ID,IP,SRC	TD		00:00.0
2021 PO5977487292	KU	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO5980787697	KU	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO5979988033	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO2427186615	KU	5	35 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO5573926904	KU	5	35 UNK	SP	CCA		V		00:00.0
2021 PO5584526848	F	6	30 UNK	SP	CRE		V		00:00.0
2021 PO5583026910	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO5579926908	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO8313766585	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO8286166536	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO2482993450	F	7	30 BRN	SP	P		V		00:00.0
2021 PO2457793197	KU	7	30 BRN	SP	CCA		V		00:00.0
2021 PO2472693220	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO2503493447	KU	4	40 BRN	SP	CRE	ED,SRS	TD		00:00.0
2021 PO4099185729	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4100285722	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4101185719	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO9025595657	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9015795470	KU	5	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9015995392	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0

2021 PO9023695600	F	5	35 KOP	SP	P		V			00:00.0
2021 PO9015095600	F	5	35 KOP	SP	P		V			00:00.0
2021 PO9007295600	KU	5	40 UNK	SP	CRE	ED,ID	BD			00:00.0
2021 PO8980495582	KU	4	45 UNK	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO8974595519	KU	5	35 UNK	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO8972295472	KU	4	45 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO5598526918	KU	5	35 UNK	SP	CRE		B			00:00.0
2021 PO5606826923	KU	5	35 UNK	SP	CCA		V			00:00.0
2021 PO8270266514	KU	4	45 ACE	SP	CCA		V			00:00.0
2021 PO4102685710	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4101585709	LGE	4	40 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO8252466483	KU	3	55 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO5582027010	KU	2	40 UNK	SP	CRE		B			00:00.0
2021 PO5580227163	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO3987883570	F	3	45 BRO	SP	A		V			00:00.0
2021 PO5579127284	KU	4	40 UNK	SP	CRE	ED,ID,RB	BX		PX	00:00.0
2021 PO4101985717	LGE	4	40 ACE	SP	P	ED,ID,RB	TX		RR	00:00.0
2021 PO2488393491	KU	6	35 BRN	SP	CRE	ED,SRS	TD			00:00.0
2021 PO2480993621	KU	7	35 BRN	SP	CCA		V			00:00.0
2021 PO8226766447	KU	3	45 ACE	SP	CRE	ED,ID	TD			00:00.0
2021 PO5588427390	KU	2	50 UNK	SP	CCA		V			00:00.0
2021 PO5583327381	KU	2	50 UNK	SP	CCA		V			00:00.0
2021 PO5578127419	KU	4	40 UNK	SP	CCA		V			00:00.0
2021 PO3987783560	F	3	45 BRO	SP	CCA		V			00:00.0
2021 PO2478286875	KU	4	40 KOP	SP	CRE	ED,ID	TD			00:00.0
2021 PO2478387490	KU	6	30 KOP	SP	CRE	ED,ID	BD			00:00.0
2021 PO3987783551	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO6964747014	LGE	4	30 BRO	SP	CCA		V			00:00.0
2021 PO6953346981	LGE	4	30 BRO	SP	CCA		V			00:00.0
2021 PO3978083522	F	4	40 BRO	SP	CCA		V			00:00.0
2021 PO3976980364	F	4	40 BRO	SP	A		V			00:00.0
2021 PO7985166826a	KU	1	55 ACE	SP	CRE	ED,HH,ID,RB	BX		PX	00:00.0
2021 PO7985166826	KU	1	55 ACE	SP	CCA		V			00:00.0
2021 PO8013766641	KU	1	45 ACE	SP	CCA		V			00:00.0
2021 PO3975783520	LGE	3	45 BRO	SP	CCA		V			00:00.0
2021 PO4101285766	LGE	4	35 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO3974583519	F	4	40 BRO	SP	A		V			00:00.0
2021 PO3973383517	F	4	40 BRO	SP	CCA		V			00:00.0
2021 PO3972083516	F	4	40 BRO	SP	A		V			00:00.0
2021 PO3970983508	F	5	25 BRO	SP	CRE		V			00:00.0
2021 PO3970983515	F	4	40 BRO	SP	A		V			00:00.0
2021 PO4103685760	LGE	4	40 ACE	SP	CRE	ID	BD			00:00.0
2021 PO4102885749	LGE	4	35 ACE	SP	CCA		V			00:00.0
2021 PO4103985785	LGE	4	40 ACE	SP	CCA		V			00:00.0
2021 PO8039166539	KU	4	45 ACE	SP	CCA		V			00:00.0
2021 PO7946267080	KU	1	75 ACE	SP	CCA		V			00:00.0
2021 PO7948267092	KU	2	65 ACE	SP	CCA		V			00:00.0
2021 PO7933967265	KU	2	70 ACE	SP	CCA		V			00:00.0
2021 PO7909367726	KU	2	80 ACE	SP	CRE		V			00:00.0
2021 PO7902567921	KU	1	85 ACE	SP	CCA		V			00:00.0
2021 PO7921067500	KU	1	75 ACE	SP	CCA		V			00:00.0
2021 PO3999983596	LGE	4	35 BRO	SP	CCA		V			00:00.0
2021 PO4011083757	LGE	3	45 BRO	SP	CCA		V			00:00.0
2021 PO7896768097	KU	4	45 ACE	SP	CRE	ED,ID	BD			00:00.0



2021 PO8312966892	KU	4	45 ACE	ST	CCA		V		00:00.0
2021 PO4004483689	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4107685795	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4105585802	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4106885797	LGE	7	25 ACE	SP	CRE	ED,MD	VX	RP1	00:00.0
2021 PO4106985794	LGE	4	40 ACE	SP	A	ED,ID,IP	BD		00:00.0
2021 PO4105585794	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4106685796	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO7812767943	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4005883696	LGE	1	90 BRO	SP	A		V		00:00.0
2021 PO2519985243	KU	4	35 KOP	SP	CRE	ED,ID,MD,RB	X	PX	00:00.0
2021 PO2512685469	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO2492685085	KU	3	45 KOP	SP	S		V		00:00.0
2021 PO2493385195	KU	5	35 KOP	SP	CRE	ED,ID	BD		00:00.0
2021 PO2469385146	KU	5	35 KOP	SP	CRE	ED,ID	BD		00:00.0
2021 PO2463785246	KU	6	30 KOP	SP	CRE	ED,ID	BD		00:00.0
2021 PO4005083698	LGE	4	35 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4005583706	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO2330690713	KU	4	35 KOP	SP	CCA	ED,ID	TD		00:00.0
2021 PO5717487645	KU	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO5718887421	KU	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO5749587511	KU	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO4005983717-A	KU	5	35 BRO	SP	A	ID	BD		00:00.0
2021 PO4005983717	LGE	3	45 BRO	SP	A	ID	BD		00:00.0
2021 PO4006383718	LGE	4	30 BRO	SP	A	ID	BD		00:00.0
2021 PO5529926871	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO7784967810	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO7782367878	KU	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5545326821	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO5557326893	KU	5	35 UNK	SP	CCA	ID,RB	BX	RP2	00:00.0
2021 PO2282990975	KU	3	45 KOP	SP	CCA		V		00:00.0
2021 PO2306390844	KU	3	45 KOP	SP	CCA		V		00:00.0
2021 PO2332991656	KU	3	45 KOP	SP	CCA		V		00:00.0
2021 PO4117385729	LGE	1	85 BRN	SP	CRE		V		00:00.0
2021 PO4116485716	LGE	1	85 BRN	SP	CRE		V		00:00.0
2021 PO4115685700	LGE	1	95 BRN	SP	CRE		V		00:00.0
2021 PO2218533161	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO3128002072-A	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO2239033178	KU	3	45 BRN	SP	CRE		V		00:00.0
2021 PO7327081216	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO4197486346	LGE	4	40 BRO	SP	A	ED,EP,ID,RB	BX	RR	00:00.0
2021 PO4761406867	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO3134501895-A	KU	6	30 UNK	SP	CRE	ID	BD		00:00.0
2021 PO3134501895	F	4	30 UNK	SP	A		V		00:00.0
2021 PO5128604514	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO3147801916	KU	6	30 UNK	SP	CCA		V		00:00.0
2021 PO3128002072	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO7326881064	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7326881277	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4776806661	F	5	35 XXX	SP	CRE		V		00:00.0
2021 PO4765606660	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4751807052	F	5	35 XXX	SP	CRE		V		00:00.0
2021 PO4734307104	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4755307278	F	5	35 XXX	SP	CRE		V		00:00.0

2021 PO4736307244	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4286599098	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO4310499008	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO4426798475	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO4404298599	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO4387498682	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO4364898817	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO4419798211	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO4439198406	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO4448997831	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO4452098053	KU	3	40 UNK	SP	CCA		V	00:00.0	
2021 PO4112285722	LGE	4	40 BRN	SP	CRE	ID,IP,SRS	TD	00:00.0	
2021 PO4112285723	LGE	4	30 BRN	SP	P	ID	TD	00:00.0	
2021 PO5137304983a	KU	6	35E BRN	SP	CCA	ED	TD	00:00.0	
2021 PO5122604806	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5137304983	KU	7	30 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4179886620	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO4180386628	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO4180786637	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO4179786621	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4113885718	LGE	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4113885712	LGE	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0	
2021 PO4112285708	LGE	4	30 BRN	SP	P	ED,ID	TD	00:00.0	
2021 PO4111385712	LGE	1	65 BRN	SP	P		V	00:00.0	
2021 PO4110385713	LGE	2	65 BRN	SP	CRE	HH,RB	X	PX	00:00.0
2021 PO4106485715	LGE	3	45 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO7651382351	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO2405115156	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO5174604858	KU	7	30 BRN	SP	CRE	ED,HH,ID,RB	X	RP1	00:00.0
2021 PO5168905055	KU	3	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7544682943	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4179286625	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO2432715406	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO2466515684	KU	4	40 BRN	SP	CRE	ID,IP,MD	BD	00:00.0	
2021 PO4178986640	LGE	5	35 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO7537583165	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7511583233	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7486783448	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4178386629	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4135586293	LGE	3	50 BRN	SP	CCA		V	00:00.0	
2021 PO4133886295	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4132286297	LGE	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4442608707	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4429008820	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO4468909026	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4453109122	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO7110722241	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7106522023A	KU	5	35 ACW	SP	CRE	ED,HH,ID,MD,RB	X	PX	00:00.0
2021 PO7130522601	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO7122622457	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7125822632	KU	5	35 ACW	SP	CRE		V	00:00.0	
2021 PO4178186634	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4129286300	LGE	4	40 BRN	SP	P	ID	TD	00:00.0	
2021 PO5186104657	KU	7	35 BRN	SP	CRE	ED,ID	TD	00:00.0	

2021	PO5167104715	KU	3	35 BRN	SP	CCA	ED	TD	00:00.0
2021	PO5187105366	KU	7	35 BRN	SP	CRE	ED,ID	B	00:00.0
2021	PO4469908535	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4456708593	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4499108855	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4483308932	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4112285733	LGE	4	40 BRN	SP	P	HH,ID,RB	RP2	00:00.0
2021	PO4440897903	KU	6	30 UNK	SP	CRE		V	00:00.0
2021	PO7953781234	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO7948381335	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO7932181273	F	4	40 BRO	SP	CRE		V	00:00.0
2021	7896281120A	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO7896281120	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO7911181114	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO7802081639	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO7807881597	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO7763481669	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO7735081749	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO7706082027	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO0807348246	KU	6	30 BRN	SP	CRE	ED,EP,HH,ID,IP,RB	PX	00:00.0
2021	PO0820248385	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO6835518395	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO6820518385	KU	6	30 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO7686782570	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO7531381433	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5152405267	KU	2	70 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO5133505317	KU	4	45 BRN	SP	CRE		B	00:00.0
2021	PO9727214127	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO4009800113	KU	3	40 UNK	SP	CCA		V	00:00.0
2021	PO4028200037	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4062999934	KU	3	40 UNK	SP	CCA		V	00:00.0
2021	PO4081699870	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4075999739	KU	4	45 UNK	SP	CCA		V	00:00.0
2021	PO0779548594	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021	PO0800448484	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5138005367	KU	2	70 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO0777248516	F	5	35 BRN	SP	CRE		V	00:00.0
2021	PO0779548594	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO7502781227	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7475181027	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6819017652	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6811517642	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6829017401	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO4125486058	LGE	4	35 BRN	SP	CRE	ID	BD	00:00.0
2021	PO8928877848	LGE	4	35 BRO	SP	P		V	00:00.0
2021	PO4124486064	LGE	3	35 BRN	SP	CCA		V	00:00.0
2021	PO4124586063	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4124386067	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021	PO4123886057	LGE	1	60 BRN	SP	S		V	00:00.0
2021	PO0765848711	KU	4	45 BRN	SP	CRE	ED,ID,IP,MD	TD	00:00.0
2021	PO5161904885	KU	5	35 BRN	SP	CRE		V	00:00.0
2021	PO5182505501	F	6	40 BRN	SP	CRE	ED,HH,ID,RB	BX	RP1 00:00.0
2021	PO4123086043	LGE	1	55 BRN	SP	CCA		V	00:00.0
2021	PO8234968847	LGE	3	65 BRN	SP	P		V	00:00.0

2021	PO0760048653	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021	PO7397180817	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7371280912	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5171905564	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO0805950636	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0805151028	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0819951177	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5199104611	KU	6	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4485707657	F	4	45 KOP	SP	CCA		V	00:00.0
2021	PO4476507688	F	4	45 KOP	SP	P		V	00:00.0
2021	PO4469307715	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4447907772	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4453707768	F	4	45 KOP	SP	P		V	00:00.0
2021	PO4436907828	F	4	40 KOP	SP	P		V	00:00.0
2021	PO4409507926	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4415308104	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4444608188	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021	PO4438308339	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4418208399	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4414208268	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4427508259	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4421008264	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4390807994	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4382508022	F	4	40 KOP	SP	P		V	00:00.0
2021	PO4367508079	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4175886626	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO7390081002	KU	5	30 BRO	SP	CRE	ED,HH,ID,RB	BX RP3	00:00.0
2021	PO7381981224	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO7146522747	KU	5	35 ACW	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7154422715	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO7139422359	KU	3	45 ACW	SP	S		V	00:00.0
2021	PO7157522211	KU	4	45 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO7183422174	KU	4	45 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO7190922740	KU	6	30 ACW	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7186522610	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO6809718955	KU	4	40 ACW	SP	S		V	00:00.0
2021	PO4122486306	LGE	4	40 BRN	SP	CRE	ID,IP	TD	00:00.0
2021	PO4122386313	KU	4	35E BRN	SP	S		V	00:00.0
2021	PO7111878479	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO8896778183	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4178086620	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4177886621	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4453698316	KU	3	40 UNK	SP	CRE		V	00:00.0
2021	PO4463698124	KU	6	30 UNK	SP	CRE	HH,ID,RB	BX RP1	00:00.0
2021	PO4481698289-A	KU	6	35 UNK	SP	CRE	ID	TD	00:00.0
2021	PO4481698289	KU	3	45 UNK	SP	CRE		V	00:00.0
2021	PO4567198554	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO0822050871	KU	4	40 BRN	SP	CRE	EP,ID	X PX	00:00.0
2021	PO7954683881	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO8017283537	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4117086350	LGE	4	35 BRN	SP	CCA	ID,IP	TD	00:00.0
2021	PO4118086349	LGE	4	35 BRN	SP	P	ID	TD	00:00.0
2021	PO4119086348	LGE	4	35 BRN	SP	CRE	ID,IP	TD	00:00.0
2021	PO4119486354	LGE	4	35 BRN	SP	CRE		V	00:00.0

2021 PO4109986247	LGE	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4121686345	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4123886343	LGE	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4121986338	LGE	4	30 BRN	SP	P	SRC	TD		00:00.0
2021 PO4121186337	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO8343675239	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4177586577	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4176786565	F	4	35 BRO	SP	A		V		00:00.0
2021 PO4176186567	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO0746349017	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD	TD		00:00.0
2021 PO0737449141	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0723349314	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO7057221399	KU	3	50 ACW	SP	CRE	ED,ID	BD		00:00.0
2021 PO7072821627	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7098622028	KU	5	35 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO7106522023	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7086221819	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO4183686468	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4184686468	LGE	4	30 BRO	SP	CRE		V		00:00.0
2021 PO4188686482	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO418999500	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4213099423	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4238299333	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4099899808	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4117899744	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4166499582	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4141899662	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4178186591	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO5144805138	KU	5	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5177505505	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4112285778	LGE	4	40 BRN	SP	P	IP	TD		00:00.0
2021 PO4112285766	LGE	4	35 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO0756248886	KU	4	40 BRN	SP	CRE	ED,HH,ID	TD		00:00.0
2021 PO4112285755	LGE	4	40 BRN	SP	P	ID,RB	TX	RR	00:00.0
2021 PO4112285745	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4178686599	F	4	35 BRO	SP	A		V		00:00.0
2021 PO4178186588	F	4	45 BRO	SP	A		V		00:00.0
2021 PO4113885732	LGE	4	35 BRN	SP	CRE	ED,HH,ID	X	RP2	00:00.0
2021 PO4258199260	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4121086323	LGE	4	40 BRN	SP	P	ID,RB	TX	RR	00:00.0
2021 PO8054383209	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO8087382984	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0807850496	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO0788750065	KU	5	35 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4185086459	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PV8970176452	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4184486450	LGE	4	45 BRO	SP	CCA		V		00:00.0
2021 PV8985576603	LGE	4	45 BRO	SP	CCA		V		00:00.0
2021 PO4120986313	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4120986307	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4119386309	LGE	4	40 BRN	SP	CRE	ID,IP	TD		00:00.0
2021 PO4117886311	LGE	4	40 BRN	SP	CRE	ID,IP	TD		00:00.0
2021 PO4114886313	LGE	4	40 BRN	SP	CCA	ID,SRC	TD		00:00.0
2021 PO4186086478	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0

2021 8062782512A	F	6	30 BRO	SP	CCA		V	00:00.0	
2021 8032682453A	F	6	30 BRO	SP	CCA		V	00:00.0	
2021 P08062782512	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 P00800949850	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 P04187286484	LGE	4	40 BRO	SP	A	ED	T	00:00.0	
2021 P00764749649	KU	4	40 BRN	SP	CRE		V	00:00.0	
2021 P00751249755	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 P04113786314	LGE	4	40 BRN	SP	P	ID,SRS	TD	00:00.0	
2021 P04111586316	LGE	4	40 BRN	SP	P	HH,ID	TX	RR	00:00.0
2021 P04112286315	LGE	4	40 BRN	SP	P	ID	TD	00:00.0	
2021 P04579298438	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0	
2021 P04533298246	KU	5	45 UNK	SP	CCA		V	00:00.0	
2021 P04168686474	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 P04188686474	LGE	3	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 P04189586473	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 P00712449463	KU	5	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 P01882713528	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 P04133185839	LGE	5	35E BRN	SP	P	HH,ID,SRS	TX	RR	00:00.0
2021 P04134085836	LGE	5	35E BRN	SP	P		V	00:00.0	
2021 P04133485835	LGE	3	45 BRN	SP	P		V	00:00.0	
2021 P01340851317	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	00:00.0	
2021 P09139370537	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 P09153770225	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 P09178170187	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 P01351951047	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	00:00.0	
2021 P02526602699	KU	4	40 UNK	SP	CRE	HH,ID,SRS	TX	RR	00:00.0
2021 P04179086466	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 P04180086472	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 P09168670082	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021 P01361050786	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021 P01371450866	KU	4	40 BRO	SP	CRE		V	00:00.0	
2021 P01391150687	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 P02470702020	KU	4	45 UNK	SP	CCA		V	00:00.0	
2021 P02499602675	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 P02454202272	KU	3	55 UNK	SP	CRE	HH,ID,MD,SRS	TX	RR	00:00.0
2021 P09205069936	KU	4	40 BRO	SP	CRE	ED,ID,RB	X	RP3	00:00.0
2021 P09217570077	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 P01397250445	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 P01404550533	KU	6	30 BRO	SP	CRE		V	00:00.0	
2021 P02487102656	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0	
2021 P01403350202	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 P05672602161	F	4	40 BRO	SP	A		V	00:00.0	
2021 P05739602205	KU	6	35 BRO	SP	CRE	ED	TD	00:00.0	
2021 P04181786470	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 P09246070004	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 P02452302310	KU	3	55 UNK	SP	CRE	HH,ID,MD	BX	RP3	00:00.0
2021 P02456302246	KU	3	55 UNK	SP	CRE	ID,IP	TD	00:00.0	
2021 P02444502660	KU	4	45 UNK	SP	CCA		V	00:00.0	
2021 P04130285841	LGE	4	30 BRN	SP	CRE	ID	TD	00:00.0	
2021 P04129485840	LGE	3	50 BRN	SP	P	ID,IP,SRS	TD	00:00.0	
2021 P09277269617	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 P02903099368	KU	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 P02914599439	F	4	40 BRN	SP	CRE	ED,ID	V	00:00.0	
2021 P02920499189	KU	4	40 BRN	SP	CRE	ED,ID	V	00:00.0	

2021 PO2914799926	F	4	40 BRN	SP	CRE	ED,ID	V		00:00.0
2021 PO4180786537	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9094670453	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4128085831	LGE	4	35 BRN	SP	P	ID	TD		00:00.0
2021 PO4181586542	LGE	3	45 BRO	SP	CCA	ED	T		00:00.0
2021 PO4126985814	LGE	3	45 BRN	SP	CRE	ID,IP,SRC	TD		00:00.0
2021 PO2532302559	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO2544102635	KU	5	40 UNK	SP	CRE	HH,ID,SRC	TX	RR	00:00.0
2021 PO9103070457	F	5	35 BRO	SP	CRE		V		00:00.0
2021 PO9242569810	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO9243569945	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO9083370230	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4182386528	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO1856713633	KU	3	45 BRN	SP	CRE		V		00:00.0
2021 PO1871113166	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO1850913452	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO1866613023	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO1830713738	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO1824113813	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO1789513600	KU	4	40 BRN	WC	CRE	HH,ID	TD		00:00.0
2021 PO1765613309	KU	6	35 BRN	SP	CRE	ID	BD		00:00.0
2021 PO1729312998	KU	4	40 BRN	WC	CRE	ID,IP	TD		00:00.0
2021 PO1732713260	KU	5	35 BRN	SP	CRE	ED,HH,ID	X	PX	00:00.0
2021 PO1178353174	F	4	40 BRO	SP	CRE		V		00:00.0
2021 A2	KU	6	35 BRN	SP	CCA		V		00:00.0
2021 PO1762713131	KU	6	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO1769313031	KU	4	40 BRN	SP	CRE	ID,IP	TD		00:00.0
2021 PO1743912676	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO1739412587	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO1687311761	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO1687212624	KU	4	40 BRN	WC	CRE	ID	TD		00:00.0
2021 PO4182986518	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4129585829	LGE	4	40 BRN	SP	P	ID,SRS	TD		00:00.0
2021 PO2550602347	KU	6	30 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO9110170773	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9111470877	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9118370982	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4129185812	LGE	3	45 BRN	SP	CRE	ID,IP,SRS	TD		00:00.0
2021 KU	KU	4	40 BRO	SP	S		V		00:00.0
2021 PO4183586507	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO1257852213	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO1246452349	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4184186496	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO1313651813	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO4129185790	LGE	3	45 BRN	SP	CRE	ID,IP,SRS	BD		00:00.0
2021 PO5636602491	KU	7	35 BRO	SP	P	ED,HH,ID,RB	X	PX	00:00.0
2021 PO5614902390	KU	4	40 BRO	SP	CRE	ED	TD		00:00.0
2021 PO2569602175	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4133985789	LGE	4	40 BRN	SP	CCA	ID,IP,SRS	BD		00:00.0
2021 PO4134085794	LGE	4	40 BRN	SP	P	ID,SRC	TD		00:00.0
2021 PO4134685806	F	3	50 BRN	SP	P		V		00:00.0
2021 PO2596002311	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO2628202408	F	6	30 UNK	SP	CRE		V		00:00.0
2021 PO2626602327	KU	4	40 UNK	SP	CRE		V		00:00.0

2021 PO2656602340	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO1281451938	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD		00:00.0
2021 PO4182486458	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4134585814	F	3	50 BRN	SP	P		V		00:00.0
2021 PO1291951617	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO1306451660	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4134885835	LGE	3	50 BRN	SP	P	ID,SRC	TD		00:00.0
2021 PO9272469664	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO2843802055	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO2866902134	KU	5	35 BRN	SP	CRE	ED,ID	BX	RP2	00:00.0
2021 PO2637402972	KU	4	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO4179486540	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5558804605	F	3	40 BRO	SP	CRE		V		00:00.0
2021 PO5564804480	F	5	40 BRO	SP	CRE		V		00:00.0
2021 PO5554804689	F	3	40 BRO	SP	CRE		V		00:00.0
2021 PO5572604317	F	3	40 BRO	SP	CRE		V		00:00.0
2021 PO1159653460	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1169553342	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1184353103	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO2959298012	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO2939198400	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO2926398928	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4127885816	LGE	4	35 BRN	SP	P	EP,IP,MD	TX	RR	00:00.0
2021 PO6091247204	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO6189846751	KU	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6164347250	KU	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6155847404	KU	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6100447038	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO6108146857	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO6116146929	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO6126247012	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO6123947216	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4683139176	KU	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4648239233	KU	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4625239273	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4597339309	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4575539342	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4549839379	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4525339412	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4502739446	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4491339450	KU	4	35 ACE	SP	CCA		V		00:00.0
2021 PO1161353361	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD		00:00.0
2021 PO2247517462	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO2686003018	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5589303561	F	3	40 BRO	SP	P		V		00:00.0
2021 PO5583203627	F	3	40 BRO	SP	P		V		00:00.0
2021 PO5628803765	KU	3	40 BRO	SP	CCA	ED	TD		00:00.0
2021 PO2226417511	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 A3	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO2134516688	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO2146416978	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO2154717235	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO2161117493	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO2196817505	KU	4	45 BRN	SP	CCA		V		00:00.0



2021 PO9082272164	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9101871284	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4132185812	LGE	4	30 BRN	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO9069271756	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2829105403	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2844705792	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO2906907085	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO2903007127	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO2882506717	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4828802971	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4843003162	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4857303043	KU	4	40 XXX	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4844703315	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4850803400	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4826903467	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4858903215	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4865203280	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4869603380	F	6	30 XXX	SP	CRE		V	00:00.0
2021 PO4871303110	F	4	55 XXX	SP	P		V	00:00.0
2021 PO9366069594	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9368169645	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8870076540	KU	4	35 BRO	SP	CCA	ED	T	00:00.0
2021 PO0728660716	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4209386314	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4210286313	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4211286312	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4212286311	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4212886323	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4212086331	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4212786336	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4208786315	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4212886349	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4213186348	LGE	4	25 ACE	SP	A		V	00:00.0
2021 PO4212486348	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4181286479	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5726702188	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5701102081	F	6 35E	BRO	SP	CRE	ED	V	00:00.0
2021 PO5676601989	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9271069935	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0927356739	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PV4178686461	LGE	3	55 BRO	SP	CCA		V	00:00.0
2021 PO4128285841	LGE	4	35 BRN	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO9285669728	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9297269864	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0759159006	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0809559104	KU	6	30 BRO	SP	CRE	ED,EP,ID	TD	00:00.0
2021 PO0918756937	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0901457330	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO2805103067	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO2864001466	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO2852901791	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO2833002371	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4253609111	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO4267108990	KU	5	35 BRN	SP	CCA		V	00:00.0

2021 PO4252108991	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO4267109105	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO4175986507	LGE	3	55 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021 PO4176686495	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO0909257139	F	5	35 BRO	SP	CRE		V	00:00.0	
2021 PO5679601863	F	3	40 BRO	SP	P		V	00:00.0	
2021 PO5640301679	F	7	35E BRO	SP	CRE	ED	V	00:00.0	
2021 PO5675601742	F	7	35E BRO	SP	CRE		V	00:00.0	
2021 PO5682701728	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO5686601562	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO5691601342	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO5697001127	F	3	40 BRO	SP	P		V	00:00.0	
2021 PO0893857490	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO0888257639	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4127185840	LGE	3	50 BRN	SP	CRE	EP,ID,IP,SR	TX	RR	00:00.0
2021 PO4126485843	LGE	4	35 BRN	SP	CRE	EP,IP,SRS	TD		00:00.0
2021 PO0926557812	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO0873657993	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO0865958168	F	3	45 BRO	SP	P		V	00:00.0	
2021 PO0858758344	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4213686393	LGE	4	30 BRN	SP	CCA		V	00:00.0	
2021 PO9332169769	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9343469900	KU	6	35 BRO	SP	CRE	ED,ID	X	RP2	00:00.0
2021 PO4177286485	LGE	3	55 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4125185844	LGE	4	35 BRN	SP	P	ID,SRS	TD		00:00.0
2021 PO2439902449	F	6	30 UNK	SP	CRE		V	00:00.0	
2021 PO2440802290	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO2423502260	KU	5	35 UNK	SP	CRE	HH,ID	X	RP1	00:00.0
2021 PO2379602276	KU	5	35 UNK	SP	CCA		V	00:00.0	
2021 PO2377602063	KU	3	55 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021 PO0798759413	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4131085864	LGE	4	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4177886475	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO9390970312	KU	4	40 BRO	SP	S		V	00:00.0	
2021 PV8867176609	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO0765359462	KU	6	35 BRO	SP	CRE	ED,EP,ID	TD		00:00.0
2021 PO0741659493	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4135985868	LGE	4	40 BRN	SP	CCA	ID,IP	BD		00:00.0
2021 PO9381770001	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4208286316	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4210886333	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO4209386333	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO4207086318	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4207086312	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4206986303	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4213686352	LGE	4	25 ACE	SP	A		V	00:00.0	
2021 PO4213286353	LGE	4	55 ACE	SP	A		V	00:00.0	
2021 PO4211986355	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4211086356	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4210186357	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO4208986359	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO0739660881	F	5	35 BRO	SP	P		V	00:00.0	
2021 PO9410469488	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4835788736	LGE	4	40 BRO	SP	P	ED,ID,IP,MD,RB	VX	RP3	00:00.0

2021 PO9483631018	ODP	5	45 UNK	SP	CRE	ID	VX	PX	00:00.0
2021 PO4860490070	LGE	4	40 BRN	SP	A	ED	VX	PX	00:00.0
2021 PO4982089822	LGE	4	35 ACE	SP	A	ED,ID,MD	VX	RP1	00:00.0
2021 PO4946090022	LGE	4	30 BRN	SP	P	ED	VX	RP1	00:00.0
2021 PO4940489649	LGE	3	45 BRN	SP	P	ED,HH,ID,IP,RB	VX	PX	00:00.0
2021 PO4939089689	LGE	3	50 BRN	SP	CCA		V		00:00.0
2021 PO8745622092	ODP	2	50 KOP	SP	CCA		V		00:00.0
2021 PO4970689523	LGE	1	60 ACE	SP	P		V		00:00.0
2021 PO4973689515	LGE	1	20 ACE	ST	CCA		V		00:00.0
2021 PO8732921909	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO8748721509	ODP	4	40 KOP	SP	CCA		V		00:00.0
2021 PO0061236481	ODP	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4825388745	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4971889541	LGE	1	60 ACE	SP	CCA		V		00:00.0
2021 PO4969589504	LGE	1	65 ACE	SP	CCA		V		00:00.0
2021 PO7275017952	ODP	4	45 BRN	SP	CCA		V		00:00.0
2021 PO7279418042	ODP	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7267818159	ODP	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7231219407	ODP	2	50 BRN	SP	CCA		V		00:00.0
2021 PO7206119438	ODP	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7177619479	ODP	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7156219508	ODP	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7162418320	ODP	4	40 BRN	SP	CCA		V		00:00.0
2021 PO7153618558	ODP	4	40 BRN	SP	CCA		V		00:00.0
2021 PO7133718928	ODP	4	45 BRN	SP	CCA		V		00:00.0
2021 PO7114919274	ODP	2	50 BRN	SP	CCA		V		00:00.0
2021 PO7134819271	ODP	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4936689925	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO4936689925	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO4937489976	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO5304608535	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO5318708688	KU	3	45 BRN	SP	S		V		00:00.0
2021 PO5306408931	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO8796722044	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO8829622106	ODP	4	45 KOP	SP	CCA		V		00:00.0
2021 PO8812022060	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO4816488747	LGE	1	60 BRO	SP	P		V		00:00.0
2021 PO4818188747	LGE	1	70 BRO	SP	P		V		00:00.0
2021 PO4818088746	LGE	1	70 BRO	SP	CRE		V		00:00.0
2021 PO4819988749	LGE	1	70 BRO	SP	CRE		V		00:00.0
2021 PO4819788747	LGE	2	70 BRO	SP	CRE		V		00:00.0
2021 PO4823488748	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021 PO8843922131	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO8781122012	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO8753421966	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO0102036851	ODP	4	40 BRN	SP	CCA		V		00:00.0
2021 PO0081536584	F	4	40 OTH	SP	P		V		00:00.0
2021 PO4716990015	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO5223305575	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5210905368	KU	3	40 BRN	SP	CCA		V		00:00.0
2021 PO5219305580	KU	1	55 BRN	SP	CCA		V		00:00.0
2021 PO5213405430	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4884788576	LGE	4	30 BRN	SP	CRE		V		00:00.0
2021 PO0266634381	F	4	40 BRN	SP	CRE		V		00:00.0

2021 PO0270334635	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021 PO7737520342	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO7706218889	ODP	3	45 UNK	SP	CCA	V	00:00.0
2021 PO5475309714	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO5472209658	KU	3	45 BRN	SP	S	V	00:00.0
2021 PO7757218911	ODP	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4951589445	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4952789452	LGE	2	65 ACE	SP	A	V	00:00.0
2021 PO7743419812	ODP	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4729389967	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4728589957	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO4727389955	LGE	4	30 ACE	SP	A	V	00:00.0
2021 PO7750319370	ODP	4	45 UNK	SP	CCA	V	00:00.0
2021 PO5443109849	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO5928698446	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4916988870	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4917188864	F	4	40 BRO	SP	A	V	00:00.0
2021 PO6644807471	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4936289839	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021 PO7668819574	ODP	6	30 UNK	SP	CCA	V	00:00.0
2021 PO7682019622	ODP	6	30 UNK	SP	CRE	V	00:00.0
2021 PO8604921607	ODP	5	35 KOP	SP	CCA	V	00:00.0
2021 PO9643531400	ODP	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4940189791	LGE	3	45 BRN	SP	P	V	00:00.0
2021 PO7732120667	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021 PO7753320679	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO0324035334	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO0374035632	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO7741719959	ODP	2	45 BRN	SP	CCA	V	00:00.0
2021 PO5347011554	KU	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5349311607	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO8474221256	ODP	6	30 KOP	SP	CCA	V	00:00.0
2021 PO7739320086	ODP	2	50 BRN	SP	CCA	V	00:00.0
2021 PO7760619480	ODP	4	40 UNK	SP	CCA	V	00:00.0
2021 PO8911522305	ODP	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8896522304	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8921022536	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8916522454	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8906722358	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8913822580	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4934789973	LGE	1	50 BRN	SP	CCA	V	00:00.0
2021 PO9316125973	ODP	4	40 XXX	SP	CCA	V	00:00.0
2021 PO4714189941	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4713389955	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4713989959	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO4975789599	LGE	1	60 ACE	SP	A	V	00:00.0
2021 PO4974789584	LGE	1	60 ACE	SP	A	V	00:00.0
2021 PO4973389563	LGE	1	60 ACE	SP	CCA	V	00:00.0
2021 PO4856988599	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4858588649	LGE	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4858088631	LGE	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4929789952	LGE	1	50 BRN	SP	CCA	V	00:00.0
2021 PO8744322255	ODP	4	40 KOP	SP	CCA	V	00:00.0
2021 PO4909188985	LGE	4	40 BRO	SP	CCA	V	00:00.0

2021 PO4935589938-a	LGE	4	40 BRN	SP	P	V	00:00.0
2021 PO4862188640	LGE	3	45 BRN	SP	A	V	00:00.0
2021 PO4721789884	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO0408037932	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021 PO0395338213	ODP	3	45 BRN	SP	CCA	V	00:00.0
2021 PO0386838245	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021 PO4895689097	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO7651719960	ODP	4	45 BRO	SP	CCA	V	00:00.0
2021 PO4883988574	LGE	2	55 BRN	SP	CCA	V	00:00.0
2021 PO8833722515	ODP	4	40 KOP	SP	CRE	V	00:00.0
2021 PO8813622384	ODP	4	40 KOP	SP	CRE	V	00:00.0
2021 PO0337438216	ODP	5	35 BRN	SP	CRE	V	00:00.0
2021 PO0323138196	F	5	40 KOP	SP	P	V	00:00.0
2021 PO9010619943	ODP	4	45 KOP	SP	S	V	00:00.0
2021 PO4916588873	F	4	40 BRO	SP	A	V	00:00.0
2021 PO7786519226	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021 PO4731889990	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO7802418916	F	2	55 BRN	SP	CCA	V	00:00.0
2021 PO4215587614	F	4	40 ACE	UN	P	V	00:00.0
2021 PO4951889466	LGE	2	65 ACE	SP	P	V	00:00.0
2021 PO4730489977	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO6465211027	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO7603720683	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO0401938596	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO9690931264	F	4	40 UNK	SP	P	V	00:00.0
2021 PO5238499146	LGE	3	40 BRO	SP	CCA	V	00:00.0
2021 PO4822488697	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO4709089818	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO9241524053	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO9255923840	ODP	4	45 BRO	SP	CCA	V	00:00.0
2021 PO9262523883	ODP	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4935889004	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4871089736	LGE	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4812488611	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021 PO5233698525	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4824188824	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4826888818	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO8642821612	ODP	6	30 KOP	SP	CCA	V	00:00.0
2021 PO4733090014	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO4937189839	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4870889735	LGE	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4869189729	LGE	1	65 BRN	SP	P	V	00:00.0
2021 PO4866889721	LGE	H2	80 BRN	SP	P	V	00:00.0
2021 PO4865089714	LGE	1	90 BRN	SP	P	V	00:00.0
2021 PO4863289707	LGE	1	90 BRN	ST	P	V	00:00.0
2021 PO4860589698	LGE	1	95 BRN	ST	P	V	00:00.0
2021 PO4857889689	LGE	1	95 BRN	ST	P	V	00:00.0
2021 PO4855289682	LGE	1	95 BRN	ST	P	V	00:00.0
2021 PO5335310186	KU	3	45 BRN	SP	S	V	00:00.0
2021 PO5356110212	KU	2	50 BRN	SP	CRE	V	00:00.0
2021 PO4966989440	LGE	1	50 ACE	SP	CCA	V	00:00.0
2021 PO5370510154	KU	4	45 BRN	SP	S	V	00:00.0
2021 PO4707489844	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4884589780	LGE	1	65 BRN	ST	P	V	00:00.0

2021 PO4882789778	LGE	1	70 BRN	ST	P		V	00:00.0
2021 PO4880789771	LGE	1	75 BRN	ST	P		V	00:00.0
2021 PO4879489764	LGE	1	75 BRN	ST	P		V	00:00.0
2021 PO4876189758	LGE	1	75 BRN	ST	P		V	00:00.0
2021 PO4873689750	LGE	1	75 BRN	SP	P		V	00:00.0
2021 PO4871489738	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO5365111858	KU	2	40 BRN	SP	CRE		V	00:00.0
2021 PO6925518833	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4825188889	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO0180033681	ODP	5	35 BRN	SP	CRE		V	00:00.0
2021 PO0177333759	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO0185533963	ODP	4	45 BRN	SP	CRE		V	00:00.0
2021 PO0138534219	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO5388712995	KU	6	30 BRN	SP	S		V	00:00.0
2021 PO0178834728	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4872989768	LGE	4	25 BRN	SP	CRE		V	00:00.0
2021 PO4945089013	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO0199334088	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO0147734411	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4944090154	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4858189846	LGE	3	50 BRN	SP	P	ED	V	00:00.0
2021 PO4944690177	F	3	45 BRN	SP	P		V	00:00.0
2021 PO6521115139	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6527115384	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6532715633	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4946890281	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO9209024569	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9204924669	ODP	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9218424372	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO7539920272	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5416112983	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO5412813016	KU	4	45 BRN	SP	S		V	00:00.0
2021 PO5425512889	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO7404020806	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO8152419825	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4880189791	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO5447812499	KU	4	40 KOP	SP	S		V	00:00.0
2021 PO5420913122	F	6	30 BRN	SP	CRE		V	00:00.0
2021 PO4825888614	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4826788608	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO5248498609	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5182600058	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO5189400084	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO5197099685	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4810688672	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4811288655	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5209199281	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4815888519	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4815188532	LGE	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9246924093	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4704289895	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8312119934	ODP	5	35 BRN	SP	CRE		V	00:00.0
2021 PO7588320039	F	4	40 SWP	SP	P		V	00:00.0
2021 PO4935589786	LGE	3	45 BRN	SP	CCA		V	00:00.0

2021 PO6433411008	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4935189797	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7100119541	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO9020023738	ODP	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8986923537	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9004023581	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO9063624060	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8680222038	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO5515312147	KU	4	40 OTH	UN	CRE		V	00:00.0
2021 PO8712422087	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO6937122826	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5349207950	F	2	75 BRN	SP	CRE		V	00:00.0
2021 PO6891024467	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5348208033	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO6913724185	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6921224093	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6906723751	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4725689820	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4726389810	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4724689785	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4723389787	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4722589802	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4885888597	LGE	4	25 BRN	ST	CRE		V	00:00.0
2021 PO0419438607	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO0404338445A	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021 PO0404338445	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4721689818	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4720789831	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4719989844	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4719189858	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4718289873	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4719989771	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4718689763	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO2525110212	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4718289731	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO5251505912	KU	1	60 BRN	SP	CCA		V	00:00.0
2021 PO8790607732	KU	4	40 OTH	SP	CRE		V	00:00.0
2021 PO4036285349	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4037285343	F	6	25 ACE	SP	P		V	00:00.0
2021 PO4037085349	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4038685339	F	5	25 ACE	SP	CRE		V	00:00.0
2021 PO4039785348	F	5	25 ACE	SP	CRE		V	00:00.0
2021 PO4038685349	F	4	45 ACE	SP	A		V	00:00.0
2021 PO4069685054	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4038785357	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4068685040	LGE	3	50 ACE	SP	P	ED,ID,JP	BD	00:00.0
2021 PO4038985371	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4034785349	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO3341028422	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO3316128535	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3296728789	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO3290828645	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3268328741	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4067485025	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0

2021 PO7821661964	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4034685343	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4033985340	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4035485193	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4034285194	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4032585335	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4033385195	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4030985196	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4032585195	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4029885197	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4028885198	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8798807688	KU	6	30 OTH	SP	CRE	ID,IP	TD	00:00.0
2021 PO8794507675	KU	5	35 OTH	SP	CCA		V	00:00.0
2021 PO8787907672	F	4	45 OTH	SP	A		V	00:00.0
2021 PO8780307733	KU	5	35 OTH	SP	CRE	ID	TD	00:00.0
2021 PO8783007672	KU	5	35 OTH	SP	CRE	ID	TD	00:00.0
2021 PO8775007735	KU	6	30 OTH	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO5920711451	KU	2	40 ACW	SP	A	ED,ID,IP	BD	00:00.0
2021 PO4142785102	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4066085008	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4030485334	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4027885199	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4026785199	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4030685333	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO7803861717	KU	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4064884992	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4065184996	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4067185039	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4066385043	LGE	4	35 ACE	SP	P		V	00:00.0
2021 PO5943911620	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO5954811689	KU	2	45 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5938011780	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO4019985203	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4018985203	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4018185198	LGE	4	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4017685204	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3779266773	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO3801766748	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO3665650993	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PV8567663050	LGE	4	35 ACE	SP	A	ID	TD	00:00.0
2021 PO4028785333	LGE	4	45 ACE	SP	A	ED	TD	00:00.0
2021 PO4020985202	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4024485200	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4025485200	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4023485201	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4022385201	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4022085198	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4021185199	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4025385186	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4024384988	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3685550975	KU	4	40 BRO	SP	CCA		B	00:00.0
2021 PO4157585302	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4140385117	LGE	4	40 ACE	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4157385300	LGE	1	50 ACE	SP	CCA		V	00:00.0



2021 PO4157985327	LGE	3	50 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5371357848	KU	4	40 BRN	SP	CRE	ID	X	RP3	00:00.0
2021 PO5387257742	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5366857718	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5347657717	KU	5	35 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5408658133	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4143085075	LGE	4	30 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4083385201	LGE	3	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4083385190	LGE	3	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4083385188	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4082385199	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4010085015	LGE	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4164485435	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4011784999	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO3463028581	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4083585228	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4082485237	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4081985231	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4081385224	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4034585222	F	4	40 BRO	SP	CRE		VX	RP3	00:00.0
2021 PO4033585223	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4016085314	LGE	5	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4021284915	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4022884903	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4025584877	F	3	45 ACE	SP	CRE		V		00:00.0
2021 PO4024184891	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4032585223	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4031085224	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4030185225	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PV4029185226	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4028085226	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4027585227	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4026985227	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4026585224	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4025585228	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4024585229	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4180585428	LGE	4	40 ACE	SP	CCA	ID,SRS	TD		00:00.0
2021 PO4014585322	LGE	2	35E ACE	SP	CRE		V		00:00.0
2021 PO4013185322	LGE	2	30E ACE	SP	CRE		V		00:00.0
2021 PO4012785323	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8788608200	KU	6	30 OTH	SP	CRE	ID,IP,SRS	TD		00:00.0
2021 PO8777508189	F	3	55 OTH	SP	CCA		V		00:00.0
2021 PO8782408154	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO4011685324	LGE	2	35 ACE	SP	CRE		V		00:00.0
2021 PO8783408026	F	2	60 OTH	ST	CCA		V		00:00.0
2021 PO8776907229	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO8792307274	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO3378928625	KU	4	40 BRN	SP	CCA		B		00:00.0
2021 PO3378228822	KU	4	40 BRN	SP	CRE		B		00:00.0
2021 PO3367728685	KU	6	30 BRN	SP	CCA		B		00:00.0
2021 PO3474128705	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4141485098	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4031585276	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4022585225	F	6	25 BRO	SP	CRE		V		00:00.0

2021 PO4022585230	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO8771908016	F	3	40 OTH	SP	CCA		V	00:00.0
2021 PO8751807927	F	5	35 OTH	SP	CRE		V	00:00.0
2021 PO8751607993	F	4	40 OTH	SP	A		V	00:00.0
2021 PO4179585428	LGE	3	55 ACE	WC	CRE	ED,HH,ID	TD	00:00.0
2021 PO4018185233	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4019085233	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5432658437	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5427858407	KU	3	45 BRN	SP	CCA		BD	00:00.0
2021 PO5419558204	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5427958216	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5441759293	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4027084866	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4027984853	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4028684852	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4030684838	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4032184828	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4011585315	LGE	4	30 ACE	SP	P	ED	TD	00:00.0
2021 PO8787508774	KU	3	50 OTH	SP	A	ID,SRS	TD	00:00.0
2021 PO4012585315	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4009385318	LGE	4	35 ACE	SP	A	ED	TD	00:00.0
2021 PO4009085318	LGE	5	30 ACE	SP	P	ED	TD	00:00.0
2021 PO4010185221	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4020185221	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4021085231	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4022785255	LGE	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4022385256	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO8788908547	KU	3	50 OTH	SP	A	ID,SRS	TD	00:00.0
2021 PO8790408554	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO4105585116	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4033584817	LGE	2	45 ACE	SP	CCA		V	00:00.0
2021 PO4034784809	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4039984829	LGE	7	25 ACE	SP	CRE		V	00:00.0
2021 PO4035784803	F	7	25 ACE	SP	CRE		V	00:00.0
2021 PO4008785382	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO3381428509	KU	4	40 ACW	SP	CRE	ID	TD	00:00.0
2021 PO3392928688	KU	4	40 BRN	SP	CCA	MD	BD	00:00.0
2021 PO4018785262	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4017885263	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4016485264	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4016785258	LGE	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4019785262	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4020485258	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4021285260	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4022785259	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4023285259	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8791908414	KU	4	45 OTH	SP	CRE	ID,IP	TD	00:00.0
2021 PO8788908414	KU	3	45 OTH	SP	A	ID	TD	00:00.0
2021 PO4010985331	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021 PO5449959256	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5453059034	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5440558968	KU	5	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5446158851	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5447258794	KU	3	45 BRN	SP	CCA		V	00:00.0

2021	PO5464459344	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021	PO5467259414	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5467259414a	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO4024285258	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4025785257	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4027285256	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4028385255	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4008485332	LGE	2	75 ACE	SP	CRE		V	00:00.0
2021	PO4029385255	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4030285254	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO8793308294	KU	5	35 OTH	SP	CRE	ID	BD	00:00.0
2021	PO4009585325	LGE	2	35E ACE	SP	CRE		V	00:00.0
2021	PO4031285254	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4032785252	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4033885252	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4034885251	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4035685251	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4035885279	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4034885280	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4033985280	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4032885281	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO8796008194	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021	PO4017185320	LGE	2	75 ACE	SP	CRE		V	00:00.0
2021	PO4015785321	LGE	2	75 ACE	SP	CRE		V	00:00.0
2021	PO4031985281	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4030985283	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO8567663050A1	KU	4	35 ACE	SP	CRE	ED,ID,RB	TD	00:00.0
2021	PO4029985283	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4141985104	LGE	4	40 ACE	SP	CRE	ED,HH,ID	TD	00:00.0
2021	PO4142285088	LGE	4	30 ACE	SP	P	ED,HH,ID	TD	00:00.0
2021	PO4018285319	LGE	4	40 ACE	SP	CCA	ED,ID	BX PX	00:00.0
2021	PO4028485284	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4026985285	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4025985286	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4019985318	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4019185319	LGE	2	75 ACE	SP	CRE		V	00:00.0
2021	PO4036484796	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4024985286	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4045284775	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4041584758	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4142185092	LGE	3	45 ACE	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4141685090	LGE	4	40 ACE	SP	CRE	ED,EP,ID,RB	VX PX	00:00.0
2021	PO4135785141	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4021285317	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021	PO4039984770	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4038084815	F	3	50 ACE	SP	P		V	00:00.0
2021	PO4037984785	F	3	50 ACE	SP	P		V	00:00.0
2021	PO4022085317	LGE	2	35E ACE	SP	CRE		BD	00:00.0
2021	PO4039384814	F	3	50 ACE	SP	P		V	00:00.0
2021	PO4039884826	F	4	45 ACE	SP	CRE		V	00:00.0
2021	PO4041184827	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4020585318	LGE	2	75 ACE	ST	CCA		V	00:00.0
2021	PO4076385054	LGE	5	30 ACE	SP	P		V	00:00.0
2021	PO5316357445	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0

2021 PO4049785194	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4047685198	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4047385203	F	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4046485192	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4045785191	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4045385186	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4044885177	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4044685166	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4044785159	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4043185173	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4042385173	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4042185166	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4041985194	LGE	4	35 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4042185208	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4047585257	LGE	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO3316252886	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO5311557548	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5308357733	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7610963930	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4127686186	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4129686260	LGE	4	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4129786258	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4130086168	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4131186254	LGE	5	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4131286165	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4133486159	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4134486157	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4135386154	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4136386152	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4137286149	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4138286147	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4139286144	LGE	5	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4139586229	LGE	4	35 BRN	SP	P	ID,IP	TD	00:00.0
2021 PO4143886307	LGE	2	55 BRN	SP	P	ID	TD	00:00.0
2021 PO4144786373	LGE	3	50 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4144886388	LGE	2	55 BRN	SP	P	ID	TD	00:00.0
2021 PO4147286365	LGE	3	45 BRN	SP	P	ID,IP,SRC	TD	00:00.0
2021 PO4148286361	LGE	3	45 BRN	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4148486307	LGE	4	35 BRN	SP	P	ID	TD	00:00.0
2021 PO4192986193	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4193686142-A	KU	5	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4193686199	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4193786155	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4193786210	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4194086193	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4198986198	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4199086207	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4199086217	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4199086228	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4199086242	LGE	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4200186238	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4200486237	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4200986208	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4200986222	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0

2021 PO4201186237	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4201386244	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4202286237	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PV4195486202	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PV4195486217	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PV9083472013	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4127686454	LGE	3	45E BRN	SP	P	ID	BD	00:00.0	
2021 PO4127786454	LGE	3	45 BRN	SP	P	ID	BD	00:00.0	
2021 PO4128686450	LGE	4	35 BRN	SP	P	ID,IP	BD	00:00.0	
2021 PO4128786438	LGE	4	35 BRN	SP	P	ID	BD	00:00.0	
2021 PO4129286454	LGE	3	45 BRN	SP	P	ID,IP	BD	00:00.0	
2021 PO4129886474	LGE	4	35 BRN	SP	P	ID,IP	BD	00:00.0	
2021 PO4130386408	LGE	3	45 BRN	SP	P	ID,IP	BD	00:00.0	
2021 PO4130686491	LGE	4	35 BRN	SP	P	EP,ID,IP	BD	00:00.0	
2021 PO4131186468	LGE	4	35 BRN	SP	P	ID	BD	00:00.0	
2021 PO4131886482	LGE	4	35 BRN	SP	P	ID	BD	00:00.0	
2021 PO4143786295	LGE	2	55 BRN	SP	CRE	ID,IP	BD	00:00.0	
2021 PO4144586341	LGE	3	50 BRN	SP	CCA	ID	BD	00:00.0	
2021 PO4144686356	LGE	3	50 BRN	SP	P	ID	BD	00:00.0	
2021 PO4144786393	LGE	3	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4145586304	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO4149486314	LGE	4	35 BRN	SP	P	ID	BD	00:00.0	
2021 PO4151086329	LGE	4	35 BRN	SP	P	ID,IP	BD	00:00.0	
2021 PO2533633862A1	KU	4	40 BRN	SP	P	ED,EP,ID,RB	X	PX	00:00.0
2021 PO3001002408	KU	5	35 UNK	SP	CRE	ED,HH,ID	X	RP1	00:00.0
2021 PO3045702309	KU	4	45 UNK	SP	CRE	ED,HH,ID	X	RP2	00:00.0
2021 PO1831442631	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO1905742320	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO1917941929	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO2394833382	KU	3	50 BRN	SP	CCA		V		00:00.0
2021 PO2401833439	KU	4	45 BRN	SP	CRE		V		00:00.0
2021 PO2404833208	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO2414033539	KU	3	50 BRN	SP	CCA		V		00:00.0
2021 PO2430733750	F	3	40 BRN	SP	A		V		00:00.0
2021 PO2433133696	KU	4	45 BRN	SP	CRE		V		00:00.0
2021 PO2445333796	KU	5	35 BRN	SP	CRE		V		00:00.0
2021 PO2461833997	F	5	35 BRN	SP	CRE		V		00:00.0
2021 PO2484934184	F	4	40 BRN	SP	CRE	ID	V		00:00.0
2021 PO2502534659	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO2517834387	F	2	35 BRN	SP	CRE		V		00:00.0
2021 PO2523434199	F	6	30 BRN	SP	CRE		V		00:00.0
2021 PO2527633462	F	6	30 BRN	SP	CRE		V		00:00.0
2021 PO2568733771	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3021402421-A	KU	5	35 UNK	SP	CCA		V		00:00.0
2021 PO3024302690	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO3056105053	KU	4	40 UNK	SP	CRE		V		00:00.0
2021 PO3056602949	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO3056602949-A	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO3061402911	KU	6	30 UNK	SP	CCA		V		00:00.0
2021 PO3074304634	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO3081303229	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO3090604613	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO3121803461	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO3133803585	KU	3	50 UNK	SP	CCA		V		00:00.0

2021 PO3183203019	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO3208602606	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO7742976883	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7873078564	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7874077894	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO7878178736	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7920678402	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7946078469	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7952278812	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO7964279061	KU	4	45 BRO	SP	S		V	00:00.0
2021 PO7964578537	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8009578834	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1850943097	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO1904641634	KU	3	50 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2397533620	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2408633719	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2456333885	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2465033952	KU	4	45 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO2475434031	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2488234140	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2497035326	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2502534256	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2506535009	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2509334310	KU	5	35 BRN	SP	CRE	ED,ID,IP,MD	TD	00:00.0
2021 PO2509934483	KU	4	40 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO2518934189	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2528834020	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2533633862	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2568733771A1	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2586933245	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2987302907	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO3002702734	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO3019102657	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO3021402421	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3070704454	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO3147203436	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO3180302992	KU	4	45 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO3234802811	KU	5	35 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO3294202424	KU	6	30 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO3296602357	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO7718476877	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7730376863	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7767977083	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7798078585	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7835278129	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7890978028	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7897978393	KU	4	40 BRO	SP	A	ED	TD	00:00.0
2021 PO7967778835	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8009578834A	KU	3	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2446734141	KU	6	30 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2516334682	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2516334682A1	KU	3	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2533633862A2	KU	7	20 BRN	SP	CRE	HH,ID	BD	00:00.0
2021 PO2568733771A2	KU	7	30 BRN	SP	P	ED,ID	BD	00:00.0

2021 PO2586933245A1	KU	7	20 BRN	SP	CRE	ED,HH,ID	BD		00:00.0
2021 PO3072304466	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO3133803585-A	KU	4	40 UNK	SP	CRE	ID,IP	BD		00:00.0
2021 PO3216902670	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO3281003175	KU	3	50 UNK	SP	CRE	ID	BD		00:00.0
2021 PO7877977475	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7931478538	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO3368007518	KU	6	30 BRN	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021 PO3205007821	KU	4	40 BRN	SP	S		V		00:00.0
2021 PO3217507760	KU	3	45 BRN	SP	CRE		V		00:00.0
2021 PO3227107753	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3228107849	KU	3	45 BRN	SP	S		V		00:00.0
2021 PO3229408090	KU	3	45 BRN	SP	CRE		V		00:00.0
2021 PO3285707751	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3298107425	KU	3	45 BRN	SP	CRE		V		00:00.0
2021 PO3298907230	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO3302407566	KU	3	45 BRN	SP	CRE		V		00:00.0
2021 PO3305207711	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO3305207711A	KU	3	40 BRN	SP	S		V		00:00.0
2021 PO3318908003	KU	4	40 BRN	SP	S		V		00:00.0
2021 PO3327407761	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3344307757	KU	4	40 BRN	SP	S		V		00:00.0
2021 PO3361307746	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO3381507731	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3382808609	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3387907792	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3442207685	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4831901831	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4838401583	F	4	45 KOP	SP	CCA		V		00:00.0
2021 PO4838901961	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4847801549	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4855001868	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4855101481	F	4	45 XXX	SP	CCA		V		00:00.0
2021 PO4864801448	F	4	45 XXX	SP	CCA		V		00:00.0
2021 PO4869901792	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4870801389	F	4	45 XXX	SP	CCA		V		00:00.0
2021 PO4877701955	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4897402163	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4902702286	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4903202066	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4907502394	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4913902040	KU	6	30 XXX	SP	CCA		V		00:00.0
2021 PO4941902049	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4942702389	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO4968502341	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO8701415928	KU	6	35 ACW	SP	CRE		V		00:00.0
2021 PO9247814514	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO9437115483	KU	3	40 ACW	SP	S		V		00:00.0
2021 PO9437415862	KU	3	45 ACW	SP	S		V		00:00.0
2021 PO9437515731	KU	3	40 ACW	SP	S		V		00:00.0
2021 PO9437515984	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO9437715600	KU	3	45 ACW	SP	S		V		00:00.0
2021 PO3323107883	KU	4	40 BRN	SP	S	ED,ID,RB	TX	RR	00:00.0
2021 PO4929402416	KU	6	30 XXX	SP	CRE	ED,ID	TX	RR	00:00.0

2021	PO3288607865	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3348907828	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0	
2021	PO3351907641	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3352707945	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0	
2021	PO3356108080	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0	
2021	PO3357607560	KU	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3363008333	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3406407703	KU	3	45 BRN	SP	CCA	ED,ID	TD	00:00.0	
2021	PO3429307661	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3446707633	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3447307679	KU	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3457107615	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3483507569	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3519207506	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3520207451	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO3531407486	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4852002804	KU	2	50 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4864001668	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4869202503	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4882901741	KU	4	45 XXX	SP	P	ED,ID	TD	00:00.0	
2021	PO4889601651	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4895202308	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4900301737	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4910501895	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4917702631	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4931701918	KU	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4978202240	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4981402380	KU	5	30 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO8712815769	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO8718115521	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO8728315623	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO8764415785	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO8791115667	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO9248714785	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9249215042	KU	4	45 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9251515385	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9254115439A	KU	2	25 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9265915331	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9272215166	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9277415005	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9343515300	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9362614828	KU	5	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO3289108007	KU	4	40 BRN	SP	CRE	ED,ID,RB	BX	RP1	00:00.0
2021	PO4891602697	KU	3	45 XXX	SP	CRE	ID,RB	BX	RP1	00:00.0
2021	PO3314807917	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021	PO4876402736	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4893901822	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4899401918	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4912602259	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4937102186	KU	4	50 XXX	SP	CRE	ID	BD		00:00.0
2021	PO9235215041	KU	6	30 ACW	SP	CRE	ED,ID	BD		00:00.0
2021	PO9446415243	KU	4	40 ACW	SP	CRE	ED,ID	BD		00:00.0
2021	PO4198586221	F	4	35 BRO	SP	CRE		V		00:00.0
2021	PO9110774178	LGE	5	35 BRO	SP	CCA		V		00:00.0



2021 PO4195786246	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO4192986238	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO9465058612	ODP	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7959977850	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO3808784988	KU	4	40 INP	SP	CRE	ID	BD		00:00.0
2021 PO7783778612	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7773778626	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7773978787	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8539252030	ODP	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4439388029	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4439688017	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4439788008	LGE	4	40 BRO	SP	P	ED,EP,ID	BD		00:00.0
2021 PO4007584041	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8005576494	KU	6	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4004284058	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7929176138	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7935576018	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO3993683571	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO3994583575	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO7998276573	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4002083619	LGE	2	45 BRO	SP	A	ID	BD		00:00.0
2021 PO7950676801	KU	4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO9441655194	ODP	5	35 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7979176876	KU	3	50 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO5257327150	KU	6	30 UNK	SP	CRE	ID,RB	BX	PX	00:00.0
2021 PO8547768277	F	4	40 KOP	SP	CRE	ED,ID	BX	RP2	00:00.0
2021 PO1310164175	KU	4	45 BRN	SP	CCA	ED,MD,SRS	T		00:00.0
2021 PO4899426298	KU	4	40 UNK	SP	CRE		T		00:00.0
2021 PO4907625708	KU	4	40 UNK	SP	CRE		T		00:00.0
2021 PO4895126589	KU	4	40 UNK	SP	CRE		T		00:00.0
2021 PO9439255336	ODP	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9476654813	ODP	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9449054625	ODP	5	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9435354511	ODP	5	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4380788656	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4356388004	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4317587478	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4258787081	KU	4	40 INP	SP	CRE	ID	TD		00:00.0
2021 PO4344486775	KU	4	40 INP	SP	CRE	ID	TD		00:00.0
2021 PO4294891268	KU	4	40 INP	SP	CRE	ID	TD		00:00.0
2021 PO7960276400	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO7969976421	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO7995276701	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO7950375644	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7925676271	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4005783738-A	KU	5	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO7980376444	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4005783738	LGE	2	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7990176466	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO1292464093	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4439088040	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4440187981	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4439987991	LGE	4	40 BRO	SP	P	EP,ID	TD		00:00.0
2021 PO7962977185	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0

2021 PO1274064110	KU	4	45 BRN	SP	CRE	ED,HH,SRS	TD	00:00.0
2021 PO8552751849	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1257564181	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1242764181	KU	4	40 BRN	SP	CRE	ED,IP	TD	00:00.0
2021 PO8510652403	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3689284634	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO7930776778	KU	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4008284104	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4015083713	LGE	1	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO9481458499	ODP	6	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3706084681	KU	4	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO3739084770	KU	3	50 INP	SP	CRE	ID	TD	00:00.0
2021 PO8542651895	ODP	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9460258488	ODP	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4004184042	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4007984119	LGE	UNK	45 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO8504053516	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4006483751	LGE	2	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4007483772	LGE	2	60 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4063391624	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO4224391332	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO1247863913	KU	5	35 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1370664835A	KU	4	40 UNK	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO8510853806	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7931077639	KU	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO1282264248	KU	6	30 BRN	SP	A	ED,IP,SRS	TD	00:00.0
2021 PO4009783817-A	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4009084118	LGE	UNK	65 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4006783759	LGE	2	60 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3703285588	KU	4	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO3696785920	KU	4	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO7954976812	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3710985249	KU	4	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO4006884120	LGE	UNK	65 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4440287971	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4440487957	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO8342253547	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8380853076	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8365253119	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8366653046	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9414156218	ODP	5	35 BRO	DF	CRE	ED,ID	TD	00:00.0
2021 PO9430355807	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8313852786	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8321052951	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4010083822	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4007384108	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7959477025	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7930977314	KU	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7935477519	KU	2	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8460652206	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8429552541	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8523153893	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3764284850	KU	4	35 INP	SP	CRE	ID	TD	00:00.0
2021 PO3715185053	KU	4	45 INP	SP	CRE	ID	TD	00:00.0

2021	PO4437388037	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO8412653146	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO1425664854	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021	PO1370664835	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021	PO9388957330	ODP	4	40 BRO	SP	CRE	ED,IP	TD	00:00.0	
2021	PO9392356558	ODP	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO9365257003	ODP	5	35 BRO	SP	CRE	ED,IP	TD	00:00.0	
2021	PO7930376865	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7930376962	KU	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO8512452706	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO4435988136	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0	
2021	PO4437188046	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4436288116	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4436988066	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4436588090	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0	
2021	PO4436188125	LGE	3	45 BRO	SP	P	ED,ID	TD	00:00.0	
2021	PO7930177068	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4009783816	LGE	2	50 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO9451857079	ODP	4	40 BRO	SP	S		V	00:00.0	
2021	PO9431456891	ODP	4	40 BRO	SP	S		V	00:00.0	
2021	PO9453556949	ODP	5	35 BRO	SP	S		V	00:00.0	
2021	PO9423656903	ODP	4	45 BRO	SP	S		V	00:00.0	
2021	PO9426156690	ODP	4	45 BRO	SP	S		V	00:00.0	
2021	PO7959277375	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021	PO7957277258	KU	6	30 ACE	SP	CCA		V	00:00.0	
2021	PO4439788030	F	4	35 BRO	SP	P		V	00:00.0	
2021	PO4440687976	F	4	35 BRO	SP	P		V	00:00.0	
2021	PO4440487986	F	4	35 BRO	SP	P		V	00:00.0	
2021	PO4439888021	F	4	35 BRO	SP	P		V	00:00.0	
2021	PO4006084120	F	3	50 ACE	SP	CCA		V	00:00.0	
2021	PO7242952679	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO8000176487	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO3991483528	F	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO4011384003	F	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO4011983989	F	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO4014783952	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021	PO3989983528	F	3	45 BRO	SP	A		V	00:00.0	
2021	PO3990283505	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO8002676389	F	5	35 ACE	SP	P		V	00:00.0	
2021	PO4001784059	LGE	4	30 ACE	SP	A	ED	V	00:00.0	
2021	PO4004384068	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO5323426233	KU	2	55 UNK	ST	CRE		V	00:00.0	
2021	PO4016583966	F	4	35 ACE	SP	CRE	ED	V	00:00.0	
2021	PO4017083974	F	4	40 ACE	SP	CRE	ED	V	00:00.0	
2021	PO4504788195	F	4	35 BRN	SP	CRE		V	00:00.0	
2021	PO4015183972	F	4	40 ACE	SP	CRE	ED	V	00:00.0	
2021	PO3992683537	F	3	45 BRO	SP	A		V	00:00.0	
2021	PO4018483998	F	4	40 ACE	SP	CRE	ED	V	00:00.0	
2021	PO4017783985	F	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO4016584029	F	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO7938175572	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021	PO3993883553	F	3	45 BRO	SP	CRE		V	00:00.0	
2021	PO4017684019	F	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO4019084018	F	4	40 ACE	SP	CCA		V	00:00.0	

2021 PO4019284014	F	4	35 ACE	SP	CRE	ED	V	00:00.0
2021 PO7941975897	F	4	45 ACE	SP	P		V	00:00.0
2021 PO7956475626	F	4	40 ACE	SP	P		V	00:00.0
2021 PO7949075758	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO7962875505	F	4	40 ACE	SP	P		V	00:00.0
2021 PO7970575359	F	4	40 ACE	SP	P		V	00:00.0
2021 PO7975575260	F	4	45 ACE	SP	P		V	00:00.0
2021 PO7978975299	F	4	40 ACE	SP	P		V	00:00.0
2021 PO3994683564	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4019984026	F	4	35 ACE	SP	CRE	ED	V	00:00.0
2021 PO4021784070	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO3995283571	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO3990583528	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4020584039	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4020884046	F	UNK	45 ACE	SP	CRE	ED	V	00:00.0
2021 PO4274986940	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5120425805	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5119325774	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5108025787	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5210726229	KU	5	35 UNK	UN	CCA		V	00:00.0
2021 PO5211426193	KU	6	30 UNK	UN	CRE		V	00:00.0
2021 PO5204726204	KU	6	30 UNK	UN	CRE		V	00:00.0
2021 PO5216526074	KU	4	40 UNK	ST	CCA		V	00:00.0
2021 PO5348326275	KU	2	55 UNK	ST	CCA		V	00:00.0
2021 PO4004484087	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4004584092	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4007884084	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO9461154714	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO9448155383	F	4	40 BRO	SP	P		V	00:00.0
2021 PO7948676843	F	6	30 ACE	SP	P		V	00:00.0
2021 PO4000983625	LGE	1	70 BRO	SP	CRE		V	00:00.0
2021 PO9003867055	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021 PO9021166944	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO8961065756	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO8903965387	F	2	45 KOP	SP	CRE		V	00:00.0
2021 PO9086068134	ODP	4	45 KOP	SP	CCA		V	00:00.0
2021 PO7989076970	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7993976962	F	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7991076886	F	4	40 ACE	SP	P	ED,HH,ID	V	00:00.0
2021 PO9034867275	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO8926265481	F	4	45 KOP	SP	CRE		V	00:00.0
2021 PO8911564994	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO8874565271	ODP	2	50 KOP	SP	CCA		V	00:00.0
2021 PO8801465486	ODP	4	45 KOP	SP	CCA		V	00:00.0
2021 PO9030467142	F	5	40 KOP	SP	CRE		V	00:00.0
2021 PO9065167732	F	4	35 KOP	SP	CRE		V	00:00.0
2021 PO9009866492	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO9026267261	F	5	35 SWP	SP	P		V	00:00.0
2021 PO8978366055	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO7962876881	F	5	35 ACE	SP	P		V	00:00.0
2021 PO4438288038	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4439088044	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4006883751	LGE	4	40 BRO	ST	CCA		V	00:00.0
2021 PO7930377164	KU	2	50 ACE	SP	CCA		V	00:00.0

2021 PO9388856884	ODP	4	45 BRO	SP	S		V	00:00.0
2021 PO8986466632	F	2	45 KOP	SP	P		V	00:00.0
2021 PO8362252684	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8352753719	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8335953380	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8339553464	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8335553686	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO4440487957-A	F	4	35 BRO	SP	P		V	00:00.0
2021 PO4078884406	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4080984424	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4440587967	F	4	35 BRO	SP	P		V	00:00.0
2021 PO4001383632	LGE	1	105 BRO	SP	CRE		V	00:00.0
2021 PO4434288114	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4434488114	F	4	30 BRO	SP	P		V	00:00.0
2021 PO4435788116	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4436788080	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4436788075	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4436488101	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8552668197	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO8645165501	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO8536068484	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8660265407	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO8737965453	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO8657965401	ODP	3	50 BRN	SP	CCA		V	00:00.0
2021 PO8584868272	ODP	4	45 KOP	SP	CCA		V	00:00.0
2021 PO8533068615	F	4	45 BRN	SP	CRE		V	00:00.0
2021 PO8650365359	ODP	2	50 BRN	SP	CRE		V	00:00.0
2021 PO8485652581	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8460652468	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4007684066	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8543368728	F	4	45 BRN	SP	CRE		V	00:00.0
2021 PO8524168481	F	4	45 BRN	SP	CRE		V	00:00.0
2021 PO8717565492	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8687965444	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8564267995	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO8549868830	F	4	45 BRN	SP	CRE		V	00:00.0
2021 PO0209684829	KU	4	40 KOP	SP	CRE	ID,IP	TD	00:00.0
2021 PO0192385435	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021 PO0224485431	KU	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO0238984850	KU	4	40 BRN	SP	A	ED,ID,SRS	TD	00:00.0
2021 PO0200585095	KU	5	35 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO0216885125	KU	4	45 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO1568396859	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4047786065	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO1306298119	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO1993641702	F	3	45 OTH	SP	CCA		V	00:00.0
2021 PO2192343233	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO2011541570	F	3	45 OTH	SP	CCA		V	00:00.0
2021 PO2124643131	F	3	45 OTH	SP	CCA		V	00:00.0
2021 PO2112842653	F	3	45 OTH	SP	CCA		V	00:00.0
2021 PO2106542321	F	3	55 OTH	SP	CCA		V	00:00.0
2021 PO2195243428	F	3	45 OTH	SP	CCA		V	00:00.0
2021 PO1963941809	F	5	35 OTH	SP	CCA		V	00:00.0
2021 PO2080142048	F	4	45 OTH	SP	CCA		V	00:00.0

2021 PO2118742888	F		4	40 OTH	SP	CCA		V	00:00.0
2021 PO2104443353	KU		3	45 BRN	SP	CCA		V	00:00.0
2021 PO2032941580	F		5	35 OTH	SP	CRE		V	00:00.0
2021 PO2066341719	F		3	35 OTH	SP	CCA		V	00:00.0
2021 PO2061041756	F		4	45 OTH	SP	CCA		V	00:00.0
2021 PO2091642211	F		4	45 OTH	SP	CCA		V	00:00.0
2021 PO2142343361	F		3	45 OTH	SP	CCA		V	00:00.0
2021 PO2041045441	F		4	45 INP	SP	CRE		V	00:00.0
2021 PO2025045344	KU		4	40 OTH	SP	CCA		V	00:00.0
2021 PO2047945315	F		3	50 OTH	SP	CCA		V	00:00.0
2021 PO2043345270	F		4	30 OTH	SP	CCA		V	00:00.0
2021 PO2063945134	F		4	40 OTH	SP	CCA		V	00:00.0
2021 PO2080344962	F		4	40 OTH	SP	CRE		V	00:00.0
2021 PO2096544791	F		4	40 OTH	SP	CCA		V	00:00.0
2021 PO2091144754	F		4	30 OTH	SP	CCA		V	00:00.0
2021 PO2115344610	F		3	45 OTH	SP	CCA		V	00:00.0
2021 PO2128944466	F		4	45 OTH	SP	CCA		V	00:00.0
2021 PO2140244340	F		3	45 OTH	SP	CCA		V	00:00.0
2021 PO2155744142	F		3	45 OTH	SP	CCA		V	00:00.0
2021 PO2156543989	F		4	40 OTH	SP	CCA		V	00:00.0
2021 PO2160043856	F		4	40 OTH	SP	CCA		V	00:00.0
2021 PO2168743703	F		4	45 OTH	SP	CCA		V	00:00.0
2021 PO2176843567	F		3	40 OTH	SP	CCA		V	00:00.0
2021 PO2171143535	F		3	35 OTH	SP	CCA		V	00:00.0
2021 PO3990984443	F		3	45 ACE	SP	CCA		V	00:00.0
2021 PV3990884422	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO3990584397	F		4	40 ACE	SP	A		V	00:00.0
2021 PO3992384381	F		4	35 ACE	SP	CCA		V	00:00.0
2021 PO4031584352	LGE	UNK		25 ACE	ST	CCA		V	00:00.0
2021 PO4001584615	F		3	45 BRN	SP	CCA		V	00:00.0
2021 PO7188657769	LGE		4	35 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4031184338	LGE		3	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO3990484427	F		4	35 ACE	SP	CRE		V	00:00.0
2021 PO3989284383	LGE		4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4032384335	LGE		4	35 ACE	SP	P	ED	TD	00:00.0
2021 PO4016084591	F		4	35 BRN	SP	A		V	00:00.0
2021 PO4016384580	F		4	40 BRN	SP	A		V	00:00.0
2021 PO4016184565	F		4	40 BRN	SP	A		V	00:00.0
2021 PO3939482562A	KU		5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3939482562	KU		4	40 BRO	SP	S		V	00:00.0
2021 PO4030784322	LGE		3	45 ACE	SP	A	ED	BD	00:00.0
2021 PO4015884550	F		4	40 BRN	SP	P		V	00:00.0
2021 PO4015584535	F		4	40 BRN	SP	CRE		V	00:00.0
2021 PO4015084504	F		4	40 BRN	SP	CRE		V	00:00.0
2021 PO4015384520	F		4	40 BRN	SP	CRE		V	00:00.0
2021 PO4012684597	LGE		4	35 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4013684603	F		3	45 BRN	SP	A		V	00:00.0
2021 PO4013184579	F		4	40 BRN	SP	CRE		V	00:00.0
2021 PO4012784557	F		4	40 BRN	SP	CRE		V	00:00.0
2021 PO4012984568	F		4	40 BRN	SP	CRE		V	00:00.0
2021 PO4011984512	F		4	40 BRN	SP	CRE		V	00:00.0
2021 PO4012384534	F		4	40 BRN	SP	CRE		V	00:00.0
2021 PO4011684535	F		4	30 BRN	SP	CRE		V	00:00.0
2021 PO9986685421	KU		4	40 BRN	SP	CRE	ED,ID	BD	00:00.0

2021 PO3807982176	KU	4	40 BRO	SP	S		V	00:00.0	
2021 PO3807982176B	KU	4	40 BRO	SP	S		V	00:00.0	
2021 PO3807982176A	KU	5	35 BRO	SP	A	ED,ID,JP,MD	TD	00:00.0	
2021 PO4048486063	LGE	4	30 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4047586061	F	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4047386056	LGE	4	30 BRN	SP	CCA		V	00:00.0	
2021 PO3978783803	F	6	25 BRO	SP	CRE		V	00:00.0	
2021 PO3978283808	F	3	45 BRO	SP	CRE		V	00:00.0	
2021 PO4128884478	LGE	3	45 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4129684471	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO3977583781	F	5	25 BRO	SP	CRE		V	00:00.0	
2021 PO7816870849	KU	1	75 ACE	SP	CRE		V	00:00.0	
2021 PO3977183799	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO7823470672	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO3975683798	F	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3973983790	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO3973983798	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3974083804	F	4	30 BRO	SP	CRE		V	00:00.0	
2021 PO7839670273	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO7838970294	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO7849170036	KU	1	75 ACE	SP	CRE		V	00:00.0	
2021 PO3972783799	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3970983787	LGE	5	25 BRO	SP	CRE		V	00:00.0	
2021 PO3972683790	LGE	4	30 BRO	SP	CRE		V	00:00.0	
2021 PO1503595281	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0	
2021 PO3971083799	LGE	4	30 BRO	SP	CRE		V	00:00.0	
2021 PO3971283801	F	5	25 BRO	SP	CRE		V	00:00.0	
2021 PO3971783804	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4130684460	LGE	3	45 BRO	SP	P	ED,ID	T	00:00.0	
2021 PO4130884450	LGE	4	30 BRO	SP	P	ED,ID,RB,SRC	TX	RR	00:00.0
2021 PO4131384454	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4131784442	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4132284444	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4133184435-A	KU	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO4135184453	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0	
2021 PV3970983815	F	5	25 BRO	SP	CRE		V	00:00.0	
2021 PV3971783815	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO7853769922	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO3975183864	F	3	45 BRO	SP	A		V	00:00.0	
2021 PO3973584554	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO3974383864	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3974283860	F	4	30 BRO	SP	CRE		V	00:00.0	
2021 PO7855469890	KU	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO7858469808	KU	1	70 ACE	SP	CRE		V	00:00.0	
2021 PO3973583864	F	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3976783830	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3973484527	LGE	4	40 ACE	SP	P	ED,ID,JP	BD	00:00.0	
2021 PO4133184435	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4133484432	LGE	1	50 BRO	SP	CCA		V	00:00.0	
2021 PO4133884427	LGE	1	50 BRO	SP	CCA		V	00:00.0	
2021 PO4134884417	LGE	3	50 BRO	SP	P	ED,ID	BD	00:00.0	
2021 PO8515556099	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4135784433	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4136284445	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0	

2021 PO3978483829	F	3	45 BRO	SP	A		V		00:00.0
2021 PO7701770647	KU	4	40 ACE	SP	CRE	ED,ID,IP,MD	TD		00:00.0
2021 PO7681370647	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7671070645	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO7660270646	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO3736782312	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3977184609	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7854073728	KU	5	35 ACE	ST	CCA		V		00:00.0
2021 PO4032184306	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4031584311	LGE	4	35 ACE	SP	A	ED	BD		00:00.0
2021 PO4030584307	LGE	1	45 ACE	SP	CCA		V		00:00.0
2021 PO7845773846	KU	5	35 ACE	ST	CCA		V		00:00.0
2021 PO7834874004	KU	6	30 ACE	ST	CCA		V		00:00.0
2021 PO9997784678	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO9996284561	KU	6	30 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO3977084593	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO3976984579	LGE	4	45 ACE	SP	CCA		V		00:00.0
2021 PO4008284495	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4009484496	F	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4009484495	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4010784479	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4015284493	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4016084493	F	7	25 BRN	SP	CRE		V		00:00.0
2021 PO9284498676	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9252298692	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO9491498018	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021 PO9495997897	KU	5	35 XXX	SP	CCA		V		00:00.0
2021 PO9495297914	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9500997661	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO9497797595	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9460398020	KU	4	40 XXX	SP	CRE	ID,RB	TX	RR	00:00.0
2021 PO4014384493	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7301456790	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4013084494	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4011584495	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4013184460	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4014684459	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4011784460	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4029984287	LGE	3	45 ACE	SP	A	ED	BD		00:00.0
2021 PO4029584269	LGE	3	45 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4008184465	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4009684461	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4010484461	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO7873473996	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4010284444	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4013084424	F	7	25 BRN	SP	A		V		00:00.0
2021 PO4012584424	F	4	40 BRN	SP	A		V		00:00.0
2021 PO9425898035	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9432697996	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9314598549	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9462598534	KU	6	30 XXX	SP	CCA		V		00:00.0
2021 PO9472098527	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9481798199	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9491398174	KU	4	40 XXX	SP	CRE	HH,ID	X	PX	00:00.0



2021	PO9493698372	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO0003184789	KU	6	30 BRN	SP	CCA		T	00:00.0
2021	PO9999684807	KU	6	30 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO0008684797	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO3976884565	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO3740281959	KU	4	40 BRO	SP	S		V	00:00.0
2021	PO3622681774	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO3634081793	KU	4	40 BRO	SP	S		V	00:00.0
2021	PO4030284300	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021	PO4027984176	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021	PO4032084248	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7745272647	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7747472586	KU	1	75 ACE	SP	CRE		V	00:00.0
2021	PO1590396277	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4031984251	F	4	30 BRN	SP	CRE		V	00:00.0
2021	PO4031084252	LGE	4	40 BRN	SP	CCA	ED,HH,ID	TD	00:00.0
2021	PO7760772263	KU	1	75 ACE	SP	CRE		V	00:00.0
2021	PO0101784359	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO0083084759	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO0015985022	KU	6	30 BRN	UN	CRE		V	00:00.0
2021	PO0111184696	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO4031884368	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4033984345	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4032184369	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4028484162	LGE	6	25 ACE	SP	CRE	ED,IP	BD	00:00.0
2021	PO7757172356	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO7773272461	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO3976184475	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO3975684475	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4085984191	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4086384200	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4085484202	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4104784308	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4104084311	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4102884300	LGE	5	25 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4102984306	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO3985783882	LGE	4	30 BRO	SP	CRE	ED,ID,RB	X RP1	00:00.0
2021	PO4030284157	LGE	4	30 ACE	SP	CRE	ED,ID,MD,RB	VX PX	00:00.0
2021	PO7787572558	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO7805472523	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021	PO7822272491	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO7846872446	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7804771150	KU	H1	85 ACE	SP	CRE		V	00:00.0
2021	PO7765972132	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO7500355319	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021	PO4033784362	LGE	3	35 BRN	SP	CRE	ED,HH,ID	BD	00:00.0
2021	PO4033884362	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4034684358	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4035084356	LGE	3	45 BRN	SP	CRE	ED,ID	BX RR	00:00.0
2021	PO4034484336	LGE	3	45 BRN	SP	A	ID	TD	00:00.0
2021	PO3986183961	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3986683950	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3986283939	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3975784463	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0

2021 PO3975184459	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO1407294939	KU	6	30 UNK	SP	CRE	ED,ID	X	PX	00:00.0
2021 PO4034284433	LGE	3	45 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4033684419	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PV4033284407	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO4105684287	LGE	4	35 BRO	UN	CRE		V		00:00.0
2021 PO4133084466	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4081984271	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4082584262	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4083384248	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4085684211	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD		00:00.0
2021 PV4032184378	LGE	3	45 ACE	SP	CRE	ED	BD		00:00.0
2021 PV4032284378	LGE	4	30 ACE	SP	A	ED	BD		00:00.0
2021 PO4098984443	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4100384445	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4102684448	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9994189395	KU	5	45 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9827487178	KU	4	40 BRN	SP	CRE	ED,SRS	TD		00:00.0
2021 PO4098184402	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4097084447	LGE	4	30 BRO	SP	CRE		V		00:00.0
2021 PO4095384474	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4097884420	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4097484442	LGE	4	40 BRO	SP	CRE		B		00:00.0
2021 PO4096084443	LGE	3	45 BRO	SP	CRE		B		00:00.0
2021 PO4105285715	LGE	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4106785714	LGE	2	65 BRN	SP	CRE		V		00:00.0
2021 PO4107385710	LGE	4	30 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4106885710	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4108485714	LGE	2	65 BRN	SP	CRE		V		00:00.0
2021 PO4109385713	LGE	2	70 BRN	SP	CRE		V		00:00.0
2021 PO4112285712	LGE	2	55 BRN	SP	CRE		V		00:00.0
2021 PO4113085712	LGE	3	55 BRN	SP	CRE		V		00:00.0
2021 PO4106185959	LGE	4	40 BRN	SP	A		V		00:00.0
2021 PO3979084483	LGE	UNK	45 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4095284439	LGE	4	35 BRO	SP	P		V		00:00.0
2021 PO4094084438	LGE	4	35 BRO	SP	P		V		00:00.0
2021 PO4092884443	LGE	4	35 BRO	SP	P		B		00:00.0
2021 PO4092684458	LGE	4	35 BRO	SP	P		B		00:00.0
2021 PO4093884473	LGE	4	35 BRO	SP	P		B		00:00.0
2021 PO4094484481	LGE	4	40 BRO	SP	P		B		00:00.0
2021 PO4032184163	LGE	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4104985976	LGE	4	45 BRN	SP	A		V		00:00.0
2021 PO4105485969	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4099485979	LGE	4	40 BRN	SP	A	ED,HH,ID	TX	RR	00:00.0
2021 PO4096685977	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4034184728	LGE	4	45 ACE	SP	P	ED	TD		00:00.0
2021 PO4021583947	LGE	1	100 BRO	ST	P		V		00:00.0
2021 PO7422651264	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4097385935	F	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4098585975	F	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4097585968	F	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4097485952	F	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4124584537	LGE	3	45 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4124184545	LGE	4	35 BRO	SP	P		B		00:00.0

2021 PO8423957447	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4126084552	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4125384558	LGE	4	40 BRO	SP	P		B		00:00.0
2021 PO4099585608	LGE	1	65 BRN	SP	CCA		V		00:00.0
2021 PO4098685589	LGE	1	60 BRN	SP	CRE		V		00:00.0
2021 PO4100285621	LGE	1	70 BRN	SP	A		V		00:00.0
2021 PO3978984458	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4101485643	LGE	2	70 BRN	SP	CRE		V		00:00.0
2021 PO3979384458	LGE	4	30 ACE	SP	CRE	ED,ID,IP	VX	RP3	00:00.0
2021 PO4102185654	LGE	2	75 BRN	SP	A		V		00:00.0
2021 PO4030584172	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO9400897867	KU	6	30 XXX	SP	CRE	ED,HH,ID	X	RP2	00:00.0
2021 PO9358898110	KU	6	30 XXX	SP	CRE	ID	X	RP2	00:00.0
2021 PO9369398085	KU	4	40 XXX	SP	CRE	HH,RB	X	RP2	00:00.0
2021 PO9388898042	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9398598027	KU	4	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9394797874	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4038284726	LGE	4	45E ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4038284731	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4092090592	KU	4	40 BRO	SP	S		V		00:00.0
2021 PO4177690450	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4120290725	KU	4	40 BRO	SP	S		V		00:00.0
2021 PO4147490395	F	4	40 BRO	SP	S		V		00:00.0
2021 PO4115390331	KU	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4123491012	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4103690462	KU	4	40 BRO	SP	S		V		00:00.0
2021 PO4005483690	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4039084723	LGE	4	45E ACE	SP	CRE	ED,ID,MD	BD		00:00.0
2021 PO4019983919	LGE	1	95 BRO	SP	A		V		00:00.0
2021 PO4021083940	LGE	2	50 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4020483929	LGE	3	45 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4019383909	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4050384724	F	3	50 ACE	SP	P		V		00:00.0
2021 PO4124884561	LGE	4	40 BRO	SP	CRE		B		00:00.0
2021 PO9846088586	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO0005589122	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO0053088204	F	3	40 BRN	SP	A		V		00:00.0
2021 PO9845088402	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO0048388145	KU	5	35 BRN	SP	CRE	ED,ID,IP,SRS	TD		00:00.0
2021 PO9975987251	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO0035788729	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO0029887902	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO0032988486	KU	4	40 BRN	SP	CRE	ED,SRS	TD		00:00.0
2021 PO0028688878	KU	6	30 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO0017188852	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO0010887665	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO0021888716	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4094185982	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	RR	00:00.0
2021 PO4093885982	LGE	4	40 BRN	SP	CCA	ED,HH,ID	TX	RR	00:00.0
2021 PO4094085979	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4089785902	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4090685902	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4088685902	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4089085916	LGE	4	35 BRN	SP	CCA		V		00:00.0

2021 PO4090285917	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4089485929	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4090685924	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4092585998	LGE	4	40 BRN	SP	P	ID	TD	00:00.0
2021 PO4091585978	LGE	4	35 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4169689978	KU	5	35 BRO	SP	S	ED	T	00:00.0
2021 PO4172790297	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO4170290148	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO4129090556	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4036984731	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4036984731	LGE	3	40 ACE	SP	CCA		V	00:00.0
2021 PO4003283659	LGE	2	50 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4037384723	F	3	40 ACE	SP	CCA		V	00:00.0
2021 PO4003783665	LGE	1	90 BRO	SP	A		V	00:00.0
2021 PO4037384727	LGE	4	40E ACE	SP	CRE	ED	BD	00:00.0
2021 PO4004283673	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4092385983	LGE	4	40 BRN	DF	CRE	ED,HH,ID,MD	X RP2	00:00.0
2021 PO4091285985	LGE	3	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4090985985	LGE	4	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4088485964	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4092285980	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4090985981	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4087385983	LGE	4	45 BRN	SP	A		V	00:00.0
2021 PO4089485982	F	4	45 BRN	SP	CRE		V	00:00.0
2021 PO4089285982	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4085786004	LGE	4	35 BRN	SP	P	ID	TD	00:00.0
2021 PO4074686104	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4075886104	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4075485988	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4074085989	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4072585978	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4072785990	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4071485991	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4069385992	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4068585993	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4067185994	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4065885995	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4064485996	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4018183888	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7568358960	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4051784723	F	4	45 ACE	SP	A		V	00:00.0
2021 PO4042484723	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4042984722	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4018983885	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4043284723	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4043584730	F	4	45 ACE	SP	P		V	00:00.0
2021 PO4044684756	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3974483880	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3975583882	F	3	45 BRO	SP	A		V	00:00.0
2021 PO3972483898	F	3	45 BRO	SP	A		V	00:00.0
2021 PO3973383903	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3974583904	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4167786404	LGE	4	40 BRO	UN	CCA		V	00:00.0
2021 PO3975583898	F	4	40 BRO	SP	A		V	00:00.0

2021	PO3975983909	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO3976383921	F	4	40 BRO	SP	A		V		00:00.0
2021	PO3976783933	F	3	45 BRO	SP	CRE		V		00:00.0
2021	PO3977583931	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO3986583420	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO3985683418	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO3985083409	LGE	1	105 BRO	CON	P		V		00:00.0
2021	PO4033784314	LGE	4	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO7526554850	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021	PO7524354732	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021	PO7509554771	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021	PO7512054888	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021	PO7774771906	KU	1	75 ACE	SP	CRE		V		00:00.0
2021	PO7784071674	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO3977183814	LGE	4	30 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4126984497	F	3	45 BRO	SP	P		V		00:00.0
2021	PO4128084486	LGE	3	45 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO7789871537	KU	1	80 ACE	SP	CRE		V		00:00.0
2021	PO7797271331	KU	3	45 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO7810571003	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO3973784581	LGE	4	40 ACE	SP	P	ED,ID,RB	X	RP2	00:00.0
2021	PO3973684568	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO1422794916	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO1499095028	KU	3	45 UNK	SP	CRE	ID	BD		00:00.0
2021	PO4055586020	LGE	2	60 BRN	SP	CRE	ED,HH,ID	BD		00:00.0
2021	PO4057286013	LGE	1	60 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4058486007	LGE	1	55 BRN	SP	CRE	ED,HH,ID	TD		00:00.0
2021	PO4054186028	LGE	2	65 BRN	SP	CRE	ED,HH,ID	BD		00:00.0
2021	PO4053186033	LGE	2	60 BRN	SP	CRE	ED,HH,ID,IP	TX	RR	00:00.0
2021	PO4052086035	F	4	40 UNK	SP	A		V		00:00.0
2021	PO4052486042	F	2	55 BRN	SP	CCA		V		00:00.0
2021	PO4050486046	LGE	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4050486051	LGE	4	30 BRN	SP	A		V		00:00.0
2021	PO4048986053	F	3	45 BRN	SP	CCA		V		00:00.0
2021	PO3973584541	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO3972683864	F	3	45 BRO	SP	A		V		00:00.0
2021	PO3972183857	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO7867369579	KU	1	70 ACE	SP	CRE		V		00:00.0
2021	PO7863069692	KU	3	40 ACE	SP	CCA		V		00:00.0
2021	PO7873369324	KU	1	75 ACE	SP	CRE		V		00:00.0
2021	PO3972083841	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO3971083829	F	5	25 BRO	SP	CRE		V		00:00.0
2021	PV3971983830	F	3	45 BRO	SP	A		V		00:00.0
2021	PO1519395173	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO1530195382	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO1600295661	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021	PO3973483840	LGE	5	25 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO7747070604	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7722370552	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO3973483832	F	3	45 BRO	SP	CCA		V		00:00.0
2021	PO3975083831	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO2055441622	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO2164643368	F	4	40 OTH	SP	CCA		V		00:00.0
2021	PO2183243373	F	3	45 OTH	SP	CCA		V		00:00.0

2021 PO1950741704	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO7822172612	KU	5	35 ACE	ST	CCA		V	00:00.0
2021 PO3984783885	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO0008484949	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO1268398734	KU	4	40 BRO	SP	CCA		T	00:00.0
2021 PO4035484235	LGE	4	40 BRN	SP	A	ID	TD	00:00.0
2021 PO3976584523	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO0026784891	KU	3	40 BRN	SP	A	ED,SRS	TD	00:00.0
2021 PO4028784234	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4027984208	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4028584225	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4028284217	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4027584195	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4034184240a1	KU	4	35 BRN	SP	A	ID	TD	00:00.0
2021 PO4034184240	LGE	4	40 BRN	SP	A	ID	BD	00:00.0
2021 PO3984683907	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3984083895	F	3	45 BRO	SP	A		V	00:00.0
2021 PO3983483884	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0143984740	KU	4	40 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO0176385086	KU	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO3353580475E	KU	3	40 BRO	SP	S		V	00:00.0
2021 PO3353580475D	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO3353580475C	KU	3	40 BRO	SP	S		V	00:00.0
2021 PO3353580475B	KU	3	40 BRO	SP	S		V	00:00.0
2021 PO3226480347	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO3242280210	KU	5	35 XXX	SP	CRE		V	00:00.0
2021 PO3241880436	F	4	40 XXX	SP	S		V	00:00.0
2021 PO3260280280	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO3257780527	F	4	40 XXX	SP	P	MD	V	00:00.0
2021 PO3288680610	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3353580475A	KU	3	40 BRO	SP	S		V	00:00.0
2021 PO3318980757	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO3353580475	F	4	40 COX	SP	P		V	00:00.0
2021 PO3323580532	F	4	40 COX	SP	P		V	00:00.0
2021 PO3462880803A	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO3451881601	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO3490481194	KU	5	35 BRN	SP	S		V	00:00.0
2021 PO3336080975	KU	6	30 BRN	DF	CRE	ED,ID	BD	00:00.0
2021 PO3353680898	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3378680903	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO1545796761	KU	3	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3982783872	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3981783864	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO3981983858	F	3	45 BRO	SP	A		V	00:00.0
2021 PV3981183844	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3980083830	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3979483822	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3973884595	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4034584342	LGE	3	45 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO4034184323	LGE	4	40 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO6855016470	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO4164386332	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4164886341	LGE	5	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO8111763551	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0

2021 PO1083553666	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0728248409	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3696707010	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7766960392	KU	5	35 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO7762760234	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0721348517	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0715548624	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO6937015518	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO0888553967	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0854653945	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0821153964	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0818653884	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4501508945	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4528008832	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4548909261	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4556309514	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO0849148172	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4527410022	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4116285916	LGE	3	50 BRN	SP	P	ID,SRS	TD	00:00.0
2021 PO6900916571	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6867316376	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO4116785926	LGE	3	45E BRN	SP	P	ID,SRS	TD	00:00.0
2021 PO4167786404	LGE	4	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO3737909056	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO3737909056a								
KU	3	45 BRN	SP	CCA	ED	TD		00:00.0
2021 PO4129786171	LGE	3	55 BRN	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO4129286162	LGE	3	55 BRN	SP	CRE	ID,SRS	TD	00:00.0
2021 PO0729048559	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4540209745	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7800959997	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO8433264994	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4555409727	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4569309755	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO3743007626	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8448865309	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8499166322	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8468665668	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4185486186	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8130256576-A	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO8347564735	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3789908695	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4124385987	LGE	4	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8310764601	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4512309701	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3844707588	KU	7	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3824408000	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8412064930	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6919215811	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6909515800	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO4163786322	LGE	5	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4505809575	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4128886153	LGE	3	45E BRN	SP	CRE	ID,SRS	TD	00:00.0
2021 PO4174286347	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0

2021 PO7773360166	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO7777760136	KU	4	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO4130286103	LGE	6	25 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4130486107	LGE	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4155186306	KU	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO8796465482	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4156786274	LGE	2	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4154986307	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4060606649	KU	3	45 BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO6917715079	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO6952915251	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO6970815413	KU	4	45 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO4120685999	LGE	4	40 BRN	SP	P	IP,RB	BX	RP2	00:00.0
2021 PO4579009649	F	4	40 XXX	SP	CRE	HH,ID	BX	RP1	00:00.0
2021 PO4516109927	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO9013165657	F	3	55 BRN	SP	CRE	HH,RB	BX	RP2	00:00.0
2021 PO8720965923	KU	4	45 BRO	SP	CRE	ED,ID	BX	RP2	00:00.0
2021 PO8724366219	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0644048248	KU	4	40 BRN	SP	CRE		BD		00:00.0
2021 PO3886406215	KU	7	35 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO0797052234	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0822152632	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0789552693	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0811153574	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0795453806	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO1402847538	KU	4	45 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4120385966	LGE	6	25 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4120385992	LGE	4	40 BRN	SP	P	ID	BD		00:00.0
2021 PO4119885949	LGE	4	35 BRN	SP	P	ID	BD		00:00.0
2021 PO1293245184	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO1070353886	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO6823817822	KU	5	35 ACW	SP	CRE	ED,ID	BD		00:00.0
2021 PO1077653915	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO8215464839	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0906254038	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0957654121	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4130386182	LGE	3	55 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4119985957	LGE	4	35 BRN	SP	P	ID	BD		00:00.0
2021 PO4119185971	LGE	4	40 BRN	SP	P	ID	BD		00:00.0
2021 PO4118285955	LGE	3	45 BRN	SP	P	ID,IP	BD		00:00.0
2021 PV4118685961	LGE	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4171086433	LGE	4	30 BRO	SP	CRE	ID	BD		00:00.0
2021 PO4117285934	LGE	3	45 BRN	SP	P	ID	BD		00:00.0
2021 PO4117385937	LGE	3	45E BRN	SP	P	ID,IP	BD		00:00.0
2021 PO0784853368	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0871448034	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4534210057	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4128386145	LGE	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4127986137	LGE	3	55 BRN	SP	CRE	ID,IP,SRC	BD		00:00.0
2021 PO4128086094	LGE	6	30 BRN	SP	CRE	ID,IP,SRS	BD		00:00.0
2021 PO4126286104	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4184886170	LGE	4	35 BRO	SP	CCA	ID	BD		00:00.0
2021 PO4124586042	LGE	4	35 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4122186025	LGE	2	55 BRN	SP	CRE	ED,ID	BD		00:00.0



2021 PO8142057148	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO4121286008	LGE	3	50 BRN	SP	P	ID	BD	00:00.0	
2021 PO8135956852	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO8506965292	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 8796465482A	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO6985115545	KU	4	45 ACW	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4123786027	LGE	4	35E BRN	SP	P		B	00:00.0	
2021 PO3740907329	KU	3	45 BRN	SP	CCA		B	00:00.0	
2021 PO1063253754A	KU	6	35 BRO	SP	CRE		B	00:00.0	
2021 PO4131186196	LGE	2	55 BRN	SP	CRE	ED,HH,ID	X	RP2	00:00.0
2021 PO7031621303	KU	5	35 ACW	DF	CRE	ED,HH,ID,MD,RB	X	RP1	00:00.0
2021 PO4138686347	KU	4	40 BRN	SP	CRE	RB	X	RP2	00:00.0
2021 PO4138486347	LGE	2	55 BRN	SP	CCA	HH,RB	X	RP2	00:00.0
2021 PO4137686328	LGE	4	55 BRN	SP	CRE		V		00:00.0
2021 PO7002220713A	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO2353832585	KU	6	30 BRO	SP	CRE		V		00:00.0
2021 PO8056959785	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO8056959785A	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1126952746	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO1137952960	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO1118552799	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4174086514	F	2	50 BRO	SP	A		V		00:00.0
2021 PO8270361575	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8172761682	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8212461734	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8241461655	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4138086336	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO4137186316	LGE	3	55 BRN	SP	CRE		V		00:00.0
2021 PO4136886306	LGE	3	65 BRN	SP	CCA		V		00:00.0
2021 PO4136386294	LGE	2	60 BRN	SP	CCA		V		00:00.0
2021 PO4136086287	LGE	3	55E BRN	SP	CCA		V		00:00.0
2021 PO4174486552	F	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4176186555	F	4	35 BRO	SP	CCA		V		00:00.0
2021 PO8876477282	LGE	5	25 BRO	SP	CRE		V		00:00.0
2021 PO4174586525	LGE	3	35 BRO	ST	CCA		V		00:00.0
2021 PO4176886554	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021 PO4172786516	LGE	5	30 BRO	SP	CRE		V		00:00.0
2021 PO4171686535	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4170286303	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4169285428	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4168685429	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO7485915627	F	4	40 ACW	SP	P		V		00:00.0
2021 PO1614344654	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO1719543302	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4170283697	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO2451731721A1	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO2451731721	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO8264558383	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO4138786356	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO4138986364	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4140186345	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4140286311	LGE	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4173186526	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO8857177215	LGE	4	40 BRO	SP	CCA		V		00:00.0

2021 PO8244558336	KU	5	35 UNK	SP	CCA	V	00:00.0
2021 PO8237958431	F	4	40 UNK	SP	A	V	00:00.0
2021 PO8064459885	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8074859935	F	6	30 BRO	SP	CRE	V	00:00.0
2021 PO8074360101	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4468304781	F	4	45 BRO	SP	CCA	V	00:00.0
2021 PO4466005192	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4468804734	F	3	40 BRO	SP	CRE	V	00:00.0
2021 PO4465305260	F	2	45 BRO	SP	CCA	V	00:00.0
2021 PO4480404724	F	4	40 BRO	SP	P	V	00:00.0
2021 PO4467005021	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4480504539	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8184058900	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO8178358670	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2266931811	KU	6	35 BRO	SP	CRE	V	00:00.0
2021 PO2269232019	KU	5	35 BRO	SP	CRE	V	00:00.0
2021 PO2302131864	KU	5	35 BRO	SP	CRE	V	00:00.0
2021 PO2297932052	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO7940362438	KU	3	45 BRO	SP	CRE	V	00:00.0
2021 PO7941462415	KU	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8030062779	KU	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8028862812	KU	3	45 BRO	SP	CRE	V	00:00.0
2021 PO8083963056	KU	3	45 BRO	SP	CRE	V	00:00.0
2021 PO8085563025	KU	3	45 BRO	SP	CRE	V	00:00.0
2021 PO4175686645	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4507005633	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO1519045113	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4179405547a	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4200706162	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO8098562684	F	7	30 BRO	SP	CRE	V	00:00.0
2021 PO8118763178	KU	3	50 BRO	SP	CCA	V	00:00.0
2021 PO8115063085	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8110762850	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8105362577	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8099562221	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4189185154	F	4	40E BRN	SP	P	V	00:00.0
2021 PO4189285151	F	3	45 BRN	SP	CRE	V	00:00.0
2021 PO4188785174	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4187985203	LGE	4	40 BRN	SP	P	V	00:00.0
2021 PO4187685229	F	3	55 BRN	SP	CRE	V	00:00.0
2021 PO4187585236	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO2321832655	KU	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4603409662	F	4	40 XXX	SP	P	V	00:00.0
2021 PV9121063636	LGE	4	35 BRN	SP	P	V	00:00.0
2021 PO4583808837	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4590909075	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4186785305	LGE	3	55 BRN	SP	CCA	V	00:00.0
2021 PO4186785316	F	4	40 BRN	SP	P	V	00:00.0
2021 PO8850576935	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO4185185437	LGE	2	60 BRN	SP	CCA	V	00:00.0
2021 PO6933116114	KU	4	40 ACW	SP	CRE	V	00:00.0
2021 PO7008620414	KU	2	55 ACW	SP	S	V	00:00.0
2021 PO4172686489	F	5	35 BRO	SP	CCA	V	00:00.0
2021 PO4171086379	F	4	40 BRO	SP	CRE	V	00:00.0

2021 PO8104162009	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8112661864	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8118961768	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8105861724	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8104761571	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4134086251	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8200158397	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO8122258838	F	6	30 UNK	SP	CRE		V	00:00.0
2021 PO8125658952	F	6	30 UNK	SP	CRE		V	00:00.0
2021 PO8190861577	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8106061127	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8108660933	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8140061231	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8128261114	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4170586369	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4170086360	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4169586351	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4169486345	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8152760998	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8170060945	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4169986339	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4169386330	LGE	4	30 BRO	SP	A		V	00:00.0
2021 PO2455824429	KU	3	50 BRN	SP	CCA		V	00:00.0
2021 PO2468724300	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4170686334	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4171586328	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8181160915	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8206460849	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8103860677	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8097660679	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4172686330	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4173486336	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO2483024216	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2495224233	KU	3	45 BRN	SP	CRE		V	00:00.0
2021 PV4032884396	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO9279698563	KU	5	35 XXX	DF	CRE	ID	TD	00:00.0
2021 PO4031684357	LGE	3	45 ACE	SP	CRE	ED	TD	00:00.0
2021 PO1951341648	F	4	40 OTH	SP	CCA		V	00:00.0
2021 PO1966541668	F	4	40 OTH	SP	CCA		V	00:00.0
2021 PO4011384425	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4011683226	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4017783218	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4012083222	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5364822598	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO5359922619	KU	2	50 UNK	UN	CCA		V	00:00.0
2021 PO5373322560	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO7299843902	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4010783205	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4010683203	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4010483201	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4042185652	F	4	40 KOP	SP	CCA		V	00:00.0
2021 PO4006185939	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4006685934	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4007285937	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0

2021 PO4007985943	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4042385677	F	4	40 KOP	SP	A		V	00:00.0
2021 PO4042485689	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4055186540	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO7678677141	LGE	2	55 ACE	SP	CRE		V	00:00.0
2021 PO4053686548	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4053486544	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4054486544	LGE	4	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4054186540	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5145622792	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO5159023041	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO4049786138	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5182023173	KU	6	30 UNK	SP	CRE		B	00:00.0
2021 PO4051386129	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4052686124	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4925712652	KU	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4916112426	KU	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4902812556	F	4	40 KOP	SP	S		V	00:00.0
2021 PO4908712693	F	4	40 KOP	SP	S		V	00:00.0
2021 PO4914012840	F	4	40 KOP	SP	S		V	00:00.0
2021 PO4920012984	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4053786120	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4054586115	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4055886109	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4054686161	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4056286161	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4054186212	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4055786211	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4055386235	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4055486242	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4055686275	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4055586258	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4058086271	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4057986256	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4057886240	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4057686221	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4057586210	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4057586199	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4052086550	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4051286559	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4050786555	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4050486544	LGE	UNK	35 ACE	SP	CRE		V	00:00.0
2021 PO5162423204	KU	6	35 UNK	SP	CRE		T	00:00.0
2021 PO4007985943a	KU	4	35 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4043285752	F	4	30 KOP	SP	A		V	00:00.0
2021 PO4043285758	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4042885760	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4937913089	KU	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4962713284	KU	2	50 KOP	SP	S		V	00:00.0
2021 PO4938513257	KU	2	50 KOP	SP	S		V	00:00.0
2021 PO4010785971a	KU	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4041285762	F	4	40 KOP	SP	CCA		V	00:00.0
2021 PV4010785971	LGE	3	55 ACE	SP	CRE	ED,EP,ID,IP	TD	00:00.0
2021 PV4011685980	LGE	2	55 ACE	SP	CRE	ED,ID	TD	00:00.0

2021 PO4012185985	LGE	3	55 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4038585760	F	4	30 KOP	SP	P		V		00:00.0
2021 PO5173023143	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO5181523094	KU	6	30 UNK	SP	CRE		B		00:00.0
2021 PO4056286184	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4057486182	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4057386170	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4057386156	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4057386160	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4031185780	LGE	4	35 KOP	SP	P	ED,ID,IP	TD		00:00.0
2021 PO7276071689	LGE	2	55 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4013585998	LGE	2	55 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PV4013385997	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4014586008	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021 PO4147186015	LGE	4	35 BRO	SP	A		V		00:00.0
2021 PO4147086013	LGE	4	40 BRO	SP	A		V		00:00.0
2021 PO4147085999	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4147085989	LGE	3	45 BRO	SP	CRE		V		00:00.0
2021 PO4147085987	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4015386015	LGE	2	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5214722903	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO4146985975	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4146985963	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO5323424053	F	3	50 UNK	SP	CCA		V		00:00.0
2021 PO4031985778	F	3	45 KOP	SP	CCA		V		00:00.0
2021 PO4025386597	LGE	4	30 ACE	SP	CRE		V		00:00.0
2021 PO7388277685	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4024986591	LGE	5	35 ACE	SP	CCA		V		00:00.0
2021 PO4025086590	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4067786098	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4066486098	F	4	40 ACE	SP	A		V		00:00.0
2021 PO4065086100	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4026786596	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO3998383590	LGE	2	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4026086584	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5470122584	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO5448322467	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO7734772777	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4062086127	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4062686128	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4044585980	F	3	45 KOP	SP	CCA		V		00:00.0
2021 PO5415522361	KU	3	45 UNK	SP	CRE	ED,ID	BX	PX	00:00.0
2021 PO5403822258	KU	2	50 UNK	SP	CRE		B		00:00.0
2021 PO5398322209	KU	3	45 UNK	SP	CRE		B		00:00.0
2021 PO5403022206	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO4042285665	F	3	45 KOP	SP	CCA		V		00:00.0
2021 PO5439232412	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5442132230	KU	5	35 UNK	SP	CRE	ED,ID	BX	RP1	00:00.0
2021 PO5431432216	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4055286534	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4053686532	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4015583262	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4015283266	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4042685738	F	3	45 KOP	SP	CCA		V		00:00.0

2021 PO4041686418	F		4	40 ACE	SP	CRE		V		00:00.0
2021 PO4039886420	F	UNK		45 ACE	SP	CRE		V		00:00.0
2021 PO4037986442	F	UNK		45 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4955913093	KU		6	30 KOP	SP	CRE	ED,HH,ID,RB	X	RP2	00:00.0
2021 PO4027385506	LGE		4	30 KOP	SP	A		V		00:00.0
2021 PO4026485516	LGE		4	40 KOP	SP	CCA		V		00:00.0
2021 PO5356224795	KU		4	40 UNK	SP	CRE	ED,ID	BX	PX	00:00.0
2021 PO5342924801	KU		4	40 UNK	SP	CRE		B		00:00.0
2021 PO4104285881	F		4	40 ACE	SP	CRE		V		00:00.0
2021 PO4106985952	F	UNK		45 ACE	SP	CRE		V		00:00.0
2021 PO4106685950	F		4	30 ACE	SP	CRE		V		00:00.0
2021 PO4105885941	F		3	45 ACE	SP	CCA		V		00:00.0
2021 PO4105085931	F		3	45 ACE	SP	CCA		V		00:00.0
2021 PO4103985921	F	UNK		45 ACE	SP	CRE		V		00:00.0
2021 PO4104185909	F		4	40 ACE	SP	CRE		V		00:00.0
2021 PO4105285899	F	UNK		25 ACE	SP	CRE		V		00:00.0
2021 PO4104385900	F		4	35 ACE	SP	CCA		V		00:00.0
2021 PO4104285890	F		4	40 ACE	SP	CCA		V		00:00.0
2021 PO5426733847	KU		4	40 KOP	SP	CCA		V		00:00.0
2021 PO5427333787	KU		4	40 KOP	SP	CCA		V		00:00.0
2021 PO5437733804	KU		5	30 KOP	SP	CCA		T		00:00.0
2021 PO4034785532	LGE		3	50 KOP	SP	A		V		00:00.0
2021 PO4034985527	LGE		5	30 KOP	SP	P		V		00:00.0
2021 PO4036185526	LGE		4	25 KOP	SP	A		V		00:00.0
2021 PO4036185532	LGE		3	50 KOP	SP	A		V		00:00.0
2021 PO4037085526	LGE		4	30 KOP	SP	P		V		00:00.0
2021 PO4037685532	LGE		3	50 KOP	SP	CCA		V		00:00.0
2021 PO4039085532	LGE		4	45 KOP	SP	A		V		00:00.0
2021 PO4038685526	LGE		5	30 KOP	SP	P		V		00:00.0
2021 PO5338624654	KU		4	40 UNK	SP	CRE		B		00:00.0
2021 PO4040085531	LGE	UNK		45 KOP	SP	A		V		00:00.0
2021 PO4039885526	LGE		6	30 KOP	SP	A		V		00:00.0
2021 PO4051886363	LGE		4	35 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4054286371	LGE	UNK		60 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4053186364	LGE	UNK		55 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5337824486	KU		4	40 UNK	SP	CRE		T		00:00.0
2021 PO5336624429	KU		2	40 UNK	SP	CCA		V		00:00.0
2021 PO5340524427	KU		2	45 UNK	SP	CCA		V		00:00.0
2021 PO5336224277	KU		3	45 UNK	SP	CCA		V		00:00.0
2021 PO4982712192	KU		4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO5446833818	KU		4	40 KOP	SP	CCA		T		00:00.0
2021 PO5449333653	KU		5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5334023997	KU		3	45 UNK	SP	CCA		V		00:00.0
2021 PO4069986024	LGE		4	40 ACE	SP	CCA		V		00:00.0
2021 PO4070186036	LGE		4	40 ACE	SP	CCA		V		00:00.0
2021 PO5331923728	KU		4	40 UNK	SP	CRE		T		00:00.0
2021 PO5331523668	KU		4	40 UNK	SP	CCA		V		00:00.0
2021 PO3989583472	LGE		2	90 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO3990083480	LGE		3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4993412479	KU		4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4999312625	KU		4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO3991283495	LGE		3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3992483511	LGE		3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3993683527	LGE		3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0

2021 PO3998983599	LGE	2	105 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3990785733	F	4	30E ACE	SP	A		V	00:00.0
2021 PO5329723444	KU	2	50 UNK	SP	CRE		T	00:00.0
2021 PO5361022756	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO5329323488	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5331223212	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO4072186033	LGE	4	35 ACE	SP	A	ED,ID,RB	X PX	00:00.0
2021 PO4071786006	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4073286001	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4051986353	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3987585688	F	4	35 ACE	SP	P		V	00:00.0
2021 PO3986685675	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4051186347	F	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4051186330	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4009385952	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5397231758	KU	3	45 BRO	SP	CRE	ID	BD	00:00.0
2021 A	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5173423284	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO5171723328	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO4049986563	LGE	5	35 ACE	SP	CRE		V	00:00.0
2021 PO4049686558	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4049086566	LGE	5	30 ACE	SP	CCA		V	00:00.0
2021 PO4048786561	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4047886564	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4950012957	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4945512853	F	4	40 KOP	SP	S		V	00:00.0
2021 PO4928913188	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4950413270	KU	2	50 KOP	SP	S		V	00:00.0
2021 PO4924513089	F	4	40 KOP	SP	S		V	00:00.0
2021 PO4057086144	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4056486132	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4055986120	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4039485780	F	4	35 KOP	SP	CCA		V	00:00.0
2021 PO4039285773	F	4	40 KOP	SP	A		V	00:00.0
2021 PO5410331643	KU	3	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5417231586	KU	4	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5414931605	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4186086035	LGE	1	60 BRO	SP	CRE		V	00:00.0
2021 PO4048086569	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4038085769	LGE	UNK	35 KOP	UN	CCA		V	00:00.0
2021 PO4184386036	LGE	2	55 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4038385785	F	4	30 KOP	SP	P		V	00:00.0
2021 PO4037885776	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4183686036	LGE	2	95 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4036185777	F	4	40 KOP	SP	A		V	00:00.0
2021 PO4180186046	F	4	35 BRO	SP	CRE	ED,HH,ID,RB	VX RP1	00:00.0
2021 PO4180786044	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4161786043	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4182386043	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4182686042	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4182786053	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4183286042	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4031385774	F	4	30 KOP	SP	CCA		V	00:00.0
2021 PO5187623058	KU	4	40 UNK	SP	CRE		B	00:00.0

2021	PO5200822985	KU	4	40 UNK	SP	CRE			B		00:00.0
2021	PO5205622956	KU	4	40 UNK	SP	CRE			B		00:00.0
2021	PO5223522851	KU	6	30 UNK	SP	CCA			V		00:00.0
2021	PO4031285779	LGE	4	30 KOP	UN	CCA			V		00:00.0
2021	PO4071486044	LGE	4	35 ACE	SP	CCA			V		00:00.0
2021	PO4028885543	LGE	4	35 KOP	SP	P	ED,ID,IP		TD		00:00.0
2021	PO4028885533	LGE	4	45 KOP	SP	A			V		00:00.0
2021	PO4030285527	F	4	30 KOP	SP	CCA			V		00:00.0
2021	PO4031085528	LGE	4	35 KOP	SP	CCA			V		00:00.0
2021	PO4030785533	LGE	3	50 KOP	SP	A	ED,ID,IP,MD		TD		00:00.0
2021	PO4110185924	F	3	45 ACE	SP	CCA			V		00:00.0
2021	PO4109185933	F	4	40 ACE	SP	CRE			V		00:00.0
2021	PO4109085930	F	4	40 ACE	SP	CRE			V		00:00.0
2021	PO4032185532	LGE	3	50 KOP	SP	A			V		00:00.0
2021	PO4032285527	LGE	4	30 KOP	SP	P	ED,ID,MD		BD		00:00.0
2021	PO4108085919	F	4	40 ACE	SP	CRE			V		00:00.0
2021	PO4107485911	F	UNK	45 ACE	SP	CRE			V		00:00.0
2021	PO4106185907	F	UNK	25 ACE	SP	CRE			V		00:00.0
2021	PO4106785903	F	4	40 ACE	SP	CRE			V		00:00.0
2021	PO4107485893	F	4	40 ACE	SP	CRE			V		00:00.0
2021	PO4107885894	LGE	2	45 ACE	SP	CCA			V		00:00.0
2021	PO4106285878	LGE	4	40 ACE	SP	CCA			V		00:00.0
2021	PO3997183574	LGE	3	45 BRO	SP	CRE	ED,ID,RB		X	RP1	00:00.0
2021	PO7699660130	KU	4	40 BRO	SP	CRE	ED,ID		BD		00:00.0
2021	PO7827859217	KU	5	35 BRO	SP	CRE			V		00:00.0
2021	PO7693460003	F	4	40 BRO	SP	CRE			V		00:00.0
2021	PO4187986148	LGE	3	45 BRO	SP	A	ED,ID,IP		TD		00:00.0
2021	PO4189086149	LGE	4	35 BRO	SP	A	ED,ID		TD		00:00.0
2021	PV4140686076	LGE	2	90 BRO	ST	P			V		00:00.0
2021	PO4141286085	LGE	1	90 BRO	ST	P			V		00:00.0
2021	PO7602059656	KU	5	35 BRO	SP	CRE	ED,ID		TD		00:00.0
2021	PO7595559514	KU	5	35 BRO	SP	CRE	ED,ID		TD		00:00.0
2021	PO7818759237	KU	6	30 BRO	SP	CRE			V		00:00.0
2021	PO7314239947	KU	4	40 BRN	SP	S			V		00:00.0
2021	PO7272040088	KU	5	35 BRN	SP	CRE	ED,ID		TD		00:00.0
2021	PO7274540037	F	3	40 BRN	SP	CCA			V		00:00.0
2021	PO7179340712	KU	3	40 BRN	SP	CCA			V		00:00.0
2021	PO7150140642	KU	3	40 BRN	SP	CCA			V		00:00.0
2021	PO7094840240	KU	3	40 BRN	SP	CCA			V		00:00.0
2021	PO7106240404	KU	3	40 BRN	SP	CCA			V		00:00.0
2021	PO7128140523	KU	3	40 BRN	SP	CCA			V		00:00.0
2021	PO7225039921	KU	4	40 BRN	SP	CRE			BD		00:00.0
2021	PO7204740108	KU	6	30 BRN	SP	CRE			V		00:00.0
2021	PO7177840788	F	4	40 BRN	SP	S			V		00:00.0
2021	PO7137141829	KU	6	30 BRN	SP	CRE	ED		VX	RP2	00:00.0
2021	PO7108341712	KU	3	45 BRN	SP	S			V		00:00.0
2021	PO7081741556	KU	3	45 BRN	SP	S			V		00:00.0
2021	PO7066841423	KU	5	35 BRN	SP	S			V		00:00.0
2021	PO7121441795	KU	3	45 BRN	SP	CCA			V		00:00.0
2021	PO7017142106	KU	4	40 BRN	SP	S			V		00:00.0
2021	PO4122485303	F	4	40 ACE	SP	P			V		00:00.0
2021	PO4122485309	F	4	40 ACE	SP	CRE			V		00:00.0
2021	PO3994212618	KU	4	40 XXX	SP	CRE	HH,ID,RB		BX	RP2	00:00.0
2021	PO4008812528	KU	4	40 XXX	SP	CRE	ED,ID		TD		00:00.0



2021 PO4008912624	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO6755651708	KU	6	30 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO6740051774	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO6739751933	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5353228409	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5453128544	F	4	40 BRO	SP	A		V	00:00.0
2021 PO5443728358	F	4	45 BRO	SP	A		V	00:00.0
2021 PO5353329076	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5364229079	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5416729309	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5385328732	KU	3	40 BRO	SP	P		V	00:00.0
2021 PO5426927454	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5425327681	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5427027922	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5428728202	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5405528142	F	3	45 BRO	SP	P		V	00:00.0
2021 PO5393628413	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5404728440	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4126885442	F	1	20 ACE	SP	A		V	00:00.0
2021 PO6769851917	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6837452558	F	5	35 UNK	SP	A		V	00:00.0
2021 PO6832852652	KU	6	35 UNK	SP	CRE	ID	TD	00:00.0
2021 PO6842352437	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4131385635	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4132085629	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4132485617	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4132885605	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4133285594	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4133585588	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4133785582	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4128885556	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4128885543	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4128885530	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4128785517	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4128885505	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4129485496	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4130085486	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4130885485	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4131985494	F	4	40 ACE	SP	CRE	ED,ID,IP	V	00:00.0
2021 PO4132585542	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4131985533	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4131885521	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4132185511	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4134285558	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4134685546	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4135185534	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4135185523	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4135585521	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4000312025	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4008611982	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4134885516	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4133985509	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4132985500	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4133685489	F	4	40 ACE	SP	CRE		V	00:00.0

2021 PO4138285494	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4136885491	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4135685488	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4134785477	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4133785469	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4132585461	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4131685453	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4130285443	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4129085434	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4128085426	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4106885442	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO3942611359	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO3979411480	F	4	45 KOP	SP	CCA		V	00:00.0
2021 PO6833952245	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO6824152102	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO7093454689	KU	5	30 UNK	SP	CRE		V	00:00.0
2021 PO4126085477	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4125685467	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4125585455	F	4	40 ACE	DF	CRE		V	00:00.0
2021 PO4125585442	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4125385412	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4125485425	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4124285425	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4122985426	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3991212228	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO6800552015	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4122885413	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4122885400	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4122785388	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4008412229	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3998612324	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4122785376	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4122685364	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4122585351	F	4	40 ACE	SP	P		V	00:00.0
2021 PO7040442707	KU	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4008612378	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO6780752002	F	4	40 UNK	SP	A		V	00:00.0
2021 PO6774951858-A	KU	3	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO6774951858	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO6775151658	KU	4	35 UNK	SP	CCA		V	00:00.0
2021 PO4119385344	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4120085344	F	3	45 ACE	SP	P		V	00:00.0
2021 PO4120885332	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4120885339	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4122585339	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4122585327	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4122485315	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4120485310	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4070185531	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4067885522	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4069085527	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4072785541	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6894944032	KU	6	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6976043627	KU	3	45 BRO	SP	CCA		V	00:00.0

2021	PO6991843729	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO7027343699	KU	4	45 BRO	SP	A		V	00:00.0	
2021	PO7036443325	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO7013214566	KU	3	70 ACW	SP	CRE		V	00:00.0	
2021	PO7020014698	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO7037614668	KU	2	70 ACW	SP	CRE		V	00:00.0	
2021	PO6497313384	KU	1	70 ACW	SP	CRE		V	00:00.0	
2021	PO6523913427	KU	2	60 ACW	SP	CRE		V	00:00.0	
2021	PO6563113497	KU	1	70 ACW	SP	S		V	00:00.0	
2021	PO6586413528	KU	2	70 ACW	SP	CRE		V	00:00.0	
2021	PO6607613550	KU	1	65 ACW	SP	S		V	00:00.0	
2021	PO6644513596	KU	2	70 ACW	SP	CRE		V	00:00.0	
2021	PO6671913636	KU	2	60 ACW	SP	CRE		V	00:00.0	
2021	PO6707513671	KU	2	65 ACW	SP	CRE		V	00:00.0	
2021	PO6742813684	KU	1	65 ACW	DF	CRE	IP	V	00:00.0	
2021	PO6766113742	KU	2	70 ACW	SP	S		V	00:00.0	
2021	PO6801713828	KU	2	70 ACW	SP	CRE		V	00:00.0	
2021	PO6840813910	KU	1	70 ACW	DF	CRE		V	00:00.0	
2021	PO6870713971	KU	1	70 ACW	SP	S		V	00:00.0	
2021	PO6905014062	KU	1	70 ACW	ST	CRE		V	00:00.0	
2021	PO6926814122	KU	1	70 ACW	ST	S		V	00:00.0	
2021	PO6946614282	KU	ST	70 ACW	ST	S		V	00:00.0	
2021	PO4046684433	LGE	2	85 BRO	SP	CRE		V	00:00.0	
2021	PO4054584462	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4053684454	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4052784446	LGE	4	40 BRO	SP	CCA	ED,ID	TD	00:00.0	
2021	PO4051884438	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP	TD	00:00.0	
2021	PO4050884434	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4050984439	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021	PO4049784438	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4047384439	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4048684448	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4046884426	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4046284413	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4045684398	LGE	4	40 BRO	SP	CCA	ED,ID	TD	00:00.0	
2021	PO4045184388	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7026243011	KU	3	45 BRO	SP	CRE		V	00:00.0	
2021	PO7010114462	KU	4	40 ACW	SP	S		V	00:00.0	
2021	PO7030614244	KU	4	40 ACW	SP	S		V	00:00.0	
2021	PO7040113965	KU	3	45 ACW	SP	S		V	00:00.0	
2021	PO7053813702	KU	4	40 ACW	SP	S		V	00:00.0	
2021	PO8878615448	KU	1	65 ACW	SP	CRE		V	00:00.0	
2021	PO8843115426	KU	1	75 ACW	SP	CRE		V	00:00.0	
2021	PO8902415484	KU	1	65 ACW	SP	CRE		V	00:00.0	
2021	PO8923915485	KU	3	55 ACW	SP	CRE		V	00:00.0	
2021	PO8951915468	KU	3	70 ACW	SP	CRE		V	00:00.0	
2021	PO8980915464	KU	1	70 ACW	SP	S		V	00:00.0	
2021	PO9042015458	KU	1	70 ACW	SP	CRE		V	00:00.0	
2021	PO9013215460	KU	2	60 ACW	SP	CRE		V	00:00.0	
2021	PO4071685519	LGE	4	30 BRN	SP	CRE	ED	BD	00:00.0	
2021	PO4049384469	LGE	4	40 BRO	SP	CCA	ED,ID,RB	TX	RR	00:00.0
2021	PO4048884458	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO6762214653	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO6747414605	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	

2021	PO7318715286	KU	3	70 ACW	SP	CRE		V		00:00.0
2021	PO7298115274	KU	3	70 ACW	SP	CRE		V		00:00.0
2021	PO7277015245	KU	3	70 ACW	SP	CRE		V		00:00.0
2021	PO7256615205	KU	3	70 ACW	SP	CRE		V		00:00.0
2021	PO7231515154	KU	2	70 ACW	SP	CRE		V		00:00.0
2021	PO7188315065	KU	2	65 ACW	SP	CRE		V		00:00.0
2021	PO7170115024	KU	2	70 ACW	SP	CRE		V		00:00.0
2021	PO7140614960	KU	2	70 ACW	SP	CRE		V		00:00.0
2021	PO7084014822	KU	1	70 ACW	ST	GAL		V		00:00.0
2021	PO7112414899	KU	2	70 ACW	SP	CRE		V		00:00.0
2021	PO7060214749	KU	2	70 ACW	SP	CRE		V		00:00.0
2021	PO6613845350	KU	5	30 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO6623845398	KU	4	45 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO6650345257	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO6773714360	KU	4	40 ACW	SP	CRE	ED,ID	BX	PX	00:00.0
2021	PO5809139391	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4054484536	LGE	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4053284545	LGE	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4052684544	LGE	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4052184534	LGE	4	40 BRO	SP	CCA	ED,EP,ID,IP		TD	00:00.0
2021	PO5770639829	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO5858738953	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO6942014436	KU	4	40 ACW	SP	CRE	ED,ID		TD	00:00.0
2021	PO4051284512	LGE	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4051784523	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TD	00:00.0
2021	PO5881538801	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO6789913881	KU	4	40 ACW	SP	CRE	ED,ID		TD	00:00.0
2021	PO6783914079	KU	4	40 ACW	SP	CRE	HH,ID,IP		TD	00:00.0
2021	PO6619646004	KU	6	30 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO6610145971	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO6619645887	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO6621545824	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4050784502	LGE	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4050384491	LGE	4	40 BRO	SP	CCA	ED,ID		TD	00:00.0
2021	PO4049784480	LGE	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4070085539	LGE	4	40 BRN	SP	P	ED		BD	00:00.0
2021	PO4070985516	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4052385437	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4060784515	LGE	6	25 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4060084517	LGE	4	40 BRO	SP	CCA	ED,ID,RB	BX	RP3	00:00.0
2021	PO4059284510	LGE	4	40 BRO	SP	CCA	ED,ID		TD	00:00.0
2021	PO4058484504	LGE	4	40 BRO	SP	CCA	ED,ID		TD	00:00.0
2021	PO4058084494	LGE	4	40 BRO	SP	CCA	ED,ID		TD	00:00.0
2021	PO4057184486	LGE	4	40 BRO	SP	CCA	ED,ID		TD	00:00.0
2021	PO4056284478	LGE	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO4055384469	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO6696545032	KU	4	45 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO6698245415	KU	4	45 BRO	SP	S		V		00:00.0
2021	PO6687645365	KU	4	30 BRO	SP	CCA		V		00:00.0
2021	PO6742944808	KU	5	35 BRO	SP	CCA		V		00:00.0
2021	PO6773044686	KU	5	35 BRO	SP	CRE	ED,ID		BD	00:00.0
2021	PO6785044525	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO6809644495	KU	4	40 BRO	SP	CRE	ED,ID		BD	00:00.0
2021	PO4053185446	F	4	40 BRN	SP	CCA		V		00:00.0

2021 PO4053985455	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4054985464	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4055985469	F	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4057085475	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4058185480	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4059185485	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4007484430	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4008484427	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4008984426	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4010184426	F	4	40 BRN	SP	A		V	00:00.0
2021 PO3976784551	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7856074241	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4029284258	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4029984257	LGE	4	40 ACE	SP	A	ED,IP	BD	00:00.0
2021 PO1269698958	KU	4	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO7725173167	KU	H1	85 ACE	SP	CRE		V	00:00.0
2021 PO3976684537	LGE	4	40 ACE	SP	CRE	ED,ID,MD	TD	00:00.0
2021 PO7755573610a	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7755573610	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4028984245	LGE	4	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO3565381941	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3591281709	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3579281448	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO3610780929	KU	4	45 BRO	SP	S		V	00:00.0
2021 PO3565181159	KU	5	35 BRO	SP	CRE	ED,HH,ID,IP	TD	00:00.0
2021 PO3563381168	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO3545480779	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO3517980718	F	4	40 BRO	SP	P		V	00:00.0
2021 PO3494480648	F	4	40 BRO	SP	S		V	00:00.0
2021 PO3462880803	KU	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO7733473473	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4028884188	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7718373334	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7720973312	KU	1	60 ACE	SP	CRE		V	00:00.0
2021 PO7717973383	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7736772882	KU	1	75 ACE	SP	CRE		V	00:00.0
2021 PO1974313853	LGE	3	45 ACE	SP	CCA	ED	V	00:00.0
2021 PO1255999297	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO1231199832	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4032884245	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4033184256	LGE	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4026984178	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4026684170	LGE	4	45 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO3976484509	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3976384492	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO1566796543	KU	3	45 UNK	SP	CRE	ID	X PX	00:00.0
2021 PO3985483934	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO3985783929	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3985283918	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3971484515	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO1583495591	KU	4	40 UNK	SP	CRE	ID	TX RR	00:00.0
2021 PO3973384513	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3972884506	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3973284499	LGE	4	40 ACE	SP	P	ED,ID	VX RP3	00:00.0

2021 PO3972684485	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4002784591	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO7170057922	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4039184608	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4037184712	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4037684712	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO1382397733	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4040784655	F	4	35 BRN	SP	CRE	ED,EP,HH,ID	BX	PX	00:00.0
2021 PO7551744131	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4044184717	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO4043384697	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4043084688	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4045484696	LGE	4	35 ACE	SP	A	ED	BD		00:00.0
2021 PO4073784239	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4072384312	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4073784310	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4042684707	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4042284697	F	4	35 BRN	SP	CRE		V		00:00.0
2021 PO3990384362	F	4	40 ACE	SP	CRE	ED,HH,ID	VX	RP3	00:00.0
2021 PO9535697811	KU	4	40 XXX	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO9562497899	KU	4	40 XXX	SP	CRE	ID	TX	RR	00:00.0
2021 PO3990284347	F	4	40 ACE	SP	CRE	ED,ID	VX	RP3	00:00.0
2021 PO0273901723	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO0281901783	KU	6	30 BRO	SP	S	ED	T		00:00.0
2021 PO4104184285	LGE	UNK	45 BRO	UN	CRE		V		00:00.0
2021 PO4079884296	LGE	4	30 BRO	UN	CRE		V		00:00.0
2021 PO4077084348	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4076784345	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4077584338	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4078684321	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4078384318	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4040184673	LGE	4	45 BRN	SP	CRE	ED,EP,HH,ID	BX	RR	00:00.0
2021 PO4041884685	F	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4041284670	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4041084671	LGE	4	40 BRN	SP	CRE	ED,EP,HH,ID	BX	RR	00:00.0
2021 PO5756726144	KU	6	30 KOP	SP	CCA		V		00:00.0
2021 PO3990184341	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3990084321	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3989584321	LGE	4	30 ACE	SP	CCA	ED	V		00:00.0
2021 PO5806625796	F	6	40 KOP	SP	CRE		V		00:00.0
2021 PO5803025837	KU	4	40 KOP	SP	CCA		V		00:00.0
2021 PO5802925763	F	3	40 MAR	SP	P		V		00:00.0
2021 PO4038183221	F	4	30 BRO	SP	A		V		00:00.0
2021 PO4040384720	F	4	35 BRN	SP	P		V		00:00.0
2021 PO4080184298	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4082184288	LGE	4	30 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO5800525742	KU	6	30 MAR	SP	CCA		V		00:00.0
2021 PO4038484679	LGE	4	35 BRN	SP	CRE	ID	BD		00:00.0
2021 PO3999784425	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4000184429	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO3999884442	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4040283236	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4170384770D	KU	6	30 BRO	SP	S		V		00:00.0
2021 PO4170384770C	KU	6	30 BRO	SP	S		V		00:00.0

2021 PO4170384770	KU	6	30 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4170384770A	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO4190484777	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO4170384770A	KU	4	25 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4170384770	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4194684560	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO4126384256	LGE	4	40 BRO	UN	CCA		V	00:00.0
2021 PO4126484268	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4128984273	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4129384278	F	4	30 BRO	SP	P		V	00:00.0
2021 PO4129884253	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	BX PX	00:00.0
2021 PO4130184263	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4045984659	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO4042083228	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4043883220	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO40414784686	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4041884656	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4041484644	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO7536057181	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4041183247	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4014884698	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4014984710	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4015284722	LGE	4	35 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO1189298372	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4039083267	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4039783263	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4037384532	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO1158798512	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7649376528	KU	H1	85 ACE	ST	CRE		V	00:00.0
2021 PO1138398360	KU	4	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO1091398224	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO1093298318	KU	4	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO7648076781	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7651276168	KU	1	80 ACE	SP	CRE		V	00:00.0
2021 PO7652975817	KU	1	70 ACE	SP	CRE		V	00:00.0
2021 PO7654275465	KU	1	70 ACE	SP	CRE		V	00:00.0
2021 PO4037684537	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4037284527	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021 PO4037284525	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO3988584138	F	1	50 ACE	SP	A		V	00:00.0
2021 PO39888984194	F	4	40 ACE	SP	A		V	00:00.0
2021 PO39888584191	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO3988984182	F	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4019884724	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4103584551	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4098684572	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO1293098734	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4021184688	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4021784687	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4023084684	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4024984686	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4024684674	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4023484628	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4024484663	F	4	40 BRN	SP	CRE		V	00:00.0

2021 PO4037583227	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO1272798605	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4023884651	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4023284649	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4023684641	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4023184615	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4021884652	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4020684654	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4020184675	LGE	4	35 BRN	SP	A		V		00:00.0
2021 PO4019984655	F	4	35 BRN	SP	A		V		00:00.0
2021 PO9434097042	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9428897317	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9384697370	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO9482797561	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9291997067	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO9344297239	KU	3	50 XXX	SP	CCA		V		00:00.0
2021 PO9260496964	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO9224796847	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO9188496445	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4005284374	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO9882787761	KU	4	45 BRN	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO4003884711	F	4	30 BRN	SP	CCA		V		00:00.0
2021 PO9860587893	KU	4	45 BRN	SP	CRE	ED,SRS	BD		00:00.0
2021 PO4003384710	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO9872687663	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4003784720	F	4	30 BRN	SP	A		V		00:00.0
2021 PO4003384722	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PV4003584734	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PV4003984745	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4004084751	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4004984754	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4005284763	F	7	25 BRN	SP	CRE		V		00:00.0
2021 PO4006184746	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4042384619	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4036984478	LGE	3	35 ACE	SP	CCA		V		00:00.0
2021 PO7678074403	KU	1	70 ACE	SP	CRE		V		00:00.0
2021 PO7686274173	KU	4	40 ACE	SP	CRE		V		00:00.0
2021 PO7690374068	KU	1	70 ACE	SP	CRE		V		00:00.0
2021 PO1093098086	KU	4	45 BRO	SP	CCA		V		00:00.0
2021 PO1395998335	KU	5	35 BRO	SP	CRE	ID	BD		00:00.0
2021 PO1456098153	KU	4	45 BRO	SP	CRE	ID	TD		00:00.0
2021 PO3992984188	F	4	30 ACE	SP	A		V		00:00.0
2021 PO3993584191	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO3991784192	F	4	45 ACE	SP	CRE		V		00:00.0
2021 PO7071153649	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO3993684204	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3993784215	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4034984457	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7702073754	KU	1	70 ACE	SP	CRE		V		00:00.0
2021 PO7714273441	KU	H1	85 ACE	SP	CRE		V		00:00.0
2021 PO7903373334	KU	5	35 ACE	ST	CCA		V		00:00.0
2021 PO4117184555	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4118184548	LGE	4	30 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4119084541	LGE	4	35 BRO	SP	P	ED,ID	TD		00:00.0



2021 PO4118684530	LGE	4	35 BRO	UN	CRE		V		00:00.0
2021 PO4117184526	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4115984519	LGE	4	30 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4116184513	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	BX	PX	00:00.0
2021 PO4118284499	LGE	4	40 BRO	SP	CCA	ED,ID	TD		00:00.0
2021 PO3993884231	F	4	40 ACE	SP	A		V		00:00.0
2021 PO3993984243	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4034484442	LGE	3	45 ACE	SP	CRE	ED	TD		00:00.0
2021 PV3994084252	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO7899973168	KU	5	35 ACE	ST	CCA		V		00:00.0
2021 PO7907273522	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7898173648b	KU	6	30E ACE	ST	CCA		V		00:00.0
2021 PO5764825409	KU	4	35 BRN	SP	CRE	ED,HH,ID,RB	X	RP2	00:00.0
2021 PO4081584269	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4081184284	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4037683198	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4025784706	F	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4025284697	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4019384704	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4037283189	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4038183206	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5760025364	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5726726127	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO5769125536	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5758725779	F	4	35 BRN	SP	CRE		V		00:00.0
2021 PO5733426056	F	4	35 BRN	SP	P		V		00:00.0
2021 PO5774825607	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO5755725410	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5749725878	F	4	35 BRN	SP	P		V		00:00.0
2021 PO9186496718	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4074084325	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4035484584	LGE	3	40 ACE	SP	CCA		V		00:00.0
2021 PO4038984692	LGE	4	35 BRN	SP	A	ID	BD		00:00.0
2021 PO4039684704	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4041184703	LGE	4	40 BRN	SP	A	ID	BD		00:00.0
2021 PO4024584707	F	4	30 BRN	SP	CRE		V		00:00.0
2021 PO5799225802	KU	4	40 MAR	SP	CRE	ID	BD		00:00.0
2021 PO5790325723	KU	3	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5795325693	F	3	40 MAR	SP	P		V		00:00.0
2021 PO9530497601	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO3991785436	LGE	7	25 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PV4162685829	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4163485853	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4071220200	KU	3	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4076885371	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4162785848	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4076785361	LGE	4	30 ACE	SP	P	ED,ID,IP	BD		00:00.0
2021 PO3994985423	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PV3994185421	LGE	4	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO3993985429	LGE	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO3993085429	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4081085386	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4081585396	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4137385583	LGE	4	35 ACE	UN	CCA		V		00:00.0

2021 PO4162685861	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4162885866	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4110285283	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4110485296	LGE	4	40 BRO	SP	A	ED,ID	BD	00:00.0	
2021 PO4110185302	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4110085314	LGE	4	40 BRO	SP	CRE	ED,EP,ID,RB	TX	RR	00:00.0
2021 PO4200611784	KU	3	45 BRN	SP	CCA	ED	TD	00:00.0	
2021 PO4074185065	LGE	3	50 BRN	SP	CCA		V	00:00.0	
2021 PO4072685056	LGE	3	40 BRN	SP	CRE	ED,EP,ID	BD	00:00.0	
2021 PO4187811780	KU	2	50 BRN	SP	CCA		V	00:00.0	
2021 PO4205009351	KU	3	45 BRN	SP	CCA	ED	TD	00:00.0	
2021 PO3902987261	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO3884687115	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO3885587255	KU	5	30 BRN	SP	CRE		V	00:00.0	
2021 PO3888687409	F	6	30 BRN	SP	CRE		V	00:00.0	
2021 PO3912287353	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO3921187399	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO3916887448	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021 PO3912887494	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021 PO3924487747	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO3918787938	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO3944688380	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO3925087589	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO3940687452	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO3929387587	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO3963187495	KU	4	45 BRN	SP	CRE		V	00:00.0	
2021 PO3968387531	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO3992287300	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO3983887174	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO3464385307	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4072885061	LGE	4	40 BRN	SP	A	ED,ID	TD	00:00.0	
2021 PO4072085062	LGE	4	40 BRN	SP	A	ED,ID	TD	00:00.0	
2021 PO4071185057	LGE	1	50 BRN	SP	CCA		V	00:00.0	
2021 PO4065085082	LGE	4	30 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO3854536021	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4166985852	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO3858136152	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO3861236283	KU	4	40 BRO	SP	CCA		B	00:00.0	
2021 PO3771811937	KU	2	45 KOP	SP	CRE		B	00:00.0	
2021 PO3754712106	KU	4	40 XXX	SP	CRE		B	00:00.0	
2021 PO3867236516	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO3905122690	KU	4	45 CPT	SP	CRE	ID	TD	00:00.0	
2021 PO6252610080	KU	6	30 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO6251610149	KU	5	30 ACW	DF	CRE	ED,ID	TD	00:00.0	
2021 PO4166885843	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO3754211877	KU	4	45 XXX	SP	CRE		B	00:00.0	
2021 PO4201710125	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4108085673	LGE	3	45 ACE	SP	P	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4107885673	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO3726212010	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO3732811803	KU	4	40 XXX	SP	CRE		B	00:00.0	
2021 PO4109585312	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO3916722442	KU	5	40 UNK	SP	CRE		V	00:00.0	
2021 PO4064585079	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	

2021 PO4064285107	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4062685091	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4166885807	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4166685809	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4166685818	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6237110189	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO6234310028	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO6231109831	KU	4	40 ACW	SP	CRE	ED,ID,IP,MD,RB	X	RP1	00:00.0
2021 PO4166785829	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4193710080	KU	3	45 BRN	SP	CRE		V		00:00.0
2021 PO5034825800	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5162426958	F	5	35 BRN	SP	CCA		V		00:00.0
2021 PO5152526977	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5139327003	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3873611773	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4162010493	KU	3	45 BRN	SP	CRE	ED,ID,IP,RB	X	PX	00:00.0
2021 PO4189810302	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4169010771	KU	4	45 BRN	SP	CRE	ED,ID,MD	TD		00:00.0
2021 PO4062085092	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4087485492	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO8019966692	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4168910548	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4061885098	F	4	40 BRN	SP	P		V		00:00.0
2021 PO3998785382	LGE	4	30 BRN	SP	CCA	ED,ID,IP	BD		00:00.0
2021 PO4086185486	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO5115827011	F	4	40 BRN	SP	P	ED,ID	BX	RP3	00:00.0
2021 PO5027826107	F	3	35 BRN	SP	P	ED,ID	BX	RP3	00:00.0
2021 PO5018726505	F	4	40 BRN	SP	P	ED,ID	BX	RP3	00:00.0
2021 PO5014826673	F	4	40 BRN	SP	P	ED,ID	BX	PX	00:00.0
2021 PO5012126812	F	4	40 BRN	SP	P	ED,ID	BX	PX	00:00.0
2021 PO6156112086	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6158312357	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO5528115301	KU	5	40 BRN	SP	CCA		V		00:00.0
2021 PO5537414755	KU	3	45 BRN	SP	CRE	ED	TD		00:00.0
2021 PO5556614647	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5535714800	KU	3	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO8813170819	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3852738481	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO3845438398	KU	4	45 KOP	SP	CRE	ID	TD		00:00.0
2021 PO4120784801	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4117885325	LGE	4	40 BRO	SP	A	ID	TD		00:00.0
2021 PO4118085313	LGE	4	35 BRO	SP	CCA	ED,ID	TD		00:00.0
2021 PO4118285299	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4117885296	LGE	4	35 BRO	SP	A	ED,ID	BD		00:00.0
2021 PO4116885295	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4115585312	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4115085314	LGE	4	30 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4115085307	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4070685302	LGE	4	40 BRN	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4070385299	LGE	4	35 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4069885299	F	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4118884802	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4116584805	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4953626176	F	4	40 BRN	SP	P		V		00:00.0

2021 PO6131412573	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO6159512491	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO61595112491A	KU	4	50 ACW	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO6182112504	KU	4	45 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4109484744	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4107484756	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4107584759	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4104584779	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO3836610867	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4956425964	F	4	40 BRN	SP	P		V	00:00.0	
2021 PO4115685293	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4114385291	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4113785267	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4113085277	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4113085267	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4113185310	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4112685312	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4112585304	LGE	4	40 BRO	SP	A	ED,EP,ID,IP	TD	00:00.0	
2021 PO4112785289	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4111385287	LGE	4	40 BRO	SP	CCA	ED,ID	TD	00:00.0	
2021 PO4069185296	LGE	4	30 BRN	SP	CCA	ED,ID	TD	00:00.0	
2021 PO4069785297	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4069085283	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4068185274	F	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4066685272	LGE	4	25 BRN	SP	CCA		V	00:00.0	
2021 PO3845138320	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO3845338455	KU	2	50 BRO	SP	CCA		V	00:00.0	
2021 PO4066385270	LGE	1	80 BRN	ST	CCA		V	00:00.0	
2021 PO4066085265	F	4	30 BRN	SP	CRE		V	00:00.0	
2021 PO4067385265	LGE	1	80 BRN	ST	CCA		V	00:00.0	
2021 PO3840411090	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4167285896	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO4167185885	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4068285245	LGE	4	35 BRN	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7842464103	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4068485253	LGE	4	35 BRN	SP	CCA		V	00:00.0	
2021 PO4070585249	LGE	1	90 BRN	ST	CCA		V	00:00.0	
2021 PO3796111124	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4068985256	LGE	1	85 BRN	SP	CRE		V	00:00.0	
2021 PO4068385260	F	4	35 BRN	SP	CRE		V	00:00.0	
2021 PO4072085264	F	3	45 BRN	SP	CRE		V	00:00.0	
2021 PO3756911250	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4960625667	F	4	40 BRN	SP	P		V	00:00.0	
2021 PO4071785261	F	1	45 BRN	SP	CCA		V	00:00.0	
2021 PO4075785172	LGE	1	80 BRN	ST	CCA		V	00:00.0	
2021 PO4167085874	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO3845611348	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4077385159	LGE	3	80 BRN	SP	CRE		V	00:00.0	
2021 PO4079885163	LGE	4	30 BRN	SP	CCA		V	00:00.0	
2021 PO4078685149	LGE	1	85 BRN	ST	CCA		V	00:00.0	
2021 PO4079785139	LGE	1	60 BRN	ST	CCA		V	00:00.0	
2021 PO4074185328	LGE	4	35 BRN	SP	CCA		V	00:00.0	
2021 PO4074685328	LGE	4	35 BRN	SP	CCA		V	00:00.0	
2021 PO4078385083	LGE	4	35 BRN	SP	CCA		V	00:00.0	

2021 PO4077485083	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4164785860	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5490414872	KU	7	30 BRN	SP	CCA		V	00:00.0
2021 PO5527614991	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO3965241633	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4167886005	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4167785997	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4167685986	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO3815110079	KU	4	45 XXX	SP	CRE	ED,HH,ID,RB	BX	RP1 00:00.0
2021 PO3824710317	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4143984822	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4143684794	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4143584785	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO6490013580	KU	5	35 ACW	SP	CRE	ED,ID,MD,SRC	TD	00:00.0
2021 PO6482513872	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6411113329	KU	4	35 ACW	SP	S		V	00:00.0
2021 PO6424813401	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO4071785314	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4143484768	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4143484755	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4943026912	F	4	40 BRN	SP	P	ED,ID	BX	RP3 00:00.0
2021 PO4955726024	F	4	40 BRN	SP	P	ED,ID	BX	RP3 00:00.0
2021 PO4070685325	LGE	4	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4072685307	F	4	30 BRN	SP	A		V	00:00.0
2021 PO4144484884	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4144384870	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4144284856	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4144184848	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8800272148	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5656415143	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5517015256	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3842438892	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO3844938888	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3845138673	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3792837277	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4167986016	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4943426867	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4143184725	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4142984706	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4944626780	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4945726718	F	4	40 BRN	SP	P		V	00:00.0
2021 PO3745168257	KU	4	45 BRN	SP	CRE		V	00:00.0
2021 PO3753168044	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3765767992	KU	4	45 BRN	SP	CRE		V	00:00.0
2021 PO3761867725	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO3758367517	KU	4	45 BRN	SP	CRE		V	00:00.0
2021 PO3756167334	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3752767016	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3750466800	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3748866598	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3746666396	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3744666222	KU	4	45 BRN	SP	CRE		V	00:00.0
2021 PO3743266032	KU	4	45 BRN	SP	CRE		V	00:00.0
2021 PO3740865857	KU	4	45 BRN	SP	CRE		V	00:00.0

2021	PO3738965649	KU	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO3737665460	KU	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO3733068703	KU	3	45 BRN	SP	CCA			V	00:00.0	
2021	PO3782310106	KU	4	40 XXX	SP	CRE		ED,ID	TD	00:00.0	
2021	PO4142884694	LGE	4	30 ACE	SP	P		ED,ID	BD	00:00.0	
2021	PO4142184685	LGE	4	35 ACE	SP	P		ED,ID	TD	00:00.0	
2021	PO4141784675	LGE	4	30 ACE	SP	CRE		ED,ID	TD	00:00.0	
2021	PO4141984665	LGE	4	30 ACE	SP	CRE		ED,ID,IP	TD	00:00.0	
2021	PO5525114981	KU	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO5509815431	KU	3	45 BRN	SP	CRE		ED,ID	TD	00:00.0	
2021	PO3738468501	KU	3	45 BRN	SP	CCA			V	00:00.0	
2021		3773768223	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021		3776768051	KU	2	50 BRN	SP	CCA		V	00:00.0	
2021		3773767770	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021		3792867588	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021		3778667335	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021		3769167003	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021		3772967095	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021	PO3721866733	KU	2	50 BRN	SP	CCA			V	00:00.0	
2021		3743866692	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021		3740666544	KU	2	55 BRN	SP	CCA		V	00:00.0	
2021		3745366263	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021		3744966042	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021	PO4072785332	LGE	4	30 BRN	SP	CCA		ED,ID,IP	TD	00:00.0	
2021	PO4070285305	LGE	4	30 BRN	SP	CRE		ED,ID,IP	TD	00:00.0	
2021	PO4125584794	LGE	4	35 ACE	SP	P		ED,ID	BD	00:00.0	
2021	PO4116285268	LGE	4	35 BRO	SP	A		ED,ID,IP	TD	00:00.0	
2021	PO4116185257	LGE	4	40 BRO	SP	CCA			V	00:00.0	
2021	PO4122884799	LGE	4	35 ACE	SP	P		ED,ID	TD	00:00.0	
2021	PO4116085280	LGE	4	35 BRO	SP	A		ED,ID	TD	00:00.0	
2021	PO3805110475	KU	4	40 XXX	SP	CRE		ED,ID	TD	00:00.0	
2021	PO3842310620A	KU	5	35 BRN	SP	CCA			V	00:00.0	
2021	PO3842310620	KU	6	30 BRN	SP	CCA			V	00:00.0	
2021	PO3753610425	KU	3	45 BRN	SP	CCA			V	00:00.0	
2021	PO3790810466	KU	3	45 BRN	SP	CCA			V	00:00.0	
2021	PO3833510703	KU	4	40 XXX	SP	CRE		ED,ID	TD	00:00.0	
2021	PO4116985337	LGE	4	35 BRO	SP	P		ID	TD	00:00.0	
2021	PO3825232562	KU	3	45 BRO	SP	CCA			V	00:00.0	
2021	PO3836932553	KU	3	45 BRO	SP	CCA			V	00:00.0	
2021	PO3809232694	KU	3	45 BRO	SP	CCA			V	00:00.0	
2021	PO3789032795	KU	3	45 BRO	SP	CCA			V	00:00.0	
2021	PO3787732895	KU	3	45 BRO	SP	CCA			V	00:00.0	
2021	PO4169586005	F	4	35 BRO	SP	CRE			V	00:00.0	
2021	PO5374212568	KU	4	40 BRN	SP	CRE		ED,ID	TD	00:00.0	
2021	PO3902710264	KU	4	40 XXX	SP	CRE		ED,HH,ID,RB	BX	PX	00:00.0
2021	PO5365712711	KU	4	40 BRN	SP	CRE		ED,ID	TD	00:00.0	
2021	PO4169786020	LGE	4	35 BRO	SP	A		ED,ID	TD	00:00.0	
2021	PO4170986020	LGE	4	35 BRO	SP	A		ED,ID,IP	TD	00:00.0	
2021	PO3902610537	KU	4	40 XXX	SP	CRE		ID	BD	00:00.0	
2021	PO3904510881	KU	4	40 XXX	SP	CRE		ED,HH,ID,RB	X	PX	00:00.0
2021	PO3902010772	KU	4	40 XXX	SP	CRE		ID	BD	00:00.0	
2021	PO3920810636	KU	5	35 XXX	SP	CRE		ED,ID	TD	00:00.0	
2021	PO3910510800	KU	4	40 XXX	SP	P		ID	BD	00:00.0	
2021	PO5347912666	KU	7	35 BRN	SP	CCA			V	00:00.0	

2021	PO5359212627	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4130384580	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4129984591	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4129384619	LGE	3	40 ACE	SP	CCA		V	00:00.0
2021	PO4129584632	LGE	4	40 ACE	SP	P	ED,ID	V	00:00.0
2021	PO4129684643	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO4129784654	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4129884667	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4129984679	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4170785872	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4170785862	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4170485817	LGE	3	45 BRO	SP	CRE	ED,EP,ID	TD	00:00.0
2021	PO3796335680	F	4	40 UNK	SP	P		V	00:00.0
2021	PO3860110982	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO3863911188	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO8476058728	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4129984690	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4130184692	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4130084700	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4170485827	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4170585837	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO3789835572	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO3834735486	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4130184707	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4129884717	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO8476958878	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO8474358954	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4132184711	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4132184714	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4170685849	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO3832482379	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3844582650	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3853382849	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3860983056	KU	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3869583227	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3876583387	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3884983563	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3891083711	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3889583877	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3888983960	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3888284029	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3887084220	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3884584383	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3882384577	KU	3	45 BRN	SP	CRE		V	00:00.0
2021	PO3880584776	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	3882685038	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	3890084890	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO9073215584	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO9073215584	KU	4	35 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO9079915845	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO9088716146	KU	4	40 ACW	SP	CRE	ED,EP,ID,IP,RB	X	RP2 00:00.0
2021	PO3802634947	KU	4	40 UNK	SP	CRE		B	00:00.0
2021	PO3942980896	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3957680814	KU	4	40 BRN	SP	CCA		V	00:00.0

2021 PO3925280995	KU	2	40 BRN	SP	CCA		V		00:00.0
2021 PO3908081088	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3892981172	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3876481259	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3860281350	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3843381437	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3835881560	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3822981769	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3812581971	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3822482171	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4170285852	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO3830234833	KU	4	40 KOP	SP	CRE		B		00:00.0
2021 PO3796234725	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3832171051	F	4	45 BRN	SP	CCA		V		00:00.0
2021 PO3860971152	KU	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3884971234	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4157285871-F	KU	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO3810934449	KU	4	40 BRO	SP	CCA		B		00:00.0
2021 PO3789134481	KU	4	40 UNK	SP	CRE	ED,ID,RB	X	RP1	00:00.0
2021 PO8437015430	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO8499615678	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO4157285871-E	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO3978680699	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3992580620	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4010680457	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4020280319	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4030280174	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4042479994	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4053779825	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4075679212	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3796070927	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO3869936706	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO9066815325	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO3794671432	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3783871580	KU	5	30 BRN	SP	CRE	ID	BD		00:00.0
2021 PO3778171649	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO3833771997	F	4	40 BRN	SP	A		V		00:00.0
2021 PO3867636895	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO3865271731	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3823871544	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4168086028	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO3865537077	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3859037542	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3820135300	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO3801135107	KU	2	50 KOP	SP	CRE	ID	TD		00:00.0
2021 PO3828071281	F	4	40 BRN	SP	A		V		00:00.0
2021 PO3807971403	KU	6	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3843270378	KU	6	30 BRN	SP	CRE	ED	X	RP2	00:00.0
2021 PO4132984579a	KU	3	45 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4131584573	LGE	3	45 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4132984579	LGE	3	50 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO3831670150	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO3842970913	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4072579037	KU	4	40 BRN	SP	CCA		V		00:00.0



2021 PO4067778852	KU	4	40 BRN	SP	CCA		V			00:00.0
2021 PO3878784970	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO3876585185	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO3874385427	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO3871985655	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO3865186531	KU	2	50 BRN	SP	CCA		V			00:00.0
2021 PO3875586062	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO3869685919	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO5479012342	KU	3	35 BRN	SP	CCA		V			00:00.0
2021 PO4157285871-D	KU	4	40 BRO	SP	CRE	ED,ID,JP	TD			00:00.0
2021 PO4157285871-C	KU	4	40 BRO	SP	A	ED,ID,JP	TD			00:00.0
2021 PO4157285871-B	KU	4	40 BRO	SP	A	ED,ID	TD			00:00.0
2021 PO4157285871-A	KU	4	40 BRO	SP	CRE	ED,ID,JP	TD			00:00.0
2021 PO5444412464	KU	3	40 BRN	SP	CRE	ED,ID,JP	TD			00:00.0
2021 PO5461712403	KU	4	40 BRN	SP	CCA	ED	TD			00:00.0
2021 PO3777434026	KU	5	35 UNK	SP	CRE	ED,ID	TX	RR		00:00.0
2021 PO5437312488	KU	3	45 BRN	SP	CRE	ED,ID,MD	TD			00:00.0
2021 PO5432112650	KU	7	30 BRN	SP	CRE	ED,ID	TD			00:00.0
2021 PO8545616084	KU	4	45 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO8548116198	KU	4	45 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO3779734260	KU	4	40 INP	SP	CRE	ID	TD			00:00.0
2021 PO3768334031	KU	4	40 INP	SP	CRE	ID	TD			00:00.0
2021 PO5431712585	KU	5	35 BRN	SP	CRE	ED,ID,RB	BX	RR		00:00.0
2021 PO4167585753	F	4	30 BRO	SP	A		V			00:00.0
2021 PO3906171708	KU	5	35 BRN	SP	CCA		V			00:00.0
2021 PO3894971728	KU	4	40 BRN	SP	CCA		V			00:00.0
2021 PO3933971192	KU	6	30 BRN	SP	CRE	ID	TD			00:00.0
2021 PO3941271085	KU	4	40 BRN	SP	CRE	ID	TD			00:00.0
2021 PO3989973859	KU	4	40 BRN	SP	CRE	ID	TD			00:00.0
2021 PO5431512509	KU	4	40 BRN	SP	CRE	MD	V			00:00.0
2021 PO5408512591	KU	4	40 BRN	SP	CCA		V			00:00.0
2021 PO5415912564	KU	4	40 BRN	SP	CCA	ED	TD			00:00.0
2021 PO5397112631	KU	3	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021 PO3622555244	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO4168185770	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4168185773	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4168285782	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4168385796	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4168385802	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO8310014901	KU	4	35 ACW	SP	P	ED,ID	TD			00:00.0
2021 PO8327015043	KU	5	35 ACW	SP	CRE	ED,HH,ID,MD,RB	BX	RP2		00:00.0
2021 PO8310014901A	KU	4	35 ACW	SP	A	ED,ID	TD			00:00.0
2021 PO8260415427	KU	4	40 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO5386012672	KU	3	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021 PO4168585845	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4168485828	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4168485821	F	4	35 BRO	SP	CRE	HH,ID,RB	VX	RP1		00:00.0
2021 PO4168485815	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4168185807	F	3	45 BRO	SP	CCA		V			00:00.0
2021 PO3961973796	KU	6	30 BRN	SP	CRE	ID	TD			00:00.0
2021 PO3965673907	KU	4	40 BRN	SP	CRE	ID	TD			00:00.0
2021 PO4029276199	KU	5	35 BRN	SP	CRE	ID	TD			00:00.0
2021 PO4170485917	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO3773733633	KU	3	45 BRO	SP	CCA		V			00:00.0

2021 PO4169385965	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4169185958	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4169285946	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4169185939	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4169185934	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4169085921	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4168885918	F	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5381612540	KU	3	40 BRN	SP	CRE	ED,ID,MD	TD	00:00.0
2021 PO5372212835	KU	7	35 BRN	SP	CCA	ED	TD	00:00.0
2021 PO3868011377	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3899511314	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3872011580	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3667163814	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO8170614877	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7972114892	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7988014837	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8004814680	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO7994914703	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO8024314269	KU	4	40 ACW	SP	CRE	ED,ID	BD	00:00.0
2021 PO7990614421	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO3884011345	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3870410901	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4170185972	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO3939310236	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO3778233460	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3782633194	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3956532826	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4015676258	F	4	40 BRN	SP	CRE	ED,HH	BX	RP2 00:00.0
2021 PO4000976179	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5376112894	KU	7	30 BRN	SP	CRE	ED,ID,MD	TD	00:00.0
2021 PO4169585998	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4168985973	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4169385974	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO3887510891	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3921710266	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4169485991	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4169485985	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO3934932764	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3917532714	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3896532654	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3871832644	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4023971166	KU	5	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4325936064	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4339035979	KU	4	40 BRO	SP	CRE		B	00:00.0
2021 PO4391836034	KU	4	40 BRO	SP	CRE		B	00:00.0
2021 PO4376836187	KU	4	45 ACW	SP	CCA		B	00:00.0
2021 PO4394336288	KU	4	45 ACW	SP	CCA		B	00:00.0
2021 PO4410736417	KU	4	45 ACW	SP	CCA	MD	BD	00:00.0
2021 PO4278836465	KU	4	40 ACW	SP	CRE	ID	TD	00:00.0
2021 PO4310536325	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4307236194	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4364735795	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO3971180933	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4348935903	KU	3	45 UNK	SP	CCA		V	00:00.0

2021	PO4358135838	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO4216536198	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO3977881154	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO3986181421	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO4010081602	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO3978970984	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021	PO3839172338	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3848772526	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3857872696	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3808071736	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3816671902	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3847373057	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3824773216	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3867472895	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3878173090	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3888473296	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3898873490	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO3910973700	KU	3	45 BRN	SP	CCA		V	00:00.0
2021		3951673685	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO3950673942	KU	2	50 BRN	SP	CCA		V	00:00.0
2021		3980273942	KU	3	45 BRN	SP	CCA	V	00:00.0
2021		4000574082	KU	3	45 BRN	SP	CCA	V	00:00.0
2021		4020770756	KU	3	45 BRN	SP	CCA	V	00:00.0
2021		4038274276	KU	3	45 BRN	SP	CCA	V	00:00.0
2021		4051674441	KU	3	45 OTH	SP	CCA	V	00:00.0
2021	PO4024774645	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO4092185290	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021	PO4569808940	KU	4	40 BRN	SP	P	ED,ID,RB	X PX	00:00.0
2021	PO4566409183	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4105985293	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4106185280	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4106685273	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4106285278	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO3660587643	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3625087895	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3707088855	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021	PO3707088579	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO3718588887	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO3726388706	KU	3	55 BRN	SP	CRE	ID	TD	00:00.0
2021	PO3729988544	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021	PO3735588356	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021	PO4187408835	KU	3	50 BRN	SP	CCA	ED	TD	00:00.0
2021	PO4098785488	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4100185486	LGE	3	55 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4099685405	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4162385765	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4162485787	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4162585799	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4101285485	LGE	3	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4184708483	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO4185908642	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4186608673	KU	3	45 BRN	SP	CCA	ED	TD	00:00.0
2021	PO3992085441	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3991085446	LGE	4	40 BRN	SP	A	ED,ID	TD	00:00.0

2021	PO4101485511	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO3871712701	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO3874112878	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO6409309215	F	4	40 ACW	SP	A		V	00:00.0
2021	PO6407709423	KU	4	45 ACW	SP	S		V	00:00.0
2021	PO6406609549	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO6415009560	KU	4	45 ACW	SP	S		V	00:00.0
2021	PO4101485504	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4101885470	LGE	3	80 ACE	SP	P		V	00:00.0
2021	PO3990085451	LGE	4	40 BRN	SP	A	ED,EP,ID	BD	00:00.0
2021	PO4100085326	LGE	7	25 BRO	SP	CRE		V	00:00.0
2021	PO4101085413	LGE	7	25 BRO	SP	CRE	ID	BD	00:00.0
2021	PO4100985404	LGE	4	45 BRO	SP	A	ED,ID	BD	00:00.0
2021	PO4100785392	LGE	4	40 BRO	SP	CRE	ED,EP,HH,ID	BD	00:00.0
2021	PO4101585391	LGE	6	25 BRO	SP	CRE		V	00:00.0
2021	PO4162285755	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4162185746	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4162085721	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4162385712	F	4	40 BRO	SP	A		V	00:00.0
2021	PO3990885463	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021	PO3990185460	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3989785464	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021	PO3988285462	LGE	3	45 BRN	SP	CCA	MD	VX PX	00:00.0
2021	PO3875212995	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO4160685807	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4160585751	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO6458909026	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO4160885755	F	4	30 BRO	SP	A		V	00:00.0
2021	PO4160585757	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4160585764	F	4	30 BRO	SP	A		V	00:00.0
2021	PO6439109439	F	3	40 ACW	SP	S		V	00:00.0
2021	PO6435409396	KU	4	45 ACW	SP	S		V	00:00.0
2021	PO6423109194	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO4081385366	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4081185364	F	4	45 ACE	SP	P		V	00:00.0
2021	PO4079785365	LGE	4	30 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021	PO4080585374	LGE	4	40 ACE	SP	A		V	00:00.0
2021	PO3878712736	F	4	40 XXX	SP	P		V	00:00.0
2021	PO3881712956	F	4	40 KOP	SP	CCA		V	00:00.0
2021	PO3882413009	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4160685771	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO3918610920	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4223809281	KU	2	55 BRN	SP	CCA	ED	TD	00:00.0
2021	PO4010985295	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4012485295	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4014185293	F	4	30 BRN	SP	CCA		V	00:00.0
2021	PO4027677796	KU	2	40 BRN	SP	CCA		V	00:00.0
2021	PO4008977215	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO4136585575	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4225909261	KU	2	50 BRN	SP	CCA	ED	TD	00:00.0
2021	PO4094385498	LGE	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4013685294	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4013485307	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PV3991085386	F	4	40 BRN	SP	CCA		V	00:00.0

2021	PO4096585368	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4162385775	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO3926110959	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO3927373845	KU	4	35 BRN	SP	CCA		V	00:00.0
2021	PO3940373947	KU	4	35 BRN	SP	CCA		V	00:00.0
2021	PO3961274149	KU	4	35 BRN	SP	CCA		V	00:00.0
2021	PO3969674291	KU	4	35 BRN	SP	CCA		V	00:00.0
2021	PO3981274489	KU	4	35 BRN	SP	CCA		V	00:00.0
2021	PO3991674683	KU	4	35 BRN	SP	CCA		V	00:00.0
2021	PO4000374845	KU	4	35 BRN	SP	CCA		V	00:00.0
2021	PO4002475076	KU	4	35 BRN	SP	CCA		V	00:00.0
2021	PO3785671297	KU	5	35 BRN	SP	CRE		V	00:00.0
2021	PO4002376351	KU	2	40 BRN	SP	CCA		V	00:00.0
2021	PO4004276613	KU	2	40 BRN	SP	CCA		V	00:00.0
2021	PO3999375981	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3997675740	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3998875609	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO4002975295	KU	2	50 BRN	SP	CCA		V	00:00.0
2021		4045475096	KU	3	45 BRN	SP	CCA	V	00:00.0
2021		4044871778	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO4217309188	KU	2	45 BRN	SP	CRE	ED	TD	00:00.0
2021	PV3990685398	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO7052465680	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021	PV3990385409	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO6386309253	KU	4	45 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO6388509461	KU	4	50 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6392209744	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO4097585366	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4098885365	LGE	4	40 BRO	SP	A	ID	TD	00:00.0
2021	PO4098785410	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4095485496	LGE	5	25 ACE	SP	A	ED,HH,ID,RB	BX	RP1 00:00.0
2021	PO4095185492	LGE	4	45 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4095785492	LGE	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO3915711278	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4206609096	KU	2	50 BRN	SP	CCA	ED,ID,IP	V	00:00.0
2021	PO4198308985	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021	PO3990485421	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3988385425	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4163385809	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4162185734	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO3988985434	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3990185436	LGE	4	40 BRN	SP	A	ED,ID,IP	BD	00:00.0
2021	PO3657987822	KU	6	35 BRN	SP	CCA		V	00:00.0
2021	PO3623087651	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO3667388193	KU	6	35 BRN	SP	CCA		V	00:00.0
2021	PO3702688118	KU	6	35 BRN	SP	CRE		V	00:00.0
2021	PO3712887738	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3711987649	KU	6	35 BRN	SP	CCA		V	00:00.0
2021	PO3546287105	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO3546687193	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO3599387258	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO3588587512	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3587187554	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO3569987387	F	4	40 BRN	SP	CRE		V	00:00.0

2021 PO3607287540	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3622787744	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3611487651	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO3612687531	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3625887579	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3984585593	LGE	4	25 BRN	SP	CCA		V	00:00.0
2021 PO4093385296	LGE	4	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4093185308	LGE	6	25 BRO	SP	CRE		V	00:00.0
2021 PO4093885304	LGE	4	40 BRO	WC	CRE	ED,EP	VX PX	00:00.0
2021 PO3980585593	F	2	60 BRN	SP	CRE		V	00:00.0
2021 PO3983285571	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3983685557	LGE	4	40 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO6428511083	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6428311203	KU	6	30 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO4111385498	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3906012099	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3893512083	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3887712167	KU	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO3926612129	KU	4	40 XXX	SP	CRE	ID,IP	BD	00:00.0
2021 PO3939912116	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3951112265	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3918312364	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO3937612343	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO3942612280	KU	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO3943412334	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO3939312509	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4573309350	F	2	50E BRN	SP	CRE	ED	V	00:00.0
2021 PO4576009488	F	3	40 BRN	SP	A	ED	V	00:00.0
2021 PO4577009339	F	3	40 BRN	SP	CRE	ED	V	00:00.0
2021 PO4094985322	LGE	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4094785334	LGE	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4095385330	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4136085592	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4159385850	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4096285343	LGE	6	25 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4096185336	LGE	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4097485336	LGE	5	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4159285839	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4159285832	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO6408509612	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO6412609652	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6412509696	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6412409886	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO4135885611	LGE	4	35 ACE	SP	A		V	00:00.0
2021 PO4134385646	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4134985625	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4135685605	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4098785333	LGE	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4100185332	LGE	4	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4101385321	LGE	4	30 BRO	SP	CRE	ED,EP,RB	X PX	00:00.0
2021 PO4159185812	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4159185824	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX RR	00:00.0
2021 PO6412310069	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6412210187	KU	4	45 ACW	SP	CRE	ED,ID	TD	00:00.0

2021 PO4134885658	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4135185649	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4135485638	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4135785626	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4136185618	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4599908164	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4159185800	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4167485523	LGE	4	35 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	TX	RR	00:00.0
2021 PO4167285512	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4167185501	LGE	4	35 BRO	SP	CRE	ED,EP,ID,IP	TD		00:00.0
2021 PO4167085491	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4167085484	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4166985474	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4168785476	LGE	4	30 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021 PO4170085478	KU	4	35 BRO	SP	A	ID,IP,MD,RB	TX	RR	00:00.0
2021 PO4160385404	LGE	4	35 BRO	SP	CRE	EP,HH,RB	BX	PX	00:00.0
2021 PO4170385504	LGE	4	35 BRO	SP	CRE	ED,EP,ID,IP	TX	RR	00:00.0
2021 PO4170485517	LGE	4	35 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO4169185566	LGE	4	30 BRO	SP	CRE	ED,EP,ID,RB	X	PX	00:00.0
2021 PO4170585529	LGE	4	35 BRO	SP	CRE	IP,RB	BX	RP3	00:00.0
2021 PO4170685542	LGE	4	35 BRO	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO4170885553	LGE	4	35 BRO	SP	CRE	ED,EP,ID,IP,RB	TX	RR	00:00.0
2021 PO3900424256	KU	4	45 BRO	SP	CCA		B		00:00.0
2021 PO3879724396	KU	4	40 BRO	SP	CCA		B		00:00.0
2021 PO3917523781	KU	4	45 BRO	SP	CCA		B		00:00.0
2021 PO3997809946	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4664107382	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4164385759	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO3905611587	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5089627199	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO5092327272	F	4	40 BRN	SP	S		V		00:00.0
2021 PO3932023863	KU	3	50 BRO	SP	CCA		B		00:00.0
2021 PO3961024107	KU	4	40 BRO	SP	S		B		00:00.0
2021 PO3958323849	KU	4	45 BRO	SP	S		B		00:00.0
2021 PO3958923381	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3968623728	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3978123764	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3985423845	KU	4	40 BRO	SP	S		B		00:00.0
2021 PO4007723858	KU	4	40 BRO	SP	S		B		00:00.0
2021 PO4075385060	LGE	4	35 BRN	SP	A	ED,ID,IP	BD		00:00.0
2021 PO4077685071	LGE	4	35 BRN	SP	A	ED,ID,IP	BD		00:00.0
2021 PO4076985060	LGE	4	35 BRN	SP	A	ED,ID,IP	BD		00:00.0
2021 PO3850335857	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4030586335	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4022185777	LGE	4	40 KOP	SP	P	ID	BD		00:00.0
2021 PO5227326375	F	4	40 BRN	SP	CRE	ID,RB	BX	PX	00:00.0
2021 PO5024934208	KU	6	30 BRN	SP	CCA	ED,ID	X	RP2	00:00.0
2021 PO5031633905	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO3915086039	LGE	4	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO3914186045	LGE	4	45 ACE	SP	CRE	ED,HH,ID	BD		00:00.0
2021 PO3913386018	LGE	4	40 ACE	SP	A	ID	TD		00:00.0
2021 PO5119837430	KU	4	40 KOP	SP	CRE	ID	BD		00:00.0
2021 PO5349737973	KU	3	45 KOP	SP	CRE	ID	TD		00:00.0
2021 PO5351437868	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0

2021 PO4048685556	F	4	40 BRO	SP	CRE		VX	RP2	00:00.0
2021 PO4021385696	LGE	4	35 KOP	SP	P	ED	TD		00:00.0
2021 PO4039886094	LGE	4	40 KOP	SP	P	ED,EP,ID	TD		00:00.0
2021 PO5378511346	KU	4	40 BRO	SP	CRE	ED	TD		00:00.0
2021 PO5277925539	KU	3	45 BRN	SP	CRE	ED,RB	BX	PX	00:00.0
2021 PO4038686066	LGE	4	40 KOP	SP	P	ED,ID,IP	TD		00:00.0
2021 PO5292825844	KU	4	40 BRN	SP	CRE		T		00:00.0
2021 PO5387611311	KU	5	40 BRO	SP	CRE	ED,ID,MD	TD		00:00.0
2021 PO4038186056	LGE	4	40 KOP	SP	P	ED,ID	TD		00:00.0
2021 PO4864532752	KU	2	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5427911014	KU	7	30 BRO	SP	CRE	ID	TD		00:00.0
2021 PO4035686372	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5009933524	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4999633341	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4984433145	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5276825378	KU	3	45 BRN	SP	CRE		T		00:00.0
2021 PO5020733716	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4032386378	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4700912382	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4693112234	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4013186325	LGE	4	30 ACE	SP	A	ID	TD		00:00.0
2021 PO5286425960	KU	2	40 BRN	SP	CRE		T		00:00.0
2021 PO4034086382	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5273425926	KU	3	40 BRN	SP	CRE		T		00:00.0
2021 PO4024585792	LGE	4	35 KOP	SP	CCA	ED	T		00:00.0
2021 PO5407511075	KU	7	30 BRO	SP	CRE		T		00:00.0
2021 4035686372A	LGE	4	40 ACE	SP	CRE	ED,ID	TX	RP3	00:00.0
2021 PO4014586315	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4013886318	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4037486043	LGE	4	40 KOP	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4036286018	LGE	4	40 KOP	SP	P	ED,EP,ID,MD	TD		00:00.0
2021 PO5368711384	KU	3	40 BRO	SP	CRE	ED	TD		00:00.0
2021 PO5453709914	KU	5	35 KOP	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021 PO4927537517	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4963037411	KU	5	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4957337375	KU	2	45 BRO	SP	CRE	ID	TD		00:00.0
2021 PO5142026705	KU	5	35 BRN	SP	CRE		T		00:00.0
2021 PO4014286516	LGE	4	40 ACE	SP	A	ID	BD		00:00.0
2021 PO4013686519	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4015586542	LGE	3	50 ACE	SP	CRE	ED,ID,IP	BX	RR	00:00.0
2021 PO4051686603	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4050986586	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4050586578	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4013286514	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4013386514	LGE	2	55 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4012686508a3	KU	3	45 ACE	SP	P	ID	TD		00:00.0
2021 PO4012686508a2	KU	3	45 ACE	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4012686509a1	KU	4	40 ACE	SP	A	ID	BD		00:00.0
2021 PO4012686508	LGE	3	50 ACE	SP	CRE	ED,HH,ID	TD		00:00.0
2021 PO4860238545	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4848638269	KU	3	45 KOP	SP	CRE	ID	BD		00:00.0
2021 PO4983537906	KU	3	45 ESC	SP	CRE	ED,ID	X	RP1	00:00.0
2021 PO5467914162	KU	2	45 BRO	SP	CRE	ED,ID,IP	X	PX	00:00.0
2021 PO5461714362	KU	3	45 BRO	SP	CRE		T		00:00.0



2021 PO4029085770	LGE	4	35 KOP	SP	P	ED	TD	00:00.0
2021 PO5188926746	KU	4	40 BRN	SP	CRE		T	00:00.0
2021 PO4901532316	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4911032266	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4904832102	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4915832242	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5402509931	KU	1	55 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO5407109898	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4018386548	LGE	4	40 ACE	SP	A	ID	BD	00:00.0
2021 PO4018686530	LGE	4	45 ACE	SP	P	ID	TD	00:00.0
2021 PO5100026632	KU	4	40 BRN	SP	CRE		T	00:00.0
2021 PO4054286581	LGE	4	40 ACE	SP	CCA		T	00:00.0
2021 PO4055286591	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4022385689	LGE	4	35 KOP	SP	CCA	ID	BD	00:00.0
2021 PO4025585685	LGE	4	40 KOP	SP	P	ED,ID	TD	00:00.0
2021 PO4053186571	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4026385704	LGE	4	35 KOP	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4052386557	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4052786565	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5394909717	KU	4	45 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO4794139035	KU	3	45 KOP	SP	CRE	ID	BD	00:00.0
2021 PO4029785786	LGE	4	35 KOP	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4067986649	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4066686656	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4066386663	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4063986670	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5386309993	KU	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO5392609998	KU	3	50 KOP	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021 PO4030785812	LGE	4	35 KOP	SP	CCA	ED,ID	TD	00:00.0
2021 PO4785138864	KU	3	45 UNK	SP	CCA	ID	BD	00:00.0
2021 PO4031185822	LGE	4	35 KOP	SP	P	ED,ID	TD	00:00.0
2021 PO4068686661	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3944385921	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4031685834	LGE	4	40 KOP	SP	P	ED,ID	TD	00:00.0
2021 PO3942585908	LGE	3	50 ACE	SP	A	ID	TD	00:00.0
2021 PO3941385884	LGE	4	30 ACE	SP	CCA	ED,ID,IP	BD	00:00.0
2021 PO3940985887	LGE	3	50 ACE	SP	CCA	ED,ID,IP	TD	00:00.0
2021 PO4066586688	LGE	4	40 ACE	SP	CRE	ED	TD	00:00.0
2021 PO4067986681	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4069286674	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3938885865	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3938485873	LGE	4	30 ACE	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO3939385867	LGE	3	55 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5459014461	KU	3	45 BRO	SP	CRE		T	00:00.0
2021 PO5497614617	KU	3	45 BRO	SP	CRE		T	00:00.0
2021 PO5479514540	KU	3	45 BRO	SP	CRE		T	00:00.0
2021 PO4810338283	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4783738454	KU	5	35 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4776138692	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4870032389	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4880132228	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4887132390	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PV3938585856	LGE	3	50 ACE	SP	CRE	ID	BD	00:00.0
2021 PO4064086451	LGE	4	40 ACE	SP	CRE	ED,ID	BX	00:00.0

2021 PO4894932156	KU	5	35 BRN	SP	CRE	ED,EP,ID	X	RP1	00:00.0
2021 PO4886032665	KU	2	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4063186508	LGE	4	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4951432484	KU	2	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5401211422	KU	4	45 BRO	SP	A	ID	TD		00:00.0
2021 PO5017638312	KU	4	40 INP	SP	CRE	ID	BD		00:00.0
2021 PO4994238163	KU	3	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4836938202	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4856338627	KU	3	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4065286547	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4064586535	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4063886521	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5222826666	KU	4	40 BRN	SP	CRE		T		00:00.0
2021 PO5411611383	KU	3	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO5118138380	KU	4	40 INP	SP	CRE	ID	TD		00:00.0
2021 PO5082138360	KU	5	35 UNK	SP	CRE	ED	TD		00:00.0
2021 PO5047538338	KU	4	40 INP	SP	CRE	ID	BD		00:00.0
2021 PO5377911514	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO4031486343	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4032185907	LGE	4	30 KOP	SP	P	ID	BD		00:00.0
2021 PO4032486349	LGE	4	35 ACE	SP	A	ID	TD		00:00.0
2021 PO4033486356	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4034086361	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4055285779	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4031186358	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4030886349	LGE	4	40 ACE	SP	CCA		T		00:00.0
2021 PO4055585752	F	4	30 BRO	SP	A		VX	RP3	00:00.0
2021 PO5366211561	KU	4	40 BRO	SP	CRE	ED	TD		00:00.0
2021 PO5438110990	KU	6	35 BRO	SP	CRE	ID,SRC	TD		00:00.0
2021 PO3911785966	LGE	4	40 ACE	SP	A	ID	BD		00:00.0
2021 PO3912585992	LGE	4	45 ACE	SP	CRE	ED,EP,ID	BD		00:00.0
2021 PO5275925262	KU	3	45 BRN	SP	CRE		T		00:00.0
2021 PO4681512025	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4673312059	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4673412108	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4031786368	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4060185637	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4060785625	F	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4060185626	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4060685608	F	5	35 BRO	SP	P		V		00:00.0
2021 PO4060085609	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4060385592	F	6	25 BRO	SP	P		V		00:00.0
2021 PO4059885578	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4060385579	F	6	25 BRO	SP	A		V		00:00.0
2021 PO4042386070	F	3	45 KOP	SP	CCA		V		00:00.0
2021 PO4042986066	F	4	40 KOP	SP	P		V		00:00.0
2021 PO5360711085	KU	7	35 BRO	SP	CCA		V		00:00.0
2021 PO4042286056	F	4	30 KOP	SP	P		V		00:00.0
2021 PO4017086308	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4016586311	LGE	4	45 ACE	SP	A		V		00:00.0
2021 PO4015686316	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4041786059	F	4	40 KOP	SP	P		V		00:00.0
2021 PO4041986044	F	4	35 KOP	SP	P		V		00:00.0
2021 PO7515375216	LGE	4	40 ACE	SP	CCA		V		00:00.0

2021 PO7519675134	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO7515875158	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO7539475013	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4040486329	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO7255874452	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO7603417372	KU	3	45 KOP	SP	S	V	00:00.0
2021 PO4995734657	KU	2	60 BRO	SP	CCA	B	00:00.0
2021 PO4985234739	KU	2	55 KOP	SP	CCA	B	00:00.0
2021 PO5069425518	KU	4	40 UNK	SP	CRE	B	00:00.0
2021 PO5067725635	KU	4	40 UNK	SP	CRE	B	00:00.0
2021 PO4047585684	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4047085691	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4048285695	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4049285658	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4049185668	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4049385683	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4049485694	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4050685688	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4050685694	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4051985694	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4053985687	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4053885675	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4053285666	F	4	30 BRO	SP	P	V	00:00.0
2021 PO4053885666	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4055985665	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4059285653	F	4	30 BRO	SP	P	V	00:00.0
2021 PO4650013578	F	4	40 KOP	SP	P	V	00:00.0
2021 PO4641913298	F	4	40 KOP	SP	P	V	00:00.0
2021 PO5181311372	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO5070425415	KU	4	40 UNK	SP	CRE	B	00:00.0
2021 PO4034385987	F	3	45 KOP	SP	CCA	V	00:00.0
2021 PO4034885992	F	3	45 KOP	SP	CCA	V	00:00.0
2021 PO4636113083	F	4	40 KOP	SP	P	V	00:00.0
2021 PO4646113441	F	4	40 KOP	SP	P	V	00:00.0
2021 PO4932435145	KU	2	45 KOP	SP	CCA	B	00:00.0
2021 PO4943235061	KU	2	50 BRO	SP	CCA	B	00:00.0
2021 PO4916835264	KU	2	50 BRO	SP	CCA	V	00:00.0
2021 PO5404112455	KU	6	35 BRO	SP	CCA	V	00:00.0
2021 PO5417512393	F	2	35E BRO	SP	P	V	00:00.0
2021 PO5407712444	F	7	25E BRO	SP	CRE	V	00:00.0
2021 PO5368412175	F	6	30 BRO	SP	CCA	V	00:00.0
2021 PO4884335524	KU	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4871435623	KU	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4857335730	KU	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4843435838	KU	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4829735943	KU	1	60 BRO	SP	CCA	V	00:00.0
2021 PO4892635452	KU	4	35 UNK	SP	P	V	00:00.0
2021 PO5316411280	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO5322711201	KU	2	55 BRO	SP	CCA	V	00:00.0
2021 PO5162025045	KU	5	35 UNK	SP	CRE	B	00:00.0
2021 PO4902035375	KU	2	55 BRO	SP	CRE	V	00:00.0
2021 PO5371012100	F	4	45 BRO	SP	CCA	V	00:00.0
2021 PO5223633161	KU	6	30 BRN	SP	CRE	V	00:00.0
2021 PO5247632965	KU	6	30 BRN	SP	CRE	V	00:00.0

2021	PO5365811189	KU	3	45 BRO	SP	CCA			V	00:00.0
2021	PO5158625729	KU	6	30 UNK	SP	CRE			B	00:00.0
2021	PO4046786337	LGE	4	30 ACE	SP	CRE			V	00:00.0
2021	PO4048486386	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4048186377	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4049386369	F	4	40 ACE	SP	CCA			V	00:00.0
2021	PO4049986365	F	4	45 ACE	SP	A			V	00:00.0
2021	PO5107737536	KU	5	35 KOP	SP	CCA			B	00:00.0
2021	PO5113037658	KU	5	35 KOP	SP	CCA			B	00:00.0
2021	PO5123337667	KU	5	35 BRO	SP	CCA			B	00:00.0
2021	PO5135037677	KU	5	35 KOP	SP	CCA			B	00:00.0
2021	PO5269625381	KU	3	45 BRN	SP	CRE			B	00:00.0
2021	PO5268325403	KU	3	45 BRN	SP	CCA			V	00:00.0
2021	PO5216332752	KU	4	45 KOP	SP	CCA			V	00:00.0
2021	PO5308710778	F	5	40 BRO	SP	CRE			V	00:00.0
2021	PO4048285830	LGE	4	30 BRO	SP	CRE			V	00:00.0
2021	PO4044985757	F	4	40 BRO	SP	P			V	00:00.0
2021	PO4046185757	F	4	40 BRO	SP	P			V	00:00.0
2021	PO4046285620	LGE	4	40 BRO	UN	CRE			V	00:00.0
2021	PO4047185756	F	4	40 BRO	SP	CRE			V	00:00.0
2021	PO4048185756	F	4	35 BRO	SP	A			V	00:00.0
2021	PO4048085142	LGE	5	30 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO5532236026	KU	2	45 UNK	SP	CRE	ID		BD	00:00.0
2021	PO5532936171	KU	3	45 BRO	SP	CCA			V	00:00.0
2021	PO5532736291	KU	3	45 INP	SP	CRE	ID		TD	00:00.0
2021	PO4040884627	LGE	3	45 OTH	SP	CCA			V	00:00.0
2021	PO4041284626	LGE	3	45 OTH	SP	A	ID,SRS		TD	00:00.0
2021	PO7571958022	LGE	4	30 OTH	SP	CCA			V	00:00.0
2021	PO4042084625	F	4	45 OTH	SP	A			V	00:00.0
2021	PO4061885133	F	3	50 BRO	SP	CCA			V	00:00.0
2021	PO4061485134	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4060185144	LGE	1	50 BRO	SP	CCA			V	00:00.0
2021	PO4059585148	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4061585133	LGE	4	45 BRO	SP	CRE			V	00:00.0
2021	PO4059985139	LGE	4	30 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO3979486369	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO6940675306	F	4	30 ACE	SP	CCA			V	00:00.0
2021	PO3981286360	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO3981886356	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO3983086350	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO4040184609	LGE	3	45 OTH	SP	CCA			V	00:00.0
2021	PO4039684592	LGE	1	50 OTH	SP	CCA			V	00:00.0
2021	PO4044684586	LGE	4	40 OTH	SP	CRE			V	00:00.0
2021	PO4045884587	LGE	4	40 OTH	SP	CCA			V	00:00.0
2021	PO4045884579	LGE	6	30 OTH	SP	CRE	HH,ID		VX	RP2 00:00.0
2021	PO4046984587	LGE	4	40 OTH	SP	A			V	00:00.0
2021	PO4048284587	LGE	5	40 OTH	SP	CRE			V	00:00.0
2021	PO4048284581	LGE	6	35 OTH	SP	CRE			V	00:00.0
2021	PO4048284569	LGE	5	30 OTH	SP	A	ID,SRS		TD	00:00.0
2021	PO4049484582	LGE	4	35 OTH	SP	CCA			V	00:00.0
2021	PO4049384587	LGE	3	45 OTH	SP	CCA			V	00:00.0
2021	PO4042584751	LGE	3	50 ACE	SP	CRE	ED,ID,IP		BD	00:00.0
2021	PO4042684750	LGE	3	45 ACE	SP	A	ED,ID		BD	00:00.0
2021	PO4048584828	LGE	4	45 ACE	SP	CCA			V	00:00.0

2021 PO4047684806	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4048184817	LGE	4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4047784790	LGE	4	45 ACE	SP	CRE		V		00:00.0
2021 PO4036486217	LGE	2	55 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4034786220	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4047184824	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4052084680	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO6420300438	F	4	40 BRN	SP	CRE	ED,HH,ID	BX	RP2	00:00.0
2021 PO6435600354	F	4	40 BRN	SP	CRE	ED	V		00:00.0
2021 PO6447500247	F	3	45 BRN	SP	P		V		00:00.0
2021 PO6428900228	F	3	45 BRN	SP	P		V		00:00.0
2021 PO6398800557	F	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4842838920	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4832538693	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4843038138	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5480135809	KU	5	35 BRO	SP	CRE	ID	BD		00:00.0
2021 PO4097486326	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4097586350	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4097486338	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4097386314	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4097286302	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4097286290	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4097186279	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4039184578	LGE	3	50 OTH	SP	CRE	HH,ID	BX	RP2	00:00.0
2021 PO4038784566	LGE	3	45 OTH	SP	CRE	ID,IP	BD		00:00.0
2021 PO4068085220	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4069385234	F	4	50 BRO	SP	CRE		V		00:00.0
2021 PO4067285238	LGE	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4067085262	F	5	30 BRO	SP	CRE		V		00:00.0
2021 PO4078785288	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4050384806	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO4050584811	LGE	5	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4048784833	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO5516936367	KU	3	45 INP	SP	CRE	ID	BD		00:00.0
2021 PO5353736331	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4035686209	LGE	2	55 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4035386212	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4041284574	LGE	4	30 OTH	SP	A		V		00:00.0
2021 PO4041084583	LGE	4	40 OTH	SP	CRE		V		00:00.0
2021 PO4042384586	LGE	4	40 OTH	SP	CCA		V		00:00.0
2021 PO4043384587	LGE	5	40 OTH	SP	CRE		V		00:00.0
2021 PO4043984740	F	3	45 ACE	SP	P		V		00:00.0
2021 PO4045584779	F	3	45 ACE	SP	P		V		00:00.0
2021 PO3949785915	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4027286234	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO5539536500	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4746838235	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4996637942	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4973237360	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4819338066	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4745738803	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4769639207	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4758739022	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4050184586	LGE	4	40 OTH	SP	A		V		00:00.0

2021	PO5348835907	KU	2	50 BRN	SP	CCA			V		00:00.0
2021	PO5350136027	KU	2	50 BRN	SP	CCA			V		00:00.0
2021	PO5351236142	KU	2	50 BRN	SP	CCA			V		00:00.0
2021	PO4047384791	LGE	4	30 ACE	SP	CCA			V		00:00.0
2021	PO4047484798	LGE	3	45 ACE	SP	CCA			V		00:00.0
2021	PO4047284796	LGE	3	45 ACE	SP	CCA			V		00:00.0
2021	PO4046984788	LGE	4	45 ACE	SP	CRE		ED,ID	BD		00:00.0
2021	PO4046484775	LGE	4	45 ACE	SP	CRE			V		00:00.0
2021	PO4049084792	LGE	4	30 ACE	SP	CCA			V		00:00.0
2021	PO5534936654	KU	6	30 UNK	SP	CRE		ID	BD		00:00.0
2021	PO4062385149	LGE	4	35 BRO	SP	CRE		ED,ID	BD		00:00.0
2021	PO4061685154	LGE	4	35 BRO	SP	CRE		ED,ID	BD		00:00.0
2021	PO4063585158	F	4	40 BRO	SP	CRE			V		00:00.0
2021	PO4062785146	F	4	45 BRO	SP	CRE			V		00:00.0
2021	PO3947985932	LGE	4	40 ACE	SP	CRE		ED,EP,ID,RB	BX	PX	00:00.0
2021	PO3949685950	LGE	3	45 ACE	SP	P		ED,ID	BD		00:00.0
2021	PO3930985879	F	1	50 ACE	SP	CCA			V		00:00.0
2021	PO3922885911	LGE	4	40 ACE	SP	CRE		ED,ID,IP	TD		00:00.0
2021	PO3923185909	LGE	4	30 ACE	SP	CRE		ED,ID	TD		00:00.0
2021	PO4055184995	LGE	1	50 ACE	SP	CCA			V		00:00.0
2021	PO4061485162	LGE	4	35 BRO	SP	CRE		ED,ID	TD		00:00.0
2021	PO4061885166	LGE	4	35 BRO	SP	CRE		ED,ID	TD		00:00.0
2021	PO5539436804	KU	3	45 INP	SP	CRE		ID	BD		00:00.0
2021	PO4049684793	LGE	4	30 ACE	SP	CRE			V		00:00.0
2021	PO5434736901	KU	3	45 BRO	SP	CRE		ID	BD		00:00.0
2021	PO3972785508	LGE	4	35 ACE	SP	CCA			V		00:00.0
2021	PO4040186259	LGE	2	45 ACE	SP	CCA			V		00:00.0
2021	PO4037986266	LGE	4	40 ACE	SP	CRE		ED,ID	BD		00:00.0
2021	PO4018086203	LGE	4	35 ACE	SP	CCA			V		00:00.0
2021	PO4008186129	LGE	4	40 ACE	SP	P		ED,ID,IP	BD		00:00.0
2021	PO4009186139	LGE	4	40 ACE	SP	P		ED,ID	TD		00:00.0
2021	PO4009786142	LGE	4	35 ACE	SP	P		ED,ID	TD		00:00.0
2021	PO4010486147	LGE	4	40 ACE	SP	P		ED,ID,IP	TD		00:00.0
2021	PO4011386154	LGE	4	35 ACE	SP	P		ED,ID	TD		00:00.0
2021	PO4012386162	LGE	4	35 ACE	SP	P		ED,ID	TD		00:00.0
2021	PO4013486169	LGE	4	35 ACE	SP	P		ED,ID	TD		00:00.0
2021	PO4014486177	LGE	4	40 ACE	SP	CCA			V		00:00.0
2021	PO4015486184	LGE	4	35 ACE	SP	P		ED,ID	TD		00:00.0
2021	PO4015986188	LGE	4	35 ACE	SP	P		ED,ID	TD		00:00.0
2021	PO4018986189	LGE	3	45 ACE	SP	CCA			V		00:00.0
2021	PO4018286199	LGE	4	40 ACE	SP	CCA			V		00:00.0
2021	PO4016986195	LGE	3	45 ACE	SP	CCA			V		00:00.0
2021	PO4020086183	LGE	4	40 ACE	SP	P		ED,ID	TD		00:00.0
2021	PO4020786105	LGE	3	45 ACE	SP	CCA			V		00:00.0
2021	PO5426637004	KU	1	60 BRO	SP	CCA			B		00:00.0
2021	PO5427536902	KU	2	50 BRO	SP	CCA			V		00:00.0
2021	PO5482235944	KU	4	40 UNK	SP	CRE		ID	BD		00:00.0
2021	PO4021286177	LGE	4	35 ACE	SP	P		ED,ID	TD		00:00.0
2021	PO5513435784	KU	3	45 BRO	SP	CRE		ID	BD		00:00.0
2021	PO5545536063	KU	5	35 ACW	SP	CRE		ID	BD		00:00.0
2021	PO5545936193	KU	5	35 ACW	SP	CRE		ID	BD		00:00.0
2021	PO4098385994	F	4	30 BRO	SP	CRE			V		00:00.0
2021	PO4098685994	F	4	40 BRO	SP	CRE			V		00:00.0
2021	PO4098886010	F	4	40 BRO	SP	CRE			V		00:00.0

2021 PO4098886023	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4098986036	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5546836267	KU	5	35 ACW	SP	CRE	ID	TD	00:00.0
2021 PO4098986049	F	5	45 BRO	SP	A		V	00:00.0
2021 PO4099086062	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4099186074	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4099286087	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4100686085	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO5547136322	KU	5	35 ACW	SP	CRE	ID	TD	00:00.0
2021 PO4022386171	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4099386100	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4023886175	LGE	4	30 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4023986171	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO5547336387	KU	5	35 ACW	SP	CRE	ID	TD	00:00.0
2021 PO4023386165	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4024486161	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4026386158	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4024886157	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4024286139	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4023486131	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4099486113	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4099586127	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4099686140	F	4	40 BRO	DF	CRE		V	00:00.0
2021 PO4099186153	F	4	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4099786153	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4099886166	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5545235952	KU	5	35 ACW	SP	CRE	ID	TD	00:00.0
2021 PO4099986178	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4099986192	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4104086293	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4103086307	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4033286279	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4022586122	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4021686114	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4019786095	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4030886283	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4037186306	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO7593774825	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO7515774788	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO7521474755	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO7527074721	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO7532174690	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7537274739	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4034686334	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7461174884	LGE	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7537474847	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4103486300	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4103886294	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4103086308	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4103386307	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4102386306	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4102186316	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4104186315	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7542974815	LGE	3	45 ACE	SP	CCA		V	00:00.0

2021 PO7549474782	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO7553674748	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO7552574915	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4031486320	LGE	UNK	70 ACE	SP	CRE		V	00:00.0	
2021 PO4032886316	LGE	UNK	70 ACE	SP	CRE		V	00:00.0	
2021 PO4034186317	LGE	UNK	70 ACE	SP	CRE		V	00:00.0	
2021 PO5550535932	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO4034786316	LGE	5	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4036586310	LGE	UNK	70 ACE	AL	CCA		V	00:00.0	
2021 PO4038686305	LGE	UNK	70 ACE	SP	CCA		V	00:00.0	
2021 PO4040286300	LGE	UNK	75 ACE	SP	A		V	00:00.0	
2021 PO4041886292	LGE	UNK	80 ACE	SP	A		V	00:00.0	
2021 PO4042986285	LGE	UNK	85 ACE	SP	A		V	00:00.0	
2021 PO5548935933	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO5545035782	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4104986292	LGE	4	35 BRO	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO4107486284	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4107086295	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4106086291	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4104386284	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO4018386091	LGE	4	30 ACE	SP	P	ED,ID,IP	TD	00:00.0	
2021 PO4018386084	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4017986079	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO7317672465	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4017686084	LGE	4	30 ACE	SP	CRE		V	00:00.0	
2021 PO4015586092	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4016486086	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5548435733	KU	3	45 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO4016486078	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4016386071	LGE	4	35 ACE	SP	P	ED,EP,ID,RB	TX	RR	00:00.0
2021 PO4016986070	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4014786057	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4015786058	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO7283573888	LGE	4	30 ACE	SP	P	ED,EP,ID,MD,RB	VX	PX	00:00.0
2021 PO4014386235	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4013686236	LGE	4	35 ACE	SP	P	ED,HH,ID	BD	00:00.0	
2021 PO7264974029	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO7271174031	LGE	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO7266574097	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO4012986243	LGE	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO7522374195	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO7235074117	LGE	6	30 ACE	SP	CCA		V	00:00.0	
2021 PO4011686249	LGE	2	45 ACE	SP	CCA		V	00:00.0	
2021 PO4010486242	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO9176914435	KU	6	35 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9157614944	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9165914728	KU	4	40 ACW	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9171213723	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO9139713390	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO3957686508	F	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO3958286514	F	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO3958386501	F	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO3959586487	F	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO3959686481	F	4	40 ACE	SP	A		V	00:00.0	



2021 PO3960786476	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3960886495	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3960686497	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3961886509	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4171686017	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4175885835	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4176085871	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4176285894	F	4	35 BRO	SP	A		V	00:00.0
2021 PO3695534601	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3872438645	KU	4	45 UNK	SP	CRE		VX	RP1 00:00.0
2021 PO3727034515	F	3	50 KOP	SP	P		V	00:00.0
2021 PO3715134186	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4649875077	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO6111712651B	KU	5	30 ACW	SP	S		V	00:00.0
2021 PO6111712651A	KU	5	30 ACW	SP	S		V	00:00.0
2021 PO6107112716	KU	5	35 ACW	SP	S		V	00:00.0
2021 PO6142512678	KU	3	55 ACW	SP	CRE		V	00:00.0
2021 PO6111712651	KU	1	70 ACW	SP	CRE		V	00:00.0
2021 PO6161912701	KU	3	55 ACW	SP	CRE		V	00:00.0
2021 PO4675876787	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4713776654	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4652576620	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4635376540	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4178385979	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4178485986	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4178485992	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4042538016	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO6972514590	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6983014438	KU	2	60 ACW	SP	CRE		V	00:00.0
2021 PO6967514222	F	4	40 ACW	SP	CRE		V	00:00.0
2021 PO6965614363	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6974213621	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO4621276229	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO6165712706	KU	6	30 ACW	SP	CRE		V	00:00.0
2021 PO6195212716	KU	2	65 ACW	SP	S		V	00:00.0
2021 PO8136815752	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO8143815470	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO8112715846	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO8112715622	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO4066684546	F	1	50 UNK	SP	CCA		V	00:00.0
2021 PO4066384549	F	4	30 UNK	SP	CCA		V	00:00.0
2021 PO4132884597	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4132784603	LGE	4	30 ACE	SP	P		V	00:00.0
2021 PO8063215641	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO8061315850	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO7473814930	KU	4	45 ACW	SP	S		V	00:00.0
2021 PO8062015402	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO8062015162	KU	3	45 ACW	SP	S		V	00:00.0
2021 PO4072384480	LGE	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4072884488	LGE	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4073984488	F	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4074984449	LGE	2	45 UNK	SP	CRE	HH,ID	BX	RP2 00:00.0
2021 PO4641375074	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4629375072	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0

2021 PO4639375585	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4662175477	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4623475662	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7469515259	KU	2	60 ACW	SP	P		V	00:00.0
2021 PO7470715173	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO7456715329	KU	5	35 ACW	SP	S		V	00:00.0
2021 PO4075584470	LGE	4	30 UNK	SP	A		V	00:00.0
2021 PO4075484476	F	4	40 UNK	SP	CRE	HH,ID	VX	RP2 00:00.0
2021 PO6877114100	F	7	35 ACW	DF	CRE		V	00:00.0
2021 PO6870214448	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6862013756	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO4081084538	F	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4083884565	LGE	4	30 UNK	SP	CRE		V	00:00.0
2021 PO4083284569	LGE	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4084384569	LGE	4	30 UNK	SP	CRE	ID,SRS	TD	00:00.0
2021 PO4085984571	LGE	4	35 UNK	SP	A	ID	TD	00:00.0
2021 PO4142084696	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4141884687	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4646176436	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4623076460	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4142484707	LGE	1	45 ACE	SP	CRE		V	00:00.0
2021 PO4133884361	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO466477532	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4668376867	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7344215292	KU	3	60 ACW	SP	CRE		V	00:00.0
2021 PO7375915277	KU	5	35 ACW	SP	S		V	00:00.0
2021 PO7376715478	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7376915621	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO7292615558	KU	5	35 ACW	SP	CRE	ED,ID	BD	00:00.0
2021 PO7329415605	KU	5	35 ACW	SP	S		V	00:00.0
2021 PO7367215283	KU	2	65 ACW	SP	CRE		V	00:00.0
2021 PO6994014216	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO4139284652	LGE	2	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4136584619	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4143684887	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4077584452	LGE	4	30 UNK	SP	A		V	00:00.0
2021 PO4077884458	F	4	40 UNK	SP	A		V	00:00.0
2021 PO4079684446	LGE	3	40 UNK	SP	CCA		V	00:00.0
2021 PO4079984441	LGE	4	40 UNK	SP	A		V	00:00.0
2021 PO4080984439	LGE	5	30 UNK	SP	A		V	00:00.0
2021 PO4080584435	LGE	3	45 UNK	SP	A		V	00:00.0
2021 PO4079384429	LGE	3	45 UNK	SP	A		V	00:00.0
2021 PO4178285955	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4178285948	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4178185942	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4178085927	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4179385940	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3928538557	KU	4	40 INP	SP	CRE	ID	BD	00:00.0
2021 PO3934938518	KU	4	40 INP	SP	CRE	ID	BD	00:00.0
2021 PO4001938322	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4667477196	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4689777191	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4072384494	LGE	4	30 UNK	SP	CCA		V	00:00.0
2021 PO4072684498	F	3	45 UNK	SP	CCA		V	00:00.0

2021 PO4071684506	F	3	45 UNK	SP	CCA		V	00:00.0
2021 PO7867486846	LGE	4	35 UNK	SP	CCA		V	00:00.0
2021 PO4070184511	LGE	5	35 UNK	SP	CRE		V	00:00.0
2021 PO4070784514	F	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4069484524	F	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4068584530	F	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4067784537	F	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4179285967	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4131684559	LGE	3	55 ACE	SP	CCA		V	00:00.0
2021 PO4140584670	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4141184678	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4003537886	KU	4	40 BRO	SP	S		B	00:00.0
2021 PO4014537776	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO4033537892	KU	4	45 BRO	SP	CCA		B	00:00.0
2021 PO4178785978	LGE	6	25 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4178285968	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4079984494	LGE	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4078584474	LGE	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4176485932	F	4	35 BRO	DF	CCA		V	00:00.0
2021 PO4176385925	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4176385919	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4178036863	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO6711312691	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO6693312683	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO6734913993	KU	5	35 ACW	SP	CRE	ED,ID	BD	00:00.0
2021 PO6748313374	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6756512847	KU	3	45 ACW	SP	S		V	00:00.0
2021 PO6756412725	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO6738812711	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO6564513359	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6588813398	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO6594513142	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO8536216315	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO6971213933	KU	3	45 ACW	SP	S		V	00:00.0
2021 PO4159836551	KU	4	40 UNK	SP	CCA		B	00:00.0
2021 PO4176736781	KU	4	45 UNK	SP	CCA		B	00:00.0
2021 PO4137784704	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4150437123	KU	5	35 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4136484679	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4133084683a	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4134984708	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4135384711	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4144737274	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4125837344	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4080937739	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4132684616	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4133684608	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4138484633	KU	6	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4140084630	LGE	6	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4140484637	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4140684636	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4076584467	F	3	40 UNK	SP	CCA		V	00:00.0
2021 PO4077384477	LGE	4	40 UNK	SP	A		V	00:00.0
2021 PO4076584460	LGE	4	40 UNK	SP	A		V	00:00.0

2021 PO7916156259	LGE	4	35 UNK	SP	CCA		V	00:00.0	
2021 PO4076184442	LGE	4	35 UNK	SP	CCA	ID	TD	00:00.0	
2021 PO7475515166	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7393515265	KU	2	65 ACW	SP	CRE		V	00:00.0	
2021 PO7422515254	KU	2	65 ACW	SP	S		V	00:00.0	
2021 PO4137984636	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO3735434079	KU	3	60 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO3917138560	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO4170286041	LGE	3	55 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4169286042	LGE	1	100 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4171286041	LGE	2	55 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4171986041	LGE	2	55 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4172886040	LGE	2	100 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4177885912	F	4	35 BRO	SP	A		V	00:00.0	
2021 PO4177985913	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TD	00:00.0	
2021 PO4138884648	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4622275855	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4638775993	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4078584452	F	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO4142184708	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4139984708	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4137384710	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4178586001	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4178686013	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4178686018	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4188936067	KU	4	45 BRO	SP	CRE	ID	TD	00:00.0	
2021 PO4162135334	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO4258836548	KU	4	45 BRO	SP	CCA		B	00:00.0	
2021 PO4599176370	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4572976275	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4558776147	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4551675969	KU	4	40 BRN	SP	CRE	ED,EP,ID	TX	RR	00:00.0
2021 PO4446575690	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4433675410	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4405175125	KU	4	45 BRN	SP	CCA		V	00:00.0	
2021 PO4176986017	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4244836606	KU	5	40 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO4213236719	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO4176885987	F	4	30 BRO	SP	CRE		V	00:00.0	
2021 PO4176785984	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4176885973	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4177185968	LGE	4	40 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO4175885967	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4176785968	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4176685953	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4176585945	F	4	35 BRO	SP	A		V	00:00.0	
2021 PO4081184508	LGE	4	40 UNK	SP	A		V	00:00.0	
2021 PO4080984508	LGE	4	40 UNK	SP	A		V	00:00.0	
2021 PO4079684518	LGE	5	40 UNK	SP	A		V	00:00.0	
2021 PO4080384528	LGE	5	35 UNK	SP	A	HH,ID	VX	RP3	00:00.0
2021 PO4081684548	LGE	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO4082484557	LGE	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO4068384573	LGE	4	30 UNK	SP	A		V	00:00.0	
2021 PO4981474842	KU	6	30 BRN	SP	CCA		V	00:00.0	

2021 PO4181585900	LGE	4	30 BRO	SP	CCA			V	00:00.0
2021 PO7554512683	KU	4	40 ACW	SP	CRE	ED,ID		TD	00:00.0
2021 PO7547712421	KU	4	40 ACW	SP	CRE	ED,ID		TD	00:00.0
2021 PO7542713287	KU	4	40 ACW	SP	CRE	ED,ID		TD	00:00.0
2021 PO3608033899	KU	4	40 BRO	SP	S			B	00:00.0
2021 PO4986375041	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021 PO4944374905	KU	4	45 BRN	SP	CRE	ID		TD	00:00.0
2021 PO4936275154	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021 PO3602133719	KU	4	40 BRO	SP	S			B	00:00.0
2021 PO3587433914	KU	3	45 BRO	SP	CCA			V	00:00.0
2021 PO3578633804	KU	3	45 BRO	SP	CCA			V	00:00.0
2021 PO3583734459	KU	3	55 BRO	SP	CRE	ID		TD	00:00.0
2021 PO4084885220	F	3	45 ACE	SP	CCA			V	00:00.0
2021 PO4085485231	F	4	40 ACE	SP	CRE			V	00:00.0
2021 PO4903874807	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021 PO4717274702	KU	6	30 BRN	SP	CRE	ID		TD	00:00.0
2021 PO7357813450	KU	4	40 ACW	SP	CRE	ED,ID		TD	00:00.0
2021 PO7544013588	KU	4	45 ACW	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO7578113771	KU	4	40 ACW	SP	CRE	ED,ID		BD	00:00.0
2021 PO7548314438	KU	4	45 ACW	SP	CRE	ED,HH,ID,MD,RB		X PX	00:00.0
2021 PO4141884469	LGE	4	35 ACE	SP	P	ED,ID		TD	00:00.0
2021 PO3595834179	KU	4	40 BRO	SP	CCA			B	00:00.0
2021 PO4141284474	LGE	4	40 ACE	SP	P	ED,ID		TD	00:00.0
2021 PO7545113816	KU	3	50 ACW	SP	CRE	ED,ID,IP		BD	00:00.0
2021 PO3605934527	KU	4	40 BRO	SP	CCA			B	00:00.0
2021 PO3636534724	KU	6	30 BRO	SP	CRE	ID		BD	00:00.0
2021 PO4053384955	LGE	2	45 UNK	SP	CRE	ID,IP		TD	00:00.0
2021 PO4140384453	F	3	45 ACE	SP	CCA			V	00:00.0
2021 PO4139584455	F	4	30 ACE	SP	P	ED,ID		V	00:00.0
2021 PO4139284439	F	4	45 ACE	SP	P			V	00:00.0
2021 PO4137184546a	KU	7	25 ACE	SP	P	ED,ID		BD	00:00.0
2021 PO4181985900	LGE	4	40 BRO	SP	A	ED,ID,IP		TD	00:00.0
2021 PO4181585894	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO4703174960	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021 PO4182085909	F	4	40 BRO	SP	A			V	00:00.0
2021 PO4181985893	LGE	4	40 BRO	SP	A	ED,ID		TD	00:00.0
2021 PO7533914141	KU	6	30 ACW	SP	CRE	ED,ID		TD	00:00.0
2021 PO3552634310	KU	4	40 BRO	SP	S			B	00:00.0
2021 PO4054684983	LGE	1	50 UNK	SP	CCA			V	00:00.0
2021 PO4053984967	LGE	2	45 UNK	SP	CRE	ID		TD	00:00.0
2021 PO4133984548	LGE	3	50 ACE	SP	P	ED,EP,HH,ID,RB		BX RP1	00:00.0
2021 PO2607717149	KU	2	55 BRN	SP	CCA			V	00:00.0
2021 PO2604316814	KU	2	55 BRN	SP	CCA			V	00:00.0
2021 PO2282715010	KU	5	35 BRN	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO2233114803	KU	5	35 BRN	WC	CRE			V	00:00.0
2021 PO2248215217	KU	4	40 BRN	SP	CCA			V	00:00.0
2021 PO4120186069	LGE	4	40 ACE	SP	P	ED,ID,IP		TD	00:00.0
2021 PO9427977324	KU	4	45 BRN	SP	CRE	ED,ID		TD	00:00.0
2021 PO9411476692	KU	4	40 BRO	SP	CRE	ED,ID		BD	00:00.0
2021 PO9407176528	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO4670898379	KU	3	40 UNK	SP	P	ID		BD	00:00.0
2021 PO5256405321	F	3	45 BRN	SP	CRE			V	00:00.0
2021 PO1401449635	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO5269605295	F	3	40 BRN	SP	CRE			V	00:00.0

2021	PO5277705221	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO1179152796	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4661497813	KU	4	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO5277605022	F	3	40 BRN	SP	CRE		V		00:00.0
2021	PO5267205067	F	5	40 BRN	SP	CRE		V		00:00.0
2021	PO9380875063	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO9372175076	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO1218152535	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO1205152624	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO1192152719	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO1169252931	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO1165152970	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO1157353092	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO1197152961	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO1147953269	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO1169353009	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD		00:00.0
2021	PO4152185535	LGE	2	55 BRN	SP	CRE	ID,IP	BD		00:00.0
2021	PO4150285526	LGE	3	45 BRN	SP	P	ID,IP	BD		00:00.0
2021	PO4150385526	LGE	4	35 BRN	SP	CRE		V		00:00.0
2021	PO4150185527	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4150185527-A	KU	4	35E BRN	SP	CCA		V		00:00.0
2021	PO4148085543	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4913904744	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4885804802	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO4180986559	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4180286561	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO1133753488	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO1137953527	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO1139453458	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD		00:00.0
2021	PO4653797648	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO4647397574	KU	5	30 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO4717697508	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO4112886080	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO9378474923	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO1140653584	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4861902265	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4853802312	KU	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO4110686138	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4142585586	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4142785594	F	5	35 BRN	SP	CRE		V		00:00.0
2021	PO4105286204	LGE	1	60 ACE	SP	CCA		V		00:00.0
2021	PO9351274821	KU	4	45 BRO	SP	CRE	ED,ID	BX	RP2	00:00.0
2021	PO4140785591	F	3	45 BRN	SP	CCA		V		00:00.0
2021	PO8555567763	KU	4	35 BRN	SP	CCA		V		00:00.0
2021	PO8880777055	LGE	1	80 BRO	ST	P		V		00:00.0
2021	PO2076734311	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021	PO2105234177	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021	PO2141633765	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021	PO2125033953	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO5258499165	KU	7	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO1821044769	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4137185280	LGE	4	40 BRN	SP	CRE	ID,IP,SRS	TD		00:00.0
2021	PO5253905077	KU	6	35 BRN	SP	CRE	ED	B		00:00.0
2021	PO4889105905	KU	6	30 XXX	SP	CRE	ED,ID	TX	RR	00:00.0

2021 PO1905244057	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1883344302	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1883645056	KU	5	30 BRO	SP	CRE		V	00:00.0
2021 PO1878945022	KU	5	30 BRO	SP	CCA		V	00:00.0
2021 PO4175186400	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4106586213	LGE	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4106486204	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4138885658	LGE	2	55 BRN	SP	P	ID,RB	TX RR	00:00.0
2021 PO8532568389	LGE	1	55 BRN	SP	CCA		V	00:00.0
2021 PO4139985643	LGE	4	30 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO5246105432	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5242405331	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5251805342	F	4	45E BRN	SP	CRE		V	00:00.0
2021 PO5252205256	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4181986400	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5271905248	F	6	40E BRN	SP	CRE		V	00:00.0
2021 PO1911544698	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5244805198	F	4	45 BRN	SP	CRE		V	00:00.0
2021 PO5289305637	F	7	40 BRN	SP	CRE		V	00:00.0
2021 PO4124485208	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4126285210	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4130485208	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4131885208	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5474604671	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5259904752	KU	7	30 BRN	SP	CCA	ED	TD	00:00.0
2021 PO4135385177	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4134585177	LGE	4	35 BRN	SP	P	ID,IP,MD	TD	00:00.0
2021 PO4104686218	LGE	1	25 ACE	SP	CRE		V	00:00.0
2021 PO4134685187	LGE	4	35 BRN	SP	P	ID	TD	00:00.0
2021 PO0848357820	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4105686218	LGE	1	25 ACE	SP	A		V	00:00.0
2021 PO1851444965	KU	4	45 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO1847044958	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4173486429	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4174586411	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4176386437	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4134685200	LGE	4	35 BRN	SP	P	ED,ID,IP,MD	TD	00:00.0
2021 PO4105486220	LGE	1	65 ACE	SP	CCA		V	00:00.0
2021 PO4129085210	LGE	4	35 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO5259604499	KU	5	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5245504388	KU	7	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4662297550	KU	6	30 UNK	SP	CRE		V	00:00.0
2021 PO1860644369	KU	4	45 BRO	SP	CRE	ED,EP,ID	TD	00:00.0
2021 PO4123486049	LGE	1	80 ACE	SP	CCA		V	00:00.0
2021 PO4175986446	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO1832144854	KU	4	45 BRN	SP	CRE	ED,EP,ID,MD	BX PX	00:00.0
2021 PO1827444891	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3269007747	F	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4127685210	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4132185203	LGE	4	30 BRN	SP	P	ID	BD	00:00.0
2021 PO4133285207	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4134685207	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4136185206	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3253507743	F	3	40 BRN	SP	CCA		V	00:00.0

2021 PO3261007932	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO3260807798	KU	4	40 BRN	SP	S		V			00:00.0
2021 PO3253807796	KU	6	30 BRN	SP	CCA		V			00:00.0
2021 PO0863457921	KU	4	40 BRN	SP	CRE	ED,EP	TD			00:00.0
2021 PO4123786073	F	3	45 ACE	SP	CCA		V			00:00.0
2021 PO4123686070	F	4	35 ACE	SP	CRE	ED,ID	V			00:00.0
2021 PO3066807847	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO3189507773	F	4	45 BRN	SP	CCA		V			00:00.0
2021 PO3198709909	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO3209407764	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO3206307501	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO5287704489	KU	5	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021 PO5276404511	KU	7	35 BRN	SP	CRE	ED	B			00:00.0
2021 PO4137585206	LGE	3	45 BRN	SP	CCA		V			00:00.0
2021 PO4137985202	LGE	4	40 BRN	SP	CCA		V			00:00.0
2021 PO4138985205	LGE	3	45 BRN	SP	CCA		V			00:00.0
2021 PO4140285204	LGE	3	45 BRN	SP	CCA		V			00:00.0
2021 PO4141685204	LGE	3	45 BRN	SP	CCA		V			00:00.0
2021 PO1908243704	KU	6	30 BRO	SP	CRE	ED,ID	X	RP1		00:00.0
2021 PO1841944753	KU	4	40 BRN	SP	CRE	ED,HH,ID	BX	RP3		00:00.0
2021 PO4109486213	LGE	4	30 ACE	SP	P	ED,ID,IP	TD			00:00.0
2021 PO4134485773	LGE	4	40 BRN	SP	CCA		V			00:00.0
2021 PO4134285761	LGE	4	40 BRN	SP	CCA		V			00:00.0
2021 PO0805657622	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4134185749	LGE	4	40 BRN	SP	P	ID	BD			00:00.0
2021 PO1923443525	KU	4	40 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO1931443422	KU	5	30 BRO	SP	CRE	ID,SRC	BD			00:00.0
2021 PO1852344631	KU	4	40 BRN	SP	CRE	ID	TD			00:00.0
2021 PO1869944444	KU	4	40 BRN	SP	CRE	HH,ID	TD			00:00.0
2021 PO8488469247	LGE	4	40 BRN	SP	P	ID	BD			00:00.0
2021 PO4109286202	LGE	4	40 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4109486197	LGE	6	30 ACE	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4893005335	KU	6	30 XXX	SP	CRE	ED,ID	TD			00:00.0
2021 PO4176586425	LGE	4	40 BRO	SP	A	ED,ID,IP	TD			00:00.0
2021 PO4134885302	LGE	4	40 BRN	SP	P	ID	TD			00:00.0
2021 PO1861644537	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO1874944484	KU	4	45 BRN	SP	CRE	ID	TD			00:00.0
2021 PO1916843824	KU	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO1893744193	KU	5	35 BRO	SP	CRE	ED,ID,MD,SRC	TD			00:00.0
2021 PO4127785288	LGE	4	35 BRN	SP	CRE	ID,IP	BD			00:00.0
2021 PO4918505361	F	6	30 XXX	SP	CRE	ED,ID	TD			00:00.0
2021 PO5281299647	F	6	35 BRN	SP	CCA		V			00:00.0
2021 PO4128985286	LGE	4	35 BRN	SP	P	ID,IP	TD			00:00.0
2021 PO4129985286	LGE	3	45 BRN	SP	CCA		V			00:00.0
2021 PO1876644372	KU	4	40 BRO	SP	CRE	ED,ID,MD	TD			00:00.0
2021 PO5266499354	KU	5	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021 PO5267699586	KU	3	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021 PO4177086418	LGE	4	30 BRO	SP	A	ED,ID	TD			00:00.0
2021 PO1877244153	KU	6	30 BRO	SP	CRE	ED,ID,MD	TD			00:00.0
2021 PO4131085281	LGE	4	35 BRN	SP	P		T			00:00.0
2021 PO4882505507	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO4872705507	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO4891805509	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO41310	KU	4	40 BRN	SP	CCA		V			00:00.0



2021 PO4132885279	LGE	6	25 BRN	SP	CRE	ID,IP	TD		00:00.0
2021 PO4131985282	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4132985282	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4134685285	LGE	4	40 BRN	SP	P	ID	BD		00:00.0
2021 PO4134685281	LGE	4	40 BRN	SP	P	ED,ID	TD		00:00.0
2021 2017633969aq	KU	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO2017633969	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO5250799331	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4883505713	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4176686410	LGE	4	35 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4176886406	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4176186404	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO1823243986	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1835544095	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4107486199	LGE	6	30 ACE	SP	CRE	ED,EP,ID	TD		00:00.0
2021 PO4107386204	LGE	4	40 ACE	SP	CRE	ED,EP,ID	TD		00:00.0
2021 PO1840544210	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO1864344317	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1812744603	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO2032834472	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO2051734427	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO2062834489	KU	6	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4106586199	LGE	6	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4174786396	LGE	5	25 BRO	SP	CRE		V		00:00.0
2021 PO4174886396	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4139085280	LGE	4	45 BRN	SP	CRE	ID,IP	TD		00:00.0
2021 PO3188508915	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3194209466	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3181408309	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3183908443	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO1910144942	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO1857545037	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO1871644968	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4175486395	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO5253505168	KU	7	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4140785279	LGE	4	40 BRN	SP	P	ID	TD		00:00.0
2021 PO4872305399	F	4	40 XXX	SP	CRE	ED,ID	BX	RP1	00:00.0
2021 PO4865605364	KU	6	30 BRN	SP	S		V		00:00.0
2021 PO4884605248	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4876405280	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5260905300	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4119486058	LGE	4	35 ACE	SP	P	ED,ID,RB	X	PX	00:00.0
2021 PO4119286053	LGE	4	35 ACE	SP	P	ED,HH,ID,RB	X	RP1	00:00.0
2021 PO4117486090	LGE	2	60 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4116386097	LGE	2	60 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4116086097	LGE	4	35 ACE	SP	P	ED,ID,IP	TD		00:00.0
2021 PV8510868204	LGE	4	35 BRN	SP	P	ED,ID,SRC	TX	RR	00:00.0
2021 PO4181486409	LGE	3	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4181886401	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO1412249294	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4705997775	KU	4	40 UNK	SP	CRE	ID,IP	BD		00:00.0
2021 PO4708198162	KU	4	40 UNK	SP	CRE	ID,IP,SRS	TD		00:00.0
2021 PO4677198137	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO1420749356	KU	4	40 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	TX	RR	00:00.0

2021 PO4951504751	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5253905077b	KU	5	35 BRN	SP	CCA	ED	TD	00:00.0
2021 PO5267205067a	KU	6	35 BRN	SP	CCA		V	00:00.0
2021 PO4138985638	LGE	3	50 BRN	SP	P	ED,HH,ID	X RP2	00:00.0
2021 PO4138485625	LGE	4	35 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO9398576159	KU	4	45 BRO	SP	CRE		V	00:00.0
2021 PO9390575866	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9380975430	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9404375368	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4948704640	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4967404522	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4138985617	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4138985619	LGE	3	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4147285553	LGE	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4179386567	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO1173052861	F	5	30 BRO	SP	CCA		V	00:00.0
2021 PO9481274655	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO9537874593	KU	4	45 BRO	SP	S		V	00:00.0
2021 PO9509474619	KU	4	45 BRO	SP	CRE		V	00:00.0
2021 PO9453274698	KU	4	45 BRO	SP	CRE		V	00:00.0
2021 PO9214873356	KU	5	30 BRO	SP	CRE		V	00:00.0
2021 PO9423474739	KU	4	45 BRO	SP	CRE		V	00:00.0
2021 PO9422374663	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4112986083	LGE	5	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4080886617	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4082386614	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5356631041	KU	2	45 BRN	SP	CCA		V	00:00.0
2021 PO5346431123	KU	3	50 BRN	SP	CCA		V	00:00.0
2021 PO5334630833	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5575609775	KU	4	45 KOP	SP	S		V	00:00.0
2021 PO5593409908	KU	4	40 KOP	SP	S		V	00:00.0
2021 PO4145785990	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5022225998	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3990285639	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3989685646	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3990085651	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3997985575	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3964985683	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO3963985689	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3963085695	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3962285700	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3961685711	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3961385706	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3960585711	F	4	40 ACE	SP	A		V	00:00.0
2021 PO6719468819	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3959685716	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3957585729	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3955885739	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5443013068	KU	3	40 BRN	SP	CCA		V	00:00.0
2021 PO4083386599	F	4	45 ACE	SP	A		V	00:00.0
2021 PO3998385580	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO3999085574	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3996985584	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4083086594	F	4	40 ACE	SP	CRE		V	00:00.0

2021 PO3995985592	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4082386581	F	UNK		45 ACE	SP	CRE		V	00:00.0
2021 PO4081386565	F	UNK		45 ACE	SP	CRE		V	00:00.0
2021 PO3994985600	F		4	40 ACE	SP	CCA		V	00:00.0
2021 PO4082186555	F		4	30 ACE	SP	CRE		V	00:00.0
2021 PO4081186556	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4080786542	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4080386529	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4080386521	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4081086515	F		3	45 ACE	SP	CCA		V	00:00.0
2021 PO4979226121	KU		5	30 BRN	SP	CRE		B	00:00.0
2021 PO4988826142	KU		4	40 BRN	SP	CCA		V	00:00.0
2021 PO5001126169	KU		4	40 BRN	SP	CCA		V	00:00.0
2021 PO4075485957	F		4	40 BRO	SP	CRE		V	00:00.0
2021 PO4077485970	F		3	45 BRO	SP	CCA		V	00:00.0
2021 PO4076685962	F		4	40 BRO	SP	CRE		V	00:00.0
2021 PO4082386513	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4083886513	F		3	45 ACE	SP	CCA		V	00:00.0
2021 PO3966685674	F		4	45 ACE	SP	CRE		V	00:00.0
2021 PO3965585680	F		1	50 ACE	SP	CCA		V	00:00.0
2021 PO3956885735	LGE		4	35 ACE	SP	CCA		V	00:00.0
2021 PO3954885745	F		3	45 ACE	SP	CCA		V	00:00.0
2021 PO4083486608	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4084686602	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4085486597	F		3	45 ACE	SP	CCA		V	00:00.0
2021 PO4143385961	LGE		3	45 BRO	SP	CCA		V	00:00.0
2021 PO3983985655	LGE		3	50 ACE	SP	CCA		V	00:00.0
2021 PO3985085643	F		4	40 ACE	SP	CCA		V	00:00.0
2021 PO3988085619	F		3	45 ACE	SP	CCA		V	00:00.0
2021 PO3989085611	LGE		4	40 ACE	SP	CRE		V	00:00.0
2021 PO3989985603	LGE		4	40 ACE	SP	CCA		V	00:00.0
2021 PO3990885596	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO3990485591	F		4	30 ACE	SP	CCA		V	00:00.0
2021 PO3991785587	F		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4016185607	LGE		4	40 KOP	SP	CCA		V	00:00.0
2021 PO5068627038	KU		6	30 BRN	SP	CCA		V	00:00.0
2021 PO5072626894	KU		4	40 BRN	SP	CRE		B	00:00.0
2021 PO5079426908	F		4	40 BRN	SP	CCA		V	00:00.0
2021 PO3991485583	F		4	30 ACE	SP	CCA		V	00:00.0
2021 PO3985685622	LGE	UNK		25 ACE	SP	CCA		V	00:00.0
2021 PO4015985602	LGE		4	30 KOP	SP	CCA		V	00:00.0
2021 PO4013485604	LGE		4	30 KOP	SP	CCA		V	00:00.0
2021 PO4014685603	LGE		4	30 KOP	SP	CCA	ED	V	00:00.0
2021 PO3986285617	LGE		4	40 ACE	SP	CRE		V	00:00.0
2021 PO4062885949	F		4	40 BRO	SP	CCA		V	00:00.0
2021 PO4062985962	F		3	45 BRO	SP	CCA		V	00:00.0
2021 PO4061685970	F		3	45 BRO	SP	CCA		V	00:00.0
2021 PO4063085979	F		3	45 BRO	SP	P		V	00:00.0
2021 PO4062985969	F		3	45 BRO	SP	CRE		V	00:00.0
2021 PO4064285967	F		3	45 BRO	SP	CCA		V	00:00.0
2021 PO4065585966	F		4	40 BRO	SP	CRE		V	00:00.0
2021 PO4066985965	F		3	45 BRO	SP	CCA		V	00:00.0
2021 PO4068385964	F		3	45 BRO	SP	CCA		V	00:00.0
2021 PO4069385963	F		3	45 BRO	SP	CCA		V	00:00.0

2021 PO4071085962	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4072485961	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4073785960	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3990485992	LGE	2	70 ACE	SP	CRE		V	00:00.0
2021 PO3985585608	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4028486548	LGE	UNK	25 ACE	SP	CRE		V	00:00.0
2021 PO4028086534	LGE	4	40 ACE	SP	CCA	ED,ID	V	00:00.0
2021 PO5504510225	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO3989085976	LGE	2	55 ACE	SP	CRE		V	00:00.0
2021 PO3984885612	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3985585596	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3985985583	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3987385571	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3986585568	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4064285895	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4066185954	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4066085940	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4068785934	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4068985923	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4067885920	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4065885925	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4065885911	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4065885903	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4065685895	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4065585891	F	3	45 BRO	SP	P		V	00:00.0
2021 PO4011885605	LGE	6	25 KOP	SP	P	ED	V	00:00.0
2021 PO3975386211	LGE	4	35 ACE	SP	P		V	00:00.0
2021 PO4066185875	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4066085864	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4065985852	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4065885839	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4065685825	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4065585813	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4015785658	LGE	4	40 KOP	SP	CCA		V	00:00.0
2021 PO4014485637	LGE	4	40 KOP	SP	CCA		V	00:00.0
2021 PO4063185807	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4064485807	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4065185806	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4066485805	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4067985803	F	4	40 BRO	SP	P		V	00:00.0
2021 PO3981086715	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3983786699	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3986586682	LGE	4	45 ACE	SP	CRE		V	00:00.0
2021 PO3988086672	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3989586663	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3990786655	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3992186647	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3993686637	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3994886630	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3996986617	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO3999086601	LGE	7	25 ACE	SP	CRE		V	00:00.0
2021 PO3999186604	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4000886594	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4002586583	LGE	3	50 ACE	SP	CRE		V	00:00.0

2021 PO4004086574	LGE	3	50 ACE	SP	CRE	V	00:00.0
2021 PO4005586561	LGE	7	25 ACE	SP	CRE	V	00:00.0
2021 PO4005786564	LGE	3	50 ACE	SP	CRE	V	00:00.0
2021 PO4007486554	LGE	3	50 ACE	SP	CRE	V	00:00.0
2021 PO4009186544	LGE	3	50 ACE	SP	CRE	V	00:00.0
2021 PO4011686530	LGE	4H	45 ACE	SP	CRE	V	00:00.0
2021 PO4011986527	LGE	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4012486527	LGE	4	30 ACE	SP	CRE	V	00:00.0
2021 PO4013286521	LGE	3	45 ACE	SP	CRE	V	00:00.0
2021 PO3992486410	LGE	3	50 ACE	SP	CCA	V	00:00.0
2021 PO3986786278	LGE	6	30 ACE	SP	P	V	00:00.0
2021 PO3993986371	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO3993586361	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO7063375123	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO7031275055	KU	3	45 ACE	SP	CCA	V	00:00.0
2021 PO3983486280	LGE	3	50 ACE	SP	CCA	V	00:00.0
2021 PO4899633376	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4916533446	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4915933396	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4923833381	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4940633261	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO3984586287	LGE	3	50 ACE	SP	P	V	00:00.0
2021 PO5090525964	KU	5	35 BRN	SP	CRE	B	00:00.0
2021 PO4186486213	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4187186220	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4188986236	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5085826208	KU	4	40 BRN	SP	CRE	B	00:00.0
2021 PO4951233163	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO4960433077	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4971032977	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4085286512	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4086686510	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4087486510	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4088786509	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5016326264	KU	4	40 BRN	SP	CRE	B	00:00.0
2021 PO5009626188	KU	4	40 BRN	SP	CRE	B	00:00.0
2021 PO3993685609	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO3994885623	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO3982385594	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4972232788	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4141585962	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO4091486504	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4087286529	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4083686568	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4084686563	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4083186539	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4084286543	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4086286554	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4087286549	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4088086544	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4089286539	F	4	50 ACE	SP	CCA	V	00:00.0
2021 PO4090186534	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4091386533	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4092286521	F	4	40 ACE	SP	CRE	V	00:00.0

2021 PO4089586547	F	4	45 ACE	SP	CCA	V	00:00.0
2021 PO4090686568	F	4	45 ACE	SP	CCA	V	00:00.0
2021 PO5484610092	KU	6	30 KOP	SP	CCA	V	00:00.0
2021 PO4144486000	LGE	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4983826396	KU	5	35 BRN	SP	CRE	B	00:00.0
2021 PO5006526439	KU	5	35 BRN	SP	CRE	B	00:00.0
2021 PO5012426433	KU	5	35 BRN	SP	CRE	B	00:00.0
2021 PO3982785585	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO3994685513	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4091886559	LGE	2	45 ACE	SP	CCA	V	00:00.0
2021 PO4710537428	KU	3	45 BRO	SP	CCA	B	00:00.0
2021 PO4089486508	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4144385993	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4991726567	KU	5	35 BRN	SP	CRE	B	00:00.0
2021 PO4141585981	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4141985984	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4091386548	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4093486532	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4092286533	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO3995785508	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO3992485524	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO3993585519	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO3991485530	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO3953085756	F	4	40 ACE	SP	A	V	00:00.0
2021 PO3951685764	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4092686508	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5001926887	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4092586496	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4089286486	F	UNK	25 ACE	SP	CRE	V	00:00.0
2021 PO3990385535	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO3989385540	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO3989285547	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO3988085548	LGE	3	35 ACE	SP	CCA	V	00:00.0
2021 PO3985485551	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO3986685553	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4999027025	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5374312323	KU	3	40 BRO	SP	CCA	V	00:00.0
2021 PO5462110006	KU	4	40 KOP	SP	S	V	00:00.0
2021 PO4074385761	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4074285749	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4074185738	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4073385762	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4071985762	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4070785763	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5367212009	F	3	40 BRO	SP	CCA	V	00:00.0
2021 PO5557410024	KU	3	45 KOP	SP	S	V	00:00.0
2021 PO5508510306	KU	3	45 KOP	SP	S	V	00:00.0
2021 PO5387812270	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5306231658	F	4	40 BRN	SP	A	V	00:00.0
2021 PO5099325930	F	3	45 BRN	SP	CRE	V	00:00.0
2021 PO5092326249	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4016785519	F	4	40 KOP	SP	P	V	00:00.0
2021 PO5076326671	KU	4	40 BRN	SP	CRE	B	00:00.0
2021 PO5317830893a	KU	6	35 BRN	SP	CCA	V	00:00.0

2021 PO5317830893	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5630610591	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO5612110641	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO5541210108	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO3972586202	LGE	4	45 ACE	SP	CRE		V	00:00.0
2021 PO3969785667	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3972786184	LGE	4	30 ACE	SP	CRE	ID	TD	00:00.0
2021 PO4696909104	KU	7	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4682808988	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4690308863	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4692008294	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4803101497	KU	7	35 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4992502438	KU	4	40 BRN	SP	CRE	ED,ID,IP,RB,SRC	TD	00:00.0
2021 PO4624308293	KU	5	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4635808296	KU	5	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4635408448	KU	7	30 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4685008447	KU	7	30 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4647708295	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD	TD	00:00.0
2021 PO4669508121	KU	6	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4658608295	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4704008292	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4935802588	KU	3	40 BRN	SP	CRE	ED,ID,MD	TD	00:00.0
2021 PO4864302767	KU	2	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4905102663	KU	2	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4925902611	KU	2	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4164686014	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4163886015	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4099885459	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4010285583	LGE	4	30 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4009885614	LGE	4	40 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO4093085496	LGE	1	80 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO3993585399	LGE	4	35 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO4027785466	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4160085956	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4094085494	LGE	1	70 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO3992185369	LGE	4	30 BRN	SP	P	ED,ID,IP	TD	00:00.0
2021 PO3991785359	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021 PV3992585357	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4159885923-A	LGE	5	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PV3990985344	LGE	4	35 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4106585303	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4105685305	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4105885310	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4109585312	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4161185923	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4107785306	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3991385376	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4098885442	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4096185448	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4004285557	LGE	4	30 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4010785483	LGE	5	25 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4020385519	LGE	4	30 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4160485978	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4007185601	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0

2021 PO4098285445	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4158485711	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4158385743	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4159885934	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4159885945	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4160485978-A	KU	6	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4096085481	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4094885482	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4094285476	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO3701389261	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3690889489	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3717888402	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3712688554	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3717788537	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3713688662	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3986019241	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3975020242	KU	3	55 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3752488987	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3881089638	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3890589640	KU	6	35 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3866589405	KU	3	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4002520419	KU	3	50 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3974020507	KU	3	50 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3717689068	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3710089073	KU	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3850389308	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3842089258	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3820489135	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3831489194	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4000817818	KU	4	40 ACW	SP	CRE	ID	TD		00:00.0
2021 PO3999117912	KU	4	45 CPT	SP	CRE	ID	TD		00:00.0
2021 PO4159885923	LGE	4	40 BRO	SP	CCA	ED	T		00:00.0
2021 PO3776389018	KU	6	30 BRN	SP	CCA	ED	T		00:00.0
2021 PO5034127738	F	4	40 BRN	SP	P	ID	BX	RP1	00:00.0
2021 PO5023827802	F	4	40 BRN	SP	P	ID	BX	RP1	00:00.0
2021 PO5013827866	F	4	40 BRN	SP	P	ID	BX	RP2	00:00.0
2021 PO4993627989	F	4	40 BRN	SP	P	ID	BX	RP1	00:00.0
2021 PO5149327314	F	4	40 BRN	SP	P	ID	BX	PX	00:00.0
2021 PO5122327392	F	4	40 BRN	SP	P	IP	BX	RP3	00:00.0
2021 PO5108927431	F	4	40 BRN	SP	P	ID	BX	RP3	00:00.0
2021 PO5136327352	F	4	40 BRN	SP	P	ID	BX	RP3	00:00.0
2021 PO5085827496	F	4	40 BRN	SP	P	ID	BX	RP3	00:00.0
2021 PO5199427112	F	4	40 BRN	SP	P	ED,ID	BX	RP1	00:00.0
2021 PO5173827245	F	4	40 BRN	SP	P	ED,SRC	BX	RP3	00:00.0
2021 PO5162527277	F	4	40 BRN	SP	P	ED,ID	BX	PX	00:00.0
2021 PO5044227678	F	4	40 BRN	SP	P	ID	BX	RP3	00:00.0
2021 PO4678508294	KU	3	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4101085546	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4096185457	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4006285574	LGE	4	40 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO3995385341	LGE	4	30 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO4159785970	LGE	4	30 BRO	SP	CRE	ID	BD		00:00.0
2021 PO4095085493	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4097385446	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0



2021 PO4099085444	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4007985622	LGE	3	25 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO3983985289	LGE	4	30 BRN	SP	CCA	ED,ID	BD		00:00.0
2021 PO3995785347	LGE	4	40 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO3996085353	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO3996285358	LGE	4	40 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO3996585365	LGE	4	40 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO3998685364	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO3998585371	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO3991285356	LGE	4	35 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO3991485377	LGE	4	35 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO4007785616	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO3995620822	KU	3	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO3983719491	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4031785376	LGE	4	40 BRN	SP	CRE		B		00:00.0
2021 PO4031985371	LGE	4	35 BRN	SP	CCA		B		00:00.0
2021 PO4643808565	KU	3	40 BRN	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021 PO4608008913	KU	3	40 BRN	SP	CRE	ED,ID,IP,RB	X	PX	00:00.0
2021 PO3736088005	KU	4	40 BRN	SP	CRE	ED,HH,RB	X	RP2	00:00.0
2021 PO3736387923	KU	6	30 BRN	SP	CRE	HH,ID,IP	X	RP2	00:00.0
2021 PO4081885417	LGE	4	35 ACE	AL	CCA		V		00:00.0
2021 PO4079885378	LGE	4	40 ACE	ST	CCA		V		00:00.0
2021 PO4084285401	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4083185428	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7978866197	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO7963666077	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4070285135	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4071785118	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO7906262957	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4077485424	LGE	1	30 ACE	SP	CRE		V		00:00.0
2021 PO4077185432	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4079585430	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4072285435	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4078785375	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4158285732	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4158185720	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4079585299	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4076085432	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4074785425	F	5	35 ACE	SP	CRE		V		00:00.0
2021 PO4073485434	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4159585887	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4159585876	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4077485431	F	4	40 ACE	SP	P		V		00:00.0
2021 PO7919062980	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4071885143	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7884763432	LGE	3	45 BRN	SP	CCA	ED,ID	V		00:00.0
2021 PO4078585431	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3725688028	KU	6	35 BRN	SP	CCA		V		00:00.0
2021 PO3742388068	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3605530685	KU	3	50 BRO	SP	CCA		V		00:00.0
2021 PO3599330385	KU	3	50 BRO	SP	CCA		V		00:00.0
2021 PO3728988341	F	3	50 BRN	SP	CRE		V		00:00.0
2021 PO3731988261	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3737187818	KU	4	40 BRN	SP	CCA		V		00:00.0

2021 PO3763687826	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO3755787841	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO3779687689	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO3803887659	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021 PO3800887678	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO3584129742	KU	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO3579129568	KU	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO3739888243	KU	4	45 BRN	SP	CCA		V	00:00.0	
2021 PO3661334025	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3645333823	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3631933882	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3655733953	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3576828976	F	5	35 KOP	SP	CCA		V	00:00.0	
2021 PO3574728849	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3635833704	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3619333105	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3609430899	KU	2	55 BRO	SP	CCA		V	00:00.0	
2021 PO3923422456	F	4	45 KOP	SP	P		V	00:00.0	
2021 PO3621333346	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3623333549	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4612608539	KU	3	40 BRN	SP	CRE	ED,HH,ID,RB,SRC	TX	RR	00:00.0
2021 PO4671808567	KU	3	40 BRN	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021 PO4159685900	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4074885433	LGE	4	40 ACE	SP	CRE	ED,EP,ID,IP	TX	RR	00:00.0
2021 PO4697208569	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4711008554	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4635208565	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4622308562	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4662808565	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4652808565	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4684508568	KU	5	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4627108879	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4623408837	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4631708858	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4574308910	KU	7	30 BRN	SP	CCA	ED	TD		00:00.0
2021 PO4626908975	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4584608386	KU	7	35 BRN	SP	CCA	ED	TD		00:00.0
2021 PO4574808649	KU	7	30 BRN	SP	CCA	ED	TD		00:00.0
2021 PO4545208124	KU	7	35 BRN	SP	CCA	ED	TD		00:00.0
2021 PO4547708295	KU	5	35 BRN	SP	CRE	ED	TD		00:00.0
2021 PO4561208398	KU	7	35 BRN	SP	CCA	ED	TD		00:00.0
2021 PO4068385092	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4067485080	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4066485067	LGE	4	40 BRN	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4068385104	LGE	4	30 BRN	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4080985429	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4080185423	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4159485863	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4159685863	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4070685218	LGE	4	30 BRN	SP	A	ED,ID	TD		00:00.0
2021 PO4159085862	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4070185117	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4070885129	LGE	4	35 BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO4082185426	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0

2021 PO4159785910	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4081185426	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4073985122	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4072585126	LGE	4	35 BRN	SP	CRE	ED,EP,ID	TD	00:00.0
2021 PO4077485431a	KU	6	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4159585879	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4079385464	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4079285454	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4078685454	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4077685453	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3955721176	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3960620995	KU	4	45 KOP	SP	CRE	ID	TD	00:00.0
2021 PO3967920741	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3954521292	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3951121567	KU	4	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO3941122164	KU	2	60 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3718988301	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3721288225	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3752688042	KU	3	50 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3757988098	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3765388092	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3775488128	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3786587890	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3789987872	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3751888303	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3745088302	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3746787821	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3741787835	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3782887739	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3791987652	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3745187965	KU	3	60 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3745187965a	KU	2	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3734287880	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3947421746	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO3945721877	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3761587923	KU	4	45 BRN	SP	CCA	ED	T	00:00.0
2021 PO3765788012	KU	6	30 BRN	SP	CCA	ED	T	00:00.0
2021 PO3807687971	KU	6	30 BRN	SP	CCA		T	00:00.0
2021 PO4080185416	LGE	4	40 ACE	SP	P	ED,HH,ID,RB	BX	RP1 00:00.0
2021 PO4616408836	KU	5	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4074585181	LGE	1	80 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4073485192	LGE	1	85 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4072785156	LGE	2	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4073585168	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4047185727	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4049185727	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4624112673	F	4	40 KOP	SP	P		V	00:00.0
2021 PO4609412555	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO4620512533	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO3840386665	KU	6	30 BRO	SP	P	ED,ID,SRC	TD	00:00.0
2021 PO3867386527	KU	4	45 BRO	SP	S		V	00:00.0
2021 PO3924886733	F	4	40 BRO	SP	P		V	00:00.0
2021 PO3897386315	KU	3	45 BRO	SP	S		V	00:00.0
2021 PO3926386759	F	6	30 BRO	SP	P		V	00:00.0

2021 PO3911086524	F	4	45 BRO	SP	P		V			00:00.0
2021 PO3228380147	KU	4	45 XXX	SP	CRE	ID	TD			00:00.0
2021 PO4029284124	F	5	30 ACE	SP	P		VX	PX		00:00.0
2021 PO3990384582	LGE	4	40 ACE	SP	A	ED,ID,RB	X	PX		00:00.0
2021 PO3990584588	LGE	4	30 ACE	SP	A	ED,ID	TD			00:00.0
2021 PO3212780268	KU	6	30 XXX	SP	CRE	ID	TD			00:00.0
2021 PO3205480061	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0
2021 PO8044971738	KU	5	35 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO8065773787	KU	4	45 ACE	SP	CCA		V			00:00.0
2021 PO8055773837	KU	4	45 ACE	SP	CCA		V			00:00.0
2021 PO8043773910	KU	4	40 ACE	SP	CCA		V			00:00.0
2021 PO4094784491	LGE	4	40 BRO	SP	P		B			00:00.0
2021 PO4095884486	LGE	4	35 BRO	SP	P		B			00:00.0
2021 PO4037984368	LGE	7	40 ACE	CON	CCA		V			00:00.0
2021 PO3847886798	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4041584350	LGE	UNK	85 ACE	SP	A		V			00:00.0
2021 PO3193080186	KU	4	45 XXX	SP	CRE	ID,IP	TD			00:00.0
2021 PO3204079985	KU	6	30 XXX	SP	CRE	ID	TD			00:00.0
2021 PO3196779989	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0
2021 PO4127784397	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO4128384379	LGE	4	40 BRO	SP	CCA		V			00:00.0
2021 PO4119984449	F	3	45 BRO	SP	CRE		V			00:00.0
2021 PO4040784333	LGE	UNK	95 ACE	SP	A		V			00:00.0
2021 PO3924986071	KU	4	30 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO3983083724	LGE	4	85 BRO	SP	CCA		V			00:00.0
2021 PO3984283752	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4039084296	LGE	1	85 ACE	SP	CRE		V			00:00.0
2021 PO4040084318	LGE	1	85 ACE	SP	A		V			00:00.0
2021 PO4109384384	F	4	40 BRO	UN	CRE		V			00:00.0
2021 PO9344698110	KU	6	30 XXX	SP	CRE	ID	TD			00:00.0
2021 PO9338598152	KU	4	45 XXX	SP	CRE	ED,ID,IP	TX	RR		00:00.0
2021 PO9346898196	KU	5	45 XXX	SP	CRE	ID	TD			00:00.0
2021 PO9344398269	KU	4	40 XXX	SP	CRE	ID,IP	TD			00:00.0
2021 PO3980384621	LGE	4	35 ACE	SP	P	ED,ID	TD			00:00.0
2021 PO4022984102	F	4	35 ACE	SP	A		V			00:00.0
2021 PO4023384115	F	4	55 ACE	SP	CCA		V			00:00.0
2021 PO4024184135	F	3	45 ACE	SP	A		V			00:00.0
2021 PO4024584146	F	3	45 ACE	SP	CCA		V			00:00.0
2021 PO4023784124	F	3	45 ACE	SP	CCA		V			00:00.0
2021 PO9333698482	KU	4	45 XXX	SP	CRE	ID,IP	BD			00:00.0
2021 PO9350998536	KU	4	45 XXX	SP	CRE	ID	TD			00:00.0
2021 PO3992084594	LGE	4	40 ACE	SP	CRE	ED,ID	TD			00:00.0
2021 PO3991984577	LGE	4	30 ACE	SP	A	ED,EP,ID,IP,MD,RB	VX	RP2		00:00.0
2021 PO4024684122	LGE	4	55 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4024384162	LGE	4	35 ACE	SP	CCA		V			00:00.0
2021 PO3976084449	F	4	40 ACE	SP	P		V			00:00.0
2021 PO3975184449	F	4	40 ACE	SP	CCA		V			00:00.0
2021 PO3975084434	F	4	40 ACE	SP	P		V			00:00.0
2021 PO3975084420	F	4	40 ACE	SP	A		V			00:00.0
2021 PO3974684402	LGE	3	45 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO3977284442	F	3	45 ACE	SP	CCA		V			00:00.0
2021 PO3978084440	F	3	45 ACE	SP	CCA		V			00:00.0
2021 PO3979284431	F	4	40 ACE	SP	P		V			00:00.0
2021 PO3981184419	F	4	40 ACE	SP	CCA		V			00:00.0

2021 PO4026084155	LGE	4	30 ACE	SP	CCA		V			00:00.0
2021 PO4025984153	LGE	1	60 ACE	SP	CCA		V			00:00.0
2021 PO4035484220	LGE	1	95E ACE	SP	A		V			00:00.0
2021 PO4034684202	LGE	1	95E ACE	SP	A		V			00:00.0
2021 PO4033784182	LGE	1	95E ACE	SP	A		V			00:00.0
2021 PO4032784162	LGE	1	90 ACE	SP	A		V			00:00.0
2021 PO3982484435	F	4	30 ACE	SP	P		V			00:00.0
2021 PO3983184436	F	3	45 ACE	SP	CCA		V			00:00.0
2021 PO3982784428	F	4	40 ACE	SP	P		V			00:00.0
2021 PO3982384411	F	4	40 ACE	SP	P		V			00:00.0
2021 PO3983684409	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4031784142	LGE	1	90E ACE	SP	A		V			00:00.0
2021 PO4031284130	LGE	3	55 ACE	SP	A	ED	BD			00:00.0
2021 PO3984484404	LGE	4	40 ACE	SP	P	ED,ID	VX	RP3		00:00.0
2021 PO3979884634	LGE	4	30 ACE	SP	P	ED,ID,IP,RB	TX	RR		00:00.0
2021 PO4025684145	LGE	1	50 ACE	SP	CCA		V			00:00.0
2021 PO9328297812	KU	6	30 XXX	SP	CRE	ID	TD			00:00.0
2021 PO9323697843	KU	4	40 XXX	SP	CRE	ID	BD			00:00.0
2021 PO4025384123	LGE	5	35E ACE	SP	CCA	ED	BD			00:00.0
2021 PO4024884117	LGE	3	55 ACE	SP	A	ED	BD			00:00.0
2021 PO7757370823	KU	3	45 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO7770670902	KU	3	45 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021 PO7784070983	KU	3	55 ACE	SP	CCA		V			00:00.0
2021 PO3991084568	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021 PO7690470548	KU	3	50 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO3991484588	LGE	4	40 ACE	SP	CRE	ED,ID	TD			00:00.0
2021 PO3990184576	LGE	5	25 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO7695670380	KU	4	45 ACE	SP	CCA		V			00:00.0
2021 PO4125084491	F	4	40 BRO	SP	P		V			00:00.0
2021 PO4124684489	F	3	45 BRO	SP	P		V			00:00.0
2021 PO4124384484	F	6	30 BRO	SP	CRE		V			00:00.0
2021 PO7703670142a	KU	2	70 ACE	SP	CCA		V			00:00.0
2021 PO7703670142	KU	4	45 ACE	SP	CCA		V			00:00.0
2021 PO7712969858b	KU	3	45 ACE	SP	CCA		V			00:00.0
2021 PO7712969858a	KU	3	45 ACE	SP	CCA		V			00:00.0
2021 PO7712969858	KU	4	45 ACE	SP	CCA		V			00:00.0
2021 PO4125384472	LGE	4	30 BRO	SP	P	ED,ID	TD			00:00.0
2021 PO4124984471	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO7718269704	KU	4	45 ACE	SP	CCA		V			00:00.0
2021 PO7709169610	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO4216189160	KU	4	45 BRO	ST	CCA		V			00:00.0
2021 PO4151291407	KU	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO4132891436	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO7722370651	KU	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO7740770724	KU	4	45 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4205288746	KU	4	45 BRO	ST	CCA		V			00:00.0
2021 PO4214888533	KU	4	45 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO4150888515	KU	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO4155388373	KU	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO4096288668	KU	5	35 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO9369198841	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0
2021 PO9364398912	KU	6	30 XXX	SP	CRE	ID	TD			00:00.0
2021 PO9381899063	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0
2021 PO9387699168	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0

2021	PO9391899406	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO7703869604	KU	6	30 ACE	SP	CRE	ED,ID	V	00:00.0
2021	PO4125584454	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4126084454	LGE	4	30 BRO	SP	S	ED,ID,IP	TD	00:00.0
2021	PO7723269559a	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO7723269559	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7726369415	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO3990684513	F	6	30 ACE	SP	A		V	00:00.0
2021	PO4078487959	KU	3	45 BRO	SP	S		V	00:00.0
2021	PO4073188648	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4035387839	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4019587651	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO3991584531	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4073287991	F	3	45 BRO	SP	S		V	00:00.0
2021	PO3990684557	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4079888452	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3989984517	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO3975287780	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO3989884530	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4052687983	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3990084541	F	4	40 ACE	SP	A		V	00:00.0
2021	PO3982484605	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO7732369222	KU	4	45 ACE	SP	CCA	ED	TD	00:00.0
2021	PO7735669235	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4126284435	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4126684435	LGE	4	30 BRO	SP	P	ED,EP,HH,ID,RB	BX PX	00:00.0
2021	PO4126984416	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4127284417	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021	PO4125984419	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO7738269147	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX RP1	00:00.0
2021	PO7738969128	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021	PO7743468996	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4025084160	F	1	55 ACE	SP	CCA		V	00:00.0
2021	PO4025984185	F	1	50 ACE	SP	CCA		V	00:00.0
2021	PO4026484148	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021	PO7944671901a	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO7944671901	KU	4	40 ACE	SP	CRE		V	00:00.0
2021	PO7946271903	KU	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4026884145	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021	PO7968072875	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO8020472900	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO7994572888	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO7941572862	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO4028484134	F	1	60 ACE	SP	CCA		V	00:00.0
2021	PO3983684596	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3984784587	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3985784577	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4029184130	F	1	60 ACE	SP	CCA		V	00:00.0
2021	PO4030484098	LGE	5	35 ACE	SP	CCA		V	00:00.0
2021	PO7971171917	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4029784101	LGE	UNK	100 ACE	SP	A		V	00:00.0
2021	PO4029384076	LGE	1	95E ACE	SP	A		V	00:00.0
2021	PO3986884570	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3987984561	F	4	40 ACE	SP	CRE		V	00:00.0

2021 PO3988884547	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO7997271656	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7983671788	KU	4	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO8023671700	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO3991084480	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO7077156348	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO3993984660	LGE	4	30 ACE	SP	A	ED,ID	VX	RP3	00:00.0
2021 PO4022084266	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4021884251	F	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4021984257	F	4	40 ACE	SP	A		V		00:00.0
2021 PO4021184254	F	4	30 ACE	SP	A		V		00:00.0
2021 PO4019984252	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4020084260	F	4	40 ACE	SP	A		V		00:00.0
2021 PO4018684255	F	4	30 ACE	SP	A		V		00:00.0
2021 PO4018284263	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4016684263	F	4	30 ACE	SP	A		V		00:00.0
2021 PO4016184267	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4015784264	LGE	4	30 ACE	SP	P	ED	TD		00:00.0
2021 PO3986684697	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO3971884624	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO3972984624	LGE	4	40 ACE	SP	A	ED,ID,IP	BX	RR	00:00.0
2021 PO3974384623	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4013684272	LGE	4	30 ACE	SP	A	ED	TD		00:00.0
2021 PO4014284272	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4024084240	LGE	4	40 ACE	SP	A	ED,IP	TD		00:00.0
2021 PO3975784623	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO3977384622	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO3981384669	LGE	4	35 ACE	SP	A	ED	V		00:00.0
2021 PO4023784225	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4022784208	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4021784211	F	6	40 ACE	SP	CRE		V		00:00.0
2021 PO4021184220	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4020784212	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4019984214	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3983784363	F	4	40 ACE	SP	P		VX	RP3	00:00.0
2021 PO3983584365	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4018884215	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4018584222	F	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4016984226	F	4	35 ACE	SP	P		V		00:00.0
2021 PO4016484220	F	4	35 ACE	SP	A		V		00:00.0
2021 PO3982384373	F	4	40 ACE	SP	A		V		00:00.0
2021 PO3981184380	F	4	40 ACE	SP	P		V		00:00.0
2021 PO3980284386	F	4	40 ACE	SP	A		V		00:00.0
2021 PO3979084393	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO3977584403	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO3976384411	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4023784207	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4023584214	F	4	40 ACE	SP	A		V		00:00.0
2021 PO4047184425	LGE	UNK	45 ACE	SP	CRE		V		00:00.0
2021 PO4025984238	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4027484349	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4027484346	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4027284324	F	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4027184316	F	4	40 ACE	SP	P		V		00:00.0

2021 PO4027084305	F	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO3990484382	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3990084382	F	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO4025784229	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4025684226	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4026684226	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4024384252	F	4	40 ACE	SP	A		V	00:00.0	
2021 PO4022984255	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4029784170	LGE	4	35 ACE	SP	CRE	ED,IP	BD	00:00.0	
2021 PO3215579690	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4021683948	LGE	1	100 BRO	ST	P		V	00:00.0	
2021 PO4029384159	LGE	4	30 ACE	SP	P	ED	TD	00:00.0	
2021 PO3991184454	F	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO3957184691	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO3973584617	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4028484175	LGE	4	40 ACE	SP	CRE	ED	V	00:00.0	
2021 PO3982084462	LGE	4	35 ACE	SP	CRE		V	00:00.0	
2021 PO9391297673	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO9378297904	KU	4	40 XXX	SP	CRE	HH,ID,IP	TX	RR	00:00.0
2021 PO9356997780	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9362597932	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO9343197829	KU	6	30 XXX	SP	CRE	ID,IP	BD	00:00.0	
2021 PO9349697970	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO9322597698	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO9314897928	KU	6	30 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO9859588125	KU	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9849988297	KU	5	35 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021 PO9846188174	KU	4	45 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021 PO4030984156	LGE	4	35 ACE	SP	A	ED,IP	TD	00:00.0	
2021 PO4103985688	LGE	2	70 BRN	SP	A		V	00:00.0	
2021 PO4103385677	LGE	2	75 BRN	SP	CRE		V	00:00.0	
2021 PO4102285680	LGE	4	30 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4176486144	LGE	3	40 BRO	SP	A	ID	BD	00:00.0	
2021 PO4176486147	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4176486154	LGE	4	40 BRO	SP	A	ID	BD	00:00.0	
2021 PO4144884503	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4143884504	LGE	4	45 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4140884516	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO4142184516	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4153985602	LGE	4	35 BRO	SP	A	ID	TD	00:00.0	
2021 PO4153985605	LGE	4	45 BRO	SP	A	ID	TD	00:00.0	
2021 PO4153385606	LGE	4	45 BRO	SP	A	ID	TD	00:00.0	
2021 PO4250040046	KU	4	45 BRO	SP	CCA		V	00:00.0	
2021 PO4260439811	KU	4	45 BRO	SP	CCA		B	00:00.0	
2021 PO4175186148	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4154185621	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4153285622	LGE	4	40 BRO	SP	A	ID	TD	00:00.0	
2021 PO7491711377	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO7376013410	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7523211660	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO7515911584	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO7492911672	KU	3	45 ACW	SP	S		V	00:00.0	
2021 PO7493211589	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO7499111590	KU	4	40 ACW	SP	S		V	00:00.0	



2021 PO7492711815	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO7492411988	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO7491712122	KU	4	45 ACW	SP	S		V	00:00.0	
2021 PO7489612309	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO7519912305	KU	3	45 ACW	SP	CRE	ED,ID	BD	00:00.0	
2021 PO7530712430	KU	3	45 ACW	SP	S		V	00:00.0	
2021 PO4131784356	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4273240066	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4267639650	KU	4	45 BRO	SP	CCA		B	00:00.0	
2021 PO4298939407	KU	4	45 BRO	SP	CCA		B	00:00.0	
2021 PO4276439452	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4256439450	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4229439446	KU	4	45 BRO	SP	CCA		B	00:00.0	
2021 PO4152985623	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4171886148	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4173086147	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4174286148	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4170986148	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4153985634	LGE	4	40 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO4154285635	LGE	4	35 BRO	SP	CCA	ED,ID	V	00:00.0	
2021 PO4154385650	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4152185606	LGE	4	45 BRO	SP	CCA		V	00:00.0	
2021 PO4158985643	LGE	4	35 BRO	SP	CRE	ED	TD	00:00.0	
2021 PO4169986149	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4141684495	LGE	4	45 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4141384486	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4168086152	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4168086163	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4428771540	KU	5	45 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO3992742503	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2119605212	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO2164005096	KU	3	50 UNK	SP	CCA		V	00:00.0	
2021 PO2197405010	KU	4	40 UNK	SP	S		V	00:00.0	
2021 PO2234104913	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO2275604807	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO2316704703	KU	3	45 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO2355404600	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO4385671529	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4397371882	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4407372192	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4406972507	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4342571501	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO7259212902	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO7246012731	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7232312553	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0	
2021 PO3994942557	KU	5	35 BRO	SP	CCA		B	00:00.0	
2021 PO4330371821	KU	4	45 BRN	SP	CCA		V	00:00.0	
2021 PO4348571424	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4354071044	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO2608203156	KU	3	50 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO2396304498	KU	3	45 UNK	SP	S	SRS	TD	00:00.0	
2021 PO2437604392	KU	3	40 UNK	SP	CRE	HH,ID	X	RP2	00:00.0
2021 PO2471304305	KU	3	50 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO2505504128	KU	3	40 UNK	SP	CRE	ID,SRS	TD	00:00.0	

2021 PO2624502967	KU	4	45 UNK	SP	CRE	EP,ID,SRS	TX	RR	00:00.0
2021 PO4159085657	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4167386093	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4167686094	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4011142412	KU	4	45 BRO	SP	CCA		B		00:00.0
2021 PO4157185641	LGE	4	40 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO4227840274	KU	4	45 BRO	SP	CCA		T		00:00.0
2021 PO4121140541	KU	3	45 BRO	SP	CCA		B		00:00.0
2021 PO4180340843	KU	4	45 BRO	SP	CCA		V		00:00.0
2021 PO4215840521	KU	4	45 BRO	SP	CCA		B		00:00.0
2021 PO4143785098	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021 PO4181086145-A	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4157285652	LGE	4	40 BRO	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021 PO4138284533	LGE	3	45 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4138984528	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4140784522	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4178386146	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4179286146	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4181086145	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4157385664	LGE	4	40 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO4157485675	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4150285606	LGE	4	45 BRO	SP	CCA		V		00:00.0
2021 PO7293113452	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7291613308	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7274813101	KU	4	40 ACW	SP	CRE	ED,ID	BD		00:00.0
2021 PO4117885242	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4159185671	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4354770944	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4378170856	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4462271236	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4011142412A	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4167686101	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4167586089	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4144184927	LGE	3	50 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4021842013	KU	4	45 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4058141817	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4153785571	LGE	2	55 BRO	SP	P	ID	BD		00:00.0
2021 PO4126685174	LGE	2	60 ACE	SP	CCA		V		00:00.0
2021 PO4492670957	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4160685668	LGE	4	35 BRO	SP	CRE	ID	TD		00:00.0
2021 PO4085985209	LGE	3	50 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4465771560	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4506971587	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4515470833	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4083041658	KU	4	45 BRO	SP	CCA		T		00:00.0
2021 PO4144284943	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7427014341	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO7397914156	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7409914171	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO7405314043	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO7549814710	KU	3	40 ACW	SP	S		V		00:00.0
2021 PO7551215007	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7516715025	F	4	40 ACW	SP	CRE		V		00:00.0
2021 PO7512115350	KU	2	65 ACW	SP	CRE	ED,HH,ID,IP,MD,RB	BX	RP2	00:00.0

2021 PO7482415273	KU	2	60 ACW	SP	CRE		V	00:00.0
2021 PO7633317931	KU	3	55 ACW	SP	S		V	00:00.0
2021 PO7626218157	KU	3	45 ACW	SP	S		V	00:00.0
2021 PO4120385243	LGE	4	30 BRO	SP	P	ID	BD	00:00.0
2021 PO4120285248	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4531170863	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4558670743	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4657671744	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4143884925	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4144484960	LGE	3	50 ACE	SP	P	ED,HH,ID,MD,RB	BX	RP1 00:00.0
2021 PO4168886131	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4170886131	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4169886131	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4093641402	KU	4	45 BRO	SP	CCA		B	00:00.0
2021 PO4127284931	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4619071662	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4167686132	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4122285247	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4167886139	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4174286129	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4127684934	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4074441307	KU	4	45 BRO	SP	CCA		B	00:00.0
2021 PO4631771870	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4553571611	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4562071526	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4649572178	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4159185453	LGE	4	30 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4158985453	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4073140615	KU	4	45 BRO	SP	CCA		B	00:00.0
2021 PO4071640765	KU	4	45 BRO	SP	CCA		B	00:00.0
2021 PO4068541064	KU	4	45 BRO	SP	CCA		B	00:00.0
2021 PO4067440254	KU	4	45 BRO	SP	CCA		B	00:00.0
2021 PO4155385603	LGE	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4156785602	LGE	4	45 BRO	SP	A	ID	BD	00:00.0
2021 PO4137485604	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4172986129	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4171886130	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4128484920	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4182886144	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4126784948	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4126084959	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4183786143	LGE	4	35 BRO	SP	A	ED,ID,RB	X	RP1 00:00.0
2021 PO4181986144	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4072740421	KU	4	45 BRO	SP	CCA		B	00:00.0
2021 PO4103640644	KU	4	45 BRO	SP	CCA		T	00:00.0
2021 PO4156985619	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4156385618	LGE	4	30 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4137884534	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4671372569	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4684372680	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4698472769	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4685872338	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4678172195	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4670674896	KU	4	45 BRN	SP	CRE		V	00:00.0

2021 PO4653974219	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4695474401	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4689674713	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4684374686	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4157085630	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4182185921	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO3829843354	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO4137084528	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4138384520	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4141385045	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4140485072	LGE	4	40 BRO	SP	CRE	ID	TD	00:00.0	
2021 PO4141485061	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4142285051	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4182385965	LGE	4	40 BRO	SP	A	ID	BD	00:00.0	
2021 PO3770043846	KU	4	40 INP	SP	CRE	ID	TD	00:00.0	
2021 PO4004665134	KU	4	45 BRN	SP	CCA		V	00:00.0	
2021 PO4005065066	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4203771553	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO3854865857	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO3897265763	KU	4	45 BRN	SP	CCA		V	00:00.0	
2021 PO3939665641	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO3966765403	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO1231507461	KU	2	65 UNK	SP	CRE	ID,IP	TD	00:00.0	
2021 PO1205507405	KU	3	50 UNK	SP	CRE	ID,IP	TD	00:00.0	
2021 PO1178107353	KU	3	50 UNK	SP	CCA		V	00:00.0	
2021 PO1153607291	KU	3	40 UNK	SP	CRE	ID,SRS	TD	00:00.0	
2021 PO1038707041	KU	3	60 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO1082607137	KU	3	45 UNK	SP	CRE	ID,SRS	TD	00:00.0	
2021 PO3927942771	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO3863843320	KU	4	40 BRN	SP	CRE		T	00:00.0	
2021 PO4182685990	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4138984515	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4137285062	LGE	4	40 BRO	SP	CRE	ED,HH,ID	BD	00:00.0	
2021 PO4143385039	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4182585977	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO3802943921	KU	5	35 INP	SP	CRE	ID	TD	00:00.0	
2021 PO4135784533	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4134984534	LGE	4	35 ACE	SP	P	ED,ID,RB	TX	RR	00:00.0
2021 PO4139585082	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4138985080	LGE	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4138385091	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4137385088	LGE	4	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4184171417	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO4146571396	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4106471376	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4195471298	KU	6	35 BRN	SP	CRE		V	00:00.0	
2021 PO4254171063	KU	4	45 BRN	SP	CCA		V	00:00.0	
2021 PO4132484546	LGE	4	35 ACE	SP	P	ED,ID,RB	TX	RR	00:00.0
2021 PO4133384539	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4145685040	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4145485060	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4145585083	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO7169511738	KU	6	35 ACW	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO3818043760	KU	4	40 INP	SP	CRE	ID	TD	00:00.0	

2021 PO4182686002	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4182786012	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4182585991	LGE	4	40 BRO	SP	A	ED,ID,IP,RR	TX	RR	00:00.0
2021 PO3847743445	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3836143561	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO3827743652	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4137685081	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4135785091	LGE	4	45 BRO	SP	A	ID	TD		00:00.0
2021 PO4254771457	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4269071375	KU	5	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4144585073	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4144785060	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO1620906496	KU	3	40 UNK	SP	CRE	ID,IP,SRS	TD		00:00.0
2021 PO4130785102	LGE	4	45 BRO	SP	A	ED,ID	X	PX	00:00.0
2021 PO7547913017	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9483897336	KU	6	30 XXX	SP	CRE		V		00:00.0
2021 PO9494497287	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5780425633	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO8340686838	KU	5	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO8376886975	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4106485357	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4107785358	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4108285364	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4107685373	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4112485346	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4111685369	LGE	4	35 ACE	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4114185333	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4114085342	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4114185353	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4108785393	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4117385403	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO8369086678	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4117285373	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO8721389851	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO8756490169	KU	5	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4070785420	F	4	35 ACE	SP	P		V		00:00.0
2021 PO4070285416	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4070085405	F	5	25 ACE	SP	CRE		V		00:00.0
2021 PO4070685404	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4067385387	F	6	25 ACE	SP	CRE		V		00:00.0
2021 PO4069085381	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4067585382	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4066985439	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4066585428	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4066485418	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4066485408	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4066485397	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4066385388	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4065985382	F	4	45 ACE	SP	P		V		00:00.0
2021 PO4066085375	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4064985370	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4064285363	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4063585355	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4061985337	F	4	40 ACE	SP	P		V		00:00.0

2021 PO4062885348	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4062385352	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4114185543	F	1	20 ACE	SP	CRE		V	00:00.0
2021 PO4076885376	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7889365565	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7889265565	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4079685512	F	5	25 ACE	SP	CRE		V	00:00.0
2021 PO4079585506	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4079285503	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4078485516	F	5	25 ACE	SP	CRE		V	00:00.0
2021 PO4078385509	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4077085515	F	5	25 ACE	SP	CRE		V	00:00.0
2021 PO4077185509	F	3	40 ACE	SP	CCA		V	00:00.0
2021 PO4075885511	F	5	25 ACE	SP	CRE		V	00:00.0
2021 PO4076085506	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4074885502	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4075085494	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4073885490	F	6	25 ACE	SP	CRE		V	00:00.0
2021 PO4082285378	F	3	45 ACE	SP	P		V	00:00.0
2021 PO4083285389	F	3	40 ACE	SP	CCA		V	00:00.0
2021 PO4070785499	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4072485500	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4073785500	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO7840566648	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4071185483	F	4	30 ACE	SP	P	ED,EP	V	00:00.0
2021 PO4070485380	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4072085379	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4081385486	LGE	4	30 ACE	SP	P		V	00:00.0
2021 PO4071185476	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4070085462	F	5	25 ACE	SP	P		V	00:00.0
2021 PO4070585465	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4068885438	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4070985461	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4070285452	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4070885449	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4070885436	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4108485323	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4105585336	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4105485328	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4083685503	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4083985497	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4082885499	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4081785502	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4080685504	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4070585395	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4083985513	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4073685369	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4070785488	LGE	6	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4073585378	LGE	5	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4075985377	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4083885492	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4068585386	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	00:00.0
2021 PO4068585395	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4084385529	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0

2021 PO4083585531	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4082685495	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4078985358	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4077385376	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4075485377	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4074685378	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4077785348	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4076385348	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4075785371	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4077485360	LGE	4	35 ACE	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4078185359	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO3921701004	KU	3	40 BRN	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021 PO4158002412	F	3	40 BRN	SP	P		V		00:00.0
2021 PO4145402341	F	3	45 BRN	SP	P		V		00:00.0
2021 PO4146802378	F	4	45 BRN	SP	CRE		V		00:00.0
2021 PO4329003076	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4318003029	F	2	50 BRN	SP	CRE		V		00:00.0
2021 PO3806700468	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3806700468a	KU	5	40 BRN	SP	CCA		V		00:00.0
2021 PO3753400660	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3774000574	F	6	40 BRN	SP	CRE	ED,ID	V		00:00.0
2021 PO3753900491	F	4	40 BRN	SP	CRE	ED	V		00:00.0
2021 PO3803800696	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3753801365	KU	5	40 BRN	SP	CCA		V		00:00.0
2021 PO3711000862	F	7	35E BRN	SP	CRE	ED,ID	V		00:00.0
2021 PO3679701186	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4303802970	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO4182902407	F	3	50 BRN	SP	CCA		V		00:00.0
2021 PO4279802871	F	2	50 BRN	SP	CRE		V		00:00.0
2021 PO4248402721	F	3	40 BRN	SP	P	ED	V		00:00.0
2021 PO4213202594	F	3	40 BRN	SP	CRE	ED	V		00:00.0
2021 PO4185002492	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO4263102791	F	2	45 BRN	SP	CRE	ED	V		00:00.0
2021 PO3651601511	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3652501465	F	3	40 BRN	SP	P	ED,SRS	V		00:00.0
2021 PO3653201861	F	3	40 BRN	SP	P		V		00:00.0
2021 PO3654002349	F	3	40 BRN	SP	P		V		00:00.0
2021 PO3582599791	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3675401397	KU	5	40 BRN	SP	CCA		V		00:00.0
2021 PO3622899956	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3654902605	F	4	40 BRN	SP	CRE	ED	V		00:00.0
2021 PO3664100124	KU	3	40 BRN	SP	CCA		V		00:00.0
2021 PO3721500357	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4095085369	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8020865652	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4088585377	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4070385372	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO8082065556	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4068585346	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4068985342	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4069885353	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4009085114	LGE	4	35 BRN	SP	A		V		00:00.0
2021 PO4084985394	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO8004965613	LGE	4	35 ACE	SP	CCA		V		00:00.0

2021 PO4009285104	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4067885338	F	4	30 BRN	SP	A		V	00:00.0
2021 PO4068185334	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4067585327	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4066985320	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4066185312	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4065585305	F	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4064885297	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4092885336	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4009585045	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4008885122	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4009385093	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3735201378	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3713100890	KU	5	40 BRN	SP	CCA	ED	TD	00:00.0
2021 PO3726800703	KU	3	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO3786400218	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4143002374	KU	3	40 BRN	SP	CCA	ED	TD	00:00.0
2021 PO3944800877	KU	3	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3875901156	KU	5	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3614101513	KU	3	40 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO3694601420	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3709800075	KU	6	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3702400278	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4095485376	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4088685382	LGE	6	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4089585376	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4094685370	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4087585383	LGE	6	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4090585375	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4091585377	LGE	6	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4091485374	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4092485372	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4087085341	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4005685081	LGE	4	35 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4006685084	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4008285054	LGE	4	30 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4085885342	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4001885099	LGE	4	35 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4002885090	LGE	4	35 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4004185086	LGE	4	35 BRN	SP	A	ED,EP,ID	TD	00:00.0
2021 PO4088385336	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4089385334	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4084085383	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4008685069	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4007985079	LGE	4	35 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4008385118	LGE	4	30 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4008985082	LGE	4	35 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4069485356	LGE	4	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4086585379	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4087585378	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4091785337	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4009085058	LGE	4	40 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4091285354	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4000285114	LGE	4	40 BRN	SP	A	ED,ID	TD	00:00.0



2021 PO4084385380	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4085685380	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4070285357	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4088385340	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4093485371	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO3569001551	KU	5	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4089785339	LGE	4	40 ACE	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4090485338	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4084085376	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4095985384	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4446904731	KU	4	40 BRN	SP	CRE	ED,ID,IP,RB	X	PX	00:00.0
2021 PO4008085196	LGE	4	40 BRN	SP	CRE	ED,HH,ID	X	RP3	00:00.0
2021 PO3638588368	KU	4	40 BRN	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021 PO4718828514	F	4	40 OTH	SP	P	ED,HH,ID,RB	VX	PX	00:00.0
2021 PO3574888477	KU	6	30 BRN	SP	CRE	ED,EP,HH,ID,MD,RB	VX	PX	00:00.0
2021 PO4856002557	KU	6	35 BRN	SP	CCA		V		00:00.0
2021 PO3824700784	F	2	55 BRN	SP	CRE		V		00:00.0
2021 PO4175402464	F	4	40 BRN	SP	P	ED	V		00:00.0
2021 PO3924801186	F	4	40 BRN	SP	CRE	ED	V		00:00.0
2021 PO3960901336	F	3	40 BRN	SP	CCA		V		00:00.0
2021 PO3857800919	F	5	40 BRN	SP	CRE	ED	V		00:00.0
2021 PO3882801023	F	3	40 BRN	SP	CRE	ED	V		00:00.0
2021 PO4078201825	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO4087701555	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4104101850	F	3	40 BRN	SP	CRE	ED,ID	V		00:00.0
2021 PO4115001931	F	3	40 BRN	SP	P	ED	V		00:00.0
2021 PO4136102089	F	2	50E BRN	SP	CRE	ED,ID	V		00:00.0
2021 PO4140602207	F	3	40 BRN	SP	P	ED	V		00:00.0
2021 PO4041901674	F	5	40 BRN	SP	CRE	ED,ID	V		00:00.0
2021 PO4009601540	F	3	40 BRN	SP	CRE	ED	V		00:00.0
2021 PO4078185316	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4079685332	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4078985325	LGE	2	50 ACE	SP	CCA		V		00:00.0
2021 PO4083785323	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4005985163	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4080385336	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4081185337	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4082585346	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4004385197	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4080785345	LGE	2	50 ACE	SP	CCA		V		00:00.0
2021 PO4008285184	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4001785257	F	4	30 BRN	SP	CRE		V		00:00.0
2021 PO7166764143	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4002085235	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4002685221	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4003285207	F	4	40 BRN	SP	P		V		00:00.0
2021 PO3997885251	LGE	4	80 BRN	ST	CCA		V		00:00.0
2021 PO3998085143	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4084485305	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO4003885295	LGE	1	80 BRN	ST	CCA		V		00:00.0
2021 PO4084185305	LGE	1	25 ACE	SP	A		V		00:00.0
2021 PO4005185310	LGE	1	80 BRN	ST	CCA		V		00:00.0
2021 PO4005785319	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4000185253	LGE	4	30 BRN	SP	CRE		V		00:00.0

2021 PO4089885301	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO2731494844a	KU	5	40 BRN	SP	CCA		V	00:00.0
2021 PO2731494844	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2731494844c	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO2405788488	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO2413788202	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO2408288404	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO5657387884	KU	4	40 ACE	SP	CRE	ED,ID	X	00:00.0
2021 PO5355826704	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5348326665	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO5344926649	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO8481567497	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO2878295894	KU	4	40 ACE	SP	CRE	ED	TD	00:00.0
2021 PO2786894867	KU	7	40 ACE	SP	CRE	ED,ID,SR	TD	00:00.0
2021 PO5632787850	KU	4	45 ACE	SP	CRE	ID	TD	00:00.0
2021 PO4111785916	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4111085922	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4104985986	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO3987883448	LGE	2	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4017583879	LGE	2	105 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4111085930	LGE	4	45 ACE	SP	A		V	00:00.0
2021 PO4016983868	LGE	2	65 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5546586824	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5550787125	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0
2021 PO5504286672	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5504287022	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5497987212	KU	3	45 ACE	SP	P		V	00:00.0
2021 PO5358626643	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO8487167394	F	3	55 ACE	SP	CRE		V	00:00.0
2021 PO2866895828	KU	7	30 ACE	SP	CCA		V	00:00.0
2021 PO4111285945	LGE	3	45 ACE	SP	A		V	00:00.0
2021 PO4111485964	LGE	3	50 ACE	SP	A		V	00:00.0
2021 PO4111585976	LGE	3	45 ACE	SP	A		V	00:00.0
2021 PO4111685987	F	3	45 ACE	SP	A		V	00:00.0
2021 PO5378226733	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO8483067296	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2436088726	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO2428789113	KU	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO5329227368	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO2922795302	KU	6	40 CRE	SP	CCA		V	00:00.0
2021 PO2904595483	KU	3	40 CRE	SP	CCA		V	00:00.0
2021 PO5315527292	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO5318727137	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO8402268307	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8392668391	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5375425893	KU	4	40 UNK	SP	CRE	IP,RB	BX	00:00.0
2021 PO2967095299	KU	7	30 ACE	SP	CRE		B	00:00.0
2021 PO5376025993	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5370026030	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5347625814	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO5349026053	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO4014083820	LGE	2	100 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5382387635	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5396887801	KU	5	30 ACE	SP	CRE	ID	TD	00:00.0

2021	PO5375187532	KU	4	40 ACE	SP	CRE		V		00:00.0
2021	PO5374387501	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO5354587421	KU	5	30 ACE	SP	CRE	ID	TD		00:00.0
2021	PO5345187439	KU	5	35 ACE	SP	CRE	ID	TD		00:00.0
2021	PO5350887473	KU	6	30 ACE	SP	CRE	ED,ID	X	RP1	00:00.0
2021	PO5354787516	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO5347587565	KU	4	45 ACE	SP	CRE	ID	TD		00:00.0
2021	PO8286068400	KU	6	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO8285168276	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO1812186356	KU	4	45 KOP	SP	CRE	ID	TD		00:00.0
2021	PO1793586191	KU	4	40 KOP	SP	CRE	ID	TD		00:00.0
2021	PO4063185997	F	4	45 ACE	SP	CRE		V		00:00.0
2021	PO4063185991	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO2815395161	KU	4	40 ACE	SP	CRE		T		00:00.0
2021	PO8299668406	KU	6	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4061785997	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4059785999	F	3	50 ACE	SP	CRE		V		00:00.0
2021	PO4060485999	F	3	45 ACE	SP	CRE		V		00:00.0
2021	PO7742071549	F	6	30 ACE	SP	P		V		00:00.0
2021	PO4060285970	F	7	25 ACE	SP	CRE		V		00:00.0
2021	PO4059585968	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021	PO8299668276	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO1785292227	KU	5	40 KOP	SP	CRE	ID	TD		00:00.0
2021	PO4013483810	LGE	3	60 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO8285368157	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8299668162	KU	6	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO8312068165	KU	6	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO8311768283	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4057785964	F	4	30 ACE	SP	CRE		V		00:00.0
2021	PO8875496183	KU	6	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO8860696217	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4096685754	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4011483780	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO4095385729	F	4	40 ACE	SP	CRE	EP,HH,ID,RB	VX	PX	00:00.0
2021	PO4096085744	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4094785716	F	4	35 ACE	SP	CRE		V		00:00.0
2021	PO4100085979	F	4	45 ACE	SP	CCA		V		00:00.0
2021	PO8443765703	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO8468766199	KU	3	40 ACE	SP	CCA		V		00:00.0
2021	PO2862695197	KU	3	45 BRN	SP	CCA		V		00:00.0
2021	PO2905494290	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO2891694638	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO2877794987	KU	3	40 ACE	SP	CCA		V		00:00.0
2021	PO4018983354	F	4	30 BRO	SP	CCA		V		00:00.0
2021	PO4019183348	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4018483377	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4019583353	F	4	40 BRO	SP	A		V		00:00.0
2021	PO4019283366	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4018983381	F	4	40 BRO	SP	A		V		00:00.0
2021	PO4018183393	F	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4017483403	F	3	45 BRO	SP	CCA		V		00:00.0
2021	PO7352945859	F	3	45 BRO	SP	CCA		V		00:00.0
2021	PO1936987317	KU	4	45 BRO	SP	CCA		V		00:00.0
2021	PO8284267886	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		00:00.0

2021 PO1959387133	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO1985986808	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8413267513	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8412867469	KU	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4055085968	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO2831394933	KU	3	40 ACE	SP	CRE		T	00:00.0
2021 PO2858694981	KU	6	40 ACE	SP	CRE		T	00:00.0
2021 PO8330668175	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8329568288	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8461665713	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO8453765709	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO1931987613	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4012183790	LGE	2	95 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1953887034	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO8888796664	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO8878696630	KU	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO8904695982	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO8899596088	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8885996145	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8883496094	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8284867989	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021 PO8300367993	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8311367998	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4018883413	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4020583426	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4019283433	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO1980186617	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4022683439	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1993886470	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2005086352	KU	4	45 BRO	SP	CCA		T	00:00.0
2021 PO4023283307	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5157026607	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO4021483322	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8331468006	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8346767979	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8360567846	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4084885988	F	5	35 ACE	SP	CCA		V	00:00.0
2021 PO4084785985	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4082785989	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4082685987	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO4084285980	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4082585971	LGE	4	45 ACE	SP	CRE		V	00:00.0
2021 PO1814586630	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO8388368203	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8373668331	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4081285988	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4079885987	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4079885991	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4063286004	F	4	35 ACE	SP	A		V	00:00.0
2021 PO4014983836	LGE	2	65 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO2964795423	KU	3	45 ACE	SP	CRE	ED,SRS	TD	00:00.0
2021 PO8395668435	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8411468224	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4012583797	LGE	2	50 BRO	SP	CRE	ED,ID,IP	TX RR	00:00.0

2021 PO8439967967	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5323727447	KU	3	45 UNK	SP	CRE		B	00:00.0	
2021 PO5340826946	KU	5	35 UNK	SP	CRE		B	00:00.0	
2021 PO5332826941	KU	2	50 UNK	SP	CRE		B	00:00.0	
2021 PO2926195618	KU	6	40 CRE	SP	CRE	ED,ID,RB,SRC	X	RP2	00:00.0
2021 PO2405989967A	KU	3	40 KOP	SP	S	ED	T	00:00.0	
2021 PO2419489496	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2407389460	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2396589383	KU	6	30 KOP	SP	S		V	00:00.0	
2021 PO1752989363	KU	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO8441267906	KU	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO8434467921	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO1779889423	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4109785996	LGE	4	30 ACE	SP	CRE	ID	BD	00:00.0	
2021 PO1806089413	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4106186037	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO2917195698	KU	3	40 BRN	SP	CRE	ED	TD	00:00.0	
2021 PO1729491333	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO1530489260	KU	4	45 BRO	SP	CCA		V	00:00.0	
2021 PO1806686730	KU	5	35 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO8472867174a	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO8472867174	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO8419068279	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5337326903	KU	3	45 UNK	SP	CRE		T	00:00.0	
2021 PO5343526831	KU	3	45 UNK	SP	CRE		B	00:00.0	
2021 PO2930696055	KU	5	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO4107486037	LGE	4	40 ACE	SP	P	ID	BD	00:00.0	
2021 PO4107286052	LGE	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO2918696264	KU	7	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4015583845	LGE	2	105 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4015683847	LGE	2	80 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO8423368121	KU	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0	
2021 PO8410068050	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8407467908	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5368926194	KU	4	40 UNK	SP	CRE		B	00:00.0	
2021 PO5367126128	KU	6	30 UNK	SP	CRE		T	00:00.0	
2021 PO4085985984	F	4	45 ACE	SP	A		V	00:00.0	
2021 PO2388090538	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2419390870	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2486891036	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2527990854	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2405989967	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2400990169	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2394490383	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5377226200	F	4	40 UNK	SP	CRE	ID,RB	BX	PX	00:00.0
2021 PO2915596433	KU	3	45 BRN	SP	S		V	00:00.0	
2021 PO2913096572	KU	7	30 BRN	SP	CCA		V	00:00.0	
2021 PO4085985989	F	4	35 ACE	SP	CRE		V	00:00.0	
2021 PO5320427112	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO4109986001	LGE	4	40 ACE	SP	A		V	00:00.0	
2021 PO8925596153	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0	
2021 PO8916496073	KU	7	35 UNK	SP	CRE	ED,EP,ID,IP	TD	00:00.0	
2021 PO8917496111	F	5	40 UNK	SP	CRE	ED	V	00:00.0	
2021 PO8912796161	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0	

2021 PO8930195853	KU	4	40 BRO	SP	P		V	00:00.0
2021 PO8937895811	KU	4	35 BRO	SP	CRE	ED	B	00:00.0
2021 PO8955695762	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8951195767	KU	4	40 KOP	SP	CCA		V	00:00.0
2021 PO8945195996	KU	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO8921396071	KU	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO8931796016	KU	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO8942395958	KU	4	40 UNK	SP	P	ED,ID,IP	BD	00:00.0
2021 PO8964395841	KU	5	35 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO8957495877	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO8976095909	F	5	40 UNK	SP	CRE	ED,ID	V	00:00.0
2021 PO8965795982	KU	5	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO8973895674	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8985995866	KU	5	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO8989695758	F	5	35 KOP	SP	P	ED	V	00:00.0
2021 PO8996595776	KU	3	50 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO8998295979	F	4	40 KOP	SP	P		V	00:00.0
2021 PO8998495949	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO9001095824	F	5	40 BRO	SP	CCA		V	00:00.0
2021 PO8989195971	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO8973396056	KU	5	35 ACW	SP	CRE	ED,ID	BD	00:00.0
2021 PO8965896097	KU	4	40 KOP	SP	CRE	ED	BD	00:00.0
2021 PO8961896171	F	5	40 KOP	SP	CRE	ED	V	00:00.0
2021 PO8956396148	KU	5	35 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO8949996236	F	4	40 KOP	SP	CRE	ED	V	00:00.0
2021 PO8930096343	F	6	35 KOP	SP	CRE	ED	V	00:00.0
2021 PO8949996182	KU	5	35 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO8940496235	KU	5	35 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO8931596271	KU	5	35 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8917796357	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO5444487339	KU	5	35 ACE	SP	CRE	ID,IP	X	00:00.0
2021 PO5533687374	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5492387353	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0
2021 PO4174386274	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4152384700	LGE	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4533404388	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4516004398	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4505404405	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5104923867	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO5121923504	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5107822188	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4170886263	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4171586264	F	4	35 BRO	SP	A		V	00:00.0
2021 PO1385744676	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4132986030	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4792603333	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4807903238	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4134786045	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3928615465	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO3920115245	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4148884733	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4148884737	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4150284732	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4152084736	LGE	4	45 ACE	SP	P	ED,ID	TD	00:00.0

2021 PO4150084737	LGE	4	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4147684890	F	1	20 ACE	SP	CRE		V	00:00.0
2021 PO7535257857	KU	4	40 UNK	SP	A	ID	TD	00:00.0
2021 PO7541557847	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7515557888	KU	3	45 UNK	SP	A	ID	BD	00:00.0
2021 PO7527358133	KU	6	30 UNK	SP	CRE		V	00:00.0
2021 PO7554958012	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO7545657991	F	4	40 UNK	SP	A		V	00:00.0
2021 PO9253667557	KU	2	50 BRO	SP	CRE		V	00:00.0
2021 PO9148267295	KU	2	70 BRO	SP	CCA		V	00:00.0
2021 PO9040566952	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9039566986	KU	1	70 BRO	SP	CCA		V	00:00.0
2021 PO8992866809	KU	2	60 BRO	SP	CCA		V	00:00.0
2021 PO8992666845	KU	1	65 BRO	SP	CCA		V	00:00.0
2021 PO4514803576	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3959214080	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4521503559	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4502103795	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3558822346	KU	5	35 KOP	SP	CCA		V	00:00.0
2021 PO3513121858	F	4	40 KOP	SP	P		V	00:00.0
2021 PO4010613215	KU	4	45 XXX	SP	CRE	ED,ID,IP,MD	TD	00:00.0
2021 PO3579422452	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3506421789	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO3534222244	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3557222451	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3515122006	F	4	40 KOP	SP	P		V	00:00.0
2021 PO9822568422	KU	4	45 BRO	SP	CRE		V	00:00.0
2021 PO9774368373	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9721668324	KU	2	60 BRO	SP	CCA		V	00:00.0
2021 PO9668568238	KU	3	50 BRO	SP	CRE		V	00:00.0
2021 PO9668268273	KU	2	55 BRO	SP	CRE		V	00:00.0
2021 PO9614968220	KU	2	50 BRO	SP	CRE		V	00:00.0
2021 PO9526168206	KU	1	65 BRO	SP	CRE	ED,EP,ID	VX	RP2 00:00.0
2021 PO9470768188	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9470968141	KU	3	50 BRO	SP	CCA		V	00:00.0
2021 PO9388567974	KU	3	45 BRO	SP	CRE		V	00:00.0
2021 PO9389167940	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9358567856	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9357967894	KU	3	60 BRO	SP	CCA		V	00:00.0
2021 PO9252967595	KU	2	70 BRO	SP	CCA		V	00:00.0
2021 PO7318054944	KU	5	35 UNK	SP	A	ID,SRS	TD	00:00.0
2021 PO7609959809	KU	2	55 BRO	SP	CRE	HH,ID	TD	00:00.0
2021 PO7626559974	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7641860136	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3987313226	KU	3	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7309355080	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO7336855298	KU	4	40 UNK	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO3616722625	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3590122432	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3600022468	KU	4	40 KOP	SP	P		BD	00:00.0
2021 PO3636622813	F	4	40 KOP	SP	P		V	00:00.0
2021 PO3593122319	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3596522365	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO3657522821	F	4	40 KOP	SP	P		V	00:00.0

2021 PO7804159797	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7786459755	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO7798459859	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7796059896	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4130986007	LGE	3	45 BRO	SP	A	ED,ID,MD	X	RP1	00:00.0
2021 PO4131586011	LGE	2	45 BRO	SP	CRE	ED,HH,ID,RB	X	RP1	00:00.0
2021 PO7542356818	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO7551656805	KU	6	30 UNK	SP	CCA		V		00:00.0
2021 PO5005602226	KU	7	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4132286016	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021 PO4133186011	LGE	4	25 BRO	SP	CRE	ED,HH,RB	X	RP1	00:00.0
2021 PO7729460935	KU	5	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7523057205	KU	4	40 UNK	SP	CRE	ID,MD	TD		00:00.0
2021 PO4133186024	LGE	1	55 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4806103080	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7525057602	KU	4	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO4828902939	KU	3	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO3893314565	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO3898314488	F	4	40 XXX	SP	P		V		00:00.0
2021 PO3901514774	KU	3	50 XXX	SP	CRE	ID	BD		00:00.0
2021 PO3907614929	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4133786028	LGE	1	70 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4143284736	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4812703482	KU	4	40 BRN	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021 PO4813903330	KU	4	40 BRN	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021 PO7818160172	F	4	40 BRO	SP	CRE		VX	PX	00:00.0
2021 PO7825960267	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4157286213	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO7478557467	KU	3	45 UNK	SP	A	ID	BD		00:00.0
2021 PO7482257715	KU	3	45 UNK	SP	A	ID,IP	TD		00:00.0
2021 PO7790760321	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7779960371	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4144684740	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4143384743	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4143584741	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4145986140	F	3	45 BRO	SP	A		V		00:00.0
2021 PO1757941434	KU	6	30 BRO	SP	CRE		V		00:00.0
2021 PO1732941489	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1747342110	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1760642659	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1786742898	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1709643556	KU	5	35 BRO	SP	CRE	ID	BD		00:00.0
2021 PO1688643978	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO1662244050	KU	4	45 BRO	SP	CRE	ID	BD		00:00.0
2021 PO1744743727	KU	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021 PO1764843854	KU	4	45 BRO	SP	CRE	ID	BD		00:00.0
2021 PO1739643895	KU	5	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7556358161	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO7789160269	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4137286044	LGE	1	85 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7767460457	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7756260445	F	5	30 BRO	SP	CRE		V		00:00.0
2021 PO7760660506	F	4	45 BRO	SP	CCA		V		00:00.0
2021 PO7774360293	F	4	40 BRO	SP	CRE		V		00:00.0



2021 PO7780760678	F	5	30 BRO	SP	CRE		V		00:00.0
2021 PO7779060801	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7783160926	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7787661059	KU	2	60 BRO	SP	CCA		V		00:00.0
2021 PO7789661053	KU	3	55 BRO	SP	CCA		V		00:00.0
2021 PO3936515663	KU	4	40 XXX	SP	CRE	ID,MD	BD		00:00.0
2021 PO3938315704	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3945315627	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4138186048	LGE	3	50 BRO	SP	A	ID	BD		00:00.0
2021 PO7773860648	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4783504374	KU	4	30 BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO4711604033	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4137286057-A	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7775360518	KU	6	35 BRO	SP	CRE		V		00:00.0
2021 PO7770060535	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7718560458	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO7730660562	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7723760504	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4136586054	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021 PO4137286057	LGE	3	45 BRO	SP	CRE	ED,HH,ID,IP,RB	X	RP1	00:00.0
2021 PO4140286111	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4140986109	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4142086094	LGE	2	85 BRO	ST	P		V		00:00.0
2021 PO4142886102	LGE	4	40 BRO	ST	CCA		V		00:00.0
2021 PO4143786110	LGE	2	80 BRO	SP	P		V		00:00.0
2021 PO4144686119	LGE	3	45 BRO	SP	P		V		00:00.0
2021 PO7698360884	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO7706560779	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO3957913378	KU	4	40 XXX	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021 PO3962613434	KU	5	35 XXX	SP	CRE	HH,ID,RB	X	RP1	00:00.0
2021 PO7408955579	KU	6	30 UNK	SP	CCA		V		00:00.0
2021 PO7394855721	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO7367555527	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO3774723736	F	4	40 KOP	SP	P		V		00:00.0
2021 PO3790624065	F	4	40 KOP	SP	P		V		00:00.0
2021 PO3753123583	F	4	40 KOP	SP	P		V		00:00.0
2021 PO3739023065	F	4	40 KOP	SP	P		V		00:00.0
2021 PO3717822980	F	4	40 KOP	SP	P		V		00:00.0
2021 PO3697622821	F	4	40 KOP	SP	P		V		00:00.0
2021 PO3877513411	KU	4	40 XXX	SP	CRE	ED,ID,MD	TX	RR	00:00.0
2021 PO7528456410	KU	6	30 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO7535356631	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO7534056736	KU	6	30 UNK	SP	CRE		V		00:00.0
2021 PO4176486312	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4177286299	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7783558910	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7787758888	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7788758968	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7797859067	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4178686300	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4178086296	F	4	40 BRO	SP	A		V		00:00.0
2021 PO9254115439	KU	2	70 KOP	SP	CRE		V		00:00.0
2021 PO9403315431	KU	2	75 BRN	SP	CRE		V		00:00.0
2021 PO9318115427	KU	2	55 KOP	SP	CRE		V		00:00.0

2021 PO9216515574	KU	5	35 KOP	SP	CCA		V	00:00.0
2021 PO9439715466	KU	2	70 BRN	SP	CRE		V	00:00.0
2021 PO9350015428	KU	2	70 BRN	SP	CRE		V	00:00.0
2021 PO9269315428	KU	2	70 KOP	SP	CRE		V	00:00.0
2021 PO9472415443	KU	4	50 BRN	SP	CRE		V	00:00.0
2021 PO9157215452	KU	3	50 KOP	SP	CRE		V	00:00.0
2021 PO9136115453	KU	3	55 KOP	SP	CRE		V	00:00.0
2021 PO9104515455	KU	3	55 KOP	SP	CRE		V	00:00.0
2021 PO9509415450	KU	2	70 BRN	SP	CRE		V	00:00.0
2021 PO9216715449	KU	3	55 KOP	SP	CRE		V	00:00.0
2021 PO9183215451	KU	3	55 KOP	SP	CRE		V	00:00.0
2021 7804159138A	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO7804159138	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7804159261	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4177586293	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4481604116	F	3	40 BRN	SP	P		V	00:00.0
2021 PO4481404253	F	4	40 BRN	SP	P	ED	V	00:00.0
2021 PO4482603868	F	3	40 BRN	SP	A		V	00:00.0
2021 PO4480904395	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4470403910	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4482103978	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4177986281	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4178486273	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4147984707	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4179186261	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4179786250	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4180486239	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO8877684846	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4181186226	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4147884703	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4146384695	LGE	7	25 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4146384704	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7814359253	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7819159316	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7821959465	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7825259390	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7838259279	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7811159316	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8875885249	KU	6	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8859885440-A	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO8869985154	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8859885440	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8810885643	KU	6	30 BRO	SP	CRE		V	00:00.0
2021 PO8649686854	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8724688484	KU	5	35 BRO	SP	CRE	EP	BX	RP2 00:00.0
2021 PO8718688931	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8698288863	KU	3	50 BRO	SP	CCA		V	00:00.0
2021 PO7809059473	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO7815159498	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7810059551	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7819059922	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4505404294	KU	7	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4525603391	KU	6	35 BRN	SP	CCA		V	00:00.0
2021 PO6557746476	KU	4	45 BRN	SP	CRE	ED	TD	00:00.0

2021 PO4163986033	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4123485242	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4164886044	LGE	2	55 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6935355397	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO4710402420	KU	3	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6960455096	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO6986754925	KU	5	35 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO4656002847a	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4640203605	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO7895859876	F	3	45 BRO	SP	CRE		V		00:00.0
2021 PO7883259954	F	3	45 BRO	SP	CRE		V		00:00.0
2021 PO7898359858	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO7902360135	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO7893859954	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO7873760016	F	3	45 BRO	SP	CRE		V		00:00.0
2021 PO7857060279	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4007485424	LGE	4	40 ACE	SP	P	ED	TD		00:00.0
2021 PO4006585414	LGE	4	40 ACE	SP	P	ED	TD		00:00.0
2021 PO4006285411	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO4006085409	LGE	4	30 ACE	SP	P	ED	BD		00:00.0
2021 PO4004985421	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO4004085426	LGE	4	40 ACE	SP	A	ED	TD		00:00.0
2021 PO4023785339	LGE	1 35E	ACE	CON	CRE		V		00:00.0
2021 PO5170656931	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO8901207454	KU	3	35 OTH	SP	CRE		V		00:00.0
2021 PO4134485148	LGE	4	30 ACE	SP	CRE	ED,EP,ID	TX	RR	00:00.0
2021 PO4134285140	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO4134085134	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4135985130	LGE	3	50 ACE	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021 PO4136485136	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4137985130	LGE	4	30 ACE	SP	CRE	ID	TD		00:00.0
2021 PO4137285122	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4138185109	LGE	7	25 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4138585115	LGE	3	50 ACE	SP	CRE	ED,HH,ID	BD		00:00.0
2021 PO4139885107	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5216157171	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5231157233	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5242157278	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5251857317	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4128885155	LGE	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO8861007740	KU	3	50 OTH	SP	CCA		V		00:00.0
2021 PO8857207600	KU	5	35 OTH	SP	CRE	ID	BD		00:00.0
2021 PO8847307753	F	5	35 OTH	SP	A		V		00:00.0
2021 PO8843607613	F	3	45 OTH	SP	A		V		00:00.0
2021 PO8905207420	KU	3	45 OTH	SP	CCA		V		00:00.0
2021 PO8906307292	KU	2	50 OTH	SP	CCA		V		00:00.0
2021 PO4000785314	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO8847807408-A	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO8814707376	F	4	45 OTH	SP	CRE		V		00:00.0
2021 PO8826307446	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO8826407387	KU	3	50 OTH	SP	CCA		V		00:00.0
2021 PO8836407397	KU	3	50 OTH	SP	CCA		V		00:00.0
2021 PO8847807408	F	3	50 OTH	SP	CCA		V		00:00.0
2021 PO8838607330	KU	6	30 OTH	SP	CRE	ID	TD		00:00.0

2021 PO4128985165	LGE	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO5256758065	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5230757935	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5244658004	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5263257368	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4001585319	F	4	40 BRN	SP	A		V		00:00.0
2021 PO3999485296	F	1	55 BRN	SP	CRE		V		00:00.0
2021 PO4128985169	LGE	2	55 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO3998985279	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO8872107139	KU	4	35 OTH	SP	CRE	ID,IP,SRS	TD		00:00.0
2021 PO8836107269	KU	6	30 OTH	SP	CCA		V		00:00.0
2021 PO3999885283	F	1	50 BRN	SP	CCA		V		00:00.0
2021 PO4000485284	F	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4000585270	F	1	50 BRN	SP	CCA		V		00:00.0
2021 PO4035485350	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4128885178	LGE	4	40 ACE	SP	CRE	ED,HH,ID	X	PX	00:00.0
2021 PO4131285166	LGE	4	30 ACE	SP	CCA	ID	TD		00:00.0
2021 PO4130885161	LGE	3	50 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4130785153	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO5276957427	KU	4	40 BRN	SP	CRE	ID,IP	TD		00:00.0
2021 PO5207157315	KU	4	40 BRN	SP	CRE	ED,ID	BX	RP2	00:00.0
2021 PO5292157483	KU	4	40 BRN	SP	CRE	ID,IP	TD		00:00.0
2021 PO5299257508	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5179657163	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4132385150	LGE	4	40 ACE	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4132285162	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4132585158	LGE	4	30 ACE	SP	CRE	ED,HH,ID	TD		00:00.0
2021 PO4133185155	LGE	4	30 ACE	SP	CRE	ID	TD		00:00.0
2021 PO4133985152	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4014585417	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4015185413	LGE	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4014585399	LGE	4	35 BRN	SP	CRE		V		00:00.0
2021 PO5262056440	KU	1	75 OTH	ST	CRE		V		00:00.0
2021 PO5371357181	KU	1	75 OTH	SP	CRE	ED,ID	BD		00:00.0
2021 PO5280356563	KU	1	75 OTH	SP	CRE		V		00:00.0
2021 PO5392057321	KU	1	75 OTH	ST	CRE		V		00:00.0
2021 PO5412757461	KU	1	75 OTH	ST	CRE		V		00:00.0
2021 PO5301056703	KU	1	75 OTH	SP	CCA		V		00:00.0
2021 PO5437157627	KU	2	70 OTH	SP	CRE		V		00:00.0
2021 PO5325856872	KU	1	80 OTH	ST	A		V		00:00.0
2021 PO5346557012	KU	1	75 OTH	SP	CCA		V		00:00.0
2021 PO8269563558	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO8953308123	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO8944107929	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO8976507181	KU	6	30 OTH	SP	CRE	ID	TD		00:00.0
2021 PO4013785386	LGE	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4111785186	LGE	3	50 ACE	SP	A	ID	BD		00:00.0
2021 PO8958907624	KU	6	30 OTH	SP	CRE	ID	BD		00:00.0
2021 PO8947707667	F	4	40 OTH	SP	CCA		V		00:00.0
2021 PO8927707664	F	3	45 OTH	SP	CCA		V		00:00.0
2021 PO4112485170	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO8269563558a1	KU	7	25 ACE	SP	CCA		V		00:00.0
2021 PO4012985373	LGE	4	35 BRN	SP	A		V		00:00.0
2021 PO4018185365	LGE	4	40 BRN	SP	CRE		V		00:00.0

2021 PO8915507651-A	KU	5	35 OTH	SP	CRE	ID,IP,SRS	TD		00:00.0
2021 PO8915507651	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO8910107520	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO4109485258	LGE	4	40 ACE	SP	A		V		00:00.0
2021 PO5263157742	KU	6	30 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5237858306	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4108385255	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4107285218	LGE	4	35 ACE	SP	A	ED,ID,IP	TD		00:00.0
2021 PO8901407809	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO8901607728	KU	6	30 OTH	SP	CCA	ID	BD		00:00.0
2021 PO8894707660	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO8883707668	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO5225158407	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5191158263	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4108685221	LGE	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO8916507665	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO8884207832	KU	5	35 OTH	SP	CRE	ID,IP,SRS	TD		00:00.0
2021 PO4017885342	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO4016385353	LGE	4	40 BRN	SP	A		V		00:00.0
2021 PO4015485360	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4015985364	LGE	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4018385416	LGE	3	45 BRN	SP	A		V		00:00.0
2021 PO4018285389	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4018185340	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4014085340	LGE	4	35 BRN	SP	CCA	ED,ID	BD		00:00.0
2021 PO5210858300	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5217358181	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5203458124	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5216657860	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4127485129	LGE	4	40 ACE	SP	CRE	ED,HH,ID	BX	RR	00:00.0
2021 PO4126085119	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4013185347	LGE	4	35 BRN	SP	CCA	ED,ID	BD		00:00.0
2021 PO4015285333	LGE	4	40 BRN	SP	CCA	ED,ID	BD		00:00.0
2021 PO8425363180	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO8877107736	F	2	50 OTH	SP	CCA		V		00:00.0
2021 PO8898007702	KU	3	50 OTH	SP	CCA		V		00:00.0
2021 PO8889707700	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO8870907846	KU	6	30 OTH	SP	CRE	ED,HH,ID	BX	RP2	00:00.0
2021 PO3999985304	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3999385308	LGE	4	25 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4000085317	LGE	4	25 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4128685139	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4129585177	LGE	4	30 ACE	SP	CRE	ED,HH,ID	X	PX	00:00.0
2021 PO4130085174	LGE	4	30 ACE	SP	P	ID	BD		00:00.0
2021 PO4129785166	LGE	3	50 ACE	SP	CCA	ED,ID,IP	TD		00:00.0
2021 PO4130885170	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4137285133	LGE	4	40 ACE	SP	CRE	ED,EP,ID	TX	RR	00:00.0
2021 PO5263057706	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4013685417	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4011985405	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021 PO9812474529	KU	2	55 OTH	SP	CRE	ID	BD		00:00.0
2021 PO9813474529	KU	2	55 OTH	SP	CRE	ID	BD		00:00.0
2021 PO3876985512	LGE	2	60 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO5942966316	LGE	1	50 ACE	SP	CCA		V		00:00.0

2021 PO3875685484	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO3876385496	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021 PO4992639155	KU	3	45 ESC	SP	CRE	ID	TD	00:00.0
2021 PO5181656185	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5162256219	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO3876885472	LGE	4	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO9812474529-B	KU	3	55 OTH	SP	CRE	ID	TD	00:00.0
2021 PO9812474529-A	KU	3	55 OTH	SP	CRE	ID	TD	00:00.0
2021 PO9924380081	KU	2	50 OTH	ST	A		V	00:00.0
2021 PO3878785466	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4064884831	LGE	4	30 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4082385139	LGE	3	90 ACE	SP	CRE		V	00:00.0
2021 PO4092684709	LGE	3	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5173656303	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5166156416	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5195256455	KU	4	40 BRN	SP	CRE	ID,IP	TD	00:00.0
2021 PO3880685460a	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3880685460	LGE	2	65 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4081585125	LGE	3	95 ACE	SP	CRE		V	00:00.0
2021 PO4080785112	LGE	3	65 ACE	SP	CRE		V	00:00.0
2021 PO4079985097	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4078885079	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4077885063	LGE	3	50 ACE	SP	P		V	00:00.0
2021 PO4077285053	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO3882385450	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO3882185451	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO3877585455	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO3878485450	LGE	3	55 ACE	SP	CCA		V	00:00.0
2021 PO3877885447	LGE	4	45 ACE	SP	CCA		V	00:00.0
2021 PO5915165507	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021 PO3879385293	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO3877985298	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO5904364594	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO5124141333A	KU	4	35 OTH	SP	P		V	00:00.0
2021 PO5094342091	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5041341638	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5130742147	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5057341830	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5144141264	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4047185067	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4047085059	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4045385060	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4048485059	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4050085050	F	5	25 BRO	SP	CRE		V	00:00.0
2021 PO4050085059	F	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4053385064	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4053085055	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4051585060	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8879208136	F	3	45 OTH	SP	CCA		V	00:00.0
2021 PO8881808074	F	5	35 OTH	SP	A		V	00:00.0
2021 PO8883507978	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021 PO4045485313	LGE	4	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4046985316	LGE	4	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4025185340	LGE	4	25 ACE	SP	CRE	ED,ID	TD	00:00.0

2021 PO4016385326	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4002985331	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO5142758247	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5134858516	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5151358684	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5169858686	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5183758721	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5192158574	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8883008415	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021 PO8888508326	KU	6	30 OTH	SP	CRE	ID,SRS	TD	00:00.0
2021 PO8885908187	F	6	30 OTH	SP	A		V	00:00.0
2021 PO8905508282	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO8913208357	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO8946408214	KU	3	45 OTH	ST	P		V	00:00.0
2021 PO8921708437	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO8960308321	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021 PO8954508240	KU	5	35 OTH	SP	CCA	ID	BD	00:00.0
2021 PO5156841217	F	2	50 UNK	SP	P		V	00:00.0
2021 PO3976785108	LGE	3	55 ACE	SP	CRE	ED,HH,ID	BD	00:00.0
2021 PO3978585117	LGE	2	55 ACE	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO4051085045	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4051485045	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4053685045	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO5154041229	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5152641165	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5145141070	F	2	45 UNK	SP	P		V	00:00.0
2021 PO4003285339	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4003385346	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4004385401	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4015685458	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3876985522	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4083985164	LGE	3	90 ACE	SP	CRE		V	00:00.0
2021 PO4054884660	LGE	3	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5076241974	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5040441609	KU	2	50 KOP	SP	CCA		V	00:00.0
2021 PO5123642242	KU	2	50 KOP	SP	CCA		V	00:00.0
2021 PO5134442124	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5124141333	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5134542289	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5043641723	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5076141495	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5095541431	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 PO5110842178	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5112441375	KU	2	45 BRN	SP	CCA		V	00:00.0
2021 PO5132942293	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5059341550	KU	2	50 OTH	SP	CCA		V	00:00.0
2021 PO5023939266	KU	3	45 ACW	SP	CRE	ID	TD	00:00.0
2021 PO5096740155	KU	2	50 UNK	SP	P	ID	TD	00:00.0
2021 PO5104740349	KU	2	50 UNK	SP	P	ID	TD	00:00.0
2021 PO5113540560	KU	2	50 UNK	SP	P	ID	TD	00:00.0
2021 PO5123240794	KU	2	45 UNK	SP	P	ID	TD	00:00.0
2021 PO5133940929	KU	2	45 UNK	SP	P	ID	TD	00:00.0
2021 PO4077185053	LGE	3	50 ACE	SP	P		V	00:00.0
2021 PO4110685997	LGE	3	45 ACE	SP	CCA		V	00:00.0

2021	PO5319787426	KU	4	45 ACE	SP	CRE	ID	TD	00:00.0
2021	PO5348287839	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0
2021	PO5461687336	KU	3	45 ACE	SP	CRE	ID	TD	00:00.0
2021	PO5444487289	KU	5	35 ACE	SP	CRE	ID	TD	00:00.0
2021	PO4126585904	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021	PO7960479886	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7953179799	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO7970579891	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO7962779635	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO7981379177	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO4596303279	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO4590703010	KU	3	50 BRN	SP	S		V	00:00.0
2021	PO4574103055	KU	4	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4578603101	KU	4	45 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO4586203176	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4127485919	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021	PO4127985928	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4128785940	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021	PO4129385952	LGE	2	50 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4128785972	LGE	4	40 BRN	SP	P	ID	BD	00:00.0
2021	PO4191086318	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO2469034395	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO5244702321	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4190086337	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4190586327	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BX	RR
2021	PO4189486348	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4188886358	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5237802880	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5241902442	F	5	45 BRN	SP	CCA		V	00:00.0
2021	PO0832557777	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO5237402697	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5231302633	F	5	35 BRN	SP	CCA		V	00:00.0
2021	PO4596906722	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4578706789	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4560206861	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4536306952	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4525206986	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4530007341	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4553007154	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4547907277	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4558207288	F	5	35 XXX	SP	CRE		V	00:00.0
2021	PO4559807230	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4576807139	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4591307064	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4600907034	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4604506988	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4620506826	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4614906824	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO4620706586	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4620906418	F	4	40 XXX	SP	CCA		V	00:00.0
2021	PO4621006344	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO0491250250	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO0483149530	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO3296701369	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0



2021 PO3298501379	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO3313501477	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO3311901051	KU	4	45 UNK	SP	CCA		V	00:00.0	
2021 PO0496150183	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	00:00.0	
2021 PO0486950292	KU	4	40 BRO	SP	CRE	ED,EP,ID	BD	00:00.0	
2021 PO4131186403	LGE	2	55 BRN	SP	CRE	ID,IP,SRS	TD	00:00.0	
2021 PO4129486304	LGE	3	45 BRN	SP	P	ID	TD	00:00.0	
2021 PO4135586280	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4131985976	LGE	2	55 BRN	ST	P		V	00:00.0	
2021 PO4128686261	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5275501369	F	3	40 BRN	SP	CRE		V	00:00.0	
2021 PO2268135022	KU	6	30 BRN	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO2261035149	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO9669615061	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5267503969	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5257704337	F	6	35E BRN	SP	CRE		V	00:00.0	
2021 PO5257404208	F	6	40 BRN	SP	CRE		V	00:00.0	
2021 PO5284803729	F	6	40 BRN	SP	CRE		V	00:00.0	
2021 PO5269003734	F	5	40 BRN	SP	CRE		V	00:00.0	
2021 PO4108855583	LGE	1	95 BRN	SP	P		V	00:00.0	
2021 PO4108885583	LGE	3	45 BRN	SP	S		V	00:00.0	
2021 PO4107885571	LGE	1	90 BRN	ST	P		V	00:00.0	
2021 PO4106985558	LGE	1	85 BRN	ST	P		V	00:00.0	
2021 PO4102085484	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4701806181	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4711606183	KU	6	30 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4728506191	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4746106200	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO9711914485A	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO9758014509	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO9711914485	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO9706114313	KU	3	45 ACW	SP	S		V	00:00.0	
2021 PO9705714001	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO4098985421	LGE	1	70 BRN	ST	P		V	00:00.0	
2021 PO4098285409	LGE	1	70 BRN	SP	CRE		V	00:00.0	
2021 PO7985081297	KU	5	30 BRO	SP	CCA		V	00:00.0	
2021 PO7988481410	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2983905941	KU	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO2986406322	KU	5	35 UNK	SP	CCA		V	00:00.0	
2021 PO3010406165	KU	5	35 UNK	SP	CCA		V	00:00.0	
2021 PO3010405991	KU	5	35 UNK	SP	CCA		V	00:00.0	
2021 PO3003005915	KU	5	35 UNK	SP	CCA		V	00:00.0	
2021 PO5298403956	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4097585395	LGE	1	70 BRN	ST	CRE		V	00:00.0	
2021 PO4096885383	LGE	1	70 BRN	ST	CRE		V	00:00.0	
2021 PO2914006014	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO2896406171	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0	
2021 PO7998880995	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4555403361	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO4565003369	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4191586346	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO5291802017	F	3	40 BRN	SP	CRE		V	00:00.0	
2021 PO5307502015	F	3	40 BRN	SP	CRE		V	00:00.0	
2021 PO7987080753	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0	

2021	PO7966480797	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2055633039	KU	4	45 BRN	SP	CRE		V	00:00.0
2021	PO5252801956	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4541903161	KU	6	30 BRN	SP	S	ED,SRC	TD	00:00.0
2021	PO4190886358	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO5262001533	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5263601406	F	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5264201333	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5258201712	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5259801636	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5254501876	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5242504595	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5242204504	F	4	40 BRN	SP	P		V	00:00.0
2021	PO5243604897	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO0477751142	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO7879377732	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7861477690	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7840677551	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7815477392	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7791477231	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7681375602	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO5244205075	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4184986419	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO3224902379	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO3237902206	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO3236202194	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4182886407	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021	PO4112986520	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4114986519	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO4183086415	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4184186415	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO3652807248	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO3647007108	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO2523630975	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO2511830895	KU	5	35 BRN	SP	CCA	ID	TD	00:00.0
2021	PO2528730418	KU	5	35 BRN	SP	P	ED,EP,ID,RB	VX PX	00:00.0
2021	PO2517830410	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO2521029930	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO2518329813	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO4110486524	LGE	3	50 BRN	SP	CRE		V	00:00.0
2021	PO4110586525	LGE	3	50 BRN	SP	CRE		V	00:00.0
2021	PO4110486522	LGE	1	50 BRN	SP	S		V	00:00.0
2021	PO4111086521	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO4109586523	LGE	4	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO4116586451	LGE	3	50 BRN	SP	CRE	ED,ID,IP,SRC	TX RR	00:00.0
2021	PO4117586516	LGE	4	25 BRN	SP	CCA		V	00:00.0
2021	PO4117086517	LGE	3	50 BRN	SP	CRE	ID	BD	00:00.0
2021	PO0507850574	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO0502750415	KU	4	40 BRO	SP	CRE	ED,EP,ID,MD	TD	00:00.0
2021	PO4127086257	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4127486262	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4185086351	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4183386376	F	2	55 BRO	SP	CCA		V	00:00.0
2021	PO0496550282	KU	5	35 BRO	SP	CRE	ED,EP,ID,SRS	TD	00:00.0

2021	PO0489549885	KU	4	40 BRO	SP	CCA			V	00:00.0
2021	PO4183786369	F	2	55 BRO	SP	CRE			V	00:00.0
2021	PO4188686288	F	2	55 BRO	SP	A			V	00:00.0
2021	PO0479449479	KU	6	30 BRO	SP	CCA			V	00:00.0
2021	PO2243035449	KU	3	35 BRN	SP	CRE	ID		TD	00:00.0
2021	PO4646006426	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO4662006433	F	4	40 XXX	SP	P			V	00:00.0
2021	PO4106285546	LGE	1	80 BRN	ST	P			V	00:00.0
2021	PO4105585533	LGE	1	85 BRN	ST	P			V	00:00.0
2021	PO4104785520	LGE	1	80 BRN	ST	CCA			V	00:00.0
2021	PO4104085508	LGE	1	75 BRN	ST	P			V	00:00.0
2021	PO4103385496	LGE	1	75 BRN	SP	P			V	00:00.0
2021	PO4102585484	LGE	1	80 BRN	SP	CRE			V	00:00.0
2021	PO4101185459	LGE	1	75 BRN	SP	P			V	00:00.0
2021	PO4100485445	LGE	1	70 BRN	ST	P			V	00:00.0
2021	PO4095185355	LGE	1	70 BRN	SP	CRE			V	00:00.0
2021	PO4091085286	LGE	1	75 BRN	SP	CRE			V	00:00.0
2021	PO4099785433	LGE	1	70 BRN	ST	P			V	00:00.0
2021	PO2281734954	KU	6	30 BRN	SP	CRE	ID		TD	00:00.0
2021	PO2281734954A1	KU	6	35 BRN	SP	CRE	ID		BD	00:00.0
2021	PO4518903272	KU	4	40 BRN	SP	CRE	ED,ID,RB		BX	00:00.0
2021	PO7965479142	KU	4	40 BRO	SP	CRE	ED,HH,ID,IP		BX	00:00.0
2021	PO4095985369	LGE	1	70 BRN	SP	CRE			V	00:00.0
2021	PO4094385342	LGE	1	70 BRN	SP	CRE			V	00:00.0
2021	PO4093485328	LGE	1	70 BRN	SP	CRE			V	00:00.0
2021	PO2090533609	KU	6	30 BRN	SP	CRE			V	00:00.0
2021	PO2083033534	KU	5	35 BRN	SP	CRE	ED,ID,IP		BD	00:00.0
2021	PO2038133982	KU	4	40 BRN	SP	CRE			V	00:00.0
2021	PO2038933764	KU	4	40 BRN	SP	CRE			V	00:00.0
2021	PO4091885300	LGE	1	70 BRN	SP	P			V	00:00.0
2021	PO4092785314	LGE	1	70 BRN	ST	P			V	00:00.0
2021	PO4090285272	LGE	1	75 BRN	SP	CRE			V	00:00.0
2021	PO9034975602	LGE	4	35 BRO	SP	CCA			V	00:00.0
2021	PO4192386336	LGE	4	30 BRO	SP	CCA			V	00:00.0
2021	PO2615706578	KU	2	60 UNK	SP	CRE	ID		BD	00:00.0
2021	PO2617506567	KU	2	60 UNK	SP	CRE	ID		BD	00:00.0
2021	PO4565003216	KU	4	40 BRN	SP	S	ED,ID,SRC		TD	00:00.0
2021	PO4538603738	KU	4	40 BRN	SP	CRE	ED,ID		TD	00:00.0
2021	PO5251302026	F	3	45 BRN	SP	CCA			V	00:00.0
2021	PO2081033197	KU	4	45 BRN	SP	CRE			V	00:00.0
2021	PO2085133146	KU	6	30 BRN	SP	CRE	ID		TD	00:00.0
2021	PO2088433172	F	4	40 BRN	SP	CCA			V	00:00.0
2021	PO2080133063	KU	6	30 BRN	SP	CRE	ID		TD	00:00.0
2021	PO2071932631	KU	4	40 BRN	SP	CRE			BD	00:00.0
2021	PO9705813753	KU	4	40 ACW	SP	S			V	00:00.0
2021	PO9705713465	KU	4	40 ACW	SP	S			V	00:00.0
2021	PO9705713237	KU	3	45 ACW	SP	S			V	00:00.0
2021	PO9706512958	KU	4	40 ACW	SP	CRE	ED,ID		TD	00:00.0
2021	PO9728113084	KU	4	40 ACW	SP	CRE	ED,ID,IP		TD	00:00.0
2021	PO9697712960	KU	3	45 ACW	SP	S			V	00:00.0
2021	PO9681912453	KU	3	45 ACW	SP	S			V	00:00.0
2021	PO9703412616	KU	4	40 ACW	SP	CRE	ED,ID		TD	00:00.0
2021	PO4192386297	LGE	4	40 BRO	SP	A	ID,IP		BD	00:00.0
2021	PO5247302201	F	4	45 BRN	SP	CCA			V	00:00.0

2021	PO5297101200	F	7	40 BRN	SP	CRE		V		00:00.0
2021	PO5339100869	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO2408133282	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021	PO4121086267	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO0520250473	KU	4	40 BRO	SP	P	ED,ID,MD,SRS	TD		00:00.0
2021	PO0511850487	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4130886048	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021	PO4131386045	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021	PO4131986041	LGE	3	50 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4132086041	LGE	3	50 BRN	SP	CRE	ED,ID,IP,SRS	TD		00:00.0
2021	PO4182586389	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO7966279254	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO7972279181	KU	6	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4184586361	F	2	55 BRO	SP	CRE		V		00:00.0
2021	PO4126486263	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4533303609	KU	4	40 BRN	SP	CRE	ED,ID	BX	PX	00:00.0
2021	PO4158585352	LGE	6	25 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4158685355	LGE	4	40 BRN	SP	P	ID	BD		00:00.0
2021	PO4158285353	LGE	3	50 BRN	SP	CCA		V		00:00.0
2021	PO4158685358	KU	3	45 BRN	SP	S		V		00:00.0
2021	PO7204984768	KU	4	40 BRO	SP	CRE	ED,EP,HH,ID,RB	BX	RP3	00:00.0
2021	PO4572107343	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4561907380	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4554804669	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		00:00.0
2021	PO7204384718	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO7253884933	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4523904695	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4538804683	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		00:00.0
2021	PO2578114314	KU	3	45 BRN	SP	CCA		V		00:00.0
2021	PO2587414021	KU	5	35 BRN	SP	CCA		V		00:00.0
2021	PO2578914272	KU	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO2588714031	KU	4	40 BRN	SP	CCA	ED,ID,IP	BD		00:00.0
2021	PO4191386443	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4567798723	KU	2	55 UNK	SP	CCA		V		00:00.0
2021	PO4566198639	KU	2	55 UNK	SP	CCA		V		00:00.0
2021	PO4590998618	KU	4	45 UNK	SP	CCA		V		00:00.0
2021	PO4615698591	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO4641398561	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO4570598216	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO5205404497	KU	7	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO2495515657	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021	PO4011284083	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO9371556833	F	5	30 BRO	SP	P		V		00:00.0
2021	PO9379057014	ODP	4	45 BRO	SP	S		V		00:00.0
2021	PO3934285812	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO3935085824	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO3935785837	LGE	4	40 ACE	SP	A		V		00:00.0
2021	PO3936085840	F	4	40 ACE	SP	A		V		00:00.0
2021	PO3942185770	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO3940685778	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO3940385736	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO3939685739	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO3938085749	LGE	4	40 ACE	SP	P		V		00:00.0
2021	PO3934985734	F	4	35 ACE	SP	A		V		00:00.0

2021 PO3932285642	LGE	4	40 ACE	SP	P		V	00:00.0
2021 PO3983685740	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO3986685719	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO5221831013	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5243630937	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5246030930	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5258130401	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5254030272	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO5261530266	KU	2	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5266530296	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5276730224	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5225230209	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3916885815	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PV3915985803	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3915285791	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3918185787	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3917485776	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3918085808	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PV3919085803	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3920385795	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3921085790	F	UNK	55 BRO	SP	CRE		V	00:00.0
2021 3922385715A	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3928685719	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3927885706	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3926785689	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3924285703	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3922385715	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO6448010425	KU	4	40 ACW	SP	S		V	00:00.0
2021 PO6442310263	KU	4	45 ACW	SP	S		V	00:00.0
2021 PO6470710862	KU	6	30 ACW	DF	CRE	ED,ID	TD	00:00.0
2021 PO3956486505	LGE	4	30 ACE	SP	A	ID	TD	00:00.0
2021 PO3955886505	LGE	4	30 ACE	SP	CRE	ED,HH,ID	BD	00:00.0
2021 PO3955086503	LGE	4	40 ACE	SP	A	ID	BD	00:00.0
2021 PO3955186497	LGE	4	30 ACE	SP	P	ID	BD	00:00.0
2021 PO3952086467	LGE	6	30 ACE	SP	CRE		V	00:00.0
2021 PO3952786478	LGE	4	30 ACE	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO3949986448	LGE	4	30 ACE	SP	CRE	ID	TD	00:00.0
2021 PO5508835443	KU	3	50 UNK	SP	CRE	ID	BD	00:00.0
2021 PO3950386432	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PV3948486439	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3922385931	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4075786270	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO3940986347	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO3939486335	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3983485815	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3983585827	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3943586318	LGE	4	30 ACE	SP	P	ID	TD	00:00.0
2021 PO3952686418	LGE	4	30 ACE	SP	A	ID	BD	00:00.0
2021 PO5055730823	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5052630805	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5064530631	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5070630543	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5074430506	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5089330394	KU	3	45 BRN	SP	CCA		V	00:00.0

2021 PO5103830311	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5117430234	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 PO4074086293	LGE	5	30 BRO	SP	CCA		V	00:00.0
2021 PO4072286296	LGE	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4072186289	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4073886283	F	5	40 BRO	SP	CRE		V	00:00.0
2021 PO4074286274	LGE	UNK	60 BRO	SP	CRE		V	00:00.0
2021 PO4073586279	LGE	UNK	70 BRO	SP	CRE		V	00:00.0
2021 PO4072086283	LGE	UNK	65 BRO	SP	CRE		V	00:00.0
2021 PO3983285803	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3982785780	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3981585772	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3980485781	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3983885838	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4070686285	LGE	UNK	65 BRO	SP	CRE		V	00:00.0
2021 PO4070786290	F	5	30 BRO	SP	CCA		V	00:00.0
2021 PO4070986297	LGE	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4069086299	LGE	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4067686302	LGE	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4068986290	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4067686291	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4068886286	LGE	2	65 BRO	SP	CRE		V	00:00.0
2021 PO4067486287	LGE	UNK	65 BRO	SP	CRE		V	00:00.0
2021 PO3952486413	LGE	4	30 ACE	SP	P	ID	TD	00:00.0
2021 PO4066286288	LGE	UNK	65 BRO	SP	CRE		V	00:00.0
2021 PO4066386292	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4065186293	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO5119130252	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5129130123	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5144030102	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5147930145	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5152730265	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5161930470	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5158230383	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 PO5164330402	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 Po5164330402a	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5178930394	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5199830321	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5216430214	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5223830186	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3982985791	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3959386509	LGE	4	30 ACE	SP	A	ID	BD	00:00.0
2021 PO3959286516	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3956986496	LGE	4	30 ACE	SP	A		V	00:00.0
2021 PO4065086288	LGE	UNK	60 BRO	SP	CRE		V	00:00.0
2021 PO4063686290	LGE	UNK	60 BRO	SP	CRE		V	00:00.0
2021 PO4063886293	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4062386290	LGE	UNK	65 BRO	SP	CRE		V	00:00.0
2021 PO4062686294	F	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4061186295	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO3980185791	LGE	4	35 ACE	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021 PO3980885797	LGE	4	30 ACE	SP	CRE	ED,ID,RB	BX RP1	00:00.0
2021 PO3980185798	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3980185813	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0

2021 PO3980185828	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3980385839	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3989285940	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3989085928	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4014786148	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4061086291	LGE	UNK	75 BRO	SP	CRE		V	00:00.0
2021 PO3927485753	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3927285751	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO5309630526	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5328930473	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO5342830436	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO5346830544	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO5337630184	KU	6	30 BRN	SP	CRE	ED,ID,RB	X RP2	00:00.0
2021 PO5273430305	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5276530299	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5280430343	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5283630448	KU	3	45 BRN	SP	CRE	ID	BX PX	00:00.0
2021 PO5285930522	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO5286931059	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5274830917	KU	5	35 BRN	SP	CRE	ID,MD	TD	00:00.0
2021 PO5279630830	KU	3	45 BRN	SP	CRE	ID	X RP3	00:00.0
2021 PO5271230803	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5085236272	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5854910442	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO5805710102	KU	6	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO3937385842	F	3	65 ACE	SP	A		V	00:00.0
2021 PO3936785850	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3936585847	F	UNK	60 ACE	SP	CRE		V	00:00.0
2021 PO3935285854	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3934385859	F	4	55 BRO	SP	CRE		V	00:00.0
2021 PO3933285866	F	UNK	55 BRO	SP	CRE		V	00:00.0
2021 PO3933485869	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO3932385876	F	5	30 BRO	SP	CCA		V	00:00.0
2021 PO3932285871	F	3	55 BRO	SP	CRE		V	00:00.0
2021 PO4012585861	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4013585883	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4013085871	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3916185890	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3916985902	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3917485911	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO3918285923	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3917885926	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO3918885932	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO3918485936	LGE	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5201536997	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4936436466	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO5506310008	F	4	40 KOP	SP	P		V	00:00.0
2021 PO5601010371	KU	4	40 KOP	SP	S		V	00:00.0
2021 PO5601910280	KU	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO5499309997	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5602710191	KU	3	45 KOP	SP	S		V	00:00.0
2021 PO5717910285	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5490309982	F	6	30 KOP	SP	S		V	00:00.0
2021 PO5600310452	KU	4	35 KOP	SP	S		V	00:00.0

2021	PO5483009965	F	4	35 KOP	SP	S			V	00:00.0
2021	PO5511310016	F	4	40 KOP	SP	S			V	00:00.0
2021	PO5465809794	KU	3	45 KOP	SP	S			V	00:00.0
2021	PO5484510294	KU	2	50 KOP	SP	S			V	00:00.0
2021	PO5485910163	F	3	45 KOP	SP	S			V	00:00.0
2021	PO4943436635	KU	5	35 BRO	SP	CRE	ID		TD	00:00.0
2021	PO4949436779	KU	4	40 CAH	SP	CRE	ID		BD	00:00.0
2021	PO4958436815	KU	4	40 KOP	SP	CRE	ID		TD	00:00.0
2021	PO4019285965	LGE	4	35 ACE	SP	CCA			V	00:00.0
2021	PO3983585701	LGE	4	40 ACE	SP	CCA			V	00:00.0
2021	PO3985085721	LGE	4	30 ACE	SP	CCA			V	00:00.0
2021	PO4976836736	KU	4	40 UNK	SP	CRE	ID		TD	00:00.0
2021	PO4032686149	LGE	3	45 ACE	SP	CRE	ED,ID,IP		BD	00:00.0
2021	PO4996636651	KU	4	40 KOP	SP	CRE	ID		TD	00:00.0
2021	PO5028636516	KU	3	45 BRO	SP	CCA			B	00:00.0
2021	PO5062636449	F	2	45 CPT	SP	P			V	00:00.0
2021	PO5059736383	F	3	45 BRO	SP	CCA			V	00:00.0
2021	PO5042636457	KU	3	45 BRO	SP	CCA			B	00:00.0
2021	PO5058236346	KU	3	45 UNK	SP	CRE	ID		TD	00:00.0
2021	PO4014085894	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4014485904	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4014985916	F	4	40 ACE	SP	P			V	00:00.0
2021	PO4015585928	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4016485934	F	4	30 ACE	SP	CRE			V	00:00.0
2021	PO4015985937	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4016485949	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4016985960	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4017485971	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4016985976	LGE	4	35 ACE	SP	P	ED,HH,ID,RB		BX	RP1 00:00.0
2021	PO3930285888	LGE	4	30 BRO	SP	CCA			T	00:00.0
2021	PO3930085884	F	UNK	55 BRO	SP	CRE			V	00:00.0
2021	PO3928685892	F	4	40 BRO	SP	CRE	ED,ID		BX	RP3 00:00.0
2021	PO5157536756	KU	3	45 CAH	SP	CRE	ID		BD	00:00.0
2021	PO5156436877	KU	3	45 UNK	SP	CRE	ID		BD	00:00.0
2021	PO4018185987	F	4	40 ACE	SP	P	ED,EP,MD		V	00:00.0
2021	PO4018385991	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO7317771667	LGE	3	45 ACE	SP	P	ED,ID		BD	00:00.0
2021	PO4018685996	F	4	30 ACE	SP	CCA			V	00:00.0
2021	PO3927885897	F	2	60 BRO	SP	CCA			V	00:00.0
2021	PO3928185901	F	4	40 BRO	SP	CRE			V	00:00.0
2021	PO3926985903	F	4	35 BRO	SP	CRE			V	00:00.0
2021	PO3927185906	F	4	40 BRO	SP	A			V	00:00.0
2021	PO3925685910	F	4	35 BRO	SP	CRE			V	00:00.0
2021	PO3925985913	F	3	45 BRO	SP	CCA			V	00:00.0
2021	PO3924885920	F	4	40 BRO	SP	CRE			V	00:00.0
2021	PO3923885926	F	4	40 BRO	SP	CCA			V	00:00.0
2021	PO3923485922	F	4	40 BRO	SP	CRE			V	00:00.0
2021	PO4019685976	LGE	7	25 ACE	SP	CRE	ED,ID,IP		BD	00:00.0
2021	PO4021385974a	KU	4	35 ACE	SP	P	ED,ID		TD	00:00.0
2021	PO4020085982	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO5205437145	KU	3	45 KOP	SP	CCA			T	00:00.0
2021	PO3978585842	LGE	7	65 ACE	SP	CRE			V	00:00.0
2021	PO5208637279	KU	3	45 UNK	SP	CRE	ID		TD	00:00.0
2021	PO3932785772	LGE	4	30 BRO	SP	CRE	ED,ID		TD	00:00.0



2021	PO3926585760	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO3928085751	LGE	7	25 BRO	SP	CRE	ED,EP,HH,ID,IP	BX	RP3	00:00.0
2021	PO5213437471	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021	PO5206737663	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021	PO4018685887	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4019085884	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4017485883	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4016985872	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4016485861	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4016085850	F	4	40 ACE	SP	P		V		00:00.0
2021	PO3924485749	F	4	25 BRO	SP	CCA		V		00:00.0
2021	PO3925485765	F	3	45 BRO	SP	CCA		V		00:00.0
2021	PO3924885764	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021	PO3924585770	F	4	40 BRO	SP	A		V		00:00.0
2021	PO3924885788	LGE	4	30 BRO	SP	CRE		V		00:00.0
2021	PO3924785800	F	3	45 BRO	SP	CRE		V		00:00.0
2021	PO3924385793	F	4	40 BRO	SP	A		V		00:00.0
2021	PO3923385771	F	4	35 BRO	SP	CRE	ED,ID	BX	RP3	00:00.0
2021	PO3922185759	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO3932085862	F	4	30 BRO	SP	CRE		V		00:00.0
2021	PO3931685863	F	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4015585838	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4015085828	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4014585817	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4014085805	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4013485793	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4012985782	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4474849373	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO4455149385	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO4435549400	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO4415549409	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO4156885446	LGE	4	35 BRO	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO4156785441	LGE	6	25 BRO	SP	CRE	ED,HH,ID	TD		00:00.0
2021	PO9394501301	KU	3	45 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021	PO9393801309	KU	3	45 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO9383601158	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO9382801165	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO9353400762	KU	3	45 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021	PO9304300321	KU	4	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO9278400226	KU	3	45 UNK	SP	CRE	ID,IP	TD		00:00.0
2021	PO9255400141	KU	3	55 UNK	SP	CRE	ID	TD		00:00.0
2021	PO4005443488	KU	6	30 KOP	SP	CRE	ID	BD		00:00.0
2021	PO4004842973	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO3818046249	KU	6	30 UNK	SP	CRE	ID	BD		00:00.0
2021	PO3778846467	KU	3	40 UNK	SP	CRE	ID	TD		00:00.0
2021	PO4155885456	LGE	4	35 BRO	SP	P	ID	TD		00:00.0
2021	PO4155585462	LGE	4	35 BRO	SP	P	ID	BD		00:00.0
2021	PO4155685479	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4181285244	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4182885419	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021	PO4184485275	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4166786192	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4164886171	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO3951142690	KU	4	35 UNK	SP	CRE	ED,ID,MD,RB	X	RP1	00:00.0

2021 PO4176685253	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4182985276	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4164186153	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4164986165	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO3975442708	KU	4	40 INP	SP	CRE	ID	TD		00:00.0
2021 PO4164986152	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4154485447	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO9558201610	KU	4	45 UNK	SP	CRE	ID,IP,SRS	TD		00:00.0
2021 PO9523701687	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO9499701741	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO9482701779	KU	3	45 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021 PO9447001860	KU	2	55 UNK	SP	CRE		V		00:00.0
2021 PO4548249687	KU	5	35 BRN	SP	CRE	ED,EP	X	RP2	00:00.0
2021 PO4176585299	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4154285439	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO3854941582	KU	4	45 BRO	SP	CCA		B		00:00.0
2021 PO6972908990	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO7036509143	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO7037008564	KU	4	35 ACW	SP	S		V		00:00.0
2021 PO7022908785	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7017808868	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO7057308802	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO7043508825	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6974508703	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6954208817	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6935708656	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO7007109403	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO7010209375	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO69333508442	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6931208210	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6930208060	KU	5	35 ACW	SP	S		V		00:00.0
2021 PO6982008113	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6962408148	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6948208173	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO7023809256	KU	4	40 ACW	SP	CCA		V		00:00.0
2021 PO4166486180	F	4	30 BRO	SP	CRE		V		00:00.0
2021 PO3808941556	KU	4	40 BRO	SP	CCA		B		00:00.0
2021 PO3822941187	KU	4	40 BRO	SP	CCA		B		00:00.0
2021 PO3823741516	KU	4	40 BRO	SP	CCA		B		00:00.0
2021 PO4176685289	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4166786183	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	X	RP1	00:00.0
2021 PO4166386092	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PV4182885412	LGE	4	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4154685453	LGE	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021 PO4164886140	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4022543284	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO4156385484	LGE	4	35 BRO	SP	P	ID	BD		00:00.0
2021 PO9414701532	KU	4	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO9415501524	KU	4	40 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021 PO4156985461	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4180785245	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4155885496	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4171785465	LGE	6	25 BRO	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021 PO4552649728	KU	6	35 BRN	SP	CRE	ID	TD		00:00.0

2021 PO4549749775	KU	6	35 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4544949601	KU	3	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4164786102	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4179585247	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4178185249	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4160186096	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4161086096	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4114285103	LGE	4	40 BRO	SP	P	ID	BD		00:00.0
2021 PO4114085133	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4116585149	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4162386095	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4176885251	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4171285260	LGE	3	45 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4172285259	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4157286088	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4117885149	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4175685253	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4157186097	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4118485288	LGE	4	40 BRO	SP	CRE	ID	TX	RR	00:00.0
2021 PO3773946238	KU	3	50 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3837443294	KU	6	30 UNK	SP	CRE		V		00:00.0
2021 PO4173285257	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4174685255	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4157486104	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4118285276	LGE	4	30 BRO	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021 PO4118785276	LGE	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO4118985262	LGE	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021 PO4118685253	LGE	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO4158286097	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4176185242	LGE	7	25 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4176585240	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4176685234	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4159086096	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4169386092	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4170386091	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4171386091	F	4	40 BRO	SP	A		V		00:00.0
2021 PO0540705214	KU	2	60 UNK	SP	CRE		V		00:00.0
2021 PO0541705216	KU	2	60 UNK	SP	CRE		V		00:00.0
2021 PO0441605750	KU	4	40 UNK	ST	P		V		00:00.0
2021 PO3757447089	F	4	45 KOP	SP	P		V		00:00.0
2021 PO4701550501	KU	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4176685311	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4168985302	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4169085301	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3728746936	F	4	45 KOP	SP	P		V		00:00.0
2021 PO3700146778	F	4	45 KOP	SP	P		V		00:00.0
2021 PO3678746936	F	3	50 KOP	SP	P		V		00:00.0
2021 PO3665947026	F	4	40 UNK	SP	P		V		00:00.0
2021 PO3657547017	KU	4	40 UNK	SP	P	ID	B		00:00.0
2021 PO3678747199	KU	4	45 UNK	SP	CCA		B		00:00.0
2021 PO3624351797	F	5	35 UNK	SP	P		V		00:00.0
2021 PO3638151747A	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3638151747	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO0390605749	F	3	45 UNK	SP	CRE		V		00:00.0

2021 PO0607302863	KU	3	40 UNK	SP	CRE	EP,ID,SRS	TX	RR	00:00.0
2021 PO0583501216	KU	3	40 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021 PO0596900605	KU	4	35 UNK	SP	CRE		V		00:00.0
2021 PO0592400810	KU	4	35 UNK	SP	CRE	ID	TD		00:00.0
2021 PO6085710184	KU	6	30 ACW	SP	S		V		00:00.0
2021 PO6074112321	KU	2	50 ACW	SP	S		V		00:00.0
2021 PO8405116295	KU	5	45 ACW	SP	S		V		00:00.0
2021 PO4168985289	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO0603600302	KU	2	60 UNK	SP	CCA		V		00:00.0
2021 PO0592900081	KU	3	55 UNK	SP	CCA		V		00:00.0
2021 PO0577901468	KU	1	65 UNK	SP	CCA		V		00:00.0
2021 PO3672653230	KU	5	35 BRN	SP	S		V		00:00.0
2021 PO3645452020	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3653352301	KU	3	50 BRN	SP	S		V		00:00.0
2021 PO3658952482	KU	4	45 BRN	SP	CRE		V		00:00.0
2021 PO3664152766	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3668753009	KU	5	35 BRN	SP	S		V		00:00.0
2021 PO3675953414	KU	4	40 BRN	SP	S		V		00:00.0
2021 PO3671653656	KU	5	35 BRN	SP	S		V		00:00.0
2021 PO3667753867	KU	5	35 BRN	SP	S		V		00:00.0
2021 PO3664654032	KU	4	45 KOP	SP	CRE	ID	BD		00:00.0
2021 PO4168885280	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4168885271	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO0586801774	KU	3	50 UNK	SP	CRE	ID	TD		00:00.0
2021 PO0594502037	KU	4	45 UNK	SP	CRE	ID	TD		00:00.0
2021 PO0601102262	KU	4	35 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4167685260	LGE	4	40 ACE	SP	CRE	ED,HH,ID	BD		00:00.0
2021 PO4166685262	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO0607502481	KU	3	45 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021 PO0599303140	KU	4	35 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021 PO0600303143	KU	4	35 UNK	SP	CRE	ID,SRS	TD		00:00.0
2021 PO0612902665	KU	3	55 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO3699553678	KU	4	40 INP	SP	CRE	ID	BD		00:00.0
2021 PO3624554212	KU	4	45 BRO	SP	CCA		B		00:00.0
2021 PO4166085266	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4165685275	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4165485288	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO3621054412	KU	4	45 BRO	SP	CCA		B		00:00.0
2021 PO3614354588	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021 PO3696152379	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO0582803723	KU	3	40 UNK	SP	CRE	ID,IP	TD		00:00.0
2021 PO0574404018	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO0568104280	KU	4	45 UNK	SP	CCA	SRS	TD		00:00.0
2021 PO4165485297	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4165585307	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4690950454	KU	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4680050409	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4681450362	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO4670250379	KU	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4659950360	KU	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4652750345	KU	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4643550324	KU	5	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4634950299	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO3728952265	KU	3	45 BRO	SP	CCA		V		00:00.0

2021 PO3755152174	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4165685315	LGE	4	35 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO3749951571	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3781052110	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3726951860	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3751151921	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4166485313	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4167385312	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4168285311	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO3673750470	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3678350582	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4169185309	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4170185298	LGE	5	25 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4170285303	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO3671550806	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3658651238	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3651451409	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3644451583	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3765347964	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4176685299	LGE	1	20 ACE	SP	A		V		00:00.0
2021 PO4712650549	KU	5	45 BRN	SP	CRE	ED,HH,RB	X	RP2	00:00.0
2021 PO4146185194	LGE	4	40 BRO	SP	CRE	ED,ID	X	RP2	00:00.0
2021 PO4165186202	F	4	40 BRO	SP	CRE	ID,RB	VX	RP1	00:00.0
2021 PO4167886170	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4169086170	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4169086175	F	6	25 BRO	SP	A		V		00:00.0
2021 PO4179085332	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4151685224	LGE	7	25 BRO	SP	CRE		V		00:00.0
2021 PO4163086216	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4163686225	F	4	35 BRO	SP	A		V		00:00.0
2021 PO4164086208	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4166186202	F	4	30 BRO	SP	A		V		00:00.0
2021 PO4165886198	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4160886194	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4161686202	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4162486210	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4149885260	LGE	7	25 BRO	SP	CRE		V		00:00.0
2021 PO4162386163	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4161586156	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4160286156	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4729949719	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4746949659	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4769349759	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4734449447	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4751949314	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4726951711	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4743851602	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4760151497	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4733351266	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4743050978	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4763651069	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4755650844	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4166086133	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4166186134	F	4	40 BRO	SP	CRE		V		00:00.0

2021 PO4166186143	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4166286154	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4166286163	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4166286171	F	3	45 BRO	SP	A	V	00:00.0
2021 PO4760050450	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4756250420	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4618350428	F	3	45 BRN	SP	A	V	00:00.0
2021 PO4629750702	F	4	40 BRN	SP	A	V	00:00.0
2021 PO4622450558	F	4	40 BRN	SP	A	V	00:00.0
2021 PO4621050516	F	4	40 BRN	SP	A	V	00:00.0
2021 PO4121005258	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO4118605472	KU	3	45 KOP	SP	CCA	V	00:00.0
2021 PO4577310173	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO0901146416	F	3	45 BRN	SP	CCA	V	00:00.0
2021 PO0956647281	F	4	40 BRN	SP	P	V	00:00.0
2021 PO0936047055	F	4	40 BRN	SP	P	V	00:00.0
2021 PO0917346846	F	4	40 BRN	SP	A	V	00:00.0
2021 PO0945546959	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4109185802	F	1	50 BRN	SP	CCA	V	00:00.0
2021 PO0994247674	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4100006581	KU	5	35 KOP	SP	P	V	00:00.0
2021 PO1005647667	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO1017447626	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO1028047550	F	4	40 BRN	SP	P	V	00:00.0
2021 PO1066747820	KU	3	45 BRN	SP	CRE	V	00:00.0
2021 PO4159686261	LGE	4	30 BRO	SP	CRE	V	00:00.0
2021 PO3964306273	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO3965906472	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO4129286188	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4128886169	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4130086192	F	4	35 BRN	SP	CRE	V	00:00.0
2021 PO4130386197	F	4	35 BRN	SP	CRE	V	00:00.0
2021 PO4130786205	F	4	35 BRN	SP	CRE	V	00:00.0
2021 PO4131986227	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4132386236	F	4	35 BRN	SP	CRE	V	00:00.0
2021 PO4133086249	F	4	35 BRN	SP	CRE	V	00:00.0
2021 PO4132886245	F	3	45 BRN	SP	P	V	00:00.0
2021 PO4133886263	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4193786273	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4194386279	F	2	55 BRO	SP	CRE	V	00:00.0
2021 PO4191086246	F	H1	65 BRO	SP	P	V	00:00.0
2021 PO4191786253	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4192086256	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4192786263	F	2	60 BRO	SP	CCA	V	00:00.0
2021 PO4605610658A	F	5	35 XXX	SP	CRE	V	00:00.0
2021 PO4194786275	F	6	25 BRO	SP	CRE	V	00:00.0
2021 PO4612310419	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4619810589	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO8770490597	KU	6	30 BRO	SP	S	V	00:00.0
2021 PO4605610658	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO6765218774	KU	4	40 ACW	SP	S	V	00:00.0
2021 PO6718019567	KU	6	30 ACW	SP	CRE	V	00:00.0
2021 PO5075203015	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4196286299	LGE	4	40 BRO	SP	CRE	ED,ID,IP TX RR	00:00.0

2021 PO0558949761	KU	4	45 BRO	SP	CRE	ED,EP,ID,IP	TX	RR	00:00.0
2021 PO4568110699	KU	4	45 XXX	SP	CRE	ED,ID,MD	TX	RR	00:00.0
2021 PO5216105024	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5216905207	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4816203781	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4829503867	KU	7	30 BRN	SP	CRE	ED	TD		00:00.0
2021 PO4200286340	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4557810511	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO1191947091	KU	4	45 BRN	SP	CRE	ED,HH,ID,RB	TD		00:00.0
2021 PO8816490226	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4165386254	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4120286005	LGE	4	30 BRN	SP	P	ED,ID	TD		00:00.0
2021 PO0575449675	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5324899710	KU	6	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO1271446171	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4551810535	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4161786282	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4118785984	LGE	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO8808090011	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4166186266	LGE	3	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO6760516458	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO3038004933	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4159286274	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4598810472	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO0585349612	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4117785959-D	KU	4	35 BRN	SP	P	ID	TD		00:00.0
2021 PO-4117785959-F	KU	4	35E BRN	DF	P	ID	TD		00:00.0
2021 PO7069519085	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6816517086	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO1216046791	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4581210602	KU	4	45 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO6846216832	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO4157286308	LGE	1	55 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4116485932	LGE	4	40 BRN	SP	P	ID,SRS	TD		00:00.0
2021 PO6710816454	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO4115085920	LGE	4	30 BRN	SP	CRE	ID,IP,SRC	TD		00:00.0
2021 PO4115085922	LGE	4	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO1243246308	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021 PO1257746336	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8725686291	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO8699686370	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4858503789	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4113985897	LGE	3	45 BRN	SP	P	ID,SRS	TD		00:00.0
2021 PO1289545616	KU	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO8817985759	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4844603792	KU	7	30 BRN	SP	CCA	ED	TD		00:00.0
2021 PO4598110434	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4853104015	KU	7	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4198186317	KU	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4603210809	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5137704231	KU	2	35 BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO1046347455	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4623210724	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8066988022	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0

2021 PO1173547366	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0540649606	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2582308477	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO2584308479	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4126686128	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8789990529	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5346499328	KU	6	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8802590373	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4136286320	LGE	4	35E BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO0608750034	KU	4	45 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO1067747348	KU	6	35 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO1060847481	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5122703841	KU	2	30E BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5108403473	KU	2	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4198386313	LGE	4	25 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4135386324	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4589510873	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4134186327	LGE	4	40 BRN	SP	CRE	ID,IP	TD	00:00.0
2021 PO0627749943	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0594450206	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4133086330	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4133186327	LGE	4	35 BRN	SP	CRE	ID,IP	TD	00:00.0
2021 PO2562005546	KU	2	70 UNK	SP	CRE	ID	TD	00:00.0
2021 PO2558205565	KU	2	70 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4569610892	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO1112547594	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8146289712	KU	4	40 BRO	DF	CRE	ED,ID	TD	00:00.0
2021 PO8461387863	KU	3	55 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4818804083	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6896316200	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO8128689880	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4578210782	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8401287238	KU	3	55 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4811703984	KU	6	30 BRN	SP	CCA	ED	TD	00:00.0
2021 PO6871616621	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6896316200A	KU	4	35 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO0700549707	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0674949738	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0692049665	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6916016026	KU	4	45 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6906616030	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4825603748	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO0600050692	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8555088581	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3379300662	KU	4	55 UNK	SP	CRE	ID	TD	00:00.0
2021 PO1136749277	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO1117247642	KU	5	35 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO1101648386	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6987820098	KU	3	45 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7001819913	KU	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7015519721	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7030619510	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO7047819258	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO6804118868	KU	6	30 ACW	SP	CRE	ED,ID	TD	00:00.0



2021 PO6802418719	KU	4	35 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO6814418752	KU	4	40 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO6764518903	KU	4	35 ACW	SP	CRE	ED,ID	TD			00:00.0
2021 PO4609310455	KU	4	40 XXX	SP	CRE	ED,ID	TD			00:00.0
2021 PO4127286138	LGE	4	35 BRN	SP	CRE	ID	TD			00:00.0
2021 PO4128486162	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021 PO8746286220	KU	5	35 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO8793286035	KU	5	35 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO5029102617	KU	2	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021 PO4599810560	KU	4	40 XXX	SP	CRE	ED,ID	TD			00:00.0
2021 PO8796191050	KU	5	35 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO1092448411	KU	4	40 BRN	SP	CRE	ED,HH,ID,MD	TD			00:00.0
2021 PO1112247515	KU	4	40 BRN	SP	CRE	ID	TD			00:00.0
2021 PO4590710664	KU	4	40 XXX	SP	CRE	ED,ID	TD			00:00.0
2021 PO4193786273-A	KU	5	35 BRO	SP	A	ED,ID	TD			00:00.0
2021 PO1121249090	KU	4	40 BRN	SP	CRE	ED,HH,ID	TD			00:00.0
2021 PO5024302600	KU	5	40 BRN	SP	CCA	ED	TD			00:00.0
2021 PO1120549575	KU	4	40 BRN	SP	CRE	ID	TD			00:00.0
2021 PO4157186290	LGE	4	40 BRO	SP	CRE	ED,ID	TD			00:00.0
2021 PO4815703577	KU	4	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021 PO2518004521	KU	2	45 UNK	SP	CRE	HH,RB	BX		PX	00:00.0
2021 PO4114785899	F	4	35 BRN	SP	CRE	HH,ID	BX		RP2	00:00.0
2021 PO4117785959-A	F	6	35 BRN	SP	CRE	ED,HH	BX		RP1	00:00.0
2021 PO8053087986	KU	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX		RP1	00:00.0
2021 PO1207847123	KU	4	40 BRN	SP	CRE	ID	BD			00:00.0
2021 PO4561210839	KU	4	45 XXX	SP	CRE	ID	BD			00:00.0
2021 PO4113385930	LGE	4	40 BRN	SP	CRE	ID	BD			00:00.0
2021 PO2961605625	KU	6	35 UNK	SP	CRE	ID	BD			00:00.0
2021 PO4115585919	LGE	2	55 BRN	SP	P	ID	BD			00:00.0
2021 PO8673286458	KU	4	30 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO4117785959-G	KU	4	35E BRN	SP	P	ID	BD			00:00.0
2021 PO5303800233	KU	4	40 BRN	SP	CRE	ED,ID	BD			00:00.0
2021 PO4117785959-E	KU	5	35E BRN	SP	A	ID	BD			00:00.0
2021 PO4163886274	LGE	3	45 BRO	SP	CRE	ID,IP	BD			00:00.0
2021 PO4117785959-C	KU	5	35 BRN	SP	P	ID	BD			00:00.0
2021 PO4117385992	LGE	4	40 BRN	SP	CRE	ID	BD			00:00.0
2021 PO4117585990	LGE	4	40 BRN	SP	P	ID	BD			00:00.0
2021 PO8831185640	KU	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO4603710438	KU	4	40 XXX	SP	CRE	ID	BD			00:00.0
2021 PO0533449361	KU	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO4133986324	LGE	4	40 BRN	SP	CRE	ID	BD			00:00.0
2021 PO4135586319	LGE	4	40 BRN	SP	CRE	ED,ID	BD			00:00.0
2021 PO0634849302	KU	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO8481788115	KU	3	45 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO2537804969	KU	2	45 UNK	SP	CRE	ID	BD			00:00.0
2021 PO2533804986	KU	2	45 UNK	SP	CRE	ED,ID	BD			00:00.0
2021 PO4133386280	LGE	4	30 BRN	SP	CRE	IP	BD			00:00.0
2021 PO8110089325	KU	4	40 BRN	SP	CRE	ED,ID	BD			00:00.0
2021 PO8117188782	KU	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO8092788906	KU	4	45 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO8071788437	KU	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO4133786313	LGE	4	35 BRN	SP	CRE	ID,IP	BD			00:00.0
2021 PO4593010340	KU	4	40 XXX	SP	CRE	ID	BD			00:00.0
2021 PO4823598037	KU	4	40 UNK	SP	CRE	ID	BD			00:00.0

2021 PO4843598015	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO2513404540	KU	2	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5310199979	KU	4	40 BRN	SP	CRE	ED	BD		00:00.0
2021 PO5026202594	KU	2	70 BRN	SP	CRE		B		00:00.0
2021 PO0624650853	KU	4	40 BRO	SP	CRE		B		00:00.0
2021 PO0927254119	KU	4	40 BRO	SP	CRE	ED,EP,ID	X	RP3	00:00.0
2021 PO6828218128	KU	4	40 ACW	SP	CRE	ED,ID	X	PX	00:00.0
2021 PO1390847812	KU	5	35 BRN	SP	CRE	ED,EP,HH,ID	X	PX	00:00.0
2021 PO4125786093	LGE	3	55 BRN	SP	P	ID,MD,RB	X	RP1	00:00.0
2021 PO3866207148	KU	7	35 BRN	SP	CRE	ED,HH,ID,MD,RB	X	PX	00:00.0
2021 PO3882305901	KU	6	35 BRN	SP	CRE	ED,ID,IP,RB	X	RP1	00:00.0
2021 PO4130786118	LGE	4	40 BRN	SP	CRE	ED,HH	X	RP1	00:00.0
2021 PO4179986165	F	4	35 BRO	SP	A	HH,ID,IP	VX	RP1	00:00.0
2021 PO4178486165	F	4	35 BRO	SP	A	HH,ID,IP	VX	RP1	00:00.0
2021 PO7808560009	F	4	45 UNK	SP	CRE	HH,RB	VX	PX	00:00.0
2021 PO4182086163	F	4	40 BRO	SP	A	HH,ID	VX	RP1	00:00.0
2021 PO7756860325	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO6982614742	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6989514644	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO6996014493	KU	2	65 ACW	SP	CRE		V		00:00.0
2021 PO4541009574	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4186685323	F	2	55 BRN	SP	CCA		V		00:00.0
2021 PO8200063563	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO8198963596	KU	4	45 BRO	SP	CRE		V		00:00.0
2021 PO4185485390	F	4	35 BRN	SP	P		V		00:00.0
2021 PO4186085384	KU	1	55 BRN	SP	CCA		V		00:00.0
2021 PO4185785395	LGE	1	55 BRN	SP	CCA		V		00:00.0
2021 PO4173486360	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4172486378	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4498009118	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4530009157	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4542909435	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4536509299	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6969714953	KU	4	40 ACW	SP	CRE		V		00:00.0
2021 PO4186485362	F	3	45 BRN	SP	P		V		00:00.0
2021 PO4186585339	F	1	55 BRN	SP	S		V		00:00.0
2021 PO4186485362	F	3	45E BRN	SP	CRE		V		00:00.0
2021 PO4186585348	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4186485356	F	1	55 BRN	SP	CCA		V		00:00.0
2021 PO4522809011	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6937614760	KU	4	40 ACW	SP	S		V		00:00.0
2021 PO4172986370	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO0720448183	KU	6	30 BRN	SP	CRE		V		00:00.0
2021 PO4185485409	F	3	45E BRN	SP	CRE		V		00:00.0
2021 PO4185285425	LGE	1	65 BRN	SP	P		V		00:00.0
2021 PO8991166194	LGE	1	55 BRN	SP	CCA		V		00:00.0
2021 PO8982666191	LGE	1	55 BRN	SP	CCA		V		00:00.0
2021 PO4115484381	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4114384376	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4113384372	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4111684363	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4112984369	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4110584358	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4109484353	F	4	40 BRO	SP	CRE		V		00:00.0

2021	PO4108584353	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3980083767	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO8044973414	KU	2	70 ACE	SP	CCA		V	00:00.0
2021	PO3969383759	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO8045173274	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8045473141	KU	2	70 ACE	SP	CCA		V	00:00.0
2021	PO3994384607	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3993584630	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO3992884613	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3991284617	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3970883773	F	4	40 BRO	SP	A		V	00:00.0
2021	PO3970983768	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO8045773013	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO4108084336	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4108684323	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4109284317	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4109984315	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4110984319	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4112084324	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4113184329	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO8046472879	KU	2	65 ACE	SP	CCA		V	00:00.0
2021	PO8046772733	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8047172575	KU	2	65 ACE	SP	CRE		V	00:00.0
2021	PO8047672413	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO3972183768	F	4	30 BRO	SP	A		V	00:00.0
2021	PO3972083772	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO1389594967A	KU	5	40 INP	SP	CRE	ID	TD	00:00.0
2021	PO8048172247	KU	2	65 ACE	SP	CRE		V	00:00.0
2021	PO8048472096	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8049371927	KU	2	60 ACE	SP	CRE		V	00:00.0
2021	PO3990884609	F	4	30 ACE	SP	A		V	00:00.0
2021	PO1362095175	KU	5	35 BRO	SP	CCA		T	00:00.0
2021	PO3973383767	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO8049571744	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8050271590	KU	1	65 ACE	SP	CRE		V	00:00.0
2021	PO3989684616	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO3990184624	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3988984632	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3706384274	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO3659284549	KU	3	45 BRO	SP	S		V	00:00.0
2021	PO3673284590	KU	4	50 BRO	SP	CCA		V	00:00.0
2021	PO3653784450	KU	5	30 BRO	SP	S		V	00:00.0
2021	PO3700184458	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3702784562	KU	5	35 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021	PO3973283772	F	4	40 BRO	SP	A		V	00:00.0
2021	PO3973883774	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3973983771	F	3	45 BRO	SP	A		V	00:00.0
2021	PO3975383770	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3974883767	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO1456895599	KU	4	45 INP	SP	CRE	ID	TD	00:00.0
2021	PO3987784640	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3986584656	F	4	30 ACE	SP	A		V	00:00.0
2021	PO3985284663	F	4	30 ACE	SP	A		V	00:00.0
2021	PO3986384649	F	4	40 ACE	SP	CRE		V	00:00.0

2021 PO3984984657	F	4	40 ACE	SP	A		V	00:00.0	
2021 PO4034284363	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4034184364	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4034084364	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO8097173257	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO8066973189	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4083284363	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO3988084692	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO3625884624	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8050571448	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO8051171320	KU	1	65 ACE	SP	CRE		V	00:00.0	
2021 PO4045284459	LGE	UNK	45 ACE	SP	CRE		V	00:00.0	
2021 PO4035484359	LGE	8	50 ACE	SP	CRE		V	00:00.0	
2021 PO3986484690	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3987584678	F	4	30 ACE	SP	A		V	00:00.0	
2021 PO3987684685	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3988784678	F	4	40 ACE	SP	A		V	00:00.0	
2021 PO3989984670	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3991084663	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4039483317	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4035584357	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4084284351	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4084984338	LGE	4	40 BRO	SP	P	ED,ID,IP	BD	00:00.0	
2021 PO4086384340	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0	
2021 PO4039384336	LGE	4	30 ACE	SP	A		V	00:00.0	
2021 PO4041183297	LGE	4	40 BRO	SP	A	ID	BD	00:00.0	
2021 PO4041483293	LGE	4	25 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021 PO8051771173	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO1508696428	KU	4	40 BRO	SP	S		V	00:00.0	
2021 PO8052171012	KU	1	65 ACE	SP	CRE		V	00:00.0	
2021 PO8052970831	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO8053270716	KU	1	65 ACE	SP	CRE		V	00:00.0	
2021 PO8053470572	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO8037370174	KU	1	65 ACE	SP	CRE		V	00:00.0	
2021 PO4041783308	LGE	3	45 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021 PO4040183325	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4045184446	LGE	3	50 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO4044684433	LGE	4	40 ACE	SP	CRE	ED	TD	00:00.0	
2021 PO4044184435	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4044584433	LGE	3	50 ACE	SP	CRE	ED	TD	00:00.0	
2021 PO8034970834	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO1511796633	KU	5	35 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO1500096424	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0	
2021 PO8014970836	KU	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO7994970839	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO1496296347	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO3991584669	F	4	30 ACE	SP	CRE		V	00:00.0	
2021 PO3992484655	F	4	30 ACE	SP	CRE		V	00:00.0	
2021 PO3991684654	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3991984638	F	4	30 ACE	SP	CRE		V	00:00.0	
2021 PO3991184641	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO7993070669	KU	5	35 ACE	SP	CCA	ED	TD	00:00.0	
2021 PO4085684359	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	BD	00:00.0	
2021 PO4084684372	LGE	4	40 BRO	SP	P	ED,EP,ID,IP	TD	00:00.0	

2021	PO4083584393	LGE	4	40 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021	PO1486096150	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO1470495826	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO5656727839	KU	6	30 BRN	SP	CCA		B	00:00.0
2021	PO5666027786	KU	5	35 BRN	SP	CCA		B	00:00.0
2021	PO5696727836	KU	5	35 BRN	SP	CRE		B	00:00.0
2021	PO5695627991	KU	5	35 BRN	SP	CRE		B	00:00.0
2021	PO4042883295	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4044283296	LGE	4	25 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4044383293	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO5680228073	KU	5	35 BRN	SP	CRE		B	00:00.0
2021	PO5654328013	KU	5	35 BRN	SP	CRE		B	00:00.0
2021	PO8015070498	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO7990570405	KU	5	35 ACE	SP	CCA	ED	TD	00:00.0
2021	PO3983684573	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3983084561	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3982784548	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5650127747	KU	3	45 BRN	SP	CRE		B	00:00.0
2021	PO5661027695	KU	2	85 BRN	SP	CRE		B	00:00.0
2021	PO5667727747	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5653627820	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO8006070398	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO8021670287	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4043883302	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4043483330	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO1351194930	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO3986184532	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3984984531	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3982684534	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO3982584519	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5633127829	KU	3	45 BRN	SP	CRE		B	00:00.0
2021	PO5642027786	KU	H1	85 BRN	SP	CRE		B	00:00.0
2021	PO5639227670	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO5645727859	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO5637427899	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4044283320	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4044983311	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5612528025	KU	3	40 BRN	SP	CRE		B	00:00.0
2021	PO5600027993	KU	5	35 BRN	SP	CRE		B	00:00.0
2021	PO5586528064	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5616427908	KU	4	40 BRN	SP	CRE		B	00:00.0
2021	PO5610127783	KU	5	35 BRN	SP	CRE		B	00:00.0
2021	PO5597427701	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO5607527727	KU	5	35 BRN	SP	CRE		V	00:00.0
2021	PO7956670017	KU	6	30 ACE	SP	CCA		V	00:00.0
2021	PO1358894926	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021	PO7981869808	KU	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO7983669781	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO7979470120	KU	5	35 ACE	SP	CCA	ED	TD	00:00.0
2021	PO1306795212	KU	6	30 UNK	SP	P	ID	TD	00:00.0
2021	PO1307395059	KU	4	40 UNK	SP	P	ID	TD	00:00.0
2021	PO3983084520	F	4	30 ACE	SP	P		V	00:00.0
2021	PO7898268668	KU	4	45 ACE	SP	A		V	00:00.0
2021	PO3978983768	F	4	40 BRO	SP	CRE	ED,ID,IP	VX	RP1 00:00.0

2021 PO4118684445	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4117584439	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4116484434	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4115384428	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4114284423	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4113184418	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4112084413	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4036484238	LGE	1	90 ACE	SP	P		V	00:00.0
2021 PO4037284256	LGE	1	90 ACE	SP	A		V	00:00.0
2021 PO4038184276	LGE	1	85 ACE	SP	A		V	00:00.0
2021 PO3988684584	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO3989184590	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3987984597	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8054270409	KU	2	70 ACE	ST	CRE		V	00:00.0
2021 PO3918886287	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3927486399	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3859685491	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO3877585738	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3986784605	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4110984407	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4110484400	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4110684389	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4111084392	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4111084376	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4107684348	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3983783765	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO3983783752	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8013573978f	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8013573978e	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO8013573978d	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO3983783740	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8013573978c	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8013573978a	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO1529096695	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO1523897015A	KU	4	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO3985084608	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO3985484614	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3984284624	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO8013573978b	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3169879847	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3161980023	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO3167279867	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3168679905	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO3151479775	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO3097879550	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3085179590	KU	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5330284413	KU	6	30 XXX	SP	CRE		V	00:00.0
2021 PO5246287571	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO5229087393	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO5216887306	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO5290986920	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5327386558	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5304386632	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5284586707	KU	3	45 XXX	SP	CRE		V	00:00.0

2021 PO5279486561	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5280786265	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5286086111	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5291185977	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3985184623	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3983683728	F	4	40 BRO	SP	A		V	00:00.0
2021 PO1523897015	KU	4	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO1512497065	KU	4	40 UNK	SP	P	ID	TD	00:00.0
2021 PO3835284847	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3827085048	KU	3	45 BRO	SP	S		V	00:00.0
2021 PO3840885233	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8042474279	KU	2	70 ACE	SP	CRE		V	00:00.0
2021 PO4116984420	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4117484408	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4117884396	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4118384384	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4118784373	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3984884639	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3985684635	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3982983766	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8013573978	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO8026274117	KU	2	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8031574176	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO3951186970	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3927187146	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO3916187223	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4028084125	LGE	5	35 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO3979784622	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3857786452	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO3849686637	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO4032385948	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4041885589	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4042385588	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4042285570	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4040085647	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4038685640	F	6	25 KOP	SP	A		V	00:00.0
2021 PO4038685647	F	4	40 KOP	SP	A		V	00:00.0
2021 PO4040085559	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4041385561	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4041285546	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4042085545	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4037585648	F	4	40 KOP	SP	A		V	00:00.0
2021 PO4036285649	F	4	40 KOP	SP	A		V	00:00.0
2021 PO4034985649	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4033485649	F	4	40 KOP	SP	A		V	00:00.0
2021 PO4041185531	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4041685526	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4040985526	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4043585528	F	4	30 BRO	SP	P		V	00:00.0
2021 PO4030285458	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4030585463	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4922110868	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO4923810940	F	4	45 KOP	SP	S		V	00:00.0
2021 PO4947510862	F	4	45 KOP	SP	S		V	00:00.0

2021 PO4034685778	F	4	40 KOP	SP	CCA		V		00:00.0
2021 PO4034785794	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4034385806	F	4	30 KOP	SP	A		V		00:00.0
2021 PO4039585958	F	3	45 KOP	SP	CCA		V		00:00.0
2021 PO4039585953	F	6	30 KOP	SP	A		V		00:00.0
2021 PO4038985944	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4038685936	F	5	40 KOP	SP	CCA		V		00:00.0
2021 PO4037985920	F	4	35 KOP	SP	A		V		00:00.0
2021 PO4037485908	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4720312840A	KU	6	30 KOP	SP	S		V		00:00.0
2021 PO4038185816	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4037585809	F	4	40 KOP	SP	A		V		00:00.0
2021 PO4036385808	F	3	45 KOP	SP	CCA		V		00:00.0
2021 PO5158310519	F	5	40 BRO	SP	CRE		V		00:00.0
2021 PO4036685893	F	4	40 KOP	SP	CCA		V		00:00.0
2021 PO4053985615	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4055885611	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4055885616	F	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4047085615	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4056685610	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4058485610	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4036185882	F	3	45 KOP	SP	CCA		V		00:00.0
2021 PO5184410590	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO5190234697	KU	2	45 BRO	SP	CCA		V		00:00.0
2021 PO5175334491	KU	2	45 BRO	SP	CCA		V		00:00.0
2021 PO5157434247	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO5135933990	KU	2	45 BRO	SP	CCA		V		00:00.0
2021 PO5112833743	KU	1	65 BRO	SP	CCA		V		00:00.0
2021 PO5084933962	KU	2	65 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5050034234	KU	1	70 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5176910590	KU	2	50 BRO	SP	CRE	ID	TD		00:00.0
2021 PO4053785612	F	4	40 BRO	SP	CRE	IP,RB	VX	RP3	00:00.0
2021 PO5168110319	KU	2	50E BRO	SP	CRE	ID	TD		00:00.0
2021 PO5348432173	KU	3	45 KOP	SP	CRE	HH,ID,IP	TX	RR	00:00.0
2021 PO5368032006	KU	3	45 KOP	SP	CRE	ID	TD		00:00.0
2021 PO5358232088	KU	3	45 KOP	SP	CRE	ID	BD		00:00.0
2021 PO4960412077	KU	6	30 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4978512097	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4992412088	KU	6	30 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4997712070	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO5451934414	KU	4	45 BRO	SP	CCA		T		00:00.0
2021 PO5453034333	KU	3	45 BRO	SP	CCA		T		00:00.0
2021 PO5008912522	KU	6	30 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO5014412505	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4039385822	LGE	4	30 KOP	SP	P		T		00:00.0
2021 PO4041485568	LGE	4	40 BRO	SP	CCA	ED,EP,RB	VX	RP3	00:00.0
2021 PO7557468150	LGE	4	40 KOP	SP	A	ED,ID,MD	TD		00:00.0
2021 PO4035085618	LGE	4	35 KOP	SP	A	ED,ID	BD		00:00.0
2021 PO5502514477	KU	4	40 BRO	SP	CRE		T		00:00.0
2021 PO7462571087	LGE	4	30 KOP	SP	CCA	ED	T		00:00.0
2021 PO4041085589	LGE	4	30 BRO	SP	P		T		00:00.0
2021 PO4043985592	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO5481814491	KU	7	35 BRO	SP	CRE	ED,ID,MD,RB	VX	PX	00:00.0
2021 PO5387431842	KU	3	45 KOP	SP	CRE	ID	TD		00:00.0



2021	PO5393931934	KU	4	30 KOP	SP	CRE	ID	TD		00:00.0
2021	PO4035185986	LGE	3	45 KOP	SP	P	ED,ID,MD	TD		00:00.0
2021	PO5416035087	KU	4	45 BRO	SP	CCA		T		00:00.0
2021	PO5418934906	KU	4	45 BRO	SP	CCA		T		00:00.0
2021	PO4040685976	LGE	6	35 KOP	SP	A	ED	TD		00:00.0
2021	PO5377131928	KU	3	45 KOP	SP	CRE	ID,IP	TD		00:00.0
2021	PO5192310361	KU	6	35 BRO	SP	CRE	ID	TD		00:00.0
2021	PO5002112188	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO5001412320	KU	6	30 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO5006612303	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO5422434698	KU	4	45 BRO	SP	CCA		T		00:00.0
2021	PO5217111343	KU	7	35 KOP	SP	CCA		T		00:00.0
2021	PO4985712275	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO4043185514	LGE	4	30 BRO	SP	CCA	ED,EP,ID,RB	TX	RR	00:00.0
2021	PO5425334506	KU	4	45 BRO	SP	CCA		T		00:00.0
2021	PO5242325747	KU	4	40 UNK	SP	CCA		T		00:00.0
2021	PO5011012416	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO5246225870	KU	6	30 UNK	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021	PO4031885462	F	4	40 BRO	SP	CRE	IP,RB	VX	RP2	00:00.0
2021	PO5033134365	KU	2	65 UNK	SP	CRE	ID	BX	RP1	00:00.0
2021	PO5182010394	KU	6	35 BRO	SP	CRE		T		00:00.0
2021	PO5246426229	KU	6	30 UNK	SP	CRE		T		00:00.0
2021	PO5413035283	KU	4	45 BRO	SP	CRE	ID	TD		00:00.0
2021	PO5399535320	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021	PO5409535332	KU	4	45 BRO	SP	CRE	ID	TD		00:00.0
2021	PO5389335347	KU	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021	PO5426834389	KU	3	55 BRO	SP	CCA		T		00:00.0
2021	PO5227825761	KU	4	40 UNK	SP	CRE		T		00:00.0
2021	PO4032285618	LGE	4	35 KOP	SP	A	ID,MD	BD		00:00.0
2021	PO5352132216	KU	6	30 KOP	SP	CRE	ID	TD		00:00.0
2021	PO5413635225	KU	4	45 BRO	SP	CCA		T		00:00.0
2021	PO4900535593	KU	4	40 KOP	SP	CRE	ID	TD		00:00.0
2021	PO4051186261	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4048986283	LGE	2	50 KOP	SP	A		V		00:00.0
2021	PO4049386283	LGE	4	45 KOP	SP	CCA		V		00:00.0
2021	PO4050686273	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4052086253	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4052986258	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4053286267	LGE	3	45 KOP	SP	A		V		00:00.0
2021	PO4050986245	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4050686239	LGE	3	45 KOP	SP	CCA		V		00:00.0
2021	PO4052686242	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4053086231	LGE	3	45 KOP	SP	P		V		00:00.0
2021	PO4053086214	LGE	4	40 KOP	SP	P		V		00:00.0
2021	PO4051386215	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4049986211	LGE	4	45 KOP	SP	A		V		00:00.0
2021	PO4050286207	LGE	4	30 KOP	SP	A		V		00:00.0
2021	PO4048786206	LGE	4	30 KOP	SP	A		V		00:00.0
2021	PO4048886210	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4045286212	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4047186211	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4047286227	LGE	4	40 KOP	SP	A		V		00:00.0
2021	PO4047386242	LGE	4	40 KOP	SP	CCA		V		00:00.0
2021	PO4047486258	LGE	3	45 KOP	SP	CCA		V		00:00.0

2021 PO4047886271	LGE	4	40 KOP	SP	A		V	00:00.0
2021 PO4047086167	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4047086182	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4047086195	F	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4050586282	LGE	4	40 KOP	SP	A	ED,ID,MD	BD	00:00.0
2021 PO4045086215	LGE	4	30 KOP	SP	P	ED,ID,MD	TD	00:00.0
2021 PO4069886599	LGE	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3990485700	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3990785715	LGE	7	25 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3991485703	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3992485697	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3993585689	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3994685681	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3995685674	F	4	40 ACE	SP	P		V	00:00.0
2021 PO3996185659	LGE	1	20 ACE	SP	A		V	00:00.0
2021 PO3996785666	F	4	40 ACE	SP	P		V	00:00.0
2021 PO3998085663	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3998585669	F	4	40 ACE	SP	CRE	ED,EP,ID	V	00:00.0
2021 PO4136085964	LGE	1	95 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4136785977	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4849632621	KU	2	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4847132589	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4858132750	KU	2	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PV4138285963	LGE	2	80 BRO	SP	CRE	ID	BD	00:00.0
2021 PO3999385680	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4000085692	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3999985698	F	4	40 ACE	SP	P		V	00:00.0
2021 PO3998885706	F	4	40 ACE	SP	P		V	00:00.0
2021 PO3997885713	F	4	40 ACE	SP	P	ED,ID	V	00:00.0
2021 PO4138585986	KU	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO3996685721	F	4	40 ACE	SP	P	ED,HH,ID	V	00:00.0
2021 PO3995585728	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3994985728	F	4	40 ACE	SP	CRE	ED,ID	V	00:00.0
2021 PO3994185718	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3993985704	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4030386605	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4030386610	LGE	5	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4024686631	LGE	UNK	65 ACE	ST	P		V	00:00.0
2021 PO4025686626	LGE	UNK	60 ACE	ST	P		V	00:00.0
2021 PO4138585986	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4139185975	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO3988785705	F	3	45 ACE	SP	A		V	00:00.0
2021 PO3988985695	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3989385692	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3989185687	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4854932689	KU	2	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO3991385670	F	4	30 ACE	SP	P		V	00:00.0
2021 PO3991385677	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3993585656	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO3993385663	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3995285650	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3996285643	F	4	40 ACE	SP	P	ED,ID,IP	V	00:00.0
2021 PO3998185629	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3967586439	F	4	40 ACE	SP	A		V	00:00.0

2021 PO3969186430	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3971086419	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3972586412	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3974486402	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3976186389	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3976985827	LGE	2	65 ACE	SP	A		V	00:00.0
2021 PO3976685863	LGE	2	50 ACE	SP	CCA		V	00:00.0
2021 PO3970985755	LGE	1	65 ACE	SP	P		V	00:00.0
2021 PO3972385773	LGE	1	75 ACE	SP	P		V	00:00.0
2021 PO3966585702	LGE	2	65 ACE	SP	A		V	00:00.0
2021 PO3968085720	LGE	2	65 ACE	SP	A		V	00:00.0
2021 PO3969585735	LGE	1	65 ACE	SP	A		V	00:00.0
2021 PO3963585665	LGE	1	70 ACE	SP	CRE		V	00:00.0
2021 PO3998386406	F	4	40 ACE	SP	P		V	00:00.0
2021 PO3997586416	F	2	55 ACE	SP	CCA		V	00:00.0
2021 PO3998486411	F	4	45 ACE	SP	P		V	00:00.0
2021 PO4842932673	KU	2	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO4085186727	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4085286722	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4083986712	LGE	4	40 ACE	SP	CRE	ED,ID	TX RR	00:00.0
2021 PO4085686727	F	5	35 ACE	SP	A		V	00:00.0
2021 PO4084886718	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3986285635	F	4	45 ACE	SP	P		V	00:00.0
2021 PO3987185626	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4083286697	F	4	40 ACE	SP	S		V	00:00.0
2021 PO4082786698	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4083086695	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4083286694	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4083886688	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PV8521171516	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4084686682	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4086286683	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4085586675	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4085986673	F	UNK	25 ACE	SP	CRE		V	00:00.0
2021 PO4831832760	KU	3	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4837032720	KU	2	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO5186435002	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5183734977	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5177934894	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5174534858	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5161434738	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5150734641	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5148634655	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5138034762	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4162586045	LGE	1	95 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO3983585630	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4087186693	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4087886702	F	2	45 ACE	SP	CCA		V	00:00.0
2021 PO4088586709	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4089386708	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4090486701	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4090786695	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4090286685	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4161286046	LGE	2	55 BRO	SP	A	ED,ID	TD	00:00.0

2021 PO4160386047	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4078186634	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4089686674	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4088886663	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3984985647	F	3	45 ACE	SP	P		V		00:00.0
2021 PO4087286644	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4087086646	F	4	30 ACE	SP	CRE	HH,RB	BX	RP3	00:00.0
2021 PO4086586629	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3994685474a	KU	4	35 ACE	SP	P		V		00:00.0
2021 PO4088186634	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4085286636	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4084186641	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4083286646	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3699197411	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO3564297655	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021 PO3612697567	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO8759472013	LGE	5	35 BRO	SP	CCA	ED	T		00:00.0
2021 PO3694589723	KU	4	40 OTH	SP	CRE	ID,IP	BD		00:00.0
2021 PO4648127828	F	4	40 OTH	SP	CRE	HH	VX	RP1	00:00.0
2021 PO4729927258	F	4	40 OTH	SP	P	ID	VX	RP3	00:00.0
2021 PO4714027124	F	4	40 OTH	SP	CRE	ED,HH,ID	VX	PX	00:00.0
2021 PO4665227498	F	4	40 CPT	SP	CRE	ED,HH,ID	VX	PX	00:00.0
2021 PO4674327419	F	4	40 CPT	SP	P	ED,ID	VX	PX	00:00.0
2021 PO4692227261	F	4	40 CPT	SP	CRE	ED,HH,ID	VX	RP1	00:00.0
2021 PO4619528242	F	4	40 BRN	SP	CRE	ED,ID	VX	RP1	00:00.0
2021 PO9438963384	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO9482763357	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4056684892	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4063984920	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4065184930	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4062884926	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4061884937	F	4	30 BRO	SP	P		V		00:00.0
2021 PO4060584938	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4061784932	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4060784943	F	4	30 BRO	SP	CRE		V		00:00.0
2021 PO9683363266	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO9682463186	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9687262966	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4066884994	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4066184983	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4065584973	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4108185542	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4632728566	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4628228455	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4623728346	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4614928132	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4610028012	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4607727993	KU	2	45 BRN	SP	CCA		V		00:00.0
2021 PO4599427921	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4598327872	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4113985566	F	1	20 ACE	SP	A		V		00:00.0
2021 PO4119285451	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4119485433	F	3	45 ACE	SP	P		V		00:00.0
2021 PO3376023574	F	4	40 BRN	SP	P		V		00:00.0

2021 PO3384523594	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3381523681	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3370423736	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3358224018	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4118485431	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4120785415	F	6	25 ACE	SP	CRE	V	00:00.0
2021 PO4119985415	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4119985400	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4119885394	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4120485382	F	5	25 ACE	SP	P	V	00:00.0
2021 PO4119785381	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4119685372	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4121185429	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4683127341	F	4	40 CPT	SP	CCA	V	00:00.0
2021 PO4646128889	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4641628779	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4637128670	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4656527577	F	4	40 CPT	SP	CRE	V	00:00.0
2021 PO4647827657	F	4	40 CPT	SP	CRE	V	00:00.0
2021 PO4639027725	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4628927818	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4619427928	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO6792048405	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO6824848434	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO6863648477	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO3423021471	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3425421525	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3413621525	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4112485544	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4111885543	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4110485545	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO3408321425	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3392721395	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3393221272	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3377121192	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4107085537	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4109285543	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4723526979	F	4	40 OTH	SP	CRE	V	00:00.0
2021 PO4708927061	F	4	40 OTH	SP	CRE	V	00:00.0
2021 PO4701227181	F	4	40 OTH	SP	P	V	00:00.0
2021 PO5586536360	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5554536343	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5584032285	KU	6	30 BRO	SP	CCA	V	00:00.0
2021 PO5594332286	F	6	30 BRO	SP	CCA	V	00:00.0
2021 PO3855712478	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO3857112636	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO3832512635	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3794812631	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3759212627	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3751312190	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3883013204	F	4	40 XXX	SP	P	V	00:00.0
2021 PO3874613115	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3850813123	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3833513150	KU	3	45 BRN	SP	CCA	V	00:00.0

2021 PO3810313195	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3780513186	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3750613192	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3735713694	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3741713680	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3730713911	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3744913379	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3738513400	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3731613138	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3723713069	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3702513028	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3705512770	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3708712488	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3780413034	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO3827313001	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO3858912205	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO3843812203	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO3824812200	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3789012194	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3861312037	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3932910986	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO3933910707	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO3961910522	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4588349622	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4598749734	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4610549827	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4621249901	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4632149962	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4067284824	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4644850020	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4656150061	F	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4666150094	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5462036417	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5492536468	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5554536468	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5522536468	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 5492536468A	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO6785545763	KU	4	45 UNK	SP	CCA	V	00:00.0
2021 PO4164385410	F	4	40 BRO	WC	CRE	V	00:00.0
2021 PO4164585424	F	4	40 BRO	WC	CRE	V	00:00.0
2021 PO4164685427	F	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4163485428	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4162385429	F	4	45 BRO	SP	A	V	00:00.0
2021 PO4157285871-C	KU	4	35 BRO	SP	CCA	V	00:00.0
2021 PO4116585466	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4117285475	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4116785488	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4118885496	F	6	25 ACE	SP	P	V	00:00.0
2021 PO4118785487	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4161685430	F	2	55 BRO	WC	CRE	V	00:00.0
2021 PO4161785426	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4161785401	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4159385407	F	2	55 BRO	SP	CRE	V	00:00.0
2021 PO4159585420	F	4	40 BRO	SP	A	V	00:00.0

2021 PO4159785430	F	3	55 BRO	WC	CRE	V	00:00.0
2021 PO4159685429	F	3	55 BRO	WC	CRE	V	00:00.0
2021 PO4155085450	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4115785459	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4117185462	F	5	25 ACE	SP	P	V	00:00.0
2021 PO4117885473	F	6	25 ACE	SP	CRE	V	00:00.0
2021 PO4113985559	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4115185568	F	5	25 ACE	SP	P	V	00:00.0
2021 PO4116485568	F	5	25 ACE	SP	P	V	00:00.0
2021 PO4115285556	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4177585423	F	5	35 BRO	SP	CRE	V	00:00.0
2021 PO4174485423	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4173185422	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO6889948949	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO6924948754	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO4064984963	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4064284951	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4063584939	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4116185561	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4117585566	F	1	25 ACE	SP	A	V	00:00.0
2021 PO4117485559	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4118685557	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4119885554	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4120985552	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4116185544	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4115485531	F	5	30 ACE	SP	CCA	V	00:00.0
2021 PO4116085532	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4116185525	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4116685502	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4116385514	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4166785432	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4165685427	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4168685425	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4166685424	F	5	35 BRO	SP	P	V	00:00.0
2021 PO4164185402	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4043374382	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO4070174146	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO3412724470	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3404524440	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3397124326	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3390224384	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO3374424322	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3378324243	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3360224197	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3335124021	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3340524120	F	4	40 BRN	SP	P	V	00:00.0
2021 PO3326524002	F	4	40 BRN	SP	P	V	00:00.0
2021 PO4112585624	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4112985621	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO4112785616	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4112985602	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4110985600	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO9703462470	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO3416024323	F	4	40 BRN	SP	P	V	00:00.0

2021 PO3416724412	F	4	40 BRN	SP	P		V	00:00.0
2021 PO9948467294	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9964567643	KU	4	45 BRO	SP	S		V	00:00.0
2021 PO4111285595	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4111785597	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4115285486	F	4	45 ACE	SP	P		V	00:00.0
2021 PO4114985481	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4106285476	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO6671247721	F	4	45 UNK	SP	CRE		V	00:00.0
2021 PO6734647797-A	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6734647797	F	4	45 UNK	SP	CRE		V	00:00.0
2021 PO6749547866	F	6	30 UNK	SP	CCA		V	00:00.0
2021 PO4113685423	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4113485439	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4114885425	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4116085427	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4117285429	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6749648056	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO6765148381	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4071085028	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4070285033	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4069485027	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4068585016	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4067785004	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4155985447	F	3	40 BRO	SP	P		V	00:00.0
2021 PO4160885658	F	4	40 BRO	WC	CRE		V	00:00.0
2021 PO4157285442	F	4	40 BRO	WC	CRE		V	00:00.0
2021 PO4160785649	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4160685638	F	4	35 BRO	WC	CRE		V	00:00.0
2021 PO4160585617	F	4	35 BRO	WC	CRE		V	00:00.0
2021 PO4160085619	F	4	30 BRO	SP	P		V	00:00.0
2021 PO415985523	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4159285488	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4159385499	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4159085473	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4158985460	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4158785436	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4161785454	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4162285466	F	6	30 BRO	WC	CRE		V	00:00.0
2021 PO4162085484	F	4	40 BRO	WC	CRE		V	00:00.0
2021 PO4162085491	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4162185505	F	4	40 BRO	WC	CRE		V	00:00.0
2021 PO4162285512	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4162385519	F	4	35 BRO	WC	CRE		V	00:00.0
2021 PO4166185591	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4166385607	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4166285596	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4119885524	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4119885517	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4119785507	F	4	40 ACE	SP	P		V	00:00.0
2021 PO1038154680	KU	5	35 BRO	SP	CRE	ED,EP,ID	TD	00:00.0
2021 PO1082553942	KU	4	45 BRO	SP	CRE	ED,EP,ID,MD	TD	00:00.0
2021 PO1964142696	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO1967941479	KU	5	40 BRN	SP	CRE	ED,ID	TD	00:00.0



2021 PO1982643320	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO1986042830	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO1992941566	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO1999642912	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2028841619	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2038641514	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2121337831	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2124537779	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2188637968	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO2414109823-A	KU	4	40 UNK	SP	A	ID,IP	TD	00:00.0
2021 PO2529903232	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO2541703151	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO2564310146	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO2567103447	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO2573814220	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO2580212355	KU	3	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO2594612679	KU	3	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO2602004225	KU	4	40 UNK	SP	CRE	ID,IP	TD	00:00.0
2021 PO8570476262	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8587875436	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8608775496	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8762872923	KU	4	40 BRO	SP	CRE	ED,ID,SRC,SRS	TD	00:00.0
2021 PO8774472897	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8779372232	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8788872008	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8790873049	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8795173291	KU	4	40 BRO	SP	A	ED	TD	00:00.0
2021 PO8819873327	KU	3	50 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO9184879167	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9185078937	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9200677159	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9208076985	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9208076985A	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1070854123	KU	4	40 BRO	SP	CRE	ED,EP,ID,MD,RB	BX PX	00:00.0
2021 PO0616757452	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0634957445	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0953556330	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0969656021	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0990455619	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0999955431	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO1010655220	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO1023554968	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO1055254389	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO2006741887	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2009241596	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2011442975	KU	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO2020442553	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2189437528	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2196337823	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2203737647	KU	2	60 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2414109823	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO2520302903	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO2547212198	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021 PO2547912078	KU	5	35 UNK	SP	CRE	ID,IP	BD	00:00.0

2021 PO2556311546	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO2559811115	KU	3	50 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO2560411782	KU	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0	
2021 PO2563910917	KU	4	45 UNK	SP	CRE	ID,IP	BD	00:00.0	
2021 PO2564711999	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO2566410576	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO2570510011	KU	3	45 UNK	SP	CRE	ID,IP	BD	00:00.0	
2021 PO2575214186	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO2599503785	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO2613104558	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO2631104246	KU	4	40 UNK	SP	CCA	ID,MD	BD	00:00.0	
2021 PO8565075360	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO8751572981	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9185179534	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4726607396	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4842006411	KU	3	45 KOP	SP	CCA		V	00:00.0	
2021 PO9696415339	KU	3	45 ACW	SP	S		V	00:00.0	
2021 PO9699215066	KU	3	45 ACW	SP	S		V	00:00.0	
2021 PO9700814914	KU	3	45 ACW	SP	S		V	00:00.0	
2021 PO9702814747	KU	3	45 ACW	SP	S		V	00:00.0	
2021 PO9704714586	KU	3	45 ACW	SP	S		V	00:00.0	
2021 PO9743315434	KU	4	40 ACW	SP	S		V	00:00.0	
2021 PO4834605710	KU	6	30 XXX	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO4620207549	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4632107554	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4641307555	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4663807558	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4689807324	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4689907572	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4718807564	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4727307517	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4740407817	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4755208045	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4759408272	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4771608390	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4820706082	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4829405326	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4835806105	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO9667815480	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9691115466	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9698015184	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9709615454	KU	4	40 ACW	SP	CRE	ED,EP,ID	TD		00:00.0
2021 PO9715915310	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9729215443	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9742015562	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9773615357	KU	6	30 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9774615413	KU	3	45 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9791615401	KU	3	45 ACW	DF	CRE	ED,ID	TD		00:00.0
2021 PO9809715387	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9827915321	KU	6	30 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9828215376	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9843315508	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO9860015355	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO4818305910	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0

2021 PO4818506102	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO9791515346	KU	6	30 ACW	SP	CRE	ED,ID	BD		00:00.0
2021 PO4139586193	F	6	30 ACE	SP	CCA	ED,ID	VX	RP1	00:00.0
2021 PO4190086156	F	4	35 BRO	SP	CRE	HH,RB	VX	RP1	00:00.0
2021 PO4132386192	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4133186111	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4133186216	F	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4133486103	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4133486189	F	4	40 ACE	SP	CRE	ED,EP	V		00:00.0
2021 PO4133686125	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4133886129	F	6	30 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4134386216	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4134486095	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4134586186	F	4	40 ACE	SP	P	ED,ID,IP	V		00:00.0
2021 PO4134586199	F	6	30 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4134686228	F	6	30 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4134886122	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4135386089	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4135786183	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4135786212	F	4	35 ACE	SP	P		V		00:00.0
2021 PO4136286091	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4136286117	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4136686181	F	4	40 ACE	SP	P	ED,ID	V		00:00.0
2021 PO4136786100	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4136786209	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4137086223	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4137186109	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4137386116	F	4	35 ACE	SP	P		V		00:00.0
2021 PO4137686178	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4137786207	F	4	35 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4138585161	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4138786175	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4138786204	F	4	35 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4139686201	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4139886172	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4140086214	F	4	35 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4140285191	LGE	4	35 BRN	SP	CRE		V		00:00.0
2021 PO4140286223	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4140786199	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4140886166	F	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4140986169	F	4	40 ACE	SP	P	ED,ID	V		00:00.0
2021 PO4141486177	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4141786198	LGE	1	20 ACE	SP	CRE		V		00:00.0
2021 PO4141986185	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4142486194	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4142986203	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4143486206	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4143486212	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4143785210	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4143886221	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO4144986228	F	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4145186278	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO4145486226	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO4145786222	LGE	4	30 ACE	SP	CCA		V		00:00.0

2021 PO4177786377	F	4	40 BRO	SP	CRE		V			00:00.0	
2021 PO4178386389	KU	5	35 BRO	SP	CCA		V			00:00.0	
2021 PO4179286386	F	4	40 BRO	SP	CRE		V			00:00.0	
2021 PO4180186391	F	4	40 BRO	SP	A		V			00:00.0	
2021 PO4180886395	F	4	40 BRO	SP	CRE		V			00:00.0	
2021 PO4190086168	F	4	35 BRO	SP	A		V			00:00.0	
2021 PO4190186175	F	4	35 BRO	SP	CRE		V			00:00.0	
2021 PO4190186181	F	4	35 BRO	SP	CRE		V			00:00.0	
2021 PO4190186193	F	4	35 BRO	SP	CCA		V			00:00.0	
2021 PO4199586260	F	4	35 BRO	SP	CRE		V			00:00.0	
2021 PO4200586260	F	4	35 BRO	SP	CRE		V			00:00.0	
2021 PO4137885161	LGE	4	35 BRN	SP	P	ID,IP,RB			TX	RR	00:00.0
2021 PO4141286238	LGE	4	35 BRN	SP	P	ID,RB			TX	RR	00:00.0
2021 PO4144286247	LGE	4	35 BRN	SP	CCA	ID,RB			TX	RR	00:00.0
2021 PO4145886246	LGE	4	35 BRN	SP	P	ID,IP,RB			TX	RR	00:00.0
2021 PO4191786156	LGE	3	40 BRO	SP	CRE	ED,ID,IP			TX	RR	00:00.0
2021 PO4127485780	LGE	3	45 BRN	SP	P	ID,IP			TD		00:00.0
2021 PO4127585784	LGE	3	45 BRN	SP	CRE	ED,ID			TD		00:00.0
2021 PO4129185783	LGE	3	45 BRN	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4130985789	LGE	4	35 BRN	SP	CRE	ID			TD		00:00.0
2021 PO4131685789	LGE	4	35 BRN	SP	P	ED,ID			TD		00:00.0
2021 PO4138085172	LGE	4	35 BRN	SP	CCA	ED,ID,SRS			TD		00:00.0
2021 PO4140486261	LGE	4	35 BRN	SP	P	ID,IP,SRS			TD		00:00.0
2021 PO4140686278	LGE	4	35 BRN	SP	P	ID,SRS			TD		00:00.0
2021 PO4140786293	LGE	4	35 BRN	SP	P	ID,SRS			TD		00:00.0
2021 PO4141386250	LGE	4	35 BRN	SP	P	ID,SRS			TD		00:00.0
2021 PO4142986239	LGE	4	35 BRN	SP	P	ID,IP			TD		00:00.0
2021 PO4143385226	LGE	3	50 BRN	SP	CRE	ID,IP			TD		00:00.0
2021 PO4143585180	LGE	4	40 BRN	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4143785195	LGE	4	40 BRN	SP	CRE	ID,IP			TD		00:00.0
2021 PO4144085225	LGE	4	40 BRN	SP	CRE	ID,IP			TD		00:00.0
2021 PO4144385243	LGE	4	30 BRN	SP	CRE	ID,IP			TD		00:00.0
2021 PO4144686286	LGE	3	45 BRN	SP	P	ID			TD		00:00.0
2021 PO4145285194	LGE	6	25 BRN	SP	CRE	ID,IP			TD		00:00.0
2021 PO4145986261	LGE	3	45 BRN	SP	P	ID			TD		00:00.0
2021 PO4147685170	LGE	3	45 BRN	SP	P	ID,IP,SRC			TD		00:00.0
2021 PO4189386193	LGE	4	40 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4190586207	LGE	4	35 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4190786214	LGE	4	35 BRO	SP	A	ED,ID			TD		00:00.0
2021 PO4190886193	LGE	4	35 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4191686139	LGE	4	35 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4191686144	LGE	4	40 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4191786168	LGE	4	40 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4191786181	LGE	4	40 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4191786199	LGE	4	35 BRO	SP	A	ED,ID,IP			TD		00:00.0
2021 PO4191886209	LGE	4	35 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4191886217	LGE	4	40 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4191886224	LGE	4	40 BRO	SP	A	ED,ID,IP			TD		00:00.0
2021 PO4191886224-A	KU	5	35 BRO	SP	A	ED,ID,IP			TD		00:00.0
2021 PO4191886229	LGE	4	40 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4191886237	LGE	3	50 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4192186176	LGE	4	35 BRO	SP	A	ED,ID,IP			TD		00:00.0
2021 PO4192386230	LGE	4	30 BRO	SP	CRE	ED,ID,IP			TD		00:00.0
2021 PO4192486175	LGE	H5	25 BRO	SP	A	ED,ID			TD		00:00.0

2021 PO4193786167	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4193786175	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PV4130985789	LGE	3	45 BRN	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO4191886231	LGE	4	40 BRO	SP	A	ED	T	00:00.0
2021 PO4124986409	LGE	3	55 BRN	SP	CRE		BD	00:00.0
2021 PO4125086409	LGE	2	55 BRN	SP	P	ID,IP	BD	00:00.0
2021 PO4136486195	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4141685383	LGE	4	40 BRN	SP	P		BD	00:00.0
2021 PO4143785165	LGE	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4144085301	LGE	4	30 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4144586285	LGE	3	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4145786276	LGE	4	35 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4191786193	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO1787944308	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO1850042999	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO1862542883	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO1885042564	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO1939041165	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO1945841185	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO1951940622	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO1956040942	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO1981140266	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2003139982	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2028539676	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2050339375	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2076338877	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2102538415	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2115538143	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2178936980	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2196136673	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2205136501	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2216836289	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2427937697	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4926689373	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4829689416	LGE	4	40 BRO	SP	P	ID	BD	00:00.0
2021 PO4829689412	LGE	4	40 BRO	SP	P	ID	BD	00:00.0
2021 PO4937489980	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4979089585	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4715789931	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4850889575	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4924389378	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4975489584	LGE	3	50 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4900489950	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO5316808405	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4937289906	LGE	4	40 BRN	SP	P	ED,ID,MD	BD	00:00.0
2021 PO4936189902	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4853489565	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4854189562	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4939689905-a	KU	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO1028442692	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5435212128	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO4827789463	LGE	4	40 BRO	SP	P	ID,IP	BD	00:00.0
2021 PO4828089455	LGE	4	40 BRO	SP	P	ID	BD	00:00.0
2021 PO0866141295	ODP	4	40 UNK	SP	CRE	ID	BD	00:00.0

2021 PO5462111589	KU	4	40 ACW	SP	CRE	ED,ID	BD	00:00.0
2021 PO8144220684	ODP	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8184220750	ODP	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4730889868	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4730789872	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4895588984	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4896588986	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4847589616	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4849389599	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4732689840	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4729889817	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4731289828	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4803988744	LGE	2	50 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5380113055	KU	6	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5371413085	KU	6	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5357112912	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4974089358	LGE	2	55 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4921789384	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO5365012632	KU	2	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4933389874	LGE	4	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO8929622846	ODP	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4934989898	LGE	4	40 BRN	SP	P	ED,ID,MD	BD	00:00.0
2021 PO4871688587	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5306008725	KU	3	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4720390034	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4919188908	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO8695122389	ODP	4	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5372213320	KU	3	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5366213159	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4919788781	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4920388766	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO9182924218	ODP	5	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5410112680	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4832689435	LGE	4	40 BRN	SP	P	ID	BD	00:00.0
2021 PO4951389889	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4947689925	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4949489908	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4716689975	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5591419905	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO0277638199	ODP	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO7137019739	ODP	2	55 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5541012278	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO4918089939	LGE	3	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5327709242	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5357909122	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4719790018	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4719290011	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5334509214	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5372809062	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4963189381	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8964922842	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4935989775	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4918689922	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4873388602	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0

2021 PO4874188599	LGE	1	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4877088583	LGE	3	50 BRN	SP	A	ED	BD	00:00.0
2021 PO1387144539	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO1429144804	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4994389328	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4993889328	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO1398044607	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4919088811	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4918788810	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4918888808	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5432911250	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO4938189713	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4944989575	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4943589589	LGE	1	80 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4947189588	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO5432704020	LGE	4	35 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4703489909	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4945289561	LGE	2	50E ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8299419902	ODP	5	30 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4944289545	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8068020576	ODP	5	35 OTH	SP	CRE	ID,IP	BD	00:00.0
2021 PO7998120474	ODP	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO7979220448	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO7919320353	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO9097423603	ODP	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4925088798	LGE	4	30 BRO	SP	CRE	ID	BD	00:00.0
2021 PO1453544889	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4724789764	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5349912684	KU	4	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5342012423	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4825388626	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021 PO4823088639	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO9310723201	ODP	6	35 UNK	SP	P	ED,ID	BD	00:00.0
2021 PO4946889394	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4823489545	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4821389532	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4820589528	LGE	4	40 BRN	SP	P		BD	00:00.0
2021 PO5524212322	KU	3	45 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO7839420232	ODP	4	40 OTH	SP	CRE	ID,IP	BD	00:00.0
2021 PO4725789927	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8457321029	ODP	4	40 KOP	SP	CRE	ED	BD	00:00.0
2021 PO4949789400	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5393012010	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4831988738	LGE	4	30 BRO	SP	P	ID	BD	00:00.0
2021 PO5376811407	KU	4	35 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO5386911769	KU	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4725489914	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4946289506	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4928488814	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4929088827	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO8030020884	ODP	4	40 OTH	SP	CRE	ID,IP	BD	00:00.0
2021 PO4944689538	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4925888841	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4941389622	LGE	4	45 BRN	SP	CRE	ED,ID	BD	00:00.0

2021 PO4924488836	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4058610998	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4824589559	LGE	4	25 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO7796319613	ODP	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4946589377	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4730489809	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4945289368	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO8098221226	ODP	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4944189361	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO6487019812	ODP	6	30 KOP	SP	CRE	ID	BD	00:00.0
2021 PO4734990036	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4822088811	LGE	4	35 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4835289422	LGE	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5512311168	KU	3	45 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO5379910015	KU	6	30 BRN	SP	CRE	ID	BD	00:00.0
2021 PO7689620250	ODP	5	30 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4931889812	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4931789811	LGE	4	30 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4931889811	LGE	4	30 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4931789812	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO6492119611	ODP	4	40 KOP	SP	CRE		BD	00:00.0
2021 PO5511511144	KU	3	45 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO5392410042	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5306809430	KU	3	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4962389417	LGE	3	45 ACE	SP	S	ED,ID	BD	00:00.0
2021 PO5487010977	KU	6	30 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO9218025064	ODP	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9198124797	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4930589929	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4823188772	LGE	5	25 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5560120247	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4937890044	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4936390039	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO5514710916	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO4936490036	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO5525211558	KU	3	45 OTH	SP	CRE	ID	BD	00:00.0
2021 PO5539611506	KU	6	30 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO5332711941	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5328311951	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4826289557	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5531411536	KU	6	30 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO4846189363	LGE	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4830088680	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021 PO5513911636	KU	6	30 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO4845189350	LGE	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO5520811811	KU	2	40 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO4974889789	LGE	6	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7750844643	ODP	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0240933246	ODP	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4812488745	LGE	3	50 BRO	SP	P	ID	BD	00:00.0
2021 PO4945790120	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4946790104	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO9205624467	ODP	5	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4839589290	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0



2021	PO5399208955	KU	3	45 BRN	SP	CRE	ID,IP	BD	00:00.0	
2021	PO4826288774	LGE	5	25 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021	PO4933289853	LGE	3	50 BRN	SP	A	ED,ID	BD	00:00.0	
2021	PO4930689864	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021	PO9100624478	ODP	4	45 BRO	SP	CRE		BD	00:00.0	
2021	PO9110324727	ODP	2	50 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021	PO5320910359	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0	
2021	PO5389208994	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0	
2021	PO9674123261	ODP	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0	
2021	PO5398109369	KU	3	45 OTH	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4818488868	LGE	3	60 BRO	SP	P	ID	BD	00:00.0	
2021	PO4811288830	LGE	3	55 BRO	SP	P		BD	00:00.0	
2021	PO4817588866	LGE	3	55 BRO	SP	P	ID	BD	00:00.0	
2021	PO5542020437	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4736590072	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO4861688948	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4859888943	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021	PO7837116862	ODP	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4959889356	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0	
2021	PO4932789872	LGE	3	50 BRN	SP	A	ED,ID	BD	00:00.0	
2021	PO4931789893	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0	
2021	PO4931789895	LGE	3	50 BRN	SP	A	ED,ID	BD	00:00.0	
2021	PO4919388793	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021	PO4957389363	LGE	2	65 ACE	SP	CCA	ED,ID	BD	00:00.0	
2021	PO0718140622	ODP	6	30 ACVW	SP	CRE	ID,IP	BD	00:00.0	
2021	PO4931289988	LGE	4	35 BRN	SP	P	ED,ID	BD	00:00.0	
2021	PO4831589414	LGE	4	40 BRO	SP	P	ID	BD	00:00.0	
2021	PO4826289502	LGE	4	30 BRO	SP	CCA	ID	BD	00:00.0	
2021	PO4826689492	LGE	H3	45 BRO	SP	P	ID	BD	00:00.0	
2021	PO4929289991	LGE	4	35 BRN	SP	P	ED,ID	BD	00:00.0	
2021	PO4929189999	LGE	4	35 BRN	SP	P	ED,ID	BD	00:00.0	
2021	PO5304307121	KU	2	50 BRN	SP	CRE	ID	BD	00:00.0	
2021	PO4963589435	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0	
2021	PO4833289418	LGE	4	40 BRO	SP	P	ID,IP	BD	00:00.0	
2021	PO5601220374	KU	4	40 ACVW	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO7708020040	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0	
2021	PO4852288917	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021	PO6877748771	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO4448606412	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4434506394	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4792389451	F	4	40 ACE	SP	P		V	00:00.0	
2021	PO4455906267	F	4	40 BRN	SP	CRE	HH,ID,IP	BX	RP1	00:00.0
2021	PO4460406326	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021	PO4446906336	F	2	50 BRN	SP	CRE		V	00:00.0	
2021	PO4364585304	LGE	3	45 BRN	SP	A		V	00:00.0	
2021	PO4363085281	LGE	4	35 BRN	SP	A		V	00:00.0	
2021	PO4365585293	LGE	4	40 BRN	SP	A		V	00:00.0	
2021	PO4365085286	LGE	5	25 BRN	SP	A		V	00:00.0	
2021	PO6867248832	KU	1	75 UNK	SP	CRE		V	00:00.0	
2021	PO6891248802	KU	1	75 UNK	SP	CRE		V	00:00.0	
2021	PO6886548746	F	4	40 KOP	SP	P		V	00:00.0	
2021	PO6894748708	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO6894448678	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO6913148727	KU	1	75 UNK	SP	CRE		V	00:00.0	

2021	PO6923348635	F	5	35 UNK	SP	CRE		V		00:00.0
2021	PO6930648619	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO6931248675	KU	1	75 UNK	SP	CRE		V		00:00.0
2021	PO6940848594	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO6946448640	KU	1	75 UNK	SP	CRE		V		00:00.0
2021	PO6949048577	F	5	40 UNK	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO6957848563	F	5	35 BRO	SP	CRE		V		00:00.0
2021	PO6957048623	KU	1	75 UNK	CRE	CRE		V		00:00.0
2021	PO6971848599	KU	1	75 UNK	SP	CRE		V		00:00.0
2021	PO6976848533	F	5	40 UNK	SP	CRE		V		00:00.0
2021	PO6988548572	KU	1	75 UNK	SP	CRE		V		00:00.0
2021	PO6986948517	F	5	40 UNK	SP	CRE		V		00:00.0
2021	PO7000548554	KU	1	75 UNK	SP	CRE		V		00:00.0
2021	PO7019048467	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO7017248527	KU	1	75 UNK	SP	CRE		V		00:00.0
2021	PO7032648502	KU	1	75 UNK	SP	CRE		V		00:00.0
2021	PO7059048460	KU	1	85 UNK	ST	CCA		V		00:00.0
2021	PO7045948481	KU	1	85 UNK	ST	CCA		V		00:00.0
2021	PO7044448425	F	5	35 UNK	SP	CRE		V		00:00.0
2021	PO7051148414	F	5	35 UNK	SP	CRE		V		00:00.0
2021	PO9495057581	KU	4	45 BRN	SP	CCA		V		00:00.0
2021	PO9238663215	KU	5	35 OTH	SP	CCA		V		00:00.0
2021	PO9225662794	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9170763124	KU	5	35 OTH	SP	CRE	ED,SRS	TD		00:00.0
2021	PO9254363044	KU	5	35 OTH	SP	CRE	HH,ID,IP,RB	X	PX	00:00.0
2021	PO9199363451	KU	6	30 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021	PO9177263127	KU	5	30 OTH	SP	CRE	ID	BD		00:00.0
2021	PO9193362801	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9200862914	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9175063089	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9493957254	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO9508857348	KU	4	45 BRN	CCA	CRE		V		00:00.0
2021	PO9246962941	F	4	40 OTH	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	00:00.0
2021	PO9502257455	KU	4	40 BRN	SP	CCA		V		00:00.0
2021	PO9470457341	KU	3	45 BRN	SP	CCA		V		00:00.0
2021	PO9002862096	KU	5	35 BRO	SP	CRE		V		00:00.0
2021	PO9004162211	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9038062495	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4366085288	LGE	3	45 BRN	SP	A		V		00:00.0
2021	PO4366285293	LGE	4	35 BRN	SP	A		V		00:00.0
2021	PO9041562435	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO9016062560	KU	4	40 BRO	SP	S		V		00:00.0
2021	PO9511757759	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO7078148480	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO7075548486	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO9016162478	KU	6	30 BRO	SP	S		V		00:00.0
2021	PO9017862530	KU	5	35 BRO	SP	CRE		V		00:00.0
2021	PO7884246916	KU	4	40 UNK	SP	P	ID	BD		00:00.0
2021	PO9095063124	KU	5	35 BRO	CCA	CRE		V		00:00.0
2021	PO4482905402	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO9029862630	KU	3	45 BRO	CRE	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO9042162945	KU	2	70 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO0060301611	KU	3	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO0079801855	KU	3	40 ACE	SP	CRE	ED,ID	BD		00:00.0

2021 PO4365585264	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO4365185345	LGE	1	60 BRN	SP	A		V	00:00.0
2021 PO7771747365	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO7468846394	KU	4	45 UNK	UN	CRE		V	00:00.0
2021 PO7509645647	KU	6	35 BRN	SP	CCA		V	00:00.0
2021 PO7771347684	KU	6	30 KOP	SP	CRE		V	00:00.0
2021 PO7765647722A	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO4560606085	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4580506190	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4598606276	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4543305839	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4586006097	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO9499457816	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO4565705998	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4618406163	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4554405914	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4534505752	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4602606179	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4546105963	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4535805916	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0092902019	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0092002025	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9531857970	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO0113802281	KU	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0130702492	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9020263216	KU	2	70 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7928446971	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7918246997	KU	3	45 UNK	SP	CRE		V	00:00.0
2021 PO4947789209	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4945889218	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4945189212	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO0147902708	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0147102715	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0190403240	KU	2	60 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0218103587	KU	2	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0236803822	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0260204115	KU	3	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9551258311	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO9539358274	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO9567158198	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8994663525	KU	5	30 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO9047463355	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4252988062	LGE	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO6978248960	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO6963448984	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO6948649009	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7181748520	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7190047300	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7178147317	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO7162947598	KU	4	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7174247548	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4253288041	LGE	4	40 BRN	SP	A	ID	BD	00:00.0
2021 PO0277204328	KU	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9044563198	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0

2021	PO9066763180	KU	5	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO9106363144	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO0294804549	KU	3	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO0310204741	KU	3	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO0332605022	KU	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO9557058133	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO9098063179	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9097863770	KU	4	45 BRO	CCA	CRE		V		00:00.0
2021	PO4360804724	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4369104783	F	4	40 BRN	CRE	CRE	ID,IP	BX	RP2	00:00.0
2021	PO9485857734	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO9477057788	KU	3	50 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4470005209	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4504405494	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4446605205	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4453105102	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021	PO4405604918	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4512405702	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4497205565	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4497305424	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4488005330	F	3	40 BRN	SP	CRE		V		00:00.0
2021	PO4435904995	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4409104824	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4430605079	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4419304887	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4466305267	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021	PO4386704805	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4518705637	KU	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4415404988	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO9485857645	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO7175547791	KU	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021	PO7186947768	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO7189447765	KU	6	30 BRO	SP	CCA		V		00:00.0
2021	PO7213247712	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO7200247741	KU	5	30 ACV	SP	CRE	ID	BD		00:00.0
2021	PO6844948865	KU	1	75 BRO	SP	CCA		V		00:00.0
2021	PO6689749460	KU	6	30 BRO	SP	CCA		V		00:00.0
2021	PO6641249553	KU	5	35 BRO	SP	CCA		V		00:00.0
2021	PO4270487955	LGE	1	50 BRN	SP	CCA		V		00:00.0
2021	PO7191047520	KU	4	40 UNK	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021	PO4253588080	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021	PO9470157902	KU	5	45 BRN	CRE	CRE	ED,ID,IP,RB	X	PX	00:00.0
2021	PO9083863460	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO9089463548	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9097863403	KU	3	50 BRO	SP	S		V		00:00.0
2021	PO9098763543	KU	3	55 BRO	SP	S		V		00:00.0
2021	PO8870061771	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4218288372	LGE	4	40 BRN	SP	A		V		00:00.0
2021	PO9675493002	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021	PO9479657988	KU	5	35 BRN	SP	CCA		V		00:00.0
2021	PO9481758053	KU	5	45 BRN	SP	CRE		V		00:00.0
2021	PO8852461764	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9460158073	KU	3	50 BRN	CRE	CRE	RB	X	RP1	00:00.0
2021	PO4251488034	LGE	4	40 BRN	SP	CRE	ID,IP	BD		00:00.0

2021 PO4240787875	LGE	4	30 BRN	ST	CCA		V		00:00.0
2021 PO4264288207	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO9380160983	KU	4	45 XXX	SP	CRE	ED,HH,ID	X	RP3	00:00.0
2021 PO9468658813	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO9474458791	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO9642063427	KU	3	50 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9648063253	KU	3	50 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9634363162	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9383559354	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO9391359411	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9352957834	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9352057853	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9284561141	KU	2	50 OTH	SP	CCA		V		00:00.0
2021 PO9287761018	KU	2	50 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021 PO9397159336	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9421159310	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 N/A	KU	4	30 BRN	CCA	CRE		V		00:00.0
2021 PO4398104270	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO4446004474	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4427104378	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO9404559410	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9409159460	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9403959505	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9373059553	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO9615263103	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9267161236	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9274461597	KU	3	50 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021 PO9278361358	KU	2	60 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021 PO9274561259	KU	4	40 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021 PO9597963061	KU	4	45 BRO	CRE	CRE	ED,ID	X	PX	00:00.0
2021 PO9585463143	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9585063082	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9584763048	KU	2	55 BRO	SP	S		V		00:00.0
2021 PO9375759625	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9379159689	KU	6	30 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4570203462	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4458004550	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO4416904341	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4469604624	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO4483904718	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4387104228	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO4436204414	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO9410161641	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9319059756	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO4406004299	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO9360559757	KU	4	45 UNK	CRE	CRE		V		00:00.0
2021 PO9341058375	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO9356558131	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO9573263317	KU	2	55 BRO	SP	CCA		V		00:00.0
2021 PO9566963382	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9563163441	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9552463629	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9553163795	KU	2	50 BRO	SP	S		V		00:00.0
2021 PO9149162147	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0

2021	PO9360459742	KU	2	50 BRO	SP	P	ED	T	00:00.0
2021	PO9353459627	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO9344759660	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO9324859735	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO9406961743	KU	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO9335959864	KU	2	50 BRO	CRE	CRE		V	00:00.0
2021	PO9318059878	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021	PO9326059877	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO9323159908	KU	4	40 UNK	SP	CRE		V	00:00.0
2021	PO9343360080	KU	3	50 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO9236961228	KU	5	30 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9245961183	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9220361316	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9274860989	KU	4	40 OTH	SP	CRE	ED,EP,ID,SR	TX RR	00:00.0
2021	PO4572587986	LGE	3	25 ACE	SP	CCA		V	00:00.0
2021	PO7956482861	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO9102354438	F	4	40 BRN	SP	P		V	00:00.0
2021	PO8155883980	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8157683835	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8163683773	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO9134755302	F	4	40 BRN	SP	P		V	00:00.0
2021	PO9136755482	ODP	4	45 BRN	SP	S		V	00:00.0
2021	PO9147655196	ODP	4	45 BRN	SP	S		V	00:00.0
2021	PO9233455117	F	4	45 BRN	SP	CRE		V	00:00.0
2021	PO9251655145	F	4	45 BRN	SP	CRE		V	00:00.0
2021	PO9204755155	ODP	4	45 BRN	SP	S		V	00:00.0
2021	PO9204755155C	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021	PO9204755155B	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO9204755155A	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO9256554822	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO9261955510	ODP	6	30 BRN	SP	S		V	00:00.0
2021	PO9261955510	ODP	6	30 BRN	SP	S		V	00:00.0
2021	PO9235955927	ODP	5	35 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO8486155522	F	4	40 XXX	SP	P		V	00:00.0
2021	PO8876552533	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8542454106	ODP	5	45 XXX	SP	CRE		V	00:00.0
2021	PO8882552688	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8885952771	ODP	5	30 XXX	SP	CRE	ID	BD	00:00.0
2021	PO8898852899	ODP	4	40 XXX	SP	CRE	ID,IP	TD	00:00.0
2021	PO8857153631	F	4	40 XXX	SP	P		V	00:00.0
2021	PO8874653834	F	4	40 XXX	SP	P		V	00:00.0
2021	PO8876754023	F	4	40 XXX	SP	P		V	00:00.0
2021	PO8877854301	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021	PO8859554502	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8882654503	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021	PO888854665	ODP	6	30 XXX	SP	CRE		V	00:00.0
2021	PO8880854632	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021	PO8888854792	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021	PO8878554689	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8834954476	ODP	6	30 XXX	SP	CCA	ED	T	00:00.0
2021	PO8846454658	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021	PO8871154734	ODP	6	30 XXX	SP	CRE	ID,IP	TD	00:00.0
2021	PO8858954768	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8827754987	ODP	4	45 XXX	SP	CCA		V	00:00.0

2021 PO8502155521	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8518655370	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8545454611	F	5	40 XXX	SP	CRE		V	00:00.0
2021 PO8556854867	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8547954039	ODP	2	60 XXX	SP	CCA		V	00:00.0
2021 PO8529654088	ODP	1	80 XXX	SP	CCA		V	00:00.0
2021 PO8501754211	ODP	3	50 XXX	SP	CCA		V	00:00.0
2021 PO8468154434	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8461554470	ODP	3	50 XXX	SP	CCA		V	00:00.0
2021 PO8450154509	ODP	1	80 XXX	SP	CCA		V	00:00.0
2021 PO8415654664	ODP	2	55 XXX	SP	CCA		V	00:00.0
2021 PO8551153935	ODP	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8542854029	ODP	5	45 XXX	SP	CCA		V	00:00.0
2021 PO8568554024	ODP	4	40 XXX	SP	CCA	ED	T	00:00.0
2021 PO9248455494	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9195955295	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9195955295	ODP	5	35 BRN	SP	S		V	00:00.0
2021 PO9190855441	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO9174755787	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4563288137	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO9180855657	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9186655709	ODP	6	30 BRN	SP	S		V	00:00.0
2021 PO9185855865	ODP	6	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO9252656370	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO9247956539	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO9246456641	F	4	40 BRN	SP	P		V	00:00.0
2021 PO9222256490	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9286455833	ODP	4	30 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO9286655701	ODP	5	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9269356269	ODP	5	35 BRN	SP	CRE		V	00:00.0
2021 PO4562288138	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4561988145	F	4	55 ACE	SP	CRE		V	00:00.0
2021 PO4563188123	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4563388143	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5243333663	KU	5	35 UNK	SP	CRE	ED	BD	00:00.0
2021 PO4576188232	LGE	2	45 ACE	SP	CCA		V	00:00.0
2021 PO4576088228	LGE	2	45 ACE	SP	CCA		V	00:00.0
2021 PO4575288227	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO4573688219	F	3	60 ACE	SP	CRE		V	00:00.0
2021 PO4565688000	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4565188008	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4564588017	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4564488029	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4564088026	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4563388036	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4571988125	LGE	4	30 ACE	SP	A	ED	V	00:00.0
2021 PO8379254582	ODP	6	30 XXX	SP	CCA	ED	T	00:00.0
2021 PO8292053521	ODP	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4567088073	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4566788068	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4565988077	LGE	1	65 ACE	SP	P		V	00:00.0
2021 PO7997782537	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4568388052	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5259933717	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0

2021 PO4567688063	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO8018682495	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5256233616	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO4561588064	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4562388063	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4562488051	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO7984583974	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4562188055	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4560988074	LGE	1	45 ACE	SP	CCA		V	00:00.0
2021 PO7980683832	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4560688079	LGE	5	25 ACE	SP	CRE	ED,ID,MD	BD	00:00.0
2021 PO7978383621	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7973783402	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7970083214	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8552654297	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8558854319	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8382754905	ODP	1	80 XXX	SP	CCA		V	00:00.0
2021 PO4565288078	LGE	1	55 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4564988078	LGE	1	75 ACE	SP	CRE		V	00:00.0
2021 PO4563688079	LGE	1	65 ACE	SP	CRE		V	00:00.0
2021 PO9334756625	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9300456505	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9298056420	ODP	4	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO9283256559	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9295456766	F	4	40 BRN	SP	S		V	00:00.0
2021 PO9293056922	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4565788059	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO7961482786	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7958582615	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7967582593	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4571388125	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5276933538	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO4568188041	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4568888044	LGE	4	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8045682647	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8040982453	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8060682418	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8080482379	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8099582342	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5290733486	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO5303733436	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO4569688032	LGE	3	50 ACE	SP	CRE	ED,ID,MD	BD	00:00.0
2021 PO5312634042	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO4570488019	LGE	4	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7929383104	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7928182972	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7910182245	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7900782094	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7915182347	KU	3	40 ACE	SP	CCA		V	00:00.0
2021 PO7919982462	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7916381929	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7922182024	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7926982106	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7931782190	KU	6	30 ACE	SP	CCA		V	00:00.0



2021 PO7929982258	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7932882414	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7924582569	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8901252182	ODP	4	40 BRN	DF	CRE	ED,ID,IP	TD	00:00.0
2021 PO9105754098	F	4	40 BRN	SP	S		V	00:00.0
2021 PO7951582696	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7950082624	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO7942382847	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7943583001	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7949883058	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7961183070	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO9133255035	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7938384225	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1 00:00.0
2021 PO8936054451	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8925654267	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8907454597	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8922254678	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9077054816	ODP	5	35 BRN	SP	P	ED,ID,IP	TD	00:00.0
2021 PO9112054797	ODP	5	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9052554835	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9039854847	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO9038255024	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8380786900	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8386987121	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8392987340	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8398987557	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8404787778	F	4	40 ACE	SP	P		V	00:00.0
2021 PO9040955552	ODP	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO9026955655	ODP	5	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO9010355033	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8405686952	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8417886791	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8428486679	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8443486497	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8426186987	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8439384048	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9039955267	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9029655443	ODP	3	55 BRN	SP	S		V	00:00.0
2021 PO9040155432	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO8016183441	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8008783302	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8008583206	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9280458386	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9293758599	ODP	4	40 XXX	DF	CRE	ED,ID,IP,MD	TD	00:00.0
2021 PO8977758022	ODP	5	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8991258617	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8009083036	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8013982966	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8023282866	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8031582841	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8048982791	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8066982749	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8086182702	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8143082271	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0

2021 PO8140982263	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7870481688	KU	2	70 ACE	SP	CRE		V		00:00.0
2021 PO7874081703	KU	4	40 ACE	SP	CRE		V		00:00.0
2021 PO7872581814	KU	2	45 ACE	SP	CCA		V		00:00.0
2021 PO7887981962	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7894182025	KU	4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7954184194	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4473087710	LGE	3	50 BRO	SP	A	ED,ID,IP,RR	TX	RR	00:00.0
2021 PO4473287664	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4472587682	LGE	1	85 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4474387652	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO1381053586	KU	4	40 KOP	SP	CRE	ID	TD		00:00.0
2021 PO4050085900	LGE	3	45 BRO	DF	CRE		V		00:00.0
2021 PO4009885609	LGE	4	30 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4010685613	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4023385574	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4019285604	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4021285602	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4037585592	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4043885629	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4042685598	LGE	4	35 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4041985599	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4457288124	LGE	4	30 BRO	SP	P		V		00:00.0
2021 PO1276358769	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5268233934	KU	4	40 UNK	SP	CRE	ED	BD		00:00.0
2021 PO1312456364	KU	6	35 BRO	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO522383744	KU	5	35 UNK	SP	CRE	ED,ID	BD		00:00.0
2021 PO4470187718	LGE	1	105 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4457388101	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4456788122	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4455888126	LGE	4	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4460688144	LGE	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO1715693779	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO5219433629	KU	4	40 UNK	SP	CRE	ED,ID	BD		00:00.0
2021 PO4465787682	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4466487689	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4466787692	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4463987679	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4464887674	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4457788088	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4456988111	F	3	45 BRO	SP	P		V		00:00.0
2021 PO1299656458	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO1303156661	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO1283956598	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO1322356262	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO136685679	KU	6	35 UNK	SP	CRE	ED,ID	X	RP1	00:00.0
2021 PO5238025943	KU	6	30 UNK	SP	CRE		BD		00:00.0
2021 PO7906977782	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO1336956102	KU	6	35 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4482487812	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO1352255949	KU	6	35 UNK	SP	CRE	ID	TD		00:00.0
2021 PO3991884320	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3996684317	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3999184337	F	4	40 ACE	SP	CCA		V		00:00.0

2021 PO3998984316	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3998784318	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4000584310	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4000884314	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4001984313	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4002784313	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4002684306	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO0254302277	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0254402458	KU	4	40 BRO	SP	S	ED,SR	T	00:00.0
2021 PO0254402657	KU	4	35 BRO	SP	S	ED	T	00:00.0
2021 PO5786725612	F	4	35 BRN	SP	P		V	00:00.0
2021 PO4025284711	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5768925445	KU	4	35 MAR	SP	CCA		V	00:00.0
2021 PO5775425506	F	4	35 BRN	SP	P		V	00:00.0
2021 PO5739925984	F	4	35 BRN	SP	P		V	00:00.0
2021 PO5754725824	KU	H1	85 BRN	ST	CRE		V	00:00.0
2021 PO5766525695	F	4	35 BRN	SP	P		V	00:00.0
2021 PO5770825649	F	3	40 BRN	SP	P		V	00:00.0
2021 PO5747725333	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4045884685	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4044984780	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4044984679	LGE	4	35 ACE	SP	P	ED	TD	00:00.0
2021 PO4019384695	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4017884692	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4018084697	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4020384689	F	4	35 BRN	SP	CRE		V	00:00.0
2021 PO1384697768	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO9414896548	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9423096736	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4042684677	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4043584674	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4102184520	LGE	5	25 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4102484523	F	3	45E BRO	SP	P		V	00:00.0
2021 PO0253902820	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0253203038	KU	4	40 BRO	SP	S	ED	T	00:00.0
2021 PO0252503250	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0238903457	F	4	40 BRO	SP	P		V	00:00.0
2021 PO0242503612	F	4	40 BRO	SP	P		V	00:00.0
2021 PO0245603829	F	4	40 BRO	SP	P		V	00:00.0
2021 PO02456003829A	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO8168857167	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8166857167	LGE	3	45 BRO	UN	CRE		V	00:00.0
2021 PO4101284531	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4101884535	LGE	4	35 BRO	SP	CRE	ED,ID,RB	BX PX	00:00.0
2021 PO4100584544	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4100184539	F	3	50 BRO	SP	P		V	00:00.0
2021 PO4104084554	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4021184723	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4022584721	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4022584728	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4021084730	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4019484731	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4018684725	F	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4017484726	LGE	4	30 BRN	SP	CCA		V	00:00.0

2021 PO4017884733	F	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4014884736	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO4013284738	F	3	45 BRN	SP	A		V	00:00.0	
2021 PO4016284734	F	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4010684608	F	4	30 BRN	SP	P		V	00:00.0	
2021 PO4009984609	F	4	30 BRN	SP	CRE		V	00:00.0	
2021 PO4009884608	F	4	30 BRN	SP	CRE		V	00:00.0	
2021 PO4010784612	F	4	40 BRN	SP	P		V	00:00.0	
2021 PO4009984613	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4010084620	LGE	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4010484648	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO4010584658	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4010284636	F	4	40 BRN	SP	P		V	00:00.0	
2021 PO4010784671	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4011084683	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO4011184695	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4011384709	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4011584724	F	3	50 BRN	SP	CRE		V	00:00.0	
2021 PO4012184723	F	4	30 BRN	SP	CRE		V	00:00.0	
2021 PO4011884739	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4012084751	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4012184763	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO4011284765	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO4009584769	F	3	45 BRN	SP	A		V	00:00.0	
2021 PO4009484801	F	4	30 BRN	SP	CRE		V	00:00.0	
2021 PO4008884791	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4009984788	F	4	30 BRN	SP	CRE		V	00:00.0	
2021 PV4008384775	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO4008284774	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO4008484762	F	4	30 BRN	SP	A		V	00:00.0	
2021 PO4008084765	F	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4008084748	F	4	30 BRN	SP	CCA		V	00:00.0	
2021 PO4007484746	F	4	40 BRN	SP	CRE	ED,EP,ID	VX	PX	00:00.0
2021 PO4115385110	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4131485181	KU	5	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4148485260	KU	5	30 BRO	DF	CRE	ED,HH,ID,IP	TD		00:00.0
2021 PO4037084513	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4036684507	LGE	3	45 ACE	SP	A	ED	BD		00:00.0
2021 PO7678976406	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4037784510	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4038384528	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4040384533	LGE	1	45 ACE	SP	CRE		V		00:00.0
2021 PO7682475517	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO3988684136	F	1	60 ACE	SP	CCA		V		00:00.0
2021 PO4040083281	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4040483277	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO4036084490	LGE	3	45 ACE	SP	P	ED	TD		00:00.0
2021 PO7655575258	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7655675150	KU	2	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7656475058	KU	H1	85 ACE	SP	CRE		V		00:00.0
2021 PO7667674712	KU	1	70 ACE	SP	CRE		V		00:00.0
2021 PO3989684134	F	1	60 ACE	SP	CCA		V		00:00.0
2021 PO3990284134	LGE	1	60 ACE	SP	CCA		V		00:00.0
2021 PO3991784133	F	1	55 ACE	SP	CCA		V		00:00.0

2021 PO3993184132	F	UNK	55 ACE	SP	CRE		V		00:00.0
2021 PO3993284150	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO3992584171	F	4	30 ACE	SP	CCA	RB	VX	RP3	00:00.0
2021 PO3993484170	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4035584473	LGE	3	45 ACE	SP	A	ED	BD		00:00.0
2021 PO4041283281	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4163285086	KU	3	40 BRO	SP	P		B		00:00.0
2021 PO4148584916	KU	3	40 BRO	SP	P		B		00:00.0
2021 PO4119184576	KU	3	40 BRO	SP	P		B		00:00.0
2021 PO4155384551	KU	6	30 BRO	SP	S		V		00:00.0
2021 PO4089284598	KU	3	45 BRO	SP	S		V		00:00.0
2021 PO3939482562B	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4115584535	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO3884282391	KU	4	40 BRO	SP	S		V		00:00.0
2021 PO4116084543	LGE	4	40 BRO	SP	CRE		B		00:00.0
2021 PO3884282391A	KU	4	40 BRO	SP	S		V		00:00.0
2021 PV4007184735	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4006684720	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4007384722	F	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4003084669	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4006184705	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4006484701	F	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4006584684	LGE	7	25 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4005184691	LGE	4	30 BRN	SP	A	ED,HH,ID	TD		00:00.0
2021 PO4005584690	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4004284675	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4002484683	F	7	25 BRN	SP	CRE		V		00:00.0
2021 PO4003384684	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4003384699	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO9171396400	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO9139896564	KU	3	50 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9140596544	KU	3	50 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9224896571	KU	4	40 XXX	SP	P	ID	TD		00:00.0
2021 PO9057997269	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9067697142	KU	4	40 XXX	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO6237285113	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4045284660	LGE	3	45 ACE	SP	P	ED,ID	TX	RR	00:00.0
2021 PO4043484658	LGE	4	40 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4004784312	F	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4044384659	LGE	4	45 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4005884307	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4006284310	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4006384306	F	4	30 ACE	SP	P		V		00:00.0
2021 PO3988884171	F	3	50 ACE	SP	CRE	ED,HH,ID	VX	RP3	00:00.0
2021 PO3988684153	F	UNK	50 ACE	SP	CRE		V		00:00.0
2021 PO3988184160	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4135684409	LGE	5 25E	BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0020168580	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4040883269	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0013168305	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO0007468308	KU	6	30 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO9919288123	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4137984412	LGE	4	40 BRO	UN	CRE		V		00:00.0
2021 PO4136984433	LGE	UNK	45 BRO	UN	CRE		V		00:00.0

2021 PO4135484416	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4135384414	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4135884412	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4136884424	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4137984429	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO7517972308	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO7207755554	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4003284374	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4001284376	F	4	35 ACE	SP	P		V	00:00.0
2021 PV4000684380	LGE	4	30 ACE	SP	P	ED,ID,RB	VX	RP2 00:00.0
2021 PO3997884381	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO3997184378	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO1302198786	KU	4	40 BRN	SP	CRE		TD	00:00.0
2021 PO1202998203	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7530572144	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4038783216	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO7543571979	KU	3	40 ACE	SP	CCA		V	00:00.0
2021 PO1190198044	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO7556671811	KU	3	40 ACE	SP	CCA		V	00:00.0
2021 PO7569971641	KU	3	40 ACE	SP	CCA		V	00:00.0
2021 PO1188797853	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4039083230	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4038983242	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4098084602	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4096784648	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4129684436	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4098284644	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4099784635	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4099784635-A	KU	4	30E BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4014484674	LGE	4	35 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO4018984657	F	4	35 BRN	SP	P		V	00:00.0
2021 PO4017684651	LGE	4	35 BRN	SP	A	ID	BD	00:00.0
2021 PO4017884659	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4016684661	F	4	35 BRN	SP	CRE		V	00:00.0
2021 PO7610675119	KU	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7599375225	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7585975102	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO1157898359	KU	5	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4014284650	LGE	4	35 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO4014184661	LGE	4	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4014984658	LGE	4	35 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO7561575088	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7551675082	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4039483240	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9907187290	KU	6	30 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO3999284356	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3999384377	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3999584396	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3999784410	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3994084265	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3992784283	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3994284281	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO1474498144	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3994284292	F	3	45 ACE	SP	CCA		V	00:00.0

2021 PO3994384303	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3994584319	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3994584329	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3994184329	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3994784349	F	4	40 ACE	SP	P		V	00:00.0
2021 PO3993984348	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO3979683796	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3981783810	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3980783810	F	5	25 BRO	SP	CRE		V	00:00.0
2021 PO3982283819	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7832074091	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7800673864	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3994884370	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3994984379	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3995084394	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3995084403	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3995184413	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3995284434	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3994884437	LGE	4	30 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO3990384413	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7065255860	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO1423098290	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO1492798265	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021 PO1487498462	KU	4	35 BRO	SP	CCA		V	00:00.0
2021 PO3984083819	F	5	25 BRO	SP	CRE		V	00:00.0
2021 PO3983583825	F	4	40 BRO	SP	A		V	00:00.0
2021 PO7799873888	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7801773899	KU	5	35 ACE	SP	CRE	ED,EP,ID,IP	BD	00:00.0
2021 PO7802873906	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3985083827	F	4	25 BRO	SP	A		V	00:00.0
2021 PO3984483833	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3986083839	F	5	25 BRO	SP	CRE		V	00:00.0
2021 PO4480780364	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3986583856	F	5	25 BRO	SP	CRE		V	00:00.0
2021 PO7559006645	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7548606611	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7529606775	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO7530306641	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7537106581	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7560906884	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO7421205399	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7413005532	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7562107016	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO7259606044	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7265306119	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7269906179	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5562013794	F	2	45 BRO	SP	P		V	00:00.0
2021 PO5553913784	F	4	40 BRO	SP	P		V	00:00.0
2021 PO5544913822	F	4	40 BRO	SP	P		V	00:00.0
2021 PO5531813872	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5518413925	F	3	40 MAR	SP	P		V	00:00.0
2021 PO5489914040	F	3	40 CPT	SP	P		V	00:00.0
2021 PO5482214074	F	4	40 BRO	SP	P		V	00:00.0
2021 PO5477414125	F	3	40 MAR	SP	P		V	00:00.0

2021	PO5414214006	F	4	40 BRO	SP	P	V	00:00.0
2021	PO7285805410	F	3	45 BRN	SP	CRE	V	00:00.0
2021	PO7288805870	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO7280905945	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO7273206016	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5559213646	F	2	45 UNK	SP	P	V	00:00.0
2021	PO5413514121	KU	6	30 BRO	SP	CCA	V	00:00.0
2021	PO5422114186	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5419914130	F	2	45 BRO	SP	P	V	00:00.0
2021	PO5427614096	F	2	45 UNK	SP	P	V	00:00.0
2021	PO5690013273	F	4	40 UNK	SP	P	V	00:00.0
2021	PO5744113151	KU	5	35 BRO	SP	CCA	V	00:00.0
2021	PO5736413161	KU	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5729212965	F	5	40 UNK	SP	P	V	00:00.0
2021	PO5603713292	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5487114209	F	5	35 BRO	SP	P	V	00:00.0
2021	PO7218205817	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO7374005975	F	3	45 BRN	SP	CCA	V	00:00.0
2021	PO5457907322	F	3	45 BRN	SP	CRE	V	00:00.0
2021	PO5458607346	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO5476907208	F	5	35 BRN	SP	CRE	V	00:00.0
2021	PO5482107128	F	3	45 BRN	SP	CRE	V	00:00.0
2021	PO5503106909	F	3	45 BRN	SP	CRE	V	00:00.0
2021	PO5504406921	F	3	45 BRN	SP	CRE	V	00:00.0
2021	PO5512106814	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5609612580	KU	5	35 BRO	SP	CCA	V	00:00.0
2021	PO5222905589	KU	1	50 XXX	SP	S	V	00:00.0
2021	PO7490806496	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5444713417	KU	2	50 BRO	SP	CCA	V	00:00.0
2021	PO5431913489	KU	2	50 BRO	SP	CCA	V	00:00.0
2021	PO7524106694	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO7537506899	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO7563007105	F	2	45 BRN	SP	CRE	V	00:00.0
2021	PO5380413514	F	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5243205719	KU	2	50 XXX	SP	S	V	00:00.0
2021	PO5451713376	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5231205563	KU	1	55 XXX	SP	S	V	00:00.0
2021	PO7391806164	F	3	45 XXX	SP	CRE	V	00:00.0
2021	PO7383306247	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO7365705881	F	4	30 BRN	SP	CRE	V	00:00.0
2021	PO7357005771	F	4	30 BRN	SP	CRE	V	00:00.0
2021	PO7349405678	F	4	40 BRN	SP	CCA	V	00:00.0
2021	PO5514713214	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5510313241	F	4	40 BRO	SP	P	V	00:00.0
2021	PO7310305670	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO7299705769	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO7559008348	KU	2	50 XXX	SP	S	V	00:00.0
2021	PO5563012941	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5550913011	F	4	40 BRO	SP	P	V	00:00.0
2021	PO7559908643	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5537113088	F	4	40 BRO	SP	P	V	00:00.0
2021	PO7567706373	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO7523705921	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO7530506284	F	4	40 BRN	SP	CRE	V	00:00.0



2021 PO7513606007	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7522605947	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7504406047	F	6	30 BRN	SP	CRE	V	00:00.0
2021 PO7497706114	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7518606317	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7486606184	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7509006380	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7501906424	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7476106254	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7485706407	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7439906115	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7446006077	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7451106045	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7455105701	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7444805770	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7428105831	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7434205824	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7434305728	F	4	45 BRN	SP	CRE	V	00:00.0
2021 PO7440805625	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7501705376	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7536105965	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5594913480	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5587713305	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5575513334	F	3	40 MAR	SP	P	V	00:00.0
2021 PO5557813379	F	3	40 UNK	SP	P	V	00:00.0
2021 PO5550413281	F	4	40 UNK	SP	P	V	00:00.0
2021 PO5554013394	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5581913595	F	4	35 UNK	SP	P	V	00:00.0
2021 PO7459007440	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7457507348	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7455307278	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7453007206	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7512906679	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7457607625	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5539613601	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO7442007071	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7448707131	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7458307540	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7416706983	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7434707006	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7455207814	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO7301805057	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7313205186	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7331905453	F	3	50 BRN	SP	CRE	V	00:00.0
2021 PO7324205343	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5413913801	F	2	45 UNK	SP	P	V	00:00.0
2021 PO7255205679	F	3	45 BRN	SP	CRE	V	00:00.0
2021 PO7244905779	F	3	45 BRN	SP	CRE	V	00:00.0
2021 PO5456013986	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5462213961	F	4	40 BRO	SP	P	V	00:00.0
2021 PO5468413933	F	3	40 BRO	SP	P	V	00:00.0
2021 PO5486813813	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO5499413762	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5515713697	F	5	40 UNK	SP	CRE	V	00:00.0

2021	PO5405613638	KU	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5424313531	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5386613746	F	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5573612884	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5497213314	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5458113537	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5432813677	F	2	45 BRO	SP	P	V	00:00.0
2021	PO7408106318	F	2	40 XXX	SP	P	V	00:00.0
2021	PO7416806407	F	2	45 XXX	SP	P	V	00:00.0
2021	PO7432406537	F	2	45 XXX	SP	P	V	00:00.0
2021	PO7423906466	F	2	40 XXX	SP	P	V	00:00.0
2021	PO7416606639	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO7405906706	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO7395306775	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO7386806842	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5499008594	F	4	40 BRN	SP	CCA	V	00:00.0
2021	PO5492008621	F	3	60 BRN	SP	CRE	V	00:00.0
2021	PO5510908395	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5514408534	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5524208353	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5526408486	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5534808453	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5573208305	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5567408327	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5585307926	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5510412728	KU	4	45 BRO	SP	CCA	V	00:00.0
2021	PO5511112729	KU	4	45 BRO	SP	CCA	V	00:00.0
2021	PO5513312730	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5520312886	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5554807292	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5561007549	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5571407977	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5568407855	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5563807668	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5893512948	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5889812798	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5887412660	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5885112526	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5883012413	F	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5860513001	F	4	40 UNK	SP	P	V	00:00.0
2021	PO5590008239	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5579508280	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5578208227	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5507708561	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5530607263	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO5829112672	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5817412699	F	4	40 CPT	SP	CRE	V	00:00.0
2021	PO5835412658	F	3	40 CPT	SP	CRE	V	00:00.0
2021	PO5255707183	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5784112545	KU	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5788712679	KU	5	35 BRO	SP	CCA	V	00:00.0
2021	PO5790412748	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5803412732	F	4	40 UNK	SP	P	V	00:00.0
2021	PO5210807460	KU	4	40 XXX	SP	S	V	00:00.0

2021 PO7424007408	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7422206229	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7429206184	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7401005764	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7391805943	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7428807530	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7423107538	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7429307595	F	4	40 XXX	SP	CRE	ED,EP	V	00:00.0
2021 PO7429307650	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7407005647	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5443914269	F	3	45 UNK	SP	P		V	00:00.0
2021 PO5425514265	F	4	40 UNK	SP	P		V	00:00.0
2021 PO5430514399	F	4	40 UNK	SP	P		V	00:00.0
2021 PO7446706447	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7444206466	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO7467606292	F	6	30 XXX	SP	CRE		V	00:00.0
2021 PO5464413144	KU	3	45 BRO	SP	CRE		V	00:00.0
2021 PO5465213121	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7566506060	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7551506014	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7542306291	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7555106332	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5552512851	F	5	40 UNK	SP	CRE		V	00:00.0
2021 PO5532012901	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5536212879	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5538012892	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5480913204	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5180408294	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO5185008277	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO5200808217	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5655212125	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5666112026	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5668412079	F	3	45 MAR	SP	CCA		V	00:00.0
2021 PO5683312025	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5696511977	F	4	40 UNK	SP	P		V	00:00.0
2021 PO5710311925	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5435210881	KU	6	30 XXX	SP	S		V	00:00.0
2021 PO5421210909	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5420110883	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5474910642	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5460710706	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5446410768	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5434310821	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5269508531	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5250108576	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5232608596	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5185508680	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5171308702	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5167108689	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5295009575	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO5291709234A	KU	3	40 XXX	SP	S		V	00:00.0
2021 PO5557412231	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5556212337	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5292109146	KU	2	50 XXX	SP	S		V	00:00.0

2021	PO5292809040	KU	2	50 XXX	SP	S		V	00:00.0
2021	PO5293408907	KU	2	50 XXX	SP	S		V	00:00.0
2021	PO5294408706	KU	2	50 XXX	SP	S		V	00:00.0
2021	PO5565611909	F	1	65 BRO	SP	CCA		V	00:00.0
2021	PO5585211836	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5573711890	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5084607962	KU	3	40 XXX	ST	CRE		V	00:00.0
2021	PO5029406685	KU	4	45 XXX	SP	S		V	00:00.0
2021	PO5015306347	KU	3	45 XXX	SP	S		V	00:00.0
2021	PO5021406479	KU	4	45 XXX	SP	S		V	00:00.0
2021	PO5549612544	KU	3	45 BRO	SP	CRE		V	00:00.0
2021	PO5543012564	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5541612568	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5562912775	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4937708560	KU	2	45 XXX	SP	S		V	00:00.0
2021	PO5626811780	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5639611730	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO9249461281	KU	4	45 OTH	SP	CRE	ID	BD	00:00.0
2021	PO9259461083	KU	5	35 OTH	SP	CRE	ID	BD	00:00.0
2021	PO9405961678	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021	PO9393961788	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO9380261898	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO9372662021	KU	6	30 XXX	SP	CCA		V	00:00.0
2021	PO4820988825	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO7728719813	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021	PO4734190025	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4941789984	LGE	1	50 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4939589987	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4831489473	LGE	4	40 BRN	SP	P	ID	BD	00:00.0
2021	PO4830789532	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021	PO4830389494	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021	PO4830089506	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021	PO4829789511	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021	PO4829489521	LGE	4	30 BRN	SP	CCA		BD	00:00.0
2021	PO4966489478	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0
2021	PO8947022385	ODP	4	40 KOP	SP	CRE		BD	00:00.0
2021	PO5596020328	KU	3	45 OTH	SP	CCA	ED,ID,IP	BD	00:00.0
2021	PO4964189443	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0
2021	PO0822040967	ODP	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4930889997	LGE	4	35 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4978789708	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0
2021	PO4827089481	LGE	H3	45 BRO	SP	P	ID	BD	00:00.0
2021	PO5299607401	KU	2	50 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO4827489470	LGE	H3	45 BRO	SP	P	ID	BD	00:00.0
2021	PO5314110390	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4726189795	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4833989465	LGE	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4940690139	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO4831589521	LGE	3	50 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4735890054	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4939390048	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4941090022	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4939990051	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO4937590099	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0

2021 PO4936090126	LGE	3	50 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4885488596	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO6102196112	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6098496093	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6090996041	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO0157091761	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0187791749	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6025696572	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6043096627	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6054096666	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6076796790	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6081896627	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6086496476	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO60909696341	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6095196195	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4411185287	F	4	40 BRO	SP	A		V	00:00.0
2021 PO2000668749	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO1988868916	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO2013768564	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO2026868379	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO1999568842	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO2017068598	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO2008568718	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4404885291	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4404885291	KU	6	25 BRO	SP	CRE		V	00:00.0
2021 PO6055195795	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6049595757	F	2	45 ACE	SP	CCA		V	00:00.0
2021 PO4437585475	LGE	UNK	55 ACE	SP	CCA		V	00:00.0
2021 PO4408085289	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4422785281	F	4	40 BRO	SP	A		V	00:00.0
2021 PO6334900890	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO1648968356	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO1648168427	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4450685596	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4451285611	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO1647668521	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6258502009	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO4425085280	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4418185283	F	3	45 BRO	SP	A		V	00:00.0
2021 PO6007896878	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4420185287	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO0160491294	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0193191544	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4421585282	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4421685287	F	4	30 BRO	SP	CCA		V	00:00.0
2021 PO6382403505	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO0095396042	KU	3	40 BRO	SP	CCA		V	00:00.0
2021 PO0068796026	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4463285743	LGE	4	35 ACE	SP	A	ED	V	00:00.0
2021 PO6341003199	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4426185407-A	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4464885758	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6426403056	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6416103161	F	4	40 ACE	SP	CRE		V	00:00.0

2021	PO6404803276	F	4	40 ACE	SP	P	V	00:00.0
2021	PO6393603391	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6374403604	F	4	40 ACE	SP	P	V	00:00.0
2021	PO6371803629	F	4	40 ACE	SP	P	V	00:00.0
2021	PO6368303590	F	4	40 ACE	SP	P	V	00:00.0
2021	PO0036493570	KU	6	30 KOP	SP	CCA	V	00:00.0
2021	PO0022693559	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO0023393421	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO0024293271	F	5	40 UNK	SP	CRE	V	00:00.0
2021	PO0025293120	F	5	40 UNK	SP	CRE	V	00:00.0
2021	PO0026492901	F	5	40 UNK	SP	CRE	V	00:00.0
2021	PO8824092408	KU	4	40 XXX	SP	S	V	00:00.0
2021	PO4474285617	LGE	2	55 ACE	SP	CCA	V	00:00.0
2021	PO6160797615	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6164997421	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6167997285	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6137498772	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO0042097565	KU	4	40 KOP	SP	CCA	V	00:00.0
2021	PO6142598543	KU	1	55 ACE	SP	CCA	V	00:00.0
2021	PO6146098369	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6148398256	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6151198110	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6154097953	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5979499549	KU	H1	85 ACE	ST	CRE	V	00:00.0
2021	PO5806400616	F	4	45 ACE	SP	CRE	V	00:00.0
2021	PO5812400582	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5940998496	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5933298501	KU	4	40 ACE	SP	P	V	00:00.0
2021	PO4496415768	KU	2	55 XXX	SP	CCA	V	00:00.0
2021	PO4627409138	F	4	40 XXX	SP	CCA	V	00:00.0
2021	PO4760007774	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO4542415647	KU	1	50 XXX	SP	CCA	V	00:00.0
2021	PO4528315504	KU	2	50 XXX	SP	CCA	V	00:00.0
2021	PO4487315999	KU	2	50 XXX	SP	CCA	V	00:00.0
2021	PO4563015836	KU	1	50 XXX	SP	CCA	V	00:00.0
2021	PO4580815999	KU	1	55 XXX	SP	CCA	V	00:00.0
2021	PO4601216177	KU	2	50 XXX	SP	CCA	V	00:00.0
2021	PO4291014124	KU	2	50 XXX	SP	CCA	V	00:00.0
2021	PO4299814481	KU	2	50 XXX	SP	CCA	V	00:00.0
2021	PO4286913957	KU	4	45 XXX	SP	CCA	V	00:00.0
2021	PO4295514308	KU	2	50 XXX	SP	CCA	V	00:00.0
2021	PO9143596387	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO9143596387A	KU	3	40 XXX	SP	S	V	00:00.0
2021	PO0125090277	F	5	40 SWP	SP	CCA	V	00:00.0
2021	PO9113396869	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5852008808	KU	3	45 XXX	SP	CCA	V	00:00.0
2021	PO5825608298	F	5	35 XXX	SP	CRE	V	00:00.0
2021	PO5836408276	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5834308147	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5832807989	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5896507040	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5877007055	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5839204534	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO0028792501	F	5	40 UNK	SP	CRE	V	00:00.0

2021	PO0029592364	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO4419385336	F	2	50 BRO	SP	A		V	00:00.0
2021	PO1359165699	F	1	50 BRO	SP	CCA		V	00:00.0
2021	PO4420685335	F	3	50 BRO	SP	A		V	00:00.0
2021	PO4420385341	F	3	45 BRO	SP	A		V	00:00.0
2021	PO5772909064	KU	6	30 XXX	SP	CRE		V	00:00.0
2021	PO5854308835A	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4417685341	F	3	50 BRO	SP	A		V	00:00.0
2021	PO5858008877	KU	3	50 XXX	SP	CCA		V	00:00.0
2021	PO5771104464	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO5781604503	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO5788104506	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO5830404248	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5833304057	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5833403910	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5827804414	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5827404441	KU	4	45 XXX	SP	CCA		V	00:00.0
2021	PO5816204469	KU	4	45 XXX	SP	CCA		V	00:00.0
2021	PO5803504500	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5793004526	KU	4	45 XXX	SP	CCA		V	00:00.0
2021	PO5796404612	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5784404716	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO9181296159	KU	2	55 XXX	SP	S		V	00:00.0
2021	PO9199595837	KU	3	50 XXX	SP	S		V	00:00.0
2021	PO9208195782	KU	5	35 XXX	SP	S		V	00:00.0
2021	PO9214995736	KU	3	50 XXX	SP	S		V	00:00.0
2021	PO4413885290	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4412785292	F	4	30 BRO	SP	A		V	00:00.0
2021	PO4442485681	LGE	3H	45 BRO	SP	CCA		V	00:00.0
2021	PO5938199758	KU	1	80 ACE	ST	CRE		V	00:00.0
2021	PO5905899943	F	4	45 ACE	SP	CRE		V	00:00.0
2021	PO5893600011	KU	1	80 ACE	ST	CRE		V	00:00.0
2021	PO4396885343	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO5854600223	KU	H1	85 ACE	ST	CRE		V	00:00.0
2021	PO4397385336	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO5841500288	F	4	45 ACE	SP	CRE		V	00:00.0
2021	PO4398085342	F	4	35 BRO	SP	CCA		V	00:00.0
2021	PO5830100375	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO5823200386	KU	H1	85 ACE	ST	CRE		V	00:00.0
2021	PO4460385576	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO0018594221	KU	4	40 KOP	SP	CCA		V	00:00.0
2021	PO0025194032	KU	3	50 BRO	SP	CCA		V	00:00.0
2021	PO0021693720	F	5	40 UNK	SP	CRE	ED	V	00:00.0
2021	PO0020593892	F	4	40 UNK	SP	CRE	ED	V	00:00.0
2021	PO4467785724	LGE	UNK	60 ACE	SP	CRE		V	00:00.0
2021	PO5805500497	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5797800539	F	4	45 ACE	SP	CRE		V	00:00.0
2021	PO4398385336	F	4	35 BRO	SP	A		V	00:00.0
2021	PO4398885332	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4399485345	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5871900134	F	4	45 ACE	SP	CRE		V	00:00.0
2021	PO5866200130	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO1103665640	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO1111065699	LGE	4	35 BRO	SP	CCA		V	00:00.0

2021 PO4415785284	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4462585584	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4388185365	F	4	35 BRO	SP	A		V	00:00.0
2021 PO8486600786	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO8482500799	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO5817000421	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5811300455	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8321902033	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO8236100876	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8345297596	KU	3	40 XXX	SP	S		V	00:00.0
2021 PO8430301240	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO8413801360	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO9224996408	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO9243696293	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO9241596307	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO9245696284	KU	4	45 XXX	SP	S		V	00:00.0
2021 PO0184888624	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0183588748	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0165189170	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO0153889453	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO0068889307	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO0104389570	KU	3	55 UNK	SP	CCA		V	00:00.0
2021 PO4408085660	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6243002273	F	1	55 ACE	SP	CRE		V	00:00.0
2021 PO6238802107	F	1	55 ACE	SP	CRE		V	00:00.0
2021 PO4427385279	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4426285280	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4416985289	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4417085284	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4450985383	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4431111564	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4433585285	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4433785298	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO6328300508	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6309800610	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6264002664	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6245802565	F	4	50 ACE	SP	CRE		V	00:00.0
2021 PO6243002273a	KU	4	40 ACE	SP	P		V	00:00.0
2021 PO0008191545	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4452485559	LGE	UNK	65 ACE	SP	CRE	ED	V	00:00.0
2021 PO4480785719	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO4484385670	LGE	UNK	45 ACE	SP	A		V	00:00.0
2021 PO5960496754	F	4	40 ACE	SP	P		V	00:00.0
2021 PO5969996773	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5975296895	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5980597004	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5985697106	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6356103454	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6350903396	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6345203331	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6171897132	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6174597031	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5978896619	KU	4	30 ACE	ST	CRE		V	00:00.0
2021 PO0017597681	KU	4	40 UNK	SP	CCA		V	00:00.0



2021 PO9978797865	KU	4	40 UNK	SP	CCA	V	00:00.0
2021 PO4399985235	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO6196596186	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4592111216	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 PO9994291337	KU	5	45 UNK	SP	CRE	V	00:00.0
2021 PO9971398001	KU	4	40 UNK	SP	CCA	V	00:00.0
2021 PO5851497997	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5842497922	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5829597816	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO9979188355	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO5861196800	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5823597757	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5818297675	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5811497563	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5814497390	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5794197491	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5785497377	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5795097274	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO0010190378	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO0017690552	F	5	40 UNK	SP	CRE	V	00:00.0
2021 PO0007990544	F	4	40 UNK	SP	P	V	00:00.0
2021 PO1975869099	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4399485264	F	3	45 BRO	SP	CRE	V	00:00.0
2021 PO4399185268	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO0014189851	F	5	40 UNK	SP	P	V	00:00.0
2021 PO0013389995	F	3	40 CPT	SP	P	V	00:00.0
2021 PO5876896590	KU	4	40 ACE	SP	CCA	V	00:00.0
2021 PO5888996753	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6265003252	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4425785348	F	3	50 BRO	SP	A	V	00:00.0
2021 PO8737592889	KU	4	40 XXX	SP	S	V	00:00.0
2021 PO8782393110	KU	4	40 XXX	SP	S	V	00:00.0
2021 PO8767793149	KU	4	40 XXX	SP	S	V	00:00.0
2021 PO5961696602	KU	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4466385748	LGE	UNK	55 ACE	SP	CRE	V	00:00.0
2021 PO6249303101	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6257303104	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4425485327	F	3	45 BRO	SP	A	V	00:00.0
2021 PO4423785333	F	2	50 BRO	SP	A	V	00:00.0
2021 PO1772471726	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4463785904	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4463385905	LGE	1	50 ACE	SP	CCA	V	00:00.0
2021 PO4462185876	F	3	50 ACE	SP	CRE	V	00:00.0
2021 PO7920910558	KU	2	55 BRN	SP	CCA	V	00:00.0
2021 PO1704570919	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4456185835	LGE	1	65 ACE	SP	P	V	00:00.0
2021 1778572426-a	LGE	3	35 ACE	SP	CCA	V	00:00.0
2021 PO9637296333	KU	4	45 XXX	SP	S	V	00:00.0
2021 PO9600595361	KU	4	45 XXX	SP	CRE	V	00:00.0
2021 PO7914110504	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4529887725	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4529387733	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4429285847	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4532687755	F	4	40 BRO	SP	CRE	V	00:00.0

2021 PO4532887760	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4534187732	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4429585760	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4428085783	F	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4536587693	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4535787706	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4537387681	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4427485791	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4426985798	F	2	55 BRO	SP	A		V	00:00.0
2021 PO4426285794	F	4	40 BRO	SP	A		V	00:00.0
2021 PO1401770340	LGE	2	50 BRO	SP	CCA		V	00:00.0
2021 PO4425585789	F	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4424685784	F	3	50 BRO	SP	CCA		V	00:00.0
2021 PO7948810363	KU	3	50 BRN	SP	CCA		V	00:00.0
2021 PO7943410267	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4422485771	F	3	55 BRO	SP	CRE		V	00:00.0
2021 PO4423885779	F	3	50 BRO	SP	CRE		V	00:00.0
2021 PO7931810339	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7938310440	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 PO3912414133	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4450385757	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4464386069	F	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4459986044	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4459786044	LGE	3	45 ACE	SP	CCA	ED	V	00:00.0
2021 PO9660693636	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO3564816183	KU	2	60 BRN	SP	CCA		V	00:00.0
2021 PO3589616128	KU	2	60 BRN	SP	CRE		V	00:00.0
2021 PO7975611750	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4263813636	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO8090612288	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7995912055	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO7960811552	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3572616335	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO9744394902	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9817894494	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO9483098298	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO7801907058	F	2	50 BRN	SP	CRE		V	00:00.0
2021 PO7806406968	F	2	50 BRN	SP	CRE		V	00:00.0
2021 PO7814506933	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7823806841	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4472985984	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4469185898	LGE	3	45 ACE	SP	CCA	ED	V	00:00.0
2021 PO4471885896	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4474085893	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4475485892	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO9663294259	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9660594213	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO9654894123	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9654094010	KU	3	45 XXX	SP	CRE		V	00:00.0
2021 PO9644493858	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO3624617954	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4225412531	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4217512331	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4223812293	KU	6	30 XXX	SP	CCA		V	00:00.0

2021 PO8098412220	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4237012879	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4240112970	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO8042112042	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8033312199	KU	4	50 BRN	SP	CCA		V	00:00.0
2021 PO4248213199	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4253713358	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO1407173151	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1405972970	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4426686050	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO9653495504	KU	5	45 XXX	SP	S		V	00:00.0
2021 PO9650495567	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO9454095020	KU	3	45 XXX	SP	CRE		V	00:00.0
2021 PO9446395042	KU	5	35 XXX	SP	CRE		V	00:00.0
2021 PO4397585321	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4426686040	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4538187839	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4536087825	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4424585993	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4424586003	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4424586016	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4424586031	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4424585952	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4427985930	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4427885953	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4425985967	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4424585965	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4424585979	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4470585962	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4469185986	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4469085991	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4471085985	LGE	4	40 ACE	SP	CCA	ED	V	00:00.0
2021 PO4472486016	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4465185949	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4466685939	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4467885937	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4467385992	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO9303390331	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9295091067	KU	4	40 KOP	SP	CCA		V	00:00.0
2021 PO4391085260	F	1	55 BRO	SP	CCA		V	00:00.0
2021 PO4391985268	F	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4392385271	F	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4453785704	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO9676698633	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4479385627	LGE	3	50 ACE	SP	P	ED	V	00:00.0
2021 PO4462885510	LGE	UNK	65 ACE	SP	CRE		V	00:00.0
2021 PO4464585522	LGE	UNK	65 ACE	SP	CRE		V	00:00.0
2021 PO7995010076	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4478285619	LGE	3	50 ACE	SP	A		V	00:00.0
2021 PO1626770265	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO1624870247	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4449185780	LGE	2	65 ACE	SP	CRE		V	00:00.0
2021 PO5889297866	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5887497838	F	4	40 ACE	SP	CRE		V	00:00.0

2021	PO4450785755	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO4456185461	LGE	UNK	60 ACE	SP	CRE	V	00:00.0
2021	PO4458785485	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021	PO8057709513	KU	3	50 BRN	SP	CCA	V	00:00.0
2021	PO9548993048	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO9535093070	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO9521293089	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5961997209	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6108702206	F	3	45 ACE	SP	CRE	V	00:00.0
2021	PO5945697454	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5908597486	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5914397588	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5922197640	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5919097719	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4471585571	LGE	UNK	65 ACE	SP	A	V	00:00.0
2021	PO9468796175	KU	5	35 XXX	SP	S	V	00:00.0
2021	PO9471495876	KU	5	35 XXX	SP	S	V	00:00.0
2021	PO8038109083	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO9552691055	KU	1	40 BRO	SP	CCA	V	00:00.0
2021	PO5988801787	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5982701647	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5976701506	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5974101447	F	3	40 ACE	SP	CRE	V	00:00.0
2021	PO5971401377	F	4	45 ACE	SP	CRE	V	00:00.0
2021	PO6381903078	F	4	30 ACE	SP	CRE	V	00:00.0
2021	PO5927401049	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5930401175	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5933001268	F	4	40 ACE	SP	P	V	00:00.0
2021	PO5963401193	F	4	45 ACE	SP	CRE	V	00:00.0
2021	PO5946901265	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5957001050	F	4	45 ACE	SP	CRE	V	00:00.0
2021	PO5950900912	F	4	45 ACE	SP	CRE	V	00:00.0
2021	PO5943900750	F	4	45 ACE	SP	CRE	V	00:00.0
2021	PO5914200193	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO3942415950	KU	3	45 XXX	SP	CCA	V	00:00.0
2021	PO4452085740	F	4	35 ACE	SP	CCA	V	00:00.0
2021	PO1667969610	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO1663569540	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021	PO1668169487	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021	PO3856415501	KU	2	60 XXX	ST	CRE	V	00:00.0
2021	PO3828715579	KU	1	55 XXX	ST	CCA	V	00:00.0
2021	PO4550487919	LGE	4	40 BRO	SP	P	V	00:00.0
2021	PO3885213962	KU	3	45 XXX	SP	CCA	V	00:00.0
2021	PO4421285763	LGE	2	55 BRO	SP	CCA	V	00:00.0
2021	PO4547987903	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021	PO4419985755	F	2	55 BRO	SP	CCA	V	00:00.0
2021	PO3702318165	KU	1	75 BRN	SP	CRE	V	00:00.0
2021	PO3712118230	KU	4	40 BRN	SP	CCA	V	00:00.0
2021	PO4417885748	LGE	4	30 BRO	SP	CCA	V	00:00.0
2021	PO4418385743	LGE	2	55 BRO	SP	CCA	V	00:00.0
2021	PO4545187884	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021	PO7963510271	KU	2	55 BRN	SP	CCA	V	00:00.0
2021	PO4399885333	F	3	45 BRO	SP	A	V	00:00.0
2021	PO4396285303	F	3	45 BRO	SP	A	V	00:00.0

2021 PO7993610759	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO4395185294	LGE	3	50 BRO	SP	CCA	V	00:00.0	
2021 PO4397185310	F	3	45 BRO	SP	A	V	00:00.0	
2021 PO4397985316	F	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO4398685322	F	3	45 BRO	SP	A	V	00:00.0	
2021 PO3716118301	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO4426685803	LGE	4	30 BRO	ST	CCA	V	00:00.0	
2021 PO7983311013	KU	6	30 BRN	SP	CCA	V	00:00.0	
2021 PO9646995902	KU	5	35 XXX	SP	S	V	00:00.0	
2021 PO9658195948	KU	5	35 XXX	SP	S	V	00:00.0	
2021 PO9657096048	KU	5	35 XXX	SP	S	V	00:00.0	
2021 PO9718694589	KU	3	45 XXX	SP	CRE	V	00:00.0	
2021 PO9709993753	KU	4	45 XXX	SP	S	V	00:00.0	
2021 PO9707593631	KU	4	45 XXX	SP	S	V	00:00.0	
2021 PO9705193510	KU	4	45 XXX	SP	S	V	00:00.0	
2021 PO9431897789	KU	5	35 BRO	SP	CCA	V	00:00.0	
2021 PO7893806122	F	2	50 BRN	SP	CRE	V	00:00.0	
2021 PO7907405974	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO7896906089	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO7867506396	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO7863506437	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO9460498745	KU	4	40 BRO	SP	CCA	V	00:00.0	
2021 PO9459098778	KU	4	40 BRO	SP	CCA	V	00:00.0	
2021 PO9458698984	KU	4	45 BRO	SP	CCA	V	00:00.0	
2021 PO9433899232	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO9443399276	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO9452999235	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO9458499196	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO9458399405	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO9436398260	KU	4	40 BRO	SP	CCA	V	00:00.0	
2021 PO9448098290	KU	4	40 UNK	SP	CRE	V	00:00.0	
2021 PO3567616718	KU	4	40 BRN	SP	CCA	V	00:00.0	
2021 PO9627698658	KU	4	40 KOP	SP	CCA	V	00:00.0	
2021 PO3567117357	KU	4	45 BRN	SP	CCA	V	00:00.0	
2021 PO9568798688	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO9545798696	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO9524798706	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO9501798715	KU	2	45 BRO	SP	CCA	V	00:00.0	
2021 PO9481898728	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO7881606251	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO7873606332	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO9422597865	KU	4	40 BRO	SP	CCA	V	00:00.0	
2021 PO9421698101	KU	4	40 BRO	SP	CCA	V	00:00.0	
2021 PO3869015466	KU	1	55 XXX	ST	CCA	V	00:00.0	
2021 PO7957511506	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO7915505893	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO7831906760	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO7847606604	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO7856406512	F	4	40 BRN	SP	CRE	V	00:00.0	
2021 PO7948411387	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO3612417958	KU	4	40 BRN	SP	CCA	V	00:00.0	
2021 PO3554216741	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4231813690	KU	3	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9587798680	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0

2021 PO9607698668	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 3589616128a	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9785494491	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9816294380	KU	3	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9768194413	KU	3	45 XXX	SP	CRE	ED,ID,MD	TD	00:00.0
2021 PO9743794468	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9723394514	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9240991316	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9254591463	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO3714318197	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3711918211	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7942010499	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO9250791774	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9268191609	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7957210746	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO9641695791	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9662495617	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9232891233	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9241891096	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO3719418444	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3717118509	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3724218305	KU	2	65 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4475387494	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4844824723	KU	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4841924744	KU	3	45 BRO	SP	CRE		T	00:00.0
2021 PO4840324743	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4527087498	LGE	4	35 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO4526987491	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4526787468	F	4	30 BRO	SP	P		V	00:00.0
2021 PO4526087474	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4524887459	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4525487451	F	4	30 BRO	SP	P		V	00:00.0
2021 PO4523687453	LGE	4	35 BRO	SP	P	ED,EP,ID,MD	TD	00:00.0
2021 PO4474087496	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4468288189	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO7571277203	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4477888416	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4474987507	LGE	3	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4478488423	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4477688420	F	4	30 ACE	SP	A		V	00:00.0
2021 PO4875723993	KU	4	40 BRO	SP	CRE	ED,ID	BX	RP1 00:00.0
2021 PO7582177204	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO7594277204	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7601377210	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7605777281	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7616977173	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4439088868	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4482787514	LGE	4	40 BEL	SP	CRE	ID,IP	BD	00:00.0
2021 PO4437788842	LGE	1	65 ACE	SP	CRE		BD	00:00.0
2021 PO7720980651	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7680880853	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7687680780	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4482287522	LGE	4	40 BEL	SP	CRE	ID,IP	BD	00:00.0
2021 PO4438088859	LGE	3	45 ACE	SP	CCA		V	00:00.0

2021	PO4437488850	LGE	1	60 ACE	AL	CCA			V		00:00.0
2021	PO7694780705	KU	4	40 ACE	SP	CRE	ED,ID		BD		00:00.0
2021	PO7709780549	KU	4	40 ACE	SP	CRE	ED,ID		BD		00:00.0
2021	PO5039023265	KU	5	35 BRO	SP	CRE	ED,ID		BD		00:00.0
2021	PO5031623169	KU	4	40 BRO	SP	CCA			V		00:00.0
2021	PO5045223364	KU	4	40 BRO	SP	CRE	ED,ID		BD		00:00.0
2021	PO5013222914	KU	4	40 BRO	SP	CRE	ED		BD		00:00.0
2021	PO5000922750	KU	4	40 BRO	SP	CRE	ED		BD		00:00.0
2021	PO4917123020	KU	4	40 BRO	SP	CRE	ED,ID		BD		00:00.0
2021	PO4858613523	KU	4	40 XXX	SP	CRE	ID		TD		00:00.0
2021	PO4755713790	KU	2	50 XXX	SP	CRE	ID		TD		00:00.0
2021	PO4817613613	KU	4	40 XXX	SP	CRE			V		00:00.0
2021	PO4822214280	KU	5	35 XXX	SP	CCA			V		00:00.0
2021	PO4822114119	KU	4	40 XXX	SP	CRE	ID		BD		00:00.0
2021	PO4821913914	KU	3	45 XXX	SP	CCA			V		00:00.0
2021	PO4468688839	LGE	4	40 ACE	SP	CRE	ED,ID		BD		00:00.0
2021	PO4467588841	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB		X	RP3	00:00.0
2021	PO4944608095	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO4934107905	F	4	40 BRN	SP	S			V		00:00.0
2021	PO4915707834	KU	5	35 XXX	SP	CRE	ED,ID		TD		00:00.0
2021	PO4918408132	F	4	40 XXX	SP	S			V		00:00.0
2021	PO4924107602	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO4936407895	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO4846807865	F	4	40 BRN	SP	CRE			V		00:00.0
2021	PO4909807687	KU	5	35 BRN	SP	CRE	ED,ID		TD		00:00.0
2021	PO4921607959	F	4	40 BRN	SP	CRE			V		00:00.0
2021	PO4930707757	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO4936608297	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO4941908032	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO4912707566	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO4913207997	F	4	40 BRN	SP	S			V		00:00.0
2021	PO4850107776	KU	6	30 BRN	SP	S			V		00:00.0
2021	PO4465288859	LGE	3	45 ACE	SP	CCA			V		00:00.0
2021	PO5017024340	KU	4	40 BRO	SP	CRE	ED		BD		00:00.0
2021	PO4464088863	LGE	4	25 ACE	SP	CRE	ED,ID		BD		00:00.0
2021	PO4463888858	LGE	4	40 ACE	SP	CCA			V		00:00.0
2021	PO4464888854	LGE	4	40 ACE	SP	CCA			V		00:00.0
2021	PO4465788850	LGE	4	35 ACE	SP	CCA			V		00:00.0
2021	PO4466588846	LGE	4	40 ACE	SP	CCA			V		00:00.0
2021	PO3977617753	KU	3	40 KOP	SP	CRE	ID		BD		00:00.0
2021	PO5012024102	KU	3	45 BRO	SP	CRE	ED		BD		00:00.0
2021	PO5034524325	KU	4	40 BRO	SP	CRE	ED		BD		00:00.0
2021	PO5048624313	KU	4	40 BRO	SP	CRE	ED		BD		00:00.0
2021	PO5064124299	KU	4	45 BRO	SP	CRE	ED		BD		00:00.0
2021	PO4820513609	KU	2	65 XXX	SP	CRE	ID		TD		00:00.0
2021	PO4459888877	LGE	4	40 ACE	SP	CCA			V		00:00.0
2021	PO4483287400	LGE	4	30 BRO	SP	CRE	ED,ID,IP		TD		00:00.0
2021	PO4460788871	LGE	3	45 ACE	SP	CCA			V		00:00.0
2021	PO4481687401	LGE	4	40 BRO	SP	A	ID		TD		00:00.0
2021	PO3981017808	KU	3	45 KOP	SP	CCA			T		00:00.0
2021	PO3989717917	KU	3	45 KOP	SP	CCA			T		00:00.0
2021	PO5077824289	KU	4	40 BRO	SP	CRE	ED		BD		00:00.0
2021	PO4461588867	LGE	4	40 ACE	SP	CCA			V		00:00.0
2021	PO4462388864	LGE	4	40 ACE	SP	CRE	ED,ID		BD		00:00.0

2021 PO4502887940-A	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO4503087946	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4801608036	F	4	40 XXX	DF	CRE		V	00:00.0	
2021 PO4781608349	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4793908278	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4441388892	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4440588884	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4439888876	LGE	3	45 ACE	SP	CCA	ED	V	00:00.0	
2021 PO4484387488	LGE	4	35 BEL	SP	CCA		V	00:00.0	
2021 PO4484087497	LGE	4	35 BEL	SP	A	ID,IP	BD	00:00.0	
2021 PO4475388038	LGE	3	55 ACE	SP	A	ED	BD	00:00.0	
2021 PO4474688048	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4994923725	KU	5	35 BRO	SP	CRE		V	00:00.0	
2021 PO5004423644	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO5025123077	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0	
2021 PO4483687501	LGE	4	40 BEL	SP	CCA		V	00:00.0	
2021 PO7657680639	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO7675380808	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4257812598	KU	3	45 BRN	SP	CCA		T	00:00.0	
2021 PO4480788567	LGE	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4480888570	LGE	3	45 ACE	SP	CRE		V	00:00.0	
2021 PO7712480815	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4481687532-A	KU	4	40 BEL	SP	CRE	ID	BD	00:00.0	
2021 PO7713580888	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4466588721	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4481687532	LGE	3	40 BEL	SP	A	ID,IP	BD	00:00.0	
2021 PO7691080952	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7686281015	KU	6	30 ACE	SP	CCA		V	00:00.0	
2021 PO7724280990	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO7705781074	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7716881166	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO8557183780	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4465788696	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4474688825	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4883208283	KU	5	35 XXX	SP	CRE	ED,ID,MD_SRC	TX	RR	00:00.0
2021 PO4473288830	LGE	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4677314081	KU	3	45 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO4685214051	KU	3	50 XXX	SP	CCA		V	00:00.0	
2021 PO4684914101	KU	5	35 XXX	SP	P		B	00:00.0	
2021 PO4470788837	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4470888840	LGE	4	25 ACE	SP	CRE		V	00:00.0	
2021 PO3942518030	KU	3	45 KOP	SP	CRE	ED,SRS	TD	00:00.0	
2021 PO4472088834	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3962617958	KU	3	35 KOP	SP	CRE		T	00:00.0	
2021 PO3965517856	KU	3	45 KOP	SP	CRE	ID	T	00:00.0	
2021 PO4912908242	KU	5	35 XXX	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4904308427	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4906208420	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO4920908361	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4692114025	KU	3	45 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO3972317965	KU	3	45 KOP	SP	CCA		T	00:00.0	
2021 PO4496887941	LGE	1	70 BRO	SP	CRE	ED,ID,IP,MD	BD	00:00.0	
2021 PO4469688840	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4500287940	LGE	2	55 BRO	SP	CRE	ED,ID,MD	BD	00:00.0	



2021 PO4498987941	LGE	2	60 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4501487940	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO4497187941	LGE	2	50 BRO	SP	A	ED,ID,IP,MD	BD	00:00.0
2021 PO4497887941	LGE	2	60 BRO	SP	CCA		V	00:00.0
2021 PO4705213980	KU	3	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4734513861	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO7738093609	KU	6	30 ACE	WC	CCA		V	00:00.0
2021 PO7861191358	KU	6	30 ACE	DF	CCA		V	00:00.0
2021 PO3992117634	KU	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4909513498	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4502887940	LGE	2	60 BRO	SP	A	ED,ID,IP	BD	00:00.0
2021 PO5161424210	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO5174824198	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4529787357	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4528787361	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4528287373	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4455888894	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4487487440	LGE	4	40 BEL	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4005418107	KU	6	35 KOP	SP	CCA		V	00:00.0
2021 PO4014718048	KU	4	40 KOP	SP	CCA		T	00:00.0
2021 PO5171723934	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5176723651	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4481887394	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4480587397	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4454788898	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4488087430	LGE	3	40 BEL	SP	CRE	ID,IP	BD	00:00.0
2021 PO4444188951	F	1	75 ACE	SP	P		V	00:00.0
2021 PO4248612290	KU	3	45 KOP	SP	CCA		T	00:00.0
2021 PO7501478040	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5142323582	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO7425078572	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7437378571	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7454178573	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5166623514	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4225711686	KU	6	35 KOP	SP	CCA		T	00:00.0
2021 PO4849407502	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4864807465	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4842207531	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4867907543	F	4	40 BRO	SP	S		V	00:00.0
2021 PO5154523206	KU	2	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5141923270	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4230311674	KU	3	45 BRN	SP	CCA		T	00:00.0
2021 PO4222211376	KU	3	45 BRN	SP	CCA		T	00:00.0
2021 PO4218011220	KU	3	45 BRN	SP	CCA		T	00:00.0
2021 PO4486287459	LGE	4	40 BEL	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4477188011	LGE	4	40 ACE	SP	CRE	ED	TD	00:00.0
2021 PO4512787954	LGE	2	55 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4444588922	LGE	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5127023597	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4485687468	LGE	4	35 BEL	SP	CCA		V	00:00.0
2021 PO7546478581	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO7545978489	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4477688011	LGE	4	30 ACE	SP	CRE	ED	BD	00:00.0
2021 PO5125023287	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0

2021	PO5115123296	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO5090223320	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO4467088696	LGE	4	30 ACE	SP	CRE		V		00:00.0
2021	PO4474688048A	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO4933822905	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4463087829	LGE	4	40 BEL	SP	A	ID,IP	BD		00:00.0
2021	PO4463587820	LGE	4	40 BEL	SP	A	ID,IP	BD		00:00.0
2021	PO4463187818	LGE	4	40 BEL	SP	CRE	ID,IP	BD		00:00.0
2021	PO4464788675	LGE	4	30 ACE	SP	CCA	ED,ID	TD		00:00.0
2021	PO8535783808	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO5090824276	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO5105224262	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO5120224248	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO4458288889	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO4819713583	KU	1	65 XXX	SP	CCA		V		00:00.0
2021	PO4822413581	KU	4	45 XXX	SP	CRE	ID,IP	TD		00:00.0
2021	PO4821313752	KU	3	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4841913547	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4000018045	KU	4	40 KOP	SP	CCA		T		00:00.0
2021	PO4458188886	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO5134524235	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO5147224223	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO4457088890	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4531887369	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4530887361	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO5170023794	KU	4	40 BRO	SP	CRE	ED,ID	BX	PX	00:00.0
2021	PO4453488903	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4453588906	LGE	4	25 ACE	SP	CRE	ED,ID,RB	X	RR	00:00.0
2021	PO5168323653	KU	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021	PO5179023813	KU	5	35 BRO	SP	CCA		V		00:00.0
2021	PO4478787987	LGE	3	50 ACE	SP	CCA	ED,IP	BD		00:00.0
2021	PO4452888900	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4025717977	KU	5	40 KOP	SP	CRE		T		00:00.0
2021	PO4452488905	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4479787394	KU	5	35 BRO	SP	A	ID	BD		00:00.0
2021	PV2294292148	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021	PO4478087998	LGE	3	50 ACE	SP	CRE	ED,IP	TD		00:00.0
2021	PO4238511957	KU	3	45 KOP	SP	CCA		T		00:00.0
2021	PO4451588911	LGE	4	40 ACE	SP	CCA	ED,ID,RB	X	PX	00:00.0
2021	PO4520187968	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021	PO4518087964	LGE	2	55 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4516987962	LGE	2	55 BRO	SP	CRE	ED,ID,MD	BD		00:00.0
2021	PO4519387967	LGE	2	60 BRO	SP	CRE	ED,ID,IP,RB	BD		00:00.0
2021	PO4518687965	LGE	1	50 BRO	SP	CCA	ED,ID	BD		00:00.0
2021	PO4477388008	LGE	3	55 ACE	SP	CRE	ED,EP,ID	TX	RR	00:00.0
2021	PO4450288915	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4875313501	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4893513491	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4688609446	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4667009310	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4675009503	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4661909552	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4488487424	LGE	4	40 BEL	SP	CCA		V		00:00.0
2021	PO4447688925	LGE	4	40 ACE	SP	P	ED,ID,RB	X	RR	00:00.0

2021 PO1575701497	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7517378250	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO1573401606	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7517578047	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4860207458	F	4	40 BRO	SP	P		V	00:00.0
2021 PO5672006779	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5663406889	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5656706731	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5649006767	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5631306840	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5620206879	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5614706890	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5618606982	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5624107123	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5639307241	KU	6	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5628607242	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5632207340	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5635507428	F	5	35 XXX	SP	P		V	00:00.0
2021 PO5636607459	F	4	45 XXX	SP	CCA		V	00:00.0
2021 PO5458304967	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5183009857	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO5188709793	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO5183909739	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO5181909699	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8100994182	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8110794144	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8136994045	KU	4	40 XXX	SP	CRE	ED,EP,ID,IP,MD,SRC	TX RR	00:00.0
2021 PO8128494313	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8120494408	KU	4	35 XXX	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8111994439	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4877185097	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4877785107	LGE	4	50 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4876285093	LGE	4	50 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4876885086	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6606697748	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6681598791	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6697399007	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6690299036	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6685699063	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6686498909	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6678398704	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6666998596	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6675298557	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6714099269	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4522387684	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4519287668	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4508687650	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4514287631	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4375085936	F	UNK	55 ACE	SP	CRE		V	00:00.0
2021 PO4373885947	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4372385947	LGE	UNK	45 ACE	SP	P		V	00:00.0
2021 PO4368385962	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6661899156	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4367185969	LGE	4	40 ACE	SP	CCA		V	00:00.0

2021	PO6656499019	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6651598895	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6647598789	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6643898697	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4515587620	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO6653598278	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6639598276	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6627898291	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6633298425	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4879685124	LGE	4	50 BRO	SP	A	ED, ID, IP	TD	00:00.0
2021	PO6638798569	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4880585133	F	3	45 BRO	SP	A		V	00:00.0
2021	PO4880285122	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4880785126	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021	PO4882985145	F	3	45 BRO	SP	A		V	00:00.0
2021	PO6653698115	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6631998183	F	5	35 ACE	SP	CRE		V	00:00.0
2021	PO6626298204	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6623698138	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6617498027	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6615397975	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6637597849	F	4	40 ACE	SP	P		V	00:00.0
2021	PO7684991012	KU	4	40 XXX	SP	CRE	ED, ID	TD	00:00.0
2021	PO4883985154	LGE	3	45 BRO	SP	CRE		V	00:00.0
2021	PO4511187683	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4511587686	F	3	45 BRO	SP	P		V	00:00.0
2021	PO4369485955	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4370285950	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4370885942	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO4371085946	F	UNK	45 ACE	SP	CRE		V	00:00.0
2021	PO4369885946	LGE	4	30 ACE	SP	A	ED, ID	TD	00:00.0
2021	PO6774997717	KU	2	55 ACE	SP	CCA		V	00:00.0
2021	PO6775397804	F	3	45 ACE	SP	P		V	00:00.0
2021	PO6780197900	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6789797877	F	3	55 ACE	SP	P		V	00:00.0
2021	PO4512287664	F	3	45 BRO	SP	P		V	00:00.0
2021	PO4515787675	F	4	40 BRO	SP	P		V	00:00.0
2021	PO4514687693	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4517787645	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4520187608	F	4	40 BRO	SP	P		V	00:00.0
2021	PO4516787660	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4885285164	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO6774297328	KU	4	40 ACE	SP	CRE	ED, ID, IP	BD	00:00.0
2021	PO6774897523	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO6773697229	KU	4	40 ACE	SP	CRE	ED, ID, IP	BD	00:00.0
2021	PO4370685957	LGE	4	30 ACE	SP	CRE	ED, ID	TD	00:00.0
2021	PO4884085155	LGE	3	45 BRO	SP	A	ED, ID	TD	00:00.0
2021	PO4885485139	LGE	4	40 BRO	SP	A	ID, IP	BD	00:00.0
2021	PO6764197068	KU	4	40 ACE	SP	CRE	ED, ID, IP	BD	00:00.0
2021	PO6760797009	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO6188601381	F	4	50 ACE	SP	CRE	ED, HH, ID, RB	BX PX	00:00.0
2021	PO6200501536	F	4	50 ACE	SP	CRE	ED, HH, ID, RB	BX PX	00:00.0
2021	PO6202801566	KU	4	50 ACE	SP	CRE		V	00:00.0
2021	PO6203901581	F	4	50 ACE	SP	CRE		V	00:00.0

2021	PO6208301639	F	4	45 ACE	SP	CRE		V	00:00.0
2021	PO6221401481	F	4	45 ACE	SP	CRE		V	00:00.0
2021	PO6229801431	F	4	50 ACE	SP	P		V	00:00.0
2021	PO6488200536	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6480600592	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5825705555	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO5832805627	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO5831605777	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO8100090634	KU	4	40 XXX	DF	CRE	ED,ID,IP,MD	TD	00:00.0
2021	PO8450495305	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8443595438	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8437095568	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8430295696	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8424395812	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8418195938	KU	3	40 XXX	SP	S		V	00:00.0
2021	PO8409196110	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8403696217	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO5821305970	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021	PO5809506150	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021	PO5805406397	KU	5	35 XXX	SP	CCA		T	00:00.0
2021	PO5812706638	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021	PO5811406917	KU	6	30 XXX	SP	CCA		V	00:00.0
2021	PO8396896351	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8390996461	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8376896737	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8383596603	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8008991763	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO8021591608	KU	4	40 XXX	DF	CRE	ED,ID,IP,MD	TD	00:00.0
2021	PO8032691473	KU	4	40 XXX	DF	CRE	ED,ID,IP,MD	TD	00:00.0
2021	PO8043591335	KU	4	40 XXX	DF	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021	PO8059691131	KU	5	35 XXX	DF	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021	PO8072790967	KU	4	40 XXX	DF	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021	PO8086190805	KU	4	40 XXX	DF	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021	PO5818606780	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021	PO5819506932	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021	PO5540506645	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5543706649	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5559006622	KU	2	50 XXX	SP	CCA		V	00:00.0
2021	PO5561606575	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5557406508	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021	PO5557406508A	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021	PO7993891920	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8006391934	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8014592130	KU	4	40 XXX	DF	CRE	ED,ID,IP	TD	00:00.0
2021	PO8023192332	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO5584306789	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5577306708	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5574106602	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5571506457	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5583206414	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5604706039	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5603206555	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5609806744	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5610206203	F	4	40 XXX	SP	CRE		V	00:00.0

2021	PO5594606092	KU	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5591006195	KU	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5587406234	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO5593706274	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5593906374	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO5596806360	KU	3	50 XXX	SP	P	ED	T		00:00.0
2021	PO8030892517A	KU	5	35 XXX	SP	P	ED,ID,IP,RB,SRC	X	PX	00:00.0
2021	PO8030892517	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO8037392449	F	7	30 XXX	SP	CRE		V		00:00.0
2021	PO8047293129	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8058893175	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO8048892946	KU	4	40 XXX	DF	CRE	ED,ID,IP,RB	X	RP2	00:00.0
2021	PO8039192715	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8047493610	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8012093296	KU	4	40 XXX	SP	CRE		V		00:00.0
2021	PO8017493271	KU	2	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO8340097494	KU	3	40 XXX	SP	S		V		00:00.0
2021	PO8343997397	KU	4	45 XXX	SP	S		V		00:00.0
2021	PO6298301338	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6290601382	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6272401485	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6278500785	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6258800898	F	4	45 ACE	SP	CRE		V		00:00.0
2021	PO6263800921	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6260901488	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6247601562	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6239901607	KU	3	45 ACE	SP	P		V		00:00.0
2021	PO6227701928	F	1	55 ACE	SP	CRE		V		00:00.0
2021	PO6217101773	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6208301554	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6192201360	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6203101520	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5787005517	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	4383985922-a	LGE	3	35 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4873385055	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4869885008	LGE	4	30 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO5771705532	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4373385710	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021	PO4372785718	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021	PO4384786001	LGE	4	30 ACE	SP	A	ED	BD		00:00.0
2021	PO4375585696	LGE	5	35 ACE	SP	CCA	ED	BD		00:00.0
2021	PO4904485290	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4380985972	LGE	4	30 ACE	SP	A	ED	BD		00:00.0
2021	PO4370885744	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021	PO6520900279	KU	4	30 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4903585313	LGE	3	45 BRO	SP	A	ID	BD		00:00.0
2021	PO4904285315	LGE	6	25 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4374085960	LGE	4	30 ACE	SP	CRE	ED	BD		00:00.0
2021	PO4378785920	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO5571006948	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO5565006786	KU	4	40 XXX	SP	CRE	ID,IP	BD		00:00.0
2021	PO4387085920	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021	PO6612899841	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO5830905406	KU	5	35 XXX	SP	CCA	ED	T		00:00.0

2021	PO5755206458	KU	6	30 XXX	SP	CCA	ED	T	00:00.0	
2021	PO4374985760	LGE	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4384085994	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4382786002	LGE	4	30 ACE	SP	CRE	ED	TD	00:00.0	
2021	PO4373386038	LGE	4	30 ACE	SP	CRE	ED	TD	00:00.0	
2021	PO4377685727	LGE	3	45 ACE	SP	P	ED	TD	00:00.0	
2021	PO4368685939	LGE	4	40 ACE	SP	CRE	ED	TD	00:00.0	
2021	PO4377485960	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4370985733	LGE	4	35 ACE	SP	P	ED	TD	00:00.0	
2021	PO4369385719	LGE	4	35 ACE	SP	P	ED	TD	00:00.0	
2021	PO4874785076	LGE	2	50 BRO	SP	A	ED,ID	TD	00:00.0	
2021	PO4874285069	LGE	2	50 BRO	SP	A	ED,ID	TD	00:00.0	
2021	PO5759805168	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO4372785954	LGE	4	35 ACE	SP	A	ED	TD	00:00.0	
2021	PO5614907653	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO4875085033	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO4875285075	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021	PO4372285726	LGE	4	40 ACE	SP	P	ED	TD	00:00.0	
2021	PO4373485786	LGE	3	45 ACE	SP	CRE	ED	TD	00:00.0	
2021	PO4372485778	LGE	3	40 ACE	SP	P	ED	TD	00:00.0	
2021	PO4387485909	LGE	3	45 ACE	SP	A	ED	TD	00:00.0	
2021	PO4865885027	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO4873785050	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021	4391786009-A	LGE	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4391985995	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4871785040	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO4872185036	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO4378485717	LGE	3	45 ACE	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021	PO4377685711	LGE	3	45 ACE	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021	PO4364285832	LGE	UNK	45 ACE	SP	CCA		V		00:00.0
2021	PO4367185849	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO4373285839	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4386785895	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO4377085885	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4376185891	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4375285897	LGE	3	45 ACE	SP	CRE		V		00:00.0
2021	PO4374385902	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4373785907	LGE	3	50 ACE	SP	CRE		V		00:00.0
2021	PO4372885912	LGE	UNK	55 ACE	SP	CRE		V		00:00.0
2021	PO4371985918	LGE	3	45 ACE	SP	CRE		V		00:00.0
2021	PO4371185923	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021	PO4370385928	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021	PO3989983976	F	4	40 ACE	SP	CRE	ED	V		00:00.0
2021	PO3990183989	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO3990284004	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO3990384017	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO3990584031	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO3990684048	F	4	40 ACE	SP	CRE	ED	V		00:00.0
2021	PO3990884060	F	4	40 ACE	SP	CRE	ED	V		00:00.0
2021	PO3990984074	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO7650670635	KU	3	50 ACE	SP	CCA		V		00:00.0
2021	PO4008483812	F	4	30 BRO	SP	CRE		V		00:00.0
2021	PO4007283791	F	4	35 BRO	SP	A		V		00:00.0
2021	PO7366368827	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0

2021	PO4500788124	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4500588120	LGE	3	45 BRN	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021	PO4473088184	F	4	30 BRN	SP	A		V		00:00.0
2021	PO4473088171	F	4	35 BRN	SP	CRE		V		00:00.0
2021	PO5817825327	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO1663365806	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO1785367878	KU	6	30 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO7437467124	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7428867356	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4130584546	LGE	3	55 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4131184553	LGE	3	55 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4128884540	LGE	4	35 BRO	SP	P	ED,EP,ID,IP,RB	TX	RR	00:00.0
2021	PO4132284567	LGE	3	55 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4129384528	LGE	3	55 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4129884537	LGE	3	55 BRO	SP	P	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO4013383884	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO5806425343	KU	5	35 ACE	SP	CCA		V		00:00.0
2021	PO5809525287	KU	4	45 ACE	SP	CRE		B		00:00.0
2021	PO5806325230	KU	5	35 ACE	SP	CCA		B		00:00.0
2021	PO5817525203	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4014283863	LGE	4	30 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO0372000372	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021	PO0468500270	KU	4	35 BRO	SP	CCA	ID	TD		00:00.0
2021	PO0503800232	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021	PO0538400198	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021	PO7419167594	KU	4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7410567836	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO7402068071	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7393068299	KU	4	40 ACE	SP	CRE	ED,ID,IP,MD	BD		00:00.0
2021	PO4003384122	F	UNK	45 ACE	SP	CRE	ED	V		00:00.0
2021	PO4001284109	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021	PO6925871826	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO4001384122	F	UNK	55 ACE	SP	CRE	ED	V		00:00.0
2021	PO6945771978	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO6965672129	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO6985572280	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO4000184122	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO3999084124	F	UNK	45 ACE	SP	CRE		V		00:00.0
2021	PO3998084124	F	UNK	45 ACE	SP	CRE		V		00:00.0
2021	PO7170971131a	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO7170971131	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO3997684052	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7171371346a	KU	2	40 ACE	SP	CCA		V		00:00.0
2021	PO7171371346	KU	2	50 ACE	SP	CCA		V		00:00.0
2021	PO7159571352	KU	H1	85 ACE	SP	CRE		V		00:00.0
2021	PO3997684063	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO3997784071	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7155571356	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7141971529a	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7141971529	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7147571511	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7129371692	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7135471677	KU	1	80 ACE	SP	CRE		V		00:00.0
2021	PO4563888097	LGE	4	30 BRN	SP	CCA	ED,HH,ID	BD		00:00.0



2021 PO4563888095	LGE	4	30 BRN	SP	A	ID	BD	00:00.0
2021 PV4563288097	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO2725293607	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4563388107	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO7114971880	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7123371839	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7111572000a	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7111572000	KU	1	80 ACE	SP	CCA		V	00:00.0
2021 PO7098372095	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7099472165	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7083672283	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7087572331	KU	1	80 ACE	SP	CRE		V	00:00.0
2021 PO4001084069	LGE	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4000984057	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4000984058	LGE	4	45 ACE	SP	CRE	ED	V	00:00.0
2021 PO3996584114	LGE	UNK	25 ACE	SP	CRE	ED	BD	00:00.0
2021 PO3996484125	F	UNK	55 ACE	SP	CRE	ED	V	00:00.0
2021 PO3995084130	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO2052492244	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4035384127	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4034384119	F	4	30 BRO	SP	P		V	00:00.0
2021 PO4072484353	LGE	4	30 BRO	UN	CCA		V	00:00.0
2021 PO7075472490	KU	2	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7067172475	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7057772570	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4044884195	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4043284186	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4048484216	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4065884319	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4067084326	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4068184333	F	3	45 BRO	DF	CCA		V	00:00.0
2021 PO4516788191	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4518088169	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7005472432	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO7025372583	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4517288182	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4515988202	LGE	4	35 BRN	SP	A	ED,ID,IP	BD	00:00.0
2021 PO4518788159	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4071884255	LGE	4	40 BRO	UN	CRE		V	00:00.0
2021 PO4072884261	LGE	4	40 BRO	UN	CRE		V	00:00.0
2021 PO4070084344	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4072084356	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4072984363	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7365768651	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7354968761	F	4	45 ACE	SP	P		V	00:00.0
2021 PO0072900387	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO0146899915	KU	6	30 KOP	SP	CRE	ID	BD	00:00.0
2021 PO3990983798	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO3991083805	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3990283803	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5812325706	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5816925703	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5834725616	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO5828525682	KU	3	45 UNK	SP	CRE		B	00:00.0

2021 PO5821025763	KU	4	40 UNK	SP	CRE			B	00:00.0
2021 PO5817325803	KU	3	40 UNK	SP	CRE			B	00:00.0
2021 PO5813625842	KU	5	35 UNK	SP	CCA			V	00:00.0
2021 PO5824725630	F	3	40 UNK	SP	CRE			V	00:00.0
2021 PO3992883822	F	4	40 BRO	SP	A			V	00:00.0
2021 PO3992283823	F	6	25 BRO	SP	CRE			V	00:00.0
2021 PO3991084088	F	4	40 ACE	SP	CRE		ED	V	00:00.0
2021 PO3991284097	F	4	40 ACE	SP	A		ED	V	00:00.0
2021 PO3991384110	F	4	40 ACE	SP	CRE		ED	V	00:00.0
2021 PO3992783803	F	4	40 BRO	SP	A			V	00:00.0
2021 PO3992883787	F	4	40 BRO	SP	A			V	00:00.0
2021 PO3991484123	F	4	40 ACE	SP	CRE		ED	V	00:00.0
2021 PO3990684123	F	4	30 ACE	SP	CRE		ED	V	00:00.0
2021 PO5788125420	KU	5	35 UNK	SP	CCA			B	00:00.0
2021 PO5792625471	KU	4	40 UNK	CON	CCA			V	00:00.0
2021 PO1770267798	KU	4	40 BRN	SP	CRE		ED,JP,SRS	TD	00:00.0
2021 PO5799225398	KU	5	35 ACE	SP	CCA			B	00:00.0
2021 PO4120084460	LGE	4	40 BRO	SP	P		ED,ID	TD	00:00.0
2021 PO8352756505	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021 PO4119384480	LGE	4	40 BRO	SP	P			B	00:00.0
2021 PO4122584493	LGE	4	30 BRO	SP	CRE			V	00:00.0
2021 PO4125184510	LGE	4	30 BRO	SP	P		ED,ID	BD	00:00.0
2021 PO4124384497	LGE	4	30 BRO	SP	P		ED,ID,JP	BD	00:00.0
2021 PO4124384499	LGE	4	35 BRO	SP	CRE			V	00:00.0
2021 PO4125384496	LGE	4	35 BRO	SP	CCA			V	00:00.0
2021 PO4020784001	LGE	4	35 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO4007783743	LGE	4	35 BRO	SP	A		ED,ID,JP	TD	00:00.0
2021 PO5551126313	KU	6	30 UNK	SP	CCA			B	00:00.0
2021 PO4557688156	LGE	4	45 BRN	SP	CRE		ED,HH,ID	BD	00:00.0
2021 PO4022284114	LGE	UNK	50 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO4023084114	LGE	2	55 ACE	SP	CCA			V	00:00.0
2021 PO4558288165	LGE	4	40 BRN	SP	P		ED,HH,ID	BD	00:00.0
2021 PO4559188171	LGE	3	45 BRN	SP	CRE		ED,HH,ID	BD	00:00.0
2021 PO4559988177	LGE	4	40 BRN	SP	CCA			V	00:00.0
2021 PO4560788183	LGE	4	40 BRN	SP	CCA			V	00:00.0
2021 PO4560888184	LGE	4	40 BRN	SP	CCA			V	00:00.0
2021 PO4024484116	LGE	UNK	60 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO4007783733	LGE	4	35 BRO	SP	A		ED,ID,JP	TD	00:00.0
2021 PO8094375702q	KU	5	35 ACE	SP	CRE		ED,HH,ID,RB	BX	RP1 00:00.0
2021 PO5562726124	KU	3	45 UNK	SP	CRE			T	00:00.0
2021 PO5551526425	KU	2	70 UNK	ST	CCA			V	00:00.0
2021 PO5564426440	KU	4	40 UNK	ST	CCA			V	00:00.0
2021 PO8094375702p	KU	5	35 ACE	SP	CCA			V	00:00.0
2021 PO8094375702o	KU	5	35 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO4560488201	LGE	4	35 BRN	SP	CRE		ED,HH,ID	BD	00:00.0
2021 PO4559588194	LGE	4	40 BRN	SP	CRE		ED,ID,JP	TD	00:00.0
2021 PO4559288192	LGE	4	40 BRN	SP	A		ED,HH,ID	TD	00:00.0
2021 PO2696794659	LGE	4	30 BRN	SP	CCA			V	00:00.0
2021 PO270094636	KU	4	35 BRN	SP	CCA			V	00:00.0
2021 PO4558088185	LGE	3	45 BRN	SP	CCA			V	00:00.0
2021 PO4557088177	LGE	3	45 BRN	SP	CCA			V	00:00.0
2021 PO4555888169	LGE	3	45 BRN	SP	CCA			V	00:00.0
2021 PO4554888163	LGE	3	45 BRN	SP	CCA			V	00:00.0
2021 PO8094375702m	KU	3	45 ACE	SP	CCA			V	00:00.0

2021 PO4553888155	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4003883680	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4003383672	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO8094375702l	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8094375702k	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4026684101	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8094375702j	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8094375702i	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO8094375702h	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4023984103	LGE	UNK	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8094375702g	KU	4	45 ACE	SP	CRE	ED,ID,MD	TD	00:00.0
2021 PO5564326048	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO5572426028	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO4011783857	LGE	2	55 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4026084098	LGE	4	35 ACE	AL	CCA		V	00:00.0
2021 PO4025284104	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO8094375702f	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO8094375702e	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO5591226252	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO5585726212	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO8094375702d	KU	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8094375702c	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8094375702a	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8094375702b	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4024884082	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4551288145	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4551688141	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4552788147	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4552788147a1	KU	4	35 BRN	SP	A	ID	BD	00:00.0
2021 PO4025484080	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5587726061	KU	7	65 UNK	SP	CRE		B	00:00.0
2021 PO5583826052	KU	3	50 UNK	SP	CRE		B	00:00.0
2021 PO4551388138	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2591793812	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4550588133	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4550188139	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4025584085	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO8094375702	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4011183810	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO5754626572	KU	2	45 UNK	SP	CRE		T	00:00.0
2021 PO4024484089	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4023284085	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4023684092	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5753926469	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5757426434	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5755126637	KU	2	60 UNK	SP	CRE		B	00:00.0
2021 PO5752726651	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5748626668	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO4012483807	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO8112975309j	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8112975309i	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8112975309h	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8112975309g	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8112975309f	KU	4	40 ACE	SP	CCA		V	00:00.0

2021 PO8112975309e	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4559388232	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4013283820	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO8116475309a	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8112975309d	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO8112975309c	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO8112975309a	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO8112977309b	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO8112975309	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO8116475309	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO7395151723	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO7386251683	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO7383051620	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0	
2021 PO4021383995	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5769927066	KU	5	35 UNK	SP	CCA		B	00:00.0	
2021 PO4558688227	LGE	4	40 BRN	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4556388212	LGE	4	40 BRN	SP	A	ID	BD	00:00.0	
2021 PO4557588220	LGE	4	40 BRN	SP	A	ID	BD	00:00.0	
2021 PO4555388204	LGE	4	40 BRN	SP	A	ID	BD	00:00.0	
2021 PO4554388197	LGE	4	40 BRN	SP	CCA	ID	TD	00:00.0	
2021 PO4553488191	LGE	4	40 BRN	SP	CCA	ID	BD	00:00.0	
2021 PO4552388184	LGE	4	40 BRN	SP	P	ID	BD	00:00.0	
2021 PO4501588295	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO5762526950	KU	6	30 UNK	SP	CCA		B	00:00.0	
2021 PO5764426866	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO4530888017	LGE	4	30 ACE	SP	P	ED,ID	X	PX	00:00.0
2021 PO4940927678	KU	6	30 BRO	SP	CRE		V	00:00.0	
2021 PO4936728021	KU	5	30 BRO	SP	CRE	ED	BD	00:00.0	
2021 PO4460988518	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4460788517	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4524987925	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4715124331	KU	3	45 BRN	SP	CRE	SRS	TD	00:00.0	
2021 PO4438688829	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO4524487934	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO5019609396	KU	2	70 BRN	ST	CCA		V	00:00.0	
2021 PO4999409515	KU	2	55 BRN	SP	CRE	ED,ID,SR	TD	00:00.0	
2021 PO4997209469	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5005509423	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4525387919	LGE	4	40 ACE	SP	P	ED,EP,ID	TX	RR	00:00.0
2021 PO4525887912	LGE	4	40 ACE	SP	P	ED	TD	00:00.0	
2021 PO4526287905	LGE	4	45 ACE	SP	CRE	ED,IP	BD	00:00.0	
2021 PO3997583984	F	4	30 BRO	SP	CRE		V	00:00.0	
2021 PO4439488816	LGE	1	80 ACE	SP	CRE		V	00:00.0	
2021 PO4695824590	KU	3	45 BRN	SP	CRE		T	00:00.0	
2021 PO4652811277	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4662011228	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4647111276	F	2	50 BRN	SP	P		V	00:00.0	
2021 PO4646611392	F	3	40 BRN	SP	CRE		V	00:00.0	
2021 PO4651111370	F	3	40 BRN	SP	CRE		V	00:00.0	
2021 PO6109352682	KU	4	45 BRN	SP	CRE	ID,IP	BD	00:00.0	
2021 PO6103752767	KU	4	45 BRO	SP	CRE	ID,IP,MD	BD	00:00.0	
2021 PO6089152993	KU	4	45 BRO	SP	CRE	ID,IP,MD	BD	00:00.0	
2021 PO607753174	KU	4	40 BRO	SP	CRE	ID,IP,MD	BD	00:00.0	
2021 PO6095952889	KU	4	45 BRO	SP	CRE	ID,IP,MD	BD	00:00.0	

2021	PO6082953090	KU	4	45 BRO	SP	CRE	ID,IP,MD	BD		00:00.0
2021	PO4440788794	LGE	1	70 ACE	SP	CRE		V		00:00.0
2021	PO4442288773	LGE	1	70 ACE	SP	CRE		V		00:00.0
2021	PO4442888771	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4443688752	LGE	1	65 ACE	SP	CRE		V		00:00.0
2021	PO5000309364	KU	6	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO5011209262	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4522388015	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4890027983	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021	PO5029909282	F	4	40 BRN	DF	CRE		V		00:00.0
2021	PO5041509212	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5059809113	F	4	40 BRN	SP	P		V		00:00.0
2021	PO4522887960	LGE	3	45 ACE	SP	CRE	ED,ID	TX	RR	00:00.0
2021	PO4523887964	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO612252480	KU	4	40 BRO	SP	CRE	ID,IP,MD	BD		00:00.0
2021	PO6115552582	KU	4	45 BRO	SP	CRE	ID,IP,MD	BD		00:00.0
2021	PO6160652049	KU	4	40 BRO	SP	CRE	ID,IP,MD	BD		00:00.0
2021	PO6165152004	KU	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO6169551967	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4522387968	LGE	4	35 ACE	SP	CRE	ED	V		00:00.0
2021	PO4523287954	LGE	3	40 ACE	SP	CCA		V		00:00.0
2021	PO4523787945	LGE	4	40 ACE	SP	P	ED,IP	TD		00:00.0
2021	PO4445688759	LGE	4	40 ACE	COMP	CCA		V		00:00.0
2021	PO4007483996	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4524088091	LGE	4	40 ACE	SP	CCA	ED	TD		00:00.0
2021	PO4006783981	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4446888764	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4597527645	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4604627581	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4595327737	F	3	45 BRO	SP	CRE		V		00:00.0
2021	PO4614527493	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4623627410	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4632227334	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4650627169	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4659327091	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4668327011	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4448388750	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4008883989	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4524788080	LGE	4	40 ACE	SP	CRE	ED,IP	BD		00:00.0
2021	PO4009883984	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4011083976	F	4	40 BRO	SP	A		V		00:00.0
2021	PO4838327880	F	3	45E OTH	SP	CRE		V		00:00.0
2021	PO4759727354	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO4771327374	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO4779927032	F	4	40 OTH	SP	CCA		V		00:00.0
2021	PO4796827721	F	4	40 OTH	SP	CCA		V		00:00.0
2021	PO4785627761	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO4774627801	F	4	40 OTH	SP	P	ED	V		00:00.0
2021	PO4763227843	F	3	45 OTH	SP	CRE	ED	V		00:00.0
2021	PO4727327420	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021	PO4698527618	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021	PO4704527652	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021	PO4718327499	F	4	40 OTH	SP	P	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO4710027577	F	4	40 OTH	SP	P	ED,HH,ID,RB	BX	RP1	00:00.0

2021 PO4738027325	F	3	45 OTH	SP	S		V	00:00.0	
2021 PO4744427331	F	4	40 OTH	SP	P	ED	V	00:00.0	
2021 PO4778227417	F	3	45 OTH	SP	P		V	00:00.0	
2021 PO4785727496	F	3	45 OTH	SP	P		V	00:00.0	
2021 PO4469888502	LGE	4	40 ACE	ST	CCA		V	00:00.0	
2021 PO4470488508	LGE	1	20 ACE	ST	P		V	00:00.0	
2021 PO4469088517	LGE	4	40 ACE	ST	CCA		V	00:00.0	
2021 PO4468788522	LGE	1	25 ACE	ST	A		V	00:00.0	
2021 PO4469588508	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO4012383964	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4011783961	F	3	45 BRO	SP	A		V	00:00.0	
2021 PO4862909926	F	4	40 XXX	SP	S		V	00:00.0	
2021 PO4445888653	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4016183962	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4015883952	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4446588639	LGE	4	40 ACE	SP	P	ED	BD	00:00.0	
2021 PO4446488655	F	4	40 ACE	SP	A		V	00:00.0	
2021 PO4014083952	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4525288071	LGE	4	40 ACE	SP	P	ED	TD	00:00.0	
2021 PO4525888062	LGE	4	40 ACE	SP	CRE	ED,IP	TD	00:00.0	
2021 PO4526388054	LGE	4	40 ACE	SP	CCA	ED	TD	00:00.0	
2021 PO4446888681	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4015283941	F	4	35 BRO	SP	A		V	00:00.0	
2021 PO4014783944	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4013683950	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4012683955	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4446588681	LGE	4	40 ACE	SP	A	ED	BD	00:00.0	
2021 PO4753425861	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4522588111	LGE	4	40 ACE	SP	CCA	ED,IP	TD	00:00.0	
2021 PO4523588099	LGE	4	40 ACE	SP	CRE	ED,IP	TD	00:00.0	
2021 PO4002184023	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3017787422	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO2984887417	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021 PO2981787363	KU	4	45 BRO	SP	CRE		V	00:00.0	
2021 PO4436688836	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4857513025	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021 PO4845312746	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD	00:00.0	
2021 PO4003584016	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4004784010	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4006184003	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4452088756	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4450388744	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4985709347	KU	6	30 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4446088714A	KU	3	60 ACE	SP	A		V	00:00.0	
2021 PO4448088691	F	4	40 ACE	COMP	CCA		V	00:00.0	
2021 PO6045553803	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021 PO4447188704	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4011083923	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4448188730	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4446088714	LGE	2	70 ACE	SP	CRE		V	00:00.0	
2021 PO4447388724	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4446388718	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO6061753423	KU	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021 PO6051353581	KU	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0	

2021 PO6066853343	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO6057053497	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6072353257	KU	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4447588691	LGE	H1	65 ACE	SP	CRE		V	00:00.0
2021 PO4448888671	LGE	2	65 ACE	SP	CRE		V	00:00.0
2021 PO4450088652	LGE	1	65 ACE	SP	CRE		V	00:00.0
2021 PO4450988646	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4526887895	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4527387888	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4527887879	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021 PO4528787865	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO6044553684	KU	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO6039753771	KU	4	40 BRO	SP	CRE	ED,IP	BD	00:00.0
2021 PO4879310055	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO4877510151	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4873510088	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4660511466	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4650611536	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4660811535	KU	2	65 BRN	SP	S		V	00:00.0
2021 PO4798808978	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4833408821	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4807608844	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4823308296	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4845208232	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4832008213	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4854708744	KU	6	30 XXX	SP	CRE		B	00:00.0
2021 PO4805808381	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4855108223	F	4	40 XXX	SP	CRE	IP	V	00:00.0
2021 PO4870008205	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4846708810	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4875908338	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4898308451	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4822308595	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4833708247	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4883508511	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4860808798	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4820408832	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4841808672	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4451288634	LGE	1	65 ACE	SP	CRE		V	00:00.0
2021 PO4530387840	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4530587835	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4531087828	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4531487822	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4531787816	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4533587787	F	5	40 ACE	SP	CRE		V	00:00.0
2021 PO4452488623	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4452688613	LGE	3	60 ACE	SP	CRE		V	00:00.0
2021 PO4453388608	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO4007883955	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4832626909	F	4	40 OTH	SP	P		V	00:00.0
2021 PO4834626774	F	4	40 OTH	SP	CCA		V	00:00.0
2021 PO4836827025	F	4	40 OTH	SP	P		V	00:00.0
2021 PO4841927094	F	4	40 OTH	SP	P		V	00:00.0
2021 PO4846027148	F	3	40 OTH	SP	P		V	00:00.0

2021 PO3996583988	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO5061509235	KU	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4639323334	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4639123264	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4663523309	KU	5	40 BRN	SP	CCA		V	00:00.0	
2021 PO4701123277	KU	3	40 BRN	SP	CCA		V	00:00.0	
2021 PO6155552106	KU	4	35 BRO	SP	CCA	ID,IP,MD	BD	00:00.0	
2021 PO6152152143	KU	4	45 BRO	SP	CRE	ID,IP,MD	BD	00:00.0	
2021 PO6144552221	KU	4	40 BRO	SP	CRE	ID,IP,MD	BD	00:00.0	
2021 PO4731423253	KU	5	40 BRN	SP	CCA		V	00:00.0	
2021 PO4769323437	KU	5	40 BRN	SP	CRE		T	00:00.0	
2021 PO4766423494	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4522687975	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO4522187962	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4763923552	KU	3	45 BRN	SP	CRE	SRS	TD	00:00.0	
2021 PO4756623704	KU	3	45 BRN	SP	CRE	SRS	TD	00:00.0	
2021 PO4733024086	KU	3	45 BRN	SP	CRE		T	00:00.0	
2021 PO4747023889	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021 PO6130052382	KU	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021 PO6136752308	KU	4	40 BRO	SP	CRE	ID,IP,MD	BD	00:00.0	
2021 PO5040309276	KU	3	45 BRN	SP	S		V	00:00.0	
2021 PO5021609330	F	4	40 BRN	DF	CRE		V	00:00.0	
2021 PO5057509178	KU	4	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5026109358	KU	4	45 BRN	SP	S		V	00:00.0	
2021 PO5036809242	F	4	40 BRN	DF	CRE		V	00:00.0	
2021 PO4008783949	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4453788595	F	3	45 ACE	SP	CRE		V	00:00.0	
2021 PO4453488599	LGE	1	65 ACE	SP	CRE		V	00:00.0	
2021 PO4009683949	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4850827212	F	3	45E OTH	SP	CCA		V	00:00.0	
2021 PO4857827322	F	4	40 OTH	SP	CRE	ED	V	00:00.0	
2021 PO4867627469	F	4	40 OTH	SP	CRE	ED	V	00:00.0	
2021 PO4875127419	F	4	40 OTH	SP	CRE	ED	V	00:00.0	
2021 PO4878027691	F	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO4882727800	F	4	40 OTH	SP	CRE	ED,ID	BX	PX	00:00.0
2021 PO4887027907	F	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO4449388740	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4893728073	F	3	40 OTH	SP	P		V	00:00.0	
2021 PO4897228162	F	3	40 OTH	SP	P	ED	V	00:00.0	
2021 PO4894828216	F	4	40 OTH	SP	CRE	ED	V	00:00.0	
2021 PO4840327596	F	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO4801627127	F	4	40 OTH	SP	CCA		V	00:00.0	
2021 PO4776028110	F	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO4838928452	F	3	45 OTH	SP	CRE		V	00:00.0	
2021 PO4828128316	F	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO4813428116	F	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO4455188572	LGE	1	60 ACE	SP	CRE		V	00:00.0	
2021 PO3996984018	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4457288538	LGE	1	60 ACE	SP	CRE		V	00:00.0	
2021 PO4456388553	LGE	1	60 ACE	SP	CRE		V	00:00.0	
2021 PO3998184024	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3999084020	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4457988525	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO1670797666	LGE	4	30 ACE	SP	CCA	ED,ID	BD	00:00.0	



2021	PO3999684020	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4000784024	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3060287443	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO2976787253	KU	4	40 BRO	SP	CRE	IP,MD	BD	00:00.0
2021	PO3041787430	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4439488794	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4438688807	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4437588823	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO0781262633	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO0773962478	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO0785062370	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO0784662269	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4345184876	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4343784880	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4343584918	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO7956406555	KU	4	60 BRN	AL	CRE		V	00:00.0
2021	PO5738799625	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5712701012	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO2553919772	KU	2	65 BRN	AL	CRE		V	00:00.0
2021	PO2535519841	KU	2	60 BRN	AL	CRE		V	00:00.0
2021	PO2625019502	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO4379284872	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021	PO2580319671	KU	H1	65 BRN	AL	CRE		V	00:00.0
2021	PO4415985943	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO793640587 A	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO7960605650	KU	2	45 BRN	SP	CCA		V	00:00.0
2021	PO7971805542	KU	2	45 BRN	SP	CCA		V	00:00.0
2021	PO4379284886	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021	PO2916018526	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO2935818459	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO2958118384	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO2984518294	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO3012218192	KU	H1	100 BRN	AL	CCA		V	00:00.0
2021	PO3040718080	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO3128117671	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO4283413814	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO4276213848	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4266713898	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO3475416388	KU	H1	100 BRN	AL	CRE		V	00:00.0
2021	PO9827895258	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5878200014	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5888299880	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5888299718	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5887099530	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5886299368	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5881299229	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5874999093	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5852198992	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5861098977	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5870498963	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5822100085	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5834100018	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5842599938	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5850399857	F	4	40 ACE	SP	CRE		V	00:00.0

2021 PO5854199746	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO2234920676	KU	2	65 BRN	AL	CRE		V			00:00.0
2021 PO2215220720	KU	2	65 BRN	AL	CRE		V			00:00.0
2021 PO2202820742	KU	1	65 BRN	AL	CRE		V			00:00.0
2021 PO2186120791	KU	ST	65 BRN	AL	CCA		V			00:00.0
2021 PO2162420856	KU	2	65 BRN	AL	CRE		V			00:00.0
2021 PO2140820915	KU	2	60 BRN	AL	CRE		V			00:00.0
2021 PO2123820962	KU	2	60 BRN	AL	CRE		V			00:00.0
2021 PO2056021070	KU	5	35 BRN	AL	CRE		V			00:00.0
2021 PO2258520621	KU	2	60 BRN	AL	CRE		V			00:00.0
2021 PO2296120542	KU	2	70 BRN	AL	CRE		V			00:00.0
2021 PO2319720491	KU	2	65 BRN	AL	CRE		V			00:00.0
2021 PO2339620448	KU	2	60 BRN	AL	CRE		V			00:00.0
2021 PO2359220407	KU	2	50 BRN	AL	CCA		V			00:00.0
2021 PO2374620375	KU	1	65 BRN	AL	CRE		V			00:00.0
2021 PO2382220359	KU	2	60 BRN	AL	CCA		V			00:00.0
2021 PO2395420329	KU	4	40 BRN	AL	CRE		V			00:00.0
2021 PO2405120307	KU	H1	70 BRN	AL	A		V			00:00.0
2021 PO2423820255	KU	2	60 BRN	AL	CRE		V			00:00.0
2021 PO2449620178	KU	2	60 BRN	AL	CRE		V			00:00.0
2021 PO2476220075	KU	2	65 BRN	AL	CRE		V			00:00.0
2021 PO2501219975	KU	2	60 BRN	AL	CRE		V			00:00.0
2021 PO2518219907	KU	2	60 BRN	AL	CRE		V			00:00.0
2021 PO4383284882	LGE	UNK	25 ACE	SP	CRE		V			00:00.0
2021 PO2668522421	KU	4	40 BRN	SP	CCA		V			00:00.0
2021 PO9690597015	KU	6	30 XXX	SP	S		V			00:00.0
2021 PO9699895990	KU	4	45 BRO	SP	CCA		V			00:00.0
2021 PO4386085231	LGE	4	35 ACE	SP	CCA		V			00:00.0
2021 PO4385885222	LGE	4	30 ACE	SP	CCA		V			00:00.0
2021 PO4387985231	LGE	2	55 ACE	SP	CCA		V			00:00.0
2021 PO4386885221	LGE	1	50 ACE	SP	CCA		V			00:00.0
2021 PO4411186039	LGE	4	35 BRO	SP	CCA		V			00:00.0
2021 PO4403585365	F	4	30 BRO	SP	CRE		V			00:00.0
2021 PO4387085222	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021 PO3520416282	KU	H1	100 BRN	SP	CRE		V			00:00.0
2021 PO4402585358	F	4	30 BRO	SP	CRE		V			00:00.0
2021 PO2703522005	KU	6	30 BRN	SP	CCA		V			00:00.0
2021 PO2698721957	KU	3	45 BRN	SP	CCA		V			00:00.0
2021 PO2687022026	KU	6	30 BRN	SP	CCA		V			00:00.0
2021 PO9680297462	KU	6	30 XXX	SP	S		V			00:00.0
2021 PO4382984911	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX		RP2	00:00.0
2021 PO8566104265	KU	6	35 BRO	SP	CRE	ED	VX		PX	00:00.0
2021 PO4379184991	LGE	4	40 ACE	SP	CRE	ED,ID,RB	VX		RP1	00:00.0
2021 PO4378484766	LGE	4	40 ACE	SP	CRE	ED,HH,ID	VX		RP2	00:00.0
2021 PO4386984887	LGE	UNK	45 ACE	SP	CRE	ED,MD	VX		RP1	00:00.0
2021 4387284996-A	LGE	3	40 ACE	SP	CRE	ED,ID	VX		RP2	00:00.0
2021 PO4384385136	LGE	4	40 ACE	SP	CRE	ED	VX		RP2	00:00.0
2021 PO4421786029	F	3	45 BRO	SP	A	ID,IP,RB	VX		RP1	00:00.0
2021 PO4428385666	F	3	45 BRO	SP	A	RB,SRS	VX		RP1	00:00.0
2021 PO4529287877	LGE	4	35 ACE	SP	CRE	HH,ID	VX		RP2	00:00.0
2021 PO4379584960	LGE	UNK	25 ACE	SP	CRE	ED,HH,RB	VX		RP1	00:00.0
2021 PO4379385058	LGE	4	40 ACE	SP	CRE	ED,HH,ID	VX		RP2	00:00.0
2021 PO4379484927	LGE	4	30 ACE	SP	P	ED,RB	VX		RP1	00:00.0
2021 PO4389085183	LGE	4	35 ACE	SP	A	ED,HH,ID	VX		RP2	00:00.0

2021	PO4415485980	LGE	4	30 BRO	SP	A	HH,ID,RB	X	RP1	00:00.0
2021	PO4438185666	LGE	4	40 BRO	SP	A	ED,RB	X	RP1	00:00.0
2021	PO9737195550	KU	3	45 UNK	SP	CRE	ED,ID,RB	X	RP3	00:00.0
2021	PO4439185655	LGE	4	40 BRO	SP	A	ED,ID,RB	X	RP1	00:00.0
2021	PO4426485696	LGE	4	30 BRO	SP	A	ED,RB	X	RP1	00:00.0
2021	PO4412886010	LGE	4	35 BRO	SP	A	ED,RB	X	RP1	00:00.0
2021	PO9308901240	KU	4	40 UNK	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021	PO9817495447	KU	3	40 UNK	SP	CRE	ED,ID	X	PX	00:00.0
2021	PO4421385656	LGE	4	35 BRO	SP	A	ED,ID,RB	X	RP1	00:00.0
2021	PO2693022395	KU	4	40 BRN	SP	CRE	RB	X	PX	00:00.0
2021	PO9955193790	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO9949194043	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO9931694036	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5627009372	KU	5	30 BRN	SP	A		V		00:00.0
2021	PO8734800704	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO7413300446	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO7356302232	KU	4	45 ACW	SP	CRE	ID	BD		00:00.0
2021	PO9077396599	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO7516105732	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0
2021	PO7372802261	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO7408202854	KU	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021	PO7393802663	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5713411711	KU	2	65 UNK	ST	CCA		V		00:00.0
2021	PO4412385926	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021	PO5428910503	KU	4	45 UNK	SP	CRE		BD		00:00.0
2021	PO7482107906	F	3	45 XXX	SP	CRE	ED,ID,MD	BX	RP1	00:00.0
2021	PO4374885126	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4374785121	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4386184951	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4374284961	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4374484990	LGE	UNK	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4374485002	LGE	3	50 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4272686847	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4282486672	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4373985137	LGE	4	40 ACE	SP	A	ED	TD		00:00.0
2021	4263586498	LGE	3	40 BRO	SP	A	ED	V		00:00.0
2021	PO4405985469	LGE	4	35 BRO	SP	P		B		00:00.0
2021	PO4404885461	LGE	4	35 BRO	SP	A		B		00:00.0
2021	PO4404185447	LGE	4	35 BRO	SP	P		B		00:00.0
2021	PO4404285414	LGE	4	35 BRO	SP	P		B		00:00.0
2021	PO4405285401	LGE	4	35 BRO	SP	P		B		00:00.0
2021	PO4406385393	LGE	4	35 BRO	SP	P		B		00:00.0
2021	PO4407585401	LGE	4	35 BRO	SP	P		B		00:00.0
2021	PO4408885409	LGE	4	35 BRO	SP	P		B		00:00.0
2021	PO4409385437	LGE	4	35 BRO	SP	A		B		00:00.0
2021	PO4410085426	LGE	4	35 BRO	SP	P		B		00:00.0
2021	PO4374485012	LGE	UNK	55 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO2571018598	F	4	40 BRN	SP	CRE	RB	BX	PX	00:00.0
2021	PO5755509292	KU	4	40 BRN	SP	CRE	RB	BX	PX	00:00.0
2021	PO7403300823	KU	5	35 UNK	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO5480611368	KU	6	30 UNK	SP	CRE		BD		00:00.0
2021	PO7907507380	KU	6	35 UNK	SP	CRE	ID	BD		00:00.0
2021	PO4378385175	LGE	UNK	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4367485061	LGE	3	45 ACE	SP	A	ED,ID	BD		00:00.0

2021 PO4373085026	LGE	2	55 ACE	SP	CRE	ED	BD	00:00.0
2021 PO9080896997	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8812197426	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9760797626	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9672198095	KU	3	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO9674698384	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5491311152	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021 PO5606111827	KU	4	45 UNK	SP	CRE		BD	00:00.0
2021 PO4374585027	LGE	2	60 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5554211363	KU	4	40 BRN	SP	CRE		BD	00:00.0
2021 PO5632610973	KU	4	45 UNK	SP	CRE		BD	00:00.0
2021 PO5632710943	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5633510806	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5570813913	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021 PO5573113875	KU	2	60 UNK	SP	CRE		BD	00:00.0
2021 PO5583513689	KU	2	60 UNK	SP	CRE		BD	00:00.0
2021 PO5506911223	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5632412887	KU	4	40 KOP	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5526011875	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5612512141	KU	3	45 UNK	SP	CRE		BD	00:00.0
2021 PO7435400229	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8687400529	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5447810994	KU	4	45 UNK	SP	CRE		BD	00:00.0
2021 PO7438103273	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5638913192	KU	2	65 KOP	SP	CRE		BD	00:00.0
2021 PO7381702560	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7459103624	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7395601829	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7433403298	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7418801372	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7410601527	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7877508878	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO7789507749	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7648607885	KU	4	50 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7758607371	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO7727707168	KU	2	50 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4269986460	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7641405189	KU	2	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO7569705147	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7505604859	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7573405060	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7803706832	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO7791906722	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO7822904791	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7568105184	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO77781007638	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7775207545	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4412985732-a	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7718008190	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO7644906540	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7696608829	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO7689408750	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7681808670	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4396885858	LGE	3	45 BRO	SP	A	ED,ID,IP	BD	00:00.0

2021	PO5615813324	KU	2	65 UNK	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7677806405	KU	3	45 BRN	SP	CRE	ED	BD		00:00.0
2021	PO4381685197	LGE	4	40 ACE	SP	A	ED	VX	RP1	00:00.0
2021	PO4264486562	LGE	3	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PV4265386626	LGE	3	55 BRO	SP	A	ED,ID	BD		00:00.0
2021	PO4265486597	LGE	4	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO9752778545	LGE	1	55 ACE	SP	CCA		V		00:00.0
2021	PO4265386584	LGE	4	35 BRO	SP	CRE	ED,ID,RB	BD		00:00.0
2021	PO4415885721	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO9923678782	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9921478779	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9895479009	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021	PO9999478939	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9764476766	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021	PO9999578938	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO0003378871	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO5601412016	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021	PO4286586689	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021	PO4415685719	LGE	4	40 BRO	SP	P	HH,ID,IP	BD		00:00.0
2021	PO4419485716-A	LGE	3	45 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021	PO4420185723	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021	PO4409285827	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4399985880	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4414385754	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5591712183	KU	4	45 UNK	SP	CRE		BD		00:00.0
2021	PO5582413473	KU	6	30 UNK	SP	CRE		BD		00:00.0
2021	PO4259086599	LGE	4	35 ACE	AL	CCA		V		00:00.0
2021	PO5489910701	KU	5	35 UNK	SP	CRE		BD		00:00.0
2021	PO5649910979	KU	4	45 UNK	SP	CRE		BD		00:00.0
2021	PO5510811802	KU	4	40 UNK	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5600311848	KU	4	45 UNK	SP	CRE		BD		00:00.0
2021	PO5472011465	KU	4	45 UNK	SP	CRE		BD		00:00.0
2021	PO5425610411	KU	4	45 UNK	SP	CRE		BD		00:00.0
2021	PO4407685857	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021	PO4434585669	LGE	4	30 BRO	SP	CRE		V		00:00.0
2021	PO4410885813	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021	PO4267086444	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021	PO9807276616	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021	PO0839162743	LGE	4	35 ACE	SP	A		V		00:00.0
2021	PO4417185830	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO5351233042	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO5347032933	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO5370933158	KU	3	50 BRO	SP	CCA		V		00:00.0
2021	PO5386132974	KU	5	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO5377532749	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO2808789081	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	4491088328	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO8374585135	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO2923388962	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO2796689307	KU	3	45 BRO	SP	CCA	ED	T		00:00.0
2021	PO2819389193	KU	3	45 BRO	SP	CCA	ED,SRS	T		00:00.0
2021	PO2822989178	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO2837389308	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO2828689223	KU	6	30 BRO	SP	CRE	ED	T		00:00.0

2021	PO4491088335	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4462888097	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO1728193293	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4459788052	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4459988046	LGE	4	35 BRO	SP	CCA	ED,ID,IP	BD	00:00.0
2021	PO4492488324	LGE	4	35 ACE	SP	CCA	ED,ID	BD	00:00.0
2021	PO4494088323	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO5335932645	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO0559351058	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO0580251177	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO0796452584	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0048128159	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5411332630	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO8412683956	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8399384149	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4493188321	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4558888084	LGE	1	65 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4560088083	LGE	1	65 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5465932566	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO5312432376	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO4478387808	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4561488082	LGE	1	65 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4562688080	LGE	1	65 ACE	SP	CCA		V	00:00.0
2021	PO8381784347	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8380484370	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8455186424	F	4	40 ACE	SP	P		V	00:00.0
2021	PO8369484528	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4477487802	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021	PO4479087798	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4479887787	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4480587777	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4556488058	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4556788063	LGE	1	105 ACE	SP	CRE		V	00:00.0
2021	PO4073986716	LGE	3	75E ACE	SP	CRE	ED,IP	BD	00:00.0
2021	PO2781188886	F	6	30 BRO	SP	CRE		V	00:00.0
2021	PO4470288282	LGE	2	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4087786734	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4087586740	LGE	4	45 ACE	SP	CCA		V	00:00.0
2021	PO4082586699	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4081586706	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO7968878939	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4075686751	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO0629150075	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0763151238	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021	PO4470988222	LGE	2	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021		4074886722	KU	4	35E ACE	SP	CCA	V	00:00.0
2021	PO4077386727	F	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4077986728	F	4	35 ACE	SP	P		V	00:00.0
2021	PO4471188200	LGE	2	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4034686675	LGE	3	65 ACE	SP	CRE	ED	BD	00:00.0
2021	PO5024925555	KU	4	35 BRO	SP	CRE		T	00:00.0
2021	PO4032686672	LGE	3	65E ACE	SP	A	ED	BD	00:00.0
2021	PO0813552612	KU	3	45 INP	SP	CRE	ID	TD	00:00.0
2021	PO0812252492	KU	4	40 INP	SP	CRE	ID	TD	00:00.0

2021 PO0803351702	KU	6	30 INP	SP	CRE		V		00:00.0
2021 A5042025520	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO5042025520	KU	6	30 BRO	SP	CRE	ED,ID	X	PX	00:00.0
2021 PO4447687944	F	4	35 BRO	SP	A		V		00:00.0
2021 PO4446787943	F	4	35 BRO	SP	CCA		V		00:00.0
2021 PO5300512172	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5303512183	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5311512212	KU	5	35 XXX	SP	CCA	ED	T		00:00.0
2021 PO5318112257	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5303312295	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5325112387	KU	5	35 XXX	SP	CCA	ED	T		00:00.0
2021 PO5343712283	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5313412071	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5316512140	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5326512103	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5335312069	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5346112029	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5360411976	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO5365511956	KU	3	50 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5373311927	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO5384511884	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5389911863	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5400111824	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO5042825660	KU	5	35 BRO	SP	CRE		T		00:00.0
2021 PO4048117271	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4065717149	KU	2	55 BRN	SP	CCA		V		00:00.0
2021 PO8435485042	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8390284806	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4441987942	F	4	35 BRO	SP	A		V		00:00.0
2021 PO4443487942	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4479788151	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5445935252	KU	2	55 BRO	SP	CCA		V		00:00.0
2021 PO4470288154	LGE	1	75 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO2835489007	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4472388153	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4471588154	LGE	1	85 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4029686652	LGE	6	35 ACE	SP	CRE	ED	BD		00:00.0
2021 PO5264233830	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO5322733285	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO5320433224	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4026086646	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4026386649	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4556688065	LGE	4	40 ACE	SP	CCA	ED,MD	V		00:00.0
2021 PV4555988076	LGE	1	65 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4556788087	LGE	1	70 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4554488089	LGE	1	65 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4555388074	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO8453386585	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4046086692	LGE	3	50 ACE	SP	CCA	ED	BD		00:00.0
2021 PO8431085424	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5377833729	KU	6	30 BRO	SP	CRE	ED	BD		00:00.0
2021 PO5375333664	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021 PO4492688342	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4046286696	LGE	4	25E ACE	SP	P	ED	BD		00:00.0

2021	PO5370733545	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO5366533437	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5362333326	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO8411785324	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4044186696	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO0813451478	KU	5	35 INP	SP	CRE	ID	TD	00:00.0
2021	PO0529351058	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4491288330	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO4047886691	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8389385210	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5368332506	KU	5	35 BRO	SP	CRE	ED,ID	BX	00:00.0
2021	PO8397184461	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4474487836	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021	PO4474887833	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO5373132632	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO5381332848	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5390233084	KU	3	50 BRO	SP	CCA		V	00:00.0
2021	PO4462788116	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4463088106	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4463388097	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4458488068	F	4	40 BRO	SP	P		V	00:00.0
2021	PO4458088077	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4475787825	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4476687815	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO5394533198	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO5428533095	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO8387184349	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4085286735	LGE	2	70 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4460088424	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4459288044	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4459488035	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4460288040	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021	PO1560092161	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4453588102	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4457888115	LGE	4	30 BRO	SP	P		V	00:00.0
2021	PO4467688373	LGE	1	60 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4467088371	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4467988362	LGE	3	55 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4467688359	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4468987869	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4066886475	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021	PO4065386482	LGE	3	50 ACE	SP	CCA	ED	BD	00:00.0
2021	PO4477788462	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4063686488	LGE	3	55 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4478388453	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4454088079	LGE	4	30 BRO	SP	P		V	00:00.0
2021	PO4454988068	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4453788088	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4062286495	LGE	3	65 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4062386496	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO4478888444	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4060286507	LGE	3	65 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4058286518	LGE	3	65 ACE	SP	CRE	ED,ID,MD	BD	00:00.0
2021	PO2795587953	F	4	40 BRO	SP	CRE		V	00:00.0



2021	PO2800788147	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO2799688360	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO2848488497	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO2624488194	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO4466888463	LGE	5	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4467688464	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4043086249	LGE	4	40E ACE	SP	CRE	ED,IP	TD	00:00.0
2021	PO4472788512	LGE	4	40 ACE	SP	CRE	ED	V	00:00.0
2021	PV4035286123	LGE	4	30E ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4474988528	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4031486154	LGE	4	45 ACE	SP	CRE	ED	TD	00:00.0
2021	PO4473788522	LGE	4	30 ACE	SP	CRE	ED,ID,RB	TD	00:00.0
2021	PO4473988522	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	4474588513	LGE	4	45 ACE	SP	A	ED,ID	TD	00:00.0
2021	PV4475288502	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4475888491	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4060786440	LGE	UNK	70 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4059086423	LGE	UNK	75 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4476488482	LGE	4	40 ACE	SP	CRE	ED,ID,RB	TD	00:00.0
2021	PO4057086405	LGE	2	75E ACE	SP	CRE	ED	BD	00:00.0
2021	PO4477088473	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4476888468	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO4055286388	LGE	3	65 ACE	SP	CRE	ED	BD	00:00.0
2021	PO8508985607	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8582485627	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8585685808	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8582785813	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8571185827	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8549985853	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8472585904	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4472988456	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4046686314	LGE	3	60 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4472188467	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4047486322	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8496385880	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4471588476	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8517884922	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO8498585088	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4470888487	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4471088490	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4459688030	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4459888025	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4479488435	LGE	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4479988429	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4475488416	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4056386528	LGE	2	45E ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4455088056	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4455488048	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4474788427	LGE	4	40 ACE	SP	CRE	ED,HH,ID	X	RP2 00:00.0
2021	PO4064986489	LGE	4	35 ACE	SP	CRE	ED	TD	00:00.0
2021	PO4064986488	F	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4067286480	F	6	30 ACE	SP	CRE		V	00:00.0
2021	PO4480387480	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4474188437	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0

2021	PO4473588446	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO8521385855	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO8463785913	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4468188087	LGE	2	50 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4470388496	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021	PO4469188492	LGE	4	25 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO8477885251	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4468088484	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4467088477	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4465988473	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4465488474	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4464788470	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4463688464	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO8473385402	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO8484085209	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO4468788379	LGE	2	50 ACE	DF	CRE	ED,ID	BD		00:00.0
2021	PO4468688376	F	4	30 ACE	SP	CCA		V		00:00.0
2021	PO4048586333	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4049486342	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4468587867	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021	PO4048486349	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO8467785506	KU	4	40 ACE	SP	CRE	ED,ID	BX	RP1	00:00.0
2021	PO8458085727	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO5498408050	KU	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5677108161	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5682108149	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5691708126	F	3	45 XXX	SP	CCA		V		00:00.0
2021	PO5690408091	F	3	45 XXX	SP	CCA		V		00:00.0
2021	PO5686307985	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5681307847	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5675307687	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5676908013	KU	5	35 XXX	SP	CCA		V		00:00.0
2021	PO5724708672	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5673008783	F	4	35 XXX	SP	CCA		V		00:00.0
2021	PO5703408725	F	4	45 XXX	SP	CCA		V		00:00.0
2021	PO8121790834	KU	4	35 XXX	SP	S		V		00:00.0
2021	PO4420285598	LGE	4	30 BRO	SP	A		V		00:00.0
2021	PO4441785457	F	3	50 ACE	SP	P		V		00:00.0
2021	PO5694008245	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5699108488	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5693808749	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6091298487	KU	2	55 ACE	SP	CCA		V		00:00.0
2021	PO6094598482	KU	1	55 ACE	SP	CCA		V		00:00.0
2021	PO6086598611	KU	3	50 ACE	SP	CCA		V		00:00.0
2021	PO4447585416	F	4	30 ACE	SP	A		V		00:00.0
2021	PO4448985410	LGE	1	70 ACE	SP	CRE	ED	V		00:00.0
2021	PO4433585322	LGE	4	40 ACE	SP	P	ED,RB	X	PX	00:00.0
2021	PO5634508563	KU	5	35 XXX	SP	CRE	HH,ID,RB	X	PX	00:00.0
2021	PO5687408270	KU	4	40 XXX	SP	CRE	HH,ID,RB	X	RP3	00:00.0
2021	PO5720509033	F	4	40 XXX	SP	CRE	IP	BD		00:00.0
2021	PO4848110774	KU	5	35 XXX	SP	CRE	ID	BD		00:00.0
2021	PO8557994007	F	4	40 XXX	SP	P	ED,MD	BD		00:00.0
2021	PO8696193112	KU	5	35 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO8268697043	KU	5	35 XXX	SP	CRE	ED,ID,IP	BD		00:00.0

2021 PO8267797288	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO8654993338	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5789707929	F	4	40 XXX	SP	CRE	HH,ID,IP	BX	RP2	00:00.0
2021 PO8569693943	KU	5	35 XXX	SP	S	ED	T		00:00.0
2021 PO4882810446	KU	6	30 XXX	SP	CCA	ED	T		00:00.0
2021 PO8635893490	KU	5	35 XXX	DF	CRE	ED,ID	TD		00:00.0
2021 PO4942411229	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO8550193966	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8541893949	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4778010865	KU	6	30 XXX	SP	CRE	ID,IP	TD		00:00.0
2021 PO8556393933	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8618293530	KU	2	40 XXX	SP	CRE	ED,ID,IP,MD	TD		00:00.0
2021 PO8621093573	KU	5	35 XXX	SP	CRE	ED,ID,MD	TD		00:00.0
2021 PO8608893641	KU	5	35 XXX	DF	CRE	ED,ID,IP	TD		00:00.0
2021 PO8597593706	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO8583593784	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8568493864	KU	4	35 XXX	SP	S	ED,ID,IP	TD		00:00.0
2021 PO5685409288	F	4	45 XXX	SP	CCA		V		00:00.0
2021 PO5679109270	KU	6	30 XXX	SP	CRE		V		00:00.0
2021 PO5569406147	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO8627093539	KU	6	30 XXX	SP	S		V		00:00.0
2021 PO8649893412	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO8667893262	KU	4	45 XXX	SP	S		V		00:00.0
2021 PO8260897355	KU	6	30 XXX	SP	CRE		V		00:00.0
2021 PO4869310524	KU	5	35 XXX	SP	CRE		V		00:00.0
2021 PO5452709422	KU	4	40 XXX	SP	CRE		V		00:00.0
2021 PO8551194076	F	4	40 XXX	SP	P		V		00:00.0
2021 PO8530893921	F	4	40 XXX	SP	P		V		00:00.0
2021 PO8522493905	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO8513994068	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO8507794188	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO8498394376	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO8487594579	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO8480894713	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO8474094847	KU	3	40 XXX	SP	S		V		00:00.0
2021 PO8466994979	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO8457395166	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO4906510942	KU	5	35 XXX	SP	CCA		V		00:00.0
2021 PO4910510840	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO4902310841	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4900210792	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4891510730	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4895410689	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4890510614	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4872910689	F	5	35 XXX	SP	CRE		V		00:00.0
2021 PO4870110612	KU	5	35 XXX	SP	CCA		V		00:00.0
2021 PO5685009245	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5747509011	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5771708993	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5758309003	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5733909023	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5708209043	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5695509055	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5682209064	F	4	40 XXX	SP	CRE		V		00:00.0

2021 PO5684408941	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5679908952	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8301497618	KU	4	40 XXX	SP	CRE	ED,ID	B	00:00.0
2021 PO4465185603	LGE	3	50 ACE	SP	A	ED	BD	00:00.0
2021 PO4465585606	LGE	4	35 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4461185574	LGE	UNK	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8435800822	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8468800710	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4464185595	LGE	UNK	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4446685662-C	LGE	5	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4446685662-A	LGE	5	35 BRO	SP	A	ID	BD	00:00.0
2021 PO0010293885	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9957993663	KU	5	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4468185724	LGE	UNK	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0045590632	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO0034190711	KU	3	45 UNK	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0022290790	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5963599639	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4465085605	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4466285612	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4433385262	LGE	4	30 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4451685577	LGE	UNK	75 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4451885555	LGE	4	35 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4448385663	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4448085668	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO4447085675	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4447385672	LGE	UNK	70 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4441685729	LGE	4	35 ACE	SP	A	ED	BD	00:00.0
2021 PO6040396996	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4452885370	LGE	UNK	65 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4450885384	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4450485388	LGE	UNK	65 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4449785394	LGE	UNK	70 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4451885378	LGE	UNK	65 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5950496578	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5970596683	KU	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5967196706	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4483185686	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4481985703	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4480785699	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4479785692	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO8966193452	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO0024196203	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO0044891338	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO0063691201	KU	4	40 UNK	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0036090378	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9522494040	KU	4	40 XXX	SP	S		BD	00:00.0
2021 PO9498894404	KU	5	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO6106496965	KU	5	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO1263165403	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 4445685420-a	LGE	3	50 ACE	SP	P	ED	BD	00:00.0
2021 PO4445685420	LGE	UNK	55 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO0016994876	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4446685662-B	LGE	5	35 BRO	SP	A	ID	BD	00:00.0

2021	PO4470885671	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4470285682	LGE	3	55 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4468785707	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0
2021	PO0162594222	KU	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021	PO0202594222	KU	4	45 UNK	SP	P	ID	BD	00:00.0
2021	PO0240094223	KU	4	40 UNK	SP	P	ID	BD	00:00.0
2021	PO92777897284	KU	1	80 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0040794797	KU	4	40 UNK	SP	CCA	ID	BD	00:00.0
2021	PO5922999971	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4468385641	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4394885207	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021	4468385641-a	LGE	3	45 ACE	SP	CCA	ED	BD	00:00.0
2021	PO4468185630	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021	PO5853996700	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4400385281	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO5881796655	KU	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4451685530	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO1649667876	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO8413795883	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO8455895496	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO5920996538	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5936696558	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4395985226	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4466085737	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO9986592382	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4398085253	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4445313032	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4449885656	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4451185654	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4448485634	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4450485649	LGE	4	35 ACE	SP	A	ED	BD	00:00.0
2021	PO4376585241	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4450785650	LGE	UNK	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4445685376	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021	PO4446385388	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021	PO4433185236	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4433185249	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021	PO4445585385	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4445785390	LGE	3	45 ACE	SP	CCA	ED	BD	00:00.0
2021	PO4444885374	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4444485362	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4443185287	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4443785286	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4490285667	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4489685675	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4488985684	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4452785549	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4453085550	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4453385545	LGE	UNK	65 ACE	SP	A	ED	BD	00:00.0
2021	PO4451485599	LGE	UNK	75 ACE	SP	CRE	ED	BD	00:00.0
2021	PO0067990735	KU	6	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO4445685698	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4446085692	LGE	UNK	70 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4446585684	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0

2021 PO4445785707	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO0116691259	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO6010996850	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4444985710	LGE	UNK	70 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4444585717	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4444085725	LGE	1	65 ACE	SP	CRE	ED,HH,ID	BD	00:00.0
2021 PO4443685732	LGE	4	40 ACE	SP	CCA	MD	BD	00:00.0
2021 PO6023896915	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 4443385435-a	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021 4441285449-a	LGE	3	50 ACE	SP	P	ED	BD	00:00.0
2021 PO4444485428	LGE	UNK	55 ACE	SP	CRE	ED	BD	00:00.0
2021 PO6078195968	KU	3	45 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021 PO0069297752	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4442485682	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO6143797228	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6123697162	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4473185635	LGE	UNK	65 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4474385626	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4472985621	LGE	UNK	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO6043799264	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6066299154	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6072099251	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6073199271	KU	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4442585649	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4472085652	LGE	3	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4470585660	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO0055296234	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4463985752	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4465585762	LGE	UNK	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4462785776	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO4461585769	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO4417185342	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO0065094221	KU	4	40 UNK	SP	P	ID,IP	BD	00:00.0
2021 PO9100596642	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO0107094222	KU	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO0135094222	KU	4	40 UNK	SP	P	ID	BD	00:00.0
2021 PO5935298500	KU	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO7540480141	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4968284906	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR 00:00.0
2021 PO5122084475	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO5120584443	LGE	4	35 ACE	SP	P	ED	VX	RP3 00:00.0
2021 PO5022084812	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7549480182	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7541080191	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7541880322	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7541980414	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5122784431	LGE	4	25 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO5122084442	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO5124384442	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO7559180357	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7567280331	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5131584421	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021 PO4972384903	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4969884903	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0

2021 PO5131384440	LGE	4	40 ACE	SP	P	ED,MD	BD		00:00.0
2021 PO4969884911	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4968784908	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO8573883749	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO5134884440	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO5139084427	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO5139084438	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO5143584436	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO4968084893	LGE	4	30 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO49444484645	LGE	5	35 BRO	SP	CRE		V		00:00.0
2021 PO4074886722	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4459388414	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4848085703	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4847085706	F	5	30 ACE	SP	CRE		V		00:00.0
2021 PO5096085117	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO5098285102	LGE	4	40 ACE	SP	P	ED	TD		00:00.0
2021 PO5100385087	LGE	4	40 ACE	SP	P	ID	BD		00:00.0
2021 PO5102585072	LGE	4	40 ACE	SP	P	ID	BD		00:00.0
2021 PO5104785057	LGE	4	40 ACE	SP	P	ID	BD		00:00.0
2021 PO7566383317	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7564283091	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7557682858	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7562382877	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7555682631	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5094584445	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO5091884449	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4368710884	F	6	30 XXX	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO4395510958A	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4381911012	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4375311039	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4395510958	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5109784420	LGE	4	30 ACE	SP	P	ED	VX	RP3	00:00.0
2021 PO7550082002	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7573781978	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7547381677	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7545581488	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7543581263	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO5108984382	LGE	4	30 ACE	SP	P	ED	BD		00:00.0
2021 PO5109784382	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO4538087878	LGE	4	30 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4537787881	LGE	4	40 BRO	SP	P	ED,EP,ID,IP	BD		00:00.0
2021 PO4538287892	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4531887843	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4341910871	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4933785032	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO6914862319	LGE	5	35 BRO	SP	CCA		V		00:00.0
2021 PO5115184419	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO5114784425	LGE	4	30 ACE	SP	P	ED	VX	RP3	00:00.0
2021 PO4533187859	LGE	4	30 BRO	SP	CRE	ED,EP,ID,MD	BD		00:00.0
2021 PO4533587854	LGE	4	40 BRO	SP	P	ED,ID,SR	TD		00:00.0
2021 PO4534387859	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4534987869	LGE	4	30 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4535187865	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4536887876	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		00:00.0

2021 PO4536087871	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4516587736	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4502587922	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5119484443	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO7543380725	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4979484826	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4978684830	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4978584825	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4974484814	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4384410402	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4392310340	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4398310352	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4374310439	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4391710664	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4390110560	KU	6	30 XXX	SP	S	ED	T	00:00.0
2021 PO4421610543	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4434910488	F	4	40 XXX	SP	S		V	00:00.0
2021 PO7569479967	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7539380011	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7570680041	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7545080004	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4975584899	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4443811138	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4442611242	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4439511024	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4433710871	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4436010876	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO4430110778	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4433710811	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO4423610591	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4426010648	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4424810668	KU	6	30 XXX	SP	CRE		V	00:00.0
2021 PO5128884441	LGE	4	40 ACE	SP	P		V	00:00.0
2021 5128884441-a	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO7552682298	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021 PO5106985042	LGE	4	40 ACE	SP	P		V	00:00.0
2021 PO4396710817	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4939884735	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4937684771	LGE	1	65 BRO	SP	A	ID	BD	00:00.0
2021 PO4937184765	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4936284800	LGE	1	70 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO5113084416	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO8306957286	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4311709653	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4338810030	F	4	40 XXX	SP	CRE	EP	V	00:00.0
2021 PO4337209971	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4331909829	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4324809617	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4317010078	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4327610053	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4326410011	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4313710036	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4322109886	F	4	40 XXX	SP	CRE	HH,ID	BX RP2	00:00.0
2021 PO4302309928	KU	5	35 XXX	SP	CCA		V	00:00.0



2021	PO4308709890	F	4	35 XXX	SP	CCA		V	00:00.0
2021	PO4314009874	F	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4317409861	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4325809578	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4299109325	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4314309321	F	4	40 XXX	SP	CRE	IP	V	00:00.0
2021	PO4334109330	KU	2	70 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4405010921	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4416811087	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4418811341	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO4843311790	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4538587887	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4352710830	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4364910778	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4350010618	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4348310537	KU	3	45 XXX	SP	S		V	00:00.0
2021	PO4365610587	KU	5	35 XXX	SP	CRE	ED,ID,IP,Src	TD	00:00.0
2021	PO4361110489	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4378110723	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7520780627	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7506780634	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7482380669	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7420183030	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5114084394	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021	PO5115284394	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4844785712	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4843585721	F	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4845985709	F	5	30E ACE	SP	CRE	ED	V	00:00.0
2021	PO4843685714	LGE	4	40 ACE	SP	A		V	00:00.0
2021	PO4848285604	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4532287845	LGE	4	35 BRO	SP	CRE	ED,ID,IP,MD	BD	00:00.0
2021	PO4532787848	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4857285984	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4854185789	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0
2021	PO4847485580	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4846985598	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO7530781015	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7542280840	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7540780946	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7539980772	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7563380484	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5012908766	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO5146884430	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4966784910	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4945585000	F	1	65 BRO	SP	CCA		V	00:00.0
2021	PO8717057328	LGE	1	50 ACE	SP	P		V	00:00.0
2021	PO5154784388	LGE	4	35 ACE	SP	P		V	00:00.0
2021	PO5149484420	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO7581679947	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4320008797	KU	5	35 BRN	SP	CRE		V	00:00.0
2021	PO4321508653	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO4316108714	KU	6	30 BRN	SP	CCA	ED	T	00:00.0
2021	PO4341409239	KU	2	70 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5107485046	LGE	4	30 ACE	SP	P		V	00:00.0

2021 PO5086584523	LGE	4	40 ACE	SP	P		V	00:00.0
2021 PO4540387677	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4541387659	LGE	3	45 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4542087640	LGE	3	45 BRO	SP	CCA	ED,HH,ID,IP,RB	BX	RP1 00:00.0
2021 PO4379111218	KU	6	30 XXX	SP	CRE	ED	T	00:00.0
2021 PO4395111234	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4381111289	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4367511071	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7667582861	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7670283115	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5090184446	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO5091384421	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO5091584417	LGE	4	35 ACE	SP	A	ID	BD	00:00.0
2021 PO7637783175	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7624582986	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7610983228	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8095557477	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5093584417	LGE	3	45 ACE	SP	A	ID	BD	00:00.0
2021 PO5093684421	LGE	4	40 ACE	SP	A	ED	V	00:00.0
2021 PO5095384463	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4333009253	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4331709194	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4327409262	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4319108983	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021 PO4317408820	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021 PO4542387626	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4542787606	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7582683283	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4542187530	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4542287520	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4542387511	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4542087511	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4541287512	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4539087900	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4539387892	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5098984419	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4948984639	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4944084682	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4946484661	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4941384705	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5104684420	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO5107684416	LGE	3	45 ACE	SP	P		V	00:00.0
2021 PO5109784416	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4408210597	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4401310453	KU	6	30 XXX	SP	CRE	ED,EP,ID,IP,SR	TX	RR 00:00.0
2021 PO4447911248	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7578180262	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7592480357	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5126884400	LGE	4	40 ACE	SP	S	ED	BD	00:00.0
2021 PO5126984417	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO5127084434	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021 PO5127284441	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4858385566	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO4859085534	LGE	3	45 ACE	SP	P	ED	BD	00:00.0

2021 PO4849385699	F	3	45 ACE	SP	P		V	00:00.0	
2021 PO4977984898	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO7603180256	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7592480097	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4389285246	LGE	2	50 BRN	SP	CCA		V	00:00.0	
2021 PO4389185243	LGE	5	35 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO4391285230	LGE	5	30 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO7767281488	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO7757781407	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4529688004	LGE	2	60 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5080784686	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5080984681	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7592481100	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7621881319	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO7594081339	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7580681358	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7599781952	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7597381668	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7627481908	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4429312167	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO7606678154	KU	2	70 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4924085004	LGE	5	25 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4403285464	F	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4402885451	F	4	30 ACE	SP	P		V	00:00.0	
2021 PO4401685453	F	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4402485476	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4402485478	F	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4401485473	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4401485486	F	4	30 ACE	SP	P		V	00:00.0	
2021 PO4400985482	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO9888031027	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO9882731047	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4378785199	LGE	4	35 BRN	SP	A	ED,ID	TD	00:00.0	
2021 PO4379085201	LGE	5	35E BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO4922484973	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4920284958	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021 PO9869931095	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO9875330782a	KU	2	50 ACE	SP	CCA		V	00:00.0	
2021 PO9875330782	KU	2	50 ACE	SP	CCA		V	00:00.0	
2021 PO5308306330	KU	5	35 XXX	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4920584953	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO9865930774	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO9847030767	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO9827830767	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO9817030808	KU	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO4376285270	LGE	4	35 BRN	SP	A	ED,HH,ID	BX	RP1	00:00.0
2021 PO4376785279	LGE	4	30 BRN	SP	CCA		V	00:00.0	
2021 PO4377085276	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO4377985279	LGE	4	30 BRN	SP	CCA		V	00:00.0	
2021 PO5200584818	LGE	4	30 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO5200884811	LGE	3	45 ACE	SP	P	ED	BD	00:00.0	
2021 PO5197384776	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4377885283	LGE	5	35 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4378585289	LGE	5	35 BRN	SP	A	ED,ID	BD	00:00.0	

2021 PO4922985041	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4379385295	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4380185302	LGE	3	45 BRN	SP	CCA	ED,ID	BD	00:00.0
2021 PO4380485304	LGE	4	35 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO7763481833	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO7761081852	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7758481829	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7743081688	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4370285220	LGE	4	40 BRN	SP	CCA		VX PX	00:00.0
2021 PO4370385256	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PV4369385235	LGE	6 30E	BRN	SP	A		V	00:00.0
2021 PO4369585229	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO4370885214	LGE	4	40 BRN	SP	CCA		VX PX	00:00.0
2021 PO4369885559	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO4360985503	F	3 35E	ACE	SP	CCA		V	00:00.0
2021 PO4358785514	LGE	3 45E	ACE	SP	P	ED,IP	TD	00:00.0
2021 PV0728667619	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4375485244	LGE	4	40 BRN	SP	CCA	ED,ID,RB	BX RP2	00:00.0
2021 PO4374285253	LGE	6 30E	BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4356885547	LGE	3	45 ACE	SP	P	ED	TD	00:00.0
2021 PO4374585256	LGE	4	40 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4373385271	LGE	5 35E	BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4372785305	F	5 35E	BRN	SP	A		V	00:00.0
2021 PO4371685285	LGE	6 30E	BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4372085287	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO0323300018	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0337530001	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0328029846	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5638206677	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4355685567	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5628206434	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO5623306328	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4372085280	LGE	5	30 BRN	SP	A		V	00:00.0
2021 PO0337629026	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0333928975	KU	4	35 ACE	SP	CCA		V	00:00.0
2021 PO5637406161	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO0711667929	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 4354985579-a	LGE	4 35E	ACE	SP	P	ED,IP	BD	00:00.0
2021 PO4354985579	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021 PO4374485274	LGE	5	35 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO0332929191	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0332229165	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4375585284	LGE	4	35 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO5387806747	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5379606584	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5376106512	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5369606389	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5367806347	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5364406279	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5359906387	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5321106283	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO0005330189	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO5623605928	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO0034929836a	KU	5	35 ACE	SP	CCA		V	00:00.0

2021 PO4376785294	LGE	5	35E	BRN	SP	A	ED,ID	BD	00:00.0
2021 PO0015130082	KU	5	35	ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0024529960	KU	5	35	ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0034929836	KU	5	35	ACE	SP	CCA		V	00:00.0
2021 PO4354085591	LGE	4	40	ACE	SP	P	ED	TD	00:00.0
2021 PO4353085602	LGE	3	45	ACE	SP	CCA		V	00:00.0
2021 PO4352285604	LGE	3	45E	ACE	DF	CCA	ED	V	00:00.0
2021 PO4402785507	F	4	40	ACE	SP	P		V	00:00.0
2021 PO9978130553	KU	5	35	ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7735981623	KU	4	45	ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7717081450	KU	4	40	ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7737182098	KU	4	40	ACE	SP	CCA		V	00:00.0
2021 PO5194084743	LGE	3	45	ACE	SP	CCA		V	00:00.0
2021 PO5191284671	LGE	3	45	ACE	SP	CRE		V	00:00.0
2021 PO5195184671	LGE	4	25	ACE	SP	P		V	00:00.0
2021 PO5195184677	LGE	4	35	ACE	SP	CCA		V	00:00.0
2021 PO4921785035	LGE	4	35	BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4380685295	LGE	4	35	BRN	SP	A	ED,ID	BD	00:00.0
2021 PO5194484716	LGE	3	45	ACE	SP	CCA		V	00:00.0
2021 PO4925985017	LGE	3	45	BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4925985017-A	KU	5	35	BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4388485239	LGE	1	65	BRN	SP	CCA	ED,ID	BD	00:00.0
2021 PO4387485250	LGE	1	55	BRN	SP	CCA	ED,ID	BD	00:00.0
2021 PO4384985269	F	4	35	BRN	SP	A		V	00:00.0
2021 PO4385685262	F	5	35E	BRN	SP	A		V	00:00.0
2021 PO7736282008	KU	4	40	ACE	SP	CCA		V	00:00.0
2021 PO7739082269	KU	4	40	ACE	SP	CCA		V	00:00.0
2021 PO7740382388	KU	4	45	ACE	SP	CCA		V	00:00.0
2021 PO7742882647	KU	4	40	ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7744082739	KU	4	40	ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7760382940	KU	4	40	ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7746382962	KU	4	40	ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7737182986	KU	4	40	ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4386185255	F	5	35	BRN	SP	A		V	00:00.0
2021 PO4386585261	LGE	3	55	BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4386485263	F	5	40E	BRN	SP	A		V	00:00.0
2021 PO5070184728	LGE	3	45	ACE	SP	A	ED	BD	00:00.0
2021 PO5083184762	LGE	4	40	ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4927585036	LGE	4	40	BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5086684753	LGE	4	40	ACE	SP	P	ED,ID	BD	00:00.0
2021 PO9953830709	KU	5	35	ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9939930743	KU	5	35	ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9931330763	KU	3	50	ACE	SP	CCA		V	00:00.0
2021 PO4918084944	LGE	3	45	BRN	SP	CCA		V	00:00.0
2021 PO4920184947	LGE	4	40	BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4921284951	LGE	4	35	BRN	SP	CCA		V	00:00.0
2021 PO4378285220	LGE	5	35	BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4378085221	LGE	6	30	BRN	SP	A		V	00:00.0
2021 PO5381506272	F	4	40	XXX	SP	S		V	00:00.0
2021 PO5376206301	F	4	40	XXX	SP	CRE		V	00:00.0
2021 PO5330706246	KU	5	35	XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4377485214	LGE	4	35	BRN	SP	CCA		V	00:00.0
2021 PO4376285229	LGE	4	40	BRN	SP	CRE		V	00:00.0
2021 PO4403385499	F	4	40	ACE	SP	P		V	00:00.0

2021	PO4404785495	F	6	30 ACE	SP	CRE	ED,HH,ID,IP,MD,RB	VX	PX	00:00.0
2021	PO4404085490	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4404685480	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4377585217	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021	PO4378085213	LGE	4	40 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO5441707052	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5440806925	KU	4	40 XXX	SP	CRE	ID	TX	RR	00:00.0
2021	PO5434906814	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5427006668	KU	5	35 XXX	SP	CCA		V		00:00.0
2021	PO5314506503	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO5363306917	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO4919685002	LGE	4	45 BRO	SP	CCA		V		00:00.0
2021	PO4922084981	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO5419106517	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5078484954	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4921884988	LGE	4	30 BRO	SP	A	ID	BD		00:00.0
2021	PO4923184988	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5363606784	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO5357406823	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5353406710	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5348106568	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5343006430	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5344806476	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO5137184979	LGE	3	45 ACE	SP	CRE	ED	BD		00:00.0
2021	PO5137384981	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO8536663227	LGE	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO5411006368	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5407206295	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO4404585465	F	4	30 ACE	SP	P	ED	V		00:00.0
2021	PO4404085470	F	5	40 ACE	SP	P	ED	V		00:00.0
2021	PO8543363236	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4920985026	LGE	3	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4928985053	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4392986047	LGE	4	30 ACE	SP	CRE	ID	VX	RP1	00:00.0
2021	PO5079984778	F	3	45 ACE	SP	CRE		V		00:00.0
2021	PO5080084768	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO5080084769	F	3	45 ACE	SP	P		V		00:00.0
2021	PO5070084752	LGE	3	50 ACE	SP	CRE	ED	BD		00:00.0
2021	PO5080084752	F	3	50 ACE	SP	CRE		V		00:00.0
2021	PO4930785045	F	3	45 BRO	SP	CCA		V		00:00.0
2021	PO5032684821	F	4	40 BRO	SP	A		V		00:00.0
2021	PO4377885303	LGE	5	35 BRN	SP	CCA	ED,ID,MD	VX	PX	00:00.0
2021	PO4378785316	LGE	4	35 BRN	SP	P	ED,ID	BD		00:00.0
2021	PO0046829736	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO0060129657	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO0073429590	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5605405788	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5625705707	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5032084811	F	4	30 BRO	SP	A		V		00:00.0
2021	PO0002630346	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX	PX	00:00.0
2021	PO9999630327	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO9998430439	KU	4	35 ACE	SP	CCA		V		00:00.0
2021	PO0013530477	KU	5	35 ACE	SP	CCA		V		00:00.0
2021	PO0007830495	KU	5	35 ACE	SP	CCA		V		00:00.0

2021 PO4908584757	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO9988030453	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO9966830641	KU	5	35 ACE	SP	CRE	ED,ID	V		00:00.0
2021 PO9905730956	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4925585017	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4375885266	LGE	5 35E	BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO4923785039	LGE	4	40 BRO	SP	A	ED,ID,RB	TX	RR	00:00.0
2021 PO5309606169	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO5320906129	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5351606024	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5359605994	KU	5	35 XXX	SP	S		V		00:00.0
2021 PO5365405975	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5379505924	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4925884904	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PV1819379203	LGE	5 35E	BRN	SP	P		V		00:00.0
2021 PO4382185253	LGE	5	35 BRN	SP	P		V		00:00.0
2021 PO4380985243	LGE	4	35 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO4379885233	LGE	4	35 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO4379085227	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4377685237	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4377085226	LGE	4	40 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO4376385235	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4374585298	LGE	5	25 BRN	SP	CCA		V		00:00.0
2021 PO4373385313	F	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4374085304	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4373385298	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4373685293	F	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4372985294	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4374085232	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO4373285220	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4372885222	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4372785216	LGE	6 30E	BRN	SP	P		V		00:00.0
2021 PO4371885214	LGE	3 45E	BRN	SP	CCA		V		00:00.0
2021 PO4371785207	LGE	5	30 BRN	SP	A		V		00:00.0
2021 PO5393505875	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5403505833	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5415905774	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5426105720	KU	5	35 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO5447705610	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5423306232	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5421806102	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5440205924	KU	4	40 XXX	SP	CRE	HH,RB	X	RP2	00:00.0
2021 PO5436806056	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5443706198	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5451506339	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5456406528	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5458306464	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5466806626	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5475406790	KU	5	35 XXX	SP	CRE	ID,IP,RB	TX	RR	00:00.0
2021 PO5168984788	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO7777782601	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7779682768	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7780882904	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7778682485	KU	4	45 ACE	SP	CCA		V		00:00.0

2021	PO7774582352	KU	4	45 ACE	SP	CCA			V	00:00.0
2021	PO7772982229	KU	4	40 ACE	SP	CCA			V	00:00.0
2021	PO7771182059	KU	4	40 ACE	SP	CCA			V	00:00.0
2021	PO4341714084	KU	2	45 XXX	SP	CRE	ID,IP		TD	00:00.0
2021	PO4349814064	KU	3	45 XXX	SP	CRE	ID		BD	00:00.0
2021	PO4643713055	KU	4	45 XXX	SP	CRE	ED,JD		TD	00:00.0
2021	PO5061384891	LGE	4	30 ACE	SP	CRE	ED,JD		BD	00:00.0
2021	PO4991184683	LGE	4	40 BRO	SP	A	ED,JD,IP		TD	00:00.0
2021	PO4989084683	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021	PO7828681388	KU	4	40 ACE	SP	CRE	ED,JD,IP		TD	00:00.0
2021	PO5174184776	LGE	3	45 ACE	SP	CCA			V	00:00.0
2021	PO8918161215	LGE	3	45 ACE	SP	CCA			V	00:00.0
2021	PO5176684714	LGE	4	35 ACE	SP	CRE	ED,JD		TD	00:00.0
2021	PO7424382780	KU	4	40 ACE	SP	CRE	ED,JD,IP		BD	00:00.0
2021	PO7422482578	KU	4	40 ACE	SP	CRE	ED,JD,IP		TD	00:00.0
2021	PO7420682378	KU	4	40 ACE	SP	CRE	ED,JD,IP		BD	00:00.0
2021	PO5177384720	LGE	3	45 ACE	SP	CCA			V	00:00.0
2021	PO8945460667	LGE	3	45 ACE	SP	CCA			V	00:00.0
2021	PO5178284672	LGE	3	45 ACE	SP	CCA			V	00:00.0
2021	PO4850285213	LGE	4	40 ACE	SP	CRE	ED,JD		BD	00:00.0
2021	PO4844585858	LGE	2	50 ACE	SP	CRE	ED,JD	TX	RR	00:00.0
2021	PO4445785866	LGE	3	50 BRO	SP	CRE	ED,JD,IP		BD	00:00.0
2021	PO4444685869	LGE	3	50 BRO	SP	P	ED,JD		BD	00:00.0
2021	PO4446185872	LGE	4	30 BRO	SP	P	ED,JD		TD	00:00.0
2021	PO4446485881	LGE	4	40 BRO	SP	P	ED,JD		TD	00:00.0
2021	PO1580071192	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4443485882	LGE	4	30 BRO	SP	P	ED,JD,IP		TD	00:00.0
2021	PO1582071251	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4875809795	F	4	40 XXX	SP	S			V	00:00.0
2021	PO4881309881	F	4	40 XXX	SP	S			V	00:00.0
2021	PO4658512576	KU	4	40 XXX	SP	CRE	ED,JD		TD	00:00.0
2021	PO4652912436	KU	6	35 XXX	SP	S			V	00:00.0
2021	PO4647312632	KU	4	40 XXX	SP	S			V	00:00.0
2021	PO4636212496	KU	4	45 XXX	SP	S			V	00:00.0
2021	PO4635412983	KU	5	35 XXX	SP	S			V	00:00.0
2021	PO4647512951	KU	5	35 XXX	SP	S	ED,SR		T	00:00.0
2021	PO1614469645	LGE	4	35 BRO	SP	CRE	ED,JD		BD	00:00.0
2021	PO4448685725	LGE	4	40 BRO	SP	CRE	ED,JD,IP		BD	00:00.0
2021	PO6162352324	KU	5	35 BRN	SP	CCA			V	00:00.0
2021	PO4353414132	KU	6	30 XXX	SP	CRE	ID		BD	00:00.0
2021	PO4335313854	KU	4	45 XXX	SP	CCA			V	00:00.0
2021	PO4337213740	KU	3	45 XXX	SP	CRE	ID,IP		BD	00:00.0
2021	PO6182252040	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO6199751963	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO6201151885	KU	4	45 OTH	SP	CRE	ID,IP		BD	00:00.0
2021	PO4449385714	LGE	3	45 BRO	SP	P	ED,JD		BD	00:00.0
2021	PO4449985703-A	LGE	5	30 BRO	SP	A	ED,JD,IP		BD	00:00.0
2021	PO4449985703	LGE	3	45 BRO	SP	CCA	ED,JD		BD	00:00.0
2021	PO4450685692	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4451185675	LGE	4	30 BRO	SP	A	ED,JD,IP		BD	00:00.0
2021	PO4451785677	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4452385663	LGE	3	45 BRO	SP	A	ED,EP,JD,IP		BD	00:00.0
2021	PO5016884841	LGE	4	40 BRO	SP	CRE			V	00:00.0
2021	PO5016884876	LGE	4	30 BRO	SP	CRE			V	00:00.0



2021 PO4843385388	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4843385380	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4849585323	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO8055866139	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO6162451730A	KU	6	30 OTH	SP	CCA	ED,ID	TD	00:00.0	
2021 PO5089085277	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO5087085286	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO5084085300	LGE	2	55 ACE	SP	CCA		V	00:00.0	
2021 PO5085385294	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO4850285213A	LGE	4	40 ACE	SP	CRE		VX	RP3	00:00.0
2021 PO4845585201	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4849185266	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4984884809	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5082785310	LGE	2	55 ACE	SP	CCA		V	00:00.0	
2021 PO4849585250	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0	
2021 PO4847585211	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO5081085324	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO5079985332	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO6206951450	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO7409981128	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7411681327	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO5184084664	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO5196384389	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4979685161	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO9087656236	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4979985151	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO4980685132	F	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO5193684389	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4980385130	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4981385112	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PV4982185089	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO5194584412	F	3	50 ACE	SP	P		V	00:00.0	
2021 PO4983185059	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO5011784818	LGE	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4839385874	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO5116984427	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO6265251333	KU	6	30 OTH	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4988984723	LGE	3	45 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021 PO4421912820	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4409012893	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4429212779	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4431112766	KU	3	45 XXX	SP	CCA		V	00:00.0	
2021 PO4436112842	KU	5	35 XXX	SP	CCA		V	00:00.0	
2021 PO4437812870	KU	5	35 XXX	SP	CCA	ED	T	00:00.0	
2021 PO7513482897	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4862285445	LGE	4	45 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4840085882	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO7487182919	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7467882933	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4845685851	F	4	30 ACE	SP	CRE		V	00:00.0	
2021 PO4845185848	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4845785840	LGE	4	40 ACE	SP	P	ED,IP	TD	00:00.0	
2021 PO4849285838	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO4849385840	LGE	4	40 ACE	SP	CCA		V	00:00.0	

2021 PO4849285800	F	6	25 ACE	SP	P		V	00:00.0
2021 PO4850185761	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4849885771	F	4	35E ACE	SP	CRE		VX	00:00.0
2021 PO4848685799	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4846285827	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4989484753	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4985784669	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4986984668	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO5062084889	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4879910452	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4448185767	LGE	4	40 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4444985736	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4853110516	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4843810584	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4845210606	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4919112033	F	6	30 XXX	SP	CRE		V	00:00.0
2021 PO4445485749-A	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4446185739	LGE	4	30 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4446285738	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO7399283059	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7377383096	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7376883349	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6190952022	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7003861221	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5078885342	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4985284782	F	3	45 BRO	SP	A		V	00:00.0
2021 PO5077785353	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO5076685363	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO5075485372	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO6198651463A	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO5082085030	LGE	4	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO5082485025	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4902209857	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4897409793	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4986184774	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4992184663	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4987684762	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7445982941	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7425782957	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4849209374A	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO4843209280	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4849209374	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4856609354	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4853209338	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4855809477	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4861209562	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4885309639	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4881809658	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4871009717	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4845385881	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4843585882	F	4	40E ACE	SP	CRE		V	00:00.0
2021 PO4843885874	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4445485831	LGE	3	45 BRO	SP	A		B	00:00.0
2021 PO4443285803	LGE	4	35 BRO	SP	CCA	ED,ID,IP,MD	BD	00:00.0

2021 PO4443385818	LGE	4	35 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4443785833	LGE	3	45 BRO	SP	CCA		B		00:00.0
2021 PO4442085834	LGE	3	50 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4443685887	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4409211456	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4404111588	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4399511798	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4443012001	KU	6	30 XXX	SP	CCA		V		00:00.0
2021 PO4432712104	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4376612265	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5105484589	LGE	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO8192859217	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5105084599	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4986384761	LGE	4	30 BRO	SP	CRE	ED,ID,IP,RB	X	RP1	00:00.0
2021 PO7530882880	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4379012374	KU	3	45 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4379112270	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4382612364	KU	4	40 XXX	SP	CRE	ID,IP	TD		00:00.0
2021 PO4400012230	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4413612219	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4413712577	KU	5	35 XXX	SP	CCA		V		00:00.0
2021 PO4428012630	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4412812754	KU	6	30 XXX	SP	CRE	ED,ID	X	RP3	00:00.0
2021 PO4444385754	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4876610402	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6153751797	KU	4	40 OTH	SP	CRE	ID	BD		00:00.0
2021 PO6162451730	KU	5	35 OTH	SP	CRE	ID	BD		00:00.0
2021 PO4313613661	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4314513703	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4319513852	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4825111312	F	3	55 XXX	SP	S		V		00:00.0
2021 PO4843511243	F	3	55 XXX	SP	S		V		00:00.0
2021 PO4849711245	F	3	55 XXX	SP	S		V		00:00.0
2021 PO4851711209	F	4	40 XXX	SP	S		V		00:00.0
2021 PO4872211104	F	3	45 XXX	SP	S		V		00:00.0
2021 PO4887611208	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4882811225	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4882811225A	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO4902611488	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6276051529	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5179484681	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO6279251359A	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO6279251359	KU	2	55 BRN	SP	CRE	ID	BD		00:00.0
2021 PO6272951244	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO7418982186	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7417081982	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7415381783	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4993384675	LGE	3	50 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021 PO5180484663	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO7413281526	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5187584668	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO6269651180	KU	3	50 OTH	SP	CRE	ID	BD		00:00.0
2021 PO6264651206	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO6337849834	KU	4	40 OTH	SP	CRE	ID	BD		00:00.0

2021	PO6346749785	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021	PO5478706912	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5471006948	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5460506990	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5450007030	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5451307062	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5453007107	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5456707203	F	4	40 XXX	SP	S		V	00:00.0
2021	PO5459007265	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5463407379	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5467107475	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5470807574	F	4	40 XXX	SP	S		V	00:00.0
2021	PO6353849746	KU	2	45 OTH	SP	CRE	ID	BD	00:00.0
2021	PO6299850858	KU	4	40 OTH	SP	CRE		V	00:00.0
2021	PO5525908060	F	4	40 XXX	SP	S		V	00:00.0
2021	PO6079852592	F	4	40 OTH	SP	A		B	00:00.0
2021	PO5703407395	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5717507341	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5717507341A	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5723707267	F	4	45 XXX	SP	P		V	00:00.0
2021	PO5743507143	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5743507208	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5758507072	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5771107046	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5785807036	F	4	45 XXX	SP	S		V	00:00.0
2021	PO5804807031	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5823807043	F	4	45 XXX	SP	S		V	00:00.0
2021	PO5839507107	F	5	30 XXX	SP	S		V	00:00.0
2021	PO5840007061	F	4	40 XXX	SP	S		V	00:00.0
2021	PO5858107069	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5840007061A	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO6251850856	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO4442085728	LGE	3	50 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4445285751	LGE	1	70 BRO	SP	P		V	00:00.0
2021	PO4445285754	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4445485764	LGE	3	50 BRO	SP	CCA	ED,ID	BD	00:00.0
2021	PO6247250881	KU	2	50 OTH	SP	CRE	ID	BD	00:00.0
2021	PO6241450924	KU	4	45 OTH	SP	CRE	ID	BD	00:00.0
2021	PO6228351022	KU	4	45 OTH	SP	CRE	ID,IP	BD	00:00.0
2021	PO6234450976	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021	PO4499015626	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021	PO5887696560	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5907396534	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5907096620	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4409386179	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4457085486	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4456185500	LGE	UNK	65 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4457885474	LGE	UNK	65 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4450285623	LGE	UNK	70 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4449285640	LGE	UNK	70 ACE	SP	P	ED	BD	00:00.0
2021	PO4448685650	LGE	UNK	65 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4547011752	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4554711931	KU	4	45 XXX	SP	CRE	EP,ID	BD	00:00.0
2021	PO4587411380	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0

2021	PO8789292605	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4464685777	LGE	UNK	55 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO0036791343	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5916499879	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4453285505	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO0075090440	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO0005190903	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4454885624	LGE	3	50 ACE	SP	A	ED	BD	00:00.0
2021	PO4397685274	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO2346289195	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4265086606	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO0899162746	LGE	4	35 ACE	SP	A		V	00:00.0
2021	PO0884162745	LGE	4	35 ACE	SP	A		V	00:00.0
2021	PO0869162745	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021	PO3938215850	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4457685562	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4457485548	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO9441195588	KU	5	35 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO9439295887	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO4456985776	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021	PO9874491807	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4455785517	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO9474595577	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO4495285740	LGE	UNK	45 ACE	SP	A	ED	BD	00:00.0
2021	PO4498285762	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO9056790181	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO8037311050	KU	3	45 BRN	SP	CCA		B	00:00.0
2021	PO8041710846	KU	3	45 BRN	SP	CCA		B	00:00.0
2021	PO8032810889	KU	6	30 BRN	SP	CCA		B	00:00.0
2021	PO8093309611	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021	PO8108509757	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021	PO8121409874	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021	PO5699200494	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5689700556	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO8150110136	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021	PO9778796159	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5662400733	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO6003298252	KU	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4387485098	LGE	UNK	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4387085094	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4387285100	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4388085108	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4412386019	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4388085123	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4388285211	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4413386014	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO9649196714	KU	2	50 UNK	SP	CCA	ID	BD	00:00.0
2021	PO4378484748	LGE	4	40 ACE	DF	CRE	ED,ID	BD	00:00.0
2021	PO4378484760	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4378984759	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4378484772	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4379184833	LGE	4	30 ACE	SP	S	ED,ID	BD	00:00.0
2021	PO4442585731	LGE	3	50 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO9716396686	KU	2	45 UNK	SP	CRE	ID	BD	00:00.0

2021 PO4440685718	LGE	3	50 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4440885709	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4379385038	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4379285018	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4379285027	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4379385047	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4421286041	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO9307701479	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO6009598897	KU	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9309901032	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9310500812	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4387084924	LGE	4	40 ACE	SP	CRE	ED,ID,MD	BD	00:00.0
2021 4392185207-A	LGE	3	25 ACE	SP	A	ED	BD	00:00.0
2021 PO5750400921	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5771900803	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5785100731	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4387084946	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4387084949	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4412585977	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO5755699793	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4373185162	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4420585942	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO9316997405	KU	1	70 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5472502357	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5379602859	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8176510440	KU	2	50 BRN	SP	CRE	ED	BD	00:00.0
2021 PO9795595740	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4386684819	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5649300819	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5646101184	KU	5	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO9313600093	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8130210582	KU	2	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4387585077	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8150210748	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO5996598660	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4422486091	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO2947621199	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8096511305	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4382185164	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9317798443	KU	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO9342698103	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4388385223	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4439285708	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO2668521780	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO9701095950	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4382884899	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9676595014	KU	3	45 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO9684495025	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4418085634	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4419285642	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4388085133	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4392085207	LGE	4	30 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4363285028	LGE	2	55 ACE	SP	A	ED	BD	00:00.0
2021 PO4363285025	LGE	2	50 ACE	SP	A	ED	BD	00:00.0

2021 PO4343284881	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0630061435	LGE	4	35 ACE	SP	A	ED	BD	00:00.0
2021 PO4343884894	LGE	3	55 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4344384906	LGE	3	55 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4379484857	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4386785108	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8089511456	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO3179317417	KU	2	65 BRN	SP	CRE	ID	BD	00:00.0
2021 PO3297117116	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4379184808	LGE	4	30 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4379184820	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO5856599520a	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9654094975	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9647094965	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8285710325	KU	1	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO9821594766	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5795400072	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4386984899	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4388585133	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4388485145	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4388185145	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4388185157	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4388185165	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4290113780	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4388285181	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4388285206	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4388285194	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO7937405296	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7948705348	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7934105249	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7957805390	KU	2	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO2525721046	KU	6	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO2532622177	KU	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO5706699379	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9646097412	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9646997494	KU	2	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5334603064	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4372785166	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4371985175	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4503187718	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9748096467	KU	3	45 KOP	SP	CRE	ID	BD	00:00.0
2021 PO4527687903	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4528787885	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9558396293	KU	3	45 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO3328316304	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO9641796499	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4502487793	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4502987784	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4503287780	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9343996043	KU	4	40 UNK	SP	P	ID	BD	00:00.0
2021 PO4503587719	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4505887733	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4504687726	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4505987737	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0

2021	PO4500387826	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4500887818	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0
2021	PO4501487808	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4501987801	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8126011650	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021	PO8110611623	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021	PO8122211895	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021	PO4499487780	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4498787790	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4498387797	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4497787805	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4429585643	LGE	5	25 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4485487922	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO9339897104	KU	2	50 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4495787835	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4494987845	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4497187814	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4493687865	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0
2021	PO4493087875	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8135112232	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021	PO4491787895	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO3399517292	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4490587913	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4489687926	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4488887922	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4486787922	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4485587915	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4484087923	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4420585805	LGE	2H	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4423685444	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4427885424	LGE	4	35 BRO	SP	A	ED,ID	BD	00:00.0
2021	PO4379385066	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4422786109	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4439885686	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4430785672	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4379084969	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4379184978	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8168810528	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021	PO4425086135	LGE	3	50 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO2505618633	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4382784859	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO9734897172	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO9802394912	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021	PO8140010664	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021	PO4378984946	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO2504622493	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4437985698	LGE	3	50 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO9433600335	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4439185698	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021	PO4439985707	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO2602821902	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021	PO9643897200	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO4389985220	LGE	UNK	55 ACE	SP	CRE	ED	BD	00:00.0
2021	PO8590803685	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0



2021	PO8561703717	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO4383184847	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4382784847	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO5784499806	KU	4	30 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4379284846	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO5901401974	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5899401990	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5897202007	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5895002034	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO2519721393	F	4	40 BRN	SP	CRE		BD		00:00.0
2021	PO4437185686	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO8259211163	KU	3	45 BRN	SP	CRE	ED	BD		00:00.0
2021	PO4390585200	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO5678001325	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5699901201	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5720601087	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5731501026	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO9719095675	KU	3	45 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO8559703229	KU	4	45 UNK	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021	PO4439485704	LGE	4	30 BRO	SP	CCA	ED,ID,RB	BX	RP1	00:00.0
2021	PO9710095511	KU	2	50 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO5818899546	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO9700997188	KU	3	40 XXX	SP	CRE	ED,HH,ID,IP	BX	RP3	00:00.0
2021	PO4379084961	LGE	4	40 ACE	SP	CRE	ED,HH,ID	BX	RR	00:00.0
2021	PO9307201694	KU	4	40 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO4379585129	LGE	4	40 ACE	SP	CRE	ED,ID	BX	RR	00:00.0
2021	PO4492387885	LGE	3	45 ACE	SP	CRE	ED,ID	BX	RR	00:00.0
2021	PO9339397835	KU	5	35 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO9346295492	KU	4	40 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO9577396302	KU	4	40 UNK	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO5488202398	KU	5	35 ACE	SP	CRE	ED,EP,ID,MD,RB	BX	RP1	00:00.0
2021	PO5445002480	KU	5	35 ACE	SP	CRE	ED,EP,ID,MD	BX	RP1	00:00.0
2021	PO5872298841	F	4	45 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO5859098695	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO5863498675	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO9745395492	KU	4	40 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO9833395664	KU	3	45 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO5758100218	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	9307701479A	KU	4	40 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO5787299393	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO2757619047	KU	2	60 BRN	SP	CRE	RB	BX	RP1	00:00.0
2021	PO2924319068	KU	4	40 BRN	SP	CRE	ID,RB	BX	RP1	00:00.0
2021	PO8259009601	KU	4	40 BRN	SP	CCA	ED,SRS	T		00:00.0
2021	PO9678597324	KU	6	30 XXX	SP	S	ED	T		00:00.0
2021	PO8099711380	KU	3	45 BRN	SP	CCA	ED	T		00:00.0
2021	PO3150417631	KU	5	35 BRN	SP	CCA	ED	T		00:00.0
2021	PO7922106023	KU	2	45 BRN	SP	CRE	ED	T		00:00.0
2021	PO7936405874	KU	2	45 BRN	SP	CCA	ED	T		00:00.0
2021	PO9684497197	KU	6	30 XXX	SP	S	ED	T		00:00.0
2021	PO9681397564	KU	6	30 XXX	SP	S	ED	T		00:00.0
2021	PO9734897172B	KU	5	35 XXX	SP	S	ED	T		00:00.0
2021		4360185627	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4525287766	F	4	40 BRO	SP	P		V		00:00.0
2021	PO5080984947	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0

2021 PO4526487773	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4525287729	F	4	40 BRO	SP	P		V		00:00.0
2021 PO5081584901	LGE	4	35 ACE	SP	P	ED,HH,ID,RB	TX	RR	00:00.0
2021 PO4531587807	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4531087816	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4530887824	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4530787788	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4531387786	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4529387785	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4529587778	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO5079984880	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5079984907	LGE	4	40 ACE	SP	P	ID	BD		00:00.0
2021 PO4924985083	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO0147129126	KU	2	50 ACE	SP	CCA		V		00:00.0
2021 PO0176129008	KU	2	50 ACE	SP	CCA		V		00:00.0
2021 PO4924185120	LGE	4	30 BRO	SP	CRE	ED,ID,RB	X	RP1	00:00.0
2021 PO0007931216	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO0018031141	KU	5	35 ACE	SP	CRE		V		00:00.0
2021 PO4361785715	LGE	4	30 ACE	SP	CCA	ED	TD		00:00.0
2021 PO4361185709	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4360385704	F	4	35 ACE	SP	P		V		00:00.0
2021 PO4359985701	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4357985693	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4358185688	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4357785610	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4356885625	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4354385666	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4354585677	LGE	4	30 ACE	SP	P	ED	BD		00:00.0
2021 PO4355085671	LGE	3	50 ACE	SP	CCA	ED	V		00:00.0
2021 PO0072030458	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO0068030442	KU	6	30 ACE	SP	CCA		V		00:00.0
2021 PO0079030282	KU	1	55 ACE	SP	CCA		V		00:00.0
2021 PO0078730254	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO0078430220	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO0097330090	KU	1	40 ACE	SP	CCA		V		00:00.0
2021 PO0093130203	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO0087230353	KU	2	50 ACE	SP	CCA		V		00:00.0
2021 PO0081030517	KU	3	50 ACE	SP	CCA		V		00:00.0
2021 PO4530587857	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4530287861	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4535987748	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO0075430670	KU	1	40 ACE	SP	CCA		V		00:00.0
2021 PO0115430888	KU	2	45 ACE	SP	CCA		V		00:00.0
2021 PO0111930981	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO0130030838	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO0130530782	KU	1	40 ACE	SP	CCA		V		00:00.0
2021 PO0141730680	KU	2	45 ACE	SP	CCA		V		00:00.0
2021 PO0146030703	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO0154230558	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO0149230542	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO0135530487	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO0157030398	KU	2	55 ACE	SP	CCA		V		00:00.0
2021 PO0162630406	KU	2	55 ACE	SP	CCA		V		00:00.0
2021 PO0163830282	KU	3	45 ACE	SP	CCA		V		00:00.0

2021	PO0168230313	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021	PO6173066291	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO5078484775	LGE	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO5080584936	LGE	3	55 ACE	SP	P		V	00:00.0	
2021	PO0189428746	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO0168128804	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021	PO0151728849	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021	PO0129128907	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO0217928216	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO0202528113	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO4928285072	F	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4928085059	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO5409709079	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO5403209262	KU	5	35 XXX	SP	CCA		V	00:00.0	
2021	PO5412309217	F	5	35 XXX	SP	CRE		V	00:00.0	
2021	PO5412209160	F	4	40 XXX	SP	CCA		V	00:00.0	
2021	PO5420509131	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO5432709162	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0	
2021	PO4523887758	F	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4523787753	F	4	40 BRO	SP	P		V	00:00.0	
2021	PO4524387743	F	4	40 BRO	SP	P		V	00:00.0	
2021	PO4522887768	F	4	40 BRO	SP	P		V	00:00.0	
2021	PO4522687779	F	5	30 BRO	SP	P		V	00:00.0	
2021	PO5081584959	LGE	3	45 ACE	SP	P	ED	BD	00:00.0	
2021	PO5080484961	LGE	4	30 ACE	SP	P	ED	BD	00:00.0	
2021	PO4917184914	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4931384871	LGE	4	40 BRO	SP	A		V	00:00.0	
2021	PO4929484888	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021	PO5082284986	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO0025431084	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO0032931029	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021	PO0039430981	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO0046030935	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021	PO4521387980	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021	PO5470808933	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO5468108879	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO7981705406A	KU	3	40 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO0056230789	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO0042630777	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO0037530776	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO0032130773	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO0052130986	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO8089806084	KU	3	45 XXX	SP	S	ED,SRC	T	00:00.0	
2021	PO8101106008	KU	3	45 XXX	SP	S	ED,SRC	T	00:00.0	
2021	PO8109506057	KU	4	40 XXX	SP	CRE	ED,ID,IP,SRC	TD	00:00.0	
2021	PO8117106099	KU	3	45 XXX	SP	S	ED,SRC	T	00:00.0	
2021	PO8122906133	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7971805277	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,RB,SRC	TX	RR	00:00.0
2021	PO9936531012	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021	PO9948231094	KU	2	35 ACE	SP	CCA		V	00:00.0	
2021	PO9958831175	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO9970131178	KU	2	50 ACE	SP	CCA		V	00:00.0	
2021	PO9996731074	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO0020430981	KU	4	40 ACE	SP	CCA		V	00:00.0	

2021 PO9974931461	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO9999031283	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO0007931216a	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO0079930851	KU	3	40 ACE	SP	CCA		V		00:00.0
2021 PO0084231012	KU	3	40 ACE	SP	CCA		V		00:00.0
2021 PO0080231069	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO5476108595	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5466708638	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5458408675	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5454208586	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5449108480	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5395708642	F	4	40 XXX	SP	CRE	IP	BD		00:00.0
2021 PO5382008697	F	6	30 XXX	SP	CRE		V		00:00.0
2021 PO5383408722	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5386908872	KU	4	35 XXX	SP	CCA		V		00:00.0
2021 PO5394608847	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5399208750	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO5401208814	F	3	45 XXX	SP	P		V		00:00.0
2021 PO5402608856	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5403508883	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5422108981	KU	6	30 XXX	SP	CRE		BD		00:00.0
2021 PO5390708998	KU	6	35 XXX	SP	CRE	HH,ID	X	RP3	00:00.0
2021 PO5084185043	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO0093731113	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO0100130950	KU	3	40 ACE	SP	CCA		V		00:00.0
2021 PO5082284966	LGE	5	35 ACE	SP	CCA		V		00:00.0
2021 PO5101184850	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021 PO5097884843	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO5097884829	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO4536887733	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO5081784842	LGE	3	45 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO2464989638	LGE	4	30 BRO	SP	CRE		V		00:00.0
2021 PO4537387716	LGE	4	30 BRO	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4540387737	LGE	3	50 BRO	SP	P		V		00:00.0
2021 PO4549187729	LGE	3	50 BRO	SP	P		V		00:00.0
2021 PO4537687719	LGE	3	50 BRO	SP	CRE		V		00:00.0
2021 PO5079984795	F	4	40 ACE	SP	P		V		00:00.0
2021 PO5079984815	F	3	45 ACE	SP	P		V		00:00.0
2021 PO5079984832	F	3	45 ACE	SP	P		V		00:00.0
2021 PO0191429630	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO0252528955	KU	1	65 ACE	SP	CCA		V		00:00.0
2021 PO0252128968	KU	1	65 ACE	ST	CCA		V		00:00.0
2021 PO0211528312	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO0202828457	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO0193828600	KU	1	70 ACE	SP	CCA		V		00:00.0
2021 PO0194528619	KU	1	70 ACE	SP	CRE		V		00:00.0
2021 PO0195328639	KU	1	70 ACE	SP	CRE		V		00:00.0
2021 PO5078584846	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO5429309097	F	2	40 XXX	SP	CRE		V		00:00.0
2021 PO5430609066	KU	5	45 XXX	SP	CRE	ID,RB	TX	RR	00:00.0
2021 PO5428809010	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5428508817	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5425008887	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5418708781	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0

2021 PO5421408775	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5425308741	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO5421108581	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5412608469A	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO0294628937	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO0294628914	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO5443909039	KU	3	50 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4926685097	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4924585123	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4926985143	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4522787773	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4521687767	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4520587760	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4520087749	F	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4519887756	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4506587728	LGE	4	40 BRO	SP	P		B	00:00.0
2021 PO4361985640	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4925485112	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4925985096	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO0072830792	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4535887905	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4525987903	LGE	5	25 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4537987866	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO5088585085	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO5090485066	LGE	4	40 ACE	SP	P		V	00:00.0
2021 PO5087785090	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021 PO5085785058	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO5463808789	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5476308821	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5479508747	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO0041230536	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0064430560	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO0068430564	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO0069630518	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5079284858	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO0077329369	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO0073129219	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO0072629180	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO0074229110	KU	2	35 ACE	SP	CCA		V	00:00.0
2021 PO0103329009a	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO0082029126	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO0103329009	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO0118228841	KU	1	65 ACE	ST	CCA		V	00:00.0
2021 PO4902285089	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4901385081	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4532487793	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0078928373	KU	2	45 ACE	SP	CCA		V	00:00.0
2021 PO0076928373	KU	2	45 ACE	SP	CCA		V	00:00.0
2021 PO0075428373	KU	2	45 ACE	SP	CCA		V	00:00.0
2021 PO0088928101	KU	1	40 ACE	SP	CCA		V	00:00.0
2021 PO0089027904	KU	1	40 ACE	SP	CCA		V	00:00.0
2021 PO0136928760	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO0149528757	KU	4	35 ACE	SP	CCA		V	00:00.0
2021 PO0160628684	KU	4	40 ACE	SP	CCA		V	00:00.0

2021	PO0160228757	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO0178928756	KU	2	35 ACE	SP	CCA		V	00:00.0	
2021	PO5419608906	F	5	35 XXX	SP	CCA		V	00:00.0	
2021	PO5413608926	F	5	35 XXX	SP	CRE		V	00:00.0	
2021	PO5408508945	KU	6	30 XXX	SP	CRE	ID	BD	00:00.0	
2021	PO5405208936	F	4	40 XXX	SP	CRE	ID	V	00:00.0	
2021	PO5407709017A	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0	
2021	PO5407709017	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO5432808953	F	5	35 XXX	SP	CRE		V	00:00.0	
2021	5079984907-a	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0	
2021	PO0296528860	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO0291928860	KU	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO0268728443	KU	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO0270028427	KU	4	40 ACE	SP	CRE		V	00:00.0	
2021	PO0244328254	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021	PO0227528040	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021	PO0276028210	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021	PO0257928167	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021	PO9916930790	KU	5	35 ACE	LAM	CCA		V	00:00.0	
2021	PO4918184921	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO8019805892	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7981705406	KU	1	60 XXX	SP	S		V	00:00.0	
2021	PO7990905368	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO8009205367	KU	6	30 XXX	SP	CRE	ED,ID,IP,SRC	TD	00:00.0	
2021	PO8015205364	KU	6	30 XXX	SP	CRE	ED,ID,IP,SRC	TD	00:00.0	
2021	PO8012305417	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO8016705513	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO8066805590	KU	7	25 XXX	ST	CRE		V	00:00.0	
2021	PO8057205751	KU	3	45 XXX	SP	S	ED,SRC	T	00:00.0	
2021	PO8073705919	KU	3	45 XXX	SP	CRE	ED,SRC	T	00:00.0	
2021	PO4511287797	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO8454564094	F	1	50 ACE	SP	CCA		V	00:00.0	
2021	PO4881884716	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0	
2021	PO8066104590	KU	1	55 XXX	SP	S		V	00:00.0	
2021	PO4447185964	LGE	4	40 BRO	SP	A	ED,ID,IP	BD	00:00.0	
2021	PO4448085962	F	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4864286028	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0	
2021	PO4863386039	LGE	3	45 ACE	SP	A	ED,IP	TD	00:00.0	
2021	PO5430107700	F	4	40 OTH	SP	P		V	00:00.0	
2021	PO5425207572	F	4	40 OTH	SP	P		V	00:00.0	
2021	PO5422407506	F	3	45 OTH	SP	CCA		V	00:00.0	
2021	PO5426107476	F	6E	30E	UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5419607434	F	3	45 OTH	SP	CCA		V	00:00.0	
2021	PO5392306836	F	4	40 KOP	SP	P		V	00:00.0	
2021	PO5400206965	F	4	40 KOP	SP	P		V	00:00.0	
2021	PO5396006766	KU	4	40 KOP	SP	CCA		V	00:00.0	
2021	PO5404006701	F	4	40 UNK	SP	CRE		V	00:00.0	
2021	PO5408306706	F	6E	30E	UNK	SP	CRE		V	00:00.0
2021	PO5396306562A	KU	5	35 KOP	SP	P		V	00:00.0	
2021	PO5396306562	F	4	35 KOP	SP	P		V	00:00.0	
2021	PO7795285931	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO7861285649	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021	PO7889585542	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO7937285437	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	

2021	PO5127484826	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO5128484821	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4994584828	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO3817617521	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4864786043	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4864286048	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO5001884714	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4994984775	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO5928655342	F	4	45 KOP	SP	P		V	00:00.0
2021	PO5967555480	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5065785407	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5062885414	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021	PO5063585421	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO1855670645	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO7823688771	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7797088756	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4450885913	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4452285912	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5002384629	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4453285910	LGE	4	35 BRO	SP	A	ED,ID,IP	BD	00:00.0
2021	PO4453885904	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4453785890	LGE	4	35 BRO	SP	P	ED,EP,ID,IP	BD	00:00.0
2021	PO4552687956	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021	PO5002284601	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4863886033	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4863186021	F	4	30 ACE	SP	P		V	00:00.0
2021	PO4862386024	F	4	40 ACE	SP	P		V	00:00.0
2021	PO5751573036	F	1	60 ACE	SP	CCA		V	00:00.0
2021	PO5002884598	LGE	5	25 BRO	SP	CRE	ED,HH,ID,IP	X	RP1 00:00.0
2021	PO5925555584	KU	4	40 OTH	SP	CRE		V	00:00.0
2021	PO5916355474	F	4	45 OTH	SP	CRE		V	00:00.0
2021	PO5905955582	F	4	40 KOP	SP	A		V	00:00.0
2021	PO5903355771	F	4	40 KOP	SP	P		V	00:00.0
2021	PO5899955934	F	4	40 KOP	SP	P		V	00:00.0
2021	PO5065385433	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5071985358	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO5901356146	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021	PO5067885380	LGE	4	40 ACE	SP	CRE	ED,ID,RB	BD	00:00.0
2021	PO3727118099	KU	1	80 XXX	SP	CRE		V	00:00.0
2021	PO3754817910	KU	2	50 XXX	SP	S		V	00:00.0
2021	PO3793717655	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO3767517825	KU	3	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO3717218180	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4702812086	KU	5	35 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4867286051	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4866786065	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PO4866286066A	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PO4866286066	F	4	30 ACE	SP	A		V	00:00.0
2021	PO5751573377	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO5731573486	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5345407404	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5342807339	F	4	45 UNK	SP	CRE		V	00:00.0
2021	PO5339907279	F	4	45 KOP	SP	P		V	00:00.0
2021	PO5336807208	F	4	45 KOP	SP	P		V	00:00.0

2021	PO5347007284	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5354407254	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5368807278	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5381907338	F	4	40 UNK	DF	CRE		V	00:00.0
2021	PO5372307378	F	5E	40 UNK	SP	CRE		V	00:00.0
2021	PO5365407405	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5358007434	F	4E	40E UNK	SP	CRE		V	00:00.0
2021	PO5307507630	F	4	35 UNK	SP	P		V	00:00.0
2021	PO5300807583	F	4	35 UNK	SP	P		V	00:00.0
2021	PO5289707563	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO5007484809	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5878256825	KU	5	35 OTH	SP	CCA		V	00:00.0
2021	PO4555088002	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5066285294	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO7777781679	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO7788781784	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO7797781773	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO7802681915	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO7817681962	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7816482053	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO1322562122	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO1689973547	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO5127085023	LGE	3	45 ACE	SP	P	ED	TD	00:00.0
2021	PO7803482841	KU	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO7807282834	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO7816582676	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4842885913	F	5	35E ACE	SP	CRE	ED	V	00:00.0
2021	PO4977985178	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4975385168	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4972685155	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4843585903	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021	PO4842585906	LGE	1	65 ACE	SP	P		V	00:00.0
2021	PO6241151361	KU	1	30 OTH	ST	CCA		V	00:00.0
2021	PO6234151415	KU	1	30 OTH	ST	CCA		V	00:00.0
2021	PO6228451457	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021	PO6235751460	KU	4	40 OTH	SP	CRE	ID,IP,MD	BD	00:00.0
2021	PO6216951597	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO6224451542	KU	1	30 OTH	ST	CCA		V	00:00.0
2021	PO4973085145	F	4	30 BRO	SP	A		V	00:00.0
2021	PO4985085077	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD	00:00.0
2021	PO1347861959	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO1284362203	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO7820082618	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO7830782439	KU	3	40 ACE	SP	CCA		V	00:00.0
2021	PO7844582204	KU	2	50 ACE	SP	CCA		V	00:00.0
2021	PO7858381975a	KU	1	50 ACE	SP	CCA		V	00:00.0
2021	PO7858381975	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4469910189	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4465510137	F	4	40 XXX	SP	CRE	ED,HH,ID	BX PX	00:00.0
2021	PO4460210014	F	3	45 XXX	SP	S		V	00:00.0
2021	PO4454809886	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4449209756	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4444009634	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4437709588	F	4	40 XXX	SP	CRE		V	00:00.0



2021 PO4449685960	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4447385909	LGE	2	50 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4447185898	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4446585899	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4446285900	LGE	3	45 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5127484991	LGE	3	45 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO5127484978	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4987685074	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO1278762585	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO5446605891	F	4	40 UNK	SP	CCA		V		00:00.0
2021 PO5440805745	F	4	40 UNK	SP	P		V		00:00.0
2021 PO5437305661	F	4E	40E UNK	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO4856985990A	F	4	25E ACE	SP	P		V		00:00.0
2021 PO4856985990	F	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4855485981	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4853685985	F	4	35 ACE	SP	P		V		00:00.0
2021 PO4852085975A	F	4	30E ACE	SP	P		V		00:00.0
2021 PO4852085975	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4852485955	LGE	4	40 ACE	SP	P	ED	TD		00:00.0
2021 PO4850185976	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4850685948	LGE	4	40 ACE	SP	P	ED	TD		00:00.0
2021 PO9147154347	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO9129154357	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO8473863789	F	1	50 ACE	SP	CCA		V		00:00.0
2021 PO5130985015	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4847085965	F	3	45 ACE	SP	P		V		00:00.0
2021 PO4848385966A	F	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4848385966	F	3	50 ACE	SP	CCA		V		00:00.0
2021 PO7703094528	KU	4	40 ACE	SP	CRE		V		00:00.0
2021 PO5129085006	LGE	3	45 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4847885946	LGE	3	45 ACE	SP	P		VX	RP3	00:00.0
2021 PO4848485929	LGE	4	40 ACE	SP	P	ED	TD		00:00.0
2021 PO7846281153	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PV5125885052	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO6254851265	KU	1	30 OTH	ST	CCA		V		00:00.0
2021 PO6247551313	KU	1	30 OTH	ST	CCA		V		00:00.0
2021 PO6244251339	KU	4	40 OTH	SP	CRE	ID	BD		00:00.0
2021 PO6240151427	KU	4	40 OTH	SP	CCA		V		00:00.0
2021 PO4842285924	LGE	2	55 ACE	SP	CRE	ED,ID	BX	RR	00:00.0
2021 PO4434110062	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4428709929	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4422809785	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4416909632	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4411709313	KU	6	30 XXX	SP	S		V		00:00.0
2021 PO4414409490	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4414709404	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO1667172969	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO1675573169	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO1679373261	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO5125385030	LGE	3	50 ACE	SP	P	ED	BD		00:00.0
2021 PO5125385025	LGE	3	50 ACE	SP	P	ED	BD		00:00.0
2021 PO7781681622	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO7786281665	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4980585108	F	4	40 BRO	SP	CRE		V		00:00.0

2021 PO4979785104	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO4978485099	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5126084967	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO6209251597	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO6211951635	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO6199951668	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO6191351735	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO6183651798	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO6193251779	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0	
2021 PO6202751704	KU	1	30 OTH	ST	CCA		V	00:00.0	
2021 PO6202951744	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0	
2021 PO4655713773	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO4458613484	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4454213348	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4450013234	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO4694311194	KU	6	30 XXX	SP	CCA		V	00:00.0	
2021 PO4717311236	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO4701711014	F	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO4696410924	F	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO4687010974	F	5	35 XXX	SP	CRE		V	00:00.0	
2021 PO4689710804	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4683910696	KU	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO4677910599	KU	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO4672010503	KU	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO4666010407	F	3	40 XXX	SP	CCA		V	00:00.0	
2021 PO4659010293	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO4651810173	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4644710059	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO4845185960	F	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5586672554	LGE	5	30 ACE	SP	P	ED	BD	00:00.0	
2021 PO6102752244	F	4	40 OTH	SP	A		V	00:00.0	
2021 PO7798192911	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5119284921	LGE	3	45 ACE	SP	P	ED	BD	00:00.0	
2021 PO6112152110	F	4	40 KOP	SP	P		V	00:00.0	
2021 PO6124252018	F	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO6135651984	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0	
2021 PO7803992943	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7814892968	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7819192863	KU	6	30 ACE	SP	CCA		V	00:00.0	
2021 PO4842085986	LGE	2	50 ACE	SP	P	ED,IP	BD	00:00.0	
2021 PO4842385979	LGE	2	50 ACE	SP	CRE	ED,EP,ID	BX	RR	00:00.0
2021 PO4846785984	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4851685991	LGE	4	30 ACE	SP	P	ED,IP	TD	00:00.0	
2021 PO4850985983	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4851885984	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4853585988	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4855385987	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5706172997	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO5734572979	F	1	60 ACE	SP	CCA		V	00:00.0	
2021 PO5723172962	F	1	50 ACE	SP	CCA		V	00:00.0	
2021 PO5116784931	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO5364606697	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO5367906766	F	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO5373206873	F	4	40 BRN	SP	CCA		V	00:00.0	

2021	PO5383507095	F	4	40 BRN	SP	CCA			V	00:00.0
2021	PO5364107144	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO5361307064	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO5357606969	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO5338206300	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO5333106162	KU	4	40 KOP	SP	CCA			V	00:00.0
2021	PO5346906040	KU	3	45 KOP	SP	CCA			V	00:00.0
2021	PO5345105986	F	2	35 KOP	SP	P			V	00:00.0
2021	PO5338806009	KU	5	35 BRN	SP	CCA			V	00:00.0
2021	PO5337306015	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO5340006063	KU	3	45 BRN	SP	CCA			V	00:00.0
2021	PO5330606095	KU	3	45 UNK	SP	CCA			V	00:00.0
2021	PO5325906316	F	5E	35E UNK	SP	CRE	ED,ID,RB	BX	RP2	00:00.0
2021	PO5285006257	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO5296806214	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO4972185246	LGE	3	35 BRO	SP	CRE	ED,ID,IP		TD	00:00.0
2021	PO6130451933	F	4	40 KOP	SP	P			V	00:00.0
2021	PO0068199904	KU	4	40 XXX	SP	CRE	ID		BD	00:00.0
2021	PO0068599961	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO0001399522	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0
2021	PO4021784562	LGE	4	40 BRN	SP	CRE	ED,ID,IP		BD	00:00.0
2021	PO4010384124	F	4	35 ACE	SP	CCA			V	00:00.0
2021	PO4010484137	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO4010584144	F	4	40 ACE	SP	A	ED		V	00:00.0
2021	PO4010684154	F	4	40 ACE	SP	P	ED		V	00:00.0
2021	PO4011184166	LGE	4	35 ACE	SP	CCA	ED,ID		BD	00:00.0
2021	PO4020983062	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4035583182	F	4	25 BRO	SP	A			V	00:00.0
2021	PO4007583584	LGE	4	35 BRO	SP	CCA			V	00:00.0
2021	PO4010784165	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO4010884180	F	3	45 ACE	SP	P	ED		V	00:00.0
2021	PO4010984195	F	3	45 ACE	SP	CCA	ED		V	00:00.0
2021	PO4011084208	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO3999984129	F	4	30 ACE	SP	CRE	ED		V	00:00.0
2021	PO0210001054	KU	6	30 XXX	SP	CRE	ID		TD	00:00.0
2021	PO0219801018	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0
2021	PO0257101207A	KU	6	30 XXX	SP	CCA			V	00:00.0
2021	PO0272201033	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0
2021	PO0227701225	KU	6	30 XXX	SP	CCA			V	00:00.0
2021	PO0235301089	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0
2021	PO0257101207	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0
2021	PO0245401346	KU	6	30 XXX	SP	CCA			T	00:00.0
2021	PO0255701658	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0
2021	PO4001484127	F	UNK	25 ACE	SP	CRE	ED		V	00:00.0
2021	PO4005983595	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TD	00:00.0
2021	PO4006683579	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021	PO4008683580	F	4	40 BRO	SP	CRE			V	00:00.0
2021	PO4004884125	F	4	35 ACE	SP	P	ED		V	00:00.0
2021	PO4006084125	LGE	4	30 ACE	SP	CCA	ED		V	00:00.0
2021	PO4007484124	F	4	40 ACE	SP	A	ED		V	00:00.0
2021	PO3989584263	F	4	40 ACE	SP	CRE	ED		V	00:00.0
2021	PO3989484255	F	4	45 ACE	SP	A	ED		V	00:00.0
2021	PO3989684338	LGE	4	30 ACE	SP	CRE	ED,ID		TD	00:00.0
2021	PO4012784201	F	4	40 ACE	SP	CRE			V	00:00.0

2021	PO9962479669	KU	4	40 BRN	SP	CCA	ED,IP	BD	00:00.0
2021	PO9977879436	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO9949279908	KU	4	40 BRN	SP	CCA	ED,SRS	T	00:00.0
2021	PO9927380094	KU	4	45 BRN	SP	CRE	ED,SRS	BD	00:00.0
2021	PO9972679632	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO9962080057	KU	4	45 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO4012984118	LGE	UNK	25 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4001584654	F	7	25 BRN	SP	A		V	00:00.0
2021	PO4001984652	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4011884606	F	4	35 BRN	SP	A		V	00:00.0
2021	PO4021284546	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4029384305	F	1	50 BRN	SP	CCA		V	00:00.0
2021	PO4029384335	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021	PO4029684320	F	1	50 BRN	SP	CCA		V	00:00.0
2021	PO4029984333	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4030184341	F	1	55 BRN	SP	CCA		V	00:00.0
2021	PO4021684401	LGE	4	45 BRN	SP	A	ID	BD	00:00.0
2021	PO4025584363	F	4	45 BRN	SP	CRE		V	00:00.0
2021	PO4025784359	F	4	30 BRN	SP	CRE		V	00:00.0
2021	PO4026484362	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4028084358	F	3	45 BRN	SP	A		V	00:00.0
2021	PO4029184356	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4029784356	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4030584354	F	4	45 BRN	SP	A		V	00:00.0
2021	PO4030984371	F	3	50 BRN	SP	CCA		V	00:00.0
2021	PV4031184380	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PV4031684394	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PV4031984405	F	3	50 BRN	SP	CCA		V	00:00.0
2021	PO4032384416	F	4	45 BRN	SP	CCA		V	00:00.0
2021	PO7498956548	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4030884426	LGE	4	30 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4030484435	F	4	40 BRN	SP	P		V	00:00.0
2021	PO4030284448	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021	PO4028184450	F	4	30 BRN	SP	CRE		V	00:00.0
2021	PO4028084439	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021	PO4028184443	F	4	40 BRN	SP	A		V	00:00.0
2021	PO4029384439	F	4	40 BRN	SP	P		V	00:00.0
2021	PO4031284433	F	4	45 BRN	SP	A		V	00:00.0
2021	PO4032284425	LGE	4	40 BRN	SP	CRE	ED,EP,HH,ID	BX PX	00:00.0
2021	PO4032884431	F	3	45 BRN	SP	P		V	00:00.0
2021	PO4033184439	F	3	50 BRN	SP	CCA		V	00:00.0
2021	PO4033584453	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4034084466	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4008184267	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4008684279	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021	PO0091580123	KU	4	40 BRN	SP	A	ED,IP,SRS	TD	00:00.0
2021	PO9951178947	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO9975680402	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO7248755028	LGE	4	30 ACE	SP	CCA	ED	V	00:00.0
2021	PO4008884296	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021	PO4009084325	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4034883235	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4036383245	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO9040795053	KU	4	40 XXX	SP	CRE		V	00:00.0

2021 PO4037283272	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4038183258	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO7551547807	LGE	1	50 BRO	SP	CCA		V	00:00.0	
2021 PO4035583617	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4823835812A	KU	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO1859468241	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021 PO1890167974	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO1819967495	KU	4	40 BRN	SP	CRE	ED,IP,MD,SRS	TD	00:00.0	
2021 PO1805167196	KU	4	40 BRN	SP	CRE	ED,IP,MD,SRS	TD	00:00.0	
2021 PO9265601799	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO9269201746	KU	2	45 OTH	SP	CRE		B	00:00.0	
2021 PO9290401826	KU	4	45 BRN	SP	CRE		B	00:00.0	
2021 PO4018584110	LGE	UNK	50 ACE	SP	CCA		V	00:00.0	
2021 PO7337752902	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4017584110	LGE	3	50 ACE	SP	CCA	ED	V	00:00.0	
2021 PO7309153046	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4823835812	KU	2	45 BRO	SP	CCA		V	00:00.0	
2021 PO5763326371	KU	2	50 ACE	SP	CRE	ED,ID	BX	PX	00:00.0
2021 PO4503488036	LGE	4	35 BRN	SP	P	ID	TD	00:00.0	
2021 PO4504288023	LGE	4	35 BRN	SP	A	ID	TD	00:00.0	
2021 PO4035184499	F	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4035384505	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO4036084523	F	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4036184525	F	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4036784541	F	4	45 BRN	SP	P		V	00:00.0	
2021 PO4037184551	F	4	45 BRN	SP	CRE		V	00:00.0	
2021 PO4037884571	F	3	50 BRN	SP	CCA		V	00:00.0	
2021 PO4038884598	F	4	40 BRN	SP	P		V	00:00.0	
2021 PO4039084606	F	4	45 BRN	SP	CCA		V	00:00.0	
2021 PO4040384643	F	3	45 BRN	SP	A		V	00:00.0	
2021 PO4039684622	F	4	45 BRN	SP	A		V	00:00.0	
2021 PO4039484613	F	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4020284373	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4022183956	LGE	1	55 BRN	SP	CRE		V	00:00.0	
2021 PO3996384249	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO4001184089	LGE	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0	
2021 PO5858925212	KU	5	35 ACE	SP	CRE		B	00:00.0	
2021 PO5840924956	F	3	40 ACE	SP	CRE		V	00:00.0	
2021 PO5847525019	F	3	40 ACE	SP	CRE		V	00:00.0	
2021 PO5860725142	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO9920182014	KU	4	40 BRN	SP	CRE	ED,IP,MD,SRS	TD	00:00.0	
2021 PO3988084091	F	4	40 ACE	SP	CRE	ED	V	00:00.0	
2021 PO3988184102	F	4	40 ACE	SP	CRE	ED	V	00:00.0	
2021 PO3987884117	F	4	30 ACE	SP	CRE	ED	V	00:00.0	
2021 PO3988384115	F	4	40 ACE	SP	P	ED	V	00:00.0	
2021 PO4012183744	LGE	1	50 BRO	SP	CCA		V	00:00.0	
2021 PO4090684127	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4088484143	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4090084130	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4093184139	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4492487978	LGE	4	45 BRN	SP	A	ED,ID	BD	00:00.0	
2021 PO2037092368	LGE	1	55 BRN	SP	CCA		V	00:00.0	
2021 PO2039792382	LGE	1	55 BRN	SP	CCA		V	00:00.0	
2021 PO2050392444	LGE	2	55 BRN	SP	CCA		V	00:00.0	

2021 PO4495088005	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3987884081	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4501187969	LGE	4	45 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO5802026237	KU	5	35 ACE	SP	CRE		B	00:00.0
2021 PO5805326274	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5796426169	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3987884073	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3999783838	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4500787974	LGE	4	35 BRN	SP	A		BD	00:00.0
2021 PO4500187983	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BD	00:00.0
2021 PO4498987991	LGE	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4497488002	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4497988015	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO3987784062	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3987584050	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3987484037	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3987384028	F	3	45 ACE	SP	CRE	ED	V	00:00.0
2021 PO5782526165	KU	2	50 ACE	SP	CRE		B	00:00.0
2021 PO5786526148	KU	4	40 ACE	SP	CRE		B	00:00.0
2021 PO5789726088	KU	3	50 ACE	SP	CRE		B	00:00.0
2021 PO5794426042	KU	5	35 ACE	SP	CRE		B	00:00.0
2021 PO3999483830	F	4	30 BRO	SP	A		V	00:00.0
2021 PO3986784095	F	4	40 ACE	SP	CCA	ED	V	00:00.0
2021 PO3985484096	F	4	40 ACE	SP	CCA	ED	V	00:00.0
2021 PO3984284097	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4501788066	LGE	4	35 BRN	SP	A	ED,HH,ID	TD	00:00.0
2021 PO1193598650	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO3978484025	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3978984035	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4009283829	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4008983829	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4008083820	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO9987784131	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO9998983960	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO0011183728	KU	4	40 BRN	SP	CRE	ED,IP,SRC	TD	00:00.0
2021 PO9950683674	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO0012383404	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO3979484046	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3980084057	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4502388060	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO2109992925	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4502588050	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3980884064	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3981784067	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3982984067	F	4	40 ACE	SP	A	ED	V	00:00.0
2021 PO4065084304	F	4	30 BRO	SP	P		V	00:00.0
2021 PO4064084284-A	KU	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4064084284	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3986584065	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3985384066	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3984184066	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3990783838	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4022583961	LGE	1	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO9049795347	KU	4	40 XXX	SP	CRE	ID	V	00:00.0

2021 PO9741798501	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO9717198502	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO9705298722	KU	3	40 XXX	DF	CCA		V	00:00.0
2021 PO9717198502B	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9717198502A	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9666499638	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO0219801018A	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO9666999295C	KU	3	40 XXX	SP	CCA		V	00:00.0
2021 PO9666999295B	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO9717799348	KU	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9717699322	KU	3	50 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9666999295A	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO9683499439	KU	6	30 XXX	SP	CRE		V	00:00.0
2021 PO9666999295	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO9688199366	KU	4	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9688299322	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9688299322A	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO9687599184	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO9685798980	KU	3	45 XXX	SP	CRE	ID	X RP3	00:00.0
2021 PO9685898636	KU	4	50 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9643998978	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO9656298429	KU	3	40 XXX	SP	CCA		V	00:00.0
2021 PO5836224992	KU	4	40 ACE	SP	CRE		B	00:00.0
2021 PO9630497676	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9625997791	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO9624697976	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO9625698214	KU	3	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9590397978	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO0088699796	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO5843325060	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5849025117	KU	6	35 ACE	SP	CCA		V	00:00.0
2021 PO5865125185	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5776226333	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO4499388100	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4500088093	LGE	4	35 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4003483832	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4004783831	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9976783727	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO9995683736	KU	4	40 BRN	SP	CRE	ED,MD,SRS	BD	00:00.0
2021 PO3978283979	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3978583990	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3978284001	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO3978384013	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4005983831	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4006783830	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4007883830	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4501088078	LGE	4	40 BRN	DF	A		V	00:00.0
2021 PO4001183902	F	5	25 BRO	SP	CCA		V	00:00.0
2021 PO0833400183	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO0825600393	KU	5	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO0757900422	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3999483901	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3995284252	LGE	4	35 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO3998383906	F	3	45 BRO	SP	CCA		V	00:00.0

2021	PO2187522510	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2230420717	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2229920791	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2187822808	KU	4	45 BRN	SP	CRE	ED,ID	TD			00:00.0
2021	PO2188222355	KU	4	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021	PO2220621724	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2190322164	KU	6	30 BRN	SP	CRE	ED,ID	TD			00:00.0
2021	PO2190522114	KU	4	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021	PO2216322239	KU	3	40 BRN	SP	CRE	ED,ID	TD			00:00.0
2021	PO2249722458	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2351120459	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2945717207	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2272921162	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2904716594	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2923816877	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2781916496	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO2836916410	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO7548408424	KU	4	40 XXX	SP	CRE	ED,ID,IP	BX	RP2		00:00.0
2021	PO5504513980	F	4	40 UNK	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO5563713367	F	4	40 UNK	SP	CRE	HH,ID	BX	RP1		00:00.0
2021	PO6455319383	KU	4	40 BRN	SP	CRE	ED,HH,ID,IP,RB	BX	PX		00:00.0
2021	PO5443214040	F	4	40 UNK	SP	CRE	ED,ID,RB	BX	PX		00:00.0
2021	PO5446013603	F	5	40 UNK	SP	CRE	ED,ID,RB	BX	PX		00:00.0
2021	PO5476213857	F	3	40 UNK	SP	CRE	ED,ID	BX	PX		00:00.0
2021	PO5643613112	F	4	40 UNK	SP	P	HH,ID,RB	BX	PX		00:00.0
2021	PO5602312527	F	4	40 UNK	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO6423624135	F	4	40 UNK	SP	CRE	ED,ID,MD	BX	PX		00:00.0
2021	PO5456314220	F	4	40 BRO	SP	P	ED,HH,ID	BX	RP1		00:00.0
2021	PO5699312882	F	4	40 UNK	SP	CRE	ID	BX	PX		00:00.0
2021	PO5557013539	F	4	40 UNK	SP	CRE	HH,ID	BX	RP1		00:00.0
2021	PO5678213348	KU	4	40 UNK	SP	CRE	ED,ID,RB	BX	RP2		00:00.0
2021	PO6003118277	KU	3	45 UNK	SP	CRE	ED,HH,ID	BX	PX		00:00.0
2021	PO5469514165	F	4	40 UNK	SP	CRE	ED,ID	BX	RP3		00:00.0
2021	PO5574413612	F	4	40 UNK	SP	CRE	ED,ID,RB	BX	RP1		00:00.0
2021		4278186647	LGE	3	50 ACE	SP	CCA	V			00:00.0
2021	PO4534687856	LGE	4	30 ACE	SP	CRE	ED,ID	TD			00:00.0
2021	PO4539887904	LGE	4	30 ACE	SP	CRE	ED,ID,RB	TX	RR		00:00.0
2021	PO4523987908	LGE	4	30 ACE	SP	CRE	ED,ID	V			00:00.0
2021	PO4510887845	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021	PO4506387861	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021	PO4487987922	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021	PO4277986574	LGE	1	55 ACE	SP	CRE	ED,ID	BD			00:00.0
2021	PO4286686360	LGE	3	45 ACE	SP	A	ED,ID	BD			00:00.0
2021	PO4277786367	LGE	3	55 ACE	SP	CRE	ED,ID	BD			00:00.0
2021	PO5473011956	KU	4	40 UNK	SP	CRE	ED,ID,IP	BD			00:00.0
2021	PO5496708275	KU	6	30 BRN	SP	CRE	ED,ID	BD			00:00.0
2021	PO4502787878	LGE	4	30 ACE	SP	CRE		V			00:00.0
2021	PO56394123993A	KU	6	30 UNK	SP	CRE	ID	BD			00:00.0
2021	PO5872912547	KU	6	30 UNK	SP	CRE	ID	BD			00:00.0
2021	PO5690612278	KU	6	30 UNK	SP	CRE	ID	BD			00:00.0
2021	PO5283207844	KU	6	30 XXX	SP	CRE	ED,ID,MD	BD			00:00.0
2021	PO2219523077	KU	4	40 BRN	SP	CRE	RB	X	PX		00:00.0
2021	PO2249822263	KU	4	40 BRN	SP	CRE	ED,ID,RB	X	PX		00:00.0
2021	PO5249708030	KU	3	45 XXX	SP	CRE	ED,ID,IP,RB	BX	PX		00:00.0



2021 PO2229120908	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO2273921369	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO2250622680	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2221121581	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6222122793	KU	5	35 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO2223021644	KU	6	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5558307437	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO2255321010	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7520904742	KU	4	40 BRN	SP	CRE	ED	BD		00:00.0
2021 PO4513987703	LGE	3	45 ACE	SP	CRE		V		00:00.0
2021 PO7417207243	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5612612632	KU	6	30 UNK	SP	CRE	ID,IP	BD		00:00.0
2021 PO5747111791	KU	4	40 UNK	SP	CRE	ID,IP	BD		00:00.0
2021 PO2845516054	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2262220913	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2216122821	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO2234323055	KU	4	40 BRN	SP	CRE	RB	X	PX	00:00.0
2021 PO2247021295	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO2250021471	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO2250222590	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2275121532	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4533087842	LGE	4	30 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4543187908	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4508387770	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4518387873	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4540687910	LGE	4	30 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4541887909	LGE	4	40 ACE	SP	A	ED,ID	V		00:00.0
2021 PO5758711886	KU	4	40 UNK	SP	CRE	ID,IP	BD		00:00.0
2021 PO5836012609	KU	6	35 UNK	SP	CRE	ID,IP	BD		00:00.0
2021 PO5686813209	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5735711834	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO2249922364	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO6432324138	KU	5	35 UNK	SP	CRE	ED,ID,IP,MD	TD		00:00.0
2021 PO6107719356	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO5445712057	KU	4	40 UNK	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO6271419043	KU	3	45 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5420411973	KU	5	35 UNK	SP	CRE		BD		00:00.0
2021 PO5548212459	KU	6	30 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5439811901	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO4278586413	LGE	4	40 ACE	SP	CRE	ED,ID,RB	BX	RR	00:00.0
2021 PO5452611855	F	4	40 XXX	SP	CRE	ED,ID	V		00:00.0
2021 PO6797124206	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO7325705503	F	2	55 BRN	SP	CRE	ED,EP,HH,ID,IP	BX	PX	00:00.0
2021 PO4406885898	LGE	2	60 BRO	SP	A	ED,EP,ID,IP,RB	VX	RP1	00:00.0
2021 PO4440206938	KU	2	55 KOP	SP	CRE	ID,IP	TX	RR	00:00.0
2021 PO5662311645	F	4	40 BRO	SP	P	ED	V		00:00.0
2021 PO5660713031	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4513687831	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO6325523678	KU	4	40 UNK	SP	P	ED,ID,IP	TD		00:00.0
2021 PO6093018571	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6221522932	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO6389523916	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO6058918830	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021 PO5470913262	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0

2021 PO4295986624	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4294086614	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4279286576	LGE	4	25 ACE	SP	CRE	HH,ID	TD		00:00.0
2021 PO4277886582	LGE	2	55 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4279186380	LGE	4	30 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4289886596	LGE	4	40 ACE	SP	CCA	ED,ID	TD		00:00.0
2021 PO4289986591	LGE	1	55 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4277786521	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4553287936	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4542787921	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5523413165	F	4	40 BRO	SP	P	ED,ID,RB	BX	PX	00:00.0
2021 PO4542387919	LGE	4	30 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4541087903	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4540287898	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4505387817	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4506187804	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4504987822	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4503987845	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4505987800	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4505187853	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4489287932	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4510787835	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4506887865	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4506687868	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4278086575	LGE	3	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4277786598	LGE	1	65 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4280386575	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4280286323	LGE	3	45 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4506787858	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4284086343	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4283286327	LGE	3	50 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4507487848	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4283786370	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4278986320	LGE	3	50 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4283986358	LGE	3	45 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4278986298	LGE	3	50 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO9845679075	LGE	2	60 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4278886300	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4277886500	LGE	2	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4276186695	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4539687886	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4542387906	LGE	4	30 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4541287898	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4540587892	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4519887878	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4529787869	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4516487897	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4503887841	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4533787850	LGE	4	35 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4532387854	LGE	4	30 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4517787864	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4512087786	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4541387916	LGE	4	25 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5461807467	F	3	45 BRN	SP	CRE	EP,HH,ID,IP,MD	BX	RP1	00:00.0

2021	PO4278386485	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5257207276	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO5460811095A	KU	6	30 XXX	SP	CRE	ED,HH,ID	TD	00:00.0
2021	PO5460811095	KU	6	30 XXX	SP	CRE	ED,HH,ID	TD	00:00.0
2021	PO6001718655	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021	PO4669711944	KU	4	40 KOP	SP	CRE	ID,IP	X	RP2 00:00.0
2021	PO5525810900	KU	5	35 KOP	SP	CRE	ID	BD	00:00.0
2021	PO5524711676	KU	6	30 KOP	SP	CRE	ID	BD	00:00.0
2021	PO5569410828A	KU	5	35 KOP	SP	CRE	ID	BD	00:00.0
2021	PO6739923162	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4666312805	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021	PO4662212945	KU	4	45 KOP	SP	CRE	ID	BD	00:00.0
2021	PO4669213298	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021	PO4677113169	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021	PO5564611852	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021	PO6657523648	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4554087941	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4553687948	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4650912036	KU	6	30 KOP	SP	CRE	ID	BD	00:00.0
2021	PO6068019362	KU	6	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO6078819314	KU	3	45 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO4912017424	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5620913233	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO4924517487	KU	2	55 BRO	SP	CCA		V	00:00.0
2021	PO2222121420	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6425424861	KU	4	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO6200419177	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO6161422000	KU	5	35 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO6368625320	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4669413218	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO2176489051	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021	PO2175489076	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021	PO6170619236	KU	3	45 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	5653411676A	KU	5	40 UNK	SP	CRE		V	00:00.0
2021	4276686694	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5872912547A	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO5458113537B	KU	4	40 BRO	SP	P		V	00:00.0
2021	PO5458113537A	KU	4	40 BRO	SP	P		V	00:00.0
2021	5581913595A	KU	5	35 UNK	SP	CRE		V	00:00.0
2021	PO5708212614A	KU	5	35 UNK	SP	CCA		V	00:00.0
2021	PO5708212614B	KU	4	35 MAR	SP	P		V	00:00.0
2021	5573711890A	KU	3	45 UNK	SP	P		V	00:00.0
2021	PO5538012892A	F	5	30 BRO	SP	P		V	00:00.0
2021	PO5028718424A	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO5049519107	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5028718424B	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	4278386659	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	4277086693	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	4292086603	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	4279286575	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO5569211872A	KU	6	30 KOP	SP	CCA		V	00:00.0
2021	PO5299316853A	KU	5	40 BRN	SP	A		V	00:00.0
2021	PO5083018417A	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO7386806842A	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0

2021	PO5557607687A	KU	4	30E	BRN	SP	CRE		T		00:00.0
2021	PO7103022996	KU	5	35	KOP	SP	CRE	ID,IP	TD		00:00.0
2021	PO5500511193	KU	5	35	KOP	SP	CRE	ID	TD		00:00.0
2021	PO6981523578	KU	5	35	KOP	SP	CRE	ID	TX	RR	00:00.0
2021	PO7011123476	KU	5	35	KOP	SP	CRE	ID	TD		00:00.0
2021	PO6634123585	KU	4	40	XXX	SP	CRE	ID	TD		00:00.0
2021	PO5591712285	KU	6	30	KOP	SP	CRE	ID	TD		00:00.0
2021	PO4643212178	KU	4	40	KOP	SP	CRE	ID	TD		00:00.0
2021	PO5494711725	KU	4	45	KOP	SP	CRE	ID	TD		00:00.0
2021	PO4647412286	KU	4	40	KOP	SP	CRE	ID	TD		00:00.0
2021	PO7123322859	KU	5	35	KOP	SP	CRE	ID	TD		00:00.0
2021	PO5568912972	KU	5	30	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5705912223	KU	5	30	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5747913040	KU	6	30	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5453713206	KU	3	45	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO4958217690	KU	3	45	CPT	SP	CRE	ED,ID	TD		00:00.0
2021	PO5071308014	KU	1	70	XXX	ST	CRE		V		00:00.0
2021	PO5029917853	KU	3	45	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5873812602	KU	6	30	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5597612376	KU	2	45	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5584113503	KU	6	30	BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO5069318315	KU	1	40	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5078518272	KU	1	40	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5596812335	KU	2	45	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5602012407	KU	4	45	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5888617454	KU	4	40	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO6131522114	KU	4	40	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO6385719260	KU	3	45	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO4278386422	LGE	H3	70	ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO5953818929	KU	6	30	UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO4393685880	LGE	4	30	BRO	SP	A	ID,MD,RB	X	RP1	00:00.0
2021	PO4395085883	LGE	4	30	BRO	SP	CCA	ID,MD	VX	RP1	00:00.0
2021	PO4392285866	LGE	3	45	BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO4390385855	LGE	3	45	BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO7034123394	KU	5	35	KOP	SP	CRE	HH,ID	X	PX	00:00.0
2021	PO4367907687	KU	4	45	KOP	SP	CRE	ED,HH,ID	X	PX	00:00.0
2021	PO4408485899	LGE	3	50	BRO	SP	A	ED,HH,ID,IP,RB	X	RP1	00:00.0
2021	PO5376726128	KU	4	40	UNK	SP	CRE		V		00:00.0
2021	PO8247064718	ODP	4	40	BRN	SP	S		V		00:00.0
2021	PO8276664728	ODP	2	50	BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO8218764718	ODP	5	35	BRN	SP	S		V		00:00.0
2021	PO8243665062	F	4	40	BRN	SP	S		V		00:00.0
2021	PO8256765091	ODP	6	30	BRN	SP	S		V		00:00.0
2021	PO8348361730	ODP	5	40	BRN	SP	S		V		00:00.0
2021	PO8358661819	ODP	4	40	BRN	SP	S		V		00:00.0
2021	PO4494288019	LGE	4	40	ACE	SP	P	ED,ID,MD	TD		00:00.0
2021	PO8443569552	ODP	6	30	XXX	SP	CRE	ID	TD		00:00.0
2021	PO8370678272	F	5	35	ACE	SP	CRE		V		00:00.0
2021	PO8374978383	F	5	35	ACE	SP	CRE		V		00:00.0
2021	PO5770322006	KU	3	45	BRO	SP	CCA		V		00:00.0
2021	PO5763222022	KU	4	45	UNK	SP	CRE	HH,ID	X	RP2	00:00.0
2021	PO5752822044	KU	4	40	UNK	SP	CRE	ID	TD		00:00.0
2021	PO5249410605	F	4	40	XXX	SP	CRE		V		00:00.0
2021	PO4493588029	LGE	3	45	ACE	SP	P	ED,ID	TD		00:00.0

2021	PO5246710526	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5251410520	F	4	40 XXX	SP	P	ED,ID,SRS	BX	RP2	00:00.0
2021	PO8407369616	ODP	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4493088039	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO5750722121	F	4	40 UNK	AL	CRE		V		00:00.0
2021	PO5705521349	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5503724888	KU	3	45 UNK	SP	CRE		BD		00:00.0
2021	PO8369678403	KU	6	30 ACE	SP	CCA	ED	TD		00:00.0
2021	PO8356678312	KU	6	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO5244110452	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5241010361	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4491888058	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4492388050	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO8376270258	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO8378569860	F	4	40 XXX	SP	P		V		00:00.0
2021	PO8402869954	ODP	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO8437770086	ODP	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5688427647	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5683027674	F	3	35 UNK	SP	CRE		V		00:00.0
2021	PO5714321522	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5710021437	KU	4	40 UNK	SP	CRE	ED,ID	BD		00:00.0
2021	PO8339178323	KU	6	30 ACE	SP	CCA	ED	TD		00:00.0
2021	PO8326878328	KU	6	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO5264010280	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5266610356	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6105828085	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021	PO5721621667	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5726721766	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5731421858	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5736421965	KU	4	40 KOP	SP	CRE	ID,RB	BX	PX	00:00.0
2021	PO5743622012	KU	2	45 KOP	SP	S		V		00:00.0
2021	PO5744222062	KU	4	40 UNK	SP	CRE	ED,HH,ID,MD	BX	RP2	00:00.0
2021	PO5739428418	KU	2	45 UNK	SP	CCA		V		00:00.0
2021	PO4441488163	LGE	4	30 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021	PO4441588172	LGE	4	30 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4441388179	LGE	4	35 BRO	SP	CCA	ED,ID	TD		00:00.0
2021	PO4441088188	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4440788195-A	KU	4	35 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4440788195	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4439988220	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4439688231	LGE	4	30 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO5920527605	KU	5	35 UNK	SP	CRE		BD		00:00.0
2021	PO5269610448	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5261410571	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5272610535	F	4	45 KOP	SP	P		V		00:00.0
2021	PO5276210625	F	4	40 KOP	SP	P		V		00:00.0
2021	PO4454887856	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4473387914	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4498688113	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4498488117	LGE	4	40 ACE	SP	P	ED,ID,MD	TD		00:00.0
2021	PO5933627563	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021	PO5929327689	F	1	20 UNK	UN	CCA		V		00:00.0
2021	PO5282010796	F	3	45 KOP	SP	P		V		00:00.0
2021	PO5279110707	F	4	40 KOP	SP	P		V		00:00.0

2021	PO5344210436	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO4455287811	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO1265456736	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021	PO1248656886	KU	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO8225661703	ODP	5	35 BRN	SP	P	ED,ID	BD		00:00.0
2021	PO8226061587	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8235361682	ODP	5	35 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO8223161778	ODP	5	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4498088124	LGE	4	40 ACE	SP	A	ED,ID,MD	TD		00:00.0
2021	PO8239261984	F	4	40 BRN	SP	P		V		00:00.0
2021	PO8251761865	ODP	4	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO8280661459	F	4	40 BRN	SP	P		V		00:00.0
2021	PO8285261593	F	4	40 BRN	SP	P		V		00:00.0
2021	PO8290461710	F	4	40 BRN	SP	P		V		00:00.0
2021	PO8260061792	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO8291861830	ODP	4	45 BRN	SP	S		V		00:00.0
2021	PO8302762023	ODP	4	45 BRN	SP	S		V		00:00.0
2021	PO8312361701	ODP	6	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO8348761943	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO8348661838	ODP	2	50 BRN	SP	CCA		V		00:00.0
2021	PO5907327084	KU	4	40 UNK	SP	CRE		T		00:00.0
2021	PO5856927311	KU	2	45 UNK	SP	CRE		BD		00:00.0
2021	PO5851127257	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO5848727233	KU	4	45 UNK	SP	CCA		V		00:00.0
2021	PO5872427460	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021	PO4455387812	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO8454870800	ODP	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO8467371370	ODP	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO8478671778	ODP	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5876427315	KU	5	35 UNK	SP	CRE		BD		00:00.0
2021	PO4497588131	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO5875727464	F	4	40 UNK	SP	CRE	ED,ID	VX	RP2	00:00.0
2021	PO5883527383	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5889027325	F	1	20 UNK	UN	CCA		V		00:00.0
2021	PO5890427310	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5897327237	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5899327215	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5904927157	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO1233757036	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021	PO4455187821	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO1195257460	KU	6	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO1203557333	KU	6	35 BRN	SP	CRE	ID	TD		00:00.0
2021	PO5740122134	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021	PO5731422154	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO4438688233	LGE	6	25 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4440888245	LGE	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4441188243	LGE	6	25 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4439788265	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4441188260	LGE	3	45 BRO	SP	CRE	ED,HH,ID,IP,RB	TX	RR	00:00.0
2021	PO4440288255	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4443188221	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4443888201	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4444388186	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4444188223	F	4	35 BRO	SP	P		V		00:00.0

2021 PO4444688224	F	4	35 BRO	SP	P		V	00:00.0
2021 PO5903227038	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5896026962	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5902627303	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO4497388135	LGE	4	40 ACE	SP	CRE	ED,ID,MD	BD	00:00.0
2021 PO8396979824	F	5	40 ACE	SP	CRE		V	00:00.0
2021 PO8389579919	F	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4496988144	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4496888146	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4496488142	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5343310343	KU	5	35 XXX	SP	CRE	ED,ID,RB	BX	RP3 00:00.0
2021 PO5330610330	KU	2	65 BRN	ST	CRE		V	00:00.0
2021 PO5341410290	KU	2	70 BRN	SP	CRE		V	00:00.0
2021 PO5336410240	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5320910366	KU	1	45 BRN	SP	CRE		V	00:00.0
2021 PO5354510384	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4455187831	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4455587822	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8506780214	F	6	30 ACE	SP	CRE		V	00:00.0
2021 PO5898427350	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5894127397	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO5910227224	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO5733322089	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5729422099	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5728722065	KU	3	45 UNK	SP	P	ED,ID	TD	00:00.0
2021 PO5717821932	KU	6	25 UNK	SP	P		V	00:00.0
2021 PO5722921915	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5695421995	KU	3	50 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5719521823	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO8356978409	F	5	35 ACE	SP	CRE		V	00:00.0
2021 PO8342478415	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4495188147	LGE	1	90 ACE	SP	CRE		V	00:00.0
2021 PO4494988140	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4495888132	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8332878419	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8327278421	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8318978424	F	4	45 ACE	SP	CCA		V	00:00.0
2021 PO8319578503	F	4	45 ACE	SP	CCA		V	00:00.0
2021 PO8314578326	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8320578294	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO1219457176	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO1183657606	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5923327184	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO5921927168	KU	1	55 UNK	SP	CCA		V	00:00.0
2021 PO5918327136	KU	3	55 UNK	SP	CCA		V	00:00.0
2021 PO4455087835	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5315610386A	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5924427257	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5920627255	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO5935627200	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO5925527205	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO5303910632	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5300110519	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5303510428A	KU	3	45 BRN	SP	S		V	00:00.0

2021	PO5308310411	KU	2	65 BRN	SP	CRE			V	00:00.0	
2021	PO5303510428	KU	3	45 BRN	SP	S			V	00:00.0	
2021	PO5298210446	F	3	45 KOP	SP	S			V	00:00.0	
2021	PO5294410328	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5290110200	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO4454887829	LGE	4	40 BRO	SP	CCA			V	00:00.0	
2021	PO4454187839	LGE	4	40 BRO	SP	A	ED,ID		TD	00:00.0	
2021	PO4496988115	LGE	4	35 ACE	SP	A	ED,ID		TD	00:00.0	
2021	PO4497588102	LGE	4	35 ACE	SP	A	ED,ID,MD		TD	00:00.0	
2021	PO5905827581	KU	4	40 UNK	SP	CRE			BD	00:00.0	
2021	PO5903227605	KU	4	40 UNK	SP	CRE			BD	00:00.0	
2021	PO5911627610	F	4	40 UNK	SP	CRE			V	00:00.0	
2021	PO8306678340	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO8305678192	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO8305078094	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO8304577992	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO8309678081	KU	5	35 ACE	SP	CCA	ED		TD	00:00.0	
2021	PO8545972026	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO8526272113	ODP	5	35 XXX	SP	CCA			V	00:00.0	
2021	PO8523271937	ODP	5	35 XXX	SP	CRE	HH,ID		X	RP3	00:00.0
2021	PO8511172318	ODP	5	35 XXX	SP	P	ED		T		00:00.0
2021	PO5923227391	KU	4	40 UNK	SP	CRE			BD	00:00.0	
2021	PO5924927374	KU	4	40 UNK	SP	CRE			BD	00:00.0	
2021	PO5933527278	KU	2	55 UNK	SP	CCA			V	00:00.0	
2021	PO5933427379	F	4	40 UNK	SP	CRE	ED,ID		VX	PX	00:00.0
2021	PO8308777932	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO5915127476	KU	4	40 UNK	SP	CRE			BD	00:00.0	
2021	PO5919427528	F	4	40 UNK	SP	CRE			V	00:00.0	
2021	PO4453687845	LGE	4	40 BRO	SP	CCA	ED		T	00:00.0	
2021	PO5272010097	F	4	40 XXX	SP	CCA			V	00:00.0	
2021	PO5325509874	KU	4	40 BRN	SP	S			V	00:00.0	
2021	PO5293010033	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5284610030	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO4453087852	LGE	4	35 BRO	SP	A	ED,ID,IP		TD	00:00.0	
2021	PO8461578475	F	4	40 ACE	SP	CCA			V	00:00.0	
2021	PO8446378483	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO5715821751	KU	6	30 UNK	SP	CRE	ID,IP		TD	00:00.0	
2021	PO8413078406	F	5	30 ACE	SP	CRE			V	00:00.0	
2021	PO8438978487	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO8431178492	F	5	40 ACE	SP	CCA			V	00:00.0	
2021	PO8415278502	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO8404778507	F	4	40 ACE	SP	P			V	00:00.0	
2021	PO8399878553	KU	5	35 ACE	SP	CCA			V	00:00.0	
2021	PO8393978513	F	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO8375678492	F	5	35 ACE	SP	CRE			V	00:00.0	
2021	PO8375678522	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO5273409872	F	5	35 XXX	SP	CRE			V	00:00.0	
2021	PO5279509877	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5276209780	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5272909682	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5284309540	KU	6	30 XXX	SP	CRE	ID		BD	00:00.0	
2021	PO5267409269	KU	4	40 XXX	SP	CRE	ID,IP		BD	00:00.0	
2021	PO4496688087	LGE	4	35 ACE	SP	CRE	ED,ID		BD	00:00.0	
2021	PO4452487861	LGE	4	40 BRO	SP	CRE	ED,ID,IP		TD	00:00.0	



2021 PO1173457770	KU	6	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4454187866	LGE	4	40 BRO	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO8467371370A please remove	ODP	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8413870775	ODP	3	45 OTH	SP	CCA		V	00:00.0
2021 PO8486072766	F	3	45 OTH	SP	P		V	00:00.0
2021 PO8463570223	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO8449970920	ODP	3	45 OTH	SP	CCA		V	00:00.0
2021 PO8473671958	ODP	4	45 OTH	SP	CCA		V	00:00.0
2021 PO8512672484	F	3	40 OTH	SP	CCA		V	00:00.0
2021 PO8497372080	F	3	45 OTH	SP	P		V	00:00.0
2021 PO8502172530	F	3	45 OTH	SP	P		V	00:00.0
2021 PO4496088097	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4495988100	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4495588105	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8405669138	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO8398669068	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5713221689	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5709521670	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5705321587	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5275409515	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6169829453	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO8391677165	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6179728612	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO4474888199	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4434987822	LGE	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021 PO4435187840	LGE	4	30 BRO	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO4436187848	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO8219678231	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4432287899	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO1846594431	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4445788123	F	4	40 BRO	SP	P		V	00:00.0
2021 PO2921989538	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8435576913	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO8424976918	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO8411876924	KU	3	45 ACE	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO4449888196	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4449788205	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4449588216	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4449388228	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4449188236	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO8411363928	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8405664087	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8409963764	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8401663759	ODP	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6159328414	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO4442087845	LGE	4	35 BRO	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO4442887850	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4448787959	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4449188241	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4449088246	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO8657461068	ODP	3	40 BRO	SP	S		V	00:00.0
2021 PO4449088248	F	4	35 BRO	SP	P		V	00:00.0
2021 PO8638361057	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0597849744	KU	5	35 UNK	SP	CRE	ID	TD	00:00.0

2021 PO6131328250	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO8222177462	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8213877444	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6192629232	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO6189429416	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4450088186	F	5	30 BRO	SP	CCA		V	00:00.0
2021 PO8657461068A	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8656661279	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8667261272	ODP	6	30 BRN	SP	S	ED	T	00:00.0
2021 PO4446188010	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO6169529220	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO8437977090	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO8431177094	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO3026689877	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2946789991	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO6175229244	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO4442587904	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0451558579	KU	3	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO0561549172	KU	4	45 BRO	SP	CRE	ID	TD	00:00.0
2021 PO8077177681	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8031577714a	KU	2	60 ACE	ST	CCA		V	00:00.0
2021 PO8724768441	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8645665802	ODP	6	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7785377444	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7777977248	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8001177785	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO7931377870	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7750477280	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8421476920	F	3	50 ACE	SP	CCA		V	00:00.0
2021 PO8087177421	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8666767458	ODP	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO8662367894	ODP	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO7759877251	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8070177687	KU	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8670968464	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8643867764	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8018777682	KU	6	30 ACE	SP	CCA	ED	TD	00:00.0
2021 PO8030777577	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8031577640	KU	6	30 ACE	SP	CCA	ED	TD	00:00.0
2021 PO8031577714	KU	4	40 ACE	SP	CCA	ED	TD	00:00.0
2021 PO8075177727	KU	6	30 ACE	SP	CCA	ED	TD	00:00.0
2021 PO8038977708	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8418161516	ODP	2	50 BRN	SP	S		V	00:00.0
2021 PO8434761264	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8435561409	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8479261460	ODP	5	30 BRN	SP	CRE	ED,ID,IP,SR	TD	00:00.0
2021 PO8473061353	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8466361229	ODP	5	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8486861018	ODP	6	30 BRN	SP	S		V	00:00.0
2021 PO8492561080	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8070477730	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7792477628	KU	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8673167970	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8670268115	ODP	6	30 XXX	SP	CCA	ED	TD	00:00.0

2021	PO8693368151	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8507461602	ODP	6	30 BRN	SP	S		V	00:00.0
2021	PO8505461732	ODP	5	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8525361725	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8649265586	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8622165548	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021	PO7872277908	KU	2	65 ACE	SP	CRE		V	00:00.0
2021	PO7869777910	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7901677888	KU	2	65 ACE	SP	CRE		V	00:00.0
2021	PO8731068719	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8418261892	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8446061773	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO8433061670	ODP	5	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO2896589660	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2901189583	KU	4	45 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO7757678005	KU	2	70 ACE	SP	CRE		V	00:00.0
2021	PO2899189517	KU	3	45 BRO	SP	CCA	ED,SRS	T	00:00.0
2021	PO8678468978	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8615368475	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8649968744	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO7800877845	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7936775092	KU	1	35 ACE	AL	S		V	00:00.0
2021	PO8452461734	ODP	4	40 BRN	SP	S	ED,SRC	T	00:00.0
2021	PO8459461548	ODP	4	45 BRN	SP	S	ED,SRC	T	00:00.0
2021	PO8465161581	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO8490561734	ODP	5	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8708668886	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8722868934	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021	PO8505661033	ODP	2	50 BRN	SP	S		V	00:00.0
2021	PO7786277974	KU	2	70 ACE	SP	CCA		V	00:00.0
2021	PO7811977945	KU	2	70 ACE	SP	CRE		V	00:00.0
2021	PO7840677926	KU	2	65 ACE	SP	CRE		V	00:00.0
2021	PO7727878041	KU	2	70 ACE	SP	CRE		V	00:00.0
2021	PO7702378071	KU	2	70 ACE	SP	CRE		V	00:00.0
2021	PO7689078085	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO2895489769	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO2905589730	F	5	35 BRO	SP	CCA		V	00:00.0
2021	PO2912289740	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2908389822	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2960589737	KU	4	30 BRO	SP	A	ED,SRS	T	00:00.0
2021	PO2839289578	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2943588978	KU	4	40 BRO	SP	CRE	ID,IP,MD	BD	00:00.0
2021	PO2859689389	KU	4	40 BRO	SP	CRE	ID,IP,MD	BD	00:00.0
2021	PO2846889417	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2892689322	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2970689159	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO2935289234	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO2876189353	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2950989200	KU	4	45 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2921289264	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2909889288	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO4445387882	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5677520177	KU	3	50 BRO	SP	CCA		V	00:00.0
2021	PO5678720223	F	5	30 UNK	SP	P	ED,ID	BX	RP1 00:00.0

2021	PO5686420203	F	4	40 UNK	SP	P		V		00:00.0
2021	PO5684420156	KU	4	45 BRO	SP	CCA		V		00:00.0
2021	PO5695520177	F	4	40 UNK	SP	P		V		00:00.0
2021	PO6183629069	KU	5	35 UNK	SP	CRE		T		00:00.0
2021	PO6193128968	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021	PO6178328935	KU	4	40 UNK	SP	CRE		T		00:00.0
2021	PO5126511134	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5048611315	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5058611290	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5078711178	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5075511207	F	4	40 XXX	SP	P	ED,ID,RB	BX	PX	00:00.0
2021	PO6169228856	KU	5	35 UNK	SP	CRE		BD		00:00.0
2021	PO6186129043	KU	4	40 UNK	SP	CCA		V		00:00.0
2021	PO6186229010	KU	4	40 UNK	SP	CCA		V		00:00.0
2021	PO6193629077	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO6190229092	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5091111134	F	4	40 XXX	SP	P	ED,ID,RB	BX	RP2	00:00.0
2021	PO5109211053	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6149129253	KU	3	45 UNK	SP	CRE		BD		00:00.0
2021	PO4501388179	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO6135629213	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO6140629169	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO6127829044	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO6123228998	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO0663850446	KU	5	35 KOP	SP	CRE	ID	BD		00:00.0
2021	PO6118828953	KU	3	45 UNK	SP	CRE		BD		00:00.0
2021	PO0664650629	KU	5	35 KOP	SP	CRE	ID	BD		00:00.0
2021	PO0651350630	KU	3	50 KOP	SP	CRE	ID	TD		00:00.0
2021	PO6114028910	KU	3	45 UNK	DF	CRE		BD		00:00.0
2021	PO6108828959	F	4	40 UNK	SP	CCA		V		00:00.0
2021	PO6106928841	KU	2	55 UNK	SP	CCA		V		00:00.0
2021	PO4501388189	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021	PO4434288246	LGE	4	40 BRO	UN	CRE		V		00:00.0
2021	PO6083228605	KU	5	35 UNK	SP	CCA		V		00:00.0
2021	PO6088228655	KU	4	50 UNK	SP	CRE		BD		00:00.0
2021	PO6093128698	KU	5	35 UNK	SP	CCA		V		00:00.0
2021	PO6095428721	KU	5	35 UNK	SP	CCA		V		00:00.0
2021	PO4435188160	LGE	4	40 BRO	SP	P	ED,ID,RB	TD		00:00.0
2021	PO4435288150	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4435088171	LGE	4	40 BRO	SP	P	ED,EP,ID,IP,RB	TD		00:00.0
2021	PO4434988180	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021	PO4435588176	F	6	30 BRO	SP	CRE	ED,HH,ID,RB	VX	PX	00:00.0
2021	PO4434988190	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO1456394008	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4434988180-A	F	4	35 BRO	SP	P		V		00:00.0
2021	PO4435588190	F	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4434888202	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4434788212	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4435488204	F	4	35 BRO	SP	P		V		00:00.0
2021	PO4435388212	F	4	35 BRO	SP	P		V		00:00.0
2021	PO4435388223	F	4	30 BRO	SP	P		V		00:00.0
2021	PO4435288231	F	4	35 BRO	SP	P		V		00:00.0
2021	PO4434688223	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4434088252	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0

2021 PO4434488243	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4434688248	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4433188244	LGE	4	30 BRO	SP	P		V	00:00.0
2021 PO4433588259	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4434588235	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5694820127	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO5707520092	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5701720086	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5718420115	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5718820061	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5738320006	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5728820033	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5734819893	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO5743519923	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO5745619986	KU	2	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5753020020	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6097928746	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO6102928780	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO4501488209	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4501288155	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO6088328767	KU	5	35 UNK	SP	CRE	ED,ID	BX	00:00.0
2021 PO6084228723	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO6080728581	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO6074128518	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO6075828672	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5126510966	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5138911197	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5134711112	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5186210801	F	4	40 KOP	SP	P		V	00:00.0
2021 PO6068628602	KU	6	30 UNK	SP	CRE	ED,ID	BX	00:00.0
2021 PO4498188158	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4450787896	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4497188161	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4497188157	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO6035928699	KU	2	45 UNK	SP	CRE		BDD	00:00.0
2021 PO6039428748	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021 PO6032628737	KU	2	45 UNK	SP	CRE		BD	00:00.0
2021 PO6054028941	KU	3	45 UNK	SP	CRE		BD	00:00.0
2021 PO6049528899	KU	2	45 UNK	SP	CRE		BD	00:00.0
2021 PO5170110976	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5159010953	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO5172711054	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO1584190517	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4447087827	LGE	3	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6058628674	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO5193510627	F	4	40 KOP	SP	CRE		B	00:00.0
2021 PO1570490695	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4511588151	LGE	4	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5179211101	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5166410444	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5137410868	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4511088149	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4510888152	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO2197294037	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0

2021 PO4445887843	LGE	4	35 BRO	SP	A	ED,ID,JP	TD	00:00.0
2021 PO6049928558	KU	2	45 UNK	SP	CRE		T	00:00.0
2021 PO4509888166	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO6543947572	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4807590229-A	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4806990244	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5592002602	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5598102717	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5682203566	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5679203511	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5526896442	KU	2	45 BRN	SP	P		V	00:00.0
2021 PO7271749076	KU	6	30 BRO	SP	CRE		V	00:00.0
2021 PO3976005144	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3965205076	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4901690878	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO5650501627	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5666501525	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5676101472	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5683601428	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5685901416	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5579602520	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5594802412	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5584202485	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5562502223	F	5	35 XXX	SP	CRE		V	00:00.0
2021 PO5602402351	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5577802141	F	4	35 XXX	SP	P		V	00:00.0
2021 PO0398076905	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0389876779	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5448497740	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5456696842	F	2	50 KOP	SP	P		V	00:00.0
2021 PO5461496979	F	2	50 KOP	SP	P		V	00:00.0
2021 PO5466397126	F	2	50 KOP	SP	CCA		V	00:00.0
2021 PO1138166914	F	3	45 XXX	SP	P		V	00:00.0
2021 PO1132966813	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO1114266594	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO1112466594A	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO1118967151	F	3	45 XXX	SP	P		V	00:00.0
2021 PO1128867249	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO0386576463	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO5471297265	KU	3	45 KOP	SP	P		V	00:00.0
2021 PO5479897599	KU	3	45 KOP	SP	P		V	00:00.0
2021 PO5481797583	KU	2	45 KOP	SP	P		V	00:00.0
2021 PO5481797583A	KU	2	45 KOP	SP	P		V	00:00.0
2021 PO0355876099	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO7563347284	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3822406611	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3821106472	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3819806335	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3761705949	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO3823606752	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3774906223	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO3824406819	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3787806482	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4916290445	LGE	1	50 BRO	SP	CCA		V	00:00.0

2021 PO4914390443	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021 PO4909190439	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021 PO4911290440	LGE	3	50 BRO	SP	CCA	V	00:00.0
2021 PO4912890442	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021 PO7220649229	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO7238149330	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4770489609	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO7251749526	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO4774789613	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO1168866977	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO1169167059	KU	4	40 XXX	SP	CRE	V	00:00.0
2021 PO1200566891	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO1231266721	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO1264666618	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO1308666715	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5477697583	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO5807201279	F	3	40 XXX	SP	CRE	V	00:00.0
2021 PO5373600996	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5378201115	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5368200854	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5390601434	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4810690123	LGE	1	50 BRN	SP	CCA	V	00:00.0
2021 PO4810390130	LGE	1	50 BRN	SP	CCA	V	00:00.0
2021 PO5184214087	LGE	1	50 BRN	SP	CCA	V	00:00.0
2021 PO5746017335	LGE	2	60 BRO	SP	CCA	V	00:00.0
2021 PO4864390438	LGE	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4866690440	LGE	3	50 BRO	SP	CCA	V	00:00.0
2021 PO5235897085	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5804101363	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5797001344	F	4	45 XXX	SP	CRE	V	00:00.0
2021 PO5806201467	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5805501606	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5795001684	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5797201772	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5800201863	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5791602278	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5798302178	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5782102328	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5787602447	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5799602666	F	3	40 XXX	SP	CRE	V	00:00.0
2021 PO5821102446	F	4	45 XXX	SP	CRE	V	00:00.0
2021 PO5833902235	F	3	50 XXX	SP	CRE	V	00:00.0
2021 PO5752802523	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5759902504	F	4	35 XXX	SP	CRE	V	00:00.0
2021 PO5743702181	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5747102281	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5752402396	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5740802093	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4836490115	LGE	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4834490112	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4765190123	LGE	UNK	80 ACE	SP	A	V	00:00.0
2021 PO0536674036	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO0542973894	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO0739369965	KU	4	40 XXX	SP	CCA	V	00:00.0

2021 PO0500874230	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5251196898	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO5263596598	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO5251996638	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO2731086221a	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO2779486038	KU	6	30 BRN	SP	S		V	00:00.0
2021 PO4864590179	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4857590159	LGE	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4862890170	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO0157375055	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4769191022	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4762991222	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0182275287	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO0175966706	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0206866384	KU	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4756489844	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4755989860	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4766491198	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4865990185	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4867390191	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO4869890203	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5280197610	F	3	45 BRN	SP	CRE	ED	V	00:00.0
2021 PO5284597514	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5247197608	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2685287258	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5251797507	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5257197398	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5268297170	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5367596440	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5374296551	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5379396651	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5390696313	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5427096110	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5415296175	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5408196540	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4881790258	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4924890303	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4592307154	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4636707852	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4585406763	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4626807678	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4614507404	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4571506823	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4601407114	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4593606945	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4596707482	F	4	40 BRN	SP	CRE	IP	V	00:00.0
2021 PO4634607847	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4620807544	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4618007482	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4835590235	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4837790242	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO4839990250	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO7297148387	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO7290648398	F	4	40 BRO	SP	CRE	ED	V	00:00.0



2021 PO7278348418	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7267948435	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7257648453	F	4	40 BRO	SP	S		V	00:00.0
2021 PO7247048470	F	3	35 BRO	SP	CRE		V	00:00.0
2021 PO7237248481	F	3	35 BRO	SP	CRE	ED	V	00:00.0
2021 PO5407996893	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5435996742	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5446796685	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5726001635	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5693701651	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5697801776	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5687901819	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5702201907	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5705402004	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5713002234	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO5716702348	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO5709202120	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5647502179	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5654702283	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5684102214	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5660302401	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5693302530	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5670302596	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5332297443	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5348297305	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3987802317	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4757090183	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5257097955	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5268197909	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4903690447	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4893790466	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4898990438	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4579406625	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4566706563	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4550106482	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4532906398	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3718206724	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO3738907076	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4689009817	C	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4764989699	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO2484584942	KU	4	35 BRN	SP	CCA		V	00:00.0
2021 PO1066262048	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO1999448081	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5281097936	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5286098046	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5290398126	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5297098091	F	3	35 BRN	SP	CRE		V	00:00.0
2021 PO5263298133	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO5259898053	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO4786990868	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4945321101	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0116227923	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO0118128080	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO0106128072	KU	3	45 BRO	SP	S		V	00:00.0

2021 PO4510806398	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4505806475	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4505706253	F	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4829690393	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4824090367	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4832990396	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO7276147202	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7275547093	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO4899990415	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4886990440	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4886390401	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4886090379	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4885890367	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO5970853958	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5972254168A	KU	3	45 BRO	SP	S		V	00:00.0
2021 PO3906505422	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4736490420	LGE	H1	75 BRN	ST	CCA		V	00:00.0
2021 PO4739590383	LGE	H1	75 BRN	ST	CCA		V	00:00.0
2021 PO4923590325	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4808190399	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5484197775A	F	2	35 BRN	SP	CRE		V	00:00.0
2021 PO5484197775	KU	2	45 KOP	SP	CRE		V	00:00.0
2021 PO7357549295	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7369248947	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5458697016	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5452297014	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5460397059	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5465097206	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5469297337	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5474197476	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4921490458	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4930590459	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4921490451	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO6261517616	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4917990447	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO7217549362	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO3808806150	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO3815705908	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3807506005	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO3814105726	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7207649480	KU	5	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO3868103242	F	4	40 BRN	SP	S		V	00:00.0
2021 PO3868903328	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3870203497	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO3859503572	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4797190570	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO7193249516	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7191449420	KU	5	35 UNK	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO3856205021	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO3877505259	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3879005381	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO3876305081	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO3860305139	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO7189649347	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0

2021	PO7188049253	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO4798790563	LGE	4	30 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4798890536	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4798590557	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5000988711	LGE	3H	45 BRN	SP	A	ID,IP	BD	00:00.0
2021	PO4108383943	LGE	3	45 BRN	SP	A	ED	BD	00:00.0
2021	PO4107583966	LGE	3	45 BRN	SP	A	ED,ID	TD	00:00.0
2021	PO4359585704	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO4362785728	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO4363485733	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4361385717	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4360485711	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO0751869362	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO3835702537	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3835002886	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3839002913	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3806102952	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO3833902374	KU	6	30 BRN	SP	S		V	00:00.0
2021	PO7117648000	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO6485248259	KU	5	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO6478648270	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO6477848201	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO7569247779A	KU	5	35 UNK	SP	CRE	ED,HH,ID	BX	RP1 00:00.0
2021	PO7575647755	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO7577447813	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7627547274	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4359885781	LGE	3	45 BRN	SP	P		V	00:00.0
2021	PO4362185778	LGE	4	45 BRN	SP	P		V	00:00.0
2021	PO4363585757	LGE	4	45 BRN	SP	P		V	00:00.0
2021	PO5623495714	KU	2	55 BRN	SP	P		V	00:00.0
2021	PO5619495656	KU	2	50 BRN	SP	P		V	00:00.0
2021	PO5614995589	KU	2	55 BRN	SP	P		V	00:00.0
2021	PO5605995648	KU	2	50 BRN	SP	P		V	00:00.0
2021	PO5592895734	KU	2	50 BRN	SP	P		V	00:00.0
2021	PO5571795846	KU	2	55 BRN	SP	P		V	00:00.0
2021	PO3968397428	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO3963297267	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO4778291053	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4777291062	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4776591067	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO3968797150	KU	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO3937297546	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3952296955	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO3842003263	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO3811003038	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO3840703405	F	4	35 BRN	SP	CCA		V	00:00.0
2021	PO3805502595	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO3803702710	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO3829303248	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1 00:00.0
2021	PO3837603336	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO5607293603	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5597193536	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5578493690	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO5582293834	F	3	40 BRN	SP	CRE		V	00:00.0

2021	PO5626193671	F	2	40 BRN	SP	CRE		V		00:00.0
2021	PO5629393708	F	2	40 BRN	SP	CRE		V		00:00.0
2021	PO3928497197	KU	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO3957897104	KU	4	40 BRN	SP	CCA		V		00:00.0
2021	PO9940182500	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO5583895782	KU	2	55 BRN	SP	P		V		00:00.0
2021	PO4774491050	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9867781994	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9869782496	KU	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO4772291033	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO9859882740	KU	5	35 BRO	SP	CCA		V		00:00.0
2021	PO5539895951	KU	2	55 BRN	SP	P		V		00:00.0
2021	PO3950396757	KU	2	50 BRN	SP	S		V		00:00.0
2021	PO3945996767	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO3919096842	KU	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO5558295892	KU	2	55 BRN	SP	P		V		00:00.0
2021	PO7826546268	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO7843046652	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO7814746506	KU	4	30 UNK	SP	CRE		V		00:00.0
2021	PO4300887086	LGE	4	35 ACE	SP	A	ED	BD		00:00.0
2021	PO4302787079	LGE	1	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4303487081	LGE	3	45 ACE	SP	CRE		V		00:00.0
2021	PO4303687074	LGE	4	40 ACE	SP	A		V		00:00.0
2021	PO6558349180	KU	6	30 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO6567849216	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO7201847501	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO6617248893	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6630648850	KU	3	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO5896902450	F	4	45 XXX	SP	CRE		V		00:00.0
2021	PO5898902722	KU	6	30 XXX	SP	S		V		00:00.0
2021	PO5851901100	F	4	40 XXX	SP	CRE	ED,ID,IP	BX	RP2	00:00.0
2021	PO4330886984	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4460985799	LGE	3	45 BRN	SP	A		V		00:00.0
2021	PO4459485800	LGE	4	35 BRN	SP	A		V		00:00.0
2021	PO4483585850	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021	PO7613147314	F	4	40 KOP	SP	CRE		V		00:00.0
2021	PO7597847357	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO7583847396	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO7580847404	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO7620347077	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO7621547135	KU	6	30 BRO	SP	CCA		V		00:00.0
2021	PO7599247082	KU	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021	PO7604047182	KU	5	35 UNK	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO7588147225	KU	5	35 BRO	SP	CCA		V		00:00.0
2021	PO7578147250	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5099984873	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO4464485854	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021	PO6602649039	KU	3	45 BRN	SP	CCA		V		00:00.0
2021	PO6604248947	KU	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6670948742	KU	5	35 BRN	SP	CCA		V		00:00.0
2021	PO7213847268	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021	PO7210347487	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021	PO7223047255	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021	PO7225947360	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0

2021	PO7226547420	KU	5	35 BRO	SP	CCA			V	00:00.0
2021	PO7227047480	KU	6	30 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO7228147576	KU	5	35 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO4458786078	LGE	4	35 BRN	SP	CCA			V	00:00.0
2021	PO4460286079	LGE	4	35 BRN	SP	CCA			V	00:00.0
2021	PO4545101117	F	4	40 BRO	SP	CRE	ED,HH,ID,RB		BX	RP3 00:00.0
2021	PO4552101030	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4559900939	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4566900844	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4574600749	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4545999608	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4541799498	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4537599386	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4533499274	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4529299162	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4524599034	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4515498794	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4519698906	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4511198681	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO7283948097	KU	5	40 KOP	SP	CRE	ED,ID		TD	00:00.0
2021	PO6550048636	KU	1	75 BRN	SP	CRE			V	00:00.0
2021	PO6544348718	KU	6	30 BRN	SP	CRE	ED,ID		TD	00:00.0
2021	PO9289493349	LGE	3	45 BRN	SP	A	ED,ID,JP		TD	00:00.0
2021	PO4450386157	F	2	65 BRN	SP	P			V	00:00.0
2021	PO4450286173	LGE	2	50 BRN	SP	P	ED,ID		BD	00:00.0
2021	PO4451886109	LGE	3	45 BRN	SP	A	ED,ID		BD	00:00.0
2021	PO4917691435	LGE	4	40 BRN	SP	CCA			V	00:00.0
2021	PO4917791407	LGE	4	40 BRN	SP	A			B	00:00.0
2021	PO6821249878	KU	4	40 BRN	SP	CRE			BD	00:00.0
2021	PO6807549885	KU	4	40 BRN	SP	CRE	ED		TD	00:00.0
2021	PO5947901576	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO4264987970	LGE	4	40 BRN	SP	CCA			V	00:00.0
2021	PO4264887970	LGE	4	35 BRN	SP	CRE			V	00:00.0
2021	PO4255287826	F	2	55 BRN	SP	CCA			V	00:00.0
2021	PO4255487830	LGE	4	35 BRN	SP	CRE			V	00:00.0
2021	PO7972290299	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO7955989792	KU	4	40 UNK	SP	CRE	ID		BD	00:00.0
2021	PO7944789533	KU	4	45 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO4255287828	LGE	4	40 BRN	SP	CCA			V	00:00.0
2021	PO4254787830	LGE	4	45 BRN	SP	CCA			V	00:00.0
2021	PO4254587842	LGE	4	35 BRN	SP	CRE			V	00:00.0
2021	PO4263787930	LGE	4	40 BRN	SP	CCA			V	00:00.0
2021	PO4254287830	LGE	4	40 BRN	SP	CCA			V	00:00.0
2021	PO4253888033	LGE	4	40 BRN	SP	CRE	ED,ID		BD	00:00.0
2021	PO4371098530	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4364098390	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4336298445	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4341998581	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4346898697	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4322198818	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4316598692	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021	PO4324798471	F	3	45 BRO	SP	CRE	ED		V	00:00.0
2021	PO4322498551	F	3	45 BRO	SP	CRE	ED		V	00:00.0
2021	PO3993097892	F	3	45 BRN	SP	CRE			V	00:00.0

2021 PO4259586657	LGE	3	25 ACE	SP	CCA		V	00:00.0
2021 PO8048487585	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8267086126	KU	5	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4256987802	LGE	4	40 BRN	SP	CCA	ED,ID	BD	00:00.0
2021 PO4256887995	LGE	3	45 BRN	SP	CCA	ED	V	00:00.0
2021 PO4256887888	LGE	3	50 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO6972747758	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7675447076	KU	6	30 UNK	SP	CRE		V	00:00.0
2021 PO6854943887	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6851744358	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO6845244105	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO6842444318	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6843344645	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO7044947777	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4217588101	LGE	1	55 BRN	SP	A	ID,IP	BD	00:00.0
2021 PO6512048915	KU	4	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6503048987	KU	3	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6496548891	KU	5	45 BRN	SP	CRE		V	00:00.0
2021 PO4235288157	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6852644535	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4037899075	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4037298982	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO6628949052	KU	6	35 BRN	SP	CCA		V	00:00.0
2021 PO6645749080	KU	4	40 BRN	SP	CRE		BD	00:00.0
2021 PO6647749161	KU	6	30 BRN	SP	CRE		BD	00:00.0
2021 PO6815044981	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6822944847	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO6831144693	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO6838444523	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6805245133	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6793745310	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6818345171	F	4	40 BRO	SP	P		V	00:00.0
2021 PO6803045334	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO6791745497	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6791445539	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6809445415	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6843643891	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4485487771	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4485187777	LGE	4	30 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO6116551179	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO6510349184	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6489449267	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6493049315	KU	4	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4332187015	F	4	35 BRN	SP	CRE		V	00:00.0
2021 PO6471647740	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6470247709	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6655149171	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO6618449306	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6633049220	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7009647092	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7010247229	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7000047096	KU	5	35 XXX	SP	CRE	ID	BX	RR 00:00.0
2021 PO7001047234	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6991047261	KU	5	35 XXX	SP	CCA		V	00:00.0

2021 PO6649749241	KU	4	40 BRN	SP	CRE		ED	TD	00:00.0
2021 PO6651949331	KU	3	45 BRN	SP	CCA			V	00:00.0
2021 PO6487247757	KU	5	35 BRN	SP	CRE			V	00:00.0
2021 PO4461585821	LGE	1	80 BRN	SP	CRE			V	00:00.0
2021 PO7475248174	KU	4	40 UNK	SP	CRE		ID	BD	00:00.0
2021 PO6905840203	KU	4	40 BRN	SP	CRE		ED	VX	PX 00:00.0
2021 PO6965740217	KU	4	40 BRN	SP	CRE		ED	TD	00:00.0
2021 PO3982299851	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO4007399728	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO3969499914	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO3994799790	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO7458648216	KU	4	45 BRO	SP	CRE		ED,ID	BD	00:00.0
2021 PO7433348286	KU	4	45 BRO	SP	CRE		ED,ID	TD	00:00.0
2021 PO7410248328	KU	4	45 BRO	SP	CRE		ED,ID	TD	00:00.0
2021 PO4461785827	LGE	4	35 BRN	SP	CCA			V	00:00.0
2021 PO4462885816	LGE	1	85 BRN	SP	CRE		ED,ID,IP	TD	00:00.0
2021 PO4448388141	LGE	4	40 BRO	SP	CCA		ED,ID	BD	00:00.0
2021 PO4448188143	LGE	4	40 BRO	SP	CCA		ED,ID,IP	BD	00:00.0
2021 PO4447888142	LGE	4	40 BRO	SP	CCA		ED,ID,IP	BD	00:00.0
2021 PO4448088146	F	4	30 BRO	SP	CRE			V	00:00.0
2021 PO4443888203	LGE	6	25 BRO	SP	CRE			V	00:00.0
2021 PO4441788257	LGE	4	40 BRO	SP	CRE			V	00:00.0
2021 PO4440388240	LGE	4	35 BRO	SP	CRE			V	00:00.0
2021 PO4437688235	LGE	6	25 BRO	SP	CRE			V	00:00.0
2021 PO4502988082	LGE	4	45 ACE	SP	CRE		ED,ID,MD	TD	00:00.0
2021 PO4502488090	LGE	4	45 ACE	SP	CRE		ED,ID,MD	TD	00:00.0
2021 PO5717922129	KU	4	40 UNK	SP	CRE		ED,ID	TD	00:00.0
2021 PO4470787999	LGE	4	40 BRO	SP	CRE		ED,ID,IP	TX	RR 00:00.0
2021 PO5834623160	KU	4	40 UNK	SP	CRE			BD	00:00.0
2021 PO5832523080	KU	4	40 UNK	SP	CRE			BD	00:00.0
2021 PO5837323267	KU	5	35 UNK	SP	CRE			V	00:00.0
2021 PO5714822196	KU	5	30 UNK	SP	CRE		ED,ID	X	RP2 00:00.0
2021 PO5719922183	KU	5	35 UNK	SP	CRE			V	00:00.0
2021 PO5772822051	KU	5	35 UNK	SP	CRE		ID	BD	00:00.0
2021 PO1227153215	KU	4	45 INP	SP	CRE		ID	TD	00:00.0
2021 PO5250411211	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO4469887993	LGE	4	40 BRO	SP	CRE		ED,ID,IP	TD	00:00.0
2021 PO4469187989	LGE	4	40 BRO	SP	CRE		ID,IP	BD	00:00.0
2021 PO5237911006	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO5235010912	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO4500088127	LGE	4	45 ACE	SP	CCA			V	00:00.0
2021 PO8342679304	KU	3	45 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO4468687985	LGE	5	25 BRO	SP	CRE		ID	BD	00:00.0
2021 PO4473987906	LGE	4	40 BRO	SP	CRE		ED,ID,IP	TX	RR 00:00.0
2021 PO5233310722	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO5230410781	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO5237610648	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO5226910686	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO5229110592	F	3	40 KOP	SP	CCA			V	00:00.0
2021 PO5225910501	F	3	40 KOP	SP	CCA			V	00:00.0
2021 PO5222710408	F	4	40 XXX	SP	CCA			V	00:00.0
2021 PO5777222042	KU	5	35 UNK	SP	CRE		ED,ID	TD	00:00.0
2021 PO5788021960	KU	3	45 BRO	SP	CCA			V	00:00.0
2021 PO5794221943	KU	3	45 BRO	SP	CCA			V	00:00.0

2021 PO5800221928	KU	3	45 BRO	SP	CCA			V	00:00.0	
2021 PO4500488146	LGE	1	95 ACE	SP	CRE			V	00:00.0	
2021 PO4498788150	LGE	4	30 ACE	SP	CCA			V	00:00.0	
2021 PO4497888146	LGE	1	90 ACE	SP	CRE			V	00:00.0	
2021 PO8352579654	KU	4	40 ACE	SP	CRE	ED,ID		BD	00:00.0	
2021 PO8343779574	KU	5	35 ACE	SP	CRE	ED,ID		BD	00:00.0	
2021 PO4508988146	LGE	4	35 ACE	SP	CRE			V	00:00.0	
2021 PO8343879532	KU	3	50 ACE	SP	CRE	ED,ID		TD	00:00.0	
2021 PO1198753187	KU	4	45 INP	SP	P	ID		TD	00:00.0	
2021 PO1179253152	KU	4	40 INP	SP	CRE	ID		TD	00:00.0	
2021 PO1145953093	KU	3	45 BRO	SP	CCA			T	00:00.0	
2021 PO1029952963	KU	3	45 BRO	SP	CCA			V	00:00.0	
2021 PO4498688134	LGE	4	45 ACE	SP	CRE	ED,ID		BD	00:00.0	
2021 PO4501188133	LGE	4	40 ACE	SP	CCA	ED,ID		BD	00:00.0	
2021 PO8328579537	KU	4	40 ACE	SP	CRE	ED,ID		TD	00:00.0	
2021 PO8342379730	KU	5	35 ACE	SP	CRE	ED,ID		TD	00:00.0	
2021 PO8356079864	KU	5	35 ACE	SP	CRE	ED,ID		TD	00:00.0	
2021 PO8361379921	KU	4	40 ACE	SP	CCA			V	00:00.0	
2021 PO8358579985	KU	4	40 ACE	SP	CCA			V	00:00.0	
2021 PO8365479990	KU	5	35 ACE	SP	CRE	ED,ID		TD	00:00.0	
2021 PO8356380041	KU	5	35 ACE	SP	CRE	ED,ID		BD	00:00.0	
2021 PO8372679994	KU	6	30 ACE	SP	CCA			V	00:00.0	
2021 PO8380580120	KU	6	30 ACE	SP	CCA			V	00:00.0	
2021 PO8376580185	KU	5	35 ACE	SP	CCA			V	00:00.0	
2021 PO4499688134	LGE	1	50 ACE	SP	CCA			V	00:00.0	
2021 PO8203882266	F	4	40 ACE	SP	CCA			V	00:00.0	
2021 PO8216482261	F	4	40 ACE	SP	CRE			V	00:00.0	
2021 PO8254382252	F	3	40 ACE	SP	P			V	00:00.0	
2021 PO8267082249	F	4	40 ACE	SP	CRE			V	00:00.0	
2021 PO8229082258	F	4	40 ACE	SP	CRE			V	00:00.0	
2021 PO8241682256	F	4	40 ACE	SP	CCA			V	00:00.0	
2021 PO8279582245	F	4	40 ACE	SP	CCA			V	00:00.0	
2021 PO8291982243	F	4	40 ACE	SP	CRE			V	00:00.0	
2021 PO8514255558	ODP	4	40 XXX	SP	CRE	ID		TD	00:00.0	
2021 PO8111361171	F	4	40 BRN	SP	P			V	00:00.0	
2021 PO8057760746	ODP	4	40 BRN	SP	CRE	ED,ID,IP		TD	00:00.0	
2021 PO8059560897	F	4	40 BRN	SP	P			V	00:00.0	
2021 PO8071060957	ODP	4	40 BRN	SP	CRE	ED,ID		TD	00:00.0	
2021 PO8061360995	ODP	6	30 BRN	SP	CRE	ED,ID		TD	00:00.0	
2021 PO8526054990	ODP	4	40 XXX	SP	CRE	ID		TD	00:00.0	
2021 PO8047961166	ODP	5	35 BRN	SP	S			V	00:00.0	
2021 PO8038061242	F	4	40 BRN	SP	CRE			V	00:00.0	
2021 PO8034361101	ODP	4	40 BRN	SP	CRE	ED,ID		TD	00:00.0	
2021 PO8017761175	ODP	4	40 BRN	SP	CRE	ED,ID,IP		TD	00:00.0	
2021 PO7999761373	ODP	4	40 BRN	SP	CRE	ED,ID,IP,RB		X	RP1	00:00.0
2021 PO8002161315	ODP	5	35 BRN	SP	S			V	00:00.0	
2021 PO7998761257	F	4	40 BRN	SP	S			V	00:00.0	
2021 PO7998761121	ODP	6	30 BRN	SP	CRE	ED,ID,IP		TD	00:00.0	
2021 PO8522355209	ODP	4	40 XXX	SP	CRE	ID		TD	00:00.0	
2021 PO8570954362	ODP	5	30 XXX	SP	CRE	ID		TD	00:00.0	
2021 PO8580954437	ODP	5	35 XXX	SP	CRE	ED,ID,IP		TD	00:00.0	
2021 PO8308782239	F	4	40 ACE	SP	CRE	ED,ID		V	00:00.0	
2021 PO8311682357	F	6	30 ACE	SP	CRE	ED,ID		V	00:00.0	
2021 PO8317282303	F	5	35 ACE	SP	CRE	ED,ID		V	00:00.0	



2021 PO7970860848	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7964160925	ODP	6	30 BRN	SP	S	ED	T	00:00.0
2021 PO7957660879	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7966861190	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7964161404	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8530354760	ODP	6	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8536254426	ODP	5	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8538954291	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8609053653	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8591353739	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8562853923	ODP	3	50 XXX	SP	CCA		V	00:00.0
2021 PO8572153829	ODP	3	50 XXX	SP	CCA		V	00:00.0
2021 PO8521553829	ODP	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8566653805	ODP	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8557053767	ODP	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO7952361046	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7944460810	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8476079227	KU	5	35 ACE	SP	CRE		V	00:00.0
2021 PO8489279232	KU	3	45 ACE	SP	CRE		V	00:00.0
2021 PO8485179350	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8495579229	KU	5	35 ACE	SP	CRE		V	00:00.0
2021 PO5800121678	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO5804921857	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO8450979135	F	5	35 ACE	SP	CRE		V	00:00.0
2021 PO8440079139	F	5	35 ACE	SP	P		V	00:00.0
2021 PO8429579143	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8416279146	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8403679150	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8386979155	F	6	30 ACE	SP	CRE	ED,ID	V	00:00.0
2021 PO8379979157	F	5	35 ACE	SP	CRE	ED,ID	V	00:00.0
2021 PO8368579161	F	5	35 ACE	SP	CRE	ED,ID	V	00:00.0
2021 PO7949061508	F	4	40 BRN	SP	CRE		VX	00:00.0
2021 PO7939561500	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7931961536A	ODP	4	40 BRN	SP	S		V	00:00.0
2021 PO7931961536	F	4	40 BRN	SP	P		V	00:00.0
2021 PO7937461621	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7944161722	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7955561891	F	6	30 BRN	SP	P		V	00:00.0
2021 PO7920561995	ODP	6	30 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7929461949	ODP	6	30 BRN	SP	S		V	00:00.0
2021 PO7926161913	F	6	30 BRN	SP	P		V	00:00.0
2021 PO7919862108	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7907862314	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5794321424	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5791021295	F	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5788121180	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5786321113	F	3	40 UNK	SP	CRE		V	00:00.0
2021 PO5784821054	F	4	50 UNK	SP	CRE		V	00:00.0
2021 PO5790021262	F	6	30 UNK	SP	CCA		V	00:00.0
2021 PO5778721589	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5788221559	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5774321589	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5767021621	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5757821506	KU	4	40 UNK	SP	CRE		BD	00:00.0

2021	PO5762621587	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO5763421506	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5731121496	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO5729421445	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5741121473	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO5738021426	F	3	45 UNK	SP	CRE		V	00:00.0
2021	PO5750221452	KU	4	35 UNK	SP	CCA		BD	00:00.0
2021	PO5749021400	F	3	30 UNK	SP	CRE		V	00:00.0
2021	PO5755521407	KU	2	40 UNK	SP	CCA		V	00:00.0
2021	PO5760421394	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO5752121296	KU	6	30 UNK	SP	CCA		V	00:00.0
2021	PO5758421316	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5756421228	KU	4	35 UNK	SP	CCA		V	00:00.0
2021	PO8413078643	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8411378745	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8411578895	F	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8411678945	F	6	30 ACE	SP	CCA		V	00:00.0
2021	PO8365379657	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8361879523	F	3	45 ACE	SP	CRE		V	00:00.0
2021	PO8360379322	F	4	40 ACE	SP	P		V	00:00.0
2021	PO8364879198	KU	6	30 ACE	SP	CCA		V	00:00.0
2021	PO8359279159	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8358178994	F	4	40 ACE	SP	CRE	ED,ID	V	00:00.0
2021	PO8365878979	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8356878826	F	4	45 ACE	SP	P		V	00:00.0
2021	PO8370078749	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8355878699	F	5	35 ACE	SP	CRE		V	00:00.0
2021	PO8355078597	F	5	35 ACE	SP	CRE	ED,ID	V	00:00.0
2021	PO8463779723	KU	5	35 ACE	SP	CRE	ED,ID	V	00:00.0
2021	PO8453379632	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8468879616	KU	6	30 ACE	SP	CCA		V	00:00.0
2021	PO8463779619	F	5	35 ACE	SP	CRE	ED,ID	V	00:00.0
2021	PO8463479437	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8463479342	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8463379247	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8463079018	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8462878891	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8462778777	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8462578644	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8462478522	F	4	40 ACE	SP	CRE	ED,HH,ID,MD,RB	VX PX	00:00.0
2021	PO8479379699	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8493679791	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8489079790	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8475379785	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO0602844588A	KU	4	40 BRN	SP	CCA		T	00:00.0
2021	PO0634344437	KU	3	45 US	SP	CCA		V	00:00.0
2021	PO4473787992	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4474287985	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4474887976	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4457987817	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4455987842	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4456987829	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO0623744452	KU	6	35 US	AL	CRE		V	00:00.0
2021	PO9559821135	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0

2021	PO4468288069	LGE	4	30 BRO	ST	CCA			V	00:00.0
2021	PO4464988044	LGE	3	50 BRO	SP	A	ID		BD	00:00.0
2021	PO0501145269	KU	4	45 BRN	SP	CRE	ID		TD	00:00.0
2021	PO0278538273	KU	4	45 BRN	SP	CRE	ID		TD	00:00.0
2021	PO4464988044-A	KU	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4466388035	LGE	4	40 BRO	SP	A	ED, ID		TD	00:00.0
2021	PO0288838518	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021	PO4467088030	LGE	4	35 BRO	SP	A	ID, IP		BD	00:00.0
2021	PO4467088026	LGE	4	30 BRO	SP	CRE	ED, ID		TD	00:00.0
2021	PO4467488025	LGE	4	35 BRO	SP	CRE	ED, ID		TD	00:00.0
2021	PO0418546215	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021	PO0428946202	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021	PO4468088028	LGE	4	35 BRO	SP	CRE	ID		TD	00:00.0
2021	PO0432846535	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021	PO0460246232	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021	PO4468988028	LGE	4	35 BRO	SP	CRE	ED, ID, IP		TD	00:00.0
2021	PO5795021126	KU	2	50 UNK	SP	CCA			V	00:00.0
2021	PO5797521212	KU	3	50 UNK	SP	CCA			V	00:00.0
2021	PO5799721323	KU	2	50 UNK	SP	CCA			V	00:00.0
2021	PO5801621392	KU	2	50 UNK	SP	CCA			V	00:00.0
2021	PO5794421102	KU	3	50 UNK	SP	CCA			V	00:00.0
2021	PO5789820779	KU	2	50 UNK	SP	CCA			V	00:00.0
2021	PO5792321023	KU	2	50 UNK	SP	CRE			BD	00:00.0
2021	PO4469088024	LGE	4	35 BRO	SP	A			V	00:00.0
2021	PO4469788030	LGE	4	40 BRO	SP	CRE	ED, ID, IP		TD	00:00.0
2021	PO4469988026	LGE	4	30 BRO	SP	CRE	ID		BD	00:00.0
2021	PO0446246386	KU	4	45 BRN	SP	CRE	ID		TD	00:00.0
2021	PO0473646091	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021	PO4469888051	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021	PO4468688069	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4469288060	LGE	4	40 BRO	SP	CRE	ID, IP		BD	00:00.0
2021	PO4470388043	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4470888035	LGE	4	40 BRO	SP	CRE	ED, ID, IP		TD	00:00.0
2021	PO4471688023	LGE	4	40 BRO	SP	CRE	ED, ID, IP		TD	00:00.0
2021	PO0485545925	KU	4	40 BRN	SP	CRE	ID		TD	00:00.0
2021	PO4473788018	F	4	30 BRO	SP	CRE			V	00:00.0
2021	PO4472788011	F	4	35 BRO	SP	A			V	00:00.0
2021	PO0491845738	KU	4	45 BRN	SP	CRE	ID		TD	00:00.0
2021	PO0500245354	KU	3	45 BRN	SP	CRE	ID		TD	00:00.0
2021	PO0511145631	KU	4	40 BRN	SP	CRE	ID		BD	00:00.0
2021	PO0528945248	KU	4	40 BRN	SP	CCA			T	00:00.0
2021	PO4474088024	LGE	4	35 BRO	SP	A	ED, ID, IP		TD	00:00.0
2021	PO0538745104	KU	4	40 UNK	SP	CCA			T	00:00.0
2021	PO0546244978	KU	4	40 UNK	SP	CRE	ID		TD	00:00.0
2021	PO0585944687	KU	4	40 UNK	SP	CRE	ID		TD	00:00.0
2021	PO4472688009	LGE	4	40 BRO	SP	A	ED, ID, IP		TD	00:00.0
2021	PO4473288000	LGE	4	40 BRO	SP	A	ED, ID, IP		TD	00:00.0
2021	PO0602844588	KU	5	30 UNK	SP	CRE	ID		TD	00:00.0
2021	PO0506251831	F	4	40 UNK	SP	CRE	ED, ID	BX	RR	00:00.0
2021	PO8476057482	ODP	5	35 XXX	SP	CRE	ID, IP	TX	RR	00:00.0
2021	PO4508588065	LGE	4	45 ACE	SP	CRE	ED, ID		TD	00:00.0
2021	PO5639123941	F	4	40 UNK	SP	CRE			V	00:00.0
2021	PO5634923991	F	4	40 UNK	SP	CRE			V	00:00.0
2021	PO4550887940	LGE	4	35 BRO	SP	CRE			V	00:00.0

2021 PO4522087829	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4516087797	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4517387802	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4517587821	F	4	50 BRO	SP	CCA		V	00:00.0
2021 PO4910984903	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0123340907	KU	3	40 ACE	SP	CRE		V	00:00.0
2021 PO9852343955	KU	2	50 ACE	SP	CCA		V	00:00.0
2021 PO9919543062	KU	2	60 ACE	SP	CCA		V	00:00.0
2021 PO4912284904	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4913084891	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO5170384866	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5166884887	F	3	45 ACE	SP	P		V	00:00.0
2021 PO5168784880	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO0413631414	KU	1	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0426431080	KU	1	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0432230871	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4901184794	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4900584795	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4899284814	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5143684944	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5141284957	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7980805419	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7986905343	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO5091185096	LGE	4	30 ACE	SP	CRE	ED,HH,ID	VX RP1	00:00.0
2021 PO4909084873	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO5091385112	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO5091185116	F	4	30 ACE	SP	P		V	00:00.0
2021 PO5090485103	LGE	4	40 ACE	SP	CRE	ED	TD	00:00.0
2021 PO0120240676	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4909284870	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4375585481	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4384085472	LGE	4	45E ACE	SP	CRE	ED	V	00:00.0
2021 PO4368985477	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4913884896	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5484309316	F	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5497709271	F	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4385685753	LGE	3	50 ACE	SP	CRE	ED,ID	BX RR	00:00.0
2021 PO6622296073	F	3	40 ACE	SP	P		V	00:00.0
2021 PO6616196262	F	4	40 ACE	SP	P		V	00:00.0
2021 PO5529109302	F	4	45 XXX	SP	CCA		V	00:00.0
2021 PO5555509231	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5513209295	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4925984879	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4915984879	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8163404160	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO8193304287	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO8192804363	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8213304281	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO8255804269	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO8285304341	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8270704285	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	100879937	LGE	1	50 ACE	SP	CCA	V	00:00.0
2021 PO4927284853	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4879284740	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0

2021 PO4386085752	LGE	6	25 ACE	SP	CRE	ED	TD	00:00.0
2021 PO6596795833	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6610895772	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4490887779	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6615096081	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6590596115	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6584696118	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5164084671	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4494387739	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4495287738	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4496087736	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4496687735	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5162484726	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO5162784715	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5161184737	LGE	3	45 ACE	SP	CCA	ID	BD	00:00.0
2021 PO4518887627	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4519787633	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4520787640	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4521987648	F	4	40 BRO	SP	P		V	00:00.0
2021 PO8332405762	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TX RR	00:00.0
2021 PO8325105608	KU	4	40 XXX	SP	CRE	ED,HH,ID,IP,SRC	TX RR	00:00.0
2021 PO4921885148	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4922185152	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4372185788	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021 PO4372985793	LGE	UNK	55E ACE	SP	CRE	ED	BD	00:00.0
2021 PO4370985781	LGE	4	30 ACE	SP	P	ED	TD	00:00.0
2021 PO4369685772	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO6693096127	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6698096227	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6687296712	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6695396874	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6689796761	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5187384524	LGE	3	45 ACE	SP	P		V	00:00.0
2021 PO6682196608	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6678796541	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5178184650	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8214902765	KU	3	50 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6673396431	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6669796328	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6644095970	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6644596066	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6652095974	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6654496145	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6664096213	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8301402421	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8283202578	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO8278202583	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8268602649	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8262602730	KU	4	45 XXX	SP	S		V	00:00.0
2021 PO8260202706	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8249802781	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8241402836	KU	1	60 XXX	SP	S		V	00:00.0
2021 PO8232002909	KU	1	60 XXX	SP	S		V	00:00.0
2021 PO8226302947	KU	2	60 XXX	SP	S		V	00:00.0

2021 PO8218703010	KU	1	55 XXX	SP	S		V		00:00.0
2021 PO8203803119	KU	1	55 XXX	SP	S		V		00:00.0
2021 PO8090904021	KU	2	50 XXX	SP	S		V		00:00.0
2021 PO8090904029	KU	2	50 XXX	SP	S		V		00:00.0
2021 PO8042904541	KU	3	45 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO5185184619	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO9020959468	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5182584640	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO6677896168	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6678796143	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO6673395994	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4384785747	LGE	3	50 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4868284769	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4493587741	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4492787736	LGE	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4494487746	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5163284695	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO8348605774	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO8305305367	KU	4	40 XXX	SP	CRE	ED,ID,MD,SRC	TD		00:00.0
2021 PO8312505494	KU	4	40 XXX	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO4387085715	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4489887752	LGE	4	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4489987754	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4490787758	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4491687765	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4491387762	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4870984777	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO5625308917	KU	4	40 XXX	SP	P	ID	TD		00:00.0
2021 PO5600209079	F	6	35 XXX	SP	CRE	ID	V		00:00.0
2021 PO5560909317	KU	5	35 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5574609180	KU	4	40 XXX	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO5594409116	KU	3	45 XXX	SP	CCA		TD		00:00.0
2021 PO5590009158	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5595709086	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5571709031	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5157984766	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO6583396075	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6579496147	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO6578095946	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6568795986	F	3	40 ACE	SP	P		V		00:00.0
2021 PO6554096066	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO6544596154	F	5	35 ACE	SP	CRE		V		00:00.0
2021 PO5185384641	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO6559596318	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO5180184557	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO6547396329	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO5182384554	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO5510609226	F	4	40 XXX	SP	CRE	EP	BD		00:00.0
2021 PO5512409216	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO5513109160	F	5	35 XXX	SP	P		V		00:00.0
2021 PO5528409105	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5530909155	F	3	45 XXX	SP	CCA		V		00:00.0
2021 PO5521609188	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5543909042	F	4	40 XXX	SP	CRE		V		00:00.0

2021 PO4490087847	LGE	4	35 BRO	SP	CCA	ED,ID,IP	BD		00:00.0
2021 PO4490287843	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4490187836	LGE	4	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4490087825	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4489987814	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4489887800	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4489887792	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO8887559983	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8867660163	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8848560336	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021 PO1993590250	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO1994790202	LGE	4	40 BRO	SP	CRE	ED,ID,RB	BX	RP1	00:00.0
2021 PO4489687771	LGE	4	40 BRO	SP	A	ED,ID	BD		00:00.0
2021 PO4489387757	LGE	4	40 BRO	SP	A	ED,ID,IP	BD		00:00.0
2021 PO8356704933	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO8350804882	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO8322005093	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8347905001	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4869984783	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4875784802	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO5591308998	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4923285139	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4878684719	LGE	5	25 BRO	SP	CCA		V		00:00.0
2021 PO4878984725	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4883784774	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO5155284795	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4883084754	LGE	4	40 BRO	SP	A	ID	BD		00:00.0
2021 PO4882584737	LGE	4	40 BRO	SP	A	ID	BD		00:00.0
2021 PO5158884820	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO5158184805	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO4928484836	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021 PO5153184815	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4385685735	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021 PO5177784564	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO5172884581	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO8961159306	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8948559417	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8935959528	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8922459627	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8906159790	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4874384743	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO5567708982	F	5	35 XXX	SP	P		V		00:00.0
2021 PO5552209016	F	5	35 XXX	SP	P		V		00:00.0
2021 PO5556709061	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5541509108	KU	4	40 XXX	SP	CRE	HH,ID,IP	X	RP3	00:00.0
2021 PO5646108924	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO4875084761	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO8879060261	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4386485725	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO6765197596	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO6760897481	F	5	35 ACE	SP	CRE		V		00:00.0
2021 PO6757397437	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6752597340	F	4	40 ACE	SP	P		V		00:00.0
2021 PO8237302599	KU	4	45 XXX	SP	S		V		00:00.0

2021	PO6695196121	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO5603308972	KU	4	40 XXX	SP	CRE	HH,ID,IP	TX	RR	00:00.0
2021	PO5617808934	KU	4	45 XXX	SP	CRE	ID,IP	TX	RR	00:00.0
2021	PO5464609488	F	2	45 XXX	SP	CRE		V		00:00.0
2021	PO5489809527	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO5502809538	KU	5	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO5500109747	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO5391009233	F	2	40 XXX	SP	CRE		V		00:00.0
2021	PO5160484707	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO5160884729	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4868484788	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4387885705	LGE	4	40 ACE	SP	CRE	HH	TD		00:00.0
2021	PO4388585696	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021	PO4373385799	LGE	4	30 ACE	SP	CRE	ED	TD		00:00.0
2021	PO4373985802	LGE	4	30 ACE	SP	P	ED	BD		00:00.0
2021	PO5159884685	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4869184780	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8295205190	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO6747197230	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO6742097126	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6736497010	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO9036258848	LGE	1	50 ACE	SP	CCA	ED,ID	V		00:00.0
2021	PO6730696893	F	3	45 ACE	SP	P		V		00:00.0
2021	PO6725296783	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO5187784529	LGE	3	45 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO6718996716	KU	4	30 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6721596705	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6725396699	F	5	35 ACE	SP	CRE		V		00:00.0
2021	PO4442487990	LGE	4	40 BRO	SP	CCA	ED,ID	TD		00:00.0
2021	PO4442288001	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4448188192	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4447688193	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO8841860188	ODP	4	45 BRO	SP	CRE	ED,EP,ID,MD	TX	RR	00:00.0
2021	PO4441188054	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO0563551464	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021	PO8716453114	ODP	2	50 XXX	SP	CCA		V		00:00.0
2021	PO4441988105	LGE	4	40 BRO	SP	CRE	ED,ID,IP,SR	TD		00:00.0
2021	PO4441588104	LGE	4	35 BRO	SP	P	ED,ID,SR	TD		00:00.0
2021	PO4440888089	LGE	4	35 BRO	SP	A	ED	TD		00:00.0
2021	PO4440388094	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5786528420	KU	1	60 UNK	SP	CCA		V		00:00.0
2021	PO5736928788	KU	1	55 UNK	SP	CCA		V		00:00.0
2021	PO5732028679	KU	1	55 UNK	SP	CCA		V		00:00.0
2021	PO5727928592	KU	1	55 UNK	SP	CCA		V		00:00.0
2021	PO5723928503	KU	1	55 UNK	SP	CCA		V		00:00.0
2021	PO5775528409	KU	5	35 UNK	SP	CCA		V		00:00.0
2021	PO5775528494	KU	1	55 UNK	SP	CCA		V		00:00.0
2021	PO0848248859	F	6	30 UNK	SP	CRE		V		00:00.0
2021	PO0848048754	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO0834249041	F	4	40 UNK	SP	CCA		V		00:00.0
2021	PO0830048990	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021	PO0824649176	F	5	35 UNK	SP	CRE		V		00:00.0
2021	PO0774849585	F	5	30 UNK	SP	CRE		V		00:00.0
2021	PO0780949827	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0



2021 PO4439688132	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4439588139	LGE	3	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO1498293714	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4438788123	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4440388123	F	2	40 BRO	SP	CCA		V	00:00.0
2021 PO0801249427	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0772849622	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4440688104	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4440288102	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4440088111	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8753460022	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8780360161	ODP	5	35 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO8802460281	ODP	3	45 BRO	SP	S		V	00:00.0
2021 PO8790760292	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO8752360149	ODP	5	35 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4453588237	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO1629094862	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8790459578	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8752360149A	ODP	6	30 BRO	SP	P		V	00:00.0
2021 PO8799052694	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8816752610	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8831552538	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8850252448	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO0554251470	KU	3	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4442188116	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO8806559478	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4439388057	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4439288067	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO8794460453	ODP	5	35 BRO	SP	S		V	00:00.0
2021 PO8809060281	F	5	35 BRO	DF	P		V	00:00.0
2021 PO8785360571	ODP	4	45 BRO	SP	S		V	00:00.0
2021 PO8812360484	ODP	4	40 BRO	SP	S	ED	T	00:00.0
2021 PO8811760173	ODP	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8813459864	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8792559819	F	4	40 BRO	SP	P		V	00:00.0
2021 PO8806559478	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5948928783	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5955528707	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5981428421	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5968428570	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5962128635	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO0595051445	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO8163578060	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8174578200	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO4443488057	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4442188119	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4438988076	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4439288067-A	F	5	35 BRO	SP	A		V	00:00.0
2021 PO8174778197	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO0621651428	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5956828790	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO2851290149	KU	5	45 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2821989917	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4443188070	F	4	35 BRO	SP	CRE		V	00:00.0

2021 PO2873090147	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2728190377	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2865890181	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2725090264	KU	4	45 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4438988071	F	4	30 BRO	SP	A		V	00:00.0
2021 PO0575551455	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO8876952286	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8888252227	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8781653035	F	5	35 XXX	SP	P		V	00:00.0
2021 PO8671552364	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8678252492	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5975528488	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5941628972	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO8163478212	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8163678348	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8169878345	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4444088031	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4444288021	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4447488209	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO0605451439	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4442988081	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO8163778474	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8830659947	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8834560005	ODP	6	30 BRO	SP	S		V	00:00.0
2021 PO8823959988	ODP	4	45 BRO	SP	S		V	00:00.0
2021 PO8917260216	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8872660207	F	5	35 BRO	SP	P		V	00:00.0
2021 PO8908659949	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4437988120	F	4	35 BRO	SP	A		V	00:00.0
2021 PO8929759904	ODP	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4445287999	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4444087996	LGE	4	40 BRO	SP	A	ED,EP,ID	TD	00:00.0
2021 PO4441388043	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4441188044	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4438588099	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4441688032	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4438488108	F	4	35 BRO	SP	A		V	00:00.0
2021 PO5933727728	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4439088071	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO5941927642	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO8708552548	ODP	3	45 XXX	SP	CCA		V	00:00.0
2021 PO8684152604	ODP	6	30 XXX	SP	CRE	ED	T	00:00.0
2021 PO5920627866	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO4443788044	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4444488012	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4444088011	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO0637251418	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4442088010	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0652351408	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0888748365	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO8163878611	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8148778742	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8162978754	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8153478939	KU	6	30 ACE	SP	CCA		V	00:00.0

2021	PO4438788088	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO5950827529	KU	5	35 UNK	SP	CRE		T	00:00.0
2021	PO4440988064	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO0873448385	KU	5	30 UNK	SP	CRE	ID	TD	00:00.0
2021	PO0871048544	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO0772850796	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO0854048778	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO4442687980	LGE	4	40 BRO	SP	P	ED,EP,ID	TD	00:00.0
2021	PO5880127947	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5859027771	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO5855727813	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO5850827864	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO4441988021	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	A5882327830	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5887727770	KU	5	35 UNK	SP	CCA		V	00:00.0
2021	PO5882327830	KU	5	35 UNK	SP	CCA		V	00:00.0
2021	PO5895327687	KU	4	45 UNK	SP	CCA		V	00:00.0
2021	PO5761828596	KU	1	55 UNK	SP	CCA		V	00:00.0
2021	PO5752128670	KU	1	55 UNK	SP	CCA		V	00:00.0
2021	PO4440188042	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO2938989503	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO2955689338	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO2948289340	F	5	35 BRO	SP	CCA		V	00:00.0
2021	PO5893827522	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO4464688361	F	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4463888358	F	1	65 ACE	SP	CCA		V	00:00.0
2021	PO8783752573	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8770452631	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8783352767	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8767952845	ODP	4	50 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8697953215	ODP	2	50 XXX	SP	CCA		V	00:00.0
2021	PO8680153302	ODP	2	50 XXX	SP	CCA		V	00:00.0
2021	PO8661753390	ODP	2	50 XXX	SP	CCA		V	00:00.0
2021	PO5909527886	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5904527686	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO8791259418	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO8841160400	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO8957059127	F	5	30 BRO	SP	CRE		V	00:00.0
2021	PO8983659383	ODP	4	45 BRO	SP	S		V	00:00.0
2021	PO8977559119	ODP	4	45 BRO	SP	S		V	00:00.0
2021	PO8733852482	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021	PO8719652514	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021	PO8752852646	ODP	6	30 XXX	SP	A	ID	TD	00:00.0
2021	PO4443587995	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	34993214596	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4454088190	F	4	35 ACE	SP	CRE		V	00:00.0
2021	PO5831028110	KU	1	65 UNK	SP	CCA		V	00:00.0
2021	PO5830428096	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO5829628089	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PV3461014200	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4440688082	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO0808049314	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO2817789969	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO2711390451	KU	4	40 BRO	SP	CRE	ED,IP,SRS	BD	00:00.0

2021 PO4453888197	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4453688206	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4453588218	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4453288231	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4453088243	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4452988249	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO1643694144	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO1640194310	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO1637294447	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8752360149B	ODP	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2833989926	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8324078991	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8215478672	F	5	35 ACE	SP	CRE		V	00:00.0
2021 PO8726465705	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8752765533	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4444988257	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4474188296	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4444388293	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8526964603	ODP	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8107978016	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO6104728275	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO4474888222	LGE	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4442488292	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4444788278	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4444788077	LGE	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4444588084	LGE	3	45 BRO	SP	CCA	ED,ID	BD	00:00.0
2021 PO4452987982	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4451287988	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4451787973	LGE	4	35 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4453387990	LGE	4	40 BRO	SP	CCA	ED,ID	BD	00:00.0
2021 PO4444888074	LGE	3	45 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4473288314	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4470288375	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4444388297	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4444388266	LGE	3	35 ACE	SP	CCA		V	00:00.0
2021 PO8202178661	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8258278986	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8118677626	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4450387985	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4447788077	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4446188108	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4445088134	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8547452022	ODP	6	30 XXX	SP	CRE		V	00:00.0
2021 PO4446788113	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO8841960501	ODP	6	30 BRO	SP	CRE		V	00:00.0
2021 PO4442588295	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO8743560007	ODP	6	30 BRO	SP	CRE		V	00:00.0
2021 PO6080127722	KU	6	30 UNK	UN	CRE		V	00:00.0
2021 PO8765259293	ODP	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4439987880	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4473988300	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4474888243	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8271079003	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6049728172	KU	5	35 UNK	SP	CRE		B	00:00.0

2021 PO4452987996	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4444688275	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4446788297	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO6087828415	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO8323479462	F	3	45 ACE	SP	CRE	ED,HH,ID,RB	VX	PX	00:00.0
2021 PO4445088249	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4445588038	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4444888139	F	4	35 BRO	SP	P		V		00:00.0
2021 PO9002865384	ODP	4	40 XXX	SP	CCA		V		00:00.0
2021 PO8722960136	ODP	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO8722160346	ODP	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4478788001	F	4	40 BRO	SP	P		V		00:00.0
2021 PO4483388022	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4484388026	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7639794567	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4264611610	KU	2	45 BRN	SP	CCA		V		00:00.0
2021 PO4265711643	KU	2	45 BRN	SP	CCA		V		00:00.0
2021 PO4259911438	KU	2	50 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO4261711617	KU	7	35 BRN	SP	CCA		V		00:00.0
2021 PO4964123225	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021 PO7652494344	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4456387811	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4982623262	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021 PO4950222811	KU	5	35 BRO	SP	CRE	ED,ID	BX	PX	00:00.0
2021 PO4961322984	KU	4	45 BRO	SP	CRE	ED	BD		00:00.0
2021 PO7702893417	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7714193213	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7732093580a	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7732093580	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4964722727	KU	4	45 BRO	SP	CRE	ED	BD		00:00.0
2021 PO4975522659	KU	4	40 BRO	SP	CRE		T		00:00.0
2021 PO4989322592	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO4482588566	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4483988562	LGE	4	45 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO5098108786	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5085008442	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5093608668	KU	5	35 BRN	DF	CRE	ED,ID,IP	TD		00:00.0
2021 PO5089908569	KU	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO5085708302	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4484288009	LGE	4	40 BRO	SP	CRE	ED,EP,ID,RB	X	PX	00:00.0
2021 PO4485388014	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4486288015	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4486188017	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4477787975	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4478487960	F	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4477287977	F	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4478687955	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4477987968	F	4	30 BRO	SP	P		V		00:00.0
2021 PO4476787985	F	4	30 BRO	SP	P		V		00:00.0
2021 PO4476287992	F	4	30 BRO	SP	A		V		00:00.0
2021 PO4476087995	F	4	30 BRO	SP	A		V		00:00.0
2021 PO4475588002	F	4	30 BRO	SP	CRE		V		00:00.0
2021 PO4475188009	F	4	35 BRO	SP	CCA		V		00:00.0
2021 PO7827590871	F	4	40 ACE	SP	CCA		V		00:00.0

2021 PO7758392159	F	4	45 ACE	SP	P		V	00:00.0
2021 PO7531494255	KU	5	35 ACE	UN	CRE		V	00:00.0
2021 PO8609583580	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8607683422	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5301012438	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8602383426	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8581583446	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8558783466	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4479588596	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4479288594	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8471584609	KU	4	40 ACE	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO4480288578	LGE	4	45 ACE	SP	CRE		V	00:00.0
2021 PO4479588562	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4480788515	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4480988511	LGE	4	60 ACE	SP	CCA		V	00:00.0
2021 PO8484084342	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4485288451	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4486188454	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4487188458	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4488388462	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4488988463	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4489588465	F	4	35 ACE	SP	A		V	00:00.0
2021 PO4490688470	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4492788491	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8490884489a	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8490884489	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8500984568	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4492188502	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4208910218	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4494988481	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4494188481	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4493388470	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4492988480	LGE	3	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4492988485	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8523884572	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8551183460	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5033209161	KU	4	45 BRN	SP	S		V	00:00.0
2021 PO5032709016	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5028609059	KU	4	45 BRN	SP	S		V	00:00.0
2021 PO4492488516	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4493388521	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4493288524	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5004008951A	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO5014009011	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5004008951	KU	4	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5006008985	KU	5	35 BRN	SP	S		V	00:00.0
2021 PO8539083463	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5298812529	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5298412623	KU	4	45 BRN	SP	CRE	ED,ID,JP	BD	00:00.0
2021 PO4216910296	KU	2	45 BRN	SP	CCA		V	00:00.0
2021 PO4240110731	KU	3	50 BRN	SP	CCA		T	00:00.0
2021 PO4237310637	KU	2	60 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO4221910470	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7748392602	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0

2021 PO4307611610	KU	5	35 BRN	SP	CCA			V	00:00.0
2021 PO4299711646	KU	2	45 BRN	SP	CCA			V	00:00.0
2021 PO4481488472	LGE	4	40 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO7755492474	KU	5	35 ACE	SP	CCA			V	00:00.0
2021 PO7762092356	KU	5	35 ACE	SP	CRE		ED,ID	TD	00:00.0
2021 PO7769292214	KU	4	45 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO7777692081	KU	5	35 ACE	SP	CRE		ED,HH,ID,RB	BX PX	00:00.0
2021 PO4937823441	KU	4	40 BRO	SP	CRE		ED,ID	BX RP2	00:00.0
2021 PO4937123574	KU	4	40 BRO	SP	CRE		ED	BD	00:00.0
2021 PO4930923498	KU	4	40 BRO	SP	CRE		ID	BD	00:00.0
2021 PO4922423568	KU	4	40 BRO	SP	CRE		ED,ID	BD	00:00.0
2021 PO4909523674	KU	4	40 BRO	SP	CRE		ED,ID	BD	00:00.0
2021 PO4901823147	KU	4	40 BRO	SP	CRE		ID	BD	00:00.0
2021 PO4442187805	F	4	40 BRO	SP	A			V	00:00.0
2021 PO4294011925	KU	2	50 BRN	SP	CCA			V	00:00.0
2021 PO4299212110	KU	2	50 BRN	SP	CCA			V	00:00.0
2021 PO7782391975	KU	5	35 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO4882123301	KU	4	40 BRO	SP	CRE		ED,ID	BD	00:00.0
2021 PO4894923202	KU	3	45 BRO	SP	CRE		ID	BD	00:00.0
2021 PO4442687813	LGE	4	40 BRO	SP	A		ID,IP	BD	00:00.0
2021 PO4863923051	KU	4	40 BRO	SP	CRE			T	00:00.0
2021 PO4854322913	F	4	40 BRO	SP	CRE			V	00:00.0
2021 PO4874223193	KU	4	45 BRO	SP	CCA			V	00:00.0
2021 PO4829624447	KU	4	40 BRO	SP	CCA			V	00:00.0
2021 PO4834724453	KU	4	40 BRO	SP	CCA			V	00:00.0
2021 PO4443387813	LGE	3	45 BRO	SP	A		ID,IP	BD	00:00.0
2021 PO4242910827	KU	2	50 BRN	SP	CRE			B	00:00.0
2021 PO7793191799	KU	5	35 ACE	SP	CRE		ED,ID	TD	00:00.0
2021 PO4839424255	KU	4	40 BRO	SP	CRE			T	00:00.0
2021 PO4844524020	KU	3	45 BRO	SP	CCA			V	00:00.0
2021 PO4824524342	KU	4	40 BRO	SP	CRE		ED	BD	00:00.0
2021 PO7806091555	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO7839291458	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO7817191358	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO7831991108	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO7839290972	KU	4	40 ACE	SP	CRE		ED,ID	TD	00:00.0
2021 PO7842790910	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO7854190702	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO7865990482	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO7877390277	KU	4	40 ACE	SP	CRE		ED,ID	TD	00:00.0
2021 PO4441487813	LGE	3	45 BRO	SP	CRE		ID,IP	BD	00:00.0
2021 PO4440487814	LGE	4	40 BRO	SP	CRE		ID,IP	BD	00:00.0
2021 PO4439287814	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021 PO4438187814	LGE	4	40 BRO	SP	A		ID,IP	BD	00:00.0
2021 PO4859524346	KU	2	40 BRO	SP	CRE		ED	BD	00:00.0
2021 PO4863824143	KU	4	40 BRO	SP	CRE			T	00:00.0
2021 PO4868824091	KU	4	40 BRO	SP	CRE		ED	BD	00:00.0
2021 PO4826123895	KU	3	45 BRO	SP	CCA			V	00:00.0
2021 PO4437387814	LGE	4	40 BRO	SP	CRE		ID,IP	BD	00:00.0
2021 PO7894689981	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO4436387813	LGE	3	45 BRO	SP	CRE		ID,IP	BD	00:00.0
2021 PO7908789712	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO7924489430	KU	4	40 ACE	SP	CRE		ED,ID	TD	00:00.0
2021 PO4435287812	LGE	3	45 BRO	SP	CCA			V	00:00.0

2021 PO4433487802	LGE	1	60 BRO	SP	CRE		V		00:00.0
2021 PO4434187804	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021 PO7941089130	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO7960288783	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO7624077218	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO7622677477	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4466088201	LGE	4	40 ACE	SP	A	ED,ID	BX	RR	00:00.0
2021 PO4893025409	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4466588200	F	6	35 ACE	SP	CRE		V		00:00.0
2021 PO4880025342	KU	4	45 BRO	SP	CRE		T		00:00.0
2021 PO4280512772	KU	2	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4881125129	KU	4	40 BRO	SP	CRE	ED	T		00:00.0
2021 PO4888525133	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021 PO4880625208	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4856525321	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4842025296	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4484788443	LGE	3	45 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO4467188167	LGE	3	50 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4468588170	LGE	3	45E ACE	SP	P	ED	TD		00:00.0
2021 PO4482088445	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4482488439	F	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4483288438	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4483088442	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4523387447	F	4	40 BRO	SP	P		V		00:00.0
2021 PO4290713071	KU	3	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO7538077648	KU	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO7532977712	KU	5	35 ACE	SP	CCA		V		00:00.0
2021 PO2797088576	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4481088434	F	4	35 ACE	SP	CCA		V		00:00.0
2021 PO2827488552	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4481688431	LGE	3	45 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO7519277613	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7519277679	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4298913047	KU	3	45 BRN	SP	CRE	ID,MD	BD		00:00.0
2021 PO4298413145	KU	3	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4476787492	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7551777630	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4850425000	KU	1	55 BRO	SP	CRE		T		00:00.0
2021 PO7552177481	KU	4	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4932207359	KU	6	30 BRN	SP	S		V		00:00.0
2021 PO4940407324	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4939307536	KU	6	30 BRN	SP	S		V		00:00.0
2021 PO4947307503	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4933307764	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4954107677	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4946207708	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4954707622	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4954207911	KU	6	30 BRN	SP	S	ED	T		00:00.0
2021 PO4962607875	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4540987829	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4549487885	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4546387865	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4548187882	LGE	4	30 BRO	SP	P	ED,EP,ID,IP	TD		00:00.0
2021 PO4542787841	LGE	4	40 BRO	SP	A	ED,ID	BD		00:00.0



2021 PO4546287846	LGE	4	40 BRO	SP	A	ED,ID	BD	00:00.0	
2021 PO4545187862	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4547487872	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4545287858	LGE	4	40 BRO	SP	P	ED,EP,ID,IP	TD	00:00.0	
2021 PO4541887841	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4542587842	LGE	4	30 BRO	SP	P	ED,ID,IP	TD	00:00.0	
2021 PO4544487852	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4549387890	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4472588081	LGE	3 45E	ACE	SP	A	ED	TD	00:00.0	
2021 PO4473188073A	LGE	3 45E	ACE	SP	A	ED	BD	00:00.0	
2021 PO4258612823	KU	4	40 BRN	SP	CRE		T	00:00.0	
2021 PO4484988608	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO5155009371	F	6	35 BRN	SP	P		V	00:00.0	
2021 PO5142609454	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5144009303	F	4	40 BRN	SP	S		V	00:00.0	
2021 PO5140609188	F	4	40 BRN	SP	S		V	00:00.0	
2021 PO5137309080	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5135809019	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5132808944	F	4	40 BRN	DF	CRE		V	00:00.0	
2021 PO5127708866	KU	4	40 BRN	SP	S		V	00:00.0	
2021 PO5126508812	F	4	40 BRN	SP	S		V	00:00.0	
2021 PO4484288626	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO4483888624	LGE	1	50 ACE	SP	CCA		V	00:00.0	
2021 PO4303913451	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO5090609031	KU	3	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO5078909083	KU	3	45 BRN	SP	S		V	00:00.0	
2021 PO4931308181	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5503912981	F	4	40 KOP	SP	P		V	00:00.0	
2021 PO5543612621	F	5	40 OTH	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO4481688658	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4477388718	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4478188709	LGE	4	35 ACE	SP	CCA	ED,ID	TD	00:00.0	
2021 PO4478888693	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO7625978075	KU	3	45 ACE	SP	CRE		V	00:00.0	
2021 PO5117509523	KU	1	60 XXX	SP	CRE		V	00:00.0	
2021 PO5138509535	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO5139709586	KU	2	70 XXX	SP	CRE	ID,IP	TD	00:00.0	
2021 PO4985306927	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4956507185	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4965507387	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4974006953	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4987406974	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4990507052	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4994107134	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4997807222	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5001607309	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4972007528	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5000707698A	KU	6	35 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO4428088920	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4684826765	F	4	40 BRO	SP	CRE	ED,ID	VX	PX	00:00.0
2021 PO4791827056	F	3	40 OTH	SP	P		V	00:00.0	
2021 PO4765227059	F	4	40 OTH	SP	CRE	ED	V	00:00.0	
2021 PO4772227028	F	3	40 OTH	SP	P		V	00:00.0	
2021 PO4743826820	F	4	40 OTH	SP	CRE	ED,EP,ID	BX	RP2	00:00.0

2021	PO4736426885	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO4740626992	F	4	40 OTH	SP	CRE	ED,HH,ID	BX	RP1	00:00.0
2021	PO4756027038	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021	PO4774426553	F	4	40 OTH	SP	P		V		00:00.0
2021	PO4417889026	LGE	4	35 ACE	SP	P	ED	BD		00:00.0
2021	PO4508987988	LGE	4	45 ACE	SP	A	ED	TD		00:00.0
2021	PO4484987405	LGE	4	30 BRO	SP	CRE	ID	BD		00:00.0
2021	PO4428888990	LGE	3	45 ACE	SP	CRE		V		00:00.0
2021	PO4799425717	KU	2	50 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4484787412	LGE	3	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4805425364	KU	2	60 BRO	ST	CCA		V		00:00.0
2021	PO4429888998	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4430589005	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4508387997	LGE	4	45 ACE	SP	CRE	ED,IP	TD		00:00.0
2021	PO4457187991	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4457887995	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4434589035	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4675626846	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4680726683	KU	6	30 BRO	SP	CRE	ED	BD		00:00.0
2021	PO4425488952	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO7218947127	KU	4	40 BRO	SP	CRE	ED,HH,IP,RB	X	RP2	00:00.0
2021	PO7229147115	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO7235347108	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO7173646942	KU	6	30 BRO	SP	CCA		V		00:00.0
2021	PO4634826692	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4634126716	KU	6	30 BRO	SP	CCA		V		00:00.0
2021	PO4627926756	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4432589017	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4430889002	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4431589008	LGE	3	45 ACE	SP	CRE	ED	BD		00:00.0
2021	PO4433689027	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4433889028	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4507387995	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4507788007	LGE	4	45 ACE	SP	CRE	ED,IP	TD		00:00.0
2021	PO4507088017	LGE	4	45 ACE	SP	P	ED,IP	TD		00:00.0
2021	PO4449587940	LGE	3	50 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4448287940	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021	PO4446087938	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4618926735	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4614526700	KU	4	40 BRO	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021	PO4445587938	LGE	4	45 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4671425165	KU	3	50 BRO	SP	CRE		T		00:00.0
2021	PO1357801460	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4541488061	LGE	4	45 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO1336601273	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO1350501329	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4837012691	F	3	45 BRN	SP	P		V		00:00.0
2021	PO4845112859	F	5	40 BRN	SP	P		V		00:00.0
2021	PO4846112976	F	4	40 BRN	SP	P		V		00:00.0
2021	PO4750210996	F	6	40 BRN	SP	CCA		V		00:00.0
2021	PO4755111109	F	3	40 BRN	SP	CRE		V		00:00.0
2021	PO4757011148	F	6	40 BRN	SP	CCA		V		00:00.0
2021	PO4760311230	F	7	40 BRN	SP	CCA		V		00:00.0
2021	PO4767111380	F	7	40 BRN	SP	CCA		V		00:00.0

2021 PO4857328102	F	4	40 OTH	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021 PO4861928218	F	4	40 OTH	SP	CRE	ED,HH	BX	RP1	00:00.0
2021 PO4853428009	F	4	40 OTH	SP	P	ED	V		00:00.0
2021 PO4850027921	F	4	40 OTH	SP	CRE	ED,HH	BX	RP2	00:00.0
2021 PO4846227827	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021 PO4841227716	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021 PO4836527643	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021 PO4827327390	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO4827727498	F	4	40 OTH	SP	P		V		00:00.0
2021 PO4763526648	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021 PO4822027386	F	3	40 OTH	SP	P		V		00:00.0
2021 PO4816527316	F	4	40 OTH	SP	CCA		V		00:00.0
2021 PO4419089005	LGE	4	35 ACE	SP	CRE	ED	VX	RP3	00:00.0
2021 PO4420288993	LGE	4	35 ACE	SP	CRE	ED	V		00:00.0
2021 PO4485287755	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4512687958	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4424488976	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4510787960	LGE	4	45 ACE	SP	CRE	ED,IP	TD		00:00.0
2021 PO4510287969	LGE	4	45 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4422188963	LGE	4	35 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4487787729	LGE	4	40 BRO	SP	A	ID	BD		00:00.0
2021 PO4422988954	LGE	4	35 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4423688946	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO4486187742	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4425188956	LGE	3	50 ACE	SP	CRE	ED,HH,ID,RB	X	RR	00:00.0
2021 PO4656208001	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4721807734	F	4	40 XXX	SP	S		V		00:00.0
2021 PO4682008005	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4706308058	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4669608002	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4632008019	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4703307696	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4749408435	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4630008092	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4719207696	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4703608010	F	4	40 XXX	SP	S		V		00:00.0
2021 PO4694008008	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4745508327	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4689607694	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4644907999	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7209247139	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO1396001956	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4431888946	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4537288043	F	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4539188051	LGE	2	65 ACE	SP	CRE	ED,ID	BX	RR	00:00.0
2021 PO4538788050	F	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4773911539	F	5	40 BRN	SP	CRE		V		00:00.0
2021 PO4788511875a	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4541588061	LGE	4	45 ACE	SP	CRE	ED,ID,MD	BD		00:00.0
2021 PO4542688072	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4438889044	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4437789033	LGE	4	40 ACE	SP	CCA	ED,ID	TD		00:00.0
2021 PO4439189032	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4504487935	LGE	4	40 ACE	SP	CCA		V		00:00.0

2021	PO4504987927	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4504887923A	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4504887923	F	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4505687917	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4506287906	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4506987898	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4507387889	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4554087897	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4556387922	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4555987927	LGE	3	45 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4557287935	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4550587892	LGE	4	40 BRO	SP	A	ED,ID	BD	00:00.0
2021	PO4558087941	LGE	4	40 BRO	SP	P	ED,EP,ID,RB	BD	00:00.0
2021	PO4558887946	LGE	4	40 BRO	SP	P	ED,ID	V	00:00.0
2021	PO4552587912	LGE	4	30 BRO	SP	A	ED,EP,ID,RB	BD	00:00.0
2021	PO4555687932	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4528887515	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4533087420	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4533287422	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4559787951	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4554387917	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4709525217	KU	3	50 BRO	SP	CRE		T	00:00.0
2021	PO4506688024	LGE	4	45 ACE	SP	CRE	ED,IP	TD	00:00.0
2021	PO2163092707	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4441887937	LGE	3	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4688125187	KU	3	75 BRO	ST	CCA		V	00:00.0
2021	PO4728325243	KU	3	50 BRO	ST	CCA		V	00:00.0
2021	PO4752225277	KU	3	55 BRO	ST	CCA		V	00:00.0
2021	PO4441788977	LGE	2	65 ACE	SP	CCA		V	00:00.0
2021	PO4441387937	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4505888035	LGE	4	45 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4505888043	LGE	4	35 ACE	SP	A	ED,IP	TD	00:00.0
2021	PO4440888988	F	1	55 ACE	SP	CRE		V	00:00.0
2021	PO4439689002	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4438989010	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4438189018	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4437289028	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021	PO4438387936	LGE	3	50 BRO	SP	CRE	ID	BD	00:00.0
2021	PO4436389051	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4437389061	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4472088114	LGE	1	50 BRO	SP	A		V	00:00.0
2021	PO4438589071	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4505288045	LGE	4	45 ACE	SP	CRE	ED	TD	00:00.0
2021	PO4643425141	KU	3	50 BRO	ST	CCA		V	00:00.0
2021	PO4439489079	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4753226738	F	4	40 OTH	SP	CRE	ED,ID,JP	V	RP2 00:00.0
2021	PO4791312623	F	7	40 BRN	SP	CRE		V	00:00.0
2021	PO4826213193	F	6	45E BRN	SP	CRE		V	00:00.0
2021	PO4818313034	F	2	40 BRN	SP	P		V	00:00.0
2021	PO4807612825	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4800612688	F	7	35 BRN	SP	CRE		V	00:00.0
2021	PO4416089054	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021	PO4416789043	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021	PO4509587978	LGE	4	45 ACE	SP	CRE	ED,ID	TX	RR 00:00.0

2021 PO4426188964	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4794225868	KU	3	45 BRO	SP	A		BD	00:00.0	
2021 PO4764726157	KU	3	45 BRO	SP	CRE		BD	00:00.0	
2021 PO4777325999	KU	3	45 BRO	SP	CRE		BD	00:00.0	
2021 PO4789325901	KU	3	45 BRO	SP	CRE		BD	00:00.0	
2021 PO4486287417	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4427288973	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4427988983	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4803625470	KU	2	50 BRO	SP	CRE	ED	BD	00:00.0	
2021 PO4791325480	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4775525309	KU	3	55 BRO	ST	CCA		V	00:00.0	
2021 PO4509087985	LGE	4	45 ACE	SP	A	ED	TD	00:00.0	
2021 PO4431389012	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4534087784	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4537487806	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0	
2021 PO4551587899	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4534887789	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4555587936	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4555187922	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4552887907	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4551487903	LGE	4	30 BRO	SP	CRE	ED,HH,ID,RB	TX	RR	00:00.0
2021 PO4553487908	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4560387955	LGE	4	40 BRO	SP	CRE	ED,ID,IP,MD	BD	00:00.0	
2021 PO2170391282	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4510187855	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4509887858	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4419888919	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4509987865	LGE	4	35 ACE	SP	A	ED	BD	00:00.0	
2021 PO4512487871	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0	
2021 PO4421088928	LGE	3	50 ACE	SP	CCA	ED	TD	00:00.0	
2021 PO4510387870	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4422288936	LGE	3	50 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO4511187875	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4511387879	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4510987886	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4510487894	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4509887904	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4509287913	LGE	4	40 ACE	SP	P	ED	BD	00:00.0	
2021 PO4508687923	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4431689015	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4507787999	LGE	4	35 ACE	SP	P	ED	TD	00:00.0	
2021 PO4583627878	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4575527980	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4453987969	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4508088002	LGE	4	45 ACE	SP	CRE	ED,ID	V	00:00.0	
2021 PO4641427251	KU	3	40 BRO	SP	CRE		BD	00:00.0	
2021 PO4665826934	KU	3	45 BRO	SP	CRE	ED	BD	00:00.0	
2021 PO4428288974	F	3	45 ACE	SP	P		V	00:00.0	
2021 PO4452887962	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO4450687947	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO4426488961	F	4	35 ACE	SP	P		V	00:00.0	
2021 PO4788511875	F	6	40 BRN	SP	CCA		V	00:00.0	
2021 PO4794812022	F	4	45 BRN	SP	CRE		V	00:00.0	
2021 PO4415789078	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0	

2021 PO4507487942	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4507187928	LGE	4	30 ACE	SP	P	ED	BD		00:00.0
2021 PO4416689069	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4800712160	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO4806812302	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO4488987713	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4415589062	LGE	4	35 ACE	SP	P	ED	BD		00:00.0
2021 PO4414989073	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4507987933	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4489387699	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4820212614	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4508787929	F	4	45 ACE	SP	CRE		V		00:00.0
2021 PO4810327236	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021 PO4837012691a	F	4	45 BRN	SP	P		V		00:00.0
2021 PO4451588595	F	4	25 ACE	SP	CRE		V		00:00.0
2021 PO4757408640	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4754208559	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4737609131	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4843407798	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO4825608068	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4820707959	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4810908000	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4787008475	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4803308088	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4745112500	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO4753812514	KU	7	30 BRN	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO4454488497	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4758012712	F	5	40 BRN	SP	CRE		V		00:00.0
2021 PO4521888023	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4521388031	LGE	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4520688043	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO6713196480	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6709295989	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6717196615	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6713896551	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6708096431	F	3	45 ACE	SP	P		V		00:00.0
2021 PO6703296335	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6702095977	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO6689895817	F	4	40 ACE	SP	P		V		00:00.0
2021 PO2658780618	F	4	40 ACW	SP	CRE		V		00:00.0
2021 PO2597580032	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO2580879941	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO2555779816	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO2614280119	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO6968067074	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO2706576096	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO2491581189	F	6	30 UNK	SP	CRE		V		00:00.0
2021 PO2496681091	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO2527581178	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO2550481170	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO2572081166	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO2398681170	F	4	40 UNK	SP	CCA		V		00:00.0
2021 PO2423681188	F	4	40 UNK	SP	A		V		00:00.0
2021 PO2706575827	KU	3	45 BRO	SP	CCA		V		00:00.0

2021 PO2709075567	KU	3	50 BRO	SP	CCA	V	00:00.0
2021 PO5862214546	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4953410035	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO4691113459	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO4684513489	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 PO3603816003	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4686913161	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO4708913016	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO3517614233	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO7331314425	KU	4	45 BRO	SP	CCA	V	00:00.0
2021 PO7346314471	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO7365313963	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2454181206	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO3159416197	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO2835875612	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO2718675522	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2713575466	KU	2	50 BRO	SP	CCA	V	00:00.0
2021 PO2736174965	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2730975079	KU	3	45 BRO	SP	CRE	V	00:00.0
2021 PO2808976227	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO2816176243	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO2829775728	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2819076079	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2818275939	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4717110657	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO6182620201	KU	4	45 BRO	SP	CCA	V	00:00.0
2021 PO6181619943	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO2925572498	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO2425377042	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO2835474869	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2856872234	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO2827572170	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO2809572158	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO4813610227	KU	6	30 BRO	SP	CCA	V	00:00.0
2021 PO4935811329	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5089413709	KU	2	55 BRO	SP	CCA	V	00:00.0
2021 PO5116213806	KU	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4720410794	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO2923871771	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO2938272188	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 PO2937372140	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO2726775237	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2763075218	KU	3	50 BRO	SP	CCA	V	00:00.0
2021 PO2300877480	KU	4	45 BRO	SP	CCA	V	00:00.0
2021 PO2676780502	F	5	30 UNK	SP	CRE	V	00:00.0
2021 PO5873011513	KU	5	45 KOP	SP	CCA	V	00:00.0
2021 PO2389278931	F	3	40 UNK	SP	P	V	00:00.0
2021 PO6210719422	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO6107719356A	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5142713901	KU	2	55 BRO	SP	CCA	V	00:00.0
2021 PO2506179427	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2374678883	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO7234167132	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO7244967270	KU	4	40 BRO	SP	CCA	V	00:00.0

2021 PO7141269014	F	4	45 BRO	SP	CRE		V	00:00.0	
2021 PO7121969087	F	2	45 BRO	SP	CRE		V	00:00.0	
2021 PO7226867472	F	4	40 BRO	SP	P		V	00:00.0	
2021 PO7214067606	F	4	40 BRO	SP	P		V	00:00.0	
2021 7196167701a	KU	4	40 BRO	SP	P		V	00:00.0	
2021 PO2795574594	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO6919766924	KU	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO6921266911	KU	4	45 UNK	SP	CRE		V	00:00.0	
2021 PO2667280714	F	6	30 UNK	SP	CRE		V	00:00.0	
2021 PO2658180757	F	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO2629480196	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO5547113809	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4839111806	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO2868881229	F	4	40 UNK	SP	P		V	00:00.0	
2021 PO2921380655	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO2909180561	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO2932380463	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO2944580933	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO2771682256	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO2790282066	F	5	35 UNK	SP	CRE		V	00:00.0	
2021 PO2809381869	F	4	40 STP	SP	CRE		V	00:00.0	
2021 PO2829781662	F	6	35 UNK	SP	CRE		V	00:00.0	
2021 PO2798481029	F	5	35 UNK	SP	CRE		V	00:00.0	
2021 PO2873080523	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO2832979870	F	4	40 UNK	SP	P		V	00:00.0	
2021 PO2847380000	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO2867480189	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO2896280460	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO3007773562	F	3	50 BRO	SP	A		V	00:00.0	
2021 PO3068371397	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO3047069855	F	3	50 XXX	SP	CRE		V	00:00.0	
2021 PO3051269800	KU	4	40 XXX	SP	CCA	ID	V	00:00.0	
2021 PO3158769696	KU	3	45 XXX	SP	CCA		V	00:00.0	
2021 PO3108069872	KU	3	45 XXX	SP	CCA		V	00:00.0	
2021 PO3263569470	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO7179268362	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO2988981459	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO3039369272	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5970518044	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO2781580455	F	5	35 UNK	SP	CRE		V	00:00.0	
2021 PO3020273333	F	2	50 BRO	SP	A		V	00:00.0	
2021 PO2749080692	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO2752780781	F	4	40 KOP	SP	P		V	00:00.0	
2021 PO2793180720	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO2782080941	F	4	40 ACW	SP	CRE		V	00:00.0	
2021 PO3068971942	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3069871667	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3027073180	F	2	50 BRO	SP	CCA		V	00:00.0	
2021 PO3036572977	F	4	50 BRO	SP	A		V	00:00.0	
2021 PO3043372808	F	3	50 BRO	SP	A		V	00:00.0	
2021 PO3051672607	KU	4	45 BRO	SP	CCA		V	00:00.0	
2021 PO4325087089	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4320387127	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4330687059	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0



2021	PO4300886998	LGE	2	50 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO4298486823	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO5014028040	KU	4	40 BRO	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021	PO5456638988	KU	4	40 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021	PO6833184855	KU	5	35 BRN	SP	CRE	ED	TD		00:00.0
2021	PO6634888920	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO6620488794	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO6618688950	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO6768085477	KU	5	35 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5890289362	KU	2	50 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5919089097	KU	2	50 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5900189270	KU	2	50 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5555406164	KU	6	30 BRO	SP	CRE	ED	TD		00:00.0
2021	PO5568805828	KU	6	30 BRO	SP	CRE	ED	TD		00:00.0
2021	PO6623788148	KU	2	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5752890629	KU	2	55 BRN	SP	CRE	SRS	TD		00:00.0
2021	PO5505504239	KU	6	30 BRO	SP	CRE	IP	TD		00:00.0
2021	PO6585288113	KU	3	55 BRN	SP	CRE	ED	TD		00:00.0
2021	PO6590488154	KU	3	55 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5761990547	KU	2	65 BRN	SP	S	SRS	TD		00:00.0
2021	PO5792890259	KU	2	55 BRN	SP	S	SRS	TD		00:00.0
2021	PO5800890186	KU	2	50 BRN	SP	CRE	SRS	TD		00:00.0
2021	PO5813890063	KU	3	45 BRN	SP	S	SRS	TD		00:00.0
2021	PO5784990334	KU	2	65 BRN	SP	CRE	SRS	TD		00:00.0
2021	PO5492904900	KU	5	35 BRO	SP	CRE	ED	TD		00:00.0
2021	PO5826189953	KU	2	50 BRN	SP	CRE	SRC,SRS	TD		00:00.0
2021	PO5495204581	KU	6	30 BRO	SP	CRE	ED	TD		00:00.0
2021	PO3924606988	KU	4	40 BRN	SP	P	ED,ID	TD		00:00.0
2021	PO5362502624	KU	3	40 XXX	SP	P	ED,ID	TD		00:00.0
2021	PO5547400131	KU	3	40 XXX	SP	P	ED,ID	TD		00:00.0
2021	PO5214001747	KU	3	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5219301907	KU	3	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5552405441	KU	6	30 BRO	SP	CRE	ED	TD		00:00.0
2021	PO5537205272	KU	5	35 BRO	SP	CRE	ED	TD		00:00.0
2021	PO6784888083	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5594503488	KU	6	30 BRO	SP	CRE	ED	TD		00:00.0
2021	PO5519804265	KU	6	30 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5411503692	KU	5	30 BRN	SP	CRE	ED	TD		00:00.0
2021	PO4324587094	LGE	2	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4319187136	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4322187112	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4323787100	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4323087105	LGE	2	50 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4316887106	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4317887152	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4318587141	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4328787081	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4326287050	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4331587071	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4323287056	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4331187076	LGE	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4330687039	LGE	6	25 BRO	SP	CRE	ED,EP,ID	TD		00:00.0
2021	PO4332587065	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4299686940	LGE	2	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0

2021 PO4298986887	LGE	2	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4295486822	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4298486827	LGE	2	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4330087051	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4299986962	LGE	2	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4300686993	LGE	2	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4302087042	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4299786768	LGE	2	50 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4318387094	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4319787099	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4315387118	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4317587070	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6970821206	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3059070145	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2848175377	KU	2	60 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2856275325	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5513638582	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7190572637	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6694621131	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7049069041	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7198372651	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7111072922	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7136172970	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5549438673	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6951367453	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7086172733	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6969767744	KU	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7070972604	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7194168479	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7008567908	KU	3	50 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7029768083	KU	4	35 UNK	SP	CCA	ED,ID	TD	00:00.0
2021 PO3071570796	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3066970589	KU	3	50 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6001117836	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6857521054	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6698421297	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6858821208	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6911921206	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2744680557	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO2944574313	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2955674176	KU	2	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2967674034	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7281067114	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6947871467	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7265667170	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7184468299	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6993567370	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6955071982	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6932372143	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7024271219	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7044770948	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7046370588	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7052170139	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7049870360	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0

2021	PO7053269930	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO7121472291	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6982566948	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7080072704	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6975667532	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5038227992	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2850370184	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2841070017	KU	6	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2886472384	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5185727929	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5154527899	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7154668908	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7003166775	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7027366793	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7178168719	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2417877610	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO2411478084	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5255527998	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021	PO5279728257	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021	PO5276828531	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7106072493	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5221927967	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO8158484204	F	6	30 ACE	SP	CRE		V	00:00.0
2021	PO8153084197	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8140484872	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8131584937	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8160184109	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO7742880641	KU	1	80 ACE	ST	CRE		V	00:00.0
2021	PO5097484604	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4851985599	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4851185599	LGE	6	25 ACE	SP	CRE		V	00:00.0
2021	PO4591112018	KU	5	35 KOP	SP	S		V	00:00.0
2021	PO4579812004	F	4	40 KOP	SP	CRE		V	00:00.0
2021	PO4529012338	F	4	40 KOP	SP	P		V	00:00.0
2021	PO4563012114	F	4	40 KOP	SP	P		V	00:00.0
2021	PO4519812505	KU	4	45 KOP	SP	CRE	ED,ID	BD	00:00.0
2021	PO4510312557	KU	4	45 KOP	SP	S		V	00:00.0
2021	PO4546912285	KU	1	65 KOP	ST	CCA		V	00:00.0
2021	PO4518312474	KU	1	65 KOP	ST	S		V	00:00.0
2021	PO4532212382	KU	1	65 KOP	ST	CCA		V	00:00.0
2021	PO4500312596	KU	1	65 KOP	SP	S		V	00:00.0
2021	PO4852985588	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4852585577	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO5099284597	LGE	3	50 ACE	SP	P	ED	BD	00:00.0
2021	PO5101684591	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO5103284597	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4852785552	LGE	4	30 ACE	SP	P	ED	TD	00:00.0
2021	PO5102984729	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4534387956	LGE	4	40 BRO	SP	A	ED,HH,ID,IP,RB	BX	RP2 00:00.0
2021	PO4482488516	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO1974872195	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO1978872133	KU	6	30 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021	PO2038173276	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2024873025	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0

2021	PO2011372787	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO1994472503	KU	4	40 BRO	SP	CCA		T	00:00.0
2021	PO1982872333	KU	4	45 BRO	SP	CCA	ED,SRS	T	00:00.0
2021	PO4864486140	LGE	3	45 ACE	SP	P	ED,IP,MD	TD	00:00.0
2021	PO4863486160	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PO4864486150	LGE	1	65 ACE	SP	CCA		V	00:00.0
2021	PO4869886117	F	4	35 ACE	SP	P		V	00:00.0
2021	PO4878586143	LGE	3	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4869286115	F	1	50 ACE	SP	CCA		V	00:00.0
2021	PO4869386122	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4869486113	F	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4871386121	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4872786124	F	4	45 ACE	SP	P		V	00:00.0
2021	PO4871186126	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4870486148	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021	PO4869786166	LGE	4	40 ACE	SP	P	ED,EP,ID,SRC	TD	00:00.0
2021	PO4476988602	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021	PO4476488609	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4870386192	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4874786129	F	3	45 ACE	SP	P		V	00:00.0
2021	Tel	F	5	30 ACE	SP	P		V	00:00.0
2021	PO4876186139	LGE	4	30 ACE	SP	CRE	ED,EP,IP	TD	00:00.0
2021	PO5016984908	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO5017084963	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO8046786988	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO8054686814	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4877886136	F	3	45 ACE	SP	P		V	00:00.0
2021	PO4878186127	F	4	35 ACE	SP	P		V	00:00.0
2021	PO4879686144	F	3	45 ACE	SP	P		V	00:00.0
2021	PO4880886150	F	3	45 ACE	SP	P		V	00:00.0
2021	PO4883086152	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PO4458988651	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4459588642	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4457888636	F	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4458288633	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8024287498	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4473688570	LGE	4	30 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4472688578	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4472888599	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4473488588	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4473688585	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4471888612	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4469588647	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4467688659	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021	PO4465388655	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4466588660	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4461288655	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO8169483353	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	4430089090	LGE	3	30 ACE	SP	P		V	00:00.0
2021	4438789092	LGE	3	30 ACE	SP	P		V	00:00.0
2021	4429489082	LGE	3	40 ACE	SP	CCA		V	00:00.0
2021	1387703148	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO5019084961	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	1386102997	LGE	4	30 ACE	SP	P	ED	BD	00:00.0

2021	1401203000	LGE	3	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4876586133	F	3	45 ACE	SP	P		V	00:00.0
2021	PO5021185013	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO7354163160	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO2259489695	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PV4516387706	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO2271589489	LGE	4	30 BRO	SP	P	ED,ID,RB	X PX	00:00.0
2021	PV2274589374	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4878386150	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO8024587534	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8045587684	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5034984699	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5035884702	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021	PO5034784708	F	4	40 BRO	SP	A		V	00:00.0
2021	PO5037984710	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021	PO4456488619	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4457088611	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8078387917	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8037587199	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX RP1	00:00.0
2021	PO8066586548	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021	PO4456788606	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4861786261	F	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4862486237	F	3	45 ACE	SP	CRE		V	00:00.0
2021	PO4859286187	LGE	3	50 ACE	SP	P	ED,IP	BD	00:00.0
2021	PO4341515594	KU	2	50 XXX	SP	CCA		V	00:00.0
2021	PO4337115598	KU	2	60 XXX	SP	CCA		V	00:00.0
2021	PO4322315567	KU	4	45 XXX	SP	CCA		V	00:00.0
2021	PO4331815411	KU	2	80 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4336815856	KU	2	60 XXX	SP	CCA		V	00:00.0
2021	PO4351416086	KU	2	60 XXX	SP	CCA		V	00:00.0
2021	PO4359316195	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO4342716372	KU	2	65 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4343016503	KU	3	50 XXX	SP	CRE	HH,ID	X RP3	00:00.0
2021	PO4349216738	KU	4	60 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4351916839	KU	4	45 XXX	SP	CCA		V	00:00.0
2021	PO4361616941	KU	4	30 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4374017632	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4380717790	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4376720435	KU	4	35 XXX	SP	CCA		V	00:00.0
2021	PO438822289A	KU	5	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4782522828	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4780822896	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4779222973	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4776123121	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4764623239	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4758523232	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4622223342	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO4593233364	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO4564022735	KU	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5026984675	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO8128685138	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5031284420	LGE	3	45 BRO	SP	CRE		V	00:00.0
2021	PO4867786103	F	1	55 ACE	SP	CCA		V	00:00.0
2021	PO4863286232	F	4	30 ACE	SP	P		V	00:00.0

2021 PO4863686223	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4862986221	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4864186206	F	3	45 ACE	SP	P		V	00:00.0
2021 PO4455388578	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4458188596	F	4	45 ACE	SP	A		V	00:00.0
2021 PO4459088584	F	4	45 ACE	SP	P		V	00:00.0
2021 PO4456688562	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4456988565	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4454088597	F	3	50 ACE	SP	CRE		V	00:00.0
2021 PO5033384694	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4859586188	LGE	3	50 ACE	SP	P	ED	BD	00:00.0
2021 PO4861186200	LGE	3	45 ACE	SP	P	ED	TD	00:00.0
2021 PO4520587708	LGE	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4520587698	LGE	6	25 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4519787710	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4518087740	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4519087721	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4519687712	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4546088028	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4545588036	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8167883425	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8169683441	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8173783566	KU	2	65 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4455788803	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4455288807	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4452888826	F	4	40 ACE	SP	P		V	00:00.0
2021 PO1633400548	F	3	45 ACE	SP	P		V	00:00.0
2021 PO5031784689	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4444088752	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4445188735	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8076086345	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4863386206	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021 PO5028784680	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4864086185	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO5024584566	LGE	3	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4432588900	LGE	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5024484597	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO5024484625	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8087086084	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8093885935a	KU	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO5024384667	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4544988045	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4545188053	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4516287977	LGE	4	40 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO4488487976	F	4	30 BRO	SP	P		V	00:00.0
2021 PO4487188001	LGE	4	40 BRO	SP	P		B	00:00.0
2021 PO4480987973	LGE	4	35 BRO	SP	A		V	00:00.0
2021 PO8093885935	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX	00:00.0
2021 PO8100485774	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5025384524	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO8106785636	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8118785371	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PV2242989721	LGE	4	35 BRO	SP	P		B	00:00.0
2021 PO4514787725	F	4	40 BRO	SP	CRE		V	00:00.0

2021 PO4516087732	LGE	3	45 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4540214665A	KU	3	40 XXX	SP	CCA		V	00:00.0
2021 PO4540214665	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4529514762	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO4520514840	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4538515017	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4540915262	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4503315323	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4522015307	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4515515105	KU	3	50 XXX	SP	CCA		V	00:00.0
2021 PO4511514891	KU	6	30 XXX	SP	CRE	HH,RB	X PX	00:00.0
2021 PO4511214962	KU	3	50 XXX	SP	CRE	ED	T	00:00.0
2021 PO4511114924	KU	3	50 XXX	SP	CCA		V	00:00.0
2021 PO4491715089	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4473315208	KU	3	50 XXX	SP	CCA		V	00:00.0
2021 PO4477215337	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4431715407	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4417815457	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4451015333	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4454415326	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4443915211	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4401215516	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4383415579	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4358315545	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO1923971175	KU	4	40 BRO	SP	CRE	ID,IP,MD	BD	00:00.0
2021 PO1956571876	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO1932071453	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1942171649	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1977271216	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4466688590	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4467088585	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4466088580	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO1940771756	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4471288569	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4469988560	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4469288556	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4862486099	LGE	3	45 ACE	SP	A	ED,IP	BD	00:00.0
2021 PO5767574121	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4864286090	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4864786106	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4469088596	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4481888524	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4860386093	LGE	3	45 ACE	SP	A	ED,IP	BD	00:00.0
2021 PO2302258505	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2279358511	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4054416309	F	3	45 XXX	SP	P		V	00:00.0
2021 PO4111316068	F	3	45 XXX	SP	S		V	00:00.0
2021 PO4111316068	KU	6	30 XXX	SP	S		V	00:00.0
2021 PO4089216162	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8590960280	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8540859694	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8569959746	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8573059103	ODP	6	35 XXX	SP	CRE		V	00:00.0
2021 PO8571359339	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0

2021 PO8531959063	ODP	5	35 XXX	SP	CCA		V	00:00.0
2021 PO8537859211	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8552658994	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8560058942	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4460887692	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4490588153	LGE	3	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4489988153	LGE	4	30 ACE	SP	A		V	00:00.0
2021 PO4489888148	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021 PO4488888149	LGE	1	85 ACE	SP	CRE		V	00:00.0
2021 PO8194981361	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7996560566	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7988160454	ODP	6	30 BRN	SP	S		V	00:00.0
2021 PO8211381368	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8316281081	KU	3	45 ACE	SP	CRE		V	00:00.0
2021 PO8315081293	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8315581247	F	4	45 ACE	SP	P		V	00:00.0
2021 PO2018093768	LGE	4	30 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4492188143	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO8303881244	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO8288381243	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO8275981236	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO8263981229	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO8242781316	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO8227681372	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO8225281543	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8223781663	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8200481848	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8211381848	F	5	35 ACE	SP	CRE		V	00:00.0
2021 PO4492988129	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4493488123	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO8000360369	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8025560456	ODP	3	45 BRN	SP	S		V	00:00.0
2021 PO8059360500	ODP	4	40 BRN	SP	S		V	00:00.0
2021 PO8043960482	ODP	6	30 BRN	SP	S		V	00:00.0
2021 PO8175061598	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8187561317	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7986861757	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8005662085	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO8217061718	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4458787685	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8218282109	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8219981979	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8221481846	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8237281843	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8249881842	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8262281841	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8274881839	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8288981838	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8289981673	F	5	35 ACE	SP	P		V	00:00.0
2021 PO8298881837	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8288181975	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8288782108	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4493788118	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4493988114	LGE	4	30 ACE	SP	CRE		V	00:00.0



2021 PO0308939795	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0217138935	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0290540019	KU	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4494888101	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8179082462	KU	2	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8180482343	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8193682402	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4019083650	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0203738556	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO0167238144	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO0200138573	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8120361695	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8274862203	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8267862234	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8255662312	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8113061454	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8109661003	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8171680991	F	6	30 ACE	SP	CRE		V	00:00.0
2021 PO8183881052	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8178881050	KU	6	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO8172181041	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8161381014	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO4018483662	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO8195181091	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO8196580953	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8200180954	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8197980799	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8191680847	F	4	45 ACE	SP	P		V	00:00.0
2021 PO4020183666	LGE	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5715023987	KU	2	40 UNK	SP	CRE		BD	00:00.0
2021 PO5719023649	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO4518688024	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8193280686	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8194080593	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8199280654	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8202380655	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8213380662	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8225780666	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8235280671	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8242680731	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO4518388028	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4518188031	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4517588041	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO0265340184	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0310339884	KU	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5732023711	KU	2	45 UNK	SP	CRE	ED	BD	00:00.0
2021 PO4515888069	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4516388061	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO5748523790	KU	2	50 UNK	SP	CRE		T	00:00.0
2021 PO8243480849	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8228180855	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO4515588080	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4514788088	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4514288095	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0

2021 PO4513688105	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5710023448	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO5691723330	KU	2	45 UNK	SP	CCA		V	00:00.0
2021 PO5661723222	KU	3	45 UNK	SP	CRE		BD	00:00.0
2021 PO5732323965	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5733323946	KU	3	45 UNK	SP	CRE		V	00:00.0
2021 PO7397648913	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO2050092445	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO8189981045	F	3	50 ACE	SP	CRE		V	00:00.0
2021 PO8186581041	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4520787989	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4520387996	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4519788005	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4519188015	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8148161049	ODP	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8147461178	ODP	6	30 BRN	SP	S	ED	T	00:00.0
2021 PO8157260907	ODP	2	50 BRN	SP	S		V	00:00.0
2021 PO8150760727	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO8138360643	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8108260727	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4513288112	LGE	4	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8296379726h	KU	3	45 ACE	SP	P		V	00:00.0
2021 PO8296379726g	KU	3	45 ACE	SP	P		V	00:00.0
2021 PO8296379726e	KU	3	45 ACE	SP	P		V	00:00.0
2021 PO8296379726c	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8296379726b	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4459187674	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5670923307	KU	1	75 UNK	SP	CRE		T	00:00.0
2021 PO5675723346	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5669523265	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5688823472	KU	1	75 UNK	SP	CRE		T	00:00.0
2021 PO4459787681	LGE	3	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4515788113	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO8437878170	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8437878245	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8437878406	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4514888112	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4515588117	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0494948184	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4471188068	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4471888058	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4515188124	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4514988127	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4514788133	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021 PO8439578645	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4472488050	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4473088041	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4513188135	LGE	3	95 ACE	SP	CRE		V	00:00.0
2021 PO0235837406	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5751523111	KU	2	55 UNK	SP	CRE	ED,ID	BX	RP2 00:00.0
2021 PO0669251639	KU	4	40 UNK	SP	CRE	ID	BX	RR 00:00.0
2021 PO8191983196	F	4	40 ACE	SP	P	ED,HH,ID,RB	VX	PX 00:00.0
2021 PO8189081585	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1 00:00.0
2021 PO8255462240	ODP	6	30 BRN	SP	S		V	00:00.0

2021 PO8252361548	ODP	6	30 BRN	SP	S		V	00:00.0
2021 PO4572488212	F	3	60 ACE	SP	A		V	00:00.0
2021 PO4569988197	F	3	60 ACE	SP	CRE		V	00:00.0
2021 PO4570988203	F	3	60 ACE	SP	A		V	00:00.0
2021 PO4570588199	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4567588082	F	4	40 ACE	SP	A		V	00:00.0
2021 PO2805393876	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4477987881	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4479287900	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO8911753772	ODP	6	30 XXX	SP	CRE	ID	BD	00:00.0
2021 PO8926353792	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8943153765	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8764455127	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8750554686	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8718254677	ODP	6	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO872154133A	ODP	3	45 XXX	SP	CCA		V	00:00.0
2021 PO8732154133	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8804253361	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8820253437	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8811952719	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4535088116	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0
2021 PO8810052830	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8807752977	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4465288269	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4465588365	F	1	65 BRO	SP	P		V	00:00.0
2021 PO4466688269	LGE	1	60 BRO	SP	CCA		V	00:00.0
2021 PO4463288394	LGE	4	35 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4463388386	LGE	3	45 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4457288034	LGE	6	25 BRO	SP	CRE		V	00:00.0
2021 PO4456788117	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4454787806	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4528788069	LGE	4	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4458187779	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4454687791	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4528388077	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5765824438	KU	4	35 UNK	SP	CRE		T	00:00.0
2021 PO5761724484	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO5755224556	KU	5	35 UNK	UN	CRE		V	00:00.0
2021 PO5747424643	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO5770924386	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO5765124324	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5758224263	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO8183682058	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8182882141	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4454687776	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5748324347	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4458287767	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4457787767	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4461687652	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4461887653	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4527688087	LGE	3	45 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO8184781967	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5706224486	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO8187281852	KU	4	40 ACE	SP	P	ED,ID	TD	00:00.0

2021 PO8186581792	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5723224480	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO5715324401	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO0565854947	KU	4	45 BRN	SP	CRE		T	00:00.0
2021 PO0527954821	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5725624412	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO0493754700	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO0580954556	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4527088098	LGE	4	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4526488108	LGE	4	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4527388120	LGE	1	95 ACE	SP	CRE		V	00:00.0
2021 PO4525488123	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4454987684	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4455987679	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5730624357	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO4525788119	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4533788124	LGE	1	95 ACE	SP	CRE		V	00:00.0
2021 PO4522388126	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4461287664	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4518488082	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4520088129	LGE	1	95 ACE	SP	CRE		V	00:00.0
2021 PO4518788124	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8191481402	KU	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8193881190	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8201781779	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8220081600	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8309781245	F	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8873855188	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4571588154	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4571388135	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4571488144	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4571788115	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4089216162	F	3	50 XXX	SP	P		V	00:00.0
2021 PO4070716240	F	3	45 XXX	SP	P		V	00:00.0
2021 PO4039916378	F	3	45 XXX	SP	P		V	00:00.0
2021 PO4041816383	F	3	45 XXX	SP	P		V	00:00.0
2021 PO4024016461	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4866786074	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021 PO4447885947	F	2	55 BRO	SP	CCA		V	00:00.0
2021 PO7791880646	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4867085995	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4868686006	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO2366579577	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO1307553182	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1342153082	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5235600420	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5240000572A	KU	2E	25E	BRN	SP	CRE	V	00:00.0
2021 PO2357779428	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5237400597	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO5240000572	KU	2	60 BRN	SP	CRE		V	00:00.0
2021 PO5240700598	KU	2	45 BRN	SP	CCA		V	00:00.0
2021 PO5244500739	KU	2	60 BRN	SP	CRE		V	00:00.0
2021 PO5248700900	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO2371279314	KU	4	45 BRN	SP	CCA		V	00:00.0

2021 PO2056573551	KU	4	40 CPT	SP	CRE	ED,ID	TD		00:00.0
2021 PO4764189772	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4765189777	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4763989758	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4763889742	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4764389725	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4763989719	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO1368053218	KU	3	40 XXX	SP	CRE	ID,IP	TX	RR	00:00.0
2021 PO1373453407	KU	4	40 XXX	SP	CRE	ID,IP	BD		00:00.0
2021 PO1379553324	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO1979277330	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO1949577219	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4850890437	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021 PO4835790404	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021 PO4862090428	LGE	3	45 BRO	SP	A		V		00:00.0
2021 PO4682407187	F	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4665906796	F	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4690307349	F	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4676907046	F	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4682507172	F	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4702407623	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4696707503	F	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4658306621	F	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4639306700	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4672506944	F	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4631306724	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO1939577338	KU	5	35 BRN	SP	CRE	ED,ID,RB	X	RP1	00:00.0
2021 PO0474640320	KU	5	35 BRO	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO9807023758	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO1910577189	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5251000987A	KU	1E	40E BRN	SP	CRE		V		00:00.0
2021 PO5251000987	KU	2	65 BRN	SP	CRE		V		00:00.0
2021 PO5253301073	KU	3	45 BRN	SP	CRE	ED	BD		00:00.0
2021 PO5255701163	KU	2	65 BRN	SP	CRE		V		00:00.0
2021 PO1872476988	KU	4	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5261801395	KU	2	65 BRN	SP	CRE		V		00:00.0
2021 PO4863890403	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO5263901472	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO5265301525	KU	ST	65 BRN	SP	CRE		V		00:00.0
2021 PO5263701577A	F	2	40 BRN	SP	A		V		00:00.0
2021 PO5263701577	KU	1	60 BRN	SP	CCA		V		00:00.0
2021 PO5272001779	KU	2	60 BRN	SP	CRE		V		00:00.0
2021 PO5279302040	KU	2	60 BRN	SP	CRE		V		00:00.0
2021 PO1380552970	KU	4	40 XXX	SP	CRE	ID	TX	RR	00:00.0
2021 PO1409652880	KU	4	40 XXX	SP	CRE	ED,HH,ID	TX	RR	00:00.0
2021 PO1436652801	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO1463553002	KU	6	30 XXX	SP	CRE		V		00:00.0
2021 PO1493553240	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO1484053091	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO1474653161	KU	6	30 XXX	SP	CRE	ID,IP	BD		00:00.0
2021 PO1467553076	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO1481952682	KU	4	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO1504452611	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO1510852856	F	4	40 XXX	SP	CRE		V		00:00.0

2021 PO1522453067	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO1561652455	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4835790404-A	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5285402271A	KU	2	45 BRN	SP	CCA		V	00:00.0
2021 PO2055877524	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO2096577635	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO2131477724	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5285402271	KU	2	65 BRN	SP	CRE		V	00:00.0
2021 PO5289502457	KU	2	60 BRN	SP	CRE		V	00:00.0
2021 PO2162177800	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO2290477452	KU	5	35 KOP	SP	CCA		V	00:00.0
2021 PO4763889816	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4838190411	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO2246677572	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO2189277734	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4863290522	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4861590567	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4833990410	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO2160578057	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2153078254	KU	4	40 BRO	SP	CRE	RB	BX	RP1 00:00.0
2021 PO4860890590	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4860190631	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4759890021	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4840290430	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO0533840616	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4662113348	LGE	3	35 ACE	SP	CCA		V	00:00.0
2021 PO4757090085	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5506217369	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO2376579083	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4758290043	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4761290098	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4759290092	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4756790069	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4840090430	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4875290826	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4628706576	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4651706465	F	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4640906519	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4649706475	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5654817457	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4735613995	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO2395879079	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4862690503	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO0370939312	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4854090449	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO0308338940	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO0390939413	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO4760090154	LGE	UNK	20 ACE	AL	CCA		V	00:00.0
2021 PO4764990126	LGE	1	80 ACE	SP	CRE		V	00:00.0
2021 PO4764990111	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO2335676777	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO2186774612a	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4862190456	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0341640678	KU	3	45 BRO	SP	CCA		V	00:00.0

2021 PO0312140671	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4859390640	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4733914012	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4765590108	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO0346241345	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4862090541	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO0379642221	KU	3	45 BRO	SP	S		V	00:00.0	
2021 PO0348142309	KU	3	45 BRO	SP	S		V	00:00.0	
2021 PO0446043257	KU	3	45 KOP	SP	CCA		V	00:00.0	
2021 PO4874890854	LGE	3	55 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO0403241447	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0370141459	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4850190445	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO4627615099	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO0418742130	KU	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0424942401	KU	4	35 KOP	SP	P	ED,ID	TD	00:00.0	
2021 PO0326841472	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO0346641449	KU	4	40 BRO	SP	S		V	00:00.0	
2021 PO4876190847	LGE	3	45 BRN	SP	P	ED,ID	T	00:00.0	
2021 PO4873290791	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0	
2021 PO4753390232	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4893790087	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO4753090237	LGE	4	30 ACE	SP	P		V	00:00.0	
2021 PO4864390446	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO4870490746	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4868390713	LGE	4	40 BRN	SP	CCA	ED,ID	BD	00:00.0	
2021 PO4864790696	LGE	4	40 BRN	SP	P	ED,ID	T	00:00.0	
2021 PO4865490899	LGE	4	45 BRN	SP	P		V	00:00.0	
2021 PO4861590479	LGE	4	30 BRN	SP	P		V	00:00.0	
2021 PO6055321388	LGE	5	35 BRN	SP	P		V	00:00.0	
2021 PO4752590245	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO4892690106	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO4891190132	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO4885390241	LGE	4	30 BRO	ST	CCA		V	00:00.0	
2021 PO6016054247	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO7932546920	KU	4	40 KOP	SP	CRE	ED,ID,JP	BD	00:00.0	
2021 PO5595300737	F	5	35 XXX	SP	CRE		V	00:00.0	
2021 PO5587400922	F	6	30 XXX	SP	CRE		V	00:00.0	
2021 PO5619501353	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5629801296	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5651401192	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5641301247	F	4	40 XXX	SP	P	ED,EP,ID,MD	BX	RP2	00:00.0
2021 PO5597300941	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5595900813	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5585801035	F	5	30 XXX	SP	P		V	00:00.0	
2021 PO5580501450	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO5580201370	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5579501230	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5606001031	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5587201158	F	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	BX	PX	00:00.0
2021 PO5597401092	F	4	40 XXX	SP	CRE	ED,ID	BX	PX	00:00.0
2021 PO5609401087	F	5	30 XXX	SP	P		V	00:00.0	
2021 PO5064899783	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO5046499638	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0	

2021 PO5034699542	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6019954143	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO6066254276	KU	5	30 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO6010554260	KU	2	50 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5999254542	KU	6	35 BRO	SP	S		V	00:00.0
2021 PO5990454419	KU	6	30 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5090498136A	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5995854497	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6000954397	KU	2	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5380898038	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO5380798063	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2116743409	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5392798022	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5404997961	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO2038141372	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2020541493	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2018541386	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6199851055	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7885347129	KU	4	45 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO5419497911	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7956546729	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO8027046323	KU	3	45 BRO	SP	S		V	00:00.0
2021 PO6203751023	KU	1	75 BRO	SP	CCA		V	00:00.0
2021 PO5428797869	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6207251066	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6216051182	KU	1	75 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO6212851138	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5437297831	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO2009541635	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7885047056	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5442197807	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7944346999	KU	4	45 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO1915241588	KU	6	30 XXX	SP	CRE		V	00:00.0
2021 PO6207051170	KU	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO6200151233	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6193751282	F	4	40 MCM	SP	S		V	00:00.0
2021 PO6258451085	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7936147037	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO1879141277	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1879141277A	KU	6	30 XXX	SP	CRE	ED,ID,RB	X	RP3 00:00.0
2021 PO1834440869	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1826041031	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5459797719	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7962346834	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7979946794	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO8022846651	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5465397693	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO8025546766	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8043446579	KU	3	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5470997670	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO2489685651	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2507985713	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO8049446563	KU	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5642801000	F	4	40 XXX	SP	P		V	00:00.0



2021 PO5624500932	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5637100884	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	PX	00:00.0
2021 PO5632000776	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5626700668	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5621300555	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5610300326	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5589400402	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5573400460	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5747003517	KU	4	30 XXX	SP	CRE		V		00:00.0
2021 PO5166397406	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021 PO8096846408	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO8075546476	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO2524285670	KU	3	50 BRN	SP	CCA		V		00:00.0
2021 PO2508585544	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO2517885394	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2515385520	KU	3	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO6265451100	KU	3	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO6252050965	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6261451024	KU	3	45 BRO	SP	CCA	ED,ID	V		00:00.0
2021 PO4011084062	F	4	40 ACE	SP	CRE	ED	V		00:00.0
2021 PO4010984042	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4007584049	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4010183824	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021 PO4009783817	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8499253732	ODP	4	45 XXX	SP	CCA		V		00:00.0
2021 PO8377952937	ODP	5	35 XXX	SP	CRE		V		00:00.0
2021 PO4007484119	F	UNK	45 ACE	SP	CRE	ED	V		00:00.0
2021 PO4909225579	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO7975076913	F	6	30 ACE	SP	CRE		V		00:00.0
2021 PO7960677510	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO8011577430	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8527252132	ODP	3	45 XXX	SP	CCA		V		00:00.0
2021 PO8005977213	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4010484117	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4011384103	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4011384098	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO3991783525	F	3	45 BRO	SP	A		V		00:00.0
2021 PO3990983514	F	3	45 BRO	SP	A		V		00:00.0
2021 PO3990883528	F	4	40 BRO	SP	A		V		00:00.0
2021 PO7950077888	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4014284069	F	4	40 ACE	SP	A		V		00:00.0
2021 PO4014184055	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4014184038	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4015484032	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7804878589	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8544151947	ODP	6	30 XXX	SP	CCA		V		00:00.0
2021 PO8543651937	ODP	6	30 XXX	SP	CCA		V		00:00.0
2021 PO7752178812	KU	2	45 ACE	SP	CCA		V		00:00.0
2021 PO4004384077	LGE	4	40 ACE	SP	CRE	ED	V		00:00.0
2021 PO7978077745	F	4	40 ACE	SP	P		V		00:00.0
2021 PO7962377754	F	5	35 ACE	SP	CRE		V		00:00.0
2021 PO7954277735	F	5	35 ACE	SP	P		V		00:00.0
2021 PO7906977782	F	4	40 ACE	SP	P		V		00:00.0
2021 PO7921377772	F	4	40 ACE	SP	P		V		00:00.0

2021 PO1274862274	F	4	40 BRN	SP	CCA		V			00:00.0
2021 PO1345861478	KU	3	45 BRO	SP	CCA		V			00:00.0
2021 PO1283461444	F	4	40 BRO	SP	A		V			00:00.0
2021 PO1274461477	KU	3	45 BRO	SP	CCA		V			00:00.0
2021 PO1250461859	KU	4	45 BRO	SP	CCA		V			00:00.0
2021 PO7983477814	KU	5	35 ACE	SP	CCA		V			00:00.0
2021 PO7962977849	KU	4	40 ACE	SP	CCA		V			00:00.0
2021 PO1289862246	KU	4	45 BRO	SP	CCA		V			00:00.0
2021 PO1272861836	F	3	40 BRO	SP	CCA		V			00:00.0
2021 PO4004684122	LGE	UNK	65 ACE	SP	CRE	ED,HH,ID,RB	VX		RP2	00:00.0
2021 PO8326353123	ODP	5	35 XXX	SP	CRE	HH,ID,RB	X		PX	00:00.0
2021 PO8512153873	ODP	5	30 XXX	SP	CRE	HH,ID	X		RP2	00:00.0
2021 PO5210423365	KU	2	45 UNK	SP	CRE		B			00:00.0
2021 PO5221123222	KU	2	45 UNK	SP	CRE		B			00:00.0
2021 PO5223323192	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO5283123311	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 A5261323233	KU	5	35 UNK	SP	CRE		B			00:00.0
2021 PO5285723273	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO5293323302	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5310023367	KU	2	50 UNK	SP	CRE		B			00:00.0
2021 PO5274524517	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5324224850	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5294225042	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO5281225226	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5295125214	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5291125218	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5309526115	KU	2	40 UNK	SP	CRE		B			00:00.0
2021 PO5318825955	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5349226171	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO5318326097	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5333225966	KU	6	30 UNK	SP	CRE		B			00:00.0
2021 PO4011584116	LGE	UNK	60 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4461788222	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO5632384583	KU	4	40 BRO	SP	CRE	ID	BD			00:00.0
2021 PO9219159217	ODP	5	35 BRO	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO4010983840	LGE	2	55 BRO	SP	A	ED,ID	BD			00:00.0
2021 PO8036977027	KU	4	45 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4460588220	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO8082277117	KU	5	35 ACE	SP	CRE	ED,EP,ID	BD			00:00.0
2021 PO8069777168	KU	5	35 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4463788277	LGE	4	35 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4464588278	LGE	4	35 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO9161158480	ODP	5	35 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO4461288271	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4460488269	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4459588268	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4458488266	LGE	4	35 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4463188224	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4461388209	LGE	4	35 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO8441051882	ODP	4	40 XXX	SP	CRE	ID	BD			00:00.0
2021 PO4012684111	LGE	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO8097077107	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO9266658166	ODP	5	35 BRO	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO2859092392	KU	4	40 UNK	SP	CRE	ID	BD			00:00.0

2021 PO7940477638	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4014284097	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4012084116	LGE	UNK	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4468588383	LGE	4	25 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4105489485	KU	4	40 INP	SP	CRE	ID	BD	00:00.0
2021 PO3998883672	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4469288366	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4469388176	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3961486865	KU	4	40 INP	SP	CRE	ID	BD	00:00.0
2021 PO3987587197	KU	4	40 INP	SP	CRE	ID	BD	00:00.0
2021 PO4098388204	KU	3	45 INP	SP	CRE	ID	BD	00:00.0
2021 PO4357789142	KU	4	40 INP	SP	CRE	ID	BD	00:00.0
2021 PO7990877639	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4469788224	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3941786584	KU	4	45 INP	SP	CRE	ID	BD	00:00.0
2021 PO4005083726	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5273523225	KU	3	45 UNK	SP	CRE	ID,RB	BX PX	00:00.0
2021 PO8024176995	KU	3	50 ACE	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021 PO5255123153	KU	3	45 UNK	SP	CRE	ID,RB	BX PX	00:00.0
2021 PO9307157769	ODP	4	45 BRO	SP	S	ED	T	00:00.0
2021 PO5299126098	KU	6	30 UNK	SP	CRE		T	00:00.0
2021 PO8525551847	ODP	5	35 XXX	SP	CCA	ED	T	00:00.0
2021 PO5308723475	KU	6	30 UNK	SP	CRE		T	00:00.0
2021 PO5202023476	KU	2	45 UNK	SP	CRE		T	00:00.0
2021 PO7984277448	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7999477579	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8008677646	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4468888220	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7998477439	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO3998083689	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO1243464585	KU	6	30 BRO	SP	CRE	ED,IP,SRC	TD	00:00.0
2021 PO2806393416	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO2828293012	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO2846692634	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO8001377422	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8012077586	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4004883722	LGE	2	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO8459951877	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8459951877	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8407151687	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4466288216	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8059177226	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO9465458440	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9470558060	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4464988214	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4463988212	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4004283710	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8028677419	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO1240164326	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1237064534	KU	4	40 BRN	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO1303564826	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO1250664816	KU	4	40 BRO	SP	CRE	ED,IP,MD	TD	00:00.0
2021 PO0753551346	KU	3	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO2478384277	KU	5	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0

2021 PO2484484269	KU	3	45 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO9224057667	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9073067932	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9051367504	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1229164826	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO1241264814	KU	4	45 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4012684098	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4012184096	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4460288204	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO9029467723	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7918776698	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7932776700	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7934776608	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7937676487	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO9318757901	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9346557274A	ODP	5	35 BRO	DF	CRE	ED,ID	TD	00:00.0
2021 PO9056868122	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9412857665	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9043568275	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4459388207	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4467188217	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4011383850	LGE	2	55 BRO	SP	CRE	ED,ID,SR	TD	00:00.0
2021 PO9071468166	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9101968275	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9064368315	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9087768512	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8049977235	KU	6	30 ACE	SP	CCA	ED	TD	00:00.0
2021 PO8049377315	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9047567033	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9215558636	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9250958326A	ODP	6	30 BRO	SP	S	ED,ID	TD	00:00.0
2021 PO0742151353	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0725251363	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0714751370	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0696451382	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0683651390	KU	4	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO9037767318	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3999183681	LGE	4	35 BRO	SP	P	ED,ID,SR	TD	00:00.0
2021 PO8471051900	ODP	6	30 XXX	SP	CCA	ED	TD	00:00.0
2021 PO2473283652	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2479383953	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO8977465736	ODP	5	30 XXX	SP	CRE	ID,IP	TD	00:00.0
2021 PO4463088276	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO9114358043	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9250958326	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9192558609	ODP	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9211758913	ODP	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9154958330	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9037666636	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9017966660	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2468483397	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4463388223	LGE	4	45 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4012984116	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021 PO7978277840	KU	2	60 ACE	ST	CRE		V	00:00.0

2021 PO7937676487c	KU	6	30 ACE	SP	CCA	V	00:00.0		
2021 PO7937676487b	KU	6	30 ACE	SP	CCA	V	00:00.0		
2021 PO7937676487a	KU	6	30 ACE	SP	CCA	V	00:00.0		
2021 PO3999483742	F	3	45 BRO	SP	A	V	00:00.0		
2021 PO3998283742	F	4	30 BRO	SP	A	V	00:00.0		
2021 PO3998383746	F	4	40 BRO	SP	CRE	V	00:00.0		
2021 PO3995983755	F	4	40 BRO	SP	CRE	V	00:00.0		
2021 PO3995883751	F	4	30 BRO	SP	CRE	V	00:00.0		
2021 PO3994383760	F	4	40 BRO	SP	A	V	00:00.0		
2021 PO3994083756	F	4	35 BRO	SP	CRE	V	00:00.0		
2021 PO5308126209	KU	2	55 UNK	SP	CCA	V	00:00.0		
2021 PO4014384085	F	3	45 ACE	SP	CCA	V	00:00.0		
2021 PO4014384098	F	4	40 ACE	SP	CCA	V	00:00.0		
2021 PO9041667565	ODP	4	40 XXX	SP	CCA	V	00:00.0		
2021 PO8030877057	F	5	35 ACE	SP	CRE	V	00:00.0		
2021 PO8024177040	F	5	35 ACE	SP	P	V	00:00.0		
2021 PO8010476958	KU	3	50 ACE	SP	CCA	V	00:00.0		
2021 PO3991683533	LGE	4	35 BRO	ST	CCA	V	00:00.0		
2021 PO4001483602	LGE	4	40 BRO	SP	CCA	V	00:00.0		
2021 PO5333626290	F	4	40 UNK	SP	CRE	V	00:00.0		
2021 PO5285127387	KU	5	35 UNK	SP	CCA	V	00:00.0		
2021 PO5299027100	KU	3	45 UNK	SP	CCA	V	00:00.0		
2021 PO9252757810	ODP	3	45 BRO	SP	S	V	00:00.0		
2021 PO5753585590	F	4	40 UNK	SP	CRE	V	00:00.0		
2021 PO5621584451	F	4	40 UNK	SP	CCA	V	00:00.0		
2021 PO5514185238	F	4	40 UNK	SP	CRE	V	00:00.0		
2021 PO5499985468	F	4	40 UNK	SP	CRE	V	00:00.0		
2021 PO4463488214	LGE	3	45 ACE	SP	CCA	V	00:00.0		
2021 PO9455659274	F	4	40 BRO	SP	CRE	V	00:00.0		
2021 PO4003483714	F	3	45 BRO	SP	CCA	V	00:00.0		
2021 PO8410451471	ODP	4	40 XXX	SP	CCA	V	00:00.0		
2021 PO8421051224	ODP	4	40 XXX	SP	CCA	V	00:00.0		
2021 PO8417451010	ODP	2	45 XXX	SP	CCA	V	00:00.0		
2021 PO8423251817	ODP	4	40 XXX	SP	CRE	V	00:00.0		
2021 PO8454151680	ODP	6	30 XXX	SP	CCA	V	00:00.0		
2021 PO5203523737	KU	2	45 UNK	SP	CCA	V	00:00.0		
2021 PO5203023658	KU	3	45 UNK	SP	CCA	V	00:00.0		
2021 PO5449985663	F	4	40 UNK	SP	CCA	V	00:00.0		
2021 PO5413485654	F	4	40 UNK	SP	CRE	V	00:00.0		
2021 PO5387485644	F	4	40 UNK	SP	CCA	V	00:00.0		
2021 PO5352085401	F	3	45 UNK	SP	CCA	V	00:00.0		
2021 PO5326885220	F	4	40 UNK	SP	CCA	V	00:00.0		
2021 PO4468988368	F	4	35 ACE	SP	CCA	V	00:00.0		
2021 PO3985883858	F	4	40 BRO	SP	CCA	V	00:00.0		
2021 PO3986183869	F	4	40 BRO	SP	A	V	00:00.0		
2021 PO3986583880	F	3	45 BRO	SP	A	V	00:00.0		
2021 PO3987383880	F	4	40 BRO	SP	A	V	00:00.0		
2021 PO3986783887	F	4	30 BRO	SP	A	V	00:00.0		
2021 PO7778173749	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO7778273724	KU	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	TX	RR	00:00.0
2021 PO7901373736	KU	5	35 ACE	SP	CCA	V	00:00.0		
2021 PO7891073748	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7898173648a	KU	6	30 ACE	ST	CCA	V	00:00.0		
2021 PO7898173648	KU	4	45 ACE	ST	CCA	V	00:00.0		

2021 PO7830470496	KU	H1	85 ACE	ST	CRE		V	00:00.0
2021 PO7159957785	F	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4001584592	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO0867300424	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO4045284223	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4044484224	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4043284233	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4043084235	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4041184248	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD	00:00.0
2021 PO4033384578	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4031484581	LGE	3	35 ACE	SP	CCA		V	00:00.0
2021 PO4022984594	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4021784597	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4020384597	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4018084591	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4016684596	F	4	45 ACE	SP	P		V	00:00.0
2021 PO4015284601	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4008384606	LGE	4	30 ACE	SP	P		V	00:00.0
2021 PO4008484609	F	4	30 ACE	SP	P		V	00:00.0
2021 PO7215457861	F	3	45 ACE	SP	P		V	00:00.0
2021 PO3995784189	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3997084188	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4003684242	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO9805498394	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9816898626	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO9809898496	KU	4	45 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4001284631	F	3	45 ACE	SP	P		V	00:00.0
2021 PO4001184631	LGE	4	35 ACE	SP	P	ED	TD	00:00.0
2021 PO3987584255	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3988984255	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO7669273204	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO7632470866	KU	2	45 ACE	SP	CCA		V	00:00.0
2021 PO4011784611	F	3	45 ACE	SP	P		V	00:00.0
2021 PO3994384131	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3995284130	F	2	55 ACE	SP	CRE		V	00:00.0
2021 PO3996784129	F	UNK	25 ACE	SP	CRE		V	00:00.0
2021 PO4035484737	F	4	35 BRN	SP	P		V	00:00.0
2021 PO4035684747	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4035684756	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9847099877	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO9861899434	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9840900074	KU	5	35 BRO	SP	CRE		V	00:00.0
2021 PO9835200331	KU	5	35 BRO	SP	CRE		V	00:00.0
2021 PO9871599478	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4063483972	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4067984057	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 Ku	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO0035378253	KU	5	35 BRN	UN	CRE		V	00:00.0
2021 PO7623971107	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO7616671067	KU	2	45 ACE	SP	CCA		V	00:00.0
2021 PO4013284609	F	3	45 ACE	SP	A		V	00:00.0
2021 PO4013884609	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO3993883925	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3992983912	LGE	3	45 BRO	SP	CCA		V	00:00.0

2021 PO4067384050	LGE	3	45 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4064384032	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4058684047	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP	BD	00:00.0
2021 PO4060184050	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4058984032	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4060784037	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4061484003	LGE	3	45 BRO	SP	P	ED,ID	TD	00:00.0
2021 Ku	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO7599971268	KU	2	45 ACE	SP	CCA		V	00:00.0
2021 PO7584371469	KU	2	45 ACE	SP	CCA		V	00:00.0
2021 PO2130046357	KU	4	40 XXX	SP	CRE	ID	BX	RP3 00:00.0
2021 PO3992683931	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4014384608	F	4	40 ACE	SP	A		V	00:00.0
2021 PO2107846349	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO0079078064	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3991583938	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4015284630	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO3990883933	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4015084625	LGE	4	35 ACE	SP	A	ED	BD	00:00.0
2021 PO0048077901	KU	4	45 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO0885299644	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO0893499525	KU	5	35 KOP	SP	CRE	ID	TD	00:00.0
2021 PO7387070685	KU	5	35 ACE	SP	CRE		V	00:00.0
2021 PO2074546334	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3989883963	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3989783951	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3989683940	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4036984770	LGE	4	40 BRN	SP	CRE	ED,EP,HH,ID	BX	RR 00:00.0
2021 PO4036784772	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO3989383917	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3989583929	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO2044746322	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO0902199406	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO0904399425	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO3989283905	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3989183893	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3988883879	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4036384782	LGE	4	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4035784772	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3987883803	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4035784777	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4035784784	F	7	25 BRN	SP	CRE		V	00:00.0
2021 PO3987583792	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4015584607	F	3	45 ACE	SP	A		V	00:00.0
2021 PO4014984618	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4014884607	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4026284726	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4026484735	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4020784771	LGE	7	25 BRN	SP	A		V	00:00.0
2021 PO4019984756	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4015784791	F	4	40 BRN	SP	A		V	00:00.0
2021 PO7402170319	KU	1	60E ACE	SP	CCA		V	00:00.0
2021 PO7388670475	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7375270636	KU	1	80 ACE	SP	CCA		V	00:00.0

2021	PO7361370796	KU	4	40 ACE	SP	CCA				V	00:00.0	
2021	PO7347470957	KU	1	80 ACE	SP	CCA				V	00:00.0	
2021	PO3980583795	F	4	40 BRO	SP	CCA				V	00:00.0	
2021	PO3981583795	F	3	45 BRO	SP	A				V	00:00.0	
2021	PO3983883799	F	4	35 BRO	SP	A				V	00:00.0	
2021	PO3984183789	F	4	35 BRO	SP	CCA				V	00:00.0	
2021	PO7334771102	KU	4	40 ACE	SP	CCA				V	00:00.0	
2021	PO7320971269	KU	H1	85 ACE	SP	CRE				V	00:00.0	
2021	PO7297071278	KU	4	45 ACE	SP	CCA				V	00:00.0	
2021	PO7276571292	KU	1	80 ACE	SP	CCA				V	00:00.0	
2021	PO7257071303	KU	4	40 ACE	SP	CCA				V	00:00.0	
2021	PO7237371313	KU	1	80 ACE	SP	CCA				V	00:00.0	
2021	PO7216571322	KU	4	40 ACE	SP	CCA				V	00:00.0	
2021	PO7178471342	KU	4	45 ACE	SP	CCA				V	00:00.0	
2021	PO3983383790	F	4	40 BRO	SP	CRE				V	00:00.0	
2021	PO3983983780	F	5	25 BRO	SP	CRE				V	00:00.0	
2021	PO1686195202	KU	4	45 BRO	SP	CCA				V	00:00.0	
2021	PO4026884757	F	4	30 BRN	SP	CCA				V	00:00.0	
2021	PO4027384751	F	4	40 BRN	SP	CRE				V	00:00.0	
2021	PO4029984770	F	4	40 BRN	SP	CRE				V	00:00.0	
2021	PO4030484774	F	7	25 BRN	SP	CRE				V	00:00.0	
2021	PO4028984778	F	7	25 BRN	SP	CRE				V	00:00.0	
2021	PO4028984769	F	4	40 BRN	SP	CRE				V	00:00.0	
2021	PO4026884768	LGE	7	25 BRN	SP	CRE				V	00:00.0	
2021	PO4027584769	F	4	40 BRN	SP	CRE				V	00:00.0	
2021	PO7273667974	KU	5	35 ACE	SP	CRE	ED,ID			BD	00:00.0	
2021	PO4034984787	LGE	4	40 BRN	SP	A	ED,HH,ID			BX	RR	00:00.0
2021	PO4035184786	LGE	4	35 BRN	SP	CRE	ED,ID,IP			TD		00:00.0
2021	PO4035384797a1	KU	4	30 BRN	SP	A	ID			TD		00:00.0
2021	PO4035384797	LGE	4	30 BRN	SP	CRE	ED,ID,IP			TD		00:00.0
2021	PO4032484843	F	4	40 BRN	SP	CCA				V	00:00.0	
2021	PO7277367914	KU	4	40 ACE	SP	CRE	ED,ID			TD	00:00.0	
2021	PO3987283805	F	4	40 BRO	SP	CCA				V	00:00.0	
2021	PO4014984612	F	4	25E ACE	SP	P				V	00:00.0	
2021	PO2008846147	KU	4	40 XXX	SP	CRE	ID			BD	00:00.0	
2021	PO2029946169	KU	4	40 XXX	SP	CRE	ID			TD	00:00.0	
2021	PO2088344659	KU	4	40 XXX	SP	CRE	ID			BD	00:00.0	
2021	PO2063444654	KU	6	30 XXX	SP	CCA	ED			TD	00:00.0	
2021	PO1803145017	KU	3	45 XXX	SP	CCA				V	00:00.0	
2021	PO4015084624	F	4	40 ACE	SP	P				V	00:00.0	
2021	PO3988683864	F	4	40 BRO	SP	CCA				V	00:00.0	
2021	PO3988383852	F	4	40 BRO	SP	CRE				V	00:00.0	
2021	PO3988083840	F	3	45 BRO	SP	A				V	00:00.0	
2021	PO3987883828	F	4	40 BRO	SP	A				V	00:00.0	
2021	PO3987583816	F	3	45 BRO	SP	A				V	00:00.0	
2021	PO3986983791	F	4	40 BRO	SP	A				V	00:00.0	
2021	PO9863599063	KU	4	40 BRO	SP	CRE	ED,ID			TD	00:00.0	
2021	PO3986783780	F	3	45 BRO	SP	A				V	00:00.0	
2021	PO9873399098	KU	4	40 BRO	SP	CRE	ED,ID,IP			TD	00:00.0	
2021	PO9835298968	KU	4	40 BRO	SP	CRE	ED,ID			TD	00:00.0	
2021	PO7274667620	KU	4	40 ACE	SP	CRE	ED,ID			BD	00:00.0	
2021	PO9925386174	F	3	45 BRN	SP	CCA				V	00:00.0	
2021	PO9947685976	KU	6	30 BRN	SP	CRE	ED,IP,SRS			TD	00:00.0	
2021	PO9929386044	KU	5	35 BRN	SP	CRE	ID,IP			BD	00:00.0	



2021 PO4036284809	LGE	4	35 BRN	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO4035884819	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4037384818	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4036484822	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4036584832	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4037084846	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4035684841	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4034184842	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4030884844	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4029684845	F	3	50 BRN	SP	CRE		V	00:00.0
2021 PO4026384843	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4025784849	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7407670837	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7411970817	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX RP1	00:00.0
2021 PO3986583746	F	4	30 BRO	SP	CCA		V	00:00.0
2021 PO3984883765	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3986283764	F	3	45 BRO	SP	CRE	ED,HH,ID,RB	VX RP1	00:00.0
2021 PO1702196279	KU	5	35 KOP	SP	CRE	ID	TD	00:00.0
2021 PO7240271462a	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7240271462	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7230171810	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7218172239	KU	2	50 ACE	SP	CCA		V	00:00.0
2021 PO7215172701	KU	5	35 ACE	SP	CRE		V	00:00.0
2021 PO4061283988	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4059184014	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4058984007	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4016884623	LGE	4	30 ACE	SP	P	ED,IP	BD	00:00.0
2021 PO9939286284	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4016784619	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4027884846	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4027784841	LGE	4	30 BRN	SP	A	ED,EP,HH,ID	X PX	00:00.0
2021 PO4027984829	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4027984824	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4028584825	F	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4027984824	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4030684810	F	4	30 BRN	SP	P		V	00:00.0
2021 PO4029184803	F	4	45 BRN	SP	A		V	00:00.0
2021 PO4030584801	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4031584798	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4031984803	F	7	25 BRN	SP	CRE		V	00:00.0
2021 PO4033084796	LGE	7	25 BRN	SP	CRE		V	00:00.0
2021 PO4032284790	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4033784783	F	7	25 BRN	SP	CRE		V	00:00.0
2021 PO4032684782	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4032784769	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4032784755	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4033484740	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4032184721	F	7	25 BRN	SP	CRE		V	00:00.0
2021 PO4032684741	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4033084728	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4030884730	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4032284730	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4027984734	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4029384732	F	3	45 BRN	SP	CCA		V	00:00.0

2021 PO4027784725	LGE	7	25 BRN	SP	CRE		V	00:00.0
2021 PO4022984754	F	4	45 BRN	SP	A		V	00:00.0
2021 PO4022884745	LGE	7	25 BRN	SP	CRE		V	00:00.0
2021 PO4021484746	F	7	25 BRN	SP	P		V	00:00.0
2021 PO4024484779	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4024884768	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7207672612	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO7457969675	KU	3	40 ACE	SP	CCA		V	00:00.0
2021 PO1823145010	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1815344929	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1832844803	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1857444966	KU	3	45 XXX	SP	CCA	ED	T	00:00.0
2021 PO1876145222	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO1886145176	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1898945271	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO1918845415	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1930045473	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO1928545498	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO1944645427	F	5	35 XXX	SP	CCA		V	00:00.0
2021 PO1946345482	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO1943445723	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4017084606	F	3	45 ACE	SP	A		V	00:00.0
2021 PO4020184602	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3997884179	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO9953585977	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO3998484177	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3998283693	F	4	40 BRO	SP	A		V	00:00.0
2021 PO5276924516	KU	3	45 UNK	SP	CRE		V	00:00.0
2021 PO5271224482	KU	2	45 UNK	SP	CCA		V	00:00.0
2021 PO5360825737	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO4470788327	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4470988321	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4471288314	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4002183692	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4003483714-A	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4001783733	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4470988159	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4469288361	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4469688353	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO6256850937	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8120046326	KU	3	50 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8121846344	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO8241546023	KU	5	35 UNK	SP	CCA	ID	BD	00:00.0
2021 PO8243046051	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO9891422486	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5525607043	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO6396899115	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6402299208	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6398699251	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6389999288	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6405899285	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5547206312	F	5	35 XXX	SP	CRE		V	00:00.0
2021 PO5529505909	KU	3	40 XXX	SP	CCA		V	00:00.0
2021 PO4387785393	LGE	4	40 ACE	SP	A		V	00:00.0

2021	PO6158500903	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6160801001	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6165801106	F	2	50 ACE	SP	P		V	00:00.0
2021	PO6169601234	F	2	45 ACE	SP	CRE		V	00:00.0
2021	PO6172101209	F	3	45 ACE	SP	CRE		V	00:00.0
2021	PO4386585454	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021	PO4387485460	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4387385454	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4388385454	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4387985450	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4387585435	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4388185439	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4388985429	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4389585421	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4390885404	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4390185413	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO6377099345	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6392899044	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4395785381	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4396385391	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4395585392	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4395485402	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4395785364	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4395985372	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4394985375	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4393885372	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4899085492	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4373885272	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4392985382	F	4	40 ACE	DF	A		V	00:00.0
2021	PO4391485379	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4392185388	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4391785393	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4391385394	F	3	45 ACE	DF	CRE		V	00:00.0
2021	PO4898685491	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO6535299556	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4389685470	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4389285485	F	4	30 ACE	SP	P		V	00:00.0
2021	PO4389885480	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4390285493	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4390685487	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4391285499	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4391485493	F	4	40 ACE	DF	CRE		V	00:00.0
2021	PO4392585498	F	4	30 ACE	SP	A		V	00:00.0
2021	PO4392385492	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6521199777	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6516599657	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6512199544	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6509599478	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6502799362	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6514899302	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6525399259	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6437699850	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6433699872	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6427099802	F	4	40 ACE	SP	P		V	00:00.0

2021 PO6433699779	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6427599659	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6412899742	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4397985423	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4398685415	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO6417299478	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6412099390	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4399385406	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4400185408	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4399985398	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4400785389	F	3	45 ACE	SP	A	V	00:00.0
2021 4400785389-a	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO1164966151	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4400985382	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4382885699	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4381685715	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6185301346	F	4	50 ACE	SP	CRE	V	00:00.0
2021 PO6182801324	F	2	50 ACE	SP	CRE	V	00:00.0
2021 PO6190101285	F	4	45 ACE	SP	CRE	V	00:00.0
2021 PO6203701036	KU	6	30 ACE	SP	CCA	V	00:00.0
2021 PO6208701125	KU	6	30 ACE	SP	CCA	V	00:00.0
2021 PO4898285576	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4387085401	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4386585408	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4385785418	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4384385423	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO4384185434	F	4	30 ACE	SP	A	V	00:00.0
2021 PO6456600192	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6450300076	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4384985428	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4384785435	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4384485445	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO4384985441	F	3	45 ACE	SP	CRE	V	00:00.0
2021 PO6444199969	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4385885448	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4386385459	F	4	30 ACE	SP	CRE	V	00:00.0
2021 4385885448-A	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO6145700437	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4381285374	F	4	40 ACE	SP	P	V	00:00.0
2021 4365785502-A	F	5	25E ACE	SP	CRE	V	00:00.0
2021 PO5812505694	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO6419200783	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6428000733	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6436000688	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6148200719	F	2	50 ACE	SP	CRE	V	00:00.0
2021 PO6151800707	F	2	50 ACE	SP	CRE	V	00:00.0
2021 PO6152700765	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4392385323	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4391785320	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4390885321	F	3	50 ACE	SP	CRE	V	00:00.0
2021 PO4389885323	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4388985326	F	4	40 ACE	SP	A	V	00:00.0
2021 PO4374685231	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4383985340	F	4	40 ACE	SP	CRE	V	00:00.0

2021 PO4384685361	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4366085491	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4367485481	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4368285471	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4369285460	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4369885454	F	4	35 ACE	SP	CCA		V	00:00.0
2021 4369885454a	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4383285348	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4382585358	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4381985366	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4379885396	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4379485405	F	4	30 ACE	SP	CRE	ED	V	00:00.0
2021 PO4379985402	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4380285412	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4380585407	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4381085418	F	4	30 ACE	SP	A		V	00:00.0
2021 PO4352585600	LGE	6	20E ACE	SP	CCA	ED	V	00:00.0
2021 PO6418800080	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4381385413	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4382085421	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4382085416	F	4	40 ACE	SP	A		V	00:00.0
2021 4379485337-A	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4381785309	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4380785321	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4379485337	F	6	35 ACE	SP	CRE		V	00:00.0
2021 PO4376585372	F	4	40 ACE	SP	CRE		V	00:00.0
2021 435685383A	KU	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4375685383	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO0907766139	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4372285319	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4385885315	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4385285322	F	4	40 ACE	SP	A		V	00:00.0
2021 PO8265688591	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO8237188843	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO0944365706	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4378885345	F	5	35 ACE	SP	P		V	00:00.0
2021 4378885345-A	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4376085388	F	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4377385373	F	1	55 ACE	SP	CRE		V	00:00.0
2021 PO4376785388	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO6379099802	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6141400090	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4385685375	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4385885366	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4386685363	F	4	40 ACE	SP	A		V	00:00.0
2021 4386685363-A	F	3	45 ACE	SP	A		V	00:00.0
2021 PO4388885364	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4389485361	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4390385359	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4391385356	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4392585363	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4392285354	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4897785627	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5823705625	KU	4	40 XXX	SP	CCA		V	00:00.0

2021	PO5823205701	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5822505762	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5813605927	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5798005962	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5797706109	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5796706263	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5795706394	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5794706553	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5800506700	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5805506809	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5805106910	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO5574106280	KU	3	45 XXX	SP	CCA	V	00:00.0
2021	PO6145499520	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6141599772	F	3	45 ACE	SP	CRE	V	00:00.0
2021	PO6140099859	F	2	45 ACE	SP	CRE	V	00:00.0
2021	PO6139099932	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4393585353	F	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4393785339	F	4	30 ACE	SP	CCA	V	00:00.0
2021	PO4392885350	F	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4392985341	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4392685331	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO1072865717	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO6136700074	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6137500104	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4898785526	F	4	30 BRO	SP	CCA	V	00:00.0
2021	PO6141100233	F	4	45 ACE	SP	P	V	00:00.0
2021	PO4388985468	F	4	30 ACE	SP	CRE	V	00:00.0
2021	PO4898885389	F	4	40 BRO	SP	CCA	V	00:00.0
2021	PO4397585470	F	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4398185462	F	4	40 ACE	SP	A	V	00:00.0
2021	PO4396985478	F	4	40 ACE	SP	A	V	00:00.0
2021	PO4396585483	F	4	40 ACE	SP	A	V	00:00.0
2021	PO6593699598	F	4	40 ACE	SP	P	V	00:00.0
2021	PO6604699518	F	4	40 ACE	SP	P	V	00:00.0
2021	PO6579399349	F	4	40 ACE	SP	P	V	00:00.0
2021	PO4395885492	F	4	40 ACE	SP	P	V	00:00.0
2021	PO4395085501	F	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4394685509	F	3	45 ACE	SP	CCA	V	00:00.0
2021	PO4394885518	F	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4395685524	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4396485530	F	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4397285536	F	4	40 ACE	SP	CCA	V	00:00.0
2021	PO6590699280	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6577399041	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6564899135	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6553899155	F	4	40 ACE	SP	P	V	00:00.0
2021	PO4398085543	F	3	45 ACE	SP	CCA	V	00:00.0
2021	PO4398785547	F	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4399885545	F	3	45 ACE	SP	CCA	V	00:00.0
2021	PO4906085395	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4906185391	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021	PO4400485538	F	3	45 ACE	SP	CCA	V	00:00.0
2021	PO8072688579	KU	4	40 XXX	SP	S	V	00:00.0
2021	PO4380685382	F	4	40 ACE	SP	A	V	00:00.0

2021 PO5822105422	KU	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO4379985390	F	4	40 ACE	SP	A		V	00:00.0	
2021 PO4379485386	F	4	30 ACE	SP	CRE		V	00:00.0	
2021 PO4379185396	F	4	30 ACE	SP	A		V	00:00.0	
2021 PO5812905326	KU	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO5805005340	KU	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO5797105421	KU	5	35 XXX	SP	CCA		V	00:00.0	
2021 PO4357985486	F	UNK	20 ACE	SP	CCA		V	00:00.0	
2021 PO4383585414	F	4	30 ACE	SP	CRE		V	00:00.0	
2021 PO4383085410	F	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4383785401	F	4	40 ACE	SP	A		V	00:00.0	
2021 PO4384385393	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4385085384	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4385185361	F	4	30 ACE	SP	CRE		V	00:00.0	
2021 PO4360785691	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4361585680	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4362385670	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4362785671	F	3	40 ACE	SP	P		V	00:00.0	
2021 PO4363185659	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4361885683	F	2	35 ACE	SP	CRE		V	00:00.0	
2021 PO4363585660	F	3	40 ACE	SP	CRE		V	00:00.0	
2021 PO4367885734	F	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4366885748	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4376585636	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4377485643	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4378385649	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4379185655	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4379985662	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3795903935	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO6986147256	KU	3	45 XXX	SP	CRE	ID,IP	TD		00:00.0
2021 PO6985847134	F	5	35 XXX	SP	P		V		00:00.0
2021 PO6984147073	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO6985447006	F	6	30 XXX	SP	CRE		V		00:00.0
2021 PO6980646975	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO6999146956	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4407885437	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021 PO7459507009	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7469106895	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7479306987	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7490907134	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7485707242	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7484907483	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7496707214	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7502707355	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7513907590	F	4	40 XXX	SP	P		V		00:00.0
2021 PO7510007471	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7503607497	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7493007540	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7483507605	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7504007840	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7493007873	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO7484207857	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO2249622145	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO7474306690	F	4	40 XXX	SP	CRE		V		00:00.0

2021	PO7464206602	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO7452106497	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO7450006427	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5543810806	KU	5	30 BRN	SP	CRE	ED,ID		TD	00:00.0
2021	PO7484806784	F	4	40 XXX	SP	P			V	00:00.0
2021	PO5770509252	KU	4	40 BRN	SP	CCA			V	00:00.0
2021	PO4266986608	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021	PO7433305318	F	4	45 UNK	SP	CRE			V	00:00.0
2021	PO7454905182	F	4	45 UNK	SP	CRE			V	00:00.0
2021	PO7444305249	F	4	45 MAR	SP	P			V	00:00.0
2021	PO7465505113	F	4	40 UNK	SP	CRE			V	00:00.0
2021	PO7479005028	F	4	40 UNK	SP	CRE			V	00:00.0
2021	PO4430585570	LGE	3	50 BRO	SP	CCA			V	00:00.0
2021	PO5500911052	KU	4	40 BRN	SP	CRE	ED,ID		TD	00:00.0
2021	PO7461106821	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5577912423	KU	3	45 KOP	SP	CCA			V	00:00.0
2021	PO7442406652	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO7452306741	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5498810808	KU	5	45 BRN	SP	CRE	ED,ID		TD	00:00.0
2021	PO7471205379	F	4	40 UNK	SP	CRE			V	00:00.0
2021	PO7458705459	F	4	40 UNK	SP	CRE			V	00:00.0
2021	PO7507208186	F	4	40 XXX	SP	P			V	00:00.0
2021	PO7504308130	F	6	30 XXX	SP	CRE			V	00:00.0
2021	PO7475408274	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO4284286674	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO9896179007	LGE	1	55 BRO	SP	CCA			V	00:00.0
2021	PO4423085541	LGE	4	40 BRO	SP	P			V	00:00.0
2021	PO4420485524	F	4	40 BRO	SP	CRE			V	00:00.0
2021	PO7506108481	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO7517008444	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO4424385550	F	4	40 BRO	SP	A			V	00:00.0
2021	PO4425385561	F	4	40 BRO	SP	CCA			V	00:00.0
2021	PO4425685558	F	4	40 BRO	SP	CCA			V	00:00.0
2021	PO9878779058	LGE	1	60 BRO	SP	CCA			V	00:00.0
2021	PO4278286692	LGE	1	60 BRO	SP	CCA			V	00:00.0
2021	PO4278886681	F	4	30 BRO	SP	A			V	00:00.0
2021	PO5624311368	KU	4	40 UNK	SP	CCA			V	00:00.0
2021	PO5624011451	KU	4	40 UNK	SP	CCA			V	00:00.0
2021	PO5603011462	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO8450286485	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO8430886707	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO5589811411	KU	6	30 UNK	SP	CRE			BD	00:00.0
2021	PO7610607882	KU	4	50 BRN	SP	CRE	ED		TD	00:00.0
2021	PO7620307968	KU	2	55 BRN	SP	CCA			V	00:00.0
2021	PO7633608083	KU	1	65 BRN	SP	CCA			V	00:00.0
2021	PO7646107946	KU	2	50 BRN	SP	CRE	ED,IP		TD	00:00.0
2021	PO5597411420	KU	6	30 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO5595711083	KU	4	40 UNK	SP	CCA			V	00:00.0
2021	PO5661510983	KU	4	40 UNK	SP	CRE			BD	00:00.0
2021	PO8401287046	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO7444207875	F	4	40 XXX	SP	CRE	ED,ID,IP,RB	BX	PX	00:00.0
2021	PO7529407958	F	3	45 XXX	SP	CRE	ED,ID,IP,RB	BX	PX	00:00.0
2021	PO7617306342	KU	4	40 XXX	SP	CRE	ED,HH,ID,IP,MD,RB	BX	RP1	00:00.0
2021	PO7734506463	KU	4	30 BRN	SP	CRE	ED,HH,ID	X	RP1	00:00.0



2021 PO7741806553	KU	6	35 BRN	SP	CRE	ED,HH,ID	X	RP1	00:00.0
2021 PO5453310543	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7438800647	KU	3	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO5595810842	KU	4	40 UNK	SP	CRE		TD		00:00.0
2021 PO5733209298	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO7879408902	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO5598811626	KU	4	40 KOP	SP	CRE		TD		00:00.0
2021 PO5653613462	KU	4	45 UNK	SP	CRE		TD		00:00.0
2021 PO8634100467	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO5562112486	KU	3	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5571112736	KU	2	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5637411677	KU	3	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5017408238	KU	1	75 XXX	DF	CRE		V		00:00.0
2021 PO5596411899	F	4	40 UNK	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO5488313165	KU	4	40 UNK	SP	CRE	ED,ID,IP,SRC	TX	RR	00:00.0
2021 PO5239307348	KU	1	75 XXX	ST	CRE		V		00:00.0
2021 PO5213707445	KU	1	70 XXX	DF	CRE		V		00:00.0
2021 PO5187907544	KU	1	80 XXX	DF	CRE		V		00:00.0
2021 PO5263607221	KU	1	75 XXX	DF	CRE		V		00:00.0
2021 PO5264607242	KU	1	75 XXX	SP	CRE		V		00:00.0
2021 PO5137007747	KU	1	70 XXX	DF	CRE		V		00:00.0
2021 PO5174307608	KU	1	75 XXX	DF	CRE		V		00:00.0
2021 PO5045008122	KU	1	75 XXX	DF	CRE		V		00:00.0
2021 PO4962008466	KU	1	75 XXX	DF	CRE		V		00:00.0
2021 PO4989708353	KU	1	70 XXX	CON	CRE		V		00:00.0
2021 PO5111607847	KU	1	80 XXX	DF	CRE		V		00:00.0
2021 PO4938008568	KU	1	75 XXX	ST	CRE		V		00:00.0
2021 PO5291709234	KU	2	50 XXX	SP	CRE		V		00:00.0
2021 PO5753811015	KU	1	70 KOP	SP	CRE		V		00:00.0
2021 PO5744811218	KU	2	70 KOP	SP	CRE		V		00:00.0
2021 PO5827109599	KU	1	80 KOP	SP	CRE		V		00:00.0
2021 PO5727811471	KU	2	65 KOP	SP	CRE		V		00:00.0
2021 PO5028718424	KU	5	35 UNK	ST	CCA		V		00:00.0
2021 PO5283307465	KU	2	50 XXX	SP	CRE		V		00:00.0
2021 PO5293909228	KU	2	50 XXX	SP	CRE		V		00:00.0
2021 PO4419007158	KU	3	45 KOP	SP	CCA		V		00:00.0
2021 PO5578012119	KU	4	45 KOP	SP	CRE	ID	TD		00:00.0
2021 PO4393808518	KU	5	35 KOP	SP	CCA	ED	T		00:00.0
2021 PO4367108564	KU	5	35 KOP	SP	CCA	ED	T		00:00.0
2021 PO5569211872	KU	5	35 KOP	SP	CCA	ED	T		00:00.0
2021 PO4659013271	KU	5	35 KOP	SP	CCA	ED	T		00:00.0
2021 PO7127622934	KU	4	40 KOP	SP	CCA	ED	T		00:00.0
2021 PO4427208485	KU	5	35 KOP	SP	CCA	ED	T		00:00.0
2021 PO5480510958	KU	6	30 KOP	SP	CRE	ID	TD		00:00.0
2021 PO5737810995	F	4	40 KOP	SP	CRE	ED,IP	BX	RP3	00:00.0
2021 PO5554812512	KU	5	35 KOP	SP	CRE	ID,RB	TX	RR	00:00.0
2021 PO5623410316	KU	6	30 KOP	SP	CRE	ID	TD		00:00.0
2021 PO4288086590	LGE	3	25 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4282986321	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5572813173	F	5	40 UNK	SP	CRE		V		00:00.0
2021 PO5714812831	F	3	40 UNK	SP	CRE		V		00:00.0
2021 PO2216022394	KU	3	40 BRN	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021 PO2437019935	KU	4	40 BRN	SP	CRE	RB	X	PX	00:00.0
2021 PO2216122520	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0

2021	PO5569612078	KU	1	60 UNK	SP	CRE	ID	BD		00:00.0
2021	PO6675223608	KU	4	40 XXX	SP	CRE	ID,IP	TX	RR	00:00.0
2021	PO5587012583	KU	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021	PO5854816913	KU	4	40 UNK	SP	CRE	ED,ID	BD		00:00.0
2021	PO5237207681	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5700814053	KU	3	50 UNK	SP	P		BD		00:00.0
2021	PO5024318085	KU	3	45 BRO	SP	CRE	ID	BD		00:00.0
2021	PO5553511938	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5596312310	KU	2	45 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5536706864	KU	3	45 BRN	SP	CRE	ED,EP,HH,ID	X	RP2	00:00.0
2021	PO5540814030	KU	4	45 UNK	SP	CRE		BD		00:00.0
2021	PO7275205502	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO7266305582	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO7431205881	F	4	30 BRN	SP	CCA		V		00:00.0
2021	PO7411006121	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO7298105310	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO7339605552	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5513308237	KU	4	45 BRN	SP	CCA		V		00:00.0
2021	PO4278286575	F	4	30 ACE	SP	CRE		V		00:00.0
2021	PO5611606881	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5562706585	KU	2	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5480908438	KU	2	60 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5558907119	KU	3	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5576107041	KU	3	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5468007836	KU	2	60 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5540306858	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5500907408	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO5598607877	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO7687505349	KU	2	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5322815624	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO2222321275	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO2261520722	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO7686005853	KU	2	45 BRN	SP	CRE	ED	BD		00:00.0
2021	PO7686605671	KU	2	45 BRN	SP	CRE	ED	BD		00:00.0
2021	PO7687005512	KU	2	45 BRN	SP	CRE	ED	BD		00:00.0
2021	PO5574007731	KU	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO4277686530	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4278086458	LGE	1	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4277686605	LGE	1	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4489087936	LGE	3	45 ACE	SP	CCA	ED	BD		00:00.0
2021	PO9915777390	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PV4272986706	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7344805619	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5539807512	KU	3	45 BRN	SP	CRE		BD		00:00.0
2021	PO5549012506	KU	5	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5572907055	KU	3	45 BRN	SP	CRE	ID,IP	BD		00:00.0
2021	PO5469511694	KU	4	45 UNK	SP	CRE	ED,ID	BD		00:00.0
2021	PO5491414236	KU	4	45 UNK	SP	CRE		BD		00:00.0
2021	PO5486311910	KU	4	40 UNK	SP	CRE		BD		00:00.0
2021	PO5471911556	KU	5	35 UNK	SP	P		BD		00:00.0
2021	PO6340419168	KU	4	40 UNK	SP	CRE	ED,ID,IP	BX	PX	00:00.0
2021	PO6110321829	KU	4	40 UNK	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021	PO5462713312	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5037518402	KU	4	40 UNK	SP	CRE		V		00:00.0

2021 PO5035418352	KU	3	45 UNK	SP	CRE		V	00:00.0
2021 PO5432912106	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5491214330	KU	4	45 UNK	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7403907576	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5875012676	F	5	35 UNK	SP	CCA		V	00:00.0
2021 PO5260909179	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5264609153	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5272709104	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5268309131	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5278009070	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5282609041	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5635811779	KU	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5246607946	KU	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5705012052	KU	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5049806878	KU	4	45 XXX	SP	S		V	00:00.0
2021 PO4523387905	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4274286625	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4423285655	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO5419612032	F	6	30 UNK	SP	CCA		V	00:00.0
2021 PO5635912986	KU	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6424724609	F	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5600212311	KU	5	35 KOP	SP	CRE	ED,ID	V	00:00.0
2021 PO5535711767	KU	6	30 KOP	SP	CRE		V	00:00.0
2021 PO4518187865	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4507787779	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4538987880	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4390685888	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4526887639	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4527187622	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4515587943	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4510987922	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4500287890	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6852523748	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5528513646	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5608312233	KU	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6230322911	KU	4	40 XXX	SP	CRE	ED,ID,MD	BX PX	00:00.0
2021 PO6315023816	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4283486577	LGE	4	35 ACE	SP	A	ED,MD	VX RP1	00:00.0
2021 PO4278686383	LGE	2	55 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4278486399	LGE	3	55 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5473411796	KU	4	40 UNK	SP	P	ED,ID,IP	BD	00:00.0
2021 PO5749714666	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO5630213183	F	4	40 UNK	SP	P		V	00:00.0
2021 PO4514287940	F	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO5444812291	F	4	40 UNK	SP	CRE	ED	V	00:00.0
2021 PO5481712034	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5487512197	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5415011993	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5477011902	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6276823523	KU	4	40 UNK	SP	CRE	ED,EP,ID	TD	00:00.0
2021 PO4516887588	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4534587803	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO2528621987	KU	4	45 BRN	SP	CRE		V	00:00.0
2021 PO5400013861	F	5	35 BRO	SP	CCA		V	00:00.0

2021	PO5557407355	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO5324818599	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO5327218219	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO5473714034	KU	6	30 UNK	SP	P	ED,ID	TD	00:00.0
2021	PO5566413690	KU	4	30 CPT	SP	P	ED,ID	TD	00:00.0
2021	PO5244708577	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5307715883	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO5626413117	KU	5	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021	PO5426113440	KU	5	35 UNK	SP	CRE	ID,IP	BD	00:00.0
2021	PO2249722211	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5393613705	KU	3	45 UNK	SP	CRE	ID,IP	BD	00:00.0
2021	PO5267208481	KU	3	45 XXX	SP	CRE	ED,ID,RB	BX	PX 00:00.0
2021	PO2205423095	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO2262621007	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4278986290	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO2250623031	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO2224021042	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO2187622661	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8423201595	KU	1	55 XXX	SP	S		V	00:00.0
2021	PO6657197302	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO6645397275	KU	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6642497262	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6628997320	F	4	40 ACE	SP	P		BD	00:00.0
2021	PO6636397511	F	4	40 ACE	SP	P		V	00:00.0
2021	PO5186284548	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO9010259117	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PO5217684229	F	3	45 ACE	SP	P		V	00:00.0
2021	PO6512196758	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6508396608	F	3	40 ACE	SP	P		V	00:00.0
2021	PO6528796696	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6504896470	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6508496456	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6518996473	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4367185760	LGE	4	40 ACE	SP	CRE	ED,IP	TD	00:00.0
2021	PO4369485777	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0
2021	PO4365885750	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO4368785772	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4372985802	LGE	3	45 ACE	SP	P	ED	TD	00:00.0
2021	PO4364985743	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4371485808	LGE	H2	65 ACE	SP	CCA		V	00:00.0
2021	PO4370885819	LGE	UNK	65 ACE	SP	P		V	00:00.0
2021	PO4373385804	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4375485820	LGE	4	40 ACE	SP	CRE	ED,IP	TD	00:00.0
2021	PO4374485812	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0
2021	PO4402085516	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4858384753	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD	00:00.0
2021	PO4858384753-A	KU	5	35 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4859884757	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR 00:00.0
2021	PO4859884757-A	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5172284813	LGE	4	40 ACE	SP	CCA	ID	V	00:00.0
2021	PO4864384801	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5124585095	LGE	2	60 ACE	SP	CCA		V	00:00.0
2021	PO5123685083	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5121985072	LGE	3	45 ACE	SP	P		V	00:00.0

2021 PO4542388028	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4542988019	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4543488010	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4545987970	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4544987987	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4545487979	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4546588021	LGE	C1	45 BRO	COMP	CCA		V	00:00.0
2021 PO4543988003	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4544387996	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4547088013	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4547588004	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4548187995	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4548687987	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4549787970	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4550287962	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4550887953	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4521987719	F	3	50 BRO	SP	CRE		V	00:00.0
2021 PO4520887736	F	3	50 BRO	SP	P		V	00:00.0
2021 PO4865784800	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4866484812	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4864684803	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4866084776	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4867384759	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4866584754	LGE	4	30 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO4869184752	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4872284743	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4871784751	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4874284738	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4365085919	LGE	3	50 ACE	SP	A	ED,MD	BD	00:00.0
2021 PO4365185937	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4366385926	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5122485176	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO8648262399	LGE	4	35 ACE	SP	P		V	00:00.0
2021 PO5169585220	LGE	4	40 ACE	SP	P		V	00:00.0
2021 PO5173385189	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO8888765288	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4868384864	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4504387763	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4505187749	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4506887793	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO5172685091	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5173285142	LGE	4	40 ACE	SP	A	ED	TD	00:00.0
2021 PO5150384886	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO5151684901	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4557087970	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4869084871	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4869784867	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5153784903	LGE	4	40 ACE	SP	CCA	ED	TD	00:00.0
2021 PO5169384907	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4558187952	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4557687961	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4863484816	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8884264657	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5171784945	LGE	4	35 ACE	SP	CCA		V	00:00.0

2021	PO5174884901	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5171084894	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4854384749	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4855584750	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4551487925	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4552387931	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4552087928	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4860584722	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4859984724	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4540088001	LGE	3	50 BRO	SP	CCA	ED,ID	BD	00:00.0
2021	PO4541888036	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5170784850	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4859584733	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO5168984840	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO5168084840	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5506908463	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5503908367	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5500808273	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5528208120	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5317310619	KU	6	30 XXX	SP	CRE		V	00:00.0
2021	PO4366585892	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021	PO4367385880	LGE	UNK	55 ACE	SP	A	ED	BD	00:00.0
2021	PO4367585876	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO6626498834	KU	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4539887941	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8261600214	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8265800065	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8269999921	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8274099776	KU	3	40 XXX	SP	S		V	00:00.0
2021	PO8278499628	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8283699445	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO8295399731	KU	2	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO4368485860	LGE	4	25 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4367985868	LGE	3	30 ACE	SP	CCA		V	00:00.0
2021	PO4368285864	LGE	UNK	65 ACE	SP	CRE		V	00:00.0
2021	PO4368785856	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4539487940	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4540087931	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4538987948	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4538387957	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO6363199881	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO6356399722	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6349999572	F	3	45 ACE	SP	CRE		V	00:00.0
2021	PO4368885853	LGE	UNK	70 ACE	SP	CRE		V	00:00.0
2021	PO4366785857	LGE	4	40 ACE	SP	CRE	ID	TD	00:00.0
2021	PO6370100103	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4465112808	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4470812946	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4365412834	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4368712960	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4354613142	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4333412980	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4338313158	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4335613292	KU	3	45 XXX	SP	CCA		V	00:00.0

2021 PO4342713294	KU	2	50 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4323613625	KU	2	65 XXX	ST	CRE		V	00:00.0	
2021 PO4320213626	KU	4	35 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO4349813511	KU	2	70 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO4381013334	KU	2	70 XXX	ST	CRE		V	00:00.0	
2021 PO5601008062	F	3	40 XXX	SP	CCA		V	00:00.0	
2021 PO4854584959	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4855684964	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4535787988	LGE	4	30 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4545287918	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO6701497693	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO6696397584	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO6687997365	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4856484943	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4359885851	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4544187936	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0	
2021 PO4544687927-A	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0	
2021 PO4544687927	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	00:00.0	
2021 PO4543587919	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO6691597471	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO6686497337	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4857584938	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4857684949	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO6556597498	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO6553797373	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO6547797205	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO6551497277	KU	4	40 ACE	SP	P		V	00:00.0	
2021 PO6559297608	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO6553797620	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO4858784937	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0	
2021 5172385043A	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4858484917	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4857784914	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4548087936	LGE	4	40 BRO	SP	P	ED,ID,IP	BD	00:00.0	
2021 PO4547587944	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4547087953	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO8874663763	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5171884993	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5171584999	LGE	4	30 ACE	SP	CRE	ID	TD	00:00.0	
2021 4369185920-a	LGE	3	45 ACE	SP	A	ED	TD	00:00.0	
2021 PO4858984898	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4860584884	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4860184874	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO6573297617	F	5	35 ACE	SP	CRE		V	00:00.0	
2021 PO6570897564	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO6586997504	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO6568197455	F	6	30 ACE	SP	CRE		V	00:00.0	
2021 PO4858585033	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4357885905	LGE	4	35 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO4360685919	LGE	4	35 ACE	SP	P	ED	BD	00:00.0	
2021 PO4362185928	LGE	4	35 ACE	SP	A	ID	TD	00:00.0	
2021 PO4363185933	LGE	4	35 ACE	SP	CRE	ED	TD	00:00.0	
2021 4364885945A	LGE	3	30 ACE	SP	P	ED	BD	00:00.0	
2021 PO8282800379	KU	4	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	

2021 PO8232401223	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO8234901519	F	5	30 XXX	SP	P		V	00:00.0
2021 PO8239901649	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8224101599	KU	4	45 XXX	SP	S		V	00:00.0
2021 PO8216801849	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO8241501597	KU	6	30 XXX	SP	CRE		V	00:00.0
2021 PO8244301180	F	6	30 XXX	SP	P		V	00:00.0
2021 PO8240101332	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8272401229	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8247401216	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO6358100326	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6356000287	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6351600212	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6348000148	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6345500104	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4364985853	LGE	4	40 ACE	SP	CRE	ID	TD	00:00.0
2021 PO4859284999	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO6334299889	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4365985854	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4861485043	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4862085045	LGE	3	45 BRO	SP	CRE		V	00:00.0
2021 PO6326399842	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6320199702	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6331200268	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6327100290	KU	6	35 ACE	SP	CCA		V	00:00.0
2021 PO4535687998	LGE	4	40 BRO	SP	CCA	ED,ID	BD	00:00.0
2021 PO6337400389	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO6351400371	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO5783263478	F	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6311400265	KU	6	30 ACE	SP	CRE		V	00:00.0
2021 PO6324600238	KU	6	35 ACE	SP	CCA		V	00:00.0
2021 PO6339100226	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6327300125	F	5	35 ACE	SP	CCA		V	00:00.0
2021 PO6330800082	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO6324199945	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4536187990	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4536787982	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4862285029	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4862285009	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4918085184	F	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4472712764	KU	2	65 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4538988017	LGE	3	55 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4517587889	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4864384841	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8196802641	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO4362985907	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4914585174	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4916285177	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4917985192	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4917485189	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4362185903	LGE	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4362085897	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4920585172	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4363585911	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0



2021	PO6375500212	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4475387876	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4474287869	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO1356955840	KU	6	35 UNK	SP	CRE	ID	TD	00:00.0
2021	PO1378455554	KU	6	35 UNK	SP	CRE	ID	TD	00:00.0
2021	PO1394255395	KU	6	35 UNK	SP	CRE	ID	TD	00:00.0
2021	PO4480287908	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4481387914	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4482087918	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4481887934	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4483987791	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4483387798	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4481787822	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4481187832	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021	PO4480487843	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4050884627	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO9493720396	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO1389753967	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO1401254347	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO1412854739	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO1408354931	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO1408355284	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO1410655343	KU	6	30 KOP	SP	CRE	ID	TD	00:00.0
2021	PO1408355284A	KU	5	30 KOP	SP	CRE	ID	TD	00:00.0
2021	PO1278358541	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO5339633732	KU	5	35 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5333333565	KU	3	45 UNK	SP	CRE	ED,ID	BX	PX 00:00.0
2021	PO4051884621	F	4	35 BRO	SP	P		V	00:00.0
2021	PO4053384622	F	3	45 BRO	SP	P		V	00:00.0
2021	PO4051984627	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5325233353	KU	3	45 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO1293758544	KU	3	45 KOP	SP	P	ID	TD	00:00.0
2021	PO1274858965	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021	PO5275434121	KU	4	40 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5279734231	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5272534048	KU	6	30 UNK	SP	CRE	ED	BD	00:00.0
2021	PO4473487666	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4473587708	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4033185927	LGE	UNK	25 BRO	SP	CRE		V	00:00.0
2021	PO4030985867	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1329158569	KU	3	45 UNK	SP	P	ID	TD	00:00.0
2021	PO1251958618	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021	PO5249633447	KU	3	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5226433925	KU	5	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5207234310	KU	4	40 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5213934482	KU	4	45 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5220934661	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO4469487727	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO4469787718	LGE	1	70 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4468787736	LGE	1	70 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO5245834302	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5250034412	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5241634189	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5234834015	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0

2021	PO5228633851	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO1223358405	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021	PO7412477883	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0
2021	PO4463188072	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4462488069	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4453688345	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO8454787216	F	4	40 ACE	SP	P		V	00:00.0
2021	PO4028786607	LGE	UNK	45E ACE	SP	CRE		V	00:00.0
2021	PO4481187768	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4572688173	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO5343533266	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021	PO4026588615	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4026088615	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4027088618	LGE	UNK	40E ACE	SP	CRE	ED	BD	00:00.0
2021	PO8939152682	ODP	4	40 BRN	SP	S		V	00:00.0
2021	PO8909052666	ODP	3	45 BRN	SP	S		V	00:00.0
2021	PO8898952449	ODP	3	45 BRN	SP	S		V	00:00.0
2021	PO2874688458	KU	6	30 BRO	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021	PO4554888140	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0
2021	PO4554588138	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4553788132	LGE	4	45 ACE	SP	CRE		V	00:00.0
2021	PO4552588123	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021	PO4552188121	LGE	3	50 ACE	SP	CCA	EP,ID	BD	00:00.0
2021	PO4552388110	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8348885487	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8922254678A	ODP	4	40 BRN	SP	S		V	00:00.0
2021	PO8916854334	F	4	40 BRN	SP	P		V	00:00.0
2021	PO8299485529	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8318385723	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5307732891	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO4478187490	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO4553488111	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021	PO3980985619	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO2622893626	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO3979585605	LGE	3	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3978285624	LGE	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3978085621	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO3977885615	F	3	50 BRO	SP	P		V	00:00.0
2021	PO4463288141	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4463288130	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4452988122	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5313233034	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO5292033290	KU	6	30 UNK	UN	CRE		V	00:00.0
2021	PO4554488102	LGE	1	70 ACE	SP	CCA		V	00:00.0
2021	PO5308033926	KU	4	40 UNK	SP	CRE	ED	BD	00:00.0
2021	PO4557288114	F	2	55 ACE	SP	CCA		V	00:00.0
2021	PO4559688130	F	4	50 ACE	SP	CRE		V	00:00.0
2021	PO4479487493	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5347834967	KU	4	40 UNK	SP	CRE	ED	BD	00:00.0
2021	PO4566488175	F	4	50 ACE	SP	CRE		V	00:00.0
2021	PO4567788183	F	4	50 ACE	SP	CRE		V	00:00.0
2021	PO8363886200	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5352435094	KU	4	40 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5354035138	KU	4	40 UNK	SP	CRE	ED,ID	BX	PX 00:00.0

2021	PO5342934834	KU	5	35 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5340934779	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4563788087	LGE	4	40 ACE	SP	CRE	ED,HH,ID	BD	00:00.0
2021	PO8364586452	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4472287652	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021	PO4561988087	F	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4472487654	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO5336734664	KU	4	40 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5330734502	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO2865289834	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO8433986039	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO2720293431	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5160834294	KU	2	45 UNK	SP	CCA		V	00:00.0
2021	PO5162634226	KU	3	45 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5316334138	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO2826689811	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO2880089800	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2878589704	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2842589877	KU	3	45 BRO	SP	CRE	ID,IP,SRS	TD	00:00.0
2021	PO8333585881	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO0757552255	F	3	45 UNK	SP	P		V	00:00.0
2021	PO0757552115	F	3	45 KOP	SP	P		V	00:00.0
2021	PO1281358296	KU	4	40 KOP	SP	CCA		V	00:00.0
2021	PO5303433806	KU	6	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5299533708	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO8348786041	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8371086591	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8373586655	KU	3	50 ACE	SP	CCA		V	00:00.0
2021	PO5295133599	KU	4	40 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5283533304	KU	5	35 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5277433149	KU	3	40 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5228735364	KU	6	30 UNK	UN	CRE		V	00:00.0
2021	PO5232735362	KU	3	50 UNK	UN	CRE		V	00:00.0
2021	PO5219535382	KU	6	30 UNK	UN	CRE		V	00:00.0
2021	PO5096333517	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO8418286231	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8402086429	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8390286565	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8403786673	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8381886730	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8377786801	KU	6	30 ACE	SP	CRE		V	00:00.0
2021	PO5135733521	KU	2	65 UNK	SP	CCA		V	00:00.0
2021	PO5172533030	KU	4	45 UNK	SP	CRE	ED	BD	00:00.0
2021	PO1823389141	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4464387668	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4463587660	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4462887653	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4028386658	F	4	30 ACE	SP	P		V	00:00.0
2021	PO4027086649	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO2425781770	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO4548388197	LGE	H6	115 ACE	SP	P		V	00:00.0
2021	PO7424378416	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO4544488101	LGE	1	100 ACE	SP	CRE		V	00:00.0
2021	PO4546288099	LGE	2	65 ACE	SP	CRE	ED,ID	BD	00:00.0

2021 PO4027986667	LGE	2	60 ACE	SP	P	ED	BD	00:00.0	
2021 PO8207759872	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO8219460518	ODP	4	40 BRN	DF	CRE	ED,ID	BD	00:00.0	
2021 PO4543188103	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4038486682	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 4540388106a	LGE	2	65 ACE	SP	CCA	ED,ID	BD	00:00.0	
2021 PO4539188107	LGE	1	55 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4540388106	LGE	1	100 ACE	SP	CRE		V	00:00.0	
2021 PO4040286686	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO4032986644	LGE	4	35 ACE	SP	CRE	ED,ID,MD	TX	RR	00:00.0
2021 PO4034386645	LGE	4	40 ACE	SP	P	ED	BD	00:00.0	
2021 PO4034386652	LGE	4	35 ACE	SP	CRE	ED,IP	BD	00:00.0	
2021 PO2466682303	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021 PO8347384880	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO8336385033	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5463132753	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5467832447	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO0743252481	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO0761552513	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO0775252416	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO9778523432	KU	5	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO9227554787	ODP	5	35 BRN	SP	CRE		V	00:00.0	
2021 PO9218054957	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9285954844	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4549988100	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO0188836420	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO0214936959	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO0789251817	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021 PO0773751962	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO0777552551	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO0772452472	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021 PO0676851773	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO0707552272	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0	
2021 PO8082858677	ODP	4	40 BRN	SP	S		V	00:00.0	
2021 PO8110258610	ODP	4	40 BRN	SP	S		V	00:00.0	
2021 PO8131158659	ODP	4	40 BRN	SP	S		V	00:00.0	
2021 PO8171159012	ODP	4	40 BRN	SP	S		V	00:00.0	
2021 PO8195859317	ODP	4	40 BRN	SP	S		V	00:00.0	
2021 PO8137373433	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO8234570434	ODP	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO8259670268	ODP	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO8447269849	ODP	4	45 XXX	SP	CCA		V	00:00.0	
2021 PO8273070189	ODP	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO8311069950	ODP	3	45 XXX	SP	CCA		V	00:00.0	
2021 PO8262369210	ODP	5	35 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO8239669133	F	4	40 XXX	SP	A		V	00:00.0	
2021 PO8224669368	F	4	40 KOP	SP	P		V	00:00.0	
2021 PO8208369572	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO8197469478	ODP	5	35 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO8198469867	ODP	4	40 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO4552188074	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4552888091	LGE	2	60 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO2193781375	KU	4	40 BRO	SP	A	ED	BD	00:00.0	
2021 PO4550588094	LGE	2	60 ACE	SP	CCA		V	00:00.0	

2021	PO4551888092	LGE	1	105 ACE	SP	CRE		V	00:00.0
2021	PO4552388090	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4029086663	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7531378558	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO5209534928	KU	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO4542788103	LGE	3	55 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4546488105	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO8368185506	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO4894535434	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4880235370	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4035186658	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO5320331808	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO5309131971	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO8355284771	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4033886644	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021	PO4544688106	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO8321585230	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4547688104	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4548288103	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4548988101	F	4	35 ACE	SP	A		V	00:00.0
2021	PO8363185827	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO2444982184	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO8192170679	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021	PO8145470942	ODP	5	35 KOP	SP	CRE	HH,ID	X	RP3 00:00.0
2021	PO8103971612	F	4	40 KOP	SP	CCA		V	00:00.0
2021	PO8094371528	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO8130771840	ODP	5	35 KOP	SP	CRE	ID	TD	00:00.0
2021	PO8090971651	F	4	40 KOP	SP	CRE		V	00:00.0
2021	PO8070471707	ODP	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO8047672274	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO8023272371	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO7992672049	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021	PO8045772013	F	4	45 BRN	SP	CRE		V	00:00.0
2021	PO8069672045	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021	PO5425933266	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO5423533423	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO2459082628	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO2453282310	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO9853795620	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO5381202873	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8632904451	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO8636104422	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO8627904269	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO8598203998	KU	3	50 BRO	SP	CCA		V	00:00.0
2021	PO8620904119	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO8613403972	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO8617803776	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO8621303613	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO8634403482	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO8565503152	F	3	45 CPT	SP	CCA		V	00:00.0
2021	PO8544702957	F	3	45 CPT	SP	CCA		V	00:00.0
2021	PO2542519735	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO2550519704	F	4	45 BRN	SP	A		V	00:00.0
2021	PO5369302929	F	4	40 ACE	SP	P		V	00:00.0

2021 PO8563403977	KU	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8637304586	KU	2	50 BRO	SP	CCA	V	00:00.0
2021 PO8421601803	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO5495902251	KU	5	35 ACE	SP	CCA	V	00:00.0
2021 PO4419585943	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4418085943	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4368585188	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4370785190	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4369985198	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4370985206	LGE	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4426485483	LGE	5	35 BRO	SP	CCA	V	00:00.0
2021 PO5785500609	F	3	50 ACE	SP	CCA	V	00:00.0
2021 PO5782000629	KU	1	80 ACE	ST	CRE	V	00:00.0
2021 PO5777400607	KU	6	30 ACE	SP	CCA	V	00:00.0
2021 PO5766800436	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO5754400346	KU	6	30 ACE	SP	CCA	V	00:00.0
2021 PO5729700362	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5978099121	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO5989599097	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5970998675	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5683101177	KU	5	35 ACE	SP	CCA	V	00:00.0
2021 PO5662901289	KU	5	35 ACE	SP	CCA	V	00:00.0
2021 PO5650701048	KU	6	30 ACE	SP	CCA	V	00:00.0
2021 PO5991499156	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4422286048	F	3	50 BRO	SP	A	V	00:00.0
2021 PO4423086049	F	3	50 BRO	SP	A	V	00:00.0
2021 PO4424486050	F	2	55 BRO	SP	A	V	00:00.0
2021 PO5997798317	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5981798363	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO2934319957	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO5991898396	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5998698501	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6006798606	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6017298578	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6028398545	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5860898602	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5869398582	F	4	45 ACE	SP	CRE	V	00:00.0
2021 PO5876698565	F	4	45 ACE	SP	CRE	V	00:00.0
2021 PO5898598551	KU	2	50 ACE	SP	P	V	00:00.0
2021 PO5900598552	F	2	50 ACE	SP	P	V	00:00.0
2021 PO5880398414	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5883798222	F	4	45 ACE	SP	CRE	V	00:00.0
2021 PO5876998206	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5870798156	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5862298086	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4416286072	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO7993412218	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO4415186069	F	4	40 BRO	SP	A	V	00:00.0
2021 PO8131211055	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO5860598766	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO8087007695	KU	2	45 BRN	SP	CCA	V	00:00.0
2021 PO8241409132	KU	1	50 BRN	SP	CRE	V	00:00.0
2021 PO9637296728	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO6023098416	F	4	40 ACE	SP	CRE	V	00:00.0

2021 PO6016498290	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6011698211	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6005598103	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6001598025	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5996298011	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5988097997	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4414086004	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4415186043	F	4	30 BRO	SP	A	V	00:00.0
2021 PO4415186047	F	3	45 BRO	SP	CRE	V	00:00.0
2021 PO4380985172	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO9778295898	KU	6	30 BRO	SP	CCA	V	00:00.0
2021 PO3498616334	KU	H1	105 BRN	AL	CRE	V	00:00.0
2021 PO9784196046	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO9775396233	KU	2	45 KOP	SP	CCA	V	00:00.0
2021 PO2733219128	KU	3	40 BRN	SP	CRE	V	00:00.0
2021 PO4421286048	LGE	2	55 BRO	SP	A	V	00:00.0
2021 PO5953098285	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6062598774	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO2810418870	KU	2	60 BRN	SP	CRE	V	00:00.0
2021 PO8149610563	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4421386000	LGE	4	30 BRO	SP	A	V	00:00.0
2021 PO4421785997	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4421385983	F	4	30 BRO	SP	A	V	00:00.0
2021 PO4421885983	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4421385967	LGE	4	30 BRO	SP	A	V	00:00.0
2021 PO4421885967	LGE	4	40 BRO	SP	A	V	00:00.0
2021 PO4421885947	F	4	40 BRO	SP	A	V	00:00.0
2021 PO9830295426	KU	1	45 BRO	SP	CCA	V	00:00.0
2021 PO9789695519	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4379285002	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO1402973624	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO1406973524	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO5790099266	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4423985844	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4421985853	LGE	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4421985843	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4422885844	F	3	45 BRO	SP	A	V	00:00.0
2021 PO1405973413	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO8211210682 Fay, Egit	KU	3	50 BRN	SP	CCA	V	00:00.0
2021 PO8213710708	KU	3	50 BRN	SP	CCA	V	00:00.0
2021 PO6023798886	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4385884899	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO4421886041	LGE	3	45 BRO	SP	A	V	00:00.0
2021 PO4423086042	LGE	4	35 BRO	SP	A	V	00:00.0
2021 PO4442585722	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4441285716	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO2519722462	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO8254809485	KU	5	40 BRN	SP	CCA	V	00:00.0
2021 PO3158317518	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021 PO3218317233	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021 PO3282516922	KU	H1	100 BRN	SP	CRE	V	00:00.0
2021 PO5784899546	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4387985093	F	4	35 ACE	SP	A	V	00:00.0
2021 PO9659396700	KU	2	45 BRO	SP	CRE	V	00:00.0

2021 PO2742422339	KU		3	45 BRN	SP	CCA	V	00:00.0
2021 PO9692095177	KU		3	45 UNK	SP	CRE	V	00:00.0
2021 PO9661394855	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO9674094888	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO5801399282	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO5790299868	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO5792399953	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO5829000355	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO2602319589	KU		1	65 BRN	SP	CCA	V	00:00.0
2021 PO4081914775	KU	H1		100E BRN	AL	CRE	V	00:00.0
2021 PO4183314310	KU	H1		100 BRN	AL	CRE	V	00:00.0
2021 PO4203014214	KU	H1		100 BRN	AL	CRE	V	00:00.0
2021 PO4302113720	KU	H1		100 BRN	AL	CRE	V	00:00.0
2021 PO5799399169	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO5804099121	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO5817099085	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO5824899064	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO4378684871	LGE		4	35 ACE	SP	CCA	V	00:00.0
2021 PO3454816435	KU	H1		100 BRN	AL	CRE	V	00:00.0
2021 PO3909615356	KU	H1		100 BRN	AL	CRE	V	00:00.0
2021 PO3891315408	KU	H1		100 BRN	AL	CRE	V	00:00.0
2021 PO9732194783	KU		5	35 BRO	SP	CCA	V	00:00.0
2021 PO5809800154	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO5804000187	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO5791900255	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO5797800172	F		4	40 ACE	SP	CRE	V	00:00.0
2021 PO4414086025	LGE		4	40 BRO	SP	CCA	V	00:00.0
2021 PO1274672576	LGE		4	35 BRO	SP	CCA	V	00:00.0
2021 PO4414186043	LGE		3	50 BRO	SP	CCA	V	00:00.0
2021 PO7931005283	KU		2	45 UNK	SP	CRE	V	00:00.0
2021 PO4387585180	LGE		4	30 ACE	SP	CCA	V	00:00.0
2021 PO4413786047	F		3	50 BRO	SP	CRE	V	00:00.0
2021 PO4412986046	F		3	50 BRO	SP	CRE	V	00:00.0
2021 PO8677503011	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO8674803027	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO8688202899	KU		2	50 BRO	SP	CCA	V	00:00.0
2021 PO8697802803	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO8709002688	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO8720202574	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO2619121268	KU		5	35 BRN	SP	CCA	V	00:00.0
2021 PO2524821740	F		4	40 BRN	SP	A	V	00:00.0
2021 PO8969697672	KU		3	45 XXX	SP	S	V	00:00.0
2021 PO8658903186	F		4	45 BRO	SP	CCA	V	00:00.0
2021 PO8668803089	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO7937605222	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO7954505319	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO7962705398	KU		3	45 KOP	SP	CCA	V	00:00.0
2021 PO8727802496	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO8740202371	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO4417686016	LGE		4	35 BRO	SP	CRE	V	00:00.0
2021 PO4418186016	LGE		4	40 BRO	SP	CRE	V	00:00.0
2021 PO4417586003	LGE		4	35 BRO	SP	CRE	V	00:00.0
2021 PO4417685993	LGE		4	35 BRO	SP	CRE	V	00:00.0
2021 PO4418285981	LGE		4	40 BRO	SP	CRE	V	00:00.0



2021 PO4417785968	LGE	4	35 BRO	SP	A	V	00:00.0
2021 PO4418185968	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO2467421415	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5708399499	F	4	45 ACE	SP	CRE	V	00:00.0
2021 PO5716699619	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO5722399703	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5732299845	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5737899926	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5347303030	KU	3	45 ACE	SP	CCA	V	00:00.0
2021 PO5358802955	KU	5	35 ACE	SP	CCA	V	00:00.0
2021 PO8679605317	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8660405014	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8660704963	KU	4	45 BRO	SP	CCA	V	00:00.0
2021 PO8618004675	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO8623904649	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8606404830	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO9700997188B	KU	4	40 XXX	SP	S	V	00:00.0
2021 PO9700997188A	KU	4	40 XXX	SP	S	V	00:00.0
2021 PO9690997579	KU	6	30 XXX	SP	S	V	00:00.0
2021 PO7975006693	KU	2	45 BRN	SP	CRE	V	00:00.0
2021 PO9672897912	KU	5	35 XXX	SP	S	V	00:00.0
2021 PO9648997681	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO9650497831	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO8621906014	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8652304838	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8642704682	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO8647005207	KU	2	45 BRO	SP	CCA	V	00:00.0
2021 PO8597904108	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2498819904	F	4	40 BRN	SP	A	V	00:00.0
2021 PO2525619797	F	4	40 BRN	SP	A	V	00:00.0
2021 PO2506919870	F	4	40 BRN	SP	A	V	00:00.0
2021 PO2511419697	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO2516419833	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5425302679	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO2545520634	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO2528920755	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO2534220808	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO2551020464	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5333603090	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5357702983	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4418186029	LGE	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4418186003	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4371585180	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4417785956	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4418185957	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4417785980	F	4	35 BRO	SP	A	V	00:00.0
2021 PO4418285993	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4368085204	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4368585170	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4367785176	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4367985181	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4419486040	F	4	35 BRO	SP	A	V	00:00.0
2021 PO4368185196	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4419486047	F	2	55 BRO	SP	A	V	00:00.0

2021 PO4369085184	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO5966198095	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3068717953	KU	2	60 BRN	SP	CRE		V	00:00.0	
2021 PO5975898050	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO3093417838	KU	2	65 BRN	SP	CRE		V	00:00.0	
2021 PO5980798028	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO8106111262	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4386285113	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO8126811035	KU	1	45 BRN	SP	CCA		V	00:00.0	
2021 PO3117917722	KU	2	65 BRN	SP	CRE		V	00:00.0	
2021 PO3250517068	KU	2	60 BRN	SP	CRE		V	00:00.0	
2021 PO3279616861	F	4	40 BRN	SP	A		V	00:00.0	
2021 PO4378584796	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO3124917616	KU	2	35 BRN	SP	CCA		V	00:00.0	
2021 PO4418186047	F	3	50 BRO	SP	A		V	00:00.0	
2021 PO3140717609	KU	2	65 BRN	SP	CRE		V	00:00.0	
2021 3158317518a	KU	4	40 BRN	SP	A		V	00:00.0	
2021 PO3149717445	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO7913906243	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO7906806180	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4392285213	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO5743604895	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4907090087	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO5793905167	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5799005256	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5801605303	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5832404095	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5842704098	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5843904056	F	3	45 XXX	SP	P		V	00:00.0	
2021 PO5856904090	KU	6	30 XXX	SP	S	ED	T	00:00.0	
2021 PO5866104093	F	3	40 XXX	SP	P	ID,IP	BX	RP1	00:00.0
2021 PO5916903973	KU	5	30 XXX	SP	S		V	00:00.0	
2021 PO5914903985	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5881904096	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5898704076	F	3	40 XXX	SP	P		V	00:00.0	
2021 PO5882404149	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO5669598669	F	5	30 XXX	SP	P		V	00:00.0	
2021 PO5348602887	F	3	45 XXX	SP	P		V	00:00.0	
2021 PO5334302943	F	3	45 XXX	SP	P		V	00:00.0	
2021 PO5328402785	F	3	45 XXX	SP	P		V	00:00.0	
2021 PO0268635607	KU	4	40 REP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2135962706a	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO2135962706	KU	5	30 BRO	SP	CRE	RB	X	PX	00:00.0
2021 PO5773505417	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5787505357	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO0261835926	KU	4	45 US	ST	CRE		V	00:00.0	
2021 PO0260236247	KU	4	45 US	ST	CCA		V	00:00.0	
2021 PO4905290076	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4903590066	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO5067389507	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO5758205476	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5744505518	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5732005566	F	2	20E BRN	SP	CRE		V	00:00.0	
2021 PO5719805612	KU	3	40 MAR	SP	CRE		V	00:00.0	

2021	PO5747605071	F	4	40 MAR	SP	CRE		V	00:00.0	
2021	PO4829491153	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0	
2021	PO0396030625	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO0417630941	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO5067589520	F	UNK	40 ACE	SP	CRE		V	00:00.0	
2021	PO2144962680	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TX	RR	00:00.0
2021	PO4830191149	LGE	4	30 BRN	SP	A	ED,ID	BD	00:00.0	
2021	PO4836091312	LGE	4	35 BRN	SP	P		V	00:00.0	
2021	PO4834991349	LGE	4	35 BRN	SP	P		V	00:00.0	
2021	PO4833891392	LGE	4	40 BRN	SP	P		V	00:00.0	
2021	PO4831591476	LGE	3	45 BRN	SP	P		V	00:00.0	
2021	PO4822890649	LGE	2	55 BRN	SP	CCA		V	00:00.0	
2021	PO4823590650	LGE	4	30 BRN	SP	CCA		V	00:00.0	
2021	PO4822690624	LGE	1	55 BRN	SP	CCA		V	00:00.0	
2021	PO5069989552	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0	
2021	PO5070189545	F	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO5072289566	F	UNK	40 ACE	SP	A		V	00:00.0	
2021	PO4901990056	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4900390046	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0	
2021	PO4898890036	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021	PO5684105426	F	4	40 MAR	SP	CRE		V	00:00.0	
2021	PO5680905556	F	4	40 MAR	SP	CRE		V	00:00.0	
2021	PO5683605646	F	4	40 MAR	SP	CCA		V	00:00.0	
2021	PO5685705735	F	4	40 MAR	SP	CCA		V	00:00.0	
2021	PO5706105662	F	4	40 MAR	SP	CRE		V	00:00.0	
2021	PO6042149734	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021	PO2152362472	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO7073770201	KU	5	35 BRO	SP	CCA		V	00:00.0	
2021	PO5030089500	LGE	UNK	30 ACE	SP	A		V	00:00.0	
2021	PO4351708506	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4394008494	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4367408524	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4379708540	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO6066449898	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO4900690029	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021	PO5706205235	F	4	40 MAR	SP	P		V	00:00.0	
2021	PO5702705129	F	4	40 MAR	SP	CRE		V	00:00.0	
2021	PO5693405277	F	4	40 MAR	SP	CRE		V	00:00.0	
2021	PO5064189322	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021	PO0435331209	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO6054649826	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021	PO6116749795	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO5064089271	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0	
2021	PO7023272474	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021	PO7008072321	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7016372264	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7026972439	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO7003672073	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO6993772413	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO4312908394	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4330108462	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4287308236	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4299108343	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4897790029	F	3	45 BRO	SP	CCA		V	00:00.0	

2021	PO0454731505	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO0473032414	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO0478932675	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO0484032914	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO0468633274	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4896590031	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO4897090032	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021	PO5749005156	F	4	40 MAR	SP	CRE		V	00:00.0	
2021	PO5740704943	F	4	40 MAR	SP	CRE		V	00:00.0	
2021	PO5732804890	F	4	40 MAR	SP	CRE		V	00:00.0	
2021	PO4897390027	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021	PO2166562274	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO4822690604	LGE	2	55 BRN	SP	CCA		V	00:00.0	
2021	PO4823290506	LGE	1	60 BRN	SP	CCA		V	00:00.0	
2021	PO4823290413	LGE	1	50 BRN	SP	CCA		V	00:00.0	
2021	PO4823290433	LGE	1	50 BRN	SP	CCA		V	00:00.0	
2021	PO4822390452	LGE	4	40 BRN	SP	CCA		V	00:00.0	
2021	PO4823290452	LGE	1	50 BRN	SP	CCA		V	00:00.0	
2021	PO4823290469	LGE	1	50 BRN	SP	CCA		V	00:00.0	
2021	PO4822590584	LGE	2	55 BRN	SP	CCA		V	00:00.0	
2021	PO5291091899	LGE	2	55 BRN	SP	CCA		V	00:00.0	
2021	PO2165561739	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4897790019	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021	PO4898190013	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO5052489339	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO7613506669	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO5053989324	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0	
2021	PO6070049768	KU	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO6087249591	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4822490564	LGE	2	55 BRN	ST	P		V	00:00.0	
2021	PO5289718641	LGE	1	55 BRN	SP	CCA		V	00:00.0	
2021	PO4822390530	LGE	H1	65 BRN	ST	P		V	00:00.0	
2021	PO5293818127	LGE	H2	65 BRN	SP	CCA		V	00:00.0	
2021	PO5369500383	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO5589798475	F	3	45 XXX	SP	P		V	00:00.0	
2021	PO5541598376	F	5	35 XXX	SP	P		V	00:00.0	
2021	PO5441300062	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO5568002965	F	5	30 XXX	SP	CRE		V	00:00.0	
2021	PO5574503077	F	5	30 XXX	SP	CRE		V	00:00.0	
2021	PO5581203169	F	5	30 XXX	SP	CRE		V	00:00.0	
2021	PO5572803218	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO6089549715	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4249908317	KU	5	35 BRN	SP	CCA	ID	BD	00:00.0	
2021	PO5053989358	LGE	1	50 ACE	SP	CCA		V	00:00.0	
2021	PO7632607078	LGE	1	55 ACE	SP	CCA		V	00:00.0	
2021	PO2233561802	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO6060613087	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021	PO4899898982	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021	PO4900589973	LGE	3	50 BRO	SP	CCA		V	00:00.0	
2021	PO7045072505	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4823290489	LGE	1	55 BRN	SP	CCA		V	00:00.0	
2021	PO4280108039	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021	PO4218708286	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4221508275	F	4	40 BRN	SP	CRE		V	00:00.0	

2021	PO4250808157	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4263108108	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4292707973	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4240008200	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO6138449759	KU	3	50 BRO	SP	CCA		V	00:00.0
2021	PO6094749681	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO6109249729	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO6126249679	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5726905281	F	4	40 MAR	SP	CCA		V	00:00.0
2021	PO5719705142	F	4	40 MAR	SP	CRE		V	00:00.0
2021	PO5706005092	F	4	40 MAR	SP	CRE		V	00:00.0
2021	PO5712405017	F	4	40 MAR	SP	CRE		V	00:00.0
2021	PO5724704939	F	4	40 MAR	SP	CRE		V	00:00.0
2021	PO7661107275	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO7650907227	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021		5057089379	LGE	1	50 ACE	SP	CCA	V	00:00.0
2021	PO5057389377	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4823590385	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO4823290393	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO4824090370	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021	PO4823790912	LGE	4	40 BRN	SP	P		V	00:00.0
2021	PO2148761709	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4900989976	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO6124649796	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6124349859	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO6145349725	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO6158349583	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO6154749527	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO6169549441	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO6160149282	KU	4	45 BRO	SP	S		V	00:00.0
2021	PO6035149018	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4901889963	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO7677306680	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO0502033402	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO0496333195	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO5062389296	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	5062389296-a	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO7705106329	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO2131861191	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4900089955	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4899589949	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4901389960	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021	PO6039749174	KU	5	35 BRO	SP	S		V	00:00.0
2021	PO7881708048	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO5060689323	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO7868307984	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO7849007920	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO4902389942	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO7829607861	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO5704203880	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO5743003676	KU	4	30 XXX	SP	CRE		V	00:00.0
2021	PO5745303612	KU	4	30 XXX	SP	CRE		V	00:00.0
2021	PO5754703594	KU	4	30 XXX	SP	CRE		V	00:00.0
2021	PO5722102461	F	4	45 XXX	SP	CRE		V	00:00.0

2021	PO5724102570	F	4	45 XXX	SP	CRE		V	00:00.0
2021	PO5727402667	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5100500988	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO5113700948	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO4902390116-A	LGE	5	35 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO5126900909	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5139600869	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO4871991044	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4871091041	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO5775021744	LGE	H1	70 BRN	SP	P	ED,ID	V	00:00.0
2021	PO5216600653	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5213400662	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5191400724	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5171400779	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO0204129462	KU	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0
2021	PO0207329728	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO0103729683	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5154500828	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5148600849	F	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5190300704	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO0365740313	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO0378140567	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5762421646	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021	PO4869290882	LGE	3	50 BRN	SP	P	ED,ID	V	00:00.0
2021	PO4867990887	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4867190891	LGE	3	45 BRN	SP	P	ED,ID	V	00:00.0
2021	PO4883690952	LGE	1	50 BRN	ST	CCA		V	00:00.0
2021	PO4859490663	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO4895890050	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO5077501058	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5079700987	KU	2	45 BRN	SP	CCA		V	00:00.0
2021	PO5192304629	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO5035889555	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021	PO7443608924	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021	PO5037389570	LGE	3	45 ACE	SP	A		V	00:00.0
2021	PO0095529464	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO0107629809	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO0141429930	KU	4	40 BRO	SP	S		V	00:00.0
2021	PO0164830039	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO0190630157	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO0190730441	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO0198830712	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO4708007745	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4691907937	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4713207870	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4718007979	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO0378440686	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO0423740055	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5001389281	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4667406583	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021	PO5034089119	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5033689122	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO5001289437	LGE	3	45 ACE	SP	CRE	ED	V	00:00.0
2021	PO5001289433	LGE	3	45 ACE	SP	CRE		V	00:00.0

2021	PO0430740015	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO0435539713	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5032089135	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO7435204051	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5755226931	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5754326916	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5751326864	KU	2	55 UNK	SP	CCA		V	00:00.0
2021	PO8114675189	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO8108975134	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8112575010	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8108474821	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8103874633	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO8041874454	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO4008283787	LGE	2	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4008283785	LGE	2	50 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4019884004	LGE	UNK	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5769526820	KU	4	45 UNK	SP	CCA		V	00:00.0
2021	PO5775026903	KU	4	40 UNK	SP	CRE		B	00:00.0
2021	PO5779926996	KU	4	40 UNK	SP	CRE		B	00:00.0
2021	PO5784026972	KU	4	40 UNK	SP	CRE		T	00:00.0
2021	PO7262649562	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO7266049545	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO8041974381	KU	3	40 ACE	SP	CCA		V	00:00.0
2021	PO8041974351	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8047474416	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8050974379	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8075874399	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO8076374321	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO8077274259	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO8078274206	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8061874168	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8038376218	KU	2	65 ACE	ST	CCA		V	00:00.0
2021	PO4019083991	LGE	UNK	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO7270649523	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO5589724624	KU	4	40 UNK	SP	CRE		B	00:00.0
2021	PO8044676397	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO8094375702n	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5588624547	F	3	50 UNK	SP	CRE		V	00:00.0
2021	PO5594824468	F	3	50 UNK	SP	CRE		V	00:00.0
2021	PO5603024374	F	3	50E UNK	SP	CRE		V	00:00.0
2021	PO5576724688	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO5578724666	F	3	50 UNK	SP	CRE		V	00:00.0
2021	PO5574725127	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5573024765	KU	1	50 UNK	SP	CRE		B	00:00.0
2021	PO5572324785	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5578824801	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO5566824960	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO8051076469	KU	3	55 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8047976435	KU	3	50 ACE	SP	CCA		V	00:00.0
2021	PO8050676396	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO8053976439	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4547488202	LGE	4	45 BRN	SP	CRE	ED,HH,ID	BD	00:00.0
2021	PO4548088193	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO8058376549	KU	2	50 ACE	SP	CCA		V	00:00.0

2021 PO8099976584	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO5568124962	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO5574924976	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5566025057	F	5	35 UNK	SP	CCA		V	00:00.0
2021 PO5573125069	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO5619926096	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO8039775937	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8040175743	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8040675515	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8038376188	KU	2	45 ACE	SP	CCA		V	00:00.0
2021 PO8038675957	KU	2	60 ACE	SP	CRE		V	00:00.0
2021 PO8039075776	KU	2	65 ACE	SP	CRE		V	00:00.0
2021 PO8029175676	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8039375540	KU	2	65 ACE	SP	CRE		V	00:00.0
2021 PO8029175532	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8039575404	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8014075272	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4548488186	LGE	3	45 BRN	SP	CRE	ED,HH,ID	BD	00:00.0
2021 PO2571994395	LGE	4	35 BRN	SP	A	ID	BD	00:00.0
2021 PO4548588173	LGE	4	30 BRN	SP	CRE	ED,ID,JP	BD	00:00.0
2021 PO4549088177	LGE	3	45 BRN	SP	CRE	ED,HH,ID	BD	00:00.0
2021 PO5602826173	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5606726232	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5602326094	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO5606426102	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO5624325956	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4024084009	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0
2021 PO2927292794	KU	5	40 ACE	SP	CRE	ID	BD	00:00.0
2021 PO4022984013	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO8040875361	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO4021884018	LGE	4	35 ACE	SP	CCA	ED,ID	V	00:00.0
2021 PO4013683729	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8014275197	KU	4	45 ACE	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO8036475149	KU	4	45 ACE	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO8040175174	KU	2	65 ACE	SP	CRE		V	00:00.0
2021 PO7372552036	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4020584018	LGE	UNK	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4020284013	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4550788199	LGE	4	40 BRN	SP	A	ID	BD	00:00.0
2021 PO4549888194	LGE	4	35 BRN	SP	P	ID	BD	00:00.0
2021 PO5620326199	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO5621526133	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO2588194189	LGE	4	35 BRN	SP	A	ED,HH,ID	BD	00:00.0
2021 PO4549988151	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4550588156	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4549588170	LGE	4	45 BRN	SP	CRE	ED,HH,ID	BD	00:00.0
2021 PO4549888167	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4550188169	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4551288176	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4558588144	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO5618526310	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO8041875042	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8040675032	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 4011783857-C	KU	5	35 BRO	SP	A	ED,ID	TD	00:00.0



2021 PO8041074897	KU	2	65 ACE	SP	CRE		V	00:00.0	
2021 4011783857-B	KU	5	35 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO8042474821	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO8042174725	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO5608126432	KU	5	35 UNK	SP	CRE		B	00:00.0	
2021 PO5606326372	F	5	35 UNK	SP	CRE		V	00:00.0	
2021 4011783857-A	KU	5	35 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO8043074590	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO8041874584	KU	2	65 ACE	SP	CRE		V	00:00.0	
2021 PO4108484530	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4109484526	LGE	4	35 BRO	SP	P		V	00:00.0	
2021 PO4105784493	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO4022784009	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4021584011	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5590626548	KU	4	40 UNK	ST	CCA		V	00:00.0	
2021 PO5579026496	KU	1	80 UNK	ST	CCA		V	00:00.0	
2021 PO5564026476	KU	2	50 UNK	SP	CCA		V	00:00.0	
2021 PO5563726523	KU	3	50 UNK	SP	CCA		V	00:00.0	
2021 PO5558426323	KU	3	45 UNK	SP	CRE		T	00:00.0	
2021 PO4104784513	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4109984492	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4112384452	LGE	4	30 BRO	SP	CRE		B	00:00.0	
2021 PO4111284473	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0	
2021 PO4109284451	LGE	3	45 BRO	SP	CRE	EP,HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4107484456	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4113484471	LGE	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4115084474	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4116384477	LGE	3	45 BRO	SP	A		B	00:00.0	
2021 PO4117484479	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4120784468	LGE	4	35 BRO	SP	P	ED,ID,IP	TD	00:00.0	
2021 PO4069584349	LGE	4	30 BRO	SP	CCA	ED,ID,IP	TD	00:00.0	
2021 PO4088684457	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4089984435	LGE	3	45 BRO	SP	P	ED,ID,IP	BD	00:00.0	
2021 PO8039176164	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO8089674508	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4056984221	LGE	4	40 BRO	SP	P		V	00:00.0	
2021 PO4057284204	LGE	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4089084472	LGE	4	30 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021 PO4088584467	LGE	4	30 BRO	SP	CRE	ED,ID,RB	BX	RP2	00:00.0
2021 PO4094084504	LGE	4	35 BRO	UN	CRE		V	00:00.0	
2021 PO4100984480	LGE	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4111684521	LGE	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4106184542	LGE	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4093384503	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4094084503	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4110984580	LGE	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO8036176309	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8038276318	KU	2	55 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5678625585	KU	3	45 UNK	AL	CCA		V	00:00.0	
2021 PO5692625645	KU	3	45 UNK	AL	CCA		V	00:00.0	
2021 PO8055676217	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO8048276271	KU	4	45 ACE	SP	CCA		V	00:00.0	
2021 PO4110784553	LGE	4	40 BRO	SP	P	ED,EP,ID,IP	BD	00:00.0	
2021 PO4110284549	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0	

2021 PO4108084565	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO4108284558	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0	
2021 PO4124684265	LGE	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4124984259	LGE	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4120484250	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4118884238	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4116884223	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4114784212	LGE	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO5584524690	KU	3	45 UNK	SP	CRE		T	00:00.0	
2021 PO5587424653	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO2883990736	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO2876091287	KU	4	40 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO2877091661	KU	4	45 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO2898292622	KU	4	40 ACE	SP	CRE	ID	BD	00:00.0	
2021 PO2877691998	KU	4	45 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO4726788821	KU	5	35 ACE	SP	CRE		V	00:00.0	
2021 PO4709288669	KU	4	40 ACE	AL	CCA		V	00:00.0	
2021 PO5199187922	KU	4	45 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO5198287971	KU	4	45 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO5261787833	KU	4	50 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO5261287890	KU	4	50 ACE	SP	CRE	ID	TD	00:00.0	
2021 PO4042684178	LGE	4	30 BRO	SP	P	ED,ID,IP	BD	00:00.0	
2021 PO4045484205	LGE	6	25 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7905775841	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PO7902775987	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4046984208	LGE	4	30 BRO	SP	P	ED,ID,IP	TD	00:00.0	
2021 PO4045984267	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4047084249	LGE	4	40 BRO	SP	CCA	ED,ID	TD	00:00.0	
2021 PO4047884242	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4068384340	LGE	UNK	25 BRO	UN	CRE		V	00:00.0	
2021 PO7893876100	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7879176018	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7879275848	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5375026454	KU	3	45 UNK	SP	CRE		B	00:00.0	
2021 PO5371626452	KU	3	45 UNK	SP	CRE		B	00:00.0	
2021 PO5366826448	KU	3	45 UNK	SP	CRE		B	00:00.0	
2021 PO5367426289	KU	3	50 UNK	ST	CCA		V	00:00.0	
2021 PO7871175984	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7862975928	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7862976138	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4049884226	LGE	4	35 BRO	SP	P	ED,ID,IP	TD	00:00.0	
2021 PO4050484241	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4068784336	LGE	3	50 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4068784333	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4068284341	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO5389826365	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO5389926305	KU	4	60 UNK	ST	CCA		V	00:00.0	
2021 PO5402426315	KU	2	60 UNK	ST	CCA		V	00:00.0	
2021 PO7847075832	KU	6	30 ACE	SP	CCA	ED	TD	00:00.0	
2021 PO7843275828	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO7852775673	KU	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7858275553	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5430426245	KU	5	35 UNK	SP	CRE		B	00:00.0	
2021 PO5417126212	F	4	40 UNK	SP	CRE		V	00:00.0	

2021 PO5416826325	KU	2	60 UNK	ST	CCA			V	00:00.0
2021 PO5432326336	KU	1	70 UNK	ST	CCA			V	00:00.0
2021 PO5463526359	KU	3	45 UNK	SP	CCA			V	00:00.0
2021 PO5479926371	KU	3	50 UNK	SP	CCA			V	00:00.0
2021 PO5452126351	KU	1	70 UNK	ST	CCA			V	00:00.0
2021 PO5456426111	KU	4	40 UNK	SP	CRE			B	00:00.0
2021 PO5428725997	KU	5	35 UNK	SP	CRE			B	00:00.0
2021 PO5443526099	KU	3	45 UNK	SP	CRE			T	00:00.0
2021 PO8030876140	KU	6	30 ACE	SP	CCA			V	00:00.0
2021 PO5466726201	KU	4	45 UNK	SP	CCA			V	00:00.0
2021 PO4123784269	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021 PO4124484270	F	4	40 BRO	SP	CCA			V	00:00.0
2021 PO4394888371	KU	4	40 UNK	SP	CRE	ID		TD	00:00.0
2021 PO4393888406	KU	4	40 UNK	SP	CRE	ID		TD	00:00.0
2021 PO4451988323	KU	4	40 UNK	SP	CRE	ID		TD	00:00.0
2021 PO4452488369	KU	4	40 UNK	SP	CRE	ID		TD	00:00.0
2021 PO4565888311	KU	3	45 BRN	SP	CCA			V	00:00.0
2021 PO4481188299	KU	4	40 ACE	SP	CRE	ID		TD	00:00.0
2021 PO4481788346	KU	4	40 ACE	SP	CRE	ID		TD	00:00.0
2021 PO4585388233	KU	4	40 ACE	SP	CRE			T	00:00.0
2021 PO4585388296	KU	4	40 ACE	SP	CRE			T	00:00.0
2021 PO4654688224 B	KU	4	45 ACE	SP	CRE	ID		BD	00:00.0
2021 PO4654688224 A	KU	4	45 ACE	SP	CRE	ED,ID		BX PX	00:00.0
2021 PO4654688224	KU	4	40 BRN	SP	CCA			T	00:00.0
2021 PO4654588184	KU	4	40 BRN	SP	CCA			T	00:00.0
2021 PO4730087587	KU	5	35 BRN	SP	CCA			V	00:00.0
2021 PO4726887619	KU	6	30 BRN	SP	CCA			V	00:00.0
2021 PO4733387720	KU	5	35 BRN	SP	CCA			V	00:00.0
2021 PO4701988486	KU	4	40 BRN	SP	S			V	00:00.0
2021 PO4679887823	KU	4	40 BRN	SP	S			V	00:00.0
2021 PO4698487789	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO7910776192	KU	4	40 ACE	SP	CRE	ED,ID		TD	00:00.0
2021 PO7911676070	KU	6	30 ACE	SP	CRE	ED,ID,IP		BD	00:00.0
2021 PO4960988005	KU	4	45 ACE	SP	CRE	ID		TD	00:00.0
2021 PO4960188054	KU	3	45 ACE	SP	CRE	ID		TD	00:00.0
2021 PO5070387819	KU	4	45 ACE	SP	CRE	ID		TD	00:00.0
2021 PO5069087779	KU	4	45 ACE	SP	CRE	ID		TD	00:00.0
2021 PO5120987665	KU	4	45 ACE	SP	CRE	ID		TD	00:00.0
2021 PO5121587707	KU	4	45 ACE	SP	CRE	ID		TD	00:00.0
2021 PO7880576242	KU	5	35 ACE	SP	CCA			V	00:00.0
2021 PO7886676260	KU	4	40 ACE	SP	CCA			V	00:00.0
2021 PO4813410599	KU	2	55 XXX	ST	CRE			V	00:00.0
2021 PO4803510593	F	4	40 XXX	SP	CRE	ED,ID,MD		BX PX	00:00.0
2021 PO4813610534	F	4	40 XXX	SP	CRE	ED,ID,MD		BX PX	00:00.0
2021 PO4825110533	KU	5	45 XXX	SP	S			V	00:00.0
2021 PO4825910553	KU	4	40 XXX	SP	S			V	00:00.0
2021 PO4832210674	KU	5	35 XXX	SP	CRE	ED,ID		BD	00:00.0
2021 PO4836410469	KU	2	60 XXX	ST	S			V	00:00.0
2021 PO4849285757	LGE	2	60E ACE	SP	CRE	ED,ID		X PX	00:00.0
2021 PO4467188625	LGE	4	40 ACE	SP	CRE	ED		BD	00:00.0
2021 PO4467888613	LGE	4	40 ACE	SP	A	ED,ID		BD	00:00.0
2021 PO2272275323	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS		TD	00:00.0
2021 PO2259275127	KU	6	30 BRO	SP	CRE	ED,IP,SRS		TD	00:00.0
2021 PO4848185780	LGE	2	65 ACE	SP	CRE	ED,IP		BD	00:00.0

2021	PO4470888627	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4847085802	LGE	2	50 ACE	SP	CRE	ED,ID	X	PX	00:00.0
2021	PO4845985824	LGE	2	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4553387969	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4554087959	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4475588622	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4554887946	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4554487954	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4945684961	LGE	4	25 BRO	SP	CCA		V		00:00.0
2021	PO4831185919	LGE	6	30 ACE	SP	CRE	ED,ID	BX	RR	00:00.0
2021	PO4969584865	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4482888735	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4483888732	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4485288729	LGE	4	35 ACE	SP	CCA	ED	V		00:00.0
2021	PO4895384762	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4551088007	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4550888010	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4550488017	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO2593392750	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4549888027	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4549288037	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4548788045	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4548388052	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021	PO4548088056	LGE	3	45 BRO	SP	CRE		V		00:00.0
2021	PO4547588065	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4554488088	LGE	1	55 BRO	SP	CRE		V		00:00.0
2021	PO4832585936	LGE	4	35 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4482288666	LGE	4	35 ACE	SP	CRE	ED	BD		00:00.0
2021	PO4483388672	LGE	4	35 ACE	SP	CRE	ED	BD		00:00.0
2021	PO7668278110	KU	2	70 ACE	SP	CRE		V		00:00.0
2021	PO7643377782	KU	1	75 ACE	SP	CRE		V		00:00.0
2021	PO7644477544	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7645577382	KU	1	75 ACE	SP	CRE		V		00:00.0
2021	PO7645777285	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7647676948	KU	1	75 ACE	SP	CRE		V		00:00.0
2021	PO4484188679	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4485388688	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021	PO4831485922	LGE	4	40 ACE	SP	P	ED,IP	TD		00:00.0
2021	PO4830785913	LGE	4	30 ACE	SP	CRE	ED,IP	BD		00:00.0
2021	PO4474688855	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4832285911	LGE	6	25 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4834185905	F	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4486688698	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO1963099574	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO1957199531	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4896184752	LGE	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021	PO4955009777	KU	2	65 XXX	OT	CRE		V		00:00.0
2021	PO4856585161	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	TX	RR	00:00.0
2021	PO4857785161	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4481588799	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO1880900393	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4988509582	KU	2	70 XXX	SP	CCA		V		00:00.0
2021	PO4969409628	F	4	40 XXX	OT	CRE		V		00:00.0
2021	PO4972409675	KU	4	40 XXX	SP	S		V		00:00.0

2021 PO4474288848	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4473888841	LGE	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4473488834	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4472088809	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4472588818	LGE	4	40 ACE	AL	CCA		V	00:00.0
2021 PO4855485188	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4989409513	F	2	70 XXX	ST	CRE		V	00:00.0
2021 PO4469788824	LGE	3	40 ACE	SP	CCA		V	00:00.0
2021 PO4856485189	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7860881662a	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7860881662	KU	1	80 ACE	ST	CCA		V	00:00.0
2021 PO4844885845	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4844285856	F	5	30 ACE	SP	CCA		V	00:00.0
2021 PO4843585873	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO2103474044	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4552688001	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4552387986	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4551787995	LGE	3	45 BRO	SP	P	ED,EP,ID,IP,RB	TX	RR 00:00.0
2021 PO4550087985	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4551087991	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4477288596	LGE	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4477888588	LGE	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4410031999	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4366832354	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4262333317	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO4288633232	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4271933499	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4221433674	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4327232716	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4436428542	KU	5	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4432828127	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4431427835	KU	4	40 XXX	SP	CCA	ED	T	00:00.0
2021 PO4428427335	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4426626954	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO4478988571	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4969784895	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4478388580	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4480888541	LGE	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4480388548	LGE	4	35 ACE	SP	CRE	ED	V	00:00.0
2021 PO4840085895	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4839885906	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4837685905	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4836285897	LGE	6	25 ACE	SP	CRE	ED,IP	TD	00:00.0
2021 PO4836285905	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4835185898	LGE	5	25 ACE	SP	CCA		V	00:00.0
2021 PO2178174549	KU	6	30 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO4880810209	KU	2	70 XXX	ST	CRE		V	00:00.0
2021 PO4862210255	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4863910310	KU	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4870310306	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4883910127	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4885709962	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4891910083A	KU	5	30 XXX	SP	P	ED,ID,IP,MD,RB	TD	00:00.0
2021 PO4835285906	LGE	4	40 ACE	SP	CCA		V	00:00.0

2021 PO4798210686	KU	2	60 XXX	ST	CRE		V	00:00.0
2021 PO4470688606	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4463488642	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4458688633	LGE	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4458488614	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7756780425	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7826579980	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7826280211	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7834980379	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7834280507	KU	4	35 ACE	SP	CCA		V	00:00.0
2021 PO7653079759	KU	1	80 ACE	ST	CCA		V	00:00.0
2021 PO7644279338	KU	1	80 ACE	ST	CCA		V	00:00.0
2021 PO7639578920	KU	1	80 ACE	ST	CCA		V	00:00.0
2021 PO7637178431	KU	1	80 ACE	ST	CCA		V	00:00.0
2021 PO7648079515	KU	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7639179148	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7637578696	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7637778254	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7641578201	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4850285786	LGE	4	30 ACE	SP	P	ED	TD	00:00.0
2021 PO4848485810	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4461588578	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4461588602	LGE	4	25 ACE	SP	CRE		V	00:00.0
2021 PO4461988605	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4462288598	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4848085823	LGE	6	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4847285822	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4779009205	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4809510069	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4828209963	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4834210054	F	3	45 XXX	SP	S		V	00:00.0
2021 PO4693109823	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4708609591	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4689609668	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4724509581	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO4734409550	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO4835110190	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4843710200	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4849910297	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4851510320	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4848810397	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO4857610345	KU	2	65 XXX	ST	CCA		V	00:00.0
2021 PO4850085752	LGE	1	75 ACE	SP	CCA		V	00:00.0
2021 PO4478288683	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4477488670	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4942084993	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4476788656	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4944584966	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4944784980	LGE	2	60 BRO	SP	CCA		V	00:00.0
2021 PO4475888642	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4553588007	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4845585835	LGE	2	50 ACE	SP	CRE	ED,ID	X PX	00:00.0
2021 PO4845485837	LGE	6	25 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4944085028	LGE	4	40 BRO	SP	CRE	ED,HH,ID,IP	TX RR	00:00.0

2021 PO4475188629	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4949585020	LGE	2	60 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO2182174646	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO2205174825	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2186774612	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6626263173	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5103884774	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5104284790	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5104984817	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO5104384824	LGE	2	50 ACE	SP	CRE	ED	BD	00:00.0
2021 PO5100984822	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO5098884826	LGE	4	30 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4386822055	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4385621844	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4384121622	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4383021442	KU	4	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4382421315	KU	4	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5098284821	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5096484817	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7740280520	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO7728680396	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7722980472	KU	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7690680186	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7708280046	KU	3	40 ACE	SP	CCA		V	00:00.0
2021 PO7685480004	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7818180152	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7822180124	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX 00:00.0
2021 PO7731979992	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7677180038	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7666579911	KU	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7700979944	KU	4	40 ACE	DF	CRE	ED,ID,IP	BD	00:00.0
2021 PO7805079834	KU	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5094384815	LGE	4	40 ACE	SP	CRE	ED	TD	00:00.0
2021 PO4347921190	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4616911865	KU	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4634811707	KU	1	70 KOP	ST	CCA		V	00:00.0
2021 PO4606611894	KU	1	85 KOP	SP	P		V	00:00.0
2021 PO4602012087	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO4852886141	LGE	3	50 ACE	SP	P	ED,IP	BD	00:00.0
2021 PO4853186129	LGE	3	50 ACE	SP	P	ED	BD	00:00.0
2021 PO4389421154	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4381221118	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4380420991	KU	4	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4379320806	KU	4	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4641311815A	KU	5	35 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO4620611730	F	4	30 KOP	SP	CRE		V	00:00.0
2021 PO4648911929	KU	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4615211765	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4621411847	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO4628211962	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO4645111872	KU	6	30 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO4624911901	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO4641311815	KU	5	35 KOP	SP	S		V	00:00.0
2021 PO4621411794	KU	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0

2021 PO4854386109	LGE	3	50 ACE	SP	P	ED	BD	00:00.0
2021 PO4852486099	LGE	4	45 ACE	SP	CCA		V	00:00.0
2021 PO5088184839	LGE	3	45 ACE	SP	A	ED	TD	00:00.0
2021 PO6498963281	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4935785020	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5086284846	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO5086384848	LGE	3	30 ACE	SP	P	ED	BD	00:00.0
2021 PO4936185025	F	4	40 BRO	SP	A		V	00:00.0
2021 PO5084184861	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5081584860	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021 PO4853785533	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4854485537	LGE	6	35 ACE	SP	CRE	ED,IP	TD	00:00.0
2021 PO4377620589	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6487963159	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4856585526	LGE	4	45 ACE	SP	P	ED	BD	00:00.0
2021 PO6480962906	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO6553463332	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO4854385524	LGE	4	45 ACE	SP	P	ED,IP	TD	00:00.0
2021 PO4854085524	LGE	4	45 ACE	SP	P	ED,IP	TD	00:00.0
2021 PO4853285520	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4375320128	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4376120274	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4375219954	KU	4	35 XXX	SP	CRE	HH,ID,IP	X PX	00:00.0
2021 PO4376719686	KU	4	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4415386148	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4416186154	LGE	3	45 BRO	SP	A		V	00:00.0
2021 PO1825369269	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4417486163	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7906707870	KU	2	45 BRN	SP	CCA		V	00:00.0
2021 PO1261573755	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4412786129	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4412886126	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6044702567	F	2	55 ACE	SP	CRE		V	00:00.0
2021 PO4242114020	KU	H2	70 XXX	ST	CRE		V	00:00.0
2021 PO4408586099	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4408286096	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO1193573128	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4405286075	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4404586070	F	4	40 BRO	SP	A		V	00:00.0
2021 PO1185473066	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4458485618	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4413286119	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4413586111	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4406486084	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4407386090	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4407786093	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO1721469767	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0
2021 PO4456785740	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4450185787	LGE	3	45 ACE	SP	CCA	ED	V	00:00.0
2021 PO4454785694	F	6	35 ACE	SP	CRE	ED	V	00:00.0
2021 PO4453785673	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4455385684	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4429385968	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4428486004	F	4	40 BRO	SP	CRE		V	00:00.0



2021 PO4427986005	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4427885981	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4428385993	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4451685798	LGE	2	65 ACE	SP	CRE	ED	V	00:00.0
2021 PO4639812153	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO9641894957	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO9617194922	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO9590894873	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO9584694863	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO9540094400	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO9562794948	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO9600095027	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO9579994970	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO5955798152	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5942798162	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO5938298167	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5923898173	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5913598180	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5900998192	F	4	50 ACE	SP	CRE		V	00:00.0
2021 PO5954097383	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5937097483	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5930397539	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5986102848	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5921997835	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5966597242	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4477485595	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO5931500527	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6250200947	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6393602960	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO6404102854	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO6412402770	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6371903177	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6240101004	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6219301118	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6202701210	F	4	50 ACE	SP	CRE		V	00:00.0
2021 PO6229401060	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6209801171	F	4	50 ACE	SP	CRE		V	00:00.0
2021 PO6186301307	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6197201349	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO6329001606	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6322301710	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6310001783	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5981502305	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO5993602231	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6008102755	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6026202656	KU	2	50 ACE	SP	P		V	00:00.0
2021 PO5997802518	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6011902326	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5939502558	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5843297534	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5839897375	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5846897323	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5857197245	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5887697015	F	4	40 ACE	SP	CRE		V	00:00.0

2021	PO5866097180	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4459385692	LGE	4	40 ACE	SP	P	V	00:00.0
2021	PO4460885700	LGE	4	40 ACE	SP	P	V	00:00.0
2021	PO6004902162	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5999002024	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5971402024	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5983301952	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5993201891	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5958602106	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4464685728	LGE	4	40 ACE	SP	P	V	00:00.0
2021	PO4463385654	LGE	3	50 ACE	SP	A	V	00:00.0
2021	PO5908196859	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5877297092	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5875797364	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5867197392	F	4	45 ACE	SP	CRE	V	00:00.0
2021	PO5897596937	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5917596789	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6061402477	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6063402490	F	2	50 ACE	SP	CRE	V	00:00.0
2021	PO4466485669	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4465285667	LGE	3	50 ACE	SP	CRE	V	00:00.0
2021	PO4462285646	LGE	3	50 ACE	SP	P	V	00:00.0
2021	PO9543294897	KU	2	60 XXX	SP	S	V	00:00.0
2021	PO9525994721	KU	2	60 XXX	SP	S	V	00:00.0
2021	PO9558796039	KU	4	40 XXX	SP	S	V	00:00.0
2021	PO9532695864	KU	2	50 XXX	SP	CRE	V	00:00.0
2021	PO9548495793	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO9539595840	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO1890868354	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO4473985579	F	UNK	45 ACE	SP	A	V	00:00.0
2021	PO3563519917	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO4468585539	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4465385517	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4464985515	F	4	40 ACE	SP	CRE	V	00:00.0
2021	4464985515-a	F	3	40 ACE	SP	CCA	V	00:00.0
2021	PO9577792730	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4479785563	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO1939468149	F	4	30 ACE	SP	CCA	V	00:00.0
2021	PO9635094946	KU	3	45 XXX	SP	CRE	V	00:00.0
2021	PO4427885968	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO3970915216	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO4056114884	KU	2	65 XXX	ST	CRE	V	00:00.0
2021	PO4033014979	KU	2	65 XXX	ST	CRE	V	00:00.0
2021	PO4003015073	KU	2	60 XXX	SP	CRE	V	00:00.0
2021	PO3978815141	KU	2	65 XXX	SP	CRE	V	00:00.0
2021	PO3948415144	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO3620119545	KU	2	50 BRN	SP	CCA	V	00:00.0
2021	PO1944667873	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021	PO3959615199	KU	2	60 XXX	SP	CRE	V	00:00.0
2021	PO3971815459	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO3982715426	KU	4	45 XXX	SP	CCA	V	00:00.0
2021	PO3580119803	KU	6	30 BRN	SP	CCA	V	00:00.0
2021	PO3576119748	KU	5	35 BRN	SP	CCA	V	00:00.0
2021	PO3569119656	KU	5	35 BRN	SP	CCA	V	00:00.0

2021 PO3562319572	KU	5	35 BRN	SP	CCA	V	00:00.0
2021 PO4459085460	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO4433686051	LGE	4	30 BRO	SP	CCA	V	00:00.0
2021 PO9499291847	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO9481691124	KU	6	30 UNK	SP	CCA	V	00:00.0
2021 PO9501091367	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO9499191607	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO9485291842	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO9462991040	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO9475490881	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO9481691045	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO1409873373	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO1643466622	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4450585422	LGE	UNK	65 ACE	SP	CRE	V	00:00.0
2021 PO4452485435	LGE	1	60 ACE	SP	A	V	00:00.0
2021 PO4454285447	LGE	UNK	60 ACE	SP	CRE	V	00:00.0
2021 PO3769315744	KU	ST	65 XXX	ST	CCA	V	00:00.0
2021 PO3534819299	KU	6	30 BRN	SP	CCA	V	00:00.0
2021 PO6306301805	KU	6	30 ACE	SP	P	V	00:00.0
2021 PO6297401856	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO9589594574	KU	5	35 XXX	SP	S	V	00:00.0
2021 PO4428786017	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4428886030	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4538887700	LGE	3	50 ACE	SP	CRE	V	00:00.0
2021 PO9641394706	KU	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4482985515	LGE	3	45 ACE	SP	A	V	00:00.0
2021 PO4483785504	LGE	4	40 ACE	SP	P	V	00:00.0
2021 PO1943667669	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4478885610	LGE	4	35 ACE	DF	CCA	V	00:00.0
2021 PO4481585524	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4428986050	F	2	55 BRO	SP	A	V	00:00.0
2021 PO4430386050	F	2	55 BRO	SP	A	V	00:00.0
2021 PO3986915493	KU	4	45 XXX	SP	CCA	V	00:00.0
2021 PO8998089376	KU	4	45 XXX	SP	S	V	00:00.0
2021 PO9149889335	KU	4	40 XXX	SP	S	V	00:00.0
2021 Pp	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4222914040	F	4	40 XXX	SP	P	V	00:00.0
2021 PO4220714122	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO4478285883	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO3678817937	KU	1	85 BRN	SP	CRE	V	00:00.0
2021 PO3673617696	KU	2	70 BRN	SP	CRE	V	00:00.0
2021 PO3669117469	KU	2	65 BRN	SP	CRE	V	00:00.0
2021 PO3664517277	KU	2	60 BRN	SP	CRE	V	00:00.0
2021 PO8997091476	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO4228814095	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 PO4532587565	F	4	25 ACE	SP	CRE	V	00:00.0
2021 PO4532287588	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO7951310349	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO7905110636	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO7902510684	KU	5	35 BRN	SP	CCA	V	00:00.0
2021 PO7908510767	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO3655016804	KU	2	70 BRN	SP	CRE	V	00:00.0
2021 PO3659817043	KU	H2	65 BRN	AL	CRE	V	00:00.0
2021 PO4537187539	LGE	4	25 ACE	SP	CRE	V	00:00.0

2021	PO4535087543	F	4	25 ACE	SP	CRE		V	00:00.0
2021	PO3651116634	KU	2	70 BRN	SP	CRE		V	00:00.0
2021	PO3646316395	KU	2	70 BRN	SP	CRE		V	00:00.0
2021	PO4158214368	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4163614415	KU	H2	70 XXX	SP	P		V	00:00.0
2021	PO4136214543	KU	H2	75 XXX	SP	P		V	00:00.0
2021	PO4110614654	KU	H2	65 XXX	SP	CRE		V	00:00.0
2021	PO4530787639	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO4530287648	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4531287671	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4532187677	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4533387668	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4533887659	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4430485765	LGE	1	50 BRO	SP	CRE		V	00:00.0
2021	PO4194114182	F	3	50 XXX	SP	CCA		V	00:00.0
2021	PO4185014227	F	2	50 XXX	SP	CCA		V	00:00.0
2021	PO4180514250	F	2	50 XXX	SP	CCA		V	00:00.0
2021	PO4156314215	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO3643016220	KU	2	70 BRN	SP	CRE		V	00:00.0
2021	PO3634016200	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3638616025	KU	2	70 BRN	SP	CRE		V	00:00.0
2021	PO3670715957	KU	2	50 BRN	SP	CCA		V	00:00.0
2021		4467186106	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO4460285861	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4460285862	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4458885875	LGE	UNK	20 ACE	SP	CCA		V	00:00.0
2021	PO4457885800	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4456885823	LGE	1	80 ACE	SP	CRE		V	00:00.0
2021	PO4455785829	LGE	1	90 ACE	SP	CRE	ED	V	00:00.0
2021	PO4425685913	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4426385933	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4427185918	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4428485926	LGE	4	40 BRO	SP	A		V	00:00.0
2021	PO4423785835	LGE	4	30 BRO	SP	A		V	00:00.0
2021	PO4425085832	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021	PO1397870737	F	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4426885849	LGE	4	35 BRO	SP	A		V	00:00.0
2021	PO4428085849	LGE	4	35 BRO	SP	A		V	00:00.0
2021	PO4526287714	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4526587709	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4523087701	F	3	50 BRO	SP	CCA		V	00:00.0
2021	PO4523687692	F	3	50 BRO	SP	CRE		V	00:00.0
2021	PO4527187699	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4524287682	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO3613316078	KU	2	60 BRN	SP	CRE		V	00:00.0
2021	PO4206114123	F	3	40 XXX	SP	CCA		V	00:00.0
2021	PO8984189249	KU	4	45 XXX	SP	S		V	00:00.0
2021	PO9055089216	KU	4	45 XXX	SP	S		V	00:00.0
2021	PO9095089082	KU	4	45 XXX	SP	S		V	00:00.0
2021	PO4421985838	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4425885843	LGE	3	45 BRO	SP	A		V	00:00.0
2021	PO9707388801	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO9670688961	KU	4	40 KOP	SP	CCA		V	00:00.0
2021	PO9634489131	KU	3	45 BRO	SP	CCA		V	00:00.0

2021 PO4532387684	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4531287702	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4530887709	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4531787693	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4427485842	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9593489331	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4534987719	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7055646744	KU	6	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7064146738	KU	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7050246886	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7068146856	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7089846829	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7080646779	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO7081346836	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7082047039	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO7081646913	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO7062542014	KU	4	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5654593769	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5679893647	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO5666993707	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO4332787007	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4333087006	F	UNK	25 BRN	SP	CCA		V	00:00.0
2021 PO3824904928	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3808804668	F	4	40 BRN	SP	S		V	00:00.0
2021 PO3818804990	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO3813004893	F	2	45 BRN	SP	CRE	HH,ID,IP,RB	BX PX	00:00.0
2021 PO4806690258	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4807590229	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4808390203	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO7136949551	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7134649401	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7132749262	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4809990150	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO5168414588	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4809090176	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4806190262	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7141449246	KU	4	45 KOP	SP	CCA		V	00:00.0
2021 PO7143249134	F	5	35 UNK	SP	CRE		V	00:00.0
2021 PO7152349505	KU	6	30 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5005519344	LGE	1	45 BRN	SP	CCA		V	00:00.0
2021 PO5948901809	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6779949248	KU	4	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6627548315	KU	1	60 BRN	ST	CRE		V	00:00.0
2021 PO6777549115	KU	4	50 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6965347382	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO7524447033	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO6778849199	KU	4	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6971047377	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6471049222	KU	5	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO6945747311	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6461649290	KU	5	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4212688060	LGE	1	65 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6953247301	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7353547777	F	4	40 UNK	SP	CRE		V	00:00.0

2021	PO4450886186	F	1	70 BRN	SP	P		V		00:00.0
2021	PO4334587031	LGE	4	35 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO3854601215	KU	3	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO4891491093	LGE	3	50 BRN	SP	A		V		00:00.0
2021	PO4441286085	LGE	3	45 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO4442386094-a	LGE	3	30 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO4443986107	LGE	UNK	55 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO4442386094	LGE	3	50 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO5831198752	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5824998598	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5458894329	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5450194067	F	5	35 BRN	SP	CRE		V		00:00.0
2021	PO4442386094-a	LGE	3	30 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO7530947100	KU	4	40 CPT	SP	CRE	ED,ID	TD		00:00.0
2021	PO7528146971	KU	4	40 UNK	SP	P	ID	BD		00:00.0
2021	PO3790797057	KU	5	35 BRN	SP	CRE		V		00:00.0
2021	PO3755896891	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO7069947574	KU	2	40 XXX	SP	CCA		V		00:00.0
2021	PO7069647410	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO7069247297	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4059384256	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4058984254	LGE	4	40 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO7773345464	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO7763945842	KU	4	40 UNK	SP	CRE	ED,ID,RB	X	RP2	00:00.0
2021	PO7804946160	KU	4	45 KOP	SP	CCA		V		00:00.0
2021	PO7648044634	F	4	40 KOP	SP	P		V		00:00.0
2021	PO7659744820	F	4	40 KOP	SP	CRE		V		00:00.0
2021	PO4196788228	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021	PO4198988225	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021	PO6542548472	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4077584419	LGE	3	45 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO3839700665	F	2	50 BRN	SP	CRE		V		00:00.0
2021	PO4449286090	LGE	4	35 BRN	SP	A	ED,ID	TD		00:00.0
2021	PO1619673246	LGE	3	45 BRN	SP	CCA	ED,ID	BD		00:00.0
2021	PO4210988203	LGE	1	55 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4449086074	LGE	4	30 BRN	ST	CCA		V		00:00.0
2021	PO4447286070	LGE	4	40 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO6600548306	KU	2	50 BRN	SP	CRE		V		00:00.0
2021	PO6596348278	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6603448195	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6601648167	KU	3	50 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4210388203	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO7022647421	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO7023047556	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO6900447510	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4008286544	LGE	H4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4008886543	LGE	H4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4008486544	LGE	H4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4008686543	LGE	H4	45 ACE	SP	CCA		V		00:00.0
2021	PO7071649193	F	5	40 UNK	SP	CRE		V		00:00.0
2021	PO7062349203	F	5	40 UNK	SP	CRE		V		00:00.0
2021	PO7058349209	F	5	40 UNK	SP	CRE		V		00:00.0
2021	PO7051149164	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO7044749248	F	5	40 UNK	SP	CRE		V		00:00.0

2021 PO7043349176	KU	6	35 UNK	SP	CRE	ID	BD	00:00:00
2021 PO7034649265	F	5	40 UNK	SP	CRE		V	00:00:00
2021 PO7033049194	KU	5	35 BRO	SP	CCA		V	00:00:00
2021 PO7016149379	F	5	30 UNK	SP	P		V	00:00:00
2021 PO2847990360	F	3	45 BRO	SP	P		V	00:00:00
2021 PO6908347512	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00:00
2021 PO4463586001	F	2	55 BRN	SP	CRE		V	00:00:00
2021 PO4464086040	F	2	55 BRN	SP	CCA		V	00:00:00
2021 PO4464286060	F	1	50 BRN	SP	CCA		V	00:00:00
2021 PO4464586081	F	2	55 BRN	SP	P	ED,HH,ID,IP,RB	VX	PX
2021 PO4465185789	F	4	35 BRN	SP	CCA		V	00:00:00
2021 PO1728269968	LGE	4	35 BRN	SP	CCA		V	00:00:00
2021 PO1723369941	LGE	3	45 BRN	SP	CCA		V	00:00:00
2021 PO1710969664	LGE	4	35 BRN	SP	CCA		V	00:00:00
2021 PO7082747248	KU	6	30 XXX	SP	CRE	ID	TD	00:00:00
2021 PO7084647406	KU	6	30 XXX	SP	CRE	ID	TD	00:00:00
2021 PO7083747635	KU	4	40 XXX	SP	CRE	ID	BD	00:00:00
2021 PO7084247761	KU	4	35 XXX	SP	CRE	ID	TD	00:00:00
2021 PO7084347832	KU	4	35 XXX	SP	CRE	ID	TD	00:00:00
2021 PO7731146049	F	4	40 KOP	SP	P		V	00:00:00
2021 PO7709645693	F	4	40 KOP	SP	P		V	00:00:00
2021 PO7748145944	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00:00
2021 PO7755746235	KU	6	30 ACW	SP	CRE	ED,ID	TD	00:00:00
2021 PO7746146295	F	4	40 KOP	SP	CRE		V	00:00:00
2021 PO4074884387	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00:00
2021 PO7905255617	LGE	4	35 BRN	SP	CCA		V	00:00:00
2021 PO7119847386AA	KU	4	45 BRO	SP	S		V	00:00:00
2021 PO3814303627	F	4	40 BRN	SP	CRE	EP,HH,ID,IP,RB	BX	RP2
2021 PO3804203723	F	4	40 BRN	SP	CCA		V	00:00:00
2021 PO3816903488	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX
2021 PO3790903797	KU	4	40 BRN	SP	CCA		V	00:00:00
2021 PO3822503548	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1
2021 PO5699193207	F	2	45 BRN	SP	CRE		V	00:00:00
2021 PO3793003801	F	4	40 BRN	SP	CRE	EP,HH,ID,IP,RB	BX	RP1
2021 PO6513148350a	KU	4	40 BRN	SP	CCA		V	00:00:00
2021 PO6513148350	KU	4	45 BRN	SP	CCA		V	00:00:00
2021 PO5607693182	F	2	50 BRN	SP	CRE		V	00:00:00
2021 PO5639393385	F	2	45 BRN	SP	CRE		V	00:00:00
2021 PO4450285756	LGE	1	60 BRN	SP	CRE	ED,ID	VX	RP1
2021 PO7119847386A	KU	4	45 BRO	SP	CRE	ED,ID,IP	BD	00:00:00
2021 PO7119847386	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00:00
2021 PO7113247387	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00:00
2021 PO7110147389	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00:00
2021 PO7104947483	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00:00
2021 PO7242248995	F	4	40 BRO	SP	CRE		V	00:00:00
2021 PO5742793135	F	3	40 BRN	SP	CRE		V	00:00:00
2021 PO5736793256A	F	3	40 BRN	SP	CRE		V	00:00:00
2021 PO5711893080	F	2	40 BRN	SP	CRE		V	00:00:00
2021 PO3799202353	KU	3	45 BRN	SP	CCA		V	00:00:00
2021 PO7228949022	F	4	40 BRO	SP	CRE		V	00:00:00
2021 PO7222648967	F	4	40 BRO	SP	CRE		V	00:00:00
2021 PO3860302086	F	4	40 BRN	SP	CRE		V	00:00:00
2021 PO3861202216	F	4	40 BRN	SP	CRE		V	00:00:00
2021 PO3859501956	F	4	40 BRN	SP	CRE		V	00:00:00

2021 PO3862202336	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3858401805	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO5715693032	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5730993365	F	2	50 BRN	SP	CRE		V	00:00.0
2021 PO5730793399	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO5733193403	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5757093897	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7091647512	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4796890550	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO3864704700	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO3859804823	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3875104431	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3877404912	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO3875804602	F	2	40 BRN	SP	CRE	HH,ID,IP	BX RP3	00:00.0
2021 PO3876804767	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO0020881029	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0002080693	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9990880792	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0018181570	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4797490532	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4798090512	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4798590497	LGE	3	45 BRN	SP	A	ID,IP	BD	00:00.0
2021 PO4999088698	LGE	2H	55 BRN	SP	A	ID,IP	BD	00:00.0
2021 PO4798690493	LGE	3	45 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021 PO3819402461	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3834402717	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3834902796	F	4	40 BRN	SP	CRE	HH,ID,IP,SRC	BX PX	00:00.0
2021 PO3838002712	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO3834202431	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7585346999	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7573446992	F	4	40 UNK	SP	P		V	00:00.0
2021 PO4995288676	LGE	2H	55 BRN	SP	A	ID,IP	BD	00:00.0
2021 PO7111147624	KU	2	70 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6454848265	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4993388666	LGE	2H	55 BRN	SP	A	ID,IP	BD	00:00.0
2021 PO7022399987	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4106284000	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4108384013	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5876394872	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5860194841	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5843494810	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7186349158	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7193649085	F	5	40 SWP	SP	P		V	00:00.0
2021 PO3802796419	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO3792896446	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO3787296319	KU	2	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5827994782	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5811894752	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7212248985	F	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7200749129	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7206549301	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7203049326	KU	5	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4783990718	LGE	3	45 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO3970197504	KU	3	50 BRN	SP	CCA		V	00:00.0



2021 PO3973397611	KU	3	50 BRN	SP	CRE		V		00:00.0
2021 PO3976997722	F	3	50 BRN	SP	CRE		V		00:00.0
2021 PO3980697511	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO9956781230	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO9962381381	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5975922693	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4793090968	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4988422345	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5656095526	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5643395598	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO9949982019	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5868802412	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO6476548102c	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO5885202090	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6476548102b	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO6476548102a	KU	5	40 BRN	SP	CRE	RB	X	PX	00:00.0
2021 PO6476548102	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6474447940	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4751691070	LGE	4	40 BRN	SP	A		V		00:00.0
2021 PO4753591050	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4755591030	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PV4487385795	LGE	1	60 BRN	SP	CRE		V		00:00.0
2021 PO4485585797	LGE	1	60 BRN	SP	A		V		00:00.0
2021 PO4484785798	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4483385800	LGE	4	40 BRN	SP	A		V		00:00.0
2021 PO1964270478	LGE	3	45 BRN	SP	CRE		V		00:00.0
2021 PO4481985802	LGE	1	60 BRN	SP	A		V		00:00.0
2021 PO5863002447	KU	3	40 XXX	SP	P		V		00:00.0
2021 PO5855402490	F	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	BX	PX	00:00.0
2021 PO5851302515	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5841602572	F	4	40 XXX	SP	CRE	ED,ID,IP,MD,RB	BX	PX	00:00.0
2021 PO5837602614	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5830401627	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5832301506	F	4	45 XXX	SP	CRE		V		00:00.0
2021 PO5833601430	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5828101746	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5836901220	F	6	35 XXX	SP	CRE		V		00:00.0
2021 PO0138489822	KU	5	35 UNK	SP	CRE	HH,ID	TD		00:00.0
2021 PO0034391555	KU	4	40 UNK	SP	CRE	ED,ID,MD	TX	RR	00:00.0
2021 PO4537111525	KU	4	40 XXX	SP	CRE	HH,ID	TX	RR	00:00.0
2021 PO5272410392	KU	5	35 XXX	SP	CCA		V		00:00.0
2021 PO4597411655	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4582511741	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4617611585	F	5	35 XXX	SP	CRE		V		00:00.0
2021 PO6326303549	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6360903660	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6348003791	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6354403862	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6302203456	F	4	40 ACE	SP	P		V		00:00.0
2021 PO6294003502	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6292103602	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4426185407	F	2	50 BRO	SP	A		V		00:00.0
2021 PO4256185409	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021 PO4463985772	LGE	3	45 ACE	SP	CCA		V		00:00.0

2021 PO4463085784	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4462185803	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4426085393	F	3	50 BRO	SP	A	V	00:00.0
2021 PO4426085367	F	3	50 BRO	SP	A	V	00:00.0
2021 PO4425985370	F	3	50 BRO	SP	A	V	00:00.0
2021 PO6258403643	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6259903551	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4425385368	F	3	45 BRO	SP	A	V	00:00.0
2021 PO6335603098	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5774704578	KU	4	45 XXX	SP	CCA	V	00:00.0
2021 PO5766904818	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 PO5764504655	KU	4	45 XXX	SP	CCA	V	00:00.0
2021 PO5774004788	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 PO5754804735	KU	4	45 XXX	SP	CCA	V	00:00.0
2021 PO5728506431	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5734706775	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5730606535	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5732806655	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5737507018	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5736206896	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO9986990912	KU	5	35 UNK	SP	CRE	V	00:00.0
2021 PO0096290414	F	5	35 MAR	SP	P	V	00:00.0
2021 PO0014390676	F	3	45 UNK	SP	CRE	V	00:00.0
2021 PO0003390683	F	4	40 UNK	SP	P	V	00:00.0
2021 PO0004490767	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO0008790853	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO0014990964	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO0062590522	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO9990191003	KU	3	35 BRO	SP	CCA	V	00:00.0
2021 PO9985991031	KU	3	45 UNK	SP	CRE	V	00:00.0
2021 PO1682768853	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO0017989270	F	4	40 BRO	SP	P	V	00:00.0
2021 PO0015289725	F	3	40 CPT	SP	P	V	00:00.0
2021 PO5828797187	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5816097045	F	4	40 ACE	SP	P	V	00:00.0
2021 PO5834596850	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5841896943	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5849097042	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5868796901	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4400285254	LGE	4	35 BRO	SP	A	V	00:00.0
2021 PO4400885278	LGE	4	30 BRO	SP	A	V	00:00.0
2021 PO0035391422	F	4	40 MAR	SP	P	V	00:00.0
2021 PO9190195889	KU	3	50 XXX	SP	S	V	00:00.0
2021 PO4427885284	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4426285285	F	4	30 BRO	SP	A	V	00:00.0
2021 PO5856100332	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5889400157	F	5	40 ACE	SP	CRE	V	00:00.0
2021 PO5881600197	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5870600254	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4408185293	F	4	30 BRO	SP	A	V	00:00.0
2021 PO4406985290	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4405585291	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4409586170	LGE	4	40 BRO	SP	P	V	00:00.0
2021 PO4410186161	LGE	4	35 BRO	SP	CRE	V	00:00.0

2021 PO4411286143	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4410686153	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4532811748	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9998791408	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6022099285	KU	1	80 ACE	ST	CRE		V	00:00.0
2021 PO6051499107	KU	1	80 ACE	ST	CRE		V	00:00.0
2021 PO4458285477	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4420485342	F	UNK	30 BRO	SP	CRE		V	00:00.0
2021 PO4415685356	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4427885266	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4427885274	F	4	35 BRO	SP	A		V	00:00.0
2021 PO8396396291	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO4407386209	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4407386209	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4408586191	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4409386179	F	4	40 BRO	SP	A		V	00:00.0
2021 PO0021492005	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6363903262	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4451485603	LGE	UNK	45 ACE	SP	P		V	00:00.0
2021 PO6266502472	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6250102651	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4403809488	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO4424309489	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4351710292	F	3	45 XXX	SP	P		V	00:00.0
2021 PO4354610347	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4345510219	F	2	50 XXX	SP	CRE		V	00:00.0
2021 PO4368909888	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4411510307	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4471711233	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4562711877	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4580711314	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5211311873	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4894209098	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4412385291	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4411285292	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO0030092261	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO0030992116	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6129900787	F	2	50 ACE	SP	CRE		V	00:00.0
2021 PO5863409077	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4468485627	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO8388396801	F	3	40 XXX	SP	CRE		V	00:00.0
2021 PO5875497892	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO9959088030	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5804197173	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO0010488571	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO0021788565	F	5	40 BRO	SP	CRE		V	00:00.0
2021 PO9347295342	KU	4	50 XXX	SP	CRE		V	00:00.0
2021 PO9346595413	KU	4	45 XXX	SP	S		V	00:00.0
2021 PO9379395505	KU	3	45 XXX	SP	S		V	00:00.0
2021 0021988744A	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0021988744	F	3	40 CPT	SP	P		V	00:00.0
2021 PO0020888939	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO0019789093	F	4	40 CPT	SP	P		V	00:00.0
2021 PO0016589416	F	4	40 MAR	SP	P		V	00:00.0

2021 0214689665B	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 0214689665C	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 0214689665D	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 0214689665E	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 0214689665F	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 P00339588481	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 P00323388678	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 P00209990388	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 P00175790024	KU	6	30 UNK	SP	CRE	V	00:00.0
2021 P06327701776	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P06319401902	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P06310602037	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P06306702194	F	4	40 ACE	SP	P	V	00:00.0
2021 P06323102497	F	4	40 ACE	SP	P	V	00:00.0
2021 P06315202349	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P06318802418	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P06326302554	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P06330902640	F	4	40 ACE	SP	P	V	00:00.0
2021 9927591113A	KU	4	35 CPT	SP	P	V	00:00.0
2021 P09927591113	F	4	35 CPT	SP	P	V	00:00.0
2021 P09935691222	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 P04308214083A	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 P04453085652	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 P04303614628	KU	2	50 XXX	SP	CCA	V	00:00.0
2021 P09417895116	KU	3	45 XXX	SP	S	V	00:00.0
2021 P09424895077	KU	3	45 XXX	SP	S	V	00:00.0
2021 P09423795061	KU	3	45 XXX	SP	S	V	00:00.0
2021 P09416694951	KU	2	50 XXX	SP	S	V	00:00.0
2021 P09425494856	KU	2	50 XXX	SP	S	V	00:00.0
2021 P09414094738	KU	2	50 XXX	SP	S	V	00:00.0
2021 P09389094659	KU	3	45 XXX	SP	S	V	00:00.0
2021 P09400494555	KU	3	45 XXX	SP	S	V	00:00.0
2021 P09406294517	KU	3	45 XXX	SP	S	V	00:00.0
2021 P09979391404	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 0214689665A	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 P09952391228	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 P09953891243	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 P09963691179	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 P09379394615	KU	6	30 XXX	SP	S	V	00:00.0
2021 P09368494037	KU	3	45 XXX	SP	S	V	00:00.0
2021 P09942191181	KU	4	30 MAR	SP	P	V	00:00.0
2021 P09946891265	F	5	35 UNK	SP	CRE	V	00:00.0
2021 P06117300034	F	2	45 ACE	SP	CRE	V	00:00.0
2021 P04454685525	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 P04436685480	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 P04403685292	F	4	40 BRO	SP	CRE	V	00:00.0
2021 P04402285305	F	4	40 BRO	SP	A	V	00:00.0
2021 P04401485315	F	4	40 BRO	SP	A	V	00:00.0
2021 P04401885302	F	5	25 BRO	SP	A	V	00:00.0
2021 P06297702137	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P06291002301	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P04400585325	F	4	40 BRO	SP	CRE	V	00:00.0
2021 P09348395483	KU	3	45 XXX	SP	S	V	00:00.0
2021 P09374495816	KU	6	30 XXX	SP	S	V	00:00.0

2021 PO9251195954	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO4399386267	LGE	5	25 BRO	SP	CRE	V	00:00.0
2021 PO4406986216	LGE	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4424411684	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4433411659	F	4	40 XXX	SP	P	V	00:00.0
2021 PO4439411644	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4421111584	F	4	40 XXX	SP	P	V	00:00.0
2021 PO0214488379	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO9369195294	KU	5	30 XXX	SP	S	V	00:00.0
2021 PO9370095373	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO9352495763	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO9360195762	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO0177589902	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO0197789773	F	3	40 CPT	SP	CRE	V	00:00.0
2021 PO0214689665	F	3	40 MAR	SP	P	V	00:00.0
2021 PO4406186227	LGE	3	50 BRO	SP	CRE	V	00:00.0
2021 PO6307800934	KU	4	45 ACE	SP	CRE	V	00:00.0
2021 PO6289600723	KU	4	45 ACE	SP	CRE	V	00:00.0
2021 PO6316300729	F	4	40 ACE	SP	P	V	00:00.0
2021 PO0014491670	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO6155201340	F	2	50 ACE	SP	CCA	V	00:00.0
2021 PO6158201316	F	2	50 ACE	SP	CCA	V	00:00.0
2021 PO6167501865	F	4	45 ACE	SP	CRE	V	00:00.0
2021 PO6173801837	F	4	45 ACE	SP	CRE	V	00:00.0
2021 PO6180101799	F	3	45 ACE	SP	CRE	V	00:00.0
2021 PO6190601744	F	4	45 ACE	SP	CRE	V	00:00.0
2021 PO6191101729	F	3	45 ACE	SP	CRE	V	00:00.0
2021 PO4450611320	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4454711432	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4460611589	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4464911688	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4468411777	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4475211961	F	4	40 XXX	SP	P	V	00:00.0
2021 PO4446912087	F	4	40 XXX	SP	CCA	V	00:00.0
2021 PO4433112401	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4440312651	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4480712363	KU	2	50 XXX	SP	CCA	V	00:00.0
2021 PO4491912298	KU	3	50 XXX	SP	CCA	V	00:00.0
2021 PO4530312258	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 PO4538711892	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4401286290	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4491385651	LGE	4	40 ACE	SP	P	V	00:00.0
2021 PO2063668898	LGE	3	45 ACE	SP	P	V	00:00.0
2021 PO4489385679	LGE	4	40 ACE	SP	P	V	00:00.0
2021 PO4489585678	LGE	4	40 ACE	SP	P	V	00:00.0
2021 PV4488385748	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO2012570129	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO6288102453	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4440785396	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4441285411	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4491485712	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO6296702594	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6277702632	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6276702801	F	4	40 ACE	SP	CRE	V	00:00.0

2021	PO6292902807	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6312302814	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4404586246	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO6345001521	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO6336201654	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4403986262-A	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4435385444	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO1377168462	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4434885388	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4402786279	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO 4403986262-A	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO 4403986262-B	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4402986276	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4403986262	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4444985361	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4409985288	F	4	40 BRO	SP	A		V	00:00.0
2021	PO0287992023	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO0265691992	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO4443385435	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO6097396127	F	2	50 ACE	SP	CRE		V	00:00.0
2021	PO5835201330	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4766390962	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4479885804	LGE	1	60 BRN	SP	CRE		V	00:00.0
2021	PO5835201091	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO5822398301	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4768190956	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4475985809	LGE	1	60 BRN	SP	A	ID	BD	00:00.0
2021	PO4874907712	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4835207560	F	4	40 BRO	DF	CRE	ED,HH,ID,MD,RB	BX	PX 00:00.0
2021	PO4868607827	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4488987416	LGE	4	40 BEL	SP	A	ID	BD	00:00.0
2021	PO4515087958	LGE	3	50 BRO	SP	A	ED,ID	BD	00:00.0
2021	PO4513587955	LGE	3	50 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4514887964	F	4	35 BRO	SP	P		V	00:00.0
2021	PO4513987961	F	4	35 BRO	SP	P		V	00:00.0
2021	PO4514187956	LGE	2	55 BRO	SP	A	ED,ID	BD	00:00.0
2021	PO4515687959	LGE	2	55 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4446188929	LGE	4	25 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4445488930	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO7487078575	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4486987448	LGE	4	40 BEL	SP	CRE	ID	BD	00:00.0
2021	PO4446388932	LGE	4	40 ACE	SP	CRE	ED,ID,MD	TD	00:00.0
2021	PO4852907585	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4833207906	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4830707683	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO4827307592	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4817807632	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5164423327	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO4445988935	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021	PO7516978461	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO7517678728	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO7517278670	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO7515578576	KU	4	45 ACE	SP	CCA		V	00:00.0
2021	PO4445488935	LGE	3	45 ACE	SP	CCA		V	00:00.0

2021 PO4620909016	KU	4	40 XXX	SP	CRE	HH,ID	X	RP2	00:00.0
2021 PO5145009777	KU	2	55 XXX	ST	OTH		V		00:00.0
2021 PO5104623306	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO5180523973	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO4442988907	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4444488888	LGE	3	35 ACE	SP	CCA		V		00:00.0
2021 PO4476088027	LGE	3	55 ACE	SP	A	ED	BD		00:00.0
2021 PO4476688018	LGE	3	55 ACE	SP	A	ED	BD		00:00.0
2021 PO4229811104	KU	2	50 BRN	SP	CCA		T		00:00.0
2021 PO2854888176	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO2856388094	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO2835188210	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO7516679314	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7516679203	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7541379206	KU	3	50 ACE	SP	CCA		V		00:00.0
2021 PO7565879211	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO7591879211	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO3952118108	KU	3	45 KOP	SP	CCA		V		00:00.0
2021 PO4477588780	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4477188771	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4476988761	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4483187406	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4831508452	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4477888791	LGE	4	40 ACE	SP	A		V		00:00.0
2021 PO4477688810	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4477888799	LGE	4	35 ACE	SP	A		V		00:00.0
2021 PO4877108077	KU	5	35 BRN	SP	S		V		00:00.0
2021 PO4822408685	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4478088819	LGE	5	35 ACE	SP	CCA		V		00:00.0
2021 PO4477188816	LGE	4	40 ACE	SP	CRE	ED	V		00:00.0
2021 PO4477388820	F	4	30 ACE	SP	A		V		00:00.0
2021 PO4475988820	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4443788914	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7517578921	KU	4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7517378958	KU	4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7534878962	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO7538878963	KU	4	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7519479659	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7516879677	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO7516779542	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4509187946	LGE	4	40 BRO	SP	A	ED,ID	BD		00:00.0
2021 PO4547287850	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4507187943	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021 PO4503987936	LGE	2	60 BRO	SP	CCA		V		00:00.0
2021 PO4512187952	LGE	3	50 BRO	SP	A	ED,ID,IP,MD	BD		00:00.0
2021 PO4508687945	LGE	2	55 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4505987940	LGE	H4	50 BRO	SP	CRE	ED,EP,ID,MD	BD		00:00.0
2021 PO4511487951	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021 PO4509487951	F	4	35 BRO	SP	P		V		00:00.0
2021 PO4539087817	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4504587937	LGE	2	55 BRO	SP	CCA		V		00:00.0
2021 PO4510087948	LGE	2	55 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4539987823	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4549808790	F	4	40 XXX	SP	CRE		V		00:00.0

2021	PO4551508825	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4566508252	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO4565808149	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO4563508023	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4552707972	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO4528908058	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO4538908020	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO4522008083	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4529508274	F	4	40 XXX	SP	A		V		00:00.0
2021	PO4537708338	KU	4	40 XXX	SP	CCA		V		00:00.0
2021	PO4536908458	F	5	40 XXX	SP	CRE		V		00:00.0
2021	PO5068523340	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO5080423329	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO5060823349	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO4442188899	LGE	4	40 ACE	SP	CRE	ED,ID,RB	X	RR	00:00.0
2021	PO4485087477	LGE	4	40 BEL	SP	A	ED,ID	TD		00:00.0
2021	PO5071323550	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4803307693	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4793807733	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4778607796	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4762407864	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4767708001	F	4	40 XXX	DF	CRE		V		00:00.0
2021	PO4796307898	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4799807986	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4789308086	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO4773908147	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO2847788123	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO2847288179	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO4914409683	F	4	40 KOP	SP	P		V		00:00.0
2021	PO4824209335	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO4926309875	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4852409081	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO4833009115	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO4835509161	F	5	35 OTH	SP	CRE		V		00:00.0
2021	PO4915309944	F	4	40 OTH	SP	CCA		V		00:00.0
2021	PO4436389119	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4487287981	LGE	3	45 ACE	SP	CRE	ED	BD		00:00.0
2021	PO4486287976	LGE	3	45 ACE	SP	CRE	ED	BD		00:00.0
2021	PO4316516360a	KU	7	30 BRN	SP	CCA		V		00:00.0
2021	PO4437189126	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4485587973	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4484587969	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4483787965	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4194416597	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO4204016543	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO4228616408	KU	3	45 BRN	SP	CCA		V		00:00.0
2021	PO4213916483	KU	3	45 BRN	SP	CCA		V		00:00.0
2021	PO4995725382	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5075723960	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO4916209009	KU	6	30 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO4566323385	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO4563323162	KU	4	40 XXX	SP	CCA	ED	T		00:00.0
2021	PO4539823408	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4431688991	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0



2021 PO4512887963	F	4	35 BRO	SP	P		V		00:00.0
2021 PO4493487935	F	4	40 BRO	SP	P		V		00:00.0
2021 PO4493987942	LGE	2	55 BRO	SP	CCA		V		00:00.0
2021 PO4493287942	LGE	2	55 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4495687942	LGE	2	55 BRO	SP	CCA		V		00:00.0
2021 PO4494687942	LGE	2	55 BRO	SP	CCA		V		00:00.0
2021 PO4518387979	LGE	4	40 BRO	SP	A		V		00:00.0
2021 PO4483087962	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4917909221	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4438089096	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4194116568	KU	6	40 BRN	SP	CCA		V		00:00.0
2021 PO4197116719	KU	2	45 KOP	SP	CCA		V		00:00.0
2021 PO4198416831	KU	3	50 KOP	SP	CCA		T		00:00.0
2021 PO4482387959	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5068223967	KU	6	35 BRO	SP	CRE	ED,ID	BX	PX	00:00.0
2021 PO4848209189A	KU	5	35 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4916209466	KU	4	40 XXX	SP	S	ED,Src	T		00:00.0
2021 PO4948209189	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO4941309211	KU	6	30 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO4437289107	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4506023437	KU	4	45 XXX	SP	CCA		V		00:00.0
2021 PO4491223448	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5089623947	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO5100623937	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021 PO4475723461	KU	4	45 XXX	SP	CCA		V		00:00.0
2021 PO4453023482	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4429123501	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5113023925	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021 PO5036808538	F	4	40 BRN	SP	P		V		00:00.0
2021 PO5052908861	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5057308367	F	4	40 BRN	DF	CRE		V		00:00.0
2021 PO5057908971	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5041508418	F	4	40 BRN	SP	CRE	RB	BX	PX	00:00.0
2021 PO5050108353	KU	3	45 BRN	SP	S		V		00:00.0
2021 PO4907409057	F	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4916609101	F	4	40 OTH	SP	CCA		V		00:00.0
2021 PO4949209608	F	4	45 KOP	SP	P		V		00:00.0
2021 PO4950509735	F	4	45 KOP	SP	P		V		00:00.0
2021 PO4876909086	F	2	50E OTH	SP	CRE		V		00:00.0
2021 PO4934509379	KU	3	45 OTH	SP	CCA		V		00:00.0
2021 PO4892109326	F	4	40 OTH	SP	P		V		00:00.0
2021 PO4941309795	F	4	40 KOP	SP	P		V		00:00.0
2021 PO4917509305	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO4930409315	F	4	40E OTH	SP	CRE		V		00:00.0
2021 PO4870108987	F	3	45E OTH	SP	CRE		V		00:00.0
2021 PO4911009012	F	3	40E OTH	SP	P		V		00:00.0
2021 PO4890009020	F	5	35E OTH	SP	CRE		V		00:00.0
2021 PO4926909265	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4943709523	F	4	45 KOP	SP	P		V		00:00.0
2021 PO4936709230	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4885409218	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO4897609415	F	3	45 OTH	SP	CCA		V		00:00.0
2021 PO4954409687	F	2	35E KOP	SP	P		V		00:00.0
2021 PO4903808966	KU	5	35 BRN	SP	CCA		V		00:00.0

2021 PO4041416712	KU	4	45 KOP	SP	CRE	ID	TD	00:00.0
2021 PO4438789087	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4438689083	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5145523895	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO5131923908	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4429887785	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4400523442	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4403423513	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4395823560	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4388723589	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4396923713	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4397923870	KU	4	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4398824012	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4399724187	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4445224046	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4451024063	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO4436489024	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4436789024	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4459488013	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4461288025	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4462088030	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4462988036	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4463788042	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4464288045	LGE	4	30 BRO	SP	A	ID	BD	00:00.0
2021 PO4436489036	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX	RP2 00:00.0
2021 PO4436289043	LGE	5	25 ACE	SP	CRE		V	00:00.0
2021 PO4442088975	F	1	75 ACE	SP	A		V	00:00.0
2021 PO5014725400	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4015717478	KU	4	45 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4529187858	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4536787660	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4529887511	F	2	60 BRO	SP	CRE		V	00:00.0
2021 PO4529887847	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4530287487	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4528487577	F	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4538287811	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4536587800	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3997917593	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5098923623	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO5110923612	KU	4	40 BRO	SP	CRE	ED,ID	BX	PX 00:00.0
2021 PO4480187966	LGE	3	55 ACE	SP	CRE	ED,IP	TD	00:00.0
2021 PO4479487978	LGE	3	50 ACE	SP	P	ED	TD	00:00.0
2021 PO5086423635	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4955808636	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4952308545	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4974208422	KU	5	35 BRN	SP	S		V	00:00.0
2021 PO4940608524	KU	6	35 BRN	SP	S		V	00:00.0
2021 PO5074423843	KU	4	40 BRO	SP	CRE		T	00:00.0
2021 PO5072823648	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4430289089	LGE	4	40 ACE	SP	A	ED	V	00:00.0
2021 PO4429489082	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4464087838	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4431189097	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO1391703303	LGE	3	45 ACE	SP	CCA		V	00:00.0

2021 PO5041123848	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5041923958	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4848308490	F	4	40 BRN	DF	CRE	ED,ID,MD,RB	BX PX	00:00.0
2021 PO4857608453	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4861808437	KU	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4836608537	F	4	40 BRN	SP	S		V	00:00.0
2021 PO4817408557	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4964708511	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4433089087	LGE	5	25 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4431989081	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO3603217570	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4231313545A	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9651698645	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9467098295	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO3573317651	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO9482098548	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO3561417081	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO3592417130	KU	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO9432098286	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9682193497	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9685593636	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9679094167	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9693093935	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9689793805	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9639493772	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4272113454	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO7978311786	KU	3	45 BRN	SP	CRE		BD	00:00.0
2021 PO4269413788	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO8108212115	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4471485896	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4476485890	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO3616616906	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO3611716693	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO3607616477	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO3603616305	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO3620817123	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4465686124	LGE	4	35 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO4230112673	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9708594524	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9548595152	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4538787843	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9341890823	KU	5	35 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO4537587835	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4537187832	LGE	4	35 ACE	SP	A	ED	BD	00:00.0
2021 PO4423085942	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4392185265	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO9278890080	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4533987816	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4533987811	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4535087819	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4533487814	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021 PO4469385991	LGE	4	35 ACE	SP	P	ED,IP	BD	00:00.0
2021 PO4467385987	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4465685903	LGE	4	40 ACE	SP	P	ED,IP	BD	00:00.0

2021 PO4467785900	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO4472485999	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO7977810508	KU	3	45 BRN	SP	CRE	ED,JD	BD	00:00.0
2021 PO4539387847	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO4534887824	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021 PO7971610409	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4458486046	LGE	2	50 ACE	SP	P	ED	BD	00:00.0
2021 PO4480785636	LGE	3	45 ACE	SP	A	ED,JD	BD	00:00.0
2021 PO4482585651	LGE	4	40 ACE	SP	A	ED,JD	BD	00:00.0
2021 PO4451185747	LGE	5	35E ACE	SP	CRE	ED,JD	BD	00:00.0
2021 PO4451885736	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021 PO4451085790	LGE	3	45 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO4447785770	LGE	2	65 ACE	SP	CRE	ED,JD	BD	00:00.0
2021 PO4449785770	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4458985483	LGE	4	40 ACE	SP	CRE	ED,JD	BD	00:00.0
2021 PO4459785488	LGE	4	40 ACE	SP	CRE	ED,JD	BD	00:00.0
2021 PO4460685495	LGE	4	40 ACE	SP	A	ED,JD	BD	00:00.0
2021 PO4461785502	LGE	4	40 ACE	SP	P	ED,JD	BD	00:00.0
2021 PO8005410060	KU	3	45 KOP	SP	CRE	ED	BD	00:00.0
2021 PO4433886150	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO9567093187	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4475385598	LGE	UNK	70 ACE	SP	A	ED,JD	BD	00:00.0
2021 PO4476285610	LGE	4	35 ACE	SP	P	ED,JD	BD	00:00.0
2021 PO4476685608	LGE	3	50 ACE	SP	A	ED,JD	BD	00:00.0
2021 PO4473085582	LGE	UNK	65 ACE	SP	A	ED,JD	BD	00:00.0
2021 PO4432485214	LGE	4	30 ACE	SP	CRE	ED,JD	BD	00:00.0
2021 PO5921500370	KU	4	40 ACE	SP	CRE	ED,JD,IP	BD	00:00.0
2021 PO5938900654	KU	4	30 ACE	SP	CRE	ED,JD,IP	BD	00:00.0
2021 PO4452285730	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021 PO4453185714	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4547087897	LGE	4	40 BRO	SP	A	ED	BD	00:00.0
2021 PO4549687914	LGE	4	40 BRO	SP	CRE	ED,JD	BD	00:00.0
2021 PO4548787908	LGE	4	40 BRO	SP	CRE	ED,JD	BD	00:00.0
2021 PO9625795615	KU	3	45 XXX	SP	CRE	ED,JD,IP	BD	00:00.0
2021 PO9632095490	KU	3	45 XXX	SP	CRE	ED,JD	BD	00:00.0
2021 PO9640395531	KU	3	45 XXX	SP	CRE	ED,JD	BD	00:00.0
2021 PO4544287878	LGE	4	35 BRO	SP	CRE	ED,JD	BD	00:00.0
2021 PO4543487873	LGE	4	40 BRO	SP	A	ED,JD	BD	00:00.0
2021 PO4422485757	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4421985746	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4421485752	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO9232491944	KU	4	40 UNK	SP	CRE	ED,JD	BD	00:00.0
2021 PO9281789810	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9654595778	KU	4	40 XXX	SP	CRE	ED,JD	BD	00:00.0
2021 PO7985110627	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4542587868	LGE	4	35 ACE	SP	A	ED,JD	BD	00:00.0
2021 PO4541787862	LGE	4	35 ACE	SP	A	ED,JD	BD	00:00.0
2021 PO4540287853	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4545987890	LGE	4	40 BRO	SP	A	ED,JD	BD	00:00.0
2021 PO7999310857	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO9107689440A	KU	3	40 XXX	SP	CRE	ED,JD,IP	BD	00:00.0
2021 PO3646816218	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 4469586009	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO4458985851	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0

2021 PO4459885858	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021 PO9602594578	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9610194694	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9450690451	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4531187613	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8026210744	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO3638017906	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO3653117902	KU	5	35 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO3633817722	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO3979915372	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4221114004	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4464886039	LGE	4	30 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4222614114	KU	3	50 XXX	SP	CRE	ID,IP	BD	00:00.0
2021 PO8976091542	KU	5	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9107689440	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7987611257	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO9753688612	KU	2	50 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9598289027	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9282591917	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9606296318	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4464285960	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO4461485870	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4457785796	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO9611296321	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO7981910575	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4425285794	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO3899814111	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4463886081	LGE	3	50 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4462986137	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4460786044	LGE	3	45 ACE	SP	P	ED,IP	BD	00:00.0
2021 PO4464785663	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4461085638	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4459785628	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4458285610	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 4462285646-a	LGE	3	30 ACE	SP	P	ED	BD	00:00.0
2021 PO4466085670	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 4468385641-b	LGE	3	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4464585623	LGE	UNK	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4463785617	LGE	UNK	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4463985613	LGE	UNK	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4463385720	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5966802392	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9641293392	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9415490975	KU	1	70 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4455285766	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO4455985753	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO8057511220	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO9590594764	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9609994844	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4450485789	LGE	1	65 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO4450885793	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4028615531	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9572494731	KU	3	45 XXX	SP	CRE	ED,ID,IP,MD	BD	00:00.0
2021 PO9558294576	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0

2021 PO4478085588	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4478585581	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4478285571	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO4479285570	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3585319800	KU	3	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO9547095094	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9543996053	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9550596165	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9553396123	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9535295907	KU	2	50 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9535696414	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9516896437	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9501996454	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9515792359	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4475785592	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4474285582	LGE	UNK	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8020810391	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4432486050	LGE	2	55 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4432386044	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO8027510528	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO8007710477	KU	2	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO9654894838	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4480185557	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4480985546	LGE	UNK	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4482085530	LGE	UNK	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4481985529	LGE	3H	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO9376690925	KU	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO4432086032	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO3991315821	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4002015763	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4456485451	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4433586094	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4434086119	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4001115995	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4012315944	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3955016229	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO8014410253	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4417786138	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4466685677	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4467185680	LGE	4	50 ACE	SP	P	ED,ID	BD	00:00.0
2021 4468385641-a	LGE	3	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO9529194255	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9621194345	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9619993893	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO3694916076	KU	6	30 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3695016186	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3703916469	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4410986113	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO3754115941	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9703492999	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4475085682	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4475485676	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4472385723	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 4472385723-a	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0

2021 PO3919515434	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3913115405	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3803015686	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3851615515	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9843392026	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9822692172	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4467085560	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO9854891946	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4462685551	LGE	UNK	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4463485539	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4463785535	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 4460485569-c	LGE	3	50 ACE	SP	A	ED	BD	00:00.0
2021 PO4470385576	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4469285588	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO1994523843	KU	5	35 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO9738492757	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9717592904	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4473685603	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4473285679	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9455495154	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8079010894	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO9585394113	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9565994237	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4458485751	LGE	3	45 ACE	SP	CCA	ED	BD	00:00.0
2021 PO9582294476	KU	5	35 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4435186150	LGE	5	25 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4482185645	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO9558193009	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO2185723568	KU	3	50 BRN	SP	CRE	ID	BD	00:00.0
2021 PO2185623522	KU	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4435686162	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4492585709	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4488085688	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4489785701	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO7996111414	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO7991211405	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7948111327	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 4463985613	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9878091288	KU	5	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9718493294	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9505195403	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4456885574	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9442995235A	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4454485572	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4448185626	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4446885646	LGE	4	35 ACE	SP	A	ED	BD	00:00.0
2021 PO4447385636	LGE	4	35 ACE	SP	A	ED	BD	00:00.0
2021 PO0552039222	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4966589592	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO6688107146	LGE	4	35 ACE	SP	CCA	ED	TD	00:00.0
2021 PO4934190153	LGE	4	40 BRN	SP	A	ED,ID,MD	TD	00:00.0
2021 PO0472138860	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO0483238759	ODP	5	35 BRN	SP	CRE	ED,ID,MD	TD	00:00.0
2021 PO5382310086	KU	6	30 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0

2021	PO5386610084	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO4937988895	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO9242925617	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO9256625412	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO9281225638	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO9290325739	ODP	6	30 XXX	DF	CRE	ED,ID,IP	TD	00:00.0
2021	PO8662221412	ODP	6	30 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021	PO8658421387	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0
2021	PO5417208928	KU	6	30 BRN	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021	PO0331138533	ODP	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7263017085	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6974419641	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7039619458	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7007719407	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO0125733430	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0120033792	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0115633917	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0256332847	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0273532949	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO8680521602	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021	PO4857288934	LGE	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO6911219616	ODP	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4823188779	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4931089913	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO9270325820	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO9647123746	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4825388788	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4825688780	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO707719316	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7092819347	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7069719497	ODP	4	40 BRN	SP	CRE	ED,EP,ID	TD	00:00.0
2021	PO4814788746	LGE	3	55 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO0022833604	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO4932788937	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6944721452	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO0022333525	ODP	5	45 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0054133404	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021	PO8717121906	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021	PO6950521107	ODP	3	45 BRN	SP	CCA	ED,ID,IP	TD	00:00.0
2021	PO8715021997	ODP	4	45 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021	PO6960320531	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5464311162	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021	PO7731916514	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7759916580	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7806216725	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4833289530	LGE	3	45 BRN	SP	P	ID	TD	00:00.0
2021	PO4937188988	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO7601821142	ODP	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5510511958	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021	PO7998721561	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO7996121424	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO0250333321	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7730844566	ODP	4	40 BRN	SP	CRE	ID,IP	TD	00:00.0
2021	PO0232433173	ODP	4	35 XXX	SP	CRE	ED,ID	TD	00:00.0



2021 PO4862588952	LGE	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4862188960	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9555624387	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9592124297	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4975989790	LGE	4	40 ACE	SP	CCA	ED	TD	00:00.0
2021 PO7493643574	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7523243686	ODP	5	30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7711344501	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8338919751	ODP	4	40 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO4806288745	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9228124397	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7603119803	ODP	6	30 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO4825488884	LGE	4	45 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4825888871	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4845489372	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5507711833	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4921288763	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8319619779	ODP	6	30 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5517711578	KU	3	45 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO5375413070	KU	6	30 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8734822053	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO8791522246	ODP	4	45 KOP	SP	CRE	ED	TD	00:00.0
2021 PO6223720809	ODP	4	40 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO6220820716	ODP	4	40 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8770322182	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO0389538458	ODP	5	35 OTH	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0656938102	ODP	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5574820604	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4885488591	LGE	1	55 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4969989570	LGE	4	40 ACE	SP	CCA	ED	TD	00:00.0
2021 PO4970689565	LGE	4	40 ACE	SP	CCA	ED	TD	00:00.0
2021 PO4971489561	LGE	4	40 ACE	SP	CCA	ED	TD	00:00.0
2021 PO7795820865	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7812120472	ODP	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9267024969	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9265525171	ODP	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8103321147	ODP	5	35 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO7403920280	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7796920296	ODP	6	30 OTH	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO9342725296	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4938389741	LGE	3	45 BRN	SP	P	ED,ID,MD	TD	00:00.0
2021 PO4938289740	LGE	3	45 BRN	SP	P	ED,ID,MD	TD	00:00.0
2021 PO9352525433	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9044423610	ODP	4	40 REP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4826888841	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4854589186	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7819119485	ODP	5	35 OTH	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO7819320203	ODP	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5509511066	KU	3	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO5512111058	KU	2	50 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7763819837	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8487221142	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO6887517645	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6892618040	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0

2021 PO6612118750	ODP	5	35 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8821021810	ODP	4	45 KOP	SP	CCA	ED,SRC	TD	00:00.0
2021 PO8808221938	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4827688671	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO6818918982	ODP	4	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO8413119763	ODP	4	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4827988813	LGE	4	35 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO4827388830	LGE	4	40 BRO	SP	P	ED,ID,MD	TD	00:00.0
2021 PO4830488743	LGE	3	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9050323385	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5369311502	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO5379611518	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO4942789709	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO7824220864	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4924588830	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO8409120665	ODP	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4826188863	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4725989911	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO8293020631	ODP	2	50 KOP	SP	CRE	ED	TD	00:00.0
2021 PO8426720726	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4829288774	LGE	4	35 BRO	SP	P	ED,ID,MD	TD	00:00.0
2021 PO5524911413	KU	5	35 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO4839189139	LGE	4	30 BRN	SP	A	ED	TD	00:00.0
2021 PO7897420320	ODP	4	40 BRO	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO7849220726	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7860020265	ODP	5	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO4926188834	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4926288841	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5508011609	KU	4	45 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO5821417552	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5725017390	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6440916973	ODP	4	40 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO6408117021	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4945789500	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4948289389	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO8350119643	ODP	5	35 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO5493012369	KU	5	35 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO4842189301	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4840889296	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8423120850	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7826420486	ODP	5	35 OTH	SP	A	ED,ID	TD	00:00.0
2021 PO4832088741	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP	TD	00:00.0
2021 PO4834588744	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO5518212225	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO4711989769	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO8332920002	ODP	5	30 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO5516512180	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO4709989790	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5383011649	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO5495211229	KU	4	50 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO4949889477	LGE	5	30 ACE	SP	A	ED,SRC	TD	00:00.0
2021 PO7815319648	ODP	5	35 OTH	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO7856721002	ODP	4	40 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO4920888750	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0

2021	PO7593220502	ODP	5	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4852089177	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4849489168	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO7811819834	ODP	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7598120944	ODP	5	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO9332022897	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9435330477	ODP	6	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5478212448	KU	5	35 OTH	SP	CRE	ED,ID	TD	00:00.0
2021	PO6973519342	ODP	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6991919386	ODP	2	50 BRN	SP	CCA	ED,ID	TD	00:00.0
2021	PO7593820768	ODP	5	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7859321224	ODP	4	45 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO6892019130	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6864319062	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8096121418	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO7598621354	ODP	5	35 OTH	SP	CRE	ED,ID	TD	00:00.0
2021	PO4724489770	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO8049821324	ODP	4	40 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021	PO4825788634	LGE	4	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4823488655	LGE	4	40 BRO	SP	P	ED,ID,MD	TD	00:00.0
2021	PO4824488659	LGE	3	45 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4825188654	LGE	4	30 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO4824488654	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO6953823225	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9890535265	ODP	4	35 BRN	SP	CCA	ED,ID,IP	TD	00:00.0
2021	PO4836689080	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4725690070	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO9863935264	ODP	4	40 BRN	SP	CCA	ED,SRS	TD	00:00.0
2021	PO4725090065	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO1410744687	ODP	4	40 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO1409244609	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO1354444333	ODP	4	40 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO4723390026	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4875088595	LGE	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4876188590	LGE	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO8985123444	ODP	5	35 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO8993123357	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO8937623145	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO8945623266	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO8953723183	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO1249343756	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO1292843852	ODP	4	40 UNK	SP	P	ED,ID,SRC	TD	00:00.0
2021	PO1314344075	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO5419311289	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8728321504	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021	PO4938589704	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO4915588930	LGE	4	35 BRO	SP	CRE	ID,IP	TD	00:00.0
2021	PO4916688934	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO0002735990	ODP	6	30 OTH	SP	CRE	ED,ID	TD	00:00.0
2021	PO4872288606	LGE	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO7949520410	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4701789872	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4838288732	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021	PO4837088734	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0

2021	PO5417212051	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO8391519403	ODP	6	25 BRN	SP	A	ED	TD		00:00.0
2021	PO5321141822	KU	3	40 BRO	SP	CRE		T		00:00.0
2021	PO5385139754	KU	4	40 KOP	SP	CRE		T		00:00.0
2021	PO5176225190	KU	4	40 BRO	SP	CRE		T		00:00.0
2021	PO5360939271	KU	5	35 KOP	SP	CRE		T		00:00.0
2021	PO5112024819	KU	4	40 BRO	SP	P		T		00:00.0
2021	PO5452635917	KU	4	45 BRN	SP	CRE		T		00:00.0
2021	PO5280624915	KU	4	40 BRO	SP	CRE		T		00:00.0
2021	PO5071524595	KU	4	40 BRO	SP	CRE		T		00:00.0
2021	PO5226225049	KU	4	40 BRO	SP	P		T		00:00.0
2021	PO6634325002	KU	4	40 XXX	SP	CCA	ED	T		00:00.0
2021	PO5472007515	KU	3	45 XXX	SP	S	ED,SRC	T		00:00.0
2021	PO5295241755	KU	4	40 BRO	SP	CRE		T		00:00.0
2021	PO4412885426	LGE	4	40 BRO	SP	CCA	ED	T		00:00.0
2021	PO1162973766	LGE	4	35 BRO	SP	CCA	ED	T		00:00.0
2021	PO5389028271A	KU	3	25 BRO	SP	P		T		00:00.0
2021	PO6469023415	KU	4	40 XXX	SP	CCA	ED	T		00:00.0
2021	PO6471623164	KU	4	40 XXX	SP	CCA	ED	T		00:00.0
2021	PO6491923083	KU	3	45 XXX	SP	CCA	ED	T		00:00.0
2021	PO6518022976	KU	4	35 XXX	SP	CCA	ED	T		00:00.0
2021	PO5277943151	KU	4	40 BRO	SP	CRE		T		00:00.0
2021	PO5320841919	KU	6	30 BRO	SP	P		T		00:00.0
2021	PO5274143541	KU	4	40 KOP	SP	P		T		00:00.0
2021	PO5272943824	KU	4	40 KOP	SP	CRE		T		00:00.0
2021	PO5309320172	KU	4	40 KOP	SP	P		T		00:00.0
2021	PO5300211354	KU	2	50 XXX	SP	S	ED,MD,SRC	T		00:00.0
2021	PO5357235596	KU	4	40 BRN	SP	CRE		T		00:00.0
2021	PO5356135714	KU	4	40 BRN	SP	CRE		T		00:00.0
2021	PO5293510939	KU	2	50 XXX	SP	S	ED,MD,SRC	T		00:00.0
2021	PO5352529111	KU	6	30 BRO	SP	CRE		T		00:00.0
2021	PO5359429038	KU	4	40 BRO	SP	CRE		T		00:00.0
2021	PO6109621027	KU	4	40 XXX	SP	CCA	ED	T		00:00.0
2021	PO5323525809	KU	4	40 ESC	SP	CRE		T		00:00.0
2021	PO6085320525	KU	4	45 XXX	SP	CCA	ED	T		00:00.0
2021	PO5316025911	KU	6	30 ESC	SP	CRE		T		00:00.0
2021	PO5316435113	KU	4	40 BRN	SP	CRE		T		00:00.0
2021	PO5345234966	KU	4	40 BRN	SP	CRE		T		00:00.0
2021	PO5089424063	KU	5	35 BRO	SP	P		T		00:00.0
2021	PO7073807555	KU	5	35 UNK	SP	CRE	ED,HH,ID	BX	RP1	00:00.0
2021	PO4968027797	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO3933407794	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021	PO3998807749	F	4	40 BRO	SP	CRE	ED,RB	BX	RP3	00:00.0
2021	PO3936407867	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021	PO5375320355	F	4	40 BRO	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO4379309084	F	4	40 XXX	SP	CRE	HH,ID	BX	PX	00:00.0
2021	PO5023327462	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO3890417132	KU	3	45 BRN	SP	CRE	ED,ID,RB	BX	RP1	00:00.0
2021	PO4689427929	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021	PO4659626623	F	6	30 XXX	SP	CRE	ED,ID,RB	BX	RP2	00:00.0
2021	PO4619226790	F	5	35 XXX	SP	CRE	ED,HH,ID,RB	BX	RP3	00:00.0
2021	PO5373708529	F	3	45 BRO	SP	CRE	ED,HH,ID,IP	BX	PX	00:00.0
2021	PO4982727707	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO5053027046	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	RP2	00:00.0

2021 PO5049027323	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO5002227589	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	RP2	00:00.0
2021 PO4992127318	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO5046227049	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4936327470	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021 PO4954927105	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	RP1	00:00.0
2021 PO4270487134	LGE	2	50 ACE	SP	CRE	ED,ID	BX	RR	00:00.0
2021 PO5485205066	F	4	40 BRO	SP	CRE	ED,HH,ID	BX	RP2	00:00.0
2021 PO4906427099	F	4	40 XXX	SP	CRE	ED,ID,RB	BX	RP3	00:00.0
2021 PO5264616773	KU	5	35 BRN	SP	CRE	ED,ID,IP,RB	BX	PX	00:00.0
2021 PO5141316709	KU	4	45 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4060107445	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021 PO5182119572	KU	3	45 KOP	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021 PO4027508003	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	RP3	00:00.0
2021 PO4079107752	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021 PO5100717432	KU	5	35 UNK	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO4736725766	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	RP3	00:00.0
2021 PO5464607673	KU	2	60 XXX	SP	CRE	ED,ID,MD,RB	BX	RP1	00:00.0
2021 PO5561509654	KU	3	45 XXX	SP	CRE	ED,ID,RB	BX	RP3	00:00.0
2021 PO4716126575	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,RB	BX	PX	00:00.0
2021 PO3969007970	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4095309182	F	3	45 XXX	SP	CRE	ED,HH,ID,RB	BX	RP3	00:00.0
2021 PO5349638890	F	4	40 XXX	SP	CRE	ED,ID,IP,MD,RB	BX	PX	00:00.0
2021 PO6951609862	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4416585442	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4318386940	LGE	3	45 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4319786917	LGE	3	50 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4319386923	LGE	3	45 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4320686903	LGE	2	50 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO5767937549	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4324286853	LGE	3	50 BRO	SP	CRE	ED,EP,ID,IP,RB	BD		00:00.0
2021 PO5294702650	KU	1	75 BRO	SP	CRE	IP	BD		00:00.0
2021 PO4424085491	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4270186976	LGE	1	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4274987031	LGE	3	50 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4274687031	LGE	3	50 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO3808118605	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4273187033	LGE	3	50 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4251387315	LGE	4	30 ACE	SP	A	ED	BD		00:00.0
2021 PO5189616197	KU	3	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5147014253	KU	2	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5347839250	KU	4	40 UNK	SP	CRE	ED,ID	BD		00:00.0
2021 PO5169614343	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5288316143	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5412007624	KU	3	45 BRO	SP	CRE		BD		00:00.0
2021 PO5762114172	KU	5	35 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO5357311102	KU	3	45 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO4270486994	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5308834113	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4400886119	LGE	4	30 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4401986102	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4401986108	LGE	4	35 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4273386940	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4272686941	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0

2021 PO4401486130	LGE	3	50 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO3814418647	KU	6	30 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO5452809355	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5870801609	KU	4	35 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6169221243	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO6132620716	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5862601828	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5855401967	KU	4	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5491605855	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO5451608749	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5433708818	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5427408843	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5417608393	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5368034918	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO6415323113	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5492505869	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO5448908599	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO6226723538	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO6253823540	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO6322322825	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5502509361	KU	1	70 BRN	SP	CRE		BD	00:00.0
2021 PO4425385499	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5414707617	KU	3	45 BRO	SP	CRE		BD	00:00.0
2021 PO4289286860	LGE	1	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5549209324	KU	2	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO5550509337	KU	6	30 BRN	SP	CRE	ED	BD	00:00.0
2021 PO5662010822	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5400610953	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4254687361	LGE	2	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5330415467	KU	5	35 KOP	SP	CRE	ID	BD	00:00.0
2021 PO5776997271	KU	5	35 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5380729160	KU	6	30 BRO	SP	P		BD	00:00.0
2021 PV4269286915	LGE	1	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4269486924	LGE	1	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5147616957	KU	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4497087881	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5137116547	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4498787854	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5378016871	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4398386177	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4265387029	LGE	3	50 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4400486143	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4265287043	LGE	2	50 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4396986197	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4498987910	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4264686975	LGE	1	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4264286944	LGE	1	50 ACE	SP	CRE	ED,HH,ID	BD	00:00.0
2021 PO4497687926	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4497187934	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4498087920	LGE	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4501687866	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4500887879	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5350338700	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO4417885724	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0

2021	PO5374508724A	KU	5	30 BRO	SP	CRE	ED	BD	00:00.0
2021	PO5374508724	KU	3	45 BRO	SP	CRE	ED	BD	00:00.0
2021	PO5302615637	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5394608659	KU	3	45 BRO	SP	CRE	ED	BD	00:00.0
2021	PO5302408086	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO5302408086a	KU	3	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4259887007	LGE	1	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4270286993	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4270787016	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4293486812	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4423985626	LGE	3	50 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO7048105810	KU	4	40 UNK	SP	P	ID	BD	00:00.0
2021	PO4418685711	LGE	1	55 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO5197616210	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4398386208	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO5839112296	KU	6	30 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4402686082	LGE	2	50 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4402686096	LGE	2	55 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO5496709132	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021	PO5409308415	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO7042106242	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021	PO7036206003	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5312116350	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5325916197	KU	5	30 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5316516124	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5272816361	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4251487318	LGE	4	40 ACE	SP	CRE	HH,ID	BD	00:00.0
2021	PO4251487317	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO6251922766	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4255087526	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5367708523	KU	3	45 BRO	SP	CRE		BD	00:00.0
2021	PO4400886100	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4428185517	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO7008909004	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5445208982	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO5438108992	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO5435008847	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO5419909035	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO4265587070	LGE	2	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5301211385	KU	2	50 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4425085605	LGE	1	60 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4253887260	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4417485691	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4416085693	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4253187375	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4253187373	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5474109226	KU	3	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO5442905194	KU	5	35 BRO	SP	CRE		BD	00:00.0
2021	PO5577007111	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5430311115	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5581407226	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4495887898	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5356937322	KU	4	40 BRN	SP	CRE	ED,ID,MD	BD	00:00.0
2021	PO5153817203	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0

2021 PO4171128586	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO4264286942	LGE	1	50 ACE	SP	CCA	ED,ID	BD	00:00.0	
2021 PO4264086926	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4401886152	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO4264287001	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PV4269186910	LGE	2	80 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PV4269186908	LGE	1	50 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4419885691	LGE	3	50 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO4426285613	LGE	1	60 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO4266786950	LGE	1	55 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO4268586947	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4267286948	LGE	2	50 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PV4267586915	LGE	4	25 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO7078514326	KU	4	40 KOP	SP	CRE		BD	00:00.0	
2021 PO4286686893	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO3968405586	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO3035969342	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO6667486448	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0	
2021 PO7060369023	KU	4	45 BRO	SP	CCA		V	00:00.0	
2021 PO2846174566	KU	1	70 BRO	SP	CRE		V	00:00.0	
2021 PO2832975016	KU	1	70 BRO	AL	CCA		V	00:00.0	
2021 PO2830975016	KU	1	70 BRO	AL	CCA		V	00:00.0	
2021 PO2834975016	KU	1	70 BRO	AL	CCA		V	00:00.0	
2021 PO2844474576	KU	1	70 BRO	SP	CRE		V	00:00.0	
2021 PO2847974556	KU	1	70 BRO	SP	CRE		V	00:00.0	
2021 PO2849777464	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO7063669624	KU	1	50 XXX	SP	CRE		V	00:00.0	
2021 PO7077869558	F	5	35 XXX	SP	P		V	00:00.0	
2021 PO3949406677	F	4	40 BRN	SP	CRE	ED,IP	V	00:00.0	
2021 PO5881489443	KU	2	55 BRN	SP	CCA	ED	T	00:00.0	
2021 PO4151005655	F	4	40 BRN	SP	CRE	IP	V	00:00.0	
2021 PO4306586894	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO4308586862	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4302786917	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO4307386876	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2355378815	F	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO4288187110	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4316086865	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO7220766254	KU	4	40 UNK	SP	CRE	ED,ID,IP,RB,SRC	TX	RR	00:00.0
2021 PO5338526550	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO6969710012	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO6837609011	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO6234522547	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5236316518	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5218417541	KU	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5317716451	KU	6	30 UNK	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4428785545	LGE	3	50 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO5252916447	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5379708513	KU	3	45 BRO	SP	CRE	ED	TD	00:00.0	
2021 PO5390608483	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0	
2021 PO6289422411	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5392208460	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0	
2021 PO4416085669	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4417285697	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0	



2021 PO3556915043	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6989710166	KU	2	60 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4401386043	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5180131728	KU	3	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5404508427	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4415285615	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4417185629	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4416385623	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO9720781461	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4261387006	LGE	3	50 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5414908401	KU	3	45 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021 PO5393308599	KU	3	45 BRO	SP	CRE	ED	TD	00:00.0
2021 PO6535023737	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4209930437	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4310429635	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4423785628	LGE	3	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5280511121	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4294586795	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4294286799	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4294286819	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5484809456	KU	3	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5481509470	KU	3	45 XXX	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO5474109500	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4424385618	LGE	1	55 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5473308663	KU	3	45 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5469008680	KU	6	30 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5411313341	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5442113613	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5426813485	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5401605068	KU	3	45 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5272942799	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5537302064	KU	5	35 XXX	SP	CRE	ED,ID,MD,SRC	TD	00:00.0
2021 PO5558301944	KU	5	35 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021 PO5577601808	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5597201672	KU	5	35 XXX	SP	CRE	ED,ID,MD,SRC	TD	00:00.0
2021 PO5617901539	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5638301424	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO6566023526	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6563423919	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6558223979	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6630224634	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6622924019	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6627024322	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4432029447	KU	6	30 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4442829628	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO435529631	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4431929344	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5134516444	KU	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5225719946	KU	4	40 KOP	SP	P	ED,ID	TD	00:00.0
2021 PO5152117135	KU	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5236316879	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5291231431	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5431008360	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5148417522	KU	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0

2021	PO5172517481	KU	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO5210916980	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4497587872	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5132717294	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4501987864	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5574808580	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021	PO4423085484	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4737410726	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4425685501	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO7588807028	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4427785514	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO5075817527	KU	5	35 UNK	SP	CRE	ED,ID,MD	TD	00:00.0
2021	PO5431707389	KU	3	40 BRO	SP	CRE	ED	TD	00:00.0
2021	PO5452810433	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5429607576	KU	2	40 BRO	SP	CRE	ED	TD	00:00.0
2021	PO5426307611	KU	6	30 BRO	SP	CRE	ED	TD	00:00.0
2021	PO5429407727	KU	5	35 BRO	SP	CRE	ED	TD	00:00.0
2021	PO6297723382	KU	4	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO5392708568	KU	3	45 BRO	SP	CRE	ED	TD	00:00.0
2021	PO4417185730	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO3529214476	KU	5	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4219928801	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO3910817610	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4412385414	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4461621003	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4226430086	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021	PO4265429220	KU	4	45 BRN	SP	CRE	ED	TD	00:00.0
2021	PO6237323011	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6211822648	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6337423361	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6342523287	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6230021916	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6211622023	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6192422144	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5444008497	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7052308323	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7148908919	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7125408654	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5498005850	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021	PO5496805831	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021	PO5372935014	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5449708686	KU	2	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5446408577	KU	2	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO5336036536	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5319037970	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5392534657	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5401034440	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6147420835	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6190420930	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5409234202	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6535823994	KU	5	35 XXX	SP	CRE	ID,IP	TD	00:00.0
2021	PO3803218708	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4412485410	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO6535223847	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0

2021 PO4291887135	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5487709352	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5465907670	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SR	TD	00:00.0
2021 PO5868101724	KU	4	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5473207489	KU	3	45 XXX	SP	CRE	ED,ID,IP,MD	TD	00:00.0
2021 PO5616437629	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5458238439	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5424838347	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5409205276	KU	2	45 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5415505298	KU	5	35 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5415905386	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5413405395	KU	5	35 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5284741033	KU	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4314986981	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4316086972	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5448734131	KU	4	40 BRO	SP	CRE	ED,HH,ID	TD	00:00.0
2021 PO5469634097	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6152021039	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6127521121	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5388204726	KU	3	45 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5386304682	KU	3	45 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5392104660	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5394204703	KU	5	35 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5390005264	KU	3	45 BRO	SP	CRE	ED	TD	00:00.0
2021 PO2402919312	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5565214055	KU	3	50 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5595213103	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5607912909	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5591612938	KU	3	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4415585606	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5359011130	KU	3	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5515211973	KU	6	30 XXX	SP	CRE	ID,IP	TD	00:00.0
2021 PO5523412074	KU	6	30 XXX	SP	CRE	ED	TD	00:00.0
2021 PO5565911723	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2386419626	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2380219368	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5419207020	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5420407016	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5283431580	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4418285617	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4596827169	KU	6	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4440729241	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4610627270	KU	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021 PO4410685403	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO5800812309	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4410085408	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO6481924020	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4439526015	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4414885661	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5385708278	KU	5	35 BRO	SP	CRE	ED	TD	00:00.0
2021 PO5460208749	KU	6	30 BRO	SP	CRE	ED	TD	00:00.0
2021 PO4417285667-A	LGE	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6482123824	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4865813209	KU	2	50 BRO	SP	CRE	ED,ID	TD	00:00.0

2021	PO4250687356	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4417185735	LGE	1	55 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4416485742	LGE	1	55 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO5263905849	KU	2	40 BRO	SP	CRE	ED	TD	00:00.0
2021	PO5319433518	KU	6	30 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5306633605	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5439408338	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5500309277	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5510509251	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7079609374	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7141810199	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5429905245	KU	5	35 BRO	SP	CRE	ED	TD	00:00.0
2021	PO5288234794	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO6896309406	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5300302852	KU	2	55 BRO	SP	CRE	ED	TD	00:00.0
2021	PO4716012305	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4401285472	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4290687145	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO4289287148	LGE	2	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4289487149	LGE	2	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4290187152	LGE	1	55 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO4290187148	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO5272532631	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5276132731	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5746537479	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5579937198	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5692037295	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5661437191	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4327386870	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4327186867	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO5546636785A	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5692709995	KU	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4419385460	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4289987135	LGE	1	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4289987130	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4289787120	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4289687114	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO6923309621	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO6131321548	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6866209247	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO4732010798	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6975809526	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO4420185465	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4415685436	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4414685429	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4413885423	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4287287139	LGE	3	50 ACE	SP	CRE	HH,ID	TD	00:00.0
2021	PO5316134287	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO4293987170	LGE	1	50 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5424236195	KU	4	40 BRO	SP	CRE		T	00:00.0
2021	PO5406436188	KU	5	35 BRO	SP	CRE		T	00:00.0
2021	PO4398486027	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4534987946	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4533587913	LGE	4	40 BRO	SP	A	ED,ID,IP	BD	00:00.0

2021	PO4889485276	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4889785297	LGE	4	40 BRO	SP	A	ED,ID,IP	BD		00:00.0
2021	PO4535987930	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4534087905	LGE	4	35 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO4532987922	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO8258196890	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO4892485292	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4894285307	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021	PO4892585297	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021	PO4891685289	LGE	3	45 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4890885285	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4399386033	LGE	UNK	45 ACE	SP	A	ID	TD		00:00.0
2021	PO6702598419	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6696898306	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4400986045	LGE	4	30 ACE	SP	P	ID	TD		00:00.0
2021	PO5494506568	KU	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5488706593	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5482206474	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO6729998212	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6736098393	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6758598185	F	4	40 ACE	SP	P		V		00:00.0
2021	PO5486406340	KU	6	30 XXX	SP	CCA		V		00:00.0
2021	PO5476106364	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5470006251	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5472206125	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5463806137	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5456706005	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5385806814	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5396406094	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5421505829	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5438206532	F	5	35 XXX	SP	CRE		V		00:00.0
2021	PO5437306619	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5446906707	F	5	35 XXX	SP	CCA		V		00:00.0
2021	PO5452806824	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO5457806925	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6765798279	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6757098299	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6746398363	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO4896685316	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4895185311	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4400086033	LGE	4	30 ACE	SP	P	ID	TD		00:00.0
2021	PO4399786036	LGE	UNK	45 ACE	SP	P	ID	TD		00:00.0
2021	PO4400486041	F	4	35 ACE	SP	P		V		00:00.0
2021	PO6738798406	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO6727098474	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6720598512	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4898285322	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4898885323	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO6708398583	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6696698633	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4899785328	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4900885331	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO6774698522	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6778498591	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0

2021	PO6764998639	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6752798705	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO6740198761	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6728398839	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO8269096993	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO8282197118	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO8289597184	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD		00:00.0
2021	PO8308097281	F	6	30 XXX	SP	P		V		00:00.0
2021	PO8303897317	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8161695635	KU	4	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5454505054	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5455305848	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5486606056	F	5	35 XXX	SP	P		V		00:00.0
2021	PO5481606081	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5497206176	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5487206205	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5498706311	F	3	45 XXX	SP	CCA		V		00:00.0
2021	PO8247196787	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO8236396684	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO8225596579	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO8214696476	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8203996371	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8184396185	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8191496280	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8193796275	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8603300026	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO8574199546	KU	5	35 XXX	SP	S		V		00:00.0
2021	PO6272401029	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6275401065	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6277501097	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6281301137	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO6022595706	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4393685991	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4394785998	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO5491306324	F	4	40 XXX	SP	CCA		V		00:00.0
2021	PO5492906381	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5494506461	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5500006606	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5497106738	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5490406838	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5484606814	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4529087934	LGE	4	40 BRO	SP	P		V		00:00.0
2021	PO4528587942	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021	PO4527987951	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4887385261	LGE	3	45 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4888185268	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4887685284	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6236501040	KU	6	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO6240401116	KU	5	35 ACE	SP	CCA	ED,ID	TD		00:00.0
2021	PO6258501052	KU	6	30 ACE	SP	CCA	ED,ID	TD		00:00.0
2021	PO4395486003	LGE	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021	PO2395191632	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4530687907	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO6717897949	F	4	40 ACE	SP	P		V		00:00.0

2021	PO6706098008	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO6694598068	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6682098126	F	4	40 ACE	SP	P		V		00:00.0
2021	PO6666898202	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4359285899	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4364985866	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4363785866	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021	PO4363585877	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4914785249	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4915185252	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4910985230	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4910985237	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4912585229	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4913185229	F	4	40 BRO	SP	A		V		00:00.0
2021	PO4914185207	F	4	30 BRO	SP	CCA		V		00:00.0
2021	PO4914985215	F	4	30 BRO	SP	A		V		00:00.0
2021	PO4914185221	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4914385224	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4916285208	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4369385871	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4370585877	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO8318897611	KU	5	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO8334597697	KU	4	40 XXX	SP	S		V		00:00.0
2021	PO6758296967	KU	3	40 ACE	SP	P		V		00:00.0
2021	PO6737396893	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6729296785	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4369985963	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4883785158	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4370885976	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4371685989	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4885185164	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021	PO4885285179	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4885485187	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4886085186	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4509387639	F	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4510587622	F	4	40 BRO	SP	A		V		00:00.0
2021	PO4511687606	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4513487582	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4513387646	F	3	45 BRO	SP	CCA		V		00:00.0
2021	PO2198089226	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4535787876	LGE	4	30 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4536587880	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4528387864	F	6	25 BRO	SP	P		V		00:00.0
2021	PO4522587926	F	4	35 BRO	SP	P		V		00:00.0
2021	PO4372385999	LGE	4	40 ACE	SP	CRE	ED	V		00:00.0
2021	PO4372886006	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4372386008	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4885785199	F	3	45 BRO	SP	CRE		V		00:00.0
2021	PO4886285217	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4886685212	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD		00:00.0
2021	PO4374086012	LGE	UNK	25 ACE	SP	CRE	ED	X	PX	00:00.0
2021	PO4887285232	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4886785239	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4373486016	F	4	40 ACE	SP	CRE		V		00:00.0

2021 PO4374086024	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4378985903	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO5601205926	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5606705908	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5638005942	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5623506095	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5644806116	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5623206591	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5627306715	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6464100323	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6493700213	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO6499800325	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO6504700428	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO6243301677	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6242101682	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6250001805	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6249001783	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1 00:00.0
2021 PO6248201836	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8118793828	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8100193903	KU	4	40 XXX	SP	P	ED,ID,IP	TD	00:00.0
2021 PO8090993941	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8100994182A	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6661099265	KU	4	30 ACE	SP	CRE		V	00:00.0
2021 PO6655999156	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6650899041	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6607897986	KU	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6599198117	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO6601498080	F	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1 00:00.0
2021 PO6607398118	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6611197863	F	3	45 ACE	SP	P		V	00:00.0
2021 PO6608497796	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5612606278	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4878685069	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR 00:00.0
2021 PO4878485113	LGE	4	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO6701999342	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6686499432	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6671799403	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6667299297	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6675599498	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX 00:00.0
2021 PO8119294614	KU	4	35 XXX	SP	CRE		BX	RP1 00:00.0
2021 PO8127994827	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO8143494981	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8135795012	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8144595220	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8153695496	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8155095475	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8157995808	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO4382085908	F	UNK	45 ACE	SP	P		V	00:00.0
2021 PO4900685362	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4901585348	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4902285337	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4382385902	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5029485123	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4381385924	F	4	40 ACE	SP	CRE		V	00:00.0



2021	PO7420864528	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021	PO4523187689	F	4	40 BRO	SP	CRE			V	00:00.0
2021	PO4520987677	F	4	40 BRO	SP	CRE			V	00:00.0
2021	PO4523087630	F	4	40 BRO	SP	P			V	00:00.0
2021	PO4513587941	F	4	40 BRO	SP	A			V	00:00.0
2021	PO2429991201	LGE	4	30 BRO	SP	CRE			V	00:00.0
2021	PO4526187865	F	4	40 BRO	SP	A			V	00:00.0
2021	PO4527487873	F	4	40 BRO	SP	P			V	00:00.0
2021	PO8367796915	KU	4	40 XXX	SP	S			V	00:00.0
2021	PO8360097067	KU	4	40 XXX	SP	S			V	00:00.0
2021	PO8357697111	KU	4	40 XXX	SP	S			V	00:00.0
2021	PO8350497254	KU	4	40 XXX	SP	S			V	00:00.0
2021	PO8082993753	KU	4	40 XXX	SP	CRE	ED,ID		TD	00:00.0
2021	PO8077493618	KU	4	40 XXX	SP	CRE	ED,ID,IP		TD	00:00.0
2021	PO8067893387	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SR		TD	00:00.0
2021	PO5597305808	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5592905689	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5616505667	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5614405607	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5624305576	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO6472800462	F	4	40 ACE	SP	P			V	00:00.0
2021	PO5629305694	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5627905804	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5630505863	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5625005814	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5615006348	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5618806462	F	4	40 XXX	SP	CCA			V	00:00.0
2021	PO5628906753	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5651006275	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5657406440	F	4	40 XXX	SP	P			V	00:00.0
2021	PO5641406302	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5649206518	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5653306619	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO5664006591	F	4	40 XXX	SP	CRE			V	00:00.0
2021	PO8451785883	KU	4	40 ACE	SP	CRE	ED,ID		BD	00:00.0
2021	PO4466387777	LGE	4	40 BRO	SP	CRE	ID,IP		BD	00:00.0
2021	PO4465787785	LGE	4	40 BRO	SP	A	ED,ID,IP		TD	00:00.0
2021	PO4465287794	LGE	4	40 BRO	SP	A	ID,IP		BD	00:00.0
2021	PO4464787802	LGE	4	40 BRO	SP	A	ED,ID,IP		TD	00:00.0
2021	PO4050386351	LGE	4	35 ACE	SP	CCA			V	00:00.0
2021	PO8450785912	KU	3	45 ACE	SP	CRE	ED,ID		TD	00:00.0
2021	PO4050786360	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO4049586373	LGE	6	25 ACE	SP	A			V	00:00.0
2021	PO4053886475	LGE	4	40 ACE	SP	CCA			V	00:00.0
2021	PO4051386463	LGE	4	40 ACE	SP	CCA			V	00:00.0
2021	PO8444985902	KU	3	45 ACE	SP	CRE	ED,ID		TD	00:00.0
2021	PO8432285838	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB		BX	PX 00:00.0
2021	PO4470287875	LGE	1	60 BRO	SP	CRE	ID,IP		BD	00:00.0
2021	PO4468288350	LGE	4	55 ACE	SP	A	ED,ID		BD	00:00.0
2021	PO4468388346	LGE	4	40 ACE	SP	A	ED,ID		BD	00:00.0
2021	PO4469687859	LGE	4	30 BRO	SP	CRE	ID		BD	00:00.0
2021	PO4468688338	LGE	2	55 ACE	SP	A	ED,ID		TD	00:00.0
2021	PO4468988327	LGE	2	55 ACE	SP	A	ED,ID		TD	00:00.0
2021	PO4089686725	F	UNK	45 ACE	SP	CCA			V	00:00.0

2021 PO8521184228	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8501684270	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8482684310	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8450984345	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8464184348	F	4	40 ACE	SP	CRE	ED,ID	V	00:00.0
2021 PO4451687960	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4451087956	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4450387951	F	4	35 BRO	SP	A		V	00:00.0
2021 PO1781995717	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO8449684580	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO3985785680	LGE	4	45E ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO5008124787	KU	6	30 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4471388406	LGE	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO8594984456	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO5001724781	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO3986885694	LGE	4	45E ACE	SP	CRE	ED	BD	00:00.0
2021 PO5000324918	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO8613884637	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8614284870	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3968285666	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3969385660	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO3970685653	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4354216219	KU	1	70 BRN	SP	CCA		T	00:00.0
2021 PO4062316555	KU	3	45 BRN	SP	CCA		T	00:00.0
2021 PO4051116678	KU	3	45 BRN	SP	P	ED,ID,IP,MD	TD	00:00.0
2021 PO4468388438	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4051084622	F	4	30 BRO	SP	P		V	00:00.0
2021 PO4468188457	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8541785243	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8548985126	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8572585032	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8574785175	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8579185434	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3988085710	LGE	4	45E ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4467488453	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8452586114	F	4	40 ACE	SP	P		V	00:00.0
2021 PO5005808076	F	2	50 BRN	SP	S		V	00:00.0
2021 PO5016807992	F	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5025607988	F	4	40 BRN	SP	P		V	00:00.0
2021 PO5036307888	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO5034207906	F	4	40 BRN	SP	P		V	00:00.0
2021 PO5023007813	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO5043107825A	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5043107825	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5052507738	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5063307637	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8579984632	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8577684669	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8574684723	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3973285639	F	4	30E ACE	SP	A		V	00:00.0
2021 PO4471488427	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4470388421	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4974024839	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4976324590	KU	4	45 BRO	SP	CRE	ED	BD	00:00.0

2021 PO8567484849	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3975285630	F	4	40E ACE	SP	CRE		V	00:00.0
2021 PO3975285632	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO3976785622	F	4	35E ACE	SP	CRE		V	00:00.0
2021 PO3971985616	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3973085635	F	4	30 ACE	SP	A		V	00:00.0
2021 PO3965485676	F	4	30 ACE	SP	A		V	00:00.0
2021 PO4469388415	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8560184973	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8546184895	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4469988427	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4978024370	KU	2	45 BRO	SP	CRE	ED	BD	00:00.0
2021 A4978024370	KU	3	50 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4969624441	KU	2	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO8539785510	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4977524461	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4971324490	KU	6	30 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4968424529	KU	2	45 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4975224709	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4965224767	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4967424824	KU	6	30 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4961824900	KU	4	40 BRO	SP	CRE		T	00:00.0
2021 PO4469088441	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4469888446	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8524785429a	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8524785429	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8531585353	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4468488450	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4972824961	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5210613020	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5200413201	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5216714219	KU	4	40 BRN	ST	CRE		V	00:00.0
2021 PO5197214126	KU	2	50 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5160713954	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 PO5162713915	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5173613696	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5189613441	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5286212744	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5277012801	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5277112590	KU	3	50 XXX	SP	CRE	ID	X	PX 00:00.0
2021 PO5276712631	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4086316613	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5019608275	F	4	40 BRN	SP	P		V	00:00.0
2021 PO5024208343	F	4	40 BRN	SP	P		V	00:00.0
2021 PO5030808441	F	4	40 BRN	SP	P		V	00:00.0
2021 PO5032208487	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5017108600	F	3	45 BRN	SP	S		V	00:00.0
2021 PO5007808669	F	4	40 BRN	SP	P		V	00:00.0
2021 PO5001108803	F	4	40 BRN	SP	S		V	00:00.0
2021 PO4993908771	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4998408738	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4993008632	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5042808648	KU	2	50 BRN	SP	S		V	00:00.0
2021 PO5000708920	KU	3	45 BRN	SP	S		V	00:00.0

2021 PO4961208779	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4980408693	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4971308732	F	4	40 BRN	SP	S		V		00:00.0
2021 PO4950308761	F	6	30 BRN	SP	CRE		V		00:00.0
2021 PO4959608898	F	4	40 BRN	SP	S		V		00:00.0
2021 PO4951708821	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4943108862	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4934208904	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4915808858	F	4	40 BRN	SP	CRE	ED,HH,ID	BX	RP2	00:00.0
2021 PO4868108846	F	6	30 BRN	SP	S		V		00:00.0
2021 PO4092316758	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4095884116	LGE	4	45 ACE	SP	CCA		V		00:00.0
2021 PO4104284044	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4103984047	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4104884041	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4105284044	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4106516933	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4122716874	KU	2	45 BRN	SP	CCA		T		00:00.0
2021 PO4175916964	KU	6	30 BRN	ST	CCA		V		00:00.0
2021 PO4171916954	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4261016575	KU	3	40 BRN	SP	CRE		T		00:00.0
2021 PO4245716576	KU	3	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4243616647	KU	3	45 BRN	SP	CCA		T		00:00.0
2021 PO4238116669	KU	3	45 BRN	SP	CRE		T		00:00.0
2021 PO4219716748	KU	3	50 BRN	SP	CCA		T		00:00.0
2021 PO4156416751	KU	3	45 BRN	SP	CCA		T		00:00.0
2021 PO4138916815	KU	3	45 BRN	SP	CCA		T		00:00.0
2021 PO4174316679a	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4180316642	KU	3	50 BRN	SP	CCA		V		00:00.0
2021 PO4174316679	KU	3	50 BRN	SP	CCA		V		00:00.0
2021 PO8497483786	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8497083661	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8496483471	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8461683325	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8462183500	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8462783708	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8463283919	F	3	45 ACE	SP	CRE		V		00:00.0
2021 PO8449384144	KU	6	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8459284005	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8460784102	KU	6	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8456484056	KU	6	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8565284283	KU	6	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8577584089	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8558484141	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8555584200	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4270216538	KU	3	45 BRN	SP	CCA		T		00:00.0
2021 PO8540684186	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8548784362	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8542384481	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8534284631	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8532184676	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8526184785	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO2851387918	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4042186259	F	3	45 ACE	SP	CCA		V		00:00.0

2021 PO4042886265	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4041686255	F	4	45 ACE	SP	CRE		V		00:00.0
2021 PO4039886237	F	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4038686225	F	4	45 ACE	SP	CCA		V		00:00.0
2021 PO4038086220	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4926025387	KU	4	30 BRO	SP	CRE	ED		BD	00:00.0
2021 PO4926625325	KU	5	35 BRO	SP	CRE	ID		BD	00:00.0
2021 A4926025387	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4925125469	KU	5	35 BRO	SP	CRE	ID		BD	00:00.0
2021 PO2843387629	KU	4	40 BRO	SP	CRE	ED,IP,SRS		TD	00:00.0
2021 PO2818287694	KU	4	40 BRO	SP	CRE	ED,IP,SRS		TD	00:00.0
2021 PO2872587933	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4037086209	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4036286202	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4034786188	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4034086180	F	4	45 ACE	SP	CRE		V		00:00.0
2021 PO4034984493	F	3	45 BRO	SP	CRE		V		00:00.0
2021 PO4033286173	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4042384620	F	3	45 BRO	SP	CRE		V		00:00.0
2021 PO4043584619	F	4	30 BRO	SP	CRE		V		00:00.0
2021 PO4044684626	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4044984622	F	4	30 BRO	SP	P		V		00:00.0
2021 PO4046084626	F	4	40 BRO	SP	P		V		00:00.0
2021 PO4032386165	F	4	30 ACE	SP	CCA		V		00:00.0
2021 PO5006024350	KU	2	40 BRO	SP	CRE	ED,ID		BD	00:00.0
2021 PO8594484041	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8613883986	F	3	45 ACE	SP	P		V		00:00.0
2021 PO4872008753	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4878508727	KU	5	35 BRN	SP	S		V		00:00.0
2021 PO4888908688	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO4908808544	F	4	40 XXX	SP	S		V		00:00.0
2021 PO8626783953	F	3	50 ACE	SP	P		V		00:00.0
2021 PO5037924638	KU	4	40 BRO	SP	CRE	ED,ID,RB		BX PX	00:00.0
2021 PO2675488059	KU	5	35 BRO	SP	CRE	ED,IP,SRS		TD	00:00.0
2021 PO2743987880	KU	4	40 BRO	SP	A	ED,IP,SRS		TD	00:00.0
2021 PO5024224649	KU	4	40 BRO	SP	CRE	ED,ID		BD	00:00.0
2021 PO2781787987	KU	6	30 BRO	SP	CRE	ED,IP,SRS		TD	00:00.0
2021 PO2789887764	KU	4	40 BRO	SP	CRE	ED,IP,SRS		TD	00:00.0
2021 PO2763587829	KU	4	40 BRO	SP	CRE	ED,IP,SRS		TD	00:00.0
2021 PO4027586119	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO5004624434	KU	3	45 BRO	SP	CRE	ED		BD	00:00.0
2021 PO4279716498	KU	3	40 BRN	SP	CRE	ED,ID,SRS		TD	00:00.0
2021 PO5003524566	KU	4	40 BRO	SP	CRE		T		00:00.0
2021 PO5002624686	KU	4	40 BRO	SP	CRE	ED,ID		BD	00:00.0
2021 PO5006024667	KU	5	35 BRO	SP	CRE	ED		BD	00:00.0
2021 PO5017924714	KU	6	30 BRO	SP	CRE	ED		BD	00:00.0
2021 PO4463188397	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4474388402	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4462188393	LGE	3	45 ACE	SP	A	ED,ID		BD	00:00.0
2021 PO4471188389	LGE	3	45 ACE	SP	CRE	ED,ID		BD	00:00.0
2021 PO4930108563	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4918008506	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4929008461	F	5	35 XXX	SP	CRE		V		00:00.0
2021 PO4943108460	F	4	40 XXX	SP	CRE		VX	RP3	00:00.0

2021 PO4941008409	F	4	40 XXX	SP	P		V			00:00.0
2021 PO4961308305	F	4	40 XXX	SP	CCA		V			00:00.0
2021 PO4946208380	F	4	40 XXX	SP	CCA		V			00:00.0
2021 PO4954708339	F	4	40 XXX	SP	CCA		V			00:00.0
2021 PO4959908456	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO4968608269	F	4	40 BRN	SP	CCA		V			00:00.0
2021 PO4974808344	F	4	40 BRN	SP	S		V			00:00.0
2021 PO4982808263	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4980308211	F	4	40 BRN	SP	CCA		V			00:00.0
2021 PO8430687620	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO8428387508	F	4	40 ACE	SP	P		V			00:00.0
2021 PO4297616423	KU	6	45 BRN	SP	CRE	ED,ID		TD		00:00.0
2021 PO5009624663	KU	4	40 BRO	SP	CRE	ED,EP,ID		BX	RP2	00:00.0
2021 PO8416987314	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO2725787928	KU	4	40 BRO	SP	CRE	ED,IP,SRS		TD		00:00.0
2021 PO8424987292	F	4	40 ACE	SP	P		V			00:00.0
2021 PO8439687251	F	4	40 ACE	SP	P		V			00:00.0
2021 PO3997283910	F	4	40 BRO	SP	A		V			00:00.0
2021 PO3996183915	F	4	40 BRO	SP	A		V			00:00.0
2021 PO3995083920	F	3	45 BRO	SP	CRE		V			00:00.0
2021 PO3997184243	LGE	4	35 ACE	SP	CCA	ED,ID		TD		00:00.0
2021 PO3991983913	F	4	30 BRO	SP	CRE		V			00:00.0
2021 PO3996184232	LGE	4	40 ACE	SP	CRE	ED,ID		BD		00:00.0
2021 PO3996584225	LGE	4	30 ACE	SP	A	ED,ID		BD		00:00.0
2021 PO3997784231	LGE	4	40 ACE	SP	P	ED,ID		TD		00:00.0
2021 PO1832867763	KU	4	40 BRN	SP	CRE	ED,IP,MD,SRS		TD		00:00.0
2021 PO1847068003	KU	4	40 BRN	SP	CRE	ED,IP,SRS		TD		00:00.0
2021 PO1800067774	KU	4	40 BRN	SP	CRE	ED,MD		TD		00:00.0
2021 PO1750866676	KU	5	35 BRN	SP	CRE	ED,IP,SRS		TD		00:00.0
2021 PO1783866983	KU	5	35 BRN	SP	CRE	ED,IP,SRS		TD		00:00.0
2021 PO4939237461	KU	3	45 BRO	SP	CCA		V			00:00.0
2021 PO7562569926	F	3	50 ACE	SP	P		V			00:00.0
2021 PO7575069997	KU	2	45 ACE	SP	CCA		V			00:00.0
2021 PO4038384736	F	4	35 BRN	SP	CRE		V			00:00.0
2021 PO4000784090	LGE	4	30 ACE	SP	A	ED,ID		BD		00:00.0
2021 PO5782124671	KU	5	35 BRO	SP	CRE		B			00:00.0
2021 PO3997884092	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021 PO7593970103	KU	2	45 ACE	SP	CCA		V			00:00.0
2021 PO7616270152	KU	2	45 ACE	SP	CCA		V			00:00.0
2021 PO3997884101	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021 PO7638470203	KU	2	45 ACE	SP	CCA		V			00:00.0
2021 PO7660970255	KU	2	45 ACE	SP	CCA		V			00:00.0
2021 PO7658270403	KU	2	45 ACE	SP	CCA		V			00:00.0
2021 PO7655570570	KU	4	40 ACE	SP	CCA		V			00:00.0
2021 PO7569169715	F	4	40 ACE	SP	P		V			00:00.0
2021 PO7590169568	F	4	40 ACE	SP	P		V			00:00.0
2021 PO3989884128	LGE	4	35 ACE	SP	P	ED,ID		BD		00:00.0
2021 PO4534588091	LGE	4	40 BRN	SP	CRE	ED,ID,IP		BD		00:00.0
2021 PO4534488096	LGE	4	30 BRN	SP	CCA	ED,ID		BD		00:00.0
2021 PO7596669331	F	4	40 ACE	SP	P		V			00:00.0
2021 PO7603469100	F	2	45 ACE	SP	P		V			00:00.0
2021 PO4050384399	LGE	4	40 BRO	SP	CRE		V			00:00.0
2021 PO3988784130	LGE	4	35 ACE	SP	P	ED,ID		TD		00:00.0
2021 PO3988884127	F	4	35 ACE	SP	P	ED,ID		V		00:00.0

2021	PO5789524748	KU	5	35 BRO	SP	CRE			B	00:00.0
2021	PO4536288111	LGE	2	60 BRN	SP	A	ED,HH,ID,RB		BD	00:00.0
2021	PO4535888105	LGE	4	40 BRN	SP	CRE	ID		BD	00:00.0
2021	PO4535588097	LGE	4	40 BRN	SP	A	ED,HH,ID,RB		BX RR	00:00.0
2021	PO4535388096	LGE	3	45 BRN	SP	CCA			V	00:00.0
2021	PO4536688091	LGE	4	40 BRN	SP	A	ED,HH,ID		BD	00:00.0
2021	PO4536088101	LGE	2	55 BRN	SP	CCA			V	00:00.0
2021	PO5806124902	KU	3	45 ACE	SP	CCA			V	00:00.0
2021	PO5811124951	KU	4	40 ACE	SP	CCA			V	00:00.0
2021	PO5798925985	KU	3	50 ACE	SP	CRE			B	00:00.0
2021	PO5807225897	KU	2	50 ACE	SP	CCA			V	00:00.0
2021	PO5800825881	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO5791225983	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO5780326103	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO5774226164	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO5776026235	KU	5	35 ACE	SP	CRE			B	00:00.0
2021	PO3983084098	F	4	40 ACE	SP	CCA			V	00:00.0
2021	PO4095284150	LGE	4	35 BRO	SP	P	ED,ID		TD	00:00.0
2021	PO3982384105	F	4	40 ACE	SP	CRE	ED		V	00:00.0
2021	PO3982184098	F	4	35 ACE	SP	CCA			V	00:00.0
2021	PO3983584030	F	4	45 ACE	SP	CRE	ED		V	00:00.0
2021	PO4501388021	LGE	3	45 BRN	SP	P	ID		TD	00:00.0
2021	PO4501388016	LGE	1	50 BRN	SP	CCA			V	00:00.0
2021	PO4499688027	F	4	40 BRN	SP	CRE			V	00:00.0
2021	PO4501588041	F	4	40 BRN	SP	CRE			V	00:00.0
2021	PO4001083834	F	4	40 BRO	SP	A			V	00:00.0
2021	PO4002383833	F	4	40 BRO	SP	A			V	00:00.0
2021	PO3999883834	F	4	40 BRO	SP	CRE			V	00:00.0
2021	PO7761754724	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4056484275	F	4	40 BRO	SP	P			V	00:00.0
2021	PO4054284284	F	3	45 BRO	SP	CCA			V	00:00.0
2021	PO4052584291	F	4	40 BRO	SP	P			V	00:00.0
2021	PO4050384299	F	4	40 BRO	SP	P			V	00:00.0
2021	PO4054284281	LGE	4	30 BRO	UN	CRE			V	00:00.0
2021	PO4050084301	LGE	UNK	25 BRO	SP	CRE			V	00:00.0
2021	PO4046384315	LGE	4	40 BRO	SP	CRE	IP		B	00:00.0
2021	PO3983684041	F	3	45 ACE	SP	CCA			V	00:00.0
2021	PO3983784054	F	4	40 ACE	SP	CRE	ED		V	00:00.0
2021	PO5764026279	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO577226271	KU	3	50 ACE	SP	CCA			V	00:00.0
2021	PO4030284122	F	1	65 BRN	SP	CCA			V	00:00.0
2021	PO4037884751	LGE	4	30 BRN	SP	CRE	ED,ID		BD	00:00.0
2021	PO4037784743	LGE	4	30 BRN	SP	A	ED,ID		BD	00:00.0
2021	PO4026584622	F	4	30 BRN	SP	A			V	00:00.0
2021	PO4028784718	F	7	25 BRN	SP	CRE			V	00:00.0
2021	PO4028584709	F	4	40 BRN	SP	CRE			V	00:00.0
2021	PO4026884682	F	7	25 BRN	SP	CRE			V	00:00.0
2021	PO4028784693	F	3	45 BRN	SP	CCA			V	00:00.0
2021	PO4032184672	F	4	40 BRN	SP	P	ED,EP,ID,RB		VX PX	00:00.0
2021	PO4033684669	F	4	40 BRN	SP	CRE			V	00:00.0
2021	PO4035384666	LGE	4	40 BRN	SP	CRE			V	00:00.0
2021	PO4036684664	F	4	40 BRN	SP	A			V	00:00.0
2021	PO4037184662	LGE	7	25 BRN	SP	CCA			V	00:00.0
2021	PO4036384667	LGE	7	25 BRN	SP	CCA			V	00:00.0

2021 PO4036484673	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4037184697	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4036984692	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4037184699	LGE	4	40 BRN	SP	CRE	ED,EP,HH,ID	BX PX	00:00.0
2021 PO4003184664	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4002484657	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4064784313	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4063184303	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4061084290	F	3	45 BRO	SP	P		V	00:00.0
2021 PO7766554655	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3992483847	F	5	25 BRO	SP	CRE		V	00:00.0
2021 PO3992483838	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3993683838	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3994883837	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3996083836	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3997283836	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4059284281	F	3	45 BRO	SP	P		V	00:00.0
2021 PO4057584262	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4057584269	F	3	45 BRO	SP	P		V	00:00.0
2021 PO9732198276	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9776298391	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9806099069	KU	3	45 XXX	SP	CRE	ID	V	00:00.0
2021 PO9785199057A	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO0809299630	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO7265869283	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5822625057	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO5810025002	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO5815724992	KU	4	40 ACE	UN	CCA		V	00:00.0
2021 PO4096084674	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO3983384134	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO5827625084	KU	4	40 ACE	SP	CRE		B	00:00.0
2021 PO5832725031	KU	5	35 ACE	SP	CRE		B	00:00.0
2021 PO7014953017	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO3988084130	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4536188085	LGE	4	35 BRN	SP	A	ID	BD	00:00.0
2021 PO4536788089	LGE	1	55 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4537288082	LGE	1	55 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4042784314	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4537988093	LGE	1	50 BRN	SP	P		V	00:00.0
2021 PO4540988095	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4541488087	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4539288061	LGE	4	35 BRN	SP	P	ID	BD	00:00.0
2021 PO4539588072	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4539088069	F	7	25 BRN	SP	CCA		V	00:00.0
2021 PO4537788066	F	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4495688013	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4042884333	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4042684330	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4043084335	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4053084251	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4054684260	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4090584126	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4092884100	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4091584104	LGE	3	45 BRO	SP	CCA		V	00:00.0



2021 PO4088284145	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0808299602	KU	4	45 BRO	SP	CCA		V	00:00.0	
2021 PO0547100321	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO1158598823	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO1103198959	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO0747099722	KU	4	45 KOP	SP	CRE	ID	T	00:00.0	
2021 PO0662500289	KU	6	35 KOP	SP	CCA		V	00:00.0	
2021 PO0680399875	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO0645899958	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO0613700035	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO0583900101	KU	4	40 KOP	SP	CRE		V	00:00.0	
2021 PO1023599120	KU	4	35 KOP	SP	CCA		V	00:00.0	
2021 PO9945081596	KU	4	40 OTH	SP	CRE	ED,IP,MD,SRS	TD	00:00.0	
2021 PO9905681771	KU	4	40 OTH	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021 PO3986384132	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO9785199057	KU	3	50 XXX	SP	CCA		V	00:00.0	
2021 PO9801598680	KU	4	45 XXX	SP	CCA		V	00:00.0	
2021 PO9769398478	KU	3	45 XXX	SP	CCA		V	00:00.0	
2021 PO4057484270	F	3	45 BRO	SP	P		V	00:00.0	
2021 PO4052984242	F	3	45 BRO	SP	CRE		V	00:00.0	
2021 PO4056684265	F	3	45 BRO	SP	P		V	00:00.0	
2021 PO4054884255	F	3	55 BRO	SP	P		V	00:00.0	
2021 PO4051684233	F	3	45 BRO	SP	CRE		V	00:00.0	
2021 PO4050284223	F	3	45 BRO	SP	P		V	00:00.0	
2021 PO4048884214	F	3	45 BRO	SP	CRE		V	00:00.0	
2021 PO3998483835	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO3989884306	F	4	40 ACE	SP	CRE	ED	V	00:00.0	
2021 PO1063699019	KU	4	35 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO3989884297	F	4	40 ACE	SP	A	ED	V	00:00.0	
2021 PO3989784285	F	4	40 ACE	SP	A	ED	V	00:00.0	
2021 PO3998683869	F	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3997483870	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO5752426371	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5753126377	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5753826384	KU	3	45 ACE	SP	CRE		B	00:00.0	
2021 PO5756226362	F	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO5745726374	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO5749326421	KU	4	40 ACE	SP	CRE	ED,ID	BX	PX	00:00.0
2021 PO3996283872	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO3995083873	F	2	45 BRO	SP	CCA		V	00:00.0	
2021 PO3989684275	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO0984099212	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO1209998299	KU	5	35 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO3989284228	F	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO3993883874	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4054684126	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4037684137	F	UNK	45 BRO	UN	CRE		V	00:00.0	
2021 PO3989384238	F	4	40 ACE	SP	CRE	ED	V	00:00.0	
2021 PO9983780430	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO0001280097	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO0009984092	KU	3	45 BRN	SP	CCA	ED,MD	T	00:00.0	
2021 PO3998983882	F	4	30 BRO	SP	CRE		V	00:00.0	
2021 PO3989184209	F	3	45 ACE	SP	P	ED	V	00:00.0	
2021 PO5742227179	KU	6	30 ACE	SP	CRE		B	00:00.0	

2021 PO5733727248	KU	4	40 ACE	SP	CRE		B		00:00.0
2021 PO5739227311	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5728627154	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3989184217	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3988584215	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO5715927207	KU	3	45 ACE	SP	CRE		T		00:00.0
2021 PO3988484208	F	4	30 ACE	SP	A	ED	V		00:00.0
2021 PO4050684169	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO7641353831	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4047384204	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4046284187	F	4	30 BRO	SP	CRE		V		00:00.0
2021 PO3992583866	LGE	4	30 BRO	SP	A	ED,ID,RB	X	RP1	00:00.0
2021 PO4046084195	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4045284190	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4043884180	F	4	45 BRO	SP	CRE	ED,EP,ID,IP	VX	PX	00:00.0
2021 PO4042784172	F	4	40E BRO	SP	CRE		V		00:00.0
2021 PO4042484169	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4041484163	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4039584151	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4038584142	F	3	45 BRO	SP	P		V		00:00.0
2021 PO7548653216	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO7546653242	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4036684129	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4035884124	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4034784117	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4032884104	F	1	60 BRO	SP	CCA		V		00:00.0
2021 PO3992783875	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO9049095069	KU	6	30 XXX	SP	CRE		V		00:00.0
2021 PO0880899977	KU	5	35 XXX	SP	CRE	ED,ID	X	RP2	00:00.0
2021 PO3991583876	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO3990884253	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO3990283877	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1241098451	KU	3	40 KOP	SP	CRE	ID	TD		00:00.0
2021 PO1257098522	F	4	40 KOP	SP	CRE	ID	BX	RP1	00:00.0
2021 PO1276498271	KU	4	40 KOP	SP	CRE	ID	TD		00:00.0
2021 PO5729927182	KU	3	45 ACE	UN	CCA		V		00:00.0
2021 PO3999883851	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO5722927049	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5710527058	KU	4	40 ACE	SP	CRE		B		00:00.0
2021 PO5718427074	KU	6	30 ACE	SP	CRE		B		00:00.0
2021 PO5724627087	KU	3	45 ACE	UN	CCA		V		00:00.0
2021 PV3992084253	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4000783862	F	4	30 BRO	SP	CCA		V		00:00.0
2021 PO3999883863	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO0128873288	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4000183874	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO5711326912	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO5714526905	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5708626844	KU	5	35 ACE	SP	CCA		V		00:00.0
2021 PO5713626833	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO5716626833	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO5718826793	KU	3	40 BRN	SP	CRE		B		00:00.0
2021 PO5718826793	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5718526798	KU	2	45 BRN	SP	CCA		V		00:00.0

2021	PO5367339700	KU	4	40 KOP	SP	CRE			T	00:00.0
2021	PO5353539663	KU	5	35 KOP	SP	CRE			T	00:00.0
2021	PO4415285444	LGE	4	40 BRO	SP	CCA		ED	T	00:00.0
2021	PO5366938193	KU	4	40 XXX	SP	P		ED,ID	T	00:00.0
2021	PO5310234912	KU	6	30 XXX	SP	CRE			T	00:00.0
2021	PO5419935810	KU	4	45 BRN	SP	CRE			T	00:00.0
2021	PO5395835738	KU	3	45 BRN	SP	CRE			T	00:00.0
2021	PO5364336054	KU	4	40 BRN	SP	CRE			T	00:00.0
2021	PO5335834750	KU	4	45 XXX	SP	CRE			T	00:00.0
2021	PO5288234794A	KU	2	25 XXX	SP	CRE			T	00:00.0
2021	PO5437008344	KU	4	40 XXX	SP	S		ED,MD,SRC	T	00:00.0
2021	PO5469509739	KU	4	40 XXX	SP	S		ED,SRC	T	00:00.0
2021	PO5270743026	KU	4	40 BRO	SP	CRE			T	00:00.0
2021	PO5354528461	KU	4	40 BRO	SP	CRE			T	00:00.0
2021	PO5385228629	KU	4	40 BRO	SP	CRE			T	00:00.0
2021	PO1325269494	LGE	3	50 BRO	SP	CCA		ED	T	00:00.0
2021	PO4085616823	KU	4	40 BRN	SP	CCA		ED	T	00:00.0
2021	PO5352735344	KU	4	40 BRN	SP	CRE			T	00:00.0
2021	PO5392139342	KU	4	40 KOP	SP	CRE			T	00:00.0
2021	PO5361528828	KU	6	30 BRO	SP	CRE			T	00:00.0
2021	PO5474408028	KU	3	45 XXX	SP	S		ED,MD,SRC	T	00:00.0
2021	PO5389028271	KU	4	40 BRO	SP	CRE			T	00:00.0
2021	PO5379128152	KU	5	35 BRO	SP	CRE			T	00:00.0
2021	PO4414085436	LGE	4	40 BRO	SP	CCA		ED	T	00:00.0
2021	PO5276443318	KU	4	40 BRO	SP	CRE			T	00:00.0
2021	PO4401585420	F	4	40 ACE	SP	A			V	00:00.0
2021	PO4400585433	F	4	40 ACE	SP	CCA			V	00:00.0
2021	PO4402485547	LGE	4	40 BRO	SP	CRE			V	00:00.0
2021	PO4403385534	F	4	40 BRO	SP	A			V	00:00.0
2021	PO4400985439	F	3	40 ACE	SP	P		ED	V	00:00.0
2021	PO4394385496	F	4	30 ACE	SP	CRE			V	00:00.0
2021	PO4399585439	F	4	30 ACE	SP	CCA			V	00:00.0
2021	PO4399285442	F	4	30 ACE	SP	CRE			V	00:00.0
2021	PO4400185442	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO7828390814	KU	6	30 XXX	SP	CRE			V	00:00.0
2021	PO6086898818	KU	2	50 ACE	SP	CCA			V	00:00.0
2021	PO5820105192	KU	4	40 XXX	SP	CCA			V	00:00.0
2021	PO6343899358	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO6348499272	KU	4	40 ACE	SP	P			V	00:00.0
2021	PO4404985376	F	4	40 ACE	SP	A		ED	V	00:00.0
2021	PO4404385383	F	UNK	45 ACE	SP	A			V	00:00.0
2021	PO4403585394	F	4	40 ACE	SP	CCA			V	00:00.0
2021	PO6338799343	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO6340399386	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO6213000519	F	4	40 ACE	SP	CRE			V	00:00.0
2021	PO1484967145	LGE	4	35 ACE	SP	CCA			V	00:00.0
2021	PO6088298888	KU	2	50 ACE	SP	CCA			V	00:00.0
2021	PO6084998904	KU	1	40 ACE	SP	CCA			V	00:00.0
2021	PO6084098910	KU	1	40 ACE	SP	CCA			V	00:00.0
2021	PO6082498917	KU	1	40 ACE	SP	CCA			V	00:00.0
2021	PO6079698933	KU	1	40 ACE	SP	CCA			V	00:00.0
2021	PO6076398979a	KU	4	45 ACE	SP	CCA			V	00:00.0
2021	PO6076398979	KU	4	45 ACE	SP	CCA			V	00:00.0
2021	PO6079998933	KU	4	45 ACE	ST	P			V	00:00.0

2021 PO6083198914	KU	2	100 ACE	ST	CRE		V			00:00.0
2021 PO6084798904	KU	4	45 ACE	SP	CCA		V			00:00.0
2021 PO6085498912	KU	2	45 ACE	SP	CCA		V			00:00.0
2021 PO4464786101	F	3	55 ACE	SP	P		V			00:00.0
2021 PO4464986124	F	2	55 ACE	SP	P		V			00:00.0
2021 PO4464986117	F	2	55 ACE	SP	P		V			00:00.0
2021 PO4462986037	LGE	4	40 ACE	SP	CCA		V			00:00.0
2021 PO4465186140	F	2	55 ACE	SP	P		V			00:00.0
2021 PO4465186142	F	1	55 ACE	SP	CCA		V			00:00.0
2021 PO4464085975	F	3	45 ACE	SP	CCA		V			00:00.0
2021 PO6173600744	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO6181000701	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO6187800662	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO6194800621	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO6201800583	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO6207800549	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4435485489	LGE	UNK	55 ACE	SP	CRE		V			00:00.0
2021 PO6161400812	F	4	40 ACE	SP	CRE		V			00:00.0
2021 PO4409185578	LGE	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4408685586	F	4	35 BRO	SP	CRE		V			00:00.0
2021 PO4407985596	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4433285521	LGE	3	50 ACE	SP	CCA		V			00:00.0
2021 PO5844505166	KU	4	40 XXX	SP	CCA		V			00:00.0
2021 PO5845505299	KU	4	40 XXX	SP	CCA		V			00:00.0
2021 PO5846405438	KU	4	40 XXX	SP	CCA		V			00:00.0
2021 PO5847405564	KU	4	40 XXX	SP	CCA		V			00:00.0
2021 PO5848705707	KU	4	40 XXX	SP	CCA		V			00:00.0
2021 PO5846805858	KU	4	40 XXX	SP	CCA		V			00:00.0
2021 PO5845005991	KU	4	40 XXX	SP	CCA		V			00:00.0
2021 PO5850906022	KU	4	40 XXX	SP	CCA		V			00:00.0
2021 PO4393885506	F	4	30 ACE	SP	CRE	ED,ID	VX		RP2	00:00.0
2021 PO4347985633	F	4	40 ACE	SP	CRE		VX		RP3	00:00.0
2021 PO4394185416	F	4	40 ACE	SP	CRE	ED,HH,ID	VX		RP1	00:00.0
2021 PO4378285325	LGE	4	25E ACE	SP	P	ED	VX		PX	00:00.0
2021 PO4416285564	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	X		RP1	00:00.0
2021 PO7849290131	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,RB,SRC	X		RP3	00:00.0
2021 PO8374987764	KU	5	35 XXX	DF	CRE	ED,HH,ID	X		RP3	00:00.0
2021 PO8111591944	KU	5	40 XXX	SP	CRE	ED,ID			BD	00:00.0
2021 PO8222492164	KU	4	40 XXX	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO6101698202	KU	4	45 ACE	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO4421185589	LGE	4	35 BRO	SP	A	ID			BD	00:00.0
2021 PO6077397174	KU	4	45 ACE	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO6105097070	KU	4	45 ACE	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO6115997769	KU	3	45 ACE	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO8054392195	KU	4	40 XXX	SP	CRE	ED,ID			BD	00:00.0
2021 PO4454685368	LGE	4	40 ACE	SP	A	ED			BD	00:00.0
2021 PO6222703241	KU	4	40 ACE	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO6230203269	KU	4	40 ACE	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO7920209058	KU	6	35 XXX	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO4455585365	LGE	4	40 ACE	SP	CRE	ED,ID			BD	00:00.0
2021 PO6184202729	KU	4	45 ACE	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO6183102657	KU	4	50 ACE	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO6182202606	KU	4	40 ACE	SP	CRE	ED,ID,IP			BD	00:00.0
2021 PO6192802533	KU	4	60 ACE	SP	CRE	ED,ID,IP			BD	00:00.0

2021 PO6213502410	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO6211602417	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4429585205	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO4430585208	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO4433085285	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO6370601807	KU	4	30 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO6381601939	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4433985356	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO6374702778	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO6359502489	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO7946691306	KU	6	30 XXX	SP	CRE	ED,ID	BX	PX	00:00.0
2021 PO5676308793	F	4	40 XXX	SP	CRE	ID,RB	BX	RP3	00:00.0
2021 PO5734708543	F	4	40 XXX	SP	CRE	HH,ID	BX	RP2	00:00.0
2021 PO5552608770	KU	6	30 XXX	SP	CCA	ED	T		00:00.0
2021 PO559108879A	KU	5	35 XXX	SP	CCA		T		00:00.0
2021 PO4417085460	LGE	3	45 BRO	SP	CCA	ED	T		00:00.0
2021 PO4415185488	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4433885347	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4434185371	LGE	4	35 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4434285387	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4409285508	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4432585248	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4433285298	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4433385309	LGE	4	40 ACE	SP	P	ED	TD		00:00.0
2021 PO4413285510	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO8081892075	KU	4	40 XXX	SP	CRE	ED,ID,MD	TD		00:00.0
2021 PO4432985273	LGE	4	40 ACE	SP	A	ED	TD		00:00.0
2021 PO5559108879	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4416385593	LGE	3	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO7970991624	KU	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO7958691460	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5570008661	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4431685218	LGE	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO4432185225	LGE	3	45 ACE	SP	A	ED	TD		00:00.0
2021 PO4432485236	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4417485588	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4418685582	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO8244691213	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8171691224	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO7931791111	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7933090296	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO7763890453	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO6181803044	KU	6	30 ACE	SP	CCA	ED,ID	TD		00:00.0
2021 PO4418785596	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 1506067316-a	LGE	3	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4435285502	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4419485610	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4450285399	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO5701308230	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO8138691919	KU	5	35 XXX	SP	CRE	ED,ID,IP,MD,SR	TD		00:00.0
2021 PO8224691840	KU	4	40 XXX	SP	CRE	ED,EP,ID,MD,SR	TD		00:00.0
2021 PO8143291028	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO8164691225A	KU	5	35 XXX	SP	CRE	ED,ID,IP,MD,SR	TD		00:00.0
2021 PO8164691225	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0

2021 PO8167391891	KU	6	35 XXX	SP	CRE	ED,ID,MD,SRC	TD	00:00.0
2021 PO8196791871	KU	6	35 XXX	SP	CRE	ED,ID,MD,SRC	TD	00:00.0
2021 PO4418985583	F	4	40 BRO	SP	A		V	00:00.0
2021 PO6219802397	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO6344502891	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6327902283	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6337202062	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6343802190	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6351702341	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4417685574	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6367202633	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5525706469	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO4437185497	LGE	3	45 ACE	SP	A		V	00:00.0
2021 PO6337302758	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6348302960	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4437685511	LGE	4	35 ACE	ST	CCA		V	00:00.0
2021 PO1495967384	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5571708834	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO4432785261	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO6366001911	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4412385530	LGE	4	30 BRO	SP	A		V	00:00.0
2021 PO4414685496	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4413585512	F	4	40 BRO	SP	A		V	00:00.0
2021 PO6374002836	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO6387702328	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6380302184	KU	4	40 ACE	SP	P		V	00:00.0
2021 PO6372702040	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4412185533	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4409285513	F	4	40 BRO	SP	A		V	00:00.0
2021 PO1247167544	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4410985525	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4410285554	LGE	4	30 BRO	SP	A		V	00:00.0
2021 PO4433685333	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6393002430	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4415785479	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4416685467	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6108498107	KU	1	50 ACE	SP	CCA		V	00:00.0
2021 PO6063497112	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4420185590	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6115197865	KU	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4453485378	F	4	30 ACE	AL	CCA		V	00:00.0
2021 PO5663408862	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO5669708761	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO5681808577	F	6	30 XXX	SP	CRE		V	00:00.0
2021 PO5673208637	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5669308432	F	4	35 XXX	SP	CCA		V	00:00.0
2021 PO5674708373	F	4	45 XXX	SP	P		V	00:00.0
2021 PO5667708351	F	4	45 XXX	SP	CCA		V	00:00.0
2021 PO5669808233	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5608908910	F	4	40 XXX	SP	P		V	00:00.0
2021 PO6082498718	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4452285360	LGE	UNK	45 ACE	SP	CCA		V	00:00.0
2021 PO6174602657	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO4455185362	F	4	40 ACE	SP	CRE		V	00:00.0

2021 PO6182702579	KU	3	50 ACE	SP	CRE	V	00:00.0
2021 PO6190202567	KU	5	35 ACE	SP	CCA	V	00:00.0
2021 PO1506067316	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO5620608803	KU	6	30 XXX	SP	CCA	V	00:00.0
2021 PO5625408748	F	3	45 XXX	SP	P	V	00:00.0
2021 PO5620708617	F	5	40 XXX	SP	CRE	V	00:00.0
2021 PO5616408631	F	4	35 XXX	SP	P	V	00:00.0
2021 PO5617308522	F	5	35 XXX	SP	CRE	V	00:00.0
2021 PO5614308439	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5610408319	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5606208204	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5633308321	F	4	45 XXX	SP	CCA	V	00:00.0
2021 PO5617108381	F	4	45 XXX	SP	CCA	V	00:00.0
2021 PO5599408448	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5608108415	F	3	45 XXX	SP	CCA	V	00:00.0
2021 PO5589808484	F	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5564108583	F	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5557308609	F	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5550108637	F	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5543508662	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5534308698	F	3	45 XXX	SP	CCA	V	00:00.0
2021 PO5525108733	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5544708564	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5540208442	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5536108333	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5532908249	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5560808078	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5565108207	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5569308332	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5574508485	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5581508513	F	4	45 XXX	SP	CCA	V	00:00.0
2021 PO5577608579	F	3	45 XXX	SP	CCA	V	00:00.0
2021 PO5580708670	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5585208802	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5588708907	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5595808930	F	4	35 XXX	SP	CCA	V	00:00.0
2021 PO4421885593	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO4418085635	LGE	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4416285623	LGE	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4418685596	LGE	4	40 BRO	SP	CRE	V	00:00.0
2021 PO5713908700	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5720408582	KU	6	30 XXX	SP	CCA	V	00:00.0
2021 PO5692708698	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO5690508199	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO6094697262	KU	3	45 ACE	SP	CCA	V	00:00.0
2021 PO6094697256	KU	3	45 ACE	SP	CCA	V	00:00.0
2021 PO6102697376	KU	2	50 ACE	SP	CCA	V	00:00.0
2021 PO6107097395	KU	2	50 ACE	SP	CCA	V	00:00.0
2021 PO6112297599	KU	3	50 ACE	SP	CCA	V	00:00.0
2021 PO6117097783	KU	2	50 ACE	SP	CCA	V	00:00.0
2021 PO6117197732	KU	2	50 ACE	SP	CCA	V	00:00.0
2021 PO4464586087	F	1	55 ACE	SP	CCA	V	00:00.0
2021 PO5768008768	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5749708819	F	4	40 XXX	SP	CRE	V	00:00.0

2021	PO5741408630	F	4	40 XXX	SP	CRE		V				00:00.0
2021	PO5737008644	F	4	40 XXX	SP	CRE		V				00:00.0
2021	PO5735508581	F	4	40 XXX	SP	CCA		V				00:00.0
2021	PO5730408364	F	4	40 XXX	SP	CCA		V				00:00.0
2021	PO5727008224	F	4	45 XXX	SP	CCA		V				00:00.0
2021	PO5742208289	F	4	40 XXX	SP	CRE		V				00:00.0
2021	PO5749608231	F	4	40 XXX	SP	P		V				00:00.0
2021	PO5741308118	F	4	40 XXX	SP	CRE		V				00:00.0
2021	PO4303386919	LGE	4	40 ACE	SP	A	ED,RB	X		RP2		00:00.0
2021	PO4304986992	F	4	35 ACE	SP	A	ED,RB	VX		RP1		00:00.0
2021	PO2820074438	KU	4	40 BRO	SP	CRE	ED,ID,RB	BX		PX		00:00.0
2021	PO2686180430	F	5	30 UNK	SP	CRE	ED,ID	BX		PX		00:00.0
2021	PO7285266609	KU	4	40 BRO	SP	CRE	ED,ID	TD				00:00.0
2021	PO2891474059	KU	5	35 XXX	SP	CRE	ID,IP	TD				00:00.0
2021	PO7057467815	KU	5	35 UNK	SP	CRE	ID	BD				00:00.0
2021	PO2255378040	KU	4	40 UNK	SP	CRE	ID	BD				00:00.0
2021	PO7071166155	KU	6	30 UNK	SP	CRE	ID	BD				00:00.0
2021	PO2541379811	KU	6	30 ACW	SP	CRE	ID	BD				00:00.0
2021	PO2829279276	KU	3	60 UNK	SP	CRE	ID	BD				00:00.0
2021	PO2543376813	KU	5	35 UNK	SP	CRE	ED,ID,RB	X		PX		00:00.0
2021	PO2696380568	KU	4	40 UNK	SP	P	ID	BD				00:00.0
2021	PO2736680428	KU	4	35 UNK	SP	CCA	ID	BD				00:00.0
2021	PO2796180252	KU	4	40 UNK	SP	CRE	ID	BD				00:00.0
2021	PO4267911732	KU	4	45 UNK	SP	CRE	ID	BD				00:00.0
2021	PO4724410878	KU	6	30 BRO	SP	CRE	ID	BD				00:00.0
2021	PO4173805107	F	3	40 CPT	SP	P	ED,EP,ID,IP,MD	BX		PX		00:00.0
2021	PO4723812435	KU	5	35 XXX	SP	CRE	ID,IP	TD				00:00.0
2021	PO4315586955	F	4	40 ACE	SP	CRE	ED	BD				00:00.0
2021	PO7391213608	KU	4	40 BRO	SP	CRE	ID	BD				00:00.0
2021	PO2976671914	KU	3	45 XXX	SP	CCA		V				00:00.0
2021	PO5174903710	KU	2	50 BRN	SP	CRE	ED,HH,ID,IP,RB	X		RP1		00:00.0
2021	PO5389304256	F	4	40 BRO	SP	CRE	HH,ID	VX		RP2		00:00.0
2021	PO5497204627	F	4	40 BRO	SP	CRE	HH,ID,IP,MD	VX		PX		00:00.0
2021	PO5629804008	F	3	45 BRO	SP	CRE		V				00:00.0
2021	PO5585104149	F	4	40 MAR	SP	CRE		V				00:00.0
2021	PO5584604100	F	4	40 MAR	SP	CRE		V				00:00.0
2021	PO4314387013	F	4	35 ACE	SP	P		V				00:00.0
2021	PO6635288845	KU	4	40 BRN	SP	CRE	ED	TD				00:00.0
2021	PO6853985085	KU	5	35 BRN	SP	CRE	ED	TD				00:00.0
2021	PO6873885310	KU	4	40 BRN	SP	CRE	ED	TD				00:00.0
2021	PO5202005355	KU	3	45 BRO	SP	CRE	ED	TD				00:00.0
2021	PO5494304315	KU	5	35 BRO	SP	CRE	ED	TD				00:00.0
2021	PO5221901984	KU	3	45 BRN	SP	CRE	ED	TD				00:00.0
2021	PO5230102216	KU	3	45 BRN	SP	CRE	ED	TD				00:00.0
2021	PO5232102364	KU	3	45 BRN	SP	CRE	ED	TD				00:00.0
2021	PO6790188063	KU	4	40 BRN	SP	CRE	ED	TD				00:00.0
2021	PO6742984971	KU	4	40 BRN	SP	CRE	ED	TD				00:00.0
2021	PO6766388161	KU	4	40 BRN	SP	CRE		BD				00:00.0
2021	PO5509104308	KU	6	30 BRO	SP	CRE	ED	BD				00:00.0
2021	PO5500604993	KU	3	45 BRO	SP	CRE	ED	BD				00:00.0
2021	PO2815674398	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD				00:00.0
2021	PO2739974893	KU	3	50 BRO	SP	CRE	ID	BD				00:00.0
2021	PO4309586876	LGE	4	40 ACE	SP	A	ED,ID	BD				00:00.0
2021	PO5189003945	KU	2	50 BRN	SP	CCA		V				00:00.0



2021 PO4305786901	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5189603959	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO4317586973	F	4	35 ACE	SP	P		V		00:00.0
2021 PO4302187054	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4319586920	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO5199204225	KU	2	45 BRN	SP	CRE		BD		00:00.0
2021 PO5188004011	KU	2	55 BRN	SP	CRE		BD		00:00.0
2021 PO5202404300	KU	2	45 BRN	SP	CRE		BD		00:00.0
2021 PO3905307912	F	4	40 BRN	SP	CRE	ED,HH,ID,IP,MD,RB	BX	PX	00:00.0
2021 PO3944005746	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,MD,RB	BX	PX	00:00.0
2021 PO5138502796	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO5166303463	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO6763484910	KU	5	35 BRN	SP	CRE		V		00:00.0
2021 PO0266581130	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO0250681085	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4304287057	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4310286985	LGE	4	30 ACE	SP	A		V		00:00.0
2021 PO6941467360	KU	5	35 BRO	SP	CRE		V		00:00.0
2021 PO6388724637	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO2333178700	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO2516779493	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO6940371527	KU	6	30 XXX	SP	CRE		V		00:00.0
2021 PO2996871919	KU	4	35 XXX	SP	CCA		V		00:00.0
2021 PO3067971441	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO2436076467	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO5063213605	KU	4	45 BRO	SP	CRE		V		00:00.0
2021 PO2630380367	KU	5	35 UNK	SP	CCA		V		00:00.0
2021 PO2735680296	KU	6	30 UNK	SP	CRE		V		00:00.0
2021 PO5066427934	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO3959607299	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX	00:00.0
2021 PO4021106946	F	4	40 BRN	SP	P	ED,HH,ID,MD,RB	BX	PX	00:00.0
2021 PO2742775299	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4708212176	KU	5	35 XXX	SP	CRE		V		00:00.0
2021 PO5216405416	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5214805380	KU	2	40 BRN	SP	CRE		V		00:00.0
2021 PO5214005359	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5213405343	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5217005431	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4306386877	LGE	4	35 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4309586960	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4321386900	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4327886950	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO2648880520	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO4102104985	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4187805497	F	4	40 UNK	SP	CRE	ED,ID,IP,MD	V		00:00.0
2021 PO4169104988	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO3948006156	F	4	40 XXX	SP	CRE	ED,HH,ID,IP,MD,RB	BX	RP1	00:00.0
2021 PO3902507591	F	4	40 BRN	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO3072271122	KU	4	40 BRO	SP	CRE	ED,ID,RB	X	RP1	00:00.0
2021 PO5509404929	F	4	40 BRO	SP	CRE	HH,ID	VX	RP2	00:00.0
2021 PO7247966466	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7058668724	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7025768104	KU	3	50 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6958567336	KU	3	45 UNK	SP	CRE	ED,ID,IP	TD		00:00.0

2021 PO6937767099	KU	4	45 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7304714876	KU	5	45 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4919813240	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4906813230	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8075914724	KU	4	45 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3514414160	KU	5	40 BRO	SP	CRE	ED,ID	BX	RP2	00:00.0
2021 PO3050672482	KU	3	45 BRO	SP	CRE	ID	BX	RP1	00:00.0
2021 PO2781374623	KU	2	80 BRO	SP	CRE	ID	BD		00:00.0
2021 PO7088568984	KU	5	35 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO5544113969	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2761175143	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2756674957	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5775414882	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3072671437	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3072671402	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2752074770	KU	1	75 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO3491114149	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO2807674490	KU	2	50 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO5823414390	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO2839974722	KU	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO2826074533	KU	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7075269338	KU	5	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO5550613824	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO3463114147	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO8079614471	KU	4	45 UNK	SP	CRE	ED,HH,ID,RB	X	RP1	00:00.0
2021 PO4315286876	LGE	4	40 ACE	SP	P	ED,ID	VX	RP1	00:00.0
2021 PO4285187115	LGE	3	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO2842975490	F	4	40 UNK	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO2590777072	KU	4	40 UNK	SP	CRE	HH,ID	BX	RP2	00:00.0
2021 PO2473181199	F	4	40 UNK	SP	CRE	HH,ID	BX	PX	00:00.0
2021 PO2437281198	F	4	40 UNK	SP	P	HH	BX	PX	00:00.0
2021 PO2400378967	F	4	40 UNK	SP	CRE	ED,HH,ID,IP	BX	PX	00:00.0
2021 PO2303978451	F	4	40 UNK	SP	CRE	ED,HH,ID	BX	RP2	00:00.0
2021 PO4900607663	KU	4	40 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021 PO4308886985	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4309387099	F	4	35 ACE	SP	CRE		V		00:00.0
2021 PO4313986946	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4312786931	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4292487106	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4304187023	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4303587028	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4313186952	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4311286967	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4305287014	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4305686942	LGE	4	35 ACE	SP	A	ED,ID	X	RP1	00:00.0
2021 PO4307386974	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4312286959	LGE	4	35 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO4304786908	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4315086939	LGE	6	25 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4310286969	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO4313986898	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4313586919	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4312786917	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4314186934	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0

2021 PO0290781695	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4319886897	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4307186999	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4312686956	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4314586941	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4313887010	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4314387103	LGE	4	35 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4316086951	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO2413777873	KU	4	40 ACW	SP	CRE	ID	BD	00:00.0
2021 PO5469404755	KU	6	30 BRO	SP	CRE		BD	00:00.0
2021 PO5539099980	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5212705325	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3590015710	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3434314140	KU	5	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO3422214230	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PV0219382169	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO6756385042	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4686312407	KU	5	35 XXX	SP	CRE		V	00:00.0
2021 PO5857411401	KU	5	45 KOP	SP	CCA		V	00:00.0
2021 PO7293566988	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4319987002	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4314386904	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4307187029	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4325386948	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4306587017	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4307587028	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4312787091	LGE	4	40 ACE	SP	P	ED,ID,MD,RB	VX	PX 00:00.0
2021 PO4322186914	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO7650615427	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3927207453	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX 00:00.0
2021 PO4327486957	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4308287108	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4310187066	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4310986964	LGE	4	30 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4309486976	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4317586924	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4316386917	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4315686912	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4308186991	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4304787018	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4307587003	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4310887106	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4326186956	LGE	4	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4326286953	LGE	5	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4328486940	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4326886965	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4321286906	LGE	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4319386935	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4317786987	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4310686974	LGE	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4311486985	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4309786979	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4305187070	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4323586928	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0

2021	PO4314686886	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4312086907	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4320286910	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO5591410664	F	4	40 UNK	SP	P		V	00:00.0
2021	PO5600610674	F	4	40 UNK	SP	P		V	00:00.0
2021	PO4430385539	LGE	4	30 BRO	ST	P		V	00:00.0
2021	PO4414785842	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021	PO5597811465	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7472207923	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7483807974	F	6	30 XXX	SP	CRE		V	00:00.0
2021	PO7536508191	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7540708308	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7490808353	F	4	40 XXX	SP	S		V	00:00.0
2021	PO4408585850	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO7515407806	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7522807783	F	3	45 XXX	SP	CRE		V	00:00.0
2021	PO5551211229	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO5665209336	F	3	40 BRN	SP	A		V	00:00.0
2021	PO5677109321	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5685709317	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4267386463	F	2	55 BRO	SP	CCA		V	00:00.0
2021	PO7479705603	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5544910952	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4416585767	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5748909336	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO5751809282	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5548411101	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4264386556	LGE	H8	40 BRO	AL	CCA		V	00:00.0
2021	PO7456506009	F	6	30 UNK	SP	CRE		V	00:00.0
2021	PO7468905932	F	4	45 UNK	SP	CRE		V	00:00.0
2021	PO7479105864	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO7487705818	F	4	40 UNK	SP	P		V	00:00.0
2021	PO4272286618	LGE	4	35 BRO	SP	P		V	00:00.0
2021	PO7483305700	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO7681507550	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021	PO7693707417	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO4264286545	LGE	H5	55 BRO	AL	CCA		V	00:00.0
2021	PO2192521762	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO7544908443	F	4	40 XXX	SP	S		V	00:00.0
2021	PO7600907562	F	3	40 XXX	SP	S		V	00:00.0
2021	PO7603607476	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO7612707364	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7621807253	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7628907164	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7631507036	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7632406941	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO7633306855	KU	3	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO5494611467	KU	5	35 UNK	SP	S		V	00:00.0
2021	PO5467811515	F	4	45 UNK	SP	P		V	00:00.0
2021	PO5460311441	F	3	50 UNK	SP	P		V	00:00.0
2021	PO4265186617	LGE	H8	70 BRO	AL	CCA		V	00:00.0
2021	PO5503311110	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO9785678451	LGE	H8	70 BRO	AL	CCA		V	00:00.0
2021	PO8719600799	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0

2021 PO4266186685	LGE	H8	75	BRO	AL	CCA		V	00:00.0
2021 PO7711807332	KU	3	45	BRN	SP	CRE	ED	TD	00:00.0
2021 PO7718707262	KU	3	45	BRN	SP	CCA		V	00:00.0
2021 PO9781378085	LGE	3	50	BRO	SP	CCA		V	00:00.0
2021 PO4525787658	F	4	40	BRO	SP	A		V	00:00.0
2021 PO4526487646	F	3	45	BRO	SP	CCA		V	00:00.0
2021 PO4264686574	LGE	H8	70	BRO	AL	CCA		V	00:00.0
2021 PO4264886591	LGE	H8	70	BRO	AL	CCA		V	00:00.0
2021 PO4263786508	LGE	3	70	BRO	AL	CCA		V	00:00.0
2021 PO4263986520	LGE	3	75	BRO	AL	CCA		V	00:00.0
2021 PO7667507702	KU	3	45	BRN	SP	CRE	ED	BD	00:00.0
2021 PO7428201179	KU	2	50	BRO	SP	CCA		V	00:00.0
2021 PO4371085027	LGE	3	50	ACE	SP	CCA		V	00:00.0
2021 PO7780107176	KU	3	45	BRN	SP	CRE	ID	TD	00:00.0
2021 PO7781907194	KU	3	45	BRN	SP	CCA		V	00:00.0
2021 PO7825104676	KU	4	40	BRN	SP	CRE	ED	TD	00:00.0
2021 PO7720306286	KU	2	55	BRN	SP	CRE	ED	TD	00:00.0
2021 PO7729706403	KU	4	40	BRN	SP	CCA		V	00:00.0
2021 PO7722506314	KU	3	40	BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7390601787	KU	5	35	UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4430885535	F	4	40	BRO	SP	CCA		V	00:00.0
2021 PO9792877357	LGE	4	35	BRO	SP	CCA		V	00:00.0
2021 PO7785307224	F	2	50	BRN	SP	CCA		V	00:00.0
2021 PO7776807308	F	4	40	BRN	SP	CRE		V	00:00.0
2021 PO7764907426	F	4	40	BRN	SP	CRE		V	00:00.0
2021 PO4409985962	LGE	3	45	BRO	SP	A	ID	BD	00:00.0
2021 PO4409385957	LGE	4	40	BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4408085949	LGE	4	40	BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4407785946	LGE	2	55	BRO	SP	A	ID	BD	00:00.0
2021 PO4407385944	LGE	4	40	BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4408685946	F	4	35	BRO	SP	A		V	00:00.0
2021 PO4407285937	F	4	35	BRO	SP	A		V	00:00.0
2021 PO4411085968	LGE	3	45	BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO8371787379	KU	5	40	UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO8177403072	F	3	50	CPT	SP	P		V	00:00.0
2021 PO4263486485	LGE	3	70	BRO	SP	CRE		V	00:00.0
2021 PO5700110991	KU	4	40	UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4287286677	LGE	3	45	BRO	SP	CCA		V	00:00.0
2021 PO4286786676	LGE	4	35	BRO	SP	A		V	00:00.0
2021 PO4405285943	LGE	3	45	BRO	SP	CCA		V	00:00.0
2021 PO4405985935	LGE	4	40	BRO	SP	CCA		V	00:00.0
2021 PO4368485027	LGE	3	50	ACE	SP	CCA		V	00:00.0
2021 PO7851908535	KU	3	45	BRN	SP	CCA		V	00:00.0
2021 PO7855808588	KU	3	45	BRN	SP	CCA		V	00:00.0
2021 PO7862608677	KU	3	45	BRN	SP	CRE	ED	TD	00:00.0
2021 PO4375585152	LGE	3	45	ACE	SP	CCA		V	00:00.0
2021 PO7845108446	KU	3	45	BRN	SP	CRE	ED	TD	00:00.0
2021 PO7847608477	KU	3	45	BRN	SP	CRE	ID,IP	TD	00:00.0
2021 PO7801407886	KU	4	45	BRN	SP	CCA		V	00:00.0
2021 PO7809307989	KU	4	40	BRN	SP	CRE	ED	TD	00:00.0
2021 PO7834608312	KU	4	40	BRN	SP	CRE	ED	TD	00:00.0
2021 PO7397900754	KU	4	40	UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7399900588	KU	4	40	UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7879708952	KU	3	45	BRN	SP	CCA		V	00:00.0

2021	PO7824907025	KU	4	35 BRN	SP	CRE	SRS	TD	00:00.0
2021	PO5406310442	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO4409285881	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4409885888	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4410785915	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4413985941	LGE	1	40 BRO	SP	CCA		V	00:00.0
2021	PO4414485940	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4413485933	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4412885928	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4411285964	F	4	35 BRO	SP	A		V	00:00.0
2021	PO4409785953	F	4	35 BRO	SP	A		V	00:00.0
2021	PO2260622799	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO5653512016	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5655612049	KU	3	45 UNK	SP	S		V	00:00.0
2021	PO5553012003	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5479411425	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021	PO5483911481	KU	4	45 UNK	SP	CCA		V	00:00.0
2021	PO4411985811	LGE	1	70 BRO	SP	A		V	00:00.0
2021	PO4265986676	LGE	H8	85 BRO	AL	CCA		V	00:00.0
2021	PO4408785843	LGE	4	35 BRO	SP	A	ED,ID,IP,SRC	TD	00:00.0
2021	PO4410485820	LGE	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4410285841	LGE	UNK	75 BRO	SP	A		V	00:00.0
2021	PO7385908262	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7394408214	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7578807598	KU	3	50 XXX	SP	S		V	00:00.0
2021	PO7589107694	KU	2	50 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7599307783	KU	2	50 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO7522307347	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7562807462	KU	3	45 XXX	SP	S		V	00:00.0
2021	PO7416407989	F	3	45 XXX	SP	CRE		V	00:00.0
2021	PO7405908111	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4414885766	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021	PO4414185776	LGE	1	60 BRO	SP	A		V	00:00.0
2021	4411185824	LGE	1	75 BRO	SP	A		V	00:00.0
2021	PO4413385789	LGE	2	55 BRO	SP	A		V	00:00.0
2021	PO4412585802	LGE	1	65 BRO	SP	A		V	00:00.0
2021	PO4415685838	LGE	3	45 BRO	SP	A		V	00:00.0
2021	PO4414685829	LGE	4	35 BRO	SP	A		V	00:00.0
2021	PO4414485836	LGE	3	45 BRO	SP	A		V	00:00.0
2021	PO7722708101	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO5612810968	KU	3	45 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7432407864	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7425907833	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7456108178	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7453708103	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7454607883	F	3	45 XXX	SP	CRE		V	00:00.0
2021	PO7601806756	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO7615106756	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7617107034	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO7607107033	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7594107030	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7594407133	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7581707287	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO7589007198	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0

2021 PO4415285741	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO5641213138	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4415485891	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7587606758	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7587406695	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO7556308147	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7560008240	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7572408110	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO5627312738	KU	4	40 KOP	SP	CRE		BD	00:00.0
2021 PO5620112545	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7601506478	KU	3	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7620706229	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO7615206410	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO7637106279	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7576006090	KU	4	40 XXX	DF	CRE	ED,ID,IP	TD	00:00.0
2021 PO7597306155	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7607206186	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7589306438	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4427685622	LGE	2	55 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO7677508621	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5506511052	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7675908607	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4428885630	LGE	3	50 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5466310921	F	4	40 UNK	SP	P		V	00:00.0
2021 PO4435885678	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5476810882	F	4	40 UNK	SP	P		V	00:00.0
2021 PO7516405740	F	3	40 BRO	SP	CRE		V	00:00.0
2021 PO4433885668	LGE	2	55 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5543010670	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5554710668	F	4	40 BRN	SP	S		V	00:00.0
2021 PO1478869118	F	2	55 BRO	SP	CCA		V	00:00.0
2021 PO5506910789	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5456010961	F	4	40 UNK	SP	P		V	00:00.0
2021 PO1489969204	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4435285678	LGE	2	50 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5510411038	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4431385650	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5516010905	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO5515410760	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5527810702	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4433085662	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO7486604993	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7475305338	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7492405140	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7497105257	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7506905504	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7511905631	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO4398885832	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO7562607532	KU	3	50 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4429885546	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4430285518	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4430785580	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4265786621	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4265086609	F	4	35 BRO	SP	CCA		V	00:00.0

2021	PO5663713686	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO5649613379	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5598313394	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4397485851	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO7572907727	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7585707971	KU	3	45 XXX	SP	S		V	00:00.0
2021	PO7581807897	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021	PO7537907685	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7547107915	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7551708032	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5588113439	KU	1	75 UNK	SP	CCA	ED,ID	TD	00:00.0
2021	PO5613012355	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO5618512342	F	4	40 KOP	SP	S		V	00:00.0
2021	PO7232805889	F	3	45 XXX	SP	CRE		V	00:00.0
2021	PO7223606026	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7229206159	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7232206230	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7240006190	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7461006354	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7537207260	KU	6	30 XXX	SP	S		V	00:00.0
2021	PO7525807144	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7546807328	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7536607236	F	4	40 XXX	SP	P		V	00:00.0
2021	PO7526307023	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7520107094	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7505306965	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7515207051	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO7495106876	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4416185774	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO7664108322	KU	2	60 BRN	SP	CCA		V	00:00.0
2021	PO7668808347	KU	2	45 BRN	SP	CCA		V	00:00.0
2021	PO7667308361	KU	2	45 BRN	SP	CCA		V	00:00.0
2021	PO7658208519	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO7651308594	F	3	40 BRN	SP	CCA		V	00:00.0
2021	PO7649608612	F	2	50 BRN	SP	CRE		V	00:00.0
2021	PO7677709129	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5605512257	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5594112133	F	3	45 KOP	SP	CCA		V	00:00.0
2021	PO5569512081	KU	3	45 UNK	SP	S		V	00:00.0
2021	PO5602312128	KU	3	45 UNK	SP	CRE		BD	00:00.0
2021	PO4521888121	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO2299893615	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021	PO4436188843	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4828512371	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4436288834	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO1870169274	KU	4	45 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021	PO1833869198	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021	PO4532087625	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4533987592	F	4	40 ACE	SP	P		V	00:00.0
2021	PO1865869091	KU	4	45 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO4532787614	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4533187606	F	4	40 ACE	SP	A		V	00:00.0
2021	PO4534487560	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4534187588	F	4	30 ACE	SP	P		V	00:00.0



2021 PO1861668915	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4533187585	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4002583983	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3997883977	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO1854768417	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO1854468789	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1834668730	KU	4	40 BRO	SP	CRE	ED,MD,SRS	TD	00:00.0
2021 PO1853168608	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3996883965	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3998983992	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3999983995	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4001483994	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4523987986	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4522087992	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4003783977	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4005883965	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4004883946	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4010683940	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4523387999	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4522988006	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4532287770	F	4	40 ACE	SP	P		V	00:00.0
2021 PO2422490235A	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4011583954	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4534487772	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4535287759	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4012683946	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4010483903	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4010583911	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO1865769646	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1883269870	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1879169673	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4803309264	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4824609910	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4765109612	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4804710279	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4840310382	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4812310404	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4801409554	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4807209643	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4817809806	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4787909999	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4823210479	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4833710420	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4787809343	F	3	45 XXX	SP	S		V	00:00.0
2021 PO4795309460	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4771709724	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4796410143	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4757709487	F	3	45 XXX	SP	S		V	00:00.0
2021 PO4779209851	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4770709422	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4817810496	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5063709092	F	2	55 BRN	SP	S		V	00:00.0
2021 PO5133308844	KU	2	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5086809141	F	4	40 XXX	SP	CRE		V	00:00.0

2021	PO5083109234	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5069209061	F	5	35 BRN	SP	S		V	00:00.0
2021	PO5128008655	KU	5	30 XXX	SP	CCA		V	00:00.0
2021	PO5129808789	KU	3	45 XXX	SP	S		V	00:00.0
2021	PO5136008623	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5123609053	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5119908836	F	5	35 XXX	SP	S		V	00:00.0
2021	PO5066509127	KU	2	55 BRN	SP	S		V	00:00.0
2021	PO5118008667	KU	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO5088608977	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5094509359	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5081308898	KU	5	35 BRN	SP	S		V	00:00.0
2021	PO5090709400	KU	6	30 XXX	SP	CRE		BD	00:00.0
2021	PO5126308604	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5103809331	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5092009285	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5091209193	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5068509203	KU	4	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO4004483973	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO1862069428	KU	4	40 BRO	SP	CRE	ED,MD,SRS	TD	00:00.0
2021	PO1841369474	KU	4	40 BRO	SP	CRE	ED,IP,MD	TD	00:00.0
2021	PO1875269496	KU	4	45 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021	PO1862269292	KU	5	35 BRO	SP	CRE	ED,MD,SRS	T	00:00.0
2021	PO4531687781	F	4	40 BRO	SP	P		V	00:00.0
2021	PO4389522495	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4390622644	KU	4	35 XXX	SP	CCA		V	00:00.0
2021	PO4391522801	KU	4	40 XXX	SP	P	ID	TD	00:00.0
2021	PO4392722989	KU	4	45 XXX	SP	CCA		V	00:00.0
2021	PO4409526810	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO7357851600	LGE	2	60 BRO	SP	CCA		V	00:00.0
2021	PO4471688786	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4470288789	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0
2021	PO1787500155	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4853985242	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4855685315	LGE	4	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4474788726	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4481388532	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4482988508	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4855585222	LGE	3	45E ACE	SP	A	ED	TD	00:00.0
2021	PO4855485208	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4483588498	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4473788547	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4474388537	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4472988559	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4473288574	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4393623135	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4394823338	KU	4	45 XXX	SP	CCA		V	00:00.0
2021	PO4423426225	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO4470888529	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4013683893	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4459188392	F	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4458188389	F	4	35 ACE	SP	P		V	00:00.0
2021	PO4660727636	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4670227698	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0

2021 PO4679427773	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4690727851	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4696327923	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4299924275	KU	6	30 XXX	SP	CRE		V	00:00.0
2021 PO4454288386	LGE	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4453488381	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4014583840	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4013683848	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4012683853	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4013283865	LGE	4	30 BRO	SP	A	ID	BD	00:00.0
2021 PO4014283863	LGE	5	35 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4455988396	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4455088390	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4012483867	LGE	4	30 BRO	SP	A	ED	TD	00:00.0
2021 PO4458288408	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4457788402	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4012683874	LGE	3	45 BRO	SP	A	ED,ID,IP,RB	TX	RR 00:00.0
2021 PO4459588415	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4460388419	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4460988423	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4462088448	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021 PO4009383908	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4008283913	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4006083924	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4246724373	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4276924357	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4299224346	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4304824148	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4317023863	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4007183919	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4004183932	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4002983943	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4001883947	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4452288561	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4453188568	F	3	55 ACE	SP	CRE		V	00:00.0
2021 PO3999583947	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4452888563	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4000783943	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4450888575	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4452088578	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4000383959	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4473288724	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4471888723	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4855685293	LGE	3	45 ACE	SP	P	ED,EP,IP,MD	BD	00:00.0
2021 PV4469988762	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4469788745	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4469488726	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4855685275	LGE	3	45 ACE	SP	A	ED,IP	BD	00:00.0
2021 PO4855785275	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4470688724	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4471688671	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4472288666	LGE	2	45 ACE	SP	CCA		V	00:00.0
2021 PO4855685255	LGE	3	45 ACE	SP	CCA	ED	TD	00:00.0
2021 PO4855685239	LGE	3	45 ACE	SP	A	ED	TD	00:00.0

2021 PO4470288535	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4863485336	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4856685373	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4856985367	LGE	4	30 ACE	SP	CRE	ED,IP	TD	00:00.0
2021 PO4471788524	LGE	4	30 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4471988520	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4856485356	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO4455788475	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4425526804	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4465488392	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4466088383	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4464588409	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4463988419	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4463288429	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4860285334	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4000383969	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3998483952	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3997383956	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4451288552	LGE	4	35 ACE	AL	CCA		V	00:00.0
2021 PO3996183959	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4011783895	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4011283898	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4012383893	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4013383911	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4013983918	LGE	4	35 BRO	SP	A	ID	BD	00:00.0
2021 PO4014283922	F	4	35 BRO	SP	A		V	00:00.0
2021 PO7313751075	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO7317651118	LGE	4	30 BRO	SP	A		V	00:00.0
2021 PO4014983935	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4858785333	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7363351577	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO4856385332	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4856285313	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021 PO4014583910	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4646527533	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4461988429	LGE	4	35 ACE	SP	CRE	ED	V	00:00.0
2021 PO4462288432	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4015783894	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4462888435	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4014883892	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4455588372	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4454488371	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4454988371	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4855385198	LGE	3	45 ACE	SP	A	ED	TD	00:00.0
2021 PO4478388886	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4479688902	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4475488862	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4477288877	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4481388920	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO1904170860	KU	6	30 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO1911970771	KU	4	40 BRO	SP	CRE	ED,MD,SRS	TD	00:00.0
2021 PO4474888913	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO1903370578	KU	3	45 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO4472388925	LGE	3	45 ACE	SP	CCA		V	00:00.0

2021 PO4473488917	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO1892370393	KU	4	45 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1897570483	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1905870354	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1914070505	KU	5	35 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO4449830842	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4432731082	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4451531051	KU	5	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4438831452	KU	5	45 XXX	SP	CRE	HH,ID	X PX	00:00.0
2021 PO4426031841	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4413432664	KU	5	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4437231927	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4418932369	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4415232604	KU	5	45 XXX	SP	CCA		V	00:00.0
2021 PO4468032763	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4489432941	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4536433338	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4556333518	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4585733747	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4568933338	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4388222289	KU	4	40 XXX	SP	P	ID	TD	00:00.0
2021 PO4832285916	LGE	4	40 ACE	SP	P	ED,IP	BD	00:00.0
2021 PO4833185912	LGE	4	45 ACE	SP	CRE	ED	TD	00:00.0
2021 PO4756725735	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4749025654	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4743525704	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4274386939	LGE	3	50 ACE	SP	CRE	ED	V	00:00.0
2021 PO4274286939	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4271286943	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4731025818	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4719925919	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4255587382	LGE	1	60 ACE	SP	CRE		V	00:00.0
2021 PO4249687320	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4249787326	LGE	1	70 ACE	SP	CRE		V	00:00.0
2021 PO5002327255	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5023427123	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5034027058	F	4	40 XXX	SP	CRE	ED,ID	V	00:00.0
2021 PO6482323963	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5344211252	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5331711307	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO5318611363	KU	3	50 XXX	SP	S		V	00:00.0
2021 PO5316211373	KU	2	45 XXX	SP	S		V	00:00.0
2021 PO4420685681	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO4272187120	LGE	1	55 ACE	SP	CRE	ED,MD	V	00:00.0
2021 PO4272587149	LGE	1	75 ACE	SP	CRE		V	00:00.0
2021 PO5349337568	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5222716243	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5850008786	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5355837574	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7888906177	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4271787095	LGE	1	75 ACE	SP	CRE		V	00:00.0
2021 PO4271587089	LGE	1	75 ACE	SP	CRE		V	00:00.0
2021 PO4401286135	LGE	4	35 BRO	SP	P		V	00:00.0
2021 PO4398986173	LGE	5	35 BRO	SP	CCA		V	00:00.0

2021 PO1123774070	LGE	5	35 BRO	ST	CCA		V	00:00.0
2021 PO4402686116	F	UNK	60 BRO	SP	CRE		V	00:00.0
2021 PO4055318797	KU	4	45 BRN	SP	CRE		V	00:00.0
2021 PO4080018708	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4106818611	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4747326306	F	3	40 XXX	SP	CRE		V	00:00.0
2021 PO4711622204	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4736626398	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4725826492	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4704126678	F	2	50 XXX	SP	P	ED	V	00:00.0
2021 PO4270286985	LGE	1	75 ACE	SP	CRE		V	00:00.0
2021 PO5293308497	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO52922108385	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO5490310873	KU	6	30 XXX	SP	S		V	00:00.0
2021 PO4472526257	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4507026509	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4578527033	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5828612213	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4543626783	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9864882383	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO5146217903	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5065220252	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4280387014	LGE	1	55 ACE	SP	CRE		V	00:00.0
2021 PO4278787090	LGE	1	75 ACE	SP	CRE		V	00:00.0
2021 PO5075420012	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5090519960	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5109620000	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5166717800	KU	1	55 BRN	SP	CCA		V	00:00.0
2021 PO4279687048	LGE	1	65 ACE	SP	CRE		V	00:00.0
2021 PO5113019960	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5119019614	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5125519709	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5146619537	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO4278587098	LGE	1	65 ACE	SP	P		V	00:00.0
2021 PO5187117698	KU	1	55 BRN	SP	CCA		V	00:00.0
2021 PO4270887024	LGE	2	70 ACE	SP	CRE		V	00:00.0
2021 PO5256831260	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5252531476	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5267530725	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5361425091	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5275030735	F	5	35 UNK	SP	CRE		V	00:00.0
2021 PO5349635185	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4046407693	F	4	40 BRO	SP	CRE	ED,ID,JP	V	00:00.0
2021 PO5176917548	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO5156619662	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5151719599	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5438507720B	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO5438507720A	F	4	30 BRO	SP	A		V	00:00.0
2021 PO5392105323	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5386205153	KU	3	65 BRO	SP	CRE		V	00:00.0
2021 PO5379504957	KU	2	65 BRO	SP	CRE		V	00:00.0
2021 PO5373904932	F	2	55 BRO	SP	CRE		V	00:00.0
2021 PO4886726984	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4890627112	F	4	40 XXX	SP	CRE	ED	V	00:00.0

2021 PO4886627064	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4879926988	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO5585612685	KU	1	80 XXX	ST	S		V	00:00.0
2021 PO5585612685	KU	1	80 XXX	SP	S		V	00:00.0
2021 PO2363319356	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO2358819116	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5567913990	KU	2	65 UNK	SP	CRE		V	00:00.0
2021 PO5420407603	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5712411048	F	5	35 XXX	SP	CRE		V	00:00.0
2021 PO5552211936	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5528912214	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5528411824	F	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5660509732	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5359111187	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO4417785449	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4295887150	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4295587131	LGE	2	55 ACE	SP	CRE		V	00:00.0
2021 PO4413985433	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4731310759	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5450836240	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4030308570	F	1	55 BRO	SP	P		V	00:00.0
2021 PO4040308409	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4047908281	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4055708148	F	4	40 XXX	SP	P	ED	V	00:00.0
2021 PO4062808027	F	3	45 XXX	SP	P		V	00:00.0
2021 PO4086309069	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO4105009300	F	3	45 XXX	SP	CRE	ED	V	00:00.0
2021 PO4114009415	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO4124909540	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO4136409668	F	2	50 XXX	SP	P		V	00:00.0
2021 PO4148209795	F	2	50 XXX	SP	P		V	00:00.0
2021 PO4160609932	F	2	50 XXX	SP	CRE	ED	V	00:00.0
2021 PO4739711181	F	6	30 BRN	SP	CRE		V	00:00.0
2021 PO4744411159	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5519510045	KU	1	70 XXX	SP	CRE		V	00:00.0
2021 PO5510409670	KU	2	75 XXX	ST	CCA		V	00:00.0
2021 PO5625310031	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5656810098	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5790037621a	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5675209743	F	4	40 BRO	SP	S		V	00:00.0
2021 PO5508934539	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO0321981378	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5790037621	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4403986267	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4404386290	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4405786285	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4408786282	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4410486276	LGE	4	35 BRO	SP	A		V	00:00.0
2021 PO4297387181	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5631237123	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5395538268	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5613137087	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5596937039	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5719937399	KU	4	40 BRO	SP	CRE		V	00:00.0

2021 PO4293987161	LGE	3	45 ACE	SP	CRE		V	00:00.0	
2021 PO5568836918	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO5546636785	KU	3	45 BRO	SP	CRE		V	00:00.0	
2021 PO3941108196	F	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3953908233	F	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO3969008283	F	2	50 BRO	SP	CCA		V	00:00.0	
2021 PO3983908331	F	2	50 BRO	SP	CCA		V	00:00.0	
2021 PO3991008356	F	1	50 BRO	SP	CCA		V	00:00.0	
2021 PO5425535576	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO5276932655	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO4792913304	F	4	40 BRN	SP	P		V	00:00.0	
2021 PO4854013158	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4792012348	F	5	40 BRN	SP	CRE		V	00:00.0	
2021 PO5317103316	KU	1	75 BRO	SP	CRE		V	00:00.0	
2021 PO5312303200	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO5306503061	KU	1	70 BRO	SP	CRE		V	00:00.0	
2021 PO5325703537	KU	1	70 BRO	SP	CRE		V	00:00.0	
2021 PO4290087140A	LGE	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO5300802867	KU	1	80 BRO	SP	CRE		V	00:00.0	
2021 PO5299602817	KU	2	55 BRO	SP	CCA		V	00:00.0	
2021 PO6875309289	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO5424605250	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO5420705264A	KU	3	45 BRO	SP	P		V	00:00.0	
2021 PO5420705264	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO5409106059	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO7063814670	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO3988608032	F	3	40 BRO	SP	P		V	00:00.0	
2021 PO5357705475	F	2	50 BRO	SP	CRE		V	00:00.0	
2021 PO7108715026	KU	4	40 KOP	SP	CRE		V	00:00.0	
2021 PO5331533917	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO5355505000	KU	2	50 BRO	SP	CCA		V	00:00.0	
2021 PO5360104984	F	2	50 BRO	SP	CRE		V	00:00.0	
2021 PO5285505783	F	2	50 BRO	SP	CRE		V	00:00.0	
2021 PO5252305537	F	2	45 BRO	SP	CRE		V	00:00.0	
2021 PO5250405485	F	2	45 BRO	SP	CRE		V	00:00.0	
2021 PO5248605435	F	2	60 BRO	SP	CRE		V	00:00.0	
2021 PO5253605574	F	2	45 BRO	SP	CRE		V	00:00.0	
2021 PO5257905684	F	2	45 BRO	SP	CRE		V	00:00.0	
2021 PO5264905870B	F	5	35 BRO	SP	CCA		V	00:00.0	
2021 PO5264905870A	KU	1	50 BRO	SP	CCA		V	00:00.0	
2021 PO5264905870	F	2	50 BRO	SP	CRE		V	00:00.0	
2021 PO5271205843	F	2	50 BRO	SP	CRE		V	00:00.0	
2021 PO5445609070	F	6	30 XXX	SP	P		V	00:00.0	
2021 PO5442208327	KU	3	40 XXX	SP	S		V	00:00.0	
2021 PO5346339556	F	4	40 KOP	SP	CRE		V	00:00.0	
2021 PO4266287128	LGE	2	50 ACE	SP	CRE		V	00:00.0	
2021 PO4266287118	LGE	2	55 ACE	SP	CRE		V	00:00.0	
2021 PO4266187110	LGE	2	45 ACE	SP	CRE		V	00:00.0	
2021 PO4265887090	LGE	2	50 ACE	SP	A	ED	V	00:00.0	
2021 PO4265787084	LGE	2	50 ACE	SP	CRE		V	00:00.0	
2021 PO5272711981	KU	6	30 XXX	SP	CRE		V	00:00.0	
2021 PO5514009823	KU	1	70 XXX	SP	CRE		V	00:00.0	
2021 PO5265631855	KU	4	40 UNK	SP	CRE	ED,JD,SRC	TX	RR	00:00.0
2021 PO6181121844	KU	5	35 XXX	SP	CRE	ID	TX	RR	00:00.0



2021	PO6185222288	KU	5	35 XXX	SP	CRE	ID,IP	TX	RR	00:00.0
2021	PO5250532283	KU	2	45 UNK	SP	CRE	ED,ID,SRC	TX	RR	00:00.0
2021	PO4417485732	LGE	1	60 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO5277542565	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TX	RR	00:00.0
2021	PO4427385512	LGE	UNK	45 BRO	SP	A	ED,EP,ID,IP,RB	TX	RR	00:00.0
2021	PO6589223953	KU	5	35 XXX	SP	CRE	ID,IP	TX	RR	00:00.0
2021	PO5266120497	KU	4	40 KOP	SP	P	ED	TX	RR	00:00.0
2021	PO4427885557	LGE	3	50 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO4427885560	LGE	2	50 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO5135008097	KU	5	30 XXX	SP	P	ED,ID,MD,SRC	TX	RR	00:00.0
2021	PO5843002236	KU	4	35 XXX	SP	CRE	ED,HH,ID,RB	TX	RR	00:00.0
2021	PO4456816998	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO4417185610	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO7047706469	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5143817915	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5485308647	KU	4	40 BRO	SP	CRE	ED	TD		00:00.0
2021	PO7080807849	KU	5	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5492008877	KU	3	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO5491008900	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO4294786817	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO5375736374	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4295386810	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO5477426552	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5400705619	KU	5	35 BRO	SP	CRE	ED	TD		00:00.0
2021	PO5408505976	KU	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4418585706	LGE	3	45 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4418985706	LGE	1	55 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4433085497	LGE	5	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6070620265	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO6479519177	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO6855009155	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO6049419407	KU	4	50 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5431509412	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO5422509070	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4481016174	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5352717634	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4201828720	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO6095720792	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5494605037	KU	4	40 BRO	SP	CRE	ED	TD		00:00.0
2021	PO5369517098	KU	4	40 ACW	SP	CRE	ED,ID	TD		00:00.0
2021	PO5361817327	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5358534816	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO5850902162	KU	4	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5468705093	KU	5	35 BRO	SP	CRE	ED	TD		00:00.0
2021	PO4453116699	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4458317177	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4426885574	LGE	3	50 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO6287323281	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO3542514751	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4417385677	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO5343337986	KU	5	35 UNK	SP	CRE	ED,ID,MD	TD		00:00.0
2021	PO5162316320	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO6561723814	KU	5	30 XXX	SP	CRE	ID	TD		00:00.0
2021	PO3787518512	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0

2021 PO4423425899	KU	6	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5461508979	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5460308924	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6205223101	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4413529632	KU	3	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO3894517154	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4317786950	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4317286958	LGE	4	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4315486951	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4330387035	LGE	2	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4311487102	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4323886924	LGE	5	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4307587113	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4306787120	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4320086892	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4322886920	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4311186988	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4305087074	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4324586938	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4311587032	LGE	4	30 ACE	SP	P		BD	00:00.0
2021 PO4319486964	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4318886932	LGE	4	50 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4318486984	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4303086933	LGE	UNK	25 ACE	SP	CRE		VX PX	00:00.0
2021 PO4316487042	F	4	30 ACE	SP	A		V	00:00.0
2021 PO4320686977	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4312787072	F	4	35 ACE	SP	P	ED,ID	VX RP1	00:00.0
2021 PO4264205920	F	4	35 CPT	SP	P		V	00:00.0
2021 PO5472200692	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO3905706722	F	4	40 BRN	SP	P	ED,ID,IP	V	00:00.0
2021 PO4331387068	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX RR	00:00.0
2021 PO4317687100	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX RR	00:00.0
2021 PO4316087112	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX RR	00:00.0
2021 PO4326887073	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO2743880273	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4293487105	LGE	3	50 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4288987111	LGE	3	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4295987102	LGE	3	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4297187101	LGE	3	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4297987099	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4300886939	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4301686932	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4304186913	LGE	4	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4313286926	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4309186875	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4305987009	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4311286898	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4310286887	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8359419243	ODP	6	30 BRN	SP	CRE	ED,SRC	TD	00:00.0
2021 PO8296120281	ODP	6	30 BRN	SP	CRE	ED,SRC,SRS	TD	00:00.0
2021 PO4924788794	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9077323512	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9066223469	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8029720522	ODP	5	35 OTH	SP	CRE	ED,ID,IP,SRC	TD	00:00.0

2021 PO4832889430	LGE	4	40 BRN	SP	CRE	ED,ID,IP,MD	TD	00:00.0
2021 PO8804721784	ODP	4	40 BRO	SP	CRE	ED	TD	00:00.0
2021 PO9201524314	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5476412180	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO8029919274	ODP	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO8574122213	ODP	3	50 UNK	SP	CRE	ED,ID,SR	TD	00:00.0
2021 PO4920688757	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7320319892	ODP	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO8068219384	ODP	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO8594621563	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO8425521249	ODP	2	50 KOP	SP	CRE	ED	TD	00:00.0
2021 PO8701722400	ODP	2	50 UNK	SP	CRE	ID	TD	00:00.0
2021 PO5410911189	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9921635762	ODP	5	35 BRN	SP	CRE	ED,ID,IP,SR	TD	00:00.0
2021 PO4718690022	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9424432551	ODP	4	40 UNK	SP	P	ED,ID	TD	00:00.0
2021 PO7323419779	ODP	6	30 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8923622886	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1082943086	ODP	5	35 KOP	SP	CRE	ED,ID,IP,SR	TD	00:00.0
2021 PO4872088600	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4871388609	LGE	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9444832000	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5150717558	KU	5	45 BRN	SP	CCA		V	00:00.0
2021 PO5229919262	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5216619635	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5218619685	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5198019466	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5182119572A	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4084107382	F	3	40 BRO	SP	CRE		V	00:00.0
2021 PO4106807501	F	3	45 BRO	SP	P		V	00:00.0
2021 PO4090607628	F	3	40 BRO	SP	P		V	00:00.0
2021 PO4072707861	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4004908400	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4013608257	F	3	45 BRO	SP	P		V	00:00.0
2021 PO4021308129	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4035107875	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4018708491	F	2	55 BRO	SP	CCA		V	00:00.0
2021 PO5150217074	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7542507800	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO5251724992	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4503287843	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4499487903	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5715426863	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5740426863	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4397386224	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO5704426949	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5682126917	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4264886991	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4264886989	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4264886979	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4400586123	LGE	2	60 BRO	SP	CCA		V	00:00.0
2021 PO4270186946	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6626825261	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO6619525516	KU	4	40 XXX	SP	CCA		V	00:00.0

2021 PO4918627090	F	5	35 XXX	SP	CRE	ED,ID	V	00:00.0
2021 PO5113420625	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5125320506	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5137420385	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5212220386	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5184120198	F	3	45 UNK	SP	P		V	00:00.0
2021 PO5192420189	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5205820101	F	4	40 UNK	SP	P		V	00:00.0
2021 PO5289325045	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5317824820	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO5340524744	KU	4	45 BRO	SP	S		V	00:00.0
2021 PO4499987889	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4500387886	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5142416410	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO5125116499	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4499687895	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO5236620193	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5360324826	F	4	45 MCM	SP	CCA		V	00:00.0
2021 PO5361924644	F	4	40 MCM	SP	CCA		V	00:00.0
2021 PO5223220006	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5248219769	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5269819602	KU	2	55 BRO	SP	CCA		V	00:00.0
2021 5330519400D	KU	3	40 BRO	SP	CCA		V	00:00.0
2021 PO5364824466	F	4	45 KOP	SP	CRE		V	00:00.0
2021 PO5359124465	F	4	35 ESC	SP	P		V	00:00.0
2021 PO5368324276	F	4	40 ESC	SP	P		V	00:00.0
2021 5330519400C	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 5330519400B	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 5330519400A	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5330519400	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5323619392	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5306619379	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5281919411	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5163919695	KU	3	45 KOP	SP	CCA		V	00:00.0
2021 PO5147819801A	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5147819801	KU	3	45 KOP	SP	CRE		V	00:00.0
2021 PO5136224955	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO5505909488	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5509309462	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5516309417	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5518009431	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5532909380	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5534309375	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5339903894	KU	1	70 BRO	SP	CCA		V	00:00.0
2021 PO5375204798	KU	1	70 BRO	SP	CRE		V	00:00.0
2021 PO5367904606	KU	1	70 BRO	SP	CRE		V	00:00.0
2021 PO5360304397	KU	1	70 BRO	SP	CRE		V	00:00.0
2021 PO0073582379	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4294587034	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5350604166	KU	1	70 BRO	SP	CRE		V	00:00.0
2021 PO5335203777	KU	1	70 BRO	SP	CRE		V	00:00.0
2021 PO5157420026	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5054620452	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 5061520514A	KU	3	50 BRO	SP	CCA		V	00:00.0

2021	PO5061520514	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5074420592	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5087220670	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5097320731	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5100620749	KU	2	55 BRO	SP	CCA		V	00:00.0
2021	PO4873026908	F	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4871126818	F	4	40 XXX	SP	CRE	ED,ID	V	00:00.0
2021	PO4929428047	F	4	40 XXX	SP	CRE	ED,ID,IP	V	00:00.0
2021	PO4925227944	F	4	40 XXX	SP	CRE	ED,ID	V	00:00.0
2021	PO4920627834	F	4	40 XXX	SP	CRE	ED,ID	V	00:00.0
2021	PO4911227618	F	3	45 XXX	SP	CRE		V	00:00.0
2021	PO4906027496	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO4901827396	F	3	45 XXX	SP	P		V	00:00.0
2021	PO4914127452	F	3	45 XXX	SP	P		V	00:00.0
2021	PO4896327268	F	4	40 XXX	SP	CRE	ED,ID,RB	V	00:00.0
2021	PO4956327544	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO4298986727	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PO5560409284	F	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5153119980	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5656112322	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4421285670	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO5524610252	KU	1	70 XXX	SP	CRE		V	00:00.0
2021	PO5531210517	KU	1	70 XXX	SP	CRE		V	00:00.0
2021	PO5536410728	KU	1	70 XXX	SP	CCA		V	00:00.0
2021	PO5542910994	KU	2	70 XXX	SP	CRE		V	00:00.0
2021	PO5546811155	KU	1	75 XXX	SP	CRE		V	00:00.0
2021	PO5561711759	KU	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5556011536	KU	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5551711358	KU	1	70 XXX	SP	CRE		V	00:00.0
2021	PO5666112757	KU	2	60 UNK	SP	CRE		V	00:00.0
2021	PO5577213976	KU	4	45 UNK	SP	CCA		V	00:00.0
2021	PO5450910443	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5516609815	KU	3	50 XXX	SP	S		V	00:00.0
2021	PO5525909782	KU	3	45 XXX	SP	S		V	00:00.0
2021	PO5575909604	KU	2	50 XXX	SP	S		V	00:00.0
2021	PO4257187156	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PV9700083581	LGE	1	65 ACE	SP	CCA		V	00:00.0
2021	PO5344839863	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5336640185	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5329240815	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5335040459	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5321041115	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5530909763	KU	3	45 XXX	SP	S		V	00:00.0
2021	PO5544109717	KU	4	45 XXX	SP	S		V	00:00.0
2021	PO5459710409	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5468310613	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO5554909675	KU	3	50 XXX	SP	S		V	00:00.0
2021	PO5586409569	KU	2	50 XXX	SP	S		V	00:00.0
2021	PO4252787188	LGE	1	60 ACE	SP	CRE		V	00:00.0
2021	PO4252287151	LGE	1	55 ACE	SP	CRE		V	00:00.0
2021	PO4252087139	LGE	1	55 ACE	SP	CRE		V	00:00.0
2021	PO5365111160	KU	3	45 XXX	SP	S		V	00:00.0
2021	PO5295909959	KU	2	50 XXX	SP	S		V	00:00.0
2021	PO5165807921	F	3	45 XXX	SP	CRE		V	00:00.0

2021 PO4252787347	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO5290043158	F	4	35 BRO	SP	P	V	00:00.0
2021 PO5300043172	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO5323815353	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO5270530310	F	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5235830442	KU	4	40 KOP	SP	CCA	V	00:00.0
2021 PO5270730547	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5270530435	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO4402686061	F	2	65 BRO	SP	A	V	00:00.0
2021 PO4403186060	F	3	50 BRO	SP	A	V	00:00.0
2021 PO4637022674	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4654422668	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4704522424	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4676122660	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4697822655	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4269786948	LGE	1	75 ACE	SP	CRE	V	00:00.0
2021 PO5874312067	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5886512017	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5902011950	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5915511892	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5929011834	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5943511771	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5960011701	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5813412264	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5274930125	F	4	40 XXX	SP	CCA	V	00:00.0
2021 PO4855320592	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO5235229731	KU	4	40 XXX	ST	CRE	V	00:00.0
2021 PO5256429798	KU	4	40 BRO	ST	CRE	V	00:00.0
2021 PO6397525202	KU	3	45 XXX	SP	CRE	V	00:00.0
2021 PO4407521120	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4854020321	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4132818518	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO4271587035	LGE	2	50 ACE	SP	CRE	V	00:00.0
2021 PO4271387061	LGE	1	70 ACE	SP	CRE	V	00:00.0
2021 PO4271087048	LGE	1	70 ACE	SP	CRE	V	00:00.0
2021 PO3902117379	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO4242329741	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5867001562	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5864101711	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5428734166	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5433834527	KU	4	45 BRO	SP	CCA	V	00:00.0
2021 PO5869501436	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5872801435	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5859201819	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5284733519	F	4	40 UNK	SP	P	V	00:00.0
2021 PO5297433844	F	4	40 UNK	SP	P	V	00:00.0
2021 PO7036608347	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO7088508271	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO7062308040	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5446908597	KU	3	45 XXX	SP	S	V	00:00.0
2021 PO6360823581	KU	6	30 XXX	SP	CCA	V	00:00.0
2021 PO6362623689	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 PO5504605957	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO6199822475	KU	4	40 XXX	SP	CCA	V	00:00.0

2021	PO5216333014	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5255532788	F	4	40 UNK	SP	P		V	00:00.0
2021	PO5265433032	F	4	40 UNK	SP	P		V	00:00.0
2021	PO5275033271	F	4	40 UNK	SP	P		V	00:00.0
2021	PO6252821771	KU	5	30 XXX	SP	CCA		V	00:00.0
2021	PO6179022604	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO6167522429	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO3997508250	F	2	50 BRO	SP	S		V	00:00.0
2021	PO4004508131	F	2	50 BRO	SP	CCA		V	00:00.0
2021	PO4010307803	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4020207864	F	3	50 BRO	SP	CCA		V	00:00.0
2021	PO4027307741	F	2	50 BRO	SP	CCA		V	00:00.0
2021	PO6176621506	KU	6	30 XXX	SP	CCA		V	00:00.0
2021	PO6180921735	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO5297805732	F	2	50 BRO	SP	CRE		V	00:00.0
2021	PO5312605667	F	2	50 BRO	SP	CRE		V	00:00.0
2021	PO5327005605	F	2	50 BRO	SP	CRE		V	00:00.0
2021	PO5341705543	F	2	50 BRO	SP	CRE		V	00:00.0
2021	PO5320035256	KU	6	30 XXX	UN	CRE		V	00:00.0
2021	PO5411519994	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5392020180	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5248332616	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5384220257	KU	3	45 BRN	SP	CRE		V	00:00.0
2021	PO6119821296	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO6096821375	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO6073621451	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO6047021621	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO6022521775	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO6042621956	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO6056722098	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO6419823660	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO6427323581	KU	6	30 XXX	SP	CCA		V	00:00.0
2021	PO6419823660A	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5388804769	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO5405204605	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5511434029	KU	4	45 BRO	SP	CRE		V	00:00.0
2021	PO5510334228	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO5492234057	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4407586230	LGE	4	35 BRO	SP	A		V	00:00.0
2021	PO4408886236	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4407986246	LGE	4	40 BRO	SP	P		V	00:00.0
2021	PO4406086261	LGE	4	30 BRO	SP	A		V	00:00.0
2021	PO4404786261	LGE	4	30 BRO	SP	A		V	00:00.0
2021	PO5416905531	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5462207552	KU	1	75 XXX	SP	CRE		V	00:00.0
2021	PO5472208021	KU	2	60 XXX	SP	CRE		V	00:00.0
2021	PO5477208241	KU	2	65 XXX	SP	CRE		V	00:00.0
2021	PO5478909388	KU	3	45 XXX	SP	S		V	00:00.0
2021	PO5461209321	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5455409315	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO4872418173	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4884317942	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO6535223941	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5447813940	F	2	60 XXX	SP	CCA		V	00:00.0

2021 PO5442113912	KU	5	35 XXX	SP	CCA			V	00:00.0
2021 PO5433714113	F	4	40 XXX	SP	P			V	00:00.0
2021 PO4437828872	KU	4	40 BRN	SP	CCA			V	00:00.0
2021 PO4766325496	F	4	40 XXX	SP	CRE		ED	V	00:00.0
2021 PO4756525586	F	4	40 XXX	SP	CRE		ED	V	00:00.0
2021 PO5283309490	KU	6	30 BRN	SP	S			V	00:00.0
2021 PO5277709575	KU	4	40 BRN	SP	CCA			V	00:00.0
2021 PO5273109442	KU	3	45 BRN	SP	CCA			V	00:00.0
2021 PO5278509604	F	4	40 KOP	SP	P			V	00:00.0
2021 PO5287309634	KU	2	50 BRN	SP	CCA			V	00:00.0
2021 PO5283209652	KU	3	45 BRN	SP	CCA			V	00:00.0
2021 PO5277109688	KU	3	45 BRN	SP	CCA			V	00:00.0
2021 PO1162357929	KU	5	35 BRN	SP	CRE		ID	TD	00:00.0
2021 PO1150758089	KU	4	40 BRN	SP	CCA			T	00:00.0
2021 PO1152658253	KU	4	40 BRN	SP	CRE		ID	TD	00:00.0
2021 PO0864953281	KU	4	40 BRN	SP	CRE		ID	TD	00:00.0
2021 PO4451987870	LGE	4	40 BRO	SP	A		ED,ID,IP	TD	00:00.0
2021 PO8355278532	F	4	40 ACE	SP	CRE		ED,ID	V	00:00.0
2021 PO8361078530	F	4	40 ACE	SP	CRE		ED,ID	V	00:00.0
2021 PO8343678540	F	4	40 ACE	SP	CCA			V	00:00.0
2021 PO8207680516	KU	6	30 ACE	SP	CRE			V	00:00.0
2021 PO8391468990	ODP	5	35 XXX	SP	CCA		ED	T	00:00.0
2021 PO8361962263	ODP	5	35 BRN	SP	CRE		ED,EP,HH,ID	X	RP1 00:00.0
2021 PO8355562443	ODP	4	40 BRN	SP	CRE		ED,ID	TD	00:00.0
2021 PO4495288110	LGE	4	40 ACE	SP	A		ED,ID	TD	00:00.0
2021 PO4494788122	LGE	4	30 ACE	SP	A		ED,ID	BD	00:00.0
2021 PO8412569192	ODP	4	40 XXX	SP	CRE		ID	TD	00:00.0
2021 PO8434369011	ODP	5	35 XXX	SP	CRE		ID	TD	00:00.0
2021 PO8489569285	ODP	4	45 XXX	SP	CRE		ID	TD	00:00.0
2021 PO8491968785	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO8510368915	ODP	6	35 XXX	SP	CRE		ID	TD	00:00.0
2021 PO8474768401	ODP	4	45 XXX	SP	CCA			V	00:00.0
2021 PO8477768671	ODP	4	40 XXX	SP	CRE		ID	TD	00:00.0
2021 PO8504268437	ODP	6	35 XXX	SP	CRE		ID	TD	00:00.0
2021 PO8596767196	F	6	30 XXX	SP	CCA			V	00:00.0
2021 PO4494688119	LGE	4	40 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO4494188127	LGE	4	40 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO5960626931	KU	5	35 UNK	SP	CRE			T	00:00.0
2021 PO4494188139	LGE	4	30 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO4493888132	LGE	4	40 ACE	SP	A		ED,ID	BD	00:00.0
2021 PO4493588137	LGE	4	40 ACE	SP	CRE		ED,ID	BD	00:00.0
2021 PO5958527028	KU	5	35 UNK	SP	CRE			BD	00:00.0
2021 PO5966726937	KU	5	35 UNK	SP	CRE			T	00:00.0
2021 PO5699921481	KU	6	30 UNK	SP	CRE		ID	TD	00:00.0
2021 PO8374862202	ODP	5	35 BRN	SP	S			V	00:00.0
2021 PO8375162596	ODP	5	35 BRN	SP	S			V	00:00.0
2021 PO8372562173	ODP	4	45 BRN	SP	S			V	00:00.0
2021 PO8378362002	ODP	4	45 BRN	SP	S			V	00:00.0
2021 PO8374161905	ODP	3	45 BRN	SP	S			V	00:00.0
2021 PO8374561808	F	6	30 BRN	SP	P			V	00:00.0
2021 PO8383861767	ODP	4	45 BRN	SP	S			V	00:00.0
2021 PO8383861767C	ODP	4	40 BRN	SP	S			V	00:00.0
2021 PO8383861767B	ODP	4	40 BRN	SP	S			V	00:00.0
2021 PO8383861767A	ODP	4	40 BRN	SP	S			V	00:00.0



2021	PO8400461626	ODP	4	45 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO8412461722	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO8452761492	F	4	40 BRN	SP	P		V		00:00.0
2021	PO9338853600	ODP	4	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO9322853462	ODP	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4491888148	LGE	1	90 ACE	SP	CRE		V		00:00.0
2021	PO5266609702	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4471887979	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4810211961	F	4	40 XXX	SP	P	ED,EP,HH,ID,IP	BX	PX	00:00.0
2021	PO4839712246	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5971526883	KU	5	35 UNK	SP	CRE		BD		00:00.0
2021	PO4492888147	LGE	1	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4493588147	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021	PO4445988184	F	4	40 BRO	SP	P		V		00:00.0
2021	PO4445688200	F	4	40 BRO	SP	P		V		00:00.0
2021	PO5974726952	KU	5	35 UNK	SP	CRE	ED,ID	BX	PX	00:00.0
2021	PO4493188144	LGE	4	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO5969527003	KU	4	40 UNK	SP	CRE	ED,ID	BX	RP3	00:00.0
2021	PO5964027057	KU	4	45 UNK	SP	CRE	ED,ID	BX	PX	00:00.0
2021	PO5696021375	KU	4	45 BRO	SP	CCA		V		00:00.0
2021	PO5694121387	KU	4	40 BRO	SP	S		V		00:00.0
2021	PO4471187975	LGE	4	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4471387970	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO8333478546	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO8323278550	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO8312178556	F	5	35 ACE	SP	CRE		V		00:00.0
2021	PO8302878561	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO8296278565	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO8283578570	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO8273178577	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO8262378584	F	4	40 ACE	SP	P		V		00:00.0
2021	PO8257478588	F	4	40 ACE	SP	P		V		00:00.0
2021	PO8257878734	F	6	30 ACE	SP	CRE		V		00:00.0
2021	PO5958027122	KU	5	35 UNK	SP	CRE		BD		00:00.0
2021	PO5954727157	KU	5	35 UNK	SP	CRE		BD		00:00.0
2021	PO5947627233	KU	5	35 UNK	SP	CRE	ED,ID	BX	RP3	00:00.0
2021	PO5948827127	KU	3	45 UNK	SP	CCA		V		00:00.0
2021	PO5956827044	KU	4	45 UNK	SP	CRE	ED,ID	BX	RP3	00:00.0
2021	PO4486088146	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4486488139	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4487188129	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO5718021287	KU	6	30 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5719021256	KU	3	45 BRO	SP	CRE	ID	BD		00:00.0
2021	PO5729321252	KU	3	45 BRO	SP	S		V		00:00.0
2021	PO5262809716	F	5	35 XXX	SP	P		V		00:00.0
2021	PO4446688208	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5737021227	KU	6	30 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5742721210	KU	6	30 UNK	SP	CRE	ID	BD		00:00.0
2021	PO5779320948	F	2	55 CPT	SP	P		V		00:00.0
2021	PO5768220980	F	2	55 CPT	SP	P		V		00:00.0
2021	PO5765520987	KU	2	55 MAR	SP	P		V		00:00.0
2021	PO5761420999	F	2	55 MAR	SP	CCA		V		00:00.0
2021	PO5752921022	F	2	50 CPT	SP	P		V		00:00.0
2021	PO5744221046	F	4	40 CPT	SP	CRE		V		00:00.0

2021	PO5729521090	F	4	40 CPT	SP	P		V	00:00.0
2021	PO5713621133	F	2	60 CPT	SP	P		V	00:00.0
2021	PO5682221277	KU	3	45 UNK	SP	S		V	00:00.0
2021	PO5697821200	F	2	55 UNK	SP	CRE		V	00:00.0
2021	PO5688121251	F	2	55 UNK	SP	P		V	00:00.0
2021	PO5701221231	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5694321083	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5699420967	KU	2	40 BRO	SP	CCA		V	00:00.0
2021	PO5706320980	KU	6	30 KOP	SP	CCA		V	00:00.0
2021	PO5703620885	KU	6	30 KOP	SP	CCA		V	00:00.0
2021	PO5695420836	KU	3	45 BRO	SP	CRE	ID	BD	00:00.0
2021	PO5692820757	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5690120665	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO4488488108	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5259709728	F	4	45 KOP	SP	P		V	00:00.0
2021	PO4472187975	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO5942027201	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021	PO5943927273	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO4445888193	F	4	40 BRO	SP	P		V	00:00.0
2021	PO4445688206	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO5945427396	KU	2	55 UNK	SP	CCA		V	00:00.0
2021	PO5941127354	KU	2	60 UNK	SP	CCA		V	00:00.0
2021	PO5953327364	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021	PO8281878555	F	4	40 ACE	SP	P		V	00:00.0
2021	PO8281378450	F	4	40 ACE	SP	P		V	00:00.0
2021	PO5240109794	F	4	45 KOP	SP	P		V	00:00.0
2021	PO5252409752	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5253209778	F	5	30 XXX	SP	CRE		V	00:00.0
2021	PO5257409900	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5261010013	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5259510143	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4445288232	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4446088250	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4487888118	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4488788104	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4489388096	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO8280878332	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8280178226	F	4	40 ACE	SP	P		V	00:00.0
2021	PO8274978160	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO8279678098	F	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8277777979	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8277577911	KU	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8276977811	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8276477709	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8280677671	F	4	40 ACE	SP	P		V	00:00.0
2021	PO8276077581	F	5	35 ACE	SP	CRE		V	00:00.0
2021	PO5962227350	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021	PO5958727521	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO4444688204	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4444588199	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021	PO4445288232-A	F	4	35 BRO	SP	P		V	00:00.0
2021	PO4442788240	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4443988243	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO4444988242	LGE	4	35 BRO	SP	P	ED,ID,IP	BD	00:00.0

2021 PO4444788244	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4446088246	LGE	3	50 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4446688251	LGE	4	40 BRO	SP	CRE	ED,ID	BX PX	00:00.0
2021 PO4448388250	LGE	3	45 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4447388253	F	5	30 BRO	SP	CRE		V	00:00.0
2021 PO4448088253	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO5969927330	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO4489788090	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4490088084	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4490388081	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4491088064	LGE	4	45 ACE	SP	A	ED	V	00:00.0
2021 PO4490888073	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4472487970	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO0865453409	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0866153529	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0902753612	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0941353732	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5952927624	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO4472887963	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4472687961	LGE	4	30 BRO	SP	A	ID	BD	00:00.0
2021 PO8207478200	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5218010276	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5955227678	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO5957227505	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO5955827491	KU	2	50 UNK	UN	CCA		V	00:00.0
2021 PO5960427538	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5964427577	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO5968527617	KU	1	60 UNK	SP	CCA		V	00:00.0
2021 PO5965527645	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO5961527685	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5962927671	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO4485188313	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4471587940	LGE	7	25 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8208878381	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8190578899	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8187078972	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8201479241	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8191079576	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8181280041	KU	6	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8247077714	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4484788316	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5957627719	KU	2	40 UNK	SP	CRE		BD	00:00.0
2021 PO4486688309	LGE	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4487688306	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4488988303	LGE	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4472087943	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5964327470	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5968627453	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021 PO5969627527	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5974027562	KU	3	45 UNK	SP	CRE		BD	00:00.0
2021 PO4472987949	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5227210249	F	5	30 XXX	SP	CRE		V	00:00.0
2021 PO5248110181	F	5	30 XXX	SP	CRE		V	00:00.0
2021 PO5236110219	F	4	40 XXX	SP	CRE		V	00:00.0

2021	PO5232610121	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5228710009	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO4490188299	LGE	4	40 ACE	SP	CRE		ED	V	00:00.0	
2021	PO4490688298	LGE	4	40 ACE	SP	CCA		ED	V	00:00.0	
2021	PO4474587939	LGE	4	40 BRO	SP	A		ED,ID	TD	00:00.0	
2021	PO4490988311	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO0957153706	KU	3	45 BRN	SP	CCA			V	00:00.0	
2021	PO4490988300	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4490888290	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4490888278	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO0945753796	KU	5	35 BRN	SP	CCA			V	00:00.0	
2021	PO0939754156	KU	3	45 BRN	SP	CCA			V	00:00.0	
2021	PO0927954249	KU	5	35 BRN	SP	CCA			V	00:00.0	
2021	PO1032852964	KU	4	45 BRN	SP	CCA			V	00:00.0	
2021	PO1025653208	KU	6	30 BRN	SP	CRE			V	00:00.0	
2021	PO9422458206	F	4	40 SWP	SP	P			V	00:00.0	
2021	PO9438158181	F	4	40 SWP	SP	P			V	00:00.0	
2021	PO5800722179	F	5	40 UNK	SP	CRE			V	00:00.0	
2021	PO5206912064	F	4	40 XXX	SP	CRE		ED,ID,RB	BX	PX	00:00.0
2021	PO8445763306	ODP	4	40 XXX	SP	CRE		ID	TD	00:00.0	
2021	PO8447663175	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO8439263197	ODP	6	30 XXX	SP	CRE		ID	TD	00:00.0	
2021	PO8467263331	ODP	4	40 XXX	SP	CRE		ID	TD	00:00.0	
2021	PO7898361872	ODP	5	35 BRN	SP	CRE		ED,ID	TD	00:00.0	
2021	PO7892161942	ODP	4	40 BRN	SP	CRE		ED,ID	BD	00:00.0	
2021	PO7879961972	ODP	4	40 BRN	SP	CRE		ED,ID	TD	00:00.0	
2021	PO7902662121	ODP	4	40 BRN	SP	CRE		ED,ID	TD	00:00.0	
2021	PO7883061740	ODP	4	40 BRN	SP	CRE		ED,ID,IP	TD	00:00.0	
2021	PO8463979788	F	4	40 ACE	SP	CRE		ED,ID	V	00:00.0	
2021	PO8465679845	F	5	35 ACE	SP	CRE			V	00:00.0	
2021	PO8455479823	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO8440379762	KU	6	30 ACE	SP	CRE			V	00:00.0	
2021	PO8439279866	F	6	30 ACE	SP	CRE			V	00:00.0	
2021	PO8444279911	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO8430479914	F	4	40 ACE	SP	P			V	00:00.0	
2021	PO8416579917	F	4	40 ACE	SP	P			V	00:00.0	
2021	PO8402279920	F	4	40 ACE	SP	P			V	00:00.0	
2021	PO4507688134	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4508188127	LGE	4	40 ACE	SP	CRE		ED,ID	BD	00:00.0	
2021	PO4508388123	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4508988113	LGE	4	40 ACE	SP	CCA			V	00:00.0	
2021	PO4509688102	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4510488157	LGE	3	50 ACE	SP	CCA			V	00:00.0	
2021	PO5145010918	F	4	40 BRO	SP	CRE			V	00:00.0	
2021	PO5148911055	F	4	40 BRO	SP	CRE			V	00:00.0	
2021	PO4444787857	LGE	4	35 BRO	SP	CRE		ED,ID,IP	TD	00:00.0	
2021	PO4445387850	LGE	4	40 BRO	SP	A		ED,ID,IP	TD	00:00.0	
2021	PO5158711019	F	4	40 BRN	SP	S			V	00:00.0	
2021	PO5171510601	F	4	40 KOP	SP	CRE			V	00:00.0	
2021	PO6068728466	KU	4	50 UNK	SP	CRE			BD	00:00.0	
2021	PO6061628395	KU	2	50 UNK	SP	CRE			BD	00:00.0	
2021	PO6055528446	KU	4	40 UNK	SP	CRE			T	00:00.0	
2021	PO6067128558	F	4	40 UNK	SP	CRE			V	00:00.0	
2021	PO6056528482	F	4	40 UNK	SP	CRE			V	00:00.0	

2021 PO6052628416	F	4	40 UNK	SP	CCA		V	00:00.0
2021 PO6048828370	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO6055128333	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO6044228333	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO0670950880	KU	5	35 KOP	SP	CRE	ID	TD	00:00.0
2021 PO4432788268	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4509088178	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4508188191	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO0665050882	KU	3	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO0500148559	F	5	35 KOP	SP	CRE		V	00:00.0
2021 PO4432888273	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4432188277	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4449988006	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4450588009	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4451088012	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4452388011	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4452988015	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4451888016	LGE	4	40 BRO	UN	CRE		V	00:00.0
2021 PO4451988016	LGE	4	40 BRO	UN	CRE		V	00:00.0
2021 PO4450987811	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4507388204	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4451087814	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6144927153	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO6145927234	F	3	45 UNK	SP	CRE	ED,ID	VX PX	00:00.0
2021 PO6133127370	KU	5	35 UNK	SP	CRE		BD	00:00.0
2021 PO6129127416	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO4507688225	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO0505948542	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO6135027469	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021 PO5179310955	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5177010779	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5183010780	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5189010734	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4451087827	LGE	5	25 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO6142627642	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021 PO6143827555	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO6149227499	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO4450687824	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4506788220	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4506488217	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO0513848771	KU	5	35 KOP	SP	CRE	ID	TD	00:00.0
2021 PO0535748887	KU	4	45 KOP	SP	CCA		T	00:00.0
2021 PO4450087835	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4449487843	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4505788230	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4506188229	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO0531548975	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4505188244	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO0537549026	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0540649114	KU	6	30 BRN	SP	CCA		T	00:00.0
2021 PO0548149027	KU	4	45 INP	SP	CRE	ID	TD	00:00.0
2021 PO4504088262	LGE	4	25 ACE	SP	CRE	ED	V	00:00.0
2021 PO2112095213	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4502988278	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0

2021	PO0483748115	KU	4	40 INP	SP	CRE	ID	TD		00:00.0
2021	PO4452188016	LGE	3	45 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4451888022	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4451488031	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4451088040	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4450688050	LGE	3	45 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4450188061	LGE	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4449788069	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4449388079	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4449088087	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4448688095	LGE	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4448388103	LGE	4	40 BRO	SP	P	ED	BX	RP2	00:00.0
2021	PO4448288105	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4447788116	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4447388125	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4446988135	LGE	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO4446888138	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4446488147	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4450188181	F	4	30 BRO	SP	CRE		V		00:00.0
2021	PO4449988191	F	4	35 BRO	SP	CRE		V		00:00.0
2021	PO4448887852	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO5198510510	F	4	40 KOP	SP	CRE	ED,RB	BX	RP3	00:00.0
2021	PO5204510370	F	4	40 BRO	SP	P		V		00:00.0
2021	PO5214310848	F	5	35 BRO	SP	CRE		V		00:00.0
2021	PO5211210912	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO5214311009	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4448287859	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO4447787867	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4447187875	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4446487883	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5217011106	F	4	40 BRO	SP	P		V		00:00.0
2021	PO1547990996	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4443187899	LGE	4	30 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4443587877	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4443187887	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO0495348431	KU	3	50 INP	SP	CRE	ID	TD		00:00.0
2021	PO0488548356	KU	4	40 INP	SP	CRE	ID	TD		00:00.0
2021	PO4442887898	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO0528051023	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4475288257	F	4	35 BRN	SP	A		V		00:00.0
2021	PO4475288229	F	4	35 BRN	SP	P		V		00:00.0
2021	PO4579988242	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4503788195	F	4	35 BRN	SP	CRE		V		00:00.0
2021	PO0521748726	KU	4	45 KOP	SP	CRE	ID	TD		00:00.0
2021	PO6179729109	KU	4	40 UNK	SP	CRE		T		00:00.0
2021	PO0477648234	KU	4	40 BRO	SP	CRE	ID	TD		00:00.0
2021	PO0483348448	KU	4	40 INP	SP	CRE	ID	TD		00:00.0
2021	PO5684319793	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021	PO8526568235	ODP	4	45 XXX	SP	CCA		V		00:00.0
2021	PO8535868454	ODP	6	30 XXX	SP	CCA		V		00:00.0
2021	PO4490788267	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4490788255	LGE	4	35 ACE	SP	CCA	ED,ID	BD		00:00.0
2021	PO4490688244	LGE	3	45 ACE	SP	P	ED,ID,MD	TD		00:00.0
2021	PO4494888203	LGE	4	35 ACE	SP	CRE	ED,ID	BD		00:00.0

2021	PO4496688171	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4497288171	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO8554468540	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8537868422	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8501668065	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8517068008	ODP	6	30 XXX	SP	CRE	HH,ID,RB	TX	RR	00:00.0
2021	PO8522267997	ODP	4	40 XXX	SP	CCA		V	00:00.0	
2021	PO8533668117	ODP	4	45 XXX	SP	CCA		V	00:00.0	
2021	PO8542968219	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8542268120	ODP	6	30 XXX	SP	CCA		V	00:00.0	
2021	PO8566368340	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8544067931	ODP	4	40 XXX	SP	CCA		V	00:00.0	
2021	PO8551267802	ODP	4	45 XXX	SP	CCA		V	00:00.0	
2021	PO8559967665	ODP	5	35 XXX	SP	CRE	ID	BD	00:00.0	
2021	PO8567767524	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8490767312	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8508767430	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8555067142	ODP	4	40 XXX	SP	CCA		V	00:00.0	
2021	PO8575267393	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8611867210	ODP	5	35 XXX	SP	CCA		V	00:00.0	
2021	PO8609967213	ODP	5	35 XXX	SP	CCA		V	00:00.0	
2021	PO8619467050	F	5	35 XXX	SP	P		V	00:00.0	
2021	PO8627566931	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8605166955	ODP	4	45 XXX	SP	CCA		V	00:00.0	
2021	PO8619766757	ODP	4	40 XXX	SP	CCA		V	00:00.0	
2021	PO8647466920	ODP	4	45 XXX	SP	CCA		V	00:00.0	
2021	PO8650466797	ODP	4	45 XXX	SP	CCA		V	00:00.0	
2021	PO8660066644	ODP	4	45 XXX	SP	CCA		V	00:00.0	
2021	PO8644366182	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8638566516A	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO8638566516	ODP	2	55 XXX	SP	CCA		V	00:00.0	
2021	PO5686019823	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO5696019798	KU	4	45 BRO	SP	CCA		V	00:00.0	
2021	PO5692819857	F	3	50 BRO	SP	P		V	00:00.0	
2021	PO5693519878	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021	PO5702219831	F	3	45 MAR	SP	P		V	00:00.0	
2021	PO5706719835	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0	
2021	PO5719819781	F	3	50 CPT	SP	P		V	00:00.0	
2021	PO5717519809	KU	2	40 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO5731119825	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO5737119735	F	3	50 CPT	SP	P		V	00:00.0	
2021	PO5743919716	F	3	45 BRO	SP	P		V	00:00.0	
2021	PO5679519816	KU	3	50 BRO	SP	CCA		V	00:00.0	
2021	PO4497288181	LGE	4	40 ACE	SP	A	ED,ID,RB	TX	RR	00:00.0
2021	PO4496688181	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0	
2021	PV1553395159	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4446888281	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PV1552895026	LGE	4	35 BRO	SP	P	ED,EP,ID,IP	BD	00:00.0	
2021	PO4447088271	LGE	4	35 BRO	SP	P	ED,ID,IP	BD	00:00.0	
2021	PO4443588263	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0	
2021	PO4496788187	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0	
2021	PO5217110075	F	5	35 XXX	SP	CRE		V	00:00.0	
2021	PO5222209954	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO5224909890	F	4	40 XXX	SP	CRE		V	00:00.0	

2021	PO5225909839	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5211309888	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO9359454063	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO9364053896	ODP	4	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO9388754204	ODP	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO9320653240	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO9483353638	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO9434453765	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4474187927	F	4	35 BRO	SP	CRE		V		00:00.0
2021	PO5678219899	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO8233277415	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO8232877382	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO8232977400	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO8227377328	F	3	50 ACE	SP	P		V		00:00.0
2021	PO5677719843	KU	3	50 BRO	SP	CCA		V		00:00.0
2021	PO5671019862	KU	3	50 BRO	SP	CCA		V		00:00.0
2021	PO5654019976	F	4	40 BRO	SP	CRE		B		00:00.0
2021	PO5652319914	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021	PO5642719943	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021	PO5637120019	F	5	30 UNK	SP	S		B		00:00.0
2021	PO5620619992	KU	1	50 UNK	SP	P	ID	TD		00:00.0
2021	PO8379077401	KU	3	50 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO8379177417	KU	3	50 ACE	SP	CCA		V		00:00.0
2021	PO4455487833	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4474087935	LGE	4	40 BRO	SP	CRE	ID,RB	X	RP1	00:00.0
2021	PO4475287927	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5197909933	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5188709964	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4497388191	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4443688278	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO1104753025	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021	PO1091152992	KU	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021	PO1070052963	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021	PO1049552969	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021	PO4442788277	LGE	3	45 BRO	SP	P	ED,ID	TD		00:00.0
2021	PO5974927682	KU	5	35 UNK	SP	CRE		T		00:00.0
2021	PO5175510010	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4474987933	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4475587938	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO5980527632	KU	2	45 UNK	SP	CRE		BD		00:00.0
2021	PO4442288276	LGE	3	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO1511895107	LGE	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4439888279	LGE	4	40 BRO	SP	P	ED,ID,SR	TD		00:00.0
2021	PO4440688273	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4439088278	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021	PO4439688282	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021	PO4437688251	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4436988251	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO5989727725	KU	5	35 UNK	SP	CCA		BD		00:00.0
2021	PO5986427688	KU	4	40 UNK	SP	CRE	ED,ID	BX	PX	00:00.0
2021	PO5985927581	KU	5	35 UNK	UN	CRE		V		00:00.0
2021	PO5974027668	KU	4	40 UNK	SP	CCA		V		00:00.0
2021	PO5984127761	KU	6	30 UNK	SP	CRE		BD		00:00.0
2021	PO4496788196	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0



2021 PO4497388196	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5165610044	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5172610020	F	4	40 KOP	SP	P		V		00:00.0
2021 PO4475587965	LGE	3	45 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4496888201	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4496888205	LGE	4	30 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4473687953	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO5145611336	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4497488204	LGE	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO6020727744	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO1029453160	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO6037627981	KU	4	40 UNK	SP	CRE		T		00:00.0
2021 PO6045528054	KU	2	50 UNK	SP	CCA		V		00:00.0
2021 PO6104529186	KU	6	30 UNK	SP	CRE		T		00:00.0
2021 PO1034253306	KU	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO4496888215	LGE	4	35 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO8233877592	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8232777540	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8231177695	KU	3	50 ACE	SP	CCA		V		00:00.0
2021 PO8229577854	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8227678021	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO1008653135	KU	6	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO5631819979	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021 PO5627119854	KU	5	35 UNK	SP	CRE	ID	TD		00:00.0
2021 PO5665919945	KU	2	50 UNK	SP	CCA		V		00:00.0
2021 PO9768196922	KU	3	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PV4387385016	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4386185108	LGE	4	30 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO9311100582	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO9317998683	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO4422186070	LGE	3	45 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO4381285175	LGE	3	45 ACE	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO2556119547	KU	4	40 BRN	SP	CRE	ED,ID,SR	TX	RR	00:00.0
2021 PO4414085979	LGE	3	45 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO2890219177	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO9669596098	KU	4	40 UNK	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO4379084950	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4436685699	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO8896798187	KU	3	45 XXX	SP	S		V		00:00.0
2021 PO8756002208	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8766402071	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8767602091	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8755301955	KU	2	60 BRO	SP	CCA		V		00:00.0
2021 PO8741301808	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8744201837	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8061311997A	KU	3	40 BRN	SP	CCA		V		00:00.0
2021 PO8056011986A	KU	3	40 BRN	SP	CCA		V		00:00.0
2021 PO8042112042A	F	3	40 BRN	SP	P		V		00:00.0
2021 PO8092012036A	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO8076612016A	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO8205312206	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5410802743	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO2555420304	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO2540520252	KU	5	35 BRN	SP	CCA		V		00:00.0

2021	PO5395802810	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO2565819925	F	5	40 BRN	SP	CCA	V	00:00.0
2021	PO2561920065	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO2589920283	KU	4	45 BRN	SP	CCA	V	00:00.0
2021	PO8608203502	F	3	45 CPT	SP	CCA	V	00:00.0
2021	PO8611803466	F	3	45 UNK	SP	CCA	V	00:00.0
2021	PO8605603528	F	3	45 CPT	SP	CCA	V	00:00.0
2021	PO8595603434	F	3	45 CPT	SP	CCA	V	00:00.0
2021	PO2632722036	KU	4	40 BRN	SP	CCA	V	00:00.0
2021	PO2645522017	KU	4	40 BRN	SP	CCA	V	00:00.0
2021	PO9752497403	KU	5	35 XXX	SP	S	V	00:00.0
2021	PO2568919815	F	4	40 BRN	SP	A	V	00:00.0
2021	PO2553419907	KU	6	30 BRN	SP	CCA	V	00:00.0
2021	PO8629403374	F	3	45 BRO	SP	CCA	V	00:00.0
2021	PO8638703402	F	3	45 BRO	SP	CCA	V	00:00.0
2021	PO8635803393	F	3	45 CPT	SP	CCA	V	00:00.0
2021	PO8648303303	F	3	45 BRO	SP	P	V	00:00.0
2021	PO8651203330	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO8656903402	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO8623103354	F	3	50 CPT	SP	CCA	V	00:00.0
2021	PO8255311204	KU	1	45 BRN	SP	CCA	V	00:00.0
2021	PO2566922127	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO4436685688	LGE	2	55 BRO	SP	CCA	V	00:00.0
2021	PO4389985208	F	4	35 ACE	SP	A	V	00:00.0
2021	PO4387885235	F	4	35 ACE	SP	CRE	V	00:00.0
2021	PO4389185217	F	4	35 ACE	SP	A	V	00:00.0
2021	PO1527869529	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021	PO4389485226	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021	PO4389785222	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO2531821957	F	4	40 BRN	SP	A	V	00:00.0
2021	PO2555921924	F	4	40 BRN	SP	A	V	00:00.0
2021	PO2580221891	F	4	40 BRN	SP	A	V	00:00.0
2021	PO5630501551	KU	3	40 ACE	SP	CCA	V	00:00.0
2021	PO2488021432	KU	3	50 BRN	SP	CCA	V	00:00.0
2021	PO8779301968	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO8775802012	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO8777702040	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO8745302317	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4379084795	LGE	4	30 ACE	SP	P	V	00:00.0
2021	PO4378984772	LGE	4	30 ACE	SP	CRE	V	00:00.0
2021	PO5787699712	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO2705319225	KU	2	60 BRN	SP	CRE	V	00:00.0
2021	PO2647922447	KU	4	40 BRN	SP	CCA	V	00:00.0
2021	PO2647919418	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021	PO2681219307	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021	PO2781918963	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021	PO2842018766	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021	PO2865818689	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021	PO2892518600	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021	PO5822599806	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5820499659	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO9740895049	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO9734995085	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5813299392	F	4	40 ACE	SP	CRE	V	00:00.0

2021 P08245611308	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 P09700894234	KU	3	45 UNK	SP	CRE	V	00:00.0
2021 P03300716778	F	4	40 BRN	SP	CRE	V	00:00.0
2021 P03300816846	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021 P03318816781	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021 P03341616712	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021 P03368616641	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021 P03397816570	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021 P03425016505	KU	H1	100 BRN	AL	CRE	V	00:00.0
2021 P05710300518	KU	6	30 ACE	SP	CCA	V	00:00.0
2021 P09791795845	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 P09845295135	KU	6	30 BRO	SP	CCA	V	00:00.0
2021 P09825195020	KU	4	45 BRO	SP	CCA	V	00:00.0
2021 P09825595049	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 P05703900367	F	5	35 ACE	SP	CRE	V	00:00.0
2021 P05704000515	KU	6	30 ACE	SP	CCA	V	00:00.0
2021 P05709500443	F	3	40 ACE	SP	P	V	00:00.0
2021 P05706400823	KU	5	35 ACE	SP	CCA	V	00:00.0
2021 P05701400748	KU	5	35 ACE	SP	CCA	V	00:00.0
2021 P05985898983	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P05982298871	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P05994499243	F	4	45 ACE	SP	CCA	V	00:00.0
2021 P06001099434	F	4	45 ACE	SP	P	V	00:00.0
2021 P06001399065	F	4	40 ACE	SP	P	V	00:00.0
2021 P05753900247	F	3	45 ACE	SP	P	V	00:00.0
2021 P05978398758	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P05964398595	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P05954398514	F	4	40 ACE	SP	CRE	V	00:00.0
2021 P04491187905	LGE	4	40 ACE	SP	CRE	V	00:00.0
2021 P03405116790	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 P04422985791	LGE	4	40 BRO	SP	A	V	00:00.0
2021 P08106712515	KU	3	40 BRN	SP	CCA	V	00:00.0
2021 P04420385796	LGE	4	30 BRO	SP	CCA	V	00:00.0
2021 P04421285800	LGE	4	30 BRO	SP	A	V	00:00.0
2021 P04420785798	F	3	45 BRO	SP	A	V	00:00.0
2021 P04421685783	F	4	40 BRO	SP	P	V	00:00.0
2021 P03540816235	KU	2	50 BRN	AL	CRE	V	00:00.0
2021 P04426685467	F	3	50 BRO	SP	A	V	00:00.0
2021 P04426385484	F	3	50 BRO	SP	A	V	00:00.0
2021 P04426585453	F	3	50 BRO	SP	P	V	00:00.0
2021 P04425985458	F	3	45 BRO	SP	P	V	00:00.0
2021 P04425885444	F	4	40 BRO	SP	P	V	00:00.0
2021 P07959005440	F	4	40 BRN	SP	CRE	V	00:00.0
2021 P07946405569	F	4	40 BRN	SP	CRE	V	00:00.0
2021 P07933905698	F	4	40 BRN	SP	CRE	V	00:00.0
2021 P04429385425	LGE	4	35 BRO	SP	A	V	00:00.0
2021 P04426485438	F	3	50 BRO	SP	P	V	00:00.0
2021 P04426285423	F	3	50 BRO	SP	P	V	00:00.0
2021 P04397685321	LGE	4	40 BRO	SP	CRE	V	00:00.0
2021 P01404572929	LGE	2	55 BRO	SP	CRE	V	00:00.0
2021 P07927005771	F	4	40 BRN	SP	CCA	V	00:00.0
2021 P08515003033	KU	4	45 BRO	SP	CCA	V	00:00.0
2021 P08510602638	F	3	45 UNK	SP	CCA	V	00:00.0
2021 P08490802809	KU	4	45 BRO	SP	CCA	V	00:00.0

2021 PO1404973303	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO8199610577	KU	3	50 BRN	SP	CCA	V	00:00.0
2021 PO8193110515	KU	3	50 BRN	SP	CCA	V	00:00.0
2021 PO8187810464	KU	3	55 BRN	SP	CCA	V	00:00.0
2021 PO5857799636	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5856599520	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5854699385	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5847499285	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5837199181	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5831299124	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO1577768253	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO1597168393	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4376085127	LGE	4	30 ACE	SP	CRE	V	00:00.0
2021 PO4379685144	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO1557468970	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO1566886830	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO1569868783	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO1587468546	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4401685351	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO3281016010	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4423485755	LGE	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4423985748	LGE	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4424485739	LGE	4	40 BRO	SP	A	V	00:00.0
2021 PO4424685725	LGE	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4424885721	LGE	4	40 BRO	SP	A	V	00:00.0
2021 PO4425485724	LGE	3	45 BRO	SP	A	V	00:00.0
2021 PO4427585683	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4428985654	LGE	3	45 BRO	SP	A	V	00:00.0
2021 PO4429485656	LGE	4	30 BRO	SP	A	V	00:00.0
2021 PO8130712088	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO8125812091	KU	3	50 BRN	SP	CCA	V	00:00.0
2021 PO4428085664	LGE	3	50 BRO	SP	A	V	00:00.0
2021 PO4426481320	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO4426085715	LGE	3	45 BRO	SP	A	V	00:00.0
2021 PO1404069515	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4426785699	LGE	4	45 BRO	SP	A	V	00:00.0
2021 PO4427485703	LGE	4	40 BRO	SP	A	V	00:00.0
2021 PO4429085650	LGE	4	40 BRO	SP	CRE	V	00:00.0
2021 PO3390116521	F	4	40 BRN	SP	A	V	00:00.0
2021 PO3366916577	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4402285349	F	3	45 BRO	SP	A	V	00:00.0
2021 PO4403085354	F	3	45 BRO	SP	A	V	00:00.0
2021 PO4403885360	F	3	45 BRO	SP	A	V	00:00.0
2021 PO4404585364	F	3	45 BRO	SP	A	V	00:00.0
2021 PO4494387855	LGE	4	40 ACE	SP	CRE	V	00:00.0
2021 PO3494416754	KU	6	30 BRN	SP	CRE	V	00:00.0
2021 PO3513116717	KU	6	30 BRN	SP	CRE	V	00:00.0
2021 PO4401685345	F	3	45 BRO	SP	A	V	00:00.0
2021 PO4408985391	F	1	60 BRO	SP	CCA	V	00:00.0
2021 PO4407185380	F	3	45 BRO	SP	A	V	00:00.0
2021 PO1338270338	LGE	2H	45 BRO	SP	CRE	V	00:00.0
2021 PO4405485370	F	3	45 BRO	SP	A	V	00:00.0
2021 PO9388497424	KU	6	30 UNK	SP	CRE	V	00:00.0
2021 PO4428285648	LGE	3	45 BRO	SP	A	V	00:00.0

2021 PO3245115881	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3266315957	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3234315798	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO9690396404	KU	2	55 KOP	SP	CCA		V	00:00.0
2021 PO4528287893	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO9687396465	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9683596460	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9346895759	KU	3	45 KOP	SP	CCA		V	00:00.0
2021 PO2131290201	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3315216711	F	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4427785659	LGE	2	50 BRO	SP	A		V	00:00.0
2021 PO9661296293	KU	4	40 UNK	SP	CRE		V	00:00.0
2021 PO3342716150	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4523087977	LGE	1	60 ACE	SP	CRE		V	00:00.0
2021 PO4524587953	LGE	3	45 ACE	SP	A	ED	V	00:00.0
2021 PO4525687936	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4526187927	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4526687919	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO9811896585	KU	3	50 BRO	SP	CCA		V	00:00.0
2021 PO9791596589	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9771696595	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO4521687940	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4522187933	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8585603340	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO8543003211	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8575503245	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO5363802823	KU	2	45 ACE	SP	P		V	00:00.0
2021 PO4525087945	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8106911490	KU	3	50 BRN	SP	CCA		V	00:00.0
2021 PO8104411485	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO9831896577	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO8412401717	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO8493802480	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO8483602384	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO8472702282	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO8461702179	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO8451102080	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO8440501981	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO8429901881	F	3	45 CPT	SP	CCA		V	00:00.0
2021 PO8503302569	F	3	45 UNK	SP	P		V	00:00.0
2021 PO8628405828	KU	4	40 KOP	SP	CCA		V	00:00.0
2021 PO4421286028	F	4	35 BRO	SP	A		V	00:00.0
2021 PO6014298968	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6036398838	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6049498809	KU	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4421386012	LGE	4	35 BRO	SP	A		V	00:00.0
2021 PO5794500681	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO5768600369	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5775200332	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5779300526	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5758099889	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5750300104	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5764700187	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4412285970	F	4	35 BRO	SP	A		V	00:00.0

2021 PO4421886013	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO5791800695	F	3	45 ACE	SP	P		V	00:00.0
2021 PO5730399324	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5745399198	F	3	40 ACE	SP	P		V	00:00.0
2021 PO8513403049	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8161910243	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO9834495773	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9846995555	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO6104827681	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO6125227456	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO6077427974	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO6080327943	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO6067828229	KU	4	35 UNK	SP	CRE		B	00:00.0
2021 PO6073428280	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO6075728230	KU	6	30 UNK	SP	CRE		B	00:00.0
2021 PO6095028481	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO6080528345	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO6102428549	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO6124827365	KU	2	60 UNK	SP	CRE		B	00:00.0
2021 PO6115927460	KU	4	60 UNK	SP	CRE		B	00:00.0
2021 PO6090927735	KU	2	60 UNK	SP	CRE		B	00:00.0
2021 PO6107127559	KU	2	60 UNK	SP	CRE		B	00:00.0
2021 PO6100127634	KU	2	60 UNK	SP	CRE		B	00:00.0
2021 PO6081927832	KU	2	60 UNK	SP	CRE		B	00:00.0
2021 PO6078727865	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO6072827928	KU	4	60 UNK	SP	CRE		B	00:00.0
2021 PO6065228009	KU	2	60 UNK	SP	CRE		B	00:00.0
2021 PO6053728132	KU	3	60 UNK	SP	CRE		B	00:00.0
2021 PO6044128228	KU	2	60 UNK	SP	CRE		B	00:00.0
2021 PO6037428303	KU	4	50 UNK	SP	CRE		B	00:00.0
2021 PO5995628257	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO5992028305	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO5996528355	KU	4	40 UNK	SP	CCA		B	00:00.0
2021 PO6006928241	KU	2	45 UNK	SP	CRE		B	00:00.0
2021 PO6005228265	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO6013328170	KU	3	45 UNK	SP	CRE		B	00:00.0
2021 PO4444488284	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4471788344	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4449987983	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4443388291	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4474988257	LGE	3	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8113479072	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8606264896	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8563364833	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8804265188	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4444788267	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4471388354	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4470788364	LGE	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4444388094	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4452287993	LGE	4	40 BRO	SP	P	ED,EP,ID,IP,MD	TD	00:00.0
2021 PO4444988065	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4445388131	LGE	4	35 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4473688307	LGE	4	40 ACE	SP	CRE	ED,ID,MD	TD	00:00.0
2021 PO4473888226	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0

2021 PO4474888233	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4445288057	LGE	4	40 BRO	SP	P	ED,EP,ID,IP	TD		00:00.0
2021 PO8119678340	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8120078202	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8966965429	ODP	5	35 XXX	SP	CRE	HH,ID,IP	BX	RP3	00:00.0
2021 PO8119278494	F	4	40 ACE	SP	CRE	ED,HH,ID,MD,RB	VX	RP1	00:00.0
2021 PO8120478061	F	4	45 ACE	SP	CRE		V		00:00.0
2021 PO0612151154	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO0637150392	KU	4	40 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4444288121	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4443588129	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4443988133	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4443388140	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8085779013	KU	5	35 ACE	SP	CCA		V		00:00.0
2021 PO4439588045	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4439488050	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO8137478613	F	4	45 ACE	SP	P		V		00:00.0
2021 PO8104878615	F	4	45 ACE	SP	P		V		00:00.0
2021 PO8090878616	F	4	40 ACE	SP	P		V		00:00.0
2021 PO8089178664	KU	6	30 ACE	SP	CCA		V		00:00.0
2021 PO6019828100	KU	3	45 UNK	SP	CCA		V		00:00.0
2021 PO6010028114	F	4	40 UNK	SP	CCA		V		00:00.0
2021 PO6003128282	KU	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4443988115	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO8118878661	F	4	40 ACE	SP	P		V		00:00.0
2021 PO8123078614	F	4	40 ACE	SP	P		V		00:00.0
2021 PO8118978597	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4434587870-A	LGE	5	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO0677751032	KU	6	30 UNK	SP	CRE	ID	TD		00:00.0
2021 PO4434087870	F	4	40 BRO	SP	A		V		00:00.0
2021 PO8064779964a	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO8064779964	F	3	45 ACE	SP	P		V		00:00.0
2021 PO8197678616	F	4	40 ACE	SP	P		V		00:00.0
2021 PO8189778716	KU	6	30 ACE	SP	CCA		V		00:00.0
2021 PO8184478614	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4452588020	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8173778612	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8118278974	F	4	40 ACE	SP	P		V		00:00.0
2021 PO8119879012	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8099179013	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8118578819	F	4	40 ACE	SP	P		V		00:00.0
2021 PO8150978612	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8212478618	F	3	50 ACE	SP	CRE		V		00:00.0
2021 PO4444188103	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO6038228170	KU	2	50 UNK	SP	CCA		V		00:00.0
2021 PO6034128130	KU	2	50 UNK	SP	CCA		V		00:00.0
2021 PO6027328167	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO6030228191	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO0666451048	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO0663651128	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO0643151114	KU	3	45 BRN	SP	CRE		V		00:00.0
2021 PO0609350992	KU	4	45 UNK	SP	CRE	ID	TD		00:00.0
2021 PO1526195247	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO0667451276	KU	4	45 UNK	SP	CRE	ID	TD		00:00.0

2021 PO8164177863	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO4436687872	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8164477622	F	4	45 ACE	SP	P		V	00:00.0
2021 PO8163077703	F	6	30 ACE	SP	P		V	00:00.0
2021 PO8165777697	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4450387968	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4445788294	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4437787879	LGE	4	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4437787872	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO8153377623	F	3	45 ACE	SP	P		V	00:00.0
2021 PO4435687871	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4436687872-A	KU	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO0700851124	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO8178877638	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8192977653	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8202877664	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8214577678	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8222077686	F	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4434587870	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6114228660	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO6118528614	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO6106128512	F	3	40 UNK	SP	CRE		V	00:00.0
2021 PO4438787867	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4471488359	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4438987859	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4441688302	LGE	4	40 ACE	SP	CRE		BD	00:00.0
2021 PO6119727523	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO8983665234	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4438687872-A	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4438687872	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4446288110	F	4	35 BRO	SP	P		V	00:00.0
2021 PO4445988138	F	4	40 BRO	SP	P		V	00:00.0
2021 PO6099527735	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6089327842	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6072828023	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6109627627	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO8724559987	ODP	4	40 BRO	SP	P		V	00:00.0
2021 PO8709059799	ODP	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8728559834	ODP	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8746859872	ODP	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8738959497	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO8753859499	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO8727959259	ODP	6	30 BRO	SP	S		V	00:00.0
2021 PO8741559273	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8116677728	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8113377716	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO8108777656	F	3	50 ACE	SP	CCA		V	00:00.0
2021 PO8117077651	F	3	50 ACE	SP	CCA		V	00:00.0
2021 PO8129477642	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO8141677633	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6054628221	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6060328159	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO6068328072	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO6066428090	F	4	40 UNK	SP	CRE		V	00:00.0



2021	PO4445488064	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4446488066	LGE	4	35 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021	PO4447488068	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO8832465194	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8858165199	F	4	45 XXX	SP	CCA		V	00:00.0
2021	PO8947265315	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021	PO8950665583	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO9011665092	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021	PO9045865264	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021	PO8742152982	ODP	2	50 XXX	SP	CCA		V	00:00.0
2021	PO4438587881	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8762065467	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8318078830	F	3	45 ACE	SP	CRE		V	00:00.0
2021	PO8316778705	KU	6	30 ACE	SP	CCA		V	00:00.0
2021	PO8094277665	F	3	55 ACE	SP	CRE		V	00:00.0
2021	PO8109177632	KU	6	30 ACE	SP	CCA		V	00:00.0
2021	PO4469988382	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4469788382	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4438787863	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4437887858	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO8267579045	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8283079043	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8297879036	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8313079028	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8322179316	F	3	45 ACE	SP	CRE		V	00:00.0
2021	PO8320979165	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8319779024	F	3	50 ACE	SP	P		V	00:00.0
2021	PO8251379038	F	3	45 ACE	SP	CRE		V	00:00.0
2021	PO0659951276	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021	PO4438487891	LGE	4	35 BRO	SP	CRE	ID	BD	00:00.0
2021	PO4438487866	LGE	6	25 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4471088368	F	4	35 ACE	SP	A		V	00:00.0
2021	4479288366	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO8675360182	ODP	5	30 BRO	SP	S		V	00:00.0
2021	PO8670460273	F	5	35 BRO	SP	CRE		V	00:00.0
2021	PO8643859808	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO8673359831	F	4	40 BRO	SP	P		V	00:00.0
2021	PO8692660123	ODP	5	35 BRO	DF	P	ED,ID,IP	TD	00:00.0
2021	PO4439987867	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8217978389	F	4	40 ACE	SP	P		V	00:00.0
2021	PO6126328480	KU	5	35 UNK	SP	CRE		T	00:00.0
2021	PO6129028499	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO0600051498	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO0655051556	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021	PO6113328579	KU	6	30 UNK	SP	CRE		T	00:00.0
2021	PO8217979022	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8232979154	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8233779029	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO8591264758	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO8631265026	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021	PO8625865111	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO0554651525	KU	5	35 UNK	SP	CRE	ID	TD	00:00.0
2021	PO4440687867	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO0546951538	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0

2021 PO0553051647	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8682360577	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8204779621	F	3	35 ACE	SP	CRE		V	00:00.0
2021 PO8208879222	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO8210379102	F	3	35 ACE	SP	CRE		V	00:00.0
2021 PO8212178948	F	5	35 ACE	SP	P		V	00:00.0
2021 PO6114828371	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO4472288335	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO0594051730	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4439987858	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO6098728222	KU	6	30 UNK	SP	CRE		T	00:00.0
2021 PO8694860409	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8694460737	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO8691460857	ODP	3	45 BRO	SP	S		V	00:00.0
2021 PO8636460009	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO8198680179	F	5	35 ACE	SP	P		V	00:00.0
2021 PO8200280037	F	5	35 ACE	SP	P		V	00:00.0
2021 PO8206080019	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8207379903	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8216779031	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8203379755	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4441687868	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4442187859	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4473688314	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4473188324	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4472688327	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4472788332	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO8113379026	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0605651522	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO8133379007	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4445488045	LGE	4	40 BRO	SP	P	ED,ID,IP,RB	TD	00:00.0
2021 PO8115877994	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO4445288052	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8116277902	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8576264658	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8610264565	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8558964433	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8231278603	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8585760657	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8577460587	ODP	2	50 BRO	SP	S		V	00:00.0
2021 PO8594760833	F	4	40 BRO	SP	P		V	00:00.0
2021 PO0648651586	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO0617753399	KU	3	50 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0619753406	KU	3	50 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0619951520	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4816121437	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5342329119	F	4	40 BRO	SP	P		V	00:00.0
2021 PO5463905095	F	4	40 BRO	SP	P		V	00:00.0
2021 PO5455505144	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5445805167	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO5457105085	F	3	45 BRO	SP	P		V	00:00.0
2021 PO4257087525	LGE	1	55 ACE	SP	CRE		V	00:00.0
2021 PO44278855560	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO4737628066	F	4	40 XXX	SP	CRE	ED	V	00:00.0

2021 PO4731228016	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4715227980	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4702627952	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5373708529 A	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5223217525	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5216817312	KU	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5123618013	KU	2	55 BRO	SP	CCA		V	00:00.0
2021 PO5106118101	KU	2	55 BRO	SP	CCA		V	00:00.0
2021 PO5094818158	KU	2	55 BRO	SP	CCA		V	00:00.0
2021 PO5174517829	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5167108689A	KU	6	30 XXX	ST	S		V	00:00.0
2021 PO5154608350A	KU	6	30 XXX	ST	S		V	00:00.0
2021 PO5146207999	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5144508031	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5148508169	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5154608350	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO5162108542	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5159008457	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO5135008097C	KU	6	30 XXX	ST	S		V	00:00.0
2021 PO5135008097B	KU	6	30 XXX	SP	S		V	00:00.0
2021 PO5135008097A	KU	6	30 XXX	ST	S		V	00:00.0
2021 PO6298822540	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5202817620	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5353937992	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4252087314	LGE	1	60 ACE	SP	CRE		V	00:00.0
2021 PO4253987311	LGE	1	60 ACE	SP	CRE		V	00:00.0
2021 PO4946627735	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4948327593	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4966427480	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4972527441	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO9628885206	LGE	1	65 ACE	SP	P		V	00:00.0
2021 PO9626285176	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5305316125	KU	6	30 KOP	SP	CCA		V	00:00.0
2021 PO5139219855	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO4257887477	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4256587467	LGE	1	55 ACE	SP	CRE		V	00:00.0
2021 PO4256787410	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4256287439	LGE	1	60 ACE	SP	CRE		V	00:00.0
2021 PO5012927524	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4257087502	LGE	3	55 ACE	SP	CRE	ED	V	00:00.0
2021 PO4992227650	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4403586142	LGE	2	55 BRO	SP	A		V	00:00.0
2021 PO4402586137	F	1	70 BRO	SP	CRE		V	00:00.0
2021 PO4402686126	F	2	60 BRO	SP	CRE		V	00:00.0
2021 PO3934318245	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4259686987	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4259586985	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PV1164073524	F	2	60 BRO	SP	CRE		V	00:00.0
2021 PO4397986214	F	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4402686105	F	2	55 BRO	SP	CCA		V	00:00.0
2021 PO5406726859	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5395327635	F	4	40 XXX	SP	CRE	ED,MD	V	00:00.0
2021 PO5396627089	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5390127307	F	4	40 XXX	SP	CRE		V	00:00.0

2021	PO5384027583	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5405027425	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5405708713	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO5397508619	KU	6	30 XXX	SP	S		V	00:00.0
2021	PO5321305147	F	2	45 BRO	SP	CRE		V	00:00.0
2021	PO5337105084	F	2	45 BRO	SP	CRE		V	00:00.0
2021	PO5372827848	F	4	40 UNK	SP	CCA		V	00:00.0
2021	PO5310329306	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5197631675	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4399686011	C	4	30 BRO	SP	A		V	00:00.0
2021	PO4402086012	LGE	UNK	75 BRO	SP	CRE		V	00:00.0
2021	PO4402885975	LGE	H3	80 BRO	SP	P		V	00:00.0
2021	PO4402585974	LGE	3	50 BRO	AL	CCA		V	00:00.0
2021	PO5328028890	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO4401886051	LGE	4	30 BRO	ST	P		V	00:00.0
2021	PO4401586049	F	4	40 BRO	ST	P		V	00:00.0
2021	PO5384621347	F	4	40 BRO	SP	P		V	00:00.0
2021	PO5343928177	F	4	40 BRO	SP	P		V	00:00.0
2021	PO5327929197	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5319729085	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5382622061	F	1	40 BRO	SP	CCA		V	00:00.0
2021	PO5357328210	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5371821518	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5292329729	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5270529498	F	4	40 UNK	SP	P		V	00:00.0
2021	PO5339128628	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO4401886043	LGE	1	75 BRO	SP	CRE		V	00:00.0
2021	PO7034205900	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4980927063	F	3	40 XXX	SP	P		V	00:00.0
2021	PO4972327113	F	3	40 XXX	SP	CRE		V	00:00.0
2021	PO4960227183	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO4949027246	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4941527290	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO4927727271	F	4	40 XXX	SP	CRE	ED,ID	V	00:00.0
2021	PO4923227397	F	3	40 XXX	SP	P	ED	V	00:00.0
2021	PO4931127351	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO4938627535	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO5471608606	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO5393704860	KU	3	50 BRO	SP	CCA		V	00:00.0
2021	PO5398904991	KU	2	45 BRO	SP	CCA		V	00:00.0
2021	PO5283542274	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO5291541924	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5372219969	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5679312419	KU	2	65 BRO	SP	CCA		V	00:00.0
2021	PO5700011945	KU	2	65 UNK	SP	CRE		V	00:00.0
2021	PO5688312185	KU	2	70 UNK	SP	CRE		V	00:00.0
2021	PO5677012241	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5667712265	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO5563514087	KU	3	55 BRO	SP	CCA		V	00:00.0
2021	PO5440411487	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5455311430	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5608413601	KU	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5604413455	KU	2	55 XXX	SP	S		V	00:00.0
2021	PO5601013322	KU	2	65 XXX	SP	S		V	00:00.0

2021	PO5645609723	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5633809718	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5642609965	F	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5657509978	F	3	40 BRO	SP	CCA	V	00:00.0
2021	PO5631909957	F	3	40 UNK	SP	CRE	V	00:00.0
2021	PO5633009845	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5626009839	F	4	40 KOP	SP	P	V	00:00.0
2021	PO5728013997	KU	5	35 BRN	SP	CCA	V	00:00.0
2021	PO4261687145	LGE	1	55 ACE	SP	CCA	V	00:00.0
2021	PO4255687202	F	4	40 ACE	SP	A	V	00:00.0
2021	PO4255287258	LGE	1	50 ACE	SP	CCA	V	00:00.0
2021	PO4257187118	LGE	1	60 ACE	SP	CRE	V	00:00.0
2021	PO5449508785	KU	5	35 BRO	SP	CCA	V	00:00.0
2021	PO5452508776	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5840808954	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5843608918	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5854308945	KU	H1	85 BRO	SP	CRE	V	00:00.0
2021	PO5852808908	KU	1	80 BRO	SP	CRE	V	00:00.0
2021	PO5738208021	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5706708090	F	3	45 UNK	SP	CCA	V	00:00.0
2021	PO5722908051	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5201214409	KU	3	45 BRO	SP	CRE	V	00:00.0
2021	PO5209414485	KU	3	50 BRO	SP	CCA	V	00:00.0
2021	PO5282914793	F	1	75 KOP	SP	CCA	V	00:00.0
2021	PO5280614860	F	4	40 KOP	SP	P	V	00:00.0
2021	PO5304115198	F	4	50 KOP	SP	P	V	00:00.0
2021	PO5311315359	F	3	50 UNK	SP	P	V	00:00.0
2021	PO5294915009	F	3	40 UNK	SP	P	V	00:00.0
2021	PO5312641515	KU	4	40 BRO	SP	P	V	00:00.0
2021	PO5751507996	F	4	40 UNK	SP	CRE	V	00:00.0
2021	PO5254143120	KU	4	40 BRO	SP	CCA	V	00:00.0
2021	PV9597385353	LGE	1	65 ACE	SP	CRE	V	00:00.0
2021	PO4293986803	F	4	35 ACE	SP	CRE	V	00:00.0
2021	PO5333918733	F	4	40 KOP	SP	P	V	00:00.0
2021	PO5334618787	F	4	40 KOP	SP	P	V	00:00.0
2021	PO5341719027	F	4	40 KOP	SP	P	V	00:00.0
2021	PO5348419366	F	4	40 KOP	SP	P	V	00:00.0
2021	PO5363520166	F	4	40 KOP	SP	P	V	00:00.0
2021	PO5368720369	F	4	40 KOP	SP	P	V	00:00.0
2021	PO5357019824	F	4	40 KOP	SP	CCA	V	00:00.0
2021	PO5353519616	F	4	50 KOP	SP	CCA	V	00:00.0
2021	PO4293686812	LGE	3	50 ACE	SP	CCA	V	00:00.0
2021	PO4294186815	LGE	1	50 ACE	SP	CCA	V	00:00.0
2021	PO4422985642	KU	2	50 BRO	SP	CCA	V	00:00.0
2021	PO4422485651	LGE	2	50 BRO	SP	CCA	V	00:00.0
2021	PO4421985660	LGE	2	55 BRO	SP	CCA	V	00:00.0
2021	PO4800221802	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO6446223989	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO4895317737	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4903417582	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4297187149	LGE	1	45 ACE	SP	CCA	V	00:00.0
2021	PO6513224007	KU	4	40 XXX	SP	CCA	V	00:00.0
2021	PO6509423902	KU	4	45 XXX	SP	CCA	V	00:00.0
2021	PO6509123737	KU	4	40 XXX	SP	CCA	V	00:00.0

2021	PO4787422598	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4276087126	LGE	1	80 ACE	SP	CRE		V	00:00.0
2021	PO4275187127	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5040927362	F	4	40 XXX	SP	CRE	ED,ID	V	00:00.0
2021	PO5057327284	F	4	40 XXX	SP	P	ED,ID	V	00:00.0
2021	PO5060927217	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5062527259	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6295823725	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO4293586807	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4790622243	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4765921969	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4731121966	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4794021965	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4720021967	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4758126214	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO4641326634	F	3	45 XXX	SP	CRE	ED,ID	V	00:00.0
2021	PO4964826703	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4913527030	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4873326693	F	4	40 XXX	SP	CRE	ED,ID	V	00:00.0
2021	PO5013627183	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4981927384	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4942427631	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4915527718	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4873227580	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4860427216	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5659926885	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5635526850	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5618726826	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5598926720	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5580126620	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5561226519	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5544426429	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO43333529637	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5463009548	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO5447809614	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO5215705400	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5817812220	KU	6	30 XXX	SP	S		V	00:00.0
2021	PO5836712186	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO5844912160	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5859212114	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO3925718006	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO3929718146	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO3931418165	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO3971518269	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3937318324	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5285719365	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5277619226	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5339018085	F	2	45 UNK	SP	P		V	00:00.0
2021	PO5161220145	KU	3	50 BRO	SP	CCA		V	00:00.0
2021	PO5172920214	KU	2	55 BRO	SP	CCA		V	00:00.0
2021	PO5376023852	F	4	40 KOP	SP	P		V	00:00.0
2021	PO5372224062	F	4	40 KOP	SP	P		V	00:00.0
2021	PO5372224062A	KU	4	40 BRO	SP	P		V	00:00.0
2021	PO5394422531	F	4	40 BRO	SP	CRE		V	00:00.0

2021	PO4497587884	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021	PO5404222687	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5219217052	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5400922670	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5398622659	KU	4	40 BRO	SP	P		V	00:00.0
2021	PO5393721184	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5389920760	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5380620611	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5386820870	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5243916955	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5265916876	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5538808692	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5541108682	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5552208635	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5163717372	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5165419596	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO5172519428	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5163319289	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5184719254	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5564308584	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5557208626	F	4	30 BRN	SP	CCA		V	00:00.0
2021	PO4268486942	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5198419038	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO5204219173	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5570208750	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5570408767	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5222619240	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5203719431	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO4473388036	F	4	35 BRO	SP	A		V	00:00.0
2021	PO5626424088	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5629924153	KU	4	40 UNK	SP	CRE	ED	BD	00:00.0
2021	PO0735351831	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021	PO5621624146	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5648424409	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5641424347	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5634924290	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO4458287749	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4507888076	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5626124215	KU	3	40 UNK	SP	CCA		V	00:00.0
2021	PO5610224386	KU	1	70 UNK	SP	CRE		BD	00:00.0
2021	PO5620624166	F	3	50 UNK	SP	A		V	00:00.0
2021	PO5604124354	F	3	45 UNK	SP	CRE		V	00:00.0
2021	PO4454877737	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4453587745	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO0739651562	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO0720651549	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO0727851544	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO5643923525	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5649023464	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5652923422	KU	6	30 UNK	SP	CCA		V	00:00.0
2021	PO5649523364	KU	3	45 UNK	SP	CRE		BD	00:00.0
2021	PO5629823691	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5637423600	F	3	40 UNK	SP	A		V	00:00.0
2021	PO5619123815	F	4	40 UNK	SP	CRE		V	00:00.0

2021 PO5613723879	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021 PO5611523909	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5602524012	F	3	45 UNK	SP	A		V	00:00.0
2021 PO5640223473	KU	4	40 UNK	ST	CCA		V	00:00.0
2021 PO5612723795	KU	5	35 UNK	ST	CCA		V	00:00.0
2021 PO4432388133	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4453288045	LGE	4	35 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO5671923088	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5672123115	KU	4	40 UNK	SP	CRE		T	00:00.0
2021 PO4452187761	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4511288084	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5677723165	KU	1	75 UNK	SP	CCA		BD	00:00.0
2021 PO5677623214	KU	2	45 UNK	SP	CCA		V	00:00.0
2021 PO4450387751	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4449387759	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5684322995	KU	4	40 UNK	SP	CRE		BD	00:00.0
2021 PO5688222948	KU	1	75 UNK	SP	CRE		BD	00:00.0
2021 PO5690922919	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5698822826	KU	5	35 UNK	OT	CRE		V	00:00.0
2021 PO0527651532	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0535451513	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0257737854	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5620722557	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5623722580	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5633222479	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5653721951	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO5620322358	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5614022427	F	3	45 UNK	SP	A		V	00:00.0
2021 PO5630522243	F	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5633122192	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO5641222117	F	5	35 UNK	SP	CRE		V	00:00.0
2021 PO5650122020	F	4	35 UNK	SP	CCA		V	00:00.0
2021 PO5660021908	F	5	35 UNK	SP	CRE		V	00:00.0
2021 PO5901220788	KU	3	45 UNK	SP	CCA		BD	00:00.0
2021 PO5895320734	KU	1	75 UNK	UN	CCA		V	00:00.0
2021 PO5887020649	KU	4	40 UNK	UN	CRE		V	00:00.0
2021 PO5882420602	KU	5	35 UNK	UN	CRE		V	00:00.0
2021 PO4511688136	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4450188161	LGE	1	75 BRO	SP	P		V	00:00.0
2021 PO4449188159	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4448888159	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4448188158	LGE	1	75 BRO	SP	P		V	00:00.0
2021 PO8583658719	ODP	2	50 XXX	SP	CCA		V	00:00.0
2021 PO8553558642	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8601858004	ODP	4	50 XXX	SP	CRE		BD	00:00.0
2021 PO8613858022	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8536657410A	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8536657410	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8533357225	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8518157156	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO0437247885	KU	3	45 BRN	SP	CCA		T	00:00.0
2021 PO0474548282	F	6	30 CPT	SP	CCA		V	00:00.0
2021 PO0480647927	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0461147693	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0



2021 PO4447388156	LGE	3	50 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4447388156-A	LGE	4	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4446288153	LGE	4	40 BRO	SP	P	ED,EP,ID,MD	BD	00:00.0
2021 PO4446088154	LGE	1	75 BRO	SP	CRE		V	00:00.0
2021 PO4445988158	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4445688153	LGE	3	45 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4444188151	LGE	2	75 BRO	SP	A		V	00:00.0
2021 PO4435088137	LGE	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4454888018	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO0723951239	KU	5	35 CPT	SP	CRE	ID	TD	00:00.0
2021 PO4507288086	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4507088079	LGE	4	35 ACE	SP	CCA		BD	00:00.0
2021 PO0722751120	F	4	35 CPT	SP	CCA		V	00:00.0
2021 PO0723151037	KU	5	35 KOP	SP	CRE	ID	TD	00:00.0
2021 PO0484251934	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4443088154	LGE	3	45 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4452687740	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4442988149	LGE	2	55 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4442588149	LGE	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4442288148	LGE	1	75 BRO	SP	P		V	00:00.0
2021 PO1515393820	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO4439488144	LGE	2	55 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4440988141	LGE	3	50 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4439988144	LGE	1	75 BRO	SP	A		V	00:00.0
2021 PO4439288148	LGE	4	30 BRO	SP	CRE	ED,ID,IP,MD	BD	00:00.0
2021 PO4438888143	LGE	3	50 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4511088052	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5649022710	KU	6	30 UNK	SP	CRE		BD	00:00.0
2021 PO4512488057	LGE	4	30 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO5693222892	KU	3	40 UNK	UN	CRE		V	00:00.0
2021 PO5709322710	KU	1	75 UNK	SP	CRE		T	00:00.0
2021 PO5705922747	KU	3	35 UNK	UN	CRE		V	00:00.0
2021 PO5713022667	KU	6	30 UNK	UN	CRE		V	00:00.0
2021 PO5714422727	F	4	40 UNK	UN	CRE		V	00:00.0
2021 PO4449487747	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4507288140	LGE	1	95 ACE	SP	CRE		V	00:00.0
2021 PO4473888030	LGE	5	35 BRO	SP	A		V	00:00.0
2021 PO5636222810	KU	5	35 UNK	SP	CRE		T	00:00.0
2021 PO5637022872	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5638522855	KU	3	45 UNK	SP	CRE		BD	00:00.0
2021 PO4468488078	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4456188022	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4456588015	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4453888032a	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4453888032	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4452788057	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4451988069	LGE	4	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO445088038	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4455588031	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4454188045	LGE	4	40 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4454088054	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4453488064	LGE	4	40 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4453188064	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4452988071	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0

2021 PO4452488075	LGE	4	40 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4451988082	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4456088139	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4502188145	LGE	3	55 ACE	SP	CRE		V	00:00.0
2021 PO4455688151	LGE	3	45 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4456188137	F	3	45 BRO	SP	P		V	00:00.0
2021 PO4455488164	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4505688129	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4505488142	LGE	1	55 ACE	SP	CRE		V	00:00.0
2021 PO4503688144	LGE	1	95 ACE	SP	CRE		V	00:00.0
2021 PO4455588160	LGE	1	75 BRO	SP	P		V	00:00.0
2021 PO4454988160	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4454088160	LGE	1	80 BRO	DF	P		V	00:00.0
2021 PO4453188161	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4445288153	LGE	3	55 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4444388164	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4504288132	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4504688127	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5583124145	KU	5	35 UNK	ST	CCA		V	00:00.0
2021 PO5679922169	KU	5	35 UNK	UN	CRE		V	00:00.0
2021 PO8573357163	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8545357120	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8546556843	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8552856947	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8538456796	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8540357160	F	5	35 XXX	SP	P		V	00:00.0
2021 PO8527257304	ODP	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4512388060	LGE	3	45 ACE	SP	P	ED,ID,RB	TD	00:00.0
2021 PO4452087743	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5648522782	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5650922813	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5656122881	KU	2	45 UNK	SP	CCA		V	00:00.0
2021 PO5663722979	KU	2	45 UNK	SP	CCA		V	00:00.0
2021 PO4451287748	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4437788141	LGE	1	75 BRO	SP	CCA		V	00:00.0
2021 PO4436888140	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4436388139	LGE	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4435888138	LGE	2	55 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4435488137	LGE	3	75 BRO	SP	P		V	00:00.0
2021 PO4433288134	LGE	1	50 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4434488136	LGE	3	50 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4467588068	KU	1	55 BRO	SP	CCA		V	00:00.0
2021 PO4466688060	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4465888052-A	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4465888052	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4466288016	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4466288016-B	KU	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4466288016-A	KU	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4465888025	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5808321659	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO5806121506	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5811521786	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO5814421908	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO5817422005	KU	3	50 UNK	SP	CRE		BD	00:00.0

2021 PO5818421897	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5818922099	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO5820722188	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO5828322362	KU	2	50 UNK	SP	CRE		BD	00:00.0
2021 PO4465788027	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5910220873	KU	2	65 UNK	SP	CRE		V	00:00.0
2021 PO4508688139	LGE	3	55 ACE	SP	CRE		V	00:00.0
2021 PO4510788123	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4510288138	LGE	1	95 ACE	AL	CCA		V	00:00.0
2021 PO4505888189	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO0466648226	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0451948056	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4503488225	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4504188216	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4504688219	LGE	4	30 ACE	SP	A	ED,ID	V	00:00.0
2021 PO4455888144	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4503288139	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4503888147	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4509188055	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO0747251532	KU	6	30 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0758751600	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0728051588	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5652623118	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5656723122	KU	2	55 UNK	SP	CCA		V	00:00.0
2021 PO5655923108	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5639223275	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5626123428	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4453687738	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4508888039	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4508488032	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4509888041	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4509888045	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5613923572	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5612723588	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO8578558920	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4503888129	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4505288117	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4505988106	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4505288108	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4506588096	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4452488161	LGE	3	50 BRO	SP	P	ED,EP,ID,RB	BD	00:00.0
2021 PO4451888165	LGE	4	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4451988161	LGE	1	75 BRO	SP	A		V	00:00.0
2021 PO4451288161	LGE	3	45 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4451088161	LGE	3	50 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4450188165	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8490557183	ODP	5	35 XXX	SP	CCA		V	00:00.0
2021 PO8497157282	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8463157773	ODP	5	35 XXX	SP	P	ED	T	00:00.0
2021 PO8459757646	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8421057627	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8508956079	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8502256442	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8503056687	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0

2021 PO8513056796	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8509756312	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8506755925	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8505355811	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5626622993	KU	4	45 UNK	SP	CRE		BD	00:00.0
2021 PO5628122974	KU	3	45 UNK	SP	CRE		BD	00:00.0
2021 PO5632022930	KU	5	35 UNK	UN	CRE		BD	00:00.0
2021 PO5627422984	KU	5	35 UNK	UN	CRE		V	00:00.0
2021 PO0470251984	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0531951474	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0495751880	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0094758791	KU	6	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO0089158820	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO2133050622	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5003088257	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO5003388280	LGE	3	50 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO5003388261	F	4	25 BRN	SP	P		V	00:00.0
2021 PO5004088278	F	4	30 BRN	SP	CCA		V	00:00.0
2021 PO1437675150	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO1455475212	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO1463275252	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO5034089626	LGE	UNK	30 ACE	SP	A		V	00:00.0
2021 PO5035689619	LGE	UNK	30 ACE	SP	A		V	00:00.0
2021 PO2067250789	KU	4	40 XXX	SP	CRE	ID,IP	BD	00:00.0
2021 PO4962088587	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO2192356825	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2177456751	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2088750603	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4964188523	LGE	2	60 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4959388503	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO1298274487A	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO1238574468	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4315087041	LGE	4	40 ACE	SP	CRE	ED	VX PX	00:00.0
2021 PO9589359034	KU	3	45 BRO	SP	S		V	00:00.0
2021 PO9717658809	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO9682258769	KU	6	30 BRO	SP	P	ID	BD	00:00.0
2021 PO4283205240	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4295705355	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4282205348	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4291005503	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4271805322	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2024952140	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2038052190	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2067052281	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2068552195	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO1473074999	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1478974705	KU	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4962888562	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO0428759688	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0436159399	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0430059382	KU	3	45 BRO	SP	CRE		V	00:00.0
2021 PO0223257924	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO0456758594	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0440458979	KU	4	40 BRO	SP	S		V	00:00.0

2021	PO0447258995	KU	3	45 BRO	SP	CCA			V	00:00.0	
2021	PO1481674630A	KU	6	30 BRO	SP	S			V	00:00.0	
2021	PO1481674630	KU	6	30 BRO	SP	P	ED,ID		TD	00:00.0	
2021	PO1455074699	KU	4	45 BRO	SP	S			V	00:00.0	
2021	PO1468974424	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0	
2021	PO5466899046	F	4	40 XXX	SP	CRE	ED,EP,ID,MD		BX	PX	00:00.0
2021	PO5489598948	F	4	40 XXX	SP	CRE	ED,HH,ID		BX	RP3	00:00.0
2021	PO5482798797	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5478098698	F	3	40 XXX	SP	P			V	00:00.0	
2021	PO5461598759	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5448498808	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5375499084	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5422798906	F	3	40 XXX	SP	P			V	00:00.0	
2021	PO5434298860	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5410498952	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5398498996	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5387499040	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5365399124	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5366599306A	KU	4	40 XXX	SP	P	ED,ID		TD	00:00.0	
2021	PO5366599306	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5359700413	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO9592458707	KU	4	40 UNK	SP	CRE	ED,ID,IP		TD	00:00.0	
2021	PO7127195745	LGE	4	40 BRN	SP	CCA			V	00:00.0	
2021	PO5001988252	LGE	3	45 BRN	SP	P	ED,ID		BD	00:00.0	
2021	PV5003088246	LGE	4	40 BRN	SP	P	ED,ID		BD	00:00.0	
2021	PO5002588250	F	4	35 BRN	SP	P			V	00:00.0	
2021	PO4974089358	LGE	2	55 ACE	SP	CCA			V	00:00.0	
2021	PO4972889360	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4962888542	LGE	4	40 BRO	SP	A	ED,ID		TD	00:00.0	
2021	PO5004388238	LGE	4	40 BRN	SP	P	ED,ID		T	00:00.0	
2021	PO4971989363	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4962888532	F	4	40 BRO	SP	A			V	00:00.0	
2021	PO6803706825	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4970389369	LGE	3	45 ACE	SP	A	ED		BD	00:00.0	
2021	PO5006088234	LGE	4	35 BRN	SP	A	ED,ID		BD	00:00.0	
2021	PO6704298404	LGE	3	45 BRO	SP	CCA			V	00:00.0	
2021	PO4318986998	LGE	4	35 ACE	SP	A	ED,ID		TD	00:00.0	
2021	PO5542704514	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO5538204552	KU	6	30 BRN	SP	CRE	ED		TD	00:00.0	
2021	PO5539804445	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO1249383718	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0	
2021	PO5558605184	F	4	40 BRN	SP	CCA			V	00:00.0	
2021	PO5559505321	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO5566105441	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO5572805616	F	2	40 BRN	SP	CCA			V	00:00.0	
2021	PO5562506001	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO5565606154	F	4	40 BRN	SP	CCA			V	00:00.0	
2021	PO5570506143	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO5577906131	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO5576205967	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO5575505799	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO1300183515	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0	
2021	PO1350183170	KU	4	40 BRO	SP	CRE	ID		TD	00:00.0	
2021	PO1328883407	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0	

2021 PO1390182674	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1357682389	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO1308282267	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO1404982515	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6190297350	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6196797327	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6213897351	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6224197365	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO1395982209	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1360581462	KU	6	30 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO6249197383	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO1361981629	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO1426681925	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO1377981929	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6267797383	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6292697368	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6312897314	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9404219353	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4839391472	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO2181559901	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4839491489	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4839291501	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO1802230841	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO1400781732A	KU	3	45 BRO	SP	S		V	00:00.0
2021 PO4839191516	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4839291532	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4839291544	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO2202759899	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2224659904	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5224399989	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5219199796	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO5215999675	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5211999530	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5206399504	KU	5	35 XXX	SP	S		V	00:00.0
2021 PO5213899600	F	3	45 XXX	SP	CRE	ED,HH,ID	BX	RP1 00:00.0
2021 PO9364518592	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1802230839	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO2180755294	KU	6	30 XXX	SP	CRE		V	00:00.0
2021 PO2161555309	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2163455169	KU	4	40 XXX	SP	CRE	ID,IP	TD	00:00.0
2021 PO2166555295	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2175955168	KU	6	30 XXX	SP	CCA		V	00:00.0
2021 PO2136054753	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2155854861	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO2151854630	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO2145454564	F	5	35 XXX	SP	CCA		V	00:00.0
2021 PO2089153976	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO2112854298	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO2138052943	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO1400781732	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1385381825	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO1370081514	KU	3	45 BRO	SP	CRE		V	00:00.0
2021 PO9394119128	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6345897189	F	4	40 BRN	SP	CRE		V	00:00.0

2021	PO6366197099	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6382397010	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6394596937	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6406896868	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4840191547	LGE	4	35 BRN	SP	A	ED,ID,IP,RB	BD	00:00.0
2021	PO2181960201	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4840991551	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4842591550	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO9380719401	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO1380281377	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO1405381258	KU	3	45 BRO	SP	CCA	ED,ID	V	00:00.0
2021	PO9376819703	KU	6	30 UNK	SP	CRE	HH,ID	TD	00:00.0
2021	PO2246159903	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4843991548	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4843991543	LGE	4	40 BRN	SP	A	ED,HH,ID,IP	VX	RP1 00:00.0
2021	PO1426781308	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO1446881194	KU	4	45 BRO	SP	CRE		V	00:00.0
2021	PO1464881018	KU	4	45 BRO	SP	CRE		V	00:00.0
2021	PO1415581110	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1422081212	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO1414080601	KU	3	45 BRO	SP	S		V	00:00.0
2021	PO9371719657	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9356819821	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9345819946	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9753158847	KU	4	40 KOP	SP	CRE		V	00:00.0
2021	PO0146663646	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO0108763605	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021	PO6424296775	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4845191546	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	2157560337a	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO2157560337	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO2158960227	F	4	45 BRO	SP	P		V	00:00.0
2021	PO2136360253	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	2091760308a	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO2091760308	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4846791548	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4850691532	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO6230397201	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4848091543	LGE	4	35 BRN	SP	CRE	ED,ID,MD	BD	00:00.0
2021	PO1447780824	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO1440380876	KU	3	45 BRO	SP	S		V	00:00.0
2021	PO1430680851	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1491180901	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6265497235	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6264397189	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6272897140	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021	PO4849491537	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO1530680954	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO1550280858	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5051389325	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO0519833662	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4827090880	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4823990948	LGE	4	40 BRN	SP	P		V	00:00.0
2021	PO4824090959	LGE	4	40 BRN	SP	P		V	00:00.0

2021 PO4823990983	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO4824091021	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO4822890676	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO4822890667	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO4822990725	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO4822990701	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO5594704257	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5607604188	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5618104480	F	4	40 MAR	SP	CRE	HH	VX	RP1	00:00.0
2021 PO5064889254	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO5636604261	KU	6	30 MAR	SP	CRE		BD		00:00.0
2021 PO5630504400	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5640404340	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5637004139	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5642704241	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5645904309	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5050689331	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO7597206453	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO7569006091	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO5069289058	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO5069089081	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4815491441	LGE	4	45 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO4823991362	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4830191381	LGE	4	35 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO4828891377	LGE	3	45 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO4827591373	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO5654204261	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5090289116	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO5092689107	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO5091389106	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO5622004523	KU	5	35 MAR	SP	CCA		V		00:00.0
2021 PO5631304540	KU	6	30 MAR	SP	CRE	ED	BD		00:00.0
2021 PO5680004792	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5670504878	KU	6	30 MAR	SP	CCA		V		00:00.0
2021 PO5657205132	F	4	40 MAR	SP	CRE		V		00:00.0
2021 PO5088389122	LGE	4	30 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO5088489120	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO6181149327	KU	6	30 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4272307857	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4294006935	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4279506819	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4249007335	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4253407272	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4255507500	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4262407668	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4426912178	F	3	45 XXX	SP	S		V		00:00.0
2021 PO4427912222	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4430212305	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5085084643	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4913384863	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021 PO4914484847	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4529387581	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4529487591	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5086784650	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0



2021	PO5087084632	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO5086784624	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021	PO7630380534	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7623380610	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4914784853	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4318810228	KU	5	35 XXX	SP	S		V		00:00.0
2021	PO4330710395	KU	6	30 XXX	SP	S		V		00:00.0
2021	PO4328010407	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4334510588	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5086584577	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021	PO4953884687	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO7658281916	KU	6	30 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO7657681865	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7661282051	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7660782183	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7665382588	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7663582450	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7666782742	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5086184557	LGE	4	35 ACE	SP	CRE	ED	BD		00:00.0
2021	PO4952584662	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4373512079	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4369611881	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4366311852	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4363511685	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4366611715	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4364011627	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4360811522	F	3	45 XXX	SP	S		V		00:00.0
2021	PO4334411442	KU	6	30 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4331011329	KU	6	30 XXX	SP	S	ED,SRC	T		00:00.0
2021	PO4350811265	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4350811178	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4349011111	F	3	40 XXX	SP	S		V		00:00.0
2021	PO4346711033	F	3	45 XXX	SP	S		V		00:00.0
2021	PO4328811069	KU	5	35 XXX	SP	S		V		00:00.0
2021	PO4322710761	KU	3	50 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO4337310712	KU	3	45 XXX	SP	CRE	ED,EP,ID,IP,SRC	TX	RR	00:00.0
2021	PO5483408092	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5485907854	KU	4	45 XXX	SP	CCA		V		00:00.0
2021	PO5484207960	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5472608053	KU	3	45 XXX	SP	CRE		BD		00:00.0
2021	PO5083484555	LGE	3	45 ACE	SP	CRE	ED	TD		00:00.0
2021	4852785552	LGE	4	40 ACE	SP	P	ED,ID	TX	RR	00:00.0
2021	PO4852185528	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021	PO7669481006	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO4408211036	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5380807609	KU	4	40 XXX	SP	CRE	ID,IP	BD		00:00.0
2021	PO5384107698	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO5391707668	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO1335067026	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021	PO1395867598	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021	PO1401767517	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021	PO5082984680	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021	PO5083984673	LGE	4	30 ACE	SP	CRE	ED	BD		00:00.0
2021	PO5081284661	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0

2021	PO5080684642	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO5082884660	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO7607282762	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7604782493	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7602282222	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5406708330	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5411008443	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO4430485637	LGE	4	30 BRN	SP	CCA	ED,ID	TD	00:00.0
2021	PO4910384768	LGE	4	40 BRO	SP	A	ID,IP	TD	00:00.0
2021	PO5541207871	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5537707769	KU	3	45 XXX	SP	CCA	ED	T	00:00.0
2021	PO4911584789	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4524287982	LGE	2	60 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4524687975	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021	PO4527887547	LGE	1	75 BRO	SP	CRE		V	00:00.0
2021	PO7645180649	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7649380979	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7651381222	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7652581332	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7654981592	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4539387677	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD	00:00.0
2021	PO4945084457	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4956084734	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021	PO4285510939	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4302510887	KU	2	50 XXX	SP	CRE	ED,HH,ID,MD,RB	BX	RP1 00:00.0
2021	PO4265410997	KU	2	50 XXX	SP	S		V	00:00.0
2021	PO5085284588	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO8017859153	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5082884576	LGE	4	35 ACE	SP	CCA		BD	00:00.0
2021	PO4955084712	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4945584515	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4947984565	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4540087681	LGE	3	45 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4537787667	LGE	4	40 BRO	SP	P	ED,EP,ID	TD	00:00.0
2021	PO4538787664	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4532387632	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO5460307645	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021	PO5463207753	KU	4	40 XXX	SP	CRE	ID,IP	TD	00:00.0
2021	PO5448707792	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO5439707817	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5482208311	KU	6	30 XXX	SP	CRE	ID	BD	00:00.0
2021	PO5534307648	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4404311200	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5526807422	KU	6	30 XXX	SP	CCA		V	00:00.0
2021	PO5524207554	KU	6	30 XXX	SP	CCA	ED	TD	00:00.0
2021	PO5522407586	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO7610680495	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4914484744	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4914384715	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4356711384	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4358811377	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4367711341	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4392112989	F	3	50 XXX	SP	S		V	00:00.0
2021	PO4386013021	KU	4	40 XXX	SP	S		V	00:00.0

2021 PO4213610200	KU	4	45 XXX	SP	S		V		00:00.0
2021 PO4226810615	KU	3	50 XXX	SP	S		V		00:00.0
2021 PO5506207466	KU	6	30 XXX	SP	CCA	ED	T		00:00.0
2021 PO5503807535	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4527687600	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4528287604	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5084484621	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO5082484597	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO5082084619	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO4493588063	LGE	4	30 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4493888058	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021 PO4494488062	LGE	4	40 ACE	SP	P	ED	TD		00:00.0
2021 PO4851185450	F	3	45 ACE	SP	P		V		00:00.0
2021 PO5658267370	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4847985419	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4850285734	LGE	1	70E ACE	SP	CRE	ED	BD		00:00.0
2021 PO5510707620	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5505907680	KU	5	35 XXX	SP	CRE	HH,ID,RB	X	RP1	00:00.0
2021 PO5502407643	KU	2	55 XXX	SP	CCA		V		00:00.0
2021 PO5489007680	KU	4	40 XXX	SP	CCA	ID	TD		00:00.0
2021 PO5476307716	KU	5	45 XXX	SP	CCA		V		00:00.0
2021 PO4915084861	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7628180650	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7613780667	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7596180668	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7588780685	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5336710642	KU	3	55 XXX	SP	CCA		V		00:00.0
2021 PO5310210582	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5323110510	KU	6	30 BRN	SP	CRE	ID	BD		00:00.0
2021 PO4321908857	KU	5	35 BRN	SP	CRE		V		00:00.0
2021 PO5093885132	LGE	4	40 ACE	SP	A	ED	TD		00:00.0
2021 PO5093185131	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO4526887993	LGE	2	60 BRO	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4528287998	LGE	2	65 BRO	DF	CRE	ED,ID,IP	TD		00:00.0
2021 PO4528388005	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4527888002	LGE	4	30 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO2342092367	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4525887988	LGE	2	60 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4429385626	LGE	3	45 BRN	SP	A	ED,ID	TD		00:00.0
2021 PO4392311908	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4377711932	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4372911642	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4386611616	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4401211590	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5401608188	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5083384644	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO5081584644	LGE	4	40 ACE	SP	A	ID	BD		00:00.0
2021 PO4268710565	KU	3	45 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO4533487639	LGE	3	45 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4395086032	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO4393586052	LGE	3	45 ACE	SP	CCA	ED	V		00:00.0
2021 PO4394486040	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4422185661	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021 PO4430285641	LGE	3	50 ACE	SP	CRE	ED,ID,IP	VX	PX	00:00.0

2021 PO4439485708	LGE	3	50 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4390085234	LGE	4	35 BRN	SP	CCA	ED,ID	BD		00:00.0
2021 PO7750081336	KU	4	45 ACE	SP	CCA		V		00:00.0
2021 PO7726381360	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO7737581223	KU	4	45 ACE	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4390485245	LGE	5	35 BRN	SP	CCA	ED,ID	BD		00:00.0
2021 PO4390985252	F	4	35 BRN	SP	A		V		00:00.0
2021 PO4390185253	F	3	50 BRN	SP	CCA		V		00:00.0
2021 PO4390585256	F	1	55 BRN	SP	CCA		V		00:00.0
2021 PO5083484723	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	X	RP3	00:00.0
2021 PO7700281909	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7698081683	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5138384510	LGE	4	40 ACE	SP	A	ED	BD		00:00.0
2021 PO5133784540	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021 PO5136084525	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4392085278	LGE	3	45 BRN	SP	CCA	ED,ID,IP	TD		00:00.0
2021 PO5140884494	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO5143084517	LGE	4	40 ACE	SP	A		V		00:00.0
2021 PO7695481432	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7694981242	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4537487621	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4537187630	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4536787636	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4535787653	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4536087648	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4952584608	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO5092585134	LGE	4	30 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO5093385144	LGE	4	30 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4950984623	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4942684736	LGE	4	30 BRO	SP	CRE		V		00:00.0
2021 PO4941684742	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO5093885138	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5468908384	KU	5	35 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO5457808263	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5081784717	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO7709882903	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7708282703	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7713383029	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7689683076	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5080284710	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO4390285262	LGE	3	45 BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO4390185266	LGE	4	45 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO5086184485	LGE	4	35 ACE	SP	CRE		V		00:00.0
2021 PO5084884520	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4391485272	LGE	3	45 BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO5131384555	LGE	4	40 ACE	SP	P		V		00:00.0
2021 PO5140984541	LGE	4	45 ACE	SP	A	ED	BD		00:00.0
2021 PO7705382405	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7703282208	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7701382008	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7678281108	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4493810129	KU	5	35 XXX	SP	S		T		00:00.0
2021 PO4522010118	KU	5	35 XXX	SP	S	ED	T		00:00.0
2021 PO4393585280	F	1	45 BRN	SP	CCA		V		00:00.0

2021 PO4540388051	LGE	2	65 BRO	DF	CRE	ED,ID,IP,MD	BD		00:00.0
2021 PO4539488047	LGE	2	70 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5324807609	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5338407558	KU	3	45 XXX	SP	CRE	ID	BD		00:00.0
2021 PO5376607495	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4399785341	LGE	4	35 BRN	SP	CCA	ED,ID,IP	TD		00:00.0
2021 PO4530087995	LGE	7	25 BRO	SP	CRE	ED,EP,ID,IP,MD,RB	BX	RP1	00:00.0
2021 PO1682396102	KU	3	45 KOP	SP	CRE	ID	TD		00:00.0
2021 PO4021984600	F	3	45 ACE	SP	CRE		V		00:00.0
2021 PO3997984209	LGE	4	40 ACE	SP	CRE	ED,ID,RB	X	RP3	00:00.0
2021 PO4000384218	LGE	4	30 ACE	SP	CRE	ED,HH,ID	VX	RP3	00:00.0
2021 PO4000884221	LGE	4	40 ACE	SP	CRE	ED,ID,RB	VX	RP3	00:00.0
2021 PO3998784218	LGE	4	40 ACE	SP	CCA	ED	V		00:00.0
2021 PO3999684232	LGE	3	45 ACE	SP	CCA	ED	V		00:00.0
2021 PO4027684782	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4027884804	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4026184806	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4024784808	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4023384817	F	7	25 BRN	SP	CRE		V		00:00.0
2021 PO4023384809	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4021384812	F	4	30 BRN	SP	CCA		V		00:00.0
2021 PO4021884807	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4020984800	F	7	25 BRN	SP	CRE		V		00:00.0
2021 PO4021684800	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4021584785	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4021584771	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4021484755	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4014684774	LGE	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4016884783	F	7	25 BRN	SP	CRE		V		00:00.0
2021 PO4016084783	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4017384791	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4014384761	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4015884760	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4015884752	LGE	7	25 BRN	SP	CRE		V		00:00.0
2021 PO4017184759	F	4	40 BRN	SP	A		VX	RP1	00:00.0
2021 PO4018584750	LGE	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4018584758	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4018784774	F	4	40 BRN	SP	P		V		00:00.0
2021 PO4019484773	LGE	7	25 BRN	SP	P		V		00:00.0
2021 PO4006184785	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4003384754	F	7	25 BRN	SP	CRE		V		00:00.0
2021 PO4002484724	F	7	25 BRN	SP	CRE		V		00:00.0
2021 PO4018884788	F	4	40 BRN	SP	A		V		00:00.0
2021 PO4019784802	F	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4019084802	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4058184170	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD		00:00.0
2021 PO4057684186	LGE	4	40 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4058584151	LGE	4	40 BRO	SP	A	ED,ID	BD		00:00.0
2021 PO4058884137	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7438557467	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4029584584	F	5	35 ACE	SP	A		V		00:00.0
2021 PO4028384583	F	4	30 ACE	SP	P		V		00:00.0
2021 PO4026784588	F	4	35 ACE	SP	A		V		00:00.0
2021 PO0203100781	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0

2021	PO0197900975	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4024984589	F	6	30 ACE	SP	CRE		V		00:00.0
2021	PO4023684595	F	4	30 ACE	SP	A		V		00:00.0
2021	PO7756853005	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4059384104	LGE	4	40 BRO	SP	CCA	ED,ID,IP	TD		00:00.0
2021	PO4022984595	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4022384579	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO1965945761	KU	5	35 XXX	SP	CRE	HH,ID	TX	RR	00:00.0
2021	PO2006645799	KU	5	35 XXX	SP	CRE	ID	TX	RR	00:00.0
2021	PO2026645821	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO3998084137	LGE	UNK	25 ACE	SP	CRE		V		00:00.0
2021	PO3997484147	LGE	4	30 ACE	SP	CRE		V		00:00.0
2021	PO3998284147	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO3998284158	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO3997784165	F	4	30 ACE	SP	CRE		V		00:00.0
2021	PO3998384168	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4019084603	F	3	45 ACE	SP	CRE		V		00:00.0
2021	PO4018184605	F	3	45 ACE	SP	A		V		00:00.0
2021	PO3998584282	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4048184206	LGE	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4048484190	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4048684180	LGE	UNK	25 BRO	SP	CRE		V		00:00.0
2021	PO4048884168	KU	3	45 BRO	SP	P		B		00:00.0
2021	PO4049284146	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4049884135	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021	PO4005684241	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4007984242	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4010884245	LGE	4	35 ACE	SP	A	ED	VX	RP2	00:00.0
2021	PO4010984234	F	4	40 ACE	DF	CCA		V		00:00.0
2021	PO4027184608	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4027284616	F	4	40 BRN	SP	A		V		00:00.0
2021	PO4027384620	F	4	40 BRN	SP	A		V		00:00.0
2021	PO4027584633	F	4	40 BRN	SP	A		V		00:00.0
2021	PO4027884648	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4028184663	F	4	40 BRN	SP	P		V		00:00.0
2021	PO4028484679	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4030584675	F	4	40 BRN	SP	A		V		00:00.0
2021	PO3986984196	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO3985584200	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO3984884197	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO3983584198	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO3983984202	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO0039678874	KU	5	35 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO4000584640	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4001484635	F	3	50 ACE	SP	CCA		V		00:00.0
2021	PO4003284629	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4004084624	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4004984624	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4006384618	F	3	40 ACE	SP	A		V		00:00.0
2021	PO0039378631	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO7505647835	LGE	1	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4030183610	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PV4030183603	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4029983586	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0

2021 PO4048284117	LGE	4	40 BRO	SP	CCA		ED,ID,IP	TD	00:00.0
2021 PO4051884126	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021 PO7663552973	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021 PO7564653008	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021 PO7581152794	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021 PO7573752727	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021 PO4028683526	LGE	4	40 BRO	SP	CRE		ED,ID,IP	TD	00:00.0
2021 PO4028483498	LGE	3	45 BRO	SP	CRE		ED,ID,IP	TD	00:00.0
2021 PO4000684239	LGE	4	40 ACE	SP	CCA		ED	V	00:00.0
2021 PO4022884602	F	4	45 ACE	SP	CRE			V	00:00.0
2021 PO4023084601	F	3	45 ACE	SP	CCA			V	00:00.0
2021 PO1970650133	F	4	40 OTH	SP	CCA			V	00:00.0
2021 PO1975349899	F	4	45 OTH	SP	CCA			V	00:00.0
2021 PO1981549598	F	4	45 OTH	SP	CCA			V	00:00.0
2021 PO1986549351	F	4	45 OTH	SP	CCA			V	00:00.0
2021 PO1991349115	F	4	40 OTH	SP	CCA			V	00:00.0
2021 PO1995548894	F	4	40 OTH	SP	CCA			V	00:00.0
2021 PO1998748724	F	3	40 OTH	SP	CCA			V	00:00.0
2021 PO1998748724A	F	3	40 OTH	SP	CCA			V	00:00.0
2021 PO2002048343	F	4	45 OTH	SP	CCA			V	00:00.0
2021 PO2004748149	F	3	50 OTH	SP	CCA			V	00:00.0
2021 PO2003347958	F	4	40 OTH	SP	CCA			V	00:00.0
2021 PO2015247717	F	4	40 OTH	SP	CCA			V	00:00.0
2021 PO2022747510	F	3	45 OTH	SP	CCA			V	00:00.0
2021 PO2028747535	F	5	35 OTH	SP	CCA			V	00:00.0
2021 PO2027347338	F	3	45 OTH	SP	CCA			V	00:00.0
2021 PO2034747197	F	3	45 OTH	SP	CCA			V	00:00.0
2021 PO2010246984	KU	4	40 OTH	SP	CCA			V	00:00.0
2021 PO2035446980	F	4	40 OTH	SP	CCA			V	00:00.0
2021 PO2036446704	F	3	45 OTH	SP	CCA			V	00:00.0
2021 PO2019146430	KU	4	40 OTH	SP	CCA			V	00:00.0
2021 PO2037546428	F	4	40 OTH	SP	CCA			V	00:00.0
2021 PO2038046233	F	3	45 OTH	SP	CCA			V	00:00.0
2021 PO2038346121	F	4	45 OTH	SP	CCA			V	00:00.0
2021 PO2107345964	KU	4	40 OTH	SP	CCA			V	00:00.0
2021 PO2086645925	KU	4	40 OTH	SP	CCA			V	00:00.0
2021 PO2039045967	F	4	45 OTH	SP	CCA			V	00:00.0
2021 PO2039445830	F	3	45 OTH	SP	CCA			V	00:00.0
2021 PO2064445749	KU	4	40 BRN	SP	CCA			V	00:00.0
2021 PO2040045652	F	4	40 INP	SP	CRE			V	00:00.0
2021 PO9823097633	KU	4	40 BRO	SP	CRE		ED,ID	TD	00:00.0
2021 PO9844597988	KU	4	40 BRO	SP	S			V	00:00.0
2021 PO9865898372	KU	4	40 BRO	SP	CRE		ED,ID,IP	TD	00:00.0
2021 PO9872898566	KU	5	30 BRO	SP	S			V	00:00.0
2021 PO9878398676	KU	5	35 BRO	SP	CRE		ED,ID	TD	00:00.0
2021 PO4018884812	F	4	40 BRN	SP	A			V	00:00.0
2021 PO4019284819	F	4	35 BRN	SP	A			V	00:00.0
2021 PO4017884821	F	4	30 BRN	SP	CRE			V	00:00.0
2021 PO4017784815	F	4	40 BRN	SP	A			V	00:00.0
2021 PO4016284817	F	4	40 BRN	SP	A			V	00:00.0
2021 PO4014984818	F	4	40 BRN	SP	A			V	00:00.0
2021 PO4013684819	F	4	40 BRN	SP	CCA			V	00:00.0
2021 PO4013684827	F	4	30 BRN	SP	CCA			V	00:00.0
2021 PO4012284821	F	4	30 BRN	SP	CRE			V	00:00.0

2021 PO4012984817	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4011984805	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4012584805	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4012484791	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4012284778	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4000284252	LGE	3	45 ACE	SP	CCA	ED	V	00:00.0
2021 PO4000784252	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0
2021 PO7197571331	KU	1	80 ACE	SP	CCA		V	00:00.0
2021 PO1659595505	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4001284268	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4000684271	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO3999184265	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO3998584273	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO1633895803	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO7693373346	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO1660095948	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO9814497450	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4026384595	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4026584594	F	3	45 ACE	SP	P		V	00:00.0
2021 PO4026984594	F	3	45 ACE	SP	P		V	00:00.0
2021 PO7645173060	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4028384591	F	3	45 ACE	SP	P		V	00:00.0
2021 PO7628272958	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7576072651	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7593272745	KU	1	40 ACE	SP	CCA		V	00:00.0
2021 PO7611072853	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4030084588	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4031584586	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO7556572536	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7538172428	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4033384587	F	3	45 ACE	SP	A		V	00:00.0
2021 PO4032684586	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4035184584	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4037184582	F	3	45 ACE	SP	P		V	00:00.0
2021 PO4038284581	F	3	45 ACE	SP	P		V	00:00.0
2021 PO4032283246	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4031883239	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4029383258	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4027983270	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4024983293	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4026483281	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3999284291	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO3998684286	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3998784291	F	4	40 ACE	SP	P		V	00:00.0
2021 PO7672471544	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7659971556	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7668771434	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7676471305	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7683771163	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7686971016	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7683170871	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7681270722	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO3998884301	F	4	40 ACE	SP	A		V	00:00.0
2021 PO3994283934	F	4	30 BRO	SP	CRE		V	00:00.0



2021 PO3992683887	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO0040578363	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO0046578096	KU	4	45 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021 PO4008484616	F	UNK	45 ACE	SP	A	ED	VX	RP2	00:00.0
2021 PO9971499422	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9967999510	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9935899305	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO3992783900	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO0858399947	KU	5	35 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO0884200630	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO0769000189	F	4	40 KOP	SP	CRE		V	00:00.0	
2021 PO0788100185	F	4	40 KOP	SP	CRE		V	00:00.0	
2021 PO0810500183	F	4	40 KOP	SP	CRE		V	00:00.0	
2021 PO0875899780	KU	4	45 KOP	SP	CRE	ID	TD	00:00.0	
2021 PO9883198811	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7454969710	KU	3	40 ACE	SP	CCA		V	00:00.0	
2021 PO4023884599	F	4	35 ACE	SP	CRE		V	00:00.0	
2021 PO4025284597	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4058683972	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4058883983	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO4058283972	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4059883972	LGE	4	40 BRO	SP	CCA	ED,ID	TD	00:00.0	
2021 PO4028684078	LGE	UNK	95 BRO	SP	CRE		V	00:00.0	
2021 PO4027684060	LGE	UNK	90 BRO	SP	CRE		V	00:00.0	
2021 PO4026784042	LGE	UNK	90 BRO	SP	CRE		V	00:00.0	
2021 PO4023683982	LGE	UNK	95 BRO	SP	CRE		V	00:00.0	
2021 PO4023183972	LGE	3	45 BRO	SP	A	ED,ID	BD	00:00.0	
2021 PO4024984006	LGE	UNK	90 BRO	SP	CRE		V	00:00.0	
2021 PO4025484020	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4025884024	LGE	UNK	90 BRO	SP	CRE		V	00:00.0	
2021 PO4026184016	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4027784008	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4029584000	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4032684004	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4030984002	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4073284250	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO1713794942	KU	4	45 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO9859286828	KU	5	30 BRN	SP	CCA		V	00:00.0	
2021 PO9895387219	KU	3	45 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021 PO9871786882	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0	
2021 PO9923686642	KU	4	40 BRN	SP	CRE	ED,SRS	TD	00:00.0	
2021 PO9876086703	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021 PO9889386800	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO3983883663	F	4	30 BRO	SP	CRE		V	00:00.0	
2021 PO4531188011	LGE	2	65 BRO	SP	CRE	ED,ID,IP	BD	00:00.0	
2021 PV4530688009	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4912284778	LGE	4	40 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021 PO5390606223	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO5400406169	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5402606210	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO5410706165	KU	4	40 XXX	SP	CRE	ID,IP	TD	00:00.0	
2021 PO4374985269	LGE	5	30 BRN	SP	P	ED,ID	TD	00:00.0	
2021 PO7868177813	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO7745582831	KU	4	40 ACE	SP	CCA		V	00:00.0	

2021 PO7850977412	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO7838377969	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7834278254	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7830178555b	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7830178555a	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7830178555	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7846978271	KU	6	30 ACE	SP	CCA		V		00:00.0
2021 PO7528578059	KU	2	70 ACE	SP	CRE		V		00:00.0
2021 PO7536578068	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7554578091	KU	2	70 ACE	SP	CRE		V		00:00.0
2021 PO7581778125	KU	2	70 ACE	SP	CRE	ED,ID,IP	V		00:00.0
2021 PO4445585775	LGE	3	50 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4446185820	LGE	3	55 BRO	SP	CCA		V		00:00.0
2021 PO5497508172	F	3	55 XXX	SP	S		V		00:00.0
2021 PO5517308093	F	4	40 XXX	SP	S		V		00:00.0
2021 PO5508608127	F	3	45 XXX	SP	S		V		00:00.0
2021 PO6081152656	F	5	35 OTH	SP	CRE		V		00:00.0
2021 PO6087452475	F	4	40 OTH	SP	A		V		00:00.0
2021 PO6093352518	F	5	35 OTH	SP	A		V		00:00.0
2021 PO6096452459	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO6100852403	F	6	30 OTH	SP	CRE		V		00:00.0
2021 PO6094952357	F	4	40 OTH	SP	A		V		00:00.0
2021 PO4450985840	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4452485840	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4436585822	LGE	2	60 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4446785863	LGE	3	55 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO6291950791	KU	4	40 OTH	SP	CRE	ED,HH,ID,RB	BX	RP2	00:00.0
2021 PO6286750941	KU	3	50 OTH	SP	CRE	ID	BD		00:00.0
2021 PO6294951005	KU	4	45 OTH	SP	CRE	ID,IP	BD		00:00.0
2021 PO6282050842	KU	3	50 OTH	SP	CRE	ID,IP	BD		00:00.0
2021 PO4446585828	LGE	3	65 BRO	SP	CRE		V		00:00.0
2021 PO4442585731	LGE	3	50 BRO	SP	A	ED,ID,IP	BD		00:00.0
2021 PO6276950721	KU	3	45 OTH	ST	CCA		V		00:00.0
2021 PO6270450754	KU	4	45 OTH	SP	CRE	ID,IP	BD		00:00.0
2021 PO6264350785	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO5556407949	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5557407977	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5561607929	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5576007875	F	4	40 XXX	SP	S		V		00:00.0
2021 PO4445585771	LGE	3	50 BRO	SP	A	ED,ID,IP	BD		00:00.0
2021 PO5597507794	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5608307753	F	5	40 XXX	SP	CRE		V		00:00.0
2021 PO5591607817	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5593307860	F	5	30 XXX	SP	CRE		V		00:00.0
2021 PO5620107708	F	4	40 XXX	SP	P		V		00:00.0
2021 PO5622707651	F	5	30 XXX	SP	CRE		V		00:00.0
2021 PO5624507692	F	4	40 XXX	SP	S		V		00:00.0
2021 PO5634407654	F	4	40 XXX	SP	S		V		00:00.0
2021 PO5403608530	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5412608496	F	4	40 XXX	SP	S		V		00:00.0
2021 PO4445885799	LGE	3	55 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO5483108226	F	2	60 XXX	SP	S		V		00:00.0
2021 PO4445485800-A	LGE	4	30 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4445385790	LGE	3	45 BRO	SP	P	ED,ID	TD		00:00.0

2021 PO4445485800	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO6078853005	F	6	30 OTH	SP	P		V	00:00.0
2021 PO6117853063	KU	6	30 SWP	SP	CRE	ID	BD	00:00.0
2021 PO6057652951	F	4	40 OTH	SP	A		V	00:00.0
2021 PO6064352832	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO6070752730	F	4	40 OTH	SP	A		V	00:00.0
2021 PO6075952736	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021 PO5648007601	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5542608000	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4446085814-A	KU	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4447985844	LGE	4	35 BRO	SP	A	ED,ID,IP	BD	00:00.0
2021 PO4445185772	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4449485842	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021 PO6053053121	KU	5	35 OTH	SP	CRE	ID	BD	00:00.0
2021 PO6053053033	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO5417808477	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5427108380	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5430408427	F	4	45 XXX	SP	S		V	00:00.0
2021 PO5444008373	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5467908283	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5454208335	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5656007571	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO5669407523	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5667907479	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5671707586	F	4	40 XXX	SP	S		V	00:00.0
2021 PO5681507476	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5690107444	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5190984396	LGE	4	25 ACE	SP	CCA		V	00:00.0
2021 PO5191084401	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4443385737	LGE	1	75 BRO	SP	A		V	00:00.0
2021 PO4444085742	LGE	1	75 BRO	SP	A		V	00:00.0
2021 PO4444485745	LGE	1	75 BRO	SP	CRE		V	00:00.0
2021 PO4446585760	LGE	2	65 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4447585768	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4445585777	LGE	3	50 BRO	SP	P	ED,ID	TD	00:00.0
2021 5194584412-a	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO4984284912	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4964384920	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5182284275	LGE	4	35 ACE	SP	P		V	00:00.0
2021 PO5187384269	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO5185984276	LGE	4	35 ACE	SP	CCA	ED	BD	00:00.0
2021 PO5186684256	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5186684226	LGE	3	45 ACE	SP	P		V	00:00.0
2021 PO4963684923	LGE	3	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4962784903	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4963784926	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5189984235	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5188384245	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO9074056038	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5607867085	LGE	4	40 ACE	SP	CRE	ED	TD	00:00.0
2021 PO4446085814	LGE	3	50 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO4445785787	LGE	3	50 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4446285827	LGE	3	55 BRO	SP	CRE	ED,EP,ID,IP	BD	00:00.0
2021 PO4445485749	LGE	4	40 BRO	SP	CCA		V	00:00.0

2021 PO4441610281	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO5213784175	LGE	4	40 ACE	SP	P	ED	BD	00:00.0	
2021 PO5205384176	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0	
2021 PO5207184187	LGE	4	40 ACE	SP	P	ED	BD	00:00.0	
2021 PO5209184197	LGE	4	40 ACE	SP	P	ED	BD	00:00.0	
2021 PO5215184216	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0	
2021 PO5213284207	LGE	3	45 ACE	SP	P	ED	BD	00:00.0	
2021 PO4960684938	F	4	30 BRO	SP	CRE		VX	RP1	00:00.0
2021 PO4959184938	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO5211384199	LGE	4	40 ACE	SP	P	ED	BD	00:00.0	
2021 PO5211484195	LGE	4	30 ACE	SP	CCA		V	00:00.0	
2021 PO4959384942	F	4	30 BRO	SP	A		V	00:00.0	
2021 PO4956584945	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO5215984190	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0	
2021 PO5091985295	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0	
2021 PO5094585251	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO4982584898	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO5092585263	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO4981684894	LGE	3	45 BRO	SP	A	ID	BD	00:00.0	
2021 PO4983784873	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4984584876	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4490711580	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4498511532	KU	6	35 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO4986184812	LGE	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4985484834-A	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4985484834	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4984185031	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO4983985026	F	4	30 BRO	SP	A		V	00:00.0	
2021 PO6986863634	LGE	1	50 BRO	SP	CCA		V	00:00.0	
2021 PO4986784770	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO5217084207	LGE	3	45 ACE	SP	P	ED	BD	00:00.0	
2021 PO4956684951	F	4	35 BRO	SP	A		V	00:00.0	
2021 PO5209984146	LGE	4	40 ACE	SP	A	ED	BD	00:00.0	
2021 PO9257554996	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO9242954856	LGE	3	45 ACE	SP	CCA		BD	00:00.0	
2021 PO9228854718	LGE	3	45 ACE	SP	CCA		BD	00:00.0	
2021 PO9214554579	LGE	3	45 ACE	SP	CCA		BD	00:00.0	
2021 PO9188554332	LGE	3	45 ACE	SP	CCA		BD	00:00.0	
2021 PO9199254431	LGE	3	45 ACE	SP	CCA		BD	00:00.0	
2021 PO2039682383	LGE	1	55 UNK	SP	CCA		V	00:00.0	
2021	2091813854	LGE	4	30 ACE	SP	CCA	V	00:00.0	
2021 PO9165054339	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5096485239	LGE	1	60 ACE	SP	CRE		V	00:00.0	
2021 PO5096285253	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO4977884902	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4917711570	KU	5	35 XXX	SP	CCA		V	00:00.0	
2021 PO4952411602	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4940111648	F	4	40 XXX	SP	CRE	HH,IP,RB	BX	PX	00:00.0
2021 PO4947611493	KU	5	35 XXX	SP	CRE	ED,HH,ID	X	RP3	00:00.0
2021 PO4955811256	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4945011300	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4938811415	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4960111965	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO4963511565	F	4	40 XXX	SP	CRE		V	00:00.0	

2021 PO4962311882	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4963911802	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4954211838	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4950011725	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4942111883	F	4	40 XXX	SP	CRE	ID	V	00:00.0
2021 PO4930511683	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4932111918	F	4	40 XXX	SP	CRE	IP	B	00:00.0
2021 PO5160384371	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021 PO4926411795	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4935912084	F	4	40 XXX	SP	CRE	ID	V	00:00.0
2021 PO4945611972	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4965912214	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4968212350	F	4	40 XXX	SP	CRE		B	00:00.0
2021 PO4970212488	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4988413046	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4978913045	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO5152884407	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0
2021 PO5155584399	LGE	3	45 ACE	SP	P		V	00:00.0
2021 PO5156784380	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO5157384391	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO4845885661	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4442210458	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4460110704	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4472210651	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4452210733	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4457910883	F	4	40 XXX	SP	CRE	ED,HH,ID	BX PX	00:00.0
2021 PO4464910856	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4478010802	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4465311070	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4485310988	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4472811040	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO4479411202	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4491711152	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4499311345	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4486811395	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4479311431	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5211884161	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0
2021 PO4978684906	LGE	4	35 BRO	SP	CRE	ED,ID,RB	X RP1	00:00.0
2021 PO4852385386	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO4850185393	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4849985385	LGE	6	30 ACE	SP	CRE	ED,HH,ID	VX PX	00:00.0
2021 PO4848685382	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4846585403	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4498887920	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4500187921	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4500887922	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4503787910	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5190184465	LGE	4	40 ACE	SP	P		V	00:00.0
2021 PO5182384393	LGE	4	40 ACE	SP	CCA		BD	00:00.0
2021 PO4415410398	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4418510307	KU	6	30 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5186984254	LGE	3	45 ACE	SP	P	ED	TD	00:00.0
2021 PO5185084396	LGE	4	40 ACE	SP	P	ED	BD	00:00.0

2021	PO5187684407	LGE	3	45 ACE	SP	CCA	ED	BD	00:00.0
2021	PO5192084424	LGE	4	35 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4427910333	KU	6	30 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4424310258	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4434210257	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4439710199	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4432310228	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4922811393	KU	5	35 XXX	SP	CRE	HH,ID	X RP3	00:00.0
2021	PO4972612633	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4981012917	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4974512753	F	4	40 XXX	SP	CRE	HH,RB	BX PX	00:00.0
2021	PO4944812257	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4942312181	F	5	35 XXX	SP	CRE		V	00:00.0
2021	PO4930711223	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4929111068	F	5	35 XXX	SP	P		V	00:00.0
2021	PO4923411088	F	3	40 XXX	SP	P		V	00:00.0
2021	PO4914911120	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4917111419	F	4	40 XXX	SP	CCA		V	00:00.0
2021	PO4902211160	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4903611312	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4455310247	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4452310173	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5189184325	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO5191584358	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO5200684356	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO5199984351	LGE	4	30 ACE	SP	P		V	00:00.0
2021	PO5204384165	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0
2021	PO4962284928	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4953884944	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4960584934	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4461910412	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4447910419	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5160484381	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO5164384368	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021	PO5164484381	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO8846857359	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5171584386	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5173384247	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO5173884252	LGE	4	25 ACE	SP	P		V	00:00.0
2021	PO5174784259	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO5176184271	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO5174484389	LGE	3	45 ACE	SP	P		V	00:00.0
2021	5182384393-a	LGE	3	45 ACE	DF	CCA		V	00:00.0
2021	PO4503087922	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4846485653	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4406010794	KU	6	30 XXX	SP	CRE		V	00:00.0
2021	PO7542880575	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7542780487	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4470288338	F	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4000683692	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4468788219	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO3997183751	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO3993883721	F	4	40 BRO	SP	A		V	00:00.0
2021	PO3994983730	F	4	30 BRO	SP	CRE		V	00:00.0

2021 PO3993183707	F	5	25 BRO	SP	A	V	00:00.0
2021 PO3997183697	F	3	45 BRO	SP	A	V	00:00.0
2021 PO4468988209	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4469088202	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4469288188	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4469388182	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO5249323161	KU	3	45 UNK	SP	CCA	V	00:00.0
2021 PO5261323233	KU	5	35 UNK	SP	CCA	V	00:00.0
2021 PO4000583738	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5197423148	KU	4	45 UNK	SP	CCA	V	00:00.0
2021 PO5218423208	KU	4	45 UNK	SP	CCA	V	00:00.0
2021 PO4010183503	F	4	40 BRO	SP	A	V	00:00.0
2021 PO4010883494	F	3	45 BRO	SP	A	V	00:00.0
2021 PO4011283489	F	3	45 BRO	SP	A	V	00:00.0
2021 PO5200923514	KU	2	45 UNK	SP	CCA	V	00:00.0
2021 PO4468188219	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4464588274	F	4	35 ACE	SP	CCA	V	00:00.0
2021 PO2504183625	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4462788270	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4462588271	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4000083700	LGE	UNK	35 BRO	SP	CRE	V	00:00.0
2021 PO3999383688	F	4	40 BRO	SP	P	V	00:00.0
2021 PO4000283685	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4000883683	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4001583680	F	3	45 BRO	SP	CRE	V	00:00.0
2021 PO8053777089	KU	6	30 ACE	SP	CCA	V	00:00.0
2021 PO8049977235a	KU	1	60 ACE	ST	CCA	V	00:00.0
2021 PO4459788218	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO8040877037	KU	3	55 ACE	SP	CCA	V	00:00.0
2021 PO3994483732	F	3	45 BRO	SP	A	V	00:00.0
2021 PO3992483715	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO3993383712	F	4	40 BRO	SP	A	V	00:00.0
2021 PO3995383717	LGE	4	35 BRO	SP	A	V	00:00.0
2021 PO3996383709	LGE	4	30 BRO	SP	A	V	00:00.0
2021 PO3994583707	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO3996083701	F	4	40 BRO	SP	A	V	00:00.0
2021 PO5600684724	F	4	40 UNK	SP	CCA	V	00:00.0
2021 PO5579784814	F	4	40 UNK	SP	CCA	V	00:00.0
2021 PO5550884997	F	4	40 UNK	SP	CCA	V	00:00.0
2021 PO9242058346	ODP	4	40 BRO	SP	S	V	00:00.0
2021 PO5691585054	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5724385265	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO9216758517	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO8039477412	KU	1	80 ACE	ST	CRE	V	00:00.0
2021 PO9326557489	ODP	3	45 BRO	DF	CRE	V	00:00.0
2021 PO8016876793	KU	6	30 ACE	SP	CCA	V	00:00.0
2021 PO8027776808	KU	5	35 ACE	SP	CCA	V	00:00.0
2021 PO4002783701	F	3	45 BRO	SP	A	V	00:00.0
2021 PO9017967448	ODP	4	45 XXX	SP	CCA	V	00:00.0
2021 PO9317857689	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO9324558047	ODP	6	30 BRO	SP	S	V	00:00.0
2021 PO9056968227	ODP	3	45 XXX	SP	CCA	V	00:00.0
2021 PO9346557274	ODP	5	35 BRO	SP	S	V	00:00.0
2021 PO9433858552	F	4	40 BRO	SP	CRE	V	00:00.0

2021 PO9432758828	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO9452959003	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO5488385672	F	4	40 UNK	SP	CRE		V			00:00.0
2021 PO7991977748	F	5	35E ACE	SP	CCA		V			00:00.0
2021 PO4001783608	LGE	4	40 BRO	SP	CCA		V			00:00.0
2021 PO4468288382	LGE	4	40 ACE	SP	CRE	ED,ID	VX		RP2	00:00.0
2021 PO9089168797	ODP	4	40 XXX	SP	CRE	HH,ID	X		PX	00:00.0
2021 PO4968425387	KU	4	45 UNK	SP	CRE		B			00:00.0
2021 PO4955525459	KU	6	30 UNK	SP	CRE		B			00:00.0
2021 PO4954825518	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO4957525266	KU	6	30 UNK	SP	CRE		B			00:00.0
2021 PO4956325371	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO4958725158	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO4959825057	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO5238622873	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO5247823029	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5345722478	KU	3	45 UNK	SP	CRE		B			00:00.0
2021 PO5307122809	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO5274722655	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO5254922775	KU	4	40 UNK	SP	CRE		B			00:00.0
2021 PO8051676990	KU	2	35E ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO4460088293	LGE	4	30 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO8008177326a	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO4460688310	LGE	4	45 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4463488319	LGE	4	40 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO4464088314	LGE	4	40 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO4463588313	LGE	4	40 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO4461888313	LGE	4	40 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO9043558082	ODP	5	35 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO8021876120	KU	4	40 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO8028976303a	KU	5	35 ACE	SP	P	ED,ID	BD			00:00.0
2021 PO8032476522	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO4465788321	LGE	4	45 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO4466988312	LGE	4	30 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO4465988317	LGE	4	40 ACE	SP	A	ED,ID	BD			00:00.0
2021 PO7918474601	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO2771989896	KU	4	40 BRO	SP	CRE	IP,MD	BD			00:00.0
2021 PO7889074502a	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO7889074502	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO7868074377	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO7881474457	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO8001175020	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD			00:00.0
2021 PO7989675540	KU	4	45 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO4463788224	LGE	4	35 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO8001775755	KU	4	45 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO8968758111	ODP	4	40 BRO	SP	CRE	ED,ID	BD			00:00.0
2021 PO4462688233	LGE	4	30 ACE	SP	CRE	ED,ID	BD			00:00.0
2021 PO7995375646	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX		PX	00:00.0
2021 PO866054277	ODP	5	35 XXX	SP	CCA	ED	T			00:00.0
2021 PO0772751333	KU	3	45 BRN	SP	CCA		T			00:00.0
2021 PO4984925549	KU	4	40 UNK	SP	CRE		T			00:00.0
2021 PO4967325491	KU	4	40 UNK	SP	CRE		T			00:00.0
2021 PO5294823106	KU	5	35 UNK	SP	CRE		T			00:00.0
2021 PO4461088287	LGE	4	40 ACE	SP	CRE	ED,ID	TD			00:00.0



2021 PO8008377100	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4460888300	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO9102558161	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9068958290	ODP	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0763251339	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4461188310	LGE	4	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8016577132	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8008177326	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8605652980	ODP	6	30 XXX	SP	CRE	ID,IP	TD	00:00.0
2021 PO8602153129	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8537252996	ODP	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8534752811	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4463388261	LGE	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO8517952977	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9019658087	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9017358384	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9035658224	ODP	5	35 BRO	DF	CRE	ED,ID,IP	TD	00:00.0
2021 PO8040276724	KU	2	70 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8036376864	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0787351832	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0778251419	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0781851535	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4463588234	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8936458578	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8917658827	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8937858861	ODP	5	35 BRO	DF	CRE	ED,ID	TD	00:00.0
2021 PO0782751388	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO0785951326	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO4463588205	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO0783551240	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8976658287	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8962958394	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8014475983	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2464283194	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4463188241	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO2447183154	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO8624853577	ODP	4	40 XXX	SP	CRE	ID,IP	TD	00:00.0
2021 PO8614053292	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8958058250	ODP	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9091156655	ODP	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9076857064	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2759289930	KU	4	40 BRO	SP	CRE	ID,IP,SRS	TD	00:00.0
2021 PO2733690118	KU	5	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2750489953	KU	4	40 BRO	SP	CRE	ED,IP,MD,SRS	TD	00:00.0
2021 PO2718190051	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2711390072	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2686890140	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2678790156	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO0808051312	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO0796751320	KU	4	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO9100756386	ODP	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2750690140	KU	6	30 BRO	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021 PO2762690104	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO0601153879	KU	3	40 INP	SP	CRE	ID	TD	00:00.0

2021 PO0818051373	KU	5	35 INP	SP	CRE	ID	TD	00:00.0
2021 PO8647554141	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8645553839	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8662153663	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7960974873	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0535155738	KU	3	50 INP	SP	CRE	ID	TD	00:00.0
2021 PO0603053886	KU	3	40 INP	SP	CRE	ID	TD	00:00.0
2021 PO7988675822	KU	6	30 ACE	SP	CRE	ED,EP,ID,IP,RB	TX RR	00:00.0
2021 PO1724894516	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO7983775412	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8001175522	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO9007358299	ODP	6	30 BRO	SP	S		V	00:00.0
2021 PO8951958070	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8947057866	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO8005975708	F	5	35 ACE	SP	P		V	00:00.0
2021 PO8002575651	F	5	35 ACE	SP	P		V	00:00.0
2021 PO8007275847	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8973858400	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4463288234	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7919874632	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO7896874495	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO7906974554	F	4	40 ACE	SP	A		V	00:00.0
2021 PO2783590018	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO2753490126	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9115456027	ODP	5	35 BRO	SP	S		V	00:00.0
2021 PO2735190169	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO2742490152	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8958258612	ODP	6	30 BRO	SP	CRE		V	00:00.0
2021 PO8963058742	ODP	5	35 BRO	SP	S		V	00:00.0
2021 PO8951258854	ODP	4	45 BRO	SP	S		V	00:00.0
2021 PO8964558847	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO8968458742	ODP	3	45 BRO	SP	S		V	00:00.0
2021 PO8969258617	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO9081356934	ODP	4	45 BRO	SP	S		V	00:00.0
2021 PO0789651943	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4462888260	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4463088247	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8636953182	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO0784551681	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4466488318	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO8028476621	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8028976303	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4967025542	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO9042958330	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO9053158409	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO8527852910	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8578353016	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8575853316	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8614453003	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4459888308	F	4	35 ACE	SP	A		V	00:00.0
2021 PO5332722345	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5328022333	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO4461188306	F	4	30 ACE	SP	A		V	00:00.0
2021 PO4458988307	F	4	35 ACE	SP	A		V	00:00.0

2021 PO4458188306	F	4	35 ACE	SP	A		V		00:00.0
2021 PO9095058351	ODP	4	45 BRO	SP	S		V		00:00.0
2021 PO0793052100	F	3	45 UNK	SP	CCA		V		00:00.0
2021 PO0796652253	F	4	40 UNK	SP	CCA		V		00:00.0
2021 PO4458188289	F	4	30 ACE	SP	A		V		00:00.0
2021 PO4459388292	F	4	30 ACE	SP	A		V		00:00.0
2021 PO8010277013	KU	4	40 ACE	SP	P		V		00:00.0
2021 PO4461488295	F	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4461588288	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO7959274869	F	3	45 ACE	SP	CRE		V		00:00.0
2021 PO7956174762	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7944774782	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO7932474707	F	4	40 ACE	SP	P		V		00:00.0
2021 PO9229454674	F	4	40 BRO	SP	P		V		00:00.0
2021 PO0806351441	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO0796851212	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO8639253509	ODP	3	45 XXX	SP	CCA		V		00:00.0
2021 PO0780751328	KU	6	30 INP	SP	CRE	ID	X	RP2	00:00.0
2021 PO7963175061	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7954375117	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7947475156	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7976175235	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7965574993	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO8152379799	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8171979015	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8161179005	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8160179150	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO8159179282	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8153679372	F	4	40 ACE	SP	P		V		00:00.0
2021 PO8152579550i	KU	6	30 ACE	ST	CCA		V		00:00.0
2021 PO8152579550h	KU	6	30 ACE	ST	CCA		V		00:00.0
2021 PO4821291399	LGE	4	40 BRN	SP	A	ED,ID,SRS	TD		00:00.0
2021 PO4822691401	LGE	4	40 BRN	SP	A	ED,HH,ID	VX	RP1	00:00.0
2021 PO4822991359	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO7774482055	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO5171584812	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4400285491	F	4	40 ACE	SP	P	ED	VX	PX	00:00.0
2021 PO4399585499	F	4	40 ACE	SP	P	ED	V		00:00.0
2021 PO4398585509	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4398085514	F	4	30 ACE	SP	P		V		00:00.0
2021 PO4362785959	LGE	3	55 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4361685967	F	4	35 ACE	SP	P	ED	V		00:00.0
2021 PO4360585983	LGE	6	30 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4395786022	LGE	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4394586028	LGE	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4923484985	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4924584998	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO8555263009	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8543363145	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8571962857	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO5169184782	LGE	4	30 ACE	SP	P		V		00:00.0
2021 PO4375485263	LGE	5	35 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO0141629181	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO0151229144	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0

2021	PO0160929104	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0170529063	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4363785653	LGE	1	50 ACE	SP	CCA	ED	V	00:00.0
2021	PO4373285662A	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021		4374785642	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021		43755856322	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021		4376185623	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO4361885561A	LGE	2	50E ACE	SP	P	ED	BD	00:00.0
2021	PO0181129017	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0189328983	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX	PX 00:00.0
2021	PO0208428900	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0218228855	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4374084898	LGE	3	45E BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4374084887	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO0196230319	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0180330318	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4374084883	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4374084877	LGE	3	45E BRN	SP	A	ED,ID	BD	00:00.0
2021	PO4361885561	LGE	2	60 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4362685551	LGE	2	55 ACE	SP	CRE	ED	BD	00:00.0
2021	PO0174230209	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO0170530168	KU	1	40 ACE	SP	CCA		V	00:00.0
2021	PO0180130062	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4364685526	LGE	1	60 ACE	SP	CRE	ED,IP	BD	00:00.0
2021	PO0192930006	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO0188829970	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4374484864	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021	PO4373984862	LGE	3	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021	PO4373784767	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4985584963	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4984885003	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4984985010	F	4	40 BRO	SP	A		V	00:00.0
2021	PO5026684811	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5024084806	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4373984827	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4988884974	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4986784970	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4373884816	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4986384960	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4373884804	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4373884791	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4985684987	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4985384989	F	4	30 BRO	SP	CCA		V	00:00.0
2021	PO4985185004	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PV4373884769	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4373884769	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4988784934	F	3	45 BRO	SP	A		V	00:00.0
2021	PO4986484906	F	4	40 BRO	SP	A		V	00:00.0
2021	PO7044262387	F	4	45 BRO	SP	CCA		V	00:00.0
2021	PO4987084936	F	3	45 BRO	SP	A		V	00:00.0
2021	PO4365485666	LGE	3	45 ACE	SP	P	ED	TD	00:00.0
2021	PO4367085678	LGE	3	45 ACE	SP	CRE	ED	TD	00:00.0
2021	PO4368785685	F	4	30 ACE	SP	P	ED	V	00:00.0
2021	PO4368685689	LGE	3	45 ACE	SP	P	ED	TD	00:00.0

2021	PO4370685702	LGE	3	45 ACE	SP	CRE	ED,IP	TD	00:00.0
2021	PO4373285662	LGE	3	45 ACE	SP	CRE	ED,IP	TD	00:00.0
2021	PO4371484933	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021	PO4374285649	LGE	3	45 ACE	SP	CRE	ED,IP	TD	00:00.0
2021	PO4374284948	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4374184927	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4374184917	LGE	5	40E BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO0070729477	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4374184907	LGE	4	40 BRN	SP	CCA	ED,ID	BD	00:00.0
2021	PO0087029407	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4368185607	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021	PO4367885625	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021	PO4369085634	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021	PO4368285644	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4367385648	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	PO0110429308	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0315930560	KU	3	55 ACE	SP	CCA		V	00:00.0
2021	PO0325330475	KU	4	40 ACE	SP	CRE		V	00:00.0
2021	PO0331730370	KU	4	40 ACE	SP	CRE		V	00:00.0
2021	PO0339130185	KU	3	45 ACE	SP	CRE		V	00:00.0
2021	PO0338830113	KU	3	40 ACE	SP	CCA		V	00:00.0
2021	PO0322530104	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO0302528988	KU	1	40 ACE	SP	CRE		V	00:00.0
2021	PO0302828973	KU	1	40 ACE	SP	CRE		V	00:00.0
2021	PO4366185652A	LGE	4	40 ACE	SP	CRE	ED	V	00:00.0
2021	PO4366185653	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4366185652	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4366385646	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021	4365285632	LGE	3	45 ACE	SP	P		V	00:00.0
2021	4365285630	LGE	3	20 ACE	SP	P		V	00:00.0
2021	4365485629	LGE	3	45 ACE	SP	P		V	00:00.0
2021	4365385631	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	4365485630	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO4365285636	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021	4364385640	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4361985640	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4360685604	LGE	4	35 ACE	SP	P		V	00:00.0
2021	PO0121129260	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0114429263	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO0132529215	KU	4	35 ACE	SP	CCA		V	00:00.0
2021	PO0124229222	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO0134229137	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4374384849	LGE	4	35 BRN	SP	A	ED,ID	TD	00:00.0
2021	PO4365985534	LGE	4	35 ACE	SP	CCA	ED	BD	00:00.0
2021	PO4365485535	LGE	3	45 ACE	SP	P	ED	TD	00:00.0
2021	PO4367285542	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021	PO0197229873	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO0205529791	KU	5	35 ACE	SP	CCA		V	00:00.0
2021	PO0206929853	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4374584847	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021	PO4373984852	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4373984847	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO0225429654	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0220029613	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0

2021	PO0233229458	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO0243429456	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO0241429360	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO0247729284	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4368585550	LGE	3	45 ACE	SP	P	ED	TD	00:00.0
2021	PO4367385550	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO0257329285	KU	4	45 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO0254529202	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO0274029086	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO0261929111	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO0285230688	KU	7	40 ACE	DF	CCA		V	00:00.0
2021	PO0300730659	KU	3	50 ACE	CON	CCA		V	00:00.0
2021	PO4373984837	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5345407404A	KU	6	30 INP	SP	CRE	ID	BD	00:00.0
2021	PO4474306388	KU	3	50 XXX	SP	CCA		V	00:00.0
2021	PO5472314007	KU	3	50 XXX	SP	CCA		V	00:00.0
2021	PO5481713763	KU	2	60 XXX	SP	CCA		V	00:00.0
2021	PO5370714353	KU	6	30 XXX	SP	CRE		V	00:00.0
2021	PO4364512617	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO4356312730	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4351312716	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4347212794	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO4332012804	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4328812814	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4324612651	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4311112540	KU	6	30 XXX	SP	CCA		V	00:00.0
2021	PO4312112563	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO4321612552	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4933684829	LGE	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4915184960	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4913384986	LGE	4	45 BRO	SP	CCA		V	00:00.0
2021	PO4916384945	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4917484929	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4919084933	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4922984926	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4925984893	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4982584920	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4982184927	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4983984936	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4984384930	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4985784924	F	4	35 BRO	SP	A		V	00:00.0
2021	PO4985484935	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4329112439	KU	6	30 XXX	SP	P	ID	BD	00:00.0
2021	PO4318112386	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4326912298	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4392112702	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO4385812697	KU	3	50 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4382012598	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4381512484	KU	3	45 XXX	SP	CRE	ID	BD	00:00.0
2021	PO4389712874	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO4901785126	LGE	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2330692466	LGE	4	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO4538588044	LGE	2	65 BRO	DF	CRE	ED,ID,IP	TD	00:00.0
2021	PO4538388027	LGE	3	55 BRO	SP	CRE	ED,ID,IP	BD	00:00.0

2021	PO4537588039	LGE	2	65 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4536088033	LGE	2	65 BRO	DF	CRE	ED,ID,IP	TD		00:00.0
2021	PO4931484851	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4899585114	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4536588028	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021	PO4534688026	LGE	2	65 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4533188020	LGE	2	65 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4517387770	LGE	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4532688007	LGE	6	25 BRO	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021	PO4899185135	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4896885132	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4899085130	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021	PO4896885167	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4894685217	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4517787746	LGE	4	25 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4518287746	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PV4514187715	LGE	5	35 BRO	SP	A		B		00:00.0
2021	PO4511787726	LGE	5	35 BRO	SP	CCA		V		00:00.0
2021	PO4512187718	LGE	4	40 BRO	SP	P		B		00:00.0
2021	PO4513187716	F	3	50 BRO	SP	CCA		V		00:00.0
2021	PV4519187713	LGE	4	40 BRO	SP	A		B		00:00.0
2021	PV4519687703	LGE	4	40 BRO	SP	A		B		00:00.0
2021	PO4510687699	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO2200589494	LGE	4	35 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO4895685216	LGE	4	40 BRO	SP	CRE	ID,IP	TD		00:00.0
2021	PO5089085080	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO9878531403	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4364085731	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO4362785722	LGE	4	30 ACE	SP	P	ED,IP	TD		00:00.0
2021	PO4900585075	LGE	4	40 BRO	SP	A	ID	BD		00:00.0
2021	PO9933530846	KU	4	45 ACE	SP	CCA		V		00:00.0
2021	PO9925630946	KU	3	45 ACE	SP	CCA		V		00:00.0
2021	PO7967605159	KU	6	30 XXX	SP	S		V		00:00.0
2021	PO7976305230	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO7979305262	KU	3	45 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO4521687971	LGE	3	55 BRO	SP	P	ED,ID	BD		00:00.0
2021	PO0066731027	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4548487724	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021	PO4903085325	F	4	40 BRO	SP	CCA		V		00:00.0
2021	690669160	LGE	2	50 ACE	SP	CCA		V		00:00.0
2021	PO4356385687	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO4527987782	F	4	40 BRO	SP	P		V		00:00.0
2021	PO4533487778	LGE	3	45 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO0073228988	KU	2	40 ACE	SP	CCA		V		00:00.0
2021	PO0083829009	KU	2	40 ACE	SP	CCA		V		00:00.0
2021	PO0082628941	KU	2	40 ACE	DF	CCA		V		00:00.0
2021	PO0080728943	KU	2	40 ACE	SP	CCA		V		00:00.0
2021	PO0066529246a	KU	2	40 ACE	SP	CCA		V		00:00.0
2021	PO0066529246	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO0063229230	KU	4	40E ACE	SP	CCA		V		00:00.0
2021	PO0065829214	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO5076684870	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021	PO4921085068	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4356285680	LGE	3	50 ACE	SP	CRE	ED,IP	TD		00:00.0

2021	PO4356685683	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021	PO4356385676	LGE	4	30 ACE	SP	P	ED,ID	VX	PX	00:00.0
2021	PO4357085680	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO0719768939	LGE	4	40 ACE	SP	CCA	ED,ID,MD	BD		00:00.0
2021	PO4921885063	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4894485303	F	4	30 BRO	SP	CRE		V		00:00.0
2021	PO5079984852	F	3	45 ACE	SP	CRE		V		00:00.0
2021	PO5008507470	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5013207576	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5000707698	F	4	40 KOP	SP	CRE		V		00:00.0
2021	PO4994207764	F	3	45 KOP	SP	CRE		V		00:00.0
2021	PO4982707879	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4983507645	KU	6	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO4478688703	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4479288694	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4289713644	KU	3	45 KOP	SP	CCA		T		00:00.0
2021	PO7607377215	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7625077048	KU	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4475587514	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4474187522	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4476688411	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4900823756	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4477288418	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4467688202	F	4	35 ACE	SP	P		V		00:00.0
2021	PO4467988202	LGE	4	35E ACE	SP	P	ED	V		00:00.0
2021	PO4467988206	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4466188168	LGE	4	35 ACE	SP	P	ED	BD		00:00.0
2021	PO4472887509	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4896623930	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO7617377083	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO7605777004	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7618476990	KU	5	35 ACE	SP	CCA		V		00:00.0
2021	PO7600976877	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7626076883	KU	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO7626176787	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO7627176535	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4476988417	F	4	30 ACE	SP	CRE		V		00:00.0
2021	PO4887023886	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4475888408	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4474288406	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO7576276866	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4913424007	KU	5	35 BRO	SP	CRE		BD		00:00.0
2021	PO4858323491	KU	4	45 BRO	SP	CCA		V		00:00.0
2021	PO4836623733	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO4845223595	KU	5	35 BRO	SP	CCA		V		00:00.0
2021	PO4868723410	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021	PO4466188183	LGE	4	35 ACE	SP	CCA	ED	BD		00:00.0
2021	PO4264112810	KU	3	45 BRN	SP	CCA		T		00:00.0
2021	PO2805788336	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO2790288364	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO2808988278	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO2816488328	KU	6	30 BRO	SP	CRE	ED,IP,MD,SRS	TD		00:00.0
2021	PO4531287432	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4490988464	LGE	4	40 ACE	SP	CCA		V		00:00.0



2021 PO7625980007	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO7616780084	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO7614180057	KU	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO7615380124	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO4479387569	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7605479957	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7589879803	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7601279618	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7612379436	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7622379232	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7617778982	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7613278772	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7602978604	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO4921524298	KU	2	45 BRO	SP	CRE	ED	BD	00:00.0	
2021 PO4904624311	KU	4	40 BRO	SP	CRE	ED,ID	BX	RP1	00:00.0
2021 PO4883024329	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4803524401	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4491788385	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7586078445	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO4527987451	F	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4528487447	F	4	30 BRO	SP	P		V	00:00.0	
2021 PO4527387454	F	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4478887578	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4478087573	LGE	4	30 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO4809325244	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4810325213	KU	3	50 BRO	SP	CCA		V	00:00.0	
2021 PO4491888417	LGE	4	40 ACE	SP	CCA	ED	V	00:00.0	
2021 PO4491588402	LGE	4	35 ACE	SP	A	ED	V	00:00.0	
2021 PO4908107865	F	4	40 BRN	SP	P		V	00:00.0	
2021 PO4905307803	F	4	40 BRN	SP	P		V	00:00.0	
2021 PO4887507774	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4880507791	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4896607633	F	4	40 BRN	SP	S		V	00:00.0	
2021 PO4892907517	KU	6	30 BRN	SP	S		V	00:00.0	
2021 PO4877707414	KU	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4892907363	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4911007287	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4304713478	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4916507424	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4295913361	KU	3	45 KOP	SP	CRE		T	00:00.0	
2021 PO4921207532	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4493488367	LGE	4	40 ACE	SP	A		V	00:00.0	
2021 PO4492188368	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4915624613	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO4473688612	LGE	4	25 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4474188615	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4472988634	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4471688646	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO4471988650	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4473188073	LGE	3	55 ACE	SP	CRE	ED,EP,ID	BX	RR	00:00.0
2021 PO4473988059	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4470888656	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4484388616	LGE	4	40 ACE	SP	CRE	ED,ID,RB	X	RR	00:00.0
2021 PO4484788619	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	

2021 PO7523977624	KU	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4548487879	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4543687847	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4530987440	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4541987836	LGE	4	40 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4482288648	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4483288633	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4273313116	KU	3	45 BRN	SP	CCA		T	00:00.0
2021 PO5035709303	KU	2	70 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5066309318	KU	4	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5063409372	KU	2	70 XXX	SP	CCA		V	00:00.0
2021 PO4282213404	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4480888670	LGE	3	45 ACE	DF	CRE	ED	BD	00:00.0
2021 PO4479788686	LGE	4	40 ACE	SP	CRE	ED,HH,ID	BD	00:00.0
2021 PO4471188102	LGE	3	45E ACE	SP	P	ED	TD	00:00.0
2021 PO4278213435	KU	6	35 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4297913275	KU	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4293113651	KU	6	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO5122408886	KU	4	45 BRN	SP	S		V	00:00.0
2021 PO5107208943	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5098908986	KU	3	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4467888155	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4899907900	KU	5	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4284913657	KU	6	35 KOP	SP	CCA		V	00:00.0
2021 PO4280413581	KU	7	30 KOP	SP	CRE	ID	BD	00:00.0
2021 PO4471688104	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4476888748	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4476488728	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO2822088245	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO7647380449	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7653880387	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7658080342a	KU	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7658080342	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO7662180387	KU	4	45 ACE	SP	CCA		V	00:00.0
2021 PO4291413698	KU	3	50 KOP	SP	CCA		T	00:00.0
2021 PO4476988737	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4476988729	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO5018623525	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4472288118	LGE	3	50 ACE	SP	P	ED	BD	00:00.0
2021 PO5007223493	KU	5	30 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5000023537	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5027023457	KU	4	40 BRO	SP	CRE	ED,ID	T	00:00.0
2021 PO4996923451	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4480987544	LGE	4	40 BEL	SP	CRE		V	00:00.0
2021 PO4899308291	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4895008164	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4885207908	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4904808028	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4889908030	F	4	40 BRN	SP	CRE	ED,ID	BX	00:00.0
2021 PO7675180512	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7677980538	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4991123375	KU	5	35 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4987723328	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4492788448	LGE	1	50 ACE	SP	CCA		V	00:00.0

2021 PO7669780223	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4492388432	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4478587565	LGE	4	30 BEL	ST	CCA		V	00:00.0	
2021 PO4468788155	LGE	2	85 ACE	SP	A		V	00:00.0	
2021 PV4479088144	LGE	3	45E ACE	SP	CRE	ED,EP,ID,SRC	TD	00:00.0	
2021 PO4468988150	LGE	3	45 ACE	SP	A	ED,EP,ID,SRC	TX	RR	00:00.0
2021 PO4281413748	F	4	40 KOP	SP	P		V	00:00.0	
2021 PO4285013106	KU	7	30 KOP	SP	CCA		T	00:00.0	
2021 PO7657780046	KU	6	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7640180124	KU	6	30 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO2809288455	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021 PO4948323712	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4954623618	KU	2	40 BRO	SP	CRE	ED	BD	00:00.0	
2021 PO4960923712	KU	2	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4959923854	KU	4	40 BRO	SP	CRE	ED	BD	00:00.0	
2021 PO7626780252	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4490688463	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4473888405	F	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO7597576889	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7585876886	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO8587483722	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO8597783703	F	4	40 ACE	SP	CRE		V	00:00.0	
2021 PO4464187811	LGE	4	40 BEL	SP	A	ID	BD	00:00.0	
2021 PO4466288681	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4467788686	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4471388659	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4529687418-A	F	4	30 BRO	SP	P		V	00:00.0	
2021 PO4525887418	F	4	30 BRO	SP	CRE		V	00:00.0	
2021 PO4527987407	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4527387427	F	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4525487414	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4529687418	F	4	40 BRO	SP	P		V	00:00.0	
2021 PO4528387401	F	4	30 BRO	SP	P		V	00:00.0	
2021 PO4524787408	F	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4527987431	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4526587406	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4524487430	F	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4528787455	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO4492588347	LGE	3	45 ACE	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO4306313468	KU	7	35 KOP	SP	CRE		BD	00:00.0	
2021 PO4480587550	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4916924453	KU	2	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4915524804	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4492388355	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4488588457	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0	
2021 PO5025225389	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO4479987559	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO4478187589	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4303312712	KU	3	45 BRN	SP	CRE	ID,SRS	TD	00:00.0	
2021 PO7567877778	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4475087641	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4475787630	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4476187622	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4476787613	LGE	3	45 BRO	SP	CCA		V	00:00.0	

2021 PO4966007771	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4974207092	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4964607089	F	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4984907380	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4980707262	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4942407199	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4953606999	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4948706957	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4942706827	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4958006705	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4951506703	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4929806808	KU	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4927206729	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4927206729A	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4936406701	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4930006559	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4948106481	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4928706424	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO4932006479	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4926106478	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4909406471	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4893806467	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4874306462	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5238614322	KU	2	50 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7551377721	KU	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7551477784	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7558277928	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4477487601	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4487888455	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4486588451	LGE	4	40 ACE	SP	CCA	ED	BD	00:00.0
2021 PO4468888140	LGE	3	45 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO7574877931	F	3	50 ACE	SP	P		V	00:00.0
2021 PO7620777760	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO7621477651	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4467988154	LGE	4	45 ACE	SP	A	ED	BD	00:00.0
2021 PO4969008031	F	4	40 BRN	SP	P		V	00:00.0
2021 PO4958308013	KU	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8861954859	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PV4571088099	LGE	3	45 ACE	SP	A	ED	V	00:00.0
2021 PO4571088094	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PV4570988085	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO8092663078	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8082162774	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8112962699	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8133162638	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8168562802	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4570988078	LGE	2	55 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO8159862627	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8150262426	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8140462262	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8134762137	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8072862090	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8093161913	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8108861900	F	4	40 BRN	SP	P		V	00:00.0

2021 PO8124361908	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8856855620	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8841356061	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8777355507	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8815155897	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO6112067538	LGE	1	40 BRO	SP	CRE		V	00:00.0
2021 PO6111867548	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6112667519	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8166083124	F	4	45 ACE	SP	P		V	00:00.0
2021 PO8165183206	F	3	45 ACE	SP	P		V	00:00.0
2021 PO8163083387	F	3	45 ACE	SP	P		V	00:00.0
2021 PO8160583585	F	3	45 ACE	SP	P		V	00:00.0
2021 PO4574888005	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4573988000	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO8283781075	KU	5	35 ACE	SP	CRE		V	00:00.0
2021 PO8264781072	KU	5	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO2854892833	LGE	4	30 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4575988006	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8383663450	F	6	30 BRN	SP	CCA		V	00:00.0
2021 PO8409364453	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO8392064339	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO8382764462	ODP	3	45 BRN	SP	S		V	00:00.0
2021 PO8368364351	ODP	4	40 BRN	SP	S		V	00:00.0
2021 PO8299964631	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8320264537	ODP	5	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8355064867	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO8347564654	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO8336864481	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO4576288014	LGE	4	30 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4575688011	LGE	3	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8286780791	KU	5	35 ACE	SP	CRE		V	00:00.0
2021 PO8287680926	KU	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8799756046	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8779656244	ODP	5	35 XXX	SP	CRE	ID,IP	TD	00:00.0
2021 PO8808956191	ODP	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8752756548	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO8754256472	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8737056291	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8715256068	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8683655742	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO0692251837	KU	1	80 UNK	SP	CCA		V	00:00.0
2021 PO0669851764	KU	5	35 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0668851547	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO0663751638	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4461688123	LGE	4	30 BRO	SP	A	ED,ID,IP	BD	00:00.0
2021 PO4462388125	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4462088136	LGE	3	45 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4461088132	LGE	4	30 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO6119567487	LGE	1	55 BRO	SP	CRE		V	00:00.0
2021 PO6120467505	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8279880909	KU	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8267080919	KU	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8249780985	KU	6	30 ACE	SP	CCA		V	00:00.0
2021 PO8253080929	F	4	40 ACE	SP	CCA		V	00:00.0

2021 PO8236281042	F	6	30 ACE	SP	CRE		V	00:00.0
2021 PO8236180968	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8218580963	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8573660291	F	4	45 BRN	SP	CRE		V	00:00.0
2021 PO1902990869	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4482787813	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4479787853	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4481087870	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4480287865	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4574888019	LGE	4	30 ACE	SP	A	ED,ID,RB	TD	00:00.0
2021 PO4575188020	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4574588028	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3969885068	LGE	4	35 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO3987985218	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO3986585232	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3985585240	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3945985953	LGE	3	50 BRO	SP	CRE		V	00:00.0
2021 PO4574088036	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4573588045	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5344533858	KU	4	40 UNK	SP	CRE	ED	BD	00:00.0
2021 PO5334433904	KU	6	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO4572988054	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PV4570888072	LGE	2	60 ACE	SP	CCA		V	00:00.0
2021 PO4572288066	LGE	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8206362554	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8223362730	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8237462875	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8234162277	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8225062391	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8238362256	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8238662129	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8250962124	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8259062038	ODP	2	40 BRN	SP	CRE		V	00:00.0
2021 PO8267162413	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5538625792	KU	3	45 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO5537225854	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO5534925981	KU	3	45 UNK	UN	CRE		V	00:00.0
2021 PO5532626094	KU	5	35 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO8174782873	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO3917385721	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO3906085613	LGE	1	60 BRO	SP	P		V	00:00.0
2021 PO3905985614	LGE	1	60 BRO	SP	P		V	00:00.0
2021 PO3909385637	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO3909485636	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO3912185669	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO3912285668	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO3915985707	LGE	2	60 BRO	SP	P		V	00:00.0
2021 PO3918985757	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP	BD	00:00.0
2021 PO8785855744	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4479287862	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO5521826057	KU	5	30 UNK	SP	CRE	ED	BD	00:00.0
2021 PO4478887919	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO8179182567	F	3	50 ACE	SP	CRE		V	00:00.0
2021 PO8181882694	F	3	50 ACE	SP	CCA		V	00:00.0

2021 PO8184482821	F	2	50 ACE	SP	CCA		V	00:00.0
2021 PO8186782936	F	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4538188108	LGE	1	100 ACE	SP	CRE	ED	V	00:00.0
2021 PO5867023514	F	1	20 UNK	SP	CCA		V	00:00.0
2021 PO3944585938	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO3944685937	LGE	3	50 BRO	SP	CCA	ED,ID,IP	BD	00:00.0
2021 PO3945785951	LGE	3	50 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO3945885951	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO3947385969	LGE	3	50 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO3947885975	LGE	2	55 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO3948485983	LGE	3	50 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4456588353	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4478687868	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4536488114	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8189183060	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8744153713	ODP	6	35 XXX	SP	CRE		V	00:00.0
2021 PO8756753241	ODP	4	45 XXX	SP	CCA		V	00:00.0
2021 PO5604422542	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5615822637	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5625622716	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5602922530	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5598422488	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5597322469	KU	3	45 UNK	SP	CRE	ED	BD	00:00.0
2021 PO5593922443	KU	3	45 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO5793223784	KU	3	45 UNK	SP	CRE	ED	BD	00:00.0
2021 PO8167583006	F	3	50 ACE	SP	P		V	00:00.0
2021 PO4478387892	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8185983329b	KU	5	35 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4530288128	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8185983329a	KU	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8185983329	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO2384793760	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO2390093785	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO2397093755	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO1858091227	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8202083635	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4474487894	LGE	3	25 BRO	SP	CCA		V	00:00.0
2021 PO1850191358	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0665852066	KU	2	60 BRN	SP	CRE		V	00:00.0
2021 PO4476387905	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO2350693796	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO2363993798	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4477087896	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO8190583638	KU	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4532688115	LGE	3	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4477387889	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4531088116	LGE	1	95 ACE	SP	CRE		V	00:00.0
2021 PO4457588349	F	1	60 BRO	SP	P		V	00:00.0
2021 PO4457388354	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4457588354	LGE	4	35 BRO	SP	P	ED,ID,MD	TD	00:00.0
2021 PO4529188118	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO5783323825	KU	2	45 UNK	SP	CRE	ED	BD	00:00.0
2021 PO5779823867	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5770223782	F	4	40 UNK	SP	CRE		V	00:00.0

2021	PO8121382305	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4532088015	LGE	3	65 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO5781123534	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021	PO5771023608	KU	3	45 UNK	SP	CCA	ED,ID	BD	00:00.0
2021	PO5775423657	KU	6	30 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5772023654	KU	6	30 UNK	SP	CRE	ED	BD	00:00.0
2021	PO5767823706	KU	3	45 UNK	SP	CRE	ED	BD	00:00.0
2021	PO4531888021	LGE	4	40 ACE	SP	CRE	ED,ID,MD	BD	00:00.0
2021	PO4531688024	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO0668052074	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO0652952521	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO8123282605	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8124682788	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8128782998	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5750323128	KU	2	55 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5750823121	KU	3	55 UNK	SP	CCA	ED,ID	BD	00:00.0
2021	PO5744223135	KU	6	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5741523165	KU	6	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO5735723118	KU	6	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021	PO4531388028	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4530788039	LGE	4	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4530188048	LGE	4	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO5746923008	KU	6	30 UNK	SP	CCA		V	00:00.0
2021	PO5738823042	KU	6	30 UNK	SP	CCA		V	00:00.0
2021	PO4458187803	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO8133083217	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO0650952511	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO0629653085	KU	2	60 BRN	SP	CRE		V	00:00.0
2021	PO5731123178	KU	6	30 UNK	SP	CRE	ED	BD	00:00.0
2021	PO4459988357	LGE	3	45 BRO	SP	CRE	ED,ID,IP,MD	BD	00:00.0
2021	PO4461588365	LGE	4	40 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021	PO5730223354	KU	5	35 UNK	SP	CCA	ED	BD	00:00.0
2021	PO5730723337	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5735523265	F	3	40 UNK	SP	CRE		V	00:00.0
2021	PO5741323269	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO5743823230	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO5738723311	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO8291862364	ODP	5	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO8321962323	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021	PO8311162565	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO8316962620	ODP	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8319862406	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO8302063056	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO8300362641	F	4	40 BRN	SP	P		V	00:00.0
2021	PO4458187791	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021	PO0632053092	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO8148682470	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO0579154548	KU	3	40 BRN	SP	CRE		V	00:00.0
2021	PO0556055211	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO0567754953	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4529488059	LGE	4	45 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO8153782628	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8159582836	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO8160382874	KU	3	45 ACE	SP	CCA		V	00:00.0



2021 PO8160982892	KU	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5728223472	KU	2	50 UNK	SP	CCA		V		00:00.0
2021 PO5726323504	KU	2	60 UNK	SP	CCA		V		00:00.0
2021 PO5734723568	KU	3	50 UNK	SP	CRE	ED,ID	BD		00:00.0
2021 PO5743323624	KU	2	50 UNK	SP	CCA		V		00:00.0
2021 PO5753723700	KU	2	50 UNK	SP	CCA		V		00:00.0
2021 PO5755223677	KU	3	45 UNK	SP	CRE	ED	BD		00:00.0
2021 PO5765223742	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO4455587806	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO8163883003	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4462888360	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4463688370	LGE	3	50 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4466388374	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO0675951888	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021 PO7975484159	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO7965482982	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4562888044	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4571088010	LGE	3	50 ACE	SP	CRE	ED,HH,ID	BD		00:00.0
2021 PO4571787999	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4572387990	LGE	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4950708238	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4962908129	KU	6	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4468288174	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4468388179	LGE	4	40 ACE	SP	A	ED	TD		00:00.0
2021 PO4480288425	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4478788420	LGE	3	45 ACE	SP	CCA	ED,ID	TD		00:00.0
2021 PO7553277198	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5081284942	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4355185665	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4355585656	LGE	3	45 ACE	SP	P	ED	TD		00:00.0
2021 PO4356685639	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4356185649	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4357385629	LGE	3	50 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4357585628	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4358485613	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4357885621	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4359385599	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021 PO6137151839	F	3	45 OTH	SP	CCA		V		00:00.0
2021 PO5114684934	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO5112784932	LGE	3	45 ACE	SP	P	ED,MD	BD		00:00.0
2021 PO7893290292	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4439185908	LGE	4	30 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4439285904	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4439085910	LGE	4	35 BRO	SP	P	ID,IP	B		00:00.0
2021 PO4992684761	LGE	4	30 BRO	SP	CRE		V		00:00.0
2021 PO4990484848	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7917390310	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7941190334	KU	5	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5110984926	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO6143451761	F	3	45 OTH	SP	CCA		V		00:00.0
2021 PO6147051718	F	3	45 OTH	SP	CCA		V		00:00.0
2021 PO6149951761	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO6153551578	F	3	45 OTH	SP	CCA		V		00:00.0
2021 PO6161551520	F	4	40 OTH	SP	P		V		00:00.0

2021 PO6173151431	F	4	40 SWP	SP	CRE		V		00:00.0
2021 PO6190851358	KU	5	35 OTH	SP	CRE	ID	BD		00:00.0
2021 PO6187451325	F	5	35 OTH	SP	CRE		B		00:00.0
2021 PO6179851382	F	4	40 SWP	SP	CRE		V		00:00.0
2021 PO7965490350	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO7994890365	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO5121284893	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO4502311874	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO4497411744	KU	4	45 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4507212010	KU	5	45 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO8012090380	KU	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8011090549a	KU	7	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8011090549	KU	6	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5119984883	LGE	3	45 ACE	SP	P	ED	TD		00:00.0
2021 PO4986584867	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4988884858	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4974185246	F	3	45 BRO	SP	A		V		00:00.0
2021 PO4436485898-A	LGE	7	25 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4436785898	LGE	3	45 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO4436485898	LGE	3	45 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4435385909	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO4434585899	LGE	3	45 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO1477471356	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO1474271210	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO1471171063	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO1456171054	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO1441271072	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO1426371090	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4557687985	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4522112015A	KU	6	30 XXX	SP	S		V		00:00.0
2021 PO4516611902	KU	5	35 XXX	SP	S		V		00:00.0
2021 PO4499612111	KU	5	35 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO4488311827	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4493011957	KU	5	35 XXX	SP	CRE		V		00:00.0
2021 PO5118384864	LGE	3	45 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO7795490880	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7761390891	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7735990856	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO5119784844	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO5120184821	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4972185260	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO7724290633	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7711190370	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7683790341	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO7655890314	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7627190285	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO7811581243	KU	1	60 ACE	ST	CCA		V		00:00.0
2021 PO4970085273	F	2	45 BRO	SP	A		V		00:00.0
2021 PO4969685250	F	3	45 BRO	SP	A		V		00:00.0
2021 PO5120784805	LGE	4	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO5122784774	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO5121484791	LGE	4	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4980585250	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4983185276	F	3	45 BRO	SP	CCA		V		00:00.0

2021 PO4982385256	F	5	25 BRO	SP	CCA		V		00:00.0
2021 PO4982185260	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4350913547	KU	5	35 XXX	SP	CRE	ID	X	RP3	00:00.0
2021 PO1274462860	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO1276662714	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO1306263319	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4980285080	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4344814203	KU	2	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO7868481777	KU	2	35 ACE	SP	CCA		V		00:00.0
2021 PO7844681484	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO7842281506	KU	1	80 ACE	SP	CRE		V		00:00.0
2021 PO4447485917	LGE	3	50 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO4447885917	LGE	3	45 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7839581208	KU	6	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO7650495417	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7829392971	KU	6	30 ACE	SP	CRE		V		00:00.0
2021 PO6967464127	LGE	4	30 BRO	SP	CCA		V		00:00.0
2021 PO4349614378	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4349614415	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4628713882	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4636913850	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4622413665	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4618513531	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4614213378	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4610413242	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4606413105	F	4	40 XXX	SP	P		V		00:00.0
2021 PO4599812871	KU	4	45 XXX	SP	CRE		V		00:00.0
2021 PO4602412967	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO1283763566	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4976785092	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO6895264186	LGE	2	45 BRO	SP	CCA		V		00:00.0
2021 PO5123484952	LGE	3	30 ACE	SP	CCA		V		00:00.0
2021 PO5033484780	F	3	45 BRO	SP	A		V		00:00.0
2021 PO5034184744	F	4	35 BRO	SP	A		V		00:00.0
2021 PO5125284952	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4978985182	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4840985942	LGE	1	60 ACE	SP	P	ED	BD		00:00.0
2021 PO4839785941	LGE	1	25 ACE	SP	CCA		V		00:00.0
2021 PO4840785946	F	4	40 ACE	SP	CRE	ED	V		00:00.0
2021 PO4842785953	F	4	45 ACE	SP	CRE		V		00:00.0
2021 PO4428413158	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021 PO4424013213	KU	2	50 XXX	SP	CCA		V		00:00.0
2021 PO4420513106	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4413713152	KU	2	70 XXX	ST	CCA		V		00:00.0
2021 PO4408213233	KU	5	35 XXX	SP	CCA		V		00:00.0
2021 PO4452613869	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4445213827	KU	2	50 XXX	SP	CCA		V		00:00.0
2021 PO5124684935	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4448585920	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4962785117	LGE	3	45 BRO	SP	A	ID	BD		00:00.0
2021 PO4964685124	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO5434705598	F	4	40 KOP	SP	CCA		V		00:00.0
2021 PO5430805500	F	4	40 KOP	SP	CCA		V		00:00.0
2021 PO5444905158	KU	5	35 KOP	SP	CCA		V		00:00.0

2021	PO5410705431	KU	5	35 BRN	SP	CCA		V		00:00.0
2021	PO5421505389	F	4	40 UNK	SP	CCA		V		00:00.0
2021	PO5417505286	F	4	40 UNK	SP	CCA		V		00:00.0
2021	PO5413805173	F	4	40 UNK	SP	CCA		V		00:00.0
2021	PO5415105053	F	4E	40E UNK	SP	CRE		V		00:00.0
2021	PO5422704944	F	4E	40E UNK	SP	CRE		V		00:00.0
2021	PO5435004844	F	5E	40E BRN	SP	CRE		V		00:00.0
2021	PO5437904888	KU	6	30 BRN	SP	CCA		V		00:00.0
2021	PO5411105945	F	5	30 UNK	SP	CCA		V		00:00.0
2021	PO5389106063	F	5E	35E UNK	SP	CRE	ED,ID		BD	00:00.0
2021	PO5378206104	F	5E	35E UNK	SP	CRE	ED,HH,ID,RB		BX PX	00:00.0
2021	PO5368306141	F	5	35 UNK	SP	CCA		V		00:00.0
2021	PO5359106176	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO5349506226	F	5E	35E UNK	SP	P		V		00:00.0
2021	PO1269363529	KU	4	40 BRO	SP	CRE	ED,IP,SRS		TD	00:00.0
2021	PO1256863496	KU	4	40 BRO	SP	CRE	ED,IP,SRS		TD	00:00.0
2021	PO5123484924	LGE	3	50 ACE	SP	P	ED,ID		BD	00:00.0
2021	PO7661994690	KU	5	35 ACE	SP	CRE	ED,ID		BD	00:00.0
2021	PO4449585935	LGE	4	35 BRO	SP	P	ED,ID		BD	00:00.0
2021	PO4452585932	LGE	4	30 BRO	SP	CRE	ED,ID,IP		BD	00:00.0
2021	PO4449285915	LGE	3	45 BRO	SP	CRE	ED,ID,IP		BD	00:00.0
2021	PO5121884906	LGE	4	30 ACE	SP	P	ED,ID		TD	00:00.0
2021	PO5121584908	LGE	3	50 ACE	SP	P	ED		BD	00:00.0
2021	PO4967985137	LGE	3	45 BRO	SP	A	ID,IP		BD	00:00.0
2021	PO4443313924	KU	6	30 XXX	SP	CCA		V		00:00.0
2021	PO4439414056	KU	4	45 XXX	SP	CRE	ID		TD	00:00.0
2021	PO4436514065	KU	4	45 XXX	SP	CRE	ID		BD	00:00.0
2021	PO7677594438	KU	4	40 ACE	SP	CRE	ED,ID		BD	00:00.0
2021	PO7666995112	KU	5	35 ACE	SP	CRE	ED,ID		BD	00:00.0
2021	PO4970285147	LGE	3	45 BRO	SP	A	ED,ID,IP		TD	00:00.0
2021	PO6234851813	KU	4	40 OTH	SP	CRE		V		00:00.0
2021	PO6233451796	KU	4	40 OTH	SP	CRE		V		00:00.0
2021	PO6232151776	KU	4	45 OTH	SP	CRE	ID		BD	00:00.0
2021	PO1547171307	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4442185897	LGE	3	45 BRO	SP	P	ED,ID		BD	00:00.0
2021	PO4441885893	LGE	3	45 BRO	SP	P	ED,ID		TD	00:00.0
2021	PO4970485172	LGE	4	30 BRO	SP	A	ED,ID,IP		TD	00:00.0
2021	PO4462213577	KU	4	45 XXX	SP	CRE	ID		BD	00:00.0
2021	PO4428013833	KU	4	45 XXX	SP	CCA		V		00:00.0
2021	PO4430313882	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO4437613658	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO4426813748	KU	6	30 XXX	SP	CRE	ID		BD	00:00.0
2021	PO4420113773	KU	6	30 XXX	SP	CCA		V		00:00.0
2021	PO4423213702	KU	4	45 XXX	SP	CCA		V		00:00.0
2021	PO4416313501	KU	4	45 XXX	SP	CCA		V		00:00.0
2021	PO4413313651	KU	6	30 XXX	SP	CRE	ED,ID,MD		BD	00:00.0
2021	PO4421013624	KU	6	30 XXX	SP	CRE	ID		BD	00:00.0
2021	PO4431713496	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO7683794814	KU	5	35 ACE	SP	CRE	ED,ID		BD	00:00.0
2021	PO7705394932	KU	5	35 ACE	SP	CRE	ED,ID		BD	00:00.0
2021	PO7727295056	KU	4	40 ACE	SP	CRE	ED,ID		BD	00:00.0
2021	PO7743794786	KU	5	35 ACE	SP	CRE	ED,ID		TD	00:00.0
2021	PO7755494624	KU	5	35 ACE	SP	CRE	ED,HH,ID,RB		BX PX	00:00.0
2021	PO7771292741	KU	4	40 ACE	SP	CCA		V		00:00.0

2021	PO6215351826	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021	PO6209051788	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021	PO6206851817	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021	PO4970085180	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4969385183	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO1542568192	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO6876465170	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4975385210	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO1479367052	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1449367068	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1558267961	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO1569867004	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1539267019	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1509267035	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4440885898	LGE	3	45 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021	PO4440885889	LGE	3	45 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021	PO4843885952	LGE	4	30 ACE	SP	P	ED	TD	00:00.0
2021	PO4977685223	F	3	45 BRO	SP	A		V	00:00.0
2021	PO4843685955	LGE	1	60 ACE	SP	CRE	ED,IP	BD	00:00.0
2021	PO4592712669A	KU	4	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4592712669	KU	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO4585212443	KU	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021	PO4580312308	KU	4	45 XXX	SP	CRE	ED,ID,SR	TD	00:00.0
2021	PO4574512146	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO2215658501	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO1362867181	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1391866924	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1421666952	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO2230358523	KU	4	40 BRO	SP	CRE	ED,IP,SR	TD	00:00.0
2021	PO2200958530	KU	4	40 BRO	SP	CRE	ED,IP	BD	00:00.0
2021	PO1362366982	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO6188251820	KU	1	30 OTH	ST	CCA		V	00:00.0
2021	PO6181251876	KU	1	30 OTH	ST	CCA		V	00:00.0
2021	PO6175251923	KU	1	30 OTH	ST	CCA		V	00:00.0
2021	PO4968885203	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4966485186	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4422713360	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4427013294	KU	3	50 XXX	SP	CCA		V	00:00.0
2021	PO4434913352	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6200351394	KU	3	40 OTH	SP	CCA		V	00:00.0
2021	PO6198651463	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO6245951713	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO6239951625	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO6250951497	KU	4	40 OTH	SP	CRE	ID,IP,MD	BD	00:00.0
2021	PO6260651432	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO6270051367	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6336051029	KU	3	50 OTH	SP	CRE		V	00:00.0
2021	PO6360250944	KU	3	50 OTH	SP	CRE		V	00:00.0
2021	PO7376383599	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4854010747	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4862110658	F	5	35 XXX	SP	CRE		V	00:00.0
2021	PO5961754076	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5954354080	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5946653969	KU	4	40 BRN	SP	CCA		V	00:00.0

2021	PO5932553870	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021	PO4446785749	LGE	4	30 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4448785711	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO4861110892A	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4862210795	KU	3	45 XXX	SP	S		V	00:00.0	
2021	PO4878910854	KU	4	40 XXX	SP	S		V	00:00.0	
2021	PO4861110892	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO4447185735	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4447685741	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4448185733	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO4897411518	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO4903311632	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO4909711759B	KU	4	40 XXX	SP	CCA		V	00:00.0	
2021	PO4909711759A	KU	4	40 XXX	SP	CCA		V	00:00.0	
2021	PO4915411737	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO4909711759	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO4901711782	KU	3	45 XXX	SP	S		V	00:00.0	
2021	PO4924212028	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO5019584797	LGE	4	35 BRO	SP	CRE		V	00:00.0	
2021	PO4328314123	KU	3	45 XXX	SP	CCA		V	00:00.0	
2021	PO4456788518	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4457488506	LGE	4	35 ACE	SP	P	ED,ID,MD	TD	00:00.0	
2021	PO4768012887	F	3	45E BRN	SP	CRE		V	00:00.0	
2021	PO4778113055	F	2	45E BRN	SP	CRE		V	00:00.0	
2021	PO4523188101	LGE	4	40 ACE	SP	CRE	ED,IP	BD	00:00.0	
2021	PO4783713153	F	3	45E BRN	SP	P		V	00:00.0	
2021	PO4815613292	KU	2	55 BRN	SP	CRE	ED,ID,IP,SRS	TD	00:00.0	
2021	PO4800413120	KU	5	35 BRN	SP	CRE	ID	TD	00:00.0	
2021	PO4789612924	F	5	40 BRN	SP	CRE		V	00:00.0	
2021	PO4778612724	KU	7	35 BRN	SP	CRE	SRS	TD	00:00.0	
2021	PO4586227306	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO4581727295	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO4571527270	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO7615247558	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO7625247531	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO7634747507	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO7644747479	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO4829813262	KU	2	50 BRN	SP	CRE	ID,IP	BD	00:00.0	
2021	PO4518288065	LGE	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4520288077	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO4526587998	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4525888008	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0	
2021	PO4462388464	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021	PO4461488471	LGE	2	55 ACE	SP	A		V	00:00.0	
2021	PO4461888463	LGE	3	45 ACE	SP	CRE		V	00:00.0	
2021	PO4776912446	KU	6	35 BRN	SP	CRE	ID,IP	TD	00:00.0	
2021	PO4770412573	KU	6	35 BRN	SP	CRE	ED,ID,RB,SR,SR	TX	RR	00:00.0
2021	PO2911787491	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021	PO2876287561	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0	
2021	PO4460188491	LGE	1	60 ACE	SP	A	ED	BD	00:00.0	
2021	PO4525188019	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4524688027	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0	
2021	PO4460888481	LGE	1	55 ACE	SP	CRE	ED	BD	00:00.0	
2021	PO4524188036	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	

2021 PO4523688045	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4462088524	LGE	4	40 ACE	SP	CRE		V	00:00.0
2021 PO7169447012	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4460988538	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4460788543	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4523088054	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4522588062	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4522088071	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4521588079	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4520888092	LGE	3	45 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4520088004	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4519788109	LGE	4	40 BRO	SP	P	ED,EP,ID,MD	BD	00:00.0
2021 PO4519288116	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4518588101	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4517488094	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4803012722	KU	7	30 BRN	SP	CCA		V	00:00.0
2021 PO5155926931	KU	3	45 BRO	SP	CRE	ED	BD	00:00.0
2021 PO3923785195-A	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO4533388073	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO3918785265	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4460188521	LGE	4	30 ACE	SP	P	ED,ID,RB	TD	00:00.0
2021 PO4905027017	KU	6	30 BRO	SP	CRE	ED	BD	00:00.0
2021 PO2426292758	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4834212931	KU	6	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4844013143	KU	7	35 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4843513242	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 PO3917685284	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4459688510	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4459188508	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4531088112	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4531488105	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4532088095	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4532488088	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4532988080	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4685527714	F	3	45 OTH	SP	P		V	00:00.0
2021 PO4743128127	F	3	40 OTH	SP	CRE	ED,ID,IP	BX PX	00:00.0
2021 PO4746028209	F	4	40 OTH	SP	P	ID,IP,RB	V	00:00.0
2021 PO4748328281	F	4	40 OTH	SP	CRE	ID	BX RP1	00:00.0
2021 PO4755928332	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO4816928447	F	4	40 OTH	SP	P	ED	V	00:00.0
2021 PO4824428248	F	3	40 OTH	SP	P		V	00:00.0
2021 PO4821028179	F	4	40 OTH	SP	CRE	ED	V	00:00.0
2021 PO4828828419	F	4	40 OTH	SP	P	ED	V	00:00.0
2021 PO4803628092	F	3	40 OTH	SP	CRE	HH,ID	BX RP1	00:00.0
2021 PO4794328110	F	3	40 OTH	SP	CRE	ID,IP	BX RP2	00:00.0
2021 PO4784328124	F	4	40 OTH	SP	CRE	ED	V	00:00.0
2021 PO4788828316	F	4	40 OTH	SP	P	ED	V	00:00.0
2021 PO4739808184	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4666109148	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4699909374	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4721409237	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4724209220	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4793108604	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4764008584	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0

2021 PO4727607877	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4733908038	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4688509153	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4742708910	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4737409032	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4678409151	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4771108590	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO2947487447	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO3927885136	LGE	2	55 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO3925385172	LGE	2	55 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO3921185233	LGE	2	55 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4461788529	LGE	4	35 ACE	SP	A	ED	BD	00:00.0
2021 PO4636107997	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4718508782	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4679907691	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4647107686	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4632507684	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4723608616	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4663807688	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7199047150	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4537588075	LGE	3	55 ACE	SP	CRE	ED,IP	TD	00:00.0
2021 PO4826426393	KU	6	30 BRO	SP	CRE	ED	BD	00:00.0
2021 PO4795926323	KU	3	45 BRO	SP	A	ED	BD	00:00.0
2021 PO4823325614	KU	2	40 BRO	SP	CRE	ED	BD	00:00.0
2021 PO3911285312	LGE	1	60 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4431588918	LGE	2	55 ACE	SP	A		V	00:00.0
2021 PO4429688953	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4800625961	KU	6	30 BRO	SP	CRE		T	00:00.0
2021 PO4803925906	KU	5	35 BRO	SP	CRE		T	00:00.0
2021 PO4430588937	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4800726040	KU	3	45 BRO	SP	A		BD	00:00.0
2021 PO4428788925	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO3901385299	LGE	1	55 BRO	SP	A		V	00:00.0
2021 PO4538488063	LGE	3	45 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4429688931	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4808026059	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4766511556	KU	7	35 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO4855309809	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4841609886	F	4	40 XXX	SP	S		V	00:00.0
2021 PO4850507931	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4523388104	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO4793528366	F	4	35 OTH	SP	CRE	ED	V	00:00.0
2021 PO4632007940	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4724008553	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4723508676	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4713608903	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4648707380	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO4717508290	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4529188009	LGE	4	45 ACE	SP	A	ED	TD	00:00.0
2021 PO4458788513	LGE	1	60 ACE	SP	A	ED	BD	00:00.0
2021 PO4459488503	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4678627784	F	3	40 OTH	SP	P	ED,ID,RB	BX	RP2 00:00.0
2021 PO4860728377	F	4	40 OTH	SP	P		V	00:00.0
2021 PO4846928423	F	2	45E OTH	SP	CRE		V	00:00.0



2021 PO4870028334	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021 PO4878828292	F	4	40 OTH	SP	CRE	ED,IP	V		00:00.0
2021 PO4458388476	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4573127555	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4565727577	F	4	40 BRO	SP	CRE	ED,ID,RB	VX	RP2	00:00.0
2021 PO7596147609	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7605847584	F	4	40 BRO	SP	A		V		00:00.0
2021 PO4581727489	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4577127457	F	4	40 BRO	SP	CRE	ED,ID	VX	PX	00:00.0
2021 PO4449788585	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4447588643	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4450388596	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4448688625	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4449288615	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4449388578	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO4452588589	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4451788587	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4450988591	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4450788584	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4456388465	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4456288465	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO4455988463	LGE	3	25 ACE	SP	CRE		V		00:00.0
2021 PO7162847472	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4568327436	F	4	40 BRO	SP	CRE		VX	PX	00:00.0
2021 PO4770011702	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO4456688466	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4759012388	F	7	35E BRN	SP	CRE		V		00:00.0
2021 PO4455288483	LGE	H3	45 ACE	SP	CCA		V		00:00.0
2021 PO4454988488	LGE	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4454788491	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7166047332	KU	4	40 BRO	SP	A	ED,IP,SRS	TD		00:00.0
2021 PO7162647331	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4750208766	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4710509306	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4644709142	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4797112432	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4795013338	KU	1	60 BRN	SP	CRE	ED,ID,IP,SRC,SRS	TD		00:00.0
2021 PO4695226949	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4457888491	LGE	4	35 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4527188041	LGE	4	40 ACE	SP	P	ED	BD		00:00.0
2021 PO4527988021	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4519988056	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4519488064	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4519088071	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4686026851	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4695326768	F	4	40 BRO	SP	CRE	ED,ID	VX	RP2	00:00.0
2021 PO3933085064	LGE	2	55 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO3931885079	LGE	2	55 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO3931085091	LGE	2	55 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO3929185118	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3930085105	LGE	2	55 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4459188486	LGE	3	35 ACE	SP	CRE		V		00:00.0
2021 PO7585847636	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO7583547548	KU	4	40 BRO	SP	CCA		V		00:00.0

2021	PO4459388484	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4577127689	F	4	40 BRO	SP	CRE	ED,ID,RB	VX	PX	00:00.0
2021	PO4581927746	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4791027567	F	3	40 OTH	SP	P		V		00:00.0
2021	PO4796327641	F	2	45 OTH	SP	P		V		00:00.0
2021	PO4802327725	F	3	45E OTH	SP	P	ED	V		00:00.0
2021	PO4809127811	F	4	40 OTH	SP	P	ED	V		00:00.0
2021	PO4680127913	F	4	40 OTH	SP	CRE	ED	V		00:00.0
2021	PO4783912817	KU	5	35 BRN	SP	CRE		V		00:00.0
2021	PO4596027278	F	4	45 BRO	SP	A		V		00:00.0
2021	PO4593827381	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4590827522	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4588927599	F	3	45 BRO	SP	A		V		00:00.0
2021	PO4465888395	LGE	2	50 ACE	SP	CRE		V		00:00.0
2021	PO4465488403	LGE	1	65 ACE	SP	A		V		00:00.0
2021	PO4464888413	LGE	1	65 ACE	SP	A		V		00:00.0
2021	PO4604327467	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4618727341	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4464188425	LGE	1	60 ACE	SP	CRE		V		00:00.0
2021	PO3926185162	LGE	3	50 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO3926085161	LGE	2	55 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4765726000	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4533988063	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4784527499	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4843827672	KU	6	30 BRO	SP	CCA		V		00:00.0
2021	PO4849826798	KU	2	45 BRO	SP	CCA		V		00:00.0
2021	PO3916385302	LGE	2	55 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4534688053	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4535588037	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4535088046	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO7169447184	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO7162347193	KU	4	45 BRO	SP	CRE	ED,EP,ID,MD,RB	X	PX	00:00.0
2021	PO7179347173	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO7189247162	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO4463288439	LGE	1	55 ACE	SP	A		V		00:00.0
2021	PO4462688450	LGE	1	55 ACE	SP	CRE	ED	V		00:00.0
2021	PO4636027190	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4645627109	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4655927021	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4705526482	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4697826555	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4718626362	F	4	40 BRO	SP	CRE	RB	VX	RP2	00:00.0
2021	PO3927085149	LGE	2	55 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4528588019	LGE	4	40 ACE	SP	CRE	ED	TD		00:00.0
2021	PO4528488015	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021	PO4737526196	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4748026102	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO4529788011	LGE	4	30 ACE	SP	CRE	ED,IP	TD		00:00.0
2021	PO4640325282	KU	2	50 BRO	SP	CCA		V		00:00.0
2021	PO7162247103	KU	4	40 BRO	SP	CRE	RB	X	RP2	00:00.0
2021	PO7162447249	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021	PO7162147072	KU	5	35 BRO	SP	CRE	ED,SRS	TD		00:00.0
2021	PO4808512448	KU	6	35 BRN	SP	CRE		BD		00:00.0
2021	PO4812112422	F	2	40 BRN	SP	P		V		00:00.0

2021 PO4816312520	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4755425139	KU	4	40 BRO	SP	CRE	ED	BD		00:00.0
2021 PO3919985251	LGE	2	55 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO7141748310	KU	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7153848288	KU	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7158748279	KU	3	50 BRO	SP	CCA		V		00:00.0
2021 PO5951202150	F	4	40 XXX	SP	CRE	ED,ID,IP,MD	BX	PX	00:00.0
2021 PO5924202299	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5927402278	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5939402223	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5908802044	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5911702025	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5891902653	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5913302121	F	5	35 XXX	SP	CRE		V		00:00.0
2021 PO5922201962	F	4	40 XXX	SP	CRE	ED,HH,ID,IP,MD	BX	PX	00:00.0
2021 PO5917202185	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5875702384	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5692693588	F	1	65 BRN	SP	CRE		V		00:00.0
2021 PO5706693522	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5718993461	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO4755589915	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4657211951	LGE	1	60 BRN	SP	CCA		V		00:00.0
2021 PO4758689903-a	LGE	1	50 BRN	SP	CCA		V		00:00.0
2021 PO4677511833	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7193848290	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4760889887	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4762689878	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO7178548588	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO7189948568	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO0880470846	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4766089892	LGE	UNK	25 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4769189919	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4768089911	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4766889903	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4466385822	LGE	1	65 BRN	SP	CCA		V		00:00.0
2021 PO4765889896	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO3838603774	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3844703881	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3824804100	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3826104219	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3833003849	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO3849604186	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3847504115	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4467985819	LGE	4	40 BRN	SP	A	ED,ID,IP	TD		00:00.0
2021 PO0895970745	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO0861371512	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO0871371241	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO0876971054	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO0895870979	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0921270886	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4764289888	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO8274986551	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO4333187012	LGE	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4936891458	LGE	4	35 BRN	SP	CCA		V		00:00.0

2021 PO4794690632	LGE	3	45 BRN	SP	CCA			V	00:00.0
2021 PO4795390608	LGE	1	60 BRN	SP	CCA			V	00:00.0
2021 PO5022019006	LGE	4	30 BRN	SP	CCA			V	00:00.0
2021 PO7155649462	KU	6	30 BRO	SP	CRE		ED,ID	TD	00:00.0
2021 PO4950491494	LGE	3	45 BRN	SP	CCA			V	00:00.0
2021 PO5955201762	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO6491228055	LGE	4	40 BRN	SP	CCA			V	00:00.0
2021 PO5928902380	F	3	40 XXX	SP	CRE			V	00:00.0
2021 PO5933401895	F	4	40 XXX	SP	CRE			V	00:00.0
2021 PO4406004299	F	4	40 BRN	SP	CRE		HH,ID,IP,RB	BX PX	00:00.0
2021 PO9360559757	KU	4	45 UNK	SP	CRE			V	00:00.0
2021 PO9341058375	KU	4	45 BRN	SP	CCA			V	00:00.0
2021 PO9356558131	KU	4	45 BRN	SP	CCA			V	00:00.0
2021 PO9573263317	KU	2	55 BRO	SP	CCA			V	00:00.0
2021 PO9566963382	KU	2	50 BRO	SP	CCA			V	00:00.0
2021 PO9563163441	KU	3	45 BRO	SP	CCA			V	00:00.0
2021 PO9552463629	KU	2	50 BRO	SP	CCA			V	00:00.0
2021 PO9553163795	KU	2	50 BRO	SP	S			V	00:00.0
2021 PO9149162147	KU	4	40 BRO	SP	CRE		ED,ID	BD	00:00.0
2021 PO9360459742	KU	2	50 BRO	SP	P		ED	T	00:00.0
2021 PO9353459627	KU	2	50 BRO	SP	CCA			V	00:00.0
2021 PO9344759660	KU	3	45 BRO	SP	CCA			V	00:00.0
2021 PO9324859735	KU	4	40 UNK	SP	CRE		ID	BD	00:00.0
2021 PO9406961743	KU	5	30 XXX	SP	CRE		ID	TD	00:00.0
2021 PO9335959864	KU	2	50 BRO	SP	CRE			V	00:00.0
2021 PO9318059878	KU	5	35 UNK	SP	CRE		ID	BD	00:00.0
2021 PO9326059877	KU	2	50 BRO	SP	CCA			V	00:00.0
2021 PO9323159908	KU	4	40 UNK	SP	CRE			V	00:00.0
2021 PO9343360080	KU	3	50 UNK	SP	CRE		ED,ID,IP	TD	00:00.0
2021 PO9236961228	KU	5	30 OTH	SP	CRE		ED,ID,SRS	TD	00:00.0
2021 PO9245961183	KU	5	35 OTH	SP	CRE		ED,ID,SRS	TD	00:00.0
2021 PO9220361316	KU	5	35 OTH	SP	CRE		ED,ID,SRS	TD	00:00.0
2021 PO9274860989	KU	4	40 OTH	SP	CRE		ED,EP,ID,SRC	TX RR	00:00.0
2021 PO9249461281	KU	4	45 OTH	SP	CRE		ID	BD	00:00.0
2021 PO9259461083	KU	5	35 OTH	SP	CRE		ID	BD	00:00.0
2021 PO9405961678	KU	4	45 XXX	SP	CRE		ID	TD	00:00.0
2021 PO9393961788	KU	4	40 XXX	SP	CRE		ID	TD	00:00.0
2021 PO9380261898	KU	4	40 XXX	SP	CRE		ID	TD	00:00.0
2021 PO9372662021	KU	6	30 XXX	SP	CCA			V	00:00.0
2021 PO9367062000	KU	2	55 XXX	SP	CCA			V	00:00.0
2021 PO9368762038	KU	4	40 XXX	SP	CRE		ED,ID,IP	TX RR	00:00.0
2021 PO9366962207	KU	5	35 XXX	SP	CRE		ID	TD	00:00.0
2021 PO9375762141	KU	4	40 XXX	SP	CCA		ED	T	00:00.0
2021 PO9389662240	KU	3	45 XXX	SP	CCA			V	00:00.0
2021 PO9383262251	KU	2	50 XXX	SP	CCA			V	00:00.0
2021 PO9387762478	KU	5	35 XXX	SP	CRE		ID	TD	00:00.0
2021 PO9393662409	KU	4	40 XXX	SP	CCA		ED	T	00:00.0
2021 PO9403762551	KU	4	45 XXX	SP	CRE		ID	TD	00:00.0
2021 PO9429462573A	KU	4	40 XXX	SP	CRE		ID	TD	00:00.0
2021 PO9431662746	KU	6	30 XXX	SP	CRE			V	00:00.0
2021 PO9419058412	KU	5	35 BRN	SP	CRE			V	00:00.0
2021 PO9408758401	KU	6	30 BRN	SP	CRE			V	00:00.0
2021 PO9402558078	KU	1	65 BRN	SP	CCA			V	00:00.0
2021 PO9404758297	KU	6	30 BRN	SP	CCA			V	00:00.0

2021 PO9415958248	KU	4	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9433358338	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9148262048	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9158962001	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9325960066	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9164062055	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9169461901	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9170561763	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9158861788	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9158061948	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9144461908	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO9145461989	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9150761978	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9088562443	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9080762466	KU	2	65 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9063262631	KU	6	30 BRO	SP	CRE	ED	V	00:00.0
2021 PO9061162707	KU	2	50 BRO	ST	CRE		V	00:00.0
2021 PO9321060023	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9313760241	KU	1	65 BRO	SP	CCA		V	00:00.0
2021 PO9318360093	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO4587103602	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4579503422	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX PX	00:00.0
2021 PO4582303493	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4575403286	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4581703641	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9306060088	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9299360118	KU	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO9298959964	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9215461632	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9247961569	KU	4	40 OTH	SP	CCA		V	00:00.0
2021 PO9231761599	KU	5	35 OTH	UN	CCA		V	00:00.0
2021 PO6288298641	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6310498533	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9438358394	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9301959823	KU	2	60 UNK	SP	CRE	HH,ID	TD	00:00.0
2021 PO9299259913	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9291860082	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9278759941	KU	1	55 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO9440758332	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO9440758332a	KU	5	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6299498586	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6325398838	F	2	45 XXX	SP	P		V	00:00.0
2021 PO6366898974	F	3	40 XXX	SP	P		V	00:00.0
2021 PO6342598921	F	2	45 XXX	SP	P		V	00:00.0
2021 PO6353398858	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6358998851	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6364698260	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6343498526	F	4	40 XXX	SP	CRE	ED,IP	V	00:00.0
2021 PO6356798295	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6345798348	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6337098407	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6384298727	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6389398695	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6367398802	F	4	40 XXX	SP	CRE	ED,ID,IP,MD	BX PX	00:00.0

2021 PO6431198431	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6420698492	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6410598568	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6400398632	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6384498585	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6378098479	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6362498225	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6371898378	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6354298734	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6350398661	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO9305061662	KU	4	40 OTH	SP	CCA		V		00:00.0
2021 PO9270661818	KU	5	35 OTH	SP	CRE	ID		TD	00:00.0
2021 PO9300362244	KU	6	30 OTH	SP	CRE	ED,ID,SRS		TD	00:00.0
2021 PO9310261932	KU	3	45 OTH	SP	CCA	ED,SRS		TD	00:00.0
2021 PO9288061610	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO9259461763	KU	4	45 OTH	SP	CCA	ED,SRS		TD	00:00.0
2021 PO9291961547	KU	5	35 OTH	SP	CRE	ED,ID,SRS		TD	00:00.0
2021 PO9309562224	KU	4	40 OTH	SP	CRE	ED,ID,SRS		TD	00:00.0
2021 PO9310062044	KU	4	40 OTH	SP	CRE	ID		BD	00:00.0
2021 PO9442258377	KU	6	30 BRN	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO9447058381	KU	4	40 BRN	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO4570503163	F	4	40 BRN	SP	CRE	HH,ID,IP,RB		BX	RP1 00:00.0
2021 PO9069162225	KU	4	40 BRO	SP	CRE	ED,ID		BD	00:00.0
2021 PO9000961611	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9192760374	KU	4	40 UNK	SP	CRE	ID		BD	00:00.0
2021 PO9265560131	KU	6	30 UNK	SP	CRE	ED,ID		TD	00:00.0
2021 PO9259260044	KU	3	50 UNK	SP	CRE	ED,ID		TD	00:00.0
2021 PO9131261391	KU	4	45 BRO	SP	CCA		V		00:00.0
2021 PO4550102756	F	4	40 BRN	SP	CRE	HH,ID,IP,RB		BX	RP2 00:00.0
2021 PO4557902874	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4566003033	KU	3	40 BRN	SP	CRE		V		00:00.0
2021 PO9390762300	KU	6	30 XXX	SP	CRE		V		00:00.0
2021 PO9449458257	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO9453958176	KU	4	40 BRN	SP	CRE	ED,ID		TD	00:00.0
2021 PO9012961783	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8994261412	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8992061203	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8991361021	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO9207560590	KU	4	45 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO4351603458	KU	4	40 BRN	SP	CRE	ID,IP		BD	00:00.0
2021 PO4349703422	KU	4	40 BRN	SP	CRE		BD		00:00.0
2021 PO4352303540	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4361203356	KU	4	40 BRN	SP	CRE	ID,IP		BD	00:00.0
2021 PO4328803593	KU	4	40 BRN	SP	CRE	ID		BD	00:00.0
2021 PO9461058356a	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO9453058370	KU	4	45 BRN	SP	CRE	ED,ID		TD	00:00.0
2021 PO9461058356	KU	4	40 BRN	SP	CRE	ED,ID		TD	00:00.0
2021 PO9119461351	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO9144861428	KU	4	40 UNK	SP	CRE	ID		BD	00:00.0
2021 PO9132361602	KU	4	40 UNK	SP	CRE	ID		BD	00:00.0
2021 PO9120461766	KU	4	45 UNK	SP	CRE	ID		BD	00:00.0
2021 PO9157061258	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0
2021 PO9160161281	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0
2021 PO9138661123	KU	4	40 KOP	SP	S		V		00:00.0

2021	PO9201460671	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9317562637	KU	6	30 OTH	UN	CRE		V	00:00.0
2021	PO9312562382	KU	5	35 OTH	SP	CRE	ED,ID,SR	TD	00:00.0
2021	PO9303663231	F	5	35 OTH	SP	CRE		V	00:00.0
2021	PO9283863365	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9332362915	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9321262940	KU	6	30 OTH	UN	CRE		V	00:00.0
2021	PO9331362789	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9320163080	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9329462578	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO4371505139	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4408205288	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4311805062	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX PX	00:00.0
2021	PO4318604963	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4322605043	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX PX	00:00.0
2021	PO4330804896	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4389705208	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4307705091	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4351605069	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO9112062129	KU	4	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9477158334	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO9184860879	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9186560892	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9077162142	KU	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO9066161998	KU	5	35 BRO	SP	S		V	00:00.0
2021	PO9111462100	KU	6	30 BRO	SP	CRE		V	00:00.0
2021	PO9123762054A	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO9123762054	KU	2	60 BRO	SP	CCA		V	00:00.0
2021	PO9113461917	KU	5	35 BRO	SP	CRE		V	00:00.0
2021	PO9109462031	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO9112462081	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO9094162134	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO9128862267	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO9489558382	KU	5	35 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4036584135	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021	PO4038384148	LGE	4	30 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021	PO4039484155	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5645027643	KU	5	35 UNK	SP	CRE		B	00:00.0
2021	PO5652027616	KU	5	35 UNK	SP	CRE		B	00:00.0
2021	PO4117184329	LGE	4	40 BRO	SP	CRE		B	00:00.0
2021	PO4117384323	LGE	4	35 BRO	SP	CCA		B	00:00.0
2021	PO4118084304	LGE	4	35 BRO	SP	CRE		B	00:00.0
2021	PO4105884454	LGE	4	40 BRO	SP	CRE		B	00:00.0
2021	PO4087384459	LGE	4	30 BRO	SP	P		B	00:00.0
2021	PO4086684455	LGE	4	30 BRO	SP	P		B	00:00.0
2021	PO5632628332	KU	4	40 UNK	SP	CRE		B	00:00.0
2021	PO5612928556	KU	4	40 UNK	SP	CRE		B	00:00.0
2021	PO5598228587	KU	4	40 UNK	SP	CRE		B	00:00.0
2021	PO4032684112	LGE	4	30 BRO	SP	CRE		B	00:00.0
2021	PO5500028211	KU	2	50 UNK	SP	CRE		B	00:00.0
2021	PO4031084117	LGE	3	50 BRO	SP	P		B	00:00.0
2021	PO8148452809	ODP	5	30 XXX	SP	CRE	ID	BD	00:00.0
2021	PO1325764244	KU	4	40 BRN	SP	CRE	ID,IP,MD	BD	00:00.0
2021	PO4014584112	LGE	UNK	55 ACE	SP	CRE	ED,ID,IP	BD	00:00.0

2021 PO8286852842	ODP	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO8327453535	ODP	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO3989283770	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4085884413	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP	BD	00:00.0
2021 PO4082684414	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4082684403	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO3994883589	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4112784568	LGE	4	40 BRO	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4022784034	LGE	4	35 ACE	SP	CCA	ED	BD	00:00.0
2021 PO4024784061	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4023484066	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4022484068	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4021684048	LGE	3	50 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4021384036	LGE	UNK	60 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8189952306	ODP	6	30 XXX	SP	CCA	ED	T	00:00.0
2021 PO1408764617	KU	3	45 BRN	SP	CCA	ED,MD	T	00:00.0
2021 PO9456453524	ODP	6	30 BRO	SP	S	ED,SR	T	00:00.0
2021 PO9463353313	ODP	4	40 BRO	SP	S	ED	T	00:00.0
2021 PO3988283763	LGE	4	40 BRO	SP	CCA	ED	T	00:00.0
2021 PO4001183720	LGE	4	35 BRO	SP	CCA	ED	T	00:00.0
2021 PO4083684437	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4004883790	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO1880968046	KU	4	40 OTH	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1866768021	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO8053352585	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8041252854	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO3686881875	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4785788098	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4785988135	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4861488044	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4861088088	KU	4	40 UNK	SP	CRE	ID	TD	00:00.0
2021 PO3502984379	KU	6	30 UNK	SP	CRE	ID	TD	00:00.0
2021 PO4231985763	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO4330188453	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO4084684432	LGE	4	40 BRO	SP	P	ED,EP,ID	TD	00:00.0
2021 PO3994383603	LGE	4	35 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO3996083607	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO1900967889	KU	4	45 BRN	SP	A	ED,IP	TD	00:00.0
2021 PO1608765238	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO3993683769	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4329888416	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO9508453305	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1532964969	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO9454454094	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3994383586	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4209285198	KU	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO1384764504	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO8247052713	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8164051888	ODP	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8190552133	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8190552133A	ODP	5	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8176752223	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8320853427	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8307953464	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0



2021	PO8208752594	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO8187352930	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1364864408	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO8169752467	ODP	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1488664917	KU	3	45 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO4023084079	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO8108452541	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1458764886	KU	4	40 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021	PO1608765238A	KU	4	40 BRN	SP	CRE	ED,IP,SRS	TD	00:00.0
2021	PO3262481882	KU	5	35 INP	SP	CRE	ID	TD	00:00.0
2021	PO3204180634	KU	6	30 BRO	SP	CRE	ID	TD	00:00.0
2021	PO4014684119	LGE	4	30 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021	PO4022884073	LGE	UNK	45 ACE	SP	CRE	ED,ID,RB	TX RR	00:00.0
2021	PO8236652645	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021	PO8143851833	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021	PO5723128210	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5724828195	KU	3	50 UNK	SP	CCA		V	00:00.0
2021	PO5720128424	KU	2	55 UNK	ST	CCA		V	00:00.0
2021	PO5678428413	KU	3	50 UNK	SP	CCA		V	00:00.0
2021	PO5660328454	KU	3	50 UNK	SP	CCA		V	00:00.0
2021	PO8237552799	F	5	35 XXX	SP	CRE		V	00:00.0
2021	PO5498127594	KU	6	30 UNK	SP	CCA		V	00:00.0
2021	PO5585827492	KU	2	50 UNK	SP	CCA		V	00:00.0
2021	PO5614926853	KU	5	35 UNK	SP	CRE		V	00:00.0
2021	PO5533026410	KU	2	45 UNK	SP	CCA		V	00:00.0
2021	PO5536426413	KU	2	60 UNK	ST	CCA		V	00:00.0
2021	PO5538726619	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5516726590	KU	4	45 UNK	SP	CCA		V	00:00.0
2021	PO5518726609	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO5516926563	KU	3	45 UNK	SP	CCA		V	00:00.0
2021	PO3990583762	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO4500388286	F	4	35 BRN	SP	CRE		V	00:00.0
2021	PO4500288279	F	4	35 BRN	SP	CRE		V	00:00.0
2021	PO2010293991	F	4	35 BRN	SP	CRE		V	00:00.0
2021	PO4492988159	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4502088285	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4473088270	F	4	35 BRN	SP	A		V	00:00.0
2021	PO4473088263	F	4	35 BRN	SP	CRE		V	00:00.0
2021	PO4473088250	F	4	35 BRN	SP	CCA		V	00:00.0
2021	PO4473088241	F	4	35 BRN	SP	CCA		V	00:00.0
2021	PO4473088228	F	4	35 BRN	SP	A		V	00:00.0
2021	PO4473088222	F	4	35 BRN	SP	CCA		V	00:00.0
2021	PV4473082185	F	4	35 BRN	SP	A		V	00:00.0
2021	PO4473088203	F	4	35 BRN	SP	CCA		V	00:00.0
2021	PO4473088191	F	4	35 BRN	SP	CCA		V	00:00.0
2021	PO3996083581	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4089284513	LGE	4	35 BRO	UN	CRE		V	00:00.0
2021	PO4080084393	LGE	6	25 BRO	SP	CRE		V	00:00.0
2021	PO4086584431	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021	PO410268448-B	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO410268448-A	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4025084027	LGE	4	35 ACE	SP	P	ED	V	00:00.0
2021	PO4024584018	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0
2021	PO4023984031	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0

2021 PO4091684489	LGE	4	30 BRO	SP	P		V	00:00.0
2021 PO7381752210	LGE	4	35 ACE	SP	CCA	ED	V	00:00.0
2021 PO4115984247	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4118984284	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9415253437	ODP	4	45 BRO	SP	S		V	00:00.0
2021 A5635027628	KU	3	35 UNK	SP	CCA		V	00:00.0
2021 PO5635027628	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO9513253380	ODP	6	30 BRO	SP	S		V	00:00.0
2021 PO9431953607	ODP	4	45 BRO	SP	S		V	00:00.0
2021 PO9463353901	ODP	4	45 BRO	SP	S		V	00:00.0
2021 PO5689626877	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5707926480	KU	4	40 UNK	ST	CCA		V	00:00.0
2021 PO5788726251	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO5761826900	KU	5	35 UNK	SP	CCA		V	00:00.0
2021 PO4319088677	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO3998683799	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3999883798	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4000883797	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4002383796	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4003483795	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4307988901	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5234388193	KU	6	30 BRO	SP	CRE		V	00:00.0
2021 PO4551288416	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3995183801	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3996383800	F	4	40 BRO	SP	A		V	00:00.0
2021 PO3997583799	F	4	40 BRO	SP	A		V	00:00.0
2021 PO1906467954	F	4	40 BRN	SP	A		V	00:00.0
2021 PO3996883594	F	1	50 BRO	SP	CRE		V	00:00.0
2021 PO3997583606	F	1	50 BRO	SP	CCA		V	00:00.0
2021 PO3991983761	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3993483761	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7133447792	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4259386576	KU	4	40 KOP	SP	S		V	00:00.0
2021 PO4080684411	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9497552776	ODP	4	40 BRO	SP	S		V	00:00.0
2021 PO9486753206	ODP	3	50 BRO	SP	S		V	00:00.0
2021 PO1591965071	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4081584391	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4082484380	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3986983764	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO3988183759	F	4	30 BRO	SP	A		V	00:00.0
2021 PO3989183757	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO3989283763	F	4	40 BRO	SP	A		V	00:00.0
2021 PO8080852540	ODP	5	35 XXX	SP	CCA		V	00:00.0
2021 PO8088052391	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8063552376	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4003983725	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4004783740	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4002283732	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4001983727	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4002283723	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4002583730	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4551288667	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4031383052	KU	4	40 UNK	SP	CRE		V	00:00.0

2021 PO4064983230	KU	4	40 UNK	SP	CRE		V	00:00.0	
2021 PO4004583794	F	3	45 BRO	SP	A		V	00:00.0	
2021 PO4004683803	F	6	25 BRO	SP	CRE		V	00:00.0	
2021 PO4119784266	LGE	3	45 BRO	UN	CRE		V	00:00.0	
2021 PO9452053418	ODP	3	50 BRO	SP	S		V	00:00.0	
2021 PO4005383750	F	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4006083763	F	4	35 BRO	SP	A		V	00:00.0	
2021 PO9523951682	ODP	4	40 BRO	SP	S		V	00:00.0	
2021 PO9523451560	F	6	30 BRO	SP	S		V	00:00.0	
2021 PO9519151449	ODP	4	40 BRO	SP	S		V	00:00.0	
2021 PO9532352164	ODP	4	40 BRO	SP	S		V	00:00.0	
2021 PO9530452698	ODP	4	40 BRO	SP	S		V	00:00.0	
2021 PO7479452965	KU	H2	65 BRO	SP	P		V	00:00.0	
2021 PO4030984119	LGE	UNK	110 BRO	SP	A		V	00:00.0	
2021 PO4149083688	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO1511064929	KU	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO3999682887	KU	4	40 INP	SP	CRE		V	00:00.0	
2021 PO7986177090	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO7982477240	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO7978677387	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO7976777498	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO7942976474	F	5	35 ACE	SP	CRE		V	00:00.0	
2021 PO7951076380	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO7945376361	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO7940876347	KU	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO7942176293	KU	6	30 ACE	SP	CCA		V	00:00.0	
2021 PO5626528171	KU	6	30 UNK	SP	CCA		V	00:00.0	
2021 PO5618928169	KU	6	30 UNK	SP	CCA		V	00:00.0	
2021 PO5638128159	KU	6	30 UNK	SP	CCA		V	00:00.0	
2021 PO5632427588	KU	5	35 UNK	SP	CCA		V	00:00.0	
2021 PO7977277596	F	4	40 ACE	SP	P		V	00:00.0	
2021 PO5394429161	KU	4	40 UNK	SP	CCA		V	00:00.0	
2021 PO5486228172	KU	3	45 UNK	SP	CCA		V	00:00.0	
2021 PO7930977594	KU	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7931077460	KU	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO7935477377	F	6	30 ACE	SP	CRE		V	00:00.0	
2021 PO7935377229	F	5	35 ACE	SP	CCA		V	00:00.0	
2021 PO7934976945	F	5	35 ACE	SP	CRE		V	00:00.0	
2021 PO7935776811	F	6	30 ACE	SP	CRE		V	00:00.0	
2021 PO8129452605	ODP	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO8148952335	ODP	5	35 XXX	SP	CCA		V	00:00.0	
2021 PO1562865025	KU	4	40 BRN	SP	CRE	HH,ID,IP,MD	X	RP2	00:00.0
2021 PO4890926892	KU	5	30 UNK	SP	CRE		B		00:00.0
2021 PO5151025866	KU	5	35 UNK	SP	CRE		B		00:00.0
2021 PO5345826327	KU	2	45 UNK	SP	CRE		B		00:00.0
2021 PO5345726470	KU	3	45 UNK	SP	CRE		B		00:00.0
2021 PO5420227474	KU	3	45 UNK	SP	CRE		B		00:00.0
2021 PO5447026761	KU	3	45 UNK	SP	CRE		B		00:00.0
2021 PO5257827406	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO5263927137	KU	3	50 UNK	SP	CRE		B		00:00.0
2021 PO4903625991	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO4905225841	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO4909525549	KU	4	40 UNK	SP	CRE		B		00:00.0
2021 PO4901426129	KU	4	40 UNK	SP	CRE		B		00:00.0

2021 PO4896926468	KU	4	40 UNK	SP	CRE		B	00:00.0
2021 PO4892626766	KU	5	35 UNK	SP	CRE		B	00:00.0
2021 PO7965376838	KU	3	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4437088058	LGE	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO3788984929	KU	4	40 INP	SP	CRE	ID	BD	00:00.0
2021 PO7959176898	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7994576916	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4436088132	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4436988018	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4433288112	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4436388109	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4437988067	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4007984106	LGE	4	40 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO7936476765	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9447758159	ODP	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4004184047	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8012677321	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4401485524	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4411185824	LGE	UNK	75 ACE	SP	CRE		V	00:00.0
2021 PO5790005301	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4373285980	LGE	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4370685995	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4369986001	LGE	4	40 ACE	SP	CRE	ED	V	00:00.0
2021 PO4369086006	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4367986013	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4904685293	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4904985299	F	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4369785933	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO4372786032	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4371886039	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4370586047	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4369986055	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO5782605358	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5769305412	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5753405413	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5752905073	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5744105132	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5740705266	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5738405372	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5736305468	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5734905589	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5787605607	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5789105736	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5773705771	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5767505676	F	5	35 XXX	SP	P		V	00:00.0
2021 PO5759905686	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5747205705	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5734105806	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5734205715	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4905085295	F	5	25 BRO	SP	CCA		V	00:00.0
2021 PO4376986063	F	3	25 ACE	SP	CRE		V	00:00.0
2021 PO4375086039	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4379085977	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4378085978	F	4	25 ACE	SP	CRE	ED	V	00:00.0

2021 PO4381385984	F	3	50 ACE	SP	A	V	00:00.0
2021 PO4380385977	F	3	45 ACE	SP	CRE	V	00:00.0
2021 PO4379385970	F	3	45 ACE	SP	A	V	00:00.0
2021 PO4378485963	F	3	45 ACE	SP	A	V	00:00.0
2021 PO5777605882	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5768405902	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5753405922	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5734605950	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5736606063	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5740306171	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5775806177	F	4	40 XXX	SP	CCA	V	00:00.0
2021 PO5760706192	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5743806271	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4375985930	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO5747606440	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO4377185923	F	3	45 ACE	SP	CRE	V	00:00.0
2021 PO4376885919	F	4	30 ACE	SP	A	V	00:00.0
2021 PO4905785278	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4905885265	F	3	50 BRO	SP	CRE	V	00:00.0
2021 PO4376685950	F	3	45 ACE	SP	A	V	00:00.0
2021 PO4376185950	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO6512100414	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6506900285	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4374185926	LGE	1	55 ACE	SP	CRE	V	00:00.0
2021 PO4373485919	LGE	1	60 ACE	SP	CCA	V	00:00.0
2021 PO4911485276	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4910485262	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4382085988	F	3	50 ACE	SP	CRE	V	00:00.0
2021 PO5748106562	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5754006565	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5746206817	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5747206686	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5745206948	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5744407065	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PV0970772126	F	3	45 ACE	SP	CRE	V	00:00.0
2021 PO4383485969	F	4	40 ACE	SP	S	V	00:00.0
2021 PO4383885963	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4384185959	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4384985949	F	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4384585955	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6660499575	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO6602799897	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6580500017	F	4	40 ACE	SP	P	V	00:00.0
2021 PO6591899957	F	4	40 ACE	SP	P	V	00:00.0
2021 PO4377485956	F	3	45 ACE	SP	CRE	V	00:00.0
2021 PO4377585938	LGE	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4375585942	F	3	50 ACE	SP	CRE	V	00:00.0
2021 PO4371585734	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4908285234	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO6535600279	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6543900228	F	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4909485246	F	2	55 BRO	SP	A	V	00:00.0
2021 PO6547900204	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO6558500145	F	4	40 ACE	SP	CRE	V	00:00.0

2021 PO6570600075	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6647399651	F	4	40 ACE	SP	P		V	00:00.0
2021 PO5720206394	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5705006419	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5706906528	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5706106589	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5707406668	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5709606796	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5710506926	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5687107064	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5695207239	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5701507217	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO5713007162	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5718507137	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5720607186	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO6623399310	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6617199209	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6611599116	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6604999007	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6599098909	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6594198826	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6601198781	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6611798715	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6621698654	F	3	45 ACE	SP	P		V	00:00.0
2021 PO6633898578	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4383185916	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4372585784	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4371685772	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4370385763	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4387985910	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4386685926	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4379785926	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6625499775	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6642599602	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6635199505	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6629499412	F	4	40 ACE	SP	CRE		V	00:00.0
2021 4378285915-A	F	3	45 ACE	SP	P		V	00:00.0
2021 PO6598199809	F	3	40 ACE	SP	P		V	00:00.0
2021 PO4374385697	LGE	3	45 ACE	SP	CCA	ED	V	00:00.0
2021 PO4383985922	F	3	45 ACE	SP	CRE		V	00:00.0
2021 PO5572206981	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4387385917	F	4	40 ACE	SP	P		V	00:00.0
2021 PO5854263360	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4390686013	F	4	40 ACE	SP	CCA		V	00:00.0
2021 4391786009-a	F	3	35 ACE	SP	CRE		V	00:00.0
2021 PO4871785004	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4391286006	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO1059272408	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4369785758	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4387085945	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4384985929	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4385885936	F	3	45 ACE	DF	CRE		V	00:00.0
2021 PO4387885951	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4388785957	F	4	40 ACE	SP	A		V	00:00.0

2021	PO4389485962	F	4	40 ACE	SP	CRE		V			00:00.0
2021	PO4389585959	F	3	40 ACE	SP	CCA		V			00:00.0
2021	PO5795605237	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO4400785533	F	4	40 ACE	SP	P		V			00:00.0
2021	PO5033385128	LGE	4	35 BRO	SP	CCA		V			00:00.0
2021	PO5031785126	LGE	3	45 BRO	SP	CRE		V			00:00.0
2021	PO5031885128	LGE	3	45 BRO	SP	CCA		V			00:00.0
2021	PO4869085011	LGE	3	45 BRO	SP	CCA		V			00:00.0
2021	PO4373885788	LGE	4	35 ACE	SP	P	ED,HH,ID	VX	PX		00:00.0
2021	PO4376885705	LGE	4	40 ACE	SP	CRE	ED,HH,ID	VX	PX		00:00.0
2021	PO8227689049	KU	4	40 XXX	DF	CRE	ED,ID,IP,MD	BD			00:00.0
2021	PO4365285508	LGE	5	35E ACE	SP	P	ED,EP	BD			00:00.0
2021	PO8240388894	KU	5	35 XXX	DF	CRE	ED,ID,IP	BD			00:00.0
2021	PO5518105499	KU	4	40 XXX	SP	CRE	ID	BD			00:00.0
2021	PO5532905400	KU	6	30 XXX	SP	CRE	ID	BD			00:00.0
2021	PO5504806358	KU	4	40 XXX	SP	P	ID	BD			00:00.0
2021	PO5504806155	KU	3	40 XXX	SP	CRE	ID	BD			00:00.0
2021	PO4898985440	LGE	4	40 BRO	SP	A	ID,IP	BD			00:00.0
2021	PO4894785483	LGE	4	40 BRO	SP	CRE	ID,IP	BD			00:00.0
2021	PO4898285550	LGE	4	40 BRO	SP	CRE	ID,IP	BD			00:00.0
2021	PO4898585491	LGE	2	50 BRO	SP	A	ID,IP	BD			00:00.0
2021	PO6560599295	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO6545899185	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO6588299643	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO6526799604	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO6562499814	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO6532099951	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO4363485516	LGE	UNK	85 ACE	SP	CRE	ED,ID	BX	RR		00:00.0
2021	PO6377200228	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO4896985575	LGE	4	30 BRO	SP	CRE	ED,HH,ID,RB	BX	RP1		00:00.0
2021	PO6540999524	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO6147800601	KU	6	30 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1		00:00.0
2021	PO6148500607	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO6448900615	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021	PO5829405194	KU	5	35 XXX	SP	CCA	ED	T			00:00.0
2021	PO5802105487	KU	5	35 XXX	SP	CCA	ED	T			00:00.0
2021	PO8086788773	KU	5	35 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD			00:00.0
2021	PO8086789073	KU	5	35 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD			00:00.0
2021	PO8086789323	KU	5	35 XXX	SP	CRE	ED,ID,MD,SRC	TD			00:00.0
2021	PO8086389583	KU	4	40 XXX	SP	CRE	ED,ID	TD			00:00.0
2021	PO8086189778	KU	6	35 XXX	SP	CRE	ED,ID,IP,MD	TD			00:00.0
2021	PO4897985573	LGE	4	40 BRO	SP	A	ED,ID,IP	TD			00:00.0
2021	PO8030588470	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO8063588458	KU	4	40 XXX	SP	CRE	ED,ID	TD			00:00.0
2021	PO4899685376	LGE	3	45 BRO	SP	A	ED,ID	TD			00:00.0
2021	PO8278788440	KU	4	40 XXX	SP	CRE	ED,ID	TD			00:00.0
2021	PO8291888289	KU	6	35 XXX	DF	CRE	ED,ID,IP,MD,SRC	TD			00:00.0
2021	PO8252588742	KU	5	35 XXX	DF	CRE	ED,ID,SRC	TD			00:00.0
2021	PO4381985373	LGE	4	30 ACE	SP	A	ED,ID	TD			00:00.0
2021	PO4896585625	LGE	4	30 BRO	SP	A	ED,ID	TD			00:00.0
2021	PO4898485513	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO8214789214	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD			00:00.0
2021	PO8201989368	KU	5	35 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD			00:00.0
2021	PO4897985592	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			00:00.0

2021 PO8161089874	KU	5	35 XXX	DF	CRE	ED,ID,IP	TD	00:00.0
2021 PO8144790083	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8115590438	KU	5	35 XXX	DF	CRE	ED,ID,IP	TD	00:00.0
2021 PO8130690252	KU	5	35 XXX	DF	CRE	ED,ID,IP,MD	TD	00:00.0
2021 PO4898385533	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4388485332	LGE	3	50 ACE	SP	CRE	ED	TD	00:00.0
2021 PO4895985579	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4897285587	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5527806061	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5534106049	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5538506238	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4897785459	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8190889504	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4898185391	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4896285595	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4897785617	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4898785462	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR 00:00.0
2021 PO4386285380	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4393585478	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4394285469	F	UNK	45 ACE	SP	A		V	00:00.0
2021 PO4394985460	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4395785451	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4397085435	F	3	45 ACE	SP	A		V	00:00.0
2021 PO4397185439	F	UNK	45 ACE	SP	A		V	00:00.0
2021 PO4398185448	F	4	40 ACE	SP	A		V	00:00.0
2021 PO6402099634	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6389199481	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4400585375	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4397485355	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4399985361	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4399585367	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4398985351	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4398185361	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4397785380	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4397185374	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4399285451	F	4	40 ACE	SP	A		V	00:00.0
2021 PO6578599707	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6574599524	F	4	40 ACE	SP	P		V	00:00.0
2021 PO6566799395	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8176089692	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO5513205704	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO4393485490	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4392885486	F	4	40 ACE	SP	A		V	00:00.0
2021 PO4899085412	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5523006230	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5516806258	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5514306265	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5534406301	F	4	40 KOP	SP	P		V	00:00.0
2021 PO5523406292	F	4	40 KOP	SP	P		V	00:00.0
2021 PO5525806516	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5521006568	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5526406617	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5531106676	F	4	40 BRN	SP	P		V	00:00.0
2021 PO5515806718	F	4	40 BRN	SP	CRE		V	00:00.0



2021	7428201179A	KU	2	50 UNK	SP	CRE	ID	BD	00:00.0	
2021	4370985002	LGE	3	20 ACE	SP	CRE		V	00:00.0	
2021	4367284972-a	LGE	4	20 ACE	SP	CRE		V	00:00.0	
2021	4367284972	LGE	4	20 ACE	SP	CRE		V	00:00.0	
2021	4367284992	LGE	3	20 ACE	SP	CRE		V	00:00.0	
2021	9839978023	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021	9840877881	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021	9841277738	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021	9850477452	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021	9841277595	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021	9839577309	LGE	4	35 BRO	SP	CCA		V	00:00.0	
2021	4374985024-a	LGE	4	35 ACE	SP	P		V	00:00.0	
2021	9811678172	LGE	1	50 BRO	SP	CCA		V	00:00.0	
2021	8719600799A	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	8719600799B	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	8719600799C	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	4283386673	LGE	3	45 BRO	SP	A		V	00:00.0	
2021	4285186675	LGE	3	40 BRO	SP	A		V	00:00.0	
2021	4286086676	LGE	3	40 BRO	SP	CRE		V	00:00.0	
2021	PO4410285835	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO7534304601	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7432100784	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7421101013	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7968606759	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7939806486	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7456600854	KU	3	45 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7433900588	KU	3	45 UNK	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO7369202366	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7380302116	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7451303509	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	8450286485A	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7462000800	KU	2	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7421503013	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO8689700982	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4401485891	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4402685899	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4400685865	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4404985881	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4401585857	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4403185868	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO4412985732	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO7505304216	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7514704333	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4427085567	LGE	3	45 BRO	SP	A	ED,ID,IP,RB	BX	RP1	00:00.0
2021	PO4420185825	LGE	3	45 BRO	SP	CRE	ED,ID,RB	BX	RR	00:00.0
2021	PO4415785749	LGE	2	55 BRO	SP	CRE	ED,EP,ID,IP,RB	TX	RR	00:00.0
2021	PO7516108569	F	4	40 XXX	SP	CRE	ED,HH,ID,IP	BX	RP2	00:00.0
2021	PO4414885864	LGE	3	45 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0
2021	PO5596310964	KU	4	45 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO4413785834	LGE	4	40 BRO	SP	CRE	ED,EP,ID,RB	VX	RP1	00:00.0
2021	PO4421885533	LGE	4	40 BRO	SP	CRE	ED,ID,RB	VX	RP1	00:00.0
2021	PO5546411008	KU	4	40 BRN	SP	CRE	ED,HH,ID	X	PX	00:00.0
2021	PO4410385871	LGE	3	50 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021	PO4411485888	LGE	4	40 BRO	SP	CRE	ED,EP,ID,RB	X	RP1	00:00.0

2021 PO8881597329	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8985596786	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8883597009	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021 PO7480003898	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO7474603828	KU	2	50 ACE	SP	CCA		V	00:00.0
2021 PO4409085862	LGE	1	70 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7425700914	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7443700705	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7412701013	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7777107568	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4374384981	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4411385877	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4412385885	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO5408210608	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7849207017	KU	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4416185866	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4416685871	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7780706680	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO4409585855	LGE	1	75 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4418985869	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO8752301116	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4410685858	F	1	65 BRO	SP	A		V	00:00.0
2021 PO2537217663	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 2540117812a	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO2540117812	F	4	40 BRN	SP	A		V	00:00.0
2021 PO2547417995	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2555218198	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4409985868	F	2	55 BRO	SP	CRE		V	00:00.0
2021 PO5609908989	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5610409039	F	4	40 BRN	SP	A		V	00:00.0
2021 PO5611109115	F	4	40 BRN	SP	A		V	00:00.0
2021 PO5613309339	F	4	40 BRN	SP	A		V	00:00.0
2021 PO5615609674	F	4	40 BRN	SP	A		V	00:00.0
2021 PO9408801720	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9427601724	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5607309453	F	5	40 BRN	SP	CRE		V	00:00.0
2021 PO5614609447	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5587910962	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5570010956	KU	4	40 BRN	SP	CRE		BD	00:00.0
2021 PO5559210954	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5574610942	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO5615009558	F	4	40 BRN	SP	A		V	00:00.0
2021 PO7601805161	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7402401692	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7622005170	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO8643200087	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO5558510733	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO9499200331	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO5564010666	KU	4	40 UNK	SP	S		V	00:00.0
2021 PO5514111451	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5569410828	KU	6	30 UNK	SP	CCA		V	00:00.0
2021 PO4419785815	F	5	25 BRO	SP	CRE		V	00:00.0
2021 PO4420185816	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4266086464	LGE	1	55 BRO	SP	CCA		V	00:00.0

2021 PO4265586466	F	1	55 BRO	SP	CCA		V	00:00.0
2021 PO9773776752	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO4419985844	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4419985843	F	3	50 BRO	SP	A		V	00:00.0
2021 PO7463400784	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7813008037	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO7821408147	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO7825308195	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7435000286	KU	3	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO2393420256	F	4	40 BRN	SP	A		V	00:00.0
2021 PO2377020293	F	4	40 BRN	SP	A		V	00:00.0
2021 PO8877697918	KU	3	40 XXX	SP	S		V	00:00.0
2021 PO8928397941	F	4	40 XXX	SP	S		V	00:00.0
2021 PO8975397621	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8837998565	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO5435310603	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO7450101112	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7447701088	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7446201073	KU	3	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO8879297661	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO2434920523	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4376884951	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4408485873	LGE	2	65 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5405310796	KU	6	30 BRN	SP	S		V	00:00.0
2021 PO5431610860	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO1279671104	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO2585319572	F	4	40 BRN	SP	A		V	00:00.0
2021 PO2598019523	F	4	40 BRN	SP	A		V	00:00.0
2021 PO2603619440	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2597719278	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2590919100	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2582518891	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5398110690	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO1255070902	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4412785861	LGE	2	55 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4383584950	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4374685074	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4375185067	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO5391910784	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5383310626	KU	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7836707133	KU	4	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7851907263	KU	4	40 BRN	SP	CRE	SRS	TD	00:00.0
2021 PO4419485868	LGE	5	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4374985024	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4375185045	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO7809506887	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5449710790	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5398210905	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO2471119949	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO2473420006	F	4	40 BRN	SP	A		V	00:00.0
2021 PO2507220039	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7471501002	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5437910745	KU	2	50 UNK	SP	CCA		V	00:00.0
2021 PO4382885207	LGE	4	40 ACE	SP	CCA		V	00:00.0

2021 PO9019396568	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO8958895800	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8955695532	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8893896717	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7763906668	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5441910737	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7464801026	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7478300943	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7456801055	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7449601081	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7734506463	KU	4	35 BRN	SP	CRE	ED	BD	00:00.0
2021 PO5493610824	F	4	40 UNK	SP	P		V	00:00.0
2021 PO7536304627	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7760706598	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5444310904	KU	3	45 UNK	SP	CRE	ID	TD	00:00.0
2021 PO7737706280	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO7762006426	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5495811089	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO9757897876	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9752997884	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9653198089	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9723897929	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9740597903	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9242296653	KU	3	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7734506463	KU	6	30 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4409185910	LGE	4	35 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO7746506612	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5470011179	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5457111224	F	3	45 UNK	SP	S		V	00:00.0
2021 PO5461210735	KU	4	40 UNK	SP	CRE	IP	BD	00:00.0
2021 PO9057797493	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO9086297726	KU	4	40 XXX	SP	S		V	00:00.0
2021 PO5496210906	KU	3	45 UNK	SP	CCA		V	00:00.0
2021 PO7652805201	KU	1	55 BRN	SP	CCA		V	00:00.0
2021 PO7653305122	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO7654505132	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO7662205209	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7670605219	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5496910935	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO7666608427	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7680508280	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7691808166	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7704208041	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7714907929	F	2	50 BRN	SP	CRE		V	00:00.0
2021 PO7726607806	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7738007693	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7739907551	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO7750807566	F	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4413285818	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4414885794	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4414085805	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4413785810	F	3	45 BRO	SP	A		V	00:00.0
2021 PO4415885787	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4415485784	F	3	50 BRO	SP	CRE		V	00:00.0

2021 PO4269286461	F	1	25 BRO	SP	CRE		V	00:00.0
2021 PO4268986461	F	1	50 BRO	SP	CRE		V	00:00.0
2021 PO4268286462	F	1	55 BRO	SP	CRE		V	00:00.0
2021 PO4418785835	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5566311495	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO1317170723	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9921894210	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9830678137	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5564111047	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 9428401459A	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5567011648	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5629409382	F	4	45 BRN	SP	A		V	00:00.0
2021 PO4418585841	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5648209358	F	4	45 BRN	SP	A		V	00:00.0
2021 PO5663409478	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5604309932	F	4	40 BRN	SP	A		V	00:00.0
2021 PO5600710056	F	3	45 BRN	SP	A		V	00:00.0
2021 PO5621909390	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5565411347	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5564711202	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO9413501248	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9430200897	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9430700686	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7546604768	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7556904909	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7552804838	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7652408215	KU	2	60 BRN	SP	CCA		V	00:00.0
2021 PO7646408164	KU	2	60 BRN	SP	CCA		V	00:00.0
2021 PO5555311096	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO4417485840	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5607109820	F	4	40 BRN	SP	A		V	00:00.0
2021 PO7530904676	KU	4	40 BRN	SP	CRE		BD	00:00.0
2021 PO7577705077	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO7576504992	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO9529200339	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5573910665	F	4	40 UNK	SP	S		V	00:00.0
2021 PO5583910664	F	4	40 UNK	SP	CCA		V	00:00.0
2021 PO9126662206	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9107162194	KU	4	45 UNK	SP	CRE		V	00:00.0
2021 PO4822590360	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4816690327	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO9094962317	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9097162294	KU	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5286107650	KU	2	50 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021 PO5557607687	KU	2	40 BRN	SP	CRE		T	00:00.0
2021 PO5121707631	KU	3	45 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021 PO5114007441	KU	3	45 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021 PO5112507221	KU	4	45 XXX	SP	S	ED,SRC	T	00:00.0
2021 PO5159207118	KU	3	45 XXX	SP	S	ED,SRC	T	00:00.0
2021 PO7134823069	KU	4	40 KOP	SP	CCA	ED	T	00:00.0
2021 PO6752423100	KU	3	45 XXX	SP	CCA	ED	T	00:00.0
2021 PO2975217641	KU	4	40 BRN	SP	CCA	ED	T	00:00.0
2021 PO4680313451	KU	5	35 KOP	SP	CCA	ED	T	00:00.0
2021 PO4410108502	KU	5	35 KOP	SP	CCA	ED	T	00:00.0

2021	PO2222821220	KU	6	30 BRN	SP	CCA	ED	T		00:00.0
2021	PO7557708300	KU	2	40 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5266607964	KU	4	45 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5221609516	KU	6	30 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5240209425	KU	4	40 XXX	SP	CRE	ED,HH,ID	BD		00:00.0
2021	PO5265609330	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5420610881	KU	5	35 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5424110892	KU	3	45 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5219708617	KU	3	45 XXX	SP	CRE	ED,ID,IP,MD	BD		00:00.0
2021	PO5257807999	KU	3	45 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5216808154	KU	4	45 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5166507990	KU	5	35 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5237308079	KU	2	45 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5241608063	KU	3	45 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5277107853	KU	6	30 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5564407331	KU	4	40 BRN	SP	CRE	ED	BD		00:00.0
2021	PO4405285905	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4405285903	LGE	5	35 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4405985909	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4400885911	LGE	4	40 BRO	SP	A	ID	BD		00:00.0
2021	PO4401785918	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4428285568	LGE	3	50 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4398085895	LGE	3	50 BRO	SP	A	ID	BD		00:00.0
2021	PO4395385877	LGE	3	50 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4392585868	LGE	3	45 BRO	SP	A	ID	BD		00:00.0
2021	PO4391485877	LGE	4	35 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO7425907454	F	4	40 XXX	SP	CRE	ED,ID	BX	RP1	00:00.0
2021	PO7409307032	F	4	40 XXX	SP	CRE	ED,ID	VX	PX	00:00.0
2021	PO7412607135	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021	PO7425306928	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	PX	00:00.0
2021	PO2215919705	KU	4	40 BRN	SP	CCA	ED,ID,SRC	TX	RR	00:00.0
2021	PO7420607328	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	PX	00:00.0
2021	PO2429619789	KU	5	35 BRN	SP	CRE	RB	X	PX	00:00.0
2021	PO7560006767	F	3	45 BRN	SP	CRE		BD		00:00.0
2021	PO4335919946	KU	4	40 BRN	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO3575615427	KU	5	35 BRN	SP	CRE	RB	X	PX	00:00.0
2021	PO5317511041	KU	2	60 XXX	SP	CRE	HH,ID	X	RP2	00:00.0
2021	PO4401086097	LGE	4	40 BRO	SP	A	ED,ID,RB	X	RP1	00:00.0
2021	PO5358726456	KU	5	35 UNK	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO5431009038	KU	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	X	PX	00:00.0
2021	PO4254787366	LGE	4	25 ACE	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO6256723267	KU	5	35 XXX	SP	CRE	HH,ID,IP	X	RP2	00:00.0
2021	PO5297037947	KU	4	40 BRO	SP	CRE	ED,HH,ID,IP	X	RP1	00:00.0
2021	PO6621823929	KU	5	35 XXX	SP	CRE	HH,ID	X	PX	00:00.0
2021	PO7103309172	KU	5	35 UNK	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO5438507720	KU	3	45 BRO	SP	CRE	ED,HH,ID,IP,MD	X	PX	00:00.0
2021	PO4293787170	LGE	3	45 ACE	SP	CRE	ED,MD	VX	PX	00:00.0
2021	PO4265386995	LGE	4	35 ACE	SP	A	ED,HH,ID	VX	RP1	00:00.0
2021	PO5382426361	F	4	40 BRO	SP	CRE		VX	PX	00:00.0
2021	PO5285529885	F	4	40 BRO	SP	CRE		VX	PX	00:00.0
2021	PO4494187925	LGE	4	40 ACE	SP	CRE	ED,ID	VX	RP1	00:00.0
2021	PO5368325879	F	4	40 ESC	SP	P		VX	RP1	00:00.0
2021	PO5378536469	KU	6	30 BRN	SP	CCA		V		00:00.0
2021	PO5349625698	F	4	40 ESC	SP	P		V		00:00.0

2021	PO5495026688	KU	4	40 KOP	SP	CCA		V	00:00.0
2021	PO5057720105	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5500208843	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO4292786819	F	4	35 ACE	SP	CRE		V	00:00.0
2021	PO4292386817	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PO4286686895	LGE	1	50 ACE	SP	CRE		V	00:00.0
2021	PO4287186888	LGE	3	55 ACE	SP	CCA		V	00:00.0
2021	PO5087819853	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5074119967	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO5103119724	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO7065007206	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO7057006864	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO7052606677	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5262630973	F	4	40 UNK	SP	CRE		V	00:00.0
2021	PO5241032036	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5236732292	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5245131836	F	2	45 XXX	SP	CCA		V	00:00.0
2021	PO5241232463	F	4	45 XXX	SP	P		V	00:00.0
2021	PO4293586801	LGE	1	50 ACE	SP	CRE		V	00:00.0
2021	PO4292986809	LGE	1	55 ACE	SP	CRE		V	00:00.0
2021	PO5355925120	F	4	40 ESC	SP	P		V	00:00.0
2021	PO5361024997	F	4	40 KOP	SP	CCA		V	00:00.0
2021	PO5358725376	F	4	40 KOP	SP	P		V	00:00.0
2021	PO5364225362	F	4	45 KOP	SP	CCA		V	00:00.0
2021	PO5368125548	F	4	45 MCM	SP	CCA		V	00:00.0
2021	PO5365325735	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4262787004	LGE	4	50 ACE	SP	CRE		V	00:00.0
2021	PO4263486997	LGE	5	25 ACE	SP	CRE		V	00:00.0
2021	PO9784981595	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PO4265486947	LGE	5	25 ACE	SP	A		V	00:00.0
2021	PO5654213006	KU	2	70 UNK	SP	CCA		V	00:00.0
2021	PO3905807979	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO3926708153	F	2	50 BRO	SP	CCA		V	00:00.0
2021	PO3919908130	F	3	45 BRO	SP	CCA	ED	V	00:00.0
2021	PO5398206334	KU	1	80 BRO	SP	CRE		V	00:00.0
2021	PO5397106340	KU	1	90 BRO	SP	CRE		V	00:00.0
2021	PO5406806644	KU	1	80 BRO	SP	CRE		V	00:00.0
2021	PO5408806637	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4426285505	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4425985503	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO7092513982	KU	4	40 KOP	SP	CRE		V	00:00.0
2021	PO5388205339	F	2	50 BRO	SP	CRE		V	00:00.0
2021	PO5372705411	F	2	50 BRO	SP	CRE		V	00:00.0
2021	PO5393222917	F	4	40 KOP	SP	P		V	00:00.0
2021	PO5380123629	F	4	40 MCM	SP	CCA		V	00:00.0
2021	PO5383023473	F	2	40 MCM	SP	CRE		V	00:00.0
2021	PO5386523281	F	4	45 KOP	SP	CCA		V	00:00.0
2021	PO5390523067	F	2	45 MCM	SP	CCA		V	00:00.0
2021	PO5336718170	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO5379616875	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO4494987913	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5358237052	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5361336406	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5519626296	KU	4	40 BRO	SP	CCA		V	00:00.0

2021	PO5538425953	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5547825782	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5557525614	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5568225422	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5580325209	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5427726803	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5182117097	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO5215217082	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO3918717822	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO4264086923	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021	PO5444609361	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO5479904953	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5482805020	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3979108000	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO3947807902	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO3957807933	F	3	45 BRO	SP	P		V	00:00.0
2021	PO5900901914	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5893101784	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5895101820	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5893601845	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5890701871	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5888701944	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5471004945	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO6043719319	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO7354105510	F	2	55 XXX	SP	CRE		V	00:00.0
2021	PO7401206031	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO3986707711	F	4	40 BRO	SP	CRE	ED,IP	V	00:00.0
2021	PO3977507683	F	4	40 BRO	SP	P	ED	V	00:00.0
2021	PO6061319857	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5375626183	F	4	40 ESC	SP	P		V	00:00.0
2021	PO4951627828	F	4	40 XXX	SP	CRE	ED,ID,IP	V	00:00.0
2021	PO4976627744	F	4	40 XXX	SP	CRE	ED,ID,IP	V	00:00.0
2021	PO4961127845	F	4	40 XXX	SP	CRE	ED,ID	V	00:00.0
2021	PO5369735642	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5359636721	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5371726027	KU	2	50 ESC	SP	CCA		V	00:00.0
2021	PO5371526017	KU	5	35 ESC	SP	CCA		V	00:00.0
2021	PO5371326006	KU	2	50 ESC	SP	CCA		V	00:00.0
2021	PO4415785402	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO4429785528	LGE	1	60 BRO	SP	CRE		V	00:00.0
2021	PO4265387050	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO4265487042	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO4400286165	F	2	55 BRO	SP	CCA		V	00:00.0
2021	PO4399486178	F	2	50 BRO	SP	A		V	00:00.0
2021	PO4399186181	F	3	50 BRO	SP	CCA		V	00:00.0
2021	PO4398586191	F	3	50 BRO	SP	CCA		V	00:00.0
2021	PO3912317020	F	4	40 BRN	SP	P		V	00:00.0
2021	PO3896917279	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4708226028	F	3	40 XXX	SP	P		V	00:00.0
2021	PO4697526134	F	3	40 XXX	SP	CRE		V	00:00.0
2021	PO4686326228	F	3	40 XXX	SP	P		V	00:00.0
2021	PO4675826319	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO4665626411	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO4655626508	F	3	45 XXX	SP	CRE	ED	V	00:00.0



2021 PO4263686902	LGE	3	50 ACE	SP	CRE		V	00:00.0
2021 PO5377121802	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5386522257	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5298129593	F	4	40 UNK	SP	P		V	00:00.0
2021 PO5349628379	F	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4401786082	F	4	35 BRO	SP	CRE		V	00:00.0
2021 PO4402086091	F	4	30 BRO	SP	CCA		V	00:00.0
2021 PO5305011416	KU	1	60 XXX	SP	S		V	00:00.0
2021 PO5293611178	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO4425985591	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4425785596	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO5033127403	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021 PO4294886792	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4852920051	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4851419780	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4850419510	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4849419240	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4848618924	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4848518653	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4861118397	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4856420860	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4857221131	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5462909046	KU	3	45 XXX	SP	S		V	00:00.0
2021 PV4250587534	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4954527891	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4808221604	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4269586930	LGE	1	80 ACE	SP	CRE		V	00:00.0
2021 PO5390326531	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5399526704	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4387286019	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4385386016	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4401186147	F	2	60 BRO	SP	CCA		V	00:00.0
2021 PO4249186932	LGE	2	60 ACE	SP	CCA		V	00:00.0
2021 PO4317507951	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4303508985	F	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4297208866	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO4297208797	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4333408826	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO4393708615	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4387708771	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4380008982	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5402610992	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5389611050	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5376811107	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5318838446	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5351438441	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO5351338505	KU	4	40 UNK	SP	CCA		V	00:00.0
2021 PO4253287221	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021 PO4254987343	LGE	1	60 ACE	SP	CRE		V	00:00.0
2021 PO4384608854	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4380309230	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4391309237	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4251787370	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO5293510698	KU	2	50 XXX	SP	S		V	00:00.0

2021	PO5293310449	KU	4	40 XXX	SP	S	V	00:00.0
2021	PO5294910219	KU	1	50 XXX	SP	S	V	00:00.0
2021	PO5294410152	KU	1	50 XXX	SP	S	V	00:00.0
2021	PO5295409780	KU	2	50 XXX	SP	S	V	00:00.0
2021	PO5180217947	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5185418054	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5187818108	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5341439233	KU	6	30 UNK	SP	CCA	V	00:00.0
2021	PO5830609385	KU	2	80 UNK	SP	CRE	V	00:00.0
2021	PO5840509202	KU	1	90 UNK	ST	CRE	V	00:00.0
2021	PO5849509034	KU	4	40 UNK	SP	CCA	V	00:00.0
2021	PO5424910998	KU	3	45 XXX	SP	CRE	V	00:00.0
2021	PO5839102123	F	3	40 XXX	SP	P	V	00:00.0
2021	PO5842802058	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5850901948	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5847302006	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5883401615	KU	4	40 XXX	SP	S	V	00:00.0
2021	PO5520505910	F	4	40 BRO	SP	P	V	00:00.0
2021	PO5505805973	F	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4251987133	LGE	1	60 ACE	SP	CCA	V	00:00.0
2021	PO4677126931	F	3	40 XXX	SP	CRE	V	00:00.0
2021	PO4836521279	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4337320237	KU	4	40 BRN	SP	CCA	V	00:00.0
2021	PO4338820565	KU	4	40 BRN	SP	CCA	V	00:00.0
2021	PO5464709175	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5466709265	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO4423385340	F	3	45 BRO	SP	A	V	00:00.0
2021	PO1366665801	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4421685340	F	3	45 BRO	SP	A	V	00:00.0
2021	PO4422185334	F	2	50 BRO	SP	A	V	00:00.0
2021	PO6267503103	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6281903102	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO6301203099	F	4	40 ACE	SP	P	V	00:00.0
2021	PO6317403096	F	4	40 ACE	SP	P	V	00:00.0
2021	PO6334503074	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4801709343	KU	6	30 XXX	SP	CCA	V	00:00.0
2021	PO4397885257	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO4396085243	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO4396985250	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5877200459	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5882000377	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO9035297552	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO9052197448	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO9063697378	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO9080297279	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO9093797223	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO9104997193	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO5892500310	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5909500047	F	1	55 ACE	SP	CRE	V	00:00.0
2021	PO9134097009	KU	2	50 XXX	SP	S	V	00:00.0
2021	PO9118097129	KU	3	45 XXX	SP	S	V	00:00.0
2021	PO6262903372	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO5947898505	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4412185286	F	4	40 BRO	SP	A	V	00:00.0

2021	PO9183097071	KU	5	45 XXX	SP	S		V			00:00.0
2021	PO0139090145	F	4	40 UNK	SP	P		V			00:00.0
2021	PO9241696834	KU	3	45 XXX	SP	S		V			00:00.0
2021	PO9241197023	KU	3	45 XXX	SP	S		V			00:00.0
2021	PO0056690265	KU	6	30 BRO	SP	CCA		V			00:00.0
2021	PO0048690306	KU	4	40 BRO	SP	CCA		V			00:00.0
2021	PO0025991025	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO9490894255	KU	2	50 XXX	SP	S		V			00:00.0
2021	PO9449294448	KU	2	50 XXX	SP	S		V			00:00.0
2021	PO9437494606	KU	3	45 XXX	SP	S		V			00:00.0
2021	PO9515094599	KU	3	45 XXX	SP	S		V			00:00.0
2021	PO0025090097	KU	5	40 BRO	SP	CCA		V			00:00.0
2021	PO6010696269	F	4	40 ACE	SP	CRE		V			00:00.0
2021	PO6007596400	F	4	40 ACE	SP	CRE		V			00:00.0
2021	PO6055195795	F	4	40 ACE	SP	P		V			00:00.0
2021	PO6004996509	F	4	40 ACE	SP	CRE		V			00:00.0
2021	PO6005896535	F	4	40 ACE	SP	CRE		V			00:00.0
2021	PO4414185285	F	4	40 BRO	SP	A		V			00:00.0
2021	PO6098696899	F	4	40 ACE	SP	CRE		V			00:00.0
2021	PO6112596926	F	4	40 ACE	SP	P		V			00:00.0
2021	PO4398685264	F	4	40 BRO	SP	CRE	ED,HH,ID,MD	VX		RP1	00:00.0
2021	PO4452485517	LGE	4	35 ACE	SP	A	ED	VX		PX	00:00.0
2021	PO4468085703	LGE	4	35 ACE	SP	CRE	ED	VX		RP2	00:00.0
2021	PO4396185325	F	4	40 BRO	SP	A		VX		RP1	00:00.0
2021	PO4420685282	F	4	40 BRO	SP	CRE	ED,ID,RB	VX		RP1	00:00.0
2021	PO4448285391	LGE	4	35 ACE	SP	CRE	ED	VX		PX	00:00.0
2021	PO4421585599	LGE	4	40 BRO	SP	A	RB	VX		RP2	00:00.0
2021	PO0003788474	KU	4	40 UNK	SP	P	ED,HH,ID	X		PX	00:00.0
2021	PO5246810764	KU	6	30 XXX	SP	CRE	ED,ID	X		RP3	00:00.0
2021	PO9955592395	KU	4	40 UNK	SP	CRE	ED,ID,RB	X		RP1	00:00.0
2021	PO8333201791	KU	5	35 XXX	SP	CRE	ED,EP,ID,MD,RB,SRC	X		RP2	00:00.0
2021	PO4395085254	LGE	4	35 BRO	SP	P	ED,ID,RB	X		RP1	00:00.0
2021	PO4395585243	LGE	4	35 BRO	SP	P	ED,ID,RB	X		RP1	00:00.0
2021	PO7892107693	KU	4	40 BRN	SP	CRE	ED,EP,ID,SRC	X		RP1	00:00.0
2021		1778572426	LGE	4	35 ACE	SP	CCA	V			00:00.0
2021	PO3549216500	KU	4	40 BRN	SP	CRE	ID,RB	BX		RP1	00:00.0
2021	PO9130889855	KU	4	40 XXX	SP	CRE	ED,HH,ID,IP	TX		RR	00:00.0
2021	PO9366390973	KU	4	40 UNK	SP	CRE	ED,HH,ID,IP	TX		RR	00:00.0
2021	PO9888390926	KU	4	40 UNK	SP	CRE	ED,HH,ID,RB	X		PX	00:00.0
2021	PO9891091104	KU	4	40 UNK	SP	CRE	ED,ID	X		RP1	00:00.0
2021	PO9668693233	KU	4	40 UNK	SP	CRE	ED,HH,ID	X		PX	00:00.0
2021	PO9242390946	KU	4	40 UNK	SP	CRE	ED,HH,ID	BX		PX	00:00.0
2021	PO4465686079	LGE	3	45 ACE	SP	P	ED,ID	TX		RR	00:00.0
2021	PO2088224205	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX		RR	00:00.0
2021	PO2094023920	KU	5	35 BRN	SP	CRE	ED,ID,IP	TX		RR	00:00.0
2021	PO9809594320	KU	3	45 XXX	SP	CRE	ED,ID,IP,MD,SRC	TX		RR	00:00.0
2021	PO9792594358	KU	3	45 XXX	SP	CRE	ED,EP,HH,ID,RB	BX		PX	00:00.0
2021	PO9480995197	KU	3	45 XXX	SP	CRE	ED,HH,ID,IP	BX		RP3	00:00.0
2021	PO4394585296	LGE	4	30 BRO	SP	A	ED,ID,RB	X		RP1	00:00.0
2021	PO4462185708	LGE	4	40 ACE	SP	A		VX		RP1	00:00.0
2021	PO4493385726	LGE	4	40 ACE	SP	CRE	ED	VX		RP1	00:00.0
2021	PO6157001932	F	4	45 ACE	SP	CRE	ED,HH,ID,RB	BX		PX	00:00.0
2021	PO4406286124	LGE	4	40 BRO	SP	P	ED,ID,RB	VX		RP1	00:00.0
2021	PO8048110992	KU	3	45 BRN	SP	CRE	ED,HH,ID,IP,RB	BX		PX	00:00.0

2021	PO4466985988	LGE	4	40 ACE	SP	CRE		VX	PX	00:00.0	
2021	PO44668085989	LGE	4	40 ACE	SP	CRE	ED,ID	BX	RR	00:00.0	
2021	PO4468985987	LGE	3	45 ACE	SP	CRE	ED,ID	TX	RR	00:00.0	
2021	PO5956302457	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0	
2021	PO8035010691	KU	3	45 BRN	SP	CRE	ED,HH,ID,IP,RB,SRC	X	PX	00:00.0	
2021		4467186006	LGE	3	45 ACE	SP	CRE	ED,HH,ID	VX	PX	00:00.0
2021	PO4619812101	KU	3	45 XXX	SP	CRE	HH,ID	X	RP3	00:00.0	
2021	PO5956497103	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0	
2021	PO5941097411	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0	
2021	PO3712817251	KU	2	60 XXX	SP	CRE	ID,IP	TX	RR	00:00.0	
2021	PO3707315879	KU	2	65 XXX	SP	CRE	ID,RB	TX	RR	00:00.0	
2021	PO5926500498	KU	4	35 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0	
2021	PO7999410175	KU	3	45 BRN	SP	CRE	ED,ID,IP	X	RP1	00:00.0	
2021	PO7967510336	KU	3	45 BRN	SP	CRE	ED,ID,IP,RB,SRC	X	RP1	00:00.0	
2021	PO4139514153	KU	4	40 XXX	SP	CRE	ID,IP	TX	RR	00:00.0	
2021	PO4152514343	KU	4	40 XXX	SP	CRE	ED,HH,ID	TX	RR	00:00.0	
2021	PO3620319878	KU	3	45 BRN	SP	CRE	ID	BX	PX	00:00.0	
2021	PO9800388419	KU	4	40 UNK	SP	CRE	ED,ID,IP,SRC	TX	RR	00:00.0	
2021	PO9526895748	KU	2	50 XXX	SP	CRE	ED,EP,HH,ID,RB	BX	PX	00:00.0	
2021	PO7964408403	KU	3	45 BRN	SP	CRE	ED,ID,RB,SRC	TX	RR	00:00.0	
2021	PO7980608554	KU	3	45 BRN	SP	CRE	ED,ID,IP	BX	RP3	00:00.0	
2021	PO4434786151	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0	
2021	PO4431686151	LGE	4	40 BRO	SP	A	ED,EP,ID,RB	TX	RR	00:00.0	
2021	PO4408786080	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP,RB	TX	RR	00:00.0	
2021	PO4406686080	LGE	3	45 BRO	SP	A	ED,ID,IP	TX	RR	00:00.0	
2021	PO4433186079	LGE	2	50 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0	
2021	PO4430386042	LGE	4	35 BRO	SP	A	RB	X	RP1	00:00.0	
2021	PO7923908028	KU	3	45 BRN	SP	CRE	ED,ID,IP	TX	RR	00:00.0	
2021	PO4257013450	KU	4	40 XXX	SP	CRE	ID,IP	X	RP3	00:00.0	
2021	PO4251213472	KU	4	40 XXX	SP	CRE	ID,IP	TX	RR	00:00.0	
2021	PO4258913499	KU	4	40 XXX	SP	CRE	ID	TX	RR	00:00.0	
2021	PO7839007243	KU	3	45 BRO	SP	CRE	MD,SRC	TX	RR	00:00.0	
2021	PO6285401924	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0	
2021	PO7822107086	KU	2	50 BRO	SP	CRE	HH,ID,IP,RB	X	PX	00:00.0	
2021	PO3914915337	KU	4	45 XXX	SP	CRE	HH,ID	X	PX	00:00.0	
2021	PO3928815641	KU	4	45 XXX	SP	CRE	HH,ID	TX	RR	00:00.0	
2021	PO3938715361	KU	3	45 XXX	SP	CCA		V		00:00.0	
2021	PO3934915269	KU	2	65 XXX	ST	CRE		V		00:00.0	
2021	PO4453785549	LGE	4	40 ACE	SP	CCA		V		00:00.0	
2021	PO4450085569	LGE	4	40 ACE	SP	CRE		V		00:00.0	
2021	PO4456285538	LGE	3	45 ACE	SP	CCA		V		00:00.0	
2021	PO4405386138	LGE	4	40 BRO	SP	A		V		00:00.0	
2021	PO1694367787	LGE	3	45 ACE	SP	CCA		V		00:00.0	
2021	PO1693967760	LGE	3	45 ACE	SP	CCA		V		00:00.0	
2021	PO9580989487	KU	3	45 BRO	SP	CCA		V		00:00.0	
2021	PO3808215634	KU	2	65 XXX	ST	CRE		V		00:00.0	
2021	PO3790015686	KU	2	60 XXX	ST	CRE		V		00:00.0	
2021	PO9437996207	KU	5	35 XXX	SP	S		V		00:00.0	
2021	PO9887491714	KU	3	45 UNK	SP	CRE		V		00:00.0	
2021	PO4456885812	LGE	3	45 ACE	SP	CCA		V		00:00.0	
2021	PO4455885819	LGE	4	30 ACE	SP	P		V		00:00.0	
2021	PO8044710852	KU	3	45 BRN	SP	CCA		V		00:00.0	
2021	PO8051010994	KU	3	45 BRN	SP	CCA		V		00:00.0	
2021	PO8079810870	KU	6	30 BRN	SP	CCA		V		00:00.0	

2021 PO4454485819	LGE	1	75 ACE	SP	CRE		V	00:00.0
2021 PO4452985809	LGE	1	70 ACE	SP	CRE		V	00:00.0
2021 PO4453585809	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4406986113	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4407186110	LGE	4	30 BRO	SP	A		V	00:00.0
2021 PO4459685588	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO6065402466	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6073902660	F	2	50 ACE	SP	CRE		V	00:00.0
2021 PO6089803021	F	2	55 ACE	SP	CRE		V	00:00.0
2021 PO6084202895	F	2	50 ACE	SP	CRE		V	00:00.0
2021 PO7835107370	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7836507358	KU	3	45 KOP	SP	CCA		V	00:00.0
2021 PO7843507282	KU	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4464885618	LGE	UNK	30 ACE	SP	CRE		V	00:00.0
2021 PO8028809692	KU	3	45 KOP	SP	CCA		V	00:00.0
2021 PO8034509771	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO8046309661	KU	3	50 BRN	SP	CCA		V	00:00.0
2021 PO8074009408	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4453885550	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4453285559	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4454285588	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO9534589655	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4466985539	LGE	UNK	65 ACE	SP	CRE		V	00:00.0
2021 PO9641691071	KU	5	35 KOP	SP	CCA		V	00:00.0
2021 PO9652391214	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4468685551	LGE	UNK	65 ACE	SP	CRE		V	00:00.0
2021 PO4470785566	LGE	UNK	65 ACE	SP	CRE		V	00:00.0
2021 PO5961497277	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4394085242	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4393585249	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4457685763	LGE	3	45 ACE	SP	CCA	ED	V	00:00.0
2021 PO4456085771	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO9570294316	KU	5	35 XXX	SP	CRE		V	00:00.0
2021 PO9562789725	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9544089973	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9523490256	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9505990488	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5912697844	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4425585506	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4393485248	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO5933597300	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4429386150	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4486485676	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7925011287	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4496885752	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4453385585	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO6104202233	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6084402352	F	4	45 ACE	SP	CRE		V	00:00.0
2021 PO6123102127	F	4	50 ACE	SP	CRE		V	00:00.0
2021 PO6136102055	F	4	50 ACE	SP	CRE		V	00:00.0
2021 PO5940496929	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5929397010	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5919097090	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO5908897166	F	4	40 ACE	SP	CRE		V	00:00.0

2021	PO5898497245	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO3750315933	KU	5	35 XXX	SP	CCA	V	00:00.0	
2021	PO4463985579	LGE	UNK	30 ACE	SP	CRE	V	00:00.0	
2021	4460485569-b	LGE	3	50 ACE	SP	CCA	V	00:00.0	
2021	PO4460485569	LGE	3	45 ACE	SP	CCA	V	00:00.0	
2021	4460485569-a	LGE	3	50 ACE	SP	CCA	V	00:00.0	
2021	PO6017102713	KU	3	45 ACE	SP	P	V	00:00.0	
2021	PO6026702666	F	2	50 ACE	SP	CRE	V	00:00.0	
2021	PO6022102562	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO6016402430	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5942102541	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5889997939	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5903097854	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5883597750	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5870197697	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5941496799	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5946296880	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5948896923	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5887697319	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5879297653	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5876197584	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5871697504	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO5847197579	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO4395485224	F	4	40 BRO	SP	CRE	V	00:00.0	
2021	PO4468585612	LGE	4	35 ACE	SP	CCA	V	00:00.0	
2021	PO4469685617	LGE	4	35 ACE	SP	CCA	V	00:00.0	
2021	PO4394785230	F	4	40 BRO	SP	CRE	V	00:00.0	
2021	PO4394885232	F	4	40 BRO	SP	CRE	V	00:00.0	
2021	PO7954808311	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021	PO9471395114	KU	4	40 XXX	SP	S	V	00:00.0	
2021	PO9759892610	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021	PO4474385639	LGE	4	40 ACE	SP	CCA	V	00:00.0	
2021	PO4474485647	LGE	4	40 ACE	SP	CCA	V	00:00.0	
2021	PO4477685645	LGE	4	40 ACE	SP	CCA	V	00:00.0	
2021	PO4477285697	LGE	UNK	40 ACE	SP	CRE	V	00:00.0	
2021	PO4470785666	LGE	4	40 ACE	SP	CCA	V	00:00.0	
2021	PO4470585604	LGE	4	35 ACE	SP	CRE	V	00:00.0	
2021	PO4399385184	F	4	30 BRO	SP	A	V	00:00.0	
2021	PO9497395196	KU	6	30 XXX	SP	S	V	00:00.0	
2021	PO9492595258	KU	6	30 XXX	SP	S	V	00:00.0	
2021	PO4475185715	LGE	UNK	45 ACE	SP	CRE	V	00:00.0	
2021	PO5837697461	F	4	40 ACE	SP	CRE	V	00:00.0	
2021	PO4411586120	LGE	4	40 BRO	SP	CRE	V	00:00.0	
2021	PO3706915807	KU	3	45 XXX	SP	CCA	V	00:00.0	
2021	PO3708716183	KU	2	70 XXX	ST	CRE	V	00:00.0	
2021	PO3711716974	KU	2	60 XXX	ST	CRE	V	00:00.0	
2021	PO4404686150	LGE	2	55 BRO	SP	CRE	V	00:00.0	
2021	PO4405586256	LGE	2	55 BRO	SP	A	V	00:00.0	
2021	PO4407486156	LGE	4	30 BRO	SP	CRE	V	00:00.0	
2021	PO4406986165	LGE	3	45 BRO	SP	CRE	V	00:00.0	
2021	PO4407986170	LGE	3	50 BRO	SP	A	V	00:00.0	
2021	PO4408386173	LGE	4	35 BRO	SP	CRE	V	00:00.0	
2021		4473885717	LGE	1	50 ACE	SP	CCA	V	00:00.0
2021		4473285717	LGE	3	50 ACE	SP	CCA	V	00:00.0

2021 PO4409586105	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4410586113	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO3714017518	KU	2	60 XXX	ST	CRE		V	00:00.0
2021 PO3715417806	KU	1	75 XXX	ST	CCA		V	00:00.0
2021 PO4413886137	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4414086138	LGE	4	40 BRO	SP	A		V	00:00.0
2021 PO4415586139	LGE	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4415186147	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9611294149	KU	4	45 XXX	SP	CCA		V	00:00.0
2021 PO8031204870	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8021804968	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8014205048	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8001905176	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8055304695	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO5369309312	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5340008971	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO5359309402	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5353809363	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5349009380	F	3	45 XXX	SP	CCA		V	00:00.0
2021 PO5343809394	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5327409445	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5319809530	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO5317509444	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5318309475	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5313609317	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8417964424	F	1	50 ACE	SP	CCA		V	00:00.0
2021 PO8435964259	F	1	50 ACE	SP	CCA		V	00:00.0
2021 PO5123485118	LGE	3	50 ACE	SP	P	ED	BD	00:00.0
2021 PO4886184725	LGE	3	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5121285137	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5119385157	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO6022660059	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6022660059-A	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5117185178	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5115485195	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5113685211	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO4511187815	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4509687755	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4509287756	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5111985227	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5110385243	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5108585259	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021 PO4893484729	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5315809137	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO5311809257	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5308309140	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO0971770801	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO0969570703	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO0962170650	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4379385834	LGE	3	40 ACE	SP	CCA		V	00:00.0
2021 PO4377685831	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4376285826	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4375185810	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO0843069944	LGE	4	35 ACE	SP	CCA		V	00:00.0

2021	PO4367485755	LGE	4	30 ACE	SP	P	ED	TD	00:00.0
2021	PO5150184780	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5150384803	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO5150484826	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO5149084835	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021	PO5151184831	LGE	1	50 ACE	SP	CCA	ED,ID	V	00:00.0
2021	PO8316004459	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO8334604530	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5131985011	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5131284980	LGE	3	45 ACE	SP	CCA	ED	BD	00:00.0
2021	PO4366485754	LGE	3	45 ACE	SP	CRE	ED	TD	00:00.0
2021	PO5417509490	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO5425309465	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4364785737	LGE	4	30 ACE	SP	P	ED	TD	00:00.0
2021	PO4364685746	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	4369985699	LGE	4	35 ACE	SP	P	ED	TD	00:00.0
2021	4370485699	LGE	3	45E ACE	SP	CRE	ED,HH	TD	00:00.0
2021	PO4374585413	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021	PO4374185411	LGE	2	55 ACE	SP	CCA	MD	V	00:00.0
2021	PO4375985422	LGE	4	40 ACE	SP	P	ED	TD	00:00.0
2021	PO4375385405	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO0442430567	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0441830232	KU	1	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5105285290	LGE	2	60 ACE	SP	CCA		V	00:00.0
2021	PO4518287807	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4519987816	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4522787862	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4520387837	F	4	40 BRO	SP	P		V	00:00.0
2021	PO4523187850	F	4	40 BRO	SP	P		V	00:00.0
2021	PO4523587838	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4524387843	F	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4540287588	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO5104785286	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO5102385267	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO5100585253	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO0311734085	KU	3	50 ACE	SP	CCA		V	00:00.0
2021	PO0299234414	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0284334813	KU	3	45 ACE	SP	CCA		V	00:00.0
2021	PO0266035300	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO509985235	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5098585238	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO4904284821	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021	PO0256335549	KU	4	40 ACE	SP	CCA		V	00:00.0
2021	PO0243435901	KU	1	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0230136247	KU	1	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO0216736603	KU	2	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4375885398	LGE	5	35 ACE	SP	CRE	ED	BD	00:00.0
2021	PO4375185399	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021	PO4378585437	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021	PO4380185447	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021	PO4381685457	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8182103459	KU	1	60 XXX	SP	S		V	00:00.0
2021	PO8192003212	KU	1	60 XXX	SP	S		V	00:00.0
2021	PO8172303554	KU	1	55 XXX	SP	S		V	00:00.0



2021 PO8159403679	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8149403778	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8142103848	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8134903918	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8126803998	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8116004103	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8131604019	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO8112004142	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8360004487	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8382804451	KU	3	45 XXX	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8381204337	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO8491904572	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8476004450	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8460404646	KU	3	45 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021 PO8441804573	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021 PO8423104501	KU	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021 PO8406104434	KU	5	35 XXX	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8423404245	KU	4	40 XXX	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8436304121	KU	4	40 XXX	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8451303977	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8076804486	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8087604380	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8100204258	KU	1	55 XXX	SP	S		V	00:00.0
2021 PO8102804286	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8109404084	KU	2	50 XXX	SP	S		V	00:00.0
2021 PO4510887795	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4488887890	LGE	4	40 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4884084724	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4487487890	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4486787896	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4486487901	LGE	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5439609540	KU	5	35 XXX	SP	CRE		V	00:00.0
2021 PO5448409483	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5449109504	F	5	35 XXX	SP	CRE		V	00:00.0
2021 PO4883584709	LGE	2	45 BRO	SP	CCA		V	00:00.0
2021 PO5130684950	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO5440709421	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5446609427	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5434409258	F	5	35 XXX	SP	CRE		V	00:00.0
2021 PO5440009217	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5374409296	F	3	45 XXX	SP	P		V	00:00.0
2021 PO4512187826	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4512187823	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4510487809	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0201037019	KU	1	45 ACE	SP	CRE		V	00:00.0
2021 PO0187437371	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4905484832	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4906884845	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5094385181	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4904384850	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5094985161	LGE	4	35 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021 PO0171937793	KU	1	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0165237982	KU	3	50 ACE	SP	CCA		V	00:00.0
2021 PO0158338380	KU	2	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0

2021 PO4535387601	F	4	40 BRO	SP	P		V		00:00.0
2021 PO4538487570	F	4	40 BRO	SP	P		V		00:00.0
2021 PO4540987593	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4540687606	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4541287577	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4541587563	F	4	40 BRO	SP	P		V		00:00.0
2021 PO5096185172	LGE	3	45 ACE	SP	P	ED	TD		00:00.0
2021 PO0151438779	KU	2	45 ACE	SP	CCA		V		00:00.0
2021 PO0144839191	KU	1	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO0138739543b	KU	1	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 POI0138739543a	KU	1	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO0138739543	KU	1	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5095585152	LGE	4	40 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO4540687561	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4539887546	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4539087532	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4538587522	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4538487512	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4521187823	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO2308890645	F	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4532287820	F	4	35 BRO	SP	P		V		00:00.0
2021 PO4541287883	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4529987890	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4539087914	LGE	4	35 BRO	SP	CRE		V		00:00.0
2021 PO4902184898	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO5098185198	LGE	4	40 ACE	SP	P	ED	V		00:00.0
2021 PO5097085195	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO4903984899	LGE	3	45 BRO	SP	A	ID	BD		00:00.0
2021 PO4905284880	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4906984857	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO5153784838	LGE	4	40 ACE	SP	CRE	ID	TD		00:00.0
2021 PO5152184850	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO5151984873	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5151184868	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4359385494	LGE	UNK	80 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO6538596413	F	5	35 ACE	SP	CRE		V		00:00.0
2021 PO6535996340	KU	4	40 ACE	SP	P		V		00:00.0
2021 PO6536396168	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6521896246	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4368285768	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4370685785	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4371885794	LGE	H1	65 ACE	SP	CCA		V		00:00.0
2021 PO5153384860	LGE	4	35 ACE	SP	P	ED,ID	TD		00:00.0
2021 PO5154284867	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO8348404583	KU	4	40 XXX	SP	S		V		00:00.0
2021 PO5397409211	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5446109230	KU	2	40 XXX	SP	CCA		V		00:00.0
2021 PO8658162087	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8639462290	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO8622262427	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO5470209127	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO5459009159	KU	4	40 XXX	SP	CRE	HH,ID,RB	TX	RR	00:00.0
2021 PO5434709015	F	5	35 XXX	SP	CRE		V		00:00.0
2021 PO5413209502	KU	5	35 XXX	SP	CRE		V		00:00.0

2021 PO8605262527	LGE	1	50 ACE	SP	CCA		V			00:00.0
2021 PO5147084915	LGE	4	35 ACE	SP	P		V			00:00.0
2021 PO8588062706	LGE	1	50 ACE	SP	CCA		V			00:00.0
2021 PO8514563430	F	1	50 ACE	SP	CCA		V			00:00.0
2021 PO8494363617	F	1	50 ACE	SP	CCA		V			00:00.0
2021 PO5134884993	LGE	4	35 ACE	SP	P		V			00:00.0
2021 5131985011-a	LGE	3	45 ACE	SP	CRE	ED	TD			00:00.0
2021 PO5306309074	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO5304509012	F	4	40 XXX	SP	P		V			00:00.0
2021 PO5303508986	KU	4	45 XXX	SP	CRE	ID	TD			00:00.0
2021 PO5295209346	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO5298509445	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO5294109520	KU	6	30 XXX	SP	CRE	ID	TD			00:00.0
2021 PO5301309527	F	3	45 XXX	SP	CCA		V			00:00.0
2021 PO5294109557	F	5	35 XXX	SP	CRE		V			00:00.0
2021 PO5293210466	KU	4	35 XXX	SP	CRE	ID, RB	TX		RR	00:00.0
2021 PO5430609066A	KU	4	40 XXX	SP	CRE	ED, ID, SRC	TX		RR	00:00.0
2021 PO5468505312	KU	6	30 XXX	SP	CRE	ID	BD			00:00.0
2021 PO5475005273	KU	6	30 XXX	SP	CRE		V			00:00.0
2021 PO5479005339	KU	6	30 XXX	SP	CRE	ID	TD			00:00.0
2021 PO5482105483	KU	6	30 XXX	SP	CRE	ID	TD			00:00.0
2021 PO5476405493	KU	6	30 XXX	SP	CRE	ID	BD			00:00.0
2021 PO5474905611	KU	5	35 XXX	SP	CRE	HH	BX		RP3	00:00.0
2021 PO5478505646	KU	4	45 XXX	SP	CRE	ID	TD			00:00.0
2021 PO5087109439	KU	2	70 XXX	ST	CRE		V			00:00.0
2021 PO5408008729	KU	6	30 XXX	SP	CRE		V			00:00.0
2021 PO4497987835	LGE	3	45 BRO	SP	CCA		V			00:00.0
2021 PO4496287880	LGE	4	30 BRO	SP	CCA	ED, ID, IP	BD			00:00.0
2021 PO4529787989	F	4	35 BRO	SP	CCA		V			00:00.0
2021 PO4892584732	LGE	4	35 BRO	SP	CRE	ID, IP	BD			00:00.0
2021 PO4893984719	LGE	4	30 BRO	SP	A	ID	BD			00:00.0
2021 PO5106985275	LGE	3	45 ACE	SP	P	ED	BD			00:00.0
2021 PO0330033594	KU	1	40 ACE	SP	CRE		V			00:00.0
2021 PO0338233376	KU	1	50 ACE	SP	CCA		V			00:00.0
2021 PO0349333087	KU	1	40 ACE	SP	CRE		V			00:00.0
2021 PO0359832801	KU	1	40 ACE	SP	CRE		V			00:00.0
2021 PO0371932473	KU	1	55 ACE	SP	CCA		V			00:00.0
2021 PO0384632206	KU	1	50 ACE	SP	CRE		V			00:00.0
2021 PO0399831783	KU	1	40 ACE	SP	CRE		V			00:00.0
2021 PO4527287986	LGE	4	25 BRO	SP	P	ED, ID, IP	BD			00:00.0
2021 PO4912084884	LGE	4	40 BRO	SP	A	ED, ID, IP	TD			00:00.0
2021 PO0438529078	KU	5	35 ACE	SP	CRE	ED, ID, IP	BD			00:00.0
2021 PO0439929235	KU	5	35 ACE	SP	CRE	ED, ID, IP	BD			00:00.0
2021 PO0440429489	KU	1	40 ACE	SP	CRE	ED, ID, IP	BD			00:00.0
2021 PO0440629732	KU	1	40 ACE	SP	CRE	ED, ID, IP	BD			00:00.0
2021 PO4540188036	F	4	35 BRO	SP	P		V			00:00.0
2021 PO7135860781	LGE	4	40 BRO	SP	CCA		V			00:00.0
2021 PO4997684755	LGE	4	35 BRO	SP	CRE	ED, MD, RB	X		RP1	00:00.0
2021 PO5124184760	LGE	3	50 ACE	SP	P	ED	BD			00:00.0
2021 PO4865486015	LGE	4	35 ACE	SP	CCA	ED, ID	TX		RR	00:00.0
2021 PO4998784740	LGE	4	40 BRO	SP	CRE	ED, ID, IP	TD			00:00.0
2021 PO5125984751	LGE	3	45 ACE	SP	P		V			00:00.0
2021 PO5125484751	LGE	3	45 ACE	SP	P	ED	BD			00:00.0
2021 PO7884688742	KU	5	35 ACE	SP	CRE	ED, ID, IP	BD			00:00.0

2021 PO7860288716	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5127484749	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO5000584719	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4866986030	LGE	4	35 ACE	SP	P	ED,IP	BD		00:00.0
2021 PO5951654753	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO5059785278	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO5874656522	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5889856751	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO5882256640	F	6	35 BRN	SP	CRE		V		00:00.0
2021 PO5886856315	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5889556103	KU	6	30 BRN	SP	CRE	ED,HH,ID,RB	X	RP1	00:00.0
2021 PO5898056094	F	4	40 KOP	SP	P		V		00:00.0
2021 PO8288582800	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4555587995	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4556087986	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4556587978	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8228083702a	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO8228083702	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4980285234	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8357184213	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO5061185282	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4632909958	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5399907549	F	5	35 BRN	SP	CCA		V		00:00.0
2021 PO5410607538	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO5410907641	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO5404307643	F	5	35 UNK	SP	CCA		V		00:00.0
2021 PO5427508024	F	4	40 UNK	SP	P		V		00:00.0
2021 PO5430808093	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO5435108184	F	4E	40E UNK	SP	P		V		00:00.0
2021 PO5347607449	F	4	40 UNK	SP	CRE	ED,HH,ID	BX	RP2	00:00.0
2021 PO5438508255	F	4	40 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021 PO5441308313	F	4	40 UNK	SP	P		V		00:00.0
2021 PO5452108243	F	5E	35E UNK	SP	CRE		V		00:00.0
2021 PO5447908139	F	5E	35E UNK	SP	CRE		V		00:00.0
2021 PO5444508053	F	5E	35E UNK	SP	CRE		V		00:00.0
2021 PO5441207972	F	4	40 KOP	SP	P		V		00:00.0
2021 PO4447485915	LGE	4H	50 BRO	SP	CRE		V		00:00.0
2021 PO4638009950	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4631809845	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4447085918	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO5972255143	KU	4	40 OTH	SP	CRE	ED,HH,ID,RB	X	RP1	00:00.0
2021 PO5966655293	KU	4	40 OTH	SP	CRE	ID	BD		00:00.0
2021 PO5960255460	KU	4	40 OTH	SP	CRE	ID	BD		00:00.0
2021 PO7807780625	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4447685933	LGE	3	50 BRO	SP	P	ED,EP,ID,IP,MD	BD		00:00.0
2021 PO1611471791	LGE	2	50 BRO	SP	CCA		V		00:00.0
2021 PO1615671786	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4448085936	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO1623071779	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4446685942	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021 PO4445985967	LGE	3	45 BRO	SP	A	ED,ID	BD		00:00.0
2021 PO4446185966	LGE	3	45 BRO	SP	P	ED,ID	BD		00:00.0
2021 PO5957154876	F	4	45 OTH	SP	P		V		00:00.0
2021 PO5953054955	F	4	45 KOP	SP	P		V		00:00.0

2021 PO5941755129	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO5947055048	F	4	40 SWP	SP	A		V	00:00.0
2021 PO5128984743	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5415706921	F	5	35 UNK	SP	CRE		V	00:00.0
2021 PO5424307092	F	5	35 UNK	SP	CCA		V	00:00.0
2021 PO5431907046	F	5	35E UNK	SP	P		V	00:00.0
2021 PO5434807084	F	4	40 UNK	SP	P		V	00:00.0
2021 PO5425807143	F	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5407207084	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5412507174	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5410107222	F	4	40 UNK	SP	P		V	00:00.0
2021 PO5416607361	F	3	45 UNK	SP	CCA		V	00:00.0
2021 PO5412507262	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5419807207	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5395707462	F	4	45 UNK	SP	CCA		V	00:00.0
2021 PO5388307199	F	5E	35E UNK	SP	CRE		V	00:00.0
2021 PO5392607293	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5348707471	F	4	45E UNK	SP	CRE		V	00:00.0
2021 PO5390107223	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO5383507380	F	4	45 UNK	SP	P		V	00:00.0
2021 PO4999784745	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5001384710	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO1867470397	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1842870716	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO1849070799	KU	6	30 BRO	SP	CCA	ED,MD,SRS	T	00:00.0
2021 PO5002684700	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5002584673	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5060985432	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO5002684693	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5002484655	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO5922855274	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021 PO5935555227	F	4	45 KOP	SP	P		V	00:00.0
2021 PO4864185975	LGE	4	35 ACE	SP	CRE	ED,IP	TD	00:00.0
2021 PO4863785976	LGE	4	35 ACE	SP	CRE	ED,ID	BX RR	00:00.0
2021 1603900787-a	LGE	3	20 ACE	AL	CRE		V	00:00.0
2021 1605001126-a	LGE	3	20 ACE	AL	CRE		V	00:00.0
2021 PO4451288893	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO1600701215	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO1605001126	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4450788871	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4450788870	F	5	45 ACE	SP	CCA		V	00:00.0
2021 PO1605900773	LGE	4	40 ACE	SP	P	ED	BD	00:00.0
2021 PO1603900787	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5990554656	KU	2	45 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO2331958497	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2359058489	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2383058481	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4461788639	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO8032286736	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5022485048	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5057485349	LGE	4	40 ACE	SP	CRE	ED	BD	00:00.0
2021 PO5058085363	LGE	4	40 ACE	DF	CRE	ED	TD	00:00.0
2021 PO5025984982	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7992088440	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0

2021	PO7997588229	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO8003588028	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5058585375	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021	PO8006187874	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO8012187777	KU	4	40 ACE	SP	CCA		V		00:00.0
2021	PO5029184976	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5060185373	LGE	H3	45 ACE	SP	CCA	ID	BD		00:00.0
2021	PO5062085379	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4866086091	LGE	1	45E ACE	SP	CCA		V		00:00.0
2021	PO5125984824	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021	PO4776813742	KU	2	60 XXX	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021	PO4711714099	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO4694114333	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4660514175	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4663414254	F	4	40 XXX	SP	P		V		00:00.0
2021	PO4661314139	KU	3	45 XXX	SP	CRE	ID,IP	TX	RR	00:00.0
2021	PO4634714306	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4639314331	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4635714234	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4625114275	KU	4	45 XXX	SP	CCA		V		00:00.0
2021	PO4608014335	KU	4	45 XXX	SP	CCA	ED	T		00:00.0
2021	PO4612114903	KU	2	50 XXX	SP	CCA		V		00:00.0
2021	PO4611014418	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4602114620	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4594714382	KU	3	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5064785323	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021	PO8087985909	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7401664459	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO7400264411	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021	PO8065885819	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4545687957	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021	PO4546487962	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021	PO4547387968	LGE	3	45 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021	PO4548287973	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4549187979	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO5063485352	LGE	4	25 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO5023285064	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO5064085356	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021	PO5033084969	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5985454796	KU	4	40 OTH	SP	CRE	ED,HH,ID,RB	X	RP1	00:00.0
2021	PO7797281119	KU	4	45 ACE	SP	CRE	ED,HH,ID,RB	X	PX	00:00.0
2021	PO4463988548	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021	PO7776680945	KU	1	90 ACE	SP	CRE		V		00:00.0
2021	PO4464188552	LGE	4	30 ACE	SP	CCA	ED	BD		00:00.0
2021	PO5971554832	KU	3	40 OTH	SP	CRE		V		00:00.0
2021	PO77758780786	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO7771780729	KU	6	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO5981854893	KU	4	45 OTH	SP	CRE	ED,HH,ID,RB	X	RP1	00:00.0
2021	PO5976555032	KU	4	45 BRN	SP	CRE	ID	BD		00:00.0
2021	PO4461888586	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7775780620	KU	6	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO7781480538	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4462188577	LGE	4	30 ACE	SP	CRE	ED	BD		00:00.0
2021	PO5437007866	F	4	40 KOP	SP	P		V		00:00.0

2021 PO5433607783	F	4	40 KOP	SP	P		V	00:00.0	
2021 PO5428607657	F	4	40 OTH	SP	P		V	00:00.0	
2021 PO5961254798	F	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO5962754766	F	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO5970954476	F	4	40 OTH	SP	A		V	00:00.0	
2021 PO5970554404	F	4	40 OTH	SP	A		V	00:00.0	
2021 PO5969854342	F	4	40 OTH	SP	P		V	00:00.0	
2021 PO5968254267	F	4	40 OTH	SP	P		V	00:00.0	
2021 PO5966154199	F	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4863786015	LGE	4	30 ACE	SP	P	ED,ID	X	PX	00:00.0
2021 PO5756173028	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021 PO7934888787	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4862886005	LGE	3	45 ACE	SP	A	ED,IP	BD		00:00.0
2021 PO5990554656A	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4863085976	LGE	4	30 ACE	SP	P		V		00:00.0
2021 PO4862485961	LGE	4	35 ACE	SP	A	ED	V		00:00.0
2021 PO4522112015	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO4468188548	LGE	4	40 ACE	SP	CCA	ED	BD		00:00.0
2021 PO4509812074	KU	3	45 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4513412172	KU	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO4466788540	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO7819581282	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4466688546	LGE	4	30 ACE	SP	CRE	ED	BD		00:00.0
2021 PO7845881072	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7818281166	KU	5	35 ACE	SP	CCA		V		00:00.0
2021 PO2258558517	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO4447185915	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4595614836	KU	6	30 XXX	SP	CCA		V		00:00.0
2021 PO4591614922	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4583614742	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4579314607	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4574314458	KU	3	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4558914530	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO4563415201	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO7910088765	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO3838717407	KU	3	50 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3860017298	KU	4	45 XXX	SP	S	ED,SRC	T		00:00.0
2021 PO3865917423	KU	6	30 XXX	SP	S		V		00:00.0
2021 PO3869017499	KU	6	30 XXX	SP	S	ED,SRC	T		00:00.0
2021 PO3884017527	KU	5	35 XXX	SP	S		V		00:00.0
2021 PO3893617684	KU	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO3777518159	KU	3	50 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO5124984814	LGE	3	45 ACE	SP	P	ED	BD		00:00.0
2021 PO4996284778	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5955355588	KU	4	40 OTH	SP	CRE	ID	BD		00:00.0
2021 PO5985355757	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO1580172083	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO1572072106	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO1574271961	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021 PO4448185977	F	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4448385992	F	2	55 BRO	SP	CCA		V		00:00.0
2021 PO4448586007	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4448686019	F	3	45 BRO	SP	CRE		V		00:00.0
2021 PO4448085993	LGE	3	45 BRO	SP	P	ED,ID	TD		00:00.0

2021 PO4449386018	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4555487970	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO5125084799	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4995284765	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5123984778	LGE	3	45 ACE	SP	P	ED	BD	00:00.0
2021 PO5064285387	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5783774055	LGE	4	35 ACE	SP	P	ED	BD	00:00.0
2021 PO5066985398	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4865086116	LGE	3	45 ACE	SP	A	ED,IP	BD	00:00.0
2021 PO5067285394	LGE	4	25 ACE	SP	CCA		V	00:00.0
2021 PO4990084766	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4992484777	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4979285238	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO5061085273	LGE	4	30 ACE	SP	P	ED	BD	00:00.0
2021 PO2464582912	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO8373785675	KU	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO8383785536	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5403033421	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5398933314	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5400533359	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO8941452345	ODP	6	30 BRN	SP	S		V	00:00.0
2021 PO8927552348	ODP	4	40 BRN	SP	CRE	ED,ID,IP,SR	TD	00:00.0
2021 PO8914352217	ODP	3	50 BRN	SP	S		V	00:00.0
2021 PO8909652132	ODP	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8967255399	ODP	5	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8971954877	ODP	4	45 BRN	SP	S		V	00:00.0
2021 PO8944254932	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8943055025	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8938454733	ODP	5	35 BRN	SP	CRE		V	00:00.0
2021 PO8928754809	ODP	6	30 BRN	SP	CRE		V	00:00.0
2021 PO8929654706	F	5	35 BRN	SP	P		V	00:00.0
2021 PO4571788174	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4571688162	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4572388163	LGE	4	30 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4571288115	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO8361585584	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO7398777821	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO8334085349	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8457187421	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4473287893	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO7404277853	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5349933997	KU	4	40 BRO	SP	CRE	ID	BX	00:00.0
2021 PO8354985420	KU	5	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5332433404	KU	5	35 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4474287898	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PV4571188104	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4571688104	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4452288343	F	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4474787901	LGE	1	60 BRO	SP	CCA		V	00:00.0
2021 PO8459287637	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4434988298	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4453588350	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4550688106	LGE	5	30 ACE	SP	CCA		V	00:00.0
2021 PO4559788092	LGE	1	50 ACE	SP	CCA		V	00:00.0



2021 PO5431232921	KU	5	35 BRO	SP	CRE	ED,ID,RB	BX	RP2	00:00.0
2021 PO4463788086	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4034386620	LGE	3	45 ACE	SP	P	ED	TD		00:00.0
2021 PO8450686799	F	4	40 ACE	SP	P		V		00:00.0
2021 PO5415432742	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO5433832749	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO4571988194	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO4572588194	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4463688090	LGE	4	40 BRO	SP	P	ED,ID,IP	BD		00:00.0
2021 PO8452787005	F	4	40 ACE	SP	P		V		00:00.0
2021 PO4464088076	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4571888184	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4572488183	LGE	4	30 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4475487906	LGE	3	45 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4023686653	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4476387911	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO0722952353	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO0707552272A	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO0688052180	KU	3	45 UNK	SP	CRE	ID	TD		00:00.0
2021 PO0737552259	F	3	45 UNK	SP	P		V		00:00.0
2021 PO5341032778	KU	4	40 UNK	SP	CRE	ED	BD		00:00.0
2021 PO5342432551	KU	6	30 UNK	SP	CCA		V		00:00.0
2021 PO4557488159	LGE	4	45 ACE	SP	CRE	ED,ID,RB	X	RR	00:00.0
2021 PO2942688922	KU	4	40 BRO	SP	A	ED,IP,SRS	TD		00:00.0
2021 PO8341885560	KU	5	35 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO8461887906	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4445588338	LGE	4	30 BRO	SP	A	ED,ID	BD		00:00.0
2021 PO4458788350	F	3	45 BRO	SP	CRE		V		00:00.0
2021 PO4449088337	F	1	55 BRO	SP	CCA		V		00:00.0
2021 PO4450588340	F	1	50 BRO	SP	CCA		V		00:00.0
2021 PO4454988346	F	3	45 BRO	SP	CRE		V		00:00.0
2021 PO4456288348	F	3	45 BRO	SP	P		V		00:00.0
2021 PO4556988155	LGE	4	40 ACE	SP	CCA	ED,ID	TD		00:00.0
2021 PO4556588152	LGE	4	45 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4477187915	LGE	2	60 BRO	SP	CCA		V		00:00.0
2021 PO2928788190	KU	6	30 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO2935588607	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO2939088766	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4478587923	LGE	2	55 BRO	SP	CCA		V		00:00.0
2021 PO8448087917	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8429087929	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO8306985429	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO5332132550	KU	5	35 UNK	SP	CRE	ED	BD		00:00.0
2021 PO5300332476	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO8078872234	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO8085172501	F	6	30 XXX	SP	P		V		00:00.0
2021 PO8150773640	F	4	45 XXX	SP	P		V		00:00.0
2021 PO8067072428	ODP	6	30 XXX	SP	CCA		V		00:00.0
2021 PO8070672578	ODP	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO8106172864	ODP	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO8104873261	ODP	4	45 XXX	SP	CCA		V		00:00.0
2021 PO8076773285	ODP	4	45 XXX	SP	CCA		V		00:00.0
2021 PO8161474023	ODP	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO8163274474	ODP	4	45 XXX	SP	CCA		V		00:00.0

2021 PO8145574502	ODP	4	45 XXX	SP	CCA		V		00:00.0
2021 PO8142175002	ODP	4	45 XXX	SP	CCA		V		00:00.0
2021 PO8180475237	ODP	4	45 XXX	SP	CCA		V		00:00.0
2021 PO4555988148	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5307632741	KU	6	30 UNK	SP	CRE	ED	BD		00:00.0
2021 PO4024486637	LGE	3	45 ACE	SP	P	ED	TD		00:00.0
2021 PO2899988336	KU	4	30 BRO	SP	CRE	ED,IP,SRS	TD		00:00.0
2021 PO5221512818	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5241912464	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO5253012482	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5282312362	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5281312209	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4469388315	LGE	2	60 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4069517217	KU	7	30 BRN	SP	CCA		T		00:00.0
2021 PO4037916430	KU	3	45 BRN	SP	CCA		T		00:00.0
2021 PO4083286732	LGE	2	60 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4077086722	LGE	UNK	60 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4080886728	LGE	4	40 ACE	SP	CRE	ED	BD		00:00.0
2021 PO4081086728	LGE	3	50 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO4469488298	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO7924979057	LGE	1	60 ACE	SP	CCA		V		00:00.0
2021 PO4079186725	LGE	2	60 ACE	SP	CCA		V		00:00.0
2021 PO4051816617	KU	2	45 BRN	SP	CCA		T		00:00.0
2021 PO4042816539	KU	4	45 BRN	SP	P	ED,ID,IP	TD		00:00.0
2021 PO4048116626	KU	3	45 BRN	SP	CCA		T		00:00.0
2021 PO4469388298	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4077386715	LGE	4	40 ACE	SP	P	ED,IP	BX	RR	00:00.0
2021 PO4469988293	LGE	2	60 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4469688304	LGE	2	60 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4470888236	LGE	2	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4470788249	LGE	2	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4075286703	LGE	4	35 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4470688262	LGE	2	55 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4470488275	LGE	1	55 ACE	SP	CCA		V		00:00.0
2021 PO4020017535	KU	3	45 BRN	SP	CCA		T		00:00.0
2021 PO4471088213	LGE	1	55 ACE	SP	A	ED,ID	BD		00:00.0
2021 PO4471288191	LGE	1	60 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4470888186	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO4471388179	LGE	1	55 ACE	SP	CRE		V		00:00.0
2021 PO4471488169	LGE	1	60 ACE	SP	CRE		V		00:00.0
2021 PO4023417582	KU	3	40 BRN	SP	P	ED,HH,ID	BX	RP2	00:00.0
2021 PO4030317683	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4462188025	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021 PO5048125043	KU	5	35 BRO	SP	CRE		T		00:00.0
2021 PO5048525012	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0594151355	KU	4	40 BRN	SP	CRE		T		00:00.0
2021 PO0688451460	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO0586951745	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO0750351252	KU	4	40 UNK	SP	CRE		V		00:00.0
2021 PO0819152899	KU	4	40 INP	SP	CRE		V		00:00.0
2021 PO0805652482	F	4	40 INP	SP	CRE		V		00:00.0
2021 PO0800852373	F	4	40 INP	SP	CRE		V		00:00.0
2021 PO4461088018	LGE	3	50 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO2732189220	KU	4	45 BRO	SP	CCA		V		00:00.0

2021 PO2724488875	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO2717488557	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO5034025142	KU	4	40 BRO	SP	CRE		T	00:00.0
2021 PO5047425141	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5045725286	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5043725361	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5022525318	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4456588102	LGE	4	35 BRO	SP	A	ED,ID	BD	00:00.0
2021 PO4468888282	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4467688279	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4998025123	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4997825169	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4467788279	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4075186718	LGE	2	75 ACE	SP	CRE	ED	BD	00:00.0
2021 PO4458988051	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4458188060	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4452888109	LGE	4	30 BRO	SP	P		V	00:00.0
2021 PO4458888116	LGE	3	45 BRO	SP	CRE		V	00:00.0
2021 PO4456388106	LGE	4	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4458088110	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4458688093	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4458888082	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4459088072	LGE	4	30 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4457688084	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4458488101	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4036717345	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4041917525	KU	3	45 BRN	SP	CRE		BD	00:00.0
2021 PO4034517412	KU	5	45 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4468088264	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4468288250	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO4468388243	F	4	35 ACE	SP	CRE		V	00:00.0
2021 PO8480384882	KU	4	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8468784824	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5008025178	KU	4	40 BRO	SP	CRE		T	00:00.0
2021 PO4047886687	LGE	3	50 ACE	SP	P	ED	BD	00:00.0
2021 PO4463188032	LGE	3	50 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4998525286	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4996725280	KU	3	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO2703787986	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2709188229	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8451984738	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8440884681	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4466588282	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4969825254	KU	2	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4971325105	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4465788264	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4465588276	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4036586679	LGE	3	55E ACE	SP	P	ED	BD	00:00.0
2021 PO4035686678	LGE	3	60 ACE	SP	P	ED	BD	00:00.0
2021 PO8427984282	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO2861189208	KU	5	30 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2864589137	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO2742189612	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO5007125599	KU	5	35 BRO	SP	CRE	ED,ID	BX	00:00.0

2021 PO4466188277	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4470888285	LGE	4	25 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4472488279	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4448287947	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO8463884137	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8440984563	KU	5	35 ACE	SP	CCA		V	00:00.0
2021 PO8418484567	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8407884513	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO8416784410	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8232661158B	ODP	5	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8232661158A	ODP	5	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8246861716A	ODP	2	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8246861716	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8232661158	ODP	4	50 BRN	SP	CRE		V	00:00.0
2021 PO8971961098	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8958760881	ODP	5	35 BRN	SP	CRE		B	00:00.0
2021 PO8932960466	ODP	5	35 BRN	SP	CRE	ED,EP	BX	RP2 00:00.0
2021 PO4472888263	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4446087943	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4030886669	LGE	3	65E ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4444587943	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4441187944	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO8412984925	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1 00:00.0
2021 PO8458385162	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4462288104	LGE	4	35 BRO	SP	P	ED,EP,ID	BD	00:00.0
2021 PO4461888113	LGE	4	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4462088109	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4451288127	LGE	4	30 BRO	SP	P		V	00:00.0
2021 PO4027686658	LGE	3	50E ACE	SP	A	ED	BD	00:00.0
2021 PO4492888279	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4471287881	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4472087886	LGE	2	60 BRO	SP	A	ID	BD	00:00.0
2021 PO8386286102	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0801451598	KU	6	30 INP	SP	CRE	ID	TD	00:00.0
2021 PO0796351539	KU	6	30 INP	SP	CRE	ID	TD	00:00.0
2021 PO5351833058	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5357833210	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO8400585923	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4492888268	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4472687889	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO4035786681	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO8414985752	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4042286689	LGE	4	45E ACE	SP	A	ED	TD	00:00.0
2021 PO8422285605	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4492988294	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4493088306	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO2819189048	KU	4	40 BRO	SP	CRE	ED,IP,SRS	TD	00:00.0
2021 PO4493488348	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO8430285466	F	5	35 ACE	SP	CCA		V	00:00.0
2021 PO4044286697	LGE	3	50 ACE	SP	CRE	ED,IP	BD	00:00.0
2021 PO4491088324	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO9586856224	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9626262799	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9637162813	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0

2021	PO9456759015	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021	PO9458259112	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO9455159050	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO9436759200	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO9435259063	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO9451458867	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO9436859005	KU	2	55 BRO	SP	CCA		V	00:00.0
2021	PO9432958817	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO9418759090	KU	4	45 UNK	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021	PO4669702771	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4651003140	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4602503205	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4632203047	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4628703422	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4621503105	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4609603169	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4616703485	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4642903362	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4658703314	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4656502827	F	3	50 BRN	SP	CRE		V	00:00.0
2021	PO4644202982	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO9586756466	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO9592456508	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO9605362834A	KU	3	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9605362834	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9586659383	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO9607759542	F	2	55 OTH	SP	CCA		V	00:00.0
2021	PO9572959145	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9585362820	KU	5	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9419559148	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO9423159028	KU	2	55 BRO	SP	CCA		V	00:00.0
2021	PO9415059282	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9607656564	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO9583562845	KU	3	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9583562868	KU	3	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9583562890	KU	2	55 BRO	SP	CCA		V	00:00.0
2021	PO9410359177	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO9407059221	KU	2	50 BRO	SP	CCA		V	00:00.0
2021	PO9417959319	KU	4	40 UNK	SP	CRE		V	00:00.0
2021	PO9405659083	KU	6	30 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO9622659690	F	2	45 OTH	SP	P		V	00:00.0
2021	PO9644959906	KU	4	45 OTH	SP	CCA		V	00:00.0
2021	PO9661560036	KU	4	45 OTH	SP	CCA		V	00:00.0
2021	PO9662860094	KU	5	35 OTH	SP	CRE		V	00:00.0
2021	PO9403258886	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO9397659002	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9387559122	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO4797589427	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4954789183	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4945189308	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO4952789186	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4950689191	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021	PO4948789204	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4793489432	F	4	40 ACE	SP	CRE		V	00:00.0

2021	PO4793589421	F	4	30 ACE	SP	CRE		V		00:00.0
2021	PO4798789437	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4800189445	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4799589456	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4798689502	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4794389421	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX	RP1	00:00.0
2021	PO4794689440	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX	RP1	00:00.0
2021	PO4797489458	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX	RP1	00:00.0
2021	PO4798689520	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4774089269	LGE	4	35 ACE	SP	P		V		00:00.0
2021	PO4779789289	LGE	4	35 ACE	ST	CCA		V		00:00.0
2021	PO4773389342	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021	PO4776089283	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4775689319	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4798289537	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4794389517	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4774989331	F	4	40 ACE	SP	P		V		00:00.0
2021	PO4793589509	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4954689164	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021	PO4952989191	LGE	4	30 BRO	SP	A		V		00:00.0
2021	PO4949089207	LGE	4	30 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4948189216	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4945089228	LGE	3	45 BRO	SP	A	ED	TD		00:00.0
2021	PO4942989233	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4945589246	LGE	4	35 BRO	SP	A	ED,HH,ID,RB	X	RP1	00:00.0
2021	PO4945189266	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4941689253	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4942589278	LGE	3	50 BRO	SP	A	ED	TD		00:00.0
2021	PO4937689513	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4940189391	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4794689533	F	4	40 ACE	SP	CRE	ED,ID	V		00:00.0
2021	PO4795789552	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4801089549	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4800289553	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4941289313	LGE	H2	60 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4941889298	LGE	2	55 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4801389574	F	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4799489566	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4797689554	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4793789547	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4791889541	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4772389203	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4940889294	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021	PO4939989345	LGE	1	60 BRO	SP	CCA		V		00:00.0
2021	PO4940089347	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4939489360	LGE	3	50 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4939389365	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021	PO4938089398	LGE	3	45 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4938689382	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO4771089195	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4938889399	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4769089196	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4773104712	LGE	4	35 ACE	SP	CCA		V		00:00.0
2021	PO4769589190	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0

2021 PO4775889277	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4775689269	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4940189369	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4941589363	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4943589372	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4943289381	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4774389326	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4776889285	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4776089313	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4779989210	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4778589301	F	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4776989300	LGE	2	60 ACE	SP	CCA		V	00:00.0
2021 PO4937689410	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4936989429	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4938289415	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4936989407	LGE	4	30 BRO	SP	CRE	ED	TD	00:00.0
2021 PO4937889432	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4936289448	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4935889459	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4935489472	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4774089346	F	4	35 ACE	SP	P		V	00:00.0
2021 PO4776189311	LGE	4	40 ACE	SP	P		V	00:00.0
2021 PO4774989316	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4773389359	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4772989337	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4773689322	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4934889487	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4936189474	LGE	4	30 BRO	SP	CRE	ED,HH,ID,IP,RB	X	RP1 00:00.0
2021 PO4933889483	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4936789508	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4936289502	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO0238230489	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO0247630248	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO0270630549	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO0318630307	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6328512196	ODP	5	35 UNK	SP	CRE	ED,ID,SRG	TD	00:00.0
2021 PO6595529101	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6330411876	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6331511684	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6340411495	F	5	40 BRN	SP	P		V	00:00.0
2021 PO6358211382	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6238616656	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6217116657	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO6225417255	ODP	5	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6182917486	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6210717598	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6186017587	ODP	5	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6194917887	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6209417905A	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6642527477	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO0096731213	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO0145931393	ODP	6	30 XXX	SP	S		V	00:00.0
2021 PO0142731244	ODP	5	45 XXX	SP	S		V	00:00.0
2021 PO0123631004	ODP	4	45 XXX	SP	CRE		V	00:00.0

2021 PO0109431114	ODP	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO0115130757	ODP	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO0111330860	ODP	6	30 XXX	SP	CRE	ED,ID,IP,MD	TD		00:00.0
2021 PO0137830721	ODP	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021 PO0149230883	ODP	5	35 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO0185530818	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO0169230591	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO0196430412	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO0217230287	ODP	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD		00:00.0
2021 PO6210617239	ODP	4	40 BRN	SP	CRE	RB	X	PX	00:00.0
2021 PO6636727426	ODP	6	30 BRO	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO6627627492	ODP	6	30 BRO	SP	CRE	ID	BD		00:00.0
2021 PO6625027623	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO6625027623A	ODP	5	35 BRO	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO6606327960	ODP	4	40 BRO	SP	CCA		V		00:00.0
2021 PO6209417905	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6221117924	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6613728588	ODP	4	40 BRO	SP	CCA		V		00:00.0
2021 PO6599828801	ODP	4	40 BRO	SP	CCA		V		00:00.0
2021 PO6585027302	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO6585027302A	ODP	5	35 SWP	SP	P	ED,ID	TD		00:00.0
2021 PO6246217952	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6611727295	ODP	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO6634227173	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO6199518027	ODP	5	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6213018038	ODP	4	40 BRN	SP	P	ED,ID	TD		00:00.0
2021 PO9676561644	KU	4	40 OTH	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO4638604510	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4663204349	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO4608104692	KU	3	40 BRN	SP	CRE		V		00:00.0
2021 PO4579604819	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4617904644	F	4	45 BRN	SP	CRE		V		00:00.0
2021 PO4616104655	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4644704470	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4564304696	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4654704407	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4604404707	F	4	45 BRN	SP	CRE		V		00:00.0
2021 PO4591704765	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4672704287	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO4554304597	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4574304795	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO4627704580	F	4	45 BRN	SP	CRE		V		00:00.0
2021 PO9672661993	KU	4	40 OTH	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO9657562613	KU	6	30 OTH	SP	CRE	ID	BD		00:00.0
2021 PO9654762231	KU	4	45 OTH	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO9660362566	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9656962726	KU	6	30 OTH	UN	CRE		V		00:00.0
2021 PO9668362263	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9647863770A	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9411860567A	KU	5	30 OTH	SP	CRE	ID	BD		00:00.0
2021 PO9418760460A	F	5	30 OTH	SP	P		V		00:00.0
2021 PO9578563189	KU	4	45 OTH	UN	CRE		V		00:00.0
2021 PO9557363062	KU	3	45 OTH	SP	CCA		V		00:00.0
2021 PO9670163703	KU	4	40 OTH	SP	CRE	ID	BD		00:00.0



2021 PO9647863770	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9440460513	KU	5	35 OTH	SP	CRE		V	00:00.0
2021 PO9436160365	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9564062942	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO9423860518	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021 PO9449660690	KU	5	30 OTH	SP	CRE		V	00:00.0
2021 PO9610563328	KU	4	45 OTH	UN	CRE		V	00:00.0
2021 PO9406060348	F	4	40 OTH	SP	P		V	00:00.0
2021 PO9418760460	F	4	40 OTH	SP	P		V	00:00.0
2021 PO9411860567	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021 PO9545662701	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO4332903861	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4584704410	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4572604323	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4327003851	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9468961562	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO9390460005	F	3	50 OTH	SP	CRE		V	00:00.0
2021 PO9461859686	KU	2	55 OTH	SP	CCA		V	00:00.0
2021 PO4627404208	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0661337282	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4509004492	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4604904551	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4590906006	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4569705911	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4596604493	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4492604382	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX PX	00:00.0
2021 PO4608906094	F	3	30 BRN	SP	CRE		V	00:00.0
2021 PO4549105779	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO6898749442	KU	3	45 UNK	UN	CCA		V	00:00.0
2021 PO4066984312	LGE	4	30 BRO	UN	CRE		V	00:00.0
2021 PO4121184267	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021 PO938246023760237A	KU	2	50 OTH	SP	CCA		V	00:00.0
2021 PO9349460220	KU	1	65 OTH	SP	CCA		V	00:00.0
2021 PO9374160049	F	2	50 OTH	SP	CCA		V	00:00.0
2021 PO8306421699	F	5	35 UNK	SP	CRE		V	00:00.0
2021 PO8323921781	F	5	35 UNK	SP	CRE		V	00:00.0
2021 PO8277322235	ODP	4	40 KOP	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO7238619894a	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7236620052	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7238619894	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8429925351	ODP	4	40 UNK	SP	P		V	00:00.0
2021 PO8602022374	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8601622545	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0409435787A	ODP	5	35 BRN	SP	CCA	ED	TD	00:00.0
2021 PO0423735818	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO6717418208	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6700018368	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6716418369	ODP	5	30 XXX	SP	A	ID,IP	BD	00:00.0
2021 PO0417835855	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0409435787	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8601422306	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8599022246	ODP	4	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO8615122298	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6752717024	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0

2021 PO6741117640	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9325325843	ODP	2	50 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9311625768	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9296725637	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8626322327	ODP	4	45 BRO	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO8649422383	ODP	2	50 BRO	SP	CCA		V	00:00.0
2021 PO8649422382	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8649422381	ODP	2	50 BRO	SP	CCA		V	00:00.0
2021 PO8671322436	ODP	4	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO0404035746	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9311625768A	ODP	4	40 XXX	SP	P	ED,ID	TD	00:00.0
2021 PO9334725564	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8673022361	ODP	4	40 BRO	SP	CRE	HH,ID,SRC	TD	00:00.0
2021 PO8681022460	ODP	3	50 BRO	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO6755717420	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO6769717217	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO6769717217a	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6760216909	ODP	6	30 XXX	SP	CRE		V	00:00.0
2021 PO8682722352	ODP	4	45 BRO	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO8691022490	ODP	6	35 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8886825205	ODP	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6733117254	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6724417433	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6706017519	ODP	5	30 XXX	SP	CCA	ED,ID	TD	00:00.0
2021 PO9361325505	ODP	4	45 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9357525565	ODP	5	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8887224910	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8884325179	ODP	5	35 UNK	SP	CRE	ED,HH,ID	BX	RP1 00:00.0
2021 PO8889524672	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8892324421	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8895224119	ODP	5	40 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8898223865	ODP	5	40 UNK	SP	CRE	ED,HH,ID	BX	PX 00:00.0
2021 PO8900023647	ODP	4	45 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO9358525764	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9325925740	ODP	5	35 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021 PO9376325934	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9372326137	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9361726035	F	4	40 XXX	SP	P		V	00:00.0
2021 PO9360925952	ODP	6	30 XXX	SP	P		V	00:00.0
2021 PO9339825845	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9352125944	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9346925667	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9350325802	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9414826172	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5232522570	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5266822377	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5193522772	ODP	5	35 UNK	SP	CRE		V	00:00.0
2021 PO0276633957	ODP	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0269634094	ODP	2	50 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0285834257	ODP	2	50 BRN	SP	CRE	ID	TD	00:00.0
2021 PO9426026447	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9421126238	ODP	6	30 XXX	SP	CCA		V	00:00.0
2021 PO9434226205	ODP	3	50 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9441626267	ODP	4	45 XXX	SP	S		V	00:00.0

2021 PO9442026095	ODP	4	45 XXX	SP	CRE	ED,ID	BD		00:00:00
2021 PO9465426061	ODP	6	30 XXX	SP	S		V		00:00:00
2021 PO6247919106	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00:00
2021 PO6235318889	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00:00
2021 PO6227418423	F	4	40 BRN	SP	CRE		V		00:00:00
2021 PO6252218762	ODP	6	30 BRN	SP	CRE	ID	BD		00:00:00
2021 PO0297634151	ODP	6	30 BRN	SP	CRE	ID	TD		00:00:00
2021 PO0309234311	ODP	5	35 BRN	SP	CRE	ID	TD		00:00:00
2021 PO0301634364	ODP	2	45 BRN	SP	CRE	ID	BD		00:00:00
2021 PO0293234273	ODP	2	60 BRN	SP	CRE	ID	TD		00:00:00
2021 PO0302234249	ODP	6	30 BRN	SP	CRE	ID	TD		00:00:00
2021 PO0301734119	ODP	4	40 BRN	SP	CRE	ID	TD		00:00:00
2021 PO5250721782	ODP	5	35 UNK	SP	CRE	ID,IP	BD		00:00:00
2021 PO5240521758	ODP	5	35 UNK	SP	CRE		V		00:00:00
2021 PO5217920998	ODP	5	35 UNK	SP	CRE	ED,ID,IP,SR	TD		00:00:00
2021 PO5155220257	ODP	4	45 UNK	SP	P	ED,ID	TD		00:00:00
2021 PO5265319666	ODP	4	40 BRO	SP	CRE	ED,ID,SR	TD		00:00:00
2021 PO9685728757	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00:00
2021 PO5241920071	ODP	4	40 BRO	SP	CRE	ED,ID,SR	TD		00:00:00
2021 PO5223820467	ODP	4	45 BRO	SP	CRE	ED,ID,SR	TD		00:00:00
2021 PO5207320774	ODP	4	45 BRO	SP	CRE	ID	BD		00:00:00
2021 PO5179320747	ODP	4	40 BRO	SP	CRE	ID	BD		00:00:00
2021 PO5178219373	ODP	4	45 BRO	SP	CCA		V		00:00:00
2021 PO9563528333	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00:00
2021 PO9586228521	ODP	4	40 XXX	SP	CRE	ED,ID,MD,SR	TD		00:00:00
2021 PO9613228730	ODP	4	40 XXX	SP	CRE	ED,ID,MD,SR	TD		00:00:00
2021 PO9796929917	ODP	2	45 XXX	SP	S		V		00:00:00
2021 PO7531018602	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00:00
2021 PO7539518573	ODP	6	30 BRN	SP	CRE	ED,ID	TD		00:00:00
2021 PO5060219768	ODP	4	45 BRO	SP	CCA		V		00:00:00
2021 PO5117919798	ODP	4	45 BRO	SP	CCA	ED,ID,SR	TD		00:00:00
2021 PO5126220051	ODP	4	45 BRO	SP	CCA		V		00:00:00
2021 PO5139020755	ODP	4	40 BRO	SP	CCA		V		00:00:00
2021 PO8797625090	ODP	6	30 UNK	SP	CRE	ED,ID,IP,RB,SR	TX	RR	00:00:00
2021 PO7548118627	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00:00
2021 PO7565618575	ODP	6	30 BRN	SP	CRE	ED,ID	TD		00:00:00
2021 PO9772129763	ODP	2	50 XXX	SP	S		V		00:00:00
2021 PO9754129653	ODP	4	45 XXX	SP	S		V		00:00:00
2021 PO5606022637	ODP	5	35 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00:00
2021 PO5573822569	ODP	4	40 BRO	SP	CCA		V		00:00:00
2021 PO5548023362	ODP	4	40 BRO	SP	CCA		V		00:00:00
2021 PO5556722940	ODP	4	40 BRO	SP	CCA		V		00:00:00
2021 PO5534922170	ODP	4	40 BRO	SP	CCA		V		00:00:00
2021 PO5465822019	ODP	5	35 UNK	SP	CRE	ID	BD		00:00:00
2021 PO5463222334	ODP	4	45 UNK	SP	CRE		V		00:00:00
2021 PO5431422445	ODP	4	45 UNK	SP	CRE		V		00:00:00
2021 PO5406621972	ODP	5	35 UNK	SP	CRE	ID,IP	BD		00:00:00
2021 PO5344121988	ODP	5	35 UNK	SP	CRE	ID	BD		00:00:00
2021 PO6227418423a	ODP	3	55 KOP	SP	CRE	ED,ID	TD		00:00:00
2021 PO6216218485	ODP	5	30 BRN	SP	CRE	ED,ID,IP	TD		00:00:00
2021 PO6307719277	ODP	6	30 BRN	SP	CRE	ID	BD		00:00:00
2021 PO6276219245	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00:00
2021 PO9411826062	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00:00
2021 PO9423925986	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00:00

2021 PO0371634771	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0366634691	ODP	6	30 BRN	SP	CCA	ED	TD	00:00.0
2021 PO0361534712	ODP	6	30 BRN	SP	CCA	ED	T	00:00.0
2021 PO0362834666	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0364734635	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0386034851	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0411234961	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0410835066	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0412135232	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0441735178	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0441035027	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0441035027A	ODP	6	30 BRN	SP	CCA	ED	T	00:00.0
2021 PO0535935081	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7627618118	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7591418359	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7595218072	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9793529673	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9819729522	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9787630054	ODP	3	45 XXX	SP	S		V	00:00.0
2021 PO9751729820	ODP	5	35 XXX	SP	S		V	00:00.0
2021 PO9735828874	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9733429539	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9714029426	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9724529221	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9705228939	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO9720728941	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9766028897	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7578418339	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7557918033	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8800524862	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8793724809	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8766324900	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021 PO9286164870	ODP	5	35 OTH	SP	CRE		V	00:00.0
2021 PO9268365048	ODP	4	40 OTH	SP	CRE		V	00:00.0
2021 PO9370564030	ODP	5	35 OTH	SP	CRE		V	00:00.0
2021 PO9357264147	ODP	5	35 OTH	SP	CRE		V	00:00.0
2021 PO9341264312	ODP	5	35 OTH	SP	CRE		V	00:00.0
2021 PO9247065263	ODP	4	40 OTH	SP	CRE		V	00:00.0
2021 PO9314064589	ODP	5	35 OTH	SP	CRE		V	00:00.0
2021 PO8685125940	ODP	6	30 UNK	SP	CRE		V	00:00.0
2021 PO6502218763	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO8686525882	ODP	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO8687926095	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO6486618908	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO6451819229	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6455918968	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6459418684	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8731126064	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8748826078A	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8748826078A	ODP	6	30 BRO	SP	CCA	ED,SRC	T	00:00.0
2021 PO8753126134	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8748826078	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8781226184	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8761525893	ODP	4	40 UNK	SP	CRE	ED,ID,IP	BD	00:00.0

2021 PO9418926126	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9399725948	ODP	3	45 XXX	SP	S		V	00:00.0
2021 PO9409025728	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9406225761	ODP	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO9402125806	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO0457835849	ODP	5	35 BRN	SP	CRE		V	00:00.0
2021 PO8753325701	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8724025851	ODP	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8752725973	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO9393626016	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO6682317688	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8641525780	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8650125704	ODP	5	35 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8575625465	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8569425195	ODP	4	40 UNK	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021 PO6630117753a	ODP	3	40 XXX	SP	CCA		V	00:00.0
2021 PO6630117753	ODP	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO6642317445	ODP	5	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6661317679	ODP	4	40 XXX	SP	CRE	ID,IP	BD	00:00.0
2021 PO6641017647	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6611017908	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8010321394	ODP	4	40 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0211834573	ODP	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0238034522	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0226434468	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0238234514	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0232934253	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8024121365	ODP	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8182521286	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8208221705	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8196721311	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8212120896	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8225221070	ODP	6	30 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO7293419893	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7252219892	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7265220056	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8236421028	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8231620910	ODP	4	45 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8242920828	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8272320967	ODP	6	30 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8283121053	ODP	6	30 UNK	SP	CCA		V	00:00.0
2021 PO8272320967A	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8290020895	ODP	2	45 BRO	SP	CCA		V	00:00.0
2021 PO8297321129	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO7259219893	ODP	4	40 XXX	SP	CRE	ED,ID,IP,RB	X	PX
2021 PO7225319897	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7260920117	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7263920347	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8266921465	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7212019895	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021 PO7232119921	ODP	3	45 XXX	SP	CCA		V	00:00.0
2021 PO8303921906	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8317721881	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8311921982	ODP	4	40 UNK	SP	CRE	ID	BD	00:00.0

2021	PO8318822061	ODP	6	30 BRO	SP	CCA		V		00:00.0
2021	PO8364922131	ODP	6	30 UNK	SP	CRE		V		00:00.0
2021	PO8334822237	ODP	4	40 UNK	SP	CRE	ED,ID,SR	TD		00:00.0
2021	PO8298522157A	ODP	5	40 UNK	SP	CRE	ED,ID,SR	TD		00:00.0
2021	PO8298522157	ODP	4	40 UNK	SP	CRE	ED,ID,SR	TD		00:00.0
2021	PO8766124786	ODP	4	40 UNK	SP	CRE	ED,ID,SR	TD		00:00.0
2021	PO4310786891	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4284687116	LGE	3	55 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4308586965	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4311886990	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4314786942	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4306386981	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4295387103	LGE	3	45 ACE	SP	CRE	ED,EP,ID	TD		00:00.0
2021	PO4321586956	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO3901107424	F	4	40 BRN	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021	PO5873809520	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4678813682	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4695912616	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4680212264	KU	5	35 XXX	SP	CRE	ID	BD		00:00.0
2021	PO3955216006	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021	PO2787069085	KU	6	35 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4696213030	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4697413582	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO2891373697	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO2884672374	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO2931672297	KU	3	50 XXX	SP	CRE	ID	BD		00:00.0
2021	PO7043169949	KU	6	30 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4727312522	KU	3	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO3246469508	KU	3	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO2831375606	KU	5	30 UNK	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021	PO5449501881	F	4	40 XXX	SP	P		V		00:00.0
2021	PO7062069324	KU	1	50 XXX	SP	CRE	ID	TD		00:00.0
2021	PO7195867970	F	5	45 BRO	SP	P		V		00:00.0
2021	PO7196167701	F	5	45 BRO	SP	P		V		00:00.0
2021	PO4214306249	F	4	45 UNK	SP	CRE	ED,HH,ID,IP,MD	BX	RP2	00:00.0
2021	PO3947007229	F	4	40 BRN	SP	CRE	ED,HH,ID,IP,MD,RB	BX	PX	00:00.0
2021	PO4167204814	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX	00:00.0
2021		4308587010	LGE	3	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	4319287020-a	F	4	30 ACE	SP	P		VX	RP1	00:00.0
2021	4315586955-a	F	4	25 ACE	SP	CRE	ED	VX	RP1	00:00.0
2021	PO5516904158A	KU	2	50 BRN	SP	A		V		00:00.0
2021	PO5217005431B	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO5217005431A	KU	3	45 BRO	SP	CRE		V		00:00.0
2021	PO5422204043A	KU	4	30 BRO	SP	CRE		V		00:00.0
2021	PO5594703969A	KU	3	40 MAR	SP	P		V		00:00.0
2021	PO5125002053A	F	2	50 BRN	SP	CCA		V		00:00.0
2021	PO5234205074B	KU	4	30 BRN	SP	CRE		V		00:00.0
2021	PO5234205074A	F	5	30 BRN	SP	P		V		00:00.0
2021	43006986957-a	F	4	35 ACE	SP	A		V		00:00.0
2021		4308386881	LGE	4	40 ACE	SP	CCA	V		00:00.0
2021	4309586936-a	F	3	30 ACE	SP	A		V		00:00.0
2021	PO2809572158A	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO2484779288A	KU	4	45 UNK	SP	CCA		V		00:00.0
2021	PO2658180757A	KU	6	30 UNK	SP	CRE		V		00:00.0

2021 PO3060270369A	KU	4	40 XXX	SP	CCA		V		00:00.0
2021 PO2300877480A	KU	4	35 KOP	SP	P	ED,ID	TD		00:00.0
2021 PO2675180677	KU	5	35 UNK	SP	CRE	ED,ID	T		00:00.0
2021 PO3068970332	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO6944572029	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO6964571296	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO6933771901	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO2933472986	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO2927771984	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO3241069191	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO3040669880	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO2559276964	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2589581158	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO2440776205	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO7057168463	KU	2	60 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO6992167720	KU	3	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO8084214150	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO7418413846	KU	4	45 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO2314978546	KU	4	45 ACW	SP	CRE	ED,ID	TD		00:00.0
2021 PO2985581597	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO2484779288	KU	4	45 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO4311286899	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4298887098	LGE	3	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO2712280668	KU	5	35 UNK	SP	P	ED,ID	TD		00:00.0
2021 PO4301587022	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	X	RP1	00:00.0
2021 PO4329387089	LGE	4	35 BRO	SP	CRE	ED,ID,RB	X	RP1	00:00.0
2021 PO4327487065	LGE	4	40 BRO	SP	CRE	ED,EP,HH,ID,RB	X	RP1	00:00.0
2021 PO3080770017	KU	5	35 XXX	SP	CRE	HH,ID	X	PX	00:00.0
2021 PO5439502684	F	4	40 BRN	SP	CRE	ED,HH,ID,IP	VX	PX	00:00.0
2021 PO5337103199	F	4	40 BRN	SP	CRE	ED,HH,ID,IP,RB	VX	RP1	00:00.0
2021 PO5381803832	F	4	40 BRN	SP	CRE	ID,IP	VX	RP2	00:00.0
2021 PO5413103643	F	4	40 BRN	SP	CRE	ED,HH,ID,IP,MD	VX	PX	00:00.0
2021 PO5428403403	F	4	40 BRN	SP	CRE	ED,ID,IP,MD	VX	PX	00:00.0
2021 PO5525304124	F	4	40 BRO	SP	CRE	ED,ID,IP,RB	VX	PX	00:00.0
2021 PO5594703969	F	4	40 MAR	SP	CRE	ED,HH,ID,IP,RB	VX	PX	00:00.0
2021 PO6768421041	KU	5	35 BRO	SP	CRE		VX	PX	00:00.0
2021 PO4112504505	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4114504406	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO5908089203	KU	2	55 BRN	SP	CCA		V		00:00.0
2021 PO5939089919	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO6605688783	KU	4	35 BRN	SP	CCA		V		00:00.0
2021 PO5552901676	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6750485420	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6759285260	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5500001021	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5494101071	F	6	30 XXX	SP	CRE		V		00:00.0
2021 PO5491900987	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5496800936	F	6	30 XXX	SP	CRE		V		00:00.0
2021 PO5457402210	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5463302162	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6738285766	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6744385629	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6668086417	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6661186450	KU	4	40 BRN	SP	CRE		V		00:00.0

2021 PO6672986479	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6730086001	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4163804851	F	4	40 CPT	SP	P		V	00:00.0
2021 PO4158004697	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO5438302294	F	4	40 XXX	SP	S		V	00:00.0
2021 PO5405702368	F	5	35 XXX	SP	CRE		V	00:00.0
2021 PO5401902458	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5391202501	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5384102464	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5384302535	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5463001352	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5453301237	F	4	40 XXX	DF	P		V	00:00.0
2021 PO5445501141	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5433300994	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5425800903	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5410200971	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5393603187	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5375603401	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4191605041	F	4	40 XXX	SP	CRE	ED,ID,MD	V	00:00.0
2021 PO4198704840	F	3	40 XXX	SP	P		V	00:00.0
2021 PO4089004998	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4211804969	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4062705331	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4069805677	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4071105813	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4074906028	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5366403453	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5362503355	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5349403193	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4122804835	F	3	50 BRN	SP	CRE		V	00:00.0
2021 PO4118004690	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4115404600	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4196105829	F	4	40 UNK	SP	CRE	ED,ID,JP	V	00:00.0
2021 PO4190305664	F	5	35 UNK	SP	P		V	00:00.0
2021 PO4144505465	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4136205230	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4131605093	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4126304941	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4138405291	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6651286607	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5484500632	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4113005847	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4178005298	F	4	40 BRN	SP	CRE	ED,MD	V	00:00.0
2021 PO4180005356	F	6	30 BRN	SP	CRE	ED,JP,MD	V	00:00.0
2021 PO4181505319	F	4	40 XXX	SP	P	ED,MD	V	00:00.0
2021 PO5510802814	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5498902865	KU	4	40 XXX	SP	P		V	00:00.0
2021 PO5475602966	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5486802919	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5461803592	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5473003112	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5456503711	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5469003287	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5468303416	KU	6	30 XXX	SP	S		V	00:00.0



2021	PO5466903457	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5452003813	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5451403939	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5452004068	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO4207706064	F	3	45 UNK	SP	P	V	00:00.0
2021	PO4089305305	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5517601368	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5514301196	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5422301293	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5431501437	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5439301568	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5449101657	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5446801701	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5461401775	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5467501844	F	4	40 XXX	SP	P	V	00:00.0
2021	PO4200605881	F	3	45 UNK	SP	P	V	00:00.0
2021	PO4109205614	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4115405598	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4116705736	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4102905552	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4107605541	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4115405277	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4194505682	F	3	40 UNK	SP	P	V	00:00.0
2021	PO4110805747	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO3964106668	F	3	40 XXX	SP	P	V	00:00.0
2021	PO5499104582	KU	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5537605700	KU	6	30 BRO	SP	CRE	V	00:00.0
2021	PO5531905710	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5545205960	KU	6	30 BRO	SP	CRE	V	00:00.0
2021	PO5539106039	F	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5547906198	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5541306210	F	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5536705840	F	3	45 BRO	SP	P	V	00:00.0
2021	PO5216805219	KU	4	45 BRO	SP	CCA	V	00:00.0
2021	PO5214805227	KU	4	45 BRO	SP	CCA	V	00:00.0
2021	PO5223705248	KU	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5220605260	KU	4	40 BRO	SP	CRE	V	00:00.0
2021	PO5215205283	KU	4	45 BRO	SP	CCA	V	00:00.0
2021	PO5206305457	KU	2	55 BRO	SP	CCA	V	00:00.0
2021	PO5503504781	F	3	45 BRO	SP	CRE	V	00:00.0
2021	PO5548502360	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5536802314	KU	5	35 XXX	SP	S	V	00:00.0
2021	PO5485602561	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5472902617	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5463402635	F	3	40 XXX	SP	P	V	00:00.0
2021	PO5533902709	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5528302734	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5530802791	F	5	30 XXX	SP	CRE	V	00:00.0
2021	PO5522402759	F	4	40 XXX	SP	P	V	00:00.0
2021	PO5527902881	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5523004860	F	3	45 BRO	SP	CRE	V	00:00.0
2021	PO4245505935	F	4	35 XXX	SP	P	V	00:00.0
2021	PO4233606001	F	5	35 BRN	SP	CRE	V	00:00.0
2021	PO4236205628	F	3	45 UNK	SP	P	V	00:00.0

2021	PO5474604825	F	6	30 BRO	SP	CRE		V	00:00.0
2021	PO5492704981	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5469304698	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5508405163	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5498804956	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4024907449	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3998007091	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5527905309	KU	5	35 BRO	SP	CRE		V	00:00.0
2021	PO5524205373	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO5517005360	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO5522905494	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO5527105593	F	3	45 BRO	SP	CRE		V	00:00.0
2021	PO3949506299	F	4	40 XXX	SP	CRE	ED,MD	V	00:00.0
2021	PO4185103879	F	3	50 BRN	SP	S		V	00:00.0
2021	PO5418904594	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4157103963	F	3	50 BRN	SP	S		V	00:00.0
2021	PO4200503832	F	2	50 BRN	SP	S		V	00:00.0
2021	PO4169803923	F	3	50 BRN	SP	S		V	00:00.0
2021	PO4301805945	F	4	35 CPT	SP	P		V	00:00.0
2021	PO4283005935	F	4	30 CPT	SP	P		V	00:00.0
2021	PO6613288269	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO6600888412	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6631987866	KU	3	55 BRN	SP	CCA		V	00:00.0
2021	PO6606887651	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO6603887626	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO6643887911	F	3	50 BRN	SP	CRE		V	00:00.0
2021	PO6628988085	F	3	50 BRN	SP	CRE		V	00:00.0
2021	PO3931407527	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4028206910	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5217605593	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5235605516	KU	1	65 BRN	SP	CCA		V	00:00.0
2021	PO5258605254	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5540504101	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO5536504169	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO3984106907	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4023706608	F	4	40 BRN	SP	P		V	00:00.0
2021	PO4315605968	F	3	40 XXX	SP	P		V	00:00.0
2021	PO4213803765	F	2	50 BRN	SP	S		V	00:00.0
2021	PO5504204207	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4039406593	F	4	40 BRN	SP	CRE	ED,MD	V	00:00.0
2021	PO5721890918	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO5727290874	F	2	50 BRN	SP	CRE		V	00:00.0
2021	PO5738390767	KU	3	45 BRN	SP	S		V	00:00.0
2021	PO8736624913	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO8735224766	ODP	4	40 UNK	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO8707224828	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021	PO7554318321	ODP	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO7546318393	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021	PO8702224748	ODP	4	40 UNK	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO8643324525	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021	PO7499518243	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO7460818203	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO7458818075	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO7427118039	ODP	4	40 BRN	SP	CCA		V	00:00.0

2021	PO7534056056	ODP	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0
2021	PO7495955981	ODP	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7966244810	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7968644753	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7961844744	ODP	6	30 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021	PO7861444242	F	4	40 XXX	SP	P	ED	V	00:00.0
2021	PO7912244571	ODP	4	40 XXX	SP	S		V	00:00.0
2021	PO8155144636	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO8154444712	ODP	6	30 BRO	SP	CRE	ID	BD	00:00.0
2021	PO7468755934	ODP	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7441355894	F	4	40 KOP	SP	CRE		V	00:00.0
2021	PO7415255792	ODP	6	30 KOP	SP	CRE		V	00:00.0
2021	PO8132944531	ODP	4	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO7601048492	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO7614848958	F	5	35 BRN	SP	P		V	00:00.0
2021	PO7625048759	F	5	35 BRN	SP	P		V	00:00.0
2021	PO7579249215	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO8147844314	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021	PO8159744340	ODP	5	35 BRO	SP	CRE	ID	BD	00:00.0
2021	PO4965289792	F	4	30 KOP	SP	CCA		V	00:00.0
2021	PO4963689789	LGE	3	45 BRN	SP	P	ED,ID,MD	TD	00:00.0
2021	PO7477450671	ODP	5	30 KOP	SP	CCA		V	00:00.0
2021	PO5559722380	KU	6	30 OTH	SP	P	ED,ID,IP	TD	00:00.0
2021	PO4937788743	F	5	35 BRO	SP	A		V	00:00.0
2021	PO7908544717	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7880844271	ODP	4	40 XXX	SP	S		V	00:00.0
2021	PO7914344426	F	4	40 XXX	SP	P		V	00:00.0
2021	PO7896044337	ODP	4	40 XXX	SP	S		V	00:00.0
2021	PO7889644396	ODP	5	35 XXX	SP	S		V	00:00.0
2021	PO7944144323	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO7937044527	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021	PO8045744839	ODP	4	45 XXX	SP	S		V	00:00.0
2021	PO8073444958	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO8037344624	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021	PO8028944699	ODP	4	45 ACW	SP	CRE	ID	BD	00:00.0
2021	PO5563522226	KU	6	30 KOP	SP	CCA		T	00:00.0
2021	PO7485950532	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021	PO8050744706	ODP	4	40 ACW	SP	CCA		V	00:00.0
2021	PO4939988762	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5567322331	KU	5	35 KOP	SP	CCA		T	00:00.0
2021	PO7456950410	ODP	6	35 KOP	SP	CRE	ED	TD	00:00.0
2021	PO5573122267	KU	2	50 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5620421889	F	2	55 BRN	SP	CRE		V	00:00.0
2021	PO5633421737	F	2	55 BRN	SP	CRE		V	00:00.0
2021	PO5623821850	F	2	55 BRN	SP	CRE		V	00:00.0
2021	PO5640021664	F	2	55 BRN	SP	CRE		V	00:00.0
2021	PO7374155656	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7395155725	ODP	6	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO5556922257	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO8252344183	F	4	40 BRN	SP	CRE	ED,ID,RB	BX PX	00:00.0
2021	PO8272244461	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO8271044182	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO8223944983	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5563322181	KU	3	45 KOP	SP	CCA		V	00:00.0

2021	PO7399855498	ODP	5	30 KOP	SP	CRE				V	00:00.0
2021	PO7360055502	ODP	6	30 KOP	SP	CCA				V	00:00.0
2021	PO7419550303	ODP	3	45 KOP	SP	CCA				V	00:00.0
2021	PO5609022000	F	3	55 BRN	SP	CCA				V	00:00.0
2021	PO5605322045	F	2	55 BRN	SP	CRE				V	00:00.0
2021	PO5598522127	F	2	55 BRN	SP	CRE				V	00:00.0
2021	PO5593021870	KU	3	45 BRN	SP	CRE		ID		BD	00:00.0
2021	PO5601421945	KU	3	45 BRN	SP	CCA				V	00:00.0
2021	PO7416250444	ODP	3	45 KOP	SP	CCA				V	00:00.0
2021	PO8036145133	ODP	4	45 ACW	SP	CRE		ID		BD	00:00.0
2021	PO8033745228	ODP	4	40 ACW	SP	CRE		ID,IP		BD	00:00.0
2021	PO7399450450	ODP	4	40 KOP	SP	CCA				V	00:00.0
2021	PO4967289743	LGE	4	40 BRN	SP	CCA				V	00:00.0
2021	PO4949089010	LGE	4	40 BRO	SP	CCA				V	00:00.0
2021	PO7359050198	ODP	5	35 KOP	SP	CRE		ED		TD	00:00.0
2021	PO4958689746	LGE	3	50 BRN	SP	A		ED,ID		BD	00:00.0
2021	PO7360055369	ODP	4	40 KOP	SP	CRE		ED,ID		TD	00:00.0
2021	PO7355055463	ODP	5	45 KOP	SP	CRE		ED,ID		TD	00:00.0
2021	PO7347255567	ODP	4	45 KOP	SP	CRE		ED,ID		BD	00:00.0
2021	PO8021545398	ODP	4	40 ACW	SP	CRE		ID		BD	00:00.0
2021	PO4721189717	LGE	4	30 ACE	SP	CRE		ED,ID,IP		BD	00:00.0
2021	PO4709689666	LGE	3	45 ACE	SP	CCA				V	00:00.0
2021	PO4706789631	F	4	35 ACE	SP	CRE				V	00:00.0
2021	PO4706589636	LGE	2	50 ACE	SP	CCA				V	00:00.0
2021	PO4706289646	LGE	4	40 ACE	SP	CCA				V	00:00.0
2021	PO4707589646	LGE	3	45 ACE	SP	CCA				V	00:00.0
2021	PO4708289652	LGE	4	40 ACE	SP	CRE		ED,ID		TD	00:00.0
2021	PO4726190035	LGE	4	40 ACE	SP	CCA				V	00:00.0
2021	PO4731190052	LGE	4	30 ACE	SP	CRE		ED,ID		BD	00:00.0
2021	PO8230844914	ODP	5	35 BRN	SP	CRE		ED,ID,IP		TD	00:00.0
2021	PO8199446160	F	4	45 BRN	SP	CRE				V	00:00.0
2021	PO8226145993	F	4	45 BRN	SP	CRE				V	00:00.0
2021	PO8220946097	F	4	45 BRN	SP	CRE				V	00:00.0
2021	PO8214446205	F	4	45 BRN	SP	CRE				V	00:00.0
NULL	NULL	NULL	NULL	NULL	NULL	NULL	NULL	NULL	NULL	NULL	NULL
2021	PO2092065839	KU	6	30 BRO	SP	CRE		ED,ID,IP		TD	00:00.0
2021	PO4838590960	LGE	3	50 BRN	SP	A				V	00:00.0
2021	PO4840190980	LGE	4	50 BRN	SP	P		ED,ID		BD	00:00.0
2021	PO4842690977	LGE	3	45 BRN	SP	P		ED,ID		BD	00:00.0
2021	PO4843290976	LGE	3	45 BRN	SP	CCA		ED,ID		BD	00:00.0
2021	PO4840190980-a	LGE	3	50 BRN	SP	P				V	00:00.0
2021	PO2058766236	KU	4	40 BRO	SP	CRE		ED,ID,IP		BD	00:00.0
2021	PO1984466695	KU	4	40 BRO	SP	CRE		ED,ID,IP		TD	00:00.0
2021	PO1983866943	KU	4	40 BRO	SP	CRE		ED,ID		TD	00:00.0
2021	PO5549604683	F	4	40 BRN	SP	CRE				V	00:00.0
2021	PO5538504790	F	4	40 BRN	SP	CRE				V	00:00.0
2021	PO1942351614	KU	3	50 XXX	SP	CRE		ID		TD	00:00.0
2021	PO0174657359	KU	4	40 UNK	SP	CRE		ED,ID		TD	00:00.0
2021	PO6274689260	F	4	40 BRN	SP	CRE				V	00:00.0
2021	PO1982967268	KU	5	35 BRO	SP	CRE				V	00:00.0
2021	PO6660587719	KU	3	50 BRN	SP	CRE				V	00:00.0
2021	PO6673587567	F	4	40 BRN	SP	CRE				V	00:00.0
2021	PO6683587400	F	4	40 BRN	SP	CRE				V	00:00.0
2021	PO6683187648	KU	4	40 BRN	SP	CRE		ED		TD	00:00.0

2021	PO1986967166	F	5	30 BRO	SP	CCA			V	00:00.0	
2021	PO6479691233	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO4306887046	LGE	UNK	50 ACE	SP	CRE	ED,ID,IP		TX	RR	00:00.0
2021	PO4305887053	LGE	3	50 ACE	SP	CCA			V	00:00.0	
2021	PO1413574352	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0	
2021	PO9903258644	KU	4	40 BRO	SP	CCA			V	00:00.0	
2021	PO9920658542	KU	6	30 BRO	SP	CCA			V	00:00.0	
2021	PO9854958327	KU	4	40 KOP	SP	CRE	ED,ID		TD	00:00.0	
2021	PO4305404581	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO4292804763	F	4	40 BRN	SP	CCA			V	00:00.0	
2021	PO4289104642	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO4288104686	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO6487591032	KU	2	55 BRN	SP	CRE			V	00:00.0	
2021	PO6485491086	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO6490390957	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO6496790785	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO6501690640	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO6476190787	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO6463690635	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO1884651899	KU	4	40 XXX	SP	CRE	ID		BD	00:00.0	
2021	PO1869651720	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0	
2021	PO1965851758	KU	3	45 XXX	SP	CCA			V	00:00.0	
2021	PO1978251849	KU	4	45 XXX	SP	CRE	ID		BD	00:00.0	
2021	PO1990751786	KU	4	40 XXX	SP	CRE	ID		BD	00:00.0	
2021	PO2002652021	KU	4	45 XXX	SP	CRE	ID		BD	00:00.0	
2021	PO5409400223	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5432700104	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5421900153	F	4	40 XXX	SP	CRE			V	00:00.0	
2021	PO5450900022	F	3	40 XXX	SP	P			V	00:00.0	
2021	PO5461199973	F	3	40 XXX	SP	P			V	00:00.0	
2021	PO5473699916	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5470099819	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5493999826	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5500199798	F	3	40 XXX	SP	P			V	00:00.0	
2021	PO5511899742	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO5523799686	F	3	40 XXX	DF	CRE	ED,EP,HH,ID,MD		BX	PX	00:00.0
2021	PO5520099612	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,MD,RB		BX	PX	00:00.0
2021	PO5515099501	F	4	40 XXX	SP	P			V	00:00.0	
2021	PO1420874107	KU	6	30 BRO	SP	CCA			V	00:00.0	
2021	PO4949288505	LGE	4	40 BRO	SP	A	ED,ID,IP		TD	00:00.0	
2021	PO6601397756	LGE	1	50 BRO	SP	CCA			V	00:00.0	
2021	PO4949888478	LGE	3	50 BRO	SP	A	ED,ID		TD	00:00.0	
2021	PO9849258080	KU	4	40 KOP	SP	CRE	ED,ID		TD	00:00.0	
2021	PO4311787012	LGE	4	40 ACE	SP	A	ED,ID		TD	00:00.0	
2021	PO6365989929	F	4	40 BRN	SP	CRE			V	00:00.0	
2021	PO5038588622	F	5	25 ACE	SP	P			V	00:00.0	
2021	PO5038088610	LGE	3	50 ACE	SP	A	ED,ID		BD	00:00.0	
2021	PO9769156323	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0	
2021	PO6126888512	KU	3	40 BRN	SP	CRE	ED		TD	00:00.0	
2021	PO4313987213	LGE	4	35 BRO	SP	CRE	ID,IP		BD	00:00.0	
2021	PO9762156265	KU	6	30 UNK	SP	CCA			V	00:00.0	
2021	PO9757456276	KU	6	30 UNK	SP	CCA			V	00:00.0	
2021	PO9769756398	KU	6	30 UNK	SP	CRE			V	00:00.0	
2021	PO9760556332	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0	

2021	PO9734456359	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO1521172081	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO1551572353	KU	3	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4018405377	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4043405393	KU	2	45 BRN	SP	CCA		V		00:00.0
2021	PO4042205220	F	3	45 BRN	SP	CCA		V		00:00.0
2021	PO4041405608	F	2	50 BRN	SP	CCA		V		00:00.0
2021	PO5041988680	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO5043388711	LGE	3H	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO5044388726	LGE	3	45 ACE	SP	P	ED,ID,IP,RB	BX	RP1	00:00.0
2021	PO5045288744	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO4310187171	LGE	4	35 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO1644872433	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4325686987	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4324987001	LGE	4	35 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4324287011	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4323687020	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4322987031	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO6157588269	KU	3	45 BRN	SP	CCA		V		00:00.0
2021	PO6155388274	KU	1	40 BRN	SP	CRE		V		00:00.0
2021	PO6152588283	KU	2	45 BRN	SP	CCA		V		00:00.0
2021	PO6151088287	KU	3	45 BRN	SP	CCA		V		00:00.0
2021	PO4327786976	LGE	UNK	45 ACE	SP	A	ED	VX	RP1	00:00.0
2021	PO4328386983	LGE	4	40 ACE	SP	CRE	ED,HH	VX	RP2	00:00.0
2021	PO4329086992	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4329987002	LGE	4	40 ACE	SP	CRE	HH,ID	BD		00:00.0
2021	PO4330187007	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4330687012	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4310987162	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5047388754	LGE	3	50 BRN	SP	P	ED,ID	BD		00:00.0
2021	PO4062304705	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4075004691	F	3	40 BRN	SP	CRE		V		00:00.0
2021	PO4060004803	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO9492254414	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9702555447	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO9705055721	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO4312187171	F	4	35 BRO	SP	CRE		V		00:00.0
2021	PO1639372294	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO5049388739	LGE	4	35 BRN	SP	P	ED,ID	TD		00:00.0
2021	PO5055588722	LGE	4	40 BRN	SP	P		V		00:00.0
2021	PO5051488737	LGE	4	40 BRN	SP	P		V		00:00.0
2021	PO1612171723	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO1619371936	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO1627572168	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4333087045	LGE	UNK	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	4332397035	LGE	1	60 ACE	SP	CCA		V		00:00.0
2021	PO9700455913	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO9706255983	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO9683556257	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO4333787054	LGE	4	40 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO1663972024	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO1661271979	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4318986996	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4319587003	LGE	4	40 ACE	SP	P	ED	VX	RP2	00:00.0

2021	PO6348989722B	KU	5	30 BRN	SP	CRE	ED	TD		00:00.0
2021	PO6348989722A	KU	4	35 BRN	SP	CRE	ED	TD		00:00.0
2021	PO1216473595	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO1214474053	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO6294289443	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO6291489466	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO9631056186	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO9639956475	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9652256488	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9635657301	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO9713757069	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO4308287214	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4305587240	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021	PO4325287037	LGE	4	40 BRO	SP	A	ID,IP,RB	X	RP1	00:00.0
2021	PO1106575211	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4324087049	LGE	4	30 BRO	SP	CRE		V		00:00.0
2021	PO4322687060	LGE	4	40 BRO	SP	CRE	HH,ID,RB	X	RP1	00:00.0
2021	PO1079575469	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9814656648	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9788956585	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9757556617	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9757556617A	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4321287071	LGE	4	40 BRO	SP	A	ED,IP,RB	X	RP1	00:00.0
2021	PO4321987065	LGE	4	40 BRO	SP	A	HH,IP,RB	X	RP1	00:00.0
2021	PO9706356458	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO4319887082	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4320587077	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4312887166	F	4	35 BRO	SP	CRE		V		00:00.0
2021	PO4313487161	F	4	35 BRO	SP	CRE		V		00:00.0
2021	PO4314387155	F	4	35 BRO	SP	A		V		00:00.0
2021	PO2128653008	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2124952810	KU	4	40 XXX	SP	CRE	HH,ID	X	RP3	00:00.0
2021	PO2121452619	KU	4	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4849989910	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO5017888953	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021	PO7290803103	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021	PO5035089014	LGE	4	35 BRN	SP	P		V		00:00.0
2021	PO5033288978	LGE	4	40 BRN	SP	P		V		00:00.0
2021	PO5031788940	LGE	4	35 BRN	SP	P		V		00:00.0
2021	PO7552395427	LGE	3	45 BRN	SP	P		V		00:00.0
2021	PO5045988220	LGE	4	45 BRN	SP	P		V		00:00.0
2021	PO5045888234	LGE	4	40 BRN	SP	P		V		00:00.0
2021	PO4185802266	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4198002384	F	4	40 BRN	SP	CRE	ED,EP	VX	RP2	00:00.0
2021	PO4177302184	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4854389863	LGE	2	55 BRO	SP	CCA		V		00:00.0
2021	PO1556379537	KU	5	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4856389854	LGE	3	45 BRO	SP	CRE	ED,ID,IP,RB	X	RP1	00:00.0
2021	PO5045789573	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO5045589571	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO5045989575	LGE	3	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO5046089576	LGE	3	45 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO5046889566	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO1549179162	KU	3	45 BRO	SP	CCA		V		00:00.0

2021 PO1549278922	KU	4	40 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO1429378969	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO1501978946	KU	5	35 BRO	SP	CRE		V		00:00.0
2021 PO5677811506	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021 PO0349563913	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO2311660526	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO2297960374	KU	5	35 BRO	SP	CRE	ED,ID	BX	RP1	00:00.0
2021 PO2281460201	KU	5	30 BRO	SP	CRE	RB	BX	PX	00:00.0
2021 PO5011288345	LGE	3	50 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO5002888445	LGE	4	45 BRN	SP	P		V		00:00.0
2021 PO5002188430	LGE	4	45 BRN	SP	P		V		00:00.0
2021 PO5003588407	LGE	3	50 BRN	SP	P		V		00:00.0
2021 PO5005588395	LGE	3	55 BRN	SP	P		V		00:00.0
2021 PO5027588402	LGE	4	40 BRN	SP	P		V		00:00.0
2021 PO5032188472	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO5028888449	LGE	3	45 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO4133901509	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4165602080	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4148101815	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4156401955	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4128901402	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4139301625	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6637494470	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6625794548	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6594194747	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6604294684	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6615294615	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO1530478330	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO1520578032	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5009488844	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO5011288868	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO5010288756	LGE	3H	50 BRO	SP	CCA		V		00:00.0
2021 PO5052589560	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO5051989592	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5051389574	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO5049389542	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5052589524	LGE	3	45 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5050989532	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO5047889551	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO5047789548	LGE	UNK	25 ACE	AL	CCA		V		00:00.0
2021 PO5054189516	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021 PO5055289510	LGE	3	45 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO5054789507	LGE	3	45 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO5057089501	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5050489564	LGE	4	40 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO2263660002	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5029588455	LGE	3	45 BRN	SP	P	ED,ID	T		00:00.0
2021 PO5030388473	LGE	4	30 BRN	SP	P	ED,ID,SR	TD		00:00.0
2021 PO0438063574	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO0592462962	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO6722994496	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6713794560	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6706794606	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6601193909	F	4	40 BRN	SP	CRE		V		00:00.0



2021 PO6577693724	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6580593684	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6514890848	F	4	45 BRN	SP	CRE		V		00:00.0
2021 PO4099000797	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4109001012	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4120901246	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4114501120	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO4094800684	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4103600905	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO0564763085	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO0535763222	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO0514863316	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO1505977618	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO2273159917	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2171859939	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO2179659711	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO2179459468	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO2186359496	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6913148727	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO6923348635	F	5	35 UNK	SP	CRE		V		00:00.0
2021 PO6930648619	F	4	40 BRO	SP	CCA		V		00:00.0
2021 PO6931248675	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO6940848594	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO6946448640	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO6949048577	F	5	40 UNK	SP	CRE	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO6957848563	F	5	35 BRO	SP	CRE		V		00:00.0
2021 PO6957048623	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO6971848599	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO6976848533	F	5	40 UNK	SP	CRE		V		00:00.0
2021 PO6988548572	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO6986948517	F	5	40 UNK	SP	CRE		V		00:00.0
2021 PO7000548554	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO7019048467	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO7017248527	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO7032648502	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO7059048460	KU	1	85 UNK	ST	CCA		V		00:00.0
2021 PO7045948481	KU	1	85 UNK	ST	CCA		V		00:00.0
2021 PO7044448425	F	5	35 UNK	SP	CRE		V		00:00.0
2021 PO7051148414	F	5	35 UNK	SP	CRE		V		00:00.0
2021 PO9495057581	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO9238663215	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO9225662794	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9170763124	KU	5	35 OTH	SP	CRE	ED,SRS	TD		00:00.0
2021 PO9254363044	KU	5	35 OTH	SP	CRE	HH,ID,IP,RB	X	PX	00:00.0
2021 PO9199363451	KU	6	30 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021 PO9177263127	KU	5	30 OTH	SP	CRE	ID	BD		00:00.0
2021 PO9193362801	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9200862914	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9175063089	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9493957254	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO9508857348	KU	4	45 BRN	SP	CRE		V		00:00.0
2021 PO9246962941	F	4	40 OTH	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	00:00.0
2021 PO9502257455	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO9470457341	KU	3	45 BRN	SP	CCA		V		00:00.0

2021 PO9002862096	KU	5	35 BRO	SP	CRE		V	00:00.0
2021 PO9004162211	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9038062495	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4366085288	LGE	3	45 BRN	SP	A		V	00:00.0
2021 PO4366285293	LGE	4	35 BRN	SP	A		V	00:00.0
2021 PO9041562435	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9016062560	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO9511757759	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7078148480	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO7075548486	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9016162478	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO9017862530	KU	5	35 BRO	SP	CRE		V	00:00.0
2021 PO7884246916	KU	4	40 UNK	SP	P	ID	BD	00:00.0
2021 PO9095063124	KU	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4482905402	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9029862630	KU	3	45 BRO	SP	CRE	ED,ID,RB	X PX	00:00.0
2021 PO9042162945	KU	2	70 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0060301611	KU	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0079801855	KU	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4365585264	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO4365185345	LGE	1	60 BRN	SP	A		V	00:00.0
2021 PO7771747365	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO7468846394	KU	4	45 UNK	UN	CRE		V	00:00.0
2021 PO7509645647	KU	6	35 BRN	SP	CCA		V	00:00.0
2021 PO7771347684	KU	6	30 KOP	SP	CRE		V	00:00.0
2021 PO7765647722A	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO4560606085	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4580506190	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4598806276	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4543305839	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4586006097	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO9499457816	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO4565705998	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4618406163	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4554405914	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4534505752	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4602606179	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4546105963	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4535805916	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0092902019	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0092002025	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9531857970	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO0113802281	KU	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0130702492	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO9020263216	KU	2	70 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7928446971	KU	3	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7918246997	KU	3	45 UNK	SP	CRE		V	00:00.0
2021 PO0147902708	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0147102715	KU	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0190403240	KU	2	60 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0218103587	KU	2	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0236803822	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0260204115	KU	3	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9551258311	KU	4	40 BRN	SP	CCA		V	00:00.0

2021 PO9539358274	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO9567158198	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO8994663525	KU	5	30 BRO	SP	P	ED,ID	TD	00:00.0	
2021 PO9047463355	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4252988062	LGE	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0	
2021 PO6978248960	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021 PO6963448984	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021 PO6948649009	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021 PO7181748520	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7190047300	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO7178147317	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO7162947598	KU	4	35 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO7174247548	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4253288041	LGE	4	40 BRN	SP	A	ID	BD	00:00.0	
2021 PO0277204328	KU	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9044563198	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9066763180	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9106363144	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0294804549	KU	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO0310204741	KU	3	40 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO0332605022	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9557058133	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9098063179	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9097863770	KU	4	45 BRO	SP	CRE		V	00:00.0	
2021 PO4360804724	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4369104783	F	4	40 BRN	SP	CRE	ID,IP	BX	RR	00:00.0
2021 PO9485857734	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9477057788	KU	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4470005209	F	3	45 BRN	SP	CRE		V	00:00.0	
2021 PO4504405494	F	3	45 BRN	SP	CRE		V	00:00.0	
2021 PO4446605205	F	3	45 BRN	SP	CRE		V	00:00.0	
2021 PO4453105102	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO4405604918	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4512405702	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4497205565	F	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4497305424	F	3	45 BRN	SP	CRE		V	00:00.0	
2021 PO4488005330	F	3	40 BRN	SP	CRE		V	00:00.0	
2021 PO4435904995	F	3	45 BRN	SP	CRE		V	00:00.0	
2021 PO4409104824	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4430605079	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4419304887	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4466305267	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4386704805	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4518705637	KU	3	45 BRN	SP	CRE		V	00:00.0	
2021 PO4415404988	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO9485857645	KU	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7175547791	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO7186947768	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7189447765	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021 PO7213247712	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021 PO7200247741	KU	5	30 ACW	SP	CRE	ID	BD	00:00.0	
2021 PO6844948865	KU	1	75 BRO	SP	CCA		V	00:00.0	
2021 PO6689749460	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021 PO6641249553	KU	5	35 BRO	SP	CCA		V	00:00.0	

2021	PO4270487955	LGE	1	50 BRN	SP	CCA		V			00:00.0
2021	PO7191047520	KU	4	40 UNK	SP	CRE	ED,ID,RB	BX	PX		00:00.0
2021	PO4253588080	LGE	4	35 BRN	SP	CCA		V			00:00.0
2021	PO9470157902	KU	5	45 BRN	SP	CRE	ED,ID,IP,RB	X	PX		00:00.0
2021	PO9083863460	KU	6	30 BRO	SP	CRE	ED,ID	BD			00:00.0
2021	PO9089463548	KU	5	35 BRO	SP	CRE	ED,ID	TD			00:00.0
2021	PO9097863403	KU	3	50 BRO	SP	S		V			00:00.0
2021	PO9098763543	KU	3	55 BRO	SP	S		V			00:00.0
2021	PO8870061771	KU	4	40 BRO	SP	CRE	ED,ID	TD			00:00.0
2021	PO4218288372	LGE	4	40 BRN	SP	A		V			00:00.0
2021	PO9675493002	LGE	4	40 BRN	SP	CCA		V			00:00.0
2021	PO9479657988	KU	5	35 BRN	SP	CCA		V			00:00.0
2021	PO9481758053	KU	5	45 BRN	SP	CRE		V			00:00.0
2021	PO8852461764	KU	4	40 BRO	SP	CRE	ED,ID	TD			00:00.0
2021	PO9460158073	KU	3	50 BRN	SP	CRE	RB	X	RP1		00:00.0
2021	PO4251488034	LGE	4	40 BRN	SP	CRE	ID,IP	BD			00:00.0
2021	PO4240787875	LGE	4	30 BRN	ST	CCA		V			00:00.0
2021	PO4264288207	LGE	3	45 BRN	SP	CCA		V			00:00.0
2021	PO9375959262	KU	4	40 UNK	SP	CRE	ED,ID	TD			00:00.0
2021	PO9380561312	KU	4	45 XXX	SP	CRE	ID	BX	RR		00:00.0
2021	PO9241160225	KU	3	50 UNK	SP	CRE	ED,ID	TD			00:00.0
2021	PO9231260336	KU	3	50 UNK	SP	CRE		V			00:00.0
2021	PO4536104422	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4541104123	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4526804488	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4495904803	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX		00:00.0
2021	PO4500304737	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4517404552	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4508204619	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4547304285	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4552504204	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4485198372	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4473098417	F	3	45 BRO	SP	CRE	ED	V			00:00.0
2021	PO4456398477	F	6	30 BRO	SP	CRE	ED	V			00:00.0
2021	PO4462498452	F	3	45 BRO	SP	CRE	ED	V			00:00.0
2021	PO4460198497	F	3	45 BRO	SP	CRE	ED,HH,ID,RB	BX	RP3		00:00.0
2021	PO4464798498	F	2	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4451398532	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4480401070	F	4	40 BRO	SP	CRE		V			00:00.0
2021	PO4350998958	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4361798913	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4371898870	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4384298817	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4393898776	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4405998724	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4417098678	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4426698637	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4439398583	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4444798881	F	4	40 BRO	SP	CRE		V			00:00.0
2021	PO4457298828	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4432898932	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4421598982	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4410799028	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4399799075	F	4	40 BRO	SP	CRE	ED	V			00:00.0

2021	PO4390099117	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4377999170	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4366799218	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO9220760444	KU	3	50 UNK	SP	CRE	ID	BD			00:00.0
2021	PO9238360177	KU	3	50 KOP	SP	CRE	ID	BD			00:00.0
2021	PO9395259602	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO9368259346	KU	5	35 UNK	SP	CRE	ED,ID	TD			00:00.0
2021	PO6134398938	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO6127299173	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO6241499208	F	4	40 XXX	SP	CRE	ED,ID,IP,MD	BX	RP1		00:00.0
2021	PO6236899731	F	4	40 XXX	SP	P		V			00:00.0
2021	PO6243199036	F	4	40 XXX	SP	P		V			00:00.0
2021	PO9291260756	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD			00:00.0
2021	PO9300760714	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD			00:00.0
2021	PO9316860772	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD			00:00.0
2021	PO9282660961	KU	4	40 OTH	SP	CRE		V			00:00.0
2021	PO9286660888	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD			00:00.0
2021	PO9466558774	KU	3	50 BRN	SP	CRE	ED,ID,IP	BD			00:00.0
2021	PO6239699409	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO6256699452	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX		00:00.0
2021	PO6271699208	F	4	40 XXX	SP	CRE	ED,HH,ID	BX	PX		00:00.0
2021	PO6272699080	F	3	40 XXX	SP	CCA		V			00:00.0
2021	PO6298199087	F	4	40 XXX	SP	P		V			00:00.0
2021	PO6305899092	F	4	40 XXX	SP	P		V			00:00.0
2021	PO6312299134	F	4	40 XXX	SP	CCA		V			00:00.0
2021	PO6318399126	F	4	40 XXX	SP	CCA		V			00:00.0
2021	PO6246699513	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO6238199567	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO6270799373	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX		00:00.0
2021	PO6278299330	F	4	40 XXX	SP	CCA		V			00:00.0
2021	PO9311860337	KU	6	30 OTH	SP	CCA	ED,SRS	TD			00:00.0
2021	PO9309560333	KU	3	55 OTH	SP	CRE	ED,ID,SRS	TD			00:00.0
2021	PO9295660639	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD			00:00.0
2021	PO9285960766	KU	6	30 OTH	SP	CRE		V			00:00.0
2021	PO9302260491	KU	2	50 OTH	SP	CCA		V			00:00.0
2021	PO9692863637	KU	4	45 BRO	SP	CRE	ED,ID	BD			00:00.0
2021	PO9687263503	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO9694463458	KU	5	35 BRO	SP	CCA		V			00:00.0
2021	PO6303199186	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX		00:00.0
2021	PO6290899257	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX		00:00.0
2021	PO9620363442	KU	4	45 BRO	SP	CRE	ED,ID	TD			00:00.0
2021	PO4425004801	F	5	35 BRN	SP	CCA		V			00:00.0
2021	PO4377604540	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4475105130	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4439804937	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4510405432	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX		00:00.0
2021	PO4503605360	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4457505030	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4412204750	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX		00:00.0
2021	PO4394104666	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4493005234	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO9367060858	KU	3	50 XXX	SP	CRE	ID	TD			00:00.0
2021	PO9386261035	KU	5	35 XXX	SP	CRE		V			00:00.0
2021	PO9394661210	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0

2021 PO9403961427	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4717789987	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4951489888	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO4951189892	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4946489939	LGE	1	45 BRN	SP	CCA		V	00:00.0
2021 PO5582720007	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO6740308170	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4925988781	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO6550709076	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4834588738	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5453804059	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5451004104	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4834689095	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4700389864	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4701089868	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4697889851	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4696989877	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4697089886	F	4	40 ACE	SP	P		V	00:00.0
2021 PO4697189890	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4928788813	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5530211401	F	6	30 OTH	SP	CRE	ED,ID	V	00:00.0
2021 PO5522011418	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6560208958	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4946889597	F	4	40 ACE	UN	S		V	00:00.0
2021 PO5459103683	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO5449403859	LGE	1	50 BRN	SP	CRE		V	00:00.0
2021 PO4835189083	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021 PO5397512206	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5417212724	KU	2	45 BRN	SP	CCA		V	00:00.0
2021 PO5400112354	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO5402912465	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO4699189902	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4699489897	F	4	30 ACE	SP	CCA		V	00:00.0
2021 PO6518608901	LGE	4	35 ACE	UN	P		V	00:00.0
2021 PO6717507057	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4963489386	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4914688927	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4964989381	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO4966189376	LGE	3	45 ACE	SP	A	ED,ID	V	00:00.0
2021 PO4966789375	LGE	4	40 ACE	SP	A	ED,ID	V	00:00.0
2021 PO4967889373	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4937589732	LGE	3	50 BRN	SP	P		V	00:00.0
2021 PO4936789754	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4969089370	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO4970389369	LGE	3	45 ACE	SP	A	ED,ID	V	00:00.0
2021 PO5383109020	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO5346109169	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO5386209039	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO6525709206	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO5361809106	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO9994436197	F	4	40 OTH	SP	A		V	00:00.0
2021 PO4971989363	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO8979122698	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8964822565	F	4	40 BRO	SP	CRE		V	00:00.0

2021 PO4975389364	LGE	3	50 ACE	SP	A	ED,ID	V	00:00.0
2021 PO4917988839	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4996089323	LGE	3	45 ACE	SP	CCA	ED,ID	V	00:00.0
2021 PO8969823422	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8996323268	ODP	6	35 BRO	SP	CRE		V	00:00.0
2021 PO4877588555	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4878188565	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4877788572	LGE	1	60 BRN	SP	CCA		V	00:00.0
2021 PO4879188564	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4721590043	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4721990037	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4722290046	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4723690056	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4918488827	F	4	40 BRO	SP	A		V	00:00.0
2021 PO0863935264a	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO9840535170	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO9908235593	F	4	40 SWP	SP	CRE		V	00:00.0
2021 PO4727090079	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4728390088	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO9830235005	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO1506344588	ODP	5	35 UNK	SP	CRE		V	00:00.0
2021 PO1475844428	ODP	5	35 UNK	SP	CRE		V	00:00.0
2021 PO9796835089	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4878988561	LGE	1	55 BRN	SP	CCA		V	00:00.0
2021 PO4879688554	LGE	1	60 BRN	SP	CCA		V	00:00.0
2021 PO4880488547	LGE	1	60 BRN	SP	CCA		V	00:00.0
2021 PO4821988650	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4825288632	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4713489892	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4713989884	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4715189889	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4715989893	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4717389889	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4716889896	F	4	35 ACE	SP	CCA		V	00:00.0
2021 PO5333112142	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8055721308	ODP	6	30 UNK	SP	CRE		V	00:00.0
2021 PO8076021268	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021 PO8085621245	ODP	6	30 UNK	SP	CRE		V	00:00.0
2021 PO4725589769	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4726889777	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4727689789	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4727989784	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4728889790	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4380810799	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4708689860	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4707989861	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4705889870	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4707089876	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4707689876	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4706789891	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4706189891	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4705289906	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4819089518	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO7949121514	ODP	6	30 BRO	SP	CRE		V	00:00.0

2021 PO9292123479	F	6	35 UNK	SP	CRE	V	00:00.0
2021 PO4704589918	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4705289929	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO7965021587	ODP	4	45 BRO	SP	CCA	V	00:00.0
2021 PO7973221343	F	4	45 UNK	SP	P	V	00:00.0
2021 PO4706689938	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4707489942	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4708989952	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4710389952	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4710889935	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO4821988669	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5317199521	LGE	4	45 BRO	SP	CCA	V	00:00.0
2021 PO4822288661	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4851089672	LGE	1	75 BRN	ST	P	V	00:00.0
2021 PO4848489664	LGE	3	70 BRN	ST	P	V	00:00.0
2021 PO4846089655	LGE	H1	70 BRN	ST	P	V	00:00.0
2021 PO4843689545	LGE	H1	65 BRN	ST	P	V	00:00.0
2021 PO4841389633	LGE	H1	65 BRN	ST	P	V	00:00.0
2021 PO4840389599	LGE	4	40 BRN	SP	CRE	V	00:00.0
2021 PO7593120637	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO7604820513	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4710489793	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO8433420921	ODP	6	30 KOP	SP	CCA	V	00:00.0
2021 PO5389911888	KU	4	40 BRN	SP	CRE	V	00:00.0
2021 PO8436220961	ODP	4	40 KOP	SP	CRE	V	00:00.0
2021 PO4950889479	LGE	2	65 ACE	SP	CCA	V	00:00.0
2021 PO5391912122	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO5378711477	KU	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4839089621	LGE	H1	70 BRN	ST	P	V	00:00.0
2021 PO4836789609	LGE	H1	75 BRN	ST	P	V	00:00.0
2021 PO4713189744	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4713289748	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO7851321351	ODP	4	45 BRO	SP	CCA	V	00:00.0
2021 PO7841121551	ODP	4	45 BRO	SP	CCA	V	00:00.0
2021 PO7827021828	ODP	4	45 BRO	SP	CCA	V	00:00.0
2021 PO4712689756	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4829989572	LGE	4	30 BRN	SP	CRE	V	00:00.0
2021 PO4831489580	LGE	3	65 BRN	SP	CRE	V	00:00.0
2021 PO4833289590	LGE	3	60 BRN	SP	A	V	00:00.0
2021 PO4835189600	LGE	2	60 BRN	SP	P	V	00:00.0
2021 PO4829789570	LGE	H1	65 BRN	ST	P	V	00:00.0
2021 PO4833488739	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4726689941	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO8418220901	ODP	4	45 KOP	SP	CCA	V	00:00.0
2021 PO4726289925	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO9068423268	F	4	40 REP	SP	CRE	V	00:00.0
2021 PO9063323111	F	4	40 REP	SP	CRE	V	00:00.0
2021 PO9067422981	F	4	40 REP	SP	CRE	V	00:00.0
2021 PO9066422825	F	4	40 REP	SP	CRE	V	00:00.0
2021 PO4822189538	LGE	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4712589875	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4847489316	LGE	3	35 BRN	SP	CRE	V	00:00.0
2021 PO4711389867	F	4	45 ACE	SP	CRE	V	00:00.0
2021 PO4708889847	F	4	40 ACE	SP	CRE	V	00:00.0



2021 PO7621921186	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4420011056	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021 PO4405710963	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4730889802	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO6842119029	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8478918681	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4825489517	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0528633973	ODP	5	35 BRN	SP	CRE		V	00:00.0
2021 PO0520734311	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0263033716	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4965389505	LGE	3	45 ACE	SP	A		V	00:00.0
2021 PO0631838475	ODP	2	50 OTH	SP	CCA		V	00:00.0
2021 PO8991624011	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO8992324207	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO9009223927	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO8993124387	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO8993824551	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO6388118351	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6388118287	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO4934289000	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4929688989	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4933088997	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9290225446	F	4	40 XXX	SP	P		V	00:00.0
2021 PO9350325075	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO9354525295	ODP	6	30 XXX	SP	S		V	00:00.0
2021 PO4931088992	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4932088994	F	4	40 BRO	SP	A		V	00:00.0
2021 PO7771820133	ODP	3	45 UNK	SP	CRE		V	00:00.0
2021 PO7791719888	ODP	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7798920171	ODP	2	45 BRN	SP	CCA		V	00:00.0
2021 PO7799220481	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5511011061	KU	4	45 KOP	SP	CRE	ED,ID	V	00:00.0
2021 PO7806320590	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO5358501466	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9041623679	ODP	4	40 REP	SP	CRE		V	00:00.0
2021 PO4934189688	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO6425810080	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO4935589693	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO6490710150	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5392212056	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO4727989954	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4829588766	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4829988752	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4828888785	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8433020748	ODP	4	30 KOP	SP	CCA		V	00:00.0
2021 PO4949589497	LGE	2	65 ACE	SP	A		V	00:00.0
2021 PO4948289516	LGE	2	65 ACE	SP	A		V	00:00.0
2021 PO4725889906	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4847789177	F	4	40 BRN	SP	A		V	00:00.0
2021 PO7820320810A	F	3	35 UNK	SP	CRE		V	00:00.0
2021 PO4947189533	LGE	2	65 ACE	SP	A	ED,ID	V	00:00.0
2021 PO7820320810	F	5	35 OTH	SP	CRE		V	00:00.0
2021 PO7845320822	ODP	6	30 UNK	SP	CRE		V	00:00.0
2021 PO6458316933	ODP	4	45 BRN	SP	CCA		V	00:00.0

2021	PO6496518103	ODP	4	40 BRN	SP	CRE				V	00:00.0	
2021	PO6464618013	ODP	5	35 BRN	SP	CRE				V	00:00.0	
2021	PO8254920476	F	4	40 BRN	SP	CRE				V	00:00.0	
2021	PO8269420597	F	2	50 BRN	SP	CRE				V	00:00.0	
2021	PO4927288798	LGE	4	40 BRO	SP	CRE				V	00:00.0	
2021	PO7842720518	ODP	4	40 UNK	SP	CCA				V	00:00.0	
2021	PO8301820400	ODP	5	35 BRN	SP	CCA				V	00:00.0	
2021	PO4702589844	F	3	45 ACE	SP	CCA				V	00:00.0	
2021	PO4701989839	F	4	30 ACE	SP	P				V	00:00.0	
2021	PO4940789625	LGE	1	75 BRN	SP	CRE				V	00:00.0	
2021	PO4941989608	F	4	45 BRN	SP	CRE				V	00:00.0	
2021	PO4941889633	LGE	4	40 BRN	SP	P				V	00:00.0	
2021	PO4942289623	LGE	1	80 BRN	SP	CRE				V	00:00.0	
2021	PO4942689613	LGE	H1	75 BRN	SP	CRE				V	00:00.0	
2021	PO4943089604	LGE	2	75 BRN	SP	CRE				V	00:00.0	
2021	PO6511109251	LGE	4	35 BRN	SP	CCA				V	00:00.0	
2021	PO6555808547	LGE	3	45 ACE	SP	CCA				V	00:00.0	
2021	PO8306820495	F	4	40 KOP	SP	CRE				V	00:00.0	
2021	PO4827688821	LGE	4	40 BRO	SP	P	ED,EP,HH,ID,IP			TX	RR	00:00.0
2021	PO6904918790	ODP	4	40 BRN	SP	CRE	ED,ID,IP			TX	RR	00:00.0
2021	PO4839989292	LGE	3	45 BRN	SP	CRE	ED,HH,ID,RB			TX	RR	00:00.0
2021	PO7514115653	ODP	4	40 KOP	SP	CRE	ED,RB			TX	RR	00:00.0
2021	PO0300638048	ODP	5	35 BRO	SP	CRE	ED,ID,IP			TX	RR	00:00.0
2021	PO4820788807	LGE	4	40 BRO	SP	CRE	ED,EP,ID,IP			TX	RR	00:00.0
2021	PO0176437093	ODP	5	35 BRN	SP	CRE	ED,ID,IP,RB,SRC			TX	RR	00:00.0
2021	PO4895289009	LGE	4	40 BRO	SP	A	ED,ID,IP			TX	RR	00:00.0
2021	PO5379812870	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC			TX	RR	00:00.0
2021	PO4823088845	LGE	4	40 BRO	SP	CRE	ED,HH,ID,IP			TX	RR	00:00.0
2021	PO4933288939	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB			TX	RR	00:00.0
2021	PO0604539045	ODP	4	40 OTH	SP	CRE	ED,ID,IP,SRC			TX	RR	00:00.0
2021	PO8618521655	ODP	6	35 KOP	SP	CRE	HH,IP,RB			TX	RR	00:00.0
2021	PO4905188969	LGE	4	40 BRO	SP	A	ED,ID,IP,RB			TX	RR	00:00.0
2021	PO0184234644	ODP	2	45 BRN	SP	CRE	ID			TX	RR	00:00.0
2021	PO0189833773	ODP	5	35 BRN	SP	CRE	ID			TD		00:00.0
2021	PO8599921425	ODP	5	35 KOP	SP	CRE	ED			TD		00:00.0
2021	PO0261934511	ODP	4	40 BRN	SP	CRE	ID			TD		00:00.0
2021	PO0233134744	ODP	4	45 BRN	SP	CRE	ID			TD		00:00.0
2021	PO0245534637	ODP	4	40 BRN	SP	CRE	ID			TD		00:00.0
2021	PO8023245634	ODP	5	35 KOP	SP	CRE	ID			BD		00:00.0
2021	PO8016245604	ODP	6	30 KOP	SP	CRE	ID			BD		00:00.0
2021	PO8018145838	ODP	5	35 KOP	SP	CRE	ID			BD		00:00.0
2021	PO5555522114	KU	3	45 OTH	SP	CRE	ED,ID			BD		00:00.0
2021	PO55556522122	KU	3	45 KOP	SP	CCA				V		00:00.0
2021	PO8231344824	ODP	4	40 BRN	SP	CCA				V		00:00.0
2021	PO8242244865	F	4	40 BRN	SP	CCA				V		00:00.0
2021	PO8252644766	ODP	4	45 BRN	SP	CCA				V		00:00.0
2021	PO8250944869	ODP	4	40 BRN	SP	CCA				V		00:00.0
2021	PO7241750491	ODP	5	30 KOP	SP	CRE				V		00:00.0
2021	PO8010845934	ODP	4	40 KOP	SP	CRE	ID			BD		00:00.0
2021	PO8006145864	ODP	6	30 KOP	SP	CCA				V		00:00.0
2021	PO8004445987	ODP	4	40 KOP	SP	CCA				V		00:00.0
2021	PO5544122018	KU	2	50 BRN	SP	CCA				V		00:00.0
2021	PO5527422376	KU	6	30 BRN	SP	CCA				V		00:00.0
2021	PO5518122383	KU	3	45 BRN	SP	CCA				V		00:00.0

2021	PO5520222405	KU	2	45 BRN	SP	CRE	EP,ID	BD	00:00.0
2021	PO5525722396	KU	2	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO5536521945	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4941888768	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4920988945	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4922688949	LGE	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4802189151	LGE	4	30 BRN	SP	CRE	ED,ID	V	00:00.0
2021	PO4799489134	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4802689099	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4800289124	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021	PO4802489104	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021	PO4799289127	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021	PO4798089106	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021	PO8043249852	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021	PO8052350061	ODP	5	30 BRN	SP	CCA		V	00:00.0
2021	PO8035550037	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5566321181	KU	2	50 OTH	SP	CRE		V	00:00.0
2021	PO5865524089	F	4	35 OTH	SP	P		V	00:00.0
2021	PO8025650272	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021	PO8019750126	ODP	2	55 BRN	SP	CCA		V	00:00.0
2021	PO5868524060	F	6	30 OTH	SP	CRE		V	00:00.0
2021	PO8019750126A	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5833723997	KU	6	30 OTH	SP	CCA		V	00:00.0
2021	PO5891323896	KU	1	40 OTH	SP	CCA		V	00:00.0
2021	PO5858124249	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5864024351	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO5839223933	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5545021410	KU	4	40 OTH	SP	CCA		V	00:00.0
2021	PO5825423831	KU	5	35 OTH	SP	CRE	ED,ID	BD	00:00.0
2021	PO5823224051	KU	5	35 OTH	SP	CCA		V	00:00.0
2021	PO5811023987	KU	5	35 OTH	SP	CRE	ID	BD	00:00.0
2021	PO5860524130	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5838224378	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5855724275	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0
2021	PO5830524123	KU	H1	100 OTH	ST	A		V	00:00.0
2021	PO5854623989	F	5	35 OTH	SP	CRE	RB	BX PX	00:00.0
2021	PO5594121387	KU	3	45 KOP	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5837824106	KU	6	30 OTH	SP	P	ID	BD	00:00.0
2021	PO5536421500	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO5886423947	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5808523916	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021	PO5449621059	F	4	35 OTH	SP	P		V	00:00.0
2021	PO9740792197	ODP	2	50 KOP	SP	CRE		V	00:00.0
2021	PO7826643883	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO7812143860	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021	PO4727589985	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4709689723	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4709489726	F	4	40 ACE	SP	CRE		V	00:00.0
2021	PO4726789993	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4724289975	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4884389858	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO4884989844	LGE	4	40 BRN	SP	P	ED,ID,SR	TD	00:00.0
2021	PO5460021032	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO5465520968	KU	3	45 BRN	SP	CCA		V	00:00.0

2021 PO5471920892	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5477020831	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO7776943875	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7796843877	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7795143922	ODP	4	45 BRN	SP	CRE	ID,IP	TD	00:00.0
2021 PO5460720831	KU	6	30 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO5467120860	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4873389918	LGE	1	65 BRN	SP	CRE	ED,HH,ID,IP	VX RP1	00:00.0
2021 PO7995543140	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4861190033	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO4861490011	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO8012343020	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4863489999	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO4865689985	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO8008743199	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4860890055	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8029243057	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5477420742	F	5	35 BRN	SP	S		V	00:00.0
2021 PO4730790020	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7545343351	ODP	5	30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7565243416	ODP	5	30 KOP	SP	CCA		V	00:00.0
2021 PO7560043534	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO5468822248(A)	KU	2	45 BRN	SP	CCA		V	00:00.0
2021 PO5444822019	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8068542328	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8056542498	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8062342435	F	4	40 XXX	SP	P		V	00:00.0
2021 PO8031142433	ODP	5	30 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8026242163	ODP	5	35 XXX	SP	CRE		V	00:00.0
2021 PO8024442065	ODP	5	35 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00.0
2021 PO8017741686	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO7881341539	ODP	6	30 XXX	SP	CRE		V	00:00.0
2021 PO7871841588	ODP	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7885641489	ODP	3	40 XXX	SP	S		V	00:00.0
2021 PO8053644452	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8058544470	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8055344572	ODP	2	50 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8040944520	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO7590743104	ODP	4	40 KOP	SP	CRE	ED	BD	00:00.0
2021 PO6946040847	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6945041082	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4859989854	LGE	3	45 BRN	SP	P	ED,HH,ID,IP	BX RP1	00:00.0
2021 PO0172033244	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO0182633183	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO0117632758	ODP	4	40 KOP	SP	CRE		V	00:00.0
2021 PO0211032532	ODP	5	35 KOP	SP	S	SRC	BD	00:00.0
2021 PO4931688706	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0151332418	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO5511219895	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5514819949	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4942588756	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7806942065	ODP	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7817342092	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7808942248	ODP	5	35 KOP	SP	CRE	ID	BD	00:00.0

2021	PO5521620054	KU	4	35 OTH	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO7812042257	F	4	40 KOP	SP	CRE		V	00:00.0
2021	PO7785842172	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021	PO7784342238	ODP	6	30 KOP	SP	CRE		V	00:00.0
2021	PO0134532698	ODP	3	50 KOP	SP	CRE	ED	TD	00:00.0
2021	PO5271322167	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5339321835	KU	3	45 BRN	SP	CRE		V	00:00.0
2021	PO5304822020	KU	3	45 BRN	SP	S		V	00:00.0
2021	PO5312322232	KU	5	35 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO5326321917	KU	3	45 BRN	SP	S		V	00:00.0
2021	PO5318322068	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5355721816	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5330121962	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5343721882	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO0130232742	ODP	6	30 KOP	SP	S		V	00:00.0
2021	PO5262622216	KU	4	40 BRN	SP	S		V	00:00.0
2021	PO5315021986	KU	3	45 BRN	SP	CRE		V	00:00.0
2021	PO5350821753	KU	3	45 BRN	SP	S		V	00:00.0
2021	PO5274622147	KU	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5315022143	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5288722064	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5334621937	F	4	35 BRN	SP	CRE		V	00:00.0
2021	PO7587748058	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO7630548093	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021	PO7672648474	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021	PO7640348316	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021	PO7037843337	ODP	5	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7057643024	ODP	2	45 BRN	SP	CCA		V	00:00.0
2021	PO7079842729	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8210045278	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021	PO8207345172	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO8213845096	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO8197944658	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO8207644669	ODP	5	30 BRN	SP	CCA		V	00:00.0
2021	PO8228344355	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8185344766	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO8170244690	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5571822121	KU	5	35 OTH	SP	CRE	ED,ID	TD	00:00.0
2021	PO5562322055	F	4	35 OTH	SP	P		V	00:00.0
2021	PO4960889813	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO5240922346	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5532620105	KU	5	35 BRN	SP	P	ED,ID,IP	BD	00:00.0
2021	PO5235622376	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5223322448	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5247022308	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5220422376	KU	6	30 BRN	SP	S	ED,SRC	TD	00:00.0
2021	PO5238522434	F	5	35 BRN	SP	A		V	00:00.0
2021	PO5247122380	F	5	35 BRN	SP	CCA		V	00:00.0
2021	PO5252722346	F	5	35 BRN	SP	CCA		V	00:00.0
2021	PO7803643290	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021	PO7811043075	ODP	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7798943249	ODP	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO4924589848	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4923889867	LGE	3	45 BRN	SP	CRE		V	00:00.0

2021 PO4923189891	LGE	3	45 BRN	SP	CRE		V	00:00.0	
2021 PO4923289894	LGE	4	40 BRN	SP	A	ED,ID	TD	00:00.0	
2021 PO4922189922	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0	
2021 PO4921889924	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO5533520177	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5526720131	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7818142878	ODP	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7799342834	ODP	4	40 KOP	SP	CRE		V	00:00.0	
2021 PO7795242882	ODP	4	40 KOP	SP	CCA		V	00:00.0	
2021 PO7805442842	ODP	4	40 KOP	SP	CCA		V	00:00.0	
2021 PO7571543041	ODP	4	40 KOP	SP	CRE		BD	00:00.0	
2021 PO7555542991	ODP	4	45 KOP	SP	CRE		BD	00:00.0	
2021 PO7534242919	ODP	4	45 KOP	SP	CCA		V	00:00.0	
2021 PO7824942687	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO7816042759	ODP	6	30 KOP	SP	CCA		V	00:00.0	
2021 PO7552542908	ODP	5	30 KOP	SP	CRE	ED	TD	00:00.0	
2021 PO7504342817	ODP	4	45 KOP	SP	CCA		V	00:00.0	
2021 PO7834542421	ODP	4	40 KOP	SP	CRE	ID,IP	BD	00:00.0	
2021 PO5201922652	F	5	35 BRN	SP	A		V	00:00.0	
2021 PO5181322774	F	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO5165622866	F	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO5190222645	KU	4	40 BRN	SP	S		V	00:00.0	
2021 PO5165722788	KU	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0	
2021 PO5202622569	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO5231722594	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO5178322715	KU	3	45 BRN	SP	S		V	00:00.0	
2021 PO5213722505	KU	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5168322850	F	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO4936388790	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4704689823	F	4	30 ACE	SP	P		V	00:00.0	
2021 PO7839142130	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO7845941927	ODP	4	45 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO4937088788	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO4929289660	F	3	40 BRN	SP	CRE		V	00:00.0	
2021 PO4929089661	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO4940488865	LGE	1	60 BRO	SP	CCA		V	00:00.0	
2021 PO4939888855	LGE	1	60 BRO	SP	CCA		V	00:00.0	
2021 PO7472442976	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0	
2021 PO4928189679	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4929089675	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO6376409873	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4929789675	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO4939988836	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021 PO5586020240	KU	6	35 OTH	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5525621170	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO7461842900	ODP	5	30 KOP	SP	CRE	ED	TD	00:00.0	
2021 PO4939388845	LGE	1	60 BRO	SP	CCA		V	00:00.0	
2021 PO5149522783	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021 PO7899442093	ODP	4	45 BRO	SP	CRE	ED,ID,IP,MD,SR	TX	RR	00:00.0
2021 PO7454342919	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0	
2021 PO7436442771	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0	
2021 PO7436142670	ODP	6	30 KOP	SP	CRE	ED	BD	00:00.0	
2021 PO7874442990	ODP	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021 PO4705489795	F	3	45 ACE	SP	CCA		V	00:00.0	

2021 PO4707689743	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4703689752	F	4	30 ACE	SP	P		V		00:00.0
2021 PO4702389776	F	4	30 ACE	SP	CRE	ED,HH,ID,RB	BX	RP1	00:00.0
2021 PO4703989820	F	4	40 ACE	SP	CCA		V		00:00.0
2021 PO4703489816	F	4	30 ACE	SP	CRE		V		00:00.0
2021 PO4700789803	F	4	30 ACE	SP	P		V		00:00.0
2021 PO5397620817	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO5396520804	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO5155522850	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5142722930	KU	5	35 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5159622917	KU	6	30 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5171823253	KU	4	45 BRN	SP	S		V		00:00.0
2021 PO5163922992	KU	6	30 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5393820580	KU	2	50 BRN	SP	S		V		00:00.0
2021 PO4916988481	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO4917688490	LGE	4	40 BRO	SP	CCA		V		00:00.0
2021 PO7871843316	ODP	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7890643187	ODP	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7887443281	ODP	6	30 BRO	SP	CRE		V		00:00.0
2021 PO7872043129	ODP	5	35 BRO	SP	CCA		V		00:00.0
2021 PO7858843152	ODP	6	30 BRO	SP	CCA		V		00:00.0
2021 PO4796689267	LGE	3	50 BRN	SP	P	ED,ID,MD	TD		00:00.0
2021 PO4795389237	LGE	4	35 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4796489245	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4797589253	LGE	3	50 BRN	SP	P	ED,ID,IP	BD		00:00.0
2021 PO5579721025	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5576121067	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5573821093	KU	3	45 KOP	SP	CCA		V		00:00.0
2021 PO5594020872	KU	4	40 KOP	SP	CCA		V		00:00.0
2021 PO7911346275	ODP	4	40 BRN	SP	CCA		V		00:00.0
2021 PO7931146322	ODP	6	30 BRN	SP	CCA		V		00:00.0
2021 PO7925446303	ODP	6	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO7941546335	ODP	6	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO7969646272	ODP	6	30 BRN	SP	CCA		V		00:00.0
2021 PO7972546309	ODP	4	45 BRN	SP	CRE	ED	T		00:00.0
2021 PO5588020930	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5615320947	KU	2	50 OTH	SP	CRE	ED,ID	BD		00:00.0
2021 PO6987543223	ODP	3	40 BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO7001243389	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7011143911a	ODP	4	45 BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO5631220722	KU	2	65 OTH	SP	CRE	ED,ID,RB	BX	PX	00:00.0
2021 PO4798789249	LGE	1	60 BRN	ST	CCA		V		00:00.0
2021 PO4799889231	LGE	1	65 BRN	SP	CRE		V		00:00.0
2021 PO4800989212	LGE	1	60 BRN	SP	CRE		V		00:00.0
2021 PO5617320909	KU	2	50 OTH	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4802189193	LGE	1	60 BRN	SP	CRE		V		00:00.0
2021 PO4803389173	LGE	1	60 BRN	SP	CRE		V		00:00.0
2021 PO4804589154	LGE	1	60 BRN	SP	CRE		V		00:00.0
2021 PO8092747764	ODP	3	45 BRN	SP	CCA		V		00:00.0
2021 PO8129846997	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4942188898	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021 PO4808189087	LGE	1	65 BRN	SP	CRE		V		00:00.0
2021 PO4805689135	LGE	1	60 BRN	SP	CRE		V		00:00.0
2021 PO4807189110	LGE	1	65 BRN	SP	CRE		V		00:00.0

2021 PO4809089060	LGE	1	60 BRN	SP	CRE		V	00:00.0
2021 PO4809889033	LGE	1	60 BRN	SP	CRE		V	00:00.0
2021 PO4810689010	LGE	1	60 BRN	SP	CRE		V	00:00.0
2021 PO4812488961	LGE	1	60 BRN	SP	CRE		V	00:00.0
2021 PO4811588986	LGE	1	60 BRN	ST	CCA		V	00:00.0
2021 PO4811988975	LGE	1	60 BRN	ST	CCA		V	00:00.0
2021 PO8145046759	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8157546561	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8159146415	F	6	30 BRN	SP	CRE		V	00:00.0
2021 PO8176446476	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO8165646435	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO7025243922	ODP	4	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO7019743836	ODP	5	30 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO7011143911	ODP	4	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO7000043835	ODP	4	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO7010643703	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7620046630	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7601946701	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7596846562	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO7572146474	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4799789060	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4799489048	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4800489053	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4802089059	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4803489065	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4787689059	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4790589043	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4804789071	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4941588887	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4813388935	LGE	1	60 BRN	SP	CRE		V	00:00.0
2021 PO4814388908	LGE	1	60 BRN	SP	CRE		V	00:00.0
2021 PO4815288882	LGE	1	60 BRN	ST	CCA		V	00:00.0
2021 PO4762689040	LGE	4	30 BRN	SP	P		V	00:00.0
2021 PO4759889052	LGE	4	30 BRN	SP	P		V	00:00.0
2021 PO4758089080	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5505220008	KU	6	30 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO8170446359	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8179546199	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8171946226	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8184646133	F	4	45 BRN	SP	CCA		V	00:00.0
2021 PO8185346087	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8185346087A	ODP	3	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8190745952	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021 PO8192945732	F	6	30 BRN	SP	CRE		V	00:00.0
2021 PO8198245753	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO8122444891	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8123144860	ODP	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8127844908	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO8092944697	ODP	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8109544752	ODP	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8125044801	ODP	4	45 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8079344665	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8088344611	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8086144674	ODP	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0



2021 PO8082144823	ODP	4	45 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8078044797	ODP	6	30 XXX	SP	CRE		V	00:00.0
2021 PO8079744736	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO7981644532	ODP	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO7797643713	ODP	5	35 XXX	SP	S		V	00:00.0
2021 PO5549022535	F	4	30 OTH	SP	P		V	00:00.0
2021 PO5544522582	KU	3	45 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7572146474A	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7579746655	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7585646664	ODP	6	30 BRN	SP	CRE		V	00:00.0
2021 PO7499848871	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO7586046901	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7586046901A	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4947988992	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4944088925	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO4925688571	LGE	4	90 BRO	SP	CCA		V	00:00.0
2021 PO4923288549	LGE	3	40 BRO	SP	CCA		V	00:00.0
2021 PO4936088754	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4937788755	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4937488744	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4758789067	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021 PO8189545642	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8196345648	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8207645412	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8203845580	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4972989998	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4969390017	LGE	3	45 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4970990010	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4969890018	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4967590027	LGE	3	45 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO4965890037	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4964490055	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO4963190070	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO7601147050	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7601247264	ODP	4	40 BRN	SP	CCA	ED	T	00:00.0
2021 PO7625348025	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO7522247683	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7569047428	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7574047403	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO8197244829	ODP	5	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8205344799	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO7503550803	ODP	4	40 KOP	SP	CRE		BD	00:00.0
2021 PO7547850525	ODP	6	30 KOP	SP	CRE	ED	BD	00:00.0
2021 PO7555050561	ODP	6	30 KOP	SP	S		V	00:00.0
2021 PO7267849250	ODP	4	45 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO7545650729	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7546950631	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7546950632	ODP	5	35 KOP	SP	CCA		V	00:00.0
2021 PO7565950653	ODP	4	45 KOP	SP	CCA		V	00:00.0
2021 PO7487050353	ODP	5	35 KOP	SP	CCA		V	00:00.0
2021 PO7488850199	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7459750239	ODP	4	45 KOP	SP	S		V	00:00.0
2021 PO7418750325	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7371750185	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0

2021 PO7381150448	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7412250661	ODP	5	35 KOP	SP	CRE	ED	BD	00:00.0
2021 PO4707589774	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4706289799	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4940588853	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4941488870	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4923389648	LGE	1	55 BRN	SP	CRE		V	00:00.0
2021 PO4922889664	LGE	1	80 BRN	ST	P		V	00:00.0
2021 PO4921989688	LGE	1	80 BRN	ST	P		V	00:00.0
2021 PO4921189712	LGE	1	70 BRN	SP	P		V	00:00.0
2021 PO4920289735	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4919489758	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4918589782	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4917789805	LGE	1	70 BRN	ST	P		V	00:00.0
2021 PO4916889829	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4916089852	LGE	1	70 BRN	ST	P		V	00:00.0
2021 PO4915289876	LGE	2	70 BRN	SP	P		V	00:00.0
2021 PO4917089882	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO7637542911	ODP	2	50 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7832442323	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4962389809	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4963589802	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7571951038	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7568950846	ODP	3	45 KOP	SP	CCA		V	00:00.0
2021 PO7568350721	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO5548922350	KU	2	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5541022442	KU	5	35 OTH	SP	P	ED,ID,RB	X	RP1 00:00.0
2021 PO7535055918	ODP	5	30 KOP	SP	CCA		T	00:00.0
2021 PO7559556104	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7261541652	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8212544914	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8217144937	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO8217444820a	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO8217444820	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO8215244498	ODP	5	30 BRN	SP	CCA		V	00:00.0
2021 PO8223944650	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4964789789	LGE	3	45 BRN	SP	P	ED,ID,MD,SRC	TD	00:00.0
2021 PO4965889767	LGE	3	45 BRN	SP	P	ED,ID,MD,SRC	TD	00:00.0
2021 PO5630121692	KU	2	55 BRN	SP	CCA	ED,SRC	TD	00:00.0
2021 PO5659221397	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5636321612	KU	2	55 BRN	SP	CCA	ED,SRC	TD	00:00.0
2021 PO5646021523	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5653121452	KU	3	45 BRN	SP	CCA	ED,SRS	T	00:00.0
2021 PO7293841724	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7284441683	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7244441619	ODP	5	30 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO7223341589	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7253941388	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7247541175	ODP	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO8166844309	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO8022444685	ODP	6	30 BRO	SP	CRE		V	00:00.0
2021 PO7480250601	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO4960189741	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4960689739	LGE	3	45 BRN	SP	P	ED,ID,IP	BD	00:00.0

2021 PO4961389736	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4961489735	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4962789741	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4948088999	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO5566820826	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5558320921	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5583320642	KU	4	50 BRN	SP	CCA		V	00:00.0
2021 PO5552620898	KU	6	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5561120794	KU	5	35 BRN	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021 PO5556220945	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5544721074	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO5573720749	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5592220541	KU	4	50 BRN	SP	CCA		V	00:00.0
2021 PO4947388985	LGE	1	60 BRO	SP	CCA		V	00:00.0
2021 PO7348355326	ODP	5	30 KOP	SP	CRE		T	00:00.0
2021 PO5355120748	KU	4	45 BRN	SP	S		V	00:00.0
2021 PO5371120621	KU	4	45 BRN	SP	CCA	ED,SR	T	00:00.0
2021 PO5356520740	KU	4	45 BRN	SP	S		V	00:00.0
2021 PO8376543688	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7877643488	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7884643516	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021 PO0066496931	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0041996979	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0065497087	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0071397159	ODP	6	30 BRO	SP	CRE		T	00:00.0
2021 PO0068797463	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0066097362	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0085897323	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0086897530	ODP	5	35 BRO	SP	CRE		V	00:00.0
2021 PO0084498132	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0084798100	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0082097916	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0080297800	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0078397632	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0069097668	ODP	6	30 BRO	SP	CRE		V	00:00.0
2021 PO00091397626	ODP	6	30 BRO	SP	CRE		V	00:00.0
2021 PO0106498058	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0101998244	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0114798307	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0138698515A	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0128198380	F	4	40 BRO	SP	P		V	00:00.0
2021 PO0138698515	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0145998397	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0157498476	ODP	6	30 BRO	SP	CCA	ED	TD	00:00.0
2021 PO0171998584	ODP	6	30 BRO	SP	CCA	ED	TD	00:00.0
2021 PO0174298678	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7887943730	ODP	4	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO7883043868	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7894743725	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7902743469	ODP	4	40 BRO	SP	P	ID	BD	00:00.0
2021 PO9856526085	ODP	4	40 KOP	SP	S		V	00:00.0
2021 PO5350720772	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO5550319849	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7906343341	F	4	40 BRO	SP	CRE		BD	00:00.0

2021	PO5315120979	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5335720862	KU	5	35 BRN	SP	S		V	00:00.0
2021	PO5345620803	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5325320922	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4942988680	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4938788677	F	4	30 BRO	SP	CRE		V	00:00.0
2021	PO4943888683	F	3	45 BRO	SP	A		V	00:00.0
2021	PO6178418239	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4941888677	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4940888674	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4940188672	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4939088669	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO6171417629	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6166317580	ODP	6	30 BRN	SP	CCA	ED,ID	TD	00:00.0
2021	PO6166717639	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6157917761	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021	PO6174217861	ODP	3	50 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4938288667	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4944788667	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4793589370a	KU	3	55 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021	PO4793589370	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4794689378	LGE	3	55 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO6751023008	ODP	6	35 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021	PO6750722738	ODP	6	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO4797889393	LGE	3	50 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4799489404	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4800289409	LGE	H3	50 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4801789418	LGE	H3	50 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4946088632	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021	PO4945788630	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4802689423	LGE	H3	50 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4803789430	LGE	H3	50 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021	PO4790589354	LGE	2	55 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021	PO4804789436	LGE	H3	50 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4789389348	LGE	3	50 ACE	SP	P	ID	BD	00:00.0
2021	PO6750122497	ODP	6	35 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO6766422003	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021	PO6749922267	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021	PO6732422183	ODP	6	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO6704222104	ODP	6	35 UNK	SP	CRE	ID,IP	BD	00:00.0
2021	PO4946288610	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6716422106	ODP	6	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO4788289343	LGE	H3	50 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021	PO4786889337	LGE	H3	55 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4785489330	LGE	3	50 ACE	SP	CCA	ED	T	00:00.0
2021	PO4946788593	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4947188577	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4784589326	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021	PO4783589321	LGE	2	60 ACE	SP	CCA		V	00:00.0
2021	PO4782489316	LGE	1	55 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO6685221981	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4801589433	F	4	30 ACE	SP	CRE		V	00:00.0
2021	PO4947588563	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO0597336440	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0

2021	PO9159559177	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO4377901391	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4373801436	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4229804059	KU	5	35 XXX	SP	S		V	00:00.0
2021	PO4339201409	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO4352201235	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4365401078	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4935488530	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4774989135	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4773789138	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021	PO6708619866	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6736419735	ODP	5	35 BRO	SP	CRE	ID	BD	00:00.0
2021	PO4936188508	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4936688489	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4771989144	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4770789160	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4770489168	LGE	4	40 ACE	SP	CCA	ED	T	00:00.0
2021	PO5887517200	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5870717176	ODP	4	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6671119822	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6650719683	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4936688499-A	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4771489175	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5873516904	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4944188537	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4948288540	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4781189152	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4778489260	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4950388489	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO6670819675	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6658519571	ODP	6	30 BRO	SP	CCA	ED,ID	TD	00:00.0
2021	PO4948488514	LGE	4	35 BRO	SP	CCA	ED	T	00:00.0
2021	PO4948888500	LGE	4	35 BRO	SP	CCA	ED	T	00:00.0
2021	PO4779189187	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO5865216747	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021	PO6670519567	ODP	4	45 BRO	SP	CCA	ED,ID	TD	00:00.0
2021	PO4949788487	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4946888513	LGE	4	35 BRO	SP	CCA	ED	T	00:00.0
2021	PO4781989147	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO5823117377	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5785217358	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4949288486	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021	PO6594698025	LGE	4	35 BRO	SP	CCA	ED	T	00:00.0
2021	PO4777889191	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4776489193	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4948288475	LGE	4	35 BRO	SP	CCA	ED	T	00:00.0
2021	PO4943488493	LGE	4	35 BRO	SP	CCA	ED	T	00:00.0
2021	PO6668119033	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6669619391	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6669119216	ODP	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4778789249	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4774489196	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4775489196	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO4943388507	LGE	4	40 BRO	SP	CCA	ED	T	00:00.0

2021	PO0658636981	ODP	4	40 XXX	SP	CCA		V		00:00.0
2021	PO4775689203	LGE	4	30 ACE	SP	P	ED,ID,MD,RB	X	RP1	00:00.0
2021	PO0676037140	ODP	4	40 XXX	SP	CCA		V		00:00.0
2021	PO0645036812	ODP	5	35 XXX	SP	CRE	ID,IP	TX	RR	00:00.0
2021	PO6659619049	ODP	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO4776989250	LGE	4	35 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4777389248	LGE	4	30 ACE	SP	P	ED,EP,HH,ID,MD,RB	BX	RP1	00:00.0
2021	PO4778089261	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4777789262	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6531298282	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO6545698319	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4944288506	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5732917518	ODP	5	30 BRN	SP	CRE		V		00:00.0
2021	PO5764517329	ODP	2	50 BRN	SP	CCA		V		00:00.0
2021	PO5738717169	ODP	4	45 BRN	SP	CCA		V		00:00.0
2021	PO4945888513	LGE	3	45 BRO	SP	CCA	ED	T		00:00.0
2021	PO4948488519	LGE	3	45 BRO	SP	CCA	ED	T		00:00.0
2021	PO4948888519	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO4948288524	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO6560398351	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO6673118855	ODP	2	50 BRO	SP	CRE	ED,ID,RB	X	RP1	00:00.0
2021	PO4802889462	F	4	40 ACE	SP	CCA		V		00:00.0
2021	PO4801589454	F	3	45 ACE	SP	CRE		V		00:00.0
2021	PO6568098372	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4939189517	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO9501160234	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9514260300	F	3	45 OTH	SP	CRE		V		00:00.0
2021	PO4261798973	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4240398705	KU	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4582700650	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4336899153	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4483398632	KU	5	35 BRN	SP	CRE	ID,IP	BD		00:00.0
2021	PO4299398801	KU	5	35 BRN	SP	S		V		00:00.0
2021	PO4548999617	KU	3	45 BRN	SP	S		V		00:00.0
2021	PO9547561380	F	5	35 OTH	SP	CRE		V		00:00.0
2021	PO9549461207	F	5	35 OTH	SP	CRE		V		00:00.0
2021	PO9545960840	F	2	50 OTH	SP	CRE		V		00:00.0
2021	PO9537660749	F	2	50 OTH	SP	CRE		V		00:00.0
2021	PO9544460953	F	4	30 OTH	SP	CRE		V		00:00.0
2021	PO9556961136	F	2	60 OTH	SP	CRE		V		00:00.0
2021	PO9548960941	F	3	50 OTH	SP	CRE		V		00:00.0
2021	PO9563261320	F	3	50 OTH	SP	CRE		V		00:00.0
2021	PO9582661166	KU	5	35 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021	PO9585061206	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO4464398051	KU	2	50 BRN	SP	S		V		00:00.0
2021	PO4359002507	KU	2	40 BRN	SP	CRE		V		00:00.0
2021	PO4334802549	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6666221804	ODP	4	40 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4767989169	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4793689396	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4772689270	LGE	4	35 ACE	DF	P		V		00:00.0
2021	PO4772789281	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021	PO6667721600	ODP	4	45 BRO	SP	CCA		V		00:00.0
2021	PO6033118100	ODP	2	50 BRN	SP	CCA		V		00:00.0

2021 PO6668221401	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO6077517851a	ODP	6	30 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO6077517851	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6088117864	ODP	4	40 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO6584220879	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6569520413	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0552335496	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021 PO0544035347	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0544135400	ODP	4	40 BRN	SP	CRE	ID,IP	TD	00:00.0
2021 PO4782789305	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO6580420629	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6542420822	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6525020805	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4781989302	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO6527620683	ODP	6	30 UNK	SP	CCA		V	00:00.0
2021 PO6498020759	ODP	5	35 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO6465320722	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO0552035614	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO6370820677	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6677821111	ODP	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4767789173	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4767289161	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BD	00:00.0
2021 PO4766889168	LGE	4	45 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0520835187	ODP	4	40 BRN	DF	CRE	ID,IP	TD	00:00.0
2021 PO0496835207A	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021 PO0511035317	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO0505035278	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0496935483	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0484335663	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0461635605	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4766589171	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4766189179	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4765689187	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4948288556	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4765089197	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4764289209	LGE	4	40 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4944888689	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6111018052	ODP	4	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO6110418204	ODP	4	40 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO6110418326	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4763689220	LGE	3	45 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021 PV4763589222	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4707404969	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4944288685	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PV4764189224	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO6668921171	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4765989219	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PV4765489226	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4767589245	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4783805425	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO6669820878	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6747020517	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6745820661	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6685320679	ODP	6	30 BRO	SP	CCA		V	00:00.0

2021 PO6694620728	ODP	4	45 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO6669320724	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6642520705	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6489399827	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4937388658	F	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4937288664	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4936088660	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4935888667	F	4	30 BRO	SP	A		V	00:00.0
2021 PO4935788673	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4764889241	F	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4765289244	F	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4762489226	F	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4763089229	F	1	65 ACE	SP	CCA		V	00:00.0
2021 PO0464935486	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0457635331	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0452435448	ODP	3	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0490535578	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0498735701	ODP	6	30 BRN	SP	CCA	ID	TD	00:00.0
2021 PO0500735690	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO0509035583	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0522935424	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0532335395	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0535335518	ODP	5	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0522135677	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO0527435721	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4935088656	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4767089254	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4769089267	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4768989274	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO6671120507	ODP	4	45 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO5943717558	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6761820508	ODP	6	30 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4936088588	LGE	5	25 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4768689272	LGE	3	45 ACE	SP	CCA	ED	T	00:00.0
2021 PO4767489288	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4934088653	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4933388660	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO6634620738	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6622420417	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6140718159	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4932988650	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7112742168	F	4	40 BRN	SP	A		V	00:00.0
2021 PO7283151227	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4731590102	LGE	3	45 ACE	SP	CRE		V	00:00.0
2021 PO4732690096	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4733990088	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4733490080	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7977845005	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7989444980	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7992144840	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7991144695	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8003744603	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO8000344697	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO7993544732	F	5	35 XXX	SP	P		V	00:00.0



2021 PO8007944779	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8014444800	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0	
2021 PO8024344831	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO8043844902	ODP	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5552222804	KU	6	30 OTH	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5569122875	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO7928543807	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7935743827	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7308851159	ODP	4	45 KOP	SP	CCA		V	00:00.0	
2021 PO7294451232	ODP	4	45 KOP	SP	CRE	ED,SRS	TD	00:00.0	
2021 PO7316451243	ODP	5	35 KOP	SP	CRE	ED,SRS	TD	00:00.0	
2021 PO4726389878	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4726689851	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4727589857	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4727989849	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO7301251746	ODP	3	45 KOP	SP	CCA		V	00:00.0	
2021 PO7633642583A	ODP	4	30 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO7632642583	ODP	2	50 KOP	SP	CCA		V	00:00.0	
2021 PO7637542433	ODP	3	50 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO5518721842	KU	4	45 BRN	SP	S		V	00:00.0	
2021 PO5508621938	KU	5	35 BRN	SP	S		V	00:00.0	
2021 PO5521321815	KU	2	45 BRN	SP	CCA		V	00:00.0	
2021 PO5515321875	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO7108541981	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7124541970	ODP	3	45 BRN	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO7121341818a	ODP	4	40 BRN	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO7134941876	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5533622861	KU	3	45 KOP	SP	CCA		T	00:00.0	
2021 PO7374051330	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0	
2021 PO7604742302	ODP	4	45 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO7624242347	ODP	5	35 KOP	SP	CCA		V	00:00.0	
2021 PO5512521740	KU	4	40 BRN	SP	CRE	ID	BX	RR	00:00.0
2021 PO5505221678	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO5517221673	F	5	35 BRN	SP	CRE		V	00:00.0	
2021 PO5522421719	KU	3	45 BRN	SP	A		V	00:00.0	
2021 PO5491821564	KU	4	45 BRN	SP	CRE	ID	BD	00:00.0	
2021 PO5516621775	KU	3	45 BRN	SP	S		V	00:00.0	
2021 PO5509521774	KU	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO7632642582	ODP	6	30 KOP	SP	CCA	ED,ID	TD	00:00.0	
2021 PO7400351101	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0	
2021 PO7435651208	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0	
2021 PO7659742475	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO7648342342	ODP	6	30 KOP	SP	CCA		V	00:00.0	
2021 PO7590841899	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0	
2021 PO5518522882	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4914589947	F	4	40 BRO	SP	A		V	00:00.0	
2021 PO4732290048	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4730490063	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4731290059	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4732390053	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO7948744185	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7965544249	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO7979144295	ODP	4	45 BRN	SP	CCA		V	00:00.0	
2021 PO7974344198	F	4	40 BRN	SP	CRE		V	00:00.0	

2021	PO7596641667	ODP	6	30 KOP	SP	CRE		V	00:00.0
2021	PO7593141778	ODP	6	30 KOP	SP	CRE		V	00:00.0
2021	PO7470651327	ODP	5	35 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021	PO7503351454	ODP	5	35 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021	PO7619541996	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021	PO7633842097	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021	PO5459521309	KU	2	60 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5469421393	KU	2	55 BRN	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021	PO7028554976	ODP	5	35 KOP	SP	CRE	ED,ID	BD	00:00.0
2021	PO7047054799	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7065354259	ODP	6	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7057354112	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7067254190	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021	PO7067154112	ODP	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7046353885	ODP	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7025953999	ODP	6	30 KOP	SP	CRE		T	00:00.0
2021	PO7007553913	ODP	5	30 KOP	SP	CCA		T	00:00.0
2021	PO7481352745	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021	PO7638142112	ODP	4	40 KOP	SP	CCA	ED,ID	TD	00:00.0
2021	PO7639642062	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7945946509	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021	PO7914746574	ODP	6	30 BRN	SP	CRE	ID	BD	00:00.0
2021	PO7922846577	ODP	6	30 BRN	SP	CRE	ID	BD	00:00.0
2021	PO7924146634	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021	PO7938146608	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO7838043917	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021	PO7831543882	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO5473121585	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5478121475	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5478021511	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5481421582	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4974690002	LGE	4	40 BRN	SP	P	ED	V	00:00.0
2021	PO4974389986	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO4974589991	LGE	4	40 BRN	SP	A		V	00:00.0
2021	PO4974989990	LGE	1	25 BRN	ST	CCA		V	00:00.0
2021	PO5504922991	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO7652142156	ODP	6	30 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8005543386	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4914188942	F	4	40 BRO	SP	A		V	00:00.0
2021	PO6250002663	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4915688954	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO7121341817	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7114541753	ODP	4	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021	PO4732990053	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4975890038	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4725190028	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4978390010	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4724190020	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4977090024	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4975990047	LGE	4	40 BRN	SP	P		V	00:00.0
2021	PO4761389641	LGE	1	20 ACE	SP	A		V	00:00.0
2021	PO4974590016	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4761189634	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4974590040	LGE	4	30 BRN	SP	P	ED,ID	BD	00:00.0

2021 PO4758989492	LGE	4	40 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4763889343	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4704989667	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4705789667	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4703789687	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4703689685	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO7655141821	ODP	4	40 KOP	SP	CCA	ED,ID	TD	00:00.0
2021 PO7647941827	ODP	4	45 KOP	SP	CRE		BX PX	00:00.0
2021 PO5499822607	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5488922724	KU	6	30 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO5494022668	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO4917288960	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5551922907	KU	5	35 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4919088966	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4920488970	F	4	40 BRO	SP	A		V	00:00.0
2021 PO7969743695	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7970343446	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7987843597	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7987643779	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7162741942	ODP	4	40 KOP	SP	CRE		BD	00:00.0
2021 PO7147241929	ODP	4	40 KOP	SP	CRE		BD	00:00.0
2021 PO7704741678	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7735041844	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7727841754	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7740142097	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7178041951	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO7199741970	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO5466421661	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5438121959	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5444121904	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5456221775	KU	3	45 BRN	SP	CCA	ED,SR	T	00:00.0
2021 PO5448622146	KU	5	35 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO7194141783	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO7261541837	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO7273141883	F	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7667541861	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7716342010	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7690141910	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7702241523	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7219341985	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7245742015	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7262542029	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4922988545	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4923488554	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO7030041699	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7039441631	ODP	4	40 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO7052841577	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5546322871	KU	6	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7970743218	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7981243218	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8012843407	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8025943491	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4974690066	LGE	4	30 BRN	SP	P		V	00:00.0
2021 PO4974790104	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0

2021 PO4974690093	LGE	4	30 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO7223141811A	F	4	45 KOP	SP	CRE		V		00:00.0
2021 PO5547522840	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO5546722853	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5545422868	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7223141811	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO5456522216	KU	5	35 BRN	SP	CRE	ED,ID,IP,SRS	TD		00:00.0
2021 PO5479822435	KU	3	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5470022342	KU	3	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO7241441816	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO5544622879	KU	3	45 KOP	SP	S		V		00:00.0
2021 PO7519742870	ODP	4	45 KOP	SP	CCA		V		00:00.0
2021 PO4935488775	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4934788762	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4936388790A	LGE	1	60 BRO	SP	CCA		V		00:00.0
2021 PO7525843035	ODP	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO7509342975	ODP	6	30 KOP	SP	CCA		V		00:00.0
2021 PO7522943163	ODP	4	40 KOP	SP	CRE		BD		00:00.0
2021 PO8296643701	ODP	5	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8321743760	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO8326544022	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO8340743920	ODP	5	35 XXX	SP	CRE		V		00:00.0
2021 PO8404044024	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8378544015	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8379344245	F	4	45 XXX	SP	P		V		00:00.0
2021 PO7505643045	ODP	4	40 KOP	SP	CRE	ED	TD		00:00.0
2021 PO5189222725	F	5	35 BRN	SP	A		V		00:00.0
2021 PO4924989671	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4926289666	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4927689662	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4923789679	LGE	4	40 BRN	SP	CRE	ED,ID,MD	BD		00:00.0
2021 PO4704889792	F	4	30 ACE	SP	P		V		00:00.0
2021 PO4703189847	F	4	30 ACE	SP	P		V		00:00.0
2021 PO7486843027	ODP	4	40 KOP	SP	S		V		00:00.0
2021 PO7861041776	ODP	5	30 BRO	SP	CCA		V		00:00.0
2021 PO5576519949	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO7853741603	ODP	6	30 BRO	SP	CRE	ED,ID,MD,SRC	TX	RR	00:00.0
2021 PO7877243148	ODP	5	35 BRO	SP	CRE		BX	RP1	00:00.0
2021 PO7867043460	ODP	4	45 BRO	SP	CRE	ED,ID,IP,MD,SRC	TX	RR	00:00.0
2021 PO7854541693	ODP	4	45 BRO	SP	CRE	ID	BD		00:00.0
2021 PO7845941927A	ODP	4	45 KOP	SP	CRE		BD		00:00.0
2021 PO5573819902	KU	5	35 OTH	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7950544581	ODP	4	40 XXX	SP	S		V		00:00.0
2021 PO7965044635	ODP	4	40 XXX	SP	S		V		00:00.0
2021 PO7976544676	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO4963889725	LGE	3	45 BRN	SP	P	ED,ID,MD	TD		00:00.0
2021 PO4965189719	LGE	4	35 BRN	SP	CCA	ED	TD		00:00.0
2021 PO6725910391	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7329749994	ODP	6	30 KOP	SP	CCA		V		00:00.0
2021 PO7345150046	ODP	4	45 KOP	SP	CCA		V		00:00.0
2021 PO4890189076	LGE	4	30 BRO	SP	CRE		V		00:00.0
2021 PO4727090042	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4764589474	LGE	1	20 ACE	SP	P		V		00:00.0
2021 PO4707090042	LGE	4	35 ACE	SP	P		V		00:00.0

2021	PO4705489658	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO7287950429	ODP	6	30 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021	PO5558822032	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO5549621936	F	4	35 BRN	SP	CRE		V	00:00.0
2021	PO7292850153	ODP	5	35 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021	PO7296849983	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021	PO4963689695	LGE	3	50 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO4964289710	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4961589684	LGE	3	45 BRN	SP	P		V	00:00.0
2021	PO4973489905	LGE	4	40 BRN	SP	P	ED	V	00:00.0
2021	PO4972989898	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO4973889932	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4973489927	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO4977389952	LGE	4	30 BRN	SP	A		V	00:00.0
2021	PO4974389958	LGE	4	35 BRN	SP	A		V	00:00.0
2021	PO4973889956	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO7348551181	F	4	40 KOP	SP	CRE		V	00:00.0
2021	PO7344551269	ODP	3	45 KOP	SP	CCA		V	00:00.0
2021	PO7311051939	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021	PO7947843685	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5095527872	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5124627890	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5512439144	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5485738502	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5601537450	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5609437929	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5602138244	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5595038548	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5305428112	KU	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021	PO5282428064	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6985171262	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6118420193	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2421477351	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO6114619904	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO6182019687	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5324921368	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2430076777	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2541177279	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2930672808	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2952672982	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5348921448	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5299632778	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4733612744	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO7346814209	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2880173582	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2891573861	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5326732926	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2325477620	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO6092719506	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3211817145	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5025513470	KU	3	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2909373640	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2366977876	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2345877747	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0

2021	PO3183716501	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3199116854	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2806774399	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2810474398	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7167669125	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7096572622	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7174972790	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7125568916	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7034466606	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7035266314	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021	PO7031266058	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7068766460	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7039266591	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7077169416	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO2390077953	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7076766236	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2810569488	KU	6	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2944872383	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2896972126	KU	2	55 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6110919646	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7002569454	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO7007269393	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO7052669338	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2929571567	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO7027065810	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO7004571243	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4986528094	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7275366571	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7274366301	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2916373441	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2924173223	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2493876519	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2520376681	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2929672159	KU	2	50 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4691612518	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4726610669	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2542376985	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO2466876356	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO3169616188	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2904273787	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2957572109	KU	2	50 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2931372578	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2949472538	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2956072489	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2932872407	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO3067070339	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021	PO3060270369	KU	2	55 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5442000434	KU	6	30 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021	PO5838289844	KU	2	50 BRN	SP	S	SRS	T	00:00.0
2021	PO5850289731	KU	2	50 BRN	SP	S	SRS	T	00:00.0
2021	PO5860989631	KU	2	50 BRN	SP	S	SRS	T	00:00.0
2021	PO5872189530	KU	2	50 BRN	SP	CCA	ED,SRS	T	00:00.0
2021	PO5931688986	KU	2	55 BRN	SP	CCA	ED	T	00:00.0
2021	PO5329428153	KU	4	40 BRO	SP	CRE	ED,ID	T	00:00.0

2021 PO2943872986	KU	4	40 XXX	SP	CCA	ED	T			00:00.0
2021 PO2957671904	KU	5	30 XXX	SP	CCA	ED	T			00:00.0
2021 PO2915072144	KU	4	45 XXX	SP	CCA	ED	T			00:00.0
2021 PO2980073905	KU	4	45 BRO	SP	CCA	ED	T			00:00.0
2021 PO5437701897	F	4	40 XXX	SP	CRE	ED,HH,ID	BX	RP1		00:00.0
2021 PO4075705319	F	4	40 BRN	SP	CRE	ID,IP	BX	RP2		00:00.0
2021 PO3975705803	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO5515202574	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	RP2		00:00.0
2021 PO5437302212	F	6	30 XXX	DF	CRE	ED,HH,ID	BX	PX		00:00.0
2021 PO5450401006	F	4	40 XXX	DF	CRE	ED,ID,MD,RB	BX	RP3		00:00.0
2021 PO5458501102	F	4	40 XXX	SP	CRE	ED,ID,MD	BX	RP3		00:00.0
2021 PO5466201191	F	4	40 XXX	SP	CRE	ED,ID	BX	RP2		00:00.0
2021 PO5617299481	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	PX		00:00.0
2021 PO5637199260	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021 PO5496101545	F	4	40 XXX	SP	CRE	ED,EP,ID,MD	BX	RP3		00:00.0
2021 PO3945305878	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO5506303525	F	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	BX	PX		00:00.0
2021 PO4010805964	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3943305670	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3979106119	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	PX		00:00.0
2021 PO3952306361	F	4	40 XXX	SP	CRE	ED,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO4037306281	F	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	BX	PX		00:00.0
2021 PO5517600086	F	4	40 XXX	SP	CRE	ED,HH,ID	BX	RP1		00:00.0
2021 PO3944105106	F	3	45 XXX	SP	CRE	ED,EP,HH,ID,IP	BX	RP3		00:00.0
2021 PO5609499566	F	4	40 XXX	SP	CRE	ED,ID,IP,MD	BX	RP3		00:00.0
2021 PO5503001616	F	4	40 XXX	SP	CRE	ED,EP,ID,MD	BX	RP3		00:00.0
2021 PO5510703172	F	4	40 XXX	SP	CRE	ED,HH,ID,MD,RB	BX	PX		00:00.0
2021 PO5535503183	F	4	40 XXX	SP	CRE	ED,HH,ID	BX	PX		00:00.0
2021 PO5578899834	F	4	40 XXX	SP	CRE	ED,EP,MD	BX	RP3		00:00.0
2021 PO5504303868	F	4	40 XXX	SP	CRE	ED,ID,MD	BX	RP2		00:00.0
2021 PO5512703846	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	PX		00:00.0
2021 PO3970307005	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3954206967	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3973707342	F	4	40 XXX	SP	P	ED,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO4009507452	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3958606674	F	4	40 BRN	SP	CRE	ED,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3979106653	F	4	40 XXX	SP	CRE	ED,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3946206371	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	RP2		00:00.0
2021 PO4002307429	F	4	40 BRN	SP	CRE	ED,ID,IP,MD,RB	BX	RP2		00:00.0
2021 PO3930807050	F	4	40 BRN	SP	CRE	ED,ID,IP,MD	BX	RP3		00:00.0
2021 PO3938107153	F	4	40 BRN	SP	CRE	ED,HH,ID,MD,RB	BX	PX		00:00.0
2021 PO3993606639	F	4	40 BRN	SP	CRE	ED,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3988007385	F	4	40 XXX	SP	CRE	ED,HH,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3985707053	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	RP1		00:00.0
2021 PO4014207165	F	4	40 XXX	SP	CRE	ED,EP,ID,IP,RB	BX	PX		00:00.0
2021 PO4010506622	F	4	40 BRN	SP	CRE	ED,ID,IP,MD,RB	BX	PX		00:00.0
2021 PO3956007617	F	4	40 XXX	SP	P	ED,ID,IP,MD,RB	BX	RP1		00:00.0
2021 PO4158204829	F	4	40 UNK	SP	CRE	ED,ID,IP,RB	BX	RP2		00:00.0
2021 PO4171406133	F	4	40 BRN	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021 PO5515800848	F	6	30 XXX	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021 PO5458901985	F	4	40 XXX	SP	CRE	ED,HH,ID,RB	BX	PX		00:00.0
2021 PO4199805932	F	4	40 UNK	SP	CRE	ED,ID,IP,MD	BX	RP3		00:00.0
2021 PO5508502460	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX		00:00.0
2021 PO5452404143	F	5	35 XXX	SP	CRE	ED,ID,RB	BX	PX		00:00.0

2021 PO5505301117	F	6	30 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO4105705454	F	4	40 BRN	SP	CRE	HH,ID,RB	BX	PX	00:00.0
2021 PO4105905289	F	4	40 BRN	SP	CCA	ED,HH,ID,RB	BX	PX	00:00.0
2021 PO4322987047	LGE	4	40 BRO	SP	A	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO4320487108	LGE	4	40 BRO	SP	A	ID,RB	BX	RP1	00:00.0
2021 PO4320987114	LGE	4	40 BRO	SP	A	ID,RB	BX	RP1	00:00.0
2021 PO2803176299	F	5	35 BRN	SP	CRE	ED,ID,RB	BX	RP3	00:00.0
2021 PO5539099980A	KU	5	35 XXX	SP	P	ED,ID	BD		00:00.0
2021 PO4079105006	F	4	40 BRN	SP	CRE	IP	BD		00:00.0
2021 PO4318987089	LGE	4	45 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4324887073	LGE	4	35 BRO	SP	CRE	ID	BD		00:00.0
2021 PO4325987081	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4324787065	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PV4301986721	LGE	2	50 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4302887064	LGE	3	50 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4328187025	LGE	3	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4327487067	LGE	2	50 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4297586834	LGE	1	55 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4313586927	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021 PO4327987071	LGE	4	35 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4329187087	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4317687163	LGE	2	50 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4328887034	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4329687043	LGE	2	55 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4305286999	LGE	4	30 ACE	SP	CCA		BD		00:00.0
2021 PO4328287059	LGE	4	40 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4329487043-A	LGE	5	35 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4323387053	LGE	4	40 BRO	SP	A	ID	BD		00:00.0
2021 PO4326387086	LGE	4	40 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO4316987154	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4316587148	LGE	2	55 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4315487135	LGE	2	50 BRO	SP	A	ID,IP	BD		00:00.0
2021 PO4326987094	LGE	4	40 BRO	SP	CRE	EP,ID	BD		00:00.0
2021 PO3042869638	KU	5	35 XXX	SP	CRE	ID	BD		00:00.0
2021 PO3043769363	F	4	40 XXX	SP	CRE	IP	BD		00:00.0
2021 PO5952318170	KU	4	35 BRO	SP	CCA	ED,ID,IP	BD		00:00.0
2021 PO6041517555	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO6023350675	KU	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021 PO6027050539	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4823690940	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO5295022527	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO4823790964	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO6020750536	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6026150377	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 2096066018a	KU	5	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5609806014	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5609205957	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5607105831	F	4	40 BRN	SP	CRE	HH,RB	VX	PX	00:00.0
2021 PO2119865917	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO2132765910	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5623905601	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5605105642	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5641405570	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5639305458	F	4	40 BRN	SP	CCA		V		00:00.0



2021	PO5647705378	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5652205269	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6021350382	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4823890987	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021	PO4823891010	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021	PO5666805809	KU	3	45 BRN	SP	P		V	00:00.0
2021	PO5664505818	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO1356671076	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4205804154	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4215004121	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4316687061	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4315987067	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO6226188036	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO6210688138	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO1482172991	KU	3	45 BRO	SP	CRE		V	00:00.0
2021	PO9583656842	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO9558356884	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021	PO1480372450	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4311187197	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO6072488536	KU	1	60 BRN	SP	CRE		V	00:00.0
2021	PO6083588586	KU	2	55 BRN	SP	CRE		V	00:00.0
2021	PO6098388647	KU	2	50 BRN	SP	CRE		V	00:00.0
2021	PO1476872587	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO1528971847	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9766355717	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9768056006	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9768656212	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6109988702	KU	2	45 BRN	SP	CCA		V	00:00.0
2021	PO9615855182	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO9618654979	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9563854340	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5040788654	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO5040688657	LGE	3H	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO1596572239	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4311687193	LGE	2	50 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4320287012	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4320887020	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4321587029	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4322487041	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO6163088416	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO6165188452	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO9531754369	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5044488771	LGE	3	45 BRN	SP	P		V	00:00.0
2021	PO5046088761	LGE	3	50 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO5046388753	LGE	5	25 BRN	SP	A	ED,ID	TD	00:00.0
2021	PO4310987153	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO1604871510	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5586504301	F	4	40 BRN	SP	CRE	ED,ID,IP,RB	VX	RP1 00:00.0
2021	PO2011767366	KU	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO6690387248	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6708886723	F	4	40 BRN	SP	CRE		BD	00:00.0
2021	PO6700486931	F	4	40 BRN	SP	P		V	00:00.0
2021	PO6697486644	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO7319597390	LGE	4	35 BRN	SP	CCA		V	00:00.0

2021 PO7359197497	LGE	1	50 BRN	SP	CCA		V		00:00.0
2021 PO1997367548	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO1986467550	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7940243511	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO7950743240	ODP	4	45 BRN	SP	CCA		V		00:00.0
2021 PO7959143149	ODP	6	30 BRN	SP	CCA		V		00:00.0
2021 PO7957643071	ODP	6	30 BRN	SP	CCA		V		00:00.0
2021 PO4792789455	F	4	30 ACE	SP	P		V		00:00.0
2021 PO4793089438	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO9367062000	KU	2	55 XXX	SP	CCA		V		00:00.0
2021 PO9368762038	KU	4	40 XXX	SP	CRE	ED,ID,IP	TX	RR	00:00.0
2021 PO9366962207	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9375762141	KU	4	40 XXX	SP	CCA	ED	T		00:00.0
2021 PO9389662240	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO9383262251	KU	2	50 XXX	SP	CCA		V		00:00.0
2021 PO9387762478	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9393662409	KU	4	40 XXX	SP	CCA	ED	T		00:00.0
2021 PO9403762551	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9429462573A	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9431662746	KU	6	30 XXX	SP	CRE		V		00:00.0
2021 PO9419058412	KU	5	35 BRN	SP	CRE		V		00:00.0
2021 PO9408758401	KU	6	30 BRN	SP	CRE		V		00:00.0
2021 PO9402558078	KU	1	65 BRN	SP	CCA		V		00:00.0
2021 PO9404758297	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO4799989474	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO9415958248	KU	4	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9433358338	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9148262048	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9158962001	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9325960066	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9164062055	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9169461901	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9170561763	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9158861788	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9158061948	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9144461908	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO9145461989	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9150761978	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9088562443	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9080762466	KU	2	65 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9063262631	KU	6	30 BRO	SP	CRE	ED	V		00:00.0
2021 PO9061162707	KU	2	50 BRO	ST	CRE		V		00:00.0
2021 PO9321060023	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO9313760241	KU	1	65 BRO	SP	CCA		V		00:00.0
2021 PO9318360093	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO4587103602	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4579503422	F	4	40 BRN	CRE	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4582303493	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4575403286	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4581703641	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO9306060088	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO9299360118	KU	5	35 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO9298959964	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO9215461632	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0

2021 PO9247961569	KU	4	40 OTH	SP	CCA		V	00:00.0
2021 PO4792189456	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO9231761599	KU	5	35 OTH	UN	CCA		V	00:00.0
2021 PO6288298641	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6310498533	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9438358394	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9301959823	KU	2	60 UNK	SP	CRE	HH,ID	TD	00:00.0
2021 PO9299259913	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9291860082	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9278759941	KU	1	55 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO9440758332	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO9440758332a	KU	5	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6299498586	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6325398838	F	2	45 XXX	SP	P		V	00:00.0
2021 PO6366898974	F	3	40 XXX	SP	P		V	00:00.0
2021 PO6342598921	F	2	45 XXX	SP	P		V	00:00.0
2021 PO6353398858	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6358998851	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6364698260	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6343498526	F	4	40 XXX	SP	CRE	ED,IP	V	00:00.0
2021 PO6356798295	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6345798348	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6337098407	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6384298727	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6389398695	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6367398802	F	4	40 XXX	CRE	CRE	ED,ID,IP,MD	BX	PX 00:00.0
2021 PO6431198431	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6420698492	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6410598568	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6400398632	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6384498585	F	4	40 XXX	SP	P		V	00:00.0
2021 PO6378098479	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6362498225	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6371898378	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6354298734	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6350398661	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9305061662	KU	4	40 OTH	SP	CCA		V	00:00.0
2021 PO9270661818	KU	5	35 OTH	SP	CRE	ID	TD	00:00.0
2021 PO9300362244	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9310261932	KU	3	45 OTH	SP	CCA	ED,SRS	TD	00:00.0
2021 PO9288061610	KU	5	35 OTH	SP	CCA		V	00:00.0
2021 PO9259461763	KU	4	45 OTH	SP	CCA	ED,SRS	TD	00:00.0
2021 PO9291961547	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9309562224	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9310062044	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021 PO9442258377	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9447058381	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4570503163	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1 00:00.0
2021 PO9069162225	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9000961611	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9192760374	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9265560131	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9259260044	KU	3	50 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9131261391	KU	4	45 BRO	SP	CCA		V	00:00.0

2021 PO4550102756	F	4	40 BRN	CRE	CRE	HH,ID,IP,RB	BX	RP2	00:00.0
2021 PO4557902874	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4566003033	KU	3	40 BRN	SP	CRE		V		00:00.0
2021 PO9390762300	KU	6	30 XXX	SP	CRE		V		00:00.0
2021 PO9449458257	KU	2	50 BRN	SP	CCA		V		00:00.0
2021 PO9453958176	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO9012961783	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8994261412	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8992061203	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO8991361021	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO9207560590	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4351603458	KU	4	40 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO4349703422	KU	4	40 BRN	SP	CRE		BD		00:00.0
2021 PO4352303540	KU	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4361203356	KU	4	40 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO4328803593	KU	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO9461058356a	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO9453058370	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO9461058356	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO9119461351	KU	4	45 BRO	SP	CCA		V		00:00.0
2021 PO9144861428	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO9132361602	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO9120461766	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO9157061258	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO9160161281	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO9138661123	KU	4	40 KOP	SP	S		V		00:00.0
2021 PO9201460671	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9317562637	KU	6	30 OTH	UN	CRE		V		00:00.0
2021 PO9312562382	KU	5	35 OTH	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO9303663231	F	5	35 OTH	SP	CRE		V		00:00.0
2021 PO9283863365	F	4	40 OTH	SP	CRE		V		00:00.0
2021 PO9332362915	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9321262940	KU	6	30 OTH	UN	CRE		V		00:00.0
2021 PO9331362789	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9320163080	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9329462578	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO4371505139	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4408205288	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4311805062	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4318604963	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4322605043	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4330804896	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4389705208	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4307705091	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4351605069	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO9112062129	KU	4	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO9477158334	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO9184860879	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9186560892	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9077162142	KU	3	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9066161998	KU	5	35 BRO	SP	S		V		00:00.0
2021 PO9111462100	KU	6	30 BRO	SP	CRE		V		00:00.0
2021 PO9123762054A	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO9123762054	KU	2	60 BRO	SP	CCA		V		00:00.0

2021 PO9113461917	KU	5	35 BRO	SP	CRE		V	00:00.0
2021 PO9109462031	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO9112462081	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9094162134	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9128862267	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO9489558382	KU	5	35 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO9126662206	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9107162194	KU	4	45 UNK	SP	CRE		V	00:00.0
2021 PO4822590360	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4816690327	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO9094962317	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9097162294	KU	4	40 UNK	SP	CRE		V	00:00.0
2021 PO9089362207	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9093662223	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9096762200	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4928890454	LGE	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO9105062243	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4432999509	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6441798381	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6453498310	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6436198282	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4270487957	LGE	3	50 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO9821491623	LGE	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO9822091681	LGE	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4803089498	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4802289497	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4800889479	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4943289259	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9359060919	KU	5	35 XXX	ST	CRE		V	00:00.0
2021 PO9609261407	KU	5	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4326199688	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4328299657	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4337500006	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4377499544	F	4	40 BRO	SP	CRE	ED,ID,IP	V	00:00.0
2021 PO4373599756	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4330999820	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4335299629	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4342599601	F	5	35 BRO	SP	CRE		V	00:00.0
2021 PO4352299503	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4370099486	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4345999361	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4341899265	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4332699058	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4333799032	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4486398703	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4499298960	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4509399216	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4503299389	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4498199266	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4492099293	F	5	35 BRO	SP	CRE	ED	V	00:00.0
2021 PO4493499158	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4480099008	F	5	35 BRO	SP	CRE	ED	V	00:00.0
2021 PO4486398987	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4480898863	F	4	40 BRO	SP	CRE	ED	V	00:00.0

2021	PO4469798774	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4475698749	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4470798633	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO9672562949	KU	6	30 OTH	SP	CCA	ED,SRS	TD	00:00.0
2021	PO4702404299	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO4718104378	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4708104444	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4697204175	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO6460499011	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6458899031	F	2	50 XXX	SP	P		V	00:00.0
2021	PO6466099224	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6476699500	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6469199478	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO6481399621	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6485499728	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6490499858	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6495199978	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6499400087	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6594298248	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6471599368	F	4	40 XXX	CCA	CCA	ED,HH,ID	BX PX	00:00.0
2021	PO6588798402	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6583498313	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6574398367	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6562898433	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6553198391	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6558398509	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6564898628	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6526798550	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6532798655	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6538698759	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6543098837	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6529998930	F	2	40 XXX	SP	CRE		V	00:00.0
2021	PO6542698881	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6556198830	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO9370061154	KU	5	35 XXX	SP	CRE		V	00:00.0
2021	PO9470462639	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO9499862507	KU	4	40 XXX	CRE	CRE	HH,ID	X PX	00:00.0
2021	PO9493462250	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO9485862052	KU	5	35 XXX	SP	CRE		V	00:00.0
2021	PO9429961632	KU	4	45 XXX	SP	CRE		V	00:00.0
2021	PO8927561239	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO8916661300	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO8930261360	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO8934961630	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3817106051	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3818506189	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5760501685	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5763501780	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5757201571	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5765901852	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5770103051	F	4	35 XXX	SP	CRE		V	00:00.0
2021	PO5769001956	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5771202027	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5772602062	F	4	35 XXX	SP	CRE		V	00:00.0

2021 PO6021354087	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6028753964	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6040453906	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7499146943	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4893290440	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO6018017540	LGE	6	30 BRO	SP	CRE		V	00:00.0
2021 PO4895290438	LGE	1	50 BRO	SP	CRE		V	00:00.0
2021 PO5398297378	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5395897574	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5384197584	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5188596658	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5389198003	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5397097968	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO5409497915	F	2	45 BRN	SP	P		V	00:00.0
2021 PO5427297837	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO6019553624	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6027253483	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6026753588	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6032353377	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6036153415	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4898090444	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4891090360	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4888490356	LGE	4	35 BRO	SP	A		V	00:00.0
2021 PO3892706451	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3891106313	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5206597392	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5233197209	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5756103481	F	2	55 XXX	SP	CRE		V	00:00.0
2021 PO5752503420	KU	3	40 XXX	SP	CRE		V	00:00.0
2021 PO5767503351	F	4	40 XXX	SP	CRE	ID,IP	V	00:00.0
2021 PO5780703237	F	4	45 XXX	SP	CRE	ID,IP	V	00:00.0
2021 PO5779403101	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5788603166	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO5795603104	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5801002934	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5762702817	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5761602751	F	4	35 XXX	SP	CRE		V	00:00.0
2021 PO5774202745	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5813502574	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5806602658	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO0545474685	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4838490120	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO0132973562	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0116673547	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4763690975	F	4	35 BRO	SP	A		V	00:00.0
2021 PO4762590984	F	4	35 BRO	SP	A		V	00:00.0
2021 PO0466373762	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0443174007	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO5245896940	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO5238396677	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5239896977	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5231996972	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO0498773543	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0521973387	KU	4	45 BRN	SP	CCA		V	00:00.0

2021 PO0130373792	F	3	35 BRO	SP	CRE	V	00:00.0
2021 PO0140573777	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO0158074250	KU	4	45 BRO	SP	S	V	00:00.0
2021 PO0133074143	KU	4	50 BRO	SP	CCA	V	00:00.0
2021 PO0581973031	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4843890131	LGE	4	40 BRN	SP	CCA	V	00:00.0
2021 PO0141774532	KU	4	45 BRO	SP	S	V	00:00.0
2021 PO0095574131	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO0056474118	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO5289197411	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5291997349	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5270797116	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5276097011	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5280796973	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4765891129	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO5296597255	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5304197222	F	3	40 BRN	SP	CRE	V	00:00.0
2021 PO5300997161	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4761689875	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO0022168059	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO5282896884	F	6	30 BRN	SP	CRE	V	00:00.0
2021 PO4735323252	LGE	4	40 BRN	SP	CCA	V	00:00.0
2021 PO3769005788	F	2	50 BRN	SP	CCA	V	00:00.0
2021 PO3806905642	F	4	45 BRN	SP	CRE	V	00:00.0
2021 PO3746006009	F	3	50 BRN	SP	CRE	V	00:00.0
2021 PO3737405969	F	2	55 BRN	SP	S	V	00:00.0
2021 PO3755505873	F	2	55 BRN	SP	CRE	V	00:00.0
2021 PO6059217334	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO5198098212	F	3	40 BRN	SP	CRE	V	00:00.0
2021 PO5225198095	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4830590394	LGE	1	55 BRO	SP	CCA	V	00:00.0
2021 PO4828290388	LGE	1	50 BRO	SP	CRE	V	00:00.0
2021 PO5212298778	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5224398756	F	4	40 MAR	SP	CRE	V	00:00.0
2021 PO5224098723	F	4	40 MAR	SP	CRE	V	00:00.0
2021 PO5234498677	F	3	45 MAR	SP	CRE	V	00:00.0
2021 PO5245398629	F	4	40 MAR	SP	CRE	V	00:00.0
2021 PO7638247653	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO2175061134a	KU	4	40 BRN	SP	CCA	V	00:00.0
2021 PO3857301612	KU	3	45 BRN	SP	S	V	00:00.0
2021 PO3848001808	KU	3	45 BRN	SP	CRE	V	00:00.0
2021 PO4137202243	F	2	60 BRN	SP	CRE	V	00:00.0
2021 PO4150802226	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4160002216	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4827790138	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021 PO4827090170	LGE	3	45 BRN	SP	P	V	00:00.0
2021 PO5347814512	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021 PO4827690147	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021 PO7168448206	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO7171348051	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO7202948146	KU	4	45 BRO	SP	CRE	V	00:00.0
2021 PO7213848124	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO5427396792	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5418696835	F	4	40 BRN	SP	CRE	V	00:00.0



2021 PO4781489687	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO3938502364	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3885902398	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3901402387	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3951102357	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3919602376	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4827690208	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4828790212	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4830990219	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4833190226	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5377697095	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5367897166	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5356997241	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5365097365	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4846190271	LGE	3	50 BRN	SP	P	ED	V	00:00.0
2021 PO4876890436	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO5715417402	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO4899090687	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4533306760	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2495376007	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO5338397374	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2484075903	KU	3	45 BRN	SP	CRE		V	00:00.0
2021 PO2486175781	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5325997520	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4561507408	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4524007023	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4553607224	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4545607257	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4576807762	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4537407074	F	3	30 BRN	SP	CRE		V	00:00.0
2021 PO4557807641	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4541606949	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4582707817	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4569607594	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4566707803	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5321897552	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5317197651	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5313397734	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5312697864	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5312997942	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7239448325	KU	4	45 BRO	SP	CRE	ED	V	00:00.0
2021 PO7227348292	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO7220448510	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO4906090668	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO4908390651	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO4908590647	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO1241061462	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO1288861025	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO1275861027	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO1280360742	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO4906590586	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO4866090435	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4868690438	LGE	1	50 BRO	SP	CRE		V	00:00.0
2021 PO7766047115	KU	5	35 BRO	SP	S		V	00:00.0

2021 PO7766047115	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO4869890430	LGE	3	50 BRO	SP	CCA	V	00:00.0
2021 PO4872290435	LGE	3	50 BRO	SP	CCA	V	00:00.0
2021 PO4874890438	LGE	1	50 BRO	SP	CRE	V	00:00.0
2021 PO4876390439	LGE	1	50 BRO	SP	CRE	V	00:00.0
2021 PO4907590298	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4908590301	LGE	4	40 BRN	SP	P	V	00:00.0
2021 PO4909690305	LGE	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5297598280A	F	5	45 BRN	SP	CRE	V	00:00.0
2021 PO5297598280	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO2390584717	KU	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4759590186	LGE	H1	75 BRN	SP	P	V	00:00.0
2021 PO5301798418A	F	2	30 BRN	SP	CRE	V	00:00.0
2021 PO3903205308	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO3931605352	F	3	40 BRN	SP	CRE	V	00:00.0
2021 PO3961505282	F	3	40 BRN	SP	CRE	V	00:00.0
2021 PO7208848677	KU	4	45 BRO	SP	CCA	V	00:00.0
2021 PO4802190408	LGE	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4802390399	LGE	2	55 BRO	SP	CCA	V	00:00.0
2021 PO4803090375	LGE	3	50 BRO	SP	CCA	V	00:00.0
2021 PO3893906587	F	4	40 BRN	SP	CCA	V	00:00.0
2021 PO7486146792B	KU	5	35 KOP	SP	S	V	00:00.0
2021 PO7486146792A	KU	4	40 BRO	SP	S	V	00:00.0
2021 PO7492046617	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO5393498220	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO5410098421	KU	4	30 BRN	SP	CCA	V	00:00.0
2021 PO5410698362	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO6038253271	F	4	40 BRO	SP	P	V	00:00.0
2021 PO6043753317	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5662498245	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5692998322	KU	6	30 XXX	SP	S	V	00:00.0
2021 PO5687698135	F	2	45 XXX	SP	P	V	00:00.0
2021 PO5711598050	F	2	45 XXX	SP	P	V	00:00.0
2021 PO5728797931	F	4	45 XXX	SP	P	V	00:00.0
2021 PO5776901103	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO0188174399	KU	4	45 BRO	SP	CCA	V	00:00.0
2021 PO5577098095	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5600798122	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5612598136	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5624598148	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5648998177	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5672598169	F	4	40 XXX	SP	P	V	00:00.0
2021 PO0852971114	F	4	40 XXX	SP	CCA	V	00:00.0
2021 PO0876670162	KU	5	35 XXX	SP	CCA	V	00:00.0
2021 PO0859670249	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO0827870394	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO0822372739	F	4	40 XXX	SP	P	V	00:00.0
2021 PO0790473262	F	4	40 XXX	SP	P	V	00:00.0
2021 PO0800973332	F	4	40 XXX	SP	P	V	00:00.0
2021 PO1175266621	F	5	35 XXX	SP	CRE	V	00:00.0
2021 PO4787690903	LGE	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4789990914	LGE	2	55 BRN	SP	CCA	V	00:00.0
2021 PO4793390920	LGE	4	45 BRN	SP	CCA	V	00:00.0
2021 PO4793290927	LGE	3	45 BRN	SP	CCA	V	00:00.0

2021 PO4795490934	LGE	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4831319548	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4775990672	LGE	3	45 BRN	SP	P		V	00:00.0	
2021 PO4774590680	LGE	3	45 BRN	SP	P		V	00:00.0	
2021 PO0330775803	KU	4	45 BRO	SP	CCA		V	00:00.0	
2021 PO4777989985	LGE	UNK	45 BRN	SP	CCA		V	00:00.0	
2021 PO4777489997	LGE	3	50 BRN	SP	CCA		V	00:00.0	
2021 PO0439075268	F	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO0476475066	KU	6	30 BRO	SP	CCA		V	00:00.0	
2021 PO0480775363A	KU	3	35 BRO	SP	CCA		V	00:00.0	
2021 PO0480775363	KU	4	50 BRO	SP	CCA		V	00:00.0	
2021 PO5723401377	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5755901217	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5806500943	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5766401161	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5789001036	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5800100977	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5745001278	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5768101509	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5774701471	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5786601404	F	4	45 XXX	SP	CRE		V	00:00.0	
2021 PO5818801890	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5814501960	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5804201980	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5806102081	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO5345700884	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4879090880	LGE	4	40 BRN	SP	P		V	00:00.0	
2021 PO5140097252	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5146197446	F	4	40 BRN	SP	P		V	00:00.0	
2021 PO5151397608	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5153497677	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5160097884	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO6254850902	KU	2	45 BRO	SP	S		V	00:00.0	
2021 PO6247951147	KU	4	40 BRO	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO8141046077	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5167098106	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5173898322	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO2728187318	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5175698378	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5179198488	F	2	45 BRN	SP	CRE	HH,ID,RB	VX	RP3	00:00.0
2021 PO5182098579	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5185498689	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO6225851315	KU	1	80 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO5002599224	KU	5	35 BRN	SP	CRE	ED	TD		00:00.0
2021 PO7910547143	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4805490296	LGE	2	55 BRO	SP	CCA		V		00:00.0
2021 PO4759919339	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4762790661	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4949513703	LGE	1	50 BRN	SP	CCA		V		00:00.0
2021 PO4755190731	LGE	4	45 BRN	SP	P		V		00:00.0
2021 PO5270600989	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5290300934	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5302300901	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5315600867	F	4	40 BRN	SP	CRE		V		00:00.0

2021	PO5328800834	F	4	40 BRN	SP	P	V	00:00.0
2021	PO5343100794	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4754290703	LGE	4	30 BRN	SP	P	V	00:00.0
2021	PO7273348634	KU	5	35 BRO	SP	CCA	V	00:00.0
2021	PO5356800755	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5395600645	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5406800593	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5424600510	F	4	40 BRN	SP	CCA	V	00:00.0
2021	PO5405800899	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4781489816	LGE	4	30 BRN	SP	CCA	V	00:00.0
2021	PO4780989798	LGE	1	50 BRN	SP	CCA	V	00:00.0
2021	PO7311049148	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO3949604914	KU	3	45 BRN	SP	CRE	V	00:00.0
2021	PO5517996348	F	3	40 BRN	SP	CCA	V	00:00.0
2021	PO5522296363	F	2	40 BRN	SP	P	V	00:00.0
2021	PO5657203079	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5667603298	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5662403202	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5674103416	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5622302440	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5651602977	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5646402884	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5634102655	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5617002340	F	4	40 XXX	SP	CRE	ED V	00:00.0
2021	PO5638801693	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5609801408	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO0421977139	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO4764789611	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4762189609	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021	PO0423377500	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO0376175878	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO7223349348	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO7478846954	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO4830690404	LGE	3	50 BRO	SP	CCA	V	00:00.0
2021	PO4826390379	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO4824690371	LGE	3	50 BRO	SP	CCA	V	00:00.0
2021	PO4835090406	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO4860090541	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO4906890437	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO4905290438	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO4903590438	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO4902790498	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO3829005634	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO3887305889	F	6	30 BRN	SP	S	V	00:00.0
2021	PO3881105487	F	3	45 BRN	SP	A	V	00:00.0
2021	PO5812501197	F	3	40 XXX	SP	CRE	V	00:00.0
2021	PO4904190681	LGE	4	40 BRN	SP	A	V	00:00.0
2021	PO5417497207	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5417897235	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4889290440	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4891190438	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO5411997532	F	2	40 BRN	SP	CRE	V	00:00.0
2021	PO5386501317	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5395901563	F	4	40 BRN	SP	CRE	V	00:00.0

2021 PO4811590095	LGE		1	60 BRN	SP	CCA	V	00:00.0
2021 PO5400601689	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO5405501812	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO4727290330	LGE		3	45 BRN	AL	CCA	V	00:00.0
2021 PO5199713744	LGE		4	35 BRN	SP	CCA	V	00:00.0
2021 PO5421097448	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO6045053153	F		4	40 BRO	SP	CRE	V	00:00.0
2021 PO5263716373	LGE		3	45 BRO	SP	CCA	V	00:00.0
2021 PO4820590349	F		4	30 BRO	SP	CCA	V	00:00.0
2021 PO4818990342	LGE		3	45 BRO	SP	CCA	V	00:00.0
2021 PO4815190316	LGE		3	45 BRO	ST	P	V	00:00.0
2021 PO7496946106	KU		4	40 BRO	SP	CCA	V	00:00.0
2021 PO7508145827	KU		4	40 BRO	SP	S	V	00:00.0
2021 PO5353416920	LGE		4	35 BRO	SP	CCA	V	00:00.0
2021 PO5809817380	LGE		3	50 BRO	SP	CCA	V	00:00.0
2021 PO4874590434	LGE		3	50 BRO	SP	CCA	V	00:00.0
2021 PO5791117322	LGE		1	50 BRO	SP	CCA	V	00:00.0
2021 PO4867890432	LGE		2	60 BRO	SP	CCA	V	00:00.0
2021 PO0522874792	KU		3	45 BRN	SP	CCA	V	00:00.0
2021 PO5303596629	F		5	35 BRN	SP	CRE	V	00:00.0
2021 PO4750690189	LGE	UNK		70 BRN	ST	CCA	V	00:00.0
2021 PO5278096555	F		2	45 BRN	SP	CRE	V	00:00.0
2021 PO5289096518	F		2	45 BRN	SP	CRE	V	00:00.0
2021 PO5295896498	F		2	45 BRN	SP	CRE	V	00:00.0
2021 PO5297096495	KU		4	40 BRN	SP	CCA	V	00:00.0
2021 PO5291396357	KU		3	45 BRN	SP	CCA	V	00:00.0
2021 PO5290996347	KU		4	40 BRN	SP	CCA	V	00:00.0
2021 PO0761070636	F		5	35 XXX	SP	CCA	V	00:00.0
2021 PO4855190154	LGE		4	45 BRN	SP	P	V	00:00.0
2021 PO4840490124	LGE		4	40 BRN	SP	CCA	V	00:00.0
2021 PO4828890100	LGE		4	25 BRN	SP	CCA	V	00:00.0
2021 PO4828790100	LGE		4	30 BRN	SP	CCA	V	00:00.0
2021 PO4768290093	LGE	H3		110 ACE	SP	CRE	V	00:00.0
2021 PO4745213908	LGE		4	40 ACE	SP	CCA	V	00:00.0
2021 PO0127672748	KU		4	40 BRO	SP	CCA	V	00:00.0
2021 PO5226496707	F		3	45 BRN	SP	CRE	V	00:00.0
2021 PO4765891174	LGE		4	40 BRO	SP	CCA	V	00:00.0
2021 PO5202696798	F		2	40 BRN	SP	CRE	V	00:00.0
2021 PO5204496904	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO5215296749	F		3	45 BRN	SP	CRE	V	00:00.0
2021 PO5204697008	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO5205897245	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO5205397128	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO5206597496	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO5226497352	F		3	45 BRN	SP	CRE	V	00:00.0
2021 PO5220897497	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO5561414379	LGE		3	45 BRN	SP	CCA	V	00:00.0
2021 PO4769991015	LGE		4	40 BRO	SP	CCA	V	00:00.0
2021 PO0014669236	KU		6	30 BRO	UN	CRE	V	00:00.0
2021 PO0021169054	KU		3	45 BRO	SP	CCA	V	00:00.0
2021 PO4618811874	LGE		3	45 ACE	SP	CCA	V	00:00.0
2021 PO5202197939	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO5199998079	F		4	40 BRN	SP	CRE	V	00:00.0
2021 PO5238897642	F		4	40 BRN	SP	CRE	V	00:00.0

2021	PO5245297671	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5258497606	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO0640968013	KU	5	30 XXX	SP	CCA		V	00:00.0
2021	PO0146975620	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO0149975321	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO0128575183	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO0120775203	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO0009968116	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO0012268074	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO0017668064	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO0062167801	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO0083167616	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO0105967389	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO0132067137	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO0154266920	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5285296936	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5287496981	F	6	30 BRN	SP	CCA		V	00:00.0
2021	PO5325997079	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO5315797153	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4765289858	LGE	4	40 ACE	SP	CRE	ED,ID	V	00:00.0
2021	PO5334897015	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO5321996696	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5310696759	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5315096844	F	3	40 BRN	SP	P		V	00:00.0
2021	PO5344096947	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO5332596638	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5356096859	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO5363396860	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4012698782	F	2	50 BRN	SP	CRE		V	00:00.0
2021	PO3999098394	KU	2	55 BRN	SP	A		V	00:00.0
2021	PO4017198917	KU	2	50 BRN	SP	CRE		V	00:00.0
2021	PO3987998072	KU	2	50 BRN	SP	CRE		V	00:00.0
2021	PO3993698234	KU	2	50 BRN	SP	CRE		V	00:00.0
2021	PO4005798584	F	2	50 BRN	SP	A		V	00:00.0
2021	PO4020499020	KU	2	50 BRN	SP	CRE		V	00:00.0
2021	PO3983597939	F	2	50 BRN	SP	CRE		V	00:00.0
2021	PO4876290233	LGE	4	40 BRN	SP	P		V	00:00.0
2021	PO4762089864	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO3724206055	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO3784305698	F	3	50 BRN	SP	CRE		V	00:00.0
2021	PO3691406264	F	1	65 BRN	SP	CRE		V	00:00.0
2021	PO3824805584	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3840305527	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO3711306128	F	2	60 BRN	SP	CCA		V	00:00.0
2021	PO3969602345	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4001702308	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4843990263	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4841990256	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4775989714	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4106302262	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4906790598	LGE	4	40 BRN	SP	P		V	00:00.0
2021	PO5367298043	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5323398234	F	4	35 BRN	SP	CRE		V	00:00.0
2021	PO5336998121	F	5	35 BRN	SP	CRE		V	00:00.0

2021	PO5341997830	F	5	35 BRN	SP	CRE		V	00:00.0
2021	PO5348897838	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5355397869	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5363797957	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4906290572	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4905490532	LGE	4	40 BRN	SP	A		V	00:00.0
2021	PO5355298151	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO5340398216	F	3	45 BRN	SP	A		V	00:00.0
2021	PO5327998271	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5314098330	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4561507191	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4573207358	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4584607530	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4770589710	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO5349997738	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5364697687	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4587607719	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4598107837	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4556806883	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4553607007	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4905090512	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5234598054	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5228497916	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5278497845	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO4904190468	LGE	3	45 BRN	SP	P	ED,ID	V	00:00.0
2021	PO5249797986	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3694506011	KU	2	50 BRN	SP	S		V	00:00.0
2021	PO3716406682	KU	2	50 BRN	SP	S		V	00:00.0
2021	PO3693406743	KU	2	50 BRN	SP	S		V	00:00.0
2021	PO3693406743	KU	2	50 BRN	SP	S		V	00:00.0
2021	PO2539285422	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO2561385312	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO4776890000	LGE	H1	105 BRN	ST	CCA		V	00:00.0
2021	PO4775290014	LGE	4	45 BRN	SP	P		V	00:00.0
2021	PO4771590062	LGE	H1	90 BRN	SP	P		V	00:00.0
2021	PO4774090033	LGE	H1	95 BRN	SP	P		V	00:00.0
2021	PO4754690196	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021	PO2508884837	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3726606875	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5301798418	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5301898384	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5305598426	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5217899052	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5213399580	KU	2	45 BRN	SP	CCA		V	00:00.0
2021	PO4911590311	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4913390318	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4915590325	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4917890333	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4919790339	LGE	4	40 BRN	SP	P		V	00:00.0
2021	PO4921890346	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4922390344	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4762390154	LGE	H1	80 BRN	SP	P		V	00:00.0
2021	PO7201348613	F	3	35 BRO	SP	P	ED	V	00:00.0
2021	PO7212248524	F	4	40 BRO	SP	CCA		V	00:00.0

2021 PO3751007250	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4773789666	LGE	4	30 ACE	SP	P		V	00:00.0
2021 PO4884390440	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4882790440	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4881190440	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4878690442	LGE	1	50 BRO	SP	CRE		V	00:00.0
2021 PO7750947121	KU	4	45 BRO	SP	S		V	00:00.0
2021 PO7179148380	KU	4	40 BRO	SP	S		V	00:00.0
2021 PO7163148405	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO3773207592	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7036046733	KU	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7027146924	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7018046936	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO4377585802	LGE	4	45 BRN	SP	CRE		V	00:00.0
2021 PO4379385781	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4380585765	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3958699964	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO6487847655	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6493147632	KU	5	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4381385755	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4382185744	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4381485739	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4380785733	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4380085728	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4379285723	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4377885749	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4376685741	LGE	4	45 BRN	SP	CRE		V	00:00.0
2021 PO4375485732	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4375085738	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4374785742	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4311398607	F	3	45 BRO	SP	CRE	ED	V	00:00.0
2021 PO4373985752	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO6773540432	F	4	40 BRO	DF	P	ED	V	00:00.0
2021 PO6774840705	F	4	40 BRO	SP	P	ED,ID	V	00:00.0
2021 PO6776140965	F	4	40 BRO	SP	P	ED,ID	V	00:00.0
2021 PO6777141253	F	4	40 BRO	SP	P	ED,ID	V	00:00.0
2021 PO6777441387	F	4	40 BRO	SP	P	ED,ID	V	00:00.0
2021 PO6805740243	F	4	40 BRO	SP	CRE	ED,ID	V	00:00.0
2021 PO6819140136	F	4	40 BRO	SP	P	ED,ID	V	00:00.0
2021 PO5895802722	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6971647480	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6534647441	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4448686053	F	3	45 BRN	SP	P		V	00:00.0
2021 PO4335787048	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO6776149222	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO4449186054	F	3	45 BRN	SP	P		V	00:00.0
2021 PO6764349046	F	6	30 BRN	SP	CRE		V	00:00.0
2021 PO6764349046	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7363747750	F	4	40 SWP	SP	P		V	00:00.0
2021 PO4821490368	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5281216707	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4450586167	F	4	40 BRN	SP	P		V	00:00.0
2021 PO7353847301	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO3852100845	KU	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0



2021	PO4334387061	LGE	4	40 BRN	SP	CRE	ED,IP	BD		00:00.0
2021	PO4908991185	LGE	4	40 BRN	SP	A		V		00:00.0
2021	PO4211388223	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021	PO5543393637	F	2	50 BRN	SP	CRE		V		00:00.0
2021	PO4893391096	LGE	3	50 BRN	SP	A		V		00:00.0
2021	PO4895191105	LGE	3	50 BRN	SP	A		V		00:00.0
2021	PO4897291106	LGE	3	55 BRN	SP	A		V		00:00.0
2021	PO4896891080	LGE	4	35 BRN	SP	A		V		00:00.0
2021	PO3784796813	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO3767700327	KU	3	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO5553393901	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO5526793925	F	5	35 BRN	SP	CRE		V		00:00.0
2021	PO7763945842A	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021	PO7768445676	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO7753545638	KU	3	40 BRO	SP	CCA		V		00:00.0
2021	PO7768046332	KU	4	45 KOP	SP	CRE	ID	BD		00:00.0
2021	PO7103347344	F	4	40 BRO	SP	S		V		00:00.0
2021	PO7105747050	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO7109547193	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO7111847831	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO6500348755	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO6489048832	KU	4	40 BRN	SP	CRE	RB	BX	PX	00:00.0
2021	PO5498394467	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5566794207	F	2	45 BRN	SP	CRE		V		00:00.0
2021	PO4206988215	LGE	2	55 BRN	SP	A	ID,IP	BD		00:00.0
2021	PO7111747869	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO7112047905	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO7112347958	KU	2	70 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO7066647918	KU	6	30 XXX	SP	CCA	ED	T		00:00.0
2021	PO7071147857	KU	5	35 XXX	SP	CRE	ED,ID	X	RP2	00:00.0
2021	PO3819101198	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO3789001639	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO3794301447	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO3806901304	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO3832901155	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4209588205	LGE	1	60 BRN	SP	CRE	ID,IP	BD		00:00.0
2021	PO4452586155	LGE	3	45 BRN	SP	CRE	ED,ID	B		00:00.0
2021	PO4452586155A	LGE	2	50 BRN	SP	CCA		V		00:00.0
2021	PO1680073998	LGE	1	50 BRN	SP	CRE		V		00:00.0
2021	PO4459586093	LGE	3	45 BRN	SP	P	ED,ID	BD		00:00.0
2021	PO7408847147	F	4	40 UNK	SP	CCA		V		00:00.0
2021	PO3787002073	KU	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO3788801870	F	2	45 BRN	SP	CRE		V		00:00.0
2021	PO3822503947	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO7780745609	KU	6	30 UNK	SP	CRE		V		00:00.0
2021	PO5542794278	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5529193984	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5531994049	F	5	35 BRN	SP	CRE		V		00:00.0
2021	PO5522894013	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5531694325	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5512894065	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5520494373	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO7070447638	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO7419647125	F	3	40 UNK	SP	P		V		00:00.0

2021 PO7446247078A	KU	3	40 SWP	SP	CCA		V	00:00.0	
2021 PO7446247078	F	4	40 SWP	SP	P		V	00:00.0	
2021 PO7463847027	F	4	40 KOP	SP	P		V	00:00.0	
2021 PO7494047107	KU	5	35 BRO	SP	CCA		V	00:00.0	
2021 PO7493347044	KU	5	35 BRO	SP	CCA		V	00:00.0	
2021 PO6454049210	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO6452349358	KU	5	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO6451949304	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO6495549340	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO6735449021	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0	
2021 PO4453686108	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0	
2021 PO6737149141A	F	4	30 BRN	SP	CRE		V	00:00.0	
2021 PO6736349094	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0	
2021 PO6737149141	KU	4	35 BRN	SP	CRE	ED	TD	00:00.0	
2021 PO4228798735	F	4	40 BRN	SP	CRE	ED	V	00:00.0	
2021 PO7058147641	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO7052347643	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0	
2021 PO3826802129	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO3803902184	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO3833902126	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO3773602557	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO3789402270	F	2	45 BRN	SP	CRE		V	00:00.0	
2021 PO3814602133	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO7069047197	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO7068747113	KU	4	40 XXX	SP	CCA		V	00:00.0	
2021 PO7068547013	KU	4	45 XXX	SP	CCA		V	00:00.0	
2021 PO6487548545	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5502194119	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5509594419	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5491494178	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5480694229	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5484194526	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5469794282	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4078384404	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO6490748458	KU	4	40 BRN	SP	CRE	RB	X	PX	00:00.0
2021 PO6494048493	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO6499848532	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO3790903665	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO3786303413	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO3797903284	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP2	00:00.0
2021 PO5599000337	KU	6	30 XXX	SP	S		V	00:00.0	
2021 PO5687598996	F	4	45 XXX	SP	S		V	00:00.0	
2021 PO5694098944	F	4	45 XXX	SP	S		V	00:00.0	
2021 PO5703698672	F	4	45 XXX	SP	P		V	00:00.0	
2021 PO569898537	F	3	40 XXX	SP	P		V	00:00.0	
2021 PO6908547606	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO6431449512	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO6475049554	F	5	30 BRN	SP	P		V	00:00.0	
2021 PO4212788206	LGE	2	50 BRN	SP	CRE	ID,IP	BD	00:00.0	
2021 PO6688849024	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0	
2021 PO6702849164A	F	5	30 BRN	SP	A		V	00:00.0	
2021 PO6720149287	KU	5	35 BRN	SP	CCA		V	00:00.0	
2021 PO6703149247	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021 PO3737001042	F	4	40 BRN	SP	CRE		V	00:00.0	

2021 PO3750300921	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO3806200708	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO3816600658	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO3794600764	F	2	50 BRN	SP	CRE		V		00:00.0
2021 PO3783200820	KU	4	40 BRN	SP	S		V		00:00.0
2021 PO3748600986	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3834400572	F	2	50 BRN	SP	CRE		V		00:00.0
2021 PO3760100931	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3842400710	F	2	50 BRN	SP	CRE		V		00:00.0
2021 PO2847990360A	F	3	45 XXX	SP	P		V		00:00.0
2021 PO4338887035	F	UNK	50 ACE	SP	CRE		V		00:00.0
2021 PO7023347653	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO6907847162	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4308587047	LGE	3	50 ACE	SP	CRE	ED,HH,ID,RB	X	RP1	00:00.0
2021 PO4305087059	LGE	1	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO4300387091	LGE	1	50 ACE	SP	CRE	ED,ID	TD		00:00.0
2021 PO9152194386	F	3	50 BRN	SP	CCA		V		00:00.0
2021 PO5708593121	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5688993256	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5679093303	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5668193354	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO4448385794	LGE	4	45 BRN	SP	CRE		V		00:00.0
2021 PO4102584058-a	LGE	3	40 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO4102584058	LGE	4	40 BRN	SP	A	ED,ID	TD		00:00.0
2021 PO7096747631	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO7092147632	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5091784920	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4477485830	LGE	5	35 BRN	SP	CRE		V		00:00.0
2021 PO4477885807	LGE	1	65 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5616093957	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5602394025	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5591094080	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5583094115	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5628693895	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5634993863	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO5641793831	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO3867002406	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3865002772	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3867703131	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3863102490	F	4	40 BRN	SP	CRE	IP	V		00:00.0
2021 PO3866202910	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3864102616	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3862702408	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO3867003021	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5763192741	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO5755992825	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO5750292935	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO0036280097	KU	4	40 BRO	SP	CRE		V		00:00.0
2021 PO9980880208	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7155149345	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5743493608	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3874504269	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO7091347417	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO7091147332	KU	5	35 XXX	SP	CRE	ID,RB	TX	RR	00:00.0

2021	PO7082547191	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO7095647189	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1328469496	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO6467348260	KU	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO5008288747	LGE	3H	45 BRN	SP	A		V	00:00.0
2021	PO5005388735	LGE	3H	45 BRN	ST	CCA		V	00:00.0
2021	PO5003088726	LGE	3H	45 BRN	SP	A	ID	BD	00:00.0
2021	PO4095884110	LGE	UNK	30 BRN	SP	CRE		V	00:00.0
2021	PO7756846889	F	4	40 UNK	SP	P		V	00:00.0
2021	PO7755446940	F	4	40 KOP	SP	P		V	00:00.0
2021	PO7753847009	F	5	40 UNK	SP	CRE		V	00:00.0
2021	PO7780946918	F	4	40 KOP	SP	P		V	00:00.0
2021	PO7576846988	KU	5	35 UNK	SP	CRE	ED,HH,ID	BX PX	00:00.0
2021	PO5657593388	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5646193387	F	2	50 BRN	SP	CRE		V	00:00.0
2021	PO5628993349	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO5619093296	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5602493084	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO7139700586	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO7133500553	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO6465448290	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7110547475	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO4086884172	LGE	UNK	45 BRN	SP	A		V	00:00.0
2021	PO5892094901	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3803202828	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO5627095692	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3848203189	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5547196105	KU	2	55 BRN	SP	P		V	00:00.0
2021	PO5549696235	KU	2	55 BRN	SP	P		V	00:00.0
2021	PO5546596327	KU	2	55 BRN	SP	P		V	00:00.0
2021	PO5535696407	KU	2	55 BRN	SP	P		V	00:00.0
2021	PO3909296707	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO3939896601	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO3948696571	KU	6	30 BRN	SP	S		V	00:00.0
2021	PO4757291019	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4758391012	F	4	40 BRO	SP	A		V	00:00.0
2021	PO4759191007	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4760291002	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4761390993	F	4	35 BRO	SP	A		V	00:00.0
2021	PO5206297645	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO5204797784	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO0014082686	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9943982636	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO9935382752	KU	4	45 BRO	SP	S		V	00:00.0
2021	PO9922282931	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021	PO4765090964	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX RR	00:00.0
2021	PO39222396120A	KU	3	45 BRN	SP	CRE		V	00:00.0
2021	PO5247205905	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO6045804026	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4896889063	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO8784022354	ODP	4	45 KOP	SP	CRE		V	00:00.0
2021	PO4928790240	LGE	4	40 BRN	SP	P		V	00:00.0
2021	PO5564720511	KU	6	35 BRN	SP	CCA		V	00:00.0
2021	PO6031217666	ODP	4	45 BRO	SP	CCA		V	00:00.0

2021 PO6019417652	ODP	4	45 BRO	SP	CCA	V	00:00.0
2021 PO7290416370	ODP	4	40 KOP	SP	CCA	V	00:00.0
2021 PO5308410187	KU	4	40 BRN	SP	S	V	00:00.0
2021 PO5548920757	KU	4	45 OTH	SP	CCA	V	00:00.0
2021 PO5545620657	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO7268316501	ODP	4	40 KOP	SP	CCA	V	00:00.0
2021 PO7325216270	ODP	4	45 KOP	SP	CCA	V	00:00.0
2021 PO0283837937	F	5	35 BRO	SP	CRE	V	00:00.0
2021 PO7299216107	ODP	4	45 KOP	SP	S	V	00:00.0
2021 PO4818488870	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021 PO4818888862	LGE	4	30 BRO	SP	P	V	00:00.0
2021 PO4819888873	LGE	3	50 BRN	SP	CCA	V	00:00.0
2021 PO4821788872	LGE	4	30 BRN	SP	CCA	V	00:00.0
2021 PO4821488879	LGE	3	50 BRN	SP	CCA	V	00:00.0
2021 PO5308910240	KU	6	30 BRN	SP	CRE	V	00:00.0
2021 PO7278415977	ODP	4	45 KOP	SP	CCA	V	00:00.0
2021 PO7303215345	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7323815450	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7360215560	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7397415581	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7430815597	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO6673009561	LGE	4	40 ACE	UN	CCA	V	00:00.0
2021 PO7468415553	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7494615470	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7519815591	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7543815699	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7552116191	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7568615814	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO5536820578	KU	5	35 BRN	SP	CCA	V	00:00.0
2021 PO7537115166	F	4	40 KOP	SP	CRE	V	00:00.0
2021 PO7287315491	ODP	5	35 KOP	SP	S	V	00:00.0
2021 PO4954989637	LGE	7	25 ACE	SP	A	V	00:00.0
2021 PO4958489645	LGE	4	30 ACE	UN	CCA	V	00:00.0
2021 PO4942990014	LGE	4	30 BRN	SP	CCA	V	00:00.0
2021 PO4942190013	LGE	3	50 BRN	SP	CCA	V	00:00.0
2021 PO4834389549	LGE	4	45 BRN	SP	CRE	V	00:00.0
2021 PO4834389547	LGE	4	45 BRN	SP	P	V	00:00.0
2021 PO5427908395	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4832089507	LGE	3	60 BRN	SP	P	V	00:00.0
2021 PO4831389524	LGE	2	75 BRN	SP	CRE	V	00:00.0
2021 PO4942790145	LGE	3	45 BRN	SP	A	V	00:00.0
2021 PO4938090131	LGE	3	45 BRN	SP	A	V	00:00.0
2021 PO5400609000	KU	2	50 BRN	SP	S	V	00:00.0
2021 PO5303408278	KU	3	45 BRN	SP	CRE	V	00:00.0
2021 PO5276407918	KU	5	35 BRN	SP	CRE	V	00:00.0
2021 PO5405409187	KU	3	45 BRN	SP	CRE	V	00:00.0
2021 PO5402409068	KU	2	50 BRN	SP	S	V	00:00.0
2021 PO4966789643	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4966189632	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4936690118	LGE	4	40 BRN	SP	P	V	00:00.0
2021 PO4934890142	LGE	3	45 BRN	SP	P	V	00:00.0
2021 PO4965689625	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4965189616	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4722589871	LGE	3	45 ACE	SP	CCA	V	00:00.0

2021 PO4723289861	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO4723989849	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4965789597	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO5407307914	KU	3	50 BRN	SP	CRE	V	00:00.0
2021 PO5426107849	KU	4	45 BRN	SP	CCA	V	00:00.0
2021 PO5422207810	F	6	30 BRN	SP	CRE	V	00:00.0
2021 PO5423707856	F	2	40 BRN	SP	CRE	V	00:00.0
2021 PO5417207874	F	4	45 BRN	SP	CRE	V	00:00.0
2021 PO4921888972	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4834889441	LGE	2	25 BRN	SP	CRE	V	00:00.0
2021 PO4834189452	LGE	2	60 BRN	SP	CRE	V	00:00.0
2021 PO4834889434	LGE	2	60 BRN	SP	P	V	00:00.0
2021 PO4824089356	LGE	2	65 BRN	SP	CCA	V	00:00.0
2021 PO4821589351	LGE	2	65 BRN	SP	CRE	V	00:00.0
2021 PO5364407913	F	3	45 BRN	SP	CRE	V	00:00.0
2021 PO5371607904	F	3	45 BRN	SP	CRE	V	00:00.0
2021 PO5374808010	F	4	45 BRN	SP	CRE	V	00:00.0
2021 PO5373007935	F	4	45 BRN	SP	CRE	V	00:00.0
2021 PO5366707994	F	2	45 BRN	SP	CRE	V	00:00.0
2021 PO4724789835	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4832889487	LGE	2	65 BRN	SP	CRE	V	00:00.0
2021 PO4833589466	LGE	2	65 BRN	SP	CRE	V	00:00.0
2021 PO7842518768	ODP	6	30 BRN	SP	CCA	V	00:00.0
2021 PO6822420501	ODP	5	35 XXX	SP	CRE	V	00:00.0
2021 PO6810820476	ODP	4	40 XXX	SP	S	V	00:00.0
2021 PO6808620384	ODP	4	40 XXX	SP	S	V	00:00.0
2021 PO6799820527	ODP	4	40 XXX	SP	S	V	00:00.0
2021 PO0622338235	ODP	2	50 BRO	SP	CCA	V	00:00.0
2021 PO2604638325	ODP	4	40 BRO	SP	CRE	V	00:00.0
2021 PO5346007962	F	2	45 BRN	SP	CRE	V	00:00.0
2021 PO7829018802	ODP	3	45 BRN	SP	CCA	V	00:00.0
2021 PO7806918784	ODP	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4726989799	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO5332707999	F	3	45 BRN	SP	CRE	V	00:00.0
2021 PO4957589391	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4956589399	LGE	1	75 ACE	SP	A	V	00:00.0
2021 PO4956389398	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO9788732508	ODP	4	40 BRO	SP	CCA	V	00:00.0
2021 PO9791432009	ODP	4	40 BRO	SP	CCA	V	00:00.0
2021 PO9755831821	ODP	1	40 BRO	SP	CCA	V	00:00.0
2021 PO9793931529	ODP	4	40 BRO	SP	CCA	V	00:00.0
2021 PO6987319673	ODP	5	30 BRN	SP	CRE	V	00:00.0
2021 PO7010219772	ODP	5	35 BRN	SP	CCA	V	00:00.0
2021 PO7024719765	ODP	6	30 BRN	SP	CCA	V	00:00.0
2021 PO6975819482	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4820588816	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4830989483	LGE	4	40 BRN	SP	CRE	V	00:00.0
2021 PO2610739743	ODP	4	40 BRO	SP	CRE	V	00:00.0
2021 PO0613739883	ODP	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5302007492	F	2	40 BRN	SP	CRE	V	00:00.0
2021 PO5300207539	F	3	45 BRN	SP	CRE	V	00:00.0
2021 PO4719990053	LGE	4	35 ACE	ST	CCA	V	00:00.0
2021 PO6369012902	LGE	1	50 BRN	SP	CCA	V	00:00.0
2021 PO4929389978	LGE	3	45 BRN	SP	CCA	V	00:00.0

2021 PO4930189973	LGE	4	35 BRN	SP	P	V	00:00.0
2021 PO4929889982	LGE	4	35 BRN	SP	P	V	00:00.0
2021 PO4928889991	LGE	3	45 BRN	SP	P	V	00:00.0
2021 PO4976989707	LGE	1	50 ACE	UN	A	V	00:00.0
2021 PO0618140009	ODP	4	45 BRO	SP	CCA	V	00:00.0
2021 PO4859888617	LGE	4	35 BRN	SP	CCA	V	00:00.0
2021 PO4711789717	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4711289717	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4712389713	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO6029803278	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO0689739961	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021 PO8927622395	ODP	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4719989964	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO7574617311	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021 PO0785740915	ODP	4	30 UNK	SP	CRE	V	00:00.0
2021 PO0788540759	ODP	5	35 UNK	SP	CCA	V	00:00.0
2021 PO0795340880	F	4	40 UNK	SP	P	V	00:00.0
2021 PO0810540942	F	4	40 UNK	SP	P	V	00:00.0
2021 PO0205037317	F	1	45 BRN	SP	P	V	00:00.0
2021 PO4978089708	F	4	40 ACE	SP	A	V	00:00.0
2021 PO0289133042	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021 PO0534934349	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO0501634355	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO0479334135	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO0168734249	ODP	6	30 BRN	SP	CCA	V	00:00.0
2021 PO0021533369	ODP	1	60 BRN	SP	CRE	V	00:00.0
2021 PO0318533835A	ODP	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4974889706	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO6828710214	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO6810410194	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO5309607887	KU	6	30 BRN	SP	S	V	00:00.0
2021 PO5302107937	F	3	45 BRN	SP	CRE	V	00:00.0
2021 PO5300807714	F	2	50 BRN	SP	CRE	V	00:00.0
2021 PO4824089415	LGE	3	30 BRO	SP	CCA	V	00:00.0
2021 PO4966889466	LGE	1	65 ACE	SP	A	V	00:00.0
2021 PO7632818548	ODP	3	45 BRN	SP	CRE	V	00:00.0
2021 PO7633218549	F	4	40 BRN	SP	A	V	00:00.0
2021 PO7210217405	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021 PO4720589974	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4721089985	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4721689995	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4968689491	LGE	2	50E ACE	SP	A	V	00:00.0
2021 PO4968289485	LGE	1	60 ACE	UN	A	V	00:00.0
2021 PO4969389487	LGE	4	40 ACE	UN	CCA	V	00:00.0
2021 PO5396810042	KU	3	45 BRN	SP	S	V	00:00.0
2021 PO5378710119	KU	3	45 BRN	SP	S	V	00:00.0
2021 PO4931589811	LGE	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4931689812	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO7653720101	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO4932989816	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021 PO4835589415	LGE	3	60 BRN	SP	CRE	V	00:00.0
2021 PO4836089399	LGE	2	60 BRN	SP	CRE	V	00:00.0
2021 PO4836789382	LGE	3	65 BRN	SP	CRE	V	00:00.0
2021 PO4834189377	LGE	3	65 BRN	SP	CRE	V	00:00.0

2021	PO0453738698	ODP	3	45 BRN	SP	CCA	V	00:00.0
2021	PO4725189829	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO5369507899	F	3	45 BRN	SP	CRE	V	00:00.0
2021	PO4711589803	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4710589819	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4709789833	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO7700020216	F	4	40 BRO	SP	CRE	V	00:00.0
2021	PO4939988879	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4939190067	LGE	4	40 BRN	SP	A	V	00:00.0
2021	PO4938490081	LGE	4	40 BRN	SP	P	V	00:00.0
2021	PO4967289651	LGE	3	45 ACE	SP	S	V	00:00.0
2021	PO4925688981	F	4	40 BRO	SP	A	V	00:00.0
2021	PO4924388978	F	4	40 BRO	SP	A	V	00:00.0
2021	PO7302317113	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021	PO4923288975	F	4	40 BRO	SP	A	V	00:00.0
2021	PO0463038501	ODP	3	45 BRO	SP	CCA	V	00:00.0
2021	PO7407417180	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021	PO7402517253	ODP	5	35 BRN	SP	CCA	V	00:00.0
2021	PO7457917234	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021	PO7455017012	ODP	6	30 BRN	SP	CCA	V	00:00.0
2021	PO4937490102	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021	PO4714989746	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4855788919	LGE	4	30 BRN	SP	CCA	V	00:00.0
2021	PO4855888929	LGE	3	50 BRN	SP	CCA	V	00:00.0
2021	PO0104633275	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021	PO4714289757	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4713289773	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4713389781	F	4	30 ACE	SP	CRE	V	00:00.0
2021	PO4712389790	F	4	40 ACE	SP	CRE	V	00:00.0
2021	PO4712589795	F	4	30 ACE	SP	CRE	V	00:00.0
2021	PO4826589361	LGE	2	65 BRN	SP	CRE	V	00:00.0
2021	PO4829089366	LGE	2	65 BRN	SP	CRE	V	00:00.0
2021	PO4836489400	LGE	3	25 BRN	SP	CCA	V	00:00.0
2021	PO4830989370	LGE	2	65 BRN	SP	CRE	V	00:00.0
2021	PO4835689421	LGE	4	30 BRN	SP	CCA	V	00:00.0
2021	PO4824688771	LGE	5	25 BRO	SP	CRE	V	00:00.0
2021	PO4824688780	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021	PO4959889389	F	4	30 ACE	UN	S	V	00:00.0
2021	PO8676721673	ODP	5	35 KOP	SP	CCA	V	00:00.0
2021	PO6976621476	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021	PO7252816747	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021	PO5567520168	KU	6	30 BRN	SP	CCA	V	00:00.0
2021	PO7233217062	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021	PO0241733173	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021	PO0242633097	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021	PO0273532949A	ODP	4	40 BRN	SP	CCA	V	00:00.0
2021	PO0145733349	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021	PO0147333708	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5306809458	KU	3	45 BRN	SP	S	V	00:00.0
2021	PO9211925325	ODP	3	50 BRO	SP	CRE	V	00:00.0
2021	PO9193324991	ODP	4	45 BRO	SP	CRE	V	00:00.0
2021	PO6964719461	ODP	4	45 BRN	SP	CCA	V	00:00.0
2021	PO4961789408	LGE	4	40 ACE	SP	S	V	00:00.0
2021	PO4712189854	F	4	40 ACE	SP	CRE	V	00:00.0



2021	PO0065733508	ODP	4	45 BRN	SP	CCA			V	00:00.0	
2021	PO4712689846	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO8658621479	F	4	40 KOP	SP	CRE			V	00:00.0	
2021	PO4962989408	LGE	2	70 ACE	SP	A			V	00:00.0	
2021	PO4967989649	LGE	4	30 ACE	ST	S			V	00:00.0	
2021	PO4968589639	LGE	4	30 ACE	SP	CCA			V	00:00.0	
2021	PO4969189632	LGE	4	40 ACE	SP	S			V	00:00.0	
2021	PO6765409514	LGE	3	45 ACE	SP	S			V	00:00.0	
2021	PO4970089653	LGE	1	45 ACE	UN	CCA			V	00:00.0	
2021	PO4968989670	LGE	4	30 ACE	UN	CCA			V	00:00.0	
2021	PO4966889677	LGE	4	40 ACE	SP	CCA			V	00:00.0	
2021	PO4968289667	LGE	3	45 ACE	SP	S			V	00:00.0	
2021	PO5414908895	KU	2	45 BRN	SP	S			V	00:00.0	
2021	PO4967889659	LGE	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4961489385	LGE	1	85 ACE	SP	A			V	00:00.0	
2021	PO4961089398	LGE	1	50 ACE	SP	S			V	00:00.0	
2021	PO4713589831	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO4714389817	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO4715289803	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO5513110905	KU	4	40 KOP	SP	CCA			V	00:00.0	
2021	PO4927388792	LGE	4	30 BRO	SP	CCA			V	00:00.0	
2021	PO4716089788	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO4716989772	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO4927488985	F	4	40 BRO	SP	CRE			V	00:00.0	
2021	PO4928388986	F	4	40 BRO	SP	A			V	00:00.0	
2021	PO4717789758	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO4716989753	F	3	45 ACE	SP	CCA			V	00:00.0	
2021	PO4716489756	F	4	30 ACE	SP	CCA			V	00:00.0	
2021	PO4715689746	F	4	40 ACE	SP	CRE			V	00:00.0	
2021	PO6697309414	LGE	6	30 ACE	SP	CRE			V	00:00.0	
2021	PO5034189081	LGE	4	40 ACE	SP	CRE	ED,ID		BD	00:00.0	
2021	PO1591752568	KU	3	45 XXX	SP	CCA			V	00:00.0	
2021	PO1570252384	KU	5	35 XXX	SP	CRE	ID		TD	00:00.0	
2021	PO1575252442	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0	
2021	PO1590552335	KU	3	45 XXX	SP	CRE	HH,ID		TX	RR	00:00.0
2021	PO1602252252	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0	
2021	PO1634452138	KU	3	50 XXX	SP	CRE			V	00:00.0	
2021	PO1614452181	F	4	40 XXX	SP	CCA			V	00:00.0	
2021	PO1634252053	KU	4	45 XXX	SP	CCA			V	00:00.0	
2021	PO4681706521	F	3	45 BRN	SP	CRE			V	00:00.0	
2021	PO4685606500	F	3	45 BRN	SP	CRE			V	00:00.0	
2021	PO4683706510	KU	3	45 BRN	SP	CRE			V	00:00.0	
2021	PO4688006474	F	3	45 BRN	SP	CRE			V	00:00.0	
2021	PO4857590655	LGE	4	40 BRN	SP	P	ED,ID,SRC		BD	00:00.0	
2021	PO0461839603	KU	3	45 BRO	SP	CCA			V	00:00.0	
2021	PO0342439614	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0	
2021	PO5034089093	LGE	4	40 ACE	SP	A	ED,ID		BD	00:00.0	
2021	PO4702106098	KU	6	30 BRN	SP	CRE	ID		BD	00:00.0	
2021	PO5197904771	KU	2	50 BRN	SP	CCA			V	00:00.0	
2021	PO5205304958	KU	2	50 BRN	SP	CCA			V	00:00.0	
2021	PO5211205108	KU	2	50 BRN	SP	CCA			V	00:00.0	
2021	PO5220805119	KU	3	45 BRN	SP	CRE			BD	00:00.0	
2021	PO4712906365	F	3	45 BRN	SP	CRE			V	00:00.0	
2021	PO4718506303	F	3	45 BRN	SP	CRE			V	00:00.0	

2021 PO4694506444	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4700506584	KU	6	30 BRN	SP	CCA	ID	BD	00:00.0
2021 PO4700506417	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4855890650	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4856090651	LGE	4	45 BRN	SP	P	ED,ID	T	00:00.0
2021 PO5629919918	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO0324639290	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0226931342	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0198631250	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0207831283	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0211831375	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO0215031448	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO7470604428	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO7466204339	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO7476004231	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5039389120	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO7451204493	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5037489125	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO2340977590	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5919115961	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5184904442	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 PO5172103932	KU	3	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5178204061	KU	2	50 BRN	SP	CRE	ED,EP	TD	00:00.0
2021 PO5181704140	KU	1	70 BRN	SP	CRE		V	00:00.0
2021 PO5167704010	KU	1	50 BRN	SP	CCA		V	00:00.0
2021 PO5165503960	KU	1	50 BRN	SP	CCA		V	00:00.0
2021 PO5175203989	KU	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5173004143	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5178904293	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5122502647	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5116202572	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4843690432	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021 PO5738903010	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5735102896	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5731002772	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5744103163	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO5739203400	F	3	40 XXX	SP	CRE		V	00:00.0
2021 PO5748903308	F	3	45 XXX	SP	CRE		V	00:00.0
2021 PO5690103877	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5698903791	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5707303708	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5718803594	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5726703519	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4709206066	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0334339076	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5643919803	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4858690664	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4481306736	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4490106943	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2393578545	KU	6	35 BRO	SP	CRE	RB	BX PX	00:00.0
2021 PO2396878408	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2383078797	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO2388578505	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4860790677	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0

2021 PO4867090728	LGE	3	45 BRN	SP	P	ED,ID	T	00:00.0
2021 PO4510507625	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4494307259	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4526307775	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4502307222	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4534207896	F	4	45 BRN	SP	CRE		V	00:00.0
2021 PO4509607190	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4510107081	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4535107738	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4517507372	F	3	30 BRN	SP	CRE		V	00:00.0
2021 PO4518307591	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4498307131	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4517307812	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4510207405	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4485807185	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4538307958	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4525207561	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4503807433	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5044689091	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO0322238819	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0183431607	KU	6	35 BRO	SP	CRE	ID	BD	00:00.0
2021 PO0175531429	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO0174131584	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0184831580	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5290008506	KU	5	35 UNK	SP	CRE	HH,ID	BX PX	00:00.0
2021 PO5228608005	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5256008187	KU	3	45 UNK	SP	CRE		V	00:00.0
2021 PO5230705375	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5223905400	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO2409078251	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2415178161	KU	6	30 BRO	SP	CRE		V	00:00.0
2021 PO5733903450	KU	6	30 XXX	SP	S		V	00:00.0
2021 PO5711303943	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5722803676	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5730703678	KU	4	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5729303834	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5681303960	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5666203982	F	5	35 XXX	SP	CRE		V	00:00.0
2021 PO5670404065	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO5675104123	KU	3	45 XXX	SP	S		V	00:00.0
2021 PO5665604211	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5692204472	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5688904407	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5685304476	KU	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5686304097	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4879290867	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4879290867-a	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4880990883	LGE	4	35 BRN	SP	P		V	00:00.0
2021 PO0311138441	KU	4	45 BRO	AL	CCA		V	00:00.0
2021 PO0303438149	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6334649591	KU	1	70 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0099131419	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0110831748	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0122632078	KU	3	45 BRO	SP	CCA		V	00:00.0

2021	PO0140132160	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO2350977790	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4887490883	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4884390894	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4888490920	LGE	3	45 BRN	SP	P	ED,ID	T	00:00.0
2021	PO4886190905	LGE	1	50 BRN	ST	CCA		V	00:00.0
2021	PO4883090897	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021	PO4885990910	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO1683851753	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1686751488	KU	4	40 XXX	SP	CRE		V	00:00.0
2021	PO1706751532	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1727651335	KU	3	50 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1697551903	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1758551523	KU	5	35 XXX	SP	CRE		V	00:00.0
2021	PO1714152027	KU	4	40 XXX	ST	CRE		V	00:00.0
2021	PO1731152151	KU	4	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1745252257	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1761152382	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1778152506	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1876350457	KU	4	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1889450394	KU	6	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1904850311	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO1842850864	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021	PO4975389364	LGE	3	50 ACE	SP	A	ED	BD	00:00.0
2021	PO4977789358	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4980289354	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO4982589349	LGE	3	45 ACE	SP	A		V	00:00.0
2021	PO4894290908	LGE	5	25 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4894590903	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021	PO4896590876	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO2362777978	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO0153132110	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021	PO0142631583	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5101102115	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021	PO5100602091	KU	1	70 BRN	SP	CRE		V	00:00.0
2021	PO5099202096	KU	1	70 BRN	SP	CRE		V	00:00.0
2021	PO5071101422	KU	1	65 BRN	SP	CRE		V	00:00.0
2021	PO5072701414	KU	1	65 BRN	SP	CCA		V	00:00.0
2021	PO6320049621	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO0137231875	KU	6	30 BRO	SP	CRE	ID	BD	00:00.0
2021	PO4479107717	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4444807446	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4450507323	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4417507576	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4413507481	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4466607256	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4399807539	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4468707755	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4451307843	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4446307221	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4432207403	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4450007833	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4903590125	LGE	4	35 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021	PO2375578066	KU	6	30 BRO	SP	CCA		V	00:00.0

2021 PO2353878012	KU	6	35 BRO	SP	CCA		V	00:00.0	
2021 PO4985289346	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO4985289348	LGE	UNK	20 ACE	SP	CCA		V	00:00.0	
2021 PO4988589339	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO4991289333	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO0134331916	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO0104732403	KU	6	30 BRO	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO0103232519	KU	3	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4906190141-A	LGE	5	35 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO2375978244	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO6314249705	KU	1	70 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4897790865	LGE	3	50 BRN	SP	P	ED,ID,IP	BD	00:00.0	
2021 PO4897190860	LGE	1	50 BRN	SP	CCA		V	00:00.0	
2021 PO4906190141	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO6379349478	F	5	35 BRO	SP	CCA		V	00:00.0	
2021 PO4886190787	LGE	4	40 BRN	SP	P	ED,ID	T	00:00.0	
2021 PO5919820795	LGE	4	35 BRN	SP	CCA		V	00:00.0	
2021 PO5904820793	LGE	4	35 BRN	SP	CCA		V	00:00.0	
2021 PO5001389391	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO5001389413	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO2328477341	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO2333777324	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO2333177074	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4907690117-A	LGE	5	35 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO0103332713	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO0115832977	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4893190826	LGE	1	50 BRN	SP	CCA		V	00:00.0	
2021 PO4894890841	LGE	1	50 BRN	SP	CCA		V	00:00.0	
2021 PO4899190843	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4899990830	LGE	4	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4901290812	LGE	3	45 BRN	SP	CCA	ED,ID	BD	00:00.0	
2021 PO4902090796	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4902990782	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0	
2021 PO4905090750	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO4903490761	LGE	4	30 BRN	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4904190765	LGE	4	35 BRN	SP	CCA		V	00:00.0	
2021 PO4905190713	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4905290714	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4906790716	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4907090718	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4907190716	LGE	3	45 BRN	SP	P	ED,ID	TD	00:00.0	
2021 PO4907490719	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4910690662	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO4909890656	LGE	6	35 BRN	SP	CRE	ED,ID,IP,RB	TD	00:00.0	
2021 PO4911390635	LGE	4	40 BRN	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO4911690637	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4912690621	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4914290596	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO4915590575	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4917190549	LGE	3	50 BRN	SP	CCA		V	00:00.0	
2021 PO4918190533	LGE	3	50 BRN	SP	CCA		V	00:00.0	
2021 PO4919590512	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4921890475	LGE	1	50 BRN	SP	CCA		V	00:00.0	
2021 PO4920890491	LGE	3	50 BRN	SP	CCA		V	00:00.0	

2021 PO4888690860	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4889990835	LGE	4	40 BRN	SP	P	ED,ID	T	00:00.0
2021 PO4889290801	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5001389365	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5001489342	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5001489336	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5788706235	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5783606131	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5775105967	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5797305689	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4994389328	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4993889328	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4994489324	LGE	UNK	25 ACE	SP	CRE		V	00:00.0
2021 PO5313809598	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5307609754	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5307009610	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4735490079	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4836589547	LGE	4	40 BRN	SP	P	ID	BD	00:00.0
2021 PO4838489562	LGE	4	35 BRN	SP	P	ID	BD	00:00.0
2021 PO4840889569	LGE	3	45 BRN	SP	P	ID	BD	00:00.0
2021 PO4942690003	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4834889538	LGE	4	40 BRN	SP	P	ID,IP	BD	00:00.0
2021 PO5308110081	KU	3	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO5307809928	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4820188875	LGE	3	50 BRN	SP	P	ID	BD	00:00.0
2021 PO4821288877	LGE	3	50 BRN	SP	P	ID	BD	00:00.0
2021 PO4823388886	LGE	3	70 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4887188582	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4884588579	LGE	1	55 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4885288586	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4900189113	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4899689111	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4933290167	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4932490180	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO6224420940	ODP	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4931390197	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4930290215	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4929490228	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO6063603773	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4928190249	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4966889438	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO6937822118	ODP	5	35 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5512412255	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO4846289318	LGE	4	40 BRN	SP	A	ED	BD	00:00.0
2021 PO4967889458	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO7110019592	ODP	2	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4934389821	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4952089431	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4952789422	LGE	4	40 ACE	SP	A	ED,ID,MD	BD	00:00.0
2021 PO6936523214	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6906423213	ODP	2	50 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4811888635	LGE	4	40 BRO	SP	P	ID	BD	00:00.0
2021 PO4808988717	LGE	3	50 BRO	SP	P	ID	BD	00:00.0
2021 PO4808588730	LGE	1	55 BRO	SP	P	ID	BD	00:00.0

2021 PO4810088688	LGE	3	45 BRO	SP	P	ID	BD	00:00.0
2021 PO5326711852	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5320411691	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5318911603	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5317711496	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5377612822	KU	2	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO0176734574	ODP	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO7551819906	ODP	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021 PO0187334079	ODP	6	30 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5449812653	KU	4	45 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO5453212592	KU	4	45 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO8465521770	ODP	4	45 BRO	SP	CRE	ID	BD	00:00.0
2021 PO9434732279	ODP	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO5513512082	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0
2021 PO5423312833	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5425812871	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO8405421496	ODP	4	45 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO5393112760	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5398413212	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5392013113	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5351111893	KU	2	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5357811876	KU	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4848288932	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4847988930	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7655719741	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4735690031	LGE	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4849688887	LGE	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO5368010164	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5340411922	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO9124124875	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4821488770	LGE	5	25 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4821988780	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO5406310003	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5415909963	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4820388849	LGE	5	25 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4814288551	LGE	H3	45 BRO	SP	CCA	ID	BD	00:00.0
2021 PO4822288846	LGE	4	40 BRO	SP	P	ID,IP	BD	00:00.0
2021 PO4821888855	LGE	5	25 BRO	SP	P	ID	BD	00:00.0
2021 PO4939888943	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4942288987	LGE	4	40 BRO	SP	A	ID	BD	00:00.0
2021 PO4734790019	LGE	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4824588841	LGE	5	25 BRO	SP	CRE	ID	BD	00:00.0
2021 PO9285923412	ODP	6	30 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO4948889407	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4849388907	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4819488712	LGE	3	45 BRO	SP	P	ID	BD	00:00.0
2021 PO4820588701	LGE	4	35 BRO	SP	P	ID	BD	00:00.0
2021 PO4820788700	LGE	3	45 BRO	SP	P	ID	BD	00:00.0
2021 PO4970589539	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4730189982	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO0671538224	ODP	4	40 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO2639138625	ODP	5	35 BRO	SP	P	ED,ID	BD	00:00.0
2021 PO4722589887	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4902289120	LGE	4	40 BRO	SP	A	ID	BD	00:00.0

2021 PO4882888565	LGE	1	60 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4736690055	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6370818399	ODP	5	35 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4850788912	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4736690043	LGE	4	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4883088546	LGE	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4939989665	LGE	3	45 BRN	SP	P	ED,ID,MD	BD	00:00.0
2021 PO4940789640	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4713089990	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4714089997	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4715390005	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4828988745	LGE	3	45 BRO	SP	P	ID	BD	00:00.0
2021 PO4825388753	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4825488748	LGE	3	45 BRO	SP	P	ID	BD	00:00.0
2021 PO7175317948	ODP	4	40 BRN	SP	A	ED,ID,IP	BD	00:00.0
2021 PO5311208507	KU	6	30 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5325508852	KU	2	50 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4912288977	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4936689925-a	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4936689925-a	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO0164136837	ODP	6	30 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0096937017	ODP	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021 PO4868588617	LGE	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO5423511684	KU	4	40 OTH	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4822488749	LGE	2	60 BRO	SP	P	EP,ID,IP,MD	BD	00:00.0
2021 PO4823488749	LGE	3	55 BRO	SP	P	ID	BD	00:00.0
2021 PO4816388746	LGE	3	60 BRO	SP	P	ID	BD	00:00.0
2021 PO8916222759	ODP	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4883288569	LGE	1	60 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4881888557	LGE	1	60 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4972389538	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4972489540	LGE	3	45 ACE	SP	CCA	ED,ID	BD	00:00.0
2021 PO4865188630	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4866188626	LGE	3	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4864188634	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4863088637	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4935589938	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4934389934	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4933289930	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4858288654	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4860588646	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4857488624	LGE	4	40 BRN	SP	A	ED	BD	00:00.0
2021 PO4973889560	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4825089408	LGE	4	40 BRO	SP	P	ID	BD	00:00.0
2021 PO4825689410	LGE	4	40 BRO	SP	P	ID	BD	00:00.0
2021 PO4827589417	LGE	4	40 BRO	SP	P	ID	BD	00:00.0
2021 PO4826889414	LGE	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO4826289413	LGE	4	40 BRO	SP	P	ID	BD	00:00.0
2021 PO4932089926	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4932289964	LGE	2	45 BRN	SP	P	ID	BD	00:00.0
2021 PO9412125172	ODP	4	40 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8923023118	ODP	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4856288571	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4932689005	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0



2021	PO5344711503	KU	5	35 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO5481609690	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4952189450	LGE	4	35 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO7735520834	ODP	4	45 OTH	SP	CRE	ID	BD	00:00.0
2021	PO7756820807	ODP	4	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4938089783	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO8512221155	ODP	6	30 KOP	SP	CRE	ED	BD	00:00.0
2021	PO4728489976	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO7731620533	ODP	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO4733289999	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5481209601	KU	6	30 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO5483609670	KU	6	30 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4936088971	LGE	4	35 BRO	SP	CRE	ID,IP	BD	00:00.0
2021	PO5453309806	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5446809834	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5429309906	KU	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO4938089843	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO4722289993	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4716889960	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4820688840	LGE	4	40 BRO	SP	P	ID,IP	BD	00:00.0
2021	PO7743418823	ODP	4	35 UNK	SP	CCA	ID	BD	00:00.0
2021	PO4733890007	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO5505611079	KU	3	45 KOP	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO4971689559	LGE	3	45 ACE	SP	CCA		B	00:00.0
2021	PO4955889633	LGE	4	30 ACE	SP	CCA		B	00:00.0
2021	PO6659309645	LGE	4	40 ACE	SP	CCA		B	00:00.0
2021	PO4955589640	LGE	4	40 ACE	SP	CCA		B	00:00.0
2021	PO4964489606	LGE	3	45 ACE	SP	S		B	00:00.0
2021	PO4968289581	LGE	4	40 ACE	SP	CCA		B	00:00.0
2021	PO4967389587	LGE	4	40 ACE	SP	CCA		B	00:00.0
2021	PO4969089576	LGE	4	40 ACE	SP	CCA		B	00:00.0
2021	PO4836989383	LGE	3	45 BRN	SP	A	ED	B	00:00.0
2021	PO7994755125	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7977554970	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7960554823a	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021	PO7960554823	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7948054875	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO7916954919	ODP	3	50 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4803989122	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4803289133	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021	PO4802889139	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021	PO5854724537	F	5	35 OTH	SP	CRE	ID,MD	BX	RP3 00:00.0
2021	PO5835023897	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5840423943	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5847524475	F	5	35 OTH	SP	P		BD	00:00.0
2021	PO5850124031	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5851124325	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5878024035	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5547221384	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO5557321289	KU	3	50 OTH	SP	CCA		V	00:00.0
2021	PO5883023983	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO5823123967	KU	4	40 OTH	SP	CCA		V	00:00.0
2021	PO5812124101	KU	4	40 OTH	SP	CCA		V	00:00.0
2021	PO5870724417	KU	6	30 OTH	UN	CRE		V	00:00.0

2021 PO5848224274	KU	H1	95 OTH	ST	CRE		V	00:00.0
2021 PO5873424083	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO5831423877	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO5865124172	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO5806824031	KU	2	50 OTH	SP	CCA		V	00:00.0
2021 PO4793289089	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4792389095	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4791389100	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO7896554836	ODP	3	50 BRN	SP	CCA		V	00:00.0
2021 PO7906954931	ODP	2	55 BRN	SP	CCA		V	00:00.0
2021 PO7916955057	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7884755041	ODP	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7892555058	ODP	3	40 BRN	SP	CCA		V	00:00.0
2021 PO7862255150	ODP	2	55 BRN	SP	CCA		V	00:00.0
2021 PO7852755649	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7838355565	ODP	4	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO7853355479	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7924145926	ODP	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7905845745	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4474085812	LGE	1	55 BRN	SP	CCA	ID,IP	BD	00:00.0
2021 PO5088484945	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO5085584956	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO5087784956	LGE	4	40 BRN	SP	A	ED,ID	TD	00:00.0
2021 PO7118048043	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7116348042	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO7114348040	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO7112648037	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7106448087	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO7112548081	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4461985843	LGE	1	55 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4461985840	LGE	1	55 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5804998331	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5862598507	KU	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO5856498547	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4455186153	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4454686137	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4332086998	LGE	4	35 ACE	SP	A	ED	T	00:00.0
2021 PO4329786970	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4331486992	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4330286976	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4460985838	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4503098462	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4256988010	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4256787975	LGE	3	45 BRN	SP	CRE	ED	V	00:00.0
2021 PO4462286082	LGE	3	50 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4460686084	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO7500481022	KU	1	75 UNK	WC	P		V	00:00.0
2021 PO6967047795	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4515901474	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4523201383	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4530901295	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4538201206	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4449598239	F	3	45 BRO	SP	CRE	ED	V	00:00.0
2021 PO4441998253	F	4	40 BRO	SP	CRE	ED	V	00:00.0

2021 PO4429898275	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4403998322	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4417298297	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4390598347	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4381598362	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4373698584	F	5	35 BRO	SP	CRE	ED	V	00:00.0
2021 PO4344698429	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4260286651	LGE	1	70 ACE	SP	CCA		V	00:00.0
2021 PO4259186607	LGE	1	45 ACE	SP	CCA		V	00:00.0
2021 PO4259886627	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO4260086639	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO6790649746	KU	4	45 BRN	SP	CRE		BD	00:00.0
2021 PO6780949743	KU	4	45 BRN	SP	CRE		BD	00:00.0
2021 PO6775249879	KU	4	40 BRN	SP	CRE		BD	00:00.0
2021 PO6770749743	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO6796149743	KU	4	45 BRN	SP	CRE		BD	00:00.0
2021 PO6512048915a	F	5	35 BRN	SP	A		V	00:00.0
2021 PO4051498934	KU	3	45 BRN	SP	CRE		BD	00:00.0
2021 PO7324548147	KU	4	45 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7324347936	KU	2	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4256887885	LGE	3	50 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO5163384803	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5163984826	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO5162684822	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5161784818	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO6459447745	KU	4	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4374585362	LGE	4	35 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4374085358	LGE	3	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4374285355	LGE	4	35 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4373285343	LGE	3	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO6696149320	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6683249078	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6693749125	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO3818496727	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6841343770	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6839443645	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6838343570	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO6835743423	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6802142193	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6809542396	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6814642573	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6823342695	F	3	40 BRO	SP	CCA		V	00:00.0
2021 PO6823442827	F	4	40 BRO	SP	P	ED,ID	V	00:00.0
2021 PO6827843083	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6833043228	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO7341648193	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7341648193	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO7456748125	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4735389831	LGE	1	60 BRN	SP	CCA		V	00:00.0
2021 PO7536848005	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4751889904	LGE	UNK	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO6599247595	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO6581247488	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO6606947517	KU	6	30 BRN	SP	CCA		V	00:00.0

2021 PO6620147477	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6623347470	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4753089909	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4754189907	F	4	40 BRN	SP	A		V	00:00.0
2021 PO4005099603	KU	5	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4019699668	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4379985773	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4468285819	LGE	1	65 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4470185817	LGE	1	60 BRN	SP	CCA		V	00:00.0
2021 PO7118448878	KU	3	50 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7119348905B	KU	3	50 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7119348905A	KU	3	50 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7119348905	KU	3	50 BRO	SP	CCA		V	00:00.0
2021 PO7118049046	KU	2	50 UNK	SP	CRE	ED,ID	BX PX	00:00.0
2021 PO7117749166	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7110349302	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO3793703883	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO3797204164	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO4943391487	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4942091457	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO6691448310	KU	1	80 BRN	ST	CRE		V	00:00.0
2021 PO6557047413	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6952947157	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4450286143	F	2	65 BRN	SP	P		V	00:00.0
2021 PO5229916379	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO7376347714	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7560247001	KU	5	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7371247646	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7355447683	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7379347587	F	4	40 UNK	SP	P		V	00:00.0
2021 PO4822690376	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4910391217	LGE	3	50 BRN	SP	A		V	00:00.0
2021 PO3860800604	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4336387056	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3853401033	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5817798798	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4909091173	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO4296298790	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4282898848	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4272298890	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4260798933	F	3	45 BRO	SP	CRE	ED	V	00:00.0
2021 PO4258098830	F	3	45 BRO	SP	CRE	ED	V	00:00.0
2021 PO4253798667	F	3	45 BRO	SP	CRE	ED	V	00:00.0
2021 PO4448886112	LGE	4	30 BRN	SP	A	ED,ID,MD	TD	00:00.0
2021 PO4447586113	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO5549792837	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5557492902	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5508792879	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5503992967	F	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5515893037	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO5522493064	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO7110047355	KU	2	70 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4449486125	LGE	4	30 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4449986157	LGE	4	30 BRN	SP	P		V	00:00.0

2021 PO3691897580	KU	3	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4445286125	LGE	3	50 BRN	SP	A	ED	BD		00:00.0
2021 PO4446886131	LGE	3	50 BRN	SP	A	ED,HH,ID,RB	TX	RR	00:00.0
2021 PO7496947171	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO7503047116	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO7569247779	KU	4	45 BRO	SP	CRE	ID	BD		00:00.0
2021 PO5853298464	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5850398456	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5840098513	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO4449286157	LGE	3	50 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO5526393199	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5498193789	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO7906646992	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO7770046085	KU	4	40 KOP	SP	CRE	ID	BD		00:00.0
2021 PO7108046804	KU	5	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7108947028AA	KU	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO7108947028A	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7108947028	KU	2	70 BRO	SP	S		V		00:00.0
2021 PO6481748757	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO5546293713	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO5507593724	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO3855901412	KU	3	45 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO5729498501	F	4	45 XXX	SP	CRE		V		00:00.0
2021 PO5742998305	F	4	45 XXX	SP	S		V		00:00.0
2021 PO5755898122	F	4	45 XXX	SP	CRE		V		00:00.0
2021 PO5754099253	F	4	45 XXX	SP	CRE		V		00:00.0
2021 PO9106694246	LGE	3	45 BRN	SP	A	ED,ID,IP	TD		00:00.0
2021 PO4465186069	LGE	4	30 BRN	SP	CRE		V		00:00.0
2021 PO1781472704	LGE	4	35 BRN	SP	P		V		00:00.0
2021 PO1830172305	LGE	1	50 BRN	SP	CRE		V		00:00.0
2021 PO9108894995	LGE	3	45 BRN	SP	A	ID,IP	TD		00:00.0
2021 PO4091184469	LGE	4	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4083284450	LGE	4	30 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO6504248547	KU	1	75 BRN	SP	CRE		V		00:00.0
2021 PO6474348658	KU	1	75 BRN	SP	CRE		V		00:00.0
2021 PO4205388252	LGE	5	25 BRN	SP	A	ED,ID,IP	TD		00:00.0
2021 PO6479448613	KU	3	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9153594501	LGE	4	35 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO3779502418	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO7070047517	KU	3	45 XXX	SP	CCA		V		00:00.0
2021 PO6737749219	KU	4	35 BRN	SP	CRE	ED	TD		00:00.0
2021 PO4217198768	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4205798799	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4194098832	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4181798876	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4170798930	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4159898984	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4149099037	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4138499090	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4127599142	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4116599196	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4104999253	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4093599309	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4082999362	F	4	40 BRO	SP	CRE	ED	V		00:00.0

2021 PO4073499409	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO6892647916	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6898747914	KU	2	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO6964547182	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO6964147060	KU	3	45 XXX	SP	CCA		V	00:00.0
2021 PO6963346956	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7021547073	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7042747090	KU	5	35 XXX	SP	CRE	ID,IP	TD	00:00.0
2021 PO7050947060	KU	5	35 XXX	SP	CRE	ED,ID,RB	X PX	00:00.0
2021 PO7051147207	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7057247369	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6908947896	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6908747761	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7101548990	F	5	35 UNK	SP	CRE		V	00:00.0
2021 PO7103349130	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO7087649017	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7090249154	F	4	40 UNK	SP	P		V	00:00.0
2021 PO7080649031	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7079449104	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7080649172	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7051149164A	KU	5	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO3940285010	LGE	1	55 ACE	SP	CRE		V	00:00.0
2021 PO3941885009	LGE	1	55 ACE	SP	CRE		V	00:00.0
2021 PO3943385008	LGE	4	35 ACE	SP	CRE		V	00:00.0
2021 PO3944185007	LGE	1	60 ACE	SP	CCA		V	00:00.0
2021 PO5695298487	F	3	40 XXX	SP	P	ED,EP,ID,MD	BX PX	00:00.0
2021 PO4462585911	F	2	55 BRN	SP	A		V	00:00.0
2021 PO4462785929	F	3	50 BRN	SP	CRE		V	00:00.0
2021 PO4462985943	F	3	50 BRN	SP	CRE		V	00:00.0
2021 PO4463085960	F	3	50 BRN	SP	A		V	00:00.0
2021 PO4463185963	F	2	55 BRN	SP	CRE		V	00:00.0
2021 PO4204888217	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4204388220	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4084984449	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO3780503029	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3783303190	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO3776202722	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3778202884	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4463285973	F	3	50 BRN	SP	CRE		V	00:00.0
2021 PO8006056323	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4212188178	LGE	2	50 BRN	SP	CCA		V	00:00.0
2021 PO6618348152	KU	5	35 BRN	SP	CRE		V	00:00.0
2021 PO4445986071	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4445486073	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO6612248073	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO6606948143	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO6594247932	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4212088181	LGE	4	35 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4448886067	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4449286066	F	3	45 BRN	SP	P		V	00:00.0
2021 PO4449386073	F	3	50 BRN	SP	P		V	00:00.0
2021 PO4211888179	LGE	1	50 BRN	SP	A	ID	BD	00:00.0
2021 PO4210888180	LGE	2	50 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4924891345	LGE	2	65 BRN	SP	A		V	00:00.0

2021 PO4922391358	LGE	2	55 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4919891369	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO7888945723	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7882645984	ODP	6	30 BRN	SP	CRE		V	00:00.0
2021 PO7589342906	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO4919389916	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4916889908	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO7624743214	ODP	2	40 KOP	SP	CCA		V	00:00.0
2021 PO7612043172	ODP	2	50 KOP	SP	CCA		V	00:00.0
2021 PO4921289945	LGE	3	45 BRN	SP	P	ED,ID,JP	BD	00:00.0
2021 PO8204942687	ODP	5	35 XXX	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO8167142608	ODP	4	40 XXX	SP	P		V	00:00.0
2021 PO8174642475	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8194642841	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO0036195159	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0060795249	ODP	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0061095440	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0041895372	ODP	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0040795425	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO0048995389	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0046995503	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO0057495506	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO0040695860	ODP	5	30 BRO	SP	CRE		T	00:00.0
2021 PO0058195823	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO0049195797	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0045495948	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0040796110	ODP	6	35 BRO	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO0042196220A	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0028096027	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO0017996035	ODP	4	40 BRO	SP	CRE		V	00:00.0
2021 PO0042196220	ODP	6	35 BRO	SP	CRE		T	00:00.0
2021 PO0025296251	ODP	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO0032696265	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO4822191355	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4823291349	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4805391199	LGE	4	40 BRN	SP	CRE	ED,HH,ID	VX	RP1 00:00.0
2021 PO5086389116	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5084389113	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO6182649369	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6198949314	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6210649272	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO5081589110	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO6220149193	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6221649235	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6278449209	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5078889105	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5078889108	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO6290149164	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6252949128	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6288148886	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO5076789102	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5626204901	KU	6	30 MAR	SP	CCA		V	00:00.0
2021 PO5633604970	F	4	40 MAR	SP	CRE		V	00:00.0
2021 PO5637705011	KU	4	40 MAR	SP	CRE		V	00:00.0

2021	PO5629305066	KU	4	40 MAR	SP	P		V			00:00.0
2021	PO5661604994	F	4	40 MAR	SP	A		V			00:00.0
2021	PO4807791158	LGE	4	40 BRN	SP	CCA		V			00:00.0
2021	PO5068389325	LGE	4	40 ACE	SP	A	ED	V			00:00.0
2021	PO5050689317	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO4247407531	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4255307726	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4255707811	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4202907428	KU	6	30 BRN	SP	CRE		BD			00:00.0
2021	PO4241507313	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5157824140	LGE	3	45 BRN	SP	CCA		V			00:00.0
2021	PO4810391114	LGE	4	40 BRN	SP	P	ED,ID	TD			00:00.0
2021	PO5066389316	LGE	4	40 ACE	SP	CCA		V			00:00.0
2021	PO5666004878	F	4	40 BRN	SP	CRE	ED,HH,ID,IP	VX	PX		00:00.0
2021	PO5666704818	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5667504740	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5658604615	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5644704590	KU	4	40 BRN	SP	CRE		V			00:00.0
2021	PO7766706468	LGE	4	40 ACE	SP	A		V			00:00.0
2021	PO6268948998	KU	6	30 BRO	SP	CRE	ED,ID	TD			00:00.0
2021	PO6319049061	KU	3	50 BRO	SP	CCA		V			00:00.0
2021	PO4815691130	LGE	4	40 BRN	SP	P	ED,ID	TD			00:00.0
2021	PO6330149044	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO6331649005	KU	6	30 BRO	SP	CCA		V			00:00.0
2021	PO6352349093	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO5070389328	LGE	4	40 ACE	SP	CCA		V			00:00.0
2021	PO7683707381	LGE	1	50 ACE	SP	CCA		V			00:00.0
2021	PO7696307445	LGE	1	50 ACE	SP	CCA		V			00:00.0
2021	PO0574533186	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO0562133481	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO0550433758	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO0538334030	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO0544634154	KU	4	45 BRO	SP	CCA		V			00:00.0
2021	PO0512334203	KU	4	45 BRO	SP	CCA		V			00:00.0
2021	PO0501134066	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO0481734313	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO4209307645	F	3	40 BRN	SP	CRE		V			00:00.0
2021	PO4200007532	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4173807762	F	4	40 BRN	SP	CCA		V			00:00.0
2021	PO4215107983	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4206807500	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX		00:00.0
2021	PO4166307586	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX		00:00.0
2021	PO4222207911	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4211907796	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4189207844	F	4	40 BRN	SP	CCA		V			00:00.0
2021	PO7690207260	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021	PO7700407316	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021	PO7725307477	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021		7712607437	LGE	3	45 ACE	SP	CCA	V			00:00.0
2021	PO4820891146	LGE	4	40 BRN	SP	P		B			00:00.0
2021	PO4825591169	LGE	4	25 BRN	SP	P		V			00:00.0
2021	PO4825791162	LGE	3	40 BRN	SP	CCA		V			00:00.0
2021	PO4800491519	LGE	4	40 BRN	SP	P		V			00:00.0
2021	PO7790307589	LGE	3	45 ACE	SP	CCA		V			00:00.0



2021 PO5070889408	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5628404566	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5610204568	F	3	45 BRN	SP	A		V	00:00.0
2021 PO6353649005	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6353048945	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5592004688	F	4	40 BRN	SP	CRE	ED,EP,HH,ID,IP,MD,RB	VX PX	00:00.0
2021 PO5593604799	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5595004954	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5597005101	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7815807681	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7810807817	LGE	1	55 ACE	SP	CCA		V	00:00.0
2021 PO7797407784	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO5070989456	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO6379148810	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6367848896	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6341148735	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4794491416	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4792591408	LGE	3	40 BRN	SP	CCA		V	00:00.0
2021 PO4790691401	LGE	3	40 BRN	SP	CCA		V	00:00.0
2021 PO4796391423	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO0465534564	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0422834817	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO0428835020	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO0415834981	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0410435273	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO6348248835	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6353048917	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6355048940	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO6355048940A	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO4798191430	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4800191438	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4802091446	LGE	4	40 BRN	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4244306865	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4218706990	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4203007070	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4176107250	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4188407148	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4166307410	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO7575206360	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5047889282	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6356948980	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6375148865	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO0399235373	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0382035778	KU	4	45 UNK	SP	CCA		V	00:00.0
2021 PO0382035778	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO0363036180	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO0351236295	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6377848778	KU	5	35 KOP	SP	P	ED,ID	TD	00:00.0
2021 PO5056089213	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5058189208	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5067089511	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO0355136414	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO0364636814	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO0621035714	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0

2021	PO4236006582	F	4	40 BRN	SP	CRE	EP,ID	V	00:00.0	
2021	PO4258606863	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4245906839	KU	6	30 BRN	SP	CRE	RB	BD	00:00.0	
2021	PO4241406752	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO5051789235	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO5066389497	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO5066989483	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0	
2021	PO7744907910	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0	
2021		5064789443	LGE	4	35 ACE	SP	CCA	VX	PX	00:00.0
2021	PO4804091454	LGE	4	40 BRN	SP	CCA		V	00:00.0	
2021	PO5053989217	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0	
2021	PO4805791460	LGE	4	40 BRN	SP	CCA	ED,ID	BD	00:00.0	
2021	PO4804991481	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0	
2021	PO4805991465	LGE	4	40 BRN	SP	P	ED,ID	T	00:00.0	
2021	PO6012349916	F	4	40 KOP	SP	S		V	00:00.0	
2021	PO6011149803	F	4	40 KOP	SP	CRE		V	00:00.0	
2021	PO6007649911	KU	6	30 KOP	SP	CCA		V	00:00.0	
2021	PO6033649930	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO6009249734	F	4	40 KOP	SP	S		V	00:00.0	
2021	PO6070349663	KU	6	30 MAR	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4804391506	LGE	4	40 BRN	SP	P	ED,ID	T	00:00.0	
2021	PO4803791498	LGE	4	45 BRN	SP	P	ED,ID	BD	00:00.0	
2021	PO5632205338	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO0586435882	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO0451536535	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO0478536404	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO0547536074	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO5049589252	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021	PO7562806010	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO7762007702	LGE	1	55 ACE	SP	CCA		V	00:00.0	
2021	PO7779407755	LGE	1	50 ACE	SP	CCA		V	00:00.0	
2021	PO5066489445	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021	PO5060289448	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO7743807658	LGE	1	55 ACE	SP	CCA		V	00:00.0	
2021	PO5064789443	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021	PO7535305901	LGE	1	50 BRO	SP	CCA		V	00:00.0	
2021	PO7541805976	LGE	1	50 BRO	SP	CCA		V	00:00.0	
2021	PO5046989271	LGE	1	50 BRO	SP	CCA		V	00:00.0	
2021	PO7726607587	LGE	1	50 ACE	SP	CCA		V	00:00.0	
2021	PO5062989414	LGE	1	55 ACE	SP	CCA		V	00:00.0	
2021	PO5061689430	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO6514890848	F	4	40 UNK	SP	CRE		V	00:00.0	
2021	PO6041249525	KU	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO6080949692	KU	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021	PO6058049592	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO4832090045	F	5	25 BRO	SP	A		V	00:00.0	
2021	PO5340514433	LGE	1	60 BRO	SP	CCA		V	00:00.0	
2021	PO4219506393	F	3	40 BRN	SP	CRE		V	00:00.0	
2021	PO4143507269	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4216506905	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4197107002	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4232006774	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4226706619	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4222106582	F	4	40 BRN	SP	CRE		V	00:00.0	

2021 PO4161107181	F	3	40 BRN	SP	CRE		V	00:00.0	
2021 PO4229506840	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4179007092	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO0398036793	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0390737173	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO5061789516	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO5061389521	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO5059889506	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO6066349447	KU	5	35 BRO	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO6054149380	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4828690121	LGE	1	55 BRO	SP	CCA		V	00:00.0	
2021 PO4830690084	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO6041349305	KU	4	45 BRO	SP	S		V	00:00.0	
2021 PO5058189488	LGE	4	30 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO5058589492	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO5058889471	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4831690066	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO4832890051	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021 PO0385437458	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0367737668A	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5058889593	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO5058089575	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0	
2021 PO6033349410	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO6017949422	KU	4	45 BRO	SP	S		V	00:00.0	
2021 PO6007749656	KU	4	40 BRO	SP	S		V	00:00.0	
2021 PO5993449442	KU	5	35 BRO	SP	CCA		V	00:00.0	
2021 PO5999449435	KU	4	40 BRO	SP	S		V	00:00.0	
2021 PO1373582890	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5057189554	LGE	4	40 ACE	SP	A		V	00:00.0	
2021 PO4833990041	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO0367737668	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0348537707	KU	6	30 UNK	SP	CRE	ED,ID,IP,MD	TX	RR	00:00.0
2021 PO5056589541	LGE	4	40 ACE	SP	CCA		V	00:00.0	
2021 PO4191506683	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4177806708	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4130006965	F	3	45 BRN	SP	CRE		V	00:00.0	
2021 PO4200606648	F	4	45 BRN	SP	CRE		V	00:00.0	
2021 PO4153006862	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4169106726	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4120007019	F	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4157006701	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4834990031	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO4834290022	LGE	4	30 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO4836090023	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO5055989528	LGE	3	50 ACE	SP	CCA		V	00:00.0	
2021 PO0348437898	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0361738145	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4837190014	LGE	3	45 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021 PO4838190005	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4116506609	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4127806641	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4107907049	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4116806840	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4839489995	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0	

2021 PO4840689974	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4840889984	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4842189973	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO6026751293	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6029004050	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6025404077	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4881790370	LGE	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6016404176	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6017504138	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6022404285	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6025404335	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6027504371	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6033504487	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6038404579	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6041604635	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6045804713	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5600603959	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5611304001	KU	6	30 KOP	SP	CCA		V	00:00.0
2021 PO4018306030	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5226504880	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5228904942	F	4	40 MAR	SP	CRE		V	00:00.0
2021 PO5227804963	F	2	45 MAR	SP	CRE		V	00:00.0
2021 PO5129102504	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5128402553	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5134102674	KU	2	55 BRN	SP	CCA		V	00:00.0
2021 PO5142602908	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5146803016	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO3938505134	F	3	50 XXX	SP	CRE		V	00:00.0
2021 PO5515703848	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5422204043	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5418704143	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5413704163	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO5404004199	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO3980006334	F	4	40 XXX	SP	P		V	00:00.0
2021 PO3893406888	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO4006305864	F	3	40 CPT	SP	P		V	00:00.0
2021 PO3988105736	F	3	40 CPT	SP	P		V	00:00.0
2021 PO5125002053	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5113102014	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3990606042	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5165001915	KU	1	55 BRN	SP	CCA		V	00:00.0
2021 PO5153201962	KU	1	55 BRN	SP	CCA		V	00:00.0
2021 PO5145401988	KU	1	55 BRN	SP	CCA		V	00:00.0
2021 PO5510101423	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5165703503	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5600603959	F	4	30 MAR	SP	P		V	00:00.0
2021 PO5583403987	F	4	40 MAR	SP	CRE		V	00:00.0
2021 PO4026006023	F	3	40 XXX	SP	P		V	00:00.0
2021 PO3899607228	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3892207066	KU	6	30 BRN	OT	CRE		V	00:00.0
2021 PO3908907179	F	4	40 BRN	OT	CRE		V	00:00.0
2021 PO3980405320	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3895607251	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO3896706898	F	4	40 BRN	SP	CRE		V	00:00.0

2021 PO3894906733	F	3	40 BRN	OT	CRE	V	00:00.0
2021 PO4019205574	F	4	40 BRN	OT	CRE	V	00:00.0
2021 PO4006405491	F	4	40 BRN	OT	CRE	V	00:00.0
2021 PO3897307070	F	3	40 BRN	OT	CRE	V	00:00.0
2021 PO3993505404	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO4007806306	F	3	40 XXX	SP	P	V	00:00.0
2021 PO5540700003	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO3942405579	KU	3	40 CPT	SP	P	V	00:00.0
2021 PO5234205074	F	2	50 MAR	SP	CRE	V	00:00.0
2021 PO5551300252	F	4	40 XXX	SP	S	V	00:00.0
2021 PO5130102430	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO5472501467	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5482501579	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5492201705	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5502401826	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5461000347	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5450700393	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5472000297	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5483000247	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5494200197	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5505000147	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5512000115	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5114502052	KU	1	65 BRN	SP	CRE	V	00:00.0
2021 PO5119702070A	KU	1	50 BRN	SP	CCA	V	00:00.0
2021 PO5119702070	KU	1	60 BRN	SP	CCA	V	00:00.0
2021 PO5121402127	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO5121202034	F	2	50 BRN	SP	CRE	V	00:00.0
2021 PO5124302260	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO5128602383	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO4006106026	F	3	40 XXX	SP	P	V	00:00.0
2021 PO3903607748	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5537003455	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5498603227	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5522303120	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5533703072	F	3	40 XXX	SP	P	V	00:00.0
2021 PO5540203043	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5496803646	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5577903398	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5153903170	KU	2	50 BRN	SP	CCA	V	00:00.0
2021 PO5159803310	KU	2	55 BRN	SP	CCA	V	00:00.0
2021 PO5298600772	F	3	45 XXX	SP	P	V	00:00.0
2021 PO5296800705	F	3	45 XXX	SP	P	V	00:00.0
2021 PO5274600627	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5300700575	F	3	55 XXX	SP	P	V	00:00.0
2021 PO5306900560	F	3	40 XXX	SP	P	V	00:00.0
2021 PO5321700520	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5331700490	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5584603222	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5589003284	F	6	30 XXX	SP	CRE	V	00:00.0
2021 PO5418904549	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO5433504489	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO5449304423	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO5463404364	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO5478204303	F	4	30 BRO	SP	CRE	V	00:00.0

2021	PO5490504264	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3946706017	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5589399788	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5599899671	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5364302617	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5528700042	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5647699192A	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5546499951	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5554199920	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5565499877	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5539503431	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5541603559	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5537503302	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5543303649	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5551203695	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5545803724	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5536103741	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5576103717	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO5574303711	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3907908112	F	3	45 BRN	SP	CCA		V	00:00.0
2021	PO3906308056	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5582303906	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO5585303828	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5577603907	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5576903654	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5499203539	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5520203499	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5508703657	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5511103782	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5490603919	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5487703838	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5482303966	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5146703022	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5148003032	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO3922405214	F	4	40 XXX	SP	CRE	ED,ID	V	00:00.0
2021	PO5474201277	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5481901368	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5489501464	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5647699192	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5625299391	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5659099142	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5671099087	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5679499048	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5587703503	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5538602361	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5529302368	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO3965706348	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5211705296	KU	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4021606293	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5558102738	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5560402874	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5562503002	KU	3	40 XXX	SP	S		V	00:00.0
2021	PO5551903017	KU	3	40 XXX	SP	S		V	00:00.0
2021	PO5559002682	F	3	40 XXX	SP	P		V	00:00.0

2021	PO5572103581	F	3	40 XXX	SP	CRE		V	00:00.0
2021	PO5571103519	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5569003389	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5566803258	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5564503120	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5552804012	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5542004055	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5527604114	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO3933606693	F	4	40 XXX	SP	P		V	00:00.0
2021	PO3919706704	F	4	40 XXX	SP	CCA		V	00:00.0
2021	PO5567903949	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5561603857	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4036307483	F	3	50 BRN	OT	S		V	00:00.0
2021	PO4040907340	F	3	50 BRN	SP	S		V	00:00.0
2021	PO4032107621	F	2	50 BRN	SP	S		V	00:00.0
2021	PO4050406851	F	4	50 BRN	SP	S		V	00:00.0
2021	PO4030307664	F	2	50 BRN	OT	S		V	00:00.0
2021	PO4048707052	F	2	50 BRN	SP	S		V	00:00.0
2021	PO4034407167	F	4	40 BRN	SP	S		V	00:00.0
2021	PO4046107205	F	4	50 BRN	SP	S		V	00:00.0
2021	PO4049106729	KU	3	50 BRN	SP	S		V	00:00.0
2021	PO4071704450	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4092804184	F	3	50 BRN	SP	S		V	00:00.0
2021	PO4138204015	F	2	50 BRN	SP	S		V	00:00.0
2021	PO4115604080	F	3	50 BRN	SP	S		V	00:00.0
2021	PO4128504038	F	2	50 BRN	SP	S		V	00:00.0
2021	PO4083704344	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4133304049	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5543001866	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5573401658	F	3	40 XXX	SP	S		V	00:00.0
2021	PO5562401739	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5553701768	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5535201706	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5541701602	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5546001457	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5564900764	KU	6	30 XXX	SP	S		V	00:00.0
2021	PO5560300774	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5567000575	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5549601314	F	2	45 XXX	SP	P		V	00:00.0
2021	PO5553001166	F	2	45 XXX	SP	P		V	00:00.0
2021	PO5547601066	F	6	30 XXX	SP	CRE		V	00:00.0
2021	PO5555601033	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5558600905	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5491900598	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5502600546	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5522500409	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5525000518	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5559500417	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5518700631	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5513200501	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4166204978	F	4	40 UNK	SP	CRE	ED,ID,MD	V	00:00.0
2021	PO4154104617	F	4	40 UNK	SP	CRE	ED,ID	V	00:00.0
2021	PO4152204828	F	4	40 UNK	SP	CRE	ED,ID	V	00:00.0
2021	PO4155605800	F	4	40 BRN	SP	CRE		V	00:00.0

2021	PO4150505849	F	4	40 BRN	SP	S		V	00:00.0
2021	PO4172305146	F	4	40 UNK	SP	P		V	00:00.0
2021	PO5376104281	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO5395404408	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO4028605700	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4046606437	F	4	50 BRN	SP	S		V	00:00.0
2021	PO4042406008	F	1	35E BRN	SP	S		V	00:00.0
2021	PO4047606585	F	4	50 BRN	SP	S		V	00:00.0
2021	PO4045306293	F	3	50 BRN	SP	S		V	00:00.0
2021	PO4039805825	F	1	50 BRN	SP	CCA		V	00:00.0
2021	PO4044206140	F	3	50 BRN	SP	S		V	00:00.0
2021	PO5422503503	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5418403564	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4150906199	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4184706389	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4176606235	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4174906420	F	3	40 BRN	SP	CCA		V	00:00.0
2021	PO5388902009	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5374002076	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5358502141	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5420902304	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5418102380	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5437402833	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5442703019	F	4	40 BRN	SP	CRE	ED	V	00:00.0
2021	PO5435203016	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4161305968	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5422101924	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5407101946	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4059005026	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6766885124	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6776084966	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6766984889	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6777284754	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6786084658	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6800084508	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6811984615	F	5	35 BRN	SP	CRE		V	00:00.0
2021	PO5503900935	F	5	35 XXX	SP	P		V	00:00.0
2021	PO5531400797	F	6	30 XXX	SP	CRE		V	00:00.0
2021	PO5527100803	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5519500923	F	5	35 XXX	SP	CRE		V	00:00.0
2021	PO5511801068	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5519901087	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4086506744	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4088706567	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4087906430	F	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4073007059	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4080906907	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO5398203738	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5404203703	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5389403789	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4084906291	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5400601012	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4178904842	F	4	40 XXX	SP	P		V	00:00.0
2021	PO9089362207	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0



2021	PO9093662223	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO9096762200	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO4928890454	LGE	3	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO9105062243	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0
2021	PO4432999509	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO6441798381	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6453498310	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO6436198282	F	4	40 XXX	SP	P		V	00:00.0
2021	PO4270487957	LGE	3	50 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO9821491623	LGE	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO9822091681	LGE	4	40 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO9359060919	KU	5	35 XXX	ST	CRE		V	00:00.0
2021	PO9609261407	KU	5	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO4326199688	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4328299657	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4337500006	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4377499544	F	4	40 BRO	SP	CRE	ED,ID,IP	V	00:00.0
2021	PO4373599756	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4330999820	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4335299629	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4342599601	F	5	35 BRO	SP	CRE		V	00:00.0
2021	PO4352299503	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4370099486	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4345999361	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4341899265	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4332699058	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4333799032	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4486398703	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4499298960	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4509399216	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4503299389	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4498199266	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4492099293	F	5	35 BRO	SP	CRE	ED	V	00:00.0
2021	PO4493499158	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4480099008	F	5	35 BRO	SP	CRE	ED	V	00:00.0
2021	PO4486398987	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4480898863	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4469798774	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4475698749	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO4470798633	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021	PO9672562949	KU	6	30 OTH	SP	CCA	ED,SRS	TD	00:00.0
2021	PO4702404299	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO4718104378	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4708104444	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4697204175	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO6460499011	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6458899031	F	2	50 XXX	SP	P		V	00:00.0
2021	PO6466099224	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6476699500	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6469199478	KU	4	40 XXX	SP	S		V	00:00.0
2021	PO6481399621	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6485499728	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6490498858	F	4	40 XXX	SP	P		V	00:00.0
2021	PO6495199978	F	4	40 XXX	SP	P		V	00:00.0

2021	PO6499400087	F	4	40 XXX	SP	P			V			00:00.0
2021	PO6594298248	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6471599368	F	4	40 XXX	SP	CCA		ED,HH,ID	BX		PX	00:00.0
2021	PO6588798402	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6583498313	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6574398367	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6562898433	F	4	40 XXX	SP	P			V			00:00.0
2021	PO6553198391	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6558398509	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6564898628	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6526798550	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6532798655	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6538698759	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6543098837	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO6529998930	F	2	40 XXX	SP	CRE			V			00:00.0
2021	PO6542698881	F	4	40 XXX	SP	P			V			00:00.0
2021	PO6556198830	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO9370061154	KU	5	35 XXX	SP	CRE			V			00:00.0
2021	PO9470462639	KU	5	35 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9499862507	KU	4	40 XXX	SP	CRE		HH,ID	X		PX	00:00.0
2021	PO9493462250	KU	5	35 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9485862052	KU	5	35 XXX	SP	CRE			V			00:00.0
2021	PO9429961632	KU	4	45 XXX	SP	CRE			V			00:00.0
2021	PO8927561239	KU	4	40 BRO	SP	CRE		ED,ID			BD	00:00.0
2021	PO8916661300	KU	4	40 BRO	SP	CCA			V			00:00.0
2021	PO8930261360	KU	6	30 BRO	SP	CRE		ED,ID			BD	00:00.0
2021	PO8934961630	KU	6	30 BRO	SP	CRE		ED,ID			TD	00:00.0
2021	PO9639161204	KU	4	45 UNK	SP	CRE		ID			BD	00:00.0
2021	PO9605761176	KU	5	30 UNK	SP	CRE		ED,ID,IP			TD	00:00.0
2021	PO8940561578	KU	4	40 BRO	SP	CRE		ED,ID			TD	00:00.0
2021	PO8947261795	KU	6	30 BRO	SP	CRE			V			00:00.0
2021	PO9587961111	KU	4	40 UNK	SP	CRE		ED,ID			TD	00:00.0
2021	PO9579260990	KU	4	40 KOP	SP	CRE		ID			BD	00:00.0
2021	PO9570860871	KU	4	40 KOP	SP	CRE		ED,ID			TD	00:00.0
2021	PO8962761743	KU	6	30 BRO	SP	CRE		ED,ID			BD	00:00.0
2021	PO8957661754	KU	4	40 BRO	SP	CCA			V			00:00.0
2021	PO9581661740	KU	5	35 BRO	SP	CRE		ED,ID			TD	00:00.0
2021	PO9594461980	KU	4	40 BRO	SP	CRE		ED,ID			TD	00:00.0
2021	PO9618561807	KU	4	40 BRO	SP	CRE		ED,ID			TD	00:00.0
2021	PO9355161374	KU	5	35 XXX	SP	CCA			V			00:00.0
2021	PO9361961385	KU	4	40 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9382760631	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO9363260649	KU	2	50 XXX	SP	CCA			V			00:00.0
2021	PO9387060409	KU	4	40 XXX	SP	CCA			V			00:00.0
2021	PO9377860534	KU	4	40 XXX	SP	P		ED			T	00:00.0
2021	PO9396460518	KU	5	35 XXX	SP	CCA			V			00:00.0
2021	PO9390760717	KU	5	35 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9373760698	KU	6	30 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9398860799	KU	5	35 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9405860914	KU	5	35 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9416460998	KU	6	30 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9402861193	KU	5	35 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9410461315	KU	4	30 XXX	SP	CRE		ID			TD	00:00.0
2021	PO9383161086	KU	5	35 XXX	SP	CRE			V			00:00.0

2021	PO9433562696	KU	6	30 XXX	SP	CRE		V	00:00.0	
2021	PO9562060749	KU	4	40 KOP	SP	CRE	ED,ID,JP	TD	00:00.0	
2021	PO9136657454	KU	5	35 BRO	SP	CRE		V	00:00.0	
2021	PO9121057433	F	2	45 UNK	SP	CCA		V	00:00.0	
2021	PO9132457301	KU	5	35 UNK	SP	CRE	ED,ID,JP	TD	00:00.0	
2021	PO4692703753	F	2	40 BRN	SP	CRE		V	00:00.0	
2021	PO4681703806	F	2	40 BRN	SP	CRE		V	00:00.0	
2021	PO4693004075	F	2	40 BRN	SP	CRE		V	00:00.0	
2021	PO4688603969	F	2	40 BRN	SP	CRE		V	00:00.0	
2021	PO4684303866	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO9104457333	F	6	30 BRO	SP	CRE		V	00:00.0	
2021	PO4722803914	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4727704014	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4734704128	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4718003810	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO9106157237	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9104257256	F	5	35 UNK	SP	CRE		V	00:00.0	
2021	PO9105157106	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO9618861946	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021	PO9547462160	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9105256967	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO9087457054	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9062057073	F	4	40 UNK	SP	P		V	00:00.0	
2021	PO9073157075	F	4	40 UNK	SP	P		V	00:00.0	
2021	PO9077356786	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9084957079	F	4	40 UNK	SP	P		V	00:00.0	
2021	PO9068056920	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9533059384	F	4	45 OTH	SP	CRE		V	00:00.0	
2021	PO9517659554	F	4	35 OTH	SP	P		V	00:00.0	
2021	PO9507159652	F	3	50 OTH	SP	P		V	00:00.0	
2021	PO9526159388	F	5	35 OTH	SP	P		V	00:00.0	
2021	PO9533359457	F	3	40 OTH	SP	P		V	00:00.0	
2021	PO9533559578	F	3	50 OTH	SP	P		V	00:00.0	
2021	PO9503659593	F	4	35 OTH	SP	CCA		V	00:00.0	
2021	PO9519359599	F	3	50 OTH	SP	CRE		V	00:00.0	
2021	PO9471859758	KU	4	40 OTH	SP	CCA		V	00:00.0	
2021	PO9488959647	KU	2	50 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021	PO9494159687	F	4	35 OTH	SP	CCA		V	00:00.0	
2021	PO9492259762	F	3	50 OTH	SP	P		V	00:00.0	
2021	PO9488059792	F	5	35 OTH	SP	P		V	00:00.0	
2021	PO9484259529	KU	2	60 OTH	SP	CCA		V	00:00.0	
2021	PO9481359704	KU	4	40 OTH	SP	CCA	ED,SRS	TD	00:00.0	
2021	PO9496559726	F	3	50 OTH	SP	CRE		V	00:00.0	
2021	PO9487259401	KU	5	35 OTH	SP	CRE	ID	BD	00:00.0	
2021	PO9031456699	F	5	35 BRO	SP	CRE		V	00:00.0	
2021	PO90016356401	F	4	40 BRO	SP	CCA		V	00:00.0	
2021	PO9003656027	KU	2	45 KOP	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO9004356172	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO9507259067	KU	5	35 UNK	SP	CRE		V	00:00.0	
2021	PO6567098786	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO6573198637	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO6578198573	KU	6	30 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021	PO6614598339	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO6583598514	F	4	40 XXX	SP	P		V	00:00.0	

2021	PO6592098436	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6601998392	F	4	40 XXX	SP	CRE	ED,ID,JP	BX	RP2	00:00.0
2021	PO6505198806	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6501598741	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6498398686	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6492398807	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6480298870	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6453498904	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6466498893	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6445998718	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6460998629	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6361299178	F	3	40 XXX	SP	P		V		00:00.0
2021	PO6372999091	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6380699053	F	4	40 XXX	SP	CRE	ED,ID	BX	RP2	00:00.0
2021	PO6399398956	KU	3	40 XXX	SP	P	ED,ID	BD		00:00.0
2021	PO6390099007	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6409398900	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6440198726	F	3	40 XXX	SP	P		V		00:00.0
2021	PO6420098838	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6429798781	F	4	40 XXX	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO6451998656	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6458098628	F	4	40 XXX	DF	P	ED,HH,ID	BX	PX	00:00.0
2021	PO6453098544	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO9559062225A	KU	5	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO9658656470	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO9559062225	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9567162166	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9594962190	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9604362333	KU	5	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9631056311	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO9628256372	KU	4	40 BRN	SP	CRE	ED,ID,JP	TD		00:00.0
2021	PO4712403661	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4749504178	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4731004304	F	5	35 BRN	SP	CRE		V		00:00.0
2021	PO4740304239	F	4	40 BRN	SP	CRE		V		00:00.0
2021	59401A	KU	6	30 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021	PO9562859295	F	4	50 OTH	SP	CRE		V		00:00.0
2021	PO9542959234	F	4	40 OTH	SP	P		V		00:00.0
2021	PO9554959027	F	4	40 OTH	SP	P		V		00:00.0
2021	PO9475659274	KU	3	50 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9542859266	F	2	60 OTH	SP	P		V		00:00.0
2021	PO9485059269	KU	2	55 OTH	SP	CCA		V		00:00.0
2021	PO9634762492	KU	5	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9663056851	KU	5	45 BRN	SP	CRE	ED,ID,JP	TD		00:00.0
2021	PO4643502885	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO9569259312	KU	3	50 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9629759758	KU	4	45 OTH	SP	CCA		V		00:00.0
2021	PO9528659259	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9495359264	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9511859257	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9554659093	F	4	30 OTH	SP	P		V		00:00.0
2021	PO9529259133	KU	4	40 OTH	SP	CRE	ID	BD		00:00.0
2021	PO9533259012	F	3	45 OTH	SP	P		V		00:00.0
2021	PO9617956403	KU	3	50 BRN	SP	CRE	ED,ID	TD		00:00.0

2021 PO9610862280	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9498959112	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO9475458902	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9475759138	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9477859137	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9475559026	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9462359176	KU	5	35 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO9666362864	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9633156686	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 N/A	F	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4627503819	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4658103654	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4665803461	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4610403888	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4647903687	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4615403803	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4616903871	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4635903766	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9665762751	KU	5	30 BRO	SP	S		V	00:00.0
2021 PO9637962779	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9637962779A	KU	3	20 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9586856224	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9626262799	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9637162813	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9456759015	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9458259112	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9455159050	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9436759200	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9435259063	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO9451458867	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9436859005	KU	2	55 BRO	SP	CCA		V	00:00.0
2021 PO9432958817	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9418759090	KU	4	45 UNK	SP	CRE	ED,HH,ID,RB	BX PX	00:00.0
2021 PO4669702771	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4651003140	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4602503205	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8107519407	ODP	5	30 BRN	SP	CRE	ED	TD	00:00.0
2021 PO8100519495	ODP	4	40 BRN	SP	CRE	ED,SRC	TD	00:00.0
2021 PO8485221828	ODP	4	45 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO9462731527	ODP	5	45 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8372621327	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8365821485	ODP	5	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO4711889980	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8180720012	ODP	6	30 BRN	SP	CRE	ED	TD	00:00.0
2021 PO8071919511	ODP	4	40 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO6633018634	ODP	4	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO6615618591	ODP	2	50 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6597018531	ODP	2	50 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO5363212884	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO8101519668	ODP	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7372319897	ODP	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5368712860	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9969036080	ODP	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9410632801	ODP	5	45 UNK	SP	CRE	ED,ID	TD	00:00.0

2021 PO8514921910	ODP	4	45 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8580321997	ODP	3	50 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8559821970	ODP	4	45 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8543721990	ODP	4	45 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO9533732936	ODP	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4946588999	LGE	2	60 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO7408119905	ODP	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO4803488753	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4802188749	LGE	4	35 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO9473631258	ODP	5	45 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7403320534	ODP	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4929789368	LGE	2	45 ACE	SP	CCA	ED	TD	00:00.0
2021 PO4896188970	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5306708072	KU	2	45 BRN	SP	CRE	ED,EP,ID	TD	00:00.0
2021 PO0892541574	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0931041832	ODP	5	35 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO6656918692	ODP	2	50 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO8900722968	ODP	2	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5469611914	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO1061942824	ODP	4	40 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO5419711534	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO4829789404	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4976889584	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO8910222859	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5431412014	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO8177119751	ODP	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7402920654	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8227720806	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO4718689944	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4828389446	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4718389955	LGE	4	35 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8101020619	ODP	5	40 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8120720650	ODP	5	40 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8210820780	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8271119955	ODP	5	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4935089358	LGE	3	45 ACE	SP	CCA	ED	TD	00:00.0
2021 PO5493011860	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO7402520400	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4932389363	LGE	3	45 ACE	SP	CCA	ED,MD	TD	00:00.0
2021 PO6798318936	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6781218902	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6761818871	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6736518825	ODP	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6667518716	ODP	4	50 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4829289424	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO9406127427	ODP	5	35 XXX	DF	CRE	ED,ID,IP	TD	00:00.0
2021 PO9427927352	ODP	2	50 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9455630706	ODP	6	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4733089834	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO9408827761	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8112720929	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0667240253	ODP	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO0276833704	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0285133567	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0

2021 PO0683040115	ODP	4	40 OTH	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8990021889	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7518217074	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9158425420A	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4831889461	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4941989351	LGE	3	50 ACE	SP	CCA	ED	TD	00:00.0
2021 PO4810988744	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7487243881	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7500543934	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4979189770	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO7039454184	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7762244689	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7755944819	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7750144941	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7752644986	ODP	5	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7468543873	ODP	4	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7468543873A	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO0267433452	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO7726144706	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5487921038	KU	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5499020916	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO0214733020	ODP	4	35 XXX	SP	CCA	ED,ID,IP	TD	00:00.0
2021 PO7531143580	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7533143442	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7518043340	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7753444224	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7756944093	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4973089834	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO7491543255	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO0653139645	ODP	5	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4976789816	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4831989455	LGE	4	40 BRN	SP	P	ED,ID,IP	TD	00:00.0
2021 PO9123625344	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9158425420	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4969689524	LGE	3	45 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4968889513	LGE	3	45 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4968889512	LGE	3	45 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO5433803896	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO0283438219	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7538716509	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7526616755	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4832489442	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4832289447	LGE	4	40 BRN	SP	P	ED,ID,IP	TD	00:00.0
2021 PO4863488958	LGE	1	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO0281433783	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5577720236	KU	5	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5587120322	KU	5	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7469343178	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7388042908	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4947490092	LGE	3	45 BRN	SP	A	ED,ID,MD	TD	00:00.0
2021 PO4980489750	LGE	4	35 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO7550044054	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4978789762	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO7019454128	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0

2021 PO7000554073	ODP	3	45 BRO	SP	CCA		TD	00:00.0
2021 PO0267333632	ODP	5	35 BRN	SP	CCA	ED	T	00:00.0
2021 PO0289433862	ODP	6	30 BRN	SP	CCA	ED	T	00:00.0
2021 PO4869089954	LGE	3	45 BRN	SP	A	ED,ID	T	00:00.0
2021 PO4863688955	LGE	1	50 BRN	SP	A	ED	T	00:00.0
2021 PO0614739463	ODP	4	45 BRO	SP	CCA	ED,MD,SRC	T	00:00.0
2021 PO4943589975	LGE	3	45 BRN	SP	P	ED,ID	T	00:00.0
2021 PO0609639717	ODP	2	50 BRO	SP	CCA	ED,MD,SRC	T	00:00.0
2021 PO7515243951	ODP	5	35 KOP	SP	CRE		T	00:00.0
2021 PO4838989325	LGE	4	40 BRN	SP	A	ED	T	00:00.0
2021 PO4838089351	LGE	4	40 BRN	SP	A	ED	T	00:00.0
2021 PO9396327750	ODP	6	30 XXX	SP	S	ED	T	00:00.0
2021 PO4930090002	LGE	4	35 BRN	SP	P	ED,ID	T	00:00.0
2021 PO8901122673	ODP	6	30 BRO	SP	CRE	ED,ID	T	00:00.0
2021 PO1098343455	ODP	6	30 BRO	SP	CCA	ED,MD,SRC	T	00:00.0
2021 PO9105423374	ODP	5	35 BRO	SP	CCA		T	00:00.0
2021 PO5543611699	KU	6	30 KOP	SP	CCA	ED,ID	T	00:00.0
2021 PO4839389135	LGE	4	40 BRN	SP	CRE	ED	T	00:00.0
2021 PO4837889121	LGE	4	40 BRN	SP	CRE	ED	T	00:00.0
2021 PO9992336405	ODP	5	30 OTH	SP	CRE		T	00:00.0
2021 PO9001922929	ODP	4	40 BRO	SP	CRE	ED	T	00:00.0
2021 PO9298923131	ODP	6	30 UNK	SP	CRE		T	00:00.0
2021 PO9072622597	ODP	4	45 BRO	SP	CRE		T	00:00.0
2021 PO4823588621	LGE	4	30 BRO	SP	CCA	ED	T	00:00.0
2021 PO4839489309	LGE	4	40 BRN	SP	A	ED	T	00:00.0
2021 PO9056123236	ODP	4	40 REP	SP	CCA		T	00:00.0
2021 PO9334525207	ODP	4	45 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021 PO9323325223	ODP	5	35 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021 PO5953598892	LGE	4	30 BRN	SP	CCA	ED	T	00:00.0
2021 PO5543211599	KU	6	30 OTH	SP	CCA	ED,SRC	T	00:00.0
2021 PO4844289310	LGE	4	40 BRN	SP	CCA	ED	T	00:00.0
2021 PO5362111929	KU	6	30 BRN	SP	S	ED,SRC	T	00:00.0
2021 PO0291137682	ODP	4	45 BRO	SP	CCA		T	00:00.0
2021 PO0338137543	ODP	4	45 BRO	SP	CCA		T	00:00.0
2021 PO4862688949	LGE	4	30 BRN	SP	CCA	ED	T	00:00.0
2021 PO0311537875	ODP	4	45 BRO	SP	CCA		T	00:00.0
2021 PO7356216464	ODP	4	45 BRN	SP	CCA	ED	T	00:00.0
2021 PO0621938422	ODP	2	50 BRO	SP	CCA		T	00:00.0
2021 PO6904223488	ODP	2	50 BRO	SP	CRE	MD,SRC	T	00:00.0
2021 PO4899189001	LGE	4	40 BRO	SP	CCA	ED	T	00:00.0
2021 PO4862088615	LGE	4	40 BRN	SP	CRE	ED	T	00:00.0
2021 PO4860688622	LGE	4	35 BRN	SP	CRE	ED	T	00:00.0
2021 PO4931589979	LGE	4	35 BRN	SP	P	ED,ID	T	00:00.0
2021 PO4845889324	LGE	3	45 BRN	SP	A	ED	T	00:00.0
2021 PO4846689323	LGE	4	40 BRN	SP	A	ED	T	00:00.0
2021 PO5464012612	KU	5	35 OTH	SP	P	ED,ID	T	00:00.0
2021 PO0168134316	ODP	4	45 BRN	SP	CCA	ED	T	00:00.0
2021 PO0209934288	ODP	4	45 BRN	SP	CCA	ED	T	00:00.0
2021 PO9235724017	ODP	5	35 BRO	SP	CCA		T	00:00.0
2021 PO4849488905	LGE	4	25 BRN	SP	CRE	ED	T	00:00.0
2021 PO9042020134	ODP	4	40 KOP	SP	S	ED,SRC,SRS	T	00:00.0
2021 PO1124243249	ODP	6	30 BRO	SP	CCA	ED,MD,SRC	T	00:00.0
2021 PO0028636547	ODP	6	30 OTH	SP	CCA		T	00:00.0
2021 PO0140236801	ODP	4	45 BRN	SP	CCA		T	00:00.0



2021 PO1190143462	ODP	4	40 BRO	SP	CRE	ED, SRC	T			00:00.0
2021 PO0257933532	ODP	5	35 BRN	SP	CCA	ED	T			00:00.0
2021 PO0612638706	ODP	4	45 BRO	SP	CCA		T			00:00.0
2021 PO9280225973	ODP	4	45 XXX	SP	S	ED, MD, SRC	T			00:00.0
2021 PO4911488967	LGE	4	40 BRO	SP	CCA	ED	T			00:00.0
2021 PO5479709687	KU	6	30 BRN	SP	S	ED, SRC	T			00:00.0
2021 PO5415811386	KU	4	40 OTH	SP	CRE	ED, ID	BX		RP2	00:00.0
2021 PO5306009106	KU	3	45 BRN	SP	CRE	HH, ID, RB	BX		PX	00:00.0
2021 PO5424911771	KU	4	40 OTH	SP	CRE	ED, ID, RB	BX		PX	00:00.0
2021 PO1114343030	ODP	4	40 UNK	SP	CRE	ED, HH, ID	BX		PX	00:00.0
2021 PO4720389888	LGE	4	30 ACE	SP	CRE	ED, HH, ID, RB	BX		RP1	00:00.0
2021 PO4821288688	LGE	4	40 BRO	SP	P	ED, ID, IP, RB	BX		RP3	00:00.0
2021 PO4820288783	LGE	5	25 BRO	SP	CRE	ED, HH, ID, IP	BX		PX	00:00.0
2021 PO6937722481	ODP	4	40 UNK	SP	CRE	ED, HH, ID	BX		PX	00:00.0
2021 PO0694039856	ODP	5	35 BRN	SP	CRE	ED, HH, ID, RB	BX		PX	00:00.0
2021 PO5412909490	KU	3	45 OTH	SP	CRE	ED, EP, ID, IP	BX		PX	00:00.0
2021 PO4826188791	LGE	5	25 BRO	SP	CRE	ED, HH, ID	BX		RP1	00:00.0
2021 PO5525612342	KU	3	45 OTH	SP	CRE	ED, ID, RB	BX		PX	00:00.0
2021 PO4960489388	LGE	3	45 ACE	SP	A	ED, HH, ID, IP, MD	BX		RP2	00:00.0
2021 PO4727289920	LGE	4	30 ACE	SP	CRE	ED, HH, ID, RB	BX		PX	00:00.0
2021 PO5483410875	KU	3	45 OTH	SP	P	ED, ID	BX		PX	00:00.0
2021 PO4825689356	LGE	2	65 BRN	SP	CRE	ED, EP, HH, ID, IP, RB	BX		PX	00:00.0
2021 PO4828488796	LGE	4	35 BRO	SP	CCA	ED, HH, ID, IP, MD, RB	BX		RP1	00:00.0
2021 PO5504312440	KU	3	45 OTH	SP	CRE	ED, ID, RB	BX		PX	00:00.0
2021 PO5347512409	KU	3	45 BRN	SP	CRE	HH, ID, IP, RB	BX		RP1	00:00.0
2021 PO5359912366	KU	3	45 BRN	SP	CRE	ED, HH, ID, IP, RB	BX		PX	00:00.0
2021 PO5346012555	KU	3	45 BRN	SP	CRE	HH, ID, RB	BX		RP1	00:00.0
2021 PO5371212322	KU	3	45 BRN	SP	CRE	HH, ID, IP, RB	BX		RP2	00:00.0
2021 PO5487012405	KU	4	40 OTH	SP	CRE	ED, EP, ID, IP, RB	BX		PX	00:00.0
2021 PO5413711305	KU	4	40 OTH	SP	CRE	ED, ID	BX		PX	00:00.0
2021 PO5307609323	KU	3	45 BRN	SP	CRE	HH, ID, IP	BX		PX	00:00.0
2021 PO5439012271	KU	4	40 OTH	SP	CRE	ED, HH, ID, RB	BX		PX	00:00.0
2021 PO5455112625	KU	4	45 OTH	SP	CRE	ED, EP, HH, ID, IP, RB	BX		PX	00:00.0
2021 PO5466111739	KU	4	40 ACW	SP	CRE	ED, ID, RB	BX		RP2	00:00.0
2021 PO4933490025	LGE	3	45 BRN	SP	CRE	ED, HH, ID, IP	BX		RP1	00:00.0
2021 PO4977089812	LGE	4	30 ACE	SP	CRE	ED, ID	BX		RP2	00:00.0
2021 PO4734990072	LGE	4	30 ACE	SP	CRE	ED, ID, IP	BD			00:00.0
2021 PO7449043110	ODP	5	35 KOP	SP	CRE	ED	BD			00:00.0
2021 PO0226933454	ODP	4	40 XXX	SP	CRE	ED, ID	BD			00:00.0
2021 PO4939589994	LGE	4	30 BRN	SP	P	ED, ID	BD			00:00.0
2021 PO4944089983	LGE	4	30 BRN	SP	P	ED, ID	BD			00:00.0
2021 PO4945389969	LGE	4	30 BRN	SP	P	ED, ID	BD			00:00.0
2021 PO4865588590	LGE	4	40 BRN	SP	CRE	ED, ID	BD			00:00.0
2021 PO4944789963	LGE	3	45 BRN	SP	P	ED, ID	BD			00:00.0
2021 PO5572420115	KU	4	40 OTH	SP	CRE	ED, ID, IP	BD			00:00.0
2021 PO5284406313	KU	3	45 BRN	SP	CRE	ID	BD			00:00.0
2021 PO5296206742	KU	3	45 BRN	SP	CRE	ID	BD			00:00.0
2021 PO5289506491	KU	3	45 BRN	SP	CRE	ID	BD			00:00.0
2021 PO5553199053	F	4	40 XXX	SP	P		V			00:00.0
2021 PO5550499002	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO5560598948	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO5568998958	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO5578098973	F	4	40 XXX	SP	CRE		V			00:00.0
2021 PO5581799051	F	4	40 XXX	SP	CRE		V			00:00.0

2021 PO5573599142	F	3	40 XXX	SP	P		V	00:00.0	
2021 PO5566099227	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO1488577439	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO1491877106	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO1466077169	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO1494877289	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO1448676961	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5027788437	LGE	3	50 BRN	SP	P	ED,ID	TD	00:00.0	
2021 PO5027688419	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO7201401985	LGE	4	40 BRO	SP	A	ED,ID,IP,RB	TX	RR	00:00.0
2021 PO5026088412	LGE	4	35 BRN	SP	A	ED,ID	TD	00:00.0	
2021 PO5023088411	LGE	2	50 BRN	SP	P	ED,ID	T	00:00.0	
2021 PO5052689574	LGE	4	40 ACE	SP	P	ED,ID	BD	00:00.0	
2021 PO5053989576	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO5053889581	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO4989788644	LGE	3H	55 BRO	SP	A		V	00:00.0	
2021 PO0502863343	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0389563762	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO0315363812	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4983788613	LGE	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO4974488606	LGE	3H	45 BRO	ST	S		V	00:00.0	
2021 PO4987088629	LGE	2	55 BRO	SP	CCA		V	00:00.0	
2021 PO4983588621	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4969088858	LGE	4	40 BRO	SP	CRE		V	00:00.0	
2021 PO5025988420	LGE	2	55 BRN	SP	P	ED,ID	BD	00:00.0	
2021 PO5050789559	LGE	4	35 ACE	SP	CCA		V	00:00.0	
2021 PO5013188893	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0	
2021 PO1428876713	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO1433976688	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO5049789550	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4980588619	LGE	2	50 BRO	SP	A	ID	BD	00:00.0	
2021 PO6901599479	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO1074279668	KU	4	40 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO5631205934	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO2116166019	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO4824091055	LGE	2	55 BRN	SP	CCA		V	00:00.0	
2021 PO6018250292	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO6009750419	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4824091078	LGE	3	50 BRN	SP	CCA		V	00:00.0	
2021 PO4824791100	LGE	2	55 BRN	SP	CCA		V	00:00.0	
2021 PO4826391117	LGE	2	55 BRN	SP	CCA		V	00:00.0	
2021 PO4827091125	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO2096066018	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO5602405483	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO5567305148	F	4	45 BRN	SP	A		V	00:00.0	
2021 PO2082065918	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO5586005074	F	4	45 BRN	SP	A		V	00:00.0	
2021 PO4829590885	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4837190905	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO5416122009	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4834590899	LGE	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO5600305292	F	4	40 BRN	SP	CRE	HH	VX	RP1	00:00.0
2021 PO5989550590	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0	
2021 PO5980050395	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0	

2021	PO5975750193	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021	PO5971749988	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021	2082065918a	F	5	40 BRO	SP	CCA		V	00:00.0
2021	PO5589906035	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO9562256965	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO9559157419	KU	3	45 BRO	SP	CCA	ID	BD	00:00.0
2021	PO4316587059	LGE	UNK	50 ACE	SP	CRE	ED,HH,ID	VX PX	00:00.0
2021	PO6195388327	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO4313587086	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4314987074	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4314287080	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO5032288504	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021	PO5029688527	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021	PO5030088529	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO5029588522	LGE	4	40 ACE	SP	P		V	00:00.0
2021	PO6171288379	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO1482973229	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO1456373682	KU	3	45 BRO	SP	CRE		V	00:00.0
2021	PO1467773676	KU	6	35 BRO	SP	CRE		V	00:00.0
2021	PO1458873644	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO1384673472	KU	3	45 BRO	SP	CRE		V	00:00.0
2021	PO9536458663	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO5954788921	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5970288923	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5985788924	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO6001388926	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO6017088928	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO9477958716	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO1419873664	KU	3	45 BRO	SP	CRE		V	00:00.0
2021	PO4044504595	F	1	50 BRN	SP	CRE		V	00:00.0
2021	PO4033504610	F	4	40 BRN	SP	S		V	00:00.0
2021	PO4063104182	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4053504358	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO4032804454	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO1427973497	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO4313587217	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO5590804586	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5602004544	KU	5	35 BRN	SP	CRE		BD	00:00.0
2021	PO5600904586	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5590404538	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5589404481	F	4	40 BRN	SP	CRE	ED,HH,ID,IP,RB	VX PX	00:00.0
2021	PO5591304635	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO2042766539	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO2005766513	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO1353482515	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO2026966617	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO2011466830	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5580004629	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5566404682	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO5563204693	KU	6	30 BRN	SP	CRE	ED	BD	00:00.0
2021	PO1976467238	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5030988469	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5031588476	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5038688602	LGE	4	35 BRN	SP	P		V	00:00.0

2021	PO5040088657	LGE	4	30 BRN	SP	P		V	00:00.0
2021	PO5038288796	LGE	UNK	40 BRN	SP	CRE		V	00:00.0
2021	PO7473001342	LGE	3	50 BRN	SP	P		V	00:00.0
2021	PO5051688734	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO5053288726	LGE	3H	50 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO5370299560	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5371899692	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5373799826	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5375599964	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5377400103	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5380800352	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5379400243	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5399600269	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5405400110	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5403799981	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5401799841	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5400299715	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5398999610	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5397999534	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5396399434	F	4	40 XXX	SP	CRE	ED,ID	BX PX	00:00.0
2021	PO2193256088	KU	4	40 XXX	SP	CRE		V	00:00.0
2021	PO2197256329	KU	6	30 XXX	SP	CRE		V	00:00.0
2021	PO1436574275	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9998459126	KU	4	40 BRO	SP	CCA		V	00:00.0
2021	PO9971459214	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4247505494	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO4270805558	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4225605316	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4271005483	F	3	50 BRN	SP	CRE		V	00:00.0
2021	PO4261405475	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4233405315	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4234105394	KU	3	45 BRN	SP	CRE		V	00:00.0
2021	PO9829258080	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO4313187006	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4314587032	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4313887024	LGE	4	40 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO9777458975	KU	4	40 BRO	SP	CRE		V	00:00.0
2021	PO9592259431	KU	6	35 BRO	SP	CRE		V	00:00.0
2021	PO9631858746	KU	4	40 BRO	SP	S		V	00:00.0
2021	PO1298274487	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4950688458	LGE	2	55 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4315287032	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4315887050	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4316187045	LGE	4	35 ACE	SP	CRE	ED,HH	TD	00:00.0
2021	PO1278474620	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4953988437	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4956788437	LGE	2	60 BRO	SP	CCA	ED,ID	T	00:00.0
2021	PO4955688472	LGE	2	60 BRO	SP	CCA	ED	T	00:00.0
2021	PO2062552210	KU	6	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2098552360	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2106152295	KU	3	45 XXX	SP	CCA		V	00:00.0
2021	PO2116352324	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO2116652398	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021	PO2126552442	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0

2021	PO2139352449	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO2159052488	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0	
2021	PO5510499406	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO5505399294	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO5499199160	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO5494999060	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO4321206089	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4252006105	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4267606127	KU	6	30 BRN	SP	CRE		V	00:00.0	
2021	PO4281006060	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4266206053	F	4	40 BRN	SP	A		V	00:00.0	
2021	PO4301306077	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4231106184	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4311087060	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0	
2021		4310387063	LGE	1	60 ACE	SP	CCA	V	00:00.0	
2021	PO6307189336	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0	
2021	PO1140974848	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4325087035	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO4325687041	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO9710056791	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO9708856658	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO9723756656	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4306787094	LGE	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0	
2021	PO4307687088	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4308487081	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4309187075	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4309587077	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4309987068	LGE	1	50 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021	PO4306387097	LGE	3	45 ACE	SP	CRE		V	00:00.0	
2021	PO4306187099	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO4315087149	F	4	35 BRO	SP	CRE		V	00:00.0	
2021	PO4305387106	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021	PO1818870863	KU	4	40 BRO	SP	CRE	ED,ID	TX	RR	00:00.0
2021	PO4316387164	LGE	3	50 BRO	SP	A	ED,ID,IP	TD	00:00.0	
2021	PO0487257300	KU	2	65 BRO	SP	CRE		V	00:00.0	
2021	PO5190598850	F	2	40 XXX	SP	CRE		V	00:00.0	
2021	PO5195699011	F	3	45 XXX	SP	CRE		V	00:00.0	
2021	PO5197199059	F	3	45 XXX	SP	CRE		V	00:00.0	
2021	PO5204499288	F	3	50 XXX	SP	CRE		V	00:00.0	
2021	PO5618998766	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO5608398747	F	4	40 XXX	SP	CRE	ED,EP,ID,IP,MD	VX	PX	00:00.0
2021	PO5627198817	F	4	40 XXX	SP	CRE	ED,ID,MD	BX	RP3	00:00.0
2021	PO5595198907	F	4	40 XXX	SP	CRE	ED,EP,ID,IP,MD	BX	PX	00:00.0
2021	PO5586798725	F	4	40 XXX	SP	CRE		V	00:00.0	
2021	PO6698494659	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO6675594713	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO6656194474	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO6652794426	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO6681094779	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO6687494736	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO5438799744	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO5431999771	F	3	40 XXX	SP	P		V	00:00.0	
2021	PO5463499648	F	4	40 XXX	SP	P		V	00:00.0	
2021	PO5425799794	F	4	40 XXX	SP	P		V	00:00.0	

2021	PO5427099504	F	4	40 XXX	SP	P		V		00:00.0
2021	PO542899656	F	3	40 XXX	SP	P		V		00:00.0
2021	PO5449899405	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5438199447	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5471199250	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021	PO5465699129	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5459199066	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5476399362	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5486699583	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5481799478	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5407199256	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4963888537	LGE	3	45 BRO	SP	A	ED,ID	TD		00:00.0
2021	PO2121650595	KU	4	40 XXX	SP	CRE	HH	X	PX	00:00.0
2021	PO2096550992	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2086950914	KU	4	40 XXX	SP	CRE	ID,IP	TD		00:00.0
2021	PO4961588599	LGE	3	45 BRO	SP	A	ID,IP	BD		00:00.0
2021	PO5033189627	LGE	3	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO5030089641	LGE	3	45 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO5031389635	LGE	3	45 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO6558489210	KU	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6569788866	KU	3	50 BRN	SP	CRE		V		00:00.0
2021	PO6563989037	KU	3	50 BRN	SP	CRE		V		00:00.0
2021	PO0153758155	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO0422359672	KU	3	45 BRO	SP	S		V		00:00.0
2021	PO4202804496	F	4	40 BRN	SP	CRE	ED,HH,ID,IP,RB	BX	PX	00:00.0
2021	PO4194104426	KU	6	30 BRN	SP	CRE		V		00:00.0
2021	PO4219204499	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4233204502	F	4	40 BRN	SP	CRE	ID,IP	V		00:00.0
2021	PO6588688746A	F	4	30 BRN	SP	CRE	HH,ID,IP,MD,RB	VX	RP2	00:00.0
2021	PO6588688746	KU	4	40 BRN	SP	CCA		V		00:00.0
2021	PO6575788745	KU	3	45 BRN	SP	CRE		V		00:00.0
2021	PO8883522846	ODP	4	40 BRO	SP	CRE		BD		00:00.0
2021	PO5279406163	KU	3	45 BRN	SP	CRE	ID	BD		00:00.0
2021	PO0161837891	ODP	4	40 BRO	SP	P	ID	BD		00:00.0
2021	PO4972689787	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4973889788	LGE	4	40 ACE	SP	P	ED,ID	BD		00:00.0
2021	PO4944190144	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO4943790142	LGE	6	25 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO4948290080	LGE	1	50 BRN	SP	P	ED,ID	BD		00:00.0
2021	PO5511120776	KU	4	40 OTH	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4809488744	LGE	3	50 BRO	SP	CRE	ID	BD		00:00.0
2021	PO4808488745	LGE	3	55 BRO	SP	CRE	ID	BD		00:00.0
2021	PO5524020623	KU	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO4970489844	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4934490029	LGE	3	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021	PO4974889823	LGE	4	35 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO0223333294	ODP	4	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO4970089807	LGE	4	30 ACE	SP	CCA	ED,ID	BD		00:00.0
2021	PO4943790187	LGE	3	45 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO4970589798	LGE	4	40 ACE	SP	CCA	ED,ID	BD		00:00.0
2021	PO4971189787	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO4949390063	LGE	4	40 BRN	SP	A	ED,ID	BD		00:00.0
2021	PO0500638989	ODP	5	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4980289758	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0

2021	PO5302308052	KU	2	45 BRN	SP	CRE	ID	BD	00:00.0
2021	PO5472412037	KU	4	40 OTH	SP	CRE	ED,ID	BD	00:00.0
2021	PO9403460143	F	4	50 OTH	SP	P		V	00:00.0
2021	PO9414859871	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9477261595	F	4	45 OTH	SP	P		V	00:00.0
2021	PO9382460237	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9400160167	F	4	45 OTH	UN	CRE		V	00:00.0
2021	PO9386259930	F	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9358560308	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9383260059	KU	5	35 OTH	SP	CCA		V	00:00.0
2021	PO9377260261	KU	5	30 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9462361599	KU	2	55 OTH	SP	CCA		V	00:00.0
2021	PO9417659946	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9402660105	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021	PO9347260166	KU	2	50 OTH	SP	CRE		V	00:00.0
2021	PO9472361601	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9342660292	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9452859399	KU	5	35 OTH	UN	CRE		V	00:00.0
2021	PO9469459380	KU	5	35 OTH	UN	CRE		V	00:00.0
2021	PO9469459606	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO9484160368	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO9485360740	KU	5	35 OTH	SP	CCA		V	00:00.0
2021	PO9423359781	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9457759720	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9444959396	KU	4	40 OTH	SP	CCA		V	00:00.0
2021	PO9485360691	KU	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9455259486	KU	5	35 OTH	SP	CRE	ID	BD	00:00.0
2021	PO9439659498	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO9468859461	KU	4	40 OTH	SP	CCA		V	00:00.0
2021	PO9484960543	KU	4	40 OTH	SP	CRE	ED,SRS	TD	00:00.0
2021	PO9450959664	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9406159829	KU	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9468259650	KU	2	60 OTH	SP	CCA		V	00:00.0
2021	PO9413259824	KU	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9447859468	KU	3	45 OTH	SP	CCA		V	00:00.0
2021	PO9516559131	KU	6	30 OTH	SP	CRE		V	00:00.0
2021	PO4564504014	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4569103944	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4558403685	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4606904198	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4523303670	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4644304101	F	2	40 BRN	SP	CRE	ID,IP	V	00:00.0
2021	PO4599904152	F	2	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1 00:00.0
2021	PO4535903602	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4616004259	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4865604406	KU	6	30 BRN	SP	CRE	ID,IP	BD	00:00.0
2021	PO4632304176	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4550903538	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4563203826	F	3	40 BRN	SP	CRE		V	00:00.0
2021	PO4656204026	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO4588204074	F	2	40 BRN	SP	CRE		V	00:00.0
2021	PO4946289008	LGE	4	35 BRO	SP	CCA	ED	T	00:00.0
2021	PO4950789080	LGE	3	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4946989014	LGE	4	30 BRO	SP	CRE	ID,IP	BD	00:00.0

2021	PO0634336897	ODP	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO0630636952	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021	PO0632137066	ODP	6	30 BRN	SP	CCA	ED	T	00:00.0
2021	PO0633337142	ODP	6	30 BRN	SP	CCA	ED	T	00:00.0
2021	PO0630837338	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0637837242	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0631637219	ODP	6	30 BRN	SP	CCA		TD	00:00.0
2021	PO0663537179	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0667337432	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021	PO0660337603	ODP	4	45 BRN	SP	CCA	ED	T	00:00.0
2021	PO0654237812	ODP	2	55 BRN	SP	CCA		V	00:00.0
2021	PO0666337874	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0625638022	ODP	2	50 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0631437786	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0618337754	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021	PO0604837814	ODP	6	30 BRN	SP	CRE	ID,IP	TD	00:00.0
2021	PO0609037712	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0603337677	ODP	5	35 BRN	SP	CRE	HH,ID	X PX	00:00.0
2021	PO0593637529	ODP	6	30 BRN	SP	CRE	HH,ID	X PX	00:00.0
2021	PO4775189258	LGE	3	45 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021	PO4775289260	LGE	3	45 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021	PO4775689257	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021	PO4873405555	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO4769889187	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4784589210	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4780289173	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4782189180	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4783289176	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4780489184	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO4780889199	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021	PO4947089015	LGE	1	50 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4948189016	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021	PO4947789025	LGE	3	45 BRO	SP	A	ED	BD	00:00.0
2021	PO4949189050	LGE	1	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4949789062	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021	PO4950489084	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4950789095	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4776189238	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4776589231	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4777589222	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4952189105	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021	PO4785889208	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4952389108	LGE	1	55 BRO	SP	CCA		V	00:00.0
2021	PO4778989221	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4780589218	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4781189217	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4782489214	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4951089096	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4951589095	LGE	1	50 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4953989143-A	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4953289127	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021	PO4783789212	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO4953989143	LGE	3	45 BRO	SP	A	ED	TD	00:00.0
2021	PO4796089449	F	4	40 ACE	SP	CCA		V	00:00.0



2021 PO4954389154	LGE	3	50 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4954389154-A	LGE	3	45 BRO	SP	A	ID	BD	00:00.0
2021 PO4948289035	LGE	3	45 BRO	SP	A	ED	TD	00:00.0
2021 PO4934089202	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4935789207	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO9250659062	F	4	30 OTH	SP	CRE		V	00:00.0
2021 PO9259759022	F	2	55 OTH	SP	CCA		V	00:00.0
2021 PO4414901417	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4406901361	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4397401294	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9562260586	F	4	50 OTH	SP	CRE		V	00:00.0
2021 PO4332200550	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4337400531	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4354601889	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9498859852	F	3	50 OTH	SP	CRE		V	00:00.0
2021 PO9537460398	F	3	45 OTH	SP	CRE		V	00:00.0
2021 PO9567260130	F	4	35 OTH	SP	CRE		V	00:00.0
2021 PO9576760270	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO4432000783	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4441800855	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4445098140	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4020306863	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4016007108	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3978106037	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4214603624	F	1	30 BRN	SP	S		V	00:00.0
2021 PO3966707649	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO3924708195	KU	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3977105942	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO9569960171	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO9579960089	F	5	35 OTH	SP	CRE		V	00:00.0
2021 PO9513060053	F	3	50 OTH	SP	CRE		V	00:00.0
2021 PO9598161178	KU	7	25 OTH	SP	CCA		V	00:00.0
2021 PO9581461346	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9604461338	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021 PO9597861246	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9620461544	KU	3	45 OTH	SP	CCA	ED,SRS	TD	00:00.0
2021 PO5729991793A	KU	2	40 XXX	SP	P	ED,ID	BD	00:00.0
2021 PO5729991793	F	2	50 XXX	SP	P		V	00:00.0
2021 PO5574392187	KU	4	40 XXX	SP	P	ED,ID	TD	00:00.0
2021 PO5579892137	F	2	50 XXX	SP	P		V	00:00.0
2021 PO5593792023	F	2	60 XXX	SP	P		V	00:00.0
2021 PO5604391932	F	1	65 XXX	SP	P		V	00:00.0
2021 PO5659391459	F	2	55 XXX	SP	P		V	00:00.0
2021 PO5652191521	F	2	45 XXX	SP	P		V	00:00.0
2021 PO5639591627	F	2	45 XXX	SP	P		V	00:00.0
2021 PO5630191709	F	2	55 XXX	SP	P		V	00:00.0
2021 PO6236303297	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6230303565	KU	2	45 XXX	SP	S		V	00:00.0
2021 PO6186502873	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6190503049	F	4	45 XXX	SP	P		V	00:00.0
2021 PO6206603189	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO6191503114	F	3	45 XXX	SP	CRE	ED,ID,IP	BX	RP3 00:00.0
2021 PO6213703211	F	4	45 XXX	SP	CRE		V	00:00.0
2021 PO6159498800	F	5	30 XXX	SP	P		V	00:00.0

2021	PO6190303040	F	4	40 XXX	SP	CRE	ED,ID,IP,MD	BX	RP1	00:00.0
2021	PO6127299173	F	4	40 XXX	SP	CRE	ED,EP,HH,ID,MD	BX	PX	00:00.0
2021	PO4374098366	KU	2	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4396698482	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4420898375	KU	4	40 BRN	SP	CRE	ID,IP	BD		00:00.0
2021	PO9656361267	KU	6	30 OTH	SP	CRE	ED,ID,SRC	TD		00:00.0
2021	PO9644261301	KU	5	35 OTH	SP	CCA	ID	BD		00:00.0
2021	PO9636761421	KU	4	40 OTH	SP	CCA		V		00:00.0
2021	PO9648361335	KU	4	40 OTH	SP	CCA		V		00:00.0
2021	PO4333700999	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4362800104	F	3	45 BRN	SP	CRE	HH,ID,IP	BX	RP3	00:00.0
2021	PO4316300800	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4302600349	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4343000155	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4328301013	F	4	45 BRN	SP	CRE		V		00:00.0
2021	PO4320700920	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4325100257	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4337700207	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4350500144	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4312000682	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4311700316	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4307200551	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4301300386	F	3	45 BRN	SP	CCA		V		00:00.0
2021	PO4322601030	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO9684161634	KU	5	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9655861054	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9658461133	KU	4	40 OTH	SP	CRE	ED,SRS	TD		00:00.0
2021	PO9680461492	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9663061271	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO4369700037	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4395899975	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4375200055	F	3	45 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021	PO4377600122	KU	6	30 BRN	SP	CRE	ID,IP	BD		00:00.0
2021	PO4386000012	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4380899984	KU	5	35 BRN	SP	CRE	ID,IP	BD		00:00.0
2021	PO9539759705	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9529059800	F	3	50 OTH	SP	P		V		00:00.0
2021	PO9550159583	F	3	45 OTH	SP	CRE		V		00:00.0
2021	PO9529059850	F	3	50 OTH	SP	P		V		00:00.0
2021	PO9550659539	F	5	35 OTH	SP	CRE		V		00:00.0
2021	PO9519859885	F	4	45 OTH	SP	P		V		00:00.0
2021	PO9593859577	KU	5	35 OTH	SP	CRE	ID	BD		00:00.0
2021	PO9618059791	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9607959699	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9566159586	F	5	30 OTH	SP	CRE		V		00:00.0
2021	PO9564459628	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO9615960345	KU	3	45 OTH	SP	CCA		V		00:00.0
2021	PO9737762406	KU	3	50 OTH	SP	CRE		V		00:00.0
2021	PO9719962402	KU	3	50 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9698562395	KU	4	40 OTH	SP	P	ED,ID,SRS	TD		00:00.0
2021	PO9662062602	KU	3	40 OTH	SP	CRE	ID	BD		00:00.0
2021	PO9672362596	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9665862604	KU	3	50 OTH	SP	CRE	ID	BD		00:00.0
2021	PO9685262583	KU	4	40 OTH	UN	CRE		V		00:00.0

2021	PO9601759929	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO9592359825	F	4	40 OTH	SP	P	ED	BX	RP3	00:00.0
2021	PO9587859698	KU	5	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9584059753	F	4	40 OTH	SP	CRE		V		00:00.0
2021	PO9588459860	F	6	30 OTH	SP	CRE		V		00:00.0
2021	PO9667960394	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9615960345	KU	4	40 OTH	SP	CCA		V		00:00.0
2021	PO4772289173	LGE	4	30 ACE	SP	CRE	ED,ID	BD		00:00.0
2021	PO4937588514	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4773789170	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO4775089166	LGE	4	30 ACE	SP	CRE	ED,HH,ID	BX	RP1	00:00.0
2021	PO4776489163	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO4777189162	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4778489158	LGE	4	40 ACE	SP	CRE	ED,EP,ID,RB	BX	RP1	00:00.0
2021	PO4938988519	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO5864217002A	ODP	6	30 BRN	SP	CCA		V		00:00.0
2021	PO5853816962	ODP	5	30 BRN	SP	CCA		V		00:00.0
2021	PO5872217007	ODP	4	45 BRN	SP	CCA		V		00:00.0
2021	PO6526498218	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021	PO6516898194	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021	PO6516898194-A	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO4779989155	LGE	4	40 ACE	SP	A	ED,ID	BD		00:00.0
2021	PO5864516863	ODP	6	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO0563335695	ODP	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021	PO0571035781	ODP	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021	PO0577835732	ODP	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021	PO4930788655	LGE	5	25 BRO	SP	CCA		V		00:00.0
2021	PO4932588633	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4932188640	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO4929488606	LGE	4	35 BRO	SP	CCA		V		00:00.0
2021	PO4796289388	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO4801189431	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO6071818043	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6085118150	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6433120676	F	4	40 UNK	SP	CRE		V		00:00.0
2021	PO6414220619	ODP	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021	PO6405620641	ODP	5	35 KOP	SP	CRE		V		00:00.0
2021	PO6399920660	ODP	6	30 KOP	SP	CRE	ED,ID	TD		00:00.0
2021	PO4938588664	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021	PO7426518295	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO7459018624	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO7476618554	ODP	6	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO7491818605	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO8642524622	ODP	4	45 BRO	SP	CCA		V		00:00.0
2021	PO8622724627	ODP	4	45 BRO	SP	CCA		V		00:00.0
2021	PO8614324624	ODP	6	30 BRO	SP	CCA		V		00:00.0
2021	PO8706323901	ODP	6	30 BRO	SP	CRE		V		00:00.0
2021	PO8706723829	ODP	6	30 BRO	SP	CRE		V		00:00.0
2021	PO8715223725	ODP	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO8713323886	ODP	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021	PO8753623555	ODP	4	40 BRO	SP	CCA		V		00:00.0
2021	PO8731823509	F	4	40 KOP	SP	P		V		00:00.0
2021	PO8718423497	ODP	3	45 BRO	SP	CCA		V		00:00.0
2021	PO8721123251	ODP	4	40 BRO	SP	CRE	ID	BD		00:00.0

2021 PO8723023118	ODP	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO8734123001	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO8726222781	ODP	4	40 KOP	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO8737622606	ODP	5	30 UNK	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO8736822522	ODP	3	50 BRO	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO8724522485	ODP	3	50 BRO	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO8728122626	ODP	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO8717625767	ODP	6	30 UNK	SP	CRE	ED,ID,IP,SRC	TD		00:00.0
2021 PO0475836083	ODP	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0475136174	ODP	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0477236298	ODP	4	40 BRN	SP	CCA	ED	T		00:00.0
2021 PO0474036392	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO8726525577	ODP	6	30 KOP	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO8724725665	ODP	4	40 BRO	SP	CCA		V		00:00.0
2021 PO8695525789	ODP	4	40 BRO	SP	CRE		V		00:00.0
2021 PO8697025711	ODP	4	45 BRO	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO8695825630	ODP	4	40 ACW	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO9347026278	ODP	5	35 XXX	SP	CRE	ED,ID,IP	X	RP2	00:00.0
2021 PO9345026565	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9351726562	ODP	4	40 XXX	SP	S		V		00:00.0
2021 PO9357826372	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO0431936114	ODP	5	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0457336203	ODP	5	35 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0438236107	ODP	6	30 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0442336056	ODP	4	45 BRN	SP	CCA		V		00:00.0
2021 PO0429835952	ODP	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO8691525550	ODP	4	45 BRO	SP	CCA		V		00:00.0
2021 PO8695725497	ODP	4	40 BRO	SP	CCA		V		00:00.0
2021 PO8697925345	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD		00:00.0
2021 PO8676324938	ODP	6	30 UNK	SP	CRE	ED,ID,IP,SRC	TD		00:00.0
2021 PO6460318415	ODP	2	60 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6483418461	ODP	2	55 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6504218499	ODP	2	60 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9351726562	ODP	4	40 XXX	SP	S		V		00:00.0
2021 PO9345526429	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO9404226869	ODP	4	45 XXX	SP	S	ED	T		00:00.0
2021 PO9388726811	ODP	5	30 XXX	SP	S	ED,MD,SRC	T		00:00.0
2021 PO8806325706	ODP	5	35 BRO	SP	CCA		V		00:00.0
2021 PO8787325551	ODP	5	35 ACW	SP	CRE	ED,ID,IP,SRC	TD		00:00.0
2021 PO9383326889	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO9403827055	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9424526873	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO9432926790	F	4	40 XXX	SP	P		V		00:00.0
2021 PO9433926611	F	3	40 XXX	SP	P		V		00:00.0
2021 PO6499018251	ODP	4	45 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO6529218221	ODP	4	40 XXX	SP	CRE	ED,EP,ID,SRC	TX	RR	00:00.0
2021 PO0453335903	ODP	4	45 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0471236042	ODP	6	30 BRN	SP	CRE	ID,IP	TD		00:00.0
2021 PO0367534454	ODP	6	30 BRN	SP	CCA	ED	T		00:00.0
2021 PO0360034363	ODP	4	40 BRN	SP	CCA		V		00:00.0
2021 PO0386034851A	ODP	5	35 BRN	SP	CCA		V		00:00.0
2021 PO8810125647	ODP	4	40 BRO	SP	CCA		V		00:00.0
2021 PO8824925190	ODP	6	30 BRO	SP	CCA		V		00:00.0
2021 PO8818325254	ODP	4	40 BRO	SP	CCA		V		00:00.0

2021 PO8785625213	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8758825202	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8758025148	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO6434018027	ODP	6	30 XXX	SP	CRE	ID	BD	00:00.0
2021 PO6446117876	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6450018017	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8740025313	ODP	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO8739325177	ODP	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO8725425271	ODP	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO8717325341	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021 PO8694625163	ODP	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8687825108	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021 PO8720825023	ODP	5	35 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO8700325155	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021 PO8691524891	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO8700524936	ODP	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO8691724815	ODP	6	30 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8520127173	ODP	5	35 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO0399734708	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021 PO0394234697	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO9359826571	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9365226738	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9366026441	ODP	5	35 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021 PO9372926511	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9386526611	ODP	6	30 XXX	SP	S	ED,MD,SRC	T	00:00.0
2021 PO0374134495	ODP	6	30 BRN	SP	CCA	ED	T	00:00.0
2021 PO0382534366	ODP	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0387134258	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0393334447	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0420734394	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO9668828596	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO967628545A	ODP	2	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9676428545	ODP	2	40 XXX	SP	S		V	00:00.0
2021 PO9679928603	ODP	2	60 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9726128185	ODP	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9844128598	ODP	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9805028422	ODP	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9768328295	ODP	4	45 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO0501434843	ODP	5	35 ESC	SP	CRE	ID	TD	00:00.0
2021 PO0517035049	ODP	4	40 ESC	SP	CRE	ID	TD	00:00.0
2021 PO0522635109	F	4	40 ESC	SP	P		V	00:00.0
2021 PO0406534547	ODP	4	45 BRN	SP	CRE	HH,ID	X	00:00.0
2021 PO0436134646	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0427434567	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0420934677	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0423634900	F	4	40 BRN	DF	P		V	00:00.0
2021 PO0468034874	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0468034874A	ODP	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0479934821	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO0386534955	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO6429717438	ODP	4	40 XXX	SP	CCA	ED,ID	TD	00:00.0
2021 PO9433427298	ODP	2	50 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9455927480	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO9483327698	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0

2021 PO6540915520	ODP	4	40 BRO	SP	CCA			V		00:00.0
2021 PO0491934962	ODP	4	40 BRN	SP	CRE	ED,ID		TX	RR	00:00.0
2021 PO0510934879	ODP	4	40 BRN	SP	CRE	ID		TD		00:00.0
2021 PO0599434450	ODP	6	30 BRN	SP	CCA	ED		T		00:00.0
2021 PO0591834513	ODP	5	35 BRN	SP	CRE	ID		TD		00:00.0
2021 PO0573334689	ODP	4	40 BRN	SP	CCA			V		00:00.0
2021 PO0588334714	ODP	5	35 BRN	SP	CRE	ED,ID		TD		00:00.0
2021 PO0585734879	ODP	5	35 BRN	SP	CRE	ID		TD		00:00.0
2021 PO0580535074	ODP	4	40 BRN	SP	CRE			V		00:00.0
2021 PO0585235109	ODP	4	40 BRN	SP	CCA			V		00:00.0
2021 PO0572435262	ODP	4	40 BRN	SP	CCA			V		00:00.0
2021 PO0548334853	ODP	3	40 BRN	SP	CRE	ID		TD		00:00.0
2021 PO0531134924	ODP	6	30 BRN	SP	CRE	ED,ID,RB		X	PX	00:00.0
2021 PO0550635009	ODP	6	30 BRN	SP	CRE	ID		TD		00:00.0
2021 PO0532135011	ODP	4	40 BRN	SP	CRE	ID		TD		00:00.0
2021 PO0543635102	ODP	4	40 BRN	SP	CRE	ID		TD		00:00.0
2021 PO6535015756	ODP	4	40 BRO	SP	CCA			V		00:00.0
2021 PO6505516899	ODP	4	40 BRO	SP	CCA			V		00:00.0
2021 PO6505516899a	ODP	5	35 XXX	SP	CRE	ED,ID,IP		TD		00:00.0
2021 PO6479516930	ODP	5	35 XXX	SP	CRE	ED,ID,IP		TD		00:00.0
2021 PO6532016902	ODP	5	40 XXX	SP	CRE	ED,IP		TD		00:00.0
2021 PO8558626826	ODP	6	30 UNK	SP	CRE	ED,ID		TD		00:00.0
2021 PO8588826855	ODP	4	40 UNK	SP	CRE	ED,ID,SR		TD		00:00.0
2021 PO8620126707	ODP	5	40 UNK	SP	CRE	ID		BD		00:00.0
2021 PO8551827076	ODP	5	35 UNK	SP	CRE			V		00:00.0
2021 PO8670126510	ODP	4	40 BRO	SP	CCA			V		00:00.0
2021 PO8674925973	ODP	5	35 UNK	SP	CRE	ID		BD		00:00.0
2021 PO8662326401A	ODP	3	45 BRO	SP	CCA			V		00:00.0
2021 PO8662326401	ODP	4	45 BRO	SP	CCA			V		00:00.0
2021 PO8638426888	ODP	5	35 UNK	SP	CRE	ID		BD		00:00.0
2021 PO8644626734	ODP	5	35 UNK	SP	CRE	ED,ID		TD		00:00.0
2021 PO0570835923	ODP	4	45 BRN	SP	CCA			V		00:00.0
2021 PO8678526972	F	4	40 UNK	SP	P			V		00:00.0
2021 PO0584236056	ODP	4	45 BRN	SP	CCA			V		00:00.0
2021 PO9628828208	ODP	5	35 XXX	SP	CRE	ED,ID		TD		00:00.0
2021 PO9610128035	ODP	6	30 XXX	SP	CRE	ED,ID,IP		TD		00:00.0
2021 PO9593328085	ODP	5	35 XXX	SP	CRE	ED,ID		BD		00:00.0
2021 PO9567328037	ODP	4	40 XXX	SP	CRE	ED,ID		TD		00:00.0
2021 PO9600727915	ODP	6	30 XXX	SP	S	ED,MD,SR		T		00:00.0
2021 PO9590027743	ODP	6	30 XXX	SP	S			V		00:00.0
2021 PO9579027852	ODP	4	45 XXX	SP	S			V		00:00.0
2021 PO9534627371	ODP	6	30 XXX	SP	CRE			V		00:00.0
2021 PO9521927663	ODP	6	35 XXX	SP	CRE	ED,ID		TD		00:00.0
2021 PO9525127520	ODP	4	40 XXX	SP	CRE	ED,ID		TD		00:00.0
2021 PO9527627458	ODP	4	40 XXX	SP	CRE	ED,ID		TD		00:00.0
2021 PO9536727481	ODP	5	30 XXX	SP	CRE	ED,ID		TD		00:00.0
2021 PO9539527068	ODP	5	35 XXX	SP	CRE	ED,ID,IP		TD		00:00.0
2021 PO9554427285	ODP	6	30 XXX	SP	CRE	ED,ID		TD		00:00.0
2021 PO9539627244	ODP	6	30 XXX	SP	CRE	ED,ID		TD		00:00.0
2021 PO8663527634	F	4	40 UNK	SP	CRE			V		00:00.0
2021 PO8647728184A	F	4	40 UNK	SP	P			V		00:00.0
2021 PO8647728184	F	4	40 BRO	SP	CCA			V		00:00.0
2021 PO8673728390	F	4	45 UNK	SP	CRE			V		00:00.0
2021 PO8719428304	F	4	40 UNK	SP	CRE			V		00:00.0

2021 PO8732228218	F	4	45 UNK	SP	CRE		V		00:00.0
2021 PO8780328589	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO8750928432	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO8755228287	ODP	4	45 UNK	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO8776328356	ODP	4	45 UNK	SP	CRE	ED,ID,SR	TD		00:00.0
2021 PO9532927271	ODP	5	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9541227314	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9489826700	ODP	4	40 XXX	SP	S		V		00:00.0
2021 PO9521126785	ODP	4	45 XXX	SP	S		V		00:00.0
2021 PO8357521250	ODP	5	35 UNK	SP	CRE	ED,ID,IP,SR	TD		00:00.0
2021 PO8325521339A	ODP	6	30 ACW	SP	CRE	ED,ID,SR	TD		00:00.0
2021 PO8353221905	ODP	5	35 KOP	SP	CRE	ED,ID,IP,SR	TD		00:00.0
2021 PO0391735822	ODP	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0381335551	ODP	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0410335648	ODP	5	35 BRN	SP	CRE	ID	BD		00:00.0
2021 PO0420035688	ODP	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO0420035688A	ODP	5	35 BRN	SP	CCA	ED	T		00:00.0
2021 PO0425235681	ODP	6	30 BRN	SP	CCA	ED	T		00:00.0
2021 PO0426035777	ODP	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0436535862	ODP	4	40 BRN	SP	CRE	ID	BD		00:00.0
2021 PO0427534262	ODP	4	40 BRN	SP	CRE	ID	TD		00:00.0
2021 PO0417134174	ODP	5	35 BRN	SP	CCA	ED	T		00:00.0
2021 PO0390534201	ODP	5	35 BRN	SP	CCA		V		00:00.0
2021 PO0356934176	ODP	4	40 BRN	SP	CCA	ED	T		00:00.0
2021 PO0377134312	ODP	6	30 BRN	SP	CCA	ED	V		00:00.0
2021 PO0449236205	ODP	5	35 BRN	SP	CCA		V		00:00.0
2021 PO0259934008	ODP	2	50 BRN	SP	CCA	ED	T		00:00.0
2021 PO0413934651	ODP	6	30 BRN	SP	CRE		V		00:00.0
2021 PO0680536954	ODP	6	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO9320225441	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO9322225690	ODP	6	30 XXX	SP	S	ED	T		00:00.0
2021 PO8556925382	ODP	5	35 UNK	SP	CRE	ED,ID,IP,MD,SR	TX	RR	00:00.0
2021 PO8545625382	ODP	4	35 UNK	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO8616425488	ODP	5	35 UNK	SP	CRE	ED,ID,IP,MD,SR	TX	RR	00:00.0
2021 PO8654925269	ODP	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021 PO8656425511	ODP	5	35 UNK	SP	CRE	ED,ID,SR	TD		00:00.0
2021 PO8644626734A	F	5	35 UNK	SP	P		V		00:00.0
2021 PO8672225828	ODP	5	35 UNK	SP	CRE	ED,ID,IP,SR	TD		00:00.0
2021 PO9542928175	ODP	4	40 XXX	SP	CRE	ED,HH,ID	BX	RP1	00:00.0
2021 PO9525828034	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9516227812	ODP	4	40 XXX	SP	CRE	ED,ID	TD		00:00.0
2021 PO9508727905	ODP	4	40 XXX	SP	S	ED,MD,SR	T		00:00.0
2021 PO8540427144A	ODP	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO8540427144	ODP	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO6470717738	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8561427013	ODP	5	35 UNK	SP	CRE	ED,ID,SR	TD		00:00.0
2021 PO6488717600	ODP	4	45 XXX	SP	CCA		V		00:00.0
2021 PO6484717253	ODP	4	45 XXX	SP	CCA		V		00:00.0
2021 PO6552713287	ODP	4	40 XXX	SP	CCA		V		00:00.0
2021 PO6548613658a	ODP	4	40 XXX	SP	CCA		V		00:00.0
2021 PO6548613658	ODP	4	40 XXX	SP	CCA		V		00:00.0
2021 PO6556414047a	ODP	4	40 XXX	SP	CCA		V		00:00.0
2021 PO6556414047	ODP	3	45 BRO	SP	CCA		V		00:00.0
2021 PO6546615015	ODP	4	40 BRO	SP	CCA		V		00:00.0

2021	PO6543415290	ODP	4	40 BRO	SP	CCA		V		00:00.0
2021	PO5568420237	KU	4	40 OTH	SP	CRE	ED,ID,IP	X	RP2	00:00.0
2021	PO4938988887	LGE	4	35 BRO	SP	CRE	ED,ID,IP,RB	X	RP1	00:00.0
2021	PO4883788639	LGE	3	45 BRN	SP	CRE	ED,ID,RB	X	RP1	00:00.0
2021	PO5348007978	KU	5	35 BRN	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO7528419906	ODP	5	35 UNK	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO8670321550	ODP	4	40 KOP	SP	CRE	RB	X	PX	00:00.0
2021	PO4813588569	LGE	4	40 BRO	SP	P	ED,EP,ID,IP	X	RP2	00:00.0
2021	PO4931788990	LGE	4	40 BRO	SP	CRE	HH,ID,IP,RB	X	RP1	00:00.0
2021	PO5484911104	KU	4	40 ACW	SP	CRE	ED,ID,IP	X	RP2	00:00.0
2021	PO4934988952	LGE	4	35 BRO	SP	CRE	ED,ID,RB	X	RP1	00:00.0
2021	PO0242134838	ODP	6	30 BRN	SP	CRE	ED,HH,ID	X	RP2	00:00.0
2021	PO4898588991	LGE	4	35 BRO	SP	A	ED,ID,IP,RB	X	RP1	00:00.0
2021	PO8098120964	ODP	5	35 UNK	SP	CRE	ED,ID,RB,SRC	X	RP1	00:00.0
2021	PO4896388964	LGE	4	30 BRO	SP	A	ED,ID,IP,RB	X	RP1	00:00.0
2021	PO4828989432	LGE	4	40 BRO	SP	P	ED,EP,HH,ID,IP,RB	X	RP2	00:00.0
2021	PO6685118754	ODP	4	40 BRN	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO4829389421	LGE	4	40 BRO	SP	CRE	ED,HH,ID,IP,RB	X	RP1	00:00.0
2021	PO8356821775	ODP	5	30 UNK	SP	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO8719221766	ODP	5	35 KOP	SP	CRE	ED,HH,ID,IP,MD,RB,SRC	X	RP2	00:00.0
2021	PO4806088740	LGE	4	25 BRO	SP	P	ED,ID,IP,MD,RB	X	RP3	00:00.0
2021	PO4822688652	LGE	4	40 BRO	SP	CCA	ED,ID,MD,RB	X	RP3	00:00.0
2021	PO9380160983	KU	4	45 XXX	SP	CRE	ED,HH,ID	X	RP3	00:00.0
2021	PO9468658813	KU	2	50 BRN	SP	CCA		V		00:00.0
2021	PO9474458791	KU	4	40 BRN	SP	CCA		V		00:00.0
2021	PO9642063427	KU	3	50 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO9648063253	KU	3	50 BRO	SP	CRE	ED,ID		BD	00:00.0
2021	PO9634363162	KU	4	45 BRO	SP	CRE	ED,ID		BD	00:00.0
2021	PO9383559354	KU	4	45 UNK	SP	CRE	ID		BD	00:00.0
2021	PO9391359411	KU	2	50 BRO	SP	CCA		V		00:00.0
2021	PO9352957834	KU	5	35 BRN	SP	CRE	ED,ID,IP		TD	00:00.0
2021	PO9352057853	KU	4	40 BRN	SP	CRE	ED,ID,IP		TD	00:00.0
2021	PO9284561141	KU	2	50 OTH	SP	CCA		V		00:00.0
2021	PO9287761018	KU	2	50 OTH	SP	CCA	ED,SRS		TD	00:00.0
2021	PO9397159336	KU	2	50 BRO	SP	CCA		V		00:00.0
2021	PO9421159310	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	N/A	KU	4	30 BRN	SP	CRE		V		00:00.0
2021	PO4398104270	F	3	45 BRN	SP	CRE		V		00:00.0
2021	PO4446004474	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO4427104378	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO9404559410	KU	2	50 BRO	SP	CCA		V		00:00.0
2021	PO9409159460	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9403959505	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO9373059553	KU	4	45 UNK	SP	CRE	ED,ID		TD	00:00.0
2021	PO9615263103	KU	4	45 BRO	SP	CRE	ED,ID		BD	00:00.0
2021	PO9267161236	KU	5	35 OTH	SP	CRE	ED,ID,SRS		TD	00:00.0
2021	PO9274461597	KU	3	50 OTH	SP	CCA	ED,SRS		TD	00:00.0
2021	PO9278361358	KU	2	60 OTH	SP	CCA	ED,SRS		TD	00:00.0
2021	PO9274561259	KU	4	40 OTH	SP	CCA	ED,SRS		TD	00:00.0
2021	PO9597963061	KU	4	45 BRO	SP	CRE	ED,ID	X	PX	00:00.0
2021	PO9585463143	KU	4	45 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO9585063082	KU	4	45 BRO	SP	CRE	ED,ID		BD	00:00.0
2021	PO9584763048	KU	2	55 BRO	SP	S		V		00:00.0
2021	PO9375759625	KU	3	45 BRO	SP	CCA		V		00:00.0



2021 PO9379159689	KU	6	30 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4570203462	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4458004550	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO4416904341	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4469604624	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO4483904718	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4387104228	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO4436204414	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO9410161641	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9319059756	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO2006505502	KU	3	45 ACE	SP	CRE		V		00:00.0
2021 PO1974005586	KU	3	45 ACE	SP	CRE		V		00:00.0
2021 PO1925205712	KU	3	45 ACE	SP	CRE		V		00:00.0
2021 PO1887405809	KU	3	45 ACE	SP	CRE		V		00:00.0
2021 PO1857805886	KU	3	50 ACE	SP	CRE		V		00:00.0
2021 PO1813805999	KU	4	40 ACE	SP	CRE		V		00:00.0
2021 PO1772606105	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO1741206186	KU	3	60 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4798889467	F	3	45 ACE	SP	CCA		V		00:00.0
2021 PO4798089482	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4795089479	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4947089195	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO1697006300	KU	3	50 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO2047805396	KU	4	40 ACE	SP	CCA		V		00:00.0
2021 PO2086705296	KU	3	45 ACE	SP	CRE	ED,ID	BD		00:00.0
2021 PO4383299427	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4395199377	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4408199324	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4421199270	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4432899221	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4445699168	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO9036362252	KU	6	30 BRO	SP	S		V		00:00.0
2021 PO9041262250	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO9027962188	KU	4	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9072062355	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9256461678	KU	2	50 OTH	SP	CCA		V		00:00.0
2021 PO9237861749	KU	4	40 OTH	SP	CRE		V		00:00.0
2021 PO9228861767	KU	3	50 OTH	SP	CCA		V		00:00.0
2021 PO4795989489	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO4797189496	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO9214361796	KU	2	50 OTH	SP	CCA		V		00:00.0
2021 PO4434405410	KU	6	30 BRN	SP	CCA		V		00:00.0
2021 PO4361085321	F	4	30 BRN	ST	P		V		00:00.0
2021 PO4432205465	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4361585327	F	4	35 BRN	SP	P		V		00:00.0
2021 PO4362185337	F	5	30 BRN	ST	A		V		00:00.0
2021 PO9192761839	KU	3	45 OTH	SP	CCA		V		00:00.0
2021 PO9191961957	KU	6	30 OTH	SP	CCA		V		00:00.0
2021 PO9196661654	KU	4	40 OTH	SP	CCA		V		00:00.0
2021 PO9199061761	KU	5	35 OTH	SP	CCA		V		00:00.0
2021 PO9205061805	KU	2	50 OTH	SP	CCA		V		00:00.0
2021 PO9219961485	KU	4	40 OTH	CCA	CRE		V		00:00.0
2021 PO9050962377	KU	6	30 BRO	CCA	CRE		V		00:00.0
2021 PO9059162336	KU	5	35 BRO	SP	CCA		V		00:00.0

2021 PO9064962373	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9078062325	KU	6	30 BRO	SP	CRE		V		00:00.0
2021 PO9055062240	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9194762031	KU	6	30 OTH	SP	CRE	ID	BD		00:00.0
2021 PO4362685345	F	4	35 BRN	ST	CCA		V		00:00.0
2021 PO9429462573	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9437162771	KU	4	40 XXX	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO9163762308	KU	5	35 OTH	SP	CRE	ID	BD		00:00.0
2021 PO9222061981	KU	4	40 OTH	SP	CRE	ED,EP,HH,ID,IP,RB	X	PX	00:00.0
2021 PO9179462196	KU	6	30 OTH	SP	CCA		V		00:00.0
2021 PO9096162498	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9196962067	KU	6	30 OTH	SP	CRE	ID	BD		00:00.0
2021 PO9213462011	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9065762273	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9026361894	KU	4	45 BRO	SP	S		V		00:00.0
2021 PO9024961955	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9033362033	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9050062098	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9066762150	KU	2	50 BRO	SP	CCA		V		00:00.0
2021 PO9057962180	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6391298089	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6396998191	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6402598291	F	4	40 XXX	CRE	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO6431098166	F	4	40 XXX	SP	CRE	ED	V		00:00.0
2021 PO6426498074	F	4	40 XXX	SP	CRE	ED,ID,MD	BX	RP1	00:00.0
2021 PO6449198035	F	2	40 XXX	SP	P		V		00:00.0
2021 PO6437998027	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6419097959	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6514698269	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6508098016	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6498097548	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6510898133	F	4	40 XXX	CRE	CRE	ED,ID,IP,MD	BX	PX	00:00.0
2021 PO6499797622	F	4	40 XXX	SP	P	ED	V		00:00.0
2021 PO6502297731	F	4	40 XXX	CRE	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO6497697521	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6508797531	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6523797506	F	2	40 XXX	CRE	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO6319498712	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6317598793	F	2	40 XXX	SP	P		V		00:00.0
2021 PO6314298613	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6214098745	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6182898802	F	2	40 XXX	SP	P		V		00:00.0
2021 PO6199898719	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6218098746	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6215698652	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6226598602	F	2	40 XXX	SP	P		V		00:00.0
2021 PO4799989509	F	4	40 ACE	SP	CRE		V		00:00.0
2021 PO6244598876	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6245698754	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6246598671	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6254698580	F	5	30 XXX	SP	P		V		00:00.0
2021 PO6247998542	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6247098506	F	5	40 XXX	CRE	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO6263398489	F	5	30 XXX	SP	P		V		00:00.0

2021	PO6256798424	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6271198362	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6284398306	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO9640856602	KU	6	30 BRN	SP	CCA		V		00:00.0
2021	PO9437462730	KU	4	40 XXX	SP	CRE	ID	TX	RR	00:00.0
2021	PO9443362763	KU	5	35 XXX	SP	CRE	ID,IP	TD		00:00.0
2021	PO4363585357	F	4	40 BRN	ST	P		V		00:00.0
2021	PO4363185316	LGE	3	50 BRN	SP	CRE		V		00:00.0
2021	PO4802289528	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4363785325	LGE	1	50 BRN	SP	CRE		V		00:00.0
2021	PO9437262751	KU	4	40 XXX	SP	CRE	ID,IP	TX	RR	00:00.0
2021	PO9427362742	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO9417762740	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO9425162938	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO9435063116	F	4	40 XXX	SP	CRE	ED,ID	BX	RP3	00:00.0
2021	PO9592057039	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO9584857005	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO9577456973	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO9142262424	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9127362541	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9126462466	KU	5	35 OTH	SP	CRE	ED,ID,SR	TD		00:00.0
2021	PO9015861989	KU	3	50 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO0097033444	KU	5	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5989454834	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO8940262082	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4436906212	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4364785339	LGE	1	55 BRN	SP	A		V		00:00.0
2021	PO4362385304	LGE	3	50 BRN	SP	A		V		00:00.0
2021	PO4361585293	LGE	3	45 BRN	SP	A		V		00:00.0
2021	PO4360685300	LGE	4	35 BRN	SP	A		V		00:00.0
2021	PO9004961962	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9097862453	KU	6	35 OTH	SP	CRE	ID	BD		00:00.0
2021	PO9111162492	KU	5	35 OTH	SP	CRE	ED,ID	BD		00:00.0
2021	PO4439805587	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4434105718	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4472505864	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4470205680	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021	PO4440805769	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4443705667	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4453705573	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4467405945	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021	PO8949962058	KU	5	35 BRO	SP	CRE		V		00:00.0
2021	PO8954862148	KU	6	30 BRO	SP	CRE		V		00:00.0
2021	PO8966262297	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9132062928	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9134263026	KU	4	40 OTH	SP	CRE	ID	BD		00:00.0
2021	PO9130362777	KU	4	45 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021	PO9137062992	KU	4	45 OTH	SP	CCA		V		00:00.0
2021	PO9562756684	KU	4	45 BRN	SP	CRE		V		00:00.0
2021	PO9556956875	KU	5	35 BRN	SP	CRE	ED,ID	TD		00:00.0
2021	PO9554056861	KU	5	35 BRN	SP	CCA		V		00:00.0
2021	PO4458199116	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021	PO4471799358	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021	PO4458799407	F	4	40 BRO	SP	CRE	ED	V		00:00.0

2021 PO4445499457	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4420099556	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4409499592	F	3	40 BRO	SP	P	ED	V	00:00.0
2021 PO4399599651	F	2	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4389499618	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4407799734	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4430400158	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4414299787	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4422699854	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4435499800	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4446199758	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4456899716	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4467799673	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4478299631	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4489399585	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4502299531	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4508599501	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4517899460	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4525699907	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4529799998	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4520299783	F	2	50 BRO	SP	CRE	ED	V	00:00.0
2021 PO4528099800	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4535099881	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4524499732	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4470100340	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4513699619	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4516199684	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO8964262384	KU	3	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8999562122	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9538356954	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4476106013	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4474006238	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4490005910	F	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4481305916	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4465806193	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4484805787	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO9151862386	KU	4	45 OTH	SP	CRE	ID	BD	00:00.0
2021 PO9153462573	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9155462771	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9155462451	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9167962978	KU	4	40 OTH	CRE	CRE	ED,ID,SRS	X	RP3 00:00.0
2021 PO9420463518A	KU	3	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9417063231	KU	4	45 XXX	SP	CCA	ED	V	00:00.0
2021 PO9411763222	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO9394763274	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021 PO9394563349	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021 PO9383463362	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9374863254	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9393863223	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9393863223A	KU	5	35 XXX	SP	P	ID	TD	00:00.0
2021 PO9410963193	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9416863060	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9423563064	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO9422263168	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0

2021	PO9439763316	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO9432063412	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021	PO9420463518	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO9417063589	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO9522857123	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO1954050964	KU	4	40 XXX	SP	CRE	ID,IP	TD	00:00.0
2021	PO1943251114	KU	4	40 XXX	SP	CCA		V	00:00.0
2021	PO1950851132	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021	PO5413699228	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5420099204	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5432999155	F	3	40 XXX	SP	P		V	00:00.0
2021	PO5443099134	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5395099314	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5368499432	F	4	40 XXX	SP	P		V	00:00.0
2021	PO7352197685	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO1458174074	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO1449173806	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO7344797884	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO6561288678	KU	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6566988569	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO1944551460	KU	4	40 XXX	SP	CRE	ED,HH,ID	X	RP3 00:00.0
2021	PO4227304849	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4208304843	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4266404936	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4261404860	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4227304914	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4249204976	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4272304786	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4249204864	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6554788838	KU	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6544989170	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO0085158671	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO6477688814	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021	PO1966167195	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO4224705427	KU	3	45 BRN	SP	CRE		V	00:00.0
2021	PO6354090023	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6345590096	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6343190090	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4317186972	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4316386976	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO4315286985	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO9635657663	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO9634858128	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO9608656875	KU	4	40 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6339390044	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6329289924	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6315989761	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4317886981	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021	PO4318186986	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021	PO1243974331	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4308287197	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4307287206	F	4	35 BRO	SP	CRE		V	00:00.0
2021	PO4306687210	F	4	30 BRO	SP	A		V	00:00.0
2021	PO4308887192	F	4	35 BRO	SP	A		V	00:00.0

2021 PO4309187190	F	4	35 BRO	SP	A		V	00:00.0	
2021 PO4310187184	F	4	35 BRO	SP	A		V	00:00.0	
2021 PO4311087193	F	4	30 BRO	SP	A		V	00:00.0	
2021 PO4310387183	F	4	35 BRO	SP	CCA		V	00:00.0	
2021 PO4309887184	F	4	35 BRO	SP	CRE		V	00:00.0	
2021 PO4305887216	F	4	35 BRO	SP	A		V	00:00.0	
2021 PO9591956876	KU	6	30 UNK	SP	CRE		V	00:00.0	
2021 PO9635056852	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9634155608	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021 PO6307889662	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO6299889568	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4316387018	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO4317287011	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0	
2021 PO1247474248	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO1235174163	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO1218873734	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4323705549	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4315805410	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4311705522	F	3	45 BRN	SP	CCA		V	00:00.0	
2021 PO4318087005	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4318587006	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4354005618	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4340605633	F	4	40 BRN	SP	CCA		V	00:00.0	
2021 PO4349605669	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4345105870	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4358906085	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4339905760	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4340506165	F	3	40 BRN	SP	CRE		V	00:00.0	
2021 PO4341006098	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4306387234	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO0203784307	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO0201884321	LGE	4	30 BRO	SP	CCA		V	00:00.0	
2021 PO4316187025	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0	
2021 PO4312087144	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO1194573948	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO1174773843	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO1211474237	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4315487025	LGE	3	45 ACE	SP	CCA		V	00:00.0	
2021 PO4313487133	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4314287127	LGE	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO4312787138	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0	
2021 PO6281889349	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO6348989722	F	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4311787054	LGE	4	40 ACE	SP	P	ED	T	00:00.0	
2021 PO4312787046	LGE	4	40 ACE	SP	P	ED	T	00:00.0	
2021 PO4313687039	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4314487124	LGE	4	40 BRO	SP	CRE	ID,IP,RR	BX	RR	00:00.0
2021 PO1169774570	KU	3	35 BRO	SP	S		V	00:00.0	
2021 PO1169774570	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO4314587123	LGE	2	50 BRO	SP	A	ID,IP	BD	00:00.0	
2021 PO4322687008	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4323386996	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO4324486979	LGE	4	30 ACE	SP	CRE	ED,ID	BD	00:00.0	
2021 PO6642494308	F	3	45 BRN	SP	CRE		V	00:00.0	

2021 PO6649394378	F	3	45 BRN	SP	P		V	00:00.0
2021 PO6636494240	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO6620494061	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6599593571	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6610693502	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0493557318	KU	2	65 BRO	SP	CRE		V	00:00.0
2021 PO0480057743	KU	2	60 BRO	SP	CCA		V	00:00.0
2021 PO0474357727	KU	1	65 BRO	SP	CCA		V	00:00.0
2021 PO0321963512	KU	3	40 BRO	SP	CRE		V	00:00.0
2021 PO6629493389	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6630493357	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6617793152	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6603192911	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6589692690	F	4	40 BRN	SP	P		V	00:00.0
2021 PO6561392217	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6575792459	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0325963526	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0211463740	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0206763545	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO0201863121	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO1748651142	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4980188610	LGE	3H	45 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO6548592011	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6536691845	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6557991748	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0245862720	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4084900366	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4080300219	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4054099664	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4088700508	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4074500079	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4068599968	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4061999834	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO4037999247	KU	2	40 BRN	SP	CRE		V	00:00.0
2021 PO4047999533	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4033499104	KU	1	45 BRN	SP	S		V	00:00.0
2021 PO4044099385	KU	2	45 BRN	SP	CRE		V	00:00.0
2021 PO2186557335	KU	5	45 BRO	AL	CRE		V	00:00.0
2021 PO2210059286	F	4	40 BRO	SP	P		V	00:00.0
2021 PO2201359250	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6578791625	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6591491550	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6610891436	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6635691266	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5006588376	LGE	3	50 BRN	SP	A		V	00:00.0
2021 PO5020788406	LGE	2	55 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO5018788394	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO5017288383	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO5017488432	LGE	3H	45 BRN	SP	P		V	00:00.0
2021 PO5019888440	LGE	3H	45 BRN	SP	P		V	00:00.0
2021 PO2202059009	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6613991192	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6595091126	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6583791087	F	4	45 BRN	SP	P		V	00:00.0

2021	PO6578091067	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5041589637	LGE	4	30 ACE	SP	CRE	ED,ID	TD		00:00.0
2021	PO0200062396	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO0199362086	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO0198761715	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO6528790896	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6517490979	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO2201558792	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TX	RR	00:00.0
2021	PO1227678467	KU	4	40 BRO	SP	CRE		V		00:00.0
2021	PO1234778549	KU	4	45 BRO	SP	S		V		00:00.0
2021	PO1241778524	KU	5	35 BRO	SP	S		V		00:00.0
2021	PO5021688448	LGE	3H	45 BRN	SP	P		V		00:00.0
2021	PO5021388399	LGE	4	35 BRN	SP	A	ED,ID	TD		00:00.0
2021	PO4977888607	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021	PO1928550193	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO1944550109	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO1965150079	KU	3	45 XXX	SP	CRE	ID,IP	BD		00:00.0
2021	PO5042189601	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO0196461423	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO1236478285	KU	6	30 BRO	SP	CRE		V		00:00.0
2021	PO5520698934	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5515598820	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5526199046	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	PX	00:00.0
2021	PO5531399165	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5541599393	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5536699279	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021	PO5546699501	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5530399569	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5552199620	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5494998631	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5502398635	KU	6	30 XXX	SP	CRE	ED,ID,IP	BD		00:00.0
2021	PO5504298591	F	4	40 XXX	SP	CRE	ED,ID,MD,RB	BX	PX	00:00.0
2021	PO6498091257	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021	PO1241378142	KU	6	30 BRO	SP	CRE	ED,ID	V		00:00.0
2021	PO1248578068	KU	5	35 BRO	SP	CCA		V		00:00.0
2021	PO1250178207	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO1265177953	KU	4	40 BRO	SP	CCA		V		00:00.0
2021	PO0284361123	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO3943907579	F	3	40 BRN	SP	S		V		00:00.0
2021	PO2179157970	KU	5	35 BRO	SP	CRE	ED,ID,IP,SRC	TX	RR	00:00.0
2021	PO5042689605	LGE	4	30 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO6884499357	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021	PO0378561757	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO0370261746	KU	4	40 BRO	SP	S		V		00:00.0
2021	PO1280077659	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO1965367365	KU	4	45 BRO	SP	CRE	RB	BX	PX	00:00.0
2021	PO0382561260	KU	3	50 BRO	SP	S		V		00:00.0
2021	PO0073458880	KU	6	30 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO6520490090	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6529289840	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6530689696	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6532089555	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6536589391	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4315486978	LGE	4	40 ACE	SP	CCA		V		00:00.0



2021 PO4316686968	LGE	UNK	50 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4313486993	LGE	UNK	55 ACE	SP	CCA		V	00:00.0
2021 PO4312686999	LGE	UNK	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4311987005	LGE	UNK	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO0035059013	KU		40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO1869151786	KU		40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO1951067475	KU		45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1972967515	KU		40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0388061281	KU		30 BRO	SP	CCA		V	00:00.0
2021 PO5015488372	LGE		30 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO5013788333	F		40 BRN	SP	CCA		V	00:00.0
2021 PO5013788353	F		40 BRN	SP	CRE		V	00:00.0
2021 PO5013388360	LGE		25 BRN	SP	CCA		V	00:00.0
2021 PO5012888376	LGE		40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO5009188372	F		40 BRN	SP	CCA		V	00:00.0
2021 PO4976888604	LGE		40 BRO	SP	CCA		V	00:00.0
2021 PO4976688564	LGE		40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4012108004	F		30 BRN	SP	S		V	00:00.0
2021 PO5043589615	LGE		40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5044689607	LGE		40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5045689599	LGE		35 ACE	SP	CCA		V	00:00.0
2021 PO5045989585	LGE	UNK	30 ACE	SP	CCA		V	00:00.0
2021 PO4308187036	LGE		40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4052707582	F		40 BRN	SP	CRE		V	00:00.0
2021 PO1087379705	KU		30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO1134179392	KU		40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO1762351010	KU		40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1800250814	KU		40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1831150668	KU		20 XXX	SP	CCA		V	00:00.0
2021 PO1859850537	KU		40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO0341562956	KU		45 BRO	SP	CCA		V	00:00.0
2021 PO0348362970	KU		45 BRO	SP	CCA		V	00:00.0
2021 PO0357862579	KU		40 BRO	SP	CCA		V	00:00.0
2021 PO0352462573	KU		45 BRO	SP	CCA		V	00:00.0
2021 PO0278662638	KU		30 BRO	SP	CRE		V	00:00.0
2021 PO0263062750	KU		40 BRO	SP	CRE		V	00:00.0
2021 PO0268562698	KU		40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0200962745	KU		40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6640891237	F		40 BRN	SP	CRE		V	00:00.0
2021 PO6636991285	F		40 BRN	SP	CRE		V	00:00.0
2021 PO5041289641	LGE		30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5040889635	LGE		40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO0213434915	ODP		40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8561221439	ODP		40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO8594221340	ODP		30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4934488922	LGE		45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8511621236	ODP		40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO8549221370	ODP		40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO5474509717	KU		45 BRN	SP	S	ED,SRC	TD	00:00.0
2021 PO0358735553	ODP		40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0284134746	ODP		40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7729818905	ODP		45 OTH	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO4939889848-a	LGE		45 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4939889848	LGE		45 BRN	SP	P	ED,ID	TD	00:00.0

2021 PO9568131627	ODP	5	35 REP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9497831839	ODP	4	40 REP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9035423772	ODP	5	35 REP	SP	CRE	ED,ID	TD	00:00.0
2021 PO5491011127	KU	3	45 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4954289432	LGE	3	50 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO8604921607	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4954589435	LGE	4	30 ACE	SP	CCA	ED	TD	00:00.0
2021 PO0135036996	ODP	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4712489969	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0956242038	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0998442428A	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO9408525661	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9382225333	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9402625308	ODP	5	30 XXX	DF	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO9443625007	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9504324669	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9476024826	ODP	5	35 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO4714789946	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5454111293	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO5452111197	KU	4	40 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO8759022347	ODP	2	55 KOP	SP	CRE	ED	TD	00:00.0
2021 PO9324126380	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9309826263	ODP	3	50 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO9292826111	ODP	2	55 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4967189493	LGE	3	50 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4897489047	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4898289026	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO8811122144	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO0350838599	ODP	4	40 CPT	SP	CRE	ED,ID	TD	00:00.0
2021 PO1202843577	ODP	4	45 UNK	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO0358038300	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8930022693	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8914022849	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8917922786	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8932222911	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1130243395	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO1134843139	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO1166843348	ODP	4	40 UNK	SP	P	ED,ID,SRC	TD	00:00.0
2021 PO4728689968	LGE	4	30 ACE	SP	P	ED,ID,IP	TD	00:00.0
2021 PO1079143282	ODP	6	30 BRO	SP	CRE	ED,ID,MD,SRC	TD	00:00.0
2021 PO4713189973	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO0998442428	ODP	5	35 MCM	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0123336719	ODP	6	30 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4912188972	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4712089983	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4827488746	LGE	3	45 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4827188754	LGE	4	30 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO0014336265	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7245017678	ODP	4	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO8751221874	ODP	6	30 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO1101043244	ODP	5	35 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO7678319997	ODP	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4954489390	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5489211133	KU	3	45 OTH	SP	CRE	ED,ID	TD	00:00.0

2021	PO6272820850	ODP	4	40 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO4903089122	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO2633338456	ODP	4	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4936288908	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6913616660	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6911216785	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6907816930	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6896317314	ODP	4	40 BRN	SP	A	ED,ID	TD	00:00.0
2021	PO7743621388	ODP	4	40 OTH	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO4971289550	LGE	3	45 ACE	SP	CCA	ED	TD	00:00.0
2021	PO4939589697	LGE	3	45 BRN	SP	P	ED,ID,MD	TD	00:00.0
2021	PO7755819177	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7787619065	ODP	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO7807219096	ODP	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021	PO4933588929	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4821588680	LGE	4	40 BRO	SP	CRE	ID	TD	00:00.0
2021	PO8346420104	ODP	5	35 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021	PO4823688837	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO4943088990	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO4940288938	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021	PO7661319612	ODP	5	35 OTH	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021	PO4939188966	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021	PO4823788856	LGE	6	25 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4813288586	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021	PO6942418647	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6926219000	ODP	4	45 BRN	SP	CCA	ED,ID	TD	00:00.0
2021	PO6954019285	ODP	2	50 BRN	SP	CCA	ED,ID	TD	00:00.0
2021	PO4936689841	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO4935488915	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8633121705	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021	PO8632521636	ODP	6	30 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021	PO4848788901	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4821488787	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4821288794	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9144824956	ODP	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO9173125160	ODP	2	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4849188900	LGE	4	40 BRN	DF	CRE	ED,ID	TD	00:00.0
2021	PO4933889835	LGE	3	45 BRN	SP	P	ED,ID,MD,SRC	TD	00:00.0
2021	PO6938321826	ODP	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6966420155	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO5345110259	KU	2	55 BRN	SP	S	ED	TD	00:00.0
2021	PO4882189794	LGE	4	35 BRN	SP	CCA	ED,MD	TD	00:00.0
2021	PO0195933948	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0170434038	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0182533767	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0172233830	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO7456419903	ODP	4	40 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021	PO7527920153	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO6956718467	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO0187034271	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0185934149	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021	PO8418121616	ODP	2	50 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO8427821646	ODP	4	45 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO5389912772	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0

2021 PO0222534656	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO8148319653	ODP	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO8390321415	ODP	4	45 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO7384820532	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9556332963	ODP	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5352412758	KU	3	45 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO5442612407	KU	4	40 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO7384220410	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9212624190	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO8346819557	ODP	4	30 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO8691721915	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO5409309351	KU	3	45 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO4966589433	LGE	4	30 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO8716822164	ODP	2	55 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO4945388976	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4824588810	LGE	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7587620236	ODP	5	35 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO8326620298	ODP	4	40 BRN	SP	CRE	ED,SRS	TD	00:00.0
2021 PO4824888802	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO9033323838	ODP	3	50 BRO	SP	CCA	ED,ID	TD	00:00.0
2021 PO9093324215	ODP	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4934989822	LGE	4	30 BRN	SP	CRE	ED,ID,MD	TD	00:00.0
2021 PO8678422034	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO9004723809	ODP	3	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4934589816	LGE	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4951389412	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO8659321807	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7135019549	ODP	2	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7572720224	ODP	5	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6945523412	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4932088934	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5416509636	KU	3	45 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO5414009539	KU	3	45 OTH	SP	CRE	ED,ID	TD	00:00.0
2021 PO4703789892	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO9260224366	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9238724166	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7588819908	ODP	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4809488705	LGE	4	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4832489415	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO9072920347	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO0745640663A	ODP	6	30 KOP	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0774640815	ODP	4	40 KOP	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO9035120927	ODP	5	35 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO0715840396	ODP	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO4919588942	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0711640517	ODP	6	30 BRN	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO8975722077	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0662840080	ODP	5	35 BRN	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO4965589465	LGE	3	50 ACE	SP	CCA	ED,SRC	TD	00:00.0
2021 PO9010321481	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4904589020	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4901788997	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7514217299	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7534317326	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0

2021 PO4863688607	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4964589450	LGE	3	50 ACE	SP	P	ED,SRC	TD	00:00.0
2021 PO5301606996	KU	2	50 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO0670239902	ODP	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021 PO4965189458	LGE	3	50 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO4937188902	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4820188830	LGE	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO4819288828	LGE	5	25 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9753230842	ODP	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9796331062	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9721631061	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO7586617473	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7593117661	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8908423150	ODP	4	45 KOP	SP	CRE	ED	TD	00:00.0
2021 PO4901088956	LGE	4	30 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO7666418088	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7672918300	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7695318616	ODP	2	55 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7675218577	ODP	4	50 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4899888984	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0318533835	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO9129320389	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO9129320389	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7660318560	ODP	4	50 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4721590001	LGE	4	30 ACE	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0533234201	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO0473534204	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0465234447	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0510634261	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0559134567	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0545634375	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4861188629	LGE	4	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9134820251	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO0302433692	ODP	5	35 BRN	SP	CRE	ID,IP	TD	00:00.0
2021 PO0298133800	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO9104619869	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO0195537242	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0839941094	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0803440778	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO8949022507	ODP	5	25 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4901989011	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO0745640663	ODP	4	40 KOP	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO5590620487	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8958122259	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5568120542	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7789018660	ODP	5	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7787518758	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7834118665	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5557220447	KU	5	35 BRN	DF	CRE	ED,ID	TD	00:00.0
2021 PO4833689475	LGE	4	35 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4833289485	LGE	4	35 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4832789496	LGE	4	30 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO7902718914	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7859518846	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0

2021	PO0447338731	ODP	5	35 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO5551220340	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4884788642	LGE	4	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO6487019382	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021	PO6507619875	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021	PO0560739093	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO0240133575	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO5539520540	KU	6	30 OTH	SP	CRE	ED,ID	TD	00:00.0
2021	PO4886488614	LGE	4	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO5532120539	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO4884488621	LGE	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4884788612	LGE	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4885088604	LGE	3	45 BRN	SP	CCA	ED	TD	00:00.0
2021	PO0273737853	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO4884188629	LGE	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO4818788860	LGE	4	30 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO4820288866	LGE	4	30 BRN	SP	P	ED,ID	TD	00:00.0
2021	PO7551417347	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO5547520781	KU	6	30 OTH	SP	CRE	ED,ID	TD	00:00.0
2021	PO5313010171	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD	00:00.0
2021	PO4854388924	LGE	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO0099333738	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0093033453	ODP	5	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021	PO0102233442	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021	PO7648420211	ODP	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021	PO3674706396	KU	3	50 BRN	SP	CCA		V	00:00.0
2021	PO3674506632	KU	3	45 BRN	SP	CRE		V	00:00.0
2021	PO3762307670	KU	6	30 BRN	SP	CRE		V	00:00.0
2021	PO3757507706	KU	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4927190265	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4801090420	LGE	3H	45 BRO	SP	CCA		V	00:00.0
2021	PO4749390208	LGE	4	40 BRN	SP	P		V	00:00.0
2021	PO4746790252	LGE	H1	75 BRN	SP	P		V	00:00.0
2021	PO4748290224	LGE	H1	75 BRN	SP	P		V	00:00.0
2021	PO4756890217	LGE	H1	75 BRN	ST	CCA		V	00:00.0
2021	PO4769089664	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021	PO4753890203	LGE	H1	80 BRN	SP	P		V	00:00.0
2021	PO4752190196	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO6333015846	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO7696347344	KU	6	30 BRO	SP	CRE		V	00:00.0
2021	PO7709947224	KU	6	30 BRO	SP	CCA		V	00:00.0
2021	PO2166142572	KU	5	35 XXX	SP	CCA		V	00:00.0
2021	PO7765248175	KU	3	45 KOP	SP	CCA		V	00:00.0
2021	PO4878690445	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021	PO4881190444	LGE	5	35 BRO	SP	CCA		V	00:00.0
2021	PO4884890447	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO7718747228	KU	4	40 BRO	SP	S		V	00:00.0
2021	PO4887290446	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021	PO4649607997	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4671307921	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4649807900	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4640907987	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4671208017	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4886690420	LGE	2	55 BRO	SP	CCA		V	00:00.0

2021	PO5381301190	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5210314049	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021	PO4815590113	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021	PO5250014156	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021	PO5276714237	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021	PO5295914292	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021	PO4823890137	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021	PO4825790142	LGE	1	60 BRN	SP	CCA	V	00:00.0
2021	PO0116173365	KU	2	50 BRO	SP	CCA	V	00:00.0
2021	PO0149073266	KU	4	45 BRO	SP	CCA	V	00:00.0
2021	PO5268496690	F	5	35 BRN	SP	CRE	V	00:00.0
2021	PO5322915809	LGE	1	50 BRN	SP	CCA	V	00:00.0
2021	PO4826190200	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021	PO4826490204	LGE	4	45 BRN	SP	CCA	V	00:00.0
2021	PO0478774114	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO0152173988	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4762489851	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021	PO4763089835	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021	PO0240966061	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO0223866219	KU	3	55 BRO	SP	CRE	V	00:00.0
2021	PO0190366564	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4768391092	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5343396577	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5356796500	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4884990239	LGE	3	50 BRN	SP	P	V	00:00.0
2021	PO4793090683	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021	PO4803790318	LGE	3	50 BRO	SP	CCA	V	00:00.0
2021	PO4801790438	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021	PO5084916850	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021	PO4806590261	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021	PO5730901783	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5727801689	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5722301520	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5717001432	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO7613147461	KU	5	35 BRO	SP	CCA	V	00:00.0
2021	PO7625447384	KU	6	30 BRO	SP	CCA	V	00:00.0
2021	PO5366014084	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021	PO4829790102	LGE	1	55 BRN	SP	CCA	V	00:00.0
2021	PO4832490108	LGE	3	45 BRN	SP	P	V	00:00.0
2021	PO3775500594	KU	3	45 BRN	SP	S	V	00:00.0
2021	PO3770000853	KU	3	45 BRN	SP	CCA	V	00:00.0
2021	PO7585347794	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO7609847727	KU	5	35 BRO	SP	CCA	V	00:00.0
2021	PO7621447698	KU	5	35 BRO	SP	CCA	V	00:00.0
2021	PO4075302263	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4018502298	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4033702289	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO3682906132	KU	5	35 BRN	SP	CRE	V	00:00.0
2021	PO4118002259	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4089402253	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4061602272	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO40407702281	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO0432365846	KU	3	45 XXX	SP	CCA	V	00:00.0
2021	PO5397096955	F	4	40 BRN	SP	CRE	V	00:00.0

2021	PO5388597018	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5383397054	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5387297095	F	5	35 BRN	SP	CRE	V	00:00.0
2021	PO4900790403	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021	PO0680266135	KU	6	35 XXX	SP	CRE	V	00:00.0
2021	PO0817065854	KU	3	40 XXX	SP	CCA	V	00:00.0
2021	PO0829966007	KU	3	40 XXX	SP	CCA	V	00:00.0
2021	PO0867365946	KU	6	30 XXX	SP	CCA	V	00:00.0
2021	PO5664502629	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5687002546	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5691802688	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5694502771	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO7285247262	KU	4	40 BRO	SP	CCA	V	00:00.0
2021	PO7285247401	KU	3	45 BRO	SP	CCA	V	00:00.0
2021	PO7285347455	KU	4	40 BRO	SP	CCA	V	00:00.0
2021	PO4901190396	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021	PO4901790387	LGE	4	40 BRN	SP	P	V	00:00.0
2021	PO4534406316	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5256798579	F	4	40 MAR	SP	CRE	V	00:00.0
2021	PO5267498530	F	4	40 MAR	SP	CRE	V	00:00.0
2021	PO5278498482	F	4	40 MAR	SP	CCA	V	00:00.0
2021	PO5289898433A	KU	3	40 MAR	SP	P	V	00:00.0
2021	PO5289898433	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4580106515	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO5681802930	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5705703151	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5697002845	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5700502956	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5704403071	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5703203255	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5698403292	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5639603515	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5635103404	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5623803196	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5618803102	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5612502987	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5654003780	F	5	30 XXX	SP	CRE	V	00:00.0
2021	PO5650903724	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO5645503624	F	4	40 XXX	SP	CRE	V	00:00.0
2021	PO4606606674	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4646306344	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4605006558	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4871190439	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021	PO4902790369	LGE	4	40 BRN	SP	P	V	00:00.0
2021	PO4903690355	LGE	3	45 BRN	SP	CCA	V	00:00.0
2021	PO4904790337	LGE	4	40 BRN	SP	P	V	00:00.0
2021	PO4905890319	LGE	4	40 BRN	SP	P	V	00:00.0
2021	pv4864390442	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO4885690351	LGE	1	50 BRO	SP	CCA	V	00:00.0
2021	PO4885390332	LGE	2	60 BRO	SP	CCA	V	00:00.0
2021	PO4902390116	LGE	3	45 BRO	SP	A	V	00:00.0
2021	PO4722707750	KU	6	30 BRN	SP	CCA	V	00:00.0
2021	PO4686407031	F	4	40 BRN	SP	CRE	V	00:00.0
2021	PO4682906877	F	3	45 BRN	SP	CRE	V	00:00.0



2021 PO4694007174	F	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO4720406717	F	3	45 BRN	SP	CRE	V	00:00.0	
2021 PO4730107920	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO4750806585	F	3	45 BRN	SP	CRE	V	00:00.0	
2021 PO4732606663	F	3	45 BRN	SP	CRE	V	00:00.0	
2021 PO4774806482	F	3	45 BRN	SP	CRE	V	00:00.0	
2021 PO4745990265	LGE	4	35 BRN	SP	P	V	00:00.0	
2021 PO4745090282	LGE	H1	60 BRN	SP	P	V	00:00.0	
2021 PO0553079370	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO4762606534	F	2	45 BRN	SP	CRE	V	00:00.0	
2021 PO0530379024	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO4717406729	F	3	45 BRN	SP	CRE	V	00:00.0	
2021 PO4680106890	F	3	45 BRN	SP	CRE	V	00:00.0	
2021 PO4785306436	F	3	45 BRN	SP	CRE	V	00:00.0	
2021 PO5943753703	KU	6	30 BRO	SP	CRE	V	00:00.0	
2021 PO5935453570	KU	4	40 BRO	SP	CCA	V	00:00.0	
2021 PO5990304789	F	3	45 UNK	UN	CRE	V	00:00.0	
2021 PO5956353601	KU	4	40 BRO	SP	CCA	V	00:00.0	
2021 PO5952253503	KU	4	40 BRO	SP	CCA	V	00:00.0	
2021 PO0554478705	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO0578578385	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO0577178151	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO4744290296	LGE	4	40 BRN	SP	CCA	V	00:00.0	
2021 PO4742390330-a	LGE	H1	75 BRN	SP	P	V	00:00.0	
2021 PO5451696682	KU	2	45 BRN	SP	P	V	00:00.0	
2021 PO5454596775	F	2	50 BRN	SP	P	V	00:00.0	
2021 PO5504296391	KU	2	45 BRN	SP	P	V	00:00.0	
2021 PO5488796439	F	2	45 BRN	SP	P	V	00:00.0	
2021 PO5475096482	F	2	45 BRN	SP	P	V	00:00.0	
2021 PO5461496525	KU	2	45 BRN	SP	P	V	00:00.0	
2021 PO5447896568	KU	2	45 BRN	SP	P	V	00:00.0	
2021 PO4741590345	LGE	2	70 BRN	SP	P	V	00:00.0	
2021 PO4740790355	LGE	4	40 BRN	SP	P	V	00:00.0	
2021 PO7291346914	KU	5	35 BRO	SP	CCA	V	00:00.0	
2021 PO7294847115	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO7285247199A	KU	5	35 BRO	SP	CCA	V	00:00.0	
2021 PO0564478023	KU	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO7261147900	KU	6	30 BRO	SP	CRE	V	00:00.0	
2021 PO7285847567	KU	3	45 BRO	SP	CCA	V	00:00.0	
2021 PO4803890352	LGE	2	55 BRO	SP	CCA	V	00:00.0	
2021 PO4804290337	LGE	2	55 BRO	SP	CCA	V	00:00.0	
2021 PO4804790322	LGE	2	55 BRO	SP	CCA	V	00:00.0	
2021 PO4773090681	LGE	3	45 BRN	SP	P	V	00:00.0	
2021 PO4779390704	LGE	3	45 BRN	SP	CCA	V	00:00.0	
2021 PO0210774523	KU	4	45 BRO	SP	CCA	V	00:00.0	
2021 PO0302875062	KU	4	40 BRO	SP	S	V	00:00.0	
2021 PO0252274717	KU	4	45 BRO	SP	S	V	00:00.0	
2021 PO0280075113	KU	4	45 BRO	SP	S	V	00:00.0	
2021 PO0291475289	KU	4	45 BRO	SP	CCA	V	00:00.0	
2021 PO4773989955	LGE	UNK	25 BRN	SP	P	V	00:00.0	
2021 PO4794390567	LGE	4	40 BRN	SP	CCA	V	00:00.0	
2021 PO4757290703	LGE	4	40 BRN	SP	CCA	V	00:00.0	
2021 PO5335814422	LGE	1	60 BRN	SP	CCA	V	00:00.0	
2021 PO7230248427	KU	6	30 BRO	SP	CCA	ED	V	00:00.0

2021 PO4798090180	LGE	3H	40	BRN	ST	CCA		V	00:00.0	
2021 PO4804790240	LGE		3	45	BRN	SP	CCA	V	00:00.0	
2021 PO5362700739	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO5364800767	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO5383300700	F		4	40	BRN	SP	A	V	00:00.0	
2021 PO4780089900	LGE	UNK		20	BRN	AL	S	V	00:00.0	
2021 PO3956305022	F		2	55	BRN	SP	CRE	V	00:00.0	
2021 PO3920006449	F		3	45	BRN	SP	CRE	V	00:00.0	
2021 PO3915105962	F		4	40	BRN	SP	CCA	V	00:00.0	
2021 PO3918006240	F		4	40	BRN	SP	CCA	V	00:00.0	
2021 PO7296948883	KU		4	45	BRO	SP	CCA	V	00:00.0	
2021 PO7325649545	KU		3	45	BRO	SP	CCA	V	00:00.0	
2021 PO5599101479	F		4	40	XXX	SP	P	V	00:00.0	
2021 PO4892890919	LGE		4	40	BRN	SP	CRE	ED,ID	V	00:00.0
2021 PO4900490707	LGE		1	45	BRN	SP	CCA	V	00:00.0	
2021 PO6095420566	LGE		4	35	BRN	SP	CCA	V	00:00.0	
2021 PO4886890690	LGE		4	40	BRN	SP	A	V	00:00.0	
2021 PO4889190699	LGE		4	40	BRN	SP	A	V	00:00.0	
2021 PO4888490670	LGE		4	40	BRN	SP	A	V	00:00.0	
2021 PO0403075744	KU		3	45	BRN	SP	CCA	V	00:00.0	
2021 PO0427275624	KU		3	45	BRN	SP	CCA	V	00:00.0	
2021 PO0460575826	KU		4	45	BRN	SP	CCA	V	00:00.0	
2021 PO5476297614	F		2	45	KOP	SP	CRE	V	00:00.0	
2021 PO5462897677	F		4	40	KOP	SP	CRE	V	00:00.0	
2021 PO5448497740	F		3	45	KOP	SP	CRE	V	00:00.0	
2021 PO5427297837A	F		3	45	KOP	SP	CCA	V	00:00.0	
2021 PO5424697728	F		4	40	KOP	SP	CRE	V	00:00.0	
2021 PO38.31607827097178-85.5588	LGE		1	50	BRO	SP	CCA	V	00:00.0	
2021 PO5425097515	F		4	40	KOP	SP	CRE	V	00:00.0	
2021 PO5422797580	F		4	40	KOP	SP	CRE	V	00:00.0	
2021 PO5442897431A	F		6	30	KOP	SP	CCA	V	00:00.0	
2021 PO5442897431	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO5434897119	F		2	40	BRN	SP	CRE	V	00:00.0	
2021 PO5407597142	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO3884705478	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO3842505597	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO3885105595	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO3814305678	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO3856405557	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO3888206027	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO3883305408	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO3866305529	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO3821405656	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO6072117463	LGE		1	50	BRO	SP	CCA	V	00:00.0	
2021 PO5099816734	LGE		2	55	BRO	SP	CCA	V	00:00.0	
2021 PO4774589970	LGE		3	50	BRN	SP	CCA	V	00:00.0	
2021 PO4822612657	LGE		1	50	BRN	SP	CCA	V	00:00.0	
2021 PO4788190534	LGE		4	40	BRN	SP	A	V	00:00.0	
2021 PO5317500933	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO5304300968	F		4	40	BRN	SP	CRE	V	00:00.0	
2021 PO4776189994	LGE	UNK		55	BRN	SP	CRE	V	00:00.0	
2021 PO4776689984	LGE		4	30	BRN	SP	CCA	V	00:00.0	
2021 PO4802390220	LGE		3	45	BRN	ST	CCA	V	00:00.0	
2021 PO4808390203-A	LGE		1	50	BRN	SP	CCA	V	00:00.0	

2021	PO6501247607	KU	4	45 KOP	SP	CCA		V	00:00.0
2021	PO5158614883	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021	PO7246048612	KU	4	45 BRO	SP	CCA		V	00:00.0
2021	PO7238548537	KU	5	35 BRO	SP	S		V	00:00.0
2021	PO7233748630	KU	3	45 BRO	SP	CCA		V	00:00.0
2021	PO6503147811	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO4807790216	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021	PO6528147563	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO4019504516	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3991504646	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4003704862	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4005205002	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4004504586	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO3966604819	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO5586202041	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5621802214	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5612202281	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5604901893	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO5595401976	F	4	40 XXX	SP	CRE	ED	V	00:00.0
2021	PO5615801831	F	4	45 XXX	SP	CRE	ED	V	00:00.0
2021	PO5631302131	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5642202058	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5652202005	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5673501891	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5591101511	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO5589201616	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO3855905476	F	2	45 BRN	SP	CRE		V	00:00.0
2021	PO3842804981	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4878090858	LGE	3	45 BRN	SP	P		V	00:00.0
2021	PO4803990444	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021	PO4880990871	LGE	3	45 BRN	SP	CCA		B	00:00.0
2021	PO6073120107	LGE	1	50 BRN	SP	CCA		B	00:00.0
2021	PO6627548295	KU	1	70 BRN	ST	CRE		V	00:00.0
2021	PO6691348330	KU	1	70 BRN	ST	CRE		V	00:00.0
2021	PO6964847285	KU	2	40 XXX	SP	CRE	ID,IP	TD	00:00.0
2021	PO6934947330	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021	PO6474949137	KU	6	30 BRN	SP	CCA		V	00:00.0
2021	PO3935785036	LGE	1	55 ACE	SP	CRE	ED,ID	TD	00:00.0
2021	PO4448986042	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO4448886030	F	3	45 BRN	SP	CRE		V	00:00.0
2021	PO4449786144	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO7509846614	KU	4	40 UNK	SP	CCA		V	00:00.0
2021	PO4815890341	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO4822590393	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021	PO3853801113	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO7380047412	KU	5	35 BRO	SP	CCA		V	00:00.0
2021	PO6065220160	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO4307598683	F	4	40 BRO	SP	CRE	ED,HH,ID,IP,RB	BX	RP1 00:00.0
2021	PO5813398665	F	4	45 XXX	SP	CRE		V	00:00.0
2021	PO5804598713	F	4	40 XXX	SP	P		V	00:00.0
2021	PO5789398802	F	3	45 XXX	SP	P		V	00:00.0
2021	PO5782198844	F	4	45 XXX	SP	P		V	00:00.0
2021	PO5774198890	F	4	45 XXX	SP	CRE		V	00:00.0
2021	PO5774299060	F	4	45 XXX	SP	CRE		V	00:00.0

2021	PO5766598935	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021	PO5757298989	KU	3	40 XXX	SP	CRE	ED,ID	BD		00:00.0
2021	PO5738199093	F	4	45 XXX	SP	CRE		V		00:00.0
2021	PO5742299074	F	4	45 XXX	SP	CRE		V		00:00.0
2021	PO5757298989	F	4	45 XXX	SP	P	ID,IP	BX	RP2	00:00.0
2021	PO5732799114	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5802398092	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5806298537	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO4337287050	F	UNK	50 BRN	SP	CRE		V		00:00.0
2021	PO6757549126A	F	6	30 BRN	SP	CRE		V		00:00.0
2021	PO6754549002	KU	6	30 BRN	SP	CCA		V		00:00.0
2021	PO6755649033	KU	6	30 BRN	SP	CCA		V		00:00.0
2021	PO6757549126	KU	4	45 BRN	SP	CRE	ED	TD		00:00.0
2021	PO4212988059	LGE	4	35 BRN	SP	A	ED,ID,IP	TD		00:00.0
2021	PO4214188057	LGE	2	60 BRN	SP	A	ID,IP	BD		00:00.0
2021	PO7006747899	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4211388061	LGE	1	65 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO7001547772	KU	4	40 XXX	SP	CRE	ID,IP	BD		00:00.0
2021	PO7001648005	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO7001647901	KU	4	40 XXX	SP	CRE	HH,ID	TX	RR	00:00.0
2021	PO6995847657	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO7001447658	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO4909591155	LGE	4	35 BRN	SP	A		V		00:00.0
2021	PO4899990984	LGE	3	55 BRN	SP	A		V		00:00.0
2021	PO4900290997	LGE	4	40 BRN	SP	A		V		00:00.0
2021	PO4899091018	LGE	4	40 BRN	SP	A		V		00:00.0
2021	PO5933723883	LGE	5	30 BRN	SP	A		V		00:00.0
2021	PO4887991082	LGE	2	65 BRN	SP	A		V		00:00.0
2021	PO4887891080	LGE	2	65 BRN	SP	A		V		00:00.0
2021	PO5935323901	LGE	5	30 BRN	SP	A		V		00:00.0
2021	PO4888091083	LGE	2	65 BRN	SP	A		V		00:00.0
2021	PO7108046804A	KU	4	40 BRO	SP	CCA	ED,ID	TD		00:00.0
2021	PO7107846721	KU	2	70 BRO	SP	S		V		00:00.0
2021	PO5530093301	F	2	45 BRN	SP	CRE		V		00:00.0
2021	PO4449986200	LGE	H1	80 BRN	SP	A		V		00:00.0
2021	PO5534893420	F	2	55 BRN	SP	CRE		V		00:00.0
2021	PO7058547793	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO4450286123	F	2	60 BRN	SP	P		V		00:00.0
2021	PO4450186110	F	2	60 BRN	SP	P		V		00:00.0
2021	PO4449786089	F	3	50 BRN	SP	P		V		00:00.0
2021	PO6752148323	KU	2	65 BRN	ST	CRE		V		00:00.0
2021	PO6752148343	KU	1	55 BRN	ST	CRE		V		00:00.0
2021	PO1631573232	F	3	45 BRN	SP	CCA		V		00:00.0
2021	PO5734399029	KU	3	45 XXX	SP	P	ED,ID	TD		00:00.0
2021	PO7001447524	KU	4	45 XXX	SP	CCA		V		00:00.0
2021	PO7058847948	KU	3	35 XXX	SP	CRE	ID	BD		00:00.0
2021	PO7058947980	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021	PO7068248029	KU	5	30 XXX	SP	CRE	ID	TD		00:00.0
2021	PO7071447969	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO7070847755	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO5456494039	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5466893990	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO6450749114	KU	4	40 BRN	SP	CCA		V		00:00.0
2021	PO6458649055	F	4	40 BRN	SP	CRE		V		00:00.0

2021	PO6466048999	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO6473948941	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO6480748890	F	4	40 BRN	SP	A		V	00:00.0	
2021	PO4450686181	F	1	70 BRN	SP	P		V	00:00.0	
2021	PO5476393928	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO5487293858	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO7001447381	KU	4	45 XXX	SP	CCA		V	00:00.0	
2021	PO3760300076	KU	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0	
2021	PO3751299745	F	3	45 BRN	SP	CRE		V	00:00.0	
2021	PO3741899513	F	3	45 BRN	SP	CRE		V	00:00.0	
2021	PO4889491101	LGE	3	50 BRN	SP	A		V	00:00.0	
2021	PO5541293587	F	2	50 BRN	SP	CRE		V	00:00.0	
2021	PO5531693622	F	3	45 BRN	SP	CRE		V	00:00.0	
2021	PO5519693667	F	3	45 BRN	SP	CRE		V	00:00.0	
2021	PO5548893789	F	3	45 BRN	SP	CRE		V	00:00.0	
2021	PO4897091074	LGE	3	50 BRN	SP	A		V	00:00.0	
2021	PO7768646961	F	4	40 BRO	SP	CRE		V	00:00.0	
2021	PO7776446707	KU	4	45 KOP	SP	CRE	ID	BD	00:00.0	
2021	PO7787045709	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO6518048636	KU	1	75 BRN	SP	CRE		V	00:00.0	
2021	PO4208188205	LGE	5	35 BRN	SP	CCA		V	00:00.0	
2021	PO5553094234	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO5562894192	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO5564794169	F	2	45 BRN	SP	CRE		V	00:00.0	
2021	PO5557494020	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO4058684076	LGE	4	40 BRN	SP	CCA		V	00:00.0	
2021	PO4059884077	LGE	4	40 BRN	SP	CCA		V	00:00.0	
2021	PO4202488220	LGE	3	45 BRN	SP	CRE	ID,IP	BD	00:00.0	
2021	PO6531148546	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0	
2021	PO3805101859	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO3817501852	F	4	40 BRN	SP	CRE		V	00:00.0	
2021	PO5718598657	F	4	45 XXX	SP	CRE	ED,EP,ID,MD	BX	RP3	00:00.0
2021	PO7380346615	KU	5	35 BRO	SP	CCA		V	00:00.0	
2021	PO7386447099	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0	
2021	PO7368947083	KU	3	40 UNK	SP	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO7345946786A	KU	5	35 BRO	SP	CCA		V	00:00.0	
2021	PO7326447094	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021	PO7341147129	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0	
2021	PO7345946786	KU	5	35 BRO	SP	CCA		V	00:00.0	
2021	PO7342147168	KU	6	30 BRO	SP	CRE		V	00:00.0	
2021	PO7340247238	KU	5	35 BRO	SP	CCA		V	00:00.0	
2021	PO7387047154	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO7416747396	KU	6	30 UNK	SP	CRE	ID	BD	00:00.0	
2021	PO7418547236	KU	6	30 BRO	SP	CRE	ID	BD	00:00.0	
2021	PO7399547178	F	5	40 UNK	SP	CRE		V	00:00.0	
2021	PO4896991056	LGE	3	50 BRN	SP	A		V	00:00.0	
2021	PO4910891107	LGE	4	40 BRN	SP	A		V	00:00.0	
2021	PO4906491085	LGE	4	40 BRN	SP	A		V	00:00.0	
2021	PO4902291063	LGE	4	40 BRN	SP	A		V	00:00.0	
2021	PO4898091041	LGE	3	50 BRN	SP	A		V	00:00.0	
2021	PO4896891037	LGE	3	50 BRN	SP	A		V	00:00.0	
2021	PO4893391024	LGE	3	45 BRN	SP	A		V	00:00.0	
2021	PO4898390894	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0	
2021	PO4932091312	LGE	2	65 BRN	SP	A		V	00:00.0	

2021 PO4934591300	LGE	4	40 BRN	SP	A		V		00:00.0
2021 PO4936991290	LGE	3	45 BRN	SP	A		V		00:00.0
2021 PO4939391279	LGE	3	45 BRN	SP	A		V		00:00.0
2021 PO4941591269	LGE	3	45 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO6890547899	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3832701841	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6186251204	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO6167750749	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7015547501	KU	5	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7022347330	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6440849442	KU	4	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO6438149404	F	4	40 BRN	SP	P		V		00:00.0
2021 PV9216394001	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4213688198	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4212488200	LGE	2	55 BRN	SP	CCA		V		00:00.0
2021 PO6738549277A	KU	4	30 BRN	SP	CCA		V		00:00.0
2021 PO6738549277	KU	5	35 BRN	SP	CRE	ED	TD		00:00.0
2021 PO4063299458	F	3	40 BRO	SP	P	ED	V		00:00.0
2021 Tel	F	3	45 BRO	SP	P	ED	V		00:00.0
2021 PO4050199522	F	2	50 BRO	SP	CRE	ED,ID,IP,RB	BX	RP3	00:00.0
2021 PO4056884242	LGE	4	40 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO4056684239	LGE	4	40 BRN	SP	A		VX	RP2	00:00.0
2021 PO4200088224	LGE	3	50 BRN	SP	CCA		V		00:00.0
2021 PO5723398964	F	2	50 XXX	SP	P		V		00:00.0
2021 PO5704898857	F	4	45 XXX	SP	CRE	ED,HH,ID,MD	BX	RP1	00:00.0
2021 PO5707798654	F	4	45 XXX	SP	A		V		00:00.0
2021 PO5713798728	F	4	45 XXX	SP	P		V		00:00.0
2021 PO6908947915	KU	3	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO3999486789	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3997986774	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3998486778	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3998586779	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3998586780	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3998786778	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3998886777	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO3999386776	LGE	3	40 ACE	SP	CCA		V		00:00.0
2021 PO6908547606b	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6908547606a	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3771600875	KU	3	45 BRN	SP	CRE	HH,ID,IP	BX	PX	00:00.0
2021 PO7014449280	F	5	30 UNK	SP	P		V		00:00.0
2021 PO6502648428	KU	4	45 BRN	SP	CCA		V		00:00.0
2021 PO4463786016	F	3	50 BRN	SP	CRE		V		00:00.0
2021 PO4448286145	LGE	2	55 BRN	SP	A	ED,ID	BD		00:00.0
2021 PO7021149344	F	4	40 UNK	SP	CRE		V		00:00.0
2021 PO7020049275	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO7018949215	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7016749100	KU	5	35 UNK	SP	CRE		V		00:00.0
2021 PO7017649148	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO7015549017	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO7028048998	KU	4	40 UNK	SP	CRE		V		00:00.0
2021 PO7038248981	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO7047248966	KU	4	40 UNK	SP	CRE	ED,ID,IP,SR	TX	RR	00:00.0
2021 PO7071048927	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO7085448905	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0

2021 PO4338287040	F	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4463485994	F	2	55 BRN	SP	CRE		V	00:00.0
2021 PO4209288182	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4209688182	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO7084647903	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7084847957	KU	4	45 XXX	SP	CRE	ID	BD	00:00.0
2021 PO7097047791	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4204388220	LGE	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5470894578	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9151594337	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4204588229	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5437894717	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5459994624	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5448994669	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5426694765	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5415694814	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5404894859	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5393994905	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5688698401	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5488298398	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5460298511	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5454898375	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5440698436	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5427398496	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5416098542	KU	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO5432398634	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5565698078	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4076884395	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO7670745011	F	4	40 KOP	SP	P		V	00:00.0
2021 PO7678445155	F	4	40 KOP	SP	P		V	00:00.0
2021 PO7684444924	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7700245312	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5382694951	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5371195004	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5611193223	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO4075684372	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7690945366	F	4	40 KOP	SP	P		V	00:00.0
2021 PO7698845503	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO5750893762	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7173549449	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9979680306	KU	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO7169649534	KU	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7180649527	KU	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7194049561	KU	4	45 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7164649534	KU	5	30 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4996089323	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7051906503	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4999189319	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4999089319	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5001589318	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO0138533099	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0130533093	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4890090150	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5690504109	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0

2021 PO5696804171	KU	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO2105465802	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6389349280	KU	1	70 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO6397649234	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4907690117	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4906390110	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5803505787	F	4	40 BRN	SP	P		V	00:00.0
2021 PO5786205900	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5812305928	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5001289312	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5001289316	LGE	3	45 ACE	SP	A		V	00:00.0
2021 PO6402449330	KU	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6402249209	KU	1	70 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4423707731	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4439406927	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4426706944	F	4	40 BRN	SP	CRE	HH,ID,RB	BX	RP1
2021 PO4412606898	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO4414806951	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4418607043	F	3	40 BRN	SP	CCA		V	00:00.0
2021 PO5004189310	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO2129065709	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5823306037	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5801406301	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5831206101	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5001489314	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO5695704322	KU	3	40 XXX	SP	P		V	00:00.0
2021 PO5002689313	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO5732304568	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5731104480	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5727104395	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5730004301	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5733404193	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5727604103	F	4	40 XXX	SP	CRE	ED,ID,IP	BX	RP1
2021 PO5701404144	F	4	40 XXX	SP	CRE	ED,ID,IP	BX	PX
2021 PO5706504013	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5734604395	KU	6	30 XXX	SP	S		V	00:00.0
2021 PO5751704125	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5783404155	F	2	45 XXX	SP	P		V	00:00.0
2021 PO5781304285	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5785404348	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5790404116	F	4	40 XXX	SP	P	ED,ID	BX	RP2
2021 PO5766604040	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5772304130	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5776804203	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5778204140	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5006389307	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO7169206362	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4905090102	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5011189311	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO0119733545	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2182065488	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7256506320	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO7271806262	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO7292306185	LGE	1	55 ACE	SP	CCA		V	00:00.0



2021 PO4903690096	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO7223506338	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7226306323	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO7231006323	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021 PO4381907611	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4376907838	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4369607661	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4356807714	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4406607310	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO2222765313	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6086103607	KU	3	45 BRN	SP	CRE	ED	BD		00:00.0
2021 PO6072703711	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021 PO4905690090	LGE	4	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO6407949123	KU	6	30 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4297107241	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4295307104	F	4	45 BRN	SP	CRE		V		00:00.0
2021 PO4388007920	KU	6	30 BRN	SP	CRE		V		00:00.0
2021 PO4368008156	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4380207995	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4327208127	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4374708124	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4894890068	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021 PO4904490084	LGE	5	35 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO4888290175	LGE	3	45 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO0131233632	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5027689041	LGE	4	40 ACE	AL	CCA		V		00:00.0
2021 PO6411249207	KU	6	35 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO6065203894	KU	5	35 BRN	SP	CRE	ED	TD		00:00.0
2021 PO6059203815A	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6059203815	KU	3	45 BRN	SP	CRE	HH,ID,IP	VX	RP1	00:00.0
2021 PO5023189017	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO0100834519	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0244734561	KU	4	40 BRO	SP	CRE	HH,ID	BX	PX	00:00.0
2021 PO6412949145	KU	1	70 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6436048991	KU	1	70 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4891390811	LGE	4	40 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO2031566880	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO1968366448	KU	5	35 BRO	SP	CRE	ED,ID	BX	RP1	00:00.0
2021 PO4336207783	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4314807668	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4291907331	F	3	35 BRN	SP	CRE		V		00:00.0
2021 PO4322207848	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4308007711	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4287107246	F	5	55 BRN	SP	CRE		V		00:00.0
2021 PO4323107632	F	4	40 BRN	SP	CRE	HH,ID,RB	BX	RP1	00:00.0
2021 PO4307207486	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4330508014	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4307907262	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4299407298	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4309207901	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5020788980	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO7300903227	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO7294003141	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021 PO5020988953	LGE	3	45 ACE	SP	CCA		V		00:00.0

2021 PO5934721041	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4888090797	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5022589018	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO5025089047	LGE	4	30 ACE	SP	A	ED	V	00:00.0
2021 PO5025989045	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO488890169	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4888590177	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4887990188	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4886890206	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5940521011	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4898890840	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO6038503976	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6045203924	F	3	50 BRN	SP	CRE		V	00:00.0
2021 PO5024789078	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5025689053	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5028989094	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4885790224	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4884990239	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4884490247	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO6076204745	F	2	45 BRN	SP	CRE		V	00:00.0
2021 PO6082804674	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO6078204703	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO6075804743	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO1940966017	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO1914265596	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4884190262	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4883990269	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4884290283	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO4884590299	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO4908490698	LGE	UNK	45 BRN	SP	CRE		V	00:00.0
2021 PO6456148819	KU	1	70 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO1891565221	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO1900465139	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5027689070	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO4882490366	LGE	3	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5029289079	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5029289074	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5031789075	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO0232935059	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4885090352	F	4	35 BRO	SP	A		V	00:00.0
2021 PO5918416124	LGE	1	60 BRO	SP	CCA		V	00:00.0
2021 PO5881716011	LGE	2	50 BRO	SP	CCA		V	00:00.0
2021 PO6031704028	KU	3	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO5858115786	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO5856115911	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5856115911-A	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6048050978	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO6338397232	F	4	40 UNK	SP	CRE		V	00:00.0
2021 PO9785023434	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5005299306	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5034899103	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5070498972	KU	4	40 BRN	SP	CRE	ED	BD	00:00.0
2021 PO5098698471	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO5012597706	KU	4	40 XXX	SP	S		V	00:00.0

2021	PO5009598045	F	5	35 XXX	SP	CRE			V			00:00.0	
2021	PO5103898602	F	4	40 XXX	SP	P			V			00:00.0	
2021	PO5112398813	KU	4	40 BRN	SP	CRE		ED			TD	00:00.0	
2021	PO5116798924	KU	4	40 BRN	SP	CRE		ED			TD	00:00.0	
2021	PO9938722768	KU	4	40 BRO	SP	CRE		ED,ID			TD	00:00.0	
2021	PO5127099180	KU	4	40 BRN	SP	CRE		ED			TD	00:00.0	
2021	PO5137599437	KU	3	45 BRN	SP	CRE		ED,SRC			TD	00:00.0	
2021	PO5086497960	F	4	40 XXX	SP	P					V	00:00.0	
2021	PO5090498136	KU	3	45 XXX	SP	S					V	00:00.0	
2021	PO4976798114	KU	5	35 XXX	SP	CRE					V	00:00.0	
2021	PO4980298143	F	2	45 XXX	SP	CRE					V	00:00.0	
2021	PO5050297911A	KU	3	40 XXX	SP	P		ED,ID			BD	00:00.0	
2021	PO5050297911	F	4	40 XXX	SP	CRE					V	00:00.0	
2021	PO5082197797	F	5	35 XXX	SP	CRE					V	00:00.0	
2021	PO5082497666	KU	4	40 XXX	SP	S		ED			T	00:00.0	
2021	PO5099697736	F	3	40 XXX	SP	P		ED,ID,IP			BX	PX	00:00.0
2021	PO5117697672	F	5	35 XXX	SP	CRE					V	00:00.0	
2021	PO5134697620	F	4	40 XXX	SP	P					V	00:00.0	
2021	PO5147597581	F	4	40 XXX	SP	CRE					V	00:00.0	
2021	PO5309502330	KU	2	50 XXX	SP	S					V	00:00.0	
2021	PO5288201558	KU	2	50 XXX	SP	S					V	00:00.0	
2021	PO5284101428	KU	2	60 XXX	SP	S					V	00:00.0	
2021	PO5244401630	KU	1	55 XXX	SP	S					V	00:00.0	
2021	PO1459852949	KU	6	30 XXX	SP	CRE					V	00:00.0	
2021	PO9970322844	KU	5	35 BRO	SP	CRE		HH,ID			BX	RP2	00:00.0
2021	PO9975722679	KU	4	40 KOP	SP	CRE		ED,ID			TD	00:00.0	
2021	PO1063553626	KU	4	40 XXX	SP	CRE		ED,ID			TX	RR	00:00.0
2021	PO1083553238	KU	4	40 XXX	SP	CRE		ID			TD	00:00.0	
2021	PO5134701382	F	3	45 BRN	SP	CRE					V	00:00.0	
2021	PO5122001432	F	4	40 BRN	SP	CRE					V	00:00.0	
2021	PO5109201482	F	4	40 BRN	SP	CRE					V	00:00.0	
2021	PO5096501533	F	4	40 BRN	SP	CRE					V	00:00.0	
2021	PO5095501573	F	4	40 BRN	SP	CRE					V	00:00.0	
2021	PO5101001711	F	4	40 BRN	SP	CRE					V	00:00.0	
2021	PO5107601874	F	4	40 BRN	SP	CRE					V	00:00.0	
2021	PO0003622676	KU	4	40 KOP	SP	CRE		ED,ID			TD	00:00.0	
2021	PO2287075499	KU	5	35 BRN	SP	CRE		ED,ID			TD	00:00.0	
2021	PO2352580479	KU	4	40 BRN	SP	CRE		ED,ID,IP			TD	00:00.0	
2021	PO4848990439	LGE	3	50 BRO	SP	CCA					V	00:00.0	
2021	PO4850590437	LGE	3	50 BRO	SP	CCA					V	00:00.0	
2021	PO4852590438	LGE	1	50 BRO	SP	CCA					V	00:00.0	
2021	PO4854390438	LGE	3	50 BRO	SP	CCA					V	00:00.0	
2021	PO4856290439	LGE	3	55 BRO	SP	CCA					V	00:00.0	
2021	PO4858190540	LGE	1	50 BRO	SP	CCA					V	00:00.0	
2021	PO4885190313	LGE	H1	65 BRO	SP	P					V	00:00.0	
2021	PO4841590426	LGE	1	50 BRO	SP	CCA					V	00:00.0	
2021	PO4839890417	LGE	1	50 BRO	SP	CCA					V	00:00.0	
2021	PO9472620148	KU	4	40 BRN	SP	CRE		ED,ID			TD	00:00.0	
2021	PO2357680063	KU	4	40 BRN	SP	CRE		ED,ID,IP			TD	00:00.0	
2021	PO2362379805	KU	4	40 BRN	SP	CRE		ED,ID,IP			TD	00:00.0	
2021	PO2356479898	KU	6	30 BRN	SP	CCA					V	00:00.0	
2021	PO5226500625	F	2	45 XXX	SP	CRE		ED,ID,MD			BX	RP2	00:00.0
2021	PO5214401742	KU	1	60 XXX	SP	S					V	00:00.0	
2021	PO5198901794	KU	2	50 XXX	SP	S					V	00:00.0	

2021	PO5236801649	KU	1	55	XXX	SP	S			V	00:00.0	
2021	PO5209001761	KU	2	50	XXX	SP	S			V	00:00.0	
2021	PO5226101694A	KU	1	40	XXX	SP	P	ED,ID		BD	00:00.0	
2021	PO5226101694	KU	1	55	XXX	SP	S			V	00:00.0	
2021	PO5184801834	KU	1	55	XXX	SP	S			V	00:00.0	
2021	PO5189801823	KU	1	55	XXX	SP	S			V	00:00.0	
2021	PO5169801282	F	3	45	XXX	SP	P			V	00:00.0	
2021	PO5185701744	KU	3	45	XXX	SP	CRE	ED,ID		BD	00:00.0	
2021	PO5180501591	KU	3	45	XXX	SP	CRE	ED,HH,ID		BX	PX	00:00.0
2021	PO5181501619	KU	3	45	XXX	SP	S			V	00:00.0	
2021	PO5170401438	F	3	45	XXX	SP	CRE			V	00:00.0	
2021	PO5174501426	F	3	45	XXX	SP	CRE	ED,ID,IP		BX	PX	00:00.0
2021	PO5778000768	F	4	40	XXX	SP	P			V	00:00.0	
2021	PO5748400932	F	4	40	XXX	SP	CRE			V	00:00.0	
2021	PO5758900873	F	4	40	XXX	SP	CRE			V	00:00.0	
2021	PO5767000828	F	4	40	XXX	SP	CRE	ED,ID,IP,MD,RB		BX	RP3	00:00.0
2021	PO5735101007	F	4	40	XXX	SP	CRE			V	00:00.0	
2021	PO5716401116	F	4	40	XXX	SP	CRE			V	00:00.0	
2021	PO5725001065	F	4	40	XXX	SP	CRE	ED,ID,IP		BX	RP3	00:00.0
2021	PO5693001247	F	3	40	XXX	SP	CRE			V	00:00.0	
2021	PO5683901298	F	3	40	XXX	SP	CRE			V	00:00.0	
2021	PO5710701262	KU	4	40	XXX	SP	CRE	ED,ID		TD	00:00.0	
2021	PO5705901175	F	4	40	XXX	SP	CRE			V	00:00.0	
2021	PO5695603971	KU	5	35	XXX	SP	CCA			V	00:00.0	
2021	PO9448919865	KU	4	40	BRO	SP	CRE	ED,ID		TD	00:00.0	
2021	PO5226500070	KU	3	50	BRN	SP	CRE	ED		BD	00:00.0	
2021	PO5228700150	KU	ST	65	BRN	SP	CCA			V	00:00.0	
2021	PO5234600369	KU	ST	65	BRN	SP	CRE			V	00:00.0	
2021	PO4942588615	F	4	40	BRO	SP	A			V	00:00.0	
2021	PO6155818161	ODP	3	50	BRN	SP	CRE	ED,ID,IP		TD	00:00.0	
2021	PO6149918269	ODP	6	30	BRN	SP	CCA	ED,ID		TD	00:00.0	
2021	PO4944988623	LGE	4	40	BRO	SP	A	ED,ID,IP		TD	00:00.0	
2021	PO4943588618	LGE	4	40	BRO	SP	A	ED,ID,IP		TD	00:00.0	
2021	PO6644920238	ODP	6	30	BRO	SP	CCA			V	00:00.0	
2021	PO6643620446	ODP	4	45	BRO	SP	CCA			V	00:00.0	
2021	PO6809620281	ODP	6	30	UNK	SP	CCA			V	00:00.0	
2021	PO4941488612	LGE	3	45	BRO	SP	A	ED,ID		TD	00:00.0	
2021	PO4941288617	LGE	4	30	BRO	SP	CRE	ED,ID		TD	00:00.0	
2021	PO4766989288	LGE	4	30	ACE	SP	P	ED,ID		TD	00:00.0	
2021	PO4766389302	LGE	4	35	ACE	SP	P	ED,ID		TD	00:00.0	
2021	PO4942388600	LGE	4	35	BRO	SP	A	ED,ID		TD	00:00.0	
2021	PO6458499111	LGE	4	40	BRO	SP	A	ED,ID		TD	00:00.0	
2021	PO4940288608	LGE	4	40	BRO	SP	A	ED,ID,IP		TD	00:00.0	
2021	PO4770589338	LGE	4	35	ACE	SP	P	ED,ID		TD	00:00.0	
2021	PO4771389350	LGE	4	35	ACE	SP	P	ED,ID		TD	00:00.0	
2021	PO4941388602	LGE	4	35	BRO	SP	A	ED,ID		TD	00:00.0	
2021	PO6798920315	ODP	3	45	UNK	SP	P	ED,ID		TD	00:00.0	
2021	PO5981017608	ODP	3	45	BRN	SP	CCA			V	00:00.0	
2021	PO5943717558b	ODP	3	45	BRN	SP	CCA			V	00:00.0	
2021	PO5943717558a	ODP	3	45	BRN	SP	CCA			V	00:00.0	
2021	PO5917217004	ODP	4	40	BRN	SP	CCA			V	00:00.0	
2021	PO5882217930	ODP	6	30	BRN	SP	CRE	ED,ID,IP		TD	00:00.0	
2021	PO5874517628	ODP	3	45	BRN	SP	CCA			V	00:00.0	
2021	PO5913217286	ODP	4	40	BRN	SP	CCA			V	00:00.0	

2021 PO5908717511	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5878317368	ODP	5	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4939488606	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4938588603	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4938488606	LGE	5	25 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4937788601	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO6783220314	ODP	4	40 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO4769089336	LGE	4	35 ACE	SP	P	ED,EP,ID,RB	X PX	00:00.0
2021 PO6780720386	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO6767120242	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO6767020310	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6748220382	ODP	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5818317734	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4928088572	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6402699438	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4768189312	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4771589303	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4770189300	LGE	4	40 ACE	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4771189288	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4770789284	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4771189281	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4769489319	LGE	4	30 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4768389325	LGE	4	35 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO4931888617	LGE	4	40 BRO	SP	CCA	ED	T	00:00.0
2021 PO4932388599	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO6739920251	ODP	5	35 ACW	SP	CRE	ED,ID	TD	00:00.0
2021 PO4935888596	LGE	4	40 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO6729820332	F	4	40 ACW	SP	P		V	00:00.0
2021 PO6719720209	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6714120327	F	4	40 BRO	SP	P		V	00:00.0
2021 PO6693220328	ODP	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4934288594	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4934288590	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4933388590	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4937588493	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6522598209	LGE	1	50 BRO	SP	CCA		V	00:00.0
2021 PO4804089465	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO9090255877	KU	4	45 OTH	SP	CCA		V	00:00.0
2021 PO9070955848	KU	4	45 OTH	SP	CCA		V	00:00.0
2021 PO9048255960	KU	4	45 OTH	SP	CCA		V	00:00.0
2021 PO9110855904	KU	2	45 OTH	SP	CCA		V	00:00.0
2021 PO2899189517	KU	5	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO2819389193A	KU	6	30 XXX	SP	S		V	00:00.0
2021 PO9419356420	KU	5	35 OTH	SP	CCA		V	00:00.0
2021 PO9385556379	F	4	45 OTH	SP	CRE		V	00:00.0
2021 PO9375956431	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO0731736452	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO0721236527	ODP	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0715036707	ODP	4	45 BRN	SP	CCA	ED	T	00:00.0
2021 PO0651136407	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4764689066	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4945288763	LGE	4	40 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4763689069	LGE	4	30 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6623624553	ODP	6	35 UNK	SP	CRE		V	00:00.0

2021 PO6646524514	ODP	3	45 UNK	SP	S		V	00:00.0
2021 PO4761989079	LGE	4	35 ACE	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6667524475	ODP	6	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO6686024443	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO0672436460	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0650136328	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO0637036262	ODP	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO0628936182	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO9256058168	F	3	45 OTH	SP	CCA		V	00:00.0
2021 PO4347400667	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4345700747	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4341100642	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4341200861	F	4	40 XXX	SP	CRE	IP	V	00:00.0
2021 PO4357300465	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9528960199	F	3	50 OTH	SP	CRE		V	00:00.0
2021 PO9565160448	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO4465502107	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4205702473	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4443398096	KU	4	45 BRN	SP	CRE		V	00:00.0
2021 PO4467702168	KU	3	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO4468102188	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4524701679	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4453800919	F	4	40 XXX	SP	P		V	00:00.0
2021 PO4418200541	F	5	30 XXX	SP	P		V	00:00.0
2021 PO4412800369	F	5	30 XXX	SP	CRE		V	00:00.0
2021 PO4357701610	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO4366802087	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4375301656	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4362201652	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO4342201911	KU	4	40 BRN	SP	S		V	00:00.0
2021 PO4352001796	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5528292807	KU	3	40 XXX	SP	P		V	00:00.0
2021 PO5518192829	KU	3	40 XXX	SP	P		V	00:00.0
2021 PO9206458471	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO9233857713	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9225357661	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021 PO9241357269	KU	5	35 OTH	SP	CCA		V	00:00.0
2021 PO9245557383	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO9258858079	F	3	45 OTH	SP	CCA		V	00:00.0
2021 PO4360300436	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9517460462	F	3	55 OTH	SP	CRE		V	00:00.0
2021 PO6445998718	F	3	40 XXX	SP	P		V	00:00.0
2021 PO6573197923	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5117205815	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5087405930	KU	5	30 XXX	SP	S		V	00:00.0
2021 PO5077005903	KU	3	50 XXX	SP	S		V	00:00.0
2021 PO5074505903	KU	3	50 XXX	SP	S		V	00:00.0
2021 PO5538492807	KU	3	40 XXX	SP	P		V	00:00.0
2021 PO9303757219	F	2	45 OTH	SP	CCA		V	00:00.0
2021 PO4447501566	KU	2	50 BRN	SP	CRE	ID	BD	00:00.0
2021 PO4049106729	KU	3	40 BRN	SP	S		V	00:00.0
2021 PO4076304266	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO3994006320	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4865306595	F	3	45 BRN	SP	CCA		V	00:00.0

2021	PO4767907161	F	3	45 BRN	SP	CRE			V			00:00.0
2021	PO4707307462	KU	3	45 BRN	SP	CCA			V			00:00.0
2021	PO9329056624	F	2	45 OTH	SP	CCA			V			00:00.0
2021	PO9546060521	F	5	35 OTH	SP	CRE			V			00:00.0
2021	PO9582460234	F	5	30 OTH	SP	CRE			V			00:00.0
2021	PO4190503258	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO4235602974	F	3	45 XXX	SP	P			V			00:00.0
2021	PO4345001320	F	4	40 XXX	SP	CRE	ED,EP,ID,IP		BX		RP2	00:00.0
2021	PO4359401151	F	4	40 XXX	SP	CRE	ED,ID,IP,MD		BX		RP2	00:00.0
2021	PO4420101456	F	4	40 XXX	SP	CRE	ED,ID,MD		BX		RP1	00:00.0
2021	PO9260659157	F	2	45 OTH	SP	CCA			V			00:00.0
2021	PO9267059319	F	3	50 OTH	SP	CRE			V			00:00.0
2021	PO9180958730	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9211759417	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9189259488	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9196459007	F	5	35 OTH	SP	CRE			V			00:00.0
2021	PO9233859376	KU	6	30 OTH	SP	CRE	ED,ID,SRS		TD			00:00.0
2021	PO9153759456	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9175458977	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9170359469	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9170058557	KU	4	40 OTH	SP	CRE	ED,ID,SRS		TD			00:00.0
2021	PO9220759656	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9215959522	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9228359199	KU	5	35 OTH	SP	CRE	ID		BD			00:00.0
2021	PO4351100571	F	4	40 XXX	SP	CRE	ED,EP,ID,MD		BX		RP3	00:00.0
2021	PO4368700407	F	4	40 XXX	SP	CRE			V			00:00.0
2021	PO4372700324	F	6	30 XXX	SP	CRE			V			00:00.0
2021	PO9525060450	KU	6	30 OTH	SP	CCA			V			00:00.0
2021	PO9522660535	F	3	35 OTH	SP	CRE			V			00:00.0
2021	PO9522260244	F	3	50 OTH	SP	CRE			V			00:00.0
2021	PO9528460618	F	3	50 OTH	SP	CRE			V			00:00.0
2021	PO9502760372	F	3	50 OTH	SP	CRE			V			00:00.0
2021	PO9506660172	KU	5	35 OTH	SP	CRE	ED,ID,SRS		TD			00:00.0
2021	PO9508260332	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9507760536	F	6	30 OTH	SP	CRE			V			00:00.0
2021	PO9518360128	F	3	50 OTH	SP	CRE			V			00:00.0
2021	PO9566060342	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9589960016	F	4	40 OTH	SP	CRE			V			00:00.0
2021	PO9493360071	KU	4	40 OTH	SP	CRE	ED,ID,SRS		TD			00:00.0
2021	PO9530660302	F	2	50 OTH	SP	CRE			V			00:00.0
2021	PO4462001990	KU	3	45 BRN	SP	CRE	HH,ID,IP,RP		BX		PX	00:00.0
2021	PO4354101717	F	3	45 XXX	SP	CRE	ED,ID,IP,MD		BX		RP3	00:00.0
2021	PO4389201998	F	4	40 BRN	SP	CRE	HH,ID,IP		BX		RP2	00:00.0
2021	PO4376102049	F	4	40 BRN	SP	CRE			V			00:00.0
2021	PO4401001956	KU	3	45 BRN	SP	CRE			V			00:00.0
2021	PO4334502332	F	4	40 BRN	SP	CRE			V			00:00.0
2021	PO4347402260	KU	4	40 BRN	SP	CRE			V			00:00.0
2021	PO4307002493	KU	3	45 BRN	SP	CRE	ID,IP		BD			00:00.0
2021	PO4329401525	KU	4	30 XXX	SP	S			V			00:00.0
2021	PO9324456728	F	2	45 OTH	SP	CCA			V			00:00.0
2021	PO9316756900	F	2	45 OTH	SP	CCA			V			00:00.0
2021	PO93333456523	F	4	45 OTH	SP	CCA			V			00:00.0
2021	PO9305657448	F	4	30 OTH	SP	CRE			V			00:00.0
2021	PO9294457384	F	2	50 OTH	SP	CCA			V			00:00.0

2021	PO9287457497	F	2	50 OTH	SP	CCA		V	00:00.0
2021	PO9057557263	F	5	35 OTH	SP	CRE		V	00:00.0
2021	PO9154857952	F	5	35 OTH	SP	CRE		V	00:00.0
2021	PO9147757658	F	2	40 OTH	SP	CCA		V	00:00.0
2021	PO9185957561	F	5	30 OTH	SP	CRE		V	00:00.0
2021	PO9185757641	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9057857862	F	5	35 OTH	SP	CRE		V	00:00.0
2021	PO9086857667	F	4	40 OTH	SP	CCA		V	00:00.0
2021	PO9144857567	F	4	40 OTH	SP	P		V	00:00.0
2021	PO4338401960	KU	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4348301806	KU	4	40 BRN	SP	S		V	00:00.0
2021	PO9251558430	F	3	45 OTH	SP	CCA		V	00:00.0
2021	PO9260857321	F	5	30 OTH	SP	CRE		V	00:00.0
2021	PO9252457366	F	6	30 OTH	SP	CRE		V	00:00.0
2021	PO9245858757	F	2	45 OTH	SP	CCA		V	00:00.0
2021	PO9266657378	F	5	35 OTH	SP	CRE		V	00:00.0
2021	PO9257257442	F	5	35 OTH	SP	CRE		V	00:00.0
2021	PO9276657688	F	4	45 OTH	SP	CCA		V	00:00.0
2021	PO9272457779	F	2	45 OTH	SP	CCA		V	00:00.0
2021	PO9267957768	F	4	40 OTH	SP	CRE		V	00:00.0
2021	PO9250358158	F	4	35 OTH	SP	CRE		V	00:00.0
2021	PO9245358425	F	6	30 OTH	SP	CRE		V	00:00.0
2021	PO4399801620	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4396101679	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4381001730	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO6609217949	ODP	6	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8370022014	ODP	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021	PO8377122048A	ODP	6	30 BRO	SP	CRE	ED,ID,SRC	TD	00:00.0
2021	PO0390235463	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0392035412	ODP	5	30 BRN	SP	CRE	ID	TD	00:00.0
2021	PO8377122048	ODP	4	40 BRO	SP	CCA	ED,ID,SRS	TD	00:00.0
2021	PO8381722085	ODP	5	35 UNK	SP	CRE	ED,ID,IP,SRC	TD	00:00.0
2021	PO8481121925	ODP	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO6931519003	ODP	2	50 XXX	SP	CCA		V	00:00.0
2021	PO6905218962	ODP	5	35 XXX	SP	CCA		V	00:00.0
2021	PO6894518937	F	4	40 XXX	SP	A		V	00:00.0
2021	PO0391435628	ODP	4	40 BRN	SP	CRE	ID,IP	TD	00:00.0
2021	PO0396035575	ODP	6	30 BRN	SP	CRE	ID	TD	00:00.0
2021	PO0404535569	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021	PO9387525802	ODP	4	40 XXX	SP	S		V	00:00.0
2021	PO6876018771	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021	PO9342126001	ODP	4	45 XXX	SP	S		V	00:00.0
2021	PO9334725930	ODP	4	45 XXX	SP	S		V	00:00.0
2021	PO9335425812	F	4	40 XXX	SP	P		V	00:00.0
2021	PO8472822247	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021	PO846522494	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021	PO8456422691	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021	PO8383625283	ODP	4	40 UNK	SP	P	ID	BD	00:00.0
2021	PO6861818709	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO6775118437	ODP	4	40 XXX	SP	CCA		V	00:00.0
2021	PO8495525428	ODP	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021	PO8531425018	F	4	40 BRO	SP	CCA		V	00:00.0
2021	PO8545625382A	ODP	5	35 UNK	SP	P	ED,ID,IP,SRC	TD	00:00.0
2021	PO6767918498	ODP	4	40 XXX	SP	CCA		V	00:00.0



2021 PO6787618243	ODP	5	30 XXX	SP	CCA			V	00:00.0
2021 PO8534125405	ODP	5	35 BRO	SP	CRE			V	00:00.0
2021 PO8516125407	F	4	40 BRO	SP	CCA			V	00:00.0
2021 PO8477425411	ODP	4	40 UNK	SP	CRE	ID		BD	00:00.0
2021 PO8310821179	ODP	5	35 UNK	SP	CRE	ED,HH,ID,RB		X PX	00:00.0
2021 PO8310021001	ODP	4	40 UNK	SP	CRE	ED,ID,IP,SRC		TD	00:00.0
2021 PO8332621117	ODP	5	35 UNK	SP	CRE	ED,ID,SRC		TD	00:00.0
2021 PO8325521339	ODP	5	35 UNK	SP	CRE	ED,ID,SRC		TD	00:00.0
2021 PO8345321439	ODP	5	35 BRO	SP	CRE	ED,ID,SRC		TD	00:00.0
2021 PO8334421610	ODP	4	40 BRO	SP	CCA			V	00:00.0
2021 PO8287021604	F	4	40 UNK	SP	CRE			V	00:00.0
2021 PO4915988473	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021 PO4914488464	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021 PO7411142676	ODP	5	35 KOP	SP	CCA			V	00:00.0
2021 PO7404642666	ODP	6	30 KOP	SP	S	SRC		T	00:00.0
2021 PO7423642751	ODP	4	40 KOP	SP	CRE	ED		TD	00:00.0
2021 PO5499821451	KU	4	40 BRN	SP	CCA			V	00:00.0
2021 PO4912988456	LGE	4	40 BRO	SP	CRE	ID,IP		BD	00:00.0
2021 PO7847742791	ODP	4	40 BRO	SP	CRE	ID		BD	00:00.0
2021 PO4924689660	LGE	1	75 BRN	SP	CRE			V	00:00.0
2021 PO4926189657	LGE	1	80 BRN	SP	CRE			V	00:00.0
2021 PO4927689654	LGE	1	70 BRN	SP	CRE			V	00:00.0
2021 PO4929089651	LGE	1	70 BRN	SP	CRE			V	00:00.0
2021 PO4930589647	LGE	1	75 BRN	SP	CRE			V	00:00.0
2021 PO4932089644	LGE	4	40 BRN	SP	CRE			V	00:00.0
2021 PO4932089645	LGE	1	75 BRN	SP	A			V	00:00.0
2021 PO4933489641	LGE	1	75 BRN	SP	CRE			V	00:00.0
2021 PO6446609408	LGE	2	55 BRN	SP	CCA			V	00:00.0
2021 PO4938989630	LGE	1	75 BRN	SP	P			V	00:00.0
2021 PO4939889628	LGE	1	75 BRN	SP	CRE			V	00:00.0
2021 PO5503121415	KU	4	40 BRN	SP	CCA			V	00:00.0
2021 PO5529919538	KU	3	45 BRN	SP	CCA			V	00:00.0
2021 PO7834243144	ODP	6	30 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO6213997476	LGE	4	35 BRO	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO4910888448-A	LGE	5	35 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO7397342683	ODP	4	40 KOP	SP	CRE	ED		T	00:00.0
2021 PO5385920692	KU	2	50 BRN	SP	CCA			V	00:00.0
2021 PO5373120598	KU	2	50 BRN	SP	S			BD	00:00.0
2021 PO5357720495	KU	4	45 BRN	SP	CRE	ID		BD	00:00.0
2021 PO5379020644	KU	2	50 BRN	SP	CCA			V	00:00.0
2021 PO7824643664	ODP	5	35 BRO	SP	CRE	ED,ID,IP		BD	00:00.0
2021 PO7827743585	ODP	6	30 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO8365243707	ODP	4	40 XXX	SP	CRE	ED,ID		TD	00:00.0
2021 PO8347143731	ODP	4	40 XXX	SP	S			V	00:00.0
2021 PO8358143891	ODP	6	30 XXX	SP	S	ED		T	00:00.0
2021 PO4910888448	LGE	3	45 BRO	SP	CCA			V	00:00.0
2021 PO4911488450	LGE	4	40 BRO	SP	CCA			V	00:00.0
2021 PO4912188453	LGE	3	45 BRO	SP	A	ID,IP		BD	00:00.0
2021 PO7838243374	ODP	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO7838243292	ODP	6	30 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO7836743467	ODP	6	30 BRO	SP	CCA			V	00:00.0
2021 PO9964033561	ODP	4	40 KOP	SP	CCA			V	00:00.0
2021 PO9997733538	ODP	5	35 KOP	SP	CRE			V	00:00.0
2021 PO7834243559A	ODP	6	30 BRO	SP	CCA			V	00:00.0

2021 PO7852643419	ODP	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7834243559	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5538919567	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5536219527	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5531919460	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO6440400929	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4934088782	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO5543419637	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO7856743780	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7855243676	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021 PO7862943590	ODP	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5549119715	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO5545619779	KU	3	45 KOP	SP	CCA		V	00:00.0
2021 PO5537719656	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO5365620686	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO7770342787	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7760642759	ODP	4	40 KOP	SP	CRE		BD	00:00.0
2021 PO7776442627	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7779842765	ODP	4	30 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7781742828	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7783443251	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7714443467	ODP	4	45 BRN	SP	CCA	ED	T	00:00.0
2021 PO7727943907	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO5517120363	KU	4	40 BRN	SP	P		V	00:00.0
2021 PO5513920310	F	4	40 CPT	SP	P		V	00:00.0
2021 PO4929588666	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5521220211	F	4	40 OTH	SP	CCA		V	00:00.0
2021 PO7740743550	ODP	5	45 BRO	SP	CCA		V	00:00.0
2021 PO7744143766	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO7729943714	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7734143730	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6926241267	ODP	2	55 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6925241908	ODP	6	30 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7763243313	ODP	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7777143358	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7772543483	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4725890003	LGE	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4725290009	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4868689941	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4930588686	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7723244031	ODP	4	45 BRN	SP	CCA	ED	T	00:00.0
2021 PO7742544038	ODP	5	35 BRN	SP	CCA		V	00:00.0
2021 PO7748744118	ODP	4	45 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7738544391	ODP	4	40 BRN	SP	CRE	ED,ID	TX	RR 00:00.0
2021 PO7775844515	ODP	5	30 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7779844318	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7797144380	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4943788920	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021 PO4904989930	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6115612308	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4905989908	LGE	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7680041176	ODP	5	35 KOP	SP	CCA		V	00:00.0
2021 PO7680141597	ODP	4	40 KOP	SP	CCA	ID	BD	00:00.0
2021 PO7680241532	ODP	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0

2021 PO7686741463	ODP	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4902889934	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4903389924	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO6112912200	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4904789900	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4905689885	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4898689860	LGE	H3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7673641397	ODP	6	30 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7659541463	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7655541449	ODP	6	30 KOP	SP	CRE		V	00:00.0
2021 PO7640941399A	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7640941399	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7626441348	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7632041186	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7627741046	ODP	5	30 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7646741239	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7673041162	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7668141197	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7662241248	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO4914489899	LGE	1	65 BRN	ST	CCA		V	00:00.0
2021 PO4912389893	LGE	1	70 BRN	ST	CCA		V	00:00.0
2021 PO4910389886	LGE	1	65 BRN	ST	CCA		V	00:00.0
2021 PO4909389883	LGE	4	40 BRN	ST	CCA		V	00:00.0
2021 PO4908389879	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4906389872	LGE	1	65 BRN	ST	CCA		V	00:00.0
2021 PO4903889862	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4901389852	LGE	1	70 BRN	ST	P		V	00:00.0
2021 PO4899189843	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4896989834	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4894889825	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4892689815	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4890489806	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4888389797	LGE	1	70 BRN	ST	P		V	00:00.0
2021 PO4886489788	LGE	1	65 BRN	ST	P		V	00:00.0
2021 PO4935188760	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4932288716	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4704189690	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO5860224041	F	4	40 OTH	SP	P		V	00:00.0
2021 PO5873424246	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO5840224371	F	4	40 OTH	SP	P	ED,ID	BX	RP3 00:00.0
2021 PO5534621516	KU	2	50 OTH	SP	CCA		V	00:00.0
2021 PO5827924011	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0
2021 PO5546718515	KU	5	35 OTH	SP	CCA		V	00:00.0
2021 PO5543318579	KU	5	35 OTH	SP	CRE	ED,ID,SR	TD	00:00.0
2021 PO5536818456	KU	5	35 OTH	SP	CRE	ED,HH,ID,RB	X	PX 00:00.0
2021 PO5544718460	KU	5	35 OTH	SP	CCA		V	00:00.0
2021 PO5887324651	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO4796989102	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4796389088	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4795689076	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4794589113	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4793889100	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO7897046018	ODP	6	30 BRN	SP	CRE		V	00:00.0
2021 PO7882746045	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0

2021 PO7895846074	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7915646117	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7919846089	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7936546134	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4792589065	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4787189101	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4787689103	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO8407944689	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO8377044514	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO4787689121	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4788489133	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4789289136	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4790589107	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4790489141	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4792189113	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4791289144	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4792489148	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4793289152	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4794089120	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021 PO7872455551	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8351344376	F	4	40 OTH	SP	P		V	00:00.0
2021 PO8317344202	F	4	40 OTH	SP	P		V	00:00.0
2021 PO7884455648	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7883255777	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7890355276	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7910155336	ODP	5	35 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO7936355231	ODP	3	50 BRN	SP	CCA		V	00:00.0
2021 PO7955155347	ODP	2	60 BRN	SP	CCA		V	00:00.0
2021 PO4794489156	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4795389125	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4796689131	LGE	4	30 BRN	SP	P		V	00:00.0
2021 PO4795289160	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4796989166	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4796389164	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4797989136	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO5608021499	KU	3	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO5607221493	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8292144188	F	4	40 OTH	SP	P		V	00:00.0
2021 PO7505348722	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO7519948480	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO5580121325	KU	2	45 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5582921296	KU	4	45 KOP	SP	CCA		T	00:00.0
2021 PO4799089140	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7985256060	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8003556052	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7976855497	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8001055663	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8024755818	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8031555900	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO8044855960	ODP	3	50 BRN	SP	CCA		V	00:00.0
2021 PO8088844408	ODP	4	45 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4797889170	LGE	4	35 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4799189176	LGE	4	35 BRN	SP	CRE	HH,ID,IP	BX	00:00.0
2021 PO8094644481	ODP	5	35 BRN	SP	CRE		V	00:00.0

2021	PO5591921267	KU	5	35 BRN	SP	CCA			V		00:00.0
2021	PO8105244514	ODP	4	40 BRN	SP	CRE	ED,ID		BD		00:00.0
2021	PO8105044571	ODP	6	30 BRN	SP	CRE	ED,ID		TD		00:00.0
2021	PO8130344649	ODP	5	45 BRN	SP	CRE	ED,ID,IP		BD		00:00.0
2021	PO8122744562	ODP	4	45 BRN	SP	CRE	ED,ID,IP		BD		00:00.0
2021	PO8116944356	ODP	5	35 BRN	SP	CRE	ED,ID,IP		BD		00:00.0
2021	PO8062556078	ODP	3	45 BRN	SP	CCA			V		00:00.0
2021	PO8064856091	ODP	3	45 BRN	SP	CCA			V		00:00.0
2021	PO8078956185	ODP	3	50 BRN	SP	CCA			V		00:00.0
2021	PO8097456322	ODP	3	50 BRN	SP	CCA			V		00:00.0
2021	PO4802189161	LGE	4	35 BRN	SP	CRE			V		00:00.0
2021	PO4801489156	LGE	4	35 BRN	SP	CRE			V		00:00.0
2021	PO4800689151	LGE	4	35 BRN	SP	CRE	ED,ID		BD		00:00.0
2021	PO4802989167	LGE	4	35 BRN	SP	P	ED,ID		BD		00:00.0
2021	PO4801589189	LGE	4	35 BRN	SP	CRE	ED,ID		BD		00:00.0
2021	PO7956346398	ODP	6	30 BRN	SP	CCA			V		00:00.0
2021	PO6948153804	ODP	6	30 KOP	SP	CRE	ED,ID		TD		00:00.0
2021	PO7001753924	ODP	6	30 KOP	SP	CRE	ED,ID		TD		00:00.0
2021	PO732855662	ODP	6	30 KOP	SP	CCA			T		00:00.0
2021	PO4924388570	LGE	3	50 BRO	SP	CRE	ED,HH,ID,IP,RB		X	RP1	00:00.0
2021	PO4925088582	LGE	3	50 BRO	SP	CRE	ED,ID,IP		TD		00:00.0
2021	PO4942488901	LGE	1	60 BRO	SP	CCA			V		00:00.0
2021	PO7420850326	ODP	6	30 KOP	SP	CCA			V		00:00.0
2021	PO7477450671A	ODP	5	35 KOP	SP	S			V		00:00.0
2021	PO7499250547	ODP	4	40 KOP	SP	CRE	ED		TD		00:00.0
2021	PO7552050577	ODP	6	30 KOP	SP	CCA	ED,SRS		TD		00:00.0
2021	PO4805989076	F	4	40 ACE	SP	CRE			V		00:00.0
2021	PO4807289081	F	4	45 ACE	SP	CRE			V		00:00.0
2021	PO4723689749	F	4	40 ACE	SP	CRE			V		00:00.0
2021	PV4721989742	F	4	40 ACE	SP	P			V		00:00.0
2021	PO4721389737	F	4	40 ACE	SP	CRE			V		00:00.0
2021	PO4708989674	LGE	5	25 ACE	SP	CRE	ED,ID,IP		TD		00:00.0
2021	PO4952589880	LGE	3	45 BRN	SP	P	ED,ID		BD		00:00.0
2021	PO4954089865	LGE	3	50 BRN	SP	CCA			V		00:00.0
2021	PO4955589851	LGE	3	45 BRN	SP	CCA			V		00:00.0
2021	PO4957189836	LGE	3	45 BRN	SP	CCA			V		00:00.0
2021	PO4958989822	LGE	3	45 BRN	SP	P	ED,ID		BD		00:00.0
2021	PO4962489814	LGE	4	30 BRN	SP	P	ED,ID		BD		00:00.0
2021	PO8222744514	ODP	5	45 BRN	SP	CCA			V		00:00.0
2021	PO8230644480	F	2	50 BRN	SP	CCA			V		00:00.0
2021	PO8237444360	ODP	6	35 BRN	SP	CCA			V		00:00.0
2021	PO5668521388	KU	3	45 BRN	SP	CCA			V		00:00.0
2021	PO5675521303	KU	2	55 BRN	SP	CCA			V		00:00.0
2021	PO3922396120	F	3	40 BRN	SP	CRE			V		00:00.0
2021	PO3934496253	KU	4	45 BRN	SP	S			V		00:00.0
2021	PO3929096274	KU	8	45 BRN	SP	CRE			V		00:00.0
2021	PO3934696449	KU	8	45 BRN	SP	CRE			V		00:00.0
2021	PO4764590963	LGE	4	30 BRO	SP	A	ED,ID,IP		TD		00:00.0
2021	PO4766190961	LGE	3	45 BRO	SP	CCA			V		00:00.0
2021	PO5843300962	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO5839600899	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO5822000859	F	4	40 XXX	SP	CRE			V		00:00.0
2021	PO5834400792	F	3	40 XXX	SP	CRE			V		00:00.0
2021	PO5831900636	F	4	40 XXX	SP	P			V		00:00.0

2021	PO5830300510	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO5832600530	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO5714199221	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO5698799312	F	3	45 XXX	SP	P		V			00:00.0
2021	PO5698099354	F	3	45 XXX	SP	P		V			00:00.0
2021	PO5806698047	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO5832598209	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO3934385050	LGE	1	55 ACE	SP	CRE	ED,HH,ID	TX		RR	00:00.0
2021	PO4233888161	LGE	3	45 BRN	SP	CRE	ED,ID,MD	BD			00:00.0
2021	PO6972347606	KU	6	30 XXX	SP	CRE	ED,ID	X		PX	00:00.0
2021	PO4484487784	LGE	4	40 BRN	SP	P	ED	VX		RP1	00:00.0
2021	PO5888402314	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO5886602296	KU	6	30 XXX	SP	S		V			00:00.0
2021	PO5880602263	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO5882802178	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO4459586091	LGE	3	45 BRN	SP	P		V			00:00.0
2021	PO4507298573	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4223988221	LGE	1	50 BRN	SP	A	ID,IP	BD			00:00.0
2021	PO7043747342	KU	5	35 XXX	SP	CRE	ID	TD			00:00.0
2021	PO7043947424	KU	5	35 XXX	SP	CRE	ID	TD			00:00.0
2021	PO7044047526	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0
2021	PO7247747262	KU	6	30 UNK	SP	CRE	ED,ID	TD			00:00.0
2021	PO4455186106	LGE	3	45 BRN	SP	A	ED,ID	BD			00:00.0
2021	PO4456586102	LGE	3	45 BRN	SP	A	ED,ID	BD			00:00.0
2021	PO6563748589	KU	6	30 BRN	SP	CRE	ED,ID	TD			00:00.0
2021	PO4329486967	LGE	4	35 ACE	SP	CRE		V			00:00.0
2021	PO7254547519	KU	4	40 UNK	SP	CRE	ID	BD			00:00.0
2021	PO7284347919	KU	6	30 UNK	SP	CRE	ID	BD			00:00.0
2021	PO7308847970	KU	3	45 BRO	SP	CCA		V			00:00.0
2021	PO5917790741	F	3	45 XXX	SP	P		V			00:00.0
2021	PO5916890720	KU	3	40 XXX	SP	P		V			00:00.0
2021	PO5902690809	F	2	45 XXX	SP	P		V			00:00.0
2021	PO5896201766	KU	4	40 XXX	SP	CRE	ED,ID	BD			00:00.0
2021	PO5904601715	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO5917601635	F	3	40 XXX	SP	CRE		V			00:00.0
2021	PO5938401583	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO5947301626	F	4	40 XXX	SP	CRE		V			00:00.0
2021	PO7300148002	KU	2	45 UNK	SP	CRE	ED,ID	TD			00:00.0
2021	PO6791749856	KU	4	40 BRN	SP	CRE		BD			00:00.0
2021	PO6534148694	F	5	35 BRN	SP	A		V			00:00.0
2021	PO6534748747	KU	1	75 BRN	DF	CRE		V			00:00.0
2021	PO6523648829	KU	2	45 BRN	SP	CRE	ED,ID,IP	BD			00:00.0
2021	PO7034347648	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0
2021	PO7044347645	KU	4	40 XXX	SP	CRE	ID,IP	BD			00:00.0
2021	PO4267186707	LGE	3	55 ACE	SP	CCA		V			00:00.0
2021	PO4263186711	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021	PO4260586716	LGE	4	30 ACE	SP	CCA		V			00:00.0
2021	PO4260686709	LGE	4	40 ACE	SP	CCA		V			00:00.0
2021	PO4260086672	LGE	3	25 ACE	SP	CRE		V			00:00.0
2021	PO4260486667	LGE	3	75 ACE	SP	CCA		V			00:00.0
2021	PO4478998158	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021	PO4465398193	F	3	45 BRO	SP	CRE	ED	BD			00:00.0
2021	PO4253088029	LGE	4	30 BRN	SP	CRE	ED,ID	BD			00:00.0
2021	PO4253288024	LGE	4	35 BRN	SP	CCA		V			00:00.0

2021 PO4253688014	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7950989262	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO8033388974	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4253588009	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4253287996	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4255787877	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4258488008	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4257788009	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4257188021	LGE	4	45 BRN	SP	CRE		V	00:00.0
2021 PO4256888019	LGE	4	45 BRN	SP	CRE		V	00:00.0
2021 PO8032488650	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO8030088263	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4939991473	LGE	4	35 BRN	SP	A	ED,EP,ID,MD	BD	00:00.0
2021 PO4941591429	LGE	3	45 BRN	SP	CRE	ED,HH,ID,IP	VX	RP1 00:00.0
2021 PO4333387015	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4333687020	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4333987024	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4335187040	LGE	4	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4334787043	LGE	4	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4334887069	LGE	1	50 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4335687063	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7333947710	F	4	40 UNK	SP	P		V	00:00.0
2021 PO4454098227	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO8042087675	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7321248274	KU	4	45 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7294348146	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7306448048	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO7302748131	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6723649106	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6721949153	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6737749094	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO6712249159	KU	5	35 BRN	SP	CRE	ED	BD	00:00.0
2021 PO6702849164 A	F	5	30 BRN	SP	CRE		V	00:00.0
2021 PO6444547795	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6702849164	KU	5	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO5165084506	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO8847158999	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5161284474	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5159384456	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5157984463	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5156184473	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5151484489	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5147484503	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4372985233	LGE	3	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4036499077	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4232088129	LGE	3	55 BRN	SP	CCA		V	00:00.0
2021 PO4040499155	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4035999104	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4030899096	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4041699196	KU	5	35 BRN	SP	CCA		V	00:00.0
2021 PO4029399059	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6804449735	KU	4	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6813349728	KU	4	45 BRN	SP	CRE		BD	00:00.0
2021 PO6823249719	KU	4	45 BRN	SP	CRE	ED	TD	00:00.0

2021 PO6834349709	KU	4	50 BRN	SP	CRE	ED	TD		00:00.0
2021 PO7045347889	KU	4	40 XXX	SP	CRE	ID,IP	TD		00:00.0
2021 PO7043648044	KU	4	40 XXX	SP	CRE	HH,ID	X	PX	00:00.0
2021 PO7043848117	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO7024247944	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO7001647942	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5099685039	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5098485055	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5096985069	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO5094385089	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO7646547710	KU	5	35 UNK	SP	CRE	ID	BD		00:00.0
2021 PO5106885301	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5109085310	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5111585310	LGE	4	30 BRN	SP	CRE		V		00:00.0
2021 PO5111185318	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO8262466642	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021 PO7015847654	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021 PO7013747722	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO6489449029	F	5	40 BRN	SP	A		V		00:00.0
2021 PO6484948971	KU	6	30 BRN	SP	CRE		V		00:00.0
2021 PO6491949069	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4918791379	LGE	3	50 BRN	SP	CRE		V		00:00.0
2021 PO4951391482	LGE	4	30 BRN	SP	A	ED	B		00:00.0
2021 PO4213088177	LGE	4	30 BRN	SP	A		V		00:00.0
2021 PO5107485314	LGE	3	45 BRN	SP	CRE		V		00:00.0
2021 PO5109985338	LGE	3	45 BRN	SP	CRE		V		00:00.0
2021 PO5109185357	LGE	3	45 BRN	SP	CRE		V		00:00.0
2021 PO5108285376	LGE	3	45 BRN	SP	CRE		V		00:00.0
2021 PO6672849306A	KU	6	30 BRN	SP	CRE	ED	TD		00:00.0
2021 PO6677749136	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6672849306	KU	4	40 BRN	SP	CRE		BD		00:00.0
2021 PO6670649204	KU	4	40 BRN	SP	CRE	ED	TD		00:00.0
2021 PO6652549081	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6445547726	KU	6	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6449247668	KU	4	40 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO3693897053A	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3911296328	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO3846196651	F	5	35 BRN	SP	CRE		V		00:00.0
2021 PO3897396371	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO3693897053	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO7627547763	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO4381485222	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4380585214	LGE	4	35 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4379885209	LGE	4	35 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4386685696	LGE	4	30 BRN	SP	CRE		V		00:00.0
2021 PO4374585793	LGE	4	40 BRN	SP	A		V		00:00.0
2021 PO4375485799	LGE	4	40 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4376285806	LGE	3	40 BRN	SP	CCA		V		00:00.0
2021 PO4378685790	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4383385694	LGE	4	35 BRN	SP	A	ED,ID	TD		00:00.0
2021 PO7649947840	KU	3	50 BRO	SP	CRE	ID	BD		00:00.0
2021 PO7038647213	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO7633847933	KU	3	45 BRO	SP	CRE	ID	BD		00:00.0
2021 PO6650749017	F	4	40 BRN	SP	CRE		V		00:00.0



2021 PO7369848414	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO3873404130	F	2	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0
2021 PO6635949096	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO3872103840	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3870203688	F	3	45 BRN	SP	CCA		V		00:00.0
2021 PO3873203974	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO6021095196	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6007295117	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5994895094	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5982895072	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5970195049	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5956495022	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5924794963	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5909794935	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5940494993	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO9967180446	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0025180464	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO6972547689	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO6966147587	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO6172050547	KU	4	45 BRO	SP	S		V		00:00.0
2021 PO6965847488	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO4742189874	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO6654749430	KU	5	35 BRN	SP	CRE	ED	TD		00:00.0
2021 PO6658649320	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6658649320	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4741289863	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4490211448	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4740989866	LGE	4	40 BRN	SP	A	ED,ID	TD		00:00.0
2021 PO4739989860	LGE	1	50 BRN	SP	CCA		V		00:00.0
2021 PO6478747679	KU	6	30 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4466811351	LGE	3	50 BRN	SP	CCA		V		00:00.0
2021 PO7523548040	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7489648136	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7340547840	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO8302186676	KU	5	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO7343447899	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO7502448099	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO4008098803	KU	3	45 BRN	SP	S		V		00:00.0
2021 PO4472085814	LGE	1	65 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO4462885816-A	LGE	5	35 BRN	SP	A	ED,ID,RB	X	RP1	00:00.0
2021 PO4743289880	LGE	UNK	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO4744889885	LGE	3	45 BRN	SP	CCA	ED	T		00:00.0
2021 PO4743089889-a	LGE	4	25 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4743089889	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4743589896	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4459785823	LGE	1	75 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO6478247800	KU	4	40 BRN	SP	CCA		V		00:00.0
2021 PO6491347793	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO3893500289	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3882800342	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3868400410	KU	3	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO3931700103	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3907800219	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3944500043	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	RP1	00:00.0

2021 PO3918800166	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4746989887	LGE	3	45 BRN	SP	CCA	ED,ID	BD	00:00.0
2021 PO4550911632	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7395148407	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7394448360	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7387548376	KU	2	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7384148384	KU	2	45 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO4753989913	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4380885741	LGE	6	25 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4379585773	LGE	4	30 BRN	SP	A	ED,ID,MD,SRS	TD	00:00.0
2021 PO4377485798	LGE	5	25 BRN	SP	CRE	ED,HH,ID,IP,MD,RB	VX PX	00:00.0
2021 PO4376385800	LGE	5	25 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO3839604192	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3797504029	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX PX	00:00.0
2021 PO7118048843	KU	3	50 UNK	SP	CRE	ID	BD	00:00.0
2021 PO7035240942	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7051040761	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7104341133	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7079541624	KU	4	45 BRN	SP	CRE	ED	BD	00:00.0
2021 PO4462685826	LGE	1	85 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO6799741516	F	4	40 BRO	SP	P	ED,ID	V	00:00.0
2021 PO6812341781	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6803541079	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6782041748	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO6776841536	F	4	40 BRO	SP	P	ED	V	00:00.0
2021 PO70041746900	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO5671821471	KU	3	50 BRN	SP	CCA		V	00:00.0
2021 PO5672321360	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5668621398	KU	2	45 BRN	SP	CCA		V	00:00.0
2021 PO5670121430	KU	CO	90 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5545822388	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4150404498	F	3	40 CPT	SP	P		V	00:00.0
2021 PO5434503148	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5433603253	F	4	50 BRN	SP	CCA		V	00:00.0
2021 PO5432903322	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5363003916	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5369204081	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4133306176	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4143906330	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5516904158	F	3	35 BRN	SP	CRE		V	00:00.0
2021 PO5520302407	KU	4	40 XXX	SP	P		V	00:00.0
2021 PO5496102516	KU	4	40 XXX	SP	P		V	00:00.0
2021 PO4086306268	F	3	40 BRN	SP	CCA		V	00:00.0
2021 PO4109706269	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4130706408	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4135906248	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5454501845	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5471702177	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5442502685	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5448502687	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4143204310	F	4	40 XXX	SP	CRE	ED,ID,MD	V	00:00.0
2021 PO4139404211	F	4	40 XXX	SP	CRE	ED,ID,MD	V	00:00.0
2021 PO5386303040	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4100506158	F	4	40 BRN	SP	CRE		V	00:00.0

2021 PO4112606218	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5439902611	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5517902013	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5513601966	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5521901860	F	4	40 XXX	SP	CRE	V	00:00.0
2021 PO5535801935	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5499702052	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5480502139	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5490802095	F	4	40 XXX	SP	P	V	00:00.0
2021 PO5372103607	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5506102022	F	3	40 XXX	SP	P	V	00:00.0
2021 PO5383203354	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO5387503280	F	4	40 BRN	SP	CRE	V	00:00.0
2021 PO3973705669	F	4	40 CPT	SP	P	V	00:00.0
2021 PO3975305668	F	3	40 CPT	SP	P	V	00:00.0
2021 PO4327686961	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4328386950	F	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4314786961	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4313786969	F	4	30 ACE	SP	A	V	00:00.0
2021 PO4312886976	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4315587129	F	4	35 BRO	SP	A	V	00:00.0
2021 PO4317087148	F	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4307586907	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4319687113	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4304586996	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4305787070	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO0182582927	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4305787081	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4306287077	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4306987072	F	4	30 ACE	SP	P	V	00:00.0
2021 PO4307887064	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4308687059	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4307586887	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4309086896	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4308186903	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4317987159	F	4	30 BRO	SP	A	V	00:00.0
2021 PO4303186985	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4309586936	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4311286923	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4310286930	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO4315187196	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4307487021	F	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4303986979	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4316687185	F	4	30 BRO	SP	A	V	00:00.0
2021 PO4315987190	F	4	35 BRO	SP	A	V	00:00.0
2021 PO4314387203	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4306186962	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4326687107	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4317387179	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4313286910	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4318887168	F	4	35 BRO	SP	A	V	00:00.0
2021 PO4306986957	F	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4305086971	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4327587016	LGE	4	40 BRO	SP	CCA	V	00:00.0

2021 PO4326987009	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4308786951	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4326487010	LGE	4	35 BRO	SP	CCA	V	00:00.0
2021 PO4326987059	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4309986998	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4310786992	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4312186916	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4316486857	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4309886871	LGE	UNK	35 ACE	SP	CCA	V	00:00.0
2021 PO4305086926	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4303886935	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4303186940	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4302486945	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4301786951	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4305587007	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4300686746	LGE	2	50 BRO	SP	CCA	V	00:00.0
2021 PO4318087126	F	4	35 BRO	SP	A	V	00:00.0
2021 PO4306286937	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4310186883	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4301587018	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4297687099	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4318787120	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4320987103	F	4	30 BRO	SP	CRE	V	00:00.0
2021 PO4302486925	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4281987118	LGE	2	55 ACE	SP	CCA	V	00:00.0
2021 PO4294887103	LGE	4	40 ACE	SP	CCA	V	00:00.0
2021 PO4294586817	LGE	3	50 BRO	SP	CCA	V	00:00.0
2021 PV4287387112	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4321687097	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4322287092	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4323187086	F	4	30 BRO	SP	A	V	00:00.0
2021 PO4323487084	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4299386912	LGE	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4307386929	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4310586904	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4309886910	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4309386914	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4308886917	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4308286922	LGE	3	45 ACE	SP	CCA	V	00:00.0
2021 PO4315687049	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4314987055	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4317087133	F	4	35 BRO	SP	A	V	00:00.0
2021 PO4320287109	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4314187061	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4310987086	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4314087016	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4313487021	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4314087018	LGE	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4315287006	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4316186999	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4317086992	F	3	50 ACE	SP	CCA	V	00:00.0
2021 PO4309587051	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4310287046	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4310987040	F	4	35 ACE	SP	A	V	00:00.0

2021 PO4311887033	F	4	30 ACE	SP	P	V	00:00.0
2021 PO4312687027	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4324087056	F	4	35 BRO	SP	CRE	V	00:00.0
2021 PO4325387072	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4314987101	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4315687095	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4316387090	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4317187083	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4318887070	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4320187061	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4320787055	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4321487049	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4323087038	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4323487031	F	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4323787026	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4324287018	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4324587013	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4326586984	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4325586998	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4325087004	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4326186988	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4326986974	F	5	35 ACE	SP	A	V	00:00.0
2021 PO4302887083	F	4	35 ACE	SP	P	V	00:00.0
2021 PO4309987094	F	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4312287086	F	4	35 ACE	SP	CCA	V	00:00.0
2021 PO4309987068	LGE	1	50 ACE	SP	CCA	V	00:00.0
2021 PO4308887045	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO4307987042	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4307187047	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4306387053	F	4	30 ACE	SP	A	V	00:00.0
2021 PO4305887057	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4305587060	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4305087064	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4306287127	LGE	4	30 ACE	SP	CCA	V	00:00.0
2021 PO4319887016	F	4	30 ACE	SP	CRE	V	00:00.0
2021 PO4319287020	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4317987077	F	3	45 BRO	SP	CRE	V	00:00.0
2021 PO4318087030	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4317387036	F	4	35 ACE	SP	CRE	V	00:00.0
2021 PO4318687084	LGE	3	45 BRO	SP	CCA	V	00:00.0
2021 PO4313587066	F	4	35 ACE	SP	A	V	00:00.0
2021 PO4303287074	LGE	4H	60 ACE	SP	CRE	V	00:00.0
2021 PO4302687069	F	4	40 ACE	SP	CRE	V	00:00.0
2021 PO4303787069	LGE	1	55E ACE	SP	CCA	V	00:00.0
2021 PO7160072931	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO7067367933	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO7196268219	F	4	45 BRO	SP	CCA	V	00:00.0
2021 PO7191168438	F	4	45 BRO	SP	CCA	V	00:00.0
2021 PO6969567601	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO7178168578	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO4900607293	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO5020207503	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO2869075176	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO2877875060	KU	3	45 BRO	SP	CCA	V	00:00.0

2021 PO2746680176	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2697180306	F	6	30 UNK	SP	CRE	V	00:00.0
2021 PO2908174698	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO3077670791	F	4	40 ACE	SP	A	V	00:00.0
2021 PO2926074554	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2889774903	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2812379982	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2817879743	F	3	50 UNK	SP	CRE	V	00:00.0
2021 PO6924966950	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO6915266935	F	4	40 KOP	SP	P	V	00:00.0
2021 PO6919666891	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO2872575518	KU	2	40 BRO	SP	CCA	V	00:00.0
2021 PO2870975531	KU	2	40 BRO	SP	CCA	V	00:00.0
2021 PO2866775567	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO2861275491	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO2856375458	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO5512838730	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO7071869223	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO6882566935	F	4	45 UNK	SP	P	V	00:00.0
2021 PO2839077048	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2822076949	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2839077179	KU	6	30 BRO	SP	CCA	V	00:00.0
2021 PO2810977146	F	5	35 UNK	SP	CRE	V	00:00.0
2021 PO2825677102	F	3	45 UNK	SP	P	V	00:00.0
2021 PO2827877209	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2830277311	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2834777514	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2833077440	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2837077809	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2840578220	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2839378067	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2841778345	KU	3	45 BRO	SP	CCA	V	00:00.0
2021 PO2844178645	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2837278957	F	3	40 UNK	SP	CRE	V	00:00.0
2021 PO6380424635	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO6371024618	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO3053870167	KU	4	40 XXX	SP	CCA	V	00:00.0
2021 PO2818776490	F	4	40 BRO	SP	CCA	V	00:00.0
2021 PO2800276935	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO3095070773	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO2817576730	KU	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2858875725	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO2868275781	F	6	25 BRO	SP	CRE	V	00:00.0
2021 PO2284478378	KU	5	35 BRO	SP	CCA	V	00:00.0
2021 PO2475279189	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2448479160	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2452179075	F	6	30 BRO	SP	CRE	V	00:00.0
2021 PO2429279093	F	4	40 BRO	SP	CRE	V	00:00.0
2021 PO2419979005	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO5588138807	KU	4	40 BRO	SP	CCA	V	00:00.0
2021 PO2344078766	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2324978650	F	4	40 UNK	SP	CRE	V	00:00.0
2021 PO2889772306	KU	3	45 XXX	SP	CCA	V	00:00.0
2021 PO2892472235	KU	3	45 XXX	SP	CCA	V	00:00.0

2021 PO2916471323	F	6	35 XXX	SP	CRE		V		00:00.0	
2021 PO2895170973	F	4	40 XXX	SP	CRE		V		00:00.0	
2021 PO2874170602	F	5	35 XXX	SP	CRE		V		00:00.0	
2021 PO2494579350	F	4	40 UNK	SP	CRE		V		00:00.0	
2021 PO2546579757	F	4	40 UNK	SP	CRE		V		00:00.0	
2021 PO2533479644	F	4	45 UNK	SP	CCA		V		00:00.0	
2021 PO7162068986	KU	3	45 BRO	SP	CCA		V		00:00.0	
2021 PO7185068971	KU	4	40 BRO	SP	CCA		V		00:00.0	
2021 PO2774868398	KU	5	35 XXX	SP	CCA		V		00:00.0	
2021 PO6942671704	KU	4	45 XXX	SP	CCA		V		00:00.0	
2021 PO7281567054	KU	3	45 BRO	SP	CCA		V		00:00.0	
2021 PO2645480272	F	4	40 UNK	SP	CRE		V		00:00.0	
2021 PO2637080233	F	4	40 UNK	SP	CRE		V		00:00.0	
2021 PO2659380501	F	4	40 UNK	SP	CRE		V		00:00.0	
2021 PO9639161204	KU	4	45 UNK	SP	CRE	ID		BD	00:00.0	
2021 PO9605761176	KU	5	30 UNK	SP	CRE	ED,ID,IP		TD	00:00.0	
2021 PO8940561578	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0	
2021 PO8947261795	KU	6	30 BRO	SP	CRE		V		00:00.0	
2021 PO9587961111	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0	
2021 PO9579260990	KU	4	40 KOP	SP	CRE	ID		BD	00:00.0	
2021 PO9570860871	KU	4	40 KOP	SP	CRE	ED,ID		TD	00:00.0	
2021 PO8962761743	KU	6	30 BRO	SP	CRE	ED,ID		BD	00:00.0	
2021 PO8957661754	KU	4	40 BRO	SP	CCA		V		00:00.0	
2021 PO9581661740	KU	5	35 BRO	SP	CRE	ED,ID		TD	00:00.0	
2021 PO9594461980	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0	
2021 PO9618561807	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0	
2021 PO9355161374	KU	5	35 XXX	SP	CCA		V		00:00.0	
2021 PO9361961385	KU	4	40 XXX	SP	CRE	ID		TD	00:00.0	
2021 PO9382760631	F	4	40 XXX	SP	CRE		V		00:00.0	
2021 PO4944089240	LGE	3	45 BRO	SP	CCA		V		00:00.0	
2021 PO9375959262	KU	4	40 UNK	SP	CRE	ED,ID		TD	00:00.0	
2021 PO9380561312	KU	4	45 XXX	SP	CRE	ID		TX	RR	00:00.0
2021 PO9241160225	KU	3	50 UNK	SP	CRE	ED,ID		TD		00:00.0
2021 PO9231260336	KU	3	50 UNK	SP	CRE		V			00:00.0
2021 PO4536104422	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4541104123	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4526804488	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4495904803	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX		PX	00:00.0
2021 PO4500304737	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4517404552	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4508204619	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4547304285	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4552504204	F	4	40 BRN	SP	CRE		V			00:00.0
2021 PO4485198372	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021 PO4473098417	F	3	45 BRO	SP	CRE	ED	V			00:00.0
2021 PO4456398477	F	6	30 BRO	SP	CRE	ED	V			00:00.0
2021 PO4462498452	F	3	45 BRO	SP	CRE	ED	V			00:00.0
2021 PO4460198497	F	3	45 BRO	CRE	CRE	ED,HH,ID,RB	BX		RP3	00:00.0
2021 PO4464798498	F	2	40 BRO	SP	CRE	ED	V			00:00.0
2021 PO4451398532	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021 PO4480401070	F	4	40 BRO	SP	CRE		V			00:00.0
2021 PO4350998958	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021 PO4361798913	F	4	40 BRO	SP	CRE	ED	V			00:00.0
2021 PO4371898870	F	4	40 BRO	SP	CRE	ED	V			00:00.0

2021 PO4384298817	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4393898776	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4405998724	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4417098678	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4426698637	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4439398583	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4444798881	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO4457298828	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4432898932	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4421598982	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4410799028	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4399799075	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4390099117	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4377999170	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO4366799218	F	4	40 BRO	SP	CRE	ED	V		00:00.0
2021 PO9220760444	KU	3	50 UNK	SP	CRE	ID	BD		00:00.0
2021 PO9238360177	KU	3	50 KOP	SP	CRE	ID	BD		00:00.0
2021 PO9395259602	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9368259346	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO6134398938	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6241499208	F	4	40 XXX	SP	CRE	ED,ID,IP,MD	BX	RP1	00:00.0
2021 PO6236899731	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6243199036	F	4	40 XXX	SP	P		V		00:00.0
2021 PO9291260756	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9300760714	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9316860772	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9282660961	KU	4	40 OTH	SP	CRE		V		00:00.0
2021 PO9286660888	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9466558774	KU	3	50 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO6239699409	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6256699452	F	4	40 XXX	CRE	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO6271699208	F	4	40 XXX	CRE	CRE	ED,HH,ID	BX	PX	00:00.0
2021 PO6272699080	F	3	40 XXX	SP	CCA		V		00:00.0
2021 PO6298199087	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6305899092	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6312299134	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO6318399126	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO6246699513	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6238199567	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO6270799373	F	4	40 XXX	CRE	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO6278299330	F	4	40 XXX	SP	CCA		V		00:00.0
2021 PO9311860337	KU	6	30 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021 PO9309560333	KU	3	55 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9295660639	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9285960766	KU	6	30 OTH	SP	CRE		V		00:00.0
2021 PO9302260491	KU	2	50 OTH	SP	CCA		V		00:00.0
2021 PO9692863637	KU	4	45 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9687263503	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO9694463458	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO6303199186	F	4	40 XXX	CRE	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO6290899257	F	4	40 XXX	CRE	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO9620363442	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO4425004801	F	5	35 BRN	SP	CCA		V		00:00.0
2021 PO4377604540	F	4	40 BRN	SP	CRE		V		00:00.0



2021 PO4475105130	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4439804937	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4510405432	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX PX	00:00.0
2021 PO4503605360	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4457505030	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4412204750	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX PX	00:00.0
2021 PO4394104666	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4493005234	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9367060858	KU	3	50 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9386261035	KU	5	35 XXX	SP	CRE		V	00:00.0
2021 PO9394661210	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9403961427	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0
2021 PO4933889517	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4933689499	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4934389500	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO9363260649	KU	2	50 XXX	SP	CCA		V	00:00.0
2021 PO9387060409	KU	4	40 XXX	SP	CCA		V	00:00.0
2021 PO9377860534	KU	4	40 XXX	SP	P	ED	T	00:00.0
2021 PO9396460518	KU	5	35 XXX	SP	CCA		V	00:00.0
2021 PO9390760717	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9373760698	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9398860799	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9405860914	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9416460998	KU	6	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9402861193	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9410461315	KU	4	30 XXX	SP	CRE	ID	TD	00:00.0
2021 PO9383161086	KU	5	35 XXX	SP	CRE		V	00:00.0
2021 PO9433562696	KU	6	30 XXX	SP	CRE		V	00:00.0
2021 PO9562060749	KU	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9136657454	KU	5	35 BRO	CCA	CRE		V	00:00.0
2021 PO9121057433	F	2	45 UNK	SP	CCA		V	00:00.0
2021 PO9132457301	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4692703753	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO4681703806	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO4693004075	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO4688603969	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO4684303866	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9104457333	F	6	30 BRO	SP	CRE		V	00:00.0
2021 PO4722803914	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4727704014	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4734704128	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4718003810	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9106157237	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9104257256	F	5	35 UNK	SP	CRE		V	00:00.0
2021 PO9105157106	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9618861946	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9547462160	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9105256967	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9087457054	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9062057073	F	4	40 UNK	SP	P		V	00:00.0
2021 PO9073157075	F	4	40 UNK	SP	P		V	00:00.0
2021 PO9077356786	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9084957079	F	4	40 UNK	SP	P		V	00:00.0
2021 PO9068056920	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0

2021	PO9533059384	F	4	45 OTH	SP	CRE		V		00:00.0
2021	PO9517659554	F	4	35 OTH	SP	P		V		00:00.0
2021	PO9507159652	F	3	50 OTH	SP	P		V		00:00.0
2021	PO9526159388	F	5	35 OTH	SP	P		V		00:00.0
2021	PO9533359457	F	3	40 OTH	SP	P		V		00:00.0
2021	PO9533559578	F	3	50 OTH	SP	P		V		00:00.0
2021	PO9503659593	F	4	35 OTH	SP	CCA		V		00:00.0
2021	PO9519359599	F	3	50 OTH	SP	CRE		V		00:00.0
2021	PO4801389517	F	4	40 ACE	SP	CRE		V		00:00.0
2021	PO4781189309	F	3	50 ACE	SP	CCA		V		00:00.0
2021	PO4782389315	F	2	55 ACE	SP	CCA		V		00:00.0
2021	PO9471859758	KU	4	40 OTH	SP	CCA		V		00:00.0
2021	PO9488959647	KU	2	50 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9494159687	F	4	35 OTH	SP	CCA		V		00:00.0
2021	PO9492259762	F	3	50 OTH	SP	P		V		00:00.0
2021	PO9488059792	F	5	35 OTH	SP	P		V		00:00.0
2021	PO9484259529	KU	2	60 OTH	SP	CCA		V		00:00.0
2021	PO9481359704	KU	4	40 OTH	SP	CCA	ED,SRS	TD		00:00.0
2021	PO9496559726	F	3	50 OTH	SP	CRE		V		00:00.0
2021	PO9487259401	KU	5	35 OTH	SP	CRE	ID	BD		00:00.0
2021	PO9031456699	F	5	35 BRO	SP	CRE		V		00:00.0
2021	PO9016356401	F	4	40 BRO	SP	CCA		V		00:00.0
2021	PO9003656027	KU	2	45 KOP	CRE	CRE	ED,ID,RB	X	PX	00:00.0
2021	PO9004356172	KU	4	45 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO9507259067	KU	5	35 UNK	SP	CRE		V		00:00.0
2021	PO6567098786	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6573198637	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6578198573	KU	6	30 XXX	CRE	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021	PO6614598339	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6583598514	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6592098436	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6601998392	F	4	40 XXX	CRE	CRE	ED,ID,IP	BX	RP2	00:00.0
2021	PO6505198806	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6501598741	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6498398686	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6492398807	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6480298870	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6453498904	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6466498893	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6445998718	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6460998629	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6361299178	F	3	40 XXX	SP	P		V		00:00.0
2021	PO6372999091	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6380699053	F	4	40 XXX	CRE	CRE	ED,ID	BX	RP2	00:00.0
2021	PO6399398956	KU	3	40 XXX	SP	P	ED,ID	BD		00:00.0
2021	PO6390099007	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6409398900	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6440198726	F	3	40 XXX	SP	P		V		00:00.0
2021	PO6420098838	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6429798781	F	4	40 XXX	CRE	CRE	ED,HH,ID	BX	PX	00:00.0
2021	PO6451998656	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6458098628	F	4	40 XXX	P	P	ED,HH,ID	BX	PX	00:00.0
2021	PO6453098544	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO9559062225A	KU	5	30 BRO	SP	CRE	ED,ID	BD		00:00.0

2021 PO9658656470	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9559062225	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9567162166	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9594962190	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9604362333	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9631056311	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9628256372	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4712403661	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4749504178	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4731004304	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO4740304239	F	4	40 BRN	SP	CRE		V	00:00.0
2021 59401A	KU	6	30 OTH	SP	CCA	ED,SRS	TD	00:00.0
2021 PO9562859295	F	4	50 OTH	SP	CRE		V	00:00.0
2021 PO9542959234	F	4	40 OTH	SP	P		V	00:00.0
2021 PO9554959027	F	4	40 OTH	SP	P		V	00:00.0
2021 PO9475659274	KU	3	50 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9542859266	F	2	60 OTH	SP	P		V	00:00.0
2021 PO9485059269	KU	2	55 OTH	SP	CCA		V	00:00.0
2021 PO9634762492	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9663056851	KU	5	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4643502885	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO9569259312	KU	3	50 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9629759758	KU	4	45 OTH	SP	CCA		V	00:00.0
2021 PO9528659259	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9495359264	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9511859257	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9554659093	F	4	30 OTH	SP	P		V	00:00.0
2021 PO9529259133	KU	4	40 OTH	SP	CRE	ID	BD	00:00.0
2021 PO9533259012	F	3	45 OTH	SP	P		V	00:00.0
2021 PO9617956403	KU	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO9610862280	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9498959112	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO9475458902	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9475759138	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9477859137	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9475559026	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9462359176	KU	5	35 UNK	SP	CRE	ID,IP	BD	00:00.0
2021 PO9666362864	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9633156686	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 N/A	F	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4627503819	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4658103654	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4665803461	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4610403888	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4647903687	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4615403803	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4616903871	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4635903766	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9665762751	KU	5	30 BRO	SP	S		V	00:00.0
2021 PO9637962779	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9637962779A	KU	3	20 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6047504744	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO0132434445	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4905990736	LGE	4	40 BRN	SP	CCA	ED	V	00:00.0

2021	PO6037104602	KU	4	40 BRN	SP	CCA		V			00:00.0
2021	PO0124034230	KU	6	30 KOP	SP	CRE	ED,ID	TD			00:00.0
2021	PO5990304789	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO6015704765	F	3	45 BRN	SP	CRE		V			00:00.0
2021	PO6029104756	F	3	45 BRN	SP	CRE		V			00:00.0
2021	PO5963104821A	F	3	45 BRN	SP	CCA		V			00:00.0
2021	PO5969504812	F	3	45 BRN	SP	CRE		V			00:00.0
2021	PO5963104821	F	3	45 BRN	SP	CCA		V			00:00.0
2021	PO4909390736	LGE	3	50 BRN	SP	P	ED,ID	BD			00:00.0
2021	PO4906190720	LGE	3	45 BRN	SP	CCA	ED	T			00:00.0
2021	PO2287642883	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0
2021	PO4460406810	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4449906799	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO6050849697	KU	6	30 BRO	SP	CRE	ED,ID	TX	RR		00:00.0
2021	PO0121534239	KU	6	30 KOP	SP	CRE	ED,ID	TD			00:00.0
2021	PO0106134116	KU	4	40 KOP	SP	CRE	ED,ID	TD			00:00.0
2021	PO5785904110	KU	4	40 XXX	SP	CRE	ED,ID	TD			00:00.0
2021	PO5766503914	KU	4	40 XXX	SP	CRE	ED,ID	TD			00:00.0
2021	PO5756603877	F	4	40 XXX	SP	P		V			00:00.0
2021	PO5749003750A	KU	3	45 XXX	SP	CRE	ED,ID,MD,SRC	TX	RR		00:00.0
2021	PO5773603961	KU	6	30 XXX	SP	CRE	ED,ID	TD			00:00.0
2021	PO7462203868	LGE	1	50 ACE	SP	CCA		V			00:00.0
2021	PO4362007477	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4397807116	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4353807278	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX		00:00.0
2021	PO4386406824	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4346207096	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4393807015	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO4390306924	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO2322042687	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0
2021	PO2353142491	KU	4	40 XXX	SP	CRE	ID	TD			00:00.0
2021	PO5939704870	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5920204915	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5901104960	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5894104836	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5888004732	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5884504672	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO5880904610	F	4	40 BRN	SP	CRE		V			00:00.0
2021	PO7456604136	LGE	1	50 ACE	SP	CCA		V			00:00.0
2021	PO7449703856	LGE	1	50 ACE	SP	CCA		V			00:00.0
2021	PO0095134071	KU	4	40 KOP	SP	CRE	ED,ID	TD			00:00.0
2021	PO0077734003	KU	4	45 KOP	SP	CRE	ED,ID	TD			00:00.0
2021	PO0051733795	KU	4	40 BRO	SP	CRE	ED,ID	TD			00:00.0
2021	PO0141035430	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO5031889200	LGE	4	40 ACE	SP	CCA		V			00:00.0
2021	PO4908290698	LGE	3	45 BRN	SP	P	ED,ID	BD			00:00.0
2021	PO6047851002	KU	4	40 BRO	SP	CRE	ED,ID	TD			00:00.0
2021	PO6052251383	KU	4	40 BRO	SP	CRE	ED,ID	TD			00:00.0
2021	PO2081465624	KU	4	30 BRO	SP	CRE	ED,ID,IP	TD			00:00.0
2021	PO7374804841	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021	PO7378404986	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021	PO7379605051	LGE	3	45 ACE	SP	CCA		V			00:00.0
2021	PO5030389172	LGE	4	40 ACE	SP	CRE		V			00:00.0
2021	PO2373542454	KU	4	40 XXX	SP	CRE	ED,ID	TX	RR		00:00.0

2021 PO2392242416	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO2474043138	KU	5	35 XXX	SP	CRE		BD	00:00.0
2021 PO2452442855	KU	5	35 XXX	SP	CRE		BD	00:00.0
2021 PO5027689179	LGE	4	40 ACE	SP	A	ED	V	00:00.0
2021 PO7357605049	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO5024089186	LGE	4	40 ACE	SP	A	ED	V	00:00.0
2021 PO7328505129	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6092651365	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4909790675	LGE	3	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4910190678	LGE	3	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4911390692	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5873004477	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5868604400	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5865904352	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4378306089	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4392206100	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4378805890	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4402306122	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4393005901	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4407405914	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO2076165120	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2067665120	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5021389172	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO5020589192	LGE	4	40 ACE	SP	CCA	ED,ID	TD	00:00.0
2021 PO5780103591	KU	4	40 XXX	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO5749003750	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5758703537	KU	3	45 XXX	SP	P	ED,ID	BD	00:00.0
2021 PO5780003531	KU	3	45 XXX	SP	P	ED,ID	TD	00:00.0
2021 PO5764303628	F	4	40 XXX	SP	P		V	00:00.0
2021 PO5780403665	KU	4	40 XXX	SP	CRE	ED,ID,SRC	TD	00:00.0
2021 PO4847490442	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4399206324	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4332106724	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4340406724	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4376306292	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4293206727	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4390106314	F	3	45 BRN	SP	A		V	00:00.0
2021 PO4313406726	F	3	40 BRN	SP	CCA		V	00:00.0
2021 PO6081051141	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4903590056	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO2074864653	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2093464635	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9920235421	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO5850704787	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5847704736	F	4	40 BRN	SP	CRE	ED,HH,ID,JP,RB	VX PX	00:00.0
2021 PO5858304891	F	4	40 BRN	SP	CRE	ED,HH,ID,JP	VX RP2	00:00.0
2021 PO6069251416	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO9941335380	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9974835645	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0024735809	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO0084336058	KU	4	40 BRO	SP	CRE	ED	BX PX	00:00.0
2021 PO0101936009	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO0194835558	KU	4	40 CAH	SP	CRE	ED,ID,JP	TD	00:00.0
2021 PO0159635855	KU	3	35 CAH	SP	CRE	ED,ID	TD	00:00.0

2021	PO0232635460	KU	4	40 CAH	SP	CRE	ED,ID	TD		00:00.0
2021	PO7312505987	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021	PO7317406074	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO5024989274	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO5025389281	LGE	4	30 ACE	SP	A	ED,ID	TD		00:00.0
2021	PO4909790627	LGE	4	40 BRN	SP	A	ED,HH,ID,IP	VX	RP1	00:00.0
2021	PO2086264252	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6049151509A	KU	5	35 BRO	SP	S		V		00:00.0
2021	PO2437342664	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2414742432	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2411242374	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2424042263	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO2420741682	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2438242140	KU	4	45 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2470041883	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2489641748	KU	4	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2502741656	KU	4	35 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2516741549	KU	4	35 XXX	SP	CRE	ID,IP	X	RP2	00:00.0
2021	PO2535941308	KU	6	30 XXX	SP	CRE	HH,ID,RB	X	PX	00:00.0
2021	PO2531041438	KU	4	35 XXX	SP	CCA	ID	TD		00:00.0
2021	PO2547741310	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021	PO2567641163	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO7069869859	KU	4	50 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5883505018	F	3	45 BRN	SP	CRE	ED,ID,MD,RB	VX	RP1	00:00.0
2021	PO4805910437	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021	PO7313006107	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO5028289264	LGE	3	50 ACE	SP	CCA		V		00:00.0
2021	PO2095063993	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO5838904580	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5833204369	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5831604450	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5823704314	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4847490438	LGE	1	50 BRO	SP	CCA		V		00:00.0
2021	PO6049151509	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO6037651362	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO5296516215	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021	PO5030589250	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO5298016167	LGE	3	50 BRO	SP	CCA		V		00:00.0
2021	PO4902490036	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5849205132	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5868305067	F	3	40 BRN	SP	CRE		V		00:00.0
2021	PO5866305031	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	VX	PX	00:00.0
2021	PO7416705700	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO5821203927	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5814903875	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO5816803820	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5811504037	F	4	40 XXX	SP	P		V		00:00.0
2021	PO5823004029	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO5821204077	KU	6	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO5809904078	KU	7	30 XXX	SP	CRE	ED,ID	TD		00:00.0
2021	PO7433205630	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO7451705524	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO2104763724	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO6039351091	KU	5	35 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0

2021	PO5800804480	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5798404527	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5804904655	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5811604780	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5818904899	F	4	40 BRN	SP	CRE	ED,ID,IP,RB	VX	PX	00:00.0
2021	PO5803204811	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO7470205419	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO7499905496	LGE	1	55 ACE	SP	CCA		V		00:00.0
2021	PO7518005523	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4861590482	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021	PO4861990481	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021	PO7513005652	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO7527905816	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO2115463450	KU	3	45 BRO	SP	CRE		V		00:00.0
2021	PO4916090142	LGE	4	40 BRO	SP	A	ID		BD	00:00.0
2021	PO4914290131	LGE	4	40 BRO	SP	A	ID,IP		BD	00:00.0
2021	PO7525005839	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO4862290452	LGE	4	35 BRN	SP	A	ED,ID		TD	00:00.0
2021	PO5693617723	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021	PO4862090460	LGE	3	35 BRN	SP	CCA		V		00:00.0
2021	PO4330106495	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4343906490	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4338606596	KU	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4292606487	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO7518904779	LGE	3	45 ACE	SP	CCA		V		00:00.0
2021	PO6091450277	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO2137762874A	F	3	40 BRO	SP	P		V		00:00.0
2021	PO2125663180	KU	5	30 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO2137762874	KU	5	30 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO5827305067	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5832005149	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5834005187	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO5817805242	F	4	40 BRN	SP	CCA		V		00:00.0
2021	PO7502904829	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021	PO7485204769	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO4912490120	LGE	4	40 BRO	SP	A	ID,IP		BD	00:00.0
2021	PO4910790110	LGE	4	40 BRO	SP	A	ID,IP		BD	00:00.0
2021	PO7485404933	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO5042589189	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021	PO6061050040	KU	4	45 BRO	SP	CCA		V		00:00.0
2021	PO6055950148	KU	3	45 BRO	SP	CCA		V		00:00.0
2021	PO6030250217	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021	PO6026850272	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO6024450186	F	4	40 BRO	SP	CRE		V		00:00.0
2021	PO6019150096	F	4	40 BRO	SP	S		V		00:00.0
2021	PO6016050009	F	4	40 BRO	SP	S		V		00:00.0
2021	PO4850491105	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4845391147	LGE	4	40 BRN	SP	CRE		V		00:00.0
2021	PO0232835274	KU	4	40 REP	SP	CRE	ED,ID		TD	00:00.0
2021	PO7478005396	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO7484905364	LGE	1	50 ACE	SP	CCA		V		00:00.0
2021	PO4269306596	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021	PO4422108135	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4407408450	F	4	40 BRN	SP	CRE		V		00:00.0

2021 PO4431207908	F	4	40 BRN	SP	CRE		V	00:00:00
2021 PO4421907943	F	4	40 BRN	SP	CRE		V	00:00:00
2021 PO4268206456	F	4	40 BRN	SP	CRE		V	00:00:00
2021 PO4278206564	F	4	40 BRN	SP	CCA		V	00:00:00
2021 PO4418608310	F	4	40 BRN	SP	CRE		V	00:00:00
2021 PO7487605192	LGE	1	50 ACE	SP	CCA		V	00:00:00
2021 PO5774704701	KU	6	30 BRN	SP	CCA		V	00:00:00
2021 PO5777604874	F	4	40 BRN	SP	CRE		V	00:00:00
2021 PO5774304814	F	4	40 BRN	SP	CRE	ED,HH,ID,IP,RB	VX	RP1 00:00:00
2021 PO4830491047	LGE	4	40 BRN	SP	CRE		V	00:00:00
2021 PO4828591040	LGE	4	40 BRN	SP	CRE		V	00:00:00
2021 PO5305820973	LGE	4	35 BRN	SP	CRE		V	00:00:00
2021 PO4822490570	LGE	2	55 BRN	SP	CRE		V	00:00:00
2021 PO4822490568	LGE	2	55 BRN	SP	CCA		V	00:00:00
2021 PO5289718641	LGE	2	55 BRN	SP	CRE		V	00:00:00
2021 PO4852391089	LGE	4	35 BRN	SP	P		V	00:00:00
2021 PO4844590983	LGE	4	35 BRN	SP	P		V	00:00:00
2021 PO4823890893	LGE	3	45 BRN	SP	P		V	00:00:00
2021 PO4808591524	LGE	UNK	45 BRN	SP	CRE		V	00:00:00
2021 PO4806591514	LGE	4	40 BRN	SP	P		V	00:00:00
2021 PO4797391571	LGE	4	40 BRN	SP	P		V	00:00:00
2021 PO4798091549	LGE	4	35 BRN	SP	P		V	00:00:00
2021 PO4799091536	LGE	4	40 BRN	SP	P		V	00:00:00
2021 PO4809591470	LGE	4	35 BRN	SP	P		V	00:00:00
2021 PO4837191272	LGE	4	40 BRN	SP	P		V	00:00:00
2021 PO4837391212	LGE	4	40 BRN	SP	CRE		V	00:00:00
2021 PO4831691193	LGE	4	30 BRN	SP	P		V	00:00:00
2021 PO4836291221	LGE	6	25 BRN	SP	CRE	ED,ID	BD	00:00:00
2021 PO4835691227	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00:00
2021 PO4832591190	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00:00
2021 PO4830791169	LGE	3	45 BRN	SP	CCA	ED,ID	T	00:00:00
2021 PO4908990099	LGE	4	40 BRO	SP	A	ID	BD	00:00:00
2021 PO5785105008	F	4	40 BRN	SP	CRE		V	00:00:00
2021 PO5756205076	F	4	40 BRN	SP	CRE		V	00:00:00
2021 PO5558219906	KU	3	40 BRN	SP	CCA		V	00:00:00
2021 PO5553619954	KU	3	40 BRN	SP	P		V	00:00:00
2021 PO5562619857	KU	5	35 OTH	SP	CRE	ED,ID,IP	TD	00:00:00
2021 PO9222125424	ODP	4	40 KOP	SP	CRE		V	00:00:00
2021 PO9260525788	ODP	5	35 KOP	SP	CRE		V	00:00:00
2021 PO7909243253	ODP	5	40 BRO	SP	CRE	ED,ID	TD	00:00:00
2021 PO7912443109	F	4	40 BRO	SP	CRE		V	00:00:00
2021 PO8376443547	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00:00
2021 PO8373243455	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00:00
2021 PO8356343408	ODP	6	30 XXX	SP	CRE	ED,ID	BD	00:00:00
2021 PO8389343577	ODP	4	40 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00:00
2021 PO8400343647	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	00:00:00
2021 PO8412743632	ODP	5	35 XXX	SP	CRE	ED,ID,IP,MD,SRC	TD	00:00:00
2021 PO8430243568	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00:00
2021 PO9124423000	F	4	40 KOP	SP	CRE		V	00:00:00
2021 PO7505918152	ODP	5	30 KOP	SP	CRE		V	00:00:00
2021 PO5295621076	KU	4	45 BRN	SP	S		V	00:00:00
2021 PO5299821107	KU	6	30 BRN	SP	CRE	ID,IP	BD	00:00:00
2021 PO5303521033	KU	4	45 BRN	SP	CRE		V	00:00:00
2021 PO5312220932	KU	4	40 BRN	SP	CRE		V	00:00:00



2021 PO9116123204	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO7918842843	ODP	5	30 BRO	SP	CCA		V		00:00.0
2021 PO7914242806	F	4	40 BRO	SP	CRE		V		00:00.0
2021 PO5571519756	KU	4	40 OTH	SP	CRE	ED,ID	BD		00:00.0
2021 PO4938888835	LGE	1	60 BRO	SP	CCA		V		00:00.0
2021 PO7920742506	ODP	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021 PO7920742506A	ODP	6	30 BRO	SP	CRE	ID	BD		00:00.0
2021 PO7882142724	ODP	4	40 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7897942536	ODP	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7885142508	ODP	6	30 BRO	SP	CCA		V		00:00.0
2021 PO7890742409	ODP	4	45 BRO	SP	CCA		V		00:00.0
2021 PO5354920293	KU	4	40 BRN	SP	CRE	ED,ID	BX	RP2	00:00.0
2021 PO5319120405	KU	2	50 BRN	SP	S		V		00:00.0
2021 PO5269320710	KU	3	55 BRN	SP	S		V		00:00.0
2021 PO5306620080	KU	2	50 BRN	SP	S		V		00:00.0
2021 PO5378120244	KU	4	40 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO5340120366	KU	2	50 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO5391420346	KU	4	45 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO5384020289	KU	3	45 BRN	SP	CRE	HH,ID,IP,RB	VX	PX	00:00.0
2021 PO5361020106	KU	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5300720515	KU	2	50 BRN	SP	S		V		00:00.0
2021 PO5324120220	KU	4	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5367620163	KU	4	40 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO5283820619	KU	3	45 BRN	SP	S	ED,SRG	T		00:00.0
2021 PO5374920281	KU	6	30 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO5369920140	KU	4	40 BRN	SP	CRE	ID,IP	BD		00:00.0
2021 PO5314520142	KU	3	45 BRN	SP	CRE	ID	BD		00:00.0
2021 PO5562519782	F	6	30 ACE	SP	P		V		00:00.0
2021 PO5566919736	F	4	35 OTH	SP	P		V		00:00.0
2021 PO5570319699	F	6	30 OTH	SP	P		V		00:00.0
2021 PO7587917203	ODP	5	35 KOP	SP	CRE	ED	TD		00:00.0
2021 PO4938388827	LGE	1	60 BRO	SP	CCA		V		00:00.0
2021 PO7877242563	ODP	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO5589219879	KU	3	45 OTH	SP	CRE		V		00:00.0
2021 PO4937088801	LGE	1	60 BRO	SP	CCA		V		00:00.0
2021 PO4937788815	LGE	1	55 BRO	SP	CCA		V		00:00.0
2021 PO7618116839	ODP	4	40 KOP	SP	CRE	ED	BD		00:00.0
2021 PO7629216647	ODP	5	35 KOP	SP	CRE	ED	TD		00:00.0
2021 PO7651516082	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO7657916192	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO7852842654	ODP	4	40 BRO	SP	CRE	ID	BD		00:00.0
2021 PO7857142495	ODP	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7855242306	ODP	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7896242204	ODP	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7869242344	ODP	4	45 BRO	SP	CCA		V		00:00.0
2021 PO5468821111	KU	6	30 OTH	SP	CCA	ED,ID	BD		00:00.0
2021 PO7674216360	ODP	4	40 KOP	SP	CCA		V		00:00.0
2021 PO7697916309	ODP	4	40 KOP	SP	CCA		V		00:00.0
2021 PO546221191	F	4	40 OTH	SP	CCA	ED,ID	V		00:00.0
2021 PO4946388883	LGE	4	40 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO5470221239	KU	2	50 OTH	SP	CRE	ED,ID,IP	BX	RP2	00:00.0
2021 PO7648916324	ODP	5	35 KOP	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO7931542192	ODP	4	40 BRO	SP	CCA	ED,ID,IP	TD		00:00.0
2021 PO5478221148	KU	3	45 OTH	SP	CRE	ED,ID	TD		00:00.0

2021 PO8076207196	ODP		4	40 KOP	SP	CRE		ED		TD	00:00.0
2021 PO4941388871	LGE	H2		65 BRO	SP	CRE				V	00:00.0
2021 PO4940888873	LGE		1	60 BRO	SP	CCA				V	00:00.0
2021 PO5485720818	KU		6	30 OTH	SP	CRE		ED,ID,IP		TD	00:00.0
2021 PO6512701920	LGE		1	60 BRO	SP	CCA				V	00:00.0
2021 PO5492120929	KU		6	30 OTH	SP	CRE		ED,ID,IP		TD	00:00.0
2021 PO4941788873	LGE		4	35 BRO	SP	CCA				V	00:00.0
2021 PO4942988830	LGE		3	45 BRO	SP	CCA				V	00:00.0
2021 PO4942688835	LGE		4	40 BRO	SP	CCA				V	00:00.0
2021 PO4942288848	LGE		3	45 BRO	SP	CCA				V	00:00.0
2021 PO4946088748	LGE		4	40 BRO	SP	A		ED,ID,IP		TD	00:00.0
2021 PO4914988944	LGE		5	25 BRO	SP	CRE				V	00:00.0
2021 PO7797144380A	ODP		5	35 BRN	SP	CCA				V	00:00.0
2021 PO5493819627	KU		5	35 BRN	SP	CRE		ED,ID,IP		BD	00:00.0
2021 PO5452621278	KU		5	35 BRN	SP	CCA		ID		BD	00:00.0
2021 PO5452221252	KU		3	50 BRN	SP	CCA				V	00:00.0
2021 PO5453321260	KU		3	50 BRN	SP	CCA				V	00:00.0
2021 PO5498419699	KU		5	35 BRN	SP	CRE		ED,ID		BD	00:00.0
2021 PO7782343046	ODP		4	30 KOP	SP	CRE		ED,ID		TD	00:00.0
2021 PO7780442912	ODP		6	30 KOP	SP	CRE				V	00:00.0
2021 PO7792142988	ODP		4	40 KOP	SP	CRE		ID		BD	00:00.0
2021 PO4931188696	LGE		3	45 BRO	SP	CRE		ED,ID,IP		TD	00:00.0
2021 PO5426221356	KU		6	30 BRN	SP	CRE		ID,IP		BD	00:00.0
2021 PO5428021345	KU		3	45 BRN	SP	CCA				V	00:00.0
2021 PO5429521353	KU		3	45 BRN	SP	CRE		ID		BD	00:00.0
2021 PO5388721461	KU		2	50 BRN	SP	CRE		ID		BD	00:00.0
2021 PO4932488701	LGE		4	30 BRO	SP	A		ED,ID,IP		TD	00:00.0
2021 PO4706289766	F		4	30 ACE	SP	P				V	00:00.0
2021 PO4868589893	LGE		3	45 BRN	SP	CCA				V	00:00.0
2021 PO4867989892	LGE		3	45 BRN	SP	A		ED,ID		BD	00:00.0
2021 PO4867089888	LGE		3	45 BRN	SP	P		ED,ID		BD	00:00.0
2021 PO4865989883	LGE	H3		45 BRN	SP	P		ED,ID		BD	00:00.0
2021 PO4865289880	LGE	H3		45 BRN	SP	P		ED,ID		BD	00:00.0
2021 PO4864589876	LGE	H3		45 BRN	SP	P		ED,ID		BD	00:00.0
2021 PO4863989874	LGE	H3		45 BRN	SP	P		ED,ID		BD	00:00.0
2021 PO5694811573	LGE		3	45 BRN	SP	P		ED,ID		BD	00:00.0
2021 PO4722989946	LGE		3	45 ACE	SP	CCA				V	00:00.0
2021 PO5420521720	KU		3	45 BRN	SP	CCA				V	00:00.0
2021 PO5378021863	KU		3	45 BRN	SP	S				V	00:00.0
2021 PO5399521935	KU		3	45 BRN	SP	CCA				V	00:00.0
2021 PO5447621427	KU		2	50 BRN	SP	CCA				V	00:00.0
2021 PO5451321514	KU		3	45 BRN	SP	CRE		ID,IP		BD	00:00.0
2021 PO5431421604	KU		3	45 BRN	SP	CCA				V	00:00.0
2021 PO5392322007	KU		2	50 BRN	SP	CCA				V	00:00.0
2021 PO5408721750	F		4	40 BRN	SP	CRE				V	00:00.0
2021 PO5410921825	KU		3	45 BRN	SP	CCA				V	00:00.0
2021 PO5438221442	KU		3	45 BRN	SP	CRE		ID		BD	00:00.0
2021 PO5395421901	F		4	40 BRN	SP	CCA				V	00:00.0
2021 PO5388422049	KU		2	50 BRN	SP	CCA				V	00:00.0
2021 PO5386521952	KU		3	45 BRN	SP	CCA				V	00:00.0
2021 PO5441321494	KU		2	50 BRN	SP	CCA				V	00:00.0
2021 PO5391522087	KU		2	50 BRN	SP	CCA				V	00:00.0
2021 PO5398821867	F		4	40 BRN	SP	CCA				V	00:00.0
2021 PO5423321604	F		4	40 BRN	SP	CRE				V	00:00.0

2021 PO5415621685	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5433221498	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5405321795	F	4	40 BRN	SP	CRE	ED,ID	BX	RR	00:00.0
2021 PO5506819828	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO9954394477	ODP	5	35 BRO	SP	CCA		V		00:00.0
2021 PO9958794403	ODP	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9961194528	ODP	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9994994903	ODP	6	35 BRO	SP	CRE	ED,ID,RB	TX	RR	00:00.0
2021 PO9973894660	ODP	6	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO9959494617	ODP	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO9987194807	ODP	5	35 BRO	SP	CRE	ID	BD		00:00.0
2021 PO0014294908	ODP	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0010695083	ODP	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0025895254	ODP	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO0023395406	ODP	4	40 BRO	SP	CCA		V		00:00.0
2021 PO0033695346	ODP	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7807442533	F	4	40 KOP	SP	CRE		V		00:00.0
2021 PO7809042335	ODP	5	45 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO0207933459	ODP	6	30 KOP	SP	CRE		BD		00:00.0
2021 PO8027944269	ODP	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO8038944288	ODP	4	50 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO8043944334	ODP	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8046744302	ODP	6	30 BRN	SP	CRE		V		00:00.0
2021 PO8064544342	F	4	45 BRN	SP	CRE		V		00:00.0
2021 PO8066144280	ODP	4	45 BRN	SP	CCA		V		00:00.0
2021 PO8059944262	ODP	4	45 BRN	SP	CCA		V		00:00.0
2021 PO8054244247	ODP	5	30 BRN	SP	CCA		V		00:00.0
2021 PO8034844202A	ODP	6	30 BRN	SP	CCA		V		00:00.0
2021 PO8034844202	ODP	6	30 BRN	SP	CCA		V		00:00.0
2021 PO8055843987	ODP	4	40 BRN	SP	CCA		V		00:00.0
2021 PO8046444230	ODP	2	50 BRN	SP	CCA		V		00:00.0
2021 PO8043643909	ODP	6	30 BRN	SP	CCA		V		00:00.0
2021 PO8069444147	F	4	40 BRN	SP	CCA		V		00:00.0
2021 PO0189733245	ODP	5	35 KOP	SP	CCA	ED	V		00:00.0
2021 PO7806542491	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4862889868	LGE	4	30 BRN	SP	P	ED,ID,IP,RB	X	RP1	00:00.0
2021 PO4862089864	LGE	3	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4860489856	LGE	3	45 BRN	SP	CRE	ED,ID	BD		00:00.0
2021 PO4724289971	LGE	4	40 ACE	SP	CCA		V		00:00.0
2021 PO6929941692	ODP	4	45 BRN	SP	CCA	ED,ID	TD		00:00.0
2021 PO6964441632	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6962541769	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6960841875	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4932688723	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO0225532077	ODP	4	45 KOP	SP	CCA	ED,SRC	T		00:00.0
2021 PO0201132718	ODP	4	45 KOP	SP	CRE		BD		00:00.0
2021 PO4724789968	LGE	4	30 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4723689959	LGE	3	45 ACE	SP	P	ED,ID	BD		00:00.0
2021 PO4722689938	LGE	4	30 ACE	SP	CCA		V		00:00.0
2021 PO4933288735	LGE	3	45 BRO	SP	CRE	ID,IP	BD		00:00.0
2021 PO0191532827	ODP	5	35 KOP	SP	CRE	ED,SRS	TD		00:00.0
2021 PO0182133069A	ODP	3	45 KOP	SP	S		V		00:00.0
2021 PO8062543908	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO8055143813	ODP	4	40 BRN	SP	CCA		V		00:00.0

2021 PO8075743927	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7768042014	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7766742176	ODP	5	30 KOP	SP	CRE		V	00:00.0
2021 PO7763142096A	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7763142096	ODP	4	45 KOP	SP	CCA		V	00:00.0
2021 PO7754442118	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7751442059	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO0182133069	ODP	3	45 KOP	SP	CCA		V	00:00.0
2021 PO0156732688	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO0154432859	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO0193033037	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4933788745	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7753041819	ODP	5	35 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7755841646	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7751341700	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7737441595	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO4936788748	F	4	40 BRO	SP	A		V	00:00.0
2021 PO5358621680	KU	2	40 BRN	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021 PO5307222162	KU	4	40 BRN	SP	CRE	ID	BD	00:00.0
2021 PO8057343599	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4721989917	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO8057343707	ODP	4	45 OTH	SP	CCA		V	00:00.0
2021 PO8042143613	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO7755841646A	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7748141210	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7780041445	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7775241579	ODP	4	40 KOP	SP	CRE	ID	TD	00:00.0
2021 PO7794541648	ODP	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7810241692	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7823341924	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7829041760	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7836441615	ODP	4	45 KOP	SP	CCA		V	00:00.0
2021 PO7837841726	ODP	5	30 KOP	SP	CCA		V	00:00.0
2021 PO8085843706	ODP	5	30 OTH	SP	CCA		V	00:00.0
2021 PO8083643667	F	4	40 OTH	SP	P		V	00:00.0
2021 PO8078843636	ODP	6	30 OTH	SP	CCA		V	00:00.0
2021 PO8064343504A	ODP	6	30 OTH	SP	CCA		V	00:00.0
2021 PO8089143539	ODP	4	40 OTH	SP	CCA		V	00:00.0
2021 PO8064343504	ODP	4	45 OTH	SP	CCA		V	00:00.0
2021 PO4722289925	LGE	4	30 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO4721889899	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4708789750	F	4	30 ACE	SP	P		V	00:00.0
2021 PO4708489744	F	4	40 ACE	SP	P		V	00:00.0
2021 PO8169343509	F	5	45 OTH	SP	P		V	00:00.0
2021 PO8143443320	ODP	6	30 OTH	SP	CCA		V	00:00.0
2021 PO8138843460	F	4	45 OTH	SP	CCA		V	00:00.0
2021 PO8124543516	ODP	5	30 OTH	SP	CCA		V	00:00.0
2021 PO8099543550	ODP	6	30 OTH	SP	CCA		V	00:00.0
2021 PO8102243535	F	4	40 OTH	SP	P		V	00:00.0
2021 PO4934288753	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5552119895	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO5541520006	F	4	35 OTH	SP	P		V	00:00.0
2021 PO8117443427	ODP	4	40 OTH	SP	CCA		V	00:00.0
2021 PO8169743371	ODP	6	30 OTH	SP	CCA		V	00:00.0

2021 PO4928289500	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO0048195200	ODP	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO8010345382	ODP	5	35 ACW	SP	CRE	ID	BD	00:00.0
2021 PO7942245292	ODP	4	45 ACW	SP	CRE	ID	BD	00:00.0
2021 PO7974745412	ODP	3	45 ACW	SP	CCA		V	00:00.0
2021 PO7989945342	ODP	5	35 ACW	SP	CRE	ID	BD	00:00.0
2021 PO7924745783	ODP	5	30 BRN	SP	CRE	ID	BD	00:00.0
2021 PO8027645562	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8028645422	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5601420440	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5599119820	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5552222171	KU	5	35 BRN	SP	S		V	00:00.0
2021 PO7318155151	ODP	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7324455300	ODP	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7294155275	ODP	4	40 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO7268154979	ODP	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7225950347	ODP	5	35 KOP	SP	CRE	ED	TD	00:00.0
2021 PO6903547621	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO6908047340b	KU	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6908047340a	KU	3	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4314086988	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO6908047348	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4314386986	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO5736793256	F	4	45 BRN	SP	CRE		V	00:00.0
2021 PO5739293529	F	3	45 BRN	SP	CCA		V	00:00.0
2021 7347248458A	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7347248458	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO7335348481	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7318848514	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO7172349365	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO5732992663	F	4	30 BRN	SP	CRE		V	00:00.0
2021 PO5727892736	F	4	40 BRN	SP	P		V	00:00.0
2021 PO5722592873	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5742192553	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5752292469	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO6480948437	KU	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5096784883	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5768494879	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5712195203	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5786094497	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5779294358	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4786890728	LGE	3	45 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021 PO3782896164	KU	2	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO3777295984	KU	2	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO4789090735	LGE	3	45 BRN	SP	A	ID	BD	00:00.0
2021 PO5773094231	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5764794057A	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5764794057	KU	2	50 BRN	SP	A		V	00:00.0
2021 PO4793991014	LGE	6	35 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO5796494722	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5793794650	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5782494800	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5754894957	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4794291031	LGE	6	30 BRN	SP	CRE	ED,HH,ID,RB	X	00:00.0
							RP1	

2021 PO4795490978	LGE	3	45 BRN	SP	CCA	ED	T	00:00.0
2021 PO0016182007A	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0016182007	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9989182024	KU	5	30 BRO	SP	S		V	00:00.0
2021 PO5740595040	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5726695120	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5697495288	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5682395374	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5667495460	F	2	50 BRN	SP	CCA		V	00:00.0
2021 PO3966097517	KU	3	50 BRN	SP	S		V	00:00.0
2021 PO4366385401	LGE	4	35 BRN	SP	CRE		V	00:00.0
2021 PO4368785393	LGE	H1	75 BRN	SP	CRE		V	00:00.0
2021 PO4366885367-a	LGE	4	35 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4366885367-a	LGE	4	35 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4366885367	LGE	H1	75 BRN	SP	CRE		V	00:00.0
2021 PO4375085340	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4374685345	LGE	4	25 BRN	SP	A	ED,ID	V	00:00.0
2021 PO7117247903	KU	4	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO7116747787	KU	5	35 BRO	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7116347688	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO7127748073	KU	4	45 BRO	SP	S		V	00:00.0
2021 PO3820103154	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO3814102482	KU	3	50 BRN	SP	CCA		V	00:00.0
2021 PO7203547281	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4494898119	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4498398336	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4921291394	LGE	4	35 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4925291410	LGE	4	35 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4929091426	LGE	4	35 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4933191442	LGE	4	35 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4447586232	LGE	H1	80 BRN	SP	CRE		V	00:00.0
2021 PO7381846734	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5633493824	F	3	40 BRN	SP	CRE		V	00:00.0
2021 PO4329186965	LGE	4	40 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO4458786090	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO6575549072	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6587449020	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6600948962	KU	3	50 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6596448855	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6601348975	KU	3	50 BRN	SP	CCA		V	00:00.0
2021 PO7043747268	KU	4	40 XXX	SP	CRE	ID	BD	00:00.0
2021 PO6581248378	F	5	40 BRN	SP	P		V	00:00.0
2021 PO6585748548	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6570448503	KU	1	75 BRN	SP	CRE		V	00:00.0
2021 PO6581548432	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6588948380	KU	1	75 BRN	SP	CRE	IP	BD	00:00.0
2021 PO6594948341	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4457586097	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4470698333	F	3	45 BRO	SP	CRE	ED	V	00:00.0
2021 PO8139087368	KU	4	45 UNK	SP	CRE	ED	BX	RP2 00:00.0
2021 PO7976088214	KU	5	35 UNK	SP	CRE	ED,ID,RB	X	PX 00:00.0
2021 PO7933889317	KU	4	40 UNK	SP	CRE	ED	BX	PX 00:00.0
2021 PO7943189736	KU	4	40 UNK	SP	CRE	ED,HH,ID,RB	X	PX 00:00.0
2021 PO7498880973	KU	1	80 UNK	WC	P		V	00:00.0

2021 PO8005288236	KU	5	35 UNK	SP	CRE	ID	BD	00:00.0
2021 PO5947391483	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5941991342	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5936491201	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5930491061	F	3	45 XXX	SP	P		V	00:00.0
2021 PO5928691015	KU	3	45 XXX	SP	P		V	00:00.0
2021 PO5924490909	F	3	40 XXX	SP	P		V	00:00.0
2021 PO5920790817	KU	3	45 XXX	SP	P		V	00:00.0
2021 PO6480849150	KU	3	45 BRN	SP	CRE	ID,IP	BD	00:00.0
2021 PO6795349893	KU	5	30 BRN	SP	CCA		V	00:00.0
2021 PO7023747784	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6685849177	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO7341648193A	KU	6	30 BRO	SP	P	ED,ID,IP	TD	00:00.0
2021 PO5089984933	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO6439547927	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6498047922	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO6488347906	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO3670096846	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO3677497097	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO3668696796	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3682797268	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO7676147211	KU	6	30 UNK	SP	CRE		V	00:00.0
2021 PO7676947292	KU	5	35 UNK	SP	CRE		V	00:00.0
2021 PO5103784972	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8174863404	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5100885022	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO3724396974	F	5	35 BRN	SP	CCA		V	00:00.0
2021 PO3808096612	F	2	40 BRN	SP	CRE		V	00:00.0
2021 PO3987098901	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO3962598969	KU	4	45 BRN	SP	S		V	00:00.0
2021 PO3811596743	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO3837996630	KU	5	35 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7608047813	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO5108485397	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5107485414	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5106385431	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5104085435	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5102185428	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5100985423	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO7589247865	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO3929393729	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3948394295	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3920893473	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3727698925	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO3889192529	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3908193108	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3939494024	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3709798319	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO3716998611	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO3913893265	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3703798087	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO3733699231	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO3957594543	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO3898592805	KU	3	45 BRN	SP	CCA		V	00:00.0

2021 PO3892092621	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6823949578	KU	4	35 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6083350786	KU	6	30 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO6143850682	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6100950678	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO6099150775	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO7330448236	KU	4	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6811449672	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6809649516	KU	5	35 BRN	SP	CRE		BD	00:00.0
2021 PO6822649506	KU	5	35 BRN	SP	CRE		BD	00:00.0
2021 PO6814449511	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO6782449582	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO6788849474	KU	3	65 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6785649247	KU	2	60 BRN	SP	CRE		V	00:00.0
2021 PO6784449149	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4736589838	LGE	3	55 BRN	SP	CCA		V	00:00.0
2021 PO6092550882	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO6171450610	KU	4	45 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO6966547687	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7570547915	KU	4	50 BRO	SP	CCA		V	00:00.0
2021 PO7022047223	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7343048083	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO8178387123	KU	4	40 UNK	SP	CRE	ID	BD	00:00.0
2021 PO4748689883	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4463785793	LGE	1	65 BRN	SP	CRE		V	00:00.0
2021 PO4463885794	LGE	1	65 BRN	SP	CRE		V	00:00.0
2021 PO4748489889	LGE	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO6501747787	KU	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO6554447579	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO7113148177	KU	2	60 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4374085774	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4376385770	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4377285756	LGE	5	30 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4377185759	LGE	4	40 BRN	SP	CCA	ED	V	00:00.0
2021 PO4376185748	LGE	2	45 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7107148180	KU	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO7115448357	KU	2	70 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO7016140739	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4031499610	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4761689875-a	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4697811832	LGE	4	40 BRN	SP	CCA	ED	BD	00:00.0
2021 PO4465485822	LGE	3	45 BRN	SP	A	ED,ID,IP	TD	00:00.0
2021 PO4464885823	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4031499610A	KU	3	55 BRN	SP	CCA		V	00:00.0
2021 PO6628047645	KU	6	30 KOP	SP	CCA		V	00:00.0
2021 PO6617447803	KU	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7022446773	KU	5	35 XXX	SP	CRE	ID	BD	00:00.0
2021 PO7029446776	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO7036846851	F	5	35 XXX	SP	CRE		V	00:00.0
2021 PO7041746900A	KU	5	35 XXX	SP	P	ED,ID	TD	00:00.0
2021 PO7041946950	KU	5	35 XXX	SP	CRE	ID	TD	00:00.0
2021 PO8226286819	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8287086600	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4759589898	LGE	4	40 BRN	SP	CCA		V	00:00.0



2021 PO7113549357	KU	5	30 UNK	SP	CRE	ED,ID,RB	X	RP2	00:00.0
2021 PO4810790286	LGE	4	35 BRN	SP	A	ED,ID,IP,RB	X	RP1	00:00.0
2021 PO7161849097	F	5	35 KOP	SP	CCA		V		00:00.0
2021 PO7170449190	KU	4	45 BRO	SP	CRE	ED,ID	X	RP2	00:00.0
2021 PO3799604150	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO4813690079	LGE	4	40 BRN	SP	A	ID	BD		00:00.0
2021 PO7116349291	KU	4	45 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO7115749314	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO7113249333	KU	5	30 UNK	SP	CRE	ID	BD		00:00.0
2021 PO3840904498	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3804404424	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3811104267	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO3821304535	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3833304513	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO3850304424	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO3801804284	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO4801790406	LGE	3	50 BRN	SP	A	ID,IP	BD		00:00.0
2021 PO0971671276	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO0946570816	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO0954870707	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO0961270892	KU	3	45 BRO	SP	S		V		00:00.0
2021 PO0980671270	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO0973471387	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO0985771413	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO0994271336	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO1007271379	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO1007371538	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO1007371688	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO4909319544	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO4784490651	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO4784690648	LGE	4	30 BRN	SP	CCA		V		00:00.0
2021 PO7110449377	KU	6	30 BRO	SP	CCA		V		00:00.0
2021 PO7107849452	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO3807004561	F	2	40 BRN	SP	CRE		V		00:00.0
2021 PO3841804609	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO7157749214	KU	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4795990588	LGE	2	60 BRN	SP	CCA		V		00:00.0
2021 PO4795490556	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4795690573	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7089846829A	KU	4	40 BRO	SP	P	ED,ID	TD		00:00.0
2021 PO3701997798	KU	3	40 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO3697897833	KU	3	45 BRN	SP	CRE	ED,ID,IP	BD		00:00.0
2021 PO4796590568	LGE	2	60 BRN	SP	CCA		V		00:00.0
2021 PO4799190399	LGE	4	35 BRN	SP	CCA		V		00:00.0
2021 PO4791891057	LGE	4	40 BRN	SP	CCA		V		00:00.0
2021 PO5527893118	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5524093166	F	2	45 BRN	SP	CRE		V		00:00.0
2021 PO5517193197	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6521228069	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO6836040001	F	4	40 BRO	SP	P	ED,ID	V		00:00.0
2021 PO4750289897	LGE	3	45 BRN	SP	CCA		V		00:00.0
2021 PO7130548330	KU	3	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021 PO7124948273	KU	5	35 BRO	SP	CCA		V		00:00.0
2021 PO7134948435	KU	6	30 BRO	SP	CRE	ED,ID	BD		00:00.0

2021 PO6707209348	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO7843116037	ODP	6	30 XXX	SP	S		V	00:00.0
2021 PO6687909472	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO7841216086	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO7823116417	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO8718921833	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO8702021735	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4712589856	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO8694422035	ODP	5	35 KOP	SP	CCA		V	00:00.0
2021 PO9618624235	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO5387709000	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4821388754	LGE	4	30 BRO	SP	P		V	00:00.0
2021 PO4979089750	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4979289742	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO6877310494	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO0486638920	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4823488806	LGE	4	30 BRO	SP	CRE		V	00:00.0
2021 PO4816488848	LGE	4	30 BRO	SP	P		V	00:00.0
2021 PO4816088857	LGE	3	80 BRO	SP	P		V	00:00.0
2021 PO4815288853	LGE	3	75 BRO	SP	CRE		V	00:00.0
2021 PO4817888858	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO8698122102	ODP	3	45 KOP	SP	CCA		V	00:00.0
2021 PO5309510410	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5404108938	KU	3	45 BRN	SP	CRE		V	00:00.0
2021 PO7617519910	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4850389338	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4707789927	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4708689912	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4709589897	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO7814522073	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO7802022318	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4710389883	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4828089564	LGE	3	50 BRN	SP	CCA	ED	V	00:00.0
2021 PO4824989554	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4848589331	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4950490088	F	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4951190077	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4943790155	F	4	25 BRN	SP	CCA		V	00:00.0
2021 PO4712389946	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4711389937	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4711789920	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4715089927	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4712589907	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4714089920	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7977521242	F	5	35 UNK	SP	P		V	00:00.0
2021 PO8025221810	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8365919763	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5499620988	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO7763644845	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO7775844516	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO0232433173A	ODP	4	40 XXX	SP	P		V	00:00.0
2021 PO7545144253	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO0524639097	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4915388908	F	4	40 BRO	SP	A		V	00:00.0

2021 PO491588891	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4812788746	LGE	3	50 BRO	SP	P		V	00:00.0
2021 PO7442743193	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7432243053	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO7449543050	ODP	4	45 KOP	SP	CRE		V	00:00.0
2021 PO4925189998	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4926690003	LGE	3	45 BRN	SP	A		V	00:00.0
2021 PO4928290008	LGE	3	50 BRN	SP	A		V	00:00.0
2021 PO4929890013	LGE	3	45 BRN	SP	A		V	00:00.0
2021 PO4905989933	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4906889936	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4907489939	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4908789943	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4910689949	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4912489956	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4914289962	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO4915989961	LGE	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4915989967	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4917689973	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021 PO4919489979	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4921389985	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO4923289991	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO4859390088	LGE	4	40 BRN	SP	P	ED	V	00:00.0
2021 PO4967389491	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4867789971	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4714989866	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4716289854	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO2613039486	ODP	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4865788598	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO0621638856	ODP	2	50 OTH	SP	CCA		V	00:00.0
2021 PO0618639120	ODP	4	45 OTH	SP	CCA		V	00:00.0
2021 PO0283438219AA	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0283438219A	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO0187237696	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5271306021	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO5265505886	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5578420120	KU	6	30 OTH	SP	CCA	IP	V	00:00.0
2021 PO7232319585	ODP	2	50 BRO	SP	CCA		V	00:00.0
2021 PO8855022653	ODP	4	40 BRO	SP	CRE		V	00:00.0
2021 PO7406542971	ODP	2	50 KOP	SP	CCA		V	00:00.0
2021 PO4931390018	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO4931890002	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO4932389991	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO7483943218	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO4718389835	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4718089830	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4718889816	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4719189820	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4719789800	F	4	30 ACE	SP	CRE		V	00:00.0
2021 PO4719989807	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4720989790	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4721589780	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4717489849	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4975689801	LGE	4	40 ACE	SP	CCA		V	00:00.0

2021 PO4943490172	LGE	3	45 BRN	SP	A		V	00:00.0
2021 PO4943590178	LGE	3	45 BRN	SP	A		V	00:00.0
2021 PO7502843351	ODP	4	40 KOP	SP	CCA		V	00:00.0
2021 PO6507115167	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5478221246	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO5504520850	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO6846310990	LGE	3	45 ACE	SP	S		V	00:00.0
2021 PO4947690083	F	5	40 BRN	SP	A		V	00:00.0
2021 PO7051554217	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4809988745	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4811488746	LGE	5	50 BRO	SP	P		V	00:00.0
2021 PO5514720657	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO4807688740	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO5553920729	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO4949090061	F	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4948890050	LGE	4	30 BRN	SP	A		V	00:00.0
2021 PO4950290049	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4949690035	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4951190037	F	3	50 BRN	SP	CRE		V	00:00.0
2021 PO4950690043	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021 PO5491912515	KU	4	45 BRN	SP	S		V	00:00.0
2021 PO4729389827	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4728689838	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4838489338	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4831289538	LGE	4	30 BRN	SP	CRE		V	00:00.0
2021 PO4830689555	LGE	4	30 BRN	SP	CCA		V	00:00.0
2021 PO4830289556	LGE	1	70 BRN	SP	A		V	00:00.0
2021 PO4830589548	LGE	3	45 BRN	SP	P		V	00:00.0
2021 PO4830889539	LGE	H1	70 BRN	ST	P		V	00:00.0
2021 PO5557109314	LGE	1	55 BRN	SP	CCA		V	00:00.0
2021 PO9468628108	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO4968289503	LGE	3	50 ACE	SP	CCA		V	00:00.0
2021 PO5392508347	LGE	1	70 BRN	SP	CRE	ED,MD	V	00:00.0
2021 PO4733489828	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO9153725329	ODP	4	40 XXX	SP	CRE		V	00:00.0
2021 PO9396127397	ODP	6	30 XXX	SP	S		V	00:00.0
2021 PO6711118812	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8250119996	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8268420085	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4828589441	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO8157420713	ODP	4	45 UNK	SP	CRE		V	00:00.0
2021 PO4937789351	LGE	1	65E ACE	ST	S		V	00:00.0
2021 PO4731689857	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4846889160	LGE	3	50 BRN	SP	A		V	00:00.0
2021 PO4844289152	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO4841789143	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO4938089946	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO8187419909	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4977989585	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4900988952	LGE	4	40 BRO	SP	CCA		V	00:00.0
2021 PO5501907301	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5501907051	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5447411977	KU	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4938889932	LGE	4	40 BRN	SP	P		V	00:00.0

2021 PO4939689905	LGE	4	40 BRN	SP	P		V	00:00.0
2021 PO1039342548	ODP	5	35 BRO	SP	CCA		V	00:00.0
2021 PO4851689551	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO5304608455	F	3	50 BRN	SP	S		V	00:00.0
2021 PO4837489367	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO8236519677	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4937289007	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4719389951	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4965589447	LGE	1	75 ACE	SP	A		V	00:00.0
2021 PO5325008020	F	3	45 BRN	SP	A		V	00:00.0
2021 PO4719089930	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4964489430	LGE	1	70 ACE	SP	A		V	00:00.0
2021 PO4719189942	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4938489010	F	4	40 BRO	SP	A		V	00:00.0
2021 PO5480506792	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO5469806773	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO5461706754	LGE	4	40 BRN	SP	CCA		V	00:00.0
2021 PO4926989373	LGE	3	45 ACE	UN	CCA		V	00:00.0
2021 PO4929389368	LGE	3E	45 ACE	UN	CCA		V	00:00.0
2021 PO4718989918	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4716289906	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4717489912	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4715889913	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4804088740	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4820788723	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4820788725	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO4829688751	LGE	4	30 BRO	SP	CCA		V	00:00.0
2021 PO4807788730	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4942689019	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9488932892	F	5	45 UNK	SP	CRE		V	00:00.0
2021 PO9449732845	F	5	45 UNK	SP	CRE		V	00:00.0
2021 PO4801988739	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO6803706825	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4972889360	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO9935735935	F	4	40 OTH	SP	A		V	00:00.0
2021 PO4977789358	LGE	3	45 ACE	SP	A	ED,ID	V	00:00.0
2021 PO1224443663	ODP	4	45 BRO	SP	CCA		V	00:00.0
2021 PO8066119708	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021 PO5490107058	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO5490006908	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO4933189873	LGE	4	35 BRN	SP	P		V	00:00.0
2021 PO4939989013	F	4	40 BRO	SP	A		V	00:00.0
2021 PO4941389016	F	3	45 BRO	SP	CCA		V	00:00.0
2021 PO8224419915	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO8222420034	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4867388622	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5314408895	KU	3	45 BRN	SP	S		V	00:00.0
2021 PO5305408638	KU	4	45 BRN	SP	S		V	00:00.0
2021 PO8764021990	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4869488614	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4870288613	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO1100042985	ODP	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4917588853	F	4	40 BRO	SP	A		V	00:00.0
2021 PO6436918180	F	4	40 KOP	SP	CRE		V	00:00.0

2021	PO6418718186	F	4	40 KOP	SP	CRE		V	00:00.0
2021	PO6404718191	F	4	40 KOP	SP	CRE		V	00:00.0
2021	PO6391018193	F	4	40 KOP	SP	CRE		V	00:00.0
2021	PO6374018214a	ODP	4	45 KOP	SP	CRE		V	00:00.0
2021	PO6374018214	F	4	40 XXX	SP	CRE		V	00:00.0
2021	PO4980289354	LGE	3	45 ACE	SP	A	ED,ID,IP	V	00:00.0
2021	PO4718390023	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO4709990033	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021	PO8941822889	F	4	40 BRO	SP	CRE		V	00:00.0
2021	PO9811034919	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021	PO4985289348	LGE	5	35E ACE	UN	CCA		V	00:00.0
2021	PO4985289346	LGE	3	45 ACE	SP	A	ED,ID,IP	V	00:00.0
2021	PO4988589339	LGE	3	45 ACE	SP	A	ED,ID	V	00:00.0
2021	PO4991289333	LGE	3	45 ACE	SP	A	ED,ID	V	00:00.0
2021	PO8056319454	F	4	40 BRN	SP	CRE		V	00:00.0
2021	PO4982589349	LGE	3	45 ACE	SP	A		V	00:00.0
2021	PO5460512553	KU	4	45 BRN	SP	CCA		V	00:00.0
2021	PO5462312544	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO7310919706	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021	PO4948489529	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021	PO4928288770	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO9123123449	ODP	6	30 BRO	SP	A		V	00:00.0
2021	PO4945089013-A	KU	4	40 BRO	SP	A		V	00:00.0
2021	PO6360808491	LGE	2	55 BRO	SP	CCA		V	00:00.0
2021	PO7907619859	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021	PO7907620105	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5409112577	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5414012662	KU	3	45 BRN	SP	S		V	00:00.0
2021	PO5530012456	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO5499503238	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO5542612272	KU	3	45 BRN	SP	CCA		V	00:00.0
2021	PO5551512232	KU	2	50 BRN	SP	CCA		V	00:00.0
2021	PO5471203463	LGE	1	55 BRN	SP	CCA		V	00:00.0
2021	PO5490603418	LGE	1	50 BRN	SP	CCA		V	00:00.0
2021	PO8849522404	ODP	5	35 KOP	SP	CRE		V	00:00.0
2021	PO5600819892	KU	4	40 BRN	SP	CCA		V	00:00.0
2021	PO5424713251	KU	5	35 BRN	SP	CCA		V	00:00.0
2021	PO7940243511A	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4725889890	LGE	4	35 ACE	SP	P	ED,ID	BD	00:00.0
2021	PO7983344206	ODP	2	50 BRN	SP	CCA		V	00:00.0
2021	PO8007844208	ODP	6	30 BRN	SP	CCA		V	00:00.0
2021	PO7996544191	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021	PO8001644136	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4881089888	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021	PO5885711903	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021	PO4928488647	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021	PO7319442343	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0
2021	PO7349042108	ODP	4	40 KOP	SP	CRE		T	00:00.0
2021	PO4882189868	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO5901511659	LGE	3	45 BRN	SP	CRE		V	00:00.0
2021	PO4883289850	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021	PO8077544993	ODP	3	45 XXX	SP	S		V	00:00.0
2021	PO8060144946	ODP	4	40 XXX	SP	CRE	ED,ID,IP	BD	00:00.0
2021	PO8072844981	ODP	5	35 XXX	SP	CRE		V	00:00.0

2021 PO8099045118	ODP	3	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8098645045	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO8106745072	ODP	4	45 XXX	SP	S		V	00:00.0
2021 PO8122345112	F	4	40 XXX	SP	P		V	00:00.0
2021 PO7987044141	ODP	6	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO7990444041	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8026443926	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8009843875A	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8027843862	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8016643776	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8009843875	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8000443687	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7998543837	ODP	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7993643960	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO7392442302	ODP	4	35 KOP	SP	CRE	ED	T	00:00.0
2021 PO7402242441	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7369442127	ODP	4	45 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7392442303	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO5909811535	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4883789841	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO7063941290	ODP	2	55 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7041041270	ODP	2	70 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO7380342297	ODP	5	30 KOP	SP	CCA		V	00:00.0
2021 PO7385842169	ODP	4	45 KOP	SP	CCA		V	00:00.0
2021 PO7407542217	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4927988637	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4927488628	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4711289733	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO7430842268	ODP	4	45 KOP	SP	S		V	00:00.0
2021 PO5534321579	KU	3	45 KOP	SP	CCA		V	00:00.0
2021 PO7402242441	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO7458942282	ODP	4	45 KOP	SP	CCA		V	00:00.0
2021 PO9690992184	F	4	40 KOP	SP	CRE	ED	V	00:00.0
2021 PO9679792185	F	4	40 KOP	SP	CRE	ED	V	00:00.0
2021 PO9718992425	ODP	5	30 KOP	SP	CCA		T	00:00.0
2021 PO9704992318	ODP	4	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO9756392425A	ODP	6	30 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO9731292572	ODP	6	30 KOP	SP	CRE	ED,ID	BD	00:00.0
2021 PO9694492182	ODP	2	50 KOP	SP	CCA		V	00:00.0
2021 PO7455542328	ODP	4	45 KOP	SP	S		V	00:00.0
2021 PO9693492269	ODP	5	35 KOP	SP	CCA		V	00:00.0
2021 PO9704992318	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO9723592377	ODP	3	50 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO9756392425	ODP	4	40 BRO	SP	CCA		T	00:00.0
2021 PO9735392416	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9787092746	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9769192501	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9804192986	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9818893185	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9833193290	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9854793510	ODP	6	30 BRO	SP	CCA		V	00:00.0
2021 PO9900093908	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9850393398	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9865593510	F	4	40 BRO	SP	CRE		V	00:00.0

2021 PO9888193647	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9889793783	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO9917094194	ODP	4	40 BRO	SP	CCA		T	00:00.0
2021 PO9924009241	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9930094097	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9924094241	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9950594061	ODP	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9959794150	ODP	6	30 BRO	SP	CRE	ID	BD	00:00.0
2021 PO9944094243	F	4	40 BRO	SP	CCA		V	00:00.0
2021 PO9938894308	ODP	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0005194817	ODP	5	35 BRO	SP	CRE	ED,ID	BD	00:00.0
2021 PO4884189832	LGE	3	50 BRN	SP	CCA		V	00:00.0
2021 PO4883489808	LGE	4	35 BRN	SP	CCA		V	00:00.0
2021 PO4884689803	LGE	4	30 BRN	SP	A		V	00:00.0
2021 PO4886389807	LGE	3	50 BRN	SP	P		V	00:00.0
2021 PO4885489812	LGE	3	55 BRN	SP	A		V	00:00.0
2021 PO4884389831	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4885089820	LGE	3	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO7807443966	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7480242340	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7492442544	ODP	5	35 KOP	SP	CRE		T	00:00.0
2021 PO7474642453	ODP	6	30 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO7497042401	ODP	4	45 KOP	SP	S		V	00:00.0
2021 PO7515842470	ODP	2	50 KOP	SP	S		V	00:00.0
2021 PO7532642635	ODP	4	40 KOP	SP	CRE	ED,SRC	TD	00:00.0
2021 PO5458821047	KU	4	40 OTH	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO4730490023	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO5471221697	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4705889700	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4883589871	LGE	4	40 BRN	SP	P	ED,ID,MD,RB	X	RP1 00:00.0
2021 PO4885689832	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO5485120750	KU	6	30 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4705689704	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4706989770	F	4	40 ACE	SP	P		V	00:00.0
2021 PO7638843262	ODP	4	40 KOP	SP	CRE	ED	T	00:00.0
2021 PO5490822538	KU	3	45 BRN	SP	CCA	ED,SRC	T	00:00.0
2021 PO7594142854	ODP	2	55 KOP	SP	CRE	ED	T	00:00.0
2021 PO7579742859	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO7016341258	ODP	2	50 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7977543040	ODP	4	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5996011329	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5995711287	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO7790644040	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7785144025	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO7765344074	ODP	5	45 BRN	SP	CCA		V	00:00.0
2021 PO7783343674	ODP	4	40 BRN	SP	CRE	ID	TD	00:00.0
2021 PO7772543717	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7759843816	ODP	4	40 BRN	SP	CCA		V	00:00.0
2021 PO7762443751	F	5	35 BRN	SP	CRE		V	00:00.0
2021 PO7757843729	ODP	6	30 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO5482922619	KU	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO8131945399	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8124245343	ODP	5	35 XXX	SP	S		V	00:00.0
2021 PO8130345329	ODP	4	40 XXX	SP	CRE	ED,ID	TD	00:00.0



2021 PO5487420703	KU	4	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4704689721	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO6972941211	ODP	2	50 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6926241267b	ODP	3	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO6926241267a	ODP	3	45 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7560843268	ODP	4	40 KOP	SP	CRE	ED,SRS	TD	00:00.0
2021 PO7546143213	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7986342810	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO5494320624	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4945188896	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7717843014	ODP	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7707242849	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7729642724	ODP	5	35 KOP	SP	CCA	ID	BD	00:00.0
2021 PO7732042903	ODP	6	30 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7721342881	ODP	5	35 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7725643189	F	4	40 KOP	SP	CRE		V	00:00.0
2021 PO4869589900	LGE	4	40 BRN	SP	A		V	00:00.0
2021 PO4870189903	LGE	3	50 BRN	SP	A		V	00:00.0
2021 PO5485620646	F	5	35 BRN	SP	CCA		V	00:00.0
2021 PO4943988910	LGE	4	35 BRO	SP	CRE	ED,EP,HH,ID,RB	X	RP1 00:00.0
2021 PO4870489943	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4871789931	LGE	4	40 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4872989920	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO7998443081	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5594622174	F	2	55 BRN	SP	A		V	00:00.0
2021 PO5347621924	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO5388720238	KU	6	30 BRN	SP	CRE		V	00:00.0
2021 PO5468822248	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5456922132	F	4	40 BRN	SP	CRE	ID,RB	BX	RP2 00:00.0
2021 PO5477322332	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5587722261	F	2	55 BRN	SP	CRE		V	00:00.0
2021 PO4929988676	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5494420544	F	4	40 OTH	SP	CRE		V	00:00.0
2021 PO4925688595	LGE	3	50 BRO	SP	CCA		V	00:00.0
2021 PO5500220556	KU	3	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5508720553	KU	6	30 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8114145632	ODP	6	30 XXX	SP	CRE	ED,ID	TD	00:00.0
2021 PO8124245768	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8105246173	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4926288606	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO4926788615	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7752343295	ODP	4	40 KOP	SP	CRE	ID	BD	00:00.0
2021 PO7744743360	ODP	2	45 KOP	SP	CRE		V	00:00.0
2021 PO7569142839	ODP	6	30 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7549242722	ODP	5	35 KOP	SP	CCA		V	00:00.0
2021 PO7553142813	ODP	3	45 KOP	SP	CCA		V	00:00.0
2021 PO4729390013	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4728590007	LGE	4	35 ACE	SP	CCA		V	00:00.0
2021 PO4727489999	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO7759943109	ODP	4	40 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO5595522331	KU	5	35 BRO	SP	S		V	00:00.0
2021 PO7766542945	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7756242890	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7755442984	ODP	6	30 KOP	SP	CCA		V	00:00.0

2021 PO5504420432	F	4	40 BRN	SP	S		V	00:00.0
2021 PO5507420468	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5512020451	KU	6	30 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7564242791	ODP	5	35 KOP	SP	CCA		V	00:00.0
2021 PO7990644337	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7996044155	ODP	4	40 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8011144338	F	4	40 BRN	SP	P		V	00:00.0
2021 PO8008844403	ODP	6	35 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8025744464	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO8028644505	ODP	6	30 BRN	SP	CRE	ED,ID	V	00:00.0
2021 PO8035344427	F	4	40 BRN	SP	P		V	00:00.0
2021 PO7580643341	ODP	4	40 KOP	SP	CRE	ED	TD	00:00.0
2021 PO7596443272	ODP	6	30 KOP	SP	CRE		V	00:00.0
2021 PO7610043312	ODP	6	30 KOP	SP	CRE	ED	BD	00:00.0
2021 PO7584743086	ODP	2	50 KOP	SP	CCA		V	00:00.0
2021 PO7799842461	ODP	4	40 KOP	SP	CRE	ID,IP	BD	00:00.0
2021 PO5508520360	KU	5	35 OTH	ST	CCA		V	00:00.0
2021 PO5507220400	KU	6	30 BRN	SP	CCA		V	00:00.0
2021 PO7778842398	ODP	6	30 KOP	SP	CCA	ED,ID,IP	TD	00:00.0
2021 PO5523720289	KU	6	35 OTH	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7768242872	ODP	6	30 KOP	SP	CRE	ED,ID	TD	00:00.0
2021 PO7974744726	ODP	6	30 XXX	SP	CRE		V	00:00.0
2021 PO4915088966	F	5	25 BRO	SP	CRE		V	00:00.0
2021 PO6645710681	LGE	1	50 BRN	SP	P	ED,ID,IP	BD	00:00.0
2021 PO4956289753	LGE	2	50 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4965989734	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4964789724	LGE	3	45 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO7718743203	ODP	2	55 BRN	SP	CCA		V	00:00.0
2021 PO7718643360	ODP	6	30 KOP	SP	CCA		V	00:00.0
2021 PO7642942784	ODP	2	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7663242832	ODP	2	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7692042901	ODP	2	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO7707142970	ODP	3	50 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO4959389673	LGE	3	50 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO4949689708	LGE	1	65 BRN	SP	A	ED,ID	BD	00:00.0
2021 PO4788089050	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4789289043	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4790589036	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4791689028	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4793289027	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO4794289026	F	3	45 ACE	SP	CCA		V	00:00.0
2021 PO4795389031	F	3	50 ACE	SP	CCA		V	00:00.0
2021 PO4796689037	F	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4797989042	F	4	40 ACE	SP	CRE		V	00:00.0
2021 PO8128544718	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8127644740	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8118644712	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO8111444687	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8099244648	F	4	40 XXX	SP	CRE		V	00:00.0
2021 PO8094144806	ODP	6	30 XXX	SP	S		V	00:00.0
2021 PO8100144788	ODP	4	40 XXX	SP	S		V	00:00.0
2021 PO8108444900	ODP	5	35 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8112144875	ODP	6	30 XXX	SP	CRE	ED,ID	BD	00:00.0
2021 PO8116844828	ODP	5	30 XXX	SP	S		V	00:00.0

2021 PO8085344519	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8090544506	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO6948242797	ODP	4	40 BRN	SP	CCA	ED,ID	TD	00:00.0
2021 PO6964442827	ODP	5	30 BRN	SP	CCA	ED	T	00:00.0
2021 PO7528148177	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO5589921251	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8069045318	ODP	3	45 BRN	SP	CCA		V	00:00.0
2021 PO8071545212	ODP	4	40 BRN	SP	CRE	ED,ID	TD	00:00.0
2021 PO8077945227	ODP	6	30 BRN	SP	CRE	ED,ID	BD	00:00.0
2021 PO8083445241	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO8090545288	ODP	4	45 BRN	SP	CCA		V	00:00.0
2021 PO8054245175	ODP	4	40 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8044645162	ODP	4	40 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO5593121212	KU	2	50 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO7982946755A	ODP	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO5603921086	KU	2	50 BRN	SP	CRE	ED,ID,IP	BD	00:00.0
2021 PO8029646752A	ODP	5	35 BRN	SP	CRE	ID	BD	00:00.0
2021 PO80296465752B	ODP	5	35 BRN	SP	CRE	ID	TD	00:00.0
2021 PO4796189278	LGE	3	45 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO6959443050	ODP	4	40 BRN	SP	CCA	ED,ID,IP	TD	00:00.0
2021 PO6582488646	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6589488544	KU	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6231489084	KU	4	35 BRN	SP	CCA		V	00:00.0
2021 PO2200356700	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRS	TD	00:00.0
2021 PO2199556521	KU	5	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4234604286	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4271704081	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4253004183	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO0181457678	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO0198157722	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO0172557021	KU	4	40 UNK	SP	CRE	ED,ID	BD	00:00.0
2021 PO4963488545	LGE	2	55 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO1478474483	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO1459374489	KU	6	30 BRO	SP	S		V	00:00.0
2021 PO5005188227	LGE	4	40 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO5005988228	LGE	4	40 BRN	SP	P	ED,ID	TD	00:00.0
2021 PO5007988217	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO2237856819	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO2217356836	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2200356596	F	4	40 BRO	SP	CRE		V	00:00.0
2021 PO2225356605	F	4	40 BRO	SP	P		V	00:00.0
2021 PO2253356599	F	4	40 BRO	SP	P		V	00:00.0
2021 PO4969089370	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4967889373	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5008288220	LGE	3	45 BRN	SP	CCA	ED	T	00:00.0
2021 PO7186895361	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO5010588230	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4963288519	LGE	3	50 BRN	SP	A	ID,IP	BD	00:00.0
2021 PO6707698274	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4966789375	LGE	4	40 ACE	SP	A	ED	BD	00:00.0
2021 PO4966189376	LGE	3	45 ACE	SP	A	ED	BD	00:00.0
2021 PO4965589384	LGE	4	30 ACE	SP	CCA		V	00:00.0
2021 PO4964989381	LGE	1	50 ACE	SP	CCA		V	00:00.0
2021 PO6742406907	LGE	4	35 ACE	SP	CCA		V	00:00.0

2021 PO5012188373	LGE	4	30 BRN	SP	P	ED,ID	BD	00:00.0
2021 PO4961788512	LGE	3	45 BRO	SP	CCA		V	00:00.0
2021 PO6227089278	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO6240489401	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO6256189337	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO6274289250	KU	3	45 BRN	SP	CCA		V	00:00.0
2021 PO9578758215	KU	5	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO6214189149	KU	4	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO6211589108	KU	5	45 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4318587046	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4319487039	LGE	4	35 ACE	SP	A	ED	T	00:00.0
2021 PO4319987035	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4320387031	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4321087026	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4317587054	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO6013088813	KU	1	50 BRN	SP	CCA		V	00:00.0
2021 PO6010288699	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO1502672883	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO5032888528	LGE	3	50 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO1481372752	KU	3	45 BRO	SP	CRE		V	00:00.0
2021 PO9457958738	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO6006788567	KU	2	50 BRN	SP	CRE		V	00:00.0
2021 PO6002488431	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO5999288320	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO6005988255	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO6022288319	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO6037988386	KU	2	50 BRN	SP	CRE		V	00:00.0
2021 PO6052488450	KU	2	45 BRN	SP	CRE		V	00:00.0
2021 PO4041704754	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4039504900	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4313687215	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO1516071877	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4322186980	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4321386994	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4320887002	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4322786969	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4323386960	LGE	4	40 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4324586941	LGE	4	35 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4323986949	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4039705040	F	3	45 BRN	SP	CCA		V	00:00.0
2021 PO4321786986	LGE	4	40 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO7445399458	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5035088615	LGE	3	45 ACE	SP	CCA		V	00:00.0
2021 PO5039788642	LGE	3	50 ACE	SP	P		V	00:00.0
2021 PO6142388429	KU	3	40 BRN	SP	CRE	ED	TD	00:00.0
2021 PO4312787207	LGE	2	50 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO1570072304	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9770356483	F	6	30 UNK	SP	CRE		V	00:00.0
2021 PO9720956444	F	3	40 MAR	SP	P		V	00:00.0
2021 PO9740356420	F	3	40 MAR	SP	P		V	00:00.0
2021 PO9644655095	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9635055124	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9584754644	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO4091304671	F	4	40 BRN	SP	CRE		V	00:00.0

2021 PO4331387022	LGE	UNK	55 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4331087018	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO5048888736	LGE	4	35 BRN	SP	P		V	00:00.0
2021 PO5049388744	LGE	4	45 BRN	SP	P		V	00:00.0
2021 PO6175288463	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO6168888496	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO6171188468	KU	2	70 BRN	SP	CRE		V	00:00.0
2021 PO6168088465	KU	4	45 BRN	SP	CCA		V	00:00.0
2021 PO6174888602	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO6174888602A	F	2	30 BRN	SP	CCA		V	00:00.0
2021 PO6174688596	KU	2	50 BRN	SP	CCA		V	00:00.0
2021 PO4311987175	LGE	4	40 BRO	SP	CRE	ID,IP	BD	00:00.0
2021 PO4823090750	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO4823090774	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO4823190799	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO4823290823	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO5298021446	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO4823390847	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO6038351048	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO6035750907	KU	6	30 BRO	SP	CRE	ID	BD	00:00.0
2021 PO6032750943	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO6037150965	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO6030050820	KU	4	40 BRO	SP	CRE		BD	00:00.0
2021 PO4823590894	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO4823590917	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO5294922232	LGE	2	55 BRN	SP	CCA		V	00:00.0
2021 PO5552104738	F	4	40 BRN	SP	CRE	ED,ID,MD	VX	RP2 00:00.0
2021 PO6512290231	F	3	45 BRN	SP	CRE		V	00:00.0
2021 PO6514990262	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6506090524	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO1287474280	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1313674445	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1331974549	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1436174132	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4947688483	LGE	4	35 BRO	SP	CCA		V	00:00.0
2021 PO6585998089	F	4	35 BRO	SP	CCA		V	00:00.0
2021 PO1436174132A	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO1390374598	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO4310687016	LGE	2	55 ACE	SP	CCA		V	00:00.0
2021 PO4310387017	LGE	UNK	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4309287027	LGE	4	40 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO6470291471	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4324986969	LGE	4	35 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO1523672525A	KU	3	45 BRO	SP	S		V	00:00.0
2021 PO1523672525	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO5030688551	LGE	4	40 ACE	SP	CCA		V	00:00.0
2021 PO4321787022	LGE	4	30 ACE	SP	CRE	ED,ID	TD	00:00.0
2021 PO4323986986	LGE	5	35 ACE	SP	CCA		V	00:00.0
2021 PO5036788591	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO5035988577	LGE	3	45 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO5035088563	LGE	3	45 ACE	SP	P	ED,ID	BD	00:00.0
2021 PO5033588602	LGE	4	30 ACE	SP	CRE	RB	VX	RP1 00:00.0
2021 PO9441858749	KU	4	40 BRO	SP	CRE	ID	BD	00:00.0
2021 PO9440258542	KU	5	35 BRO	SP	CRE	ID	BD	00:00.0

2021 PO9732355722	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO6108088615	KU	3	40 BRN	SP	CRE	ED,MD	TX	RR	00:00.0
2021 PO4974888598	LGE	2	50 BRO	SP	A	ED,ID	TD		00:00.0
2021 PO1252076616	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO1277476607	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0
2021 PO6855899044	LGE	3	45 BRO	SP	CCA		V		00:00.0
2021 PO4055008779	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4036208601	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4077408989	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4068308909	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5005688326	LGE	4	30 BRN	SP	A	ED,ID,IP	BD		00:00.0
2021 PO5005888318	LGE	2	55 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO2093256654	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO6554189551	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6567589571	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6582289593	F	4	40 BRN	SP	CRE	ED	V		00:00.0
2021 PO6586589488	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6605989514	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6626189540	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO1949350291	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO1956050479	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO1950950643	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO5048189579	LGE	4	40 ACE	SP	A	ED,ID	TD		00:00.0
2021 PO0189561280	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO0173660975	KU	5	35 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO0154560662	KU	5	35 UNK	SP	CRE	ED,ID,IP	TD		00:00.0
2021 PO4971588573-A	KU	3	45 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO5004288310	LGE	2	55 BRN	SP	P	ED,ID	BD		00:00.0
2021 PO4308687031	LGE	UNK	55 ACE	SP	CRE	ED,IP	BD		00:00.0
2021 PO4307787039	LGE	2	55 ACE	SP	CCA		V		00:00.0
2021 PO9942458985	KU	4	40 KOP	SP	CRE	ED,ID	TD		00:00.0
2021 PO9943259305	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO9916159399	KU	4	40 UNK	SP	CRE	ED,ID	TD		00:00.0
2021 PO4266404535	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4273704495	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4281804447	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6457791090	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO6478891049	KU	3	45 BRN	SP	CCA		V		00:00.0
2021 PO1920351805	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO1899052011	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO6463991638	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6455991836	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6466091577	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6475891327	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO5650498603	F	4	40 XXX	SP	CRE		V		00:00.0
2021 PO5662598668	F	3	40 XXX	SP	P		V		00:00.0
2021 PO5673398729	F	4	40 XXX	SP	P		V		00:00.0
2021 PO6668489592	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO6688389615	F	3	45 BRN	SP	CRE		V		00:00.0
2021 PO6693189621	F	2	45 BRN	SP	P		V		00:00.0
2021 PO4971588573	LGE	3	45 BRO	SP	A	ID	BD		00:00.0
2021 PO4965188529	LGE	1	55 BRO	SP	A	ED,ID,IP	TD		00:00.0
2021 PO1359476755	KU	4	40 BRO	SP	CCA		V		00:00.0
2021 PO1390376491	KU	4	40 BRO	SP	CRE	ED,ID	TD		00:00.0

2021 PO1411076408	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1957450789	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO1944651014	KU	5	35 XXX	SP	CCA	ED	T	00:00.0
2021 PO1997350262	KU	4	40 XXX	SP	CRE	ID,IP	TD	00:00.0
2021 PO4312587005	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO2019750436	KU	4	40 XXX	SP	CRE	ID	TD	00:00.0
2021 PO6710590003	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6719090192	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6728590397	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6740190644	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO1429576265	KU	4	40 BRO	SP	P	ED,ID	TD	00:00.0
2021 PO1431976456	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 PO4967188538	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO4968588549	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO7097895518	LGE	2	60 BRN	SP	CCA		V	00:00.0
2021 PO7317297468	LGE	3	45 BRN	SP	CCA		V	00:00.0
2021 PO1425676042	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO1417576058	KU	4	40 BRO	SP	P		V	00:00.0
2021 PO1432376093	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO2151556522	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO2135056578	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO4313287014	LGE	4	40 ACE	SP	P	ED,ID	TD	00:00.0
2021 PO1319174696	KU	4	40 BRO	SP	CRE		V	00:00.0
2021 PO4955188497	LGE	3	45 BRO	SP	A	ID,IP	BD	00:00.0
2021 PO9838059364	KU	4	40 BRO	SP	CCA		V	00:00.0
2021 PO983859460	KU	6	30 BRO	SP	CCA		V	00:00.0
2021 PO9816559340	KU	4	40 UNK	SP	CRE		V	00:00.0
2021 PO6451090486	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6438190330	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4950288469	LGE	3	45 BRO	SP	A	ED,ID	TD	00:00.0
2021 PO6409289984	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6391889935	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6380989897	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6375789849	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6417890094	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9821759237	KU	5	45 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9809859006	KU	3	45 BRO	SP	CCA		V	00:00.0
2021 2170156591a	KU	5	35 BRO	SP	CCA		V	00:00.0
2021 PO5043089583	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO5043389588	LGE	4	40 ACE	SP	A		V	00:00.0
2021 PO6742190681	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6765090633	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6786890591	F	4	40 MAR	SP	P		V	00:00.0
2021 PO6808290543	F	3	45 MAR	SP	P		V	00:00.0
2021 PO6849590449	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO6835790531	KU	4	35 BRN	SP	CRE		BD	00:00.0
2021 PO6825690504	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO5039689594	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0
2021 PO1442375808	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO4179704342	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4082107274	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4954488456	LGE	3	50 BRO	SP	P	ED,ID,Src	TD	00:00.0
2021 PO4964388548	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	00:00.0
2021 PO5036789611	LGE	3	45 ACE	SP	A	ED,ID	TD	00:00.0

2021 PO5035089619	LGE	3	45 ACE	SP	A	ED,ID	BD	00:00.0
2021 PO2170156591	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO0127058581	KU	4	35 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO4632203047	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4628703422	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4621503105	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4609603169	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4616703485	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4642903362	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4658703314	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO4656502827	F	3	50 BRN	SP	CRE		V	00:00.0
2021 PO4644202982	F	4	40 BRN	SP	CRE		V	00:00.0
2021 PO9586756466	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9592456508	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9605362834A	KU	3	30 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9605362834	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9586659383	KU	3	45 OTH	SP	CCA		V	00:00.0
2021 PO9607759542	F	2	55 OTH	SP	CCA		V	00:00.0
2021 PO9572959145	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0
2021 PO9585362820	KU	5	45 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9419559148	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO9423159028	KU	2	55 BRO	SP	CCA		V	00:00.0
2021 PO9415059282	KU	6	30 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9607656564	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9583562845	KU	3	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9583562868	KU	3	50 BRO	SP	CRE	ED,ID	TD	00:00.0
2021 PO9583562890	KU	2	55 BRO	SP	CCA		V	00:00.0
2021 PO9410359177	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9407059221	KU	2	50 BRO	SP	CCA		V	00:00.0
2021 PO9417959319	KU	4	40 UNK	SP	CRE		V	00:00.0
2021 PO9405659083	KU	6	30 UNK	SP	CRE	ED,ID,IP	TD	00:00.0
2021 PO9622659690	F	2	45 OTH	SP	P		V	00:00.0
2021 PO9644959906	KU	4	45 OTH	SP	CCA		V	00:00.0
2021 PO9661560036	KU	4	45 OTH	SP	CCA		V	00:00.0
2021 PO9662860094	KU	5	35 OTH	SP	CRE		V	00:00.0
2021 PO9403258886	KU	4	45 BRO	SP	CCA		V	00:00.0
2021 PO9397659002	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO9387559122	KU	4	40 UNK	SP	CRE	ED,ID	TD	00:00.0
2021 PO2006505502	KU	3	45 ACE	SP	CRE		V	00:00.0
2021 PO1974005586	KU	3	45 ACE	SP	CRE		V	00:00.0
2021 PO1925205712	KU	3	45 ACE	SP	CRE		V	00:00.0
2021 PO1887405809	KU	3	45 ACE	SP	CRE		V	00:00.0
2021 PO1857805886	KU	3	50 ACE	SP	CRE		V	00:00.0
2021 PO1813805999	KU	4	40 ACE	SP	CRE		V	00:00.0
2021 PO1772606105	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO1741206186	KU	3	60 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO1697006300	KU	3	50 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO2047805396	KU	4	40 ACE	SP	CCA		V	00:00.0
2021 PO2086705296	KU	3	45 ACE	SP	CRE	ED,ID	BD	00:00.0
2021 PO4383299427	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4395199377	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4408199324	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4421199270	F	4	40 BRO	SP	CRE	ED	V	00:00.0
2021 PO4432899221	F	4	40 BRO	SP	CRE	ED	V	00:00.0



2021 PO4445699168	F	4	40 BRO	SP	CRE	ED	V	00:00.0	
2021 PO9036362252	KU	6	30 BRO	SP	S		V	00:00.0	
2021 PO9041262250	KU	4	40 BRO	SP	CCA		V	00:00.0	
2021 PO9027962188	KU	4	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9072062355	KU	4	40 BRO	SP	CRE	ED,ID	BD	00:00.0	
2021 PO9256461678	KU	2	50 OTH	SP	CCA		V	00:00.0	
2021 PO9237861749	KU	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO9228861767	KU	3	50 OTH	SP	CCA		V	00:00.0	
2021 PO9214361796	KU	2	50 OTH	SP	CCA		V	00:00.0	
2021 PO4434405410	KU	6	30 BRN	SP	CCA		V	00:00.0	
2021 PO4361085321	F	4	30 BRN	ST	P		V	00:00.0	
2021 PO4432205465	KU	4	40 BRN	SP	CRE		V	00:00.0	
2021 PO4361585327	F	4	35 BRN	SP	P		V	00:00.0	
2021 PO4362185337	F	5	30 BRN	ST	A		V	00:00.0	
2021 PO9192761839	KU	3	45 OTH	SP	CCA		V	00:00.0	
2021 PO9191961957	KU	6	30 OTH	SP	CCA		V	00:00.0	
2021 PO9196661654	KU	4	40 OTH	SP	CCA		V	00:00.0	
2021 PO9199061761	KU	5	35 OTH	SP	CCA		V	00:00.0	
2021 PO9205061805	KU	2	50 OTH	SP	CCA		V	00:00.0	
2021 PO9219961485	KU	4	40 OTH	SP	CRE		V	00:00.0	
2021 PO9050962377	KU	6	30 BRO	SP	CRE		V	00:00.0	
2021 PO9059162336	KU	5	35 BRO	SP	CCA		V	00:00.0	
2021 PO9064962373	KU	6	30 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9078062325	KU	6	30 BRO	SP	CRE		V	00:00.0	
2021 PO9055062240	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9194762031	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0	
2021 PO4362685345	F	4	35 BRN	ST	CCA		V	00:00.0	
2021 PO9429462573	KU	4	45 XXX	SP	CRE	ID	TD	00:00.0	
2021 PO9437162771	KU	4	40 XXX	SP	CRE	ED,ID	TX	RR	00:00.0
2021 PO9163762308	KU	5	35 OTH	SP	CRE	ID	BD	00:00.0	
2021 PO9222061981	KU	4	40 OTH	SP	CRE	ED,EP,HH,ID,IP,RB	X	PX	00:00.0
2021 PO9179462196	KU	6	30 OTH	SP	CCA		V	00:00.0	
2021 PO9096162498	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021 PO9196962067	KU	6	30 OTH	SP	CRE	ID	BD	00:00.0	
2021 PO9213462011	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD	00:00.0	
2021 PO9065762273	KU	5	35 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO9026361894	KU	4	45 BRO	SP	S		V	00:00.0	
2021 PO9024961955	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO9033362033	KU	3	45 BRO	SP	CCA		V	00:00.0	
2021 PO9050062098	KU	2	50 BRO	SP	CCA		V	00:00.0	
2021 PO9066762150	KU	2	50 BRO	SP	CCA		V	00:00.0	
2021 PO9057962180	KU	4	40 BRO	SP	CRE	ED,ID	TD	00:00.0	
2021 PO6391298089	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO6396998191	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO6402598291	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021 PO6431098166	F	4	40 XXX	SP	CRE	ED	V	00:00.0	
2021 PO6426498074	F	4	40 XXX	SP	CRE	ED,ID,MD	BX	RP1	00:00.0
2021 PO6449198035	F	2	40 XXX	SP	P		V	00:00.0	
2021 PO6437998027	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO6419097959	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO6514698269	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO6508098016	F	4	40 XXX	SP	CRE		V	00:00.0	
2021 PO6498097548	F	4	40 XXX	SP	P		V	00:00.0	
2021 PO6510898133	F	4	40 XXX	SP	CRE	ED,ID,IP,MD	BX	PX	00:00.0

2021	PO6499797622	F	4	40 XXX	SP	P	ED	V		00:00.0
2021	PO6502297731	F	4	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021	PO6497697521	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6508797531	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6523797506	F	2	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021	PO6319498712	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6317598793	F	2	40 XXX	SP	P		V		00:00.0
2021	PO6314298613	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6214098745	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6182898802	F	2	40 XXX	SP	P		V		00:00.0
2021	PO6199898719	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6218098746	F	4	40 XXX	SP	P		V		00:00.0
2021	PO6215698652	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6226598602	F	2	40 XXX	SP	P		V		00:00.0
2021	PO6244598876	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6245698754	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6246598671	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6254698580	F	5	30 XXX	SP	P		V		00:00.0
2021	PO6247998542	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6247098506	F	5	40 XXX	SP	CRE	ED,HH,ID,MD	BX	PX	00:00.0
2021	PO6263398489	F	5	30 XXX	SP	P		V		00:00.0
2021	PO6256798424	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6271198362	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO6284398306	F	4	40 XXX	SP	CRE		V		00:00.0
2021	PO9640856602	KU	6	30 BRN	SP	CCA		V		00:00.0
2021	PO9437462730	KU	4	40 XXX	SP	CRE	ID	TX	RR	00:00.0
2021	PO9443362763	KU	5	35 XXX	SP	CRE	ID,IP	TD		00:00.0
2021	PO4363585357	F	4	40 BRN	ST	P		V		00:00.0
2021	PO4363185316	LGE	3	50 BRN	SP	CRE		V		00:00.0
2021	PO4363785325	LGE	1	50 BRN	SP	CRE		V		00:00.0
2021	PO9437262751	KU	4	40 XXX	SP	CRE	ID,IP	TX	RR	00:00.0
2021	PO9427362742	KU	3	45 XXX	SP	CCA		V		00:00.0
2021	PO9417762740	KU	5	35 XXX	SP	CRE	ID	BD		00:00.0
2021	PO9425162938	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021	PO9435063116	F	4	40 XXX	SP	CRE	ED,ID	BX	RP3	00:00.0
2021	PO9592057039	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO9584857005	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO9577456973	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		00:00.0
2021	PO9142262424	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9127362541	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021	PO9126462466	KU	5	35 OTH	SP	CRE	ED,ID,SR	TD		00:00.0
2021	PO9015861989	KU	3	50 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO0097033444	KU	5	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO5989454834	KU	6	30 UNK	SP	CRE	ED,ID	TD		00:00.0
2021	PO8940262082	KU	4	40 BRO	SP	CRE	ED,ID	BD		00:00.0
2021	PO4436906212	F	4	40 BRN	SP	CRE		V		00:00.0
2021	PO4364785339	LGE	1	55 BRN	SP	A		V		00:00.0
2021	PO4362385304	LGE	3	50 BRN	SP	A		V		00:00.0
2021	PO4361585293	LGE	3	45 BRN	SP	A		V		00:00.0
2021	PO4360685300	LGE	4	35 BRN	SP	A		V		00:00.0
2021	PO9004961962	KU	5	35 BRO	SP	CRE	ED,ID	TD		00:00.0
2021	PO9097862453	KU	6	35 OTH	SP	CRE	ID	BD		00:00.0
2021	PO9111162492	KU	5	35 OTH	SP	CRE	ED,ID	BD		00:00.0
2021	PO4439805587	F	4	40 BRN	SP	CRE		V		00:00.0

2021 PO4434105718	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO4472505864	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO4470205680	F	4	40 BRN	SP	CRE	HH,ID,IP,RB		BX PX	00:00.0
2021 PO4440805769	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO4443705667	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO4453705573	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO4467405945	F	4	40 BRN	SP	CRE	HH,ID,IP,RB		BX RP1	00:00.0
2021 PO8949962058	KU	5	35 BRO	SP	CRE			V	00:00.0
2021 PO8954862148	KU	6	30 BRO	SP	CRE			V	00:00.0
2021 PO8966262297	KU	4	40 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO9132062928	KU	6	30 OTH	SP	CRE	ED,ID,SRS		TD	00:00.0
2021 PO9134263026	KU	4	40 OTH	SP	CRE	ID		BD	00:00.0
2021 PO9130362777	KU	4	45 OTH	SP	CCA	ED,SRS		TD	00:00.0
2021 PO9137062992	KU	4	45 OTH	SP	CCA			V	00:00.0
2021 PO9562756684	KU	4	45 BRN	SP	CRE			V	00:00.0
2021 PO9556956875	KU	5	35 BRN	SP	CRE	ED,ID		TD	00:00.0
2021 PO9554056861	KU	5	35 BRN	SP	CCA			V	00:00.0
2021 PO4458199116	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4471799358	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4458799407	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4445499457	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4420099556	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4409499592	F	3	40 BRO	SP	P	ED		V	00:00.0
2021 PO4399599651	F	2	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4389499618	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4407799734	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4430400158	F	4	40 BRO	SP	CRE			V	00:00.0
2021 PO4414299787	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4422699854	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4435499800	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4446199758	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4456899716	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4467799673	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4478299631	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4489399585	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4502299531	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4508599501	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4517899460	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4525699907	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4529799998	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4520299783	F	2	50 BRO	SP	CRE	ED		V	00:00.0
2021 PO4528099800	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4535099881	F	4	40 BRO	SP	CRE			V	00:00.0
2021 PO4524499732	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4470100340	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4513699619	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO4516199684	F	4	40 BRO	SP	CRE	ED		V	00:00.0
2021 PO8964262384	KU	3	45 BRO	SP	CRE	ED,ID		TD	00:00.0
2021 PO8999562122	KU	5	35 BRO	SP	CRE	ED,ID		BD	00:00.0
2021 PO9538356954	KU	4	40 BRN	SP	CRE	ED,ID,IP		TD	00:00.0
2021 PO4476106013	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO4474006238	F	4	40 BRN	SP	CRE			V	00:00.0
2021 PO4490005910	F	4	35 BRN	SP	CRE			V	00:00.0
2021 PO4481305916	F	4	40 BRN	SP	CRE			V	00:00.0

2021 PO4465806193	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO4484805787	F	3	40 BRN	SP	CRE		V		00:00.0
2021 PO9151862386	KU	4	45 OTH	SP	CRE	ID	BD		00:00.0
2021 PO9153462573	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9155462771	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9155462451	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		00:00.0
2021 PO9167962978	KU	4	40 OTH	SP	CRE	ED,ID,SRS	X	RP3	00:00.0
2021 PO9420463518A	KU	3	45 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9417063231	KU	4	45 XXX	SP	CCA	ED	V		00:00.0
2021 PO9411763222	KU	5	35 XXX	SP	CCA		V		00:00.0
2021 PO9394763274	KU	5	35 XXX	SP	CCA	ED	T		00:00.0
2021 PO9394563349	KU	5	35 XXX	SP	CCA	ED	T		00:00.0
2021 PO9383463362	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9374863254	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9393863223	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9393863223A	KU	5	35 XXX	SP	P	ID	TD		00:00.0
2021 PO9410963193	KU	6	30 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9416863060	KU	4	40 XXX	SP	CRE	ID	BD		00:00.0
2021 PO9423563064	KU	4	45 XXX	SP	CRE	ID	BD		00:00.0
2021 PO9422263168	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9439763316	KU	5	35 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9432063412	KU	5	35 XXX	SP	CCA	ED	T		00:00.0
2021 PO9420463518	KU	4	40 XXX	SP	CRE	ID	TD		00:00.0
2021 PO9417063589	KU	5	35 XXX	SP	CCA		V		00:00.0
2021 PO9522857123	KU	4	45 BRN	SP	CRE	ED,ID	TD		00:00.0
2021 PO6877748771	KU	4	40 UNK	SP	CRE	ID	BD		00:00.0
2021 PO4448606412	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4434506394	F	4	40 BRN	SP	CRE		V		00:00.0
2021 PO4455906267	F	4	40 BRN	SP	CRE	HH,ID,IP	BX	RP1	00:00.0
2021 PO4460406326	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	BX	PX	00:00.0
2021 PO4446906336	F	2	50 BRN	SP	CRE		V		00:00.0
2021 PO4364585304	LGE	3	45 BRN	SP	A		V		00:00.0
2021 PO4363085281	LGE	4	35 BRN	SP	A		V		00:00.0
2021 PO4365585293	LGE	4	40 BRN	SP	A		V		00:00.0
2021 PO4365085286	LGE	5	25 BRN	SP	A		V		00:00.0
2021 PO6867248832	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO6891248802	KU	1	75 UNK	SP	CRE		V		00:00.0
2021 PO6886548746	F	4	40 KOP	SP	P		V		00:00.0
2021 PO6894748708	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0
2021 PO6894448678	KU	4	45 UNK	SP	CRE	ID	BD		00:00.0