

Work Order Details

SP240124: UNIT 4 BOILER BED THERMOCOUPLES ANNUAL OUTAGE (MATS)

UNIT 4 BOILER BED THERMOCOUPLES ANNUAL OUTAGE (MATS)

Asset: **Location:** SP03.BO.IC Unit 03 Boiler Instrumentation **Model:** **Product Version:**

Sched Start:	10/8/2024	Business Unit:	SPUR-Spurlock Station	Job Plan:	INS.065
Sched Finish:	10/9/2024	Priority:	3 (Low - Routine)	Supervisor:	
Target Start:	9/1/2024	Work Type:	PM-Preventative Maint	Lead:	
Target Finish:	9/3/2024	Status:	WCMP	Vendor:	
Actual Start:	9/20/2024	Parent:		Reported by:	03890
Actual Finish:	10/9/2024	Failure Class:		Reported by:	Kathy Lippert
Report Date:	5/16/2024	Problem Code:		Defect Tag:	NO
Craft:	INS	PM Number:	PM3076	Commodity:	
Unit:	4	GL Account:	512000~SP03~400~3000~03200~BASE~00~00000~00000	Comdty Grp:	
Outage:	Outage	UNID:		Classification:	

Tasks										
WO Task	Task ID	Craft	Description	Status	Sched Start	Sched Finish	Est Hours	Actual Start	Actual Finish	
SP240125	10	OPERATIONS	OPERATIONS LOTO NECESSARY SYSTEMS FOR U4 BOILER BED THERMOCOUPLES INSPECTION AND REPLACEMENT	WCMP			1			
<i>Instructions:</i>										
SP240126	20	INS	UNIT 4 BOILER BED THERMOCOUPLES ANNUAL OUTAGE	WCMP	10/8/24	10/9/24	60			
<i>Instructions:</i>										
SP240127	30	OPERATIONS	OPERATIONS REMOVE LOTO NECESSARY SYSTEMS FOR U4 BOILER BED THERMOCOUPLES INSPECTION AND REPLACEMENT	WCMP			1			
<i>Instructions:</i>										

Work Order Details

SP240124: UNIT 4 BOILER BED THERMOCOUPLES ANNUAL OUTAGE (MATS)

Planned Labor									
Task ID	Craft	Skill Level	Labor	Vendor	Contract	Qty	Hours	Rate	Line Cost
10	OPERATIONS					1	01:00		
20	INS					2	30:00		
30	OPERATIONS					1	01:00		
	INS					2	20:00		
Total Planned Labor:									

Planned Services						
Task ID	Service Item	Description	Vendor	Qty	Unit Cost	Line Cost
		To Provide all Labor to remove and replace bed thermocouples on U4 Boiler (Contract # 1262); Labor	0000022751	4195	1.00	4195.00
		Tool Rental - Core Drill; Tool Rental	0000022751	1	450.00	450.00
Total Planned Services:						4645.00

Actual Labor								
Task ID	Craft	Skill Level	Labor	Vendor	Contract Num	Regular Hours	Premium Hours	
20	INS		03534			02:00	00:00	
20	INS		03535			05:00	00:00	
20	ALL		SP_TL_RG			00:00	00:00	
	ALL		SP_TL_RG			00:00	00:00	
	INS		02734			04:00	00:00	
	INS		02734			05:00	00:00	
	INS		02734			04:00	00:00	
	ALL		SP_TL_RG			00:00	00:00	
	INS		02734			00:00	04:00	
	ALL		SP_TL_OT			00:00	00:00	
	ALL		SP_TL_RG			00:00	00:00	

Actual Materials					
Task ID	Item Description	Binnun	Qty	Unit Cost	Line Cost
42924	Thermocouple, 38-1/4", 310SS Pipe (W/310SS Barstock Tip)	SWHS3-W3-88-02	3	1632.34	4897.02
Total Actual Materials:					4897.02

Actual Services						
Task ID	Service Item	Description	Vendor	Qty	Unit Cost	Line Cost
		To Provide all Labor to remove and replace bed thermocouples on U4 Boiler (Contract # 1262); Labor	0000022751	4,195	1.00	4195.00
		Tool Rental - Core Drill; Tool Rental	0000022751	1	450.00	450.00

Work Order Details

SP240124: UNIT 4 BOILER BED THERMOCOUPLES ANNUAL OUTAGE (MATS)

Actual Services							
Task ID	Service Item	Description	Vendor	Qty	Unit Cost	Line Cost	
						Total Actual Services:	4645.00

Log			
Date	Class	Created By	Description
09/21/2024 02:15:55 PM	WORKORDER	02734 Jason Wilson	
Inspected bed thermocouples. #3 and #13 on the front need to be replaced. #1 on the rear needs to be replaced.			

Report EK_woprint.rptdesign