#### COMMONWEALTH OF KENTUCKY

#### BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

CITY OF DRAKESBORO d/b/a DRAKESBORO NATURAL GAS COMPANY

CASE NO. 2019-00065

ELECTRONIC INVESTIGATION OF ALLEGED FAILURE TO COMPLY WITH KRS 278.495, 807 KAR 5:027, AND 49 C.F.R. PART 192

Notice of Filing

Notice is given to all parties that a copy of this Notice and the inspection report

have been filed into the record of this proceeding.

Done at Frankfort, Kentucky, this 18th day of June 2019.

wen R. Renso

Gwen R. Pinson Executive Director Public Service Commission of Kentucky

### **INSPECTION REPORT**

#### **INSPECTION INFORMATION**

KY PSC Inspector(s):	Melissa Holbrook and Chris Bai	ey Report Number:	Drakesboro-06172019
Inspection Date(s):	6-14-2019	Report Date:	6-17-2019
Inspection Type:	Standard	Integrity Management     Construction	Operator Qualification

#### **OPERATOR INFORMATION**

r: City of Drake	sboro	OP ID No.: (If no if an application has		
Municipal		the second se		City of Drakesboro
City of Drake	sboro			
Contact and Add	ress: (Contact	Unit Name and A	ddress	
7				
ail: 270-476-89	86 jonesy0120@	ogmail.com		
Drakesboro	Fire Dept.			
Title		Phone No.	Email	
	Office			
		270-820-6439	Deeius8308@c	
provided an upd	lated Emergency		Yes	No
mers:	667	×		
mployees:				
Gas:				
	Unknown		Selection of	
re(s):	MAOP (w	rithin last year)		ing Pressure (at time of nspection)
Feeder:	Unknown	and the second of the second second second	Unknown	nopection)
Town: Other:				
	mission pipeline	(above 20% SMVS)	n/a	
or Information:	ppon	- (42010 2070 01113).		
	City of Drake Contact and Add Drakesboro Title Mayor Russmar Compliance Russmar Superintence Drakesboro Employee provided an upd mers: mployees: Gas: Feeder: Town: Other: r have any trans	City of Drakesboro         Contact and Address: (Contact         ail:       270-476-8986 jonesy0120@         Drakesboro Fire Dept.         Title         Mayor         Russmar Compliance Office         Russmar Superintendent         Drakesboro Employee         provided an updated Emergency         ners:       667         nployees:       2         Texas Gas         Gas:       Unknown         Vinknown       Unknown         re(s):       MAOP (w         Feeder:       Unknown         Town:       Other:         r have any transmission pipeline	Municipal       Location of Facility         i:       City of Drakesboro         Contact and Address:       (Contact         Unit Name and Address:       Unit Name and Address         nil:       270-476-8986       jonesy0120@gmail.com         Drakesboro Fire Dept.       Drakesboro Fire Dept.         Title       Phone No.         Aayor       270-543-6425         tussmar Compliance Office       606-875-4655         tussmar Superintendent       270-543-4160         Drakesboro Employee       270-820-6439         provided an updated Emergency Contact List?       Maop (within last year)         mers:       667         nployees:       2         Texas Gas       Gas:         Unknown       Unknown         ve(s):       MAOP (within last year)         Feeder:       Unknown         Town:       Other:         r       Town:         Other:       Town:         Other:       Town:         Town:       Other:	City of Drakesboro Contact and Address: (Contact Unit Name and Address Email 270-476-8986 jonesy0120@gmail.com Drakesboro Fire Dept. Title Phone No. Email Jonesy0120@ Identify the second s

Date of Last Inspection:	2-21-2019			
Number of Deficiencies:	35	Deficiencies not Cleared:	11	

#### Summary of Areas Inspected

PHM	SA Question Set				
×	Emergency Plan	$\boxtimes$	Operations and Maintenance Plan		Critical Valves Maintenance Inspections
×	Cathodic Protection		Accidents	$\boxtimes$	Leak Surveys
×	Odorization	$\boxtimes$	Operator Qualification	$\boxtimes$	Damage Prevention
×	Pipeline Markers	$\boxtimes$	Regulator Stations	$\boxtimes$	DIMP
×	Field Inspection		Other		
Othe	<u>:</u>				
L					
Stat	e Question Set				and a second
×	Cybersecurity		Other		
Othe					

#### **Summary**

The following deficiencies were cited in the February 2019 inspection. A follow-up inspection was required to clear the 35 deficiencies and check operator's progress. The following deficiencies were reviewed as follows.

#### Follow-up Inspection Findings

1. Drakesboro's written procedural manual for operations and maintenance activities does not include all procedures required by **49 CFR §192.605**. The missing items are highlighted in red.

Follow-up: The plan was provided for review.

- Drakesboro's plan to minimize the hazard resulting from a gas pipeline emergency does not include all procedures required by 49 CFR §192.615. The missing items are highlighted in red.
   Follow-up: The plan was provided for review.
- 3. Drakesboro does not have a written program to prevent damage to underground pipelines from excavation activities as required by **49 CFR §192.614**. Follow-up: The plan was provided for review.
- Drakesboro does not have a written public education program as required by 49 CFR § 192.616.
   Follow-up: The plan was provided for review.
- 5. Drakesboro does not have a written anti-drug plan as required by **49 CFR § 199.101**. Follow-up: The plan was provided for review.
- Drakesboro does not have a written alcohol misuse plan as required by 49 CFR § 199.202.
   Follow-up: The plan was provided for review.
- Drakesboro has not conducted drug tests as required by 49 CFR § 199.105.
   Follow-up: Mike Jones, Melissa Holland, Donald Sims, Jordon Shaw were drug tested on February 19, 2019.
- Drakesboro has not provided training for supervisory personnel who will determine whether an employee must be drug tested based on reasonable cause as required by 49 CFR § 199.113 (c).
   Follow-up: The operator has not conducted training yet. Operator stated he would contact police dept. to conduct training.
- Drakesboro does not have a written distribution integrity management plan as required by 49 CFR § 192.1005.
   Follow-up: The written plan was provided for review. Original version April 21, 2014.
- 10. Drakesboro does not have welding procedures as required by **49 CFR § 192.225**. Follow-up: The welding procedures manual was provided for review.
- Drakesboro does not have written plastic joining procedures as required by 49 CFR § 192.273(b).
   Follow-up: The fusion procedures manual was provided for review. The operator is currently only using compression and stab fittings.

- Drakesboro's operator qualification program does not meet the requirements of 49 CFR § 192.805. The missing items are highlighted in red.
   Follow-up: The operator qualification plan was provided for review.
- 13. Drakesboro has not submitted annual reports as required by **49 CFR § 191.11**. Follow-up: The operator has not submitted online report as required to PHMSA online.
- 14. Drakesboro has not sent the customer notification required by **49 CFR § 192.16**. Follow-up: The operator hand- delivered notifications to the customers in March 2019. when paying their gas bill. Notice was also, posted in the local newspaper. The remaining customer notifications will be hand- deliver to customers.
- Drakesboro has not sent public awareness messages as required by 49 CFR § 192.616.
   Follow-up: The public awareness message has not been delivered as required. The operator stated brochures are currently being printed.
- Drakesboro has not trained appropriate operating personnel to ensure they are knowledgeable of emergency procedures as required by 49 CFR § 192.615(b)(2).
   Follow-up: Emergency Response Training was conducted on June 14, 2019 by Jeff Roberts and documented.
- Drakesboro did not establish and maintain liaison with appropriate fire, police, and other public officials as required by 49 CFR § 192.615(c).
   Follow-up: Meeting was conducted on June 14,2019 with Mayor, Gas Dept., Russmar and Fire Dept. Chief reviewing issues with gas emergencies and record reviewed.
- Drakesboro does not review or update its operation and maintenance plan as required by 49 CFR § 192.605 (a).
   Follow-up: New plan was implemented in 2019.
- Drakesboro has not conducted periodic sampling of combustible gases in its distribution lines to assure the proper concentration of odorant test as required by 49 CFR § 192.625(f) since November 2017.
   Follow-up: The records for May 8, 2019, May 17.2019, May 20, 2019, May 31,2019, 6June 6,2019 indicate readings were conducted by Drakesboro Employee Donald Sims (OQ-February 13, 2019).
- Drakesboro has not conducted patrolling of its distribution mains as required by 49 CFR § 192.721 since 2017.
   Follow-up: Operator needs to make a patrolling list for known hazardous piping and document as required.
- 21. Drakesboro has not conducted a leakage survey in its business district as required by 49 CFR § 192.723 since 2017. Additionally, the employee who is listed on the record of the 2017 survey as having conducted the survey, Jordon Shaw, verified to Staff on February 7, 2019, that he did not conduct the leak survey.

Follow-up- Leak survey conducted by Russmar on March 20,2019 until April 16,2019. No Class 1 leaks, 22-Class 2 leaks, and 7-Class 3 leaks.

- 22. Drakesboro has not conducted regulator/relief valve inspections as required by 49 CFR § 192.739.
   Follow-up- The operator could not produce records at the time of inspection.
- Drakesboro has not conducted valve inspections as required by 49 CFR § 192.747 since 2016.
   Follow-up: Critical Valve inspections conducted on May 15, 2019 by Donald Sims (OQ February 21,2019).
- 24. Drakesboro has not tested pipelines under cathodic protection as required by 49 CFR § 192.465 (a).
   Follow-up: Pipe to soil readings conducted on May 4, 2019 by Donald Sims is not operator qualified and Marvin Anderson (OQ December 10,2021). All Readings are below the required -0.85.
- 25. Drakesboro has not conducted cathodic protection rectifier inspections as required 49 CFR § 192.465 (b). Follow-up: Donald Sims visits rectifier monthly, he is currently not documenting readings. Operator is not operator qualified to conduct inspections. After review of cathodic protection readings the rectifier is properly working.
- Drakesboro has not conducted atmospheric corrosion inspections as required by 49 CFR § 192.481.
   Follow-up: The inspection has not been conducted at this time.
- 27. Drakesboro's pipeline markers do not meet the requirements of 49 CFR § 192.707. Numerous pipeline markers in field were unable to read. Follow-up: The operator has ordered new pipeline markers to be installed upon arrival. New signs have been installed at all regulator stations.
- 28. Drakesboro failed to ensure that individuals performing covered tasks were qualified as required by 49 CFR § 192.805(b). At the time of Staff's inspection, two employees of Drakesboro who were not properly qualified were performing covered tasks. Staff also received a report from a customer that prisoners turned on gas service and entered the home to relight appliances. Follow-up: The operator has two current employees, Donald Sims and Jordon Shaw,

who are operator qualified to restore service (OQ February 14,2019), and Russmar employee Marvin Anderson (OQ July 31,2022) on site to turn on gas for customers.

- 29. Drakesboro did not properly repair a damaged plastic main on Wyatt's Chapel Road as required by **49 CFR § 192.311**. Operator repaired a 2 "plastic main with a clamp. Follow-up: The operator has not found location at this time to repair.
- 30. Drakesboro did not ensure that combustible gas in its distribution lines was properly odorized as required by 49 CFR § 192.625(a). A 3<sup>rd</sup> party contractor conducted odor test and verified there was no odorant in the gas system.

Follow-up: The records for May 8, 2019, May 17.2019, May 20, 2019, May 31,2019, 6June 6,2019 indicate readings were conducted by Drakesboro Employee Donald Sims (OQ-February 13, 2019).

- 31. Drakesboro failed to follow procedures in its emergency plan in response to two reports of gas detected inside and outside of homes as required by CFR § 192.605(a). Follow-up: No issues indicated in records. All emergency calls through 911 in cad system. A record of each emergency documented.
- 32. Drakesboro has not offered excess flow valves to existing customers as required by 49 CFR § 192.383(d). Follow-up: At this time the operator has not sent. The operator plans on sending to customers when public awareness message goes out.
- 33. Drakesboro has failed to ensure that each person making joints in plastic pipelines is qualified as required by 49 CFR § 192.285. Follow-up: Drakesboro employees Donald Sims and Jordon Shaw are currently operator qualified on using stab and mechanical fittings on (OQ February 19,2019).
- 34. Drakesboro has failed to maintain for the useful life of each pipeline records of each test performed under 49 CFR Subpart J as required by 49 CFR 192.517. Follow-up: The original MAOP records were not found. A history of operating pressure needs to be reviewed to establish MAOP.
- 35. Drakesboro has failed to keep records of the following procedures as required by **49** CFR § 192.603(b):
  - Installation of new service lines;
  - Installation of excess flow valves;
  - Response to and repair of leaking pipelines;
  - Atmospheric corrosion inspections;
  - Odorant tests (2018 and 2019);
  - Patrolling of distribution mains (2018);
  - Leak surveys (2018);
  - Valve inspections (2018 and 2019);
  - Pipe-to-soil readings (2018); and
  - Cathodic protection rectifier inspections (2018).

Follow-up: The following records were reviewed: installation of new service line, installation efv, odor tests, leak survey, valve inspections, and pipe to soil readings, and leak repairs. The records provided by Russmar were not adequate documentation for leak repairs. Please see records below.

#### Inspector Comments

The closing conference was conducted with the following: Mayor Mike Jones, Drakesboro employee Donald Sims, and Russmar employee Jeff Roberts.

After conducting the follow-up inspection, it was discussed that 12 of the 35 deficiencies have not been corrected. The following recommendations were made: The City of Drakesboro needs to contract trained and operator qualified specialists to assess the pipeline system for corrosion, rectifier's, measurement, and regulator stations.

Submitted by:

Melisa Halliada

Melissa Holbrook 6-17-2019 Utility Regulatory and Safety Investigator

City of Drakesboro leak Repairs.

There was a total of 29 Leaks Reported in the annual Leak Survey

22 Grade 2 Leaks

7 Grade 3 Leaks

Putting all this information together from the DFR and the Leak Survey, which doesn't correspond due to documentation.

Leaks Repaired from DFR's Location , Date , Leak Order #

- 1. 100 Harper Circle 3-18-2019
- 2. Jackson Town Rd 3-19-2019
- 3. US.431 3-19-2019
- 4. 48 Beach Creek Brown RD 3-20-2019 Leak Order 1016
- 5. 301 Union Chapel Lane 3-20-2019
- 6. Intersection of Broad St & Kennedy Jones Ave 3-21-2019
- 7. Christian Street 3-25-2019 ? Multiple on Christian Street
- 8. 160 woodruff & Beech creek 3-25-2019
- 9. Jones Ave & Christian 3-25-2019 Leak Order 1006
- 10. Everly & Christian 3-26-2019
- 11. 310 Christian 3-26-2019
- 12. 217 Guitar Ave 3/27/2019 Leak Order 1002
- 13. 116 Cornette St 3/27/2019
- 14. 507 Broad way 3-28-2019
- 15. Ditney Hill Rd 3/28/2019
- 16. 3190 Hwy 431 4/1/2019
- 17. 110 Kirtley Rd 4/1/2019 Leak Order 1026
- 18. 1554 Hwy 431 4/1/2019 Leak Order 1024
- 19. Merale Travis Hwy 4/2/2019
- 20. Hwy 1163 & Beechcreek Rd 4/3/2019
- 21. 208 Mill Rd 4/3/2019

Job Name: Dra Kesborn TAM\_

Job Number:

19.356

Date: 3-18-2019

Drakes Doro, Harper circle supervisor: Dustin hagner Exact Location: A+B+C=D A 8 С Cost Total Drive Work Employee Name & Start End Lunch Vac Codes Time Time Hours Time Time Class (Foreman, Op, Lab) Time Dustin Logoer Cordell Hill 7 11 Foreman 4 6:00 5:00 Lab 7:00 5:00 3 ٦ 10

Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
stated and the state of the local division o	169905	70180	275	
483	3111	3114	3	
	1			
		<u> </u>		
	Number	Number Miles/Hrs	Number Miles/Hrs Miles/Hrs 164 69905 70180	Number Miles/Hrs Miles/Hrs Miles/Hrs

To	day's Production	
Task Description	Units/Footage	Additional Comments
Dug up leak and fixed it		100 Harper Circle
Cut blacktop		
Lut blacktop Hauled off blacktop and backfilled		
with dense o rade		
The put band champ onit		

Job Name: Drakesbora. TAM Job Number:

19356

3-19-2019 Date:

supervisor: Dustin Wagner Makesborn Exact Location: A+B+C=D A B С Cost Drive Work Total Lunch Vac Employee Name & End Start Codes Hours Time Time Time Time Time Class (Foreman, Op, Lab) 7:30 5:00 9 P Foreman Dustin Wonner Cordell Hill 0,5 q 9 Lab 7:30 5:00 0.5

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
Cherly 2500	164	70180	10319	33	
Chevy 2500 CX55B prov. EX	483	3114	3116	9	
			1		
			1		

1	oday's Production	
Task Description	Units/Footage	Additional Comments
Dug up alines and fixed leaks		
2"steel line, cappedit		Jackson Town Rd
		45 431
pin Hole in steel service line put band clamp on it		
•		

Job Name: Drakesboro TIM

Job Number:

19356 Date:

Drakesboro A+B+C=D supervisor: Dustin Wagner Exact Location: A 8 С Cost Drive Work Total Vac Start End Lunch Employee Name & Codes Hours Time Time Time Class (Foreman, Op, Lab) Time Time Dustin Wagner Cordell Hill 9 9 Foreman 0.5 5:00 7:30 9 9 Lab 5:00 0.5 7:30

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
CLOWN DEM	164	70212	70265	53	
Chevy 2500 CX55B mini Ex	483	3116	3119	3	
		1			
				-+	
				1	
				+	

То	day's Production	
Task Description	Units/Footage	Additional Comments
Dug up 2 lines and fixed leaks Tighten cap on service Tap Steel		48 Blech Creek Browder Rd
5		301 Union Chapel Lane
pin hole in 15" service line plastic cut out and fixed, cut blacktop Backfilled with dense grade		
<u>_</u>		

MAR	TIN	V C	ON	TR.	AC'	ΓΠ	NG	, INC.
100 Nome: Drakesborg	TAM	۱	lob Number	:		193	56	Date: 3-21-2019
supervisor: Dustin War	gner			A	Exact Locat B	ion: C	АлаК	esboro
Employee Name & Class (Foreman, Op, Lab)	Start Time	End Time	Lunch	Vac Time	Drive Time	Work Time	Total Hours	Cost Codes
Dustin Whoner Cordell Hill	7:30 7:30	5:00 5:00	0.5 0.5			9	9	Foreman Lab
								·
Equipment Description		Unit Number	Start Miles/Hrs	End Miles/Hrs				Cost Code
Chevy 2500 CX55B Mini EX		164 483	70265	3119	105 0			
						-		
			Tod	ay's Pro				Additional Comments
Task D	Description			Units	/Footage	TIN		of Broadst and

T	oday's Production	
Task Description	Units/Footage	Additional Comments
et band clampon 2" steel line		Intersection of Broadstan
It Dand Clamp and Star line		Intersection of Broadstance Kennedy Sones Ave
I I I I V		
lped with leak survey		

Job Nome: Dra Keshara TAM

supervisor: Dustin Wagner				Exact Location: Drakesboro						
	Juse			A	В	С	A+B+C=D			
Employee Name & Class (Foreman, Op, Lab)	Start Time	End Time	Lunch	Vac Time	Drive Time	Work Time	Total Hours	Cost Codes		
Nustin 1 maner	7:30	12:00				4.5	4.5	Foreman		
Dustin Wagner Cordell Hill		12:00			1	4.5	4.5	Lab		
	+				1	1				
							+			
				+		-		-		
and the second	-				1					

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
Chevy 2500	164	70370	70730	360	
Chevy 2500 CX556	483	3119	3119	0	

Today's Production							
Task Description	Units/Footage	Additional Comments					
Located lines							
Located lines helped with Raksurvey							
<u> </u>							

b Name: DRAKESBORO TEM			lob Numbe	<u>r:</u>	19356			Date:	3/25/19
upervisor. JEREMY JANES					Exact Loca	tion:	JONES AV	/E	
uper visor serverin sances				A	B	C	A+B+C=D		(
Employee Name & Class (Foreman, Op, Lab)	Start Time	End Time	Lunch	Vac Time	Drive Time	Work Time	Total Hours		
EREMY JANES	3:00 PM	10:30 PM	d.B		1.0	6.5	7.5	1hr-75	5.5hrs-101
Equipment Description		Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs				
2016 CHEVY 2500		143			7.5	1hr-25 6.5hrs-101			
					1				
[			Too	lay's Pro	duction				1.6
Task	Description	on		Units	s/Footage			Addition	al Comments
Took air compressor to DRAM	ESBORO a	nd help fix l	eak on	_					
4" steel main									

4" steel main

Job Name: Drakesboro t and m		Job Number: 19356				Date: 3/25/19				
Supervisor. Jeremy banks	<u></u>	Exact Location: Drakesboro								
-la-minimum de la constance de		5		A	В	C	A+B+C=D	12		
Employee Name & Class (Foreman, Op, Lab)	Start Time	End Time	Lunch	Vac Time	Drive Time	Work Time	Total Hours			
Foreman Jeremy Banks	6 AM	6:30 PM	53 G		3.5	8.5	12.0	25-3.5/	101-8.5	
Lab Dustin Drake	6 AM	6:30 PM	14.14		3.5	8.5	12.0	25-3.5/	101-8.5	
Lab William Hampton	6 AM	6:30 PM	40.5		3.5	8.5	12.0	25-3.5/	101-8.5	

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs			
2016 chevy 3500	136			148.0	25-3.5/101-8.5	
Case 55 min	An			1.415.0	25-3.5/101-8.5	
		+				

Today's Production							
Task Description	Units/Footage	Additional Comments					
Repaired leak		Cristian st					
		1					

Job Name: Drakesboro T&M

Job Number:

19356

Date: 3-25-2019

Drakesboro supervisor: Dustin Wagper Exact Location: A+B+C=D A B C Cost Work Total Drive Start End Lunch Vac Employee Name & Codes Time Time Hours Time Time Class (Foreman, Op, Lab) Time 13.5 17.5 25-4hr 101-135h 4 5:00 11:00M Dustinhogner For Cordell Hill Lob C. 5 16.5 25-365 101-13.5kg 3 135 05

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
C. HRVY 2500	164	70730	71000	270	101
CXSSB	483	3/19	344	5	101
				1	
		1			
		1			

Today	's Production	
Task Description	Units/Footage	Additional Comments
Fixed 3" service live plastic with stop fitting		160 Woodruff In, Beechcreek
Jug up 4" stoelline, found leak, bad leak		Intersection of Jones Ave and
bland on a 4" short stop in seperate dell		Christian St
holes Cutout 2' at leak		
Welded 2° of 4° steel backin Cut blacktop for 1 of bell bales		
Howled off 2' loads of concrete Diacktoard "		
Hauled 2 loads of gravel		

					Exact Loca	tion:	Drakesbo	ro	
upervisor. Jeremy banks			1	A	B	С	A+B+C=D		
Employee Name & Class (Foreman, Op, Lab)	Start Time	End Time	Lunch	Vac Time	Drive Time	Work Time	Total Hours		
Foreman Jeremy Banks	7:30 AM	5:30 PM	. w. 5.			9.5	9.5	0101-9-	
ab Dustin Drake	7:30 AM	5:30 PM	18.11			9.5	9.5	0101-9-	
ab William Hampton	7:30 AM	5:30 PM	9			9.5	9.5	0101-9-	5
Equipment	1	Unit	Start	End	Total		ļ		
Description		Number	Miles/Hrs	Miles/Hrs	Miles/Hrs	0100.01			
2016 chevy 3500		136			148,123.0	0101-9-5			
Case 55 mim		463			1,413.0	0101-9-			
									And the second se

Today's Production							
Task Description	Units/Footage	Additional Comments					
Repaired leak	3h	Corner of Ike everly ave. And Christian st. 2" coated					
repaired teak		Steele main in the dirt 2 leaks					
Repaired leak	6h	Front of 310 Christian st 2" coated steel main under					
Repaired teak		Blacktop cut blacktop 15'x5'					
Moved excavator	30m	From Christian st, To broad st.					
		and the second					

## MARTIN CONTRACTING, INC. Drakes boro T&M Job Number: 19356 Date: 3-26-2019

Job Name: Drakes boro T&M

supervisor: Dustin Wa			Exact Loca	tion:	Makesboro				
State 1- State 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1-	<u> </u>			A	В	С	A+8+C=D		
Employee Name & Class (Foreman, Op, Lab)	Start Time	End Time	Lunch	Vac Time	Drive Time	Work Time	Total Hours	Cost Codes	
Mustin Whener For	8:00	6:00	0.5			9.5	9.5	/01	
Dustin Wheyner For Coedell Hill J Lab	8:00	6:00	0.5			9.5	9.5	/01	
	1								
						1			
						1			
			1	1		1			
	1	1		1					
	1		1						

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
Cheve 2500	164	71000	71040	40	101
Chevy 2500 CX5510 Mini Ex	483	3124	3131	7	101
		<u></u>			
			1		
			+		

Toda	y's Production	
Task Description	Units/Footage	Additional Comments
Cut Blacktop, Hawled off 310ads of dirt		219 Christian Ave
Which 21- adds at aravel		
There was no leak, around saturated		
A A A A A A A A STERI		
Dugant 20 of service line 1"steel		
Dudout Tap		
NO Leak		
	1	

upervisor Jeremy banks				1	Exact Loca	tion:	Drakesbo		and the second
P	1		1	A	В	с	A+B+C=D		
Employee Name & Class (Foreman, Op, Lab)	Start Time	End Time	Lunch	Vac Time	Drive Time	Work Time	Total Hours		
oreman Jeremy Banks	7:30 AM	4:30 PM	198 T.C			8.5	8.5	0101-8-5	A CONTRACTOR OF THE OWNER
ab Dustin Drake	7:30 AM	4:30 PM	12.11			8.5	8.5	0101-8-5	
ab William Hampton	7:30 AM	4:30 PM	0 -			8.5	8.5	0101-8-5	
							<u></u>		
	1								
								1	
Equipment		Unit	Start	End	Total				
Description		Number		Miles/Hrs	Miles/Hrs				
2016 chevy 3500	and the second	136			147,201.0				
Case 55 mini		463			1,525,0	0101-8-	5		
				1					
			+						and the second sec
			+		1				
			1	1					the second s

an san an a	<b>Today's Production</b>	
Task Description	Units/Footage	Additional Comments
and a state of the	8h 30m	507 broad st. Pin pointed leak stripped out 2" main
Repaired leak		Found a service line had been abandoned with a
		Thread on 1" cap, cap was leaking. Loosed up cap added
		Thread compound retighten cap stopped leak 4'x4'
وروا در است. و و و و و و و و و و و و و و و و و و و	An or a state of the	Blacktop cut

## MARTIN CONTRACTING, INC. Drokesborg TAM Job Number: 19356 Date: 3-28

Job Nome: Drakesboro T+M

Date: 3-28-2019

supervisor: Dustin blagaer					Exact Location: Drakes boro					
	J			A	B	С	A+B+C=D			
Employee Name & Class (Foreman, Op, Lab)	Start Time	End Time	Lunch	Vac Time	Drive Time	Work Time	Total Hours	Cost Codes		
Dustin Wagner Cordell Hill	7:30	200				6.5	6.5	101 101		
					+					

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code	
	164	71084		361	/0/	
Chevy 2500 Chevy 2500	483	3135	3137	2	1.31	
		1				
		1				

Toda	y's Production	
Task Description Cut Blacktop, dug up 2° steel line put Band Clamp on, Hauled of 11900 dict. Hauled 1 load of gravel	Units/Footage	Additional Comments Ditney Hill Rd Leak Aclose to Hillside Lo

# MARTIN CONTRACTING, INC.Job Number: 19356Date: 4-1-2019

upervisor: Dustin W	naner				Exact Loca	ation:	A+B+C=D	boro	
Employee Name &	Stort Time	End Time	Lunch	A Vac Time	Drive Time	Work Time	Total Hours		Cost Codes
Closs (Foreman, Op, Lab)	5:00	6:00	0.5		4	8.5	125	25-460	101-8.5hr
Justin Wagner For Cordell Hill Lab	16:00	6:00	0.5		3	8.5	11.5	25-3hr	101- 8. She
Sound Adams Op	5:00	6:00	0.5		4	8.5	12.5	25-4hr	101- 8.5hr
1					+				
				1	1	1		1	
			ļ						
		·		1		1		1	
				1	1	1			
		1		1					
				1				1	and the second second second second

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
	164	71445	17071	326	101- X.Sbc
Levy 2500	483		3140	3	101 - 8.5hr
				1	
		1			
				-	

Today	's Production	
Task Description Ingout 4" steel lice, Fixed leak with 1" Band Clamp	Units/Footage	Additional Comments
In Band Clamp Jug up 2" Steel. Tightened up band clamp That was already on it		110 Kictley Rd.
that was already an it Dug up 4" steel line and 4X1" steel Tap. 1"steel Found leak, Has to be Replaced.	line	1554 11400 431
Found leak, Hastobe Replaced. Covered backup. Didn't have parts to fix		

REVISED 11/18/11

## MARTIN CONTRACTING, INC. Vokesborg The Job Number: 19356 Date: 3-27-2019

Job Name: Drakesboro TOM Job Number:

supervisor: Dustin Wagner					Exact Loca	ation: C	Arakest A+B+C=D	010	
Employee Name & Class (Foreman, Op, Lab)	Start Time	End Time	Lunch	A Vac Time	Drive Time	Work Time	Total Hours	Cost Codes	*****
Dustin Wagner For Cordell Hill Lab	7:30	5:30	0.5			9.5	9.5	/01	
OFORU TITIS NO	1.30	06.5	0.5						
and all any of the state of the									
						ļ			
								÷	

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
Chevy 2500 CX55B Mini Ex	164	71040	3135	44	/oi /oi
		<u> </u>		<u> </u>	
		<u> </u>			
			<u> </u>		

Toda	y's Production	
Task Description	Units/Footage	Additional Comments
Dug up 1" steel, Fixed leak with band		217 Guitar Ave
Cut Blacktop, Hawled off 1 load dirt Repaired 2" Steel gas leak with band clamp. Hawled 1 load of grave 1		116 Cornette St.

4-2-2019 Job Name: Licakesbara T&M 19356 Date: Job Number: Drakesboro Supervisor: Bustin Wagner Exact Location: A+B+C=D C A B Cost Drive Work Total Vac End Lunch Employee Name & Start Codes Time Time Time Hours Class (Foreman, Op, Lab) Time Time 5:00 5:30 25- lohr 101. lohr 12 Dustin Wagner For Condell Hill bob Jarred Adams op 0.5 6 6 8 8 101-8hr 7:30 4:00 0.5 8 101-8hc 8 7:30 4:00 0.5

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
Chevy 2500	164	71771	72192	421	101 - 1260 101 - 860
CX558 Mini Ep	483	3140	3140	0	101-860
				·+	
		+		++	
			1	1 1	

Today	's Production	
Task Description	Units/Footage	Additional Comments
Dugue 2" steel line. Put Randclampon.		528 Beechcreek Rd
Removed Tap. Fixed leak, Hove to come back		
20 Aziestall Tab + Service		
Dug up 2" steel line value. Covered back	24	
up that to be fixed, Waiting on parts	1	
Drove to Delta Meeting and Back		I
Drove to Levia Meeting and Later		A LE LU MARLEN V
	-	Mearle Travis Hoy and Brechereek
		Browder Rd Totesection

Job Name: Drakesboro T&M

Job Number:

19356

Date: 4-3-2019

1 rakesborg supervisor: Dustin Wadner Exact Location: A+B+C=D A B C Cost Total End Lunch Vac Drive Work Start Employee Name & Codes Hours Time Time Time Class (Foreman, Op, Lab) Time Time 9 9 101 - 96 7:30 5:00 Dustin Wagner For Condell Hill Lab Darred Adams Op 6.5 Q 101 - 950 0.5 9 9 9 101-96 Op 0.5 7:30 5:00

Equipment Description	Unit Number	Start Miles/Hrs	End Miles/Hrs	Total Miles/Hrs	Cost Code
Chevy 2500	164	72192	7.50	58	101 - 9ke
CX.550 Min Ex	483	3140	3143	3	101- 9he
				1	

Today's Production			
Task Description Taskalled 2X5 Tab. 2 of 5 and plastic.	Units/Footage	Additional Comments Intersection Hury 1163 and	
5×1 Returer. 1 of 1° pipe plastic. 1×14 Reducer. Fixed Tap and service from yesterd	Fittings	Beschereek Rd. 523 Brechereek Rd	
Dug up 1" steel line. Fixed leak with		208 M: 11 Rd.	
Paldiciamp			

\*Drakesboro Natural Gas Co. 212 Mose Rager Boulevard P. O. Box 129 Drakesboro, KY 42337

\*Drakesboro Natural Gas Co. Drakesboro Natural Gas Co. 212 Mose Rager Boulevard P. O. Box 129 Drakesboro, KY 42337

\*Ryan Driskill Attorney Yonts, Sherman & Driskill, P.S.C. P.O. Box 370 Greenville, KENTUCKY 42345