



representatives of a public or private corporation or a partnership or association or a governmental agency, be accompanied by a signed certification of the preparer or the person supervising the preparation of the response on behalf of the entity that the response is true and accurate to the best of that person's knowledge, information, and belief formed after a reasonable inquiry.

Ohio District shall make timely amendment to any prior response if Ohio District obtains information that indicates the response was incorrect or incomplete when made or, though correct or complete when made, is now incorrect or incomplete in any material respect.

For any request to which Ohio District fails or refuses to furnish all or part of the requested information, Ohio District shall provide a written explanation of the specific grounds for its failure to completely and precisely respond.

Careful attention shall be given to copied and scanned material to ensure that it is legible. When the requested information has been previously provided in this proceeding in the requested format, reference may be made to the specific location of that information in responding to this request. When applicable, the requested information shall be separately provided for total company operations and jurisdictional operations. When filing a paper containing personal information, Ohio District shall, in accordance with 807 KAR 5:001, Section 4(10), encrypt or redact the paper so that personal information cannot be read.

A copy of this request shall be served on the Complainant, John Riley Dowell, by U.S. certified mail, return receipt requested at 856 Buford Road, Utica, Kentucky 42376.

1. Provide a pressure chart summary for 856 Buford Road from December 1, 2022, to the date of the issuance of this request.
2. Provide a full printout of the pressure chart summary for 856 Buford Road from July 18, 2023, through July 24, 2023.
3. Provide any and all work orders created by Ohio District to check the pressure at 856 Buford Road from December 1, 2022, to the date of the issuance of this request.
4. Provide the work order completed by distribution personnel from Ohio District to read the pressure at a hydrant near 856 Buford Road.
5. State the general reasons that a regulator may be installed at a meter.
6. State the reasons why a regulator was installed at 856 Buford Road on July 11, 2023, or close to July 11, 2023.
7. Provide the current reading off of 856 Buford Road's supply line after installing the regulator.
8. State whether or not on any day from December 1, 2022, to the date of issuance of this request the pressure at the service pipe at 856 Buford Road was more than 150 psi.
9. State all of the actions done by Ohio District from December 2022 to the issuance of the date of this request to remedy high pressure at 856 Buford Road.
10. State whether high pressure at 856 Buford Road is still an ongoing issue.
11. Provide the telemetry date for the tank that fills the system for 2023.



Linda C. Bridwell, PE  
Executive Director  
Public Service Commission  
P.O. Box 615  
Frankfort, KY 40602

DATED     MAY 22 2024    

cc: Parties of Record

Case No. 2023-00249

\*John Dowell  
856 Buford Road  
Utica, KENTUCKY 42376

\*Ohio County Water District  
124 E Washington Street  
P. O. Box 207  
Hartford, KY 42347

\*Eric Hickman  
Ohio County Water District  
124 E Washington Street  
P. O. Box 207  
Hartford, KY 42347