RECEIVED

COMMONWEALTH OF KENTUCKY

FEB 03 2025

BEFORE THE PUBLIC SERVICE COMMISSION

PUBLIC SERVICE COMMISSION

In the matter of: Debra A. Peternan
COMPLAINANT
VS.
(Name of Utility) DEFENDANT
COMPLAINT
The complaint of <u>Petra + Larry Petronan</u> respectfully shows: (Your Full Name)
(a) Debra + Larcy Peternas (Your Full Name)
51 Woodland Way Grayson Ky 41143 (Your Address)
(b) Kentucky Power (Name of Utility)
12333 Kevin Ave Ashland Ky 41102 (Address of Utility)
(c) That: Strang checker, cal voltage or quatrical (Describe here, attaching additional sheets if necessary,
the specific act, fully and clearly, or facts that are the reason
(See attached papers) and basis for the complaint.)

Formal Complaint	
Debra + Lary Peternes_ vs.	Kentucky Power
Page 2 of 2	
	1 <u>bi</u>
Wherefore, complainant asks All St. (Specif	ran electrical voltage rically state the relief desired.)
A list or attached	paper gives
by Matthew Porter	master electrician.
Dated at Gray Son (Your City)	day
of January, 20 (Month)	25 elga A Jetemenn (Your Signature*)
(Name and address of attorney, if any)	Date

^{*}Complaints by corporations or associations, or any other organization having the right to file a complaint, must be signed by its attorney and show his post office address. No oral or unsigned complaints will be entertained or acted upon by the commission.

Summary of Electrical Problem:

We purchased this property and took possession November, 2023. We were not made aware of any electrical issues by the seller at the time of purchase. In June 2024, when we opened the pool we began to experience varying degrees of electric shock while swimming in the pool, and while sitting on or touching the concrete deck or metal coping around the pool. The shock felt like a stinging sensation, especially where skin was broken. It was also felt more prominently by our four young grandchildren (ages 3-6). Our grandson, who was 5 at the time, stated to me, "Grandpa, why does your pool keep shocking me?" In addition, several adults, when sitting on the steps of the pool, would state that they felt like their legs were stinging. After doing as much research as we could, we finally realized that we have stray current going into our pool and pool deck area. We learned from a few different sources that even a very small amount of electricity (E.g. as little as 10 milliamps, which is around 1/50th the current used by a 60-watt light bulb, can be dangerous in water and potentially cause paralysis and drowning due to electric shock drowning; making any level of electricity in water a potential hazard. Although we would later be given different opinions about whether this could be dangerous or not, many electricians with knowledge warned that it would be unsafe to get in the pool.

As a first step, we contacted AEP about the problem. They sent a technician/lineman, Derrick McKinney, in response. He stated that he had been called out multiple times by the previous owners about this issue, and had warned them not to use the pool. He also said that he had done checks before, and that the problem was not AEPs fault, and suggested that I call an electrician for assistance. It was then that we realized that we had a big problem that was not disclosed upon the purchase of our house. This is, of course, a separate matter that we are trying to address through our realtor.

At that time, we took Mr McKinney's advice and called a local electrician that he suggested named Roger Yates. This man came out and also stated that he had been called to the residence about this problem previously. He checked all of my grounding connections and added bonding wires to my pump and salt chlorinator. These actions didn't change the voltage in my pool.

We continued to research online and learn as much as we could about the subject. During this process, I became familiar with Mike Holt. He is also referred to as the "Electrical Code Coach" and offers services online and classes to make electricians familiar with the National Electrical Code. Mr. Holt seems to be very well known and respected by the electrical community. I proceeded to begin a correspondence with him via email and phone calls over the next few months. He directed me, and other electricians that I subsequently hired to tend to my problem with the stray electrical current. He also instructed us to be sure and stay out of the water, and that it could be fatally dangerous. He said that even the smallest amount of voltage was unacceptable, and it could increase unpredictably.

Meanwhile, in addition, I spoke to the company that installed my pool, on two different occasions, to verify the correct implementation of an equipotential bonding grid around my pool when it was installed. I was assured by them that it was properly bonded. Currently there is an exposed #8 wire coming up from under the concrete near my pool equipment that seems to

verify this.

After exhausting all of the recommendations for improvements and corrections on my side of my electrical service, I still was left with a charge in my pool. It always varied between 1-3 volts. There were, during this process, several things that were corrected by about 5 different electricians and a pool installer. These include waterproofing some conduit fittings, installing a water bonding system, and tightening and cleaning some grounding lugs.

When I could do no more, I turned back to AEP. They sent out a team of electricians and an engineer. They spent parts of two afternoons running various tests. At the time, they seemed very perplexed by the problem and could only suggest one possible solution. They said that I should drive two additional ground rods and tie into my breaker box grounding system to hopefully mitigate some or all of the voltage. So, I contacted a master electrician that I had become acquainted with to assist me. He was very sure that this would not solve my problem, but did this work anyway. By this time, I was about \$1000+ in electrical work that had produced no results.

The master electrician, Matthew Porter offered to help me. He was able to access the electrical service box and disconnect the service neutral wire. When this happened, the voltage in my pool went to zero, and the voltage on AEP service ground wire was at 2 volts. When he reconnected it, my pool water went back to 2 volts.

In addition, while AEP was trying to determine a solution, they had disconnected my service at the pole, which also took my pool voltage to zero. When service is connected, and I turn off all power in my breaker box, the voltage is still in the pool. All of this proves beyond any doubt that the voltage is coming from AEP service line leaking voltage. Mr Porter recommended several remedies that AEP could use to correct this situation. Being unable to be present when AEP scheduled a time to come back, Mr. Porter left me with the following text to help me communicate his findings to the AEP employees:

We.....

- *Shut off both main breakers to isolate the house electrical system from power.
- *Read voltage from pool water to wet concrete at 2 volts.
- *Disconnected AEP undersized aluminum neutral in meter base.
- *Read voltage from wet concrete to undersized neutral was 2 volts.
- *With the undersized neutral isolated, the voltage from pool water to wet concrete was zero.

Possible causes...

*Check neutral and ground bonding "XO" connection on the transformer can. Paint, corrosion, loose connection, etc. can preventing adequate contact between components.

*Check adequate grounding installed at pole. Possible that not enough wire was installed below ground when the pole was set, or the soil/rock was not a suitable ground medium.

*Check stray voltage possibly originating from the neighbors house since both are being served, paralleled, from a common service lateral. It's possible, a high resistance ground in the parallel circuit at the neighbors would push more voltage to a better ground if available.

*With the 2 existing ½" x 8' rods and the 2 new 2/4" x 10' rods at the Peterman's, this could have become the best ground path on the circuit causing the standing voltage on the neutral wire to flow that direction from either or both of the TX can/pole and neighbors.

I called AEP to come out one last time. From the time they arrived (with a team of electricians and two engineers) I could not help but feel that they were only set on any solution that didn't involve them having to fix the problem. The reason I felt this way was that they would not respond in conversation to any of the suggestions I talked to them about. It felt very obvious that they were only there because they had to respond to my call. Unlike before, they did not even seem to show concern about finding the problem, which was very confusing to me. I read twice to them the reasons for the voltage and the tests they could perform to prove this, along with the remedies they could use to help me as suggested by Matthew Porter. They were completely dismissive, even to the point that they wouldn't even respond. They would just stand there and look at the ground for a minute, and then change the subject to deflect. The one thing they kept repeating and leaning on was that this was a problem with Optimum, my Internet provider. They continue to repeat this now, even though they actually cut my internet and phone lines at the pole for several days and the voltmeter still read 2.7 volts. My apologies for being upset, but I feel that anyone would have been very frustrated, upset, and at a loss.

I've had Optimum come out twice to check their grounding of my Internet. They have done this

(while rolling their eyes) and are very sure everything is done properly. I've personally never been shocked by a coax cable, let alone have voltage travel through the ground and shock me from cable service. This obviously makes no sense, and I feel this is just AEPs way of not taking responsibility for fixing the problem that is on their side.

I bought this property specifically for the pool for my grandkids. I couldn't use it all summer I've lost many many hours of sleep and spent money trying to fix this. Every single person that I hire (including the Electrical Code Coach) agree that this is not a pool bonding problem, or a problem with my electrical wiring. They ALL agree that AEP is the only one that can fix this. On top of that, I have even offered multiple times to pay for a new service drop to be ran, like a new construction would do. However, they will not even do that. I have no recourse left. I am looking for assistance in what to do next. I would also like to mention that my neighbors across the street have told us that their kids can feel a shock in their pool as well, but they swim in it anyway. I do not believe they realize the danger of this problem. If they are having the same issue, then this is obviously not all their fault too.

Please help us use our pool safely. I feel like we are stuck here with a house that we can't fully use without risking electrical shock.

Thank you for your help. At the end of the day- when the electrical service is connected, I have stray voltage. When it's disconnected- I do not. The reason is not my responsibility to diagnose. The voltage is coming in on AEP wires, so they should be responsible for fixing it and making it safe. They blame it on Optimum, but that really doesn't even matter if it were true (which I believe makes no sense anyway).

Thanks again,

Larry Peterman

Grayson, KY 41143

51 Woodland Way

Vhat we have tried
 Shut off both main breakers to isolate the house electrical system from power. Read voltage from pool water to wet concrete at 2 volts. Disconnected AEP undersized aluminum neutral in meter base. Read voltage from wet concrete to undersized neutral was 2 volts. With the undersized neutral isolated, the voltage from pool water to wet concrete was zero.
Possible causes
 Check neutral and ground bonding "XO" connection on the transformer car Paint, corrosion, loose connection, etc. can preventing adequate contact between components. Check adequate grounding installed at pole. Possible that not enough wire was installed below ground when the pole was set, or the soil/rock was not suitable ground medium.
Check stray voltage possibly originating from the neighbors house since both are being served, paralleled, from a common service lateral. It's possible, high resistance ground in the parallel circuit at the neighbors would push mor voltage to a better ground if available.
□ With the 2 existing ½" x 8' rods and the 2 new 2/4" x 10' rods at the Peterman's, this could have become the best ground path on the circu causing the standing voltage on the neutral wire to flow that direction from either or both of the TX can/pole and neighbors.