

RECEIVED

MAR 3 0 2018

PUBLIC SERVICE COMMISSION

A Touchstone Energy Cooperative

March 28, 2018

Ms. Gwen R. Pinson
Executive Director
Kentucky Public Service Commission
P. O. Box 615
Frankfort, KY 40602-0615

Re: ADMINISTRATIVE CASE NO. 2006-00494

AN INVESTIGATION OF THE RELIABILITY MEASURES OF KENTUCKY'S JURISDICTIONAL ELECTRIC DISTRIBUTION UTILITIES AND CERTAIN RELIABILITY MAINTENANCE PRACTICES

Dear Ms. Pinson:

Enclosed is Inter-County Energy Cooperative's Annual Report of Reliability pursuant to Public Service Commission Case No. 2006-00494 dated October 26, 2007.

If you have further questions or comments, please direct those to David Phelps, Vice President-Operations, 859-936-7818, <a href="mailto:davidp@intercountyenergy.net">davidp@intercountyenergy.net</a> or to Jessie Turpin, System Engineer, 859-936-7857, <a href="mailto:jessie@intercountyenergy.net">jessie@intercountyenergy.net</a>.

Sincerely,

Jerry W. Carter President/CEO

## RECEIVED

MAR 3 0 2018

PUBLIC SERVICE COMMISSION

## Electric Distribution Utility Annual Reliability Report

# SECTION 1: CONTACT INFORMATION

### **SECTION 2: REPORT YEAR**

CALENDAR YEAR OF REPORT 2.1 2017

### **SECTION 3: MAJOR EVENT DAYS**

T<sub>MED</sub> 3.1 9.7441

FIRST DATE USED TO DETERMINE T<sub>MED</sub> 3.2 Jan. 1, 2012

LAST DATE USED TO DETERMINE T<sub>MED</sub> 3.3 Dec. 31, 2016

NUMBER OF MED IN REPORT YEAR 3.4 2

NOTE: Per IEEE 1366  $T_{\text{MED}}$  should be calculated using the daily SAIDI values for the five prior years. If five years of data are not available, then utilities should use what is available until five years are accumulated.

#### SECTION 4: SYSTEM RELIABILITY INFORMATION AND RESULTS

System-wide Information

TOTAL CUSTOMERS 26047 TOTAL CIRCUITS 43

### **Excluding MED**

 5 YEAR AVERAGE
 REPORTING YEAR

 SAIDI 94.61
 SAIDI 101.78

 SAIFI 1.07
 SAIFI 1.02

### Including MED

EAR AVERAGE	REF	PORTING YEAR	
246.42	SAIDI	175.92	
1.70	SAIFI	2.00	
	246.42	246.42 SAIDI	246.42 SAIDI 175.92

#### Notes:

- 1) All duration indices (SAIDI, CAIDI) are to be reported in units of minutes.
- 2) Reports are due on the first business day of May of each year
- 3) Reports cover the calendar year ending in the December before the reports are due.
- 4) IEEE 1366 (latest version) is used to define SAIDI, SAIFI, CAIDI, and T<sub>MED</sub>

Circuit :	#'	١
-----------	----	---

Circuit #1		
Substation Name and Number	Lanca	ster (1)
2. Substation Location	Garra	rd-Buckeye Rd-Lancaster
3. Circuit Name and Number	Old H	wy 52 (3)
4. Circuit Location		
	Conns Ln, C	urtis Ln, Deer Haven Ln, Hale Ln
	<del></del>	<del></del>
5. Total Circuit Length (Miles)		4.01
6. Customer Count		7
7. Date of Last Circuit Trim		May-10
8. Outage Cause (% of Total Outage Numbers)		
	Animals	0.00%
	Lightning	0.00%
	High Wind	0.00%
	Equip. Failure	0.00%
	Deteriorated	0.00%
	Cars or Trucks	0.00%
	Insulation broke	0.00%
	/egetation/Trees	0.00%
Tn	es Cut Into Line	0.00%
<del></del>	Equipment OL	0.00%
	Rain/ Ice	0.00%
	Cased by Others	100.00%
9. Circuit 5 Year Average (SAIDI)		0.008730159
		0.55877193
10. Reporting Year (SAIDI)	<del></del>	0.011904762
11. Circuit 5 Year Average (SAIFI)		0.368421053
12. Reporting Year (SAIFI)	Do Tolean	0.308421053
13. List of Corrective Action, If Any, Taken or To I		
2018-2021 Work Plan Actions To Be Taken:	None	
	<del></del>	<del></del>
		<del></del>

_		••	
1		111	#2
	116	AIL.	##

Olicult #2			
1. Substation Name and Number	er	Highland (3)	
2. Substation Location	Lincoln-GreasyRdgRd-Stanford		
3. Circuit Name and Number		Green River (3)	
4. Circuit Location	Greasy Ridge Rd, Good	Paster Rd, KyHwy 698, Martins Trail	
Spice Ridge, Peck	Hollow, Hwy 198, Mt Salem Rd, S	hort Pike, Indian Creek, Angel Ridge Rd	
5. Total Circuit Length (Miles)		133.64	
6. Customer Count		1013	
7. Date of Last Circuit Trim		Apr-17	
8. Outage Cause (% of Total O	itage Numbers)	Api-17	
8. Outage Cause (% or Total Of	Animal	s 0.59%	
	Lightning	<del></del>	
<del></del>	High Wind	<del></del>	
	Equip. Failure		
	Deteriorate		
	Cars or Truck	<del></del>	
	Insulation broke		
	Vegetation/Tree	<del></del>	
	Trees Cut Into Line		
	Equipment O	L 0.44%	
	Rain/ Ic		
	Cased by Other	s 8.32%	
9. Circuit 5 Year Average (SAID	DI)	1.623999558	
10. Reporting Year (SAIDI)		3.001201053	
11. Circuit 5 Year Average (SA	FI)	1.224655462	
12. Reporting Year (SAIFI)		1.744323791	
13. List of Corrective Action, If	Any, Taken or To Be Taken		
2018-2021 Work Plan Actions	Го Be Taken:	None	

-		• •	110
(''	mi	117	77.

2. Substation LocationBoyle3. Circuit Name and NumberGrave	133.09
Circuit Name and Number     Grave     Circuit Location Perryville Rd, Short Line Rd, US 68 We     Riley-Gravel Switch Rd, Fork Land Rd, Scrubgrass Rd, Logan R      Total Circuit Length (Miles)     Customer Count	rel Switch (3) est, Aliceton Rd, WardsBranch Rd Rd, Craintown Road, Long Run Rd 133.09
4. Circuit Location Perryville Rd, Short Line Rd, US 68 We Riley-Gravel Switch Rd, Fork Land Rd, Scrubgrass Rd, Logan R  5. Total Circuit Length (Miles)  6. Customer Count	est, Aliceton Rd, WardsBranch Rd Rd, Craintown Road, Long Run Rd 133.09
Riley-Gravel Switch Rd, Fork Land Rd, Scrubgrass Rd, Logan R  5. Total Circuit Length (Miles)  6. Customer Count	Rd, Craintown Road, Long Run Rd 133.09
Total Circuit Length (Miles)     Customer Count	133.09
6. Customer Count	
6. Customer Count	
7 Date of Leat Circuit Trim	834
7. Date of East Circuit Tilli	Mar-12
8. Outage Cause (% of Total Outage Numbers)	
Animals	1.94%
Lightning	3.13%
High Wind	28.31%
Equip. Failure	0.25%
Deteriorated	0.02%
Cars or Trucks	3.97%
Insulation broke	0.18%
Vegetation/Trees	38.17%
Trees Cut Into Line	15.50%
Equipment OL	0.00%
Rain/ Ice	0.19%
Cased by Others	8.34%
9. Circuit 5 Year Average (SAIDI)	0.712595648
10. Reporting Year (SAIDI)	5.599440448
11. Circuit 5 Year Average (SAIFI)	0.307993007
12. Reporting Year (SAIFI)	3.057553957
13. List of Corrective Action, If Any, Taken or To Be Taken	
2018-2021 Work Plan Actions To Be Taken:	
326 (2020) Forkland Rd - Voltage Conversion 7.2kV to 14.4kV	

Circuit #4			
Substation Name and Number		Sulpher Ck.(9)	
2. Substation Location		Nelson-Gap Knob Rd-New Hope	
3. Circuit Name and Number	Raywick (1)		
4. Circuit Location	Highview Pike, Salt Lick Rd, Levelwood Rd,		
Howardstown Rd, Sc	otts Ridge Rd, FrankLe	e Rd, St Joe Rd, Raywick-StFrancis Rd	
5. Total Circuit Length (Miles)		174.98	
6. Customer Count		1150	
7. Date of Last Circuit Trim		2009	
8. Outage Cause (% of Total Outage Num	bers)		
	Animals	0.29%	
	Lightning	53.14%	
	High Wind	0.10%	
	Equip. Failure	9.86%	
	Deteriorated	0.16%	
	Cars or Trucks	21.37%	
	Insulation broke	0.00%	
	Vegetation/Trees	1.93%	
	Trees Cut Into Line	0.00%	
	Equipment OL	0.00%	
	Rain/ Ice	0.08%	
	Cased by Others	13.07%	
	<del></del>	<del></del>	
9. Circuit 5 Year Average (SAIDI)		1.388916857	
10. Reporting Year (SAIDI)		5.39015942	
11. Circuit 5 Year Average (SAIFI)		1.003541865	
12. Reporting Year (SAIFI)		2.993913043	
13. List of Corrective Action, If Any, Taken			
2018-2021 Work Plan Actions To Be Take		<del></del>	
330 (2018) Clear Creek - Voltage Convers			
331 (2021) Raywick-StFrancis - 1ph to 3pl			
333 (2019) Raywick Rd - Voltage Convers	ion		

~:			
<i>(</i> 'ı	m	111	***

Circuit #5		
Substation Name and Number	Sulpher Cl	k.(9)
2. Substation Location	Nelson-Gap Knob Rd-New Hope	
3. Circuit Name and Number	Howardsto	own(2)
4. Circuit Location		
	Stiles Rd, Scott Rd, Howa	ardstown Rd, Walter Hall Rd
5. Total Circuit Length (Miles)		53.6
6. Customer Count		284
7. Date of Last Circuit Trim		May-14
8. Outage Cause (% of Total Outage Numbers)		
	Animals	0.11%
	Lightning	2.38%
	High Wind	46.71%
	Equip. Failure	29.41%
	Deteriorated	0.06%
	Cars or Trucks	0.00%
	Insulation broke	0.00%
_	Vegetation/Trees	20.76%
	Trees Cut Into Line	0.00%
	Equipment OL	0.00%
	Rain/ Ice	0.00%
	Cased by Others	0.58%
9. Circuit 5 Year Average (SAIDI)		1.484364646
10. Reporting Year (SAIDI)		3.559800469
11. Circuit 5 Year Average (SAIFI)		1.004192121
12. Reporting Year (SAIFI)		2.982394366
13. List of Corrective Action, If Any, Taken or T	o Be Taken	
2018-2021 Work Plan Actions To Be Taken:		
332 (2020) Howardstown Rd - 1ph to 3ph Conv	omion	

~		••	110
1 1	mi	117	#6
_		41L	$\mathbf{m}$

Circuit #0	
Substation Name and Number	T. Adams (10)
2. Substation Location	Mercer-Dry Branch-Harrodsburg
3. Circuit Name and Number	Dixville(2)
4. Circuit Location	
	Rose Hill, Perryville Rd, Dixville
5. Total Circuit Length (Miles)	64.51
6. Customer Count	619
7. Date of Last Circuit Trim	Apr-11
8. Outage Cause (% of Total Outage Numbers)	
Anima	als 0.29%
Lightni	ng 6.03%
High Wi	nd 21.32%
Equip. Failu	ure 2.81%
Deteriorat	ed 0.00%
Cars or Truc	cks 0.00%
Insulation bro	ke 0.00%
Vegetation/Tre	es 0.92%
Trees Cut Into L	ine 0.87%
Equipment	OL 0.00%
Rain/	Ice 0.13%
Cased by Othe	ers 67.63%
9. Circuit 5 Year Average (SAIDI)	0.850504674
10. Reporting Year (SAIDI)	2.181690899
11. Circuit 5 Year Average (SAIFI)	0.693904229
12. Reporting Year (SAIFI)	2.363489499
13. List of Corrective Action, If Any, Taken or To Be Taken	
2018-2021 Work Plan Actions To Be Taken:	
305 (2019) Oakland Ln - 1ph to 2ph Conversion	<del> </del>
306 (2019) Mackville Rd - 1ph to 2ph Conversion	

|--|

Ollouit #1		
Substation Name and Number	Gooch(11)	
2. Substation Location	Lincoln-Rice Ln-Stanford	
Circuit Name and Number	Danville(3)	
4. Circuit Location		
	Carmans Lr	n, Crawford Ln, US 150
5. Total Circuit Length (Miles)		12.83
6. Customer Count		265
7. Date of Last Circuit Trim		Sep-16
8. Outage Cause (% of Total Outage Numbers)		
	Animals	4.99%
	Lightning	0.00%
Hi	igh Wind	46.84%
Equip	o. Failure	0.15%
Dete	eriorated	0.00%
Cars o	or Trucks	0.00%
Insulation	on broke	0.00%
Vegetation	on/Trees	0.00%
Trees Cut	Into Line	0.00%
Equip	ment OL	0.00%
	Rain/ Ice	0.00%
Cased b	y Others	48.02%
9. Circuit 5 Year Average (SAIDI)		0.921983368
10. Reporting Year (SAIDI)		2.509119497
11. Circuit 5 Year Average (SAIFI)		0.680871113
12. Reporting Year (SAIFI)	<del></del>	3.226415094
13. List of Corrective Action, If Any, Taken or To Be Taken		0.220-1000-1
2018-2021 Work Plan Actions To Be Taken:	None	<del></del> _
LOTO LOLI TTOIN I IQUI AGGODIO TO DO TONGUI.	140110	

# Electric Distribution Utility Annual Reliability Report

Additional pages may be attached as necessary SECTION 6: VEGETATION MANAGEMENT PLAN REVIEW

Inter-County Energy completed the third year of its 6 year vegetation management plan. I Energy is closely monitoring the results of the cycle progress.	nter-County
SECTION 7: UTILITY COMMENTS	