

3. Provide the results of hydrogen sulfide tests performed on BTU s system during the last 12 months. Explain how the tests were conducted.

4. Is BTU purchasing natural gas from recently drilled wells? If yes, provide the odor level and the hydrogen sulfide content of the gas produced from the new wells.

Done at Frankfort, Kentucky, this 7th day of July, 1999.

By the Commission

ATTEST:

Executive Director