

David S. Samford david@gosssamfordlaw.com (859) 368-7740

July 17, 2013

JUL 1 7 2013

RECEIVED

PUGLIC SERVICE COMMISSION

Mr. Jeffrey Derouen Executive Director Kentucky Public Service Commission P.O. Box 615 211 Sower Boulevard Frankfort, KY 40602

Re: PSC Case No. 2013-00158, In the Matter of: South Kentucky RECC Alleged Failure to Comply With KRS 278.042

Dear Mr. Derouen:

Via Hand Delivery

Enclosed please find for filing with the Commission in the above-referenced case an original and ten (10) copies of the Response to Informal Conference Memorandum on behalf of South Kentucky Rural Electric Cooperative Corporation. Please a return file-stamped copy to me.

Do not hesitate to contact me if you have any questions.

Sincerely yours,

David S. Samford

Enclosures

M:\Clients\7100 - South Kentucky Rural Electric Coop Corp\ Correspondence\Lt. to Jeff Derouen - 130717.docx

COMMONWEALTH OF KENTUCKY

BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

SOUTH KENTUCKY RECC

ALLEGED FAILURE TO COMPLY WITH KRS 278.042

CASE NO. 2013-00158

)))

)

)

SOUTH KENTUCKY RURAL ELECTRIC COOPERATIVE CORPORATION'S **RESPONSE TO INFORMAL CONFERENCE MEMORANDUM**

Comes now South Kentucky Rural Electric Cooperative Corporation ("SKRECC" or "South Kentucky"), by and through counsel, and makes its response to the Informal Conference Memorandum of July 1, 2013, as follows:

I. Procedural History

On July 30, 2012, Ronnie Parrett, a SKRECC lineman, sustained injuries to both arms and hands after making contact with an energized 7200-volt conductor while working on a job site at 2750 East Williamsburg Road in Whitley City, McCreary County, Kentucky.

As a result of this incident, the Kentucky Public Service Commission ("Commission"), by and through Mr. Jeffrey C. Moore, Electric Utility Investigator, Engineering Division, investigated the facts leading up to and following the injury. Mr. Moore reduced his findings to an Incident Investigation Report ("the Report") dated December 3, 2012.

This Report resulted in a Show Cause Order by the Commission dated May 6, 2013 which:

JUL 17 2013

PUBLIC SERVICE COMMISSION

RECEIVED

1. Alleged that SKRECC violated KRS 278.042 and 18 provisions of the National Electric Safety Code ("NESC") and of SKRECC's Safety Manual¹;

2. Required SKRECC to respond to the allegations contained in the Report within twenty (20) days; and,

3. Scheduled a hearing at the Commission on August 27, 2013 for the purpose of presenting evidence concerning the alleged violations referenced above and showing cause why SKRECC should not be subject to the penalties prescribed in KRS 278.990(1).

On June 7, 2013, SKRECC filed its formal Response to the Commission's May 6, 2013 Order. Subsequently, on June 27, 2013, an Informal Conference was held at the Commission's Offices to discuss all aspects of the case.

Following that Informal Conference, Commission Staff provided a Memorandum which summarized the discussion held at the Informal Conference and which also requested that SKRECC provide:

1. Specific and detailed documentation addressing its corrective actions, revised safety policies and training programs put into place following this accident;

2. Explicit information pertaining to the policies and procedures SKRECC has or will enact pertaining to the vine management program;

3. Itemized monetary costs incurred by the institution of the training programs, safety policies, vine management and methods and the purchase of related equipment and material;

4. The material factual issues contained in the Report to which it does and does not agree;

¹ SKRECC had adopted as its safety manual the American Public Power Association ("APPA") Safety Manual, 14th Ed. (2008) at the time of the incident.

5. All of this information should be filed by July 18, 2013.

SKRECC's compliance with these requests follows.

II. Discussion of Specific Corrective Actions, Vine Management Program, And Monetary Costs Associated with Employee Training, Vine Management and Equipment and Material

A. <u>Corrective Action and Vine Management Program</u>

Ronnie Parrett was injured while trying to remove a vine that was growing up a single phase dead end pole which was energized. He was ascending beside the pole in an insulated bucket and removing vines while moving up the side of the pole. SKRECC believes the vine made contact with the 7,200 volt stinger wire which runs from the primary conductor to the high side bushing on the transformer. Immediately after the contact the other crew members on site issued a "mayday" call and began bucket rescue. Mr. Parrett was removed from the bucket and evacuated by ambulance to the local helipad where he was picked up by helicopter and flown to the University of Kentucky burn center.

The following morning, July 31, 2012, South Kentucky's Vice President of Engineering and Operations, Dennis Holt, met with the Somerset Construction and Right-of-Way employees and advised them of the facts of the accident. All employees were informed to treat vines extending near the primary line or primary bushing on a transformer as potentially energized and the line should be de-energized and/or rubberized insulating safety cover up used to isolate the vine from the primary wire before it is removed. In addition, the same message was relayed by Mr. Holt to all district office operation managers via telephone with known details of the accident and instructions to treat all vines as energized if they are near the primary conductor.

On August 8, 2012, Mr. Holt met with Paul Merrick, South Kentucky's Right-of-Way Manager and they decided for the in-house right-of-way employees to utilize rainy days to drive

the system and cut vines from the ground and clear around the base of the pole. By cutting a gap in the vine it will kill any growth going up the pole and delay the re-growth of the vine. In addition, the pruners used to cut the vines would be made available to all servicemen and construction crews so they could also cut vines while performing their routine duties. Instructions were also given during the handout of these pruners that all vines located near an energized conductor should be treated as energized and not cut from the ground without deenergizing the line or utilizing insulated cover up.

On August 16, 2012, Mike Higgenbotham, the crew foreman on the job site went over the details of the accident with all employees and again emphasis was put on treating vines as potentially energized.² At this same safety meeting, SKRECC introduced a new product which could be used for removing vines from primary lines from the ground safely by using an insulated extend-stick and rubber gloves. The device is called a "de-viner" and SKRECC ordered three units for testing with the intention of stocking them on all trucks if they proved to be a solution to the problem. After several weeks of testing it was determined that in many instances the de-viners were causing significant problems with telephone and cable TV drops as they were being damaged while removing the vines.

During the remainder of the foliage season vines were cut and removed from dozens of poles; however, as the foliage began to emerge in May 2013, and the advent of a wet spring and summer has caused significant foliage growth, it has become evident that cutting alone will not control the re-growth of some vines as they have already returned and grown several feet up poles that were just cleared last fall. It is also evident that in addition to cutting the vines a herbicide application must be applied to control the growth. This can be problematic in several areas as SKRECC cannot apply herbicide in the Daniel Boone National Forest and also herbicide

² An attendance sheet for this meeting is attached hereto as Exhibit 1.

used in back yards and around cropland could damage lawns and or crops. There are also other limitations on utilizing herbicides as they cannot be applied after foliage has fallen from the deciduous plants and they cannot be applied near streams of water or in windy conditions. Mr. Merrick and Mr. Holt met with a representative from Dupont Chemical Company on May 23, 2013 to discuss these concerns and were advised that there are various herbicide mixtures that would kill the vine and not harm the lawn and/or crop. In addition DOW chemical also has different mixtures of various herbicides to obtain the best result; however, this still does not address the ban on herbicides in the Daniel Boone National Forest.

South Kentucky recognizes that vines growing on utility poles can pose a danger to line technicians and to the general public, if the vines are growing into the high voltage wires. They can also present a climbing hazard for line technicians including telephone and cable employees. Historically, SKRECC has removed vines from poles during regular scheduled trim cycles and also during on-going hammer sound inspections. In addition, large concentrations of vines have been written up during routine inspection and service orders given to SKRECC's right-or-way department to cut and clear the vines.

In order to better control vine growth it has became evident that SKRECC's in-house crews are not able to cover the entire system for vine removal as the herbicide must be applied in dry weather and reallocating the in-house right-of-way employees during this time would lead to significant lag times in responding to member needs on tree trimming and removal. In 2012 South Kentucky performed 1,736 right-of-way service orders.

SKRECC therefore took bids from its existing right-of-way contractors for providing a two man crew to work specifically on vines located throughout the system. Phillips Tree Experts will be adding the two man crew and they will be doing vine removal and spraying during the

foliage season until the entire system has been covered. SKRECC estimates this will take two years to perform. After the initial clearing of vines SKRECC will have identified any heavy vine growth areas (particularly kudzu) and will be making special efforts to check and trim these areas on an annual basis. All vines encountered on a pole and/or guy wire are to be cut at the base of the facility and herbicide applied in areas where it is permissible to do so. Vines shall never be pulled off energized facilities when at or above energized equipment. In the event vines are found to be at or above energized equipment the vine is to be removed from the area with an insulated extension stick, or the line de-energized and the vine removed, or rubber cover-up applied to the line prior to vine removal.

To better facilitate this work and obtain the best efficiency, a South Kentucky Employee will need to be assigned to drive and scout the area in front of the vine crew. There are many lines and areas that have no vine issues and it would be more cost effective to utilize a South Kentucky Employee to spot individual poles and record the pole number. The assigned vine crew could then drive directly to the pole in question and perform their work utilizing a GPS unit with digital maps of South Kentucky's poles and lines installed.

While re-growth can occur in some areas and complete control will be an ongoing effort SKRECC feels this new program will identify and control ongoing vine issues throughout the system.

South Kentucky is also in the process of changing from the 14th Edition of the American Public Power Association (APPA) Safety Manual to the 15th Edition. Its in-house safety committee has been meeting and has reviewed all sections and subsections of the safety manual and assigned a corrective action for every potential violation. Once this is in place, SKRECC will be moving from a "five foot rule" in which an employee working on an ungrounded

energized line must put on rubber gloves and sleeves before approaching within five feet of the energized line to a "ground to ground; cradle to cradle" rule which requires employees to utilize rubber gloves and sleeves from the moment they leave the ground or cradle on a bucket truck until they return to the ground or cradle. Employees are aware of this change and have already made this adjustment.

Also, going forward South Kentucky plans on making it company policy to perform annual training for all employees on the dangers of vine growth on its poles and the need to safely isolate the vine from the power source through de-energizing the line or insulating the vine from any energized line with rubber cover up.

B. <u>Monetary Costs Associated with Employee Training</u>, <u>Vine Management and Equipment and Material</u>

South Kentucky has not tracked the specific amount spent on vine removal since the accident but conservatively estimates that 2% to 3% of the time spent by in-house and contract right-of-way crews, was spent removing and/or spraying vines. This would represent \$54,000 to \$81,000 for the 2012 calendar year as the right-of-way budget for South Kentucky was slightly over \$2.7 million last year. SKRECC is able to quantify several expenditures related to addressing the accident and vine removal. They are as follows:

1. On July 31, 2012 approximately one hour was spent with each outside employee reviewing the accident. In the Somerset office the accident was reviewed by the operations manager and in each district office it was reviewed by the district construction manager. This cost was approximately \$2,646.³

2. On August 16, 2012 three safety meetings were held throughout the day with all employees to review the accident and discuss vine safety and our proposal to utilize de-viners to

³ This cost is itemized in Exhibit 2 attached.

address the issue. Each safety meeting lasted approximately 2 hours. In addition, employees from three district offices have a one-half hour drive time each way resulting in a three hour commitment. One of the district office requires almost one hour drive time which results in four hours for each employee to attend the meeting and several employees were required to be at all three meetings (executive staff, CEO, safety department and the crew leader involved in the accident) these employees spent six hours in the safety meetings. This resulted in a final cost of \$13,256.81, excluding vehicle costs for transportation to and from the Somerset Office from the districts.⁴

3. SKRECC has not tracked the daily vine removal performed by its right-of-way employees; however, SKRECC has devoted three specific days to vine removal by these employees and their cost for these three days was \$6,218.31, inclusive of labor and fringe benefit costs, but not transportation costs.⁵

4. Prior to the accident South Kentucky had purchased vine pruners for many of its outside employees over the last several years. SKRECC has included only the cost of pruners, sprayers, and de-viners purchased since the accident (only three de-viners were purchased for testing purposes and found to cause damage to phone and cable T.V. lines). These costs total \$417.71.⁶

5. Going forward South Kentucky will have one employee and one two man contract crew assigned to perform vine removal. The cost of this employee including his transportation

⁴ This cost is itemized in Exhibit 3 attached.

⁵ This cost is itemized in Exhibit 4 attached.

⁶ This cost is itemized in Exhibit 5 attached.

and fringe benefits and the cost of the right-of-way crew are estimated to be ongoing for 18 months to two years. The total estimated cost of this is \$217,146 on an annual basis.⁷

6. The total amount of quantifiable costs for vine control to date is 22,537,81, and the amount expected to be spent in the future for vine control is $217,146.^8$

III. Material Factual Issues

SKRECC essentially agrees with all of the material factual issues contained in the Report. However, SKRECC states that the judgment made by its personnel in this incident was not inconsistent with policies and procedures then in effect and was not a willful violation of any law, rule, order or policy.

IV. Conclusion

Hopefully, from the lengthy discussion between SKRECC and Commission Staff held at the June 27, 2013 Informal Conference, and the written explanation of the numerous mitigation activities taken by SKRECC in the hours, days and months following this incident, it should be abundantly clear that SKRECC takes very seriously its obligation to provide and foster a safe work environment for its employees and customers.

Ronnie Parrett has been a dedicated employee and member of the SKRECC family for more than nine years. SKRECC regrets that the incident resulting in Mr. Parrett's injuries ever happened. Although the facts surrounding the incident are unique and the serious result not easily foreseen, SKRECC has learned a valuable lesson regarding the ability of an otherwise seemingly harmless vine to act as a conductor of electricity. This lesson has resulted in an immediate and dedicated effort by SKRECC, at substantial future expense, to put into place the aggressive vine management program described above.

⁷ This cost is itemized in Exhibit 6 attached.

⁸ These costs are contained in Exhibit 7 attached.

While SKRECC wishes that Mr. Parrett's injuries had never occurred, they have been the catalyst for the implementation of a program which should prevent a similar incident from ever happening again.

SKRECC appreciates the attention which the Commission has paid to this incident and its willingness to work with SKRECC to fix the problem.

SKRECC respectfully requests that the Commission accept the above described mitigation efforts as an adequate and effective response to this situation, and, further, that the Commission dismiss the Show Cause portion of this case and determine that no penalty under KRS 278.990 should be assessed against SKRECC.

This 17+1 day of July, 2013.

Respectfully submitted,

Mark David Goss David S. Samford GOSS SAMFORD, PLLC 2365 Harrodsburg Road, Suite B325 Lexington, Kentucky 40504 (859) 368-7740 mdgoss@gosssamfordlaw.com

Counsel for South Kentucky Rural Electric Cooperative Corporation

5

TOPIC
Accident Review, Minimum Approach Distance
LOTO

1

EXHIBIT

INSTRU	ICTOR
EB	<u>MR</u>

TIME	DATE
7:30	8/16/12

ACTION OF A MALERAL AND

PRINT NAME	TEAM	
HARLA STOUT		SIGNATURE
Edward Black	CONST	Harlan Stout
DENNIS HOLT	Safet)	Et a Rhigh
DENNIS HOLT	Engeneering + Operation	Dennis Holf
Pave Condiff	const	horene lundell
Rainey Jones	Mant	Rodney Chies
Any Actor	CED	
Allen Anderson		Chen Carton
JEFF Crate	(EO	allen anderson
Alice CRAig	Staking Aut	Jette Croce
GILLE GEALS	CALL CENTER	Aliel Craine
Cathy Jones	Servia letters	attur Amas
ROBIN PENDERALASS	Caphier,	
Sime Musse	+ band Caslier	Chilli Hardler mars
Nora Wall	Member Services	
Joy Bullocke	Communications)	ora Wall
Toni Shadoar		Je Bullock
	Wayne Co	Ju LA
Kenneth CBall	Dispatch	Show to chall
David Sparks	lect Surs	FAIEZ-
Doug Carter	IT	(by la
		- 14 6
		/

the local property and the second second

TOPIC Accident Review, Minimum Approach Distance LO/TO	INSTRUCTOR EB MR	TIME 7:30	DATE 8/16/12
PRINT NAME	TEAM		
Ton ho Chitwood	whitle City	Dora A	IGNATURE
Sondra Stockton	Service Center	Sondin	Chruppol
Brian Young	Staking	the m	Schore
Allan Coffey	MEMBER SERVICES	LUIX	~
Tony TupmAn	METERING-	Gon	Codesta
Donnie Burdine	Metering	Donnie	Burdne
Jusian Sandlins	Metania q		alu
Mitch Robertson	stating	Mith West	
ROBERT Edwards	MAINT	Roberton Edu Da	. L
Michael Algolabothen	Whiteg city	ALL Lat	
LedFord Chitwood	Rioin	Lifford C	htwood
Karen Black	H.R.	Here Bla	ch
DANNYFINEST	GARAGE	10amp 7	une
Donald Ridner	Ridiwi	Done del.	Richne
JOE STRUNK	Garage	los that	A
JIM EASTHAN	SAFETY .	Figuets	
Harvey Parsous	Dispatch	Hawen Darson	
Stephen Johnson	Mgmt Team	D. John &	C

and managed and the state of the state

TOPIC Accident Review, Minimum Approach Distance LO/TO	INSTRUCTOR EB MR	TIME	DATE
20/10		7:30	9/16/12
PRINT NAME	TEAM		
Haul Wilson	ROM	D. Die	SIGNATURE
Kandy Mounce	R.OW.	Fairen	illoon
DELVANWATERS	11.000.	10m fp Mo	We ce
RUBY & DOMETRICAL	W.C.	Lieam	MAT
PROTEFAILED	MANAGEMENT	Rely YA	Honsen)
STEVE BURKE	MONTICELLO	st	E Burke
Brian Taylor	Whitley City	- Brin	This
KENNY Burton	Montigallo	VAL	say let
David Vorhungle	MAR E. II	Det Det	
Denss/ Mc Ginnis	- monullur	Lavid Upc	herely
	Staking	Kan m	China
SANEK	Member Services	LAD 6-00	Blom
Jerry whitaker	Cons	Crow las	kita)
Tominy Type	Building/6rounds	Torm Tu	and the fer
Michael Ramsey	Safety	M-11	1 P
		Millhare	& Famaet

٠.

~

1--

where the party property

TOPIC Accident Review, Minimum Approach Distance LO/TO		TIME 10×00	DATE
PRINT NAME	TEAM		0/16/12
Chuck BALL	Menteer Serie		NATURE
Bruce Parkey	Encineering	Blue De	pell
Iracy Hopper	Russell	I nan Heat	(Ab)
Missy Johnson	HR		
Kelinda Brown	Engineering	Relinda Bro	
Jeannie Wood	Accounting	$1 \rightarrow 1 \rightarrow$	
JAN BAKER	Acct.	Dance alos	<u>y</u>
Christy Stevens	Accounting	NCL	
LANA Sidwell	Accounting	Dana Store	m
Mary Lou Henderlight	Accounting	mary Lon He	LIE A.
Christing Cundiff	I.T.	Ch ti	nderlight
lammy Cash	Eng Dept	Danny Co	DD
Jamie Evans	Call Center	Jamie Wan	
Serry Sutton	Servila Center		
Glenda Bell	Servicy Center	Blenda Bell	erc
banne Bryant	Whitley City	Jeanne brin	1
Nancy Duncan	Monticello	Tanas Durica	
Copy here thillips	Manticello	Masta Mail	
r -		- chand der tation	(H)

100 3 ----

TOPIC Accident Review, Minimum Approach Distance LO/TO	INSTRUCTOR EB MR	TIME	DATE
		10:00	8/16/12
PRINT NAME	TEAM		• • • •
Ricky Buwling	MONFICEILO	DA	SIGNATURE
DAVID Prezey		- weky	Server
GRa FRisman	MONTICELLO	Wacte,	King !!
	Monticelle	Aley Crian	~ /0
Joe Landon	- FT	heard	ar
David Trimble	Techinal Services Disp	KIL & D	01
Stephen Johnson	Most To	ATCHEV PL	any funder
Mike V Strunk	Marct Team	N. Matrice	
	W.K Service	M. ho ge	Sheets
Brodley Coffee Jr	whith city	Bush latt in	
Mitchell Staton	Albany	N. St. M. S.	11
Mike Qaniels	manticello	Invente Da	- ser
Erick Amorp		Thirthe Sa	nuels
Ricky Fletcher	A/Dany	antina	
	Albany	RIG. A.	4
Robelt flullips	Montice 110	HA -	
Downd Huches	Monticello	-TS D	11 6
GARRY E. NEA	MONTICELLO	1606	the spectra
DON BETHER		C.	see
	ANI/SPAKING	C TT	
David W: thers	Member Services	Stat	
Leon Wooldridge	RUSSP.11	Leave Out	Adaite .
)			- www.yo

TOPIC Acoldent Review, Minimum Approach Distance LO/TO	INSTRUCTOR EB MR	TIME 	DATE 8/16/12
PRINT NAME	TEAM		IGNATURE
Shelia M. Richardson Heather Idewine	Russell Dist.	Shelin R. R.	chardson
RUBY KPATTERSON	Somerset Dist. MANAGEMENT	allother h	laurie
Bothe Smith	Somerset	Holing In	NOP
DENNIS HOLT	Emaneserio, + Operationo		F
			1

TOPIC Accident Review, Minimum Approach Distance LO/TO	INSTRUCTOR EB MR	TIME 	DATE	
PRINT NAME	TEAM		7/16/12	
Danidary	CONST	8	GNATURE	
JACK & WILLIS	Const	- Contro	11.1	
Mick leger	11 11	- 7 And 2.	N Shi	_
Son Staury	11 11	here	6	_
Dennis Reynolds	const	Dinnis Py	11	_
Barney Singlaton	Const	Dh B. L	m002	\neg
ISHMARI HELTON	Const.	OP DR	<u> </u>	-
Robert Phelps	Const	All All	Hatton	_
Darrell Scruggs	Const	Danell Scar		\neg
Stephen DeBord	11 11	Stephen DeBrid	igne	
Stephen Johnson	Mapel Teon	- Aller Clina		_
DAUED Durham	WARELOOSE	- Aller	0	_
Fodie Tombinson	Const	El a ci da	wham	_
Steve Harris	const	Here Con	skuner	-
WARK ward	LONST	Malinik	<u> </u>	-
Daniel Coomer	Const.	Pa il		_
Perch Marrath	const	Derde Maint	mi	_
John Jones	BUSSEI	the A	14	
		for you	e	

TOPIC Accident Review, Minimum Approach Distance <u>LO/TO</u>	INSTRUCTOR EB MR	TIME 2:00	DATE 8/16/12
PRINT NAME	TEAM		
Man Nen	Albany Constantion		IGNATURE
Byron Koonta		- cantu	Viet
Haul Tucken	1 ATT ATT	- Dan	foreing -
Onille Brown	1410AN/Const.	Alle	inter
	DE CHUYFI	- augh	Bring
	KS Construction	At the	and
Bay Bray	Const.		+ TR
Chris Cain	Const.	and	\sim
MORRIS MURPHY	WAREHOOSE	Monis Mal	
Teresa Bledsoe	Russell	Aluna Co.	
TAMMY Shipp	CARL contur		usof
Melisa Pile		California Cal	The second secon
Ludy Keith	Dudalla	Juccio	
Tonya Slagle	Finge Chille	Judia to	ett
Frances Guffey	Coma Sada M	patricello	
Seff Greek	takee Suppey	(longy	
	FIRAMER TRAM	ALL A	
	Cashier	ashley x	teriko
Gay BRINSON	Service Center	Gay Drinson	
Sharon B Leith	Service, Center	apon B Leal	/
1	1.000	equine to the the	

water of a particular particular sector and particular sector and

TOPIC Accident Review, Minimum Approach Distance LO/TO	INSTRUCTOR EB MR	Тіме 2:00	DATE 8/16/12
Fonnie Blevins	TEAM		NATURE
Linla Harnes	Engineering Cashiek	Jonie Ble	un
Jallus Hopkins	Tech Services	Dall Hop	٩

Expenses related to vine control

Meeting held with Outside Employees to go over the accident of July 30 and advise how to address vine issues - Meeting held on July 31, 2012 with Somerset Personnel and each district office had their own meeting with the district manager.

	Hourly		Total	Fringe	Total with
Employee #	Wage	Hours	Hourly	Benefits 60.63%	Fringe Benefits
400	#00.07		400 00		
198	\$28.07	1	\$28.07	\$17.02	\$45.09
227	\$32.61	1	\$32.61	\$19.77	\$52.38
275 391	\$50.85	1	\$50.85	\$30.83	\$81.68
	\$25.31	1	\$25.31	\$15.35	\$40.66
265 271	\$28.23	1	\$28.23	\$17.12	\$45.35
	\$31.87	1	\$31.87	\$19.32	\$51.19
377	\$25.66	1	\$25.66	\$15.56	\$41.22
453	\$24.89	1	\$24.89	\$15.09	\$39.98
290	\$27.42	1	\$27.42	\$16.62	\$44.04
565	\$28.91	1	\$28.91	\$17.53	\$46.44
616	\$17.03	1	\$17.03	\$10.33	\$27.36
460	\$23.08	1	\$23.08	\$13.99	\$37.07
342	\$23.39	1	\$23.39	\$14.18	\$37.57
472	\$21.53	1	\$21.53	\$13.05	\$34.58
373	\$30.20	1	\$30.20	\$18.31	\$48.51
232	\$34.00	1	\$34.00	\$20.61	\$54.61
384	\$27.37	1	\$27.37	\$16.59	\$43.96
447	\$25.43	1	\$25.43	\$15.42	\$40.85
284	\$28.76	1	\$28.76	\$17.44	\$46.20
343	\$27.93	1	\$27.93	\$16.93	\$44.86
528	\$24.58	1	\$24.58	\$14.90	\$39.48
358	\$31.53	1	\$31.53	\$19.12	\$50.65
267	\$27.42	1	\$27.42	\$16.62	\$44.04
628	\$21.87	1	\$21.87	\$13.26	\$35.13
545	\$29.20	1	\$29.20	\$17.70	\$46.90
523	\$23.98	1	\$23.98	\$14.54	\$38.52
654	\$21.17	1	\$21.17	\$12.84	\$34.01
242	\$32.16	1	\$32.16	\$19.50	\$51.66
584	\$26.06	1	\$26.06	\$15.80	\$41.86
600	\$23.18	1	\$23.18	\$14.05	\$37.23
598	\$24.30	1	\$24.30	\$14.73	\$39.03
623	\$21.82	1	\$21.82	\$13.23	\$35.05
625	\$25.33	1	\$25.33	\$15.36	\$40.69
627	\$24.28	1	\$24.28	\$14.72	\$39.00
624	\$20.06	1	\$20.06	\$12.16	\$32.22
					-



364	\$27.06	1	\$27.0 6	\$16.41	\$43.47
433	\$26.38	1	\$26.38	\$15.99	\$42.37
635	\$21.67	1	\$21.67	\$13.14	\$34.81
634	\$21,82	1	\$21.82	\$13.23	\$35.05
478	\$24.83	1	\$24.83	\$15.05	\$39.88
524	\$23.51	1	\$23.51	\$14.25	\$37.76
192	\$27 .60	1	\$27.60	\$16.73	\$44.33
150	\$36.16	1	\$36.16	\$21.92	\$58.08
560	\$29.60	1	\$29.60	\$17.95	\$47.55
329	\$30.12	1	\$30.12	\$18.26	\$48.38
519	\$21.72	1	\$21.72	\$13.17	\$34.89
458	\$19.42	1	\$19.42	\$11.77	\$31.19
209	\$29.41	1	\$29.41	\$17.83	\$47.24
301	\$30.04	1	\$30.04	\$18.21	\$48.25
461	\$24.97	1	\$24.97	\$15.14	\$40.11
508	\$24.30	1	\$24.30	\$14.73	\$39.03
656	\$18.52	1	\$18.52	\$11.23	\$29.75
599	\$24.93	1	\$24.93	\$15.12	\$40.05
629	\$21.77	1	\$21.77	\$13.20	\$34.97
626	\$21.77	1	\$21.77	\$13.20	\$34.97
324	\$29.84	1	\$29.84	\$18.09	\$47.93
592	\$21.82	1	\$21.82	\$13.23	\$35.05
451	\$26.02	1	\$26.02	\$15.78	\$41.80
569	\$21.82	1	\$21.82	\$13.23	\$35.05
489	\$24.30	1	\$24.30	\$14.73	\$39.03
304	\$27.83	1	\$27.83	\$16.87	\$44.70
363	\$27,38	1	\$27.38	\$16.60	\$43.98
507	\$23.41	1	\$23.41	\$14.19	\$37.60

Total Vine Control Safety Meeting Cost

\$2,646.38

Expenses related to vine control

Safety Meeting with all employees to review the accident and go over vine control Held on August 16, 2012

	Hourly		Total	Fringe	Total with
Employee #	Wage	Hours	Hourly	Benefits 60.63%	Fringe Benefits
198	\$28.07	2	65C 44		•
227	\$32.61	2 6	\$56.14 \$195.66	\$34.04	\$90.18
275	\$50.85	6		\$118.63	\$314.29
391	\$25.31	2	\$305.10	\$184.98	\$490.08
265	\$28.23	2	\$50.62	\$30.69	\$81.31
602	\$23.86	× 6	\$56.46	\$34.23	\$90.69
395	\$24.89	2	\$143.16	\$86.80	\$229.96
525	\$17.98	2	\$49.78 \$25.00	\$30.18	\$79.96
126	\$30.79		\$35.96	\$21.80	\$57.76
652	\$30.79 \$14.70	2	\$61.58	\$37.34	\$98.92
657	\$14.70 \$14.35	2	\$29.40	\$17.83	\$47.23
309	\$14.35 \$23.98	4	\$57.40	\$34.80	\$92.20
491		2	\$47.96	\$29.08	\$77.04
578	\$25.11	2	\$50.22	\$30.45	\$80.67
526	\$20.73	3	\$62.19	\$37.71	\$99.90
439	\$23.43	2	\$46.86	\$28.41	\$75.27
653	\$21.94 \$20.00	2	\$43.88	\$26.60	\$70.48
421	\$26.92	2	\$53.84	\$32.64	\$86.48
52 9	\$23.68	2	\$47.36	\$28.71	\$76.07
	\$17.51	2	\$35.02	\$21.23	\$56.25
562	\$23.68	3	\$71.04	\$43.07	\$114.11
564	\$29.54	2	\$59.08	\$35.82	\$94.90
271	\$31.87	2	\$63.74	\$38.65	\$102.39
377	\$25.66	2	\$51.32	\$31.12	\$82.44
453	\$24.89	2	\$49.78	\$30.18	\$79.96
378	\$24.87	2	\$49.74	\$30.16	\$79.90
290	\$27.42	2	\$54.84	\$33.25	\$88.09
565	\$28.91		\$173.46	\$105.17	\$278.63
616	\$17.03	2	\$34.06	\$20.65	\$54.71
563	\$32.55	2	\$65.10	\$39.47	\$104.57
362	\$29.88	2	\$59.76	\$36.23	\$95.99
460	\$23.08	2	\$46.16	\$27.99	\$74.15
488	\$24.09	2	\$48.18	\$29.21	\$77.39
658	\$19.80	2	\$39.60	\$24.01	\$63.61
647	\$48.76		\$292.56	\$177.38	\$469.94
342	\$23,39	2	\$46.78	\$28.36	\$75.14
472	\$21.53	2	\$43.06	\$26.11	\$69.17
373	\$30.20	3	\$90.60	\$54.93	\$145.53
291	\$51.54	6 \$	\$309.24	\$187.49	\$496.73
232	\$34.00	3 \$	102.00	\$61.84	\$163.84



384	\$27.37	3	\$82.11	\$49.78	\$131.89	
447	\$25.43	3	\$76.29	\$46.25	\$122.54	
284	\$28.76	3	\$86.28	\$52.31	\$138.59	
432	\$24.73	2	\$49.46	\$29.99	\$79.45	
566	\$28.18	2	\$56.36	\$34.17	\$90.53	
343	\$27.93	3	\$83.79	\$50.80	\$134.59	
571	\$17.45	2	\$34.90	\$21.16	\$56.06	
528	\$24.58	6	\$147.48	\$89.42		
455	\$24.56	3	\$73.68		\$236.90	
258	\$28.81			\$44.67	\$118.35	
358		2	\$57.62	\$34.94	\$92.56	
	\$31,53	3	\$94.59	\$57.35	\$151.94	
594	\$20.21	2	\$40.42	\$24.51	\$64.93	
636	\$17.53	2	\$35.06	\$21.26	\$56.32	
644	\$19.31	2	\$38.62	\$23.42	\$62.04	
200	\$21,94	2	\$43.88	\$26.60	\$70.48	
570	\$24.25	2	\$48.50	\$29.41	\$77.91	
240	\$23.85	2	\$47.70	\$28.92	\$76.62	
297	\$30.34	2	\$60.68	\$36.79	\$97.47	
431	\$20,40	2	\$40.80	\$24.74	\$65.54	
416	\$19.31	2	\$38.62	\$23.42	\$62.04	
655	\$16.18	2	\$32.36	\$19.62	\$51.98	
613	\$16.68	2	\$33.36	\$20.23	\$53.59	
436	\$19.42	2	\$38.84	\$23.55	\$62.39	
614	\$16.83	3	\$50.49	\$30.61	\$81.10	
661	\$14.35	3	\$43.05	\$26.10	\$69.15	
633	\$18.31	3	\$54.93	\$33.30	\$88.23	
267	\$27.42	3	\$82.26	\$49.87	\$132.13	
628	\$21.87	3	, \$65.61	\$39.78	\$105.39	
545	\$29.20	3	\$87.60	\$53.11	\$140.71	
320	\$33.11	2	\$66.22	\$40.15	\$106.37	
440	\$23.20	2	\$46.40	\$28.13	\$74.53	
523	\$23.98	3	\$71.94	\$43.62	\$115.56	
654	\$21.17	3	\$63.51	\$38.51		
242	\$32.16	_			\$102.02	
584	\$26.06		\$128.64	\$77.99	\$206.63	
600		3	\$78.18	\$47.40	\$125.58	
	\$23.18	4	\$92.72	\$56.22	\$148.94	
598	\$24 30	4	\$97.20	\$58.93	\$156.13	
623	\$21.82	3	\$65.46	\$39.69	\$105.15	
625	\$25.33	3	\$75.99	\$46.07	\$122.06	
627	\$24 .28	3	\$72.84	\$44.16	\$117.00	
624	\$20.06	3	\$60.18	\$36.49	\$96.67	
601	\$21.82	3	\$65.46	\$39.69	\$105.15	
364	\$27.06	3	\$81.18	\$49.22	\$130.40	
296	\$19.72	3	\$59.16	\$35.87	\$95.03	
659	\$12.45	2	\$24.90	\$15.10	\$40.00	
660	\$12.45	2	\$24.90	\$15.10	\$40.00	
433	\$26.38	2	\$52.76	\$31.99	\$84.75	
				-	-	

.

.

635	\$21.67	2	\$43.34	\$26.28	\$69.62
634	\$21.82	2	\$43.64	\$26.46	\$70.10
478	\$24.83	2	\$49.66	\$30.11	\$79.77
524	\$23,51	2	\$47.02	\$28.51	\$75.53
192	\$27.60	2	\$55.20	\$33.47	\$88.67
150	\$36.16	2	\$72.32	\$43.85	\$116.17
560	\$29,60	3	\$88.80	\$53.84	\$142.64
329	\$30.12	2	\$60.24	\$36.52	\$96.76
519	\$21.72	2	\$43.44	\$26.34	\$69.78
458	\$19.42	2	\$38.84	\$23.55	\$62.39
209	\$29.41	2	\$58.82	\$35.66	\$94.48
301	\$30.04	2	\$60.08	\$36.43	\$96.51
461	\$2 4.97	2	\$49.94	\$30.28	\$80.22
508	\$24.30	3	\$72.90	\$44.20	\$117.10
656	\$18.52	3	\$55.56	\$33.69	\$89.25
599	\$24.93	3	\$74.79	\$45.35	\$120.14
629	\$21.77	4	\$87.08	\$52.80	\$139.88
626	\$21.77	4	\$87.08	\$52.80	\$139.88
597	\$27.11	4	\$108.44	\$65.75	\$174.19
324	\$29.84	2	\$59.68	\$36.18	\$95.86
592	\$21.82	3	\$65.46	\$39.69	\$105.15
451	\$26.02	2	\$52.04	\$31.55	\$83.59
569	\$21.82	2	\$43.64	\$26.46	\$70.10
457	\$19.69	2	\$39.38	\$23.88	\$63.26
298	\$23.26	3	\$69.78	\$42.31	\$112.09
381	\$17.78	2	\$35.56	\$21.56	\$57.12
397	\$21.50	2	\$43.00	\$26.07	\$69.07
374	\$19.42	2	\$38.84	\$23.55	\$62.39
630	\$18.31	3	\$54.93	\$33.30	\$88.23
437	\$21.02	4	\$84.08	\$50.98	\$135.06
394	\$39.77	2	\$79.54	\$48.23	\$127.77
662	\$12.45	2	\$24.90	\$15.10	\$40.00
110	\$23.30	2	\$46.60	\$28.25	\$74.85
631	\$17.64	2	\$35.28	\$21.39	\$56.67
380	\$20.55	2	\$41.10	\$24.92	\$66.02
360	\$23.23	2	\$46.46	\$28.17	\$74.63
480	\$31.94	2	\$63.88	\$38.73	\$102.61

.

.

Total Vine Control Safety Meeting Cost

\$13,256.81

20 X

Right of Way Department has spent many hours cutting vines from poles. Vines are cut on a regular basis with several vines cut each week by each right-of-way employee; however we can only document three days in which vines were specifically addressed.

\$6,218.31

Employee Number	Wage	Hours Worked	Labor Cost	Fringe Benefit 60.63%	Labor & Fringe Cost
337 464 506 616 460 342	\$32.65 \$20.73 \$22.89 \$17.03 \$23.08 \$23.39	24 24 24 24	\$783.60 \$497.52 \$549.36 \$408.72 \$553.92 \$561.36	\$475.10 \$301.65 \$333.08 \$247.81 \$335.84	\$1,258.70 \$799.17 \$882.44 \$656.53 \$889.76
472	\$21.53		\$516.72	\$340.35 \$313.29	\$901.71 \$830.01

Total verifiable labor spent on vine removal



Equipment purchased for Vine Removal

	Equipment				S	nipping	Total
Date	Description		Cost	Quantity		& Tax	Cost
	2 Vine Pruner	\$	1 8.65	2	\$	1.83	\$ 32.35
	2 De-Viner	\$	55.00	3	\$	13.13	\$ 178.13
8/27/2012	2 Sprayer for Vines	\$	28.5 9	2	\$	2.63	\$ 46.53
10/18/2012	Vine Pruner	\$	18.65	3	\$	3.05	\$ 53.90
5/14/2013	Vine Pruner and	\$	18.95	3			\$ 56.8 5
	Sprayer for Vines	\$	21.95	2	\$	6.05	\$ 49.95
Total Equipment Costs							\$ 417.71

In addition there has been an outlay for herbicide; however we cannot itemize this due to the herbicide being used on vines, trees and other foilage.



K & T SAW SHUP & EQUIPMENT FAX # 606-361-0209 1199 NORTH HWY 1247 SUMERGEF, KY 42503 (606) 678-9623

BILL TD: 678-4121 SOUTH KY RECC P 0 BOX 910 SOMERSET, KY 42501 (606) 872-3496 Alt: (606) 872-3304 Date.....: 08-03-12 14:19:03 Invoice #...: 502214, Page 1 Gustomer #..: 678-4121 Salesperson.: DB P.O. #.....

SHIP 10: South Ky Recc P 0 Bux 910 Somerset, Ky 42501

- INVUICE -

		TERMS: 30	Days			fr		3ta	tement	Date				
MFR	I FART/MODEL #	I IDESCRIPTION		IQI ISL			0TY 8/0		PRICE	 	NET	1	TOTAL	ITISI IXIDI
SLILE	PP10	PRUNER			2		6		18.6	3	15.2	6	30.52	3

	SUBTOTAL TAX	30, 52 1, 83
	INVOICE FUTAL	32.35
	AMOUNT PAID	0.00
RECEIVED BY: 33301508 - MSEDOL - 1803 - 5	BALANCE DUE	32. 35
111 A R R R R R R R R R R R R R R R R R		

ELEIVED BY: 33301208 - MELDOI - 1803 - 593.50

SO. KY. R E C C RECEIVED <u>PM</u> DATE <u>8-3-12</u> PRICES & TOTALS CKD. APPROVED <u>Paul Merucl</u>



	INVOICI voice Numbe Dennis Ho Invoice Date 8/17/201 Page
Please Remit To: Inv Mail To: 640 Belle Shoals Road Pickens, SC 29671 or Wire To:	voice Numbe Dennis Ho Invoice Date 8/17/201
Please Remit To: Im Mail To: 640 Belle Shoals Road Pickens, SC 29671 or Wire To:	voice Numbe Dennis Ho Invoice Date 8/17/201
Mail To: 640 Belle Shoals Road Pickens, SC 29671 or Wire To:	Dennis Ho Invoice Date 8/17/201
Wachovla Routing # 053207766, Acct # 2000054783986	Invoice Date 8/17/201
Bill To: Ship To:	
South Kentucky Rural Co	00
925 n. Main St	-
Somerset, Ky 42502	
paid 8/17/2012 : cc run by wmorris	
Customer ID / # Customer PO / # Ship Date Poymer	nt Terms*
N	et 30
Quantity Catalog # Description Unit Price Exte	ension
3 DV-1 Deviner \$55.00 \$1	65.00
	0.00
	D. OO
1 TSD-1 Penta Socket Driver nc \$6	0.00
Subtotal \$10	55.00
3 - DEVINERS Sales Tax st	3.13
	0.00
	78.13
O.K. Please Remit To: Paid 8/17	/2012 by cc
Mail To: 640 Ballin Shoats Road	
Pictures, SC 29871	
0r Olirect Wire To: Wechovie Rowting # 053207765 Acct # 200054783986	
yment. The prices set forth on the face of the invoice shall be paid by Customer within thirty (30) days of the date of the invoice. All payments shall be ble without offest, discount (unless explicitly provided for in the Contract), or any reduction in the Contract price. Seller shall have the right to charge percent (1.5%) intentst per month (or, if less, the matchmum lawful rate allowed by law) on invoices that are not paid within thirty (30) days of the invo tion to its right to charge interest for outstanding invoices, Seller shall be entitled to ell rights and remedies provided by the Uniform Commercial Code was of South Carolina.	one and one-
For Invoice / Payment Questions Contact Venice @ 704-491-0056 or vd@madillc.c	om

Involce (2)

.

8/17/2012

1.4

K & T SAW SHOP & EQUIPMENT FAX # 606-561-0209 1199 NORTH HWY 1247 SOMERSET, KY 42503 (606) 678-9623

Date..... 08-27-12 11:47:44 Invoice #...: 504736, Page 1 Customer #... 678-4121 Salesperson.: CK P.O. #.......

BILL (0: 678-4121 SHIP TU: BOUTH KY RECC SOUTH KY RECC P U BUX 910 P 0 80X 910 SOMERSET, KY 42501 SOMERSET, KY 42501 (606) 872-3496 Alt: (606) 872-3504

i Mer i pai	RT/MODEL #	I IDESCRIPTION	1	QTY SLD		QTY I B/C I	PRICE I	i NET i	ITTE TOTAL IXIO
STI 5610)	MANUAL HAND	ield spra		2	8	28. 59	21.95	43.90 1
	*******	**********	e see our	WEB :	SIT	E "WWW.	K FOUTDUOR. CU	***** ***	****
	₩₩₩₩₩₩	***************************************	MTHS NU \$	WIT	H P	AYMENTS	/ DEFERRED ?	······································	****

AMOUNT PAID BALANCE DUE

RECEIVED BY: 33301508 - MEED 01 - 1803 - 593.50

SO. KY. R E C C NECEIVED PM DATE 7-27-12 PRICES & TOTALS, CID. . APPROVED Jane Momele



0.00

46, 53

K & T SAW SHOP & EQUIPMENT Dave..... 10-11-12 10:42:59 FAX # 606-561-0203 Involue #...: 506208, Page 1 1199 NORTH HWY 1247 Eustomer #...: 678-4121 JUNLINGET, INY 42503 Laresper sour = DK 150L1 078 0623 BILL IU: 678-4121 SOUTH KY RECC. SOUTH LA REDO F 0-B0X 910 P J DJX .10 SOMERSET, KY 42501 SUGARSET. KY 42501

INVULCE -	
THADTOC	

		IERMS. JØ	Days P	vet, f	om Stat	ewant Lut	e	
	1							ىۋات
MFK I PF	RT/NODEL # 1D	ESCRIPITON	1	SLD T	B/O I	RAICE I	NET	TOTAL IXIDE
				2,002				and maile and a
STI PP1	2 1 PI	RUNER		3	. Ø	18,65	:6.95	50.85 1

		 	 	A AND AND AND AND AND AND AND AND AND AN
			were this min	50.85
			TFIX	3. (5
			INVUICE (UTAL	53)
				조지로 자보는 것은 것은
			ANUL FAID	4. 16
RECEIVED BY:	3330 (508		DALANLE DUE	53.00

M2=0 01 - 1803 - 593.50

(606) 872-3496 Alt. (506) 272-2304

SO. NY. R E C C RECEIVED PM DATE 10-18-12 PRICES & TOTALS CKD. MPROVED FRUE MEM d -



K & T SAW SHOP & EQUIPMENT Date....: 05-09-13 09:02:36 FAX # 606-561-0209 Invoice #...: 520514, Page 1 Customer #..: 678-4121 1199 NORTH HWY 1247 SOMERSET, KY 42503 Salesperson. : CK (606) 678-9623 P.D. #..... BILL TO: 678-4121 SHIP TO: SOUTH KY RECC SOUTH KY RECC P 0 BOX 910 P 0 BOX 910 SOMERSET, KY 42501 SOMERSET, KY 42501 (606) 872-3496 Alt: (606) 872-3504

- INVOICE men yB TERMS: 30 Days Net, from Statement Date -----1 ł I QTY (QTY) 1 1 ITISL MFR | PART/MODEL # IDESCRIPTION ISLD | B/D | PRICE | NET I TOTAL IXIOI ____ STI PP10 STI SG10 PRUNER 3 8 29.85 18, 95 56.85 T Manual Handheld Spra 2 0 24.15 21.95 43.90 T

SUBTOTAL	100.75
TAX	6.05
INVOICE TOTAL	106.80
AMDUNT PAID	0.00
BALANCE DUE	106.80

RECEIVED BY:

PAST BALANCE OVER 30 DAYS.

23301508 02.592 · 5031 · 50 0320

SR. KY. R E C C RECEIVED DATE 5-14-13 PRICES & TOTALS CKD. -APPROVED Save Manuel



Proposed vine removal and treatment costs for the remainder of 2013 and for 2014

Description	Hou Contracto	*Hours Per Year	Total Cost			
Foreman	\$	21.40	1,936	\$	41,430.40	
Groundman	\$	17.65	1,936	\$	34,170.40	
4x4 Spray Truck	\$7.		1,936	\$	14,520.00	
Description	Costs		Gallons Per Year			
Herbicide per gallon (mixed)	\$	0.80	40,000	\$	32,000.00	
	Total Vehi	\$ 122,120.80				

South Kentucky Employee Costs

Employee			_		Fringe Benefit		Total Cost		
Vine Crew CoordInator Transportation Cost #283	\$ \$	26.79 6.03			49,722.24 11,191.68		27,844.45 6,267.34		77,566.69 17,459.02
				Total Employee Cost				\$	95,025.72
Total Cost of the contract of the	1 -								

 Total Cost of Vine Spray and Removal Crew and Coordinator on an Annual Basis =
 \$ 217,146.52

*Contractors do not work during 8 scheduled South Kentucky Holidays and also have two weeks vacation per year **South Kentucky Employee gets 10 days holiday per year and 20 days vacation per year



Total Quantifiable Expenditures for Vine Control

Description	Attachment #		Total		
July 31, 2012 Outside Employee Meeting	1	\$	2,646.00		
August 16, 2012 Safety Meeting	2	\$	13,256.81		
Right-ofWay Labor	3	\$	6,218.00		
Equipment Purchases	4	\$	417.00		
Quantifiable Costs of Vine Control to Date		\$	22,537.81		
Future Estimated Expenditures					
*Vine Removal Crew, Herbicide and Coordinator	5	\$ 2	217,146.00		

*Estimate of Annual Cost

