CASE No. 2019-00258

To the Commission,

Per your order I am filing this status report.

Green River Valley restored water service 5/5/2021, however; on 5/7/2021 I submitted a service call to report an outage to Green River Valley. The service technician that arrived stated the new service line had busted and they would be fixing the problem as soon as possible because he thought he was done with our headache and had a new headache to take care of. Hearing we had become a headache to our water company was very upsetting considering we have been paying for the service for 5 years, begging for help, and being very patient. I reported to Green River Valley Water by phone that the water has an odd smell and is cloudy/milky when first ran out of the tap. The customer service representative stated due to the break in the service line that they would probably need to the bleed the line. The water pressure and volume have been sufficient since 5/7/2021

With regards to expenses incurred during the period of inadequate pressure and volume, I am including images of receipts and/or invoices. Please be aware that the lists of costs presented in this status report are not complete as it has been difficult to obtain all of the documentation going back to our initial complaint to Green River Valley District in 2016. For example, when the first pump failed there was a significant water leak which caused us to incur a bill of over \$200.00. Unfortunately, the Green River Valley Water District Member Portal will only allow me to view/retrieve thirteen months of billing which is after that particular event. Green River Valley Water District would be able to provide complete documentation from that time period. Furthermore, our lawn has considerable amount of damage from the installation of the 4.5ft hole for inline pump, the electrical ditch line dug to provide electric to pump and the newly dug pipe line running the entire front lawn (see included photos) and there has been no attempt to address the damage.

I ask that the Commission not dismiss the case at this time, but instead, consider the evidence regarding damage to the property as well as the cost evidence I have been able to gather thus far. Additionally, I ask that the commission permit me additional time to gather and submit additional cost evidence before the case is considered resolved.

Additional considerations:

I have also had to pay for the electricity for the in-line pressure pump that provided water to the house since fist pump installation in 2017. I am unsure of how to calculate that cost.

Purchase of IBC totes (for rain-catchment project) during the early days of the pandemic having no running water to with which to clean and disinfect. Purchased on April 7th 2020 from RJ's Farm Equipment And More, 5369 US 127 Liberty KY 42539. Phone 606.787.7661, After Hours -606.706.1735 76 Miles one-way. (Trying to locate proof of purchase.)

JUN 10 2021

RECEIVED

PUBLIC SERVICE COMMISSION During the time of the pandemic, we also considered having a well drilled and paid \$700 for a sitesurvey. Unfortunately, the \$10,000 estimate the drilling company presented us with was far more than we could afford. (Lewis Well Drilling Contact Telephone: 859.333.1200) 6521 Highway 519 West Liberty, Kentucky 41472. (Trying to locate receipt.)

Having a wood-heated home and not having reliable water has always been a concern for me. It was also a concern for my insurance company with regards to homeowners insurance.

Costs (incomplete list):

\$459.76 - 1st Replacement Pump

\$562.82 – 2nd Replacement pump

\$???- Plumbing supplies and tools from Ace, Home Depot and Lowes. (Need receipts)

\$114.96 – Sump Pump and Hose (-\$5 from receipt pictured for bag of pretzels also on the receipt)

\$700.00 – Water well-site survey (Need receipt)

\$200.00 – Used IBC Totes for rain catchment project (Need Receipt) 4 totes @ \$50.00 each.

1 - First replacement pump



View order details

Order date	Sep 21, 2019
Order #	114-4200222-
	5310602
Order total	\$459.76 (1 item)

Shipment details

Economy Shipping

Shipped

Sep 27, 2019 - Oct 2, 2019



Simer 3075SS- \$433.74 01 3/4 HP Pressure

Booster Pump

Qty: 1 Sold By: samis shop

Contact Seller



2 - Second replacement pump

12					INVOICE	
Branch: 2 PO Box 34 Louisville, US	1337 KY 40232	ply - Elizabethtown	MASTERS SUPPLY, INC		INVOICE 4764387 ate Page 07:03 I of 2 DER NUMBER 2263722	
502-459-29 Bill To: Elizabethtov 1839 S. Dixi Elizabethtow US Customer ID	vn D+ COD ie n, KY 42701		Ship To: Elizabethtown 1839 S. Dixie Elizabethtown			
	Number	Term Description	Net Due Date	Disc Due Date	Discount Amount	
Tammy	Conahan	COD	6/19/2020	6/19/2020	0.00	
Order Date	Pick Ticket No	Primary Sa	lesrep Name		Taker	
6/18/2020 14:59:08	3881889	CASH	SALES		KLP	
Qi Ordered Shipped	Remaining UOM Unit Size	Item ID Item Description	and the s	Pricing UOM Unit Size	Unit Extended Price Price	
Carrier:	Delivery Instructi EWC - E-Town Will Cal					
	1.0 Ordered Order Line Not	407588 SIMER 3/41 407588 NEW PART NUMBER - 4s: 407588 es: DATE CODE 22K 19L	407588	EA IP 1.0000	562.8182 562.82	
					17	
GINAL 14						

3- Sump pump and hose



3:33 🗖 🍪 ð ð Ø 👁 •	()	ⅆ 71%∎			
ORDER # 1011	151199616374				
	ft. L				
	Prinsco Plastic Disch Hose Kit 1-1/4 in. Dia ft. L				
	ltem no. 4752408	1			
	BUY AGAIN				
	Dot's Pretzels Homo Pretzels 1 lb. Baggeo				
	Dot's Pretzels Home Pretzels 1 lb. Bagged	style			
	Item no. 9388844	1			
	BUY AGAIN				
Subtotal (4 items)	Ş	\$119.96			
Promo		- \$0.00			
Тах		\$0.00			
Total	\$1	19.96			
ACE Rewards	You have earned 1,19	90			
Temardo	points with this order.				
<u> </u>	⊙ ≡Q	•••			
HOME REWARDS	MY STORE SHOPPING	MORE			

4 - IBC Totes













































