COMMONWEALTH OF KENTUCKY BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:		
KENTUCKY FRONTIER GAS, LLC)	
ALLEGED VIOLATION OF UNDERGROUND FACILITY DAMAGE PREVENTION ACT)	CASE NO. 2019-00317

NOTICE OF FILING

Notice is given to all parties that the Gas Excavation Damage Report for Incident 31325 has been filed into the record for this proceeding.

Gwen R. Pinson Executive Director

Public Service Commission

P.O. Box 615

Frankfort, KY 40602

DATED OCT 3 1 2019

cc: Parties of Record

Gas Excavation Damage Report

Kentucky Frontier Gas, LLC

Submitted 2/12/2019 Incident ID: 31325

Set back to Edit	Staff Edit	Print
Reported By:		··\.

Name:

Heather Music

Phone:

606-886-2431 ext 100

Email:

hmusic@kyfrontiergas.com

Gas Line Incident Occured:

Date: 1/7/2019

Time: 6:00 PM

Details:

Reported Date: 2/12/2019 11:02 AM

Incident Location Address:

Location:

37.44514 -82.80802

Address: 2nd Street

City: Wayland

State: KY

County: Floyd

Zip: 41666

Confirm Code:

Address	City	State	
ZipCode	County	State	

Locate Request Ticket No.: NA

Excavator: Contractor

Organization ID	Company	Status	Company Type
Excavator Address: First Name: Elvis			
Last Name: Keathley			
Organization ID:			
Company: Jigsaw Construction			
Phone: 606-791-4118			
Email:			
Address: 190 Left Fork of Island Crk			
City: Pikeville			
State: KY			
Zip: 41501			
Confirm Code:			
Address	City		State

Excavation Damage: No notification made to the One Call Center

Description of Incident 1" service line broken by an excavator, city utility personnel on site shut down a valve which caused loss of 14 customers.

State

County

Summary Information 2/12/2019

ZipCode

Full details such as the line which resulted in a hole in the line. KFG field technicians caught a 1" service line which resulted in a hole in the line. KFG field technicians cut out the damaged section and replaced it with 2 feet of pretested pipe by

electrofusion. Once the line was pressured back up, technicians went to each affected customer and restored service.

Minimal, line was not broken through and very little gas lost due to valve being shut off immediately

Cost of the damage

Extent of the damage

re-occurance Amount billed to excavator

\$200.00

Steps taken to prevent KFG technicians spoke with the construction supervisor about the 811 laws

\$0.00

CT Corporation System Register Agent 306 W Main Street, Suite 512 Frankfort, KENTUCKY 40601

*Honorable John N Hughes Attorney at Law 124 West Todd Street Frankfort, KENTUCKY 40601

*Kentucky Frontier Gas, LLC 4891 Independence Street, Suite 200 Wheat Ridge, CO 80033

*Kentucky Frontier Gas, LLC Kentucky Frontier Gas, LLC 4891 Independence Street, Suite 200 Wheat Ridge, CO 80033