

COMMONWEALTH OF KENTUCKY  
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY FRONTIER GAS, LLC )  
)  
\_\_\_\_\_ )  
)

ALLEGED VIOLATION OF UNDERGROUND )  
FACILITY DAMAGE PREVENTION ACT )

CASE NO.  
2019-00320

NOTICE OF FILING

Notice is given to all parties that the Gas Excavation Damage Report for Incident 31384 has been filed into the record for this proceeding.



Gwen R. Pinson  
Executive Director  
Public Service Commission  
P.O. Box 615  
Frankfort, KY 40602

DATED OCT 31 2019

cc: Parties of Record

# Gas Excavation Damage Report

## Kentucky Frontier Gas, LLC

Submitted 3/14/2019 Incident ID: 31384

[Set back to Edit](#)

[Staff Edit](#)

[Print](#)

Reported By:

Name:

Heather Music

Phone:

606-886-2431 ext 100

Email:

hmusic@kyfrontiergas.com

Gas Line Incident Occured:

Date:

2/14/2019

Time:

6:00 PM

Details:

Reported Date: 3/14/2019 2:12 PM

Incident Location Address:

Location:

37.64483 -82.27058

Address:

31 Sycamore Addition Ct

City:

Forest Hills

State:

KY

County:

Pike

Zip:

41527

Confirm Code:

<b>Address</b>	<b>City</b>	<b>State</b>	
<b>ZipCode</b>	<b>County</b>	<b>State</b>	

Number of Customers out: 2

Locate Request Ticket No.: NA

**Excavator:** Utility

Organization ID	Company	Status	Company Type
-----------------	---------	--------	--------------

Excavator Address:

First Name:

Doug

Last Name:

Scalf

Organization ID:

Company:

Mountain Water District

Phone:

606-358-8190

Email:

Address:

6336 Zebulon Hwy

City:

Pikeville

State:

KY

Zip:

41567

Confirm Code:

Address	City	State
ZipCode	County	State

Excavation Damage: No notification made to the One Call Center

**Description of Incident** While installing a sewer and water line, the utility crew broke a 2" PE main line.

Summary Information 3/14/2019

<b>Full details such as the cause</b>	The utility did not call 811, therefore KFG was unaware that they were digging in the area. A 2" main line was broken and then consequently squeezed off by the utility crew, at this time they kept digging and also broke a tap tee on the same line before a technician could make it to the dig site. Repairs were made to the 2" main with pretested pipe and also to the 1" line coming off of the tap which was then pressure tested. Gas service to customers was already off and not restored at the time of incident.
<b>Extent of the damage</b>	Minimal, no significant gas loss, cost based on parts and equipment/crew time to repair.
<b>Cost of the damage</b>	\$400.00
<b>Steps taken to prevent re-occurrence</b>	Mountain Water District's onsite crews and also in-office supervisor have previously been advised about calling 811 and the dig laws. The onsite crew at this incident were also advised of the appropriate actions to be taken when a gas line is broken as far as continuing to run equipment before the gas company has arrived.
<b>Amount billed to excavator</b>	\$0.00

CT Corporation System Register Agent  
306 W Main Street, Suite 512  
Frankfort, KENTUCKY 40601

\*Honorable John N Hughes  
Attorney at Law  
124 West Todd Street  
Frankfort, KENTUCKY 40601

\*Kentucky Frontier Gas, LLC  
4891 Independence Street, Suite 200  
Wheat Ridge, CO 80033

\*Kentucky Frontier Gas, LLC  
Kentucky Frontier Gas, LLC  
4891 Independence Street, Suite 200  
Wheat Ridge, CO 80033