Archived: Thursday, May 31, 2012 4:00:27 PM

From: Mike Galbraith

Sent: Tuesday, June 14, 2011 10:37:14 AM

To: 'jkaput@airtechenv.com'

Cc: Tom Shaw

**Subject:** RE: HAPS testing **Response requested:** No

**Importance:** Normal

\_\_\_\_\_

From: Mike Galbraith

Sent: Tuesday, June 14, 2011 10:33 AM

**To:** 'jchrist@airtechenv.com' **Subject:** HAPS testing

Jim,

Here we go!

Please provide a proposal for each Station for the following HAPS testing:

(Inlet an outlet testing performed simultaneously for each parameter)

#### Wilson Station

SCR outlet speciated Hg, RM30b

ESP outlet speciated Hg, RM30b

Stack speciated Hg, RM30b

ESP outlet HCI, RM26

Stack HCI, RM26A

ESP outlet PM, RM5b and RM202

Stack PM, RM5b and RM202

#### **Coleman Station**

Coleman Unit One ESP outlet speciated Hg, RM30b

Coleman Unit Two ESP outlet speciated Hg, RM30b

Coleman Unit Three ESP outlet speciated Hg, RM30b

Common Stack speciated Hg, RM30b

Coleman Unit One ESP outlet HCI, RM26

Coleman Unit Two ESP outlet HCI, RM26

Coleman Unit Three ESP outlet HCI, RM26

Common Stack HCI, RM26A

Coleman Unit One ESP outlet PM, RM5b and RM202

Coleman Unit Two ESP outlet PM, RM5b and RM202

Coleman Unit Three ESP outlet PM, RM5b and RM202

Common Stack PM, RM5b and RM202

## **Green Station**

Please price each unit separately

Green One ESP outlet speciated Hg, RM30b

Green One Stack speciated Hg, RM30b

Green One ESP outlet HCI, RM26

Green One Stack HCI, RM26A

Green One ESP outlet PM, RM5b and RM202

Green One Stack PM, RM5b and RM202

Green Two ESP outlet speciated Hg, RM30b

Green Two Stack speciated Hg, RM30b

Green Two ESP outlet HCI, RM26

Green Two Stack HCl, RM26A

Green Two ESP outlet PM, RM5b and RM202

Green Two Stack PM, RM5b and RM202

## **Henderson Station**

Please price each unit separately

Henderson One SCR outlet speciated Hg, RM30b

Henderson One ESP outlet speciated Hg, RM30b

Henderson One Stack speciated Hg, RM30b

Henderson One ESP outlet HCI, RM26

Henderson One Stack HCI, RM26A

Henderson One ESP outlet PM, RM5b and RM202

Henderson One Stack PM, RM5b and RM202

Henderson Two SCR outlet speciated Hg, RM30b
Henderson Two ESP outlet speciated Hg, RM30b
Henderson Two Stack speciated Hg, RM30b
Henderson Two ESP outlet HCI, RM26
Henderson Two Stack HCI, RM26A
Henderson Two ESP outlet PM, RM5b and RM202
Henderson Two Stack PM, RM5b and RM202
Reid Station
ESP outlet speciated Hg, RM30b
Stack speciated Hg, RM30b
ESP outlet HCI, RM26
Stack HCI, RM26
ESP outlet PM, RM5b and RM202
Stack PM, RM5b and RM202
Please let me know if testing can start sooner than our prescheduled blocked dates in July.
Thanks,

# Michael Galbraith

Senior Scientist

Big Rivers Electric Corporation

201 Third Street

Henderson, KY 42419-0024

(270) 844-6030 (Office)

(270) 993-1588 (Cell)

(270) 844-6023 (Fax)