

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY FRONTIER GAS, LLC

ALLEGED VIOLATION OF UNDERGROUND
FACILITY DAMAGE PREVENTION ACT

)
)
)
)
)
)

CASE NO.
2019-00319

NOTICE OF FILING

Notice is given to all parties that the Gas Excavation Damage Report for Incident 31348 has been filed into the record for this proceeding.



Gwen R. Pinson
Executive Director
Public Service Commission
P.O. Box 615
Frankfort, KY 40602

DATED OCT 31 2019

cc: Parties of Record

Gas Excavation Damage Report

Kentucky Frontier Gas, LLC

Submitted 3/1/2019 Incident ID: 31348

[Set back to Edit](#)

[Staff Edit](#)

[Print](#)

Reported By:

Name:

Heather Music

Phone:

606-886-2431 ext 100

Email:

hmusic@kyfrontiergas.com

Gas Line Incident Occured:

Date:

2/4/2019

Time:

4:30 PM

Details:

Reported Date: 3/1/2019 11:55 AM

Incident Location Address:

Location:

37.44526 -82.80734

Address:

1st River St

City:

Wayland

State:

KY

County:

Floyd

Zip:

41666

Confirm Code:

Address	City	State	
ZipCode	County	State	

Number of Customers out: 14

Locate Request Ticket No.: 1811301042

Excavator: Contractor

Organization ID	Company	Status	Company Type
-----------------	---------	--------	--------------

Excavator Address:

First Name:

Nick

Last Name:

Burchett

Organization ID:

0400609

Company:

JIGSAW ENTERPRISES, LLC

Phone:

(606) 437-7638

Email:

Address:

190 Left Fork of Island Crk

City:

Pikeville

State:

KY

Zip:

41501

Confirm Code:

Y

Address	City	State
ZipCode	County	State

Excavation Damage: Other

Description of Incident Encased 2" main gas line broken during installation of sewer lines

Summary Information 3/1/2019

Full details such as the cause

Jigsaw Enterprises has been working on an ongoing sewer line installation in a area that has KFG main lines, our companies have been working together on this project. Using the maps inherited from the previous owners of this area of gas lines, the KFG supervisor has had someone stay at the jobsite for the most part and discussed with the contractor the general area of the lines. On this instance, the construction crew for Jigsaw found a steel line in the ground and did not realize it was an active gas line and sawed into it, which resulted in damage to the encased poly line. KFG construction crew replaced a 2ft section of pipe to repair and then restored service to all affected customers.

**Extent of the damage
Cost of the damage**

Minimal, only required 2' of PE to repair.
\$200.00

Steps taken to prevent re-occurrence

Jigsaw Enterprises has been very communicative with the KFG supervisor and we have been working together on this project. I did discuss the updated dig laws with Mr. Burchett as the only 811 we received was out of date.

Amount billed to excavator

\$0.00

CT Corporation System Register Agent
306 W Main Street, Suite 512
Frankfort, KENTUCKY 40601

*Honorable John N Hughes
Attorney at Law
124 West Todd Street
Frankfort, KENTUCKY 40601

*Kentucky Frontier Gas, LLC
4891 Independence Street, Suite 200
Wheat Ridge, CO 80033

*Kentucky Frontier Gas, LLC
Kentucky Frontier Gas, LLC
4891 Independence Street, Suite 200
Wheat Ridge, CO 80033