SHEEHAN, BARNETT, DEAN, PENNINGTON, LITTLE & DEXTER, P.S.C.

d/b/a THE DANVILLE LAW GROUP ATTORNEYS AT LAW 111 SOUTH FOURTH STREET P.O. BOX 1517 DANVILLE, KENTUCKY 40423-1517

> Telephone (859) 236-2641 Fax Number (859) 236-0081

JAMES WILLIAM BARNETT

JAMES HADDEN DEAN

HENRY VINCENT PENNINGTON, III

RAMONA CASTELLVI LITTLE

STEPHEN ABELL DEXTER

OF COUNSEL
ELIZABETH NICKELS LENN

<u>RETIRED</u>

JAMES G. SHEEHAN, JR

January 6, 2012

RECEIVED

Mr. Jeff Derouen
Executive Director
Public Service Commission
211 Sower Boulevard
Frankfort, KY 40602

ALULIVLU

JAN - 9 2012

PUBLIC SERVICE COMMISSION

RE: Public Contact 2011-00280

Dear Mr. Derouen:

Pursuant to the order entered on November 7, 2011 and in keeping with compliance with that order, I am enclosing a copy of various documents.

I would ask that you review those documents and let me know if you believe, for any reason, those documents fail to meet the requirements of the order. The "content page" is structured to identify each exhibit and references which paragraph of the order it addresses. Pursuant to the order and my correspondence with Allyson Honaker, I am including the original and one copy. If you need additional copies please let me know.

I appreciate your review of this document and getting back with me at your earliest convenience regarding any questions or concerns.

Very truly yours.


HON. V. HADDEN DEAN

JHD/ebs Enclosure(s)

Cc: L. Allyson Honaker

Jim Jacobus





RECEIVED

JAN - 9 2012

PUBLIC SERVICE COMMISSION

PSC Case No. 2011-00280

In The Matter Of Inter-County Energy Cooperative Corporation Alleged Failure to Comply With KRS 278.042

January 6, 2012

INTER-COUNTY ENERGY COOPERATIVE

P. O. Box 87 • Danville, KY 40423-0087

Case No. 2011-00280

CONTENT

EXHIBIT 1

Pursuant to the November 7, 2011 Order, page 4, paragraph 6, within 30 days of the Order, Inter-County shall provide a summary report to the Commission of the system-wide inspection performed as a result of this incident. The report shall contain all potential violations found including this type of violation, the curative action taken and the timeframe in which they were corrected.

Inter-County Energy Potential Clearance Findings and Corrections

Updated Response - January 6, 2012

EXHIBIT 2

Pursuant to the November 7, 2011 Order, page 4, paragraph 8, beginning with the December 2011 issue, Inter-County shall provide information in each issue of its monthly magazine distributed to all customers regarding safety. At least once per year, Inter-County will provide specific information in the magazine on clearance issues. Inter-County shall file a copy of each monthly magazine with the Commission beginning with the December 2011 issue.

Kentucky Living – January 2012 (Page 26L)



Inter County Energy - Clearance Findings and Corrections

1/6/2012

COMPLETION	5/27/2011	6/2/2011	6/13/2011	6/24/2011	6/24/2011	7/12/2011	7/21/2011	8/1/2011	9/28/2011	9/28/2011	9/28/2011	5/4/2011	9/19/2011	10/4/2011	9/27/2011	10/5/2011	5/2/2011	11/2/2011	11/8/2011	11/8/2011	11/3/2011	11/8/2011	11/9/2011	1/4/2012	1/5/2012	1/3/2012	11/10/2011	11/10/2011	11/30/2011	12/5/2011	12/12/2011	12/16/2011	1/3/2012	1/3/2012
COUNTY	Lincoln	Casey	Nelson	Lincoln	Garrard	Marion	Lincoln	Marion	Marion	Maríon	Marion	Lincoln	Marion	Laurue	Marion	Marion	Lincoln	Lincoln	Marion	Lincoln	Marion	Marion	Lincoln	Marion	Marion	Marion	Marion	Boyle	Casey	Casey	Garrard	Marion	Marion	Nelson
DESCRIPTION	Changed OH to UG primary	Install 50' Pole and shorten Primary Tap	Moved Phase to new cross arm	Rerouted 500' Primary away from Grain bins	Insall 55' Pole and shorten Primary Tap	Relocated 307' of primary	Relocated 118' of primary line	Replaced OH service with UG service	Install new pole and relocate primary	Relocate 312' of OH primary	Change out pole and move away from Grain bin	Change Pole and add pole in line	URD Primary to Padmount Xfmer for grain bins	add pole and reroute line away from grain bin	Change out pole and move away from Grain bin	Reroute primary line away from grain bins	Relocate primary close to grain bin	Add pole in line for rd Clearance	Move primary line away from grain bin	Move primary line away from grain bin	Change out poles for Clearance	Changed 1-35' &1-40' pole to 2-60' poles	Relocated 393' of primary	Reroute 3 phase from building for Clearance	Rerouted service	Rerouted service	Changed out 2 poles for clearance	Changed out two poles for Clearance	Changed out two poles for Clearance	Changed out 2 poles for clearance	Move primary line and change svc to urd	Retire 3 phase and relocate single phase	Change pole for Clearance on svc wire	Add pole in line and reroute svc for cleareance
Clearance issue	Neutral 8' over grain bin	Primary 10' from grain bin	Phase 2' inside clearance window	Neutral 3' over grain bin	Primary line 10' inside vertical window at 28' away	Primary line over fuel storage tanks	Line over swimming pool / Pool removed after line move	Overhead service to close/ changed to underground	Line at 15' of grain bin	Line at 8' of grain bin	Primary line close to grain bins	Primary 12' over barn	Removed OH prim Installed URD prim for clearance	Primary line close to grain bins	Primary line close to grain bins	Primary line close to grain bins	Clearance issue	Rd Clearance issue	Clearance issue at grain bin	Clearance issue at grain bin	Clearance issue over road	Clearance issue at grain bin	Clearance issue at grain bin	Clearance from wall on a recently built addition	Low Service	Low Service	Low Service	Clearance issue at junk yard	Clearance issue at grain bin	Clearance issue at grain bin	Clearance issue at grain bin	Clearance issue	Clearance issue	Clearance issue
Member Name	James Coffey	James Beeler	Lyndal Mattingly	Floyd Rowe	Old Railroad Bed Rd	William Peterson	Kay Hale	Thomas Martin Mattingly	Cloyd Brady	Bill & Susan Mattingly	Joseph Buckman	George Burdine	Peterson Grain Bin	Danny Gentry	Joseph Buckman	Katherine Peake	George Burdine	Timothy Miller	John Thompson	W C Brogle	Thompson Drive	Hourigan Lane	Norris Rd	Makers Mark	Norman Robbins	Marcus Clark	David Sandusky	Airport Rd	Dewey Coffey	Dewey Coffey	J W Brogle	Farris Rd	Marcus Clark	Terry Cecil
Staked Date	5/2/2011	5/24/2011	5/13/2011	5/23/2011	5/23/2011	5/13/2011	4/27/2011	7/7/2011	5/13/2011	6/22/2011	7/7/2011	4/19/2011	9/6/2011	9/29/2011	7/7/2011	9/30/2011	4/19/2011	10/25/2011	10/18/2011	10/25/2011	10/4/2011	10/18/2011	10/25/2011	10/26/2011	1/3/2012	1/3/2012	10/4/2011	11/7/2011	11/14/2011	11/14/2011	11/11/2011	12/14/2011	1/3/2012	12/13/2011 BG
#OM	110383	110505	110475	110499	110500	110476	110372	110657	110474	110611	110655	110349	110889	110968		XH age		T of	(1 1 ₁₁₁₀₃₇	111069	110986	111037	111069	* 111072	* 11130E	* 111307	110987	111113	** 111147	** 111149	** 111162	** 111268	** 111307	** 111259

Completed Projects Listed As "In Progress" on the 12/1/2011 Report

^{**} Additional Identified Clearance Findings and Completed Projects Since 12/1/2011 Report

CELEBRATING THE ENERGY
OF YOUR COMMUNITY

GOING DOWNTOWN

How local shops are offering the edge in fun and freshness

BE A MONEY EXPERT Investment tips for a Grazy economy in the Kentucky Living 2012 Financial Planning Guide

PERFECT PICTURES
Kentucky Living
photographers
spill their secrets

EXHIBIT 2

(Ref. Page 26L)



Protect yourself and your loved ones

Check for and eliminate electrical hazards in your home:

- Replace missing or broken wall plates.
- Check for loose-fitting plugs.
- Check for outlets overloaded with multiple adapters & plugs.
- Have an electrician check outlets or switch plates that are discolored or warm to the touch.
- Make sure light bulb wattage matches the fixture requirements.
- Replace electrical cords that have frays or broken casing.
- Make sure outlets have Ground Fault Circuit Interrupters (GFCIs) in the kitchen, bathroom, laundry and outside.

To learn more about electrical safety, please visit our web site at www.intercountyenergy.net.

