

representatives of a public or private corporation or a partnership or association or a governmental agency, be accompanied by a signed certification of the preparer or the person supervising the preparation of the response on behalf of the entity that the response is true and accurate to the best of that person's knowledge, information, and belief formed after a reasonable inquiry.

Ohio District shall make timely amendment to any prior response if Ohio District obtains information that indicates the response was incorrect or incomplete when made or, though correct or complete when made, is now incorrect or incomplete in any material respect.

For any request to which Ohio District fails or refuses to furnish all or part of the requested information, Ohio District shall provide a written explanation of the specific grounds for its failure to completely and precisely respond.

Careful attention shall be given to copied and scanned material to ensure that it is legible. When the requested information has been previously provided in this proceeding in the requested format, reference may be made to the specific location of that information in responding to this request. When applicable, the requested information shall be separately provided for total company operations and jurisdictional operations. When filing a paper containing personal information, Ohio District shall, in accordance with 807 KAR 5:001, Section 4(10), encrypt or redact the paper so that personal information cannot be read.

A copy of this request shall be served on the Complainant, John Riley Dowell, by U.S. certified mail, return receipt requested at 856 Buford Road, Utica, Kentucky 42376.

1. Explain why Ohio District had not installed a pressure regulator at 856 Buford Road, Utica, Kentucky 42376 (856 Buford Road) prior to the date in which the regulator was installed.

2. Confirm that Ohio District performs pressure surveys to identify service addresses that may need a regulator.

a. If confirmed, explain Ohio District's policy or process related to the performance of these surveys and provide a listing of service addresses where surveys have been performed, including the actions taken at each service address following the survey, since January 1, 2023. If available, also please provide Ohio District's written policy for this process.

b. If not confirmed, explain Ohio District's policy or process to address water pressurization that may exceed 150 psi.

3. Explain how the pressure information Ohio District submitted in response to Commission Staff's First Request for Information demonstrated that Ohio District had not exceeded 150 psi at 856 Buford Road.

4. State whether or not on any day from December 1, 2022, to the date of issuance of this request for information the water pressure at the service pipe at 856 Buford Road exceeded 150psi.

*John Dowell
856 Buford Road
Utica, KENTUCKY 42376

*Ohio County Water District
124 E Washington Street
P. O. Box 207
Hartford, KY 42347

*Eric Hickman
Ohio County Water District
124 E Washington Street
P. O. Box 207
Hartford, KY 42347