COMMONWEALTH OF KENTUCKY BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

ELECTRONIC APPLICATION OF)
MOUNTAIN WATER DISTRICT PURSUANT)
TO 807 KAR 5:071, SECTION 7(4) FOR) CASE NO. 2018-001478
APPROVAL OF PROPOSED INSPECTION)
PROCEDURES)

RESPONSE OF MOUNTAIN WATER DISTRICT TO COMMISSION STAFF'S FIRST REQUEST FOR INFORMATION DATED OCTOBER 19, 2018

FILED: NOVEMBER 26, 2018

VERIFICATION

COMMONWEALTH OF KENTUCKY)
) SS:
COUNTY OF PIKE)

The undersigned, Roy Sawyers, being duly sworn, deposes and states that he is the General Manager of Mountain Water District and that he has personal knowledge of the matters set forth in the responses for which he is identified as the witness, and the answers contained therein are true and correct to the best of his information, knowledge and belief.

Roy Sawyers

Subscribed and sworn to before me, a Notary Public in and before said County and State, this 26th day of November 2018.

Notary Public

My Commission Expires: 12 May 2021

Notary ID: 579303

VERIFICATION

COMMONWEALTH OF KENTUCKY)
) SS:
COUNTY OF PIKE)

The undersigned, Jamey Keathley, being duly sworn, deposes and states that he is the Wastewater Operations Manager of Mountain Water District and that he has personal knowledge of the matters set forth in the responses for which he is identified as the witness, and the answers contained therein are true and correct to the best of his information, knowledge and belief.

Subscribed and sworn to before me, a Notary Public in and before said County and State, this 26th day of November 2018.

Muld B Wulder Notary Public

My Commission Expires: 12 May 2021

Notary ID: 579303

MOUNTAIN WATER DISTRICT

Response to Commission Staff's First Request for Information October 19, 2018

Case No. 2018-00147

Question No. 1

Witness: Tammy Olson/Roy Sawyers/Jamey Keathley

- **Q-1.** Refer to page 3 of the application. Mountain District's application states that it primarily uses a pressurized system rather than a conventional gravity collection system to transport wastewater to its sewage treatment facilities. State what percentage of the system is pressurized and what percentage uses gravity collection
- **A-1.** See Application, Exhibit 2. Mountain Water District's ("Mountain District") sewage treatment and collection facilities serve 2,307 customers. 1,903 customers, or 82.5 percent of Mountain District's customers, are served through grinder/pump stations and pressurized systems. The remaining 403 customers (17.5 percent) are served through gravity collection systems.

Note that Mountain District operates several sewer septic systems and aerator sewage systems in the Big Creek area of Pike County, Kentucky under contract with the owners of those systems. Each system serves only one residence or structure. The Public Service Commission has previously held that these systems are not "utilities" and are not subject to Commission jurisdiction. *See Petition of Mountain Water District for a Disclaimer of Jurisdiction or Approval of Tariff*, Case No. 2009-00405 (Ky. PSC Apr. 12, 2010). These systems are not considered in this Response.

MOUNTAIN WATER DISTRICT

Response to Commission Staff's First Request for Information October 19, 2018

Case No. 2018-00147

Question No. 2

Witness: Tammy Olson/Roy Sawyers/Jamey Keathley

- **Q-2.** Describe the most common problem(s) at a grinding pump station when the grinding pump fails.
- A-2. Based upon a review of Mountain Water District ("Mountain District") work orders from 2010 to present, the most common problem was internal pump failure. Mountain District does not undertake any effort to break the grinder/pump's seal to inspect or troubleshoot the grinder/pump's internal components. Breaking the internal seal of a grinder/pump station will void the manufacturer's warranty. See Application, Exhibit 11. When an internal pump failure is found, Mountain District replaces the grinder/pump and returns the failing grinder/pump to the manufacturer's representative for repair. Other problems commonly found were: control board failure, electric quick disconnect engagement, and customer power supply issues.

For a listing of all service calls involving grinder/pump stations, see Attachment to this Response. An electronic copy of the Attachment in Excel format has been attached to the electronic version of Mountain District's Response to Commission Staff's Request.

WORK ORDER SUMMARY

YEAR	GRINDER SERVICE CALLS	EMERGENCY CALLS	CUSTOMER COMPLAINTS	GENERAL WORK ORDERS
2010	861	565	115	181
2011	819	647	81	91
2012	920	669	120	131
2013	696	610	66	20
2014	633	564	49	20
2015	711	635	57	19
2016	619	561	52	6
2017	554	504	42	8
2018	431	389	31	11
TOTAL	6244	5144	613	487

COMPLAINT SERVICE CALLS

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/19/2010	STATION BACKING UP	PROBLEM ON CUSTOMER'S SIDE	1.0	
01/28/2010	PUMP RUNS CONTINUOUSLY	STATION CHECKED OKAY	1.0	
02/05/2010	WATER STANDING IN STATION	CUSTOMER REFERRING TO PRESSURE CONNECT BOX. NO PROBLEM FOUND. CONNECT BOX FINE	2.0	
02/07/2010	BLOCKAGE	BLOCKAGE ON CUSTOMER'S SIDE	3.0	YES
02/11/2010	DISCONNECT SEWER	CUSTOMER SAID HE WOULD COME TO OFFICE AND PUT IN HIS NAME	1.0	
02/12/2010	STATION IN MIDDLE OF DRIVEWAY NOT WORKING	STATION CHECKED OKAY. NEEDS RISER INSTALLED.	1.0	
02/17/2010	NEED RISER	INSTALLED A 6" RISER	1.0	
	PUMP NOT WORKING	STATION CHECKED OKAY	0.5	
	PUMP NOT WORKING	STATION CHECKED OKAY	1.0	
	NEEDS RISER	INSTALLED 6" RISER	0.5	
	POWER ISSUE	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
		CONTACTED THE CONTRACTOR FOR REPAIR. STILL		
03/06/2010	PUMP NOT WORKING	UNDER PROJECT WARRANTY CUSTOMER SAID HE WOULD COME TO OFFICE AND	1.0	
03/10/2010	DISCONNECT SEWER	PUT IN HIS NAME	1.0	
	NEED RISER	INSTALLED 12" RISER	1.0	
	ODOR	STATION CHECKED OKAY	1.0	
	PUMP NOT WORKING	STATION CHECKED OUT OKAY	3.0	YES
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
04/05/2010	VENT CAP	VENT CAP WAS PUSHED DOWN. RAISED IT BACK UP.	0.5	
04/06/2010	CUSTOMER READY FOR US TO CONNECT	MWD HAS COMPLETED THEIR SIDE. CUSTOMER NEEDS TO CONNECT THEIR 4" PIPE TO MWD LINE.	1.0	
04/06/2010	VENT CAP	REPLACED VENT CAP	0.5	
04/14/2010	MOVE CONTROL BOX	MOVED CONTROL BOX CLOSER TO STN	2.0	
04/16/2010	VENT CAP	REPLACED VENT CAP	0.5	
04/20/2010	CUSTOMER READY FOR US TO CONNECT	MWD HAS COMPLETED THEIR SIDE. CUSTOMER NEEDS TO CONNECT HER 4" PIPE TO MWD LINE.	0.5	
04/21/2010	PUMP RUNS CONTINUOUSLY	CHECKED OUT OKAY ON MWD SIDE. CUSTOMER HAS BLOCKED LINE ON THEIR SIDE.	2.0	YES
04/21/2010	COMMODES WONT FLUSH	CUSTOMER HAS BLOCKED LINE ON THEIR SIDE	2.0	
04/23/2010	PUMP RUNS CONTINUOUSLY	CHECKED OUT OKAY ON MWD SIDE.	0.5	
04/23/2010	ODOR	STATION CHECKED OKAY	1.0	
04/29/2010	GRINDER SINKING	PUT DIRT AROUND THE STATION TO FILL IN	1.0	
04/30/2010	IMPROPER INSTALL COMPLAINT	STATION CHECKED OKAY. HELPED CUSTOMER CONTACT PLUMBER TO FIX THEIR SIDE.	1.0	
04/30/2010	ODOR	STATION NOW WORKING PROPERLY. SPREAD LIM	1.0	
	REPLACE LID	INSTALLED LID ON DISCONNECT BOX	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
05/06/2010	CONNECTION CHECK	CUSTOMER IS PROPERLY CONNECTED TO STATION	0.5	
05/06/2010	MOVE CONTROL BOX	MOVED CONTROL BOX CLOSER TO STN	2.0	
05/06/2010	REPLACE LID	REPLACED LID ON STATION	0.5	
05/14/2010	CLOGGED LINE	CLOGGED ON CUSTOMER'S SIDE	3.0	
	VENT CAP	REPLACED VENT CAP	0.5	
05/20/2010	VENT CAP	REPLACED VENT CAP	0.5	
06/04/2010	RAIN WATER INFILTRATION	CONTRACTOR HAD INSTALLED A 4" THIN WALL PIPE AND RAIN WATER FOLLOWING PIPE INTO STATION.	1.0	
06/07/2010	ODOR	NEED TO INSTALL 4" THICK WALL PIPE. CHECKED OUT OKAY ON MWD SIDE	1.5	
06/11/2010	STATION BACKING UP	NO LEAK, BLDNG BURNED DOWN A LONG TIME AGO, STAGNATED WATER	1.0	
06/14/2010	COMMODES WONT FLUSH	CHECKED OUT OKAY ON MWD SIDE	1.0	
06/15/2010	NEEDS RISER & LID	INSTALLED A RISER AND LID	0.5	
06/18/2010	VERIFY IF DAMAGE TO STATION	CHECKED OUT OKAY ON MWD SIDE	1.0	
06/23/2010	ODOR	CHECKED OUT OKAY ON MWD SIDE	1.0	
06/23/2010	COMMODES WONT FLUSH	CUSTOMER HAS BLOCKED LINE ON THEIR SIDE	1.0	
06/24/2010	VERIFY DAMAGE TO CONTROL BOARD	BOX THAT WAS DAMAGED WAS CUSTOMER'S. MWD SIDE IS GOOD.	1.0	
06/25/2010	MOVE CONTROL BOX	MOVED CONTROL BOX	2.0	
	CHANGE 4" PIPE	CHANGED OUT A 4" PIPE	2.0	
	STATION MAKES LOUD NOISE	STATION CHECKED OKAY	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
07/07/2010	PUMP NOT WORKING	STATION CHECKED OKAY	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
07/13/2010	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
07/13/2010	VENT CAP	REPLACED VENT CAP	0.5	
07/15/2010	ODOR	STATION CHECKED OKAY	1.0	
		BATHROOM RUNNING WATER. PROBLEM ON		
07/20/2010	GRINDER RUNS EVERY 10 MINS	CUSTOMER'S SIDE CONSTANT WATER COMING FROM THE HOUSE.	1.5	
07/20/2010	GRINDER RUNS CONSTANTLY	PROBLEM ON CUSTOMER'S SIDE	1.0	
	NEED RISER INSTALLED	INSTALLED A 1' RISER	1.0	
08/02/2010	NEED RISER INSTALLED	INSTALLED RISER & REPLACED PUMP	1.5	
08/02/2010	STATION EMPTYING SLOWLY	STATION CHECKED OKAY	1.0	
08/05/2010	ODOR	STATION CHECKED OKAY	1.0	
08/05/2010	ODOR	STATION CHECKED OKAY	0.5	
08/09/2010	ODOR	STATION CHECKED OKAY	1.0	
08/10/2010	SEWER LEAK	REPAIRED SEWER LINE LEAK IN DITCH	2.5	
08/12/2010	MOVE CONTROL BOX	MOVED CONTROL BOX FROM HOUSE TO TRAILER	3.0	
08/17/2010	ODOR	STATION CHECKED OKAY	1.0	
08/23/2010	COST ESTIMATE TO MOVE GRINDER STN	COST ESTIMATE PERFORMED	0.5	
08/23/2010	ODOR	STATION CHECKED OKAY	0.5	
09/03/2010	MOVE CONTROL BOX	MOVED CONTROL BOX CLOSER TO STN	2.0	
	CLOGGED LINE	LINE BLOCKED ON CUSTOMER'S SIDE	1.0	
09/07/2010	CLOGGED LINE	LINE BLOCKED ON CUSTOMER'S SIDE	1.0	
09/07/2010	ODOR	RESET THE PUMP	1.0	
09/10/2010	ODOR	STATION CHECKED OKAY	1.5	
09/10/2010	ODOR	STATION CHECKED OKAY	1.0	
09/14/2010	VENT CAP	REPLACED VENT CAP	0.5	
09/20/2010	ODOR	STATION CHECKED OKAY	1.0	
09/21/2010	ODOR	STATION CHECKED OUT OKAY	1.0	
09/27/2010	VENT CAP	REPLACED VENT CAP	1.0	
09/28/2010	ODOR	STATION CHECKED OUT OKAY	1.0	
09/30/2010	ODOR	STATION CHECKED OUT OKAY.	1.0	
10/02/2010	CLOGGED LINE	UNCLOGGED 4" LINE WITH JETTER	6.0	YES
10/04/2010	ODOR	STATION CHECKED OUT OKAY	1.0	
10/05/2010	RISER & VENT CAP	INSTALLED 12" RISER AND VENT CAP	1.0	
10/05/2010	ODOR	STATION CHECKED OUT OKAY	1.0	
10/07/2010	DAMAGE ELECTRICAL POLE	REPLACED CONTROL BOX. LINE WAS BLOCKED ON CUSTOMER'S SIDE	1.5	
10/10/2010	BLOCKAGE	LINE BLOCKED ON CUSTOMER'S SIDE	3.0	YES
10/11/2010	ODOR	STATION CHECK OUT OKAY	1.0	11.5
10/11/2010	ODON	MWD EMPLOYEES TALKED WITH CUSTOMER ABOUT	1.0	
10/12/2010	RISER TOO BIG	NEEDING THE 6" RISER	1.0	
	CLOGGED LINE	CUTOUT AND REPLACED Y DUE TO BEING CLOGGED	2.0	YES
10/18/2010	ODOR	STATION CHECKED OUT OKAY.	1.0	
10/20/2010	NEED RISER & VENT CAP	INSTALLED 6" RISER AND VENT CAP	1.0	
10/20/2010	ODOR	STATION CHECKED OUT OKAY. CUSTOMER NEEDS VENT PIPE ON THEIR SIDE	0.5	
10/26/2010	ODOR	CHECKED OUT OKAY ON MWD SIDE	0.5	
10/26/2010	MOVE ELECTRICAL BOX	COST ESTIMATE TO MOVE ELECTRICAL BOX NEAR	0.5	
10/20/2010	NEED DICED 8 VENT CAD	GRINDER STN	1.0	
10/28/2010	NEED RISER & VENT CAP	INSTALLED 6" RISER AND VENT CAP	1.0	
10/29/2010	POSSIBLE LEAK	NO LEAK, WAS GROUND WATER COMING THROUGH DRAINAGE AT THE BACK OF BUILDING	1.0	
10/29/2010	MOVE ELECTRICAL BOX	REMOVED CONTROL BOX OFF OF OLD HOUSE AND MOVED TO A POST NEXT TO GRINDER	1.0	
11/02/2010	REPLACE RESET BUTTON	RESET BUTTON REPLACED	1.0	
11/12/2010	VENT CAP	REPLACED VENT CAP	1.0	
11/16/2010	VENT CAP	REPLACED VENT CAP	0.5	
11/17/2010	ODOR	STATION CHECKED OUT OKAY.	1.0	
11/19/2010	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
11/19/2010	VENT CAP	REPLACED VENT CAP	0.5	
11/19/2010	VENT CAP	REPLACED VENT CAP	0.5	
	NEW CUSTOMER - SEWER HAD NEVER BEEN	PUMP WAS DOWN, PLUGGED 4" PIPE & TURNED		
11/22/2010	TURNED OFF	BREAKERS OFF	0.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
		STATION CHECKED OUT OKAY. GREASE PROBLEM.	,	
12/01/2010	ODOR	ADVISED CUSTOMER TO USE MORE WATER AND USE	1.0	
		DAWN FOR GREASE ISSUES.		
12/07/2010	VENT CAP	REPLACED VENT CAP	0.5	
12/07/2010	VENT CAP	REPLACED VENT CAP	0.5	
12/07/2010	ODOR	STATION CHECKED OUT OKAY	1.0	
		MWD DUG DITCH TO REDIRECT OVERFLOW FROM		
12/08/2010	LIFT STN OVERFLOW ISSUE	CUSTOMER'S PROPERTY WHILE PROBLEM IS BEING	2.0	
		REPAIRED		
12/15/2010	ODOR	REPLACED VENT CAP	1.0	
12/15/2010	FLOW ISSUE	TOO MUCH WATER FLOW IN THE SYSTEM. MWD	1.0	
12/16/2010	IFLOW ISSUE	WORKING ON THE PROBLEM.	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/13/2011	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	1.0	
02/22/2011	RISER	INSTALLED 12" RISER	0.5	
,, -	COST ESTIMATE TO RELOCATE STATION	PERFORMED COST ESTIMATE	0.5	
05/05/2011	ODOR	SHOWED CUSTOMER GREASE ISSUE	0.5	
	VENT CAP	REPLACED VENT CAP REPLACED VENT CAP	1.0	
05/09/2011 05/13/2011	COST ESTIMATE TO RECONNECT STATION	PERFORMED COST ESTIMATE	1.0	
05/16/2011	VENT CAP	REPLACED VENT CAP	1.0	
05/24/2011	VENT CAP	REPLACED VENT CAP	1.0	
	SEWER LID	REPLACED BROKEN SEWER LID	1.0	
	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
06/20/2011	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
07/01/2011	VENT CAP	REPLACED VENT CAP	1.0	
07/07/2011	VENT CAP	REPLACED VENT CAP	0.5	
07/07/2011	VENT CAP	REPLACED VENT CAP	0.5	
07/07/2011	VENT CAP	REPLACED VENT CAP	0.5	
- , - , -	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
- , -, -	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	COST ESTIMATE TO RELOCATE STATION	PERFORMED COST ESTIMATE	1.0	
	RISER	INSTALLED RISER ON PRESSURE CONNECT BOX	1.0 0.5	
07/28/2011 07/28/2011	VENT CAP VENT CAP	REPLACED VENT CAP REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
08/19/2011	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
09/02/2011	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
09/02/2011	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
09/02/2011	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
,-,-	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	VENT CAP	REPLACED VENT CAP	1.0	
	SLIDE COVERED STATION	UNCOVERED STATION, PULLED PUMP	1.0 0.3	
	CLEAN OUT CAP CLEAN OUT CAP	REPLACED CLEAN OUT CAP REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
09/09/2011	CLEAN OUT CAP	REPLACED CLEAN OUT CAP	0.3	
09/09/2011	CUSTOMER REQUEST MWD VERIFY - GUTTERS REMOVED FROM DRAINING INTO STATION	VERIFIED GUTTERS REMOVED FROM DRAINING INTO STATION	0.5	
09/14/2011	VENT CAP	REPLACED VENT CAP	1.0	
09/14/2011	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	1.0	
09/14/2011	VENT CAP	REPLACED VENT CAP	1.0	
09/20/2011	CUSTOMER REQUEST MWD VERIFY - GUTTERS REMOVED FROM DRAINING INTO	VERIFIED GUTTERS REMOVED FROM DRAINING INTO STATION	0.5	
	STATION	STATION		

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
09/26/2011	VENT CAP	REPLACED VENT CAP	0.5	
09/26/2011	CUSTOMER REQUEST MWD VERIFY - GUTTERS REMOVED FROM DRAINING INTO	VERIFIED GUTTERS REMOVED FROM DRAINING INTO	1.0	
	STATION			
	COST ESTIMATE TO RELOCATE STATION	PERFORMED COST ESTIMATE	1.0	
10/04/2011	VENT CAP	REPLACED VENT CAP	0.5	
10/06/2011	VENT CAP	REPLACED VENT CAP	1.0	
10/06/2011	CUSTOMER REQUEST MWD VERIFY - GUTTERS REMOVED FROM DRAINING INTO STATION	VERIFIED GUTTERS REMOVED FROM DRAINING INTO STATION	1.0	
10/10/2011	COST ESTIMATE TO RELOCATE STATION	PERFORMED COST ESTIMATE	1.0	
10/11/2011	VENT CAP	REPLACED VENT CAP	1.0	
10/17/2011	VENT CAP	REPLACED VENT CAP	1.0	
10/17/2011	VENT CAP	REPLACED VENT CAP	1.0	
10/17/2011	VENT CAP	REPLACED VENT CAP	1.0	
10/26/2011	PRESSURE CONNECT BOX	RAISED PRESSURE CONNECT BOX	1.0	
11/08/2011	VENT CAP	REPLACED VENT CAP	1.0	
11/14/2011	COST ESTIMATE TO REPAIR DAMAGES	PERFORMED COST ESTIMATE	4.0	YES
11/15/2011	VENT CAP	REPLACED VENT CAP	1.0	
11/29/2011	VENT CAP	REPLACED VENT CAP	0.5	
12/01/2011	VENT CAP	REPLACED VENT CAP	1.0	
12/06/2011	RISER	INSTALLED 12" RISER	1.0	
12/30/2011	SPREAD LIME	SPREAD LIME FROM OVERFLOW	0.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
01/05/2012	RISER	INSTALLED 12" RISER	(HOURS) 1.0	HOURS
	MOVE BOX	MOVED BOX CLOSER TO STATION	2.0	
	VENT CAP	INSTALL VENT CAP	1.0	
	VENT CAP	INSTALL VENT CAP	1.0	
	VENT CAP	INSTALL VENT CAP	1.0	
	VENT CAP	INSTALL VENT CAP	1.0	
	VENT CAP	INSTALL VENT CAP	1.0	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	RISER	INSTALLED 12" RISER	0.5	
	BROKEN LID	REPLACE LID	0.5	
04/05/2012	BROKEN LID	REPLACE LID	1.0	
04/18/2012	VENT CAP	INSTALL VENT CAP	1.0	
04/18/2012	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
04/18/2012	VENT CAP	INSTALL VENT CAP	0.5	
04/19/2012	VENT CAP	INSTALL VENT CAP	0.5	
04/19/2012	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	2.0	
05/01/2012	VENT CAP	INSTALL VENT CAP	0.5	
05/01/2012	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.3	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.3	
	VENT CAP	INSTALL VENT CAP	0.5 0.5	
	VENT CAP	INSTALL VENT CAP		
	VENT CAP VENT CAP	INSTALL VENT CAP	0.5 0.5	
05/28/2012	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	1.0	
05/28/2012		INSTALL VENT CAP	0.3	
05/28/2012		INSTALL VENT CAP	1.0	
06/01/2012		INSTALL VENT CAP	0.5	
06/01/2012		INSTALL VENT CAP	0.5	
06/01/2012		INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.3	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.3	
	VENT CAP	INSTALL VENT CAP	0.5	
06/18/2012		INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	1.0	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.3	
	VENT CAP	INSTALL VENT CAP	0.3	
	VENT CAP	INSTALL VENT CAP	0.5	
	VENT CAP	INSTALL VENT CAP	0.3	
	VENT CAP	INSTALL VENT CAP	0.3	
06/26/2012		INSTALL VENT CAP	0.3 0.3	
	VENT CAP			

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
06/26/2012	VENT CAD	INCTALL VENT CAR	(HOURS)	HOURS
06/26/2012	VENT CAP	INSTALL VENT CAP	0.3	
06/26/2012 06/26/2012	VENT CAP	INSTALL VENT CAP INSTALL VENT CAP	0.3	
07/11/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/11/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/12/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/14/2012	VENT CAP	INSTALL VENT CAP	1.0	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/14/2012	VENT CAP	INSTALL VENT CAP	1.0	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/14/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.3	
07/24/2012	VENT CAP	INSTALL VENT CAP	1.0	
07/24/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/26/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/26/2012	VENT CAP	INSTALL VENT CAP	0.5	
07/31/2012	VENT CAP	INSTALL VENT CAP	0.5	
08/07/2012	VENT CAP	INSTALL VENT CAP	0.5	
08/13/2012	VENT CAP	INSTALL VENT CAP	0.5	
08/14/2012	VENT CAP	INSTALL VENT CAP	0.5	
8/17/2012	BROKEN LID	REPLACE LID	0.5	
08/22/2012	VENT CAP	INSTALL VENT CAP	1.0	
08/30/2012	VENT CAP	INSTALL VENT CAP	0.5	
08/30/2012	VENT CAP	INSTALL VENT CAP	0.5	
09/04/2012	VENT CAP	INSTALL VENT CAP	1.0	
09/04/2012		INSTALL VENT CAP	0.5	
09/12/2012		INSTALL VENT CAP	0.5	
09/18/2012		INSTALL VENT CAP	0.5	
09/24/2012		INSTALL VENT CAP	0.5	
09/26/2012	VENT CAP	INSTALL VENT CAP	1.0	
10/1/2012	BROKEN LID	REPLACE LID	1.0	
10/22/2012	VENT CAP	INSTALL VENT CAP	0.5	
10/23/2012		INSTALLED 12" RISER	0.5	
10/26/2012	BROKEN LID	REPLACE LID	0.5	
11/26/2012	VENT CAP	INSTALL VENT CAP	0.5	
	- · · ·		0.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/23/2013	VENT CAP	REPLACED VENT CAP	0.5	
01/24/2013	VENT CAP	REPLACED VENT CAP	0.5	
	CHECK FOR STATION	BARREL IN BUT NO STATION	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	1.0	
	CUSTOMER NEEDS STATION RAISED	PERFORMED COST ESTIMATE TO RAISE STATION	1.0	
04/10/2013 04/22/2013	RECONNECT SERVICE VENT CAP	RECONNECTED REPLACED VENT CAP	1.0 0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	RISER	INSTALLED 12" RISER	1.0	
	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
- ' '	RELOCATE STATION	MOVED STATION CLOSER TO HOUSE & FRONT YARD	4.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	NEEDS 24" MBE	ADDED DISCONNECT BOX	1.0	
06/04/2013	VENT CAP	REPLACED VENT CAP	0.5	
06/05/2013	VENT CAP	REPLACED VENT CAP	0.5	
06/05/2013	VENT CAP	REPLACED VENT CAP	0.5	
06/06/2013	RELOCATE STATION	PERFORMED COST ESTIMATE TO RELOCATE STATION	1.0	
06/10/2013	VENT CAP	REPLACED VENT CAP	0.5	
06/10/2013	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	-
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
, -,	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP REPLACED VENT CAP	0.5 0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	GRANDSON FLUSHED UNDERWEAR	NO PROBLEM FOUND	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
08/07/2013	VENT CAP	REPLACED VENT CAP	1.0	
08/12/2013	VENT CAP	REPLACED VENT CAP	1.0	
08/13/2013	VENT CAP	REPLACED VENT CAP	0.5	
	RAISE MANHOLE	UNCOVERED & RAISED MANHOLE	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP VENT CAP	REPLACED VENT CAP REPLACED VENT CAP	0.5 0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
09/12/2013		REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
09/27/2013		REPLACED VENT CAP	0.5	
10/01/2013		REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
10/14/2013	VENT CAP	REPLACED VENT CAP	1.0	
10/18/2013	VENT CAP	REPLACED VENT CAP	0.5	
10/23/2013		REPLACED VENT CAP	0.5	
	HOSE TOO HIGH	PROBLEM ON CUSTOMER'S SIDE	1.0	
	ODOR	NEW CUSTOMER, STAGNANT WATER IN BARREL	1.0	
	POWER ISSUE	PROBLEM ON CUSTOMER'S SIDE	0.5	
	RECONNECT SERVICE LINE	RECONNECTED	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	1.0 1.0	
12/03/2013	VLIVI CAP	REPLACED VENT CAP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/04/2014	ODOR	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	3.0	YES
01/10/2014	ODOR	NO POWER ON CUSTOMER'S SIDE	1.0	
01/13/2014	BLOCKED LINE	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	3.0	YES
01/20/2014	ODOR	REPLACED SLIDER HOSE	1.0	
02/12/2014	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
02/21/2014	VENT CAP	REPLACED VENT CAP	0.5	
02/22/2014	BLOCKED LINE	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	3.0	YES
02/28/2014	VENT CAP	REPLACED VENT CAP	0.5	
03/07/2014	SEWER LINE EXPOSED & ODOR	NOT A SEWER LINE EXPOSED. BURIED CABLE. GREASE PROBLEM IN BARREL AND THEIR PIPE CAUSING ODOR.	1.0	
03/26/2014	VENT CAP	REPLACED VENT CAP	0.5	
03/28/2014	BLOCKED LINE	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
04/11/2014	VENT CAP	REAPLCED VENT CAP	0.5	
04/15/2014	VENT CAP AND CHECK PUMP	REPLACED VENT CAP AND REPLACED PUMP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
04/29/2014	VENT CAP	REPLACED VENT CAP	1.0	
04/30/2014	VENT CAP	REPLACED VENT CAP	1.0	
05/06/2014	VENT CAP	REPLACED VENT CAP	0.5	
05/12/2014	ODOR	STATION CHECK OKAY, LINE BLOCKED ON CUSTOMER'S SIDE	1.0	
05/14/2014	ODOR AND VENT CAP	REPLACED VENT CAP AND REPLACED PUMP	1.0	
05/20/2014	VENT CAP	REPLACED VENT CAP	0.5	
05/21/2014	WATER COMING UP THROUGH CONDUIT IN TANK	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
05/22/2014	VENT CAP	REPLACED VENT CAP	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
06/06/2014	VENT CAP	REPLACED VENT CAP	0.5	
	ODOR	NO POWER ON CUSTOMER'S SIDE	1.0	
06/16/2014	VENT CAP	REPLACED VENT CAP	0.5	
06/16/2014	VENT CAP	REPLACED VENT CAP	0.5	
06/17/2014	PUMP NOT WORKING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
06/20/2014	NO PUMP IN STATION	STATION HAD BEEN DISCONNECTED. DID NOT INSTALL PUMP AND ADVISED RESIDENT TO CONTACT THE OFFICE.	4.0	YES
06/23/2014	VENT CAP	REPLACED VENT CAP	1.0	
06/30/2014	ODOR	ODOR ISSUE ON CUSTOMER'S SIDE	0.5	
07/02/2014	REPLACE LID	REPLACED SEWER LID	0.5	
07/09/2014	ODOR	STATION CHECKED OKAY	1.0	
07/11/2014	VENT CAP	REPLACED VENT CAP	1.0	
07/15/2014	COMMODES WONT FLUSH	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
07/18/2014	ODOR	STATION CHECKED OKAY	0.5	
07/21/2014	ODOR	REPLACED VENT CAP & BURIED CABLE	1.0	
07/25/2014	VENT CAP	REPLACED VENT CAP	0.5	
08/13/2014	VENT CAP	REPLACED VENT CAP	0.5	
08/14/2014	REQUEST FOR RISER	CUSTOMER NEEDS TO UNCOVER STATION BEFORE MEASUREMENT FOR RISER CAN BE DONE	0.5	
08/20/2014	ODOR	INSTALLED PUMP AND REPLACED CABLE	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
10/13/2014	REQUEST FOR RISER	INSTALLED 12" RISER	1.0	
	VENT CAP	REPLACED VENT CAP	0.5	
10/28/2014	VENT CAP	REPLACED VENT CAP	0.5	
11/03/2014	BLOCKED LINE	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
11/13/2014	NEIGHBOR REPORTED SEWER RUNNING IN CREEK	CUSTOMER HAS BEEN DISCONNECTED. THEY WERE BYPASSING THROUGH THE 4" PIPE GOING TO THE	1.0	
12/14/2011		CREEK. REPORT TO HEALTH DEPT.	1.0	
12/14/2014	VENT CAP	REPLACED VENT CAP	1.0	

O3/11/2015 OSSIBLE ALARM ISSUE	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
S006/2015 DOOR	DATE	COMPLAINT	RESOLUTION	(HOURS)	HOURS
98/18/2015 NO POWER	03/11/2015	POSSIBLE ALARM ISSUE	ALARM CHECKED OUT OK	1.0	
99/04/2015 DISCONNECT LEAKING				1.0	
93/07/2015 SIORM DRAIN ISSUE			CUSTOMER SIDE	1.0	
MAINTAINED POWER ISSUE	09/04/2015	DISCONNECT LEAKING	DISCONNECT REPLACED	3.0	YES
MONTAGE POWER ISSUE/CUSTOMER SIDE 3.5 YES	03/07/2015	STORM DRAIN ISSUE	DOES NOT BELONG TO MWD	2.5	YES
Systap.2015 OUSTOMER ISSUE			POWER ISSUE/CUSTOMER SIDE	1.0	
09/15/2015 DORR	04/01/2015	CUSTOMER ISSUE	POWER ISSUE/CUSTOMER SIDE	3.5	YES
OPTION POWER ISSUE/CUSTOMER SIDE 3.0 YES	05/18/2015	CUSTOMER ISSUE	POWER ISSUE/CUSTOMER SIDE	1.0	
07/29/2015 CUST INSTALLING DRAIN REMOVED SEWER LINES FOR INSTALLATION OF A 9.5 06/22/2015 DAMAGED CONTROL BOX REPLACED CONTROL BOX 1.0 03/31/2015 DAMAGED CONTROL BOX REPLACED CONTROL BOX 1.0 02/05/2015 NEEDS VENT CAP REPLACED CONTROL BOX 1.0 03/30/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 03/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 04/14/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 04/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 05/28/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 05/28/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 05/28/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 06/12/2015 NEEDS VENT CAP REPLACED VENT CAP	08/25/2015	ODOR	POWER ISSUE/CUSTOMER SIDE	1.0	
DRAIN AND REPLACED AFTER THEY FINISHED 9.5	09/15/2015	PUMP NOT WORKING CORRECTLY	POWER ISSUE/CUSTOMER SIDE	3.0	YES
GAPAZZO15 DAMAGED CONTROL BOX REPLACED DORN ON CONTROL BOX 1.0	07/29/2015	CUST INSTALLING DRAIN		9.5	
03/11/2015 DAMAGED CONTROL BOX REPLACED DOOR ON CONTROL BOX 1.0	06/22/2015	DAMAGED CONTROL BOX		1.0	
02/05/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5					
0.3730/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0					
04/14/2015 NEEDS VENT CAP					
DS/18/2015 NEEDS VENT CAP REPLACED VENT CAP D.5 DS/28/2015 DDCR REPLACED VENT CAP D.5 DS/28/2015 NEEDS VENT CAP REPLACED VENT CAP D.5 DS/28/2015 DOCR REPLACED VENT CAP D.5 DS/28/2015 DOCR RE					
S7/26/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0					
10.0 10.0					
06/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5					
06/19/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5				_	
O6/29/2015 ODOR					
O7/07/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5					
07/09/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5					
O7/20/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 O7/28/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 O7/31/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O8/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O8/10/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O8/10/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O8/10/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O8/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O9/08/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O9/10/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O9/10/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O9/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 O9/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 O1/21/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 O1/21/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 O1/21/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 O1/30/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 O8/31/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 O8/31/2015 ODOR ST					
07/28/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5					
07/31/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/10/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/17/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 08/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/24/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/24/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/09/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/21/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 <t< td=""><td></td><td></td><td></td><td></td><td></td></t<>					
08/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/10/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 08/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/24/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 11/04/2015 ODOR REPLACED VENT CAP 0.5 11/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/29/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/29/20					
08/10/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/17/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 08/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/24/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/09/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 10/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 <t< td=""><td></td><td></td><td></td><td></td><td></td></t<>					
08/17/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 08/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/24/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/09/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 10/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 <t< td=""><td></td><td></td><td></td><td></td><td></td></t<>					
08/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 08/24/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/09/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/21/2015 ODOR REPLACED VENT CAP 0.5 10/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/40/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/20					
08/24/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/09/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/21/2015 ODOR REPLACED VENT CAP 0.5 10/23/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/20					
09/08/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/09/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/21/2015 ODOR REPLACED VENT CAP 0.5 10/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/04/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 ODOR REPLACED VENT CAP 0.5 11/30/2015 ODOR STN OK 0.5 11/30/2015 ODOR					
09/09/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/21/2015 DOOR REPLACED VENT CAP 0.5 10/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/04/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 ODOR REPLACED VENT CAP 0.5 11/30/2015 ODOR STN OK 3.0 03/13/2015 ODOR STN OK 3.0 03/13/2015 ODOR STN OK/CUS					
09/10/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/21/2015 ODOR REPLACED VENT CAP 0.5 10/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/04/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 ODOR REPLACED VENT CAP 0.5 11/30/2015 ODOR REPLACED VENT CAP 0.5 11/30/2015 ODOR STN OK 3.0 03/13/2015 ODOR STN OK 3.0 03/13/2015 GODR STN OK/PROBLEM ON CU					
09/16/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 10/06/2015 NEEDS VENT CAP 1.0 10/21/2015 ODOR REPLACED VENT CAP 0.5 10/30/2015 NEEDS VENT CAP 0.5 11/04/2015 NEEDS VENT CAP 0.5 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 ODOR REPLACED VENT CAP 0.5 11/30/2015 ODOR STN OK 3.0 03/13/2015 ODOR STN OK 3.0 03/13/2015 POSSIBLE GRINDER ISSUE STN OK/POBLEM ON CUSTOMERS SIDE 1.0 05/05/2015 GRINDER NOT WORKING STN OK/CUSTOMER SIDE VENT PIPE 1.0					
10/06/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0					
10/21/2015 ODOR REPLACED VENT CAP O.5 10/30/2015 NEEDS VENT CAP REPLACED VENT CAP O.5 11/04/2015 NEEDS VENT CAP REPLACED VENT CAP O.5 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP O.5 11/19/2015 NEEDS VENT CAP REPLACED VENT CAP O.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP O.5 11/30/2015 NEEDS VENT CAP REPLACED VENT CAP O.5 11/30/2015 ODOR REPLACED VENT CAP O.5 10/17/2015 ODOR STN OK O.5 10/17/2015 ODOR STN OK O.5 10/17/2015 ODOR STN OK/PROBLEM ON CUSTOMERS SIDE O.0 1.0 OS/05/2015 ODOR STN OK/PROBLEM ON CUSTOMERS SIDE O.0 1.0 OS/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE O.0 1.0 OS/12/2015 ODOR OS/12/2015 OS/12/2015 OS/12/2015 OS/12/2015 OS/12/2015 OS/12/2015 OS/12/2015 OS/1	, -, -				
10/30/2015 NEEDS VENT CAP REPLACED VENT CAP 1.0					
11/04/2015 NEEDS VENT CAP 1.0 11/19/2015 NEEDS VENT CAP 0.5 11/20/2015 NEEDS VENT CAP 0.5 11/20/2015 NEEDS VENT CAP 0.5 11/30/2015 NEEDS VENT CAP 0.5 11/30/2015 ODOR REPLACED VENT CAP 0.5 10/17/2015 ODOR STN OK 3.0 03/13/2015 POSSIBLE GRINDER ISSUE STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 04/20/2015 GRINDER NOT WORKING STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 05/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/					
11/19/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 NEEDS VENT CAP 0.5 0.5 11/30/2015 ODOR REPLACED VENT CAP 0.5 10/17/2015 ODOR STN OK 3.0 03/13/2015 POSSIBLE GRINDER ISSUE STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 04/20/2015 GRINDER NOT WORKING STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 05/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 3.0 YES 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE					
11/20/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 NEEDS VENT CAP 0.5 11/30/2015 ODOR REPLACED VENT CAP 0.5 10/17/2015 ODOR STN OK 3.0 03/13/2015 POSSIBLE GRINDER ISSUE STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 04/20/2015 GRINDER NOT WORKING STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 05/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 3.0 YES 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0					
11/30/2015 NEEDS VENT CAP REPLACED VENT CAP 0.5 11/30/2015 ODOR REPLACED VENT CAP 0.5 10/17/2015 ODOR STN OK 3.0 03/13/2015 POSSIBLE GRINDER ISSUE STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 04/20/2015 GRINDER NOT WORKING STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 05/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 3.0 YES 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0				· ·	
11/30/2015 ODOR REPLACED VENT CAP 0.5 10/17/2015 ODOR STN OK 3.0 03/13/2015 POSSIBLE GRINDER ISSUE STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 04/20/2015 GRINDER NOT WORKING STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 05/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 3.0 YES 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0					
10/17/2015 ODOR STN OK 3.0 03/13/2015 POSSIBLE GRINDER ISSUE STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 04/20/2015 GRINDER NOT WORKING STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 05/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 3.0 YES 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0					
03/13/2015 POSSIBLE GRINDER ISSUE STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 04/20/2015 GRINDER NOT WORKING STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 05/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 3.0 YES 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0					
04/20/2015 GRINDER NOT WORKING STN OK/ PROBLEM ON CUSTOMERS SIDE 1.0 05/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 3.0 YES 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0					
05/05/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 3.0 YES 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0					
08/11/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 3.0 YES 08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0			,		
08/18/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0					
09/09/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0	08/11/2015		STN OK/CUSTOMER SIDE VENT PIPE		YES
09/23/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0		ODOR	STN OK/CUSTOMER SIDE VENT PIPE	1.0	
09/29/2015 ODOR STN OK/CUSTOMER SIDE VENT PIPE 1.0 03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0		ODOR	STN OK/CUSTOMER SIDE VENT PIPE	1.0	
03/12/2015 POSSIBLE GRINDER ISSUE STN OK/WORKING PROPERLY 1.0	09/23/2015	ODOR	STN OK/CUSTOMER SIDE VENT PIPE	1.0	
		ODOR	STN OK/CUSTOMER SIDE VENT PIPE		
00/00/2015 EVERSONE MATERIAL CTN	03/12/2015	POSSIBLE GRINDER ISSUE	STN OK/WORKING PROPERLY	1.0	
U3/U3/2U15 EXCESSIVE WATER IN STN TOILET RUNNING 1.0	09/09/2015	EXCESSIVE WATER IN STN	TOILET RUNNING	1.0	

			COMPLETION TIME	AFTER
DATE	COMPLAINT	RESOLUTION	(HOURS)	HOURS
01/08/2016	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
01/11/2016	REPLACE VENT CAP	REPLACED VENT CAP	1.0	
01/15/2016	SLOW DRAINS	CHECKED OKAY	0.5	
01/21/2016	COMMODE WON'T FLUSH	CHECKED OKAY	2.0	
01/30/2016	STATION NOT WORKING PROPERLY	CHANGED CABLE, EQD, HOUSING	3.0	YES
03/16/2016	ODOR	CHECKED OKAY	0.5	
04/06/2016	REPLACE LID	REPLACED LID	0.5	
04/07/2016	ODOR	CHECKED OKAY	1.0	
04/13/2016	TRAILER BURNED	REMOVED PUMP, PLUGGED SEWER	1.0	
05/10/2016	BURY CABLE	BURIED CABLE	1.0	
05/11/2016	REPLACE VENT CAP	REPLACED VENT CAP	0.3	
05/11/2016	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
05/24/2016		CHECKED OKAY	1.0	
		REPLACED VENT CAP	1.0	
06/21/2016		CHECKED OKAY	1.0	
	REPLACE VENT CAP	REPLACED VENT CAP	1.0	
	REPLACE VENT CAP	REPLACED VENT CAP	0.3	
	COMMODE WON'T FLUSH	CHECKED OKAY	1.0	
	ODOR	CHECKED OKAY	1.5	
07/19/2016		CHECKED OKAY	1.0	
	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
07/21/2016	REPLACE VENT CAP	REPLACED VENT CAP	0.3	
07/21/2016	WATER WON'T GO DOWN IN SINK	SINK WAS ONLY PLACE CUSTOMER WAS HAVING PROBLEM, ISSUE ON CUSTOMER'S SIDE.	1.0	
07/25/2016	ODOR	CHECKED OKAY	1.0	
07/27/2016	ODOR	LEAK IN NEIGHBORHOOD CAUSING ODOR	1.0	
08/02/2016	REPLACE VENT CAP	REPLACED VENT CAP	0.3	
08/02/2016	REPLACE VENT CAP	REPLACED VENT CAP	0.3	
08/02/2016	REPLACE VENT CAP	REPLACED VENT CAP	1.0	
08/08/2016	ODOR	CHECKED OKAY	1.0	
08/10/2016	ODOR	CHECKED OKAY	1.0	
08/12/2016	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
08/22/2016	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
08/29/2016	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
09/06/2016	COST ESTIMATE TO RECONNECT	LISTED PARTS NEEDED TO COST OUT FOR RECONNECTION OF SERVICE	1.0	
09/06/2016	HOUSE BEING TORN DOWN	PULLED PUMP, TURNED OFF BREAKERS	0.5	
	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
09/08/2016	ODOR	CHECKED OKAY	1.0	
	REPLACE LID	REPLACED CRACKED LID	0.5	
	POSSIBLE LEAK	NO LEAK FOUND ON MWD SIDE. OLD SEPTIC LINE LEAKING ON CUSTOMER'S SIDE.	2.0	
09/30/2016	BREAKER ISSUE	TURNED BREAKER ON, CHECKED OKAY	1.0	
10/06/2016		REPLACED LID ON VALVE	0.5	
	BREAKER ISSUE	TURNED BREAKER ON, CHECKED OKAY	1.0	
10/07/2016		CHECKED OKAY	1.0	
	STATION NOT WORKING	NO POWER ON CUSTOMER'S SIDE	0.5	
	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
	ODOR ODOR	CHECKED OKAY	0.5	
	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
	REPLACE VENT CAP	REPLACED VENT CAP	0.5	
	ODOR ODOR	REPAIRED CLEANOUT CAP	1.0	
	KICKING OFF AND ON	REPLACED EQD	1.0	
	TROUBLE FLUSHING	CHECKED OKAY	0.5	
12/16/2016	ODOR	PUT OUT ODOR BLOCK	0.5	
,,,	1		5.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
02/03/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	1.0	1100113
02/28/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	1.0	
03/09/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
03/09/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
04/04/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	1.0	
04/12/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	1.0	
04/17/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
05/01/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	1.0	
	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
			0.5	
06/16/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP		
06/16/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
06/20/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
06/28/2017	RISER	INSTALLED 2' RISER ON STATION	1.0	
07/03/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
07/03/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
07/03/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
07/10/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
07/19/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
08/02/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
08/07/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	1.0	
08/09/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	1.0	
08/25/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
09/01/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
09/01/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
09/07/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
09/20/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
09/29/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
10/13/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.5	
		CUSTOMER CLAIMED LID WAS BUSTED. FOUND A		
10/27/2017	BUSTED LID	CAVED IN SEPTIC TANK NOT CONNECTED TO MWD	0.5	
		SYSTEM		
11/03/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
12/01/2017	LEVEL STATION	DUG UP AND LEVELED STATION	2.0	
12/07/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
12/07/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
12/07/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
12/07/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
12/07/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
12/07/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	
12/07/2017	NEEDS VENT CAP REPLACED	REPLACED VENT CAP	0.3	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
03/01/2018	VENT CAP	REPLACED VENT CAP	(HOURS) 0.5	HOURS
03/01/2018	VENT CAP	REPLACED VENT CAP	0.5	
04/06/2018	REPLACE LID	REPLACED SEWER LID	1.0	
	VENT CAP	REPLACED SEWER EID	0.3	
04/09/2018	VENT CAP	REPLACED VENT CAP	0.3	
04/23/2018	VENT CAP	REPLACED VENT CAP	0.8	
04/27/2018	VENT CAP	REPLACED VENT CAP	1.0	
04/30/2018	VENT CAP	REPLACED VENT CAP	1.0	
05/02/2018	VENT CAP	REPLACED VENT CAP	0.5	
05/02/2018	VENT CAP	REPLACED VENT CAP	0.5	
	VENT CAP	REPLACED VENT CAP	0.5	
05/09/2018	VENT CAP	REPLACED VENT CAP	0.5	
06/08/2018	VENT CAP	REPLACED VENT CAP	1.0	
06/16/2018	VENT CAP	REPLACED VENT CAP	1.5	YES
06/18/2018	VENT CAP	REPLACED VENT CAP	0.5	123
06/18/2018	VENT CAP	REPLACED VENT CAP	1.0	
06/19/2018	VENT CAP	REPLACED VENT CAP	0.5	
06/20/2018	RISER	INSTALLED 12" RISER	1.0	
06/26/2018	VENT CAP	REPLACED VENT CAP	0.5	
07/03/2018	VENT CAP	REPLACED VENT CAP	0.5	
07/05/2018	VENT CAP	REPLACED VENT CAP	0.5	
07/06/2018	VENT CAP	REPLACED VENT CAP	0.5	
07/10/2018	RISER	INSTALLED 12" RISER	1.0	
		CUSTOMER REPLACED BREAKER BOX AND WATER		
07/23/2018	CUSTOMER REQUEST	MWD TO CHECK PUMP. WORKING FINE	1.0	
07/23/2018	RISER	INSTALLED 24" RISER	1.0	
07/23/2018	VENT CAP	REPLACED VENT CAP	0.5	
07/24/2018	VENT CAP	REPLACED VENT CAP	0.5	
08/02/2018	VENT CAP	REPLACED VENT CAP	0.5	
08/27/2018	VENT CAP	REPLACED VENT CAP	0.5	
08/29/2018	VENT CAP	REPLACED VENT CAP	0.5	
09/05/2018	VENT CAP	REPLACED VENT CAP	0.5	

EMERGENCY SERVICE CALLS

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP AND CABLE	4.0	YES
01/02/2010	LIGHT/ALARM	REPLACED PUMP	3.0	
01/05/2010	OVERFLOWING	UNDER PROJECT WARRANTY. CONTACTED THE CONTRACTOR.	1.0	
01/06/2010	STATION BACKING UP	UNDER PROJECT WARRANTY. CONTACTED THE CONTRACTOR.	1.0	
01/07/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	2.0	
	OVERFLOWING	REPLACED PUMP, THAWED PIPE IN CREEK	4.0	
	LIGHT/ALARM	REPLACED WET CABLE	4.5	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	5.0	YES
01/12/2010	LIGHT/ALARM	REPLACED PUMP	1.0	120
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
01/13/2010	OVERFLOWING	REPLACED PUMP	1.0	
01/18/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD ON/OFF SWITCH	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
01/20/2010	ODOR	STATION CHECKED OKAY UPON ARRIVAL.	1.0	
	OVERFLOWING	REPLACED PUMP	2.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
01/28/2010			2.0	
	OVERFLOWING	REPLACED PUMP		VEC
	LIGHT/ALARM	CLEANED OUT STATION DUE TO SOLIDS	4.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
02/03/2010	LIGHT/ALARM	REPLACED PUMP AND CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP, CABLE & BREAKERS	1.0	
	LIGHT/ALARM	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	2.0	
	LIGHT/ALARM	PROBLEM ON CUSTOMER'S SIDE	2.0	
	OVERFLOWING	NO POWER AT STATION	3.0	YES
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	PUMP NOT WORKING	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	2.0	YES
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
02/23/2010	OVERFLOWING	REPLACED PUMP	4.0	YES
02/23/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
02/24/2010	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP DUE TO BAD ON/OFF SWITCH	1.0	
	LIGHT/ALARM	REPLACED PUMP AND CABLE	2.0	
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
02/26/2010	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	2.0	
03/01/2010	OVERFLOWING	REPLACED PUMP	2.0	YES
03/01/2010	LIGHT/ALARM	REPLACED PUMP	2.0	
03/01/2010	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
03/03/2010		DEDI ACED DUMAD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
03/04/2010	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	2.0	
	i .			YES

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
,,	PUMP NOT WORKING	REPLACED PUMP DUE TO BABY WIPES IN STATION	2.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	5.0	YES
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM OVERFLOWING	REPLACED PUMP REPLACED PUMP DUE TO BAD STATOR	1.0 1.0	
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.5	TES
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
1 1	LIGHT/ALARM	RESET PUMP DUE TO AIR LOCKED	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
1 1	LIGHT/ALARM	REPLACED PUMP AND CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP AND CABLE	5.0	YES
	OVERFLOWING	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP	3.0	YES
03/22/2010		REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PLASTIC PIG TAIL ON OUTSIDE OF BARRELL	2.0	
03/24/2010	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.5	
03/26/2010		REPLACED PUMP	1.0	
	COMMODES NOT FLUSHING PROPERLY	REPLACED PUMP, CABLE & CONTROL BOARD	5.0	YES
03/26/2010		RESET PUMP IN ALARM STAGE	0.5	
03/27/2010	OVERFLOWING	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	
03/29/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	1.5	
03/30/2010	STATION BACKING UP	BLOCKED LINE ON CUSTOMER'S SIDE	0.5	
03/30/2010	OVERFLOWING	NO POWER AT STATION	1.0	
03/31/2010	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	3.0	YES
04/01/2010	OVERFLOWING	REPLACED PUMP	1.0	
04/01/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
04/03/2010	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
04/05/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
04/05/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
04/06/2010	OVERFLOWING	REPLACED PLASTIC PIG TAIL WITH BRASS. INSTALLED PRESSURE CONNECT & BOX.	3.0	
04/06/2010	OVERFLOWING	REPLACED PUMP, CABLE & CONTROL BOARD	2.0	
04/06/2010	OVERFLOWING	STATION CHECKED OKAY UPON ARRIVAL.	1.0	
	LIGHT/ALARM	RESET PUMP IN ALARM STAGE	1.0	-
04/08/2010	LIGHT/ALARM	REPLACED PUMP	3.0	YES
04/08/2010	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE ISSUE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	NO POWER AT STATION	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	RESET PUMP IN ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
04/13/2010	LIGHT/ALARM	REPLACED PUMP	3.0	YES
04/14/2010	OVERFLOWING	REPLACED PLASTIC PIG TAIL ON OUTSIDE OF BARRELL	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
04/19/2010	LIGHT/ALARM	REPLACED PUMP	3.0	YES
04/19/2010	LIGHT/ALARM	REPLACED PUMP DUE TO ELECTRICAL SHORT IN PUMP	1.5	
04/19/2010	OVERFLOWING	UNDER PROJECT WARRANTY. CONTACTED THE CONTRACTOR.	1.0	
04/20/2010	OVERFLOWING	REPLACED PUMP	1.0	
04/20/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
04/20/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
04/20/2010	LIGHT/ALARM	UNDER PROJECT WARRANTY. CONTACTED THE	1.0	
04/21/2010	LIGHT/ALARM	CONTRACTOR. REPLACED PUMP AND CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	UNDER PROJECT WARRANTY. CONTACTED THE CONTRACTOR.	0.5	
04/23/2010	LIGHT/ALARM	REPLACED PUMP	3.0	YES
04/24/2010	LIGHT/ALARM	REPLACED PUMP	4.0	YES
04/26/2010	OVERFLOWING	REPLACED PUMP	1.0	
04/26/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
04/26/2010	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP, CABLE, CONTROL BOARD	2.0	YES
04/26/2010	OVERFLOWING	REPLACED PUMP, CLEANED LINE, BLOCKED ON MWD SIDE	6.0	
04/27/2010	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
04/28/2010	ODOR	REPLACED PUMP	1.0	
04/28/2010	STATION BACKING UP	REPLACED PUMP AND CABLE	2.0	
04/30/2010	BREAKERS KICKING	REPLACED PUMP, CABLE, CONTROL BOARD & BREAKER	1.0	
	LIGHT/ALARM	RESET ALARM	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD ON/OFF SWITCH	1.0	
05/03/2010	PUMP NOT WORKING	REPLACED PUMP DUE TO BAD STATOR	1.0	
05/03/2010	LIGHT/ALARM	REPLACED PUMP, CUSTOMER TO REPAIR GROUND WATER PROBLEM ON THEIR SIDE	2.0	
05/04/2010	LIGHT/ALARM	CUSTOMER HAD PLUMBED A SUMP PUMP INTO STATION. MWD MADE CUSTOMER TURN IT OFF AND REMOVE IT.	1.0	
05/06/2010	LIGHT/ALARM	REPLACED PUMP AND CABLE, MOVED CONTROL BOX	4.0	
05/06/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.5	
05/07/2010	LIGHT/ALARM	REPLACED BAD CABLE	3.0	YES
<u> </u>	OVERFLOWING	STATION CHECKED OKAY UPON ARRIVAL.	2.0	
05/10/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
05/10/2010	OVERFLOWING	STATION CHECKED OKAY. CUSTOMER HAS LEAK ON HIS SIDE.	0.5	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE ISSUE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
1 1	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	3.0	YES
	LIGHT/ALARM LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL. REPLACED PUMP	3.0 1.5	YES
	STATION BACKING UP	REPLACED PUMP. CUSTOMER ALSO HAS BLOCKED LINE		YES
		ON HIS SIDE.		
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD CHECK VALVE	1.5	
	LIGHT/ALARM	REPLACED PUMP BREAKER KNOCKED IN THE BARRELL. RESET BREAKER	1.0 0.5	
	LIGHT/ALARM OVERFLOWING	NO POWER AT STATION	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	3.0	YES
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	CUSTOMER'S 4" LINE BLOCKED	1.0	
	LIGHT/ALARM	NO POWER AT STATION	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP. UNDER PROJECT WARRANTY. BILLED CONTRACTOR.	5.0	YES
05/24/2010	OVERFLOWING	NO POWER AT STATION	1.0	
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
	STATION BACKING UP	CUSTOMER'S 4" LINE BLOCKED	1.0	
	OVERFLOWING	NO POWER AT STATION	1.0	
	PUMP NOT WORKING	REPLACED PUMP & CONTROL BOARD	2.0	

OURSPICATION OUR O	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
09.271/2010 UGHT/ALARM	05/26/2010	OVERELOWING	REDIACED DIIMP	· · · · · · · · · · · · · · · · · · ·	HOURS
05/27/2010 IGHT/ALARM					
05/29/2010 DUERTLOWING REPLACED PUMP 3.0 YES 05/29/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/29/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/29/2010 LIGHT/ALARM REPLACED PUMP AND CABLE 1.0 05/20/2010 LIGHT/ALARM RESET PUMP DUE TO AR LOCKED 0.5 05/20/2010 LIGHT/ALARM RESET PUMP DUE TO AR LOCKED 0.5 05/20/2010 LIGHT/ALARM RESET PUMP DUE TO AR LOCKED 0.5 05/20/2010 LIGHT/ALARM RESET PUMP DUE TO AR LOCKED 0.5 05/20/2010 LIGHT/ALARM CONTRACTED THE 1.0 06/20/2010 COMMODES NOT FLUSHING PROPERLY 0.0 06/20/2010 COMPETION PRO		•			YES
05/29/2010 LIGHT/JALARM					
0,000/12/2010 LIGHT/ALARM				3.0	YES
0.60/01/2010 UGHT/JALARM		-	REPLACED PUMP	3.0	YES
UNDER PROJECT USHT/ALARM	06/01/2010	LIGHT/ALARM	REPLACED PUMP AND CABLE	1.0	
USHT/ALARM	06/01/2010	LIGHT/ALARM	RESET PUMP DUE TO AIR LOCKED	0.5	
06/03/2010 COMMODES NOT FLUSHING PROPERLY CLOGGED LUNE ON MYD SIDE, CLEANED OUT 1.0 06/03/2010 OVERFLOWING REPLACED PUMP AND CABLE 2.0 06/03/2010 OVERFLOWING REPLACED PUMP AND CABLE 1.0 06/03/2010 PUMP NOT WORKING STATION CHECKED OKAY UPON ARRIVAL 1.0 06/03/2010 PUMP NOT WORKING STATION CHECKED OKAY UPON ARRIVAL 1.0 06/03/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 1.0 06/03/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 2.0 06/03/2010 PUMP NOT WORKING REPLACED PUMP DIA DO ADD STATOR 1.0 06/03/2010 PUMP NOT WORKING REPLACED PUMP DIA DO ADD STATOR 1.0 06/03/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO ADD STATOR 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP DIA DO CARD 3.0 YES 06/05/2010 USHTYALABM REPLACED PUMP 3.0 YES 06/05/2010 USH	06/01/2010	LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL.	2.0	
0.603/2010 OVERLOWING	06/01/2010	LIGHT/ALARM		1.0	
0.6963/2010 OVERFLOWING	06/03/2010	COMMODES NOT FLUSHING PROPERLY	CLOGGED LINE ON MWD SIDE, CLEANED OUT	1.0	
SATION CHECKED OKAY UPON ARRIVAL 1.0	06/03/2010	OVERFLOWING	REPLACED PUMP AND CABLE	2.0	
06/04/2010 OVERFLOWING REPLACED PUMP NO CABLE 2.0		OVERFLOWING	REPLACED PUMP AND CABLE	1.0	
G6/04/2010 UMPN DOT WORKING REPLACED PUMP AND CABLE 2.0	06/03/2010	PUMP NOT WORKING	STATION CHECKED OKAY UPON ARRIVAL.	1.0	
	06/04/2010	OVERFLOWING	REPLACED PUMP	1.0	
				2.0	
STATION BACKING UP REPLACED PUMP DUE TO BAD STATOR 3.0 YES	06/05/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
SEWER LEAK					YES
SCAPE_COLOR PUMP NOT WORKING REPLACED PUMP AND CABLE 2.0					
MASTORN LODSE FROM THE BOX 2.0	06/09/2010	LIGHT/ALARM		1.0	
	06/10/2010	DAMAGE TO STATION	1	2.0	
	06/10/2010	LIGHT/ALARM	REPLACED PUMP	2.0	
	06/10/2010	LIGHT/ALARM	REPLACED PUMP	3.0	
ODOR		LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
06/11/2010 ODOR	06/10/2010	LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL.	0.5	
	06/10/2010	ODOR		1.0	
06/11/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/12/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/12/2010 LIGHT/ALARM STATION CHECKED OKAY UPON ARRIVAL 5.0 YES 06/13/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/14/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/15/2010 STATION BACKING UP BREAKER SKNOCKED ON CUSTOMER'S SIDE 1.0 06/16/2010 OVERFLOWING REPLACED PUMP 1.0 06/16/2010 LIGHT/ALARM STATION CHECKED OKAY UPON ARRIVAL 0.5 06/17/2010 OVERFLOWING REPLACED PUMP 1.0 06/17/2010 OVERFLOWING REPLACED PUMP 1.0 06/17/2010 OVERFLOWING REPLACED PUMP 1.0 06/17/2010 LIGHT/ALARM REPLACED PUMP 1.0	06/11/2010	LIGHT/ALARM		1.0	
06/12/2010 LIGHT/ALARM					
06/13/2010 LIGHT/ALARM		1		3.0	YES
06/13/2010 LIGHT/ALARM	06/12/2010	LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL.	5.0	YES
06/14/2010	06/13/2010	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/14/2010 LIGHT/ALARM		LIGHT/ALARM	REPLACED PUMP	1.0	
06/15/2010 STATION BACKING UP BREAKERS KNOCKED ON CUSTOMER'S SIDE 1.0 06/16/2010 OVERFLOWING REPLACED PUMP 1.0 06/16/2010 LIGHT/ALARM STATION CHECKED DKAY UPON ARRIVAL. 0.5 06/17/2010 OVERFLOWING BREAKERS KNOCKED ON CUSTOMER'S SIDE 4.0 YES 06/17/2010 OVERFLOWING REPLACED PUMP 1.0 WES 06/17/2010 LIGHT/ALARM REPLACED PUMP 1.0 WES 06/17/2010 LIGHT/ALARM REPLACED PUMP 1.0 WES 06/19/2010 LIGHT/ALARM NO POWER AT STATION 3.0 YES 06/19/2010 LIGHT/ALARM NO POWER AT STATION 3.0 YES 06/19/2010 LIGHT/ALARM REPLACED PUMP 1.0 WES 06/21/2010 UIGHT/ALARM REPLACED PUMP 1.0 WES 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 WES 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 WES 06/21/2010	06/14/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
06/16/2010 OVERFLOWING REPLACED PUMP 1.0 06/16/2010 LIGHT/ALARM STATION CHECKED OKAY UPON ARRIVAL. 0.5 06/17/2010 OVERFLOWING BREAKERS KNOCKED ON CUSTOMER'S SIDE 4.0 YES 06/17/2010 OVERFLOWING REPLACED PUMP 1.0 1.0 06/17/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 1.0 06/19/2010 LIGHT/ALARM NO POWER AT STATION 3.0 YES 06/19/2010 LIGHT/ALARM NO POWER AT STATION 3.0 YES 06/19/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2010 OVERFLOWING REPLACED PUMP 1.0 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES					
06/16/2010 LIGHT/ALARM STATION CHECKED OKAY UPON ARRIVAL. 0.5 06/17/2010 OVERFLOWING BREAKERS KNOCKED ON CUSTOMER'S SIDE 4.0 YES 06/17/2010 OVERFLOWING REPLACED PUMP 1.0 06/17/2010 1.0 06/17/2010 1.0 06/17/2010 1.0 06/17/2010 00 06/17/2010 1.0 06/17/2010 00 00 00 00 00 1.0 06/17/2010 00 00 1.0 06/17/2010 1.0 00 00 00 1.0 06/19/2010 1.0 00 00 06/19/2010 1.0 00 00 00 1.0 00 06/19/2010 1.0 00 00 00 00 00 00 1.0 00					
06/17/2010 OVERFLOWING BREAKERS KNOCKED ON CUSTOMER'S SIDE 4.0 YES 06/17/2010 OVERFLOWING REPLACED PUMP 1.0 06/17/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 06/19/2010 LIGHT/ALARM NO POWER AT STATION 3.0 YES 06/19/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2010 OVERFLOWING REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 CONTROL BOARD 2.0 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOA					
06/17/2010 OVERFLOWING REPLACED PUMP 1.0 06/17/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 06/19/2010 LIGHT/ALARM NO POWER AT STATION 3.0 YES 06/19/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2010 OVERFLOWING REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 OC 06/22/2010 LIGHT/ALARM REPLACED PUMP AND CABLE 1.0 OC <td></td> <td></td> <td></td> <td></td> <td></td>					
06/17/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 06/19/2010 LIGHT/ALARM NO POWER AT STATION 3.0 YES 06/19/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2010 OVERFLOWING REPLACED PUMP 1.0 06/21/2010 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/21/2010 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2010 06/21/2010 UIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/21/2010 06/22/2010 LIGHT/ALARM REPLACED PUMP AND CABLE					YES
06/17/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 06/19/2010 LIGHT/ALARM NO POWER AT STATION 3.0 YES 06/19/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2010 OVERFLOWING REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP CABLE & CONTROL BOARD 2.0 YES 06/21/2010 UIGHT/ALARM REPLACED PUMP CABLE & CONTROL BOARD 2.0 YES 06/22/2010 LIGHT/ALARM REPLACED PUMP AND CABLE 1.0 YES 06/22/2010 LIGHT/ALARM					
06/19/2010 LIGHT/ALARM NO POWER AT STATION 3.0 YES 06/19/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2010 OVERFLOWING REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 YES 06/21/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 I.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 I.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 I.0 06/22/2010					
06/19/2010 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2010 OVERFLOWING REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 VES 06/21/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 VES 06/22/2010 LIGHT/ALARM REPLACED PUMP AND CABLE 1.0 VES 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 VES 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 VES 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 VES 06/22/2010		1			VEC
06/21/2010 OVERFLOWING REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 DVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP 2.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP AND CABLE 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 1.0 06/22/2010		1			
06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 COMMAND 06/21/2010 DVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 COMMAND 06/22/2010 LIGHT/ALARM REPLACED PUMP 2.0 COMMAND 06/22/2010 LIGHT/ALARM REPLACED PUMP AND CABLE 1.0 COMMAND 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 COMMAND 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 COMMAND 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 COMMAND 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5					YES
06/21/2010 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 1.0 06/21/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP 2.0 1.0 06/22/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP CABLE & CONTROL BOARD					
06/21/2010 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 CONTROL BOARD 2.0 06/21/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM REPLACED PUMP 2.0 CONTROL BOARD 2.0 06/22/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 1.0 CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 CONTROL BOARD 0.5 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 CONTROL BOARD 1.5					
06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP 2.0 06/22/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 DOOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0		-			
06/21/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 2.0 YES 06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP 2.0 06/22/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 DOOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0	· ·	•			
06/21/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP 2.0 06/22/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 DOOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0					YFS
06/21/2010 OVERFLOWING STATION CHECKED OKAY UPON ARRIVAL. 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP 2.0 06/22/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 ODOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0					112
06/22/2010 LIGHT/ALARM REPLACED PUMP 2.0 06/22/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 ODOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0			·		
06/22/2010 PUMP NOT WORKING REPLACED PUMP AND CABLE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 ODOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0	· ·				
06/22/2010 LIGHT/ALARM REPLACED PUMP STUCK IN ALARM STAGE 1.0 06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 ODOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0		1			
06/22/2010 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 ODOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0		1		1	
06/22/2010 LIGHT/ALARM RESET PUMP DUE TO AIR LOCKED 0.5 06/22/2010 ODOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0		1			
06/22/2010 ODOR STATION CHECKED OKAY UPON ARRIVAL. 1.5 06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0		1			
06/23/2010 PUMP NOT WORKING NO POWER AT STATION 1.0 06/23/2010 OVERFLOWING REPLACED PUMP 1.0		1			
06/23/2010 OVERFLOWING REPLACED PUMP 1.0		PUMP NOT WORKING		1.0	
06/23/2010 LIGHT/ALARM REPLACED PUMP 1.0	06/23/2010	OVERFLOWING		1.0	
	06/23/2010	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	CLOGGED LINE ON MWD SIDE, CLEANED OUT	4.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
, -, -	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	STATION BACKING UP	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
06/28/2010	LIGHT/ALARM	REPLACED PUMP	3.5	YES
06/28/2010	LIGHT/ALARM	UNDER PROJECT WARRANTY. CONTACTED THE CONTRACTOR.	1.0	
	VERIFY CONNECTION	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
06/30/2010	OVERFLOWING	NO POWER AT STATION	1.0	
06/30/2010	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED A BROKEN PIG TAIL	2.0	
	OVERFLOWING	REPLACED PUMP	1.0	
07/02/2010	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	2.0	
07/02/2010	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.5	
	OVERFLOWING	REPLACED PUMP DUE TO BAD ON/OFF SWITCH	2.5	
		REPLACED PUMP IN ALARM STAGE. STILL UNDER		
07/02/2010	OVERFLOWING	WARRANTY. BILLED CONTRACTOR	1.0	
07/02/2010	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP AND CABLE	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	1123
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	NO POWER AT STATION	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	COMMODES NOT FLUSHING PROPERLY	CUSTOMER'S 4" LINE BLOCKED	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	NO POWER AT STATION	1.0	
	LIGHT/ALARM	NO POWER AT STATION	1.0	
	OVERFLOWING	REPLACED A BROKEN PIG TAIL	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	i ·			
	LIGHT/ALARM	REPLACED PUMP AND CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD ON/OFF SWITCH	1.5	
	BREAKERS KICKING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP, CABLE & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP NOT WORKING	REPLACED PUMP AND CABLE	2.5	
	LIGHT/ALARM	REPLACED PUMP AND CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL.	5.0	YES
	LIGHT/ALARM	BREAKERS KNOCKED ON CUSTOMER'S SIDE	3.0	YES
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	2.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP AND CABLE	1.5	
	OVERFLOWING	REPLACED PUMP AND CABLE	2.0	
	OVERFLOWING	NO POWER AT STATION	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
07/27/2010	LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL.	1.0	
07/27/2010	OVERFLOWING	STATION CHECKED OKAY UPON ARRIVAL.	1.0	

07/28/2010 L 07/29/2010 P 07/29/2010 L 07/29/2010 L 07/29/2010 L	LIGHT/ALARM LIGHT/ALARM PUMP NOT WORKING	REPLACED PUMP	(HOURS) 3.0	HOURS YES
07/28/2010 L 07/29/2010 P 07/29/2010 L 07/29/2010 L 07/29/2010 L	LIGHT/ALARM			
07/29/2010 P 07/29/2010 L 07/29/2010 L 07/29/2010 L	,	STATION CHECKED OKAY UPON ARRIVAL.	0.5	
07/29/2010 L 07/29/2010 L	FOIVIF INOT WORKING	NO POWER AT STATION	1.0	
07/29/2010 L	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
07/20/2010	LIGHT/ALARM	REPLACED PUMP	4.5	YES
01/23/2010 F	LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL.	0.5	
07/30/2010 P	PUMP NOT WORKING	BAD BREAKER ON CUSTOMER SIDE	1.0	
07/30/2010	OVERFLOWING	REPLACED PUMP	2.0	
08/02/2010 L	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
08/02/2010 C	OVERFLOWING	REPLACED PUMP AND CABLE	2.0	
	LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL.	1.0	<u> </u>
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	<u> </u>
	LIGHT/ALARM	REPLACED PUMP	1.5	<u> </u>
	LIGHT/ALARM	REPLACED PUMP	1.5	<u> </u>
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP DUE TO GREASE ISSUE	1.0	
	OVERFLOWING	NO POWER AT STATION	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD ON/OFF SWITCH	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	1.0	
	LIGHT/ALARM	RESET PUMP IN ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP NOT WORKING	CLOGGED LINE ON MWD SIDE, CLEANED OUT	2.5 3.0	VEC
	OVERFLOWING LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD ON/OFF SWITCH	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD ON/OTT SWITCH	2.0	YES
	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE ISSUE	1.0	ILS
08/03/2010 L	LIGITI/ALANIVI	UNDER PROJECT WARRANTY. CONTACTED THE	1.0	
	LIGHT/ALARM	CONTRACTOR.	1.0	
08/10/2010	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	2.0	YES
	OVERFLOWING	REPLACED PUMP AND CABLE	5.0	YES
08/12/2010 L		REPLACED PUMP	1.0	
— · · · · ·	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	REPLACED PUMP	4.0	YES
08/13/2010 L		REPLACED PUMP	1.0	
08/13/2010 L		REPLACED PUMP STUCK IN ALARM STAGE	1.0	VE-2
	OVERFLOWING	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP DUE TO GREASE ISSUE	2.0	
	PUMP NOT WORKING	STATION CHECKED OKAY UPON ARRIVAL.	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	2.5	YES
08/18/2010 L		REPLACED PUMP	3.0	YES
08/18/2010 L		REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	RESET PUMP IN ALARM STAGE	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	VEC
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	BREAKERS KNOCKED ON CUSTOMER'S SIDE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL.	0.5	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP AND CABLE	1.0	
U0//3//U11	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE REPLACED PUMP STUCK IN ALARM STAGE	1.0 1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
00/27/2010	LICUT/ALADAA	DEDI ACED DUAAD	(HOURS)	HOURS
08/27/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
08/27/2010 08/27/2010	LIGHT/ALARM OVERFLOWING	REPLACED PUMP REPLACED PUMP & EQD END	1.0 1.0	
08/27/2010	PUMP NOT WORKING	-	1.0	
08/27/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR REPLACED PUMP DUE TO GREASE ISSUE		
08/27/2010		RESET PUMP IN ALARM STAGE	1.0 2.0	VEC
	LIGHT/ALARM			YES
08/27/2010	LIGHT/ALARM	RESET PUMP IN ALARM STAGE CUSTOMER HAS DAMAGED STATION AND MUST PAY	2.0	YES
08/30/2010	STATION BACKING UP	FOR DAMAGES BEFORE RECONNECTION.	1.0	
08/30/2010	OVERFLOWING	NO POWER AT STATION	1.0	
08/30/2010	ODOR	REPLACED PUMP	1.0	
08/30/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
08/30/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
08/30/2010	LIGHT/ALARM	REPLACED PUMP	3.0	YES
08/30/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
08/30/2010	PUMP NOT WORKING	UNDER PROJECT WARRANTY. CONTACTED THE	1.0	
		CONTRACTOR.		
08/31/2010	OVERFLOWING	NO POWER AT STATION	1.0	
08/31/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
08/31/2010	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
09/01/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
09/01/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
09/03/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
09/03/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
09/03/2010	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	2.5	YES
09/03/2010	LIGHT/ALARM	RESET PUMP	1.0	
09/07/2010	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
09/07/2010	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
09/08/2010	LIGHT/ALARM	NO POWER AT STATION	1.5	YES
09/08/2010	OVERFLOWING	REPLACED PUMP	1.0	
09/08/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
09/09/2010	OVERFLOWING	NO POWER AT STATION	1.0	
09/09/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
09/10/2010	ODOR	REPLACED PUMP	1.0	
09/10/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
09/13/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
09/13/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE ISSUE	1.0	
	LIGHT/ALARM	REPLACED PUMP		
09/14/2010	- ,		1.0	
	PUMP NOT WORKING	STATION CHECKED OKAY UPON ARRIVAL.	1.0	
		CLOGGED LINE ON MWD SIDE, CLEANED OUT	7.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	STATION CHECKED OKAY UPON ARRIVAL.	1.0	
09/16/2010	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE ISSUE	1.0	
09/20/2010	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE ISSUE	3.0	YES
09/20/2010	PUMP NOT WORKING	STATION CHECKED OKAY UPON ARRIVAL.	1.0	
09/21/2010	OVERFLOWING	NO POWER AT STATION	3.0	YES
09/21/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
09/24/2010	LIGHT/ALARM	RESET PUMP	1.0	
09/25/2010	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/25/2010	OVERFLOWING	REPLACED PUMP AND CABLE	3.0	YES
09/28/2010	LIGHT/ALARM	REPLACED PUMP AND CABLE	5.0	YES
09/29/2010	LIGHT/ALARM	NO POWER AT STATION	1.0	
09/29/2010	LIGHT/ALARM	NO POWER AT STATION	0.5	
09/30/2010	PUMP NOT WORKING	REPLACED PUMP DUE TO BREAKERS BEING TRIPPED	1.0	
09/30/2010	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE ISSUE	1.0	
10/01/2010	OVERFLOWING	REPLACED PUMP	2.0	YES
10/01/2010	LIGHT/ALARM	REPLACED PUMP	1.0	11.3
10/01/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
10/01/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
10/04/2010	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	REPLACED PUMP AND CABLE	1.0	
10/05/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
10/05/2010	ODOR	UNDER PROJECT WARRANTY. CONTACTED THE CONTRACTOR.	1.0	
10/06/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
10/06/2010	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE ISSUE	1.0	
10/08/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
10/12/2010	ODOR	REPLACED PUMP	1.0	
10/12/2010	LIGHT/ALARM	REPLACED PUMP AND LEAKING PIG TAIL	1.0	
10/13/2010	OVERFLOWING	REPLACED PUMP AND CABLE	1.0	
10/14/2010	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.5	YES
10/15/2010	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
10/15/2010	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	3.5	YES
40/45/2040	LICUT/ALABA	REPLACED PUMP. CONTRACTOR LEFT OFF A PRESSURE	2.0	VEC
10/15/2010	LIGHT/ALARM	CONNECT. BILLED CONTRACTOR	3.0	YES
10/16/2010	OVERFLOWING	NO POWER AT STATION	4.0	YES
	OVERFLOWING	BREAKERS KNOCKED ON CUSTOMER'S SIDE	0.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP DUE TO GREASE ISSUE	1.0	
	OVERFLOWING	REPLACED PUMP AND CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	5.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	123
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	STATION BACKING UP	REPLACED PUMP & CONTROL BOARD	2.0	123
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	TLS
	OVERFLOWING	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	REPLACED PUMP STUCK IN ALARM STAGE	1.0	
-, -,	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	2.0	YES
	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	1.0	TES
	i ·	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR		
	LIGHT/ALARM		1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0	
		REPLACED PUMP	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	ODOR	REPLACED PUMP DUE TO BAD STATOR	1.0	
	PUMP NOT WORKING	REPLACED PUMP DUE TO GREASE ISSUE	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	NO POWER AT STATION	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	ODOR	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP AND CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED BAD BREAKER ON MWD SIDE	3.0	YES
	LIGHT/ALARM	NO POWER AT STATION	1.0	
11/15/2010	OVERFLOWING	REPLACED PUMP	1.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
11/16/2010	COMMODES NOT FLUSHING PROPERLY	CUSTOMER'S 4" LINE BLOCKED	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP AND CABLE	2.0	
	OVERFLOWING	REPLACED PUMP DUE TO BAD ON/OFF SWITCH	1.0	
	OVERFLOWING	NO POWER AT STATION	1.0	
	OVERFLOWING	REPLACED PUMP	1.5	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	TES
	ODOR	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.5	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	PUMP NOT WORKING	REPLACED PUMP DUE TO BAD STATOR	1.0	
11/24/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
11/24/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
11/24/2010	LIGHT/ALARM	REPLACED PUMP AND CABLE	1.0	
11/25/2010	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPAIRED PRESSURE CONNECT	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP AND CABLE	1.5	
	OVERFLOWING	REPLACED PUMP DUE TO BAD ON/OFF SWITCH	1.0	
	OVERFLOWING	REPLACED PUMP	2.0	1/50
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0	
	LIGHT/ALAKIVI	REPLACED PUMP, REPAIRED CABLE, VALVE &	1.0	
12/07/2010	OVERFLOWING	REPLACED CONTROL BOARD	1.5	
12/08/2010	STATION BACKING UP	CUSTOMER'S 4" LINE BLOCKED	0.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.5	
12/10/2010	PUMP NOT WORKING	STATION CHECKED OKAY UPON ARRIVAL.	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	1.0	\
	LIGHT/ALARM	REPLACED PUMP STUCK IN ALARM STAGE	3.0	YES
	LIGHT/ALARM	NO POWER AT STATION	1.0	
	STATION BACKING UP	REPLACED PUMP & EQD END REPLACED PUMP STUCK IN ALARM STAGE	1.0 3.0	YES
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0	153
	OVERFLOWING	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	ILJ
	OVERFLOWING	REPLACED PUMP	1.0	
		REPLACED PUMP	2.0	
	COMMODES NOT FLUSHING PROPERLY	CUSTOMER'S 4" LINE BLOCKED	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
12/30/2010	LIGHT/ALARM	REPLACED PUMP	1.0	
,,	'			

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
_ · ·	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	PUMP RUNNING CONSTANTLY	REPLACED PUMP	1.0	
01/06/2011	OVERFLOWING	REPAIRED SERVICE LINE LEAK OUTSIDE OF BARREL	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	CLEANED CHECK VALVE	2.0	YES
	STATION BACKING UP	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	\/F6
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.5	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	1/50
	LIGHT/ALARM	REPLACED PUMP & CABLE	5.0	YES
01/25/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
01/25/2011	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
01/26/2011	OVERFLOWING	REPAIRED BLOCKED LINE ON MWD SIDE	0.5	
01/27/2011	OVERFLOWING	REPLACED PUMP	3.0	YES
01/27/2011	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
01/28/2011	LIGHT/ALARM	REPLACED PUMP	2.5	YES
01/29/2011	BREAKER BOX MAKING NOISE	POWER ISSUE ON CUSTOMER'S SIDE	3.0	YES
01/29/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
01/31/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
01/31/2011	LIGHT/ALARM	REPLACED PUMP	2.0	
01/31/2011	OVERFLOWING	REPLACED PUMP	1.0	
02/01/2011	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE PROBLEM	1.0	
02/04/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
02/04/2011	OVERFLOWING	REPLACED PUMP	1.0	
02/04/2011	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	0.5	
02/07/2011	OVERFLOWING	REPLACED PUMP	2.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	BREAKER ISSUE	1.0	
	LIGHT/ALARM	REPLACED PUMP & SLIDER VALVE	1.0	
	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	5.0	YES
02/14/2011	OVERFLOWING	BREAKER ISSUE	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	11.5
· · · ·	OVERFLOWING	REPLACED PUMP	1.0	
02/14/2011	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
02/14/2011	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
02/14/2011	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
	•	SIDE		1
02/15/2011	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
02/15/2011	OVERFLOWING	REPLACED PUMP	1.0	
02/15/2011	OVERFLOWING PUMP NOT WORKING	REPLACED PUMP STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	0.5	
02/15/2011	LIGHT/ALARM	SIDE REPLACED PUMP	1.0	
02/10/2011	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	<u> </u>
02/17/2011	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
02/18/2011	LIGHT/ALARM	SIDE REPLACED PUMP	1.0	
02/18/2011	OVERFLOWING	REPLACED PUMP	1.0	
02/22/2011	ODOR	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	0.5	
		SIDE		<u> </u>
02/25/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
02/25/2011	OVERFLOWING	REPLACED PUMP & CABLE	2.0	YES
02/25/2011	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
02/28/2011	LIGHT/ALARM	BREAKER ISSUE	1.0	
02/28/2011	PUMP NOT WORKING	REPLACED PUMP	2.0	1

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
02/28/2011	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
02/28/2011	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
03/01/2011	PUMP NOT WORKING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
03/03/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
03/04/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
03/04/2011	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
,-,-	PUMP NOT WORKING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
03/08/2011	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	2.0	
	·	SIDE		
03/10/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	0.5	
03/17/2011 03/18/2011	OVERFLOWING OVERFLOWING	REPLACED PUMP REPLACED PUMP	1.5 1.0	
	OVERFLOWING			
	OVERFLOWING	REPLACED PUMP REPLACED PUMP & CABLE	1.0 1.0	
	STATION BACKING UP	POWER ISSUE ON CUSTOMER'S SIDE	3.0	YES
03/21/2011	STATION BACKING UP	REPLACED PUMP DUE TO GREASE PROBLEM	1.0	1123
	STATION BACKING UP	REPLACED PUMP, CONTROL BOARD & CABLE	2.0	
03/21/2011	OVERFLOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
03/21/2011	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
03/22/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
03/22/2011	OVERFLOWING	REPLACED PUMP	1.0	
03/22/2011	OVERFLOWING	REPLACED PUMP	1.0	
03/23/2011	OVERFLOWING	REPLACED PUMP	2.0	
03/23/2011	OVERFLOWING	REPLACED PUMP	2.0	
03/23/2011	PUMP RUNNING CONSTANTLY	REPLACED PUMP	1.0	
03/23/2011	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
03/28/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
03/28/2011	PUMP NOT WORKING	REPLACED PUMP STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
03/28/2011	ODOR	SIDE STATION CHECKED OKAY, PROBLEM ON CUSTOMER'S	1.0	
03/29/2011	STATION BACKING UP	SIDE	1.0	
03/30/2011	PUMP NOT WORKING	REPLACED PUMP	1.0	
03/31/2011	OVERFLOWING	REPLACED PUMP	1.0	
04/01/2011	LIGHT/ALARM	REPLACED PUMP	2.5	
04/04/2011	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	PUMP NOT WORKING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
04/04/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
04/04/2011	OVERFLOWING	REPLACED PUMP	1.0	
04/04/2011	OVERFLOWING	REPLACED PUMP	1.0	
04/04/2011	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
04/06/2011 04/07/2011	ODOR LIGHT/ALARM	REPLACED PUMP	1.0 1.0	
04/07/2011	LIGHT/ALARM PUMP NOT WORKING	REPLACED PUMP REPLACED PUMP	5.5	YES
04/07/2011	LIGHT/ALARM	REPLACED PUMP	1.0	163
04/08/2011	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0	
04/11/2011	LIGHT/ALARM	REPLACED PUMP	1.5	
04/11/2011	OVERFLOWING	REPLACED PUMP	2.0	YES
04/13/2011	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE PROBLEM	2.0	123

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0 1.0	
	BLOCKED LINE	REPAIRED BLOCKED LINE ON MWD SIDE	5.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.5	YES
	LIGHT/ALARM	REPLACED PUMP	2.5	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	ODOR	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
04/22/2011	LIGHT/ALARM	REPLACED PUMP	1.5	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
04/26/2011	STATION BACKING UP	SEWER LINE BLOCKED ON CUSTOMER'S SIDE	1.0	
04/27/2011	LIGHT/ALARM	REPLACED PUMP	1.5	
04/28/2011	PUMP RUNNING CONSTANTLY	REPLACED PUMP	1.0	
04/28/2011	STATION BACKING UP	REPLACED PUMP	1.0	
04/28/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
04/28/2011	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
04/29/2011	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
04/29/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
04/29/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	3.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/03/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
05/03/2011	PUMP RUNNING CONSTANTLY	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
05/04/2011	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
05/05/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
05/05/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.5	
, ,	OVERFLOWING ODOR	REPLACED PUMP & CABLE STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	VEC
,,	ODOR	SIDE	4.0	YES
	OVERFLOWING	REPLACED PUMP, CONTROL BOARD & CABLE	3.0	YES
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/10/2011	OVERFLOWING	REPLACED PUMP	1.0	
05/10/2011	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
05/20/2011	OVERFLOWING	REPLACED PUMP	1.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
05/20/2011	LIGHT/ALARM	REPLACED PUMP & CABLE	2.5	
05/20/2011	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	3.5	YES
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	OVERFLOWING	BREAKER ISSUE	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
, -, -	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
05/26/2011	OVERFLOWING	REPLACED PUMP, CONTROL BOARD & CABLE	1.5	
05/26/2011	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	ODOR	REPLACED PUMP	1.0	
05/27/2011	OVERFLOWING	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
, -, -	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	3.5	YES
05/28/2011	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & VENT CAP	3.0	YES
05/29/2011	LIGHT/ALARM	REPLACED PUMP, CABLE, CONTROL BOARD & VENT CAP	6.0	YES
05/30/2011	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	123
	OVERFLOWING	REPLACED PUMP	1.0	
	PUMP RUNNING CONSTANTLY	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
06/02/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
06/02/2011	PUMP NOT WORKING	REPLACED PUMP	3.0	YES
06/02/2011	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
06/03/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/03/2011	OVERFLOWING	REPLACED PUMP	1.0	
06/03/2011	OVERFLOWING	REPLACED PUMP	1.0	
06/03/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/03/2011	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE PROBLEM	1.0	
06/06/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
06/06/2011	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/06/2011	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	1.0	
06/06/2011	COMMODE LOSING WATER	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
06/07/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	1
	LIGHT/ALARM	REPLACED PUMP	1.0	1
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
06/09/2011	OVERFLOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
		SIDE STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S		
06/09/2011	OVERFLOWING	SIDE	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
06/09/2011	ODOR	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
06/13/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
06/13/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
06/14/2011	LIGHT/ALARM	INSTALLED PRESSURE CONNECT IN SERVICE LINE	1.0	
06/14/2011	OVERFLOWING	REPLACED PUMP	1.0	
06/14/2011	OVERFLOWING	REPLACED PUMP	1.0	
06/15/2011	OVERFLOWING	BREAKER ISSUE	1.0	
06/15/2011	OVERFLOWING	BREAKER ISSUE	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE PROBLEM	1.0	
06/15/2011	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE PROBLEM	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
06/16/2011	PUMP RUNNING CONSTANTLY	REPLACED PUMP & EQD STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
	STATION BACKING UP	SIDE	1.0	
06/17/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/18/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/18/2011	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	3.5	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/20/2011	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	0.5	
06/20/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
06/20/2011	OVERFLOWING	REPLACED PUMP & CABLE STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.5	
06/20/2011	STATION BACKING UP	SIDE	0.5	
06/21/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
06/21/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
06/21/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
06/21/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
06/21/2011	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
06/22/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
06/22/2011	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
06/23/2011	PUMP NOT WORKING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
<u> </u>	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	SEWER LINE UNDER HOUSE CAME LOOSE	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
06/24/2011	OVERFLOWING	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
<u> </u>	STATION BACKING UP	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	ODOR	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
<u> </u>	OVERFLOWING	REPLACED PUMP & CABLE	3.0	YES
	OVERFLOWING	REPLACED PUMP & CABLE	2.0	123
	OVERFLOWING	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.5	
	STATION BACKING UP	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	123
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	ODOR	REPLACED PUMP & CONTROL BOARD	2.5	TES
07/01/2011		INTI FACED FOIRIF & CONTROL DOARD	2.3	1
<u> </u>	PUMP RUNNING CONSTANTLY	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
07/03/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	123
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
		STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S		
07/05/2011	STATION BACKING UP	SIDE	1.0	
07/06/2011	OVERFLOWING	REPLACED PUMP DUE TO GREASE PROBLEM	1.0	
07/06/2011	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	2.0	
07/06/2011	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	4.0	YES
07/00/2011	LIGITI/ALAKIVI	SIDE	4.0	ILS
07/06/2011	OVERFLOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
		SIDE		
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.5	YES
	LIGHT/ALARM	REPLACED PUMP	2.5	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	2.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
07/13/2011	LIGHT/ALARM	REPLACED PUMP STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	-
07/13/2011	LIGHT/ALARM	SIDE	3.0	YES
07/13/2011	OVERFLOWING	REPLACED PUMP & EQD	1.0	
07/14/2011	PUMP NOT WORKING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
07/15/2011	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	PUMP NOT WORKING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	2.0	
	110117/414884	SIDE		1/50
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	-
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
/ / /-				VEC
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP		TES
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE REPLACED PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP NOT WORKING	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD REPLACED PUMP & VENT CAP	3.0	YES
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	<u> </u>
	OVERFLOWING	REPLACED PUMP	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	5.0	
	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	t

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
07/28/2011	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	2.0	
	PUMP RUNNING CONSTANTLY	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
07/29/2011	OVERFLOWING	REPLACED PUMP	3.3	YES
07/29/2011	CUSTOMER BUILDING NEW HOUSE ON	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
07/29/2011	PROPERTY	SIDE	1.0	
07/31/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
08/01/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/01/2011	OVERFLOWING	REPLACED PUMP	1.0	
08/01/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/02/2011	ODOR	REPLACED PUMP	1.0	
08/02/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/02/2011	OVERFLOWING	REPLACED PUMP	1.0	
08/02/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/02/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/02/2011	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
08/03/2011	ODOR	POWER ISSUE ON CUSTOMER'S SIDE	0.5	
08/03/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	PUMP NOT WORKING	REPLACED PUMP	1.0	
	PUMP NOT WORKING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	-
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	3.0	YES
	OVERFLOWING	BREAKER ISSUE	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP & CABLE	1.0	1123
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
08/10/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/10/2011	LIGITI/ALARIVI	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
08/10/2011	LIGHT/ALARM	SIDE	1.0	
08/11/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/11/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/11/2011	OVERFLOWING	REPLACED PUMP	1.0	
08/11/2011	OVERFLOWING	REPLACED PUMP	1.0	
00/44/0044	OLUEDEL OLUMNIC	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S		
08/11/2011	OVERFLOWING	SIDE	1.0	
08/11/2011	PUMP NOT WORKING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
08/12/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/12/2011	PUMP NOT WORKING	REPLACED PUMP	1.0	
08/12/2011	OVERFLOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.5	
08/14/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
08/15/2011	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
08/15/2011	PUMP NOT WORKING	REPLACED PUMP	1.0	
08/15/2011	OVERFLOWING	REPLACED PUMP	1.0	
08/15/2011	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE PROBLEM	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
08/16/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
08/17/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/17/2011	OVERFLOWING	REPLACED PUMP	1.0	
	:		•	

08/17/2011 0VERLOWING REPLACED PUMP 1.0	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
SIDE 1.0	08/17/2011	OVERFLOWING		1.0	
10	08/17/2011	ODOR		1.0	
09/19/2011 LIGHT/ALARM		LIGHT/ALARM	REPLACED PUMP	1.0	
10.5913/10.11 LIGHT/ALARM					
08/13/2011 LIGHT ALARM REPLACED PUMP 1.0					
08/27/2011 IJOHT ALARM REPLACED PUMP 1.0 08/27/2011 IJOHT ALARM REPLACED PUMP 1.0 08/27/2011 IJOHT ALARM REPLACED PUMP 1.0 08/27/2011 OVERHOWING REPLACED PUMP 1.0 08/27/2011 OVERHOWING REPLACED PUMP 1.0 08/27/2011 OVERHOWING REPLACED PUMP & CABLE 2.0 YES 08/27/2011 OVERHOWING REPLACED PUMP & CABLE 2.0 YES 08/27/2011 OVERHOWING REPLACED PUMP & CABLE 1.0 08/27/2011 IJOHT ALARM REPLACED PUMP & CABLE 1.0 08/27/2011 IJOHT ALARM REPLACED PUMP & CABLE 1.0 08/27/2011 IJOHT ALARM REPLACED PUMP & 1.0 08/27/201		•	*		
08/27/2011 LIGHT/ALARM			*		
08/22/2011 UGHT/ALARM					
08/27/2011 OVERFLOWING REPLACED PUMP 1.0		•	*		
08/22/2011 OVERFLOWING			*		
08/23/2011 USHT/ALARM					
08/23/2011 OVERLOWING					YES
08/23/2011 UPENFLOWING REPLACED PUMP 1.0					
10,000					
SIDE		PUMP NOT WORKING	REPLACED PUMP & CABLE	1.0	
	08/23/2011	COMMODE NOT TIED TO SYSTEM		1.0	
	08/24/2011	LIGHT/ALARM		1.0	
08/24/2011 UGHT/ALARM					
S02/2/2011 LIGHT/ALARM					
08/25/2011 UIGHT/ALARM		•	REPLACED PUMP		
08/25/2011 UIGHT/ALARM		LIGHT/ALARM	*		
SIDE 1.0					
	08/25/2011	LIGHT/ALARM		1.0	
08/26/2011 UGHT/ALARM	08/26/2011	LIGHT/ALARM		1.0	
08/26/2011 ODOR			*		
18/28/2011 IJGHT/ALARM		·	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	-	
08/28/2011 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/29/2011 STATION BACKING UP BREAKER ISSUE 1.0 0 08/29/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/29/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/29/2011 LIGHT/ALARM REPLACED PUMP 0.5 08/29/2011 LIGHT/ALARM REPLACED PUMP 1.5 08/29/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/30/2011 LIGHT/ALARM POWER ISSUE ON CUSTOMER'S SIDE 1.0 08/30/2011 LIGHT/ALARM POWER ISSUE ON CUSTOMER'S SIDE 1.0 08/30/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/31/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/01/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/01/2011	08/28/2011	LIGHT/ALARM		3.0	YES
08/29/2011 STATION BACKING UP BREAKER ISSUE 1.0		•			
08/29/2011 LIGHT/ALARM					
08/29/2011 LIGHT/ALARM REPLACED PUMP 0.5					
08/29/2011 LIGHT/ALARM		•	REPLACED PUMP	1.0	
08/29/2011 LIGHT/ALARM	08/29/2011	OVERFLOWING	REPLACED PUMP	0.5	
08/29/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/29/2011 OVERELOWING REPLACED PUMP 1.0 08/30/2011 LIGHT/ALARM POWER ISSUE ON CUSTOMER'S SIDE 1.0 08/30/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/30/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/31/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/01/2011 DOR REPLACED PUMP 1.0 09/01/2011 DOR REPLACED PUMP 1.0 09/01/2011 PUMP RUNNING CONSTANTLY REPLACED PUMP 1.0 09/01/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 5.0 YES 09/02/2011 STATION BACKING UP REPLACED PUMP 1.0 PUMP RUNNING CONSTANTLY STATION CHECKED DUMP 1.0 PUMP RUNNING CONSTANTLY YES 09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 </td <td></td> <td>LIGHT/ALARM</td> <td>REPLACED PUMP</td> <td>1.5</td> <td></td>		LIGHT/ALARM	REPLACED PUMP	1.5	
08/29/2011 OVERFLOWING REPLACED PUMP 1.0 08/30/2011 LIGHT/ALARM POWER ISSUE ON CUSTOMER'S SIDE 1.0 08/30/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/30/2011 LIGHT/ALARM REPLACED PUMP 1.5 08/31/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/01/2011 DODR REPLACED PUMP 1.0 09/01/2011 PUMP RUNNING CONSTANTLY REPLACED PUMP 1.0 09/01/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/02/2011 STATION BACKING UP REPLACED PUMP 1.0 09/02/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP <td>08/29/2011</td> <td>LIGHT/ALARM</td> <td>REPLACED PUMP</td> <td>1.0</td> <td></td>	08/29/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
08/30/2011 LIGHT/ALARM POWER ISSUE ON CUSTOMER'S SIDE 1.0 08/30/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/30/2011 LIGHT/ALARM REPLACED PUMP 1.5 08/31/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/01/2011 DOR REPLACED PUMP 1.0 09/01/2011 PUMP RUNNING CONSTANTLY REPLACED PUMP 1.0 09/01/2011 ILGHT/ALARM REPLACED PUMP 1.0 09/02/2011 STATION BACKING UP REPLACED PUMP 1.0 09/02/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD <td< td=""><td></td><td>LIGHT/ALARM</td><td>REPLACED PUMP</td><td>1.0</td><td></td></td<>		LIGHT/ALARM	REPLACED PUMP	1.0	
08/30/2011 LIGHT/ALARM REPLACED PUMP 1.0 08/30/2011 LIGHT/ALARM REPLACED PUMP 1.5 08/31/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/01/2011 DOR REPLACED PUMP 1.0 09/01/2011 PUMP RUNNING CONSTANTLY REPLACED PUMP 1.0 09/01/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 5.0 YES 09/02/2011 STATION BACKING UP REPLACED PUMP 1.0 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 YES 09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 PUMP RUNNING CONSTANTLY STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 3.0 YES 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP & D.O 1.0				1.0	
08/30/2011 LIGHT/ALARM REPLACED PUMP 1.5 08/31/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/01/2011 DODG REPLACED PUMP 1.0 09/01/2011 PUMP RUNNING CONSTANTLY REPLACED PUMP 1.0 09/01/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 5.0 YES 09/02/2011 STATION BACKING UP REPLACED PUMP 1.0 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 YES 09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 PUMP 09/07/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 PUMP 09/07/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 PUMP 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 <t< td=""><td></td><td></td><td></td><td></td><td></td></t<>					
08/31/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/01/2011 ODOR REPLACED PUMP 1.0 09/01/2011 PUMP RUNNING CONSTANTLY REPLACED PUMP 1.0 09/01/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 5.0 YES 09/02/2011 STATION BACKING UP REPLACED PUMP 1.0 1.0 09/02/2011 LIGHT/ALARM REPLACED PUMP 1.0 YES 09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 PUMP RUNNING CONSTANTLY STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 3.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 <td></td> <td></td> <td></td> <td></td> <td></td>					
09/01/2011 ODOR REPLACED PUMP 1.0 09/01/2011 PUMP RUNNING CONSTANTLY REPLACED PUMP 1.0 09/01/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 5.0 YES 09/02/2011 STATION BACKING UP REPLACED PUMP 1.0		•	*		
09/01/2011 PUMP RUNNING CONSTANTLY REPLACED PUMP 1.0 09/01/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 5.0 YES 09/02/2011 STATION BACKING UP REPLACED PUMP 1.0 1.0 09/02/2011 LIGHT/ALARM REPLACED PUMP 1.0 YES 09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 PUMP RUNNING CONSTANTLY STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 3.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 ID 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 ID 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 ID 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 ID 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 ID 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 ID 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 ID 09/09/2011 LIGH					
09/01/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 5.0 YES 09/02/2011 STATION BACKING UP REPLACED PUMP 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 PUMP RUNNING CONSTANTLY STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 3.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/10/2011 LIGHT/ALARM R			*		
09/02/2011 STATION BACKING UP REPLACED PUMP 1.0 09/02/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 PUMP RUNNING CONSTANTLY STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 3.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/10/2011 DVERFLOWING REPLACED PUMP 1.0 1.0 09/10/2011 LIGHT/ALARM R			*		VEC
09/02/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 PUMP RUNNING CONSTANTLY STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 3.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/10/2011 LIGHT/ALARM		·			152
09/05/2011 LIGHT/ALARM REPLACED PUMP 4.0 YES 09/05/2011 PUMP RUNNING CONSTANTLY STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 3.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 1.0 09/10/2011					
09/05/2011 PUMP RUNNING CONSTANTLY STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 3.0 YES 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0					VES
09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 OVERFLOWING REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0			STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S		
09/06/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/06/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 OVERFLOWING REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0	09/06/2011	LIGHT/ALARM		1.0	
09/06/2011 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 OVERFLOWING REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0					
09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 OVERFLOWING REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0		·			
09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 OVERFLOWING REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0		·			
09/07/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 OVERFLOWING REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0					
09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 OVERFLOWING REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0					
09/08/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 OVERFLOWING REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0		•			
09/09/2011 LIGHT/ALARM REPLACED PUMP 1.0 09/10/2011 OVERFLOWING REPLACED PUMP 1.0 09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0			REPLACED PUMP		
09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0			REPLACED PUMP	1.0	
			REPLACED PUMP	1.0	
09/10/2011 LIGHT/ALARM REPLACED PUMP 1.0		•	*		
	09/10/2011	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
09/10/2011	LIGHT/ALARM	REPLACED PUMP	1.0	1100110
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/12/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
09/13/2011	OVERFLOWING	REPLACED PUMP	1.0	
09/13/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
09/13/2011	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
09/14/2011	ODOR	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	REPLACED PUMP & CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/22/2011	ODOR	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
09/22/2011	PUMP NOT WORKING	SIDE STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
00/24/2211	LICUT/ALADAA	SIDE DEPLACED BLIAD	5.0	\/FC
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
09/26/2011	OVERFLOWING	REPLACED PUMP	3.0	YES
09/26/2011	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
09/26/2011	ODOR	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
09/27/2011	OVERFLOWING	REPLACED BROKEN PIG TAIL ON OUTSIDE OF BARREL	1.0	
09/27/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
09/27/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	3.0	YES
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	0.5	
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
10/02/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	2.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	123
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
10/05/2011	LIGHT/ALADAA	SIDE REDI ACED DUMP	1.0	
10/05/2011	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	OVERFLOWING	REPLACED PUMP, CONTROL BOARD & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/10/2011	ODOR	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/11/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/11/2011	ODOR	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
10/12/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	3.0	YES
10/13/2011	OVERFLOWING	REPLACED PUMP	1.0	
	•			

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
10/13/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/13/2011	OVERFLOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	3.0	YES
10/15/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
10/17/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/17/2011	OVERFLOWING	REPLACED PUMP	1.0	
10/17/2011	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
10/17/2011	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
10/17/2011	ODOR	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
10/18/2011	OVERFLOWING	REPLACED PUMP	1.0	
10/18/2011	OVERFLOWING	REPLACED PUMP	3.0	YES
10/18/2011	LIGHT/ALARM	REPLACED PUMP, CABLE & EQD	1.5	
10/19/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/20/2011	LIGHT/ALARM	REPLACED PUMP	1.5	
10/20/2011	ODOR	REPLACED PUMP	1.5	
10/20/2011	OVERFLOWING	REPLACED PUMP	1.0	
10/21/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/21/2011	LIGHT/ALARM	REPLACED PUMP	1.0	†
10/21/2011	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
10/21/2011	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP		
10/24/2011 10/24/2011	,	REPLACED PUMP	1.0 1.0	
	LIGHT/ALARM		_	
10/24/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/24/2011	OVERFLOWING	REPLACED PUMP	1.0	
10/24/2011	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
10/25/2011	OVERFLOWING	REPLACED PUMP	1.0	
10/25/2011	OVERFLOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
10/26/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/26/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/26/2011	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
10/27/2011	OVERFLOWING	REPLACED PUMP	1.0	
10/27/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/27/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/27/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/31/2011	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
10/31/2011	PUMP NOT WORKING	REPLACED PUMP	1.0	
10/31/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
10/31/2011	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
11/01/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
11/01/2011	LIGHT/ALARM	REPLACED PUMP	1.0	1
11/01/2011	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	İ
11/02/2011	LIGHT/ALARM	REPLACED PUMP	3.0	YES
11/03/2011	PUMP NOT WORKING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
11/04/2011	PUMP NOT WORKING	REPLACED PUMP	1.0	
11/04/2011	LIGHT/ALARM	REPLACED PUMP	1.0	1
11/05/2011	LIGHT/ALARM	REPLACED PUMP	5.0	YES
11/07/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
11/07/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
11/07/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
11/07/2011	LIGHT/ALARM	REPLACED PUMP	1.0	İ
11/07/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
11/08/2011	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	OVERT LOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
11/08/2011	STATION BACKING UP	SIDE	1.0	
11/08/2011	PUMP NOT WORKING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
11/09/2011	OVERFLOWING	REPLACED PUMP	2.0	YES
11/09/2011	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
11/09/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
11/10/2011	PUMP NOT WORKING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
11/12/2011	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	0.5	+
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	SEAL FAILURE, RESET LIGHT	0.5	
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	1
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	1
	OVERFLOWING	REPLACED PUMP	3.0	YES
11/21/2011	OVERFLOWING	REPLACED PUMP	1.0	125
	LIGHT/ALARM	REPLACED PUMP	1.0	+
	LIGHT/ALARM	REPLACED PUMP	1.0	+
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	+
11/22/2011	OVERFLOWING	REPLACED PUMP, CONTROL BOARD & CABLE	1.0	+
	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	3.0	YES
		SIDE		1.20
	PUMP NOT WORKING	REPLACED MALE & FEMALE PLUG ENDS ON MOTOR	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
11/29/2011	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	_
12/07/2011	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	1.5	
12/08/2011	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
12/13/2011	LIGHT/ALARM	REPLACED PUMP	1.0	
12/14/2011	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
12/14/2011	OVERFLOWING	REPLACED PUMP, CABLE, BREAKER & CONTROL BOARD	2.0	
12/15/2011	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	1.0	†
	OVERFLOWING	REPLACED PUMP	1.0	†
	OVERFLOWING	REPLACED PUMP	1.0	+
	LIGHT/ALARM	REPLACED PUMP	1.0	+
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
12/17/2011	PUMP NOT WORKING	REPLACED PUMP	1.0	112
	OVERFLOWING	REPLACED PUMP	1.0	+
12/19/2011	OVERFLOWING	REPLACED PUMP	1.0	+
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
12/20/2011	OVERFLOWING	REPLACED PUMP & CABLE	2.0	ILJ
	LIGHT/ALARM	REPLACED PUMP & CABLE REPLACED PUMP, CABLE & VENT CAP	1.0	+
	LIGHT/ALARM	REPLACED PUMP, CABLE & VENT CAP	1.0	+
	LIGHT/ALARM	REPLACED PUMP, CABLE & EQD	1.0	+
12/21/2011		BREAKER ISSUE	3.0	YES
	OVERFLOWING		1.0	1 [2
	LIGHT/ALARM	REPLACED PUMP		+
12/29/2011	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/03/2012	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	0.5	
01/03/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP DUE TO STATOR	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	STATION BACKING UP	CLOGGED LINE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
	OVERFLOWING	REPLACE PUMP	4.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.5	<u> </u>
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	RESET BEAKERS	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	PUMP RUNNING CONTINUOUSLY	REPLACE PUMP	5.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	<u> </u>
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	OVERFLOWING	NO PROBLEM FOUND	1.0	<u> </u>
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
01/19/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
01/22/2012	OVERFLOWING	NO PROBLEM FOUND	2.0	YES
01/22/2012	OVERFLOWING	REPLACE PUMP	3.0	YES
01/23/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
01/23/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
01/23/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
01/24/2012	CLOGGED LINE	REPAIRED BLOCKED LINE	4.0	
01/24/2012	OVERFLOWING	REPLACE PUMP	1.0	
01/25/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
01/26/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
01/27/2012	OVERFLOWING	REPLACE PUMP	1.0	
01/27/2012	OVERFLOWING	REPLACE PUMP	2.0	
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	OVERFLOWING	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	RESET BEAKERS	3.0	YES
	LIGHT/ALARM	RESET BEAKERS	4.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	†
	LIGHT/ALARM	REPLACE PUMP	1.0	1
	LIGHT/ALARM	REPLACE PUMP	1.0	1
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP CABLE AND EQD	2.0	1
	OVERFLOWING	REPAIRED BROKEN PIG TAIL	2.0	1
	OVERFLOWING	REPLACE PUMP	1.0	1
	OVERFLOWING	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	OVERFLOWING	REPLACE PUMP	1.0	11.5
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	+
	LIGHT/ALARM	REPLACE PUMP	1.0	
	ODOR		1.0	
		NO PROBLEM FOUND		
	LIGHT/ALARM	REPLACE PUMP	1.0	+
	STATION BACKING UP	REPLACED PUMP & CABLE	2.0	VEC
0777077017	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	LICUT/ALADAA			
02/20/2012	LIGHT/ALARM LIGHT/ALARM	REPLACE PUMP REPLACE CONTROL BOARD	4.0 1.0	YES

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
02/22/2012	LIGHT/ALARM	REPLACE PUMP	(HOURS) 1.0	HOURS
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
<u> </u>	OVERFLOWING	REPLACE PUMP	2.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	PUMP NOT WORKING	REPLACED PUMP & CABLE	1.5	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.5	YES
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
03/04/2012	LIGHT/ALARM	BREAKER CHANGED	3.0	YES
03/04/2012	OVERFLOWING	NO PROBLEM FOUND	3.0	YES
03/05/2012	LIGHT/ALARM	BREAKER CHANGED	1.0	
03/05/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	STATION BACKING UP	CLOGGED LINE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	STATION BACKING UP	CLOGGED LINE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	OVERFLOWING	REPLACE PUMP	3.0	YES
	CLOGGED LINE	REPAIRED BLOCKED LINE	3.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED CABLE	1.5	
	OVERFLOWING	REPLACED PUMP & CABLE	1.5	
	OVERFLOWING	REPLACE PUMP	1.0	
	ODOR	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	YES
03/17/2012	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	YES
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.5	YES
	LIGHT/ALARM	BREAKER CHANGED	1.0	123
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP & VENT CAP	3.0	YES
<u> </u>	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.5	123
	STATION BACKING UP	RESET BEAKERS	0.5	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	OVERFLOWING	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	CHECK FOR ILLEGAL	REPLACED PUMP	1.0	
<u> </u>	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.5	
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
04/06/2012				

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
04/09/2012	LIGHT/ALARM	REPLACE PUMP	1.0	YES
04/09/2012	LIGHT/ALARM	REPLACE PUMP	1.5	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
04/11/2012	OVERFLOWING	REPLACE PUMP	1.5	
	LIGHT/ALARM	REPLACE PUMP	1.0	
04/12/2012	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	VEC
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP & CABLE REPLACE PUMP	3.0 1.0	YES
04/16/2012 04/16/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
04/10/2012	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
04/17/2012	LIGHT/ALARM	RESET BEAKERS	1.0	
04/18/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
04/19/2012	LIGHT/ALARM	REPLACE PUMP DUE TO STATOR	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
04/20/2012	OVERFLOWING	REPAIRED BROKEN PIG TAIL	1.5	
	LIGHT/ALARM	REPLACE PUMP	1.5	YES
04/21/2012	LIGHT/ALARM	REPLACE PUMP	3.0	YES
04/21/2012	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.5	YES
04/23/2012	ODOR	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
04/23/2012	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
04/24/2012	LIGHT/ALARM	REPLACE PUMP DUE TO STATOR	1.0 1.0	
04/25/2012 04/26/2012	LIGHT/ALARM LIGHT/ALARM	REPLACE PUMP REPLACE PUMP	1.0	
04/26/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
04/26/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
04/27/2012	LIGHT/ALARM	BREAKER CHANGED	3.0	YES
04/27/2012	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	123
04/28/2012	OVERFLOWING	NO PROBLEM FOUND	4.0	YES
04/28/2012	LIGHT/ALARM	REPLACE PUMP	4.0	YES
04/28/2012	LIGHT/ALARM	REPLACE PUMP	3.0	YES
04/29/2012	LIGHT/ALARM	REPLACE PUMP	2.5	YES
04/29/2012	LIGHT/ALARM	REPLACE PUMP	2.5	YES
04/30/2012	OVERFLOWING	CLOGGED LINE ON CUSTOMER'S SIDE	2.0	
04/30/2012	LIGHT/ALARM	REPLACE PUMP	1.5	YES
	OVERFLOWING	REPLACED PUMP, UNCLOGGED LINE	2.0	YES
05/01/2012		NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	2.0	YES
	LIGHT/ALARM	REPLACED PUMP, CABLE & VENT CAP	2.0	YES
	ODOR	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM OVERFLOWING	REPLACE PUMP	1.0 0.5	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE REPLACE PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP & VENT CAP	3.0	YES
	OVERFLOWING	RESET BEAKERS	1.0	i LJ
	OVERFLOWING	REPLACE PUMP	1.0	
05/04/2012	ODOR	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	2.0	YES
05/05/2012	OVERFLOWING	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	2.0	YES
	LEAK AT STATION	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	0.5	
05/07/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
05/07/2012	LIGHT/ALARM	REPLACE PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
05/07/2012	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
05/08/2012	ODOR	NO PROBLEM FOUND	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM OVERFLOWING	REPLACED PUMP & CABLE REPLACED PUMP & CABLE	1.0 1.0	
<u> </u>	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP & CABLE	3.0	YES
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
05/14/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
05/16/2012	OVERFLOWING	REPLACE PUMP	1.0	
05/16/2012	PUMP NOT WORKING	REPLACED PUMP & VENT CAP	1.0	
05/17/2012	ODOR	NO PROBLEM FOUND	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
_ · ·	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.5	
	STATION BACKING UP	CUSTOMER DISCONNECTED	0.5	
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	OVERFLOWING	RESET BEAKERS	1.0	
<u> </u>	LIGHT/ALARM	REPLACE PUMP	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	2.0	YES
	OVERFLOWING	REPLACE PUMP	3.0	YES
	LIGHT/ALARM LIGHT/ALARM	REPLACE PUMP REPLACE PUMP	2.0 1.0	
	STATION BACKING UP	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	ODOR	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
05/25/2012	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	3.0	YES
05/29/2012	OVERFLOWING	REPLACE PUMP	4.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
05/29/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	1.5	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	VEC
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0 1.0	
	LIGHT/ALARM STATION BACKING UP	REPLACE PUMP NO PROBLEM FOUND	0.5	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	OVERFLOWING	REPLACE PUMP	1.0	163
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	4.0	YES
	OVERFLOWING	REPLACE PUMP	1.0	
06/05/2012	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
06/06/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	4.5	YES
06/08/2012	OVERFLOWING	REPLACE PUMP	1.0	
06/08/2012	LIGHT/ALARM	REPLACE PUMP	1.0	YES

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
06/09/2012	OVERFLOWING	REPLACE PUMP	(HOURS) 1.0	HOURS
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	YES
06/11/2012	OVERFLOWING	REPLACE PUMP	1.0	123
	OVERFLOWING	REPLACE PUMP	1.0	
06/13/2012	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.5	
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
06/18/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
06/18/2012	LIGHT/ALARM	REPLACED PUMP & VENT CAP	3.0	YES
06/19/2012	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
06/20/2012	ODOR	NO PROBLEM FOUND	1.0	
06/21/2012	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
06/22/2012	OVERFLOWING	REPLACE PUMP	1.0	
06/22/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
06/25/2012	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
06/25/2012	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
06/25/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
06/26/2012	LIGHT/ALARM	REPLACE PUMP	4.0	YES
06/26/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
06/26/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
06/27/2012	ODOR	CLOGGED LINE ON CUSTOMER'S SIDE	0.5	
06/27/2012	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
06/27/2012	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
	STATION BACKING UP	NO PROBLEM FOUND	1.0	
06/28/2012	OVERFLOWING	REPLACE PUMP	1.0	
06/28/2012	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
07/02/2012	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
07/03/2012	ODOR	NO PROBLEM FOUND	0.5	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	0.5	
	OVERFLOWING	REPLACE PUMP	3.0	YES
	OVERFLOWING	REPLACE PUMP	1.0	
07/05/2012	OVERFLOWING	REPLACE PUMP	1.0	
07/05/2012	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	CLOGGED LINE ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPAIRED BROKEN PIG TAIL	1.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	
	LIGHT/ALARM	REPLACE PUMP	2.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	113
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
0110012012	LIST I / CLCINIVI	INO I OWER ON COSTONIER SSIDE	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
07/09/2012	STATION BACKING UP	NO PROBLEM FOUND	1.0	
07/09/2012	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP DUE TO STATOR	1.0	
	LIGHT/ALARM	REPLACE PUMP DUE TO STATOR	1.0	
	LIGHT/ALARM OVERFLOWING	REPLACED PUMP & CABLE REPLACED PUMP & CONTROL BOARD	1.0	
07/09/2012 07/10/2012	ODOR	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
07/10/2012	LIGHT/ALARM	NO PROBLEM FOUND	0.5	
07/11/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	3.0	YES
07/12/2012	OVERFLOWING	REPLACE PUMP	1.0	
07/12/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
07/12/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
	OVERFLOWING	REPLACED PUMP & VENT CAP	2.0	YES
	OVERFLOWING OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP REPLACE PUMP	1.5 1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
07/17/2012	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.5	YES
07/17/2012	LIGHT/ALARM	RESET BEAKERS	1.0	
07/18/2012	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	2.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	V/50
<u>·</u>	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	3.0	YES
	LIGHT/ALARM	REPLACE PUMP & VENT CAP	1.5	VEC
	OVERFLOWING LIGHT/ALARM	REPLACE PUMP REPLACE PUMP	4.0 3.0	YES YES
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	TES
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP, CABLE & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	OVERFLOWING	CUSTOMER DISCONNECTED	0.5	
07/21/2012	ODOR	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	5.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
07/23/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
07/23/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	OVERFLOWING	REPLACE PUMP	2.0	
07/24/2012	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
07/25/2012	LIGHT/ALARM	REPLACE PUMP	1.0	<u> </u>
07/25/2012	STATION BACKING UP	REPLACED PUMP, CABLE, CONTROL BOARD & VENT CAP	1.5	
07/25/2012	CUSTOMER CALL	REPLACED VENT CAP & CONTROL BOARD	0.5	ļ
07/26/2012	LIGHT/ALARM	NO PROBLEM FOUND	0.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
07/26/2012	LIGHT/ALARM	REPLACED PUMP & VENT CAP	3.0	
07/27/2012	PUMP NOT WORKING	NO POWER ON CUSTOMER'S SIDE	1.0	
07/27/2012	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	0.8	
07/28/2012	LIGHT/ALARM	REPLACE PUMP	3.0	YES
07/28/2012	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
07/29/2012	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	3.5	YES
07/30/2012	OVERFLOWING	REPLACE PUMP	1.0	
07/30/2012	OVERFLOWING	REPLACED PUMP & VENT CAP	1.5	YES
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
07/30/2012	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	1.5	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	3.0	YES
	OVERFLOWING	REPLACED PUMP & VENT CAP	3.0	YES
08/01/2012	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.5	YES
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	4.0	YES
08/04/2012	OVERFLOWING	RESET BEAKERS	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	2.0	YES
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
08/06/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
08/06/2012	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	2.0	
08/06/2012	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	OVERFLOWING	REPLACE PUMP	4.0	YES
08/08/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	RESET BEAKERS	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	STATION BACKING UP	REPLACED PUMPS DUE TO GREASE PROBLEM	2.0	
08/10/2012	LIGHT/ALARM	REPLACE PUMP	2.0	
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	5.0	YES
	OVERFLOWING	CUSTOMER COVERED STATION/SENT LETTER	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	3.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	OVERFLOWING	REPLACED PUMPS DUE TO RAGS/CLOTH IN STATION	2.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	OVERFLOWING	REPLACE PUMP	4.0	YES
	LIGHT/ALARM	REPLACE CONTROL BOARD	1.0	
08/20/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE & VENT CAP	1.0	
	LIGHT/ALARM	REPLACE CONTROL BOARD	3.0	YES
08/21/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
08/21/2012	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
09/21/2012	ODOR	DEDIACED DUMAD CUDED VALVE & LIGGE	(HOURS)	HOURS
, , -	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	11.5
	LIGHT/ALARM	RESET BEAKERS	3.0	YES
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
08/25/2012	LIGHT/ALARM	REPLACED PUMP & VENT CAP	3.0	YES
08/27/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
08/27/2012	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
08/27/2012	LIGHT/ALARM	REPLACED PUMP & VENT CAP	4.0	
08/28/2012	ODOR	NO PROBLEM FOUND	1.0	
08/28/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	ODOR	REPLACED PUMP & VENT CAP	1.0	
08/29/2012	STATION BACKING UP	NO PROBLEM FOUND	1.0	
08/29/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
<u> </u>	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
, -, -	LIGHT/ALARM	REPLACED PUMP DUE TO ALARM STAGE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	ODOR	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	ļ
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	2.0	YES
<u> </u>	ODOR	REPLACED PUMP, CABLE & VENT CAP	1.5	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
_ · ·	LIGHT/ALARM	REPLACE PUMP	1.0	\/FC
	LIGHT/ALARM	REPLACED PUMP & CABLE	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	VEC
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	3.0 1.0	YES
	LIGHT/ALARM	REPLACE PUMP REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
<u> </u>	CUSTOMER CALL	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
_ · ·	LIGHT/ALARM	REPLACE PUMP DUE TO STATOR	1.5	
- '. '.	STATION BACKING UP	NO PROBLEM FOUND	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	11.5
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP CABLE AND EQD	1.0	
	STATION BACKING UP	RESET BEAKERS	1.0	
	LIGHT/ALARM	REPLACED PUMP, CABLE & VENT CAP	2.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	İ
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	1.0	İ
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
09/11/2012	OVERFLOWING	REPLACE PUMP	1.0	
09/11/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
09/12/2012	ODOR	NO PROBLEM FOUND	1.0	
09/12/2012	OVERFLOWING	REPLACE PUMP	3.0	YES
09/12/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
09/12/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
09/12/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
09/12/2012	LIGHT/ALARM	REPLACE PUMP DUE TO STATOR	1.0	1

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
09/14/2012	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	3.0	YES
	LIGHT/ALARM	RESET BEAKERS	1.0	
	OVERFLOWING	REPLACE PUMP	2.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	1/50
	LIGHT/ALARM	REPLACE PUMP	4.0	YES
	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP & CONTROL BOARD	1.0	VEC
	STATION BACKING UP	NO PROBLEM FOUND	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	VEC
	PUMP NOT WORKING	REPLACE PUMP	3.5	YES
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.5	
	LIGHT/ALARM	NO PROBLEM FOUND REPLACE PUMP	0.5	
	OVERFLOWING		1.0	
	LIGHT/ALARM OVERFLOWING	REPLACE PUMP REPLACED PUMP & CABLE	1.0 1.5	
	OVERFLOWING LIGHT/ALARM	REPLACED PUMP & CABLE REPLACED PUMP & CONTROL BOARD	1.0 1.5	YES
	OVERFLOWING	REPLACED PUMP A CONTROL BOARD REPLACED PUMP DUE TO ALARM STAGE	1.0	TES
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP & VENT CAP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	YES
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.5	123
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	PUMP RUNNING CONTINUOUSLY	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
	PUMP MAKING NOISE	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
10/09/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
10/10/2012	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	3.0	YES
10/10/2012	OVERFLOWING	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
10/11/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
10/12/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
10/14/2012	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
10/16/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
10/17/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	OVERFLOWING	CUSTOMER DISCONNECTED	0.5	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACE PUMP	2.0	
10/20/2012	LIGHT/ALARM	REPLACE PUMP	2.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
10/20/2012	LIGHT/ALARM	REPLACE PUMP	3.0	
10/20/2012	LIGHT/ALARM	REPLACE PUMP	2.0	
	LIGHT/ALARM	REPLACE PUMP	3.0	YES
10/22/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
10/22/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
10/22/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
10/23/2012	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	4.0	YES
10/24/2012	OVERFLOWING	REPLACE PUMP	2.0	YES
10/24/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	STATION BACKING UP	CUSTOMER DISCONNECTED	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
10/27/2012	LIGHT/ALARM	RESET BEAKERS	3.0	YES
	LIGHT/ALARM	REPLACE PUMP	1.0	YES
	OVERFLOWING	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
11/05/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	PUMP NOT WORKING	NO PROBLEM FOUND	1.0	
11/07/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	CUSTOMER CALL	NO PROBLEM FOUND	1.0	
11/09/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
11/13/2012	STATION BACKING UP	NO PROBLEM FOUND	1.0	
11/13/2012	OVERFLOWING	REPLACE PUMP	1.0	
11/13/2012	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
11/14/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
11/15/2012	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
11/16/2012	OVERFLOWING	REPLACE PUMP	1.0	
11/16/2012	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
11/17/2012	ODOR	NO PROBLEM FOUND	4.0	YES
11/17/2012	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
11/18/2012	STATION BACKING UP	NO PROBLEM FOUND	3.0	YES
11/19/2012	STATION BACKING UP	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	RESET BEAKERS	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	2.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
11/28/2012	LIGHT/ALARM	REPLACE PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
12/05/2012	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
12/05/2012	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE & VENT CAP	1.0	
12/06/2012	STATION BACKING UP	NO PROBLEM FOUND	1.0	
12/06/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
12/10/2012	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	OVERFLOWING	CUSTOMER DISCONNECTED	1.0	
12/11/2012	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	OVERFLOWING	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	5.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
. ,		, -,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
12/17/2012	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	(HOURS) 1.0	HOURS
		,		
12/19/2012	LIGHT/ALARM	REPLACED PUMP & BLADDER	1.0	
12/21/2012	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
12/24/2012	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	4.0	YES
12/26/2012	LIGHT/ALARM	CUSTOMER DISCONNECTED	0.5	
12/26/2012	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
12/27/2012	OVERFLOWING	REPAIRED BROKEN PIG TAIL	2.0	
12/27/2012	OVERFLOWING	REPLACED PUMP, SLIDER VALVE, HOSE & CABLE	1.5	
12/28/2012	LIGHT/ALARM	REPLACE PUMP	2.5	YES
12/28/2012	LIGHT/ALARM	REPLACED PUMP, CABLE, CONTROL BOARD	1.0	
12/30/2012	LIGHT/ALARM	REPLACE PUMP	1.5	
12/31/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
12/31/2012	LIGHT/ALARM	REPLACE PUMP	1.0	
12/31/2012	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
12/31/2012	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
01/01/2013	OVERFLOWING	REPLACED PUMP	3.0	YES
01/02/2013 01/02/2013	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	0.5 1.0	
01/02/2013	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	REPLACED PUMP	1.0	
01/07/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
01/07/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
01/08/2013	OVERFLOWING	REPLACED PUMP	1.0	
01/09/2013	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
01/09/2013	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
01/10/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
01/12/2013	LIGHT/ALARM	REPLACED PUMP	2.0	YES
01/12/2013	OVERFLOWING	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
01/16/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
01/16/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
01/16/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
01/16/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
01/16/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
01/17/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & DISCHARGE HOSE	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
01/20/2013	LIGHT/ALARM	REPLACED PUMP	4.0	YES
01/21/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
01/21/2013	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
01/23/2013	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
01/24/2013	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
01/24/2013	LIGHT/ALARM	REPLACED PUMP	2.0	YES
01/25/2013	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
01/28/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
01/28/2013	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	<u> </u>
01/29/2013	OVERFLOWING	REPLACED PUMP	1.0	
01/29/2013	OVERFLOWING	REPLACED PUMP, CONTROL BOARD & CABLE REPLACED PUMP	1.0	
01/30/2013 01/30/2013	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
02/01/2013	LIGHT/ALARM	REPLACED PUMP	4.0	YES
02/02/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	123
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED CONTROL BOARD	0.5	
<u> </u>		REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
02/07/2013	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
02/07/2013	OVERFLOWING	REPLACED PUMP	1.0	
02/08/2013	ODOR	NO PROBLEM FOUND	0.5	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
02/14/2013	LIGHT/ALARM	BLOCKED LINE ON CUSTOMER'S SIDE	3.0	
02/15/2013	ODOR	NO PROBLEM FOUND	0.5	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
02/25/2013	OVERFLOWING	REPLACED BROKEN PIG TAIL	2.0	l

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
02/27/2013	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	(HOURS) 1.0	HOURS
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.5	YES
03/04/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
03/04/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
03/04/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	REPLACED PUMP	1.0	
03/06/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	STATION BACKING UP	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	,,==
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED BROKEN PIG TAIL	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.5 1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	1.5	
	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED FUMP	2.5	YES
	LIGHT/ALARM	REPLACED PUMP	1.5	YES
	LIGHT/ALARM	REPLACED FUMP	2.0	113
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	STATION BACKING UP	REPLACED PUMP	1.0	
	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
04/10/2013	OVERFLOWING	REPLACED PUMP	1.5	
	OVERFLOWING	REPLACED PUMP	3.0	YES
04/11/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
04/11/2013	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	3.0	YES
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
04/15/2013	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
04/16/2013	STATION BACKING UP	NO PROBLEM FOUND	1.0	
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
04/16/2013	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.5	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
	STATION BACKING UP	BLOCKED LINE ON CUSTOMER'S SIDE	0.5	
04/17/2013	LIGHT/ALARM	REPLACED PUMP & CABLE	3.0	YES

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
- 1/ - 1/	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
<u> </u>	STATION BACKING UP	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	0.5 2.0	YES
	STATION BACKING UP OVERFLOWING	REPLACED PUMP BREAKER ISSUE ON CUSTOMER'S SIDE	0.5	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	TES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED DISCONNECT BOX	1.0	123
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
<u> </u>	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/07/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
05/07/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/08/2013	LIGHT/ALARM	NO PROBLEM FOUND	3.0	YES
05/08/2013	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	1.0	
05/10/2013	STATION BACKING UP	NO PROBLEM FOUND	1.0	
05/10/2013	OVERFLOWING	REPLACED PUMP	1.0	
05/15/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
05/15/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
05/15/2013	OVERFLOWING	REPLACED PUMP	1.0	
05/16/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
05/17/2013	LIGHT/ALARM	NO PROBLEM FOUND	0.5	
05/17/2013	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	0.5	
05/17/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
<u> </u>	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.5	VEC
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM OVERFLOWING	REPLACED PUMP & VENT CAP	1.0 1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP REPLACED PUMP & CONTROL BOARD	3.0	YES
	OVERFLOWING	REPAIRED SEWER LINE & REPLACED PUMP	2.0	153
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	0.5	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	0.5	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	YES

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
05/31/2013	OVERFLOWING	REPLACED PUMP & VENT CAP	1.5	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	3.0	YES
	PUMP NOT WORKING	BLOCKED LINE ON CUSTOMER'S SIDE	1.0	1/50
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	
	PUMP NOT WORKING	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM OVERFLOWING	REPLACED PUMP	1.0 1.0	
<u> </u>		REPLACED PUMP	1.0	
	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP		
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
<u> </u>	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	,	REPLACED PUMP, CONTROL BOARD & CABLE	1.0	
	OVERFLOWING	REPLACED CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	7/56
<u> </u>	OVERFLOWING	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	3.0	YES
	OVERFLOWING	NO PROBLEM FOUND	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	1/50
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
06/18/2013	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	1.5	
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
06/19/2013	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
<u> </u>	OVERFLOWING	REPLACED PUMP, CONTROL BOARD & CABLE	2.0	1/50
	STATION BACKING UP	NO PROBLEM FOUND	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	VEC
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	PUMP NOT WORKING	REPLACED PUMP	1.0	
<u> </u>	LIGHT/ALARM	REPLACED PUMP	0.5	
	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	\/==
06/25/2013	OVERFLOWING	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	
06/25/2013	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
06/26/2013	OVERFLOWING	REPLACED PUMP	1.0	
06/27/2013	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	0.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
06/28/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/28/2013	OVERFLOWING	REPLACED PUMP	1.0	
06/29/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	4.0	YES
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE REPLACED PUMP	3.0 2.0	YES YES
	OVERFLOWING	REPLACED PUMP	2.0	YES
_ · ·	LIGHT/ALARM	REPLACED PUMP	1.0	ILJ
	OVERFLOWING	REPLACED PUMP	1.0	
	ODOR	REPLACED PUMP & CABLE	2.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	. 20
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
07/09/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
07/09/2013	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
07/10/2013	ODOR	NO PROBLEM FOUND	1.0	
07/10/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
07/11/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
07/11/2013	OVERFLOWING	REPLACED PUMP	3.0	YES
07/11/2013	STATION BACKING UP	REPLACED PUMP, CONTROL BOARD, SLIDER VALVE & HOSE	2.0	
07/12/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
07/12/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
07/15/2013	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	4.0	YES
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
· · · · · ·	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0 1.0	
	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	2.0	YES
	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	IES
	ODOR	NO PROBLEM FOUND	0.5	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
	ODOR	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	3.0	YES
07/26/2013		INCLUDED FORM & VENT CAL	5.0	2
	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
07/29/2013	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	(HOURS) 1.0	HOURS
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	0.5	
08/06/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/06/2013	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	1.0	
08/06/2013	LIGHT/ALARM	REPLACED PUMP & VENT CAP	4.0	YES
08/06/2013	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	
08/07/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/08/2013	LIGHT/ALARM	NO PROBLEM FOUND	0.5	
08/08/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/08/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/08/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	ODOR	REPLACED PUMP	1.0	
08/09/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/10/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
08/13/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP, CONTROL BOARD & CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	ODOR	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
<u> </u>	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	11.5
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	ILJ
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	0.5	
	OVERFLOWING	NO PROBLEM FOUND	1.0	
	OVERFLOWING	NO PROBLEM FOUND	0.5	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
		-		
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	1.0	7/50
112/1/1/1172	LIGHT/ALARM	NO PROBLEM FOUND	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
08/26/2013	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
08/27/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/28/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/28/2013	OVERFLOWING	REPLACED PUMP	3.0	YES
08/29/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/30/2013	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
08/30/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/30/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
08/30/2013	OVERFLOWING	REPLACED PUMP & VENT CAP	1.0	<u> </u>
08/31/2013	LIGHT/ALARM	REPLACED PUMP	4.0	YES
08/31/2013	LIGHT/ALARM	REPLACED PUMP	4.0	YES
09/02/2013	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	4.0	YES
09/03/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/03/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/03/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/03/2013	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	1.0	
09/04/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/05/2013	OVERFLOWING	REPLACED BREAKER, CONTROL BOARD, CABLE & PUMP	2.5	
09/05/2013	OVERFLOWING	REPLACED PUMP	1.0	
<u> </u>	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/10/2013	LIGHT/ALARM	RESET STATION	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/12/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/12/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/12/2013	ODOR	REPLACED PUMP	1.0	
09/13/2013	LIGHT/ALARM	REPLACED PUMP	2.5	YES
09/13/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/13/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/13/2013	OVERFLOWING	REPLACED PUMP	2.5	YES
09/14/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/14/2013	LIGHT/ALARM	REPLACED PUMP	4.0	YES
09/15/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/16/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/16/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/16/2013	OVERFLOWING	REPLACED PUMP	3.0	YES
	OVERFLOWING	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
09/18/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
09/18/2013	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/19/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/22/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/23/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	

	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
09/26/2013	LIGHT/ALARM	REPLACED PUMP	(HOURS) 1.0	HOURS
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/30/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/01/2013	OVERFLOWING	REPLACED PUMP	1.0	
10/02/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
10/03/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
10/03/2013	OVERFLOWING	REPLACED PUMP	1.0	
10/04/2013	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
10/07/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP, CONTROL BOARD & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/09/2013	LIGHT/ALARM	NO PROBLEM FOUND	0.5	
10/09/2013	STATION BACKING UP	NO PROBLEM FOUND	3.0	YES
10/09/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
10/09/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
10/10/2013	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
10/10/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
10/10/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
10/10/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
10/10/2013	OVERFLOWING	REPLACED PUMP	1.0	
10/11/2013	OVERFLOWING	REPLACED CABLE	1.0	
10/12/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
10/12/2013	OVERFLOWING	REPLACED PUMP	2.0	YES
10/13/2013	LIGHT/ALARM	REPLACED PUMP	4.0	YES
10/14/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
10/14/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
10/14/2013	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
10/15/2013	OVERFLOWING	REPLACED PUMP	3.0	YES
	STATION BACKING UP	NO PROBLEM FOUND	3.0	YES
10/18/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/19/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	PUMP MAKING NOISE	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
1073077012	LIGHT/ALARM	REPLACED PUMP	1.0 1.0	
			1 1 ()	1
10/30/2013	LIGHT/ALARM OVERFLOWING	REPLACED PUMP & CABLE BREAKER ISSUE ON CUSTOMER'S SIDE	0.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM STATION BACKING UP	REPLACED PUMP & CONTROL BOARD REPLACED PUMP & CONTROL BOARD	1.5 1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	STATION BACKING UP	REPLACED PUMP	1.0	
	STATION BACKING OF	BLOCKED LINE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
11/06/2013	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	3.0	YES
11/07/2013	LIGHT/ALARM	REPLACED PUMP	1.0	123
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.5	
11/12/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
11/12/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
11/13/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
11/13/2013	LIGHT/ALARM	REPLACED PUMP	4.0	YES
11/13/2013	OVERFLOWING	REPLACED PUMP	1.0	
11/14/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
11/14/2013	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	1.0	
11/15/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
11/18/2013	OVERFLOWING	NO PROBLEM FOUND	0.5	
11/18/2013	OVERFLOWING	REPLACED PUMP	1.0	-
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
11/22/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
11/24/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
11/25/2013	LIGHT/ALARM	REPLACED PUMP	2.0	
11/25/2013	ODOR	REPLACED PUMP	4.0	YES
11/26/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
11/27/2013	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0 3.0	YES
11/29/2013 12/01/2013	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	0.5	ILJ
12/02/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
12/02/2013	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
12/02/2013	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	STATION BACKING UP	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	RESET STATION	1.0	
12/10/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
12/10/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	2.0	
12/12/2013	LIGHT/ALARM	REPLACED PUMP	4.0	YES
12/13/2013	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
12/14/2013	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	3.0	YES
	STATION BACKING UP	NO PROBLEM FOUND	3.0	YES
		REPLACED PUMP	1.0	
	STATION BACKING UP	BLOCKED LINE ON CUSTOMER'S SIDE	2.0	
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
	STATION BACKING UP	NO PROBLEM FOUND	1.0	
12/18/2013	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	3.0	YES

DATE	COMPLAINT	PECOLUTION	COMPLETION TIME	AFTER
DATE	COMPLAINT	RESOLUTION	(HOURS)	HOURS
12/19/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
12/19/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
12/19/2013	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	
12/20/2013	OVERFLOWING	REPLACED PUMP	3.0	YES
12/20/2013	OVERFLOWING	REPLACED PUMP	1.0	
12/20/2013	ODOR	REPLACED PUMP	1.0	
12/21/2013	LIGHT/ALARM	POWER ISSUE ON CUSTOMER'S SIDE	3.0	YES
12/23/2013	LIGHT/ALARM	REPLACED PUMP	3.0	YES
12/24/2013	OVERFLOWING	REPLACED PUMP	3.0	YES
12/24/2013	OVERFLOWING	REPLACED PUMP	4.0	YES
12/26/2013	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
12/26/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
12/30/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
12/30/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
12/31/2013	STATION BACKING UP	NO PROBLEM FOUND	1.0	
12/31/2013	LIGHT/ALARM	REPLACED PUMP	1.0	
6/11/813	PUMP RUNNING CONTINUOUSLY	REPLACED PUMP	1.0	
9/12/813	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/02/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
01/02/2014	PUMP NOT WORKING	REPLACED PUMP	1.0	
01/04/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
01/05/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
01/07/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
01/08/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
01/08/2014	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
01/09/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
01/09/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
01/09/2014	PUMP NOT WORKING	REPLACED PUMP THAT WAS FROZEN	1.0	
01/10/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	0.5	
01/13/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
01/13/2014	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
01/14/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
01/14/2014	OVERFLOWING	REPLACED PUMP, CABLE & CONTROL BOARD	3.0	YES
01/14/2014	OVERFLOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
01/16/2014	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	0.5	
		SIDE		
	STATION BACKING UP	INSTALLED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
01/17/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
01/17/2014	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
01/20/2014	OVERFLOWING	REPLACED PUMP	1.0	
01/20/2014	STATION BACKING UP	REPLACED PUMP & CABLE	1.0	
01/20/2014	LIGHT/ALARM	REPLACED PUMP DUE TO EXCESSIVE BABY WIPES IN STATION.	1.5	
01/20/2014	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
01/22/2014	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	3.0	YES
	LIGHT/ALARM	REPLACED EQD END	1.0	123
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	11.5
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	11.5
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	RESET BREAKERS	1.0	
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	NO POWER ON COSTOMER'S SIDE	0.5	
	LIGHT/ALARM	REPLACED PUMP & 20' OF FROZEN SERVICE LINE	2.0	
	LIGHT/ALARM	REPLACED PUMP & FROZEN SERVICE LINE REPLACED PUMP & FROZEN SERVICE LINE IN CREEK	4.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED CABLE & CONTROL BOX	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.5	IES
		REPLACED PUMP	1.0	
01/31/2014	LIGHT/ALARM	REPLACED PUMP & FROZEN SERVICE LINE UNDER	1.0	
02/02/2014	OVERFLOWING	ROAD	4.0	YES
02/03/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
02/03/2014	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
02/04/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
02/04/2014	LIGHT/ALARM	REPLACED PUMP, HIGH AMPED DUE TO BLOCKED LINE. REPAIRED BLOCKAGE.	1.0	
02/05/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
32,00,2014	,/ \www.	2.020 1 01111	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
02/06/2014	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	RESET BREAKERS REPLACED PUMP	1.0 3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	TES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
02/12/2014	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
02/16/2014	LIGHT/ALARM	REPLACED PUMP	4.0	YES
02/17/2014	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
		REPLACED PUMP	1.0	
	OVERFLOWING LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP, BREAKERS & CABLE	1.0	123
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	PUMP NOT WORKING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
03/01/2014	OVERFLOWING	REPLACED PUMP	4.0	YES
03/03/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
03/03/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
	PUMP NOT WORKING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0 1.5	
03/10/2014	OVERFLOWING	REPLACED PUMP	1.5	
		REPLACED PUMP, HIGH AMPED DUE TO BLOCKED		
03/10/2014	LIGHT/ALARM	LINE. REPAIRED BLOCKAGE.	4.5	
03/11/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
03/11/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
03/12/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
03/14/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
03/16/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
03/19/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING OVERFLOWING	REPLACED PUMP REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	. 20
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
03/24/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
	OVERFLOWING OVERFLOWING	REPLACED PUMP REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	3.0	YES
03/30/2014	LIGHT/ALARM	REPLACED PUMP	1.0	ILJ
04/02/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.5	
04/04/2014	LIGHT/ALARM	REPLACED PUMP	1.5	
04/05/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
04/07/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
·	· · · · · · · · · · · · · · · · · · ·	·		

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
04/07/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
04/07/2014	LIGHT/ALARM	REPLACED PUMP	0.5	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP, CABLE & CONTROL BOARD	0.5	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	\/F6
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0 1.0	
		REPLACED PUMP REPLACED PUMP	1.0	
	LIGHT/ALARM OVERFLOWING	REPLACED PUMP & CABLE	3.5	YES
	OVERFLOWING	REPLACED PUMP & CABLE REPLACED PUMP & EQD	1.0	TES
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	ILS
	OVERFLOWING	REPLACED PUMP & BLADDER	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.5	
04/23/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.5	
	LIGHT/ALARM	REPLACED PUMP. SLIDER VALVE & HOSE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	123
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	1123
	PUMP NOT WORKING	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	_
05/07/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
05/07/2014	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
05/08/2014	OVERFLOWING	REPAIRED PRESSURE CONNECT	1.0	
05/08/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
05/09/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
05/09/2014	STATION RUNNING CONTINUOUSLY	REPLACED PUMP	1.0	
05/09/2014	COMMODES SLOW TO FLUSH	STATION CHECKED OKAY. BLOCKAGE ON CUSTOMER'S SIDE	1.0	
05/10/2014	LIGHT/ALARM	REPLACED PUMP IN ALARM STAGE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/13/2014	OVERFLOWING	REPLACED PUMP, CABLE END & CONTROL BOARD	1.5	
05/14/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
05/16/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/16/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/16/2014	OVERFLOWING	REPLACED PUMP	1.0	
05/16/2014	PUMP NOT WORKING	REPLACED PUMP & CONTROL BOARD	2.0	
05/17/2014	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	3.0	YES
05/19/2014	LIGHT/ALARM	REPLACED EQD END	1.0	
05/19/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/19/2014	LIGHT/ALARM	REPLACED PUMP	2.0	
05/19/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
05/19/2014	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
05/20/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
05/21/2014	LIGHT/ALARM	REPLACED PUMP	1.0	

S727/2701 LIGHT/ALARM	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
05/23/2014 LIGHT/ALARM	05/22/2014	LICUT/ALADAA	DEDI ACED DI IMP	· · · · · · · · · · · · · · · · · · ·	
SPAIR SPAI		•			YES
SSJA1/2014 LICHIT/ALARM REPIACED PUMP 4.0 YES SSJA1/2014 LICHIT/ALARM REPIACED PUMP 4.0 YES SSJA1/2014 LICHIT/ALARM REPIACED PUMP 4.0 YES SSJA1/2014 LICHIT/ALARM REPIACED PUMP 3.0 YES SSJA1/2014 LICHIT/ALARM REPIACED PUMP 3.0 YES SSJA1/2014 LICHIT/ALARM REPIACED PUMP 1.0 SSJA1/2014 LICHIT/ALARM REPIACED PUMP 1.0 SSJA1/2014 LICHIT/ALARM REPIACED PUMP 1.0 SSJA1/2014 LICHIT/ALARM REPIACED PUMP 1.0 SSJA1/2014 LICHIT/ALARM REPIACED PUMP 1.0 SSJA1/2014 LICHIT/ALARM REPIACED PUMP 1.0 SSJA1/2014 LICHIT/ALARM REPIACED PUMP 1.0 SSJA1/2014 LICHIT/ALARM REPIACED PUMP 1.0 SSJA1/2014 LICHIT/ALARM REPIACED PUMP 1.0 SSJA1/2014 LICHIT/ALARM REPIACED PUMP 2.5 YES SSJA1/2014 LICHIT/ALARM REPIACED PUMP 3.0 YES SSJA1/2014 LICHIT/ALARM REPIACED					VES
S05747014 USHT/ALARM				<u> </u>	
SSTAGDIA USHT/ALARM				<u> </u>	
Sy21/2014 UCHEFLOWING		· · · · · · · · · · · · · · · · · · ·		<u> </u>	
S05/27/2014 UGHT/ALARM				<u> </u>	
					11.5
S0529/2014 UNIFF NOT WORKING					
SSTARCED PUMP 1.0					
OSFAD/2014 LIGHT/ALARM					
S5/30/2014 UGHT/ALARM					YFS
SEPERATED PLIMP & CABLE 1.0					123
MORPHICANING REPLACED PUMP 3.0 YES					
					YES
0.00000000000000000000000000000000000					
				<u> </u>	120
				<u> </u>	
		-			
0.6/03/2014 LIGHT/ALARM		-		<u> </u>	
0.603/2014 LIGHT/ALARM					
0.6/03/2014 LIGHT/ALARM					
06/03/2014 UGHT/ALARM					
G6/05/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0					VFS
		-		<u> </u>	ILJ
06/09/2014 UGHT/ALARM				<u> </u>	
06/09/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0				<u> </u>	
REPLACED PUMP DUE TO GREASE, BABY WIPES, 2.0					
FEMININE HYGINE PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMINING PRODUCTS. FEMININ					
06/11/2014 LIGHT/ALARM REPLACED PUMP 1.0			FEMININE HYGINE PRODUCTS.	2.0	
06/11/2014 LIGHT/ALARM REPLACED PUMP 1.0		-	RESET BREAKERS	3.0	YES
06/11/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/11/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/11/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/12/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/13/2014 LIGHT/ALARM REPLACED PUMP UP TO BAD STATOR 3.0 YES 06/16/2014 LIGHT/ALARM REPLACED PUMP WE CABLE 1.0 1.0 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 1.0 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 1.0 06/16/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 1.0 06/16/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/19/2014 LIGHT/ALARM REPLACED P	06/10/2014	LIGHT/ALARM	REPLACED PUMP	2.0	
06/11/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/11/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/12/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/13/2014 LIGHT/ALARM REPLACED PUMP DUE TO BAD STATOR 3.0 YES 06/16/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 1.0 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 1.0 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 1.0 06/16/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/17/2014 USERLOWING REPLACED PUMP 1.0 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/19/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/19/2014 STATION MAKING NOISE REPLA			REPLACED PUMP	1.0	
06/11/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/12/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/13/2014 LIGHT/ALARM REPLACED PUMP DUE TO BAD STATOR 3.0 YES 06/16/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 YES 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 YES 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 YES 06/16/2014 DUERFLOWING REPLACED PUMP & CABLE 1.0 YES 06/16/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 YES 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 YES 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 YES 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 YES 06/19/2014 LIGHT/ALARM REPLACED PUMP 1.0 YES 06/19/2014 LIGHT/ALARM REPLACED PUMP 2.0 YES 06/20/2014 LIGHT/ALARM </td <td>06/11/2014</td> <td>LIGHT/ALARM</td> <td>REPLACED PUMP</td> <td>1.0</td> <td></td>	06/11/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
06/12/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/13/2014 LIGHT/ALARM REPLACED PUMP DUE TO BAD STATOR 3.0 YES 06/16/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 1.0 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 1.0 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 1.0 06/16/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/17/2014 OVERFLOWING REPLACED PUMP 1.0 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 1.0 06/19/2014 OVERFLOWING STATION CHECKED DKAY. PROBLEM ON CUSTOMER'S 1.0 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 0 0	06/11/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
06/13/2014 LIGHT/ALARM REPLACED PUMP DUE TO BAD STATOR 3.0 YES 06/16/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/16/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 OVERFLOWING REPLACED PUMP 1.0 06/17/2014 OVERFLOWING REPLACED PUMP 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP	06/11/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/16/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/16/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE <t< td=""><td>06/12/2014</td><td>LIGHT/ALARM</td><td>REPLACED PUMP</td><td>1.0</td><td></td></t<>	06/12/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/16/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 UGHT/ALARM REPLACED PUMP 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0	06/13/2014	LIGHT/ALARM	REPLACED PUMP DUE TO BAD STATOR	3.0	YES
06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/16/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 OVERFLOWING REPLACED PUMP 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BO			REPLACED PUMP	3.0	YES
06/16/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/16/2014 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 OVERFLOWING REPLACED PUMP 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BO	06/16/2014	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0					
06/17/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/17/2014 OVERFLOWING REPLACED PUMP 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 SIDE SIDE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE & CONTROL BOARD 2.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 YES 06/23/2014 LIGHT/ALARM <t< td=""><td>06/16/2014</td><td>LIGHT/ALARM</td><td>REPLACED PUMP & CONTROL BOARD</td><td>1.0</td><td></td></t<>	06/16/2014	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
06/17/2014 OVERFLOWING REPLACED PUMP 1.0 06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 <td< td=""><td>06/17/2014</td><td>LIGHT/ALARM</td><td>REPLACED PUMP</td><td>1.0</td><td></td></td<>	06/17/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 <td< td=""><td>06/17/2014</td><td>LIGHT/ALARM</td><td>REPLACED PUMP</td><td>1.0</td><td></td></td<>	06/17/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
06/18/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 <td< td=""><td>06/17/2014</td><td>OVERFLOWING</td><td>REPLACED PUMP</td><td>1.0</td><td></td></td<>	06/17/2014	OVERFLOWING	REPLACED PUMP	1.0	
06/19/2014 STATION MAKING NOISE REPLACED PUMP 1.0 06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0			REPLACED PUMP	1.0	
06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0	06/19/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
06/19/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0	06/19/2014	STATION MAKING NOISE	REPLACED PUMP	1.0	
06/20/2014 LIGHT/ALARM REPLACED PUMP 2.0 06/20/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0		OVERFLOWING		1.0	
06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0	06/20/2014	LIGHT/ALARM		2.0	
06/20/2014 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 06/20/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0	06/20/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/20/2014 OVERFLOWING REPLACED PUMP & CABLE 1.0 06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0					
06/20/2014 LIGHT/ALARM REPLACED PUMP, CABLE & CONTROL BOARD 2.0 06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0			REPLACED PUMP & CABLE	1.0	
06/21/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0			REPLACED PUMP, CABLE & CONTROL BOARD		
06/21/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0					YES
06/21/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 2.0 YES 06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0					
06/23/2014 OVERFLOWING LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0		-			YES
06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0 06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0					-
06/23/2014 LIGHT/ALARM REPLACED PUMP 1.0					
			REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
06/24/2014	LIGHT/ALARM	REPLACED PUMP IN ALARM STAGE	1.0	
06/24/2014	LIGHT/ALARM	RESET BREAKERS	4.0	YES
	COMMODES SLOW TO FLUSH	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
—	PUMP NOT WORKING OVERFLOWING	REPLACED PUMP REPLACED PUMP	4.0 1.0	YES
	STATION BACKING UP	REPLACED PUMP & CABLE	1.0	
00/30/2014	STATION BACKING OF	REPLACED POIVIP & CABLE	1.0	
	LIGHT/ALARM	CONTROL BOX HAS 110V NOT 220V CUSTOMER'S SIDE	1.0	
	COMMODES SLOW TO FLUSH	REPLACED CONTROL BOARD	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.5	
07/02/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
07/03/2014	LIGHT/ALARM	CONTROL BOX HAS 110V NOT 220V CUSTOMER'S SIDE	2.5	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, CABLE, EQD	4.5	YES
07/06/2014	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP & EQD	1.5	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
07/14/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
07/14/2014	COMMODES SLOW TO FLUSH	STATION CHECKED OKAY. BLOCKAGE ON CUSTOMER'S SIDE	1.0	
07/14/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
07/14/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
07/15/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
07/15/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
07/16/2014	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	4.0	YES
07/16/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.5	V.5.5
07/21/2014	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
07/21/2014	PUMP NOT WORKING	REPLACED PUMP & EQD, REPAIRED SEWER LEAK	2 DAYS (LEAK REPAIR)	
	OVERFLOWING	REPLACED PUMP, CABLE & CONTROL BOARD	2.0	
07/22/2014	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
07/23/2014	PUMP NOT WORKING	REPLACED PUMP	1.0	
	STATION MAKING NOISE	REPLACED PUMP	1.0	
07/25/2014	LIGHT/ALARM	REPLACED PUMP	6.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	2.0	
07/28/2014	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
07/29/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
07/29/2014	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	
07/29/2014	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
07/29/2014	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
07/30/2014	LIGHT/ALARM	REPLACED PUMP	2.0	
07/30/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
07/30/2014	LIGHT/ALARM	REPLACED PUMP	4.0	YES
07/30/2014	OVERFLOWING	REPLACED PUMP	1.0	
07/30/2014	OVERFLOWING	REPLACED PUMP	1.0	
07/30/2014	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
08/02/2014	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	STATION BACKING UP	INSTALLED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
08/05/2014	OVERFLOWING	REPLACED PUMP DUE TO GREASE ISSUE IN STATION.1		
08/06/2014	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	3.0	YES
<u> </u>		NO POWER ON CUSTOMER'S SIDE		1 E 3
	OVERFLOWING LIGHT/ALARM	REPLACED PUMP	1.0 3.0	YES
				YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	\/FC
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPAIRED PRESSURE CONNECT	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
08/12/2014	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	1.0	
08/12/2014	PUMP NOT WORKING	REPLACED PUMP, CUSTOMER REPAIRED A FUSE ON THEIR SIDE, & MWD REMOVED 4 BAGS OF GREASE	2.0	
		FROM STATION.		
	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	CLEANED OUT LINES	3.0	
	OVERFLOWING	REPAIRED PIG TAIL	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
, -, -	OVERFLOWING	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	4.0	YES
08/19/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
08/19/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
08/20/2014	OVERFLOWING	REPLACED PUMP	1.0	
08/21/2014	LIGHT/ALARM	REPLACED PUMP	4.0	YES
08/21/2014	LIGHT/ALARM	REPLACED PUMP	1.5	
08/22/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
08/22/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
08/22/2014	OVERFLOWING	REPLACED PUMP	1.0	
08/25/2014	LIGHT/ALARM	CLEANOUT WAS FULL, USED JETTER TO REMOVE BLOCKAGE	2.0	
08/25/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
08/27/2014	PUMP NOT WORKING	REPLACED PUMP	4.0	YES
00/2//2014	I OIVII IVOI VVOINKIIVO	IVEL FUCED EQUALE	4.∪	1 EJ

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
08/27/2014	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
08/27/2014	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	3.0	YES
08/27/2014	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
08/28/2014	STATION BACKING UP	LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE	2.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
08/29/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
08/29/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
08/29/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
08/30/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
08/30/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
08/30/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/01/2014	OVERFLOWING	REPLACED PUMP	3.0	YES
09/02/2014	OVERFLOWING	REPLACED PUMP	1.0	
09/02/2014	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	3.0	YES
	OVERFLOWING	INSTALLED PUMP	1.0	
09/04/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/04/2014	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
09/05/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
09/06/2014	LIGHT/ALARM	REPLACED CONTROL BOARD	2.0	YES
09/06/2014	LIGHT/ALARM	REPLACED PUMP	2.0	YES
09/06/2014	LIGHT/ALARM	REPLACED PUMP	4.0	YES
09/06/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/07/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/08/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
09/08/2014	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
09/08/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	NO POWER	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	STATION BACKING UP	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
, -, -	OVERFLOWING	REPLACED PUMP	1.0	
09/11/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
09/11/2014	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	1.0	
09/12/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
09/12/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
09/13/2014	LIGHT/ALARM	CONTROL BOX HAS 110V NOT 220V CUSTOMER'S SIDE	0.5	
09/13/2014	LIGHT/ALARM	REPLACED PUMP	2.5	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
09/18/2014	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/22/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
09/22/2014	OVERFLOWING	REPLACED PUMP & CABLE	1.0	
09/23/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	CLOGGED LINE	LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE	2.5	
	OVERFLOWING	REPLACED CONTROL BOARD	1.0	-
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/24/2014	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.5	
	PUMP NOT WORKING	REPLACED PUMP & VENT CAP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/29/2014	OVERFLOWING	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
00/00/0044	11017/11100	PREAMER ISSUE ON GUSTONAFRIS CIRE	(HOURS)	HOURS
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	2.0	VEC
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	4.0 1.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
		REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/08/2014	OVERFLOWING	REPLACED PUMP & EQD	1.0	
10/08/2014	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
10/09/2014	LIGHT/ALARM	SIDE BREAKER ISSUE ON CUSTOMER'S SIDE	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP NOT WORKING	REPLACED PUMP	1.0	
	ODOR ODOR	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
		SIDE PEDALBED LOOSE WIDE		
	LIGHT/ALARM	REPAIRED LOOSE WIRE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	4.0 1.0	YES
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.5	ILJ
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
	STATION BACKING UP	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
10/22/2014	LIGHT/ALARM	SIDE REPLACED PUMP	1.0	
	LIGHT/ALARM	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
	·	SIDE		
	LIGHT/ALARM	REPLACED PUMP	1.0	\/F\$
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
10/27/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
10/27/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
10/27/2014	COMMODES SLOW TO FLUSH	STATION CHECKED OKAY. BLOCKAGE ON CUSTOMER'S SIDE	0.5	
10/28/2014	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACED PUMP	2.0	
10/29/2014	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
10/29/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/31/2014	LIGHT/ALARM	BLOCKED LINE, TURNED VALVE ON AT DISCONNECT	1.5	
10/31/2014	LIGHT/ALARM	REPLACED PUMP	2.0	
11/01/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
11/03/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
11/03/2014	OVERFLOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE	0.5	
11/04/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	

11/05/2014 USHT/ALARM	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
11/06/2014 LIGHT/ALARM	11/05/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
11/06/2014 LIGHT/ALARM	11/06/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
11/06/2014 UGHT/ALARM					
11/09/2014 LIGHT/ALRAM	11/06/2014	LIGHT/ALARM		1.0	
11/07/2014 UGHT/ALARM REPLACED PUMP 1.0	11/06/2014	LIGHT/ALARM		1.0	
11/07/2014 OVERFLOWING REPLACED PUMP & EQD 2.0	11/07/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
11/07/2014 UGHT/ALARM	11/07/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
11/07/2014 UGHT/ALARM	11/07/2014	OVERFLOWING	REPLACED PUMP	1.0	
11/07/2014 STATION CHECKED DIAGY. PROBLEM ON CUSTOMERS 1.0	11/07/2014	OVERFLOWING	REPLACED PUMP & EQD	2.0	
11/09/2014 GINT/ALARM	11/07/2014	LIGHT/ALARM		1.0	
11/09/2014 GHT/ALARM	11/07/2014	STATION BACKING UP		1.0	
11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.5 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.5 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.5 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.1 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.1 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.1 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.1 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.1 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.1 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.1 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0 1.1 11/10/2014 IGHT/ALARM REPLACED PUMP 1.0	11/09/2014	LIGHT/ALARM	<u> </u>	3.0	YES
11/10/2014 IGHT/ALARM REPLACED PUMP, SLIDER VALVE & HOSE 3.0 YES 11/12/2014 OVERFLOWING REPLACED PUMP 1.0 11/12/2014 OVERFLOWING REPLACED PUMP 1.0 11/12/2014 IGHT/ALARM REPLACED PUMP 1.5 11/15/2014 IGHT/ALARM REPLACED PUMP 1.0 11/12/2014 IGHT/ALARM REPLACED PUMP, HIGH AMPED DUE TO BLOCKED 1.0 11/12/2014 IGHT/ALARM REPLACED PUMP, HIGH AMPED DUE TO BLOCKED 1.0 11/12/2014 IGHT/ALARM REPLACED PUMP, HIGH AMPED DUE TO BLOCKED 1.0 11/12/2014 IGHT/ALARM REPLACED PUMP 1.5 11/12/2014 IGHT/ALARM REPLACED PUMP 1.5 11/12/2014 IGHT/ALARM REPLACED PUMP 1.0 11/12/2014 IGHT/ALARM REPLACED PUMP 1.0 11/12/2014 IGHT/ALARM NO POWER ON CUSTOMER'S SIDE 4.0 YES 11/12/2014 IGHT/ALARM REPLACED PUMP 1.5 11/12/2014 IGHT/ALARM REPLACED PUMP 1.0 12/01/2014 I		·			
11/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.5 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.5 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM NO POWER ON CUSTOMER'S SIDE 4.0 YES 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0 1.0 1.1/12/2014 UGHT/ALARM REPLACED PLIMP 1.0		·			YES
11/12/2014 USHT/JALARM REPLACED PLIMP 1.0 11/14/2014 USHT/JALARM REPLACED PLIMP 4.5 YES 11/14/2014 USHT/JALARM REPLACED PLIMP 4.5 YES 11/14/2014 USHT/JALARM REPLACED PLIMP 4.5 YES 11/14/2014 USHT/JALARM REPLACED PLIMP 1.0 11/14/2014 USHT/JALARM REPLACED PLIMP 1.0 11/14/2014 USHT/JALARM REPLACED PLIMP 1.0 11/14/2014 USHT/JALARM REPLACED PLIMP 1.0 11/14/2014 USHT/JALARM REPLACED PLIMP 1.0 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.5 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.5 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.7 11/14/2014 USHT/JALARM REPLACED PLIMP 1.0 VES 11/14/2014 USHT/JALARM NO POWER ON CUSTOMER'S SIDE 4.0 VES 11/14/2014 USHT/JALARM NO POWER ON CUSTOMER'S SIDE 3.0 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.1 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.1 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.1 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.1 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.1 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.1 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.1 11/14/2014 USHT/JALARM REPLACED PLIMP 1.5 1.1 11/14/2014 USHT/JALARM REPLACED PLIMP 1.0 11/14/2014 USHT/JALARM REPLACED PLIMP 2.0 YES 11/14/2014 USHT/JALARM REPLACED PLIMP 2.0 YES 11/14/2014 USHT/JALARM REPLACED PLIMP 2.0 YES 11/14/2014 USHT/JALARM REPLACED PLIMP 3.0 YES 11/14/2014 USHT/JALARM REPLACED PLIMP 4.0		·	·	1.0	
11/14/2014 LIGHT/ALARM		-			
11/15/2014 LIGHT/ALARM		I.	REPLACED PUMP		
11/17/2014 LIGHT/ALARM					YES
11/17/2014 LIGHT/ALARM					
11/17/2014 LIGHT/ALARM	11/17/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
11/19/2014 OVERFLOWING				1.0	
11/21/2014 LIGHT/ALARM	11/19/2014	OVERELOWING		15	
11/23/2014 LIGHT/ALARM					
11/24/2014 UGHT/ALARM			<u> </u>		YES
11/24/2014 LIGHT/ALARM					. 20
11/24/2014					
11/25/2014					
11/25/2014 OVERFLOWING		·	REPLACED PUMP	1.5	
11/25/2014 PUMP NOT WORKING SIDE 0.5 11/27/2014 LIGHT/ALARM REPLACED PUMP 2.0 YES 11/27/2014 UIGHT/ALARM REPLACED PUMP CABLE & CONTROL BOARD 4.0 YES 11/30/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 11/30/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/01/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/01/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/01/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/01/2014 PUMP NOT WORKING REPLACED PUMP & CABLE 1.0 12/01/2014 PUMP NOT WORKING REPLACED PUMP & STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 12/01/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 12/01/2014 LIGHT/ALARM BREAKER ISSUE ON CUSTOMER'S SIDE 1.0 12/02/2014 LIGHT/ALARM BREAKER ISSUE ON CUSTOMER'S SIDE 1.0 12/02/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/04/2014 STATION BACKING UP STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 12/05/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/05/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/05/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/05/2014 LIGHT/ALARM REPLACED PUMP 4.0 YES 12/09/2014 LIGHT/ALARM REPLACED PUMP 4.0 YES 12/09/2014 LIGHT/ALARM REPLACED PUMP 4.5 YES 12/09/2014 LIGHT/ALARM REPLACED PUMP 4.5 YES 12/09/2014 LIGHT/ALARM REPLACED PUMP 4.5 YES 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/10/2014 LIG	11/25/2014	OVERFLOWING	REPLACED PUMP	1.0	
11/27/2014	11/25/2014	PUMP NOT WORKING		0.5	
11/27/2014 OVERFLOWING	11/27/2014	LIGHT/ALARM	<u> </u>	2.0	YES
11/30/2014					
12/01/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/01/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 12/01/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 12/01/2014 LIGHT/ALARM REPLACED PUMP 1.0 1.0 12/01/2014 PUMP NOT WORKING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 1					
12/01/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/01/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/01/2014 PUMP NOT WORKING REPLACED PUMP & CABLE 1.0 12/01/2014 PUMP NOT WORKING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/01/2014 PUMP NOT WORKING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/01/2014 PUMP NOT WORKING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 12/01/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 12/02/2014 LIGHT/ALARM BREAKER ISSUE ON CUSTOMER'S SIDE 1.0 12/02/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/04/2014 STATION BACKING UP STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 12/05/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/06/2014 LIGHT/ALARM REPLACED PUMP 4.0 YES 12/06/2014 LIGHT/ALARM REPLACED PUMP 4.0 YES 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/10/2014 LIGHT/ALARM REPLACED PUMP & 2.0 12/10/2014 LIGHT/ALARM REPLACED PUMP & 3.0 YES 12/12/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/13/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 8.0 TO THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR THE TOR					_
12/01/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/01/2014 PUMP NOT WORKING REPLACED PUMP & CABLE 1.0 12/01/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/01/2014 PUMP NOT WORKING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 12/01/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 12/01/2014 LIGHT/ALARM BREAKER ISSUE ON CUSTOMER'S SIDE 1.0 12/02/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/04/2014 STATION BACKING UP SIDE 1.0 12/05/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/06/2014 LIGHT/ALARM REPLACED PUMP 4.0 YES 12/06/2014 LIGHT/ALARM REPLACED PUMP 4.5 YES 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/10/2014 LIGHT/ALARM REPLACED PUMP 1.5 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.5 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/11/2014 OVERFLOWING REPLACED PUMP & CABLE 2.0 12/11/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP SEDD 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP SEDD 3.0 S					
12/01/2014 PUMP NOT WORKING REPLACED PUMP, SLIDER VALVE & HOSE 1.0		·	REPLACED PUMP	1.0	
12/01/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0					
12/01/2014 PUMP NOT WORKING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0			REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
12/01/2014 OVERFLOWING STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S 1.0 12/02/2014	12/01/2014	PUMP NOT WORKING		1.0	
SIDE 1.0	12/01/2014	OVERFLOWING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S	1.0	
12/02/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/04/2014 STATION BACKING UP STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE 1.0 12/05/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/06/2014 LIGHT/ALARM REPLACED PUMP 4.0 YES 12/06/2014 LIGHT/ALARM REPLACED PUMP 4.5 YES 12/09/2014 LIGHT/ALARM INSTALLED PUMP 1.0 1.0 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.5 1.0 12/09/2014 OVERFLOWING REPLACED PUMP & EQD 1.0 1.0 12/10/2014 LIGHT/ALARM REPLACED PUMP & CABLE 2.0 1.0 12/11/2014 OVERFLOWING REPLACED PUMP & CABLE 2.0 1.0 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 LIGHT/ALARM REPLACED PUMP, SLIDER VALVE			_	1.0	
12/04/2014 STATION BACKING UP STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S SIDE					
12/05/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/06/2014 LIGHT/ALARM REPLACED PUMP 4.0 YES 12/06/2014 LIGHT/ALARM REPLACED PUMP 4.5 YES 12/09/2014 LIGHT/ALARM INSTALLED PUMP 1.0 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.5 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.5 12/09/2014 OVERFLOWING REPLACED PUMP & EQD 1.0 12/10/2014 LIGHT/ALARM REPLACED PUMP & CABLE 2.0 12/11/2014 OVERFLOWING REPLACED PUMP & CABLE 2.0 12/12/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP & EQD 2.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0			STATION CHECKED OKAY. PROBLEM ON CUSTOMER'S		
12/06/2014 LIGHT/ALARM REPLACED PUMP 4.5 YES 12/09/2014 LIGHT/ALARM INSTALLED PUMP 1.0 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.5 12/09/2014 OVERFLOWING REPLACED PUMP & EQD 1.0 12/10/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/11/2014 OVERFLOWING REPLACED PUMP & CABLE 2.0 12/12/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0					
12/09/2014 LIGHT/ALARM INSTALLED PUMP 1.0 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.5 12/09/2014 OVERFLOWING REPLACED PUMP & EQD 1.0 12/10/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/11/2014 OVERFLOWING REPLACED PUMP & CABLE 2.0 12/12/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0	12/06/2014	LIGHT/ALARM	REPLACED PUMP	4.0	YES
12/09/2014 LIGHT/ALARM INSTALLED PUMP 1.0 12/09/2014 LIGHT/ALARM REPLACED PUMP 1.5 12/09/2014 OVERFLOWING REPLACED PUMP & EQD 1.0 12/10/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/11/2014 OVERFLOWING REPLACED PUMP & CABLE 2.0 12/12/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0	12/06/2014	LIGHT/ALARM	REPLACED PUMP	4.5	YES
12/09/2014 OVERFLOWING REPLACED PUMP & EQD 1.0 12/10/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/11/2014 OVERFLOWING REPLACED PUMP & CABLE 2.0 12/12/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0			INSTALLED PUMP	1.0	
12/10/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/11/2014 OVERFLOWING REPLACED PUMP & CABLE 2.0 12/12/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0	12/09/2014	LIGHT/ALARM	REPLACED PUMP	1.5	
12/11/2014 OVERFLOWING REPLACED PUMP & CABLE 2.0 12/12/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0	12/09/2014	OVERFLOWING	REPLACED PUMP & EQD	1.0	
12/12/2014 CLOGGED LINE LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE 2.5 12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0	12/10/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
12/12/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0		OVERFLOWING	REPLACED PUMP & CABLE		
12/14/2014 LIGHT/ALARM REPLACED PUMP 3.0 YES 12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0		CLOGGED LINE	LINE BLOCKED, USED JETTER TO REMOVE BLOCKAGE	2.5	
12/15/2014 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0					YES
12/15/2014 OVERFLOWING REPLACED PUMP, SLIDER VALVE & HOSE 1.0 12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0			<u> </u>		YES
12/16/2014 OVERFLOWING REPLACED PUMP & EQD 2.0		LIGHT/ALARM	REPLACED PUMP	1.0	
		OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE		
12/17/2014 LIGHT/ALARM REPLACED PUMP 1.0		OVERFLOWING	REPLACED PUMP & EQD	2.0	
	12/17/2014	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
12/19/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
12/22/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
12/22/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
12/22/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
12/23/2014	STATION MAKING NOISE	STATION CHECKED OKAY.	1.0	
12/26/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
12/26/2014	LIGHT/ALARM	REPLACED PUMP	3.0	YES
12/26/2014	LIGHT/ALARM	REPLACED PUMP	2.0	YES
12/26/2014	OVERFLOWING	REPLACED PUMP & EQD	2.0	YES
12/26/2014	OVERFLOWING	RESET BREAKERS	2.0	YES
12/29/2014	LIGHT/ALARM	REPLACED PUMP	1.0	
12/31/2014	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
01/02/2015	LICUT/ALADAA	DEDIACED DUMB	(HOURS)	HOURS
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0	
	LIGHT/ALARM		1.0	
	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP		
	OVERFLOWING	REPLACED PUMP	1.0	
01/07/2015	GMF	REPLACED PUMP	1.0	
			1.0	
	OVERFLOWING LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & VENT CAP REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	TES
01/10/2015	LIGHT/ALARM	REPLACED PUMP	4.5	YES
	OVERFLOWING		1.0	TES
		REPLACED PUMP & CABLE		
	LIGHT/ALARM GMF	REPLACED PUMP	1.0	
		REPLACED PUMP		
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	SEWER BACKING UP	CLOGGED LINE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	1/50
	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	3.0	YES
	OVERFLOWING	CLOGGED LINE ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP NOT WORKING	REPLACED PUMP	1.0	
	SEWER BACKING UP	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	SEWER BACKING UP	REPLACED PUMP	1.0	
01/21/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
01/21/2015	PUMP NOT WORKING	STATION CHECKED OKAY. PROBLEM ON CUSTOMER' SIDE.	1.0	
01/22/2015	OVERFLOWING	ISSUE ON THE CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	GRINDER NOT WORKING	REPLACED PUMP, CONTROL BOARD & CABLE ENDS	2.5	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	POWER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	ISSUE ON THE CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	RESET BREAKERS	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	1.25
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	FROZEN SERVICE LINE/THAWED LINE	1.0	
	OVERFLOWING	NO POWER ON THE CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	GROUND WATER DUE TO SNOW AND RAIN	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	11.3
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
	LIGHT/ALARM	ISSUE ON THE CUSTOMER'S SIDE	1.0	
02/2//2013	LIOTH/ALANIVI	1930F OIM THE COSTOINIER 3 SINE	1.0	

0.798/1015 USHT/ALARIM	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
03/03/2015 DORRELOWING SSUE ON THE CUSTOMERS SIDE 1.0		LIGHT/ALARM	REPLACED PUMP	1.0	
03/04/2015 UIGHT/ALARM		LIGHT/ALARM	REPLACED PUMP	4.0	YES
03/04/2015 UGHT/ALARM					
B3/04/2015	03/03/2015	SEWER BACKING UP	ISSUE ON THE CUSTOMER'S SIDE	1.0	
03/04/2015 UGHT/ALARM	03/04/2015	LIGHT/ALARM	LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY	1.0	
03/07/2015 USHFI/QAIRM	03/04/2015	LIGHT/ALARM	LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY	1.0	
0.3098/2015 OVERFLOWING NO POWER ON CUSTOMER'S SIDE 1.0	03/04/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
03/09/2015 OKER-LOWING	03/07/2015	LIGHT/ALARM	REPLACED PUMP	4.0	YES
03/09/2015 UGHT/ALARM		OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
SAMPADIOS GIGHT/ALARM REPLACED PUMP 1.0		OVERFLOWING	REPLACED 4 PUMPS		
0.30972015 IGHT/ALARM			REPLACED PUMP		
03/11/2015 OVERTIOWING REPLACED PUMP 3.0 YES 03/11/2015 UGHT/ALARM REPLACED PUMP SLORE VALVE & HOSE 1.0 03/13/12015 UGHT/ALARM REPLACED PUMP 3.0 YES 03/13/2015 UGHT/ALARM REPLACED PUMP 3.0 YES 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/13/2015 UGHT/ALARM REPLACED PUMP 1.0 03/20/2015 UGHT/ALARM REPLACED PUMP 3.0 YES 03/23/2015 UGHT/ALARM REPLACED PUMP 3.0 YES 03/23					
03/13/2015 USHT/IALARM REPLACED PUMP & CONTROL BOADD 4.0 YES 03/13/2015 USHT/IALARM REPLACED PUMP 3.0 YES 03/13/2015 USHT/IALARM REPLACED PUMP 3.0 YES 03/16/2015 USHT/IALARM REPLACED PUMP 1.0 03/16/2015 USHT/IALARM REPLACED PUMP 1.0 03/16/2015 USHT/IALARM REPLACED PUMP 1.0 03/16/2015 USHT/IALARM REPLACED PUMP 1.0 03/16/2015 USHT/IALARM REPLACED PUMP 1.0 03/16/2015 USHT/IALARM REPLACED PUMP 1.0 03/17/2015 USHT/IALARM REPLACED PUMP 1.0 03/18/2015 USHT/IALARM REPLACED PUMP 1.0 03/18/2015 USHT/IALARM REPLACED PUMP & CABLE 0.5 03/18/2015 USHT/IALARM REPLACED PUMP & CABLE 0.5 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.5 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.5 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE END 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE END 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE END 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE END 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE END 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE END 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE END 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & CABLE 0.0 03/19/2015 USHT/IALARM REPLACED PUMP & C					
0.3/14/2015 UGHT/ALARM					
03/14/2015 UGHT/ALARM					YES
03/16/2015 LIGHT/ALARM					
0.3/16/2015 LIGHT/ALARM REPLACED PUMP 1.0					YES
0.3/17/2015 UDETF/ALARM REPLACED PUMP 1.0					
03/17/2015 LIGHT/ALARM					
03/18/2015 LIGHT/ALARM					
03/18/2015 UIGHT/ALARM					
0.5 0.5		·			
03/13/2015 IGHT/ALARM					
03/19/2015 IGHT/ALARM REPLACED PUMP 1.0					
03/13/2015 IJGHT/ALARM		•			
03/20/2015 UIGHT/ALARM				-	
03/20/2015 LIGHT/ALARM REPLACED PUMP 1.0					
03/20/2015 LIGHT/ALARM REPLACED PUMP 3.0 YES					
03/21/2015 LIGHT/ALARM REPLACED PUMP 1.0					
03/23/2015 LIGHT/ALARM					VEC
03/24/2015 LIGHT/ALARM					YES
03/24/2015 USERFLOWING REPLACED PUMP & CABLE 1.0					
03/25/2015 LIGHT/ALARM REPLACED PUMP 1.0					
03/26/2015 LIGHT/ALARM REPLACED PUMP 1.0					VEC
03/26/2015 LIGHT/ALARM REPLACED PUMP & EQD END 1.0					ILJ
03/27/2015 LIGHT/ALARM REPLACED PUMP 1.0					
03/27/2015 LIGHT/ALARM REPLACED PUMP 1.0 03/28/2015 LIGHT/ALARM REPLACED PUMP 1.0 03/30/2015 LIGHT/ALARM RESET BREAKERS 1.0 03/31/2015 LIGHT/ALARM REPLACED PUMP 0.5 03/31/2015 LIGHT/ALARM REPLACED PUMP & VENT CAP 0.5 04/01/2015 LIGHT/ALARM REPLACED PUMP & VENT CAP 0.5 04/02/2015 LIGHT/ALARM REPLACED PUMP & VENT CAP 0.5 04/03/2015 LIGHT/ALARM REPLACED PUMP 3.0 YES 04/03/2015 LIGHT/ALARM REPLACED PUMP, CABLE, CONTROL BOARD. CLEANED 4.0 STATION DUE TO BABY WIPES. 4.0 YES 04/04/02015 LIGHT/ALARM LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY 4.0 YES 04/06/2015 LIGHT/ALARM REPLACED PUMP 3.0 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP & EQD 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP & EQD 1.0 04/07/2015 OVERFLOWING REPLACED PUMP & DOWNER ISSUE ON CUSTOMER'S					
03/28/2015 LIGHT/ALARM REPLACED PUMP 1.0 03/30/2015 LIGHT/ALARM RESET BREAKERS 1.0 03/31/2015 LIGHT/ALARM REPLACED PUMP 0.5 03/31/2015 LIGHT/ALARM REPLACED PUMP & VENT CAP 0.5 04/01/2015 LIGHT/ALARM REPLACED PUMP 3.0 YES 04/02/2015 LIGHT/ALARM REPLACED PUMP 1.0 1.0 04/03/2015 LIGHT/ALARM REPLACED PUMP, CABLE, CONTROL BOARD. CLEANED STATION DUE TO BABY WIPES. 4.0 4.0 04/04/2015 LIGHT/ALARM LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY 4.0 YES 04/06/2015 LIGHT/ALARM REPLACED PUMP 3.0 4.0 YES 04/06/2015 LIGHT/ALARM REPLACED PUMP 1.0 4.0 YES 04/06/2015 LIGHT/ALARM REPLACED PUMP & EQD 1.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0 4.0		•			
03/30/2015 LIGHT/ALARM RESET BREAKERS 1.0					
03/31/2015 LIGHT/ALARM REPLACED PUMP 0.5					
03/31/2015 LIGHT/ALARM REPLACED PUMP & VENT CAP 0.5 04/01/2015 LIGHT/ALARM REPLACED PUMP 3.0 YES 04/02/2015 LIGHT/ALARM REPLACED PUMP 1.0 1.0 04/03/2015 LIGHT/ALARM REPLACED PUMP, CABLE, CONTROL BOARD. CLEANED STATION DUE TO BABY WIPES. 4.0 4.0 04/04/2015 LIGHT/ALARM LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY 4.0 YES 04/06/2015 LIGHT/ALARM REPLACED PUMP 3.0 4.0 04/06/2015 LIGHT/ALARM REPLACED PUMP 3.0 4.0 04/06/2015 LIGHT/ALARM REPLACED PUMP 1.0 4.0 04/06/2015 LIGHT/ALARM REPLACED PUMP & EQD 1.0 4.0 04/06/2015 LIGHT/ALARM REPLACED PUMP P. POWER ISSUE ON CUSTOMER'S SIDE 1.0 4.0 04/09/2015 LIGHT/ALARM REPLACED PUMP 1.0 4.0 4.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 4.0 4.0 4.0 4.0 4.0 4.0					
04/01/2015 LIGHT/ALARM REPLACED PUMP 3.0 YES 04/02/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/03/2015 LIGHT/ALARM REPLACED PUMP, CABLE, CONTROL BOARD. CLEANED STATION DUE TO BABY WIPES. 4.0 04/04/2015 LIGHT/ALARM LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY 4.0 YES 04/06/2015 LIGHT/ALARM REPLACED PUMP 3.0 3.0 3.0 4.0 4.0 YES					
04/02/2015 LIGHT/ALARM REPLACED PUMP, CABLE, CONTROL BOARD. CLEANED STATION DUE TO BABY WIPES. 4.0 04/03/2015 LIGHT/ALARM LIGHT ON DUE TO BABY WIPES. 4.0 04/04/2015 LIGHT/ALARM LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY 4.0 YES 04/06/2015 LIGHT/ALARM REPLACED PUMP 3.0 3.0 3.0 4.0 4.0 4.0 YES YES 4.0 YES <					YFS
04/03/2015 LIGHT/ALARM REPLACED PUMP, CABLE, CONTROL BOARD. CLEANED STATION DUE TO BABY WIPES. 4.0 04/04/2015 LIGHT/ALARM LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY 4.0 YES 04/06/2015 LIGHT/ALARM REPLACED PUMP 3.0 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP & EQD 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP. POWER ISSUE ON CUSTOMER'S SIDE 1.0 04/07/2015 OVERFLOWING REPLACED PUMP 1.0 04/08/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/09/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES		,			123
04/04/2015 LIGHT/ALARM LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY 4.0 YES 04/06/2015 LIGHT/ALARM REPLACED PUMP 3.0 04/06/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP & EQD 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP. POWER ISSUE ON CUSTOMER'S SIDE 1.0 04/07/2015 OVERFLOWING REPLACED PUMP 1.0 04/08/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/09/2015 LIGHT/ALARM ALARM ON DUE TO STORM. STATION WORKING PROPERLY. 1.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0			REPLACED PUMP, CABLE, CONTROL BOARD. CLEANED		
04/06/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP & EQD 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP. POWER ISSUE ON CUSTOMER'S SIDE 1.0 04/07/2015 OVERFLOWING REPLACED PUMP 1.0 04/08/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/09/2015 LIGHT/ALARM ALARM ON DUE TO STORM. STATION WORKING PROPERLY. 1.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0	04/04/2015	LIGHT/ALARM		4.0	YES
04/06/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP & EQD 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP. POWER ISSUE ON CUSTOMER'S SIDE 1.0 04/07/2015 OVERFLOWING REPLACED PUMP 1.0 04/08/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/09/2015 LIGHT/ALARM ALARM ON DUE TO STORM. STATION WORKING PROPERLY. 1.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0	04/06/2015	LIGHT/ALARM	REPLACED PUMP	3.0	
04/06/2015 LIGHT/ALARM REPLACED PUMP & EQD 1.0 04/06/2015 LIGHT/ALARM REPLACED PUMP. POWER ISSUE ON CUSTOMER'S SIDE 1.0 04/07/2015 OVERFLOWING REPLACED PUMP 1.0 04/08/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/09/2015 LIGHT/ALARM ALARM ON DUE TO STORM. STATION WORKING PROPERLY. 1.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0					
04/06/2015 LIGHT/ALARM REPLACED PUMP. POWER ISSUE ON CUSTOMER'S SIDE 1.0 04/07/2015 OVERFLOWING REPLACED PUMP 1.0 04/08/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/09/2015 LIGHT/ALARM ALARM ON DUE TO STORM. STATION WORKING PROPERLY. 1.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0					
04/08/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/09/2015 LIGHT/ALARM ALARM ON DUE TO STORM. STATION WORKING PROPERLY. 1.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0					
04/08/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/09/2015 LIGHT/ALARM ALARM ON DUE TO STORM. STATION WORKING PROPERLY. 1.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0	04/07/2015	OVERELOWING	REPLACED PUMP	1.0	
04/09/2015 LIGHT/ALARM ALARM ON DUE TO STORM. STATION WORKING PROPERLY. 1.0 04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0					
04/09/2015 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 0.5 04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0			ALARM ON DUE TO STORM. STATION WORKING		
04/09/2015 LIGHT/ALARM REPLACED PUMP DUE TO GREASE ISSUE 1.0 04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0	04/09/2015	LIGHT/ALARM		0.5	
04/10/2015 LIGHT/ALARM REPLACED PUMP 1.0 04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0					
04/11/2015 CUSTOMER ISSUE NO POWER ON CUSTOMER'S SIDE 3.0 YES 04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0					
04/13/2015 LIGHT/ALARM REPLACED PUMP 1.0					YES
	04/13/2015	OVERFLOWING	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
04/14/2015	OVERFLOWING	REPLACED PUMP	4.0	YES
		SLIP ON CUSTOMER'S PROPERTY CAUSED DAMAGE TO		
04/14/2015	OVERFLOWING	STATION. CUSTOMER REPAIRING HIS SIDE. REPLACED	2.0	
		PUMP & CABLE END		
04/14/2015	OVERFLOWING	STATION WORKING PROPERLY. RAIN WATER	1.0	
		OVERTAKING STATION AND PUMP CANT KEEP UP.		
04/15/2015	LIGHT/ALARM	LIGHT ON DUE TO RAIN. STATION WORKING PROPERLY	1.0	
04/16/2015	BREAKER ISSUE	RESET BREAKERS DUE TO STORM	1.0	
04/17/2015	LIGHT/ALARM	BREAKER ISSUE DUE TO STORM	3.0	YES
04/17/2015	OVERFLOWING	BREAKER ISSUE ON THE CUSTOMER'S SIDE	1.0	
04/17/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
04/18/2015	OVERFLOWING	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
04/18/2015	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
04/18/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
04/20/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
04/20/2015	SEWER BACKING UP	REPLACED PUMP, REPAIRED LEAK ON STATION,	2.0	
		REPLACED SLIDER VALVE & HOSE		\/
04/21/2015	LIGHT/ALARM	REPLACED PUMP AND VENT CAP	3.0	YES
04/22/2015	OVERFLOWING	REPLACED PUMP	1.0	
04/23/2015	OVERFLOWING	REPLACED PUMP	1.0	
04/23/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
04/23/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
04/24/2015	OVERFLOWING	BREAKER ISSUE ON THE CUSTOMER'S SIDE	1.0	
04/24/2015	LIGHT/ALARM	REPLACED PUMP	1.0	1/50
04/24/2015	LIGHT/ALARM	REPLACED PUMP, BOARD, CABLE	2.0	YES
04/25/2015	LIGHT/ALARM	REPLACED PUMP & EQD END	2.0	VEC
04/26/2015	LIGHT/ALARM	REPLACED PUMP	4.0	YES
04/28/2015	BREAKER ISSUE	WEAK BREAKER ON CUSTOMER'S SIDE	1.0 3.0	VEC
05/01/2015 05/02/2015	OVERFLOWING LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	4.0	YES YES
05/02/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/02/2015	LIGHT/ALARM	REPLACED PUMP	1.0	TES
05/04/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/04/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/04/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/04/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/05/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/05/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	SEWER BACKING UP	REPLACED 4 PUMPS & MOTOR CONTROL	2.0	
05/08/2015	OVERFLOWING	REPLACED PUMP	1.5	
05/09/2015	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/11/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/11/2015	OVERFLOWING	STATION CHECKED OUT OKAY	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/12/2015	SEWER BACKING UP	REPLACED PUMP	1.0	
05/12/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/12/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/13/2015	OVERFLOWING	REPLACED PUMP	1.0	
05/13/2015	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
05/15/2015	LIGHT/ALARM	NOT ENOUGH POWER ON THE CUSTOMER'S SIDE. 110	1.0	
05/15/2015	LICUT/ALADAA	INSTEAD OF 220	4.0	VEC
05/15/2015	LIGHT/ALARM	REPLACED PUMP	4.0	YES
05/15/2015	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP, CLEANED STATION WHICH WAS	1.0	
05/15/2015	STATION NOT WORKING	FULL OF BABY WIPES	1.0	
05/16/2015	GMF	REPLACED PUMP	1.0	
05/16/2015	LIGHT/ALARM	REPLACED PUMP	5.0	YES
05/16/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/17/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/17/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/18/2015	LIGHT/ALARM	STATION CHECKED OUT OKAY	1.0	
05/19/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/21/2015	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
05/21/2015	LIGHT/ALARM	REPLACED PUMP	1.0	HOURS
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/23/2015	LIGHT/ALARM	REPLACED PUMP & EQD END	2.0	YES
		REPLACED PUMP, REPAIRED SLIDER VALVE, REPLACED		
05/23/2015	OVERFLOWING	CONTROL BOARD & CABLE	5.0	YES
05/26/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
05/28/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/28/2015	OVERFLOWING	REPLACED PUMP	1.0	
05/29/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
05/29/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
06/01/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
06/01/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP, CABLE, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	0.5	
06/09/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
06/09/2015	LIGHT/ALARM	REPLACED PUMP	2.0	
	OVERFLOWING	REPLACED PUMP & EQD END	2.0	
06/09/2015	LIGHT/ALARM	REPLACED PUMP & EQD END	1.0	
06/09/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
06/10/2015	LIGHT/ALARM	REPLACED PUMP	1.5	
06/10/2015	LIGHT/ALARM	REPLACED PUMP & EQD END	1.5	
06/10/2015	LIGHT/ALARM	REPLACED PUMP & VENT CAP	2.0	
06/11/2015	LIGHT/ALARM	REPLACED PUMP, VENT CAP, SLIDER VALVE & HOSE	2.0	
06/13/2015	LIGHT/ALARM	REPLACED PUMP & VENT CAP	4.0	YES
06/13/2015	LIGHT/ALARM	REPLACED PUMP. EQD END, SLIDER VALVE & HOSE	2.0	
06/15/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
06/15/2015	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
06/16/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
06/17/2015	CUSTOMER ISSUE	NO POWER ON CUSTOMER'S SIDE	1.0	
06/17/2015	OVERFLOWING	REPLACED 2 PUMPS. SLIDER VALVE & HOSES. HAD TO	3.0	
00/17/2013	OVERILOWING	CLEAN STATIONS.	3.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
06/18/2015	OVERFLOWING	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP & EQD END	1.0	
	OVERFLOW	NO POWER ON THE CUSTOMER'S SIDE	3.5	YES
	LIGHT/ALARM	REPLACED CABLE AND CONTROL BOARD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD END	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD END	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP THAT WAS IN ALARM STAGE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
06/27/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	LIGHT/ALARM	REPLACED PUMP	0.5	
	OVERFLOWING	NO POWER ON THE CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
06/29/2015	LIGHT/ALARM	REPLACED PUMP DUE TO DAMAGE BY BABY WIPES	2.0	
	LIGHT/ALARM	REPLACED PUMP, CHECKED FOR FLOW RESTRICTION	1.0	
	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE	2.5	YES
	GMF	STATION CHECKED OUT OKAY	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
07/02/2015	ODOR	REPLACED PUMP & CABLE END	1.0	
07/02/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
07/03/2015	OVERFLOWING	ISSUE ON THE CUSTOMER'S SIDE	3.0	YES
	OVERFLOWING	REPLACED PUMP & EQD	2.0	YES
07/04/2015	LIGHT/ALARM	ISSUE ON THE CUSTOMER'S SIDE	1.0	
07/04/2015	LIGHT/ALARM	REPLACE PUMP & CABLE END	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACE PUMP	1.0	
07/07/2015		REPLACED PUMP & EQD END	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	5.0	YES
07/10/2015		REPLACED PUMP & CABLE	1.5	ILJ
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	NO POWER ON THE CUSTOMER'S SIDE DUE TO STORM	1.0	TES
07/12/2015	LICUT/ALADAA	DEDI ACED CONTROL DOADD	1.0	
	LIGHT/ALARM	REPLACED CONTROL BOARD	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	OVERFLOWING	REPLACED PUMP & CABLE DUE TO STORM	2.0	
07/13/2015	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
07/13/2015	BREAKER ISSUE - POWER BEEN OUT DUE TO STORM	REPLACED PUMP, CONTROL BOARD & EQD	2.0	
	LIGHT/ALARM	STATION CHECKED OUT OKAY. LIGHT/ALARM DUE TO STORM	1.0	
07/13/2015	GMF	REPLACED PUMP, BOARD & CABLE	1.5	
07/14/2015	LIGHT/ALARM	NO POWER ON THE CUSTOMER'S SIDE DUE TO STORM	1.0	
07/14/2015	LIGHT/ALARM	NO POWER ON THE CUSTOMER'S SIDE DUE TO STORM	1.0	
07/14/2015	PUMP NOT WORKING - POWER BEEN OFF DUE TO STORM	REPLACED PUMP	1.0	
07/14/2015	PUMP RUNNING CONSTANTLY	REPLACED PUMP	1.0	
07/14/2015	LIGHT/ALARM	REPLACED PUMP, BOARD, CABLES	2.0	
07/14/2015	GMF	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
07/15/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
07/15/2015	LIGHT/ALARM	REPLACED PUMP	2.0	
07/15/2015	OVERFLOWING - POWER BEEN OFF DUE TO STORM	REPLACED PUMP	1.0	
07/15/2015	LIGHT/ALARM	REPLACED PUMP	1.5	
07/15/2015	GMF	REPLACED PUMP & CABLE	1.0	
	PUMP NOT WORKING - POWER BEEN OFF			
07/15/2015	DUE TO STORM	REPLACED PUMP & CABLE	2.0	
07/15/2015 07/15/2015	LIGHT/ALARM GMF	REPLACED PUMP & EQD END REPLACED PUMP, CONTROL BOARD & CABLE	1.0 1.0	
07/15/2015	LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & CABLE REPLACED PUMP, REPAIRED SLIDER VALVE	2.0	
	LIGHT/ALARM	REPLACED PUMP, BOARD & CABLE	2.0	YES
			2.5	TES
07/16/2015	POWER OFF DUE TO STORM	REPLACED PUMP & CABLE	2.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
07/16/2015	GMF	REPLACED PUMP & EQD	1.5	
07/16/2015	LIGHT/ALARM	REPLACED PUMP, CLEANED STATION WHICH WAS	2.0	
07/16/2015	GMF	FULL OF WIPES AND FEMALE PRODUCTS REPLACED PUMP, CONTROL BOARD & EQD	2.0	
		REPLACED PUMP, CABLE & BOARD. POWER HAD BEEN		
07/16/2015	GMF	OUT DUE TO STORM.	2.5	
07/17/2015	OVERFLOWING	NO POWER ON THE CUSTOMER'S SIDE	1.0	
	1	REPLACED PUMP	2.5	YES
07/17/2015	LIGHT/ALARM	REPLACED PUMP & CABLE REPLACED PUMP & CLEANED OUT STATION DUE TO	1.0	
07/17/2015	GMF	WIPES, FEMALE PRODUCTS, CONDOMS & NEEDLES IN	2.0	
	STATION IS FULL	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP & EQD END	2.0	
	LIGHT/ALARM	REPLACED PUMP, CABLE & BOARD	4.0	YES
	LIGHT/ALARM OVERFLOWING	REPLACED PUMP, VENT CAP REPLACED PUMP	1.0 2.0	YES
	OVERFLOWING	NO POWER ON THE CUSTOMER'S SIDE	1.0	TES
07/20/2015		NO POWER ON THE CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
07/20/2015	1	REPLACED PUMP	1.5	
07/20/2015	ODOR	REPLACED PUMP, EQD END	1.0	
07/21/2015	LIGHT/ALARM	REPLACED PUMP & EQD END	2.0	
07/22/2015	LIGHT/ALARM	REPLACED PUMP & EQD END	2.0	
07/22/2015	GMF	REPLACED PUMP, EQD END, SLIDER VALVE & HOSE	2.0	
07/22/2015	LIGHT/ALARM	REPLACED PUMP, EQD END, SLIDER VALVE & HOSE.CLEARED BLOCKED LINE	1.0	
07/23/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & EQD END	2.0	
	POWER ISSUE ON CUSTOMER'S SIDE LIGHT/ALARM	REPLACED PUMP, CONTROL BOARD & EQD REPLACED PUMP, REPAIRED EQD END	1.5 1.0	
07/23/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
07/24/2015	OVERFLOWING	REPLACED PUMP	1.0	
07/24/2015	GMF	REPLACED PUMP	1.0	
07/24/2015	GMF	REPLACED PUMP	1.0	
07/24/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
07/25/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP, CONTROL BOARD & EQD	2.0	
	PUMP ISSUES	REPLACED PUMP. EQD & CONTROL BOARD	1.5	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP & EQD	1.0 1.5	
07/29/2015	OVERFLOWING	RESET STATION	4.0	YES
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	0.5	
07/30/2015	LIGHT/ALARM	NO POWER ON THE CUSTOMER'S SIDE	1.0	
07/30/2015	PUMP NOT WORKING	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
07/30/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
07/30/2015	LIGHT/ALARM	REPLACED PUMP, EQD END & HOUSING	2.0	
07/30/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
07/31/2015	GMF	REPLACED PUMP & CABLE RESET BREAKERS. STATION WORKING PROPERLY	2.0 1.0	
07/31/2015 08/01/2015	PUMP ISSUES	REPLACED PUMP, CABLE, EQD & EQD HOUSING	1.0	
08/01/2015	GMF	REPLACED PUMP. EQD, EQD HOUSING, SLIDER VALVE	4.0	YES
08/01/2015	LIGHT/ALARM	& HOSE STATION CHECKED OUT OKAY	4.0	YES
08/01/2015	GMF	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	IES
08/04/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
08/04/2015	GMF	REPLACED PUMP & EQD	2.0	
08/07/2015	LIGHT/ALARM	REPLACED PUMP	4.0	YES
08/07/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
08/07/2015	OVERFLOWING	REPLACED PUMP	2.0	
08/07/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
08/07/2015	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	YES
08/07/2015	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	2.5	VEC
08/07/2015	LIGHT/ALARM	STATION CHECKED OUT OKAY	5.5	YES

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
08/09/2015	OVERFLOWING	REPLACED PUMP	5.0	YES
08/10/2015	OVERFLOWING	REPLACED PUMP	1.0	
08/10/2015	GMF	REPLACED PUMP	1.0	
08/10/2015	LIGHT/ALARM	REPLACES CONTROL BOARD	1.0	
08/11/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
08/11/2015	GMF	REPLACED PUMP	1.0	
08/12/2015	GMF	REPLACED PUMP	2.0	
08/12/2015	GMF	REPLACED PUMP	1.0	
08/13/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
08/13/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
08/14/2015	LIGHT/ALARM	REPLACED PUMP/ALARM STAGE	2.0	
08/15/2015	OVERFLOWING	RESET BREAKER. STATION WORKING PROPERLY	3.0	YES
	OVEREI OWING	STATION WORKING PROPERLY. DISCHARGE HOSE HAD	3.0	VEC
08/16/2015	OVERFLOWING	CUSTOMER'S 4" LINE BLOCKED.	3.0	YES
08/17/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
08/17/2015	OVERFLOWING	REPLACED PUMP, EQD & CABLE	1.0	
08/19/2015	LIGHT/ALARM	REPAIRED VALVE IN THE BARRELL	1.0	
	OVERFLOWING	REPLACED CONTROL BOARD	1.0	
<u> </u>	LIGHT/ALARM	REPLACED PUMP	1.0	
08/19/2015	OVERFLOWING	REPLACED PUMP	1.0	
08/19/2015	ODOR & CANT FLUSH TOILETS	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.5	
08/20/2015	GMF	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	ILJ
	PUMP NOT WORKING	REPLACED PUMP & CABLE	2.0	YES
	LIGHT/ALARM		4.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP REPLACED PUMP, EQD & VENT CAP		YES YES
			2.0 1.0	YES
	SEWER BACKING UP	NO POWER ON CUSTOMER'S SIDE		
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	3.0	VEC
	OVERFLOWING	REPLACED PUMP	3.0	YES
08/24/2015	GMF	REPLACED PUMP	1.0	
08/25/2015	GMF	REPLACED PUMP	1.0	
08/26/2015	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
08/27/2015	OVERFLOWING	REPLACED PUMP	2.0	VEC
08/28/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
08/29/2015	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
<u> </u>	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	3.0	YES
<u> </u>	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/04/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
09/05/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
09/05/2015	OVERFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
09/08/2015	OVERFLOWING	POSSIBLE LEAK. NOTHING FOUND ON MWD SIDE.	1.0	
		POSSIBLE 4" LINE BROKEN ON CUSTOMER'S SIDE.	1.0	
09/08/2015	LIGHT/ALARM	REPLACED PUMP	2.0	
09/08/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
09/08/2015	OVERFLOWING	REPLACED PUMP & EQD	1.5	
09/08/2015	LIGHT/ALARM	STATION CHECKED OUT OKAY	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
09/09/2015	OVERFLOWING	NO ONE LIVING IN HOUSE SINCE MAY, 2014. DISCONNECTED STATION & INSTALLED 4" PLUG.	0.5	
09/09/2015	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	GMF	REPLACED PUMP	1.0	
09/09/2015	GMF	REPLACED PUMP	1.0	
09/09/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED SLIDER HOSE	1.0	
	LIGHT/ALARM	REPLACED SLIDER VALVE	1.5	
09/10/2015	GMF	REPLACED PUMP	3.0	YES
09/11/2015	OVERFLOWING	BREAKERS WERE OFF IN CONTROL BOX. RESET BREAKERS.	1.0	
09/11/2015	GMF	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	0.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	SEWER BACKING UP	NO POWER ON CUSTOMER'S SIDE	0.5	
	GMF	REPLACE PUMP & CONTROL BOARD	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
, ,	LIGHT/ALARM	REPLACED PUMP	1.0	
09/14/2015	ODOR	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP & EQD END REPLACED PUMP	1.0 0.5	
			1.0	
	OVERFLOWING OVERFLOWING	REPLACED PUMP REPLACED PUMP & EQD	2.0	
		·	4.0	YES
	OVERFLOWING LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0	TES
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	BREAKER ISSUE	REPLACED BREAKERS	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	ODOR/ALARM	REPLACED PUMP	1.0	123
	LIGHT/ALARM	REPLACED PUMP, REBURIED CABLE	1.0	
	GMF	REPLACED PUMP	4.0	YES
09/19/2015	GMF	REPLACED PUMP & CABLE END	2.0	
09/19/2015	GMF	REPLACED PUMP & CABLE END	2.0	
09/20/2015	GMF	REPLACED PUMP & CABLE END	2.0	YES
09/20/2015	GMF	REPLACED PUMP AND VENT CAP	4.0	YES
09/21/2015	OVERFLOWING	REPLACED EQD	1.0	
09/21/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
09/21/2015	OVERFLOWING	REPLACED PUMP	1.0	
	GMF	REPLACED PUMP, CABLE END & CONTROL BOARD	3.0	YES
09/22/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	\/EC
	OVERFLOWING	REPLACED PUMP, CABLE & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD END	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING OVERFLOWING	REPLACED PUMP & CONTROL BOARD REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP & CABLE END	2.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE END	2.0	
	LIGHT/ALARM	REPLACED PUMP, CABLE END AND CONTROL BOX	2.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.5	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
TO/03/2013				

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
10/07/2015	LIGHT/ALARM	REPLACED PUMP	1.0	1100113
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/10/2015	LIGHT/ALARM	REPLACED PUMP	4.0	YES
10/10/2015	LIGHT/ALARM	REPLACED PUMP	4.0	YES
10/12/2015	LIGHT/ALARM	REPLACED PUMP, CABLE, SLIDER VALVE & HOSE	2.0	
10/12/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
10/13/2015	LIGHT/ALARM	NO ONE LIVING IN HOUSE. SILENCED ALARM	0.5	
10/14/2015	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
10/14/2015	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/14/2015	LIGHT/ALARM	REPLACED PUMP & CABLE END	3.0	YES
10/15/2015	LIGHT/ALARM	REPLACED PUMP	4.0	YES
10/16/2015	LIGHT/ALARM	REPLACE PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/17/2015	PUMP RUNNING CONSTANTLY	REPLACED PUMP	4.0	YES
	OVERFLOWING	STATION WORKING PROPERLY. ISSUE ON CUSTOMER'S	3.0	YES
	OVERFLOWING	SIDE. REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	4.0	YES
	LIGHT/ALARM LIGHT/ALARM		_	153
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0 1.0	
	PUMP NOT WORKING PROPERLY	REPLACED PUMP & CABLE	3.0	
	OVERFLOWING	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.5	
10/23/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
10/23/2015	LIGHT/ALARM	REPLACED PUMP DUE TO GREASE AND BABY WIPES IN STATION	1.5	
10/24/2015	LIGHT/ALARM	REPLACED CONTROL BOARD & CABLE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	120
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	GRINDER MAKING NOISES	REPLACED PUMP	1.0	123
	LIGHT/ALARM	REPLACED PUMP. CABLE, EQD & HOUSING	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	11.5
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACE PUMP	2.0	
	PUMP NOT WORKING	REPLACED PUMP	2.0	
11/04/2013	POINT NOT WORKING	REPLACED PUMP, CHANGED HOUSING ON SUPPLY	2.0	
11/04/2015	LIGHT/ALARM	SIDE	1.5	
11/05/2015	LIGHT/ALARM	REPLACE PUMP	1.5	
11/05/2015	LIGHT/ALARM	REPLACED PUMP, DUG UP & OPENEND BLOCKED LINE	2.0	
11/05/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
11/05/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
11/06/2015	OVERFLOWING	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP, CABLE & BOARD	2.0	
	BREAKER ISSUE	CHANGED PUMP, SLIDER VALVE & HOSE	2.0	
	PUMP RUNNING CONSTANTLY	REPLACED PUMP	1.0	
11/10/2015	OVERFLOWING	REPLACED PUMP & EQD	2.0	
11/12/2015	OVERFLOWING	BREAKERS WERE OFF. STATION WORKING PROPERLY	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	
11/13/2015	LIGHT/ALARM	REPLACED PUMP, EQD & HOUSING	3.0	
11/14/2015	LIGHT/ALARM	REPLACED PUMP, EQD & HOUSING	2.0	YES
11/14/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE, HOSE, EQD & HOUSING	3.0	YES
11/15/2015	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	CLEANED PUMP & EQD	3.5	
	OVERFLOWING	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.5	
,,013	1	2.012.0 a Equ	1.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	GMF	REPLACED PUMP & CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE, HOSE & CABLE	2.0	YES
11/21/2015	OVERFLOWING	REPLACED PUMP JETTED SEWER LINES TO CLEAR CLOG. LINES NOW	3.0	YES
11/23/2015	OVERFLOWING	FLOWING PROPERLY.	2.0	
11/24/2015	LIGHT/ALARM	REPLACED PUMP	2.0	
11/24/2015	LIGHT/ALARM	REPLACED PUMP, CONVERTED FROM GATOR TO EXTREME	1.0	
	ODOR	RESET BREAKERS	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	SEWER BACKING UP	REPLACED PUMP	3.0	
	OVERFLOWING	REPLACED PUMP	3.0	
	LIGHT/ALARM	REPLACED PUMP, EQD & HOUSING	2.5	
	LIGHT/ALARM	REPLACED PUMP, EQD & HOUSING	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	
	GMF	REPLACED PUMP	2.0	
	GMF	REPLACED PUMP	1.0	
	GMF	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD END	5.0	YES
	LIGHT/ALARM	REPLACED PUMP, EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	1/50
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
	OVERFLOWING	REPLACED PUMP	3.0	YES
12/05/2015 12/06/2015	GRINDER MALFUNCTION (GMF) OVERFLOWING	REPLACED PUMP & EQD END BREAKERS WERE OFF. STATION WORKING PROPERLY	5.0 3.0	YES YES
	LIGHT/ALARM	REPLACED PUMP	2.0	
12/07/2015	OVERFLOWING	REPLACED PUMP	1.0	
12/07/2015	LIGHT/ALARM	REPLACED PUMP, SHORTENED CABLE	4.0	
12/08/2015	STATION NOT WORKING	NO POWER ON THE CUSTOMER'S SIDE	1.0	
12/08/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
12/08/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM OVERFLOWING/LIGHT ON FOR OVER 3	REPLACED PUMP & EQD END	1.5	
12/08/2015	MONTHS PER NEIGHBOR	REPLACED PUMP, CABLE & BOARD	3.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
12/09/2015	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
12/09/2015 12/09/2015	LIGHT/ALARM OVERFLOWING & RECENT WASHOUT FILLED	REPLACED PUMP & EQD END REPLACED PUMP & EQD END	2.0	
12/10/2015	STN WITH SAND STATION NOT WORKING	BREAKERS WERE OFF. STATION WORKING PROPERLY	1.0	
		DEDI ACED DUAAD		
12/11/2015	LIGHT/ALARM	REPLACED PUMP	1.5	
12/11/2015	LIGHT/ALARM	REPLACED PUMP BREAKERS WERE TRIPPED. TURNED THEM OFF AND	1.5	
12/12/2015	OVERFLOWING	BACK ON AND STATION PUMPED DOWN OKAY AND WORKING PROPERLY	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	STATION IS FULL	NO POWER ON THE CUSTOMER'S SIDE	1.0	
12/14/2015	GMF	REPLACED PUMP	1.0	
12/14/2015	GMF	REPLACED PUMP	2.0	
12/14/2015	OVERFLOWING & VENT CAP RUSTED	REPLACED PUMP & VENT CAP	1.0	
12/16/2015	LIGHT/ALARM	REPLACED PUMP	5.0	YES
12/16/2015	GMF	REPLACED PUMP	2.0	
12/16/2015	GMF	STATION CHECKED OUT OKAY	1.0	

DATE	COMPLAINT	DECOLUTION	COMPLETION TIME	AFTER
DATE	COMPLAINT	RESOLUTION	(HOURS)	HOURS
12/18/2015	LIGHT/ALARM	REPLACED EQD & CONTROL BOARD	1.0	
12/18/2015	PUMP RUNNING CONSTANTLY	REPLACED PUMP	1.0	
12/19/2015	ODOR	STATION CHECKED OUT OKAY	3.0	YES
12/20/2015	GMF	REPLACED PUMP	3.0	
12/21/2015	GMF	REPLACED PUMP	1.0	
12/22/2015	GRINDER MALFUNCTION (GMF)	REPLACED PUMP	1.0	
12/22/2015	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
12/22/2015	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
12/23/2015	GMF	REPLACED PUMP	2.0	
12/23/2015	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
12/25/2015	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
12/26/2015	LIGHT/ALARM	REPLACED PUMP	2.0	YES
12/26/2015	LIGHT/ALARM	REPLACED PUMP	3.0	
12/26/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
12/28/2015	LIGHT/ALARM	REPLACED BULB IN CONTROL BOX	1.0	
12/28/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
12/28/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
12/28/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
12/28/2015	PUMP RUNNING CONSTANTLY	REPLACED PUMP & EQD	1.0	
12/28/2015	ODOR	STATION CHECKED OUT OKAY	1.0	
12/29/2015	LIGHT/ALARM	REPLACED PUMP & EQD END	1.0	
12/29/2015	LIGHT/ALARM	REPLACED PUMP & EQD END	1.0	
12/30/2015	LIGHT/ALARM	REPLACED PUMP	1.0	
12/31/2015	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/01/2016	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	2.0	YES
	LIGHT/ALARM	REPLACED PUMP, CABLE, BOARD & BREAKER	2.0	. 20
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	LIGHT/ALARM	CHECKED OKAY	0.3	
	OVERLFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	OVERLFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	1.5	
01/08/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
01/11/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
01/12/2016	LIGHT/ALARM	REPLACED PUMP	1.5	
01/12/2016	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
01/13/2016	OVERLFLOWING	REPLACED PUMP	2.0	
01/14/2016	CLOGGED LINE	JETTED SEWER LINE FOR BOE AND BILLED THEM	4.0	
01/15/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	3.0	YES
01/18/2016	LIGHT/ALARM	REPLACED PUMP	2.0	
	OVERLFLOWING	REPLACED PUMP	2.0	
	OVERLFLOWING	CHANGED EQD END	2.0	
01/21/2016	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
01/27/2016	OVERLFLOWING	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
01/28/2016	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	3.0	YES
01/29/2016	BREAKER ISSUE	RESET BREAKER	3.0	YES
01/30/2016	LIGHT/ALARM	REPLACED PUMP	3.0	YES
02/01/2016	OVERLFLOWING	REPLACED PUMP & EQD & REPAIRED LEAK	4.0	
02/02/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
02/03/2016	LIGHT/ALARM	CHECKED OKAY	4.0	YES
02/03/2016	STATION BACKING UP	RESET BREAKER	1.0	
02/05/2016	LIGHT/ALARM	REPLACED PUMP & BOARD	1.5	
02/08/2016	LIGHT/ALARM	REPLACED PUMP	2.0	
02/10/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
02/10/2016	LIGHT/ALARM	REPLACED PUMP	2.0	
02/10/2016	LIGHT/ALARM	REPLACED PUMP	2.0	
02/11/2016	LIGHT/ALARM	REPLACED PUMP	2.0	
	OVERLFLOWING	REPLACED PUMP, REPAIRED BLOCKED LINE	10.0	
02/15/2016	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	OVERLFLOWING	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.5	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	0.5	VEC
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	2.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	V/50
	OVERLFLOWING	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	RESET BREAKER	3.0	YES
	LIGHT/ALARM	CHANGED EQD END	2.0	
03/07/2016	OVERLELOWING	REPLACED PUMP & EQD	1.0	
	OVERLFLOWING	REPLACED PUMP	1.0	
03/08/2016	LIGHT/ALARM	REPLACED PUMP	2.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
03/08/2016	LIGHT/ALARM	REPLACED PUMP	2.0	
03/11/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	VEC
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP & EQD	3.0 2.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	ILS
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERLFLOWING	REPLACED PUMP & EQD	1.0	. 20
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	OVERLFLOWING	REPLACED PUMP	1.0	
03/21/2016	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
03/22/2016	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
03/22/2016	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	
	OVERLFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	2.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	OVERLFLOWING	SEWER LINE BLOCKED ON CUSTOMER'S SIDE	1.5	YES
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
03/28/2016	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	2.0	
03/29/2016	OVERLFLOWING	INSTALLED PUMP, REPLACED EQD, HOUSING & CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
03/29/2016	LIGHT/ALARM	REPLACED PUMP, EQD, HOUSING & CABLE	1.0	
03/29/2016	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE, EQD & HOUSING	1.0	
	OVERLFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PIG TAIL	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP EQD & HOUSING	2.0	YES
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0 1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERLFLOWING	REPLACED PUMP, EQD, HOUSING & CABLE	1.0	
	LIGHT/ALARM	CHECKED OKAY	1.0	
04/06/2016	CONTINUOUSLY RUNNING	REPLACED PUMP & EQD	1.0	
04/07/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
04/08/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.5	YES
	OVERLFLOWING	REPLACED PUMP EQD & HOUSING	1.0	
	OVERLFLOWING	CHECKED OKAY	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP, BOARD & EQD	1.0	
	LIGHT/ALARM LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE REPLACED PUMP	0.5 3.0	YES
	BREAKER ISSUE	RESET BREAKER	2.0	YES
	LIGHT/ALARM	REPLACED PUMP & BOARD	3.5	YES
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	123
	LIGHT/ALARM	REPLACED PUMP	3.5	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
04/19/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
04/19/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
04/20/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
04/21/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
04/21/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
04/21/2016	OVERLFLOWING	REPLACED PUMP, BOARD & EQD	1.0	
04/21/2016	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
04/22/2016	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
04/22/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
04/23/2016	LIGHT/ALARM	REPLACED PUMP	3.0	YES
04/25/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
04/25/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERLFLOWING	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERLFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
	OVERLFLOWING	CHECKED OKAY	0.5	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERLFLOWING	REPLACED PUMP	1.0	
<u> </u>	OVERLFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERLFLOWING	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD END, PRESSURE CONNECT	4.0	
	LIGHT/ALARM	TURNED DISCONNECT BACK ON	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & BOARD	3.0	YES
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0 1.0	
	OVERLELOWING	REPLACED PUMP	2.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, HOUSING & BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, HOUSING & BOARD	4.0	YES
	LIGHT/ALARWI	NOT ENOUGH POWER COMING INTO STATION ON	4.0	ILJ
05/19/2016	LIGHT/ALARM	CUSTOMER SIDE	0.5	
05/19/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	BREAKER ISSUE	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERLFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.5	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	2.0	YES
	CLOGGED LINE	JETTED SEWER LINE FOR BOE AND BILLED THEM	5.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERLFLOWING	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	CHECKED OKAY	1.0	
	OVERLFLOWING	REPLACED PUMP & EQD	1.5	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/25/2016	LIGHT/ALARM	REPLACED PUMP, EQD & BREAKERS	2.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
05/26/2016	LIGHT/ALARM	REPLACED PUMP	2.0	YES
05/27/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & BOARD	1.5	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/28/2016	OVERLFLOWING	REPLACED PUMP	3.0	YES

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
05/28/2016	OVERLFLOWING	REPLACED PUMP	3.0	YES
05/29/2016	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/31/2016	PUMP NOT WORKING	NO POWER ON CUSTOMER'S SIDE	0.5	
05/31/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERLFLOWING	REPLACED PUMP	1.5	
	STATION BACKING UP	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.5	
05/31/2016	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
05/31/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	BREAKER ISSUE	REPLACED PUMP EQD & HOUSING	1.5	
05/31/2016	LIGHT/ALARM	RESET BREAKER	1.5	
	LIGHT/ALARM	REPLACED PUMP & BOARD	2.0	
	OVERLFLOWING	REPLACED PUMP EQD & HOUSING	0.5	
06/02/2016	LIGHT/ALARM	REPLACED PUMP	4.5	YES
06/02/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
06/03/2016	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
06/03/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
06/05/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	3.0	YES
	BREAKER ISSUE	NO POWER ON CUSTOMER'S SIDE	4.0	YES
06/06/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
06/08/2016	OVERLFLOWING	REPLACED PUMP & EQD	2.0	
06/08/2016	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
06/08/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
06/09/2016	OVERLFLOWING	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
06/10/2016	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
06/13/2016		REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	BREAKER ISSUE	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	3.0	YES
	OVERLFLOWING	REPLACED PUMP EQD & HOUSING	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	1123
06/18/2016	OVERLELOWING	REPLACED PUMP	2.0	
	STATION BACKING UP	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	
	LIGHT/ALARM	REPLACED PUMP & EQD REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED CABLE AND EQD	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	3.0	YES
		REPLACED PUMP EQD & HOUSING	2.0	TES
	RUNNING CONTINUOUSLY	REPLACED PUMP		YES
	LIGHT/ALARM		3.0	
	LIGHT/ALARM	REPLACED BOARD, BREAKER, PUMP & EQD	4.0 1.0	YES
	LIGHT/ALARM	REPLACED PUMP		
	OVERLELOWING	REPLACED PUMP & EQD	2.0	
06/27/2016	OVERLELOWING	REPLACED PUMP & EQD	1.0	
	OVERLELOWING	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD & HOUSING	7.0	YES
	STATION BACKING UP	REPLACED PUMP, EQD & HOUSING	2.0	YES
06/28/2016	LIGHT/ALARM	REPLACED PUMP, EQD & HOUSING	3.0	
06/29/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
1 06/29/2016	OVERLFLOWING	REPLACED PUMP & EQD	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
06/29/2016	OVERLFLOWING	REPLACED PUMP & EQD	2.0	1100113
, . ,	OVERLFLOWING	NO POWER ON CUSTOMER'S SIDE	0.5	
	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	
06/30/2016	OVERLFLOWING	REPLACED PUMP & EQD	2.0	
06/30/2016	OVERLFLOWING	REPLACED PUMP, EQD & HOUSING	1.0	
06/30/2016	LIGHT/ALARM	REPLACED PUMP, EQD & HOUSING	1.0	
07/01/2016	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	2.0	
07/01/2016	OVERLFLOWING	RESET BREAKER	0.5	
	STATION BACKING UP	REPLACED PUMP, EQD & HOUSING	3.0	YES
07/05/2016	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	
07/05/2016	ODOR	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	YES
	LIGHT/ALARM	REPLACED PUMP & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP & HOUSING	1.0	
	BREAKER ISSUE	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	
	OVERLELOWING	RESET BREAKER	0.5	
	LIGHT/ALARM	REPLACED PUMP - GMF	3.0	V/50
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	1.5	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP & EQD REPLACED PRESSURE CONNECT BOX	2.0 1.5	
	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	2.0	YES
	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	3.0	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	ILJ
	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	2.0	
	OVERLELOWING	REPLACED PUMP - GMF	3.0	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	1.5	123
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP, CABLE & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	YES
	STATION BACKING UP	REPLACED PUMP - GMF	1.0	
	OVERLFLOWING	REPLACED PUMP - GMF	2.0	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	3.0	YES
	OVERLFLOWING	REPLACED CONTROL BOARD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.5	
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.5	
07/19/2016	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
07/19/2016	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	OVERLFLOWING	REPLACED PUMP & EQD	1.0	
07/20/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
07/20/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
07/21/2016	OVERLFLOWING	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	2.0	<u> </u>
	OVERLFLOWING	REPLACED PUMP, CABLE & EQD	6.0	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	ODOR	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	PUMP NOT WORKING	RESET BREAKER	0.5	
07/26/2016	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
07/27/2016	PUMP NOT WORKING	NOT ENOUGH POWER COMING INTO STATION ON CUSTOMER SIDE	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
07/27/2016	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	1100110
07/27/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
07/28/2016	LIGHT/ALARM	REPLACED PUMP - GMF	3.5	YES
07/29/2016	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
07/30/2016	LIGHT/ALARM	REPLACED PUMP - GMF	3.5	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
08/01/2016	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
08/01/2016	LIGHT/ALARM	REPLACED PUMP, BOARD & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	4.0	YES
08/04/2016	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	OVERLFLOWING	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
08/06/2016	LIGHT/ALARM	CHECKED OKAY	2.0	YES
08/07/2016	PUMP NOT WORKING	NOT ENOUGH POWER COMING INTO STATION ON CUSTOMER SIDE	2.0	YES
08/08/2016	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	ELECTRICAL WIRES SHOWING	PROBLEM ON CUSTOMER'S SIDE OF MWD CONTROL BOX	1.0	
08/09/2016	OVERLFLOWING	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	
	LIGHT/ALARM	RESET BREAKER	3.0	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	OVERLFLOWING	REPLACED PUMP & EQD	2.5	YES
	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.5	
	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	
08/19/2016	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	
08/19/2016	LIGHT/ALARM	REPLACED PUMP - GMF	3.0	
08/19/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
08/19/2016	OVERLFLOWING	REPLACED PUMP, CABLE & EQD	3.0	YES
08/20/2016	OVERLFLOWING	NO POWER ON CUSTOMER'S SIDE	3.0	YES
08/22/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
08/22/2016	LIGHT/ALARM	REPLACED PUMP & BOARD	1.0	
08/22/2016	OVERLFLOWING	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	OVERLFLOWING	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED CABLE	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	
	LIGHT/ALARM	REPLACED PUMP, BOARD & EQD	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	PUMP NOT WORKING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.5	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	PUMP NOT WORKING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
08/29/2016 08/29/2016	LIGHT/ALARM BREAKER ISSUE	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP, BRAKERS, CONTROL BOARD & EQD REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.5	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	ILJ
	LIGHT/ALARM	REPLACED PUMP & BOARD	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
09/03/2016	LIGHT/ALAKIVI	INEFLACED PUIVIP & EQU	3.0	115

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	LIGHT/ALARM	REPLACED PUMP	1.0	
,,	OVERLFLOWING	REPLACED PUMP & BOARD	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
09/06/2016	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
09/07/2016	LIGHT/ALARM	CUSTOMER CAUSED - GREASE PROBLEM, CLEANED OUT STATION, REPLACED PUMP	2.0	
09/08/2016	OVERLFLOWING	REPLACED PUMP, CABLE & EQD	2.0	
09/08/2016	OVERLFLOWING	RESET BREAKER	0.5	
09/09/2016	STATION BACKING UP	CUSTOMER HAD FENCE INSTALLED AND PUNCTURED CABLE. REPLACED PUMP, EQD, CONTROL BOARD AND	2.5	
		CABLE		
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	RESET STATION	4.0	YES
	STATION BACKING UP	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	2.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	2.0	
	LIGHT/ALARM	REPLACED SLIDER VALVE & HOSE	1.0	
	OVERLFLOWING	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERLFLOWING	REPLACED PUMP	1.0	
	OVERLFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP MAKING NOISE	REPLACED PUMP	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	11.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0 1.0	
	OVERLFLOWING LIGHT/ALARM	REPLACED PUMP & EQD REPLACED PUMP & EQD		
	LIGHT/ALARM		1.0 0.5	
	LIGHT/ALARM	RESET BREAKER		
		REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP REPLACED PUMP	1.0 1.0	
, ,	- ,			
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP & EQD	1.0 1.0	
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE REPLACED PUMP	4.0	YES
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP	4.0	YES
		CUSTOMER CAUSED - BABY WIPES IN STATION -		163
10/03/2016	LIGHT/ALARM	REPLACED PUMP & EQD & SENT LETTER TO CUSTOMER	1.0	
10/03/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED CABLE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, HOUSING & BOARD	1.5	
	LIGHT/ALARM	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/08/2016	OVERLFLOWING	REPLACED PUMP, EQD, HOUSING & CABLE	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP NOT WORKING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/13/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
10/14/2016	OVERLFLOWING	REPLACED PUMP, SLIDER VALVE & HOSE	3.0	YES
	•	• • • • • • • • • • • • • • • • • • • •		

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	LIGHT/ALARM	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	0.5	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	
	STATION BACKING UP	REPLACED SLIDER VALVE	0.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	STATION BACKING UP	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, CABLE & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERLFLOWING	REPLACED PUMP & EQD	1.0	
10/27/2016	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
10/27/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
10/28/2016	LIGHT/ALARM	CHECKED OKAY	4.0	
10/28/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
10/29/2016	LIGHT/ALARM	REPLACED PUMP - GMF	3.0	YES
10/29/2016	LIGHT/ALARM	REPLACED PUMP - GMF	2.0	YES
10/31/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
11/01/2016	LIGHT/ALARM	RESET BREAKER	1.0	
11/01/2016	CLOGGED LINE	USED JETTER TO UNCLOG LINE	3.0	
11/02/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP NOT WORKING	CHECKED OKAY	0.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	OVERLFLOWING	REPLACED PIG TAIL, PRESSURE CONNECT & VENT CAP	2.0	. 20
11/07/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP - GMF	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & BOARD	1.0	
	LIGHT/ALARM	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERLFLOWING	REPLACED PUMP, CABLE, BOARD & BREAKER	1.5	
	OVERLFLOWING	REPLACED PUMP, EQD, HOUSING & CABLE	2.0	
	BREAKER ISSUE	REPLACED PUMP & BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
11/11/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
11/15/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERLFLOWING	NOT ENOUGH POWER COMING INTO STATION ON CUSTOMER SIDE	4.0	YES
11/15/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
				VEC
	LIGHT/ALARM	REPLACED PUMP	3.0 1.0	YES
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE		VEC
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	PUMP NOT WORKING	REPLACED PUMP	1.0	
11/17/2016	LIGHT/ALARM	REPLACED PUMP & BOARD	1.0	
11/18/2016	OVERLFLOWING	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
DAIL	CONFLAINT	RESOLUTION	(HOURS)	HOURS
11/21/2016	LIGHT/ALARM	REPLACED PUMP	0.5	
11/21/2016	LIGHT/ALARM	REPLACED PUMP	0.5	
11/22/2016	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
11/22/2016	LIGHT/ALARM	REPLACED PUMP	3.0	YES
11/23/2016	STATION BACKING UP	CHECKED OKAY	0.5	
11/23/2016	OVERLFLOWING	REPLACED PUMP & EQD	2.0	
11/23/2016	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
11/25/2016	LIGHT/ALARM	REPLACED PUMP, EQD, HOUSING & BOARD	1.0	
11/26/2016	LIGHT/ALARM	REPLACED PUMP, EQD, HOUSING & CABLE	1.5	
11/28/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
11/28/2016	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
		CUSTOMER CAUSED - BABY WIPES AND DIAPERS IN		
11/30/2016	LIGHT/ALARM	STATION - REPLACED PUMP & SENT LETTER TO	1.0	
11,00,1010		CUSTOMER	2.0	
12/02/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP	2.0	YES
	LIGHT/ALARM	REPLACED PUMP & CABLE	2.0	ILJ
	OVERLELOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	•			
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	RESET BREAKER	0.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	1/50
12/11/2016	LIGHT/ALARM	REPLACED PUMP	5.0	YES
12/11/2016	OVERLFLOWING	REPLACED PUMP	1.0	
12/12/2016	LIGHT/ALARM	NOT ENOUGH POWER COMING INTO STATION ON	1.0	
	·	CUSTOMER SIDE		
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
12/14/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERLFLOWING	REPLACED PUMP	1.0	
12/16/2016	OVERLFLOWING	REPLACED PUMP	1.0	
12/17/2016	LIGHT/ALARM	REPLACED PUMP EQD & HOUSING	4.0	YES
12/19/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
12/19/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
12/19/2016	LIGHT/ALARM	REPLACED PUMP	3.0	YES
12/20/2016	LIGHT/ALARM	REPLACED PUMP	1.0	
12/21/2016	OVERLFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
12/30/2016	PUMP NOT WORKING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP, BOARD & EQD	1.0	
12/31/2016	PUMP NOT WORKING	4" LINE FROM CUSTOMER'S SIDE WAS CLOGGED	2.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
09/27/2014	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
01/03/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
01/03/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	STATION RUNNING CONTINUOUSLY	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
01/04/2017	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	3.0	YES
	OVERFLOWING	REPLACED PUMP & EQD	1.0	ļ
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
01/04/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
01/04/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
01/04/2017	OVERFLOWING	RESET BREAKER	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
01/09/2017	LIGHT/ALARM	LINE FROZEN ON CUSTOMER'S SIDE	1.0	
01/09/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
01/13/2017	LIGHT/ALARM	REPLACED PUMP	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CABLE	1.0	ļ
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
01/23/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
01/24/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
01/26/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
01/27/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
01/27/2017	LIGHT/ALARM	REPLACED PUMP & EQD DUE TO FISHING LINE & BABY	1.0	
	·	WIPES IN STATION.		
01/31/2017	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/01/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD & HOSE	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	<u> </u>
	ODOR	REPLACED PUMP	1.0	
02/13/2017	OVERFLOWING	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	2.0	<u> </u>
	OVERFLOWING	REPLACED PUMP & EQD	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.5	<u> </u>
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	1.0	<u> </u>
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	<u> </u>
	OVERFLOWING	REPLACED PUMP	1.0	
02/22/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
		IDEDLACED DUMAN O FOR	1 40	
02/23/2017	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP & EQD REPLACED PUMP & EQD	1.0 1.0	

02/27/2017 L 02/28/2017 L 02/28/2017 C 03/01/2017 L 03/03/2017 L	DDOR IGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/28/2017 L 02/28/2017 C 03/01/2017 L 03/03/2017 L			1.0	
02/28/2017 C 03/01/2017 L 03/03/2017 L	ICUT/ALADAA	REPLACED PUMP & EQD	1.0	
03/01/2017 L 03/03/2017 L	.IGHT/ALARM	REPLACED PUMP & EQD	1.0	
03/03/2017 L	OVERFLOWING	RESET BREAKER	1.0	
	.IGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/02/2017	IGHT/ALARM	REPLACED PUMP	2.5	
	.IGHT/ALARM	REPLACED PUMP	1.5	
	IGHT/ALARM	REPLACED PUMP & EQD	1.5	
03/03/2017 L		REPLACED PUMP & EQD	1.0	
	IGHT/ALARM	LINE CLOGGED ON CUSTOMER'S SIDE	0.5	
	IGHT/ALARM	REPLACED PUMP	1.0	
	IGHT/ALARM	REPLACED PUMP	1.5	
	OVERFLOWING	REPLACED PUMP, CABLE, EQD & CONTROL BOARD	1.5	
	OVERFLOWING	REPLACED PUMP	4.0	YES
	DDOR	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
	IGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	RESET BREAKER	4.0	YES
	IGHT/ALARM	REPLACED PUMP	3.0	YES
	PUMP NOT WORKING	NO PROBLEM FOUND	1.0	
03/13/2017 L	·	REPLACED PUMP & EQD	1.0	
03/13/2017 L		REPLACED PUMP & EQD	1.0	
	OVERFLOWING	LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
	IGHT/ALARM	REPLACED PUMP	1.0	
03/18/2017	OVERFLOWING	REPLACED PUMP & EQD	3.0	YES
03/18/2017	OVERFLOWING	REPLACED PUMP & EQD	3.0	YES
03/18/2017 L	IGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
03/19/2017 L	IGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
03/20/2017 L	IGHT/ALARM	REPLACED PUMP	1.0	
03/21/2017 L	IGHT/ALARM	REPLACED PUMP	1.0	
03/21/2017 L	.IGHT/ALARM	REPLACED PUMP & EQD	1.0	
03/21/2017 L	.IGHT/ALARM	REPLACED PUMP & EQD	1.0	
03/22/2017	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
03/22/2017 L	.IGHT/ALARM	REPLACED PUMP	1.0	
03/23/2017 L	IGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	.IGHT/ALARM	NO PROBLEM FOUND	1.0	
03/23/2017 L	IGHT/ALARM	REPLACED PUMP & EQD	1.0	
	.IGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
03/24/2017 L		REPLACED PUMP	1.0	
	.IGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	IGHT/ALARM	REPLACED PUMP & EQD	1.0	
03/28/2017 L	•	REPLACED PUMP	3.0	YES
	VERFLOWING	REPLACED PUMP & EQD	1.0	
	.IGHT/ALARM	REPLACED PUMP	1.0	
03/29/2017 L		REPLACED PUMP & EQD	1.0	
03/30/2017 L		REPLACED PUMP & EQD	1.0	
03/31/2017 L		NO POWER ON CUSTOMER'S SIDE	0.5	
03/31/2017 L		REPLACED PUMP	1.0	
03/31/2017 L		REPLACED PUMP	1.0	
03/31/2017 C		REPLACED PUMP & EQD	1.0	
04/02/2017 L		REPLACED PUMP	3.0	YES
04/03/2017 L		NO POWER ON CUSTOMER'S SIDE	1.0	
	IGHT/ALARM	NO PROBLEM FOUND	1.0	
	IGHT/ALARM	REPLACED PUMP	1.0	
04/05/2017 L	•	LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
	IGHT/ALARM	REPLACED LID ON PRESSURE CONNECT BOX	1.0	
	DVERFLOWING	RESET BREAKER	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
04/13/2017 L		RESET BREAKER	1.0	
			1.0	
	OVERFLOWING IGHT/ALARM	REPLACED PUMP		
	IGHT/ALARM	REPLACED PUMP	1.0	
04/20/2017 L		REPLACED PUMP & CONTROL BOARD	1.0	
04/23/2017 L		REPLACED PUMP	1.0	VEC
04/24/2017 L	·	REPLACED PUMP	3.0	YES
04/24/2017 C	OVERFLOWING IGHT/ALARM	REPLACED PUMP, CABLE, EQD & CONTROL BOARD REPLACED PUMP	1.0 1.0	<u> </u>

MORPE MARKED PUMP & EDD 1.0	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
MARSONT OVERFLOWING	04/26/2017	LICUT/ALADAA	DEDIACED DI IMP 8 FOD	(HOURS)	HOURS
0.75/2017 UCHT/ALARM					
0.59(1)/2017 UGHT/ALARM					
0.501/2017 UcHT/ALARM REPLACED PUMP & COD 1.0 0.507/2017 OVERHLOWING REPLACED PUMP & COD 1.0 0.507/2017 OVERHLOWING REPLACED PUMP & COD 1.0 0.507/2017 UcHT/ALARM REPLACED PUMP & COD 1.0 0.507/2017 UcHT/ALARM REPLACED PUMP & COD 1.0 0.507/50217 UcHT/ALARM REPLACED PUMP & COD 4.0 YES 0.507/50217 UcHT/ALARM REPLACED PUMP & COD 4.0 YES 0.507/50217 UcHT/ALARM REPLACED PUMP & COD 4.0 YES 0.507/50217 UcHT/ALARM REPLACED PUMP & COD 1.0 0.507/50217 UCHT/ALARM REPLACED PUMP & COD		-			
SS/02/2017 OVERFLOWING REPLACED PUMP & COD 1.0		•			
SS/04/2017 LIGHT/ALARM					
DS/04/2017 UGHT/ALARM			-		YES
					123
0.505/02/2017 0.VERTLOWING					YFS
0.5/09/2017 UGHT/JALABM REPLACED PUMP, REPAIRED BROKEN SEWER LINE 2.0 VES 0.5/08/2017 UGHT/JALABM REPLACED PUMP & EQD 1.0 0.5/08/2017 UGHT/JALABM REPLACED PUMP & EQD 1.0 0.5/09/2017 PUMP RUNNING CONTINUOUSLY REPLACED PUMP & EQD 1.0 0.5/09/2017 PUMP RUNNING CONTINUOUSLY REPLACED PUMP & EQD 1.0 0.5/09/2017 UGHT/JALABM REPLACED PUMP & EQD 1.0 0.5/09/2017 UGHT/JALABM REPLACED PUMP & EQD 1.0 0.5/10/2017 UGHT/JALABM					123
DS/07/2017 OVERFLOWING		,			
10.508/2017 LIGHT/ALARM BREAKER ISSUE ON CUSTOMER'S SIDE 1.0					YES
					123
05/09/2017 PUMP RUNNING CONTINUOUSLY REPLACED PUMP & EQD 1.0					
10.507/2017 LIGHT/ALARM		•	-		
IOS/10/2017 LIGHT/ALARM	_ · ·	,	-		
		-	-		
				_	
		,			
DS/12/2017 UGHT/ALARM REPLACED PUMP, CABLE, EQD. & CONTROL BOARD 1.0					
OS/13/2017 LIGHT/ALARM					
			, , , ,		VEC
D5/14/2017 UIGHT/ALARM					
			·		
O5/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 O5/15/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 1.0 O5/15/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 O5/15/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 O5/15/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 O5/15/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 O5/18/2017 UGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 O5/19/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 O5/20/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 O5/20/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 O5/20/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 O5/20/2017 LIGHT/ALARM REPLACED PUMP, EQD & 4.0 YES O5/21/2017 LIGHT/ALARM NO PORBLEM FOUND 1.0 O5/21/2017 UGHT/ALARM NO PROBLEM FOUND 1.0 O5/21/2017 UGHT/ALARM REPLACED PUMP & EQD 4.0 YES O5/21/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES O5/21/2017 UGHT/ALARM REPLACED PUMP 3.0 YES O5/21/2017 UGHT/ALARM REPLACED PUMP 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 O5/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					YES
D55/12/2017 LIGHT/ALARM					
D55/18/2017 LIGHT/ALARM					
D5/18/2017 OVERLOWING					
05/19/2017					
05/19/2017 LIGHT/ALARM					\/F6
05/20/2017 LIGHT/ALARM					YES
05/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES					
05/22/2017 LIGHT/ALARM					
05/22/2017 OVERFLOWING NO PROBLEM FOUND, GROUND WATER 1.0					YES
OS/22/2017 LIGHT/ALARM REPLACED PUMP 1.0					
05/22/2017 OVERFLOWING REPLACED PUMP 1.0					
05/22/2017 STATION RUNNING CONTINUOUSLY REPLACED PUMP 1.0		-			YES
05/22/2017					
05/22/2017					
05/23/2017			-		
05/23/2017 LIGHT/ALARM REPLACED EQD 1.0 05/24/2017 LIGHT/ALARM NO PROBLEM FOUND, RAIN WATER IN STATION 1.0 05/24/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/24/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 0.5 05/25/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM					
05/24/2017 LIGHT/ALARM NO PROBLEM FOUND, RAIN WATER IN STATION 1.0 05/24/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/24/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 0.5 05/25/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 05/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/201					
05/24/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/24/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 0.5 05/25/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO POBLEM FOUND 3.0 YES 05/30/2017 </td <td></td> <td></td> <td></td> <td></td> <td></td>					
05/24/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 0.5 05/25/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 <td></td> <td></td> <td></td> <td></td> <td></td>					
05/25/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 05/27/2017 LIGHT/ALARM REPLACED PUMP 4.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0					
05/25/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/25/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/27/2017 LIGHT/ALARM REPLACED PUMP 4.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM					
05/25/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/27/2017 LIGHT/ALARM REPLACED PUMP 4.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0				1.0	
05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/27/2017 LIGHT/ALARM REPLACED PUMP 4.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0					
05/26/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/27/2017 LIGHT/ALARM REPLACED PUMP 4.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0	05/25/2017	LIGHT/ALARM	·	1.0	
05/26/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/27/2017 LIGHT/ALARM REPLACED PUMP 4.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0		-	REPLACED PUMP		
05/26/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/27/2017 LIGHT/ALARM REPLACED PUMP 4.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0	05/26/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
05/27/2017 LIGHT/ALARM REPLACED PUMP 4.0 YES 05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0		-	REPLACED PUMP & CONTROL BOARD	3.0	YES
05/29/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0			REPLACED PUMP & EQD	1.0	
05/30/2017 LIGHT/ALARM NO PROBLEM FOUND 3.0 YES 05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0		LIGHT/ALARM	REPLACED PUMP	4.0	YES
05/30/2017 LIGHT/ALARM REPLACED PUMP 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0	05/29/2017	LIGHT/ALARM	REPLACED PUMP	3.0	YES
05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0	05/30/2017	LIGHT/ALARM	NO PROBLEM FOUND	3.0	YES
05/30/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0			REPLACED PUMP	1.0	
05/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0					
05/30/2017 LIGHT/ALARM REPLACED PUMP, CABLE & EQD 2.0 YES 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0					
05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0					YES
05/31/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0					-
		LIGHT/ALARM	NO PROBLEM FOUND	1.0	

G6/07/2017 LGHT/ALARM	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
DOP/10/2017 LIGHT/ALARM			REPLACED PUMP		
Ge/Fig/2017 GefT/ALARM REPLACED PUMP & EQD 1.0					YES
G6/F0/2017 G0HT/ALARM		· · · · · · · · · · · · · · · · · · ·			
		· · · · · · · · · · · · · · · · · · ·			
G6/09/2017 G6/H7/ALARM		· · · · · · · · · · · · · · · · · · ·			
					VEC
			-		
			-		ILJ
GOOGGOOT GIGHT/ALARM			-		
			-		
G6/08/2017 LIGHT/ALARM REPLACED PUMP 1.0					
G6/G8/2017 LIGHT/ALARM REPLACED PLIMP 2.0 YE			-		
					YES
		· · · · · · · · · · · · · · · · · · ·			
		· · · · · · · · · · · · · · · · · · ·			
D6/99/2017 LIGHT/ALARM					
		· · · · · · · · · · · · · · · · · · ·			
D6/12/2017 OVERFLOWING DIRE CLOGGED ON CUSTOMER'S SIDE 3.0 YE					YES
D6/12/2017 OVERFLOWING REPLACED PUMP 1.0					YES
D6/12/2017 DVERFLOWING					
D6/13/2017 ODOR	06/12/2017	OVERFLOWING	REPLACED PUMP	1.0	
D6/15/2017 DODR			REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
D6/15/2017 LIGHT/ALARM	06/13/2017	ODOR	REPLACED PUMP, CONTROL BOARD & VENT CAP	1.0	
Dof/15/2017 OVERFLOWING	06/15/2017	ODOR	LINE CLOGGED ON CUSTOMER'S SIDE	0.5	
D6/15/2017 OVERFLOWING	06/15/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
OS/15/2017 DUMP NOT WORKING	06/15/2017	OVERFLOWING	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
06/16/2017 OVERFLOWING	06/15/2017	OVERFLOWING	REPLACED PUMP, EQD & CONTROL BOARD	2.0	
06/16/2017 IGHT/ALARM	06/15/2017	PUMP NOT WORKING	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
06/17/2017	06/16/2017	OVERFLOWING	NO PROBLEM FOUND	1.0	
06/29/2017 USER-LOWING REPLACED PUMP & EQD 1.0			REPLACED PUMP & EQD	1.0	
06/20/2017 LIGHT/ALARM	06/17/2017	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	4.0	YES
06/20/2017 OVERFLOWING				1.0	
06/21/2017 LIGHT/ALARM					
06/21/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0					
06/23/2017 LIGHT/ALARM	<u> </u>	·			
O6/24/2017 LIGHT/ALARM					
O6/24/2017	<u> </u>	·			
O6/25/2017		· · · · · · · · · · · · · · · · · · ·			YES
06/25/2017 LIGHT/ALARM REPLACED PUMP & EQD 5.0 YE 06/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 06/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/29/2017 LIGHT/ALARM REPLACED CONTROL BOARD 1.0 06/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 06/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/03/2017 STATION BACKING UP LINE CLOGGED, DUG OUT CLEAN OUT CAP & UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 1.0 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 <t< td=""><td></td><td></td><td></td><td></td><td>YES</td></t<>					YES
06/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 06/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/29/2017 LIGHT/ALARM REPLACED CONTROL BOARD 1.0 06/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 06/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/03/2017 STATION BACKING UP LINE CLOGGED, DUG OUT CLEAN OUT CAP & UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 1.0 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 1.0 07/06/2017 LIGHT/ALARM REPLACED					YES
06/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/29/2017 LIGHT/ALARM REPLACED CONTROL BOARD 1.0 06/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/03/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017					YES
06/29/2017 LIGHT/ALARM REPLACED CONTROL BOARD 1.0 06/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 06/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/03/2017 STATION BACKING UP LINE CLOGGED, DUG OUT CLEAN OUT CAP & UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD <td< td=""><td></td><td></td><td>-</td><td></td><td></td></td<>			-		
06/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 06/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/03/2017 STATION BACKING UP LINE CLOGGED, DUG OUT CLEAN OUT CAP & UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM					
06/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/03/2017 STATION BACKING UP LINE CLOGGED, DUG OUT CLEAN OUT CAP & UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 LIGHT/ALARM NO PROBL					
06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/03/2017 STATION BACKING UP LINE CLOGGED, DUG OUT CLEAN OUT CAP & UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 DVERFLOWING REPLAC					
06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/03/2017 STATION BACKING UP LINE CLOGGED, DUG OUT CLEAN OUT CAP & UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 DVERFLOWING REPLACED PUMP 1.0					
06/30/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/03/2017 STATION BACKING UP LINE CLOGGED, DUG OUT CLEAN OUT CAP & UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 DVERFLOWING REPLACED PUMP 1.0					
07/03/2017 STATION BACKING UP LINE CLOGGED, DUG OUT CLEAN OUT CAP & UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0	<u> </u>				
07/03/2017 STATION BACKING UP UNCLOGGED LINE 5.0 YE 07/05/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0	06/30/201/	LIGHT/ALAKIVI	-	1.0	
07/05/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0	07/03/2017	STATION BACKING UP	,	5.0	YES
07/06/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0	07/05/2017	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
07/06/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0	07/05/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
07/06/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 07/06/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0			REPLACED PUMP	1.0	
07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YE 07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0			REPLACED PUMP & CONTROL BOARD	1.0	
07/07/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0	07/06/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
07/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0	07/07/2017	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	YES
07/10/2017 LIGHT/ALARM REPLACED PUMP 1.0 07/10/2017 OVERFLOWING REPLACED PUMP 1.0	07/07/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
07/10/2017 OVERFLOWING REPLACED PUMP 1.0		LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	07/10/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
1 OZ/10/2017 LICHT/ALADM				1.0	
U//IU/ZUI/ LIGHI/ALAKIVI KEPLACED PUMP & EQD 1.0	07/10/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	

07/11/2017 LICHT/JALARM	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
0711/2017 USHT/ALARM	07/11/2017	11017/41484	DEDI AGED CONTROL DOADD	(HOURS)	HOURS
07/12/2017 ICHIT/ALARIM					
GP/12/2017 GHT/MARM					
O7/14/2017 IGHT/ALARM		•	·		
10714/2017 UGHT/ALARM					
O7/14/2017 UGHT/ALARM					
O7/15/2017 UGHT/ALARM					
			-		YES
O7/17/2017 UGHT/ALARM	07/15/2017	LIGHT/ALARM	REPLACED PUMP	3.0	YES
		LIGHT/ALARM	REPLACED PUMP	2.0	
10,717,2017 IGHT/ALABM			REPLACED PUMP & EQD	1.0	
107/18/2017 USHT/ALARM	07/17/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
07/22/2017 USHT/ALARM	07/17/2017	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
	07/18/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
07/23/2017 UGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 07/23/2017 UGHT/ALARM NO PROBLEM FOUND 1.0 07/25/2017 UGHT/ALARM NO PROBLEM FOUND 1.0 07/25/2017 UGHT/ALARM REPLACED PUMP 1.0 07/25/2017 UGHT/ALARM REPLACED PUMP 1.0 07/25/2017 UGHT/ALARM REPLACED PUMP 1.0 07/25/2017 UGHT/ALARM REPLACED PUMP 1.0 07/25/2017 UGHT/ALARM REPLACED PUMP & EQD 1.0 07/27/2017 UGHT/ALARM REPLACED PUMP & EQD 1.0 07/27/2017 UGHT/ALARM REPLACED PUMP & EQD 1.0 07/27/2017 UGHT/ALARM REPLACED PUMP & EQD 1.0 07/28/2017 UGHT/ALARM REPLACED PUMP & EQD 1.0 07/31/2017 UGHT/ALARM REPLACED PUMP & EQD 1.0 08/01/2017 UGH		LIGHT/ALARM	<u> </u>	1.0	
07/28/2017 IGHT/ALARM		•	-		YES
07/25/2017 LIGHT/ALARM			<u> </u>		YES
107/25/2017 LIGHT/ALARM			1 1		
07/27/2017 LIGHT/ALARM					
			<u> </u>		
07/31/2017					
07/31/2017 LIGHT/ALARM REPLACED PUMP, EQD & HOSE 1.0					
07/31/2017 LIGHT/ALARM			· ·		
08/01/2017 LIGHT/ALARM					
D8/01/2017 LIGHT/ALARM			· · · · · · · · · · · · · · · · · · ·		
08/02/2017 DDOR			-		
08/02/2017 LIGHT/ALARM		•	-		
08/03/2017 LIGHT/ALARM REPLACED PUMP 1.0		LIGHT/ALARM		3.0	YES
08/07/2017	08/02/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
08/07/2017 OVERFLOWING REPLACED PUMP, CABLE, EQD & CONTROL BOARD 1.5 08/07/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 08/07/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.0 YES 08/07/2017 OVERFLOWING RESET BREAKER 1.0 08/08/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/08/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/08/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/08/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/09/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/10/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 8/03/2017	LIGHT/ALARM	REPLACED PUMP	1.0		
08/07/2017 LIGHT/ALARM	08/07/2017	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
08/07/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.0 YES 08/07/2017 OVERFLOWING RESET BREAKER 1.0		OVERFLOWING	REPLACED PUMP, CABLE, EQD & CONTROL BOARD	1.5	
08/07/2017 OVERFLOWING RESET BREAKER 1.0 08/08/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/08/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/08/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/09/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/10/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/13/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0	08/07/2017	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
08/08/2017		·	· · · · · · · · · · · · · · · · · · ·		YES
08/08/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
08/08/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/09/2017 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 08/09/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 08/09/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/10/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/13/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/14/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/15/2017 DOR REPLACED PUMP & EQD 1.0 08/15/2017 DOR REPLACED PUMP & EQD 1.0 08/16/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 <					
08/09/2017 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 08/09/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 08/09/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/10/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 DOR NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/13/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/14/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 08/14/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 08/15/2017 0.0 08/16/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/15/2017 1.0 08/15/2017 0.0 08/15/2017 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0					
08/09/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 08/09/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/10/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 DOR NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/13/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 08/14/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 08/15/2017 08/15/2017 DOR REPLACED PUMP, EQD & CONTROL BOARD 1.0 08/15/2017 08/16/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/17/2017 DOR REPLACED PUMP & CONTROL BOARD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 LIGHT/ALARM <td></td> <td></td> <td></td> <td></td> <td></td>					
08/09/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/10/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 DOR NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/13/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 08/14/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 08/15/2017 DOR REPLACED PUMP & EQD 1.0 08/15/2017 DOR REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/17/2017 DOR REPLACED PUMP & EQD 1.0 08/17/2017 DOR REPLACED PUMP & EQD 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 </td <td></td> <td></td> <td></td> <td></td> <td></td>					
08/10/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 DODR NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/13/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 08/14/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 1.0 08/15/2017 ODOR REPLACED PUMP & EQD 1.0 1.0 08/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/19/2017 LIGHT/ALARM RE					
08/10/2017 LIGHT/ALARM NO PROBLEM FOUND 1.0 08/10/2017 ODOR NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/13/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 08/14/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 1.0 08/15/2017 ODOR REPLACED PUMP & EQD 1.0 1.0 08/16/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 08/17/2017 DOR REPLACED PUMP & CONTROL BOARD 1.0 1.0 08/17/2017 DOR REPLACED PUMP & EQD 1.0 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT					
08/10/2017 ODOR NO PROBLEM FOUND 1.0 08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/13/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 08/14/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 1.0 08/15/2017 ODOR REPLACED PUMP & EQD 1.0 1.0 08/16/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/17/2017 DOR REPLACED PUMP & EQD 1.0 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM					
08/10/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/13/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 08/14/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 08/15/2017 ODOR REPLACED PUMP & EQD 1.0 08/16/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/17/2017 ODOR REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES					
08/13/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 3.0 YES 08/14/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 08/15/2017 ODOR REPLACED PUMP & EQD 1.0 08/16/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/17/2017 ODOR REPLACED PUMP & EQD 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 <td></td> <td></td> <td></td> <td></td> <td></td>					
08/14/2017 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 1.0 08/15/2017 ODOR REPLACED PUMP & EQD 1.0 08/16/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/17/2017 DOOR REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 Y					YFS
08/15/2017 ODOR REPLACED PUMP & EQD 1.0 08/16/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/17/2017 ODOR REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5			<u> </u>		113
08/16/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/17/2017 DOOR REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5		·			
08/17/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 08/17/2017 ODOR REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5					
08/17/2017 ODOR REPLACED PUMP & EQD 1.0 08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5					
08/17/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5					
08/18/2017 STATION BACKING UP LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5			-		
08/18/2017 LIGHT/ALARM REPLACED PUMP 1.0 08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5					YES
08/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5					
08/20/2017 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5					
08/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 4.0 YES 08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5	08/19/2017	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
08/21/2017 ODOR LINE CLOGGED ON CUSTOMER'S SIDE 0.5		LIGHT/ALARM	REPLACED PUMP	3.0	YES
· ·	08/20/2017	LIGHT/ALARM	REPLACED PUMP & EQD		YES
08/21/2017LIGHT/ALARMNO POWER ON CUSTOMER'S SIDE1.0	08/21/2017	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
08/22/2017	ODOR	LINE CLOGGED ON CUSTOMER'S SIDE, JETTED SEWER LINES FOR BOE. BILLED FOR SERVICE.	4.0	
08/22/2017	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP NOT WORKING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	STATION BACKING UP	RESET BREAKER	0.5	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	·	CUSTOMER HAD NO POWER TO STATION BUT WAS		
08/28/2017	OVERFLOWING	USING SERVICE. COST ESTIMATE TO REPLACE DAMAGED PARTS & NEEDS TO HOOK UP POWER TO STATION	1.0	
08/28/2017	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
08/31/2017	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
09/01/2017	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP & EQD	1.0	
09/01/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
09/02/2017	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	2.0	YES
09/05/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
09/05/2017	OVERFLOWING	REPLACED PUMP & EQD	1.0	
09/07/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
09/07/2017	LIGHT/ALARM	REPLACED PUMP, CABLE, EQD & CONTROL BOARD	1.5	
09/08/2017	ODOR	LINE CLOGGED ON CUSTOMER'S SIDE	4.0	YES
	PUMP NOT WORKING	NO POWER ON CUSTOMER'S SIDE	1.0	
09/08/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
09/09/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	YES
	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD & HOSE	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
	STATION BACKING UP	NO PROBLEM FOUND	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	1.0	1,550
	OVERFLOWING	REPLACED PUMP, EQD & HOSE	4.0	YES
09/17/2017	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOWING	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP & EQD	2.5	YES
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	2.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	VEC
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED CONTROL BOARD	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	0.5	
09/29/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
09/30/2017	LIGHT/ALARM	REPLACED PUMP	2.5	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	YES
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	3.0	YES
10/02/2017	LIGHT/ALARM	RESET BREAKER	0.5	
10/03/2017	OVERFLOWING	NO POWER ON CUSTOMER'S SIDE	1.0	
10/03/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.3	
10/04/2017	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	0.5	
10/04/2017	LIGHT/ALARM	REPLACED EQD & CABLE	1.0	
10/04/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
10/05/2017	BLOCKED LINE	JETTED LINES	3.0	
10/06/2017	LIGHT/ALARM	REPLACED DISCHARGE HOSE	1.0	
10/06/2017	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	3.0	YES
10/07/2017	OVERFLOWING	REPLACED PUMP & EQD	3.0	
10/09/2017	LIGHT/ALARM	NO PROBLEM FOUND	1.0	
10/09/2017	LIGHT/ALARM	REPLACED EQD, CABLE & CONDUIT	1.0	
10/09/2017	OVERFLOWING	REPLACED PUMP & EQD	1.0	
10/10/2017	STATION BACKING UP	LINE CLOGGED, SNAKED AND UNCLOGGED LINE	2.0	YES
10/10/2017		REPLACED PUMP & EQD	1.0	
10/10/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	ODOR	CUSTOMER REPLACED A 100AMP FUSE	1.0	
10/11/2017	LIGHT/ALARM_	REPLACED PUMP & EQD	1.0	
10/11/2017		REPLACED PUMP & EQD	1.0	
10/12/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	1.0	
10/12/2017	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
	ODOR	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
10/17/2017		REPLACED PUMP & EQD	2.0	YES
10/17/2017	•	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	RESET BREAKER	1.0	
	ODOR	NO PROBLEM FOUND	11.0	
10/18/2017		REPLACED PUMP	1.0	
1 1	STATION BACKING UP	REPLACED PUMP, CABLE, EQD & CONTROL BOARD	2.0	
	LIGHT/ALARM	NO PROBLEM FOUND	3.0	YES
1 1	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	123
		LINE CLOGGED DUE TO BROKEN PLUG, REMOVED		
10/21/2017	OVERFLOWING	PLUG AND UNCLOGGED LINE	3.0	YES
10/22/2017	LIGHT/ALARM	REPLACED PUMP	3.0	YES
10/22/2017	- 1	REPLACED PUMP & EQD	3.0	YES
10/23/2017	•	REPLACED PUMP	1.0	ILJ
10/23/2017		REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP & EQD	1.0	
10/25/2017		REPLACED PUMP & EQD		
	OVERFLOWING	REPLACED PUMP	1.0	
10/26/2017		REPLACED PUMP, CABLE, EQD & CONTROL BOARD	1.5	
	OVERFLOWING	REPLACED PUMP & CONTROL BOARD	1.0	
		REPLACED PUMP & CONTROL BOARD	1.0	
11/02/2017 11/04/2017			1.0	
		REPLACED PUMP		
	OVERFLOWING	REPLACED PUMP	1.0	
11/06/2017		REPLACED PUMP & EQD	1.0	
1 1	PUMP NOT WORKING	REPLACED PUMP & EQD	1.0	
11/08/2017	•	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	VEC
11/12/2017		REPLACED PUMP & CONTROL BOARD	4.0	YES
11/13/2017	•	REPLACED PUMP	1.0	
11/13/2017	•	REPLACED PUMP	1.0	
	OVERFLOWING	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	OVERFLOWING	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
11/14/2017		REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED CONTROL BOARD	1.0	
11/15/2017		REPLACED PUMP & EQD	1.0	
11/15/2017	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	

	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
11/20/2017 UGHT/ALARM REPLACED PUMP & CABLE, EQD & CONTROL BOARD 1.0 11/21/2017 UGHT/ALARM REPLACED PUMP & CABLE 1.0 1.15 11/21/2017 UGHT/ALARM REPLACED PUMP & CABLE 1.0 11/21/2017 UGHT/ALARM REPLACED PUMP & CABLE 1.0 11/21/2017 UGHT/ALARM REPLACED PUMP & CABLE 1.0 11/21/2017 UGHT/ALARM REPLACED PUMP & CABLE 1.0 11/21/2017 UGHT/ALARM REPLACED PUMP & CABLE 1.0 11/21/2017 UGHT/ALARM REPLACED PUMP & COD & CONTROL BOARD 2.5 YES 11/21/2017 UGHT/ALARM REPLACED PUMP 1.0 11/21/2017 UGHT/ALARM REPLACED PUMP 1.0 11/21/2017 UGHT/ALARM REPLACED PUMP 1.0 11/21/2017 UGHT/ALARM REPLACED PUMP 1.0 11/28/2017 UGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 11/28/2017 UGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 11/28/2017 UGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 11/28/2017 UGHT/ALARM REPLACED PUMP & COD 3.0 YES 11/28/2017 UGHT/ALARM REPLACED PUMP & COD 3.0 YES 11/28/2017 UGHT/ALARM REPLACED PUMP & ECD 3.0 YES 11/28/2017 UGHT/ALARM REPLACED PUMP & ECD 3.0 YES 11/28/2017 UGHT/ALARM REPLACED PUMP & ECD 3.0 YES 11/29/2017 UGHT/ALARM	44/46/2047	OVEREI OVIING	DEDI ACED DUMAD & CONTROL DOADD		HOURS
11/21/2017 UGHT/ALARM REPLACED PUMP & EQD 1.5 11/22/2017 OVERFLOWING REPLACED PUMP & CABLE 1.0 11/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 11/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 11/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 11/22/2017 UGHT/ALARM NO PROBLEM FOUND 1.0 11/27/2017 UGHT/ALARM NO PROBLEM FOUND 1.0 11/27/2017 UGHT/ALARM REPLACED PUMP 1.0 11/27/2017 UGHT/ALARM REPLACED PUMP 1.0 11/27/2017 UGHT/ALARM REPLACED PUMP 1.0 11/27/2017 UGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.5 11/28/2017 UGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.5 11/28/2017 UGHT/ALARM REPLACED PUMP & EQD 3.0 YES 11/28/2017 UGHT/ALARM REPLACED PUMP & EQD 3.0 YES 11/28/2017 UGHT/ALARM REPLACED PUMP & EQD 3.0 YES 11/28/2017 UGHT/ALARM REPLACED PUMP & EQD 3.0 YES 11/28/2017 UGHT/ALARM REPLACED PUMP & EQD 3.0 YES 11/29/2017 U					
11/22/2017 USHT/ALARM			, , , ,		
11/22/2017 UGHT/ALARM		-			
11/24/2017 OVERFLOWING					
11/27/2017 LIGHT/ALARM		-			1/50
11/27/2017 LIGHT/ALARM			•		YES
11/27/2017 LIGHT/ALARM					
11/27/2017 OVERFLOWING					
11/28/2017 LIGHT/ALARM					
11/28/2017 LIGHT/ALARM					
11/28/2017 LIGHT/ALARM					
11/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0		LIGHT/ALARM	REPLACED PUMP & EQD		YES
11/29/2017 IJGHT/ALARM			REPLACED PUMP & EQD	1.0	
11/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES	11/28/2017	LIGHT/ALARM	REPLACED PUMP & EQD		YES
12/01/2017	11/29/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
12/01/2017 LIGHT/ALARM	11/29/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
12/03/2017 LIGHT/ALARM	12/01/2017	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
12/04/2017 OVERFLOWING REPLACED PUMP 3.0 YES 12/11/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 12/11/2017 LIGHT/ALARM REPLACED PUMP 1.0 1.0 12/11/2017 OVERFLOWING REPLACED PUMP 1.0 1.0 12/11/2017 UIGHT/ALARM REPLACED PUMP 1.0 1.0 12/11/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.	12/01/2017	LIGHT/ALARM	REPLACED PUMP, EQD & HOSE	2.0	
12/04/2017 OVERFLOWING REPLACED PUMP 3.0 YES 12/11/2017 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 12/11/2017 LIGHT/ALARM REPLACED PUMP 1.0 1.0 12/11/2017 OVERFLOWING REPLACED PUMP 1.0 1.0 12/11/2017 UIGHT/ALARM REPLACED PUMP 1.0 1.0 12/11/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.	12/03/2017	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
1.7/11/2017		-			YES
1.7/11/2017					
17/11/2017 OVERFLOWING REPLACED PUMP 1.0 12/11/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/12/2017 ODOR NO PROBLEM FOUND 1.0 12/12/2017 DOOR NO PROBLEM FOUND 1.0 12/14/2017 UIGHT/ALARM REPLACED PUMP & CABLE 1.0 12/14/2017 UIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 12/14/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 UIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 UIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/AL					
1.7/11/2017 LIGHT/ALARM					
1.7/12/2017 ODOR					
12/14/2017 BLOCKED LINE JETTED LINES 2.5 12/14/2017 DODR NO PROBLEM FOUND 1.0 12/14/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/14/2017 OVERFLOWING REPLACED PUMP & CABLE 1.0 12/14/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 12/15/2017 LIGHT/ALARM REPLACED CABLE 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/23/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/23/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/23/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP &					
12/14/2017 ODOR					
12/14/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/14/2017 LIGHT/ALARM REPLACED PUMP & CABLE 1.0 12/14/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 12/15/2017 LIGHT/ALARM REPLACED DUMP & CONTROL BOARD 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/22/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM					
12/14/2017 OVERFLOWING REPLACED PUMP & CABLE 1.0 12/14/2017 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD 1.0 12/15/2017 LIGHT/ALARM REPLACED CABLE 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 1.0 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 12/19/2017 DVERFLOWING REPLACED PUMP & EQD 1.3 1.2 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.2 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 1.0 12/22/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD <					
12/14/2017		-			
12/15/2017 LIGHT/ALARM REPLACED CABLE 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 IC 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 IC 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 IC 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 IC 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 IC 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 IC 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 IC 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 IC 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 IC 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 IC 12/28/2017 LIGHT/ALARM REPLACED PUMP					
12/15/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 <t< td=""><td></td><td>•</td><td></td><td></td><td></td></t<>		•			
12/15/2017 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 UGHT/ALARM REPLACED PUMP & EQD 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 <td< td=""><td></td><td>-</td><td></td><td></td><td></td></td<>		-			
12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/19/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.3 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0		•			VEC
12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/19/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.3 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 OVERFLOWING LINE CLOGGED ON CUSTOMER'S SIDE 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					YES
12/18/2017 LIGHT/ALARM REPLACED PUMP & EQD 2.5 12/19/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/19/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.3 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 DVERFLOWING LINE CLOGGED ON CUSTOMER'S SIDE 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
12/19/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/19/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.3 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 OVERFLOWING LINE CLOGGED ON CUSTOMER'S SIDE 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
12/19/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.3 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 OVERFLOWING LINE CLOGGED ON CUSTOMER'S SIDE 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.3 12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 OVERFLOWING LINE CLOGGED ON CUSTOMER'S SIDE 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
12/20/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 OVERFLOWING LINE CLOGGED ON CUSTOMER'S SIDE 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
12/22/2017 OVERFLOWING REPLACED PUMP & EQD 1.0 12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 OVERFLOWING LINE CLOGGED ON CUSTOMER'S SIDE 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
12/27/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/28/2017 OVERFLOWING LINE CLOGGED ON CUSTOMER'S SIDE 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
12/28/2017 OVERFLOWING LINE CLOGGED ON CUSTOMER'S SIDE 0.3 12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
12/28/2017 LIGHT/ALARM REPLACED PUMP 0.5 12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0		•			
12/28/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
12/28/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0		•			
12/29/2017 LIGHT/ALARM REPLACED PUMP 1.0 12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0	12/28/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0	12/28/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	12/29/2017	LIGHT/ALARM	REPLACED PUMP	1.0	
12/29/2017 LIGHT/ALARM REPLACED PUMP & EQD 1.0	12/29/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	12/29/2017	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	

02/02/2016 ODOR	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME	AFTER
0,007,018 USHT/ALARM	01/02/2019	ODOR	NO DROPLEM FOLIND ON MWD SIDE	` '	HOURS
01/03/2018 ILGHT/JALARM					VES
0,003/2018 LIGHT/ALARM					11.5
1,03/2018 LIGHT/ALARM			-		YES
10/08/2018 LIGHT/ALARM		-			
0.1/04/2015 UIGHT/ALARM RELAID FROZEN SEWER LINE 5.0 0.1/04/2015 OVERFLOW RELAID FROZEN SEWER LINE 5.0 0.1/04/2015 OVERFLOW RELAID FROZEN SEWER LINE 5.0 0.1/05/2018 OVERFLOW REPLACED PUMP 1.0 0.1/05/2018 OVERFLOW REPLACED PUMP 1.0 0.1/05/2018 UIGHT/ALARM HOWE 1.0 0.1/05/2018 UIGHT/ALARM HOWE 1.0 0.1/05/2018 UIGHT/ALARM HOWE 1.0 0.1/05/2018 UIGHT/ALARM HOWE 1.0 0.1/05/2018 UIGHT/ALARM HOWE 1.0 0.1/06/2018 OVERFLOW REPLACED PUMP & EQD 4.0 YES 0.1/06/2018 UIGHT/ALARM FROZEN SEWER LINE HAWEO LINE 2.0 0.1/06/2018 UIGHT/ALARM FROZEN SEWER LINE HAWEO LINE 2.0 0.1/06/2018 UIGHT/ALARM FROZEN SEWER LINE HAWEO LINE 2.0 0.1/08/2018 UIGHT/ALARM FROZEN SEWER LINE HAWEO LINE 2.0 0.1/08/2018 UIGHT/ALARM FROZEN SEWER LINE HAWEO LINE 2.0 0.1/08/2018 UIGHT/ALARM FROZEN SEWER LINE HAWEO LINE 3.0 0.1/08/2018 UIGHT/ALARM REPLACED PUMP 3.0 0.1/08/2018 UIGHT/ALARM NO PROBLEM FOUND ON MYD SIDE 1.0 0.1/08/2018 UIGHT/ALARM REPLACED PUMP 3.0 0.1/08/2018 UIGHT/ALARM REPLACED PUMP 3.0 0.1/08/2018 UIGHT/ALARM REPLACED PUMP 2.5 0.1/08/2018 UIGHT/ALARM REPLACED PUMP 1.0 0.1/08/2018 UIGHT/ALARM REPLACED PUMP 1.0 0.1/08/2018 UIGHT/ALARM REPLACED PUMP 1.0 0.1/08/2018 UIGHT/ALARM REPLACED PUMP 1.0 0.1/08/2018 UIGHT/ALARM REPLACED PUMP 1.0 0.1/08/2018 UIGHT/ALARM REPLACED PUMP & SOCIARGE HOSE 0.5 0.1/08/2018 UIGHT/ALARM REPLACED PUMP & SOCIARGE HOSE 0.5 0.1/08/2018 UIGHT/ALARM REPLACED PUMP & SOCIARGE HOSE 0.5 0.1/08/2018 UIGHT/ALARM REPLACED PUMP & SOCIARGE HOSE 0.5 0.1/08/2018 UIGHT/ALARM REPLACED PUMP & SOCIARGE HOSE 0.5 0.1/08/2018 UIGHT/ALARM REPLACED PUMP & SOCIARGE HOSE 0.5 0.1/08/2018 UIGHT/ALARM REPLACED PUMP & SOCIARGE HOSE 0.5 0.1/10/2018 UIGHT/ALARM REPLACED PUMP & SOCIARGE HOSE 0.5 0.1/10/2018 UIGHT/ALARM REPLACED PUMP & SOCIARGE HOSE 0.0 0.1/10/201	01/03/2018	LIGHT/ALARM	·	3.0	
10,104,2018 OVERFLOW		·		E O	
01/03/2018 CHHT/ALARM		-			
10,05/2018 USERIOW REPLACED PUMP 1.0		I.			
O1/05/2018 LIGHT/ALARM					
HOSE			THAWED FROZEN LINE, REPLACED SLIDER VALVE &		
		,			
19.08/2018 GHT/ALARM					VEC
0.1/08/2018 UGHT/ALARM					TES
01/08/2018 IGHT/ALARM		1	•		
0.1/08/2018 IGHT/ALARM					
0.1/08/2018 IGHT/ALARM		1			
0.1/08/2018 LIGHT/ALARM					
0.1/08/2018 LIGHT/ALARM					YES
0.1/08/2018 LIGHT/ALARM REPLACED PUMP 1.0					
DIJOR/2018 DUMP RUNNING CONTINUOUSLY REPLACED PUMP & CONTROL BOARD 1.0					
D1/08/2018 LIGHT/ALARM				1.0	
D1/08/2018 LIGHT/ALARM	01/08/2018	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
O1/08/2018 LIGHT/ALARM	01/08/2018	LIGHT/ALARM	REPLACED PUMP & DISCHARGE HOSE	0.5	
D1/09/2018 LIGHT/ALARM	01/08/2018	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	
DI/09/2018 LIGHT/ALARM	01/08/2018	LIGHT/ALARM	<u> </u>	2.5	
DI/09/2018 IIGHT/ALARM	01/09/2018	LIGHT/ALARM		2.5	
10/19/2018 DOOR					
10,007,018 LIGHT/ALARM					
1.0					
01/10/2018 LIGHT/ALARM					
O1/12/2018 LIGHT/ALARM			•	1.0	
DISCHARGE HOSE DISC	01/10/2018	LIGHT/ALARM		0.5	
01/12/2018 LIGHT/ALARM	01/12/2018	LIGHT/ALARM		1.0	
01/12/2018 LIGHT/ALARM REPLACED FROZEN LINE, SLIDER VALVE & HOSE 3.0 01/12/2018 LIGHT/ALARM REPLACED PUMP & DISCHARGE HOSE 4.0 YES 01/12/2018 LIGHT/ALARM REPLACED PUMP & DISCHARGE HOSE 1.0 0.1 01/12/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0 0.1 01/12/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0 0.0 01/14/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0 0.0 01/14/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0 0.0 VES 01/15/2018 UGHT/ALARM REPLACED PUMP EQD 2.3 0.0 VIS 0.0 0.1 0.0 0.1 0.0 0.1 0.0 0.1 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 VES 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	01/12/2018	LIGHT/ALARM		1.0	
01/12/2018 LIGHT/ALARM REPLACED PUMP & DISCHARGE HOSE 4.0 YES 01/12/2018 LIGHT/ALARM REPLACED PUMP & DISCHARGE HOSE 1.0 01/12/2018 LIGHT/ALARM REPLACED PUMP, EQD 1.3 01/12/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0 01/14/2018 LIGHT/ALARM REPLACED PUMP, EQD, CONTROL BOARD & CABLE 4.0 YES 01/15/2018 UGHT/ALARM REPLACED PUMP, EQD, CONTROL BOARD & CABLE 4.0 YES 01/19/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.2 1.1 01/19/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.2 1.0 01/20/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 1.0 01/20/2018 LIGHT/ALARM RESET BREAKER 0.5 0.5 1.0 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 <td< td=""><td></td><td></td><td></td><td></td><td></td></td<>					
01/12/2018 LIGHT/ALARM REPLACED PUMP & DISCHARGE HOSE 1.0 01/12/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.3 01/12/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0 01/14/2018 LIGHT/ALARM REPLACED PUMP, EQD, CONTROL BOARD & CABLE 4.0 YES 01/15/2018 OVERFLOW REPLACED PUMP 2.3 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.0 1.2 1.0 1.2 1.0			,		YFS
01/12/2018 LIGHT/ALARM					123
01/12/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0 01/14/2018 LIGHT/ALARM REPLACED PUMP, EQD, CONTROL BOARD & CABLE 4.0 YES 01/15/2018 OVERFLOW REPLACED PUMP 2.3 01/19/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.2 01/19/2018 LIGHT/ALARM REPLACED PUMP, EQD 1.0 01/19/2018 1.0 01/20/2018 1.0 01/20/2018 1.0 01/20/2018 1.0 01/20/2018 1.0 01/20/2018 1.0 01/20/2018 1.0 0.0 01/20/2018 1.0 0.0 01/20/2018 1.0 0.0					
01/14/2018 LIGHT/ALARM REPLACED PUMP, EQD, CONTROL BOARD & CABLE 4.0 YES 01/15/2018 OVERFLOW REPLACED PUMP 2.3 01/19/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.2 01/19/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/20/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 5.0 YES 01/20/2018 DVERFLOW SEWER LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 01/20/2018 LIGHT/ALARM RESET BREAKER 0.5 0.5 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 0.5 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 0.1 01/24/2018 LIGHT/ALARM REPLACED PUMP 1.0 0.1 01/25/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 1.0 0.1 01/26/2018 LIGHT/ALARM REPLACED PUMP 4.0 0.0 01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 0.0 01/27/2018 LIGHT/ALARM <td></td> <td></td> <td></td> <td></td> <td></td>					
01/19/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.2 01/19/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/20/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 5.0 YES 01/20/2018 OVERFLOW SEWER LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 01/22/2018 LIGHT/ALARM RESET BREAKER 0.5 0.5 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 0.0 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 0.0 0.0 01/24/2018 LIGHT/ALARM RESET BREAKER 1.0 0.0				4.0	YES
01/19/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/20/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 5.0 YES 01/20/2018 OVERFLOW SEWER LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 01/23/2018 LIGHT/ALARM RESET BREAKER 0.5 CI 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 CI 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 CI CI </td <td></td> <td></td> <td></td> <td>2.3</td> <td></td>				2.3	
01/20/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 5.0 YES 01/20/2018 OVERFLOW SEWER LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 01/22/2018 LIGHT/ALARM RESET BREAKER 0.5 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/24/2018 LIGHT/ALARM RESET BREAKER 1.0 01/24/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/25/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP 2	01/19/2018	LIGHT/ALARM	NO PROBLEM FOUND ON MWD SIDE	1.2	
01/20/2018 OVERFLOW SEWER LINE CLOGGED ON CUSTOMER'S SIDE 3.0 YES 01/22/2018 LIGHT/ALARM RESET BREAKER 0.5 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/23/2018 LIGHT/ALARM RESET BREAKER 1.0 01/24/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/25/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018			REPLACED PUMP & EQD		
01/22/2018 LIGHT/ALARM RESET BREAKER 0.5 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/23/2018 LIGHT/ALARM RESET BREAKER 1.0 01/24/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/25/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 OVERFLOW REMOVED 6 BAGS OF WASTE FROM STATION 3.8 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0		1			
01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/23/2018 LIGHT/ALARM RESET BREAKER 1.0 01/24/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/25/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 OVERFLOW REMOVED 6 BAGS OF WASTE FROM STATION 3.8 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD <					YES
01/23/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/23/2018 LIGHT/ALARM RESET BREAKER 1.0 01/24/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/25/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 OVERFLOW REMOVED 6 BAGS OF WASTE FROM STATION 3.8 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0			•		
01/23/2018 LIGHT/ALARM RESET BREAKER 1.0 01/24/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/25/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 OVERFLOW REMOVED 6 BAGS OF WASTE FROM STATION 3.8 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0			•		
01/24/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/25/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 OVERFLOW REMOVED 6 BAGS OF WASTE FROM STATION 3.8 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0					
01/25/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 OVERFLOW REMOVED 6 BAGS OF WASTE FROM STATION 3.8 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0		,			
01/26/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 OVERFLOW REMOVED 6 BAGS OF WASTE FROM STATION 3.8 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0		·	•		
01/26/2018 LIGHT/ALARM REPLACED PUMP, EQD & CONTROL BOARD 3.5 YES 01/27/2018 OVERFLOW REMOVED 6 BAGS OF WASTE FROM STATION 3.8 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0					
01/27/2018 OVERFLOW REMOVED 6 BAGS OF WASTE FROM STATION 3.8 YES 01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0			-		VEC
01/27/2018 LIGHT/ALARM REPLACED PUMP 2.5 YES 01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0					
01/28/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0					
01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0		1			IES
01/29/2018 LIGHT/ALARM REPLACED PUMP 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0		-		+	
01/29/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0			•		
01/29/2018 LIGHT/ALARM REPLACED PUMP, EQD & DISCHARGE HOSE 1.0		1	·		
			·		
			REPLACED PUMP & EQD	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/30/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	HUUKS
	LIGHT/ALARM	REPLACED PUMP	1.0	
02/01/2018	OVERFLOW	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
		FROZEN SEWER LINE, THAWED LINE, REPLACED		
02/05/2018	LIGHT/ALARM	DISCHARGE HOSE	1.0	
02/06/2018	LIGHT/ALARM	NO PROBLEM FOUND ON MWD SIDE	1.0	
02/06/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/06/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/07/2018	OVERFLOW	REPLACED PUMP, EQD & CABLE	1.0	
02/07/2018	OVERFLOW	SEWER LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
02/08/2018	OVERFLOW	SEWER LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
02/12/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
02/12/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
02/12/2018	LIGHT/ALARM	REPLACED PUMP	0.8	
02/12/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/12/2018	OVERFLOW	REPLACED PUMP & EQD	1.0	
02/12/2018	LIGHT/ALARM	REPLACED SLIDER VALVE & HOSE	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/15/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/18/2018	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
02/21/2018	OVERFLOW	NO PROBLEM FOUND ON MWD SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
02/22/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/22/2018	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	3.0	
02/22/2018	LIGHT/ALARM	RESET BREAKER	1.0	
02/22/2018	OVERFLOW	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
02/26/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/26/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/26/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/27/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
02/28/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	0.5	
	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
02/28/2018	LIGHT/ALARM	RESET BREAKER	0.5	\/FC
03/01/2018	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
03/01/2018	OVERFLOW LIGHT (ALABAA	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
03/02/2018	OVERFLOW LIGHT/ALARM	SEWER LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD REPLACED PUMP & EQD	1.0 4.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
03/07/2018		NO POWER ON CUSTOMER'S SIDE	1.0	IES
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
03/09/2018	ODOR	NO PROBLEM FOUND ON MWD SIDE	1.0	
03/12/2018	OVERFLOW	REPLACED PUMP & CONTROL BOARD	4.0	YES
03/12/2018	OVERFLOW	REPLACED PUMP & CONTROL BOARD	1.0	ILJ
03/12/2018	OVERFLOW	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
03/14/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
03/15/2018		REPLACED PUMP	1.0	
03/10/2018	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	REPLACED CONTROL BOARD	1.0	
03/19/2018	OVERFLOW	REPLACED PUMP & CONTROL BOARD	1.0	
03/19/2018	OVERFLOW	REPLACED PUMP & CONTROL BOARD	1.0	
	OVERFLOW	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	RESET BREAKER	0.5	
03/23/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
03/25/2018	LIGHT/ALARM	REPLACED PUMP & EQD	2.0	YES
	,			
	LIGHT/ALARM	REPLACED PUMP	1.0	
03/26/2018	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP REPLACED PUMP & EQD	1.0 1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	IGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOW	SEWER LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
	IGHT/ALARM	REPLACED PUMP	1.0	
	DDOR	REPLACED PUMP & EQD	2.0	
	STATION BACKING UP	SEWER LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
	OVERFLOW LIGHT/ALARM	REPLACED PUMP REPLACED PUMP & EQD	1.0 1.0	
	IGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
04/02/2018 L		REPLACED PUMP & EQD	1.0	ILJ
	IGHT/ALARM	REPLACED PUMP	1.0	
	DDOR	RESET BREAKER	0.5	
	IGHT/ALARM	REPLACED PUMP	1.0	
	DDOR	NO POWER ON CUSTOMER'S SIDE	1.0	
	IGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	IGHT/ALARM	REPLACED PUMP	1.0	
04/11/2018 L	IGHT/ALARM	RESET BREAKER	1.0	
04/13/2018 L		REPLACED PUMP, EQD, CONTROL BOARD & CABLE	1.0	
04/15/2018 L	IGHT/ALARM	NO PROBLEM FOUND ON MWD SIDE	1.0	
04/18/2018	OVERFLOW	REPLACED PUMP, EQD & VENT CAP	1.0	
04/18/2018	OVERFLOW	REPLACED PUMP, SLIDER VALVE & HOSE	1.0	
04/19/2018	OVERFLOW	REPLACED PUMP & EQD	1.0	
04/20/2018	OVERFLOW	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
04/20/2018 L		REPLACED PUMP & EQD	1.0	
04/21/2018	OVERFLOW	REPLACED PUMP & EQD	2.5	YES
04/22/2018	OVERFLOW	REPLACED PUMP & EQD	3.0	YES
04/24/2018 L		REPLACED PUMP & EQD	1.0	
04/24/2018 L	IGHT/ALARM	REPLACED PUMP & EQD	1.0	
	COMMODE WON'T FLUSH	SEWER LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
	OVERFLOW	REPLACED PUMP & EQD	1.0	
04/27/2018 L	•	REPLACED PUMP, EQD, CABLE & CONDUIT	2.0	
	IGHT/ALARM	REPLACED PUMP	3.0	YES
	IGHT/ALARM	REPLACED PUMP	1.0	
05/01/2018 L		REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	-
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
05/04/2018 L	•	REPLACED PUMP & EQD	1.0	
05/04/2018 L		RESET BREAKER	1.0	
05/07/2018 L		REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
	IGHT/ALARM	REPLACED SLIDER VALVE	1.0	
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	0.5	
	PUMP NOT WORKING	NO PROBLEM FOUND ON MWD SIDE	0.5	-
	LIGHT/ALARM	REPLACED PUMP & EQD REPLACED PUMP & EQD	1.0	
05/09/2018 C 05/10/2018 L	OVERFLOW	REPLACED PUMP	1.0	VEC
			3.0	YES
05/10/2018 L		REPLACED PUMP & EQD	1.0	
05/11/2018 L 05/11/2018 L	•	BREAKER ISSUE ON CUSTOMER'S SIDE REPLACED PUMP & CONTROL BOARD	0.5 1.0	
			3.0	VEC
05/11/2018 L 05/11/2018 C	•	REPLACED PUMP & EQD REPLACED PUMP & EQD	1.0	YES
05/11/2018 (RESET BREAKER	1.0	
05/12/2018 L		REPLACED PUMP & EQD	3.0	YES
05/13/2018 L		REPLACED PUMP & EQD	1.0	IES
05/14/2018 L		REPLACED PUMP	1.0	
05/14/2018 L		REPLACED PUMP & EQD	1.0	
05/14/2018 L		REPLACED PUMP, CONTROL BOARD & CABLE	2.0	YES
05/15/2018 L	-	REPLACED PUMP & EQD	1.0	123
	IGHT/ALARM	REPLACED PUMP, EQD, CONTROL BOARD & CABLE	2.5	YES
05/16/2018 L		REPLACED PUMP, EQD, SLIDER VALVE & HOSE	3.5	YES
05/17/2018 L		REPLACED PUMP	1.0	125
	IGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
05/21/2018		NO POWER ON CUSTOMER'S SIDE	1.0	
05/21/2018 L		REPLACED PUMP & EQD	3.0	YES
05/22/2018 L		REPLACED PUMP	1.0	
05/22/2018 L		REPLACED PUMP & CONTROL BOARD	1.0	
05/23/2018 L	•	NO POWER ON CUSTOMER'S SIDE	1.0	
	IGHT/ALARM		1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
	OVERFLOW	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	STATION MAKING NOISE	REPLACED PUMP & EQD	1.0	
	PUMP NOT WORKING	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	3.0	YES
05/23/2018		RESET BREAKER	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	\/EC
	LIGHT/ALARM	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	\/FC
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
05/30/2018		REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	\/50
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
—	STATION BACKING UP	REPLACED PUMP & EQD	1.0	
,	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
	ODOR	NO PROBLEM FOUND ON MWD SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
	LIGHT/ALARM	UNCLOGGED LINE, REPLACED PUMP, EQD	6.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	SEWER LINE CLOGGED ON CUSTOMER'S SIDE	0.5	
	OVERFLOW	REPLACED PUMP & EQD	1.0	
	ODOR	NO PROBLEM FOUND ON MWD SIDE	1.0	
06/08/2018	LIGHT/ALARM	RESET BREAKER	1.0	
	ODOR	NO PROBLEM FOUND ON MWD SIDE	1.0	
06/11/2018	STATION BACKING UP	NO PROBLEM FOUND ON MWD SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
06/11/2018	STATION RUNNING CONTINUOUSLY	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	OVERFLOW	REPLACED VENT CAP	0.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
06/15/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.5	YES
06/18/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
06/22/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	SEWER LINE CLOGGED ON CUSTOMER'S SIDE	1.0	
06/25/2018	OVERFLOW	NO PROBLEM FOUND ON MWD SIDE	2.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
06/26/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	BLOCKAGE	REPLACED PUMP & EQD	1.0	
06/28/2018	PUMP NOT WORKING	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND ON MWD SIDE	1.0	
06/29/2018	LIGHT/ALARM	REPLACED SLIDER VALVE	1.0	
06/30/2018	PUMP NOT WORKING	REPLACED PUMP & VENT CAP	1.0	
07/02/2018	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
07/03/2018	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
07/05/2018	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.5	
	LIGHT/ALARM	REPLACED CONTROL BOARD & VENT CAP	1.0	
07/05/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
07/05/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	1.0	
	ODOR	NO POWER ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOW	REPLACED PUMP & EQD	1.0	
	•	•		

	DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
107174/2018 ICHIT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0	0.7-07-0-0	ODOR	REPLACED PUMP, EQD, SLIDER VALVE & HOSE	1.0	
O7126/2018 UGHT/ALARM REPLACED PUMP & DO 1.0	07/11/2018	ODOR	NO PROBLEM FOUND ON MWD SIDE	1.0	
O7/16/2018 UGHT/ALARM REPLACED PUMP, EGD & CONTROL BOARD 2.0 O7/16/2018 OVERFLOW REST-BREAKER 1.0 O7/16/2018 OVERFLOW REST-BREAKER 1.0 O7/16/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0 O7/18/2018 UGHT/ALARM REPLACED PUMP B CONTROL BOARD 1.0 O7/18/2018 UGHT/ALARM REPLACED PUMP B CONTROL BOARD 1.0 O7/19/2018 UGHT/ALARM REPLACED PUMP B COD 1.5 O7/19/2018 UGHT/ALARM REPLACED PUMP B COD 1.5 O7/20/2018 UGHT/ALARM REPLACED PUMP B COD 1.5 O7/20/2018 UGHT/ALARM REPLACED PUMP B COD 1.5 O7/20/2018 UGHT/ALARM REPLACED PUMP B COD 1.0 O7/20/2018 UGHT/ALARM REPLACED PUMP B COD 1.0 O7/20/2018 UGHT/ALARM REPLACED PUMP B COD 1.0 O7/20/2018 UGHT/ALARM REPLACED PUMP B COD 1.0 O7/20/2018 UGHT/ALARM GOMER CONTROL BOARD 1.0 O7/21/2018 UGHT/ALARM GOMER CONTROL BOARD 1.0 O7/21/2018 UGHT/ALARM GOMER CONTROL BOARD 1.0 O7/21/2018 UGHT/ALARM REPLACED PUMP B COD 1.0 OR/01/2018 UGHT/ALARM		-			
O7/15/2018 OWERLOW					
		-	·		
10718/2018 USHT/JALARM REPLACED PUMP & CONTROL BOARD 1.0					
O7/19/2018 GIGHT/ALARM					
O7/19/2018 GHT/ALARM					
107/20/2018 COMMODE WONT FLUSH REPLACED DULPEX PUMP & EQD 1.0					
					VEC
CUSTOMER HAD BEEN DISCONNECTED. TO CALL 3.0 YES					TES
07/21/2018 UGHT/ALARM	07/20/2018	OVERFLOW		1.0	
BEFORE CAN RECONNECT.	07/21/2019	LIGHT/ALARM		2.0	VEC
07/22/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES	07/21/2018	LIGITI/ALAKIVI		3.0	ILS
107/24/2018 LIGHT/ALARM	07/21/2019	DLIMB NOT WORKING		2 0	VEC
107/24/2018 LIGHT/ALARM					
107/27/2018 UGHT/ALARM REPLACED PUMP & EQD 1.0		-			163
07/27/2018 UGHT/ALARM REPLACED PUMP & EQD 1.5			·		
1073/07/2018 GHT/TALARM			1 1 1		
107/31/2018 IGHT/ALARM					
1.0 1.0			1 1		
1.0 1.0					
08/05/2018 LIGHT/ALARM					
08/06/2018 LIGHT/ALARM					YFS
08/06/2018 UGHT/ALARM REPLACED EQD & CABLE 1.5					
B8/06/2018					
08/06/2018	08/06/2018	OVERFLOW	REMOVED KINKS FROM LINE & REPLACED SLIDER HOSE	3.0	
08/06/2018 IGHT/ALARM					
08/08/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/09/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/09/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/09/2018 OVERFLOW REPLACED PUMP & EQD 1.0 0.0 <					
08/09/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/09/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/09/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/10/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/11/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 2.0 08/11/2018 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/11/2018 JUSTELOW REPLACED PUMP 3.0 YES 08/11/2018 JUSTELOW REPLACED PUMP & EQD 4.0 YES 08/13/2018 OVERFLOW REPLACED PUMP & EQD 4.0 YES 08/13/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 0.5 08/13/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/13/2018 LIGHT/ALARM REPLACED PUMP P. EQD & CABLE 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP P. EQD & CABLE 1.0 08/15/2018 OVERFLOW REPLACED PUMP P. EQD & CABLE 1.0 08/25/2018 LIGHT/AL					YES
08/09/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/09/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/10/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/11/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 2.0 08/11/2018 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/11/2018 OVERFLOW REPLACED PUMP 3.0 YES 08/11/2018 OVERFLOW REPLACED PUMP 3.0 YES 08/11/2018 OVERFLOW REPLACED PUMP 3.0 YES 08/13/2018 OVERFLOW REPLACED PUMP 3.0 YES 08/13/2018 IJGHT/ALARM REPLACED PUMP 1.0 0.5 08/13/2018 LIGHT/ALARM REPLACED PUMP, EQD & CABLE 1.0 0.6 08/15/2018 DVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0 0.6 08/15/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 0.6 08/15/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1		-	·		
08/09/2018 OVERFLOW REPLACED PUMP & EQD 1.0					
08/10/2018 LIGHT/ALARM					YES
08/11/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 2.0 08/11/2018 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/11/2018 OVERFLOW REPLACED PUMP & EQD 4.0 YES 08/12/2018 OVERFLOW REPLACED PUMP 3.0 YES 08/13/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 0.5 08/13/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/13/2018 LIGHT/ALARM REPLACED PUMP, EQD & CABLE 1.0 08/13/2018 LIGHT/ALARM REPLACED PUMP & CO. CUSTOMER'S SIDE 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP & CO. 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/22/2018			·		
08/11/2018 LIGHT/ALARM REPLACED PUMP 3.0 YES 08/11/2018 OVERFLOW REPLACED PUMP & EQD 4.0 YES 08/12/2018 OVERFLOW REPLACED PUMP 3.0 YES 08/13/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 0.5 0.5 08/13/2018 LIGHT/ALARM REPLACED PUMP 1.0 0.5 0.5 08/14/2018 LIGHT/ALARM REPLACED PUMP 1.0 0.		·	·		
08/11/2018 OVERFLOW REPLACED PUMP & EQD 4.0 YES 08/12/2018 OVERFLOW REPLACED PUMP 3.0 YES 08/13/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 0.5 08/13/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/13/2018 LIGHT/ALARM REPLACED PUMP, EQD & CABLE 1.0 08/14/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/15/2018 OVERFLOW REPLACED PUMP 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/15/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/23/2018 LIGHT/ALARM REPLACED PUMP & CONTROL BOARD<		1			
08/12/2018 OVERFLOW REPLACED PUMP 3.0 YES 08/13/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 0.5 08/13/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/13/2018 LIGHT/ALARM REPLACED PUMP, EQD & CABLE 1.0 08/14/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/15/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/15/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/23/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & EQ					
08/13/2018 OVERFLOW NO PROBLEM FOUND ON MWD SIDE 0.5 08/13/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/13/2018 LIGHT/ALARM REPLACED PUMP, EQD & CABLE 1.0 08/14/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/15/2018 UGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/23/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW					
08/13/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/13/2018 LIGHT/ALARM REPLACED PUMP, EQD & CABLE 1.0 08/14/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/15/2018 OVERFLOW REPLACED PUMP 1.0 08/15/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 DOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/22/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP 4.0 YES 08/23/2018 OVERFLOW REPLACED PUMP & EQD <td< td=""><td></td><td></td><td></td><td></td><td>YES</td></td<>					YES
08/13/2018 LIGHT/ALARM REPLACED PUMP, EQD & CABLE 1.0 08/14/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/15/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 DOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/22/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 DOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND O		1			
08/14/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0 08/15/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/15/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/22/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES 08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM NO					
08/15/2018 LIGHT/ALARM REPLACED PUMP 1.0 08/15/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 DOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/22/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/23/2018 ODR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP					
08/15/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 DODR NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/22/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES 08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 0.5 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 0.5 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD					
08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 DOOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/23/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES 08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 0.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 0.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 0.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 0.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 0.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 0.0 08/24/2018					
08/20/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/20/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/22/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES 08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018					
08/20/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/22/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES 08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					
08/20/2018 LIGHT/ALARM SEWER LINE CLOGGED ON CUSTOMER'S SIDE 1.0 08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/22/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES 08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					
08/21/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/22/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES 08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					
08/22/2018 LIGHT/ALARM REPLACED PUMP 4.0 YES 08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					
08/23/2018 ODOR NO PROBLEM FOUND ON MWD SIDE 0.5 08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					VES
08/23/2018 OVERFLOW REPLACED PUMP & CONTROL BOARD 1.0 08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					112
08/23/2018 OVERFLOW REPLACED PUMP & EQD 1.0 08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					
08/24/2018 LIGHT/ALARM NO POWER ON CUSTOMER'S SIDE 1.0 08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0		1			
08/24/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 1.0 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					
08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 2.0 YES 08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					
08/24/2018 LIGHT/ALARM REPLACED PUMP & EQD 1.0 08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0		-			YES
08/25/2018 LIGHT/ALARM REPLACED PUMP & EQD 3.0 YES 08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0					123
08/27/2018 OVERFLOW NO POWER ON CUSTOMER'S SIDE 1.0		-			YES
		-			. 20
08/27/2018 LIGHT/ALARM NO PROBLEM FOUND ON MWD SIDE 0.5			NO PROBLEM FOUND ON MWD SIDE	0.5	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
08/27/2018	ODOR	REPLACED PUMP, EQD & CONTROL BOARD	1.0	
08/28/2018	OVERFLOW	REPLACED PUMP	1.0	
	LIGHT/ALARM	NO PROBLEM FOUND ON MWD SIDE	1.0	
08/29/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	PUMP NOT WORKING	REPLACED PUMP, EQD & CONTROL BOARD	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD & CABLE	3.0	YES
	PUMP NOT WORKING	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	RESET BREAKER	3.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/04/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
09/05/2018	OVERFLOW	UNCLOGGED LINE, REPLACED PUMP, EQD, CONTROL	5.0	
	00.00	BOARD & CABLE	1.0	
09/06/2018	ODOR	NO PROBLEM FOUND ON MWD SIDE	1.0	
	OVERFLOW	REPLACED PUMP	1.0	VEC
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	3.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	STATION TAKING RAIN WATER. CUSTOMER TO FIX	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	VEC
, -, -	OVERFLOW	REPLACED PUMP & EQD	3.0	YES
	OVERFLOW	RESET BREAKER	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	\/F6
	LIGHT/ALARM	REPLACED PUMP	3.0	YES
	OVERFLOW CONTROLLER	REPLACED PUMP & EQD	1.0	
	COMMODE WON'T FLUSH	RESET BREAKERS & REPLACED EQD	1.0	VEC
	LIGHT/ALARM LIGHT/ALARM	REPLACED PUMP & EQD	1.5 1.0	YES
		REPLACED PUMP & EQD	1.0	
	ODOR OVERFLOW	NO PROBLEM FOUND ON MWD SIDE REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	NO POWER ON CUSTOMER'S SIDE	4.0	YES
	LIGHT/ALARM	REPLACED PUMP	1.5	TES
	LIGHT/ALARM	REPLACED PUMP	1.0	
	OVERFLOW	REPLACED PUMP, EQD & VENT CAP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
09/18/2018	OVERFLOW	RESET BREAKER	0.5	TES
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	LIGHT/ALARM	REPLACED PUMP, EQD, CONTROL BOARD & CABLE	4.0	YES
	LIGHT/ALARM	REPLACED PUMP & EQD	4.0	YES
	LIGHT/ALARM	BREAKER ISSUE ON CUSTOMER'S SIDE	2.3	11.5
	LIGHT/ALARM	REPLACED PUMP	1.0	
09/25/2018		REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
	OVERFLOW	BREAKER ISSUE ON CUSTOMER'S SIDE	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP, EQD & CABLE	1.5	
	LIGHT/ALARM	REPLACED PUMP	1.0	
10/08/2018	OVERFLOW	NO POWER ON CUSTOMER'S SIDE	1.0	
	ODOR	NO PROBLEM FOUND ON MWD SIDE	1.0	
10/10/2018	LIGHT/ALARM	REPLACED PUMP	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	3.0	YES
10/11/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP & CONTROL BOARD	1.0	
	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
	LIGHT/ALARM	RESET BREAKER	1.0	
	LIGHT/ALARM	RESET BREAKERS & REPLACED EQD	1.0	
	LIGHT/ALARM	REPLACED PUMP	1.0	

DATE	COMPLAINT	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
10/18/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	
10/18/2018	LIGHT/ALARM	REPLACED PUMP & EQD	1.0	

GENERAL WORK ORDERS

DATE	ISSUE	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/04/2010	INSTALL	CONTRACTOR ISSUE TO FINISH INSTALLATION. UNDER PROJECT WARRANTY.	1.0	
01/05/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
01/13/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
01/18/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
01/18/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
		STATION IN USE BUT NOT WORKING PROPERLY.		
01/21/2010	VERIFY SEWER	CONTRACTOR ISSUE. STILL UNDER PROJECT WARRANTY.	1.0	
01/21/2010	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
02/09/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
02/11/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
02/11/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
02/12/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
02/12/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
02/12/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
02/12/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
02/12/2010	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
02/19/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
02/19/2010	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
02/19/2010	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
02/23/2010	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
02/23/2010		PULLED PUMP FROM SERVICE	0.5	
	INSTALL	INSTALLED SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	<u> </u>
· ·	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	<u> </u>
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
03/15/2010	1	BURIED CABLE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
03/19/2010		PULLED PUMP FROM SERVICE	1.0	
03/22/2010 03/23/2010	1	PULLED PUMP FROM SERVICE PULLED PUMP FROM SERVICE	1.0 1.0	
03/23/2010		PULLED PUMP FROM SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
	VERIFY SEWER VERIFY SEWER	VERIFIED SEWER AT LOCATION VERIFIED SEWER AT LOCATION	0.5	
	INSTALL	INSTALLED SERVICE	1.0	
	INSTALL	INSTALLED SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION VERIFIED SEWER AT LOCATION	1.0	
04/15/2010		PULLED PUMP FROM SERVICE	1.0	
04/28/2010		PULLED PUMP FROM SERVICE	1.0	
04/28/2010		PULLED PUMP FROM SERVICE	1.0	
04/29/2010	1	BURIED CABLE	1.0	
	BURY CABLE	BURIED CABLE & REPAIRED 4" LINE	3.0	
05/03/2010		BURIED CABLE	2.0	
05/06/2010		BURIED CABLE	1.0	
05/06/2010		BURIED CABLE	1.0	
	BURY CABLE	BURIED CABLE	1.0	
05/10/2010		BURIED CABLE	1.0	
05/10/2010	INSTALL	INSTALLED SERVICE	1.0	1 .

DATE	ISSUE	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
05/12/2010	VERIFY SEWER	VERIFIED SEWER AT LOCATION. STN DAMAGED. EVALUATED STATION FOR COST ESTIMATE TO REPAIR.	4.0	
05/13/2010	INSTALL	INSTALLED SERVICE	2.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
05/14/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
05/14/2010	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
05/14/2010	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	BURY CABLE	BURIED CABLE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	BURY CABLE	BURIED CABLE	2.5	YES
06/01/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
06/07/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
06/08/2010	BURY CABLE	BURIED CABLE	1.0	
	BURY CABLE	BURIED CABLE	1.0	
	BURY CABLE	BURIED CABLE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
, ,	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
_ · ·	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
, ,	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
, ,	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
06/29/2010		PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
_ · ·	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	PULL PUMP BURY CABLE	PULLED PUMP FROM SERVICE	1.0	
		BURIED CABLE	1.0 1.0	
	PULL PUMP	INSTALLED SERVICE PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE PULLED PUMP FROM SERVICE		
	INSTALL	INSTALLED SERVICE	1.0	
	INSTALL	INSTALLED SERVICE INSTALLED SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
07/20/2010		PULLED PUMP FROM SERVICE	1.0	
07/21/2010		PULLED PUMP FROM SERVICE	0.5	
07/21/2010		PULLED PUMP FROM SERVICE	1.0	
07/21/2010		PULLED PUMP FROM SERVICE	0.5	
07/21/2010		PULLED PUMP FROM SERVICE	0.5	
07/21/2010		PULLED PUMP FROM SERVICE PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
07/21/2010		PULLED PUMP FROM SERVICE	1.0	
07/21/2010		PULLED PUMP FROM SERVICE	0.5	
07/21/2010		PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
07/21/2010		PULLED PUMP FROM SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
	BURY CABLE	BURIED CABLE	1.0	
	BURY CABLE	BURIED CABLE	1.0	
	INSTALL	INSTALLED SERVICE	1.0	
	INSTALL	INSTALLED SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	INSTALL	INSTALLED SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	

			COMPLETION TIME	AFTER
DATE	ISSUE	RESOLUTION	(HOURS)	HOURS
08/11/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
08/11/2010		PULLED PUMP FROM SERVICE	1.0	
08/11/2010		PULLED PUMP FROM SERVICE	1.0	
08/13/2010		PULLED PUMP FROM SERVICE	1.0	
08/18/2010	BURY CABLE	BURIED CABLE	1.0	
08/18/2010	BURY CABLE	BURIED CABLE	1.0	
08/31/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
09/01/2010	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
09/20/2010		PULLED PUMP FROM SERVICE	1.0	
09/20/2010		PULLED PUMP FROM SERVICE	1.0	
09/29/2010		BURIED CABLE	1.0	
10/04/2010	INSTALL	INSTALLED SERVICE	1.0	
10/05/2010		BURIED CABLE	1.0	
10/11/2010		PULLED PUMP FROM SERVICE	1.0	
10/11/2010		PULLED PUMP FROM SERVICE	0.5	
10/13/2010		PULLED PUMP FROM SERVICE	1.0	
10/13/2010		PULLED PUMP FROM SERVICE	0.5	
10/13/2010		PULLED PUMP FROM SERVICE	1.0	
10/13/2010		PULLED PUMP FROM SERVICE	1.0	
10/13/2010		PULLED PUMP FROM SERVICE	1.0	
10/13/2010		PULLED PUMP FROM SERVICE	1.0	
10/13/2010		PULLED PUMP FROM SERVICE	1.0	
10/13/2010		INSTALLED SERVICE	1.0	
10/15/2010		PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	INSTALL	INSTALLED SERVICE	1.0	
10/18/2010		PULLED PUMP FROM SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
10/20/2010		PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
10/27/2010		INSTALLED SERVICE	1.0	
10/28/2010		BURIED CABLE	1.0	
10/29/2010		PULLED PUMP FROM SERVICE	0.5	
11/01/2010		PULLED PUMP FROM SERVICE	1.0	
11/02/2010		PULLED PUMP FROM SERVICE	0.5	
11/09/2010		PULLED PUMP FROM SERVICE	0.5	
11/10/2010		PULLED PUMP FROM SERVICE	1.0	
11/12/2010		BURIED CABLE	1.0	
11/18/2010		PULLED PUMP FROM SERVICE	1.0	
11/19/2010		BURIED CABLE	1.0	
11/19/2010		PULLED PUMP FROM SERVICE	0.5	
11/23/2010		INSTALLED SERVICE	1.0	
11/23/2010		INSTALLED SERVICE	1.0	
11/24/2010		PULLED PUMP FROM SERVICE	1.0	
12/02/2010		PULLED PUMP FROM SERVICE	1.0	
12/02/2010		PULLED PUMP FROM SERVICE	2.0	
12/02/2010		BURIED CABLE	1.0	
12/07/2010		PULLED PUMP FROM SERVICE	1.0	
12/07/2010		INSTALLED SERVICE	1.0	
12/10/2010		PULLED PUMP FROM SERVICE	2.0	
12/13/2010		PULLED PUMP FROM SERVICE	1.0	
	BURY CABLE	BURIED CABLE	1.0	
12/30/2010	DUNI CABLE	DUVIED CABLE	1.0	

DATE	ISSUE	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/07/2011		INSTALLED SERVICE	1.0	
01/10/2011		PULLED PUMP - CUSTOMER REQUEST	1.0	
01/12/2011		PULLED PUMP - INACTIVE	1.5	
01/20/2011		PULLED PUMP - INACTIVE	1.0	
01/24/2011		PULLED PUMP - CUSTOMER REQUEST	1.0	
01/27/2011 01/27/2011	INSTALL	BURIED CABLE INSTALLED SERVICE	1.0	
02/14/2011		INSTALLED SERVICE	1.0	
02/14/2011		INSTALLED SERVICE	1.0	
02/18/2011		BURIED CABLE	2.0	
	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
02/25/2011		BURIED CABLE	2.0	
02/25/2011	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
02/28/2011	INSTALL	INSTALLED SERVICE	1.0	
03/04/2011		PULLED PUMP - CUSTOMER REQUEST	1.0	
03/05/2011		INSTALLED SERVICE	3.0	YES
03/14/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
03/14/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
03/23/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
04/04/2011		BURIED CABLE	1.0	
04/08/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
04/11/2011	BURY CABLE	BURIED CABLE	1.0	
04/12/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
04/15/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	0.5	
04/15/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
04/18/2011	PULL PUMP	PULLED PUMP - INACTIVE	1.0	
04/20/2011		PULLED PUMP - CUSTOMER REQUEST	1.0	
04/27/2011		PULLED PUMP - CUSTOMER REQUEST	1.0	
04/29/2011		PULLED PUMP - CUSTOMER REQUEST	0.5	
	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	2.0	
05/20/2011		PULLED PUMP - CUSTOMER REQUEST	0.5	
05/24/2011		PULLED PUMP - CUSTOMER REQUEST	1.0	
05/26/2011		PULLED PUMP - CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP - INACTIVE	1.0	
06/07/2011		INSTALLED SERVICE	2.0	
06/15/2011		INSTALLED SERVICE	2.0	
06/15/2011		INSTALLED SERVICE	1.0	1/50
06/16/2011		PULLED PUMP - CUSTOMER REQUEST	5.0	YES
06/16/2011		PULLED PUMP - CUSTOMER REQUEST	3.0	YES
06/23/2011		PULLED PUMP - INACTIVE	1.0	
07/05/2011		PULLED PUMP - INACTIVE	1.0	
07/06/2011		BURIED CABLE	2.0	
07/07/2011 07/11/2011		INSTALLED VENT CAP, BURIED CABLE PULLED PUMP - INACTIVE	1.5 1.0	
07/11/2011		PULLED PUMP - INACTIVE PULLED PUMP - INACTIVE	1.0	
07/12/2011		PULLED PUMP - CUSTOMER REQUEST	1.0	
07/14/2011		PULLED PUMP - INACTIVE	1.0	
07/18/2011		PULLED PUMP - INACTIVE	1.0	
07/18/2011		PULLED PUMP - INACTIVE	0.5	
08/02/2011		INSTALLED SERVICE	1.5	
	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	0.5	
08/02/2011		PULLED PUMP - INACTIVE	1.0	
08/03/2011		PULLED PUMP - INACTIVE	1.0	
08/03/2011		PULLED PUMP - CUSTOMER REQUEST	0.5	
08/04/2011		PULLED PUMP - CUSTOMER REQUEST	1.0	
08/04/2011		BURIED CABLE	1.0	
08/09/2011		PULLED PUMP - CUSTOMER REQUEST	0.5	
08/10/2011		PULLED PUMP - INACTIVE	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	

DATE	ISSUE	DESCRIPTION	COMPLETION TIME	AFTER
DATE	ISSUE	RESOLUTION	(HOURS)	HOURS
08/19/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
08/31/2011	BURY CABLE	BURIED CABLE	1.0	
09/02/2011	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
09/23/2011	BURY CABLE	BURIED CABLE	1.0	
09/23/2011	PULL PUMP	PULLED PUMP - INACTIVE	1.0	
09/27/2011	INSTALL	INSTALLED SERVICE	1.5	
09/30/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
10/20/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
10/31/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
11/08/2011	PULL PUMP	PULLED PUMP - INACTIVE	1.0	
11/09/2011	PULL PUMP	PULLED PUMP - INACTIVE	1.0	
11/10/2011	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
11/10/2011	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
11/16/2011	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
11/17/2011	INSTALL	INSTALLED SERVICE	2.0	
11/18/2011	INSTALL	INSTALLED SERVICE	1.0	
11/28/2011	PULL PUMP	PULLED PUMP - INACTIVE	1.0	
11/29/2011	BURY CABLE	BURIED CABLE	1.0	
12/01/2011	INSTALL	INSTALLED SERVICE	1.0	
12/06/2011	INSTALL	INSTALLED SERVICE	1.0	
12/07/2011	INSTALL	INSTALLED SERVICE	1.0	
12/19/2011	PULL PUMP	PULLED PUMP - INACTIVE	1.0	
12/28/2011	INSTALL	INSTALLED SERVICE	1.0	
12/28/2011	PULL PUMP	PULLED PUMP - INACTIVE	0.5	
12/28/2011	PULL PUMP	PULLED PUMP - INACTIVE	0.5	

DATE	ISSUE	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
01/04/2012	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.5	
01/05/2012	BURY CABLE	BURIED CABLE	1.0	
	BURY CABLE	BURIED CABLE	2.0	
	BURY CABLE	BURIED CABLE	0.5	
<u> </u>	INSTALL	INSTALL SERVICE	1.0	
	BURY CABLE	BURIED CABLE	1.0	
<u> </u>	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.3	
	INSTALL	INSTALL SERVICE	0.3	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.3	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	INSTALL	INSTALL SERVICE	1.0	
	INSTALL	INSTALL SERVICE	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	INSTALL	INSTALL SERVICE	1.0	
	BURY CABLE	BURIED CABLE	1.0	
	INSTALL	INSTALL SERVICE	2.0	
	ILLEGAL	FOUND SERVICE ILLEGAL	1.0	
	INSTALL	INSTALL SERVICE	2.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	2.0	
	ILLEGAL	FOUND SERVICE ILLEGAL	1.0	
	ILLEGAL	FOUND SERVICE ILLEGAL	1.0	
	INSTALL	INSTALL SERVICE	3.0	
	INSTALL	INSTALL SERVICE	0.3	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.3	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
<u> </u>	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
04/15/2012		PULLED PUMP FROM SERVICE	1.0	
<u> </u>	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
04/27/2012		PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.3	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	INSTALL	INSTALL SERVICE	0.3	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.3	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	BURY CABLE	BURIED CABLE	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.3	
<u> </u>	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.5	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.3	
	INSTALL	INSTALL SERVICE	1.0	
,-,-	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.3	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
,-,-	INSTALL	INSTALL SERVICE	0.3	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
<u> </u>	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.3	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
08/13/2012	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	2.0	
08/20/2012	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	

DATE	ISSUE	RESOLUTION	COMPLETION TIME	AFTER
08/24/2012	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	(HOURS) 1.0	HOURS
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	BURY CABLE	BURIED CABLE	0.5	
09/04/2012		PULLED PUMP FROM SERVICE	1.0	
	BURY CABLE	BURIED CABLE	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	INSTALL	INSTALL SERVICE	0.3	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
09/20/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
09/25/2012	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.5	
09/26/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
09/26/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
09/26/2012	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
09/26/2012	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
09/26/2012	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
09/26/2012	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
09/26/2012	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
09/26/2012	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
09/26/2012	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	INSTALL	INSTALL SERVICE	0.3	
10/01/2012	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
10/01/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
10/02/2012	INSTALL	INSTALL SERVICE	0.3	
10/02/2012	INSTALL	INSTALL SERVICE	1.0	
10/02/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
10/03/2012	VERIFY SEWER	VERIFIED SEWER AT LOCATION	4.0	
10/12/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
10/12/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
10/16/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
10/17/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
10/17/2012	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
10/18/2012	INSTALL	INSTALL SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
10/25/2012		PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	
10/25/2012		PULLED PUMP FROM SERVICE	0.5	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
, , -	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.5	
11/05/2012		RECONNECTED SERVICE	1.0	
11/09/2012		PULLED PUMP CUSTOMER REQUEST	1.0	
11/15/2012		PULLED PUMP CUSTOMER REQUEST	1.0	
11/15/2012	1	PULLED PUMP CUSTOMER REQUEST	2.0	
11/27/2012		PULLED PUMP CUSTOMER REQUEST	0.5	
	INSTALL	INSTALL SERVICE	0.3	
11/28/2012		PULLED PUMP FROM SERVICE	1.0	
, , -	INSTALL	INSTALL SERVICE	0.3	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
	PULL PUMP	PULLED PUMP FROM SERVICE	1.0	
12/06/2012		PULLED PUMP CUSTOMER REQUEST	1.0	
12/07/2012		PULLED PUMP CUSTOMER REQUEST	0.5	
, - , -	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	0.5	
	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
	PULL PUMP	PULLED PUMP CUSTOMER REQUEST	1.0	
12/13/2012	1	PULLED PUMP FROM SERVICE	0.5 0.5	
	PULL PUMP	PULLED PUMP FROM SERVICE		
12/13/2012		PULLED PUMP FROM SERVICE	0.5	
12/13/2012		PULLED PUMP FROM SERVICE	0.5	
12/13/2012		PULLED PUMP FROM SERVICE	1.0	
12/18/2012		PULLED PUMP CUSTOMER REQUEST	1.0	
12/19/2012	PULL PUMP	PULLED PUMP FROM SERVICE	0.5	

DATE	ISSUE	DECOLUTION	COMPLETION TIME	AFTER
DATE	ISSUE	RESOLUTION	(HOURS)	HOURS
02/15/2013	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
02/15/2013	PULL PUMP	PULLED PUMP - CUSTOMER REQUEST	1.0	
02/25/2013	INSTALL	NSTALLED SERVICE	1.0	
02/27/2013	INSTALL	NSTALLED SERVICE	3.0	
04/03/2013	BURY CABLE	BURIED CABLE	1.0	
04/09/2013	PULL PUMP	PULLED PUMP - INACTIVE	0.5	
05/02/2013	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
05/14/2013	BURY CABLE	BURIED CABLE	1.0	
05/15/2013	BURY CABLE	BURIED CABLE	2.0	
06/04/2013	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
06/05/2013	BURY CABLE	BURIED CABLE	1.0	
06/05/2013	BURY CABLE	BURIED CABLE	1.0	
06/24/2013	VERIFY SEWER	VERIFIED SEWER AT LOCATION	0.5	
07/15/2013	INSTALL	NSTALLED SERVICE	2.0	
07/16/2013	VERIFY SEWER	VERIFIED SEWER AT LOCATION	1.0	
09/09/2013	INSTALL	NSTALLED SERVICE	1.0	
10/04/2013	PULL PUMP	PULLED PUMP - INACTIVE	1.0	
10/22/2013	INSTALL	NSTALLED SERVICE	1.0	
12/02/2013	INSTALL	NSTALLED SERVICE	1.0	
12/02/2013	PULL PUMP	PULLED PUMP - INACTIVE	1.0	

DATE	ISSUE	PECOLUTION	COMPLETION TIME	AFTER
DATE	IJJUL	RESOLUTION	(HOURS)	HOURS
01/09/2014	ESTIMATE TO MOVE STATION	PERFORMED COST ESTIMATE TO MOVE STATION.	1.0	
		CUSTOMER NEEDS TO PAY FOR DAMAGED		
01/13/2014	RECONNECT SEWER	EQUIPMENT AND PROVIDE POWER BEFORE CAN	1.0	
		RECONNECT SERVICE		
02/19/2014	RECONNECT SEWER	PERFORMED COST ESTIMATE TO RECONNECTED	0.5	
02/19/2014	RECONNECT SEWER	SERVICE	0.5	
02/27/2014	BURY CABLE	BURIED CABLE	1.0	
03/10/2014	ESTIMATE TO MOVE STATION	PERFORMED COST ESTIMATE TO MOVE STATION.	1.0	
03/19/2014	RECONNECT SEWER	CUSTOMER NEEDS TO PAY FOR CONTROL BOX &	1.0	
03/19/2014	RECONNECT SEWER	CABLE BEFORE SERVICE CAN BE RECONNECTED	1.0	
04/11/2014	INSTALL PUMP	INSTALLED PUMP, CABLE & CONTROL BOX	1.0	
06/16/2014	PULL PUMP - INACTIVE	PULLED PUMP, TURNED OFF BREAKERS, INSTALLED	1.0	
00/10/2014	FOLL FOWIF - INACTIVE	PLUG	1.0	
06/16/2014	PULL PUMP - INACTIVE	PULLED PUMP, TURNED OFF BREAKERS, INSTALLED	1.0	
00/10/2014	POLL POWIP - INACTIVE	PLUG	1.0	
07/02/2014	BURY CABLE	BURIED CABLE	1.0	
07/07/2014	MOVING INQUIRY TO DISC SERVICE	ADVISED CUSTOMER WHAT TO DO TO MOVE SERVICE	1.0	
07/07/2014	INOVING INQUIRT TO DISC SERVICE	TO NEW TRAILER WHEN TIME	1.0	
07/21/2014	PULL PUMP - INACTIVE	PULLED PUMP, TURNED OFF BREAKERS, INSTALLED	1.0	
07/21/2014	TOLETOWN INVACTIVE	PLUG	1.0	
07/21/2014	PULL PUMP - INACTIVE	PULLED PUMP, TURNED OFF BREAKERS, INSTALLED	1.0	
07/21/2014	TOLETOWN INVACTIVE	PLUG	1.0	
07/21/2014	PULL PUMP - INACTIVE	PULLED PUMP, TURNED OFF BREAKERS, INSTALLED	1.0	
07/21/2011	TOLETOWN MAKETIVE	PLUG	1.0	
07/21/2014	PULL PUMP - INACTIVE	PULLED PUMP, TURNED OFF BREAKERS, INSTALLED	1.0	
, ,		PLUG	=	
09/02/2014	REPLACE CABLE - TOO SHORT	REPLACED CABLE	1.0	
09/25/2014	PULL PUMP - INACTIVE	PULLED PUMP, TURNED OFF BREAKERS, INSTALLED	0.5	
, ,		PLUG		
	BURY CABLE	BURIED CABLE	0.5	
10/13/2014	MOVE STATION. CUSTOMER PAID.	RELOCATED STATION	3.0	
10/27/2014	VERIFY SEWER	VERIFIED SEWER AT RESIDENCE	1.0	

DATE	ISSUE	RESOLUTION	COMPLETION TIME	AFTER
			(HOURS)	HOURS
02/03/2015	PULL PUMP	PULLED PUMP/CUSTOMER REQUEST	1.0	
02/03/2015	PULL PUMP	PULLED PUMP/CUSTOMER REQUEST	1.0	
02/03/2015	PULL PUMP	PULLED PUMP/CUSTOMER REQUEST	1.0	
02/10/2015	PULL PUMP	PULLED PUMP/CUSTOMER REQUEST	1.0	
02/10/2015	PULL PUMP	PULLED PUMP/CUSTOMER REQUEST	1.0	
02/10/2015	PULL PUMP	PULLED PUMP/CUSTOMER REQUEST	1.0	
02/10/2015	PULL PUMP	PULLED PUMP/CUSTOMER REQUEST	1.0	
03/27/2015	PULL PUMP	PULLED PUMP/CUSTOMER REQUEST	1.0	
05/26/2015	BURY CABLE	BURIED CABLE/STN WORKING PROPERLY	1.0	
06/09/2015	ACTIVATE ACCT	ACTIVATED ACCOUNT IN SYSTEM	0.0	
06/09/2015	PULL PUMP	PULLED PUMP/INACTIVE	1.0	
06/19/2015	MOVE STN	COST ESTIMATE TO MOVE STN	1.0	
08/06/2015	BURY CABLE	BURIED CABLE/STN WORKING PROPERLY	1.0	
08/14/2015	MOVE STN	MOVED STATION PER CUSTOMER PYMT	6.0	
10/20/2015	NEW CUSTOMER	INSTALLED SERVICE	1.5	
11/05/2015	VERIFY SEWER	VERIFIED SEWER/SMOKE TESTED	1.0	
11/12/2015	BURY CABLE	BURIED CABLE/STN WORKING PROPERLY	1.0	
12/03/2015	NEW CUSTOMER	INSTALLED SERVICE	1.0	
12/17/2015	VERIFY SEWER	VERIFIED SEWER	1.0	

DATE	ISSUE	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
06/13/2016	INSTALL	INSTALLED PUMP	1.0	1100113
08/22/2016	INSTALL	INSTALLED PUMP AND CABLE	2.0	
09/06/2016	INSTALL	INSTALLED PUMP AND REPLACED EQD	1.0	
10/07/2016	CABLE ISSUE	REPLACED AND BURIED CABLE	1.0	
10/16/2016	INSTALL	INSTALLED PUMP	0.5	
10/19/2016	BURY CABLE	BURIED CABLE	1.0	

DATE	ISSUE	RESOLUTION	COMPLETION TIME (HOURS)	AFTER HOURS
02/13/2017	RECONNECT	REMOVED PLUG, INSTALLED PUMP	1.0	
02/13/2017	POSSIBLE TAP	SPOKE TO CUSTOMER ABOUT SERVICE INSTALL TO RECONNECT	0.5	
05/15/2017	CUSTOMER DAMAGE	PERFORMED COST ESTIMATE TO RESTORE SERVICE	1.0	
05/16/2017	INSTALL	INSTALLED STATION	1.0	
06/05/2017	VERIFY SEWER	VERIFIED SEWER AT LOCATION, CUT CONCRETE AND REPAIRED DAMAGED PARTS AND RESTORED SERVICE	1.0	
08/30/2017	RECONNECT	CUSTOMER HAD REROUTED LINE FROM UNDER TRAILER. REPLACED CONTROL BOARD, CABLE AND PUMP	1.0	
09/01/2017	INSTALL	INSTALLED STATION	1.0	
10/05/2017	INSTALL	INSTALLED STATION	1.0	

DATE	ISSUE	RESOLUTION	COMPLETION TIME	AFTER
2.112			(HOURS)	HOURS
03/19/2018	REVIEW SERVICE	CUSTOMER HAS BUILT PORCH OVER STATION. OFFICE		
		TO SEND LETTER REQUESTING CUSTOMER PAY TO	1.0	
		MOVE STATION		
05/08/2018	MOVE STATION	CUSTOMER REQUESTED TO MOVE STATION. COST	1.0	
		ESTIMATE ON MOVING STATION PERFORMED		
05/10/2018	COST ESTIMATE	PERFORMED COST ESTIMATE TO REPLACE STATION	1.0	
06/26/2018	INSTALL	INSTALLED SERVICE	1.0	
	BUSTED BARREL	REMOVED BUSTED BARREL & REPLACED BARREL,		
07/27/2018		PUMP, CABLE, EQD & CONTROL BOX. NO POWER ON	4.0	
		CUSTOMER'S SIDE.		
08/01/2018	COST ESTIMATE	PERFORMED COST ESTIMATE TO REPAIR DAMAGED	1.0	
		STATION	1.0	
08/21/2018	INSTALL	INSTALLED SERVICE	2.0	
08/23/2018	INSTALL	INSTALLED SERVICE	1.0	
09/05/2018	BURY CABLE	BURIED CABLE	1.0	
09/05/2018	BURY CABLE	BURIED CABLE	1.0	
09/05/2018	REVIEW SERVICE	CUSTOMER HAS BUILT PATIO OVER STATION. OFFICE		
		TO SEND LETTER REQUESTING CUSTOMER PAY TO	1.0	
		MOVE STATION		

Response to Commission Staff's First Request for Information October 19, 2018

Case No. 2018-00147

Question No. 3

Witness: Tammy Olson/Roy Sawyers/Jamey Keathley

- **Q-3.** Provide Mountain District's response policy and procedures for a failure of a grinding pump station.
- **A-3.** Mountain Water District's ("Mountain District") policy requires an on-site response to a customer complaint involving a grinder pump station, including a light or audible alarm, within 40 minutes of receipt of a complaint or report of trouble. To meet this standard, Mountain District maintains a satellite office in each of its three pressurized sewer zones from which wastewater employees report during regular work hours. The establishment of satellite offices reduces the time needed to respond to a customer complaints or report of trouble. Mountain District maintains one employee on call during non-business hours to respond to reports of trouble.

Mountain District applies the following procedures when receiving a customer complaint or report of trouble:

- 1. Upon arrival, the Mountain District employee will clear the grinder/pump station's alarm.
- 2. Using a volt meter and visual inspection, the Mountain District employee will use inspect and troubleshoot any issues with the grinder/pump station's control panel, emergency quick disconnect, and cables and the customer's circuit breaker. (The customer is responsible for providing electric power to the grinder/pump station and, at the time of applying for service, agrees to allow the grinder/pump station to be connected to the customer's electric service.)
- 3. If no electrical problems are detected and the grinder/pump is submerged and not operating as designed, the Mountain District employee will pull the grinder/pump and check it with his volt meter. If the grinder/pump pulls below the range of 5.5 to 6 amps, the Mountain District employee is to assume that the stator has malfunctioned and the grinder/pump should be replaced.
- 4. If the Mountain District employee finds no electrical issues and the grinder/pump is not operational, the pump is considered non-functional and replaced.
- 5. If replacement of the pump is required, replacement is made during the service call.

6. The Mountain District employee making the service call will not make undertake any effort to break the grinder/pump's seal to inspect or troubleshoot the grinder/pump's internal components. Breaking the internal seal of a grinder/pump station voids the manufacturer's warranty.

Response to Commission Staff's First Request for Information October 19, 2018

Case No. 2018-00147

Question No. 4

- **Q-4.** Provide the number of service calls Mountain District has received about the grinder/pump stations since 2010.
- **A-4.** Mountain Water District's records show that 6,244 work orders involving grinder/pump stations since 2010. See Attachment to Response 2 for a listing of the date of each service call, the nature of the service call, and the time required to address the service call.

Response to Commission Staff's First Request for Information October 19, 2018

Case No. 2018-00147

Question No. 5

Witness: Tammy Olson/Roy Sawyers/Jamey Keathley

- **Q-5.** Provide the number of service calls that were emergency calls, and state whether Mountain District met its target response time of 40 minutes for each of the emergency calls.
- **A-5.** The number of emergency service calls from 2010 to present related to grinder/pump stations is 5,144. Mountain Water District ("Mountain District") does not maintain a record of the time elapsing from the receipt of the service call and Mountain District personnel's arrival at the grinder/pump station's location. It records the time elapsing from receipt of the call to completion of the repair work. The table below summarizes the time elapsing form receipt of the service call to the resolution of the service call. See Attachment to Response 2 for the response time for each service call.

To determine whether the target response time was met, Mountain District has assumed that service personnel would require at least twenty minutes onsite to interview the customer, inspect the grinder/pump station and undertake corrective action. Applying this assumption, the target response time of 40 minutes or less was met for sixty-seven percent of the emergency service calls for the period in question.

Year	1 Hr or Less	1-2 Hrs	2-3 Hrs	3-4 Hrs	More than 4 Hrs
2010	353	31	80	64	37
2011	476	28	47	69	27
2012	469	32	62	72	37
2013	441	18	43	73	35
2014	355	26	60	80	41
2015	351	37	116	79	51
2016	315	26	108	77	35
2017	383	13	24	50	34
2018	284	9	20	45	31
TOTAL	3427	220	560	609	328
	67%	4%	11%	12%	6%

Response to Commission Staff's First Request for Information October 19, 2018

Case No. 2018-00147

Question No. 6

- **Q-6.** Provide the number of customer complaints Mountain District has received about the grinder pump stations since 2010. For each complaint, state the resolution.
- **A-6**. The number of customer complaint work orders that have been received from 2010 to present is 613. For a breakdown of complaints and their resolutions, see Attachment to Response 2.

Response to Commission Staff's First Request for Information October 19, 2018

Case No. 2018-00147

Question No. 7

- **Q-7.** Confirm that the manufacturer's warranty on the grinder/pump stations covers the equipment in question and would not pay for any damage, which might occur to the customer's property in the event the grinder/pump stations malfunction.
- **A-7**. Confirmed. The grinder/pump station's manufacturer warrants that its equipment from any defects in material and factory workmanship for 60 months after its installation. Repairs or parts replacement required as a result of such defect will be made at no cost to Mountain District that period.

Response to Commission Staff's First Request for Information October 19, 2018

Case No. 2018-00147

Question No. 8

- **Q-8.** Refer to paragraph 7 of the application. Mountain District states in its application that the grinder pump stations have been equipped with visual and audio alarms that can easily be seen and heard from a "considerable distance."
 - a. Define "considerable distance."
 - b. Refer to paragraph 3 of the application. State whether the audio and visual alarms are an effective warning system in an area of low customer density such as Mountain District's territory.
- A-8. a. The grinder pump stations have a visual alarm and an audible alarm. The visual alarm lamp is usually mounted to the residence or other structure that the grinder pump station serves. When activated, it can be seen from a distance of approximately 250 to 350 feet during daylight conditions and a minimum distance of 1,000 feet at night. The audible alarm is capable of 93 decibels at 2 feet. See Attachment to this Response. This sound level is the equivalent of a train whistle at 500 feet and a subway train at 200 feet.¹
 - b. The primary purpose of the alarms is to alert the occupants of the structure that the grinder pump serves. Once alerted, the occupants can notify Mountain District of the problem. Generally, service personnel will arrive within 40 minutes of notification. The triggering of the alarms does not mean that an overflow event is imminent. The grinder pump station's storage tank has a capacity of 170 gallons.² The guidelines that Mountain District provides to its customers at the time the customer applies for service advise that if the alarms are triggered, customers should immediately notify Mountain District and avoid water usage until repairs are made. See Application, Exhibit 8. If the structure is unoccupied, then the immediate risk of overflows is significantly less.

¹ See https://www.hearnet.com/at_risk/risk_trivia.shtml (last visited Nov. 23, 2018) archived at https://perma.cc/8QVH-Q8PW; https://www.chem.purdue.edu/chemsafety/Training/PPE Train/dblevels.htm (last visited Nov. 23, 2018), archived at https://perma.cc/TMP4-ZTXJ.

² In its Application, Mountain District erroneously stated that the capacity of these tanks is only 120 gallons.

The secondary purpose of the alarms is to alert adjacent property owners and patrolling law enforcement and Mountain District service personnel. While the effectiveness of the alarms decreases as the distance from the grinder pump station increases, Mountain District believes that alarms will be detectable to others besides the served structure's occupants and will result in trouble notifications to Mountain District.



November 1, 2018

Mr. Jamey Keathley Mountain Water District 6332 Zebulon Hwy Pikeville, KY 41501

Mr. Keathley,

Per your request for clarification of the alarm components that are provided in the Environment One (E/One) Alarms Panels please see an explanation of the technical features of our alarms.

The Environment One (E/One) Alarm Panels have two alarms, visual and audible. The visual alarm lamp is inside a red, oblong lens mounted to the top of the enclosure in such a manner as to maintain NEMA 4X rating. The audible alarm is externally mounted on the bottom of the enclosure, capable of 93 dB @ 2 feet. The audible alarm is capable of being deactivated by depressing a push-type switch that is encapsulated in a weatherproof silicone boot and mounted on the bottom of the enclosure (push-to-silence button).

Please feel free to contact me if I can be of further assistance.

Regards,

Marvin Springer Regional Sales Manager Environment One Corporation

Direct Telephone: (816) 719-2501 E-mail: mspringer@eone.com

Response to Commission Staff's First Request for Information October 19, 2018

Case No. 2018-00147

Question No. 9

- **Q-9.** Provide the current system's inspection procedures that Mountain District has in place to detect a poorly functioning or nonfunctioning grinding pump station.
- **A-9.** Mountain Water District ("Mountain District") primarily relies upon customer reports of poorly functioning or nonfunctioning grinding pump stations. Inspections are of limited value as its personnel cannot inspect the internal workings of the grinder pumps. These pumps are encased in a water proof outer hull that is sealed from the material in the barrel. Breaking the seal to inspect the inner mechanical parts of the pump would void the manufacturer's warranty and thus increase Mountain District's financial risks and potentially increase its operating and maintenance expenses. See Application, Exhibit 11. Moreover, breaking the seal and dismantling the grinder pump in the field for inspection may compromise the functioning of the pump and shorten its useful life.